Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:17:1	9.54	890	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.62	15.33	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:1	9.54	890	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.62	15.33	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:1	8.18	872	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.63	15.31	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:1	8.18	872	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.64	15.31	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:1	8.18	891	0.8	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.65	15.32	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:1	8.18	886	0.8	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.64	15.31	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:2	9.54	886	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.64	15.31	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:2	9.54	886	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.63	15.31	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:2	9.54	893	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.62	15.29	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:2	9.54	893	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.66	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:2	8.18	888	0.8	13.47	113	194	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.66	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:2	8.18	884	0.8	13.48	113	194	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.68	15.25	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:3	8.18	902	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.66	15.25	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:3	8.18	902	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.68	15.24	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:3	8.18	900	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.67	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:3	9.54	898	0.8	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.68	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:3	9.54	898	0.8	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.69	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:3	9.54	902	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.69	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:4	8.18	909	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:4	8.18	909	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.66	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:4	8.18	909	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.68	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:4	8.18	904	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.65	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:4	8.18	904	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.67	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:4	8.18	905	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.66	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:4	8.18	907	0.8	13.46	113	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.75	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:5	8.18	909	0.8	13.47	113	194	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.72	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:5	8.18	909	0.8	13.49	113	194	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.74	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:5	8.18	908	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.73	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:5	8.18	908	0.8	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.74	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:5	8.18	905	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.7	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:17:5	8.18	905	0.8	13.48	113	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.73	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:17:6	8.18	909	0.8	13.46	113	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.71	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:17:6	8.18	909	0.8	13.47	113	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.73	14.97	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:17:6	8.18	902	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.74	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:6	8.18	894	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.73	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:6	8.18	893	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:6	8.18	893	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:6	8.18	893	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.71	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:7	8.18	885	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:7	8.18	882	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.72	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:7	10.9	879	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:7	10.9	879	0.8	13.47	113	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.73	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:7	10.9	866	0.8	13.47	113	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.7	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:7	10.9	866	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.72	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:8	9.54	878	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.68	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:8	9.54	878	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.67	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:8	9.54	854	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.67	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:8	9.54	854	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.67	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:8	10.9	856	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.66	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:8	10.9	857	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.65	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:9	10.9	858	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.66	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:9	10.9	858	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.63	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:9	10.9	858	0.8	13.45	114	194	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.63	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:9	9.54	867	0.8	13.44	114	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.58	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:9	9.54	867	0.8	13.44	113	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.62	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:9	9.54	872	0.8	13.44	113	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.57	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:17:9	9.54	872	0.8	13.43	114	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.59	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:0	9.54	876	0.8	13.44	114	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.58	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:18:0	9.54	876	0.8	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.58	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:0	9.54	874	0.8	13.44	114	194	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.57	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:0	9.54	873	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.59	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:0	9.54	891	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.6	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:0	9.54	891	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.62	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:1	9.54	880	0.8	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.65	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:1	9.54	870	0.8	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.61	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:1	9.54	870	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.63	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:1	9.54	871	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.59	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:1	9.54	867	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.62	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:1	9.54	863	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.6	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:1	9.54	863	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.63	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:2	8.18	873	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.59	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:2	8.18	873	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.6	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:2	8.18	873	0.8	13.45	114	194	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.59	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:2	8.18	871	0.8	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.58	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:2	9.54	870	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.58	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:2	9.54	870	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.55	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:3	9.54	870	0.8	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.59	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:3	9.54	881	0.8	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.55	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:3	9.54	882	0.8	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.59	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:3	9.54	882	0.8	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.58	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:3	9.54	882	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.59	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:3	9.54	874	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.56	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:4	9.54	882	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.58	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:4	8.18	882	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.53	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:4	8.18	882	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.56	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:4	8.18	881	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.56	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:4	8.18	881	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.58	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:4	9.54	882	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.59	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:4	9.54	883	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.58	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:5	9.54	868	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.57	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:5	9.54	868	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.56	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:5	9.54	868	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.57	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:5	9.54	869	0.81	13.45	114	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.53	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:5	9.54	869	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.56	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:5	9.54	865	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.55	15.01	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:6	9.54	865	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.58	15.05	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:6	9.54	869	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.55	15.09	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:6	9.54	873	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.54	15.18	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:6	9.54	862	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.5	15.23	1.04	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:6	9.54	862	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.5	15.25	1.04	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:6	9.54	862	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.49	15.29	1.04	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:6	9.54	869	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.52	15.32	1.04	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:7	9.54	880	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.53	15.35	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:7	9.54	880	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.54	15.36	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:7	9.54	880	0.81	13.45	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.56	15.41	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:7	8.18	874	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.55	15.43	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:7	8.18	877	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.58	15.43	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:7	8.18	877	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.53	15.43	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:8	8.18	877	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.57	15.44	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:8	8.18	898	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.57	15.43	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:8	8.18	903	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.58	15.42	1.05	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:18:8	8.18	903	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.58	15.42	1.05	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:8	8.18	903	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.6	15.41	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:8	6.81	892	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.58	15.4	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:9	6.81	892	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.59	15.36	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:9	6.81	899	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.58	15.36	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:18:9	6.81	906	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.6	15.35	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:9	6.81	914	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.58	15.34	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:9	6.81	914	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.62	15.33	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:9	6.81	919	0.81	13.46	113	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.64	15.32	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:18:9	6.81	919	0.81	13.48	113	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.62	15.32	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:0	6.81	917	0.81	13.48	113	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.65	15.31	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:0	6.81	917	0.81	13.47	113	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.63	15.32	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:0	6.81	918	0.81	13.47	113	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.68	15.32	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:0	6.81	919	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.64	15.32	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:0	8.18	919	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.64	15.34	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:0	8.18	920	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.66	15.35	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:1	8.18	916	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	15.35	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:1	8.18	913	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	15.36	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:1	8.18	913	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.72	15.36	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:1	6.81	919	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.71	15.37	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:1	6.81	919	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.7	15.37	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:1	6.81	924	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.69	15.37	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:1	6.81	913	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.71	15.37	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:2	8.18	913	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.7	15.37	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:2	8.18	913	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.74	15.36	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:2	8.18	915	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.69	15.36	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:19:2	8.18	915	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.76	15.36	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:19:2	8.18	918	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.75	15.37	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:19:2	8.18	922	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.76	15.36	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:19:3	8.18	902	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.75	15.37	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:3	8.18	902	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.78	15.35	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:3	8.18	898	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.73	15.35	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:3	8.18	898	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.74	15.35	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:3	8.18	901	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.72	15.32	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:3	8.18	901	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.76	15.31	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:4	8.18	900	0.81	13.45	114	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.72	15.3	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:4	8.18	898	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.74	15.28	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:4	8.18	897	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.75	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:4	8.18	897	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.75	15.24	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:4	8.18	902	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.72	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:4	8.18	902	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.72	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:4	8.18	902	0.81	13.45	114	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.73	15.2	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:5	8.18	899	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.7	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:5	8.18	908	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.7	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:5	8.18	908	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.69	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:5	8.18	908	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.75	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:5	8.18	893	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.72	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:5	8.18	896	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.77	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:6	8.18	896	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.73	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:6	8.18	896	0.81	13.5	114	194	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.76	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:6	8.18	897	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.75	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:6	8.18	897	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.76	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:6	8.18	895	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.75	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:6	8.18	893	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.76	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:6	8.18	892	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.75	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:7	8.18	892	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.75	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:7	9.54	896	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.73	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:7	9.54	899	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.72	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:7	9.54	881	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.73	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:7	9.54	881	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.73	15.05	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:7	8.18	896	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.74	15.01	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:8	8.18	896	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.73	15.01	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:8	8.18	896	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.73	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:19:8	8.18	896	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.7	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:8	8.18	896	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.72	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:8	9.54	889	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.69	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:8	9.54	889	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.7	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:9	9.54	877	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:9	9.54	877	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.7	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:9	8.18	891	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.69	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:9	8.18	891	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.69	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:9	8.18	892	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.7	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:9	8.18	894	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:19:9	9.54	893	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:0	9.54	893	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:0	9.54	893	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.66	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:0	9.54	886	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:20:0	9.54	888	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.7	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:20:0	8.18	889	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.7	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:20:0	8.18	889	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.73	14.86	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:20:1	8.18	904	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.72	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:1	8.18	903	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.72	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:1	8.18	902	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:1	8.18	902	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.72	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:1	8.18	909	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:1	8.18	909	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.73	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:1	8.18	906	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.72	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:2	8.18	906	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:2	8.18	905	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:2	8.18	904	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.72	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:2	8.18	913	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:2	8.18	913	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.75	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:2	8.18	916	0.81	13.45	114	194	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.75	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:3	8.18	916	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.77	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:3	8.18	915	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.78	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:3	8.18	915	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.75	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:3	8.18	914	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.73	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:3	8.18	914	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.73	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:3	8.18	920	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.73	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:4	8.18	920	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.72	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:4	8.18	916	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.75	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:4	8.18	916	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.72	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:4	6.81	909	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.75	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:4	6.81	906	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.78	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:4	6.81	909	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.79	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:4	6.81	909	0.81	13.5	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.78	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:5	6.81	908	0.81	13.51	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.78	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:5	8.18	906	0.81	13.5	114	194	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.74	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:5	8.18	906	0.81	13.5	114	194	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.76	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:5	8.18	911	0.81	13.5	114	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.71	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:5	8.18	911	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.76	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:5	8.18	914	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.73	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:6	8.18	914	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.76	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:6	8.18	908	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.71	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:6	8.18	908	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.77	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:6	6.81	918	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.74	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:6	6.81	918	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.8	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:6	6.81	919	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.79	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:6	6.81	920	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.8	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:7	8.18	922	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.82	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:7	8.18	925	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:20:7	8.18	901	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.76	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:7	8.18	901	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.76	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:7	8.18	898	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.74	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:7	8.18	896	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.77	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:8	8.18	901	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.77	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:8	8.18	901	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:8	8.18	900	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.75	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:8	8.18	899	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.74	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:8	8.18	895	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.74	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:8	8.18	895	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:9	8.18	894	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:9	8.18	894	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:9	8.18	898	0.81	13.5	114	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:9	8.18	898	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:9	8.18	898	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.77	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:9	8.18	894	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:20:9	8.18	894	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:0	8.18	890	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.72	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:0	8.18	886	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:0	8.18	891	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:0	8.18	891	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:0	8.18	894	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.75	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:0	8.18	898	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:1	9.54	903	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:1	9.54	903	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:1	9.54	895	0.81	13.45	114	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:1	9.54	887	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:1	8.18	897	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:1	8.18	897	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:1	8.18	897	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:2	8.18	901	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:2	8.18	901	0.81	13.46	113	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.7	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:2	8.18	901	0.81	13.45	113	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:2	8.18	901	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.7	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:2	8.18	898	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:2	8.18	897	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.71	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:3	8.18	897	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.68	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:3	8.18	897	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:3	8.18	896	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:3	8.18	896	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:3	9.54	900	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:3	9.54	900	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.71	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:4	9.54	900	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:4	9.54	886	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:4	9.54	902	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:4	9.54	902	0.81	13.48	113	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:4	9.54	902	0.81	13.46	113	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.7	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:4	9.54	894	0.81	13.47	113	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.71	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:4	8.18	896	0.81	13.46	113	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.72	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:5	8.18	896	0.81	13.48	113	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.71	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:5	8.18	896	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:5	8.18	877	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:5	8.18	871	0.81	13.51	114	194	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:5	9.54	871	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.63	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:5	9.54	871	0.81	13.5	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.65	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:6	9.54	870	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.63	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:6	9.54	870	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.67	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:6	8.18	876	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:21:6	8.18	876	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:6	8.18	876	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:6	8.18	873	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.67	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:6	8.18	892	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.68	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:7	9.54	892	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.66	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:7	9.54	886	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.67	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:7	9.54	880	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.67	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:7	9.54	880	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.68	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:7	9.54	890	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.66	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:7	9.54	890	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:8	9.54	866	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.63	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:8	9.54	866	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.65	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:8	10.9	882	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.61	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:8	10.9	882	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.61	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:8	10.9	890	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.62	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:8	10.9	890	0.81	13.5	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.63	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:9	10.9	873	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.64	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:9	10.9	873	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.66	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:9	10.9	874	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.66	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:9	10.9	874	0.81	13.5	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.62	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:9	10.9	874	0.81	13.5	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.64	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:9	9.54	875	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.58	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:21:9	9.54	888	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.58	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:0	9.54	888	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.57	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:0	9.54	888	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.58	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:0	8.18	888	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.56	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:0	8.18	888	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.58	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:0	8.18	886	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.56	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:0	8.18	885	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.57	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:1	6.81	881	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.57	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:1	6.81	877	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.58	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:1	6.81	903	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.58	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:1	6.81	903	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.58	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:1	6.81	896	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.59	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:1	6.81	890	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.58	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:1	6.81	879	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.59	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:2	6.81	879	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.56	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:2	6.81	879	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.56	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:2	8.18	864	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.51	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:2	8.18	864	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.52	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:2	8.18	870	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.51	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:2	8.18	876	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.54	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:3	8.18	881	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.57	14.98	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:3	8.18	881	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.58	15.01	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:3	8.18	885	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.59	15.03	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:3	8.18	889	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.59	15.06	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:3	8.18	879	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.56	15.07	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:3	8.18	879	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.56	15.09	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:4	8.18	879	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.55	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:4	8.18	880	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.54	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:4	8.18	890	0.82	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.56	15.14	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:4	9.54	890	0.82	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.53	15.15	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:4	9.54	885	0.82	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.58	15.16	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:22:4	9.54	871	0.82	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.55	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:4	9.54	871	0.82	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.59	15.18	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:5	8.18	886	0.82	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:5	8.18	886	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.6	15.19	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:5	8.18	892	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:22:5	8.18	899	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.6	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:5	8.18	886	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.56	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:5	8.18	886	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:6	8.18	890	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:6	8.18	890	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.59	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:6	8.18	892	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.57	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:6	8.18	893	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:6	8.18	900	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:6	8.18	900	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.57	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:6	8.18	900	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.61	15.19	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:7	9.54	900	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	15.19	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:7	9.54	900	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.63	15.2	1.04	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:7	9.54	899	0.81	13.47	113	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.6	15.19	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:7	9.54	899	0.81	13.48	113	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.63	15.19	1.04	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:7	8.18	899	0.81	13.46	113	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.6	15.2	1.04	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:7	8.18	899	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.65	15.2	1.04	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:8	8.18	915	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.6	15.2	1.04	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:8	8.18	915	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.63	15.2	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:8	6.81	909	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.59	15.22	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:8	6.81	909	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.64	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:8	6.81	915	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.6	15.21	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:8	6.81	915	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.65	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:9	8.18	905	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.64	15.23	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:9	8.18	895	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.68	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:9	8.18	901	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.68	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:9	8.18	901	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.69	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:9	8.18	898	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.64	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:9	8.18	894	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.65	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:22:9	8.18	887	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.65	15.19	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:0	8.18	887	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.64	15.19	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:0	8.18	885	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.64	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:0	8.18	883	0.81	13.5	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.67	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:0	8.18	903	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.67	15.16	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:0	8.18	903	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.63	15.15	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:23:0	8.18	901	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.67	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:23:1	9.54	899	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.66	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:23:1	9.54	899	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.67	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:23:1	9.54	879	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.67	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:1	9.54	882	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.66	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:1	8.18	885	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.65	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:1	8.18	885	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.66	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:1	8.18	906	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.62	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:2	8.18	906	0.81	13.47	114	194	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.66	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:2	8.18	896	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.66	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:2	8.18	896	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.62	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:2	8.18	892	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.61	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:2	8.18	889	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.61	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:2	8.18	888	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.61	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:3	6.81	888	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.62	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:3	6.81	894	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.66	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:3	6.81	899	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.65	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:3	6.81	898	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.67	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:3	6.81	898	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.65	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:3	6.81	898	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.68	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:4	6.81	896	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.64	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:4	6.81	894	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.67	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:4	6.81	887	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.61	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:4	6.81	887	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.61	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:23:4	6.81	894	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.6	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:4	6.81	900	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.62	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:4	8.18	890	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.65	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:5	8.18	890	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.67	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:5	8.18	879	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.67	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:5	8.18	868	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.67	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:5	8.18	872	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.65	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:5	9.54	875	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.64	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:5	9.54	875	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.64	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:6	9.54	879	0.81	13.49	114	194	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.62	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:6	9.54	878	0.81	13.48	114	194	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.62	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:6	9.54	876	0.81	13.46	114	194	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.58	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:6	9.54	876	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.58	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:6	9.54	882	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.56	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:6	9.54	882	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.57	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:6	9.54	881	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.57	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:7	9.54	880	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.59	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:7	9.54	897	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.6	14.97	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:7	9.54	897	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.6	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:7	8.18	897	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.67	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:7	8.18	897	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.6	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:7	8.18	897	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.64	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:8	8.18	897	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.6	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:8	9.54	909	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.61	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:8	9.54	909	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.61	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:8	9.54	909	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.67	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:8	9.54	899	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:8	9.54	911	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:9	8.18	911	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.64	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:9	8.18	902	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.67	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:9	8.18	892	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.64	14.73	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:9	8.18	902	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.67	14.74	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:9	8.18	902	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.63	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:9	8.18	902	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.68	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:23:9	8.18	902	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.64	14.77	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:0	8.18	906	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.64	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:0	8.18	902	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.62	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:0	8.18	898	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.6	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:0	8.18	890	0.81	13.46	113	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.6	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:0	8.18	890	0.81	13.47	113	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.61	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:0	8.18	892	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.62	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:1	8.18	892	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.65	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:1	8.18	899	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.66	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:1	8.18	899	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.67	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:1	8.18	899	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:1	8.18	881	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.66	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:1	8.18	881	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.65	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:1	8.18	884	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.66	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:2	8.18	884	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.67	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:2	8.18	885	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.63	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:2	8.18	885	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.66	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:2	8.18	879	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.61	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:2	8.18	873	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.64	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:2	8.18	899	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.65	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:3	8.18	899	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.66	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:3	8.18	880	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.66	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:3	8.18	880	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:3	8.18	888	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.6	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:24:3	8.18	895	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.58	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:3	8.18	895	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.58	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:4	8.18	882	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.57	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:4	8.18	888	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.6	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:4	8.18	894	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.57	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:4	8.18	894	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.61	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:4	8.18	884	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.6	15.05	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:4	8.18	884	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.61	15.06	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:4	9.54	892	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.63	15.07	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:5	9.54	893	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.65	15.08	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:5	9.54	893	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.66	15.06	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:5	9.54	893	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.67	15.07	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:5	9.54	891	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.64	15.08	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:5	9.54	891	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.65	15.08	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:24:5	9.54	901	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.66	15.07	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:6	9.54	901	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.61	15.07	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:6	8.18	901	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.63	15.07	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:6	8.18	907	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.62	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:6	8.18	911	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.65	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:6	8.18	911	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.64	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:6	8.18	911	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.68	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:6	8.18	913	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.68	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:7	8.18	913	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.68	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:7	8.18	913	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.69	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:7	8.18	913	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:7	8.18	922	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:7	8.18	913	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.71	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:7	8.18	913	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.71	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:8	8.18	913	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.74	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:8	8.18	920	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.69	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:8	8.18	920	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.7	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:8	8.18	908	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.68	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:8	8.18	897	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:8	8.18	908	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.71	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:9	8.18	908	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.74	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:9	8.18	910	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.75	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:9	8.18	910	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.77	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:9	8.18	912	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.74	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:9	8.18	912	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.74	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:9	8.18	893	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.71	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:24:9	8.18	893	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:0	8.18	914	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.73	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:0	8.18	914	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.7	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:0	8.18	909	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:0	8.18	909	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:0	8.18	908	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:0	8.18	908	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:1	8.18	908	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:1	8.18	905	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:1	8.18	905	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:1	8.18	905	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:1	8.18	906	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:1	8.18	907	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:1	8.18	902	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:2	8.18	902	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.64	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:2	8.18	900	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:2	8.18	898	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.63	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:2	8.18	898	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:25:2	8.18	903	0.82	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:2	8.18	903	0.82	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:3	8.18	904	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:3	8.18	906	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:3	8.18	908	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:3	8.18	908	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:3	8.18	915	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:3	8.18	922	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:4	6.81	917	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:4	6.81	917	0.82	13.48	113	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:4	6.81	922	0.82	13.45	113	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.68	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:4	6.81	927	0.82	13.48	113	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:4	6.81	925	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:4	6.81	925	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:4	6.81	924	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:5	6.81	924	0.82	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:5	8.18	925	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.67	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:5	8.18	926	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:5	8.18	928	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:5	8.18	928	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:5	8.18	919	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	14.76	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:6	8.18	910	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	14.76	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:6	8.18	904	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	14.74	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:6	8.18	904	0.82	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.74	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:6	8.18	906	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.74	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:6	9.54	909	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	14.75	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:6	9.54	909	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.7	14.74	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:6	9.54	910	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.74	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:7	9.54	910	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	14.75	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:7	9.54	902	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:7	9.54	902	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:7	9.54	892	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:7	9.54	892	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:7	8.18	888	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:8	8.18	885	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:8	8.18	894	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:8	8.18	894	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:8	8.18	888	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:8	8.18	883	0.82	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.8	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:8	8.18	888	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:9	8.18	888	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.65	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:9	8.18	888	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:9	10.9	895	0.82	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.62	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:9	10.9	895	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:9	10.9	875	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:9	10.9	875	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:25:9	10.9	893	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:0	10.9	893	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:0	10.9	875	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:0	10.9	875	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.66	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:0	9.54	897	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.63	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:0	9.54	897	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.65	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:0	9.54	891	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.62	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:1	9.54	891	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.63	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:1	9.54	890	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.6	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:1	9.54	889	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.61	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:1	9.54	884	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.61	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:1	9.54	884	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.56	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:26:1	9.54	882	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.58	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:1	9.54	879	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.53	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:2	9.54	892	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.57	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:2	9.54	892	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.53	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:2	9.54	892	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.58	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:2	8.18	889	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.52	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:2	8.18	889	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.54	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:2	8.18	903	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.49	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:3	8.18	903	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.5	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:3	6.81	884	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.47	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:3	6.81	884	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.48	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:3	6.81	893	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.48	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:3	6.81	902	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.48	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:3	8.18	902	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.5	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:4	8.18	901	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.52	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:4	8.18	887	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.49	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:26:4	8.18	887	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.48	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:26:4	9.54	887	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.49	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:26:4	9.54	909	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.45	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:26:4	9.54	909	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.48	14.89	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:26:4	9.54	887	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.48	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:5	9.54	886	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.51	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:5	9.54	885	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.51	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:5	9.54	885	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.52	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:5	9.54	878	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.48	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:5	9.54	870	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.48	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:5	10.9	860	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.48	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:6	10.9	860	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.46	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:6	10.9	866	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.45	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:6	10.9	871	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.47	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:6	10.9	872	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.47	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:6	10.9	872	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.46	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:6	10.9	872	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.48	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:6	10.9	882	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.47	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:7	10.9	882	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.48	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:7	10.9	870	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.48	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:7	10.9	870	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.49	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:7	10.9	872	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.42	15.1	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:7	10.9	872	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.46	15.1	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:7	9.54	883	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.45	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:8	9.54	883	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.43	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:8	9.54	876	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.47	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:8	9.54	870	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.5	15.12	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:26:8	9.54	873	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.52	15.11	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:26:8	9.54	873	0.81	13.44	113	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.49	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:26:8	9.54	883	0.81	13.44	113	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.5	15.1	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:26:9	9.54	893	0.81	13.44	113	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.48	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:9	9.54	889	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.51	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:9	9.54	889	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.45	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:9	9.54	889	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.5	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:9	9.54	875	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.49	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:9	9.54	889	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.53	15.12	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:26:9	8.18	889	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.53	15.12	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:0	8.18	889	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.58	15.12	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:0	8.18	879	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.58	15.12	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:0	8.18	879	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.53	15.14	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:0	8.18	894	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.52	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:0	8.18	894	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.48	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:27:0	8.18	879	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.48	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:1	8.18	879	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.51	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:1	8.18	882	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.52	15.19	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:1	6.81	886	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.54	15.2	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:1	6.81	886	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.57	15.22	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:1	6.81	909	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.56	15.23	1.04	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:1	6.81	902	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.58	15.23	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:1	8.18	895	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.5	15.24	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:2	8.18	895	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.54	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:2	8.18	898	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.5	15.26	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:2	8.18	898	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.54	15.25	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:2	8.18	892	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.57	15.27	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:2	8.18	885	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.58	15.28	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:2	8.18	899	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.58	15.29	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:3	8.18	899	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.6	15.32	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:3	8.18	899	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.58	15.33	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:3	8.18	899	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	15.34	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:3	8.18	894	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	15.36	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:3	8.18	894	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	15.38	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:3	8.18	898	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	15.41	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:4	8.18	901	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	15.41	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:4	8.18	901	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.61	15.42	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:4	8.18	907	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.59	15.44	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:4	8.18	907	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.62	15.46	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:4	8.18	904	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.62	15.47	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:4	8.18	902	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.64	15.49	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:4	8.18	895	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	15.5	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:5	8.18	902	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.64	15.51	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:5	8.18	902	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	15.51	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:5	8.18	902	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.65	15.51	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:5	8.18	907	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	15.52	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:5	8.18	907	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.65	15.52	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:5	8.18	908	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	15.51	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:6	8.18	908	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	15.5	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:6	8.18	907	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	15.49	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:6	8.18	907	0.81	13.43	113	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.72	15.47	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:6	8.18	908	0.81	13.44	113	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	15.46	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:6	8.18	909	0.81	13.43	113	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	15.44	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:6	8.18	905	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.67	15.42	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:6	8.18	905	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	15.4	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:7	8.18	908	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.66	15.38	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:7	8.18	910	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.66	15.37	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:7	8.18	889	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	15.34	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:7	8.18	889	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	15.33	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:7	8.18	895	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	15.31	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:7	8.18	895	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.64	15.3	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:8	8.18	895	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.65	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:27:8	8.18	892	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.64	15.24	1.04	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:8	8.18	903	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	15.23	1.04	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:8	8.18	903	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.66	15.23	1.04	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:8	8.18	895	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.69	15.2	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:8	8.18	887	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.66	15.17	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:9	8.18	887	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.67	15.16	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:9	8.18	888	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.65	15.14	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:9	8.18	888	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.68	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:9	8.18	892	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.63	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:9	8.18	895	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.67	15.11	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:27:9	8.18	891	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.66	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:27:9	8.18	891	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.68	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:28:0	8.18	892	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.65	15.08	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:28:0	8.18	894	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.64	15.08	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:28:0	9.54	887	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.66	15.07	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:28:0	9.54	887	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.61	15.08	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:28:0	9.54	897	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.65	15.07	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:28:0	9.54	907	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.63	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:1	9.54	894	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.69	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:1	9.54	894	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.65	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:1	9.54	895	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.69	15.07	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:1	9.54	896	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.66	15.08	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:1	9.54	896	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.7	15.08	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:1	8.18	921	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.69	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:1	8.18	921	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.72	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:2	8.18	917	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:2	8.18	917	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.72	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:2	6.81	908	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.67	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:2	6.81	908	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.69	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:2	6.81	916	0.81	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.67	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:2	6.81	925	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.69	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:3	8.18	931	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.67	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:3	8.18	931	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.65	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:3	8.18	924	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:3	8.18	917	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:3	6.81	912	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.7	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:3	6.81	912	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:4	6.81	904	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.68	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:4	6.81	896	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:4	6.81	897	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:4	8.18	897	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:4	8.18	898	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:4	8.18	898	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:4	8.18	891	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:5	8.18	891	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:5	8.18	896	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:5	8.18	901	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:5	8.18	881	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.96	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:5	9.54	881	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:5	9.54	881	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:6	9.54	894	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	14.91	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:6	9.54	894	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	14.91	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:6	6.81	894	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.92	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:6	6.81	894	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:6	6.81	898	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:6	6.81	898	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:6	8.18	881	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:7	8.18	881	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:7	8.18	881	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:7	8.18	887	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:7	8.18	889	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:7	9.54	891	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.64	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:7	9.54	880	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:8	9.54	880	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.62	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:8	9.54	892	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:8	10.9	903	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.62	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:8	10.9	881	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:8	10.9	881	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.62	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:8	10.9	881	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:28:9	9.54	901	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.63	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:9	9.54	901	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.6	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:9	9.54	897	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.6	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:9	9.54	893	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.6	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:9	10.9	893	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.63	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:9	10.9	903	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.64	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:28:9	10.9	910	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.66	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:0	10.9	910	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.64	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:0	9.54	910	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.67	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:0	9.54	911	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.66	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:0	9.54	898	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.7	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:0	9.54	898	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:0	9.54	898	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:1	8.18	902	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.64	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:1	8.18	900	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.67	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:1	8.18	900	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.59	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:1	8.18	896	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.65	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:1	8.18	893	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.62	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:1	8.18	893	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.64	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:1	8.18	892	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.62	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:2	8.18	892	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.64	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:2	8.18	894	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.63	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:2	8.18	895	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.63	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:2	8.18	897	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.61	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:2	8.18	897	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.64	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:2	8.18	892	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:3	8.18	886	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.64	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:3	8.18	866	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.63	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:3	8.18	866	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.59	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:3	9.54	875	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.6	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:3	9.54	884	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.53	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:3	9.54	884	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.57	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:4	9.54	889	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.54	14.82	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:4	9.54	889	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.56	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:4	8.18	883	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.54	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:4	8.18	877	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.57	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:4	8.18	876	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.55	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:4	8.18	876	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.55	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:4	9.54	883	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.52	14.92	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:5	9.54	890	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.56	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:5	9.54	901	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.54	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:5	9.54	901	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.53	14.98	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:5	9.54	901	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.56	14.99	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:5	9.54	880	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.56	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:5	9.54	880	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:6	9.54	880	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.58	15	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:6	8.18	886	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.59	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:6	8.18	891	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.58	15	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:6	8.18	910	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.61	14.99	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:29:6	8.18	910	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.57	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:6	8.18	910	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.59	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:6	9.54	908	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.61	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:7	9.54	908	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.63	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:7	9.54	904	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.61	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:7	9.54	904	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.63	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:7	9.54	912	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.6	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:7	9.54	912	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.62	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:7	9.54	920	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.61	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:29:8	9.54	920	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.63	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:8	9.54	923	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:8	9.54	923	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.62	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:8	9.54	921	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.62	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:8	9.54	921	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:8	6.81	936	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.67	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:9	6.81	936	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.68	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:9	6.81	936	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.71	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:9	6.81	936	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.71	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:9	6.81	936	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	15.14	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:9	6.81	917	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.69	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:9	6.81	922	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.67	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:29:9	6.81	928	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	15.19	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:0	8.18	913	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.68	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:0	8.18	913	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:0	8.18	914	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.69	15.23	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:0	8.18	916	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.71	15.26	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:0	8.18	936	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.73	15.26	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:0	8.18	936	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.75	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:1	8.18	934	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.76	15.28	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:1	8.18	931	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.76	15.29	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:1	8.18	922	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.73	15.29	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:1	8.18	922	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.75	15.29	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:1	8.18	927	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.76	15.28	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:1	8.18	932	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.73	15.29	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:1	8.18	926	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.77	15.28	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:2	8.18	926	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.75	15.28	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:2	8.18	924	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	15.27	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:2	8.18	923	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.72	15.26	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:2	8.18	934	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.76	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:2	9.54	934	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.74	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:2	9.54	930	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.77	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:3	9.54	926	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:3	8.18	926	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.79	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:3	8.18	926	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.78	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:3	8.18	926	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.79	15.2	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:3	8.18	925	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	15.19	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:3	8.18	924	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.78	15.19	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:4	9.54	932	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:4	9.54	932	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:4	9.54	920	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:4	9.54	909	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:4	8.18	908	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:4	8.18	908	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:4	8.18	911	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:5	8.18	911	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:5	8.18	911	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:5	8.18	889	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:5	8.18	904	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:5	8.18	904	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:5	8.18	900	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:6	8.18	896	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:6	8.18	884	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:6	8.18	884	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:6	8.18	884	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:6	9.54	894	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:6	9.54	892	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:6	9.54	891	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:30:7	9.54	891	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:7	9.54	876	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:7	9.54	872	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:7	9.54	869	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:7	9.54	869	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.65	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:7	9.54	878	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.65	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:8	9.54	878	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.64	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:8	9.54	878	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.62	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:8	9.54	879	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.61	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:8	9.54	884	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.66	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:8	8.18	884	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.59	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:8	8.18	888	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:9	8.18	891	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.59	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:9	8.18	891	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.62	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:9	8.18	875	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.62	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:9	8.18	880	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.64	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:9	8.18	884	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.64	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:9	8.18	884	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.63	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:30:9	8.18	878	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.65	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:0	8.18	873	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.64	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:0	8.18	872	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.6	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:0	8.18	872	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.6	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:0	8.18	871	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.59	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:0	8.18	871	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.54	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:0	8.18	871	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.56	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:1	8.18	878	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.53	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:1	8.18	872	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.57	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:1	6.81	867	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.56	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:1	6.81	867	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.58	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:1	6.81	862	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.58	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:1	6.81	862	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.58	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:1	9.54	868	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.55	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:2	9.54	875	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.55	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:2	9.54	875	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.52	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:2	9.54	875	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.52	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:2	9.54	875	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.52	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:2	9.54	861	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.52	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:2	9.54	866	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.52	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:3	9.54	870	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.48	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:3	9.54	870	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.48	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:3	9.54	883	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.51	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:3	9.54	886	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.55	14.9	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:3	9.54	888	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.54	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:3	9.54	888	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.58	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:4	8.18	881	0.81	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.56	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:4	8.18	881	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.57	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:4	8.18	876	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.58	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:4	8.18	870	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.59	15.06	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:4	8.18	869	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.58	15.07	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:4	8.18	869	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.58	15.08	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:4	8.18	876	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.58	15.08	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:5	8.18	883	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.54	15.1	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:5	8.18	883	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.55	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:5	6.81	883	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.54	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:5	6.81	892	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.56	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:5	6.81	892	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.57	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:5	6.81	892	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.58	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:6	8.18	892	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.56	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:31:6	8.18	892	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.58	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:31:6	8.18	896	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.56	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:6	8.18	900	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.6	15.09	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:6	8.18	893	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.62	15.09	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:6	8.18	893	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.58	15.09	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:6	8.18	900	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:7	8.18	906	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.63	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:7	8.18	904	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.62	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:7	8.18	904	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.6	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:7	8.18	904	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.58	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:7	8.18	908	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.6	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:7	8.18	908	0.81	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.62	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:8	8.18	908	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.63	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:8	8.18	913	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.67	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:8	8.18	913	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.64	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:8	8.18	900	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.66	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:8	8.18	900	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.64	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:8	8.18	900	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.66	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:9	8.18	896	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.64	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:9	8.18	903	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.68	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:9	8.18	903	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.66	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:9	8.18	903	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.68	15.09	1.03	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:9	8.18	881	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.66	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:9	8.18	881	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.65	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:31:9	8.18	882	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.62	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:0	8.18	883	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.63	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:0	8.18	892	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.61	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:0	8.18	892	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:0	8.18	888	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.63	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:0	8.18	888	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:0	8.18	884	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:1	8.18	884	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:1	8.18	875	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:1	9.54	875	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:1	9.54	878	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:1	9.54	881	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.62	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:1	9.54	881	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.65	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:1	8.18	882	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.59	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:2	8.18	882	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.61	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:2	8.18	889	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.59	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:2	8.18	889	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.59	15.02	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:2	10.9	876	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.59	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:2	10.9	863	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.59	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:2	10.9	867	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.58	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:3	10.9	867	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.58	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:3	9.54	870	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.59	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:3	9.54	874	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.58	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:3	9.54	882	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.58	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:3	9.54	882	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.56	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:3	9.54	882	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.58	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:4	9.54	875	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.54	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:4	9.54	875	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.55	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:4	9.54	882	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.54	14.93	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:4	9.54	882	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.57	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:4	8.18	894	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.53	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:4	8.18	894	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.54	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:4	8.18	886	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.51	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:5	8.18	877	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.51	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:32:5	6.81	888	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.51	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:5	6.81	888	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.54	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:5	6.81	894	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.56	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:5	6.81	899	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.53	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:5	6.81	899	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.56	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:6	6.81	882	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.54	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:6	6.81	880	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.55	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:6	6.81	877	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.5	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:6	6.81	877	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.55	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:6	8.18	896	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.52	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:6	8.18	896	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.55	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:32:6	8.18	894	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.55	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:7	8.18	893	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.6	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:7	8.18	889	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.58	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:7	8.18	889	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.59	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:7	8.18	894	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.59	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:7	8.18	899	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.57	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:7	8.18	881	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.56	14.83	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:8	8.18	881	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.53	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:8	8.18	889	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.55	14.87	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:8	8.18	897	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.54	14.86	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:8	8.18	897	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.58	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:8	8.18	897	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.55	14.91	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:8	8.18	896	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.58	14.93	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:9	8.18	896	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.55	14.96	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:9	8.18	896	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.58	15.01	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:9	9.54	890	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.55	15.04	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:9	9.54	890	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.58	15.06	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:9	9.54	890	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.56	15.08	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:9	9.54	890	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.58	15.11	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:32:9	8.18	897	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.54	15.11	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:0	8.18	897	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.56	15.13	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:0	8.18	880	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.53	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:0	8.18	880	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.57	15.14	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:0	9.54	899	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.54	15.14	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:0	9.54	899	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.55	15.15	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:0	9.54	902	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.56	15.15	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:1	9.54	906	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.55	15.17	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:1	9.54	906	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.57	15.16	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:1	9.54	900	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.55	15.17	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:1	9.54	906	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.59	15.19	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:33:1	9.54	906	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.56	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:1	9.54	906	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.59	15.2	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:1	9.54	919	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.57	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:2	9.54	919	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.64	15.21	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:2	9.54	918	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.6	15.22	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:2	9.54	923	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.65	15.23	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:2	8.18	923	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.63	15.23	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:2	8.18	923	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.67	15.24	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:2	8.18	932	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.62	15.24	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:3	8.18	920	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.68	15.23	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:3	6.81	920	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.66	15.23	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:3	6.81	920	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.7	15.22	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:3	6.81	947	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.68	15.22	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:33:3	6.81	933	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.72	15.22	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:33:3	6.81	933	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.69	15.22	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:33:4	6.81	933	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.71	15.21	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:33:4	6.81	925	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:33:4	6.81	925	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.73	15.21	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:4	8.18	921	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.69	15.21	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:4	8.18	921	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.74	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:4	8.18	910	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:4	8.18	910	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.74	15.2	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:5	8.18	915	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	15.19	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:5	8.18	915	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	15.18	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:5	8.18	912	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	15.17	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:5	8.18	908	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.7	15.16	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:5	8.18	904	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:5	8.18	904	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:6	8.18	913	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:6	8.18	913	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:6	8.18	905	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:6	8.18	905	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:6	8.18	900	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:6	8.18	894	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:6	8.18	894	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:7	8.18	897	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:7	8.18	897	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:7	8.18	897	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:7	8.18	897	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:7	9.54	901	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:7	9.54	901	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:8	9.54	889	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:8	9.54	889	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:8	9.54	898	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:8	9.54	898	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:8	9.54	900	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:8	9.54	903	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:9	9.54	892	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:9	9.54	892	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:9	9.54	891	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:9	9.54	890	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:9	10.9	901	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.66	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:9	10.9	901	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:33:9	10.9	901	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:0	10.9	895	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.63	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:0	10.9	902	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.66	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:0	9.54	902	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:0	9.54	902	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.66	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:0	9.54	913	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.62	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:0	9.54	913	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.64	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:1	8.18	908	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:1	8.18	903	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:1	8.18	913	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:1	8.18	929	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:1	8.18	929	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:1	8.18	920	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.69	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:1	8.18	911	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.68	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:2	8.18	911	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.69	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:2	8.18	900	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.67	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:2	8.18	900	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:2	8.18	900	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:2	8.18	900	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:2	8.18	896	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:3	8.18	891	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.68	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:3	8.18	886	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.65	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:34:3	8.18	886	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.63	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:3	8.18	886	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:3	8.18	893	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.6	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:3	8.18	893	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:4	8.18	896	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:4	8.18	896	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:4	8.18	890	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.58	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:4	8.18	890	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.6	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:4	8.18	890	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.58	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:4	8.18	889	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.58	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:4	8.18	897	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.57	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:5	8.18	897	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.61	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:5	8.18	898	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.58	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:5	8.18	900	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.61	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:5	8.18	901	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.59	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:5	8.18	901	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.58	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:5	8.18	902	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.58	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:6	8.18	904	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.57	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:6	8.18	904	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.56	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:6	8.18	912	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.56	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:6	8.18	923	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.58	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:6	8.18	923	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.56	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:6	8.18	923	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.55	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:6	6.81	905	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.54	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:7	6.81	914	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.57	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:7	6.81	914	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.5	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:7	6.81	914	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.56	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:7	8.18	905	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.55	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:7	8.18	920	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.57	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:7	8.18	920	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.55	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:8	8.18	920	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.58	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:8	8.18	898	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.58	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:8	8.18	898	0.81	13.5	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.58	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:8	8.18	893	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.55	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:8	8.18	893	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.55	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:8	8.18	895	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.54	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:9	8.18	895	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.56	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:34:9	8.18	898	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.57	15.04	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:34:9	8.18	900	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.57	15.04	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:34:9	8.18	904	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.58	15.02	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:34:9	8.18	904	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.57	15.01	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:34:9	8.18	907	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.53	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:34:9	8.18	907	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.55	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:0	8.18	911	0.81	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.55	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:0	8.18	915	0.81	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.57	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:0	8.18	918	0.81	13.37	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.62	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:0	8.18	918	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.63	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:0	8.18	907	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.66	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:0	6.81	907	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.61	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:1	6.81	907	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.6	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:1	6.81	913	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.58	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:1	6.81	913	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.62	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:1	8.18	918	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.61	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:1	8.18	923	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:1	8.18	923	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.67	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:1	8.18	911	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:2	8.18	911	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:2	8.18	911	0.81	13.46	114	195	Idle	93.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:35:2	8.18	910	0.81	13.46	114	195	Idle	93.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.66	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:2	8.18	910	0.81	13.46	114	195	Idle	93.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:2	8.18	913	0.81	13.44	114	195	Idle	93.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.65	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:2	8.18	913	0.81	13.45	114	195	Idle	93.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.68	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:3	8.18	917	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.66	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:3	8.18	921	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:3	9.54	927	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:3	9.54	927	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:3	9.54	903	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:3	9.54	903	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:4	9.54	916	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:4	9.54	916	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.68	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:4	9.54	914	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:4	9.54	914	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:4	9.54	926	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:4	9.54	926	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:4	9.54	909	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:5	9.54	909	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:5	8.18	920	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:5	8.18	920	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:5	8.18	920	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:5	8.18	923	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:5	8.18	903	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:6	8.18	903	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:6	8.18	903	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:6	8.18	898	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:6	8.18	891	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.7	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:6	8.18	891	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:6	8.18	891	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:6	8.18	905	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.67	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:7	8.18	905	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:7	9.54	892	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:7	9.54	892	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:7	9.54	900	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:7	9.54	900	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:7	8.18	904	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.68	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:8	8.18	904	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:8	8.18	904	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:8	8.18	913	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.67	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:8	8.18	893	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.67	14.9	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:8	8.18	893	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.65	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:8	8.18	893	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.67	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:9	8.18	895	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.64	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:9	8.18	881	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.67	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:9	8.18	881	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.63	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:9	8.18	881	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.67	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:9	8.18	887	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.64	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:9	8.18	887	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.67	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:35:9	8.18	880	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.64	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:0	8.18	873	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.67	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:0	8.18	866	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.67	14.92	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:0	8.18	866	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.65	14.91	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:0	9.54	866	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.63	14.9	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:0	9.54	841	0.81	13.44	114	195	Idle	93.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.58	14.9	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:0	9.54	838	0.81	13.44	114	195	Idle	93.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.56	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:1	9.54	838	0.81	13.44	114	195	Idle	93.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.54	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:1	9.54	838	0.81	13.43	114	195	Idle	93	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.52	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:1	9.54	819	0.81	13.43	114	195	Idle	92.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.48	14.88	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:36:1	9.54	819	0.81	13.44	114	195	Idle	92.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.46	14.88	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:1	9.54	810	0.81	13.43	114	195	Idle	92.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.42	14.87	1.01	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:36:1	9.54	802	0.81	13.44	114	195	Idle	92.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.37	14.86	1.01	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:36:1	9.54	798	0.81	13.44	114	195	Idle	92.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.35	14.85	1.01	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:36:2	10.9	793	0.81	13.42	114	195	Idle	92.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.31	14.83	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:36:2	10.9	793	0.81	13.43	114	195	Idle	92.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.3	14.83	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:36:2	10.9	785	0.81	13.41	114	195	Idle	92	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.28	14.86	1.01	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:2	10.9	785	0.81	13.41	114	195	Idle	92	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.26	14.87	1.01	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:2	19.09	813	0.81	13.41	114	195	Idle	92.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.25	14.88	1.01	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:2	19.09	813	0.81	13.41	114	195	Idle	92.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.22	14.89	1.01	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:3	19.09	813	0.81	13.44	114	195	Idle	92.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.2	14.9	1.02	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:3	19.09	800	0.81	13.44	114	195	Idle	92.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.16	14.92	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:3	19.09	788	0.81	13.44	114	195	Idle	92.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.15	14.95	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:3	19.09	814	0.81	13.47	114	195	Idle	92.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.12	14.96	1.02	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:3	19.09	814	0.82	13.45	114	195	Idle	92.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.1	14.98	1.02	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:3	19.09	814	0.82	13.45	114	195	Idle	92.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.09	14.99	1.02	4.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:36:4	19.09	847	0.82	13.45	114	195	Idle	92.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.12	14.99	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:36:4	19.09	865	0.82	13.45	114	195	Idle	93	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.14	14.98	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:36:4	16.36	865	0.82	13.45	114	195	Idle	93.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.14	14.99	1.02	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:36:4	16.36	878	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.18	14.99	1.02	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:36:4	16.36	890	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.17	15	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:4	16.36	890	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.24	15.01	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:4	14.99	927	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.25	15.01	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:5	14.99	936	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.31	15.02	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:36:5	14.99	944	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.31	15.02	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:5	14.99	964	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.4	15.02	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:5	14.99	964	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.38	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:5	14.99	967	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.45	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:5	14.99	970	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.43	15.05	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:6	14.99	970	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.48	15.06	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:6	14.99	989	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.5	15.06	1.03	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:6	14.99	1001	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.58	15.06	1.03	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:6	14.99	1001	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	15.06	1.03	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:6	14.99	1001	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.63	15.06	1.03	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:6	14.99	997	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.62	15.09	1.03	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:6	14.99	988	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.67	15.09	1.03	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:7	14.99	988	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.66	15.09	1.03	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:7	13.63	1006	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.7	15.08	1.03	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:7	13.63	1006	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.77	15.07	1.03	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:7	13.63	1011	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.77	15.06	1.03	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:7	13.63	997	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.81	15.06	1.03	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:7	13.63	983	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.8	15.06	1.03	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:8	13.63	983	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.84	15.06	1.03	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:07:36:8	13.63	986	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.86	15.03	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:8	13.63	986	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.89	15.03	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:8	14.99	1001	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.89	15.04	1.02	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:8	14.99	1001	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.93	15.05	1.03	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:8	14.99	986	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.89	15.06	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:9	13.63	999	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.94	15.06	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:9	13.63	999	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.9	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:9	13.63	990	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.93	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:9	13.63	980	0.82	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.91	15.08	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:9	13.63	980	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.93	15.09	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:9	13.63	976	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.91	15.1	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:36:9	13.63	981	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.96	15.09	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:0	13.63	981	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.95	15.09	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:0	13.63	980	0.82	13.36	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.99	15.09	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:0	13.63	980	0.82	13.37	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.94	15.08	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:37:0	13.63	973	0.82	13.36	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.96	15.07	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:0	13.63	973	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.93	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:0	13.63	974	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.9	15.03	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:1	13.63	974	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.91	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:1	13.63	969	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.89	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:1	13.63	969	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.88	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:1	14.99	971	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.86	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:1	14.99	971	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.83	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:1	14.99	957	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.81	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:1	14.99	957	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.84	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:2	12.27	962	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.81	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:2	12.27	966	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.89	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:2	12.27	988	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.82	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:2	12.27	975	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.86	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:2	12.27	975	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.83	14.91	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:2	12.27	975	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.86	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:3	12.27	995	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.86	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:3	12.27	995	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.89	14.81	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:3	12.27	977	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.86	14.79	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:3	12.27	992	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.89	14.78	1.01	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:3	12.27	992	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.86	14.77	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:3	10.9	989	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.89	14.75	1	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:4	10.9	986	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.89	14.74	1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:4	10.9	970	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.9	14.74	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:4	10.9	970	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.89	14.76	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:4	10.9	972	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.88	14.77	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:4	10.9	973	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.83	14.78	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:4	10.9	973	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.86	14.79	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:37:4	10.9	977	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.82	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:5	12.27	964	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.89	14.64	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:5	12.27	964	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.88	14.64	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:5	12.27	950	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.91	14.64	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:5	12.27	935	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.89	14.65	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:5	12.27	955	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.89	14.66	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:5	12.27	955	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.87	14.69	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:6	12.27	952	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.89	14.71	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:6	12.27	948	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.88	14.74	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:6	10.9	948	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.87	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:6	10.9	937	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.89	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:6	10.9	940	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.89	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:6	10.9	940	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.89	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:6	10.9	940	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.9	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:7	10.9	939	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.88	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:7	10.9	942	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.89	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:7	10.9	942	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.85	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:7	9.54	934	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.89	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:7	9.54	934	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.86	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:7	9.54	934	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.86	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:8	9.54	945	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.88	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:8	9.54	950	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.87	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:8	9.54	950	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.86	15.26	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:8	9.54	950	0.82	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.86	15.26	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:8	9.54	950	0.82	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.86	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:8	9.54	947	0.82	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.89	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:9	9.54	947	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.9	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:9	9.54	944	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.89	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:9	9.54	941	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.89	15.28	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:9	8.18	944	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.87	15.29	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:37:9	8.18	944	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.86	15.28	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:9	8.18	944	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.85	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:37:9	8.18	944	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.86	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:0	8.18	931	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.88	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:0	8.18	931	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.86	15.26	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:0	8.18	920	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.83	15.26	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:0	8.18	920	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.85	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:0	8.18	925	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.83	15.24	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:0	8.18	925	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.84	15.23	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:1	8.18	936	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.84	15.21	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:1	8.18	936	0.82	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.83	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:1	8.18	930	0.82	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.81	15.19	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:1	8.18	924	0.82	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.8	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:1	8.18	930	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.79	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:1	8.18	930	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:1	8.18	927	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:2	8.18	927	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:2	8.18	932	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:2	8.18	937	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:2	8.18	926	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:2	9.54	926	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:2	9.54	926	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:3	9.54	927	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:3	9.54	927	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:3	9.54	933	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:3	9.54	932	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:3	9.54	931	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:3	9.54	931	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:4	8.18	934	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:4	8.18	936	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:4	8.18	937	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:4	8.18	937	0.82	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:4	8.18	928	0.82	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:4	8.18	932	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:4	8.18	936	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:5	8.18	936	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:5	8.18	930	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:5	8.18	930	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:5	8.18	934	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:5	8.18	934	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.83	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:5	8.18	922	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:6	8.18	922	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.83	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:6	8.18	930	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:6	8.18	938	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.83	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:6	8.18	912	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:6	8.18	912	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:6	8.18	923	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:6	8.18	934	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	14.8	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:7	8.18	930	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	14.78	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:7	8.18	930	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	14.77	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:7	8.18	930	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.76	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:7	8.18	930	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	14.75	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:7	8.18	927	0.82	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.73	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:7	8.18	924	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.73	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:8	8.18	909	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	14.72	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:8	8.18	909	0.82	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.73	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:8	6.81	909	0.82	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.72	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:8	6.81	909	0.82	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.71	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:38:8	6.81	915	0.82	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	14.7	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:8	6.81	915	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	14.7	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:9	8.18	916	0.82	13.38	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.68	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:9	8.18	916	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.68	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:9	8.18	879	0.82	13.39	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.68	1	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:9	8.18	879	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	14.67	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:9	8.18	886	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	14.65	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:9	8.18	892	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.65	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:38:9	8.18	898	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.64	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:0	8.18	898	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.63	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:0	8.18	898	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.62	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:0	8.18	888	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.63	1	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:0	8.18	878	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.62	1	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:0	8.18	878	0.82	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.61	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:0	8.18	878	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.6	0.99	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:1	9.54	891	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.59	0.99	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:1	9.54	891	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.6	0.99	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:1	9.54	886	0.82	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	14.6	0.99	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:1	9.54	881	0.82	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	14.6	0.99	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:1	9.54	881	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	14.6	0.99	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:1	8.18	881	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.6	14.61	1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:1	8.18	899	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	14.61	0.99	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:2	8.18	899	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.59	14.62	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:2	8.18	894	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.63	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:2	9.54	888	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.57	14.65	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:2	9.54	888	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	14.65	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:2	9.54	889	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.6	14.66	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:2	9.54	897	0.82	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.68	1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:3	10.9	905	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.6	14.69	1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:3	10.9	905	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	14.69	1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:3	10.9	890	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.7	1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:3	10.9	898	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.6	14.71	1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:3	9.54	898	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.59	14.72	1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:3	9.54	905	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	14.73	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:4	9.54	899	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.62	14.73	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:4	9.54	899	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.75	1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:4	9.54	906	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.59	14.75	1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:4	9.54	912	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	14.74	1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:4	9.54	897	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.59	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:4	9.54	897	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.59	14.74	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:39:4	8.18	902	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.61	14.75	1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:39:5	8.18	908	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.61	14.74	1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:39:5	8.18	908	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.74	1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:39:5	8.18	908	0.81	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.6	14.74	1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:39:5	8.18	904	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.74	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:39:5	8.18	899	0.81	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.57	14.75	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:39:5	8.18	899	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.62	14.76	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:39:6	8.18	887	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.6	14.76	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:6	8.18	887	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.61	14.76	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:6	8.18	882	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.58	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:6	8.18	878	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.61	14.77	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:6	8.18	890	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.62	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:6	8.18	890	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.61	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:6	9.54	879	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.63	14.79	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:7	9.54	879	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.62	14.78	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:7	9.54	872	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.66	14.79	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:7	9.54	872	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.59	14.8	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:7	10.9	866	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.61	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:39:7	10.9	866	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.56	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:7	10.9	864	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.58	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:8	10.9	864	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.55	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:8	10.9	867	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.58	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:8	8.18	858	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.56	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:8	8.18	858	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.57	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:8	8.18	856	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.51	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:8	8.18	855	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.52	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:9	10.9	859	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.49	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:9	10.9	859	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.5	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:39:9	10.9	861	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.51	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:39:9	10.9	863	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.51	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:39:9	10.9	854	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.53	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:39:9	9.54	854	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.49	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:39:9	9.54	854	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.5	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:0	9.54	858	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.46	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:0	9.54	858	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.48	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:0	9.54	862	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.47	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:0	9.54	866	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.48	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:0	9.54	866	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.48	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:0	9.54	873	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.48	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:1	9.54	867	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.49	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:1	8.18	867	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.5	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:1	8.18	867	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.51	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:1	8.18	870	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.51	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:1	8.18	870	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.51	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:1	9.54	878	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.48	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:1	9.54	878	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.48	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:2	9.54	876	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.44	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:40:2	9.54	876	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.47	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:40:2	8.18	875	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.45	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:40:2	8.18	875	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.45	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:40:2	8.18	878	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.46	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:40:2	8.18	880	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.46	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:40:3	9.54	877	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.47	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:40:3	9.54	877	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.48	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:40:3	9.54	872	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.49	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:40:3	9.54	867	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.48	15.07	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:3	9.54	873	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.48	15.09	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:3	9.54	873	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.47	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:4	9.54	873	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.47	15.11	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:4	9.54	861	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.45	15.12	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:4	9.54	861	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.46	15.12	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:4	9.54	857	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.42	15.12	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:4	9.54	853	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.43	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:4	9.54	860	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.41	15.15	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:4	9.54	860	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.43	15.17	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:5	9.54	860	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.45	15.19	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:5	9.54	851	0.81	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.46	15.2	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:5	9.54	851	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.47	15.21	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:5	9.54	850	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.44	15.22	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:5	9.54	849	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.44	15.22	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:5	9.54	832	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.41	15.24	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:6	9.54	832	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.4	15.25	1.04	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:6	9.54	832	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.39	15.27	1.04	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:6	9.54	842	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.39	15.28	1.04	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:6	9.54	824	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.38	15.28	1.04	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:6	10.9	824	0.81	13.43	114	195	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.38	15.29	1.04	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:40:6	10.9	824	0.81	13.43	114	195	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.37	15.28	1.04	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:40:6	10.9	816	0.81	13.42	114	195	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.35	15.3	1.04	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:7	10.9	816	0.81	13.43	114	195	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.32	15.31	1.04	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:7	10.9	810	0.81	13.44	114	195	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.31	15.31	1.04	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:7	10.9	805	0.81	13.43	114	195	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.27	15.31	1.04	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:7	10.9	803	0.81	13.42	114	195	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.25	15.31	1.04	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:7	10.9	803	0.81	13.41	114	195	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.24	15.3	1.04	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:7	10.9	803	0.81	13.41	114	195	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.24	15.29	1.04	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:8	19.09	825	0.81	13.42	114	195	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.22	15.29	1.04	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:8	19.09	825	0.81	13.42	114	195	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.21	15.29	1.04	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:8	19.09	825	0.81	13.44	114	195	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.17	15.28	1.04	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:40:8	19.09	784	0.81	13.42	114	195	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.13	15.27	1.04	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:40:8	19.09	803	0.81	13.43	114	195	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.1	15.27	1.04	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:40:8	17.72	803	0.81	13.42	114	195	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.09	15.27	1.04	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:40:9	17.72	803	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.08	15.26	1.04	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:40:9	17.72	813	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.08	15.25	1.04	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:9	17.72	813	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.1	15.25	1.04	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:9	17.72	812	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.08	15.24	1.04	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:9	17.72	812	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.06	15.23	1.04	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:9	17.72	817	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.06	15.22	1.04	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:40:9	17.72	817	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.06	15.21	1.04	5.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:0	17.72	817	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.06	15.19	1.03	5.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:0	17.72	801	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.04	15.18	1.03	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:0	17.72	801	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.06	15.17	1.03	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:0	17.72	816	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.07	15.17	1.03	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:0	17.72	831	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.07	15.16	1.03	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:0	17.72	831	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.09	15.14	1.03	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:1	16.36	826	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.1	15.13	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:1	16.36	829	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.11	15.13	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:1	16.36	829	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.13	15.12	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:1	16.36	829	0.8	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.12	15.11	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:1	16.36	839	0.8	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.1	15.1	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:1	16.36	839	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.12	15.1	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:1	16.36	837	0.8	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.11	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:2	16.36	837	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.13	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:2	16.36	837	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.16	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:2	14.99	834	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.17	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:2	14.99	834	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.16	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:2	14.99	834	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.17	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:2	14.99	833	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.19	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:3	16.36	841	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.18	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:3	16.36	841	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.17	15.12	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:3	16.36	838	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.16	15.12	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:3	16.36	836	0.8	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.12	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:3	13.63	820	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.11	15.12	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:3	13.63	820	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.15	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:4	13.63	820	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.15	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:4	13.63	841	0.8	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.19	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:4	13.63	841	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.2	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:4	14.99	845	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.21	15.1	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:4	14.99	845	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.18	15.1	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:4	14.99	840	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.2	15.08	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:4	14.99	834	0.8	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.18	15.08	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:5	14.99	823	0.8	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.17	15.06	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:5	13.63	823	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.17	15.07	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:5	13.63	823	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.18	15.06	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:5	13.63	832	0.8	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.16	15.05	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:5	13.63	832	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.17	15.04	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:41:5	13.63	824	0.8	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.17	15.03	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:6	13.63	815	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.17	15.02	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:6	13.63	811	0.8	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.19	15.01	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:6	13.63	811	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.2	15.02	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:6	13.63	811	0.8	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.19	15.03	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:6	10.9	802	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.18	15.02	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:6	10.9	802	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.16	15.01	1.02	5.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:6	10.9	802	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.13	15.01	1.02	5.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:41:7	10.9	782	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.08	14.99	1.02	5.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:7	10.9	782	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.07	14.98	1.02	5.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:7	12.27	766	0.8	13.44	114	195	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.04	14.95	1.02	5.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:7	12.27	751	0.8	13.43	114	195	Idle	93.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.01	14.94	1.02	5.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:7	12.27	796	0.8	13.43	114	195	Idle	93.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.01	14.92	1.02	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:7	12.27	796	0.8	13.41	114	195	Idle	92.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.99	14.89	1.01	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:8	12.27	739	0.8	13.43	114	196	Idle	92.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.95	14.86	1.01	5.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:8	23.18	739	0.8	13.4	114	196	Idle	92.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.96	14.85	1.01	5.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:8	23.18	739	0.8	13.43	114	196	Idle	92.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.84	14.85	1.01	5.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:8	23.18	750	0.8	13.45	114	195	Idle	92.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.86	14.85	1.01	5.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:8	23.18	750	0.8	13.42	114	195	Idle	92.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.84	14.85	1.01	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:8	23.18	750	0.8	13.43	114	196	Idle	92.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.83	14.86	1.01	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:9	21.81	756	0.8	13.42	114	196	Idle	92.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.85	14.86	1.01	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:9	21.81	756	0.8	13.42	114	196	Idle	92.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.85	14.86	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:9	21.81	785	0.8	13.43	114	196	Idle	92.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.85	14.86	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:41:9	21.81	785	0.8	13.42	114	195	Idle	93	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.8	14.85	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:9	21.81	785	0.8	13.45	114	195	Idle	93	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.81	14.85	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:9	17.72	765	0.8	13.44	114	196	Idle	93.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.85	14.83	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:41:9	17.72	765	0.8	13.44	114	196	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.81	14.82	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:0	17.72	785	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.86	14.81	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:0	17.72	785	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.84	14.79	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:0	17.72	790	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.83	14.78	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:0	17.72	796	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.85	14.77	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:0	17.72	787	0.8	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.82	14.75	1	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:0	17.72	787	0.8	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.83	14.75	1	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:1	17.72	787	0.8	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.84	14.75	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:1	17.72	789	0.8	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.84	14.76	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:1	17.72	789	0.8	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.81	14.75	1	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:1	17.72	789	0.8	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.84	14.74	1	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:1	17.72	772	0.8	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.83	14.74	1	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:1	17.72	772	0.8	13.4	114	195	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.81	14.76	1.01	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:1	17.72	784	0.8	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.84	14.74	1	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:2	17.72	784	0.8	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.84	14.75	1	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:2	17.72	786	0.79	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.82	14.74	1	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:2	17.72	788	0.79	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.84	14.74	1	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:2	17.72	788	0.79	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.82	14.74	1	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:2	17.72	770	0.79	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.85	14.75	1	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:2	17.72	753	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.82	14.75	1	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:3	17.72	771	0.79	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.85	14.77	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:3	17.72	771	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.83	14.8	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:3	17.72	771	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.81	14.82	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:3	17.72	778	0.79	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.85	14.83	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:3	17.72	778	0.79	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.81	14.85	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:3	17.72	781	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.84	14.86	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:4	17.72	784	0.79	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.82	14.86	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:4	17.72	784	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.79	14.87	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:4	21.81	795	0.79	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.82	14.88	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:4	21.81	795	0.79	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.77	14.88	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:4	21.81	772	0.79	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.82	14.86	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:4	21.81	772	0.79	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.81	14.85	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:42:4	16.36	788	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.84	14.85	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:5	16.36	803	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.86	14.84	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:5	16.36	803	0.79	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.87	14.84	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:42:5	16.36	816	0.79	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.91	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:5	16.36	829	0.79	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.94	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:5	16.36	829	0.79	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.96	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:5	16.36	829	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.94	14.9	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:6	16.36	838	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.97	14.9	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:6	16.36	838	0.79	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.94	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:6	14.99	842	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.96	14.98	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:6	14.99	846	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7	15	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:6	14.99	861	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.01	15.03	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:6	14.99	861	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.07	15.05	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:6	14.99	861	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.09	15.05	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:7	14.99	852	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.1	15.05	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:7	14.99	852	0.79	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.14	15.04	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:7	14.99	850	0.79	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.15	15.06	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:7	14.99	849	0.79	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.16	15.06	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:7	14.99	866	0.79	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.19	15.03	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:7	14.99	866	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.19	15.03	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:8	14.99	872	0.79	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.21	15.01	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:42:8	14.99	879	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.2	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:8	14.99	879	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.26	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:8	14.99	875	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.26	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:8	14.99	872	0.79	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.3	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:8	14.99	872	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.3	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:9	14.99	870	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.32	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:9	13.63	877	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.3	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:9	13.63	877	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.32	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:9	13.63	888	0.8	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.31	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:9	13.63	898	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.33	14.98	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:9	13.63	891	0.8	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.35	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:42:9	13.63	891	0.8	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.33	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:0	13.63	891	0.8	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.38	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:0	13.63	884	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.39	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:0	13.63	904	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.45	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:0	13.63	904	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.44	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:0	13.63	905	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.48	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:0	13.63	906	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.48	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:1	13.63	907	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.49	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:1	13.63	907	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.41	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:1	13.63	907	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.45	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:1	13.63	918	0.8	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.43	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:1	13.63	893	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.48	15.16	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:1	13.63	893	0.8	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.48	15.18	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:1	13.63	893	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.54	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:2	13.63	911	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.54	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:2	13.63	911	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.58	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:2	13.63	911	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:2	13.63	911	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.61	15.22	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:2	13.63	890	0.81	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	15.23	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:2	13.63	890	0.81	13.37	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.61	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:3	13.63	896	0.81	13.36	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.61	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:3	13.63	903	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:3	13.63	913	0.81	13.37	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	15.24	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:3	13.63	913	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:3	13.63	904	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:3	13.63	896	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:43:4	13.63	896	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:4	13.63	896	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:4	12.27	904	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:4	12.27	913	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	15.27	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:4	12.27	913	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	15.27	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:4	12.27	898	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	15.28	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:4	12.27	897	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	15.3	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:5	12.27	897	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.59	15.32	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:5	12.27	896	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.59	15.33	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:5	12.27	897	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.34	1.05	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:43:5	12.27	897	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.35	1.05	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:43:5	12.27	884	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.37	1.05	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:43:5	12.27	884	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	15.37	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:43:6	12.27	901	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.61	15.4	1.05	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:6	12.27	901	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	15.42	1.05	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:6	12.27	906	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	15.42	1.05	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:6	12.27	910	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.42	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:6	12.27	910	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.43	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:6	12.27	903	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	15.45	1.05	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:43:6	10.9	899	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	15.45	1.05	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:43:7	10.9	899	0.81	13.42	114	196	Idle	93.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.48	1.05	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:43:7	10.9	899	0.81	13.4	114	196	Idle	93.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.61	15.48	1.05	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:43:7	10.9	921	0.81	13.42	114	196	Idle	93.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	15.49	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:7	10.9	921	0.81	13.41	114	196	Idle	93.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	15.51	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:7	10.9	921	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.52	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:7	10.9	921	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.52	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:8	10.9	912	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	15.52	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:8	10.9	912	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.52	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:8	10.9	936	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.53	15.52	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:8	10.9	926	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.5	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:8	10.9	916	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	15.49	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:8	10.9	916	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	15.48	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:9	10.9	916	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.56	15.45	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:9	10.9	893	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.58	15.45	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:9	10.9	893	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.55	15.44	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:9	10.9	893	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.58	15.42	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:9	9.54	898	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.56	15.42	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:9	9.54	909	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.6	15.4	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:43:9	9.54	909	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.58	15.4	1.05	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:0	9.54	909	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.59	15.38	1.05	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:0	9.54	905	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.56	15.36	1.05	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:0	9.54	905	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.58	15.35	1.05	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:0	9.54	904	0.81	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.56	15.33	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:0	9.54	903	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.57	15.32	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:0	9.54	910	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.57	15.3	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:1	9.54	910	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.58	15.29	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:1	9.54	915	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.6	15.28	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:1	9.54	920	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.59	15.26	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:1	9.54	908	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.62	15.24	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:1	9.54	908	0.81	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.61	15.24	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:1	9.54	908	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.67	15.22	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:1	9.54	908	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.63	15.2	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:2	8.18	908	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.68	15.19	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:2	8.18	906	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.59	15.19	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:2	8.18	906	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.62	15.18	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:2	8.18	905	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.59	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:2	8.18	905	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.62	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:2	8.18	895	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.64	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:44:3	8.18	887	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.68	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:3	8.18	879	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.65	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:3	8.18	879	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.65	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:3	9.54	890	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.61	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:3	9.54	890	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.61	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:3	9.54	873	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.58	15.07	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:4	9.54	873	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.61	15.06	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:4	9.54	874	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.63	15.05	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:4	9.54	874	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.6	15.04	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:4	9.54	870	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.65	15.02	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:4	9.54	867	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.6	15.02	1.02	5.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:4	9.54	850	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.63	15.03	1.02	5.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:4	9.54	850	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.56	15.02	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:5	9.54	850	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.56	15.02	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:5	9.54	865	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.48	15.01	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:5	9.54	865	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.49	15.01	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:5	9.54	862	0.81	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.49	15	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:5	9.54	860	0.81	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.48	14.99	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:5	9.54	869	0.81	13.37	114	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.47	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:6	9.54	869	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.48	14.96	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:6	9.54	866	0.81	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.48	14.94	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:6	9.54	864	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.48	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:6	9.54	878	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.49	14.91	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:6	9.54	878	0.81	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.48	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:6	9.54	874	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.49	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:6	8.18	870	0.81	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.47	14.91	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:7	8.18	870	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.49	14.91	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:7	8.18	861	0.81	13.38	114	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.46	14.9	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:7	8.18	861	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.49	14.9	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:7	8.18	853	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.48	14.9	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:7	8.18	853	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.48	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:7	8.18	863	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.48	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:8	8.18	873	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.47	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:8	8.18	873	0.81	13.39	114	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.49	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:8	8.18	874	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.45	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:8	8.18	876	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.48	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:8	8.18	879	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.47	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:8	8.18	879	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.48	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:9	8.18	894	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.47	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:9	8.18	894	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.51	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:44:9	8.18	886	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.49	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:9	8.18	879	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.49	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:9	6.81	888	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.52	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:9	6.81	888	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.51	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:44:9	6.81	888	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.53	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:0	6.81	887	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.55	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:0	9.54	888	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.5	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:0	9.54	888	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.5	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:0	9.54	888	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.5	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:0	9.54	881	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.46	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:0	9.54	890	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.47	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:1	9.54	890	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.47	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:1	9.54	886	0.81	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.48	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:1	9.54	882	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.48	14.82	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:1	9.54	921	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.52	14.81	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:1	9.54	921	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.49	14.81	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:1	9.54	916	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.55	14.82	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:45:1	9.54	911	0.81	13.4	114	196	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.5	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:45:2	9.54	911	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.55	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:2	9.54	909	0.81	13.41	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.52	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:2	9.54	909	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.54	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:2	9.54	901	0.81	13.42	114	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.54	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:2	9.54	915	0.81	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.57	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:2	8.18	915	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.57	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:3	8.18	915	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.59	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:3	8.18	915	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.58	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:3	8.18	913	0.81	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.6	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:3	8.18	934	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.6	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:3	8.18	934	0.81	13.44	114	196	Idle	93.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.59	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:3	8.18	920	0.81	13.43	114	196	Idle	93.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.6	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:4	8.18	906	0.81	13.47	114	196	Idle	93.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.57	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:4	8.18	906	0.81	13.47	114	196	Idle	93.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.6	15.05	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:4	8.18	933	0.81	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.61	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:4	8.18	930	0.81	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.6	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:4	8.18	927	0.81	13.48	114	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.62	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:4	8.18	925	0.81	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.64	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:4	8.18	925	0.81	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.61	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:5	8.18	908	0.81	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.61	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:5	8.18	908	0.81	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.6	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:5	8.18	914	0.81	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.59	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:5	8.18	921	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.57	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:5	8.18	922	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.61	15.1	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:45:5	8.18	922	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.6	15.09	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:45:6	8.18	920	0.81	13.48	114	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	15.1	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:45:6	8.18	917	0.81	13.49	114	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.6	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:45:6	8.18	898	0.81	13.49	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.61	15.08	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:45:6	8.18	898	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.59	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:6	8.18	901	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.61	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:6	9.54	904	0.81	13.48	114	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.6	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:6	9.54	904	0.81	13.48	114	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.65	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:7	9.54	907	0.81	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.63	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:7	9.54	907	0.81	13.48	114	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:7	9.54	901	0.81	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.59	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:7	9.54	901	0.81	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.62	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:7	9.54	898	0.81	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.6	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:7	9.54	898	0.81	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.6	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:8	8.18	899	0.81	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.6	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:8	8.18	899	0.81	13.47	114	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.59	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:8	8.18	905	0.81	13.46	114	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.61	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:8	8.18	911	0.81	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.6	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:8	8.18	904	0.81	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.62	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:8	8.18	904	0.81	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.62	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:9	8.18	904	0.81	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.61	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:9	8.18	892	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.59	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:9	8.18	891	0.81	13.48	114	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.58	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:9	8.18	890	0.81	13.48	114	196	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.58	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:9	8.18	890	0.81	13.48	114	196	Full Load	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.59	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:9	8.18	884	0.82	13.46	114	195	Off Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.59	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:45:9	8.18	884	0.82	13.46	114	195	Off Idle	92.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.58	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:46:0	9.54	889	0.83	13.46	114	195	Off Idle	92.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.52	14.94	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:46:0	9.54	884	0.84	13.46	114	196	Off Idle	91.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.5	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:46:0	9.54	879	0.86	13.44	114	196	Off Idle	91.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.39	14.89	1.01	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:46:0	9.54	879	0.87	13.48	114	196	Off Idle	89.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.33	14.89	1.01	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:46:0	10.9	888	0.88	13.46	114	196	Off Idle	89.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.23	14.89	1.01	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:46:0	10.9	888	0.91	13.48	114	196	Off Idle	88.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.06	14.89	1.01	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:46:1	10.9	881	0.93	13.45	114	196	Off Idle	88.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.96	14.89	1.01	4.7	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:46:1	10.9	881	0.96	13.46	114	196	Off Idle	87.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.8	14.89	1.01	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:1	10.9	884	0.98	13.46	114	196	Off Idle	87.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.68	14.87	1.01	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:1	10.9	888	1	13.47	114	196	Off Idle	87.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.64	14.87	1.01	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:1	10.9	888	1.04	13.46	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.44	14.87	1.01	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:1	10.9	888	1.06	13.47	114	196	Off Idle	86	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.26	14.87	1.01	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:07:46:1	9.54	899	1.11	13.46	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.14	14.85	1.01	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:07:46:2	9.54	910	1.13	13.46	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.88	14.84	1.01	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:07:46:2	9.54	919	1.16	13.46	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.74	14.83	1.01	4.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:07:46:2	9.54	919	1.19	13.46	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.61	14.83	1.01	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:46:2	9.54	921	1.24	13.48	114	196	Off Idle	85	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.51	14.82	1.01	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:46:2	8.18	923	1.26	13.47	114	196	Off Idle	85	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.35	14.85	1.01	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:46:2	8.18	923	1.29	13.48	114	196	Off Idle	85	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.19	14.86	1.01	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:46:3	8.18	950	1.3	13.48	114	196	Off Idle	85.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.11	14.88	1.01	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:3	9.54	986	1.32	13.5	114	196	Off Idle	85.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.06	14.9	1.02	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:3	9.54	986	1.35	13.49	114	196	Off Idle	85.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.86	14.94	1.02	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:3	9.54	986	1.37	13.46	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.8	14.98	1.02	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:3	9.54	985	1.39	13.48	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.68	15.03	1.02	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:3	9.54	997	1.4	13.47	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.62	15.07	1.03	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:4	9.54	997	1.42	13.48	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.56	15.09	1.03	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:4	9.54	1004	1.43	13.46	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.47	15.11	1.03	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:4	9.54	1012	1.44	13.48	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.43	15.13	1.03	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:4	9.54	1024	1.45	13.46	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.36	15.15	1.03	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:4	9.54	1024	1.46	13.48	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.31	15.17	1.03	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:4	9.54	1011	1.46	13.46	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.23	Rich	1	14.6	-4.28	15.18	1.03	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:46:4	9.54	1008	1.47	13.45	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.2	15.21	1.04	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:46:5	9.54	1008	1.47	13.43	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.13	15.22	1.04	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:46:5	9.54	1006	1.48	13.47	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.09	15.23	1.04	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:46:5	9.54	1006	1.48	13.44	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4	15.25	1.04	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:5	12.27	1006	1.48	13.45	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.01	15.25	1.04	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:5	12.27	1019	1.48	13.45	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.9	15.26	1.04	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:5	12.27	1000	1.48	13.46	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.92	15.27	1.04	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:6	12.27	1000	1.49	13.46	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.82	15.29	1.04	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:6	12.27	1002	1.49	13.45	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.82	15.29	1.04	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:6	12.27	1002	1.5	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.71	15.29	1.04	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:6	12.27	1002	1.5	13.46	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.73	15.3	1.04	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:6	12.27	995	1.51	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.62	15.3	1.04	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:6	10.9	994	1.51	13.48	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.62	15.31	1.04	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:6	10.9	1000	1.51	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.57	15.3	1.04	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:7	10.9	1005	1.52	13.46	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.53	15.3	1.04	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:46:7	10.9	1005	1.52	13.49	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.5	15.28	1.04	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:46:7	21.81	1055	1.52	13.47	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.49	15.27	1.04	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:46:7	21.81	990	1.52	13.5	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.45	15.28	1.04	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:46:7	21.81	990	1.52	13.48	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.39	15.24	1.04	4.7	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:46:7	21.81	990	1.52	13.51	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.41	15.21	1.04	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:46:8	21.81	1006	1.53	13.5	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.35	15.12	1.03	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:46:8	21.81	1006	1.53	13.47	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.38	15	1.02	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:46:8	21.81	1013	1.53	13.49	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.32	14.91	1.02	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:8	21.81	1002	1.53	13.47	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.35	14.8	1.01	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:8	21.81	1002	1.53	13.46	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.3	14.74	1	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:46:8	21.81	996	1.52	13.48	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.36	14.54	0.99	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:9	21.81	990	1.52	13.5	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.31	14.36	0.98	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:9	21.81	1012	1.52	13.47	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.35	14.21	0.97	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:9	21.81	1012	1.52	13.5	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.31	14.07	0.96	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:9	21.81	1007	1.52	13.46	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.36	13.93	0.95	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:9	21.81	1002	1.51	13.5	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.31	13.8	0.94	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:9	21.81	1000	1.51	13.46	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.33	13.69	0.93	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:46:9	21.81	1000	1.51	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.27	13.58	0.93	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:0	21.81	991	1.51	13.47	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.26	13.45	0.92	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:47:0	21.81	991	1.51	13.5	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.3	13.39	0.91	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:0	21.81	986	1.5	13.47	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.22	13.3	0.91	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:0	21.81	972	1.5	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.3	13.25	0.9	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:0	21.81	972	1.5	13.48	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.23	13.22	0.9	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:0	23.18	972	1.5	13.48	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.26	13.2	0.9	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:1	23.18	960	1.5	13.49	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.24	13.18	0.9	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:1	23.18	959	1.5	13.49	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.24	13.17	0.9	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:1	23.18	958	1.5	13.5	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.19	13.16	0.9	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:1	23.18	958	1.49	13.5	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.23	13.16	0.9	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:1	21.81	950	1.49	13.47	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.13	13.16	0.9	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:1	21.81	950	1.49	13.5	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.2	13.15	0.9	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:1	21.81	950	1.49	13.48	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.12	13.15	0.9	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:2	21.81	944	1.49	13.48	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.16	13.13	0.89	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:2	21.81	939	1.49	13.48	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.1	13.12	0.89	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:2	21.81	939	1.48	13.51	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.17	13.1	0.89	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:2	21.81	936	1.48	13.48	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.09	13.08	0.89	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:2	21.81	936	1.48	13.53	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.15	13.08	0.89	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:2	21.81	934	1.48	13.5	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.12	13.07	0.89	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:3	21.81	933	1.48	13.49	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.15	13.05	0.89	4.9	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:47:3	21.81	920	1.47	13.48	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.07	13.04	0.89	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:3	21.81	906	1.47	13.48	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.09	13.03	0.89	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:3	21.81	906	1.47	13.45	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.02	13.02	0.89	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:3	21.81	906	1.47	13.46	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.02	13.01	0.89	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:3	21.81	890	1.47	13.44	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.98	13	0.89	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:4	21.81	890	1.47	13.45	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.01	13	0.89	4.7	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:4	21.81	894	1.46	13.45	114	196	Off Idle	85.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.97	13	0.89	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:4	21.81	899	1.46	13.48	114	196	Off Idle	85.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.95	12.99	0.88	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:4	21.81	894	1.46	13.43	114	196	Off Idle	85.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.94	12.99	0.88	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:4	21.81	894	1.46	13.48	114	196	Off Idle	85	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.9	12.99	0.89	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:4	21.81	883	1.45	13.45	114	196	Off Idle	85	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.91	13.01	0.89	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:4	21.81	872	1.45	13.44	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.89	13.03	0.89	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:5	21.81	867	1.45	13.42	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.89	13.04	0.89	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:5	21.81	867	1.45	13.42	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.81	13.08	0.89	5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:5	21.81	867	1.44	13.42	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.87	13.1	0.89	5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:5	21.81	856	1.44	13.44	114	196	Off Idle	84.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.8	13.13	0.89	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:5	21.81	856	1.44	13.45	114	196	Off Idle	84.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.82	13.17	0.9	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:5	21.81	849	1.44	13.44	114	196	Off Idle	84.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.78	13.22	0.9	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:6	21.81	849	1.43	13.47	114	196	Off Idle	84.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.78	13.26	0.9	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:6	21.81	834	1.43	13.44	114	196	Off Idle	84.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.77	13.29	0.9	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:6	21.81	834	1.43	13.45	114	196	Off Idle	84.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.73	13.32	0.91	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:6	21.81	834	1.42	13.45	114	196	Off Idle	84.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.76	13.33	0.91	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:6	21.81	830	1.42	13.46	114	196	Off Idle	84.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.7	13.34	0.91	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:6	21.81	830	1.42	13.45	114	196	Off Idle	84.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.69	13.36	0.91	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:6	21.81	826	1.41	13.46	114	196	Off Idle	84.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.64	13.37	0.91	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:7	21.81	826	1.41	13.46	114	196	Off Idle	84	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.62	13.38	0.91	5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:7	21.81	810	1.41	13.46	114	196	Off Idle	84	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.61	13.38	0.91	5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:7	21.81	810	1.41	13.46	114	196	Off Idle	83.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.58	13.37	0.91	5.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:7	21.81	812	1.4	13.29	114	196	Off Idle	83.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.58	13.37	0.91	5.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:7	21.81	815	1.4	13.14	114	196	Off Idle	83.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.57	13.36	0.91	5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:7	21.81	822	1.4	13.05	114	196	Off Idle	83.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.56	13.36	0.91	5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:47:8	21.81	822	1.39	13	114	196	Off Idle	83.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.57	13.36	0.91	5	4	ON	28 Pin	OFF	Removed	Disabled
03:07:47:8	21.81	822	1.39	12.97	114	196	Off Idle	83.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.56	13.35	0.91	4.9	4	ON	28 Pin	OFF	Removed	Disabled
03:07:47:8	20.45	835	1.39	13.17	114	196	Off Idle	83.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.55	13.33	0.91	4.8	4	ON	28 Pin	OFF	Removed	Disabled
03:07:47:8	20.45	835	1.39	13.29	114	196	Off Idle	83.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.58	13.31	0.91	4.8	4	ON	28 Pin	OFF	Removed	Disabled
03:07:47:8	20.45	854	1.38	13.34	114	196	Off Idle	83.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.58	13.28	0.9	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:8	20.45	872	1.38	13.38	114	196	Off Idle	83.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.6	13.25	0.9	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:9	19.09	885	1.38	13.43	114	196	Off Idle	83.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.64	13.19	0.9	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:9	19.09	885	1.38	13.48	114	196	Off Idle	83.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.67	13.15	0.9	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:47:9	19.09	904	1.38	13.45	114	196	Off Idle	83.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.71	13.1	0.89	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:47:9	19.09	922	1.38	13.48	114	196	Off Idle	83.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.77	13.04	0.89	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:07:47:9	19.09	959	1.38	13.45	114	196	Off Idle	84	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.8	12.96	0.88	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:07:47:9	19.09	959	1.38	13.46	114	196	Off Idle	84.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.89	12.9	0.88	4.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:07:47:9	19.09	976	1.38	13.41	114	196	Off Idle	84.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.94	12.84	0.87	4.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:0	19.09	994	1.38	13.44	114	196	Off Idle	84.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.93	12.78	0.87	4.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:0	19.09	1004	1.39	13.43	114	196	Off Idle	84.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.01	12.71	0.87	4.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:0	19.09	1004	1.39	13.43	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.05	12.67	0.86	4.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:0	19.09	1006	1.4	13.42	114	196	Off Idle	85.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.09	12.6	0.86	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:0	19.09	1009	1.4	13.44	114	196	Off Idle	85.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.12	12.56	0.86	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:0	19.09	1016	1.41	13.41	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.16	12.51	0.85	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:1	19.09	1018	1.41	13.44	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.28	12.47	0.85	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:1	19.09	1019	1.42	13.41	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.24	12.44	0.85	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:1	19.09	1019	1.42	13.45	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.34	12.41	0.85	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:1	19.09	1018	1.43	13.44	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.26	12.38	0.84	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:1	19.09	1027	1.43	13.42	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.35	12.33	0.84	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:1	19.09	1027	1.44	13.44	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.35	12.29	0.84	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:1	19.09	1034	1.44	13.43	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.39	12.25	0.83	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:2	19.09	1041	1.45	13.45	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.46	12.22	0.83	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:2	19.09	1055	1.45	13.41	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.47	12.18	0.83	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:2	19.09	1078	1.45	13.44	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.54	12.15	0.83	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:2	20.45	1078	1.46	13.43	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.57	12.13	0.83	4.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:2	20.45	1086	1.46	13.41	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.68	12.08	0.82	4.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:2	20.45	1094	1.46	13.43	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.64	12.06	0.82	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:07:48:3	20.45	1104	1.46	13.43	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.74	12.02	0.82	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:07:48:3	20.45	1114	1.46	13.43	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.8	12.01	0.82	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:07:48:3	20.45	1134	1.47	13.43	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.84	11.98	0.82	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:3	20.45	1133	1.47	13.43	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.93	11.96	0.81	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:3	20.45	1133	1.47	13.43	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.98	11.94	0.81	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:3	20.45	1148	1.47	13.41	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.09	11.93	0.81	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:4	20.45	1148	1.46	13.43	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.12	11.91	0.81	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:4	20.45	1157	1.46	13.43	114	196	Off Idle	86	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.25	11.91	0.81	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:4	20.45	1165	1.46	13.45	114	196	Off Idle	86	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.36	11.91	0.81	4.3	2.8	ON	28 Pin	OFF	Removed	Disabled
03:07:48:4	20.45	1173	1.45	13.45	114	196	Off Idle	86	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.39	11.93	0.81	4.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:07:48:4	21.81	1179	1.45	13.46	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.47	11.94	0.81	4.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:07:48:4	21.81	1179	1.44	13.46	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.5	11.95	0.81	4.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:07:48:4	21.81	1178	1.44	13.48	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.56	12	0.82	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:07:48:5	21.81	1189	1.44	13.47	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.64	12.01	0.82	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:07:48:5	21.81	1198	1.44	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.68	12.03	0.82	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:07:48:5	21.81	1198	1.43	13.47	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.82	12.08	0.82	4.3	2.7	ON	28 Pin	OFF	Removed	Disabled
03:07:48:5	21.81	1206	1.43	13.45	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.94	12.11	0.83	4.3	2.7	ON	28 Pin	OFF	Removed	Disabled
03:07:48:5	21.81	1213	1.42	13.47	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.97	12.15	0.83	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:07:48:5	21.81	1220	1.42	13.46	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.1	12.2	0.83	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:07:48:6	21.81	1220	1.41	13.45	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.19	12.24	0.83	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:07:48:6	21.81	1232	1.41	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.2	12.29	0.84	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:07:48:6	21.81	1238	1.41	13.47	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.28	12.32	0.84	4.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:48:6	23.18	1260	1.4	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.35	12.39	0.84	4.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:48:6	23.18	1260	1.4	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.41	12.43	0.85	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:48:6	23.18	1252	1.4	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.45	12.48	0.85	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:48:6	23.18	1264	1.4	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.51	12.51	0.85	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:48:7	23.18	1264	1.39	13.49	114	196	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.55	12.55	0.85	4.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:07:48:7	23.18	1268	1.39	13.47	114	196	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.61	12.57	0.86	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:7	23.18	1269	1.39	13.49	114	196	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.7	12.59	0.86	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:7	23.18	1270	1.39	13.48	114	196	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.79	12.62	0.86	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:7	23.18	1274	1.38	13.47	114	196	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.82	12.64	0.86	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:7	23.18	1274	1.38	13.47	114	196	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.89	12.66	0.86	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:8	23.18	1281	1.37	13.48	114	196	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6	12.67	0.86	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:48:8	23.18	1288	1.37	13.46	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.03	12.69	0.86	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:48:8	24.54	1299	1.37	13.46	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.12	12.71	0.87	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:8	24.54	1291	1.36	13.46	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.23	12.73	0.87	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:8	24.54	1291	1.36	13.47	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.26	12.75	0.87	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:8	25.9	1311	1.36	13.47	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.31	12.77	0.87	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:9	25.9	1299	1.36	13.46	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.33	12.78	0.87	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:48:9	25.9	1299	1.36	13.48	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.43	12.82	0.87	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:9	24.54	1309	1.35	13.48	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.46	12.85	0.88	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:9	24.54	1316	1.35	13.48	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.54	12.87	0.88	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:9	24.54	1323	1.35	13.48	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.59	12.9	0.88	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:9	24.54	1328	1.34	13.48	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.63	12.94	0.88	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:48:9	24.54	1339	1.34	13.46	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.73	13.01	0.89	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:0	24.54	1343	1.34	13.46	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.78	13.05	0.89	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:0	24.54	1340	1.33	13.47	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.81	13.11	0.89	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:0	24.54	1347	1.33	13.46	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.92	13.14	0.89	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:49:0	24.54	1353	1.33	13.47	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.01	13.2	0.9	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:49:0	24.54	1353	1.32	13.49	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.04	13.25	0.9	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:49:0	24.54	1355	1.32	13.48	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.11	13.3	0.91	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:49:1	24.54	1357	1.32	13.47	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.16	13.34	0.91	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:49:1	24.54	1357	1.32	13.48	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.21	13.39	0.91	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:49:1	24.54	1361	1.31	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.19	13.45	0.92	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:1	24.54	1367	1.31	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.25	13.49	0.92	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:1	24.54	1378	1.3	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.31	13.53	0.92	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:1	24.54	1378	1.3	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.37	13.59	0.93	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:1	25.9	1366	1.3	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.39	13.61	0.93	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:2	25.9	1369	1.29	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.45	13.63	0.93	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:2	25.9	1371	1.29	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.46	13.65	0.93	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:2	25.9	1371	1.29	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.48	13.68	0.93	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:2	25.9	1373	1.28	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.53	13.73	0.94	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:2	25.9	1376	1.28	13.49	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.59	13.75	0.94	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:2	25.9	1384	1.28	13.49	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.59	13.78	0.94	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:3	25.9	1384	1.27	13.49	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.62	13.81	0.94	4.2	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:3	25.9	1389	1.27	13.48	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.62	13.85	0.94	4.2	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:3	25.9	1394	1.27	13.49	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	13.87	0.94	4.2	2	ON	28 Pin	OFF	Removed	Disabled
03:07:49:3	25.9	1394	1.27	13.49	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	13.91	0.95	4.2	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:49:3	27.27	1419	1.27	13.48	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.71	13.94	0.95	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:49:3	27.27	1410	1.26	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.76	13.97	0.95	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:49:4	25.9	1398	1.26	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.01	0.95	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:49:4	25.9	1394	1.26	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.82	14.02	0.96	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:49:4	25.9	1420	1.25	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	14.08	0.96	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:49:4	25.9	1406	1.25	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	14.13	0.96	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:49:4	25.9	1400	1.25	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	14.18	0.97	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:4	25.9	1403	1.25	13.48	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.88	14.22	0.97	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:4	25.9	1403	1.24	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.89	14.27	0.97	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:5	25.9	1404	1.24	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.98	14.31	0.97	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:5	25.9	1401	1.24	13.49	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8	14.35	0.98	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:5	25.9	1401	1.23	13.48	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.03	14.39	0.98	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:5	25.9	1410	1.23	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.01	14.42	0.98	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:5	25.9	1391	1.22	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.04	14.44	0.98	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:5	25.9	1411	1.22	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.08	14.46	0.99	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:6	25.9	1411	1.21	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.06	14.47	0.99	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:6	27.27	1391	1.21	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.08	14.48	0.99	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:6	27.27	1400	1.2	13.45	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.09	14.5	0.99	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:6	27.27	1400	1.2	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.12	14.51	0.99	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:6	28.63	1389	1.19	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.1	14.51	0.99	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:6	28.63	1388	1.19	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.15	14.54	0.99	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:6	28.63	1383	1.19	13.44	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.17	14.54	0.99	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:7	28.63	1383	1.18	13.46	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.19	14.57	0.99	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:7	28.63	1375	1.18	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.2	14.59	0.99	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:49:7	28.63	1385	1.17	13.47	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.21	14.61	1	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:7	28.63	1385	1.16	13.46	114	196	Full Load	86.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.27	14.62	1	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:49:7	28.63	1392	1.15	13.48	114	196	Idle	86.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.33	14.64	1	4.3	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:49:7	28.63	1397	1.12	13.47	114	196	Idle	86.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.4	14.66	1	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:49:8	28.63	1388	1.1	13.46	114	196	Idle	86.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.52	14.69	1	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:8	28.63	1384	1.08	13.48	114	195	Idle	86.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.6	14.71	1	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:8	27.27	1384	1.07	13.47	114	195	Idle	87	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.72	14.74	1	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:8	27.27	1390	1.06	13.47	114	196	Idle	87	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.71	14.76	1.01	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:8	27.27	1390	1.05	13.46	114	196	Idle	87	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.74	14.77	1.01	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:8	27.27	1380	1.03	13.48	114	196	Idle	87	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.85	14.81	1.01	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:9	27.27	1375	1.01	13.47	114	196	Idle	87	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.9	14.83	1.01	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:9	25.9	1357	1	13.46	114	196	Idle	87	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.93	14.85	1.01	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:9	25.9	1352	0.98	13.47	114	196	Idle	87	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.03	14.86	1.01	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:9	25.9	1346	0.97	13.47	114	196	Idle	86.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.04	14.87	1.01	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:9	25.9	1322	0.96	13.47	114	196	Idle	86.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.03	14.89	1.01	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:9	25.9	1322	0.95	13.46	114	196	Idle	86.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.04	14.91	1.02	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:49:9	25.9	1314	0.94	13.47	114	196	Idle	86.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.02	14.91	1.02	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:50:0	27.27	1286	0.93	13.48	114	196	Idle	86.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9	14.92	1.02	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:50:0	27.27	1286	0.92	13.48	114	196	Idle	86.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9	14.9	1.01	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:07:50:0	27.27	1257	0.91	13.48	114	196	Idle	86.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.94	14.89	1.01	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:07:50:0	25.9	1232	0.92	13.49	114	196	Idle	85.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.98	14.87	1.01	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:07:50:0	25.9	1232	0.93	13.5	114	196	Idle	85.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.01	14.89	1.01	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:07:50:0	25.9	1221	0.94	13.48	114	196	Idle	85.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.94	14.89	1.01	4.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:07:50:1	25.9	1202	0.94	13.48	114	196	Idle	85.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.9	14.9	1.02	4.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:07:50:1	25.9	1204	0.93	13.49	114	196	Idle	84.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.9	14.92	1.02	4.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:1	25.9	1204	0.93	13.47	114	196	Idle	84.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.81	14.94	1.02	4.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:1	25.9	1189	0.93	13.47	114	196	Idle	84.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.81	14.97	1.02	4.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:1	25.9	1196	0.94	13.47	114	196	Idle	84.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.74	15.04	1.02	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:1	25.9	1203	0.95	13.47	114	196	Idle	84.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.71	15.09	1.03	4.3	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:1	25.9	1203	0.95	13.48	114	196	Idle	84.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.7	15.13	1.03	4.3	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:2	25.9	1196	0.95	13.48	114	196	Idle	84.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.65	15.18	1.03	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:2	25.9	1190	0.96	13.48	114	196	Idle	84.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.63	15.21	1.04	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:2	25.9	1148	0.96	13.49	114	196	Idle	84.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.63	15.25	1.04	4.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:2	24.54	1148	0.96	13.47	114	196	Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.61	15.29	1.04	4.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:2	24.54	1147	0.96	13.45	114	196	Idle	85.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.61	15.34	1.04	4.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:2	24.54	1143	0.96	13.45	114	196	Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.6	15.38	1.05	4.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:3	24.54	1143	0.96	13.42	114	196	Idle	86.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.59	15.43	1.05	4.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:3	24.54	1144	0.96	13.4	114	196	Idle	86.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.59	15.5	1.06	4.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:3	24.54	1148	0.96	13.41	114	196	Idle	87.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.57	15.57	1.06	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:3	24.54	1140	0.96	13.41	114	196	Idle	87.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.58	15.62	1.06	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:3	24.54	1140	0.96	13.42	114	196	Idle	87.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.51	15.67	1.07	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:3	24.54	1122	0.96	13.41	114	196	Idle	88.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.46	15.74	1.07	4.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:4	24.54	1106	0.95	13.42	114	196	Idle	88.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.49	15.82	1.08	4.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:4	24.54	1106	0.95	13.42	114	196	Idle	89	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.48	15.88	1.08	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:4	24.54	1110	0.95	13.41	114	196	Idle	89.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.46	15.94	1.09	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:4	24.54	1114	0.94	13.43	114	196	Idle	89.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.46	16.01	1.09	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:4	23.18	1102	0.94	13.42	114	196	Idle	89.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.47	16.08	1.1	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:4	23.18	1085	0.94	13.45	114	196	Idle	89.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.45	16.14	1.1	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:4	23.18	1085	0.93	13.43	114	196	Idle	90.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.41	16.2	1.1	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:5	23.18	1076	0.93	13.43	114	196	Idle	90.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.41	16.24	1.11	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:5	23.18	1068	0.92	13.44	114	196	Idle	91.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.37	16.32	1.11	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:5	23.18	1079	0.92	13.42	114	196	Idle	91.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.37	16.38	1.12	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:5	23.18	1079	0.91	13.44	114	196	Idle	91.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.32	16.43	1.12	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:5	23.18	1075	0.91	13.42	114	196	Idle	92	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.33	16.48	1.12	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:5	23.18	1061	0.91	13.43	114	196	Idle	92.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.31	16.54	1.13	4.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:50:6	23.18	1061	0.9	13.42	114	196	Idle	92.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.29	16.59	1.13	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:6	23.18	1046	0.9	13.43	114	196	Idle	92.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.27	16.64	1.13	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:6	23.18	1046	0.89	13.42	114	196	Idle	92.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.27	16.73	1.14	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:50:6	23.18	1046	0.89	13.42	114	196	Idle	92.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.33	16.78	1.14	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:6	23.18	1045	0.89	13.42	114	196	Idle	92.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.32	16.9	1.15	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:6	21.81	1019	0.88	13.41	114	196	Idle	92.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.35	16.94	1.15	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:6	21.81	1019	0.88	13.41	114	196	Idle	93	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.31	17.08	1.16	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:7	21.81	1007	0.87	13.41	114	196	Idle	93	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.31	17.2	1.17	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:7	21.81	1007	0.87	13.43	114	196	Idle	92.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.29	17.32	1.18	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:7	21.81	993	0.87	13.43	114	196	Idle	92.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.29	17.45	1.19	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:7	21.81	993	0.86	13.44	114	196	Idle	92.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.24	17.65	1.2	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:7	21.81	994	0.86	13.43	114	196	Idle	92.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.21	17.8	1.21	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:7	21.81	990	0.86	13.44	114	196	Idle	92.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.19	17.98	1.22	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:8	21.81	985	0.85	13.43	114	196	Idle	92.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.17	18.16	1.24	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:8	21.81	985	0.85	13.45	114	196	Idle	92.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.17	18.4	1.25	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:8	21.81	980	0.85	13.43	114	196	Idle	92.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.1	18.58	1.27	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:8	21.81	974	0.85	13.44	114	196	Idle	92.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.12	18.71	1.27	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:8	21.81	969	0.85	13.43	114	196	Idle	92.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.06	18.88	1.29	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:8	21.81	969	0.85	13.45	114	196	Idle	92.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.08	19	1.29	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:9	21.81	962	0.85	13.43	114	196	Idle	92.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.02	19.14	1.3	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:9	21.81	934	0.84	13.45	114	196	Idle	92.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.05	19.2	1.31	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:9	20.45	934	0.84	13.45	114	196	Idle	92.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8	19.32	1.32	4.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:9	20.45	934	0.84	13.46	114	196	Idle	92.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.03	19.36	1.32	4.9	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:50:9	20.45	925	0.84	13.44	114	196	Idle	92.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.99	19.39	1.32	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:50:9	20.45	926	0.84	13.44	114	196	Idle	92.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8	19.41	1.32	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:50:9	20.45	926	0.84	13.44	114	196	Idle	92.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.95	19.4	1.32	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:0	20.45	927	0.84	13.43	114	196	Idle	93	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.96	19.36	1.32	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:0	20.45	927	0.84	13.43	114	196	Idle	93.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.89	19.32	1.32	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:0	20.45	928	0.84	13.44	114	196	Idle	93.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.92	19.25	1.31	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:0	20.45	910	0.84	13.43	114	196	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.89	19.16	1.3	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:0	20.45	910	0.84	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.91	19.06	1.3	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:0	20.45	908	0.84	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.89	18.9	1.29	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:1	20.45	907	0.84	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.9	18.78	1.28	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:1	20.45	913	0.84	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.87	18.66	1.27	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:1	20.45	913	0.84	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.85	18.52	1.26	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:1	20.45	915	0.84	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.81	18.32	1.25	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:1	20.45	915	0.84	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.82	18.19	1.24	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:1	19.09	918	0.84	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.83	18.09	1.23	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:1	19.09	918	0.84	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.84	17.93	1.22	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:2	19.09	915	0.84	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	17.85	1.22	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:2	19.09	912	0.83	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	17.81	1.21	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:2	19.09	924	0.83	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.81	17.69	1.21	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:2	19.09	924	0.83	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	17.63	1.2	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:2	19.09	928	0.83	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	17.56	1.2	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:2	19.09	933	0.83	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	17.51	1.19	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:3	17.72	926	0.83	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	17.46	1.19	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:3	17.72	926	0.83	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	17.43	1.19	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:3	17.72	911	0.83	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.82	17.37	1.18	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:3	17.72	911	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	17.35	1.18	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:3	17.72	908	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.81	17.31	1.18	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:3	17.72	905	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	17.29	1.18	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:4	17.72	919	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	17.26	1.18	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:4	17.72	919	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	17.26	1.18	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:4	16.36	914	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	17.23	1.17	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:4	16.36	909	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	17.23	1.17	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:4	16.36	913	0.82	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	17.22	1.17	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:4	16.36	913	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	17.21	1.17	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:4	16.36	916	0.82	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.76	17.21	1.17	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:5	16.36	918	0.82	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	17.21	1.17	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:5	16.36	918	0.82	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.76	17.23	1.17	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:5	16.36	914	0.82	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	17.24	1.17	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:51:5	16.36	914	0.82	13.44	114	196	Idle	93.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	17.26	1.18	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:5	16.36	905	0.82	13.44	114	196	Idle	93.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	17.17	1.17	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:5	16.36	905	0.82	13.44	114	196	Idle	93.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	17.17	1.17	5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:51:6	16.36	890	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	17.18	1.17	5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:6	16.36	890	0.82	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	17.2	1.17	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:6	16.36	892	0.82	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	17.22	1.17	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:6	16.36	892	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	17.25	1.17	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:6	16.36	894	0.82	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	17.26	1.18	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:6	16.36	896	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	17.27	1.18	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:6	16.36	870	0.82	13.44	114	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	17.28	1.18	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:7	16.36	870	0.82	13.45	114	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	17.41	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:7	16.36	869	0.82	13.43	114	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	17.42	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:7	16.36	868	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	17.43	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:7	16.36	868	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	17.44	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:7	16.36	861	0.82	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.57	17.45	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:7	16.36	861	0.82	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.55	17.45	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:8	16.36	863	0.82	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	17.46	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:8	16.36	863	0.82	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	17.46	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:8	16.36	861	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	17.46	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:8	16.36	861	0.82	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	17.45	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:8	16.36	860	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	17.43	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:8	16.36	860	0.81	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	17.42	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:9	16.36	860	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.56	17.41	1.19	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:9	16.36	861	0.81	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.53	17.39	1.18	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:9	16.36	861	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.52	17.36	1.18	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:9	16.36	862	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.48	17.34	1.18	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:9	16.36	862	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.5	17.31	1.18	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:9	13.63	850	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.49	17.28	1.18	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:51:9	13.63	850	0.81	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.47	17.24	1.17	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:0	13.63	854	0.81	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.43	17.22	1.17	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:0	13.63	858	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.43	17.18	1.17	5.1	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:0	13.63	828	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.44	17.14	1.17	5.1	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:0	13.63	828	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.42	17.09	1.16	5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:0	13.63	832	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.44	17.06	1.16	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:0	13.63	835	0.81	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.45	17.04	1.16	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:1	13.63	835	0.81	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.43	17.01	1.16	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:1	14.99	809	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.4	16.97	1.16	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:1	14.99	809	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.39	16.94	1.15	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:1	14.99	809	0.8	13.45	114	196	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.37	16.91	1.15	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:1	14.99	804	0.8	13.43	114	196	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.33	16.9	1.15	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:1	14.99	804	0.8	13.44	114	196	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.31	16.88	1.15	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:1	14.99	805	0.8	13.42	114	196	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.32	16.89	1.15	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:2	14.99	806	0.8	13.42	114	196	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.88	1.15	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:2	14.99	825	0.8	13.42	114	196	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.87	1.15	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:2	14.99	825	0.8	13.4	114	196	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.26	16.86	1.15	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:2	17.72	818	0.8	13.41	114	196	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.26	16.87	1.15	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:2	17.72	812	0.8	13.42	114	196	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.26	16.88	1.15	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:2	17.72	823	0.8	13.44	114	196	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.88	1.15	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:3	17.72	823	0.8	13.43	114	196	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.25	16.87	1.15	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:3	17.72	823	0.8	13.45	114	196	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.25	16.87	1.15	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:3	17.72	825	0.8	13.43	114	196	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.22	16.86	1.15	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:3	17.72	825	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.18	16.87	1.15	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:3	17.72	836	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.21	16.86	1.15	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:52:3	17.72	846	0.8	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.19	16.87	1.15	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:4	17.72	849	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.19	16.85	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:4	17.72	849	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.2	16.86	1.15	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:4	17.72	842	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.22	16.85	1.15	5.1	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:4	17.72	836	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.23	16.85	1.15	5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:52:4	17.72	861	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.26	16.86	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:4	14.99	861	0.8	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.85	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:4	14.99	861	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.29	16.84	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:5	14.99	879	0.79	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.29	16.84	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:5	14.99	879	0.79	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.3	16.83	1.15	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:5	14.99	874	0.79	13.42	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.82	1.15	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:5	14.99	868	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.81	1.14	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:5	14.99	862	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.8	1.14	5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:5	14.99	862	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.8	1.14	5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:6	14.99	864	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.3	16.79	1.14	5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:6	14.99	865	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.31	16.8	1.14	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:6	14.99	872	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.33	16.79	1.14	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:6	14.99	872	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.33	16.79	1.14	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:6	14.99	872	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.32	16.78	1.14	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:6	16.36	869	0.79	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.31	16.8	1.14	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:6	16.36	869	0.79	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.31	16.8	1.14	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:7	16.36	862	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.8	1.14	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:7	16.36	856	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.29	16.8	1.14	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:7	14.99	866	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.29	16.79	1.14	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:7	14.99	866	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.79	1.14	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:7	14.99	872	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.29	16.78	1.14	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:7	14.99	877	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.81	1.15	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:8	14.99	880	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.3	16.81	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:8	14.99	880	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.82	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:8	14.99	872	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.3	16.8	1.14	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:8	14.99	865	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.81	1.15	5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:8	14.99	865	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.29	16.82	1.15	5	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:8	14.99	859	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.84	1.15	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:9	14.99	859	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.3	16.84	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:9	14.99	870	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.84	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:9	14.99	870	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.29	16.82	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:9	14.99	866	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.32	16.83	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:9	14.99	863	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.31	16.85	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:9	14.99	863	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.32	16.85	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:52:9	14.99	846	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.31	16.86	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:0	14.99	846	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.32	16.85	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:0	13.63	858	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.29	16.85	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:0	13.63	858	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.32	16.83	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:0	13.63	858	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.31	16.85	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:0	13.63	857	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.86	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:0	13.63	840	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.85	1.15	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:1	13.63	840	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.83	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:1	13.63	842	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	16.82	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:1	13.63	844	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	16.82	1.15	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:1	13.63	844	0.8	13.44	114	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.26	16.8	1.14	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:1	13.63	833	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.24	16.78	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:1	13.63	833	0.8	13.43	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.22	16.77	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:1	13.63	843	0.8	13.41	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.2	16.75	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:2	13.63	843	0.8	13.45	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.19	16.73	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:2	14.99	844	0.8	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.19	16.73	1.14	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:2	14.99	846	0.8	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.16	16.72	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:2	14.99	841	0.8	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.19	16.7	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:2	14.99	841	0.8	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.18	16.69	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:2	12.27	846	0.8	13.46	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.2	16.7	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:3	12.27	852	0.79	13.48	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.19	16.69	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:3	12.27	862	0.79	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.22	16.7	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:3	12.27	862	0.79	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.17	16.69	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:3	12.27	862	0.79	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.17	16.7	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:53:3	12.27	858	0.79	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.16	16.7	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:3	12.27	858	0.79	13.48	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.15	16.72	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:4	12.27	866	0.79	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.16	16.73	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:4	12.27	873	0.79	13.49	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.17	16.77	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:4	12.27	873	0.79	13.47	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.16	16.79	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:4	12.27	870	0.79	13.49	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.19	16.81	1.15	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:4	12.27	872	0.79	13.48	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.22	16.83	1.15	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:4	12.27	875	0.79	13.49	114	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.19	16.86	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:4	12.27	875	0.79	13.48	114	196	Full Load	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.23	16.86	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:5	12.27	863	0.79	13.5	114	196	Off Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.24	16.89	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:5	12.27	863	0.79	13.5	114	196	Off Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.24	16.9	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:5	12.27	847	0.81	13.48	114	196	Off Idle	92.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.11	16.93	1.15	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:5	12.27	847	0.84	13.48	114	196	Off Idle	92	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.07	16.94	1.15	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:5	10.9	855	0.87	13.48	114	196	Off Idle	91.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.9	16.96	1.15	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:5	10.9	855	0.93	13.47	114	196	Off Idle	90.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.5	16.98	1.16	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:6	10.9	848	0.96	13.46	114	196	Off Idle	90.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.24	16.98	1.16	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:6	10.9	848	1.02	13.5	114	196	Off Idle	89.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.93	17	1.16	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:53:6	10.9	848	1.07	13.51	114	196	Off Idle	88.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.52	17.02	1.16	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:53:6	10.9	805	1.14	13.49	114	196	Off Idle	87.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.1	17.03	1.16	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:53:6	10.9	805	1.18	13.49	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.76	17.04	1.16	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:53:6	10.9	799	1.25	13.47	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.33	17.02	1.16	5.1	5.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:6	10.9	799	1.29	13.48	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.14	17.04	1.16	5.2	5.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:7	21.81	820	1.34	13.5	114	196	Off Idle	84.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.7	17.04	1.16	5.3	5.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:7	21.81	840	1.39	13.52	114	196	Off Idle	84.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.56	17.04	1.16	5.1	5.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:7	21.81	843	1.43	13.54	114	196	Off Idle	83.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.18	17.04	1.16	4.8	5.2	ON	28 Pin	OFF	Removed	Disabled
03:07:53:7	21.81	843	1.47	13.53	114	196	Off Idle	83.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.97	17.05	1.16	4.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:07:53:7	21.81	874	1.52	13.57	114	196	Off Idle	83.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.84	17.05	1.16	4.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:07:53:7	19.09	905	1.56	13.54	114	196	Off Idle	83.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.64	17.04	1.16	4.2	5.6	ON	28 Pin	OFF	Removed	Disabled
03:07:53:8	19.09	905	1.61	13.56	114	196	Off Idle	83.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.6	17.05	1.16	4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:07:53:8	19.09	1018	1.64	13.57	114	196	Off Idle	83.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.48	17.06	1.16	4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:07:53:8	19.09	1091	1.65	13.57	114	196	Off Idle	83.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.54	17.06	1.16	4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:07:53:8	19.09	1091	1.66	13.57	114	196	Off Idle	83.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.51	17.06	1.16	3.9	4.8	ON	28 Pin	OFF	Removed	Disabled
03:07:53:8	19.09	1165	1.67	13.53	114	196	Off Idle	84	0	2	132	944 Turbo	0.07	Lean	1	14.6	-2.59	17.07	1.16	4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:8	20.45	1165	1.67	13.54	114	196	Off Idle	84.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-2.68	17.09	1.16	4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:9	20.45	1188	1.66	13.53	114	196	Off Idle	84.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-2.72	17.08	1.16	4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:53:9	20.45	1262	1.66	13.53	114	196	Off Idle	84.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-2.8	17.07	1.16	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:53:9	21.81	1262	1.67	13.52	114	196	Off Idle	84.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-2.9	17.08	1.16	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:53:9	21.81	1277	1.67	13.53	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3	17.08	1.16	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:07:53:9	21.81	1342	1.67	13.52	114	196	Off Idle	85.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.1	17.09	1.16	4.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:07:53:9	21.81	1352	1.67	13.53	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.21	17.1	1.16	4.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:07:53:9	21.81	1363	1.67	13.53	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-3.36	17.15	1.17	4.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:07:54:0	21.81	1440	1.68	13.54	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.49	17.21	1.17	4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:07:54:0	21.81	1472	1.67	13.54	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.64	17.26	1.18	4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:07:54:0	21.81	1484	1.66	13.53	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.93	17.32	1.18	4.1	3	ON	28 Pin	OFF	Removed	Disabled
03:07:54:0	23.18	1514	1.62	13.54	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.45	17.33	1.18	4.1	3	ON	28 Pin	OFF	Removed	Disabled
03:07:54:0	23.18	1542	1.56	13.53	114	196	Full Load	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.8	17.28	1.18	4.1	3	ON	28 Pin	OFF	Removed	Disabled
03:07:54:0	23.18	1553	1.46	13.52	114	196	Idle	86.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.45	17.16	1.17	4.1	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:1	23.18	1579	1.41	13.5	114	196	Idle	86.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.81	17.01	1.16	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:1	23.18	1589	1.37	13.5	114	196	Idle	86.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-6.19	16.75	1.14	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:07:54:1	21.81	1601	1.34	13.49	114	196	Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.38	16.41	1.12	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:07:54:1	21.81	1626	1.32	13.5	114	196	Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.96	16	1.09	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:1	21.81	1632	1.29	13.51	114	196	Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.27	15.51	1.06	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:1	21.81	1632	1.25	13.5	114	196	Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.58	15.01	1.02	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:1	21.81	1602	1.16	13.5	114	196	Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.95	14.25	0.97	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:54:2	21.81	1592	1.11	13.49	114	196	Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.12	13.77	0.94	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:54:2	21.81	1580	1.07	13.48	114	196	Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.31	13.35	0.91	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:07:54:2	21.81	1557	1.02	13.48	114	196	Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.45	12.8	0.87	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:07:54:2	21.81	1557	1.01	13.48	114	196	Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.54	12.52	0.85	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:54:2	21.81	1527	0.95	13.47	114	196	Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.62	12.23	0.83	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:07:54:2	20.45	1491	0.92	13.47	114	196	Idle	86.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.62	12.16	0.83	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:07:54:3	20.45	1484	0.85	13.46	114	196	Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.71	12.02	0.82	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:54:3	20.45	1449	0.82	13.48	114	196	Idle	84.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.81	11.97	0.82	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:54:3	20.45	1423	0.82	13.48	114	196	Idle	84.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.84	11.94	0.81	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:54:3	20.45	1423	0.85	13.48	114	196	Idle	83.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.89	11.94	0.81	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:54:3	20.45	1395	0.89	13.48	114	196	Idle	82.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.85	11.94	0.81	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:07:54:3	20.45	1388	0.93	13.49	114	196	Idle	81.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.86	11.95	0.81	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:4	20.45	1381	0.95	13.47	114	196	Idle	79.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.8	11.95	0.81	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:4	21.81	1330	0.94	13.48	114	196	Idle	78.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.73	11.94	0.81	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:4	21.81	1330	0.93	13.48	114	196	Idle	78	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.7	11.94	0.81	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:4	20.45	1330	0.93	13.47	114	196	Idle	77	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.68	11.96	0.81	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:4	20.45	1324	0.97	13.47	114	196	Idle	76.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.61	12	0.82	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:4	20.45	1327	1.01	13.47	114	196	Idle	75.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.58	12.05	0.82	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:4	20.45	1327	1.03	13.46	114	196	Idle	74.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.54	12.09	0.82	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:5	20.45	1321	1.03	13.46	114	196	Idle	74.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.53	12.14	0.83	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:5	20.45	1324	1.03	13.47	114	196	Idle	75	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.49	12.18	0.83	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:5	20.45	1325	1.03	13.47	114	196	Idle	75.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.52	12.29	0.84	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:5	20.45	1325	1.05	13.49	114	196	Idle	76.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.52	12.38	0.84	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:5	20.45	1321	1.07	13.49	114	196	Idle	77.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.51	12.47	0.85	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:5	20.45	1321	1.08	13.49	114	196	Idle	78.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.52	12.57	0.86	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:6	20.45	1319	1.08	13.49	114	196	Idle	79.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.55	12.7	0.87	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:6	20.45	1323	1.08	13.47	114	196	Idle	80.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.53	12.8	0.87	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:6	19.09	1316	1.07	13.47	114	196	Idle	82.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.58	12.88	0.88	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:07:54:6	19.09	1327	1.07	13.47	114	196	Idle	83.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.64	12.99	0.89	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:6	19.09	1327	1.06	13.47	114	196	Idle	84.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.68	13.08	0.89	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:6	19.09	1324	1.06	13.46	114	196	Idle	85.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.73	13.16	0.9	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:6	19.09	1322	1.06	13.44	114	196	Idle	86.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.76	13.31	0.91	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:7	19.09	1309	1.05	13.46	114	196	Idle	87	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.77	13.43	0.91	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:7	19.09	1309	1.04	13.45	114	196	Idle	87.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.8	13.57	0.92	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:7	19.09	1306	1.02	13.45	114	196	Idle	88.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.83	13.73	0.94	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:7	19.09	1302	1.01	13.47	114	196	Idle	89.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.85	13.88	0.95	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:7	17.72	1304	1	13.49	114	196	Idle	89.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.88	14.25	0.97	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:54:7	17.72	1306	0.99	13.47	114	196	Idle	89.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.92	14.58	0.99	4.3	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:8	17.72	1306	0.98	13.48	114	196	Idle	90.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.94	14.97	1.02	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:8	17.72	1290	0.97	13.47	114	196	Idle	90.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.96	15.63	1.06	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:8	17.72	1274	0.96	13.46	114	196	Idle	90.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.94	16.13	1.1	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:8	17.72	1262	0.96	13.47	114	196	Idle	91	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.98	16.65	1.13	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:8	17.72	1262	0.94	13.46	114	196	Idle	91.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.99	17.47	1.19	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:8	17.72	1256	0.94	13.46	114	196	Idle	91.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.97	18.02	1.23	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:9	17.72	1244	0.93	13.46	114	196	Idle	91.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.97	18.54	1.26	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:9	17.72	1238	0.93	13.48	114	196	Idle	91.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.97	18.78	1.28	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:9	17.72	1238	0.92	13.48	114	196	Full Load	92	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.99	19.17	1.31	4.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:9	17.72	1211	0.92	13.48	114	196	Off Idle	92.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.94	19.64	1.34	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:9	17.72	1202	0.92	13.48	114	196	Off Idle	92.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.92	19.87	1.35	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:9	17.72	1202	0.92	13.47	114	196	Off Idle	92.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.91	20.04	1.36	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:07:54:9	17.72	1189	0.93	13.46	114	196	Off Idle	92.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.85	20.19	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:55:0	19.09	1182	0.93	13.46	114	196	Off Idle	91.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.83	20.24	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:55:0	19.09	1169	0.94	13.48	114	196	Off Idle	91.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.73	20.25	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:07:55:0	19.09	1156	0.94	13.47	114	196	Off Idle	90.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.67	20.25	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:55:0	19.09	1139	0.95	13.49	114	196	Off Idle	90.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.57	20.25	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:07:55:0	19.09	1139	0.96	13.48	114	196	Off Idle	89.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.46	20.25	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:07:55:0	19.09	1138	0.98	13.46	114	196	Off Idle	89.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.4	20.24	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:55:1	19.09	1138	0.99	13.46	114	196	Off Idle	89.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.35	20.24	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:55:1	19.09	1128	1.01	13.48	114	196	Off Idle	88.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.22	20.24	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:55:1	19.09	1128	1.01	13.47	114	196	Off Idle	88.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.15	20.24	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:07:55:1	19.09	1124	1.02	13.48	114	196	Off Idle	88.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.03	20.24	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:55:1	19.09	1123	1.04	13.49	114	196	Off Idle	87.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.92	20.19	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:55:1	19.09	1123	1.06	13.49	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.84	20.13	1.37	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:07:55:1	19.09	1119	1.07	13.47	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.73	20.01	1.36	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:55:2	19.09	1118	1.09	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.73	19.84	1.35	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:55:2	20.45	1118	1.1	13.46	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.64	19.65	1.34	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:07:55:2	20.45	1111	1.12	13.46	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.6	19.41	1.32	4.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:2	20.45	1111	1.13	13.47	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.48	19.17	1.31	4.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:2	20.45	1107	1.15	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.33	18.72	1.28	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:2	20.45	1103	1.17	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.27	18.4	1.25	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:3	20.45	1108	1.19	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.14	18.07	1.23	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:07:55:3	20.45	1102	1.22	13.5	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.99	17.58	1.2	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:07:55:3	20.45	1102	1.24	13.5	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.82	17.3	1.18	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:07:55:3	20.45	1099	1.26	13.5	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.75	16.9	1.15	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:3	20.45	1098	1.29	13.49	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.62	16.66	1.13	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:3	20.45	1097	1.3	13.5	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.47	16.42	1.12	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:4	20.45	1097	1.33	13.48	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.26	16.22	1.1	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:4	20.45	1090	1.35	13.48	114	196	Off Idle	86	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.05	15.94	1.09	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:55:4	21.81	1087	1.37	13.47	114	196	Off Idle	86	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.91	15.79	1.08	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:55:4	21.81	1087	1.4	13.48	114	196	Off Idle	86	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.68	15.64	1.07	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:07:55:4	21.81	1080	1.42	13.46	114	196	Off Idle	86	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.53	15.52	1.06	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:4	21.81	1074	1.44	13.48	114	196	Off Idle	86	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.28	15.36	1.05	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:4	21.81	1073	1.47	13.47	114	196	Off Idle	86	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.07	15.29	1.04	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:5	21.81	1065	1.52	13.46	114	196	Off Idle	86	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.73	15.23	1.04	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:5	21.81	1065	1.55	13.46	114	196	Off Idle	86	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.43	15.19	1.03	4.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:5	21.81	1064	1.6	13.46	114	196	Off Idle	86	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.26	15.13	1.03	4.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:5	21.81	1062	1.62	13.46	114	196	Off Idle	86	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.14	15.1	1.03	4.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:5	21.81	1081	1.65	13.46	114	196	Off Idle	86	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.83	15.08	1.03	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:5	21.81	1081	1.68	13.48	114	196	Off Idle	86	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.43	15.07	1.03	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:6	24.54	1094	1.69	13.49	114	196	Off Idle	86	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.18	15.06	1.03	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:6	24.54	1089	1.71	13.5	114	196	Off Idle	86	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.05	15.06	1.03	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:07:55:6	24.54	1089	1.74	13.49	114	196	Off Idle	86	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.84	15.07	1.03	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:55:6	21.81	1090	1.75	13.47	114	196	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.85	15.07	1.03	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:55:6	21.81	1132	1.77	13.49	114	196	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.81	15.06	1.03	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:55:6	21.81	1132	1.78	13.47	114	196	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.74	15.07	1.03	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:55:6	21.81	1136	1.79	13.49	114	196	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.72	15.08	1.03	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:55:7	21.81	1141	1.8	13.48	114	196	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.66	15.1	1.03	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:55:7	21.81	1155	1.8	13.47	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.64	15.09	1.03	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:7	21.81	1169	1.8	13.49	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.62	15.05	1.03	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:7	21.81	1169	1.8	13.48	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.64	15.04	1.02	4.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:7	21.81	1168	1.8	13.48	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.63	14.96	1.02	4.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:55:7	21.81	1172	1.79	13.5	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.61	14.87	1.01	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:07:55:8	21.81	1176	1.79	13.49	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.58	14.78	1.01	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:07:55:8	21.81	1176	1.78	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.58	14.68	1	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:07:55:8	21.81	1181	1.78	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.51	14.57	0.99	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:55:8	21.81	1178	1.78	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.53	14.42	0.98	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:55:8	21.81	1178	1.77	13.47	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.53	14.23	0.97	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:55:8	21.81	1181	1.77	13.46	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.53	14.06	0.96	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:55:9	21.81	1188	1.77	13.47	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.55	13.95	0.95	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:55:9	23.18	1194	1.77	13.47	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.57	13.85	0.94	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:55:9	23.18	1176	1.76	13.46	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.56	13.8	0.94	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:55:9	23.18	1158	1.76	13.46	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.57	13.68	0.93	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:55:9	21.81	1146	1.76	13.46	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.48	13.6	0.93	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:55:9	21.81	1154	1.76	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.52	13.51	0.92	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:07:55:9	21.81	1154	1.76	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.48	13.42	0.91	4.5	4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:0	23.18	1137	1.76	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.48	13.3	0.91	4.5	4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:0	23.18	1130	1.76	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.49	13.2	0.9	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:0	23.18	1123	1.76	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.48	13.06	0.89	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:0	24.54	1113	1.76	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.51	12.99	0.89	4.7	4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:0	24.54	1113	1.76	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.41	12.91	0.88	4.7	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:56:0	24.54	1096	1.76	13.47	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.46	12.85	0.88	4.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:56:1	24.54	1096	1.76	13.47	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.37	12.78	0.87	4.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:56:1	23.18	1071	1.76	13.46	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.34	12.71	0.87	4.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:56:1	23.18	1071	1.76	13.46	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.33	12.68	0.86	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:56:1	23.18	1075	1.76	13.44	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.26	12.66	0.86	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:56:1	23.18	1075	1.75	13.46	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.21	12.65	0.86	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:56:1	23.18	1054	1.75	13.47	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.1	12.66	0.86	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:56:1	23.18	1054	1.75	13.47	114	196	Off Idle	86	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.1	12.65	0.86	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:2	23.18	1054	1.75	13.49	114	196	Off Idle	86	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.06	12.67	0.86	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:2	23.18	1054	1.75	13.48	114	196	Off Idle	86	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.04	12.7	0.87	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:2	23.18	1054	1.74	13.5	114	196	Off Idle	86	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.05	12.74	0.87	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:2	23.18	1043	1.74	13.49	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.99	12.76	0.87	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:2	23.18	1030	1.74	13.48	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.01	12.79	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:2	21.81	1030	1.74	13.48	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.96	12.83	0.87	4.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:3	21.81	1022	1.74	13.48	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.97	12.87	0.88	4.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:3	21.81	1013	1.73	13.48	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.92	12.9	0.88	4.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:3	21.81	1013	1.73	13.48	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.96	12.98	0.88	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:3	21.81	1015	1.72	13.47	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.87	13.02	0.89	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:3	21.81	997	1.72	13.48	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.94	13.09	0.89	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:3	21.81	997	1.72	13.51	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.85	13.14	0.9	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:4	21.81	993	1.71	13.5	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.9	13.19	0.9	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:4	21.81	989	1.71	13.51	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.83	13.24	0.9	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:4	21.81	984	1.71	13.48	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.82	13.29	0.91	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:4	21.81	984	1.71	13.52	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.79	13.32	0.91	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:4	23.18	988	1.71	13.49	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.75	13.35	0.91	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:4	23.18	991	1.71	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.69	13.37	0.91	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:4	23.18	984	1.71	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.64	13.38	0.91	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:5	23.18	984	1.71	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.56	13.39	0.91	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:5	20.45	968	1.71	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.52	13.37	0.91	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:5	20.45	968	1.71	13.51	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.47	13.37	0.91	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:5	20.45	981	1.71	13.49	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.46	13.37	0.91	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:56:5	20.45	994	1.71	13.51	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.42	13.36	0.91	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:56:5	21.81	986	1.71	13.48	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.41	13.36	0.91	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:56:6	21.81	977	1.71	13.51	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.44	13.36	0.91	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:56:6	21.81	977	1.71	13.48	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.39	13.34	0.91	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:56:6	21.81	984	1.71	13.51	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.4	13.31	0.91	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:56:6	21.81	991	1.71	13.48	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.36	13.3	0.91	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:56:6	21.81	991	1.71	13.52	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.4	13.27	0.9	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:56:6	21.81	993	1.71	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.31	13.25	0.9	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:56:6	20.45	989	1.71	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.35	13.22	0.9	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:56:7	20.45	989	1.71	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.32	13.18	0.9	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:56:7	20.45	992	1.71	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.35	13.15	0.9	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:7	20.45	995	1.71	13.47	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.28	13.11	0.89	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:7	21.81	1001	1.72	13.48	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.32	13.08	0.89	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:7	21.81	1001	1.72	13.51	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.23	13.06	0.89	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:7	21.81	987	1.72	13.48	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.19	13.01	0.89	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:56:8	21.81	987	1.72	13.52	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.14	13	0.89	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:8	20.45	993	1.72	13.5	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.1	12.97	0.88	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:8	20.45	993	1.72	13.53	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.08	12.95	0.88	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:8	20.45	992	1.72	13.49	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.06	12.93	0.88	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:56:8	20.45	988	1.73	13.52	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.06	12.9	0.88	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:56:8	20.45	985	1.73	13.48	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1	12.88	0.88	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:56:9	20.45	985	1.73	13.51	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.05	12.87	0.88	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:56:9	20.45	988	1.73	13.48	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1	12.86	0.88	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:9	20.45	981	1.74	13.51	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.04	12.86	0.88	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:9	19.09	981	1.74	13.49	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.97	12.85	0.88	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:9	19.09	981	1.74	13.51	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.04	12.85	0.88	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:56:9	19.09	980	1.74	13.48	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.95	12.85	0.88	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:56:9	20.45	953	1.74	13.48	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.99	12.84	0.87	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:0	20.45	953	1.75	13.49	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.93	12.83	0.87	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:0	20.45	953	1.74	13.49	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.01	12.83	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:0	20.45	942	1.74	13.48	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.91	12.83	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:0	20.45	938	1.74	13.5	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.97	12.82	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:0	20.45	938	1.73	13.49	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.92	12.81	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:0	20.45	937	1.73	13.49	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.95	12.8	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:1	20.45	936	1.73	13.49	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.87	12.79	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:1	19.09	936	1.73	13.5	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.93	12.78	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:1	19.09	939	1.72	13.49	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.89	12.77	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:1	19.09	962	1.72	13.52	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.93	12.79	0.87	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:1	19.09	986	1.72	13.49	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.88	12.8	0.87	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:1	21.81	1003	1.72	13.52	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.91	12.8	0.87	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:1	21.81	1003	1.73	13.51	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.88	12.81	0.87	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:57:2	21.81	1021	1.73	13.52	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.9	12.82	0.87	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:2	21.81	1021	1.73	13.52	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.87	12.83	0.87	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:2	19.09	1032	1.74	13.49	115	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.86	12.85	0.88	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:2	19.09	1044	1.74	13.49	115	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.87	12.86	0.88	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:2	19.09	1067	1.74	13.5	115	196	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.91	12.87	0.88	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:2	20.45	1067	1.75	13.51	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.95	12.88	0.88	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:3	20.45	1075	1.76	13.5	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.91	12.86	0.88	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:3	20.45	1086	1.76	13.49	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.94	12.85	0.88	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:3	20.45	1086	1.77	13.5	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.91	12.85	0.88	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:3	20.45	1091	1.78	13.49	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.93	12.82	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:3	20.45	1104	1.79	13.52	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.91	12.81	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:3	20.45	1112	1.8	13.49	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.89	12.78	0.87	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:4	19.09	1112	1.8	13.52	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.95	12.77	0.87	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:4	19.09	1126	1.81	13.52	114	196	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.88	12.76	0.87	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:4	19.09	1139	1.82	13.48	114	196	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.89	12.72	0.87	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:4	19.09	1139	1.83	13.51	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.87	12.72	0.87	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:4	20.45	1143	1.84	13.48	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.85	12.72	0.87	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:4	20.45	1139	1.84	13.48	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.86	12.71	0.87	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:57:4	20.45	1139	1.85	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.8	12.71	0.87	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:5	20.45	1156	1.86	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.83	12.71	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:5	20.45	1161	1.87	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.81	12.71	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:5	20.45	1166	1.88	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.78	12.7	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:5	20.45	1179	1.88	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.79	12.7	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:5	20.45	1179	1.89	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.73	12.73	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:5	20.45	1183	1.9	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.73	12.71	0.87	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:6	20.45	1201	1.91	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.74	12.73	0.87	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:6	20.45	1201	1.91	13.51	115	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.71	12.74	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:6	20.45	1209	1.92	13.49	115	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.79	12.75	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:6	20.45	1228	1.92	13.51	115	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.72	12.77	0.87	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:6	20.45	1238	1.93	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.71	12.79	0.87	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:57:6	20.45	1254	1.94	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.73	12.82	0.87	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:6	21.81	1254	1.94	13.53	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.69	12.86	0.88	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:7	21.81	1264	1.95	13.53	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.69	12.92	0.88	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:7	21.81	1287	1.95	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.71	12.96	0.88	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:7	21.81	1286	1.96	13.51	114	196	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.7	13	0.89	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:7	21.81	1286	1.96	13.51	114	196	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.7	13.05	0.89	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:7	21.81	1298	1.97	13.5	114	196	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.71	13.09	0.89	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:7	21.81	1315	1.97	13.51	114	196	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.76	13.15	0.9	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:8	21.81	1327	1.98	13.51	114	196	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.75	13.19	0.9	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:8	21.81	1327	1.98	13.53	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.73	13.25	0.9	4.3	4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:8	21.81	1331	2	13.51	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.83	13.31	0.91	4.2	4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:8	21.81	1346	2	13.51	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.82	13.39	0.91	4.2	4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:8	21.81	1358	2.01	13.5	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.8	13.45	0.92	4.3	4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:8	21.81	1360	2.02	13.49	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.79	13.5	0.92	4.3	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:57:9	21.81	1368	2.03	13.47	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.71	13.59	0.93	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:9	21.81	1378	2.03	13.5	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.7	13.66	0.93	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:9	23.18	1384	2.04	13.5	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.67	13.73	0.93	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:57:9	23.18	1380	2.04	13.5	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.67	13.8	0.94	4.3	4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:9	23.18	1384	2.05	13.5	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.69	13.9	0.95	4.2	4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:9	23.18	1402	2.06	13.52	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.71	13.98	0.95	4.2	4	ON	28 Pin	OFF	Removed	Disabled
03:07:57:9	23.18	1413	2.07	13.5	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.68	14.05	0.96	4.1	4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:0	23.18	1419	2.07	13.51	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.69	14.12	0.96	4.1	4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:0	23.18	1438	2.08	13.49	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.72	14.19	0.97	4.1	4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:0	23.18	1456	2.09	13.5	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.71	14.29	0.97	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:58:0	23.18	1462	2.09	13.51	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-0.7	14.36	0.98	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:58:0	23.18	1480	2.1	13.5	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.71	14.45	0.98	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:58:0	23.18	1484	2.1	13.5	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.8	14.51	0.99	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:58:1	23.18	1496	2.12	13.51	114	196	Off Idle	86.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-0.76	14.59	0.99	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:07:58:1	24.54	1511	2.12	13.5	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-0.75	14.63	1	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:1	24.54	1511	2.13	13.49	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-0.71	14.68	1	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:1	24.54	1518	2.13	13.49	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-0.7	14.73	1	4.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:1	24.54	1529	2.14	13.47	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-0.7	14.76	1.01	4.1	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:1	24.54	1543	2.15	13.5	114	196	Off Idle	86.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-0.72	14.78	1.01	4.1	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:1	24.54	1543	2.15	13.49	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-0.7	14.82	1.01	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:2	24.54	1561	2.16	13.51	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-0.71	14.91	1.02	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:2	24.54	1568	2.17	13.49	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-0.68	14.96	1.02	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:2	24.54	1574	2.17	13.49	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-0.71	14.99	1.02	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:2	24.54	1574	2.18	13.5	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-0.71	15.05	1.03	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:2	24.54	1602	2.19	13.48	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-0.7	15.12	1.03	4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:2	24.54	1627	2.2	13.49	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-0.71	15.25	1.04	3.9	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:3	24.54	1627	2.2	13.48	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.68	15.33	1.04	3.9	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:3	25.9	1651	2.21	13.49	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-0.76	15.46	1.05	3.9	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:3	25.9	1656	2.21	13.48	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-0.74	15.53	1.06	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:3	25.9	1672	2.22	13.49	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-0.78	15.57	1.06	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:3	25.9	1680	2.23	13.51	114	196	Off Idle	86.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-0.78	15.62	1.06	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:3	25.9	1698	2.23	13.51	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-0.77	15.67	1.07	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:4	25.9	1707	2.24	13.49	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-0.78	15.7	1.07	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:07:58:4	25.9	1707	2.25	13.5	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-0.8	15.7	1.07	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:4	25.9	1722	2.26	13.5	114	196	Off Idle	86.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-0.79	15.69	1.07	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:4	25.9	1753	2.27	13.49	114	196	Off Idle	86.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-0.81	15.68	1.07	3.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:4	27.27	1753	2.27	13.49	114	196	Off Idle	86.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-0.81	15.65	1.07	3.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:4	27.27	1747	2.28	13.5	114	196	Off Idle	86.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-0.85	15.61	1.06	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:4	27.27	1762	2.29	13.49	114	196	Off Idle	86.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-0.81	15.59	1.06	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:58:5	27.27	1785	2.3	13.48	114	196	Off Idle	86.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-0.83	15.56	1.06	3.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:5	27.27	1785	2.3	13.48	114	196	Off Idle	86.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-0.81	15.54	1.06	3.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:5	27.27	1773	2.32	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-0.83	15.47	1.05	3.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:5	27.27	1782	2.32	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-0.87	15.4	1.05	3.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:5	27.27	1798	2.33	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-0.88	15.37	1.05	3.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:5	27.27	1804	2.34	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-0.87	15.35	1.05	3.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:6	27.27	1823	2.34	13.47	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-0.84	15.29	1.04	3.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:6	27.27	1839	2.35	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.85	15.25	1.04	3.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:6	27.27	1860	2.36	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.84	15.23	1.04	3.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:6	27.27	1870	2.37	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.89	15.21	1.04	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:6	27.27	1896	2.37	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.89	15.19	1.04	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:6	27.27	1906	2.38	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.91	15.19	1.03	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:6	27.27	1906	2.39	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.91	15.21	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:7	28.63	1932	2.4	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.96	15.23	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:7	28.63	1938	2.4	13.53	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-0.97	15.24	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:7	28.63	1950	2.41	13.54	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-0.98	15.28	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:58:7	28.63	1956	2.41	13.53	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-0.97	15.29	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:7	28.63	1983	2.42	13.52	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-0.94	15.29	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:7	28.63	1979	2.43	13.51	114	196	Off Idle	86.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-0.91	15.28	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:58:8	28.63	1984	2.43	13.48	114	196	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-0.91	15.29	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:8	28.63	2001	2.44	13.46	114	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.91	15.29	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:8	28.63	2020	2.45	13.45	114	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.91	15.27	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:8	28.63	2019	2.45	13.44	114	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.94	15.24	1.04	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:8	28.63	2019	2.46	13.44	114	196	Off Idle	86	0	2	132	944 Turbo	0.11	Lean	1	14.6	-0.96	15.22	1.04	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:8	28.63	2038	2.46	13.44	114	196	Off Idle	86	0	2	132	944 Turbo	0.11	Lean	1	14.6	-0.97	15.19	1.03	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:9	28.63	2053	2.47	13.44	114	196	Off Idle	86	0	2	132	944 Turbo	0.12	Lean	1	14.6	-0.96	15.16	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:9	28.63	2053	2.48	13.45	114	196	Off Idle	86	0	2	132	944 Turbo	0.13	Lean	1	14.6	-0.91	15.13	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:9	28.63	2068	2.48	13.45	114	196	Off Idle	86	0	2	132	944 Turbo	0.14	Lean	1	14.6	-0.92	15.11	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:9	28.63	2087	2.49	13.46	114	196	Off Idle	86	0	2	132	944 Turbo	0.16	Lean	1	14.6	-0.9	15.09	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:9	28.63	2094	2.49	13.47	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-0.91	15.08	1.03	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:9	29.99	2126	2.5	13.49	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.95	15.07	1.03	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:58:9	29.99	2118	2.5	13.51	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-0.99	15.05	1.03	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:0	29.99	2122	2.51	13.52	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.02	15.04	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:0	29.99	2138	2.51	13.53	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-1.02	15.03	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:0	29.99	2179	2.52	13.53	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.05	15.03	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:0	29.99	2175	2.52	13.53	114	196	Off Idle	85.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.07	15.03	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:0	29.99	2178	2.53	13.51	114	196	Off Idle	85.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-1.07	15.03	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:0	29.99	2188	2.54	13.5	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-1.13	15.02	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:1	29.99	2194	2.54	13.48	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-1.09	15.01	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:1	29.99	2216	2.55	13.48	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-1.05	14.99	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:1	29.99	2215	2.55	13.46	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-1.06	14.97	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:1	29.99	2220	2.56	13.48	114	196	Off Idle	85	0	2	132	944 Turbo	0.54	Rich	1	14.6	-1.03	14.95	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:1	29.99	2237	2.56	13.47	114	196	Off Idle	84.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.97	14.94	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:1	29.99	2245	2.57	13.49	114	196	Off Idle	84.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.99	14.92	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:1	29.99	2250	2.57	13.5	114	196	Off Idle	84.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-1	14.91	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:2	29.99	2266	2.58	13.52	114	196	Off Idle	83.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.02	14.87	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:2	29.99	2285	2.58	13.52	114	196	Off Idle	83.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.05	14.87	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:2	31.36	2315	2.59	13.52	114	196	Off Idle	82.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-1.1	14.87	1.01	3.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:2	31.36	2320	2.59	13.52	114	196	Off Idle	82	0	2	132	944 Turbo	0.43	Rich	1	14.6	-1.08	14.88	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:2	31.36	2320	2.6	13.5	114	196	Off Idle	81.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.11	14.87	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:2	31.36	2346	2.61	13.49	114	196	Off Idle	81	0	2	132	944 Turbo	0.34	Lean	1	14.6	-1.1	14.86	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:3	31.36	2353	2.61	13.47	114	196	Off Idle	80.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-1.08	14.87	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:3	31.36	2387	2.62	13.47	114	196	Off Idle	79.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.07	14.88	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:3	31.36	2382	2.63	13.47	114	196	Off Idle	78.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-1.11	14.93	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:3	31.36	2397	2.63	13.48	114	196	Off Idle	78.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-1.09	14.98	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:3	31.36	2400	2.63	13.48	114	196	Off Idle	77.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-1.1	15	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:3	31.36	2412	2.64	13.5	114	196	Off Idle	76.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.09	15	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:4	31.36	2430	2.64	13.48	114	196	Off Idle	76.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-1.1	15.03	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:4	31.36	2429	2.65	13.48	114	196	Off Idle	75.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-1.08	15.07	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:4	31.36	2442	2.65	13.49	114	196	Off Idle	75	0	2	132	944 Turbo	0.38	Rich	1	14.6	-1.04	15.1	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:4	31.36	2442	2.66	13.49	114	196	Off Idle	73.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-1.03	15.14	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:4	31.36	2464	2.67	13.5	114	196	Off Idle	73.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.09	15.15	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:4	31.36	2459	2.67	13.51	114	196	Off Idle	72.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-1.07	15.13	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:4	31.36	2475	2.68	13.51	114	196	Off Idle	72	0	2	132	944 Turbo	0.59	Rich	1	14.6	-1.13	15.11	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:5	31.36	2475	2.69	13.51	114	196	Off Idle	71.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.15	15.06	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:5	31.36	2484	2.69	13.5	114	196	Off Idle	71.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.12	15	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:5	31.36	2510	2.7	13.52	114	196	Off Idle	70.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.16	14.82	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:5	31.36	2510	2.7	13.51	114	196	Off Idle	69.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.13	14.77	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:5	31.36	2526	2.71	13.51	114	196	Off Idle	69.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.13	14.72	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:5	31.36	2553	2.71	13.52	114	196	Off Idle	68.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.18	14.67	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:6	31.36	2553	2.72	13.5	114	196	Off Idle	68.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.2	14.62	1	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:6	31.36	2553	2.72	13.5	114	196	Off Idle	68	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.14	14.6	0.99	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:6	31.36	2578	2.73	13.48	114	196	Off Idle	67.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.12	14.59	0.99	3.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:6	31.36	2578	2.73	13.49	114	196	Off Idle	67.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1.09	14.61	0.99	3.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:6	31.36	2594	2.74	13.48	114	196	Off Idle	66.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-1.07	14.59	0.99	3.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:6	31.36	2606	2.74	13.49	114	196	Off Idle	65.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.11	14.75	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:07:59:6	31.36	2616	2.75	13.49	114	196	Off Idle	65.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-1.14	14.76	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:07:59:7	31.36	2617	2.76	13.5	114	196	Off Idle	64.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-1.16	14.79	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:07:59:7	31.36	2639	2.76	13.49	114	196	Off Idle	64.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-1.16	14.78	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:7	31.36	2639	2.76	13.5	114	196	Off Idle	64	0	2	132	944 Turbo	0.46	Lean	1	14.6	-1.2	14.78	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:7	31.36	2658	2.77	13.5	114	196	Off Idle	63.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-1.17	14.78	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:7	31.36	2679	2.77	13.51	114	196	Off Idle	61.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-1.17	14.81	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:7	31.36	2686	2.78	13.52	114	196	Off Idle	61.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.23	14.86	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:8	31.36	2712	2.79	13.5	114	196	Off Idle	60.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-1.22	14.94	1.02	3.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:8	31.36	2746	2.79	13.51	114	196	Off Idle	60	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.21	14.99	1.02	3.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:07:59:8	31.36	2752	2.8	13.5	114	196	Off Idle	59.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-1.19	15.06	1.03	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:07:59:8	31.36	2765	2.8	13.5	114	196	Off Idle	58.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.16	15.08	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:8	31.36	2765	2.81	13.48	114	196	Off Idle	57.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-1.19	15.11	1.03	3.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:8	31.36	2840	2.82	13.47	114	196	Off Idle	56.7	0	2	132	944 Turbo	0.32	Rich	1	14.6	-1.14	15.18	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:07:59:9	32.72	2789	2.82	13.49	114	196	Off Idle	56	0	2	132	944 Turbo	0.38	Rich	1	14.6	-1.14	15.24	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:9	32.72	2792	2.83	13.51	114	196	Off Idle	55.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-1.13	15.26	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:9	32.72	2792	2.83	13.49	114	196	Off Idle	54.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.18	15.25	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:9	32.72	2797	2.84	13.5	114	196	Off Idle	53.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.12	15.2	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:9	32.72	2797	2.84	13.5	114	196	Off Idle	53.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.13	15.18	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:9	32.72	2805	2.85	13.49	114	196	Off Idle	52.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-1.11	15.1	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:07:59:9	32.72	2820	2.86	13.49	114	196	Off Idle	52.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.09	15.04	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:0	32.72	2835	2.87	13.51	114	196	Off Idle	51.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.08	14.99	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:0	32.72	2850	2.87	13.49	114	196	Off Idle	50.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.09	14.95	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:0	32.72	2855	2.88	13.5	114	196	Off Idle	50.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.07	14.9	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:0	32.72	2872	2.88	13.5	114	196	Off Idle	49.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-1.06	14.86	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:0	32.72	2895	2.89	13.51	114	196	Off Idle	49.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-1.07	14.84	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:0	32.72	2890	2.89	13.51	114	196	Off Idle	48.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-1.14	14.82	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:1	32.72	2904	2.89	13.51	114	196	Off Idle	48.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.15	14.82	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:1	32.72	2911	2.9	13.5	114	196	Off Idle	47.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.13	14.84	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:1	32.72	2920	2.9	13.5	114	196	Off Idle	47	0	2	132	944 Turbo	0.47	Rich	1	14.6	-1.07	14.86	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:1	32.72	2944	2.91	13.49	114	196	Off Idle	46.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-1.05	14.88	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:1	32.72	2964	2.91	13.49	114	196	Off Idle	46.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-1.09	14.89	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:1	32.72	2964	2.92	13.48	114	196	Off Idle	45.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-1.12	14.89	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:1	32.72	2986	2.92	13.48	114	196	Off Idle	45.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-1.13	14.91	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:2	32.72	2998	2.93	13.49	114	196	Off Idle	44.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.12	14.98	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:2	32.72	3038	2.93	13.49	114	196	Off Idle	44.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-1.15	15	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:2	32.72	3032	2.94	13.49	114	196	Off Idle	44	0	2	132	944 Turbo	0.21	Lean	1	14.6	-1.12	15.05	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:2	32.72	3037	2.94	13.49	114	196	Off Idle	43.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-1.09	15.07	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:2	32.72	3048	2.95	13.49	114	196	Off Idle	42.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-1.07	15.1	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:2	32.72	3094	2.96	13.49	114	196	Off Idle	42.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-1.05	15.11	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:3	32.72	3094	2.96	13.49	114	196	Off Idle	42.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-1.07	15.13	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:3	32.72	3085	2.97	13.49	114	196	Off Idle	42.2	0	2	132	944 Turbo	0.23	Rich	1	14.6	-1.18	15.15	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:3	32.72	3104	2.97	13.49	114	196	Off Idle	42	0	2	132	944 Turbo	0.27	Rich	1	14.6	-1.16	15.17	1.03	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:00:3	32.72	3113	2.98	13.49	114	196	Off Idle	41.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-1.21	15.18	1.03	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:3	32.72	3148	2.99	13.47	114	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-1.21	15.16	1.03	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:3	32.72	3140	2.99	13.48	115	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-1.21	15.12	1.03	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:4	32.72	3135	2.99	13.48	115	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-1.18	15.08	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:4	32.72	3142	3	13.49	114	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-1.18	15.03	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:00:4	32.72	3151	3	13.49	114	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-1.25	14.99	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:00:4	32.72	3154	3	13.5	114	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.25	14.94	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:4	32.72	3165	3.01	13.49	114	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.3	14.86	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:4	32.72	3171	3.01	13.48	114	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.26	14.79	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:00:4	32.72	3178	3.02	13.47	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.24	14.74	1	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:00:5	32.72	3240	3.02	13.48	114	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.23	14.7	1	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:00:5	32.72	3206	3.02	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.17	14.68	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:5	32.72	3206	3.02	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.25	14.66	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:5	32.72	3222	3.02	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.23	14.65	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:5	32.72	3236	3.03	13.51	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.29	14.65	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:5	32.72	3250	3.03	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.2	14.67	1	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:6	32.72	3254	3.03	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.28	14.7	1	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:00:6	32.72	3275	3.04	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.23	14.74	1	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:6	32.72	3340	3.04	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-1.21	14.77	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:6	32.72	3340	3.04	13.47	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	-1.24	14.79	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:6	34.08	3312	3.04	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Lean	1	14.6	-1.23	14.8	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:6	34.08	3331	3.05	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-1.26	14.86	1.01	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:6	34.08	3351	3.05	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-1.25	14.9	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:7	34.08	3351	3.05	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-1.28	14.95	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:00:7	34.08	3377	3.06	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-1.23	14.99	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:7	34.08	3402	3.06	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.21	15.04	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:00:7	34.08	3402	3.06	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-1.2	15.08	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:7	34.08	3412	3.06	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-1.19	15.12	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:7	34.08	3425	3.06	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-1.17	15.16	1.03	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:00:8	34.08	3431	3.07	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.29	15.19	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:8	34.08	3433	3.07	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-1.3	15.17	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:8	34.08	3432	3.07	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-1.39	15.1	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:8	34.08	3436	3.07	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-1.44	15.05	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:8	34.08	3438	3.08	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.39	14.99	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:8	34.08	3444	3.08	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.44	14.92	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:9	34.08	3445	3.08	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.44	14.87	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:9	34.08	3464	3.08	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.43	14.81	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:9	34.08	3455	3.08	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.36	14.77	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:9	34.08	3458	3.08	13.52	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-1.45	14.73	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:9	34.08	3479	3.08	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-1.36	14.76	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:00:9	34.08	3531	3.08	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-1.33	14.76	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:00:9	34.08	3518	3.09	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-1.41	14.77	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:01:0	34.08	3520	3.09	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-1.32	14.78	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:01:0	34.08	3536	3.09	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-1.34	14.86	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:01:0	34.08	3554	3.09	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.35	14.89	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:01:0	34.08	3592	3.09	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.42	14.91	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:01:0	34.08	3592	3.09	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.44	14.93	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:01:0	34.08	3605	3.09	13.51	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.54	14.98	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:01:1	34.08	3609	3.1	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.54	15	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:01:1	34.08	3623	3.1	13.52	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-1.57	15.04	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:1	34.08	3629	3.1	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-1.44	15.1	1.03	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:1	34.08	3642	3.1	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-1.45	15.1	1.03	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:1	34.08	3630	3.1	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.54	15.06	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:01:1	34.08	3652	3.11	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-1.53	15.03	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:01:1	34.08	3656	3.11	13.47	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.61	15	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:01:2	34.08	3660	3.11	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1.64	14.99	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:01:2	35.45	3686	3.11	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.65	14.93	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:01:2	35.45	3684	3.11	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.68	14.89	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:01:2	35.45	3695	3.11	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.67	14.87	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:01:2	35.45	3695	3.11	13.52	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.76	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:01:2	35.45	3706	3.12	13.52	114	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.74	14.8	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:01:3	34.08	3718	3.12	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.77	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:01:3	34.08	3718	3.12	13.51	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-1.84	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:01:3	34.08	3730	3.12	13.51	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-1.78	14.83	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:3	34.08	3744	3.12	13.48	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-1.73	14.83	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:01:3	34.08	3778	3.12	13.46	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-1.83	14.88	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:3	34.08	3768	3.11	13.49	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-1.97	14.92	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:01:4	34.08	3769	3.1	13.46	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-2.18	14.96	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:01:4	34.08	3782	3.09	13.47	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-2.6	14.99	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:01:4	34.08	3814	3.06	13.5	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.09	15	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:01:4	35.45	3801	3.02	13.51	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.7	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:01:4	35.45	3785	2.97	13.51	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.5	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:01:4	35.45	3782	2.87	13.55	114	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.73	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:01:4	36.81	3739	2.79	13.53	114	196	Full Load	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.54	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:01:5	36.81	3739	2.72	13.52	114	196	Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.27	15.01	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:01:8	36.81	3712	2.65	13.51	114	196	Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.02	14.95	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	36.81	3685	2.62	13.49	114	196	Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.45	14.79	1.01	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	36.81	3558	2.55	13.49	114	196	Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.8	14.66	1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	25.9	3561	2.48	13.49	114	196	Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.02	14.52	0.99	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	25.9	3530	2.36	13.48	114	196	Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.21	14.32	0.98	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3516	2.29	13.5	114	196	Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.38	14.02	0.96	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3518	2.21	13.5	114	196	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.44	13.85	0.94	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3512	2.14	13.51	114	196	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.52	13.68	0.93	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3462	2.03	13.53	114	196	Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.53	13.54	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3421	1.96	13.51	114	196	Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.54	13.31	0.91	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3389	1.89	13.51	114	196	Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.58	13.18	0.9	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3344	1.83	13.51	114	196	Idle	40.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.55	13.08	0.89	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:7	20.45	3346	1.8	13.5	114	196	Idle	40.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.54	12.95	0.88	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:7	20.45	3312	1.74	13.5	114	196	Idle	39.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.57	12.88	0.88	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:7	20.45	3261	1.69	13.49	114	196	Idle	37.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.54	12.81	0.87	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:7	20.45	3237	1.68	13.5	114	196	Idle	36.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.56	12.73	0.87	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:7	20.45	3216	1.68	13.52	114	196	Idle	35.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.54	12.68	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:7	20.45	3194	1.69	13.53	114	196	Idle	34.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.53	12.61	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3170	1.69	13.52	114	196	Idle	32.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.48	12.61	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3162	1.7	13.54	114	196	Idle	32.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.45	12.63	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3110	1.7	13.52	114	196	Idle	31.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.35	12.72	0.87	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3068	1.71	13.5	114	196	Idle	30.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.29	12.84	0.87	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3068	1.72	13.51	114	196	Idle	28.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.25	13	0.89	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:8	20.45	3036	1.73	13.49	114	196	Idle	27.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.18	13.22	0.9	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:9	19.09	2932	1.75	13.48	114	196	Idle	26.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.12	13.85	0.94	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:9	19.09	2965	1.76	13.49	114	196	Idle	24.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.1	14.53	0.99	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:9	19.09	2956	1.77	13.5	114	196	Idle	24	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.07	15.28	1.04	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:9	19.09	2922	1.78	13.5	114	196	Idle	22.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.03	16.39	1.12	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:9	19.09	2896	1.79	13.5	114	196	Idle	22.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.97	17.11	1.17	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:9	19.09	2821	1.8	13.52	114	196	Idle	22.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.98	17.8	1.21	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:01:9	19.09	2821	1.81	13.5	114	196	Idle	22.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.93	18.44	1.26	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:0	19.09	2828	1.82	13.5	114	196	Idle	22.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.88	19.34	1.32	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:0	19.09	2794	1.82	13.49	114	196	Idle	22.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.82	19.84	1.35	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:0	19.09	2760	1.83	13.49	114	196	Idle	22.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.76	20.12	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:0	19.09	2760	1.83	13.5	114	196	Idle	22.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.7	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:0	19.09	2682	1.83	13.51	114	196	Idle	23.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.7	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:0	19.09	2696	1.84	13.5	114	196	Idle	23.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.69	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:1	19.09	2650	1.84	13.5	114	196	Idle	24.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.65	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:1	19.09	2634	1.84	13.5	114	196	Idle	24.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.65	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:1	19.09	2625	1.84	13.5	114	196	Idle	26.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:1	19.09	2579	1.84	13.51	114	196	Idle	27.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.54	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:1	19.09	2561	1.84	13.51	114	196	Full Load	28.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.46	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:1	19.09	2552	1.84	13.51	114	196	Off Idle	29.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.42	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:1	19.09	2398	1.84	13.51	114	196	Off Idle	30.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.35	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:02:2	10.9	2507	1.84	13.51	114	196	Off Idle	31.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.27	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:02:2	13.63	2489	1.85	13.5	114	196	Off Idle	34.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.21	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:02:2	13.63	2478	1.85	13.5	114	196	Off Idle	40.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.14	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:02:2	16.36	2438	1.85	13.49	114	196	Off Idle	43.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.01	20.24	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:02:2	16.36	2387	1.85	13.49	114	196	Off Idle	45.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.97	20.24	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:02:2	19.09	2387	1.85	13.48	114	196	Off Idle	48.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.86	20.24	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:02:3	21.81	2360	1.86	13.48	114	196	Off Idle	48.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.73	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:02:3	21.81	2326	1.87	13.47	114	196	Off Idle	51.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.61	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:02:3	24.54	2234	1.89	13.47	114	196	Off Idle	54.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.48	20.26	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:02:3	27.27	2234	1.9	13.46	114	196	Off Idle	60.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.23	20.26	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:3	27.27	2244	1.91	13.45	114	196	Off Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.09	20.26	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:02:3	29.99	2215	1.91	13.47	114	196	Off Idle	66	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.95	20.26	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:02:4	29.99	2202	1.93	13.48	114	196	Off Idle	68.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.76	20.25	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:02:4	32.72	2151	1.94	13.49	114	196	Off Idle	71.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.65	20.25	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:02:4	32.72	2151	1.95	13.49	114	196	Off Idle	74.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.54	20.25	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:02:4	32.72	2195	1.97	13.52	114	196	Off Idle	76.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.4	20.25	1.38	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:02:4	32.72	2210	2	13.53	114	196	Off Idle	77.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.33	20.24	1.38	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:02:4	32.72	2222	2.02	13.54	114	196	Off Idle	78.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.08	20.24	1.38	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:4	32.72	2237	2.05	13.54	114	196	Off Idle	79.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.95	20.25	1.38	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:02:5	32.72	2254	2.08	13.53	114	196	Off Idle	80.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.53	20.25	1.38	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:02:5	32.72	2254	2.11	13.54	114	196	Off Idle	80.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.24	20.26	1.38	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:02:5	32.72	2281	2.13	13.53	114	196	Off Idle	81	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.94	20.26	1.38	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:5	32.72	2288	2.16	13.52	114	196	Off Idle	81.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.68	20.26	1.38	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:5	32.72	2299	2.18	13.51	114	196	Off Idle	81.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.57	20.26	1.38	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:5	32.72	2300	2.2	13.48	114	196	Off Idle	81.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.49	20.27	1.38	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:6	32.72	2303	2.22	13.47	114	196	Off Idle	80.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.35	20.28	1.38	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:6	32.72	2299	2.23	13.46	114	196	Off Idle	80.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.25	20.27	1.38	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:6	32.72	2294	2.25	13.47	114	196	Off Idle	80.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.15	20.27	1.38	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:6	32.72	2273	2.27	13.49	114	196	Off Idle	79.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.11	20.25	1.38	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:6	32.72	2256	2.28	13.49	114	196	Off Idle	79.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.1	20.15	1.37	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:6	32.72	2256	2.31	13.48	114	196	Off Idle	79	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.98	19.9	1.36	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:6	32.72	2243	2.32	13.48	114	196	Off Idle	79	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.94	19.7	1.34	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:7	32.72	2244	2.34	13.46	114	196	Off Idle	79	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.89	19.58	1.33	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:08:02:7	32.72	2245	2.34	13.47	114	196	Off Idle	79.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.87	19.16	1.31	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:08:02:7	32.72	2253	2.34	13.47	114	196	Off Idle	79.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.89	18.86	1.28	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:7	32.72	2269	2.34	13.47	114	196	Off Idle	79.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.88	18.52	1.26	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:7	32.72	2281	2.34	13.48	114	196	Off Idle	79.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.83	17.94	1.22	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:02:7	32.72	2286	2.34	13.5	114	196	Off Idle	79.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-3.82	17.53	1.19	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:02:8	32.72	2304	2.33	13.51	114	196	Off Idle	79.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.78	17.18	1.17	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:02:8	31.36	2294	2.34	13.49	114	196	Off Idle	79.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.78	16.85	1.15	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:02:8	31.36	2314	2.34	13.49	114	196	Off Idle	79.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.8	16.53	1.13	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:8	31.36	2314	2.34	13.49	114	196	Off Idle	79.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.86	16.39	1.12	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:8	31.36	2301	2.34	13.47	114	196	Off Idle	79.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.85	16.02	1.09	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:8	31.36	2315	2.34	13.48	114	196	Off Idle	79	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.82	15.8	1.08	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:9	31.36	2318	2.34	13.47	114	196	Off Idle	78.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.78	15.6	1.06	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:9	31.36	2303	2.34	13.49	114	196	Off Idle	78.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.7	15.39	1.05	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:02:9	31.36	2300	2.34	13.5	114	196	Off Idle	78.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.68	15.33	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:02:9	31.36	2300	2.35	13.52	114	196	Off Idle	78	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.7	15.25	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:02:9	31.36	2291	2.35	13.52	114	196	Off Idle	77.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.74	15.15	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:02:9	31.36	2304	2.35	13.51	114	196	Off Idle	77.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.78	15.13	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:02:9	31.36	2309	2.35	13.5	114	196	Off Idle	77.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.8	15.08	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:0	31.36	2314	2.35	13.51	114	196	Off Idle	77.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.78	15.02	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:0	31.36	2325	2.35	13.49	114	196	Off Idle	77.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.74	14.99	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:0	31.36	2340	2.36	13.49	114	196	Off Idle	77.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.67	14.97	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:0	31.36	2338	2.36	13.49	114	196	Off Idle	77.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.64	14.95	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:0	31.36	2344	2.36	13.51	114	196	Off Idle	76.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.64	14.91	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:0	31.36	2344	2.36	13.5	114	196	Off Idle	76.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.73	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:1	31.36	2346	2.36	13.5	114	196	Off Idle	76.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.77	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:1	31.36	2348	2.36	13.51	114	196	Off Idle	76.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.8	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:1	31.36	2348	2.36	13.5	114	196	Off Idle	76.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.82	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:1	31.36	2348	2.36	13.49	114	196	Off Idle	76.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.79	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:1	31.36	2348	2.36	13.5	114	196	Off Idle	76.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.79	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:1	31.36	2346	2.37	13.5	114	196	Off Idle	75.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.79	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:1	31.36	2342	2.37	13.49	114	196	Off Idle	75.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.74	14.75	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:2	31.36	2348	2.37	13.5	114	196	Off Idle	75.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.79	14.74	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:2	31.36	2348	2.37	13.49	114	196	Off Idle	75.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.77	14.72	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:2	31.36	2360	2.37	13.48	114	196	Off Idle	75.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.7	14.71	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:2	31.36	2363	2.37	13.48	114	196	Off Idle	75.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.72	14.71	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:2	31.36	2370	2.37	13.49	114	196	Off Idle	75	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.72	14.71	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:2	31.36	2370	2.37	13.47	114	196	Off Idle	74.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.72	14.71	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:3	31.36	2370	2.38	13.47	114	196	Off Idle	74.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.73	14.73	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:3	31.36	2383	2.38	13.48	114	196	Off Idle	74.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.76	14.72	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:03:3	31.36	2388	2.38	13.48	114	196	Off Idle	74.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.79	14.74	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:3	31.36	2388	2.38	13.47	114	196	Off Idle	74.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.79	14.74	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:3	31.36	2390	2.38	13.48	114	196	Off Idle	73.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.77	14.74	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:3	31.36	2404	2.38	13.5	114	196	Off Idle	73.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.75	14.75	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:4	31.36	2394	2.38	13.5	114	196	Off Idle	73.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.73	14.76	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:4	31.36	2386	2.38	13.5	114	196	Off Idle	73.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.73	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:4	31.36	2386	2.39	13.51	114	196	Off Idle	73.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.69	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:4	31.36	2389	2.39	13.51	114	196	Off Idle	73	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.69	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:4	31.36	2389	2.39	13.51	114	196	Off Idle	72.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.71	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:4	31.36	2396	2.39	13.5	114	196	Off Idle	72.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.74	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:4	31.36	2399	2.39	13.52	114	196	Off Idle	72.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.72	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:5	31.36	2408	2.39	13.51	114	196	Off Idle	72.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.76	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:5	31.36	2408	2.39	13.49	114	196	Off Idle	72.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.8	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:03:5	31.36	2408	2.39	13.49	114	196	Off Idle	72.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.78	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:03:5	31.36	2418	2.39	13.49	114	196	Off Idle	72.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.77	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:03:5	31.36	2422	2.4	13.49	114	196	Off Idle	72.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.8	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:03:5	31.36	2422	2.4	13.48	114	196	Off Idle	72	0	2	132	944 Turbo	0.56	Rich	1	14.6	-3.81	14.86	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:03:6	31.36	2429	2.4	13.48	114	196	Off Idle	71.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.84	14.84	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:6	31.36	2430	2.4	13.49	114	196	Off Idle	71.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.83	14.85	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:6	31.36	2430	2.4	13.49	114	196	Off Idle	71.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-3.83	14.86	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:6	31.36	2430	2.4	13.5	114	196	Off Idle	71.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-3.8	14.87	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:6	31.36	2433	2.4	13.5	114	196	Off Idle	71	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.81	14.88	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:6	31.36	2432	2.4	13.5	114	196	Off Idle	70.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.74	14.91	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:6	31.36	2432	2.41	13.52	114	196	Off Idle	70.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.82	14.93	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:7	31.36	2437	2.41	13.5	114	196	Off Idle	70.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.81	14.98	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:7	32.72	2452	2.41	13.51	114	196	Off Idle	70.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.76	15.03	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:7	32.72	2452	2.41	13.51	114	196	Off Idle	70.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-3.77	15.09	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:7	32.72	2450	2.41	13.49	114	196	Off Idle	70.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.83	15.17	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:7	32.72	2458	2.41	13.48	114	196	Off Idle	70	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.84	15.2	1.04	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:7	32.72	2484	2.41	13.48	114	196	Off Idle	69.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.9	15.24	1.04	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:8	32.72	2478	2.41	13.48	114	196	Off Idle	69.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.91	15.25	1.04	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:8	32.72	2470	2.41	13.5	114	196	Off Idle	69.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.9	15.26	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:8	32.72	2471	2.42	13.48	114	196	Off Idle	69.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-3.9	15.27	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:8	32.72	2474	2.42	13.49	114	196	Off Idle	69.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.92	15.26	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:8	32.72	2470	2.42	13.5	114	196	Off Idle	69.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.93	15.25	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:8	32.72	2471	2.42	13.49	114	196	Off Idle	69	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.97	15.22	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:03:9	32.72	2470	2.42	13.48	114	196	Off Idle	68.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.97	15.21	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:9	32.72	2469	2.41	13.51	114	196	Off Idle	68.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.99	15.17	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:03:9	32.72	2468	2.41	13.49	114	196	Off Idle	68.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.01	15.15	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:03:9	32.72	2469	2.41	13.48	114	196	Off Idle	68.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.04	15.17	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:03:9	32.72	2469	2.4	13.49	114	196	Off Idle	68.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.11	15.16	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:03:9	32.72	2477	2.4	13.49	114	196	Off Idle	68.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.15	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:03:9	32.72	2481	2.4	13.47	114	196	Off Idle	68.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.21	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:04:0	32.72	2484	2.39	13.49	114	196	Off Idle	68.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.21	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:04:0	32.72	2486	2.39	13.51	114	196	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.23	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:04:0	32.72	2487	2.39	13.5	114	196	Off Idle	68.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.27	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:04:0	32.72	2490	2.39	13.51	114	196	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.26	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:04:0	32.72	2491	2.38	13.53	114	196	Off Idle	67.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.28	14.96	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:04:0	32.72	2492	2.38	13.52	114	196	Off Idle	67.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.39	14.89	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:04:1	32.72	2495	2.37	13.52	114	196	Off Idle	67.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.47	14.87	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:04:1	32.72	2494	2.37	13.52	114	196	Off Idle	67.7	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.59	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:04:1	32.72	2496	2.36	13.5	114	196	Off Idle	67.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.68	14.87	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:04:1	32.72	2502	2.35	13.49	114	196	Off Idle	67.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.8	14.87	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:04:1	32.72	2506	2.34	13.51	114	196	Off Idle	67.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.91	14.85	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:04:1	32.72	2511	2.33	13.52	114	196	Off Idle	67.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.04	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:04:1	32.72	2510	2.31	13.51	114	196	Off Idle	67.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.22	14.85	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:04:2	32.72	2509	2.3	13.52	114	196	Off Idle	67	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.37	14.87	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:2	32.72	2518	2.29	13.53	114	196	Off Idle	66.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.46	14.9	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:04:2	32.72	2508	2.28	13.51	114	195	Off Idle	66.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.5	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:2	32.72	2507	2.27	13.49	114	195	Off Idle	66.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.63	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:2	32.72	2508	2.26	13.49	114	196	Off Idle	66.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.74	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:2	32.72	2500	2.25	13.51	114	196	Off Idle	66.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.79	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:3	32.72	2512	2.24	13.5	114	196	Off Idle	66.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.91	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:3	32.72	2516	2.23	13.51	114	196	Off Idle	66.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.91	15.27	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:3	32.72	2517	2.22	13.52	114	196	Off Idle	66.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.94	15.3	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:3	32.72	2520	2.21	13.52	114	196	Off Idle	66	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.02	15.32	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:3	32.72	2524	2.2	13.51	114	196	Off Idle	65.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.02	15.3	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:3	34.08	2524	2.19	13.5	114	196	Off Idle	65.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.05	15.28	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:4	34.08	2536	2.18	13.49	114	196	Off Idle	65.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.09	15.27	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:4	34.08	2529	2.18	13.49	114	195	Off Idle	65.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.06	15.25	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:4	34.08	2529	2.18	13.49	114	195	Off Idle	65.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.08	15.22	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:4	34.08	2530	2.18	13.48	114	195	Off Idle	65.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.09	15.2	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:4	34.08	2531	2.18	13.5	114	196	Off Idle	65.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.03	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:4	34.08	2533	2.18	13.52	114	196	Off Idle	64.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.06	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:4	34.08	2534	2.18	13.51	114	196	Off Idle	64.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.06	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:5	34.08	2544	2.18	13.51	114	196	Off Idle	64.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.07	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:5	34.08	2537	2.18	13.49	114	196	Off Idle	64.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.08	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:5	34.08	2539	2.18	13.49	114	196	Off Idle	64.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.11	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:5	34.08	2546	2.18	13.49	114	196	Off Idle	64.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.11	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:5	34.08	2546	2.18	13.5	114	196	Off Idle	64.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.09	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:5	34.08	2548	2.18	13.5	114	196	Off Idle	64.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.12	15.19	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:6	34.08	2550	2.18	13.52	114	196	Off Idle	63.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.12	15.19	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:6	34.08	2548	2.18	13.51	114	196	Off Idle	63.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.15	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:6	34.08	2547	2.18	13.5	114	196	Off Idle	63.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.16	15.19	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:6	34.08	2548	2.18	13.51	114	196	Off Idle	63.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.16	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:6	34.08	2548	2.19	13.5	114	196	Off Idle	63.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.17	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:6	34.08	2548	2.19	13.5	114	196	Off Idle	63.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.16	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:6	34.08	2554	2.19	13.5	114	196	Off Idle	63.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.19	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:04:7	34.08	2544	2.19	13.51	114	196	Off Idle	64	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.16	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:04:7	34.08	2559	2.19	13.51	114	196	Off Idle	64	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.16	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:7	34.08	2567	2.19	13.51	114	196	Off Idle	63.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.17	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:7	34.08	2566	2.19	13.51	114	196	Off Idle	63.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.2	15.06	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:04:7	34.08	2566	2.19	13.5	114	196	Off Idle	63.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.22	15.04	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:7	34.08	2570	2.19	13.5	114	196	Off Idle	63.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.23	15.04	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:8	34.08	2568	2.19	13.51	114	196	Off Idle	63.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.24	15.03	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:8	34.08	2568	2.19	13.51	114	196	Off Idle	63.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.26	15.05	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:8	34.08	2569	2.19	13.51	114	196	Off Idle	63.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.23	15.04	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:8	34.08	2588	2.19	13.51	114	196	Off Idle	63.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.23	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:8	34.08	2588	2.19	13.51	114	196	Off Idle	63.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.23	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:8	34.08	2567	2.19	13.5	114	196	Off Idle	63.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.24	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:9	34.08	2562	2.19	13.52	114	196	Off Idle	63.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.23	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:9	34.08	2559	2.19	13.51	114	195	Off Idle	63.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.29	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:9	34.08	2564	2.19	13.49	114	195	Off Idle	63	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.35	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:9	34.08	2566	2.18	13.48	114	195	Off Idle	62.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.36	14.96	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:04:9	34.08	2568	2.18	13.49	114	196	Off Idle	62.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.41	14.93	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:9	34.08	2571	2.18	13.48	114	196	Off Idle	62.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.43	14.89	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:04:9	34.08	2581	2.18	13.51	114	196	Off Idle	62.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.44	14.85	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:05:0	34.08	2574	2.17	13.51	114	195	Off Idle	62.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.47	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:05:0	34.08	2578	2.17	13.51	114	195	Off Idle	62.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.53	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:05:0	34.08	2579	2.16	13.51	114	195	Off Idle	62.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.54	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:05:0	34.08	2583	2.16	13.51	114	196	Off Idle	62.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.56	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:05:0	34.08	2588	2.15	13.52	114	196	Off Idle	62.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.6	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:05:0	34.08	2588	2.15	13.51	114	196	Off Idle	62.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.63	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:05:1	34.08	2591	2.14	13.52	114	196	Off Idle	62.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.67	14.77	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:05:1	34.08	2590	2.14	13.52	114	196	Off Idle	62	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.75	14.78	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:05:1	34.08	2587	2.14	13.5	114	196	Off Idle	61.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.74	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:05:1	34.08	2587	2.13	13.49	114	196	Off Idle	61.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.78	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:1	34.08	2583	2.12	13.5	114	196	Off Idle	61.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.8	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:1	34.08	2578	2.12	13.49	114	196	Off Idle	61.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.82	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:1	34.08	2578	2.11	13.49	114	196	Off Idle	61.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.86	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:2	34.08	2581	2.11	13.5	114	196	Off Idle	61.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.88	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:2	34.08	2579	2.11	13.5	114	196	Off Idle	61.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.93	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:2	34.08	2583	2.1	13.51	114	196	Off Idle	61.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.96	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:2	34.08	2584	2.1	13.5	114	196	Off Idle	61.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.99	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:2	34.08	2587	2.1	13.51	114	196	Off Idle	61.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.02	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:2	34.08	2594	2.09	13.52	114	196	Off Idle	61.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.02	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:3	34.08	2599	2.09	13.5	114	196	Off Idle	61.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.06	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:05:3	34.08	2599	2.09	13.51	114	196	Off Idle	61.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.04	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:3	34.08	2606	2.09	13.52	114	196	Off Idle	61.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.04	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:3	34.08	2606	2.08	13.52	114	196	Off Idle	61.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.07	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:3	34.08	2608	2.08	13.52	114	196	Off Idle	61.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.09	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:3	34.08	2608	2.08	13.53	114	196	Off Idle	61.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.11	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:4	34.08	2610	2.07	13.52	114	196	Off Idle	61	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.15	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:4	34.08	2612	2.07	13.5	114	196	Off Idle	60.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.21	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:4	34.08	2611	2.07	13.49	114	196	Off Idle	60.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.25	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:4	34.08	2611	2.07	13.49	114	196	Off Idle	60.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.25	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:4	34.08	2606	2.06	13.49	114	196	Off Idle	60.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.27	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:4	34.08	2603	2.06	13.48	114	196	Off Idle	60.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.32	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:4	34.08	2597	2.05	13.5	114	196	Off Idle	60.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.34	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:5	34.08	2596	2.05	13.52	114	196	Off Idle	60.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.39	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:5	34.08	2604	2.04	13.52	114	196	Off Idle	60.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.47	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:05:5	34.08	2592	2.03	13.53	114	196	Off Idle	60.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.52	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:05:5	34.08	2595	2.02	13.53	114	195	Off Idle	60.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.59	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:05:5	34.08	2595	2.02	13.53	114	195	Off Idle	60.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.64	15.05	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:05:5	34.08	2575	2.01	13.53	114	195	Off Idle	60.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	15.06	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:05:6	34.08	2596	2	13.53	114	196	Off Idle	60.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.72	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:6	34.08	2598	2	13.52	114	196	Off Idle	61.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.76	15.14	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:6	34.08	2599	1.99	13.52	114	196	Off Idle	61.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.78	15.16	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:6	34.08	2602	1.99	13.52	114	196	Off Idle	61.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.82	15.18	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:6	34.08	2605	1.98	13.51	114	196	Off Idle	61.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.81	15.18	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:6	35.45	2615	1.98	13.51	114	196	Off Idle	61.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.81	15.17	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:6	35.45	2608	1.97	13.51	114	196	Off Idle	60.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.81	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:7	35.45	2613	1.96	13.51	114	196	Off Idle	60.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.88	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:7	35.45	2606	1.96	13.49	114	196	Off Idle	60.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.9	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:7	35.45	2604	1.95	13.5	114	196	Off Idle	60.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.92	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:7	35.45	2602	1.95	13.5	114	196	Off Idle	60.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.93	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:7	35.45	2607	1.95	13.5	114	196	Off Idle	60.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:7	35.45	2608	1.95	13.52	114	196	Off Idle	60.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:8	35.45	2608	1.94	13.5	114	196	Off Idle	60.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:8	35.45	2612	1.94	13.5	114	196	Off Idle	60.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.98	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:8	35.45	2612	1.94	13.5	114	196	Off Idle	60.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:8	35.45	2609	1.94	13.51	114	196	Off Idle	60.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.04	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:8	35.45	2609	1.94	13.52	114	196	Off Idle	60	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.07	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:8	35.45	2610	1.93	13.52	114	196	Off Idle	60	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.1	14.77	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:05:9	35.45	2614	1.93	13.52	114	195	Off Idle	60	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.17	14.73	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:9	35.45	2613	1.93	13.51	114	195	Off Idle	60	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.19	14.71	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:9	35.45	2612	1.93	13.52	114	195	Off Idle	60	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.2	14.7	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:9	35.45	2612	1.92	13.52	114	196	Off Idle	60	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.25	14.71	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:9	35.45	2610	1.92	13.53	114	196	Off Idle	60	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.26	14.73	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:9	35.45	2608	1.92	13.51	114	196	Off Idle	60	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.31	14.75	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:05:9	35.45	2606	1.91	13.53	114	196	Off Idle	60	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.33	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:06:0	35.45	2602	1.91	13.53	114	196	Off Idle	59.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.35	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:06:0	35.45	2602	1.9	13.52	114	196	Off Idle	59.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.37	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:06:0	35.45	2612	1.89	13.52	114	196	Off Idle	59.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.38	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:06:0	35.45	2605	1.89	13.52	114	196	Off Idle	59.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.41	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:08:06:0	35.45	2605	1.88	13.52	114	196	Off Idle	60	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.46	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:08:06:0	35.45	2605	1.87	13.54	114	196	Off Idle	60.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.57	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:08:06:1	35.45	2604	1.85	13.51	114	196	Off Idle	60.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.64	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:06:1	35.45	2602	1.85	13.5	114	196	Off Idle	60.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.72	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:06:1	35.45	2601	1.83	13.5	114	196	Off Idle	60.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.85	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:06:1	35.45	2595	1.82	13.49	114	196	Off Idle	60.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.93	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:06:1	35.45	2574	1.81	13.48	114	196	Off Idle	60.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.96	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:06:1	35.45	2574	1.8	13.5	114	196	Off Idle	60.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.99	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:06:1	35.45	2589	1.79	13.5	114	196	Off Idle	60.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.07	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:06:2	35.45	2588	1.77	13.5	114	196	Off Idle	61.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.13	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:06:2	35.45	2590	1.76	13.51	114	196	Off Idle	61.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.14	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:06:2	35.45	2579	1.75	13.51	114	196	Off Idle	61.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.21	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:06:2	35.45	2580	1.74	13.51	114	196	Off Idle	61.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.24	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:06:2	35.45	2569	1.73	13.51	114	196	Off Idle	61.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.29	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:06:2	35.45	2578	1.72	13.52	114	196	Off Idle	61.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.4	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:06:3	35.45	2576	1.71	13.52	114	196	Off Idle	61.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.46	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:06:3	35.45	2576	1.69	13.53	114	196	Off Idle	61.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.51	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:06:3	35.45	2571	1.68	13.53	114	196	Off Idle	61.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.57	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:3	35.45	2568	1.66	13.51	114	195	Off Idle	61.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.63	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:3	35.45	2561	1.66	13.52	114	195	Off Idle	62.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.64	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:06:3	35.45	2560	1.64	13.5	114	195	Off Idle	62.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.66	14.74	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:06:4	35.45	2560	1.63	13.49	114	196	Off Idle	62.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.69	14.71	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:4	35.45	2555	1.62	13.48	114	196	Off Idle	62.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.71	14.68	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:4	35.45	2557	1.61	13.52	114	196	Off Idle	62.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.77	14.68	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:4	35.45	2557	1.6	13.52	114	196	Off Idle	62.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.86	14.65	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:4	35.45	2572	1.58	13.53	114	196	Off Idle	62.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.88	14.63	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:4	35.45	2573	1.57	13.53	114	196	Off Idle	62.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.94	14.62	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:4	35.45	2580	1.57	13.52	114	196	Off Idle	63	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.95	14.62	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:5	35.45	2580	1.55	13.52	114	196	Off Idle	63	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.94	14.61	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:5	35.45	2606	1.54	13.51	114	196	Off Idle	62.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.95	14.63	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:5	35.45	2594	1.53	13.51	114	195	Off Idle	62.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.98	14.65	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:5	35.45	2591	1.53	13.51	114	195	Off Idle	62.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.98	14.67	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:5	35.45	2578	1.52	13.51	114	196	Off Idle	62.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.03	14.69	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:5	35.45	2586	1.51	13.5	114	196	Off Idle	62.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.06	14.71	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:6	35.45	2582	1.51	13.52	114	196	Off Idle	62.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.07	14.73	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:6	35.45	2581	1.5	13.52	114	196	Off Idle	62.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.09	14.76	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:6	35.45	2581	1.5	13.52	114	196	Off Idle	62.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.13	14.8	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:6	35.45	2569	1.49	13.53	114	195	Off Idle	62.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.15	14.82	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:06:6	35.45	2563	1.48	13.52	114	195	Full Load	62.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.16	14.86	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:06:6	35.45	2563	1.47	13.51	114	195	Idle	62.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.22	14.9	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:06:6	35.45	2560	1.46	13.51	114	196	Idle	62.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.27	14.93	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:06:7	35.45	2557	1.44	13.51	114	196	Idle	62.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.29	14.96	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:06:7	35.45	2548	1.44	13.53	114	196	Idle	62.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.31	15	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:06:7	35.45	2538	1.43	13.53	114	196	Idle	62.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.35	15.04	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:06:7	35.45	2538	1.42	13.52	114	196	Idle	61	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.38	15.07	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:06:7	32.72	2490	1.42	13.51	114	196	Idle	59.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.36	15.11	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:06:7	32.72	2484	1.41	13.49	114	195	Idle	58.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.33	15.13	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:06:8	27.27	2484	1.41	13.49	114	195	Idle	55.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.33	15.14	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:06:8	21.81	2471	1.42	13.49	114	196	Idle	54.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.27	15.15	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:06:8	21.81	2492	1.43	13.5	114	196	Idle	53.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.2	15.15	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:8	19.09	2510	1.44	13.5	114	196	Idle	53.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.1	15.16	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:8	19.09	2521	1.44	13.52	114	196	Idle	51.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.05	15.16	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:8	19.09	2515	1.45	13.52	114	196	Idle	51.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.98	15.16	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:9	19.09	2515	1.45	13.51	114	196	Idle	50.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.94	15.14	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:9	19.09	2514	1.46	13.5	114	196	Idle	50.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.89	15.13	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:9	19.09	2545	1.46	13.51	114	196	Idle	50.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.89	15.12	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:9	19.09	2526	1.47	13.51	114	196	Idle	50	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.86	15.09	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:06:9	19.09	2526	1.48	13.51	114	196	Idle	51.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.87	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:9	19.09	2506	1.48	13.51	114	196	Idle	52.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.86	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:06:9	19.09	2523	1.49	13.52	114	196	Idle	54.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.87	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:0	19.09	2512	1.49	13.52	114	196	Idle	55.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.89	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:0	19.09	2515	1.5	13.52	114	196	Idle	58.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.9	15.06	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:0	19.09	2512	1.5	13.51	114	196	Idle	59.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.93	15.05	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:0	19.09	2506	1.5	13.51	114	196	Idle	60.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.93	15.06	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:0	19.09	2500	1.5	13.51	114	196	Idle	61	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.93	15.05	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:0	19.09	2500	1.48	13.5	114	196	Idle	62.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.95	15.06	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:1	19.09	2494	1.48	13.5	114	196	Idle	62.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.94	15.06	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:1	19.09	2486	1.45	13.52	114	196	Idle	63.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.94	15.07	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:1	19.09	2480	1.44	13.51	114	196	Idle	63.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.95	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:1	19.09	2480	1.42	13.49	114	196	Idle	63.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.96	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:1	19.09	2478	1.41	13.5	114	196	Idle	64	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.96	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:1	19.09	2485	1.4	13.49	114	196	Idle	64	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.98	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:1	19.09	2473	1.39	13.49	114	196	Idle	64.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.01	15.08	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:2	19.09	2472	1.38	13.49	114	196	Idle	64.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.03	15.11	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:2	19.09	2472	1.37	13.49	114	196	Idle	64.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.05	15.13	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:2	19.09	2471	1.36	13.5	114	196	Idle	64.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.04	15.14	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:2	19.09	2469	1.36	13.5	114	196	Idle	64.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.04	15.2	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:2	19.09	2469	1.35	13.52	114	196	Idle	64.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.05	15.3	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:2	19.09	2466	1.35	13.53	114	196	Idle	64.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.07	15.41	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:3	19.09	2443	1.34	13.52	114	196	Idle	64.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.08	15.56	1.06	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:3	19.09	2443	1.34	13.52	114	196	Idle	65.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.1	15.74	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:3	19.09	2457	1.33	13.54	114	196	Idle	65.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.11	16.12	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:3	19.09	2450	1.33	13.53	114	196	Idle	65.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.11	16.44	1.12	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:3	19.09	2449	1.33	13.53	114	196	Idle	65.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.08	16.84	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:3	19.09	2448	1.33	13.54	114	196	Idle	65.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.11	17.3	1.18	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:4	19.09	2434	1.33	13.52	114	195	Idle	66.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.1	17.76	1.21	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:4	19.09	2439	1.32	13.52	114	195	Idle	66.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.14	18.43	1.26	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:4	19.09	2417	1.32	13.51	114	195	Idle	66.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.15	18.84	1.28	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:4	17.72	2417	1.32	13.52	114	196	Idle	66.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.15	19.21	1.31	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:4	17.72	2434	1.31	13.53	114	196	Idle	66.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.19	19.54	1.33	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:4	17.72	2434	1.31	13.53	114	196	Idle	66.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.22	19.82	1.35	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:4	17.72	2431	1.31	13.51	114	196	Idle	67	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.21	20.12	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:5	17.72	2428	1.3	13.52	114	196	Idle	67.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.21	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:5	17.72	2426	1.3	13.52	114	196	Idle	67.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.21	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:5	17.72	2425	1.3	13.52	114	196	Idle	67.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.22	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:5	17.72	2422	1.29	13.53	114	196	Idle	67.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.21	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:5	17.72	2399	1.29	13.53	114	196	Idle	67.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.23	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:5	17.72	2416	1.28	13.51	114	196	Idle	68.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.22	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:6	17.72	2414	1.28	13.52	114	196	Idle	68.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.21	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:6	17.72	2416	1.27	13.52	114	196	Idle	68.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.24	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:6	17.72	2405	1.27	13.51	114	196	Idle	68.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:6	17.72	2383	1.26	13.5	114	196	Idle	69	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:6	17.72	2395	1.26	13.51	114	196	Idle	69.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.3	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:6	17.72	2395	1.25	13.51	114	196	Idle	69.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.3	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:6	17.72	2390	1.25	13.52	114	196	Idle	69.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:7	17.72	2388	1.24	13.51	114	196	Idle	69.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:7	17.72	2385	1.24	13.5	114	196	Idle	70	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:7	17.72	2385	1.24	13.51	114	196	Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.32	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:7	17.72	2382	1.23	13.51	114	196	Idle	70.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.32	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:7	17.72	2388	1.23	13.51	114	196	Idle	70.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.31	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:7	17.72	2376	1.22	13.52	114	196	Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.31	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:8	17.72	2376	1.22	13.52	114	196	Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:8	17.72	2357	1.22	13.51	114	196	Idle	70.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:8	17.72	2374	1.21	13.51	114	196	Idle	70.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:8	17.72	2369	1.21	13.52	114	196	Idle	70.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.3	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:07:8	17.72	2369	1.21	13.52	114	196	Idle	70.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.31	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:8	17.72	2366	1.2	13.53	114	196	Idle	70.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.32	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:9	17.72	2379	1.2	13.51	114	196	Idle	70.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:9	17.72	2357	1.2	13.51	114	196	Idle	71	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:9	17.72	2347	1.2	13.52	114	196	Idle	71.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:9	17.72	2353	1.19	13.51	114	196	Idle	71.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:9	17.72	2350	1.19	13.5	114	196	Idle	71.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:9	17.72	2347	1.19	13.5	114	196	Idle	71.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:07:9	17.72	2347	1.19	13.5	114	196	Idle	71.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:0	17.72	2342	1.18	13.51	114	195	Idle	71.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:0	17.72	2347	1.18	13.52	114	195	Idle	71.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:0	17.72	2335	1.18	13.52	114	195	Idle	72.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:0	17.72	2335	1.18	13.52	114	196	Idle	72.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:0	17.72	2324	1.17	13.52	114	196	Idle	72.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:0	17.72	2332	1.17	13.52	114	196	Idle	72.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:1	17.72	2329	1.17	13.51	114	196	Idle	72.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:1	17.72	2320	1.17	13.52	114	196	Idle	72.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:1	17.72	2326	1.16	13.52	114	196	Idle	72.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.34	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:1	17.72	2358	1.16	13.52	114	196	Idle	72.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:1	17.72	2318	1.16	13.53	114	196	Idle	73.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:1	17.72	2318	1.15	13.52	114	196	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:1	17.72	2296	1.15	13.5	114	196	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:2	17.72	2310	1.14	13.52	114	196	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:2	17.72	2305	1.14	13.51	114	196	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:2	17.72	2305	1.14	13.51	114	196	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:2	17.72	2311	1.14	13.51	114	196	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:2	17.72	2297	1.13	13.51	114	196	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:2	17.72	2287	1.13	13.5	114	196	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:3	17.72	2293	1.13	13.49	114	196	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:3	17.72	2288	1.12	13.49	114	196	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:3	17.72	2284	1.12	13.5	114	196	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:3	17.72	2284	1.12	13.51	114	196	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:3	17.72	2279	1.11	13.53	114	196	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:3	17.72	2266	1.11	13.52	114	196	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:4	17.72	2272	1.11	13.54	114	196	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:4	17.72	2271	1.11	13.52	114	196	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:4	17.72	2270	1.1	13.51	114	196	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:4	17.72	2269	1.1	13.49	114	196	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:4	17.72	2266	1.1	13.49	114	196	Idle	76.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:4	17.72	2264	1.09	13.5	114	196	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:4	17.72	2261	1.09	13.52	114	196	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:5	17.72	2259	1.09	13.53	114	196	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:5	17.72	2256	1.09	13.55	114	196	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:5	17.72	2253	1.09	13.54	114	196	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:5	17.72	2252	1.08	13.53	114	196	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:5	17.72	2232	1.08	13.51	114	196	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:5	17.72	2244	1.08	13.51	114	196	Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:6	17.72	2243	1.08	13.49	114	196	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:6	17.72	2241	1.08	13.51	114	196	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:6	17.72	2241	1.07	13.51	114	196	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:6	17.72	2254	1.07	13.51	114	196	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:6	17.72	2236	1.07	13.52	114	196	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:6	17.72	2216	1.06	13.54	114	196	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:6	17.72	2223	1.06	13.54	114	196	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:7	17.72	2247	1.06	13.53	114	196	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:7	17.72	2227	1.06	13.54	114	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:7	17.72	2227	1.06	13.54	114	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:7	17.72	2222	1.05	13.51	114	196	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:08:7	17.72	2220	1.05	13.51	114	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:7	17.72	2215	1.05	13.51	114	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:8	17.72	2212	1.05	13.51	114	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:8	17.72	2210	1.05	13.52	114	196	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:8	17.72	2204	1.05	13.51	114	196	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:8	17.72	2201	1.04	13.51	114	196	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:8	17.72	2201	1.04	13.5	114	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:8	17.72	2198	1.04	13.5	114	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:9	17.72	2194	1.04	13.5	114	196	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:9	17.72	2175	1.03	13.51	114	195	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:9	17.72	2175	1.03	13.52	114	195	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:9	17.72	2196	1.03	13.53	114	195	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:9	17.72	2183	1.03	13.52	114	196	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:9	17.72	2181	1.03	13.51	114	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:08:9	17.72	2160	1.03	13.52	114	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:0	17.72	2182	1.02	13.51	114	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:0	17.72	2172	1.02	13.48	114	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:0	17.72	2172	1.02	13.49	114	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:0	17.72	2161	1.02	13.5	114	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:0	17.72	2168	1.02	13.49	114	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:0	17.72	2183	1.01	13.51	114	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:1	17.72	2162	1.01	13.53	114	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:1	17.72	2162	1.01	13.53	114	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:1	17.72	2150	1.01	13.51	114	196	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:1	17.72	2171	1	13.5	114	196	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:1	17.72	2153	1	13.5	114	196	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:1	17.72	2152	1	13.49	114	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:1	17.72	2114	1	13.49	114	196	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:2	17.72	2129	1	13.49	114	196	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:2	17.72	2175	0.99	13.48	114	196	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:2	17.72	2139	0.99	13.48	114	196	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:2	17.72	2103	0.99	13.49	114	196	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:2	17.72	2103	0.99	13.49	114	196	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:2	17.72	2148	0.99	13.52	114	196	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:3	17.72	2128	0.99	13.52	114	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:3	17.72	2126	0.99	13.52	114	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:3	17.72	2091	0.99	13.52	114	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:3	17.72	2120	0.98	13.51	114	196	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:3	17.72	2116	0.98	13.49	114	196	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:3	17.72	2116	0.98	13.48	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:4	17.72	2114	0.98	13.48	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:4	17.72	2111	0.98	13.48	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:4	17.72	2108	0.98	13.5	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:4	17.72	2107	0.98	13.5	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:4	17.72	2103	0.97	13.5	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:4	17.72	2106	0.97	13.5	114	196	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:4	17.72	2095	0.97	13.5	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:5	17.72	2095	0.97	13.5	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:5	17.72	2084	0.97	13.5	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:5	17.72	2097	0.97	13.51	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:5	17.72	2086	0.97	13.52	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:5	17.72	2084	0.97	13.51	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:5	17.72	2075	0.97	13.49	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:6	17.72	2079	0.96	13.5	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:6	17.72	2078	0.96	13.49	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:6	17.72	2076	0.96	13.51	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:6	17.72	2074	0.96	13.53	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:6	17.72	2086	0.96	13.53	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:09:6	17.72	2068	0.96	13.52	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:6	17.72	2057	0.96	13.52	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:7	17.72	2062	0.96	13.52	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:7	17.72	2062	0.96	13.52	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:7	17.72	2050	0.96	13.53	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:7	17.72	2054	0.96	13.53	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:7	17.72	2069	0.96	13.53	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:7	17.72	2060	0.96	13.51	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:8	17.72	2033	0.96	13.51	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:8	17.72	2048	0.96	13.51	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:8	17.72	2043	0.96	13.5	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:8	17.72	2043	0.96	13.48	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:8	17.72	2046	0.96	13.49	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:8	17.72	2034	0.96	13.49	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:9	17.72	2033	0.96	13.5	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:9	17.72	2033	0.96	13.51	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:9	17.72	2020	0.96	13.52	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:9	17.72	2023	0.96	13.53	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:9	17.72	2022	0.96	13.52	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:9	17.72	2020	0.96	13.51	114	196	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:09:9	17.72	2034	0.96	13.5	114	196	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:0	17.72	2017	0.96	13.5	114	196	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:0	17.72	2008	0.96	13.51	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:0	17.72	2012	0.96	13.51	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:0	17.72	2008	0.96	13.53	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:0	17.72	2007	0.96	13.53	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:0	17.72	2003	0.96	13.53	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:1	17.72	2006	0.96	13.52	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:1	17.72	1994	0.96	13.52	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:1	17.72	1994	0.96	13.51	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:1	17.72	1982	0.96	13.5	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:1	17.72	1987	0.96	13.49	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:1	17.72	1984	0.96	13.5	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:1	17.72	1992	0.96	13.51	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.07	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:2	17.72	1980	0.96	13.52	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.08	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:2	17.72	1978	0.96	13.51	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.08	1.37	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:2	17.72	1969	0.96	13.51	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.09	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:2	17.72	1975	0.96	13.51	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.09	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:2	17.72	1971	0.96	13.5	114	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.09	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:2	17.72	1970	0.96	13.51	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.09	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:3	17.72	1968	0.96	13.51	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.09	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:3	17.72	1966	0.96	13.5	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.09	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:3	17.72	1962	0.96	13.5	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.09	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:3	17.72	1961	0.96	13.5	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.09	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:3	17.72	1958	0.96	13.5	114	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:3	17.72	1955	0.96	13.5	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:4	17.72	1951	0.96	13.5	114	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:4	17.72	1951	0.96	13.5	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:4	17.72	1948	0.96	13.49	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:4	17.72	1947	0.96	13.51	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:4	17.72	1941	0.96	13.51	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:4	17.72	1941	0.96	13.51	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:4	17.72	1937	0.96	13.52	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:5	17.72	1935	0.96	13.51	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:5	17.72	1934	0.96	13.52	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:5	17.72	1930	0.96	13.53	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:5	17.72	1919	0.96	13.53	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:5	17.72	1911	0.96	13.54	114	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:10:5	17.72	1920	0.96	13.53	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:6	17.72	1920	0.96	13.52	114	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:6	17.72	1920	0.96	13.51	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:6	17.72	1918	0.96	13.51	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:6	17.72	1917	0.96	13.51	114	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:6	17.72	1917	0.96	13.52	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:6	17.72	1913	0.96	13.53	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:6	17.72	1925	0.96	13.54	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:7	17.72	1925	0.96	13.53	113	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:7	17.72	1904	0.96	13.53	113	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:7	17.72	1898	0.96	13.52	113	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:7	17.72	1895	0.96	13.52	113	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:7	17.72	1895	0.96	13.52	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:7	17.72	1888	0.96	13.52	114	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:8	17.72	1887	0.96	13.51	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:8	17.72	1887	0.96	13.52	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:8	17.72	1884	0.96	13.5	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:8	17.72	1884	0.96	13.51	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:8	17.72	1879	0.96	13.53	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:8	17.72	1875	0.96	13.53	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:9	17.72	1875	0.96	13.51	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:9	17.72	1875	0.96	13.53	114	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:9	17.72	1879	0.96	13.53	114	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:9	17.72	1879	0.96	13.52	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:9	17.72	1867	0.96	13.52	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:9	17.72	1858	0.96	13.53	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:10:9	17.72	1860	0.96	13.52	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:0	17.72	1857	0.96	13.52	114	196	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:0	17.72	1857	0.96	13.5	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:0	17.72	1852	0.96	13.5	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:0	17.72	1850	0.96	13.5	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.25	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:0	17.72	1845	0.96	13.51	114	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:0	17.72	1845	0.96	13.52	114	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:1	17.72	1840	0.96	13.51	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:1	17.72	1838	0.97	13.51	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:1	17.72	1834	0.97	13.5	114	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:1	17.72	1834	0.97	13.5	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:1	17.72	1832	0.97	13.51	114	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:1	17.72	1830	0.97	13.5	114	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:1	17.72	1829	0.97	13.5	114	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:2	17.72	1826	0.97	13.5	114	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:2	17.72	1823	0.97	13.51	114	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:2	17.72	1819	0.97	13.51	114	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:2	17.72	1818	0.97	13.52	114	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:2	17.72	1814	0.97	13.53	114	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:2	17.72	1812	0.97	13.53	114	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:3	17.72	1809	0.97	13.51	114	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:3	17.72	1808	0.96	13.51	114	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:3	17.72	1805	0.96	13.52	114	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:3	17.72	1802	0.96	13.51	114	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:3	17.72	1802	0.96	13.49	114	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.25	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:3	17.72	1800	0.96	13.5	114	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.25	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:4	17.72	1800	0.96	13.51	114	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.26	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:4	17.72	1796	0.96	13.51	114	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.26	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:4	17.72	1796	0.96	13.51	114	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.26	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:4	17.72	1792	0.96	13.51	114	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.25	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:4	17.72	1789	0.96	13.51	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.25	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:4	17.72	1789	0.96	13.51	114	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:11:4	17.72	1787	0.96	13.51	114	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:5	17.72	1784	0.96	13.52	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:5	17.72	1783	0.96	13.5	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:5	17.72	1779	0.96	13.51	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:5	17.72	1762	0.96	13.51	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:5	17.72	1772	0.96	13.5	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:5	17.72	1770	0.97	13.5	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:6	17.72	1768	0.97	13.51	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:6	17.72	1778	0.97	13.51	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.25	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:6	17.72	1762	0.97	13.51	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:6	17.72	1762	0.97	13.52	114	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:6	17.72	1754	0.97	13.51	114	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:6	17.72	1758	0.97	13.51	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:6	17.72	1754	0.98	13.51	114	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:7	17.72	1754	0.98	13.5	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:7	17.72	1754	0.98	13.51	114	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:7	17.72	1752	0.98	13.52	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:7	17.72	1750	0.98	13.53	114	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:7	17.72	1745	0.98	13.53	114	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:7	17.72	1741	0.98	13.53	114	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:8	17.72	1736	0.99	13.52	114	196	Full Load	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:8	17.72	1736	0.99	13.5	114	196	Off Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:11:8	17.72	1732	0.99	13.48	114	196	Off Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.24	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:11:8	17.72	1684	0.99	13.48	114	196	Off Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.25	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:11:8	8.18	1735	0.99	13.48	114	196	Off Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.25	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:11:8	8.18	1734	1	13.48	114	196	Off Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.25	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:11:9	10.9	1734	1	13.49	114	196	Off Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.25	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:11:9	10.9	1731	1	13.5	114	196	Off Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.25	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:11:9	13.63	1743	1.01	13.5	114	196	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.25	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:11:9	13.63	1736	1.01	13.5	114	196	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.24	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:11:9	16.36	1727	1.02	13.51	114	196	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.24	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:11:9	16.36	1727	1.03	13.51	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:11:9	19.09	1725	1.04	13.49	114	196	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:12:0	19.09	1724	1.04	13.5	114	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:12:0	21.81	1723	1.05	13.51	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:12:0	21.81	1725	1.06	13.49	114	196	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:12:0	21.81	1725	1.07	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:12:0	24.54	1712	1.08	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:12:0	24.54	1731	1.1	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:12:1	27.27	1731	1.11	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:12:1	27.27	1730	1.12	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:12:1	29.99	1734	1.13	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:12:1	29.99	1729	1.14	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:1	31.36	1715	1.15	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:1	31.36	1718	1.16	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:12:1	31.36	1720	1.17	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:12:2	31.36	1720	1.17	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.21	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:12:2	31.36	1727	1.18	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:2	31.36	1720	1.18	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:2	31.36	1715	1.19	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:2	31.36	1715	1.2	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:2	31.36	1712	1.21	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:3	31.36	1709	1.21	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	20.23	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:3	31.36	1709	1.21	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:3	31.36	1710	1.22	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	20.21	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:3	31.36	1710	1.22	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.48	20.21	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:3	31.36	1710	1.23	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.21	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:12:3	31.36	1710	1.23	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:12:4	31.36	1706	1.24	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	20.21	1.38	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:12:4	31.36	1704	1.25	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.37	20.2	1.38	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:12:4	31.36	1703	1.25	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	20.21	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:12:4	31.36	1702	1.26	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.27	20.21	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:12:4	31.36	1702	1.27	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.23	20.22	1.38	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:4	29.99	1688	1.27	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.21	20.22	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:4	29.99	1697	1.28	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.18	20.23	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:5	29.99	1697	1.29	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.23	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:5	29.99	1689	1.29	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	20.23	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:12:5	29.99	1686	1.3	13.48	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	20.23	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:12:5	29.99	1685	1.3	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.04	20.24	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:12:5	29.99	1673	1.31	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.99	20.24	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:5	29.99	1673	1.32	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.99	20.24	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:6	29.99	1672	1.32	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.97	20.24	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:6	29.99	1675	1.33	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.96	20.23	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:6	29.99	1673	1.33	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.94	20.23	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:6	29.99	1670	1.33	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.9	20.23	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:6	29.99	1668	1.34	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.86	20.23	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:6	29.99	1674	1.34	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.83	20.23	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:6	29.99	1674	1.35	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.74	20.23	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:7	29.99	1678	1.35	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.72	20.22	1.38	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:12:7	29.99	1678	1.36	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.69	20.14	1.37	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:12:7	29.99	1692	1.37	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.54	19.94	1.36	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:7	29.99	1694	1.38	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.49	19.76	1.35	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:12:7	29.99	1693	1.39	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.44	19.55	1.33	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:12:7	29.99	1690	1.4	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.38	19.33	1.32	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:12:8	29.99	1690	1.41	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.32	19.07	1.3	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:12:8	29.99	1691	1.42	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.25	18.8	1.28	3.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:12:8	29.99	1687	1.43	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.19	18.5	1.26	3.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:12:8	29.99	1687	1.44	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.13	18.19	1.24	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:12:8	29.99	1687	1.45	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.11	17.91	1.22	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:12:8	29.99	1687	1.46	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.08	17.67	1.2	3.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:12:9	29.99	1687	1.47	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.04	17.45	1.19	3.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:12:9	29.99	1686	1.48	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8	17.27	1.18	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:12:9	29.99	1682	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.99	17.1	1.16	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:12:9	29.99	1683	1.5	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.97	16.88	1.15	3.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:12:9	29.99	1683	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.93	16.74	1.14	3.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:12:9	29.99	1684	1.52	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.91	16.62	1.13	3.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:12:9	29.99	1681	1.53	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.87	16.45	1.12	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:0	29.99	1681	1.53	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.85	16.4	1.12	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:0	29.99	1681	1.53	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.84	16.29	1.11	3.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:13:0	28.63	1676	1.53	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.82	16.18	1.1	3.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:13:0	28.63	1677	1.53	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.8	16.05	1.09	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:0	28.63	1685	1.53	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.79	15.95	1.09	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:0	28.63	1685	1.53	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.79	15.86	1.08	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:1	28.63	1686	1.53	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.79	15.79	1.08	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:1	28.63	1686	1.53	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.79	15.72	1.07	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:1	28.63	1679	1.53	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.77	15.65	1.07	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:1	28.63	1679	1.53	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.77	15.59	1.06	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:1	28.63	1682	1.53	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.74	15.56	1.06	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:1	29.99	1701	1.53	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	15.52	1.06	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:1	29.99	1689	1.53	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15.47	1.05	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:2	29.99	1688	1.53	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.43	1.05	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:2	29.99	1688	1.53	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.39	1.05	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:2	29.99	1691	1.53	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.35	1.05	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:2	29.99	1692	1.53	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	15.32	1.04	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:2	29.99	1692	1.52	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15.3	1.04	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:2	29.99	1692	1.52	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15.29	1.04	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:13:3	29.99	1694	1.52	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.77	15.21	1.04	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:3	29.99	1696	1.52	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	15.15	1.03	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:3	29.99	1693	1.52	13.47	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.09	1.03	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:3	29.99	1693	1.52	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.03	1.02	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:3	29.99	1689	1.52	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.76	14.98	1.02	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:3	29.99	1692	1.52	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.76	14.92	1.02	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:4	29.99	1692	1.52	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	14.9	1.02	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:4	29.99	1691	1.52	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.77	14.83	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:4	29.99	1691	1.52	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.78	14.77	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:4	29.99	1693	1.52	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	14.7	1	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:4	29.99	1694	1.52	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	14.69	1	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:4	29.99	1696	1.52	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.68	1	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:4	29.99	1688	1.52	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	14.67	1	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:5	29.99	1700	1.52	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.67	1	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:5	29.99	1697	1.51	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.81	14.66	1	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:5	29.99	1697	1.51	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	14.66	1	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:13:5	29.99	1699	1.51	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	14.64	1	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:5	29.99	1700	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.64	1	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:6	29.99	1708	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.83	14.66	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:6	29.99	1708	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.85	14.67	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:6	29.99	1707	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.86	14.68	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:6	29.99	1706	1.51	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.87	14.69	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:6	29.99	1707	1.51	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.89	14.7	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:6	29.99	1707	1.51	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.89	14.7	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:6	29.99	1708	1.51	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.91	14.71	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:6	29.99	1706	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.93	14.74	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:7	29.99	1704	1.51	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.93	14.74	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:7	29.99	1704	1.51	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.92	14.76	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:7	29.99	1704	1.51	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.94	14.77	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:7	29.99	1702	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.91	14.79	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:7	29.99	1700	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.9	14.81	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:7	29.99	1700	1.51	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.89	14.82	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:8	29.99	1702	1.51	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.89	14.83	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:8	29.99	1701	1.51	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.88	14.82	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:8	29.99	1706	1.51	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.89	14.82	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:8	29.99	1706	1.51	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.91	14.82	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:8	29.99	1706	1.51	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.92	14.82	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:8	29.99	1718	1.51	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.95	14.82	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:9	29.99	1719	1.51	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-7.93	14.82	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:9	29.99	1719	1.51	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-7.93	14.84	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:9	29.99	1721	1.51	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-7.92	14.9	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:9	29.99	1725	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-7.93	14.93	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:13:9	29.99	1725	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.92	14.94	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:13:9	29.99	1725	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.92	14.96	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:13:9	29.99	1725	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.97	14.95	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:0	29.99	1724	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.95	14.95	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:0	29.99	1718	1.51	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.96	14.95	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:0	29.99	1715	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.01	14.93	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:0	29.99	1715	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.98	14.91	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:0	29.99	1714	1.51	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.94	14.88	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:0	29.99	1715	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.95	14.83	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:1	29.99	1714	1.51	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.93	14.78	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:1	29.99	1713	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.92	14.75	1	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:1	29.99	1716	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.95	14.73	1	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:1	29.99	1720	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.95	14.71	1	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:1	29.99	1720	1.51	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.93	14.7	1	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:1	29.99	1720	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.97	14.67	1	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:1	29.99	1725	1.51	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.97	14.65	1	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:14:2	29.99	1725	1.51	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.94	14.62	1	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:2	29.99	1729	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.97	14.58	0.99	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:2	29.99	1729	1.51	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8	14.57	0.99	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:2	29.99	1729	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.96	14.55	0.99	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:2	29.99	1728	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.99	14.52	0.99	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:2	29.99	1729	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8	14.5	0.99	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:3	29.99	1726	1.51	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8	14.49	0.99	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:3	29.99	1718	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8	14.46	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:3	29.99	1718	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.01	14.44	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:3	29.99	1720	1.51	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8	14.42	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:3	29.99	1722	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8	14.4	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:3	29.99	1723	1.51	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8	14.39	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:4	29.99	1723	1.51	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.04	14.39	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:4	29.99	1726	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.01	14.38	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:4	29.99	1732	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.02	14.38	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:4	29.99	1733	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.05	14.38	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:4	29.99	1733	1.5	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.07	14.38	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:4	29.99	1734	1.5	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.1	14.39	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:4	29.99	1739	1.5	13.53	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.1	14.4	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:5	29.99	1740	1.5	13.53	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.12	14.4	0.98	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:5	29.99	1740	1.5	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.13	14.41	0.98	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:5	29.99	1740	1.5	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.14	14.42	0.98	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:5	29.99	1740	1.5	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.15	14.43	0.98	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:5	29.99	1738	1.5	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.17	14.43	0.98	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:5	29.99	1731	1.5	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.13	14.43	0.98	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:6	29.99	1731	1.5	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.13	14.44	0.98	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:6	29.99	1728	1.49	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.17	14.44	0.98	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:6	29.99	1726	1.49	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.14	14.45	0.98	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:6	29.99	1725	1.49	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.12	14.46	0.99	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:6	29.99	1720	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.16	14.49	0.99	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:6	29.99	1720	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.14	14.5	0.99	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:6	29.99	1724	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.16	14.51	0.99	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:7	29.99	1727	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.16	14.53	0.99	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:7	29.99	1727	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.17	14.57	0.99	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:7	29.99	1730	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.19	14.59	0.99	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:7	29.99	1738	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.17	14.62	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:7	29.99	1741	1.49	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.17	14.64	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:7	29.99	1742	1.49	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.17	14.67	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:8	29.99	1742	1.49	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.13	14.68	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:8	29.99	1742	1.49	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.13	14.68	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:8	29.99	1741	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.15	14.69	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:8	29.99	1737	1.49	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.1	14.7	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:8	29.99	1729	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.12	14.7	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:8	29.99	1722	1.49	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.11	14.71	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:9	29.99	1721	1.49	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.12	14.72	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:9	29.99	1720	1.49	13.48	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.13	14.71	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:9	29.99	1720	1.49	13.48	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.12	14.73	1	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:9	29.99	1727	1.49	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.14	14.74	1	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:14:9	29.99	1727	1.49	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.11	14.75	1	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:9	29.99	1734	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.13	14.77	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:14:9	29.99	1738	1.49	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.14	14.78	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:0	29.99	1740	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.13	14.79	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:0	29.99	1742	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.14	14.79	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:0	29.99	1747	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.16	14.8	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:0	29.99	1759	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.16	14.82	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:0	29.99	1744	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.16	14.84	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:0	29.99	1744	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.19	14.87	1.01	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:1	31.36	1746	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.17	14.9	1.02	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:15:1	31.36	1733	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.18	14.94	1.02	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:1	31.36	1730	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.18	14.97	1.02	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:1	31.36	1731	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.2	15.03	1.02	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:1	31.36	1731	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.21	15.07	1.03	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:1	31.36	1734	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.21	15.11	1.03	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:1	31.36	1734	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.21	15.14	1.03	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:2	31.36	1736	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.2	15.2	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:2	31.36	1740	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.2	15.22	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:2	31.36	1740	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.19	15.23	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:2	29.99	1741	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.19	15.28	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:2	29.99	1741	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.21	15.31	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:2	29.99	1742	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.21	15.31	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:3	29.99	1742	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.21	15.33	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:3	29.99	1742	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.23	15.35	1.05	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:3	29.99	1738	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.23	15.37	1.05	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:3	29.99	1738	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.21	15.34	1.05	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:3	29.99	1733	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.2	15.34	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:3	29.99	1732	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.22	15.32	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:4	29.99	1730	1.49	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.21	15.31	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:4	29.99	1723	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.21	15.29	1.04	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:4	29.99	1724	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.21	15.27	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:4	29.99	1720	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.19	15.25	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:4	29.99	1723	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.17	15.23	1.04	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:4	29.99	1732	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.18	15.19	1.04	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:4	29.99	1735	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.18	15.18	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:5	29.99	1735	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.2	15.15	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:5	29.99	1738	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.21	15.14	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:5	29.99	1740	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.19	15.11	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:5	29.99	1740	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.2	15.1	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:5	29.99	1740	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.21	15.09	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:5	29.99	1741	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.21	15.08	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:6	29.99	1739	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.21	15.07	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:6	29.99	1736	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.21	15.09	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:6	29.99	1734	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.18	15.1	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:6	31.36	1741	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.19	15.08	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:6	31.36	1740	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.21	15.05	1.03	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:6	31.36	1731	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.19	15.02	1.02	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:6	31.36	1734	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.2	15	1.02	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:7	31.36	1734	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.21	14.97	1.02	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:7	31.36	1738	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.21	14.95	1.02	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:7	31.36	1734	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.22	14.9	1.02	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:7	31.36	1733	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.24	14.87	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:7	31.36	1734	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.24	14.85	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:7	29.99	1728	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.21	14.84	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:8	29.99	1734	1.49	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.21	14.84	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:8	29.99	1740	1.49	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.2	14.83	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:8	29.99	1737	1.49	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.18	14.82	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:8	29.99	1737	1.49	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.17	14.83	1.01	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:15:8	29.99	1738	1.49	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.17	14.83	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:8	29.99	1737	1.49	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.18	14.83	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:9	29.99	1736	1.49	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.2	14.82	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:9	29.99	1737	1.49	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.19	14.82	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:9	29.99	1737	1.49	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.2	14.82	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:9	29.99	1738	1.49	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.2	14.82	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:9	29.99	1737	1.49	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.21	14.83	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:9	29.99	1737	1.49	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.21	14.84	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:15:9	29.99	1738	1.49	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.21	14.84	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:0	29.99	1735	1.49	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.19	14.83	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:16:0	29.99	1732	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.18	14.82	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:0	29.99	1734	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.13	14.82	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:0	29.99	1735	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.13	14.81	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:0	29.99	1736	1.49	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.11	14.81	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:0	29.99	1736	1.49	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.15	14.82	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:1	29.99	1735	1.5	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.12	14.85	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:1	29.99	1741	1.5	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.14	14.86	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:1	29.99	1746	1.5	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.13	14.89	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:1	29.99	1749	1.5	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.1	14.92	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:1	29.99	1749	1.5	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.1	14.95	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:1	29.99	1750	1.5	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.11	14.98	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:1	31.36	1766	1.5	13.53	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.1	15.01	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:2	31.36	1759	1.5	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.11	15.06	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:2	31.36	1748	1.5	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.11	15.09	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:2	31.36	1746	1.51	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.11	15.11	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:2	31.36	1744	1.51	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.13	15.14	1.03	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:2	31.36	1744	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.12	15.15	1.03	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:2	31.36	1746	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.12	15.16	1.03	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:3	31.36	1746	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.12	15.16	1.03	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:3	31.36	1727	1.51	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.1	15.17	1.03	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:3	29.99	1727	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.09	15.17	1.03	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:3	29.99	1737	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.08	15.17	1.03	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:3	29.99	1723	1.51	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.09	15.16	1.03	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:3	29.99	1738	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.12	15.15	1.03	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:4	29.99	1740	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.1	15.12	1.03	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:4	29.99	1740	1.51	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.09	15.09	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:4	29.99	1748	1.51	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.09	15.07	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:4	29.99	1748	1.51	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.09	15.08	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:4	29.99	1748	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.1	15.09	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:4	29.99	1751	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.1	15.07	1.03	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:4	29.99	1749	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.11	15.04	1.02	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:5	29.99	1744	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.11	15.02	1.02	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:5	29.99	1744	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.1	14.98	1.02	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:5	29.99	1744	1.51	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.11	14.97	1.02	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:5	29.99	1755	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.11	14.94	1.02	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:5	29.99	1741	1.51	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.09	14.93	1.02	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:6	29.99	1742	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.07	14.88	1.01	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:6	29.99	1745	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.07	14.81	1.01	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:6	29.99	1743	1.51	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.07	14.79	1.01	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:6	29.99	1741	1.51	13.49	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.07	14.79	1.01	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:6	29.99	1741	1.51	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.1	14.76	1.01	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:6	29.99	1745	1.51	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.09	14.75	1	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:6	29.99	1750	1.51	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.09	14.73	1	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:6	29.99	1750	1.51	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.09	14.73	1	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:7	29.99	1748	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.08	14.75	1	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:7	29.99	1748	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.08	14.76	1.01	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:7	29.99	1738	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.11	14.77	1.01	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:08:16:7	29.99	1730	1.51	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.1	14.78	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:7	29.99	1736	1.51	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.1	14.8	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:7	29.99	1744	1.51	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.11	14.81	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:8	29.99	1747	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.1	14.84	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:8	29.99	1747	1.51	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.09	14.85	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:8	29.99	1748	1.51	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.11	14.85	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:8	29.99	1751	1.51	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.12	14.85	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:8	29.99	1754	1.51	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.1	14.85	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:8	29.99	1754	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.1	14.84	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:9	29.99	1754	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.1	14.82	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:9	29.99	1754	1.51	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.1	14.81	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:16:9	29.99	1754	1.51	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.1	14.82	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:9	29.99	1754	1.51	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.09	14.83	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:9	29.99	1750	1.51	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.1	14.85	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:9	29.99	1744	1.51	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.11	14.87	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:16:9	29.99	1740	1.51	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.12	14.89	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:0	31.36	1746	1.51	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.1	14.92	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:0	31.36	1736	1.51	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.1	14.95	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:0	31.36	1737	1.51	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.1	15	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:0	31.36	1737	1.51	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.07	15.02	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:0	31.36	1743	1.51	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.07	15.06	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:0	31.36	1753	1.51	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.08	15.08	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:1	31.36	1755	1.52	13.48	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.1	15.11	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:1	31.36	1761	1.52	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.06	15.13	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:1	31.36	1761	1.52	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.05	15.15	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:1	31.36	1762	1.52	13.53	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.01	15.17	1.03	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:1	31.36	1766	1.52	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.96	15.19	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:1	31.36	1758	1.53	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.96	15.2	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:1	31.36	1758	1.53	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.94	15.21	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:2	31.36	1757	1.53	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.95	15.22	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:2	31.36	1751	1.53	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.98	15.21	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:2	31.36	1748	1.54	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.97	15.21	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:2	31.36	1748	1.54	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.96	15.19	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:2	29.99	1744	1.54	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.96	15.16	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:2	29.99	1744	1.55	13.53	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.95	15.15	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:3	29.99	1744	1.55	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.92	15.11	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:3	29.99	1749	1.55	13.55	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.91	15.09	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:3	29.99	1753	1.56	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.92	15.05	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:3	29.99	1758	1.56	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.89	15.02	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:3	29.99	1759	1.56	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.87	15.01	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:3	29.99	1760	1.57	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.87	15	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:4	29.99	1761	1.57	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.84	14.99	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:4	29.99	1761	1.57	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.84	14.99	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:4	29.99	1760	1.58	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	14.98	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:4	29.99	1758	1.58	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	14.98	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:4	29.99	1758	1.59	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	14.99	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:4	29.99	1760	1.59	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.01	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:4	29.99	1760	1.59	13.53	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	15.01	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:5	29.99	1758	1.6	13.52	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:5	29.99	1757	1.6	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.98	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:5	29.99	1757	1.6	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.97	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:5	29.99	1757	1.6	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.97	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:5	29.99	1758	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.95	1.02	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:17:5	29.99	1759	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	14.95	1.02	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:17:6	29.99	1766	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	14.91	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:6	29.99	1766	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.62	14.9	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:6	29.99	1764	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.6	14.89	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:6	29.99	1765	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	14.87	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:6	29.99	1768	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	14.86	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:6	29.99	1778	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.66	14.85	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:6	29.99	1771	1.62	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	14.82	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:7	29.99	1767	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	14.81	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:7	29.99	1766	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	14.8	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:7	29.99	1770	1.62	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	14.76	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:7	29.99	1770	1.62	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	14.76	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:7	29.99	1767	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	14.73	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:7	29.99	1766	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	14.72	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:8	29.99	1766	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	14.73	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:8	29.99	1766	1.62	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.73	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:17:8	29.99	1763	1.62	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.75	1	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:8	29.99	1766	1.62	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.76	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:8	29.99	1766	1.62	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	14.76	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:8	29.99	1770	1.62	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.77	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:9	29.99	1772	1.62	13.48	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.62	14.79	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:9	29.99	1772	1.62	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.82	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:17:9	29.99	1774	1.62	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	14.83	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:9	29.99	1781	1.62	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.85	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:9	29.99	1782	1.62	13.49	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.66	14.86	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:9	29.99	1782	1.62	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.62	14.86	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:17:9	29.99	1782	1.62	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.69	14.86	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:0	29.99	1782	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.7	14.87	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:0	29.99	1778	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.69	14.86	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:0	29.99	1778	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.71	14.86	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:0	29.99	1772	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.69	14.86	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:0	29.99	1770	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.86	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:0	29.99	1772	1.61	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.66	14.85	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:1	29.99	1772	1.61	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.67	14.84	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:1	29.99	1771	1.61	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.66	14.83	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:1	29.99	1760	1.61	13.5	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.65	14.82	1.01	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:1	29.99	1777	1.61	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.64	14.82	1.01	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:1	29.99	1778	1.61	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.66	14.83	1.01	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:1	29.99	1795	1.61	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.67	14.84	1.01	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:1	29.99	1784	1.61	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	14.87	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:2	29.99	1784	1.61	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	14.88	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:2	29.99	1784	1.61	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	14.91	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:2	29.99	1787	1.61	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.93	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:2	29.99	1787	1.61	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.67	14.94	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:2	29.99	1789	1.61	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.99	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:2	29.99	1790	1.61	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	15.01	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:3	29.99	1789	1.61	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	15.02	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:3	29.99	1786	1.61	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	15.03	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:3	29.99	1781	1.61	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	15.04	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:3	29.99	1782	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	15.05	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:3	29.99	1780	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	15.06	1.03	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:3	29.99	1777	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	15.09	1.03	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:4	29.99	1779	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	15.11	1.03	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:4	29.99	1784	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	15.14	1.03	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:4	29.99	1784	1.61	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	15.15	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:4	29.99	1786	1.61	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	15.17	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:4	29.99	1791	1.61	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	15.18	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:4	29.99	1796	1.61	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	15.19	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:4	29.99	1796	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.78	15.19	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:5	29.99	1797	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.77	15.19	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:5	29.99	1797	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.72	15.18	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:5	29.99	1797	1.61	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	15.16	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:5	29.99	1797	1.61	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	15.15	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:5	29.99	1787	1.61	13.5	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	15.12	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:5	29.99	1787	1.61	13.51	114	196	Off Idle	86.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	15.11	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:6	29.99	1787	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.73	15.07	1.03	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:6	29.99	1789	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.71	15.05	1.03	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:18:6	29.99	1789	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.73	15.03	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:6	29.99	1794	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.75	15	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:6	29.99	1794	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.71	14.99	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:6	29.99	1796	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.71	14.98	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:6	29.99	1796	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.69	14.98	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:7	29.99	1797	1.61	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.71	14.97	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:7	29.99	1797	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	14.96	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:18:7	29.99	1800	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.78	14.95	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:7	29.99	1799	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.8	14.96	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:7	29.99	1796	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.83	14.97	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:7	29.99	1798	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.81	14.99	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:8	29.99	1800	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.81	15	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:8	29.99	1795	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.83	14.99	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:8	29.99	1797	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.83	14.98	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:8	29.99	1796	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	14.97	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:8	29.99	1797	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	14.97	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:8	29.99	1797	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	14.96	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:18:9	29.99	1801	1.61	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	14.95	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:18:9	29.99	1803	1.61	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	14.92	1.02	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:18:9	29.99	1805	1.61	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	14.88	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:18:9	29.99	1806	1.61	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	14.86	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:18:9	29.99	1804	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	14.83	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:18:9	29.99	1802	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.82	14.82	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:18:9	29.99	1802	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.82	14.81	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:0	29.99	1802	1.61	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.83	14.8	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:0	29.99	1797	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.8	14.78	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:0	29.99	1791	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.78	14.78	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:0	29.99	1796	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.75	14.78	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:0	29.99	1794	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.75	14.74	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:0	29.99	1794	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.78	14.75	1	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:1	29.99	1792	1.61	13.48	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.79	14.76	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:1	29.99	1795	1.61	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.8	14.76	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:1	29.99	1795	1.61	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.79	14.76	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:1	29.99	1804	1.61	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.78	14.77	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:1	29.99	1806	1.61	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.79	14.76	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:1	29.99	1813	1.61	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.78	14.76	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:1	29.99	1813	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.75	14.77	1.01	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:2	29.99	1816	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.77	14.78	1.01	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:2	29.99	1815	1.61	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	14.82	1.01	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:2	29.99	1812	1.61	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.77	14.84	1.01	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:2	29.99	1812	1.61	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.88	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:2	29.99	1813	1.61	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.78	14.9	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:2	29.99	1810	1.61	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.92	1.02	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:3	29.99	1810	1.61	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.96	1.02	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:3	29.99	1807	1.62	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.73	14.99	1.02	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:3	29.99	1806	1.62	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	15.03	1.02	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:3	29.99	1804	1.62	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.77	15.05	1.02	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:3	29.99	1804	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	15.07	1.03	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:3	29.99	1807	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.73	15.09	1.03	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:4	29.99	1809	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.72	15.11	1.03	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:4	29.99	1810	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	15.14	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:4	29.99	1812	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.68	15.16	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:4	29.99	1814	1.62	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.69	15.19	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:4	29.99	1818	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.69	15.21	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:4	29.99	1817	1.62	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.69	15.23	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:4	29.99	1815	1.62	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.73	15.24	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:5	29.99	1816	1.62	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	15.25	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:5	29.99	1818	1.62	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.79	15.23	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:5	29.99	1816	1.62	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.77	15.21	1.04	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:5	29.99	1816	1.62	13.52	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.76	15.18	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:5	29.99	1812	1.62	13.51	114	196	Off Idle	86.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.7	15.17	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:5	29.99	1816	1.63	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.63	15.17	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:19:6	29.99	1815	1.64	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	15.12	1.03	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:6	29.99	1815	1.65	13.53	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.48	15.08	1.03	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:6	29.99	1812	1.66	13.53	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.4	15.05	1.03	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:19:6	29.99	1813	1.67	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.3	15.01	1.02	3.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:19:6	29.99	1820	1.69	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.13	14.98	1.02	3.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:19:6	29.99	1820	1.71	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.05	14.97	1.02	3.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:19:6	29.99	1823	1.73	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.84	14.95	1.02	3.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:19:7	29.99	1830	1.75	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.66	14.92	1.02	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:19:7	29.99	1833	1.76	13.54	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.52	14.87	1.01	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:19:7	29.99	1836	1.78	13.53	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.35	14.85	1.01	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:19:7	29.99	1846	1.81	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.12	14.84	1.01	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:19:7	29.99	1849	1.83	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.99	14.82	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:7	29.99	1850	1.84	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.96	14.81	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:8	29.99	1851	1.86	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.78	14.8	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:8	29.99	1851	1.88	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.71	14.79	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:8	29.99	1852	1.9	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.63	14.79	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:8	29.99	1852	1.92	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.58	14.79	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:8	29.99	1853	1.94	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.44	14.8	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:8	29.99	1851	1.96	13.5	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.39	14.78	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:9	29.99	1849	1.97	13.52	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.35	14.79	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:9	28.63	1841	1.98	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.32	14.82	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:9	28.63	1836	1.98	13.51	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.29	14.87	1.01	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:19:9	28.63	1835	1.99	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.26	14.89	1.01	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:9	28.63	1837	2	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.26	14.98	1.02	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:9	28.63	1844	2	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.21	15.02	1.02	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:08:19:9	28.63	1846	2	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.2	15.05	1.02	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:08:20:0	28.63	1850	2	13.49	113	196	Off Idle	86.3	0	2	132	944 Turbo	0.67	Lean	1	14.6	-5.22	15.08	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:08:20:0	28.63	1858	2	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.18	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:20:0	28.63	1862	2	13.49	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.18	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:20:0	28.63	1864	2	13.5	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.23	15.13	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:0	28.63	1865	1.99	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.19	15.13	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:0	28.63	1865	1.99	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.25	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:1	28.63	1865	1.99	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.29	15	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:1	28.63	1865	1.99	13.53	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.26	14.92	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:1	28.63	1862	1.99	13.52	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.25	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:1	28.63	1861	1.99	13.54	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.23	14.77	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:1	29.99	1861	1.99	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.19	14.64	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:1	29.99	1875	1.99	13.51	113	196	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.19	14.59	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:1	29.99	1866	1.98	13.5	113	196	Off Idle	86.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.25	14.53	0.99	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:2	29.99	1866	1.98	13.51	113	196	Off Idle	86.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.24	14.44	0.98	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:2	29.99	1869	1.98	13.5	113	196	Off Idle	86.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.27	14.4	0.98	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:2	29.99	1877	1.98	13.5	113	196	Off Idle	86.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.25	14.37	0.98	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:2	29.99	1878	1.98	13.51	113	196	Off Idle	86.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.29	14.37	0.98	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:2	29.99	1878	1.98	13.51	113	196	Off Idle	86.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.24	14.39	0.98	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:2	29.99	1884	1.98	13.51	113	196	Off Idle	86.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.29	14.42	0.98	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:3	29.99	1896	1.98	13.52	113	196	Off Idle	86.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.32	14.47	0.99	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:3	29.99	1888	1.98	13.53	113	196	Off Idle	86.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.31	14.51	0.99	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:3	29.99	1888	1.98	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.31	14.54	0.99	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:3	29.99	1892	1.98	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.39	14.6	0.99	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:3	29.99	1898	1.98	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.39	14.65	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:3	29.99	1899	1.97	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.39	14.7	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:4	29.99	1900	1.97	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.39	14.72	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:4	29.99	1900	1.97	13.54	113	196	Off Idle	86	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.39	14.71	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:4	29.99	1896	1.97	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.4	14.75	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:4	29.99	1879	1.97	13.53	113	196	Off Idle	86	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.39	14.81	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:4	29.99	1893	1.97	13.53	113	196	Off Idle	86	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.38	14.86	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:4	29.99	1895	1.97	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.37	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:20:4	29.99	1895	1.97	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.41	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:20:5	29.99	1898	1.97	13.54	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.43	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:20:5	29.99	1906	1.97	13.53	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.42	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:20:5	29.99	1906	1.97	13.52	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.42	15.19	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:20:5	29.99	1909	1.97	13.53	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.45	15.31	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:5	29.99	1910	1.97	13.53	113	196	Off Idle	86	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.47	15.34	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:5	29.99	1911	1.97	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.47	15.39	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:6	29.99	1916	1.97	13.53	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.52	15.4	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:6	29.99	1918	1.97	13.54	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.55	15.42	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:6	29.99	1920	1.97	13.53	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.52	15.44	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:6	29.99	1920	1.97	13.54	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.54	15.4	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:6	29.99	1921	1.97	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.54	15.41	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:6	29.99	1921	1.96	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.52	15.38	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:20:6	29.99	1919	1.96	13.51	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.57	15.34	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:7	29.99	1917	1.96	13.52	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.61	15.32	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:7	29.99	1918	1.96	13.5	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.62	15.25	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:7	29.99	1917	1.96	13.51	114	196	Off Idle	85.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.64	15.21	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:7	29.99	1917	1.96	13.53	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.63	15.18	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:7	29.99	1917	1.96	13.53	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.64	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:7	29.99	1936	1.96	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.59	15.14	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:8	29.99	1930	1.96	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.6	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:8	29.99	1924	1.96	13.51	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.59	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:8	29.99	1929	1.95	13.51	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.63	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:8	29.99	1929	1.95	13.51	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.63	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:20:8	29.99	1925	1.95	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.68	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:20:8	29.99	1935	1.95	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.71	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:20:9	29.99	1936	1.95	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.73	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:9	29.99	1936	1.95	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.74	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:9	29.99	1945	1.95	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.77	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:9	29.99	1941	1.95	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.79	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:9	29.99	1944	1.95	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.82	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:9	29.99	1948	1.94	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.81	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:20:9	29.99	1950	1.94	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.81	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:0	29.99	1953	1.94	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.82	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:0	29.99	1956	1.94	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.81	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:0	29.99	1956	1.94	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.81	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:0	29.99	1955	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.84	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:0	29.99	1952	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.81	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:0	29.99	1951	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.81	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:1	29.99	1951	1.94	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.83	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:1	29.99	1953	1.94	13.5	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.85	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:1	29.99	1955	1.94	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.84	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:1	31.36	1957	1.94	13.51	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.86	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:1	31.36	1957	1.94	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.86	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:1	31.36	1959	1.94	13.48	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.92	15.13	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:1	31.36	1956	1.94	13.48	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.91	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:2	31.36	1974	1.94	13.48	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.9	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:2	31.36	1963	1.94	13.47	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.86	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:2	31.36	1966	1.94	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.83	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:2	31.36	1970	1.94	13.5	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.8	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:2	31.36	1977	1.94	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.83	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:2	31.36	1980	1.94	13.5	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.86	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:3	31.36	1980	1.94	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.93	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:3	31.36	1982	1.94	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.94	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:3	31.36	1983	1.94	13.51	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.96	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:3	31.36	1980	1.94	13.51	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.94	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:3	31.36	1973	1.94	13.5	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.92	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:3	31.36	1976	1.94	13.48	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.91	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:4	31.36	1974	1.94	13.47	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.91	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:4	31.36	1971	1.94	13.46	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.89	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:4	31.36	1973	1.94	13.47	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.94	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:4	31.36	1974	1.94	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.95	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:21:4	31.36	1978	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.94	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:4	31.36	1979	1.94	13.51	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.97	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:4	31.36	1977	1.94	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.96	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:5	31.36	1981	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.91	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:5	31.36	1981	1.94	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.95	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:5	31.36	1983	1.94	13.48	113	196	Off Idle	86	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.96	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:5	31.36	1991	1.94	13.47	113	196	Off Idle	86	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.98	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:5	31.36	2011	1.94	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.99	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:5	31.36	2011	1.94	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:6	31.36	2002	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.98	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:6	31.36	2001	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.99	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:6	31.36	2001	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:6	31.36	1998	1.94	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.01	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:6	31.36	1993	1.94	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.04	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:6	31.36	1993	1.94	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.07	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:6	31.36	1982	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.07	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:7	31.36	1986	1.94	13.53	113	196	Off Idle	86	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.03	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:7	31.36	1984	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.98	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:21:7	31.36	1991	1.94	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.98	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:7	31.36	1990	1.94	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.94	15.22	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:7	31.36	1996	1.94	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.93	15.3	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:7	31.36	2000	1.94	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.93	15.32	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:8	31.36	2009	1.94	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.94	15.34	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:8	31.36	2009	1.94	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.96	15.35	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:8	31.36	2012	1.94	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.93	15.35	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:8	31.36	2015	1.94	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.02	15.31	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:8	31.36	2020	1.94	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.04	15.29	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:8	31.36	2020	1.94	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.02	15.22	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:9	31.36	2024	1.93	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.05	15.18	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:9	31.36	2028	1.93	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.1	15.14	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:9	31.36	2028	1.93	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.1	15.07	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:21:9	31.36	2028	1.93	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.12	15.03	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:9	31.36	2028	1.93	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.15	15.02	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:9	31.36	2027	1.93	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.2	14.99	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:21:9	31.36	2026	1.93	13.52	113	196	Off Idle	86	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.2	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:0	31.36	2021	1.93	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.22	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:0	31.36	2019	1.92	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.3	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:0	31.36	2019	1.92	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.31	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:0	31.36	2016	1.92	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.32	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:0	31.36	2014	1.92	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.33	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:0	31.36	2016	1.91	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.32	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:1	31.36	2025	1.91	13.48	113	196	Off Idle	86	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.35	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:1	31.36	2024	1.91	13.47	113	196	Off Idle	86	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.39	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:1	31.36	2023	1.91	13.48	113	196	Off Idle	86	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.44	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:1	31.36	2026	1.91	13.48	113	196	Off Idle	86	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.45	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:1	31.36	2033	1.9	13.5	113	196	Off Idle	86	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.47	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:1	31.36	2039	1.9	13.51	113	196	Off Idle	86	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.47	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:1	31.36	2040	1.9	13.53	113	196	Off Idle	86	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.48	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:2	31.36	2042	1.9	13.53	113	196	Off Idle	86	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.47	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:2	31.36	2048	1.9	13.54	113	196	Off Idle	86	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.5	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:2	31.36	2048	1.89	13.54	113	196	Off Idle	86	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.53	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:2	31.36	2042	1.89	13.55	113	196	Off Idle	86	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.5	14.75	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:2	31.36	2042	1.89	13.53	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.51	14.76	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:2	31.36	2034	1.89	13.51	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.51	14.76	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:3	31.36	2015	1.89	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.5	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:3	31.36	2034	1.89	13.48	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.52	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:3	31.36	2035	1.89	13.48	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.54	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:3	31.36	2041	1.88	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.6	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:22:3	31.36	2044	1.88	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.64	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:3	31.36	2044	1.88	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.66	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:4	31.36	2046	1.88	13.51	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.7	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:4	31.36	2048	1.88	13.53	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.67	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:4	31.36	2051	1.88	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.63	14.84	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:4	31.36	2051	1.88	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.61	14.87	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:4	31.36	2054	1.88	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.63	14.92	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:4	31.36	2056	1.88	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.65	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:4	31.36	2059	1.88	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.65	14.96	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:5	31.36	2060	1.88	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.68	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:5	31.36	2060	1.88	13.49	113	196	Off Idle	86	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.7	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:5	31.36	2060	1.87	13.49	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.69	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:5	31.36	2062	1.87	13.5	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.72	15.12	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:5	31.36	2062	1.87	13.5	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.71	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:5	31.36	2063	1.87	13.5	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.75	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:6	31.36	2080	1.87	13.52	113	196	Off Idle	85.9	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.71	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:6	31.36	2064	1.87	13.51	113	196	Off Idle	85.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.71	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:6	31.36	2060	1.87	13.51	113	196	Off Idle	85.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.75	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:6	31.36	2056	1.87	13.51	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.75	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:6	31.36	2056	1.87	13.51	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.77	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:6	31.36	2056	1.87	13.51	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.77	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:6	31.36	2062	1.87	13.52	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.75	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:7	31.36	2063	1.87	13.53	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.72	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:7	31.36	2064	1.87	13.53	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.71	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:7	31.36	2082	1.87	13.52	113	196	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.68	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:7	31.36	2069	1.88	13.51	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.68	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:7	31.36	2069	1.88	13.5	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.66	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:7	32.72	2078	1.88	13.47	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.72	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:8	32.72	2073	1.88	13.46	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.71	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:8	32.72	2073	1.88	13.47	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.71	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:8	32.72	2074	1.88	13.47	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.72	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:8	32.72	2077	1.88	13.49	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.71	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:22:8	32.72	2076	1.89	13.51	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.66	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:8	32.72	2074	1.89	13.53	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.63	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:9	32.72	2076	1.89	13.55	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.62	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:9	31.36	2063	1.89	13.54	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.59	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:9	31.36	2078	1.9	13.52	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.58	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:9	31.36	2078	1.9	13.51	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.62	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:9	31.36	2081	1.9	13.52	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.61	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:9	31.36	2081	1.91	13.53	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.62	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:22:9	31.36	2082	1.91	13.55	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.6	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:23:0	31.36	2084	1.91	13.54	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.54	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:23:0	31.36	2086	1.91	13.54	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.54	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:23:0	31.36	2078	1.91	13.53	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.49	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:23:0	31.36	2085	1.91	13.53	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.45	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:23:0	31.36	2089	1.92	13.52	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.45	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:23:0	31.36	2091	1.92	13.51	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.43	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:23:1	31.36	2090	1.93	13.49	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.38	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:23:1	31.36	2090	1.93	13.5	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.36	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:23:1	31.36	2093	1.94	13.51	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.3	15.16	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:23:1	31.36	2096	1.95	13.52	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.23	15.21	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:23:1	31.36	2095	1.95	13.53	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.11	15.25	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:23:1	31.36	2096	1.96	13.53	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.04	15.26	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:23:1	31.36	2102	1.96	13.53	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.99	15.26	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:23:2	31.36	2105	1.97	13.52	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.9	15.26	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:23:2	31.36	2105	1.97	13.5	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.87	15.25	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:23:2	31.36	2108	1.98	13.5	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.84	15.24	1.04	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:2	31.36	2125	1.98	13.49	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.81	15.24	1.04	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:23:2	31.36	2125	1.99	13.47	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.79	15.23	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:2	31.36	2106	2	13.47	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.81	15.17	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:3	31.36	2106	2	13.48	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.8	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:3	31.36	2106	2.01	13.47	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.8	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:3	31.36	2105	2.02	13.48	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.75	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:3	31.36	2102	2.02	13.47	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.73	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:3	31.36	2106	2.03	13.47	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.71	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:3	31.36	2106	2.03	13.45	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.7	14.9	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:4	31.36	2102	2.03	13.46	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.7	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:4	31.36	2116	2.03	13.46	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.69	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:4	31.36	2120	2.03	13.46	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.67	14.83	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:4	31.36	2121	2.03	13.48	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.64	14.86	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:23:4	31.36	2123	2.03	13.48	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.64	14.89	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:4	31.36	2130	2.03	13.48	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.66	14.9	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:4	31.36	2126	2.03	13.48	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.68	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:5	31.36	2126	2.03	13.48	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.71	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:5	31.36	2126	2.04	13.46	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.71	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:5	31.36	2126	2.04	13.46	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.69	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:5	31.36	2126	2.04	13.46	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.67	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:5	31.36	2124	2.04	13.47	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.66	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:5	31.36	2123	2.04	13.48	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.6	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:6	31.36	2121	2.04	13.5	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.58	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:6	31.36	2118	2.05	13.51	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.5	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:6	31.36	2129	2.06	13.53	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.39	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:6	31.36	2129	2.07	13.54	113	196	Off Idle	85.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.29	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:23:6	31.36	2140	2.08	13.54	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.19	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:23:6	31.36	2146	2.09	13.54	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.06	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:23:6	31.36	2140	2.11	13.55	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.88	14.9	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:23:7	31.36	2153	2.12	13.53	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.77	14.85	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:23:7	31.36	2154	2.13	13.52	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.66	14.8	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:23:7	31.36	2154	2.15	13.51	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-4.53	14.79	1.01	3.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:23:7	31.36	2163	2.16	13.51	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-4.47	14.79	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:23:7	31.36	2169	2.17	13.51	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-4.42	14.79	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:23:7	31.36	2177	2.18	13.52	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.17	Rich	1	14.6	-4.41	14.77	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:23:8	31.36	2178	2.19	13.52	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.35	14.77	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:23:8	31.36	2180	2.2	13.5	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.32	14.79	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:23:8	31.36	2174	2.22	13.49	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.25	14.82	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:23:8	31.36	2170	2.23	13.47	113	196	Off Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.24	14.87	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:23:8	31.36	2167	2.24	13.47	113	196	Off Idle	85.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.24	14.94	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:23:8	31.36	2167	2.25	13.48	113	196	Off Idle	85.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.21	14.99	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:23:9	31.36	2173	2.25	13.51	113	196	Off Idle	85.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.21	15.06	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:23:9	31.36	2166	2.25	13.53	113	196	Off Idle	85.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.16	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:23:9	31.36	2172	2.25	13.54	113	196	Off Idle	85	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.17	15.24	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:23:9	31.36	2172	2.25	13.53	113	196	Off Idle	85	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.16	15.31	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:23:9	31.36	2178	2.25	13.53	113	196	Off Idle	85	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.16	15.37	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:23:9	31.36	2189	2.25	13.53	113	196	Off Idle	84.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.18	15.37	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:23:9	31.36	2190	2.25	13.52	113	196	Off Idle	84.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.18	15.38	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:0	31.36	2196	2.25	13.53	113	196	Off Idle	84.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.18	15.39	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:0	31.36	2201	2.25	13.53	113	196	Off Idle	84.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.19	15.34	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:0	31.36	2201	2.25	13.53	113	196	Off Idle	84.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.19	15.26	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:0	31.36	2185	2.25	13.54	113	196	Off Idle	84.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.18	15.17	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:0	31.36	2200	2.25	13.54	113	196	Off Idle	83.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.14	15.09	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:0	31.36	2200	2.25	13.52	113	196	Off Idle	83.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.06	14.95	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:1	31.36	2199	2.26	13.5	113	196	Off Idle	83.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.99	14.91	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:1	31.36	2200	2.26	13.48	113	196	Off Idle	83.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.95	14.78	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:24:1	31.36	2202	2.27	13.47	113	196	Off Idle	83.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.91	14.7	1	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:08:24:1	31.36	2206	2.28	13.48	113	196	Off Idle	83.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.82	14.64	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:24:1	31.36	2211	2.29	13.5	113	196	Off Idle	83.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.7	14.59	0.99	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:24:1	31.36	2211	2.3	13.52	113	196	Off Idle	83	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.61	14.57	0.99	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:1	31.36	2238	2.31	13.53	113	196	Off Idle	82.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.47	14.55	0.99	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:2	31.36	2234	2.32	13.54	113	196	Off Idle	82.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.31	14.55	0.99	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:08:24:2	31.36	2234	2.33	13.54	113	196	Off Idle	82.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.21	14.57	0.99	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:08:24:2	31.36	2240	2.34	13.55	113	196	Off Idle	82.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.06	14.6	0.99	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:08:24:2	31.36	2243	2.36	13.54	113	196	Off Idle	82.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.95	14.61	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:24:2	31.36	2254	2.37	13.55	113	196	Off Idle	82	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.84	14.65	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:24:2	31.36	2256	2.38	13.53	113	196	Off Idle	82	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.79	14.67	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:24:3	31.36	2260	2.4	13.52	113	196	Off Idle	81.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.75	14.7	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:24:3	31.36	2260	2.42	13.51	113	196	Off Idle	81.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.7	14.71	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:24:3	31.36	2261	2.43	13.51	113	196	Off Idle	81.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.66	14.75	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:24:3	31.36	2261	2.44	13.52	113	196	Off Idle	81.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.57	14.76	1.01	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:24:3	31.36	2262	2.46	13.53	113	196	Off Idle	80.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.46	14.78	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:08:24:3	31.36	2262	2.47	13.52	113	196	Off Idle	80.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.38	14.79	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:08:24:4	31.36	2262	2.48	13.51	113	196	Off Idle	80.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.31	14.82	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:08:24:4	31.36	2286	2.49	13.5	113	196	Off Idle	80.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.19	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:24:4	31.36	2274	2.5	13.49	113	196	Off Idle	80.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.03	14.89	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:24:4	31.36	2280	2.51	13.51	113	196	Off Idle	80.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.95	14.92	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:24:4	31.36	2283	2.52	13.52	113	196	Off Idle	80.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.88	14.93	1.02	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:24:4	31.36	2282	2.53	13.53	113	196	Off Idle	80.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.81	14.93	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:24:4	31.36	2299	2.54	13.52	113	196	Off Idle	80	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.77	14.92	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:24:5	31.36	2307	2.55	13.5	113	196	Off Idle	79.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.75	14.91	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:5	31.36	2310	2.56	13.49	113	196	Off Idle	79.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.71	14.9	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:5	31.36	2315	2.56	13.47	113	196	Off Idle	79.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.64	14.87	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:5	31.36	2314	2.57	13.48	113	196	Off Idle	79.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.59	14.82	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:24:5	31.36	2314	2.58	13.5	113	196	Off Idle	78.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.48	14.77	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:24:5	31.36	2317	2.59	13.52	113	196	Off Idle	78.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.35	14.74	1	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:24:6	31.36	2321	2.6	13.52	113	196	Off Idle	78.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.26	14.71	1	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:24:6	31.36	2349	2.61	13.53	113	196	Off Idle	78.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.17	14.7	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:6	31.36	2349	2.62	13.53	113	196	Off Idle	77.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.06	14.68	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:6	31.36	2343	2.63	13.53	113	196	Off Idle	77.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.96	14.66	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:6	31.36	2353	2.64	13.55	113	196	Off Idle	77.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.91	14.65	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:6	31.36	2353	2.64	13.56	113	196	Off Idle	77	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.9	14.63	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:6	31.36	2368	2.65	13.54	113	196	Off Idle	76.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.87	14.62	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:7	31.36	2362	2.66	13.54	113	196	Off Idle	76.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.84	14.59	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:7	31.36	2363	2.67	13.55	113	196	Off Idle	76.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.8	14.57	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:7	31.36	2362	2.67	13.53	113	196	Off Idle	76.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.76	14.53	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:7	31.36	2368	2.68	13.54	113	196	Off Idle	75.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.71	14.5	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:7	31.36	2371	2.69	13.52	113	196	Off Idle	75.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.69	14.5	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:7	31.36	2374	2.7	13.51	113	196	Off Idle	74.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.64	14.48	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:8	31.36	2382	2.7	13.51	113	196	Off Idle	74.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.6	14.46	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:8	31.36	2387	2.71	13.5	113	196	Off Idle	74.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.58	14.43	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:8	31.36	2393	2.71	13.53	113	196	Off Idle	73.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.46	14.4	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:8	31.36	2395	2.72	13.54	113	196	Off Idle	73.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.45	14.35	0.98	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:24:8	31.36	2403	2.72	13.53	113	196	Off Idle	73.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.5	14.35	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:8	31.36	2409	2.73	13.52	113	196	Off Idle	73.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.47	14.32	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:9	31.36	2402	2.73	13.53	113	196	Off Idle	73	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.46	14.29	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:9	31.36	2402	2.73	13.51	113	196	Off Idle	72.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.46	14.28	0.97	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:9	31.36	2428	2.73	13.49	113	196	Off Idle	72.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.43	14.24	0.97	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:9	31.36	2436	2.74	13.52	113	196	Off Idle	72.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.46	14.2	0.97	3.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:9	31.36	2442	2.74	13.51	113	196	Off Idle	71.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.46	14.2	0.97	3.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:9	31.36	2442	2.75	13.49	113	196	Off Idle	71.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.41	14.19	0.97	3.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:24:9	29.99	2445	2.75	13.51	113	196	Off Idle	71.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.39	14.2	0.97	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:0	29.99	2445	2.75	13.52	113	196	Off Idle	71.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.39	14.18	0.97	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:0	29.99	2444	2.76	13.51	113	196	Off Idle	71.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.29	14.17	0.96	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:0	29.99	2444	2.76	13.52	113	196	Off Idle	71.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.29	14.15	0.96	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:0	29.99	2444	2.76	13.51	113	196	Off Idle	70.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.31	14.14	0.96	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:0	29.99	2444	2.77	13.53	113	196	Off Idle	70.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.24	14.14	0.96	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:25:0	29.99	2456	2.77	13.52	113	196	Off Idle	70.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.29	14.15	0.96	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:1	29.99	2470	2.77	13.51	113	196	Off Idle	70.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.29	14.16	0.96	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:1	29.99	2469	2.78	13.51	113	196	Off Idle	70.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.23	14.19	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:1	31.36	2468	2.78	13.53	113	196	Off Idle	69.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.19	14.21	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:1	31.36	2502	2.78	13.51	113	196	Off Idle	69.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.19	14.26	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:1	31.36	2500	2.79	13.52	113	196	Off Idle	69.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.14	14.34	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:1	31.36	2512	2.79	13.51	113	196	Off Idle	69	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.2	14.39	0.98	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:25:1	31.36	2512	2.79	13.51	113	196	Off Idle	68.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.24	14.45	0.98	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:25:2	31.36	2504	2.8	13.51	113	196	Off Idle	68.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.29	14.5	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:2	31.36	2520	2.8	13.52	113	196	Off Idle	68.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.3	14.59	0.99	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:2	31.36	2519	2.8	13.51	113	196	Off Idle	67.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.28	14.62	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:2	31.36	2519	2.81	13.5	113	196	Off Idle	67.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.25	14.66	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:2	31.36	2532	2.81	13.51	113	196	Off Idle	67.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.16	14.69	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:2	31.36	2526	2.81	13.51	113	196	Off Idle	67.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.14	14.72	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:3	31.36	2526	2.81	13.51	113	196	Off Idle	67	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.08	14.74	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:3	31.36	2534	2.82	13.51	113	196	Off Idle	66.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.08	14.74	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:3	31.36	2534	2.82	13.51	113	196	Off Idle	66.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.12	14.76	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:3	31.36	2561	2.82	13.5	113	196	Off Idle	65.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.11	14.78	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:3	31.36	2550	2.83	13.5	113	196	Off Idle	65.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.11	14.81	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:3	31.36	2560	2.83	13.51	113	196	Off Idle	65.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.12	14.82	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:4	31.36	2562	2.83	13.52	113	196	Off Idle	65.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.12	14.83	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:25:4	31.36	2578	2.84	13.52	113	196	Off Idle	65	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.08	14.85	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:25:4	31.36	2574	2.84	13.52	113	196	Off Idle	64.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.07	14.88	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:25:4	31.36	2576	2.84	13.52	113	196	Off Idle	64.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.03	14.9	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:25:4	31.36	2582	2.84	13.5	113	196	Off Idle	64.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.03	14.9	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:25:4	31.36	2574	2.85	13.5	113	196	Off Idle	64.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-0.03	14.91	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:4	29.99	2574	2.85	13.5	113	196	Off Idle	63.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-0.07	14.9	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:5	29.99	2592	2.85	13.5	113	196	Off Idle	63.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-0.08	14.88	1.01	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:5	29.99	2598	2.85	13.5	113	196	Off Idle	63.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-0.08	14.91	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:5	29.99	2596	2.86	13.5	113	196	Off Idle	63	0	2	132	944 Turbo	0.37	Lean	1	14.6	-0.03	14.94	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:5	29.99	2588	2.86	13.5	113	196	Off Idle	62.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-0.02	14.98	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:5	29.99	2608	2.86	13.52	113	196	Off Idle	62.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-0.03	14.99	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:5	29.99	2616	2.86	13.51	113	196	Off Idle	62.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	0.02	15.02	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:6	29.99	2618	2.87	13.54	113	196	Off Idle	62	0	2	132	944 Turbo	0.2	Lean	1	14.6	0.04	15.08	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:6	29.99	2627	2.87	13.52	113	196	Off Idle	61.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	0.01	15.1	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:25:6	29.99	2636	2.87	13.52	113	196	Off Idle	61.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	0.02	15.16	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:25:6	29.99	2644	2.88	13.52	113	196	Off Idle	61.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	0.05	15.22	1.04	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:25:6	29.99	2646	2.88	13.5	113	196	Off Idle	60.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	0.05	15.21	1.04	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:6	29.99	2654	2.88	13.5	113	196	Off Idle	60.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	0.04	15.22	1.04	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:6	29.99	2662	2.89	13.51	113	196	Off Idle	60.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	0.05	15.21	1.04	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:25:7	31.36	2662	2.89	13.51	113	196	Off Idle	59.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	0.07	15.22	1.04	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:7	31.36	2662	2.89	13.51	113	196	Off Idle	59.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	0.07	15.21	1.04	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:7	31.36	2660	2.89	13.52	113	196	Off Idle	59.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	0.06	15.14	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:7	31.36	2662	2.9	13.52	113	196	Off Idle	59	0	2	132	944 Turbo	0.61	Lean	1	14.6	0.1	15.1	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:7	29.99	2673	2.9	13.51	113	196	Off Idle	58.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	0.13	15.03	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:7	29.99	2673	2.9	13.5	113	196	Off Idle	58.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.12	14.94	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:8	29.99	2681	2.91	13.52	113	196	Off Idle	58.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.09	14.9	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:8	29.99	2689	2.91	13.5	113	196	Off Idle	58	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.13	14.87	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:8	29.99	2692	2.91	13.5	113	196	Off Idle	57.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.14	14.81	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:8	29.99	2702	2.92	13.5	113	196	Off Idle	57.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.16	14.72	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:8	29.99	2710	2.92	13.51	113	196	Off Idle	56.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.15	14.71	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:8	29.99	2716	2.92	13.51	113	196	Off Idle	56.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.15	14.71	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:9	29.99	2718	2.93	13.51	113	196	Off Idle	56.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.23	14.73	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:25:9	31.36	2767	2.93	13.52	113	196	Off Idle	55.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.25	14.74	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:9	31.36	2731	2.93	13.52	113	196	Off Idle	55.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	0.21	14.77	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:25:9	31.36	2731	2.93	13.52	113	196	Off Idle	55.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	0.23	14.79	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:25:9	31.36	2731	2.94	13.52	113	196	Off Idle	54.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	0.18	14.78	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:25:9	29.99	2725	2.94	13.52	113	196	Off Idle	54.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	0.16	14.8	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:25:9	29.99	2732	2.94	13.5	113	196	Off Idle	54.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	0.23	14.8	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:08:26:0	29.99	2746	2.95	13.51	113	196	Off Idle	53.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	0.21	14.81	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:08:26:0	29.99	2756	2.95	13.51	113	196	Off Idle	53.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	0.27	14.85	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:0	29.99	2760	2.95	13.51	113	196	Off Idle	53.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	0.29	14.86	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:0	29.99	2802	2.95	13.51	113	196	Off Idle	53.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	0.27	14.9	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:08:26:0	31.36	2780	2.96	13.52	113	196	Off Idle	52.8	0	2	132	944 Turbo	0.29	Rich	1	14.6	0.28	14.93	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:08:26:0	31.36	2783	2.96	13.52	113	196	Off Idle	52.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	0.33	14.95	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:1	31.36	2790	2.96	13.5	113	195	Off Idle	52.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	0.34	14.99	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:1	31.36	2785	2.97	13.52	113	195	Off Idle	52.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	0.34	15.09	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:1	29.99	2789	2.97	13.51	113	195	Off Idle	51.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	0.36	15.13	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:1	29.99	2788	2.97	13.52	113	196	Off Idle	51.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	0.34	15.13	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:1	29.99	2789	2.98	13.52	113	196	Off Idle	51.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	0.36	15.09	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:1	29.99	2788	2.98	13.51	113	196	Off Idle	51.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	0.33	15.07	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:1	29.99	2782	2.98	13.5	113	196	Off Idle	51.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.3	15.02	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:2	29.99	2801	2.98	13.5	113	196	Off Idle	51	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.36	14.97	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:2	29.99	2804	2.99	13.5	113	196	Off Idle	50.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.35	14.95	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:2	29.99	2802	2.99	13.49	113	196	Off Idle	50.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.35	14.9	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:2	29.99	2810	2.99	13.49	113	196	Off Idle	49.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.37	14.81	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:2	29.99	2828	3	13.51	113	196	Off Idle	49.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.33	14.79	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:2	29.99	2846	3	13.51	113	196	Off Idle	49.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.34	14.78	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:3	29.99	2856	3	13.49	113	196	Off Idle	49.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	0.37	14.77	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:08:26:3	29.99	2860	3.01	13.5	113	196	Off Idle	49.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	0.39	14.77	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:08:26:3	31.36	2874	3.01	13.51	113	196	Off Idle	49.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	0.44	14.8	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:3	31.36	2883	3.01	13.49	113	196	Off Idle	49	0	2	132	944 Turbo	0.45	Rich	1	14.6	0.44	14.81	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:3	31.36	2883	3.02	13.49	113	196	Off Idle	48.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	0.42	14.84	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:08:26:3	31.36	2888	3.02	13.49	113	196	Off Idle	48.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	0.39	14.88	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:08:26:4	31.36	2860	3.03	13.49	113	196	Off Idle	48	0	2	132	944 Turbo	0.32	Lean	1	14.6	0.4	14.89	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:4	31.36	2860	3.03	13.48	113	196	Off Idle	47.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	0.43	14.91	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:08:26:4	31.36	2881	3.03	13.5	113	196	Off Idle	47.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	0.43	14.96	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:4	31.36	2881	3.04	13.51	113	196	Off Idle	47.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	0.47	14.98	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:4	31.36	2882	3.04	13.51	113	196	Off Idle	47.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	0.45	15.01	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:4	29.99	2880	3.04	13.51	113	196	Off Idle	46.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	0.39	15.07	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:4	29.99	2895	3.05	13.52	113	196	Off Idle	46.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	0.45	15.1	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:5	29.99	2904	3.05	13.49	113	196	Off Idle	46.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	0.49	15.09	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:5	29.99	2904	3.05	13.5	113	196	Off Idle	46.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	0.54	15.05	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:5	29.99	2900	3.06	13.5	113	196	Off Idle	45.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	0.62	15	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:08:26:5	31.36	2922	3.06	13.49	113	196	Off Idle	45.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.55	14.95	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:5	31.36	2927	3.06	13.5	113	196	Off Idle	45.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	0.57	14.91	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:5	31.36	2937	3.07	13.5	113	196	Off Idle	45.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.52	14.87	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:6	31.36	2940	3.07	13.49	113	196	Off Idle	45	0	2	132	944 Turbo	0.64	Rich	1	14.6	0.53	14.81	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:6	31.36	2990	3.07	13.49	113	196	Off Idle	44.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	0.54	14.78	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:08:26:6	31.36	2972	3.08	13.51	113	196	Off Idle	44.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	0.59	14.76	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:08:26:6	31.36	2962	3.08	13.49	113	196	Off Idle	43.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	0.63	14.77	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:08:26:6	31.36	2972	3.08	13.5	113	196	Off Idle	43.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	0.65	14.78	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:08:26:6	31.36	2986	3.08	13.5	113	196	Off Idle	43.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	0.64	14.82	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:08:26:6	31.36	2995	3.09	13.49	113	196	Off Idle	43	0	2	132	944 Turbo	0.28	Lean	1	14.6	0.65	14.91	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:08:26:7	31.36	2996	3.09	13.48	113	196	Off Idle	42.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	0.55	14.99	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:08:26:7	31.36	2990	3.09	13.49	113	196	Off Idle	42.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	0.52	15.03	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:7	31.36	2991	3.1	13.51	113	196	Off Idle	42.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	0.55	15.07	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:7	31.36	3003	3.1	13.5	113	196	Off Idle	42	0	2	132	944 Turbo	0.31	Lean	1	14.6	0.54	15.1	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:7	31.36	3003	3.11	13.51	113	196	Off Idle	41.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	0.54	15.18	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:7	31.36	2991	3.11	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	0.59	15.18	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:8	31.36	2991	3.11	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	0.68	15.14	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:8	29.99	3004	3.11	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	0.67	15.11	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:8	29.99	3004	3.12	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.66	15.06	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:8	29.99	3012	3.12	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.74	14.98	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:8	29.99	3024	3.12	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.66	14.91	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:8	29.99	3027	3.12	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.71	14.82	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:26:9	31.36	3044	3.13	13.48	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.74	14.77	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:08:26:9	31.36	3044	3.13	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.73	14.75	1	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:08:26:9	31.36	3045	3.13	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.72	14.72	1	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:08:26:9	31.36	3060	3.13	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.71	14.71	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:9	31.36	3066	3.14	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.79	14.7	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:08:26:9	31.36	3067	3.14	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	0.78	14.7	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:26:9	31.36	3072	3.14	13.51	113	196	Off Idle	41.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	0.8	14.69	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:0	31.36	3075	3.14	13.52	113	196	Off Idle	41.7	0	2	132	944 Turbo	0.57	Lean	1	14.6	0.83	14.71	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:0	29.99	3083	3.14	13.52	113	196	Off Idle	41.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	0.76	14.71	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:0	29.99	3088	3.15	13.54	113	196	Off Idle	41.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	0.75	14.73	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:0	29.99	3096	3.15	13.53	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	0.79	14.77	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:0	29.99	3127	3.15	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	0.79	14.89	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:0	31.36	3117	3.15	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	0.86	14.9	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:1	31.36	3119	3.16	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	0.89	14.89	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:1	31.36	3127	3.16	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.95	14.83	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:1	31.36	3128	3.16	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.92	14.72	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:1	31.36	3136	3.16	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.91	14.59	0.99	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:1	31.36	3140	3.17	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.92	14.46	0.99	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:27:1	31.36	3142	3.17	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.85	14.25	0.97	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:1	31.36	3141	3.17	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.85	14.05	0.96	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:2	31.36	3142	3.17	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.88	13.8	0.94	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:2	31.36	3146	3.17	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.93	13.6	0.93	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:2	31.36	3148	3.18	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.95	13.49	0.92	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:2	31.36	3140	3.18	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.99	13.38	0.91	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:2	31.36	3174	3.18	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1	13.29	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:2	31.36	3182	3.18	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.91	13.26	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:3	31.36	3184	3.18	13.48	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.95	13.22	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:3	31.36	3216	3.19	13.47	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.88	13.18	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:3	31.36	3200	3.19	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.86	13.15	0.9	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:27:3	31.36	3204	3.19	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.88	13.21	0.9	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:27:3	31.36	3210	3.19	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.82	13.18	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:27:3	31.36	3212	3.2	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.95	13.18	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:4	31.36	3226	3.2	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.95	13.2	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:4	31.36	3220	3.2	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.06	13.15	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:4	31.36	3224	3.2	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.13	13.16	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:4	31.36	3225	3.21	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.12	13.15	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:4	31.36	3230	3.21	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.14	13.07	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:4	31.36	3252	3.21	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.14	13.1	0.89	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:08:27:4	31.36	3254	3.21	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.06	13.14	0.9	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:08:27:5	31.36	3266	3.21	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.05	13.15	0.9	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:08:27:5	31.36	3266	3.22	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.01	13.16	0.9	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:08:27:5	31.36	3294	3.22	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.05	13.18	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:27:5	31.36	3276	3.22	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.12	13.19	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:27:5	31.36	3284	3.22	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.17	13.29	0.91	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:27:5	31.36	3290	3.22	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.13	13.28	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:6	31.36	3293	3.23	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.18	13.28	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:6	31.36	3297	3.23	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.14	13.28	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:6	31.36	3304	3.23	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.15	13.26	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:6	31.36	3312	3.23	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.21	13.26	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:6	31.36	3312	3.23	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.11	13.23	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:6	31.36	3310	3.23	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.19	13.22	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:6	31.36	3318	3.24	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.25	13.18	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:7	31.36	3327	3.24	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.27	13.17	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:7	31.36	3333	3.24	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.19	13.14	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:7	31.36	3334	3.24	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.27	13.13	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:7	31.36	3340	3.24	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.22	13.09	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:7	31.36	3351	3.24	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.27	13.1	0.89	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:7	31.36	3365	3.24	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.27	13.11	0.89	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:27:8	31.36	3365	3.24	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.28	13.11	0.89	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:27:8	31.36	3371	3.24	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.34	13.12	0.89	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:8	31.36	3378	3.25	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.37	13.15	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:8	31.36	3388	3.25	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.41	13.14	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:8	31.36	3404	3.25	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.4	13.16	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:8	31.36	3395	3.25	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.36	13.18	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:9	31.36	3394	3.25	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.34	13.17	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:9	31.36	3406	3.25	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.32	13.18	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:9	31.36	3409	3.25	13.49	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.32	13.18	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:9	31.36	3414	3.25	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.29	13.17	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:9	31.36	3415	3.26	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.25	13.18	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:9	31.36	3430	3.26	13.49	113	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.34	13.18	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:27:9	31.36	3435	3.26	13.51	113	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.25	13.19	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:0	31.36	3443	3.26	13.5	113	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.3	13.19	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:0	31.36	3443	3.26	13.5	113	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.3	13.19	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:0	31.36	3448	3.27	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.28	13.19	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:0	31.36	3455	3.27	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.2	13.2	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:0	31.36	3456	3.27	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.2	13.19	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:0	31.36	3476	3.27	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.13	13.19	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:1	31.36	3474	3.27	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.23	13.19	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:1	31.36	3478	3.28	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.23	13.21	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:1	31.36	3478	3.28	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.24	13.19	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:1	31.36	3496	3.28	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.32	13.19	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:1	31.36	3486	3.28	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.35	13.2	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:1	31.36	3488	3.28	13.53	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.27	13.21	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:1	31.36	3494	3.28	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.43	13.24	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:2	31.36	3510	3.29	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.39	13.25	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:2	31.36	3515	3.29	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.28	13.24	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:2	31.36	3519	3.29	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.38	13.26	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:2	31.36	3536	3.29	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.39	13.29	0.91	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:2	31.36	3542	3.29	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.3	13.28	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:2	31.36	3542	3.29	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.46	13.3	0.91	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:3	31.36	3548	3.3	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.51	13.3	0.91	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:3	31.36	3554	3.3	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.43	13.28	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:3	31.36	3562	3.3	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.4	13.28	0.9	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:3	31.36	3591	3.3	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.48	13.28	0.9	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:3	31.36	3579	3.3	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.4	13.27	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:28:3	31.36	3566	3.31	13.48	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.39	13.26	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:4	31.36	3566	3.31	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.4	13.25	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:4	31.36	3567	3.31	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.41	13.22	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:4	31.36	3586	3.31	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.55	13.23	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:4	31.36	3585	3.32	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.51	13.2	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:4	31.36	3597	3.32	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.48	13.21	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:4	31.36	3602	3.32	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.49	13.21	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:4	32.72	3628	3.32	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.54	13.21	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:5	32.72	3619	3.32	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.5	13.17	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:5	32.72	3617	3.33	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.51	13.21	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:5	32.72	3620	3.33	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.54	13.19	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:5	32.72	3631	3.33	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.63	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:5	31.36	3643	3.33	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.68	13.22	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:5	31.36	3644	3.33	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.66	13.22	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:6	31.36	3648	3.34	13.49	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.68	13.19	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:6	31.36	3657	3.34	13.49	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.64	13.19	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:6	31.36	3658	3.34	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.59	13.18	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:6	31.36	3665	3.34	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.55	13.18	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:6	31.36	3664	3.34	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.56	13.14	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:6	31.36	3664	3.35	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.57	13.12	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:6	31.36	3673	3.35	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.67	13.11	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:28:7	31.36	3683	3.35	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.51	13.11	0.89	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:7	31.36	3685	3.35	13.53	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.42	13.1	0.89	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:7	31.36	3696	3.35	13.53	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.52	13.11	0.89	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:7	31.36	3698	3.36	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.57	13.15	0.9	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:7	31.36	3736	3.36	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.53	13.16	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:7	31.36	3710	3.36	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.59	13.18	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:8	31.36	3718	3.36	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.7	13.19	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:8	31.36	3719	3.37	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.67	13.21	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:8	31.36	3728	3.37	13.5	113	196	Off Idle	41.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.6	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:8	31.36	3736	3.37	13.52	113	196	Off Idle	41.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.61	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:8	31.36	3750	3.37	13.52	113	196	Off Idle	41.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.75	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:8	31.36	3752	3.37	13.49	113	196	Off Idle	41.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.65	13.2	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:9	31.36	3770	3.38	13.52	113	196	Off Idle	41.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.58	13.18	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:9	31.36	3761	3.38	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.66	13.15	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:28:9	31.36	3768	3.38	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.71	13.15	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:9	31.36	3769	3.38	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.69	13.16	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:9	31.36	3772	3.39	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.69	13.15	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:9	31.36	3772	3.39	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.66	13.13	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:28:9	31.36	3774	3.39	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.58	13.12	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:0	31.36	3784	3.39	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.5	13.11	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:0	31.36	3811	3.39	13.53	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.59	13.11	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:0	31.36	3792	3.39	13.53	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.6	13.13	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:0	31.36	3811	3.4	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.7	13.15	0.9	3.6	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:0	31.36	3814	3.4	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.7	13.14	0.9	3.6	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:0	31.36	3824	3.4	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.62	13.13	0.89	3.6	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:1	31.36	3797	3.4	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.49	13.14	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:1	31.36	3827	3.4	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.53	13.14	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:1	31.36	3830	3.4	13.53	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.54	13.17	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:1	31.36	3840	3.41	13.54	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.61	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:1	32.72	3876	3.41	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.71	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:1	32.72	3852	3.41	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.75	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:1	32.72	3852	3.41	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.73	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:2	32.72	3860	3.41	13.48	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.69	13.23	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:2	32.72	3861	3.41	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.58	13.23	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:2	32.72	3870	3.41	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.49	13.23	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:2	32.72	3876	3.41	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.38	13.23	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:2	32.72	3878	3.42	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.41	13.21	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:2	32.72	3888	3.42	13.54	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.43	13.19	0.9	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:3	32.72	3908	3.42	13.54	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.39	13.15	0.9	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:3	32.72	3908	3.42	13.54	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.36	13.14	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:3	32.72	3908	3.42	13.54	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.3	13.11	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:3	32.72	3913	3.42	13.55	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.38	13.1	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:3	32.72	3930	3.42	13.55	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.49	13.1	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:3	32.72	3930	3.42	13.53	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.6	13.09	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:4	32.72	3931	3.42	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.68	13.09	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:4	32.72	3940	3.43	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.59	13.12	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:4	32.72	3941	3.43	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.56	13.14	0.89	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:4	32.72	3946	3.43	13.49	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.57	13.12	0.89	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:4	32.72	3944	3.43	13.5	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.44	13.15	0.9	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:4	32.72	3952	3.43	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.46	13.16	0.9	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:4	32.72	3960	3.44	13.53	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.48	13.17	0.9	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:5	32.72	3958	3.44	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.5	13.14	0.9	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:5	32.72	3996	3.44	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.49	13.13	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:5	32.72	3978	3.44	13.52	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.49	13.1	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:5	32.72	3986	3.44	13.51	113	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.56	13.1	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:5	32.72	3993	3.44	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.58	13.04	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:5	32.72	3996	3.45	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.58	13.06	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:6	32.72	4006	3.45	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.44	13.03	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:29:6	32.72	4009	3.45	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.48	13.04	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:6	32.72	4014	3.45	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.38	13.02	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:6	32.72	4014	3.45	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.34	13.05	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:6	32.72	4034	3.46	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.38	13.03	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:6	32.72	4018	3.46	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.4	13.04	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:6	32.72	4025	3.46	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.37	13.06	0.89	3.6	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:7	32.72	4026	3.46	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.37	13.06	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:7	32.72	4039	3.46	13.53	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.27	13.06	0.89	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:08:29:7	32.72	4049	3.46	13.55	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.2	13.1	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:7	32.72	4058	3.46	13.55	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.23	13.1	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:7	32.72	4059	3.46	13.55	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.21	13.1	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:7	32.72	4065	3.47	13.55	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.25	13.09	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:8	32.72	4072	3.47	13.55	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.34	13.14	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:8	32.72	4072	3.47	13.55	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.39	13.14	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:8	32.72	4113	3.47	13.55	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.48	13.14	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:8	32.72	4100	3.47	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.52	13.12	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:8	32.72	4088	3.47	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.64	13.13	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:8	32.72	4095	3.47	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.61	13.13	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:9	32.72	4110	3.47	13.51	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.62	13.13	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:9	32.72	4107	3.47	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.59	13.14	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:29:9	32.72	4125	3.47	13.47	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.54	13.18	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:9	32.72	4118	3.47	13.47	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.38	13.17	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:9	32.72	4123	3.48	13.49	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.25	13.17	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:9	32.72	4128	3.48	13.5	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.26	13.15	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:29:9	32.72	4136	3.48	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.25	13.16	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:0	32.72	4147	3.48	13.54	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.31	13.15	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:0	32.72	4148	3.48	13.54	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.38	13.15	0.9	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:0	32.72	4154	3.48	13.51	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.46	13.14	0.89	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:0	32.72	4155	3.48	13.48	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.43	13.13	0.89	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:0	32.72	4159	3.48	13.47	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.48	13.13	0.89	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:0	32.72	4160	3.48	13.44	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.43	13.11	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:1	32.72	4158	3.48	13.43	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.47	13.1	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:1	32.72	4170	3.48	13.44	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.42	13.11	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:1	32.72	4171	3.48	13.46	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.45	13.08	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:1	32.72	4187	3.49	13.48	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.47	13.1	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:1	32.72	4193	3.49	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.4	13.12	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:1	32.72	4196	3.49	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.41	13.13	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:30:1	32.72	4200	3.49	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.36	13.14	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:2	32.72	4242	3.49	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.38	13.14	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:2	32.72	4226	3.49	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.37	13.14	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:2	32.72	4213	3.49	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.44	13.14	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:2	32.72	4222	3.49	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.4	13.14	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:2	32.72	4239	3.49	13.51	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.47	13.15	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:2	34.08	4233	3.49	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.38	13.16	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:08:30:3	34.08	4247	3.49	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	1.27	13.16	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:3	34.08	4248	3.49	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.28	13.14	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:3	34.08	4252	3.49	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.17	13.13	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:3	34.08	4278	3.49	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.17	13.12	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:3	34.08	4263	3.49	13.47	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.08	13.11	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:3	34.08	4263	3.49	13.46	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.98	13.1	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:4	34.08	4258	3.49	13.45	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.89	13.08	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:4	34.08	4262	3.49	13.47	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.84	13.05	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:4	34.08	4273	3.49	13.47	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.79	13.07	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:4	34.08	4274	3.5	13.46	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.84	13.05	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:4	34.08	4284	3.5	13.47	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.94	13.05	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:4	34.08	4298	3.5	13.48	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.98	13.04	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:4	34.08	4308	3.5	13.48	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.1	13.04	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:5	34.08	4308	3.49	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.14	13.05	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:30:5	34.08	4316	3.49	13.53	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.1	13.07	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:5	34.08	4319	3.49	13.54	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.96	13.07	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:5	34.08	4320	3.5	13.52	113	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.87	13.07	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:5	34.08	4324	3.5	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.73	13.08	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:6	34.08	4330	3.5	13.48	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.7	13.08	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:6	34.08	4330	3.5	13.46	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.81	13.08	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:6	34.08	4332	3.5	13.47	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.91	13.1	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:08:30:6	34.08	4335	3.5	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.96	13.11	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:6	34.08	4336	3.49	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.92	13.13	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:6	34.08	4344	3.49	13.55	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.72	13.13	0.89	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:08:30:6	34.08	4346	3.49	13.55	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.48	13.13	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:6	34.08	4334	3.48	13.55	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.03	13.15	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:08:30:7	35.45	4336	3.44	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1	13.15	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:08:30:7	35.45	4329	3.39	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.92	13.16	0.9	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:7	35.45	4291	3.32	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.99	13.15	0.9	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:30:7	35.45	4272	3.24	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.17	13.12	0.89	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:7	36.81	4238	3.15	13.51	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-5.31	13.08	0.89	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:30:7	36.81	4204	3.06	13.52	112	196	Full Load	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.71	12.98	0.88	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:30:8	36.81	4202	2.92	13.53	112	196	Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	-7.69	12.83	0.87	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:30:8	36.81	4201	2.87	13.53	112	196	Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	-8.21	12.7	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:8	36.81	4192	2.76	13.51	112	196	Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	-8.58	12.52	0.85	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:08:30:8	36.81	4184	2.61	13.52	112	196	Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	-8.89	12.31	0.84	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:8	36.81	4148	2.56	13.51	112	196	Idle	41.7	0	2	132	944 Turbo	0.91	Rich	1	14.6	-9.18	12.1	0.82	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:8	31.36	4047	2.4	13.49	112	196	Idle	41.7	0	2	132	944 Turbo	0.91	Rich	1	14.6	-9.4	11.87	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:9	25.9	4002	2.29	13.48	112	195	Idle	41.7	0	2	132	944 Turbo	0.91	Rich	1	14.6	-9.55	11.56	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:9	20.45	4018	2.19	13.49	112	195	Idle	41.7	0	2	132	944 Turbo	0.91	Rich	1	14.6	-9.57	11.46	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:9	20.45	4004	2.08	13.48	112	195	Idle	41.7	0	2	132	944 Turbo	0.9	Rich	1	14.6	-9.62	11.28	0.77	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:9	20.45	3995	1.98	13.48	112	195	Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-9.66	11.14	0.76	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:9	20.45	3936	1.84	13.49	112	195	Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.69	11	0.75	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:9	20.45	3923	1.8	13.5	112	195	Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.74	10.95	0.75	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:30:9	20.45	3908	1.72	13.5	112	196	Idle	40.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.76	10.94	0.75	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:0	20.45	3863	1.61	13.53	112	196	Idle	40.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.82	10.98	0.75	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:0	20.45	3815	1.56	13.53	112	195	Idle	39.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.81	11.03	0.75	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:0	20.45	3808	1.54	13.54	112	195	Idle	38.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.8	11.07	0.75	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:0	20.45	3760	1.54	13.54	112	195	Idle	37.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.72	11.15	0.76	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:0	20.45	3718	1.54	13.56	112	195	Idle	34.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.63	11.25	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:0	20.45	3711	1.55	13.56	112	195	Idle	33	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.53	11.38	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:1	20.45	3673	1.56	13.55	112	195	Idle	31.6	0	2	132	944 Turbo	0.16	Rich	1	14.6	-9.52	11.54	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:1	20.45	3639	1.58	13.55	112	195	Idle	30.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.52	11.75	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:1	20.45	3539	1.59	13.55	112	195	Idle	28.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.52	12.19	0.83	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:1	20.45	3558	1.61	13.55	112	195	Idle	25.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.45	12.36	0.84	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:1	20.45	3552	1.64	13.55	112	195	Idle	23.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.37	13.06	0.89	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:1	20.45	3459	1.66	13.55	112	195	Idle	22.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.33	13.8	0.94	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:1	20.45	3478	1.7	13.53	112	195	Idle	21.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.22	14.64	1	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:2	20.45	3472	1.72	13.54	112	195	Idle	20.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.21	15.91	1.08	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:2	20.45	3403	1.74	13.52	112	195	Idle	19.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.19	16.71	1.14	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:2	20.45	3392	1.76	13.52	112	195	Full Load	19.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.13	17.81	1.21	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:2	20.45	3366	1.77	13.52	112	195	Off Idle	18.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.16	18.47	1.26	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:2	20.45	3358	1.8	13.53	112	195	Off Idle	18.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	18.47	1.26	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:2	20.45	3313	1.82	13.54	112	195	Off Idle	18.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9	19.36	1.32	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:3	10.9	3210	1.85	13.54	112	195	Off Idle	18.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.88	19.85	1.35	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:31:3	13.63	3277	1.88	13.52	112	195	Off Idle	19.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.48	20.16	1.37	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:31:3	13.63	3268	1.92	13.52	112	196	Off Idle	21.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.22	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:08:31:3	16.36	3211	1.97	13.51	112	196	Off Idle	22.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.59	20.23	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:3	19.09	3154	2.05	13.52	112	196	Off Idle	24.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.59	20.24	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:3	21.81	2981	2.11	13.51	112	196	Off Idle	26	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.9	20.24	1.38	3.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:31:4	24.54	2981	2.2	13.5	112	196	Off Idle	29.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.14	20.25	1.38	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:31:4	24.54	2954	2.26	13.51	112	195	Off Idle	30.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-4.1	20.25	1.38	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:31:4	27.27	2915	2.31	13.51	112	195	Off Idle	32.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-3.83	20.24	1.38	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:31:4	29.99	2919	2.36	13.5	112	195	Off Idle	33.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-3.1	20.25	1.38	3.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:31:4	32.72	2929	2.42	13.52	112	195	Off Idle	35.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-2.88	20.25	1.38	3.7	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:31:4	32.72	2939	2.48	13.51	112	196	Off Idle	37.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-2.55	20.25	1.38	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:31:4	32.72	2967	2.55	13.5	112	196	Off Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-2.34	20.25	1.38	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:08:31:5	32.72	3001	2.6	13.5	112	196	Off Idle	42.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-2.07	20.25	1.38	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:31:5	32.72	3006	2.65	13.52	112	195	Off Idle	42.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-2.07	20.25	1.38	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:08:31:5	34.08	3008	2.71	13.51	112	195	Off Idle	42.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-2.06	20.25	1.38	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:31:5	34.08	2987	2.76	13.53	112	195	Off Idle	42.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-2.07	20.25	1.38	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:31:5	34.08	2979	2.82	13.5	112	196	Off Idle	42.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.99	20.14	1.37	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:31:5	34.08	2948	2.86	13.5	112	196	Off Idle	42.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-1.96	19.7	1.34	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:31:6	34.08	2914	2.88	13.51	112	196	Off Idle	42.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-1.89	19.49	1.33	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:31:6	34.08	2917	2.9	13.52	112	195	Off Idle	42.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-1.86	19.05	1.3	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:31:6	34.08	2922	2.91	13.52	112	195	Off Idle	42.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-1.79	18.52	1.26	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:31:6	34.08	2932	2.92	13.53	112	195	Off Idle	42.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.8	17.95	1.22	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:31:6	32.72	2959	2.91	13.55	112	195	Off Idle	42.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.83	17.32	1.18	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:31:6	32.72	2964	2.9	13.54	112	195	Off Idle	42.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.78	17.01	1.16	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:31:6	32.72	2973	2.9	13.52	112	196	Off Idle	42	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.75	16.04	1.09	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:7	32.72	2982	2.9	13.52	112	196	Off Idle	42	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.78	15.4	1.05	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:7	32.72	2985	2.9	13.51	112	196	Off Idle	42	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.78	14.89	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:7	34.08	2987	2.89	13.52	112	196	Off Idle	42.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.8	14.69	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:7	34.08	2984	2.89	13.52	112	196	Off Idle	42.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.79	14.39	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:7	34.08	2982	2.89	13.53	112	196	Off Idle	42.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.78	14.12	0.96	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:7	34.08	2974	2.89	13.53	112	196	Off Idle	42.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.79	14.06	0.96	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:8	34.08	2977	2.89	13.53	112	196	Off Idle	42.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.8	13.99	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:8	34.08	2964	2.89	13.53	112	196	Off Idle	42.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.76	14.01	0.95	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:8	34.08	2968	2.89	13.53	112	195	Off Idle	42.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.78	14.05	0.96	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:31:8	34.08	2977	2.89	13.53	112	195	Off Idle	41.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.72	14.11	0.96	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:31:8	34.08	2989	2.89	13.53	112	195	Off Idle	41.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.7	14.13	0.96	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:31:8	34.08	3003	2.89	13.54	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.65	14.18	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:9	34.08	3006	2.9	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.64	14.21	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:9	34.08	3010	2.9	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.66	14.22	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:9	34.08	2989	2.9	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.64	14.27	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:9	32.72	3001	2.9	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.68	14.3	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:9	32.72	2998	2.91	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.69	14.31	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:9	32.72	2990	2.91	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.68	14.31	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:31:9	32.72	2994	2.91	13.55	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.67	14.31	0.98	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:32:0	32.72	2998	2.91	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.6	14.31	0.97	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:32:0	32.72	2999	2.91	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.57	14.3	0.97	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:32:0	32.72	2990	2.91	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.56	14.3	0.97	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:08:32:0	32.72	2996	2.92	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.49	14.3	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:0	32.72	3004	2.92	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.51	14.28	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:0	32.72	3004	2.92	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.54	14.29	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:1	32.72	3012	2.92	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.51	14.3	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:1	32.72	3014	2.92	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.52	14.31	0.97	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:1	32.72	3020	2.92	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.45	14.33	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:1	32.72	3023	2.93	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.49	14.36	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:1	32.72	3018	2.93	13.51	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.5	14.38	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:1	32.72	3018	2.93	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.52	14.39	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:1	32.72	3018	2.93	13.51	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.47	14.4	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:2	34.08	3030	2.93	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.49	14.41	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:2	34.08	3026	2.93	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.43	14.43	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:2	34.08	3028	2.93	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.39	14.45	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:2	34.08	3038	2.93	13.51	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.37	14.46	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:2	34.08	3043	2.93	13.54	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.33	14.46	0.98	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:2	34.08	3044	2.94	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.33	14.46	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:3	34.08	3048	2.94	13.54	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.39	14.49	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:3	34.08	3020	2.94	13.55	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.39	14.52	0.99	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:32:3	32.72	3020	2.94	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.44	14.55	0.99	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:3	32.72	3032	2.94	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.47	14.58	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:3	32.72	3025	2.94	13.51	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.48	14.6	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:3	32.72	3028	2.94	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.48	14.61	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:4	32.72	3017	2.94	13.5	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.45	14.63	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:4	32.72	3035	2.94	13.5	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.46	14.65	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:4	32.72	3036	2.94	13.51	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.49	14.7	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:4	32.72	3048	2.94	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.45	14.7	1	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:4	32.72	3048	2.94	13.51	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.49	14.71	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:4	32.72	3056	2.94	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.46	14.72	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:4	32.72	3062	2.94	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.52	14.72	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:5	32.72	3062	2.94	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.45	14.73	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:5	32.72	3073	2.94	13.54	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.5	14.73	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:5	32.72	3063	2.94	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.5	14.73	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:5	32.72	3061	2.94	13.53	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.5	14.74	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:5	32.72	3057	2.94	13.52	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.5	14.74	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:5	32.72	3056	2.94	13.5	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.44	14.74	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:6	32.72	3058	2.94	13.51	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.44	14.76	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:6	32.72	3064	2.94	13.52	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.47	14.77	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:6	32.72	3025	2.94	13.53	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.38	14.79	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:6	32.72	3050	2.94	13.52	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.4	14.81	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:6	32.72	3076	2.94	13.54	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.47	14.83	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:6	32.72	3079	2.94	13.53	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.43	14.85	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:32:6	32.72	3081	2.94	13.51	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1.52	14.86	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:7	32.72	3080	2.94	13.53	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.49	14.87	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:7	32.72	3073	2.94	13.54	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.55	14.88	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:7	32.72	3067	2.94	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-1.53	14.88	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:7	32.72	3096	2.94	13.54	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.52	14.87	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:7	34.08	3089	2.94	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-1.48	14.88	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:7	34.08	3089	2.94	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.53	14.92	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:8	34.08	3100	2.94	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-1.52	14.92	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:8	34.08	3100	2.94	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-1.59	14.93	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:8	32.72	3103	2.94	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-1.64	14.97	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:8	32.72	3095	2.94	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-1.71	15.04	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:8	32.72	3093	2.94	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-1.7	15.07	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:08:32:8	32.72	3093	2.94	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-1.75	15.1	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:32:9	32.72	3115	2.94	13.51	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-1.73	15.13	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:32:9	34.08	3090	2.94	13.5	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-1.84	15.19	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:9	34.08	3097	2.93	13.5	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-1.85	15.19	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:9	34.08	3097	2.93	13.51	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-1.85	15.19	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:9	34.08	3116	2.93	13.51	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.91	15.13	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:9	34.08	3108	2.93	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.89	15.09	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:08:32:9	34.08	3107	2.92	13.54	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.92	15.02	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:33:0	34.08	3108	2.92	13.51	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.94	14.96	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:08:33:0	34.08	3106	2.92	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.01	14.9	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:08:33:0	34.08	3100	2.92	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-1.96	14.86	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:0	34.08	3101	2.91	13.53	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.01	14.78	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:0	34.08	3101	2.91	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.02	14.74	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:0	34.08	3108	2.91	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-2.04	14.72	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:1	34.08	3108	2.91	13.55	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-2.01	14.73	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:33:1	34.08	3134	2.91	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-2.04	14.79	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:33:1	34.08	3134	2.9	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.08	14.86	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:1	34.08	3132	2.9	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.11	14.94	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:1	34.08	3132	2.9	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.18	14.97	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:1	34.08	3116	2.9	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.2	15.06	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:1	34.08	3114	2.9	13.54	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-2.2	15.1	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:2	34.08	3114	2.9	13.54	111	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-2.2	15.13	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:08:33:2	34.08	3120	2.9	13.54	111	195	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.16	15.2	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:33:2	34.08	3116	2.9	13.54	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.18	15.25	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:33:2	34.08	3119	2.9	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.19	15.23	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:33:2	34.08	3120	2.9	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.22	15.19	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:33:2	34.08	3124	2.89	13.53	111	195	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.23	15.13	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:33:3	34.08	3128	2.89	13.52	111	195	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.28	15.08	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:33:3	34.08	3133	2.89	13.52	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-2.23	15.04	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:33:3	34.08	3136	2.89	13.52	112	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.26	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:33:3	34.08	3134	2.89	13.52	112	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-2.21	14.95	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:3	34.08	3136	2.89	13.54	111	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-2.22	14.89	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:3	34.08	3137	2.89	13.54	111	195	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.24	14.86	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:4	34.08	3136	2.89	13.54	111	195	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-2.26	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:4	34.08	3143	2.89	13.53	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-2.33	14.86	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:4	34.08	3148	2.89	13.53	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.35	14.9	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:4	34.08	3151	2.88	13.51	111	195	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.41	14.93	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:4	34.08	3152	2.88	13.51	111	195	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.38	14.97	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:4	34.08	3152	2.88	13.51	111	195	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.38	14.99	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:4	34.08	3146	2.88	13.53	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.46	15.03	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:33:5	34.08	3144	2.88	13.52	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-2.52	15.07	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:5	34.08	3145	2.87	13.52	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.62	15.14	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:5	34.08	3148	2.87	13.54	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.74	15.18	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:5	34.08	3148	2.86	13.53	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-3	15.17	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:08:33:5	34.08	3147	2.84	13.53	112	195	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.32	15.15	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:08:33:5	34.08	3142	2.78	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.75	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:08:33:6	34.08	3136	2.72	13.53	112	195	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.39	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:33:6	34.08	3132	2.65	13.53	112	195	Full Load	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.77	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:6	35.45	3119	2.58	13.54	112	195	Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.56	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:6	35.45	3119	2.52	13.54	112	195	Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.3	14.91	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:33:6	35.45	3101	2.44	13.54	112	195	Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.23	14.8	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:33:6	35.45	3089	2.39	13.55	112	195	Idle	39.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	14.73	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:33:6	35.45	3015	2.33	13.54	112	195	Idle	39.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-7.92	14.68	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:33:7	32.72	3015	2.27	13.54	112	195	Idle	37.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.19	14.64	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:33:7	27.27	2988	2.18	13.53	112	195	Idle	33.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.36	14.61	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:33:7	21.81	2948	2.13	13.54	111	195	Idle	30.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-8.4	14.53	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:33:7	21.81	2998	2.08	13.53	111	195	Idle	28.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.47	14.48	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:33:7	19.09	2999	2.04	13.53	111	195	Idle	26.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.45	14.41	0.98	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:7	19.09	3017	2	13.53	111	195	Idle	24	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.48	14.31	0.98	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:8	19.09	3024	1.94	13.52	111	195	Idle	21.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.46	14.18	0.97	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:8	19.09	3050	1.89	13.53	111	196	Idle	19.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.49	13.98	0.95	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:8	19.09	3122	1.84	13.53	111	196	Idle	19.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.5	13.84	0.94	3.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:8	19.09	3231	1.81	13.54	111	196	Idle	19.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.53	13.68	0.93	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:8	19.09	3173	1.8	13.53	111	195	Idle	19.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.6	13.53	0.92	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:8	19.09	3173	1.79	13.53	111	195	Idle	19.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.68	13.45	0.92	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:9	19.09	3165	1.8	13.53	111	195	Idle	21.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.83	13.32	0.91	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:9	19.09	3141	1.81	13.53	111	195	Idle	23.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.89	13.24	0.9	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:9	19.09	3091	1.82	13.53	111	195	Idle	26.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.04	13.21	0.9	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:9	19.09	3096	1.81	13.54	111	195	Idle	28.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.06	13.24	0.9	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:9	20.45	3095	1.8	13.55	111	195	Idle	30.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.21	13.35	0.91	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:9	19.09	3095	1.8	13.54	111	195	Idle	32.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.21	13.48	0.92	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:33:9	19.09	3054	1.8	13.55	111	195	Idle	35	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.3	13.81	0.94	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:0	19.09	3042	1.8	13.54	111	195	Idle	37	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.33	14.14	0.96	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:0	19.09	3042	1.8	13.55	111	195	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	14.54	0.99	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:0	19.09	3044	1.79	13.55	111	195	Idle	40.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:0	19.09	3054	1.77	13.55	111	195	Idle	39.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	15.86	1.08	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:0	19.09	3082	1.76	13.56	111	195	Idle	39.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	16.48	1.12	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:0	19.09	3086	1.74	13.56	111	195	Idle	39.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	17.39	1.18	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:1	19.09	3122	1.74	13.55	111	195	Idle	39.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	17.95	1.22	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:1	19.09	3112	1.74	13.56	111	195	Idle	39.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	18.52	1.26	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:1	19.09	3114	1.73	13.56	111	195	Idle	39.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	18.97	1.29	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:34:1	19.09	3106	1.72	13.55	111	195	Idle	39.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.44	19.54	1.33	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:1	19.09	3106	1.71	13.55	111	195	Idle	39.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.44	19.69	1.34	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:1	19.09	3085	1.71	13.54	111	195	Idle	39.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	19.94	1.36	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:1	19.09	3085	1.72	13.54	111	195	Idle	39.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	20.1	1.37	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:2	19.09	3063	1.72	13.54	111	195	Idle	39.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.2	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:2	19.09	3040	1.72	13.54	111	195	Idle	40.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.52	20.2	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:2	19.09	3046	1.72	13.54	111	195	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:2	19.09	3045	1.72	13.54	111	195	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:2	19.09	3030	1.72	13.55	111	195	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:2	19.09	3030	1.72	13.56	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.21	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:3	19.09	3051	1.72	13.54	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:3	19.09	3059	1.72	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:3	19.09	3091	1.72	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:3	19.09	3068	1.71	13.54	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:3	19.09	3067	1.71	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:3	19.09	3065	1.71	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:4	19.09	3062	1.71	13.55	111	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:4	19.09	3060	1.7	13.55	111	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:4	19.09	3053	1.7	13.54	111	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:4	19.09	3042	1.7	13.54	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:4	19.09	3057	1.7	13.54	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:4	19.09	3028	1.7	13.54	111	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:4	19.09	3005	1.7	13.55	111	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:5	19.09	3026	1.7	13.55	111	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:5	19.09	3025	1.7	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:5	19.09	3019	1.7	13.54	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:5	19.09	3028	1.7	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:5	19.09	3030	1.7	13.54	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:5	19.09	3033	1.7	13.54	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:6	19.09	3033	1.7	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:6	19.09	3035	1.7	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:6	19.09	3036	1.7	13.56	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:6	19.09	3032	1.7	13.56	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:6	19.09	3026	1.7	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:6	19.09	3026	1.7	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:6	19.09	3022	1.7	13.54	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:7	19.09	3016	1.7	13.54	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:7	19.09	3012	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:7	19.09	3011	1.71	13.54	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:7	19.09	3010	1.71	13.55	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:7	19.09	3008	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:7	19.09	3003	1.71	13.56	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:8	19.09	3003	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:8	19.09	2997	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:8	19.09	2996	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:8	19.09	2996	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:8	19.09	2988	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:8	19.09	2988	1.71	13.53	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:9	19.09	2986	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.2	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:9	19.09	2987	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.2	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:9	19.09	2988	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.2	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:9	19.09	3004	1.71	13.53	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:9	19.09	2982	1.71	13.53	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:9	19.09	2982	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:34:9	19.09	2994	1.71	13.54	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:0	19.09	2995	1.71	13.54	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:0	19.09	2992	1.71	13.55	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:0	19.09	2992	1.71	13.56	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:35:0	19.09	2963	1.71	13.55	111	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:0	19.09	2979	1.71	13.55	111	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:0	19.09	2978	1.7	13.54	111	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:1	19.09	2982	1.7	13.54	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:1	19.09	2964	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:1	19.09	2938	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:1	19.09	2948	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:1	19.09	2956	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:1	19.09	2957	1.71	13.56	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:1	19.09	2957	1.71	13.56	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:2	19.09	2935	1.71	13.56	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:2	19.09	2960	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:2	19.09	2961	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:2	19.09	2984	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:2	19.09	2961	1.71	13.54	111	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:2	19.09	2958	1.71	13.55	111	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:3	19.09	2958	1.71	13.54	111	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:3	19.09	2956	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:3	19.09	3001	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:3	19.09	2953	1.71	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:3	19.09	2930	1.71	13.55	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:3	19.09	2948	1.71	13.53	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:4	19.09	2965	1.71	13.53	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:4	19.09	2965	1.71	13.52	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:4	19.09	2942	1.71	13.51	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:4	19.09	2924	1.71	13.51	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:4	19.09	2946	1.7	13.53	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:4	19.09	2947	1.7	13.53	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:4	19.09	2954	1.7	13.54	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:5	19.09	2958	1.7	13.55	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:5	19.09	2963	1.7	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:5	19.09	2963	1.7	13.55	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:5	19.09	2964	1.7	13.54	111	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:5	19.09	2960	1.7	13.54	111	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:5	19.09	2951	1.7	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:6	19.09	2951	1.7	13.53	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:6	19.09	2932	1.7	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:6	19.09	2912	1.7	13.53	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:6	19.09	2912	1.7	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:6	19.09	2896	1.71	13.56	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:6	19.09	2863	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:6	19.09	2863	1.71	13.54	111	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:7	19.09	2877	1.71	13.55	111	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:7	19.09	2872	1.71	13.54	111	195	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:7	19.09	2874	1.71	13.54	111	195	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:7	19.09	2875	1.71	13.54	111	196	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:7	19.09	2892	1.71	13.55	111	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:7	19.09	2886	1.71	13.54	111	196	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:8	19.09	2876	1.71	13.54	111	195	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:8	19.09	2892	1.71	13.54	111	195	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:8	19.09	2889	1.71	13.55	111	195	Idle	40.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:8	19.09	2888	1.71	13.55	111	195	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:8	19.09	2886	1.72	13.56	111	195	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:8	19.09	2884	1.72	13.55	111	195	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:9	19.09	2884	1.71	13.55	111	195	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:9	19.09	2883	1.71	13.55	111	195	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.48	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:9	19.09	2885	1.71	13.54	111	195	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.47	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:9	19.09	2886	1.71	13.54	111	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.48	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:35:9	19.09	2890	1.71	13.55	111	195	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:9	19.09	2896	1.71	13.55	111	195	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:35:9	19.09	2896	1.7	13.55	111	195	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:0	19.09	2874	1.7	13.55	111	195	Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:0	19.09	2896	1.7	13.54	111	195	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:0	19.09	2894	1.7	13.54	111	195	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.21	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:0	19.09	2894	1.7	13.54	111	195	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:0	19.09	2890	1.7	13.54	111	195	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:0	19.09	2863	1.69	13.54	111	195	Full Load	44	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:1	19.09	2863	1.69	13.54	111	195	Off Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:1	9.54	2804	1.69	13.54	111	195	Off Idle	44	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:36:1	9.54	2891	1.69	13.55	111	195	Off Idle	44.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:36:1	12.27	2882	1.69	13.53	111	195	Off Idle	44.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:36:1	14.99	2880	1.69	13.52	111	195	Off Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:36:1	17.72	2874	1.7	13.54	111	195	Off Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:36:1	17.72	2870	1.7	13.54	111	195	Off Idle	45.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.37	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:36:2	20.45	2868	1.71	13.54	111	196	Off Idle	45.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.32	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:36:2	23.18	2871	1.71	13.54	111	196	Off Idle	45.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.27	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:36:2	25.9	2875	1.72	13.56	111	196	Off Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.28	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:36:2	28.63	2883	1.72	13.55	111	196	Off Idle	46.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.28	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:36:2	28.63	2896	1.74	13.56	111	196	Off Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.27	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:2	31.36	2908	1.75	13.54	111	196	Off Idle	46.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.29	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:3	34.08	2908	1.75	13.55	111	195	Off Idle	46.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.31	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:3	36.81	2909	1.76	13.56	111	195	Off Idle	46.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.32	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:3	36.81	2901	1.76	13.56	111	195	Off Idle	46.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.32	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:3	36.81	2895	1.77	13.55	111	195	Off Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.32	20.26	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:3	36.81	2894	1.78	13.53	111	195	Off Idle	46.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.33	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:3	36.81	2884	1.79	13.53	111	195	Off Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.33	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:36:4	36.81	2876	1.8	13.51	111	196	Off Idle	45.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.33	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:4	36.81	2876	1.8	13.5	111	196	Off Idle	45.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.31	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:4	36.81	2870	1.81	13.51	111	196	Off Idle	45.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.32	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:4	36.81	2858	1.81	13.51	111	195	Off Idle	45.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.29	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:4	36.81	2854	1.82	13.54	111	195	Off Idle	45.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.27	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:4	36.81	2843	1.82	13.54	111	195	Off Idle	45.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.21	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:4	35.45	2840	1.83	13.54	111	195	Off Idle	45.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.18	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:5	35.45	2845	1.83	13.53	111	195	Off Idle	45.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.15	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:5	35.45	2844	1.84	13.53	111	196	Off Idle	45.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.1	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:36:5	35.45	2838	1.84	13.55	111	196	Off Idle	45.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.08	20.23	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:5	35.45	2833	1.85	13.55	111	196	Off Idle	45.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.06	20.23	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:5	36.81	2856	1.85	13.56	111	196	Off Idle	45.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.03	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:5	36.81	2845	1.85	13.54	111	196	Off Idle	46.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.03	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:6	36.81	2840	1.86	13.53	111	196	Off Idle	46.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.99	20.23	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:6	36.81	2846	1.87	13.52	111	196	Off Idle	46.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.93	20.14	1.37	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:6	36.81	2847	1.87	13.52	111	196	Off Idle	47	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.87	20	1.36	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:6	36.81	2847	1.88	13.54	111	196	Off Idle	47.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.84	19.84	1.35	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:6	35.45	2837	1.88	13.54	111	196	Off Idle	47.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.81	19.62	1.34	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:6	35.45	2841	1.88	13.55	111	196	Off Idle	47.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.78	19.37	1.32	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:6	35.45	2841	1.89	13.57	111	196	Off Idle	47.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.74	19.11	1.3	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:7	35.45	2846	1.89	13.55	111	196	Off Idle	47.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.76	18.81	1.28	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:7	35.45	2845	1.9	13.55	111	196	Off Idle	47.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.73	18.49	1.26	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:7	35.45	2845	1.9	13.55	111	196	Off Idle	47.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.74	18.16	1.24	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:7	35.45	2842	1.9	13.55	111	196	Off Idle	47.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.73	17.85	1.22	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:7	35.45	2845	1.91	13.54	111	196	Off Idle	47.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.72	17.59	1.2	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:7	35.45	2847	1.91	13.55	111	196	Off Idle	47.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.68	17.36	1.18	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:8	35.45	2847	1.91	13.55	111	195	Off Idle	47	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.69	17.16	1.17	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:8	35.45	2857	1.92	13.54	111	195	Off Idle	46.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.63	17	1.16	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:8	35.45	2860	1.92	13.56	111	195	Off Idle	46.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.64	16.88	1.15	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:8	35.45	2856	1.92	13.55	111	195	Off Idle	46.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	16.76	1.14	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:36:8	35.45	2859	1.92	13.55	111	195	Off Idle	46.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.6	16.63	1.13	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:8	35.45	2877	1.93	13.54	111	195	Off Idle	46.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	16.59	1.13	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:9	35.45	2858	1.93	13.55	111	195	Off Idle	46.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	16.5	1.12	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:9	35.45	2858	1.93	13.55	111	196	Off Idle	46.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	16.41	1.12	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:9	35.45	2850	1.93	13.54	111	196	Off Idle	46.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.53	16.32	1.11	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:9	35.45	2797	1.94	13.54	111	196	Off Idle	46.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	16.24	1.11	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:36:9	35.45	2797	1.94	13.52	111	196	Off Idle	46.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	16.17	1.1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:9	35.45	2828	1.94	13.53	111	196	Off Idle	46.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.48	16.06	1.09	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:36:9	35.45	2824	1.94	13.54	111	196	Off Idle	46.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.48	16.03	1.09	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:0	35.45	2822	1.95	13.55	111	196	Off Idle	47	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.48	15.97	1.09	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:0	35.45	2818	1.95	13.56	111	196	Off Idle	47.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.41	15.91	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:0	35.45	2814	1.95	13.56	111	196	Off Idle	47.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.43	15.81	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:0	35.45	2814	1.95	13.56	111	196	Off Idle	47.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.45	15.79	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:0	35.45	2817	1.95	13.55	111	196	Off Idle	47.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	15.75	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:0	35.45	2824	1.95	13.56	111	196	Off Idle	48.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.42	15.7	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:1	35.45	2832	1.95	13.56	111	196	Off Idle	48.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.4	15.67	1.07	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:1	35.45	2832	1.95	13.57	111	196	Off Idle	48.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.41	15.63	1.06	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:1	35.45	2838	1.95	13.57	111	196	Off Idle	48.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.41	15.6	1.06	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:1	35.45	2833	1.95	13.56	111	196	Off Idle	48.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.41	15.55	1.06	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:37:1	35.45	2830	1.95	13.56	111	196	Off Idle	48.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.39	15.53	1.06	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:37:1	35.45	2830	1.96	13.57	111	196	Off Idle	48.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.36	15.51	1.06	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:1	35.45	2836	1.96	13.56	111	196	Off Idle	48.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.31	15.5	1.06	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:2	35.45	2833	1.96	13.55	111	196	Off Idle	48.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.25	15.48	1.05	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:2	35.45	2831	1.97	13.55	111	196	Off Idle	48.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.21	15.45	1.05	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:2	35.45	2832	1.97	13.55	111	196	Off Idle	48.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.18	15.42	1.05	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:2	35.45	2832	1.98	13.55	111	196	Off Idle	48.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.14	15.39	1.05	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:2	35.45	2826	1.99	13.53	111	196	Off Idle	47.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.07	15.37	1.05	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:37:2	35.45	2831	2.01	13.54	111	195	Off Idle	47.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.98	15.31	1.04	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:37:3	35.45	2836	2.02	13.52	111	195	Off Idle	47.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.88	15.29	1.04	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:37:3	35.45	2842	2.04	13.55	111	196	Off Idle	47.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.62	15.22	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:37:3	35.45	2844	2.07	13.55	111	196	Off Idle	47.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.39	15.15	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:37:3	35.45	2860	2.08	13.55	111	196	Off Idle	48	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.35	15.09	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:37:3	35.45	2855	2.1	13.57	111	196	Off Idle	48	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.27	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:37:3	35.45	2855	2.12	13.58	111	196	Off Idle	47.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.2	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:4	35.45	2860	2.13	13.58	111	196	Off Idle	47.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.12	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:4	35.45	2858	2.15	13.56	111	195	Off Idle	47.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.96	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:37:4	35.45	2841	2.17	13.55	111	195	Off Idle	47.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.86	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:37:4	35.45	2838	2.18	13.54	110	196	Off Idle	47.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.83	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:37:4	35.45	2825	2.19	13.55	110	196	Off Idle	47	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.77	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:37:4	35.45	2819	2.21	13.53	110	196	Off Idle	46.9	0	2	132	944 Turbo	0.17	Rich	1	14.6	-6.71	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:37:4	35.45	2819	2.23	13.56	111	196	Off Idle	46.9	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.71	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:37:5	35.45	2793	2.23	13.56	111	195	Off Idle	46.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.67	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:5	35.45	2812	2.24	13.56	111	195	Off Idle	46.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.64	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:5	35.45	2813	2.25	13.56	111	195	Off Idle	46.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.61	15.26	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:5	35.45	2816	2.25	13.54	111	196	Off Idle	46.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.56	15.3	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:5	35.45	2818	2.26	13.55	111	196	Off Idle	47	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.56	15.32	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:5	35.45	2827	2.26	13.54	111	196	Off Idle	47.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.54	15.34	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:6	35.45	2828	2.26	13.52	111	196	Off Idle	47.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.5	15.35	1.05	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:6	35.45	2835	2.26	13.54	111	196	Off Idle	47.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.49	15.33	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:6	35.45	2834	2.26	13.54	111	196	Off Idle	47.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.51	15.28	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:6	35.45	2833	2.27	13.54	111	196	Off Idle	47.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.5	15.19	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:6	35.45	2835	2.27	13.55	110	196	Off Idle	47.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.49	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:6	35.45	2838	2.27	13.55	110	196	Off Idle	47.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.47	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:6	35.45	2838	2.27	13.55	111	195	Off Idle	47.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.44	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:7	35.45	2838	2.27	13.55	111	195	Off Idle	47.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.38	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:37:7	35.45	2857	2.28	13.55	111	195	Off Idle	47.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.32	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:37:7	35.45	2834	2.28	13.54	111	195	Off Idle	47.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.22	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:37:7	35.45	2833	2.29	13.55	111	195	Off Idle	47.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.16	14.74	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:37:7	35.45	2835	2.3	13.55	111	196	Off Idle	47.6	0	2	132	944 Turbo	0.7	Lean	1	14.6	-6.03	14.71	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:37:7	35.45	2838	2.3	13.54	110	196	Off Idle	47.4	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.94	14.72	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:37:8	35.45	2839	2.31	13.56	110	196	Off Idle	47.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.89	14.72	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:37:8	35.45	2840	2.32	13.56	110	196	Off Idle	47.1	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.78	14.71	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:37:8	35.45	2846	2.33	13.56	111	196	Off Idle	47.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.67	14.73	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:8	35.45	2849	2.34	13.56	111	196	Off Idle	47.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.56	14.75	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:8	35.45	2810	2.35	13.56	111	196	Off Idle	47	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.52	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:8	35.45	2832	2.36	13.56	110	196	Off Idle	47	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.5	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:9	35.45	2851	2.37	13.55	110	196	Off Idle	47	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.48	14.76	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:9	34.08	2849	2.38	13.55	111	196	Off Idle	47	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.45	14.78	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:9	34.08	2848	2.38	13.55	111	196	Off Idle	47	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.41	14.83	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:9	34.08	2840	2.4	13.54	111	196	Off Idle	47	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.39	14.88	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:37:9	34.08	2837	2.41	13.53	110	196	Off Idle	47	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.34	14.96	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:37:9	34.08	2838	2.41	13.52	110	196	Off Idle	47	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.29	15.01	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:37:9	34.08	2838	2.42	13.51	111	196	Off Idle	47.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.27	15.07	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:0	34.08	2840	2.43	13.53	111	196	Off Idle	47.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.26	15.11	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:0	34.08	2854	2.43	13.54	111	196	Off Idle	47.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.28	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:0	34.08	2854	2.44	13.56	110	196	Off Idle	47.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.28	15.21	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:0	34.08	2846	2.44	13.55	110	196	Off Idle	47.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.28	15.21	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:0	34.08	2840	2.44	13.57	111	196	Off Idle	47.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.26	15.17	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:0	34.08	2851	2.44	13.56	111	196	Off Idle	48	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.31	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:1	34.08	2852	2.45	13.55	111	196	Off Idle	48	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.29	15.08	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:1	34.08	2843	2.45	13.55	110	196	Off Idle	47.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.29	15.02	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:1	34.08	2852	2.45	13.54	110	196	Off Idle	47.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.26	14.94	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:1	34.08	2852	2.45	13.54	110	196	Off Idle	47.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.25	14.89	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:1	34.08	2849	2.45	13.54	110	196	Off Idle	47.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.28	14.85	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:1	34.08	2847	2.45	13.53	110	196	Off Idle	47.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.23	14.77	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:1	34.08	2847	2.45	13.54	110	196	Off Idle	47.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.25	14.74	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:2	34.08	2849	2.45	13.53	110	196	Off Idle	47.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.27	14.69	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:2	34.08	2853	2.45	13.53	110	196	Off Idle	47.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.24	14.69	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:2	34.08	2858	2.45	13.52	110	196	Off Idle	47.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.22	14.7	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:2	34.08	2858	2.45	13.53	110	196	Off Idle	47	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.22	14.71	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:2	34.08	2858	2.45	13.53	110	196	Off Idle	46.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.19	14.74	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:2	34.08	2877	2.45	13.55	110	196	Off Idle	46.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.23	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:3	34.08	2858	2.45	13.55	110	196	Off Idle	46.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.23	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:3	34.08	2858	2.45	13.55	110	196	Off Idle	46.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.19	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:3	34.08	2854	2.45	13.55	110	196	Off Idle	46.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.24	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:3	34.08	2852	2.45	13.54	110	196	Off Idle	46.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.24	14.81	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:3	34.08	2850	2.45	13.53	110	196	Off Idle	46.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.22	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:3	34.08	2852	2.45	13.52	110	196	Off Idle	46.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.22	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:4	34.08	2852	2.45	13.52	110	196	Off Idle	46.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.24	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:4	34.08	2860	2.45	13.54	110	196	Off Idle	46.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.23	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:4	34.08	2884	2.45	13.52	110	196	Off Idle	46.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.19	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:4	34.08	2876	2.45	13.54	110	196	Off Idle	46.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.19	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:4	34.08	2866	2.45	13.52	110	196	Off Idle	46.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.2	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:4	34.08	2870	2.45	13.53	110	196	Off Idle	46.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.21	14.9	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:4	34.08	2869	2.46	13.52	111	196	Off Idle	46.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.17	14.97	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:5	34.08	2856	2.46	13.53	111	196	Off Idle	46.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.15	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:5	34.08	2863	2.46	13.54	111	196	Off Idle	46.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.05	15.05	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:5	34.08	2864	2.46	13.54	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.01	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:5	34.08	2866	2.47	13.54	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.98	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:5	34.08	2874	2.47	13.54	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.96	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:5	34.08	2874	2.47	13.53	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.93	15.14	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:6	34.08	2872	2.48	13.54	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.94	15.14	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:6	34.08	2872	2.48	13.55	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.92	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:6	34.08	2865	2.48	13.55	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.64	Lean	1	14.6	-4.97	15.16	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:6	34.08	2865	2.49	13.55	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.68	Lean	1	14.6	-4.93	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:38:6	34.08	2864	2.49	13.54	111	196	Off Idle	45.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.88	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:38:6	34.08	2864	2.49	13.54	111	196	Off Idle	45.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.87	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:6	34.08	2866	2.5	13.54	111	196	Off Idle	45.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.86	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:7	34.08	2870	2.5	13.54	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.79	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:7	34.08	2870	2.5	13.53	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.77	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:7	34.08	2873	2.5	13.53	110	196	Off Idle	45.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.77	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:7	34.08	2873	2.51	13.54	110	196	Off Idle	45.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.81	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:7	34.08	2870	2.51	13.54	110	196	Off Idle	45.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.83	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:7	34.08	2877	2.51	13.54	110	196	Off Idle	45.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.87	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:8	34.08	2877	2.51	13.55	110	196	Off Idle	45.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.81	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:8	34.08	2876	2.51	13.56	110	196	Off Idle	45.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.8	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:8	34.08	2878	2.51	13.56	110	196	Off Idle	45.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.79	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:8	34.08	2873	2.51	13.55	110	196	Off Idle	45.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.8	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:8	34.08	2873	2.51	13.55	110	196	Off Idle	45	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.83	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:8	34.08	2874	2.51	13.55	110	195	Off Idle	45	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.87	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:9	34.08	2871	2.51	13.55	110	195	Off Idle	45	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.9	14.74	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:9	34.08	2878	2.51	13.54	110	195	Off Idle	44.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.86	14.74	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:9	34.08	2878	2.52	13.55	111	196	Off Idle	45	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.85	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:9	34.08	2878	2.52	13.54	111	196	Off Idle	45	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.84	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:9	34.08	2884	2.52	13.54	111	196	Off Idle	45.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.83	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:38:9	34.08	2885	2.52	13.53	111	196	Off Idle	45.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.83	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:38:9	34.08	2886	2.52	13.56	111	196	Off Idle	45.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.8	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:0	34.08	2888	2.52	13.55	110	196	Off Idle	45.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.88	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:0	34.08	2882	2.52	13.55	110	196	Off Idle	45.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.87	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:0	34.08	2880	2.52	13.55	110	196	Off Idle	45.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.87	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:0	34.08	2876	2.52	13.54	110	196	Off Idle	45.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.88	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:0	34.08	2874	2.52	13.53	110	196	Off Idle	45.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.86	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:0	34.08	2876	2.52	13.53	110	196	Off Idle	45.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.84	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:1	34.08	2878	2.52	13.54	110	196	Off Idle	45.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.81	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:1	34.08	2911	2.52	13.55	110	196	Off Idle	45.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.84	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:1	34.08	2901	2.52	13.53	110	196	Off Idle	45.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.81	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:1	34.08	2898	2.52	13.54	110	196	Off Idle	45.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.87	14.9	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:1	34.08	2900	2.52	13.55	110	196	Off Idle	45.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.85	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:1	34.08	2878	2.52	13.53	110	196	Off Idle	45.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.84	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:1	34.08	2886	2.52	13.52	110	196	Off Idle	45.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.84	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:2	34.08	2887	2.52	13.51	110	196	Off Idle	45.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.78	15	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:2	34.08	2882	2.52	13.53	110	196	Off Idle	45.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.78	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:2	34.08	2882	2.52	13.53	110	196	Off Idle	45.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.81	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:2	34.08	2892	2.52	13.52	110	196	Off Idle	45.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.82	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:2	34.08	2883	2.52	13.52	110	196	Off Idle	45	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.86	15.16	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:2	34.08	2887	2.52	13.54	110	196	Off Idle	44.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.86	15.14	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:3	34.08	2897	2.52	13.55	110	196	Off Idle	44.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.82	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:3	34.08	2897	2.52	13.55	110	196	Off Idle	44.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.82	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:3	34.08	2890	2.52	13.56	110	195	Off Idle	44.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.85	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:3	34.08	2900	2.52	13.55	110	195	Off Idle	44.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.84	14.99	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:3	34.08	2901	2.52	13.54	110	195	Off Idle	44.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.84	14.95	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:3	34.08	2900	2.52	13.53	110	195	Off Idle	44.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.82	14.93	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:4	34.08	2896	2.52	13.54	110	196	Off Idle	44.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.81	14.83	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:4	34.08	2888	2.52	13.53	110	196	Off Idle	44.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.86	14.8	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:4	34.08	2884	2.52	13.54	110	196	Off Idle	44.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.84	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:4	34.08	2885	2.52	13.53	110	196	Off Idle	44.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.82	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:4	34.08	2889	2.52	13.52	110	196	Off Idle	44.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.81	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:4	34.08	2893	2.52	13.53	110	196	Off Idle	44.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.79	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:4	34.08	2894	2.52	13.53	110	196	Off Idle	44.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.85	14.85	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:5	34.08	2900	2.52	13.54	110	196	Off Idle	44	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.86	14.86	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:5	34.08	2905	2.52	13.55	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.82	14.84	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:5	34.08	2907	2.53	13.56	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.83	14.84	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:5	34.08	2912	2.53	13.56	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.79	14.84	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:5	34.08	2908	2.53	13.55	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.78	14.87	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:39:5	34.08	2900	2.53	13.56	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.79	14.89	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:6	34.08	2898	2.53	13.55	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.82	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:6	34.08	2898	2.53	13.55	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.84	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:6	34.08	2898	2.53	13.55	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.82	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:6	34.08	2907	2.53	13.54	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.81	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:6	34.08	2907	2.53	13.54	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.78	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:6	34.08	2898	2.53	13.53	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.78	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:6	34.08	2902	2.53	13.54	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.8	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:7	34.08	2901	2.53	13.53	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.78	15.09	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:7	34.08	2906	2.53	13.54	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.78	15.06	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:7	34.08	2902	2.53	13.54	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.82	15.03	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:7	34.08	2901	2.53	13.54	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.81	15.01	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:7	34.08	2904	2.53	13.54	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.82	14.97	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:7	34.08	2905	2.53	13.54	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.82	14.95	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:8	34.08	2910	2.53	13.55	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.86	14.93	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:8	34.08	2917	2.53	13.55	110	196	Off Idle	43.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.88	14.88	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:8	34.08	2918	2.53	13.55	110	196	Off Idle	43.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.87	14.86	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:8	34.08	2920	2.53	13.54	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.87	14.85	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:8	34.08	2919	2.53	13.53	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.88	14.83	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:8	34.08	2915	2.53	13.51	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.89	14.83	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:9	34.08	2916	2.53	13.52	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.86	14.85	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:39:9	34.08	2912	2.53	13.51	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.85	14.88	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:9	34.08	2909	2.53	13.52	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.85	14.9	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:9	34.08	2909	2.53	13.53	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.87	14.91	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:39:9	34.08	2911	2.53	13.54	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.87	14.92	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:9	34.08	2913	2.52	13.54	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.91	14.95	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:39:9	34.08	2915	2.52	13.54	110	196	Off Idle	43.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.92	15.01	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:0	34.08	2916	2.52	13.53	110	196	Off Idle	43.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.92	15.05	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:0	34.08	2939	2.52	13.53	110	196	Off Idle	43.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.92	15.06	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:0	34.08	2919	2.52	13.53	110	196	Off Idle	42.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.88	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:0	34.08	2921	2.52	13.53	110	196	Off Idle	42.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.95	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:0	34.08	2921	2.52	13.53	110	196	Off Idle	42.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.93	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:0	34.08	2914	2.52	13.53	110	196	Off Idle	42.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.97	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:1	34.08	2891	2.52	13.53	110	196	Off Idle	42.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.98	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:1	34.08	2902	2.52	13.53	110	196	Off Idle	42.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.93	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:1	34.08	2917	2.52	13.53	110	196	Off Idle	42.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.92	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:1	34.08	2921	2.52	13.53	110	196	Off Idle	42.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.93	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:1	34.08	2920	2.51	13.54	110	196	Off Idle	42.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.91	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:1	34.08	2920	2.51	13.54	110	196	Off Idle	42.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.93	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:1	34.08	2921	2.51	13.53	110	196	Off Idle	42.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.95	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:2	34.08	2922	2.51	13.51	110	196	Off Idle	42.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.95	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:2	34.08	2923	2.51	13.5	110	196	Off Idle	42.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.98	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:2	34.08	2902	2.51	13.51	110	196	Off Idle	43.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.98	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:2	34.08	2925	2.51	13.51	110	195	Off Idle	43.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.96	14.92	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:2	34.08	2924	2.51	13.53	110	195	Off Idle	43.1	0	2	132	944 Turbo	0.21	Rich	1	14.6	-4.98	14.95	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:2	34.08	2920	2.51	13.54	110	195	Off Idle	43.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-4.97	14.99	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:3	34.08	2920	2.51	13.55	110	195	Off Idle	43.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.01	15.02	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:3	34.08	2920	2.51	13.54	110	195	Off Idle	43.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5	15.06	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:3	34.08	2932	2.51	13.55	110	195	Off Idle	43.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.98	15.09	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:3	34.08	2931	2.51	13.55	110	196	Off Idle	43.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.98	15.13	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:3	34.08	2933	2.51	13.53	110	196	Off Idle	42.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.98	15.15	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:3	34.08	2944	2.51	13.53	110	196	Off Idle	42.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.95	15.13	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:4	34.08	2926	2.51	13.53	110	196	Off Idle	42.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:4	34.08	2926	2.51	13.52	110	196	Off Idle	42.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:4	34.08	2927	2.51	13.52	110	196	Off Idle	42.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:4	34.08	2940	2.51	13.52	110	196	Off Idle	42.1	0	2	132	944 Turbo	0.69	Lean	1	14.6	-4.99	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:4	34.08	2940	2.51	13.53	110	196	Off Idle	42	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.03	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:4	34.08	2929	2.51	13.53	110	196	Off Idle	41.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.99	14.88	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:40:4	34.08	2925	2.51	13.53	110	196	Off Idle	41.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.02	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:5	34.08	2926	2.51	13.53	110	196	Off Idle	41.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5	14.79	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:5	34.08	2926	2.51	13.54	110	196	Off Idle	42	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5	14.78	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:5	34.08	2932	2.51	13.52	110	196	Off Idle	42	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.05	14.76	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:5	34.08	2942	2.51	13.5	110	196	Off Idle	42.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.99	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:5	34.08	2949	2.51	13.5	110	196	Off Idle	42.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.97	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:5	34.08	2948	2.51	13.51	110	196	Off Idle	42.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.99	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:6	34.08	2943	2.51	13.52	110	196	Off Idle	42.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.96	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:6	34.08	2942	2.51	13.52	110	196	Off Idle	42.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.97	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:6	34.08	2936	2.51	13.53	110	195	Off Idle	42.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.93	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:6	34.08	2939	2.51	13.54	110	195	Off Idle	42.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.97	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:6	34.08	2929	2.51	13.53	110	195	Off Idle	42.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.98	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:6	34.08	2928	2.51	13.55	110	195	Off Idle	42.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.01	15.07	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:6	34.08	2931	2.51	13.55	110	195	Off Idle	42.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.02	15.1	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:7	34.08	2937	2.51	13.55	110	195	Off Idle	42.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.01	15.12	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:7	34.08	2937	2.52	13.55	110	195	Off Idle	42.1	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:7	34.08	2934	2.52	13.55	110	195	Off Idle	42.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.99	15.14	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:7	34.08	2928	2.52	13.54	110	196	Off Idle	42.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.93	15.14	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:40:7	34.08	2943	2.52	13.54	110	196	Off Idle	42	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.93	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:7	34.08	2934	2.52	13.54	110	196	Off Idle	42	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.88	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:8	34.08	2949	2.52	13.54	110	196	Off Idle	42.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.87	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:8	34.08	2954	2.52	13.54	110	195	Off Idle	42.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.87	15.01	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:8	34.08	2953	2.52	13.52	110	195	Off Idle	42.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.84	14.99	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:8	34.08	2953	2.52	13.53	110	196	Off Idle	42.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-4.85	14.94	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:8	34.08	2950	2.52	13.54	110	196	Off Idle	42.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-4.87	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:8	34.08	2943	2.53	13.53	110	196	Off Idle	42.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.91	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:40:9	34.08	2942	2.53	13.55	110	196	Off Idle	42.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.93	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:9	34.08	2937	2.53	13.54	110	196	Off Idle	42.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.94	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:9	34.08	2942	2.53	13.55	110	195	Off Idle	42.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.9	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:9	34.08	2942	2.53	13.55	110	195	Off Idle	42.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.9	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:9	34.08	2945	2.53	13.53	110	195	Off Idle	42.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.85	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:9	34.08	2950	2.53	13.53	110	196	Off Idle	41.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.86	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:40:9	34.08	2954	2.54	13.53	110	196	Off Idle	41.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.88	15.04	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:0	34.08	2956	2.54	13.53	110	196	Off Idle	41.7	0	2	132	944 Turbo	0.63	Lean	1	14.6	-4.87	15.04	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:0	34.08	2960	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.67	Lean	1	14.6	-4.89	15.04	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:0	34.08	2958	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.89	15.02	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:0	34.08	3002	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.9	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:0	34.08	2978	2.54	13.54	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.89	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:0	34.08	2952	2.54	13.55	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.92	14.93	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:1	34.08	2952	2.54	13.53	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.94	14.92	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:1	34.08	2926	2.54	13.53	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.92	14.89	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:1	34.08	2935	2.54	13.53	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.92	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:1	34.08	2948	2.55	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.88	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:1	34.08	2953	2.55	13.52	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.86	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:1	34.08	2956	2.54	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.87	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:1	34.08	2949	2.54	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.87	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:2	34.08	2962	2.55	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.87	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:2	34.08	2965	2.55	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.87	14.85	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:2	34.08	2965	2.55	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.91	14.86	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:2	34.08	2987	2.55	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.93	14.87	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:2	34.08	2958	2.55	13.52	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.93	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:2	34.08	2957	2.55	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.89	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:3	34.08	2958	2.55	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.9	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:3	34.08	2966	2.55	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.84	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:3	34.08	2955	2.54	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-4.83	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:3	34.08	2957	2.54	13.54	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.83	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:3	34.08	2958	2.54	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.84	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:3	34.08	2964	2.54	13.54	110	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.87	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:41:4	34.08	2956	2.54	13.55	110	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.87	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:4	34.08	2967	2.54	13.55	110	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.92	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:4	34.08	2968	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.96	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:4	34.08	2969	2.54	13.56	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.97	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:4	34.08	2970	2.54	13.56	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.96	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:4	34.08	2969	2.54	13.56	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.97	14.88	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:4	35.45	2982	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.97	14.85	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:5	35.45	2974	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.96	14.84	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:5	35.45	2968	2.54	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.95	14.84	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:5	35.45	2966	2.54	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.96	14.85	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:5	35.45	2966	2.54	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.96	14.87	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:5	35.45	2966	2.54	13.54	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.98	14.89	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:5	35.45	2969	2.54	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.95	14.92	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:6	35.45	2980	2.54	13.54	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.95	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:41:6	35.45	2968	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.98	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:6	35.45	2974	2.54	13.53	110	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.94	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:6	34.08	2974	2.54	13.54	110	196	Off Idle	41.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.98	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:6	34.08	2974	2.54	13.53	110	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.95	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:6	34.08	2967	2.54	13.53	110	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.97	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:6	34.08	2965	2.54	13.54	110	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.01	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:7	34.08	2967	2.54	13.55	110	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.01	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:7	34.08	2967	2.54	13.56	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:7	34.08	2972	2.54	13.54	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.98	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:7	34.08	2976	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.98	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:7	34.08	2982	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.98	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:7	34.08	2982	2.54	13.52	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.96	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:8	35.45	2984	2.54	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-4.99	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:8	35.45	2982	2.54	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.99	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:8	35.45	2980	2.54	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.99	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:8	35.45	2980	2.54	13.51	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:8	35.45	2988	2.54	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.98	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:8	35.45	2989	2.54	13.52	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.03	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:9	35.45	2992	2.54	13.51	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.02	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:9	35.45	2996	2.54	13.52	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.04	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:9	35.45	2992	2.54	13.5	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.1	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:9	35.45	2992	2.54	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.11	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:41:9	35.45	2989	2.54	13.51	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.1	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:9	35.45	2988	2.54	13.51	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.07	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:41:9	35.45	2983	2.54	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.06	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:0	35.45	2985	2.54	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.06	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:0	35.45	2983	2.54	13.53	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.04	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:0	35.45	2984	2.54	13.55	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.08	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:0	35.45	2990	2.54	13.54	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.01	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:0	35.45	2989	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.96	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:0	35.45	2987	2.54	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.98	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:1	35.45	2987	2.54	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.95	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:1	35.45	2987	2.54	13.54	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.9	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:1	35.45	2995	2.54	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.94	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:1	35.45	2993	2.54	13.51	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.95	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:1	35.45	2994	2.54	13.51	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.97	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:1	35.45	2994	2.54	13.52	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.97	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:1	35.45	3000	2.54	13.53	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.98	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:2	35.45	2997	2.54	13.54	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.97	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:2	35.45	2996	2.54	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:42:2	35.45	2994	2.54	13.56	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.02	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:42:2	35.45	2994	2.54	13.56	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.04	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:2	35.45	2992	2.54	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.04	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:2	35.45	2990	2.53	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.07	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:42:3	35.45	2990	2.53	13.55	110	195	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.11	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:3	35.45	2994	2.53	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.18	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:3	35.45	3004	2.53	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.16	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:3	35.45	3003	2.53	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.19	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:42:3	35.45	3004	2.52	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.25	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:42:3	35.45	3007	2.52	13.55	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.3	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:42:4	35.45	3002	2.52	13.54	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.41	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:08:42:4	35.45	3003	2.51	13.53	110	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.4	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:42:4	35.45	2998	2.5	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.5	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:42:4	35.45	3008	2.5	13.52	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.5	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:42:4	35.45	2993	2.49	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.61	14.93	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:42:4	35.45	2994	2.48	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.63	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:42:4	35.45	2988	2.47	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.78	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:08:42:5	35.45	3007	2.46	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.86	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:42:5	35.45	3007	2.45	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.95	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:42:5	35.45	3006	2.44	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.03	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:42:5	35.45	3007	2.43	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.12	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:42:5	35.45	3001	2.41	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.23	Rich	1	14.6	-6.26	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:42:5	35.45	2996	2.4	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.34	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:08:42:6	35.45	2996	2.38	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.53	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:42:6	35.45	2992	2.36	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.6	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:42:6	35.45	2991	2.35	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.73	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:42:6	35.45	2991	2.33	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.83	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:42:6	35.45	2999	2.31	13.55	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.92	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:42:6	35.45	2990	2.28	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.07	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:42:6	35.45	2992	2.26	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.16	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:42:7	35.45	2991	2.24	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.32	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:7	35.45	2978	2.22	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.54	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:7	35.45	2988	2.2	13.51	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.66	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:08:42:7	35.45	2988	2.17	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.82	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:7	35.45	2975	2.14	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.88	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:7	35.45	2976	2.13	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.03	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:8	35.45	2975	2.11	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.21	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:8	35.45	2977	2.09	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.4	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:42:8	36.81	2982	2.07	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.5	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:42:8	36.81	2981	2.05	13.53	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.59	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:42:8	36.81	2980	2.02	13.54	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.66	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:42:8	36.81	2972	1.98	13.56	110	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.83	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:42:9	36.81	2972	1.97	13.57	110	195	Full Load	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.95	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:42:9	36.81	2977	1.94	13.56	110	195	Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.11	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:42:9	36.81	2964	1.9	13.56	110	195	Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.25	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:42:9	36.81	2968	1.88	13.56	110	195	Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.31	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:42:9	36.81	2967	1.86	13.54	110	195	Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.37	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:42:9	36.81	2964	1.84	13.55	110	195	Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.47	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:42:9	34.08	2941	1.82	13.56	110	195	Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.53	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:0	28.63	2913	1.8	13.56	110	195	Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.6	14.8	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:0	28.63	2900	1.78	13.57	110	195	Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.62	14.81	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:0	23.18	2900	1.76	13.57	110	195	Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.67	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:0	19.09	2924	1.75	13.57	110	195	Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.69	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:0	19.09	2923	1.74	13.57	110	195	Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.7	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:0	19.09	2923	1.73	13.55	110	195	Idle	41.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.7	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:1	19.09	2903	1.72	13.56	110	195	Idle	41.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.7	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:1	19.09	2934	1.71	13.55	110	195	Idle	41.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.72	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:1	19.09	2940	1.71	13.55	110	195	Idle	42.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.75	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:1	19.09	2970	1.7	13.56	110	195	Idle	42.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.77	15.18	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:1	19.09	2952	1.7	13.56	110	195	Idle	42.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.8	15.19	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:1	19.09	2954	1.7	13.56	110	195	Idle	42.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.78	15.21	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:1	19.09	2963	1.7	13.56	110	195	Idle	42.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.74	15.2	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:43:2	19.09	2965	1.7	13.56	110	195	Idle	42.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.74	15.2	1.04	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:2	19.09	3008	1.7	13.56	110	195	Idle	42.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.71	15.19	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:2	19.09	3008	1.7	13.56	110	195	Idle	42.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.66	15.18	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:2	19.09	2934	1.7	13.56	110	195	Idle	42.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.62	15.17	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:2	19.09	2951	1.7	13.55	110	195	Idle	42.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.64	15.16	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:2	19.09	2943	1.69	13.55	110	195	Idle	41.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.62	15.15	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:3	19.09	2942	1.69	13.55	110	195	Idle	41.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.56	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:3	19.09	2934	1.69	13.54	110	195	Idle	41.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.56	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:3	19.09	2931	1.69	13.55	110	195	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.53	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:3	19.09	2931	1.69	13.55	110	195	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.51	15.12	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:3	19.09	2932	1.69	13.54	110	195	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.5	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:3	19.09	2954	1.69	13.53	110	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.48	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:4	19.09	2933	1.69	13.54	110	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	15.14	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:4	19.09	2922	1.69	13.55	110	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.52	15.16	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:4	19.09	2932	1.7	13.55	110	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	15.23	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:4	19.09	2931	1.7	13.55	110	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	15.34	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:4	19.09	2931	1.7	13.54	110	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	15.42	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:4	19.09	2925	1.7	13.54	110	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	15.81	1.08	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:4	19.09	2902	1.7	13.53	110	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	16.48	1.12	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:5	19.09	2920	1.7	13.54	110	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.47	16.98	1.16	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:5	19.09	2920	1.7	13.54	110	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	17.49	1.19	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:5	19.09	2940	1.7	13.52	110	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.47	17.99	1.23	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:5	19.09	2926	1.7	13.54	110	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	18.72	1.27	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:5	19.09	2921	1.7	13.56	110	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	19.17	1.31	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:5	19.09	2907	1.7	13.55	110	195	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	19.76	1.35	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:6	19.09	2906	1.7	13.55	110	195	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.04	1.36	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:6	19.09	2884	1.7	13.56	110	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.18	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:6	19.09	2906	1.7	13.56	110	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:6	19.09	2903	1.7	13.54	110	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:6	19.09	2904	1.7	13.55	109	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:6	19.09	2902	1.7	13.54	109	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:6	19.09	2879	1.7	13.54	109	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.47	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:7	19.09	2900	1.7	13.54	110	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:7	19.09	2899	1.7	13.55	110	195	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:7	19.09	2918	1.7	13.56	110	195	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:7	19.09	2918	1.7	13.56	110	195	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:7	19.09	2892	1.7	13.55	110	195	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:7	19.09	2888	1.7	13.54	110	195	Idle	42.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:8	19.09	2883	1.7	13.54	110	195	Idle	42.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:8	19.09	2883	1.7	13.54	110	195	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:8	19.09	2880	1.7	13.56	110	195	Idle	42.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:8	19.09	2878	1.7	13.54	110	195	Idle	42.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:8	19.09	2898	1.7	13.55	110	195	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:8	19.09	2876	1.7	13.54	110	195	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:9	19.09	2874	1.7	13.53	110	195	Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:9	19.09	2862	1.7	13.54	110	195	Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:9	19.09	2873	1.7	13.54	110	195	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:9	19.09	2874	1.69	13.53	110	195	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:9	19.09	2884	1.69	13.54	110	195	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:9	19.09	2871	1.69	13.56	110	195	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:43:9	19.09	2856	1.69	13.56	110	195	Idle	43.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:0	19.09	2865	1.69	13.55	110	195	Idle	43.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:0	19.09	2862	1.68	13.54	110	195	Idle	43.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:0	19.09	2860	1.68	13.56	110	195	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:0	19.09	2863	1.68	13.54	110	195	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:0	19.09	2867	1.68	13.55	110	195	Idle	44.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:0	19.09	2878	1.68	13.56	110	195	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:1	19.09	2871	1.68	13.57	110	195	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:44:1	19.09	2873	1.68	13.57	110	195	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:1	19.09	2873	1.68	13.57	110	195	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:1	19.09	2872	1.68	13.56	110	195	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:1	19.09	2869	1.67	13.56	110	195	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:1	19.09	2862	1.67	13.54	110	195	Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:1	19.09	2846	1.67	13.55	110	195	Idle	44.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:2	19.09	2852	1.67	13.55	110	195	Idle	45.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:2	19.09	2820	1.67	13.55	110	195	Idle	45.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:2	19.09	2828	1.67	13.55	110	196	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:2	19.09	2834	1.67	13.55	110	196	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:2	19.09	2834	1.67	13.56	109	195	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:2	19.09	2833	1.66	13.55	109	195	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:3	19.09	2832	1.66	13.54	110	195	Idle	46.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:3	19.09	2814	1.66	13.54	110	195	Idle	46.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:3	19.09	2824	1.66	13.54	110	195	Idle	46.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:3	19.09	2835	1.66	13.53	110	195	Idle	46.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:3	19.09	2835	1.66	13.54	110	195	Idle	46.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:3	19.09	2835	1.65	13.55	110	195	Idle	46.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:4	19.09	2844	1.65	13.55	110	195	Idle	46.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:4	19.09	2831	1.65	13.55	110	195	Idle	46.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:4	19.09	2829	1.65	13.56	110	195	Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:4	19.09	2828	1.65	13.56	110	195	Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:4	19.09	2824	1.65	13.56	110	195	Idle	46.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:4	19.09	2801	1.65	13.55	110	195	Idle	46.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:4	19.09	2801	1.64	13.55	110	195	Idle	47	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:5	19.09	2816	1.64	13.55	110	195	Idle	47.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:5	19.09	2834	1.64	13.55	110	195	Idle	47.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:5	19.09	2809	1.64	13.55	110	195	Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:5	19.09	2809	1.64	13.56	110	195	Idle	47.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:5	19.09	2798	1.63	13.55	110	195	Idle	47.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:5	19.09	2809	1.63	13.55	110	195	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:6	19.09	2810	1.63	13.56	110	195	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:6	19.09	2809	1.63	13.55	110	195	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:6	19.09	2810	1.63	13.55	110	195	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:6	19.09	2810	1.63	13.55	110	195	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:6	19.09	2808	1.62	13.56	110	195	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:6	19.09	2806	1.62	13.55	110	195	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:6	19.09	2806	1.62	13.56	110	195	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:7	19.09	2803	1.62	13.55	110	195	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:7	19.09	2800	1.62	13.56	110	195	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:7	19.09	2798	1.62	13.56	110	195	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:7	19.09	2798	1.62	13.56	109	195	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:7	19.09	2807	1.62	13.56	109	195	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:7	19.09	2793	1.62	13.56	110	195	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:8	19.09	2794	1.61	13.57	110	195	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:8	19.09	2790	1.61	13.58	110	195	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:8	19.09	2778	1.61	13.57	110	195	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:8	19.09	2784	1.61	13.57	110	195	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:8	19.09	2779	1.61	13.56	110	195	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:8	19.09	2767	1.62	13.55	110	195	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:9	19.09	2776	1.62	13.55	110	195	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:9	19.09	2768	1.62	13.55	110	195	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:9	19.09	2768	1.61	13.55	110	195	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:9	19.09	2764	1.61	13.55	110	195	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:9	19.09	2773	1.61	13.55	109	195	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:9	19.09	2760	1.61	13.56	109	195	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:44:9	19.09	2760	1.61	13.54	109	195	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:0	19.09	2760	1.61	13.55	109	195	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:45:0	19.09	2752	1.61	13.55	109	195	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:0	19.09	2777	1.61	13.55	109	195	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:0	19.09	2767	1.61	13.56	110	195	Idle	49	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:0	19.09	2769	1.61	13.55	110	195	Idle	49.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:0	19.09	2768	1.61	13.55	109	195	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:1	19.09	2766	1.61	13.56	109	195	Idle	49.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:1	19.09	2766	1.61	13.56	109	195	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:1	19.09	2754	1.6	13.56	109	195	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:1	19.09	2760	1.6	13.55	109	195	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:1	19.09	2780	1.6	13.56	109	195	Idle	50	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:1	19.09	2749	1.59	13.56	110	195	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:1	19.09	2723	1.59	13.56	110	195	Idle	50.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:2	19.09	2723	1.59	13.57	110	195	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:2	19.09	2740	1.59	13.56	109	195	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:2	19.09	2738	1.58	13.56	109	195	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:2	19.09	2738	1.58	13.56	109	195	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:2	19.09	2736	1.58	13.57	110	195	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:2	19.09	2744	1.57	13.56	110	195	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:3	19.09	2741	1.57	13.57	110	195	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:3	19.09	2736	1.57	13.56	109	195	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:3	19.09	2736	1.57	13.56	109	195	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:3	19.09	2735	1.57	13.56	109	195	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:3	19.09	2735	1.56	13.55	109	195	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:3	19.09	2733	1.56	13.56	109	195	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:4	19.09	2730	1.56	13.55	109	195	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:4	19.09	2730	1.56	13.56	109	195	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:4	19.09	2725	1.56	13.56	109	195	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:4	19.09	2740	1.56	13.55	109	195	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:4	19.09	2717	1.56	13.56	109	195	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:4	19.09	2716	1.56	13.56	109	195	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:4	19.09	2703	1.56	13.56	109	195	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:5	19.09	2713	1.56	13.55	109	195	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:5	19.09	2692	1.56	13.57	109	195	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:5	19.09	2692	1.56	13.56	109	195	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:5	19.09	2709	1.56	13.56	109	195	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:5	19.09	2711	1.56	13.55	109	195	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:5	19.09	2712	1.56	13.55	109	195	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:6	19.09	2711	1.55	13.56	109	195	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:6	19.09	2711	1.55	13.56	109	195	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:6	19.09	2711	1.55	13.56	110	195	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:6	19.09	2710	1.55	13.56	110	195	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:6	19.09	2709	1.54	13.56	109	195	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:6	19.09	2708	1.54	13.55	109	195	Idle	52.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:6	19.09	2706	1.54	13.54	109	195	Idle	53.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:7	19.09	2700	1.53	13.55	110	195	Idle	53.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:7	19.09	2697	1.53	13.55	110	195	Idle	53.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:7	19.09	2697	1.53	13.55	110	195	Idle	53.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:7	19.09	2694	1.53	13.55	109	195	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:7	19.09	2704	1.53	13.56	109	195	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:7	19.09	2692	1.53	13.54	109	195	Idle	54.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:8	19.09	2680	1.52	13.55	109	195	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:8	19.09	2680	1.52	13.55	109	195	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:8	19.09	2688	1.52	13.55	109	195	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:8	19.09	2688	1.52	13.55	110	195	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:8	19.09	2685	1.52	13.56	110	195	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:8	19.09	2682	1.51	13.56	110	195	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:9	19.09	2682	1.51	13.56	109	195	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:9	19.09	2682	1.51	13.56	109	195	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:45:9	19.09	2679	1.51	13.56	109	195	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:9	19.09	2678	1.51	13.56	109	195	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:9	19.09	2674	1.51	13.57	109	195	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:9	19.09	2671	1.51	13.56	109	195	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:45:9	19.09	2667	1.51	13.56	109	195	Idle	54.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:0	19.09	2667	1.51	13.56	109	195	Idle	54.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.09	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:0	19.09	2665	1.51	13.56	109	195	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.1	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:0	19.09	2665	1.51	13.55	109	195	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.1	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:0	19.09	2673	1.5	13.55	109	195	Idle	55.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.09	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:0	19.09	2662	1.5	13.54	109	195	Idle	55.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.1	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:0	19.09	2662	1.5	13.55	109	195	Idle	55.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.1	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:1	19.09	2662	1.5	13.54	109	195	Idle	55.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.1	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:1	19.09	2661	1.5	13.54	109	195	Idle	56.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.09	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:1	19.09	2657	1.49	13.55	109	195	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.09	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:1	19.09	2657	1.49	13.55	109	195	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.09	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:1	19.09	2654	1.49	13.55	109	195	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:1	19.09	2654	1.49	13.56	109	195	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:1	19.09	2651	1.49	13.55	109	195	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:2	19.09	2640	1.48	13.55	109	195	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:2	19.09	2646	1.48	13.56	109	195	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:2	19.09	2644	1.48	13.56	109	195	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:2	19.09	2641	1.47	13.55	109	195	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:2	19.09	2641	1.47	13.56	109	195	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:2	19.09	2630	1.47	13.56	109	195	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:3	19.09	2640	1.47	13.57	109	195	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:3	19.09	2639	1.46	13.56	109	195	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:3	19.09	2636	1.46	13.56	109	195	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:3	19.09	2640	1.46	13.57	109	195	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:3	19.09	2636	1.46	13.57	109	195	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:3	19.09	2635	1.46	13.55	109	195	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:4	19.09	2635	1.46	13.56	109	195	Idle	57.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:4	19.09	2633	1.45	13.56	109	195	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:4	19.09	2629	1.45	13.56	109	195	Idle	57.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:4	19.09	2629	1.45	13.55	109	195	Idle	57.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:4	19.09	2626	1.45	13.55	109	195	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:4	19.09	2624	1.45	13.55	109	195	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:4	19.09	2624	1.45	13.56	109	195	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:5	19.09	2622	1.45	13.56	109	195	Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:5	19.09	2617	1.45	13.56	109	195	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:5	19.09	2616	1.45	13.56	109	195	Idle	58.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:5	19.09	2626	1.45	13.56	109	195	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:5	19.09	2615	1.45	13.55	109	195	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:5	19.09	2613	1.44	13.54	109	195	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:6	19.09	2612	1.44	13.55	109	195	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:6	19.09	2614	1.44	13.55	109	195	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:6	19.09	2613	1.44	13.55	109	195	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:6	19.09	2612	1.44	13.55	109	195	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:6	19.09	2590	1.44	13.55	109	195	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:6	19.09	2608	1.43	13.55	109	195	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:6	19.09	2608	1.43	13.56	109	195	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:7	19.09	2626	1.43	13.56	109	195	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:7	19.09	2603	1.43	13.56	109	195	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:7	19.09	2603	1.43	13.56	109	195	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:7	19.09	2598	1.43	13.56	109	195	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:7	19.09	2598	1.43	13.55	109	195	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:7	19.09	2584	1.43	13.55	109	195	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:8	19.09	2592	1.42	13.56	109	195	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:8	19.09	2613	1.42	13.55	109	195	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:46:8	19.09	2602	1.42	13.54	109	195	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:8	19.09	2591	1.42	13.55	109	195	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:8	19.09	2590	1.42	13.55	109	195	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:8	19.09	2590	1.42	13.56	109	195	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:9	19.09	2567	1.42	13.55	109	195	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:9	19.09	2567	1.42	13.55	109	195	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:9	19.09	2584	1.42	13.55	109	195	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:9	19.09	2592	1.42	13.55	109	195	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:9	19.09	2592	1.42	13.55	109	195	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:9	19.09	2574	1.42	13.56	109	195	Idle	60	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:46:9	19.09	2573	1.41	13.56	109	195	Idle	60.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:0	19.09	2571	1.41	13.56	109	195	Idle	60.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:0	19.09	2567	1.41	13.55	109	195	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:0	19.09	2567	1.41	13.57	109	195	Idle	60.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:0	19.09	2588	1.41	13.56	109	195	Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:0	19.09	2566	1.4	13.57	109	195	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:0	19.09	2527	1.4	13.57	109	195	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:1	19.09	2547	1.4	13.57	109	195	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:1	19.09	2575	1.4	13.56	109	195	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:1	19.09	2563	1.4	13.55	109	195	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:1	19.09	2562	1.4	13.54	109	195	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:1	19.09	2572	1.4	13.55	109	195	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:1	19.09	2560	1.4	13.54	109	195	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:1	19.09	2536	1.39	13.55	109	195	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:2	19.09	2536	1.39	13.55	109	195	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:2	19.09	2552	1.39	13.56	109	195	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:2	19.09	2532	1.39	13.56	109	195	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:2	19.09	2549	1.38	13.56	109	195	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:2	19.09	2548	1.38	13.56	109	195	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:2	19.09	2546	1.38	13.56	109	195	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:3	19.09	2545	1.38	13.57	109	195	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:3	19.09	2543	1.38	13.57	109	195	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:3	19.09	2544	1.38	13.58	109	195	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:3	19.09	2534	1.38	13.57	109	195	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:3	19.09	2545	1.38	13.56	109	195	Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:3	19.09	2563	1.38	13.55	109	195	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:4	19.09	2544	1.38	13.54	109	195	Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:4	19.09	2543	1.38	13.55	109	195	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:4	19.09	2539	1.38	13.57	109	195	Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:4	19.09	2538	1.37	13.56	109	195	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:4	19.09	2548	1.37	13.56	109	195	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:4	19.09	2533	1.37	13.56	109	195	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:4	19.09	2530	1.37	13.56	109	195	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:5	19.09	2518	1.37	13.56	109	195	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:5	19.09	2523	1.37	13.56	109	195	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:5	19.09	2523	1.37	13.56	109	195	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:5	19.09	2520	1.37	13.56	109	195	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:5	19.09	2516	1.37	13.55	109	195	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:5	19.09	2522	1.37	13.52	109	195	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:6	19.09	2511	1.36	13.53	109	195	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:6	19.09	2491	1.36	13.53	109	195	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:6	19.09	2502	1.36	13.52	109	195	Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:6	19.09	2512	1.36	13.55	109	195	Idle	63.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:6	19.09	2511	1.35	13.56	109	195	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:6	19.09	2513	1.35	13.55	109	195	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:6	19.09	2512	1.35	13.55	109	195	Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:7	19.09	2512	1.35	13.56	109	195	Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:7	19.09	2512	1.35	13.56	109	195	Idle	64.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:47:7	19.09	2508	1.35	13.56	109	195	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:7	19.09	2496	1.34	13.56	109	195	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:7	19.09	2496	1.34	13.55	109	195	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:7	19.09	2500	1.34	13.55	109	195	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:8	19.09	2500	1.34	13.56	109	195	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:8	19.09	2498	1.34	13.56	109	195	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:8	19.09	2496	1.33	13.57	109	195	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:8	19.09	2492	1.33	13.56	109	195	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:8	19.09	2492	1.33	13.56	109	195	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:8	19.09	2490	1.33	13.57	109	195	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:9	19.09	2490	1.33	13.56	109	195	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:9	19.09	2489	1.32	13.56	109	195	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:9	19.09	2489	1.32	13.56	109	195	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:9	19.09	2488	1.32	13.56	109	195	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:9	19.09	2487	1.32	13.55	109	195	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:9	19.09	2485	1.32	13.56	109	195	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:47:9	19.09	2484	1.32	13.55	109	195	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:0	19.09	2482	1.32	13.56	109	195	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:0	19.09	2498	1.31	13.57	109	195	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:0	19.09	2488	1.31	13.57	109	195	Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:0	19.09	2466	1.31	13.56	109	195	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:0	19.09	2475	1.31	13.57	109	195	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:0	19.09	2474	1.3	13.56	109	195	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:1	19.09	2471	1.3	13.56	109	195	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:1	19.09	2468	1.3	13.56	109	195	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:1	19.09	2468	1.3	13.57	109	195	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:1	19.09	2465	1.29	13.56	109	195	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:1	19.09	2465	1.29	13.57	109	195	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:1	19.09	2465	1.29	13.57	109	195	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:1	19.09	2464	1.29	13.57	109	195	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:2	19.09	2473	1.28	13.57	109	195	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:2	19.09	2461	1.28	13.56	109	195	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:2	19.09	2460	1.28	13.56	109	195	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:2	19.09	2460	1.27	13.56	109	195	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:2	19.09	2459	1.27	13.56	109	195	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:2	19.09	2457	1.27	13.56	109	195	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:3	19.09	2457	1.27	13.58	109	195	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:3	19.09	2436	1.27	13.56	109	195	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:3	19.09	2451	1.26	13.57	109	195	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:3	19.09	2451	1.26	13.57	109	195	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:3	17.72	2440	1.26	13.56	109	195	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:3	17.72	2445	1.26	13.55	109	195	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:4	19.09	2462	1.26	13.54	109	195	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:4	19.09	2439	1.26	13.55	109	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:4	19.09	2436	1.26	13.55	109	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:4	17.72	2436	1.26	13.55	109	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:4	17.72	2423	1.26	13.56	109	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:4	17.72	2430	1.25	13.56	109	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:4	17.72	2430	1.25	13.56	109	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:5	17.72	2430	1.25	13.55	109	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:5	17.72	2430	1.25	13.56	109	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:5	17.72	2430	1.25	13.56	109	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:5	17.72	2430	1.25	13.57	109	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:5	17.72	2429	1.25	13.56	109	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:5	17.72	2430	1.25	13.56	109	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:6	17.72	2428	1.25	13.55	109	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:6	17.72	2426	1.25	13.56	109	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:6	17.72	2421	1.24	13.55	109	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:48:6	17.72	2421	1.24	13.55	109	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:6	17.72	2418	1.24	13.55	109	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:6	17.72	2414	1.24	13.55	109	195	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:6	17.72	2414	1.24	13.56	109	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:7	17.72	2410	1.24	13.56	109	195	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:7	17.72	2392	1.24	13.56	109	195	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:7	17.72	2407	1.24	13.56	109	195	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:7	17.72	2407	1.23	13.56	109	195	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:7	17.72	2408	1.23	13.56	109	195	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:7	17.72	2409	1.23	13.56	109	195	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:8	17.72	2411	1.23	13.57	109	195	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:8	17.72	2411	1.23	13.56	109	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:8	17.72	2402	1.23	13.57	109	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:8	17.72	2411	1.22	13.57	109	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:8	17.72	2411	1.22	13.56	109	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:8	17.72	2408	1.22	13.56	109	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:9	17.72	2405	1.22	13.58	109	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:9	17.72	2402	1.21	13.58	109	195	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:9	17.72	2402	1.21	13.56	109	195	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:9	17.72	2399	1.21	13.56	109	195	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:9	17.72	2396	1.21	13.56	109	195	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:9	17.72	2408	1.21	13.55	109	195	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:48:9	17.72	2408	1.2	13.56	109	195	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:0	17.72	2380	1.2	13.58	109	195	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:0	17.72	2386	1.2	13.57	109	195	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:0	17.72	2383	1.2	13.57	109	195	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:0	17.72	2383	1.19	13.56	109	195	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:0	17.72	2383	1.19	13.57	109	195	Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:0	17.72	2382	1.19	13.56	109	195	Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:1	17.72	2398	1.19	13.55	109	195	Idle	71.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:1	17.72	2398	1.19	13.55	109	195	Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:1	17.72	2378	1.18	13.57	109	195	Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:1	17.72	2360	1.18	13.56	109	195	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.19	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:1	17.72	2360	1.18	13.56	109	195	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:1	17.72	2377	1.18	13.57	109	195	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:1	17.72	2377	1.18	13.57	109	195	Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:2	17.72	2375	1.18	13.56	109	195	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:2	17.72	2373	1.18	13.57	109	195	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:2	17.72	2370	1.18	13.57	109	195	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:2	17.72	2370	1.17	13.57	109	195	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:2	17.72	2366	1.17	13.57	109	195	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:2	17.72	2364	1.17	13.57	109	195	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:3	17.72	2364	1.17	13.56	109	195	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:3	17.72	2364	1.17	13.56	109	195	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:3	17.72	2360	1.17	13.56	109	195	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:3	17.72	2359	1.17	13.56	109	195	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:3	17.72	2359	1.16	13.55	109	195	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:3	17.72	2366	1.16	13.56	109	195	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:4	17.72	2354	1.16	13.57	109	195	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:4	17.72	2354	1.16	13.57	109	195	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:4	17.72	2354	1.16	13.56	109	195	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:4	17.72	2352	1.15	13.57	109	195	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:4	17.72	2349	1.15	13.57	109	195	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:4	17.72	2347	1.15	13.56	109	195	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:4	17.72	2346	1.15	13.57	109	195	Idle	73.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:5	17.72	2343	1.15	13.56	109	195	Idle	73.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:5	17.72	2342	1.14	13.55	109	195	Idle	73.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:5	17.72	2342	1.14	13.56	109	195	Idle	73.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:49:5	17.72	2340	1.14	13.56	109	195	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:5	17.72	2338	1.14	13.54	109	195	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:5	17.72	2337	1.14	13.55	109	195	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:6	17.72	2335	1.14	13.56	109	195	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:6	17.72	2334	1.14	13.57	109	195	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:6	17.72	2334	1.13	13.57	109	195	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:6	17.72	2332	1.13	13.6	109	195	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:6	17.72	2332	1.13	13.59	109	195	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:6	17.72	2330	1.13	13.58	109	195	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:6	17.72	2330	1.13	13.57	109	195	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:7	17.72	2318	1.13	13.58	109	195	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:7	17.72	2324	1.13	13.57	109	195	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:7	17.72	2324	1.12	13.56	109	195	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:7	17.72	2332	1.12	13.56	109	195	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:7	17.72	2321	1.12	13.54	109	195	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:7	17.72	2320	1.12	13.53	109	195	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:8	17.72	2310	1.12	13.55	109	195	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:8	17.72	2316	1.12	13.53	109	195	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.25	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:8	17.72	2333	1.12	13.53	109	195	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:8	17.72	2333	1.12	13.54	109	195	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:8	17.72	2313	1.12	13.56	109	195	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:8	17.72	2302	1.12	13.57	109	195	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:9	17.72	2309	1.11	13.56	109	195	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:9	17.72	2308	1.11	13.56	109	195	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:9	17.72	2307	1.11	13.56	109	195	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:9	17.72	2313	1.11	13.55	109	195	Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:9	17.72	2301	1.11	13.55	109	195	Idle	75.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:9	17.72	2280	1.11	13.55	109	195	Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:49:9	17.72	2289	1.11	13.55	109	195	Idle	75.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:0	17.72	2296	1.1	13.54	109	195	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:0	17.72	2296	1.1	13.55	109	195	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:0	17.72	2294	1.1	13.56	109	195	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:0	17.72	2310	1.1	13.56	109	194	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:0	17.72	2300	1.1	13.56	109	194	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:0	17.72	2270	1.09	13.56	109	194	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:1	17.72	2288	1.09	13.56	109	195	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:1	17.72	2289	1.09	13.56	109	195	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:1	17.72	2287	1.09	13.55	109	195	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:1	17.72	2289	1.08	13.55	109	195	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:1	17.72	2288	1.08	13.55	109	195	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:1	17.72	2289	1.08	13.56	109	195	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:1	17.72	2287	1.08	13.56	109	195	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:2	17.72	2286	1.08	13.57	109	195	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:2	17.72	2285	1.07	13.59	109	195	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:2	17.72	2284	1.07	13.59	109	195	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:2	17.72	2280	1.07	13.58	109	195	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:2	17.72	2280	1.07	13.57	109	195	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:2	17.72	2277	1.07	13.56	109	195	Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:3	17.72	2275	1.07	13.56	109	195	Idle	77.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:3	17.72	2289	1.07	13.56	109	195	Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:3	17.72	2289	1.06	13.56	109	195	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:3	17.72	2270	1.06	13.55	109	195	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:3	17.72	2249	1.06	13.56	109	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:3	17.72	2249	1.06	13.56	109	195	Idle	78	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:4	17.72	2265	1.06	13.56	109	195	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:4	17.72	2264	1.06	13.56	109	195	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:4	17.72	2263	1.06	13.57	109	195	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:4	17.72	2263	1.06	13.57	109	195	Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:50:4	17.72	2262	1.05	13.57	109	195	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:4	17.72	2260	1.05	13.57	109	195	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:4	17.72	2258	1.05	13.57	109	194	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:5	17.72	2258	1.05	13.57	109	194	Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:5	17.72	2255	1.05	13.56	109	194	Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:5	17.72	2255	1.05	13.55	109	194	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:5	17.72	2254	1.05	13.56	109	194	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:5	17.72	2251	1.05	13.56	109	194	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:5	17.72	2250	1.04	13.55	109	195	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:6	17.72	2249	1.04	13.55	109	195	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:6	17.72	2248	1.04	13.56	109	195	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:6	17.72	2248	1.04	13.55	109	194	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:6	17.72	2247	1.04	13.54	109	194	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:6	17.72	2246	1.04	13.54	109	194	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:6	17.72	2241	1.04	13.53	109	194	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:6	17.72	2242	1.04	13.53	109	194	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:7	17.72	2240	1.04	13.54	109	194	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:7	17.72	2236	1.03	13.54	109	195	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:7	17.72	2218	1.03	13.52	109	195	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:7	17.72	2218	1.03	13.52	109	195	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:7	17.72	2230	1.03	13.52	109	195	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:7	17.72	2245	1.03	13.54	109	195	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:8	17.72	2229	1.03	13.55	109	194	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:8	17.72	2220	1.03	13.56	109	194	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:8	17.72	2224	1.03	13.56	109	194	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:8	17.72	2241	1.02	13.56	109	194	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:8	17.72	2224	1.02	13.55	109	194	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:8	17.72	2224	1.02	13.55	109	194	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:9	17.72	2207	1.02	13.55	109	194	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:9	17.72	2220	1.02	13.56	109	194	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:9	17.72	2219	1.02	13.57	109	194	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:9	17.72	2219	1.02	13.57	109	194	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:9	17.72	2200	1.02	13.57	109	194	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.2	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:9	17.72	2215	1.02	13.56	109	194	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:50:9	17.72	2230	1.01	13.55	109	194	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:0	17.72	2230	1.01	13.55	109	194	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:0	17.72	2212	1.01	13.53	109	194	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:0	17.72	2210	1.01	13.52	109	194	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:0	17.72	2208	1.01	13.53	109	194	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:0	17.72	2190	1.01	13.52	109	194	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:0	17.72	2206	1.01	13.53	109	194	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:1	17.72	2222	1.01	13.54	109	194	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:1	17.72	2222	1.01	13.54	109	194	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:1	17.72	2196	1.01	13.54	109	194	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:1	17.72	2203	1.01	13.56	109	194	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:1	17.72	2200	1.01	13.56	109	194	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:1	17.72	2200	1	13.57	109	194	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:1	17.72	2200	1	13.57	109	194	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:2	17.72	2196	1	13.56	109	194	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:2	17.72	2196	1	13.56	109	194	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:2	17.72	2194	1	13.55	109	194	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:2	17.72	2192	1	13.56	109	194	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:2	17.72	2200	1	13.56	109	194	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:2	17.72	2189	1	13.56	109	194	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:3	17.72	2178	1	13.55	109	194	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:3	17.72	2185	1	13.54	109	194	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:3	17.72	2185	0.99	13.54	109	194	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:3	17.72	2193	0.99	13.56	109	194	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:51:3	17.72	2182	0.99	13.56	109	194	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:3	17.72	2173	0.99	13.55	109	194	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:4	17.72	2181	0.99	13.56	109	194	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.19	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:4	17.72	2188	0.99	13.56	109	194	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:4	17.72	2178	0.99	13.56	109	194	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:4	17.72	2169	0.99	13.56	109	194	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.19	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:4	17.72	2176	0.99	13.55	109	194	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:4	17.72	2192	0.99	13.55	109	194	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:4	17.72	2182	0.99	13.54	109	194	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:5	17.72	2171	0.99	13.54	109	194	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:5	17.72	2168	0.98	13.56	109	194	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:5	17.72	2166	0.98	13.58	109	194	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:5	17.72	2166	0.98	13.58	109	194	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:5	17.72	2162	0.98	13.58	109	194	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:5	17.72	2160	0.98	13.59	109	194	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:6	17.72	2159	0.98	13.57	109	194	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:6	17.72	2159	0.98	13.58	109	194	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:6	17.72	2160	0.98	13.56	109	194	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:6	17.72	2159	0.97	13.56	109	194	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:6	17.72	2159	0.97	13.56	109	194	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:6	17.72	2158	0.97	13.55	109	194	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:6	17.72	2157	0.97	13.55	109	194	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:7	17.72	2156	0.97	13.53	109	194	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:7	17.72	2152	0.97	13.54	109	194	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:7	17.72	2152	0.97	13.53	109	194	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:7	17.72	2142	0.97	13.56	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:7	17.72	2147	0.96	13.56	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:7	17.72	2161	0.96	13.58	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:8	17.72	2152	0.96	13.58	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:8	17.72	2150	0.96	13.58	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:8	17.72	2140	0.96	13.57	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:8	17.72	2140	0.96	13.56	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:8	17.72	2130	0.96	13.54	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:8	17.72	2138	0.96	13.53	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:9	17.72	2138	0.96	13.52	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:9	17.72	2138	0.96	13.53	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:9	17.72	2120	0.96	13.54	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:9	17.72	2136	0.96	13.55	109	194	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:9	17.72	2134	0.95	13.56	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:9	17.72	2134	0.95	13.55	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:51:9	17.72	2140	0.95	13.54	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:0	17.72	2129	0.95	13.53	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:0	17.72	2127	0.95	13.52	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:0	17.72	2119	0.95	13.53	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:0	17.72	2125	0.95	13.52	109	194	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:0	17.72	2121	0.95	13.52	109	194	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:0	17.72	2121	0.95	13.52	109	194	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:1	17.72	2118	0.95	13.52	109	194	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:1	17.72	2117	0.95	13.52	109	194	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:1	17.72	2117	0.96	13.53	109	194	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:1	17.72	2115	0.96	13.54	109	194	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:1	17.72	2113	0.96	13.53	109	194	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:1	17.72	2114	0.96	13.53	109	194	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:1	17.72	2114	0.96	13.54	109	194	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:2	17.72	2112	0.96	13.54	109	194	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:2	17.72	2111	0.96	13.53	109	194	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:2	17.72	2109	0.96	13.54	109	194	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:2	17.72	2108	0.96	13.54	109	194	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.2	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:52:2	17.72	2106	0.96	13.53	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:2	17.72	2104	0.96	13.53	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:3	17.72	2103	0.96	13.53	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:3	17.72	2103	0.96	13.53	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:3	17.72	2100	0.96	13.53	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:3	17.72	2099	0.96	13.54	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:3	17.72	2098	0.96	13.55	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:3	17.72	2096	0.96	13.56	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:4	17.72	2100	0.96	13.56	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:4	17.72	2092	0.95	13.55	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:4	17.72	2092	0.95	13.54	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:4	17.72	2084	0.95	13.54	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:4	17.72	2090	0.95	13.54	109	194	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:4	17.72	2088	0.95	13.55	109	194	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:4	17.72	2088	0.95	13.54	109	194	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:5	17.72	2094	0.95	13.54	109	194	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:5	17.72	2085	0.95	13.54	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:5	17.72	2085	0.95	13.53	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:5	17.72	2076	0.95	13.52	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:5	17.72	2097	0.95	13.53	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:5	17.72	2097	0.95	13.53	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:6	17.72	2080	0.95	13.54	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:6	17.72	2062	0.95	13.56	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:6	17.72	2077	0.95	13.57	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:6	17.72	2076	0.95	13.57	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:6	17.72	2072	0.95	13.58	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:6	17.72	2078	0.95	13.58	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:6	17.72	2078	0.95	13.56	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:7	17.72	2068	0.95	13.54	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:7	17.72	2052	0.95	13.53	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:7	17.72	2052	0.95	13.53	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:7	17.72	2063	0.95	13.54	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:7	17.72	2063	0.95	13.56	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:7	17.72	2062	0.95	13.57	109	194	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:8	17.72	2060	0.95	13.58	109	194	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:8	17.72	2060	0.95	13.57	109	194	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:8	17.72	2050	0.95	13.57	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:8	17.72	2055	0.95	13.57	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:8	17.72	2055	0.95	13.56	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.2	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:8	17.72	2054	0.95	13.54	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:9	17.72	2068	0.95	13.53	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:9	17.72	2050	0.95	13.52	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:9	17.72	2048	0.95	13.52	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:9	17.72	2047	0.95	13.52	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:9	17.72	2045	0.95	13.52	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:9	17.72	2036	0.96	13.52	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:52:9	17.72	2042	0.96	13.52	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:0	17.72	2040	0.96	13.51	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:0	17.72	2039	0.96	13.52	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:0	17.72	2039	0.96	13.52	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:0	17.72	2030	0.96	13.53	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:0	17.72	2038	0.96	13.53	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:0	17.72	2038	0.96	13.53	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:1	17.72	2038	0.96	13.54	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:1	17.72	2037	0.96	13.54	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:1	17.72	2038	0.96	13.56	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.2	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:1	17.72	2036	0.96	13.56	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.2	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:1	17.72	2035	0.96	13.57	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:53:1	17.72	2031	0.96	13.57	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:1	17.72	2031	0.96	13.56	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:2	17.72	2030	0.96	13.55	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:2	17.72	2032	0.96	13.54	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:2	17.72	2020	0.96	13.52	109	194	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:2	17.72	2020	0.96	13.52	109	194	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:2	17.72	2010	0.96	13.52	109	194	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:2	17.72	2015	0.96	13.52	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:3	17.72	2014	0.96	13.51	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:3	17.72	2014	0.96	13.52	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:3	17.72	2013	0.96	13.53	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:3	17.72	2012	0.95	13.55	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:3	17.72	2012	0.95	13.56	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:3	17.72	2012	0.95	13.56	109	194	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:4	17.72	2012	0.95	13.56	109	194	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:4	17.72	2009	0.95	13.54	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:4	17.72	2010	0.95	13.54	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:4	17.72	2006	0.95	13.54	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:4	17.72	2006	0.95	13.54	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:4	17.72	2004	0.95	13.54	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:4	17.72	2001	0.95	13.54	109	194	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:5	17.72	2001	0.95	13.52	109	194	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:5	17.72	1999	0.95	13.52	109	194	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:5	17.72	1998	0.95	13.53	109	194	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:5	17.72	1996	0.95	13.54	109	194	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:5	17.72	1996	0.95	13.55	109	194	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:5	17.72	1995	0.95	13.54	109	194	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:6	17.72	1994	0.96	13.53	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:6	17.72	1991	0.96	13.51	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:6	17.72	1992	0.96	13.51	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:6	17.72	1991	0.96	13.52	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:6	17.72	1992	0.96	13.52	109	194	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:6	17.72	1990	0.96	13.54	109	194	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:6	17.72	1990	0.96	13.54	109	194	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:7	17.72	1987	0.96	13.52	109	194	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:7	17.72	1987	0.96	13.52	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:7	17.72	1985	0.96	13.53	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:7	17.72	1984	0.96	13.54	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:7	17.72	1982	0.96	13.55	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:7	17.72	1978	0.95	13.55	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:8	17.72	1978	0.95	13.54	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:8	17.72	1976	0.95	13.52	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:8	17.72	1973	0.95	13.5	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:8	17.72	1970	0.95	13.5	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:8	17.72	1970	0.95	13.52	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:8	17.72	1968	0.95	13.55	109	194	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:9	17.72	1966	0.95	13.56	109	194	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:9	17.72	1966	0.95	13.56	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:9	17.72	1966	0.95	13.57	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:9	17.72	1964	0.95	13.55	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.2	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:9	17.72	1965	0.95	13.54	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:9	17.72	1964	0.95	13.53	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:53:9	17.72	1961	0.95	13.52	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:0	17.72	1960	0.95	13.54	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:0	17.72	1960	0.95	13.55	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:0	17.72	1958	0.95	13.56	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:0	17.72	1957	0.96	13.57	109	194	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:0	17.72	1954	0.96	13.57	109	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:54:0	17.72	1948	0.96	13.56	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:1	17.72	1953	0.96	13.55	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:1	17.72	1959	0.96	13.53	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:1	17.72	1949	0.96	13.53	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:1	17.72	1949	0.96	13.53	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:1	17.72	1948	0.96	13.54	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:1	17.72	1947	0.96	13.55	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:1	17.72	1944	0.96	13.55	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:2	17.72	1944	0.96	13.56	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:2	17.72	1942	0.96	13.55	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:2	17.72	1942	0.96	13.55	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:2	17.72	1941	0.96	13.56	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:2	17.72	1938	0.96	13.56	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:2	17.72	1935	0.96	13.57	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:3	17.72	1934	0.96	13.58	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:3	17.72	1934	0.96	13.58	109	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:3	17.72	1934	0.96	13.55	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:3	17.72	1922	0.96	13.55	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:3	17.72	1929	0.96	13.55	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:3	17.72	1927	0.96	13.55	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:4	17.72	1927	0.96	13.55	109	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:4	17.72	1926	0.96	13.56	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:4	17.72	1936	0.96	13.56	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:4	17.72	1936	0.96	13.56	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:4	17.72	1921	0.96	13.56	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:4	17.72	1918	0.96	13.57	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:4	17.72	1910	0.96	13.56	109	194	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:5	17.72	1914	0.96	13.55	109	194	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:5	17.72	1913	0.96	13.55	109	194	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:5	17.72	1912	0.96	13.54	109	194	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:5	17.72	1911	0.96	13.55	109	194	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:5	17.72	1925	0.96	13.55	109	194	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:5	17.72	1911	0.96	13.55	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:6	17.72	1910	0.96	13.56	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:6	17.72	1908	0.96	13.57	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:6	17.72	1907	0.96	13.56	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:6	17.72	1904	0.96	13.56	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:6	17.72	1900	0.96	13.56	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:6	17.72	1882	0.96	13.56	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:6	17.72	1863	0.96	13.56	109	194	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:7	17.72	1863	0.96	13.56	109	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:7	17.72	1830	0.96	13.55	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:7	17.72	1795	0.96	13.54	109	194	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:7	17.72	1773	0.96	13.53	109	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:7	17.72	1773	0.96	13.54	109	194	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:7	17.72	1749	0.96	13.53	109	194	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:8	17.72	1706	0.96	13.54	109	194	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:8	17.72	1677	0.96	13.55	109	194	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:8	17.72	1677	0.97	13.54	109	194	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:8	17.72	1652	0.97	13.52	109	194	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:8	17.72	1629	0.97	13.53	109	194	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:8	17.72	1603	0.99	13.54	109	194	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.22	1.38	4.1	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:9	17.72	1603	1	13.54	109	194	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.21	1.38	4.1	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:9	17.72	1578	1.01	13.55	109	194	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.22	1.38	4.2	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:9	17.72	1553	1.02	13.55	109	194	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	4.2	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:9	17.72	1516	1.04	13.54	109	194	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	4.2	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:9	17.72	1516	1.04	13.54	109	194	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	4.2	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:54:9	17.72	1502	1.06	13.53	109	194	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	4.2	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:54:9	17.72	1462	1.07	13.53	109	194	Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.48	20.22	1.38	4.3	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:0	17.72	1449	1.09	13.52	109	194	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.4	20.22	1.38	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:0	17.72	1436	1.1	13.53	109	194	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.33	20.22	1.38	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:0	17.72	1404	1.12	13.54	109	194	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.2	20.22	1.38	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:0	17.72	1385	1.13	13.53	109	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.11	20.22	1.38	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:0	19.09	1380	1.15	13.52	109	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.05	20.22	1.38	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:0	19.09	1330	1.16	13.51	109	194	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.92	20.22	1.38	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:1	19.09	1330	1.17	13.52	109	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.83	20.22	1.38	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:55:1	17.72	1303	1.18	13.52	109	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.73	20.22	1.38	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:55:1	17.72	1274	1.19	13.53	109	194	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.66	20.21	1.38	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:55:1	17.72	1274	1.2	13.54	109	194	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.52	20.22	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:55:1	16.36	1256	1.21	13.53	109	194	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.44	20.22	1.38	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:55:1	16.36	1219	1.21	13.54	109	194	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.36	20.22	1.38	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:55:1	16.36	1219	1.22	13.54	109	194	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.21	20.22	1.38	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:55:2	16.36	1211	1.22	13.55	109	194	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.17	20.21	1.38	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:55:2	16.36	1209	1.22	13.54	109	194	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.11	20.21	1.38	4.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:55:2	16.36	1209	1.22	13.54	109	194	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.98	20.21	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:2	16.36	1219	1.22	13.54	109	194	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.95	20.21	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:2	16.36	1234	1.22	13.54	109	194	Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.89	20.22	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:2	16.36	1240	1.22	13.53	109	194	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.84	20.21	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:55:3	16.36	1248	1.21	13.55	109	194	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.87	20.21	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:55:3	16.36	1253	1.21	13.54	109	194	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.87	20.21	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:55:3	16.36	1250	1.2	13.55	109	194	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.91	20.21	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:55:3	14.99	1269	1.19	13.54	109	194	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.96	20.21	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:55:3	14.99	1269	1.17	13.53	109	194	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.02	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:55:3	14.99	1258	1.16	13.53	109	194	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.05	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:55:4	14.99	1269	1.16	13.53	109	194	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.11	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:55:4	14.99	1250	1.15	13.54	109	194	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.15	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:55:4	14.99	1250	1.13	13.53	109	194	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.2	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:55:4	14.99	1260	1.12	13.53	109	194	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.23	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:55:4	14.99	1269	1.1	13.54	109	194	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.3	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:55:4	14.99	1268	1.09	13.53	109	194	Idle	86.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.38	20.23	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:55:4	13.63	1274	1.07	13.55	109	194	Idle	87.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.45	20.23	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:55:5	13.63	1302	1.06	13.55	109	194	Idle	87.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.52	20.23	1.38	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:55:5	13.63	1325	1.05	13.55	109	194	Idle	87.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.6	20.22	1.38	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:55:5	12.27	1344	1.03	13.56	109	194	Idle	87.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.66	20.22	1.38	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:55:5	12.27	1427	1.01	13.56	109	194	Idle	88.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.77	20.22	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:5	12.27	1427	1	13.56	109	194	Idle	88.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	20.22	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:5	13.63	1511	0.98	13.56	109	194	Idle	88.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.04	20.21	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:55:6	13.63	1527	0.97	13.55	109	194	Idle	89.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.1	20.21	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:55:6	13.63	1576	0.96	13.56	109	193	Idle	89.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.14	20.21	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:55:6	13.63	1606	0.95	13.56	109	193	Idle	89.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.25	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:55:6	13.63	1668	0.94	13.56	109	193	Idle	90.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.41	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:55:6	13.63	1723	0.94	13.56	109	194	Idle	90.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.52	20.21	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:55:6	14.99	1751	0.93	13.56	109	194	Idle	91	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.66	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:55:6	14.99	1786	0.92	13.55	109	194	Idle	91.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.83	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:55:7	14.99	1834	0.92	13.56	109	194	Idle	92	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.95	20.22	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:55:7	14.99	1874	0.91	13.56	109	194	Idle	92.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.07	20.07	1.37	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:7	14.99	1894	0.91	13.58	109	194	Idle	92.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.17	20.07	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:7	14.99	1951	0.9	13.58	109	194	Idle	92.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.23	20.07	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:7	14.99	1951	0.9	13.59	109	194	Idle	93	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.32	20.07	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:7	14.99	2030	0.89	13.58	109	194	Idle	93.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.35	20.08	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:8	17.72	2060	0.89	13.57	109	194	Idle	92.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.38	20.07	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:8	17.72	2078	0.89	13.56	109	194	Idle	92.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.45	20.07	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:8	17.72	2147	0.88	13.56	109	194	Idle	92.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.48	20.07	1.37	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:8	17.72	2180	0.88	13.56	109	194	Idle	91.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.51	20.07	1.37	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:8	17.72	2180	0.88	13.56	109	194	Idle	91.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.56	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:8	17.72	2254	0.88	13.57	109	194	Idle	90	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.57	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:55:9	17.72	2254	0.88	13.58	109	194	Idle	89.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.62	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:9	17.72	2343	0.88	13.59	109	194	Idle	88.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.69	20.22	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:9	17.72	2395	0.88	13.58	109	194	Idle	87.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.7	20.16	1.37	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:9	17.72	2395	0.89	13.58	109	194	Idle	86.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.72	20.07	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:9	17.72	2438	0.89	13.57	109	194	Idle	84.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.8	19.83	1.36	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:9	17.72	2469	0.9	13.57	109	194	Idle	83.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.82	19.63	1.34	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:55:9	17.72	2519	0.91	13.56	109	194	Idle	81.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.81	19.39	1.32	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:0	17.72	2552	0.92	13.57	109	194	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.85	18.96	1.29	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:0	17.72	2567	0.93	13.56	109	194	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.84	18.65	1.27	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:0	17.72	2624	0.94	13.56	109	194	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.82	18.31	1.25	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:0	17.72	2617	0.95	13.57	109	194	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.82	17.96	1.22	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:0	17.72	2626	0.98	13.57	109	194	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	17.51	1.19	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:0	17.72	2634	1	13.58	109	194	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	17.27	1.18	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:1	19.09	2622	1.03	13.57	109	194	Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	17.08	1.16	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:1	19.09	2594	1.05	13.56	109	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	16.92	1.15	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:1	19.09	2588	1.09	13.57	109	194	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	16.81	1.14	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:1	19.09	2566	1.11	13.57	109	194	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	16.71	1.14	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:1	19.09	2543	1.14	13.58	109	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	16.69	1.14	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:1	19.09	2506	1.17	13.58	109	194	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	16.71	1.14	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:1	19.09	2498	1.19	13.56	109	194	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	16.79	1.14	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:2	19.09	2490	1.23	13.56	109	194	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	16.93	1.15	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:2	19.09	2487	1.25	13.55	109	193	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	17.12	1.17	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:2	19.09	2468	1.27	13.56	109	193	Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	17.39	1.18	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:2	19.09	2481	1.3	13.56	109	193	Idle	60.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	17.74	1.21	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:2	19.09	2484	1.31	13.56	109	194	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	18.1	1.23	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:2	19.09	2488	1.33	13.56	109	194	Idle	60.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	18.44	1.26	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:3	19.09	2504	1.34	13.56	109	194	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	18.8	1.28	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:3	19.09	2518	1.36	13.56	109	194	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	19.3	1.31	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:3	19.09	2526	1.37	13.57	109	194	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	19.6	1.33	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:3	19.09	2526	1.38	13.57	109	194	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	19.85	1.35	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:3	19.09	2530	1.38	13.55	109	194	Idle	60	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.12	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:3	19.09	2548	1.39	13.55	109	194	Idle	60.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:4	19.09	2524	1.39	13.55	109	194	Idle	60.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:4	19.09	2515	1.39	13.55	109	194	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:4	19.09	2502	1.39	13.55	109	194	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:4	19.09	2485	1.39	13.56	109	193	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:4	19.09	2481	1.39	13.56	109	193	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:4	19.09	2465	1.39	13.57	109	193	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:4	19.09	2465	1.38	13.56	109	194	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:5	19.09	2461	1.38	13.55	109	194	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:5	19.09	2449	1.38	13.57	109	194	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:5	19.09	2449	1.38	13.57	109	193	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:5	19.09	2450	1.38	13.57	109	193	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:5	19.09	2436	1.37	13.58	109	193	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:5	19.09	2458	1.37	13.57	109	193	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:6	19.09	2458	1.36	13.56	109	193	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:6	19.09	2470	1.36	13.56	109	193	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:6	19.09	2466	1.35	13.56	109	194	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:6	19.09	2465	1.35	13.54	109	194	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:6	19.09	2465	1.34	13.55	109	193	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:6	19.09	2468	1.34	13.56	109	193	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:6	19.09	2465	1.34	13.55	109	193	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:7	19.09	2443	1.33	13.55	109	194	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:7	19.09	2457	1.33	13.56	109	194	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:7	19.09	2454	1.33	13.56	109	194	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:7	19.09	2452	1.33	13.54	109	193	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:7	19.09	2434	1.33	13.55	109	193	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:7	19.09	2426	1.32	13.56	109	193	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:56:8	19.09	2426	1.32	13.56	109	193	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:8	19.09	2420	1.32	13.56	109	193	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:8	19.09	2417	1.32	13.56	109	193	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:8	19.09	2417	1.31	13.55	109	194	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:8	19.09	2424	1.31	13.55	109	194	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:8	17.72	2395	1.31	13.55	109	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:9	17.72	2386	1.3	13.56	109	193	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:9	17.72	2413	1.3	13.56	109	193	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:9	17.72	2412	1.3	13.56	109	193	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:9	17.72	2410	1.29	13.56	109	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:9	17.72	2410	1.29	13.57	109	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:9	17.72	2399	1.29	13.58	109	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:56:9	17.72	2406	1.28	13.57	109	193	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:0	17.72	2406	1.28	13.58	109	193	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:0	17.72	2418	1.28	13.57	109	193	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:0	17.72	2388	1.28	13.57	108	193	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:0	17.72	2391	1.27	13.57	108	193	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:0	17.72	2389	1.27	13.56	108	193	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:0	17.72	2383	1.27	13.57	109	193	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:1	17.72	2379	1.26	13.56	109	193	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:1	17.72	2376	1.26	13.55	109	193	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:1	17.72	2375	1.25	13.56	109	193	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:1	17.72	2371	1.25	13.55	109	193	Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:1	17.72	2370	1.25	13.54	109	193	Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:1	17.72	2370	1.24	13.56	109	193	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:1	17.72	2370	1.24	13.57	109	193	Idle	71.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:2	17.72	2368	1.24	13.57	109	193	Idle	71.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:2	17.72	2366	1.23	13.58	109	193	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:2	17.72	2361	1.23	13.56	109	193	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:2	17.72	2360	1.23	13.56	109	193	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:2	17.72	2359	1.22	13.56	109	193	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:2	17.72	2374	1.22	13.56	109	193	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:3	17.72	2356	1.22	13.54	109	193	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:3	17.72	2354	1.21	13.56	109	193	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:3	17.72	2344	1.21	13.55	109	193	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:3	17.72	2350	1.2	13.54	109	193	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:3	17.72	2350	1.2	13.56	109	193	Idle	72	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:3	17.72	2346	1.2	13.56	109	193	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:4	17.72	2341	1.2	13.57	109	193	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:4	17.72	2337	1.2	13.56	109	193	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:4	17.72	2337	1.2	13.57	109	193	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:4	17.72	2330	1.19	13.57	109	193	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:4	17.72	2314	1.19	13.57	109	193	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:4	17.72	2320	1.19	13.56	109	193	Idle	73.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:4	17.72	2320	1.19	13.56	109	193	Idle	73.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:5	17.72	2326	1.18	13.56	109	193	Idle	73.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:5	17.72	2315	1.18	13.56	109	193	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:5	17.72	2315	1.18	13.56	109	193	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:5	17.72	2309	1.17	13.56	109	193	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:5	17.72	2309	1.17	13.56	109	193	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:5	17.72	2307	1.17	13.56	109	193	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:6	17.72	2307	1.17	13.56	109	193	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:6	17.72	2307	1.16	13.55	109	193	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:6	17.72	2301	1.16	13.56	109	193	Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:6	17.72	2310	1.16	13.57	109	193	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:6	17.72	2298	1.16	13.57	109	193	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:6	17.72	2284	1.15	13.56	109	193	Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:6	17.72	2290	1.15	13.55	109	193	Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:57:7	17.72	2288	1.15	13.54	109	193	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:7	17.72	2286	1.14	13.53	109	193	Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:7	17.72	2283	1.14	13.55	109	193	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:7	17.72	2277	1.14	13.54	109	193	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:7	17.72	2277	1.14	13.53	109	193	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:7	17.72	2274	1.13	13.54	109	193	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:8	17.72	2270	1.13	13.55	109	193	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:8	17.72	2266	1.13	13.56	109	193	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:8	17.72	2266	1.13	13.56	109	193	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:8	17.72	2273	1.12	13.56	109	193	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:8	17.72	2262	1.12	13.55	109	193	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:8	17.72	2261	1.12	13.55	109	193	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:9	17.72	2251	1.12	13.55	109	193	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:9	17.72	2257	1.11	13.55	109	193	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:9	17.72	2264	1.11	13.54	109	193	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:9	17.72	2264	1.11	13.54	109	193	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:9	17.72	2252	1.11	13.57	109	193	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:9	17.72	2215	1.11	13.58	109	193	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:57:9	17.72	2248	1.11	13.59	109	193	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:0	17.72	2246	1.11	13.59	109	193	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:0	17.72	2241	1.1	13.6	109	193	Idle	77.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:0	17.72	2237	1.1	13.59	109	193	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:0	17.72	2236	1.1	13.59	109	193	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:0	17.72	2234	1.1	13.59	109	193	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:0	17.72	2231	1.1	13.59	109	193	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:1	17.72	2244	1.1	13.57	109	193	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:1	17.72	2226	1.09	13.56	109	193	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:1	17.72	2225	1.09	13.55	109	193	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:1	17.72	2205	1.09	13.55	109	193	Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:1	17.72	2218	1.09	13.54	108	193	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:1	17.72	2216	1.08	13.55	108	193	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:1	17.72	2212	1.08	13.56	108	193	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:2	17.72	2191	1.08	13.56	109	193	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:2	17.72	2191	1.07	13.58	109	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:2	17.72	2203	1.07	13.57	109	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:2	17.72	2202	1.07	13.57	109	193	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:2	17.72	2206	1.07	13.58	109	193	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:2	17.72	2194	1.06	13.57	109	193	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:3	17.72	2192	1.06	13.56	109	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:3	17.72	2183	1.06	13.55	109	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:3	17.72	2187	1.05	13.54	109	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:3	17.72	2203	1.05	13.54	109	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:3	17.72	2181	1.05	13.53	109	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:3	17.72	2181	1.05	13.53	109	193	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:4	17.72	2160	1.04	13.52	109	193	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:4	17.72	2168	1.04	13.53	109	193	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:4	17.72	2175	1.04	13.53	109	193	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:4	17.72	2172	1.04	13.53	109	193	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:4	17.72	2172	1.04	13.53	109	193	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:4	17.72	2171	1.04	13.53	109	193	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:4	17.72	2171	1.04	13.51	109	193	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:5	17.72	2166	1.03	13.53	109	193	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:5	17.72	2164	1.03	13.53	109	193	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:5	17.72	2161	1.03	13.53	109	193	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:5	17.72	2160	1.03	13.52	109	193	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:5	17.72	2158	1.03	13.53	109	193	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:5	17.72	2154	1.03	13.52	109	193	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:6	17.72	2149	1.03	13.53	109	193	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:58:6	17.72	2166	1.02	13.52	109	193	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:6	17.72	2156	1.02	13.52	109	193	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:6	17.72	2144	1.02	13.51	109	193	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:6	17.72	2134	1.02	13.52	109	193	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:6	17.72	2156	1.02	13.53	109	193	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:6	17.72	2156	1.02	13.54	109	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:7	17.72	2137	1.01	13.53	109	193	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:7	17.72	2134	1.01	13.54	109	193	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:7	17.72	2134	1.01	13.55	109	193	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:7	17.72	2124	1.01	13.53	109	193	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:7	17.72	2129	1.01	13.53	109	193	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:7	17.72	2127	1.01	13.54	109	193	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:8	17.72	2126	1.01	13.54	109	193	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:8	17.72	2068	1.01	13.54	109	193	Full Load	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:8	9.54	2117	1.01	13.54	109	193	Off Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:08:58:8	9.54	2117	1.01	13.54	109	193	Off Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:08:58:8	12.27	2129	1.02	13.56	109	193	Off Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.4	1.2	ON	28 Pin	OFF	Removed	Disabled
03:08:58:8	12.27	2126	1.02	13.57	109	193	Off Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:9	14.99	2121	1.03	13.58	109	193	Off Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:9	14.99	2117	1.04	13.58	109	193	Off Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:9	17.72	2116	1.04	13.57	109	193	Off Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:08:58:9	17.72	2111	1.05	13.55	109	193	Off Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:58:9	20.45	2108	1.06	13.55	109	193	Off Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:58:9	23.18	2105	1.07	13.53	109	193	Off Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:58:9	23.18	2101	1.08	13.51	109	193	Off Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:59:0	25.9	2101	1.09	13.53	109	193	Off Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:08:59:0	25.9	2097	1.1	13.53	109	193	Off Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:59:0	28.63	2096	1.11	13.51	109	193	Off Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:59:0	28.63	2103	1.12	13.51	109	193	Off Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:59:0	31.36	2093	1.14	13.53	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:08:59:0	31.36	2096	1.16	13.52	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:59:1	34.08	2094	1.18	13.56	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:59:1	34.08	2095	1.2	13.56	108	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:59:1	34.08	2095	1.22	13.57	108	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:08:59:1	34.08	2100	1.24	13.56	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:59:1	34.08	2105	1.25	13.55	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:59:1	34.08	2098	1.27	13.54	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:08:59:1	34.08	2112	1.29	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:2	34.08	2108	1.31	13.52	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:2	34.08	2110	1.33	13.52	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:2	34.08	2110	1.34	13.52	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:2	34.08	2103	1.36	13.52	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:2	34.08	2101	1.38	13.52	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:2	34.08	2097	1.4	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:3	34.08	2095	1.42	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.44	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:3	34.08	2090	1.43	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.38	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:3	34.08	2081	1.45	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.3	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:59:3	32.72	2072	1.48	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.16	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:59:3	32.72	2074	1.5	13.54	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:3	32.72	2071	1.51	13.56	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	20.23	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:4	32.72	2067	1.53	13.59	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.84	20.23	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:4	32.72	2066	1.56	13.59	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.72	20.24	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:4	32.72	2069	1.58	13.59	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.48	20.22	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:4	32.72	2074	1.6	13.57	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.27	20.23	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:4	32.72	2083	1.64	13.57	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:59:4	32.72	2088	1.67	13.57	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.79	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:08:59:4	32.72	2105	1.7	13.56	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.58	20.23	1.38	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:08:59:5	32.72	2114	1.73	13.55	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.47	20.23	1.38	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:08:59:5	32.72	2118	1.78	13.54	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.13	20.24	1.38	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:5	32.72	2133	1.82	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.86	20.23	1.38	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:5	32.72	2139	1.85	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.61	20.23	1.38	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:5	32.72	2144	1.88	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.38	20.25	1.38	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:08:59:5	32.72	2139	1.93	13.52	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.05	20.2	1.38	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:6	32.72	2136	1.96	13.52	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-5.89	20.15	1.37	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:6	32.72	2129	2	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-5.78	19.99	1.36	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:6	32.72	2117	2.02	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.61	19.66	1.34	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:6	32.72	2087	2.05	13.55	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.55	19.4	1.32	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:6	32.72	2087	2.06	13.55	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.5	19.12	1.3	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:6	31.36	2070	2.08	13.53	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.42	18.81	1.28	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:6	31.36	2073	2.11	13.53	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.29	18.48	1.26	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:7	31.36	2073	2.12	13.52	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.19	17.95	1.22	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:7	31.36	2076	2.14	13.52	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.11	17.57	1.2	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:7	31.36	2084	2.16	13.54	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.98	17.25	1.18	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:7	31.36	2096	2.17	13.54	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.86	17	1.16	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:7	31.36	2099	2.19	13.53	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.69	16.78	1.14	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:08:59:7	31.36	2113	2.21	13.52	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.42	16.48	1.12	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:08:59:8	31.36	2128	2.22	13.51	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.2	16.3	1.11	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:08:59:8	31.36	2135	2.24	13.52	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.01	16.03	1.09	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:8	31.36	2177	2.25	13.55	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.8	15.86	1.08	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:8	31.36	2177	2.27	13.55	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.62	15.71	1.07	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:08:59:8	31.36	2159	2.28	13.55	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.47	15.61	1.06	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:59:8	31.36	2160	2.29	13.55	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.37	15.51	1.06	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:08:59:9	31.36	2160	2.31	13.54	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.23	15.35	1.05	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:59:9	29.99	2157	2.32	13.54	109	193	Off Idle	85.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-3.18	15.26	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:59:9	29.99	2157	2.34	13.52	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.13	15.17	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:9	29.99	2150	2.35	13.54	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.03	15.03	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:9	29.99	2145	2.37	13.54	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-2.97	14.98	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:08:59:9	29.99	2144	2.38	13.54	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-2.88	14.97	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:08:59:9	29.99	2145	2.39	13.55	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-2.79	14.97	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:00:0	29.99	2150	2.41	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-2.71	14.96	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:00:0	29.99	2157	2.41	13.53	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.66	14.96	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:00:0	29.99	2175	2.43	13.56	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-2.58	14.99	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:0	29.99	2175	2.43	13.56	109	193	Off Idle	85.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.5	15.01	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:0	29.99	2186	2.44	13.57	109	193	Off Idle	85.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.43	15.03	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:0	29.99	2200	2.45	13.57	109	193	Off Idle	85.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.29	15.15	1.03	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:1	29.99	2203	2.45	13.56	109	193	Off Idle	85.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.24	15.18	1.03	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:1	29.99	2213	2.46	13.54	109	193	Off Idle	85	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.19	15.16	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:1	31.36	2209	2.46	13.54	109	193	Off Idle	84.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.16	15.09	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:1	31.36	2212	2.47	13.53	109	193	Off Idle	84.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.09	15.02	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:1	31.36	2212	2.47	13.53	109	193	Off Idle	84.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.02	14.95	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:1	31.36	2212	2.48	13.56	109	193	Off Idle	84.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.02	14.87	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:1	31.36	2213	2.49	13.57	109	193	Off Idle	84.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.96	14.7	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:2	31.36	2213	2.49	13.57	109	193	Off Idle	83.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.94	14.57	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:2	31.36	2212	2.5	13.56	109	193	Off Idle	83.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.94	14.42	0.98	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:2	31.36	2212	2.51	13.54	109	193	Off Idle	83.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.96	14.37	0.98	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:2	31.36	2237	2.51	13.53	109	193	Off Idle	83.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.01	14.29	0.97	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:2	31.36	2229	2.52	13.52	109	193	Off Idle	83.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2	14.26	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:2	31.36	2238	2.52	13.53	109	193	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.02	14.23	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:3	31.36	2242	2.52	13.54	109	193	Off Idle	82.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.99	14.2	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:3	31.36	2242	2.53	13.56	109	193	Off Idle	82.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.97	14.22	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:3	31.36	2257	2.53	13.57	109	193	Off Idle	82.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.93	14.21	0.97	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:3	31.36	2260	2.53	13.56	109	193	Off Idle	82.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.93	14.16	0.96	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:3	31.36	2264	2.53	13.56	109	193	Off Idle	82.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.92	14.14	0.96	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:3	31.36	2276	2.53	13.54	109	193	Off Idle	82	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.95	14.1	0.96	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:4	31.36	2269	2.54	13.53	109	193	Off Idle	81.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.95	14.07	0.96	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:4	31.36	2269	2.54	13.52	109	193	Off Idle	81.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.93	14.05	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:00:4	31.36	2272	2.54	13.54	109	193	Off Idle	81	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.93	14.03	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:00:4	31.36	2274	2.54	13.54	109	193	Off Idle	80.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.9	14.03	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:4	31.36	2282	2.54	13.54	109	193	Off Idle	80.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.92	14.03	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:4	31.36	2282	2.54	13.54	109	193	Off Idle	80.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.96	14.04	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:4	31.36	2285	2.54	13.54	109	193	Off Idle	79.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.99	14.06	0.96	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:5	31.36	2293	2.54	13.54	109	193	Off Idle	79.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.02	14.1	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:00:5	31.36	2284	2.54	13.56	109	193	Off Idle	79.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.02	14.12	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:00:5	31.36	2295	2.55	13.56	109	193	Off Idle	79.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.02	14.15	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:00:5	31.36	2308	2.55	13.58	109	193	Off Idle	79	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.06	14.15	0.96	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:00:5	31.36	2314	2.55	13.58	109	193	Off Idle	78.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.06	14.18	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:00:5	31.36	2315	2.55	13.56	109	193	Off Idle	78.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.06	14.21	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:6	31.36	2320	2.55	13.57	109	193	Off Idle	78.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.12	14.25	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:6	31.36	2329	2.55	13.55	109	193	Off Idle	78.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.11	14.27	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:6	31.36	2354	2.55	13.55	109	193	Off Idle	77.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.05	14.29	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:6	31.36	2344	2.55	13.57	109	193	Off Idle	77.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.09	14.31	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:6	31.36	2334	2.55	13.56	109	193	Off Idle	77.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.16	14.35	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:6	31.36	2335	2.55	13.57	109	193	Off Idle	77.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.16	14.42	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:6	31.36	2335	2.55	13.56	109	193	Off Idle	76.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.22	14.43	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:7	31.36	2340	2.55	13.56	109	193	Off Idle	76.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.27	14.45	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:7	31.36	2343	2.55	13.57	109	193	Off Idle	76.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.28	14.46	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:00:7	31.36	2346	2.55	13.56	109	193	Off Idle	75.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.28	14.49	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:7	31.36	2357	2.55	13.56	109	193	Off Idle	75.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.34	14.5	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:7	31.36	2363	2.55	13.56	109	193	Off Idle	75.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.34	14.52	0.99	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:7	31.36	2363	2.55	13.55	109	193	Off Idle	75.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.33	14.55	0.99	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:8	31.36	2368	2.55	13.55	109	193	Off Idle	75	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.35	14.57	0.99	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:8	31.36	2374	2.55	13.56	109	193	Off Idle	74.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.3	14.61	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:00:8	31.36	2374	2.55	13.55	109	193	Off Idle	74.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.25	14.64	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:8	31.36	2374	2.55	13.55	109	193	Off Idle	74.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.24	14.66	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:8	31.36	2376	2.55	13.56	109	193	Off Idle	74.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.24	14.68	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:8	31.36	2378	2.55	13.54	109	193	Off Idle	74.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.29	14.7	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:9	31.36	2381	2.55	13.54	109	193	Off Idle	74.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.34	14.72	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:00:9	31.36	2381	2.55	13.55	109	193	Off Idle	73.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.37	14.74	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:00:9	31.36	2396	2.56	13.54	109	193	Off Idle	73.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.37	14.75	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:00:9	31.36	2394	2.56	13.54	109	193	Off Idle	73.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.37	14.77	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:00:9	31.36	2398	2.56	13.54	109	193	Off Idle	73	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.37	14.76	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:00:9	31.36	2404	2.56	13.55	109	193	Off Idle	73	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.35	14.77	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:00:9	31.36	2411	2.56	13.56	109	193	Off Idle	73	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.37	14.78	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:0	31.36	2411	2.56	13.56	109	193	Off Idle	72.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.4	14.79	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:0	31.36	2422	2.56	13.56	109	193	Off Idle	72.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.43	14.81	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:0	31.36	2438	2.57	13.56	109	193	Off Idle	72	0	2	132	944 Turbo	0.53	Rich	1	14.6	-2.43	14.81	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:0	31.36	2436	2.57	13.57	109	193	Off Idle	71.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.47	14.81	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:0	31.36	2438	2.57	13.57	109	193	Off Idle	71.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-2.47	14.81	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:0	31.36	2439	2.57	13.56	109	193	Off Idle	71.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-2.44	14.82	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:1	31.36	2444	2.58	13.56	109	193	Off Idle	71.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.4	14.84	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:1	31.36	2468	2.58	13.57	109	193	Off Idle	70.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-2.37	14.85	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:1	31.36	2453	2.59	13.56	109	193	Off Idle	70.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-2.27	14.89	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:01:1	31.36	2453	2.59	13.54	109	193	Off Idle	70.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.27	14.92	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:01:1	31.36	2454	2.59	13.55	109	193	Off Idle	70.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-2.24	14.96	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:01:1	31.36	2458	2.61	13.55	109	192	Off Idle	70.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-2.16	14.99	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:1	31.36	2468	2.61	13.56	109	192	Off Idle	69.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-2.09	15.02	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:2	31.36	2468	2.63	13.55	109	192	Off Idle	69.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-1.96	15.09	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:01:2	31.36	2479	2.63	13.57	109	193	Off Idle	69.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-1.85	15.12	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:01:2	31.36	2492	2.64	13.58	109	193	Off Idle	69.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.81	15.16	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:01:2	31.36	2492	2.64	13.56	109	193	Off Idle	69.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-1.72	15.16	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:01:2	31.36	2495	2.65	13.56	109	193	Off Idle	69.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.64	15.15	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:01:2	31.36	2502	2.67	13.57	109	193	Off Idle	68.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.53	15.11	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:01:3	31.36	2502	2.67	13.55	109	193	Off Idle	68.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.48	15.08	1.03	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:3	31.36	2508	2.68	13.56	109	193	Off Idle	68.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.41	15.03	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:01:3	31.36	2514	2.69	13.56	109	193	Off Idle	68.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.42	14.99	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:3	31.36	2514	2.7	13.56	109	193	Off Idle	68.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.41	14.98	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:3	31.36	2514	2.71	13.57	109	193	Off Idle	68.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.31	14.95	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:3	31.36	2517	2.72	13.57	109	193	Off Idle	67.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.25	14.9	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:4	31.36	2524	2.73	13.57	109	193	Off Idle	67.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.17	14.85	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:4	31.36	2551	2.74	13.56	109	193	Off Idle	67	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.09	14.87	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:01:4	31.36	2544	2.74	13.56	109	193	Off Idle	66.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.02	14.86	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:4	31.36	2544	2.75	13.57	109	193	Off Idle	65.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.92	14.85	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:4	31.36	2552	2.76	13.56	109	193	Off Idle	65.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.83	14.84	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:4	31.36	2566	2.77	13.57	109	193	Off Idle	65	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.81	14.82	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:4	31.36	2559	2.78	13.56	109	192	Off Idle	64.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.68	14.81	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:09:01:5	31.36	2559	2.79	13.56	109	192	Off Idle	64.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.5	14.82	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:09:01:5	31.36	2564	2.8	13.56	109	193	Off Idle	64.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.46	14.81	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:01:5	31.36	2556	2.8	13.56	109	193	Off Idle	64.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.34	14.78	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:5	31.36	2556	2.81	13.56	109	193	Off Idle	63.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.26	14.77	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:5	31.36	2582	2.82	13.58	109	193	Off Idle	63.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.26	14.77	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:5	31.36	2596	2.83	13.56	109	192	Off Idle	63.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.19	14.78	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:6	31.36	2611	2.84	13.56	109	192	Off Idle	63.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.17	14.79	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:6	31.36	2611	2.85	13.56	109	192	Off Idle	62.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.1	14.79	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:6	29.99	2622	2.86	13.56	109	193	Off Idle	62.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.01	14.81	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:6	29.99	2626	2.87	13.54	108	193	Off Idle	62.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.03	14.79	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:01:6	29.99	2633	2.88	13.54	108	193	Off Idle	62.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.09	14.81	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:01:6	29.99	2634	2.89	13.54	108	193	Off Idle	62.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.16	14.82	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:6	29.99	2646	2.89	13.54	109	193	Off Idle	61.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.16	14.83	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:7	29.99	2637	2.9	13.54	109	192	Off Idle	61.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.19	14.82	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:7	29.99	2640	2.91	13.55	108	192	Off Idle	61.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.26	14.82	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:7	29.99	2642	2.91	13.55	108	192	Off Idle	61	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.34	14.83	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:7	29.99	2644	2.92	13.56	108	193	Off Idle	60.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.38	14.83	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:7	29.99	2629	2.93	13.58	109	193	Off Idle	60.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.4	14.83	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:7	29.99	2629	2.93	13.56	109	193	Off Idle	59.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.45	14.84	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:8	29.99	2659	2.94	13.56	109	193	Off Idle	59.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.53	14.83	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:8	29.99	2666	2.95	13.54	109	193	Off Idle	59.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.6	14.82	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:01:8	29.99	2666	2.95	13.55	109	193	Off Idle	59.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.58	14.81	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:8	29.99	2675	2.96	13.55	109	193	Off Idle	58.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.63	14.8	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:8	29.99	2685	2.96	13.54	108	193	Off Idle	58.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.7	14.79	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:8	29.99	2703	2.97	13.56	108	193	Off Idle	58.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.66	14.79	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:9	29.99	2703	2.98	13.56	108	193	Off Idle	58.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.67	14.77	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:9	28.63	2710	2.98	13.54	109	193	Off Idle	57.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.75	14.74	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:9	28.63	2718	2.99	13.55	109	193	Off Idle	57.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.81	14.73	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:9	28.63	2718	2.99	13.55	109	193	Off Idle	57.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.75	14.73	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:9	28.63	2726	3	13.53	108	192	Off Idle	56.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.78	14.75	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:9	28.63	2752	3.01	13.56	108	192	Off Idle	56.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.84	14.77	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:01:9	31.36	2735	3.01	13.55	109	192	Off Idle	55.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.86	14.77	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:02:0	31.36	2735	3.01	13.55	109	193	Off Idle	55.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.85	14.77	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:0	31.36	2748	3.02	13.54	109	193	Off Idle	55.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.96	14.78	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:02:0	31.36	2756	3.02	13.54	109	193	Off Idle	54.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.09	14.82	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:02:0	29.99	2764	3.03	13.53	109	193	Off Idle	54.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	1.04	14.85	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:02:0	29.99	2764	3.04	13.52	109	192	Off Idle	54.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	1.12	14.85	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:02:0	29.99	2772	3.04	13.53	109	192	Off Idle	53.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	1.06	14.85	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:1	29.99	2774	3.05	13.54	109	192	Off Idle	53.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	1.07	14.85	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:1	29.99	2783	3.05	13.53	109	192	Off Idle	52.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	1.07	14.83	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:1	29.99	2783	3.06	13.53	109	193	Off Idle	52.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	1.14	14.84	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:1	29.99	2794	3.06	13.55	109	193	Off Idle	52	0	2	132	944 Turbo	0.49	Lean	1	14.6	1.15	14.8	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:1	29.99	2799	3.07	13.54	109	193	Off Idle	51.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	1.17	14.78	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:02:1	29.99	2801	3.07	13.56	109	193	Off Idle	51.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	1.17	14.76	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:02:1	29.99	2824	3.08	13.56	109	193	Off Idle	51.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	1.19	14.78	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:02:2	29.99	2824	3.08	13.55	109	193	Off Idle	50.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	1.22	14.81	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:02:2	29.99	2820	3.09	13.55	109	193	Off Idle	50.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	1.24	14.82	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:02:2	29.99	2831	3.09	13.54	109	193	Off Idle	50.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	1.27	14.85	1.01	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:02:2	29.99	2862	3.09	13.54	109	193	Off Idle	50.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	1.33	14.86	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:02:2	29.99	2853	3.09	13.55	109	193	Off Idle	49.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	1.34	14.92	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:02:2	29.99	2850	3.1	13.56	109	193	Off Idle	49.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	1.32	15.01	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:02:3	29.99	2855	3.11	13.55	108	193	Off Idle	49.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	1.38	15.03	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:02:3	29.99	2856	3.11	13.57	108	192	Off Idle	49.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	1.44	15.06	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:02:3	29.99	2834	3.12	13.57	108	192	Off Idle	49	0	2	132	944 Turbo	0.57	Rich	1	14.6	1.42	15.04	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:02:3	29.99	2864	3.12	13.56	108	193	Off Idle	48.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	1.53	15	1.02	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:02:3	29.99	2866	3.13	13.56	108	193	Off Idle	48.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	1.59	14.97	1.02	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:02:3	29.99	2878	3.13	13.56	109	193	Off Idle	48.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	1.58	14.95	1.02	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:02:4	29.99	2912	3.14	13.55	109	193	Off Idle	48.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.61	14.92	1.02	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:02:4	29.99	2883	3.14	13.55	109	193	Off Idle	48	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.65	14.82	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:02:4	29.99	2884	3.14	13.54	109	193	Off Idle	47.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.64	14.78	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:02:4	29.99	2884	3.15	13.53	109	192	Off Idle	46.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.66	14.76	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:02:4	29.99	2895	3.16	13.52	109	192	Off Idle	46.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	1.7	14.75	1	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:02:4	29.99	2888	3.16	13.5	109	192	Off Idle	46.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	1.74	14.77	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:02:4	29.99	2900	3.17	13.52	109	193	Off Idle	46.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	1.79	14.77	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:02:5	29.99	2926	3.17	13.54	109	193	Off Idle	46.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	1.79	14.76	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:02:5	29.99	2944	3.18	13.54	109	193	Off Idle	45.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	1.77	14.75	1	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:02:5	29.99	2948	3.18	13.55	108	192	Off Idle	45.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	1.79	14.78	1.01	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:02:5	28.63	2961	3.19	13.54	108	192	Off Idle	45.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	1.87	14.79	1.01	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:02:5	28.63	2951	3.19	13.53	109	192	Off Idle	44.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	1.95	14.83	1.01	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:02:5	28.63	2962	3.2	13.52	109	192	Off Idle	44.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	2.06	14.86	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:02:6	28.63	2964	3.2	13.53	109	192	Off Idle	43.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	2.12	14.88	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:02:6	28.63	2952	3.2	13.54	109	192	Off Idle	43.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	2.16	14.9	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:02:6	28.63	2970	3.21	13.55	109	192	Off Idle	43.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	2.11	14.93	1.02	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:09:02:6	28.63	2986	3.21	13.55	109	192	Off Idle	43.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	2.23	14.99	1.02	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:09:02:6	28.63	2993	3.22	13.54	108	192	Off Idle	43.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	2.22	15.04	1.02	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:6	28.63	2993	3.22	13.54	108	192	Off Idle	42.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	2.25	15.11	1.03	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:6	28.63	3010	3.23	13.55	109	192	Off Idle	42.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	2.25	15.12	1.03	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:7	28.63	3010	3.23	13.55	109	192	Off Idle	42.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	2.3	15.11	1.03	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:7	28.63	3009	3.23	13.55	109	192	Off Idle	41.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	2.3	15.11	1.03	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:02:7	28.63	3018	3.24	13.56	109	192	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	2.42	15.03	1.02	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:7	28.63	3022	3.25	13.57	109	192	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	2.47	14.95	1.02	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:02:7	28.63	3030	3.25	13.57	109	192	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	2.53	14.9	1.02	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:02:7	28.63	3044	3.25	13.57	109	192	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	2.52	14.85	1.01	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:8	28.63	3044	3.25	13.57	109	192	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	2.56	14.82	1.01	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:8	28.63	3062	3.26	13.56	109	192	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	2.61	14.71	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:8	28.63	3046	3.26	13.56	109	192	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	2.59	14.69	1	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:8	28.63	3049	3.27	13.54	109	192	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	2.61	14.68	1	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:02:8	28.63	3048	3.27	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	2.6	14.7	1	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:02:8	28.63	3048	3.27	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	2.62	14.73	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:02:9	28.63	3060	3.28	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	2.71	14.75	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:9	28.63	3060	3.28	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	2.76	14.79	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:9	28.63	3086	3.29	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	2.81	14.83	1.01	3.4	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:9	28.63	3092	3.29	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	2.85	14.86	1.01	3.4	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:02:9	27.27	3143	3.29	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	2.9	14.88	1.01	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:02:9	27.27	3131	3.3	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	2.9	14.94	1.02	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:02:9	27.27	3132	3.3	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	2.91	14.99	1.02	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:03:0	27.27	3125	3.3	13.53	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	2.94	15.05	1.03	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:03:0	28.63	3138	3.31	13.53	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	2.94	15.06	1.03	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:03:0	28.63	3131	3.31	13.52	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	2.92	15.06	1.03	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:0	28.63	3133	3.32	13.51	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	3	15.03	1.02	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:0	28.63	3145	3.32	13.52	109	193	Off Idle	41.6	0	2	132	944 Turbo	0.69	Lean	1	14.6	3.1	14.98	1.02	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:0	28.63	3146	3.33	13.52	109	193	Off Idle	41.5	0	2	132	944 Turbo	0.72	Lean	1	14.6	3.06	14.99	1.02	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:1	28.63	3155	3.33	13.52	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.13	14.95	1.02	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:1	28.63	3161	3.34	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.17	14.88	1.01	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:1	28.63	3161	3.34	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.2	14.8	1.01	3.4	6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:03:1	28.63	3162	3.35	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.15	14.75	1	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:1	28.63	3180	3.35	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.24	14.76	1.01	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:1	28.63	3182	3.35	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.26	14.78	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:1	28.63	3194	3.36	13.53	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	3.34	14.82	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:2	28.63	3201	3.37	13.52	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	3.41	14.82	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:2	28.63	3201	3.37	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	3.44	14.82	1.01	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:03:2	28.63	3218	3.37	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	3.47	14.84	1.01	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:2	28.63	3216	3.38	13.54	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	3.5	14.83	1.01	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:03:2	28.63	3219	3.38	13.53	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	3.53	14.85	1.01	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:2	28.63	3224	3.38	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	3.62	14.85	1.01	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:3	28.63	3255	3.38	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	3.53	14.86	1.01	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:3	28.63	3267	3.39	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	3.55	14.89	1.01	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:3	28.63	3271	3.39	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	3.58	14.91	1.02	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:3	28.63	3270	3.39	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	3.69	14.93	1.02	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:03:3	29.99	3286	3.4	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	3.72	15	1.02	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:3	29.99	3273	3.4	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	3.71	15.03	1.02	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:4	29.99	3275	3.41	13.57	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	3.78	15.03	1.02	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:4	29.99	3275	3.41	13.56	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	3.76	15.03	1.02	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:4	29.99	3268	3.41	13.56	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	3.79	15.01	1.02	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:4	28.63	3286	3.42	13.56	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	3.9	14.95	1.02	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:4	28.63	3289	3.42	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	3.87	14.92	1.02	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:4	28.63	3287	3.42	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	3.92	14.87	1.01	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:03:4	28.63	3286	3.42	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	3.86	14.81	1.01	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:5	28.63	3324	3.42	13.55	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	3.83	14.74	1	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:5	28.63	3314	3.43	13.55	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	3.88	14.71	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:5	28.63	3318	3.43	13.56	109	192	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	3.93	14.71	1	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:5	28.63	3318	3.43	13.56	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	3.95	14.71	1	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:5	28.63	3339	3.43	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	4.01	14.73	1	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:5	28.63	3350	3.43	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	3.99	14.81	1.01	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:6	28.63	3371	3.44	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	4.09	14.85	1.01	3.4	6.5	ON	28 Pin	OFF	Removed	Disabled
03:09:03:6	28.63	3371	3.44	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	4.04	14.88	1.01	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:6	28.63	3401	3.44	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	4.12	14.94	1.02	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:6	28.63	3394	3.44	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	4.11	15.01	1.02	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:6	28.63	3397	3.45	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	4.21	15.07	1.03	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:03:6	28.63	3403	3.45	13.51	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	4.28	15.1	1.03	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:03:6	28.63	3414	3.45	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	4.29	15.13	1.03	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:03:7	27.27	3408	3.46	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	4.34	15.11	1.03	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:03:7	27.27	3383	3.46	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	4.31	15.08	1.03	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:03:7	27.27	3380	3.46	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	4.39	15.01	1.02	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:03:7	27.27	3382	3.46	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	4.37	14.98	1.02	3.6	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:03:7	27.27	3349	3.47	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	4.51	14.88	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:03:7	27.27	3384	3.47	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	4.56	14.87	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:03:8	27.27	3390	3.48	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	4.66	14.83	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:03:8	27.27	3408	3.48	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	4.7	14.76	1.01	3.5	7.6	ON	28 Pin	OFF	Removed	Disabled
03:09:03:8	27.27	3474	3.49	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	4.71	14.75	1	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:03:8	28.63	3512	3.49	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	4.72	14.74	1	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:03:8	28.63	3506	3.49	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	4.72	14.75	1.01	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:03:8	28.63	3532	3.5	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	4.81	14.84	1.01	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:9	28.63	3541	3.5	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	4.77	14.94	1.02	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:9	28.63	3547	3.5	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	4.78	14.98	1.02	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:03:9	28.63	3544	3.51	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	4.81	14.93	1.02	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:03:9	28.63	3528	3.51	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	4.62	14.8	1.01	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:03:9	28.63	3512	3.52	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	4.63	14.64	1	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:03:9	28.63	3512	3.52	13.52	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.74	Lean	1	14.6	4.67	14.47	0.99	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:03:9	28.63	3487	3.52	13.51	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.79	Lean	1	14.6	4.59	14.21	0.97	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:04:0	28.63	3499	3.52	13.52	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	4.5	14	0.95	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:04:0	28.63	3505	3.52	13.53	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.43	13.89	0.95	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:04:0	28.63	3505	3.52	13.53	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.38	13.63	0.93	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:04:0	28.63	3524	3.52	13.53	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.3	13.29	0.91	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:0	28.63	3550	3.52	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.29	13.23	0.9	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:0	28.63	3572	3.52	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.26	13.1	0.89	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:1	28.63	3576	3.52	13.55	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.25	13	0.89	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:1	28.63	3618	3.52	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.27	12.95	0.88	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:09:04:1	28.63	3600	3.52	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.21	12.87	0.88	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:09:04:1	28.63	3604	3.52	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.28	12.82	0.87	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:09:04:1	28.63	3609	3.52	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.31	12.78	0.87	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:1	28.63	3635	3.51	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.37	12.75	0.87	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:1	28.63	3604	3.51	13.52	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.36	12.71	0.87	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:2	28.63	3608	3.51	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.47	12.71	0.87	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:2	28.63	3608	3.51	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.45	12.71	0.87	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:2	28.63	3610	3.51	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.39	12.73	0.87	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:2	28.63	3611	3.51	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.32	12.76	0.87	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:2	28.63	3643	3.51	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.37	12.8	0.87	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:2	28.63	3649	3.51	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.29	12.81	0.87	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:3	29.99	3684	3.51	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.39	12.83	0.87	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:3	29.99	3680	3.51	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.36	12.87	0.88	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:3	29.99	3691	3.52	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.2	12.89	0.88	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:09:04:3	29.99	3694	3.52	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.17	12.91	0.88	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:3	29.99	3712	3.52	13.51	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.19	12.92	0.88	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:3	29.99	3696	3.52	13.51	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.08	12.93	0.88	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:4	29.99	3709	3.53	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.19	12.95	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:4	29.99	3710	3.53	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.25	12.98	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:4	29.99	3705	3.53	13.52	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.36	13	0.89	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:4	28.63	3727	3.53	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.28	13.01	0.89	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:4	28.63	3727	3.54	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.25	13.01	0.89	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:4	28.63	3732	3.54	13.55	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.23	13.01	0.89	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:4	28.63	3732	3.54	13.55	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.25	13.02	0.89	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:5	28.63	3741	3.54	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.28	13.02	0.89	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:5	28.63	3746	3.54	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.28	13.02	0.89	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:5	28.63	3768	3.55	13.53	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.35	13	0.89	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:5	28.63	3777	3.55	13.51	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.37	12.99	0.88	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:5	28.63	3777	3.55	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.21	12.96	0.88	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:04:5	28.63	3802	3.56	13.53	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.3	12.97	0.88	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:6	28.63	3799	3.56	13.51	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.41	12.97	0.88	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:6	28.63	3809	3.56	13.49	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.41	12.97	0.88	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:6	28.63	3809	3.56	13.51	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.39	12.96	0.88	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:6	28.63	3846	3.57	13.5	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.41	12.95	0.88	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:6	29.99	3824	3.57	13.5	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.42	12.94	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:6	29.99	3822	3.57	13.5	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.38	12.94	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:6	29.99	3830	3.58	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.32	12.95	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:7	29.99	3831	3.58	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.27	12.95	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:7	28.63	3844	3.58	13.51	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.25	12.94	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:7	28.63	3839	3.58	13.5	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.19	12.94	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:7	28.63	3845	3.59	13.5	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.21	12.98	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:7	28.63	3856	3.59	13.47	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.27	12.99	0.88	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:04:7	28.63	3856	3.59	13.47	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.29	13	0.89	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:04:8	29.99	3864	3.59	13.5	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.21	13	0.89	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:04:8	29.99	3884	3.6	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.13	13.01	0.89	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:8	29.99	3894	3.6	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.19	13	0.89	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:8	29.99	3894	3.6	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.2	13.01	0.89	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:8	29.99	3911	3.6	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.22	13	0.89	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:04:8	29.99	3915	3.6	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.2	12.98	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:9	29.99	3918	3.61	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.11	12.94	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:9	29.99	3930	3.61	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	3.99	12.94	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:9	29.99	3939	3.61	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	3.98	12.93	0.88	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:9	29.99	3943	3.61	13.57	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	3.89	12.95	0.88	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:04:9	29.99	3951	3.61	13.57	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	3.9	12.95	0.88	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:04:9	29.99	3964	3.61	13.56	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.88	12.98	0.88	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:09:04:9	29.99	3950	3.6	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.78	13.01	0.89	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:09:05:0	29.99	3952	3.6	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.68	12.98	0.88	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:09:05:0	29.99	3956	3.6	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.43	12.95	0.88	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:09:05:0	31.36	3985	3.6	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	3.35	12.94	0.88	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:09:05:0	31.36	3980	3.59	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	3.17	12.92	0.88	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:09:05:0	31.36	3984	3.59	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	3.14	12.89	0.88	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:09:05:0	31.36	3996	3.58	13.56	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	3.1	12.86	0.88	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:05:1	31.36	4018	3.58	13.56	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	3.09	12.79	0.87	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:09:05:1	31.36	4010	3.57	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	3.05	12.73	0.87	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:05:1	31.36	4012	3.57	13.5	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.94	12.72	0.87	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:05:1	31.36	4021	3.56	13.51	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.72	12.73	0.87	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:09:05:1	31.36	4021	3.54	13.51	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.17	12.77	0.87	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:09:05:1	31.36	4015	3.52	13.53	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.63	12.79	0.87	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:05:1	31.36	4009	3.47	13.56	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.77	12.82	0.87	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:05:2	31.36	3992	3.42	13.55	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.06	12.87	0.88	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:05:2	31.36	4013	3.36	13.52	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.08	12.9	0.88	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:05:2	35.45	3942	3.28	13.5	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	-2.16	12.89	0.88	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:2	35.45	3940	3.2	13.48	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.38	12.87	0.88	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:05:2	35.45	3926	3.07	13.5	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	-4.99	12.74	0.87	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:05:2	35.45	3948	2.98	13.51	108	192	Full Load	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	-5.88	12.62	0.86	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:05:3	36.81	3934	2.87	13.52	108	192	Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	-6.64	12.49	0.85	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:05:3	36.81	3922	2.76	13.53	108	192	Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	-7.27	12.32	0.84	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:05:3	36.81	3923	2.64	13.53	108	192	Idle	41.5	0	2	132	944 Turbo	0.92	Rich	1	14.6	-7.77	12.12	0.83	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:3	36.81	3923	2.47	13.54	108	192	Idle	41.5	0	2	132	944 Turbo	0.92	Rich	1	14.6	-8.46	11.78	0.8	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:3	31.36	3838	2.36	13.57	108	192	Idle	41.5	0	2	132	944 Turbo	0.92	Rich	1	14.6	-8.78	11.52	0.78	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:09:05:3	25.9	3812	2.2	13.57	108	192	Idle	41.5	0	2	132	944 Turbo	0.92	Rich	1	14.6	-8.99	11.31	0.77	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:09:05:4	20.45	3813	2.1	13.57	108	192	Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	-9.22	11.03	0.75	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:4	20.45	3801	1.99	13.57	108	192	Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	-9.26	10.88	0.74	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:4	20.45	3794	1.83	13.54	108	192	Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	-9.35	10.72	0.73	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:4	20.45	3763	1.73	13.54	108	192	Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.42	10.64	0.73	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:4	20.45	3674	1.6	13.56	108	192	Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-9.46	10.62	0.72	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:4	20.45	3684	1.54	13.56	108	192	Idle	41.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.53	10.61	0.72	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:4	20.45	3645	1.5	13.57	108	192	Idle	40.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.56	10.64	0.72	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:5	20.45	3637	1.47	13.58	108	192	Idle	40.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.48	10.7	0.73	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:5	20.45	3596	1.45	13.56	108	192	Idle	38.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.5	10.78	0.73	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:5	20.45	3596	1.43	13.56	108	192	Idle	37.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.49	10.91	0.74	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:5	20.45	3527	1.42	13.56	108	192	Idle	37.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.41	11.15	0.76	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:5	20.45	3517	1.43	13.56	108	192	Idle	36.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.44	11.24	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:5	20.45	3469	1.45	13.56	108	192	Idle	34.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.44	11.6	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:6	20.45	3461	1.48	13.56	108	192	Idle	33.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.35	11.88	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:6	20.45	3418	1.52	13.57	108	192	Idle	32.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.32	12.38	0.84	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:6	20.45	3382	1.54	13.57	108	192	Idle	30.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.24	12.57	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:6	20.45	3331	1.56	13.58	108	192	Idle	29.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.18	13.13	0.89	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:6	20.45	3338	1.58	13.58	108	192	Idle	28.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.15	13.91	0.95	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:6	20.45	3311	1.61	13.58	108	192	Idle	27	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	14.74	1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:6	20.45	3279	1.63	13.57	108	192	Idle	25.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	15.57	1.06	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:7	20.45	3270	1.66	13.57	108	192	Idle	23.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.05	16.38	1.12	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:7	20.45	3232	1.7	13.56	108	192	Full Load	22.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	17.16	1.17	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:7	20.45	3198	1.72	13.56	108	192	Off Idle	22.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	17.87	1.22	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:7	20.45	3168	1.74	13.55	108	192	Off Idle	21.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	18.86	1.28	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:05:7	10.9	3080	1.76	13.56	108	192	Off Idle	22.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	19.45	1.33	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:05:7	13.63	3146	1.79	13.55	108	192	Off Idle	24	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.08	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:05:8	16.36	3134	1.81	13.54	108	192	Off Idle	26.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.62	20.2	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:05:8	16.36	3095	1.83	13.52	108	192	Off Idle	27.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.44	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:05:8	19.09	3078	1.85	13.53	108	192	Off Idle	29.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.14	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:09:05:8	21.81	3001	1.89	13.52	108	192	Off Idle	30.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.86	20.07	1.37	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:05:8	24.54	3003	1.95	13.55	108	192	Off Idle	31.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.68	20.06	1.37	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:05:8	24.54	2992	1.98	13.55	108	192	Off Idle	33.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.22	20.06	1.37	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:09:05:9	27.27	2938	2.06	13.56	108	192	Off Idle	35.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-6.59	20.07	1.37	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:9	29.99	2842	2.14	13.56	108	192	Off Idle	37.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-5.58	20.08	1.37	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:05:9	32.72	2759	2.22	13.58	108	192	Off Idle	39	0	2	132	944 Turbo	0.01	Lean	1	14.6	-4.49	20.08	1.37	3.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:05:9	35.45	2730	2.28	13.57	108	192	Off Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-3.9	20.08	1.37	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:05:9	35.45	2694	2.34	13.57	108	192	Off Idle	42.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-3.11	20.08	1.37	3.7	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:05:9	35.45	2694	2.4	13.58	108	192	Off Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-2.9	20.24	1.38	3.7	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:05:9	32.72	2659	2.45	13.55	108	192	Off Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-2.22	20.26	1.38	3.7	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:0	32.72	2728	2.48	13.55	108	192	Off Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-1.87	20.27	1.38	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:06:0	32.72	2728	2.56	13.55	108	192	Off Idle	47.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-1.48	20.27	1.38	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:06:0	32.72	2746	2.61	13.53	108	192	Off Idle	47.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-1.36	20.26	1.38	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:0	32.72	2760	2.68	13.53	108	192	Off Idle	49.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-1.12	20.26	1.38	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:0	32.72	2771	2.73	13.55	108	192	Off Idle	50.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-0.97	20.26	1.38	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:0	32.72	2756	2.78	13.55	108	192	Off Idle	50.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-0.83	20.24	1.38	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:1	32.72	2741	2.82	13.58	108	192	Off Idle	52.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-0.77	20.02	1.36	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:1	32.72	2736	2.86	13.58	108	192	Off Idle	52.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-0.77	19.74	1.34	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:1	32.72	2725	2.89	13.57	108	192	Off Idle	53	0	2	132	944 Turbo	0.4	Lean	1	14.6	-0.76	19.36	1.32	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:1	32.72	2723	2.91	13.56	108	192	Off Idle	53.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-0.76	18.93	1.29	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:1	32.72	2724	2.92	13.55	108	192	Off Idle	53.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.68	18.47	1.26	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:1	32.72	2737	2.92	13.54	108	192	Off Idle	53.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.6	17.66	1.2	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:1	32.72	2746	2.93	13.54	108	192	Off Idle	53.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.52	16.8	1.14	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:2	31.36	2730	2.93	13.56	108	192	Off Idle	53	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.48	16.19	1.1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:2	31.36	2762	2.93	13.57	108	192	Off Idle	53	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.5	15.4	1.05	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:06:2	31.36	2761	2.92	13.56	108	192	Off Idle	53	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.45	14.72	1	3.3	5	ON	28 Pin	OFF	Removed	Disabled
03:09:06:2	31.36	2762	2.92	13.56	108	192	Off Idle	53	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.49	14.54	0.99	3.3	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:2	31.36	2774	2.92	13.55	108	192	Off Idle	53	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.45	14.32	0.98	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:2	31.36	2774	2.92	13.53	108	192	Off Idle	53	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.5	14.13	0.96	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:3	31.36	2760	2.93	13.53	108	192	Off Idle	53	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.48	14.04	0.96	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:3	31.36	2766	2.93	13.55	108	191	Off Idle	53	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.47	13.97	0.95	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:3	31.36	2766	2.93	13.55	108	191	Off Idle	53	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.45	13.92	0.95	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:3	31.36	2784	2.93	13.54	108	191	Off Idle	52.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.37	13.89	0.95	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:06:3	32.72	2765	2.93	13.54	108	192	Off Idle	52.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.33	13.87	0.94	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:06:3	32.72	2769	2.93	13.54	108	192	Off Idle	52.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.22	13.83	0.94	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:06:4	32.72	2776	2.93	13.55	108	192	Off Idle	52.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.25	13.83	0.94	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:4	32.72	2775	2.93	13.54	108	192	Off Idle	52.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.21	13.84	0.94	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:4	31.36	2788	2.94	13.56	108	192	Off Idle	52.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.17	13.86	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:4	31.36	2786	2.94	13.56	108	192	Off Idle	52	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.18	13.84	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:4	31.36	2786	2.95	13.54	108	192	Off Idle	51.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.11	13.85	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:4	31.36	2793	2.95	13.54	108	192	Off Idle	51.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.08	13.85	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:4	31.36	2793	2.95	13.54	108	192	Off Idle	51.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.08	13.85	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:5	31.36	2792	2.96	13.54	108	192	Off Idle	51.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.04	13.88	0.95	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:5	31.36	2795	2.96	13.56	108	192	Off Idle	51.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.02	13.89	0.95	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:5	31.36	2797	2.96	13.56	108	192	Off Idle	51.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.02	13.92	0.95	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:5	31.36	2803	2.96	13.57	108	192	Off Idle	51	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.03	13.93	0.95	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:06:5	31.36	2803	2.97	13.56	108	192	Off Idle	50.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.03	13.92	0.95	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:5	31.36	2806	2.97	13.56	108	192	Off Idle	50.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.11	13.95	0.95	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:6	31.36	2807	2.98	13.55	108	192	Off Idle	50.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.2	13.97	0.95	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:6	31.36	2806	2.98	13.55	108	192	Off Idle	50.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.22	14.02	0.95	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:6	31.36	2806	2.98	13.53	108	192	Off Idle	50.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.29	14.05	0.96	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:6	31.36	2811	2.99	13.52	108	192	Off Idle	50.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.37	14.07	0.96	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:6	31.36	2818	2.99	13.51	108	192	Off Idle	50.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.43	14.08	0.96	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:06:6	31.36	2820	3	13.52	108	192	Off Idle	50.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.51	14.09	0.96	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:6	31.36	2827	3	13.53	108	192	Off Idle	50.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.54	14.1	0.96	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:7	31.36	2828	3.01	13.54	108	192	Off Idle	50.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.62	14.13	0.96	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:7	31.36	2836	3.01	13.53	108	192	Off Idle	49.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.64	14.15	0.96	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:7	31.36	2836	3.02	13.54	108	192	Off Idle	49.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.65	14.15	0.96	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:7	31.36	2833	3.02	13.54	108	192	Off Idle	49.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.71	14.17	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:06:7	31.36	2833	3.03	13.54	108	192	Off Idle	49.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.71	14.18	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:7	31.36	2826	3.03	13.53	108	192	Off Idle	49	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.75	14.17	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:8	31.36	2830	3.04	13.54	108	192	Off Idle	48.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.81	14.17	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:8	31.36	2836	3.04	13.54	108	192	Off Idle	48.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.8	14.19	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:8	31.36	2838	3.05	13.53	108	192	Off Idle	48.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.77	14.2	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:8	31.36	2843	3.05	13.55	108	192	Off Idle	48.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.76	14.21	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:8	29.99	2834	3.05	13.55	108	192	Off Idle	48.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.68	14.24	0.97	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:06:8	29.99	2854	3.06	13.54	108	192	Off Idle	48.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.74	14.26	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:9	29.99	2861	3.06	13.53	108	192	Off Idle	48	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.77	14.28	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:9	29.99	2855	3.06	13.53	108	192	Off Idle	47.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.82	14.28	0.97	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:06:9	29.99	2854	3.06	13.53	108	192	Off Idle	47.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.9	14.3	0.97	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:06:9	29.99	2868	3.07	13.54	108	192	Off Idle	47.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.97	14.31	0.97	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:06:9	29.99	2860	3.07	13.56	108	192	Off Idle	47.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.98	14.32	0.98	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:06:9	29.99	2860	3.08	13.56	108	192	Off Idle	47.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.99	14.32	0.98	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:06:9	29.99	2868	3.08	13.56	108	192	Off Idle	47.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.99	14.33	0.98	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:0	29.99	2868	3.08	13.56	108	192	Off Idle	47.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.05	14.36	0.98	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:0	29.99	2872	3.08	13.56	108	192	Off Idle	47.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.02	14.37	0.98	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:0	29.99	2878	3.09	13.56	108	192	Off Idle	46.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.03	14.39	0.98	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:0	29.99	2885	3.09	13.55	108	192	Off Idle	46.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.06	14.4	0.98	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:07:0	29.99	2885	3.09	13.54	108	192	Off Idle	46.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.11	14.42	0.98	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:0	29.99	2862	3.09	13.54	108	192	Off Idle	46.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.06	14.45	0.98	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:1	29.99	2880	3.1	13.52	108	192	Off Idle	46.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.14	14.46	0.99	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:1	29.99	2880	3.1	13.53	108	192	Off Idle	46	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.07	14.46	0.99	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:1	29.99	2882	3.1	13.54	108	192	Off Idle	45.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.15	14.45	0.98	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:1	29.99	2890	3.1	13.54	108	192	Off Idle	45.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.12	14.43	0.98	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:1	29.99	2892	3.1	13.55	108	192	Off Idle	45.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.17	14.43	0.98	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:1	29.99	2892	3.11	13.55	108	191	Off Idle	45	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.17	14.43	0.98	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:1	29.99	2900	3.11	13.54	108	191	Off Idle	45	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.25	14.44	0.98	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:07:2	29.99	2900	3.11	13.54	108	191	Off Idle	44.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.27	14.45	0.98	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:2	29.99	2914	3.11	13.54	108	192	Off Idle	44.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.27	14.45	0.98	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:2	29.99	2904	3.12	13.54	108	192	Off Idle	44.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.3	14.45	0.98	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:07:2	29.99	2912	3.12	13.56	108	192	Off Idle	44.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.33	14.47	0.99	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:2	29.99	2912	3.12	13.54	108	192	Off Idle	44.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.37	14.5	0.99	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:2	29.99	2903	3.12	13.55	108	192	Off Idle	44.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.39	14.52	0.99	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:3	28.63	2918	3.13	13.54	108	192	Off Idle	44	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.4	14.53	0.99	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:3	28.63	2916	3.13	13.55	108	192	Off Idle	43.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.43	14.55	0.99	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:3	28.63	2914	3.13	13.55	108	192	Off Idle	43.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.47	14.54	0.99	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:3	28.63	2917	3.14	13.53	108	192	Off Idle	43.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.51	14.56	0.99	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:3	28.63	2917	3.14	13.55	108	192	Off Idle	43.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.5	14.58	0.99	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:3	29.99	2921	3.14	13.54	108	192	Off Idle	43.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.56	14.59	0.99	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:4	29.99	2932	3.14	13.54	108	192	Off Idle	43.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.52	14.62	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:4	29.99	2946	3.15	13.55	108	192	Off Idle	43.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.57	14.63	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:4	29.99	2969	3.15	13.55	108	192	Off Idle	43.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.53	14.67	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:4	29.99	2958	3.15	13.53	108	192	Off Idle	43.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.57	14.67	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:4	29.99	2946	3.15	13.54	108	191	Off Idle	43.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.6	14.68	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:4	29.99	2946	3.16	13.55	108	191	Off Idle	43	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.65	14.72	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:4	29.99	2941	3.16	13.53	108	191	Off Idle	42.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.7	14.73	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:5	29.99	2942	3.16	13.51	108	192	Off Idle	42.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.72	14.74	1	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:07:5	29.99	2948	3.16	13.51	108	192	Off Idle	42.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	1.8	14.74	1	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:07:5	29.99	2949	3.17	13.51	108	192	Off Idle	42.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	1.82	14.75	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:5	29.99	2948	3.17	13.53	108	192	Off Idle	42	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.82	14.76	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:5	29.99	2956	3.17	13.53	108	192	Off Idle	41.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.84	14.77	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:5	29.99	2955	3.17	13.52	108	192	Off Idle	41.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.81	14.78	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:6	29.99	2958	3.17	13.52	107	191	Off Idle	41.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	1.83	14.81	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:6	29.99	2965	3.18	13.54	107	191	Off Idle	41.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	1.81	14.81	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:6	29.99	2958	3.18	13.53	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	1.86	14.8	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:07:6	29.99	2968	3.18	13.53	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	1.88	14.8	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:07:6	29.99	2982	3.18	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	1.91	14.83	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:07:6	29.99	2976	3.18	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	1.98	14.86	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:07:6	29.99	2972	3.19	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	1.97	14.89	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:07:7	29.99	2974	3.19	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	2.05	14.9	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:07:7	29.99	2977	3.19	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	2.1	14.93	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:07:7	29.99	2988	3.19	13.56	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	2.01	14.98	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:07:7	29.99	2994	3.19	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	2	15	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:07:7	29.99	2997	3.2	13.54	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	2.01	15.05	1.03	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:7	29.99	3000	3.2	13.54	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	2.07	15.13	1.03	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:8	29.99	3004	3.2	13.53	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	2.02	15.15	1.03	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:8	29.99	3005	3.2	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	2.06	15.14	1.03	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:8	29.99	3028	3.2	13.53	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	2.06	15.12	1.03	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:8	29.99	3014	3.21	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	2.04	15.07	1.03	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:8	29.99	2999	3.21	13.53	108	191	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	2.02	15.02	1.02	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:8	29.99	3008	3.21	13.52	108	191	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.12	14.93	1.02	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:9	29.99	3010	3.21	13.53	108	191	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.13	14.89	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:9	28.63	3013	3.21	13.53	108	191	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.15	14.85	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:9	28.63	3021	3.22	13.54	108	191	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.19	14.82	1.01	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:07:9	28.63	3021	3.22	13.53	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	2.1	14.73	1	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:07:9	28.63	3028	3.22	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	2.21	14.71	1	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:9	28.63	3054	3.22	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	2.2	14.7	1	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:07:9	28.63	3024	3.22	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	2.32	14.74	1	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:08:0	28.63	3020	3.23	13.56	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	2.28	14.78	1.01	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:08:0	28.63	3021	3.23	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	2.33	14.81	1.01	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:08:0	28.63	2971	3.23	13.56	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	2.44	14.82	1.01	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:08:0	28.63	2998	3.23	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	2.42	14.83	1.01	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:08:0	28.63	3042	3.23	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	2.5	14.85	1.01	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:08:0	28.63	3058	3.24	13.52	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	2.52	14.88	1.01	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:08:1	28.63	3067	3.24	13.53	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	2.52	14.91	1.02	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:08:1	28.63	3079	3.24	13.52	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	2.52	14.95	1.02	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:08:1	28.63	3078	3.24	13.52	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	2.51	14.99	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:08:1	28.63	3073	3.24	13.52	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	2.49	15.01	1.02	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:08:1	28.63	3057	3.25	13.52	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	2.52	15.04	1.02	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:1	28.63	3056	3.25	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	2.57	15.07	1.03	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:1	28.63	3056	3.25	13.54	108	191	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	2.54	15.12	1.03	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:2	28.63	3060	3.25	13.55	108	191	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	2.49	15.11	1.03	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:2	28.63	3060	3.26	13.54	108	191	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	2.52	15.09	1.03	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:2	28.63	3060	3.26	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	2.54	15.05	1.03	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:2	28.63	3068	3.26	13.55	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	2.52	15.03	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:2	28.63	3076	3.26	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	2.51	14.99	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:2	28.63	3087	3.26	13.54	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	2.55	14.96	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:3	28.63	3098	3.26	13.55	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	2.61	14.95	1.02	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:3	28.63	3076	3.27	13.55	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	2.66	14.94	1.02	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:3	28.63	3088	3.27	13.54	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	2.71	14.86	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:3	28.63	3109	3.27	13.53	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	2.77	14.84	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:3	28.63	3109	3.27	13.53	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	2.77	14.85	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:3	29.99	3127	3.27	13.52	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	2.81	14.88	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:4	29.99	3128	3.28	13.52	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	2.77	14.96	1.02	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:4	29.99	3126	3.28	13.53	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	2.8	14.98	1.02	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:4	28.63	3108	3.28	13.53	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	2.78	14.94	1.02	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:4	28.63	3116	3.28	13.53	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	2.83	14.8	1.01	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:4	28.63	3109	3.28	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	2.78	14.7	1	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:4	28.63	3106	3.28	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	2.75	14.59	0.99	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:4	28.63	3099	3.28	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	2.74	14.42	0.98	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:5	28.63	3100	3.28	13.57	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	2.7	14.26	0.97	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:5	28.63	3114	3.29	13.55	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	2.72	14.07	0.96	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:5	28.63	3136	3.29	13.54	108	192	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.84	13.8	0.94	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:5	28.63	3136	3.29	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	2.89	13.66	0.93	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:5	28.63	3148	3.29	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	2.93	13.57	0.92	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:08:5	28.63	3148	3.29	13.55	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	2.96	13.5	0.92	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:6	28.63	3157	3.29	13.53	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.89	13.44	0.92	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:6	28.63	3154	3.3	13.54	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.88	13.4	0.91	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:6	28.63	3154	3.3	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.93	13.35	0.91	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:6	28.63	3150	3.3	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.95	13.32	0.91	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:6	28.63	3134	3.3	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.95	13.29	0.9	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:6	28.63	3140	3.3	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.94	13.23	0.9	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:6	28.63	3159	3.3	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.95	13.22	0.9	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:7	28.63	3173	3.31	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.86	13.21	0.9	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:7	28.63	3176	3.31	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.96	13.2	0.9	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:7	28.63	3186	3.31	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.94	13.19	0.9	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:7	28.63	3186	3.31	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.98	13.18	0.9	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:7	28.63	3197	3.31	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.96	13.17	0.9	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:7	28.63	3176	3.31	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.99	13.17	0.9	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:8	28.63	3182	3.31	13.54	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	3	13.18	0.9	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:8	28.63	3182	3.31	13.54	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	3.01	13.21	0.9	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:8	28.63	3184	3.31	13.54	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	3.02	13.2	0.9	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:8	28.63	3188	3.31	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.98	13.19	0.9	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:8	28.63	3191	3.31	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.94	13.18	0.9	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:08:8	28.63	3191	3.31	13.54	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.89	13.18	0.9	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:9	28.63	3198	3.31	13.53	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.91	13.17	0.9	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:09:08:9	28.63	3197	3.31	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.74	13.15	0.9	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:09:08:9	28.63	3208	3.31	13.53	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.75	13.13	0.89	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:9	28.63	3209	3.31	13.55	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.68	13.11	0.89	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:9	28.63	3214	3.31	13.55	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.68	13.09	0.89	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:08:9	28.63	3218	3.3	13.54	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.61	13.08	0.89	3.4	6.5	ON	28 Pin	OFF	Removed	Disabled
03:09:08:9	28.63	3225	3.3	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.63	13.05	0.89	3.4	6.5	ON	28 Pin	OFF	Removed	Disabled
03:09:09:0	28.63	3225	3.3	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.57	13.05	0.89	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:0	28.63	3247	3.3	13.53	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.58	13.06	0.89	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:0	29.99	3232	3.3	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.58	13.06	0.89	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:0	29.99	3242	3.3	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.51	13.05	0.89	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:0	29.99	3243	3.3	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.52	13.06	0.89	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:0	29.99	3245	3.29	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.51	13.06	0.89	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:1	29.99	3243	3.29	13.54	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.55	13.07	0.89	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:1	29.99	3243	3.29	13.54	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.48	13.07	0.89	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:1	29.99	3244	3.29	13.52	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.57	13.08	0.89	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:1	29.99	3248	3.29	13.54	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.52	13.09	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:09:1	29.99	3249	3.29	13.51	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.47	13.09	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:09:1	29.99	3254	3.29	13.53	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.36	13.07	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:09:1	29.99	3255	3.29	13.52	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.32	13.08	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:09:2	29.99	3262	3.29	13.53	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.26	13.09	0.89	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:09:2	29.99	3273	3.29	13.52	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.27	13.09	0.89	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:09:2	29.99	3274	3.28	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.19	13.11	0.89	3.4	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:09:2	29.99	3276	3.28	13.53	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	2.21	13.14	0.89	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:09:2	29.99	3274	3.28	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.1	13.15	0.9	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:09:2	29.99	3274	3.28	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.13	13.16	0.9	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:09:3	29.99	3275	3.28	13.55	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.11	13.18	0.9	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:09:3	29.99	3269	3.28	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.11	13.21	0.9	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:09:3	29.99	3269	3.28	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.03	13.21	0.9	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:09:3	29.99	3280	3.27	13.53	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.07	13.21	0.9	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:3	29.99	3304	3.27	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	2.05	13.23	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:3	29.99	3300	3.27	13.52	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.02	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:4	29.99	3304	3.27	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.9	13.23	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:4	31.36	3314	3.27	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.91	13.22	0.9	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:4	31.36	3300	3.26	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.7	13.21	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:09:09:4	31.36	3300	3.26	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.75	13.2	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:09:09:4	31.36	3300	3.26	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.61	13.2	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:09:4	31.36	3302	3.26	13.53	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.58	13.2	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:09:4	29.99	3298	3.25	13.53	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.61	13.19	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:09:5	29.99	3304	3.25	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.58	13.2	0.9	3.6	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:09:5	29.99	3314	3.25	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.49	13.2	0.9	3.6	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:09:5	29.99	3314	3.25	13.54	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.44	13.19	0.9	3.6	5.9	ON	28 Pin	OFF	Removed	Disabled
03:09:09:5	31.36	3316	3.24	13.56	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.38	13.19	0.9	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:09:5	31.36	3318	3.24	13.55	107	191	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.2	13.2	0.9	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:09:5	31.36	3323	3.23	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.24	13.19	0.9	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:09:6	31.36	3328	3.23	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.08	13.18	0.9	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:09:6	31.36	3329	3.22	13.54	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	1.02	13.19	0.9	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:09:6	31.36	3329	3.22	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.86	13.18	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:09:6	31.36	3334	3.21	13.56	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.68	13.16	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:09:6	32.72	3348	3.21	13.57	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.64	13.15	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:09:6	32.72	3339	3.2	13.57	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.56	13.15	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:6	32.72	3339	3.19	13.57	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.46	13.14	0.89	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:09:7	32.72	3342	3.18	13.56	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.46	13.14	0.89	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:09:7	32.72	3324	3.18	13.56	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.37	13.14	0.89	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:09:7	31.36	3344	3.18	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.36	13.13	0.89	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:09:7	31.36	3344	3.17	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.29	13.12	0.89	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:09:7	31.36	3344	3.16	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.16	13.15	0.9	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:09:7	31.36	3374	3.15	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.06	13.17	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:8	32.72	3349	3.15	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	0.04	13.21	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:8	32.72	3350	3.14	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.18	13.22	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:8	32.72	3362	3.13	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.24	13.24	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:8	32.72	3367	3.13	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.4	13.26	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:09:8	32.72	3369	3.12	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.41	13.29	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:09:8	32.72	3368	3.12	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.46	13.32	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:09:9	32.72	3363	3.11	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.53	13.35	0.91	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:09:9	32.72	3362	3.11	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.63	13.37	0.91	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:09:9	32.72	3363	3.1	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.66	13.39	0.91	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:09:9	32.72	3364	3.09	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.73	13.41	0.91	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:09:9	32.72	3368	3.09	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.81	13.43	0.91	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:09:9	32.72	3373	3.08	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.93	13.45	0.92	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:09:9	34.08	3402	3.07	13.53	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1	13.48	0.92	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:10:0	34.08	3380	3.07	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.19	13.5	0.92	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:09:10:0	34.08	3384	3.06	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.23	13.53	0.92	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:0	34.08	3383	3.05	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.33	13.55	0.92	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:0	34.08	3377	3.04	13.53	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.54	13.57	0.92	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:0	34.08	3375	3.03	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.62	13.58	0.92	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:0	34.08	3373	3.02	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.81	13.59	0.93	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:10:1	34.08	3373	3.01	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.89	13.6	0.93	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:1	34.08	3379	3	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.02	13.6	0.93	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:1	34.08	3382	2.98	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.16	13.64	0.93	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:10:1	34.08	3391	2.97	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.21	13.64	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:10:1	34.08	3390	2.96	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.37	13.64	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:10:1	34.08	3394	2.94	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.49	13.63	0.93	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:10:1	34.08	3391	2.94	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.69	13.63	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:10:2	34.08	3391	2.93	13.58	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.73	13.65	0.93	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:10:2	34.08	3391	2.91	13.58	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.79	13.66	0.93	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:10:2	34.08	3400	2.9	13.58	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.92	13.67	0.93	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:10:2	34.08	3389	2.89	13.57	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.95	13.69	0.93	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:10:2	34.08	3389	2.88	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.04	13.71	0.93	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:10:2	35.45	3395	2.87	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.15	13.75	0.94	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:10:3	35.45	3403	2.86	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.3	13.82	0.94	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:10:3	35.45	3413	2.85	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.43	13.88	0.95	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:10:3	35.45	3414	2.84	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.48	13.94	0.95	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:3	35.45	3410	2.83	13.53	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.62	13.99	0.95	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:3	35.45	3401	2.82	13.55	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.72	14.06	0.96	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:3	35.45	3396	2.81	13.55	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.77	14.1	0.96	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:10:4	35.45	3398	2.81	13.54	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.87	14.14	0.96	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:10:4	35.45	3398	2.79	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.98	14.18	0.97	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:10:4	35.45	3402	2.79	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.04	14.22	0.97	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:10:4	35.45	3397	2.78	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.11	14.25	0.97	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:10:4	35.45	3402	2.77	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.18	14.26	0.97	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:10:4	35.45	3407	2.77	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.24	14.28	0.97	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:4	35.45	3407	2.76	13.57	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.32	14.32	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:5	35.45	3410	2.75	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.4	14.35	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:10:5	35.45	3414	2.74	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.46	14.42	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:5	35.45	3410	2.74	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.51	14.47	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:5	35.45	3410	2.73	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.51	14.55	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:5	35.45	3413	2.72	13.54	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.54	14.59	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:5	35.45	3413	2.72	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.55	14.63	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:10:6	35.45	3415	2.71	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.57	14.68	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:10:6	35.45	3404	2.71	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.58	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:10:6	35.45	3410	2.7	13.57	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.67	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:10:6	35.45	3408	2.7	13.57	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.68	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:10:6	35.45	3410	2.7	13.56	107	191	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.77	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:6	35.45	3415	2.69	13.57	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.78	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:6	35.45	3428	2.69	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.84	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:7	35.45	3418	2.68	13.55	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.87	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:10:7	35.45	3420	2.68	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.97	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:10:7	35.45	3420	2.67	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.96	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:10:7	35.45	3432	2.67	13.57	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.14	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:10:7	35.45	3426	2.67	13.57	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.22	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:10:7	35.45	3425	2.66	13.57	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.36	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:10:8	35.45	3396	2.63	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.72	15.17	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:10:8	35.45	3396	2.6	13.57	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.04	15.19	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:09:10:8	35.45	3434	2.58	13.56	107	192	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.41	15.2	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:8	36.81	3411	2.51	13.57	107	192	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.13	15.22	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:10:8	36.81	3399	2.46	13.56	107	192	Full Load	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.51	15.19	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:10:8	36.81	3399	2.41	13.56	107	192	Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.96	15.15	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:10:9	36.81	3382	2.36	13.55	107	192	Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.29	15.1	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:10:9	36.81	3308	2.31	13.55	107	192	Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.7	15.01	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:10:9	31.36	3300	2.24	13.55	107	192	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.03	14.95	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:9	25.9	3268	2.2	13.55	107	192	Idle	40.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-9.13	14.88	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:9	20.45	3268	2.15	13.56	107	192	Idle	39.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-9.27	14.81	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:9	20.45	3272	2.1	13.56	107	192	Idle	39.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-9.33	14.7	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:10:9	20.45	3265	2.04	13.56	107	192	Idle	39.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-9.35	14.58	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:0	20.45	3257	1.99	13.55	107	192	Idle	39.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-9.4	14.47	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:0	20.45	3201	1.92	13.56	107	192	Idle	39.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.46	14.31	0.97	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:0	20.45	3180	1.9	13.56	107	192	Idle	39.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.45	14.18	0.97	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:0	20.45	3156	1.83	13.58	107	192	Idle	39.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.48	14	0.96	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:0	20.45	3125	1.79	13.57	107	192	Idle	38.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.47	13.93	0.95	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:0	20.45	3117	1.75	13.56	107	191	Idle	38.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.45	13.86	0.94	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:1	20.45	3084	1.72	13.57	107	191	Idle	38.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.39	13.67	0.93	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:1	20.45	3064	1.71	13.55	107	192	Idle	37.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.42	13.55	0.92	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:1	20.45	3027	1.71	13.56	107	192	Idle	36.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.37	13.45	0.92	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:1	20.45	2928	1.72	13.57	107	192	Idle	36.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.34	13.34	0.91	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:1	20.45	2954	1.73	13.56	107	192	Idle	36.5	0	2	132	944 Turbo	0.17	Rich	1	14.6	-9.31	13.3	0.91	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:1	20.45	2944	1.73	13.58	107	192	Idle	34.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.27	13.25	0.9	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:1	20.45	2925	1.73	13.58	107	192	Idle	33.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.23	13.24	0.9	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:2	19.09	2894	1.74	13.56	107	192	Idle	32.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.21	13.26	0.9	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:2	19.09	2858	1.74	13.56	107	192	Idle	30.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.14	13.31	0.91	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:2	19.09	2846	1.75	13.55	107	192	Idle	29.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.08	13.33	0.91	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:2	19.09	2812	1.75	13.56	107	192	Idle	28.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	13.4	0.91	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:2	19.09	2797	1.76	13.54	107	192	Idle	27.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	13.59	0.93	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:2	19.09	2762	1.76	13.55	107	192	Idle	27.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	13.79	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:11:3	19.09	2754	1.77	13.56	107	192	Idle	27.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.86	13.98	0.95	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:3	19.09	2712	1.79	13.56	107	192	Idle	27.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	14.16	0.96	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:3	19.09	2712	1.8	13.56	107	192	Idle	27.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	14.69	1	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:3	19.09	2656	1.8	13.56	107	191	Idle	27.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	15.04	1.02	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:3	19.09	2652	1.81	13.55	107	191	Idle	27.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.72	16.05	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:3	19.09	2626	1.81	13.54	107	191	Idle	28.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.68	17.04	1.16	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:4	19.09	2587	1.82	13.54	107	191	Idle	29.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.64	17.96	1.22	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:4	19.09	2582	1.82	13.55	107	192	Idle	30.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.63	18.54	1.26	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:4	19.09	2555	1.82	13.55	107	192	Idle	30.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.63	19.1	1.3	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:4	19.09	2538	1.82	13.55	107	192	Idle	32.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	19.9	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:4	19.09	2538	1.81	13.56	107	192	Full Load	33.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.67	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:4	19.09	2486	1.81	13.56	107	192	Off Idle	34.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:4	19.09	2468	1.81	13.57	107	192	Off Idle	35.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.61	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:5	19.09	2459	1.81	13.57	107	192	Off Idle	36.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.55	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:11:5	9.54	2352	1.81	13.58	107	192	Off Idle	37.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.45	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:11:5	12.27	2415	1.81	13.55	107	192	Off Idle	37.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.34	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:11:5	12.27	2398	1.81	13.55	107	192	Off Idle	43.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.3	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:09:11:5	14.99	2392	1.81	13.54	107	192	Off Idle	45.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.26	20.23	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:09:11:5	17.72	2372	1.8	13.53	107	192	Off Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.24	20.23	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:09:11:6	17.72	2348	1.79	13.54	107	192	Off Idle	53.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.23	20.23	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:09:11:6	20.45	2373	1.77	13.56	107	192	Off Idle	55.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.24	20.23	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:09:11:6	23.18	2407	1.78	13.57	107	192	Off Idle	60.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.2	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:11:6	23.18	2407	1.8	13.57	106	192	Off Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.09	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:11:6	25.9	2454	1.81	13.57	106	192	Off Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.84	20.24	1.38	3.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:11:6	28.63	2508	1.83	13.58	106	192	Off Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.68	20.24	1.38	3.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:6	28.63	2535	1.84	13.6	106	192	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.39	20.24	1.38	3.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:11:7	31.36	2594	1.87	13.6	106	192	Off Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.21	20.25	1.38	3.3	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:11:7	34.08	2577	1.92	13.6	106	192	Off Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.01	20.24	1.38	3.3	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:11:7	34.08	2589	1.96	13.6	107	192	Off Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.72	20.24	1.38	3.3	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:11:7	34.08	2606	2	13.59	107	192	Off Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.72	20.24	1.38	3.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:11:7	34.08	2614	2.04	13.59	106	191	Off Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.35	20.23	1.38	3.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:11:7	34.08	2681	2.06	13.6	106	191	Off Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.11	20.23	1.38	3.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:11:8	34.08	2612	2.08	13.59	106	191	Off Idle	66.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-5.81	20.24	1.38	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:11:8	34.08	2612	2.09	13.59	106	191	Off Idle	66.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-5.69	20.24	1.38	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:11:8	34.08	2511	2.12	13.6	106	192	Off Idle	64.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-5.57	20.24	1.38	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:11:8	34.08	2439	2.17	13.59	106	192	Off Idle	64.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-5.42	20.24	1.38	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:11:8	34.08	2423	2.19	13.56	106	192	Off Idle	64.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.28	20.24	1.38	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:11:8	34.08	2419	2.23	13.56	106	192	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.2	20.25	1.38	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:11:9	34.08	2429	2.26	13.56	106	192	Off Idle	64	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.12	20.25	1.38	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:11:9	34.08	2440	2.3	13.56	106	192	Off Idle	64.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.04	20.26	1.38	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:11:9	34.08	2501	2.32	13.56	106	192	Off Idle	64.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.01	20.21	1.38	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:11:9	32.72	2507	2.32	13.57	106	192	Off Idle	64.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.97	20.1	1.37	3.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:11:9	32.72	2557	2.34	13.57	106	192	Off Idle	65.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.97	19.85	1.35	3.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:11:9	32.72	2591	2.35	13.56	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.92	19.61	1.34	3.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:11:9	32.72	2581	2.36	13.56	106	192	Off Idle	66	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.86	19.18	1.31	3.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:12:0	32.72	2566	2.37	13.56	106	192	Off Idle	66	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.79	18.84	1.28	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:12:0	32.72	2545	2.36	13.56	106	192	Off Idle	66.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.71	18.3	1.25	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:0	32.72	2533	2.37	13.57	106	192	Off Idle	66.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.66	17.91	1.22	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:0	32.72	2500	2.37	13.57	106	192	Off Idle	66.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.65	17.52	1.19	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:0	32.72	2476	2.38	13.58	106	192	Off Idle	66.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.56	17.15	1.17	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:0	32.72	2477	2.38	13.59	106	192	Off Idle	66	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.48	16.69	1.14	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:1	32.72	2497	2.38	13.59	106	192	Off Idle	66	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.44	16.31	1.11	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:1	32.72	2509	2.38	13.57	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.39	16.02	1.09	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:1	32.72	2526	2.39	13.58	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.37	15.94	1.09	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:1	32.72	2537	2.39	13.58	106	192	Off Idle	65.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.38	15.73	1.07	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:1	32.72	2553	2.4	13.58	106	192	Off Idle	64.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.36	15.58	1.06	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:1	32.72	2551	2.4	13.57	106	192	Off Idle	64.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.38	15.54	1.06	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:1	32.72	2537	2.41	13.58	106	192	Off Idle	64.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.37	15.5	1.06	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:12:2	32.72	2531	2.41	13.59	106	192	Off Idle	64.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.36	15.49	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:12:2	32.72	2513	2.42	13.58	106	192	Off Idle	64.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.35	15.44	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:12:2	32.72	2508	2.42	13.56	106	192	Off Idle	65.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.35	15.41	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:12:2	32.72	2498	2.42	13.56	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-4.36	15.38	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:12:2	32.72	2502	2.42	13.56	106	192	Off Idle	65.6	0	2	132	944 Turbo	0.7	Lean	1	14.6	-4.36	15.35	1.05	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:2	32.72	2517	2.42	13.56	106	192	Off Idle	65.8	0	2	132	944 Turbo	0.74	Lean	1	14.6	-4.36	15.33	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:3	32.72	2522	2.42	13.56	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.36	15.31	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:3	32.72	2536	2.42	13.57	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.29	15.25	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:3	32.72	2540	2.42	13.56	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.26	15.16	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:12:3	32.72	2546	2.42	13.55	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.25	15.1	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:3	32.72	2536	2.42	13.55	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.22	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:3	32.72	2530	2.42	13.55	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.18	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:4	32.72	2530	2.43	13.55	106	192	Off Idle	65.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.11	14.91	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:4	32.72	2530	2.44	13.58	106	192	Off Idle	65.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.08	14.86	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:4	32.72	2523	2.44	13.57	106	192	Off Idle	65.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.04	14.81	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:4	32.72	2528	2.44	13.57	106	192	Off Idle	65.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.02	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:4	32.72	2538	2.45	13.57	106	192	Off Idle	65	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.02	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:4	32.72	2537	2.45	13.56	106	192	Off Idle	65	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.04	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:4	32.72	2549	2.45	13.54	106	192	Off Idle	65	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:5	32.72	2548	2.46	13.53	106	192	Off Idle	64.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.98	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:12:5	32.72	2542	2.46	13.55	106	192	Off Idle	64.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.96	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:5	32.72	2537	2.46	13.55	106	192	Off Idle	64.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.96	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:5	32.72	2537	2.47	13.56	106	192	Off Idle	64.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.94	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:5	32.72	2530	2.47	13.56	106	192	Off Idle	64.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.92	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:5	32.72	2528	2.48	13.55	106	192	Off Idle	64.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.87	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:6	32.72	2530	2.48	13.53	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.76	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:6	32.72	2538	2.49	13.53	106	192	Off Idle	63.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.73	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:6	32.72	2553	2.49	13.56	106	192	Off Idle	63.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.68	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:6	32.72	2554	2.49	13.57	106	192	Off Idle	63.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.64	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:6	32.72	2564	2.5	13.57	106	192	Off Idle	63.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.62	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:6	32.72	2554	2.5	13.58	106	192	Off Idle	63.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.59	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:6	32.72	2548	2.5	13.58	106	192	Off Idle	63.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.62	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:7	32.72	2548	2.51	13.58	106	192	Off Idle	63.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.59	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:7	32.72	2545	2.51	13.58	106	192	Off Idle	63.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.59	14.82	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:7	32.72	2531	2.52	13.58	106	192	Off Idle	63.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.55	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:7	32.72	2542	2.52	13.58	106	192	Off Idle	63.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.55	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:7	32.72	2544	2.52	13.57	106	192	Off Idle	63.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.51	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:7	32.72	2553	2.52	13.57	106	192	Off Idle	63.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.51	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:8	32.72	2552	2.52	13.56	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.49	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:8	32.72	2552	2.53	13.56	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.49	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:8	32.72	2553	2.53	13.55	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.51	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:12:8	32.72	2554	2.53	13.55	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.52	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:8	32.72	2553	2.53	13.55	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.49	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:8	32.72	2550	2.53	13.55	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.54	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:9	32.72	2554	2.53	13.53	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.52	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:9	32.72	2555	2.53	13.54	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.48	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:9	32.72	2556	2.53	13.53	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.47	14.86	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:9	32.72	2561	2.53	13.54	106	192	Off Idle	64.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.52	14.86	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:9	32.72	2560	2.53	13.54	106	192	Off Idle	63.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.45	14.86	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:9	32.72	2560	2.53	13.56	106	192	Off Idle	63.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.45	14.85	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:12:9	32.72	2560	2.53	13.56	106	192	Off Idle	63.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.4	14.85	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:0	32.72	2563	2.53	13.56	106	192	Off Idle	63.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.41	14.85	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:0	32.72	2568	2.53	13.55	106	192	Off Idle	63.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.41	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:0	32.72	2566	2.53	13.55	106	192	Off Idle	63.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.43	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:0	32.72	2561	2.54	13.56	106	192	Off Idle	63.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.43	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:0	32.72	2558	2.54	13.54	106	192	Off Idle	63.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.46	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:0	32.72	2559	2.54	13.56	106	192	Off Idle	63.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.48	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:1	32.72	2559	2.54	13.56	106	192	Off Idle	63.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.46	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:13:1	32.72	2569	2.54	13.56	106	192	Off Idle	63.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.45	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:13:1	32.72	2576	2.54	13.56	106	192	Off Idle	63.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.43	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:13:1	32.72	2576	2.54	13.56	106	192	Off Idle	63.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.45	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:13:1	32.72	2580	2.54	13.55	106	192	Off Idle	63.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	-3.44	14.85	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:13:1	32.72	2581	2.54	13.55	106	192	Off Idle	63.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-3.46	14.85	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:13:1	32.72	2573	2.54	13.56	106	192	Off Idle	62.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-3.46	14.85	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:13:2	32.72	2573	2.54	13.56	106	192	Off Idle	62.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-3.48	14.85	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:13:2	32.72	2568	2.54	13.56	106	192	Off Idle	62.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-3.45	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:13:2	32.72	2569	2.54	13.56	106	192	Off Idle	62.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-3.41	14.9	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:2	32.72	2570	2.54	13.56	106	192	Off Idle	62.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-3.43	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:2	32.72	2571	2.55	13.56	106	192	Off Idle	62.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.36	14.96	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:2	32.72	2575	2.55	13.56	106	192	Off Idle	62.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-3.36	15.02	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:3	32.72	2579	2.55	13.56	106	192	Off Idle	62.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-3.32	15.05	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:3	32.72	2578	2.55	13.57	106	192	Off Idle	62.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.28	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:3	32.72	2577	2.55	13.56	106	192	Off Idle	62.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.32	15.11	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:3	32.72	2578	2.55	13.58	106	192	Off Idle	62.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.36	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:3	32.72	2580	2.55	13.57	106	192	Off Idle	62.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.4	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:3	32.72	2582	2.55	13.57	106	192	Off Idle	62.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.45	15.03	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:4	32.72	2584	2.55	13.57	106	192	Off Idle	62.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.4	15	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:4	32.72	2584	2.55	13.56	106	192	Off Idle	62.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.42	14.97	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:4	32.72	2586	2.55	13.56	106	192	Off Idle	62.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.39	14.92	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:4	32.72	2576	2.55	13.56	106	192	Off Idle	62.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.37	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:4	32.72	2583	2.55	13.56	106	192	Off Idle	62.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.35	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:4	32.72	2582	2.56	13.56	106	192	Off Idle	62.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.33	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:4	32.72	2581	2.56	13.56	106	192	Off Idle	62.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.34	14.8	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:5	32.72	2582	2.56	13.56	106	192	Off Idle	61.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.3	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:5	32.72	2584	2.56	13.56	106	192	Off Idle	61.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.31	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:5	32.72	2588	2.56	13.55	106	192	Off Idle	61.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-3.4	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:5	32.72	2589	2.56	13.56	106	192	Off Idle	61.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.35	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:5	32.72	2596	2.56	13.56	106	192	Off Idle	61.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.41	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:5	32.72	2597	2.56	13.56	106	192	Off Idle	61.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.41	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:6	32.72	2597	2.56	13.57	106	192	Off Idle	61.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3.39	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:6	32.72	2595	2.56	13.58	106	192	Off Idle	61.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.41	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:6	32.72	2594	2.56	13.58	106	192	Off Idle	61.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.41	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:6	32.72	2594	2.56	13.57	106	192	Off Idle	61.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.41	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:6	32.72	2598	2.56	13.57	106	192	Off Idle	61.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.45	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:6	32.72	2600	2.56	13.56	106	192	Off Idle	61.2	0	2	132	944 Turbo	0.3	Rich	1	14.6	-3.44	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:6	32.72	2600	2.55	13.56	106	192	Off Idle	61.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-3.49	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:7	32.72	2603	2.55	13.56	106	192	Off Idle	60.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-3.47	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:7	32.72	2604	2.55	13.58	106	192	Off Idle	60.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-3.41	15.03	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:7	32.72	2604	2.55	13.58	106	192	Off Idle	60.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.46	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:7	32.72	2605	2.55	13.57	106	192	Off Idle	60.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.49	15.11	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:7	32.72	2604	2.55	13.56	106	192	Off Idle	60.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.47	15.11	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:7	32.72	2599	2.55	13.56	106	192	Off Idle	60.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.49	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:8	32.72	2598	2.55	13.56	106	192	Off Idle	60.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.52	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:8	32.72	2594	2.55	13.57	106	192	Off Idle	60.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.51	15.03	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:13:8	32.72	2599	2.55	13.56	106	192	Off Idle	60.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.49	15.02	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:13:8	32.72	2599	2.55	13.57	106	192	Off Idle	60.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.58	15	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:13:8	32.72	2612	2.55	13.56	106	192	Off Idle	61	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.59	14.96	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:8	32.72	2614	2.55	13.57	106	192	Off Idle	61	0	2	132	944 Turbo	0.52	Rich	1	14.6	-3.59	14.93	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:9	32.72	2616	2.55	13.57	106	192	Off Idle	60.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.61	14.88	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:9	32.72	2617	2.55	13.56	106	192	Off Idle	60.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-3.59	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:9	32.72	2616	2.55	13.54	106	192	Off Idle	60.4	0	2	132	944 Turbo	0.31	Rich	1	14.6	-3.54	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:9	32.72	2614	2.55	13.55	106	192	Off Idle	60.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-3.56	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:9	32.72	2612	2.55	13.55	106	192	Off Idle	60.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-3.55	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:9	32.72	2612	2.55	13.56	106	192	Off Idle	60.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.55	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:13:9	32.72	2637	2.55	13.58	106	192	Off Idle	59.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.55	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:0	32.72	2616	2.55	13.57	106	192	Off Idle	59.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.6	14.9	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:14:0	32.72	2617	2.55	13.58	106	192	Off Idle	59.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.59	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:0	32.72	2620	2.55	13.58	106	192	Off Idle	59.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.6	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:0	32.72	2618	2.55	13.58	106	192	Off Idle	59.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.56	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:14:0	32.72	2617	2.55	13.58	106	192	Off Idle	59.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-3.58	15.02	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:14:0	32.72	2617	2.55	13.58	106	192	Off Idle	59.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	-3.57	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:1	32.72	2618	2.55	13.59	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.66	Lean	1	14.6	-3.57	15.11	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:1	32.72	2618	2.55	13.59	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.69	Lean	1	14.6	-3.58	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:1	32.72	2619	2.55	13.57	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.58	15.06	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:14:1	32.72	2610	2.55	13.57	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.6	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:1	32.72	2626	2.55	13.58	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.62	15.01	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:1	32.72	2625	2.55	13.58	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.62	15	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:1	32.72	2625	2.55	13.56	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-3.61	14.97	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:2	32.72	2635	2.55	13.54	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.58	14.94	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:2	32.72	2627	2.55	13.56	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-3.58	14.93	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:2	32.72	2629	2.55	13.55	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-3.59	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:2	32.72	2631	2.55	13.56	106	192	Off Idle	59.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-3.55	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:2	32.72	2635	2.55	13.55	106	192	Off Idle	59.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-3.54	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:2	32.72	2640	2.55	13.55	106	192	Off Idle	59.3	0	2	132	944 Turbo	0.19	Rich	1	14.6	-3.55	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:3	32.72	2629	2.55	13.56	106	192	Off Idle	59.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.55	14.89	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:14:3	32.72	2629	2.56	13.56	106	192	Off Idle	59	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.57	14.92	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:14:3	32.72	2637	2.55	13.58	106	192	Off Idle	59	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.56	14.94	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:3	32.72	2632	2.55	13.57	106	192	Off Idle	59	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.6	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:3	32.72	2642	2.55	13.57	106	192	Off Idle	59	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.57	14.99	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:3	32.72	2633	2.56	13.57	106	192	Off Idle	59	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.59	15.02	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:4	32.72	2634	2.56	13.57	106	192	Off Idle	59	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.58	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:4	32.72	2634	2.56	13.56	106	192	Off Idle	59	0	2	132	944 Turbo	0.57	Lean	1	14.6	-3.58	15.11	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:4	32.72	2635	2.56	13.56	106	192	Off Idle	59.1	0	2	132	944 Turbo	0.63	Lean	1	14.6	-3.62	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:4	32.72	2638	2.56	13.56	106	192	Off Idle	59.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.6	15.08	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:4	32.72	2642	2.56	13.56	106	192	Off Idle	59.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.56	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:4	32.72	2642	2.56	13.55	106	192	Off Idle	59	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.58	15	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:4	32.72	2624	2.56	13.55	106	192	Off Idle	58.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.57	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:5	32.72	2640	2.56	13.58	106	192	Off Idle	58.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.58	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:5	32.72	2640	2.56	13.57	106	192	Off Idle	58.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.63	14.88	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:5	32.72	2638	2.56	13.56	106	192	Off Idle	58.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.56	14.81	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:5	32.72	2644	2.56	13.56	106	192	Off Idle	58.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.57	14.78	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:5	32.72	2644	2.56	13.57	106	192	Off Idle	58.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.54	14.78	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:6	32.72	2648	2.56	13.56	106	192	Off Idle	58.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.55	14.77	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:6	32.72	2652	2.56	13.56	106	192	Off Idle	58.7	0	2	132	944 Turbo	0.51	Lean	1	14.6	-3.57	14.78	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:6	32.72	2678	2.56	13.58	106	192	Off Idle	58.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-3.62	14.8	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:6	32.72	2659	2.56	13.58	106	192	Off Idle	58.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.57	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:6	32.72	2659	2.56	13.58	106	192	Off Idle	58.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.58	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:6	32.72	2653	2.56	13.58	106	192	Off Idle	58.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.59	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:6	32.72	2652	2.56	13.57	106	192	Off Idle	58.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.52	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:6	32.72	2651	2.56	13.57	106	192	Off Idle	58.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.55	14.81	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:14:7	32.72	2652	2.56	13.56	106	192	Off Idle	58.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.56	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:14:7	32.72	2651	2.57	13.56	106	192	Off Idle	58.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.58	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:7	32.72	2652	2.57	13.56	106	192	Off Idle	58.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.61	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:7	32.72	2656	2.57	13.56	106	192	Off Idle	58	0	2	132	944 Turbo	0.38	Rich	1	14.6	-3.61	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:7	32.72	2652	2.57	13.56	106	192	Off Idle	57.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.6	14.97	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:7	32.72	2652	2.57	13.56	106	192	Off Idle	57.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.59	15.03	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:8	32.72	2655	2.57	13.56	106	192	Off Idle	57.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.56	15.05	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:8	32.72	2655	2.57	13.56	106	192	Off Idle	57.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.53	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:8	32.72	2655	2.57	13.56	106	192	Off Idle	57.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.53	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:8	32.72	2658	2.57	13.56	106	192	Off Idle	57.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.52	15.03	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:8	32.72	2663	2.57	13.54	106	192	Off Idle	57.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.51	14.99	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:8	32.72	2663	2.57	13.56	106	192	Off Idle	57.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.52	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:9	32.72	2656	2.57	13.56	106	192	Off Idle	57.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.53	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:14:9	32.72	2665	2.57	13.57	106	192	Off Idle	57.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	-3.52	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:14:9	32.72	2672	2.57	13.58	106	192	Off Idle	57.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-3.52	14.88	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:9	32.72	2672	2.57	13.57	106	192	Off Idle	57.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.56	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:9	32.72	2677	2.57	13.57	106	192	Off Idle	57.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.55	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:9	32.72	2682	2.57	13.56	106	192	Off Idle	57.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.62	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:14:9	32.72	2681	2.57	13.55	106	192	Off Idle	57.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3.58	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:0	32.72	2680	2.57	13.56	106	192	Off Idle	57.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.6	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:0	32.72	2674	2.57	13.55	106	192	Off Idle	57.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.61	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:0	32.72	2670	2.57	13.56	106	192	Off Idle	57.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.56	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:0	32.72	2667	2.57	13.56	106	192	Off Idle	57.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-3.58	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:0	32.72	2668	2.57	13.56	106	192	Off Idle	57.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-3.55	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:0	32.72	2672	2.57	13.57	106	192	Off Idle	57.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.53	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:1	32.72	2672	2.58	13.56	106	192	Off Idle	57	0	2	132	944 Turbo	0.52	Rich	1	14.6	-3.56	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:1	32.72	2673	2.58	13.56	106	192	Off Idle	57.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.55	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:1	32.72	2676	2.58	13.55	106	192	Off Idle	57.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.53	15.08	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:1	32.72	2679	2.58	13.55	106	192	Off Idle	57.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.5	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:1	32.72	2685	2.58	13.56	106	192	Off Idle	57.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.47	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:1	32.72	2682	2.58	13.56	106	192	Off Idle	56.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.45	15.01	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:1	32.72	2681	2.58	13.56	106	192	Off Idle	56.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.46	14.97	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:2	32.72	2671	2.58	13.57	106	192	Off Idle	56.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.46	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:2	32.72	2670	2.58	13.56	106	192	Off Idle	56.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.45	14.91	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:2	32.72	2678	2.59	13.56	106	192	Off Idle	56.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.43	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:2	32.72	2680	2.59	13.55	106	192	Off Idle	56.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.4	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:2	32.72	2690	2.59	13.54	106	192	Off Idle	56.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.34	14.8	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:2	32.72	2697	2.59	13.55	106	192	Off Idle	56.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.37	14.8	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:3	32.72	2713	2.59	13.58	106	192	Off Idle	56.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.4	14.81	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:3	32.72	2713	2.59	13.57	106	192	Off Idle	55.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.43	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:3	32.72	2696	2.59	13.59	106	192	Off Idle	55.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.42	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:3	32.72	2692	2.59	13.58	106	192	Off Idle	55.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-3.41	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:3	32.72	2689	2.59	13.58	106	192	Off Idle	55.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.45	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:3	32.72	2682	2.59	13.58	106	192	Off Idle	55.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.45	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:4	32.72	2699	2.59	13.58	106	192	Off Idle	55.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.43	14.82	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:15:4	32.72	2700	2.59	13.58	106	192	Off Idle	55.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.48	14.81	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:15:4	32.72	2700	2.6	13.59	106	192	Off Idle	55.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.49	14.81	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:15:4	32.72	2699	2.6	13.58	106	192	Off Idle	55.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.49	14.83	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:15:4	32.72	2706	2.6	13.56	106	192	Off Idle	55.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.53	14.86	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:15:4	32.72	2706	2.6	13.57	106	192	Off Idle	55.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.52	14.88	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:15:4	32.72	2703	2.6	13.58	106	192	Off Idle	55.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.52	14.9	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:5	32.72	2698	2.6	13.58	106	192	Off Idle	55.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.52	14.97	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:5	32.72	2694	2.6	13.57	106	192	Off Idle	55.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.49	14.99	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:5	32.72	2694	2.6	13.58	105	192	Off Idle	55.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.52	15.04	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:5	32.72	2693	2.6	13.56	105	192	Off Idle	55.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.48	15.07	1.03	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:5	32.72	2696	2.6	13.55	105	192	Off Idle	55.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.47	15.08	1.03	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:5	32.72	2708	2.6	13.55	106	192	Off Idle	55.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.47	15.05	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:6	32.72	2708	2.6	13.55	106	192	Off Idle	55.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.49	15.01	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:6	32.72	2710	2.6	13.55	106	192	Off Idle	55.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.52	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:6	32.72	2712	2.6	13.57	106	192	Off Idle	55	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.52	14.91	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:6	32.72	2705	2.6	13.56	106	192	Off Idle	55	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.55	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:6	32.72	2714	2.6	13.57	106	192	Off Idle	54.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.53	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:6	32.72	2710	2.6	13.56	106	192	Off Idle	54.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.58	14.77	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:6	32.72	2710	2.6	13.55	106	192	Off Idle	54.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.51	14.73	1	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:7	32.72	2709	2.6	13.56	106	192	Off Idle	54.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.49	14.71	1	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:7	32.72	2712	2.6	13.57	106	192	Off Idle	54.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.52	14.71	1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:15:7	32.72	2713	2.6	13.56	106	192	Off Idle	54.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.51	14.71	1	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:7	32.72	2719	2.6	13.55	105	192	Off Idle	54.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.55	14.72	1	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:7	32.72	2723	2.6	13.56	105	192	Off Idle	54.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.52	14.74	1	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:7	32.72	2724	2.6	13.57	105	192	Off Idle	54.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3.52	14.78	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:8	32.72	2726	2.6	13.57	106	192	Off Idle	54.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.52	14.8	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:8	32.72	2724	2.6	13.56	106	192	Off Idle	54.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.51	14.83	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:15:8	32.72	2724	2.6	13.56	106	192	Off Idle	54	0	2	132	944 Turbo	0.5	Lean	1	14.6	-3.45	14.86	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:8	32.72	2724	2.6	13.57	106	192	Off Idle	54	0	2	132	944 Turbo	0.56	Lean	1	14.6	-3.49	14.93	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:8	32.72	2744	2.6	13.58	106	192	Off Idle	54	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.54	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:8	32.72	2723	2.6	13.59	106	192	Off Idle	54.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.55	14.94	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:9	32.72	2724	2.6	13.57	106	192	Off Idle	54.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.56	14.96	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:9	32.72	2734	2.6	13.56	106	192	Off Idle	54.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.52	14.95	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:9	34.08	2728	2.6	13.56	106	192	Off Idle	54.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.55	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:9	34.08	2738	2.6	13.56	106	192	Off Idle	54.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.54	14.91	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:15:9	34.08	2736	2.6	13.56	106	192	Off Idle	54.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.53	14.89	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:15:9	34.08	2724	2.6	13.56	106	192	Off Idle	54.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.52	14.87	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:15:9	32.72	2727	2.6	13.57	106	192	Off Idle	54.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-3.55	14.82	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:0	32.72	2727	2.6	13.55	106	192	Off Idle	54.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.55	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:0	32.72	2735	2.6	13.57	106	192	Off Idle	54.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.51	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:0	32.72	2742	2.6	13.56	106	192	Off Idle	54.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.54	14.77	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:0	32.72	2741	2.6	13.56	106	192	Off Idle	54.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.52	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:0	34.08	2745	2.6	13.57	106	192	Off Idle	54	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.55	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:0	34.08	2746	2.6	13.59	106	192	Off Idle	53.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.55	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:1	34.08	2747	2.6	13.59	106	192	Off Idle	53.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.6	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:1	34.08	2746	2.6	13.58	106	192	Off Idle	53.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.63	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:1	34.08	2746	2.6	13.59	106	192	Off Idle	53.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.6	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:1	34.08	2754	2.6	13.56	106	192	Off Idle	53.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-3.64	14.91	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:1	34.08	2740	2.6	13.56	106	192	Off Idle	53.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.62	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:1	34.08	2740	2.6	13.55	106	192	Off Idle	53	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.6	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:1	34.08	2741	2.6	13.56	106	192	Off Idle	52.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.54	15.05	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:2	34.08	2724	2.6	13.56	106	192	Off Idle	52.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.6	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:2	34.08	2734	2.6	13.57	105	192	Off Idle	52.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.56	15.08	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:2	34.08	2751	2.6	13.58	105	192	Off Idle	52.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.6	15.05	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:2	34.08	2757	2.6	13.57	105	192	Off Idle	52.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.61	15.04	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:2	34.08	2756	2.6	13.58	106	192	Off Idle	52.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.64	15.01	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:2	34.08	2755	2.6	13.58	106	192	Off Idle	52.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.61	14.98	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:3	34.08	2753	2.6	13.57	106	192	Off Idle	52.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.67	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:3	34.08	2751	2.6	13.56	106	192	Off Idle	52.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.64	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:3	34.08	2754	2.6	13.56	106	192	Off Idle	52.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.64	14.85	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:3	34.08	2756	2.6	13.56	106	192	Off Idle	52.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.68	14.8	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:3	34.08	2764	2.6	13.57	106	192	Off Idle	52.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.62	14.78	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:3	34.08	2764	2.6	13.56	106	192	Off Idle	52.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.64	14.77	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:4	34.08	2765	2.6	13.57	106	192	Off Idle	52.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.65	14.77	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:4	34.08	2769	2.6	13.57	106	192	Off Idle	52.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-3.63	14.77	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:4	34.08	2769	2.6	13.56	105	192	Off Idle	52.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-3.7	14.77	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:4	34.08	2766	2.6	13.57	105	192	Off Idle	52.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-3.68	14.79	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:4	34.08	2762	2.6	13.57	106	192	Off Idle	52.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-3.73	14.83	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:4	34.08	2761	2.6	13.56	106	192	Off Idle	52.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-3.75	14.86	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:4	34.08	2770	2.6	13.57	106	192	Off Idle	52.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-3.75	14.88	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:5	34.08	2762	2.6	13.58	106	192	Off Idle	52.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-3.74	14.91	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:5	34.08	2773	2.61	13.56	106	192	Off Idle	52.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.67	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:5	34.08	2773	2.61	13.55	106	192	Off Idle	52.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.71	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:5	34.08	2772	2.61	13.54	105	192	Off Idle	52.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.66	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:5	34.08	2780	2.61	13.54	105	192	Off Idle	52.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.7	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:5	34.08	2762	2.61	13.54	105	192	Off Idle	52.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.75	15.05	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:6	34.08	2781	2.61	13.55	105	192	Off Idle	52.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.73	15.03	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:6	34.08	2776	2.61	13.56	105	192	Off Idle	52.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.77	15	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:6	34.08	2769	2.61	13.57	105	192	Off Idle	52.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.72	14.98	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:6	34.08	2771	2.61	13.56	105	192	Off Idle	52.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.68	14.94	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:6	34.08	2773	2.61	13.56	105	192	Off Idle	52.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.62	14.91	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:6	34.08	2780	2.61	13.57	105	192	Off Idle	52.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.64	14.85	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:6	34.08	2782	2.61	13.57	105	192	Off Idle	52.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.62	14.79	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:7	34.08	2784	2.61	13.57	105	192	Off Idle	52	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.61	14.76	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:7	34.08	2795	2.61	13.57	105	192	Off Idle	51.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.62	14.75	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:16:7	34.08	2782	2.61	13.58	105	192	Off Idle	51.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.66	14.75	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:7	34.08	2779	2.61	13.57	105	192	Off Idle	51.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-3.63	14.75	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:7	34.08	2780	2.61	13.57	105	192	Off Idle	51.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.62	14.76	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:7	34.08	2778	2.61	13.57	105	192	Off Idle	51	0	2	132	944 Turbo	0.45	Lean	1	14.6	-3.65	14.76	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:8	34.08	2779	2.61	13.56	106	192	Off Idle	51	0	2	132	944 Turbo	0.42	Lean	1	14.6	-3.66	14.77	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:8	34.08	2788	2.61	13.56	106	192	Off Idle	50.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.68	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:8	34.08	2792	2.61	13.56	106	192	Off Idle	50.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3.64	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:8	34.08	2800	2.61	13.56	105	192	Off Idle	50.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.67	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:8	34.08	2800	2.61	13.58	105	192	Off Idle	50.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.64	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:8	34.08	2800	2.61	13.58	105	192	Off Idle	50	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.63	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:9	34.08	2800	2.61	13.58	105	192	Off Idle	49.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.62	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:16:9	34.08	2799	2.61	13.57	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-3.64	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:9	34.08	2812	2.61	13.58	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-3.65	14.9	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:9	34.08	2796	2.61	13.56	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.65	14.92	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:9	34.08	2774	2.61	13.56	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.64	14.99	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:16:9	34.08	2774	2.61	13.56	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.69	15.02	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:16:9	34.08	2775	2.61	13.56	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.69	15.04	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:0	34.08	2770	2.61	13.57	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.65	15.04	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:0	34.08	2804	2.61	13.56	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.63	15.03	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:0	34.08	2809	2.61	13.57	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.64	15	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:17:0	34.08	2809	2.61	13.57	105	192	Off Idle	49.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.69	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:0	34.08	2825	2.61	13.56	105	192	Off Idle	49.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.69	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:0	34.08	2798	2.61	13.56	105	192	Off Idle	49.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-3.67	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:1	34.08	2798	2.61	13.55	105	192	Off Idle	49.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.65	14.9	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:17:1	34.08	2797	2.62	13.57	105	192	Off Idle	49.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.64	14.83	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:17:1	34.08	2787	2.62	13.56	105	192	Off Idle	49.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.7	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:17:1	34.08	2787	2.62	13.56	105	192	Off Idle	49.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.7	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:17:1	34.08	2803	2.62	13.57	105	192	Off Idle	49.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.73	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:17:1	34.08	2808	2.62	13.57	105	192	Off Idle	49.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.77	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:17:1	34.08	2803	2.61	13.56	105	192	Off Idle	49.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.77	14.88	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:17:2	34.08	2814	2.61	13.57	105	192	Off Idle	49	0	2	132	944 Turbo	0.35	Rich	1	14.6	-3.83	14.9	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:17:2	34.08	2802	2.61	13.58	105	192	Off Idle	48.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-3.84	14.91	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:17:2	34.08	2799	2.61	13.56	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.84	14.93	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:17:2	34.08	2807	2.61	13.58	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.81	14.99	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:17:2	34.08	2807	2.61	13.59	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.86	15.02	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:17:2	34.08	2809	2.61	13.59	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.84	15.01	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:17:3	34.08	2812	2.61	13.58	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.81	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:3	34.08	2814	2.6	13.58	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.83	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:3	34.08	2814	2.6	13.56	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.83	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:3	34.08	2814	2.6	13.56	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.89	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:3	34.08	2812	2.6	13.55	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.91	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:3	34.08	2810	2.6	13.54	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.96	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:4	34.08	2829	2.59	13.55	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.02	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:4	34.08	2809	2.59	13.54	105	192	Off Idle	48.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.05	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:17:4	34.08	2809	2.58	13.56	105	192	Off Idle	49	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.15	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:4	34.08	2810	2.58	13.55	105	192	Off Idle	49	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.2	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:4	34.08	2794	2.57	13.56	105	192	Off Idle	49.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.2	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:4	34.08	2794	2.57	13.56	105	192	Off Idle	49.2	0	2	132	944 Turbo	0.27	Rich	1	14.6	-4.32	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:4	34.08	2824	2.56	13.57	105	192	Off Idle	49.1	0	2	132	944 Turbo	0.22	Rich	1	14.6	-4.4	14.84	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:5	34.08	2823	2.55	13.56	105	192	Off Idle	49.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.51	14.86	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:5	34.08	2821	2.53	13.56	105	192	Off Idle	49	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.73	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:17:5	34.08	2810	2.52	13.57	105	192	Off Idle	49	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.86	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:5	34.08	2800	2.49	13.57	105	192	Off Idle	49	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.19	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:17:5	34.08	2800	2.47	13.57	105	192	Off Idle	49	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.44	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:17:5	34.08	2798	2.42	13.58	105	192	Off Idle	49	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.73	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:6	34.08	2795	2.38	13.57	105	192	Off Idle	49	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.11	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:17:6	34.08	2792	2.34	13.56	105	192	Off Idle	48.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.48	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:17:6	34.08	2792	2.26	13.56	105	192	Full Load	48.9	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.14	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:17:6	34.08	2790	2.21	13.56	105	192	Idle	48.9	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.33	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:17:6	34.08	2788	2.14	13.57	105	192	Idle	48.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.07	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:6	34.08	2778	2.09	13.58	105	192	Idle	49.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.18	15.04	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:6	34.08	2766	2.05	13.57	105	192	Idle	49.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.45	15.02	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:7	34.08	2739	2	13.58	105	192	Idle	49.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.66	15.01	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:7	34.08	2724	1.98	13.6	105	192	Idle	49.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.95	14.96	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:7	28.63	2697	1.93	13.58	105	192	Idle	49.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.08	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:17:7	23.18	2683	1.88	13.57	105	192	Idle	50.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.21	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:17:7	19.09	2723	1.81	13.58	105	192	Idle	50.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.37	14.78	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:7	19.09	2728	1.77	13.56	105	192	Idle	50.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.46	14.7	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:8	19.09	2736	1.73	13.58	105	192	Idle	51.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.55	14.63	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:8	19.09	2766	1.68	13.58	105	192	Idle	51.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.66	14.57	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:8	19.09	2819	1.64	13.58	105	192	Idle	51.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.73	14.48	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:8	19.09	2819	1.61	13.57	105	192	Idle	51.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.78	14.43	0.98	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:8	19.09	2848	1.58	13.59	105	192	Idle	51.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.86	14.41	0.98	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:8	19.09	2848	1.56	13.59	105	192	Idle	50.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.9	14.4	0.98	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:9	19.09	2809	1.55	13.59	105	192	Idle	50.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.93	14.39	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:9	19.09	2802	1.56	13.6	105	192	Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.91	14.4	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:9	19.09	2802	1.56	13.59	105	192	Idle	50.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.89	14.42	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:9	19.09	2772	1.56	13.59	105	192	Idle	50.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.85	14.44	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:9	19.09	2751	1.57	13.59	105	192	Idle	50.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.82	14.47	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:9	19.09	2751	1.56	13.59	105	192	Idle	50	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.8	14.52	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:17:9	19.09	2745	1.56	13.57	105	192	Idle	49.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.77	14.57	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:0	19.09	2749	1.56	13.56	105	192	Idle	49.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.75	14.61	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:0	19.09	2766	1.56	13.57	105	192	Idle	48.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.7	14.64	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:0	19.09	2772	1.57	13.57	105	192	Idle	47.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.66	14.67	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:0	19.09	2792	1.57	13.57	105	192	Idle	47.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.63	14.75	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:0	19.09	2802	1.57	13.58	105	192	Idle	47.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.64	14.86	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:0	19.09	2802	1.58	13.59	105	192	Idle	47.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	14.95	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:1	19.09	2803	1.58	13.58	105	192	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	15.15	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:1	19.09	2798	1.59	13.58	105	192	Idle	48.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	15.48	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:1	19.09	2785	1.59	13.59	105	192	Idle	48.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	15.73	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:1	19.09	2774	1.6	13.58	105	192	Idle	48.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	16.01	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:1	19.09	2772	1.6	13.57	105	192	Idle	48.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	16.32	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:1	19.09	2762	1.6	13.57	105	192	Idle	48.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	16.92	1.15	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:1	19.09	2746	1.61	13.57	105	192	Idle	49.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	17.4	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:2	19.09	2755	1.6	13.55	105	192	Idle	49.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	18.08	1.23	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:2	19.09	2756	1.6	13.57	105	192	Idle	50	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	18.47	1.26	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:2	19.09	2763	1.6	13.56	105	192	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	18.98	1.29	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:2	19.09	2773	1.59	13.58	105	192	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	19.3	1.31	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:2	19.09	2779	1.59	13.58	105	192	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	19.59	1.33	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:2	19.09	2781	1.59	13.58	105	192	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	19.83	1.35	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:3	19.09	2804	1.59	13.57	105	192	Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.04	1.36	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:3	19.09	2780	1.59	13.58	105	192	Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.17	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:3	19.09	2772	1.58	13.56	105	192	Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:3	19.09	2750	1.58	13.56	105	192	Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:3	19.09	2765	1.58	13.56	105	192	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:3	19.09	2755	1.58	13.56	105	192	Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:4	19.09	2750	1.57	13.57	105	192	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:4	19.09	2751	1.57	13.56	105	192	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:4	19.09	2749	1.57	13.58	105	192	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:4	19.09	2748	1.57	13.57	105	192	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:4	19.09	2750	1.57	13.58	105	192	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:4	19.09	2762	1.57	13.58	105	192	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:4	19.09	2753	1.57	13.58	105	192	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:5	19.09	2754	1.57	13.58	105	192	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:5	19.09	2754	1.57	13.59	105	192	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:5	19.09	2750	1.57	13.58	105	192	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:18:5	19.09	2726	1.57	13.58	105	192	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:5	19.09	2737	1.57	13.58	105	192	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:5	19.09	2744	1.57	13.58	105	192	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:6	19.09	2739	1.57	13.58	105	192	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:6	19.09	2737	1.57	13.57	105	192	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:6	19.09	2725	1.57	13.58	105	192	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:6	19.09	2725	1.57	13.58	105	192	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:6	19.09	2720	1.56	13.58	105	192	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:6	19.09	2702	1.56	13.58	105	192	Idle	51.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:6	19.09	2725	1.56	13.58	105	192	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:7	19.09	2726	1.56	13.58	105	192	Idle	51.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:7	19.09	2747	1.56	13.58	105	192	Idle	51.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:7	19.09	2745	1.56	13.58	105	192	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:7	19.09	2746	1.56	13.57	105	192	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:7	19.09	2742	1.56	13.58	105	192	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:7	19.09	2720	1.56	13.59	105	192	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:8	19.09	2723	1.56	13.58	105	192	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:8	19.09	2722	1.56	13.58	105	192	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:8	19.09	2719	1.55	13.58	105	192	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:8	19.09	2721	1.55	13.58	105	192	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:8	19.09	2721	1.55	13.57	105	192	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:8	19.09	2715	1.55	13.58	105	192	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:9	19.09	2731	1.55	13.57	105	192	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:9	19.09	2731	1.55	13.57	105	192	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:9	19.09	2743	1.54	13.58	105	192	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:9	19.09	2734	1.54	13.58	105	192	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:9	19.09	2733	1.54	13.57	105	192	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:9	19.09	2731	1.54	13.56	105	192	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:18:9	19.09	2727	1.54	13.56	105	192	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:0	19.09	2720	1.54	13.56	105	192	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:0	19.09	2700	1.54	13.57	105	192	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:0	19.09	2705	1.54	13.57	105	192	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:0	19.09	2702	1.54	13.58	105	192	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:0	19.09	2700	1.54	13.59	105	192	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:0	19.09	2697	1.54	13.57	105	192	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:1	19.09	2715	1.54	13.59	105	192	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:1	19.09	2715	1.54	13.59	105	192	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:1	19.09	2696	1.54	13.57	105	192	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:1	19.09	2698	1.54	13.57	105	192	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:1	19.09	2700	1.54	13.58	105	192	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:1	19.09	2700	1.54	13.57	105	192	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:1	19.09	2689	1.54	13.56	105	192	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:2	19.09	2689	1.54	13.57	105	192	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:2	19.09	2698	1.54	13.57	105	192	Idle	53.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:2	19.09	2694	1.53	13.58	105	192	Idle	53.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:2	19.09	2690	1.53	13.58	105	192	Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:2	19.09	2689	1.53	13.57	105	192	Idle	53.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:2	19.09	2688	1.53	13.56	105	192	Idle	53.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:3	19.09	2682	1.53	13.56	105	192	Idle	53.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:3	19.09	2683	1.52	13.58	105	192	Idle	53.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:3	19.09	2681	1.52	13.56	105	192	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:3	19.09	2679	1.52	13.56	105	192	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:3	19.09	2675	1.52	13.57	105	192	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:3	19.09	2684	1.52	13.58	105	192	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:4	19.09	2675	1.52	13.58	105	192	Idle	54.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:4	19.09	2680	1.51	13.58	105	192	Idle	54.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:4	19.09	2688	1.51	13.59	105	192	Idle	54.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:4	19.09	2688	1.51	13.57	105	192	Idle	54.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:19:4	19.09	2691	1.51	13.56	105	192	Idle	54.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:4	19.09	2689	1.51	13.57	105	192	Idle	54.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:4	19.09	2689	1.51	13.58	105	192	Idle	54.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:5	19.09	2686	1.51	13.58	105	192	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:5	19.09	2683	1.5	13.57	105	192	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:5	19.09	2672	1.5	13.58	105	192	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:5	19.09	2664	1.5	13.58	105	192	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:5	19.09	2664	1.5	13.57	105	192	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:5	19.09	2654	1.5	13.58	105	192	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:6	19.09	2652	1.5	13.58	105	192	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:6	19.09	2652	1.5	13.58	105	192	Idle	55.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:6	19.09	2652	1.5	13.57	105	192	Idle	55.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:6	19.09	2654	1.49	13.56	105	192	Idle	55.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:6	19.09	2656	1.49	13.58	105	192	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:6	19.09	2656	1.49	13.56	105	192	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:6	19.09	2658	1.49	13.57	105	192	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:7	19.09	2656	1.49	13.56	105	192	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:7	19.09	2653	1.48	13.56	105	192	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:7	19.09	2652	1.48	13.57	105	192	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:7	19.09	2645	1.48	13.57	105	192	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.05	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:7	19.09	2640	1.48	13.56	105	192	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.05	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:7	19.09	2636	1.48	13.57	105	192	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.05	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:8	19.09	2636	1.47	13.56	105	192	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.05	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:8	19.09	2651	1.47	13.57	105	192	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.05	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:8	19.09	2630	1.47	13.57	105	192	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.06	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:8	19.09	2589	1.47	13.58	105	192	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.06	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:8	19.09	2631	1.47	13.58	105	192	Idle	57.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.05	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:8	19.09	2631	1.46	13.59	105	192	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.05	1.37	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:9	19.09	2632	1.46	13.59	105	192	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.05	1.37	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:9	19.09	2634	1.46	13.59	105	192	Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.05	1.37	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:9	19.09	2634	1.46	13.59	105	192	Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:9	19.09	2634	1.46	13.58	105	192	Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:9	19.09	2632	1.46	13.56	105	192	Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:9	19.09	2628	1.46	13.57	105	192	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:19:9	19.09	2626	1.45	13.57	105	192	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:0	19.09	2610	1.45	13.56	105	192	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:0	19.09	2615	1.45	13.57	105	192	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:0	19.09	2612	1.45	13.56	105	192	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:0	19.09	2612	1.44	13.57	105	192	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:0	19.09	2612	1.44	13.57	105	192	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:0	19.09	2614	1.44	13.58	105	192	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:1	19.09	2616	1.44	13.59	105	192	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:1	19.09	2616	1.44	13.58	105	192	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:1	19.09	2618	1.44	13.59	105	192	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:1	19.09	2617	1.44	13.59	105	192	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:1	19.09	2613	1.43	13.57	105	192	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:1	19.09	2609	1.43	13.56	105	192	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:1	19.09	2608	1.43	13.57	105	192	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:2	19.09	2600	1.43	13.56	105	192	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:2	19.09	2592	1.43	13.57	105	192	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:2	19.09	2588	1.43	13.58	105	192	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:2	19.09	2588	1.43	13.58	105	192	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:2	19.09	2587	1.43	13.58	105	192	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:2	19.09	2587	1.42	13.59	105	192	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:3	19.09	2591	1.42	13.58	105	192	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:3	19.09	2592	1.42	13.58	105	192	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:3	19.09	2598	1.42	13.58	105	192	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:3	19.09	2599	1.42	13.58	105	192	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:20:3	19.09	2599	1.42	13.57	105	192	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:3	19.09	2598	1.42	13.59	105	192	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:4	19.09	2593	1.42	13.58	105	192	Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:4	19.09	2592	1.41	13.58	105	192	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:4	19.09	2584	1.41	13.59	105	192	Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:4	19.09	2578	1.41	13.59	105	192	Idle	60	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:4	19.09	2572	1.41	13.58	105	192	Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:4	19.09	2566	1.41	13.59	105	192	Idle	60.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:4	19.09	2566	1.41	13.58	105	192	Idle	60.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:5	19.09	2545	1.41	13.59	105	192	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:5	19.09	2565	1.4	13.58	105	192	Idle	60.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:5	19.09	2566	1.4	13.57	105	192	Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:5	19.09	2569	1.4	13.57	105	192	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:5	19.09	2572	1.4	13.56	105	192	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:5	19.09	2574	1.4	13.57	105	192	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:6	19.09	2572	1.4	13.58	105	192	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:6	19.09	2572	1.4	13.57	105	192	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:6	19.09	2568	1.39	13.58	105	192	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:6	19.09	2560	1.39	13.57	105	192	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:6	19.09	2556	1.39	13.57	105	192	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:6	19.09	2544	1.39	13.56	105	192	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:6	19.09	2516	1.39	13.56	105	192	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:7	19.09	2530	1.39	13.56	105	192	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:7	19.09	2530	1.39	13.57	105	192	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:7	19.09	2532	1.39	13.57	105	192	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:7	19.09	2537	1.38	13.57	105	192	Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:7	19.09	2545	1.38	13.57	105	192	Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:7	19.09	2548	1.38	13.57	105	192	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:8	19.09	2564	1.38	13.56	105	192	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:8	19.09	2558	1.37	13.56	105	192	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:8	19.09	2535	1.37	13.57	104	192	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:8	19.09	2535	1.37	13.57	104	192	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:8	19.09	2550	1.37	13.58	105	192	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:8	19.09	2540	1.37	13.59	105	192	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:9	19.09	2540	1.37	13.59	105	192	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:9	19.09	2519	1.37	13.59	105	192	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:9	19.09	2520	1.37	13.59	105	192	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:9	19.09	2514	1.37	13.58	105	192	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:9	19.09	2515	1.36	13.57	105	192	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:9	19.09	2514	1.36	13.57	105	192	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:20:9	19.09	2511	1.36	13.56	105	192	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:0	19.09	2511	1.36	13.56	105	192	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:0	19.09	2512	1.36	13.57	105	192	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:0	19.09	2512	1.36	13.57	104	192	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:0	19.09	2511	1.36	13.56	104	192	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:0	19.09	2511	1.36	13.58	104	192	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:0	19.09	2508	1.36	13.57	105	192	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:1	19.09	2508	1.36	13.56	105	192	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:1	19.09	2506	1.36	13.58	105	192	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:1	19.09	2508	1.35	13.56	105	192	Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:1	19.09	2510	1.35	13.56	105	192	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:1	19.09	2510	1.35	13.57	105	192	Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:1	19.09	2513	1.34	13.58	105	192	Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:1	19.09	2513	1.34	13.58	105	192	Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:2	19.09	2509	1.34	13.59	105	192	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:2	19.09	2503	1.34	13.59	105	192	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:2	19.09	2503	1.34	13.58	105	192	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:2	19.09	2495	1.34	13.58	105	192	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:21:2	19.09	2487	1.33	13.58	105	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:2	19.09	2487	1.33	13.58	105	192	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:3	19.09	2480	1.33	13.58	105	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:3	19.09	2478	1.33	13.59	105	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:3	19.09	2477	1.32	13.59	105	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:3	19.09	2476	1.32	13.59	105	192	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:3	19.09	2478	1.32	13.61	105	192	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:3	19.09	2480	1.32	13.6	105	192	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:4	19.09	2480	1.31	13.59	105	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:4	19.09	2484	1.31	13.59	105	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:4	19.09	2484	1.31	13.59	105	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:4	19.09	2484	1.31	13.59	105	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:4	19.09	2481	1.31	13.58	105	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:4	19.09	2474	1.31	13.58	105	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:4	19.09	2474	1.3	13.58	105	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:5	19.09	2467	1.3	13.58	105	192	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:5	19.09	2459	1.3	13.58	105	192	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:5	19.09	2459	1.3	13.59	105	192	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:5	19.09	2455	1.3	13.58	105	192	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:5	19.09	2454	1.3	13.59	105	192	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:5	19.09	2454	1.3	13.58	105	192	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:6	19.09	2456	1.29	13.57	105	192	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:6	19.09	2448	1.29	13.56	105	192	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:6	19.09	2456	1.29	13.57	105	192	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:6	19.09	2456	1.29	13.56	105	192	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:6	19.09	2456	1.28	13.59	105	192	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:6	19.09	2454	1.28	13.58	105	192	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:6	19.09	2452	1.28	13.58	105	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:7	19.09	2468	1.28	13.58	105	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:7	19.09	2426	1.27	13.59	105	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:7	19.09	2440	1.27	13.57	105	192	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:7	19.09	2440	1.27	13.58	105	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:7	17.72	2436	1.26	13.57	105	192	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:7	17.72	2435	1.26	13.58	105	192	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:8	17.72	2435	1.26	13.57	105	192	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:8	17.72	2426	1.25	13.59	105	192	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:8	17.72	2436	1.25	13.58	105	192	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:8	17.72	2436	1.25	13.58	105	192	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:8	17.72	2435	1.24	13.58	105	192	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:8	17.72	2434	1.24	13.57	105	192	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:9	17.72	2433	1.24	13.58	105	192	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:9	17.72	2438	1.24	13.57	105	192	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:9	17.72	2438	1.23	13.56	105	192	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:9	17.72	2422	1.23	13.58	105	192	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:9	17.72	2408	1.23	13.58	105	192	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:9	17.72	2413	1.23	13.57	105	192	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:21:9	17.72	2413	1.22	13.57	105	192	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:22:0	17.72	2410	1.22	13.57	105	192	Full Load	69.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:22:0	17.72	2391	1.22	13.56	105	192	Full Load	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:22:0	17.72	2410	1.22	13.56	105	192	Off Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:22:0	17.72	2350	1.23	13.56	105	192	Off Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:22:0	9.54	2450	1.24	13.57	105	192	Off Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:22:0	12.27	2431	1.27	13.58	105	192	Off Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:22:1	12.27	2435	1.28	13.59	105	192	Off Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:1	14.99	2431	1.31	13.59	105	192	Off Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:1	17.72	2431	1.34	13.57	105	192	Off Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:22:1	17.72	2423	1.37	13.56	105	192	Off Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:22:1	20.45	2422	1.38	13.55	105	192	Off Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:22:1	20.45	2421	1.41	13.55	105	192	Off Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:22:1	23.18	2417	1.41	13.55	105	192	Off Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.36	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:22:2	25.9	2425	1.45	13.56	105	192	Off Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.26	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:22:2	25.9	2436	1.48	13.55	105	192	Off Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.18	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:22:2	28.63	2440	1.52	13.58	105	192	Off Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.14	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:22:2	31.36	2446	1.54	13.57	105	192	Off Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.11	20.24	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:22:2	31.36	2450	1.56	13.56	105	192	Off Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.04	20.23	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:09:22:2	34.08	2433	1.59	13.58	105	192	Off Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:09:22:3	34.08	2432	1.64	13.59	105	192	Off Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:09:22:3	34.08	2432	1.64	13.57	105	192	Off Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.86	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:09:22:3	34.08	2435	1.7	13.58	105	192	Off Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.74	20.23	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:22:3	34.08	2436	1.72	13.57	105	192	Off Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.64	20.23	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:22:3	34.08	2436	1.74	13.57	105	192	Off Idle	70.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.56	20.23	1.38	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:09:22:3	34.08	2438	1.76	13.57	105	192	Off Idle	70.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.51	20.23	1.38	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:09:22:4	34.08	2431	1.77	13.58	105	192	Off Idle	70.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.41	20.23	1.38	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:09:22:4	34.08	2403	1.79	13.61	105	192	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.26	20.24	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:22:4	34.08	2396	1.81	13.62	105	192	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.21	20.25	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:22:4	34.08	2377	1.83	13.62	105	192	Off Idle	70.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.11	20.25	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:22:4	34.08	2359	1.85	13.6	105	192	Off Idle	70.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.93	20.25	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:22:4	34.08	2357	1.87	13.58	105	192	Off Idle	70.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.81	20.25	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:22:4	34.08	2348	1.89	13.56	105	192	Off Idle	70.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.56	20.25	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:22:5	34.08	2363	1.91	13.55	105	192	Off Idle	71	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.4	20.25	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:22:5	34.08	2366	1.94	13.55	105	192	Off Idle	71.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.26	20.25	1.38	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:5	34.08	2382	1.96	13.56	105	192	Off Idle	71.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.17	20.24	1.38	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:5	34.08	2406	1.97	13.58	105	192	Off Idle	71.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.97	20.24	1.38	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:09:22:5	34.08	2416	2	13.57	105	192	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.82	20.21	1.38	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:22:5	34.08	2434	2.03	13.58	105	192	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.55	20.04	1.37	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:22:6	32.72	2423	2.05	13.58	105	192	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.34	19.86	1.35	3.3	3	ON	28 Pin	OFF	Removed	Disabled
03:09:22:6	32.72	2428	2.07	13.56	105	192	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.2	19.66	1.34	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:22:6	32.72	2431	2.1	13.56	105	192	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.98	19.28	1.31	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:22:6	32.72	2431	2.12	13.56	105	192	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.9	19.02	1.3	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:22:6	32.72	2390	2.15	13.54	105	192	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.7	18.73	1.28	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:22:6	32.72	2370	2.17	13.53	104	192	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.57	18.31	1.25	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:22:6	32.72	2361	2.18	13.55	104	192	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.51	18.01	1.23	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:22:7	32.72	2361	2.2	13.55	104	192	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.35	17.76	1.21	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:22:7	32.72	2352	2.23	13.56	105	192	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.18	17.56	1.2	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:22:7	32.72	2380	2.25	13.58	105	192	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.94	17.33	1.18	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:22:7	32.72	2389	2.27	13.57	105	192	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.8	17.2	1.17	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:22:7	32.72	2396	2.3	13.56	105	192	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.56	17.15	1.17	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:22:7	32.72	2401	2.32	13.57	105	192	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.41	16.97	1.16	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:22:8	32.72	2417	2.33	13.56	105	192	Off Idle	72.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.27	16.83	1.15	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:22:8	32.72	2413	2.34	13.57	105	192	Off Idle	72.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.18	16.69	1.14	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:22:8	32.72	2413	2.35	13.58	105	192	Off Idle	72.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.09	16.52	1.13	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:22:8	32.72	2402	2.36	13.58	105	192	Off Idle	72.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.02	16.38	1.12	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:22:8	32.72	2385	2.37	13.57	105	192	Off Idle	72.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.99	16.17	1.1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:22:8	32.72	2372	2.38	13.55	105	192	Off Idle	72.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.97	16.09	1.1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:22:9	32.72	2372	2.39	13.55	105	192	Off Idle	72.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.92	15.96	1.09	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:9	32.72	2374	2.4	13.55	105	192	Off Idle	72.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3.83	15.77	1.07	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:9	32.72	2379	2.41	13.56	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.8	15.72	1.07	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:9	31.36	2397	2.41	13.56	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.79	15.62	1.06	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:9	31.36	2397	2.42	13.56	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-3.75	15.53	1.06	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:9	31.36	2402	2.42	13.57	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-3.81	15.42	1.05	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:22:9	31.36	2400	2.43	13.56	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.83	15.39	1.05	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:0	31.36	2392	2.43	13.56	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.83	15.32	1.04	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:0	31.36	2378	2.43	13.56	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.88	15.25	1.04	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:0	31.36	2375	2.43	13.57	104	192	Off Idle	72.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.9	15.18	1.03	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:0	31.36	2378	2.43	13.57	104	192	Off Idle	72.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.84	15.07	1.03	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:0	31.36	2378	2.42	13.57	105	192	Off Idle	73	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.82	15	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:23:0	31.36	2383	2.42	13.56	105	192	Off Idle	73.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.8	14.94	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:1	31.36	2383	2.42	13.56	105	192	Off Idle	73.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.78	14.92	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:1	31.36	2390	2.42	13.56	105	192	Off Idle	73	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.73	14.86	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:1	31.36	2395	2.42	13.56	105	192	Off Idle	72.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.77	14.76	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:1	31.36	2394	2.42	13.56	105	192	Off Idle	72.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.79	14.74	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:23:1	31.36	2392	2.42	13.57	104	192	Off Idle	72.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.75	14.71	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:23:1	31.36	2376	2.42	13.56	104	192	Off Idle	72.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.76	14.71	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:23:1	31.36	2368	2.42	13.56	104	192	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.76	14.72	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:23:2	31.36	2369	2.43	13.56	105	192	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.68	14.73	1	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:2	31.36	2380	2.43	13.55	105	192	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.52	14.75	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:23:2	31.36	2388	2.44	13.55	105	192	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.39	14.77	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:23:2	31.36	2390	2.46	13.57	105	192	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.26	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:23:2	31.36	2390	2.47	13.56	105	192	Off Idle	72.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.06	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:23:2	31.36	2394	2.47	13.57	105	192	Off Idle	72.6	0	2	132	944 Turbo	0.66	Lean	1	14.6	-2.86	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:23:3	31.36	2404	2.48	13.57	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-2.79	14.86	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:23:3	31.36	2404	2.49	13.56	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-2.71	14.87	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:23:3	31.36	2408	2.5	13.56	105	192	Off Idle	72.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-2.67	14.86	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:23:3	31.36	2401	2.51	13.56	105	192	Off Idle	72.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-2.62	14.85	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:23:3	31.36	2388	2.51	13.56	105	192	Off Idle	72.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.61	14.83	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:23:3	31.36	2386	2.52	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.57	14.83	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:23:4	31.36	2383	2.53	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.54	14.85	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:4	31.36	2378	2.54	13.59	104	192	Off Idle	72	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.52	14.87	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:23:4	31.36	2389	2.55	13.56	105	192	Off Idle	72	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.5	14.9	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:23:4	31.36	2390	2.55	13.56	105	192	Off Idle	72	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.49	14.92	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:23:4	31.36	2392	2.56	13.55	105	192	Off Idle	72	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.48	14.97	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:23:4	31.36	2404	2.56	13.55	105	192	Off Idle	72	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.49	15	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:4	31.36	2408	2.57	13.55	105	192	Off Idle	72	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.51	15.01	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:5	31.36	2405	2.58	13.56	105	192	Off Idle	72	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.43	14.99	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:23:5	31.36	2401	2.58	13.57	105	192	Off Idle	72	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.43	14.93	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:23:5	31.36	2390	2.58	13.57	105	192	Off Idle	72	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.42	14.84	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:5	31.36	2386	2.58	13.58	105	192	Off Idle	72.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.4	14.75	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:5	31.36	2387	2.57	13.57	105	192	Off Idle	72.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.38	14.65	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:5	31.36	2388	2.57	13.58	105	192	Off Idle	72.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.39	14.54	0.99	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:6	31.36	2394	2.57	13.57	105	192	Off Idle	72.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.39	14.42	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:6	31.36	2393	2.57	13.57	105	192	Off Idle	72.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.4	14.31	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:6	31.36	2392	2.57	13.58	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.37	14.16	0.96	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:6	31.36	2392	2.57	13.58	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.35	14.1	0.96	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:6	31.36	2388	2.57	13.56	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.33	14.06	0.96	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:6	31.36	2388	2.57	13.56	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.31	14.05	0.96	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:6	31.36	2389	2.57	13.55	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.27	14.04	0.96	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:7	31.36	2402	2.57	13.54	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.27	14.04	0.96	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:7	31.36	2399	2.57	13.55	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.27	14.04	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:7	31.36	2400	2.58	13.55	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.3	14.05	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:7	31.36	2400	2.58	13.55	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.27	14.07	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:7	31.36	2401	2.58	13.56	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.36	14.08	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:7	31.36	2397	2.58	13.56	105	192	Off Idle	72.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.33	14.09	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:8	31.36	2396	2.58	13.56	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.28	14.11	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:8	31.36	2392	2.58	13.56	105	192	Off Idle	72.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.25	14.12	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:8	31.36	2391	2.58	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.26	14.14	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:8	31.36	2391	2.58	13.59	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.26	14.16	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:8	31.36	2398	2.58	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.23	14.18	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:8	31.36	2403	2.58	13.58	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.23	14.18	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:9	31.36	2404	2.58	13.58	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.24	14.19	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:9	31.36	2396	2.59	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.22	14.21	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:9	31.36	2403	2.59	13.56	104	192	Off Idle	72.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.19	14.22	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:9	31.36	2399	2.59	13.56	104	192	Off Idle	72.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.18	14.23	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:23:9	31.36	2397	2.59	13.56	105	192	Off Idle	72.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.16	14.24	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:23:9	31.36	2397	2.59	13.56	105	192	Off Idle	72.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.16	14.25	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:23:9	31.36	2414	2.59	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.15	14.26	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:0	31.36	2396	2.59	13.57	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.13	14.26	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:0	31.36	2400	2.59	13.57	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.13	14.26	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:0	31.36	2400	2.59	13.58	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.12	14.27	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:0	31.36	2400	2.59	13.56	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.16	14.29	0.97	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:0	31.36	2398	2.59	13.56	104	192	Off Idle	71.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.16	14.28	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:0	31.36	2398	2.59	13.56	105	192	Off Idle	71.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.19	14.29	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:1	31.36	2398	2.59	13.57	105	192	Off Idle	71.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.13	14.29	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:1	31.36	2396	2.6	13.57	105	192	Off Idle	71.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.15	14.31	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:1	31.36	2398	2.6	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.15	14.33	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:1	31.36	2398	2.6	13.55	104	192	Off Idle	72	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.12	14.35	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:1	31.36	2400	2.6	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.16	14.38	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:1	31.36	2408	2.6	13.55	104	192	Off Idle	72	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.19	14.41	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:1	31.36	2423	2.6	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.17	14.43	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:2	31.36	2401	2.6	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.11	14.46	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:2	31.36	2400	2.6	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.1	14.47	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:2	31.36	2396	2.6	13.59	104	192	Off Idle	72	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.13	14.49	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:2	31.36	2378	2.6	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.14	14.52	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:2	31.36	2400	2.6	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.13	14.54	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:2	31.36	2402	2.6	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.06	14.55	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:3	31.36	2404	2.6	13.56	105	192	Off Idle	72	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.04	14.56	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:3	31.36	2406	2.6	13.58	105	192	Off Idle	72	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.03	14.57	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:3	31.36	2410	2.6	13.58	105	192	Off Idle	72	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.97	14.58	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:3	31.36	2410	2.6	13.59	104	192	Off Idle	72	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.98	14.6	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:3	31.36	2408	2.6	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.05	14.64	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:3	31.36	2406	2.6	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.04	14.66	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:4	31.36	2406	2.6	13.56	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.01	14.67	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:4	31.36	2416	2.6	13.56	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.03	14.69	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:4	31.36	2406	2.6	13.55	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.05	14.7	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:4	31.36	2409	2.6	13.55	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.01	14.71	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:4	31.36	2410	2.6	13.56	104	192	Off Idle	71.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.04	14.72	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:4	31.36	2415	2.6	13.55	105	192	Off Idle	71.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.04	14.72	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:4	31.36	2409	2.61	13.55	105	192	Off Idle	71.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.04	14.73	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:24:5	31.36	2406	2.61	13.56	104	192	Off Idle	71.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.05	14.74	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:5	31.36	2406	2.61	13.56	104	192	Off Idle	71	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.06	14.76	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:5	31.36	2404	2.61	13.55	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.1	14.78	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:5	31.36	2401	2.61	13.54	104	192	Off Idle	70.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.04	14.78	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:5	31.36	2402	2.61	13.56	104	192	Off Idle	70.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.07	14.81	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:5	31.36	2406	2.61	13.56	104	192	Off Idle	70.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.04	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:6	31.36	2398	2.61	13.56	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.99	14.84	1.01	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:6	31.36	2408	2.61	13.56	104	192	Off Idle	71.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.04	14.85	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:6	31.36	2419	2.61	13.57	104	192	Off Idle	71.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.97	14.86	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:6	31.36	2417	2.61	13.57	104	192	Off Idle	71.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-1.96	14.86	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:6	31.36	2410	2.61	13.56	104	192	Off Idle	71.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-1.96	14.84	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:6	31.36	2414	2.61	13.56	105	192	Off Idle	71.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-1.96	14.84	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:6	31.36	2407	2.61	13.57	105	192	Off Idle	71.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.96	14.86	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:7	31.36	2407	2.61	13.56	105	192	Off Idle	71.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2	14.88	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:7	31.36	2410	2.61	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.02	14.9	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:7	31.36	2411	2.61	13.56	104	192	Off Idle	72.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-2.05	14.92	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:7	31.36	2416	2.61	13.56	104	192	Off Idle	72.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-2.09	14.95	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:7	31.36	2416	2.61	13.56	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-2.19	14.96	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:24:7	31.36	2417	2.6	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.27	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:24:8	31.36	2414	2.59	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-2.31	15.03	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:24:8	31.36	2414	2.58	13.58	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-2.48	15.1	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:24:8	31.36	2408	2.57	13.58	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-2.63	15.09	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:24:8	31.36	2386	2.55	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.82	15.07	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:24:8	31.36	2393	2.54	13.58	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.96	15.05	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:8	31.36	2396	2.53	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.23	14.99	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:24:9	31.36	2399	2.51	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.3	14.95	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:9	31.36	2397	2.5	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.51	14.9	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:9	31.36	2397	2.48	13.56	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.58	14.86	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:9	31.36	2396	2.47	13.56	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.62	14.8	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:24:9	31.36	2402	2.46	13.56	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.64	14.66	1	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:9	31.36	2402	2.45	13.56	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.63	14.63	1	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:24:9	31.36	2401	2.43	13.57	104	192	Off Idle	72.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-3.65	14.59	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:0	31.36	2404	2.42	13.57	104	192	Off Idle	72.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-3.67	14.57	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:0	31.36	2404	2.41	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.42	Lean	1	14.6	-3.74	14.57	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:0	31.36	2405	2.4	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3.81	14.58	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:0	31.36	2405	2.39	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.89	14.58	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:0	31.36	2408	2.38	13.55	104	192	Off Idle	72	0	2	132	944 Turbo	0.17	Lean	1	14.6	-3.85	14.61	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:0	31.36	2410	2.37	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.88	14.67	1	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:1	31.36	2428	2.37	13.59	104	192	Off Idle	72	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.92	14.75	1	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:1	31.36	2428	2.37	13.58	104	192	Off Idle	72	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.92	14.86	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:1	32.72	2410	2.37	13.58	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.97	15.03	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:1	32.72	2403	2.37	13.56	104	192	Off Idle	71.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:1	32.72	2397	2.37	13.56	104	192	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.02	15.21	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:1	32.72	2397	2.37	13.56	104	192	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.01	15.41	1.05	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:1	32.72	2378	2.37	13.57	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.04	15.54	1.06	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:2	32.72	2403	2.37	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.06	15.68	1.07	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:2	32.72	2413	2.37	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.07	15.77	1.07	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:2	32.72	2413	2.37	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.05	15.84	1.08	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:2	32.72	2418	2.37	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.06	15.89	1.08	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:2	32.72	2427	2.37	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.03	15.9	1.08	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:2	32.72	2406	2.37	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.03	15.9	1.08	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:3	32.72	2403	2.37	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.03	15.89	1.08	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:3	32.72	2403	2.37	13.56	104	192	Off Idle	72.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.04	15.87	1.08	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:3	32.72	2378	2.37	13.55	104	192	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.1	15.82	1.08	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:25:3	32.72	2403	2.37	13.54	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.13	15.8	1.08	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:3	32.72	2404	2.37	13.54	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.1	15.76	1.07	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:3	32.72	2403	2.37	13.56	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.07	15.73	1.07	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:4	32.72	2406	2.37	13.56	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.12	15.68	1.07	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:4	32.72	2407	2.37	13.55	104	192	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.08	15.66	1.07	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:4	32.72	2406	2.37	13.56	104	192	Off Idle	72.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.06	15.66	1.07	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:4	32.72	2404	2.37	13.57	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.09	15.64	1.07	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:4	32.72	2403	2.37	13.56	105	192	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.11	15.61	1.06	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:4	32.72	2406	2.37	13.57	105	192	Off Idle	71.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.05	15.59	1.06	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:4	32.72	2408	2.37	13.58	105	192	Off Idle	71.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.07	15.57	1.06	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:5	32.72	2408	2.37	13.58	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.08	15.56	1.06	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:5	32.72	2407	2.37	13.58	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.06	15.55	1.06	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:5	32.72	2407	2.37	13.58	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.09	15.56	1.06	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:5	32.72	2405	2.37	13.57	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.08	15.56	1.06	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:5	32.72	2404	2.37	13.56	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.1	15.53	1.06	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:5	32.72	2401	2.37	13.56	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.08	15.51	1.06	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:6	32.72	2401	2.37	13.57	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.12	15.5	1.06	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:6	32.72	2401	2.37	13.59	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.15	15.48	1.05	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:6	32.72	2401	2.37	13.58	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.14	15.45	1.05	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:6	32.72	2406	2.37	13.59	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.14	15.41	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:6	32.72	2405	2.37	13.59	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.12	15.37	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:6	32.72	2402	2.37	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.12	15.32	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:6	32.72	2404	2.37	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.13	15.29	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:7	32.72	2404	2.37	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.1	15.27	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:7	32.72	2403	2.37	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.12	15.22	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:7	32.72	2405	2.37	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.14	15.2	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:7	32.72	2405	2.37	13.57	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.17	15.17	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:7	32.72	2399	2.37	13.57	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.19	15.15	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:7	32.72	2402	2.37	13.56	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.22	15.12	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:25:8	32.72	2405	2.37	13.57	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.19	15.1	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:8	32.72	2407	2.37	13.57	104	192	Off Idle	71.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.18	15.08	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:8	32.72	2407	2.37	13.58	104	192	Off Idle	71.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.2	15.05	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:8	32.72	2402	2.37	13.58	104	192	Off Idle	71.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.16	15.03	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:8	32.72	2402	2.37	13.57	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.17	15.03	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:8	32.72	2399	2.37	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.18	15.03	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:25:9	32.72	2400	2.37	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.16	15.04	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:9	32.72	2399	2.37	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.15	15.04	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:9	32.72	2400	2.37	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.14	15.06	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:9	32.72	2401	2.37	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.16	15.07	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:9	32.72	2401	2.37	13.57	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.14	15.07	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:9	32.72	2404	2.37	13.58	104	192	Off Idle	72	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.11	15.06	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:25:9	32.72	2410	2.37	13.59	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.14	15.06	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:0	32.72	2410	2.37	13.6	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.22	15.06	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:0	32.72	2410	2.37	13.61	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.2	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:0	32.72	2409	2.37	13.61	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.26	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:0	32.72	2401	2.36	13.6	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.26	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:0	32.72	2399	2.37	13.61	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.25	14.98	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:0	32.72	2403	2.37	13.58	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.23	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:1	32.72	2403	2.37	13.58	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.22	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:1	32.72	2404	2.37	13.58	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.19	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:1	32.72	2407	2.37	13.58	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.18	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:1	32.72	2408	2.37	13.59	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.19	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:1	32.72	2405	2.36	13.59	104	192	Off Idle	71.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.2	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:1	32.72	2416	2.36	13.59	104	192	Off Idle	71.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.2	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:1	32.72	2411	2.36	13.58	104	192	Off Idle	71.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.21	14.98	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:2	32.72	2411	2.37	13.58	104	192	Off Idle	71.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.19	14.96	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:2	32.72	2409	2.37	13.59	104	192	Off Idle	71	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.11	14.9	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:2	32.72	2390	2.37	13.6	104	192	Off Idle	71	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.12	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:2	32.72	2396	2.37	13.61	104	192	Off Idle	71	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.12	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:2	32.72	2398	2.37	13.59	104	192	Off Idle	71	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.14	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:2	32.72	2397	2.37	13.59	104	192	Off Idle	71	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.18	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:3	32.72	2380	2.37	13.59	104	192	Off Idle	71	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.22	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:3	32.72	2380	2.37	13.58	104	192	Off Idle	71	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.21	14.9	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:3	32.72	2404	2.37	13.59	104	192	Off Idle	71	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.21	14.92	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:3	32.72	2400	2.37	13.59	104	192	Off Idle	71	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.22	14.94	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:3	32.72	2395	2.37	13.57	104	192	Off Idle	71.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.22	14.97	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:3	32.72	2395	2.36	13.56	104	192	Off Idle	71.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.24	14.99	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:4	32.72	2397	2.36	13.57	104	192	Off Idle	71.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.19	15.04	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:4	32.72	2399	2.36	13.57	104	192	Off Idle	71.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.2	15.06	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:4	32.72	2400	2.37	13.59	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.21	15.05	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:4	32.72	2408	2.36	13.57	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.18	15.03	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:4	32.72	2410	2.36	13.58	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.18	15.01	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:26:4	32.72	2409	2.36	13.58	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.2	14.99	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:26:4	32.72	2409	2.36	13.56	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.22	14.96	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:5	32.72	2410	2.36	13.57	104	192	Off Idle	71.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.16	14.95	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:5	32.72	2427	2.36	13.59	104	192	Off Idle	71.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.18	14.93	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:5	32.72	2427	2.36	13.57	104	192	Off Idle	71.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.19	14.9	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:5	32.72	2410	2.36	13.58	104	192	Off Idle	71.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.2	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:5	32.72	2412	2.36	13.57	104	192	Off Idle	71.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.21	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:5	32.72	2416	2.36	13.57	104	192	Off Idle	71	0	2	132	944 Turbo	0.25	Rich	1	14.6	-4.19	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:6	32.72	2406	2.36	13.58	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.17	Rich	1	14.6	-4.19	14.84	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:6	32.72	2410	2.36	13.58	104	192	Off Idle	70.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.16	14.85	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:6	32.72	2410	2.36	13.57	104	192	Off Idle	70.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.14	14.88	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:6	32.72	2404	2.36	13.58	104	192	Off Idle	70.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.14	14.9	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:6	32.72	2399	2.37	13.57	104	192	Off Idle	70.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.16	14.93	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:6	32.72	2399	2.37	13.56	104	192	Off Idle	70.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.14	14.97	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:6	31.36	2392	2.37	13.57	104	192	Off Idle	70.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.12	14.99	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:26:7	31.36	2398	2.37	13.58	104	192	Off Idle	70.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.13	15.01	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:7	31.36	2399	2.37	13.57	104	192	Off Idle	70.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.16	15.06	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:7	31.36	2402	2.37	13.56	104	192	Off Idle	70.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.14	15.09	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:7	31.36	2403	2.37	13.58	104	192	Off Idle	70.7	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.15	15.12	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:7	31.36	2403	2.37	13.57	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.66	Lean	1	14.6	-4.2	15.13	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:7	32.72	2405	2.37	13.55	104	192	Off Idle	71.1	0	2	132	944 Turbo	0.69	Lean	1	14.6	-4.23	15.11	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:8	32.72	2403	2.37	13.56	104	192	Off Idle	71.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.21	15.07	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:8	32.72	2403	2.37	13.58	104	192	Off Idle	71.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.24	15.04	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:26:8	32.72	2401	2.37	13.56	104	192	Off Idle	71.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.25	15.01	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:26:8	32.72	2402	2.37	13.56	104	192	Off Idle	71.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.21	14.97	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:26:8	32.72	2402	2.37	13.58	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.21	14.95	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:26:8	32.72	2416	2.36	13.57	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.24	14.91	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:26:9	32.72	2411	2.36	13.56	104	192	Off Idle	72	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.26	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:26:9	32.72	2413	2.36	13.56	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.24	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:9	32.72	2414	2.36	13.58	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.26	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:9	32.72	2414	2.36	13.58	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.28	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:9	32.72	2409	2.36	13.56	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.29	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:9	32.72	2408	2.36	13.55	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.33	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:26:9	32.72	2402	2.36	13.55	104	192	Off Idle	72.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.33	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:0	32.72	2402	2.36	13.53	104	192	Off Idle	72.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.34	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:0	32.72	2406	2.36	13.54	104	192	Off Idle	72.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.33	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:0	32.72	2411	2.36	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.32	14.86	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:0	32.72	2414	2.36	13.56	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.31	14.89	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:0	32.72	2414	2.36	13.58	104	192	Off Idle	72.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.33	14.92	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:0	32.72	2413	2.36	13.59	104	192	Off Idle	72.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.3	14.94	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:1	32.72	2410	2.36	13.59	104	192	Off Idle	72	0	2	132	944 Turbo	0.3	Rich	1	14.6	-4.29	14.97	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:1	32.72	2405	2.36	13.58	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.36	Rich	1	14.6	-4.28	15	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:1	32.72	2401	2.36	13.58	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.28	15.05	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:1	32.72	2382	2.36	13.56	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.29	15.07	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:1	32.72	2398	2.36	13.55	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.3	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:1	32.72	2403	2.36	13.56	104	192	Off Idle	71.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.29	15.12	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:1	32.72	2404	2.36	13.56	104	192	Off Idle	71.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.27	15.1	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:2	32.72	2406	2.36	13.58	104	192	Off Idle	71.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.26	15.08	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:2	32.72	2418	2.36	13.57	104	192	Off Idle	71	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.25	15.03	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:27:2	32.72	2406	2.36	13.56	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.23	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:2	32.72	2406	2.36	13.54	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.24	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:2	32.72	2390	2.36	13.55	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.24	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:2	31.36	2409	2.36	13.54	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.2	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:3	31.36	2402	2.36	13.55	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.2	14.88	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:3	31.36	2403	2.36	13.58	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.24	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:3	31.36	2409	2.36	13.58	104	192	Off Idle	70.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.25	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:3	31.36	2396	2.36	13.56	104	192	Off Idle	70.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.26	14.79	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:3	31.36	2396	2.36	13.57	104	192	Off Idle	70.7	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.29	14.78	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:3	32.72	2416	2.36	13.56	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.26	Rich	1	14.6	-4.32	14.77	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:4	32.72	2415	2.36	13.55	104	192	Off Idle	70.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.32	14.78	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:4	32.72	2410	2.36	13.56	104	192	Off Idle	71.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.34	14.79	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:4	32.72	2407	2.36	13.58	104	192	Off Idle	71.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.36	14.82	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:27:4	32.72	2407	2.36	13.56	104	192	Off Idle	71.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.36	14.87	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:4	32.72	2407	2.35	13.58	104	192	Off Idle	71.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.42	14.88	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:4	32.72	2418	2.35	13.56	104	191	Off Idle	71.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.42	14.91	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:27:4	32.72	2410	2.35	13.56	104	191	Off Idle	71.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.45	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:27:5	32.72	2408	2.34	13.58	104	191	Off Idle	71.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.46	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:27:5	32.72	2408	2.34	13.59	104	192	Off Idle	71.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.46	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:27:5	32.72	2409	2.34	13.61	104	192	Off Idle	71.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.48	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:27:5	32.72	2410	2.33	13.61	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.51	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:27:5	32.72	2409	2.33	13.6	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.57	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:5	32.72	2403	2.32	13.59	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.57	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:6	32.72	2399	2.32	13.59	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.67	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:27:6	32.72	2408	2.31	13.58	104	192	Off Idle	71.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.66	15.03	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:6	32.72	2408	2.31	13.58	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.69	15	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:6	32.72	2406	2.3	13.56	104	192	Off Idle	71.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.73	14.98	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:27:6	32.72	2409	2.3	13.58	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.73	14.97	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:27:6	32.72	2402	2.29	13.57	104	192	Off Idle	72	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.8	14.93	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:27:6	32.72	2402	2.28	13.55	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.88	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:7	32.72	2402	2.28	13.54	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.98	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:7	32.72	2381	2.27	13.55	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.03	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:7	32.72	2396	2.27	13.54	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.11	14.84	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:27:7	32.72	2401	2.27	13.51	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.19	14.83	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:7	32.72	2401	2.26	13.54	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.26	14.84	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:7	32.72	2404	2.25	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.3	14.84	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:8	32.72	2404	2.25	13.56	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.33	14.87	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:27:8	32.72	2404	2.24	13.58	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.36	14.9	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:27:8	32.72	2408	2.24	13.6	104	192	Off Idle	71.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.38	14.93	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:27:8	32.72	2392	2.23	13.59	104	191	Off Idle	72.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.44	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:27:8	32.72	2389	2.22	13.58	104	191	Off Idle	72.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.51	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:09:27:8	32.72	2370	2.21	13.58	104	191	Off Idle	72.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.6	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:09:27:9	32.72	2389	2.21	13.59	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.64	15.1	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:09:27:9	32.72	2390	2.2	13.6	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.71	15.14	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:27:9	32.72	2395	2.19	13.61	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.73	15.15	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:27:9	32.72	2398	2.18	13.58	104	192	Off Idle	72.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.83	15.16	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:27:9	32.72	2400	2.17	13.57	104	192	Off Idle	72.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.92	15.18	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:27:9	32.72	2400	2.16	13.56	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.99	15.18	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:27:9	32.72	2417	2.15	13.58	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.06	15.15	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:28:0	32.72	2399	2.14	13.58	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.1	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:28:0	32.72	2396	2.13	13.59	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.12	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:28:0	32.72	2375	2.13	13.57	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.14	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:28:0	32.72	2375	2.12	13.56	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.23	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:28:0	32.72	2390	2.11	13.57	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.25	14.96	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:28:0	32.72	2388	2.11	13.59	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.3	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:28:1	32.72	2385	2.1	13.59	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.42	14.88	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:28:1	32.72	2385	2.09	13.58	104	192	Off Idle	72.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.53	14.83	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:28:1	32.72	2386	2.07	13.57	104	192	Off Idle	72.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.75	14.81	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:09:28:1	32.72	2400	2.05	13.56	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.85	14.81	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:09:28:1	34.08	2400	2.04	13.57	104	192	Off Idle	72.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.08	14.85	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:1	34.08	2388	2.03	13.56	104	191	Off Idle	72.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.27	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:09:28:1	34.08	2386	2	13.57	104	191	Off Idle	72.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.53	14.92	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:09:28:2	34.08	2380	1.96	13.59	104	191	Off Idle	72.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.66	14.98	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:28:2	34.08	2380	1.95	13.59	104	191	Off Idle	72.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.72	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:28:2	34.08	2375	1.9	13.6	104	191	Off Idle	72.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.96	15.08	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:28:2	34.08	2372	1.86	13.58	104	191	Off Idle	72.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.19	15.18	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:28:2	34.08	2368	1.81	13.59	104	191	Off Idle	73.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.46	15.22	1.04	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:28:2	34.08	2368	1.74	13.57	104	191	Off Idle	73.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.74	15.26	1.04	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:28:3	34.08	2364	1.7	13.58	104	192	Idle	73.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.25	15.3	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:28:3	34.08	2359	1.65	13.6	104	192	Idle	73.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.45	15.32	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:28:3	34.08	2368	1.57	13.6	104	191	Idle	73.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.66	15.31	1.04	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:3	34.08	2366	1.52	13.61	104	191	Idle	73.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.79	15.31	1.04	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:3	35.45	2366	1.47	13.6	104	191	Idle	73.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.93	15.31	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:3	35.45	2335	1.41	13.59	104	191	Idle	73.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.05	15.28	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:4	35.45	2309	1.39	13.58	104	191	Idle	73.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.13	15.25	1.04	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:4	35.45	2300	1.33	13.56	104	191	Idle	73.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.22	15.21	1.04	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:4	35.45	2299	1.32	13.56	104	191	Idle	73.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.3	15.2	1.04	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:4	35.45	2300	1.26	13.57	104	191	Idle	72.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.32	15.2	1.04	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:4	35.45	2280	1.22	13.58	104	191	Idle	72.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.31	15.18	1.03	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:4	29.99	2302	1.2	13.57	104	191	Idle	71.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.33	15.12	1.03	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:4	24.54	2349	1.17	13.57	104	191	Idle	70.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.34	15.08	1.03	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:5	24.54	2380	1.16	13.58	104	192	Idle	70.3	0	2	132	944 Turbo	0.72	Lean	1	14.6	-10.34	15.06	1.03	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:28:5	19.09	2376	1.15	13.59	104	192	Idle	70.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-10.34	15.03	1.02	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:5	17.72	2401	1.14	13.59	104	192	Idle	70.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	-10.36	15.01	1.02	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:5	17.72	2402	1.14	13.58	104	191	Idle	69.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-10.37	14.94	1.02	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:5	17.72	2391	1.14	13.59	104	191	Idle	70	0	2	132	944 Turbo	0.44	Lean	1	14.6	-10.36	14.91	1.02	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:5	17.72	2384	1.16	13.59	104	191	Idle	69.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.39	14.82	1.01	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:6	17.72	2366	1.16	13.59	104	191	Idle	69.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.41	14.78	1.01	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:6	17.72	2366	1.17	13.58	104	191	Idle	70.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.39	14.77	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:6	17.72	2335	1.17	13.59	104	191	Idle	70.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.39	14.76	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:6	17.72	2341	1.18	13.6	104	191	Idle	70.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.4	14.75	1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:6	17.72	2300	1.18	13.59	104	191	Idle	71	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.43	14.74	1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:6	17.72	2319	1.18	13.59	104	191	Idle	71.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.44	14.73	1	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:6	17.72	2324	1.18	13.59	104	191	Idle	71.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.46	14.74	1	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:7	17.72	2328	1.18	13.58	104	191	Idle	71.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.43	14.76	1.01	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:7	17.72	2346	1.18	13.57	104	191	Idle	70.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.42	14.76	1.01	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:7	17.72	2395	1.18	13.57	104	191	Idle	70.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.44	14.75	1.01	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:7	17.72	2364	1.18	13.58	104	191	Idle	70.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.43	14.8	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:7	17.72	2368	1.18	13.59	104	191	Idle	70.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.41	14.86	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:7	17.72	2367	1.18	13.58	104	191	Idle	71	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.43	15	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:8	17.72	2367	1.18	13.59	104	191	Idle	71	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.43	15.14	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:8	17.72	2348	1.17	13.58	104	191	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	15.4	1.05	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:8	17.72	2348	1.17	13.58	104	192	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	15.5	1.06	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:8	17.72	2343	1.16	13.6	104	192	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	15.86	1.08	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:8	17.72	2327	1.16	13.59	104	192	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	16.28	1.11	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:8	17.72	2323	1.16	13.59	104	191	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	16.65	1.13	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:9	17.72	2318	1.16	13.59	104	191	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	16.88	1.15	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:9	17.72	2318	1.15	13.58	104	191	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.5	-10.46	17.09	1.16	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:9	17.72	2326	1.15	13.57	104	191	Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	17.35	1.18	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:9	17.72	2330	1.15	13.58	104	191	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	17.54	1.2	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:9	17.72	2334	1.15	13.56	104	191	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	17.64	1.2	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:9	17.72	2339	1.15	13.56	104	191	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	17.74	1.21	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:28:9	17.72	2359	1.14	13.56	104	191	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	17.84	1.22	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:0	17.72	2349	1.14	13.57	104	191	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	17.99	1.23	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:0	17.72	2316	1.14	13.56	104	191	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	18.21	1.24	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:0	17.72	2331	1.13	13.59	104	191	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	18.45	1.26	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:0	17.72	2319	1.13	13.59	104	191	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	18.82	1.28	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:0	17.72	2319	1.13	13.57	104	191	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	19.07	1.3	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:0	17.72	2316	1.12	13.57	104	191	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	19.18	1.31	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:1	17.72	2322	1.12	13.57	104	191	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	19.53	1.33	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:1	17.72	2298	1.12	13.57	104	191	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	19.85	1.35	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:1	17.72	2298	1.12	13.57	104	191	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.02	1.36	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:1	17.72	2289	1.12	13.56	104	191	Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.15	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:1	17.72	2300	1.11	13.56	104	191	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:1	17.72	2305	1.11	13.57	104	191	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:1	17.72	2305	1.11	13.57	104	191	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:2	17.72	2321	1.11	13.57	104	191	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:2	17.72	2317	1.11	13.58	104	191	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:2	17.72	2317	1.11	13.58	104	191	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:2	17.72	2318	1.1	13.59	104	191	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:2	17.72	2318	1.1	13.59	104	191	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:2	17.72	2314	1.1	13.59	104	191	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:3	17.72	2312	1.1	13.57	104	191	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:3	17.72	2288	1.1	13.56	104	191	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:3	17.72	2297	1.09	13.58	104	191	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:3	17.72	2297	1.09	13.57	104	192	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:3	17.72	2295	1.09	13.57	104	192	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:3	17.72	2293	1.09	13.58	104	191	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:4	17.72	2292	1.08	13.58	104	191	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:4	17.72	2292	1.08	13.59	104	191	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:29:4	17.72	2294	1.08	13.58	104	191	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:4	17.72	2294	1.08	13.59	104	191	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:4	17.72	2294	1.08	13.59	104	191	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:4	17.72	2293	1.08	13.58	104	191	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:4	17.72	2290	1.08	13.59	104	191	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:5	17.72	2290	1.08	13.58	104	191	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:5	17.72	2286	1.08	13.58	104	191	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:5	17.72	2280	1.08	13.59	104	191	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:5	17.72	2274	1.08	13.59	104	191	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:5	17.72	2274	1.08	13.57	104	191	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:5	17.72	2271	1.07	13.57	104	191	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:6	17.72	2267	1.07	13.57	104	191	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:6	17.72	2268	1.07	13.56	104	191	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:6	17.72	2269	1.07	13.57	104	191	Full Load	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:6	17.72	2270	1.07	13.57	104	191	Off Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:6	17.72	2270	1.07	13.57	104	191	Off Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:6	17.72	2271	1.07	13.57	104	191	Off Idle	77.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:09:29:6	8.18	2156	1.08	13.58	104	191	Off Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:09:29:7	8.18	2220	1.08	13.58	104	191	Off Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:7	10.9	2287	1.09	13.57	104	191	Off Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:7	13.63	2284	1.1	13.57	104	191	Off Idle	78	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:29:7	13.63	2282	1.11	13.57	104	191	Off Idle	78.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:29:7	16.36	2282	1.11	13.58	104	191	Off Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:29:7	16.36	2280	1.13	13.58	104	191	Off Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:29:8	19.09	2280	1.14	13.58	104	191	Off Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:29:8	21.81	2278	1.16	13.57	104	191	Off Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:29:8	21.81	2261	1.18	13.57	104	191	Off Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:29:8	24.54	2277	1.19	13.57	104	191	Off Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:29:8	24.54	2277	1.2	13.58	104	191	Off Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:29:8	27.27	2280	1.22	13.57	104	191	Off Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:29:9	29.99	2284	1.24	13.59	104	191	Off Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:29:9	29.99	2330	1.26	13.6	104	191	Off Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:29:9	32.72	2316	1.28	13.61	104	191	Off Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:29:9	32.72	2304	1.3	13.61	104	191	Off Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:29:9	35.45	2284	1.32	13.58	104	191	Off Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:29:9	35.45	2265	1.35	13.57	104	191	Off Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:29:9	35.45	2270	1.37	13.56	104	191	Off Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:0	35.45	2274	1.38	13.56	104	191	Off Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:0	35.45	2272	1.4	13.57	104	191	Off Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:0	35.45	2271	1.42	13.59	104	191	Off Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:0	35.45	2271	1.43	13.6	104	191	Off Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:0	35.45	2264	1.45	13.6	104	191	Off Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:0	35.45	2256	1.46	13.61	104	191	Off Idle	78.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:1	35.45	2256	1.47	13.61	104	191	Off Idle	78.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.53	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:1	35.45	2252	1.47	13.61	104	191	Off Idle	78.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.5	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:1	35.45	2249	1.48	13.6	104	191	Off Idle	79.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.53	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:1	35.45	2249	1.48	13.59	104	191	Off Idle	79.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.53	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:1	34.08	2227	1.49	13.58	104	191	Off Idle	79.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.54	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:1	34.08	2230	1.49	13.56	104	191	Off Idle	79.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.53	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:1	34.08	2238	1.49	13.56	104	191	Off Idle	80.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.51	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:2	34.08	2245	1.5	13.56	104	191	Off Idle	80.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.49	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:2	34.08	2240	1.5	13.57	104	191	Off Idle	80.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.46	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:2	34.08	2254	1.5	13.58	104	191	Off Idle	80.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.46	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:2	34.08	2236	1.5	13.58	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.45	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:2	34.08	2233	1.5	13.59	104	191	Off Idle	81.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.42	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:2	34.08	2231	1.5	13.6	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.44	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:3	34.08	2213	1.5	13.58	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.45	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:3	34.08	2228	1.5	13.59	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.45	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:30:3	34.08	2230	1.49	13.58	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.46	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:3	34.08	2233	1.49	13.58	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.46	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:3	34.08	2236	1.49	13.59	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.44	20.19	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:3	34.08	2236	1.49	13.6	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.41	20.09	1.37	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:4	34.08	2235	1.49	13.58	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.43	19.87	1.35	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:4	34.08	2238	1.49	13.59	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.43	19.66	1.34	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:4	34.08	2244	1.48	13.6	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.45	19.3	1.31	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:4	34.08	2247	1.48	13.58	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.48	19.02	1.3	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:4	34.08	2247	1.48	13.57	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.49	18.71	1.27	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:4	34.08	2244	1.48	13.57	104	191	Off Idle	81	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.47	18.39	1.25	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:4	34.08	2242	1.48	13.58	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.47	18.05	1.23	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:5	34.08	2243	1.48	13.59	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.44	17.61	1.2	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:5	34.08	2243	1.48	13.59	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.44	17.36	1.18	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:5	34.08	2240	1.48	13.6	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.47	17.14	1.17	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:5	34.08	2239	1.48	13.58	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.51	16.94	1.15	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:5	34.08	2239	1.48	13.56	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.55	16.78	1.14	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:5	35.45	2257	1.47	13.56	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.58	16.64	1.13	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:6	35.45	2248	1.47	13.56	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.59	16.52	1.13	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:6	35.45	2241	1.47	13.56	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.6	16.37	1.12	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:30:6	35.45	2240	1.46	13.55	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.6	16.28	1.11	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:6	35.45	2238	1.46	13.56	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.59	16.2	1.1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:6	35.45	2237	1.45	13.57	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.59	16.09	1.1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:6	35.45	2236	1.44	13.58	104	191	Off Idle	81	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.67	16.03	1.09	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:6	34.08	2193	1.44	13.58	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.74	15.97	1.09	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:7	34.08	2218	1.43	13.57	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.77	15.95	1.09	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:7	34.08	2218	1.42	13.54	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.86	15.91	1.08	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:30:7	34.08	2214	1.41	13.54	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.88	15.86	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:7	34.08	2209	1.4	13.55	104	191	Off Idle	81.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.89	15.82	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:7	34.08	2208	1.39	13.55	104	191	Off Idle	81.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.89	15.8	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:7	34.08	2209	1.38	13.55	104	191	Off Idle	81.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.91	15.78	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:8	34.08	2208	1.37	13.56	104	191	Off Idle	81.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.89	15.76	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:8	34.08	2209	1.36	13.57	104	191	Off Idle	81.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.88	15.74	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:8	34.08	2209	1.35	13.6	104	191	Off Idle	81.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.91	15.71	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:8	34.08	2208	1.35	13.61	104	191	Off Idle	82	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.93	15.68	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:8	34.08	2212	1.34	13.59	104	191	Off Idle	82.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.97	15.64	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:8	34.08	2212	1.34	13.59	104	191	Off Idle	82.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.98	15.64	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:9	34.08	2218	1.33	13.56	104	191	Off Idle	82.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.03	15.6	1.06	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:9	34.08	2204	1.32	13.55	104	192	Off Idle	82.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.07	15.58	1.06	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:9	34.08	2222	1.32	13.56	104	192	Off Idle	82.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.06	15.56	1.06	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:9	34.08	2222	1.32	13.55	104	192	Off Idle	82.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.05	15.54	1.06	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:9	34.08	2221	1.32	13.55	104	191	Off Idle	82.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.08	15.53	1.06	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:9	34.08	2220	1.31	13.56	104	191	Off Idle	82.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.06	15.5	1.06	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:30:9	34.08	2218	1.31	13.57	104	191	Off Idle	82.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.04	15.49	1.06	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:0	34.08	2216	1.31	13.57	104	191	Off Idle	82.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.08	15.47	1.05	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:0	34.08	2210	1.31	13.57	104	191	Off Idle	82.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.08	15.45	1.05	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:0	34.08	2208	1.31	13.57	104	191	Off Idle	82.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.05	15.43	1.05	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:0	34.08	2216	1.31	13.56	104	191	Off Idle	82.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.04	15.4	1.05	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:0	34.08	2204	1.31	13.55	104	191	Off Idle	82.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.06	15.38	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:0	34.08	2202	1.31	13.55	104	191	Off Idle	82.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-10.02	15.35	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:1	34.08	2202	1.31	13.56	104	191	Off Idle	82.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-10	15.34	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:1	34.08	2195	1.31	13.57	104	191	Off Idle	81.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-10.01	15.29	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:1	34.08	2200	1.31	13.57	104	191	Off Idle	81.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-10	15.26	1.04	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:1	34.08	2196	1.31	13.58	104	191	Off Idle	82	0	2	132	944 Turbo	0.58	Lean	1	14.6	-10.03	15.22	1.04	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:1	34.08	2194	1.32	13.57	104	191	Off Idle	82	0	2	132	944 Turbo	0.6	Lean	1	14.6	-10.06	15.18	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:1	34.08	2194	1.32	13.54	104	191	Off Idle	82.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.08	15.15	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:1	34.08	2198	1.32	13.53	104	191	Off Idle	82.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.1	15.13	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:2	34.08	2200	1.32	13.53	104	191	Off Idle	82.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.08	15.11	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:2	34.08	2200	1.32	13.53	104	191	Off Idle	82.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.08	15.1	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:31:2	34.08	2205	1.32	13.54	104	191	Off Idle	82.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.08	15.08	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:2	34.08	2211	1.31	13.56	104	191	Off Idle	82.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.07	15.07	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:2	34.08	2207	1.31	13.57	104	191	Off Idle	82.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.11	15.05	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:2	34.08	2207	1.29	13.58	104	191	Off Idle	82.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.16	15.05	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:31:3	34.08	2202	1.28	13.59	104	191	Full Load	82.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.22	15.04	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:3	34.08	2204	1.24	13.6	104	191	Idle	82.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.34	15.04	1.02	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:31:3	34.08	2204	1.21	13.61	104	191	Idle	82.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.43	15.01	1.02	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:31:3	34.08	2202	1.2	13.61	104	191	Idle	83	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.51	14.99	1.02	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:31:3	34.08	2192	1.18	13.59	104	191	Idle	82.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.58	14.98	1.02	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:31:3	34.08	2177	1.16	13.58	104	191	Idle	82.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.64	15	1.02	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:31:4	34.08	2165	1.15	13.57	104	191	Idle	81.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.71	15.01	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:4	34.08	2160	1.13	13.56	104	191	Idle	81.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-10.75	15	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:4	34.08	2150	1.11	13.56	104	191	Idle	81.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.75	14.98	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:4	31.36	2115	1.1	13.57	104	191	Idle	80.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.74	14.97	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:4	31.36	2110	1.08	13.58	104	191	Idle	80.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.72	14.95	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:31:4	25.9	2088	1.06	13.59	104	191	Idle	80	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.7	14.95	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:31:4	20.45	2063	1.05	13.6	104	191	Idle	79.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.68	14.94	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:5	20.45	2063	1.04	13.59	104	191	Idle	79.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.68	14.93	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:5	17.72	2055	1.03	13.59	104	191	Idle	78.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.68	14.89	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:5	17.72	2046	1.02	13.58	104	191	Idle	78.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.69	14.86	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:5	17.72	2026	1.01	13.59	104	191	Idle	77.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.7	14.83	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:5	17.72	2026	1.01	13.58	104	191	Idle	77.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.7	14.82	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:5	17.72	1987	1.01	13.59	104	191	Idle	77.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.68	14.82	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:6	17.72	1963	1.02	13.57	104	191	Idle	76.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.64	14.83	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:6	17.72	1942	1.04	13.58	103	191	Idle	76.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.59	14.82	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:6	17.72	1932	1.05	13.56	103	191	Idle	76.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.55	14.82	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:6	17.72	1899	1.05	13.55	103	191	Idle	75.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.5	14.84	1.01	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:6	17.72	1876	1.05	13.55	104	191	Idle	75	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.44	14.84	1.01	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:6	17.72	1854	1.06	13.55	104	191	Idle	74.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.36	14.84	1.01	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:6	17.72	1836	1.07	13.54	104	191	Idle	73.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.29	14.84	1.01	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:7	17.72	1810	1.08	13.54	104	191	Idle	73.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.22	14.86	1.01	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:7	17.72	1789	1.09	13.56	104	191	Idle	71.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.18	14.86	1.01	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:7	17.72	1789	1.1	13.56	104	191	Idle	71.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.11	14.84	1.01	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:7	17.72	1754	1.12	13.56	104	191	Idle	70.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.04	14.83	1.01	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:7	17.72	1720	1.12	13.56	104	191	Idle	69.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.97	14.82	1.01	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:7	17.72	1720	1.13	13.57	104	191	Idle	69.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.88	14.83	1.01	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:8	17.72	1683	1.13	13.58	104	191	Idle	68.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.82	14.81	1.01	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:8	17.72	1672	1.15	13.57	104	191	Idle	68.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.71	14.84	1.01	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:8	17.72	1649	1.16	13.57	104	191	Idle	67.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.64	14.84	1.01	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:8	17.72	1637	1.17	13.56	104	191	Idle	67.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.56	14.86	1.01	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:8	17.72	1613	1.18	13.55	104	191	Idle	67.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.49	14.86	1.01	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:8	17.72	1577	1.19	13.56	104	191	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.42	14.89	1.01	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:9	17.72	1577	1.2	13.56	104	191	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	14.93	1.02	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:9	17.72	1540	1.21	13.55	104	191	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.28	14.98	1.02	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:9	17.72	1528	1.22	13.56	104	191	Full Load	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.17	15.08	1.03	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:31:9	17.72	1502	1.23	13.56	104	191	Off Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	15.16	1.03	4.2	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:31:9	8.18	1502	1.24	13.57	104	191	Off Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.99	15.26	1.04	4.2	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:31:9	8.18	1431	1.26	13.56	104	191	Off Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.87	15.37	1.05	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:31:9	8.18	1431	1.27	13.56	104	191	Off Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.75	15.51	1.06	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:32:0	10.9	1435	1.28	13.56	104	191	Off Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	15.58	1.06	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:32:0	10.9	1421	1.3	13.56	104	191	Off Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.53	15.76	1.07	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:32:0	10.9	1421	1.31	13.57	104	191	Off Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.37	15.93	1.09	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:32:0	14.99	1372	1.32	13.56	104	191	Off Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.23	16.19	1.1	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:32:0	14.99	1359	1.32	13.56	104	191	Off Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.2	16.38	1.12	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:0	17.72	1353	1.33	13.54	104	191	Off Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.04	16.67	1.14	4.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:1	17.72	1347	1.34	13.56	104	191	Off Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.92	16.86	1.15	4.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:1	17.72	1356	1.34	13.54	104	191	Off Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.86	17.07	1.16	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:1	20.45	1376	1.35	13.56	104	191	Off Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.82	17.54	1.2	4.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:32:1	20.45	1422	1.35	13.58	104	191	Off Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.82	17.9	1.22	4.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:1	20.45	1457	1.36	13.59	104	191	Off Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.81	18.25	1.24	4.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:32:1	21.81	1490	1.36	13.6	104	191	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.86	18.77	1.28	4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:32:1	21.81	1555	1.36	13.58	104	191	Off Idle	86.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.9	19.07	1.3	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:32:2	24.54	1619	1.36	13.57	104	191	Off Idle	86.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.94	19.37	1.32	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:32:2	24.54	1688	1.36	13.57	104	191	Off Idle	86.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.96	19.64	1.34	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:09:32:2	27.27	1769	1.36	13.57	104	191	Off Idle	86.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.04	19.9	1.36	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:09:32:2	27.27	1823	1.35	13.58	104	191	Off Idle	86.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.22	20.17	1.37	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:32:2	29.99	1864	1.34	13.59	104	191	Off Idle	86.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.36	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:32:2	29.99	1911	1.32	13.57	104	191	Off Idle	86.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.6	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:32:3	29.99	1959	1.31	13.59	104	191	Off Idle	86.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.75	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:32:3	29.99	1959	1.29	13.6	104	191	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.91	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:32:3	31.36	2025	1.28	13.6	104	191	Off Idle	86.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.04	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:32:3	31.36	2059	1.27	13.6	104	191	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.16	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:3	31.36	2094	1.26	13.6	104	191	Off Idle	86.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.25	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:3	31.36	2114	1.25	13.58	104	191	Off Idle	86.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.38	20.23	1.38	3.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:4	31.36	2184	1.24	13.58	104	191	Off Idle	86.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.46	20.23	1.38	3.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:4	31.36	2202	1.23	13.58	104	191	Off Idle	86	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.57	20.23	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:4	31.36	2304	1.22	13.59	104	191	Off Idle	85.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.69	20.23	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:4	32.72	2312	1.22	13.62	104	191	Off Idle	85.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.77	20.23	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:4	32.72	2337	1.21	13.62	104	191	Off Idle	85.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.91	20.23	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:4	32.72	2376	1.21	13.63	104	191	Off Idle	84.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10	20.24	1.38	3.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:4	32.72	2477	1.2	13.6	104	191	Off Idle	83	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.11	20.24	1.38	3.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:5	32.72	2474	1.2	13.59	104	191	Off Idle	82	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.19	20.23	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:5	32.72	2514	1.2	13.6	104	191	Off Idle	80.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.26	20.12	1.37	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:5	34.08	2578	1.2	13.58	104	191	Off Idle	79.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.33	19.94	1.36	3.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:5	34.08	2580	1.22	13.58	104	191	Off Idle	78.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.36	19.68	1.34	3.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:5	34.08	2654	1.23	13.58	104	191	Off Idle	76.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.38	19.36	1.32	3.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:5	34.08	2667	1.24	13.58	104	191	Off Idle	75.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	18.79	1.28	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:32:6	34.08	2729	1.26	13.57	104	191	Off Idle	71.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	18.58	1.27	3.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:6	34.08	2822	1.28	13.57	104	191	Off Idle	69.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.4	17.75	1.21	3.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:6	35.45	2812	1.31	13.57	104	191	Off Idle	65.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	17.29	1.18	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:6	35.45	2834	1.33	13.58	104	191	Off Idle	65.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	16.86	1.15	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:6	35.45	2882	1.36	13.57	104	191	Off Idle	62.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	16.51	1.12	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:32:6	35.45	2882	1.37	13.6	104	191	Off Idle	60.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	16.25	1.11	3.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:32:6	35.45	2980	1.4	13.6	104	191	Off Idle	58.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.3	16.07	1.09	3.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:32:7	36.81	2945	1.43	13.6	104	191	Off Idle	57	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.27	16.06	1.09	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:32:7	36.81	2934	1.46	13.6	104	191	Off Idle	55.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.22	16.1	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:32:7	36.81	2920	1.5	13.6	104	191	Off Idle	53.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.14	16.23	1.11	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:32:7	36.81	2895	1.52	13.58	104	191	Off Idle	52.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.11	16.67	1.14	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:32:7	36.81	2890	1.55	13.59	104	191	Off Idle	49.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10	16.92	1.15	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:32:7	36.81	2886	1.57	13.59	104	191	Off Idle	48.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.93	17.16	1.17	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:32:8	36.81	2873	1.6	13.6	103	191	Off Idle	48	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.87	17.51	1.19	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:32:8	36.81	2839	1.62	13.6	103	191	Off Idle	47.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.82	17.77	1.21	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:32:8	36.81	2839	1.65	13.6	103	191	Off Idle	46.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.74	18	1.23	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:32:8	36.81	2828	1.68	13.6	104	191	Off Idle	45.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	18.29	1.25	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:32:8	36.81	2825	1.68	13.6	104	191	Off Idle	45.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.64	18.45	1.26	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:32:8	36.81	2811	1.7	13.61	104	191	Off Idle	45.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.6	18.63	1.27	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:32:9	36.81	2778	1.72	13.61	104	191	Off Idle	46	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.57	18.75	1.28	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:32:9	36.81	2798	1.74	13.6	104	191	Off Idle	46.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.57	18.79	1.28	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:32:9	36.81	2792	1.75	13.59	104	191	Off Idle	47.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.55	18.8	1.28	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:32:9	36.81	2791	1.76	13.59	104	191	Off Idle	47.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.55	18.72	1.28	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:32:9	36.81	2791	1.77	13.59	104	191	Off Idle	48.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.53	18.64	1.27	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:32:9	36.81	2789	1.77	13.58	104	191	Off Idle	48.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.5	18.46	1.26	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:32:9	36.81	2791	1.77	13.59	104	191	Off Idle	48.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.51	18.31	1.25	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:0	36.81	2786	1.77	13.58	104	191	Off Idle	49	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.56	18.12	1.23	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:0	36.81	2809	1.77	13.58	104	191	Off Idle	49.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.53	17.93	1.22	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:0	36.81	2818	1.77	13.59	104	191	Off Idle	49.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.57	17.62	1.2	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:33:0	36.81	2818	1.77	13.59	104	191	Off Idle	49.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.55	17.4	1.19	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:0	36.81	2830	1.77	13.59	104	191	Off Idle	49.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.56	17.09	1.16	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:0	36.81	2830	1.76	13.6	104	191	Off Idle	49.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.57	16.87	1.15	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:1	36.81	2822	1.76	13.57	104	191	Off Idle	49.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.57	16.65	1.13	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:1	36.81	2820	1.76	13.57	104	191	Off Idle	49.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.6	16.38	1.12	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:1	36.81	2818	1.76	13.59	104	191	Off Idle	49	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.61	16.2	1.1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:1	36.81	2814	1.75	13.58	104	191	Off Idle	49.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.59	15.98	1.09	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:1	36.81	2814	1.75	13.59	104	191	Off Idle	49.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.58	15.84	1.08	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:1	36.81	2814	1.75	13.59	104	191	Off Idle	49.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.56	15.72	1.07	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:1	36.81	2816	1.75	13.59	104	191	Off Idle	49	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.56	15.53	1.06	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:2	36.81	2814	1.75	13.58	104	191	Off Idle	48.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.57	15.46	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:2	36.81	2813	1.75	13.59	104	191	Off Idle	48.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.56	15.33	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:2	36.81	2818	1.75	13.59	104	191	Off Idle	48.7	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.55	15.29	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:2	36.81	2818	1.75	13.6	104	191	Off Idle	48.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.53	15.21	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:2	36.81	2812	1.75	13.59	104	191	Off Idle	48.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.51	15.17	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:2	36.81	2816	1.75	13.58	104	191	Off Idle	49	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.53	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:3	36.81	2813	1.75	13.56	104	191	Off Idle	48.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.53	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:3	36.81	2812	1.76	13.57	104	191	Off Idle	48.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.54	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:3	36.81	2814	1.76	13.57	104	191	Off Idle	48.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.52	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:3	36.81	2810	1.76	13.59	104	191	Off Idle	48.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.52	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:3	36.81	2810	1.76	13.59	104	191	Off Idle	48.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.51	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:3	36.81	2809	1.76	13.59	103	191	Off Idle	48.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.51	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:4	36.81	2811	1.76	13.58	103	191	Off Idle	48.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.55	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:4	36.81	2810	1.76	13.57	103	191	Off Idle	48.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:4	36.81	2806	1.76	13.58	104	191	Off Idle	48.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.52	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:4	36.81	2810	1.76	13.6	104	191	Off Idle	48.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.53	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:4	36.81	2802	1.76	13.6	104	191	Off Idle	48.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.52	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:4	36.81	2802	1.76	13.6	104	191	Off Idle	48.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.47	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:4	36.81	2803	1.76	13.58	104	191	Off Idle	48.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.5	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:5	36.81	2807	1.76	13.59	104	191	Off Idle	48.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.44	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:5	36.81	2806	1.76	13.59	103	191	Off Idle	48.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.44	15.17	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:5	36.81	2809	1.76	13.6	103	191	Off Idle	48.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.46	15.23	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:5	36.81	2809	1.76	13.59	104	191	Off Idle	48.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.49	15.26	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:5	36.81	2809	1.76	13.6	104	191	Off Idle	48.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.5	15.28	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:5	36.81	2806	1.76	13.6	104	191	Off Idle	48.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.51	15.29	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:6	36.81	2804	1.76	13.59	104	191	Off Idle	48.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.49	15.29	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:6	36.81	2801	1.76	13.59	104	191	Off Idle	49	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.5	15.28	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:6	36.81	2803	1.76	13.58	104	191	Off Idle	49.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.49	15.27	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:6	36.81	2802	1.76	13.6	104	191	Off Idle	49.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.5	15.23	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:6	36.81	2802	1.76	13.6	104	191	Off Idle	49.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.5	15.2	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:6	36.81	2809	1.76	13.58	104	191	Off Idle	49.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.5	15.17	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:6	36.81	2794	1.76	13.59	104	191	Off Idle	49.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.53	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:7	36.81	2787	1.76	13.58	104	191	Off Idle	49.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.56	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:33:7	36.81	2784	1.76	13.58	104	191	Off Idle	50.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.56	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:7	36.81	2770	1.76	13.57	104	191	Off Idle	50.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.58	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:7	36.81	2780	1.76	13.57	104	191	Off Idle	50.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.56	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:7	36.81	2780	1.75	13.58	104	191	Off Idle	50.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.53	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:7	36.81	2774	1.75	13.56	104	191	Off Idle	50.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.55	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:8	36.81	2771	1.75	13.58	104	191	Off Idle	50.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.55	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:8	36.81	2767	1.75	13.58	104	191	Off Idle	50.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.55	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:8	36.81	2765	1.75	13.58	104	191	Off Idle	50.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.56	15.05	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:8	36.81	2761	1.75	13.58	104	191	Off Idle	50.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.59	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:8	36.81	2761	1.75	13.58	103	191	Off Idle	50.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.59	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:8	36.81	2781	1.75	13.59	103	191	Off Idle	51	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.6	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:9	36.81	2762	1.75	13.59	103	191	Off Idle	51.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.59	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:9	36.81	2764	1.74	13.6	104	191	Off Idle	51.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.59	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:9	36.81	2773	1.74	13.58	104	191	Off Idle	51.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.59	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:33:9	36.81	2766	1.73	13.59	104	191	Off Idle	51.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.62	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:33:9	36.81	2779	1.72	13.59	104	191	Full Load	51.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.68	14.81	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:33:9	36.81	2772	1.7	13.59	104	191	Idle	52.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.79	14.81	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:33:9	36.81	2795	1.69	13.6	103	191	Idle	52.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.83	14.82	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:34:0	36.81	2788	1.68	13.6	103	191	Idle	52.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.87	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:34:0	36.81	2783	1.67	13.59	103	191	Idle	52.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.94	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:0	36.81	2778	1.66	13.6	103	191	Idle	51.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.05	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:0	36.81	2754	1.66	13.6	103	191	Idle	51.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.08	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:34:0	34.08	2722	1.64	13.59	104	191	Idle	51.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.11	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:0	28.63	2718	1.63	13.6	104	191	Idle	51.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.14	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:1	23.18	2713	1.62	13.61	104	191	Idle	51.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.19	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:1	23.18	2713	1.61	13.61	104	191	Idle	51.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-10.18	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:1	19.09	2727	1.59	13.6	103	191	Idle	51.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.19	14.78	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:1	19.09	2704	1.59	13.6	103	191	Idle	51.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.19	14.77	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:1	19.09	2723	1.57	13.59	103	191	Idle	51.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.21	14.79	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:1	19.09	2721	1.56	13.59	103	191	Idle	51.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.24	14.81	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:1	19.09	2720	1.56	13.59	103	191	Idle	51.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.26	14.83	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:2	19.09	2721	1.55	13.6	103	191	Idle	51.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.26	14.84	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:2	19.09	2728	1.55	13.59	104	191	Idle	51.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.21	14.87	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:2	19.09	2739	1.55	13.59	104	191	Idle	51.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.17	14.9	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:2	19.09	2742	1.55	13.59	104	191	Idle	50.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.14	14.93	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:2	19.09	2764	1.56	13.59	103	191	Idle	50.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-10.08	14.97	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:2	19.09	2758	1.56	13.58	103	191	Idle	50.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.07	14.98	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:3	19.09	2762	1.56	13.58	103	191	Idle	50.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.07	14.98	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:3	19.09	2762	1.56	13.57	103	191	Idle	50.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.04	14.97	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:3	19.09	2752	1.56	13.57	104	191	Idle	50.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.01	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:3	19.09	2737	1.56	13.58	104	191	Idle	50.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.01	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:3	19.09	2737	1.56	13.57	104	191	Idle	50.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:3	19.09	2725	1.56	13.58	103	191	Idle	51	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.98	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:4	19.09	2718	1.56	13.57	103	191	Idle	51	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.97	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:4	19.09	2713	1.56	13.58	104	191	Idle	51.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.94	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:4	19.09	2694	1.56	13.59	104	191	Idle	51.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.95	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:4	19.09	2704	1.56	13.58	104	191	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	14.96	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:4	19.09	2717	1.56	13.58	104	191	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	14.96	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:4	19.09	2720	1.56	13.58	104	191	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	14.94	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:4	19.09	2740	1.56	13.57	103	191	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	14.9	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:5	19.09	2734	1.56	13.58	103	191	Idle	51.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:5	19.09	2738	1.56	13.59	103	191	Idle	52	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:5	19.09	2746	1.56	13.58	104	191	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:5	19.09	2743	1.56	13.59	104	191	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	15.4	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:5	19.09	2734	1.56	13.6	104	191	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	15.82	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:5	19.09	2726	1.56	13.61	103	191	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	16.59	1.13	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:6	19.09	2724	1.55	13.61	103	191	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	16.85	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:6	19.09	2717	1.55	13.6	103	191	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	17.66	1.2	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:6	19.09	2705	1.55	13.59	103	191	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	18.23	1.24	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:6	19.09	2702	1.55	13.59	103	191	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	18.75	1.28	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:6	19.09	2691	1.55	13.58	104	191	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	19.22	1.31	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:6	19.09	2667	1.55	13.59	104	191	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	19.61	1.34	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:6	19.09	2681	1.55	13.59	104	191	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	19.92	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:7	19.09	2681	1.55	13.59	104	191	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.13	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:7	19.09	2680	1.55	13.61	104	191	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:7	19.09	2683	1.55	13.61	104	191	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:7	19.09	2684	1.55	13.61	103	191	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:7	19.09	2684	1.55	13.6	103	191	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:7	19.09	2687	1.55	13.6	103	191	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:8	19.09	2688	1.55	13.58	103	191	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:8	19.09	2688	1.55	13.58	103	191	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:8	19.09	2689	1.55	13.59	103	191	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:8	19.09	2687	1.55	13.58	103	191	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:34:8	19.09	2681	1.54	13.6	103	191	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:8	19.09	2680	1.54	13.6	103	191	Idle	53.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:9	19.09	2675	1.54	13.59	103	191	Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:9	19.09	2674	1.54	13.6	103	191	Idle	53.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:9	19.09	2678	1.54	13.59	103	191	Idle	53.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:9	19.09	2665	1.53	13.58	104	191	Idle	53.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:9	19.09	2662	1.53	13.58	104	191	Idle	53.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:9	19.09	2662	1.53	13.56	104	191	Idle	54.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:34:9	19.09	2655	1.53	13.58	103	191	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:0	19.09	2666	1.53	13.57	103	191	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:0	19.09	2668	1.52	13.54	103	191	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:0	19.09	2668	1.52	13.52	103	191	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:0	19.09	2668	1.52	13.51	103	191	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:0	19.09	2666	1.52	13.49	104	191	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:0	19.09	2661	1.52	13.51	104	191	Idle	54.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:1	19.09	2660	1.51	13.5	104	191	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:1	19.09	2643	1.51	13.51	104	191	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:1	19.09	2646	1.51	13.53	104	191	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:1	19.09	2665	1.5	13.51	103	191	Idle	55.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:1	19.09	2665	1.5	13.52	103	191	Idle	55.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:1	19.09	2641	1.5	13.53	103	191	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:1	19.09	2628	1.49	13.53	103	191	Idle	56.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:2	19.09	2646	1.49	13.53	103	191	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:2	19.09	2634	1.49	13.53	103	191	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:2	19.09	2634	1.49	13.54	104	191	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:2	19.09	2635	1.48	13.54	104	191	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:2	19.09	2636	1.48	13.55	104	191	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:2	19.09	2636	1.48	13.54	103	191	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:3	19.09	2656	1.48	13.54	103	191	Idle	57.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:3	19.09	2634	1.48	13.53	104	191	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:3	19.09	2634	1.47	13.54	104	191	Idle	57.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:3	19.09	2623	1.47	13.53	104	191	Idle	57.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:3	19.09	2630	1.47	13.53	103	191	Idle	57.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:3	19.09	2646	1.47	13.54	103	191	Idle	57.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:4	19.09	2623	1.46	13.53	104	191	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:4	19.09	2622	1.46	13.54	104	191	Idle	58.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:4	19.09	2619	1.46	13.52	104	191	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:4	19.09	2616	1.46	13.54	104	191	Idle	58.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:4	19.09	2616	1.46	13.53	104	191	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:4	19.09	2614	1.46	13.53	104	191	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:4	19.09	2612	1.45	13.53	103	191	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:5	19.09	2602	1.45	13.53	103	191	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:5	19.09	2612	1.45	13.53	104	191	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:5	19.09	2611	1.45	13.54	104	191	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:5	19.09	2611	1.44	13.53	104	191	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:5	19.09	2610	1.44	13.54	104	191	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:5	19.09	2618	1.44	13.55	104	191	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:6	19.09	2606	1.44	13.53	103	191	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:6	19.09	2583	1.44	13.52	103	191	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:6	19.09	2592	1.43	13.53	103	191	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:6	19.09	2598	1.43	13.52	103	191	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:6	19.09	2590	1.43	13.52	103	191	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:6	19.09	2588	1.43	13.53	103	191	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:6	19.09	2562	1.43	13.55	103	191	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:7	19.09	2574	1.43	13.54	103	191	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:7	19.09	2574	1.43	13.54	103	191	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:7	19.09	2566	1.42	13.54	103	191	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:7	19.09	2561	1.42	13.53	103	191	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:35:7	19.09	2553	1.42	13.52	103	191	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.26	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:7	19.09	2552	1.42	13.53	103	191	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:8	19.09	2548	1.42	13.53	103	191	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.26	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:8	19.09	2538	1.42	13.52	104	191	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.26	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:8	19.09	2545	1.42	13.53	104	191	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.26	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:8	19.09	2545	1.42	13.54	104	191	Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:8	19.09	2545	1.42	13.53	103	191	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:8	19.09	2545	1.42	13.55	103	191	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:9	19.09	2545	1.42	13.54	103	191	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:9	19.09	2542	1.42	13.55	103	191	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:9	19.09	2539	1.42	13.54	103	191	Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:9	19.09	2532	1.41	13.55	103	191	Idle	60	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:9	19.09	2528	1.41	13.54	103	191	Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:9	19.09	2518	1.41	13.54	103	191	Idle	60.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:35:9	19.09	2513	1.41	13.54	103	191	Idle	60.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:0	19.09	2508	1.41	13.54	103	191	Idle	60.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:0	19.09	2509	1.41	13.55	103	191	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:0	19.09	2510	1.41	13.54	103	191	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:0	19.09	2510	1.4	13.53	103	191	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:0	19.09	2508	1.4	13.54	103	191	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:0	19.09	2507	1.4	13.54	103	191	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:1	19.09	2507	1.4	13.52	103	191	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:1	19.09	2503	1.39	13.53	103	191	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:1	19.09	2503	1.39	13.53	103	191	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:1	19.09	2498	1.39	13.52	103	191	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:1	19.09	2490	1.38	13.53	103	191	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:1	19.09	2486	1.38	13.53	103	191	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:1	19.09	2472	1.38	13.53	103	191	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:2	19.09	2454	1.37	13.54	103	191	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:2	19.09	2438	1.37	13.53	103	191	Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:2	19.09	2401	1.36	13.53	103	191	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:2	19.09	2391	1.36	13.53	103	191	Idle	64.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:2	19.09	2362	1.36	13.52	103	191	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:2	19.09	2326	1.35	13.52	103	191	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:3	19.09	2303	1.35	13.53	104	191	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:3	19.09	2303	1.34	13.53	104	191	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:3	17.72	2262	1.34	13.53	104	191	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:3	17.72	2242	1.34	13.53	103	191	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:3	17.72	2240	1.33	13.53	103	191	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:3	17.72	2202	1.33	13.51	103	191	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:4	17.72	2146	1.33	13.5	103	191	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:4	17.72	2140	1.32	13.51	103	191	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:4	17.72	2140	1.32	13.52	103	191	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:4	17.72	2118	1.32	13.53	103	191	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:4	17.72	2077	1.32	13.54	103	191	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:4	17.72	2026	1.32	13.53	103	191	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:4	17.72	2031	1.32	13.52	103	191	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:5	17.72	1999	1.32	13.52	103	191	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:5	17.72	1992	1.32	13.53	103	191	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:5	17.72	1982	1.32	13.56	103	191	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:5	17.72	1950	1.32	13.56	103	191	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:5	17.72	1910	1.32	13.57	104	191	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:5	17.72	1884	1.32	13.58	104	191	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:6	17.72	1884	1.32	13.56	104	191	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:6	17.72	1851	1.32	13.57	103	191	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:6	17.72	1840	1.32	13.57	103	191	Full Load	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:6	17.72	1829	1.33	13.58	103	191	Off Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:6	17.72	1795	1.37	13.57	103	191	Off Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.2	20.22	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:36:6	17.72	1681	1.43	13.57	103	191	Off Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.3	20.23	1.38	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:09:36:6	9.54	1681	1.53	13.57	103	191	Off Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.79	20.23	1.38	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:09:36:7	9.54	1744	1.58	13.56	104	191	Off Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-5.81	20.24	1.38	3.8	6.7	ON	28 Pin	OFF	Removed	Disabled
03:09:36:7	12.27	1715	1.67	13.54	104	191	Off Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-4.38	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:7	12.27	1695	1.73	13.56	104	191	Off Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-3.08	20.25	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:7	14.99	1695	1.77	13.55	103	191	Off Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-2.06	20.25	1.38	3.9	10.3	ON	28 Pin	OFF	Removed	Disabled
03:09:36:7	14.99	1674	1.83	13.53	103	191	Off Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-1.56	20.24	1.38	3.9	10.3	ON	28 Pin	OFF	Removed	Disabled
03:09:36:7	14.99	1711	1.86	13.54	103	191	Off Idle	75.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-1.44	20.25	1.38	3.9	6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:8	17.72	1711	1.89	13.55	103	191	Off Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-1.68	20.25	1.38	3.8	6	ON	28 Pin	OFF	Removed	Disabled
03:09:36:8	17.72	1786	1.88	13.56	103	191	Full Load	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-2.58	20.24	1.38	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:36:8	20.45	1805	1.83	13.57	103	191	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-3.32	20.24	1.38	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:36:8	20.45	1797	1.78	13.58	103	191	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-4.11	20.23	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:36:8	23.18	1790	1.73	13.58	103	191	Idle	80.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.84	20.23	1.38	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:09:36:8	23.18	1739	1.71	13.56	103	191	Idle	80.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.42	20.21	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:36:9	17.72	1751	1.71	13.59	103	191	Idle	80.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.96	20.21	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:36:9	17.72	1795	1.72	13.59	103	191	Idle	79.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.44	20.21	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:36:9	17.72	1859	1.73	13.6	103	191	Idle	78.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.96	20.21	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:36:9	17.72	1894	1.71	13.59	103	191	Idle	77.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.27	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:36:9	17.72	1909	1.68	13.6	103	191	Idle	77.9	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.57	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:36:9	17.72	1942	1.61	13.6	103	191	Idle	77.9	0	2	132	944 Turbo	0.68	Lean	1	14.6	-7.91	20.16	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:36:9	17.72	1967	1.57	13.59	103	190	Idle	77.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.12	19.93	1.36	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:0	17.72	1988	1.47	13.59	103	190	Idle	77.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.36	19.54	1.33	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:0	17.72	2027	1.36	13.6	103	190	Idle	77.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.62	19.08	1.3	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:0	17.72	2027	1.27	13.6	103	191	Idle	77.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-8.83	18.53	1.26	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:0	17.72	2107	1.17	13.61	103	191	Idle	77.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-9.1	17.59	1.2	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:0	17.72	2136	1.11	13.61	103	191	Idle	77.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-9.29	16.92	1.15	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:0	17.72	2181	1.06	13.61	103	191	Idle	79	0	2	132	944 Turbo	0.87	Rich	1	14.6	-9.44	16.23	1.11	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:1	17.72	2181	1	13.6	103	191	Idle	80.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-9.56	15.52	1.06	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:1	17.72	2239	0.97	13.62	103	191	Idle	81.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.79	14.47	0.99	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:1	17.72	2276	0.98	13.62	103	191	Idle	83.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.91	13.95	0.95	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:1	17.72	2336	1.04	13.62	104	191	Idle	83.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.01	13.57	0.92	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:1	17.72	2351	1.06	13.62	104	191	Idle	84.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-10.16	13.26	0.9	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:1	17.72	2385	1.07	13.59	104	190	Idle	83.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-10.29	13.03	0.89	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:1	17.72	2413	1.05	13.58	103	190	Idle	83.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-10.38	12.83	0.87	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:2	17.72	2483	1.02	13.56	103	191	Idle	81.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.47	12.68	0.86	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:2	17.72	2607	0.99	13.55	103	191	Idle	80.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.51	12.55	0.85	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:2	17.72	2634	1	13.55	103	191	Idle	78.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.57	12.36	0.84	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:2	17.72	2672	1.01	13.55	103	191	Idle	77.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.62	12.26	0.84	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:2	17.72	2716	1.01	13.55	103	191	Idle	75.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.66	12.15	0.83	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:2	17.72	2772	1.01	13.54	103	191	Idle	71.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.67	12.03	0.82	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:3	17.72	2864	1.02	13.55	103	190	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	11.96	0.81	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:3	17.72	2864	1.03	13.55	103	190	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	11.91	0.81	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:3	19.09	2995	1.07	13.54	103	191	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	11.9	0.81	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:3	19.09	2998	1.1	13.54	103	191	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	11.94	0.81	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:3	19.09	3014	1.13	13.54	103	191	Idle	60.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	12.05	0.82	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:3	19.09	3166	1.16	13.53	103	191	Idle	58.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	12.18	0.83	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:4	19.09	3154	1.19	13.54	103	191	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	12.37	0.84	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:4	19.09	3212	1.22	13.54	103	191	Idle	51.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	12.65	0.86	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:4	19.09	3238	1.25	13.54	103	191	Idle	50	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	13.1	0.89	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:4	19.09	3325	1.28	13.53	103	191	Idle	48.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	13.82	0.94	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:4	19.09	3324	1.32	13.55	104	191	Idle	46.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	14.63	1	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:4	19.09	3336	1.35	13.54	104	191	Idle	45.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	15.84	1.08	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:4	19.09	3378	1.39	13.55	104	191	Idle	44.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	16.62	1.13	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:5	20.45	3388	1.42	13.53	103	191	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	17.36	1.18	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:5	20.45	3374	1.47	13.54	103	191	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	18.42	1.25	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:5	20.45	3337	1.5	13.55	103	191	Idle	42	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	19.07	1.3	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:5	20.45	3318	1.53	13.54	103	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	19.36	1.32	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:5	20.45	3276	1.56	13.55	103	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.04	1.36	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:37:5	20.45	3276	1.59	13.52	103	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:6	20.45	3242	1.61	13.52	103	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:6	20.45	3218	1.62	13.53	103	191	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:6	20.45	3153	1.63	13.52	103	191	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:6	20.45	3172	1.64	13.52	103	190	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:6	20.45	3174	1.65	13.54	103	190	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:6	20.45	3171	1.67	13.54	103	190	Idle	38.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:6	20.45	3171	1.68	13.54	103	191	Idle	38.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:7	20.45	3178	1.69	13.54	103	191	Idle	37.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:7	20.45	3185	1.69	13.54	103	191	Idle	37	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:7	20.45	3188	1.7	13.55	103	190	Idle	36.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:7	20.45	3199	1.7	13.54	103	190	Idle	36.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.26	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:7	20.45	3200	1.71	13.55	103	190	Idle	36.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:7	20.45	3224	1.71	13.54	103	190	Idle	36.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:8	20.45	3209	1.72	13.54	103	190	Idle	36.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:8	20.45	3189	1.72	13.54	103	190	Idle	36.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:8	20.45	3174	1.72	13.52	103	190	Idle	37.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:8	20.45	3158	1.72	13.52	103	190	Idle	38	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:8	20.45	3107	1.72	13.52	103	191	Idle	38.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:8	20.45	3107	1.72	13.52	103	191	Idle	39.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:9	20.45	3110	1.72	13.52	104	191	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:9	20.45	3073	1.72	13.54	104	191	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:9	20.45	3079	1.72	13.55	104	191	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:9	20.45	3076	1.72	13.55	103	191	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:9	20.45	3064	1.72	13.55	103	191	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:9	20.45	3057	1.72	13.55	103	191	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:37:9	20.45	3053	1.72	13.53	103	190	Idle	39.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:0	20.45	3051	1.72	13.52	103	190	Idle	39.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:0	19.09	3040	1.71	13.53	103	191	Idle	38.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:0	19.09	3049	1.71	13.53	103	191	Idle	38.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:0	19.09	3048	1.71	13.52	103	191	Idle	38	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:0	19.09	3065	1.71	13.53	103	191	Idle	38	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:0	19.09	3065	1.71	13.52	103	191	Idle	38	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:1	19.09	3034	1.71	13.53	103	191	Idle	38	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:1	19.09	3007	1.71	13.52	103	191	Idle	38.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:1	19.09	3014	1.71	13.54	103	191	Idle	38.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:1	19.09	3008	1.71	13.54	103	191	Idle	38.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:1	19.09	2995	1.71	13.54	103	190	Idle	38.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:1	19.09	2995	1.71	13.54	103	190	Idle	39.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:1	19.09	2980	1.71	13.54	103	190	Idle	39.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:2	19.09	2963	1.71	13.55	103	191	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:2	19.09	2951	1.71	13.54	103	191	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:2	19.09	2937	1.71	13.54	103	191	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:2	19.09	2936	1.71	13.55	103	190	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:2	19.09	2918	1.71	13.54	103	190	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:2	19.09	2921	1.71	13.56	103	190	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:3	19.09	2918	1.71	13.56	103	190	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:3	19.09	2906	1.71	13.55	103	190	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:3	19.09	2911	1.71	13.54	103	190	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:3	19.09	2905	1.7	13.54	103	190	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:3	19.09	2901	1.7	13.54	103	190	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:3	19.09	2900	1.7	13.53	103	190	Idle	39.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:4	19.09	2908	1.7	13.53	103	190	Idle	39.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:4	19.09	2908	1.7	13.54	103	190	Idle	39.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:4	19.09	2879	1.7	13.54	103	190	Idle	39.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:4	19.09	2856	1.71	13.52	103	190	Idle	39.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:4	19.09	2859	1.71	13.53	103	190	Idle	39.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:4	19.09	2856	1.71	13.52	103	190	Idle	39.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:38:4	19.09	2847	1.71	13.53	103	190	Idle	39.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:5	19.09	2834	1.71	13.54	103	190	Idle	39.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:5	19.09	2834	1.71	13.55	103	190	Idle	39.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:5	19.09	2822	1.71	13.56	103	190	Idle	39.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:5	19.09	2813	1.71	13.56	103	190	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:5	19.09	2802	1.71	13.57	103	190	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:5	19.09	2804	1.71	13.56	103	190	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.48	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:6	19.09	2813	1.71	13.54	103	190	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.48	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:6	19.09	2796	1.71	13.53	103	190	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.44	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:6	19.09	2789	1.71	13.52	103	190	Idle	42.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:6	19.09	2781	1.71	13.52	103	190	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.47	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:6	19.09	2770	1.71	13.52	103	190	Idle	42.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:6	19.09	2770	1.7	13.52	103	190	Idle	42.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:6	19.09	2761	1.7	13.52	103	190	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:7	19.09	2761	1.7	13.52	103	190	Idle	44.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:7	19.09	2736	1.69	13.53	103	190	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:7	19.09	2738	1.69	13.54	104	190	Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:7	19.09	2732	1.69	13.54	104	190	Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:7	19.09	2730	1.68	13.54	104	190	Idle	45.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:7	19.09	2721	1.68	13.55	103	190	Idle	45.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:8	19.09	2714	1.68	13.54	103	190	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:8	19.09	2707	1.67	13.53	104	190	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:8	19.09	2677	1.67	13.54	104	190	Idle	46.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:8	19.09	2677	1.66	13.53	104	190	Idle	46.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:8	19.09	2687	1.66	13.54	103	190	Idle	47.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:8	19.09	2683	1.66	13.53	103	190	Idle	47.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:9	19.09	2690	1.65	13.53	103	190	Idle	47.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:9	19.09	2670	1.65	13.55	103	190	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:9	19.09	2646	1.64	13.54	103	190	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:9	19.09	2647	1.63	13.53	103	190	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:9	19.09	2634	1.63	13.55	103	190	Idle	48.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:9	19.09	2634	1.62	13.53	103	190	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:38:9	19.09	2624	1.62	13.54	103	190	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:0	19.09	2607	1.62	13.54	103	190	Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:0	19.09	2607	1.61	13.53	103	190	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:0	19.09	2590	1.6	13.53	103	190	Idle	51.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:0	19.09	2590	1.59	13.52	103	190	Idle	52	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:0	19.09	2572	1.58	13.52	103	190	Idle	52.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:0	19.09	2568	1.58	13.52	103	190	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:1	19.09	2557	1.57	13.51	103	190	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:1	19.09	2543	1.56	13.52	103	190	Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:1	19.09	2540	1.56	13.53	103	190	Idle	53.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:1	19.09	2516	1.55	13.53	103	190	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:1	19.09	2515	1.54	13.54	103	190	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:1	19.09	2481	1.53	13.55	103	190	Idle	55.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:1	19.09	2481	1.53	13.53	103	190	Idle	55.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:2	19.09	2490	1.52	13.54	103	190	Idle	55.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:2	19.09	2488	1.51	13.55	103	190	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:2	19.09	2468	1.51	13.54	103	190	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:2	19.09	2468	1.5	13.54	103	190	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:2	19.09	2456	1.49	13.54	103	190	Idle	57.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:2	19.09	2444	1.48	13.53	103	190	Idle	58.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:3	19.09	2444	1.48	13.53	103	190	Idle	58.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:3	19.09	2410	1.47	13.54	103	190	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:3	17.72	2417	1.46	13.53	103	190	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:3	17.72	2417	1.46	13.53	103	190	Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:3	17.72	2388	1.46	13.53	103	190	Idle	60.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:3	17.72	2392	1.45	13.53	103	190	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:39:4	17.72	2385	1.44	13.53	103	190	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:4	17.72	2385	1.44	13.54	103	190	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:4	17.72	2380	1.43	13.54	103	190	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:4	17.72	2386	1.42	13.56	103	190	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:4	17.72	2378	1.41	13.57	103	190	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:4	17.72	2378	1.41	13.57	103	190	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:4	17.72	2370	1.4	13.58	103	190	Idle	64.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:5	17.72	2382	1.4	13.58	103	190	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.18	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:5	17.72	2381	1.39	13.57	103	190	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.18	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:5	17.72	2383	1.38	13.58	103	190	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.17	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:5	17.72	2384	1.37	13.57	103	190	Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.16	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:5	17.72	2381	1.36	13.59	103	190	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.17	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:5	17.72	2381	1.35	13.59	103	190	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.17	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:6	17.72	2381	1.35	13.58	103	190	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:6	17.72	2379	1.33	13.6	103	190	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:6	17.72	2377	1.32	13.61	103	190	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:6	17.72	2373	1.31	13.62	103	190	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:6	17.72	2368	1.3	13.62	103	190	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:6	17.72	2366	1.29	13.63	103	190	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:6	17.72	2357	1.28	13.62	103	190	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:7	17.72	2351	1.27	13.6	103	190	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:7	17.72	2344	1.27	13.6	103	190	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:7	17.72	2344	1.26	13.6	103	190	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:7	17.72	2333	1.25	13.6	103	190	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:7	17.72	2332	1.24	13.61	103	190	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:7	17.72	2326	1.23	13.61	103	190	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:8	17.72	2320	1.23	13.59	103	190	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:8	17.72	2299	1.22	13.58	103	190	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:8	17.72	2305	1.21	13.57	103	190	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:8	17.72	2306	1.2	13.59	103	190	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.06	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:8	17.72	2300	1.2	13.59	103	190	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.07	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:8	17.72	2299	1.19	13.59	103	190	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.07	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:9	17.72	2298	1.19	13.6	103	190	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.07	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:9	17.72	2297	1.19	13.6	103	190	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.07	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:9	17.72	2296	1.18	13.59	103	190	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.08	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:9	17.72	2296	1.18	13.59	103	190	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.08	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:9	17.72	2306	1.18	13.6	103	190	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.08	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:9	17.72	2294	1.18	13.59	103	190	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.07	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:39:9	17.72	2284	1.17	13.58	103	190	Idle	73.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:0	17.72	2291	1.17	13.6	103	190	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:0	17.72	2289	1.17	13.61	103	190	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:0	17.72	2287	1.17	13.6	103	190	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:0	17.72	2295	1.16	13.6	103	190	Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:0	17.72	2282	1.16	13.58	103	190	Idle	75.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:0	17.72	2282	1.16	13.56	103	190	Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:1	17.72	2278	1.15	13.56	103	190	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:1	17.72	2275	1.15	13.57	103	190	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:1	17.72	2274	1.15	13.57	103	190	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:1	17.72	2268	1.14	13.57	103	190	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:1	17.72	2259	1.14	13.57	103	190	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:1	17.72	2248	1.13	13.58	103	190	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:1	17.72	2248	1.13	13.59	103	190	Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:2	17.72	2230	1.12	13.6	103	190	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:2	17.72	2230	1.12	13.63	103	190	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:2	17.72	2218	1.11	13.63	103	190	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:2	17.72	2226	1.11	13.62	103	190	Idle	78.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:2	17.72	2243	1.1	13.61	103	190	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:2	17.72	2234	1.1	13.61	103	190	Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:40:3	17.72	2244	1.09	13.61	103	190	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:3	17.72	2231	1.09	13.61	103	190	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:3	17.72	2209	1.09	13.6	103	190	Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:3	17.72	2218	1.09	13.6	103	190	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:3	17.72	2224	1.08	13.58	103	190	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:3	17.72	2224	1.08	13.57	103	190	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:4	17.72	2224	1.08	13.57	103	190	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:4	17.72	2225	1.07	13.59	103	190	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:4	17.72	2226	1.07	13.6	103	190	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:4	17.72	2224	1.07	13.61	103	190	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:4	17.72	2217	1.06	13.61	103	190	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:4	17.72	2206	1.06	13.61	103	190	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:4	17.72	2206	1.06	13.59	103	190	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:5	17.72	2186	1.06	13.59	103	190	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:5	17.72	2185	1.05	13.58	103	190	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:5	17.72	2185	1.05	13.58	103	190	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:5	17.72	2166	1.05	13.59	103	190	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:5	17.72	2166	1.05	13.6	103	190	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:5	17.72	2157	1.04	13.61	103	190	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:6	17.72	2157	1.04	13.62	103	190	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:6	17.72	2155	1.04	13.6	103	190	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:6	17.72	2152	1.04	13.6	103	190	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:6	17.72	2149	1.03	13.59	103	190	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:6	17.72	2148	1.03	13.59	103	190	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:6	17.72	2150	1.03	13.6	103	190	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:6	17.72	2152	1.03	13.6	103	190	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:7	17.72	2152	1.02	13.6	103	190	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:7	17.72	2158	1.02	13.59	103	190	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:7	17.72	2161	1.02	13.59	103	190	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:7	17.72	2161	1.02	13.57	103	190	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:7	17.72	2162	1.02	13.56	103	190	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:7	17.72	2159	1.02	13.55	103	190	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:8	17.72	2154	1.01	13.56	103	190	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:8	17.72	2145	1.01	13.57	103	190	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:8	17.72	2145	1.01	13.57	103	190	Full Load	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:8	17.72	2130	1.01	13.57	103	190	Full Load	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:8	17.72	2132	1.01	13.58	103	190	Off Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:8	17.72	2021	1.01	13.57	103	190	Off Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.4	1.2	ON	28 Pin	OFF	Removed	Disabled
03:09:40:9	9.54	2081	1.01	13.59	103	190	Off Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.4	1.2	ON	28 Pin	OFF	Removed	Disabled
03:09:40:9	9.54	2136	1.03	13.59	103	190	Off Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:9	12.27	2133	1.04	13.6	103	190	Off Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:40:9	12.27	2130	1.05	13.61	103	190	Off Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:40:9	14.99	2121	1.08	13.62	103	190	Off Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:40:9	14.99	2120	1.1	13.62	103	190	Off Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:40:9	17.72	2108	1.12	13.61	103	190	Off Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:41:0	20.45	2108	1.14	13.58	103	190	Off Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:41:0	20.45	2106	1.15	13.57	103	190	Off Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:0	23.18	2090	1.18	13.56	103	190	Off Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:0	23.18	2108	1.24	13.55	103	190	Off Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.4	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:0	25.9	2111	1.28	13.55	103	190	Off Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.25	20.22	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:0	25.9	2121	1.32	13.55	103	190	Off Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.07	20.22	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:41:1	28.63	2122	1.37	13.56	103	190	Off Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.88	20.23	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:41:1	28.63	2122	1.44	13.57	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.56	20.23	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:41:1	31.36	2129	1.49	13.58	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.34	20.23	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:41:1	32.72	2129	1.56	13.58	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.1	20.24	1.38	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:41:1	32.72	2130	1.61	13.59	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.75	20.24	1.38	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:41:1	32.72	2144	1.67	13.59	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.46	20.24	1.38	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:41:1	32.72	2164	1.75	13.6	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.01	20.24	1.38	3.3	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:41:2	32.72	2182	1.8	13.6	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.69	20.25	1.38	3.3	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:2	32.72	2182	1.85	13.6	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.33	20.24	1.38	3.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:41:2	32.72	2196	1.9	13.59	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.95	20.25	1.38	3.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:41:2	32.72	2247	1.95	13.59	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.63	20.24	1.38	3.3	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:41:2	32.72	2245	2.03	13.59	103	190	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-5.16	20.25	1.38	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:41:2	32.72	2245	2.08	13.59	103	190	Off Idle	85.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-4.88	20.25	1.38	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:3	32.72	2268	2.12	13.59	103	190	Off Idle	85.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-4.65	20.24	1.38	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:3	32.72	2268	2.16	13.58	103	190	Off Idle	84.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-4.37	20.24	1.38	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:3	32.72	2302	2.22	13.58	103	190	Off Idle	83.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-3.91	20.24	1.38	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:3	32.72	2274	2.25	13.58	103	189	Off Idle	83.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-3.76	20.23	1.38	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:41:3	32.72	2239	2.29	13.59	103	189	Off Idle	83	0	2	132	944 Turbo	0.04	Lean	1	14.6	-3.55	20.24	1.38	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:09:41:3	32.72	2239	2.32	13.6	103	189	Off Idle	82.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.4	20.23	1.38	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:41:4	32.72	2166	2.36	13.6	103	190	Off Idle	81.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.18	20.13	1.37	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:41:4	31.36	2163	2.38	13.59	103	190	Off Idle	81.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.04	19.97	1.36	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:41:4	31.36	2140	2.42	13.59	103	190	Off Idle	81.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.92	19.76	1.35	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:41:4	31.36	2132	2.43	13.59	103	190	Off Idle	81.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-2.74	19.62	1.34	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:41:4	31.36	2119	2.45	13.59	103	190	Off Idle	81.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.6	19.29	1.31	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:41:4	29.99	2110	2.46	13.59	103	190	Off Idle	81.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-2.48	18.92	1.29	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:09:41:4	29.99	2151	2.48	13.6	103	190	Off Idle	81.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.22	18.31	1.25	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:41:5	29.99	2151	2.5	13.59	103	190	Off Idle	82.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.08	18.1	1.23	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:41:5	29.99	2176	2.51	13.59	103	190	Off Idle	82.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-2.06	17.4	1.19	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:41:5	29.99	2194	2.52	13.58	103	190	Off Idle	83.3	0	2	132	944 Turbo	0.63	Lean	1	14.6	-1.75	16.73	1.14	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:5	29.99	2212	2.52	13.58	103	190	Off Idle	83.6	0	2	132	944 Turbo	0.69	Lean	1	14.6	-1.7	16.53	1.13	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:5	29.99	2234	2.54	13.57	103	190	Off Idle	83.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.5	16.08	1.1	3.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:5	29.99	2249	2.55	13.57	103	190	Off Idle	84.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.39	15.81	1.08	3.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:6	29.99	2249	2.56	13.57	103	190	Off Idle	84.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.27	15.6	1.06	3.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:6	29.99	2260	2.57	13.58	103	190	Off Idle	84	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.2	15.32	1.04	3.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:6	29.99	2251	2.57	13.6	103	190	Off Idle	83.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.16	15.09	1.03	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:6	29.99	2247	2.58	13.59	103	190	Off Idle	83.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.09	14.98	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:6	29.99	2244	2.59	13.58	103	190	Off Idle	82.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.04	14.89	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:6	29.99	2254	2.6	13.58	103	189	Off Idle	82.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.98	14.82	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:6	31.36	2237	2.61	13.58	103	189	Off Idle	81.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.95	14.72	1	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:7	31.36	2244	2.62	13.6	103	189	Off Idle	81.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.96	14.67	1	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:7	31.36	2260	2.63	13.6	103	189	Off Idle	81	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.92	14.65	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:7	29.99	2265	2.64	13.62	103	190	Off Idle	80.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.93	14.64	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:7	29.99	2280	2.65	13.62	103	190	Off Idle	80.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.91	14.62	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:7	29.99	2286	2.65	13.6	103	190	Off Idle	80.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.86	14.59	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:7	29.99	2291	2.65	13.6	103	190	Off Idle	80.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.79	14.51	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:41:8	29.99	2310	2.66	13.59	103	190	Off Idle	80	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.82	14.44	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:8	31.36	2288	2.66	13.57	103	190	Off Idle	79.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.78	14.29	0.97	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:8	31.36	2286	2.66	13.57	103	190	Off Idle	79.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.81	14.18	0.97	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:8	31.36	2281	2.67	13.57	103	190	Off Idle	79.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.8	14.07	0.96	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:8	31.36	2276	2.67	13.59	103	190	Off Idle	79.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.76	13.97	0.95	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:41:8	31.36	2268	2.67	13.59	103	190	Off Idle	79.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.64	13.87	0.94	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:9	29.99	2281	2.68	13.6	103	190	Off Idle	79.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.61	13.76	0.94	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:9	29.99	2285	2.68	13.58	103	190	Off Idle	79.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.63	13.69	0.93	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:9	29.99	2289	2.68	13.58	103	190	Off Idle	79	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.56	13.68	0.93	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:9	29.99	2297	2.69	13.59	103	190	Off Idle	78.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.57	13.66	0.93	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:9	29.99	2320	2.7	13.6	103	190	Off Idle	78.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.5	13.65	0.93	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:9	31.36	2324	2.7	13.6	103	190	Off Idle	78.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.45	13.65	0.93	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:41:9	31.36	2324	2.7	13.59	103	190	Off Idle	78.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.49	13.65	0.93	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:42:0	31.36	2344	2.71	13.57	103	190	Off Idle	78.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.48	13.64	0.93	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:42:0	29.99	2375	2.71	13.57	103	190	Off Idle	78	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.5	13.63	0.93	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:42:0	29.99	2379	2.71	13.58	103	189	Off Idle	77.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.58	13.6	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:42:0	29.99	2379	2.71	13.56	103	189	Off Idle	77.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.52	13.57	0.92	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:42:0	29.99	2380	2.72	13.56	103	189	Off Idle	77.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.39	13.52	0.92	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:0	29.99	2377	2.72	13.56	103	190	Off Idle	76.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.34	13.48	0.92	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:1	29.99	2374	2.73	13.57	103	190	Off Idle	76.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.36	13.43	0.91	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:42:1	29.99	2374	2.73	13.57	103	190	Off Idle	76.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.35	13.39	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:1	29.99	2375	2.73	13.58	103	189	Off Idle	75.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.31	13.38	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:1	29.99	2378	2.74	13.59	103	189	Off Idle	75.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.32	13.37	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:1	29.99	2378	2.74	13.59	103	189	Off Idle	74.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.35	13.36	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:1	29.99	2387	2.75	13.57	103	189	Off Idle	74.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.3	13.38	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:1	29.99	2392	2.75	13.57	103	189	Off Idle	74.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.27	13.4	0.91	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:2	29.99	2394	2.76	13.57	103	190	Off Idle	74.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.28	13.42	0.91	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:2	29.99	2400	2.76	13.56	103	190	Off Idle	74	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.2	13.48	0.92	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:2	29.99	2391	2.76	13.56	103	190	Off Idle	73.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.17	13.51	0.92	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:2	29.99	2405	2.77	13.59	103	189	Off Idle	73.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.14	13.57	0.92	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:2	29.99	2426	2.77	13.6	103	189	Off Idle	73	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.14	13.62	0.93	3.3	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:2	29.99	2434	2.78	13.59	103	189	Off Idle	72.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.17	13.66	0.93	3.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:42:3	29.99	2455	2.78	13.6	103	189	Off Idle	72.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.19	13.69	0.93	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:42:3	29.99	2446	2.79	13.59	103	189	Off Idle	72.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.14	13.73	0.94	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:3	29.99	2443	2.79	13.57	103	189	Off Idle	72	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.09	13.75	0.94	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:3	29.99	2443	2.8	13.58	103	189	Off Idle	71.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.1	13.78	0.94	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:3	29.99	2444	2.8	13.58	103	189	Off Idle	71.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.03	13.83	0.94	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:3	29.99	2449	2.8	13.58	103	189	Off Idle	71.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.05	13.87	0.94	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:4	29.99	2449	2.81	13.59	103	189	Off Idle	70.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.04	13.9	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:4	29.99	2452	2.81	13.58	103	189	Off Idle	70.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.09	13.96	0.95	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:4	29.99	2458	2.82	13.56	103	189	Off Idle	70.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.04	14.02	0.96	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:4	29.99	2467	2.82	13.56	103	189	Off Idle	69.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.05	14.06	0.96	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:4	29.99	2473	2.82	13.56	103	189	Off Idle	69.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.12	14.1	0.96	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:4	29.99	2476	2.83	13.56	103	190	Off Idle	69.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.14	14.15	0.96	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:4	29.99	2486	2.83	13.57	103	190	Off Idle	69.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.16	14.2	0.97	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:5	29.99	2494	2.84	13.58	103	189	Off Idle	68.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.17	14.24	0.97	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:5	29.99	2495	2.84	13.57	103	189	Off Idle	68.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.22	14.29	0.97	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:5	29.99	2500	2.84	13.57	103	189	Off Idle	68.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.22	14.32	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:5	29.99	2506	2.85	13.57	103	189	Off Idle	68.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.24	14.38	0.98	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:5	29.99	2515	2.85	13.59	103	189	Off Idle	68.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.3	14.39	0.98	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:5	29.99	2515	2.85	13.59	103	189	Off Idle	68	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.3	14.41	0.98	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:6	29.99	2522	2.86	13.6	103	189	Off Idle	67.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.35	14.44	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:6	29.99	2524	2.86	13.58	103	189	Off Idle	67	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.39	14.47	0.99	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:6	29.99	2540	2.86	13.58	103	189	Off Idle	66.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.37	14.49	0.99	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:6	29.99	2540	2.87	13.58	103	189	Off Idle	66.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.35	14.51	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:6	29.99	2547	2.87	13.58	103	189	Off Idle	66.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.34	14.52	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:6	29.99	2565	2.88	13.56	103	189	Off Idle	65.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.34	14.53	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:6	29.99	2558	2.88	13.56	103	189	Off Idle	65.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.38	14.53	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:7	29.99	2560	2.88	13.56	103	189	Off Idle	65.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.4	14.54	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:7	29.99	2564	2.89	13.57	103	189	Off Idle	64.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.45	14.56	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:7	29.99	2605	2.89	13.57	103	189	Off Idle	64.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	0.51	14.58	0.99	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:7	29.99	2587	2.9	13.57	103	189	Off Idle	63.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	0.55	14.59	0.99	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:7	29.99	2578	2.9	13.57	103	189	Off Idle	63.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	0.62	14.61	1	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:7	29.99	2584	2.91	13.58	103	189	Off Idle	63.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.67	14.63	1	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:8	29.99	2584	2.91	13.58	103	189	Off Idle	63.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.71	14.66	1	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:8	29.99	2589	2.92	13.57	103	189	Off Idle	63.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.68	14.68	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:8	29.99	2598	2.92	13.56	103	189	Off Idle	63.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.73	14.7	1	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:42:8	29.99	2600	2.92	13.57	103	189	Off Idle	63	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.75	14.71	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:8	29.99	2606	2.93	13.56	103	189	Off Idle	63	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.78	14.75	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:8	29.99	2614	2.93	13.57	103	189	Off Idle	62.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.81	14.77	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:9	29.99	2617	2.94	13.56	103	189	Off Idle	62.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.78	14.79	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:9	29.99	2617	2.94	13.56	103	189	Off Idle	62.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.75	14.8	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:42:9	29.99	2619	2.95	13.55	103	189	Off Idle	62	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.77	14.81	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:42:9	28.63	2614	2.95	13.56	103	189	Off Idle	61.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.8	14.82	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:42:9	28.63	2641	2.95	13.56	103	189	Off Idle	61.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	0.83	14.81	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:42:9	28.63	2651	2.96	13.56	103	189	Off Idle	61	0	2	132	944 Turbo	0.56	Rich	1	14.6	0.88	14.81	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:42:9	28.63	2652	2.96	13.55	103	189	Off Idle	60.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	0.96	14.82	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:43:0	28.63	2665	2.97	13.56	103	189	Off Idle	60.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	1.02	14.85	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:43:0	28.63	2718	2.97	13.55	103	189	Off Idle	60	0	2	132	944 Turbo	0.38	Rich	1	14.6	1.04	14.87	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:43:0	29.99	2699	2.98	13.57	103	189	Off Idle	60	0	2	132	944 Turbo	0.32	Lean	1	14.6	1.07	14.88	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:43:0	29.99	2690	2.99	13.57	103	189	Off Idle	59.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	1.06	14.91	1.02	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:43:0	29.99	2696	2.99	13.58	103	189	Off Idle	58.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	1.13	14.95	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:0	29.99	2682	3	13.57	103	189	Off Idle	58.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	1.17	14.98	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:1	28.63	2707	3	13.58	103	190	Off Idle	57.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	1.27	15.04	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:1	28.63	2707	3.01	13.57	103	190	Off Idle	57.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	1.32	15.07	1.03	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:1	28.63	2712	3.02	13.57	103	189	Off Idle	56.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	1.31	15.11	1.03	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:1	28.63	2712	3.02	13.57	103	189	Off Idle	56.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	1.33	15.11	1.03	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:1	28.63	2712	3.03	13.57	103	189	Off Idle	56.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	1.36	15.08	1.03	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:1	29.99	2710	3.03	13.57	103	189	Off Idle	55.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	1.37	15.05	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:1	29.99	2719	3.04	13.57	103	189	Off Idle	55.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.4	15.02	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:2	29.99	2719	3.04	13.56	103	189	Off Idle	55	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.41	14.96	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:2	29.99	2726	3.05	13.57	103	189	Off Idle	54.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	1.45	14.89	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:2	28.63	2740	3.05	13.56	103	189	Off Idle	54.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.54	14.84	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:43:2	28.63	2752	3.06	13.57	103	189	Off Idle	54.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.55	14.75	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:2	28.63	2752	3.06	13.57	103	189	Off Idle	54.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.63	14.71	1	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:2	28.63	2759	3.07	13.57	103	189	Off Idle	54	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.61	14.68	1	3.3	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:3	28.63	2803	3.07	13.58	103	189	Off Idle	53.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	1.59	14.67	1	3.3	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:3	29.99	2803	3.08	13.58	103	189	Off Idle	53.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.6	14.67	1	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:43:3	29.99	2773	3.08	13.57	103	189	Off Idle	53.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	1.64	14.68	1	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:09:43:3	29.99	2793	3.09	13.56	103	189	Off Idle	53	0	2	132	944 Turbo	0.67	Rich	1	14.6	1.68	14.69	1	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:43:3	29.99	2784	3.09	13.57	103	189	Off Idle	52.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	1.65	14.71	1	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:43:3	28.63	2812	3.1	13.57	103	189	Off Idle	52.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	1.65	14.77	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:09:43:4	28.63	2812	3.1	13.55	103	189	Off Idle	52.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	1.75	14.8	1.01	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:4	28.63	2808	3.1	13.55	103	189	Off Idle	51.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	1.74	14.8	1.01	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:43:4	28.63	2812	3.11	13.54	103	189	Off Idle	51.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	1.75	14.81	1.01	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:43:4	29.99	2827	3.11	13.55	103	189	Off Idle	50.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	1.79	14.83	1.01	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:43:4	29.99	2833	3.12	13.55	103	189	Off Idle	50.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	1.86	14.84	1.01	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:09:43:4	29.99	2851	3.12	13.54	103	189	Off Idle	50	0	2	132	944 Turbo	0.36	Rich	1	14.6	1.9	14.85	1.01	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:4	29.99	2859	3.13	13.55	103	189	Off Idle	49.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	1.89	14.86	1.01	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:5	29.99	2859	3.14	13.57	103	189	Off Idle	49.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	1.96	14.89	1.01	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:5	29.99	2884	3.14	13.57	103	189	Off Idle	48.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	2.01	14.97	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:5	29.99	2879	3.15	13.56	103	189	Off Idle	48.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	2.09	14.97	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:5	29.99	2880	3.15	13.56	103	189	Off Idle	48.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	2.12	14.96	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:5	29.99	2882	3.16	13.57	103	189	Off Idle	48	0	2	132	944 Turbo	0.64	Rich	1	14.6	2.12	14.95	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:5	29.99	2856	3.16	13.56	103	189	Off Idle	47.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	2.11	14.92	1.02	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:6	28.63	2866	3.17	13.55	103	189	Off Idle	47.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.17	14.9	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:6	28.63	2875	3.18	13.56	103	189	Off Idle	47.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.2	14.86	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:6	28.63	2884	3.18	13.57	103	189	Off Idle	47.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	2.21	14.84	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:6	28.63	2888	3.18	13.57	103	189	Off Idle	46.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	2.25	14.75	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:6	28.63	2894	3.19	13.57	103	189	Off Idle	46.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	2.28	14.71	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:6	28.63	2900	3.19	13.57	103	189	Off Idle	46.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	2.32	14.69	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:6	28.63	2911	3.19	13.56	103	189	Off Idle	46.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	2.42	14.69	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:7	28.63	2911	3.2	13.56	103	189	Off Idle	45.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	2.46	14.71	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:7	28.63	2925	3.2	13.56	103	189	Off Idle	45.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	2.52	14.7	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:7	28.63	2942	3.21	13.57	103	189	Off Idle	45.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.54	14.72	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:7	28.63	2950	3.21	13.56	103	189	Off Idle	45	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.61	14.73	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:7	28.63	2951	3.22	13.56	103	189	Off Idle	44.5	0	2	132	944 Turbo	0.72	Lean	1	14.6	2.6	14.73	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:7	28.63	2952	3.22	13.57	103	189	Off Idle	44.2	0	2	132	944 Turbo	0.66	Lean	1	14.6	2.66	14.73	1	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:43:8	28.63	2986	3.23	13.57	103	189	Off Idle	43.9	0	2	132	944 Turbo	0.63	Lean	1	14.6	2.67	14.72	1	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:43:8	28.63	2973	3.23	13.56	103	189	Off Idle	43.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	2.73	14.73	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:43:8	28.63	2975	3.24	13.57	103	189	Off Idle	43.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	2.73	14.72	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:43:8	28.63	2977	3.24	13.57	103	189	Off Idle	43.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	2.8	14.74	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:43:8	28.63	3004	3.24	13.57	103	189	Off Idle	42.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	2.8	14.77	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:43:8	28.63	3004	3.25	13.57	103	189	Off Idle	42.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	2.84	14.82	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:43:9	28.63	3000	3.25	13.57	103	189	Off Idle	42.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	2.87	14.85	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:09:43:9	28.63	3018	3.26	13.58	103	189	Off Idle	42	0	2	132	944 Turbo	0.3	Lean	1	14.6	2.94	14.88	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:43:9	27.27	3013	3.26	13.58	103	189	Off Idle	41.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	2.95	14.92	1.02	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:09:43:9	27.27	3014	3.27	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	2.99	14.99	1.02	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:9	27.27	3042	3.27	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	3.01	15.01	1.02	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:09:43:9	27.27	3036	3.28	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	3.17	15.03	1.02	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:09:43:9	27.27	3044	3.29	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	3.15	15	1.02	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:09:44:0	27.27	3046	3.29	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	3.29	14.98	1.02	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:09:44:0	27.27	3052	3.3	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	3.26	14.95	1.02	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:44:0	27.27	3078	3.3	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	3.39	14.9	1.02	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:44:0	27.27	3078	3.31	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	3.32	14.86	1.01	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:44:0	27.27	3114	3.31	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	3.4	14.83	1.01	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:44:0	27.27	3094	3.32	13.59	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	3.41	14.72	1	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:09:44:1	27.27	3097	3.32	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	3.49	14.62	1	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:44:1	27.27	3100	3.33	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	3.47	14.52	0.99	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:44:1	27.27	3104	3.33	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.49	14.42	0.98	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:09:44:1	27.27	3108	3.34	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.53	14.22	0.97	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:44:1	27.27	3110	3.34	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	3.58	14.09	0.96	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:09:44:1	27.27	3118	3.35	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.62	13.88	0.95	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:1	27.27	3156	3.35	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.69	13.74	0.94	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:2	27.27	3145	3.36	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	3.69	13.61	0.93	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:2	27.27	3149	3.36	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	3.76	13.49	0.92	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:2	27.27	3160	3.37	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	3.74	13.43	0.91	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:2	27.27	3167	3.37	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.83	13.33	0.91	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:2	28.63	3186	3.38	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.96	13.25	0.9	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:2	28.63	3186	3.38	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.99	13.17	0.9	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:44:3	28.63	3204	3.39	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.01	13.13	0.89	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:44:3	28.63	3208	3.39	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.08	13.08	0.89	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:44:3	27.27	3198	3.39	13.59	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.09	13.07	0.89	3.4	7.6	ON	28 Pin	OFF	Removed	Disabled
03:09:44:3	27.27	3220	3.4	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.11	13.04	0.89	3.4	7.6	ON	28 Pin	OFF	Removed	Disabled
03:09:44:3	27.27	3226	3.4	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	4.15	12.97	0.88	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:44:3	27.27	3228	3.41	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.11	12.94	0.88	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:44:4	27.27	3236	3.42	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.25	12.93	0.88	3.4	7.6	ON	28 Pin	OFF	Removed	Disabled
03:09:44:4	27.27	3239	3.42	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.32	12.91	0.88	3.4	7.6	ON	28 Pin	OFF	Removed	Disabled
03:09:44:4	27.27	3248	3.43	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.39	12.92	0.88	3.4	7.6	ON	28 Pin	OFF	Removed	Disabled
03:09:44:4	27.27	3256	3.43	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.49	12.88	0.88	3.4	7.6	ON	28 Pin	OFF	Removed	Disabled
03:09:44:4	27.27	3270	3.44	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.48	12.88	0.88	3.4	7.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:4	27.27	3273	3.44	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.61	12.86	0.88	3.4	7.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:4	27.27	3286	3.45	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.69	12.86	0.88	3.4	7.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:5	27.27	3297	3.45	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.74	12.87	0.88	3.4	7.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:5	27.27	3300	3.46	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	4.8	12.86	0.88	3.4	7.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:5	27.27	3328	3.46	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	4.72	12.85	0.88	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:5	27.27	3318	3.47	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	4.77	12.84	0.87	3.6	7.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:5	27.27	3320	3.47	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	4.89	12.83	0.87	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:09:44:5	27.27	3331	3.48	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	4.97	12.81	0.87	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:09:44:6	28.63	3354	3.48	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	5.07	12.79	0.87	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:09:44:6	28.63	3354	3.49	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	5.17	12.79	0.87	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:09:44:6	28.63	3360	3.5	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	5.22	12.79	0.87	3.4	7.8	ON	28 Pin	OFF	Removed	Disabled
03:09:44:6	28.63	3388	3.5	13.56	103	189	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.22	12.8	0.87	3.4	7.9	ON	28 Pin	OFF	Removed	Disabled
03:09:44:6	27.27	3386	3.51	13.56	103	189	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.23	12.79	0.87	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:09:44:6	27.27	3380	3.51	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.33	12.77	0.87	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:09:44:6	27.27	3382	3.52	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.33	12.76	0.87	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:09:44:7	27.27	3385	3.52	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.38	12.75	0.87	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:09:44:7	27.27	3407	3.53	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.46	12.77	0.87	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:09:44:7	27.27	3406	3.53	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.58	12.77	0.87	3.5	8.2	ON	28 Pin	OFF	Removed	Disabled
03:09:44:7	27.27	3417	3.54	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.68	12.76	0.87	3.4	8.2	ON	28 Pin	OFF	Removed	Disabled
03:09:44:7	27.27	3435	3.55	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.89	12.74	0.87	3.4	8.3	ON	28 Pin	OFF	Removed	Disabled
03:09:44:7	27.27	3471	3.56	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.92	12.71	0.87	3.4	8.3	ON	28 Pin	OFF	Removed	Disabled
03:09:44:8	27.27	3458	3.56	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.94	12.71	0.87	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:09:44:8	27.27	3458	3.56	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.08	12.71	0.87	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:44:8	27.27	3459	3.58	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.16	12.71	0.87	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:8	27.27	3465	3.58	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.27	12.71	0.87	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:8	25.9	3478	3.59	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.38	12.7	0.86	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:09:44:8	25.9	3478	3.59	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.52	12.68	0.86	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:09:44:9	25.9	3492	3.6	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.57	12.65	0.86	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:09:44:9	25.9	3516	3.61	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.58	12.64	0.86	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:09:44:9	27.27	3516	3.62	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.59	12.62	0.86	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:9	27.27	3516	3.63	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	6.69	12.61	0.86	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:9	27.27	3529	3.64	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	6.63	12.59	0.86	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:09:44:9	27.27	3539	3.64	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	6.74	12.59	0.86	3.4	8.9	ON	28 Pin	OFF	Removed	Disabled
03:09:44:9	27.27	3546	3.65	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	6.75	12.56	0.86	3.4	8.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:0	25.9	3572	3.66	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	6.87	12.54	0.85	3.4	8.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:0	25.9	3576	3.66	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	7.04	12.53	0.85	3.4	9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:0	25.9	3584	3.67	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.9	Rich	1	14.6	7.11	12.5	0.85	3.4	8.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:0	25.9	3592	3.68	13.55	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	7.21	12.48	0.85	3.4	9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:0	25.9	3626	3.69	13.55	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	7.4	12.45	0.85	3.4	9.1	ON	28 Pin	OFF	Removed	Disabled
03:09:45:0	25.9	3612	3.7	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	7.5	12.4	0.84	3.4	9.1	ON	28 Pin	OFF	Removed	Disabled
03:09:45:1	25.9	3599	3.7	13.55	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.53	12.36	0.84	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:09:45:1	25.9	3602	3.71	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.61	12.33	0.84	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:09:45:1	25.9	3622	3.72	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.77	12.29	0.84	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:09:45:1	25.9	3626	3.73	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.85	12.29	0.84	3.5	9.4	ON	28 Pin	OFF	Removed	Disabled
03:09:45:1	25.9	3642	3.74	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.05	12.29	0.84	3.5	9.4	ON	28 Pin	OFF	Removed	Disabled
03:09:45:1	25.9	3653	3.75	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.09	12.27	0.84	3.5	9.6	ON	28 Pin	OFF	Removed	Disabled
03:09:45:1	25.9	3658	3.75	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.19	12.28	0.84	3.5	9.6	ON	28 Pin	OFF	Removed	Disabled
03:09:45:2	25.9	3678	3.76	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.34	12.27	0.84	3.5	9.6	ON	28 Pin	OFF	Removed	Disabled
03:09:45:2	25.9	3687	3.77	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.37	12.25	0.83	3.4	9.6	ON	28 Pin	OFF	Removed	Disabled
03:09:45:2	25.9	3687	3.78	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.48	12.23	0.83	3.4	9.8	ON	28 Pin	OFF	Removed	Disabled
03:09:45:2	25.9	3722	3.79	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	8.46	12.21	0.83	3.4	9.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:2	24.54	3734	3.8	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	8.51	12.18	0.83	3.4	9.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:2	24.54	3737	3.81	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	8.59	12.14	0.83	3.4	9.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:3	24.54	3748	3.82	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	8.7	12.09	0.82	3.4	9.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:3	24.54	3753	3.83	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	8.9	12.05	0.82	3.4	10	ON	28 Pin	OFF	Removed	Disabled
03:09:45:3	24.54	3758	3.83	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	8.94	12	0.82	3.4	10	ON	28 Pin	OFF	Removed	Disabled
03:09:45:3	24.54	3786	3.84	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	8.93	11.98	0.82	3.4	10	ON	28 Pin	OFF	Removed	Disabled
03:09:45:3	25.9	3766	3.85	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.09	11.96	0.81	3.5	10.2	ON	28 Pin	OFF	Removed	Disabled
03:09:45:3	25.9	3762	3.86	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.09	11.95	0.81	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled
03:09:45:4	25.9	3765	3.86	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.08	11.94	0.81	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled
03:09:45:4	25.9	3798	3.87	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.31	11.91	0.81	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:09:45:4	25.9	3796	3.88	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.51	11.89	0.81	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:09:45:4	25.9	3814	3.89	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.61	11.88	0.81	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:09:45:4	25.9	3817	3.9	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.63	11.86	0.81	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:09:45:4	25.9	3824	3.9	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.68	11.83	0.81	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:09:45:4	24.54	3844	3.91	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.73	11.85	0.81	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:09:45:5	24.54	3844	3.92	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.77	11.84	0.81	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:09:45:5	24.54	3858	3.93	13.59	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.94	11.82	0.8	3.5	11	ON	28 Pin	OFF	Removed	Disabled
03:09:45:5	24.54	3870	3.94	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.21	11.81	0.8	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:09:45:5	24.54	3870	3.95	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.44	11.8	0.8	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:09:45:5	24.54	3882	3.96	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.59	11.78	0.8	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:09:45:5	24.54	3892	3.97	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	10.67	11.78	0.8	3.4	11.2	ON	28 Pin	OFF	Removed	Disabled
03:09:45:6	24.54	3896	3.98	13.52	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.69	11.78	0.8	3.4	11.4	ON	28 Pin	OFF	Removed	Disabled
03:09:45:6	24.54	3911	3.99	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.65	11.77	0.8	3.4	11.4	ON	28 Pin	OFF	Removed	Disabled
03:09:45:6	24.54	3944	3.99	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.72	11.75	0.8	3.4	11.6	ON	28 Pin	OFF	Removed	Disabled
03:09:45:6	24.54	3934	4	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	11.03	11.72	0.8	3.4	11.7	ON	28 Pin	OFF	Removed	Disabled
03:09:45:6	24.54	3936	4.02	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	11.06	11.72	0.8	3.4	11.7	ON	28 Pin	OFF	Removed	Disabled
03:09:45:6	24.54	3962	4.03	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	11.18	11.66	0.79	3.4	11.7	ON	28 Pin	OFF	Removed	Disabled
03:09:45:6	24.54	4033	4.04	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.11	11.61	0.79	3.4	11.8	ON	28 Pin	OFF	Removed	Disabled
03:09:45:7	24.54	4008	4.05	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.16	11.59	0.79	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:09:45:7	24.54	4000	4.06	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.13	11.52	0.78	3.5	12.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:45:7	24.54	4022	4.07	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.36	11.48	0.78	3.5	12.2	ON	28 Pin	OFF	Removed	Disabled
03:09:45:7	24.54	4020	4.09	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.44	11.4	0.78	3.5	12.2	ON	28 Pin	OFF	Removed	Disabled
03:09:45:7	24.54	4026	4.1	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.5	11.35	0.77	3.5	12.2	ON	28 Pin	OFF	Removed	Disabled
03:09:45:7	24.54	4026	4.1	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.51	11.32	0.77	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:09:45:8	24.54	4037	4.11	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.63	11.31	0.77	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:09:45:8	24.54	4049	4.13	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.73	11.24	0.77	3.5	12.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:8	23.18	4040	4.14	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.98	11.22	0.76	3.5	12.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:8	23.18	4053	4.14	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	12.15	11.21	0.76	3.5	12.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:8	23.18	4053	4.15	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	12.16	11.18	0.76	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:09:45:8	23.18	4064	4.16	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	12.01	11.13	0.76	3.5	12.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:9	23.18	4102	4.17	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.92	11.09	0.76	3.4	12.9	ON	28 Pin	OFF	Removed	Disabled
03:09:45:9	24.54	4106	4.17	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	11.77	11.05	0.75	3.5	13.1	ON	28 Pin	OFF	Removed	Disabled
03:09:45:9	24.54	4090	4.18	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.9	11.01	0.75	3.5	13.1	ON	28 Pin	OFF	Removed	Disabled
03:09:45:9	24.54	4102	4.19	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	12.09	10.95	0.75	3.5	13.1	ON	28 Pin	OFF	Removed	Disabled
03:09:45:9	24.54	4128	4.19	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	12.25	10.87	0.74	3.5	13.1	ON	28 Pin	OFF	Removed	Disabled
03:09:45:9	23.18	4148	4.2	13.52	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	12.21	10.8	0.74	3.4	13	ON	28 Pin	OFF	Removed	Disabled
03:09:45:9	23.18	4153	4.2	13.52	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	12.21	10.71	0.73	3.4	13.1	ON	28 Pin	OFF	Removed	Disabled
03:09:46:0	23.18	4150	4.21	13.52	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.21	10.64	0.72	3.4	13.1	ON	28 Pin	OFF	Removed	Disabled
03:09:46:0	23.18	4157	4.21	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.2	10.58	0.72	3.4	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:0	23.18	4162	4.22	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.07	10.57	0.72	3.4	13.2	ON	28 Pin	OFF	Removed	Disabled
03:09:46:0	23.18	4183	4.22	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.05	10.54	0.72	3.4	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:0	23.18	4190	4.22	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.14	10.51	0.72	3.4	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:0	23.18	4204	4.23	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.13	10.48	0.71	3.4	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:1	23.18	4204	4.23	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	12.14	10.46	0.71	3.4	13.2	ON	28 Pin	OFF	Removed	Disabled
03:09:46:1	23.18	4288	4.24	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	12.11	10.44	0.71	3.4	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:1	24.54	4260	4.24	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	12.14	10.46	0.71	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:09:46:1	24.54	4230	4.25	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	12.22	10.45	0.71	3.5	13.6	ON	28 Pin	OFF	Removed	Disabled
03:09:46:1	24.54	4241	4.25	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	12.25	10.43	0.71	3.5	13.5	ON	28 Pin	OFF	Removed	Disabled
03:09:46:1	24.54	4230	4.25	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	12.32	10.36	0.71	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:09:46:1	23.18	4248	4.26	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	12.27	10.34	0.7	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:2	23.18	4283	4.26	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	12.19	10.33	0.7	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:09:46:2	23.18	4281	4.26	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	12.25	10.32	0.7	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:2	23.18	4282	4.26	13.52	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	12.26	10.3	0.7	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:2	24.54	4320	4.27	13.49	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.93	Rich	1	14.6	12.5	10.29	0.7	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:2	24.54	4316	4.27	13.47	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	12.58	10.27	0.7	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:09:46:2	24.54	4316	4.27	13.46	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	12.6	10.27	0.7	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:09:46:3	24.54	4316	4.28	13.47	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.94	Rich	1	14.6	12.65	10.26	0.7	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:3	24.54	4322	4.28	13.47	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.94	Rich	1	14.6	12.66	10.28	0.7	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:09:46:3	23.18	4318	4.28	13.49	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.94	Rich	1	14.6	12.42	10.27	0.7	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:09:46:3	23.18	4321	4.29	13.49	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.94	Rich	1	14.6	12.44	10.26	0.7	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:3	23.18	4353	4.29	13.49	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	12.43	10.25	0.7	3.4	13.5	ON	28 Pin	OFF	Removed	Disabled
03:09:46:3	23.18	4394	4.29	13.49	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	12.42	10.27	0.7	3.4	13.5	ON	28 Pin	OFF	Removed	Disabled
03:09:46:4	24.54	4373	4.29	13.5	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	12.41	10.28	0.7	3.5	0.4	ON	28 Pin	OFF	Removed	Disabled
03:09:46:4	24.54	4380	4.29	13.49	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.94	Rich	1	14.6	12.53	10.27	0.7	3.5	0.4	ON	28 Pin	OFF	Removed	Disabled
03:09:46:4	24.54	4384	4.29	13.5	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.95	Rich	1	14.6	12.53	10.24	0.7	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:09:46:4	24.54	4406	4.29	13.52	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.94	Rich	1	14.6	12.51	10.2	0.7	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:09:46:4	24.54	4411	4.29	13.53	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.94	Rich	1	14.6	12.23	10.19	0.69	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:09:46:4	24.54	4414	4.29	13.55	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	11.99	10.21	0.7	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:09:46:4	24.54	4443	4.29	13.56	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	11.73	10.2	0.69	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:09:46:5	24.54	4456	4.28	13.52	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	11.59	10.19	0.69	3.5	12.7	ON	28 Pin	OFF	Removed	Disabled
03:09:46:5	24.54	4456	4.27	13.51	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	11.37	10.16	0.69	3.5	12.6	ON	28 Pin	OFF	Removed	Disabled
03:09:46:5	24.54	4456	4.27	13.51	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	11.18	10.15	0.69	3.5	12.6	ON	28 Pin	OFF	Removed	Disabled
03:09:46:5	24.54	4425	4.25	13.52	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.93	Rich	1	14.6	9.83	10.15	0.69	3.5	12	ON	28 Pin	OFF	Removed	Disabled
03:09:46:5	24.54	4427	4.23	13.54	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	8.56	10.17	0.69	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:09:46:5	25.9	4316	4.13	13.58	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	5.75	10.16	0.69	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:09:46:6	25.9	4242	4.03	13.59	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.93	Rich	1	14.6	3.84	10.16	0.69	3.6	7.5	ON	28 Pin	OFF	Removed	Disabled
03:09:46:6	25.9	4204	3.9	13.56	103	189	Off Idle	41.7	0	2	132	944 Turbo	0.93	Rich	1	14.6	1.75	10.15	0.69	3.7	5.7	ON	28 Pin	OFF	Removed	Disabled
03:09:46:6	35.45	3952	3.7	13.53	103	189	Full Load	41.7	0	2	132	944 Turbo	0.91	Rich	1	14.6	-0.2	10.14	0.69	3.7	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:46:6	35.45	4052	3.59	13.51	103	189	Idle	41.7	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.12	10.16	0.69	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:46:6	35.45	4044	3.39	13.5	103	189	Idle	41.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2.69	10.18	0.69	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:46:6	35.45	4034	3.19	13.52	103	189	Idle	41.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.95	10.18	0.69	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:46:6	35.45	3974	2.89	13.55	103	189	Idle	41.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.03	10.36	0.71	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:7	29.99	3974	2.68	13.57	103	189	Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-6.11	10.78	0.73	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:7	24.54	4021	2.48	13.6	103	189	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-6.59	11.16	0.76	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:7	20.45	4055	2.3	13.61	103	189	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-7.06	11.34	0.77	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:7	20.45	4016	2.04	13.59	103	189	Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-7.71	11.65	0.79	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:7	20.45	4016	1.78	13.61	103	189	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.13	11.89	0.81	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:7	20.45	3971	1.6	13.6	102	189	Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.39	11.98	0.82	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:8	20.45	3962	1.33	13.6	102	189	Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.56	12.08	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:8	20.45	3916	1.24	13.61	102	189	Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-8.79	12.16	0.83	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:8	20.45	3870	1.06	13.58	102	189	Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.9	12.17	0.83	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:8	20.45	3831	0.9	13.58	102	189	Idle	41.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.02	12.05	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:8	20.45	3799	0.74	13.57	102	189	Idle	40.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.13	11.66	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:8	20.45	3792	0.67	13.56	103	189	Idle	40.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.18	11.32	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:9	20.45	3732	0.65	13.58	103	189	Idle	39.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.27	11.02	0.75	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:9	20.45	3703	0.7	13.6	103	189	Idle	39.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.31	10.78	0.73	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:9	20.45	3698	0.73	13.6	102	189	Idle	38.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.29	10.77	0.73	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:9	20.45	3637	0.83	13.61	102	189	Idle	36.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.35	10.8	0.74	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:9	20.45	3618	0.89	13.59	102	189	Idle	34.9	0	2	132	944 Turbo	0.16	Rich	1	14.6	-9.27	11	0.75	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:9	20.45	3595	0.96	13.6	102	188	Idle	33.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.27	11.31	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:46:9	20.45	3574	1.03	13.6	102	188	Idle	32	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.25	11.68	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:0	20.45	3548	1.13	13.59	102	189	Idle	30.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.15	12.72	0.87	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:0	20.45	3532	1.18	13.59	102	189	Idle	27.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.13	13.65	0.93	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:0	20.45	3436	1.26	13.6	102	189	Full Load	26.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	15.09	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:0	20.45	3448	1.31	13.58	103	189	Off Idle	25	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	16.04	1.09	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:0	20.45	3248	1.36	13.59	103	189	Off Idle	23.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.92	16.93	1.15	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:0	12.27	3317	1.47	13.59	103	189	Off Idle	22.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.68	17.76	1.21	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:1	14.99	3395	1.59	13.59	102	188	Off Idle	23.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.36	18.48	1.26	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:47:1	17.72	3373	1.67	13.6	102	188	Off Idle	24	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.21	19.13	1.3	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:47:1	20.45	3330	1.74	13.6	103	188	Off Idle	25.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.65	19.96	1.36	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:1	23.18	3274	1.84	13.59	103	189	Off Idle	27	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.21	20.2	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:1	23.18	3252	1.91	13.59	103	189	Off Idle	28.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.75	20.22	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:1	25.9	3252	2.01	13.59	103	189	Off Idle	31.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.95	20.23	1.38	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:1	28.63	3170	2.08	13.59	103	189	Off Idle	32.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.45	20.23	1.38	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:2	31.36	3092	2.18	13.57	103	189	Off Idle	34.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-4.95	20.24	1.38	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:2	34.08	2967	2.29	13.57	103	189	Off Idle	37.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-4.39	20.24	1.38	3.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:47:2	34.08	2983	2.33	13.57	103	189	Off Idle	37.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-4.12	20.24	1.38	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:2	35.45	2974	2.4	13.57	103	189	Off Idle	40.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-3.29	20.23	1.38	3.7	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:47:2	35.45	2959	2.49	13.57	103	189	Off Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-2.69	20.24	1.38	3.7	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:47:2	35.45	2963	2.58	13.58	103	188	Off Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-2.25	20.25	1.38	3.7	5.3	ON	28 Pin	OFF	Removed	Disabled
03:09:47:3	32.72	2946	2.66	13.58	103	188	Off Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-1.98	20.25	1.38	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:47:3	32.72	3020	2.74	13.58	103	188	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-1.92	20.24	1.38	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:47:3	32.72	3052	2.81	13.58	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-1.83	20.23	1.38	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:47:3	32.72	3060	2.85	13.58	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-1.73	20.22	1.38	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:47:3	34.08	3072	2.9	13.56	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-1.59	20.03	1.36	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:47:3	34.08	3044	2.93	13.55	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-1.41	19.67	1.34	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:47:4	34.08	3029	2.95	13.55	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-1.29	19.32	1.32	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:4	34.08	3023	2.97	13.55	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-1.23	18.88	1.29	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:4	34.08	2996	2.98	13.56	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-1.21	18.21	1.24	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:4	32.72	3000	2.98	13.59	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.12	17.69	1.21	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:4	32.72	3000	2.99	13.6	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.1	17.41	1.19	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:4	32.72	3007	3	13.6	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.02	16.55	1.13	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:4	32.72	3021	2.99	13.6	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.99	16.27	1.11	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:5	32.72	3024	2.99	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.92	15.58	1.06	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:5	32.72	3040	2.99	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.86	15.37	1.05	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:5	32.72	3054	2.99	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.84	15.02	1.02	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:47:5	32.72	3059	2.99	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.81	14.76	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:5	32.72	3059	3.01	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.81	14.58	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:5	32.72	3052	3.01	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.74	14.39	0.98	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:6	32.72	3043	3.02	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.82	14.26	0.97	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:6	32.72	3043	3.02	13.57	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.77	14.21	0.97	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:6	32.72	3037	3.02	13.58	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.78	14.1	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:6	32.72	3034	3.02	13.56	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.66	14.04	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:6	32.72	3043	3.02	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.68	13.98	0.95	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:6	32.72	3046	3.02	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.6	13.92	0.95	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:6	32.72	3055	3.03	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.65	13.87	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:7	32.72	3069	3.03	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.62	13.83	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:7	32.72	3069	3.03	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.66	13.79	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:7	32.72	3074	3.03	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.59	13.74	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:7	32.72	3076	3.03	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.64	13.73	0.93	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:7	32.72	3073	3.04	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.54	13.71	0.93	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:7	32.72	3073	3.04	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.6	13.7	0.93	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:8	32.72	3067	3.04	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.5	13.7	0.93	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:8	32.72	3067	3.05	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.49	13.71	0.93	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:8	32.72	3070	3.05	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.43	13.73	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:8	32.72	3076	3.05	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.44	13.76	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:8	32.72	3096	3.05	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.43	13.79	0.94	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:8	32.72	3090	3.05	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.43	13.82	0.94	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:47:9	32.72	3093	3.06	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.41	13.85	0.94	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:9	32.72	3118	3.06	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.49	13.88	0.95	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:9	32.72	3106	3.06	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.38	13.91	0.95	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:9	32.72	3096	3.06	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.39	13.93	0.95	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:9	32.72	3092	3.07	13.55	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.34	13.96	0.95	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:9	32.72	3092	3.07	13.56	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.37	13.98	0.95	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:47:9	32.72	3100	3.07	13.56	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.26	14.01	0.95	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:0	32.72	3105	3.08	13.57	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.28	14.03	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:0	32.72	3112	3.08	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.21	14.04	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:0	32.72	3112	3.08	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.28	14.06	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:0	32.72	3116	3.08	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.19	14.06	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:0	32.72	3118	3.08	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.25	14.08	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:0	32.72	3120	3.09	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.23	14.08	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:1	32.72	3119	3.09	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.19	14.09	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:1	32.72	3117	3.09	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.11	14.12	0.96	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:1	32.72	3118	3.09	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.16	14.15	0.96	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:1	32.72	3120	3.09	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.15	14.17	0.96	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:1	32.72	3118	3.09	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.07	14.19	0.97	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:1	32.72	3106	3.1	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.19	14.19	0.97	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:1	31.36	3126	3.1	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.16	14.22	0.97	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:2	31.36	3130	3.1	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.16	14.27	0.97	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:2	31.36	3137	3.1	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.2	14.29	0.97	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:2	31.36	3140	3.1	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.2	14.28	0.97	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:2	31.36	3150	3.1	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.17	14.29	0.97	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:2	32.72	3148	3.1	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.14	14.29	0.97	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:2	32.72	3154	3.11	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.11	14.3	0.97	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:3	32.72	3152	3.11	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.05	14.32	0.98	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:3	32.72	3152	3.11	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.03	14.34	0.98	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:3	32.72	3152	3.11	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.06	14.35	0.98	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:3	32.72	3152	3.12	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.09	14.39	0.98	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:3	32.72	3152	3.12	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.1	14.42	0.98	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:3	32.72	3152	3.12	13.58	102	188	Off Idle	41.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.07	14.43	0.98	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:4	31.36	3144	3.12	13.59	102	188	Off Idle	41.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.12	14.46	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:4	31.36	3162	3.12	13.6	102	188	Off Idle	41.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.09	14.47	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:4	31.36	3162	3.12	13.59	102	188	Off Idle	41.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.13	14.48	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:4	31.36	3170	3.13	13.6	102	188	Off Idle	41.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.07	14.5	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:48:4	31.36	3193	3.13	13.58	102	188	Off Idle	41.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.08	14.51	0.99	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:4	31.36	3164	3.13	13.57	102	188	Off Idle	41.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.07	14.54	0.99	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:4	31.36	3164	3.13	13.57	102	188	Off Idle	41.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.03	14.55	0.99	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:5	32.72	3157	3.13	13.57	102	188	Off Idle	41.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	0.04	14.57	0.99	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:5	32.72	3166	3.13	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	0.08	14.59	0.99	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:5	32.72	3177	3.14	13.55	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	0.06	14.62	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:5	32.72	3185	3.14	13.55	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	0.14	14.63	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:5	32.72	3185	3.14	13.55	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	0.15	14.66	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:5	31.36	3198	3.14	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	0.22	14.69	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:6	31.36	3183	3.14	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.25	14.72	1	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:6	31.36	3182	3.14	13.61	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.2	14.74	1	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:6	31.36	3182	3.14	13.61	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.27	14.74	1	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:6	31.36	3187	3.14	13.6	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.24	14.75	1	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:6	31.36	3188	3.14	13.6	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.29	14.75	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:6	31.36	3190	3.14	13.59	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.33	14.78	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:48:6	31.36	3197	3.14	13.59	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.36	14.79	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:48:7	32.72	3197	3.14	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.36	14.8	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:48:7	32.72	3210	3.14	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	0.28	14.83	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:48:7	32.72	3213	3.14	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	0.3	14.83	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:48:7	32.72	3218	3.14	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	0.22	14.82	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:7	32.72	3218	3.15	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	0.17	14.84	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:7	32.72	3208	3.15	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	0.21	14.86	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:48:8	32.72	3222	3.15	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	0.19	14.89	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:48:8	32.72	3217	3.15	13.57	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	0.24	14.93	1.02	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:48:8	32.72	3195	3.15	13.56	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	0.27	14.99	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:48:8	31.36	3195	3.15	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	0.28	15.03	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:48:8	31.36	3212	3.16	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	0.33	15.12	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:8	31.36	3212	3.16	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	0.34	15.19	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:9	31.36	3212	3.16	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	0.34	15.2	1.04	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:9	31.36	3228	3.16	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	0.33	15.18	1.03	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:9	31.36	3214	3.16	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.31	15.13	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:9	31.36	3220	3.16	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.32	15.06	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:9	31.36	3225	3.16	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.3	14.99	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:48:9	31.36	3238	3.16	13.57	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.3	14.94	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:09:48:9	32.72	3197	3.17	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.31	14.9	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:0	32.72	3206	3.17	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.36	14.78	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:0	32.72	3243	3.17	13.57	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.43	14.74	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:0	32.72	3248	3.17	13.58	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.43	14.73	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:0	32.72	3270	3.17	13.6	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.47	14.74	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:0	32.72	3266	3.17	13.6	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.53	14.74	1	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:0	32.72	3261	3.17	13.6	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.49	14.8	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:49:1	32.72	3258	3.17	13.6	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	0.53	14.82	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:49:1	32.72	3253	3.17	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	0.41	14.87	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:49:1	32.72	3255	3.17	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	0.45	14.87	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:49:1	32.72	3253	3.17	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	0.44	14.87	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:09:49:1	32.72	3252	3.18	13.61	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	0.51	14.84	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:1	31.36	3252	3.18	13.61	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	0.49	14.84	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:1	31.36	3254	3.18	13.6	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	0.44	14.86	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:2	31.36	3260	3.18	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	0.5	14.88	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:2	31.36	3270	3.18	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.22	Rich	1	14.6	0.4	14.9	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:2	32.72	3269	3.18	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	0.42	14.93	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:2	32.72	3283	3.18	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	0.34	14.95	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:2	32.72	3284	3.18	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	0.41	15.06	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:2	32.72	3285	3.18	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	0.32	15.11	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:3	31.36	3300	3.18	13.55	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	0.34	15.13	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:3	31.36	3271	3.17	13.54	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	0.38	15.11	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:49:3	31.36	3270	3.17	13.55	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.37	15.08	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:49:3	31.36	3271	3.17	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.24	15.03	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:49:3	32.72	3268	3.16	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.21	14.98	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:09:49:3	32.72	3271	3.16	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.02	14.93	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:49:4	32.72	3281	3.16	13.55	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.01	14.82	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:49:4	32.72	3281	3.16	13.55	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.03	14.79	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:49:4	32.72	3293	3.15	13.55	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.16	14.78	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:49:4	32.72	3322	3.14	13.56	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.14	14.78	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:4	32.72	3287	3.14	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.28	14.8	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:4	32.72	3285	3.13	13.56	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.33	14.81	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:4	32.72	3283	3.13	13.56	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-0.37	14.81	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:5	32.72	3286	3.12	13.57	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-0.56	14.83	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:5	32.72	3292	3.11	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-0.61	14.81	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:09:49:5	32.72	3292	3.1	13.56	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-0.66	14.81	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:09:49:5	32.72	3300	3.1	13.56	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-0.65	14.83	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:49:5	34.08	3308	3.09	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-0.7	14.87	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:5	34.08	3310	3.09	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-0.78	14.91	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:6	34.08	3310	3.08	13.59	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-0.84	14.95	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:6	34.08	3313	3.07	13.58	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.88	15.01	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:6	34.08	3314	3.07	13.57	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-0.99	15.03	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:6	34.08	3314	3.06	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-1.1	15.06	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:6	34.08	3312	3.05	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-1.2	15.1	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:6	34.08	3310	3.05	13.6	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.22	Rich	1	14.6	-1.31	15.14	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:6	34.08	3310	3.04	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-1.33	15.16	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:7	34.08	3316	3.03	13.61	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-1.42	15.14	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:7	34.08	3317	3.02	13.61	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-1.46	15.09	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:7	34.08	3348	3.01	13.6	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-1.46	15.07	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:09:49:7	34.08	3327	3	13.6	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-1.54	15.05	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:49:7	34.08	3327	3	13.6	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-1.64	15.03	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:49:7	34.08	3336	2.99	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-1.64	15.01	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:8	34.08	3344	2.99	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-1.74	14.98	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:09:49:8	34.08	3346	2.98	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.83	14.96	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:8	34.08	3346	2.97	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-1.88	14.95	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:8	34.08	3337	2.96	13.55	102	188	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-2.02	15	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:49:8	34.08	3326	2.95	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.25	15.03	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:09:49:8	34.08	3326	2.94	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.31	15.02	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:9	34.08	3322	2.93	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.4	14.94	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:9	34.08	3322	2.93	13.57	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.41	14.87	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:9	34.08	3328	2.92	13.58	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.48	14.76	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:09:49:9	34.08	3333	2.91	13.57	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.55	14.68	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:9	34.08	3333	2.9	13.58	102	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.68	14.54	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:09:49:9	34.08	3338	2.89	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.69	14.41	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:49:9	34.08	3342	2.89	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.74	14.19	0.97	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:50:0	34.08	3348	2.88	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.79	14.12	0.96	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:09:50:0	34.08	3351	2.87	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.86	14.04	0.96	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:50:0	34.08	3351	2.87	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.99	14.01	0.95	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:50:0	34.08	3373	2.86	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.15	14.01	0.95	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:50:0	34.08	3342	2.85	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.21	14.01	0.95	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:09:50:0	34.08	3342	2.84	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.29	14.04	0.96	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:50:1	34.08	3341	2.84	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.34	14.04	0.96	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:09:50:1	34.08	3342	2.84	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.36	14.05	0.96	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:50:1	34.08	3346	2.83	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.4	14.07	0.96	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:50:1	34.08	3351	2.82	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.45	14.08	0.96	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:50:1	34.08	3351	2.82	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.53	14.11	0.96	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:50:1	35.45	3366	2.81	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.55	14.14	0.96	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:50:1	35.45	3364	2.81	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.66	14.16	0.96	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:09:50:2	35.45	3366	2.8	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.69	14.19	0.97	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:50:2	35.45	3366	2.79	13.6	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.72	14.2	0.97	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:50:2	35.45	3379	2.79	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.87	14.21	0.97	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:09:50:2	35.45	3360	2.78	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.91	14.24	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:50:2	35.45	3364	2.78	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.04	14.27	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:50:2	35.45	3362	2.78	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.05	14.28	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:50:3	35.45	3342	2.77	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.07	14.29	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:09:50:3	35.45	3353	2.77	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.05	14.29	0.97	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:3	35.45	3354	2.76	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.16	14.31	0.97	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:3	35.45	3362	2.76	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.19	14.31	0.97	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:3	35.45	3362	2.75	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.29	14.33	0.98	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:3	35.45	3394	2.75	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.36	14.36	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:4	35.45	3369	2.75	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.37	14.38	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:4	35.45	3367	2.74	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.41	14.4	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:4	35.45	3363	2.74	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.39	14.42	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:4	35.45	3365	2.73	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.41	14.44	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:4	35.45	3365	2.73	13.56	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.41	14.44	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:4	35.45	3360	2.73	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.43	14.45	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:4	35.45	3336	2.72	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.44	14.48	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:5	35.45	3350	2.72	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.45	14.5	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:09:50:5	35.45	3366	2.72	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.52	14.51	0.99	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:5	35.45	3374	2.71	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.58	14.54	0.99	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:5	35.45	3390	2.71	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.56	14.57	0.99	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:5	35.45	3390	2.71	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.55	14.6	0.99	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:5	35.45	3382	2.71	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.56	14.64	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:6	35.45	3384	2.7	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.65	14.66	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:6	35.45	3372	2.7	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.68	14.69	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:6	35.45	3370	2.7	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.74	14.69	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:6	35.45	3372	2.7	13.6	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.75	14.71	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:6	35.45	3372	2.7	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.75	14.72	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:6	35.45	3366	2.7	13.57	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.73	14.73	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:6	35.45	3354	2.7	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.78	14.73	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:7	35.45	3370	2.7	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.77	14.73	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:7	35.45	3376	2.69	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.8	14.74	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:7	35.45	3385	2.69	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.79	14.75	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:7	35.45	3389	2.69	13.59	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.84	14.76	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:7	35.45	3392	2.69	13.58	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.82	14.79	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:7	35.45	3388	2.69	13.56	102	188	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.89	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:8	35.45	3384	2.69	13.55	101	189	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.84	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:8	35.45	3382	2.69	13.56	101	189	Off Idle	41.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.84	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:8	35.45	3374	2.69	13.55	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.9	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:8	35.45	3378	2.69	13.57	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.92	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:8	35.45	3387	2.69	13.57	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.95	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:8	35.45	3389	2.68	13.58	101	189	Off Idle	41.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.97	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:9	35.45	3387	2.68	13.59	101	189	Off Idle	41.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.95	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:9	35.45	3393	2.68	13.6	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.97	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:50:9	35.45	3386	2.68	13.59	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.97	14.9	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:9	35.45	3380	2.68	13.58	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.01	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:9	35.45	3376	2.68	13.57	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.01	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:50:9	35.45	3375	2.68	13.58	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.61	Lean	1	14.6	-4.98	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:50:9	35.45	3367	2.68	13.58	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.67	Lean	1	14.6	-5.01	15.06	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:0	35.45	3363	2.68	13.59	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.98	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:51:0	35.45	3363	2.68	13.59	101	188	Off Idle	41.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:51:0	35.45	3368	2.68	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.04	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:0	35.45	3384	2.68	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.01	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:0	35.45	3390	2.67	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.06	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:0	35.45	3396	2.67	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.06	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:1	35.45	3396	2.67	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.06	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:51:1	35.45	3394	2.67	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.06	14.75	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:51:1	35.45	3400	2.67	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.05	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:51:1	35.45	3400	2.67	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.09	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:51:1	35.45	3402	2.67	13.61	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.11	14.75	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:51:1	35.45	3402	2.67	13.61	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.14	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:51:1	35.45	3402	2.67	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.15	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:51:2	35.45	3397	2.67	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.19	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:09:51:2	35.45	3395	2.66	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.14	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:2	35.45	3392	2.66	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.18	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:2	35.45	3413	2.66	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.13	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:2	35.45	3392	2.66	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.16	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:2	35.45	3390	2.66	13.61	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.17	15.1	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:3	35.45	3384	2.66	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.16	15.1	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:3	35.45	3384	2.66	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.2	15.08	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:3	35.45	3390	2.66	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.23	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:3	35.45	3396	2.66	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.27	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:3	35.45	3394	2.66	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.24	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:3	35.45	3392	2.66	13.56	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.24	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:09:51:4	35.45	3390	2.66	13.54	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.26	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:51:4	35.45	3386	2.66	13.55	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.27	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:51:4	35.45	3384	2.66	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.31	14.75	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:51:4	35.45	3375	2.65	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.38	14.77	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:51:4	35.45	3375	2.65	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.38	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:51:4	35.45	3384	2.65	13.56	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.41	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:09:51:4	35.45	3416	2.64	13.55	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.43	14.79	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:5	36.81	3402	2.64	13.54	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.47	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:5	36.81	3402	2.63	13.55	101	188	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.54	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:5	36.81	3409	2.63	13.54	101	188	Off Idle	41.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.6	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:09:51:5	36.81	3410	2.62	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.6	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:51:5	35.45	3413	2.62	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.66	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:51:5	35.45	3412	2.61	13.62	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.7	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:09:51:6	35.45	3404	2.6	13.62	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.71	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:09:51:6	35.45	3394	2.59	13.62	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.81	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:51:6	35.45	3417	2.59	13.61	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.91	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:51:6	36.81	3386	2.58	13.61	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.89	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:6	36.81	3386	2.57	13.62	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.93	15.05	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:6	36.81	3391	2.56	13.63	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.94	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:51:6	36.81	3389	2.55	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.08	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:51:7	36.81	3400	2.54	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.17	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:7	36.81	3407	2.54	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.15	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:7	36.81	3409	2.53	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.17	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:7	36.81	3414	2.53	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.18	Rich	1	14.6	-6.23	14.71	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:51:7	36.81	3410	2.53	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.27	14.71	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:7	36.81	3405	2.52	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.38	14.73	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:8	36.81	3398	2.51	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.42	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:8	36.81	3396	2.51	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.4	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:8	36.81	3381	2.5	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.38	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:8	36.81	3381	2.5	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.37	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:8	36.81	3380	2.49	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.37	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:8	36.81	3388	2.49	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.39	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:9	36.81	3390	2.49	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.41	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:9	36.81	3397	2.48	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.47	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:9	36.81	3401	2.48	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.47	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:9	36.81	3404	2.47	13.61	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.48	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:51:9	36.81	3404	2.47	13.62	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.47	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:51:9	36.81	3401	2.47	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.49	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:51:9	36.81	3400	2.47	13.57	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.52	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:0	36.81	3398	2.47	13.56	101	189	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.53	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:0	36.81	3403	2.47	13.57	101	189	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.57	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:09:52:0	36.81	3399	2.46	13.57	101	189	Off Idle	41.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.55	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:52:0	36.81	3402	2.46	13.61	101	189	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.64	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:09:52:0	36.81	3400	2.45	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.75	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:52:0	36.81	3394	2.43	13.59	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.94	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:09:52:1	36.81	3393	2.42	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.04	14.9	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:09:52:1	36.81	3386	2.39	13.6	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.25	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:09:52:1	36.81	3380	2.39	13.58	101	188	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.35	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:09:52:1	36.81	3376	2.37	13.58	101	188	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.48	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:09:52:1	36.81	3376	2.33	13.57	101	188	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:09:52:1	36.81	3376	2.3	13.56	101	188	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.08	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:09:52:1	38.18	3379	2.24	13.6	101	188	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.38	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:09:52:2	38.18	3375	2.21	13.61	101	188	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.52	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:2	38.18	3374	2.19	13.6	101	188	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.8	14.95	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:52:2	38.18	3373	2.13	13.59	101	188	Full Load	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.07	14.87	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:52:2	38.18	3372	2.11	13.57	101	188	Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.27	14.86	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:52:2	38.18	3357	2.05	13.57	101	188	Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.4	14.85	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:52:2	38.18	3317	2	13.59	101	188	Idle	40.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.44	14.86	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:52:3	38.18	3325	1.95	13.61	101	188	Idle	36.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.63	14.84	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:52:3	38.18	3309	1.91	13.61	101	188	Idle	35.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.67	14.84	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:09:52:3	38.18	3306	1.86	13.58	101	188	Idle	31.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.71	14.84	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:52:3	32.72	3255	1.83	13.55	101	188	Idle	28.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.69	14.84	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:52:3	27.27	3266	1.8	13.55	101	188	Idle	26.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.65	14.84	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:09:52:3	21.81	3270	1.79	13.55	101	188	Idle	23.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.6	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:4	20.45	3309	1.78	13.56	101	188	Idle	20.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.58	14.8	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:4	20.45	3386	1.78	13.58	101	189	Idle	19.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.6	14.78	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:4	20.45	3396	1.78	13.61	101	189	Idle	18.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.59	14.75	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:4	20.45	3399	1.8	13.62	101	189	Idle	21.5	0	2	132	944 Turbo	0.17	Rich	1	14.6	-9.58	14.72	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:4	20.45	3391	1.8	13.61	101	189	Idle	24.9	0	2	132	944 Turbo	0.11	Rich	1	14.6	-9.61	14.7	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:4	20.45	3386	1.81	13.59	101	189	Idle	26.5	0	2	132	944 Turbo	0.08	Rich	1	14.6	-9.61	14.69	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:4	20.45	3372	1.82	13.57	101	188	Idle	28.2	0	2	132	944 Turbo	0.07	Rich	1	14.6	-9.64	14.7	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:5	20.45	3350	1.82	13.58	101	188	Idle	29.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.65	14.7	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:5	20.45	3330	1.82	13.58	101	188	Idle	31.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.66	14.69	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:5	20.45	3305	1.81	13.6	101	189	Idle	34.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.68	14.7	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:5	20.45	3307	1.8	13.59	101	189	Idle	36.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.68	14.76	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:5	20.45	3306	1.79	13.6	101	189	Idle	39.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:5	20.45	3300	1.78	13.59	101	189	Idle	40.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.67	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:6	20.45	3300	1.76	13.6	101	189	Idle	41.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.68	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:6	20.45	3315	1.76	13.61	101	189	Idle	40.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.72	15.16	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:6	20.45	3332	1.75	13.6	101	189	Idle	40.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.74	15.36	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:6	20.45	3361	1.74	13.61	101	188	Idle	39.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.75	15.43	1.05	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:6	20.45	3366	1.73	13.6	101	188	Idle	39.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.73	15.55	1.06	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:6	20.45	3377	1.73	13.61	101	188	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	15.77	1.07	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:6	20.45	3380	1.72	13.61	101	188	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	15.96	1.09	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:7	20.45	3369	1.72	13.61	101	188	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	16.2	1.1	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:7	20.45	3353	1.72	13.61	101	188	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	16.73	1.14	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:7	20.45	3348	1.72	13.6	101	189	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	17.17	1.17	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:7	20.45	3296	1.72	13.61	101	189	Idle	39.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	17.82	1.21	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:7	20.45	3308	1.72	13.6	101	189	Idle	40	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	18.25	1.24	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:7	20.45	3291	1.72	13.6	101	188	Idle	40.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	18.64	1.27	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:8	20.45	3288	1.72	13.61	101	188	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	19.21	1.31	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:8	20.45	3270	1.72	13.61	101	188	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	19.56	1.33	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:8	20.45	3266	1.72	13.6	101	188	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	19.96	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:8	20.45	3244	1.72	13.61	101	188	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.17	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:8	20.45	3258	1.72	13.6	101	188	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:8	20.45	3288	1.72	13.58	101	188	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:9	20.45	3310	1.72	13.59	101	188	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:9	20.45	3314	1.72	13.58	101	188	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:9	20.45	3338	1.72	13.56	101	188	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:9	20.45	3330	1.72	13.56	101	188	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:9	20.45	3327	1.72	13.56	101	188	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:52:9	20.45	3326	1.72	13.56	101	188	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:52:9	20.45	3322	1.71	13.56	101	189	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:0	20.45	3312	1.71	13.59	101	189	Idle	40.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:0	20.45	3304	1.71	13.6	101	189	Idle	40.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:0	20.45	3298	1.71	13.61	101	189	Idle	40.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:0	20.45	3296	1.71	13.62	101	189	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:0	20.45	3283	1.71	13.61	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:0	20.45	3280	1.71	13.62	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:1	20.45	3274	1.71	13.63	101	188	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:1	20.45	3272	1.71	13.61	101	188	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:1	20.45	3257	1.71	13.61	101	188	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:1	20.45	3271	1.71	13.6	101	188	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:1	20.45	3270	1.71	13.59	101	188	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:1	20.45	3270	1.71	13.6	101	188	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:1	20.45	3276	1.71	13.6	101	189	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:2	20.45	3302	1.71	13.61	101	189	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:2	20.45	3275	1.71	13.61	101	189	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:2	20.45	3275	1.71	13.62	101	189	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:2	20.45	3276	1.71	13.6	101	189	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:2	20.45	3270	1.71	13.6	101	189	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:2	20.45	3265	1.71	13.58	101	189	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:3	20.45	3250	1.71	13.58	101	189	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:3	20.45	3253	1.71	13.57	101	189	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:3	20.45	3242	1.71	13.59	101	189	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:3	20.45	3239	1.71	13.58	101	189	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:3	20.45	3238	1.71	13.6	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:3	20.45	3224	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:4	20.45	3241	1.71	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:4	20.45	3248	1.71	13.61	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:4	20.45	3262	1.71	13.61	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:4	20.45	3258	1.71	13.62	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:4	20.45	3264	1.71	13.61	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:4	20.45	3267	1.71	13.62	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:4	20.45	3266	1.71	13.61	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:5	20.45	3263	1.71	13.61	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:5	20.45	3257	1.7	13.6	101	188	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:5	20.45	3257	1.7	13.6	101	188	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:5	20.45	3248	1.7	13.61	101	188	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:5	20.45	3237	1.7	13.61	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:5	20.45	3224	1.7	13.62	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:6	20.45	3224	1.7	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:6	20.45	3218	1.7	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:6	20.45	3188	1.7	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:6	20.45	3200	1.7	13.59	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:6	20.45	3208	1.7	13.59	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:6	20.45	3208	1.71	13.59	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:6	20.45	3208	1.71	13.59	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:7	20.45	3208	1.71	13.6	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:7	20.45	3213	1.71	13.61	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:7	20.45	3217	1.71	13.6	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:7	20.45	3217	1.71	13.62	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:7	20.45	3214	1.71	13.61	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:7	20.45	3215	1.71	13.61	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:8	20.45	3210	1.71	13.62	101	189	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:8	20.45	3208	1.71	13.61	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:8	20.45	3204	1.71	13.61	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:8	20.45	3198	1.71	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:8	20.45	3198	1.71	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:8	20.45	3194	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:53:9	20.45	3194	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:9	20.45	3193	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:9	20.45	3193	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:9	20.45	3194	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:9	20.45	3194	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:9	20.45	3195	1.71	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:53:9	20.45	3197	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:0	20.45	3194	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:0	20.45	3190	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:0	20.45	3184	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:0	20.45	3182	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:0	20.45	3176	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:0	20.45	3166	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:1	20.45	3166	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:1	20.45	3159	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:1	20.45	3152	1.7	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:1	20.45	3151	1.7	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:1	20.45	3152	1.7	13.61	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:1	20.45	3128	1.7	13.6	101	189	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:1	20.45	3157	1.7	13.6	101	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:2	20.45	3157	1.7	13.6	101	189	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:2	20.45	3167	1.7	13.6	101	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:2	20.45	3169	1.7	13.6	101	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:2	20.45	3172	1.7	13.6	101	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:2	20.45	3172	1.7	13.6	101	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:2	20.45	3170	1.7	13.59	101	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:3	20.45	3165	1.7	13.6	101	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:3	20.45	3160	1.7	13.59	101	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:3	20.45	3158	1.7	13.58	101	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:3	20.45	3150	1.7	13.59	101	189	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:3	20.45	3136	1.7	13.59	101	189	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:3	20.45	3146	1.7	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:4	20.45	3130	1.7	13.61	101	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:4	20.45	3130	1.7	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:4	20.45	3131	1.7	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:4	20.45	3132	1.7	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:4	20.45	3138	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:4	20.45	3138	1.71	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:4	20.45	3142	1.71	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:5	20.45	3145	1.71	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:5	20.45	3144	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:5	20.45	3132	1.71	13.6	101	189	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:5	20.45	3123	1.71	13.62	101	189	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:5	20.45	3123	1.71	13.62	101	189	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:5	20.45	3108	1.71	13.6	101	189	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:6	20.45	3097	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:6	20.45	3096	1.71	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:6	20.45	3092	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:6	20.45	3091	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:6	20.45	3092	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:6	19.09	3080	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:6	19.09	3080	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:7	19.09	3113	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:7	19.09	3122	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:7	19.09	3122	1.71	13.59	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:7	19.09	3125	1.71	13.59	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:7	19.09	3122	1.71	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:7	19.09	3119	1.71	13.59	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:54:8	19.09	3118	1.71	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:8	19.09	3108	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:8	19.09	3098	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:8	19.09	3112	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:8	20.45	3112	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:8	19.09	3076	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:9	19.09	3066	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:9	19.09	3066	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:9	19.09	3073	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:9	19.09	3076	1.71	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:9	19.09	3077	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:9	19.09	3077	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:54:9	19.09	3076	1.71	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:0	19.09	3074	1.71	13.62	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:0	19.09	3072	1.71	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:0	19.09	3056	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:0	19.09	3062	1.71	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:0	19.09	3062	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:0	19.09	3060	1.71	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:1	19.09	3060	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:1	19.09	3065	1.71	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:1	19.09	3066	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:1	19.09	3074	1.71	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:1	19.09	3076	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:1	19.09	3076	1.7	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:1	19.09	3076	1.7	13.62	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:2	19.09	3071	1.7	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:2	19.09	3063	1.7	13.61	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:2	19.09	3062	1.7	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:2	19.09	3054	1.7	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:2	19.09	3048	1.7	13.59	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:2	19.09	3046	1.7	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:3	19.09	3038	1.71	13.59	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:3	19.09	3030	1.71	13.6	101	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:3	19.09	3028	1.71	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:3	19.09	3028	1.71	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:3	19.09	3028	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:3	19.09	3029	1.71	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:4	19.09	3029	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:4	19.09	3032	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:4	19.09	3034	1.71	13.62	100	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:4	19.09	3032	1.71	13.62	100	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:4	19.09	3032	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:4	19.09	3032	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:4	19.09	3029	1.71	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:5	19.09	3050	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:5	19.09	3036	1.71	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:5	19.09	3016	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:5	19.09	3016	1.71	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:5	19.09	3010	1.71	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:5	19.09	3006	1.71	13.61	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:6	19.09	3007	1.71	13.61	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:6	19.09	3002	1.71	13.62	100	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:6	19.09	2998	1.71	13.61	100	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:6	19.09	2998	1.71	13.62	100	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:6	19.09	2994	1.71	13.61	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:6	19.09	2995	1.71	13.6	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:6	19.09	2996	1.71	13.6	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:55:7	19.09	2996	1.71	13.6	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:7	19.09	2995	1.71	13.59	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:7	19.09	2995	1.71	13.6	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:7	19.09	2996	1.71	13.59	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:7	19.09	2992	1.71	13.6	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:7	19.09	2991	1.71	13.6	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:8	19.09	2981	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:8	19.09	2981	1.71	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:8	19.09	2987	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:8	19.09	2987	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:8	19.09	2988	1.71	13.62	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:8	19.09	2987	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:9	19.09	2988	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:9	19.09	2987	1.7	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:9	19.09	2987	1.7	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:9	19.09	2986	1.7	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:9	19.09	2987	1.7	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:9	19.09	2986	1.7	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:55:9	19.09	2984	1.7	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:0	19.09	2979	1.7	13.62	100	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:0	19.09	2977	1.7	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:0	19.09	2971	1.7	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:0	19.09	2964	1.7	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:0	19.09	2964	1.7	13.6	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:0	19.09	2962	1.7	13.59	101	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:1	19.09	2962	1.7	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:1	19.09	2949	1.7	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:1	19.09	2960	1.7	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:1	19.09	2979	1.71	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:1	19.09	2969	1.71	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:1	19.09	2936	1.71	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:1	19.09	2954	1.71	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:2	19.09	2954	1.71	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:2	19.09	2952	1.71	13.58	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:2	19.09	2949	1.71	13.58	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:2	19.09	2943	1.71	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:2	19.09	2939	1.71	13.61	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:2	19.09	2938	1.71	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:3	19.09	2932	1.71	13.6	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:3	19.09	2932	1.7	13.6	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:3	19.09	2925	1.7	13.59	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:3	19.09	2922	1.7	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:3	19.09	2924	1.7	13.59	100	189	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:3	19.09	2934	1.7	13.6	100	189	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:4	19.09	2924	1.7	13.6	100	189	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:4	19.09	2906	1.7	13.59	100	189	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:4	19.09	2929	1.7	13.58	100	189	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:4	19.09	2929	1.7	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:4	19.09	2928	1.7	13.58	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:4	19.09	2928	1.7	13.59	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:4	19.09	2922	1.7	13.59	100	189	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:5	19.09	2922	1.7	13.59	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:5	19.09	2920	1.7	13.6	100	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:5	19.09	2920	1.7	13.59	100	189	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:5	19.09	2932	1.7	13.59	100	189	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:5	19.09	2919	1.7	13.6	100	189	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:5	19.09	2906	1.7	13.6	100	189	Idle	42.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:6	19.09	2916	1.7	13.59	100	189	Idle	42.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:56:6	19.09	2914	1.7	13.59	100	189	Idle	42.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:6	19.09	2914	1.7	13.59	100	189	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:6	19.09	2907	1.7	13.6	100	189	Idle	42.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:6	19.09	2901	1.7	13.59	100	189	Idle	42.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:6	19.09	2900	1.7	13.61	100	189	Idle	42.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:6	19.09	2894	1.7	13.59	100	189	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:7	19.09	2887	1.7	13.59	100	189	Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:7	19.09	2882	1.7	13.6	100	189	Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:7	19.09	2884	1.7	13.59	100	189	Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:7	19.09	2882	1.69	13.59	100	189	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:7	19.09	2882	1.69	13.59	100	189	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:7	19.09	2887	1.69	13.6	100	189	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:8	19.09	2887	1.69	13.6	100	189	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:8	19.09	2890	1.69	13.6	100	189	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:8	19.09	2897	1.69	13.6	100	189	Idle	43.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:8	19.09	2898	1.69	13.6	100	189	Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:8	19.09	2896	1.69	13.6	100	189	Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:8	19.09	2891	1.69	13.61	100	189	Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:9	19.09	2886	1.69	13.59	100	189	Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:9	19.09	2883	1.69	13.6	100	189	Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:9	19.09	2870	1.69	13.6	100	189	Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:9	19.09	2860	1.69	13.6	100	189	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:9	19.09	2852	1.69	13.59	100	189	Idle	43.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:9	19.09	2848	1.69	13.61	100	189	Idle	44.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:56:9	19.09	2846	1.69	13.6	100	189	Idle	44.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:0	19.09	2853	1.68	13.61	100	189	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:0	19.09	2862	1.68	13.6	100	189	Idle	44.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:0	19.09	2864	1.68	13.61	100	189	Idle	44.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:0	19.09	2883	1.68	13.6	100	189	Idle	44.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:0	19.09	2893	1.68	13.6	100	189	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:0	19.09	2894	1.68	13.61	100	189	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:1	19.09	2897	1.68	13.6	100	189	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:1	19.09	2894	1.67	13.62	100	189	Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:1	19.09	2892	1.67	13.61	100	189	Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:1	19.09	2884	1.67	13.61	100	189	Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:1	19.09	2868	1.67	13.61	100	189	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:1	19.09	2855	1.67	13.6	100	189	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:1	19.09	2854	1.67	13.6	100	189	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:2	19.09	2836	1.67	13.6	100	189	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:2	19.09	2827	1.67	13.6	100	189	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:2	19.09	2814	1.67	13.6	100	189	Idle	44.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:2	19.09	2817	1.67	13.59	100	189	Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:2	19.09	2814	1.67	13.6	100	189	Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:2	19.09	2814	1.67	13.6	100	189	Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:3	19.09	2816	1.67	13.6	100	189	Idle	45.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:3	19.09	2820	1.67	13.6	100	189	Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:3	19.09	2826	1.67	13.61	100	189	Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:3	19.09	2830	1.67	13.6	100	189	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:3	19.09	2831	1.67	13.59	100	189	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:3	19.09	2832	1.67	13.59	100	189	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:4	19.09	2834	1.67	13.58	100	189	Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:4	19.09	2834	1.67	13.59	100	189	Idle	45.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:4	19.09	2834	1.66	13.6	100	189	Idle	45.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:4	19.09	2831	1.66	13.6	100	189	Idle	45.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:4	19.09	2831	1.66	13.6	100	189	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:4	19.09	2824	1.66	13.6	100	189	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:4	19.09	2819	1.66	13.6	100	189	Idle	46.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:5	19.09	2816	1.66	13.61	100	189	Idle	46.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:57:5	19.09	2816	1.65	13.62	100	189	Idle	46.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:5	19.09	2812	1.65	13.6	100	189	Idle	46.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:5	19.09	2808	1.65	13.61	100	189	Idle	46.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:5	19.09	2805	1.64	13.6	100	189	Idle	47.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:5	19.09	2805	1.64	13.6	100	189	Idle	47.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:6	19.09	2804	1.64	13.6	100	189	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:6	19.09	2808	1.64	13.6	100	189	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:6	19.09	2808	1.63	13.61	100	189	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:6	19.09	2810	1.63	13.6	100	189	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:6	19.09	2809	1.63	13.61	100	189	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:6	19.09	2809	1.63	13.61	100	189	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:6	19.09	2810	1.62	13.6	100	189	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:7	19.09	2810	1.62	13.6	100	189	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:7	19.09	2807	1.62	13.6	100	189	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:7	19.09	2804	1.62	13.61	100	189	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:7	19.09	2794	1.61	13.62	100	189	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:7	19.09	2784	1.61	13.62	100	189	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:7	19.09	2778	1.61	13.62	100	189	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:8	19.09	2778	1.61	13.6	100	189	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:8	19.09	2775	1.61	13.61	100	189	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:8	19.09	2776	1.61	13.6	100	189	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:8	19.09	2778	1.61	13.6	100	189	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:8	19.09	2780	1.61	13.59	100	189	Idle	48.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:8	19.09	2784	1.61	13.59	100	189	Idle	49	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:9	19.09	2784	1.61	13.59	100	189	Idle	49	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:9	19.09	2782	1.61	13.6	100	189	Idle	49.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:9	19.09	2778	1.61	13.59	100	189	Idle	49.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:9	19.09	2778	1.6	13.6	100	189	Idle	49.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:9	19.09	2772	1.6	13.6	100	189	Idle	49.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:9	19.09	2767	1.6	13.61	100	189	Idle	49.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:57:9	19.09	2760	1.6	13.61	100	189	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:0	19.09	2758	1.6	13.62	100	189	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:0	19.09	2756	1.6	13.6	100	189	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:0	19.09	2753	1.6	13.59	100	189	Idle	50	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:0	19.09	2753	1.6	13.59	100	189	Idle	50	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:0	19.09	2753	1.59	13.6	100	189	Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:0	19.09	2755	1.59	13.59	100	189	Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:1	19.09	2755	1.59	13.59	100	189	Idle	50	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:1	19.09	2760	1.59	13.59	100	189	Idle	50	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:1	19.09	2777	1.59	13.59	100	189	Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:1	19.09	2770	1.59	13.59	100	189	Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:1	19.09	2772	1.59	13.6	100	189	Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:1	19.09	2768	1.58	13.6	100	189	Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:1	19.09	2772	1.58	13.6	100	189	Idle	50.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:2	19.09	2772	1.58	13.61	100	189	Idle	50.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:2	19.09	2765	1.58	13.61	100	189	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:2	19.09	2753	1.58	13.6	100	189	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:2	19.09	2753	1.58	13.6	100	189	Idle	50.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:2	19.09	2736	1.57	13.61	100	189	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:2	19.09	2729	1.57	13.6	100	189	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:3	19.09	2718	1.57	13.59	100	189	Idle	50.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:3	19.09	2717	1.57	13.6	100	189	Idle	50.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:3	19.09	2704	1.57	13.61	100	189	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:3	19.09	2716	1.57	13.6	100	189	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:3	19.09	2717	1.57	13.61	100	189	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:3	19.09	2722	1.57	13.6	100	189	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:4	19.09	2726	1.57	13.59	100	189	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:4	19.09	2746	1.57	13.6	100	189	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:58:4	19.09	2741	1.56	13.6	100	189	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:4	19.09	2744	1.56	13.59	100	189	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:4	19.09	2744	1.56	13.59	100	189	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:4	19.09	2742	1.56	13.6	100	189	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:4	19.09	2737	1.56	13.6	100	189	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:5	19.09	2737	1.56	13.59	100	189	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:5	19.09	2731	1.56	13.61	100	189	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:5	19.09	2724	1.56	13.59	100	189	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:5	19.09	2715	1.56	13.61	100	189	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:5	19.09	2715	1.56	13.6	100	189	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:5	19.09	2707	1.55	13.59	100	189	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:6	19.09	2701	1.55	13.59	100	189	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:6	19.09	2701	1.55	13.6	100	189	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:6	19.09	2696	1.55	13.59	100	189	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:6	19.09	2698	1.54	13.61	100	189	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:6	19.09	2697	1.54	13.58	100	189	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:6	19.09	2697	1.54	13.55	100	189	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:6	19.09	2694	1.54	13.53	100	189	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:7	19.09	2694	1.54	13.54	100	189	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:7	19.09	2696	1.54	13.51	100	189	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:7	19.09	2696	1.54	13.51	100	189	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:7	19.09	2700	1.54	13.52	100	189	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:7	19.09	2703	1.53	13.54	100	189	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:7	19.09	2704	1.53	13.54	100	189	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:8	19.09	2705	1.53	13.56	100	189	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:8	19.09	2716	1.53	13.54	100	189	Idle	52.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:8	19.09	2702	1.53	13.55	100	189	Idle	53.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:8	19.09	2686	1.52	13.55	100	189	Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:8	19.09	2688	1.52	13.54	100	189	Idle	53.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:8	19.09	2685	1.52	13.54	100	189	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:9	19.09	2674	1.51	13.54	100	189	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:9	19.09	2660	1.51	13.56	100	189	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:9	19.09	2660	1.51	13.55	100	189	Idle	54.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:9	19.09	2653	1.51	13.55	100	189	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:9	19.09	2630	1.51	13.55	100	189	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:9	19.09	2649	1.5	13.55	100	189	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:58:9	19.09	2648	1.5	13.55	100	189	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:0	19.09	2658	1.5	13.54	100	189	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:0	19.09	2645	1.49	13.55	100	189	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:0	19.09	2645	1.49	13.54	100	189	Idle	55.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:0	19.09	2640	1.49	13.53	100	189	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:0	19.09	2634	1.48	13.55	100	189	Idle	55.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:0	19.09	2622	1.48	13.55	100	189	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:1	19.09	2622	1.48	13.55	100	189	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:1	19.09	2612	1.48	13.55	100	189	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:1	19.09	2599	1.48	13.55	100	189	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:1	19.09	2591	1.48	13.54	100	189	Idle	55.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:1	19.09	2580	1.48	13.54	100	189	Idle	55.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:1	19.09	2578	1.48	13.55	100	189	Idle	55.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:1	19.09	2592	1.48	13.54	100	189	Idle	55.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:2	19.09	2563	1.48	13.55	100	189	Idle	56.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:2	19.09	2562	1.48	13.54	100	189	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:2	19.09	2539	1.48	13.54	100	189	Idle	56.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:2	19.09	2556	1.47	13.55	100	189	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:2	19.09	2556	1.47	13.54	100	189	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:2	19.09	2556	1.47	13.55	100	189	Idle	56.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:3	19.09	2546	1.47	13.55	100	189	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:3	19.09	2556	1.47	13.55	100	189	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:09:59:3	19.09	2559	1.46	13.56	100	189	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:3	19.09	2559	1.46	13.56	100	189	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:3	19.09	2556	1.46	13.55	100	189	Idle	57.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:3	19.09	2554	1.46	13.55	100	189	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:4	19.09	2552	1.45	13.55	100	189	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:4	19.09	2540	1.45	13.55	100	189	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:4	19.09	2528	1.44	13.55	100	189	Idle	59.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:4	19.09	2519	1.44	13.56	100	189	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:4	19.09	2494	1.43	13.56	100	189	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:4	19.09	2500	1.43	13.56	100	189	Idle	59.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:4	19.09	2495	1.42	13.56	100	189	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:5	19.09	2487	1.42	13.55	100	189	Idle	60.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:5	19.09	2483	1.41	13.53	100	189	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:5	19.09	2471	1.4	13.55	100	189	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:5	19.09	2466	1.4	13.55	100	189	Idle	62	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:5	19.09	2456	1.39	13.54	100	189	Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:5	19.09	2470	1.39	13.56	100	189	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:6	19.09	2418	1.38	13.56	100	189	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:6	19.09	2418	1.38	13.57	100	189	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:6	19.09	2422	1.37	13.57	100	189	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:6	19.09	2412	1.36	13.57	100	189	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:6	19.09	2399	1.36	13.56	100	189	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:6	19.09	2384	1.35	13.55	100	189	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:6	17.72	2352	1.35	13.53	100	189	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:7	17.72	2334	1.34	13.53	100	189	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:7	17.72	2313	1.34	13.51	100	189	Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:7	17.72	2304	1.33	13.52	100	189	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:7	17.72	2274	1.33	13.52	100	189	Idle	63.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:7	17.72	2244	1.32	13.53	100	189	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:7	17.72	2197	1.32	13.53	100	189	Idle	64.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:8	17.72	2197	1.32	13.53	100	189	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:8	17.72	2185	1.32	13.55	100	189	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:8	17.72	2121	1.31	13.53	100	189	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:8	17.72	2126	1.31	13.53	100	189	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:8	17.72	2112	1.3	13.53	100	189	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:8	17.72	2082	1.3	13.52	100	189	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:9	17.72	2035	1.29	13.5	100	189	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:9	17.72	2035	1.29	13.51	100	189	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:9	17.72	2030	1.28	13.52	100	189	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:9	17.72	1993	1.28	13.52	100	189	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:9	17.72	1990	1.28	13.5	100	189	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:9	17.72	1954	1.27	13.5	100	189	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:09:59:9	17.72	1922	1.27	13.51	100	189	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:0	17.72	1887	1.26	13.52	100	189	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:0	17.72	1878	1.26	13.53	100	189	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:0	17.72	1878	1.26	13.52	100	189	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:0	17.72	1868	1.26	13.53	100	189	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:0	17.72	1822	1.26	13.53	100	189	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:0	17.72	1793	1.26	13.54	100	189	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:1	17.72	1775	1.26	13.55	100	189	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:1	17.72	1741	1.26	13.53	100	190	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:1	17.72	1741	1.25	13.53	100	190	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:1	17.72	1718	1.26	13.51	100	190	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:1	17.72	1681	1.26	13.51	100	189	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:1	17.72	1669	1.26	13.5	100	189	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.4	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:1	17.72	1669	1.26	13.51	100	189	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.37	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:2	17.72	1634	1.26	13.5	100	189	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.35	20.22	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:2	17.72	1622	1.26	13.51	100	189	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.29	20.22	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:00:2	17.72	1604	1.26	13.51	100	189	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.27	20.22	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:2	17.72	1583	1.26	13.52	100	189	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.21	20.22	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:2	17.72	1547	1.26	13.51	100	189	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.14	20.22	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:2	17.72	1511	1.26	13.5	100	189	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.05	20.22	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:3	17.72	1496	1.26	13.52	100	189	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.99	20.23	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:3	17.72	1496	1.26	13.51	100	189	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.91	20.23	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:3	17.72	1469	1.26	13.51	100	189	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.84	20.23	1.38	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:3	17.72	1469	1.26	13.52	100	189	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.82	20.23	1.38	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:3	17.72	1443	1.26	13.53	100	189	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.77	20.23	1.38	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:3	17.72	1405	1.25	13.54	100	189	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.73	20.24	1.38	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:4	19.09	1400	1.25	13.53	100	189	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.66	20.24	1.38	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:4	19.09	1400	1.25	13.52	100	189	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.61	20.24	1.38	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:4	19.09	1362	1.25	13.53	100	189	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.56	20.24	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:4	19.09	1333	1.25	13.53	100	189	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.51	20.23	1.38	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:00:4	19.09	1286	1.24	13.53	100	189	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.48	20.23	1.38	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:00:4	19.09	1286	1.24	13.53	100	189	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.42	20.22	1.38	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:00:4	16.36	1275	1.24	13.53	100	189	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.33	20.23	1.38	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:00:5	16.36	1280	1.23	13.51	100	189	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.32	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:00:5	16.36	1283	1.23	13.51	100	189	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.24	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:00:5	16.36	1286	1.22	13.5	100	189	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.16	20.22	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:00:5	16.36	1308	1.22	13.5	100	189	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.15	20.22	1.38	4.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:00:5	16.36	1363	1.21	13.52	100	189	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.18	20.22	1.38	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:00:5	16.36	1397	1.2	13.56	100	189	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.18	20.22	1.38	4.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:00:6	16.36	1428	1.2	13.57	100	189	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.24	20.21	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:00:6	14.99	1557	1.19	13.59	100	189	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.31	20.21	1.38	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:00:6	14.99	1610	1.17	13.58	100	189	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.4	20.21	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:00:6	16.36	1694	1.15	13.58	100	189	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.61	20.21	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:00:6	16.36	1783	1.13	13.57	100	189	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:00:6	16.36	1878	1.11	13.56	100	189	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:00:6	16.36	1904	1.1	13.56	100	189	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.19	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:7	16.36	1930	1.08	13.57	100	189	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.31	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:7	16.36	2008	1.06	13.57	100	189	Idle	86.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:7	16.36	2008	1.05	13.59	100	189	Idle	87.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:7	16.36	2094	1.02	13.59	100	189	Idle	88.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.21	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:7	17.72	2175	0.99	13.61	100	189	Idle	88.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:7	17.72	2248	0.97	13.6	100	189	Idle	89	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:8	17.72	2248	0.94	13.6	100	189	Idle	88.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:8	17.72	2322	0.93	13.59	100	189	Idle	87.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.44	20.21	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:8	17.72	2435	0.9	13.58	100	189	Idle	87.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.57	20.21	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:8	17.72	2469	0.89	13.57	100	189	Idle	86.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.64	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:8	17.72	2529	0.88	13.57	100	189	Idle	83.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.71	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:8	17.72	2588	0.88	13.57	100	189	Idle	82.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.78	20.23	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:9	17.72	2606	0.88	13.57	100	189	Idle	80.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.8	20.23	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:9	17.72	2710	0.89	13.57	100	189	Idle	79	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.81	20.23	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:9	17.72	2730	0.91	13.57	100	189	Idle	76.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.8	20.23	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:9	17.72	2756	0.93	13.57	100	189	Idle	74.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.81	20.24	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:9	17.72	2806	0.94	13.57	100	189	Idle	72.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.78	20.24	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:9	19.09	2806	0.97	13.56	100	189	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.24	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:00:9	19.09	2888	0.99	13.56	100	189	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.24	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:0	19.09	2888	1.03	13.56	100	189	Idle	62.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.25	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:0	19.09	2896	1.06	13.56	100	189	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.25	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:0	19.09	2862	1.12	13.56	100	189	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:0	19.09	2830	1.16	13.56	100	189	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:0	19.09	2800	1.18	13.56	100	189	Idle	54.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:0	19.09	2786	1.21	13.56	100	189	Idle	53	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:1	19.09	2786	1.23	13.56	100	189	Idle	51.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:1	19.09	2744	1.29	13.55	100	189	Idle	50.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:1	19.09	2706	1.31	13.55	100	189	Idle	49.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:01:1	19.09	2698	1.37	13.55	100	189	Idle	48.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:1	19.09	2654	1.4	13.54	100	189	Idle	47.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:1	19.09	2622	1.43	13.55	100	189	Idle	46.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:1	19.09	2611	1.46	13.55	100	189	Idle	46.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:2	19.09	2609	1.48	13.54	100	189	Idle	45.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:2	19.09	2601	1.51	13.56	100	189	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:2	19.09	2603	1.53	13.57	100	189	Idle	45.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:2	19.09	2603	1.57	13.58	100	189	Idle	45.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:2	19.09	2617	1.58	13.57	100	189	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:2	19.09	2637	1.6	13.56	100	189	Idle	45.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:3	19.09	2637	1.61	13.56	100	189	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:3	19.09	2677	1.61	13.56	100	189	Idle	45.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:3	19.09	2660	1.62	13.55	100	189	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:3	19.09	2655	1.62	13.54	100	189	Idle	46.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:3	19.09	2652	1.62	13.55	100	189	Idle	47.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:3	19.09	2634	1.62	13.56	100	189	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:4	19.09	2616	1.61	13.55	100	189	Idle	50.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:4	19.09	2616	1.6	13.56	100	189	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:4	19.09	2569	1.59	13.56	100	189	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:4	19.09	2570	1.59	13.55	100	189	Idle	53.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:4	19.09	2551	1.58	13.55	100	189	Idle	54.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:4	19.09	2546	1.57	13.55	100	189	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:4	19.09	2509	1.56	13.55	100	189	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:5	19.09	2519	1.55	13.56	100	189	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:5	19.09	2520	1.53	13.55	100	189	Idle	58.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:5	19.09	2520	1.52	13.55	100	189	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:5	19.09	2527	1.51	13.55	100	189	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:5	19.09	2562	1.5	13.54	100	189	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:5	19.09	2562	1.49	13.55	100	189	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:6	19.09	2552	1.48	13.56	100	189	Idle	57.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:6	19.09	2553	1.47	13.57	100	189	Idle	57.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:6	19.09	2566	1.45	13.58	100	189	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:6	19.09	2584	1.45	13.58	100	189	Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:6	19.09	2572	1.44	13.58	100	189	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:6	19.09	2554	1.44	13.59	100	189	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:6	19.09	2554	1.44	13.59	100	189	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:7	19.09	2538	1.43	13.6	100	189	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:7	19.09	2523	1.43	13.6	100	189	Idle	60	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:7	19.09	2509	1.43	13.59	100	189	Idle	60.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:7	19.09	2477	1.42	13.59	100	189	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:7	19.09	2482	1.42	13.6	100	189	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:7	19.09	2481	1.42	13.6	100	189	Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:8	19.09	2477	1.41	13.61	100	189	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:8	19.09	2477	1.41	13.6	100	189	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:8	19.09	2474	1.4	13.61	100	189	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:8	19.09	2473	1.4	13.61	100	189	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:8	19.09	2473	1.39	13.6	100	189	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:8	19.09	2476	1.39	13.57	100	189	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:9	19.09	2479	1.38	13.58	100	189	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:9	19.09	2485	1.38	13.57	100	189	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:9	19.09	2485	1.38	13.58	100	189	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:9	19.09	2486	1.37	13.59	100	189	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:9	19.09	2484	1.37	13.6	100	189	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:9	19.09	2480	1.37	13.6	100	189	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:01:9	19.09	2477	1.37	13.6	100	189	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:0	19.09	2471	1.36	13.6	100	189	Idle	63.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:0	19.09	2462	1.36	13.6	100	189	Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:0	19.09	2458	1.35	13.6	100	189	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:02:0	19.09	2450	1.35	13.61	100	189	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:0	19.09	2450	1.35	13.6	100	189	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:0	19.09	2425	1.34	13.59	100	189	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:1	17.72	2442	1.34	13.58	100	189	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:1	17.72	2441	1.33	13.6	100	189	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:1	17.72	2438	1.33	13.6	100	189	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:1	17.72	2438	1.32	13.6	100	189	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:1	17.72	2436	1.32	13.61	100	189	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:1	17.72	2436	1.31	13.62	100	189	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:1	17.72	2436	1.3	13.62	100	189	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:2	17.72	2444	1.3	13.62	100	189	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:2	17.72	2444	1.29	13.62	100	189	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:2	17.72	2416	1.29	13.59	100	189	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:2	17.72	2419	1.28	13.59	100	189	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:2	17.72	2414	1.28	13.59	100	189	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:2	17.72	2402	1.28	13.59	100	189	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:3	17.72	2398	1.27	13.6	100	189	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:3	17.72	2387	1.27	13.59	100	189	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:3	17.72	2379	1.26	13.59	100	189	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:3	17.72	2368	1.26	13.6	100	189	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:3	17.72	2366	1.25	13.59	100	189	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:3	17.72	2361	1.25	13.58	100	189	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:4	17.72	2358	1.25	13.61	100	189	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:4	17.72	2356	1.25	13.6	100	189	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:4	17.72	2352	1.24	13.6	100	189	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:4	17.72	2350	1.24	13.61	100	189	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:4	17.72	2350	1.24	13.6	100	189	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:4	17.72	2352	1.24	13.6	100	189	Off Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:4	17.72	2352	1.24	13.61	100	189	Off Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:5	8.18	2293	1.24	13.63	100	189	Off Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:02:5	10.9	2369	1.25	13.63	100	189	Off Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:02:5	10.9	2367	1.25	13.63	100	189	Off Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:02:5	13.63	2367	1.25	13.63	100	189	Off Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:02:5	16.36	2376	1.26	13.63	100	189	Off Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:02:5	16.36	2350	1.27	13.61	100	189	Off Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:02:6	19.09	2341	1.27	13.62	100	189	Off Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:02:6	21.81	2341	1.29	13.59	100	189	Off Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:02:6	21.81	2316	1.3	13.57	100	189	Off Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:02:6	24.54	2326	1.31	13.58	100	189	Off Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:02:6	24.54	2316	1.33	13.59	100	189	Off Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:02:6	27.27	2316	1.35	13.59	100	189	Off Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:02:6	29.99	2313	1.37	13.63	100	189	Off Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:02:7	29.99	2338	1.39	13.64	100	189	Off Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:02:7	32.72	2320	1.41	13.64	100	189	Off Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:02:7	32.72	2320	1.43	13.62	100	189	Off Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:02:7	35.45	2312	1.45	13.61	100	189	Off Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:02:7	35.45	2300	1.48	13.62	100	189	Off Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:02:7	35.45	2312	1.5	13.62	100	189	Off Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	20.22	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:02:8	35.45	2335	1.52	13.63	100	189	Off Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	20.22	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:02:8	35.45	2339	1.56	13.61	100	189	Off Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.17	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:02:8	35.45	2345	1.57	13.59	100	189	Off Idle	77.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.08	20.22	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:02:8	34.08	2346	1.61	13.59	100	189	Off Idle	77.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.87	20.23	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:02:8	34.08	2348	1.64	13.6	100	189	Off Idle	77.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.64	20.23	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:8	34.08	2350	1.67	13.59	100	189	Off Idle	77.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.4	20.23	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:02:9	34.08	2350	1.73	13.6	100	189	Off Idle	77.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8	20.24	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:02:9	34.08	2352	1.77	13.62	100	189	Off Idle	76.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.87	20.24	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:02:9	34.08	2354	1.81	13.6	100	189	Off Idle	76.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.42	20.25	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:02:9	34.08	2359	1.85	13.59	100	189	Off Idle	76	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.11	20.24	1.38	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:02:9	34.08	2360	1.91	13.6	100	189	Off Idle	75.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.75	20.25	1.38	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:02:9	34.08	2360	1.94	13.61	100	189	Off Idle	75.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.43	20.24	1.38	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:02:9	34.08	2357	1.98	13.62	100	189	Off Idle	75.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.15	20.24	1.38	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:03:0	34.08	2342	2.02	13.61	100	189	Off Idle	75	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.91	20.24	1.38	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:03:0	34.08	2330	2.08	13.61	100	189	Off Idle	74.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.5	20.24	1.38	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:0	34.08	2328	2.12	13.61	100	189	Off Idle	74.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.21	20.2	1.38	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:03:0	32.72	2314	2.17	13.61	100	189	Off Idle	74.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.88	20.08	1.37	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:03:0	32.72	2315	2.23	13.61	100	189	Off Idle	74.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.38	19.83	1.35	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:03:0	32.72	2305	2.27	13.63	100	189	Off Idle	75	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.05	19.61	1.34	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:03:1	32.72	2320	2.31	13.62	100	189	Off Idle	75.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.75	19.36	1.32	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:03:1	32.72	2322	2.35	13.61	100	189	Off Idle	75.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.44	19.09	1.3	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:1	32.72	2331	2.39	13.61	100	189	Off Idle	75.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.11	18.65	1.27	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:1	31.36	2331	2.42	13.6	100	189	Off Idle	75.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-2.89	18.48	1.26	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:1	31.36	2357	2.44	13.58	100	189	Off Idle	75.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-2.7	18.13	1.24	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:1	31.36	2361	2.47	13.59	100	189	Off Idle	75.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.54	17.77	1.21	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:03:1	31.36	2373	2.5	13.59	100	189	Off Idle	75.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.42	17.31	1.18	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:03:2	31.36	2374	2.53	13.56	100	189	Off Idle	75.8	0	2	132	944 Turbo	0.24	Rich	1	14.6	-2.26	16.94	1.15	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:03:2	31.36	2390	2.55	13.56	100	189	Off Idle	75.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-2.13	16.83	1.15	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:2	31.36	2382	2.57	13.56	100	189	Off Idle	75.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-1.99	16.61	1.13	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:2	31.36	2372	2.6	13.56	100	189	Off Idle	75.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.8	16.33	1.11	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:2	31.36	2370	2.62	13.56	100	189	Off Idle	75.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-1.67	16.12	1.1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:2	31.36	2367	2.64	13.58	100	189	Off Idle	75.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.54	15.97	1.09	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:3	31.36	2364	2.64	13.6	100	189	Off Idle	75.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.45	15.8	1.08	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:3	31.36	2364	2.65	13.59	100	189	Off Idle	74.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.46	15.62	1.06	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:3	31.36	2366	2.66	13.59	100	189	Off Idle	74.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.44	15.43	1.05	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:3	31.36	2369	2.66	13.58	100	189	Off Idle	74.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.3	15.23	1.04	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:3	31.36	2359	2.67	13.58	100	189	Off Idle	74.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.32	14.95	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:3	31.36	2372	2.67	13.59	100	189	Off Idle	74.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.29	14.78	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:03:4	31.36	2400	2.68	13.6	100	189	Off Idle	74.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.19	14.59	0.99	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:03:4	31.36	2407	2.69	13.61	100	189	Off Idle	74	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.03	14.35	0.98	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:03:4	31.36	2418	2.7	13.62	100	189	Off Idle	73.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.01	14.18	0.97	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:10:03:4	31.36	2424	2.7	13.62	100	189	Off Idle	73.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.98	14	0.95	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:10:03:4	31.36	2433	2.71	13.59	100	189	Off Idle	73.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.01	13.88	0.95	3.3	4.9	ON	28 Pin	OFF	Removed	Disabled
03:10:03:4	31.36	2440	2.71	13.58	100	189	Off Idle	72.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1	13.8	0.94	3.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:03:4	31.36	2440	2.71	13.59	100	189	Off Idle	72.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.98	13.75	0.94	3.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:03:5	31.36	2455	2.72	13.58	100	189	Off Idle	72.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.96	13.68	0.93	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:03:5	31.36	2434	2.72	13.6	100	189	Off Idle	71.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.87	13.64	0.93	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:03:5	31.36	2445	2.73	13.61	100	189	Off Idle	71.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.75	13.59	0.93	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:10:03:5	31.36	2441	2.74	13.6	100	189	Off Idle	71.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.79	13.55	0.92	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:10:03:5	31.36	2452	2.75	13.59	100	189	Off Idle	70.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.72	13.5	0.92	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:10:03:5	31.36	2456	2.75	13.59	100	189	Off Idle	70.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.57	13.46	0.92	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:03:6	31.36	2467	2.76	13.59	100	189	Off Idle	70.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.51	13.42	0.91	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:03:6	31.36	2470	2.77	13.59	100	189	Off Idle	69.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.44	13.41	0.91	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:03:6	31.36	2474	2.78	13.59	100	189	Off Idle	69.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.37	13.37	0.91	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:03:6	31.36	2476	2.79	13.58	100	189	Off Idle	69.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.24	13.34	0.91	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:03:6	31.36	2496	2.79	13.59	100	189	Off Idle	69.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.19	13.3	0.91	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:6	31.36	2491	2.8	13.59	100	189	Off Idle	69.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.02	13.29	0.91	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:6	31.36	2490	2.81	13.6	100	189	Off Idle	68.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.08	13.28	0.9	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:7	31.36	2493	2.82	13.58	100	189	Off Idle	68.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.11	13.28	0.9	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:7	31.36	2510	2.83	13.56	100	189	Off Idle	68.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.09	13.3	0.91	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:7	31.36	2498	2.83	13.58	100	189	Off Idle	68.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.12	13.33	0.91	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:7	31.36	2500	2.84	13.59	100	189	Off Idle	68.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.1	13.34	0.91	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:7	31.36	2512	2.85	13.6	100	189	Off Idle	67.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.14	13.34	0.91	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:7	31.36	2502	2.86	13.62	100	189	Off Idle	67.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.23	13.35	0.91	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:8	29.99	2533	2.86	13.62	100	189	Off Idle	67.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.24	13.35	0.91	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:8	29.99	2534	2.87	13.6	100	189	Off Idle	67.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.25	13.34	0.91	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:8	29.99	2538	2.88	13.59	100	189	Off Idle	66.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.25	13.33	0.91	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:8	29.99	2540	2.88	13.59	100	189	Off Idle	66.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.25	13.29	0.91	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:03:8	29.99	2544	2.89	13.6	100	189	Off Idle	65.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.34	13.28	0.9	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:03:8	29.99	2553	2.89	13.61	100	189	Off Idle	65.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.42	13.26	0.9	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:9	29.99	2554	2.89	13.62	100	189	Off Idle	65.3	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.47	13.26	0.9	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:9	29.99	2554	2.9	13.6	100	189	Off Idle	64.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.52	13.28	0.9	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:9	29.99	2554	2.9	13.61	100	189	Off Idle	64.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.54	13.28	0.9	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:9	29.99	2568	2.91	13.58	100	189	Off Idle	64.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.56	13.31	0.91	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:9	29.99	2569	2.92	13.59	100	189	Off Idle	64.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.56	13.35	0.91	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:9	29.99	2577	2.92	13.58	100	189	Off Idle	64.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.54	13.43	0.91	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:03:9	29.99	2577	2.92	13.59	100	189	Off Idle	63.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.57	13.49	0.92	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:04:0	29.99	2590	2.93	13.61	100	189	Off Idle	63.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.61	13.53	0.92	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:04:0	29.99	2594	2.93	13.61	100	189	Off Idle	63	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.61	13.59	0.93	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:04:0	29.99	2603	2.94	13.59	100	189	Off Idle	62.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.72	13.64	0.93	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:04:0	29.99	2604	2.94	13.6	100	189	Off Idle	62.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.78	13.64	0.93	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:04:0	29.99	2596	2.95	13.59	100	189	Off Idle	62.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.83	13.7	0.93	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:04:0	28.63	2621	2.96	13.6	100	189	Off Idle	62.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.9	13.76	0.94	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:04:1	28.63	2621	2.96	13.59	100	189	Off Idle	62.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.93	13.8	0.94	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:04:1	28.63	2626	2.96	13.58	100	189	Off Idle	61.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.98	13.83	0.94	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:04:1	28.63	2634	2.97	13.59	100	189	Off Idle	61.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.05	13.86	0.94	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:04:1	29.99	2657	2.98	13.6	100	189	Off Idle	61.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.02	13.89	0.95	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:04:1	29.99	2657	2.98	13.6	100	189	Off Idle	61.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.01	13.92	0.95	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:04:1	29.99	2643	2.99	13.61	100	189	Off Idle	61.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.01	13.96	0.95	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:04:1	29.99	2650	2.99	13.6	100	189	Off Idle	60.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.03	13.99	0.95	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:2	29.99	2657	3	13.58	100	189	Off Idle	60.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.07	14.01	0.95	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:2	28.63	2650	3	13.6	100	189	Off Idle	60.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.17	14.03	0.96	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:2	28.63	2670	3.01	13.59	100	189	Off Idle	60	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.26	14.04	0.96	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:2	28.63	2670	3.01	13.58	100	189	Off Idle	59.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.27	14.08	0.96	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:2	28.63	2682	3.02	13.57	100	189	Off Idle	59.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.32	14.11	0.96	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:2	28.63	2682	3.02	13.57	100	189	Off Idle	59.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.32	14.13	0.96	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:3	29.99	2733	3.03	13.57	100	189	Off Idle	58.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.38	14.19	0.97	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:3	29.99	2704	3.04	13.58	100	189	Off Idle	58	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.48	14.26	0.97	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:3	29.99	2703	3.04	13.58	100	189	Off Idle	57.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.53	14.3	0.97	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:04:3	29.99	2703	3.05	13.58	100	189	Off Idle	57.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.59	14.33	0.98	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:04:3	28.63	2692	3.06	13.59	100	189	Off Idle	57	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.6	14.36	0.98	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:04:3	28.63	2700	3.06	13.58	100	189	Off Idle	56.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.61	14.38	0.98	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:04:4	28.63	2715	3.07	13.59	100	189	Off Idle	56.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.64	14.39	0.98	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:04:4	28.63	2715	3.07	13.58	100	189	Off Idle	56.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.69	14.39	0.98	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:04:4	28.63	2741	3.08	13.59	100	189	Off Idle	55.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.79	14.39	0.98	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:04:4	28.63	2747	3.08	13.59	100	189	Off Idle	55.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.8	14.39	0.98	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:04:4	28.63	2749	3.09	13.59	100	189	Off Idle	55.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.87	14.37	0.98	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:04:4	28.63	2756	3.09	13.57	100	189	Off Idle	55.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.89	14.36	0.98	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:04:4	28.63	2774	3.1	13.57	100	189	Off Idle	54.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.88	14.36	0.98	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:04:5	28.63	2806	3.1	13.57	100	189	Off Idle	54.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.9	14.38	0.98	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:04:5	28.63	2806	3.11	13.57	100	189	Off Idle	53.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.92	14.39	0.98	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:04:5	28.63	2800	3.12	13.59	100	189	Off Idle	53.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.91	14.4	0.98	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:04:5	28.63	2800	3.12	13.59	100	189	Off Idle	53.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.97	14.42	0.98	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:04:5	28.63	2796	3.13	13.59	100	189	Off Idle	52.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.99	14.43	0.98	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:04:5	28.63	2796	3.13	13.59	100	189	Off Idle	52.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	2.14	14.43	0.98	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:04:6	28.63	2797	3.14	13.59	100	189	Off Idle	52.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	2.2	14.43	0.98	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:04:6	28.63	2801	3.15	13.58	100	189	Off Idle	51.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	2.26	14.44	0.98	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:04:6	28.63	2803	3.15	13.56	100	189	Off Idle	51.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	2.36	14.44	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:6	28.63	2804	3.16	13.57	100	189	Off Idle	50.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	2.47	14.42	0.98	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:04:6	28.63	2824	3.16	13.58	100	189	Off Idle	50.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	2.42	14.43	0.98	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:04:6	28.63	2829	3.17	13.58	100	189	Off Idle	50.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	2.49	14.43	0.98	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:04:6	28.63	2845	3.17	13.58	100	189	Off Idle	49.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	2.54	14.44	0.98	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:04:7	28.63	2853	3.18	13.58	100	189	Off Idle	49.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	2.52	14.44	0.98	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:04:7	28.63	2862	3.19	13.58	100	189	Off Idle	49.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	2.57	14.44	0.98	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:7	28.63	2862	3.2	13.59	100	189	Off Idle	49.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	2.6	14.44	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:7	28.63	2872	3.2	13.6	100	189	Off Idle	48.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	2.7	14.45	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:04:7	28.63	2878	3.21	13.58	100	189	Off Idle	48.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	2.78	14.45	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:7	28.63	2883	3.21	13.58	100	189	Off Idle	48.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	2.87	14.47	0.99	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:8	28.63	2883	3.22	13.58	100	189	Off Idle	47.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	2.86	14.49	0.99	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:8	28.63	2894	3.23	13.58	100	189	Off Idle	47.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	2.94	14.48	0.99	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:04:8	28.63	2898	3.23	13.59	100	189	Off Idle	47.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	2.99	14.48	0.99	3.4	6	ON	28 Pin	OFF	Removed	Disabled
03:10:04:8	28.63	2896	3.24	13.58	100	189	Off Idle	46.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	2.99	14.49	0.99	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:04:8	28.63	2896	3.24	13.59	100	189	Off Idle	46.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	3.03	14.5	0.99	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:04:8	27.27	2903	3.25	13.59	100	189	Off Idle	46.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	3.09	14.53	0.99	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:04:9	27.27	2920	3.25	13.59	100	189	Off Idle	46.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	3.13	14.54	0.99	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:04:9	27.27	2921	3.26	13.57	100	189	Off Idle	45.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	3.19	14.57	0.99	3.4	6.2	ON	28 Pin	OFF	Removed	Disabled
03:10:04:9	27.27	2926	3.26	13.57	100	189	Off Idle	45.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	3.34	14.6	0.99	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:04:9	27.27	2926	3.27	13.56	100	189	Off Idle	45	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.43	14.63	1	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:04:9	27.27	2949	3.28	13.56	100	189	Off Idle	44.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.46	14.66	1	3.4	6.2	ON	28 Pin	OFF	Removed	Disabled
03:10:04:9	27.27	2959	3.29	13.56	100	189	Off Idle	44.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	3.57	14.71	1	3.4	6.2	ON	28 Pin	OFF	Removed	Disabled
03:10:04:9	27.27	2971	3.29	13.57	100	189	Off Idle	44.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	3.65	14.75	1	3.3	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:0	27.27	2971	3.3	13.56	100	189	Off Idle	43.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	3.72	14.78	1.01	3.3	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:0	27.27	3006	3.3	13.57	100	189	Off Idle	43.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	3.76	14.83	1.01	3.4	6.2	ON	28 Pin	OFF	Removed	Disabled
03:10:05:0	27.27	2999	3.31	13.56	100	189	Off Idle	43.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	3.87	14.85	1.01	3.4	6.2	ON	28 Pin	OFF	Removed	Disabled
03:10:05:0	27.27	3008	3.32	13.56	100	189	Off Idle	43.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	3.87	14.89	1.01	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:0	27.27	3009	3.32	13.56	100	189	Off Idle	43	0	2	132	944 Turbo	0.71	Rich	1	14.6	3.96	14.93	1.02	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:0	27.27	3009	3.33	13.56	100	189	Off Idle	42.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.01	14.94	1.02	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:1	27.27	3023	3.34	13.55	100	189	Off Idle	42.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.19	14.96	1.02	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:1	27.27	2999	3.34	13.57	100	189	Off Idle	42.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.24	14.97	1.02	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:1	27.27	2997	3.35	13.55	100	189	Off Idle	42	0	2	132	944 Turbo	0.69	Rich	1	14.6	4.42	14.98	1.02	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:10:05:1	27.27	3016	3.35	13.57	100	189	Off Idle	41.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	4.45	14.97	1.02	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:10:05:1	27.27	3016	3.36	13.57	100	189	Off Idle	41.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	4.44	14.95	1.02	3.4	6.5	ON	28 Pin	OFF	Removed	Disabled
03:10:05:1	27.27	3022	3.37	13.59	100	189	Off Idle	41.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	4.5	14.93	1.02	3.4	6.8	ON	28 Pin	OFF	Removed	Disabled
03:10:05:1	27.27	3049	3.38	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	4.55	14.92	1.02	3.4	6.5	ON	28 Pin	OFF	Removed	Disabled
03:10:05:2	25.9	3065	3.38	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	4.55	14.9	1.01	3.4	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:05:2	25.9	3065	3.39	13.59	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	4.59	14.91	1.02	3.4	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:05:2	25.9	3066	3.39	13.59	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	4.76	14.91	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:2	25.9	3081	3.4	13.59	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	4.83	14.93	1.02	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:2	25.9	3121	3.41	13.59	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	4.92	14.96	1.02	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:2	25.9	3121	3.42	13.59	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	4.96	14.98	1.02	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:3	25.9	3104	3.42	13.59	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	5.08	15	1.02	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:10:05:3	25.9	3106	3.43	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	5.23	15.03	1.02	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:10:05:3	25.9	3104	3.45	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	5.34	15.02	1.02	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:10:05:3	27.27	3128	3.45	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.66	Lean	1	14.6	5.58	14.97	1.02	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:05:3	27.27	3123	3.46	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	5.74	14.95	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:3	27.27	3146	3.47	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	5.7	14.94	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:4	27.27	3155	3.47	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	5.87	14.91	1.02	3.4	7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:4	27.27	3158	3.48	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	5.92	14.85	1.01	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:05:4	25.9	3175	3.49	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	5.86	14.83	1.01	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:05:4	25.9	3188	3.5	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	6.05	14.83	1.01	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:05:4	25.9	3191	3.51	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	6.13	14.85	1.01	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:05:4	25.9	3194	3.52	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	6.17	14.85	1.01	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:10:05:4	25.9	3189	3.53	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	6.31	14.86	1.01	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:10:05:5	25.9	3189	3.54	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	6.41	14.85	1.01	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:05:5	25.9	3180	3.55	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	6.48	14.84	1.01	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:10:05:5	25.9	3186	3.56	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	6.68	14.85	1.01	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:5	24.54	3198	3.56	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	6.69	14.85	1.01	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:05:5	24.54	3198	3.57	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	6.87	14.83	1.01	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:05:5	24.54	3242	3.58	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	6.9	14.81	1.01	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:6	24.54	3274	3.59	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	7.02	14.81	1.01	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:6	24.54	3291	3.59	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	7.13	14.82	1.01	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:6	24.54	3290	3.6	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	7.19	14.89	1.01	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:05:6	24.54	3291	3.61	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	7.38	14.9	1.01	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:05:6	24.54	3291	3.62	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	7.49	14.91	1.02	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:05:6	24.54	3293	3.63	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	7.65	14.92	1.02	3.4	7.5	ON	28 Pin	OFF	Removed	Disabled
03:10:05:6	24.54	3285	3.64	13.59	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	7.73	14.92	1.02	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:7	24.54	3289	3.65	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	7.88	14.94	1.02	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:7	24.54	3301	3.66	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	8.09	14.99	1.02	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:10:05:7	24.54	3306	3.67	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	8.15	14.99	1.02	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:10:05:7	24.54	3310	3.68	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	8.51	14.98	1.02	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:10:05:7	24.54	3324	3.69	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	8.57	14.89	1.01	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:10:05:7	24.54	3350	3.7	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	8.78	14.9	1.01	3.4	8.4	ON	28 Pin	OFF	Removed	Disabled
03:10:05:8	24.54	3362	3.7	13.56	100	189	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	8.79	14.89	1.01	3.4	8.4	ON	28 Pin	OFF	Removed	Disabled
03:10:05:8	23.18	3366	3.72	13.56	100	189	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	8.94	14.91	1.02	3.4	8	ON	28 Pin	OFF	Removed	Disabled
03:10:05:8	23.18	3388	3.73	13.56	100	189	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	9.1	14.95	1.02	3.4	8	ON	28 Pin	OFF	Removed	Disabled
03:10:05:8	23.18	3399	3.74	13.56	100	189	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	9.23	14.96	1.02	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:10:05:8	23.18	3390	3.75	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	9.38	14.91	1.02	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled
03:10:05:8	23.18	3388	3.77	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	9.64	14.88	1.01	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:10:05:9	21.81	3391	3.78	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	9.67	14.88	1.01	3.5	10.7	ON	28 Pin	OFF	Removed	Disabled
03:10:05:9	21.81	3424	3.79	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	9.75	14.88	1.01	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:10:05:9	21.81	3441	3.8	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	9.94	14.85	1.01	3.5	11	ON	28 Pin	OFF	Removed	Disabled
03:10:05:9	21.81	3486	3.81	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	10.03	14.72	1	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:10:05:9	23.18	3516	3.82	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	10.2	14.55	0.99	3.4	11.1	ON	28 Pin	OFF	Removed	Disabled
03:10:05:9	23.18	3512	3.83	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	10.34	14.26	0.97	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:10:05:9	23.18	3515	3.84	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	10.45	14.05	0.96	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:10:06:0	23.18	3517	3.85	13.55	100	189	Off Idle	41.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	10.53	13.83	0.94	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:10:06:0	23.18	3514	3.86	13.55	100	189	Off Idle	41.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	10.65	13.58	0.92	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:10:06:0	23.18	3510	3.87	13.56	100	189	Off Idle	41.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	10.77	13.17	0.9	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:10:06:0	23.18	3510	3.88	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	11	12.9	0.88	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:10:06:0	23.18	3519	3.89	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	11.16	12.64	0.86	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:10:06:0	23.18	3519	3.91	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	11.27	12.42	0.85	3.5	12	ON	28 Pin	OFF	Removed	Disabled
03:10:06:1	21.81	3528	3.92	13.55	100	189	Off Idle	41.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	11.45	12.17	0.83	3.5	12	ON	28 Pin	OFF	Removed	Disabled
03:10:06:1	21.81	3548	3.93	13.55	100	189	Off Idle	41.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	11.63	12.04	0.82	3.5	12	ON	28 Pin	OFF	Removed	Disabled
03:10:06:1	21.81	3562	3.93	13.53	100	189	Off Idle	41.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	11.79	11.93	0.81	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:1	21.81	3563	3.95	13.55	100	189	Off Idle	41.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	11.96	11.85	0.81	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:10:06:1	21.81	3578	3.96	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	12.08	11.78	0.8	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:10:06:1	21.81	3584	3.97	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	12.29	11.72	0.8	3.5	12.7	ON	28 Pin	OFF	Removed	Disabled
03:10:06:1	21.81	3611	3.98	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	12.4	11.66	0.79	3.4	12.7	ON	28 Pin	OFF	Removed	Disabled
03:10:06:2	21.81	3627	4	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.39	11.61	0.79	3.4	12.8	ON	28 Pin	OFF	Removed	Disabled
03:10:06:2	21.81	3684	4.01	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	12.73	11.56	0.79	3.4	12.8	ON	28 Pin	OFF	Removed	Disabled
03:10:06:2	21.81	3678	4.02	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	12.96	11.53	0.79	3.4	12.9	ON	28 Pin	OFF	Removed	Disabled
03:10:06:2	21.81	3686	4.03	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	13.05	11.49	0.78	3.4	13.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:2	21.81	3699	4.05	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	13.35	11.44	0.78	3.4	13.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:2	21.81	3701	4.06	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	13.61	11.38	0.78	3.4	13.7	ON	28 Pin	OFF	Removed	Disabled
03:10:06:3	21.81	3710	4.08	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	13.94	11.3	0.77	3.4	13.9	ON	28 Pin	OFF	Removed	Disabled
03:10:06:3	21.81	3700	4.09	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	14.11	11.28	0.77	3.5	14.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:3	21.81	3711	4.1	13.52	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	14.33	11.25	0.77	3.5	14.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:3	21.81	3724	4.11	13.51	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	14.44	11.18	0.76	3.5	14.4	ON	28 Pin	OFF	Removed	Disabled
03:10:06:3	21.81	3724	4.13	13.53	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	14.35	11.12	0.76	3.5	14.7	ON	28 Pin	OFF	Removed	Disabled
03:10:06:3	20.45	3714	4.14	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	14.48	11.05	0.75	3.5	14.6	ON	28 Pin	OFF	Removed	Disabled
03:10:06:4	20.45	3706	4.16	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	14.77	10.98	0.75	3.5	14.7	ON	28 Pin	OFF	Removed	Disabled
03:10:06:4	20.45	3712	4.17	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	15	10.89	0.74	3.5	15	ON	28 Pin	OFF	Removed	Disabled
03:10:06:4	20.45	3753	4.18	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	15.34	10.84	0.74	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:4	20.45	3754	4.19	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	15.73	10.77	0.73	3.4	15.2	ON	28 Pin	OFF	Removed	Disabled
03:10:06:4	20.45	3794	4.2	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	15.8	10.71	0.73	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:4	20.45	3826	4.22	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	16.09	10.6	0.72	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:4	20.45	3855	4.23	13.53	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	16.08	10.57	0.72	3.4	15	ON	28 Pin	OFF	Removed	Disabled
03:10:06:5	21.81	3874	4.25	13.51	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	16.19	10.54	0.72	3.3	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:5	21.81	3874	4.26	13.53	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	15.98	10.46	0.71	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:5	21.81	3890	4.26	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	15.99	10.42	0.71	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:5	21.81	3901	4.27	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.7	16.12	10.4	0.71	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:5	21.81	3900	4.28	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.7	16.3	10.35	0.7	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:06:5	21.81	3920	4.29	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	16.49	10.3	0.7	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:6	21.81	3882	4.3	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	16.75	10.28	0.7	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:6	21.81	3886	4.31	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.7	16.79	10.26	0.7	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:6	21.81	3915	4.32	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	16.8	10.23	0.7	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:6	20.45	3906	4.32	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	16.81	10.23	0.7	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:6	20.45	3941	4.33	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.7	16.93	10.21	0.7	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:6	20.45	3940	4.34	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	17.11	10.2	0.69	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:6	20.45	3970	4.34	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	17.22	10.22	0.7	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:7	20.45	4006	4.35	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.2	10.25	0.7	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:7	21.81	4032	4.35	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.21	10.28	0.7	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:7	21.81	4036	4.36	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17	10.31	0.7	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:7	21.81	4047	4.36	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	16.94	10.37	0.71	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:7	21.81	4047	4.37	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.1	10.41	0.71	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:7	20.45	4079	4.37	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.21	10.44	0.71	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:8	20.45	4080	4.38	13.53	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.3	10.51	0.72	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:8	20.45	4078	4.38	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.35	10.57	0.72	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:8	20.45	4126	4.38	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.27	10.64	0.72	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:8	21.81	4126	4.39	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.28	10.65	0.73	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:8	21.81	4100	4.39	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.18	10.67	0.73	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:8	21.81	4115	4.39	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.7	17.27	10.71	0.73	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:9	21.81	4112	4.4	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.7	17.4	10.75	0.73	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:9	20.45	4116	4.4	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.7	17.42	10.79	0.74	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:9	20.45	4152	4.4	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.7	17.4	10.86	0.74	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:9	20.45	4148	4.4	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.7	17.35	10.86	0.74	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:9	20.45	4167	4.41	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.6	10.93	0.74	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:9	20.45	4187	4.41	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.69	10.97	0.75	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:06:9	21.81	4210	4.41	13.52	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.98	11.03	0.75	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:0	21.81	4211	4.42	13.52	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	18.11	11.11	0.76	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:0	21.81	4256	4.42	13.52	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.7	17.93	11.16	0.76	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:0	21.81	4257	4.42	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.7	17.75	11.17	0.76	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:0	20.45	4290	4.42	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	17.5	11.19	0.76	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:0	20.45	4292	4.42	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.6	17.52	11.22	0.76	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:0	20.45	4294	4.42	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.92	Rich	1	14.7	17.45	11.26	0.77	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:1	20.45	4308	4.43	13.57	99	189	Off Idle	41.7	0	2	132	944 Turbo	0.93	Rich	1	14.6	17.43	11.32	0.77	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:1	20.45	4344	4.43	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.59	11.35	0.77	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:1	21.81	4331	4.43	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.83	11.38	0.78	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:1	21.81	4326	4.43	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.7	18.04	11.41	0.78	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:1	21.81	4350	4.43	13.53	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	18.31	11.4	0.78	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:1	21.81	4360	4.43	13.5	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	18.42	11.42	0.78	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:1	21.81	4375	4.44	13.49	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	18.29	11.44	0.78	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:2	21.81	4376	4.44	13.48	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	18.39	11.51	0.78	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:2	21.81	4391	4.44	13.51	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	18.17	11.53	0.79	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:2	21.81	4409	4.44	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	17.99	11.56	0.79	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:2	21.81	4409	4.44	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	17.73	11.58	0.79	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:2	21.81	4422	4.44	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	17.45	11.61	0.79	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:2	21.81	4446	4.44	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	17.27	11.64	0.79	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:3	21.81	4446	4.45	13.58	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	17.28	11.69	0.8	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:3	21.81	4448	4.45	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	17.4	11.72	0.8	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:3	21.81	4470	4.45	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	17.43	11.77	0.8	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:3	21.81	4483	4.45	13.52	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	17.67	11.8	0.8	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:3	21.81	4490	4.45	13.51	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	17.87	11.86	0.81	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:3	21.81	4550	4.45	13.49	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	17.99	11.89	0.81	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:4	21.81	4536	4.45	13.52	100	189	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.83	11.93	0.81	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:4	21.81	4538	4.45	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.67	11.95	0.81	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:4	21.81	4552	4.45	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	17.51	11.95	0.81	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:4	21.81	4566	4.45	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	17.36	12.02	0.82	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:4	21.81	4596	4.45	13.53	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.51	12.06	0.82	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:4	21.81	4594	4.46	13.51	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.73	12.09	0.82	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:07:4	21.81	4620	4.46	13.52	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.84	12.1	0.82	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:5	21.81	4601	4.46	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.74	12.11	0.82	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:5	21.81	4600	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.58	12.09	0.82	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:5	21.81	4625	4.46	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	17.44	12.1	0.82	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:5	23.18	4668	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	17.35	12.13	0.83	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:5	23.18	4658	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.43	12.21	0.83	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:5	23.18	4680	4.46	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.4	12.2	0.83	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:6	23.18	4715	4.46	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	17.36	12.19	0.83	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:6	23.18	4727	4.46	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	17.35	12.2	0.83	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:6	23.18	4739	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	17.37	12.23	0.83	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:6	23.18	4738	4.46	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	17.3	12.25	0.83	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:6	23.18	4742	4.46	13.56	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	17.28	12.25	0.83	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:6	23.18	4748	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	17.05	12.28	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:6	23.18	4762	4.46	13.56	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	16.83	12.29	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:7	23.18	4766	4.46	13.56	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	16.79	12.32	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:7	23.18	4777	4.46	13.56	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	16.79	12.34	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:7	23.18	4793	4.46	13.56	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	16.77	12.34	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:7	23.18	4796	4.46	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	16.73	12.34	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:7	23.18	4834	4.46	13.53	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	16.79	12.35	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:7	23.18	4806	4.46	13.54	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.68	12.34	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:8	23.18	4827	4.46	13.55	100	189	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.58	12.35	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:8	23.18	4832	4.46	13.54	100	189	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.62	12.37	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:8	23.18	4854	4.46	13.55	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.59	12.4	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:8	23.18	4874	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	16.39	12.4	0.85	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:8	23.18	4881	4.46	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.57	12.39	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:8	23.18	4912	4.46	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	16.63	12.41	0.85	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:9	23.18	4954	4.46	13.53	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.62	12.41	0.85	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:9	24.54	4941	4.46	13.53	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.68	12.43	0.85	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:9	24.54	4956	4.46	13.53	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.63	12.4	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:9	24.54	4958	4.46	13.54	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.49	12.4	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:9	24.54	4974	4.46	13.53	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	16.37	12.36	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:9	24.54	5004	4.46	13.53	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	16.17	12.35	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:07:9	24.54	4996	4.46	13.5	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.15	12.34	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:0	24.54	4996	4.46	13.5	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.15	12.34	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:0	24.54	4992	4.46	13.52	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	16.19	12.34	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:0	24.54	5002	4.46	13.53	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	16.28	12.28	0.84	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:0	24.54	5057	4.46	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	16.21	12.31	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:0	24.54	5034	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	16.21	12.33	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:0	24.54	5038	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	16.21	12.38	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:1	24.54	5056	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	16.2	12.4	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:1	24.54	5068	4.46	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	16.02	12.38	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:1	24.54	5094	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	15.98	12.37	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:1	24.54	5094	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	15.96	12.34	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:1	24.54	5103	4.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	16	12.34	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:1	24.54	5108	4.46	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	15.79	12.36	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:1	24.54	5159	4.46	13.53	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	15.88	12.39	0.84	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:2	24.54	5138	4.46	13.51	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	15.82	12.41	0.85	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:2	24.54	5142	4.46	13.53	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	15.7	12.41	0.85	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:2	24.54	5145	4.46	13.52	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	15.65	12.43	0.85	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:2	24.54	5174	4.46	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	15.59	12.47	0.85	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:2	24.54	5192	4.46	13.53	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	15.63	12.51	0.85	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:2	24.54	5192	4.46	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	15.5	12.56	0.86	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:3	24.54	5197	4.46	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	15.42	12.59	0.86	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:3	24.54	5216	4.46	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	14.66	12.62	0.86	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:3	25.9	5236	4.46	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	13.88	12.61	0.86	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:3	25.9	5209	4.45	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	12.28	12.61	0.86	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:3	25.9	5152	4.41	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	9.98	12.57	0.86	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:08:3	25.9	4987	4.33	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.89	12.55	0.85	3.6	0.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:08:4	32.72	5064	4.13	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	2.29	12.48	0.85	3.6	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:08:4	32.72	4862	3.93	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.52	12.29	0.84	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:08:4	32.72	4782	3.72	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.58	12.12	0.83	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:08:4	32.72	4741	3.51	13.53	99	189	Full Load	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.98	11.93	0.81	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:08:4	32.72	4744	3.29	13.52	99	189	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.99	11.79	0.8	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:08:4	34.08	4667	3.08	13.53	99	189	Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.82	11.74	0.8	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:08:4	34.08	4662	2.77	13.52	99	189	Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.74	11.87	0.81	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:5	34.08	4619	2.66	13.52	99	189	Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.24	11.94	0.81	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:5	28.63	4588	2.35	13.54	99	189	Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	12.22	0.83	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:5	23.18	4634	2.13	13.56	99	189	Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.14	12.41	0.85	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:5	20.45	4624	1.92	13.59	99	189	Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.32	12.51	0.85	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:5	20.45	4589	1.71	13.62	99	189	Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.68	12.68	0.86	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:5	20.45	4574	1.51	13.63	99	189	Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.96	12.79	0.87	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:6	20.45	4519	1.32	13.64	99	189	Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.08	12.87	0.88	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:6	20.45	4456	1.04	13.64	99	189	Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.44	12.97	0.88	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:6	20.45	4456	0.95	13.64	99	189	Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.51	12.94	0.88	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:6	20.45	4418	0.78	13.62	99	189	Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.7	12.71	0.87	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:6	20.45	4374	0.65	13.61	99	189	Idle	41.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.7	12.48	0.85	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:6	20.45	4269	0.56	13.6	99	189	Idle	40.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.77	12.21	0.83	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:6	20.45	4294	0.53	13.58	99	189	Idle	39.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.77	11.85	0.81	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:7	20.45	4285	0.6	13.58	99	189	Idle	37.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.75	11.75	0.8	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:7	20.45	4255	0.67	13.6	99	189	Idle	36.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.72	11.63	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:7	20.45	4182	0.74	13.6	99	189	Full Load	35.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.7	11.66	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:7	20.45	4168	0.85	13.59	99	189	Full Load	33.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.65	11.81	0.8	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:7	20.45	4147	0.88	13.6	99	189	Off Idle	31	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.63	12.04	0.82	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:7	12.27	4032	1.01	13.6	99	189	Off Idle	29.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.48	12.52	0.85	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:08:8	14.99	4083	1.1	13.61	99	189	Off Idle	29.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.31	13.15	0.9	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:08:8	17.72	4070	1.19	13.61	99	189	Off Idle	29.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.09	13.98	0.95	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:8	20.45	4064	1.34	13.58	99	189	Off Idle	29.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.84	14.84	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:08:8	23.18	4028	1.5	13.57	99	189	Off Idle	30	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.46	16.54	1.13	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:08:8	25.9	3958	1.55	13.57	99	189	Off Idle	30.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.08	17.34	1.18	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:08:8	28.63	3951	1.66	13.57	99	189	Off Idle	31.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.63	18.07	1.23	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:08:9	31.36	3922	1.76	13.58	99	189	Off Idle	32.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.06	19.05	1.3	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:08:9	34.08	3912	1.87	13.61	99	189	Off Idle	34.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.42	19.66	1.34	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:08:9	36.81	3852	1.98	13.61	99	189	Off Idle	35.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6	20.06	1.37	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:10:08:9	36.81	3718	2.13	13.61	99	189	Off Idle	37.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-4.78	20.22	1.38	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:08:9	36.81	3709	2.23	13.61	99	189	Off Idle	38.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-4.02	20.23	1.38	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:08:9	36.81	3658	2.38	13.6	99	189	Off Idle	40.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-2.9	20.24	1.38	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:10:08:9	36.81	3644	2.48	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-2.38	20.23	1.38	3.7	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:09:0	36.81	3591	2.57	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-1.91	20.24	1.38	3.7	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:09:0	34.08	3435	2.69	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-1.33	20.25	1.38	3.7	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:09:0	34.08	3510	2.77	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-1.02	20.24	1.38	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:0	34.08	3510	2.84	13.6	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-0.93	20.25	1.38	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:0	34.08	3501	2.94	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-0.58	20.14	1.37	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:0	34.08	3509	3	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-0.49	19.95	1.36	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:1	34.08	3525	3.05	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-0.34	19.67	1.34	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:09:1	34.08	3556	3.12	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-0.1	19.1	1.3	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:09:1	34.08	3558	3.17	13.57	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	0.02	18.9	1.29	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:09:1	34.08	3566	3.2	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	0.04	18.13	1.24	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:1	34.08	3580	3.24	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	0.23	17.55	1.2	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:1	34.08	3580	3.26	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.28	16.9	1.15	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:1	34.08	3560	3.27	13.6	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.39	15.93	1.09	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:2	34.08	3556	3.28	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.44	15.35	1.05	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:2	34.08	3544	3.29	13.6	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.48	14.89	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:2	32.72	3530	3.29	13.6	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.58	14.51	0.99	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:2	32.72	3544	3.28	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.68	14.08	0.96	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:09:2	32.72	3560	3.28	13.61	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.72	13.87	0.94	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:09:2	32.72	3564	3.28	13.57	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.89	13.73	0.94	3.4	5.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:09:3	32.72	3582	3.29	13.56	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.98	13.64	0.93	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:09:3	32.72	3592	3.3	13.57	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.04	13.64	0.93	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:09:3	32.72	3592	3.31	13.56	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.11	13.64	0.93	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:09:3	32.72	3592	3.31	13.57	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.1	13.67	0.93	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:09:3	32.72	3592	3.32	13.6	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.26	13.67	0.93	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:09:3	32.72	3598	3.33	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.37	13.66	0.93	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:09:4	32.72	3576	3.33	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.59	13.64	0.93	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:10:09:4	32.72	3577	3.34	13.57	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.61	13.62	0.93	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:4	32.72	3580	3.34	13.57	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.61	13.62	0.93	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:4	32.72	3566	3.35	13.57	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.69	13.59	0.93	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:4	31.36	3566	3.35	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.67	13.56	0.92	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:4	31.36	3600	3.36	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.77	13.55	0.92	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:4	31.36	3598	3.37	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.81	13.52	0.92	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:5	31.36	3609	3.37	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.9	13.51	0.92	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:09:5	31.36	3610	3.38	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.96	13.51	0.92	3.4	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:09:5	31.36	3640	3.38	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2	13.52	0.92	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:09:5	31.36	3627	3.39	13.6	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.14	13.53	0.92	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:10:09:5	31.36	3626	3.39	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.31	13.56	0.92	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:09:5	31.36	3623	3.4	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	2.32	13.57	0.92	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:10:09:6	29.99	3598	3.41	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	2.47	13.54	0.92	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:10:09:6	29.99	3628	3.41	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	2.52	13.55	0.92	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:10:09:6	29.99	3628	3.42	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.57	13.56	0.92	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:09:6	29.99	3626	3.42	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.73	13.56	0.92	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:09:6	29.99	3644	3.43	13.59	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.91	13.57	0.92	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:09:6	29.99	3641	3.43	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.02	13.58	0.93	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:10:09:6	29.99	3634	3.44	13.59	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.94	13.6	0.93	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:10:09:7	29.99	3660	3.45	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.07	13.6	0.93	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:10:09:7	29.99	3668	3.45	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.08	13.63	0.93	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:10:09:7	29.99	3696	3.46	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.09	13.68	0.93	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:10:09:7	29.99	3682	3.46	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.29	13.69	0.93	3.6	6.4	ON	28 Pin	OFF	Removed	Disabled
03:10:09:7	29.99	3661	3.47	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.36	13.7	0.93	3.6	6.5	ON	28 Pin	OFF	Removed	Disabled
03:10:09:7	29.99	3660	3.48	13.57	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.36	13.73	0.94	3.6	6.5	ON	28 Pin	OFF	Removed	Disabled
03:10:09:8	29.99	3662	3.48	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.51	13.74	0.94	3.6	6.5	ON	28 Pin	OFF	Removed	Disabled
03:10:09:8	29.99	3636	3.49	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.63	13.76	0.94	3.6	6.5	ON	28 Pin	OFF	Removed	Disabled
03:10:09:8	29.99	3670	3.49	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.61	13.76	0.94	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:8	29.99	3668	3.5	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.7	13.77	0.94	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:8	29.99	3679	3.5	13.53	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.83	13.76	0.94	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:8	29.99	3679	3.51	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.95	13.75	0.94	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:10:09:9	28.63	3692	3.52	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.94	13.75	0.94	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:9	28.63	3696	3.52	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.11	13.75	0.94	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:9	28.63	3694	3.52	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.08	13.75	0.94	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:9	28.63	3692	3.53	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.17	13.74	0.94	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:9	28.63	3692	3.54	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.38	13.72	0.93	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:10:09:9	28.63	3692	3.54	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.38	13.72	0.93	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:10:09:9	28.63	3702	3.55	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	4.46	13.72	0.93	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:10:10:0	28.63	3704	3.55	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.62	13.72	0.93	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:10:0	28.63	3710	3.56	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.71	13.75	0.94	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:10:0	28.63	3710	3.56	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.81	13.75	0.94	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:10:0	28.63	3722	3.57	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.01	13.78	0.94	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:10:0	28.63	3733	3.58	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.21	13.79	0.94	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:10:0	28.63	3731	3.59	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.2	13.8	0.94	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:1	28.63	3731	3.59	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.19	13.81	0.94	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:1	28.63	3734	3.6	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	5.28	13.81	0.94	3.4	7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:1	28.63	3737	3.6	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.37	13.8	0.94	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:10:1	28.63	3740	3.61	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.45	13.8	0.94	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:10:1	28.63	3750	3.62	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.59	13.79	0.94	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:10:1	27.27	3736	3.63	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	5.56	13.78	0.94	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:10:1	27.27	3751	3.63	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	5.67	13.78	0.94	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:10:2	27.27	3751	3.64	13.58	99	189	Off Idle	41.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	5.63	13.78	0.94	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:10:10:2	27.27	3750	3.64	13.57	99	189	Off Idle	41.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	5.72	13.78	0.94	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:10:10:2	27.27	3744	3.65	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	5.75	13.8	0.94	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:10:10:2	28.63	3761	3.66	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	5.86	13.83	0.94	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:10:2	28.63	3764	3.67	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	6.1	13.84	0.94	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:10:2	28.63	3785	3.67	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	6.12	13.86	0.94	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:10:3	28.63	3799	3.68	13.59	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	6.07	13.88	0.95	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:10:3	28.63	3798	3.69	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	6.22	13.88	0.95	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:10:10:3	28.63	3822	3.7	13.59	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	6.14	13.86	0.94	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:10:3	28.63	3784	3.7	13.59	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	6.34	13.85	0.94	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:10:3	28.63	3780	3.71	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	6.38	13.85	0.94	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:10:3	28.63	3782	3.72	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	6.37	13.81	0.94	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:4	27.27	3780	3.72	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	6.5	13.81	0.94	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:4	27.27	3785	3.72	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	6.62	13.8	0.94	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:4	27.27	3787	3.73	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	6.7	13.8	0.94	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:4	27.27	3798	3.74	13.59	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	6.83	13.8	0.94	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:4	27.27	3822	3.74	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	6.92	13.8	0.94	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:4	27.27	3825	3.75	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.09	13.82	0.94	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:4	27.27	3826	3.75	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.18	13.83	0.94	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:5	27.27	3832	3.76	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.1	13.83	0.94	3.5	7.6	ON	28 Pin	OFF	Removed	Disabled
03:10:10:5	27.27	3829	3.76	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.18	13.86	0.94	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:5	27.27	3829	3.77	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.28	13.86	0.94	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:5	27.27	3822	3.78	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.46	13.88	0.95	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:10:10:5	27.27	3827	3.79	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.54	13.9	0.95	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:10:10:5	27.27	3826	3.79	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.62	13.9	0.95	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:10:10:6	27.27	3814	3.8	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.8	13.9	0.95	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:10:10:6	25.9	3833	3.8	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.85	13.91	0.95	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:10:10:6	25.9	3864	3.81	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	7.82	13.95	0.95	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:10:10:6	25.9	3866	3.82	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	7.91	13.98	0.95	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:10:10:6	25.9	3863	3.82	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	8.06	13.98	0.95	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:10:10:6	27.27	3865	3.83	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	8.2	14	0.95	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:10:10:6	27.27	3862	3.84	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	8.23	13.97	0.95	3.5	8.2	ON	28 Pin	OFF	Removed	Disabled
03:10:10:7	27.27	3885	3.85	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	8.36	13.96	0.95	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:10:10:7	27.27	3885	3.85	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	8.41	13.96	0.95	3.4	8.3	ON	28 Pin	OFF	Removed	Disabled
03:10:10:7	27.27	3889	3.86	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	8.36	13.98	0.95	3.4	8.3	ON	28 Pin	OFF	Removed	Disabled
03:10:10:7	27.27	3879	3.87	13.57	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	8.39	13.99	0.95	3.5	8.2	ON	28 Pin	OFF	Removed	Disabled
03:10:10:7	27.27	3880	3.87	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	8.52	13.96	0.95	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:10:10:7	27.27	3887	3.88	13.6	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	8.77	13.93	0.95	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:10:10:8	27.27	3892	3.89	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	8.95	13.92	0.95	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:10:10:8	27.27	3861	3.89	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	9.07	13.92	0.95	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:8	25.9	3890	3.9	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	9.09	13.95	0.95	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:8	25.9	3888	3.9	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	9.19	13.92	0.95	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:8	25.9	3900	3.91	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	9.29	13.93	0.95	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:8	25.9	3908	3.91	13.58	99	189	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	9.5	13.93	0.95	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:9	25.9	3908	3.92	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	9.62	13.92	0.95	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:10:10:9	25.9	3922	3.93	13.54	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.59	13.93	0.95	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:10:10:9	25.9	3925	3.94	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.55	13.93	0.95	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:10:10:9	25.9	3924	3.94	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.58	13.93	0.95	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:9	25.9	3946	3.94	13.59	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.64	13.91	0.95	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:9	25.9	3942	3.95	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.96	13.92	0.95	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:10:10:9	25.9	3938	3.95	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	10.06	13.92	0.95	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:10:11:0	25.9	3944	3.96	13.52	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	10.11	13.91	0.95	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:10:11:0	25.9	3956	3.97	13.5	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	10.02	13.9	0.95	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:10:11:0	25.9	3940	3.97	13.51	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.78	13.89	0.95	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:10:11:0	25.9	3940	3.98	13.51	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.83	13.88	0.95	3.4	8.7	ON	28 Pin	OFF	Removed	Disabled
03:10:11:0	25.9	3971	3.98	13.52	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.91	13.87	0.95	3.4	8.8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:0	25.9	3986	3.98	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.86	13.86	0.94	3.4	8.7	ON	28 Pin	OFF	Removed	Disabled
03:10:11:1	25.9	3986	3.99	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.88	13.85	0.94	3.4	8.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:11:1	25.9	3982	3.99	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.97	13.86	0.94	3.4	8.5	ON	28 Pin	OFF	Removed	Disabled
03:10:11:1	25.9	3968	3.99	13.56	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.83	13.85	0.94	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:10:11:1	25.9	3968	3.99	13.56	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.85	13.89	0.95	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:10:11:1	25.9	3954	3.99	13.56	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.81	13.9	0.95	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:10:11:1	24.54	3956	3.99	13.55	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.77	13.89	0.95	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:10:11:1	24.54	3967	3.99	13.55	99	189	Off Idle	41.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.58	13.89	0.95	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:10:11:2	24.54	3968	3.99	13.55	99	189	Off Idle	41.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.41	13.9	0.95	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:10:11:2	24.54	3970	3.99	13.57	99	189	Off Idle	41.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.36	13.92	0.95	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:10:11:2	25.9	3996	3.98	13.56	99	189	Off Idle	41.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.44	13.93	0.95	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:10:11:2	25.9	4025	3.98	13.57	98	189	Off Idle	41.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.44	13.94	0.95	3.4	7.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:2	25.9	4026	3.98	13.59	98	189	Off Idle	41.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.35	13.95	0.95	3.4	7.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:2	25.9	4042	3.97	13.59	98	189	Off Idle	41.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.3	13.97	0.95	3.4	7.8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:3	25.9	4028	3.97	13.59	98	189	Off Idle	41.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	9.15	13.99	0.95	3.4	7.8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:3	25.9	4028	3.97	13.59	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	8.95	14.03	0.96	3.5	10	ON	28 Pin	OFF	Removed	Disabled
03:10:11:3	25.9	4031	3.96	13.61	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	8.9	14.08	0.96	3.5	10	ON	28 Pin	OFF	Removed	Disabled
03:10:11:3	25.9	4035	3.96	13.6	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	9.01	14.14	0.96	3.5	10	ON	28 Pin	OFF	Removed	Disabled
03:10:11:3	25.9	4039	3.95	13.59	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	9.05	14.19	0.97	3.5	9.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:3	25.9	4041	3.95	13.58	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	8.98	14.2	0.97	3.5	9.7	ON	28 Pin	OFF	Removed	Disabled
03:10:11:4	25.9	4045	3.94	13.57	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	8.81	14.18	0.97	3.5	9.6	ON	28 Pin	OFF	Removed	Disabled
03:10:11:4	25.9	4053	3.93	13.58	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	8.49	14.07	0.96	3.5	9.5	ON	28 Pin	OFF	Removed	Disabled
03:10:11:4	27.27	4043	3.93	13.58	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.32	13.92	0.95	3.5	9.5	ON	28 Pin	OFF	Removed	Disabled
03:10:11:4	27.27	4049	3.92	13.59	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	8.23	13.63	0.93	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:10:11:4	27.27	4048	3.92	13.59	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	8.21	13.41	0.91	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:10:11:4	27.27	4058	3.91	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	8.23	13.18	0.9	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:10:11:4	27.27	4071	3.91	13.52	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.1	12.94	0.88	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:10:11:5	27.27	4078	3.9	13.49	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.99	12.54	0.85	3.4	9.2	ON	28 Pin	OFF	Removed	Disabled
03:10:11:5	27.27	4078	3.89	13.51	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.86	12.31	0.84	3.4	9.2	ON	28 Pin	OFF	Removed	Disabled
03:10:11:5	27.27	4089	3.89	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.68	12.12	0.83	3.4	8.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:5	28.63	4114	3.88	13.57	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.46	12.03	0.82	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:5	28.63	4088	3.88	13.59	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.39	11.96	0.81	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:5	28.63	4086	3.87	13.57	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	7.38	11.93	0.81	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:6	28.63	4080	3.86	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.34	11.93	0.81	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:6	28.63	4082	3.86	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.26	11.93	0.81	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:6	28.63	4087	3.85	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	7.22	11.93	0.81	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:6	28.63	4095	3.84	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	7.18	11.96	0.81	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:6	28.63	4096	3.84	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.97	11.96	0.82	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:10:11:6	28.63	4099	3.84	13.53	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.87	11.99	0.82	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:10:11:6	28.63	4108	3.83	13.53	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.87	11.99	0.82	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:10:11:7	28.63	4120	3.83	13.53	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.67	11.99	0.82	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:10:11:7	28.63	4119	3.82	13.58	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.49	11.98	0.82	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:10:11:7	28.63	4124	3.82	13.58	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.36	12	0.82	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:10:11:7	28.63	4125	3.81	13.6	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.36	11.99	0.82	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:10:11:7	28.63	4128	3.81	13.6	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.28	11.98	0.82	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:10:11:7	28.63	4128	3.8	13.57	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	6.16	11.99	0.82	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:8	28.63	4146	3.79	13.55	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	6	11.99	0.82	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:8	29.99	4126	3.79	13.52	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.78	12	0.82	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:8	29.99	4130	3.78	13.52	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.62	12.01	0.82	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:10:11:8	29.99	4132	3.76	13.53	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.14	12.03	0.82	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:10:11:8	29.99	4142	3.76	13.56	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.02	12.07	0.82	3.4	7.3	ON	28 Pin	OFF	Removed	Disabled
03:10:11:8	29.99	4150	3.74	13.6	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.88	12.06	0.82	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:10:11:9	29.99	4169	3.73	13.59	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.73	12.13	0.83	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:10:11:9	29.99	4154	3.72	13.58	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.69	12.18	0.83	3.4	7.1	ON	28 Pin	OFF	Removed	Disabled
03:10:11:9	29.99	4156	3.72	13.57	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.56	12.24	0.83	3.4	6.9	ON	28 Pin	OFF	Removed	Disabled
03:10:11:9	29.99	4156	3.7	13.58	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.21	12.26	0.84	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:9	29.99	4152	3.69	13.58	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.08	12.32	0.84	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:10:11:9	29.99	4154	3.66	13.58	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.72	12.38	0.84	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:10:11:9	29.99	4159	3.65	13.57	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.56	12.43	0.85	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:10:12:0	31.36	4152	3.64	13.56	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	3.37	12.45	0.85	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:12:0	31.36	4159	3.61	13.53	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	2.86	12.53	0.85	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:10:12:0	31.36	4162	3.59	13.52	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	2.52	12.6	0.86	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:10:12:0	31.36	4162	3.57	13.52	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	2.11	12.65	0.86	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:10:12:0	32.72	4201	3.55	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.58	12.67	0.86	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:10:12:0	32.72	4172	3.54	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.47	12.73	0.87	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:10:12:1	32.72	4175	3.5	13.54	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.13	12.79	0.87	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:10:12:1	32.72	4176	3.48	13.52	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.65	12.85	0.88	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:1	32.72	4176	3.45	13.52	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.23	12.88	0.88	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:10:12:1	34.08	4194	3.43	13.55	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.12	12.92	0.88	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:12:1	34.08	4176	3.4	13.55	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.5	12.98	0.88	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:12:1	34.08	4156	3.35	13.56	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.83	13	0.89	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:12:1	34.08	4157	3.32	13.56	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.16	13.01	0.89	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:12:2	35.45	4161	3.28	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.47	13.03	0.89	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:12:2	35.45	4162	3.25	13.52	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.83	13.04	0.89	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:12:2	35.45	4174	3.22	13.52	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.19	13.04	0.89	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:12:2	35.45	4215	3.18	13.51	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.53	13.05	0.89	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:12:2	36.81	4198	3.14	13.5	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.97	13.07	0.89	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:12:2	36.81	4180	3.11	13.49	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.24	13.14	0.9	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:12:3	36.81	4173	3.08	13.5	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.5	13.21	0.9	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:3	36.81	4171	3.05	13.52	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.73	13.26	0.9	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:12:3	36.81	4168	3.01	13.55	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.02	13.34	0.91	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:12:3	36.81	4162	2.96	13.56	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.46	13.49	0.92	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:12:3	36.81	4161	2.92	13.57	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.77	13.61	0.93	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:12:3	36.81	4161	2.88	13.57	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.21	13.74	0.94	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:12:4	36.81	4160	2.8	13.54	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.74	13.86	0.94	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:12:4	36.81	4154	2.77	13.53	98	189	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.02	14.04	0.96	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:12:4	36.81	4148	2.72	13.54	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.68	14.13	0.96	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:12:4	36.81	4141	2.66	13.56	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.35	14.21	0.97	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:12:4	36.81	4142	2.59	13.59	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.97	14.26	0.97	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:12:4	36.81	4133	2.48	13.61	98	189	Full Load	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.74	14.3	0.97	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:4	36.81	4132	2.41	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.12	14.27	0.97	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:5	38.18	4075	2.34	13.64	98	189	Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.35	14.24	0.97	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:12:5	38.18	4080	2.23	13.63	98	189	Idle	38.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.66	14.17	0.97	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:12:5	38.18	4022	2.17	13.6	98	189	Idle	37.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.78	14.1	0.96	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:5	32.72	3971	2.1	13.58	98	189	Idle	35.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.89	14.03	0.96	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:5	27.27	3955	2.04	13.57	98	189	Idle	34.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.97	13.97	0.95	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:12:5	21.81	3972	1.96	13.56	98	189	Idle	32.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.96	13.93	0.95	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:6	20.45	4062	1.89	13.61	98	189	Idle	31.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.89	13.85	0.94	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:6	20.45	4104	1.86	13.62	98	189	Idle	29.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.89	13.83	0.94	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:6	20.45	4128	1.8	13.63	98	189	Idle	28.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.77	13.8	0.94	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:6	20.45	4158	1.76	13.6	98	189	Idle	27.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.73	13.8	0.94	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:6	20.45	4182	1.74	13.58	98	189	Idle	27.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.7	13.78	0.94	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:6	20.45	4220	1.72	13.55	98	189	Idle	27.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.69	13.78	0.94	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:6	20.45	4175	1.7	13.56	98	189	Idle	27.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.78	13.83	0.94	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:7	20.45	4170	1.69	13.57	98	189	Idle	27.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.83	13.88	0.95	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:7	20.45	4144	1.69	13.57	98	189	Idle	27.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.89	13.95	0.95	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:7	20.45	4120	1.69	13.58	98	189	Idle	30.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.99	14.17	0.97	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:7	20.45	4114	1.69	13.6	98	189	Idle	32	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.12	14.57	0.99	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:7	20.45	4080	1.7	13.59	98	189	Idle	33.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	15.15	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:7	20.45	4068	1.71	13.6	98	189	Idle	34.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	15.78	1.08	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:8	20.45	4064	1.72	13.62	98	189	Idle	36.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	16.43	1.12	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:8	20.45	4066	1.73	13.63	98	189	Idle	37.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	17.05	1.16	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:8	20.45	4074	1.73	13.64	98	189	Idle	39.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	17.36	1.18	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:8	20.45	4092	1.73	13.64	98	189	Idle	40.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	18.27	1.24	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:8	20.45	4104	1.73	13.63	98	189	Idle	39.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	18.57	1.26	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:8	20.45	4106	1.73	13.62	98	189	Idle	39.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	19.15	1.3	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:9	20.45	4117	1.73	13.6	98	189	Idle	39.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	19.92	1.36	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:9	20.45	4118	1.72	13.59	98	189	Idle	39.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.17	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:12:9	20.45	4111	1.72	13.57	98	189	Idle	39.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:9	20.45	4111	1.71	13.58	98	189	Idle	39.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:9	20.45	4106	1.7	13.59	98	189	Idle	39.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:9	20.45	4096	1.69	13.6	98	189	Idle	39.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:9	20.45	4088	1.69	13.62	98	189	Idle	39.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:0	20.45	4088	1.69	13.63	98	189	Idle	39.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:0	20.45	4081	1.7	13.64	98	189	Idle	39.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:0	20.45	4081	1.7	13.64	98	189	Idle	39.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:0	20.45	4064	1.71	13.63	98	189	Idle	40.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:0	20.45	4077	1.71	13.61	98	189	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:0	20.45	4079	1.71	13.6	98	189	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:1	20.45	4078	1.71	13.58	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:1	20.45	4073	1.71	13.56	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:1	20.45	4067	1.7	13.56	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:1	20.45	4067	1.7	13.58	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:1	20.45	4062	1.7	13.59	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:1	20.45	4055	1.7	13.61	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:1	20.45	4056	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:2	20.45	4050	1.69	13.61	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:2	20.45	4046	1.69	13.6	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:2	20.45	4046	1.69	13.59	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:2	20.45	4046	1.69	13.59	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:2	20.45	4046	1.69	13.59	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:2	20.45	4046	1.69	13.62	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:3	20.45	4050	1.69	13.62	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:3	20.45	4054	1.69	13.59	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:3	20.45	4054	1.69	13.58	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:3	20.45	4054	1.69	13.56	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:3	20.45	4053	1.69	13.54	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:3	20.45	4049	1.7	13.52	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:4	20.45	4050	1.7	13.52	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:4	20.45	4046	1.7	13.53	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:4	20.45	4040	1.7	13.53	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:4	20.45	4040	1.7	13.53	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:4	20.45	4036	1.7	13.53	98	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:4	20.45	4031	1.7	13.53	98	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:4	20.45	4030	1.7	13.56	98	189	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:5	20.45	4028	1.7	13.58	98	189	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:5	20.45	4024	1.7	13.61	98	190	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:5	20.45	4022	1.7	13.63	98	190	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:5	20.45	4020	1.7	13.64	98	190	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:5	20.45	4018	1.7	13.64	98	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:5	20.45	4018	1.7	13.64	98	189	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:6	20.45	4016	1.7	13.63	98	189	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:6	20.45	4012	1.71	13.63	98	189	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:6	20.45	4011	1.71	13.64	98	189	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:6	20.45	4007	1.7	13.64	98	189	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:6	20.45	4008	1.7	13.64	98	189	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:6	20.45	4008	1.7	13.63	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:6	20.45	4006	1.7	13.63	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:7	20.45	4012	1.7	13.63	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:7	20.45	4014	1.7	13.63	98	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:7	20.45	4016	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:7	20.45	4019	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:7	20.45	4018	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:7	20.45	4015	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:8	20.45	4012	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:8	20.45	4012	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:13:8	20.45	4005	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:8	20.45	4001	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:8	20.45	4000	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:8	20.45	3993	1.7	13.64	98	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:9	20.45	3986	1.7	13.64	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:9	20.45	3977	1.7	13.63	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:9	20.45	3980	1.7	13.62	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:9	20.45	3968	1.7	13.61	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:9	20.45	3960	1.7	13.57	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.26	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:9	20.45	3961	1.7	13.56	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:13:9	20.45	3941	1.7	13.55	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:0	20.45	3950	1.7	13.54	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:0	20.45	3956	1.7	13.54	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:0	20.45	3939	1.7	13.54	98	189	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:0	20.45	3954	1.7	13.58	98	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:0	20.45	3954	1.7	13.59	98	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:0	20.45	3973	1.7	13.61	98	189	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:1	20.45	3958	1.7	13.62	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:1	20.45	3951	1.7	13.61	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:1	20.45	3952	1.7	13.61	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:1	20.45	3950	1.7	13.61	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:1	20.45	3946	1.7	13.61	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:1	20.45	3938	1.7	13.61	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:1	20.45	3937	1.7	13.64	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:2	20.45	3936	1.7	13.65	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:2	20.45	3906	1.7	13.64	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:2	20.45	3918	1.7	13.64	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:2	20.45	3936	1.7	13.64	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:2	20.45	3954	1.7	13.64	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:2	20.45	3937	1.7	13.63	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:3	20.45	3938	1.7	13.64	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:3	20.45	3934	1.7	13.62	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:3	20.45	3926	1.7	13.59	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:3	20.45	3928	1.7	13.58	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:3	20.45	3908	1.7	13.56	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:3	20.45	3917	1.7	13.54	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:4	20.45	3917	1.7	13.54	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:4	20.45	3910	1.7	13.55	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:4	20.45	3907	1.7	13.57	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:4	20.45	3900	1.7	13.59	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:4	20.45	3900	1.7	13.62	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:4	20.45	3900	1.7	13.63	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:4	20.45	3909	1.7	13.64	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:5	20.45	3909	1.7	13.63	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:5	20.45	3912	1.7	13.62	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:5	20.45	3914	1.7	13.61	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:5	20.45	3914	1.7	13.61	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:5	20.45	3910	1.7	13.6	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:5	20.45	3905	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:6	20.45	3902	1.7	13.62	97	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:6	20.45	3900	1.7	13.61	97	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:6	20.45	3894	1.7	13.62	98	189	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:6	20.45	3892	1.7	13.64	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:6	20.45	3888	1.7	13.64	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:6	20.45	3888	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:6	20.45	3886	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:7	20.45	3884	1.7	13.6	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:7	20.45	3882	1.7	13.6	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:14:7	20.45	3881	1.7	13.6	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:7	20.45	3875	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:7	20.45	3874	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:7	20.45	3867	1.7	13.64	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:8	20.45	3863	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:8	20.45	3864	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:8	20.45	3862	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:8	20.45	3842	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:8	20.45	3861	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:8	20.45	3859	1.7	13.61	98	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:9	20.45	3861	1.7	13.62	98	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:9	20.45	3862	1.7	13.64	98	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:9	20.45	3863	1.7	13.63	98	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:9	20.45	3863	1.7	13.63	98	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:9	20.45	3858	1.7	13.62	98	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:9	20.45	3857	1.7	13.61	98	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:14:9	20.45	3818	1.7	13.61	97	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:0	20.45	3832	1.7	13.61	97	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:0	20.45	3842	1.7	13.59	97	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:0	20.45	3841	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:0	20.45	3838	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:0	20.45	3841	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:0	20.45	3842	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:1	20.45	3842	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:1	20.45	3838	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:1	20.45	3838	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:1	20.45	3836	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:1	20.45	3832	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:1	20.45	3834	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:1	20.45	3830	1.7	13.61	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:2	20.45	3829	1.7	13.61	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:2	20.45	3832	1.7	13.62	98	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:2	20.45	3828	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:2	20.45	3823	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:2	20.45	3820	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:2	20.45	3818	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:3	20.45	3819	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:3	20.45	3818	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:3	20.45	3813	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:3	20.45	3813	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:3	20.45	3807	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:3	20.45	3805	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:4	20.45	3804	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:4	20.45	3803	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:4	20.45	3804	1.7	13.62	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:4	20.45	3805	1.7	13.62	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:4	20.45	3804	1.7	13.62	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:4	20.45	3803	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:4	20.45	3797	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:5	20.45	3797	1.7	13.58	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:5	20.45	3795	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:5	20.45	3790	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:5	20.45	3791	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:5	20.45	3791	1.7	13.6	97	190	Full Load	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:5	20.45	3775	1.7	13.61	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:6	20.45	3784	1.7	13.61	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:6	20.45	3688	1.7	13.61	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:15:6	12.27	3810	1.7	13.63	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:15:6	14.99	3807	1.71	13.6	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:15:6	17.72	3805	1.71	13.6	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:15:6	20.45	3799	1.72	13.61	97	190	Off Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:15:6	23.18	3785	1.72	13.62	97	190	Off Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:15:7	25.9	3795	1.73	13.64	97	190	Off Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:15:7	28.63	3802	1.74	13.64	97	190	Off Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:15:7	31.36	3799	1.75	13.63	97	190	Off Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:7	34.08	3800	1.76	13.62	97	190	Off Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:7	39.54	3812	1.77	13.6	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:7	39.54	3788	1.78	13.6	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:15:8	39.54	3788	1.79	13.6	98	190	Off Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.13	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:15:8	39.54	3794	1.79	13.58	98	190	Off Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.17	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:8	39.54	3764	1.8	13.57	98	190	Off Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.23	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:8	39.54	3777	1.81	13.6	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.24	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:8	39.54	3782	1.82	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.24	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:8	39.54	3767	1.82	13.6	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.22	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:9	39.54	3748	1.83	13.61	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.14	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:9	39.54	3743	1.84	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.08	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:9	39.54	3742	1.85	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.08	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:9	39.54	3746	1.85	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.05	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:9	39.54	3747	1.85	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.08	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:15:9	39.54	3750	1.85	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.13	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:15:9	39.54	3760	1.86	13.61	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:0	39.54	3767	1.86	13.61	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:0	39.54	3772	1.86	13.6	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:16:0	39.54	3772	1.85	13.63	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:0	39.54	3771	1.85	13.62	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.2	20.1	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:0	39.54	3764	1.85	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.25	19.9	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:0	39.54	3760	1.85	13.58	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.29	19.66	1.34	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:1	39.54	3760	1.85	13.59	97	190	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.29	19.4	1.32	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:1	39.54	3744	1.85	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.27	19.1	1.3	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:1	39.54	3738	1.85	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.24	18.63	1.27	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:1	39.54	3736	1.85	13.62	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.19	18.29	1.25	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:16:1	39.54	3734	1.84	13.6	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.19	17.93	1.22	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:16:1	39.54	3734	1.84	13.59	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.2	17.54	1.2	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:1	39.54	3735	1.84	13.58	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.24	17.23	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:2	39.54	3738	1.84	13.58	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.29	16.98	1.16	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:2	39.54	3738	1.84	13.59	97	190	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.31	16.81	1.15	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:2	39.54	3739	1.84	13.57	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.31	16.65	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:2	39.54	3739	1.83	13.6	97	190	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.34	16.52	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:2	39.54	3746	1.82	13.62	97	190	Full Load	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.33	16.39	1.12	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:2	39.54	3748	1.82	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.34	16.28	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:16:3	39.54	3748	1.8	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.41	16.14	1.1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:3	39.54	3748	1.8	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.45	16.08	1.1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:3	39.54	3744	1.79	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.47	16.01	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:3	39.54	3749	1.78	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.49	15.93	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:3	39.54	3726	1.78	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.49	15.86	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:3	39.54	3725	1.77	13.61	97	190	Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.53	15.81	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:4	39.54	3712	1.76	13.6	97	190	Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.57	15.74	1.07	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:4	36.81	3652	1.75	13.6	97	190	Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-10.6	15.69	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:4	31.36	3645	1.75	13.62	97	190	Idle	41.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-10.59	15.64	1.07	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:4	25.9	3646	1.74	13.62	97	190	Idle	41	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.56	15.59	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:4	20.45	3672	1.73	13.61	97	190	Idle	41	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10.51	15.55	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:4	20.45	3724	1.73	13.61	97	190	Idle	40.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.5	15.51	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:4	20.45	3710	1.72	13.6	97	190	Idle	40.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.48	15.45	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:5	20.45	3696	1.71	13.6	97	190	Idle	39.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.49	15.4	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:5	20.45	3700	1.71	13.6	97	190	Idle	39.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.47	15.32	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:5	20.45	3704	1.7	13.6	97	190	Idle	39.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-10.45	15.29	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:16:5	20.45	3704	1.7	13.61	97	190	Idle	39.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-10.45	15.26	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:5	20.45	3712	1.71	13.61	97	190	Idle	39.2	0	2	132	944 Turbo	0.22	Rich	1	14.6	-10.44	15.19	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:5	20.45	3711	1.71	13.61	97	190	Idle	39.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.4	15.14	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:6	20.45	3707	1.71	13.61	97	190	Idle	39.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.43	15.04	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:6	20.45	3707	1.71	13.61	97	190	Idle	39.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.43	15.01	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:6	20.45	3704	1.71	13.61	97	190	Idle	39.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.42	14.93	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:6	20.45	3698	1.71	13.61	97	190	Idle	39.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.42	14.92	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:6	20.45	3696	1.71	13.59	97	190	Idle	39.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.48	14.86	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:6	20.45	3688	1.71	13.6	97	190	Idle	40.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.49	14.83	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:6	20.45	3683	1.71	13.59	97	190	Idle	40.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.44	14.77	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:7	20.45	3682	1.71	13.58	97	190	Idle	40.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.45	14.77	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:7	20.45	3682	1.71	13.58	97	190	Idle	41	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.47	14.64	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:7	20.45	3681	1.71	13.6	97	190	Idle	41.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.42	14.83	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:7	20.45	3681	1.71	13.59	97	190	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	15.08	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:7	20.45	3682	1.71	13.61	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	15.66	1.07	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:7	20.45	3681	1.71	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	16.18	1.1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:8	20.45	3681	1.71	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	16.72	1.14	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:8	20.45	3680	1.71	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	17.28	1.18	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:8	20.45	3676	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	18.1	1.23	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:8	20.45	3676	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	18.6	1.27	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:8	20.45	3658	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	19.23	1.31	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:8	20.45	3668	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	19.63	1.34	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:9	20.45	3663	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	19.94	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:9	20.45	3690	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.18	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:9	20.45	3677	1.7	13.61	97	190	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:9	20.45	3662	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:9	20.45	3665	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:9	20.45	3666	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:16:9	20.45	3665	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:0	20.45	3666	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:0	20.45	3667	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:0	20.45	3667	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:0	20.45	3650	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:0	20.45	3657	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:0	20.45	3654	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:1	20.45	3647	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:1	20.45	3648	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:1	20.45	3651	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:1	20.45	3644	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:1	20.45	3642	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:1	20.45	3642	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:1	20.45	3642	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:2	20.45	3641	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:2	20.45	3641	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:2	20.45	3642	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:2	20.45	3639	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:2	20.45	3636	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:2	20.45	3636	1.69	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:3	20.45	3632	1.69	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:3	20.45	3629	1.69	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:3	20.45	3628	1.69	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:3	20.45	3625	1.69	13.63	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:3	20.45	3625	1.69	13.63	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:3	20.45	3616	1.69	13.64	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:4	20.45	3612	1.69	13.64	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.18	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:4	20.45	3605	1.69	13.64	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:4	20.45	3605	1.69	13.64	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:4	20.45	3604	1.69	13.63	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:17:4	20.45	3604	1.69	13.61	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:4	20.45	3609	1.69	13.61	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:4	20.45	3607	1.69	13.62	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:5	20.45	3607	1.69	13.6	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:5	20.45	3613	1.69	13.61	97	190	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:5	20.45	3611	1.69	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:5	20.45	3610	1.69	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:5	20.45	3606	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:5	20.45	3604	1.69	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:6	20.45	3602	1.69	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:6	20.45	3602	1.69	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:6	20.45	3596	1.69	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:6	20.45	3594	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:6	20.45	3591	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:6	20.45	3590	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:6	20.45	3587	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:7	20.45	3586	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:7	20.45	3586	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:7	20.45	3584	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:7	20.45	3582	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:7	20.45	3582	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:7	20.45	3578	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:8	20.45	3575	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:8	20.45	3571	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:8	20.45	3570	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:8	20.45	3566	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:8	20.45	3562	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:8	20.45	3560	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:9	20.45	3556	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:9	20.45	3540	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:9	20.45	3550	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:9	20.45	3550	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:9	20.45	3552	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:9	20.45	3552	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:17:9	20.45	3552	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:0	20.45	3549	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:0	20.45	3549	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:0	20.45	3561	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:0	20.45	3546	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:0	20.45	3542	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:0	20.45	3540	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:1	20.45	3535	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:1	20.45	3535	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:1	20.45	3520	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:1	20.45	3525	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:1	20.45	3523	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:1	20.45	3520	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:1	20.45	3520	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:2	20.45	3517	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:2	20.45	3519	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:2	20.45	3516	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:2	20.45	3517	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:2	20.45	3517	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:2	20.45	3511	1.7	13.57	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:3	20.45	3511	1.7	13.58	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:3	20.45	3510	1.7	13.58	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:3	20.45	3506	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:3	20.45	3506	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:18:3	20.45	3507	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:3	20.45	3508	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:4	20.45	3510	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:4	20.45	3509	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:4	20.45	3511	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:4	20.45	3512	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:4	20.45	3511	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:4	20.45	3507	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:4	20.45	3506	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:5	20.45	3504	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:5	20.45	3504	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:5	20.45	3501	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:5	20.45	3494	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:5	20.45	3488	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:5	20.45	3485	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:6	20.45	3485	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:6	20.45	3484	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:6	20.45	3482	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:6	20.45	3510	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:6	20.45	3495	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:6	20.45	3480	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:6	20.45	3480	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:7	20.45	3481	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:7	20.45	3478	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:7	20.45	3474	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:7	20.45	3468	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:7	20.45	3468	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:7	20.45	3460	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:8	20.45	3454	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:8	20.45	3454	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:8	20.45	3454	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:8	20.45	3456	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:8	20.45	3459	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:8	20.45	3461	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:9	20.45	3460	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:9	20.45	3463	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:9	20.45	3463	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:9	20.45	3470	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:9	20.45	3452	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:9	20.45	3448	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:18:9	20.45	3434	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:0	20.45	3443	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:0	20.45	3438	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:0	20.45	3439	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:0	20.45	3438	1.7	13.59	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:0	20.45	3438	1.7	13.58	97	191	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:0	20.45	3439	1.7	13.6	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:1	20.45	3437	1.7	13.6	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:1	20.45	3434	1.7	13.58	97	190	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:1	20.45	3431	1.7	13.62	97	190	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:1	20.45	3434	1.7	13.61	97	190	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:1	20.45	3432	1.7	13.6	97	191	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:1	20.45	3425	1.7	13.62	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:1	20.45	3427	1.7	13.62	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:2	20.45	3411	1.7	13.6	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:2	20.45	3422	1.7	13.62	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:2	20.45	3420	1.7	13.62	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:2	20.45	3420	1.7	13.61	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:19:2	20.45	3420	1.7	13.61	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:2	20.45	3420	1.7	13.62	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:3	20.45	3420	1.7	13.61	97	190	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:3	20.45	3418	1.7	13.63	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:3	20.45	3415	1.7	13.62	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:3	20.45	3415	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:3	20.45	3413	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:3	20.45	3412	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:4	20.45	3407	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:4	20.45	3408	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:4	20.45	3404	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:4	20.45	3402	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:4	20.45	3400	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:4	20.45	3400	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:4	20.45	3398	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:5	20.45	3397	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:5	20.45	3398	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:5	20.45	3398	1.7	13.64	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:5	20.45	3398	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:5	20.45	3389	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:5	20.45	3389	1.7	13.64	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:6	20.45	3388	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:6	20.45	3385	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:6	20.45	3383	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:6	20.45	3383	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:6	20.45	3382	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:6	20.45	3381	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:6	20.45	3379	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:7	20.45	3376	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:7	20.45	3376	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:7	20.45	3375	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:7	20.45	3375	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:7	20.45	3374	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:7	20.45	3370	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:8	20.45	3371	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:8	20.45	3370	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:8	20.45	3370	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:8	20.45	3369	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:8	20.45	3366	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:8	20.45	3336	1.7	13.59	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:9	20.45	3350	1.7	13.6	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:9	20.45	3361	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:9	20.45	3358	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:9	20.45	3356	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:9	20.45	3352	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:9	20.45	3352	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:19:9	20.45	3348	1.7	13.6	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:0	20.45	3348	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:0	20.45	3348	1.7	13.59	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:0	20.45	3348	1.7	13.6	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:0	20.45	3323	1.7	13.6	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:0	20.45	3347	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:0	20.45	3347	1.7	13.6	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:1	20.45	3345	1.7	13.62	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:1	20.45	3344	1.7	13.62	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:1	20.45	3340	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:1	20.45	3338	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:1	20.45	3336	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:20:1	20.45	3336	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:1	20.45	3335	1.7	13.62	97	190	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:2	20.45	3332	1.7	13.62	97	190	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:2	20.45	3332	1.7	13.62	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:2	20.45	3333	1.7	13.62	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:2	20.45	3332	1.7	13.62	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:2	20.45	3331	1.7	13.6	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:2	20.45	3328	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:3	20.45	3326	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:3	20.45	3322	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:3	20.45	3320	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:3	20.45	3316	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:3	20.45	3316	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:3	20.45	3313	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:4	20.45	3312	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:4	20.45	3310	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:4	20.45	3310	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:4	20.45	3307	1.7	13.62	97	191	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:4	20.45	3306	1.7	13.63	97	191	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:4	20.45	3303	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:4	20.45	3303	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:5	20.45	3304	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:5	20.45	3301	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:5	20.45	3300	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:5	20.45	3300	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:5	20.45	3298	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:5	20.45	3293	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:6	20.45	3295	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:6	20.45	3295	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:6	20.45	3294	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:6	20.45	3291	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:6	20.45	3292	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:6	20.45	3288	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:6	20.45	3286	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:7	20.45	3287	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:7	20.45	3286	1.7	13.61	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:7	20.45	3286	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:7	20.45	3283	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:7	20.45	3285	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:7	20.45	3274	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:8	20.45	3287	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:8	20.45	3282	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:8	20.45	3279	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:8	20.45	3277	1.7	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:8	20.45	3273	1.7	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:8	20.45	3273	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:9	20.45	3270	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:9	20.45	3279	1.7	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:9	20.45	3266	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:9	20.45	3262	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:9	20.45	3262	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:9	20.45	3262	1.7	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:20:9	20.45	3259	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:0	20.45	3260	1.7	13.58	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:0	20.45	3264	1.7	13.57	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:0	20.45	3276	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:0	20.45	3264	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:0	20.45	3263	1.7	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:21:0	20.45	3239	1.7	13.58	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:1	20.45	3257	1.7	13.58	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:1	20.45	3253	1.7	13.59	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:1	20.45	3247	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:1	20.45	3245	1.7	13.63	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:1	20.45	3240	1.7	13.63	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:1	20.45	3237	1.7	13.63	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:1	20.45	3233	1.7	13.63	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:2	20.45	3230	1.7	13.64	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:2	20.45	3229	1.7	13.63	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:2	20.45	3229	1.7	13.62	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:2	20.45	3228	1.7	13.62	97	191	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:2	20.45	3223	1.7	13.6	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:2	20.45	3222	1.7	13.61	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:3	20.45	3220	1.7	13.62	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:3	20.45	3218	1.7	13.6	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:3	20.45	3218	1.7	13.58	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:3	20.45	3218	1.7	13.56	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:3	20.45	3215	1.7	13.55	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:3	20.45	3215	1.7	13.51	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:4	20.45	3214	1.7	13.51	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:4	20.45	3213	1.7	13.51	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:4	20.45	3211	1.7	13.52	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:4	20.45	3211	1.7	13.55	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:4	20.45	3211	1.7	13.56	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:4	20.45	3204	1.7	13.57	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:4	20.45	3204	1.7	13.56	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:5	20.45	3201	1.7	13.56	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:5	20.45	3198	1.7	13.56	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:5	20.45	3198	1.7	13.54	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:5	20.45	3194	1.7	13.56	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:6	20.45	3195	1.7	13.57	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:6	20.45	3167	1.7	13.57	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:6	20.45	3178	1.7	13.58	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:6	20.45	3190	1.7	13.56	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:6	20.45	3187	1.7	13.56	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:6	20.45	3184	1.7	13.55	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:6	20.45	3182	1.7	13.54	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:6	20.45	3175	1.7	13.55	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:6	20.45	3167	1.7	13.54	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:7	20.45	3164	1.7	13.56	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:7	20.45	3164	1.7	13.56	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:7	20.45	3150	1.7	13.57	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:7	20.45	3150	1.7	13.58	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:7	20.45	3143	1.7	13.57	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:7	20.45	3136	1.7	13.57	97	190	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:8	20.45	3132	1.69	13.56	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:8	20.45	3126	1.69	13.55	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:8	20.45	3123	1.69	13.54	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:8	20.45	3117	1.69	13.54	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:8	20.45	3114	1.69	13.54	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:8	20.45	3106	1.69	13.54	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:9	20.45	3103	1.69	13.54	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:9	20.45	3097	1.69	13.54	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:9	19.09	3088	1.69	13.56	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:9	19.09	3078	1.69	13.58	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:9	19.09	3081	1.69	13.59	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:21:9	19.09	3076	1.69	13.59	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:21:9	19.09	3072	1.69	13.56	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:0	19.09	3062	1.69	13.56	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:0	19.09	3060	1.69	13.55	97	191	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:0	19.09	3077	1.69	13.55	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:0	19.09	3052	1.69	13.55	97	191	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:0	19.09	3034	1.69	13.55	97	191	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:0	19.09	3039	1.69	13.56	97	191	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:1	19.09	3003	1.69	13.56	97	191	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:1	19.09	3003	1.69	13.57	97	191	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:1	19.09	3019	1.69	13.57	97	191	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:1	19.09	3038	1.69	13.56	97	191	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:1	19.09	3009	1.69	13.55	97	191	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:1	19.09	2974	1.7	13.55	97	191	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:1	19.09	2974	1.7	13.56	97	191	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:2	19.09	2984	1.7	13.56	97	191	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:2	19.09	2992	1.7	13.56	97	191	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:2	19.09	2990	1.7	13.55	97	191	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:2	19.09	2984	1.7	13.55	97	191	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:2	19.09	2978	1.7	13.56	97	191	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:2	19.09	2978	1.7	13.56	97	191	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:3	19.09	2970	1.7	13.55	97	191	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:3	19.09	2962	1.7	13.56	97	191	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:3	19.09	2958	1.69	13.56	97	191	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:3	19.09	2949	1.69	13.56	97	191	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:3	19.09	2947	1.69	13.56	97	191	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.26	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:3	19.09	2938	1.69	13.56	97	191	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.26	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:4	19.09	2932	1.69	13.56	97	191	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:4	19.09	2930	1.69	13.56	97	191	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:4	19.09	2922	1.69	13.56	97	191	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:4	19.09	2916	1.69	13.56	97	191	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:4	19.09	2916	1.69	13.57	97	191	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:4	19.09	2933	1.69	13.56	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:4	19.09	2904	1.69	13.57	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:5	19.09	2897	1.69	13.56	97	191	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:5	19.09	2896	1.69	13.57	97	191	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:5	19.09	2889	1.69	13.57	97	191	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:5	19.09	2898	1.69	13.57	97	191	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:5	19.09	2880	1.69	13.56	97	191	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:5	19.09	2874	1.69	13.57	97	191	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:6	19.09	2862	1.69	13.56	97	191	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:6	19.09	2866	1.69	13.56	97	191	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:6	19.09	2855	1.69	13.56	97	191	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:6	19.09	2850	1.69	13.57	97	191	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:6	19.09	2850	1.69	13.56	97	191	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:6	19.09	2864	1.69	13.56	97	191	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:6	19.09	2864	1.69	13.55	97	191	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:7	19.09	2832	1.69	13.56	97	191	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:7	19.09	2825	1.69	13.56	97	191	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:7	19.09	2822	1.69	13.55	97	191	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:7	19.09	2808	1.69	13.56	97	191	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:7	19.09	2813	1.69	13.56	97	191	Idle	42	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:7	19.09	2812	1.69	13.56	97	191	Idle	42.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:8	19.09	2807	1.69	13.56	97	191	Idle	42.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:8	19.09	2800	1.69	13.55	97	191	Idle	42.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:8	19.09	2796	1.69	13.55	97	191	Idle	43.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:8	19.09	2794	1.68	13.56	97	191	Idle	43.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:8	19.09	2786	1.68	13.56	97	191	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:8	19.09	2782	1.68	13.56	97	191	Idle	43.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:22:9	19.09	2782	1.68	13.56	97	191	Idle	44.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:9	19.09	2777	1.68	13.56	97	191	Idle	44.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:9	19.09	2770	1.67	13.56	97	191	Idle	44.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:9	19.09	2765	1.67	13.56	97	191	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:9	19.09	2774	1.67	13.55	97	191	Idle	45.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:9	19.09	2757	1.66	13.55	97	191	Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:22:9	19.09	2733	1.66	13.55	97	191	Idle	46.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:0	19.09	2742	1.65	13.56	97	191	Idle	46.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:0	19.09	2745	1.65	13.55	97	191	Idle	47.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:0	19.09	2728	1.65	13.56	97	191	Idle	47.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:0	19.09	2732	1.64	13.56	97	191	Idle	47.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:0	19.09	2732	1.64	13.56	97	191	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:0	19.09	2727	1.63	13.57	97	191	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:1	19.09	2723	1.63	13.57	97	191	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:1	19.09	2713	1.62	13.56	97	191	Idle	49.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:1	19.09	2718	1.62	13.56	97	191	Idle	49.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:1	19.09	2716	1.61	13.57	97	191	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:1	19.09	2738	1.61	13.56	97	191	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:1	19.09	2710	1.6	13.56	97	191	Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:1	19.09	2710	1.6	13.56	97	191	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:2	19.09	2696	1.59	13.56	97	191	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:2	19.09	2700	1.59	13.57	97	191	Idle	50.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:2	19.09	2696	1.58	13.57	97	191	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:2	19.09	2694	1.57	13.57	97	191	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:2	19.09	2689	1.57	13.56	97	191	Idle	51.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:2	19.09	2684	1.56	13.57	97	191	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:3	19.09	2680	1.56	13.57	97	191	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:3	19.09	2680	1.55	13.57	97	191	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:3	19.09	2674	1.55	13.56	97	191	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:3	19.09	2670	1.55	13.55	97	191	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:3	19.09	2665	1.54	13.55	97	191	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:3	19.09	2665	1.54	13.55	97	191	Idle	52.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:4	19.09	2661	1.54	13.55	97	191	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:4	19.09	2661	1.53	13.55	97	191	Idle	53.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:4	19.09	2677	1.53	13.55	97	191	Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:4	19.09	2650	1.52	13.55	97	191	Idle	53.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:4	19.09	2650	1.52	13.56	97	191	Idle	53.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:4	19.09	2647	1.51	13.56	97	191	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:4	19.09	2640	1.51	13.55	97	191	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:5	19.09	2593	1.5	13.56	97	190	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:5	19.09	2610	1.5	13.56	97	190	Idle	54.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:5	19.09	2620	1.5	13.57	97	190	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:5	19.09	2620	1.5	13.57	97	191	Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:5	19.09	2620	1.49	13.56	97	191	Idle	55.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:5	19.09	2608	1.49	13.56	97	191	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:6	19.09	2604	1.49	13.55	97	191	Idle	55.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:6	19.09	2624	1.48	13.56	97	191	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:6	19.09	2624	1.48	13.55	97	191	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:6	19.09	2601	1.47	13.55	97	191	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:6	19.09	2590	1.47	13.56	97	191	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:6	19.09	2599	1.47	13.56	97	191	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:6	19.09	2598	1.46	13.56	97	191	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:7	19.09	2594	1.46	13.57	97	191	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:7	19.09	2586	1.46	13.56	97	191	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:7	19.09	2578	1.46	13.57	97	191	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:7	19.09	2578	1.45	13.56	97	191	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:7	19.09	2570	1.45	13.56	97	191	Idle	57.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:7	19.09	2554	1.44	13.56	97	191	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:23:8	19.09	2558	1.44	13.55	97	191	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:8	19.09	2558	1.44	13.55	97	191	Idle	58.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:8	19.09	2552	1.44	13.56	97	191	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:8	19.09	2588	1.43	13.57	97	191	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:8	19.09	2568	1.43	13.58	97	191	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:8	19.09	2544	1.42	13.57	97	191	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:9	19.09	2502	1.42	13.57	97	191	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:9	19.09	2521	1.42	13.58	97	191	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:9	19.09	2521	1.41	13.57	97	191	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:9	19.09	2531	1.41	13.57	97	191	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:9	19.09	2527	1.41	13.57	97	191	Idle	60.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:9	19.09	2506	1.4	13.56	97	191	Idle	60.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:23:9	19.09	2516	1.4	13.55	97	191	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:0	19.09	2510	1.39	13.56	97	191	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:0	19.09	2509	1.39	13.56	97	191	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:0	19.09	2502	1.39	13.56	97	191	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:0	19.09	2495	1.38	13.56	97	191	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:0	19.09	2493	1.38	13.57	97	191	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:0	19.09	2493	1.37	13.56	97	191	Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:1	19.09	2485	1.37	13.56	97	191	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:1	19.09	2481	1.37	13.55	97	191	Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:1	19.09	2479	1.36	13.55	97	191	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:1	19.09	2478	1.36	13.56	97	191	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:1	19.09	2475	1.36	13.55	97	191	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:1	19.09	2468	1.36	13.56	97	191	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:1	19.09	2465	1.35	13.57	97	191	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:2	19.09	2464	1.35	13.56	97	191	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:2	19.09	2454	1.34	13.56	97	191	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:2	19.09	2447	1.34	13.58	97	191	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:2	19.09	2446	1.34	13.58	97	191	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:2	19.09	2423	1.33	13.57	97	191	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:2	17.72	2453	1.33	13.56	97	191	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:3	17.72	2453	1.33	13.56	97	191	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:3	17.72	2426	1.32	13.55	97	191	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:3	17.72	2414	1.32	13.56	97	191	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:3	17.72	2421	1.32	13.56	97	191	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:3	17.72	2418	1.32	13.57	97	191	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:3	17.72	2416	1.31	13.57	97	191	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:4	17.72	2412	1.31	13.56	97	191	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:4	17.72	2412	1.3	13.57	97	191	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:4	17.72	2407	1.29	13.57	97	191	Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:4	17.72	2392	1.29	13.56	97	191	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:4	17.72	2393	1.28	13.57	97	191	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:4	17.72	2391	1.28	13.56	97	191	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:4	17.72	2384	1.28	13.56	97	191	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:5	17.72	2384	1.27	13.56	97	191	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:5	17.72	2374	1.26	13.57	97	191	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:5	17.72	2364	1.26	13.57	97	191	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:5	17.72	2359	1.24	13.57	97	191	Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:5	17.72	2359	1.24	13.57	97	191	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:5	17.72	2360	1.23	13.56	97	191	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:6	17.72	2360	1.22	13.56	97	191	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:6	17.72	2344	1.21	13.56	97	191	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:6	17.72	2322	1.2	13.56	97	191	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:6	17.72	2335	1.19	13.55	97	191	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:6	17.72	2343	1.19	13.54	97	191	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:6	17.72	2330	1.18	13.55	97	191	Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:6	17.72	2324	1.18	13.55	97	191	Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:24:7	17.72	2324	1.17	13.55	97	191	Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:7	17.72	2317	1.17	13.55	97	191	Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:7	17.72	2292	1.16	13.55	97	191	Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:7	17.72	2304	1.16	13.55	97	191	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:7	17.72	2304	1.15	13.56	97	191	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:7	17.72	2298	1.15	13.55	97	191	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:8	17.72	2310	1.14	13.56	97	191	Idle	72	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:8	17.72	2299	1.14	13.57	97	191	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:8	17.72	2285	1.14	13.56	97	191	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:8	17.72	2270	1.14	13.58	97	191	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:8	17.72	2270	1.14	13.58	97	191	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:8	17.72	2272	1.13	13.57	97	191	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:9	17.72	2266	1.13	13.57	97	191	Idle	73.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:9	17.72	2264	1.13	13.57	97	191	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:9	17.72	2264	1.12	13.57	97	191	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:9	17.72	2245	1.12	13.56	97	191	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:9	17.72	2246	1.12	13.57	97	191	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:9	17.72	2244	1.12	13.56	97	191	Idle	74.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.25	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:24:9	17.72	2256	1.11	13.55	97	191	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:0	17.72	2256	1.11	13.55	97	191	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:0	17.72	2214	1.1	13.56	97	191	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:0	17.72	2221	1.1	13.55	97	191	Idle	75.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:0	17.72	2199	1.1	13.55	97	191	Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:0	17.72	2206	1.09	13.56	97	191	Idle	75.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:0	17.72	2225	1.09	13.54	97	191	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:1	17.72	2201	1.08	13.53	97	191	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:1	17.72	2201	1.08	13.53	97	191	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:1	17.72	2188	1.07	13.55	97	191	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:1	17.72	2188	1.07	13.55	97	191	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:1	17.72	2187	1.06	13.55	97	191	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:1	17.72	2181	1.06	13.56	97	191	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:1	17.72	2174	1.06	13.56	97	191	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:2	17.72	2174	1.05	13.56	97	191	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:2	17.72	2182	1.05	13.57	97	191	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:2	17.72	2141	1.04	13.58	97	191	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:2	17.72	2106	1.04	13.58	97	191	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:2	17.72	2104	1.03	13.57	97	190	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:2	17.72	2082	1.02	13.55	97	190	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:3	17.72	2062	1.02	13.53	97	190	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:3	17.72	2051	1.01	13.52	97	191	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:3	17.72	1988	1.01	13.52	97	191	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:3	17.72	1999	1	13.53	97	191	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:3	17.72	1987	1	13.55	97	191	Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:3	17.72	1954	1	13.56	97	191	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:4	17.72	1933	1	13.56	97	191	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:4	17.72	1888	1	13.55	97	191	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:4	17.72	1888	1.01	13.54	97	191	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:4	17.72	1881	1.01	13.53	97	191	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:4	17.72	1843	1.02	13.53	97	191	Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:4	17.72	1826	1.03	13.53	97	191	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.2	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:4	17.72	1798	1.03	13.55	97	191	Idle	73.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:5	17.72	1774	1.04	13.56	97	190	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:5	17.72	1751	1.05	13.55	97	190	Idle	71.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.2	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:5	17.72	1740	1.06	13.53	97	190	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.2	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:5	17.72	1710	1.08	13.53	97	190	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:5	17.72	1680	1.09	13.52	97	191	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:5	17.72	1656	1.11	13.52	97	191	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:6	17.72	1656	1.12	13.53	97	191	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:25:6	17.72	1633	1.14	13.54	97	191	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:6	17.72	1608	1.15	13.55	97	191	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:6	17.72	1583	1.16	13.55	97	191	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:6	17.72	1565	1.17	13.54	97	191	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.24	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:6	17.72	1540	1.18	13.54	96	191	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.24	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:6	17.72	1533	1.19	13.55	96	191	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.32	20.24	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:7	17.72	1520	1.2	13.53	96	191	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.23	20.24	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:7	17.72	1482	1.21	13.54	96	191	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.17	20.23	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:7	17.72	1455	1.21	13.53	97	190	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.05	20.22	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:7	17.72	1418	1.22	13.54	97	190	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.99	20.22	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:7	17.72	1418	1.22	13.53	97	190	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.9	20.23	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:7	17.72	1403	1.22	13.54	97	190	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.85	20.22	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:8	19.09	1403	1.23	13.54	97	190	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.77	20.22	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:8	19.09	1387	1.23	13.55	97	190	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.73	20.22	1.38	4.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:8	19.09	1349	1.23	13.56	97	190	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.66	20.22	1.38	4.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:25:8	17.72	1302	1.23	13.54	97	190	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.59	20.22	1.38	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:25:8	17.72	1302	1.23	13.55	97	191	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.52	20.21	1.38	4.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:25:8	17.72	1282	1.23	13.54	97	191	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.44	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:25:9	16.36	1265	1.23	13.52	97	191	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.39	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:25:9	16.36	1226	1.23	13.53	97	191	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.31	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:25:9	16.36	1226	1.22	13.53	97	191	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.29	20.22	1.38	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:9	16.36	1217	1.22	13.54	97	191	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.21	20.22	1.38	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:9	16.36	1217	1.21	13.55	97	191	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.17	20.21	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:25:9	16.36	1208	1.21	13.54	97	191	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.1	20.21	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:25:9	16.36	1212	1.21	13.55	97	191	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.05	20.22	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:0	16.36	1217	1.2	13.54	97	191	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.01	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:0	16.36	1220	1.2	13.53	97	191	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.97	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:0	16.36	1226	1.2	13.54	97	191	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.95	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:0	16.36	1229	1.19	13.54	97	191	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.95	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:0	16.36	1225	1.18	13.54	97	190	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.96	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:0	16.36	1225	1.18	13.54	97	190	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.97	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:1	14.99	1248	1.17	13.54	97	190	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.99	20.24	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:1	14.99	1244	1.14	13.52	97	191	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.06	20.24	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:1	14.99	1249	1.13	13.53	97	191	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:1	14.99	1249	1.11	13.53	97	191	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.18	20.23	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:1	14.99	1285	1.1	13.53	97	191	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.23	20.23	1.38	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:10:26:1	13.63	1321	1.08	13.54	97	191	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.32	20.23	1.38	4.2	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:26:1	13.63	1321	1.07	13.55	97	191	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.38	20.23	1.38	4.2	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:26:2	13.63	1373	1.04	13.55	97	191	Idle	83.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.45	20.24	1.38	4.1	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:26:2	12.27	1427	1.03	13.54	97	191	Idle	83.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.61	20.23	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:26:2	12.27	1501	1.01	13.55	97	190	Idle	85.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.74	20.23	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:26:2	12.27	1501	1	13.56	97	190	Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.94	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:26:2	14.99	1526	0.98	13.58	97	190	Idle	87.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.05	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:26:2	14.99	1598	0.97	13.56	97	191	Idle	87.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.14	20.24	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:26:3	14.99	1615	0.95	13.57	97	191	Idle	87.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.28	20.24	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:26:3	14.99	1636	0.94	13.56	97	191	Idle	88	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.42	20.24	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:26:3	14.99	1676	0.92	13.57	97	191	Idle	88.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.53	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:26:3	14.99	1735	0.91	13.57	97	190	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.69	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:26:3	14.99	1735	0.89	13.56	97	190	Idle	88.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.9	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:26:3	14.99	1814	0.88	13.55	97	191	Idle	89	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.97	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:26:4	16.36	1845	0.87	13.55	97	191	Idle	89.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.13	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:4	16.36	1878	0.87	13.55	97	191	Idle	89.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.26	20.19	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:4	16.36	1878	0.86	13.57	97	191	Idle	89.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.34	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:4	16.36	1926	0.86	13.58	97	191	Idle	89.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:4	16.36	1973	0.85	13.6	97	191	Idle	89.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.47	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:4	16.36	1973	0.84	13.61	97	191	Idle	90	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.5	20.19	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:4	16.36	2027	0.84	13.6	97	191	Idle	90.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.53	20.19	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:5	16.36	2081	0.84	13.6	97	191	Idle	90.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.55	20.18	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:26:5	17.72	2088	0.83	13.6	97	191	Idle	90	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.62	20.18	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:5	17.72	2148	0.83	13.6	97	191	Idle	89.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.69	20.17	1.37	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:5	17.72	2184	0.83	13.59	97	191	Idle	89.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.72	20.11	1.37	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:5	17.72	2184	0.82	13.58	97	191	Idle	89.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.77	20.01	1.36	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:5	17.72	2233	0.82	13.56	97	191	Idle	88.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.79	19.77	1.35	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:6	17.72	2266	0.82	13.55	97	191	Idle	88.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.8	19.58	1.33	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:6	17.72	2311	0.82	13.54	97	191	Idle	87.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.82	19.37	1.32	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:6	17.72	2315	0.83	13.56	97	191	Idle	86.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.82	19.12	1.3	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:6	17.72	2375	0.83	13.56	97	191	Idle	85.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.86	18.86	1.29	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:6	17.72	2396	0.84	13.56	97	191	Idle	84.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.87	18.57	1.27	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:6	17.72	2410	0.84	13.57	97	191	Idle	83.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.88	18.25	1.24	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:6	17.72	2466	0.85	13.58	97	191	Idle	82.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.91	17.95	1.22	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:7	17.72	2491	0.86	13.57	97	191	Idle	81.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.92	17.69	1.21	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:7	17.72	2512	0.88	13.57	97	191	Idle	79.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.91	17.47	1.19	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:7	17.72	2549	0.89	13.57	97	191	Idle	78.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.92	17.3	1.18	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:7	19.09	2577	0.91	13.57	97	191	Idle	77	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.94	17.16	1.17	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:7	19.09	2570	0.93	13.58	97	191	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.91	17.05	1.16	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:7	19.09	2562	0.95	13.58	97	191	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.88	16.93	1.15	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:8	19.09	2555	0.97	13.57	97	191	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.87	16.89	1.15	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:8	19.09	2550	0.99	13.58	97	191	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.82	16.9	1.15	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:8	19.09	2524	1.02	13.58	97	191	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.8	16.95	1.15	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:8	19.09	2499	1.05	13.57	97	191	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	17.04	1.16	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:8	19.09	2491	1.08	13.57	97	191	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	17.28	1.18	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:8	19.09	2451	1.11	13.56	97	191	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	17.38	1.18	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:9	19.09	2451	1.13	13.55	97	191	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	17.82	1.21	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:9	19.09	2422	1.15	13.56	97	191	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	18.14	1.24	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:9	19.09	2400	1.18	13.56	97	191	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	18.64	1.27	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:9	19.09	2400	1.2	13.56	97	191	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	18.96	1.29	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:9	17.72	2380	1.22	13.53	97	191	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	19.26	1.31	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:9	17.72	2374	1.24	13.54	97	191	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	19.55	1.33	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:26:9	17.72	2386	1.25	13.56	97	191	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	19.8	1.35	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:0	17.72	2380	1.27	13.55	97	191	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20	1.36	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:0	17.72	2395	1.28	13.56	97	191	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.15	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:0	17.72	2397	1.3	13.57	96	191	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:0	17.72	2404	1.3	13.56	96	191	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:0	17.72	2407	1.31	13.55	96	191	Idle	62.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:0	17.72	2407	1.32	13.56	97	191	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:1	17.72	2442	1.32	13.56	97	191	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:1	17.72	2422	1.32	13.56	97	191	Idle	63.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:1	17.72	2390	1.32	13.56	97	191	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:1	17.72	2376	1.31	13.55	97	191	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:1	17.72	2320	1.31	13.56	97	191	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:1	17.72	2320	1.3	13.56	97	191	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:1	17.72	2344	1.29	13.55	97	191	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:2	17.72	2338	1.29	13.56	97	191	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:2	17.72	2309	1.28	13.56	97	191	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:2	17.72	2299	1.27	13.56	97	191	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:2	17.72	2299	1.26	13.57	97	191	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:2	17.72	2284	1.26	13.56	97	191	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:2	17.72	2290	1.25	13.56	97	191	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:3	17.72	2289	1.24	13.56	97	191	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:3	17.72	2289	1.23	13.56	97	191	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:3	17.72	2301	1.23	13.56	97	191	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:3	17.72	2291	1.21	13.56	97	191	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:3	17.72	2271	1.2	13.56	97	191	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:3	17.72	2271	1.19	13.56	97	191	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:4	17.72	2286	1.19	13.56	97	191	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:4	17.72	2279	1.18	13.56	97	191	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:27:4	17.72	2276	1.17	13.57	97	190	Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:4	17.72	2267	1.16	13.56	97	190	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:4	17.72	2260	1.15	13.56	97	190	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:4	17.72	2245	1.14	13.56	97	191	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:4	17.72	2245	1.14	13.55	97	191	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:5	17.72	2230	1.13	13.55	97	191	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:5	17.72	2206	1.12	13.55	97	191	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:5	17.72	2211	1.12	13.55	97	191	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:5	17.72	2210	1.11	13.55	97	191	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:5	17.72	2198	1.1	13.55	97	191	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:5	17.72	2198	1.1	13.56	97	191	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:6	17.72	2191	1.1	13.55	97	191	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:6	17.72	2188	1.09	13.54	97	191	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:6	17.72	2178	1.09	13.55	97	191	Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:6	17.72	2181	1.08	13.55	97	191	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:6	17.72	2179	1.07	13.55	97	190	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:6	17.72	2176	1.07	13.55	97	190	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:6	17.72	2169	1.06	13.56	97	190	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:7	17.72	2163	1.05	13.56	97	191	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:7	17.72	2156	1.05	13.56	97	191	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:7	17.72	2154	1.04	13.56	97	191	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:7	17.72	2143	1.04	13.56	97	191	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:7	17.72	2128	1.03	13.56	97	191	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:7	17.72	2125	1.03	13.55	97	191	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:8	17.72	2125	1.02	13.54	97	191	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:8	17.72	2114	1.02	13.51	97	191	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:8	17.72	2107	1.02	13.51	97	191	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:8	17.72	2101	1.01	13.51	97	191	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:8	17.72	2098	1.01	13.51	97	191	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:8	17.72	2106	1.01	13.51	97	191	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:9	17.72	2078	1	13.51	97	191	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:9	17.72	2080	1	13.51	97	191	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:9	17.72	2080	1	13.53	97	191	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:9	17.72	2072	1	13.53	97	190	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:9	17.72	2065	0.99	13.54	97	190	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:9	17.72	2065	0.99	13.55	97	190	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:27:9	17.72	2058	0.99	13.54	97	191	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:0	17.72	2050	0.99	13.53	97	191	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:0	17.72	2029	0.98	13.52	97	191	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:0	17.72	2034	0.98	13.53	97	190	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:0	17.72	2033	0.98	13.54	97	190	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:0	17.72	2028	0.98	13.55	97	190	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:0	17.72	2025	0.98	13.55	97	191	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:1	17.72	2015	0.98	13.57	97	191	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:1	17.72	2010	0.98	13.57	97	191	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:1	17.72	2007	0.98	13.57	97	191	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.26	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:1	17.72	1997	0.98	13.57	97	191	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:1	17.72	1996	0.98	13.57	97	190	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:1	17.72	1978	0.98	13.57	97	190	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:1	17.72	1978	0.98	13.57	97	190	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:2	17.72	1961	0.98	13.57	97	191	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:2	17.72	1962	0.98	13.57	97	191	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:2	17.72	1962	0.98	13.57	97	191	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:2	17.72	1954	0.98	13.56	97	191	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:2	17.72	1945	0.98	13.55	96	191	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:2	17.72	1940	0.98	13.54	96	191	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:3	17.72	1937	0.98	13.53	96	191	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:3	17.72	1929	0.98	13.54	97	191	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:28:3	17.72	1921	0.98	13.55	97	191	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:3	17.72	1921	0.98	13.56	97	191	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:3	17.72	1912	0.98	13.56	97	191	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:3	17.72	1887	0.98	13.56	97	191	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:4	17.72	1891	0.98	13.56	97	191	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:4	17.72	1888	0.98	13.56	97	191	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.05	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:4	17.72	1882	0.98	13.56	97	191	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.06	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:4	17.72	1882	0.98	13.58	97	191	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.06	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:4	17.72	1872	0.98	13.59	97	191	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.06	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:4	17.72	1862	0.98	13.58	97	191	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.06	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:4	17.72	1862	0.98	13.56	96	191	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.06	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:5	17.72	1852	0.98	13.54	96	191	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.07	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:5	17.72	1843	0.98	13.53	96	190	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.07	1.37	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:5	17.72	1835	0.98	13.54	97	190	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.06	1.37	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:5	17.72	1835	0.98	13.55	97	190	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.05	1.37	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:5	17.72	1826	0.98	13.55	97	191	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:5	17.72	1814	0.98	13.55	96	191	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:6	17.72	1807	0.98	13.55	96	191	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:6	17.72	1807	0.98	13.56	96	191	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:6	17.72	1796	0.98	13.55	97	191	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:6	17.72	1785	0.98	13.55	97	191	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:6	17.72	1785	0.98	13.56	97	190	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.2	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:6	17.72	1777	0.98	13.55	97	190	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.2	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:6	17.72	1770	0.98	13.56	97	190	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.2	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:7	17.72	1766	0.98	13.57	97	191	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.2	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:7	17.72	1742	0.99	13.56	97	191	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.21	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:7	17.72	1748	0.99	13.54	97	191	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.21	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:7	17.72	1744	0.99	13.55	97	191	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:7	17.72	1738	0.99	13.53	97	191	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:7	17.72	1725	0.99	13.54	97	191	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:8	17.72	1725	0.99	13.55	97	191	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:8	17.72	1714	0.99	13.55	97	191	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:8	17.72	1710	0.99	13.55	97	191	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:8	17.72	1706	0.99	13.56	97	191	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:8	17.72	1694	0.99	13.55	97	191	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:8	17.72	1686	0.99	13.55	97	191	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:9	17.72	1682	0.99	13.54	97	191	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:9	17.72	1674	0.99	13.53	97	191	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:9	17.72	1662	0.99	13.54	97	191	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:9	17.72	1659	0.99	13.53	97	191	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:9	17.72	1656	1	13.53	97	191	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:9	17.72	1641	1	13.53	97	190	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:28:9	17.72	1641	1	13.54	97	190	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:0	17.72	1632	1	13.53	97	190	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:0	17.72	1612	1	13.53	97	191	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:0	17.72	1612	1	13.53	97	191	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:0	17.72	1610	1	13.52	97	191	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:0	17.72	1606	1	13.52	97	191	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:0	17.72	1589	1	13.53	97	191	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:1	17.72	1589	1	13.52	97	191	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:1	17.72	1580	1	13.52	97	191	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:1	17.72	1575	1	13.52	97	191	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:1	17.72	1566	0.99	13.52	97	191	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:1	17.72	1557	0.99	13.54	97	191	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:1	17.72	1552	0.99	13.55	97	191	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:1	17.72	1548	0.99	13.55	97	191	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:2	17.72	1536	0.99	13.54	97	190	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:2	17.72	1529	0.99	13.54	97	190	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:29:2	17.72	1521	0.99	13.54	97	190	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:2	17.72	1521	0.99	13.56	97	190	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:2	17.72	1513	0.98	13.55	97	191	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:2	17.72	1505	0.98	13.55	97	191	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:3	17.72	1505	0.98	13.53	97	191	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:3	17.72	1490	0.98	13.54	97	191	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.21	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:3	17.72	1485	0.98	13.52	97	191	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.21	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:3	17.72	1478	0.99	13.52	97	191	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:3	17.72	1450	0.99	13.51	97	190	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:3	17.72	1438	0.99	13.53	97	190	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:4	17.72	1427	0.99	13.53	97	191	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.22	1.38	4.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:4	19.09	1414	0.99	13.54	97	191	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.22	1.38	4.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:4	19.09	1388	0.99	13.52	97	191	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.22	1.38	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:4	19.09	1354	0.99	13.53	97	191	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.23	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:4	17.72	1354	0.99	13.54	97	191	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.42	20.23	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:29:4	17.72	1306	0.99	13.54	97	191	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.37	20.23	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:29:4	17.72	1288	1	13.55	97	191	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.31	20.23	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:29:5	17.72	1288	1	13.56	97	191	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	20.23	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:29:5	17.72	1248	1	13.56	97	191	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.21	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:5	17.72	1248	1.01	13.56	96	191	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.13	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:5	16.36	1223	1.01	13.55	96	191	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	20.23	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:5	16.36	1215	1.01	13.56	97	191	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:29:5	16.36	1207	1.02	13.56	97	191	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	20.21	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:29:6	16.36	1207	1.02	13.54	97	191	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.75	20.21	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:29:6	16.36	1187	1.03	13.54	97	191	Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.65	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:29:6	16.36	1179	1.03	13.56	97	191	Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.62	20.2	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:6	16.36	1161	1.03	13.55	97	190	Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.53	20.21	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:6	16.36	1161	1.04	13.56	97	190	Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.48	20.21	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:6	16.36	1163	1.04	13.56	97	191	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.41	20.21	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:6	16.36	1164	1.05	13.56	97	191	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.41	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:7	16.36	1164	1.05	13.56	97	191	Idle	76.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.35	20.23	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:7	16.36	1176	1.05	13.53	97	191	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.34	20.23	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:7	16.36	1169	1.05	13.55	97	191	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.31	20.23	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:7	14.99	1162	1.05	13.53	97	191	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.28	20.23	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:7	14.99	1168	1.05	13.52	97	191	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.27	20.23	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:7	14.99	1173	1.04	13.54	97	191	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.28	20.22	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:8	14.99	1177	1.04	13.53	97	190	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.28	20.22	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:8	14.99	1174	1.03	13.52	97	190	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.31	20.22	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:29:8	14.99	1174	1.03	13.53	97	190	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.31	20.22	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:8	14.99	1168	1.02	13.53	97	191	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.34	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:8	14.99	1158	1.01	13.54	97	191	Idle	84.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.37	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:8	14.99	1154	1.01	13.53	97	191	Idle	85.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.39	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:9	14.99	1154	0.99	13.52	97	191	Idle	86.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.45	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:9	14.99	1154	0.99	13.51	97	191	Idle	87	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.46	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:9	14.99	1149	0.98	13.51	97	191	Idle	87.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.5	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:9	14.99	1149	0.96	13.54	97	191	Idle	87.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.54	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:9	13.63	1126	0.96	13.52	97	191	Idle	87.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.53	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:9	13.63	1123	0.95	13.53	97	191	Idle	87.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.58	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:29:9	13.63	1123	0.94	13.53	97	191	Idle	87.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.52	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:30:0	13.63	1107	0.93	13.53	97	191	Idle	88	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.55	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:30:0	13.63	1098	0.92	13.55	97	191	Idle	88.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.56	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:30:0	13.63	1088	0.91	13.53	97	191	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.54	20.21	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:0	13.63	1088	0.91	13.55	97	191	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.57	20.21	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:0	13.63	1069	0.9	13.53	97	191	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	20.21	1.38	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:0	13.63	1054	0.9	13.53	97	191	Idle	88.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.56	20.21	1.38	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:1	13.63	1054	0.9	13.54	97	191	Idle	88.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.5	20.21	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:1	13.63	1058	0.89	13.53	97	191	Idle	88.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:1	13.63	1061	0.89	13.53	97	191	Idle	88.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.48	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:30:1	13.63	1046	0.89	13.54	97	191	Idle	88.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.48	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:1	13.63	1046	0.89	13.56	97	191	Idle	89.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.47	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:1	12.27	1024	0.88	13.54	97	191	Idle	89.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.46	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:1	12.27	1024	0.88	13.55	97	191	Idle	89.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.43	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:2	12.27	1022	0.88	13.55	97	191	Idle	89.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.42	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:2	12.27	1018	0.88	13.54	97	191	Idle	88.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.42	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:2	12.27	1016	0.88	13.53	97	191	Idle	88.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.37	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:2	12.27	1006	0.87	13.54	97	191	Idle	88.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:2	12.27	1006	0.87	13.55	97	191	Idle	88.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.34	20.23	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:2	12.27	980	0.87	13.54	97	190	Idle	88.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.36	20.22	1.38	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:3	12.27	980	0.87	13.55	97	190	Idle	88.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.28	20.21	1.38	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:3	12.27	972	0.87	13.55	97	190	Idle	88.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.25	20.16	1.37	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:3	12.27	963	0.87	13.55	97	190	Idle	88.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.22	20.07	1.37	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:3	12.27	965	0.87	13.53	97	190	Idle	88.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	19.91	1.36	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:3	12.27	965	0.87	13.54	97	190	Idle	88.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.17	19.72	1.34	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:3	12.27	950	0.87	13.51	97	190	Idle	88.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.18	19.46	1.33	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:4	12.27	950	0.87	13.53	97	190	Idle	88.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.14	19.18	1.31	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:4	10.9	925	0.87	13.52	97	190	Idle	88.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.1	18.71	1.27	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:4	10.9	925	0.87	13.55	97	190	Idle	88.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.06	18.36	1.25	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:4	10.9	922	0.87	13.54	97	191	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.06	18	1.23	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:4	10.9	922	0.87	13.56	97	191	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8	17.66	1.2	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:4	10.9	922	0.87	13.55	97	191	Idle	89	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8	17.34	1.18	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:4	10.9	916	0.87	13.56	97	191	Idle	89.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.96	16.98	1.16	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:5	10.9	913	0.87	13.56	97	191	Idle	89.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.96	16.78	1.14	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:5	10.9	910	0.87	13.56	97	190	Idle	89.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.93	16.65	1.13	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:5	10.9	912	0.86	13.55	97	190	Idle	90	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.96	16.47	1.12	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:5	10.9	912	0.86	13.55	97	190	Idle	90.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.91	16.4	1.12	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:5	10.9	914	0.86	13.55	97	191	Idle	90.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.94	16.33	1.11	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:5	10.9	914	0.86	13.55	97	191	Idle	91.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.9	16.29	1.11	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:6	10.9	916	0.85	13.55	97	191	Idle	91.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.92	16.25	1.11	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:6	10.9	927	0.85	13.54	97	191	Idle	91.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.89	16.22	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:6	10.9	923	0.85	13.54	97	191	Idle	92.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.94	16.19	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:6	10.9	923	0.85	13.54	97	191	Idle	92.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.9	16.17	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:6	10.9	923	0.84	13.53	97	191	Idle	92.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.91	16.15	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:6	9.54	934	0.84	13.53	97	191	Idle	92.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.89	16.15	1.1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:6	9.54	928	0.84	13.54	97	190	Idle	92.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.92	16.12	1.1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:7	9.54	923	0.83	13.55	97	190	Idle	93	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.86	16.11	1.1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:7	9.54	923	0.83	13.55	97	190	Idle	93	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.85	16.1	1.1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:7	8.18	933	0.83	13.52	97	190	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.87	16.09	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:7	8.18	933	0.82	13.53	97	190	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.89	16.08	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:30:7	8.18	946	0.82	13.54	97	190	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.86	16.06	1.09	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:7	8.18	946	0.82	13.55	97	190	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.89	16.05	1.09	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:8	8.18	923	0.82	13.55	97	191	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.88	16.03	1.09	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:8	8.18	923	0.82	13.55	97	191	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.92	16.02	1.09	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:8	8.18	912	0.82	13.52	97	190	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.87	16	1.09	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:8	8.18	912	0.81	13.53	97	190	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.89	15.99	1.09	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:8	9.54	928	0.81	13.49	97	190	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.87	15.98	1.09	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:8	9.54	928	0.81	13.49	97	191	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.87	15.98	1.09	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:9	9.54	911	0.81	13.49	97	191	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.89	15.96	1.09	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:9	9.54	911	0.81	13.54	97	191	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.9	15.96	1.09	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:9	8.18	904	0.81	13.52	97	191	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.89	15.95	1.09	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:9	8.18	904	0.81	13.55	97	191	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.89	15.93	1.09	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:9	8.18	902	0.8	13.53	97	191	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.89	15.92	1.08	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:9	8.18	899	0.8	13.52	97	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.85	15.91	1.08	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:30:9	8.18	903	0.8	13.52	97	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.87	15.9	1.08	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:0	8.18	903	0.8	13.53	97	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	15.86	1.08	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:0	8.18	902	0.8	13.52	97	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	15.85	1.08	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:0	8.18	902	0.8	13.52	97	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	15.82	1.08	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:31:0	8.18	887	0.8	13.56	97	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	15.8	1.08	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:0	8.18	887	0.8	13.55	97	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.88	15.77	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:0	8.18	887	0.8	13.55	97	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.87	15.74	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:1	8.18	887	0.8	13.54	97	191	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	15.72	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:1	8.18	887	0.8	13.54	97	191	Idle	93	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.68	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:1	8.18	880	0.79	13.52	97	191	Idle	92.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.66	1.07	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:1	8.18	873	0.79	13.54	97	190	Idle	92.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.61	1.06	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:1	8.18	888	0.79	13.52	97	190	Idle	92.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15.59	1.06	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:1	8.18	888	0.79	13.54	97	190	Idle	92.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	15.55	1.06	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:1	9.54	878	0.79	13.52	97	190	Idle	92.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	15.48	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:2	9.54	868	0.79	13.54	97	190	Idle	92.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	15.46	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:31:2	9.54	869	0.79	13.52	97	190	Idle	92.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	15.39	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:2	9.54	869	0.79	13.54	97	190	Idle	92.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.69	15.37	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:2	9.54	869	0.79	13.54	97	191	Idle	92.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.69	15.3	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:2	9.54	875	0.79	13.54	97	191	Idle	92.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.67	15.27	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:2	9.54	864	0.79	13.53	97	191	Idle	92.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.73	15.23	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:3	9.54	864	0.79	13.53	97	190	Idle	93.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.69	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:3	9.54	864	0.79	13.53	97	190	Idle	93.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.7	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:3	9.54	864	0.79	13.53	97	191	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:3	9.54	864	0.79	13.54	97	191	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:3	9.54	858	0.79	13.53	97	191	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:3	9.54	853	0.79	13.54	97	191	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.62	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:4	8.18	865	0.79	13.55	97	191	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:4	8.18	865	0.79	13.54	97	191	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:4	8.18	865	0.79	13.53	97	191	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:4	8.18	859	0.79	13.54	97	191	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:4	8.18	856	0.79	13.54	97	191	Idle	93.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:4	9.54	853	0.79	13.53	97	190	Idle	93	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:4	9.54	853	0.79	13.54	97	190	Idle	92.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:31:5	9.54	852	0.79	13.53	97	191	Idle	92.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:5	9.54	852	0.79	13.55	97	191	Idle	92.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.57	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:5	10.9	847	0.79	13.53	97	191	Idle	92.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.56	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:5	10.9	847	0.79	13.55	97	190	Idle	92.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.55	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:5	10.9	847	0.79	13.54	97	190	Idle	92.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.54	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:5	10.9	841	0.79	13.53	97	190	Idle	91.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.53	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:6	10.9	846	0.79	13.53	97	190	Idle	91.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.53	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:6	9.54	850	0.79	13.53	97	190	Idle	91.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.51	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:6	9.54	857	0.79	13.52	97	191	Idle	91.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.52	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:6	9.54	857	0.79	13.52	97	191	Idle	91.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.48	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:6	9.54	857	0.79	13.53	97	191	Idle	91.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.5	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:6	9.54	844	0.79	13.53	97	191	Idle	91.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.47	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:6	9.54	844	0.79	13.53	97	191	Idle	91.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.47	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:7	9.54	846	0.8	13.54	97	191	Idle	91.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.44	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:7	9.54	847	0.8	13.55	97	190	Idle	91.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.44	15.03	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:7	9.54	836	0.8	13.55	97	190	Idle	91.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.46	15.04	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:7	9.54	836	0.8	13.55	97	190	Idle	92	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.45	15.05	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:7	9.54	836	0.8	13.56	97	191	Idle	92	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.45	15.06	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:7	9.54	836	0.8	13.55	97	191	Idle	92.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.42	15.07	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:8	9.54	846	0.8	13.55	97	191	Idle	92.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.46	15.07	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:8	10.9	864	0.8	13.53	97	190	Idle	92.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.43	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:8	10.9	864	0.8	13.54	97	190	Idle	92.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.47	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:8	10.9	863	0.8	13.53	97	190	Idle	92.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.48	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:8	10.9	862	0.81	13.53	97	191	Idle	92.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.47	15.11	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:8	10.9	874	0.81	13.53	97	191	Idle	92.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.47	15.11	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:9	9.54	874	0.8	13.52	97	191	Idle	92.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.5	15.15	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:9	9.54	872	0.8	13.53	97	191	Idle	92.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.51	15.17	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:9	9.54	872	0.8	13.54	97	191	Idle	92.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.52	15.19	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:9	9.54	870	0.8	13.53	97	190	Idle	92.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.55	15.2	1.04	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:31:9	9.54	894	0.8	13.54	97	190	Idle	92.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.51	15.21	1.04	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:9	9.54	906	0.8	13.54	97	190	Idle	93.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.53	15.22	1.04	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:31:9	9.54	906	0.8	13.52	97	190	Idle	93.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.52	15.24	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:0	9.54	906	0.8	13.52	97	190	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.57	15.24	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:0	8.18	909	0.8	13.52	97	191	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.58	15.25	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:0	8.18	909	0.79	13.52	97	191	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.63	15.25	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:0	8.18	909	0.79	13.5	97	191	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.61	15.23	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:0	8.18	909	0.79	13.54	97	191	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.63	15.23	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:0	8.18	912	0.79	13.52	97	191	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.6	15.22	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:1	8.18	912	0.79	13.54	97	191	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.65	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:1	8.18	911	0.79	13.52	97	191	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.61	15.21	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:1	8.18	910	0.79	13.54	97	191	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.67	15.18	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:1	8.18	909	0.79	13.51	97	191	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.66	15.17	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:1	8.18	909	0.79	13.53	97	191	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.67	15.16	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:1	8.18	909	0.79	13.52	97	190	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.68	15.14	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:1	8.18	904	0.79	13.54	97	190	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.71	15.14	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:2	8.18	920	0.79	13.54	97	190	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.7	15.12	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:2	8.18	920	0.79	13.56	97	190	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	15.11	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:2	8.18	920	0.79	13.56	97	190	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15.1	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:2	8.18	924	0.79	13.59	97	190	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	15.09	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:2	8.18	899	0.79	13.58	97	190	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	15.09	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:2	8.18	899	0.79	13.59	97	190	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.08	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:3	8.18	901	0.79	13.58	97	190	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:3	8.18	903	0.79	13.6	97	190	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	15.04	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:3	8.18	905	0.79	13.58	97	190	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:3	8.18	905	0.79	13.58	97	190	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:3	8.18	905	0.79	13.58	97	190	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	15.03	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:3	8.18	901	0.79	13.59	97	190	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:4	8.18	885	0.79	13.6	97	190	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.81	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:4	8.18	885	0.79	13.6	97	190	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.79	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:4	8.18	885	0.79	13.6	97	190	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.82	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:32:4	8.18	883	0.79	13.59	97	190	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.79	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:4	8.18	883	0.79	13.58	97	190	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.82	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:4	9.54	878	0.79	13.57	97	190	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.81	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:4	9.54	874	0.79	13.58	97	190	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.8	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:5	9.54	881	0.79	13.57	97	190	Idle	93.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.8	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:5	9.54	881	0.79	13.59	97	190	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.79	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:5	10.9	882	0.79	13.57	97	190	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.78	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:5	10.9	883	0.79	13.58	97	190	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:5	10.9	883	0.79	13.59	97	190	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:5	10.9	880	0.79	13.59	97	190	Full Load	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:6	10.9	885	0.79	13.59	97	190	Off Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:6	10.9	890	0.8	13.58	97	190	Off Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:6	10.9	890	0.8	13.58	97	190	Off Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	14.94	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:32:6	10.9	905	0.81	13.59	97	190	Off Idle	92.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.63	14.93	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:32:6	10.9	898	0.82	13.58	97	190	Off Idle	91.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.6	14.9	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:32:6	9.54	891	0.83	13.58	97	190	Off Idle	91	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.54	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:32:6	9.54	891	0.85	13.59	97	190	Off Idle	90.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.5	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:32:7	9.54	903	0.87	13.57	97	190	Off Idle	89.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.36	14.84	1.01	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:32:7	9.54	903	0.87	13.57	97	190	Off Idle	89.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.32	14.84	1.01	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:32:7	9.54	912	0.9	13.56	97	190	Off Idle	88.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.19	14.84	1.01	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:32:7	9.54	912	0.92	13.57	97	190	Off Idle	88.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.13	14.83	1.01	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:32:7	9.54	912	0.94	13.56	97	190	Off Idle	87.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.04	14.82	1.01	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:10:32:7	9.54	912	0.97	13.59	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.94	14.81	1.01	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:10:32:8	10.9	915	1	13.58	97	190	Off Idle	86.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.75	14.83	1.01	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:10:32:8	10.9	915	1.03	13.6	97	190	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.66	14.84	1.01	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:10:32:8	10.9	924	1.05	13.58	97	190	Off Idle	85	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.54	14.84	1.01	4.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:32:8	10.9	924	1.09	13.6	97	190	Off Idle	85	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.42	14.86	1.01	4.6	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:32:8	9.54	940	1.14	13.59	97	191	Off Idle	85.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.24	14.88	1.01	4.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:32:8	9.54	940	1.16	13.59	97	191	Off Idle	85.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.16	14.9	1.02	4.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:32:9	9.54	958	1.19	13.58	97	191	Off Idle	85.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.01	14.92	1.02	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:32:9	9.54	958	1.21	13.6	97	191	Off Idle	85.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.89	14.96	1.02	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:32:9	9.54	966	1.24	13.58	97	191	Off Idle	85.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.81	14.99	1.02	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:32:9	9.54	966	1.25	13.58	97	191	Off Idle	85.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.71	15.02	1.02	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:32:9	9.54	969	1.28	13.56	97	191	Off Idle	85.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.58	15.04	1.02	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:32:9	9.54	969	1.3	13.58	97	191	Off Idle	85.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.47	15.08	1.03	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:32:9	9.54	981	1.31	13.56	97	191	Off Idle	85.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.38	15.08	1.03	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:33:0	9.54	997	1.34	13.6	97	190	Off Idle	85.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.24	15.11	1.03	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:33:0	9.54	997	1.35	13.58	97	190	Off Idle	85.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.16	15.12	1.03	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:33:0	9.54	1008	1.36	13.6	97	191	Off Idle	85.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.1	15.14	1.03	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:33:0	10.9	1018	1.37	13.6	97	191	Off Idle	85.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.01	15.14	1.03	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:33:0	10.9	1018	1.39	13.59	97	191	Off Idle	85.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.97	15.14	1.03	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:33:0	10.9	1026	1.39	13.6	97	190	Off Idle	85.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.85	15.14	1.03	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:33:1	10.9	1026	1.41	13.58	97	190	Off Idle	85.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-4.77	15.15	1.03	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:33:1	10.9	1051	1.42	13.59	97	190	Off Idle	85.6	0	2	132	944 Turbo	0.67	Lean	1	14.6	-4.65	15.14	1.03	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:33:1	10.9	1060	1.43	13.58	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.72	Lean	1	14.6	-4.64	15.14	1.03	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:33:1	10.9	1076	1.45	13.6	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.77	Lean	1	14.6	-4.49	15.12	1.03	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:33:1	10.9	1076	1.47	13.58	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.4	15.11	1.03	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:33:1	10.9	1086	1.49	13.6	97	190	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.32	15.1	1.03	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:33:1	10.9	1097	1.5	13.58	97	190	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.17	15.11	1.03	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:33:2	10.9	1097	1.52	13.59	97	190	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.05	15.1	1.03	4.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:33:2	10.9	1096	1.53	13.59	97	190	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.88	15.12	1.03	4.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:33:2	10.9	1101	1.55	13.59	97	190	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.83	15.13	1.03	4.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:33:2	10.9	1170	1.56	13.6	97	190	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.75	15.12	1.03	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:33:2	21.81	1170	1.59	13.6	97	191	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.6	15.07	1.03	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:33:2	21.81	1144	1.6	13.63	97	191	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.61	15.03	1.02	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:33:3	21.81	1117	1.62	13.61	97	191	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.52	14.97	1.02	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:33:3	21.81	1124	1.63	13.61	97	191	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.53	14.89	1.01	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:33:3	21.81	1124	1.64	13.63	97	191	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.43	14.77	1.01	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:33:3	21.81	1132	1.66	13.6	97	191	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.44	14.59	0.99	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:33:3	21.81	1126	1.67	13.62	97	191	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.41	14.42	0.98	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:33:3	20.45	1120	1.68	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.38	14.24	0.97	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:33:4	20.45	1132	1.69	13.61	97	190	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.38	14.09	0.96	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:33:4	20.45	1143	1.69	13.63	97	190	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.35	13.95	0.95	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:33:4	20.45	1155	1.7	13.61	97	190	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.31	13.8	0.94	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:33:4	20.45	1158	1.7	13.6	97	190	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.36	13.66	0.93	4.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:33:4	20.45	1158	1.7	13.6	97	190	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.33	13.46	0.92	4.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:4	21.81	1152	1.69	13.58	97	190	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.28	13.36	0.91	4.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:4	21.81	1149	1.69	13.58	97	190	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.32	13.27	0.9	4.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:5	21.81	1149	1.69	13.58	97	190	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.33	13.15	0.9	4.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:5	21.81	1149	1.69	13.6	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.38	13.09	0.89	4.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:5	21.81	1149	1.69	13.6	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.4	13.04	0.89	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:5	21.81	1155	1.68	13.59	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.41	12.99	0.89	4.3	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:5	21.81	1169	1.68	13.6	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.39	12.97	0.88	4.3	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:5	23.18	1169	1.68	13.62	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.41	12.94	0.88	4.3	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:6	23.18	1166	1.68	13.6	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.4	12.92	0.88	4.3	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:6	23.18	1166	1.68	13.61	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.39	12.91	0.88	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:6	23.18	1169	1.68	13.62	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.41	12.9	0.88	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:6	23.18	1169	1.68	13.61	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.41	12.89	0.88	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:6	23.18	1155	1.68	13.59	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.38	12.88	0.88	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:6	23.18	1144	1.68	13.59	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.41	12.83	0.87	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:6	23.18	1144	1.68	13.59	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.37	12.81	0.87	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:7	23.18	1139	1.68	13.59	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.35	12.77	0.87	4.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:7	23.18	1133	1.68	13.59	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.36	12.72	0.87	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:7	23.18	1127	1.68	13.57	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.32	12.67	0.86	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:7	23.18	1122	1.68	13.58	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.35	12.65	0.86	4.6	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:33:7	23.18	1118	1.68	13.59	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.28	12.61	0.86	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:7	24.54	1118	1.68	13.58	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.3	12.57	0.86	4.7	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:8	24.54	1102	1.68	13.59	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.25	12.5	0.85	4.7	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:8	24.54	1102	1.68	13.58	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.19	12.48	0.85	4.7	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:8	23.18	1108	1.68	13.59	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.23	12.46	0.85	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:8	23.18	1114	1.68	13.61	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.22	12.42	0.85	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:10:33:8	23.18	1109	1.68	13.58	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.24	12.42	0.85	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:8	23.18	1109	1.68	13.6	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.24	12.41	0.85	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:9	21.81	1120	1.68	13.57	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.25	12.41	0.85	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:9	21.81	1157	1.67	13.58	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.26	12.4	0.84	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:9	21.81	1182	1.67	13.59	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.25	12.41	0.85	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:9	23.18	1182	1.67	13.61	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.27	12.41	0.85	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:9	23.18	1188	1.67	13.61	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.28	12.41	0.85	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:33:9	23.18	1193	1.67	13.62	97	190	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.31	12.41	0.85	4.3	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:33:9	21.81	1203	1.67	13.62	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.35	12.41	0.85	4.3	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:34:0	21.81	1203	1.67	13.61	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.4	12.39	0.84	4.3	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:34:0	21.81	1248	1.67	13.6	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.43	12.38	0.84	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:34:0	21.81	1253	1.67	13.6	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.47	12.37	0.84	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:34:0	21.81	1253	1.67	13.6	97	190	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.54	12.34	0.84	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:34:0	21.81	1263	1.68	13.59	97	190	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.59	12.3	0.84	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:34:0	21.81	1284	1.68	13.59	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.63	12.28	0.84	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:34:1	21.81	1284	1.68	13.59	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.67	12.25	0.83	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:34:1	21.81	1285	1.68	13.59	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.71	12.21	0.83	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:34:1	21.81	1285	1.69	13.59	97	191	Off Idle	86.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.72	12.15	0.83	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:34:1	21.81	1296	1.69	13.59	97	191	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.76	12.12	0.83	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:34:1	21.81	1300	1.7	13.58	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.83	12.08	0.82	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:1	21.81	1302	1.7	13.58	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.83	12.06	0.82	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:1	21.81	1309	1.7	13.58	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.86	12.02	0.82	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:2	21.81	1309	1.71	13.59	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.85	12	0.82	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:2	23.18	1326	1.71	13.6	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.83	11.97	0.82	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:2	23.18	1318	1.72	13.61	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.89	11.95	0.81	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:2	23.18	1318	1.72	13.61	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.91	11.93	0.81	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:2	23.18	1335	1.73	13.62	97	191	Off Idle	86.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.94	11.92	0.81	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:2	23.18	1340	1.73	13.6	97	191	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.96	11.89	0.81	4.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:3	23.18	1340	1.74	13.6	97	191	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.01	11.87	0.81	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:3	23.18	1359	1.74	13.62	97	191	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.01	11.85	0.81	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:3	23.18	1374	1.75	13.61	97	191	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.03	11.83	0.81	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:3	23.18	1390	1.75	13.59	97	191	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.06	11.81	0.8	4.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:3	23.18	1390	1.75	13.59	97	191	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.07	11.8	0.8	4.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:34:3	23.18	1408	1.76	13.6	97	191	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.06	11.8	0.8	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:4	23.18	1434	1.76	13.6	97	191	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.1	11.8	0.8	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:4	23.18	1434	1.76	13.6	97	190	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.16	11.81	0.8	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:4	23.18	1439	1.77	13.6	97	190	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.22	11.82	0.81	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:4	23.18	1461	1.77	13.6	97	190	Off Idle	87	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.27	11.84	0.81	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:4	23.18	1461	1.77	13.61	97	191	Off Idle	87	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.26	11.86	0.81	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:4	24.54	1458	1.78	13.62	97	191	Off Idle	87	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.28	11.9	0.81	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:4	24.54	1467	1.78	13.61	97	191	Off Idle	87	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.32	11.93	0.81	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:5	24.54	1467	1.78	13.61	97	191	Off Idle	87	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.35	11.94	0.81	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:5	24.54	1473	1.79	13.62	97	191	Off Idle	87	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.35	11.97	0.82	4.1	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:5	24.54	1481	1.79	13.61	97	191	Off Idle	87	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.34	11.99	0.82	4.1	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:5	25.9	1509	1.79	13.59	97	190	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.39	12	0.82	4.1	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:5	25.9	1509	1.79	13.62	97	190	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.41	12.01	0.82	4.2	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:5	25.9	1492	1.8	13.62	97	190	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.44	12.03	0.82	4.2	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:6	25.9	1497	1.8	13.6	97	191	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.43	12.05	0.82	4.2	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:6	25.9	1507	1.8	13.6	97	191	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.46	12.05	0.82	4.2	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:6	25.9	1514	1.8	13.61	97	190	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.46	12.05	0.82	4.2	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:6	25.9	1526	1.81	13.6	97	190	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.47	12.06	0.82	4.1	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:6	25.9	1536	1.81	13.6	97	190	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.5	12.07	0.82	4.1	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:34:6	25.9	1551	1.81	13.6	97	190	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.47	12.08	0.82	4.1	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:34:6	25.9	1551	1.82	13.61	97	190	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.46	12.09	0.82	4.1	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:7	27.27	1575	1.82	13.6	97	190	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.47	12.1	0.82	4.1	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:7	27.27	1571	1.82	13.61	97	190	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.48	12.1	0.82	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:34:7	27.27	1571	1.83	13.61	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.48	12.11	0.82	4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:34:7	27.27	1583	1.83	13.6	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.52	12.12	0.83	4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:34:7	27.27	1588	1.84	13.59	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.53	12.15	0.83	4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:34:7	27.27	1601	1.84	13.59	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.56	12.19	0.83	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:34:8	27.27	1606	1.84	13.58	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.59	12.2	0.83	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:34:8	27.27	1619	1.85	13.57	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.64	12.23	0.83	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:34:8	27.27	1626	1.85	13.59	97	191	Off Idle	86.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.66	12.25	0.83	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:34:8	27.27	1626	1.86	13.61	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.69	12.28	0.84	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:8	27.27	1634	1.86	13.61	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.7	12.33	0.84	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:8	27.27	1642	1.86	13.59	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.7	12.35	0.84	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:9	27.27	1645	1.87	13.61	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.72	12.37	0.84	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:9	27.27	1667	1.87	13.59	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.72	12.42	0.85	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:9	27.27	1667	1.88	13.59	97	190	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.74	12.45	0.85	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:9	27.27	1674	1.88	13.61	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.77	12.49	0.85	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:9	27.27	1678	1.88	13.59	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.83	12.52	0.85	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:9	27.27	1678	1.88	13.59	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.81	12.55	0.85	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:10:34:9	27.27	1687	1.89	13.61	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.87	12.58	0.86	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:35:0	28.63	1706	1.89	13.62	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.9	12.61	0.86	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:35:0	28.63	1703	1.89	13.61	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.92	12.64	0.86	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:35:0	28.63	1707	1.89	13.6	97	191	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.97	12.67	0.86	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:35:0	28.63	1719	1.89	13.6	97	191	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.01	12.7	0.87	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:35:0	28.63	1727	1.89	13.59	97	191	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.04	12.72	0.87	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:35:0	28.63	1731	1.9	13.59	97	191	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.06	12.75	0.87	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:35:1	28.63	1740	1.9	13.59	97	191	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.08	12.77	0.87	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:35:1	28.63	1744	1.9	13.59	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.11	12.81	0.87	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:1	28.63	1751	1.9	13.59	97	190	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.15	12.85	0.88	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:1	28.63	1758	1.9	13.6	97	190	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.19	12.87	0.88	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:1	28.63	1767	1.91	13.6	97	190	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.22	12.91	0.88	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:1	28.63	1767	1.91	13.61	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.27	12.95	0.88	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:1	28.63	1775	1.91	13.61	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.29	12.96	0.88	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:2	28.63	1784	1.91	13.62	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.31	13.01	0.89	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:2	28.63	1797	1.91	13.61	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.3	13.06	0.89	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:2	28.63	1805	1.91	13.62	97	190	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.31	13.11	0.89	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:2	28.63	1808	1.92	13.61	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.29	13.16	0.9	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:2	28.63	1822	1.92	13.59	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.26	13.2	0.9	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:35:2	28.63	1822	1.92	13.59	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.3	13.26	0.9	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:35:3	28.63	1822	1.92	13.6	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.34	13.31	0.91	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:35:3	28.63	1829	1.92	13.62	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.41	13.36	0.91	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:35:3	28.63	1835	1.93	13.62	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.43	13.41	0.91	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:35:3	28.63	1836	1.93	13.61	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.49	13.46	0.92	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:35:3	28.63	1840	1.93	13.62	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.48	13.53	0.92	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:35:3	28.63	1846	1.93	13.62	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.49	13.57	0.92	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:35:4	28.63	1852	1.93	13.62	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.5	13.61	0.93	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:35:4	28.63	1856	1.93	13.61	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.54	13.66	0.93	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:4	28.63	1862	1.93	13.61	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.57	13.71	0.93	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:4	28.63	1862	1.93	13.61	97	191	Off Idle	86.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.58	13.75	0.94	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:4	28.63	1875	1.93	13.6	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.6	13.83	0.94	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:4	28.63	1884	1.93	13.59	97	191	Off Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.62	13.89	0.95	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:4	28.63	1888	1.93	13.61	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.63	13.94	0.95	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:5	28.63	1888	1.93	13.6	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.63	14.04	0.96	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:5	28.63	1903	1.93	13.59	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.11	0.96	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:5	28.63	1910	1.93	13.6	97	191	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.68	14.17	0.97	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:5	28.63	1912	1.93	13.6	97	191	Off Idle	86.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.67	14.26	0.97	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:5	28.63	1918	1.93	13.59	97	191	Off Idle	86.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.68	14.3	0.97	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:35:8	28.63	1918	1.94	13.59	97	191	Off Idle	86.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.68	14.35	0.98	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:6	28.63	1945	1.94	13.6	97	191	Off Idle	86	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.71	14.41	0.98	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:6	28.63	1930	1.94	13.62	97	191	Off Idle	86	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.75	14.44	0.98	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:6	28.63	1935	1.94	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.78	14.46	0.99	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:6	29.99	1946	1.94	13.62	97	191	Off Idle	85.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.78	14.5	0.99	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:6	29.99	1943	1.94	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.81	14.54	0.99	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:6	29.99	1945	1.94	13.62	97	191	Off Idle	86	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.83	14.57	0.99	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:6	29.99	1948	1.94	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.84	14.61	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:7	29.99	1957	1.94	13.6	97	191	Off Idle	86	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.85	14.65	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:7	29.99	1960	1.94	13.59	97	191	Off Idle	86	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.86	14.67	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:7	29.99	1965	1.94	13.58	97	190	Off Idle	86	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.84	14.7	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:7	31.36	1965	1.94	13.57	97	190	Off Idle	86	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.87	14.72	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:7	31.36	1985	1.94	13.57	97	190	Off Idle	86	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.91	14.75	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:7	31.36	1976	1.94	13.58	97	191	Off Idle	86	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.99	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:8	31.36	1976	1.94	13.58	97	191	Off Idle	86	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.99	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:8	31.36	1994	1.95	13.6	97	191	Off Idle	86	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:8	31.36	1994	1.95	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.01	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:8	31.36	2004	1.95	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.99	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:8	31.36	2019	1.95	13.6	97	191	Off Idle	86	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.97	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:8	31.36	2029	1.95	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.98	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:35:9	31.36	2030	1.95	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.03	14.96	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:9	31.36	2044	1.95	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.08	14.83	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:9	31.36	2044	1.95	13.61	97	191	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.08	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:9	31.36	2042	1.95	13.6	97	191	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.12	14.97	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:9	31.36	2040	1.95	13.6	97	191	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.14	15.04	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:9	31.36	2038	1.95	13.62	97	190	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.13	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:35:9	31.36	2040	1.95	13.62	97	190	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.17	15.15	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:0	31.36	2042	1.95	13.62	97	191	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.18	15.16	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:0	31.36	2047	1.95	13.63	97	191	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.2	15.17	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:0	31.36	2047	1.95	13.64	97	191	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.19	15.17	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:0	31.36	2052	1.95	13.64	97	191	Off Idle	86	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.17	15.33	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:0	31.36	2060	1.95	13.63	97	191	Off Idle	86	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.13	15.31	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:0	31.36	2069	1.96	13.63	97	191	Off Idle	86	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.14	15.29	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:1	31.36	2070	1.96	13.62	97	191	Off Idle	85.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.13	15.27	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:1	31.36	2075	1.96	13.62	97	191	Off Idle	85.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.14	15.24	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:1	31.36	2081	1.97	13.62	97	191	Off Idle	85.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.14	15.22	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:36:1	31.36	2081	1.97	13.62	97	191	Off Idle	85.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.12	15.19	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:36:1	31.36	2096	1.97	13.61	97	191	Off Idle	85.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.05	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:1	31.36	2096	1.98	13.61	97	191	Off Idle	85.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.96	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:1	31.36	2106	1.99	13.62	97	191	Off Idle	85.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.92	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:2	31.36	2112	1.99	13.62	97	191	Off Idle	85.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.86	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:2	31.36	2112	2	13.64	97	191	Off Idle	85.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.81	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:2	31.36	2112	2.01	13.62	97	190	Off Idle	85.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.76	15.06	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:2	31.36	2138	2.02	13.62	97	190	Off Idle	85.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.71	15.03	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:2	31.36	2145	2.03	13.63	97	190	Off Idle	85.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.62	15.01	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:36:2	31.36	2148	2.04	13.63	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.55	14.99	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:36:3	31.36	2172	2.05	13.65	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.5	14.98	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:36:3	31.36	2158	2.06	13.65	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.41	14.96	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:3	31.36	2161	2.07	13.64	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.35	14.95	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:3	31.36	2166	2.08	13.64	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.29	14.96	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:3	31.36	2169	2.09	13.64	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.29	14.97	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:3	31.36	2178	2.1	13.64	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.24	14.98	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:4	31.36	2180	2.11	13.63	97	191	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.23	15.01	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:4	31.36	2189	2.12	13.62	97	191	Off Idle	85.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.21	15.01	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:4	31.36	2196	2.13	13.61	97	191	Off Idle	85.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.15	15.01	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:4	31.36	2203	2.14	13.59	97	191	Off Idle	85.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.03	15.02	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:4	31.36	2206	2.15	13.59	97	191	Off Idle	84.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.97	15.02	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:36:4	31.36	2213	2.16	13.61	97	191	Off Idle	84.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.87	15.02	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:36:4	31.36	2224	2.18	13.61	97	190	Off Idle	84.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.74	15.02	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:36:5	31.36	2224	2.19	13.63	97	190	Off Idle	84.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.71	15.02	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:36:5	31.36	2238	2.2	13.65	97	190	Off Idle	84.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.65	15.02	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:36:5	31.36	2234	2.21	13.65	97	190	Off Idle	83.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.54	15.02	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:36:5	31.36	2234	2.22	13.65	97	191	Off Idle	83.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.51	15.03	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:36:5	31.36	2247	2.23	13.63	97	191	Off Idle	83.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.39	15.05	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:36:5	31.36	2249	2.24	13.63	97	191	Off Idle	82.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.29	15.04	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:36:6	31.36	2262	2.25	13.62	97	191	Off Idle	82.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.21	15.03	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:36:6	31.36	2266	2.26	13.63	97	190	Off Idle	82.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.14	15.01	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:36:6	31.36	2274	2.28	13.64	97	190	Off Idle	81.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.01	14.98	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:36:6	31.36	2299	2.29	13.63	97	191	Off Idle	81.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.98	14.95	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:36:6	32.72	2324	2.31	13.61	97	191	Off Idle	81.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.92	14.93	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:36:6	32.72	2324	2.32	13.62	97	191	Off Idle	81	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.85	14.9	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:36:6	32.72	2328	2.33	13.6	97	191	Off Idle	80.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.81	14.85	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:7	32.72	2342	2.35	13.61	97	191	Off Idle	80.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.7	14.81	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:7	31.36	2362	2.36	13.61	97	191	Off Idle	79.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.68	14.82	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:7	31.36	2366	2.37	13.6	97	191	Off Idle	79.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.6	14.83	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:7	31.36	2379	2.38	13.6	97	191	Off Idle	78.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.55	14.84	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:7	31.36	2391	2.4	13.6	97	191	Off Idle	78.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.42	14.88	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:7	31.36	2391	2.41	13.59	97	191	Off Idle	77.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3.34	14.92	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:36:8	31.36	2398	2.43	13.58	97	191	Off Idle	76.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.16	14.96	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:36:8	31.36	2406	2.44	13.6	97	191	Off Idle	76	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.11	15	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:36:8	31.36	2409	2.46	13.59	97	191	Off Idle	75.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.06	15.04	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:36:8	31.36	2412	2.47	13.59	97	191	Off Idle	75	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3	15.11	1.03	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:8	31.36	2415	2.48	13.61	97	191	Off Idle	74.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.94	15.11	1.03	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:8	31.36	2434	2.49	13.63	97	191	Off Idle	73.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.89	15.1	1.03	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:9	31.36	2432	2.5	13.62	97	191	Off Idle	73.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.83	15.07	1.03	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:9	31.36	2439	2.51	13.62	97	191	Off Idle	73	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.86	15.03	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:9	31.36	2442	2.52	13.61	97	191	Off Idle	72.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.79	15.01	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:9	31.36	2466	2.53	13.62	97	191	Off Idle	72.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.75	14.98	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:9	31.36	2466	2.54	13.6	97	191	Off Idle	72	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.74	14.95	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:36:9	31.36	2494	2.55	13.61	97	191	Off Idle	71.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.68	14.92	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:36:9	31.36	2503	2.57	13.62	97	191	Off Idle	71.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.54	14.86	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:37:0	31.36	2518	2.58	13.61	97	191	Off Idle	70.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.5	14.85	1.01	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:37:0	31.36	2522	2.59	13.62	97	191	Off Idle	70.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.44	14.84	1.01	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:37:0	32.72	2545	2.59	13.62	97	191	Off Idle	69.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.38	14.83	1.01	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:37:0	32.72	2545	2.61	13.62	97	191	Off Idle	69.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.32	14.83	1.01	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:37:0	32.72	2565	2.61	13.62	97	191	Off Idle	68.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.25	14.82	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:0	32.72	2581	2.62	13.63	97	191	Off Idle	67.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.2	14.81	1.01	3.3	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:1	32.72	2581	2.63	13.61	97	191	Off Idle	67.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.16	14.8	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:1	32.72	2618	2.64	13.61	97	191	Off Idle	66.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.15	14.78	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:1	32.72	2615	2.65	13.6	97	191	Off Idle	65.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.14	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:1	32.72	2629	2.66	13.59	97	191	Off Idle	64.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.11	14.77	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:1	32.72	2634	2.67	13.6	97	191	Off Idle	63.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.11	14.77	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:1	32.72	2660	2.68	13.6	97	191	Off Idle	63.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.08	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:1	32.72	2661	2.69	13.59	97	191	Off Idle	62.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.07	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:2	32.72	2673	2.7	13.61	97	191	Off Idle	62.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.01	14.77	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:2	32.72	2674	2.71	13.61	97	191	Off Idle	60.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.98	14.77	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:2	32.72	2680	2.73	13.59	97	191	Off Idle	60.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.95	14.77	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:2	32.72	2691	2.73	13.6	97	191	Off Idle	60.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.86	14.77	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:2	32.72	2703	2.74	13.62	97	191	Off Idle	59.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.86	14.77	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:2	32.72	2703	2.75	13.59	97	191	Off Idle	59.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.87	14.75	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:37:3	32.72	2712	2.75	13.61	97	191	Off Idle	58.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.89	14.73	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:37:3	32.72	2738	2.76	13.62	97	191	Off Idle	58	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.89	14.72	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:37:3	32.72	2746	2.77	13.59	97	191	Off Idle	57.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.76	14.71	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:37:3	32.72	2746	2.78	13.6	97	191	Off Idle	57.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.76	14.72	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:3	32.72	2763	2.78	13.59	97	191	Off Idle	56.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.69	14.73	1	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:3	32.72	2764	2.79	13.58	97	191	Off Idle	56.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.66	14.74	1	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:37:4	32.72	2784	2.8	13.58	97	191	Off Idle	55.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.65	14.74	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:37:4	32.72	2806	2.81	13.59	97	191	Off Idle	55.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.65	14.76	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:4	32.72	2825	2.82	13.59	97	191	Off Idle	54.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.62	14.77	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:4	32.72	2845	2.82	13.6	97	191	Off Idle	54.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.54	14.78	1.01	3.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:4	32.72	2873	2.83	13.61	97	191	Off Idle	53.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.46	14.8	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:37:4	32.72	2866	2.83	13.61	97	191	Off Idle	52.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.48	14.82	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:4	32.72	2872	2.84	13.62	97	191	Off Idle	52.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.46	14.82	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:5	32.72	2876	2.85	13.62	97	191	Off Idle	51.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.45	14.83	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:5	32.72	2893	2.86	13.6	97	191	Off Idle	50.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.43	14.85	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:5	32.72	2922	2.86	13.61	97	191	Off Idle	49.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.43	14.85	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:5	32.72	2922	2.87	13.6	97	191	Off Idle	49	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.47	14.85	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:5	32.72	2922	2.87	13.59	97	191	Off Idle	48.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.52	14.85	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:5	32.72	2934	2.88	13.61	97	191	Off Idle	47.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.54	14.87	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:6	32.72	2973	2.89	13.59	97	191	Off Idle	47.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.49	14.87	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:6	32.72	2965	2.89	13.61	97	191	Off Idle	46.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.45	14.87	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:6	32.72	2968	2.9	13.59	97	191	Off Idle	46.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.42	14.85	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:6	32.72	2984	2.9	13.61	97	191	Off Idle	45.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.44	14.86	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:6	32.72	2984	2.91	13.59	97	191	Off Idle	45.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-1.41	14.86	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:37:6	34.08	3027	2.92	13.6	97	191	Off Idle	44.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-1.45	14.87	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:6	34.08	3019	2.93	13.6	97	191	Off Idle	43.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.41	14.89	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:7	34.08	3028	2.94	13.6	97	191	Off Idle	43.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-1.44	14.9	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:7	34.08	3031	2.94	13.6	97	191	Off Idle	43.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-1.39	14.89	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:37:7	32.72	3050	2.94	13.59	97	191	Off Idle	42.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-1.35	14.89	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:37:7	32.72	3062	2.95	13.59	97	191	Off Idle	42.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-1.34	14.89	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:37:7	32.72	3096	2.96	13.6	97	191	Off Idle	42.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-1.36	14.9	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:37:7	32.72	3096	2.96	13.6	97	191	Off Idle	42	0	2	132	944 Turbo	0.44	Lean	1	14.6	-1.33	14.95	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:37:8	32.72	3111	2.97	13.58	97	191	Off Idle	41.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-1.28	14.99	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:37:8	32.72	3146	2.97	13.59	97	191	Off Idle	41.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-1.3	15.03	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:37:8	32.72	3138	2.98	13.59	97	191	Off Idle	41.7	0	2	132	944 Turbo	0.57	Lean	1	14.6	-1.25	15.02	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:37:8	32.72	3142	2.98	13.59	97	191	Off Idle	41.7	0	2	132	944 Turbo	0.63	Lean	1	14.6	-1.26	15.02	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:37:8	32.72	3150	2.99	13.6	97	191	Off Idle	41.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.29	15.02	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:37:8	32.72	3190	3	13.6	97	191	Off Idle	41.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.23	15	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:9	32.72	3173	3	13.61	97	191	Off Idle	41.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.24	14.98	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:9	32.72	3177	3.01	13.6	97	191	Off Idle	41.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.15	14.97	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:9	32.72	3184	3.01	13.6	97	191	Off Idle	41.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.14	14.87	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:9	32.72	3187	3.02	13.6	97	191	Off Idle	41.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.12	14.81	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:37:9	32.72	3199	3.03	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.1	14.77	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:37:9	32.72	3199	3.03	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.14	14.76	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:37:9	32.72	3224	3.03	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.13	14.75	1	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:0	32.72	3235	3.04	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.12	14.76	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:0	32.72	3264	3.05	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.07	14.76	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:0	32.72	3264	3.05	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.07	14.76	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:0	32.72	3290	3.06	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1	14.77	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:0	32.72	3310	3.07	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.91	14.79	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:0	32.72	3310	3.07	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.95	14.81	1.01	3.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:1	34.08	3386	3.08	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.88	14.82	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:1	34.08	3347	3.08	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.86	14.82	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:1	34.08	3355	3.09	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.85	14.83	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:1	34.08	3364	3.1	13.59	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.8	14.83	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:1	32.72	3368	3.1	13.6	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-0.8	14.84	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:1	32.72	3388	3.11	13.59	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.78	14.85	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:1	32.72	3392	3.11	13.6	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-0.87	14.85	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:2	32.72	3397	3.12	13.6	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-0.76	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:38:2	32.72	3394	3.12	13.58	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-0.74	14.81	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:38:2	32.72	3410	3.13	13.58	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-0.75	14.82	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:38:2	32.72	3420	3.13	13.6	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-0.71	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:38:2	32.72	3424	3.14	13.57	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-0.57	14.86	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:38:2	32.72	3455	3.14	13.58	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-0.64	14.92	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:38:3	32.72	3480	3.15	13.58	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-0.53	14.96	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:38:3	32.72	3490	3.15	13.56	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.54	14.98	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:38:3	32.72	3492	3.16	13.58	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-0.7	15	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:38:3	32.72	3517	3.16	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-0.68	15.06	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:3	32.72	3531	3.16	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-0.72	15.12	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:3	32.72	3550	3.17	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-0.71	15.14	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:4	32.72	3542	3.17	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-0.69	15.14	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:4	32.72	3549	3.18	13.62	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.65	15.14	1.03	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:4	32.72	3546	3.18	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-0.65	15.11	1.03	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:4	34.08	3560	3.18	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.67	15.06	1.03	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:38:4	34.08	3564	3.19	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-0.64	14.99	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:4	34.08	3576	3.19	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-0.66	14.97	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:4	34.08	3587	3.19	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-0.73	14.87	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:5	34.08	3631	3.19	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-0.68	14.84	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:5	34.08	3619	3.19	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-0.73	14.84	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:5	34.08	3615	3.19	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-0.71	14.89	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:5	34.08	3634	3.2	13.62	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.64	14.92	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:5	34.08	3681	3.2	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-0.6	14.97	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:5	34.08	3670	3.2	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-0.68	15.03	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:6	34.08	3674	3.2	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-0.69	15.07	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:38:6	34.08	3698	3.2	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-0.79	15.14	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:6	34.08	3700	3.2	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-0.96	15.23	1.04	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:6	34.08	3737	3.2	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-0.91	15.23	1.04	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:6	34.08	3732	3.2	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-0.91	15.22	1.04	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:6	34.08	3750	3.2	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-0.91	15.14	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:6	34.08	3750	3.2	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.89	15.06	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:7	34.08	3758	3.2	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.97	15	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:7	34.08	3753	3.2	13.62	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.09	14.95	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:7	34.08	3756	3.2	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-1	14.91	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:7	34.08	3754	3.2	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.06	14.8	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:7	34.08	3772	3.2	13.62	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-1.05	14.76	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:7	34.08	3799	3.2	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-0.97	14.79	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:8	34.08	3804	3.21	13.59	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.12	14.81	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:8	34.08	3813	3.21	13.61	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-1.13	14.86	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:8	34.08	3839	3.21	13.59	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-1.13	14.93	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:8	35.45	3853	3.21	13.6	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-1.23	14.97	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:38:8	35.45	3879	3.21	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-1.21	15.02	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:8	35.45	3882	3.21	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-1.25	15.1	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:38:9	35.45	3892	3.21	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-1.34	15.16	1.03	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:38:9	35.45	3903	3.21	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-1.3	15.15	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:38:9	35.45	3889	3.21	13.56	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.44	15.12	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:38:9	35.45	3888	3.21	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-1.57	15.07	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:38:9	35.45	3893	3.21	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-1.66	15.01	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:9	35.45	3896	3.2	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-1.75	14.98	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:38:9	35.45	3896	3.2	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.84	14.96	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:0	35.45	3912	3.18	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-2.18	14.9	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:0	35.45	3922	3.16	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.55	14.87	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:39:0	35.45	3917	3.13	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.08	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:39:0	35.45	3922	3.07	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.1	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:39:0	35.45	3921	3.02	13.63	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.79	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:39:0	35.45	3923	2.93	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.87	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:1	35.45	3913	2.9	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.6	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:39:1	36.81	3889	2.78	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.49	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:39:1	36.81	3875	2.66	13.6	97	191	Idle	41.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.99	14.93	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:39:1	36.81	3860	2.54	13.62	97	191	Idle	41.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.43	14.78	1.01	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:1	36.81	3826	2.46	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.86	14.58	0.99	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:1	38.18	3761	2.38	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.13	14.44	0.98	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:10:39:1	38.18	3768	2.3	13.62	97	191	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.37	14.28	0.97	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:39:2	38.18	3734	2.18	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.53	13.97	0.95	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:10:39:2	38.18	3696	2.14	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.6	13.8	0.94	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:10:39:2	35.45	3662	2.06	13.63	97	191	Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.63	13.67	0.93	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:10:39:2	29.99	3561	1.95	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.73	13.51	0.92	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:2	24.54	3557	1.85	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.7	13.47	0.92	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:2	20.45	3566	1.82	13.6	97	191	Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.76	13.37	0.91	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:3	20.45	3566	1.76	13.62	97	191	Idle	41.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.72	13.33	0.91	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:3	20.45	3521	1.71	13.59	97	191	Idle	40.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.74	13.28	0.9	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:3	20.45	3474	1.68	13.59	97	191	Idle	39.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.71	13.27	0.9	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:3	20.45	3463	1.64	13.6	97	191	Idle	38.3	0	2	132	944 Turbo	0.19	Rich	1	14.6	-9.71	13.27	0.9	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:3	20.45	3454	1.63	13.6	97	191	Idle	36.2	0	2	132	944 Turbo	0.11	Rich	1	14.6	-9.7	13.2	0.9	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:3	20.45	3382	1.63	13.62	97	191	Idle	35.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.68	13.28	0.9	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:4	20.45	3351	1.63	13.61	97	191	Idle	35.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.63	13.38	0.91	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:4	20.45	3351	1.64	13.62	97	191	Idle	33.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.61	13.5	0.92	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:4	20.45	3314	1.66	13.6	97	191	Idle	32.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	13.9	0.95	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:4	20.45	3298	1.67	13.61	97	191	Idle	31.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	14.38	0.98	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:4	20.45	3260	1.67	13.61	97	191	Idle	30.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.45	15.02	1.02	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:4	20.45	3252	1.69	13.61	97	191	Idle	29	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.39	15.71	1.07	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:4	20.45	3220	1.7	13.61	97	191	Idle	27.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.32	16.39	1.12	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:5	20.45	3198	1.72	13.61	97	191	Idle	25.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.28	17.15	1.17	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:5	20.45	3164	1.72	13.62	97	191	Idle	25.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.26	17.8	1.21	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:5	20.45	3140	1.74	13.62	97	191	Idle	24.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	18.71	1.27	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:5	20.45	3096	1.75	13.64	97	191	Idle	23.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	19.54	1.33	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:5	20.45	3083	1.76	13.63	97	191	Idle	23.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	19.95	1.36	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:5	20.45	3074	1.78	13.64	97	191	Idle	22.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	20.16	1.37	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:6	20.45	3015	1.79	13.63	97	191	Idle	22.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.03	20.22	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:6	20.45	3000	1.8	13.62	97	191	Idle	21.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.22	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:6	20.45	2983	1.81	13.62	97	191	Idle	21.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.99	20.22	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:6	20.45	2963	1.82	13.6	97	191	Idle	21.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	20.22	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:6	19.09	2921	1.82	13.61	97	191	Idle	21.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	20.22	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:6	19.09	2921	1.83	13.61	97	191	Idle	21.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	20.21	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:6	19.09	2890	1.83	13.6	97	191	Idle	21.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.84	20.21	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:7	19.09	2881	1.84	13.6	97	191	Idle	21.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.83	20.21	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:7	19.09	2836	1.84	13.6	97	191	Idle	21.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.81	20.22	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:7	19.09	2816	1.84	13.6	97	191	Full Load	21.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.79	20.22	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:7	19.09	2790	1.85	13.6	97	191	Off Idle	22.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.73	20.22	1.38	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:7	19.09	2772	1.85	13.6	97	191	Off Idle	23.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.68	20.22	1.38	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:7	19.09	2750	1.85	13.6	97	191	Off Idle	23.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.64	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:39:8	9.54	2644	1.86	13.61	97	191	Off Idle	24.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.55	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:39:8	12.27	2712	1.87	13.6	97	191	Off Idle	26.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.45	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:39:8	12.27	2702	1.88	13.62	97	191	Off Idle	28.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.4	20.22	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:8	14.99	2665	1.88	13.61	97	191	Off Idle	31.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.29	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:39:8	17.72	2632	1.89	13.61	97	191	Off Idle	33.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.21	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:39:8	17.72	2582	1.9	13.61	97	191	Off Idle	36.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.12	20.22	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:9	20.45	2566	1.9	13.6	97	191	Off Idle	38.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.08	20.22	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:9	23.18	2522	1.91	13.59	97	191	Off Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.01	20.23	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:9	25.9	2468	1.92	13.6	97	191	Off Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.93	20.22	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:39:9	25.9	2392	1.93	13.58	97	191	Off Idle	49.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.87	20.22	1.38	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:39:9	28.63	2406	1.93	13.58	97	191	Off Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.78	20.24	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:39:9	28.63	2389	1.94	13.58	97	191	Off Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.73	20.24	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:39:9	31.36	2321	1.94	13.59	97	191	Off Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.67	20.24	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:40:0	34.08	2299	1.94	13.59	97	191	Off Idle	60.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.59	20.24	1.38	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:40:0	34.08	2269	1.94	13.6	97	191	Off Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.55	20.24	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:0	34.08	2265	1.95	13.61	97	191	Off Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.49	20.24	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:0	34.08	2262	1.96	13.61	97	191	Off Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.4	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:40:0	34.08	2272	1.96	13.61	97	191	Off Idle	70	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.34	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:40:0	34.08	2274	1.96	13.61	97	191	Off Idle	71.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.24	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:40:1	34.08	2282	1.97	13.59	97	191	Off Idle	72.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.13	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:40:1	34.08	2294	1.97	13.6	97	191	Off Idle	73.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7	20.22	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:40:1	32.72	2303	1.98	13.62	97	191	Off Idle	74.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.86	20.23	1.38	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:1	32.72	2322	1.99	13.62	97	191	Off Idle	75.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.73	20.23	1.38	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:1	32.72	2351	2.01	13.6	97	191	Off Idle	76.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.46	20.23	1.38	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:1	32.72	2364	2.02	13.62	97	191	Off Idle	76.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.31	20.23	1.38	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:1	32.72	2369	2.04	13.62	97	191	Off Idle	77.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.13	20.2	1.38	3.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:2	32.72	2387	2.05	13.62	97	191	Off Idle	77.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.02	20.13	1.37	3.3	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:2	32.72	2409	2.06	13.62	97	191	Off Idle	77	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.96	19.98	1.36	3.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:2	32.72	2427	2.06	13.61	97	191	Off Idle	76.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.88	19.75	1.35	3.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:2	32.72	2417	2.07	13.61	97	191	Off Idle	76.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.82	19.48	1.33	3.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:2	32.72	2394	2.09	13.62	97	191	Off Idle	75.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.84	19.02	1.3	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:2	32.72	2374	2.11	13.62	97	191	Off Idle	74.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.8	18.69	1.27	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:3	32.72	2340	2.13	13.62	97	191	Off Idle	74.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.77	18.35	1.25	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:3	32.72	2340	2.14	13.61	97	191	Off Idle	74	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.77	18	1.23	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:3	32.72	2320	2.16	13.6	97	191	Off Idle	73.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.71	17.66	1.2	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:3	32.72	2314	2.17	13.58	97	191	Off Idle	73.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.66	17.34	1.18	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:3	32.72	2316	2.18	13.57	97	191	Off Idle	73.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.6	17.08	1.16	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:3	32.72	2326	2.19	13.59	97	191	Off Idle	73.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.54	16.88	1.15	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:4	32.72	2339	2.19	13.58	97	191	Off Idle	73.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.52	16.72	1.14	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:4	32.72	2339	2.19	13.58	97	191	Off Idle	73.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.5	16.51	1.12	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:4	32.72	2364	2.19	13.59	97	191	Off Idle	74.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.48	16.39	1.12	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:4	32.72	2386	2.19	13.61	97	191	Off Idle	74.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.49	16.27	1.11	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:4	32.72	2402	2.19	13.62	97	191	Off Idle	74.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.5	16.11	1.1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:4	32.72	2407	2.19	13.62	97	191	Off Idle	74.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.55	16	1.09	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:4	32.72	2408	2.19	13.63	97	191	Off Idle	74.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.54	15.89	1.08	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:5	32.72	2410	2.19	13.62	97	191	Off Idle	74.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.59	15.78	1.08	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:5	32.72	2407	2.19	13.62	97	191	Off Idle	73.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.62	15.69	1.07	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:5	32.72	2404	2.19	13.62	97	191	Off Idle	73.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.63	15.61	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:5	32.72	2391	2.19	13.61	97	191	Off Idle	73.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.68	15.53	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:5	32.72	2382	2.19	13.6	97	191	Off Idle	72.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.69	15.5	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:5	32.72	2382	2.19	13.59	97	191	Off Idle	72.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.68	15.44	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:6	32.72	2369	2.19	13.58	97	191	Off Idle	72.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.65	15.37	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:6	32.72	2369	2.19	13.57	97	191	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.6	15.29	1.04	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:6	32.72	2366	2.19	13.57	97	191	Off Idle	71.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.58	15.18	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:6	32.72	2372	2.19	13.58	97	191	Off Idle	71.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.52	15.11	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:6	32.72	2392	2.2	13.59	97	191	Off Idle	71.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.52	15.02	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:6	32.72	2392	2.2	13.62	97	191	Off Idle	72	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.52	14.96	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:6	32.72	2406	2.2	13.62	97	191	Off Idle	72	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.6	14.91	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:7	32.72	2418	2.2	13.62	97	191	Off Idle	72.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.67	14.84	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:7	32.72	2429	2.2	13.62	97	191	Off Idle	72.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.67	14.8	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:7	32.72	2432	2.2	13.61	97	191	Off Idle	72.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.65	14.76	1.01	3.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:7	32.72	2440	2.2	13.61	97	191	Off Idle	72.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.64	14.76	1.01	3.3	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:7	32.72	2441	2.2	13.61	97	191	Off Idle	72	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.62	14.78	1.01	3.3	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:7	32.72	2455	2.2	13.62	97	191	Off Idle	71.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.63	14.8	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:8	32.72	2422	2.2	13.59	97	191	Off Idle	71.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.68	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:8	32.72	2417	2.2	13.6	97	191	Off Idle	71.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.71	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:8	34.08	2405	2.2	13.61	97	191	Off Idle	71.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.63	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:8	34.08	2405	2.2	13.6	97	191	Off Idle	70.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.65	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:8	34.08	2405	2.2	13.61	97	191	Off Idle	70.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.65	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:8	34.08	2405	2.2	13.61	97	191	Off Idle	70.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.6	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:9	34.08	2413	2.2	13.59	97	191	Off Idle	70.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.61	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:9	34.08	2422	2.2	13.58	97	191	Off Idle	70.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.64	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:9	32.72	2388	2.21	13.59	97	191	Off Idle	70.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.63	14.99	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:40:9	32.72	2430	2.21	13.61	97	191	Off Idle	70.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.6	14.96	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:9	32.72	2446	2.21	13.63	97	191	Off Idle	70.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.64	14.93	1.02	3.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:40:9	32.72	2471	2.21	13.63	97	191	Off Idle	70.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.69	14.87	1.01	3.3	3	ON	28 Pin	OFF	Removed	Disabled
03:10:40:9	32.72	2462	2.21	13.63	97	191	Off Idle	70.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.74	14.83	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:0	32.72	2454	2.21	13.61	97	191	Off Idle	70.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.74	14.8	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:41:0	32.72	2457	2.21	13.6	97	191	Off Idle	70.8	0	2	132	944 Turbo	0.23	Rich	1	14.6	-5.74	14.78	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:0	32.72	2460	2.21	13.6	97	191	Off Idle	70.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.74	14.77	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:0	32.72	2469	2.21	13.6	97	191	Off Idle	70.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.72	14.78	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:0	32.72	2460	2.22	13.62	97	191	Off Idle	70.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.72	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:0	32.72	2458	2.22	13.63	97	191	Off Idle	70.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.68	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:1	32.72	2455	2.22	13.63	97	191	Off Idle	70	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.63	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:1	32.72	2455	2.22	13.65	97	191	Off Idle	69.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.62	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:1	32.72	2453	2.22	13.64	97	191	Off Idle	69.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.61	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:1	32.72	2456	2.22	13.62	97	191	Off Idle	69.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.61	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:1	32.72	2460	2.22	13.62	97	191	Off Idle	69.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.62	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:1	32.72	2464	2.22	13.6	97	191	Off Idle	69.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.63	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:1	32.72	2452	2.23	13.61	97	191	Off Idle	69.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.66	15.06	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:2	32.72	2473	2.23	13.6	97	191	Off Idle	69.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.71	15.1	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:41:2	32.72	2478	2.23	13.6	97	191	Off Idle	69.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.73	15.11	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:41:2	32.72	2478	2.23	13.61	97	191	Off Idle	69.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.7	15.1	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:41:2	32.72	2479	2.23	13.61	97	191	Off Idle	69.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.7	15.08	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:41:2	32.72	2476	2.23	13.62	97	191	Off Idle	69.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.69	15.05	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:41:2	32.72	2476	2.23	13.62	97	191	Off Idle	69.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.69	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:41:3	32.72	2477	2.23	13.6	97	191	Off Idle	69.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.68	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:41:3	34.08	2499	2.23	13.59	97	191	Off Idle	68.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.66	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:41:3	34.08	2482	2.23	13.58	96	191	Off Idle	68.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.71	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:3	34.08	2482	2.23	13.58	96	191	Off Idle	68.4	0	2	132	944 Turbo	0.67	Lean	1	14.6	-5.65	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:3	34.08	2486	2.24	13.61	97	191	Off Idle	68.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.69	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:3	34.08	2493	2.24	13.59	97	191	Off Idle	68.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.69	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:4	34.08	2500	2.24	13.6	97	191	Off Idle	68.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.65	14.82	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:4	34.08	2504	2.24	13.62	97	191	Off Idle	68	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.64	14.82	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:4	34.08	2504	2.24	13.62	97	191	Off Idle	67.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.67	14.82	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:4	34.08	2506	2.24	13.61	97	191	Off Idle	67.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.64	14.81	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:4	34.08	2506	2.24	13.62	97	191	Off Idle	67.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.63	14.8	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:4	34.08	2504	2.24	13.6	97	191	Off Idle	67.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.67	14.8	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:4	34.08	2505	2.25	13.59	97	191	Off Idle	67.1	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.66	14.81	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:5	34.08	2508	2.25	13.6	97	191	Off Idle	67.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.65	14.83	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:5	34.08	2510	2.25	13.6	97	191	Off Idle	66.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.65	14.87	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:5	34.08	2514	2.25	13.6	97	191	Off Idle	66.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.62	14.89	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:5	34.08	2520	2.25	13.6	97	191	Off Idle	66.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.58	14.92	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:5	34.08	2520	2.26	13.62	97	191	Off Idle	66.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.52	14.95	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:6	34.08	2523	2.26	13.62	97	191	Off Idle	66.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.5	14.97	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:6	34.08	2524	2.26	13.64	97	191	Off Idle	66	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.48	15.04	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:6	34.08	2524	2.27	13.63	97	191	Off Idle	65.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.47	15.1	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:41:6	34.08	2526	2.27	13.62	97	191	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.47	15.11	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:6	34.08	2526	2.27	13.62	97	191	Off Idle	65.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.47	15.09	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:6	34.08	2531	2.28	13.6	97	191	Off Idle	65.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.44	15.04	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:6	34.08	2535	2.28	13.61	97	191	Off Idle	65.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.43	15.01	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:6	32.72	2537	2.29	13.62	97	191	Off Idle	65.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.39	14.97	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:7	32.72	2544	2.29	13.62	97	191	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.36	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:7	32.72	2548	2.3	13.61	97	191	Off Idle	65	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.32	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:41:7	32.72	2550	2.31	13.61	97	191	Off Idle	64.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.29	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:41:7	32.72	2555	2.31	13.61	97	191	Off Idle	64.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.22	14.73	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:41:7	32.72	2556	2.32	13.6	97	191	Off Idle	64.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.18	14.72	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:41:7	32.72	2558	2.33	13.62	97	191	Off Idle	64.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.07	14.71	1	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:41:8	32.72	2562	2.33	13.63	97	191	Off Idle	64.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5	14.71	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:41:8	32.72	2563	2.34	13.62	97	191	Off Idle	64.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.99	14.72	1	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:41:8	32.72	2564	2.35	13.62	97	191	Off Idle	63.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.91	14.73	1	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:41:8	32.72	2568	2.35	13.6	97	191	Off Idle	63.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.9	14.73	1	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:10:41:8	32.72	2568	2.36	13.61	97	191	Off Idle	63.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.83	14.75	1	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:41:8	32.72	2567	2.37	13.62	97	191	Off Idle	63.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.81	14.78	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:41:9	32.72	2578	2.37	13.62	97	191	Off Idle	63.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.77	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:41:9	32.72	2571	2.38	13.63	97	191	Off Idle	63.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.72	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:41:9	32.72	2572	2.38	13.62	97	191	Off Idle	63.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.66	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:41:9	32.72	2577	2.39	13.61	97	191	Off Idle	63.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.64	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:41:9	32.72	2579	2.4	13.6	97	191	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.59	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:41:9	34.08	2590	2.4	13.6	97	191	Off Idle	63.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.57	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:41:9	34.08	2590	2.41	13.59	97	191	Off Idle	63.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.54	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:42:0	34.08	2599	2.42	13.59	97	191	Off Idle	62.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.46	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:42:0	34.08	2605	2.43	13.6	97	191	Off Idle	62.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.32	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:42:0	34.08	2605	2.44	13.61	97	191	Off Idle	62.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.28	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:0	34.08	2608	2.46	13.61	97	191	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.12	14.73	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:42:0	34.08	2612	2.47	13.62	96	191	Off Idle	62.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.99	14.72	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:10:42:0	34.08	2613	2.49	13.61	96	191	Off Idle	62.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.9	14.7	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:42:1	32.72	2602	2.49	13.61	96	191	Off Idle	61.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.85	14.7	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:42:1	32.72	2625	2.51	13.61	97	191	Off Idle	61.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.81	14.7	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:1	32.72	2625	2.51	13.62	97	191	Off Idle	61.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.73	14.71	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:1	32.72	2632	2.53	13.62	97	191	Off Idle	60.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.72	14.73	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:42:1	32.72	2633	2.54	13.62	96	191	Off Idle	60.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.67	14.74	1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:42:1	32.72	2636	2.55	13.62	96	191	Off Idle	60.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.67	14.75	1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:42:1	32.72	2636	2.56	13.61	96	191	Off Idle	60.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.56	14.77	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:42:2	32.72	2643	2.57	13.62	97	191	Off Idle	60.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.55	14.8	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:2	32.72	2648	2.58	13.6	97	191	Off Idle	60	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.54	14.84	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:2	32.72	2647	2.58	13.6	97	191	Off Idle	59.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.55	14.89	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:2	32.72	2647	2.59	13.61	97	191	Off Idle	59.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.51	14.91	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:2	32.72	2650	2.6	13.63	97	191	Off Idle	59.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.46	14.92	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:2	32.72	2655	2.6	13.62	97	191	Off Idle	59	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.42	14.9	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:3	32.72	2655	2.61	13.61	97	191	Off Idle	58.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.38	14.87	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:3	32.72	2684	2.61	13.61	97	191	Off Idle	58.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.33	14.83	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:3	32.72	2674	2.62	13.61	97	191	Off Idle	58.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.31	14.77	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:3	32.72	2674	2.62	13.61	97	191	Off Idle	58.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.26	14.66	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:3	32.72	2680	2.62	13.62	97	191	Off Idle	58	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.26	14.56	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:3	32.72	2684	2.62	13.61	96	191	Off Idle	57.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.28	14.45	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:4	32.72	2686	2.63	13.63	96	191	Off Idle	57.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.21	14.33	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:4	32.72	2689	2.64	13.61	97	191	Off Idle	57.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.08	14.27	0.97	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:4	32.72	2690	2.64	13.61	97	191	Off Idle	57.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.07	14.21	0.97	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:42:4	32.72	2690	2.65	13.61	97	191	Off Idle	57.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.96	14.17	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:4	32.72	2699	2.65	13.62	96	191	Off Idle	57.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.9	14.16	0.96	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:4	32.72	2709	2.66	13.62	96	191	Off Idle	57.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.89	14.15	0.96	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:4	32.72	2709	2.67	13.61	97	191	Off Idle	56.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.83	14.16	0.96	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:5	32.72	2717	2.67	13.6	97	191	Off Idle	56.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.73	14.15	0.96	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:5	32.72	2725	2.68	13.6	97	191	Off Idle	56.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.71	14.14	0.96	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:5	32.72	2725	2.68	13.6	97	191	Off Idle	56.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.69	14.15	0.96	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:5	32.72	2734	2.69	13.59	97	191	Off Idle	56.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.63	14.18	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:5	32.72	2742	2.69	13.6	97	191	Off Idle	56.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.58	14.2	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:5	32.72	2747	2.7	13.6	97	191	Off Idle	55.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.59	14.22	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:6	32.72	2749	2.71	13.6	97	191	Off Idle	55.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.55	14.25	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:6	32.72	2759	2.71	13.6	97	191	Off Idle	55.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.52	14.26	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:6	32.72	2750	2.72	13.6	97	191	Off Idle	54.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.51	14.27	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:6	32.72	2749	2.72	13.59	97	191	Off Idle	54.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.47	14.28	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:6	32.72	2748	2.73	13.58	97	191	Off Idle	54	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.47	14.3	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:6	32.72	2746	2.73	13.58	97	191	Off Idle	53.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.41	14.29	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:6	32.72	2748	2.74	13.59	97	191	Off Idle	53.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.4	14.29	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:7	32.72	2754	2.74	13.59	97	191	Off Idle	53.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.36	14.28	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:7	32.72	2754	2.74	13.6	97	191	Off Idle	53.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.34	14.28	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:7	32.72	2766	2.75	13.59	97	191	Off Idle	53	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.31	14.3	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:7	32.72	2778	2.75	13.61	97	191	Off Idle	52.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.35	14.31	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:7	32.72	2784	2.76	13.6	97	191	Off Idle	52.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.35	14.32	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:7	32.72	2789	2.76	13.61	97	191	Off Idle	52.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.38	14.32	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:8	32.72	2790	2.76	13.62	97	191	Off Idle	52.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.43	14.33	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:8	32.72	2806	2.76	13.62	97	191	Off Idle	52.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.42	14.33	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:42:8	32.72	2800	2.76	13.63	97	191	Off Idle	51.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.42	14.32	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:8	32.72	2804	2.77	13.63	97	191	Off Idle	51.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.41	14.33	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:8	32.72	2804	2.77	13.63	97	191	Off Idle	51.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.36	14.3	0.97	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:8	32.72	2805	2.77	13.62	97	191	Off Idle	51.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.29	14.29	0.97	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:9	32.72	2811	2.77	13.6	97	191	Off Idle	50.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.32	14.26	0.97	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:9	32.72	2819	2.78	13.61	97	191	Off Idle	50.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.34	14.27	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:9	32.72	2819	2.78	13.6	97	191	Off Idle	50.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.28	14.28	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:42:9	32.72	2824	2.78	13.6	97	191	Off Idle	50.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.26	14.29	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:9	32.72	2835	2.78	13.58	97	191	Off Idle	50	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.27	14.31	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:9	32.72	2849	2.78	13.6	97	191	Off Idle	49.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.22	14.32	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:42:9	32.72	2853	2.79	13.6	97	191	Off Idle	49.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.18	14.35	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:0	32.72	2856	2.79	13.61	97	191	Off Idle	49.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.19	14.36	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:0	32.72	2858	2.79	13.61	97	191	Off Idle	49.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.21	14.39	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:0	32.72	2856	2.79	13.62	97	191	Off Idle	48.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.17	14.44	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:0	32.72	2857	2.8	13.6	97	191	Off Idle	48.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.16	14.45	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:0	32.72	2860	2.8	13.6	97	191	Off Idle	48.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.16	14.47	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:0	32.72	2861	2.8	13.6	97	191	Off Idle	48.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.16	14.47	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:1	32.72	2865	2.81	13.62	97	191	Off Idle	48.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.12	14.49	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:1	32.72	2867	2.81	13.6	97	191	Off Idle	47.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.14	14.5	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:1	32.72	2870	2.81	13.62	97	191	Off Idle	47.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.11	14.52	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:1	32.72	2866	2.81	13.62	97	191	Off Idle	47.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.16	14.53	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:1	32.72	2877	2.81	13.61	96	191	Off Idle	47.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.14	14.54	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:1	32.72	2874	2.82	13.61	96	191	Off Idle	47.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.15	14.55	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:1	32.72	2888	2.82	13.61	96	191	Off Idle	46.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.14	14.57	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:2	32.72	2894	2.82	13.6	97	191	Off Idle	46.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.14	14.6	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:2	32.72	2900	2.82	13.6	97	191	Off Idle	46.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.06	14.63	1	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:2	32.72	2912	2.83	13.6	97	191	Off Idle	45.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.04	14.65	1	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:2	32.72	2919	2.83	13.6	97	191	Off Idle	45.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.07	14.7	1	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:2	32.72	2919	2.84	13.61	97	191	Off Idle	45.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.96	14.71	1	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:2	32.72	2921	2.84	13.62	97	191	Off Idle	45.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.9	14.75	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:43:3	32.72	2927	2.85	13.61	97	191	Off Idle	44.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.93	14.78	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:43:3	32.72	2930	2.85	13.6	97	191	Off Idle	44.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.83	14.8	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:43:3	32.72	2928	2.86	13.6	97	191	Off Idle	44.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.75	14.81	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:43:3	32.72	2937	2.86	13.61	97	191	Off Idle	44.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.68	14.83	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:43:3	32.72	2940	2.87	13.59	97	191	Off Idle	43.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.7	14.85	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:43:3	32.72	2960	2.87	13.59	97	191	Off Idle	43.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-1.53	14.86	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:43:4	32.72	2957	2.88	13.59	97	191	Off Idle	43.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-1.46	14.83	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:4	32.72	2957	2.89	13.6	97	191	Off Idle	43.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-1.34	14.83	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:43:4	32.72	2966	2.9	13.59	97	191	Off Idle	43	0	2	132	944 Turbo	0.43	Lean	1	14.6	-1.26	14.82	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:4	32.72	2992	2.91	13.61	97	191	Off Idle	42.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-1.17	14.81	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:4	32.72	2988	2.91	13.59	97	191	Off Idle	42.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-1.17	14.8	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:43:4	32.72	2992	2.93	13.59	97	191	Off Idle	42.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-1.06	14.84	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:43:4	32.72	2997	2.93	13.58	97	191	Off Idle	42.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-1.02	14.87	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:43:5	32.72	2997	2.94	13.57	97	191	Off Idle	42	0	2	132	944 Turbo	0.27	Lean	1	14.6	-0.97	14.89	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:43:5	32.72	3007	2.95	13.6	97	191	Off Idle	41.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-0.97	14.94	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:5	32.72	3007	2.96	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-0.92	14.96	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:5	32.72	3010	2.97	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-0.9	15.05	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:5	32.72	3009	2.97	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-0.93	15.07	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:5	32.72	3012	2.98	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.94	15.06	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:6	32.72	3012	2.99	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.89	15.04	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:6	32.72	3014	2.99	13.58	96	191	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.9	14.99	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:6	32.72	3016	3	13.57	96	191	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.84	14.89	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:6	32.72	3023	3	13.57	96	191	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.76	14.77	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:6	32.72	3028	3.01	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.71	14.7	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:6	32.72	3039	3.01	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.66	14.54	0.99	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:43:6	32.72	3040	3.01	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.63	14.47	0.99	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:7	32.72	3042	3.02	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.61	14.44	0.98	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:7	32.72	3050	3.02	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.65	14.43	0.98	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:43:7	32.72	3076	3.02	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.69	14.44	0.98	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:7	32.72	3074	3.03	13.62	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.69	14.46	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:7	32.72	3074	3.03	13.62	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.62	14.48	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:43:7	32.72	3076	3.03	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.61	14.51	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:43:8	32.72	3078	3.03	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.63	14.53	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:8	32.72	3095	3.04	13.6	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.6	14.58	0.99	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:8	32.72	3104	3.04	13.6	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.58	14.61	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:8	32.72	3104	3.05	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.54	14.64	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:8	32.72	3126	3.05	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.5	14.67	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:8	32.72	3113	3.05	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.52	14.68	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:9	32.72	3110	3.06	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.47	14.71	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:9	32.72	3110	3.06	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.48	14.72	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:9	32.72	3116	3.07	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.47	14.73	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:43:9	32.72	3124	3.07	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.34	14.75	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:43:9	32.72	3127	3.08	13.59	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.28	14.75	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:43:9	32.72	3135	3.09	13.59	97	191	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.08	14.76	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:43:9	32.72	3136	3.09	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	0.04	14.77	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:0	32.72	3136	3.1	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	0.18	14.77	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:0	32.72	3150	3.11	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	0.32	14.76	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:0	32.72	3163	3.11	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	0.34	14.76	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:0	32.72	3167	3.12	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	0.49	14.79	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:0	32.72	3180	3.13	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	0.6	14.85	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:0	32.72	3198	3.14	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	0.59	14.89	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:1	31.36	3202	3.14	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	0.64	14.94	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:1	31.36	3203	3.15	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	0.7	15	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:1	31.36	3204	3.16	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	0.71	15.08	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:1	31.36	3201	3.17	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	0.74	15.08	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:1	31.36	3203	3.17	13.57	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	0.87	15.08	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:1	31.36	3203	3.18	13.56	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	0.88	15.09	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:1	31.36	3206	3.19	13.57	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	0.89	15.06	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:2	31.36	3210	3.2	13.57	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.96	15.02	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:2	31.36	3213	3.2	13.57	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.92	14.98	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:2	31.36	3214	3.21	13.58	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.01	14.9	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:2	31.36	3224	3.21	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.97	14.83	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:2	31.36	3234	3.21	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.04	14.79	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:2	31.36	3246	3.22	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.08	14.71	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:3	31.36	3255	3.22	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.03	14.73	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:3	31.36	3259	3.22	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.06	14.74	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:3	31.36	3271	3.23	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.03	14.77	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:3	31.36	3299	3.23	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.05	14.78	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:3	31.36	3288	3.23	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	1.05	14.79	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:3	31.36	3282	3.23	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	1.05	14.82	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:4	31.36	3286	3.23	13.6	96	191	Off Idle	41.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	1	14.83	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:4	31.36	3286	3.23	13.58	96	191	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	1.03	14.83	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:4	31.36	3278	3.23	13.58	96	191	Off Idle	41.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	0.92	14.83	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:4	31.36	3304	3.23	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	0.91	14.84	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:4	32.72	3359	3.23	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	0.92	14.86	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:4	32.72	3338	3.24	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	0.91	14.87	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:4	32.72	3331	3.24	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	0.83	14.93	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:10:44:5	32.72	3344	3.24	13.6	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	0.8	15	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:10:44:5	32.72	3318	3.23	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	0.8	15	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:10:44:5	31.36	3330	3.23	13.58	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	0.73	14.99	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:10:44:5	31.36	3344	3.23	13.58	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	0.62	14.99	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:10:44:5	31.36	3342	3.23	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.56	14.95	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:10:44:5	31.36	3340	3.22	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.46	14.93	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:10:44:6	31.36	3346	3.22	13.58	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.34	14.89	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:10:44:6	31.36	3328	3.21	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.21	14.87	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:10:44:6	31.36	3329	3.2	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.09	14.83	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:44:6	31.36	3338	3.19	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.16	14.74	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:10:44:6	32.72	3350	3.18	13.6	97	192	Off Idle	41.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.23	14.71	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:6	32.72	3363	3.18	13.59	97	192	Off Idle	41.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.32	14.71	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:6	32.72	3367	3.17	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.42	14.73	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:7	32.72	3371	3.16	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.43	14.77	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:7	34.08	3377	3.15	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.54	14.8	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:7	34.08	3379	3.15	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-0.61	14.82	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:7	34.08	3387	3.14	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-0.6	14.83	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:44:7	34.08	3384	3.13	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-0.79	14.83	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:44:7	34.08	3393	3.12	13.58	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-0.85	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:44:8	34.08	3394	3.11	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-0.93	14.88	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:10:44:8	34.08	3416	3.1	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.2	Rich	1	14.6	-1.02	14.95	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:8	34.08	3424	3.09	13.59	97	192	Off Idle	41.7	0	2	132	944 Turbo	0.15	Rich	1	14.6	-1.02	14.98	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:8	34.08	3431	3.08	13.58	97	192	Off Idle	41.7	0	2	132	944 Turbo	0.11	Rich	1	14.6	-1.07	15.01	1.02	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:10:44:8	34.08	3431	3.08	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-1.16	15.06	1.03	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:8	34.08	3432	3.07	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-1.22	15.14	1.03	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:9	34.08	3436	3.07	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-1.31	15.18	1.03	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:9	34.08	3434	3.06	13.59	97	192	Off Idle	41.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-1.48	15.25	1.04	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:10:44:9	34.08	3433	3.05	13.61	97	192	Off Idle	41.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-1.51	15.31	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:10:44:9	34.08	3437	3.05	13.59	97	192	Off Idle	41.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-1.57	15.31	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:44:9	34.08	3437	3.04	13.61	96	191	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-1.69	15.3	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:10:44:9	34.08	3442	3.03	13.59	96	191	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-1.81	15.25	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:44:9	34.08	3449	3.03	13.6	96	191	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-1.96	15.23	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:10:45:0	34.08	3456	3.02	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-2.05	15.18	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:45:0	34.08	3456	3.01	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.19	15.15	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:45:0	34.08	3456	3	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.31	15.12	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:45:0	34.08	3459	2.99	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.35	15.09	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:45:0	34.08	3468	2.98	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.49	15.07	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:45:0	34.08	3463	2.97	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.63	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:45:1	34.08	3463	2.95	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-2.76	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:10:45:1	34.08	3455	2.94	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.86	15.01	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:45:1	34.08	3457	2.92	13.61	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.03	15	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:10:45:1	34.08	3452	2.91	13.59	97	191	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.2	15.01	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:1	35.45	3466	2.89	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.35	15.01	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:1	35.45	3473	2.87	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.54	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:45:1	35.45	3484	2.85	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.94	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:10:45:2	35.45	3492	2.83	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.24	15.06	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:45:2	35.45	3490	2.79	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.63	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:45:2	35.45	3490	2.78	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:45:2	35.45	3482	2.73	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.27	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:2	35.45	3474	2.69	13.57	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.84	15.15	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:45:2	36.81	3489	2.62	13.57	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.2	15.15	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:45:3	36.81	3465	2.57	13.58	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.62	15.14	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:45:3	36.81	3439	2.52	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.23	15.19	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:45:3	36.81	3430	2.47	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.59	15.2	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:45:3	36.81	3426	2.42	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.92	15.18	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:45:3	38.18	3386	2.34	13.62	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.19	15.13	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:45:3	38.18	3384	2.28	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.41	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:45:4	38.18	3373	2.2	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.66	15	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:45:4	38.18	3355	2.14	13.61	97	192	Full Load	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.86	14.94	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:4	38.18	3348	2.08	13.6	97	192	Full Load	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.01	14.89	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:45:4	38.18	3337	2	13.6	97	192	Idle	41.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.16	14.83	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:45:4	38.18	3329	1.95	13.59	97	192	Idle	41.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.28	14.74	1	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:45:4	38.18	3350	1.91	13.61	97	192	Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.38	14.7	1	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:45:4	38.18	3358	1.86	13.62	97	192	Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.39	14.69	1	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:45:5	32.72	3346	1.82	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.46	14.66	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:5	27.27	3390	1.79	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.42	14.67	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:5	21.81	3398	1.77	13.61	97	191	Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.47	14.7	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:45:5	20.45	3481	1.73	13.59	96	192	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.52	14.79	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:5	20.45	3481	1.71	13.61	96	192	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.6	14.87	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:5	20.45	3489	1.69	13.6	96	192	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.61	14.95	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:6	20.45	3484	1.68	13.61	96	192	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.69	15.11	1.03	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:6	20.45	3502	1.66	13.6	96	192	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.76	15.23	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:6	20.45	3486	1.66	13.6	97	192	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.75	15.44	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:6	20.45	3420	1.65	13.6	97	192	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.74	15.62	1.06	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:6	20.45	3412	1.65	13.6	97	192	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	15.79	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:6	20.45	3394	1.65	13.61	96	192	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	15.88	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:6	20.45	3356	1.66	13.62	96	192	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	16.2	1.1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:7	20.45	3363	1.66	13.62	97	192	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	16.47	1.12	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:7	20.45	3368	1.66	13.62	97	192	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	16.81	1.15	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:7	20.45	3364	1.66	13.61	97	192	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	17.43	1.19	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:7	20.45	3362	1.67	13.62	97	192	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	17.85	1.22	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:7	20.45	3365	1.67	13.61	97	192	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	18.47	1.24	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:7	20.45	3352	1.67	13.61	97	192	Idle	40	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	18.85	1.28	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:8	20.45	3372	1.68	13.61	97	192	Idle	39.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	19.03	1.3	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:8	20.45	3386	1.68	13.6	97	192	Idle	39.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	19.37	1.32	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:8	20.45	3410	1.69	13.61	97	192	Idle	39.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	19.81	1.35	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:8	20.45	3402	1.69	13.6	97	192	Idle	39.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.03	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:8	20.45	3402	1.69	13.62	96	192	Idle	39.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.15	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:8	20.45	3402	1.69	13.62	96	192	Idle	39.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:9	20.45	3396	1.7	13.6	96	192	Idle	39.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:9	20.45	3395	1.7	13.61	97	192	Idle	39.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:9	20.45	3384	1.7	13.62	97	192	Idle	39.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:9	20.45	3376	1.7	13.61	97	192	Idle	39.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:9	20.45	3374	1.7	13.61	97	192	Idle	39.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:9	20.45	3355	1.7	13.61	97	192	Idle	40.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:45:9	20.45	3347	1.7	13.61	97	192	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:0	20.45	3344	1.7	13.62	97	192	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:0	20.45	3334	1.7	13.6	97	192	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:0	20.45	3303	1.7	13.6	97	192	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:0	20.45	3316	1.71	13.62	97	192	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:0	20.45	3332	1.71	13.61	97	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:0	20.45	3332	1.71	13.62	97	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:1	20.45	3335	1.7	13.62	96	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:1	20.45	3335	1.7	13.62	96	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:1	20.45	3338	1.7	13.63	96	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:1	20.45	3340	1.7	13.62	96	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:1	20.45	3341	1.7	13.62	96	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:1	20.45	3338	1.7	13.61	96	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:1	20.45	3336	1.7	13.61	96	192	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:2	20.45	3331	1.7	13.62	96	192	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:2	20.45	3326	1.7	13.6	96	192	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:2	20.45	3324	1.7	13.61	97	192	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:2	20.45	3313	1.7	13.61	97	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:2	20.45	3303	1.7	13.61	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:2	20.45	3300	1.7	13.62	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:3	20.45	3291	1.7	13.62	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:3	20.45	3289	1.7	13.61	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:3	20.45	3279	1.7	13.61	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:3	20.45	3276	1.7	13.6	97	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:3	20.45	3251	1.7	13.6	97	192	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:3	20.45	3254	1.7	13.6	97	192	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:4	20.45	3254	1.7	13.61	97	192	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:4	20.45	3271	1.7	13.62	97	192	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:4	20.45	3272	1.7	13.61	97	192	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:4	20.45	3274	1.7	13.62	97	192	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:46:4	20.45	3278	1.7	13.62	96	192	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:4	20.45	3279	1.7	13.62	96	192	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:4	20.45	3303	1.7	13.61	96	192	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:5	20.45	3292	1.7	13.62	97	192	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:5	20.45	3280	1.7	13.61	97	192	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:5	20.45	3280	1.7	13.62	97	192	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:5	20.45	3278	1.7	13.61	97	192	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:5	20.45	3264	1.7	13.61	97	192	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:5	20.45	3268	1.7	13.62	96	192	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:6	20.45	3247	1.7	13.62	96	192	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:6	20.45	3247	1.7	13.63	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:6	20.45	3252	1.7	13.61	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:6	20.45	3252	1.7	13.63	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:6	20.45	3244	1.7	13.62	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:6	20.45	3240	1.7	13.63	97	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:6	20.45	3213	1.7	13.62	97	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:7	20.45	3228	1.7	13.64	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:7	20.45	3228	1.7	13.62	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:7	20.45	3226	1.7	13.61	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:7	20.45	3220	1.7	13.62	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:7	20.45	3219	1.7	13.6	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:7	20.45	3218	1.7	13.61	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:8	20.45	3214	1.7	13.6	97	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:8	20.45	3212	1.7	13.61	97	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:8	20.45	3211	1.7	13.6	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:8	20.45	3209	1.7	13.61	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:8	20.45	3204	1.7	13.62	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:8	20.45	3202	1.7	13.62	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:9	20.45	3202	1.7	13.62	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:9	20.45	3198	1.7	13.62	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:9	20.45	3198	1.7	13.63	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:9	20.45	3193	1.7	13.62	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:9	20.45	3186	1.7	13.62	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:9	20.45	3186	1.7	13.63	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:46:9	20.45	3182	1.7	13.62	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:0	20.45	3176	1.7	13.63	97	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:0	20.45	3177	1.7	13.62	96	192	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:0	20.45	3171	1.7	13.61	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:0	20.45	3174	1.7	13.62	96	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:0	20.45	3172	1.7	13.62	96	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:0	20.45	3172	1.7	13.62	96	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:1	20.45	3172	1.7	13.62	96	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:1	20.45	3173	1.7	13.62	96	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:1	20.45	3174	1.7	13.62	96	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:1	20.45	3173	1.7	13.61	96	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:1	20.45	3171	1.7	13.63	96	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:1	20.45	3168	1.7	13.62	96	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:1	20.45	3165	1.7	13.63	97	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:2	20.45	3164	1.7	13.62	97	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:2	20.45	3155	1.7	13.62	97	192	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:2	20.45	3148	1.7	13.62	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:2	20.45	3144	1.7	13.62	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:2	20.45	3138	1.7	13.61	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:2	20.45	3109	1.7	13.61	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:3	20.45	3123	1.7	13.62	96	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:3	20.45	3123	1.7	13.61	97	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:3	20.45	3117	1.7	13.63	97	192	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:3	20.45	3116	1.7	13.63	97	192	Full Load	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:47:3	20.45	3111	1.7	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:3	20.45	3030	1.7	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:47:4	20.45	3133	1.7	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:47:4	12.27	3132	1.71	13.58	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:47:4	14.99	3132	1.71	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:47:4	17.72	3134	1.72	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:47:4	20.45	3134	1.72	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:47:4	23.18	3136	1.73	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:47:4	25.9	3135	1.73	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:47:5	25.9	3136	1.74	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:47:5	28.63	3137	1.75	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.45	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:47:5	31.36	3148	1.76	13.62	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.43	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:47:5	34.08	3152	1.77	13.62	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.45	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:47:5	34.08	3152	1.78	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.45	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:5	38.18	3152	1.79	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.47	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:6	38.18	3148	1.79	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:47:6	38.18	3148	1.8	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.44	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:47:6	38.18	3149	1.81	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:47:6	38.18	3146	1.81	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.42	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:47:6	38.18	3136	1.82	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.45	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:6	38.18	3135	1.83	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.44	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:6	38.18	3130	1.84	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.45	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:7	38.18	3126	1.84	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.41	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:7	38.18	3121	1.85	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.42	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:7	38.18	3108	1.85	13.59	96	192	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.37	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:7	38.18	3106	1.86	13.6	96	192	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.37	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:7	38.18	3098	1.86	13.59	96	192	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.36	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:47:7	38.18	3100	1.87	13.61	96	192	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.29	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:47:8	38.18	3100	1.87	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.24	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:47:8	38.18	3090	1.88	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.19	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:47:8	38.18	3094	1.88	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.11	20.2	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:47:8	38.18	3096	1.89	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.07	20.12	1.37	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:47:8	38.18	3094	1.89	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.07	19.97	1.36	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:47:8	38.18	3091	1.91	13.63	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9	19.77	1.35	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:47:9	36.81	3079	1.92	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.88	19.39	1.32	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:47:9	36.81	3092	1.93	13.61	96	192	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.79	19.12	1.3	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:47:9	36.81	3093	1.94	13.61	96	192	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.69	18.82	1.28	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:47:9	36.81	3101	1.96	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.56	18.34	1.25	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:47:9	36.81	3102	1.97	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.56	18.01	1.23	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:47:9	36.81	3106	1.98	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.47	17.67	1.2	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:47:9	36.81	3112	1.98	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.44	17.38	1.18	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:48:0	36.81	3125	2	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.32	17.16	1.17	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:48:0	36.81	3125	2.01	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.24	17	1.16	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:48:0	36.81	3133	2.03	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.15	16.87	1.15	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:48:0	36.81	3134	2.05	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.03	16.69	1.14	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:48:0	36.81	3136	2.06	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.96	16.59	1.13	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:48:0	36.81	3136	2.08	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.89	16.51	1.12	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:48:1	36.81	3134	2.1	13.63	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.8	16.43	1.12	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:48:1	36.81	3131	2.11	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.71	16.32	1.11	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:48:1	36.81	3124	2.13	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.6	16.25	1.11	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:48:1	36.81	3124	2.15	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.56	16.18	1.1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:48:1	36.81	3110	2.16	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.43	16.09	1.1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:48:1	36.81	3106	2.17	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.34	16.03	1.09	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:48:1	36.81	3106	2.18	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	15.95	1.09	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:48:2	36.81	3106	2.2	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.2	15.88	1.08	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:48:2	36.81	3106	2.22	13.61	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.11	15.79	1.08	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:48:2	36.81	3100	2.23	13.59	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.03	15.72	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:48:2	36.81	3100	2.24	13.59	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.96	15.67	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:48:2	36.81	3100	2.27	13.59	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.85	15.62	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:2	36.81	3110	2.28	13.58	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.76	15.52	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:3	36.81	3116	2.3	13.58	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.66	15.45	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:3	36.81	3126	2.31	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.52	15.37	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:3	36.81	3141	2.32	13.6	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.44	15.32	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:3	36.81	3144	2.33	13.62	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.4	15.27	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:3	36.81	3150	2.34	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.38	15.2	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:3	36.81	3159	2.35	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.36	15.17	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:4	36.81	3158	2.36	13.62	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.31	15.13	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:4	36.81	3158	2.37	13.61	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.27	15.12	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:4	35.45	3128	2.38	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.27	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:4	35.45	3141	2.39	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.26	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:4	35.45	3141	2.4	13.58	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.29	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:4	35.45	3132	2.41	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.26	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:4	35.45	3123	2.42	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.28	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:5	35.45	3113	2.43	13.57	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.24	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:5	35.45	3120	2.43	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.2	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:5	35.45	3116	2.44	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.22	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:5	35.45	3116	2.44	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.22	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:5	35.45	3130	2.44	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.17	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:5	35.45	3139	2.44	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.23	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:6	35.45	3151	2.44	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.2	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:6	35.45	3156	2.44	13.6	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.2	14.77	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:6	35.45	3164	2.44	13.59	97	192	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.21	14.78	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:6	35.45	3168	2.44	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.15	14.78	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:6	35.45	3168	2.44	13.58	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.13	14.79	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:6	35.45	3166	2.44	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.16	14.81	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:6	35.45	3162	2.44	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.18	14.81	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:7	35.45	3205	2.44	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.2	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:7	35.45	3159	2.44	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.18	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:7	35.45	3159	2.44	13.58	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.19	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:7	35.45	3155	2.44	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.18	14.81	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:7	35.45	3160	2.44	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.19	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:7	35.45	3160	2.44	13.59	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.23	14.79	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:8	35.45	3168	2.44	13.61	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.26	14.79	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:8	35.45	3172	2.44	13.61	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.19	14.79	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:48:8	35.45	3172	2.44	13.6	96	192	Off Idle	41.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.25	14.71	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:8	35.45	3173	2.44	13.6	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.2	14.72	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:8	35.45	3176	2.44	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.21	14.75	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:8	35.45	3176	2.44	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.25	14.78	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:9	35.45	3176	2.44	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.28	14.82	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:9	35.45	3225	2.44	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.28	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:9	35.45	3199	2.44	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.3	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:9	35.45	3170	2.44	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.32	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:9	35.45	3166	2.43	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.28	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:9	35.45	3166	2.43	13.63	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.25	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:48:9	35.45	3171	2.43	13.64	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.3	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:0	35.45	3175	2.43	13.64	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.25	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:0	35.45	3181	2.43	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.29	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:0	35.45	3181	2.43	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.31	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:0	35.45	3180	2.43	13.61	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.33	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:0	35.45	3184	2.43	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.27	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:0	35.45	3184	2.43	13.6	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.32	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:1	35.45	3188	2.43	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.26	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:1	35.45	3193	2.43	13.62	96	192	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.34	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:1	35.45	3196	2.43	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.32	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:1	35.45	3196	2.43	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.34	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:1	35.45	3190	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.39	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:49:1	35.45	3194	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.4	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:1	35.45	3197	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.38	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:2	35.45	3197	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.4	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:2	35.45	3200	2.42	13.6	97	193	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.41	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:2	35.45	3208	2.42	13.6	97	193	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.38	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:2	35.45	3208	2.42	13.6	97	193	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.38	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:2	35.45	3214	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.45	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:2	35.45	3218	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.45	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:3	35.45	3215	2.42	13.61	96	193	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.51	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:3	36.81	3222	2.42	13.59	96	193	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.5	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:3	36.81	3213	2.42	13.59	96	193	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.47	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:3	36.81	3207	2.42	13.6	96	193	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.43	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:3	36.81	3207	2.42	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.44	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:3	36.81	3209	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.42	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:4	35.45	3189	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.44	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:4	35.45	3206	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.42	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:4	35.45	3210	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.49	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:4	35.45	3208	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.44	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:4	35.45	3205	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.47	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:4	36.81	3210	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.39	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:4	36.81	3210	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.4	14.9	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:5	36.81	3218	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.39	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:5	36.81	3223	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.44	14.83	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:5	35.45	3205	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.46	14.78	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:5	35.45	3218	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.48	14.78	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:5	35.45	3238	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.48	14.79	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:5	35.45	3238	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.48	14.79	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:6	35.45	3236	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.48	14.79	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:6	36.81	3232	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.48	14.8	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:6	36.81	3230	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.46	14.82	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:6	36.81	3230	2.42	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.48	14.82	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:6	36.81	3218	2.42	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.44	14.83	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:6	36.81	3218	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.47	14.85	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:6	36.81	3236	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.47	14.86	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:7	36.81	3236	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.54	14.87	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:7	36.81	3235	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.48	14.87	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:7	36.81	3235	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.56	14.91	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:7	36.81	3241	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.53	14.94	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:7	36.81	3243	2.42	13.63	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.52	14.95	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:7	36.81	3271	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.55	14.94	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:49:8	36.81	3258	2.42	13.63	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.51	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:49:8	36.81	3252	2.42	13.63	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.44	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:49:8	36.81	3247	2.42	13.63	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.45	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:49:8	36.81	3247	2.42	13.64	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.49	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:49:8	36.81	3232	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.45	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:49:8	36.81	3245	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.46	14.81	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:9	36.81	3246	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.5	14.78	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:9	36.81	3245	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.5	14.78	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:9	36.81	3276	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.49	14.8	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:9	36.81	3264	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.52	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:49:9	36.81	3252	2.41	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.55	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:9	36.81	3255	2.41	13.63	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.58	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:49:9	36.81	3261	2.41	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.61	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:0	36.81	3271	2.41	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.56	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:0	36.81	3273	2.41	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.57	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:0	36.81	3275	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.52	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:0	36.81	3278	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.54	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:0	36.81	3324	2.41	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.52	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:50:0	36.81	3270	2.41	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.54	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:1	36.81	3266	2.41	13.57	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.58	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:1	36.81	3266	2.41	13.58	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.54	15.03	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:1	36.81	3262	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.57	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:1	36.81	3236	2.41	13.6	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.58	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:1	36.81	3261	2.41	13.61	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.58	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:1	36.81	3261	2.41	13.61	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.56	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:1	36.81	3259	2.41	13.61	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.55	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:2	36.81	3263	2.41	13.61	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.59	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:2	36.81	3266	2.41	13.62	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.54	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:2	36.81	3270	2.41	13.61	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.59	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:2	36.81	3280	2.41	13.63	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.58	14.9	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:2	36.81	3282	2.41	13.62	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.55	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:2	36.81	3296	2.41	13.62	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.53	14.85	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:3	36.81	3299	2.41	13.62	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.58	14.83	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:3	36.81	3301	2.41	13.6	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.55	14.82	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:3	36.81	3302	2.41	13.61	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.62	14.84	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:3	36.81	3298	2.41	13.62	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.55	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:3	36.81	3295	2.41	13.6	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.61	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:3	36.81	3294	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.64	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:4	36.81	3288	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.64	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:4	36.81	3282	2.41	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.64	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:4	36.81	3274	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.67	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:4	36.81	3276	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.63	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:4	36.81	3276	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.59	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:4	36.81	3275	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.58	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:4	36.81	3282	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.54	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:5	36.81	3291	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.6	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:5	36.81	3292	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	-6.56	15.01	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:5	36.81	3298	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.62	14.98	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:5	36.81	3327	2.41	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.57	14.95	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:5	36.81	3307	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.63	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:5	36.81	3308	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.63	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:6	36.81	3309	2.41	13.58	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.65	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:6	36.81	3309	2.42	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.65	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:6	36.81	3309	2.42	13.57	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.66	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:6	36.81	3306	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.7	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:6	36.81	3305	2.41	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.63	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:6	36.81	3304	2.41	13.6	97	193	Off Idle	41.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.63	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:6	36.81	3304	2.41	13.6	97	193	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.66	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:7	36.81	3304	2.41	13.6	97	193	Off Idle	41.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.61	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:7	36.81	3306	2.41	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.58	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:7	36.81	3308	2.41	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.64	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:7	36.81	3316	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.57	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:7	36.81	3317	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.6	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:7	36.81	3322	2.41	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.6	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:8	36.81	3322	2.41	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.6	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:8	36.81	3317	2.41	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.63	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:8	36.81	3319	2.41	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.64	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:8	36.81	3320	2.42	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.64	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:8	36.81	3320	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.64	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:50:8	36.81	3317	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.65	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:9	36.81	3317	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.67	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:9	36.81	3318	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.66	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:9	36.81	3318	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.67	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:9	36.81	3320	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.67	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:9	36.81	3326	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.7	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:50:9	36.81	3330	2.42	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.71	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:50:9	36.81	3334	2.42	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.72	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:51:0	36.81	3335	2.42	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.72	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:51:0	36.81	3339	2.42	13.58	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.72	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:51:0	36.81	3340	2.42	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.67	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:51:0	36.81	3340	2.42	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.69	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:0	36.81	3335	2.42	13.62	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.69	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:0	36.81	3328	2.42	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.73	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:1	36.81	3322	2.42	13.63	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.74	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:51:1	36.81	3316	2.41	13.63	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	-6.77	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:51:1	36.81	3316	2.41	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.75	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:1	36.81	3317	2.4	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.92	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:1	36.81	3322	2.4	13.6	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.96	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:1	36.81	3328	2.39	13.59	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.16	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:51:1	36.81	3330	2.35	13.58	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.57	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:51:2	36.81	3337	2.32	13.61	96	193	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.83	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:51:2	36.81	3337	2.29	13.59	96	193	Off Idle	41.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.14	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:51:2	36.81	3332	2.25	13.62	96	193	Full Load	41.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.43	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:51:2	36.81	3330	2.19	13.59	96	193	Idle	41.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.72	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:51:2	38.18	3346	2.16	13.61	96	193	Idle	41.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.1	14.8	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:2	38.18	3306	2.12	13.61	97	193	Idle	41.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.28	14.81	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:3	38.18	3296	2.07	13.61	97	193	Idle	41.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.45	14.82	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:3	38.18	3296	2.05	13.61	97	193	Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.56	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:3	38.18	3233	2	13.62	96	193	Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.64	14.86	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:3	35.45	3198	1.96	13.61	96	193	Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.71	14.91	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:3	29.99	3184	1.91	13.61	96	193	Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.77	14.95	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:3	24.54	3168	1.87	13.6	96	193	Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.77	14.96	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:4	20.45	3168	1.82	13.61	96	193	Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.84	14.95	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:4	20.45	3170	1.77	13.61	96	193	Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.86	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:4	20.45	3155	1.73	13.63	96	193	Idle	41.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.89	14.8	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:4	20.45	3155	1.72	13.64	96	193	Idle	41.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.97	14.72	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:4	20.45	3100	1.7	13.63	96	193	Idle	40.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.97	14.63	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:4	20.45	3081	1.7	13.62	96	193	Idle	40.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.95	14.43	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:4	20.45	3059	1.7	13.62	96	193	Idle	40	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.94	14.31	0.97	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:5	20.45	3024	1.71	13.61	96	193	Idle	39.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.87	14.19	0.97	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:5	20.45	3016	1.71	13.62	96	193	Idle	38.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.81	14.13	0.96	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:5	20.45	2975	1.71	13.62	96	193	Idle	37.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.76	14.07	0.96	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:5	20.45	2952	1.71	13.62	96	193	Idle	36.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.7	14.04	0.96	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:5	19.09	2952	1.72	13.62	96	193	Idle	35.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.64	14.03	0.96	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:5	19.09	2897	1.72	13.63	96	193	Idle	34.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.56	14.04	0.96	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:6	19.09	2879	1.73	13.62	96	193	Idle	33.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.52	14.06	0.96	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:6	19.09	2842	1.73	13.61	96	193	Idle	32.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.48	14.08	0.96	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:6	19.09	2828	1.74	13.6	96	193	Idle	31.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.42	14.15	0.96	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:6	19.09	2795	1.75	13.61	96	193	Idle	30.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.36	14.24	0.97	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:6	19.09	2761	1.75	13.6	96	193	Idle	29.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.33	14.31	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:6	19.09	2762	1.76	13.61	96	193	Idle	28.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	14.39	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:6	19.09	2738	1.77	13.63	96	193	Idle	28.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.21	14.46	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:7	19.09	2691	1.77	13.65	96	193	Idle	28.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	14.56	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:7	19.09	2680	1.78	13.63	96	193	Idle	28.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.12	14.74	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:7	19.09	2680	1.79	13.63	96	193	Idle	28.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	14.93	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:7	19.09	2645	1.79	13.63	96	193	Idle	28.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.03	15.36	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:7	19.09	2620	1.8	13.61	96	193	Idle	28.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	15.82	1.08	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:7	19.09	2597	1.8	13.6	96	193	Idle	29.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.96	16.36	1.11	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:8	19.09	2562	1.8	13.61	96	193	Idle	31.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.93	17.18	1.17	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:8	19.09	2562	1.8	13.6	96	193	Idle	32	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.93	17.73	1.21	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:8	19.09	2509	1.8	13.59	96	193	Idle	33	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.89	18.26	1.24	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:8	19.09	2494	1.8	13.61	96	193	Idle	33.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.88	18.77	1.28	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:8	19.09	2494	1.8	13.6	96	193	Idle	34.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.86	19.24	1.31	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:8	19.09	2457	1.79	13.6	96	193	Idle	36	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.85	19.83	1.35	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:51:9	19.09	2442	1.79	13.6	96	193	Idle	37.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.83	19.98	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:9	19.09	2388	1.78	13.62	96	193	Idle	39.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.83	20.16	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:9	19.09	2389	1.78	13.61	96	193	Full Load	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.87	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:9	19.09	2380	1.77	13.61	96	193	Off Idle	42.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.86	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:9	19.09	2336	1.76	13.61	96	193	Off Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.86	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:9	19.09	2334	1.75	13.62	96	193	Off Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.85	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:51:9	19.09	2328	1.75	13.6	96	193	Off Idle	46.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.82	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:52:0	10.9	2233	1.74	13.6	96	193	Off Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.71	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:0	10.9	2280	1.74	13.59	96	193	Off Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.62	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:0	13.63	2264	1.74	13.59	97	193	Off Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.55	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:0	13.63	2228	1.73	13.57	97	193	Off Idle	57.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.49	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:52:0	16.36	2228	1.72	13.57	97	193	Off Idle	60.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.46	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:52:0	19.09	2192	1.69	13.59	96	193	Off Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.49	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:52:1	19.09	2197	1.69	13.59	96	193	Off Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.52	20.25	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:1	21.81	2203	1.66	13.61	96	193	Off Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.59	20.25	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:1	21.81	2212	1.65	13.62	96	193	Off Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.62	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:52:1	24.54	2252	1.64	13.63	96	193	Off Idle	74.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:52:1	27.27	2283	1.63	13.61	96	193	Off Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.8	20.23	1.38	3.3	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:52:1	27.27	2296	1.62	13.6	96	193	Off Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.88	20.23	1.38	3.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:1	29.99	2288	1.61	13.59	96	193	Off Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.94	20.23	1.38	3.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:2	29.99	2288	1.6	13.59	96	193	Off Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:52:2	32.72	2289	1.59	13.61	96	193	Off Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.05	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:52:2	34.08	2290	1.58	13.62	96	193	Off Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:52:2	34.08	2272	1.57	13.62	96	193	Off Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:2	34.08	2272	1.57	13.62	96	193	Off Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:2	34.08	2272	1.55	13.61	96	193	Off Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:3	34.08	2271	1.54	13.6	96	193	Off Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:3	34.08	2267	1.53	13.6	96	193	Off Idle	80.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.22	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:3	34.08	2266	1.52	13.6	96	193	Off Idle	80.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.21	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:3	34.08	2259	1.52	13.63	96	193	Off Idle	80.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.17	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:3	34.08	2262	1.53	13.64	96	193	Off Idle	79.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.17	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:3	34.08	2238	1.54	13.64	96	193	Off Idle	79.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.19	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:4	34.08	2222	1.54	13.62	96	193	Off Idle	79.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.21	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:4	34.08	2222	1.54	13.6	96	193	Off Idle	79.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.19	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:4	34.08	2206	1.54	13.6	96	193	Off Idle	79.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.18	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:4	34.08	2210	1.54	13.58	96	193	Off Idle	80	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.2	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:4	34.08	2208	1.54	13.59	96	193	Off Idle	80.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.19	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:4	34.08	2206	1.54	13.59	96	193	Off Idle	80.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.17	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:4	34.08	2206	1.54	13.57	96	193	Off Idle	80.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.2	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:5	34.08	2200	1.54	13.58	96	193	Off Idle	81	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.2	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:5	34.08	2214	1.54	13.59	96	193	Off Idle	81.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.16	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:5	34.08	2217	1.54	13.61	96	193	Off Idle	81.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.18	20.19	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:5	34.08	2220	1.54	13.62	96	193	Off Idle	81.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.15	20.11	1.37	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:5	34.08	2230	1.53	13.64	96	193	Off Idle	82	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.15	20	1.36	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:5	34.08	2227	1.53	13.65	96	193	Off Idle	82.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.17	19.76	1.35	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:6	34.08	2227	1.53	13.63	96	193	Off Idle	82.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.19	19.58	1.33	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:6	34.08	2235	1.53	13.62	96	193	Off Idle	82.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.22	19.36	1.32	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:6	34.08	2239	1.52	13.61	96	193	Off Idle	82.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.24	19.12	1.3	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:6	34.08	2239	1.52	13.59	96	193	Off Idle	82.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.25	18.73	1.28	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:6	34.08	2241	1.52	13.59	96	193	Off Idle	82.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.25	18.47	1.26	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:6	34.08	2241	1.52	13.61	96	193	Off Idle	82.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.21	18.36	1.25	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:6	34.08	2246	1.52	13.62	96	193	Off Idle	82.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.19	18.02	1.23	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:7	34.08	2250	1.51	13.65	96	193	Off Idle	82.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.21	17.72	1.21	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:7	34.08	2250	1.51	13.65	96	193	Off Idle	81.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.19	17.54	1.19	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:7	34.08	2251	1.51	13.66	96	193	Off Idle	81.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.2	17.37	1.18	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:7	34.08	2248	1.51	13.65	96	193	Off Idle	81.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.25	17.15	1.17	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:7	34.08	2239	1.51	13.65	96	193	Off Idle	81.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.26	17	1.16	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:7	34.08	2229	1.51	13.63	96	193	Off Idle	80.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.3	16.79	1.14	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:52:8	34.08	2213	1.51	13.62	96	193	Off Idle	80.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.31	16.64	1.13	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:8	34.08	2213	1.51	13.61	96	193	Off Idle	80.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.29	16.52	1.13	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:8	34.08	2200	1.51	13.59	96	193	Off Idle	80.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.31	16.4	1.12	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:8	34.08	2206	1.52	13.59	96	193	Off Idle	80.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.26	16.29	1.11	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:8	34.08	2208	1.52	13.6	96	193	Off Idle	80.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.25	16.18	1.1	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:8	34.08	2208	1.52	13.61	96	193	Off Idle	81.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.23	16.05	1.09	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:9	34.08	2213	1.52	13.61	96	193	Off Idle	81.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.19	15.96	1.09	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:9	34.08	2218	1.52	13.63	96	193	Off Idle	81.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.18	15.88	1.08	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:9	34.08	2220	1.52	13.64	96	193	Off Idle	81.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.17	15.79	1.08	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:9	34.08	2223	1.52	13.64	96	193	Off Idle	81.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.14	15.79	1.08	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:9	34.08	2249	1.52	13.63	96	193	Off Idle	82	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.14	15.71	1.07	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:52:9	34.08	2242	1.52	13.63	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.14	15.65	1.07	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:52:9	34.08	2235	1.53	13.62	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.17	15.6	1.06	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:0	34.08	2234	1.53	13.6	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.15	15.58	1.06	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:0	34.08	2233	1.53	13.59	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.15	15.58	1.06	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:0	34.08	2227	1.53	13.59	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.17	15.52	1.06	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:0	34.08	2224	1.53	13.59	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.19	15.49	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:0	34.08	2218	1.54	13.6	96	193	Off Idle	82.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.15	15.43	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:0	34.08	2202	1.54	13.6	96	193	Off Idle	82.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.14	15.41	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:1	34.08	2202	1.54	13.6	96	193	Off Idle	82.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.12	15.37	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:1	34.08	2200	1.54	13.61	96	193	Off Idle	82	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.07	15.32	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:1	34.08	2204	1.54	13.63	96	193	Off Idle	82.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.06	15.29	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:1	34.08	2207	1.55	13.64	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.02	15.26	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:1	34.08	2194	1.55	13.64	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9	15.22	1.04	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:1	34.08	2202	1.55	13.64	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.98	15.19	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:1	34.08	2232	1.55	13.63	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.94	15.16	1.03	3.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:2	34.08	2227	1.55	13.62	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.91	15.14	1.03	3.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:2	34.08	2234	1.56	13.62	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.94	15.13	1.03	3.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:2	34.08	2234	1.56	13.63	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.96	15.13	1.03	3.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:2	34.08	2230	1.56	13.64	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.98	15.1	1.03	3.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:2	34.08	2239	1.56	13.63	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.03	15.07	1.03	3.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:2	34.08	2228	1.56	13.63	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.04	15.04	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:3	34.08	2228	1.57	13.61	96	193	Off Idle	82.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.04	15.01	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:3	34.08	2211	1.57	13.59	96	193	Off Idle	82	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.05	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:3	34.08	2202	1.57	13.58	96	193	Off Idle	82	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:53:3	34.08	2192	1.57	13.58	96	193	Off Idle	82	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.97	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:3	34.08	2201	1.57	13.58	96	193	Off Idle	82	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.93	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:3	34.08	2203	1.57	13.61	96	193	Off Idle	82	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.89	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:4	34.08	2214	1.57	13.63	96	193	Off Idle	82	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.89	14.82	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:4	34.08	2214	1.57	13.64	96	193	Off Idle	82.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.89	14.8	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:4	34.08	2218	1.57	13.65	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.89	14.8	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:4	34.08	2225	1.57	13.65	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.89	14.8	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:4	34.08	2225	1.58	13.64	96	194	Off Idle	82.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.86	14.8	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:4	34.08	2221	1.58	13.64	96	194	Off Idle	82.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.83	14.8	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:4	34.08	2221	1.58	13.64	96	194	Off Idle	82.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.83	14.81	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:5	34.08	2220	1.58	13.64	96	194	Off Idle	82.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.83	14.83	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:5	34.08	2218	1.59	13.64	96	193	Off Idle	82.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.78	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:53:5	34.08	2217	1.59	13.65	96	193	Off Idle	82.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.79	14.84	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:5	34.08	2216	1.6	13.64	96	193	Off Idle	82.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.77	14.85	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:5	34.08	2216	1.6	13.64	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.74	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:5	34.08	2212	1.6	13.63	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.73	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:6	34.08	2212	1.6	13.62	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.73	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:6	34.08	2204	1.61	13.61	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.73	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:6	34.08	2214	1.61	13.6	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.73	14.79	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:6	34.08	2214	1.61	13.59	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.7	14.79	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:6	34.08	2220	1.62	13.59	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.68	14.8	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:6	34.08	2235	1.62	13.59	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.68	14.82	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:6	34.08	2218	1.62	13.59	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.66	14.83	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:53:7	34.08	2220	1.63	13.59	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.65	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:7	34.08	2220	1.63	13.59	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.67	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:7	34.08	2218	1.63	13.58	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.66	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:7	34.08	2238	1.64	13.58	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.67	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:7	34.08	2221	1.64	13.59	96	194	Off Idle	82.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.68	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:7	34.08	2221	1.65	13.6	96	194	Off Idle	82.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.68	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:8	34.08	2211	1.65	13.61	96	194	Off Idle	82.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.62	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:8	34.08	2210	1.65	13.62	96	194	Off Idle	82.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.59	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:8	34.08	2192	1.65	13.63	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.53	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:8	34.08	2212	1.65	13.63	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.53	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:8	34.08	2214	1.65	13.62	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.53	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:8	34.08	2218	1.65	13.61	96	194	Off Idle	82.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.55	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:9	34.08	2224	1.66	13.6	96	194	Off Idle	82.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.59	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:9	34.08	2229	1.66	13.58	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.6	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:9	34.08	2230	1.66	13.59	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.57	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:9	34.08	2230	1.66	13.6	96	194	Off Idle	82.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.55	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:9	34.08	2224	1.66	13.6	96	193	Off Idle	82.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.48	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:9	34.08	2221	1.66	13.61	96	193	Off Idle	82	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.49	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:53:9	34.08	2215	1.66	13.62	96	193	Off Idle	82	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.47	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:0	34.08	2214	1.66	13.63	96	193	Off Idle	82	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.44	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:0	34.08	2208	1.66	13.63	96	193	Off Idle	82	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.46	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:0	34.08	2207	1.67	13.64	96	193	Off Idle	82.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.44	14.79	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:0	34.08	2207	1.67	13.64	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.42	14.77	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:0	34.08	2203	1.67	13.64	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.41	14.76	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:0	34.08	2211	1.67	13.63	96	193	Off Idle	82.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.41	14.75	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:1	34.08	2220	1.68	13.63	96	193	Off Idle	82.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.41	14.76	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:54:1	34.08	2220	1.68	13.61	96	193	Off Idle	82.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.41	14.76	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:54:1	34.08	2230	1.69	13.59	96	193	Off Idle	82.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.4	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:54:1	34.08	2236	1.69	13.58	96	194	Off Idle	82.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.36	14.78	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:1	34.08	2236	1.7	13.58	96	194	Off Idle	82.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.34	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:1	34.08	2235	1.71	13.58	96	194	Off Idle	82.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.26	14.82	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:1	34.08	2235	1.71	13.59	96	194	Off Idle	82.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.21	14.82	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:2	34.08	2230	1.72	13.59	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.15	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:2	34.08	2230	1.73	13.59	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.08	14.85	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:54:2	34.08	2230	1.74	13.62	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:54:2	34.08	2228	1.74	13.62	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.98	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:54:2	34.08	2223	1.75	13.64	96	194	Off Idle	82.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.95	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:54:2	32.72	2207	1.76	13.64	96	194	Off Idle	82.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.94	14.84	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:54:3	32.72	2223	1.76	13.63	96	194	Off Idle	81.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.93	14.85	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:54:3	32.72	2222	1.77	13.63	96	194	Off Idle	81.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.91	14.89	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:54:3	32.72	2222	1.78	13.61	96	194	Off Idle	81.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.92	14.92	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:3	32.72	2231	1.78	13.62	96	194	Off Idle	81.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.92	14.94	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:3	32.72	2223	1.79	13.6	96	194	Off Idle	81.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.92	14.96	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:3	32.72	2223	1.79	13.6	96	194	Off Idle	81.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.92	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:4	32.72	2228	1.8	13.6	96	194	Off Idle	81.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.87	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:4	32.72	2230	1.8	13.62	96	194	Off Idle	81.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.81	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:4	32.72	2229	1.8	13.63	96	194	Off Idle	81.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.76	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:4	32.72	2228	1.8	13.64	96	194	Off Idle	81.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:4	32.72	2224	1.8	13.65	96	194	Off Idle	81.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:4	32.72	2232	1.81	13.63	96	194	Off Idle	81.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:4	32.72	2227	1.81	13.62	96	194	Off Idle	81.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:5	32.72	2227	1.81	13.63	96	194	Off Idle	81.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:5	32.72	2232	1.81	13.61	96	194	Off Idle	81.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:5	32.72	2222	1.81	13.61	96	194	Off Idle	81.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.66	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:5	32.72	2222	1.81	13.61	96	194	Off Idle	81.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:5	32.72	2227	1.82	13.61	96	194	Off Idle	81.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:54:5	32.72	2223	1.82	13.6	96	194	Off Idle	81.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:54:6	32.72	2222	1.83	13.61	96	194	Off Idle	81.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.59	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:54:6	32.72	2228	1.84	13.6	96	194	Off Idle	81.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.53	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:54:6	32.72	2234	1.84	13.59	96	194	Off Idle	81.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.49	14.81	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:54:6	32.72	2242	1.85	13.57	96	194	Off Idle	81.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.46	14.77	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:54:6	32.72	2248	1.86	13.59	96	194	Off Idle	81.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.38	14.76	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:6	32.72	2251	1.87	13.6	96	194	Off Idle	81.8	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.31	14.73	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:6	32.72	2254	1.87	13.61	96	194	Off Idle	81.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.28	14.74	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:7	32.72	2254	1.88	13.63	96	194	Off Idle	81.8	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.21	14.75	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:7	32.72	2252	1.89	13.62	96	194	Off Idle	81.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.17	14.77	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:7	32.72	2248	1.89	13.61	96	194	Off Idle	81.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.12	14.78	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:7	32.72	2246	1.9	13.59	96	194	Off Idle	81.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.11	14.77	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:7	32.72	2241	1.9	13.58	96	194	Off Idle	81.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.07	14.78	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:7	32.72	2236	1.91	13.59	96	194	Off Idle	81.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.05	14.79	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:8	32.72	2225	1.92	13.6	96	194	Off Idle	81	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.02	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:8	32.72	2225	1.92	13.61	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:8	32.72	2215	1.93	13.6	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.96	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:8	32.72	2223	1.93	13.6	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.94	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:8	32.72	2224	1.93	13.6	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.92	14.96	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:8	32.72	2230	1.93	13.6	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.91	15.01	1.02	3.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:9	32.72	2246	1.94	13.61	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.96	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:9	32.72	2244	1.94	13.63	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.94	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:54:9	32.72	2244	1.94	13.64	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.91	15.12	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:54:9	32.72	2248	1.94	13.65	96	194	Off Idle	80.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.92	15.15	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:54:9	32.72	2250	1.94	13.66	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.9	15.18	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:54:9	32.72	2249	1.94	13.65	96	194	Off Idle	80.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.9	15.16	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:54:9	32.72	2249	1.94	13.64	96	194	Off Idle	81.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.97	15.11	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:0	32.72	2248	1.94	13.64	96	194	Off Idle	81.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.98	15.08	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:0	32.72	2247	1.94	13.64	96	194	Off Idle	80.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.95	15.03	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:0	34.08	2263	1.94	13.63	96	194	Off Idle	80.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.98	14.97	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:0	34.08	2242	1.94	13.61	96	194	Off Idle	80.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.99	14.91	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:0	34.08	2242	1.94	13.59	96	194	Off Idle	80.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.01	14.9	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:0	34.08	2244	1.94	13.57	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.04	14.84	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:1	34.08	2247	1.94	13.57	96	194	Off Idle	80.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.03	14.77	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:1	34.08	2246	1.94	13.58	96	194	Off Idle	80.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.02	14.74	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:1	34.08	2250	1.94	13.57	96	194	Off Idle	80.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7	14.71	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:1	32.72	2242	1.94	13.59	96	194	Off Idle	80.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.96	14.71	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:1	32.72	2265	1.94	13.6	96	194	Off Idle	80.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.96	14.71	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:1	32.72	2265	1.94	13.61	96	194	Off Idle	80.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.96	14.73	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:1	32.72	2266	1.94	13.6	96	194	Off Idle	80	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.95	14.74	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:2	32.72	2263	1.94	13.61	96	194	Off Idle	79.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.97	14.74	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:2	32.72	2257	1.94	13.6	96	194	Off Idle	79.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.98	14.75	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:2	34.08	2257	1.94	13.59	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.99	14.76	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:2	34.08	2268	1.94	13.6	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.97	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:2	34.08	2249	1.94	13.6	96	194	Off Idle	79.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.93	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:2	34.08	2250	1.94	13.62	96	194	Off Idle	79.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.92	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:3	34.08	2255	1.95	13.64	96	194	Off Idle	79.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.9	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:3	34.08	2247	1.95	13.65	96	194	Off Idle	79.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.93	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:3	34.08	2255	1.95	13.63	96	194	Off Idle	79.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.93	14.99	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:3	34.08	2257	1.95	13.62	96	194	Off Idle	79.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.94	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:3	34.08	2258	1.95	13.6	96	194	Off Idle	79.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.93	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:3	34.08	2262	1.95	13.6	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.93	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:4	34.08	2262	1.95	13.59	96	194	Off Idle	79.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.9	15.08	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:4	34.08	2259	1.95	13.6	96	194	Off Idle	79.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.89	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:4	34.08	2258	1.95	13.61	96	194	Off Idle	79.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.92	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:4	34.08	2255	1.95	13.61	96	194	Off Idle	79.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.91	15.12	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:4	32.72	2246	1.95	13.6	96	194	Off Idle	80.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.89	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:4	32.72	2253	1.95	13.61	96	194	Off Idle	80.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.87	15.05	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:4	32.72	2251	1.95	13.62	96	194	Off Idle	80.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.81	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:5	32.72	2254	1.95	13.6	96	194	Off Idle	80.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.79	14.99	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:55:5	32.72	2255	1.95	13.62	96	194	Off Idle	80.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.79	14.96	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:5	32.72	2256	1.95	13.63	96	194	Off Idle	80.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.77	14.93	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:5	34.08	2275	1.96	13.62	96	194	Off Idle	80.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.8	14.89	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:5	34.08	2261	1.96	13.59	96	194	Off Idle	80.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.76	14.83	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:55:5	34.08	2262	1.96	13.6	96	194	Off Idle	80.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.75	14.78	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:6	34.08	2268	1.97	13.61	96	194	Off Idle	80.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.71	14.76	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:6	34.08	2288	1.97	13.62	96	194	Off Idle	80.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.65	14.76	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:6	34.08	2273	1.98	13.62	96	194	Off Idle	80.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.68	14.76	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:6	34.08	2276	1.98	13.6	96	194	Off Idle	80.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.63	14.76	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:6	34.08	2279	1.98	13.59	96	194	Off Idle	80.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.64	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:6	34.08	2280	1.98	13.58	96	194	Off Idle	80.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.64	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:6	34.08	2277	1.99	13.59	96	194	Off Idle	80.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.59	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:7	34.08	2275	1.99	13.59	96	194	Off Idle	80	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.55	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:7	34.08	2273	2	13.6	96	194	Off Idle	79.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.54	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:55:7	34.08	2272	2	13.61	96	194	Off Idle	79.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.52	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:10:55:7	34.08	2270	2.01	13.61	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.18	Rich	1	14.6	-6.51	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:7	32.72	2270	2.01	13.61	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.55	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:7	32.72	2268	2.01	13.61	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.53	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:8	32.72	2267	2.01	13.61	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.48	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:8	32.72	2268	2.02	13.62	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.49	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:8	32.72	2270	2.02	13.63	96	194	Off Idle	79.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.46	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:8	32.72	2270	2.02	13.63	96	194	Off Idle	79.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.46	15.14	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:8	32.72	2274	2.02	13.63	96	194	Off Idle	79.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.47	15.16	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:8	32.72	2273	2.02	13.62	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.54	15.19	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:9	32.72	2289	2.02	13.61	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.46	15.19	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:9	32.72	2282	2.02	13.61	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.43	15.17	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:9	32.72	2281	2.02	13.6	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.39	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:9	32.72	2285	2.02	13.61	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.36	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:55:9	32.72	2288	2.02	13.62	96	194	Off Idle	79.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.3	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:9	32.72	2289	2.03	13.64	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.31	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:55:9	32.72	2291	2.03	13.64	96	194	Off Idle	79.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.28	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:56:0	32.72	2289	2.04	13.64	96	194	Off Idle	79.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.27	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:56:0	32.72	2289	2.04	13.63	96	194	Off Idle	78.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.19	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:0	32.72	2289	2.04	13.63	96	194	Off Idle	78.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.19	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:0	32.72	2284	2.05	13.63	96	194	Off Idle	78.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.05	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:0	32.72	2284	2.06	13.62	96	194	Off Idle	78.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.99	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:0	32.72	2287	2.06	13.61	96	194	Off Idle	78.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.97	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:1	32.72	2291	2.07	13.6	96	194	Off Idle	78.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.95	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:1	32.72	2298	2.08	13.58	96	194	Off Idle	78.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.88	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:1	32.72	2302	2.08	13.58	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.86	14.83	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:1	32.72	2311	2.09	13.59	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.78	14.84	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:1	32.72	2316	2.1	13.6	96	194	Off Idle	78	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.66	14.86	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:1	32.72	2318	2.11	13.61	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.6	14.88	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:1	32.72	2317	2.12	13.61	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.13	Rich	1	14.6	-5.57	14.91	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:2	32.72	2304	2.13	13.62	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.57	14.97	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:2	32.72	2304	2.14	13.62	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.58	15.03	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:2	32.72	2297	2.15	13.61	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.58	15.09	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:2	32.72	2297	2.16	13.62	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.56	15.19	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:2	32.72	2288	2.16	13.62	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.44	15.24	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:2	32.72	2292	2.16	13.63	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.44	15.25	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:3	32.72	2293	2.17	13.63	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.42	15.27	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:3	32.72	2293	2.17	13.63	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.38	15.27	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:3	32.72	2306	2.17	13.63	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.43	15.29	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:3	32.72	2309	2.17	13.62	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.43	15.26	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:3	32.72	2310	2.18	13.61	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.39	15.2	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:3	32.72	2296	2.18	13.61	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.45	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:4	32.72	2305	2.18	13.61	96	194	Off Idle	78.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.48	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:4	32.72	2313	2.17	13.61	96	194	Off Idle	78.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.51	14.86	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:56:4	32.72	2307	2.17	13.6	96	194	Off Idle	78.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.53	14.77	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:4	32.72	2307	2.17	13.6	96	194	Off Idle	78.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.51	14.72	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:4	32.72	2308	2.17	13.59	96	194	Off Idle	78.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.47	14.65	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:4	32.72	2309	2.17	13.59	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.42	14.59	0.99	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:4	32.72	2310	2.17	13.6	96	194	Off Idle	78	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.43	14.56	0.99	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:5	32.72	2316	2.17	13.62	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.42	14.55	0.99	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:5	32.72	2318	2.17	13.62	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.49	14.55	0.99	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:5	32.72	2318	2.17	13.6	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.49	14.68	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:56:5	32.72	2320	2.17	13.59	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.5	14.7	1	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:5	32.72	2318	2.17	13.58	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.54	14.72	1	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:5	32.72	2318	2.17	13.58	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.5	14.74	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:6	32.72	2317	2.17	13.58	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.49	14.75	1	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:6	32.72	2316	2.17	13.6	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.44	14.77	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:6	32.72	2316	2.18	13.61	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.4	14.78	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:6	32.72	2326	2.18	13.62	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.39	14.77	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:6	32.72	2326	2.18	13.6	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.42	14.78	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:6	32.72	2328	2.18	13.61	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.42	14.82	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:6	32.72	2330	2.18	13.61	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.46	14.84	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:7	32.72	2330	2.18	13.59	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.46	14.88	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:7	32.72	2331	2.18	13.6	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.47	14.9	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:7	32.72	2331	2.18	13.61	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.46	14.91	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:7	32.72	2334	2.19	13.6	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.39	14.97	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:7	32.72	2330	2.19	13.62	96	194	Off Idle	76.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.39	14.99	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:7	32.72	2366	2.19	13.63	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.33	15.05	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:8	32.72	2366	2.19	13.61	96	194	Off Idle	76.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.31	15.08	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:8	32.72	2331	2.19	13.61	96	194	Off Idle	76.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.29	15.1	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:8	32.72	2327	2.19	13.61	96	194	Off Idle	76.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.3	15.13	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:8	32.72	2326	2.19	13.61	96	194	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.33	15.16	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:8	32.72	2337	2.2	13.59	96	194	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.39	15.14	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:8	32.72	2338	2.2	13.59	96	194	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.4	15.13	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:9	32.72	2338	2.2	13.61	96	194	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.38	15.08	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:9	32.72	2338	2.2	13.61	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.35	15.03	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:9	32.72	2340	2.2	13.63	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.3	15	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:9	32.72	2352	2.2	13.64	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.29	14.96	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:56:9	32.72	2347	2.2	13.62	96	194	Off Idle	76.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.3	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:9	32.72	2347	2.2	13.62	96	194	Off Idle	76.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.29	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:56:9	32.72	2347	2.2	13.62	96	194	Off Idle	76.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.32	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:0	32.72	2344	2.2	13.62	96	194	Off Idle	76.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.31	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:0	32.72	2343	2.2	13.62	96	194	Off Idle	76	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.3	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:0	32.72	2340	2.2	13.63	96	194	Off Idle	75.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.28	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:0	32.72	2344	2.2	13.63	96	194	Off Idle	75.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.29	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:0	32.72	2340	2.21	13.59	96	194	Off Idle	75.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.32	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:0	32.72	2345	2.21	13.58	96	194	Off Idle	75.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.35	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:1	32.72	2353	2.21	13.58	96	194	Off Idle	75.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.37	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:1	32.72	2353	2.21	13.59	96	194	Off Idle	75.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.37	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:1	32.72	2360	2.21	13.6	96	194	Off Idle	75	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.36	14.88	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:1	32.72	2365	2.21	13.61	96	194	Off Idle	74.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.35	14.92	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:1	32.72	2367	2.21	13.62	96	194	Off Idle	74.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.31	14.98	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:1	32.72	2366	2.21	13.63	96	194	Off Idle	74.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.33	15.02	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:1	32.72	2363	2.21	13.63	96	194	Off Idle	74.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.33	15.05	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:2	32.72	2360	2.21	13.63	96	194	Off Idle	74.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.33	15.08	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:2	32.72	2354	2.21	13.63	96	194	Off Idle	74	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.34	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:2	32.72	2352	2.21	13.61	96	194	Off Idle	73.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.32	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:2	32.72	2352	2.22	13.61	96	194	Off Idle	73.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.34	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:2	32.72	2358	2.22	13.61	96	194	Off Idle	73.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.26	15.07	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:2	32.72	2362	2.22	13.63	96	194	Off Idle	73.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.27	15.06	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:3	32.72	2364	2.22	13.64	96	194	Off Idle	73.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.28	15	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:3	32.72	2366	2.22	13.64	96	194	Off Idle	73.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.28	14.97	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:57:3	32.72	2366	2.22	13.64	96	194	Off Idle	73.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.26	14.92	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:3	32.72	2369	2.22	13.64	96	194	Off Idle	73.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.26	14.86	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:3	32.72	2370	2.22	13.65	96	194	Off Idle	73.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.27	14.82	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:3	32.72	2370	2.22	13.66	96	194	Off Idle	73.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.28	14.8	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:4	32.72	2379	2.22	13.65	96	194	Off Idle	74	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.28	14.79	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:4	32.72	2374	2.22	13.65	96	194	Off Idle	74	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.31	14.79	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:4	32.72	2373	2.22	13.65	96	194	Off Idle	74	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.29	14.78	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:4	32.72	2373	2.22	13.64	96	194	Off Idle	74	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.27	14.77	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:4	32.72	2378	2.22	13.64	96	194	Off Idle	74	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.26	14.78	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:4	32.72	2378	2.22	13.64	96	194	Off Idle	73.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.28	14.78	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:4	32.72	2371	2.22	13.63	96	194	Off Idle	73.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.31	14.83	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:5	32.72	2370	2.22	13.61	96	194	Off Idle	73.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.31	14.85	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:5	32.72	2367	2.22	13.6	96	194	Off Idle	73.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.35	14.88	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:5	32.72	2367	2.22	13.61	96	194	Off Idle	73.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.32	14.88	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:5	32.72	2368	2.22	13.59	96	194	Off Idle	73.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.3	14.92	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:5	32.72	2371	2.22	13.59	96	194	Off Idle	73.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.3	14.97	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:5	32.72	2370	2.22	13.59	96	194	Off Idle	73.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.3	15.02	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:6	32.72	2373	2.22	13.59	96	194	Off Idle	73.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.31	15.03	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:6	32.72	2377	2.22	13.58	96	194	Off Idle	73.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.29	14.99	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:6	32.72	2377	2.22	13.58	96	194	Off Idle	73.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.3	14.98	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:6	32.72	2382	2.22	13.6	96	194	Off Idle	73.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.3	14.95	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:6	32.72	2390	2.22	13.62	96	194	Off Idle	73.7	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.36	14.91	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:6	32.72	2391	2.22	13.62	96	194	Off Idle	73.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.37	14.88	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:6	32.72	2391	2.22	13.62	96	194	Off Idle	73.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.36	14.83	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:7	32.72	2389	2.22	13.62	96	194	Off Idle	73.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.37	14.78	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:7	32.72	2392	2.22	13.62	96	194	Off Idle	73.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.37	14.76	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:7	32.72	2389	2.22	13.62	96	194	Off Idle	73.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.38	14.76	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:7	32.72	2389	2.22	13.61	96	194	Off Idle	73.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.41	14.76	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:7	32.72	2392	2.22	13.6	96	194	Off Idle	73.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.41	14.77	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:7	32.72	2395	2.22	13.6	96	195	Off Idle	73.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.4	14.78	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:8	32.72	2406	2.22	13.59	96	195	Off Idle	73.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.45	14.79	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:57:8	32.72	2400	2.22	13.6	96	195	Off Idle	73.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.46	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:8	32.72	2398	2.22	13.61	96	195	Off Idle	73.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.42	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:8	32.72	2372	2.22	13.62	96	195	Off Idle	73.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.43	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:8	32.72	2372	2.22	13.61	96	194	Off Idle	73	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.46	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:8	32.72	2385	2.22	13.61	96	194	Off Idle	72.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.5	14.95	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:9	32.72	2386	2.22	13.61	96	194	Off Idle	72.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.51	14.98	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:9	32.72	2392	2.22	13.6	96	195	Off Idle	72.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.5	15.04	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:57:9	32.72	2396	2.22	13.59	96	195	Off Idle	72.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.47	15.07	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:57:9	32.72	2397	2.22	13.6	96	195	Off Idle	72.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.42	15.07	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:57:9	32.72	2397	2.22	13.61	96	194	Off Idle	72.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.42	15.06	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:57:9	32.72	2395	2.22	13.62	96	194	Off Idle	72.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.39	15.04	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:57:9	32.72	2394	2.22	13.62	96	194	Off Idle	72.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.44	15.01	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:58:0	32.72	2397	2.22	13.63	96	194	Off Idle	72.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.45	14.96	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:58:0	32.72	2400	2.21	13.63	96	194	Off Idle	72.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.46	14.93	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:58:0	32.72	2403	2.21	13.62	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.5	14.87	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:10:58:0	32.72	2403	2.21	13.63	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.53	14.83	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:0	32.72	2406	2.21	13.62	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.55	14.79	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:0	32.72	2407	2.21	13.62	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.59	14.78	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:1	32.72	2408	2.2	13.6	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.65	14.76	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:1	32.72	2410	2.2	13.61	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.67	14.74	1	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:1	32.72	2412	2.19	13.62	96	195	Off Idle	72.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.71	14.73	1	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:1	32.72	2416	2.18	13.61	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.77	14.76	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:58:1	32.72	2416	2.18	13.62	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.82	14.79	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:10:58:1	32.72	2416	2.17	13.64	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.88	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:58:1	34.08	2432	2.16	13.63	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.02	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:58:2	34.08	2408	2.16	13.61	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.15	14.89	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:10:58:2	34.08	2405	2.15	13.61	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.25	14.91	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:58:2	34.08	2405	2.14	13.6	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.33	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:58:2	34.08	2405	2.12	13.6	96	194	Off Idle	72.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.44	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:58:2	34.08	2404	2.11	13.6	96	194	Off Idle	72.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.44	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:10:58:2	32.72	2387	2.1	13.63	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.54	15.09	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:58:3	32.72	2398	2.09	13.62	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.57	15.1	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:58:3	32.72	2407	2.08	13.64	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.64	15.09	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:58:3	32.72	2410	2.07	13.64	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.77	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:58:3	32.72	2412	2.06	13.62	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.88	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:58:3	32.72	2394	2.04	13.62	96	195	Off Idle	72	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.96	15.01	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:58:3	32.72	2417	2.03	13.6	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.04	14.98	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:58:4	32.72	2417	2.02	13.59	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.09	14.95	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:58:4	32.72	2419	2.01	13.61	96	195	Off Idle	71.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.15	14.92	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:58:4	32.72	2417	2	13.6	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.24	14.84	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:58:4	32.72	2412	1.99	13.59	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.27	14.81	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:10:58:4	32.72	2412	1.97	13.6	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.38	14.8	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:58:4	32.72	2409	1.97	13.61	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.48	14.79	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:58:4	34.08	2414	1.96	13.61	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.56	14.78	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:10:58:5	34.08	2404	1.95	13.6	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.64	14.78	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:5	34.08	2406	1.93	13.61	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.79	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:5	34.08	2416	1.92	13.61	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:5	34.08	2410	1.91	13.59	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.86	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:5	34.08	2409	1.9	13.61	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.95	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:5	34.08	2415	1.89	13.62	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.04	14.92	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:58:6	34.08	2415	1.88	13.63	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.12	14.96	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:58:6	34.08	2418	1.87	13.61	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.19	15	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:58:6	34.08	2418	1.86	13.62	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.19	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:10:58:6	34.08	2432	1.85	13.63	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.23	15.11	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:6	34.08	2432	1.84	13.62	96	195	Off Idle	71.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.26	15.14	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:6	34.08	2411	1.82	13.62	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.32	15.17	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:6	34.08	2408	1.81	13.61	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.37	15.16	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:7	34.08	2387	1.8	13.61	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.51	15.15	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:7	34.08	2387	1.79	13.59	96	195	Off Idle	71.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.57	15.16	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:7	34.08	2404	1.77	13.59	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.6	15.16	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:7	34.08	2401	1.77	13.59	96	194	Off Idle	70.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.61	15.14	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:7	34.08	2400	1.76	13.61	96	194	Off Idle	70.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.6	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:7	34.08	2401	1.75	13.64	96	194	Off Idle	71	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.67	15.06	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:8	34.08	2400	1.75	13.63	96	195	Off Idle	71.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.71	15.04	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:8	34.08	2400	1.74	13.63	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.75	14.99	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:8	34.08	2400	1.73	13.63	96	195	Off Idle	71	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.83	14.97	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:10:58:8	34.08	2400	1.73	13.63	96	195	Off Idle	71.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.87	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:8	34.08	2404	1.72	13.62	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.88	14.91	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:8	34.08	2410	1.71	13.63	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.93	14.86	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:9	34.08	2410	1.71	13.63	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.95	14.84	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:9	34.08	2414	1.7	13.62	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.04	14.84	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:9	34.08	2417	1.69	13.61	96	195	Off Idle	71.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.03	14.83	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:9	34.08	2417	1.69	13.63	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.04	14.84	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:9	34.08	2416	1.68	13.6	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.05	14.84	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:9	35.45	2425	1.68	13.6	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.06	14.82	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:58:9	35.45	2414	1.68	13.61	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.07	14.81	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:59:0	35.45	2414	1.67	13.61	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.07	14.81	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:59:0	35.45	2414	1.67	13.59	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.11	14.82	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:59:0	35.45	2412	1.67	13.6	96	195	Off Idle	71.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.13	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:59:0	35.45	2404	1.66	13.61	96	195	Off Idle	71.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.16	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:59:0	35.45	2404	1.66	13.59	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.16	14.88	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:0	34.08	2403	1.66	13.59	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.23	14.89	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:1	34.08	2401	1.66	13.59	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.22	14.92	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:1	34.08	2398	1.65	13.59	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.22	14.95	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:1	34.08	2403	1.65	13.6	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.7	Lean	1	14.6	-9.24	14.98	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:10:59:1	34.08	2405	1.65	13.62	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.23	15.03	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:1	34.08	2405	1.65	13.63	96	195	Off Idle	72	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.25	15.05	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:1	34.08	2403	1.64	13.62	96	195	Off Idle	72.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.26	15.05	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:1	34.08	2405	1.64	13.62	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.26	15.04	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:2	34.08	2405	1.64	13.63	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.25	15.05	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:2	34.08	2404	1.64	13.64	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.26	15.07	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:2	34.08	2404	1.63	13.64	96	195	Off Idle	72.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.25	15.08	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:2	34.08	2400	1.63	13.64	96	195	Off Idle	72.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.24	15.06	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:2	35.45	2417	1.63	13.63	96	195	Off Idle	72.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.26	15.04	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:2	35.45	2400	1.63	13.63	96	195	Off Idle	72	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.28	15.02	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:3	35.45	2400	1.63	13.62	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.31	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:3	35.45	2406	1.62	13.62	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.29	14.99	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:3	35.45	2407	1.62	13.61	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.32	14.98	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:3	35.45	2413	1.62	13.61	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.36	14.97	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:3	35.45	2413	1.62	13.61	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.35	14.92	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:10:59:3	34.08	2410	1.62	13.62	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.35	14.89	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:4	34.08	2417	1.62	13.63	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.36	14.85	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:4	34.08	2413	1.62	13.63	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.36	14.84	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:4	34.08	2413	1.61	13.62	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.35	14.83	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:4	34.08	2418	1.61	13.62	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.36	14.83	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:4	34.08	2416	1.61	13.61	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.38	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:4	35.45	2405	1.61	13.61	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.41	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:4	35.45	2405	1.61	13.6	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:5	35.45	2406	1.6	13.62	96	195	Off Idle	71.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.46	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:5	35.45	2405	1.6	13.62	96	195	Off Idle	72	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.49	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:5	35.45	2402	1.59	13.62	96	195	Off Idle	72	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.53	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:5	35.45	2400	1.59	13.63	96	195	Off Idle	72	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.55	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:5	35.45	2390	1.58	13.63	96	195	Off Idle	72	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.59	14.9	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:59:5	35.45	2394	1.57	13.63	96	195	Off Idle	72	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.65	14.92	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:59:6	35.45	2388	1.56	13.63	96	195	Off Idle	72	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.72	14.96	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:10:59:6	35.45	2387	1.55	13.62	96	195	Off Idle	72.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.73	15.01	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:59:6	35.45	2388	1.54	13.62	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.77	15.05	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:59:6	35.45	2388	1.53	13.61	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.8	15.08	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:10:59:6	35.45	2385	1.51	13.61	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.89	15.11	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:6	35.45	2385	1.5	13.61	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.94	15.12	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:6	35.45	2377	1.48	13.62	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.01	15.12	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:7	35.45	2375	1.45	13.63	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.07	15.11	1.03	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:59:7	35.45	2366	1.44	13.63	96	195	Full Load	72.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.16	15.11	1.03	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:59:7	35.45	2363	1.4	13.62	96	195	Idle	72.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.27	15.08	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:59:7	35.45	2356	1.38	13.64	96	195	Idle	72.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.34	15.06	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:59:7	35.45	2356	1.36	13.63	96	195	Idle	72.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.39	15.05	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:59:7	35.45	2354	1.34	13.61	96	195	Idle	71.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.46	15.04	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:59:8	35.45	2346	1.32	13.62	96	195	Idle	70.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.5	15.02	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:59:8	35.45	2347	1.3	13.61	96	195	Idle	68.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.5	15.02	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:59:8	35.45	2349	1.29	13.61	96	195	Idle	67.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.52	15.02	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:59:8	35.45	2358	1.28	13.61	96	195	Idle	66.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.48	15.02	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:59:8	32.72	2340	1.28	13.61	96	195	Idle	66	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.44	15.01	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:10:59:8	32.72	2345	1.28	13.61	96	195	Idle	65.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.38	14.99	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:9	27.27	2364	1.27	13.62	96	195	Idle	65.1	0	2	132	944 Turbo	0.66	Lean	1	14.6	-10.29	14.99	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:9	27.27	2382	1.27	13.62	96	195	Idle	64.7	0	2	132	944 Turbo	0.63	Lean	1	14.6	-10.25	14.98	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:9	21.81	2386	1.27	13.61	96	195	Idle	64.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-10.23	14.95	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:9	17.72	2396	1.26	13.61	96	195	Idle	64.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-10.21	14.93	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:9	17.72	2423	1.26	13.63	96	195	Idle	64.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-10.26	14.92	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:9	17.72	2407	1.26	13.62	96	195	Idle	64.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.31	14.86	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:59:9	17.72	2405	1.26	13.62	96	195	Idle	65.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.39	14.82	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:0	17.72	2383	1.26	13.63	96	195	Idle	66.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.44	14.81	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:0	17.72	2364	1.26	13.61	96	195	Idle	67.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.52	14.78	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:0	17.72	2327	1.27	13.61	96	195	Idle	68.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.56	14.77	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:00:0	17.72	2335	1.27	13.6	96	195	Idle	69.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.56	14.77	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:0	17.72	2332	1.27	13.6	96	195	Idle	70.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.52	14.81	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:0	17.72	2307	1.27	13.61	96	195	Idle	70.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.5	14.85	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:1	17.72	2328	1.27	13.6	96	195	Idle	71.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.47	14.9	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:1	17.72	2357	1.26	13.62	96	195	Idle	71	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.45	14.95	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:1	17.72	2357	1.24	13.63	96	195	Idle	70.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.44	15.03	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:1	17.72	2361	1.23	13.62	96	195	Idle	70.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.49	15.1	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:1	17.72	2378	1.22	13.61	96	195	Idle	70.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.48	15.2	1.04	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:1	17.72	2378	1.21	13.61	96	195	Idle	70.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.48	15.39	1.05	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:1	17.72	2400	1.21	13.6	96	195	Idle	70.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.5	15.56	1.06	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:2	17.72	2390	1.2	13.61	96	195	Idle	70.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.48	15.69	1.07	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:2	17.72	2384	1.2	13.61	96	195	Idle	70.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.49	15.84	1.08	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:2	17.72	2381	1.19	13.63	96	195	Idle	70.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.51	16.03	1.09	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:2	17.72	2368	1.19	13.64	96	195	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	16.21	1.1	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:2	17.72	2357	1.18	13.62	96	195	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	16.5	1.12	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:2	17.72	2357	1.18	13.61	96	195	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	16.78	1.14	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:3	17.72	2339	1.18	13.6	96	195	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	17.01	1.16	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:3	17.72	2335	1.18	13.6	96	195	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	17.15	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:3	17.72	2332	1.18	13.6	96	195	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	17.28	1.18	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:3	17.72	2332	1.17	13.6	96	195	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	17.4	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:3	17.72	2338	1.17	13.61	96	195	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	17.44	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:3	17.72	2341	1.17	13.63	97	195	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	17.49	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:4	17.72	2344	1.17	13.63	97	195	Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	17.5	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:4	17.72	2331	1.17	13.61	96	195	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	17.56	1.2	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:4	17.72	2348	1.17	13.62	96	195	Idle	72	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	17.62	1.2	3.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:4	17.72	2364	1.17	13.61	96	195	Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	17.76	1.21	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:4	17.72	2355	1.17	13.61	96	195	Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	17.95	1.22	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:4	17.72	2354	1.16	13.6	96	195	Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	18.32	1.25	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:4	17.72	2346	1.16	13.61	96	195	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	18.59	1.27	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:5	17.72	2324	1.16	13.62	96	195	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	18.98	1.29	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:5	17.72	2333	1.15	13.62	96	195	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	19.37	1.32	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:5	17.72	2341	1.15	13.62	96	195	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	19.6	1.34	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:5	17.72	2326	1.15	13.61	96	195	Idle	73.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	19.93	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:5	17.72	2326	1.15	13.6	96	195	Idle	73.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.1	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:5	17.72	2315	1.14	13.62	96	195	Idle	73.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:6	17.72	2324	1.14	13.62	96	195	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:6	17.72	2326	1.14	13.62	96	195	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:6	17.72	2328	1.14	13.62	96	195	Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:6	17.72	2330	1.14	13.61	96	195	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:6	17.72	2334	1.14	13.62	96	195	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:6	17.72	2336	1.13	13.62	96	195	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:6	17.72	2355	1.13	13.6	96	195	Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:7	17.72	2345	1.12	13.61	96	195	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:7	17.72	2314	1.12	13.61	96	195	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:7	17.72	2329	1.12	13.61	96	195	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:7	17.72	2326	1.12	13.61	96	195	Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:7	17.72	2323	1.12	13.63	96	195	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:7	17.72	2320	1.11	13.64	96	195	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:8	17.72	2314	1.11	13.63	96	195	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:8	17.72	2310	1.11	13.62	96	195	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:8	17.72	2307	1.11	13.63	96	195	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:8	17.72	2307	1.11	13.63	96	195	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:8	17.72	2306	1.11	13.63	96	195	Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:8	17.72	2306	1.11	13.62	96	195	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:9	17.72	2307	1.11	13.61	96	195	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:9	17.72	2309	1.11	13.6	96	195	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:9	17.72	2308	1.11	13.59	96	195	Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:9	17.72	2308	1.11	13.59	96	195	Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:00:9	17.72	2306	1.11	13.59	96	195	Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:9	17.72	2306	1.11	13.59	96	195	Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:00:9	17.72	2305	1.11	13.62	96	195	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:0	17.72	2302	1.11	13.63	96	195	Idle	75.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:0	17.72	2299	1.11	13.64	96	195	Idle	75.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:0	17.72	2299	1.1	13.63	96	195	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:0	17.72	2296	1.1	13.63	96	195	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:0	17.72	2291	1.1	13.61	96	195	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:0	17.72	2291	1.1	13.6	96	195	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:1	17.72	2290	1.1	13.61	96	195	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:1	17.72	2287	1.09	13.61	96	195	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:1	17.72	2287	1.09	13.62	96	195	Idle	77.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:1	17.72	2287	1.09	13.63	96	195	Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:1	17.72	2288	1.09	13.64	96	195	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:1	17.72	2290	1.08	13.64	96	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:1	17.72	2290	1.08	13.63	96	195	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:2	17.72	2290	1.07	13.62	96	195	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:2	17.72	2290	1.07	13.61	96	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:2	17.72	2290	1.07	13.62	96	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:2	17.72	2289	1.07	13.62	96	195	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:2	17.72	2288	1.07	13.61	96	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:2	17.72	2285	1.06	13.62	96	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:3	17.72	2283	1.06	13.62	96	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:3	17.72	2280	1.06	13.6	96	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:3	17.72	2280	1.06	13.6	96	195	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:3	17.72	2276	1.06	13.61	96	195	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:3	17.72	2275	1.05	13.64	96	195	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:3	17.72	2274	1.05	13.64	96	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:4	17.72	2273	1.05	13.64	96	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:4	17.72	2271	1.05	13.64	96	195	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:4	17.72	2270	1.05	13.62	96	195	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:4	17.72	2270	1.05	13.61	96	195	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:4	17.72	2269	1.05	13.62	96	195	Idle	78	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:4	17.72	2270	1.05	13.63	96	195	Idle	78	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:4	17.72	2269	1.05	13.62	96	195	Idle	78	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:5	17.72	2268	1.05	13.62	96	195	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:5	17.72	2267	1.05	13.61	96	195	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:5	17.72	2266	1.05	13.61	96	195	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:5	17.72	2265	1.05	13.61	96	195	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:5	17.72	2264	1.05	13.61	96	195	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:5	17.72	2263	1.05	13.61	96	195	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:6	17.72	2262	1.05	13.62	96	195	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:6	17.72	2259	1.05	13.63	96	195	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:6	17.72	2259	1.05	13.63	96	195	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:6	17.72	2253	1.05	13.63	96	195	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:6	17.72	2252	1.05	13.63	96	195	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:6	17.72	2234	1.05	13.63	96	195	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:6	17.72	2247	1.05	13.64	96	195	Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:7	17.72	2247	1.04	13.64	96	195	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:7	17.72	2246	1.04	13.63	96	195	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:7	17.72	2246	1.04	13.62	96	195	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:7	17.72	2244	1.04	13.62	96	195	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:7	17.72	2243	1.04	13.6	96	195	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:7	17.72	2242	1.04	13.6	96	195	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:8	17.72	2242	1.04	13.61	96	195	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:8	17.72	2250	1.03	13.61	96	195	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:8	17.72	2242	1.03	13.61	96	195	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:8	17.72	2224	1.03	13.61	96	195	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:01:8	17.72	2231	1.03	13.62	96	195	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:8	17.72	2236	1.03	13.62	96	195	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:9	17.72	2235	1.03	13.62	96	195	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:9	17.72	2235	1.03	13.61	96	195	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:9	17.72	2232	1.03	13.62	96	195	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:9	17.72	2230	1.03	13.62	96	195	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:9	17.72	2227	1.02	13.61	96	195	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:9	17.72	2227	1.02	13.62	96	195	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:01:9	17.72	2224	1.02	13.63	96	195	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:0	17.72	2224	1.02	13.63	96	195	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:0	17.72	2214	1.02	13.62	96	195	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:0	17.72	2222	1.02	13.64	96	195	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:0	17.72	2220	1.02	13.62	96	195	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:0	17.72	2219	1.02	13.6	96	195	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:0	17.72	2219	1.02	13.6	96	195	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:1	17.72	2227	1.02	13.61	96	195	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:1	17.72	2216	1.01	13.63	96	195	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:1	17.72	2212	1.01	13.65	96	195	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:1	17.72	2212	1.01	13.66	96	195	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:1	17.72	2220	1.01	13.65	96	195	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:1	17.72	2210	1.01	13.64	96	195	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:1	17.72	2192	1.01	13.65	96	195	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:2	17.72	2200	1.01	13.63	96	195	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:2	17.72	2207	1.01	13.64	96	195	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:2	17.72	2204	1	13.64	96	195	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:2	17.72	2204	1	13.62	96	195	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:2	17.72	2203	1	13.59	96	195	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:2	17.72	2202	1	13.59	96	195	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:3	17.72	2202	1	13.58	96	195	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:3	17.72	2201	1	13.58	96	195	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:3	17.72	2200	1	13.58	96	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:3	17.72	2199	1	13.58	96	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:3	17.72	2199	1	13.59	96	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:3	17.72	2197	1	13.59	96	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:4	17.72	2212	1	13.59	96	195	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:4	17.72	2193	1	13.6	96	195	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:4	17.72	2192	1	13.59	96	195	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:4	17.72	2171	1	13.59	96	195	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:4	17.72	2188	1	13.61	96	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:4	17.72	2187	1	13.62	96	195	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:4	17.72	2187	0.99	13.62	96	195	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:5	17.72	2186	0.99	13.62	96	195	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:5	17.72	2185	0.99	13.62	96	195	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:5	17.72	2185	0.99	13.63	96	195	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:5	17.72	2184	0.99	13.63	96	195	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:5	17.72	2182	0.99	13.64	96	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:5	17.72	2182	0.99	13.65	96	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:6	17.72	2181	0.99	13.65	96	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:6	17.72	2181	0.99	13.65	96	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:6	17.72	2178	0.99	13.63	96	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:6	17.72	2178	0.99	13.61	96	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:6	17.72	2175	0.99	13.59	96	195	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:6	17.72	2175	0.99	13.58	96	195	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:6	17.72	2174	0.99	13.58	96	195	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:7	17.72	2171	0.99	13.59	96	195	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:7	17.72	2169	0.99	13.6	96	195	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:7	17.72	2168	0.99	13.62	96	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:7	17.72	2168	0.98	13.63	96	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:02:7	17.72	2166	0.98	13.64	96	195	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:7	17.72	2162	0.98	13.65	96	195	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:8	17.72	2163	0.98	13.65	96	195	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:8	17.72	2160	0.98	13.65	96	195	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:8	17.72	2162	0.98	13.63	96	195	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:8	17.72	2161	0.98	13.62	96	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:8	17.72	2161	0.98	13.6	96	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:8	17.72	2160	0.98	13.58	96	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:9	17.72	2158	0.98	13.57	96	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:9	17.72	2157	0.97	13.57	96	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:9	17.72	2157	0.97	13.59	96	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:9	17.72	2157	0.97	13.61	96	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:9	17.72	2155	0.97	13.62	96	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.84	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:9	17.72	2144	0.97	13.62	96	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.85	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:02:9	17.72	2149	0.97	13.61	96	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.85	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:0	17.72	2147	0.96	13.59	96	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.83	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:0	17.72	2154	0.96	13.59	96	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.83	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:0	17.72	2142	0.96	13.58	96	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.83	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:0	17.72	2142	0.96	13.6	96	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.83	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:0	17.72	2141	0.96	13.6	96	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:0	17.72	2138	0.96	13.59	96	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.83	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:1	17.72	2130	0.96	13.59	96	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:1	17.72	2135	0.95	13.58	96	196	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:1	17.72	2134	0.95	13.56	96	196	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:1	17.72	2133	0.95	13.59	96	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:1	17.72	2133	0.95	13.6	96	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:1	17.72	2132	0.95	13.61	96	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:1	17.72	2132	0.95	13.61	96	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:2	17.72	2129	0.95	13.62	96	195	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:2	17.72	2129	0.95	13.59	96	195	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:2	17.72	2120	0.95	13.59	96	195	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:2	17.72	2127	0.95	13.59	96	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:2	17.72	2126	0.95	13.6	96	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:2	17.72	2126	0.95	13.63	96	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:3	17.72	2124	0.95	13.62	96	195	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:3	17.72	2123	0.95	13.64	96	195	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:3	17.72	2123	0.95	13.64	96	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:3	17.72	2123	0.95	13.64	96	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:3	17.72	2122	0.96	13.63	96	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:3	17.72	2121	0.96	13.62	96	196	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:4	17.72	2121	0.96	13.59	96	196	Off Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:4	17.72	2120	0.96	13.58	96	196	Off Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:4	17.72	2120	0.96	13.57	96	196	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.4	1.2	ON	28 Pin	OFF	Removed	Disabled
03:11:03:4	8.18	2010	0.96	13.58	96	196	Off Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.4	1.2	ON	28 Pin	OFF	Removed	Disabled
03:11:03:4	8.18	2133	0.96	13.58	96	196	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.4	1.2	ON	28 Pin	OFF	Removed	Disabled
03:11:03:4	10.9	2130	0.97	13.58	96	196	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.4	1.2	ON	28 Pin	OFF	Removed	Disabled
03:11:03:4	10.9	2130	0.97	13.58	96	196	Off Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.4	1.2	ON	28 Pin	OFF	Removed	Disabled
03:11:03:5	13.63	2124	0.98	13.57	96	196	Off Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.24	1.38	3.4	1.2	ON	28 Pin	OFF	Removed	Disabled
03:11:03:5	16.36	2124	0.99	13.56	96	196	Off Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.25	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:03:5	16.36	2118	0.99	13.56	96	196	Off Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:03:5	19.09	2113	1	13.56	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:03:5	19.09	2111	1.01	13.56	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:03:5	21.81	2109	1.02	13.56	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:03:6	21.81	2106	1.03	13.57	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:03:6	24.54	2103	1.04	13.57	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:03:6	24.54	2102	1.05	13.57	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:03:6	27.27	2102	1.06	13.57	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:03:6	29.99	2103	1.08	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:03:6	29.99	2109	1.09	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:6	32.72	2112	1.11	13.58	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:7	32.72	2118	1.13	13.6	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:7	34.08	2110	1.14	13.6	96	195	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:03:7	34.08	2116	1.16	13.6	96	195	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:7	34.08	2116	1.17	13.6	96	195	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:7	34.08	2116	1.19	13.6	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:7	34.08	2114	1.21	13.61	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:8	34.08	2110	1.22	13.63	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:8	34.08	2110	1.23	13.62	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:8	34.08	2108	1.25	13.63	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:8	34.08	2100	1.26	13.61	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:8	34.08	2102	1.26	13.61	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:8	34.08	2092	1.28	13.62	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:9	34.08	2086	1.29	13.61	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:9	34.08	2077	1.3	13.61	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:9	34.08	2072	1.3	13.6	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.87	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:9	34.08	2061	1.31	13.6	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:03:9	34.08	2062	1.32	13.6	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:03:9	34.08	2062	1.33	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:03:9	34.08	2064	1.34	13.64	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:04:0	34.08	2065	1.34	13.64	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:04:0	34.08	2065	1.35	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:04:0	34.08	2065	1.36	13.64	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:04:0	34.08	2068	1.37	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.42	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:04:0	34.08	2090	1.39	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.35	20.24	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:04:0	34.08	2090	1.4	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.28	20.24	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:1	34.08	2102	1.41	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.24	20.24	1.38	3.3	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:1	34.08	2112	1.42	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.23	20.24	1.38	3.3	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:1	34.08	2135	1.44	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.12	20.24	1.38	3.3	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:1	34.08	2123	1.45	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.03	20.24	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:1	34.08	2125	1.48	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.94	20.24	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:1	32.72	2115	1.49	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.91	20.23	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:1	32.72	2137	1.5	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.87	20.18	1.37	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:2	32.72	2137	1.52	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.87	20.05	1.37	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:2	32.72	2133	1.54	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.83	19.86	1.35	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:2	32.72	2122	1.55	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.8	19.63	1.34	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:2	32.72	2102	1.56	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.73	19.37	1.32	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:2	32.72	2094	1.58	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.69	19.07	1.3	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:04:2	32.72	2069	1.59	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.62	18.75	1.28	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:04:3	32.72	2057	1.6	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.57	18.4	1.25	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:04:3	32.72	2048	1.61	13.62	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.5	18.05	1.23	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:04:3	32.72	2034	1.62	13.61	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.44	17.7	1.21	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:3	32.72	2034	1.63	13.6	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.39	17.38	1.18	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:3	32.72	2054	1.63	13.58	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.16	Rich	1	14.6	-8.36	17.12	1.17	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:3	32.72	2065	1.64	13.56	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.2	Rich	1	14.6	-8.31	16.9	1.15	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:4	32.72	2065	1.65	13.57	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.25	16.71	1.14	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:04:4	32.72	2085	1.66	13.57	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.21	16.46	1.12	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:04:4	32.72	2088	1.67	13.58	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.14	16.32	1.11	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:04:4	32.72	2092	1.68	13.57	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.06	16.21	1.1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:04:4	32.72	2105	1.7	13.59	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.95	16.03	1.09	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:04:4	32.72	2110	1.71	13.59	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.87	15.97	1.09	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:04:4	32.72	2108	1.72	13.62	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.72	15.78	1.08	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:04:5	32.72	2108	1.73	13.63	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	15.67	1.07	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:04:5	32.72	2106	1.74	13.61	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.63	15.57	1.06	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:04:5	32.72	2097	1.75	13.61	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.62	15.44	1.05	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:5	32.72	2095	1.76	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.58	15.36	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:5	32.72	2095	1.77	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.54	15.3	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:04:8	32.72	2088	1.79	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.46	15.21	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:6	32.72	2084	1.79	13.65	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.38	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:6	32.72	2084	1.8	13.65	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.33	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:6	32.72	2083	1.81	13.64	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.3	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:6	32.72	2082	1.83	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.22	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:6	32.72	2079	1.83	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.18	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:6	32.72	2079	1.84	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.18	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:6	32.72	2086	1.84	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.16	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:7	32.72	2088	1.85	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.13	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:7	32.72	2094	1.85	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.07	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:7	32.72	2094	1.86	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.02	15.21	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:04:7	32.72	2098	1.86	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.98	15.22	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:7	32.72	2099	1.87	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.96	15.24	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:7	32.72	2096	1.87	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.93	15.24	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:8	32.72	2093	1.88	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.84	15.23	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:8	32.72	2093	1.88	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.83	15.22	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:8	32.72	2091	1.88	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.79	15.2	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:8	31.36	2073	1.89	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.79	15.2	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:8	31.36	2087	1.89	13.56	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.79	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:8	31.36	2087	1.89	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.73	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:9	31.36	2090	1.9	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.7	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:9	31.36	2098	1.9	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.68	15.02	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:9	31.36	2101	1.9	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.64	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:9	31.36	2105	1.91	13.64	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.65	14.92	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:9	31.36	2105	1.91	13.64	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.65	14.89	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:9	32.72	2115	1.91	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.64	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:04:9	32.72	2108	1.92	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.59	14.78	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:05:0	32.72	2104	1.92	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.52	14.75	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:05:0	32.72	2104	1.92	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.52	14.76	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:05:0	32.72	2102	1.93	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.48	14.76	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:05:0	32.72	2099	1.93	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.44	14.76	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:05:0	32.72	2099	1.93	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.43	14.77	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:05:0	31.36	2085	1.93	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.4	14.78	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:05:1	31.36	2102	1.94	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.35	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:05:1	31.36	2106	1.94	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.39	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:05:1	31.36	2108	1.94	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.37	14.8	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:1	31.36	2110	1.95	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.36	14.8	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:1	31.36	2113	1.95	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.35	14.8	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:1	31.36	2113	1.96	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.3	14.79	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:1	31.36	2115	1.96	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.23	14.78	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:2	31.36	2116	1.96	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.19	14.78	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:05:2	31.36	2116	1.97	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.09	14.8	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:05:2	31.36	2118	1.98	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.02	14.81	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:2	31.36	2119	1.98	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.96	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:2	31.36	2117	1.99	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.91	14.86	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:2	31.36	2118	1.99	13.58	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.88	14.88	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:3	31.36	2117	1.99	13.57	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.82	14.9	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:3	31.36	2116	2	13.57	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.81	14.91	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:3	31.36	2111	2.01	13.56	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.77	14.95	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:05:3	31.36	2109	2.02	13.58	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.72	15	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:05:3	31.36	2109	2.04	13.56	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.64	15.02	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:05:3	31.36	2114	2.04	13.57	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.59	15.03	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:4	31.36	2119	2.05	13.57	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.49	15.01	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:4	31.36	2119	2.06	13.58	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.41	15	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:4	31.36	2127	2.07	13.6	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.36	14.97	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:4	31.36	2129	2.08	13.6	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.29	14.95	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:4	31.36	2131	2.09	13.59	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.23	14.93	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:4	31.36	2135	2.09	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.17	14.92	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:05:4	31.36	2144	2.1	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.09	14.87	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:5	31.36	2133	2.11	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.99	14.83	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:5	31.36	2133	2.12	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.96	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:5	31.36	2130	2.12	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.97	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:5	31.36	2129	2.13	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.96	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:5	31.36	2112	2.14	13.64	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.92	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:5	31.36	2121	2.14	13.64	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.93	14.8	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:6	31.36	2135	2.15	13.64	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.91	14.81	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:6	31.36	2136	2.15	13.64	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.89	14.85	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:6	31.36	2138	2.15	13.65	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.89	14.89	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:6	31.36	2154	2.15	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.89	14.9	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:6	31.36	2138	2.15	13.63	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.92	14.91	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:6	31.36	2140	2.15	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.94	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:6	31.36	2140	2.15	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.92	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:7	31.36	2141	2.15	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.9	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:7	31.36	2134	2.15	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.88	14.92	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:7	31.36	2140	2.15	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.85	14.92	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:7	31.36	2141	2.15	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.84	14.89	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:7	31.36	2146	2.15	13.62	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.88	14.86	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:7	31.36	2148	2.15	13.61	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.91	14.84	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:8	31.36	2150	2.15	13.6	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.95	14.84	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:8	31.36	2152	2.15	13.6	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.93	14.84	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:8	31.36	2153	2.15	13.58	96	196	Off Idle	85.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.92	14.84	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:05:8	31.36	2154	2.15	13.57	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.87	14.83	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:8	31.36	2156	2.15	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.86	14.83	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:8	31.36	2158	2.15	13.58	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.87	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:9	31.36	2158	2.15	13.57	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.87	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:9	31.36	2153	2.15	13.57	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.87	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:9	31.36	2153	2.15	13.57	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.86	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:9	31.36	2154	2.15	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.84	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:05:9	31.36	2155	2.16	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.78	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:05:9	31.36	2163	2.16	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.76	14.85	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:05:9	31.36	2163	2.17	13.62	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.7	14.88	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:06:0	31.36	2166	2.17	13.61	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.19	Rich	1	14.6	-4.6	14.89	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:0	31.36	2171	2.18	13.6	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.22	Rich	1	14.6	-4.56	14.9	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:0	31.36	2179	2.19	13.59	96	196	Off Idle	85.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-4.37	14.93	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:0	31.36	2180	2.21	13.58	96	196	Off Idle	85.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.16	14.99	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:0	31.36	2179	2.21	13.58	96	196	Off Idle	85.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.05	15.01	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:0	31.36	2177	2.22	13.59	96	196	Off Idle	85.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.98	15.03	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:1	31.36	2177	2.23	13.6	96	196	Off Idle	85.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.91	15.04	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:1	31.36	2177	2.24	13.61	96	196	Off Idle	85.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.83	15.04	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:1	31.36	2180	2.25	13.62	96	196	Off Idle	85.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.79	15.04	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:1	31.36	2182	2.26	13.61	96	196	Off Idle	85.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.79	15.04	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:1	31.36	2183	2.27	13.61	96	196	Off Idle	85.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.82	15.02	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:1	31.36	2183	2.28	13.6	96	196	Off Idle	85.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.78	15.01	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:1	31.36	2178	2.28	13.59	96	196	Off Idle	85.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.77	14.99	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:2	29.99	2161	2.29	13.59	96	196	Off Idle	85.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.73	14.97	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:2	29.99	2161	2.3	13.61	96	196	Off Idle	85.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.67	14.96	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:2	29.99	2178	2.31	13.61	96	196	Off Idle	85.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.63	14.93	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:2	29.99	2182	2.32	13.62	96	196	Off Idle	85	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.66	14.9	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:2	29.99	2190	2.32	13.62	96	196	Off Idle	85	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.69	14.88	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:2	29.99	2190	2.32	13.61	96	196	Off Idle	85	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.69	14.86	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:3	29.99	2188	2.32	13.6	96	196	Off Idle	85	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.69	14.83	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:3	29.99	2185	2.32	13.6	96	196	Off Idle	85	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.68	14.81	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:3	29.99	2185	2.32	13.62	96	196	Off Idle	84.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.61	14.79	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:3	29.99	2204	2.31	13.63	96	196	Off Idle	84.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.66	14.77	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:3	29.99	2198	2.31	13.64	96	196	Off Idle	84.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.69	14.76	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:3	31.36	2189	2.31	13.63	96	196	Off Idle	84.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.7	14.73	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:06:4	31.36	2189	2.31	13.63	96	196	Off Idle	84.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.68	14.72	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:4	31.36	2186	2.31	13.6	96	196	Off Idle	84.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.73	14.72	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:4	31.36	2203	2.31	13.6	96	196	Off Idle	84.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.65	14.72	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:4	31.36	2207	2.31	13.59	96	196	Off Idle	84.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.62	14.72	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:4	31.36	2209	2.31	13.59	96	196	Off Idle	84.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.62	14.73	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:4	31.36	2209	2.31	13.58	96	196	Off Idle	84.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.63	14.75	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:4	31.36	2204	2.31	13.57	96	196	Off Idle	83.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.64	14.77	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:5	31.36	2204	2.31	13.57	96	196	Off Idle	83.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.65	14.77	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:5	31.36	2201	2.31	13.58	96	196	Off Idle	83.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.64	14.78	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:5	31.36	2204	2.31	13.6	96	196	Off Idle	83.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-3.6	14.79	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:5	31.36	2215	2.32	13.61	96	196	Off Idle	83.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-3.6	14.8	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:5	31.36	2215	2.32	13.63	96	196	Off Idle	83.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-3.62	14.79	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:5	31.36	2222	2.32	13.64	96	196	Off Idle	83	0	2	132	944 Turbo	0.26	Rich	1	14.6	-3.65	14.81	1.01	3.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:6	31.36	2222	2.32	13.64	96	196	Off Idle	82.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.62	14.84	1.01	3.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:6	31.36	2240	2.32	13.64	96	196	Off Idle	82.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.65	14.86	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:6	31.36	2223	2.32	13.64	96	196	Off Idle	82.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.65	14.88	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:6	31.36	2222	2.32	13.64	96	196	Off Idle	82.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.63	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:06:6	31.36	2218	2.32	13.64	96	196	Off Idle	82.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.63	14.93	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:6	31.36	2218	2.32	13.64	96	196	Off Idle	82.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.67	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:6	31.36	2218	2.32	13.63	96	196	Off Idle	82.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-3.58	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:7	31.36	2218	2.33	13.62	96	196	Off Idle	82.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-3.55	15.02	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:7	31.36	2224	2.33	13.62	96	196	Off Idle	82.3	0	2	132	944 Turbo	0.63	Lean	1	14.6	-3.55	15.07	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:7	31.36	2228	2.33	13.62	96	196	Off Idle	82.2	0	2	132	944 Turbo	0.68	Lean	1	14.6	-3.56	15.09	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:7	31.36	2228	2.33	13.61	96	196	Off Idle	82	0	2	132	944 Turbo	0.73	Lean	1	14.6	-3.57	15.06	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:7	31.36	2232	2.33	13.61	96	196	Off Idle	81.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.65	15.05	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:7	31.36	2235	2.33	13.61	96	196	Off Idle	81.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.68	15.02	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:8	31.36	2238	2.33	13.6	96	196	Off Idle	81.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.7	14.98	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:8	31.36	2238	2.33	13.59	96	196	Off Idle	81.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.67	14.93	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:8	31.36	2236	2.33	13.6	96	196	Off Idle	81.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.69	14.86	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:8	31.36	2236	2.33	13.6	96	196	Off Idle	81.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.65	14.8	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:8	31.36	2237	2.33	13.63	96	196	Off Idle	81.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.56	14.7	1	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:8	31.36	2240	2.33	13.63	96	196	Off Idle	81.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.58	14.67	1	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:9	31.36	2242	2.33	13.64	96	196	Off Idle	81.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.56	14.66	1	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:9	31.36	2253	2.34	13.63	96	196	Off Idle	81.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.5	14.65	1	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:06:9	31.36	2253	2.34	13.63	96	196	Off Idle	81.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.53	14.65	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:9	31.36	2254	2.34	13.62	96	196	Off Idle	81.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.56	14.67	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:9	31.36	2250	2.34	13.62	96	196	Off Idle	81.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.56	14.72	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:9	31.36	2250	2.34	13.62	96	196	Off Idle	81.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.59	14.74	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:06:9	31.36	2246	2.34	13.62	96	196	Off Idle	81.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.61	14.77	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:0	31.36	2249	2.34	13.63	96	196	Off Idle	81.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.58	14.79	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:0	31.36	2252	2.34	13.63	96	196	Off Idle	80.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.56	14.8	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:0	31.36	2253	2.34	13.61	96	196	Off Idle	80.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.61	14.82	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:0	31.36	2263	2.34	13.62	96	196	Off Idle	80.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-3.68	14.83	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:0	31.36	2259	2.34	13.62	96	196	Off Idle	80.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.73	14.85	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:0	31.36	2259	2.34	13.6	96	196	Off Idle	80.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.76	14.86	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:1	31.36	2268	2.35	13.58	96	196	Off Idle	80.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.73	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:07:1	31.36	2266	2.35	13.59	96	196	Off Idle	80.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.66	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:07:1	31.36	2268	2.35	13.59	96	196	Off Idle	80.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.62	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:07:1	31.36	2269	2.35	13.59	96	196	Off Idle	80.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.62	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:07:1	31.36	2266	2.35	13.62	96	196	Off Idle	80.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.63	14.83	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:07:1	31.36	2274	2.35	13.62	96	196	Off Idle	80.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.66	14.86	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:07:1	31.36	2273	2.35	13.62	96	196	Off Idle	80	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.73	14.87	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:2	31.36	2274	2.35	13.61	96	196	Off Idle	79.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.76	14.89	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:2	31.36	2283	2.35	13.59	96	196	Off Idle	79.7	0	2	132	944 Turbo	0.22	Rich	1	14.6	-3.78	14.9	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:2	31.36	2283	2.35	13.58	96	196	Off Idle	79.7	0	2	132	944 Turbo	0.22	Rich	1	14.6	-3.81	14.9	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:2	31.36	2273	2.35	13.57	96	196	Off Idle	79.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-3.82	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:2	31.36	2275	2.35	13.57	96	196	Off Idle	79.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-3.81	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:2	31.36	2276	2.34	13.56	96	196	Off Idle	79.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-3.81	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:07:3	31.36	2277	2.34	13.58	96	196	Off Idle	79.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.81	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:3	31.36	2280	2.34	13.58	96	196	Off Idle	79.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.83	15.09	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:3	31.36	2274	2.34	13.55	96	196	Off Idle	79.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.86	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:3	31.36	2274	2.34	13.53	96	196	Off Idle	79.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.87	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:3	31.36	2281	2.34	13.5	96	196	Off Idle	79.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.9	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:3	31.36	2287	2.34	13.47	96	196	Off Idle	79.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.89	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:4	31.36	2290	2.33	13.44	96	196	Off Idle	79.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.92	14.99	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:4	31.36	2296	2.33	13.43	96	197	Off Idle	79.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.92	14.97	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:4	31.36	2299	2.33	13.43	96	197	Off Idle	78.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.91	14.96	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:4	31.36	2292	2.33	13.44	96	197	Off Idle	78.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.92	14.94	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:4	31.36	2292	2.33	13.45	96	197	Off Idle	78.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-3.94	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:4	31.36	2291	2.33	13.44	96	197	Off Idle	78.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-3.95	14.86	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:4	31.36	2291	2.33	13.43	96	197	Off Idle	78.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-3.98	14.85	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:5	31.36	2290	2.33	13.42	96	196	Off Idle	78.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-3.96	14.86	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:5	31.36	2291	2.33	13.41	96	196	Off Idle	78.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.94	14.88	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:5	31.36	2290	2.32	13.41	96	196	Off Idle	78.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.95	14.93	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:5	31.36	2307	2.32	13.42	96	196	Off Idle	78	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.94	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:5	31.36	2311	2.32	13.43	96	196	Off Idle	77.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.98	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:5	31.36	2311	2.32	13.44	96	196	Off Idle	77.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.02	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:6	31.36	2311	2.32	13.44	96	197	Off Idle	77.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.05	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:6	31.36	2310	2.32	13.45	96	197	Off Idle	77.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.08	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:6	31.36	2308	2.32	13.44	96	197	Off Idle	77.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.06	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:6	31.36	2302	2.32	13.46	96	196	Off Idle	77.8	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.05	15.14	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:6	31.36	2323	2.32	13.45	96	196	Off Idle	77.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.04	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:6	31.36	2323	2.32	13.43	96	197	Off Idle	77.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.03	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:6	32.72	2307	2.32	13.43	96	197	Off Idle	77.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.97	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:7	32.72	2307	2.33	13.44	96	197	Off Idle	77.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.98	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:7	32.72	2310	2.33	13.43	96	197	Off Idle	77.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:7	32.72	2318	2.33	13.43	96	197	Off Idle	77.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.98	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:7	32.72	2325	2.33	13.44	96	197	Off Idle	77.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.01	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:7	32.72	2313	2.33	13.43	96	197	Off Idle	77.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.05	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:7	31.36	2322	2.33	13.43	96	197	Off Idle	77.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.02	14.87	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:8	31.36	2328	2.33	13.44	96	197	Off Idle	77.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.02	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:8	31.36	2326	2.33	13.45	96	197	Off Idle	77.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.08	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:8	31.36	2326	2.33	13.44	96	197	Off Idle	77.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.09	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:8	31.36	2325	2.33	13.45	96	197	Off Idle	77.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.1	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:8	31.36	2319	2.33	13.44	96	197	Off Idle	77.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.13	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:8	31.36	2321	2.33	13.44	96	197	Off Idle	76.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.1	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:9	32.72	2321	2.33	13.44	96	197	Off Idle	76.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.1	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:9	32.72	2330	2.33	13.45	96	197	Off Idle	76.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.08	15.03	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:07:9	32.72	2319	2.33	13.44	96	197	Off Idle	76.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.08	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:9	32.72	2340	2.33	13.44	96	197	Off Idle	76.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.05	15.15	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:9	32.72	2340	2.33	13.44	96	197	Off Idle	76.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.08	15.21	1.04	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:07:9	32.72	2340	2.33	13.44	96	197	Off Idle	76.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.09	15.22	1.04	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:07:9	32.72	2356	2.33	13.45	96	197	Off Idle	76.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.12	15.23	1.04	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:0	32.72	2346	2.33	13.44	96	197	Off Idle	76.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.13	15.23	1.04	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:0	32.72	2334	2.33	13.42	96	197	Off Idle	76.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.18	15.24	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:0	32.72	2333	2.33	13.41	96	197	Off Idle	76.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.22	15.21	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:0	32.72	2331	2.34	13.41	96	197	Off Idle	76.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.19	15.18	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:0	32.72	2334	2.34	13.42	96	197	Off Idle	76.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.16	15.12	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:0	32.72	2348	2.34	13.44	96	196	Off Idle	76.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.18	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:1	32.72	2353	2.34	13.46	96	196	Off Idle	76.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.14	15.05	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:1	32.72	2354	2.34	13.47	96	196	Off Idle	76	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.1	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:1	32.72	2375	2.34	13.48	96	196	Off Idle	75.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.15	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:1	32.72	2359	2.34	13.47	96	196	Off Idle	75.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.16	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:1	32.72	2359	2.34	13.46	96	196	Off Idle	75.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.19	14.9	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:1	32.72	2354	2.34	13.44	96	197	Off Idle	75.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.2	14.84	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:1	32.72	2351	2.34	13.44	96	197	Off Idle	75.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.16	14.84	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:08:2	32.72	2342	2.34	13.44	96	197	Off Idle	75	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.13	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:2	32.72	2354	2.34	13.43	96	197	Off Idle	74.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.11	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:2	32.72	2355	2.34	13.42	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.14	14.88	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:2	32.72	2355	2.34	13.44	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.14	14.9	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:2	32.72	2361	2.34	13.43	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.2	14.94	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:2	32.72	2364	2.34	13.43	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.24	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:3	32.72	2364	2.34	13.45	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.22	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:3	32.72	2363	2.34	13.47	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.17	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:3	32.72	2364	2.34	13.48	96	197	Off Idle	74.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.14	15.07	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:3	32.72	2365	2.35	13.49	96	196	Off Idle	74.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.13	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:3	32.72	2368	2.35	13.49	96	196	Off Idle	74.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.13	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:3	32.72	2370	2.35	13.46	96	196	Off Idle	74.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.13	15.17	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:4	32.72	2356	2.35	13.47	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-4.08	15.17	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:4	32.72	2368	2.35	13.47	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.09	15.13	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:4	32.72	2369	2.35	13.46	96	197	Off Idle	74.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.12	15.09	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:4	32.72	2372	2.35	13.46	96	197	Off Idle	74.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.13	15.07	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:4	32.72	2377	2.35	13.48	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.13	15.01	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:4	32.72	2396	2.35	13.47	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.17	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:4	32.72	2389	2.35	13.46	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.19	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:5	32.72	2392	2.35	13.48	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.19	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:5	32.72	2392	2.35	13.48	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.19	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:5	32.72	2384	2.35	13.48	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.19	14.78	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:5	32.72	2382	2.35	13.47	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.22	14.77	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:5	32.72	2374	2.35	13.46	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.23	14.78	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:5	31.36	2366	2.35	13.45	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.23	14.77	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:6	31.36	2376	2.35	13.45	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.23	14.78	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:6	31.36	2385	2.35	13.46	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.22	14.78	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:6	31.36	2387	2.35	13.46	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.21	14.82	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:6	31.36	2394	2.35	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.2	14.85	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:6	31.36	2399	2.35	13.47	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.19	14.89	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:6	31.36	2421	2.35	13.47	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.22	14.9	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:6	32.72	2412	2.35	13.47	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.16	Rich	1	14.6	-4.16	14.94	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:7	32.72	2400	2.35	13.46	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.24	Rich	1	14.6	-4.25	15	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:7	32.72	2395	2.35	13.45	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-4.25	15.05	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:7	32.72	2409	2.35	13.45	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.36	Rich	1	14.6	-4.25	15.09	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:7	32.72	2397	2.35	13.46	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.25	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:7	32.72	2388	2.35	13.46	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.27	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:7	32.72	2392	2.35	13.46	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.27	15.16	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:8	32.72	2396	2.35	13.48	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.25	15.21	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:8	32.72	2403	2.35	13.48	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.26	15.18	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:8	32.72	2414	2.35	13.48	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.26	15.15	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:8	32.72	2418	2.35	13.48	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.67	Lean	1	14.6	-4.27	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:8	32.72	2418	2.35	13.48	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.26	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:08:8	32.72	2416	2.35	13.46	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.26	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:9	32.72	2412	2.35	13.46	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.25	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:9	32.72	2403	2.35	13.45	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.26	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:08:9	32.72	2404	2.35	13.45	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.25	14.9	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:9	32.72	2404	2.35	13.46	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.23	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:9	32.72	2409	2.35	13.48	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.23	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:08:9	32.72	2423	2.35	13.48	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.21	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:08:9	32.72	2423	2.36	13.48	96	197	Off Idle	72	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.23	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:09:0	32.72	2428	2.36	13.49	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.28	14.85	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:09:0	32.72	2428	2.36	13.48	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.32	14.86	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:09:0	32.72	2426	2.36	13.48	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.34	14.91	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:09:0	32.72	2426	2.36	13.48	96	197	Off Idle	71	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.35	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:0	32.72	2422	2.36	13.47	96	197	Off Idle	71	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.35	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:0	32.72	2417	2.36	13.48	96	197	Off Idle	71	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.26	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:1	32.72	2417	2.36	13.48	96	197	Off Idle	71	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.23	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:09:1	32.72	2415	2.36	13.46	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.24	15.07	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:1	32.72	2416	2.36	13.46	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.25	15.09	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:1	32.72	2418	2.36	13.45	96	197	Off Idle	70.4	0	2	132	944 Turbo	0.66	Lean	1	14.6	-4.25	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:1	32.72	2424	2.36	13.44	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.27	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:1	32.72	2424	2.37	13.45	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.24	15.09	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:1	32.72	2435	2.37	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.18	15.04	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:09:2	32.72	2435	2.37	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.18	15	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:09:2	32.72	2444	2.37	13.48	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.22	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:09:2	32.72	2434	2.37	13.47	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.23	14.92	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:09:2	32.72	2432	2.37	13.46	97	197	Off Idle	70.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.24	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:09:2	32.72	2434	2.37	13.46	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.28	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:09:2	32.72	2434	2.37	13.44	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.28	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:09:3	32.72	2436	2.37	13.46	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.33	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:09:3	32.72	2442	2.37	13.45	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.38	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:3	32.72	2442	2.37	13.45	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.43	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:3	32.72	2436	2.36	13.46	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.43	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:3	32.72	2447	2.36	13.46	96	197	Off Idle	70	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.48	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:3	32.72	2449	2.36	13.45	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.54	14.88	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:4	32.72	2449	2.36	13.47	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.56	14.89	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:09:4	32.72	2446	2.35	13.47	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.64	14.91	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:09:4	32.72	2444	2.34	13.47	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.68	14.92	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:09:4	32.72	2439	2.34	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.77	14.93	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:4	32.72	2437	2.33	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.87	14.98	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:4	32.72	2437	2.33	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.92	15.03	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:09:4	32.72	2440	2.32	13.5	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.99	15.05	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:09:5	32.72	2446	2.31	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.06	15.02	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:09:5	32.72	2465	2.3	13.48	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.08	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:5	32.72	2443	2.29	13.47	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.21	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:5	32.72	2448	2.28	13.45	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.3	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:5	32.72	2452	2.27	13.47	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.36	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:5	32.72	2451	2.26	13.48	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.39	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:09:6	32.72	2451	2.25	13.48	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.43	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:09:6	32.72	2450	2.24	13.5	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.5	14.82	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:6	32.72	2448	2.23	13.5	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.55	14.78	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:6	32.72	2470	2.23	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.62	14.77	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:6	34.08	2470	2.22	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.7	14.75	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:6	34.08	2457	2.2	13.49	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.78	14.73	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:6	34.08	2470	2.2	13.48	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.86	14.76	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:7	34.08	2461	2.19	13.46	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.91	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:09:7	34.08	2460	2.19	13.48	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.98	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:7	34.08	2464	2.18	13.48	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.06	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:7	34.08	2464	2.17	13.46	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.12	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:09:7	34.08	2462	2.17	13.45	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.19	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:7	34.08	2460	2.16	13.46	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.21	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:09:8	34.08	2458	2.15	13.46	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.27	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:09:8	34.08	2455	2.15	13.47	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.35	15.23	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:09:8	34.08	2456	2.14	13.48	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.35	15.28	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:09:8	34.08	2458	2.14	13.5	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.37	15.32	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:09:8	34.08	2462	2.13	13.49	96	197	Off Idle	69	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.45	15.35	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:09:8	34.08	2465	2.12	13.48	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.44	15.36	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:09:9	34.08	2466	2.12	13.49	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.47	15.34	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:09:9	34.08	2465	2.11	13.48	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.54	15.31	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:09:9	34.08	2465	2.11	13.48	96	197	Off Idle	69	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.55	15.29	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:09:9	34.08	2461	2.1	13.5	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.57	15.28	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:09:9	34.08	2443	2.1	13.5	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.6	15.26	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:09:9	34.08	2443	2.09	13.51	96	197	Off Idle	69	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.67	15.22	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:09:9	34.08	2466	2.09	13.5	96	197	Off Idle	69	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.7	15.19	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:10:0	34.08	2468	2.08	13.49	96	196	Off Idle	69	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.72	15.18	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:10:0	34.08	2469	2.08	13.49	96	196	Off Idle	68.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.75	15.14	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:0	34.08	2478	2.07	13.48	96	196	Off Idle	68.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.8	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:0	34.08	2470	2.07	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.87	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:0	34.08	2469	2.06	13.47	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.93	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:10:0	34.08	2468	2.06	13.47	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.96	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:10:1	34.08	2463	2.06	13.47	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.97	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:10:1	34.08	2463	2.05	13.48	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.99	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:10:1	34.08	2461	2.05	13.47	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.02	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:1	34.08	2459	2.05	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.05	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:1	34.08	2482	2.05	13.47	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.09	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:1	34.08	2482	2.04	13.46	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.08	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:1	34.08	2469	2.04	13.48	96	197	Off Idle	68.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.09	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:2	34.08	2478	2.04	13.47	96	197	Off Idle	68.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.11	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:2	34.08	2486	2.03	13.48	96	197	Off Idle	68.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.11	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:2	34.08	2482	2.03	13.48	96	197	Off Idle	68.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.16	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:2	34.08	2484	2.03	13.49	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.19	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:2	34.08	2481	2.02	13.48	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.23	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:2	34.08	2470	2.02	13.48	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.24	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:10:3	34.08	2472	2.01	13.48	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.28	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:10:3	34.08	2465	2.01	13.49	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.37	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:10:3	34.08	2464	2	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.17	Rich	1	14.6	-7.41	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:10:3	34.08	2466	2	13.49	96	197	Off Idle	68	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.48	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:10:3	34.08	2467	1.99	13.51	96	197	Off Idle	68	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.51	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:10:3	34.08	2466	1.98	13.5	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.58	15.16	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:10:4	34.08	2468	1.98	13.5	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.62	15.2	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:10:4	34.08	2472	1.97	13.49	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.66	15.23	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:10:4	34.08	2472	1.96	13.49	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	15.24	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:10:4	34.08	2473	1.96	13.47	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	15.22	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:10:4	34.08	2476	1.95	13.47	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.79	15.2	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:10:4	34.08	2484	1.94	13.44	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.85	15.2	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:10:4	34.08	2473	1.94	13.44	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.9	15.2	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:10:5	34.08	2476	1.93	13.44	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.96	15.17	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:10:5	34.08	2476	1.92	13.47	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:5	34.08	2478	1.9	13.47	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.1	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:5	34.08	2478	1.89	13.48	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.11	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:5	34.08	2477	1.88	13.49	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.19	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:6	34.08	2467	1.88	13.47	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.22	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:6	34.08	2471	1.87	13.46	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.28	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:6	34.08	2470	1.86	13.47	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.34	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:6	34.08	2466	1.85	13.46	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.41	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:6	34.08	2466	1.85	13.46	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.46	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:6	34.08	2472	1.84	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.49	14.77	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:6	34.08	2474	1.82	13.5	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.53	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:6	34.08	2474	1.82	13.52	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.54	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:7	34.08	2496	1.81	13.53	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.62	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:7	35.45	2484	1.8	13.51	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.66	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:10:7	35.45	2489	1.79	13.51	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.71	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:10:7	35.45	2488	1.79	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.77	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:10:7	35.45	2465	1.78	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.82	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:10:7	35.45	2483	1.77	13.47	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.82	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:10:8	35.45	2480	1.76	13.48	96	197	Off Idle	68	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.86	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:8	35.45	2469	1.76	13.49	96	197	Off Idle	68	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.91	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:8	35.45	2469	1.75	13.49	96	197	Off Idle	68	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.96	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:8	35.45	2466	1.75	13.49	96	197	Off Idle	68	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.99	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:8	35.45	2462	1.74	13.51	96	197	Off Idle	68	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.97	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:8	35.45	2459	1.74	13.49	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.99	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:9	35.45	2459	1.73	13.49	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.97	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:9	34.08	2452	1.72	13.5	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.99	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:10:9	34.08	2463	1.72	13.5	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.02	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:9	34.08	2464	1.71	13.49	96	197	Off Idle	68.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.06	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:9	34.08	2480	1.7	13.49	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.14	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:10:9	34.08	2472	1.7	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.25	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:10:9	34.08	2466	1.69	13.47	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.27	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:0	35.45	2469	1.69	13.46	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.26	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:0	35.45	2452	1.69	13.46	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.27	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:0	35.45	2464	1.68	13.47	96	197	Off Idle	69	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.25	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:0	35.45	2477	1.68	13.48	96	197	Off Idle	69	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.3	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:0	35.45	2479	1.68	13.48	96	197	Off Idle	69	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.3	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:0	35.45	2482	1.67	13.49	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.33	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:1	35.45	2482	1.67	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.35	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:1	35.45	2482	1.67	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.35	14.77	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:1	35.45	2481	1.66	13.47	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.37	14.74	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:1	35.45	2476	1.66	13.47	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.35	14.73	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:1	35.45	2471	1.66	13.48	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.32	14.7	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:1	35.45	2471	1.66	13.49	96	197	Off Idle	68	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.31	14.7	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:1	35.45	2471	1.66	13.49	96	197	Off Idle	67.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.3	14.72	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:2	35.45	2469	1.66	13.49	96	197	Off Idle	67.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.3	14.72	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:2	35.45	2468	1.66	13.5	96	197	Off Idle	67.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.33	14.74	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:2	35.45	2468	1.66	13.49	96	197	Off Idle	67.9	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.33	14.75	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:2	35.45	2466	1.66	13.49	96	197	Off Idle	67.9	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.29	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:2	35.45	2466	1.66	13.49	96	197	Off Idle	67.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.25	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:2	35.45	2466	1.66	13.49	96	197	Off Idle	67.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.25	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:3	35.45	2466	1.66	13.48	96	197	Off Idle	67.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.26	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:3	35.45	2470	1.66	13.49	96	197	Off Idle	67.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.27	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:3	35.45	2470	1.66	13.49	96	197	Off Idle	67.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.28	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:3	35.45	2460	1.67	13.49	96	197	Off Idle	68	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.27	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:3	35.45	2468	1.67	13.5	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.27	14.79	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:3	35.45	2468	1.67	13.5	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.31	14.79	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:4	35.45	2468	1.67	13.48	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.3	14.8	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:4	35.45	2488	1.67	13.48	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.3	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:4	35.45	2468	1.67	13.49	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.31	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:4	35.45	2468	1.67	13.49	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.29	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:4	35.45	2470	1.67	13.49	96	197	Off Idle	68.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.25	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:4	35.45	2460	1.67	13.49	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.25	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:4	35.45	2468	1.67	13.49	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.25	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:5	35.45	2464	1.67	13.49	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.26	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:5	35.45	2464	1.67	13.49	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.28	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:5	35.45	2464	1.67	13.49	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.34	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:5	35.45	2462	1.67	13.48	96	197	Off Idle	69	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.35	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:5	35.45	2463	1.67	13.47	96	197	Off Idle	69	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.35	15.14	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:5	35.45	2464	1.67	13.46	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.37	15.14	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:6	35.45	2462	1.67	13.47	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.38	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:6	35.45	2459	1.67	13.47	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.35	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:6	35.45	2455	1.67	13.46	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.37	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:6	35.45	2454	1.66	13.49	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.35	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:6	35.45	2464	1.66	13.49	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.35	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:6	35.45	2455	1.66	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.35	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:6	35.45	2455	1.66	13.48	96	197	Off Idle	68.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.35	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:7	35.45	2456	1.66	13.5	96	197	Off Idle	68.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.34	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:7	35.45	2443	1.66	13.5	96	197	Off Idle	68.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.33	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:7	35.45	2443	1.66	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.31	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:7	35.45	2468	1.66	13.51	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.29	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:7	35.45	2471	1.66	13.51	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.29	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:7	35.45	2471	1.66	13.5	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.29	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:8	35.45	2482	1.66	13.5	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.29	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:8	35.45	2475	1.66	13.51	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.3	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:11:8	35.45	2473	1.66	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.3	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:8	35.45	2451	1.66	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.3	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:8	35.45	2460	1.66	13.47	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.32	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:8	35.45	2470	1.66	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.16	Rich	1	14.6	-9.33	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:9	35.45	2471	1.66	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.35	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:9	35.45	2471	1.66	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.37	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:9	35.45	2492	1.66	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.35	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:9	35.45	2482	1.66	13.5	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.33	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:11:9	35.45	2474	1.66	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.33	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:9	35.45	2472	1.66	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.31	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:11:9	35.45	2462	1.66	13.5	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.31	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:0	35.45	2470	1.66	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.33	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:0	35.45	2469	1.66	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.32	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:0	35.45	2465	1.66	13.5	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.34	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:0	35.45	2475	1.66	13.5	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.35	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:0	35.45	2475	1.66	13.5	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.37	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:0	35.45	2449	1.66	13.51	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.36	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:1	35.45	2447	1.66	13.49	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.38	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:1	35.45	2447	1.66	13.48	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.35	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:1	35.45	2439	1.66	13.48	96	197	Off Idle	68.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.35	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:1	35.45	2454	1.66	13.47	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.36	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:1	35.45	2454	1.66	13.47	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.34	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:1	35.45	2455	1.66	13.49	96	197	Off Idle	69	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.35	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:1	35.45	2458	1.65	13.48	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.39	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:2	35.45	2458	1.65	13.49	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.39	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:2	35.45	2458	1.65	13.49	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.41	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:2	35.45	2450	1.65	13.48	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.46	14.76	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:2	35.45	2458	1.65	13.48	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.46	14.73	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:2	35.45	2456	1.64	13.5	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.46	14.72	1	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:2	35.45	2456	1.64	13.47	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.49	14.69	1	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:12:3	35.45	2456	1.64	13.47	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.52	14.69	1	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:3	35.45	2453	1.64	13.49	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.49	14.84	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:3	35.45	2455	1.63	13.48	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.5	14.85	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:3	35.45	2455	1.63	13.47	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.52	14.87	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:3	35.45	2454	1.63	13.49	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.5	14.89	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:3	35.45	2458	1.62	13.5	96	197	Off Idle	69	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.5	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:4	35.45	2444	1.62	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.54	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:4	35.45	2441	1.62	13.49	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.54	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:4	35.45	2440	1.61	13.5	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.54	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:4	35.45	2438	1.61	13.5	96	197	Off Idle	68.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.55	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:4	35.45	2432	1.61	13.5	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.67	Lean	1	14.6	-9.53	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:4	35.45	2430	1.61	13.52	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.49	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:4	35.45	2430	1.61	13.51	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.52	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:5	35.45	2411	1.6	13.49	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.56	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:5	35.45	2434	1.6	13.5	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.58	15.14	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:5	35.45	2434	1.6	13.48	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.61	15.13	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:5	35.45	2438	1.6	13.48	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.58	15.13	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:5	35.45	2445	1.6	13.49	96	197	Off Idle	69.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.56	15.14	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:5	35.45	2459	1.6	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.56	15.13	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:6	35.45	2459	1.6	13.5	96	197	Off Idle	70	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.57	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:6	35.45	2465	1.6	13.49	96	197	Off Idle	70	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.59	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:6	35.45	2480	1.6	13.49	96	197	Off Idle	70	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.6	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:6	35.45	2480	1.6	13.47	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.63	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:6	35.45	2468	1.59	13.48	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.62	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:6	35.45	2468	1.59	13.5	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.61	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:6	35.45	2429	1.59	13.5	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.65	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:7	35.45	2429	1.59	13.5	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.65	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:7	35.45	2465	1.59	13.5	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.63	14.88	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:12:7	35.45	2462	1.59	13.49	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.66	14.87	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:7	35.45	2460	1.59	13.49	96	197	Off Idle	69	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.63	14.89	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:7	35.45	2478	1.59	13.48	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.63	14.91	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:7	35.45	2458	1.59	13.46	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.63	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:8	35.45	2454	1.59	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.61	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:8	35.45	2454	1.59	13.46	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.62	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:8	35.45	2442	1.59	13.46	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.63	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:8	35.45	2446	1.59	13.46	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.64	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:8	35.45	2442	1.59	13.47	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.66	15.17	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:8	35.45	2442	1.59	13.49	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.65	15.2	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:9	35.45	2434	1.59	13.49	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.66	15.23	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:9	35.45	2434	1.59	13.48	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.68	15.23	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:9	35.45	2435	1.58	13.46	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.69	15.22	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:9	35.45	2435	1.58	13.47	96	197	Off Idle	69.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.69	15.19	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:9	35.45	2432	1.58	13.46	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.71	15.18	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:9	35.45	2420	1.58	13.46	96	197	Off Idle	70	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.76	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:12:9	35.45	2431	1.57	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.72	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:0	35.45	2432	1.57	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.73	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:0	35.45	2432	1.56	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.76	15.05	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:0	35.45	2428	1.56	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.77	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:0	35.45	2427	1.55	13.48	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.77	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:0	35.45	2428	1.55	13.49	96	197	Off Idle	70.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.79	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:0	35.45	2428	1.54	13.49	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.81	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:1	35.45	2424	1.54	13.48	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.81	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:1	35.45	2424	1.54	13.48	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.82	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:1	35.45	2426	1.53	13.5	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.82	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:1	35.45	2426	1.53	13.48	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.83	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:1	35.45	2434	1.53	13.48	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.82	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:1	35.45	2426	1.52	13.47	96	197	Off Idle	71	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.86	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:1	35.45	2433	1.52	13.48	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.87	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:2	35.45	2433	1.52	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.87	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:2	35.45	2439	1.51	13.5	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.89	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:2	35.45	2442	1.51	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.9	14.99	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:2	35.45	2442	1.51	13.47	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.89	14.98	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:2	35.45	2454	1.5	13.47	96	197	Off Idle	71	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.88	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:2	35.45	2445	1.5	13.47	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.88	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:3	35.45	2444	1.5	13.48	96	197	Off Idle	70.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.89	14.94	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:3	35.45	2444	1.5	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.9	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:3	35.45	2421	1.5	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.87	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:3	35.45	2436	1.5	13.5	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.89	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:3	35.45	2436	1.5	13.51	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.87	14.86	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:3	35.45	2435	1.5	13.52	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.83	14.85	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:4	35.45	2456	1.5	13.5	96	197	Off Idle	69.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.85	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:4	35.45	2456	1.5	13.49	96	197	Off Idle	69.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.86	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:4	35.45	2434	1.5	13.49	96	197	Off Idle	69.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.84	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:4	35.45	2432	1.5	13.48	96	197	Off Idle	69.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.86	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:4	35.45	2432	1.5	13.48	96	197	Off Idle	69.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.87	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:4	35.45	2422	1.51	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.87	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:4	35.45	2430	1.51	13.49	96	197	Off Idle	70	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.87	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:5	35.45	2431	1.51	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.86	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:5	35.45	2431	1.51	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.84	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:5	35.45	2442	1.51	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.86	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:5	35.45	2432	1.51	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.85	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:5	35.45	2432	1.51	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.87	14.92	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:5	35.45	2432	1.51	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.87	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:6	35.45	2434	1.51	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.86	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:6	35.45	2428	1.51	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.88	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:6	35.45	2428	1.51	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.9	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:13:6	35.45	2428	1.51	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.9	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:6	35.45	2424	1.51	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.87	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:6	35.45	2424	1.51	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.88	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:6	35.45	2423	1.51	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.85	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:7	35.45	2421	1.51	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.82	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:7	35.45	2423	1.51	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.8	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:7	35.45	2423	1.51	13.49	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.83	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:7	35.45	2426	1.51	13.5	96	197	Off Idle	70.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.83	15.05	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:7	35.45	2416	1.51	13.5	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.83	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:7	35.45	2426	1.51	13.5	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.85	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:8	35.45	2426	1.51	13.51	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.85	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:8	35.45	2422	1.51	13.5	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.84	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:8	35.45	2422	1.51	13.49	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.88	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:8	35.45	2418	1.51	13.48	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.9	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:8	35.45	2418	1.51	13.49	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.89	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:8	35.45	2420	1.5	13.5	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.9	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:9	35.45	2423	1.5	13.5	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.91	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:9	35.45	2423	1.5	13.5	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.9	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:9	35.45	2426	1.5	13.48	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.87	14.9	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:9	35.45	2424	1.5	13.47	96	197	Off Idle	70.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.87	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:9	35.45	2423	1.5	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.87	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:13:9	35.45	2423	1.5	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.87	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:13:9	35.45	2422	1.5	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.82	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:14:0	35.45	2417	1.5	13.5	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.81	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:14:0	35.45	2417	1.5	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.82	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:0	35.45	2408	1.5	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.85	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:0	35.45	2419	1.5	13.47	96	197	Off Idle	70.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.87	14.86	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:0	35.45	2420	1.5	13.48	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.87	14.86	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:0	35.45	2417	1.5	13.46	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.91	14.86	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:1	35.45	2416	1.5	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.89	14.86	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:1	35.45	2416	1.5	13.49	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.87	14.87	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:1	35.45	2413	1.5	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.89	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:1	35.45	2412	1.5	13.48	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.87	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:1	35.45	2410	1.5	13.5	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.87	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:1	35.45	2411	1.5	13.5	96	197	Off Idle	71.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.88	14.94	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:1	35.45	2411	1.5	13.5	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.9	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:2	35.45	2408	1.5	13.5	96	197	Off Idle	71.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.9	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:2	35.45	2409	1.5	13.48	96	197	Off Idle	72.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.91	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:2	35.45	2400	1.5	13.47	96	197	Off Idle	72	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.92	15	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:2	35.45	2406	1.5	13.48	96	197	Off Idle	71.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.91	15	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:2	35.45	2404	1.5	13.49	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.89	15	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:2	35.45	2402	1.49	13.47	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.9	15	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:3	35.45	2410	1.49	13.49	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.9	15	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:3	35.45	2401	1.49	13.47	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.88	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:3	35.45	2401	1.49	13.47	96	197	Off Idle	71.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.87	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:14:3	35.45	2400	1.49	13.47	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.89	14.96	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:14:3	35.45	2392	1.49	13.5	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.86	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:14:3	35.45	2392	1.49	13.51	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.86	14.91	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:14:4	35.45	2399	1.49	13.52	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.89	14.86	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:4	35.45	2395	1.49	13.52	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.87	14.84	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:4	35.45	2399	1.49	13.5	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.88	14.84	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:4	35.45	2399	1.49	13.48	96	197	Off Idle	71.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.89	14.83	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:4	35.45	2410	1.49	13.48	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.87	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:4	35.45	2404	1.49	13.48	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.87	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:4	35.45	2409	1.49	13.48	96	197	Off Idle	72	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.87	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:5	35.45	2409	1.49	13.48	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.87	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:5	35.45	2412	1.49	13.47	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.87	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:5	35.45	2411	1.49	13.48	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.89	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:14:8	35.45	2409	1.49	13.48	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.88	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:8	35.45	2422	1.49	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.93	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:8	35.45	2412	1.49	13.5	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.93	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:6	35.45	2412	1.49	13.5	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.96	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:6	35.45	2412	1.48	13.5	96	197	Off Idle	72	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.95	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:6	35.45	2411	1.48	13.5	96	197	Off Idle	72	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.95	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:6	35.45	2402	1.48	13.5	96	197	Off Idle	72	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.93	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:6	35.45	2408	1.48	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.93	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:6	35.45	2404	1.48	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.9	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:6	35.45	2392	1.48	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.88	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:7	35.45	2392	1.48	13.5	96	197	Off Idle	72	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.88	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:7	35.45	2378	1.48	13.48	96	197	Off Idle	72	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.89	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:7	35.45	2378	1.48	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.89	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:7	35.45	2381	1.48	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.88	15.01	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:7	35.45	2381	1.48	13.48	96	197	Off Idle	72	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.9	15.04	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:7	35.45	2381	1.48	13.49	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.87	15.07	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:8	35.45	2379	1.48	13.47	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.87	15.08	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:8	35.45	2378	1.48	13.46	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.87	15.08	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:8	35.45	2378	1.48	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.87	15.09	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:8	35.45	2398	1.48	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.87	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:8	35.45	2383	1.48	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.89	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:8	35.45	2383	1.48	13.49	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.87	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:14:9	35.45	2385	1.48	13.48	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.88	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:14:9	35.45	2371	1.48	13.49	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.87	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:9	35.45	2371	1.48	13.51	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.89	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:9	35.45	2394	1.48	13.49	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.92	15.06	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:9	35.45	2396	1.48	13.49	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.92	15.05	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:9	35.45	2400	1.48	13.49	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.91	15.04	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:14:9	35.45	2399	1.48	13.49	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.89	15.02	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:0	35.45	2399	1.48	13.5	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.87	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:0	35.45	2402	1.48	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.88	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:0	35.45	2398	1.48	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.85	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:0	35.45	2398	1.48	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.85	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:0	35.45	2396	1.48	13.5	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.86	14.9	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:0	35.45	2395	1.48	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.87	14.9	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:1	35.45	2395	1.48	13.5	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.84	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:1	35.45	2395	1.48	13.5	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.87	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:1	35.45	2391	1.48	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.86	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:1	35.45	2390	1.48	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.83	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:1	35.45	2391	1.48	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.83	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:1	35.45	2373	1.49	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.83	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:1	35.45	2373	1.49	13.47	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.8	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:2	35.45	2380	1.49	13.47	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.81	14.9	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:2	35.45	2379	1.49	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.79	14.92	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:2	35.45	2380	1.5	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.78	14.93	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:15:2	35.45	2377	1.5	13.46	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.77	14.95	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:2	35.45	2379	1.51	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.72	14.98	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:2	35.45	2380	1.51	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.7	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:3	35.45	2378	1.51	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.66	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:3	35.45	2374	1.52	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.66	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:3	35.45	2377	1.52	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.56	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:3	35.45	2380	1.53	13.5	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.55	14.98	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:3	35.45	2380	1.53	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.66	Lean	1	14.6	-9.54	14.98	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:15:3	35.45	2384	1.54	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.51	14.98	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:4	35.45	2388	1.55	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.44	15	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:4	35.45	2393	1.56	13.5	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.44	15.01	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:4	35.45	2393	1.57	13.48	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.44	15	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:4	35.45	2394	1.57	13.48	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.39	15.01	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:15:4	35.45	2414	1.58	13.49	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.38	15	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:4	35.45	2412	1.59	13.48	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.38	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:4	35.45	2407	1.6	13.47	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.4	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:5	35.45	2409	1.6	13.47	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.39	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:5	35.45	2410	1.61	13.47	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.35	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:5	35.45	2410	1.61	13.47	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.29	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:5	35.45	2411	1.62	13.47	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.27	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:5	35.45	2409	1.62	13.49	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.23	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:5	35.45	2406	1.63	13.49	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.19	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:6	35.45	2384	1.63	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.17	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:6	35.45	2383	1.64	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.16	14.87	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:15:6	35.45	2378	1.64	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.13	14.9	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:6	35.45	2376	1.65	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.1	14.92	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:6	35.45	2371	1.65	13.48	96	197	Off Idle	72	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.1	14.94	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:6	34.08	2362	1.66	13.47	96	197	Off Idle	72	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.09	14.98	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:6	34.08	2370	1.66	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.02	15.02	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:7	34.08	2374	1.67	13.5	96	197	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9	15.04	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:7	34.08	2372	1.67	13.48	96	197	Off Idle	72	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.98	15.06	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:7	34.08	2373	1.68	13.47	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.94	15.07	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:7	34.08	2373	1.68	13.48	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.85	15.11	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:7	34.08	2382	1.69	13.49	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.83	15.11	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:7	34.08	2378	1.7	13.49	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.77	15.1	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:8	34.08	2378	1.7	13.5	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.74	15.06	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:8	34.08	2378	1.71	13.49	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.73	15.04	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:8	34.08	2378	1.71	13.5	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.71	15.02	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:8	34.08	2372	1.71	13.49	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.7	15	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:8	34.08	2390	1.72	13.48	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.69	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:8	34.08	2371	1.72	13.48	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.64	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:9	34.08	2370	1.72	13.48	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.63	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:9	34.08	2369	1.73	13.48	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.65	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:15:9	34.08	2353	1.73	13.49	96	197	Off Idle	73.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.65	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:15:9	34.08	2369	1.73	13.49	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.7	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:15:9	34.08	2371	1.73	13.49	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.71	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:15:9	34.08	2378	1.74	13.49	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.71	14.85	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:15:9	34.08	2385	1.74	13.48	96	197	Off Idle	74	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.67	14.85	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:16:0	34.08	2388	1.74	13.51	96	197	Off Idle	73.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.6	14.86	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:16:0	34.08	2388	1.75	13.52	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.59	14.86	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:16:0	34.08	2388	1.75	13.5	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.58	14.87	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:16:0	34.08	2389	1.75	13.5	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.58	14.86	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:16:0	34.08	2388	1.75	13.5	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.53	14.84	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:16:0	34.08	2384	1.76	13.5	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.42	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:16:1	34.08	2383	1.77	13.5	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.37	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:16:1	34.08	2383	1.77	13.49	96	197	Off Idle	73	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.31	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:16:1	34.08	2378	1.78	13.5	96	197	Off Idle	73	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.28	14.86	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:16:1	34.08	2378	1.79	13.5	96	197	Off Idle	73	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.25	14.87	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:16:1	34.08	2378	1.79	13.47	96	197	Off Idle	73	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.22	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:16:1	34.08	2378	1.81	13.47	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.14	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:16:1	34.08	2377	1.81	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.01	14.91	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:2	34.08	2378	1.83	13.47	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:2	34.08	2372	1.84	13.49	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.97	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:2	34.08	2372	1.85	13.5	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.93	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:2	34.08	2376	1.86	13.49	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.91	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:2	34.08	2374	1.86	13.48	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.7	Lean	1	14.6	-7.89	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:2	34.08	2388	1.87	13.47	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.84	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:3	34.08	2390	1.88	13.48	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.77	15.01	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:3	34.08	2390	1.89	13.48	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.74	14.99	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:3	34.08	2400	1.89	13.49	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.69	14.97	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:3	34.08	2389	1.9	13.5	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.65	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:16:3	34.08	2388	1.91	13.5	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.63	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:3	34.08	2382	1.91	13.5	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.61	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:4	34.08	2372	1.91	13.48	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.6	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:4	34.08	2372	1.92	13.49	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.56	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:4	34.08	2376	1.92	13.5	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.5	14.8	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:4	34.08	2378	1.93	13.5	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.48	14.8	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:4	34.08	2382	1.93	13.51	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.48	14.82	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:4	34.08	2382	1.93	13.5	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.43	14.84	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:4	34.08	2392	1.93	13.48	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.47	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:5	34.08	2386	1.93	13.48	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.47	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:5	34.08	2386	1.94	13.48	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.45	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:5	34.08	2378	1.94	13.5	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.44	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:5	34.08	2388	1.94	13.5	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.43	15.01	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:5	34.08	2390	1.94	13.51	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.44	15.02	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:5	34.08	2388	1.94	13.49	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.45	15.03	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:6	34.08	2388	1.94	13.47	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.48	15.02	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:16:6	34.08	2407	1.94	13.47	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.48	15.01	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:6	34.08	2387	1.94	13.47	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.48	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:6	34.08	2386	1.94	13.48	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.48	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:6	34.08	2366	1.94	13.48	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.42	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:6	34.08	2366	1.94	13.49	96	197	Off Idle	73	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.45	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:6	34.08	2382	1.94	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.48	14.88	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:7	34.08	2384	1.94	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.48	14.87	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:7	34.08	2389	1.94	13.49	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.41	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:7	34.08	2415	1.94	13.49	96	197	Off Idle	73	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.44	14.84	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:7	34.08	2415	1.94	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.43	14.83	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:7	34.08	2398	1.95	13.49	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.35	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:7	34.08	2400	1.95	13.5	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.33	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:8	34.08	2398	1.95	13.48	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.37	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:8	34.08	2398	1.95	13.49	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.37	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:8	34.08	2396	1.95	13.5	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.28	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:8	34.08	2396	1.95	13.5	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.32	14.98	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:8	34.08	2396	1.96	13.51	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.3	15.02	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:8	34.08	2398	1.96	13.49	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.28	15.09	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:16:9	34.08	2397	1.96	13.48	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.27	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:9	34.08	2396	1.96	13.48	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.26	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:9	34.08	2395	1.97	13.47	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.23	15.14	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:9	34.08	2397	1.97	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.19	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:9	34.08	2401	1.97	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.16	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:9	34.08	2401	1.97	13.51	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.13	15.15	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:16:9	34.08	2405	1.98	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.15	15.15	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:0	34.08	2407	1.98	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.16	15.12	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:0	34.08	2405	1.98	13.47	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.13	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:0	34.08	2405	1.98	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.16	15.08	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:0	34.08	2406	1.98	13.47	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.17	15.05	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:0	34.08	2404	1.99	13.49	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.18	15.03	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:0	34.08	2404	1.99	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.18	15	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:1	34.08	2406	1.99	13.48	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.2	14.97	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:1	34.08	2417	1.99	13.47	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.18	14.92	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:1	34.08	2408	1.99	13.49	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.15	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:1	34.08	2410	1.99	13.49	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.14	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:1	34.08	2410	1.99	13.5	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.17	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:1	34.08	2398	1.99	13.49	96	197	Off Idle	71.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.18	14.84	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:1	34.08	2408	1.99	13.49	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.19	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:2	34.08	2407	1.99	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.19	14.87	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:2	34.08	2407	1.99	13.47	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.22	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:2	34.08	2408	1.99	13.47	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.14	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:2	34.08	2414	2	13.49	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.13	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:17:2	34.08	2405	2	13.47	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.14	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:2	34.08	2405	2	13.47	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.09	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:3	34.08	2404	2	13.48	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.08	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:3	34.08	2401	2	13.47	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.1	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:3	34.08	2407	2	13.48	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.07	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:3	34.08	2408	2	13.47	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.06	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:3	34.08	2410	2	13.49	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.03	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:3	34.08	2414	2	13.49	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:4	34.08	2414	2.01	13.48	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.97	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:4	34.08	2426	2.01	13.47	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.96	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:4	34.08	2418	2.01	13.5	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.94	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:4	34.08	2418	2.01	13.5	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.96	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:4	34.08	2418	2.01	13.52	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.9	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:4	34.08	2419	2.02	13.53	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.9	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:4	34.08	2420	2.02	13.53	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.92	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:5	34.08	2418	2.02	13.51	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.93	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:5	34.08	2418	2.02	13.5	96	197	Off Idle	70.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.91	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:5	34.08	2401	2.02	13.49	96	198	Off Idle	70.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.92	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:5	34.08	2410	2.03	13.5	96	198	Off Idle	70.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.91	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:5	34.08	2416	2.03	13.49	96	198	Off Idle	70.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.89	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:5	34.08	2420	2.03	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.91	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:6	34.08	2424	2.03	13.49	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.93	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:6	34.08	2424	2.03	13.49	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.93	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:6	34.08	2425	2.03	13.5	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.94	14.84	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:6	34.08	2429	2.03	13.5	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.91	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:6	34.08	2429	2.03	13.5	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.93	14.89	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:6	34.08	2433	2.03	13.49	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.94	14.92	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:6	34.08	2433	2.03	13.47	96	197	Off Idle	71.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.93	14.95	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:7	34.08	2430	2.03	13.47	96	197	Off Idle	71.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.94	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:7	34.08	2426	2.03	13.47	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.94	15.04	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:7	34.08	2426	2.03	13.47	96	197	Off Idle	71	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.94	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:7	34.08	2420	2.03	13.47	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.96	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:7	34.08	2420	2.03	13.48	96	197	Off Idle	70.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.93	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:7	34.08	2421	2.03	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.95	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:8	34.08	2422	2.03	13.48	96	197	Off Idle	70	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.92	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:8	34.08	2426	2.03	13.49	96	197	Off Idle	70	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.91	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:8	34.08	2426	2.03	13.5	96	197	Off Idle	70	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.91	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:8	34.08	2427	2.03	13.49	96	197	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.96	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:8	34.08	2427	2.03	13.48	96	197	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.97	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:8	34.08	2432	2.03	13.48	96	197	Off Idle	70	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.96	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:9	34.08	2436	2.03	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.98	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:17:9	34.08	2438	2.03	13.46	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.95	15.05	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:9	34.08	2438	2.03	13.46	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.95	15	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:9	34.08	2436	2.03	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.01	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:9	34.08	2436	2.03	13.46	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.01	14.89	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:9	34.08	2436	2.03	13.46	96	198	Off Idle	70.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.01	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:17:9	34.08	2436	2.03	13.48	96	198	Off Idle	70.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.96	14.84	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:0	34.08	2437	2.03	13.49	96	198	Off Idle	70.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.91	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:0	34.08	2439	2.03	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.93	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:0	34.08	2438	2.03	13.52	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.93	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:0	34.08	2454	2.04	13.52	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.96	14.78	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:0	34.08	2439	2.04	13.52	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.97	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:0	34.08	2439	2.04	13.51	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:1	34.08	2441	2.04	13.51	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.01	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:1	34.08	2445	2.04	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.98	14.9	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:1	34.08	2446	2.04	13.48	96	197	Off Idle	70	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.02	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:1	34.08	2448	2.04	13.48	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.97	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:1	34.08	2445	2.04	13.46	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.97	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:18:1	34.08	2445	2.04	13.46	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.98	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:1	34.08	2444	2.04	13.45	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.97	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:2	34.08	2444	2.04	13.45	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.94	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:2	34.08	2442	2.04	13.47	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.97	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:2	34.08	2440	2.04	13.48	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.93	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:2	34.08	2447	2.04	13.48	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.95	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:2	34.08	2447	2.04	13.47	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.98	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:2	34.08	2449	2.04	13.48	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.97	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:3	34.08	2453	2.04	13.47	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.96	15.07	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:18:3	34.08	2453	2.04	13.46	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.98	15.05	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:18:3	34.08	2454	2.04	13.48	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.96	15.02	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:18:3	34.08	2491	2.04	13.48	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.96	15.01	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:18:3	34.08	2454	2.04	13.48	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.99	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:18:3	34.08	2454	2.04	13.48	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.99	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:4	34.08	2418	2.04	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.01	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:4	34.08	2455	2.04	13.49	96	198	Off Idle	69.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.99	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:4	34.08	2455	2.04	13.47	96	198	Off Idle	69.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.98	14.85	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:18:4	34.08	2452	2.04	13.48	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.02	14.85	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:18:4	34.08	2455	2.04	13.48	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.05	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:18:4	34.08	2455	2.04	13.46	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.09	14.84	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:4	34.08	2456	2.03	13.46	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.14	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:5	34.08	2455	2.03	13.49	96	198	Off Idle	69.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.14	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:5	34.08	2470	2.03	13.48	96	198	Off Idle	69.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.16	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:5	34.08	2460	2.03	13.47	96	198	Off Idle	69.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.19	14.9	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:5	34.08	2449	2.02	13.48	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.16	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:5	34.08	2450	2.02	13.49	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.17	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:5	34.08	2452	2.02	13.49	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.2	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:18:6	34.08	2452	2.01	13.5	96	197	Off Idle	69	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.19	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:18:6	34.08	2453	2.01	13.49	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.26	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:18:6	34.08	2455	2.01	13.51	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.32	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:18:6	34.08	2458	2	13.5	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.4	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:18:6	34.08	2458	1.99	13.5	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.48	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:18:6	34.08	2454	1.99	13.5	96	197	Off Idle	69	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.58	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:18:6	34.08	2455	1.98	13.48	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.81	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:18:7	34.08	2458	1.97	13.49	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	14.76	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:18:7	34.08	2459	1.96	13.5	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	14.72	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:18:7	34.08	2459	1.95	13.47	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.84	14.7	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:18:7	34.08	2460	1.94	13.48	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.9	14.7	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:18:7	34.08	2456	1.93	13.5	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.95	14.71	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:18:7	34.08	2454	1.92	13.49	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.02	14.73	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:8	34.08	2454	1.91	13.47	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.07	14.74	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:8	34.08	2456	1.9	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.09	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:8	34.08	2446	1.89	13.49	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.14	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:8	34.08	2457	1.87	13.48	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.21	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:8	34.08	2458	1.86	13.49	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.67	Lean	1	14.6	-8.26	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:8	34.08	2457	1.85	13.5	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.63	Lean	1	14.6	-8.31	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:18:9	34.08	2449	1.84	13.49	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.37	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:18:9	35.45	2470	1.83	13.49	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.43	14.88	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:9	35.45	2460	1.83	13.51	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.46	14.91	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:9	35.45	2479	1.82	13.5	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.53	14.91	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:9	35.45	2479	1.81	13.46	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.59	14.91	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:18:9	35.45	2459	1.8	13.48	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.64	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:18:9	35.45	2460	1.79	13.48	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.7	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:19:0	35.45	2459	1.79	13.48	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.72	14.74	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:19:0	35.45	2478	1.78	13.48	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.8	14.73	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:19:0	35.45	2468	1.77	13.49	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.8	14.72	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:19:0	35.45	2457	1.76	13.48	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.85	14.72	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:19:0	35.45	2460	1.76	13.46	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.87	14.7	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:19:0	35.45	2442	1.76	13.46	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.83	14.71	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:19:1	35.45	2452	1.75	13.48	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.86	14.72	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:19:1	35.45	2462	1.75	13.48	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.89	14.74	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:19:1	35.45	2459	1.74	13.47	96	198	Off Idle	68.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.92	14.75	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:19:1	35.45	2450	1.74	13.47	96	198	Off Idle	68.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:19:1	35.45	2463	1.73	13.47	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.03	14.96	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:1	35.45	2462	1.73	13.46	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.03	15	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:1	35.45	2461	1.73	13.46	96	197	Off Idle	69	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.04	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:2	35.45	2480	1.72	13.47	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.05	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:2	35.45	2460	1.72	13.47	96	197	Off Idle	69	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.04	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:2	35.45	2454	1.72	13.49	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.05	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:2	35.45	2454	1.71	13.5	96	197	Off Idle	69	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.08	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:2	35.45	2415	1.71	13.49	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.09	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:2	35.45	2456	1.71	13.49	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.09	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:3	35.45	2455	1.71	13.5	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.1	15.09	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:3	35.45	2456	1.71	13.49	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.11	15.11	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:3	35.45	2467	1.7	13.49	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.09	15.11	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:3	35.45	2456	1.7	13.49	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.09	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:3	35.45	2456	1.7	13.49	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.09	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:3	35.45	2452	1.7	13.49	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.1	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:4	34.08	2461	1.7	13.47	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.11	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:4	34.08	2461	1.7	13.48	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.14	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:4	34.08	2460	1.7	13.48	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.14	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:4	34.08	2460	1.7	13.48	96	198	Off Idle	69.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.13	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:4	34.08	2475	1.69	13.49	96	198	Off Idle	69.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.12	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:4	34.08	2475	1.69	13.48	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.14	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:4	35.45	2451	1.69	13.49	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.14	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:5	35.45	2451	1.69	13.49	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.14	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:5	35.45	2441	1.69	13.5	96	198	Off Idle	68.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.17	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:5	35.45	2448	1.69	13.49	96	198	Off Idle	68.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.19	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:5	35.45	2450	1.69	13.49	96	198	Off Idle	68.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.19	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:5	35.45	2434	1.69	13.48	96	198	Off Idle	68.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.22	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:5	35.45	2434	1.68	13.48	96	198	Off Idle	68.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.23	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:6	34.08	2447	1.68	13.48	96	198	Off Idle	68.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.25	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:6	34.08	2452	1.67	13.49	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.27	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:6	34.08	2452	1.67	13.49	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.33	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:6	34.08	2466	1.66	13.49	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.38	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:19:6	34.08	2460	1.66	13.49	96	198	Off Idle	69.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.43	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:19:6	34.08	2457	1.66	13.49	96	198	Off Idle	69.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.44	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:19:6	35.45	2457	1.65	13.49	96	198	Off Idle	69.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.46	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:19:7	35.45	2457	1.65	13.49	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.46	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:19:7	35.45	2454	1.64	13.49	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.46	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:19:7	35.45	2453	1.63	13.48	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.49	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:19:7	35.45	2439	1.63	13.48	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.52	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:19:7	35.45	2446	1.62	13.48	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.59	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:19:7	35.45	2445	1.62	13.49	96	197	Off Idle	69	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.63	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:19:8	35.45	2444	1.6	13.5	96	197	Off Idle	69	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.66	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:19:8	35.45	2442	1.6	13.5	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.66	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:19:8	35.45	2444	1.6	13.5	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.73	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:19:8	35.45	2444	1.59	13.49	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.73	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:19:8	35.45	2447	1.58	13.48	96	198	Off Idle	69.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.73	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:19:8	35.45	2444	1.57	13.48	96	198	Off Idle	69.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.74	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:19:9	35.45	2444	1.57	13.48	96	198	Off Idle	69.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.75	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:19:9	35.45	2445	1.56	13.48	96	198	Off Idle	69.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.76	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:19:9	35.45	2444	1.55	13.5	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.78	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:19:9	35.45	2440	1.55	13.48	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.81	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:19:9	35.45	2440	1.54	13.48	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.83	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:19:9	35.45	2437	1.54	13.5	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.84	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:19:9	35.45	2434	1.53	13.49	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.88	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:0	35.45	2428	1.53	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.9	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:0	35.45	2428	1.52	13.5	96	197	Off Idle	70	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.9	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:0	35.45	2420	1.51	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.89	15	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:0	35.45	2420	1.51	13.51	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.9	14.98	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:0	35.45	2380	1.5	13.5	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.95	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:0	35.45	2399	1.5	13.49	96	197	Off Idle	70.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.98	14.96	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:1	35.45	2429	1.49	13.49	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10	14.92	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:1	35.45	2429	1.48	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.02	14.89	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:1	35.45	2432	1.48	13.48	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.01	14.88	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:1	35.45	2462	1.48	13.5	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.02	14.86	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:1	35.45	2451	1.47	13.48	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.05	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:1	35.45	2451	1.47	13.47	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.07	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:1	35.45	2460	1.46	13.46	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.06	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:2	35.45	2462	1.46	13.48	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.08	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:2	35.45	2462	1.46	13.47	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.06	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:2	35.45	2459	1.45	13.48	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.08	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:2	35.45	2455	1.45	13.5	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.07	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:2	35.45	2454	1.45	13.5	96	197	Off Idle	70.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.06	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:2	35.45	2446	1.45	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.06	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:3	35.45	2441	1.45	13.51	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.06	14.96	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:3	35.45	2440	1.45	13.51	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.06	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:3	35.45	2434	1.45	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10.08	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:3	35.45	2429	1.45	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-10.07	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:3	35.45	2419	1.45	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-10.05	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:3	35.45	2419	1.45	13.48	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.05	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:4	35.45	2408	1.45	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.06	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:4	35.45	2414	1.45	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.07	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:4	35.45	2412	1.45	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.07	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:4	35.45	2412	1.45	13.48	96	197	Off Idle	70	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.08	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:4	35.45	2414	1.45	13.47	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.08	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:4	35.45	2424	1.45	13.48	96	197	Off Idle	70.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.06	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:4	35.45	2438	1.45	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-10.06	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:5	35.45	2438	1.44	13.49	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.08	15.03	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:5	35.45	2448	1.44	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-10.09	15.06	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:5	35.45	2471	1.44	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.11	15.07	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:5	35.45	2462	1.44	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.13	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:5	35.45	2450	1.44	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.13	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:5	35.45	2465	1.44	13.49	96	197	Off Idle	71	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.13	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:6	35.45	2441	1.44	13.5	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.15	15.01	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:6	35.45	2441	1.44	13.49	96	197	Off Idle	70.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.16	14.99	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:6	35.45	2440	1.44	13.49	96	197	Off Idle	70.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.15	14.98	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:6	35.45	2416	1.44	13.49	96	197	Off Idle	70.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.15	14.95	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:6	35.45	2430	1.44	13.49	96	197	Off Idle	70.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.16	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:6	35.45	2430	1.44	13.49	96	198	Off Idle	70.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.15	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:6	35.45	2423	1.44	13.49	96	198	Off Idle	70.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.13	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:7	35.45	2421	1.44	13.49	96	198	Off Idle	69.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.15	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:7	35.45	2417	1.44	13.48	96	198	Off Idle	69.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.12	14.83	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:7	35.45	2416	1.44	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.11	14.86	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:7	35.45	2409	1.44	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.12	14.9	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:7	35.45	2409	1.44	13.47	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.09	14.93	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:7	35.45	2408	1.44	13.47	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.09	14.97	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:8	35.45	2409	1.44	13.47	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10.11	15.01	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:8	35.45	2409	1.44	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-10.1	15.05	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:8	35.45	2408	1.44	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.09	15.09	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:20:8	35.45	2404	1.44	13.47	96	197	Off Idle	70.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-10.11	15.14	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:8	35.45	2403	1.44	13.48	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.11	15.15	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:8	35.45	2404	1.44	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.09	15.15	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:20:9	35.45	2412	1.44	13.48	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.09	15.14	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:9	35.45	2419	1.44	13.49	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.11	15.13	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:9	35.45	2426	1.44	13.48	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.11	15.12	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:9	35.45	2426	1.44	13.48	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.11	15.1	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:9	35.45	2423	1.44	13.47	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.11	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:9	35.45	2420	1.44	13.46	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.12	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:20:9	35.45	2420	1.44	13.48	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.12	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:0	35.45	2421	1.44	13.48	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.08	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:0	35.45	2420	1.44	13.48	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.08	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:0	35.45	2420	1.44	13.48	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.08	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:0	35.45	2422	1.44	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.05	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:0	35.45	2411	1.44	13.48	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.06	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:0	35.45	2413	1.44	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.08	15.01	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:1	35.45	2413	1.44	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.09	15.02	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:1	35.45	2393	1.44	13.49	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.09	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:1	35.45	2408	1.44	13.51	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	-10.1	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:1	35.45	2408	1.43	13.51	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.48	Lean	1	14.6	-10.1	15	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:1	35.45	2409	1.43	13.5	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.1	14.99	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:1	35.45	2410	1.43	13.5	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.08	14.98	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:1	35.45	2447	1.43	13.48	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-10.11	14.96	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:2	35.45	2429	1.43	13.48	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.13	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:2	35.45	2411	1.43	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.14	14.89	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:2	35.45	2412	1.43	13.5	96	197	Off Idle	72.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.14	14.89	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:2	35.45	2375	1.43	13.48	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.17	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:2	35.45	2394	1.43	13.51	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.16	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:2	35.45	2412	1.43	13.5	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.17	14.89	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:3	35.45	2410	1.43	13.49	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.14	14.9	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:3	35.45	2410	1.43	13.5	96	197	Off Idle	72.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.15	14.89	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:3	35.45	2420	1.43	13.51	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.14	14.88	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:3	35.45	2412	1.43	13.5	96	197	Off Idle	71.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.15	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:3	35.45	2413	1.42	13.5	96	197	Off Idle	71.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.13	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:3	35.45	2413	1.42	13.49	96	197	Off Idle	71.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-10.13	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:4	35.45	2402	1.42	13.49	96	197	Off Idle	71.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-10.12	14.91	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:4	35.45	2412	1.43	13.49	96	197	Off Idle	71.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-10.1	14.93	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:4	35.45	2409	1.43	13.48	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-10.09	14.96	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:4	35.45	2406	1.43	13.49	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.07	15.01	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:4	35.45	2414	1.43	13.48	96	198	Off Idle	71.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.08	15.03	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:4	35.45	2391	1.43	13.47	96	198	Off Idle	71.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.09	15.09	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:4	35.45	2389	1.43	13.48	96	198	Off Idle	71.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.06	15.12	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:5	35.45	2389	1.43	13.49	96	197	Off Idle	71.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.07	15.16	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:5	35.45	2369	1.43	13.48	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.08	15.16	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:5	35.45	2385	1.43	13.49	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.06	15.16	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:5	35.45	2384	1.43	13.5	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.05	15.15	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:5	35.45	2382	1.43	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.08	15.16	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:5	35.45	2381	1.43	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.1	15.13	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:6	35.45	2402	1.43	13.48	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.12	15.12	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:6	35.45	2395	1.43	13.48	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.11	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:6	35.45	2394	1.42	13.5	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.12	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:6	35.45	2401	1.42	13.5	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.12	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:6	35.45	2401	1.42	13.49	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-10.1	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:6	35.45	2400	1.42	13.51	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-10.1	15	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:6	35.45	2402	1.42	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.36	Rich	1	14.6	-10.12	14.97	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:7	35.45	2406	1.41	13.46	96	197	Off Idle	73	0	2	132	944 Turbo	0.32	Rich	1	14.6	-10.14	14.92	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:7	35.45	2406	1.41	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.14	14.88	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:7	35.45	2406	1.41	13.48	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.11	14.86	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:7	35.45	2404	1.41	13.47	96	198	Off Idle	72.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.11	14.85	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:7	35.45	2400	1.41	13.49	96	198	Off Idle	72.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.08	14.85	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:7	35.45	2410	1.41	13.49	96	198	Off Idle	72.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.05	14.85	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:21:8	35.45	2410	1.41	13.5	96	198	Off Idle	72.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.06	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:8	35.45	2390	1.41	13.51	96	197	Off Idle	72.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.1	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:8	35.45	2388	1.41	13.52	96	197	Off Idle	72.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.09	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:8	35.45	2379	1.41	13.52	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.11	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:8	35.45	2389	1.41	13.51	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.12	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:8	35.45	2389	1.41	13.48	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.12	14.83	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:9	35.45	2388	1.41	13.49	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.09	14.84	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:9	35.45	2387	1.41	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.1	14.84	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:9	35.45	2407	1.41	13.47	96	197	Off Idle	73	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.11	14.85	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:21:9	35.45	2391	1.41	13.47	96	197	Off Idle	73	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.11	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:9	35.45	2392	1.41	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.1	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:9	35.45	2384	1.42	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.11	14.9	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:21:9	35.45	2394	1.42	13.5	96	197	Off Idle	73	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.11	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:0	35.45	2394	1.42	13.51	96	197	Off Idle	73	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.1	14.95	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:0	35.45	2387	1.42	13.52	96	197	Off Idle	73	0	2	132	944 Turbo	0.33	Rich	1	14.6	-10.08	15.03	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:0	35.45	2387	1.41	13.52	96	197	Off Idle	73	0	2	132	944 Turbo	0.39	Rich	1	14.6	-10.08	15.04	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:0	35.45	2381	1.41	13.5	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.11	15.06	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:0	35.45	2390	1.41	13.5	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.14	15.07	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:0	35.45	2383	1.41	13.5	96	197	Off Idle	73	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.13	15.08	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:1	35.45	2381	1.41	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.14	15.09	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:1	35.45	2390	1.41	13.48	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.13	15.09	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:1	35.45	2380	1.41	13.5	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.07	15.11	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:1	35.45	2379	1.41	13.49	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.06	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:1	35.45	2379	1.41	13.51	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.06	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:1	35.45	2365	1.41	13.48	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.08	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:1	35.45	2371	1.41	13.49	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.06	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:2	35.45	2373	1.41	13.49	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.08	15.07	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:2	35.45	2373	1.41	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.08	15.06	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:2	35.45	2370	1.41	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.08	15.07	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:2	35.45	2389	1.41	13.5	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.06	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:2	35.45	2381	1.41	13.5	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-10.09	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:2	35.45	2374	1.41	13.48	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-10.08	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:3	35.45	2384	1.41	13.49	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-10.09	15.05	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:3	35.45	2373	1.41	13.48	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-10.09	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:3	35.45	2393	1.41	13.49	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.07	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:3	35.45	2393	1.42	13.5	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.05	14.98	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:3	35.45	2390	1.42	13.48	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.07	14.96	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:3	35.45	2388	1.42	13.49	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.04	14.93	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:4	35.45	2388	1.42	13.5	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.03	14.9	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:22:4	35.45	2386	1.42	13.49	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.04	14.85	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:4	35.45	2383	1.42	13.48	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.04	14.85	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:4	35.45	2378	1.42	13.49	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.02	14.84	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:4	35.45	2376	1.43	13.49	96	197	Off Idle	73	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.01	14.83	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:4	35.45	2371	1.43	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.23	Rich	1	14.6	-10	14.8	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:4	35.45	2372	1.43	13.47	96	197	Off Idle	73	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.98	14.8	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:5	35.45	2372	1.44	13.47	96	197	Off Idle	73	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.96	14.82	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:5	35.45	2370	1.44	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.95	14.85	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:5	35.45	2367	1.44	13.47	96	197	Off Idle	73	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.97	14.86	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:5	35.45	2367	1.45	13.47	96	197	Off Idle	73	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.92	14.9	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:5	35.45	2367	1.45	13.49	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.9	14.91	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:5	35.45	2370	1.46	13.49	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.87	14.95	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:6	35.45	2371	1.46	13.49	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.84	14.96	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:6	35.45	2371	1.47	13.49	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.82	15.02	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:6	35.45	2372	1.47	13.48	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.82	15.06	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:6	35.45	2389	1.48	13.47	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.81	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:6	35.45	2376	1.49	13.48	96	197	Off Idle	74	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.8	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:6	35.45	2377	1.49	13.5	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.72	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:6	35.45	2359	1.49	13.51	96	197	Off Idle	74	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.69	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:22:7	35.45	2359	1.5	13.51	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.7	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:7	35.45	2375	1.5	13.5	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.67	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:22:7	35.45	2372	1.51	13.49	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.66	15.08	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:7	35.45	2372	1.51	13.49	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.66	15.07	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:7	35.45	2370	1.51	13.49	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.64	15.05	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:7	35.45	2378	1.52	13.49	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.62	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:8	35.45	2371	1.52	13.48	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.61	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:8	35.45	2372	1.53	13.48	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.59	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:8	35.45	2372	1.53	13.48	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.56	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:8	35.45	2377	1.53	13.49	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.53	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:8	35.45	2377	1.53	13.5	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.56	14.94	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:22:8	35.45	2381	1.54	13.5	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.56	14.91	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:22:9	35.45	2390	1.54	13.5	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.52	14.89	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:9	35.45	2381	1.55	13.5	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.52	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:9	35.45	2380	1.55	13.49	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.52	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:22:9	35.45	2377	1.55	13.49	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.49	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:22:9	35.45	2378	1.56	13.5	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.49	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:22:9	35.45	2376	1.56	13.5	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.47	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:22:9	35.45	2376	1.56	13.5	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.46	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:23:0	35.45	2372	1.57	13.5	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.44	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:23:0	35.45	2348	1.57	13.49	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.42	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:23:0	35.45	2356	1.57	13.47	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.39	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:23:0	35.45	2360	1.58	13.47	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.39	14.91	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:0	35.45	2359	1.58	13.48	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.38	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:23:0	35.45	2359	1.58	13.49	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.37	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:23:1	35.45	2369	1.58	13.48	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.39	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:1	35.45	2358	1.59	13.49	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.35	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:1	35.45	2356	1.59	13.49	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.31	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:1	35.45	2356	1.59	13.47	96	197	Off Idle	74	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.28	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:1	35.45	2340	1.59	13.47	96	197	Off Idle	74	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.24	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:1	35.45	2349	1.6	13.46	96	197	Off Idle	74	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.24	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:1	35.45	2354	1.6	13.46	96	197	Off Idle	74	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.23	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:2	35.45	2348	1.6	13.46	96	197	Off Idle	74	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.26	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:2	34.08	2358	1.61	13.46	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.25	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:23:2	34.08	2362	1.61	13.46	96	197	Off Idle	74.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.22	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:2	34.08	2362	1.62	13.47	96	197	Off Idle	74.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.19	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:2	34.08	2360	1.62	13.47	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.14	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:2	34.08	2360	1.63	13.46	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.05	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:3	34.08	2372	1.64	13.48	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.98	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:3	34.08	2367	1.64	13.46	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.95	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:3	34.08	2369	1.65	13.48	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.93	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:3	34.08	2369	1.66	13.48	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.85	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:3	34.08	2362	1.67	13.48	96	197	Off Idle	74.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.83	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:3	34.08	2373	1.68	13.48	96	197	Off Idle	74.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.77	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:4	34.08	2374	1.69	13.48	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.71	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:4	34.08	2375	1.7	13.49	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.69	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:4	34.08	2374	1.71	13.49	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.67	14.81	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:4	34.08	2381	1.72	13.49	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.63	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:4	34.08	2369	1.72	13.49	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.63	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:4	34.08	2369	1.73	13.47	96	198	Off Idle	74	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.59	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:4	34.08	2367	1.74	13.47	96	198	Off Idle	73.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.51	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:5	34.08	2347	1.75	13.5	96	198	Off Idle	73.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.46	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:5	34.08	2363	1.76	13.49	96	197	Off Idle	73.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.41	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:5	34.08	2354	1.76	13.51	96	197	Off Idle	73.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.4	15.04	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:5	34.08	2358	1.77	13.52	96	197	Off Idle	73.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.39	15.07	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:5	34.08	2359	1.77	13.51	96	197	Off Idle	73.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.36	15.11	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:5	34.08	2368	1.77	13.52	96	197	Off Idle	74	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.34	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:6	34.08	2366	1.78	13.52	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.33	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:23:6	34.08	2369	1.78	13.51	96	197	Off Idle	74.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.36	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:6	34.08	2370	1.78	13.51	96	197	Off Idle	74.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.41	15.14	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:6	34.08	2366	1.78	13.49	96	197	Off Idle	74.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.42	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:6	34.08	2373	1.78	13.47	96	197	Off Idle	74.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.39	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:6	34.08	2373	1.79	13.49	96	197	Off Idle	74.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.38	15.09	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:6	34.08	2369	1.79	13.47	96	197	Off Idle	74.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.32	15.03	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:7	34.08	2364	1.79	13.47	96	197	Off Idle	74.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.31	14.98	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:7	34.08	2364	1.79	13.47	96	197	Off Idle	74.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.31	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:7	34.08	2353	1.79	13.47	96	197	Off Idle	74.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.32	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:7	34.08	2354	1.79	13.5	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.31	14.73	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:7	34.08	2355	1.79	13.49	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.32	14.68	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:7	34.08	2355	1.79	13.49	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.32	14.65	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:8	34.08	2359	1.79	13.48	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.33	14.62	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:8	34.08	2362	1.79	13.48	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.32	14.6	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:8	34.08	2368	1.79	13.49	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.3	14.59	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:8	34.08	2368	1.79	13.49	96	197	Off Idle	74.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.26	14.59	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:8	34.08	2373	1.79	13.5	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.26	14.59	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:8	34.08	2374	1.8	13.5	97	197	Off Idle	74	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.24	14.59	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:23:9	34.08	2374	1.8	13.49	97	197	Off Idle	74	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.21	14.73	1	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:9	34.08	2374	1.8	13.49	96	197	Off Idle	74	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.22	14.73	1	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:9	34.08	2372	1.81	13.49	96	197	Off Idle	74	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.19	14.74	1	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:9	34.08	2371	1.81	13.48	96	197	Off Idle	74	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.13	14.75	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:9	34.08	2370	1.82	13.48	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.09	14.77	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:23:9	34.08	2366	1.82	13.47	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.05	14.78	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:23:9	34.08	2362	1.83	13.46	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:24:0	34.08	2366	1.83	13.48	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.93	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:24:0	34.08	2365	1.83	13.48	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.96	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:24:0	34.08	2365	1.84	13.48	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.95	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:24:0	34.08	2369	1.85	13.48	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.96	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:24:0	34.08	2372	1.85	13.49	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.92	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:0	34.08	2372	1.86	13.49	96	197	Off Idle	74	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.86	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:1	34.08	2354	1.87	13.5	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.8	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:1	34.08	2364	1.87	13.5	96	197	Off Idle	74.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:1	34.08	2369	1.88	13.48	96	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	14.85	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:1	34.08	2369	1.88	13.49	96	197	Off Idle	73.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.89	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:1	34.08	2368	1.89	13.49	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	14.92	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:1	34.08	2367	1.89	13.48	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.71	14.96	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:1	34.08	2368	1.89	13.48	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.65	15	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:24:2	34.08	2372	1.9	13.48	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.64	15.06	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:24:2	34.08	2374	1.9	13.49	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.61	15.11	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:2	34.08	2374	1.91	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.56	15.14	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:2	34.08	2375	1.91	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.55	15.16	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:2	34.08	2372	1.91	13.46	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.53	15.17	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:2	34.08	2372	1.92	13.49	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.52	15.17	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:3	34.08	2373	1.92	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.51	15.16	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:3	34.08	2370	1.92	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.51	15.14	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:3	34.08	2367	1.93	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.48	15.13	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:3	34.08	2367	1.93	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.44	15.13	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:24:3	34.08	2373	1.93	13.49	96	198	Off Idle	73.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.46	15.1	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:3	34.08	2377	1.93	13.48	96	198	Off Idle	73.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.46	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:4	34.08	2377	1.93	13.48	96	198	Off Idle	73.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.46	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:4	34.08	2383	1.94	13.46	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.49	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:4	34.08	2385	1.94	13.45	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.48	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:4	34.08	2368	1.94	13.44	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.47	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:4	34.08	2382	1.94	13.47	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.5	14.96	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:4	34.08	2379	1.94	13.49	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.48	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:24:4	34.08	2374	1.94	13.51	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.5	14.9	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:24:5	34.08	2370	1.94	13.51	96	197	Off Idle	73	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.46	14.87	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:24:5	34.08	2369	1.94	13.5	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.47	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:24:5	34.08	2369	1.94	13.5	96	197	Off Idle	72.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.44	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:24:5	34.08	2374	1.94	13.49	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.4	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:24:5	34.08	2368	1.94	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.4	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:5	34.08	2381	1.94	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.37	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:6	34.08	2381	1.94	13.47	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.37	14.91	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:6	34.08	2381	1.94	13.47	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.32	14.94	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:6	34.08	2381	1.95	13.48	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.27	14.97	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:24:6	34.08	2397	1.95	13.48	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.2	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:24:6	34.08	2388	1.96	13.5	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.16	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:24:6	34.08	2375	1.97	13.5	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.1	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:24:6	34.08	2378	1.97	13.49	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.05	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:24:7	34.08	2384	1.98	13.49	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:24:7	34.08	2384	1.99	13.49	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.93	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:24:7	34.08	2387	2	13.48	96	197	Off Idle	73.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.85	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:7	34.08	2389	2	13.49	96	197	Off Idle	73.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.84	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:7	34.08	2390	2.01	13.47	96	197	Off Idle	73.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.85	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:7	34.08	2395	2.01	13.47	96	197	Off Idle	73.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.79	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:8	34.08	2395	2.02	13.49	96	197	Off Idle	73.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.78	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:8	34.08	2393	2.03	13.49	96	197	Off Idle	73.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.76	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:8	34.08	2392	2.04	13.48	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.75	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:8	34.08	2388	2.04	13.47	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.77	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:8	34.08	2386	2.04	13.48	96	197	Off Idle	73.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.81	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:8	34.08	2386	2.05	13.47	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.15	Rich	1	14.6	-6.81	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:9	34.08	2389	2.05	13.47	96	198	Off Idle	73.2	0	2	132	944 Turbo	0.19	Rich	1	14.6	-6.79	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:9	34.08	2389	2.05	13.49	96	198	Off Idle	73	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.75	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:24:9	32.72	2380	2.05	13.49	96	198	Off Idle	73	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.76	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:24:9	32.72	2387	2.05	13.47	96	197	Off Idle	73	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.75	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:24:9	32.72	2384	2.05	13.49	96	197	Off Idle	72.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.76	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:24:9	32.72	2384	2.05	13.49	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.74	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:24:9	32.72	2382	2.04	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.73	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:0	32.72	2382	2.04	13.49	96	197	Off Idle	73	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.73	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:0	32.72	2375	2.04	13.48	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.75	15.21	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:0	32.72	2386	2.04	13.47	96	197	Off Idle	73.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.78	15.21	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:25:0	32.72	2387	2.04	13.47	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.81	15.18	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:25:0	32.72	2392	2.04	13.48	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.82	15.15	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:0	32.72	2392	2.04	13.5	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.79	15.1	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:1	32.72	2408	2.04	13.51	96	197	Off Idle	73.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.77	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:1	34.08	2400	2.04	13.5	96	197	Off Idle	73.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.81	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:25:1	34.08	2400	2.04	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.82	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:25:1	34.08	2400	2.04	13.48	96	197	Off Idle	73	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.85	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:25:1	34.08	2398	2.04	13.48	96	197	Off Idle	72.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.85	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:1	34.08	2398	2.04	13.5	96	197	Off Idle	72.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.87	14.64	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:1	34.08	2394	2.04	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.84	14.61	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:2	34.08	2394	2.04	13.51	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.83	14.6	0.99	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:2	34.08	2376	2.04	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.82	14.62	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:2	34.08	2402	2.04	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.84	14.62	1	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:2	34.08	2409	2.04	13.47	96	197	Off Idle	72.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.81	14.62	1	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:2	34.08	2409	2.04	13.48	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.78	14.62	1	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:2	34.08	2410	2.04	13.48	96	197	Off Idle	72	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.77	14.61	1	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:3	34.08	2411	2.04	13.49	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.76	14.79	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:3	34.08	2410	2.04	13.51	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.75	14.81	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:3	34.08	2411	2.04	13.51	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.72	14.86	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:3	34.08	2411	2.04	13.51	96	197	Off Idle	71.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.75	14.87	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:3	34.08	2419	2.04	13.49	96	197	Off Idle	72.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.76	14.9	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:3	34.08	2408	2.05	13.48	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.72	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:4	34.08	2406	2.05	13.47	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.73	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:4	34.08	2406	2.05	13.46	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.74	15.05	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:25:4	34.08	2403	2.05	13.46	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.68	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:4	34.08	2405	2.05	13.48	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.71	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:4	34.08	2406	2.05	13.49	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.69	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:4	34.08	2406	2.05	13.49	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.66	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:4	34.08	2410	2.05	13.48	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.63	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:5	34.08	2403	2.05	13.47	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.64	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:5	32.72	2410	2.06	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.6	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:5	32.72	2410	2.06	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.62	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:5	32.72	2410	2.06	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.65	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:5	32.72	2409	2.06	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.62	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:5	32.72	2429	2.06	13.5	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.64	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:6	32.72	2421	2.06	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.65	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:6	32.72	2414	2.06	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.67	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:6	32.72	2419	2.06	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.71	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:6	32.72	2385	2.06	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.75	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:6	32.72	2402	2.06	13.48	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.74	14.81	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:6	32.72	2417	2.06	13.49	96	197	Off Idle	72.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.73	14.8	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:6	32.72	2435	2.06	13.49	96	197	Off Idle	72.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.75	14.8	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:7	34.08	2435	2.06	13.48	96	197	Off Idle	72.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.75	14.8	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:7	34.08	2420	2.06	13.49	96	197	Off Idle	72	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.74	14.78	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:7	34.08	2423	2.06	13.49	96	197	Off Idle	71.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.74	14.79	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:7	34.08	2422	2.06	13.5	96	197	Off Idle	71.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.7	14.8	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:7	34.08	2421	2.06	13.51	96	197	Off Idle	71.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.68	14.82	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:7	34.08	2422	2.06	13.5	96	197	Off Idle	71.2	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.71	14.85	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:25:8	34.08	2422	2.06	13.5	96	197	Off Idle	71.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.71	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:8	34.08	2422	2.06	13.5	96	197	Off Idle	70.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.7	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:8	34.08	2425	2.06	13.49	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.75	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:8	34.08	2425	2.06	13.48	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.72	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:8	34.08	2424	2.06	13.49	96	197	Off Idle	70.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.75	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:8	34.08	2419	2.06	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.73	15.05	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:9	34.08	2418	2.06	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.74	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:9	34.08	2418	2.06	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.77	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:9	34.08	2422	2.06	13.46	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.8	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:9	34.08	2427	2.06	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.83	15.08	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:9	34.08	2428	2.05	13.48	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.87	15.07	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:25:9	34.08	2429	2.05	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.9	15.04	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:25:9	34.08	2430	2.05	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.92	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:26:0	34.08	2428	2.05	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.93	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:26:0	34.08	2427	2.04	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.94	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:26:0	34.08	2427	2.04	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.96	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:26:0	34.08	2424	2.03	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.05	14.91	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:26:0	34.08	2422	2.03	13.47	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.11	14.85	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:26:0	34.08	2424	2.02	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.16	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:26:1	34.08	2424	2.02	13.48	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.2	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:26:1	34.08	2422	2.01	13.46	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.26	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:26:1	34.08	2422	2.01	13.48	96	197	Off Idle	70.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.27	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:26:1	34.08	2421	1.99	13.5	96	197	Off Idle	70.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.4	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:1	34.08	2422	1.99	13.49	96	197	Off Idle	70.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.46	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:1	34.08	2427	1.98	13.49	96	197	Off Idle	70.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.48	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:26:1	34.08	2435	1.97	13.51	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.53	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:26:2	34.08	2433	1.96	13.51	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.55	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:2	34.08	2438	1.95	13.49	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.58	14.88	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:2	34.08	2439	1.95	13.5	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.61	14.88	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:2	34.08	2447	1.94	13.5	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.66	14.9	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:2	34.08	2432	1.93	13.49	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.72	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:2	34.08	2430	1.92	13.47	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:3	34.08	2408	1.92	13.47	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.77	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:3	34.08	2408	1.91	13.45	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:26:3	34.08	2428	1.91	13.47	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.8	14.85	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:3	34.08	2431	1.9	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.81	14.87	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:3	34.08	2431	1.9	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.84	14.89	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:3	34.08	2444	1.9	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.86	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:4	34.08	2432	1.89	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.87	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:4	34.08	2433	1.89	13.48	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.87	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:4	34.08	2432	1.89	13.5	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.88	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:4	34.08	2432	1.89	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.89	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:4	34.08	2432	1.89	13.48	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.89	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:4	34.08	2436	1.88	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.95	15.08	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:4	34.08	2434	1.88	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.99	15.07	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:5	34.08	2434	1.88	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.98	15.09	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:5	34.08	2456	1.88	13.5	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:5	34.08	2446	1.88	13.48	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.06	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:5	34.08	2434	1.87	13.48	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.05	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:5	34.08	2435	1.87	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.07	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:5	34.08	2433	1.87	13.48	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.11	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:6	34.08	2433	1.87	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.12	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:6	34.08	2430	1.87	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.13	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:6	34.08	2420	1.86	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.15	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:6	34.08	2420	1.86	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.18	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:6	34.08	2431	1.86	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.18	14.96	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:6	34.08	2434	1.86	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.2	14.91	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:6	34.08	2435	1.86	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.21	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:7	34.08	2435	1.85	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.19	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:7	34.08	2436	1.85	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.15	14.88	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:26:7	34.08	2435	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.13	14.87	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:26:7	34.08	2454	1.85	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.15	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:7	34.08	2454	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.15	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:7	34.08	2427	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.13	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:8	34.08	2428	1.85	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.15	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:8	34.08	2411	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.18	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:8	34.08	2432	1.85	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.19	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:8	34.08	2432	1.85	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.19	Rich	1	14.6	-8.21	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:8	34.08	2432	1.85	13.46	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.23	14.87	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:8	34.08	2434	1.85	13.46	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.21	14.85	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:26:9	34.08	2437	1.85	13.48	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.21	14.84	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:9	34.08	2439	1.85	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.21	14.85	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:9	34.08	2439	1.85	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.21	14.86	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:9	34.08	2440	1.85	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.21	14.86	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:9	34.08	2439	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.21	14.87	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:9	34.08	2436	1.85	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.23	14.89	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:26:9	34.08	2435	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.24	14.91	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:0	34.08	2432	1.85	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.23	14.94	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:0	34.08	2446	1.85	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.24	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:0	34.08	2427	1.85	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.24	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:0	34.08	2429	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.23	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:0	34.08	2432	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.25	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:0	34.08	2437	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.26	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:1	34.08	2430	1.85	13.47	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.23	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:1	34.08	2441	1.85	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.21	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:1	34.08	2441	1.85	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.19	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:1	34.08	2440	1.85	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.2	15.03	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:1	34.08	2440	1.85	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.2	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:1	34.08	2437	1.85	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.2	15	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:1	34.08	2438	1.85	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.25	14.95	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:2	34.08	2439	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.29	14.91	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:2	34.08	2439	1.85	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.25	14.85	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:27:2	34.08	2442	1.85	13.51	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.26	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:2	34.08	2442	1.85	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.29	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:2	35.45	2441	1.84	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.28	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:2	35.45	2434	1.84	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.26	14.77	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:3	35.45	2440	1.84	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.29	14.77	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:3	35.45	2438	1.84	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.31	14.77	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:3	35.45	2432	1.84	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.29	14.79	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:3	35.45	2412	1.84	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.31	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:3	34.08	2412	1.84	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.31	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:3	34.08	2428	1.84	13.48	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.31	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:4	34.08	2430	1.84	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.29	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:4	34.08	2436	1.84	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.31	14.82	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:4	34.08	2438	1.84	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.31	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:4	34.08	2447	1.83	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.33	14.87	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:4	34.08	2445	1.83	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.33	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:4	34.08	2445	1.83	13.48	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.31	14.92	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:4	34.08	2446	1.83	13.47	96	197	Off Idle	70.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.27	14.94	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:5	34.08	2454	1.83	13.49	96	197	Off Idle	70.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.27	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:5	34.08	2444	1.83	13.5	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.25	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:5	34.08	2442	1.83	13.5	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.26	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:5	34.08	2435	1.83	13.49	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.29	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:5	34.08	2435	1.83	13.47	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.31	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:5	34.08	2436	1.83	13.46	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.66	Lean	1	14.6	-8.31	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:6	34.08	2434	1.83	13.46	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.69	Lean	1	14.6	-8.34	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:6	34.08	2434	1.83	13.48	96	197	Off Idle	69.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.34	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:6	34.08	2434	1.83	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.31	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:6	34.08	2441	1.83	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.29	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:6	34.08	2443	1.83	13.5	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.28	15.05	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:27:6	34.08	2443	1.84	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.24	15.04	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:6	34.08	2446	1.84	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.21	15.04	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:7	34.08	2446	1.84	13.48	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.21	15.02	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:7	34.08	2447	1.84	13.48	96	197	Off Idle	69.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.2	15.01	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:7	34.08	2448	1.84	13.48	96	197	Off Idle	70	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.23	15.02	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:7	34.08	2448	1.85	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.22	15.01	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:7	34.08	2449	1.85	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.21	14.99	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:7	34.08	2447	1.85	13.5	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.22	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:27:8	34.08	2444	1.85	13.51	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.21	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:27:8	34.08	2442	1.86	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.16	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:27:8	34.08	2418	1.86	13.49	96	197	Off Idle	70	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.15	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:27:8	34.08	2418	1.86	13.5	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.13	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:27:8	34.08	2439	1.86	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.12	14.89	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:8	34.08	2440	1.87	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.09	14.91	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:9	34.08	2439	1.87	13.5	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.05	14.92	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:27:9	34.08	2442	1.88	13.51	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8	14.94	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:27:9	34.08	2445	1.88	13.51	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.89	14.97	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:27:9	34.08	2444	1.89	13.52	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.83	14.99	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:27:9	34.08	2443	1.9	13.5	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	15.01	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:27:9	34.08	2445	1.91	13.5	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.05	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:27:9	34.08	2466	1.91	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:0	34.08	2452	1.92	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:0	34.08	2453	1.93	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:0	34.08	2453	1.93	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.51	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:0	34.08	2442	1.94	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.48	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:0	34.08	2449	1.95	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.43	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:0	34.08	2449	1.95	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.42	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:1	34.08	2446	1.96	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.41	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:1	34.08	2428	1.97	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.37	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:1	34.08	2439	1.97	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.37	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:28:1	34.08	2449	1.98	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.33	14.96	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:1	34.08	2452	1.99	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.3	14.88	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:28:1	34.08	2449	1.99	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.29	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:1	34.08	2448	1.99	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.26	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:2	34.08	2451	1.99	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.26	14.87	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:2	34.08	2453	2	13.49	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.27	14.89	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:2	34.08	2453	2	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.28	14.91	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:2	34.08	2492	2	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.28	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:2	34.08	2449	2	13.48	96	197	Off Idle	70	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.33	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:2	34.08	2450	2	13.49	96	197	Off Idle	70.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.34	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:3	34.08	2451	2	13.49	96	197	Off Idle	70	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.33	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:3	34.08	2444	2	13.48	96	197	Off Idle	69.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.3	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:3	34.08	2450	2	13.47	96	197	Off Idle	69.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.32	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:3	34.08	2452	2	13.47	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.27	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:3	34.08	2452	2	13.47	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.28	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:3	34.08	2456	2	13.47	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.69	Lean	1	14.6	-7.28	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:4	34.08	2477	2	13.48	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.27	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:4	34.08	2470	2	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.27	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:4	34.08	2466	2	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.27	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:4	34.08	2466	2	13.49	96	197	Off Idle	69.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.27	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:4	34.08	2468	2	13.49	96	197	Off Idle	69.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.26	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:4	34.08	2467	2	13.5	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.24	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:4	34.08	2466	2	13.5	96	197	Off Idle	69	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.22	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:5	34.08	2462	2	13.51	96	197	Off Idle	68.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.24	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:5	34.08	2458	2	13.51	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.23	14.73	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:28:5	34.08	2458	2	13.52	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.24	14.74	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:5	34.08	2454	2	13.5	96	197	Off Idle	69.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.27	14.76	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:5	34.08	2452	2	13.49	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.26	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:5	34.08	2448	2	13.48	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.26	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:6	34.08	2454	2	13.48	96	197	Off Idle	69.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.23	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:6	34.08	2448	2	13.49	96	197	Off Idle	69.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.23	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:6	34.08	2460	2	13.48	96	197	Off Idle	69.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.21	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:6	34.08	2461	2	13.46	96	197	Off Idle	69	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.24	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:6	34.08	2462	2	13.46	96	197	Off Idle	69	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.24	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:6	34.08	2463	2	13.47	96	197	Off Idle	69	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.22	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:6	34.08	2466	2	13.47	96	197	Off Idle	69	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.26	15.15	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:7	34.08	2468	2	13.47	96	197	Off Idle	69	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.27	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:7	34.08	2469	2	13.49	96	197	Off Idle	69	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.23	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:7	34.08	2466	2	13.48	96	197	Off Idle	68.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.25	15.15	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:7	34.08	2464	2	13.47	96	197	Off Idle	68.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.27	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:7	34.08	2464	2	13.46	96	197	Off Idle	68.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.27	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:7	34.08	2468	2	13.47	96	197	Off Idle	68.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.28	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:8	34.08	2486	2	13.45	96	197	Off Idle	68.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.28	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:8	34.08	2465	2	13.47	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.27	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:8	34.08	2465	2	13.48	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.25	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:8	34.08	2466	2	13.46	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.29	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:8	34.08	2464	2	13.46	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.27	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:8	34.08	2467	2	13.48	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.27	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:9	34.08	2466	2	13.46	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.28	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:9	34.08	2465	2	13.46	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.25	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:9	34.08	2465	2.01	13.48	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.22	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:9	34.08	2476	2.01	13.46	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.26	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:28:9	34.08	2470	2.01	13.46	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.22	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:28:9	34.08	2475	2.01	13.47	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.19	14.91	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:28:9	34.08	2475	2.01	13.47	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.22	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:0	34.08	2479	2.01	13.48	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.2	14.96	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:0	34.08	2484	2.01	13.5	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.22	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:29:0	34.08	2483	2.01	13.49	96	197	Off Idle	68.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.27	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:29:0	34.08	2480	2.01	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.26	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:0	34.08	2476	2.01	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.23	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:0	34.08	2472	2.01	13.47	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.27	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:1	34.08	2468	2.01	13.47	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.28	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:1	34.08	2468	2.01	13.47	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.31	15.13	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:1	34.08	2459	2.01	13.46	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.36	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:1	34.08	2465	2.01	13.46	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.36	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:1	34.08	2465	2.01	13.47	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.37	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:1	34.08	2468	2.01	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.37	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:1	34.08	2474	2.01	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.38	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:2	34.08	2478	2	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.37	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:29:2	34.08	2481	2	13.5	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.39	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:29:2	34.08	2486	2	13.49	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.4	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:2	34.08	2489	2	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.42	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:2	34.08	2489	1.99	13.48	96	197	Off Idle	68.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.47	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:2	34.08	2485	1.99	13.47	96	197	Off Idle	68	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.48	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:29:3	34.08	2482	1.99	13.47	96	197	Off Idle	67.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.49	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:3	34.08	2476	1.99	13.47	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.53	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:3	34.08	2468	1.98	13.47	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.54	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:3	34.08	2468	1.98	13.49	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.58	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:3	34.08	2468	1.98	13.48	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.62	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:3	34.08	2462	1.97	13.48	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.63	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:4	34.08	2476	1.97	13.49	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.66	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:4	34.08	2478	1.97	13.47	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.68	14.9	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:4	34.08	2482	1.96	13.48	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.7	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:4	34.08	2482	1.96	13.49	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.72	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:4	34.08	2493	1.95	13.49	96	197	Off Idle	67.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:4	34.08	2485	1.95	13.48	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.72	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:4	34.08	2480	1.95	13.48	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:5	34.08	2481	1.94	13.46	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:5	34.08	2472	1.94	13.47	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:5	34.08	2476	1.94	13.48	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:5	34.08	2477	1.94	13.49	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.8	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:5	34.08	2478	1.94	13.5	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.81	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:5	34.08	2478	1.94	13.49	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.79	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:6	34.08	2490	1.93	13.5	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.78	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:6	34.08	2483	1.93	13.49	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.79	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:6	34.08	2483	1.93	13.49	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.78	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:6	34.08	2483	1.93	13.48	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.75	14.94	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:6	34.08	2480	1.93	13.47	96	197	Off Idle	67.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.79	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:6	34.08	2492	1.93	13.49	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.83	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:6	34.08	2497	1.93	13.48	96	197	Off Idle	67.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.83	14.87	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:7	34.08	2496	1.93	13.48	96	197	Off Idle	67.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.86	14.86	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:7	34.08	2489	1.93	13.5	96	197	Off Idle	67.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.84	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:7	34.08	2482	1.93	13.49	96	197	Off Idle	67.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.84	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:7	34.08	2482	1.93	13.49	96	197	Off Idle	67.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.84	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:29:7	34.08	2478	1.93	13.5	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.82	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:7	34.08	2476	1.93	13.48	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.82	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:8	34.08	2479	1.93	13.47	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.83	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:8	34.08	2500	1.93	13.47	96	197	Off Idle	67.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.8	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:8	34.08	2500	1.93	13.47	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.81	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:8	34.08	2487	1.93	13.46	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.79	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:8	34.08	2487	1.93	13.47	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.78	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:8	34.08	2488	1.93	13.49	96	197	Off Idle	66.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:9	34.08	2482	1.93	13.48	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	15.12	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:9	34.08	2491	1.93	13.47	96	197	Off Idle	66.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:9	34.08	2493	1.93	13.48	96	197	Off Idle	67	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.83	15.17	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:9	34.08	2493	1.94	13.47	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.86	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:29:9	34.08	2502	1.94	13.47	96	197	Off Idle	67.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.86	15.12	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:9	34.08	2493	1.94	13.5	96	197	Off Idle	67.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.8	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:29:9	34.08	2493	1.94	13.5	96	197	Off Idle	67.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.82	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:30:0	34.08	2484	1.94	13.49	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.82	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:30:0	34.08	2492	1.94	13.49	96	197	Off Idle	67.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.81	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:30:0	34.08	2492	1.94	13.48	96	197	Off Idle	67.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.84	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:30:0	34.08	2492	1.94	13.46	96	197	Off Idle	67.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.82	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:30:0	34.08	2488	1.94	13.47	96	197	Off Idle	67.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.82	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:30:0	34.08	2491	1.93	13.49	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.85	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:30:1	34.08	2491	1.93	13.47	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.87	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:30:1	34.08	2493	1.93	13.49	96	197	Off Idle	67	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.86	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:30:1	34.08	2499	1.93	13.5	96	197	Off Idle	66.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.93	14.81	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:30:1	34.08	2499	1.92	13.47	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.98	14.82	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:1	34.08	2501	1.92	13.47	96	197	Off Idle	66.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8	14.85	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:1	34.08	2502	1.91	13.49	96	197	Off Idle	66.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.04	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:1	34.08	2498	1.91	13.46	96	197	Off Idle	66.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.09	14.91	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:2	34.08	2498	1.91	13.47	96	197	Off Idle	66.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.12	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:2	34.08	2498	1.91	13.48	96	197	Off Idle	66.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.16	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:2	35.45	2498	1.9	13.47	96	197	Off Idle	66.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.21	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:2	35.45	2496	1.9	13.47	96	197	Off Idle	66.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.24	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:2	35.45	2493	1.89	13.48	96	197	Off Idle	66.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.25	15.01	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:2	35.45	2493	1.89	13.47	96	197	Off Idle	66.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.29	15.03	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:30:3	35.45	2486	1.89	13.47	96	197	Off Idle	66.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.27	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:30:3	35.45	2486	1.88	13.48	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.29	15.05	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:30:3	35.45	2486	1.88	13.46	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.29	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:3	35.45	2486	1.87	13.47	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.29	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:3	35.45	2486	1.87	13.47	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.27	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:30:3	35.45	2490	1.86	13.47	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.31	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:30:4	35.45	2492	1.86	13.46	96	197	Off Idle	67	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.33	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:30:4	35.45	2492	1.86	13.46	96	197	Off Idle	67	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.31	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:4	35.45	2516	1.86	13.48	96	197	Off Idle	67	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.33	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:4	35.45	2495	1.86	13.48	96	197	Off Idle	66.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.33	14.75	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:4	35.45	2498	1.85	13.47	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.33	14.72	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:4	35.45	2498	1.85	13.49	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.38	14.69	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:4	35.45	2492	1.84	13.5	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.41	14.68	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:30:5	35.45	2501	1.83	13.49	96	197	Off Idle	66.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.49	14.69	1	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:30:5	35.45	2494	1.83	13.5	96	197	Off Idle	66.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.55	14.73	1	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:5	35.45	2508	1.82	13.49	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.69	14.75	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:5	35.45	2498	1.81	13.48	96	197	Off Idle	66.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.79	14.77	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:5	35.45	2482	1.8	13.47	96	197	Off Idle	67	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.82	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:5	35.45	2482	1.79	13.47	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.92	14.77	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:6	35.45	2483	1.79	13.47	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.93	14.78	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:6	35.45	2484	1.78	13.47	96	197	Off Idle	67	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.91	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:6	35.45	2484	1.77	13.49	96	197	Off Idle	66.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.91	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:6	35.45	2486	1.76	13.49	96	197	Off Idle	67	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.93	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:6	35.45	2466	1.75	13.5	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.94	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:6	35.45	2489	1.75	13.49	96	197	Off Idle	67.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.99	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:6	35.45	2492	1.74	13.46	96	197	Off Idle	66.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:7	35.45	2496	1.73	13.46	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.02	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:7	35.45	2520	1.72	13.48	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.04	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:30:7	35.45	2510	1.72	13.48	96	197	Off Idle	66.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.03	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:7	35.45	2501	1.72	13.48	96	197	Off Idle	66.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.05	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:7	35.45	2502	1.72	13.5	96	197	Off Idle	66.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.08	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:7	35.45	2478	1.71	13.49	96	197	Off Idle	66.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.17	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:8	35.45	2488	1.7	13.49	96	197	Off Idle	66.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.25	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:8	35.45	2497	1.68	13.48	96	197	Off Idle	66.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.4	14.94	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:30:8	35.45	2494	1.66	13.48	96	197	Full Load	66.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.51	14.91	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:11:30:8	35.45	2488	1.63	13.48	96	197	Idle	66.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.7	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:30:8	35.45	2481	1.6	13.5	96	197	Idle	66.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.81	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:30:8	35.45	2481	1.58	13.5	96	197	Idle	66.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.92	14.77	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:30:9	35.45	2470	1.55	13.51	96	197	Idle	66.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.03	14.74	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:30:9	35.45	2465	1.53	13.52	96	197	Idle	66.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.16	14.73	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:30:9	35.45	2452	1.51	13.52	96	197	Idle	66.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-10.24	14.74	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:30:9	35.45	2452	1.49	13.51	96	197	Idle	66.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-10.3	14.74	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:30:9	35.45	2436	1.45	13.52	96	197	Idle	67.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.36	14.75	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:30:9	35.45	2422	1.43	13.52	96	197	Idle	67.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.39	14.77	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:30:9	35.45	2382	1.39	13.52	96	197	Idle	67.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.41	14.78	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:0	29.99	2388	1.36	13.53	96	197	Idle	68.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.45	14.78	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:0	29.99	2410	1.33	13.53	96	197	Idle	68.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.45	14.79	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:0	24.54	2410	1.31	13.52	96	197	Idle	68.7	0	2	132	944 Turbo	0.74	Lean	1	14.6	-10.5	14.79	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:0	24.54	2424	1.29	13.5	96	197	Idle	68.6	0	2	132	944 Turbo	0.7	Lean	1	14.6	-10.55	14.8	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:0	19.09	2459	1.28	13.51	96	197	Idle	68.7	0	2	132	944 Turbo	0.67	Lean	1	14.6	-10.6	14.81	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:0	19.09	2482	1.26	13.5	96	197	Idle	68.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-10.66	14.84	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:1	19.09	2494	1.26	13.5	96	197	Idle	68.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-10.7	14.88	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:1	19.09	2491	1.26	13.51	96	197	Idle	68.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-10.71	14.89	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:1	19.09	2478	1.26	13.51	96	197	Idle	68.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-10.73	14.89	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:1	19.09	2478	1.26	13.5	96	197	Idle	68.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-10.76	14.91	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:1	19.09	2467	1.26	13.5	96	197	Idle	68.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.78	14.92	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:1	19.09	2481	1.25	13.49	96	197	Idle	68.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.79	14.92	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:1	19.09	2450	1.25	13.49	96	197	Idle	68.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.75	14.9	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:2	19.09	2418	1.25	13.5	96	197	Idle	67.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.74	14.88	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:2	19.09	2426	1.25	13.5	96	197	Idle	67.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.68	14.87	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:2	19.09	2435	1.25	13.5	96	197	Idle	67.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.64	14.84	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:2	19.09	2428	1.25	13.5	96	197	Idle	67.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.58	14.71	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:2	19.09	2444	1.25	13.48	96	197	Idle	67.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.55	14.67	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:2	19.09	2454	1.25	13.48	96	197	Idle	67.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.55	14.64	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:3	19.09	2462	1.25	13.48	96	197	Idle	67.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.55	14.63	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:3	19.09	2462	1.25	13.49	96	197	Idle	67.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.52	14.61	0.99	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:3	19.09	2488	1.25	13.5	96	197	Idle	67.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.53	14.61	0.99	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:3	17.72	2480	1.25	13.48	96	197	Idle	67.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.54	14.62	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:3	19.09	2481	1.25	13.47	96	197	Idle	67.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.53	14.65	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:3	19.09	2466	1.26	13.46	96	197	Idle	67.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.51	14.67	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:4	19.09	2466	1.26	13.47	96	197	Idle	67.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.5	14.68	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:4	19.09	2438	1.26	13.48	96	197	Idle	67.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.5	14.69	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:4	19.09	2447	1.26	13.48	96	197	Idle	67.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.5	14.73	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:4	19.09	2429	1.26	13.48	96	197	Idle	67.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.48	14.82	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:4	19.09	2443	1.26	13.5	96	197	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	14.95	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:4	19.09	2443	1.26	13.5	96	197	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	15.04	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:4	19.09	2430	1.26	13.5	96	197	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	15.13	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:5	19.09	2429	1.26	13.51	96	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	15.23	1.04	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:5	19.09	2428	1.26	13.5	96	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	15.45	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:5	19.09	2430	1.26	13.51	96	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	15.57	1.06	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:5	19.09	2434	1.26	13.5	96	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	15.74	1.07	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:5	19.09	2434	1.26	13.49	96	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	15.85	1.08	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:5	19.09	2434	1.26	13.5	96	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	16.03	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:6	19.09	2436	1.26	13.49	96	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	16.36	1.11	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:6	17.72	2435	1.26	13.49	96	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	16.85	1.15	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:6	17.72	2431	1.26	13.5	96	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	17.22	1.17	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:6	17.72	2427	1.26	13.5	96	197	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	17.66	1.2	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:6	17.72	2424	1.26	13.5	96	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	17.87	1.22	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:6	17.72	2414	1.26	13.46	96	197	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	18.3	1.25	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:6	17.72	2406	1.25	13.43	96	197	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	18.7	1.27	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:7	17.72	2406	1.25	13.41	96	197	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	19.27	1.31	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:7	17.72	2402	1.25	13.4	96	197	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	19.57	1.33	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:7	17.72	2406	1.25	13.4	96	197	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	19.82	1.35	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:7	17.72	2409	1.25	13.42	96	197	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.02	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:31:7	17.72	2410	1.25	13.43	96	197	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.13	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:7	17.72	2418	1.25	13.42	96	197	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:8	17.72	2420	1.25	13.41	96	197	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:8	17.72	2427	1.24	13.43	96	197	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:8	17.72	2430	1.24	13.43	96	197	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:8	17.72	2438	1.24	13.43	96	197	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:8	17.72	2425	1.24	13.45	96	197	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:8	17.72	2423	1.23	13.44	96	197	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:9	17.72	2417	1.23	13.44	96	197	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:9	17.72	2410	1.23	13.45	96	197	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:9	17.72	2407	1.23	13.44	96	197	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:9	17.72	2404	1.22	13.42	96	197	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:9	17.72	2383	1.22	13.42	96	197	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:9	17.72	2400	1.22	13.42	96	197	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:31:9	17.72	2399	1.21	13.42	96	197	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:0	17.72	2399	1.21	13.42	96	197	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:0	17.72	2400	1.21	13.45	96	197	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:0	17.72	2399	1.21	13.45	96	197	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:0	17.72	2399	1.21	13.45	96	197	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:0	17.72	2398	1.2	13.46	96	197	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:0	17.72	2395	1.2	13.46	96	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:1	17.72	2391	1.2	13.45	96	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:1	17.72	2390	1.2	13.43	96	197	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:1	17.72	2385	1.2	13.43	96	197	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:1	17.72	2380	1.2	13.43	96	197	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:1	17.72	2375	1.2	13.43	96	197	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:1	17.72	2374	1.2	13.42	96	197	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:1	17.72	2371	1.2	13.43	96	197	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:2	17.72	2362	1.2	13.43	96	197	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:2	17.72	2370	1.19	13.43	96	197	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.25	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:2	17.72	2389	1.19	13.44	96	197	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:2	17.72	2380	1.19	13.44	96	197	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:2	17.72	2370	1.19	13.42	96	197	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:2	17.72	2368	1.19	13.43	96	197	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:3	17.72	2366	1.19	13.44	96	197	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:3	17.72	2366	1.19	13.44	96	197	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:3	17.72	2360	1.18	13.43	96	197	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:3	17.72	2357	1.18	13.43	96	197	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:3	17.72	2352	1.18	13.44	96	197	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:3	17.72	2350	1.18	13.44	96	197	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:4	17.72	2344	1.17	13.42	96	197	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:4	17.72	2338	1.17	13.42	96	197	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:4	17.72	2335	1.17	13.42	96	197	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:4	17.72	2333	1.17	13.42	96	197	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:4	17.72	2318	1.16	13.43	96	197	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:4	17.72	2319	1.16	13.44	96	197	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:4	17.72	2318	1.16	13.44	96	197	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:5	17.72	2314	1.16	13.46	96	197	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:5	17.72	2309	1.15	13.45	96	197	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:5	17.72	2308	1.15	13.45	96	197	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:5	17.72	2300	1.15	13.44	96	197	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:5	17.72	2298	1.15	13.43	96	197	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:5	17.72	2296	1.14	13.43	96	197	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:6	17.72	2291	1.14	13.43	96	197	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:6	17.72	2287	1.14	13.44	96	197	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:6	17.72	2267	1.14	13.44	96	197	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:6	17.72	2274	1.13	13.43	96	197	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:6	17.72	2282	1.13	13.43	96	197	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:32:6	17.72	2296	1.13	13.44	96	197	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:6	17.72	2274	1.12	13.43	96	197	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:7	17.72	2272	1.12	13.42	96	197	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:7	17.72	2267	1.12	13.43	96	197	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:7	17.72	2265	1.12	13.44	96	197	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:7	17.72	2259	1.12	13.43	96	197	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:7	17.72	2242	1.12	13.44	96	197	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:7	17.72	2242	1.11	13.45	96	197	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:8	17.72	2236	1.11	13.46	96	197	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:8	17.72	2234	1.11	13.47	96	197	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:8	17.72	2217	1.11	13.47	96	197	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:8	17.72	2218	1.11	13.45	96	197	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:8	17.72	2218	1.1	13.45	96	197	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:8	17.72	2214	1.1	13.44	96	197	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:9	17.72	2208	1.1	13.43	96	197	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:9	17.72	2221	1.1	13.44	96	197	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:9	17.72	2199	1.1	13.43	96	197	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:9	17.72	2199	1.09	13.42	96	197	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:9	17.72	2186	1.09	13.41	96	197	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:9	17.72	2187	1.09	13.4	96	197	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:32:9	17.72	2184	1.09	13.41	96	197	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:0	17.72	2174	1.08	13.4	96	197	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:0	17.72	2174	1.08	13.42	96	197	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:0	17.72	2166	1.08	13.42	96	197	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:0	17.72	2161	1.07	13.4	96	197	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:0	17.72	2157	1.07	13.39	96	197	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.26	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:0	17.72	2155	1.07	13.39	96	197	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.26	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:1	17.72	2150	1.06	13.39	96	197	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.26	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:1	17.72	2147	1.06	13.4	96	197	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.26	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:1	17.72	2146	1.06	13.4	96	197	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:1	17.72	2140	1.05	13.41	96	197	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:1	17.72	2134	1.05	13.42	96	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:1	17.72	2132	1.05	13.41	96	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:1	17.72	2093	1.04	13.43	96	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:2	17.72	2121	1.04	13.44	96	197	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:2	17.72	2121	1.04	13.45	96	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:2	17.72	2119	1.03	13.46	96	197	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:2	17.72	2103	1.03	13.46	96	197	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:2	17.72	2097	1.03	13.46	96	197	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:2	17.72	2094	1.03	13.45	96	197	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:3	17.72	2082	1.02	13.45	96	197	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:3	17.72	2075	1.02	13.43	96	197	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:3	17.72	2075	1.02	13.42	96	197	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:3	17.72	2068	1.02	13.43	96	197	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:3	17.72	2060	1.01	13.43	96	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:3	17.72	2055	1.01	13.43	96	197	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:4	17.72	2053	1.01	13.43	96	197	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:4	17.72	2031	1.01	13.42	96	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:4	17.72	2040	1.01	13.41	96	197	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:4	17.72	2034	1.01	13.41	96	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:4	17.72	2034	1.01	13.41	96	197	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:4	17.72	2028	1.01	13.42	96	197	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:4	17.72	2023	1.01	13.42	96	197	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:5	17.72	2020	1.01	13.43	96	197	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:5	17.72	2020	1.01	13.44	96	197	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:5	17.72	2016	1.01	13.44	96	197	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:5	17.72	2009	1.01	13.42	96	197	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:5	17.72	2005	1.01	13.42	96	197	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:33:5	17.72	2002	1.01	13.42	96	197	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:6	17.72	1996	1.01	13.42	96	197	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:6	17.72	1988	1.01	13.42	96	197	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:6	17.72	1988	1.01	13.43	96	197	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:6	17.72	1977	1.01	13.43	96	197	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:6	17.72	1956	1.01	13.43	96	197	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:6	17.72	1956	1.01	13.43	96	197	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:6	17.72	1964	1.01	13.44	96	197	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:7	17.72	1956	1.01	13.45	96	197	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:7	17.72	1950	1	13.44	96	197	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:7	17.72	1945	1	13.43	96	197	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:7	17.72	1942	1	13.42	96	197	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:7	17.72	1933	1	13.41	96	197	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.26	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:7	17.72	1924	1	13.41	96	197	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.26	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:8	17.72	1920	1	13.43	96	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.26	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:8	17.72	1917	1	13.43	96	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.26	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:8	17.72	1907	1	13.44	96	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.26	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:8	17.72	1898	1	13.44	96	197	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.25	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:8	17.72	1895	1	13.43	96	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.25	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:8	17.72	1892	1	13.43	96	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:9	17.72	1885	1	13.43	96	197	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.25	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:9	17.72	1879	1	13.42	96	197	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.25	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:9	17.72	1876	1	13.43	96	197	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:9	17.72	1870	1	13.41	96	197	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:9	17.72	1870	1	13.42	96	197	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:9	17.72	1867	1.01	13.43	96	197	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:33:9	17.72	1849	1.01	13.43	96	197	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:0	17.72	1858	1.01	13.44	96	197	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:0	17.72	1862	1.01	13.43	96	197	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:0	17.72	1848	1.01	13.44	96	197	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:0	17.72	1829	1.01	13.45	96	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:0	17.72	1833	1.01	13.46	96	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:0	17.72	1829	1.01	13.44	96	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:1	17.72	1826	1.01	13.45	96	197	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:1	17.72	1821	1.01	13.43	96	197	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:1	17.72	1812	1.01	13.42	96	197	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:1	17.72	1806	1.01	13.42	96	197	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:1	17.72	1800	1.01	13.41	96	197	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.25	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:1	17.72	1797	1.01	13.4	96	197	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.25	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:1	17.72	1792	1.01	13.42	96	197	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.25	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:2	17.72	1783	1.01	13.41	96	197	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.25	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:2	17.72	1777	1.01	13.4	96	197	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:2	17.72	1777	1	13.41	96	197	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.24	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:2	17.72	1768	1	13.42	96	197	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:2	17.72	1758	1	13.41	96	197	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.24	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:2	17.72	1752	1	13.41	96	197	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:3	17.72	1752	1	13.42	96	197	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:3	17.72	1745	1	13.41	96	197	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.24	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:3	17.72	1739	1	13.4	96	197	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.24	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:3	17.72	1735	0.99	13.41	96	197	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:3	17.72	1727	0.99	13.41	96	197	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.24	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:3	17.72	1710	0.99	13.42	96	197	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.24	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:4	17.72	1690	0.99	13.43	96	197	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:4	17.72	1690	0.99	13.44	97	197	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:4	17.72	1654	0.99	13.43	97	197	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:4	17.72	1642	0.99	13.41	97	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:4	17.72	1623	0.99	13.41	96	197	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:4	17.72	1590	1	13.41	96	197	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:34:4	17.72	1564	1	13.41	96	197	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:5	17.72	1546	1	13.42	96	197	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:5	17.72	1520	1	13.41	96	197	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:5	17.72	1512	1	13.41	96	197	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:5	17.72	1498	1.01	13.41	96	197	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:5	17.72	1471	1.02	13.41	96	197	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:5	17.72	1444	1.02	13.41	96	197	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:6	17.72	1430	1.03	13.41	96	197	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.24	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:6	17.72	1410	1.04	13.4	96	197	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.42	20.24	1.38	4.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:6	19.09	1388	1.05	13.4	96	197	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.37	20.24	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:6	19.09	1354	1.06	13.4	96	197	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.3	20.24	1.38	4.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:6	19.09	1324	1.07	13.42	96	197	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.17	20.25	1.38	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:34:6	17.72	1315	1.08	13.41	96	197	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	20.25	1.38	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:34:6	17.72	1315	1.09	13.42	96	197	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	20.25	1.38	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:34:7	17.72	1284	1.1	13.41	96	197	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.86	20.24	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:34:7	16.36	1244	1.11	13.41	96	197	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.75	20.24	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:34:7	16.36	1224	1.12	13.41	96	197	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	20.24	1.38	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:34:7	16.36	1224	1.13	13.41	96	197	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.61	20.23	1.38	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:7	16.36	1210	1.14	13.42	96	197	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.52	20.23	1.38	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:7	16.36	1210	1.15	13.42	96	197	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.41	20.23	1.38	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:34:8	16.36	1211	1.15	13.42	96	197	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.29	20.23	1.38	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:34:8	16.36	1218	1.16	13.42	96	197	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.23	20.23	1.38	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:34:8	16.36	1218	1.16	13.41	96	197	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.09	20.23	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:34:8	16.36	1218	1.17	13.41	96	197	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.02	20.23	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:34:8	16.36	1218	1.17	13.43	96	197	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:34:8	16.36	1237	1.16	13.42	96	197	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8	20.24	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:34:9	16.36	1254	1.16	13.42	96	197	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.02	20.23	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:34:9	16.36	1242	1.16	13.42	96	197	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.05	20.24	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:34:9	14.99	1242	1.15	13.41	97	197	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.09	20.24	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:34:9	14.99	1262	1.15	13.41	97	197	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.11	20.24	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:34:9	14.99	1267	1.13	13.41	97	197	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.15	20.23	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:34:9	14.99	1267	1.13	13.41	96	197	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.21	20.24	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:11:34:9	14.99	1266	1.12	13.41	96	197	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.24	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:0	13.63	1258	1.11	13.4	96	197	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.26	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:0	13.63	1250	1.09	13.41	96	197	Idle	82.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.32	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:0	13.63	1265	1.07	13.41	96	197	Idle	84.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.35	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:0	13.63	1244	1.06	13.42	96	197	Idle	85.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.39	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:0	13.63	1244	1.05	13.41	96	197	Idle	86.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.46	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:0	13.63	1241	1.03	13.42	96	197	Idle	87	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.52	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:1	13.63	1228	1.02	13.42	96	197	Idle	87.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.56	20.25	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:1	14.99	1228	1.01	13.42	96	197	Idle	87.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.58	20.25	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:1	14.99	1219	1	13.41	96	197	Idle	88	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.61	20.24	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:1	14.99	1210	0.99	13.43	96	197	Idle	88.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.59	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:1	14.99	1190	0.98	13.43	96	197	Idle	88.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.6	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:1	14.99	1186	0.97	13.43	96	197	Idle	88.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.63	20.24	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:1	14.99	1162	0.96	13.44	96	196	Idle	88.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.58	20.24	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:2	14.99	1162	0.95	13.43	96	196	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.6	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:2	14.99	1162	0.95	13.43	96	196	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.58	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:2	14.99	1159	0.94	13.43	96	197	Idle	88.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.59	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:2	14.99	1142	0.94	13.45	96	197	Idle	88.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.64	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:2	14.99	1142	0.93	13.44	96	197	Idle	88.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.67	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:35:2	14.99	1137	0.93	13.43	96	197	Idle	88.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.67	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:3	14.99	1137	0.93	13.42	96	197	Idle	89	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.67	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:3	13.63	1117	0.92	13.42	96	197	Idle	89.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:3	13.63	1111	0.92	13.41	96	197	Idle	89.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:3	13.63	1111	0.92	13.43	96	197	Idle	89.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.54	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:3	13.63	1108	0.91	13.43	96	197	Idle	90.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.56	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:3	13.63	1108	0.91	13.41	96	197	Idle	90.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:35:4	13.63	1103	0.91	13.42	96	197	Idle	90.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.53	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:4	13.63	1098	0.9	13.43	96	197	Idle	91.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:4	13.63	1073	0.9	13.42	96	197	Idle	91.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.5	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:4	13.63	1073	0.9	13.43	96	197	Idle	91.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.5	20.24	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:4	13.63	1077	0.89	13.43	96	197	Idle	91.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.49	20.24	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:4	13.63	1076	0.89	13.41	96	197	Idle	92.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.48	20.24	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:4	13.63	1076	0.89	13.43	96	197	Idle	92.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.51	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:5	13.63	1064	0.88	13.42	96	197	Idle	92.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.49	20.15	1.37	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:5	12.27	1058	0.88	13.42	96	197	Idle	92.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	20.01	1.36	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:5	12.27	1052	0.88	13.44	96	197	Idle	92.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.48	19.84	1.35	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:5	12.27	1052	0.87	13.42	96	197	Idle	93	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.51	19.53	1.33	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:5	12.27	1054	0.87	13.42	96	197	Idle	93.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.48	19.29	1.31	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:5	12.27	1050	0.87	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.51	19.03	1.3	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:6	12.27	1051	0.86	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.51	18.62	1.27	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:6	12.27	1051	0.86	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.5	18.33	1.25	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:6	12.27	1040	0.86	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.49	18.03	1.23	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:6	12.27	1029	0.86	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.49	17.77	1.21	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:6	12.27	1029	0.85	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.49	17.57	1.2	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:6	12.27	1015	0.85	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.45	17.32	1.18	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:6	12.27	1016	0.85	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.47	17.19	1.17	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:7	12.27	1018	0.85	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	17.07	1.16	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:7	12.27	1018	0.84	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.43	16.98	1.16	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:7	12.27	1008	0.84	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.37	16.86	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:7	10.9	986	0.84	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.39	16.83	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:7	10.9	986	0.84	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.31	16.75	1.14	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:11:35:7	10.9	984	0.84	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.32	16.71	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:8	10.9	982	0.84	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.29	16.69	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:8	10.9	982	0.83	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.26	16.67	1.14	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:8	10.9	974	0.83	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.29	16.64	1.13	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:8	10.9	960	0.83	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.25	16.61	1.13	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:8	10.9	960	0.83	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.24	16.59	1.13	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:8	10.9	959	0.83	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.22	16.56	1.13	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:9	10.9	959	0.83	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.18	16.52	1.13	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:9	10.9	960	0.83	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.17	16.47	1.12	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:9	10.9	960	0.83	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.12	16.43	1.12	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:9	10.9	960	0.83	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.16	16.38	1.12	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:9	10.9	959	0.82	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.16	16.33	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:9	10.9	947	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.13	16.25	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:35:9	10.9	947	0.82	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.15	16.19	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:0	9.54	946	0.82	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.11	16.14	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:0	9.54	945	0.82	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.11	16.09	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:0	9.54	943	0.82	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.1	16.03	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:0	9.54	943	0.82	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.05	15.98	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:0	8.18	938	0.82	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.02	15.89	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:0	8.18	938	0.82	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.05	15.87	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:1	8.18	938	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.02	15.79	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:1	8.18	948	0.82	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.04	15.75	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:1	9.54	931	0.82	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.02	15.69	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:1	9.54	931	0.82	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8	15.65	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:1	9.54	931	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.99	15.6	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:1	9.54	928	0.82	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.96	15.56	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:1	9.54	931	0.82	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.97	15.52	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:2	9.54	931	0.82	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.95	15.49	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:2	9.54	928	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.97	15.46	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:2	9.54	926	0.82	13.43	96	197	Idle	93.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.93	15.45	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:2	9.54	934	0.82	13.42	96	197	Idle	93.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.95	15.42	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:2	8.18	934	0.82	13.42	96	197	Idle	93.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.91	15.41	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:2	8.18	936	0.82	13.42	96	197	Idle	93.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.93	15.38	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:36:3	8.18	939	0.82	13.43	96	197	Idle	93.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.87	15.36	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:3	8.18	939	0.82	13.41	96	197	Idle	93.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.9	15.34	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:3	8.18	943	0.82	13.41	96	197	Idle	93.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.85	15.32	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:3	8.18	941	0.82	13.42	96	197	Idle	93.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.89	15.32	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:3	8.18	941	0.82	13.43	96	197	Idle	93.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.87	15.3	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:3	8.18	941	0.81	13.41	96	197	Idle	93.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.89	15.28	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:4	8.18	930	0.81	13.43	96	197	Idle	93.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.9	15.27	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:4	8.18	923	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.91	15.26	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:4	8.18	923	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.88	15.27	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:4	8.18	923	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.92	15.26	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:4	9.54	923	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.88	15.27	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:4	9.54	912	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.89	15.26	1.04	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:4	9.54	912	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.83	15.26	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:5	9.54	912	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	15.25	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:5	9.54	921	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.85	15.24	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:5	9.54	919	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.89	15.23	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:5	9.54	919	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.84	15.22	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:5	9.54	922	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.89	15.22	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:5	9.54	925	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.86	15.21	1.04	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:6	9.54	927	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.86	15.18	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:6	9.54	927	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.17	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:6	8.18	926	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.83	15.16	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:6	8.18	926	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.82	15.14	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:6	8.18	926	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	15.12	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:6	8.18	927	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.83	15.11	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:6	8.18	927	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	15.1	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:7	8.18	925	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	15.08	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:7	8.18	925	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.06	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:7	8.18	922	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:7	8.18	920	0.81	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.8	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:7	8.18	910	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15.02	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:7	8.18	910	0.81	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.8	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:36:8	8.18	905	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.81	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:8	8.18	905	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.81	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:8	8.18	895	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.78	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:8	8.18	895	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.76	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:8	8.18	902	0.8	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.74	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:8	8.18	908	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.74	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:9	8.18	887	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.75	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:9	8.18	887	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.75	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:9	8.18	887	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.78	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:9	8.18	887	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.72	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:9	8.18	890	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:9	8.18	889	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:36:9	8.18	889	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.69	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:0	8.18	903	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.7	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:0	8.18	903	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.72	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:0	9.54	903	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:0	9.54	893	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:0	9.54	888	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:0	9.54	888	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:1	9.54	891	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:1	9.54	891	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:1	9.54	910	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:1	9.54	910	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:1	9.54	907	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:1	9.54	907	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:1	9.54	906	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:37:2	9.54	904	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:2	9.54	922	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:2	9.54	922	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:2	9.54	919	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:2	9.54	916	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:2	8.18	906	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:3	8.18	906	0.8	13.42	96	197	Idle	93.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.64	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:3	8.18	902	0.8	13.41	96	197	Idle	93.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.9	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:3	8.18	899	0.8	13.42	96	197	Idle	93.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:3	8.18	914	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:3	8.18	914	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.67	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:3	8.18	914	0.8	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.7	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:4	8.18	910	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:4	8.18	910	0.8	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.73	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:4	8.18	923	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.71	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:4	8.18	923	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.78	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:4	8.18	902	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.73	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:4	8.18	902	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.75	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:4	8.18	914	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.73	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:5	8.18	914	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.73	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:5	8.18	910	0.8	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.71	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:5	8.18	905	0.8	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.72	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:5	6.81	907	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.73	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:5	6.81	907	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.76	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:5	6.81	910	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.77	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:6	6.81	913	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.73	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:6	6.81	913	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.77	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:6	8.18	910	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.73	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:6	8.18	910	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.75	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:6	8.18	910	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.72	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:6	8.18	910	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.76	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:6	8.18	901	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:7	8.18	900	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:7	8.18	899	0.81	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.66	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:7	9.54	899	0.81	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:7	9.54	908	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:7	9.54	900	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.72	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:7	9.54	891	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:8	9.54	891	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:8	8.18	918	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:8	8.18	918	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:8	8.18	905	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:8	8.18	892	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:8	8.18	892	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:9	8.18	892	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:9	8.18	893	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:9	8.18	893	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:9	8.18	893	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:9	8.18	898	0.8	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:9	8.18	894	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:37:9	8.18	894	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:0	8.18	894	0.8	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:0	8.18	909	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:0	8.18	915	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:0	8.18	915	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:0	8.18	915	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:0	6.81	894	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:1	6.81	901	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:38:1	6.81	901	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:1	6.81	901	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:1	8.18	904	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:1	8.18	904	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:1	8.18	902	0.8	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:1	8.18	902	0.8	13.43	97	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:2	8.18	889	0.8	13.42	97	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:2	8.18	889	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.62	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:2	8.18	889	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.6	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:2	8.18	889	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.59	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:2	8.18	892	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.6	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:2	8.18	896	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.61	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:3	8.18	896	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.63	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:3	8.18	896	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.59	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:3	8.18	888	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.65	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:3	8.18	881	0.8	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.59	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:3	8.18	881	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.65	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:3	8.18	894	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.65	14.9	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:38:4	8.18	896	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.67	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:38:4	8.18	897	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.65	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:38:4	8.18	897	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.64	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:38:4	8.18	913	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.59	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:4	8.18	913	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.62	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:4	8.18	898	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.59	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:4	8.18	898	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:5	8.18	906	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.66	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:5	8.18	906	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:5	8.18	910	0.8	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.67	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:5	8.18	914	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:5	8.18	916	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.68	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:5	8.18	916	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.7	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:6	6.81	908	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:6	6.81	900	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.74	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:6	6.81	920	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:6	6.81	920	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:6	8.18	920	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	14.9	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:6	8.18	908	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.68	14.91	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:6	8.18	904	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:7	8.18	904	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:7	8.18	908	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.72	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:7	8.18	912	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:7	8.18	912	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:7	8.18	910	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.65	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:7	8.18	911	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:8	8.18	911	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.67	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:8	8.18	912	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.73	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:38:8	8.18	911	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.7	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:8	8.18	920	0.8	13.44	96	196	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.74	15.04	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:8	6.81	920	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.75	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:8	6.81	920	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.73	15.05	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:9	6.81	918	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.75	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:9	6.81	918	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.74	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:9	6.81	926	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:9	6.81	926	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:9	6.81	939	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15.06	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:9	6.81	911	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:38:9	8.18	911	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:0	8.18	911	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:39:0	8.18	922	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:0	8.18	922	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:0	8.18	920	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:0	8.18	917	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.05	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:0	8.18	924	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.04	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:1	8.18	924	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.03	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:1	8.18	910	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15.03	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:1	8.18	896	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:1	8.18	908	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:1	8.18	908	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:1	9.54	906	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.97	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:1	9.54	904	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:2	9.54	905	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:39:2	9.54	905	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:2	8.18	904	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:2	8.18	904	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:2	8.18	899	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.79	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:2	8.18	899	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.77	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:3	8.18	899	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.8	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:3	8.18	909	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.74	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:3	8.18	907	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.76	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:3	8.18	907	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.72	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:3	8.18	907	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:3	8.18	898	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.69	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:4	8.18	898	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.71	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:4	8.18	886	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.9	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:4	8.18	886	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	14.88	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:4	9.54	886	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:4	9.54	877	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:4	9.54	890	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:4	9.54	890	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:5	9.54	890	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.87	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:5	9.54	865	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:5	9.54	865	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:5	9.54	876	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:5	9.54	887	0.8	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:5	8.18	901	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:6	8.18	911	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:6	8.18	911	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:6	8.18	911	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:6	8.18	895	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:6	8.18	895	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:6	8.18	896	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:6	8.18	898	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:7	8.18	898	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:7	8.18	898	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.66	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:7	8.18	898	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:7	8.18	897	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.65	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:7	8.18	891	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.71	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:7	8.18	885	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:8	8.18	885	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.68	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:8	8.18	886	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.65	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:8	8.18	888	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.69	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:8	8.18	888	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.62	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:8	8.18	888	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.65	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:8	8.18	882	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.63	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:9	8.18	882	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.59	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:9	9.54	882	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.58	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:39:9	9.54	882	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.58	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:39:9	9.54	875	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.56	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:39:9	9.54	875	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.58	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:39:9	10.9	892	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.55	15.12	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:39:9	10.9	908	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.55	15.12	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:0	10.9	887	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.55	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:0	10.9	887	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.55	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:0	10.9	887	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.58	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:0	8.18	902	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.6	15.15	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:0	8.18	907	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.62	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:0	8.18	907	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.6	15.14	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:1	8.18	907	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.61	15.12	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:1	8.18	917	0.8	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.58	15.11	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:1	8.18	922	0.8	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.6	15.11	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:40:1	8.18	922	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:1	8.18	914	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:1	6.81	914	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.62	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:1	6.81	924	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.62	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:2	6.81	935	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.63	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:2	6.81	935	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.63	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:2	6.81	907	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.62	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:2	6.81	916	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.65	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:2	6.81	925	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.64	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:2	6.81	925	0.8	13.44	96	196	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.67	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:3	6.81	909	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.63	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:3	6.81	909	0.8	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.65	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:3	6.81	908	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.65	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:3	6.81	907	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:3	8.18	912	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:3	8.18	912	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:4	8.18	912	0.8	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:4	8.18	913	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:4	8.18	906	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:4	8.18	906	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:4	8.18	906	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:4	8.18	903	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:4	8.18	902	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:5	8.18	902	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:5	8.18	902	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:5	8.18	894	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:5	8.18	894	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:5	8.18	908	0.8	13.39	96	196	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:5	8.18	908	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	15	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:6	8.18	891	0.8	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:6	8.18	891	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:6	8.18	905	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:6	8.18	905	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:6	8.18	905	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:6	8.18	905	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:6	8.18	902	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:7	8.18	900	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:7	8.18	906	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:7	8.18	906	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:7	8.18	908	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:7	8.18	911	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:7	8.18	915	0.8	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:8	8.18	915	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:8	6.81	904	0.8	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:40:8	6.81	892	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:8	6.81	905	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:8	6.81	905	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:8	6.81	900	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.84	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:9	8.18	896	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:9	8.18	896	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:9	8.18	902	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:9	8.18	902	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:9	8.18	898	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:9	8.18	893	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:40:9	8.18	898	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:0	8.18	898	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:0	8.18	898	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:0	8.18	897	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:0	8.18	920	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:0	8.18	920	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:0	6.81	902	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:1	6.81	902	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:1	6.81	917	0.8	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:1	6.81	917	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:1	6.81	917	0.8	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:1	6.81	898	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:1	6.81	917	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:1	6.81	917	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:2	8.18	917	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:2	8.18	902	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:2	8.18	902	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:2	8.18	903	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:2	8.18	903	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:2	8.18	916	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:3	8.18	906	0.8	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	14.9	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:3	8.18	896	0.8	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:3	8.18	896	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:3	8.18	888	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:3	8.18	888	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:3	8.18	895	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:4	8.18	895	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:4	8.18	898	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:4	8.18	898	0.8	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:4	8.18	913	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:4	8.18	913	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.68	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:4	8.18	906	0.8	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.66	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:4	8.18	900	0.8	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.63	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:5	8.18	917	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.65	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:5	8.18	917	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.58	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:5	8.18	917	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.61	14.9	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:5	8.18	905	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.63	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:5	8.18	902	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.67	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:5	8.18	902	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.69	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:6	8.18	896	0.8	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.7	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:6	8.18	891	0.8	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.71	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:6	8.18	899	0.8	13.44	96	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.7	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:6	8.18	899	0.8	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.68	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:6	8.18	899	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.7	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:6	8.18	895	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.64	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:6	8.18	895	0.8	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.67	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:7	8.18	900	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.67	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:7	8.18	906	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.65	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:41:7	8.18	900	0.81	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:7	8.18	900	0.81	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:7	8.18	900	0.81	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:7	8.18	901	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.63	14.9	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:8	8.18	886	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.63	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:8	8.18	886	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:8	8.18	892	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:8	8.18	897	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.6	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:8	8.18	892	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.62	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:8	8.18	886	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.61	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:9	8.18	899	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.64	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:9	8.18	899	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.6	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:41:9	8.18	899	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:41:9	8.18	909	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.6	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:41:9	8.18	913	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.64	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:41:9	8.18	913	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.61	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:41:9	8.18	916	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.65	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:0	9.54	918	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.63	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:0	9.54	918	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.67	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:0	9.54	913	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.61	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:0	9.54	913	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.65	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:0	9.54	916	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.63	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:0	9.54	920	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.65	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:1	9.54	923	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.66	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:1	9.54	923	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.69	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:1	8.18	915	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.69	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:1	8.18	907	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.69	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:1	8.18	923	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.7	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:1	8.18	923	0.81	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.71	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:1	9.54	922	0.81	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:2	9.54	921	0.81	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:2	9.54	927	0.81	13.39	96	196	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.72	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:2	9.54	927	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:2	9.54	910	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.68	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:2	9.54	910	0.81	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.66	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:2	9.54	914	0.81	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.65	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:3	9.54	917	0.81	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.68	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:3	8.18	919	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.71	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:3	8.18	919	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.68	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:3	8.18	918	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.75	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:3	8.18	916	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.71	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:3	8.18	916	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.72	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:4	9.54	913	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.7	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:4	9.54	909	0.81	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.76	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:4	9.54	909	0.81	13.44	96	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.72	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:4	9.54	909	0.81	13.43	96	196	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.77	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:4	8.18	912	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.72	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:4	8.18	912	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.73	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:4	8.18	910	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:5	8.18	900	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.73	14.95	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:5	8.18	892	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.95	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:5	8.18	892	0.81	13.44	96	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	14.95	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:5	8.18	885	0.81	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:5	8.18	885	0.81	13.44	96	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:5	8.18	891	0.81	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:6	8.18	891	0.81	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:6	8.18	898	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.68	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:6	8.18	906	0.81	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.66	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:42:6	8.18	895	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:6	8.18	895	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.64	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:6	8.18	895	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:6	8.18	903	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.63	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:7	8.18	892	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.63	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:7	8.18	892	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.6	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:7	8.18	892	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.69	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:42:7	8.18	896	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.66	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:7	8.18	896	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.67	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:7	9.54	894	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.64	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:8	9.54	894	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.64	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:8	9.54	900	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.62	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:8	9.54	900	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.63	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:8	8.18	894	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:8	8.18	888	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:8	8.18	893	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:9	8.18	893	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:9	8.18	899	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:9	8.18	899	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:9	8.18	892	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.58	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:9	8.18	884	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:9	8.18	884	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.59	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:42:9	8.18	903	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.58	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:0	8.18	898	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:0	8.18	893	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.64	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:0	8.18	890	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:0	8.18	890	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.6	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:0	8.18	890	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.61	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:0	8.18	892	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.61	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:1	8.18	892	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.63	14.98	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:1	8.18	915	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.63	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:1	8.18	915	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.67	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:1	8.18	912	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.64	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:1	8.18	908	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.65	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:1	8.18	909	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.65	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:1	8.18	909	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.62	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:2	8.18	902	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.6	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:2	8.18	894	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.61	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:2	8.18	894	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.62	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:2	8.18	901	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:2	8.18	901	0.81	13.39	96	196	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:2	8.18	901	0.81	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.64	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:3	8.18	896	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:3	8.18	896	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.61	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:3	8.18	896	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.63	14.96	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:3	8.18	871	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.6	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:3	8.18	871	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.6	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:3	8.18	883	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.58	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:4	8.18	883	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.6	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:4	8.18	883	0.81	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:4	8.18	883	0.81	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:4	8.18	878	0.81	13.42	96	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:4	8.18	872	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:4	8.18	879	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.59	14.8	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:4	8.18	879	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.57	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:5	6.81	879	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.58	14.78	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:5	6.81	876	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.54	14.78	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:5	6.81	902	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.58	14.78	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:43:5	6.81	902	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.57	14.76	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:5	8.18	902	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.62	14.76	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:5	8.18	899	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.62	14.75	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:6	8.18	895	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.64	14.74	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:6	8.18	891	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.62	14.75	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:6	8.18	899	0.81	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.65	14.75	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:6	8.18	899	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.61	14.74	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:6	8.18	899	0.81	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.62	14.75	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:6	8.18	903	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.58	14.73	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:6	8.18	903	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.58	14.74	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:7	8.18	900	0.81	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.59	14.75	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:7	8.18	898	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.62	14.76	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:43:7	8.18	902	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.62	14.65	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:7	8.18	902	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.64	14.65	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:7	9.54	900	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.6	14.66	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:7	9.54	899	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.61	14.68	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:8	9.54	916	0.81	13.41	96	197	Idle	93.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.61	14.68	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:8	9.54	916	0.81	13.41	96	197	Idle	93.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.61	14.71	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:8	9.54	900	0.81	13.42	96	197	Idle	93.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.65	14.71	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:8	8.18	883	0.81	13.4	96	197	Idle	93.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.6	14.71	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:8	8.18	883	0.81	13.41	96	197	Idle	93.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.64	14.72	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:8	8.18	905	0.81	13.4	96	197	Idle	93.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.62	14.72	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:9	8.18	911	0.81	13.42	96	196	Idle	93.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.64	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:9	8.18	917	0.81	13.4	96	196	Idle	93.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.6	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:9	8.18	917	0.81	13.41	96	196	Idle	93.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.67	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:9	8.18	906	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.63	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:9	8.18	906	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:9	8.18	912	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.62	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:43:9	8.18	912	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:0	8.18	908	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:0	8.18	908	0.81	13.41	96	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:0	8.18	931	0.81	13.38	96	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:0	8.18	931	0.81	13.4	96	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:0	8.18	908	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:0	8.18	908	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:1	6.81	901	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:1	6.81	901	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:1	6.81	916	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:1	6.81	916	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.7	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:1	8.18	916	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:1	8.18	915	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:1	8.18	898	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:2	8.18	898	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:2	8.18	898	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:2	8.18	899	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:2	8.18	895	0.81	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:2	8.18	895	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.7	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:2	8.18	896	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.7	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:3	8.18	896	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:3	8.18	896	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:3	8.18	892	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:3	8.18	892	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:3	9.54	893	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.61	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:3	9.54	893	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.64	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:4	9.54	886	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.6	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:4	9.54	886	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	14.93	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:4	8.18	901	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.59	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:4	8.18	916	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:44:4	8.18	912	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.59	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:4	8.18	912	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:4	8.18	912	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:5	8.18	911	0.81	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:5	8.18	912	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:5	8.18	912	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:5	8.18	914	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.62	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:5	8.18	914	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.62	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:5	8.18	914	0.81	13.37	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:6	8.18	913	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:6	8.18	914	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:6	8.18	914	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:6	8.18	914	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:6	8.18	901	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:6	8.18	901	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:6	8.18	909	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.67	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:7	8.18	904	0.82	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.7	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:7	8.18	900	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.66	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:7	8.18	900	0.82	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.66	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:7	8.18	910	0.82	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:7	8.18	910	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.62	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:7	8.18	906	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.61	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:8	8.18	906	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:8	8.18	908	0.82	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.63	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:8	8.18	908	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:8	8.18	906	0.82	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:8	8.18	904	0.82	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:8	8.18	897	0.82	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.68	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:9	8.18	897	0.82	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:9	8.18	896	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:9	8.18	896	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.66	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:9	8.18	900	0.82	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:9	8.18	900	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:9	8.18	900	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:44:9	8.18	901	0.82	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:0	8.18	907	0.82	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:0	8.18	907	0.82	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.65	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:0	8.18	907	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:0	8.18	900	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.63	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:0	8.18	906	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.68	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:0	8.18	913	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.64	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:1	8.18	913	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:1	8.18	913	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:1	8.18	907	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:1	6.81	907	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:1	6.81	901	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.9	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:1	6.81	897	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	14.92	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:1	6.81	897	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	14.94	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:2	8.18	888	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.95	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:2	8.18	880	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.66	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:2	8.18	893	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.63	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:2	8.18	893	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.61	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:2	9.54	886	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:2	9.54	880	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.6	14.98	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:3	9.54	884	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.62	14.98	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:3	9.54	888	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.64	14.98	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:3	9.54	888	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.64	14.98	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:3	8.18	908	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.65	14.93	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:45:3	8.18	902	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.66	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:45:3	8.18	902	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.64	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:4	8.18	897	0.81	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.66	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:4	8.18	891	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.64	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:4	8.18	891	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.66	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:4	8.18	907	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.61	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:4	8.18	907	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.62	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:4	8.18	911	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.6	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:4	8.18	911	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:5	8.18	908	0.81	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.62	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:5	8.18	906	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:5	8.18	911	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:5	8.18	911	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:5	8.18	917	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:5	8.18	917	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:6	8.18	917	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:6	8.18	909	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:6	8.18	906	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:6	8.18	903	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:6	8.18	907	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:6	8.18	907	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:6	8.18	912	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:7	8.18	916	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:7	8.18	904	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:7	8.18	904	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:7	8.18	912	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:7	8.18	912	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:7	8.18	912	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:8	8.18	917	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:8	8.18	917	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:8	8.18	912	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:8	8.18	907	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.71	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:8	6.81	909	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.66	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:8	6.81	909	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.71	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:9	6.81	923	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:9	6.81	923	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:9	8.18	887	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:9	8.18	887	0.81	13.43	97	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:9	8.18	892	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:9	8.18	892	0.81	13.44	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.93	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:45:9	9.54	892	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.92	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:0	9.54	893	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:0	9.54	894	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:0	9.54	894	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:0	9.54	894	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:0	9.54	903	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:0	9.54	894	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:1	9.54	894	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.58	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:1	8.18	898	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.61	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:1	8.18	903	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.58	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:1	8.18	898	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.65	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:1	8.18	898	0.81	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.64	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:1	8.18	898	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.66	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:1	8.18	897	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.64	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:2	8.18	897	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.64	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:2	8.18	886	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.61	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:2	8.18	886	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.64	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:2	9.54	894	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.65	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:46:2	9.54	902	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.68	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:2	9.54	902	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.69	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:3	9.54	900	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.17	Rich	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:3	9.54	901	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:3	9.54	901	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:3	9.54	901	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.83	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:3	9.54	891	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.61	14.83	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:3	8.18	881	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:4	8.18	881	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:4	8.18	881	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:4	8.18	913	0.81	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:4	8.18	913	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:4	9.54	889	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:4	9.54	900	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:4	9.54	900	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:5	9.54	900	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:5	8.18	905	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:5	8.18	905	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:5	8.18	910	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:5	8.18	915	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:5	8.18	905	0.81	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:6	8.18	905	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:6	8.18	905	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:6	8.18	905	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:6	8.18	899	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:6	8.18	899	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.61	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:6	8.18	903	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:6	8.18	907	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.59	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:7	8.18	907	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.63	15.06	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:7	8.18	881	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.64	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:7	8.18	886	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.65	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:7	8.18	892	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.61	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:7	8.18	892	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.61	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:7	9.54	892	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.58	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:8	9.54	891	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.59	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:8	9.54	890	0.81	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.59	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:8	9.54	890	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.61	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:8	8.18	897	0.82	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.63	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:8	8.18	897	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.65	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:8	8.18	903	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:9	8.18	903	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:9	8.18	902	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:9	8.18	902	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:9	8.18	900	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:9	8.18	898	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.59	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:9	8.18	898	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.62	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:46:9	8.18	901	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.6	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:0	8.18	901	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:0	8.18	901	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.58	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:0	8.18	901	0.82	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:0	8.18	915	0.82	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:0	8.18	915	0.82	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:0	8.18	904	0.82	13.38	97	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:1	8.18	904	0.82	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:1	6.81	897	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.62	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:1	6.81	913	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:1	6.81	913	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.62	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:1	6.81	913	0.82	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:47:1	8.18	913	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:1	8.18	913	0.82	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:2	8.18	913	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:2	8.18	913	0.82	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:2	8.18	904	0.82	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:2	8.18	904	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:2	8.18	904	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:2	8.18	904	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:3	8.18	911	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:3	8.18	911	0.82	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:3	8.18	904	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:3	8.18	898	0.82	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.91	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:3	8.18	872	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.88	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:3	8.18	872	0.82	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:4	8.18	872	0.82	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:4	8.18	876	0.82	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.61	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:4	8.18	873	0.82	13.43	96	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.57	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:4	9.54	870	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.57	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:4	9.54	870	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.56	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:4	9.54	869	0.82	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.58	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:4	9.54	869	0.82	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.61	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:5	10.9	889	0.82	13.38	96	197	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.59	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:5	10.9	889	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.58	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:5	10.9	880	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.57	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:5	10.9	870	0.82	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.51	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:5	10.9	870	0.82	13.38	97	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.49	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:5	10.9	871	0.82	13.38	97	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.5	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:6	10.9	874	0.82	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.5	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:6	10.9	877	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.51	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:6	10.9	887	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.49	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:6	8.18	887	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.49	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:6	8.18	896	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.51	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:6	8.18	905	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.52	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:6	8.18	905	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.56	14.87	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:7	8.18	876	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.55	14.87	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:7	8.18	876	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.57	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:7	8.18	898	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.55	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:7	8.18	898	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:7	6.81	893	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.55	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:7	6.81	893	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.56	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:8	6.81	893	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.57	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:8	6.81	893	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.53	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:8	8.18	898	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.54	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:8	8.18	902	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.54	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:8	8.18	894	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.58	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:47:8	8.18	885	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.56	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:9	8.18	899	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.57	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:9	8.18	899	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.55	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:9	8.18	899	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.54	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:9	8.18	885	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.49	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:9	8.18	885	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.53	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:9	8.18	889	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.51	14.95	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:47:9	8.18	893	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.57	14.98	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:0	8.18	908	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.6	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:0	8.18	908	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:0	9.54	911	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:0	9.54	911	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:0	9.54	902	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.6	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:48:0	9.54	892	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.59	15.06	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:1	9.54	899	0.81	13.38	97	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.62	15.07	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:1	9.54	899	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.61	15.1	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:1	9.54	906	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.63	15.1	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:1	9.54	912	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.64	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:1	9.54	903	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:1	9.54	903	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:1	9.54	903	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:2	9.54	907	0.81	13.42	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:2	9.54	907	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:2	9.54	908	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.63	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:2	9.54	910	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:2	9.54	915	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:2	9.54	915	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:3	8.18	889	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.61	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:3	8.18	889	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:3	8.18	897	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.58	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:3	8.18	897	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.6	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:3	8.18	906	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.59	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:3	8.18	906	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:4	8.18	906	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:4	8.18	905	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:4	8.18	903	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.64	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:4	8.18	903	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.64	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:4	8.18	898	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.63	14.92	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:4	8.18	893	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.61	14.89	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:4	8.18	892	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.63	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:5	8.18	892	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.61	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:5	8.18	892	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.63	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:5	8.18	912	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.64	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:5	9.54	880	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.67	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:5	9.54	880	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.66	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:5	9.54	885	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.69	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:6	9.54	885	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.65	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:6	9.54	890	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.63	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:6	9.54	912	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.61	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:6	9.54	912	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.62	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:6	9.54	902	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:6	9.54	892	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:6	8.18	893	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:7	8.18	893	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:7	8.18	895	0.81	13.38	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:7	8.18	897	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:7	8.18	895	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.63	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:7	8.18	895	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.61	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:7	8.18	893	0.81	13.38	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.62	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:8	8.18	891	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.62	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:8	8.18	891	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:8	8.18	889	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.57	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:8	8.18	889	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.57	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:8	8.18	890	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.57	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:8	8.18	890	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.59	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:9	8.18	891	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.59	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:9	8.18	891	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.62	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:48:9	8.18	904	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.61	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:48:9	8.18	904	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.62	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:48:9	9.54	897	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.61	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:48:9	9.54	897	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.61	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:48:9	9.54	897	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.59	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:0	9.54	891	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.6	14.9	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:0	8.18	891	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.6	14.92	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:0	8.18	891	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.58	14.94	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:0	8.18	891	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.6	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:0	8.18	898	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.6	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:0	9.54	897	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.63	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:1	9.54	897	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.64	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:1	9.54	897	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.67	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:1	9.54	892	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.63	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:1	9.54	892	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.62	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:1	9.54	900	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.59	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:1	9.54	900	0.81	13.4	96	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.62	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:1	9.54	904	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.58	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:2	9.54	904	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.63	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:2	9.54	906	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.61	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:2	9.54	908	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.66	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:2	9.54	910	0.81	13.39	96	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.64	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:2	9.54	910	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.68	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:2	9.54	910	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.65	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:3	9.54	910	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:3	9.54	909	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.63	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:3	9.54	909	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:3	8.18	904	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:3	8.18	904	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:3	8.18	904	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:4	8.18	903	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:4	8.18	891	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:4	8.18	891	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:4	8.18	891	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:4	8.18	889	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:4	9.54	887	0.81	13.41	96	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:4	9.54	887	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:5	9.54	887	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.63	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:5	9.54	872	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.58	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:5	9.54	872	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.6	14.91	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:5	9.54	884	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.58	14.9	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:5	9.54	895	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.63	14.89	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:5	9.54	893	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.6	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:6	9.54	893	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.64	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:6	9.54	894	0.81	13.39	97	197	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.62	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:6	9.54	895	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.64	14.91	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:6	9.54	867	0.81	13.4	97	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.64	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:6	9.54	867	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.62	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:6	6.81	884	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.63	14.92	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:6	6.81	900	0.81	13.41	97	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.59	14.94	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:7	6.81	898	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	14.95	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:7	6.81	898	0.81	13.44	97	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.59	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:7	6.81	902	0.81	13.44	97	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.62	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:7	8.18	907	0.81	13.46	97	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.62	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:7	8.18	907	0.81	13.45	97	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.62	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:7	8.18	868	0.81	13.44	97	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.58	14.95	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:8	8.18	868	0.81	13.44	97	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.6	14.93	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:8	8.18	893	0.81	13.44	97	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.58	14.93	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:8	8.18	893	0.81	13.43	97	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.6	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:49:8	8.18	883	0.81	13.43	97	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.59	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:8	8.18	883	0.81	13.44	97	197	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.61	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:8	8.18	895	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.59	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:49:9	8.18	895	0.81	13.45	97	197	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.62	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:9	8.18	897	0.81	13.45	97	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.63	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:9	8.18	897	0.81	13.45	97	197	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.61	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:9	8.18	897	0.81	13.44	97	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:9	9.54	900	0.81	13.44	97	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:9	9.54	902	0.81	13.42	97	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:49:9	9.54	902	0.81	13.45	97	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:0	9.54	902	0.81	13.44	97	197	Full Load	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:0	9.54	894	0.81	13.45	97	197	Off Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.6	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:0	9.54	903	0.81	13.45	96	197	Off Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:0	9.54	903	0.83	13.45	96	197	Off Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.54	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:0	9.54	903	0.84	13.45	96	197	Off Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.48	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:0	9.54	896	0.86	13.43	97	197	Off Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.36	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:1	9.54	896	0.88	13.43	97	197	Off Idle	92.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.24	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:1	9.54	901	0.91	13.42	97	197	Off Idle	91.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.13	15	1.02	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:1	9.54	908	0.94	13.44	97	197	Off Idle	91.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.96	15.02	1.02	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:1	10.9	909	0.99	13.43	97	197	Off Idle	90.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.59	15.02	1.02	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:1	10.9	909	1.03	13.43	97	197	Off Idle	90	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.36	15.02	1.02	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:1	10.9	905	1.08	13.43	97	197	Off Idle	88.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.99	15.01	1.02	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:1	10.9	905	1.12	13.44	97	197	Off Idle	88.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.88	15.01	1.02	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:50:2	10.9	923	1.16	13.44	97	197	Off Idle	87.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.55	15	1.02	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:50:2	10.9	923	1.2	13.45	97	197	Off Idle	87.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.41	14.99	1.02	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:50:2	10.9	941	1.23	13.43	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.22	15	1.02	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:2	10.9	941	1.27	13.46	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.69	Lean	1	14.6	-5.09	15	1.02	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:2	20.45	1013	1.33	13.45	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-4.86	15.03	1.02	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:2	20.45	1013	1.36	13.48	97	197	Off Idle	85	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.78	15.04	1.02	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:3	20.45	1020	1.42	13.5	97	197	Off Idle	85.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.62	15.05	1.03	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:3	20.45	1074	1.45	13.5	97	197	Off Idle	85.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.57	15.04	1.02	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:3	20.45	1074	1.47	13.5	97	197	Off Idle	85.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.49	15.04	1.02	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:3	20.45	1140	1.49	13.49	97	197	Off Idle	85.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.53	15.02	1.02	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:11:50:3	20.45	1140	1.51	13.5	97	197	Off Idle	85.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.47	15.02	1.02	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:11:50:3	20.45	1180	1.53	13.48	97	197	Off Idle	85.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.46	15	1.02	4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:11:50:4	20.45	1211	1.54	13.46	97	197	Off Idle	85.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.47	14.96	1.02	4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:50:4	20.45	1242	1.54	13.46	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-4.49	14.92	1.02	4.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:50:4	21.81	1272	1.55	13.45	97	197	Off Idle	85.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.54	14.89	1.01	4.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:50:4	21.81	1312	1.56	13.45	97	197	Off Idle	85.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.61	14.85	1.01	4.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:50:4	21.81	1313	1.56	13.47	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.65	14.83	1.01	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:4	21.81	1313	1.56	13.45	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.72	14.83	1.01	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:4	21.81	1332	1.57	13.45	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.79	14.83	1.01	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:5	21.81	1338	1.57	13.45	97	197	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.84	14.84	1.01	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:5	21.81	1345	1.57	13.45	97	197	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.86	14.86	1.01	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:5	21.81	1348	1.58	13.44	96	197	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.89	14.89	1.01	4.2	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:5	21.81	1348	1.59	13.43	96	197	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.89	14.96	1.02	4.2	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:5	21.81	1347	1.6	13.45	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.88	14.97	1.02	4.2	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:50:5	21.81	1355	1.61	13.44	97	197	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.87	14.94	1.02	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:6	23.18	1349	1.62	13.45	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.89	Rich	1	14.6	-4.81	14.88	1.01	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:6	23.18	1349	1.64	13.45	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.89	Rich	1	14.6	-4.72	14.79	1.01	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:6	23.18	1329	1.65	13.44	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.89	Rich	1	14.6	-4.62	14.56	0.99	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:11:50:6	23.18	1311	1.67	13.43	97	197	Off Idle	86.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-4.51	14.47	0.99	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:11:50:6	23.18	1290	1.7	13.43	96	197	Off Idle	86.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-4.32	14.23	0.97	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:11:50:6	23.18	1268	1.72	13.43	96	197	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.15	13.85	0.94	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:50:6	23.18	1268	1.73	13.43	96	197	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.06	13.71	0.93	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:50:7	23.18	1268	1.75	13.43	97	197	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.82	13.24	0.9	4.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:50:7	23.18	1260	1.77	13.45	97	197	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.62	12.99	0.88	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:7	24.54	1206	1.78	13.45	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.52	12.78	0.87	4.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:7	24.54	1204	1.8	13.45	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.4	12.59	0.86	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:7	24.54	1204	1.81	13.44	97	197	Off Idle	86.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.12	12.44	0.85	4.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:50:7	25.9	1190	1.83	13.42	97	197	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.93	12.29	0.84	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:50:8	25.9	1160	1.83	13.44	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.82	12.25	0.83	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:50:8	25.9	1144	1.84	13.43	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.69	12.25	0.83	4.8	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:50:8	24.54	1146	1.86	13.46	97	197	Off Idle	86.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.57	12.28	0.84	4.7	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:50:8	24.54	1146	1.87	13.43	97	197	Off Idle	86.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.43	12.32	0.84	4.7	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:50:8	24.54	1127	1.87	13.42	97	197	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.42	12.39	0.84	4.7	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:50:8	24.54	1126	1.88	13.45	97	197	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.3	12.52	0.85	4.7	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:50:9	24.54	1124	1.88	13.41	97	197	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.23	12.58	0.86	4.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:50:9	24.54	1124	1.88	13.44	97	197	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.22	12.64	0.86	4.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:50:9	24.54	1109	1.87	13.42	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.1	12.9	0.88	4.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:50:9	24.54	1090	1.87	13.42	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.12	13.03	0.89	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:50:9	24.54	1090	1.86	13.44	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.02	13.17	0.9	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:50:9	24.54	1072	1.85	13.41	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2	13.34	0.91	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:50:9	24.54	1054	1.85	13.45	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.02	13.44	0.92	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:51:0	23.18	1036	1.84	13.43	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.94	13.54	0.92	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:51:0	23.18	1036	1.83	13.47	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.94	13.63	0.93	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:51:0	23.18	1028	1.82	13.45	97	197	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.82	13.71	0.93	4.9	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:51:0	23.18	986	1.81	13.46	97	197	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.85	13.74	0.94	4.9	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:51:0	23.18	986	1.8	13.45	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.79	13.73	0.94	4.8	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:51:0	23.18	986	1.79	13.46	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.8	13.71	0.93	4.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:51:1	23.18	982	1.78	13.44	97	197	Off Idle	85.8	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.69	13.69	0.93	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:1	23.18	966	1.77	13.44	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.73	13.64	0.93	4.7	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:1	23.18	966	1.76	13.45	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.63	13.56	0.92	4.7	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:1	23.18	953	1.75	13.45	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.67	13.48	0.92	4.7	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:1	23.18	940	1.74	13.44	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.55	13.37	0.91	4.8	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:1	21.81	922	1.74	13.44	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.6	13.25	0.9	4.9	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:1	21.81	922	1.72	13.45	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.54	13.08	0.89	4.9	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:2	21.81	922	1.72	13.45	97	197	Off Idle	85.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.55	12.97	0.88	5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:2	21.81	908	1.71	13.44	97	197	Off Idle	85.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.48	12.86	0.88	5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:2	21.81	899	1.7	13.42	97	197	Off Idle	85.3	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.48	12.7	0.87	5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:2	21.81	890	1.69	13.41	97	197	Off Idle	85.2	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.42	12.62	0.86	5.1	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:2	21.81	890	1.68	13.4	97	197	Off Idle	85.2	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.41	12.54	0.85	5.1	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:2	21.81	860	1.67	13.37	97	197	Off Idle	85.2	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.35	12.47	0.85	5.1	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:51:3	21.81	860	1.66	13.4	97	197	Off Idle	85	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.34	12.4	0.84	5.1	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:51:3	20.45	829	1.65	13.38	97	197	Off Idle	84.9	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.33	12.35	0.84	5.1	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:51:3	20.45	829	1.64	13.41	97	197	Off Idle	84.8	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.26	12.29	0.84	5.2	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:51:3	20.45	814	1.63	13.42	97	197	Off Idle	84.7	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.29	12.24	0.83	5.2	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:51:3	20.45	800	1.63	13.42	97	197	Off Idle	84.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.29	12.2	0.83	5.1	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:3	20.45	800	1.62	13.42	97	197	Off Idle	84.3	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.25	12.14	0.83	4.8	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:4	20.45	796	1.61	13.41	97	197	Off Idle	84.2	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.25	12.1	0.82	4.9	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:4	20.45	796	1.6	13.41	97	197	Off Idle	84	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.21	12.07	0.82	4.9	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:4	20.45	796	1.59	13.4	97	197	Off Idle	83.9	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.17	12.04	0.82	5	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:4	20.45	785	1.57	13.39	97	197	Off Idle	83.8	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.14	12.02	0.82	5.2	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:4	20.45	785	1.56	13.4	97	197	Off Idle	83.7	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.11	12	0.82	5.3	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:4	20.45	771	1.55	13.41	97	197	Off Idle	83.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.12	11.98	0.82	5.3	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:4	20.45	771	1.55	13.43	97	197	Off Idle	83.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.08	11.96	0.81	5.3	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:5	20.45	785	1.54	13.44	97	197	Off Idle	83.3	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.1	11.95	0.81	5.1	5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:5	20.45	785	1.52	13.47	97	197	Off Idle	83.1	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.11	11.93	0.81	4.9	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:51:5	20.45	785	1.52	13.46	97	197	Off Idle	83	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.1	11.91	0.81	4.7	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:51:5	20.45	832	1.51	13.47	97	197	Off Idle	82.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.13	11.88	0.81	4.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:51:5	20.45	854	1.51	13.47	97	197	Off Idle	83	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.17	11.86	0.81	4.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:51:5	20.45	877	1.51	13.48	97	197	Off Idle	83.1	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.15	11.85	0.81	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:6	20.45	877	1.51	13.49	97	197	Off Idle	83.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.23	11.82	0.81	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:6	17.72	914	1.51	13.5	97	197	Off Idle	83.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.23	11.79	0.8	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:6	17.72	959	1.51	13.49	97	197	Off Idle	83.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.31	11.77	0.8	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:6	17.72	959	1.52	13.49	97	197	Off Idle	83.8	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.32	11.74	0.8	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:6	17.72	959	1.52	13.5	97	197	Off Idle	83.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.37	11.72	0.8	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:6	17.72	992	1.53	13.47	97	197	Off Idle	84.1	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.4	11.71	0.8	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:6	17.72	1028	1.54	13.49	97	197	Off Idle	84.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.47	11.7	0.8	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:51:7	17.72	1028	1.55	13.46	97	197	Off Idle	84.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.46	11.69	0.8	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:7	19.09	1019	1.56	13.45	97	197	Off Idle	84.8	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.52	11.68	0.8	4.7	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:7	19.09	1010	1.57	13.47	97	197	Off Idle	85	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.5	11.67	0.79	4.7	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:7	19.09	1023	1.59	13.44	97	197	Off Idle	85.2	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.52	11.67	0.79	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:7	19.09	1023	1.6	13.47	97	197	Off Idle	85.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.54	11.66	0.79	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:7	19.09	1038	1.61	13.44	97	197	Off Idle	85.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.54	11.64	0.79	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:8	19.09	1038	1.63	13.47	97	197	Off Idle	85.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.56	11.63	0.79	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:8	19.09	1043	1.64	13.45	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.61	11.62	0.79	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:8	19.09	1048	1.66	13.48	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.62	11.6	0.79	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:8	19.09	1057	1.68	13.45	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.61	11.58	0.79	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:8	19.09	1077	1.69	13.48	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.6	11.56	0.79	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:8	19.09	1077	1.7	13.48	97	197	Off Idle	85.8	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.61	11.54	0.79	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:9	20.45	1091	1.71	13.46	97	197	Off Idle	85.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.59	11.52	0.78	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:9	20.45	1104	1.72	13.47	97	197	Off Idle	85.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.57	11.52	0.79	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:51:9	20.45	1118	1.73	13.47	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.57	11.52	0.78	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:9	20.45	1118	1.74	13.47	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.58	11.52	0.78	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:9	20.45	1125	1.75	13.47	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.53	11.53	0.79	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:51:9	20.45	1157	1.76	13.46	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.57	11.55	0.79	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:51:9	20.45	1157	1.76	13.48	97	197	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.55	11.57	0.79	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:52:0	20.45	1176	1.77	13.47	97	197	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.59	11.6	0.79	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:52:0	20.45	1197	1.78	13.47	97	197	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.67	11.63	0.79	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:52:0	20.45	1210	1.79	13.46	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.68	11.69	0.8	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:52:0	20.45	1210	1.79	13.47	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.7	11.72	0.8	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:52:0	20.45	1230	1.8	13.45	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.74	11.76	0.8	4.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:52:0	20.45	1230	1.81	13.46	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.76	11.81	0.8	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:52:1	20.45	1239	1.82	13.46	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.82	11.87	0.81	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:52:1	20.45	1253	1.82	13.43	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.86	11.93	0.81	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:52:1	20.45	1258	1.83	13.45	96	197	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.87	12	0.82	4.1	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:52:1	21.81	1295	1.83	13.44	96	197	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.88	12.07	0.82	4.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:52:1	21.81	1295	1.84	13.45	96	197	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.9	12.12	0.83	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:52:1	21.81	1280	1.85	13.45	97	197	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.91	12.17	0.83	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:52:1	21.81	1292	1.85	13.45	97	197	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.92	12.22	0.83	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:52:2	21.81	1292	1.86	13.43	97	197	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.92	12.28	0.84	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:52:2	21.81	1304	1.87	13.45	97	197	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.94	12.31	0.84	4.3	4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:2	21.81	1327	1.87	13.46	97	197	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.94	12.33	0.84	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:2	21.81	1333	1.88	13.46	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.96	12.36	0.84	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:2	21.81	1351	1.89	13.46	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2	12.38	0.84	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:2	21.81	1351	1.89	13.48	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.06	12.39	0.84	4.3	4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:3	21.81	1365	1.9	13.48	97	197	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.07	12.42	0.85	4.2	3.9	ON	28 Pin	OFF	Removed	Disabled
03:11:52:3	23.18	1380	1.91	13.46	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.13	12.44	0.85	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:11:52:3	23.18	1380	1.91	13.47	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.17	12.48	0.85	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:11:52:3	23.18	1403	1.92	13.47	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.2	12.51	0.85	4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:11:52:3	23.18	1433	1.92	13.46	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.17	12.55	0.86	4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:11:52:3	23.18	1457	1.93	13.45	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.25	12.59	0.86	4.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:52:4	24.54	1457	1.94	13.45	97	197	Off Idle	86.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.3	12.65	0.86	4.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:52:4	24.54	1437	1.94	13.46	97	197	Off Idle	86.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.33	12.69	0.86	4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:52:4	24.54	1475	1.95	13.44	97	197	Off Idle	86.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.31	12.74	0.87	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:52:4	24.54	1475	1.95	13.44	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.32	12.78	0.87	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:52:4	24.54	1480	1.96	13.45	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.36	12.81	0.87	4.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:52:4	25.9	1491	1.96	13.46	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.36	12.85	0.88	4.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:52:4	25.9	1498	1.97	13.46	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.34	12.9	0.88	4.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:52:5	25.9	1494	1.97	13.44	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.37	12.96	0.88	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:52:5	25.9	1500	1.98	13.43	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.4	12.99	0.88	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:52:5	25.9	1529	1.99	13.45	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.43	13.03	0.89	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:52:5	25.9	1529	1.99	13.47	97	197	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.44	13.07	0.89	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:52:5	25.9	1545	2	13.46	97	197	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.46	13.14	0.89	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:52:5	25.9	1545	2	13.47	97	197	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.47	13.19	0.9	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:52:6	25.9	1562	2.01	13.47	97	197	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.5	13.24	0.9	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:52:6	25.9	1576	2.01	13.45	97	197	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.5	13.3	0.91	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:52:6	25.9	1590	2.02	13.46	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.58	13.34	0.91	4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:11:52:6	25.9	1590	2.02	13.46	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.59	13.39	0.91	4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:11:52:6	25.9	1604	2.03	13.45	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.58	13.42	0.91	3.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:11:52:6	25.9	1624	2.03	13.44	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.65	13.5	0.92	3.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:11:52:6	25.9	1634	2.03	13.44	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.71	13.53	0.92	3.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:7	27.27	1633	2.04	13.44	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.72	13.58	0.93	3.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:7	27.27	1645	2.04	13.42	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.74	13.62	0.93	3.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:7	27.27	1672	2.05	13.43	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.76	13.63	0.93	3.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:7	27.27	1672	2.05	13.44	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.8	13.68	0.93	3.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:7	27.27	1673	2.06	13.44	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.84	13.74	0.94	3.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:7	27.27	1692	2.06	13.44	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.88	13.79	0.94	3.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:8	27.27	1698	2.06	13.44	97	197	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.9	13.83	0.94	3.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:8	27.27	1705	2.07	13.45	97	197	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.94	13.9	0.95	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:8	27.27	1721	2.07	13.44	97	197	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.96	13.94	0.95	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:8	27.27	1725	2.08	13.45	97	197	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.98	13.97	0.95	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:8	27.27	1729	2.08	13.45	97	197	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.02	14.01	0.95	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:8	27.27	1736	2.09	13.43	97	197	Off Idle	86.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.07	14.09	0.96	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:52:9	27.27	1744	2.09	13.42	97	197	Off Idle	86.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.09	14.13	0.96	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:9	27.27	1750	2.1	13.43	97	197	Off Idle	86.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.09	14.18	0.97	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:9	27.27	1750	2.1	13.42	97	197	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.11	14.24	0.97	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:9	28.63	1776	2.11	13.44	97	197	Off Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.16	14.29	0.97	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:9	28.63	1786	2.11	13.45	97	197	Off Idle	86.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.21	14.32	0.98	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:9	28.63	1786	2.12	13.46	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.2	14.37	0.98	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:52:9	28.63	1786	2.12	13.46	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.19	14.42	0.98	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:0	28.63	1796	2.13	13.46	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.19	14.46	0.98	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:0	28.63	1816	2.13	13.45	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.24	14.52	0.99	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:0	28.63	1837	2.13	13.44	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.27	14.55	0.99	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:0	28.63	1837	2.14	13.46	97	198	Off Idle	86.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.26	14.58	0.99	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:0	28.63	1848	2.14	13.47	97	198	Off Idle	86.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.31	14.63	1	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:0	28.63	1848	2.14	13.47	97	198	Off Idle	86.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.32	14.67	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:1	28.63	1864	2.15	13.46	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-3.38	14.72	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:1	28.63	1872	2.15	13.46	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-3.4	14.75	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:1	28.63	1874	2.16	13.46	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-3.46	14.78	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:1	28.63	1878	2.16	13.46	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.45	14.79	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:1	28.63	1891	2.16	13.48	97	197	Off Idle	86.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.5	14.8	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:1	28.63	1898	2.17	13.47	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.51	14.83	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:1	28.63	1916	2.17	13.46	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.48	14.9	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:2	28.63	1916	2.17	13.47	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.51	14.93	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:2	28.63	1944	2.17	13.47	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.56	14.99	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:2	28.63	1943	2.18	13.46	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.53	15.02	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:2	28.63	1956	2.18	13.45	97	197	Off Idle	86.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.55	15.06	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:2	28.63	1956	2.18	13.44	97	197	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.54	15.1	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:2	28.63	1973	2.18	13.42	97	197	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.54	15.17	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:3	29.99	1968	2.18	13.41	97	197	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.57	15.24	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:3	29.99	1968	2.19	13.41	97	197	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.68	15.28	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:3	29.99	1973	2.19	13.42	97	197	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.7	15.32	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:3	29.99	1991	2.19	13.43	97	198	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.78	15.33	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:53:3	29.99	2000	2.19	13.43	97	198	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.83	15.35	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:3	29.99	2004	2.2	13.44	97	198	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.86	15.34	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:4	29.99	2019	2.2	13.44	97	197	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.87	15.35	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:4	29.99	2024	2.2	13.42	97	197	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.84	15.35	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:4	29.99	2034	2.2	13.41	97	197	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.82	15.34	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:4	29.99	2031	2.2	13.41	97	197	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.79	15.32	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:4	29.99	2034	2.21	13.41	97	197	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.77	15.3	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:4	29.99	2045	2.21	13.41	97	197	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.8	15.26	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:4	29.99	2045	2.21	13.41	97	197	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.78	15.22	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:5	29.99	2058	2.21	13.41	97	197	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.79	15.19	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:53:5	29.99	2073	2.21	13.42	97	197	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.78	15.19	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:5	29.99	2073	2.21	13.42	97	197	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.78	15.18	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:5	29.99	2086	2.22	13.44	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.79	15.16	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:5	29.99	2119	2.22	13.45	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.84	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:5	29.99	2115	2.22	13.46	97	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.88	15.12	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:6	29.99	2118	2.22	13.46	97	197	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.94	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:6	29.99	2128	2.22	13.45	97	198	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.95	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:6	29.99	2134	2.22	13.45	97	198	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.97	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:6	29.99	2154	2.22	13.43	97	198	Off Idle	85.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.98	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:6	31.36	2154	2.23	13.41	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:6	31.36	2144	2.23	13.4	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.03	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:6	31.36	2150	2.23	13.41	97	197	Off Idle	85.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.01	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:7	31.36	2151	2.23	13.41	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.04	15.14	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:7	31.36	2152	2.23	13.42	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.03	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:7	31.36	2162	2.23	13.44	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.07	15.17	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:7	31.36	2188	2.23	13.44	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.05	15.18	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:7	29.99	2175	2.24	13.44	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.1	15.17	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:53:7	29.99	2190	2.24	13.43	97	197	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.14	15.15	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:8	29.99	2200	2.24	13.41	97	197	Off Idle	85.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.16	15.14	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:8	29.99	2200	2.24	13.41	97	197	Off Idle	85.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.2	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:8	29.99	2212	2.24	13.41	97	197	Off Idle	85.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.21	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:8	29.99	2226	2.24	13.41	97	197	Off Idle	85	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.2	15.11	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:8	29.99	2258	2.24	13.43	97	197	Off Idle	84.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.2	15.09	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:8	31.36	2252	2.25	13.45	97	197	Off Idle	84.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.19	15.1	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:9	31.36	2258	2.25	13.47	97	197	Off Idle	84	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.22	15.09	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:9	31.36	2265	2.25	13.47	97	197	Off Idle	83.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.26	15.1	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:53:9	31.36	2265	2.25	13.46	97	197	Off Idle	83.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.32	15.1	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:53:9	31.36	2279	2.25	13.43	97	197	Off Idle	82.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.38	15.11	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:53:9	31.36	2280	2.26	13.43	97	197	Off Idle	82.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.33	15.12	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:53:9	31.36	2287	2.26	13.45	97	197	Off Idle	81.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.31	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:53:9	32.72	2287	2.26	13.46	97	197	Off Idle	81.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.32	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:0	32.72	2294	2.27	13.48	97	197	Off Idle	80.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.33	15.16	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:54:0	32.72	2294	2.27	13.5	97	197	Off Idle	80.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.3	15.13	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:54:0	32.72	2298	2.27	13.49	97	197	Off Idle	79.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.28	15.11	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:54:0	32.72	2302	2.28	13.47	97	198	Off Idle	79.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.27	15.08	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:54:0	32.72	2304	2.29	13.47	97	198	Off Idle	79.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.14	15.04	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:54:0	31.36	2336	2.3	13.45	97	197	Off Idle	78.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.04	15	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:1	31.36	2328	2.32	13.45	97	197	Off Idle	78.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.87	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:1	31.36	2338	2.33	13.46	97	197	Off Idle	78.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.72	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:11:54:1	31.36	2358	2.34	13.47	97	198	Off Idle	77.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-3.61	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:54:1	31.36	2358	2.36	13.45	97	198	Off Idle	77.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.5	14.91	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:54:1	31.36	2402	2.38	13.46	97	198	Off Idle	76.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.41	14.95	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:54:1	31.36	2394	2.4	13.46	97	198	Off Idle	76.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.37	15.03	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:1	31.36	2398	2.41	13.48	97	198	Off Idle	76.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.31	15.09	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:2	31.36	2421	2.43	13.49	97	198	Off Idle	75.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.18	15.17	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:2	31.36	2434	2.45	13.47	97	198	Off Idle	74.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.08	15.25	1.04	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:2	32.72	2480	2.47	13.48	97	198	Off Idle	74.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-3.05	15.33	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:2	32.72	2456	2.49	13.44	97	198	Off Idle	73.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-3	15.37	1.05	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:2	32.72	2467	2.51	13.43	97	198	Off Idle	72.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3	15.39	1.05	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:2	31.36	2454	2.52	13.45	97	198	Off Idle	71.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-2.94	15.38	1.05	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:54:3	31.36	2466	2.54	13.45	97	198	Off Idle	71.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-2.84	15.37	1.05	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:54:3	31.36	2482	2.56	13.45	97	198	Off Idle	70.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-2.81	15.34	1.05	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:11:54:3	31.36	2484	2.57	13.46	97	198	Off Idle	69.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.74	15.36	1.05	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:3	31.36	2484	2.58	13.45	97	198	Off Idle	69.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.71	15.29	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:3	32.72	2502	2.58	13.43	97	198	Off Idle	68.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.67	15.27	1.04	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:3	32.72	2498	2.59	13.43	97	198	Off Idle	68.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.59	15.17	1.03	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:4	32.72	2502	2.59	13.44	97	198	Off Idle	67.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.59	15.17	1.03	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:4	32.72	2513	2.59	13.43	97	198	Off Idle	67.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.6	14.98	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:54:4	32.72	2526	2.6	13.44	97	198	Off Idle	67.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.6	14.86	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:4	32.72	2536	2.61	13.47	97	198	Off Idle	66.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.6	14.66	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:4	32.72	2551	2.61	13.48	97	198	Off Idle	66.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.59	14.49	0.99	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:4	32.72	2556	2.63	13.5	97	198	Off Idle	66.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.58	14.3	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:4	32.72	2588	2.64	13.5	97	198	Off Idle	66.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.48	14.15	0.96	3.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:5	32.72	2593	2.65	13.5	97	198	Off Idle	65.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.44	14.16	0.96	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:5	32.72	2598	2.66	13.49	97	198	Off Idle	65.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.39	14.17	0.97	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:5	32.72	2617	2.66	13.47	97	198	Off Idle	64.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.35	14.23	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:5	32.72	2634	2.67	13.46	97	198	Off Idle	64.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.3	14.3	0.97	3.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:5	32.72	2679	2.67	13.46	97	198	Off Idle	63.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.29	14.34	0.98	3.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:5	32.72	2679	2.68	13.47	97	198	Off Idle	62.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.28	14.36	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:6	32.72	2677	2.69	13.47	97	198	Off Idle	62.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.25	14.36	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:6	32.72	2689	2.7	13.48	97	198	Off Idle	61.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.28	14.37	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:6	32.72	2700	2.71	13.47	97	198	Off Idle	60.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.27	14.35	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:11:54:6	32.72	2727	2.72	13.47	97	198	Off Idle	59.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.27	14.34	0.98	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:54:6	32.72	2712	2.73	13.47	97	198	Off Idle	59.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.22	14.32	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:54:6	32.72	2719	2.73	13.47	97	198	Off Idle	58.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.14	14.31	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:54:6	32.72	2725	2.74	13.44	97	198	Off Idle	57.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.05	14.31	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:54:7	32.72	2729	2.75	13.45	97	198	Off Idle	56.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.96	14.31	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:54:7	32.72	2750	2.76	13.44	97	198	Off Idle	56.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.93	14.33	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:54:7	32.72	2751	2.77	13.44	97	198	Off Idle	55.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.91	14.33	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:54:7	32.72	2758	2.77	13.45	97	198	Off Idle	55.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.88	14.34	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:54:7	32.72	2758	2.78	13.44	97	198	Off Idle	55	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.82	14.35	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:54:7	32.72	2778	2.79	13.45	97	198	Off Idle	54.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.75	14.36	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:54:8	32.72	2790	2.79	13.46	97	198	Off Idle	53.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.73	14.36	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:8	32.72	2806	2.81	13.46	97	198	Off Idle	53.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.54	14.38	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:54:8	32.72	2820	2.82	13.46	97	198	Off Idle	53.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.45	14.39	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:54:8	32.72	2824	2.83	13.45	97	198	Off Idle	52.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.39	14.4	0.98	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:54:8	32.72	2854	2.84	13.44	97	198	Off Idle	52.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.22	14.4	0.98	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:54:8	32.72	2876	2.86	13.45	97	198	Off Idle	52.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.12	14.42	0.98	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:54:9	32.72	2888	2.87	13.45	97	198	Off Idle	51.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.99	14.42	0.98	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:54:9	32.72	2913	2.89	13.45	97	198	Off Idle	51.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.94	14.44	0.98	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:54:9	32.72	2935	2.9	13.46	97	197	Off Idle	50.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.77	14.47	0.99	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:54:9	32.72	2935	2.91	13.45	97	197	Off Idle	49.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.73	14.5	0.99	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:54:9	32.72	2958	2.92	13.47	97	197	Off Idle	48.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.75	14.53	0.99	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:54:9	32.72	2974	2.94	13.46	97	198	Off Idle	47.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.74	14.56	0.99	3.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:54:9	32.72	2992	2.95	13.46	97	198	Off Idle	46.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.74	14.58	0.99	3.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:0	32.72	3072	2.97	13.46	97	197	Off Idle	46	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.77	14.59	0.99	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:0	32.72	3012	2.98	13.45	97	197	Off Idle	44.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.79	14.6	0.99	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:0	32.72	3026	2.99	13.47	97	197	Off Idle	44.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.71	14.59	0.99	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:0	32.72	3030	3.01	13.45	97	198	Off Idle	43.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.73	14.57	0.99	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:0	32.72	3039	3.02	13.45	97	198	Off Idle	42.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.61	14.55	0.99	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:0	32.72	3049	3.03	13.47	97	198	Off Idle	42.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.6	14.52	0.99	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:1	32.72	3061	3.03	13.46	97	198	Off Idle	42.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.6	14.49	0.99	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:1	32.72	3065	3.04	13.47	97	198	Off Idle	42	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.62	14.46	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:1	32.72	3071	3.05	13.46	97	198	Off Idle	41.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.6	14.44	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:1	32.72	3092	3.05	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.55	14.42	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:1	32.72	3092	3.06	13.47	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.52	14.41	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:1	32.72	3110	3.07	13.47	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.45	14.4	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:1	32.72	3126	3.07	13.47	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.46	14.41	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:2	32.72	3144	3.08	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.38	14.39	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:2	32.72	3144	3.09	13.47	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.39	14.39	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:2	32.72	3164	3.09	13.46	97	197	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.35	14.38	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:2	32.72	3192	3.1	13.46	97	197	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.27	14.39	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:2	32.72	3204	3.1	13.44	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.33	14.39	0.98	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:2	32.72	3234	3.11	13.44	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.27	14.4	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:3	32.72	3223	3.11	13.44	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.35	14.4	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:3	32.72	3249	3.12	13.44	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.29	14.42	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:55:3	32.72	3265	3.12	13.44	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.31	14.43	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:3	32.72	3262	3.13	13.47	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.29	14.43	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:3	32.72	3284	3.13	13.47	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.32	14.44	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:3	32.72	3300	3.14	13.46	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.3	14.46	0.99	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:4	32.72	3314	3.14	13.48	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.32	14.48	0.99	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:4	32.72	3320	3.15	13.46	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.3	14.51	0.99	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:4	32.72	3336	3.15	13.46	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.22	14.52	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:4	32.72	3349	3.15	13.47	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.22	14.54	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:4	32.72	3351	3.16	13.45	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.08	14.57	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:4	32.72	3361	3.16	13.45	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.11	14.57	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:4	32.72	3374	3.17	13.45	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.06	14.58	0.99	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:5	32.72	3379	3.17	13.44	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.1	14.58	0.99	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:5	32.72	3396	3.18	13.44	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.05	14.59	0.99	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:5	32.72	3402	3.18	13.44	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.1	14.61	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:5	32.72	3434	3.19	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.06	14.64	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:5	32.72	3440	3.19	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.02	14.65	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:5	32.72	3440	3.19	13.45	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.03	14.66	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:6	32.72	3454	3.2	13.47	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	0.03	14.69	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:11:55:6	32.72	3506	3.2	13.46	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	0.11	14.68	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:11:55:6	32.72	3490	3.21	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	0.06	14.71	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:11:55:6	32.72	3492	3.21	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	0.11	14.77	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:11:55:6	32.72	3520	3.21	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	0.17	14.82	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:11:55:6	32.72	3534	3.22	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	0.1	14.86	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:11:55:6	32.72	3562	3.22	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	0.11	14.93	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:7	32.72	3566	3.23	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	0.14	15	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:7	32.72	3586	3.23	13.49	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	0.08	15.05	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:7	32.72	3594	3.24	13.48	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	0.26	15.04	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:7	32.72	3609	3.24	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	0.3	15.05	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:7	32.72	3609	3.24	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	0.18	15.01	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:7	32.72	3621	3.25	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	0.16	14.96	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:8	32.72	3629	3.25	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.08	14.91	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:8	32.72	3632	3.25	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.02	14.88	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:11:55:8	34.08	3650	3.25	13.48	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.04	14.81	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:8	34.08	3667	3.26	13.49	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.11	14.74	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:8	34.08	3664	3.26	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.13	14.7	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:8	34.08	3677	3.26	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.13	14.67	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:9	34.08	3685	3.26	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Lean	1	14.6	0.13	14.71	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:9	34.08	3690	3.27	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	0.13	14.74	1	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:55:9	34.08	3700	3.27	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	0.05	14.77	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:9	34.08	3700	3.27	13.49	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	0.01	14.77	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:9	32.72	3718	3.27	13.48	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	0.12	14.78	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:9	32.72	3753	3.27	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	0.12	14.84	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:55:9	32.72	3766	3.27	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	0.01	14.87	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:56:0	32.72	3772	3.27	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	0	14.9	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:56:0	32.72	3805	3.27	13.45	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-0.02	14.95	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:56:0	32.72	3838	3.28	13.45	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-0.08	14.96	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:11:56:0	32.72	3840	3.28	13.49	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-0.18	15.02	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:56:0	32.72	3858	3.28	13.48	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-0.16	15.08	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:56:0	32.72	3859	3.28	13.48	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.7	-0.15	15.11	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:56:1	34.08	3871	3.28	13.47	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-0.25	15.13	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:56:1	34.08	3880	3.28	13.44	97	197	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.27	15.1	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:56:1	34.08	3884	3.28	13.44	97	197	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.34	15.06	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:11:56:1	34.08	3889	3.28	13.44	97	197	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.4	15.02	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:56:1	34.08	3930	3.29	13.43	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.52	15.02	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:56:1	34.08	3906	3.29	13.46	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.58	14.97	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:56:1	34.08	3908	3.29	13.49	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.6	14.9	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:56:2	34.08	3924	3.29	13.48	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-0.74	14.87	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:11:56:2	34.08	3927	3.28	13.48	97	198	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-0.76	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:56:2	34.08	3953	3.28	13.48	97	197	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-0.74	14.82	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:56:2	34.08	3950	3.28	13.46	97	197	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-0.86	14.82	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:56:2	34.08	3955	3.28	13.48	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-0.85	14.84	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:56:2	34.08	3961	3.28	13.46	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-0.9	14.88	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:11:56:3	35.45	4000	3.28	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-0.98	14.92	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:56:3	35.45	4012	3.28	13.46	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-1.02	14.93	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:56:3	35.45	4038	3.27	13.45	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-1.16	15.02	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:56:3	35.45	4044	3.27	13.45	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-1.26	15.04	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:56:3	35.45	4049	3.27	13.45	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-1.4	15.06	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:11:56:3	35.45	4066	3.26	13.44	97	197	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-1.44	15.1	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:4	35.45	4070	3.26	13.47	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-1.58	15.16	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:4	35.45	4082	3.25	13.48	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-1.79	15.23	1.04	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:11:56:4	35.45	4077	3.24	13.49	97	198	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.09	15.22	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:11:56:4	35.45	4078	3.22	13.47	97	198	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-2.53	15.19	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:11:56:4	35.45	4072	3.18	13.48	97	198	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.08	15.11	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:4	35.45	4067	3.11	13.48	97	198	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4	15.03	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:56:4	35.45	4053	3.06	13.47	97	198	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.8	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:56:5	36.81	4031	3	13.46	97	198	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.6	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:5	36.81	4028	2.89	13.46	97	198	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.72	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:11:56:5	36.81	4001	2.82	13.46	97	198	Full Load	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.43	14.84	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:11:56:5	36.81	3995	2.69	13.46	97	198	Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.99	14.74	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:11:56:5	38.18	3947	2.65	13.45	97	197	Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.42	14.65	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:56:5	38.18	3928	2.56	13.47	97	197	Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.94	14.55	0.99	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:11:56:6	38.18	3894	2.48	13.44	97	197	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.1	14.45	0.98	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:6	38.18	3812	2.4	13.44	97	197	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.35	14.34	0.98	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:6	32.72	3777	2.32	13.45	97	197	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.57	14.22	0.97	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:6	27.27	3769	2.23	13.46	97	197	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.8	14.01	0.95	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:6	21.81	3747	2.15	13.48	97	197	Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.87	13.88	0.95	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:6	20.45	3747	2.02	13.49	97	197	Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.86	13.75	0.94	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:6	20.45	3712	1.94	13.48	97	197	Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.88	13.59	0.93	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:7	20.45	3696	1.91	13.5	97	197	Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.87	13.5	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:7	20.45	3696	1.84	13.49	97	197	Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.85	13.45	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:7	20.45	3642	1.75	13.46	97	197	Idle	41.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.88	13.42	0.91	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:7	20.45	3592	1.71	13.47	97	197	Idle	40.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-9.87	13.42	0.91	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:7	20.45	3576	1.67	13.46	97	197	Idle	39.7	0	2	132	944 Turbo	0.15	Rich	1	14.6	-9.82	13.42	0.91	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:7	20.45	3519	1.63	13.45	97	197	Idle	39.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.79	13.45	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:8	20.45	3515	1.63	13.45	97	197	Idle	38.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.77	13.52	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:8	20.45	3506	1.62	13.46	97	197	Idle	37.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.74	13.63	0.93	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:8	20.45	3436	1.62	13.48	97	197	Idle	36.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.68	13.8	0.94	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:8	20.45	3430	1.63	13.49	97	197	Idle	35.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.64	14.02	0.96	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:8	20.45	3407	1.64	13.49	97	197	Idle	34.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.61	14.39	0.98	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:8	20.45	3398	1.66	13.48	97	197	Idle	33.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	15.21	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:9	20.45	3358	1.66	13.47	97	197	Idle	32	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	15.52	1.06	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:9	20.45	3320	1.67	13.45	97	197	Idle	29.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	16.5	1.12	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:9	20.45	3278	1.69	13.47	97	197	Idle	27.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	17.14	1.17	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:9	20.45	3278	1.7	13.45	97	197	Idle	26.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.32	17.75	1.21	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:9	20.45	3258	1.72	13.47	97	197	Idle	25	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.29	18.34	1.25	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:9	20.45	3220	1.74	13.47	97	197	Idle	23.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.24	19.19	1.31	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:56:9	20.45	3180	1.75	13.46	97	197	Idle	23.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.12	19.67	1.34	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:0	20.45	3180	1.76	13.46	97	197	Idle	22.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.11	19.99	1.36	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:0	20.45	3140	1.77	13.46	97	197	Idle	21.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.16	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:0	20.45	3132	1.79	13.48	97	197	Idle	21.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.05	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:0	20.45	3085	1.8	13.47	97	197	Idle	21.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.95	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:0	20.45	3052	1.81	13.48	97	197	Idle	21.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:0	20.45	3003	1.82	13.48	97	197	Idle	21.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:1	20.45	3008	1.83	13.47	97	197	Idle	21.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:1	19.09	2978	1.83	13.46	97	197	Idle	21.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.89	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:1	19.09	2956	1.84	13.47	97	197	Idle	21.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:57:1	19.09	2931	1.84	13.46	97	197	Idle	21.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.88	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:1	19.09	2923	1.84	13.47	97	197	Idle	21.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.86	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:1	19.09	2882	1.85	13.47	97	197	Idle	21.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.81	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:1	19.09	2848	1.85	13.47	97	197	Idle	22.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.78	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:2	19.09	2848	1.85	13.47	97	197	Idle	22.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.78	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:2	19.09	2794	1.85	13.46	97	197	Idle	22.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.77	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:2	19.09	2783	1.86	13.48	97	197	Idle	23.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.76	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:2	19.09	2751	1.86	13.47	97	197	Idle	23.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:2	19.09	2742	1.86	13.47	97	197	Full Load	24.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.7	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:57:2	9.54	2581	1.86	13.47	97	197	Off Idle	24.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.63	20.24	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:11:57:3	12.27	2703	1.86	13.46	97	197	Off Idle	25.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.62	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:57:3	12.27	2669	1.86	13.47	97	197	Off Idle	27.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.51	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:57:3	14.99	2669	1.87	13.47	97	197	Off Idle	29.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.45	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:11:57:3	17.72	2629	1.87	13.47	97	197	Off Idle	31.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.38	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:11:57:3	17.72	2604	1.88	13.46	97	197	Off Idle	34	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.32	20.24	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:57:3	20.45	2602	1.88	13.46	97	197	Off Idle	39	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.29	20.25	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:57:4	23.18	2576	1.88	13.48	97	197	Off Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.24	20.26	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:57:4	23.18	2555	1.89	13.46	97	197	Off Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.15	20.25	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:57:4	25.9	2513	1.9	13.45	97	197	Off Idle	46.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.05	20.26	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:11:57:4	28.63	2514	1.91	13.45	97	197	Off Idle	49.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.05	20.26	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:4	28.63	2493	1.92	13.45	97	197	Off Idle	52.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.97	20.27	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:57:4	31.36	2451	1.93	13.46	97	197	Off Idle	54.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.89	20.28	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:57:4	34.08	2429	1.93	13.44	97	197	Off Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.84	20.28	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:11:57:5	34.08	2388	1.93	13.44	97	197	Off Idle	59.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.76	20.27	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:5	34.08	2390	1.94	13.46	97	197	Off Idle	62.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.73	20.27	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:5	34.08	2383	1.95	13.47	97	197	Off Idle	63.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.66	20.26	1.38	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:57:5	34.08	2383	1.95	13.45	97	197	Off Idle	64.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.61	20.27	1.38	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:57:5	34.08	2384	1.95	13.46	97	197	Off Idle	65.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.58	20.26	1.38	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:57:5	34.08	2389	1.96	13.47	97	197	Off Idle	66.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.57	20.26	1.38	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:57:6	34.08	2397	1.96	13.46	97	197	Off Idle	67.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.57	20.26	1.38	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:57:6	34.08	2403	1.96	13.45	97	197	Off Idle	68.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.52	20.25	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:6	34.08	2408	1.95	13.46	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.5	20.25	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:6	34.08	2418	1.95	13.46	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.5	20.25	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:6	34.08	2422	1.96	13.46	97	197	Off Idle	70.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.47	20.24	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:6	34.08	2431	1.96	13.44	97	197	Off Idle	71.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.44	20.25	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:6	34.08	2437	1.97	13.45	97	197	Off Idle	71.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.36	20.24	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:11:57:7	34.08	2426	1.96	13.44	97	197	Off Idle	71.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.31	20.15	1.37	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:11:57:7	34.08	2431	1.96	13.44	97	197	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.27	20.01	1.36	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:57:7	34.08	2432	1.96	13.43	97	197	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.22	19.81	1.35	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:57:7	34.08	2430	1.97	13.42	97	197	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.11	19.56	1.33	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:57:7	34.08	2430	1.98	13.44	97	197	Off Idle	71.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.04	19.11	1.3	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:57:7	34.08	2429	1.99	13.44	97	197	Off Idle	71.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.94	18.93	1.29	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:57:8	34.08	2432	1.99	13.46	97	198	Off Idle	71.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.85	18.58	1.27	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:57:8	34.08	2436	2	13.46	97	198	Off Idle	70.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.83	18.22	1.24	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:57:8	34.08	2437	2.01	13.45	97	198	Off Idle	70.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.8	17.64	1.2	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:8	34.08	2438	2.02	13.45	97	197	Off Idle	70.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.76	17.27	1.18	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:8	34.08	2441	2.03	13.44	97	197	Off Idle	70.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.77	16.98	1.16	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:8	34.08	2445	2.04	13.43	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.75	16.65	1.13	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:9	34.08	2468	2.05	13.45	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.7	16.51	1.12	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:9	34.08	2468	2.05	13.46	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.68	16.41	1.12	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:9	34.08	2448	2.06	13.45	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.66	16.36	1.11	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:9	34.08	2448	2.07	13.46	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.64	16.33	1.11	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:9	34.08	2448	2.08	13.47	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.63	16.29	1.11	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:9	34.08	2452	2.08	13.47	97	197	Off Idle	70.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.61	16.27	1.11	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:57:9	34.08	2441	2.09	13.46	97	197	Off Idle	70	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.6	16.26	1.11	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:0	34.08	2442	2.09	13.46	97	197	Off Idle	69.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.62	16.25	1.11	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:0	34.08	2442	2.09	13.46	97	197	Off Idle	69.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.59	16.23	1.11	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:0	34.08	2440	2.09	13.45	97	197	Off Idle	69.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.58	16.2	1.1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:58:0	34.08	2446	2.09	13.45	97	197	Off Idle	69.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.58	16.11	1.1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:0	34.08	2446	2.09	13.48	97	197	Off Idle	69.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.56	16.05	1.09	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:0	34.08	2447	2.09	13.46	97	197	Off Idle	69.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.58	15.99	1.09	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:1	34.08	2455	2.09	13.45	97	197	Off Idle	69.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.55	15.88	1.08	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:1	34.08	2458	2.09	13.46	97	197	Off Idle	69.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.58	15.84	1.08	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:1	34.08	2460	2.09	13.43	97	197	Off Idle	69.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.64	15.73	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:1	34.08	2466	2.09	13.43	97	197	Off Idle	69.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.63	15.62	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:1	34.08	2472	2.09	13.45	97	197	Off Idle	69.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.65	15.55	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:1	34.08	2469	2.09	13.45	97	197	Off Idle	69.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.68	15.48	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:1	34.08	2469	2.09	13.44	97	197	Off Idle	69.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.63	15.41	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:2	34.08	2468	2.09	13.46	97	197	Off Idle	69.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.61	15.32	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:2	34.08	2467	2.09	13.47	97	197	Off Idle	69.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.64	15.27	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:2	34.08	2467	2.09	13.46	97	197	Off Idle	69.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.64	15.24	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:58:2	34.08	2467	2.1	13.47	97	197	Off Idle	69	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.65	15.2	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:58:2	34.08	2469	2.1	13.46	97	197	Off Idle	68.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.68	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:58:2	34.08	2470	2.1	13.44	97	197	Off Idle	68.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.69	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:58:3	34.08	2470	2.1	13.45	97	197	Off Idle	68.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.63	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:58:3	34.08	2470	2.1	13.46	97	197	Off Idle	68.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.64	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:58:3	34.08	2472	2.1	13.46	97	197	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.63	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:58:3	34.08	2475	2.1	13.46	97	197	Off Idle	68.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.63	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:11:58:3	34.08	2479	2.1	13.45	97	197	Off Idle	68.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.63	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:4	34.08	2483	2.1	13.44	97	197	Off Idle	68.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.64	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:4	34.08	2484	2.1	13.44	97	197	Off Idle	68.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.64	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:4	34.08	2484	2.11	13.45	97	197	Off Idle	68.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.63	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:4	34.08	2490	2.11	13.46	97	197	Off Idle	68.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.62	15	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:4	34.08	2481	2.11	13.46	97	197	Off Idle	68.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.62	14.97	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:11:58:4	34.08	2489	2.12	13.47	97	197	Off Idle	68.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.58	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:11:58:4	34.08	2489	2.12	13.45	97	197	Off Idle	68.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.52	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:58:5	34.08	2492	2.13	13.45	97	197	Off Idle	68.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.46	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:11:58:5	34.08	2495	2.13	13.45	97	197	Off Idle	68.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.39	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:5	34.08	2500	2.14	13.45	97	197	Off Idle	68.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.23	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:5	34.08	2500	2.14	13.45	97	197	Off Idle	68.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.15	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:5	34.08	2507	2.15	13.45	97	197	Off Idle	68	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.07	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:5	34.08	2511	2.16	13.46	97	197	Off Idle	67.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.03	15.17	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:6	34.08	2512	2.17	13.45	97	197	Off Idle	67.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.94	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:6	34.08	2505	2.19	13.46	97	197	Off Idle	67.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.89	15.19	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:58:6	34.08	2517	2.2	13.45	97	197	Off Idle	67.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.86	15.2	1.04	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:58:6	34.08	2518	2.21	13.44	97	197	Off Idle	67.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.76	15.19	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:6	34.08	2517	2.22	13.43	97	197	Off Idle	66.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.71	15.18	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:6	34.08	2516	2.22	13.44	97	197	Off Idle	66.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.71	15.17	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:6	34.08	2509	2.24	13.45	97	197	Off Idle	66.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.6	15.17	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:7	34.08	2510	2.25	13.46	97	197	Off Idle	66.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.55	15.14	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:7	34.08	2515	2.25	13.47	97	197	Off Idle	66.1	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.5	15.13	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:7	34.08	2515	2.26	13.46	97	197	Off Idle	65.9	0	2	132	944 Turbo	0.7	Lean	1	14.6	-5.47	15.15	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:7	34.08	2516	2.27	13.45	97	197	Off Idle	65.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.44	15.15	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:7	32.72	2514	2.27	13.47	97	197	Off Idle	65.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.46	15.13	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:7	32.72	2531	2.28	13.45	97	197	Off Idle	65.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.49	15.11	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:8	32.72	2536	2.28	13.47	97	197	Off Idle	65.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.48	15.08	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:8	32.72	2538	2.28	13.46	97	197	Off Idle	65.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.49	15.07	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:8	32.72	2564	2.29	13.46	97	197	Off Idle	65.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.5	15.02	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:8	32.72	2545	2.29	13.46	97	197	Off Idle	65	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.5	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:8	32.72	2545	2.29	13.45	97	197	Off Idle	64.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.49	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:8	32.72	2544	2.29	13.45	97	197	Off Idle	64.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.45	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:9	32.72	2534	2.29	13.46	97	197	Off Idle	64.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.42	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:9	32.72	2540	2.29	13.46	97	197	Off Idle	64.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.47	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:9	32.72	2538	2.29	13.45	97	197	Off Idle	64	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.44	14.74	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:9	32.72	2538	2.29	13.46	97	197	Off Idle	63.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.46	14.74	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:58:9	32.72	2537	2.3	13.45	97	197	Off Idle	63.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.45	14.74	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:58:9	32.72	2540	2.3	13.44	97	197	Off Idle	63.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.48	14.75	1	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:58:9	32.72	2535	2.3	13.45	97	197	Off Idle	63.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.44	14.76	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:0	32.72	2535	2.3	13.44	97	197	Off Idle	63.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.43	14.77	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:0	32.72	2558	2.3	13.44	97	197	Off Idle	63.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.42	14.77	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:0	32.72	2559	2.3	13.46	97	197	Off Idle	63.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.44	14.76	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:0	32.72	2570	2.3	13.45	97	197	Off Idle	63.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.43	14.84	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:0	32.72	2598	2.3	13.45	97	197	Off Idle	63.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.42	14.84	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:0	32.72	2598	2.3	13.46	97	197	Off Idle	63.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.46	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:1	32.72	2586	2.3	13.46	97	197	Off Idle	63.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.49	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:1	32.72	2586	2.3	13.46	97	197	Off Idle	63	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.48	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:1	32.72	2586	2.3	13.45	97	197	Off Idle	62.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.49	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:1	32.72	2577	2.3	13.45	97	197	Off Idle	62.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.47	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:1	32.72	2561	2.3	13.45	97	197	Off Idle	62.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.49	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:1	32.72	2561	2.3	13.44	97	197	Off Idle	62.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.47	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:1	32.72	2560	2.3	13.45	97	197	Off Idle	62.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.47	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:2	32.72	2560	2.3	13.45	97	197	Off Idle	62	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.49	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:2	32.72	2568	2.31	13.44	97	197	Off Idle	61.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.45	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:2	32.72	2570	2.31	13.44	97	197	Off Idle	61.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.43	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:2	32.72	2574	2.31	13.45	97	197	Off Idle	61.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.47	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:2	32.72	2587	2.31	13.46	97	197	Off Idle	61.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.45	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:59:2	32.72	2587	2.31	13.46	97	197	Off Idle	61.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.43	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:3	32.72	2604	2.31	13.47	97	197	Off Idle	61.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.5	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:3	34.08	2604	2.31	13.48	97	197	Off Idle	61.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.49	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:3	34.08	2615	2.31	13.47	97	197	Off Idle	61.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.49	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:3	34.08	2613	2.31	13.46	97	197	Off Idle	61.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.48	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:3	34.08	2615	2.31	13.46	97	197	Off Idle	61.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.5	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:3	34.08	2615	2.32	13.46	97	197	Off Idle	61.2	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.53	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:4	34.08	2614	2.32	13.45	97	197	Off Idle	61	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.49	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:4	34.08	2611	2.32	13.45	97	197	Off Idle	60.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.47	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:4	34.08	2610	2.32	13.47	97	197	Off Idle	60.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.48	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:4	34.08	2604	2.32	13.47	97	197	Off Idle	60.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.45	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:4	34.08	2605	2.32	13.47	97	197	Off Idle	60.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.49	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:4	34.08	2604	2.32	13.45	97	197	Off Idle	60.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.48	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:4	34.08	2604	2.32	13.47	97	197	Off Idle	60.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.5	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:5	34.08	2624	2.33	13.46	97	197	Off Idle	60.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.48	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:5	34.08	2612	2.33	13.46	97	197	Off Idle	60.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.48	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:5	34.08	2622	2.33	13.47	97	197	Off Idle	60.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.46	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:5	34.08	2624	2.33	13.48	97	197	Off Idle	60.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.46	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:5	34.08	2635	2.33	13.46	97	197	Off Idle	59.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.49	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:5	34.08	2641	2.33	13.46	97	197	Off Idle	59.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.49	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:6	34.08	2641	2.33	13.46	97	197	Off Idle	59.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.53	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:6	34.08	2641	2.33	13.47	97	197	Off Idle	59.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.55	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:6	34.08	2641	2.33	13.45	97	197	Off Idle	59.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.53	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:6	34.08	2636	2.33	13.46	97	197	Off Idle	59.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.5	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:6	34.08	2636	2.33	13.46	97	197	Off Idle	59.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.5	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:6	34.08	2636	2.33	13.45	97	197	Off Idle	59.8	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.48	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:6	34.08	2640	2.33	13.46	97	197	Off Idle	59.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.44	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:7	34.08	2632	2.33	13.46	97	197	Off Idle	59.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.41	14.84	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:7	34.08	2661	2.34	13.46	97	197	Off Idle	59	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.4	14.85	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:7	34.08	2658	2.34	13.47	97	197	Off Idle	58.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.41	14.84	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:59:7	34.08	2660	2.34	13.46	97	197	Off Idle	58.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.36	14.85	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:59:7	34.08	2665	2.35	13.46	97	197	Off Idle	58.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.29	14.85	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:59:7	34.08	2670	2.35	13.47	97	197	Off Idle	58.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.26	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:8	34.08	2670	2.36	13.47	97	197	Off Idle	57.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.16	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:8	34.08	2668	2.37	13.47	97	197	Off Idle	57.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.1	14.9	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:11:59:8	34.08	2666	2.38	13.47	97	197	Off Idle	57.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.06	14.91	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:59:8	34.08	2656	2.39	13.47	97	197	Off Idle	57.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.99	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:11:59:8	34.08	2669	2.4	13.46	97	197	Off Idle	57.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.92	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:11:59:8	34.08	2672	2.41	13.46	97	197	Off Idle	57.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.81	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:9	34.08	2669	2.42	13.46	97	197	Off Idle	57.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.76	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:9	34.08	2669	2.42	13.45	97	197	Off Idle	57	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.67	15.03	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:59:9	34.08	2695	2.43	13.46	97	197	Off Idle	57	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.61	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:59:9	34.08	2680	2.44	13.46	97	197	Off Idle	57	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.56	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:11:59:9	34.08	2690	2.45	13.45	97	197	Off Idle	57	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.56	15	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:59:9	34.08	2690	2.46	13.47	97	197	Off Idle	57	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.55	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:11:59:9	34.08	2688	2.47	13.47	97	197	Off Idle	56.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.56	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:00:0	34.08	2708	2.47	13.46	97	197	Off Idle	56.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.56	14.93	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:0	34.08	2715	2.48	13.47	97	197	Off Idle	56.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.56	14.88	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:0	32.72	2704	2.49	13.47	97	196	Off Idle	56.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.56	14.88	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:0	32.72	2712	2.49	13.46	97	196	Off Idle	56	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.55	14.88	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:0	32.72	2716	2.5	13.47	97	196	Off Idle	56	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.49	14.9	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:0	32.72	2716	2.5	13.45	97	197	Off Idle	55.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.46	14.9	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:1	32.72	2700	2.5	13.43	97	197	Off Idle	55.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.44	14.9	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:00:1	32.72	2709	2.5	13.46	97	197	Off Idle	55.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.42	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:1	34.08	2709	2.5	13.44	97	197	Off Idle	55.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.4	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:1	34.08	2684	2.5	13.45	97	197	Off Idle	55.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.39	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:1	34.08	2708	2.51	13.45	97	197	Off Idle	55.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.35	14.88	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:1	34.08	2716	2.51	13.46	97	197	Off Idle	55	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.44	14.84	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:1	34.08	2731	2.51	13.46	97	197	Off Idle	54.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.49	14.83	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:2	34.08	2763	2.51	13.47	97	197	Off Idle	54.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.52	14.81	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:2	34.08	2755	2.51	13.48	97	197	Off Idle	54.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.48	14.81	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:2	34.08	2746	2.51	13.48	97	197	Off Idle	54.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.47	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:2	34.08	2740	2.51	13.49	97	197	Off Idle	54.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.49	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:2	34.08	2739	2.51	13.48	97	197	Off Idle	54.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.45	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:2	34.08	2738	2.52	13.48	97	197	Off Idle	54.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.42	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:3	34.08	2737	2.52	13.47	97	197	Off Idle	54.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.46	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:3	34.08	2736	2.52	13.48	97	197	Off Idle	53.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.46	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:00:3	34.08	2736	2.52	13.47	97	197	Off Idle	53.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.48	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:00:3	34.08	2741	2.52	13.46	97	197	Off Idle	53.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.48	14.88	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:00:3	34.08	2743	2.51	13.46	97	197	Off Idle	53.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.56	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:00:3	34.08	2756	2.51	13.45	97	197	Off Idle	53.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.63	14.85	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:4	34.08	2787	2.5	13.47	97	197	Off Idle	53.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.82	14.85	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:4	34.08	2787	2.48	13.48	97	197	Off Idle	53.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.08	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:00:4	34.08	2766	2.44	13.47	97	197	Off Idle	53.1	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.65	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:00:4	34.08	2761	2.38	13.46	97	197	Full Load	53.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.15	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:00:4	34.08	2755	2.29	13.47	97	197	Idle	53.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.96	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:4	35.45	2739	2.23	13.49	97	197	Idle	53.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.21	14.9	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:12:00:4	35.45	2734	2.18	13.47	97	197	Idle	53	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.67	14.91	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:12:00:5	35.45	2712	2.14	13.47	97	197	Idle	52.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.21	15	1.02	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:12:00:5	35.45	2621	2.1	13.49	97	196	Idle	52.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.45	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:5	35.45	2643	2.05	13.47	97	196	Idle	51.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.72	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:5	32.72	2616	2	13.45	97	196	Idle	50.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.92	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:00:5	32.72	2568	1.95	13.46	97	197	Idle	48.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.01	15.02	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:5	27.27	2550	1.91	13.47	97	197	Idle	47.6	0	2	132	944 Turbo	0.78	Lean	1	14.6	-9.13	14.98	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:6	21.81	2550	1.87	13.46	97	197	Idle	45.4	0	2	132	944 Turbo	0.72	Lean	1	14.6	-9.16	14.92	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:6	21.81	2560	1.82	13.47	97	197	Idle	44.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.2	14.77	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:6	19.09	2602	1.79	13.48	97	197	Idle	43.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.18	14.64	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:6	19.09	2635	1.75	13.48	97	197	Idle	42.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.21	14.49	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:6	19.09	2682	1.71	13.47	97	197	Idle	42.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.26	14.26	0.97	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:6	19.09	2694	1.67	13.49	97	197	Idle	41.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.26	14.14	0.96	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:6	19.09	2771	1.64	13.48	97	196	Idle	42	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.29	14.02	0.96	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:7	19.09	2765	1.62	13.46	97	196	Idle	42	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.35	13.94	0.95	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:7	19.09	2781	1.63	13.47	97	196	Idle	41.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.39	13.82	0.94	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:7	19.09	2781	1.63	13.46	98	196	Idle	43.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.45	13.79	0.94	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:7	19.09	2780	1.65	13.48	98	196	Idle	43.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.48	13.78	0.94	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:7	19.09	2766	1.66	13.47	98	196	Idle	44.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.54	13.85	0.94	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:00:7	19.09	2760	1.67	13.48	97	197	Idle	45.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.57	13.92	0.95	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:8	19.09	2726	1.66	13.48	97	197	Idle	47.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.59	14.01	0.95	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:8	19.09	2718	1.65	13.46	97	197	Idle	48.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.6	14.14	0.96	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:8	19.09	2710	1.65	13.46	97	196	Idle	49.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.62	14.25	0.97	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:8	19.09	2682	1.66	13.46	97	196	Idle	50.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.63	14.42	0.98	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:8	19.09	2654	1.65	13.47	97	196	Idle	51	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.66	14.77	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:8	19.09	2654	1.65	13.47	97	196	Idle	51.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	15.02	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:9	19.09	2640	1.63	13.48	97	196	Idle	52	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	15.3	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:9	19.09	2634	1.61	13.48	97	196	Idle	51	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	15.75	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:9	19.09	2634	1.6	13.47	97	196	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	16.08	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:9	19.09	2640	1.59	13.47	97	196	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	16.46	1.12	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:9	19.09	2662	1.59	13.47	97	196	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	16.93	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:9	19.09	2665	1.59	13.48	97	196	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	17.43	1.19	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:00:9	19.09	2670	1.58	13.47	97	196	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	17.9	1.22	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:0	19.09	2686	1.57	13.47	97	196	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	18.33	1.25	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:0	19.09	2696	1.57	13.47	97	196	Idle	50.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	18.52	1.26	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:0	19.09	2679	1.57	13.47	97	196	Idle	50.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	18.89	1.29	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:0	19.09	2687	1.57	13.47	97	196	Idle	51	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	19.24	1.31	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:0	19.09	2690	1.57	13.47	97	196	Idle	51.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	19.53	1.33	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:0	19.09	2681	1.56	13.48	97	196	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	19.8	1.35	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:1	19.09	2678	1.56	13.49	97	196	Idle	51.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.09	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:1	19.09	2661	1.55	13.48	97	196	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:1	19.09	2648	1.55	13.47	97	196	Idle	53	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:1	19.09	2644	1.55	13.46	97	196	Idle	53.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:1	19.09	2617	1.54	13.46	97	196	Idle	53.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:1	19.09	2616	1.54	13.48	97	196	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:1	19.09	2616	1.54	13.47	97	196	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:2	19.09	2610	1.53	13.47	97	196	Idle	55.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:2	19.09	2610	1.53	13.47	97	196	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:2	19.09	2611	1.52	13.47	97	196	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:2	19.09	2619	1.52	13.47	97	196	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:2	19.09	2619	1.51	13.47	97	196	Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:2	19.09	2625	1.51	13.46	97	196	Idle	55.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:3	19.09	2625	1.5	13.48	97	196	Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:3	19.09	2653	1.5	13.47	97	196	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:3	19.09	2631	1.49	13.49	97	197	Idle	55.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:3	19.09	2631	1.49	13.48	97	197	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:3	19.09	2629	1.49	13.49	97	196	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:3	19.09	2624	1.48	13.49	97	196	Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:4	19.09	2612	1.48	13.48	97	196	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:4	19.09	2608	1.48	13.48	97	196	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:4	19.09	2612	1.47	13.47	97	196	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:4	19.09	2594	1.47	13.47	97	196	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:4	19.09	2591	1.47	13.48	97	196	Idle	58.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:4	19.09	2582	1.46	13.47	97	196	Idle	58.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:4	19.09	2579	1.46	13.46	97	196	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:5	19.09	2575	1.46	13.47	97	196	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:5	19.09	2574	1.46	13.46	98	196	Idle	59.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:5	19.09	2575	1.45	13.46	98	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:5	19.09	2576	1.45	13.46	98	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:5	19.09	2576	1.45	13.44	98	196	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:5	19.09	2588	1.45	13.44	98	196	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:6	19.09	2578	1.44	13.46	97	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:6	19.09	2557	1.44	13.44	97	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:6	19.09	2568	1.43	13.44	97	196	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:6	19.09	2596	1.43	13.45	98	196	Idle	59.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:6	19.09	2596	1.43	13.45	98	196	Idle	59.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:6	19.09	2571	1.43	13.46	98	196	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:01:6	19.09	2571	1.42	13.47	97	196	Idle	60.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:7	19.09	2561	1.42	13.48	97	196	Idle	60.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:7	19.09	2557	1.42	13.48	97	196	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:7	19.09	2550	1.41	13.47	97	196	Idle	60.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:7	19.09	2548	1.41	13.47	97	196	Idle	60.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:7	19.09	2541	1.41	13.47	97	196	Idle	61.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:7	19.09	2537	1.41	13.47	97	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:8	19.09	2536	1.4	13.47	97	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:8	19.09	2533	1.4	13.46	97	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:8	19.09	2530	1.4	13.47	97	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:8	19.09	2530	1.4	13.45	97	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:8	19.09	2529	1.39	13.45	98	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:8	19.09	2530	1.39	13.46	98	196	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:9	19.09	2527	1.39	13.46	97	196	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:9	19.09	2527	1.39	13.46	97	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:9	19.09	2525	1.39	13.47	97	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:9	19.09	2525	1.38	13.48	97	196	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:9	19.09	2544	1.38	13.48	97	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:9	19.09	2521	1.38	13.46	97	196	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:01:9	19.09	2518	1.38	13.46	98	196	Idle	61.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:0	19.09	2518	1.38	13.47	98	196	Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:0	19.09	2513	1.38	13.47	98	196	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:0	19.09	2509	1.37	13.48	98	196	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:0	19.09	2507	1.37	13.48	98	196	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:0	19.09	2506	1.37	13.47	97	196	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:0	19.09	2498	1.37	13.47	97	196	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:1	19.09	2494	1.36	13.45	97	196	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:1	19.09	2494	1.36	13.47	97	196	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:1	19.09	2489	1.35	13.46	97	196	Idle	64.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:1	19.09	2488	1.35	13.46	97	196	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:1	19.09	2484	1.35	13.49	97	196	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:1	19.09	2481	1.34	13.48	97	196	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:1	19.09	2479	1.34	13.47	97	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:2	19.09	2479	1.34	13.48	97	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:2	19.09	2478	1.33	13.47	97	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:2	19.09	2475	1.33	13.47	97	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:2	19.09	2472	1.33	13.48	97	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:2	19.09	2472	1.32	13.46	97	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:2	19.09	2468	1.32	13.45	97	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:3	19.09	2464	1.31	13.46	98	196	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:3	19.09	2460	1.31	13.46	98	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:3	19.09	2460	1.31	13.46	98	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:3	19.09	2457	1.31	13.47	97	196	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:3	19.09	2435	1.31	13.47	97	196	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:3	17.72	2452	1.31	13.45	97	196	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:4	17.72	2450	1.31	13.45	98	196	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:4	19.09	2465	1.31	13.45	98	196	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:4	19.09	2443	1.31	13.45	97	196	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:4	19.09	2405	1.31	13.45	97	196	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:4	17.72	2423	1.31	13.45	97	196	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:4	17.72	2438	1.31	13.47	97	196	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:4	17.72	2435	1.3	13.46	97	196	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:5	17.72	2436	1.3	13.46	97	196	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:5	17.72	2444	1.3	13.47	97	196	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:5	17.72	2433	1.3	13.46	97	196	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:5	17.72	2432	1.29	13.45	97	196	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:5	17.72	2426	1.29	13.48	97	196	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:5	17.72	2404	1.29	13.48	97	196	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:02:6	17.72	2421	1.28	13.5	98	196	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:6	17.72	2420	1.28	13.49	98	196	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:6	17.72	2416	1.28	13.49	98	196	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:6	17.72	2412	1.27	13.48	97	196	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:6	17.72	2392	1.27	13.46	97	196	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:6	17.72	2400	1.27	13.47	97	196	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:6	17.72	2406	1.26	13.47	97	196	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:7	17.72	2403	1.26	13.47	98	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:7	17.72	2400	1.26	13.47	98	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:7	17.72	2408	1.25	13.47	98	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:7	17.72	2394	1.25	13.46	97	196	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:7	17.72	2375	1.24	13.44	97	196	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:7	17.72	2390	1.24	13.45	98	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:8	17.72	2390	1.24	13.47	98	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:8	17.72	2386	1.24	13.45	98	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:8	17.72	2384	1.23	13.46	97	196	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:8	17.72	2384	1.23	13.47	97	196	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:8	17.72	2381	1.23	13.46	97	196	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:8	17.72	2388	1.23	13.48	97	196	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:9	17.72	2374	1.22	13.48	97	196	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:9	17.72	2364	1.22	13.46	97	196	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:9	17.72	2368	1.22	13.46	98	196	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:9	17.72	2365	1.21	13.45	98	196	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:9	17.72	2365	1.21	13.45	98	196	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:9	17.72	2360	1.21	13.46	97	196	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:02:9	17.72	2373	1.2	13.47	97	196	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:0	17.72	2373	1.2	13.45	97	196	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:0	17.72	2352	1.2	13.47	98	196	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:0	17.72	2348	1.19	13.46	98	196	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:0	17.72	2349	1.19	13.46	98	196	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:0	17.72	2336	1.19	13.47	98	196	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:0	17.72	2342	1.19	13.47	98	196	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:1	17.72	2342	1.18	13.45	98	196	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:1	17.72	2340	1.18	13.47	98	196	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:1	17.72	2346	1.18	13.48	98	196	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:1	17.72	2335	1.17	13.46	98	196	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:1	17.72	2335	1.17	13.46	97	196	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:1	17.72	2330	1.17	13.47	97	196	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:1	17.72	2338	1.16	13.46	97	196	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:2	17.72	2325	1.16	13.45	97	196	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:2	17.72	2326	1.16	13.46	97	196	Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:2	17.72	2323	1.15	13.47	97	196	Idle	73.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:2	17.72	2319	1.15	13.48	97	196	Idle	73.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:2	17.72	2301	1.15	13.47	97	196	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:2	17.72	2301	1.14	13.48	98	196	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:3	17.72	2313	1.14	13.48	98	196	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:3	17.72	2300	1.14	13.49	98	196	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:3	17.72	2304	1.13	13.48	97	196	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:3	17.72	2304	1.13	13.49	97	196	Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:3	17.72	2302	1.13	13.48	97	196	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:3	17.72	2302	1.12	13.47	97	196	Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:4	17.72	2298	1.12	13.48	97	196	Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:4	17.72	2298	1.11	13.47	98	196	Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:4	17.72	2296	1.11	13.44	98	196	Idle	75.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:4	17.72	2291	1.11	13.45	97	196	Idle	75.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:4	17.72	2286	1.1	13.45	97	196	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:4	17.72	2286	1.1	13.46	97	196	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:4	17.72	2284	1.1	13.47	97	196	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:03:5	17.72	2282	1.09	13.49	98	196	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:5	17.72	2277	1.09	13.49	98	196	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:5	17.72	2275	1.09	13.49	98	196	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:5	17.72	2274	1.09	13.5	98	196	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:5	17.72	2270	1.09	13.49	97	196	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:5	17.72	2266	1.08	13.49	97	196	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:6	17.72	2266	1.08	13.49	98	196	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:6	17.72	2264	1.08	13.48	98	196	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:6	17.72	2270	1.07	13.48	98	196	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:6	17.72	2258	1.07	13.47	98	196	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:6	17.72	2258	1.07	13.46	98	196	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:6	17.72	2256	1.07	13.46	98	196	Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:6	17.72	2254	1.07	13.47	98	197	Idle	77.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:7	17.72	2251	1.07	13.48	98	197	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:7	17.72	2251	1.07	13.47	98	197	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:7	17.72	2258	1.06	13.47	98	196	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:7	17.72	2245	1.06	13.46	98	196	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:7	17.72	2225	1.06	13.46	98	196	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:7	17.72	2232	1.06	13.46	98	196	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:8	17.72	2228	1.06	13.45	98	196	Idle	78	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:8	17.72	2233	1.05	13.44	98	196	Idle	78	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:8	17.72	2233	1.05	13.45	98	196	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:8	17.72	2238	1.05	13.46	98	196	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:8	17.72	2217	1.05	13.46	98	196	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:8	17.72	2222	1.05	13.46	98	196	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:9	17.72	2222	1.05	13.45	98	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:9	17.72	2219	1.04	13.46	98	196	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:9	17.72	2219	1.04	13.47	98	196	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:9	17.72	2206	1.04	13.48	98	196	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:9	17.72	2211	1.04	13.49	98	196	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:9	17.72	2242	1.04	13.49	98	196	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:03:9	17.72	2242	1.04	13.48	98	196	Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:0	17.72	2197	1.03	13.47	98	196	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:0	17.72	2202	1.03	13.47	98	196	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:0	17.72	2201	1.03	13.48	98	196	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:0	17.72	2181	1.03	13.48	97	196	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:0	17.72	2205	1.03	13.47	97	196	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:0	17.72	2205	1.03	13.46	97	196	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:1	17.72	2193	1.03	13.44	98	196	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:1	17.72	2172	1.02	13.44	98	196	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:1	17.72	2179	1.02	13.44	98	196	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:1	17.72	2201	1.02	13.43	98	196	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:1	17.72	2182	1.02	13.43	98	196	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:1	17.72	2161	1.02	13.44	98	196	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:1	17.72	2161	1.01	13.43	98	196	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:2	17.72	2161	1.01	13.43	98	196	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:2	17.72	2181	1.01	13.44	98	196	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:2	17.72	2169	1.01	13.44	98	196	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:2	17.72	2167	1.01	13.44	98	196	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:2	17.72	2166	1.01	13.46	98	196	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:2	17.72	2163	1	13.47	98	196	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:3	17.72	2160	1	13.48	98	196	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:3	17.72	2158	1	13.49	98	196	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:3	17.72	2157	1	13.49	98	196	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:3	17.72	2153	0.99	13.49	98	196	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:3	17.72	2148	0.99	13.49	98	196	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:3	17.72	2147	0.99	13.48	98	197	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:4	17.72	2143	0.99	13.48	98	197	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:04:4	17.72	2142	0.98	13.47	98	196	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:4	17.72	2142	0.98	13.46	98	196	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:4	17.72	2137	0.98	13.46	98	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:4	17.72	2118	0.98	13.46	98	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:4	17.72	2126	0.98	13.45	98	196	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:4	17.72	2131	0.97	13.47	98	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:5	17.72	2130	0.97	13.46	98	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:5	17.72	2126	0.97	13.46	98	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:5	17.72	2123	0.97	13.45	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:5	17.72	2123	0.97	13.45	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:5	17.72	2122	0.97	13.46	98	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:5	17.72	2120	0.97	13.45	98	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:6	17.72	2116	0.96	13.46	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:6	17.72	2116	0.96	13.46	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:6	17.72	2113	0.96	13.47	98	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:6	17.72	2102	0.96	13.47	98	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:6	17.72	2122	0.96	13.48	97	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:6	17.72	2122	0.96	13.45	97	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:6	17.72	2102	0.96	13.44	97	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:7	17.72	2099	0.95	13.43	98	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.26	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:7	17.72	2099	0.95	13.43	98	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:7	17.72	2095	0.95	13.43	98	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:7	17.72	2091	0.95	13.44	98	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:7	17.72	2090	0.95	13.47	98	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:7	17.72	2070	0.95	13.47	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.26	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:8	17.72	2092	0.95	13.46	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:8	17.72	2081	0.95	13.46	98	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:8	17.72	2080	0.95	13.45	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:8	17.72	2079	0.95	13.45	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:8	17.72	2075	0.95	13.44	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:8	17.72	2075	0.95	13.46	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:9	17.72	2072	0.95	13.46	98	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:9	17.72	2070	0.95	13.47	98	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:9	17.72	2066	0.95	13.47	98	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:9	17.72	2065	0.95	13.47	98	196	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:9	17.72	2062	0.95	13.47	98	196	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:9	17.72	2057	0.95	13.47	98	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:04:9	17.72	2040	0.95	13.44	98	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:0	17.72	2040	0.95	13.43	98	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:0	17.72	2052	0.95	13.42	98	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:0	17.72	2066	0.95	13.41	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:0	17.72	2049	0.95	13.43	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:0	17.72	2048	0.95	13.43	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:0	17.72	2044	0.95	13.44	98	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:1	17.72	2043	0.95	13.46	98	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:1	17.72	2024	0.95	13.45	98	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:1	17.72	2030	0.95	13.47	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:1	17.72	2052	0.95	13.49	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:1	17.72	2032	0.95	13.49	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.06	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:1	17.72	2029	0.95	13.49	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.06	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:1	17.72	2029	0.95	13.49	98	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.06	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:2	17.72	2026	0.95	13.48	98	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.06	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:2	17.72	2023	0.95	13.48	98	196	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.05	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:2	17.72	2023	0.95	13.48	98	196	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.06	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:2	17.72	2021	0.95	13.47	98	196	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.07	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:2	17.72	2018	0.95	13.46	98	196	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.07	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:2	17.72	2016	0.95	13.44	98	196	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.07	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:3	17.72	2013	0.95	13.44	98	196	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.07	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:05:3	17.72	2012	0.95	13.44	98	196	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:3	17.72	1992	0.95	13.45	98	196	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:3	17.72	2012	0.95	13.46	98	196	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:3	17.72	2000	0.96	13.47	98	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:3	17.72	2000	0.96	13.47	98	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:4	17.72	1998	0.96	13.47	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:4	17.72	1996	0.96	13.46	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:4	17.72	1977	0.96	13.45	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:4	17.72	1977	0.96	13.43	98	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:4	17.72	1988	0.96	13.43	98	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:4	17.72	1988	0.96	13.42	98	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:4	17.72	2000	0.96	13.43	98	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:5	17.72	2000	0.95	13.45	98	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:5	17.72	1982	0.95	13.45	98	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:5	17.72	1979	0.95	13.43	98	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:5	17.72	1977	0.95	13.45	98	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:5	17.72	1968	0.95	13.46	98	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:5	17.72	1972	0.95	13.46	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:6	17.72	1972	0.95	13.45	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:6	17.72	1967	0.95	13.45	98	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:6	17.72	1967	0.95	13.47	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:6	17.72	1962	0.95	13.46	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:6	17.72	1962	0.95	13.47	98	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:6	17.72	1960	0.95	13.48	98	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:6	17.72	1956	0.95	13.48	98	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:7	17.72	1953	0.95	13.48	98	196	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:7	17.72	1953	0.95	13.48	98	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:7	17.72	1950	0.95	13.48	98	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:7	17.72	1948	0.95	13.47	98	196	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:7	17.72	1944	0.95	13.45	98	196	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:7	17.72	1944	0.95	13.44	98	196	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:8	17.72	1942	0.95	13.43	98	196	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:8	17.72	1939	0.95	13.43	98	196	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:8	17.72	1936	0.95	13.45	98	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:8	17.72	1936	0.95	13.45	98	196	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:8	17.72	1935	0.95	13.44	98	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:8	17.72	1931	0.95	13.45	98	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:9	17.72	1929	0.95	13.45	98	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:9	17.72	1927	0.95	13.43	98	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:9	17.72	1923	0.95	13.43	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:9	17.72	1923	0.95	13.43	98	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:9	17.72	1920	0.95	13.43	98	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:9	17.72	1917	0.95	13.43	98	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:05:9	17.72	1915	0.95	13.43	98	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:0	17.72	1913	0.95	13.43	98	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:0	17.72	1912	0.95	13.46	98	196	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:0	17.72	1904	0.95	13.46	98	196	Full Load	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:0	17.72	1909	0.95	13.45	98	196	Off Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:0	17.72	1909	0.95	13.45	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:0	17.72	1906	0.96	13.46	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:1	17.72	1854	0.96	13.46	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:12:06:1	9.54	1929	0.97	13.44	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:12:06:1	9.54	1912	0.98	13.44	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:12:06:1	12.27	1912	0.98	13.45	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:12:06:1	12.27	1908	0.99	13.46	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:1	14.99	1905	0.99	13.44	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:1	14.99	1904	1	13.45	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:2	17.72	1904	1.01	13.46	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:06:2	17.72	1900	1.02	13.46	98	196	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:2	20.45	1898	1.03	13.45	98	197	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:06:2	20.45	1895	1.04	13.44	98	197	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:06:2	23.18	1894	1.05	13.46	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:06:2	23.18	1892	1.07	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.25	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:3	25.9	1874	1.08	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:3	25.9	1884	1.09	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:3	28.63	1904	1.11	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:3	28.63	1915	1.13	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:3	31.36	1915	1.14	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:3	31.36	1926	1.15	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:4	32.72	1926	1.17	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:06:4	32.72	1906	1.18	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:06:4	32.72	1896	1.19	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:06:4	32.72	1893	1.2	13.46	98	196	Off Idle	86	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:06:4	32.72	1884	1.22	13.46	98	196	Off Idle	86	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:06:4	32.72	1879	1.23	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:06:4	32.72	1879	1.25	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.26	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:06:5	32.72	1882	1.26	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.27	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:06:5	32.72	1882	1.28	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.26	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:06:5	32.72	1882	1.28	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.27	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:06:5	32.72	1869	1.3	13.46	98	196	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	20.26	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:06:5	32.72	1869	1.31	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.44	20.27	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:06:5	32.72	1868	1.33	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.4	20.28	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:06:6	32.72	1869	1.34	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.35	20.28	1.38	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:6	32.72	1869	1.36	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.3	20.27	1.38	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:6	32.72	1870	1.37	13.42	98	196	Off Idle	86	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.18	20.26	1.38	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:6	32.72	1870	1.38	13.42	98	196	Off Idle	86	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.14	20.26	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:6	32.72	1876	1.38	13.42	98	196	Off Idle	86	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.14	20.26	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:6	32.72	1876	1.39	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.09	20.25	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:6	31.36	1874	1.41	13.42	98	196	Off Idle	86	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.96	20.25	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:7	31.36	1889	1.42	13.42	98	196	Off Idle	86	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.94	20.25	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:7	31.36	1892	1.43	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.88	20.24	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:06:7	31.36	1891	1.45	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.72	20.25	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:06:7	31.36	1894	1.46	13.42	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.68	20.26	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:7	31.36	1901	1.48	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.66	20.26	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:7	31.36	1900	1.49	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.6	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:8	31.36	1890	1.51	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.52	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:06:8	31.36	1890	1.52	13.46	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.48	20.23	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:06:8	31.36	1880	1.54	13.46	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.41	20.13	1.37	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:06:8	31.36	1874	1.56	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.33	20	1.36	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:8	31.36	1874	1.57	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.29	19.81	1.35	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:8	31.36	1860	1.58	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.22	19.59	1.33	3.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:9	31.36	1856	1.6	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.13	19.34	1.32	3.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:9	31.36	1841	1.61	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.08	18.93	1.29	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:9	31.36	1841	1.62	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.02	18.62	1.27	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:9	29.99	1851	1.63	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.97	18.3	1.25	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:9	29.99	1865	1.64	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.95	17.84	1.22	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:9	29.99	1869	1.64	13.46	98	196	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.91	17.57	1.2	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:06:9	29.99	1869	1.65	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.84	17.34	1.18	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:07:0	29.99	1876	1.66	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.83	17.14	1.17	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:07:0	29.99	1883	1.66	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.79	16.98	1.16	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:0	29.99	1890	1.67	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.76	16.76	1.14	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:0	31.36	1918	1.67	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.76	16.69	1.14	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:07:0	31.36	1888	1.67	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.73	16.5	1.12	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:0	31.36	1888	1.67	13.47	98	196	Off Idle	86	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.75	16.38	1.12	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:1	31.36	1889	1.67	13.46	98	196	Off Idle	86	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.69	16.27	1.11	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:1	31.36	1886	1.68	13.47	98	196	Off Idle	86	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.72	16.11	1.1	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:07:1	31.36	1885	1.68	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.7	16	1.09	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:1	31.36	1881	1.68	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15.9	1.08	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:07:1	31.36	1877	1.68	13.46	98	196	Off Idle	86	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.79	1.08	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:1	31.36	1877	1.68	13.47	98	196	Off Idle	86	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.69	1.07	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:1	31.36	1864	1.68	13.48	98	196	Off Idle	86	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.59	1.06	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:2	31.36	1869	1.68	13.48	98	196	Off Idle	86	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.51	1.06	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:2	31.36	1869	1.68	13.48	98	196	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	15.43	1.05	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:2	31.36	1872	1.68	13.48	98	196	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	15.3	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:07:2	31.36	1882	1.69	13.48	98	196	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.59	15.24	1.04	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:07:2	31.36	1878	1.69	13.47	98	196	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.53	15.22	1.04	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:07:2	31.36	1878	1.71	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.4	15.17	1.03	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:07:3	31.36	1885	1.73	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.23	15.13	1.03	3.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:3	31.36	1884	1.75	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.05	15.06	1.03	3.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:3	31.36	1899	1.78	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.85	15.02	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:07:3	31.36	1899	1.8	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.61	14.95	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:07:3	31.36	1902	1.81	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.43	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:07:3	31.36	1911	1.83	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.22	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:07:4	31.36	1911	1.85	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.07	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:07:4	31.36	1928	1.88	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.92	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:07:4	29.99	1914	1.9	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.74	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:4	29.99	1931	1.92	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.69	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:4	29.99	1931	1.93	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.62	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:4	29.99	1934	1.95	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.54	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:4	29.99	1932	1.97	13.42	98	196	Off Idle	86	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.47	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:5	29.99	1927	2	13.42	98	196	Off Idle	86	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.36	14.84	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:5	29.99	1921	2.01	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.35	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:5	29.99	1921	2.04	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.36	14.91	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:5	29.99	1914	2.04	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.32	14.99	1.02	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:07:5	29.99	1907	2.05	13.42	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.33	15.06	1.03	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:07:5	29.99	1907	2.05	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.33	15.13	1.03	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:07:6	29.99	1907	2.05	13.42	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.29	15.18	1.03	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:07:6	29.99	1905	2.05	13.42	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.2	15.21	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:07:6	29.99	1922	2.05	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.1	15.27	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:07:6	29.99	1931	2.05	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.02	15.36	1.05	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:07:6	29.99	1936	2.06	13.42	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.97	15.37	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:6	29.99	1962	2.06	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.88	15.32	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:6	29.99	1948	2.07	13.42	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.78	15.26	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:7	29.99	1947	2.08	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.72	15.17	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:07:7	29.99	1950	2.09	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.66	15.05	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:7	29.99	1950	2.09	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.55	14.93	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:7	29.99	1951	2.11	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.47	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:7	29.99	1950	2.11	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.36	14.64	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:7	29.99	1955	2.12	13.45	98	197	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.28	14.52	0.99	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:07:8	29.99	1958	2.12	13.45	98	197	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.18	14.4	0.98	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:07:8	29.99	1966	2.14	13.48	98	197	Off Idle	86	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.13	14.36	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:8	29.99	1974	2.15	13.46	98	196	Off Idle	86	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.06	14.32	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:8	29.99	1978	2.15	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.08	14.32	0.98	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:8	29.99	1986	2.17	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.03	14.36	0.98	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:8	29.99	1986	2.18	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.99	14.41	0.98	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:9	29.99	1986	2.19	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.96	14.45	0.98	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:9	29.99	1980	2.19	13.41	98	196	Off Idle	86	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.94	14.51	0.99	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:9	29.99	1980	2.2	13.4	98	196	Off Idle	86	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.88	14.57	0.99	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:9	29.99	1976	2.21	13.41	98	196	Off Idle	86	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.9	14.64	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:9	29.99	1973	2.21	13.42	98	196	Off Idle	86	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.88	14.72	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:9	29.99	1990	2.22	13.43	98	196	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.84	14.76	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:07:9	29.99	1980	2.22	13.44	98	196	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.82	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:0	29.99	1984	2.22	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.8	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:0	29.99	1992	2.22	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.8	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:08:0	29.99	2000	2.23	13.45	98	196	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.79	14.78	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:0	29.99	2008	2.23	13.46	98	197	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.8	14.76	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:0	29.99	2015	2.23	13.47	98	197	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.76	14.72	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:0	29.99	2020	2.23	13.47	98	197	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.73	14.7	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:1	29.99	2025	2.23	13.47	98	197	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.77	14.69	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:1	29.99	2007	2.23	13.47	98	197	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.72	14.67	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:1	29.99	2012	2.23	13.47	98	197	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.71	14.68	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:1	29.99	2020	2.23	13.47	98	196	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.71	14.68	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:1	29.99	2025	2.24	13.47	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.7	14.69	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:1	29.99	2018	2.24	13.47	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.72	14.7	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:1	29.99	2018	2.24	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.7	14.72	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:2	29.99	2026	2.24	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.67	14.74	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:2	29.99	2029	2.24	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.72	14.77	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:2	29.99	2034	2.24	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.73	14.78	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:2	29.99	2040	2.24	13.43	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.76	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:08:2	29.99	2048	2.24	13.46	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.78	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:08:2	29.99	2067	2.24	13.47	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.8	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:08:3	29.99	2063	2.24	13.48	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.8	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:08:3	29.99	2063	2.24	13.47	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.83	14.88	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:08:3	29.99	2061	2.24	13.47	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.83	14.89	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:08:3	29.99	2056	2.24	13.46	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.83	14.89	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:08:3	29.99	2056	2.24	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.84	14.9	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:08:3	29.99	2049	2.24	13.45	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.85	14.89	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:08:4	29.99	2056	2.24	13.44	98	196	Off Idle	85.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.85	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:4	29.99	2055	2.24	13.45	98	196	Off Idle	85.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.85	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:4	29.99	2078	2.24	13.43	98	196	Off Idle	85.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.86	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:4	29.99	2072	2.24	13.43	98	196	Off Idle	85.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-3.82	14.89	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:4	29.99	2072	2.24	13.41	98	196	Off Idle	85.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-3.82	14.86	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:4	29.99	2088	2.24	13.41	98	196	Off Idle	85.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-3.82	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:4	29.99	2109	2.24	13.4	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.81	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:5	31.36	2106	2.24	13.4	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.85	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:5	31.36	2106	2.24	13.43	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.91	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:5	31.36	2107	2.24	13.44	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-3.94	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:5	31.36	2108	2.24	13.45	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.96	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:5	31.36	2091	2.24	13.46	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.99	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:08:5	31.36	2104	2.24	13.46	98	196	Off Idle	85.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.02	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:08:6	31.36	2095	2.23	13.47	98	196	Off Idle	85.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.04	15.01	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:08:6	29.99	2099	2.23	13.46	98	196	Off Idle	85.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.06	15.05	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:08:6	29.99	2099	2.23	13.46	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-4.11	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:08:6	29.99	2099	2.22	13.44	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.14	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:08:6	29.99	2108	2.21	13.43	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.26	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:08:6	29.99	2114	2.21	13.44	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.32	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:08:6	29.99	2116	2.2	13.44	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.41	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:08:7	29.99	2126	2.2	13.46	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.49	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:08:7	31.36	2129	2.19	13.46	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.61	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:08:7	31.36	2122	2.18	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.68	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:08:7	31.36	2123	2.17	13.46	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.76	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:08:7	31.36	2124	2.16	13.45	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.86	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:08:7	31.36	2132	2.14	13.43	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.96	14.72	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:08:8	31.36	2132	2.13	13.41	98	196	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.05	14.66	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:08:8	31.36	2120	2.12	13.4	98	196	Off Idle	85.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.25	14.61	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:08:8	31.36	2104	2.11	13.41	98	196	Off Idle	85.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.33	14.61	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:08:8	31.36	2121	2.09	13.41	98	196	Off Idle	85.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.43	14.62	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:08:8	31.36	2130	2.08	13.42	98	196	Off Idle	85.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.57	14.63	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:08:8	31.36	2130	2.07	13.43	98	196	Off Idle	85.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.65	14.65	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:08:9	31.36	2130	2.06	13.46	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.73	14.68	1	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:08:9	31.36	2140	2.04	13.47	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.85	14.7	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:08:9	31.36	2142	2.03	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.91	14.7	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:08:9	31.36	2160	2.02	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.98	14.72	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:08:9	31.36	2153	2.01	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.05	14.74	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:08:9	31.36	2154	2	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.15	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:08:9	31.36	2154	1.99	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.23	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:0	31.36	2172	1.98	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.28	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:0	31.36	2156	1.97	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.34	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:0	31.36	2152	1.96	13.49	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.42	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:0	31.36	2150	1.96	13.49	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.49	15.13	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:0	31.36	2150	1.95	13.49	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.53	15.22	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:0	31.36	2149	1.95	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.58	15.3	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:1	31.36	2150	1.95	13.47	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.6	15.39	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:1	31.36	2148	1.94	13.45	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.58	15.45	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:1	31.36	2149	1.94	13.44	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.57	15.5	1.06	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:1	31.36	2154	1.94	13.45	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.59	15.53	1.06	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:1	31.36	2154	1.93	13.46	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.59	15.54	1.06	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:1	31.36	2163	1.93	13.47	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.61	15.54	1.06	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:1	31.36	2164	1.93	13.48	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.66	15.53	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:2	31.36	2169	1.93	13.47	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.69	15.53	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:2	31.36	2173	1.92	13.45	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.68	15.51	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:2	31.36	2176	1.92	13.45	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.71	15.48	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:2	31.36	2176	1.92	13.45	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.72	15.46	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:2	31.36	2158	1.92	13.45	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.71	15.45	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:2	31.36	2170	1.93	13.45	98	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.71	15.46	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:3	31.36	2168	1.93	13.46	98	196	Off Idle	85.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.7	15.45	1.05	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:3	31.36	2167	1.93	13.45	98	196	Off Idle	85.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.69	15.45	1.05	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:3	31.36	2164	1.93	13.45	98	196	Off Idle	85.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.66	15.45	1.05	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:3	31.36	2164	1.93	13.45	98	196	Off Idle	85.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.65	15.44	1.05	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:3	31.36	2168	1.93	13.45	98	196	Off Idle	85.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.67	15.44	1.05	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:09:3	31.36	2162	1.93	13.45	98	196	Off Idle	85.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.72	15.44	1.05	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:4	31.36	2183	1.93	13.46	98	196	Off Idle	85.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.74	15.44	1.05	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:4	31.36	2191	1.93	13.45	98	197	Off Idle	85.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.75	15.44	1.05	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:4	31.36	2188	1.94	13.43	98	197	Off Idle	84.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.75	15.4	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:4	31.36	2186	1.94	13.45	98	197	Off Idle	84.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.69	15.4	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:4	31.36	2188	1.94	13.46	98	196	Off Idle	84.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.66	15.38	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:4	31.36	2200	1.94	13.44	98	196	Off Idle	84.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.64	15.36	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:4	32.72	2193	1.94	13.44	98	196	Off Idle	84.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.64	15.35	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:5	32.72	2193	1.94	13.44	98	196	Off Idle	84.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.62	15.34	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:5	32.72	2194	1.95	13.44	98	196	Off Idle	84.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.61	15.32	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:5	32.72	2191	1.95	13.44	98	196	Off Idle	84.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.58	15.3	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:09:5	32.72	2185	1.95	13.44	98	196	Off Idle	83.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.55	15.28	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:09:5	32.72	2185	1.96	13.46	98	196	Off Idle	83.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.51	15.24	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:09:5	32.72	2192	1.96	13.46	98	196	Off Idle	83.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.5	15.23	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:6	32.72	2198	1.97	13.45	98	196	Off Idle	83.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.45	15.21	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:6	32.72	2203	1.97	13.45	98	196	Off Idle	83.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.4	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:6	32.72	2205	1.98	13.45	98	197	Off Idle	83.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.37	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:6	32.72	2206	1.98	13.45	98	197	Off Idle	83.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.36	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:6	32.72	2200	1.98	13.45	98	197	Off Idle	83.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.33	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:09:6	32.72	2200	1.99	13.46	98	196	Off Idle	83.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.26	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:09:6	32.72	2204	2	13.46	98	196	Off Idle	83.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.23	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:09:7	32.72	2206	2	13.47	98	196	Off Idle	83.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.19	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:09:7	32.72	2209	2.01	13.48	98	196	Off Idle	83.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.17	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:7	32.72	2209	2.01	13.46	98	196	Off Idle	83.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.18	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:7	32.72	2212	2.02	13.45	98	196	Off Idle	83.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.17	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:7	32.72	2203	2.02	13.44	98	196	Off Idle	83.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.06	14.98	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:7	32.72	2203	2.03	13.44	98	196	Off Idle	82.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.09	14.95	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:8	32.72	2229	2.03	13.44	98	196	Off Idle	82.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.02	14.93	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:8	32.72	2232	2.04	13.45	98	196	Off Idle	82.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.99	14.92	1.02	3.3	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:8	32.72	2233	2.04	13.45	98	196	Off Idle	82.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6	14.92	1.02	3.3	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:09:8	32.72	2233	2.04	13.45	98	196	Off Idle	82.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6	14.91	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:09:8	32.72	2251	2.05	13.46	98	196	Off Idle	82.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.98	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:09:8	32.72	2231	2.05	13.46	98	196	Off Idle	82.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.95	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:9	32.72	2231	2.06	13.46	98	196	Off Idle	82.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.98	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:9	32.72	2231	2.06	13.45	98	196	Off Idle	82.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.97	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:9	32.72	2228	2.06	13.44	98	196	Off Idle	82.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.92	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:9	32.72	2229	2.07	13.44	98	196	Off Idle	82	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.91	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:9	32.72	2232	2.07	13.45	98	196	Off Idle	81.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.85	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:9	32.72	2232	2.07	13.45	98	196	Off Idle	81.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.83	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:09:9	32.72	2216	2.07	13.46	98	196	Off Idle	81.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.86	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:0	32.72	2236	2.07	13.46	98	196	Off Idle	81.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.88	15.11	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:0	32.72	2233	2.08	13.45	98	196	Off Idle	81.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.82	15.11	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:0	32.72	2234	2.08	13.47	98	196	Off Idle	81.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.81	15.13	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:0	32.72	2235	2.08	13.47	98	196	Off Idle	81.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.82	15.12	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:0	32.72	2257	2.08	13.46	98	196	Off Idle	81.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.81	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:0	32.72	2249	2.08	13.46	98	196	Off Idle	81.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.83	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:1	32.72	2259	2.08	13.46	98	196	Off Idle	81.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.87	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:10:1	32.72	2259	2.08	13.47	98	196	Off Idle	81.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.88	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:10:1	32.72	2260	2.08	13.47	98	196	Off Idle	81.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.88	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:10:1	32.72	2270	2.08	13.48	98	196	Off Idle	81.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.91	14.97	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:10:1	32.72	2274	2.08	13.48	98	196	Off Idle	81	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.94	14.93	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:10:1	32.72	2274	2.08	13.49	98	196	Off Idle	80.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.95	14.88	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:1	32.72	2272	2.08	13.49	98	196	Off Idle	80.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.95	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:2	32.72	2305	2.08	13.49	98	196	Off Idle	80.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.96	14.82	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:10:2	32.72	2265	2.08	13.47	98	196	Off Idle	80.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.98	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:2	32.72	2265	2.08	13.46	98	196	Off Idle	80.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.97	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:2	32.72	2258	2.08	13.44	98	196	Off Idle	79.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.9	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:2	32.72	2239	2.08	13.43	98	196	Off Idle	79.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.91	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:2	32.72	2256	2.08	13.41	98	196	Off Idle	79.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.91	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:3	32.72	2258	2.09	13.44	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.9	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:3	32.72	2258	2.09	13.44	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.91	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:3	32.72	2265	2.09	13.46	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.93	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:3	32.72	2287	2.09	13.48	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.95	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:3	32.72	2278	2.09	13.49	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.91	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:3	32.72	2278	2.09	13.48	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.94	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:10:4	32.72	2282	2.09	13.46	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.96	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:10:4	32.72	2287	2.09	13.44	98	196	Off Idle	79.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.99	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:4	32.72	2292	2.09	13.44	98	196	Off Idle	79.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.98	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:4	32.72	2294	2.09	13.44	98	196	Off Idle	79.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:4	32.72	2298	2.09	13.46	98	196	Off Idle	79.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.02	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:4	32.72	2299	2.08	13.47	98	196	Off Idle	79.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.06	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:4	32.72	2297	2.08	13.46	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.14	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:10:5	32.72	2295	2.08	13.46	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.2	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:10:5	32.72	2297	2.07	13.45	98	196	Off Idle	79.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.29	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:10:5	32.72	2298	2.07	13.44	98	196	Off Idle	78.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.37	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:10:5	32.72	2298	2.06	13.45	98	196	Off Idle	78.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.47	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:10:5	32.72	2297	2.05	13.46	98	196	Off Idle	78.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.56	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:10:5	32.72	2298	2.04	13.45	98	196	Off Idle	78.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.66	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:6	32.72	2298	2.03	13.44	98	196	Off Idle	78.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.65	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:6	32.72	2298	2.02	13.45	98	196	Off Idle	78.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.75	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:6	32.72	2298	2.01	13.47	98	196	Off Idle	77.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.8	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:6	32.72	2298	2	13.48	98	196	Off Idle	77.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.85	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:6	32.72	2295	1.99	13.46	98	196	Off Idle	77.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.92	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:6	32.72	2296	1.98	13.46	98	196	Off Idle	77.4	0	2	132	944 Turbo	0.69	Lean	1	14.6	-6.93	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:6	32.72	2292	1.98	13.46	98	196	Off Idle	77.5	0	2	132	944 Turbo	0.72	Lean	1	14.6	-6.94	15.13	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:7	32.72	2292	1.97	13.45	98	196	Off Idle	77.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.96	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:7	32.72	2296	1.96	13.45	98	196	Off Idle	77.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.01	15.15	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:7	32.72	2303	1.95	13.46	98	196	Off Idle	77.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.08	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:10:7	34.08	2304	1.94	13.47	98	196	Off Idle	77.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.14	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:7	34.08	2304	1.94	13.47	98	196	Off Idle	77.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.19	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:7	34.08	2308	1.93	13.48	98	196	Off Idle	77.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.25	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:8	34.08	2321	1.93	13.48	98	196	Off Idle	77.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.25	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:8	34.08	2321	1.92	13.48	98	196	Off Idle	77.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.25	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:8	34.08	2326	1.92	13.46	98	196	Off Idle	77.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.32	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:8	34.08	2325	1.92	13.46	98	196	Off Idle	77.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.35	14.79	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:8	34.08	2325	1.92	13.45	98	196	Off Idle	76.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.38	14.78	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:8	34.08	2326	1.92	13.44	98	196	Off Idle	76.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.4	14.78	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:9	34.08	2329	1.92	13.45	98	196	Off Idle	76.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.37	14.78	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:10:9	34.08	2320	1.92	13.44	98	196	Off Idle	76.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.41	14.77	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:9	34.08	2320	1.92	13.46	98	196	Off Idle	76	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.42	14.76	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:9	34.08	2326	1.91	13.46	98	196	Off Idle	76	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.4	14.78	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:9	34.08	2334	1.92	13.47	98	196	Off Idle	76	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.42	14.81	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:9	34.08	2323	1.92	13.45	98	196	Off Idle	75.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.43	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:10:9	34.08	2322	1.92	13.44	98	196	Off Idle	75.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.41	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:0	34.08	2321	1.92	13.44	98	196	Off Idle	75.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.4	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:0	34.08	2326	1.92	13.43	98	196	Off Idle	75.7	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.37	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:0	34.08	2330	1.92	13.43	98	196	Off Idle	75.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.38	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:0	34.08	2333	1.92	13.43	98	196	Off Idle	75.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.31	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:0	34.08	2334	1.92	13.44	98	196	Off Idle	75.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.26	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:0	34.08	2337	1.93	13.45	98	196	Off Idle	75.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.25	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:1	34.08	2340	1.93	13.45	98	196	Off Idle	75.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.21	15.14	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:1	34.08	2340	1.93	13.45	98	196	Off Idle	75.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.23	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:1	34.08	2340	1.93	13.46	98	196	Off Idle	75.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.22	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:1	34.08	2339	1.93	13.45	98	196	Off Idle	75.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.24	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:1	34.08	2338	1.94	13.45	98	196	Off Idle	75.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.29	15.14	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:1	34.08	2359	1.94	13.44	98	196	Off Idle	75.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.3	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:1	34.08	2359	1.94	13.45	98	196	Off Idle	75.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.28	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:2	34.08	2342	1.94	13.45	98	196	Off Idle	75.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.23	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:11:2	34.08	2346	1.95	13.47	98	196	Off Idle	75.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.2	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:2	34.08	2346	1.95	13.46	98	196	Off Idle	75.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.2	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:2	34.08	2337	1.95	13.46	98	196	Off Idle	75.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.16	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:2	34.08	2346	1.95	13.47	98	196	Off Idle	75.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.15	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:2	34.08	2344	1.95	13.46	98	196	Off Idle	75.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.17	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:3	34.08	2325	1.95	13.47	98	196	Off Idle	75.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.16	14.78	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:3	34.08	2325	1.96	13.49	98	196	Off Idle	75.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.16	14.75	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:3	34.08	2347	1.96	13.48	98	196	Off Idle	75.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.17	14.74	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:3	34.08	2343	1.96	13.47	98	196	Off Idle	75.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.16	14.73	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:11:3	34.08	2343	1.96	13.46	98	196	Off Idle	75.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.16	14.73	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:11:3	34.08	2360	1.96	13.45	98	196	Off Idle	75.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.2	14.72	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:11:4	34.08	2348	1.96	13.46	98	196	Off Idle	75.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.18	14.74	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:11:4	34.08	2348	1.97	13.46	98	196	Off Idle	75.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.18	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:4	34.08	2348	1.97	13.46	98	196	Off Idle	75.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.14	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:4	34.08	2352	1.97	13.46	98	196	Off Idle	75	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.15	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:4	34.08	2351	1.97	13.46	98	196	Off Idle	75	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.14	14.9	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:4	34.08	2353	1.97	13.45	98	196	Off Idle	75	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.12	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:4	34.08	2358	1.97	13.46	98	196	Off Idle	75	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.1	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:5	34.08	2361	1.97	13.44	98	196	Off Idle	75	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.08	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:5	34.08	2361	1.98	13.45	98	196	Off Idle	74.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.05	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:5	34.08	2365	1.98	13.46	98	196	Off Idle	74.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.05	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:5	34.08	2365	1.98	13.45	98	196	Off Idle	74.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.02	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:5	34.08	2366	1.98	13.46	98	196	Off Idle	74.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.98	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:5	34.08	2367	1.99	13.47	98	196	Off Idle	74.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.96	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:6	34.08	2389	1.99	13.46	98	196	Off Idle	74.3	0	2	132	944 Turbo	0.7	Lean	1	14.6	-6.93	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:6	34.08	2373	2	13.47	98	196	Off Idle	74.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.88	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:11:6	34.08	2370	2	13.47	98	196	Off Idle	74.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.87	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:11:6	34.08	2370	2.01	13.45	98	196	Off Idle	74.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.84	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:11:6	34.08	2370	2.01	13.45	98	196	Off Idle	74.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.75	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:11:6	34.08	2374	2.02	13.46	98	196	Off Idle	74.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.7	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:11:6	34.08	2374	2.02	13.44	98	196	Off Idle	74.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.65	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:11:7	34.08	2377	2.03	13.45	98	196	Off Idle	73.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.54	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:11:7	34.08	2379	2.04	13.47	98	196	Off Idle	73.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.45	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:11:7	34.08	2368	2.05	13.46	98	196	Off Idle	73.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.4	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:11:7	32.72	2368	2.06	13.45	98	196	Off Idle	73.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.32	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:11:7	32.72	2393	2.07	13.47	98	196	Off Idle	73.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.21	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:11:7	32.72	2398	2.08	13.47	98	196	Off Idle	73.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.14	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:11:8	32.72	2395	2.09	13.47	98	196	Off Idle	73.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.12	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:11:8	32.72	2396	2.1	13.47	98	196	Off Idle	73.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.11	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:11:8	32.72	2396	2.11	13.46	98	196	Off Idle	73.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.08	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:11:8	32.72	2395	2.12	13.45	98	196	Off Idle	73	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.03	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:11:8	32.72	2397	2.13	13.43	98	196	Off Idle	72.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.99	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:11:8	32.72	2398	2.14	13.43	98	196	Off Idle	72.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.92	15.2	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:11:9	32.72	2398	2.15	13.44	98	196	Off Idle	72.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.88	15.23	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:11:9	32.72	2398	2.16	13.45	98	196	Off Idle	72.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.83	15.26	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:11:9	32.72	2405	2.17	13.43	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.78	15.27	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:11:9	32.72	2400	2.18	13.45	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.68	15.25	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:11:9	32.72	2400	2.19	13.47	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.66	15.24	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:11:9	32.72	2400	2.19	13.47	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.65	15.25	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:11:9	32.72	2403	2.2	13.47	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.64	15.24	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:0	32.72	2404	2.2	13.47	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.66	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:0	32.72	2403	2.2	13.45	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.65	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:0	32.72	2407	2.21	13.46	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.6	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:0	32.72	2411	2.21	13.46	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.56	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:0	32.72	2411	2.21	13.46	98	196	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.54	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:0	32.72	2421	2.22	13.46	98	196	Off Idle	72.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.51	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:1	32.72	2432	2.22	13.45	98	196	Off Idle	72.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.46	14.91	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:1	32.72	2437	2.23	13.46	98	196	Off Idle	72	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.42	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:1	32.72	2437	2.23	13.45	98	196	Off Idle	71.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.38	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:1	32.72	2436	2.23	13.45	98	196	Off Idle	71.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.31	14.75	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:12:1	32.72	2433	2.24	13.44	98	196	Off Idle	71.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.33	14.75	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:1	32.72	2433	2.24	13.43	98	196	Off Idle	71.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.32	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:1	32.72	2434	2.25	13.44	98	196	Off Idle	71.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.3	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:2	32.72	2430	2.25	13.43	98	196	Off Idle	70.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.25	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:2	32.72	2433	2.26	13.45	98	196	Off Idle	70.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.2	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:2	32.72	2440	2.26	13.46	98	196	Off Idle	70.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.18	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:2	32.72	2440	2.27	13.44	98	196	Off Idle	70.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.2	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:2	32.72	2448	2.27	13.44	98	196	Off Idle	70.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.14	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:2	32.72	2448	2.27	13.46	98	196	Off Idle	70.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.13	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:12:3	32.72	2458	2.28	13.45	98	196	Off Idle	70.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.17	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:12:3	32.72	2459	2.28	13.44	98	196	Off Idle	70.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.1	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:3	32.72	2461	2.29	13.46	98	196	Off Idle	70	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.11	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:3	32.72	2461	2.29	13.46	98	196	Off Idle	69.9	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.13	15.01	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:3	32.72	2462	2.3	13.46	98	196	Off Idle	69.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.1	15.07	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:3	32.72	2464	2.3	13.45	98	196	Off Idle	69.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.05	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:4	32.72	2468	2.31	13.45	98	196	Off Idle	69.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.01	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:4	32.72	2468	2.31	13.46	98	196	Off Idle	69.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.97	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:4	32.72	2473	2.31	13.46	98	196	Off Idle	69.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.95	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:4	32.72	2478	2.31	13.47	98	196	Off Idle	68.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.89	15.06	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:4	32.72	2476	2.32	13.47	98	196	Off Idle	68.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.81	15.02	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:4	32.72	2478	2.32	13.47	98	196	Off Idle	68.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.8	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:4	32.72	2478	2.33	13.46	98	196	Off Idle	68.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.8	14.93	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:5	32.72	2478	2.33	13.45	98	196	Off Idle	68.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.77	14.9	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:5	32.72	2476	2.34	13.45	98	196	Off Idle	68.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.79	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:12:5	32.72	2481	2.34	13.47	98	196	Off Idle	68	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.73	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:5	32.72	2485	2.34	13.47	98	196	Off Idle	67.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.69	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:12:5	32.72	2491	2.35	13.48	98	196	Off Idle	67.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.66	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:5	32.72	2495	2.35	13.48	98	196	Off Idle	67.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.61	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:6	32.72	2496	2.36	13.48	98	196	Off Idle	67.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.59	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:6	32.72	2510	2.36	13.47	98	196	Off Idle	67.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.6	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:6	32.72	2510	2.37	13.47	98	196	Off Idle	67.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.54	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:12:6	32.72	2511	2.37	13.45	98	196	Off Idle	67.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.5	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:6	32.72	2511	2.38	13.45	98	196	Off Idle	67.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.5	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:6	32.72	2516	2.38	13.44	98	196	Off Idle	66.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.52	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:6	32.72	2518	2.39	13.44	98	196	Off Idle	66.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.5	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:7	32.72	2519	2.39	13.46	98	196	Off Idle	66.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.46	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:12:7	32.72	2520	2.4	13.47	98	196	Off Idle	66.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.44	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:12:7	32.72	2527	2.41	13.47	98	196	Off Idle	66.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.39	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:12:7	32.72	2532	2.41	13.47	98	196	Off Idle	66.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.36	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:12:7	32.72	2537	2.42	13.47	98	196	Off Idle	65.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.34	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:7	32.72	2538	2.42	13.45	98	196	Off Idle	65.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.3	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:8	32.72	2538	2.43	13.46	98	196	Off Idle	65	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.33	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:8	32.72	2558	2.43	13.46	98	196	Off Idle	64.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.32	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:8	32.72	2535	2.44	13.46	98	196	Off Idle	64.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.28	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:8	32.72	2534	2.44	13.46	98	196	Off Idle	64.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.25	15.04	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:8	32.72	2536	2.45	13.46	98	196	Off Idle	64.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.23	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:8	32.72	2536	2.45	13.45	98	196	Off Idle	64.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.22	15.04	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:9	32.72	2540	2.46	13.44	98	196	Off Idle	64.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.22	15.01	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:9	32.72	2544	2.46	13.43	98	196	Off Idle	64.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.17	14.97	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:9	32.72	2553	2.46	13.44	98	196	Off Idle	64.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.16	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:9	32.72	2559	2.47	13.45	98	196	Off Idle	64	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.14	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:9	32.72	2568	2.47	13.45	98	196	Off Idle	63.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.14	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:9	32.72	2568	2.47	13.45	98	196	Off Idle	63.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.14	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:12:9	32.72	2571	2.47	13.45	98	196	Off Idle	63.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.14	14.72	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:13:0	32.72	2572	2.47	13.44	98	196	Off Idle	63.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.17	14.68	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:13:0	32.72	2572	2.48	13.45	98	196	Off Idle	63.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.19	14.66	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:13:0	32.72	2574	2.48	13.44	98	196	Off Idle	63.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.2	14.65	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:0	32.72	2577	2.48	13.45	98	196	Off Idle	63.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.19	14.64	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:0	32.72	2577	2.48	13.44	98	196	Off Idle	63	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.2	14.65	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:13:0	32.72	2578	2.48	13.46	98	196	Off Idle	62.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.2	14.66	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:13:1	32.72	2593	2.48	13.45	98	196	Off Idle	62.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.21	14.68	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:13:1	32.72	2588	2.48	13.46	98	196	Off Idle	62.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.23	14.68	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:13:1	32.72	2591	2.48	13.46	98	196	Off Idle	61.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.25	14.69	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:1	32.72	2598	2.48	13.46	98	196	Off Idle	61.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.23	14.71	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:1	32.72	2603	2.48	13.46	98	196	Off Idle	61.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.25	14.71	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:1	32.72	2603	2.48	13.47	98	196	Off Idle	61.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.23	14.72	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:1	32.72	2606	2.48	13.45	98	196	Off Idle	61.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.25	14.75	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:2	32.72	2603	2.48	13.46	98	196	Off Idle	61.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.26	14.77	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:2	32.72	2603	2.48	13.46	98	196	Off Idle	61.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.31	14.78	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:2	32.72	2602	2.48	13.44	98	196	Off Idle	61.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.35	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:2	34.08	2614	2.48	13.44	98	196	Off Idle	61.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.37	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:2	34.08	2612	2.48	13.44	98	196	Off Idle	61.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.38	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:2	34.08	2612	2.48	13.45	98	196	Off Idle	61.2	0	2	132	944 Turbo	0.69	Lean	1	14.6	-4.42	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:3	34.08	2635	2.48	13.45	98	196	Off Idle	61.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-4.43	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:3	34.08	2622	2.48	13.45	98	196	Off Idle	61	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.44	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:3	34.08	2628	2.48	13.45	98	196	Off Idle	60.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.44	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:3	34.08	2635	2.48	13.45	98	196	Off Idle	60.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.41	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:3	34.08	2636	2.48	13.45	98	196	Off Idle	60.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.36	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:3	34.08	2642	2.48	13.45	98	196	Off Idle	60.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.36	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:4	34.08	2645	2.48	13.46	98	196	Off Idle	60.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.43	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:4	34.08	2646	2.48	13.46	98	196	Off Idle	59.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.43	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:4	34.08	2645	2.48	13.45	98	196	Off Idle	59.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.45	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:4	34.08	2645	2.48	13.45	98	196	Off Idle	59.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-4.44	14.87	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:4	34.08	2646	2.48	13.45	98	196	Off Idle	58.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-4.42	14.93	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:13:4	34.08	2646	2.48	13.44	98	196	Off Idle	58.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.41	14.97	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:4	34.08	2648	2.48	13.46	98	196	Off Idle	58	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.42	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:5	34.08	2648	2.48	13.46	98	196	Off Idle	57.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.46	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:5	32.72	2631	2.48	13.46	98	196	Off Idle	57.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.43	15.11	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:5	32.72	2655	2.48	13.47	98	196	Off Idle	57.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.43	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:5	32.72	2655	2.48	13.44	98	196	Off Idle	57.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.41	15.18	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:5	32.72	2661	2.48	13.45	98	196	Off Idle	57.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.4	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:5	32.72	2664	2.48	13.45	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.42	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:6	32.72	2664	2.49	13.45	98	196	Off Idle	57.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.43	15.06	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:6	34.08	2668	2.49	13.45	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.43	15.02	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:6	34.08	2664	2.49	13.46	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.45	14.99	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:6	34.08	2685	2.49	13.45	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.45	14.96	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:6	34.08	2670	2.49	13.45	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.43	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:6	34.08	2671	2.49	13.46	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.46	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:13:6	34.08	2677	2.49	13.47	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.44	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:7	34.08	2677	2.49	13.47	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.44	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:7	34.08	2687	2.49	13.48	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.49	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:7	34.08	2683	2.49	13.47	98	196	Off Idle	57.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.46	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:13:7	34.08	2683	2.49	13.46	98	196	Off Idle	56.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.44	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:7	34.08	2694	2.49	13.46	98	196	Off Idle	56.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.44	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:7	32.72	2655	2.5	13.45	98	196	Off Idle	56.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.43	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:8	32.72	2704	2.5	13.45	98	196	Off Idle	56.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.41	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:8	32.72	2704	2.5	13.45	98	196	Off Idle	55.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.4	14.85	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:8	32.72	2706	2.5	13.45	98	196	Off Idle	55.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.39	14.88	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:8	32.72	2719	2.5	13.44	98	196	Off Idle	55.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.43	14.91	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:13:8	32.72	2712	2.5	13.43	98	196	Off Idle	55.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.43	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:8	34.08	2722	2.5	13.43	98	196	Off Idle	55	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.42	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:9	34.08	2714	2.5	13.44	98	196	Off Idle	54.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.4	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:9	34.08	2706	2.51	13.43	98	196	Off Idle	54.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.42	15.06	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:9	34.08	2721	2.51	13.43	98	196	Off Idle	54.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.45	15.13	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:9	34.08	2722	2.51	13.44	98	196	Off Idle	54.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.46	15.16	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:9	34.08	2728	2.51	13.45	98	196	Off Idle	53.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.41	15.15	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:9	34.08	2754	2.51	13.45	98	196	Off Idle	53.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.43	15.11	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:13:9	34.08	2736	2.51	13.46	98	196	Off Idle	53.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.45	15.09	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:0	34.08	2742	2.51	13.46	98	196	Off Idle	53.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.44	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:0	34.08	2735	2.52	13.47	98	196	Off Idle	53.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.43	15	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:0	34.08	2735	2.52	13.47	98	196	Off Idle	53.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.45	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:0	34.08	2726	2.52	13.46	98	196	Off Idle	53.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.41	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:0	34.08	2746	2.52	13.46	98	196	Off Idle	53	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.42	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:1	34.08	2756	2.52	13.46	98	196	Off Idle	52.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.43	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:1	34.08	2758	2.52	13.45	98	196	Off Idle	52.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.43	14.86	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:1	34.08	2767	2.52	13.46	98	196	Off Idle	52.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.43	14.87	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:1	34.08	2769	2.52	13.46	98	196	Off Idle	52.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.44	14.9	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:14:1	34.08	2772	2.53	13.45	98	196	Off Idle	52.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.45	14.94	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:14:1	34.08	2770	2.53	13.44	98	196	Off Idle	52.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.39	14.96	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:1	34.08	2778	2.53	13.45	98	196	Off Idle	52.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.42	14.98	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:2	34.08	2762	2.53	13.46	98	196	Off Idle	52	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.44	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:2	34.08	2756	2.53	13.46	98	196	Off Idle	51.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.4	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:2	34.08	2756	2.53	13.47	98	196	Off Idle	51.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.35	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:2	34.08	2754	2.53	13.45	98	196	Off Idle	51.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.34	15.16	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:2	34.08	2757	2.53	13.45	98	196	Off Idle	51.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.29	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:2	34.08	2762	2.53	13.45	98	196	Off Idle	51.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.28	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:3	34.08	2762	2.54	13.45	98	196	Off Idle	51.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.3	15.06	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:3	34.08	2782	2.54	13.43	98	196	Off Idle	51.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.37	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:3	34.08	2782	2.54	13.43	98	196	Off Idle	51.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.34	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:3	34.08	2802	2.54	13.44	98	196	Off Idle	51.1	0	2	132	944 Turbo	0.57	Lean	1	14.6	-4.35	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:14:3	34.08	2800	2.54	13.45	98	196	Off Idle	51.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.35	14.79	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:14:3	34.08	2801	2.54	13.46	98	196	Off Idle	51.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.35	14.76	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:14:4	34.08	2796	2.54	13.46	98	196	Off Idle	51.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.4	14.74	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:14:4	34.08	2808	2.54	13.47	98	196	Off Idle	51.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.41	14.72	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:14:4	34.08	2807	2.54	13.46	98	196	Off Idle	51.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.41	14.73	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:14:4	34.08	2806	2.54	13.45	98	196	Off Idle	50.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.38	14.74	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:4	34.08	2808	2.54	13.46	98	196	Off Idle	50.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.4	14.77	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:4	34.08	2811	2.54	13.46	98	196	Off Idle	50.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.4	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:4	34.08	2812	2.55	13.44	98	196	Off Idle	50.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.42	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:5	34.08	2814	2.55	13.46	98	196	Off Idle	49.8	0	2	132	944 Turbo	0.34	Rich	1	14.6	-4.4	14.9	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:5	34.08	2813	2.55	13.46	98	196	Off Idle	49.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.39	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:5	34.08	2812	2.55	13.46	98	196	Off Idle	49.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.38	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:5	34.08	2820	2.55	13.45	98	196	Off Idle	49.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.37	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:14:5	34.08	2812	2.55	13.46	98	196	Off Idle	49	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.33	15.09	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:14:5	34.08	2815	2.56	13.46	98	196	Off Idle	49	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.38	15.1	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:14:6	34.08	2817	2.56	13.45	98	196	Off Idle	49	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.33	15.09	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:6	34.08	2824	2.56	13.46	98	196	Off Idle	48.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.28	15.08	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:6	34.08	2827	2.56	13.46	98	196	Off Idle	48.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.26	15.03	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:6	34.08	2828	2.57	13.46	98	196	Off Idle	48.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.2	15	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:6	34.08	2838	2.57	13.46	98	196	Off Idle	48.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.17	14.96	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:6	34.08	2847	2.57	13.47	98	196	Off Idle	48.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.14	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:6	34.08	2857	2.58	13.46	98	196	Off Idle	48.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.11	14.9	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:7	34.08	2857	2.58	13.47	98	196	Off Idle	48.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.14	14.88	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:7	34.08	2860	2.59	13.47	98	196	Off Idle	48.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.13	14.9	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:7	34.08	2860	2.59	13.46	98	196	Off Idle	48.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.14	14.88	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:7	34.08	2874	2.6	13.45	98	196	Off Idle	48.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.12	14.92	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:7	34.08	2874	2.6	13.43	98	196	Off Idle	48.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.07	14.94	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:7	34.08	2856	2.6	13.43	98	196	Off Idle	48.1	0	2	132	944 Turbo	0.57	Lean	1	14.6	-4.03	15.02	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:8	34.08	2856	2.61	13.43	98	196	Off Idle	48	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:8	34.08	2860	2.61	13.43	98	196	Off Idle	47.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.98	15.07	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:8	34.08	2859	2.62	13.44	98	196	Off Idle	47.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.94	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:14:8	34.08	2865	2.62	13.46	98	196	Off Idle	47.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.9	15.03	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:8	34.08	2878	2.63	13.48	98	196	Off Idle	47.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.9	15	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:8	34.08	2889	2.63	13.48	98	196	Off Idle	47.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.85	14.98	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:9	34.08	2889	2.64	13.47	98	196	Off Idle	46.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.84	14.93	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:9	34.08	2906	2.64	13.48	98	196	Off Idle	46.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.82	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:9	34.08	2895	2.64	13.47	98	196	Off Idle	46	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.79	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:9	34.08	2892	2.65	13.45	98	196	Off Idle	45.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.77	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:9	34.08	2892	2.65	13.43	98	196	Off Idle	45.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.74	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:9	34.08	2892	2.65	13.45	98	196	Off Idle	45.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.74	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:14:9	34.08	2897	2.66	13.46	98	196	Off Idle	45.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.73	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:0	34.08	2900	2.66	13.44	98	196	Off Idle	45	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.72	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:0	34.08	2900	2.66	13.45	98	196	Off Idle	44.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.72	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:0	34.08	2906	2.66	13.46	98	196	Off Idle	44.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.75	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:0	34.08	2907	2.66	13.46	98	196	Off Idle	44.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.76	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:0	34.08	2908	2.67	13.47	98	196	Off Idle	44	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.8	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:0	34.08	2913	2.67	13.48	98	196	Off Idle	43.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.82	14.88	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:1	34.08	2919	2.67	13.47	98	196	Off Idle	43.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.82	14.88	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:1	34.08	2919	2.67	13.46	98	196	Off Idle	43.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.82	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:1	34.08	2920	2.67	13.45	98	196	Off Idle	43.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.77	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:1	34.08	2928	2.67	13.46	98	196	Off Idle	43.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.74	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:1	34.08	2932	2.67	13.45	98	196	Off Idle	43.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.78	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:1	34.08	2934	2.67	13.46	98	196	Off Idle	43.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.77	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:1	34.08	2931	2.67	13.48	98	196	Off Idle	43.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.83	14.83	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:2	34.08	2943	2.67	13.46	98	196	Off Idle	43.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-3.91	14.82	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:2	34.08	2948	2.67	13.47	98	196	Off Idle	43.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-3.95	14.83	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:2	34.08	2948	2.67	13.48	98	196	Off Idle	43.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4	14.84	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:2	34.08	2962	2.67	13.48	98	196	Off Idle	43.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.01	14.84	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:2	34.08	2954	2.67	13.48	98	196	Off Idle	43	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.07	14.86	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:15:2	34.08	2954	2.67	13.47	98	196	Off Idle	42.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4	14.88	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:15:3	34.08	2959	2.66	13.46	98	196	Off Idle	42.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.97	14.9	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:3	34.08	2960	2.66	13.45	98	196	Off Idle	42.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.06	14.93	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:15:3	34.08	2976	2.66	13.45	98	196	Off Idle	42.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.05	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:15:3	34.08	2969	2.66	13.45	98	196	Off Idle	42	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.13	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:3	34.08	2970	2.66	13.47	98	196	Off Idle	41.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.19	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:3	34.08	2968	2.65	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.25	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:4	34.08	2968	2.65	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.24	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:4	34.08	2968	2.65	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.25	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:4	34.08	2980	2.64	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.25	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:4	34.08	2970	2.64	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.3	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:4	34.08	2976	2.63	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.39	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:15:4	34.08	2976	2.63	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.46	14.94	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:4	34.08	2981	2.63	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.5	14.91	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:5	34.08	2992	2.62	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.53	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:5	34.08	2992	2.62	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.59	14.79	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:5	34.08	2994	2.61	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.62	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:5	34.08	2979	2.6	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.67	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:15:5	34.08	2990	2.59	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.79	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:15:5	34.08	3010	2.59	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.89	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:15:6	35.45	2999	2.58	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.95	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:15:6	35.45	2997	2.58	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.01	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:15:6	35.45	2997	2.57	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.08	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:15:6	35.45	3003	2.56	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.12	14.97	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:15:6	35.45	2995	2.55	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.21	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:6	35.45	3007	2.54	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.27	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:6	35.45	3008	2.53	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.29	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:15:7	35.45	3012	2.52	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.37	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:15:7	35.45	3016	2.52	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.43	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:7	35.45	3016	2.51	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.48	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:7	35.45	3017	2.5	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.56	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:7	35.45	3012	2.49	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.57	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:15:7	35.45	3012	2.48	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.68	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:15:8	35.45	3018	2.48	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.7	15.09	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:15:8	35.45	3018	2.47	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.81	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:15:8	35.45	3019	2.46	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.83	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:8	35.45	3021	2.45	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.84	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:8	35.45	3020	2.44	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.95	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:8	35.45	3022	2.43	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.99	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:9	35.45	3028	2.43	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.04	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:9	35.45	3032	2.42	13.43	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.08	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:9	35.45	3037	2.42	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.12	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:9	35.45	3036	2.41	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.16	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:9	35.45	3034	2.4	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.17	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:9	35.45	3034	2.4	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.21	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:15:9	35.45	3034	2.39	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.23	15.22	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:16:0	35.45	3033	2.39	13.49	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.28	15.26	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:16:0	35.45	3033	2.38	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.32	15.28	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:16:0	35.45	3041	2.37	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.4	15.28	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:16:0	35.45	3048	2.37	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.44	15.28	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:16:0	35.45	3050	2.36	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.48	15.27	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:16:0	35.45	3053	2.35	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.54	15.26	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:1	35.45	3071	2.35	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.59	15.26	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:16:1	35.45	3053	2.34	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.65	15.24	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:1	35.45	3052	2.34	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.68	15.22	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:16:1	35.45	3046	2.33	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.74	15.2	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:16:1	35.45	3043	2.32	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.79	15.17	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:1	35.45	3045	2.32	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.78	15.15	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:1	35.45	3045	2.31	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.83	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:16:2	35.45	3052	2.31	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.84	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:2	35.45	3030	2.3	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.88	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:2	35.45	3041	2.3	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.92	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:2	35.45	3053	2.29	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.96	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:16:2	35.45	3053	2.29	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.97	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:16:2	35.45	3048	2.28	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.07	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:3	35.45	3044	2.27	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.09	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:3	35.45	3050	2.27	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.12	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:16:3	35.45	3052	2.27	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.11	15.13	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:16:3	35.45	3056	2.26	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.16	15.15	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:16:3	35.45	3064	2.26	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.22	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:16:3	35.45	3066	2.25	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.2	15.14	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:16:4	35.45	3071	2.25	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.25	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:16:4	35.45	3065	2.25	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.27	15.14	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:16:4	35.45	3063	2.24	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.27	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:16:4	35.45	3064	2.24	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.27	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:4	35.45	3067	2.23	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.37	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:4	35.45	3057	2.23	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.37	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:4	35.45	3060	2.22	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.47	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:5	35.45	3059	2.22	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.46	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:5	35.45	3060	2.21	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.49	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:5	35.45	3058	2.21	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.54	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:5	35.45	3070	2.2	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.57	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:5	35.45	3057	2.2	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.61	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:5	35.45	3056	2.19	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.65	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:6	35.45	3058	2.19	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:6	35.45	3056	2.19	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:6	35.45	3056	2.18	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:6	35.45	3060	2.18	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.69	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:6	35.45	3091	2.18	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.69	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:6	36.81	3091	2.17	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.76	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:6	36.81	3072	2.17	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.73	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:7	36.81	3075	2.16	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.74	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:7	36.81	3078	2.16	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.74	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:7	36.81	3094	2.16	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.72	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:16:7	36.81	3088	2.15	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:7	36.81	3089	2.15	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.82	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:7	36.81	3082	2.15	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.88	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:8	36.81	3082	2.14	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.89	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:16:8	36.81	3080	2.14	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.94	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:16:8	36.81	3073	2.13	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.01	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:16:8	36.81	3086	2.12	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.06	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:16:8	36.81	3066	2.11	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.2	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:16:8	36.81	3053	2.11	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.21	15.17	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:16:9	36.81	3052	2.1	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.21	15.18	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:16:9	36.81	3050	2.09	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.24	15.16	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:16:9	36.81	3048	2.08	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.26	15.19	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:16:9	36.81	3046	2.08	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.32	15.17	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:16:9	36.81	3046	2.07	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.34	15.16	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:16:9	36.81	3047	2.06	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:16:9	36.81	3047	2.06	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.43	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:0	36.81	3054	2.05	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.45	15.05	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:0	36.81	3032	2.04	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.43	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:0	36.81	3044	2.03	13.43	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.45	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:0	36.81	3062	2.02	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.46	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:0	36.81	3070	2.02	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.46	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:0	36.81	3067	2.01	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.47	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:1	36.81	3070	2.01	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.52	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:17:1	36.81	3072	2	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.55	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:1	36.81	3078	2	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.59	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:1	36.81	3086	2	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.59	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:1	36.81	3086	2	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.61	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:1	36.81	3089	1.99	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.6	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:1	36.81	3086	1.99	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.59	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:2	36.81	3089	1.99	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.62	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:2	36.81	3088	1.99	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.62	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:2	36.81	3084	1.99	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.64	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:17:2	36.81	3075	1.99	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.69	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:2	36.81	3073	1.98	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.71	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:2	36.81	3073	1.98	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.74	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:3	36.81	3059	1.98	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.77	15.15	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:3	36.81	3051	1.97	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.76	15.15	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:3	36.81	3050	1.97	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.78	15.15	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:3	36.81	3048	1.97	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.81	15.14	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:3	36.81	3047	1.96	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.87	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:3	36.81	3046	1.96	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.85	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:4	36.81	3050	1.96	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.91	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:4	36.81	3051	1.95	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.97	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:4	36.81	3053	1.95	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.97	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:4	36.81	3054	1.95	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.94	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:4	36.81	3044	1.94	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.95	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:4	36.81	3058	1.94	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.98	15.04	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:4	36.81	3060	1.94	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.94	15.04	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:5	36.81	3062	1.93	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.94	15.03	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:5	36.81	3066	1.93	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.93	15.01	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:5	36.81	3091	1.93	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.96	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:5	36.81	3071	1.93	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.93	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:5	36.81	3070	1.93	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.94	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:5	36.81	3070	1.93	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.96	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:6	36.81	3049	1.93	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.01	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:6	36.81	3069	1.93	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.02	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:6	36.81	3071	1.92	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.02	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:6	36.81	3071	1.92	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.04	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:6	36.81	3064	1.92	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.04	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:6	36.81	3066	1.92	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.04	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:6	36.81	3065	1.92	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.06	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:7	36.81	3062	1.92	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.09	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:7	36.81	3072	1.92	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.07	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:7	36.81	3059	1.92	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.1	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:7	36.81	3058	1.92	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.06	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:7	36.81	3050	1.92	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.12	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:7	36.81	3042	1.91	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.07	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:8	36.81	3030	1.91	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.12	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:8	36.81	3030	1.91	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.13	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:8	36.81	3032	1.91	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.14	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:8	36.81	3009	1.91	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.17	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:8	36.81	3021	1.91	13.45	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.17	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:8	36.81	3035	1.91	13.45	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.13	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:9	36.81	3029	1.91	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.14	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:9	36.81	3034	1.9	13.44	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.16	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:9	36.81	3034	1.9	13.43	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.17	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:9	36.81	3034	1.9	13.44	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.16	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:17:9	36.81	3038	1.9	13.44	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.2	14.79	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:9	36.81	3037	1.9	13.45	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.17	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:17:9	36.81	3039	1.9	13.45	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.14	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:0	36.81	3038	1.9	13.45	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.15	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:18:0	36.81	3042	1.9	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.18	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:0	36.81	3046	1.89	13.45	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.15	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:0	36.81	3048	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.19	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:0	36.81	3048	1.89	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.18	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:0	36.81	3048	1.89	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.17	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:1	36.81	3072	1.89	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.16	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:1	36.81	3060	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.18	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:1	36.81	3042	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.18	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:1	36.81	3057	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.2	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:1	36.81	3020	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.2	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:1	36.81	3020	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.24	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:1	36.81	3040	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.21	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:2	36.81	3041	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.22	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:2	36.81	3042	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.2	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:2	36.81	3026	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.19	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:2	36.81	3038	1.89	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.16	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:2	36.81	3036	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.17	15.03	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:2	36.81	3038	1.89	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.15	15.01	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:3	36.81	3066	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.16	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:3	36.81	3044	1.89	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.16	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:3	36.81	3051	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Rich	1	14.6	-9.18	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:3	36.81	3050	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Rich	1	14.6	-9.24	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:3	36.81	3030	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.2	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:3	36.81	3058	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.22	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:4	36.81	3050	1.89	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.2	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:4	36.81	3050	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.2	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:4	36.81	3060	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.18	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:4	36.81	3060	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.23	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:4	36.81	3060	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.21	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:4	36.81	3056	1.89	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.23	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:4	36.81	3067	1.89	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.24	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:5	36.81	3044	1.89	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.26	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:5	36.81	3044	1.89	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.22	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:5	36.81	3018	1.89	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.23	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:5	36.81	3043	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.2	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:5	36.81	3043	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.21	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:6	36.81	3038	1.89	13.44	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.2	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:6	36.81	3036	1.89	13.44	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.19	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:6	36.81	3031	1.89	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.2	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:6	36.81	3028	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.21	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:6	36.81	3023	1.89	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.2	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:6	36.81	3022	1.89	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.2	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:6	36.81	3014	1.89	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.22	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:6	36.81	3018	1.89	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.17	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:7	36.81	3016	1.89	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.18	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:7	36.81	3014	1.89	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.18	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:7	36.81	3014	1.89	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.2	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:7	36.81	3017	1.89	13.49	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.19	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:7	36.81	3017	1.89	13.49	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.17	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:7	36.81	3017	1.89	13.49	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.17	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:8	36.81	3006	1.89	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.15	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:8	36.81	3022	1.89	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.15	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:8	36.81	3022	1.89	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.15	14.82	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:18:8	36.81	3028	1.89	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.2	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:8	36.81	3030	1.89	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.15	14.87	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:8	36.81	3035	1.89	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.16	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:9	36.81	3036	1.89	13.46	98	196	Off Idle	41.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.16	14.91	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:9	36.81	3048	1.89	13.46	98	196	Off Idle	41.7	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.2	14.94	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:18:9	36.81	3026	1.89	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.15	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:9	36.81	3026	1.89	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.19	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:9	36.81	3036	1.89	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.22	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:9	36.81	3034	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Lean	1	14.6	-9.2	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:18:9	36.81	3031	1.89	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.21	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:0	36.81	3031	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.2	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:0	36.81	3026	1.89	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.21	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:0	36.81	3022	1.89	13.44	98	196	Off Idle	41.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.25	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:0	36.81	3018	1.89	13.45	98	196	Off Idle	41.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.25	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:0	36.81	3018	1.89	13.46	98	196	Off Idle	41.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.25	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:0	36.81	3021	1.89	13.45	98	196	Off Idle	41.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.25	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:1	36.81	3024	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.18	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:1	36.81	3024	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.19	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:1	36.81	3025	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Rich	1	14.6	-9.21	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:1	36.81	3028	1.89	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.21	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:1	36.81	3021	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.21	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:1	36.81	3021	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.26	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:1	36.81	3022	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.27	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:2	36.81	3022	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.26	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:2	36.81	3012	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.25	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:2	36.81	3020	1.88	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.27	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:2	36.81	3018	1.88	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.22	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:2	36.81	3014	1.88	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.17	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:2	36.81	3028	1.88	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.19	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:3	36.81	3015	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.16	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:3	36.81	3016	1.88	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.14	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:3	36.81	3010	1.88	13.5	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.16	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:3	36.81	3009	1.88	13.49	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.16	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:3	36.81	3008	1.88	13.49	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.16	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:3	36.81	3008	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.17	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:4	36.81	3002	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.17	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:4	36.81	2998	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.21	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:4	36.81	2998	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.23	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:4	36.81	2997	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.23	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:4	36.81	2994	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.22	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:4	36.81	2996	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.22	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:4	36.81	2999	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.17	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:5	36.81	2999	1.88	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.16	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:5	36.81	3000	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.15	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:5	36.81	2977	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.14	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:5	36.81	3004	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.14	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:5	36.81	3004	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.19	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:5	36.81	3004	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.18	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:6	36.81	3010	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.19	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:6	36.81	3000	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.2	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:6	36.81	3001	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.2	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:6	36.81	3002	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.2	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:6	36.81	2994	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.21	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:6	36.81	3003	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.22	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:6	36.81	3004	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.25	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:7	36.81	3008	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.25	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:7	36.81	3006	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Lean	1	14.6	-9.22	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:7	36.81	3006	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.22	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:7	36.81	3009	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.19	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:7	36.81	3010	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.18	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:7	36.81	3010	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.18	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:8	36.81	3009	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.18	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:8	36.81	2999	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.18	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:19:8	36.81	3000	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.19	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:8	36.81	3004	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.22	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:8	36.81	3008	1.88	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.21	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:8	36.81	3007	1.88	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.23	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:9	36.81	3007	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.25	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:9	36.81	3009	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.25	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:19:9	36.81	3014	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.21	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:9	36.81	3016	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.21	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:9	36.81	3016	1.88	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.18	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:9	36.81	3013	1.88	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.18	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:19:9	36.81	3017	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.21	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:0	36.81	3017	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.21	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:0	36.81	3019	1.88	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.23	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:0	36.81	3019	1.88	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.25	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:0	36.81	3020	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.24	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:0	36.81	3022	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.21	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:0	36.81	3023	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.23	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:1	36.81	3025	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.21	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:1	36.81	3026	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.25	14.93	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:1	36.81	3024	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.27	14.99	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:1	36.81	3017	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.25	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:1	36.81	3011	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.25	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:1	36.81	3030	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.29	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:1	36.81	3017	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.23	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:2	36.81	2995	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.25	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:2	36.81	2977	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.25	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:2	36.81	2981	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.22	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:2	36.81	2971	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.2	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:2	36.81	2971	1.88	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.18	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:2	36.81	2971	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.15	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:3	36.81	2976	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.17	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:3	36.81	2976	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.19	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:3	36.81	2981	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.18	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:3	36.81	2985	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.17	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:3	36.81	2989	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.17	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:3	36.81	2990	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.12	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:4	36.81	2992	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.14	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:4	36.81	2998	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.12	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:4	36.81	2999	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.14	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:4	36.81	2999	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.14	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:4	36.81	3004	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.16	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:4	36.81	3000	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.18	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:4	36.81	2988	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.23	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:5	36.81	2994	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.17	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:5	36.81	2986	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.18	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:5	36.81	2980	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.2	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:5	36.81	2980	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.2	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:5	36.81	2976	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.16	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:5	36.81	2974	1.88	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.22	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:6	36.81	2975	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.15	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:6	36.81	2975	1.88	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.15	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:6	36.81	2978	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.16	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:6	36.81	2972	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.15	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:6	36.81	2972	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.15	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:6	36.81	2970	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.16	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:6	36.81	2977	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.15	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:7	36.81	2978	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.14	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:7	36.81	2980	1.88	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.14	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:20:7	36.81	2983	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.15	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:7	36.81	2983	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.15	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:7	36.81	2986	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.18	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:7	36.81	2986	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.21	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:8	36.81	2987	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.19	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:8	36.81	2986	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.19	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:8	36.81	2974	1.88	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.16	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:8	36.81	2976	1.88	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.14	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:8	36.81	2976	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.17	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:20:8	36.81	2965	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.18	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:9	36.81	2975	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.2	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:9	36.81	2963	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.15	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:9	36.81	2963	1.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.14	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:9	36.81	2981	1.88	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.13	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:9	36.81	2961	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.14	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:9	36.81	2962	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.14	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:20:9	36.81	2962	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.16	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:0	36.81	2941	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.18	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:0	36.81	2967	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.19	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:0	36.81	2966	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.17	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:0	36.81	2968	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.16	14.99	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:0	36.81	2982	1.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.18	14.97	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:0	36.81	2973	1.88	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.14	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:1	36.81	2973	1.88	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.14	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:1	36.81	2974	1.88	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.14	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:1	36.81	2988	1.88	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.12	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:1	36.81	2975	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.14	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:1	36.81	2974	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.14	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:1	36.81	2976	1.88	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.14	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:1	36.81	2966	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.13	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:2	36.81	2979	1.88	13.46	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.17	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:2	36.81	2976	1.88	13.47	98	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.18	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:2	36.81	2976	1.88	13.47	98	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.18	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:2	36.81	2975	1.88	13.46	98	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.21	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:2	36.81	2976	1.88	13.47	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.19	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:2	36.81	2977	1.88	13.48	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.19	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:3	36.81	2977	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.2	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:3	36.81	2978	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.2	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:3	36.81	2981	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.18	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:3	36.81	2980	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.22	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:3	36.81	2980	1.88	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.22	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:3	36.81	2969	1.88	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.21	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:4	36.81	2977	1.88	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.2	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:4	36.81	2977	1.88	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.21	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:4	36.81	2976	1.88	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-9.18	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:4	36.81	2974	1.88	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.18	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:21:4	36.81	2991	1.88	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.13	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:4	36.81	2977	1.88	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.14	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:4	36.81	2964	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.13	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:5	36.81	2966	1.88	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.14	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:5	36.81	2968	1.88	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.14	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:5	36.81	2968	1.88	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.11	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:5	36.81	2968	1.89	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.09	14.88	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:5	36.81	2966	1.89	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.09	14.87	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:5	36.81	2966	1.89	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.03	14.86	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:6	36.81	2980	1.9	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.97	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:21:6	36.81	2980	1.9	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.97	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:21:6	36.81	2970	1.9	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.91	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:21:6	36.81	2975	1.91	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.89	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:21:6	36.81	2976	1.91	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.86	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:21:6	36.81	2978	1.92	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.85	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:21:6	36.81	2983	1.93	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.74	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:7	36.81	2996	1.94	13.48	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.69	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:7	36.81	2986	1.94	13.48	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.65	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:7	36.81	2986	1.95	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.59	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:21:7	36.81	2984	1.96	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.58	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:21:7	36.81	2985	1.96	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.54	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:21:7	36.81	2984	1.97	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.56	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:8	36.81	2983	1.98	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.47	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:8	36.81	2976	1.99	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.42	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:8	36.81	2964	2	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.41	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:8	36.81	2979	2.01	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.31	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:8	36.81	2984	2.02	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.27	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:8	36.81	2984	2.03	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.18	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:21:9	36.81	2989	2.03	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.14	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:21:9	36.81	3000	2.04	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.08	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:21:9	36.81	2991	2.05	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.03	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:21:9	36.81	2993	2.06	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.02	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:21:9	36.81	2994	2.06	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.97	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:21:9	36.81	2999	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.83	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:21:9	36.81	3002	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.73	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:22:0	36.81	3007	2.11	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.61	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:22:0	36.81	3006	2.12	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.48	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:22:0	36.81	3012	2.14	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.35	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:22:0	36.81	3014	2.15	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.26	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:0	36.81	3016	2.17	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.17	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:0	36.81	3005	2.18	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.11	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:1	35.45	3033	2.2	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.06	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:1	35.45	3038	2.21	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:1	35.45	3038	2.23	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.96	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:1	35.45	3041	2.24	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.89	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:22:1	35.45	3044	2.25	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.85	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:22:1	35.45	3046	2.26	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.84	15.14	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:1	35.45	3042	2.28	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.78	15.14	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:2	35.45	3040	2.29	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.78	15.14	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:2	35.45	3035	2.3	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.77	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:2	35.45	3036	2.31	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.71	15.15	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:2	35.45	3028	2.32	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.66	15.14	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:2	35.45	3041	2.32	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.61	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:2	35.45	3043	2.33	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.56	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:3	35.45	3038	2.34	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.43	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:22:3	35.45	3040	2.34	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.35	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:22:3	35.45	3040	2.35	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.36	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:22:3	35.45	3040	2.36	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.24	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:22:3	35.45	3042	2.37	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.19	14.76	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:22:3	35.45	3052	2.37	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.12	14.71	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:22:4	35.45	3056	2.39	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.04	14.71	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:4	35.45	3066	2.4	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.89	14.71	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:4	35.45	3070	2.41	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.83	14.72	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:4	35.45	3074	2.43	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.73	14.73	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:22:4	35.45	3110	2.44	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.59	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:22:4	35.45	3092	2.45	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.47	14.79	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:4	35.45	3094	2.47	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.39	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:5	35.45	3100	2.48	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.37	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:22:5	35.45	3100	2.49	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.33	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:22:5	35.45	3101	2.5	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.33	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:22:5	35.45	3099	2.52	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.28	14.86	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:22:5	35.45	3096	2.53	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.19	14.88	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:5	35.45	3078	2.54	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.14	14.9	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:6	35.45	3078	2.55	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.11	14.94	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:6	35.45	3073	2.56	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.06	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:6	35.45	3064	2.57	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.07	15.02	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:6	35.45	3064	2.58	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.05	15.03	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:6	35.45	3053	2.59	13.46	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.04	15.05	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:6	35.45	3071	2.6	13.45	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.02	15.01	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:6	35.45	3092	2.6	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.98	14.95	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:7	35.45	3092	2.6	13.48	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.95	14.87	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:7	35.45	3098	2.6	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.93	14.78	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:7	35.45	3111	2.61	13.45	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.95	14.69	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:7	35.45	3122	2.61	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.95	14.61	0.99	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:7	35.45	3130	2.61	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.92	14.43	0.98	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:7	35.45	3132	2.61	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.93	14.35	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:8	35.45	3146	2.61	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.94	14.29	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:8	35.45	3135	2.62	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.87	14.25	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:8	35.45	3135	2.62	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.95	14.24	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:8	35.45	3135	2.62	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.94	14.26	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:8	35.45	3132	2.62	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.92	14.27	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:8	35.45	3132	2.62	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.91	14.29	0.97	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:9	35.45	3136	2.62	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.92	14.33	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:9	35.45	3145	2.62	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.88	14.35	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:9	35.45	3153	2.63	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.87	14.35	0.98	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:22:9	35.45	3157	2.63	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.87	14.37	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:9	35.45	3158	2.63	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.9	14.4	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:9	35.45	3164	2.63	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.87	14.42	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:22:9	35.45	3138	2.63	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.86	14.45	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:0	35.45	3165	2.63	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.87	14.47	0.99	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:0	35.45	3165	2.64	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.77	14.48	0.99	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:0	35.45	3166	2.64	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.78	14.49	0.99	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:0	35.45	3167	2.64	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.77	14.5	0.99	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:0	35.45	3159	2.64	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.78	14.54	0.99	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:0	35.45	3163	2.64	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.81	14.58	0.99	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:1	35.45	3159	2.64	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.76	14.6	0.99	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:1	35.45	3158	2.64	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.74	14.63	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:1	35.45	3189	2.65	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.72	14.66	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:1	35.45	3176	2.65	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.66	14.69	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:1	35.45	3170	2.66	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.66	14.72	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:1	35.45	3178	2.66	13.46	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.56	14.74	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:1	35.45	3192	2.67	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.54	14.74	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:23:2	35.45	3196	2.67	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.39	14.75	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:23:2	35.45	3204	2.69	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.15	14.77	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:23:2	35.45	3215	2.7	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.09	14.78	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:23:2	35.45	3216	2.71	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.89	14.8	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:23:2	34.08	3210	2.73	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.75	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:2	34.08	3224	2.74	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.71	14.8	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:3	34.08	3232	2.75	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.52	14.79	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:3	34.08	3232	2.77	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.31	14.83	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:12:23:3	34.08	3236	2.78	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.24	14.86	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:3	35.45	3272	2.79	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.12	14.88	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:3	35.45	3254	2.81	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.05	14.92	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:3	35.45	3261	2.82	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.01	14.97	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:12:23:4	35.45	3262	2.84	13.45	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-2.96	15.01	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:12:23:4	35.45	3265	2.85	13.45	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-2.99	15.01	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:12:23:4	34.08	3264	2.87	13.44	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-2.92	14.99	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:12:23:4	34.08	3263	2.87	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.84	14.95	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:23:4	34.08	3262	2.88	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.81	14.84	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:12:23:4	34.08	3258	2.89	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.79	14.74	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:4	35.45	3260	2.9	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.78	14.56	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:5	35.45	3258	2.9	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.76	14.45	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:12:23:5	35.45	3260	2.9	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.78	14.3	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:5	35.45	3267	2.9	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.82	14.09	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:5	35.45	3282	2.9	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.8	14.05	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:5	34.08	3292	2.9	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.8	13.95	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:5	34.08	3293	2.9	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.84	13.92	0.95	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:12:23:6	34.08	3302	2.91	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.8	13.88	0.95	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:12:23:6	35.45	3332	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.82	13.86	0.94	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:6	35.45	3311	2.91	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.79	13.88	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:12:23:6	35.45	3312	2.91	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.84	13.9	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:6	35.45	3314	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.79	13.91	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:6	35.45	3314	2.91	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.86	13.92	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:6	35.45	3315	2.91	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.83	13.96	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:7	35.45	3316	2.91	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.81	13.98	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:7	35.45	3321	2.91	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.8	13.98	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:7	35.45	3327	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.79	13.97	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:7	35.45	3332	2.91	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.85	13.97	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:7	35.45	3334	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.82	13.96	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:12:23:7	35.45	3333	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.89	13.96	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:8	35.45	3342	2.91	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.88	13.94	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:8	35.45	3357	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.85	13.96	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:8	35.45	3359	2.91	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.85	13.98	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:8	35.45	3371	2.91	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.82	13.98	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:8	35.45	3375	2.91	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.78	14	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:8	35.45	3378	2.91	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.79	14.05	0.96	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:9	35.45	3382	2.91	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.86	14.11	0.96	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:9	35.45	3383	2.91	13.41	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.84	14.16	0.96	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:9	35.45	3383	2.91	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.96	14.25	0.97	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:9	34.08	3392	2.91	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.96	14.3	0.97	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:9	34.08	3390	2.91	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3	14.37	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:9	34.08	3395	2.91	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.1	14.41	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:23:9	34.08	3394	2.91	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.1	14.43	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:24:0	34.08	3393	2.91	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.1	14.5	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:24:0	34.08	3396	2.91	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.1	14.54	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:0	34.08	3398	2.91	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.05	14.56	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:0	34.08	3402	2.91	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.03	14.58	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:0	35.45	3402	2.91	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.99	14.61	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:0	35.45	3400	2.91	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.02	14.66	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:1	35.45	3416	2.91	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.01	14.66	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:1	35.45	3423	2.91	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3	14.66	1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:1	35.45	3424	2.91	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.03	14.68	1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:1	35.45	3438	2.91	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.99	14.68	1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:1	35.45	3438	2.91	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3	14.7	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:1	35.45	3432	2.91	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.04	14.72	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:1	35.45	3437	2.91	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.1	14.73	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:2	35.45	3440	2.91	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.13	14.73	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:2	35.45	3443	2.91	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.21	14.74	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:2	35.45	3444	2.91	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.17	14.76	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:24:2	35.45	3446	2.91	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.14	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:2	35.45	3448	2.91	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.15	14.8	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:2	35.45	3450	2.91	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.18	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:24:3	35.45	3462	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-3.15	14.83	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:3	35.45	3468	2.91	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-3.23	14.87	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:24:3	35.45	3468	2.91	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-3.23	14.91	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:12:24:3	35.45	3476	2.91	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.26	14.96	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:24:3	35.45	3482	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.26	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:3	35.45	3484	2.91	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.27	15	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:4	35.45	3493	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.29	15.01	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:4	35.45	3494	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.29	15.03	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:4	35.45	3548	2.91	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.27	15.1	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:4	35.45	3491	2.91	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-3.33	15.12	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:4	35.45	3490	2.91	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-3.31	15.12	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:4	35.45	3484	2.91	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	-3.35	15.07	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:4	35.45	3472	2.91	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.38	15.03	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:5	35.45	3472	2.91	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.37	15.02	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:5	35.45	3512	2.91	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.37	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:5	35.45	3512	2.9	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.43	14.93	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:5	35.45	3517	2.9	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.47	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:5	35.45	3529	2.89	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.6	14.8	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:5	35.45	3529	2.89	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.7	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:24:6	35.45	3532	2.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.81	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:12:24:6	35.45	3536	2.88	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.88	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:12:24:6	35.45	3522	2.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.94	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:12:24:6	35.45	3530	2.86	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.12	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:24:6	35.45	3528	2.85	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.26	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:12:24:6	35.45	3519	2.84	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.47	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:12:24:6	35.45	3513	2.82	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.69	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:24:7	35.45	3513	2.81	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.81	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:24:7	35.45	3506	2.79	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.93	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:7	35.45	3510	2.78	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.01	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:7	35.45	3519	2.77	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.07	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:7	35.45	3519	2.75	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.12	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:24:7	35.45	3520	2.73	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.28	14.74	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:24:8	35.45	3525	2.72	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.3	14.7	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:24:8	35.45	3542	2.7	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.34	14.65	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:24:8	35.45	3549	2.69	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.45	14.61	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:8	35.45	3553	2.68	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.53	14.61	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:8	35.45	3553	2.66	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.66	14.71	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:8	35.45	3538	2.65	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.72	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:9	36.81	3552	2.64	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.78	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:9	36.81	3544	2.63	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.91	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:9	36.81	3544	2.62	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.97	15.18	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:24:9	36.81	3556	2.61	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.98	15.26	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:9	36.81	3542	2.6	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.14	15.34	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:9	36.81	3545	2.59	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.23	15.47	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:24:9	36.81	3544	2.58	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.32	15.54	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:25:0	36.81	3546	2.57	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.35	15.57	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:25:0	36.81	3544	2.56	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.5	15.57	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:25:0	36.81	3542	2.55	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.59	15.55	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:25:0	36.81	3550	2.54	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.57	15.5	1.06	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:25:0	36.81	3562	2.53	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.69	15.48	1.05	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:25:0	36.81	3558	2.52	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.76	15.45	1.05	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:25:1	36.81	3565	2.51	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.76	15.44	1.05	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:25:1	36.81	3604	2.5	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.92	15.43	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:25:1	36.81	3564	2.49	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.98	15.42	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:25:1	36.81	3555	2.48	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.97	15.4	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:25:1	36.81	3559	2.47	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.98	15.39	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:25:1	36.81	3529	2.46	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.1	15.38	1.05	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:25:1	36.81	3552	2.45	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.15	15.36	1.05	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:25:2	36.81	3551	2.44	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.22	15.35	1.05	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:25:2	36.81	3553	2.43	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.32	15.35	1.05	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:25:2	36.81	3553	2.43	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.32	15.35	1.05	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:25:2	36.81	3547	2.41	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.37	15.35	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:25:2	36.81	3547	2.39	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.48	15.36	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:25:2	36.81	3548	2.38	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.52	15.36	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:25:3	36.81	3582	2.37	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.58	15.38	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:25:3	36.81	3552	2.36	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.68	15.4	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:25:3	36.81	3552	2.35	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.71	15.41	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:25:3	36.81	3556	2.34	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.79	15.42	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:3	38.18	3554	2.33	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.81	15.42	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:25:3	38.18	3554	2.32	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.86	15.44	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:25:4	38.18	3559	2.31	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.94	15.45	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:4	38.18	3554	2.3	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.9	15.46	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:4	36.81	3562	2.29	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.93	15.47	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:4	36.81	3578	2.28	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.02	15.47	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:4	36.81	3565	2.27	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.03	15.46	1.05	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:4	36.81	3568	2.26	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.13	15.46	1.05	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:4	38.18	3568	2.26	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	15.46	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:5	38.18	3576	2.25	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.18	15.47	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:5	38.18	3573	2.25	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.27	15.47	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:5	38.18	3567	2.24	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.24	15.47	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:5	38.18	3566	2.23	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.23	15.43	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:5	38.18	3570	2.23	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.25	15.43	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:5	38.18	3564	2.22	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.29	15.4	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:6	38.18	3563	2.22	13.45	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.26	15.38	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:6	38.18	3558	2.21	13.46	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.35	15.34	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:6	38.18	3558	2.2	13.48	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.4	15.3	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:6	38.18	3559	2.2	13.47	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.4	15.26	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:25:6	38.18	3560	2.19	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.49	15.22	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:6	38.18	3564	2.18	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	15.17	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:6	38.18	3536	2.17	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.53	15.17	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:7	38.18	3552	2.17	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.6	15.15	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:7	38.18	3550	2.16	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.62	15.14	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:25:7	38.18	3550	2.15	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.69	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:7	38.18	3570	2.14	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.73	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:7	38.18	3544	2.14	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.77	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:7	38.18	3532	2.12	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.91	15.16	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:8	38.18	3532	2.12	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.93	15.16	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:8	38.18	3522	2.11	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.01	15.17	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:8	38.18	3533	2.09	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.03	15.2	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:25:8	38.18	3528	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.04	15.2	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:25:8	38.18	3530	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.07	15.18	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:8	38.18	3528	2.06	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.13	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:9	38.18	3526	2.06	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.17	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:9	38.18	3524	2.05	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.18	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:9	38.18	3525	2.04	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.17	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:9	38.18	3538	2.03	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.18	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:9	38.18	3522	2.02	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.16	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:9	38.18	3523	2.02	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.19	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:25:9	38.18	3527	2.01	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.22	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:0	38.18	3524	2.01	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.19	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:0	38.18	3522	2	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.24	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:0	38.18	3528	2	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.24	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:0	38.18	3528	2	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.25	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:0	38.18	3534	2	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.24	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:0	38.18	3538	1.99	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.27	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:1	38.18	3541	1.99	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.27	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:1	38.18	3542	1.99	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.27	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:1	38.18	3554	1.99	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.31	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:1	38.18	3566	1.99	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.28	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:1	38.18	3561	1.99	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.34	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:26:1	38.18	3559	1.99	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.35	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:1	38.18	3559	1.99	13.42	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.33	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:2	38.18	3553	1.99	13.43	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.33	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:2	38.18	3536	1.99	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.32	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:2	38.18	3540	1.99	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Lean	1	14.6	-9.32	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:2	38.18	3534	1.99	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.34	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:2	38.18	3524	1.99	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.35	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:2	38.18	3526	1.99	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.33	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:3	38.18	3521	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.32	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:3	38.18	3521	1.98	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.34	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:3	38.18	3520	1.98	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.32	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:3	38.18	3515	1.98	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.32	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:3	38.18	3517	1.98	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.29	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:3	38.18	3518	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.28	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:4	38.18	3528	1.98	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.3	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:4	38.18	3523	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Rich	1	14.6	-9.29	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:4	38.18	3520	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.32	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:4	38.18	3523	1.98	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.33	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:4	38.18	3528	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.35	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:4	38.18	3528	1.98	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.35	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:4	38.18	3532	1.98	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.35	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:5	38.18	3530	1.98	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.32	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:5	38.18	3526	1.98	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.35	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:5	38.18	3525	1.98	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.33	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:5	38.18	3515	1.98	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.35	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:5	38.18	3517	1.98	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.35	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:5	38.18	3514	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.37	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:6	38.18	3507	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.34	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:6	38.18	3502	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.35	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:6	38.18	3504	1.98	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.35	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:6	38.18	3496	1.98	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.33	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:6	38.18	3496	1.98	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.35	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:6	38.18	3494	1.98	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.32	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:6	38.18	3506	1.98	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.3	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:7	38.18	3504	1.98	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.29	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:7	38.18	3500	1.98	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.31	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:7	38.18	3501	1.98	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.32	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:7	38.18	3516	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.36	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:7	38.18	3505	1.98	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.35	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:7	38.18	3506	1.98	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.35	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:8	38.18	3507	1.98	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.34	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:8	38.18	3507	1.98	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.32	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:8	38.18	3505	1.98	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.28	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:8	38.18	3507	1.98	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.29	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:8	38.18	3508	1.98	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.32	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:8	38.18	3509	1.98	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.29	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:9	38.18	3504	1.98	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.28	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:9	38.18	3499	1.98	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.25	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:9	38.18	3498	1.99	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.22	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:9	38.18	3496	1.99	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.19	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:26:9	38.18	3493	1.99	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.18	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:9	38.18	3493	2	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.15	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:26:9	38.18	3497	2	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.14	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:27:0	38.18	3497	2	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.11	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:27:0	38.18	3493	2.01	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.04	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:0	38.18	3494	2.01	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.94	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:0	38.18	3492	2.02	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.93	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:0	38.18	3492	2.03	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.92	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:27:0	38.18	3491	2.03	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.92	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:1	38.18	3493	2.04	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.91	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:1	38.18	3490	2.04	13.47	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.94	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:1	38.18	3491	2.04	13.46	98	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.92	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:1	38.18	3508	2.05	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.89	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:1	38.18	3502	2.05	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.85	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:1	38.18	3502	2.06	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.8	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:1	38.18	3506	2.06	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.82	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:2	38.18	3509	2.07	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.81	14.9	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:2	38.18	3511	2.07	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.82	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:2	38.18	3510	2.07	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.84	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:2	38.18	3510	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.83	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:2	38.18	3507	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.81	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:2	38.18	3504	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.85	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:3	38.18	3510	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.88	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:3	38.18	3509	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.83	15.14	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:3	38.18	3509	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.86	15.14	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:3	38.18	3508	2.09	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.85	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:3	38.18	3504	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.83	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:3	38.18	3494	2.09	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.85	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:4	38.18	3483	2.09	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.87	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:4	38.18	3486	2.09	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.83	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:4	38.18	3470	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.82	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:4	38.18	3469	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.83	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:4	38.18	3464	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.83	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:4	38.18	3464	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.79	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:4	38.18	3462	2.08	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.8	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:5	38.18	3454	2.08	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.8	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:5	38.18	3456	2.08	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.79	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:5	38.18	3462	2.08	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.76	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:5	38.18	3465	2.08	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.77	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:5	38.18	3469	2.08	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.73	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:5	38.18	3470	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.76	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:6	38.18	3474	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.71	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:6	38.18	3475	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.74	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:6	38.18	3504	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.75	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:6	38.18	3488	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.75	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:6	38.18	3477	2.08	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.78	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:6	38.18	3474	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.79	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:6	38.18	3475	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.76	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:7	38.18	3476	2.08	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.78	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:7	38.18	3474	2.08	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.79	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:7	38.18	3470	2.08	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.8	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:7	38.18	3470	2.08	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.78	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:7	38.18	3458	2.08	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.79	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:7	38.18	3474	2.08	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.81	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:8	38.18	3474	2.08	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.82	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:27:8	38.18	3473	2.08	13.47	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.8	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:8	38.18	3466	2.08	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.79	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:8	38.18	3462	2.08	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.83	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:8	38.18	3461	2.08	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.78	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:8	38.18	3460	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.79	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:9	38.18	3462	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.8	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:9	38.18	3462	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.8	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:9	38.18	3462	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.79	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:9	38.18	3458	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.81	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:9	38.18	3458	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.83	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:27:9	38.18	3460	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.83	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:27:9	38.18	3465	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.82	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:0	38.18	3466	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.82	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:0	38.18	3466	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.81	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:0	38.18	3466	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.81	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:0	38.18	3470	2.08	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.81	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:0	38.18	3473	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.76	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:0	38.18	3466	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.8	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:1	38.18	3477	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.74	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:1	38.18	3473	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.77	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:1	38.18	3472	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.8	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:1	38.18	3467	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.8	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:1	38.18	3466	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.8	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:1	38.18	3459	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.78	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:1	38.18	3452	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Lean	1	14.6	-8.78	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:2	38.18	3449	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.76	15.15	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:2	38.18	3448	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.75	15.14	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:2	38.18	3442	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.73	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:2	38.18	3438	2.08	13.48	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.73	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:2	38.18	3429	2.08	13.48	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.72	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:2	38.18	3429	2.08	13.48	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.72	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:3	38.18	3436	2.08	13.46	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.7	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:3	38.18	3437	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.76	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:28:3	38.18	3436	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.76	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:28:3	38.18	3442	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.79	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:3	38.18	3446	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.75	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:3	38.18	3449	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.77	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:28:4	38.18	3449	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.73	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:28:4	38.18	3449	2.08	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.71	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:28:4	38.18	3452	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.76	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:4	38.18	3460	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.74	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:4	38.18	3460	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.75	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:4	38.18	3462	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.77	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:4	38.18	3456	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.75	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:5	38.18	3464	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.75	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:5	38.18	3462	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.75	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:5	38.18	3460	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.76	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:5	38.18	3460	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.8	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:5	38.18	3459	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.75	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:5	38.18	3463	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.79	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:6	38.18	3463	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.76	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:6	38.18	3456	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.73	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:6	38.18	3452	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.73	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:6	38.18	3452	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.72	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:6	38.18	3453	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.67	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:6	38.18	3453	2.08	13.48	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.69	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:6	38.18	3453	2.09	13.46	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.73	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:7	38.18	3455	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.73	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:7	38.18	3454	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.71	14.79	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:7	38.18	3458	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.73	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:7	38.18	3459	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.71	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:7	38.18	3459	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.71	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:7	38.18	3435	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.73	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:8	38.18	3449	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.78	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:8	38.18	3464	2.09	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.8	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:8	38.18	3467	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.81	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:8	38.18	3471	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.8	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:8	38.18	3471	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.79	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:8	38.18	3468	2.09	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.77	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:28:9	38.18	3464	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.74	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:9	38.18	3457	2.09	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.73	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:9	38.18	3442	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.73	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:9	38.18	3440	2.09	13.46	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.72	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:9	38.18	3429	2.08	13.47	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.7	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:9	38.18	3398	2.08	13.47	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.73	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:28:9	38.18	3398	2.08	13.47	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.73	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:0	38.18	3426	2.08	13.47	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.7	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:0	38.18	3419	2.08	13.48	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.65	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:0	38.18	3418	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.65	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:0	38.18	3448	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.63	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:0	38.18	3436	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.64	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:0	38.18	3425	2.08	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.68	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:1	38.18	3428	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.68	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:1	38.18	3428	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.64	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:1	38.18	3433	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.65	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:1	38.18	3433	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.65	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:1	38.18	3439	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.68	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:1	38.18	3447	2.08	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.71	14.81	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:1	38.18	3447	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.73	14.82	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:2	38.18	3449	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.75	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:2	38.18	3454	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.77	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:2	38.18	3457	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.76	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:2	38.18	3455	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-8.76	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:2	38.18	3457	2.08	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.75	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:2	38.18	3458	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.8	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:3	38.18	3454	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.77	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:3	38.18	3454	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.79	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:3	38.18	3450	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.76	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:3	38.18	3450	2.08	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.77	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:3	38.18	3447	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.82	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:3	38.18	3450	2.08	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.77	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:4	38.18	3451	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.8	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:4	38.18	3445	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.75	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:4	38.18	3448	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.75	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:4	38.18	3448	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.71	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:4	38.18	3416	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.73	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:4	38.18	3440	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.73	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:4	38.18	3432	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.71	14.77	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:5	38.18	3434	2.08	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.71	14.76	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:5	38.18	3432	2.08	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.7	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:5	38.18	3441	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.66	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:5	38.18	3427	2.08	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.66	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:5	38.18	3424	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.67	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:5	38.18	3423	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.68	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:6	38.18	3402	2.08	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.68	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:6	38.18	3427	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.68	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:6	38.18	3426	2.08	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.66	15.07	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:6	38.18	3425	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.68	15.13	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:6	38.18	3452	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.67	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:6	38.18	3422	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.65	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:6	38.18	3420	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.63	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:7	38.18	3418	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.62	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:7	38.18	3411	2.09	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.62	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:7	38.18	3412	2.09	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.64	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:7	38.18	3415	2.09	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.62	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:7	38.18	3417	2.09	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.63	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:7	38.18	3424	2.09	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.64	14.91	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:29:8	38.18	3425	2.09	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.65	14.87	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:8	38.18	3427	2.09	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.64	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:8	38.18	3426	2.09	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.6	14.84	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:8	38.18	3430	2.09	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Rich	1	14.6	-8.6	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:29:8	38.18	3430	2.09	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-8.56	14.87	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:8	38.18	3444	2.09	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.58	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:9	38.18	3434	2.09	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.62	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:9	38.18	3437	2.1	13.45	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.59	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:9	38.18	3432	2.1	13.47	98	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.57	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:9	38.18	3432	2.1	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.56	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:9	38.18	3432	2.1	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.54	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:9	38.18	3429	2.1	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.57	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:29:9	38.18	3429	2.1	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.56	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:0	38.18	3430	2.11	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.62	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:0	38.18	3430	2.11	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.61	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:0	38.18	3422	2.11	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.59	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:0	38.18	3422	2.11	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.55	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:0	38.18	3424	2.11	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.55	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:0	38.18	3424	2.12	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.52	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:1	38.18	3431	2.12	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.49	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:1	38.18	3430	2.12	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.51	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:1	38.18	3428	2.12	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.49	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:1	38.18	3426	2.12	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.47	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:1	38.18	3426	2.12	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.47	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:1	38.18	3427	2.12	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.47	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:1	38.18	3426	2.12	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.44	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:2	38.18	3421	2.13	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.41	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:2	38.18	3422	2.13	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.42	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:2	38.18	3424	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.43	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:2	38.18	3420	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.42	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:2	38.18	3418	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Lean	1	14.6	-8.47	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:2	38.18	3399	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Lean	1	14.6	-8.46	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:3	38.18	3416	2.13	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.47	15.14	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:3	38.18	3415	2.13	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.48	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:3	38.18	3416	2.13	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.48	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:3	38.18	3416	2.13	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.45	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:3	38.18	3418	2.13	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.45	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:3	38.18	3419	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.47	14.99	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:4	38.18	3422	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.46	14.96	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:4	38.18	3421	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.45	14.92	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:4	38.18	3428	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.41	14.87	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:4	38.18	3428	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.45	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:4	38.18	3432	2.13	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.41	14.82	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:4	38.18	3458	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.45	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:4	38.18	3428	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.44	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:5	38.18	3428	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.44	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:5	38.18	3422	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.46	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:5	38.18	3415	2.13	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.43	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:5	38.18	3426	2.13	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.42	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:5	38.18	3426	2.13	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.43	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:5	38.18	3428	2.14	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.4	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:6	38.18	3426	2.14	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.37	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:6	38.18	3426	2.14	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.34	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:6	38.18	3418	2.14	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.35	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:6	38.18	3418	2.14	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.38	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:6	38.18	3412	2.14	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.39	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:6	38.18	3386	2.14	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.43	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:6	38.18	3415	2.14	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.42	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:30:7	38.18	3415	2.14	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.42	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:7	38.18	3415	2.14	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.41	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:7	38.18	3417	2.14	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.37	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:7	38.18	3415	2.14	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.38	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:7	38.18	3416	2.14	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.37	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:7	38.18	3419	2.14	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.35	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:30:8	38.18	3419	2.14	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.4	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:8	38.18	3413	2.14	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.4	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:8	38.18	3421	2.14	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.4	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:8	38.18	3421	2.14	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.41	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:8	38.18	3417	2.14	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.41	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:8	38.18	3423	2.14	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.41	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:9	38.18	3425	2.14	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Rich	1	14.6	-8.4	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:9	38.18	3430	2.14	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.42	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:9	38.18	3435	2.14	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.39	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:9	38.18	3433	2.14	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.42	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:9	38.18	3432	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.4	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:9	38.18	3429	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.4	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:30:9	38.18	3426	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.41	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:0	38.18	3445	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.4	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:0	38.18	3430	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.41	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:0	38.18	3411	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.45	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:0	38.18	3405	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.45	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:0	38.18	3399	2.13	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.43	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:0	38.18	3399	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.47	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:1	38.18	3398	2.13	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.44	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:1	38.18	3399	2.13	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.49	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:1	38.18	3404	2.13	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.43	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:1	38.18	3404	2.13	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.42	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:1	38.18	3393	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.46	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:1	38.18	3409	2.13	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.44	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:1	38.18	3410	2.13	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.45	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:2	38.18	3411	2.13	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.44	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:2	38.18	3414	2.12	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.45	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:2	38.18	3417	2.12	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.44	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:2	38.18	3422	2.12	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.39	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:2	38.18	3425	2.12	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.44	14.82	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:2	38.18	3430	2.12	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.45	14.75	1	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:3	38.18	3437	2.12	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.45	14.73	1	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:3	38.18	3434	2.12	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.46	14.75	1	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:3	38.18	3432	2.12	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.49	14.76	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:3	38.18	3452	2.12	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.45	14.77	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:3	38.18	3432	2.12	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.46	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:3	38.18	3432	2.12	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.49	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:4	38.18	3421	2.12	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.48	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:4	38.18	3411	2.13	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.46	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:4	38.18	3400	2.13	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.51	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:4	38.18	3407	2.13	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.48	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:4	38.18	3406	2.13	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.47	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:4	38.18	3400	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.46	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:4	38.18	3387	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.4	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:5	38.18	3387	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.41	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:5	38.18	3390	2.13	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.43	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:5	38.18	3397	2.13	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.39	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:5	38.18	3401	2.13	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.41	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:5	38.18	3402	2.13	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.41	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:5	38.18	3407	2.13	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.35	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:6	38.18	3414	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.37	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:31:6	38.18	3424	2.13	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.38	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:6	38.18	3410	2.13	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.35	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:6	38.18	3430	2.13	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.37	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:31:6	38.18	3436	2.13	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.36	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:6	38.18	3440	2.14	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.36	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:6	38.18	3434	2.14	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.34	14.88	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:7	38.18	3432	2.14	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.31	14.91	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:7	38.18	3430	2.14	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.31	14.93	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:7	38.18	3428	2.15	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.27	14.98	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:7	38.18	3424	2.15	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.3	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:7	38.18	3430	2.15	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.26	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:7	38.18	3405	2.15	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.24	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:8	38.18	3403	2.16	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.18	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:31:8	38.18	3400	2.17	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.12	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:31:8	38.18	3368	2.17	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.04	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:31:8	38.18	3382	2.19	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.97	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:31:8	38.18	3400	2.19	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.89	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:31:8	38.18	3406	2.2	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.83	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:31:9	38.18	3410	2.21	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.77	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:31:9	38.18	3412	2.23	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.68	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:31:9	38.18	3429	2.24	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.67	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:31:9	38.18	3435	2.24	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.56	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:31:9	38.18	3434	2.25	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.52	14.87	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:31:9	38.18	3440	2.26	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.43	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:31:9	38.18	3440	2.27	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.46	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:32:0	38.18	3444	2.28	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.45	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:32:0	38.18	3445	2.29	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.48	14.99	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:0	38.18	3442	2.29	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.47	15	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:0	38.18	3437	2.31	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.55	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:0	38.18	3428	2.31	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.53	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:0	38.18	3428	2.32	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.58	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:1	38.18	3408	2.32	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.53	15.15	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:1	38.18	3419	2.32	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-7.51	15.19	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:1	38.18	3413	2.33	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.46	15.19	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:1	38.18	3413	2.33	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.45	15.16	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:1	38.18	3403	2.33	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.42	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:1	38.18	3404	2.33	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.35	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:32:1	36.81	3396	2.34	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.28	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:32:2	36.81	3412	2.34	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.25	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:2	36.81	3415	2.34	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.2	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:2	36.81	3429	2.35	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.19	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:2	36.81	3430	2.35	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.13	14.87	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:32:2	36.81	3447	2.36	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.1	14.84	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:32:2	36.81	3452	2.37	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.09	14.84	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:32:3	36.81	3458	2.37	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.08	14.85	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:32:3	36.81	3488	2.38	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.09	14.88	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:3	36.81	3461	2.38	13.45	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.09	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:3	36.81	3461	2.39	13.45	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.05	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:3	36.81	3458	2.39	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.04	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:3	36.81	3449	2.4	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.02	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:4	36.81	3439	2.4	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.99	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:4	36.81	3439	2.41	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.03	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:4	36.81	3428	2.41	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.03	15.16	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:32:4	36.81	3423	2.41	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.03	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:4	36.81	3416	2.41	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.99	15.09	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:4	36.81	3416	2.41	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.02	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:4	36.81	3421	2.41	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.01	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:5	36.81	3420	2.41	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:32:5	36.81	3427	2.41	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.04	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:5	36.81	3416	2.41	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7	14.76	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:5	36.81	3434	2.41	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.93	14.69	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:5	36.81	3440	2.41	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.91	14.66	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:32:5	36.81	3453	2.42	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.89	14.65	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:6	36.81	3454	2.42	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.86	14.67	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:32:6	36.81	3461	2.42	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.87	14.68	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:6	36.81	3466	2.43	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.77	14.71	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:32:6	36.81	3466	2.44	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.69	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:32:6	36.81	3468	2.45	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.59	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:32:6	36.81	3464	2.46	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.53	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:6	36.81	3467	2.47	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.49	14.79	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:7	36.81	3467	2.48	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.44	14.8	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:7	36.81	3470	2.49	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.33	14.81	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:7	36.81	3468	2.5	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.27	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:12:32:7	36.81	3466	2.51	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.27	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:12:32:7	36.81	3466	2.52	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.21	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:7	36.81	3463	2.52	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.24	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:8	36.81	3460	2.53	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.24	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:8	36.81	3460	2.54	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.25	15.05	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:8	36.81	3456	2.55	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.22	15.08	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:8	36.81	3448	2.56	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.17	15.13	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:8	36.81	3449	2.56	13.4	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.13	15.13	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:8	36.81	3454	2.57	13.4	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.08	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:9	36.81	3461	2.57	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.09	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:9	36.81	3467	2.57	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.11	14.9	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:9	36.81	3470	2.57	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.1	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:9	36.81	3478	2.57	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.12	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:9	36.81	3478	2.57	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.1	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:32:9	36.81	3478	2.57	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.08	14.65	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:32:9	36.81	3476	2.57	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.15	14.6	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:0	36.81	3453	2.57	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.15	14.59	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:0	36.81	3487	2.57	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.19	14.59	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:0	36.81	3487	2.57	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.19	14.61	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:0	36.81	3501	2.56	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.25	14.62	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:0	36.81	3490	2.56	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.24	14.65	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:0	36.81	3500	2.56	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.24	14.68	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:1	36.81	3500	2.56	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.23	14.68	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:1	36.81	3489	2.56	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.24	14.7	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:1	36.81	3486	2.55	13.41	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.32	14.71	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:1	36.81	3486	2.55	13.4	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.36	14.73	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:1	36.81	3487	2.55	13.4	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.4	14.75	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:1	36.81	3489	2.55	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.4	14.77	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:1	36.81	3490	2.55	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.41	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:2	36.81	3490	2.55	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.36	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:2	36.81	3486	2.55	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.37	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:2	36.81	3493	2.55	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.35	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:2	36.81	3492	2.54	13.44	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.39	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:2	36.81	3488	2.54	13.46	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.36	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:2	36.81	3480	2.54	13.47	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.34	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:3	36.81	3500	2.54	13.47	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.39	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:3	36.81	3503	2.54	13.48	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.39	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:3	36.81	3508	2.54	13.47	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.44	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:3	36.81	3505	2.54	13.46	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.44	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:3	36.81	3506	2.54	13.46	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.38	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:3	36.81	3512	2.54	13.47	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.36	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:4	36.81	3512	2.54	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.35	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:4	36.81	3508	2.54	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.33	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:33:4	36.81	3520	2.54	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.4	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:4	36.81	3498	2.54	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.42	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:4	36.81	3499	2.54	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.43	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:4	36.81	3503	2.54	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.42	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:4	36.81	3502	2.54	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-6.44	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:5	36.81	3506	2.54	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.4	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:5	36.81	3506	2.54	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.38	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:5	36.81	3501	2.54	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.44	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:5	36.81	3507	2.54	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.43	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:5	36.81	3511	2.53	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.48	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:5	36.81	3533	2.53	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.5	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:6	36.81	3537	2.53	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.49	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:6	36.81	3537	2.53	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.47	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:6	36.81	3536	2.53	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.48	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:6	36.81	3549	2.53	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.52	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:6	36.81	3527	2.53	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.51	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:6	36.81	3525	2.53	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.5	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:6	36.81	3521	2.53	13.41	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.5	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:7	36.81	3522	2.53	13.41	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.48	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:7	36.81	3522	2.53	13.41	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.46	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:7	36.81	3519	2.53	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.45	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:7	36.81	3518	2.53	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.45	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:7	36.81	3521	2.53	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.43	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:7	36.81	3515	2.53	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.46	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:8	36.81	3520	2.53	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.46	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:8	36.81	3516	2.53	13.42	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.45	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:8	36.81	3522	2.53	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.44	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:8	36.81	3523	2.53	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.45	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:8	36.81	3528	2.53	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.43	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:8	36.81	3539	2.54	13.41	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.39	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:9	36.81	3539	2.54	13.41	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.43	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:9	36.81	3556	2.54	13.41	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.4	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:9	36.81	3562	2.54	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.38	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:9	36.81	3565	2.54	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.38	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:9	36.81	3563	2.54	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.39	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:33:9	36.81	3560	2.55	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.36	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:33:9	36.81	3527	2.55	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.35	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:0	36.81	3551	2.55	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.38	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:0	36.81	3539	2.55	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.42	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:0	36.81	3533	2.56	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.38	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:0	36.81	3532	2.56	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.44	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:0	36.81	3526	2.56	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.43	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:0	36.81	3549	2.56	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.41	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:1	36.81	3550	2.56	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.36	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:1	36.81	3550	2.56	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.33	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:1	36.81	3581	2.56	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.32	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:34:1	36.81	3553	2.56	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.33	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:34:1	36.81	3561	2.56	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.35	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:34:1	36.81	3562	2.56	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.3	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:1	36.81	3563	2.57	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.33	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:2	36.81	3554	2.57	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.31	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:2	36.81	3560	2.57	13.48	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.23	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:34:2	36.81	3575	2.57	13.45	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.23	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:2	36.81	3570	2.57	13.46	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.3	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:34:2	36.81	3573	2.57	13.48	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.2	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:34:2	36.81	3571	2.57	13.45	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.24	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:34:3	36.81	3573	2.57	13.47	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.28	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:3	36.81	3577	2.57	13.49	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.23	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:34:3	36.81	3577	2.58	13.48	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.19	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:3	36.81	3576	2.58	13.49	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.25	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:3	36.81	3578	2.58	13.49	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.2	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:3	36.81	3570	2.58	13.49	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.16	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:4	36.81	3532	2.58	13.48	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.16	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:4	36.81	3532	2.59	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.16	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:4	36.81	3563	2.59	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.2	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:4	36.81	3566	2.59	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.15	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:4	36.81	3566	2.59	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.18	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:34:4	36.81	3594	2.59	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.12	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:34:4	36.81	3588	2.6	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.13	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:34:5	36.81	3601	2.6	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.1	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:34:5	36.81	3601	2.6	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.12	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:34:5	36.81	3602	2.6	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.09	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:12:34:5	36.81	3598	2.6	13.41	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.06	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:12:34:5	36.81	3602	2.6	13.41	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.12	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:5	36.81	3600	2.6	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.12	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:6	36.81	3599	2.6	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.1	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:6	36.81	3596	2.61	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.16	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:6	36.81	3597	2.61	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.16	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:6	36.81	3598	2.61	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.12	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:6	36.81	3594	2.61	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.13	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:6	36.81	3588	2.61	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.11	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:6	36.81	3601	2.61	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.12	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:7	36.81	3602	2.61	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.2	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:7	36.81	3606	2.61	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.16	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:7	36.81	3607	2.6	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.2	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:12:34:7	36.81	3620	2.6	13.44	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.25	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:34:7	36.81	3602	2.6	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.25	14.75	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:34:7	36.81	3604	2.6	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.28	14.75	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:12:34:8	36.81	3603	2.59	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.39	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:34:8	36.81	3602	2.57	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.66	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:12:34:8	36.81	3597	2.56	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.76	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:12:34:8	36.81	3598	2.55	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.99	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:34:8	36.81	3602	2.52	13.45	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.21	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:34:8	36.81	3596	2.5	13.43	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.35	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:34:9	36.81	3597	2.48	13.41	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.57	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:34:9	36.81	3594	2.46	13.44	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:34:9	36.81	3584	2.44	13.45	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.83	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:34:9	36.81	3576	2.4	13.44	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.02	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:34:9	38.18	3576	2.38	13.46	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.15	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:34:9	38.18	3567	2.36	13.46	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.23	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:34:9	38.18	3565	2.33	13.47	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.35	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:35:0	38.18	3565	2.3	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.43	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:35:0	38.18	3564	2.27	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.52	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:35:0	38.18	3563	2.24	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.59	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:35:0	38.18	3561	2.22	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.71	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:0	38.18	3561	2.19	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.8	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:0	38.18	3556	2.17	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.83	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:1	38.18	3533	2.13	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.98	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:1	38.18	3548	2.11	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.07	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:1	38.18	3547	2.09	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.13	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:1	38.18	3543	2.07	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.24	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:1	38.18	3545	2.06	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.29	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:1	38.18	3546	2.04	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.32	15.19	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:1	38.18	3547	2.03	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.32	15.28	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:2	38.18	3552	2.02	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.31	15.39	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:2	38.18	3559	2.01	13.45	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.36	15.48	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:35:2	38.18	3562	2	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.36	15.52	1.06	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:2	38.18	3566	1.99	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.38	15.55	1.06	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:2	38.18	3576	1.98	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.44	15.56	1.06	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:2	38.18	3582	1.97	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	15.56	1.06	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:3	38.18	3584	1.96	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.48	15.55	1.06	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:3	38.18	3590	1.96	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.53	15.54	1.06	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:3	38.18	3594	1.95	13.43	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.51	15.51	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:3	39.54	3608	1.95	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.49	15.5	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:3	39.54	3596	1.95	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.5	15.46	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:3	39.54	3592	1.95	13.51	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	15.43	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:4	39.54	3617	1.95	13.51	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.44	15.43	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:4	39.54	3583	1.95	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	15.43	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:4	39.54	3583	1.95	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.49	15.43	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:4	39.54	3580	1.95	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	15.45	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:4	39.54	3574	1.95	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.5	15.47	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:4	38.18	3542	1.96	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.48	15.47	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:4	38.18	3563	1.96	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.48	15.47	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:5	38.18	3558	1.96	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.43	15.48	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:5	38.18	3552	1.96	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.42	15.48	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:5	38.18	3546	1.96	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.42	15.47	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:5	38.18	3544	1.96	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.4	15.45	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:5	38.18	3542	1.96	13.49	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.4	15.4	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:5	38.18	3547	1.96	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.4	15.36	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:6	38.18	3549	1.96	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.43	15.34	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:6	38.18	3548	1.96	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	15.32	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:6	38.18	3554	1.96	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.42	15.33	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:6	38.18	3555	1.96	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	15.32	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:6	38.18	3555	1.96	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.48	15.3	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:6	38.18	3539	1.96	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.45	15.27	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:6	38.18	3555	1.96	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.45	15.26	1.04	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:7	38.18	3555	1.96	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.49	15.25	1.04	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:7	38.18	3554	1.96	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.5	15.22	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:7	38.18	3573	1.96	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.49	15.21	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:7	39.54	3549	1.96	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.47	15.18	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:7	39.54	3549	1.96	13.44	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.49	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:7	39.54	3550	1.96	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.48	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:8	39.54	3551	1.96	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.46	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:8	39.54	3551	1.96	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.49	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:8	39.54	3548	1.96	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.49	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:8	39.54	3549	1.96	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.5	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:8	39.54	3548	1.96	13.51	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.48	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:8	39.54	3548	1.96	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.45	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:9	39.54	3548	1.95	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.47	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:9	39.54	3540	1.95	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.47	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:9	39.54	3538	1.95	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.44	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:9	39.54	3534	1.95	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.5	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:9	39.54	3532	1.95	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.49	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:35:9	39.54	3525	1.95	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.52	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:35:9	39.54	3519	1.95	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.54	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:0	39.54	3520	1.95	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.49	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:0	39.54	3520	1.95	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.52	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:0	39.54	3522	1.95	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.5	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:0	39.54	3531	1.95	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.46	14.94	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:0	39.54	3531	1.95	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.48	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:0	39.54	3534	1.95	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.66	Lean	1	14.6	-9.51	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:1	39.54	3534	1.95	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.48	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:1	39.54	3538	1.95	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.49	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:1	39.54	3538	1.95	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.51	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:36:1	39.54	3532	1.95	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.51	14.78	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:1	39.54	3531	1.95	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.53	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:1	39.54	3535	1.95	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.54	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:1	39.54	3534	1.95	13.5	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.51	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:2	39.54	3528	1.95	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.47	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:2	39.54	3528	1.94	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.54	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:2	39.54	3522	1.94	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.49	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:2	39.54	3522	1.94	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.52	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:2	39.54	3532	1.94	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.53	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:2	39.54	3518	1.94	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.5	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:3	39.54	3512	1.94	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.5	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:3	39.54	3510	1.94	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.47	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:3	39.54	3506	1.94	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.46	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:3	39.54	3495	1.94	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.48	14.9	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:3	39.54	3500	1.94	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.45	14.94	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:3	39.54	3502	1.94	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.47	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:4	39.54	3503	1.94	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.48	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:4	39.54	3510	1.94	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.51	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:4	39.54	3513	1.94	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.5	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:4	39.54	3511	1.94	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.54	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:4	39.54	3525	1.94	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.53	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:4	39.54	3524	1.94	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.55	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:4	39.54	3520	1.94	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.55	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:5	39.54	3518	1.94	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.52	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:5	39.54	3518	1.94	13.46	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Rich	1	14.6	-9.52	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:5	39.54	3516	1.94	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.57	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:5	39.54	3510	1.94	13.47	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.6	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:5	39.54	3503	1.93	13.48	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.63	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:5	39.54	3500	1.93	13.5	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.58	14.88	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:6	39.54	3500	1.93	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.62	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:36:6	38.18	3498	1.93	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.65	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:6	38.18	3497	1.92	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.62	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:6	38.18	3498	1.92	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.66	14.97	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:6	38.18	3497	1.92	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.68	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:6	38.18	3497	1.91	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.67	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:6	39.54	3508	1.91	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.66	15.05	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:7	39.54	3496	1.91	13.49	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.65	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:7	39.54	3496	1.9	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.69	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:7	39.54	3484	1.9	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.68	15.14	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:7	39.54	3494	1.89	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.71	15.18	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:7	39.54	3489	1.89	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.75	15.17	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:7	39.54	3489	1.89	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.77	15.15	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:36:8	39.54	3486	1.88	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.77	15.12	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:36:8	39.54	3482	1.87	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.75	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:36:8	39.54	3471	1.87	13.45	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.81	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:36:8	39.54	3474	1.87	13.48	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.79	14.96	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:36:8	39.54	3472	1.86	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.87	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:36:8	39.54	3468	1.85	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.92	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:36:9	39.54	3472	1.85	13.47	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.97	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:36:9	39.54	3472	1.84	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.99	14.78	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:36:9	39.54	3466	1.83	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.01	14.78	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:36:9	39.54	3467	1.82	13.46	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.08	14.78	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:36:9	39.54	3469	1.81	13.48	99	196	Full Load	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.11	14.79	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:36:9	39.54	3470	1.8	13.48	99	196	Full Load	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.15	14.8	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:36:9	39.54	3471	1.79	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.2	14.82	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:0	39.54	3472	1.78	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.25	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:0	39.54	3467	1.77	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.26	14.85	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:12:37:0	39.54	3465	1.76	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.28	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:37:0	39.54	3464	1.75	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.27	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:0	39.54	3459	1.74	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.29	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:0	39.54	3457	1.73	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.28	14.84	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:1	36.81	3403	1.73	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.29	14.83	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:1	31.36	3400	1.72	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-10.27	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:1	25.9	3391	1.71	13.47	99	196	Idle	41.6	0	2	132	944 Turbo	0.25	Rich	1	14.6	-10.28	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:1	20.45	3392	1.71	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-10.26	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:1	20.45	3437	1.71	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.16	Rich	1	14.6	-10.31	14.84	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:1	20.45	3430	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.29	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:1	20.45	3413	1.7	13.48	99	196	Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.32	14.81	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:2	20.45	3412	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.32	14.8	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:2	20.45	3400	1.7	13.49	99	196	Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.23	14.82	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:2	20.45	3398	1.7	13.49	99	196	Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.18	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:2	20.45	3389	1.7	13.49	99	196	Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.14	14.87	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:2	20.45	3386	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.1	14.9	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:2	20.45	3390	1.7	13.49	99	196	Idle	41.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.03	14.91	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:3	20.45	3391	1.7	13.49	99	196	Idle	41	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.02	14.95	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:3	20.45	3426	1.7	13.49	99	196	Idle	40.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.04	14.98	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:3	20.45	3414	1.7	13.48	99	196	Idle	40.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.98	15.06	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:3	20.45	3408	1.7	13.48	99	196	Idle	40.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.97	15.08	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:3	20.45	3417	1.7	13.47	99	196	Idle	40.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.97	15.13	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:3	20.45	3417	1.7	13.47	99	196	Idle	40.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.99	15.18	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:4	20.45	3420	1.7	13.46	99	196	Idle	40.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.99	15.23	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:4	20.45	3416	1.7	13.48	99	196	Idle	40.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.98	15.27	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:4	20.45	3410	1.7	13.47	99	196	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	15.3	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:4	20.45	3396	1.7	13.48	99	196	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	15.32	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:4	20.45	3401	1.7	13.47	99	196	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	15.37	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:4	20.45	3391	1.7	13.48	99	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	15.53	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:4	20.45	3381	1.7	13.47	99	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	15.71	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:5	20.45	3380	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	16	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:5	20.45	3372	1.7	13.48	99	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	16.66	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:5	20.45	3365	1.7	13.48	99	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	17.13	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:5	20.45	3359	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	17.84	1.22	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:5	20.45	3331	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	18.33	1.25	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:5	20.45	3344	1.7	13.5	99	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	18.57	1.27	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:6	20.45	3354	1.7	13.5	99	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	19.24	1.31	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:6	20.45	3352	1.7	13.48	99	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	19.63	1.34	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:6	20.45	3351	1.7	13.48	99	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	19.95	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:6	20.45	3350	1.7	13.48	99	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.15	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:6	20.45	3351	1.7	13.49	99	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:6	20.45	3348	1.7	13.48	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:6	20.45	3348	1.7	13.48	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:7	20.45	3347	1.7	13.49	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:7	20.45	3345	1.7	13.48	99	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:7	20.45	3356	1.7	13.48	99	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:7	20.45	3341	1.7	13.48	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:7	20.45	3326	1.7	13.49	99	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:7	20.45	3334	1.7	13.48	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:8	20.45	3334	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:8	20.45	3331	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:8	20.45	3327	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:8	20.45	3326	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:8	20.45	3320	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:8	20.45	3313	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:9	20.45	3313	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:9	20.45	3296	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:9	20.45	3303	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:9	20.45	3330	1.7	13.48	99	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:37:9	20.45	3314	1.7	13.48	99	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:9	20.45	3299	1.7	13.48	99	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:37:9	20.45	3296	1.7	13.47	99	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:0	20.45	3289	1.7	13.48	99	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:0	20.45	3289	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:0	20.45	3285	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:0	20.45	3280	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:0	20.45	3277	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:0	20.45	3276	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:1	20.45	3257	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:1	20.45	3268	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:1	20.45	3268	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:1	20.45	3274	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:1	20.45	3262	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:1	20.45	3260	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:1	20.45	3246	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:2	20.45	3256	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:2	20.45	3253	1.7	13.49	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:2	20.45	3252	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:2	20.45	3252	1.7	13.5	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:2	20.45	3250	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:2	20.45	3249	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:3	20.45	3245	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:3	20.45	3244	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:3	20.45	3241	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:3	20.45	3237	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:3	20.45	3232	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:3	20.45	3232	1.7	13.45	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:4	20.45	3218	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:4	20.45	3225	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:4	20.45	3225	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:4	20.45	3220	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:4	20.45	3217	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:4	20.45	3188	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:4	20.45	3188	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:5	20.45	3208	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:5	20.45	3229	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:5	20.45	3199	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:5	20.45	3199	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:5	20.45	3184	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:5	20.45	3194	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:6	20.45	3193	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:6	20.45	3205	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:6	20.45	3188	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:6	20.45	3185	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:6	20.45	3182	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:6	20.45	3181	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:6	20.45	3180	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:7	20.45	3171	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:7	20.45	3170	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:7	20.45	3144	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:7	20.45	3164	1.7	13.45	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:7	20.45	3159	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:7	20.45	3158	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:8	20.45	3155	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:8	20.45	3155	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:8	20.45	3152	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:8	20.45	3152	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:38:8	20.45	3150	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:8	20.45	3151	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:9	20.45	3150	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:9	20.45	3144	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:9	20.45	3144	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:9	20.45	3132	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:9	20.45	3140	1.7	13.49	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:9	20.45	3136	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:38:9	20.45	3136	1.7	13.49	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:0	20.45	3136	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:0	20.45	3136	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:0	20.45	3117	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:0	20.45	3117	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:0	20.45	3115	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:0	20.45	3112	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:1	20.45	3108	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:1	20.45	3108	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:1	19.09	3119	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:1	19.09	3108	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:1	19.09	3107	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:1	19.09	3105	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:1	19.09	3104	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:2	19.09	3104	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:2	19.09	3076	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:2	19.09	3095	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:2	19.09	3091	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:2	19.09	3089	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:2	19.09	3084	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:3	19.09	3092	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:3	19.09	3073	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:3	19.09	3074	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:3	19.09	3044	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:3	19.09	3065	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:3	19.09	3037	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:4	19.09	3049	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:4	19.09	3058	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:4	19.09	3065	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:4	19.09	3051	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:4	19.09	3032	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:4	19.09	3043	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:4	19.09	3055	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:5	19.09	3066	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:5	19.09	3056	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:5	19.09	3056	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:5	19.09	3052	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:5	19.09	3025	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:5	19.09	3025	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:6	19.09	3043	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:6	19.09	3037	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:6	19.09	3046	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:6	19.09	3029	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:6	19.09	3012	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:6	19.09	3018	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:6	19.09	3016	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:7	19.09	3000	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:7	19.09	3007	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:7	19.09	3033	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:7	19.09	3007	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:39:7	19.09	3007	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:7	19.09	2984	1.7	13.45	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:8	19.09	3009	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:8	19.09	3008	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:8	19.09	3010	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:8	19.09	3006	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:8	19.09	3002	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:8	19.09	3002	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:9	19.09	3006	1.7	13.49	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:9	19.09	2989	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:9	19.09	2988	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:9	19.09	2969	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:9	19.09	2973	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:9	19.09	2991	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:39:9	19.09	2977	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:0	19.09	2962	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:0	19.09	2935	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:0	19.09	2946	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:0	19.09	2955	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:0	19.09	2956	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:0	19.09	2935	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:1	19.09	2935	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:1	19.09	2956	1.7	13.47	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:1	19.09	2958	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:1	19.09	2956	1.7	13.47	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:1	19.09	2956	1.7	13.46	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:1	19.09	2930	1.7	13.46	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:1	19.09	2950	1.7	13.47	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:2	19.09	2950	1.7	13.46	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:2	19.09	2954	1.7	13.47	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:2	19.09	2938	1.7	13.46	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:2	19.09	2931	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:2	19.09	2931	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:2	19.09	2925	1.7	13.47	99	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:3	19.09	2942	1.7	13.46	99	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:3	19.09	2942	1.7	13.48	99	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:3	19.09	2918	1.7	13.48	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:3	19.09	2916	1.7	13.47	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:3	19.09	2915	1.7	13.47	99	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:3	19.09	2914	1.7	13.46	99	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:4	19.09	2924	1.7	13.46	99	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:4	19.09	2910	1.7	13.46	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:4	19.09	2910	1.7	13.47	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:4	19.09	2908	1.7	13.48	99	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:4	19.09	2908	1.7	13.49	99	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:4	19.09	2906	1.7	13.47	99	196	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:4	19.09	2904	1.7	13.48	99	196	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:5	19.09	2898	1.7	13.46	99	196	Idle	42.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:5	19.09	2898	1.7	13.46	99	196	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:5	19.09	2893	1.7	13.46	99	196	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:5	19.09	2865	1.7	13.46	99	196	Idle	42.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:5	19.09	2883	1.7	13.46	99	196	Idle	42.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:5	19.09	2882	1.7	13.45	99	196	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:6	19.09	2888	1.69	13.47	99	196	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:6	19.09	2871	1.69	13.47	99	196	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:6	19.09	2845	1.69	13.47	99	196	Idle	42.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:6	19.09	2865	1.69	13.46	99	196	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:6	19.09	2864	1.69	13.47	99	196	Idle	42.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:40:6	19.09	2872	1.69	13.45	99	196	Idle	42.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:6	19.09	2860	1.69	13.47	99	196	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:7	19.09	2835	1.69	13.48	99	196	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:7	19.09	2847	1.69	13.47	99	196	Idle	42.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:7	19.09	2858	1.69	13.46	99	196	Idle	42.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:7	19.09	2834	1.69	13.47	99	196	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:7	19.09	2853	1.69	13.47	99	196	Idle	43.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:7	19.09	2854	1.69	13.47	99	196	Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:8	19.09	2850	1.69	13.46	99	196	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:8	19.09	2826	1.69	13.48	99	196	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:8	19.09	2826	1.68	13.46	99	196	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:8	19.09	2843	1.68	13.46	99	196	Idle	44	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:8	19.09	2839	1.68	13.46	99	196	Idle	44.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:8	19.09	2839	1.68	13.46	99	196	Idle	44.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:9	19.09	2836	1.68	13.46	99	196	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:9	19.09	2844	1.68	13.46	99	196	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:9	19.09	2830	1.68	13.47	99	196	Idle	44.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:9	19.09	2828	1.67	13.48	99	196	Idle	45.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:9	19.09	2804	1.67	13.48	99	196	Idle	45.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:9	19.09	2804	1.67	13.48	99	196	Idle	45.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:40:9	19.09	2820	1.67	13.48	99	196	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:0	19.09	2818	1.67	13.48	99	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:0	19.09	2814	1.66	13.48	99	196	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:0	19.09	2824	1.66	13.47	99	196	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:0	19.09	2810	1.66	13.47	99	196	Idle	46.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:0	19.09	2785	1.66	13.48	99	196	Idle	46.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:0	19.09	2785	1.66	13.48	99	196	Idle	46.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:1	19.09	2801	1.65	13.46	99	196	Idle	46.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:1	19.09	2795	1.65	13.48	99	196	Full Load	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:1	19.09	2794	1.65	13.47	99	196	Off Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:1	19.09	2719	1.65	13.45	99	196	Off Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:1	10.9	2831	1.65	13.47	99	196	Off Idle	46.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:41:1	10.9	2805	1.65	13.46	99	196	Off Idle	47.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:41:1	13.63	2804	1.65	13.44	99	196	Off Idle	47.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:41:2	16.36	2800	1.65	13.46	99	196	Off Idle	47.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:41:2	19.09	2756	1.65	13.46	99	196	Off Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:41:2	19.09	2776	1.65	13.47	99	196	Off Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:2	21.81	2796	1.65	13.47	99	196	Off Idle	48.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:41:2	24.54	2794	1.65	13.45	99	196	Off Idle	48.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:41:2	27.27	2801	1.66	13.45	99	196	Off Idle	49.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:3	27.27	2801	1.66	13.46	99	196	Off Idle	49.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:3	29.99	2809	1.66	13.46	99	196	Off Idle	49.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:3	32.72	2820	1.67	13.47	99	196	Off Idle	49.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:3	35.45	2829	1.67	13.46	99	196	Off Idle	50.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.26	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:3	35.45	2807	1.67	13.48	99	196	Off Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:3	36.81	2807	1.68	13.48	99	196	Off Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:4	36.81	2812	1.68	13.47	99	196	Off Idle	50.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:4	36.81	2809	1.69	13.47	99	196	Off Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:4	36.81	2831	1.69	13.48	99	196	Off Idle	50.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:4	36.81	2831	1.69	13.47	99	196	Off Idle	50	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:4	36.81	2804	1.69	13.47	99	196	Off Idle	49.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:4	36.81	2797	1.69	13.46	99	196	Off Idle	49.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:41:4	36.81	2789	1.7	13.45	99	196	Off Idle	49.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.76	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:5	36.81	2785	1.7	13.45	99	196	Off Idle	49.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.76	20.26	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:5	36.81	2773	1.7	13.45	99	196	Off Idle	49.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.74	20.26	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:5	36.81	2758	1.71	13.46	99	196	Off Idle	49.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.74	20.26	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:5	36.81	2756	1.71	13.46	99	196	Off Idle	49.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.73	20.26	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:5	36.81	2734	1.71	13.46	99	196	Off Idle	50.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.73	20.27	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:41:8	36.81	2751	1.71	13.46	99	196	Off Idle	50.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.7	20.27	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:6	36.81	2751	1.71	13.47	99	196	Off Idle	50.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.69	20.28	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:6	36.81	2750	1.71	13.48	99	196	Off Idle	50.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	20.28	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:6	36.81	2750	1.71	13.47	99	196	Off Idle	51	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.65	20.27	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:6	36.81	2750	1.71	13.46	99	196	Off Idle	51.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	20.27	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:6	36.81	2750	1.71	13.48	99	196	Off Idle	51.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:6	36.81	2749	1.71	13.47	99	196	Off Idle	51.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.68	20.14	1.37	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:6	36.81	2754	1.71	13.48	99	197	Off Idle	51.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	20.01	1.36	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:7	36.81	2754	1.71	13.48	99	197	Off Idle	52	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.67	19.74	1.34	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:7	36.81	2763	1.71	13.48	99	197	Off Idle	52.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.69	19.52	1.33	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:7	36.81	2762	1.71	13.47	99	197	Off Idle	52.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.68	19.28	1.31	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:7	36.81	2765	1.71	13.47	99	196	Off Idle	52.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.67	19.15	1.3	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:7	36.81	2770	1.71	13.48	99	196	Off Idle	52.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.7	18.87	1.29	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:7	36.81	2768	1.71	13.48	99	196	Off Idle	52.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.66	18.59	1.27	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:8	36.81	2768	1.71	13.48	99	196	Off Idle	52.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.66	18.28	1.25	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:8	36.81	2763	1.71	13.48	99	196	Off Idle	52	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.67	17.86	1.22	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:8	36.81	2759	1.71	13.47	99	197	Off Idle	52	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.68	17.65	1.2	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:8	36.81	2758	1.71	13.46	99	197	Off Idle	52	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.73	17.44	1.19	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:8	36.81	2757	1.71	13.46	99	197	Off Idle	52	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.74	17.26	1.18	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:8	36.81	2756	1.71	13.48	99	197	Off Idle	52	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.76	17.1	1.16	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:9	36.81	2772	1.71	13.49	99	197	Off Idle	52	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.76	16.95	1.15	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:9	36.81	2746	1.71	13.48	99	197	Off Idle	52	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.73	16.83	1.15	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:9	36.81	2744	1.71	13.47	99	197	Off Idle	52	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.7	16.63	1.13	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:9	36.81	2744	1.71	13.48	99	197	Off Idle	52	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.68	16.52	1.13	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:9	36.81	2734	1.71	13.48	99	197	Off Idle	52.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.73	16.41	1.12	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:9	36.81	2745	1.71	13.47	99	196	Off Idle	52.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.7	16.3	1.11	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:41:9	36.81	2745	1.71	13.47	99	196	Off Idle	52.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.71	16.21	1.1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:0	36.81	2747	1.71	13.49	99	196	Off Idle	52.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.7	16.13	1.1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:0	36.81	2736	1.71	13.47	99	197	Off Idle	52.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.72	16.02	1.09	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:0	36.81	2746	1.71	13.47	99	197	Off Idle	52.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.72	15.94	1.09	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:0	36.81	2743	1.71	13.47	99	197	Off Idle	52.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.73	15.87	1.08	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:0	36.81	2742	1.71	13.46	99	196	Off Idle	52.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.72	15.81	1.08	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:0	36.81	2742	1.71	13.47	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.74	15.76	1.07	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:1	36.81	2742	1.71	13.47	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.73	15.71	1.07	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:1	36.81	2735	1.7	13.46	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.74	15.65	1.07	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:1	36.81	2735	1.7	13.47	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.73	15.6	1.06	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:1	36.81	2740	1.71	13.45	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.73	15.56	1.06	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:1	36.81	2754	1.71	13.46	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.71	15.51	1.06	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:1	36.81	2743	1.71	13.46	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.66	15.47	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:1	36.81	2740	1.71	13.45	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.66	15.45	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:2	36.81	2734	1.71	13.45	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.69	15.4	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:2	36.81	2728	1.71	13.47	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.68	15.36	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:2	36.81	2730	1.71	13.47	99	197	Off Idle	52.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.71	15.33	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:2	36.81	2732	1.71	13.46	99	197	Off Idle	52.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.7	15.29	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:2	36.81	2734	1.71	13.48	99	197	Off Idle	52.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.67	15.26	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:2	36.81	2737	1.71	13.47	99	196	Off Idle	52.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.64	15.22	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:3	36.81	2737	1.72	13.48	99	196	Off Idle	52.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.63	15.2	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:3	36.81	2737	1.72	13.48	99	196	Off Idle	52.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.65	15.18	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:3	36.81	2739	1.72	13.48	99	196	Off Idle	52.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.65	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:3	36.81	2735	1.72	13.46	99	196	Off Idle	52.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.62	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:3	36.81	2714	1.72	13.47	99	196	Off Idle	52.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.64	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:3	36.81	2735	1.72	13.47	99	196	Off Idle	52.8	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.63	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:4	36.81	2732	1.72	13.45	99	196	Off Idle	52.8	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.63	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:4	36.81	2736	1.73	13.43	99	197	Off Idle	52.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.64	14.98	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:4	36.81	2736	1.73	13.46	99	197	Off Idle	52.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.62	14.98	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:4	36.81	2735	1.73	13.45	99	197	Off Idle	52.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.65	14.96	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:4	36.81	2734	1.73	13.44	99	197	Off Idle	52.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.65	14.96	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:4	36.81	2735	1.73	13.46	99	196	Off Idle	53	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.61	14.97	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:42:4	36.81	2736	1.73	13.47	99	196	Off Idle	53.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.59	15.01	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:5	36.81	2738	1.73	13.47	99	196	Off Idle	53.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.62	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:5	36.81	2738	1.72	13.46	99	197	Off Idle	53.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.62	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:5	36.81	2738	1.72	13.47	99	197	Off Idle	53.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.65	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:5	36.81	2738	1.72	13.45	99	197	Off Idle	53.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.67	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:5	36.81	2732	1.72	13.45	99	197	Off Idle	53.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.67	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:5	36.81	2729	1.72	13.45	99	197	Off Idle	53.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.68	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:6	36.81	2730	1.72	13.45	99	197	Off Idle	53.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.68	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:6	36.81	2738	1.72	13.46	99	196	Off Idle	54	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.68	15.17	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:6	36.81	2725	1.72	13.46	99	196	Off Idle	54	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.67	15.18	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:6	36.81	2725	1.72	13.48	99	196	Off Idle	54.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.66	15.17	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:6	36.81	2718	1.72	13.48	99	197	Off Idle	54.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.66	15.15	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:6	36.81	2718	1.72	13.48	99	197	Off Idle	54	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.65	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:6	36.81	2709	1.72	13.48	99	197	Off Idle	54	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.65	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:7	36.81	2718	1.72	13.48	99	196	Off Idle	54	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.63	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:7	36.81	2719	1.71	13.48	99	196	Off Idle	54.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.66	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:7	36.81	2715	1.71	13.48	99	196	Off Idle	54.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.65	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:7	36.81	2715	1.71	13.48	99	196	Off Idle	54.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.67	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:7	36.81	2710	1.71	13.48	99	196	Off Idle	54.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.67	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:7	36.81	2709	1.71	13.44	99	196	Off Idle	54.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.65	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:8	36.81	2709	1.71	13.43	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.66	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:8	36.81	2712	1.71	13.43	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.64	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:8	36.81	2714	1.71	13.41	99	197	Off Idle	54.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-9.66	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:8	36.81	2715	1.71	13.41	99	197	Off Idle	54.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.66	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:8	36.81	2721	1.71	13.41	99	197	Off Idle	54.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.66	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:42:8	36.81	2732	1.71	13.42	99	197	Off Idle	54.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.66	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:9	36.81	2724	1.71	13.43	99	197	Off Idle	54.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.69	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:9	36.81	2724	1.71	13.44	99	197	Off Idle	54.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.69	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:9	36.81	2722	1.71	13.44	99	197	Off Idle	54.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.68	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:9	36.81	2727	1.71	13.43	99	197	Off Idle	54.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.69	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:9	36.81	2727	1.71	13.42	99	197	Off Idle	54.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.66	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:9	36.81	2726	1.71	13.42	99	197	Off Idle	54.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.65	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:42:9	36.81	2720	1.71	13.41	99	197	Off Idle	54.2	0	2	132	944 Turbo	0.67	Lean	1	14.6	-9.65	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:0	36.81	2707	1.71	13.41	99	197	Off Idle	54.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.63	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:0	36.81	2717	1.71	13.41	99	197	Off Idle	54	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.63	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:0	36.81	2717	1.71	13.42	99	197	Off Idle	53.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.66	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:0	36.81	2711	1.71	13.44	99	196	Off Idle	53.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.66	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:0	36.81	2710	1.71	13.45	99	196	Off Idle	53.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.66	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:0	36.81	2707	1.71	13.44	99	196	Off Idle	53.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.66	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:1	36.81	2701	1.71	13.43	99	197	Off Idle	53.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.66	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:1	36.81	2702	1.71	13.43	99	197	Off Idle	53.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.64	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:43:1	36.81	2701	1.71	13.43	99	197	Off Idle	53.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.65	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:43:1	36.81	2701	1.71	13.42	99	196	Off Idle	53.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.68	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:43:1	36.81	2700	1.71	13.42	99	196	Off Idle	54	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.66	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:43:1	36.81	2701	1.71	13.43	99	197	Off Idle	54.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.63	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:43:1	36.81	2702	1.71	13.44	99	197	Off Idle	54.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.67	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:2	36.81	2704	1.71	13.44	99	197	Off Idle	54.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.68	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:2	36.81	2705	1.71	13.44	99	196	Off Idle	54.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.7	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:2	36.81	2705	1.7	13.44	99	196	Off Idle	54.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.75	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:2	36.81	2705	1.7	13.47	99	196	Off Idle	54.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.77	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:2	36.81	2701	1.69	13.46	99	196	Off Idle	54.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.81	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:12:43:2	36.81	2700	1.69	13.47	99	196	Off Idle	54.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.84	14.81	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:43:3	36.81	2699	1.68	13.47	99	196	Off Idle	54.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.88	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:43:3	36.81	2686	1.67	13.48	99	197	Off Idle	55.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.91	14.78	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:43:3	36.81	2697	1.66	13.48	99	197	Off Idle	55.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.97	14.78	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:3	36.81	2697	1.66	13.47	99	197	Off Idle	55.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.02	14.79	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:43:3	35.45	2669	1.64	13.47	99	197	Off Idle	55.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.07	14.81	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:12:43:3	35.45	2684	1.64	13.46	99	197	Off Idle	55.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.11	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:43:4	35.45	2682	1.63	13.46	99	196	Off Idle	55.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.11	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:4	35.45	2677	1.61	13.46	99	196	Off Idle	55.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.16	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:4	35.45	2676	1.61	13.45	99	196	Off Idle	55.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.19	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:4	35.45	2677	1.59	13.45	99	196	Off Idle	55.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.21	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:4	35.45	2668	1.58	13.45	99	196	Full Load	55.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.21	14.95	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:4	35.45	2666	1.57	13.47	99	196	Idle	55.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.24	14.99	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:4	35.45	2666	1.56	13.45	99	196	Idle	55.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.27	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:43:5	35.45	2657	1.55	13.47	99	196	Idle	55.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.29	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:43:5	35.45	2668	1.54	13.46	99	196	Idle	55.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.35	15	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:43:5	32.72	2668	1.53	13.47	99	196	Idle	55.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.35	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:5	32.72	2645	1.52	13.47	99	196	Idle	54.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.38	14.96	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:43:5	27.27	2645	1.52	13.47	99	196	Idle	53.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.39	14.94	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:12:43:5	21.81	2639	1.52	13.48	99	196	Idle	52.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-10.38	14.9	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:6	21.81	2658	1.52	13.49	99	196	Idle	52.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-10.36	14.85	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:6	19.09	2652	1.52	13.48	99	196	Idle	51.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.34	14.79	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:6	19.09	2660	1.52	13.47	99	196	Idle	50.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.29	14.74	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:6	19.09	2658	1.53	13.46	99	196	Idle	50.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.23	14.73	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:6	19.09	2656	1.53	13.45	99	197	Idle	50	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.19	14.74	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:6	19.09	2656	1.53	13.44	99	197	Idle	49.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.16	14.74	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:6	19.09	2637	1.54	13.44	99	197	Idle	49.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.12	14.75	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:7	19.09	2626	1.54	13.44	99	196	Idle	48.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.11	14.77	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:7	19.09	2633	1.55	13.44	99	196	Idle	48.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.1	14.8	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:7	19.09	2634	1.55	13.43	99	196	Idle	49.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.05	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:7	19.09	2636	1.55	13.44	99	197	Idle	49.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.04	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:7	19.09	2636	1.55	13.43	99	197	Idle	50.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.05	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:7	19.09	2640	1.55	13.42	99	197	Idle	51.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.04	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:8	19.09	2642	1.56	13.43	99	197	Idle	51.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.04	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:8	19.09	2643	1.56	13.44	99	197	Idle	52.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.07	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:8	19.09	2644	1.56	13.44	99	196	Idle	54.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.08	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:8	19.09	2643	1.55	13.44	99	196	Idle	54.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.08	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:8	19.09	2642	1.55	13.44	99	196	Idle	55.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.1	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:8	19.09	2638	1.54	13.43	99	197	Idle	55.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.11	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:9	19.09	2636	1.53	13.45	99	197	Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:9	19.09	2636	1.52	13.44	99	197	Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:9	19.09	2623	1.52	13.42	99	196	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	15.05	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:9	19.09	2616	1.51	13.42	99	196	Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	15.15	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:9	19.09	2610	1.5	13.41	99	196	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	15.26	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:9	19.09	2610	1.49	13.42	99	196	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	15.42	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:43:9	19.09	2603	1.48	13.43	99	196	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	15.78	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:0	19.09	2600	1.47	13.45	99	197	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	16.15	1.1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:0	19.09	2597	1.47	13.45	99	197	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	16.62	1.13	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:0	19.09	2598	1.46	13.45	99	196	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	17.13	1.17	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:0	19.09	2598	1.46	13.45	99	196	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	17.37	1.18	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:0	19.09	2596	1.45	13.45	99	196	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	17.87	1.22	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:0	19.09	2597	1.45	13.45	99	196	Idle	58.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	18.58	1.27	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:1	19.09	2598	1.45	13.46	99	196	Idle	58.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	19.02	1.3	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:1	19.09	2599	1.44	13.47	99	196	Idle	58.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	19.43	1.32	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:1	19.09	2598	1.44	13.48	99	196	Idle	58.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	19.78	1.35	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:1	19.09	2598	1.44	13.49	99	196	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.03	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:1	19.09	2595	1.44	13.47	99	196	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:1	19.09	2592	1.44	13.47	99	196	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:1	19.09	2587	1.44	13.47	99	196	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:2	19.09	2586	1.43	13.47	99	196	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:2	19.09	2581	1.43	13.47	99	197	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:2	19.09	2576	1.43	13.47	99	197	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:2	19.09	2570	1.43	13.47	99	196	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:2	19.09	2570	1.43	13.47	99	196	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:2	19.09	2555	1.42	13.46	99	196	Idle	60.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:44:3	19.09	2558	1.42	13.46	99	196	Idle	60.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:3	19.09	2574	1.42	13.46	99	196	Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:3	19.09	2564	1.42	13.46	99	196	Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:3	19.09	2552	1.41	13.47	99	196	Idle	60.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:3	19.09	2526	1.41	13.47	99	196	Idle	60.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:3	19.09	2526	1.41	13.47	99	196	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:4	19.09	2552	1.41	13.47	99	196	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:4	19.09	2549	1.41	13.48	99	196	Idle	60.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:4	19.09	2548	1.41	13.48	99	197	Idle	60.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:4	19.09	2549	1.4	13.49	99	197	Idle	60.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:4	19.09	2547	1.4	13.47	99	197	Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:4	19.09	2544	1.4	13.46	99	196	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:4	19.09	2541	1.4	13.44	99	196	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:5	19.09	2540	1.4	13.43	99	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:5	19.09	2537	1.39	13.43	99	197	Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:5	19.09	2531	1.39	13.42	99	197	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:5	19.09	2528	1.39	13.42	99	197	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:5	19.09	2523	1.38	13.43	99	197	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:5	19.09	2523	1.38	13.43	99	197	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:6	19.09	2517	1.38	13.43	99	197	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:6	19.09	2517	1.38	13.43	99	197	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:6	19.09	2522	1.37	13.42	99	197	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:6	19.09	2510	1.37	13.42	99	197	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:6	19.09	2488	1.37	13.42	99	196	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:6	19.09	2488	1.37	13.41	99	196	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:6	19.09	2506	1.36	13.41	99	196	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:7	19.09	2500	1.36	13.41	99	197	Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:7	19.09	2500	1.36	13.41	99	197	Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:7	19.09	2499	1.35	13.41	99	197	Idle	63.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:7	19.09	2495	1.35	13.44	99	197	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:7	19.09	2493	1.35	13.43	99	197	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:7	19.09	2490	1.35	13.43	99	197	Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:8	19.09	2489	1.34	13.43	99	197	Idle	64.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:8	19.09	2485	1.34	13.44	99	197	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:8	19.09	2482	1.34	13.44	99	197	Idle	64.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:8	19.09	2482	1.34	13.44	99	197	Idle	64.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:8	19.09	2478	1.34	13.45	99	197	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:8	19.09	2477	1.34	13.47	99	196	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:9	19.09	2475	1.33	13.47	99	196	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:9	19.09	2473	1.33	13.46	99	196	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:9	19.09	2470	1.33	13.48	99	196	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:9	19.09	2469	1.33	13.48	99	196	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:9	19.09	2468	1.32	13.47	99	196	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:9	19.09	2465	1.32	13.48	99	196	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:44:9	19.09	2463	1.32	13.47	99	196	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:0	19.09	2452	1.32	13.46	99	197	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:0	17.72	2450	1.31	13.46	99	197	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:0	19.09	2475	1.31	13.48	99	197	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:0	19.09	2454	1.31	13.49	99	197	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:0	19.09	2433	1.3	13.5	99	197	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:0	19.09	2433	1.3	13.5	99	197	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:1	19.09	2448	1.3	13.5	99	196	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:1	19.09	2463	1.3	13.49	99	196	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:1	19.09	2441	1.29	13.48	99	197	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:1	19.09	2458	1.29	13.46	99	197	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:1	19.09	2448	1.28	13.46	99	197	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:1	19.09	2426	1.28	13.46	99	196	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:1	19.09	2431	1.28	13.45	99	196	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:45:2	19.09	2431	1.27	13.45	99	196	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:2	19.09	2420	1.26	13.46	99	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:2	19.09	2424	1.26	13.48	99	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:2	19.09	2424	1.26	13.47	99	196	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:2	19.09	2413	1.26	13.47	99	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:2	17.72	2410	1.25	13.47	99	196	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:3	17.72	2418	1.25	13.44	99	196	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:3	17.72	2418	1.25	13.44	99	196	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:3	17.72	2431	1.24	13.43	99	196	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:3	17.72	2410	1.24	13.41	99	196	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:3	17.72	2408	1.24	13.42	99	196	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:3	17.72	2407	1.23	13.42	99	196	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:4	17.72	2404	1.23	13.41	99	196	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:4	17.72	2399	1.23	13.41	99	196	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:4	17.72	2398	1.22	13.42	99	197	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:4	17.72	2396	1.22	13.41	99	197	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:4	17.72	2394	1.22	13.43	99	197	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:4	17.72	2392	1.21	13.43	99	196	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:4	17.72	2388	1.21	13.43	99	196	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:5	17.72	2388	1.21	13.45	99	196	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:5	17.72	2386	1.21	13.46	99	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:5	17.72	2383	1.21	13.45	99	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:5	17.72	2381	1.21	13.44	99	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:5	17.72	2379	1.21	13.44	99	197	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:5	17.72	2375	1.2	13.43	99	197	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:6	17.72	2372	1.2	13.44	99	197	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:6	17.72	2372	1.2	13.42	99	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:6	17.72	2365	1.2	13.43	99	196	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:6	17.72	2364	1.19	13.43	99	196	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:6	17.72	2362	1.19	13.42	99	197	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:6	17.72	2362	1.19	13.42	99	197	Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:6	17.72	2358	1.19	13.43	99	196	Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:7	17.72	2356	1.19	13.43	99	196	Idle	71.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:7	17.72	2354	1.18	13.43	99	196	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:7	17.72	2352	1.18	13.42	99	197	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:7	17.72	2349	1.18	13.42	99	197	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:7	17.72	2349	1.18	13.44	99	197	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:7	17.72	2346	1.18	13.44	99	196	Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:8	17.72	2347	1.17	13.44	99	196	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:8	17.72	2343	1.17	13.46	99	196	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:8	17.72	2334	1.16	13.46	99	196	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:8	17.72	2340	1.16	13.44	99	196	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:8	17.72	2340	1.16	13.45	99	196	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:8	17.72	2330	1.16	13.46	99	196	Idle	73.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:9	17.72	2334	1.16	13.46	99	196	Idle	73.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:9	17.72	2351	1.15	13.47	99	196	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:9	17.72	2330	1.15	13.47	99	196	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:9	17.72	2320	1.15	13.48	99	196	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:9	17.72	2324	1.15	13.48	99	196	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:9	17.72	2324	1.14	13.47	99	196	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:45:9	17.72	2320	1.14	13.47	99	196	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:0	17.72	2318	1.14	13.47	99	196	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:0	17.72	2332	1.14	13.47	99	196	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:0	17.72	2309	1.14	13.46	99	196	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:0	17.72	2308	1.13	13.46	99	197	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:0	17.72	2307	1.13	13.47	99	197	Idle	74.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:0	17.72	2285	1.13	13.48	99	197	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:1	17.72	2293	1.13	13.49	99	196	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:46:1	17.72	2308	1.12	13.46	99	196	Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:1	17.72	2296	1.12	13.46	99	196	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:1	17.72	2295	1.12	13.44	99	196	Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:1	17.72	2294	1.12	13.42	99	196	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:1	17.72	2289	1.12	13.42	99	196	Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:1	17.72	2286	1.11	13.41	99	196	Idle	75.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:2	17.72	2286	1.11	13.4	99	197	Idle	75.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:2	17.72	2284	1.11	13.4	99	197	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:2	17.72	2282	1.1	13.41	99	197	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:2	17.72	2279	1.1	13.44	99	197	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:2	17.72	2278	1.1	13.43	99	197	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:2	17.72	2276	1.1	13.43	99	197	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:3	17.72	2273	1.1	13.43	99	196	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:3	17.72	2272	1.09	13.42	99	196	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:3	17.72	2269	1.09	13.41	99	197	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:3	17.72	2269	1.09	13.42	99	197	Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:3	17.72	2264	1.08	13.42	99	197	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:3	17.72	2261	1.08	13.41	99	197	Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:4	17.72	2260	1.08	13.43	99	196	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:4	17.72	2258	1.07	13.42	99	196	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:4	17.72	2246	1.07	13.41	99	197	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:4	17.72	2252	1.07	13.4	99	197	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:4	17.72	2250	1.07	13.41	99	197	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:4	17.72	2247	1.06	13.41	99	196	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:4	17.72	2245	1.06	13.43	99	196	Idle	78.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:5	17.72	2242	1.06	13.43	99	196	Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:5	17.72	2242	1.06	13.44	99	197	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:5	17.72	2248	1.06	13.46	99	197	Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:5	17.72	2237	1.05	13.46	99	197	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:5	17.72	2235	1.05	13.46	99	197	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:5	17.72	2226	1.04	13.46	99	197	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:6	17.72	2230	1.04	13.46	99	197	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:6	17.72	2227	1.04	13.45	99	196	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:6	17.72	2225	1.04	13.46	99	196	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:6	17.72	2224	1.04	13.46	99	196	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:6	17.72	2207	1.03	13.47	99	196	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:6	17.72	2220	1.03	13.47	99	196	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:6	17.72	2218	1.03	13.48	99	196	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.03	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:7	17.72	2214	1.03	13.47	99	197	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.03	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:7	17.72	2226	1.03	13.47	99	197	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.03	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:7	17.72	2207	1.03	13.46	99	196	Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.02	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:7	17.72	2205	1.03	13.45	99	196	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.03	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:7	17.72	2205	1.02	13.44	99	196	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.03	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:7	17.72	2210	1.02	13.43	99	196	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.03	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:8	17.72	2198	1.02	13.46	99	196	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.03	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:8	17.72	2198	1.02	13.45	99	196	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.04	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:8	17.72	2177	1.02	13.47	99	196	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:8	17.72	2192	1.02	13.47	99	196	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:8	17.72	2187	1.02	13.46	99	196	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:8	17.72	2187	1.01	13.45	99	196	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:9	17.72	2192	1.01	13.45	99	196	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:9	17.72	2181	1.01	13.47	99	196	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:9	17.72	2172	1.01	13.49	99	197	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:9	17.72	2178	1.01	13.48	99	197	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:9	17.72	2180	1	13.47	99	196	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:9	17.72	2178	1	13.46	99	196	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:46:9	17.72	2175	1	13.46	99	196	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:0	17.72	2172	1	13.48	99	196	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:47:0	17.72	2171	1	13.48	99	196	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:0	17.72	2171	1	13.48	99	196	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:0	17.72	2176	0.99	13.49	99	196	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:0	17.72	2166	0.99	13.49	99	196	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:0	17.72	2163	0.99	13.49	99	196	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:1	17.72	2162	0.99	13.49	99	196	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:1	17.72	2162	0.98	13.48	99	196	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:1	17.72	2159	0.98	13.47	99	196	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:1	17.72	2157	0.98	13.45	99	196	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:1	17.72	2156	0.98	13.45	99	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:1	17.72	2152	0.98	13.44	99	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:1	17.72	2151	0.97	13.45	99	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:2	17.72	2145	0.97	13.47	99	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:2	17.72	2144	0.97	13.47	99	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:2	17.72	2157	0.97	13.47	99	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:2	17.72	2139	0.97	13.47	99	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.84	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:2	17.72	2138	0.97	13.46	99	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.84	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:2	17.72	2102	0.96	13.45	99	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:3	17.72	2146	0.96	13.46	99	196	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:3	17.72	2125	0.96	13.45	99	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:3	17.72	2125	0.96	13.45	99	196	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:3	17.72	2106	0.96	13.46	99	196	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:3	17.72	2119	0.96	13.46	99	196	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:3	17.72	2133	0.96	13.46	99	196	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:4	17.72	2124	0.96	13.44	99	196	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:4	17.72	2113	0.96	13.45	99	196	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:4	17.72	2097	0.96	13.47	99	196	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:4	17.72	2110	0.96	13.47	99	196	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:4	17.72	2118	0.96	13.46	99	196	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:4	17.72	2106	0.96	13.45	99	196	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:4	17.72	2103	0.96	13.44	99	196	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:5	17.72	2101	0.96	13.43	99	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:5	17.72	2101	0.96	13.43	99	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:5	17.72	2083	0.96	13.43	99	196	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:5	17.72	2102	0.96	13.43	99	196	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:5	17.72	2091	0.96	13.44	99	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:5	17.72	2091	0.96	13.45	99	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:6	17.72	2080	0.96	13.45	99	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:6	17.72	2084	0.96	13.45	99	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:6	17.72	2099	0.95	13.46	99	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:6	17.72	2090	0.95	13.47	99	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:6	17.72	2080	0.95	13.48	99	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:6	17.72	2077	0.95	13.49	99	197	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:6	17.72	2076	0.95	13.49	99	197	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.82	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:7	17.72	2076	0.95	13.49	99	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:7	17.72	2058	0.95	13.48	99	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:7	17.72	2072	0.95	13.47	99	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:7	17.72	2068	0.95	13.45	99	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:7	17.72	2068	0.95	13.42	99	197	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:7	17.72	2065	0.95	13.42	99	197	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:8	17.72	2062	0.95	13.41	99	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:8	17.72	2059	0.95	13.4	99	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:8	17.72	2057	0.95	13.41	99	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:8	17.72	2053	0.95	13.41	99	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:8	17.72	2045	0.95	13.41	99	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:8	17.72	2052	0.95	13.4	99	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:9	17.72	2050	0.95	13.39	99	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:9	17.72	2047	0.95	13.38	99	197	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:47:9	17.72	2046	0.95	13.38	99	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:9	17.72	2042	0.95	13.38	99	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:9	17.72	2042	0.95	13.38	99	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:9	17.72	2039	0.95	13.39	99	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:47:9	17.72	2036	0.95	13.41	99	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:0	17.72	2036	0.95	13.42	99	196	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:0	17.72	2031	0.95	13.41	99	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:0	17.72	2029	0.95	13.42	99	197	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:0	17.72	2028	0.95	13.41	99	197	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:0	17.72	2024	0.95	13.39	99	197	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:0	17.72	2020	0.95	13.39	99	197	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:1	17.72	2018	0.95	13.41	99	197	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:1	17.72	2018	0.95	13.41	99	197	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:1	17.72	2012	0.95	13.41	99	197	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:1	17.72	2010	0.95	13.41	99	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:1	17.72	2007	0.95	13.41	99	196	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:1	17.72	2007	0.95	13.41	99	196	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:1	17.72	2004	0.95	13.42	99	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:2	17.72	2002	0.95	13.42	99	197	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:2	17.72	2002	0.95	13.43	99	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:2	17.72	1999	0.95	13.41	99	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:2	17.72	1997	0.95	13.41	99	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:2	17.72	1995	0.95	13.4	99	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:2	17.72	1994	0.95	13.4	99	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:3	17.72	1989	0.95	13.39	99	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:3	17.72	1986	0.95	13.41	99	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:3	17.72	1966	0.95	13.41	99	197	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:3	17.72	1973	0.95	13.41	99	197	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:3	17.72	1990	0.95	13.42	99	197	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:3	17.72	1971	0.95	13.42	99	197	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:4	17.72	1962	0.95	13.42	99	197	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:4	17.72	1965	0.95	13.43	99	196	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:4	17.72	1958	0.95	13.44	99	196	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:4	17.72	1958	0.95	13.43	99	196	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:4	17.72	1952	0.95	13.42	99	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:4	17.72	1947	0.95	13.41	99	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:4	17.72	1944	0.95	13.4	99	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:5	17.72	1944	0.95	13.41	99	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:5	17.72	1939	0.95	13.4	99	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:5	17.72	1936	0.95	13.41	99	197	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:5	17.72	1929	0.95	13.41	99	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:5	17.72	1929	0.95	13.39	99	196	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:5	17.72	1922	0.95	13.39	99	196	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:6	17.72	1916	0.95	13.41	99	196	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:6	17.72	1908	0.95	13.39	99	196	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:6	17.72	1908	0.95	13.38	99	196	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:6	17.72	1903	0.95	13.39	99	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:6	17.72	1894	0.95	13.39	99	196	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:6	17.72	1886	0.95	13.39	99	196	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:6	17.72	1886	0.95	13.41	99	196	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:7	17.72	1880	0.96	13.41	99	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:7	17.72	1870	0.96	13.39	99	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:7	17.72	1870	0.96	13.41	99	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:7	17.72	1868	0.96	13.42	99	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:7	17.72	1858	0.96	13.42	99	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:7	17.72	1858	0.97	13.41	99	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:8	17.72	1842	0.97	13.42	99	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:8	17.72	1840	0.97	13.41	99	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:48:8	17.72	1834	0.97	13.41	99	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.26	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:8	17.72	1834	0.97	13.41	99	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.25	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:8	17.72	1828	0.97	13.4	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.25	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:8	17.72	1818	0.98	13.4	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.26	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:9	17.72	1818	0.98	13.4	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.26	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:9	17.72	1807	0.98	13.4	99	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.25	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:9	17.72	1801	0.98	13.41	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.25	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:9	17.72	1794	0.98	13.4	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:9	17.72	1788	0.98	13.41	99	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:9	17.72	1784	0.99	13.4	99	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:48:9	17.72	1773	0.99	13.4	99	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:0	17.72	1768	0.99	13.39	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:0	17.72	1761	0.99	13.4	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:0	17.72	1761	0.99	13.4	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:0	17.72	1752	0.99	13.4	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:0	17.72	1748	0.99	13.41	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:0	17.72	1734	0.99	13.41	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:1	17.72	1734	0.99	13.41	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:1	17.72	1728	0.99	13.41	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:1	17.72	1716	0.99	13.41	99	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:1	17.72	1713	0.99	13.41	99	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:1	17.72	1709	0.99	13.39	99	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:1	17.72	1697	0.99	13.39	99	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:1	17.72	1689	0.99	13.4	99	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:2	17.72	1668	0.99	13.39	99	197	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:2	17.72	1668	0.99	13.39	99	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:2	17.72	1668	0.99	13.4	99	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:2	17.72	1654	0.99	13.4	99	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:2	17.72	1654	0.99	13.41	99	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:2	17.72	1647	0.99	13.41	99	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:3	17.72	1638	0.99	13.4	99	196	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:3	17.72	1638	0.99	13.41	99	196	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:3	17.72	1626	0.99	13.4	99	196	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:3	17.72	1619	0.99	13.4	99	196	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:3	17.72	1606	1	13.4	99	196	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:3	17.72	1606	1	13.4	99	196	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:4	17.72	1597	1	13.4	99	196	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:4	17.72	1588	1	13.4	99	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:4	17.72	1588	1	13.39	99	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:4	17.72	1574	1	13.39	99	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.21	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:4	17.72	1564	1	13.4	99	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.21	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:4	17.72	1564	1	13.39	99	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.21	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:4	17.72	1532	1	13.39	99	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.21	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:5	17.72	1525	1	13.39	99	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:5	17.72	1503	1	13.4	99	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.22	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:5	17.72	1503	1.01	13.4	99	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.22	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:5	17.72	1480	1.01	13.4	99	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:5	17.72	1454	1.01	13.4	99	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:5	17.72	1427	1.01	13.4	99	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:6	17.72	1427	1.01	13.41	99	196	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:6	17.72	1399	1.01	13.4	99	196	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.24	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:6	19.09	1371	1.01	13.39	99	196	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	20.24	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:6	19.09	1371	1.01	13.39	99	196	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	20.25	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:6	19.09	1332	1.02	13.39	99	196	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.24	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:49:6	16.36	1294	1.02	13.4	99	196	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.24	20.24	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:49:6	16.36	1294	1.03	13.38	99	196	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.18	20.24	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:12:49:7	16.36	1295	1.03	13.4	99	196	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.23	1.38	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:7	17.72	1244	1.03	13.4	99	196	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	20.23	1.38	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:49:7	17.72	1244	1.04	13.4	99	196	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9	20.24	1.38	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:12:49:7	17.72	1215	1.04	13.4	99	196	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.91	20.24	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:49:7	16.36	1202	1.05	13.41	99	196	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.75	20.24	1.38	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:49:7	16.36	1202	1.06	13.41	99	197	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.63	20.24	1.38	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:49:8	16.36	1184	1.06	13.41	99	197	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.52	20.24	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:49:8	16.36	1172	1.07	13.42	99	197	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.45	20.24	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:49:8	16.36	1172	1.08	13.41	99	196	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.36	20.24	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:49:8	16.36	1165	1.09	13.4	99	196	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.26	20.25	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:49:8	16.36	1163	1.09	13.41	99	196	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.23	20.25	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:49:8	16.36	1168	1.1	13.4	99	196	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.2	20.24	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:49:9	16.36	1172	1.1	13.38	99	196	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.15	20.24	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:49:9	16.36	1172	1.11	13.41	99	196	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:49:9	16.36	1167	1.11	13.39	99	197	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.05	20.23	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:49:9	16.36	1163	1.11	13.4	99	197	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.02	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:49:9	16.36	1163	1.11	13.39	99	196	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8	20.24	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:49:9	14.99	1183	1.11	13.39	99	196	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.02	20.25	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:49:9	14.99	1183	1.1	13.4	99	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.04	20.24	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:0	14.99	1186	1.1	13.39	99	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.06	20.24	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:0	14.99	1197	1.09	13.41	99	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.24	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:0	14.99	1197	1.08	13.42	99	196	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.15	20.25	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:0	14.99	1196	1.07	13.41	99	196	Idle	83.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.17	20.25	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:0	14.99	1191	1.06	13.41	99	196	Idle	84.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.23	20.24	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:0	14.99	1191	1.05	13.41	99	196	Idle	85	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.24	20.24	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:1	14.99	1195	1.04	13.38	99	196	Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.26	20.24	1.38	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:50:1	13.63	1195	1.03	13.4	99	196	Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.31	20.24	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:50:1	13.63	1181	1.02	13.39	99	196	Idle	86.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.31	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:50:1	13.63	1173	1.01	13.39	99	196	Idle	86.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.36	20.24	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:1	13.63	1157	1	13.4	99	197	Idle	87	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.37	20.24	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:1	13.63	1157	0.98	13.39	99	197	Idle	87.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.39	20.24	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:1	13.63	1149	0.97	13.4	99	197	Idle	87.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.43	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:50:2	13.63	1141	0.96	13.38	99	196	Idle	87.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.41	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:50:2	12.27	1129	0.96	13.38	99	196	Idle	87.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.43	20.24	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:50:2	12.27	1129	0.95	13.4	99	196	Idle	88	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:12:50:2	12.27	1123	0.94	13.39	99	196	Idle	88.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:2	12.27	1114	0.94	13.4	99	196	Idle	88.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.44	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:2	13.63	1105	0.94	13.41	99	196	Idle	88.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.42	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:3	13.63	1105	0.93	13.38	99	196	Idle	89.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.48	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:3	13.63	1098	0.93	13.41	99	196	Idle	89.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.46	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:3	13.63	1070	0.92	13.39	99	196	Idle	89.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.48	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:3	13.63	1061	0.92	13.41	99	196	Idle	89.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.48	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:3	13.63	1061	0.91	13.39	99	196	Idle	89.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.49	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:3	13.63	1071	0.91	13.41	99	197	Idle	90.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.51	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:4	12.27	1071	0.9	13.39	99	197	Idle	90.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.47	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:4	12.27	1059	0.9	13.39	99	196	Idle	90.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.45	20.23	1.38	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:4	12.27	1047	0.9	13.41	99	196	Idle	90.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.42	20.23	1.38	5	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:4	12.27	1016	0.89	13.39	99	196	Idle	91	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.42	20.23	1.38	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:4	12.27	1016	0.89	13.39	99	196	Idle	91.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.4	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:4	12.27	1025	0.89	13.4	99	196	Idle	91.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.37	20.21	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:4	12.27	1025	0.89	13.4	99	196	Idle	91.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.37	20.14	1.37	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:5	12.27	1022	0.88	13.4	99	196	Idle	91.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.38	20.01	1.36	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:5	12.27	1022	0.88	13.41	99	196	Idle	91.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.38	19.83	1.35	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:5	12.27	1014	0.88	13.4	99	196	Idle	91.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	19.47	1.33	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:5	12.27	1005	0.88	13.41	99	196	Idle	91.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.33	19.18	1.31	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:5	12.27	1005	0.87	13.42	99	196	Idle	91	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.27	18.86	1.28	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:5	12.27	988	0.87	13.4	99	196	Idle	91	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.27	18.33	1.25	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:6	12.27	981	0.87	13.41	99	196	Idle	91	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	17.96	1.22	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:6	10.9	986	0.87	13.4	99	196	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	17.58	1.2	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:6	10.9	986	0.87	13.4	99	196	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.16	17.23	1.17	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:50:6	10.9	979	0.87	13.38	99	197	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.16	16.93	1.15	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:6	10.9	972	0.86	13.4	99	197	Idle	90.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.13	16.57	1.13	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:6	10.9	944	0.86	13.4	99	197	Idle	90.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.14	16.37	1.12	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:6	10.9	944	0.86	13.4	99	196	Idle	90.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.1	16.2	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:7	10.9	944	0.86	13.4	99	196	Idle	90.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.1	16.14	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:50:7	10.9	946	0.86	13.41	99	196	Idle	90.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.06	15.95	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:7	10.9	946	0.86	13.41	99	196	Idle	91.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.06	15.86	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:7	10.9	935	0.86	13.41	99	196	Idle	91.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8	15.82	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:7	10.9	935	0.86	13.4	99	196	Idle	91.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.01	15.78	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:7	10.9	932	0.86	13.4	99	196	Idle	91.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.99	15.77	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:8	10.9	930	0.86	13.4	99	196	Idle	91.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.99	15.76	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:8	10.9	927	0.86	13.4	99	196	Idle	92	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.93	15.76	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:8	10.9	927	0.86	13.4	99	196	Idle	92.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.91	15.77	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:8	10.9	913	0.85	13.41	99	196	Idle	92.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.87	15.77	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:8	10.9	926	0.85	13.4	99	197	Idle	92.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.89	15.77	1.07	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:8	9.54	938	0.85	13.41	99	197	Idle	92.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.85	15.78	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:9	9.54	938	0.85	13.41	99	197	Idle	92.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.87	15.78	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:9	9.54	933	0.85	13.41	99	196	Idle	93	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.85	15.81	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:9	9.54	933	0.85	13.4	99	196	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.87	15.83	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:9	9.54	931	0.84	13.4	99	196	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.83	15.84	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:9	9.54	926	0.84	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.86	15.85	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:9	9.54	924	0.84	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.82	15.85	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:50:9	9.54	916	0.84	13.42	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.84	15.85	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:0	9.54	916	0.84	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.81	15.86	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:0	9.54	916	0.83	13.42	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.84	15.87	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:0	9.54	916	0.83	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.81	15.86	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:0	9.54	934	0.83	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.81	15.84	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:0	9.54	920	0.83	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.82	15.82	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:0	9.54	920	0.83	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.82	15.81	1.08	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:1	9.54	920	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.83	15.81	1.08	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:1	9.54	920	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.85	15.79	1.08	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:1	9.54	936	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.81	15.77	1.07	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:1	9.54	936	0.82	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.85	15.75	1.07	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:1	9.54	927	0.82	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.8	15.73	1.07	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:1	9.54	938	0.82	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.83	15.72	1.07	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:1	8.18	938	0.82	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.83	15.7	1.07	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:2	8.18	938	0.82	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.84	15.69	1.07	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:2	8.18	926	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.8	15.66	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:2	8.18	926	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.83	15.64	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:2	9.54	929	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15.61	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:2	9.54	929	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.8	15.59	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:2	9.54	924	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	15.57	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:3	9.54	924	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	15.55	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:3	8.18	920	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.52	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:3	8.18	920	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.88	15.49	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:3	8.18	934	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.85	15.45	1.05	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:3	8.18	934	0.81	13.42	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.86	15.42	1.05	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:3	8.18	916	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.86	15.39	1.05	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:4	8.18	916	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	15.38	1.05	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:4	8.18	916	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.35	1.05	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:4	8.18	916	0.81	13.42	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	15.32	1.04	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:4	6.81	888	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.3	1.04	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:4	6.81	888	0.81	13.42	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	15.28	1.04	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:4	6.81	888	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	15.24	1.04	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:12:51:4	6.81	891	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:5	6.81	891	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	15.2	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:5	8.18	890	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15.17	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:5	8.18	888	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.16	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:51:5	8.18	893	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.77	15.13	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:5	8.18	893	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.74	15.11	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:5	8.18	899	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.76	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:6	8.18	899	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.75	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:6	8.18	886	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.73	15.05	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:6	8.18	886	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.73	15.03	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:6	9.54	884	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.72	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:6	9.54	884	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.72	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:6	9.54	888	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.7	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:6	9.54	888	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.71	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:7	8.18	882	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.7	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:7	8.18	882	0.81	13.42	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.67	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:7	8.18	876	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.66	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:7	8.18	896	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:7	8.18	896	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.93	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:7	9.54	897	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.92	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:8	9.54	895	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.91	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:8	9.54	893	0.8	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.91	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:8	9.54	893	0.8	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.9	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:8	8.18	903	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:8	8.18	900	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:8	8.18	897	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:9	8.18	897	0.8	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:9	8.18	900	0.8	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.9	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:9	8.18	900	0.8	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.91	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:9	8.18	914	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.92	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:9	8.18	914	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:9	8.18	895	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:51:9	8.18	895	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:0	8.18	896	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:0	8.18	896	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:0	8.18	896	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:0	8.18	904	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:0	8.18	892	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.68	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:0	8.18	892	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.67	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:1	8.18	892	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.67	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:1	9.54	898	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.66	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:1	9.54	900	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.68	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:1	9.54	895	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.67	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:1	9.54	905	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.69	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:1	8.18	905	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.67	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:1	8.18	905	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:2	8.18	902	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.7	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:2	8.18	902	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.7	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:2	9.54	906	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:2	9.54	910	0.8	13.42	99	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.18	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:2	9.54	888	0.8	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.17	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:2	9.54	888	0.8	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:3	8.18	896	0.8	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:3	8.18	905	0.8	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:3	8.18	910	0.8	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:3	8.18	910	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	15.14	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:3	8.18	893	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	15.15	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:3	8.18	893	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.75	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:4	8.18	897	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.74	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:4	8.18	901	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.73	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:4	8.18	901	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.72	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:4	8.18	906	0.8	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.7	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:52:4	8.18	896	0.8	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.7	15.13	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:4	8.18	886	0.8	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.67	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:4	8.18	886	0.8	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.69	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:5	8.18	878	0.8	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.68	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:5	8.18	878	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:5	8.18	878	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.73	15.03	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:5	8.18	880	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	15.02	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:5	9.54	889	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:5	9.54	889	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:6	9.54	892	0.8	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.66	14.97	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:6	9.54	892	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.66	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:6	8.18	890	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:6	8.18	887	0.8	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.99	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:6	8.18	905	0.8	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:6	8.18	905	0.8	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:6	8.18	904	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:7	8.18	904	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:7	8.18	904	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:7	8.18	898	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:7	8.18	898	0.8	13.42	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:7	8.18	885	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:7	8.18	877	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:8	8.18	877	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:8	8.18	877	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:8	6.81	899	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:8	6.81	899	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:52:8	6.81	882	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:8	6.81	882	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.9	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:9	6.81	871	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	14.94	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:9	6.81	871	0.8	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:9	6.81	871	0.8	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:9	6.81	879	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.68	15	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:9	6.81	885	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.67	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:9	6.81	885	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.65	15.01	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:52:9	6.81	885	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.66	15.02	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:53:0	6.81	894	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.62	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:0	6.81	894	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.66	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:0	6.81	891	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.65	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:0	6.81	891	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.67	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:0	6.81	900	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.68	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:0	6.81	900	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.68	15.07	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:1	6.81	881	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.66	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:1	6.81	881	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:1	6.81	881	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.63	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:1	6.81	900	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.6	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:1	8.18	883	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:1	8.18	883	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.54	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:1	8.18	883	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.59	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:2	8.18	884	0.8	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.57	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:2	8.18	880	0.8	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:2	8.18	875	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.59	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:2	8.18	875	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:2	8.18	878	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.62	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:2	8.18	878	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.6	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:3	8.18	865	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:3	8.18	865	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.59	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:3	8.18	866	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.57	15.03	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:53:3	8.18	867	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	15.02	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:53:3	9.54	872	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.57	14.99	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:53:3	9.54	872	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.57	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:53:4	9.54	870	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.58	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:53:4	9.54	869	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.57	14.96	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:53:4	9.54	869	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:53:4	6.81	869	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.58	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:53:4	6.81	869	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.58	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:53:4	6.81	897	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.55	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:4	6.81	897	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.56	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:5	9.54	887	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.53	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:5	9.54	887	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.53	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:5	9.54	880	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.53	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:5	9.54	880	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.54	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:5	9.54	916	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.53	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:5	9.54	916	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.52	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:6	9.54	890	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.53	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:6	9.54	890	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.53	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:6	8.18	908	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.55	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:6	8.18	908	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.58	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:6	8.18	904	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.6	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:6	8.18	900	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.63	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:6	10.9	909	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:7	10.9	909	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:7	10.9	890	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.83	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:7	10.9	870	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:7	10.9	888	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:7	8.18	888	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:7	8.18	888	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:8	8.18	900	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:8	8.18	900	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:8	8.18	906	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:8	8.18	906	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:8	8.18	898	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:8	8.18	898	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:9	8.18	900	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:9	8.18	901	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:9	8.18	905	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.66	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:9	8.18	905	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:9	8.18	910	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:9	8.18	910	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:53:9	8.18	910	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:0	8.18	906	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:0	8.18	905	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:0	8.18	905	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:0	8.18	904	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:0	8.18	904	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:0	8.18	898	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.74	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:1	6.81	898	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.74	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:1	6.81	898	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.77	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:1	6.81	902	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.72	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:1	6.81	902	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.72	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:1	8.18	900	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:1	8.18	900	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:1	8.18	907	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:2	8.18	907	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:2	8.18	895	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:2	8.18	895	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:2	8.18	904	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:54:2	8.18	904	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:2	8.18	904	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:3	8.18	903	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:3	8.18	900	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:3	8.18	900	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:3	8.18	900	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:3	8.18	891	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:3	8.18	896	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:4	8.18	896	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:4	8.18	896	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:4	8.18	902	0.81	13.36	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:4	8.18	902	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:4	8.18	902	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:4	8.18	901	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:4	8.18	888	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:5	8.18	888	0.81	13.42	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:5	8.18	880	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:5	8.18	880	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:5	8.18	880	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:5	8.18	880	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:5	8.18	885	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:6	8.18	890	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:6	8.18	890	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:6	8.18	889	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:6	8.18	898	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:6	8.18	908	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:6	8.18	908	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:6	8.18	908	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:7	8.18	901	0.81	13.42	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:7	8.18	897	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:7	8.18	897	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:7	8.18	903	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:7	8.18	903	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:7	8.18	905	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:8	8.18	905	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:8	8.18	906	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:8	8.18	906	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:8	8.18	900	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:8	8.18	900	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:8	8.18	896	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:9	8.18	893	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:9	8.18	876	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:9	8.18	876	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:9	8.18	888	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:9	8.18	900	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:9	8.18	900	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:54:9	8.18	890	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:0	8.18	890	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:0	9.54	886	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:0	9.54	886	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:0	9.54	867	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:0	9.54	867	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:0	9.54	893	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:1	9.54	893	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:1	9.54	877	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:1	9.54	877	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:1	8.18	878	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:1	8.18	880	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.63	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:55:1	8.18	882	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.63	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:1	8.18	882	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.61	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:2	8.18	882	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.64	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:2	6.81	895	0.81	13.4	99	197	Idle	93.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.64	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:2	6.81	899	0.81	13.39	99	197	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:2	6.81	899	0.81	13.39	99	197	Idle	93.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.64	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:2	6.81	899	0.81	13.39	99	197	Idle	93.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:2	6.81	888	0.81	13.38	99	197	Idle	93.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.63	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:3	6.81	888	0.81	13.39	99	197	Idle	93.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.61	14.85	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:3	6.81	864	0.81	13.38	99	197	Idle	93.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.59	14.84	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:3	6.81	864	0.81	13.4	99	197	Idle	93.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.59	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:3	8.18	868	0.81	13.39	99	196	Idle	93.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.58	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:3	8.18	871	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.58	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:3	8.18	857	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.57	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:4	8.18	857	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.57	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:4	8.18	858	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.56	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:4	8.18	860	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.53	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:4	8.18	860	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.52	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:4	8.18	854	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.51	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:4	8.18	854	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.52	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:4	8.18	854	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.51	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:5	8.18	853	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.53	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:5	8.18	852	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.52	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:5	8.18	851	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.49	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:5	9.54	851	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.49	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:5	9.54	845	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.46	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:5	9.54	846	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.43	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:6	9.54	847	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.44	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:6	9.54	849	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.43	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:6	9.54	849	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.42	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:6	9.54	849	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.44	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:6	9.54	863	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.43	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:6	9.54	863	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.44	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:6	9.54	866	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.43	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:7	9.54	870	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.44	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:7	9.54	873	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.45	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:7	9.54	873	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.45	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:7	8.18	880	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.48	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:7	8.18	887	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.43	14.9	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:7	8.18	906	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.51	14.91	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:55:8	8.18	906	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.48	14.94	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:8	8.18	906	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.5	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:8	8.18	897	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.48	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:8	8.18	897	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.5	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:8	8.18	898	0.81	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.48	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:8	8.18	898	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.49	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:9	9.54	917	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.49	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:9	9.54	917	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.56	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:9	9.54	905	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.55	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:9	9.54	905	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.53	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:9	9.54	902	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.58	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:9	9.54	899	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.61	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:55:9	9.54	915	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.62	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:0	9.54	915	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.62	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:0	9.54	915	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.64	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:0	9.54	918	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.61	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:0	9.54	921	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	15.2	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:0	9.54	921	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:56:0	9.54	921	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.22	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:1	9.54	905	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.23	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:1	9.54	894	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.24	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:1	9.54	894	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:1	8.18	901	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.24	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:1	8.18	908	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:1	8.18	910	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:1	8.18	910	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.23	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:2	8.18	910	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	15.22	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:2	8.18	894	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:2	8.18	894	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.19	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:2	8.18	901	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:2	8.18	901	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:2	8.18	902	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:3	8.18	902	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:3	8.18	907	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:3	8.18	907	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:3	8.18	881	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.69	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:3	8.18	881	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.67	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:3	8.18	881	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.67	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:4	8.18	883	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.65	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:4	8.18	878	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.65	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:4	8.18	878	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.64	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:4	8.18	886	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.66	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:4	8.18	895	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.62	15.02	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:4	8.18	895	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.66	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:4	9.54	871	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.64	14.98	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:5	9.54	868	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.68	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:5	9.54	865	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.66	14.9	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:5	9.54	865	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.66	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:5	8.18	874	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:5	8.18	884	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.63	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:5	8.18	902	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.61	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:6	8.18	902	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.64	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:6	9.54	898	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.64	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:6	9.54	894	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.63	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:6	9.54	894	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:56:6	9.54	894	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:6	9.54	913	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:6	8.18	932	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:7	8.18	932	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:7	8.18	909	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:7	8.18	921	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:7	8.18	921	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:7	8.18	918	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:7	8.18	914	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:8	8.18	905	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:8	8.18	905	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:8	8.18	904	0.81	13.36	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:8	8.18	904	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.66	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:8	8.18	904	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.71	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:8	9.54	896	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:9	9.54	896	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:9	9.54	896	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:9	9.54	882	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:9	8.18	886	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:9	8.18	890	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.71	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:56:9	8.18	893	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:56:9	8.18	893	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:0	8.18	894	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:0	8.18	894	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:0	8.18	890	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:0	8.18	890	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:0	8.18	890	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:0	8.18	878	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:1	8.18	881	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.06	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:1	8.18	881	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	15.06	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:1	8.18	881	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:1	9.54	877	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.65	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:1	9.54	877	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.63	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:1	9.54	886	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.61	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:1	9.54	894	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.62	15.05	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:2	9.54	884	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.58	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:2	9.54	873	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.6	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:2	9.54	898	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.61	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:2	9.54	898	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.62	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:2	9.54	901	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.64	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:2	9.54	904	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.67	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:3	9.54	917	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.69	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:3	9.54	917	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.66	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:3	9.54	908	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:3	9.54	908	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.65	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:3	9.54	903	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.66	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:3	9.54	903	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.66	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:4	9.54	903	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.64	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:4	9.54	904	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.64	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:4	9.54	905	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.67	14.94	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:4	9.54	880	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.67	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:4	9.54	880	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.7	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:4	9.54	894	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:4	9.54	894	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.7	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:5	9.54	892	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:5	9.54	892	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.7	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:5	8.18	912	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:5	8.18	912	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:5	8.18	898	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:5	8.18	884	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:6	8.18	886	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:6	8.18	886	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.63	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:6	8.18	886	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.62	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:6	8.18	876	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.59	14.69	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:6	8.18	876	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.61	14.7	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:6	8.18	856	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.58	14.73	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:6	8.18	856	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.58	14.74	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:57:7	8.18	868	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.57	14.77	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:7	8.18	868	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.57	14.79	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:7	6.81	865	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.58	14.8	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:7	6.81	865	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.58	14.8	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:7	6.81	872	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.61	14.8	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:7	6.81	878	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.62	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:8	6.81	867	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.64	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:8	8.18	867	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:8	8.18	867	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.64	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:8	8.18	866	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:8	8.18	869	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:8	8.18	872	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:57:9	8.18	872	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:9	8.18	877	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:9	8.18	877	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.94	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:9	8.18	873	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:9	8.18	873	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:9	8.18	875	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.56	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:57:9	8.18	877	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.53	14.94	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:0	8.18	888	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.54	14.94	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:0	8.18	888	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.53	14.94	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:0	8.18	888	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.57	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:0	8.18	889	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:0	8.18	885	0.81	13.42	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:0	6.81	885	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.54	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:1	6.81	885	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	14.96	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:1	6.81	885	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.56	14.97	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:1	6.81	899	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.59	14.98	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:1	6.81	902	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.59	14.99	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:1	6.81	902	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.63	15	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:58:1	6.81	908	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.62	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:1	6.81	915	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.62	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:2	8.18	900	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.61	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:2	8.18	900	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.63	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:2	8.18	903	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.64	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:2	8.18	906	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:2	8.18	910	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:2	8.18	914	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:3	8.18	916	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:3	8.18	916	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:3	6.81	912	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:3	6.81	909	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:3	6.81	910	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:3	6.81	910	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:4	6.81	904	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:4	8.18	897	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:4	8.18	897	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.7	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:4	8.18	888	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:4	8.18	878	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:4	8.18	890	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:4	8.18	890	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:5	8.18	898	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:5	8.18	898	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:5	9.54	900	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:5	9.54	900	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:5	9.54	894	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:5	9.54	894	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:6	8.18	894	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:6	8.18	895	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:6	8.18	900	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:6	8.18	900	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:6	9.54	900	0.81	13.36	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:6	9.54	911	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:6	9.54	906	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:7	9.54	906	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:7	9.54	902	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.85	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:7	8.18	888	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:7	8.18	888	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:7	8.18	894	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.69	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:7	8.18	901	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.74	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:58:8	8.18	899	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.71	14.78	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:8	8.18	899	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.7	14.77	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:8	8.18	895	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.7	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:8	8.18	895	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.7	14.75	1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:8	8.18	892	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.74	1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:8	8.18	892	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.67	14.73	1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:9	8.18	892	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	14.74	1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:9	8.18	910	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.72	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:9	8.18	916	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	14.73	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:9	8.18	916	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.74	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:9	8.18	911	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.75	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:9	8.18	906	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.77	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:58:9	6.81	908	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.79	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:0	6.81	908	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.8	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:0	6.81	906	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.8	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:0	6.81	905	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:0	8.18	905	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:0	8.18	906	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.7	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:0	8.18	905	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.73	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:1	8.18	904	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:1	8.18	904	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.71	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:1	8.18	894	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:1	8.18	894	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.7	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:1	8.18	892	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.68	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:1	8.18	892	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.7	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:1	8.18	895	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.67	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:2	8.18	895	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:2	8.18	895	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:2	8.18	892	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:2	8.18	886	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:2	8.18	886	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.71	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:2	8.18	902	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:3	8.18	902	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:3	9.54	891	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	15.05	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:3	9.54	880	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:3	9.54	891	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15.09	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:3	9.54	891	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	15.09	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:3	9.54	899	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15.1	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:4	8.18	907	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	15.1	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:4	8.18	907	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:4	8.18	904	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:4	8.18	904	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:4	8.18	906	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:4	8.18	907	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:4	8.18	903	0.81	13.35	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:5	8.18	903	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:5	8.18	893	0.81	13.36	99	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.65	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:5	8.18	893	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.63	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:5	8.18	896	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.61	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:5	8.18	898	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.63	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:5	8.18	886	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.65	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:6	8.18	886	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.68	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:6	8.18	884	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.67	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:6	8.18	882	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.67	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:6	8.18	878	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.68	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:6	8.18	878	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.67	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:6	8.18	878	0.82	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.67	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:12:59:6	8.18	889	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.66	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:12:59:7	8.18	889	0.82	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.66	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:7	9.54	880	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.65	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:7	9.54	880	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.63	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:7	9.54	878	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.67	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:7	9.54	878	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.59	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:7	9.54	884	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.57	14.78	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:8	9.54	889	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.53	14.77	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:8	9.54	881	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.56	14.75	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:8	9.54	881	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.53	14.73	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:8	9.54	881	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.56	14.72	1	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:8	6.81	884	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.59	14.71	1	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:8	6.81	905	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.61	14.71	1	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:9	6.81	905	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.57	14.71	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:9	6.81	905	0.82	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.59	14.71	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:9	6.81	901	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.57	14.7	1	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:9	6.81	887	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.58	14.84	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:9	6.81	887	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.59	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:9	6.81	887	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.61	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:12:59:9	6.81	891	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.61	14.85	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:00:0	6.81	891	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.63	14.87	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:00:0	6.81	904	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.61	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:0	6.81	904	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.61	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:0	6.81	896	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.6	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:0	6.81	896	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.58	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:0	6.81	900	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.59	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:1	6.81	903	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.6	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:1	8.18	899	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.59	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:1	8.18	899	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.61	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:1	8.18	899	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:1	8.18	913	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:1	8.18	902	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:1	8.18	902	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:2	8.18	902	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:2	8.18	904	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:2	8.18	904	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:2	8.18	920	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:2	8.18	920	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:2	8.18	926	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.65	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:00:3	8.18	915	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15.02	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:00:3	6.81	904	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	15.02	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:00:3	6.81	904	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.7	15.01	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:00:3	6.81	917	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:3	6.81	917	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:3	8.18	907	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:4	8.18	907	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:4	8.18	899	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:4	8.18	899	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	15.01	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:4	9.54	889	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:4	9.54	879	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:4	9.54	883	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:4	9.54	887	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:5	8.18	901	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:5	8.18	901	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:5	8.18	894	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:5	8.18	887	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:5	8.18	889	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:5	8.18	889	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.7	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:6	8.18	894	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:00:6	8.18	899	0.81	13.35	99	197	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:6	8.18	899	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:6	9.54	905	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:6	9.54	905	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.64	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:6	9.54	898	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.62	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:6	9.54	892	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.66	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:7	9.54	890	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.65	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:7	9.54	890	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:7	9.54	890	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.65	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:7	9.54	895	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:7	9.54	902	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:7	9.54	902	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:8	9.54	902	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:8	9.54	894	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:8	9.54	910	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:8	9.54	910	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:8	9.54	910	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:8	9.54	881	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:9	9.54	899	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:9	8.18	917	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:9	8.18	917	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:9	8.18	915	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.66	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:9	8.18	899	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.76	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:9	8.18	899	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.75	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:00:9	8.18	899	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.71	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:0	8.18	898	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.72	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:0	8.18	896	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.71	14.72	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:0	8.18	911	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.74	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:0	8.18	911	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.73	14.75	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:0	8.18	913	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.73	14.76	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:0	8.18	915	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.75	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:1	6.81	914	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.73	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:1	6.81	914	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.7	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:1	6.81	923	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.7	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:1	6.81	923	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:1	6.81	910	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:1	8.18	910	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.71	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:1	8.18	912	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.74	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:2	8.18	914	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.73	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:2	8.18	915	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.78	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:2	8.18	915	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.75	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:2	8.18	901	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.75	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:2	8.18	901	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:2	8.18	901	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:3	8.18	906	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:3	8.18	906	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:3	8.18	908	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:3	8.18	913	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:3	8.18	917	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:3	8.18	917	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:4	8.18	910	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:4	8.18	910	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:4	6.81	914	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.05	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:4	6.81	923	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:4	6.81	929	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:4	6.81	929	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:4	8.18	912	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:5	8.18	912	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:01:8	8.18	910	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	910	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	905	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	905	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	904	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	904	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	896	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	896	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	894	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	893	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	893	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	9.54	884	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:7	9.54	886	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:7	9.54	889	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:7	9.54	864	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.92	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:7	8.18	864	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	14.9	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:7	8.18	864	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:7	8.18	883	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	883	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	874	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	866	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.64	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	895	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.65	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	8.18	895	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.65	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:8	9.54	881	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.65	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:9	9.54	881	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.66	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:9	9.54	881	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.67	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:01:9	9.54	885	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.63	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:01:9	9.54	885	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.65	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:01:9	8.18	885	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.61	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:01:9	8.18	885	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.64	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:01:9	8.18	892	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.62	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:0	8.18	892	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.67	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:0	9.54	892	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.64	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:0	9.54	892	0.81	13.41	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.63	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:0	9.54	898	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.6	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:0	9.54	903	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.62	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:0	8.18	912	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.61	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:1	8.18	912	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.65	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:1	8.18	909	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:1	8.18	906	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:1	8.18	887	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.65	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:1	8.18	887	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.59	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:1	8.18	887	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.63	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:1	8.18	881	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.6	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:2	8.18	881	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.61	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:2	8.18	903	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.62	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:2	8.18	903	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:2	8.18	895	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.67	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:2	8.18	895	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.68	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:2	8.18	887	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.64	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:3	8.18	887	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.63	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:3	8.18	884	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.61	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:3	8.18	884	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.59	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:3	8.18	894	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:3	8.18	903	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:3	8.18	892	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:4	8.18	892	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:4	8.18	889	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:02:4	8.18	886	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:4	8.18	894	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:4	8.18	894	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:4	8.18	892	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.6	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:4	9.54	890	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:5	9.54	902	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:5	9.54	902	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:5	9.54	902	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.59	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:5	9.54	886	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.56	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:5	9.54	886	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:5	9.54	901	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.55	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:6	9.54	901	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:6	9.54	897	0.82	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:6	9.54	893	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:6	9.54	904	0.82	13.36	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:6	9.54	904	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.6	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:6	9.54	906	0.82	13.36	99	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.59	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:6	9.54	909	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.61	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:7	9.54	890	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.63	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:7	9.54	890	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.6	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:7	8.18	897	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.63	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:7	8.18	904	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.62	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:7	8.18	904	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.65	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:7	8.18	904	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.61	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:8	8.18	904	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.65	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:8	8.18	904	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.65	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:8	8.18	904	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:8	8.18	907	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:8	8.18	908	0.82	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:8	8.18	910	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:9	8.18	910	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:9	8.18	904	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:9	8.18	904	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:9	8.18	894	0.82	13.36	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:9	8.18	894	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:9	8.18	897	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:02:9	8.18	897	0.82	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:0	8.18	898	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:0	8.18	900	0.82	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:0	8.18	913	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:0	8.18	913	0.82	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:0	8.18	913	0.82	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:0	8.18	907	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:1	8.18	921	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:1	8.18	921	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:1	8.18	921	0.82	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:1	6.81	927	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:1	6.81	922	0.82	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.72	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:1	6.81	922	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.68	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:1	6.81	918	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.73	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:2	8.18	915	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.7	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:2	8.18	910	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.76	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:2	8.18	910	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:2	8.18	909	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.75	15.05	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:2	8.18	908	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.72	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:2	8.18	908	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.75	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:3	8.18	910	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:3	8.18	910	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.72	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:03:3	8.18	921	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:3	8.18	921	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:3	8.18	918	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.7	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:3	8.18	915	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.73	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:4	6.81	918	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.74	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:4	6.81	918	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.76	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:4	6.81	912	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.76	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:4	6.81	906	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.76	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:4	8.18	901	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.73	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:4	8.18	901	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:4	8.18	901	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:5	8.18	887	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:5	8.18	892	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:5	8.18	892	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:5	8.18	892	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:5	8.18	889	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:5	8.18	875	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:6	8.18	875	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:6	8.18	875	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:6	8.18	874	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:6	8.18	874	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:6	8.18	877	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:6	8.18	877	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:6	8.18	883	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.62	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:7	8.18	883	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:7	9.54	883	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.59	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:7	9.54	883	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.58	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:7	9.54	892	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.59	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:7	9.54	902	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.57	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:7	9.54	874	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.59	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:8	10.9	874	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.58	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:8	10.9	895	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	15.02	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:8	10.9	895	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	15.03	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:8	10.9	895	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:8	9.54	899	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:8	9.54	899	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:9	9.54	904	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:9	9.54	910	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.6	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:9	9.54	903	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.58	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:9	9.54	903	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.62	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:9	9.54	912	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.62	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:9	9.54	912	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:03:9	9.54	912	0.82	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:0	9.54	912	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:0	9.54	903	0.82	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:0	9.54	894	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:0	8.18	908	0.82	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:0	8.18	908	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:0	8.18	905	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:1	8.18	902	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:1	8.18	896	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:1	8.18	896	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:1	8.18	896	0.82	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	14.88	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:1	8.18	887	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:1	8.18	892	0.82	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:1	8.18	897	0.82	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:2	8.18	895	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:2	8.18	895	0.82	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:04:2	8.18	895	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.65	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:2	8.18	894	0.82	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.67	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:2	8.18	894	0.82	13.41	100	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.67	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:2	8.18	879	0.82	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.69	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:3	8.18	879	0.82	13.41	100	197	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.68	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:3	8.18	879	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.68	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:3	8.18	894	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:3	8.18	895	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:3	8.18	895	0.82	13.41	100	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.66	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:3	6.81	893	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:4	6.81	891	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:4	6.81	890	0.81	13.4	99	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:4	6.81	890	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.59	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:4	6.81	890	0.81	13.36	99	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:4	6.81	901	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:4	6.81	901	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:4	6.81	904	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:5	6.81	906	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.89	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:5	8.18	890	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:5	8.18	890	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:5	8.18	885	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:5	8.18	885	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:5	8.18	883	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:6	8.18	883	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:6	8.18	881	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.61	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:04:6	8.18	881	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.59	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:04:6	9.54	876	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.59	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:04:6	9.54	871	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.58	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:04:6	9.54	871	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.59	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:04:6	9.54	870	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.55	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:04:7	9.54	876	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.57	14.92	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:04:7	9.54	882	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.54	14.94	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:04:7	9.54	899	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.58	14.97	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:04:7	9.54	899	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.54	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:7	9.54	899	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.59	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:7	8.18	886	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.58	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:8	8.18	886	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.6	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:8	8.18	894	0.81	13.34	100	197	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.59	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:8	8.18	894	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.61	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:8	9.54	907	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.6	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:8	9.54	907	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.62	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:8	9.54	897	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.6	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:9	9.54	897	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.59	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:9	8.18	899	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.59	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:9	8.18	901	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.56	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:9	8.18	901	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.55	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:9	8.18	901	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.58	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:9	8.18	904	0.81	13.37	99	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.61	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:04:9	8.18	906	0.81	13.39	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:0	8.18	908	0.81	13.38	99	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:0	8.18	908	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:0	8.18	908	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:0	8.18	900	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:0	8.18	900	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:0	8.18	900	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.65	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:1	8.18	899	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:1	8.18	899	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:1	8.18	899	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:05:1	8.18	898	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:1	8.18	898	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:1	8.18	890	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:1	8.18	890	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:2	8.18	882	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:2	8.18	873	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:2	8.18	889	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:2	9.54	889	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.63	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:2	9.54	860	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:2	9.54	860	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:3	9.54	860	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:3	8.18	869	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.66	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:3	8.18	869	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.65	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:3	8.18	865	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.61	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:3	8.18	865	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.61	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:3	9.54	871	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.59	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:4	9.54	877	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.58	14.96	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:4	9.54	877	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.58	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:4	9.54	855	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.56	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:4	9.54	856	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.58	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:4	9.54	856	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.53	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:4	9.54	856	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.55	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:4	9.54	863	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.49	14.91	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:5	9.54	863	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.53	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:5	8.18	874	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.49	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:5	8.18	874	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.5	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:5	8.18	880	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.5	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:5	8.18	887	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.51	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:5	9.54	872	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.53	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:6	9.54	872	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.48	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:6	9.54	874	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.51	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:6	9.54	877	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.48	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:6	9.54	906	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.51	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:6	9.54	906	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.51	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:6	9.54	906	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.57	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:05:6	9.54	886	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.54	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:7	8.18	892	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:7	8.18	892	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:7	8.18	892	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:7	8.18	901	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:7	8.18	901	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:7	8.18	903	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.58	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:8	8.18	908	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:8	8.18	911	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.58	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:8	8.18	911	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.6	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:8	9.54	899	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.6	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:8	9.54	899	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.59	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:8	9.54	899	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.61	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:9	9.54	897	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.58	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:9	8.18	919	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.6	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:9	8.18	919	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.59	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:9	8.18	912	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.65	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:9	8.18	905	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.62	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:9	8.18	907	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:05:9	8.18	907	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.62	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:0	8.18	912	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:0	8.18	917	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.6	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:0	8.18	902	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	15.15	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:06:0	8.18	902	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:0	8.18	902	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:0	8.18	904	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.66	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:1	8.18	904	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:1	8.18	899	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:1	8.18	899	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:1	8.18	894	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:1	8.18	894	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:1	8.18	891	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:1	8.18	891	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:2	8.18	892	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:2	8.18	892	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:2	8.18	892	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:2	8.18	888	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:2	8.18	885	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:2	8.18	885	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:3	8.18	885	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	15.04	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:3	8.18	900	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	15.03	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:3	8.18	902	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.65	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:3	8.18	904	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.61	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:3	8.18	904	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:3	8.18	892	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.62	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:4	8.18	881	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.64	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:4	8.18	881	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.65	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:4	8.18	881	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.65	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:4	8.18	890	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.63	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:4	8.18	890	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.64	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:4	8.18	891	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:4	8.18	892	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.64	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:5	8.18	887	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.66	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:5	8.18	887	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.67	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:5	8.18	889	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:5	8.18	889	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.67	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:5	8.18	889	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.68	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:5	8.18	887	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.65	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:6	8.18	900	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.67	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:6	8.18	900	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.62	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:6	8.18	900	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.64	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:6	8.18	867	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.59	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:6	8.18	867	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.61	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:6	8.18	879	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.59	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:06:6	8.18	879	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.59	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:06:7	8.18	880	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.58	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:06:7	8.18	880	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.58	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:06:7	8.18	886	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.56	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:06:7	8.18	892	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.58	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:7	8.18	894	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.61	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:7	8.18	894	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.61	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:8	8.18	890	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.65	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:8	8.18	887	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:8	8.18	887	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.66	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:8	8.18	897	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.61	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:8	8.18	897	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:8	8.18	890	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.62	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:9	8.18	884	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.63	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:9	6.81	890	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.59	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:9	6.81	890	0.81	13.41	100	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.6	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:06:9	6.81	871	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.58	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:06:9	6.81	871	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.59	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:06:9	8.18	890	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.61	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:06:9	8.18	890	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.61	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:0	8.18	877	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.62	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:0	8.18	877	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.61	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:0	8.18	875	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.57	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:0	8.18	873	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.55	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:0	8.18	874	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.53	14.96	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:0	8.18	874	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.51	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:1	8.18	874	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.53	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:1	8.18	877	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.55	14.98	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:1	8.18	877	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.57	14.97	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:1	8.18	892	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:1	8.18	892	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:1	6.81	877	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	14.98	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:1	6.81	877	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	14.98	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:2	6.81	883	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	14.98	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:2	6.81	883	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.57	14.98	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:2	9.54	886	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.57	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:2	9.54	886	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.16	Rich	1	14.6	-7.57	14.99	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:2	9.54	890	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.54	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:07:2	9.54	894	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.57	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:3	9.54	894	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.58	15.03	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:3	8.18	864	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.55	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:3	8.18	864	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.55	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:3	8.18	886	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.56	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:3	8.18	886	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.55	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:3	9.54	879	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.55	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:4	9.54	905	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.57	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:4	9.54	905	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.58	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:4	9.54	905	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.58	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:4	8.18	892	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	15.07	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:4	8.18	879	0.81	13.37	100	197	Idle	93.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:4	8.18	895	0.81	13.36	100	197	Idle	93.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.57	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:4	8.18	895	0.81	13.38	100	197	Idle	93.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.57	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:5	8.18	898	0.81	13.37	100	197	Idle	93.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:5	8.18	900	0.81	13.38	100	198	Idle	93.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.57	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:5	8.18	904	0.81	13.37	100	198	Idle	93.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.63	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:5	8.18	904	0.81	13.38	100	198	Idle	93.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.59	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:5	8.18	903	0.81	13.37	100	198	Idle	93.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.66	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:5	8.18	902	0.81	13.37	100	198	Idle	93.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.61	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:6	8.18	902	0.81	13.37	100	197	Idle	93.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:6	8.18	902	0.81	13.36	100	197	Idle	93.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.62	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:6	8.18	912	0.81	13.36	100	197	Idle	93.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:6	8.18	912	0.81	13.35	100	197	Idle	93.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:6	8.18	905	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:6	8.18	905	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:6	8.18	898	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:7	8.18	895	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:7	8.18	895	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:7	8.18	895	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:7	8.18	895	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:7	8.18	879	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:7	8.18	879	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:8	8.18	879	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:8	8.18	894	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:8	9.54	894	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:8	9.54	889	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.59	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:07:8	9.54	884	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:8	9.54	886	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.59	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:9	9.54	886	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:9	9.54	898	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.58	14.86	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:9	9.54	898	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:9	9.54	874	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.62	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:9	9.54	874	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:9	6.81	882	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.59	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:07:9	6.81	890	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:0	6.81	899	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.61	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:0	6.81	899	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.58	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:0	8.18	902	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.64	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:0	8.18	902	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.68	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:0	8.18	892	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.69	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:0	8.18	881	0.81	13.41	100	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.66	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:1	8.18	876	0.81	13.41	100	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.7	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:1	8.18	876	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:1	8.18	878	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:1	8.18	878	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:1	8.18	878	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:1	9.54	888	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:1	9.54	888	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:2	9.54	880	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:08:2	9.54	880	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:08:2	9.54	865	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:08:2	9.54	865	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:08:2	9.54	883	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:08:2	9.54	883	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:08:3	9.54	883	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:08:3	9.54	881	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.8	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:08:3	9.54	888	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.79	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:08:3	9.54	888	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.78	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:3	9.54	888	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.79	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:3	8.18	907	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:4	8.18	918	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:4	8.18	918	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:4	8.18	918	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:4	8.18	894	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:4	8.18	894	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:4	8.18	900	0.81	13.4	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:4	8.18	905	0.82	13.4	100	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:5	8.18	899	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:5	8.18	899	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:5	8.18	900	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:5	8.18	900	0.81	13.4	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:5	8.18	900	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.65	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:5	8.18	900	0.81	13.4	100	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.66	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:6	8.18	899	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.63	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:6	8.18	899	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.64	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:6	8.18	896	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.66	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:6	8.18	893	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.65	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:6	8.18	897	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.66	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:6	8.18	897	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.64	15.16	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:6	8.18	897	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.66	15.16	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:7	8.18	897	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.63	15.16	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:7	8.18	897	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	15.17	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:7	8.18	908	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.17	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:7	8.18	900	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:08:7	8.18	891	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:7	8.18	891	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:8	8.18	893	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.56	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:8	8.18	893	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.57	15.16	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:8	8.18	891	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.57	15.16	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:8	8.18	889	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.59	15.15	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:8	8.18	894	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	15.15	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:8	8.18	894	0.81	13.35	100	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.58	15.14	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:9	8.18	896	0.81	13.35	100	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.58	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:9	8.18	899	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:9	8.18	898	0.81	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.6	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:9	8.18	898	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.62	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:9	8.18	898	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:9	8.18	904	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:08:9	8.18	904	0.81	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:0	8.18	902	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:0	8.18	893	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:0	8.18	893	0.81	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:0	8.18	893	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:0	8.18	898	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.61	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:0	8.18	898	0.81	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.64	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:1	8.18	882	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.6	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:1	8.18	882	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.61	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:1	8.18	892	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.61	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:1	8.18	892	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.63	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:1	8.18	896	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.63	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:1	8.18	896	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.66	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:1	8.18	901	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.66	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:2	8.18	901	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:2	9.54	910	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:2	9.54	920	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.6	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:2	9.54	890	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.6	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:2	9.54	890	0.82	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.61	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:2	8.18	890	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.63	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:3	8.18	895	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.59	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:3	8.18	901	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.59	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:3	8.18	907	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.61	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:3	8.18	907	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.61	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:3	8.18	904	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.63	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:3	8.18	906	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.65	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:4	8.18	908	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.63	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:4	8.18	908	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.67	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:4	6.81	909	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.63	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:4	6.81	914	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.65	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:4	6.81	914	0.82	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.64	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:4	6.81	914	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.64	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:4	8.18	922	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.63	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:5	8.18	922	0.82	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.65	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:5	8.18	914	0.82	13.35	100	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.62	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:5	8.18	907	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:5	6.81	895	0.82	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:5	6.81	895	0.82	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:5	6.81	902	0.82	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:6	6.81	909	0.82	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:6	8.18	905	0.82	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:6	8.18	901	0.82	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:6	8.18	897	0.82	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:6	8.18	893	0.82	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:09:6	8.18	893	0.82	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:6	8.18	903	0.82	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:7	8.18	904	0.82	13.39	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:7	8.18	906	0.82	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:7	8.18	906	0.82	13.4	100	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.89	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:7	8.18	901	0.82	13.4	100	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:7	8.18	901	0.82	13.43	100	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.91	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:7	8.18	904	0.82	13.43	100	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.62	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:8	8.18	908	0.82	13.45	100	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:8	8.18	905	0.82	13.43	100	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:8	8.18	905	0.82	13.43	100	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:8	8.18	908	0.82	13.42	100	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	15	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:8	8.18	911	0.82	13.43	100	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.71	15.02	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:8	8.18	920	0.82	13.4	100	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.67	15.03	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:9	8.18	920	0.82	13.42	100	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.68	15.04	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:09:9	8.18	914	0.82	13.4	100	198	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.67	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:9	8.18	909	0.82	13.42	100	198	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.69	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:9	6.81	918	0.82	13.42	100	198	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.65	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:9	6.81	918	0.82	13.43	100	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.65	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:9	6.81	918	0.82	13.42	100	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.65	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:9	6.81	914	0.82	13.42	100	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.67	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:0	8.18	919	0.82	13.41	100	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.68	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:0	8.18	919	0.82	13.42	100	197	Idle	93.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:0	8.18	919	0.82	13.4	100	197	Idle	93.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:0	8.18	919	0.82	13.42	100	198	Idle	93.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:0	8.18	920	0.82	13.41	100	198	Idle	93.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:0	8.18	921	0.82	13.4	100	198	Idle	93.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:1	8.18	907	0.82	13.4	100	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.74	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:1	8.18	907	0.82	13.41	100	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:1	8.18	907	0.82	13.41	100	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.71	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:1	8.18	915	0.82	13.41	100	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:1	8.18	920	0.82	13.41	100	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:1	8.18	920	0.82	13.43	100	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.73	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:1	8.18	920	0.82	13.43	100	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.74	15.05	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:2	8.18	903	0.82	13.43	100	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:2	8.18	906	0.82	13.43	100	198	Off Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:2	8.18	906	0.82	13.43	100	198	Off Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.63	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:2	8.18	914	0.83	13.43	100	198	Off Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.65	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:2	6.81	914	0.83	13.41	100	198	Off Idle	92.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.61	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:2	6.81	922	0.85	13.42	100	198	Off Idle	92.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.63	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:3	6.81	917	0.86	13.42	100	198	Off Idle	91.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.52	15.04	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:10:3	6.81	917	0.86	13.41	100	198	Off Idle	91.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.5	15.04	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:10:3	8.18	916	0.87	13.4	100	198	Off Idle	90.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.43	15.03	1.02	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:10:3	8.18	914	0.88	13.41	100	198	Off Idle	89.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.37	15.03	1.02	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:10:3	8.18	924	0.9	13.4	100	198	Off Idle	89.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.28	15	1.02	4.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:10:3	8.18	924	0.92	13.43	100	198	Off Idle	88.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.22	14.99	1.02	4.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:10:4	9.54	925	0.94	13.41	100	198	Off Idle	88.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.11	14.98	1.02	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:10:4	9.54	925	0.95	13.42	100	198	Off Idle	87.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.99	14.96	1.02	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:10:4	9.54	931	0.97	13.4	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.81	14.93	1.02	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:13:10:4	9.54	937	1	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.74	14.87	1.01	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:13:10:4	9.54	934	1.02	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.63	14.85	1.01	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:13:10:4	9.54	934	1.05	13.44	100	198	Off Idle	85.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.52	14.83	1.01	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:13:10:4	9.54	940	1.07	13.44	100	198	Off Idle	85.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.43	14.82	1.01	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:13:10:5	9.54	947	1.1	13.44	100	198	Off Idle	85.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.35	14.8	1.01	4.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:5	8.18	973	1.13	13.43	100	198	Off Idle	85.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.27	14.8	1.01	4.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:5	8.18	973	1.15	13.43	100	198	Off Idle	85.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.23	14.79	1.01	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:5	8.18	987	1.17	13.41	100	198	Off Idle	85.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.11	14.77	1.01	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:10:5	8.18	989	1.19	13.42	100	198	Off Idle	85.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.11	14.77	1.01	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:10:5	8.18	989	1.21	13.39	100	198	Off Idle	85.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.02	14.76	1.01	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:10:6	8.18	994	1.22	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.02	14.77	1.01	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:10:6	8.18	999	1.24	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.92	14.77	1.01	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:6	9.54	999	1.25	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.91	14.78	1.01	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:6	9.54	997	1.26	13.4	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.82	14.8	1.01	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:6	9.54	1007	1.26	13.42	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-5.8	14.81	1.01	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:6	9.54	1007	1.27	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.7	Lean	1	14.6	-5.71	14.82	1.01	4.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:6	9.54	1002	1.28	13.41	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.74	Lean	1	14.6	-5.71	14.84	1.01	4.8	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:7	9.54	996	1.28	13.41	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.66	14.85	1.01	4.8	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:7	9.54	999	1.29	13.41	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.64	14.85	1.01	4.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:7	9.54	999	1.29	13.44	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.59	14.85	1.01	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:7	9.54	999	1.3	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.47	14.84	1.01	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:7	9.54	999	1.31	13.44	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.44	14.83	1.01	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:10:7	9.54	1010	1.31	13.4	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.37	14.83	1.01	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:10:8	9.54	1027	1.33	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.28	14.83	1.01	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:10:8	10.9	1027	1.33	13.4	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.18	14.87	1.01	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:10:8	10.9	1028	1.34	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.17	14.89	1.01	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:10:8	10.9	1028	1.35	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.07	14.9	1.02	4.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:10:8	10.9	1028	1.36	13.43	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.99	14.91	1.02	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:10:8	10.9	1027	1.38	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.86	14.91	1.02	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:10:9	10.9	1037	1.39	13.41	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.82	14.9	1.02	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:10:9	10.9	1037	1.41	13.43	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.72	14.9	1.01	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:10:9	10.9	1037	1.42	13.41	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.65	14.87	1.01	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:10:9	10.9	1037	1.43	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.61	14.85	1.01	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:10:9	10.9	1041	1.44	13.4	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.54	14.76	1.01	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:10:9	10.9	1041	1.45	13.42	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.47	14.69	1	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:10:9	10.9	1042	1.46	13.4	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.44	14.6	0.99	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:11:0	10.9	1042	1.47	13.42	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.38	14.55	0.99	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:11:0	10.9	1043	1.48	13.4	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.28	14.4	0.98	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:11:0	12.27	1043	1.49	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.28	14.29	0.97	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:11:0	12.27	1039	1.51	13.41	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.09	14.13	0.96	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:11:0	12.27	1037	1.52	13.41	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.04	14.03	0.96	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:11:0	12.27	1039	1.53	13.43	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.94	13.93	0.95	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:11:1	13.63	1045	1.53	13.4	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.88	13.83	0.94	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:11:1	13.63	1045	1.54	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.82	13.68	0.93	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:11:1	13.63	1021	1.55	13.39	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.73	13.6	0.93	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:13:11:1	13.63	1031	1.56	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.71	13.54	0.92	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:13:11:1	13.63	1031	1.56	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.62	13.49	0.92	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:13:11:1	13.63	1031	1.57	13.43	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.58	13.43	0.91	4.6	4	ON	28 Pin	OFF	Removed	Disabled
03:13:11:1	13.63	1033	1.58	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.44	13.4	0.91	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:11:2	21.81	1070	1.58	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.42	13.38	0.91	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:11:2	21.81	1070	1.59	13.43	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.26	13.38	0.91	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:11:2	21.81	1054	1.6	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.22	13.37	0.91	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:2	21.81	1038	1.61	13.43	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.13	13.38	0.91	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:2	20.45	1042	1.62	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.14	13.4	0.91	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:2	20.45	1042	1.62	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.04	13.42	0.91	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:3	20.45	1065	1.63	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.96	13.43	0.91	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:3	20.45	1065	1.64	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.91	13.43	0.91	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:3	20.45	1078	1.64	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.84	13.44	0.92	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:3	20.45	1078	1.65	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.85	13.44	0.92	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:3	20.45	1082	1.66	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.76	13.43	0.91	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:3	21.81	1102	1.66	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.77	13.42	0.91	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:4	21.81	1102	1.67	13.43	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.74	13.4	0.91	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:4	21.81	1083	1.67	13.42	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.73	13.38	0.91	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:4	20.45	1096	1.68	13.45	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.76	13.36	0.91	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:4	20.45	1096	1.68	13.43	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.65	13.33	0.91	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:4	20.45	1106	1.69	13.43	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.71	13.3	0.91	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:4	20.45	1117	1.69	13.42	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.68	13.29	0.91	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:11:4	21.81	1101	1.7	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.62	13.25	0.9	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:5	21.81	1099	1.7	13.44	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.58	13.23	0.9	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:5	21.81	1099	1.71	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.55	13.21	0.9	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:5	21.81	1106	1.71	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.49	13.19	0.9	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:5	21.81	1114	1.72	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.44	13.19	0.9	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:5	21.81	1122	1.72	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.46	13.17	0.9	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:11:5	21.81	1109	1.72	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.46	13.15	0.9	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:11:6	21.81	1109	1.73	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.37	13.12	0.89	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:11:6	21.81	1117	1.73	13.42	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.39	13.1	0.89	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:11:6	21.81	1125	1.73	13.41	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.33	13.07	0.89	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:6	21.81	1125	1.73	13.41	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.37	13.06	0.89	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:6	21.81	1141	1.74	13.42	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.37	13.02	0.89	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:6	21.81	1142	1.74	13.4	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.38	12.99	0.89	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:6	21.81	1142	1.74	13.42	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.42	12.97	0.88	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:7	21.81	1121	1.74	13.41	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.44	12.96	0.88	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:7	21.81	1125	1.75	13.4	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.44	12.94	0.88	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:7	21.81	1125	1.75	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.42	12.92	0.88	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:7	23.18	1130	1.75	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.39	12.91	0.88	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:7	23.18	1118	1.75	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.4	12.9	0.88	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:7	23.18	1118	1.75	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.36	12.87	0.88	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:8	20.45	1104	1.75	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.42	12.85	0.88	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:8	20.45	1090	1.75	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.37	12.83	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:8	20.45	1110	1.75	13.41	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.42	12.82	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:8	20.45	1087	1.75	13.43	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.38	12.79	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:8	20.45	1087	1.75	13.4	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.34	12.78	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:8	20.45	1081	1.75	13.4	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.36	12.75	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:9	20.45	1081	1.75	13.38	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.28	12.74	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:9	23.18	1077	1.75	13.39	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.31	12.73	0.87	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:9	23.18	1073	1.75	13.39	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.21	12.72	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:9	23.18	1058	1.74	13.38	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.15	12.71	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:9	23.18	1042	1.74	13.42	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.16	12.7	0.87	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:9	23.18	1042	1.74	13.4	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.08	12.69	0.86	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:11:9	23.18	1042	1.74	13.43	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.1	12.68	0.86	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:12:0	23.18	1041	1.74	13.43	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.09	12.68	0.86	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:0	23.18	1030	1.73	13.42	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.13	12.66	0.86	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:0	23.18	1030	1.73	13.43	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.07	12.65	0.86	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:0	23.18	1018	1.73	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.15	12.64	0.86	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:0	23.18	1018	1.72	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.11	12.62	0.86	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:0	21.81	1001	1.72	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.09	12.61	0.86	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:1	21.81	1001	1.71	13.44	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.05	12.58	0.86	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:1	21.81	994	1.71	13.41	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.06	12.56	0.86	4.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:1	21.81	994	1.71	13.44	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2.03	12.53	0.85	4.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:1	21.81	980	1.7	13.41	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2.02	12.52	0.85	4.9	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:1	21.81	980	1.7	13.44	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.96	12.48	0.85	4.9	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:1	21.81	980	1.69	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.95	12.43	0.85	4.9	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:1	21.81	964	1.69	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.92	12.39	0.84	4.9	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:2	23.18	964	1.69	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.88	12.36	0.84	4.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:2	23.18	964	1.68	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.92	12.33	0.84	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:2	23.18	965	1.68	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.87	12.27	0.84	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:2	23.18	965	1.67	13.44	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.87	12.24	0.83	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:2	23.18	963	1.67	13.43	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.88	12.22	0.83	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:2	23.18	963	1.67	13.43	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.91	12.19	0.83	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:3	23.18	969	1.66	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.85	12.15	0.83	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:3	23.18	990	1.66	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.91	12.13	0.83	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:3	23.18	1006	1.66	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.89	12.11	0.83	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:3	23.18	1010	1.65	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.95	12.11	0.83	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:12:3	23.18	1010	1.65	13.44	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.96	12.1	0.82	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:12:3	23.18	1010	1.65	13.44	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.96	12.08	0.82	4.6	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:12:4	20.45	1050	1.65	13.47	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.01	12.06	0.82	4.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:12:4	20.45	1082	1.65	13.46	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.03	12.08	0.82	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:13:12:4	20.45	1082	1.65	13.48	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.05	12.08	0.82	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:13:12:4	20.45	1122	1.66	13.45	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.11	12.08	0.82	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:13:12:4	20.45	1138	1.66	13.46	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.13	12.08	0.82	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:13:12:4	20.45	1138	1.66	13.42	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.25	12.07	0.82	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:4	20.45	1163	1.67	13.42	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.28	12.06	0.82	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:5	20.45	1163	1.67	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.34	12.06	0.82	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:5	20.45	1182	1.68	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.35	12.06	0.82	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:5	21.81	1187	1.69	13.43	100	198	Off Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.41	12.06	0.82	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:5	21.81	1187	1.69	13.44	100	198	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.44	12.03	0.82	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:5	21.81	1197	1.7	13.43	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.46	12.04	0.82	4.3	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:5	21.81	1200	1.71	13.45	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.51	12.03	0.82	4.3	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:6	21.81	1200	1.72	13.44	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.5	12.03	0.82	4.3	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:6	21.81	1210	1.72	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.56	12.04	0.82	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:6	21.81	1221	1.73	13.44	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.58	12.05	0.82	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:6	21.81	1223	1.74	13.43	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.56	12.05	0.82	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:12:6	21.81	1227	1.74	13.42	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.59	12.07	0.82	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:12:6	21.81	1236	1.75	13.44	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.61	12.08	0.82	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:12:6	21.81	1241	1.76	13.43	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.6	12.1	0.82	4.3	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:12:7	21.81	1253	1.76	13.42	100	198	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.63	12.11	0.83	4.3	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:12:7	21.81	1279	1.77	13.44	100	198	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.68	12.14	0.83	4.3	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:12:7	21.81	1279	1.78	13.43	100	198	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.7	12.16	0.83	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:12:7	21.81	1284	1.78	13.42	100	198	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.74	12.19	0.83	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:12:7	21.81	1301	1.79	13.42	100	198	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.78	12.25	0.83	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:12:7	21.81	1320	1.79	13.42	100	198	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.79	12.3	0.84	4.3	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:12:8	21.81	1320	1.8	13.41	100	198	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.8	12.37	0.84	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:12:8	23.18	1336	1.8	13.41	100	198	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.84	12.44	0.85	4.2	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:12:8	23.18	1363	1.81	13.43	100	198	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.89	12.5	0.85	4.2	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:12:8	23.18	1373	1.81	13.42	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.94	12.57	0.86	4.2	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:12:8	23.18	1374	1.82	13.42	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.95	12.65	0.86	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:12:8	23.18	1374	1.82	13.42	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.02	12.72	0.87	4.2	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:12:9	23.18	1386	1.83	13.42	100	198	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.03	12.84	0.87	4.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:12:9	23.18	1394	1.83	13.4	100	198	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.03	12.91	0.88	4.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:12:9	23.18	1402	1.84	13.41	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.02	12.98	0.88	4.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:12:9	23.18	1402	1.84	13.41	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.08	13.08	0.89	4.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:12:9	23.18	1411	1.85	13.42	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.14	13.14	0.9	4.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:12:9	23.18	1430	1.85	13.42	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.11	13.2	0.9	4.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:12:9	23.18	1424	1.86	13.4	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.12	13.25	0.9	4.3	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:0	23.18	1424	1.86	13.41	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.21	13.3	0.91	4.3	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:0	23.18	1433	1.87	13.42	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.26	13.37	0.91	4.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:0	24.54	1457	1.87	13.43	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.27	13.42	0.91	4.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:0	24.54	1462	1.88	13.42	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.28	13.46	0.92	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:0	25.9	1462	1.88	13.42	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.3	13.5	0.92	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:0	25.9	1466	1.88	13.44	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.36	13.53	0.92	4.1	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:1	25.9	1487	1.89	13.43	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.36	13.56	0.92	4.1	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:1	25.9	1492	1.89	13.44	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.35	13.6	0.93	4.1	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:1	25.9	1505	1.89	13.42	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.39	13.63	0.93	4.1	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:1	25.9	1519	1.9	13.43	100	198	Off Idle	86.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.45	13.68	0.93	4.1	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:1	25.9	1528	1.9	13.44	100	198	Off Idle	86.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.48	13.71	0.93	4.1	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:1	25.9	1537	1.9	13.42	100	198	Off Idle	86.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.42	13.75	0.94	4.1	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:1	25.9	1556	1.91	13.43	100	198	Off Idle	86.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.49	13.79	0.94	4.1	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:2	25.9	1556	1.91	13.41	100	198	Off Idle	86.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.55	13.8	0.94	4.1	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:2	25.9	1566	1.91	13.41	100	198	Off Idle	86.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.61	13.83	0.94	4.1	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:2	25.9	1571	1.92	13.41	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.67	13.9	0.95	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:2	25.9	1571	1.92	13.41	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.7	13.96	0.95	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:2	25.9	1575	1.92	13.42	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.63	14.01	0.95	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:2	25.9	1580	1.92	13.43	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.64	14.05	0.96	4	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:13:3	25.9	1586	1.93	13.42	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.67	14.13	0.96	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:3	25.9	1590	1.93	13.44	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.69	14.19	0.97	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:3	25.9	1601	1.93	13.43	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.73	14.25	0.97	3.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:3	25.9	1606	1.94	13.43	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.74	14.3	0.97	3.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:3	25.9	1606	1.94	13.43	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.74	14.35	0.98	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:13:3	25.9	1627	1.95	13.43	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.74	14.43	0.98	4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:13:4	25.9	1628	1.95	13.42	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.71	14.47	0.99	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:4	25.9	1632	1.96	13.42	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.67	14.52	0.99	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:4	25.9	1636	1.97	13.43	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.65	14.59	0.99	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:4	27.27	1652	1.97	13.42	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.62	14.66	1	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:4	27.27	1663	1.98	13.41	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.63	14.7	1	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:13:4	27.27	1674	1.99	13.41	100	198	Off Idle	86.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-3.63	14.72	1	3.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:4	27.27	1685	2	13.42	100	198	Off Idle	86.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.56	14.76	1.01	3.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:5	27.27	1685	2.01	13.42	100	198	Off Idle	86.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.53	14.79	1.01	3.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:5	27.27	1698	2.02	13.42	100	198	Off Idle	86.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.51	14.8	1.01	3.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:5	27.27	1720	2.03	13.41	100	198	Off Idle	86.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.39	14.81	1.01	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:5	27.27	1720	2.05	13.43	100	198	Off Idle	86.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.39	14.84	1.01	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:5	27.27	1737	2.05	13.41	100	198	Off Idle	86.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.31	14.88	1.01	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:5	27.27	1737	2.06	13.42	100	198	Off Idle	86.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.34	14.9	1.02	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:6	27.27	1775	2.08	13.41	100	198	Off Idle	86.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.34	14.98	1.02	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:6	27.27	1766	2.09	13.41	100	198	Off Idle	86.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.36	15	1.02	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:6	27.27	1780	2.1	13.42	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.37	15.04	1.02	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:6	27.27	1787	2.11	13.41	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.37	15.12	1.03	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:6	27.27	1808	2.12	13.42	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.27	15.23	1.04	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:6	28.63	1808	2.12	13.42	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.31	15.28	1.04	3.8	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:13:6	28.63	1800	2.13	13.41	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.32	15.32	1.04	3.8	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:13:7	28.63	1805	2.14	13.42	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.36	15.39	1.05	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:7	28.63	1812	2.15	13.39	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.31	15.41	1.05	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:7	28.63	1816	2.16	13.4	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.34	15.42	1.05	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:7	28.63	1818	2.16	13.41	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.32	15.42	1.05	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:13:7	28.63	1821	2.16	13.4	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.26	15.38	1.05	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:7	28.63	1821	2.17	13.4	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.23	15.37	1.05	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:8	28.63	1827	2.17	13.42	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.17	15.36	1.05	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:8	28.63	1833	2.18	13.42	100	198	Off Idle	86.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.19	15.35	1.05	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:8	28.63	1842	2.18	13.42	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.1	15.29	1.04	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:8	28.63	1858	2.19	13.42	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.08	15.23	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:13:8	28.63	1864	2.19	13.42	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-3.08	15.18	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:8	28.63	1880	2.2	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.06	15.12	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:13:9	28.63	1880	2.21	13.42	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.02	15.08	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:13:9	28.63	1891	2.22	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.87	15.05	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:13:9	28.63	1891	2.23	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-2.79	14.99	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:13:9	28.63	1913	2.24	13.42	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-2.76	14.89	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:13:9	28.63	1941	2.25	13.41	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-2.64	14.85	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:13:9	28.63	1959	2.26	13.42	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.62	14.85	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:13:9	28.63	1959	2.27	13.42	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.55	14.88	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:0	28.63	1978	2.28	13.42	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-2.51	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:0	29.99	2003	2.29	13.43	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-2.46	15.03	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:0	29.99	2015	2.3	13.44	100	198	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.6	-2.48	15.05	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:0	29.99	2027	2.31	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.6	-2.41	15.12	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:14:0	29.99	2032	2.32	13.42	100	198	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.6	-2.46	15.18	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:14:0	29.99	2055	2.33	13.42	100	198	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.44	15.32	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:14:1	29.99	2049	2.34	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.12	Lean	1	14.6	-2.46	15.37	1.05	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:1	29.99	2052	2.35	13.43	100	198	Off Idle	86	0	2	132	944 Turbo	0.17	Lean	1	14.6	-2.47	15.39	1.05	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:1	29.99	2062	2.36	13.42	100	198	Off Idle	86	0	2	132	944 Turbo	0.25	Lean	1	14.6	-2.48	15.42	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:1	29.99	2065	2.36	13.42	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.49	15.42	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:1	29.99	2087	2.37	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.5	15.41	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:1	29.99	2067	2.37	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.49	15.38	1.05	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:1	29.99	2067	2.37	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-2.47	15.38	1.05	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:14:2	29.99	2066	2.38	13.44	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.44	15.35	1.05	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:2	29.99	2069	2.38	13.41	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-2.38	15.3	1.04	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:2	29.99	2080	2.38	13.4	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.34	15.24	1.04	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:2	29.99	2091	2.39	13.39	100	198	Off Idle	85.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.38	15.15	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:2	29.99	2103	2.39	13.38	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.41	15.1	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:2	29.99	2108	2.39	13.39	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.42	15.05	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:3	29.99	2126	2.4	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.45	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:3	29.99	2135	2.41	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.41	14.92	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:3	29.99	2149	2.41	13.42	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.37	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:3	29.99	2166	2.41	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-2.27	14.85	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:14:3	29.99	2195	2.42	13.4	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-2.22	14.84	1.01	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:3	29.99	2190	2.43	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-2.21	14.84	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:4	29.99	2198	2.43	13.42	100	198	Off Idle	85.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-2.18	14.83	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:4	29.99	2218	2.44	13.42	100	198	Off Idle	85.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-2.22	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:4	29.99	2218	2.45	13.43	100	198	Off Idle	84.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.21	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:4	31.36	2269	2.46	13.42	100	198	Off Idle	84.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.2	14.83	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:4	31.36	2252	2.46	13.41	100	198	Off Idle	84.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.19	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:4	31.36	2269	2.47	13.43	100	198	Off Idle	83.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-2.19	14.9	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:4	31.36	2279	2.48	13.44	100	198	Off Idle	83.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-2.2	14.94	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:5	31.36	2321	2.49	13.41	100	198	Off Idle	82.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-2.23	15	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:5	31.36	2309	2.49	13.43	100	198	Off Idle	82.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.18	15.02	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:5	31.36	2317	2.5	13.43	100	198	Off Idle	81.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.16	15.08	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:14:5	31.36	2320	2.51	13.43	100	198	Off Idle	80.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.16	15.15	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:14:5	31.36	2325	2.52	13.44	100	198	Off Idle	80.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.18	15.19	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:14:5	31.36	2331	2.53	13.43	100	198	Off Idle	79.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-2.16	15.22	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:14:6	31.36	2331	2.53	13.43	100	198	Off Idle	78.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.16	15.23	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:6	31.36	2342	2.54	13.44	100	198	Off Idle	78.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-2.12	15.24	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:6	31.36	2354	2.54	13.44	100	198	Off Idle	77.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.1	15.24	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:6	31.36	2375	2.55	13.45	100	198	Off Idle	77.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.11	15.2	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:6	31.36	2369	2.55	13.45	100	198	Off Idle	76.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.11	15.16	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:6	31.36	2368	2.56	13.45	100	198	Off Idle	76.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.11	15.12	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:6	31.36	2389	2.57	13.43	100	198	Off Idle	75.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.17	15.02	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:7	31.36	2394	2.57	13.41	100	198	Off Idle	75.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.17	14.99	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:7	31.36	2408	2.58	13.4	100	198	Off Idle	75.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-2.18	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:14:7	31.36	2408	2.58	13.38	100	198	Off Idle	75.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-2.17	14.9	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:14:7	31.36	2432	2.59	13.4	100	198	Off Idle	74.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.16	14.84	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:14:7	31.36	2439	2.6	13.4	100	198	Off Idle	74.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.12	14.83	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:14:7	31.36	2475	2.61	13.41	100	198	Off Idle	73.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.11	14.82	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:14:8	31.36	2479	2.61	13.43	100	198	Off Idle	73.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-2.07	14.81	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:14:8	31.36	2479	2.62	13.43	100	198	Off Idle	72.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.08	14.81	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:14:8	31.36	2498	2.62	13.44	100	198	Off Idle	72.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.04	14.82	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:14:8	31.36	2513	2.63	13.45	100	198	Off Idle	71.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-2.08	14.84	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:14:8	32.72	2536	2.64	13.43	100	198	Off Idle	70.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-2.06	14.86	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:8	32.72	2548	2.65	13.43	100	198	Off Idle	70.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-2.09	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:9	32.72	2559	2.65	13.42	100	198	Off Idle	69.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-2.05	14.91	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:9	32.72	2583	2.66	13.42	100	198	Off Idle	69.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-2.02	14.98	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:14:9	32.72	2571	2.67	13.42	100	198	Off Idle	67.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.01	15.02	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:9	32.72	2574	2.68	13.44	100	198	Off Idle	67.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-1.96	15.04	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:9	32.72	2584	2.68	13.44	100	198	Off Idle	66.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.98	15.01	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:14:9	32.72	2598	2.69	13.43	100	198	Off Idle	65.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.98	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:14:9	32.72	2610	2.69	13.43	100	198	Off Idle	64.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.99	14.96	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:0	32.72	2610	2.7	13.44	100	198	Off Idle	64.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.03	14.89	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:0	32.72	2622	2.7	13.43	100	198	Off Idle	63.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.05	14.85	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:0	32.72	2634	2.71	13.41	100	198	Off Idle	63.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.02	14.81	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:0	32.72	2663	2.72	13.42	100	198	Off Idle	63	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.01	14.77	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:0	32.72	2656	2.72	13.42	100	198	Off Idle	62.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.97	14.67	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:0	32.72	2658	2.72	13.42	100	198	Off Idle	62	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.95	14.64	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:1	32.72	2666	2.73	13.43	100	198	Off Idle	61.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.94	14.63	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:15:1	32.72	2678	2.74	13.43	100	198	Off Idle	60.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.94	14.64	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:1	32.72	2691	2.74	13.43	100	198	Off Idle	60.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.9	14.68	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:1	32.72	2702	2.75	13.42	100	198	Off Idle	59.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.95	14.67	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:1	32.72	2709	2.75	13.42	100	198	Off Idle	59.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.92	14.68	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:1	32.72	2714	2.75	13.43	100	198	Off Idle	59.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-1.93	14.71	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:1	32.72	2734	2.76	13.41	100	198	Off Idle	58.9	0	2	132	944 Turbo	0.58	Lean	1	14.6	-1.91	14.73	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:2	32.72	2760	2.76	13.41	100	198	Off Idle	58.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-1.91	14.74	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:2	32.72	2760	2.77	13.41	100	198	Off Idle	58	0	2	132	944 Turbo	0.48	Lean	1	14.6	-1.86	14.77	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:2	32.72	2778	2.77	13.41	100	198	Off Idle	57.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-1.87	14.78	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:2	32.72	2801	2.78	13.41	100	198	Off Idle	56.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-1.87	14.77	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:2	32.72	2821	2.78	13.43	100	198	Off Idle	56	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.85	14.79	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:2	32.72	2821	2.79	13.43	100	198	Off Idle	54.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.91	14.77	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:3	32.72	2842	2.79	13.43	100	198	Off Idle	54	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.93	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:3	32.72	2854	2.8	13.41	100	198	Off Idle	53.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-1.91	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:3	32.72	2858	2.81	13.43	100	198	Off Idle	52.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.91	14.96	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:3	32.72	2870	2.81	13.44	100	198	Off Idle	51.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-1.92	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:3	32.72	2879	2.82	13.44	100	198	Off Idle	51	0	2	132	944 Turbo	0.59	Rich	1	14.6	-1.96	14.98	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:3	32.72	2880	2.82	13.46	101	198	Off Idle	49.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.95	14.98	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:4	32.72	2880	2.83	13.44	101	198	Off Idle	49	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.94	14.97	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:4	32.72	2899	2.83	13.46	100	198	Off Idle	48.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.92	14.95	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:4	32.72	2893	2.84	13.46	100	198	Off Idle	47.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.92	14.93	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:4	32.72	2901	2.84	13.45	100	198	Off Idle	47	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.89	14.91	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:4	32.72	2916	2.85	13.42	100	198	Off Idle	46.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.85	14.82	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:15:4	32.72	2926	2.85	13.44	100	198	Off Idle	46.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	-1.85	14.79	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:15:4	32.72	2926	2.86	13.43	100	198	Off Idle	45.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-1.92	14.76	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:15:5	32.72	2957	2.86	13.43	101	198	Off Idle	45.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-1.86	14.74	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:15:5	32.72	2971	2.87	13.41	101	198	Off Idle	44.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-1.87	14.72	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:15:5	32.72	2976	2.87	13.42	100	198	Off Idle	44.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-1.82	14.73	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:15:5	32.72	2999	2.88	13.43	100	198	Off Idle	43.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.81	14.76	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:15:5	32.72	3022	2.88	13.42	100	198	Off Idle	43.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.85	14.79	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:5	32.72	3022	2.89	13.43	100	198	Off Idle	43.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-1.83	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:6	34.08	3045	2.89	13.42	100	198	Off Idle	42.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-1.85	14.89	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:6	34.08	3058	2.9	13.42	100	198	Off Idle	42.7	0	2	132	944 Turbo	0.45	Lean	1	14.6	-1.94	14.94	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:6	34.08	3058	2.9	13.42	101	198	Off Idle	42.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.94	14.94	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:6	34.08	3065	2.9	13.41	101	198	Off Idle	42.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-1.92	14.96	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:6	34.08	3077	2.91	13.42	101	198	Off Idle	42.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.93	14.98	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:6	34.08	3089	2.91	13.41	100	198	Off Idle	41.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.95	14.98	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:6	34.08	3090	2.91	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.87	14.97	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:7	34.08	3096	2.92	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-1.94	14.96	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:7	34.08	3118	2.92	13.44	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.88	14.95	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:7	34.08	3115	2.93	13.44	100	198	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-1.85	14.89	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:7	34.08	3130	2.93	13.46	100	198	Off Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-1.83	14.85	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:7	34.08	3130	2.93	13.45	100	198	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-1.9	14.84	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:7	34.08	3142	2.94	13.45	101	198	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.88	14.81	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:8	34.08	3164	2.94	13.45	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-1.9	14.8	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:8	34.08	3170	2.94	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-1.89	14.82	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:15:8	34.08	3199	2.95	13.45	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-1.85	14.86	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:15:8	34.08	3241	2.95	13.45	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-1.89	14.88	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:8	34.08	3235	2.96	13.44	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-1.87	14.89	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:8	34.08	3238	2.96	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-1.91	14.93	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:9	34.08	3256	2.96	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-1.98	15	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:9	34.08	3260	2.97	13.41	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-2	15.01	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:9	34.08	3282	2.97	13.42	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-1.95	15.01	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:9	34.08	3280	2.97	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.97	15.01	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:9	34.08	3280	2.97	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2	14.96	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:15:9	34.08	3294	2.98	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.96	14.92	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:15:9	34.08	3328	2.98	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.95	14.87	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:16:0	34.08	3317	2.98	13.41	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.96	14.81	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:16:0	34.08	3310	2.98	13.41	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.96	14.71	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:0	34.08	3315	2.98	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.05	14.61	0.99	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:0	34.08	3318	2.98	13.41	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.07	14.59	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:0	34.08	3335	2.98	13.41	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.12	14.58	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:16:0	34.08	3335	2.98	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.22	14.63	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:16:1	34.08	3350	2.98	13.44	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.21	14.66	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:1	34.08	3371	2.98	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.26	14.67	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:1	34.08	3375	2.98	13.45	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.31	14.69	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:1	34.08	3377	2.98	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.37	14.74	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:1	34.08	3388	2.98	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.45	14.76	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:1	34.08	3398	2.98	13.45	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.46	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:1	34.08	3403	2.97	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.48	14.78	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:16:2	34.08	3404	2.97	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.49	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:16:2	34.08	3419	2.97	13.44	100	198	Off Idle	41.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.62	14.79	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:16:2	34.08	3433	2.96	13.43	100	198	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.58	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:16:2	34.08	3433	2.96	13.45	100	198	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-2.64	14.81	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:16:2	34.08	3462	2.96	13.44	100	198	Off Idle	41.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-2.67	14.88	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:2	34.08	3467	2.96	13.45	100	198	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-2.73	14.93	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:3	34.08	3470	2.95	13.44	101	198	Off Idle	41.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.77	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:3	34.08	3493	2.95	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.83	15.02	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:3	34.08	3502	2.95	13.43	101	198	Off Idle	41.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-2.89	15.06	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:3	34.08	3506	2.95	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.94	15.08	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:16:3	34.08	3512	2.94	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3	15.14	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:3	34.08	3550	2.94	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.1	15.2	1.04	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:4	34.08	3531	2.94	13.44	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.21	15.2	1.04	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:4	34.08	3537	2.93	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-3.31	15.19	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:4	34.08	3538	2.93	13.42	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.31	15.15	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:4	34.08	3562	2.93	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.41	15.13	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:4	35.45	3522	2.92	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-3.43	15.1	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:4	35.45	3531	2.92	13.46	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-3.47	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:4	35.45	3531	2.92	13.45	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.5	15.01	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:5	35.45	3548	2.91	13.44	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.56	14.99	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:5	35.45	3563	2.91	13.45	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-3.61	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:5	35.45	3566	2.9	13.45	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.64	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:5	35.45	3578	2.9	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.7	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:5	35.45	3587	2.89	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.8	15	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:6	35.45	3600	2.89	13.46	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.79	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:6	35.45	3602	2.89	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.75	15.11	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:16:6	35.45	3608	2.88	13.44	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.94	15.19	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:6	35.45	3620	2.88	13.46	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.89	15.27	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:6	35.45	3647	2.88	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.89	15.32	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:6	35.45	3634	2.87	13.43	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.99	15.35	1.05	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:6	35.45	3624	2.87	13.44	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.09	15.36	1.05	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:16:6	35.45	3639	2.87	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.08	15.34	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:16:7	35.45	3643	2.86	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.26	15.32	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:16:7	35.45	3645	2.86	13.45	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.32	15.29	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:16:7	35.45	3652	2.85	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.4	15.27	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:16:7	35.45	3659	2.84	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.68	15.24	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:16:7	35.45	3666	2.81	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.08	15.22	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:16:7	35.45	3675	2.78	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.48	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:16:8	36.81	3664	2.74	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.94	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:16:8	36.81	3660	2.67	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.48	15.2	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:13:16:8	36.81	3645	2.61	13.45	101	198	Full Load	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.32	15.2	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:16:8	36.81	3658	2.55	13.44	101	198	Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.79	15.2	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:16:8	38.18	3623	2.49	13.46	101	198	Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.07	15.19	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:8	38.18	3594	2.41	13.44	101	198	Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.66	15.18	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:9	38.18	3594	2.35	13.43	101	198	Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.97	15.22	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:16:9	38.18	3527	2.3	13.43	101	198	Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.25	15.19	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:16:9	32.72	3460	2.24	13.43	101	198	Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.33	15.14	1.03	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:16:9	27.27	3432	2.15	13.44	101	198	Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.54	15.02	1.02	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:13:16:9	21.81	3400	2.09	13.43	101	198	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.59	14.97	1.02	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:16:9	20.45	3430	2	13.45	101	198	Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.61	14.84	1.01	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:16:9	20.45	3416	1.98	13.45	101	198	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.63	14.72	1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:0	20.45	3377	1.92	13.44	101	198	Idle	41.5	0	2	132	944 Turbo	0.71	Lean	1	14.6	-9.63	14.58	0.99	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:0	20.45	3370	1.85	13.45	100	198	Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.65	14.37	0.98	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:0	20.45	3322	1.8	13.45	100	198	Idle	41.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.61	14.19	0.97	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:0	20.45	3297	1.76	13.45	100	198	Idle	40.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.61	14.01	0.95	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:0	20.45	3290	1.72	13.45	101	198	Idle	39.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.6	13.81	0.94	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:0	20.45	3248	1.71	13.46	101	198	Idle	39.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.58	13.75	0.94	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:1	20.45	3227	1.7	13.46	101	198	Idle	38.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.5	13.61	0.93	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:1	20.45	3172	1.7	13.45	101	198	Idle	38	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.51	13.54	0.92	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:1	20.45	3156	1.71	13.45	101	198	Idle	37.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.43	13.48	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:1	20.45	3156	1.71	13.43	101	198	Idle	35	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.43	13.45	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:1	20.45	3103	1.71	13.44	101	198	Idle	33.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.37	13.44	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:1	20.45	3076	1.72	13.43	101	198	Idle	32.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.34	13.53	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:1	20.45	3076	1.72	13.44	101	198	Idle	31.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.31	13.64	0.93	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:2	20.45	3034	1.73	13.45	101	198	Idle	30.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.29	13.92	0.95	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:2	20.45	3012	1.74	13.45	101	198	Idle	29.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	14.36	0.98	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:2	20.45	3004	1.75	13.45	101	198	Idle	27.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.17	15.3	1.04	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:2	19.09	2937	1.76	13.46	101	198	Idle	26.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	15.99	1.09	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:2	19.09	2936	1.77	13.44	101	198	Idle	26	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	16.68	1.14	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:2	19.09	2890	1.78	13.45	101	198	Idle	25	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	17.36	1.18	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:3	19.09	2882	1.78	13.43	101	198	Idle	24.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.06	18.32	1.25	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:3	19.09	2873	1.79	13.42	101	198	Idle	24.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	18.92	1.29	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:3	19.09	2830	1.8	13.41	101	198	Idle	24.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	19.48	1.33	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:3	19.09	2806	1.81	13.42	101	198	Idle	24.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.83	20.03	1.36	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:3	19.09	2758	1.82	13.42	101	198	Idle	24.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.8	20.13	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:3	19.09	2746	1.83	13.42	101	198	Idle	24.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.77	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:4	19.09	2746	1.83	13.43	101	198	Idle	24.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.77	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:4	19.09	2694	1.84	13.44	101	198	Idle	24.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.78	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:4	19.09	2696	1.84	13.44	101	198	Idle	25.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.71	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:4	19.09	2679	1.84	13.44	101	198	Idle	25.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.68	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:4	19.09	2624	1.84	13.44	101	198	Idle	26.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.7	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:4	19.09	2622	1.84	13.45	101	198	Idle	27.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:4	19.09	2595	1.84	13.43	101	198	Idle	28.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.67	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:5	19.09	2561	1.84	13.44	101	198	Idle	29.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.71	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:5	19.09	2561	1.84	13.44	101	198	Idle	31.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.71	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:5	19.09	2536	1.84	13.44	101	198	Idle	32.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:5	19.09	2473	1.83	13.45	101	198	Idle	33.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.7	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:5	19.09	2484	1.83	13.44	101	198	Idle	34.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.71	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:5	19.09	2459	1.82	13.42	101	198	Idle	35.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:6	19.09	2423	1.81	13.44	101	198	Full Load	37.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.7	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:6	19.09	2423	1.81	13.43	101	198	Off Idle	38.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.7	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:6	19.09	2388	1.8	13.45	101	198	Off Idle	39.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:13:17:6	19.09	2352	1.79	13.44	101	198	Off Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.67	20.24	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:17:6	8.18	2231	1.79	13.44	101	198	Off Idle	42.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.62	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:17:6	8.18	2280	1.79	13.45	101	198	Off Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.55	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:17:6	10.9	2325	1.79	13.45	101	198	Off Idle	46.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.41	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:7	13.63	2281	1.79	13.45	101	198	Off Idle	49	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.35	20.23	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:7	13.63	2250	1.79	13.44	101	198	Off Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.29	20.23	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:7	16.36	2214	1.78	13.45	101	198	Off Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.24	20.24	1.38	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:7	16.36	2168	1.77	13.45	101	198	Off Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.22	20.23	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:7	19.09	2135	1.76	13.45	101	198	Off Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.2	20.24	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:7	19.09	2116	1.74	13.45	101	198	Off Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.19	20.24	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:8	21.81	2112	1.74	13.45	101	198	Off Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.18	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:8	24.54	2105	1.73	13.45	101	198	Off Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.18	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:17:8	24.54	2117	1.73	13.45	101	198	Off Idle	73.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.16	20.25	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:8	27.27	2117	1.73	13.45	101	198	Off Idle	75.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.19	20.25	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:17:8	27.27	2122	1.72	13.45	101	198	Off Idle	78.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.16	20.25	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:17:8	29.99	2122	1.72	13.45	101	198	Off Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.15	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:17:9	29.99	2125	1.72	13.46	101	198	Off Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.1	20.23	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:9	32.72	2127	1.74	13.46	101	198	Off Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.99	20.24	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:17:9	32.72	2116	1.75	13.45	101	198	Off Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.85	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:17:9	32.72	2124	1.76	13.45	101	198	Off Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.69	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:17:9	32.72	2137	1.78	13.44	101	198	Off Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.43	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:17:9	32.72	2145	1.78	13.42	101	198	Off Idle	85.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.27	20.23	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:17:9	32.72	2149	1.8	13.41	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7	20.23	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:18:0	32.72	2169	1.81	13.4	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.83	20.24	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:18:0	32.72	2200	1.82	13.4	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.64	20.25	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:18:0	32.72	2217	1.85	13.39	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.47	20.26	1.38	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:13:18:0	32.72	2236	1.89	13.37	101	198	Off Idle	85.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.18	20.26	1.38	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:0	32.72	2245	1.92	13.38	101	198	Off Idle	84.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.02	20.25	1.38	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:0	32.72	2263	1.95	13.39	101	198	Off Idle	84.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.95	20.24	1.38	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:18:1	32.72	2286	1.99	13.4	101	198	Off Idle	84.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.71	20.08	1.37	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:18:1	32.72	2262	2.02	13.41	101	198	Off Idle	83.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.58	19.9	1.36	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:1	32.72	2262	2.07	13.43	101	198	Off Idle	82.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.39	19.66	1.34	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:1	32.72	2236	2.1	13.44	101	198	Off Idle	82.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.27	19.41	1.32	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:1	32.72	2202	2.13	13.45	101	198	Off Idle	82	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.18	18.99	1.29	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:1	32.72	2161	2.16	13.45	101	198	Off Idle	81.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.08	18.68	1.27	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:1	32.72	2158	2.18	13.43	101	198	Off Idle	81.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.91	18.21	1.24	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:18:2	32.72	2139	2.19	13.43	101	198	Off Idle	81.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.77	17.87	1.22	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:18:2	32.72	2136	2.2	13.41	101	198	Off Idle	81.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.69	17.56	1.2	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:18:2	32.72	2121	2.22	13.4	101	198	Off Idle	81.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.62	17.2	1.17	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:2	31.36	2124	2.23	13.42	101	198	Off Idle	81.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.51	16.94	1.15	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:2	31.36	2169	2.23	13.42	101	198	Off Idle	81.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.52	16.85	1.15	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:2	31.36	2197	2.24	13.42	101	198	Off Idle	82.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.52	16.68	1.14	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:3	31.36	2197	2.24	13.43	101	198	Off Idle	82.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.53	16.61	1.13	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:3	31.36	2224	2.25	13.45	101	198	Off Idle	83.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.52	16.51	1.12	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:3	31.36	2232	2.25	13.45	101	198	Off Idle	83.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.52	16.21	1.1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:3	31.36	2243	2.25	13.43	101	198	Off Idle	83.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-4.49	16.03	1.09	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:3	31.36	2246	2.26	13.42	101	198	Off Idle	83.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.51	15.89	1.08	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:3	31.36	2265	2.26	13.41	101	198	Off Idle	83.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.47	15.71	1.07	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:4	31.36	2242	2.26	13.4	101	198	Off Idle	83.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.46	15.57	1.06	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:4	31.36	2230	2.26	13.4	101	198	Off Idle	83.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.46	15.36	1.05	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:4	31.36	2230	2.26	13.4	101	198	Off Idle	82.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.41	15.24	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:4	31.36	2213	2.26	13.41	101	198	Off Idle	82.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.36	15.18	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:4	31.36	2208	2.26	13.42	101	198	Off Idle	82.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.34	15.08	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:4	31.36	2206	2.26	13.43	101	198	Off Idle	81.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.26	15.01	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:4	31.36	2205	2.27	13.44	101	198	Off Idle	81.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.17	14.93	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:18:5	31.36	2201	2.28	13.45	101	198	Off Idle	81.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.07	14.85	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:18:5	31.36	2220	2.29	13.46	101	198	Off Idle	81.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.94	14.78	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:18:5	31.36	2227	2.31	13.47	101	198	Off Idle	81.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.66	14.73	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:18:5	31.36	2243	2.33	13.46	101	198	Off Idle	81.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.5	14.72	1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:18:5	31.36	2243	2.36	13.44	101	198	Off Idle	81.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.4	14.71	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:18:5	31.36	2256	2.37	13.43	101	198	Off Idle	81.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.21	14.73	1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:18:6	31.36	2266	2.39	13.43	101	198	Off Idle	81.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.9	14.76	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:18:6	31.36	2284	2.4	13.41	101	198	Off Idle	81.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-2.73	14.77	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:18:6	31.36	2295	2.42	13.42	101	198	Off Idle	81.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-2.54	14.77	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:18:6	31.36	2310	2.44	13.43	101	198	Off Idle	81	0	2	132	944 Turbo	0.28	Rich	1	14.6	-2.38	14.79	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:18:6	31.36	2316	2.45	13.43	101	198	Off Idle	80.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-2.37	14.83	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:18:6	31.36	2316	2.46	13.44	101	198	Off Idle	80.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.37	14.88	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:18:6	31.36	2310	2.48	13.44	101	198	Off Idle	80.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-2.4	14.9	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:7	31.36	2307	2.5	13.43	101	198	Off Idle	79.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-2.46	15.02	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:7	31.36	2291	2.51	13.41	101	198	Off Idle	79.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.42	15.06	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:18:7	31.36	2280	2.52	13.4	101	198	Off Idle	78.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-2.31	15.09	1.03	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:7	31.36	2278	2.54	13.41	101	198	Off Idle	78.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-2.27	15.18	1.03	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:7	31.36	2280	2.55	13.41	101	198	Off Idle	78.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-2.22	15.24	1.04	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:7	31.36	2281	2.56	13.42	101	198	Off Idle	77.9	0	2	132	944 Turbo	0.64	Lean	1	14.6	-2.17	15.25	1.04	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:8	31.36	2295	2.56	13.44	101	198	Off Idle	77.7	0	2	132	944 Turbo	0.74	Lean	1	14.6	-2.18	15.16	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:8	31.36	2300	2.56	13.46	101	198	Off Idle	77.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.17	15.06	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:8	31.36	2312	2.56	13.46	101	198	Off Idle	77.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.21	14.88	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:8	31.36	2326	2.55	13.46	101	198	Off Idle	77.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.22	14.69	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:8	31.36	2339	2.55	13.44	101	198	Off Idle	77.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.24	14.52	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:18:8	31.36	2345	2.55	13.43	101	198	Off Idle	77.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.28	14.34	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:18:9	31.36	2346	2.55	13.42	101	198	Off Idle	77.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.26	14.19	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:18:9	31.36	2366	2.55	13.42	101	198	Off Idle	77.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.26	14.01	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:18:9	31.36	2350	2.56	13.41	101	198	Off Idle	77.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.26	13.84	0.94	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:18:9	31.36	2345	2.56	13.42	101	198	Off Idle	77	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.22	13.79	0.94	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:18:9	31.36	2345	2.56	13.42	101	198	Off Idle	76.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.16	13.76	0.94	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:18:9	31.36	2344	2.56	13.41	101	198	Off Idle	76.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.17	13.77	0.94	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:18:9	31.36	2347	2.56	13.41	101	198	Off Idle	76.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.17	13.77	0.94	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:19:0	31.36	2347	2.56	13.4	101	198	Off Idle	75.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.15	13.81	0.94	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:19:0	31.36	2355	2.57	13.39	101	198	Off Idle	75.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.09	13.85	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:19:0	31.36	2373	2.57	13.4	101	198	Off Idle	75.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.06	13.85	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:19:0	31.36	2373	2.57	13.43	101	198	Off Idle	75	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.05	13.88	0.95	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:19:0	31.36	2382	2.57	13.42	101	198	Off Idle	74.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.06	13.89	0.95	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:19:0	31.36	2382	2.58	13.42	101	198	Off Idle	74.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.08	13.93	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:1	31.36	2404	2.58	13.41	101	198	Off Idle	74.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.06	13.97	0.95	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:19:1	31.36	2412	2.59	13.4	101	198	Off Idle	74.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.06	14	0.95	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:19:1	31.36	2412	2.59	13.41	101	198	Off Idle	73.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.06	14.04	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:13:19:1	31.36	2419	2.6	13.4	101	198	Off Idle	73.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.02	14.05	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:1	31.36	2420	2.6	13.41	101	198	Off Idle	73.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.96	14.12	0.96	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:1	31.36	2422	2.61	13.44	101	198	Off Idle	73.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.94	14.16	0.96	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:1	31.36	2432	2.61	13.42	101	198	Off Idle	72.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.92	14.17	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:2	31.36	2422	2.61	13.42	101	198	Off Idle	72.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.86	14.19	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:2	31.36	2422	2.62	13.44	101	198	Off Idle	72.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.83	14.2	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:2	31.36	2425	2.63	13.42	101	198	Off Idle	71.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.84	14.17	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:2	31.36	2426	2.63	13.4	101	198	Off Idle	71.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.76	14.16	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:2	31.36	2431	2.64	13.42	101	198	Off Idle	71.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.75	14.15	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:2	31.36	2443	2.64	13.41	101	198	Off Idle	71.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.74	14.15	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:3	31.36	2447	2.65	13.41	101	198	Off Idle	70.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.69	14.15	0.96	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:3	31.36	2452	2.65	13.42	101	198	Off Idle	70.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.67	14.15	0.96	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:3	31.36	2476	2.66	13.41	101	198	Off Idle	70.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.7	14.16	0.96	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:3	31.36	2475	2.67	13.41	101	198	Off Idle	70.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.63	14.17	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:3	31.36	2482	2.67	13.43	101	198	Off Idle	70.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.63	14.19	0.97	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:3	31.36	2482	2.68	13.44	101	198	Off Idle	70.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.64	14.2	0.97	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:4	31.36	2484	2.68	13.42	101	198	Off Idle	69.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.63	14.22	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:4	31.36	2481	2.69	13.44	101	198	Off Idle	69.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.54	14.24	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:4	31.36	2481	2.69	13.44	101	198	Off Idle	69.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.57	14.24	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:4	31.36	2484	2.7	13.43	101	198	Off Idle	69.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.49	14.25	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:4	31.36	2482	2.7	13.43	101	198	Off Idle	69.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.43	14.25	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:4	31.36	2491	2.7	13.44	101	198	Off Idle	68.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.43	14.25	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:4	31.36	2491	2.71	13.42	101	198	Off Idle	68.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.44	14.26	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:5	31.36	2505	2.71	13.44	101	198	Off Idle	68.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.43	14.25	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:5	31.36	2516	2.71	13.44	101	198	Off Idle	68.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.42	14.26	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:5	31.36	2521	2.71	13.44	101	198	Off Idle	67.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.42	14.28	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:5	31.36	2521	2.72	13.45	101	198	Off Idle	67.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.44	14.27	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:5	31.36	2531	2.72	13.45	101	198	Off Idle	67.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.43	14.27	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:5	31.36	2536	2.72	13.44	101	198	Off Idle	67.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.43	14.27	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:6	31.36	2536	2.73	13.44	101	198	Off Idle	67	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.43	14.3	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:6	31.36	2540	2.73	13.44	101	198	Off Idle	66.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.44	14.3	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:6	31.36	2542	2.73	13.43	101	198	Off Idle	66.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.44	14.26	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:19:6	31.36	2552	2.73	13.43	101	198	Off Idle	66.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.4	14.28	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:6	31.36	2552	2.74	13.44	101	198	Off Idle	66.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.42	14.27	0.97	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:6	31.36	2556	2.74	13.43	101	198	Off Idle	65.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.41	14.26	0.97	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:6	31.36	2582	2.74	13.42	101	198	Off Idle	65.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.41	14.28	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:7	31.36	2574	2.74	13.43	101	198	Off Idle	65.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.44	14.31	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:7	31.36	2564	2.74	13.43	101	198	Off Idle	65	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.43	14.33	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:7	31.36	2568	2.75	13.44	101	198	Off Idle	64.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.39	14.34	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:7	31.36	2594	2.75	13.44	101	198	Off Idle	64.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.38	14.36	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:7	31.36	2594	2.75	13.43	101	198	Off Idle	63.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.36	14.44	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:7	31.36	2587	2.75	13.44	101	198	Off Idle	63.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.34	14.46	0.99	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:8	31.36	2598	2.76	13.42	101	198	Off Idle	63.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.33	14.48	0.99	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:8	31.36	2606	2.76	13.43	101	198	Off Idle	62.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.31	14.52	0.99	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:8	31.36	2618	2.77	13.43	101	198	Off Idle	62.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.3	14.53	0.99	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:8	32.72	2610	2.77	13.41	101	198	Off Idle	62.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.23	14.57	0.99	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:19:8	32.72	2616	2.77	13.42	101	198	Off Idle	62	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.13	14.58	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:8	32.72	2618	2.78	13.42	101	198	Off Idle	61.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.15	14.6	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:9	32.72	2618	2.79	13.41	101	198	Off Idle	61.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.99	14.65	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:9	31.36	2609	2.79	13.42	101	198	Off Idle	61.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.98	14.65	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:19:9	31.36	2620	2.79	13.42	101	198	Off Idle	61.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.96	14.68	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:9	31.36	2620	2.8	13.41	101	198	Off Idle	61.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.96	14.72	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:9	31.36	2634	2.81	13.41	101	198	Off Idle	61	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.88	14.74	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:9	31.36	2634	2.81	13.41	101	198	Off Idle	60.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.95	14.78	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:19:9	31.36	2650	2.81	13.41	101	198	Off Idle	60.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.86	14.79	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:20:0	31.36	2658	2.82	13.4	101	198	Off Idle	60.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.88	14.8	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:20:0	31.36	2664	2.83	13.41	101	198	Off Idle	60.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.8	14.85	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:0	31.36	2666	2.83	13.4	101	198	Off Idle	59.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.82	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:20:0	31.36	2688	2.84	13.4	101	198	Off Idle	59.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.77	14.86	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:20:0	31.36	2686	2.85	13.41	101	198	Off Idle	59.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.76	14.86	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:0	31.36	2691	2.85	13.41	101	198	Off Idle	58.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.73	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:13:20:1	31.36	2691	2.86	13.42	101	198	Off Idle	58.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.72	14.85	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:1	31.36	2716	2.86	13.42	101	198	Off Idle	58.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.64	14.83	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:1	32.72	2702	2.87	13.42	101	198	Off Idle	57.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.63	14.85	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:1	32.72	2702	2.87	13.43	101	198	Off Idle	57.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.62	14.86	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:1	32.72	2699	2.87	13.42	101	198	Off Idle	57.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.59	14.86	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:1	32.72	2704	2.88	13.42	101	198	Off Idle	56.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.61	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:1	32.72	2709	2.88	13.43	101	198	Off Idle	56.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-0.61	14.89	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:2	32.72	2710	2.89	13.42	101	198	Off Idle	56.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.56	14.89	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:2	32.72	2716	2.89	13.42	101	198	Off Idle	56.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.55	14.9	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:2	32.72	2717	2.89	13.43	101	198	Off Idle	55.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-0.45	14.91	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:2	32.72	2728	2.9	13.42	101	198	Off Idle	55.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-0.48	14.91	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:2	31.36	2735	2.9	13.42	101	198	Off Idle	55.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-0.41	14.9	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:2	31.36	2746	2.9	13.44	101	198	Off Idle	55	0	2	132	944 Turbo	0.34	Rich	1	14.6	-0.45	14.88	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:3	31.36	2753	2.91	13.44	101	198	Off Idle	54.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-0.43	14.88	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:3	31.36	2756	2.91	13.44	101	198	Off Idle	54.1	0	2	132	944 Turbo	0.28	Rich	1	14.6	-0.43	14.9	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:3	31.36	2762	2.91	13.43	101	198	Off Idle	54	0	2	132	944 Turbo	0.28	Rich	1	14.6	-0.34	14.92	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:20:3	31.36	2766	2.92	13.43	101	198	Off Idle	53.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-0.32	14.94	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:20:3	31.36	2764	2.92	13.44	101	198	Off Idle	53.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-0.31	15	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:3	31.36	2766	2.92	13.44	101	198	Off Idle	53.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-0.27	15.05	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:4	31.36	2768	2.93	13.44	101	198	Off Idle	52.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-0.29	15.07	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:4	31.36	2754	2.93	13.43	101	198	Off Idle	52.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-0.22	15.08	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:4	31.36	2754	2.94	13.42	101	198	Off Idle	51.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-0.18	15.11	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:4	31.36	2793	2.94	13.42	101	198	Off Idle	51.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.19	15.08	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:4	31.36	2802	2.94	13.42	101	198	Off Idle	51.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.19	15.03	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:20:4	31.36	2809	2.95	13.42	101	198	Off Idle	51.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.17	15.02	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:20:4	31.36	2834	2.95	13.42	101	198	Off Idle	51	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.19	14.99	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:20:5	31.36	2822	2.95	13.42	101	198	Off Idle	50.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.2	14.95	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:20:5	31.36	2827	2.96	13.42	101	198	Off Idle	50.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.2	14.9	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:20:5	31.36	2827	2.96	13.42	101	198	Off Idle	50.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.17	14.84	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:20:5	31.36	2828	2.97	13.43	101	198	Off Idle	50	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.14	14.83	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:20:5	31.36	2828	2.97	13.41	101	198	Off Idle	49.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.06	14.81	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:5	31.36	2830	2.97	13.43	101	198	Off Idle	49.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-0.08	14.85	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:6	31.36	2830	2.97	13.43	101	198	Off Idle	49.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-0.07	14.87	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:20:6	31.36	2833	2.98	13.42	101	198	Off Idle	49.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-0.05	14.87	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:20:6	31.36	2858	2.98	13.41	101	198	Off Idle	49.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-0.01	14.87	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:20:6	31.36	2858	2.98	13.41	101	198	Off Idle	49	0	2	132	944 Turbo	0.35	Lean	1	14.6	-0.03	14.86	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:20:6	31.36	2856	2.99	13.42	101	198	Off Idle	48.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-0.03	14.89	1.01	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:6	31.36	2870	2.99	13.42	101	198	Off Idle	48.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.02	14.92	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:6	31.36	2883	3	13.42	101	198	Off Idle	48.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	0	14.97	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:7	31.36	2898	3	13.43	101	198	Off Idle	47.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-0.04	15.01	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:7	31.36	2900	3	13.44	101	198	Off Idle	47.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	0.03	15.02	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:7	31.36	2907	3.01	13.44	101	198	Off Idle	47.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-0.02	15.12	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:7	31.36	2908	3.01	13.43	101	198	Off Idle	47.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-0.01	15.17	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:7	31.36	2909	3.01	13.43	101	198	Off Idle	47	0	2	132	944 Turbo	0.41	Lean	1	14.6	0.04	15.19	1.04	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:7	31.36	2908	3.02	13.43	101	198	Off Idle	46.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	0.06	15.21	1.04	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:8	31.36	2908	3.02	13.43	101	198	Off Idle	46.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	0.11	15.17	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:8	31.36	2906	3.02	13.43	101	198	Off Idle	45.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.14	15.12	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:8	31.36	2906	3.03	13.42	101	198	Off Idle	45.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.13	15.05	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:8	31.36	2928	3.03	13.43	101	198	Off Idle	45.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.12	15.01	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:8	31.36	2927	3.03	13.44	101	198	Off Idle	44.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.15	14.98	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:8	31.36	2928	3.04	13.44	101	198	Off Idle	44.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	0.14	14.88	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:20:9	31.36	2940	3.04	13.44	101	198	Off Idle	44.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.2	14.85	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:9	31.36	2949	3.04	13.44	101	198	Off Idle	44.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	0.23	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:20:9	31.36	2961	3.04	13.44	101	198	Off Idle	43.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	0.17	14.82	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:9	31.36	2968	3.05	13.41	101	198	Off Idle	43.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	0.24	14.81	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:9	31.36	2970	3.05	13.41	101	198	Off Idle	43.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	0.22	14.81	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:9	31.36	2976	3.05	13.41	101	198	Off Idle	43.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	0.16	14.82	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:13:20:9	31.36	2980	3.06	13.4	101	197	Off Idle	42.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	0.15	14.85	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:0	31.36	2985	3.06	13.41	101	197	Off Idle	42.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	0.13	14.92	1.02	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:0	31.36	2985	3.06	13.41	101	197	Off Idle	42.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	0.18	14.94	1.02	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:0	31.36	2983	3.07	13.41	101	198	Off Idle	42.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	0.23	14.98	1.02	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:0	31.36	2984	3.07	13.41	101	198	Off Idle	42.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	0.23	15.03	1.02	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:0	31.36	2984	3.07	13.42	101	198	Off Idle	42	0	2	132	944 Turbo	0.33	Lean	1	14.6	0.23	15.09	1.03	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:0	31.36	2976	3.07	13.44	101	198	Off Idle	41.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	0.24	15.14	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:1	31.36	2993	3.07	13.42	101	198	Off Idle	41.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	0.23	15.14	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:1	31.36	3001	3.07	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	0.22	15.13	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:1	31.36	3004	3.08	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	0.21	15.09	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:1	31.36	3013	3.08	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.14	15.02	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:1	31.36	3017	3.08	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.15	14.98	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:1	31.36	3028	3.09	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.13	14.92	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:1	31.36	3032	3.09	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.08	14.85	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:2	31.36	3040	3.09	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.17	14.74	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:2	31.36	3040	3.09	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.18	14.7	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:2	31.36	3044	3.09	13.41	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	0.22	14.69	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:2	31.36	3070	3.09	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	0.23	14.69	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:13:21:2	31.36	3064	3.09	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	0.2	14.71	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:2	31.36	3065	3.1	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	0.24	14.7	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:3	31.36	3072	3.1	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	0.23	14.7	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:3	31.36	3076	3.1	13.45	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	0.27	14.75	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:3	31.36	3078	3.1	13.44	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	0.22	14.8	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:3	31.36	3083	3.1	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	0.25	14.84	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:3	31.36	3093	3.11	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	0.23	14.91	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:13:21:3	31.36	3148	3.11	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	0.13	14.97	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:4	32.72	3126	3.11	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	0.15	15.05	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:4	32.72	3111	3.11	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	0.13	15.06	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:4	32.72	3117	3.11	13.43	101	197	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	0.15	15.07	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:4	32.72	3117	3.11	13.43	101	197	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	0.1	15.06	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:21:4	32.72	3120	3.11	13.43	101	197	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.06	14.97	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:4	32.72	3123	3.11	13.42	101	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.06	14.9	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:4	32.72	3123	3.11	13.42	101	197	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.04	14.84	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:5	31.36	3111	3.11	13.42	101	197	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.05	14.75	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:5	31.36	3134	3.12	13.43	101	197	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.01	14.67	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:5	31.36	3141	3.12	13.41	101	197	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.01	14.61	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:5	31.36	3142	3.12	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.01	14.59	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:5	32.72	3160	3.11	13.42	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.06	14.6	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:5	32.72	3155	3.11	13.41	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.07	14.63	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:6	32.72	3158	3.11	13.41	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.05	14.65	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:6	32.72	3165	3.11	13.43	101	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.11	14.72	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:21:6	32.72	3177	3.11	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.17	14.74	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:21:6	32.72	3182	3.11	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.22	14.77	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:21:6	32.72	3182	3.11	13.41	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.22	14.8	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:6	32.72	3183	3.1	13.41	101	198	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-0.34	14.82	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:6	32.72	3181	3.1	13.41	101	198	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-0.35	14.83	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:21:7	32.72	3189	3.09	13.41	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-0.47	14.83	1.01	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:21:7	32.72	3190	3.09	13.41	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-0.49	14.85	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:21:7	32.72	3198	3.09	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-0.73	14.89	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:13:21:7	32.72	3207	3.08	13.41	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-0.85	14.92	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:13:21:7	32.72	3210	3.07	13.41	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-1.07	14.96	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:13:21:7	32.72	3223	3.06	13.41	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.15	15.02	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:8	32.72	3223	3.05	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-1.28	15.05	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:13:21:8	32.72	3216	3.04	13.41	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-1.33	15.05	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:13:21:8	32.72	3199	3.03	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-1.53	15.06	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:8	32.72	3199	3.02	13.43	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.58	15.06	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:13:21:8	32.72	3200	3.01	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.83	15.03	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:8	34.08	3209	2.99	13.43	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.94	14.95	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:9	34.08	3208	2.98	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-2.05	14.92	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:13:21:9	34.08	3219	2.97	13.41	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-2.12	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:9	34.08	3227	2.95	13.43	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-2.25	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:9	34.08	3226	2.94	13.43	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-2.33	14.75	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:9	34.08	3230	2.92	13.43	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-2.46	14.75	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:13:21:9	34.08	3238	2.91	13.44	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-2.58	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:13:21:9	34.08	3236	2.9	13.44	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.17	Rich	1	14.6	-2.7	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:0	34.08	3236	2.88	13.44	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-2.77	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:0	34.08	3238	2.87	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.82	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:0	34.08	3231	2.86	13.41	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3	15.08	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:0	34.08	3243	2.85	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.1	15.14	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:0	34.08	3244	2.83	13.42	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.22	15.23	1.04	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:0	34.08	3254	2.82	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.4	15.34	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:13:22:1	34.08	3252	2.81	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.45	15.43	1.05	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:22:1	34.08	3258	2.79	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.58	15.5	1.06	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:22:1	34.08	3260	2.78	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.72	15.6	1.06	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:22:1	35.45	3262	2.77	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.79	15.65	1.07	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:22:1	35.45	3264	2.76	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.84	15.68	1.07	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:22:1	35.45	3268	2.75	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.06	15.73	1.07	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:22:1	35.45	3261	2.74	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.18	15.77	1.07	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:22:2	35.45	3260	2.73	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.26	15.79	1.08	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:13:22:2	35.45	3260	2.71	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.46	15.78	1.08	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:13:22:2	35.45	3252	2.7	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.62	15.78	1.08	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:13:22:2	35.45	3252	2.69	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.67	15.78	1.08	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:13:22:2	35.45	3252	2.67	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.98	15.76	1.07	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:13:22:2	35.45	3247	2.64	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.14	15.73	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:22:3	35.45	3251	2.63	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.21	15.72	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:22:3	35.45	3250	2.6	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.59	15.69	1.07	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:3	35.45	3241	2.58	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.74	15.69	1.07	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:22:3	35.45	3241	2.55	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6	15.68	1.07	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:22:3	35.45	3230	2.52	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.33	15.69	1.07	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:22:3	35.45	3245	2.49	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.47	15.69	1.07	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:22:4	35.45	3241	2.47	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.64	15.7	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:22:4	36.81	3254	2.44	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.75	15.7	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:22:4	36.81	3240	2.41	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.85	15.7	1.07	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:22:4	36.81	3242	2.38	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.99	15.72	1.07	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:22:4	36.81	3239	2.36	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.06	15.71	1.07	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:22:4	36.81	3234	2.33	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.25	15.71	1.07	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:22:4	36.81	3218	2.3	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.38	15.72	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:13:22:5	36.81	3228	2.27	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.49	15.75	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:13:22:5	36.81	3230	2.24	13.41	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.62	15.77	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:22:5	36.81	3243	2.2	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.84	15.81	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:22:5	36.81	3230	2.17	13.41	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.01	15.89	1.08	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:22:5	36.81	3230	2.14	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.17	15.93	1.08	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:22:5	36.81	3230	2.1	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.5	16.06	1.09	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:22:6	36.81	3210	2.06	13.45	101	197	Full Load	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.6	16.16	1.1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:22:6	36.81	3218	2.03	13.44	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.8	16.27	1.11	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:22:6	36.81	3208	2	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.92	16.36	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:6	36.81	3207	1.97	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.05	16.44	1.12	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:6	36.81	3195	1.95	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.16	16.52	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:6	36.81	3178	1.92	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.27	16.57	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:6	36.81	3178	1.9	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.35	16.61	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:7	34.08	3115	1.86	13.44	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.42	16.64	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:7	28.63	3111	1.84	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.53	16.64	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:7	23.18	3110	1.81	13.44	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.57	16.62	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:7	20.45	3111	1.79	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.64	16.6	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:7	20.45	3168	1.77	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.69	16.56	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:7	20.45	3180	1.75	13.46	101	197	Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.75	16.49	1.12	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:8	20.45	3187	1.73	13.46	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.74	16.45	1.12	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:8	20.45	3190	1.73	13.46	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.7	16.43	1.12	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:8	20.45	3201	1.72	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.67	16.39	1.12	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:8	20.45	3206	1.7	13.44	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.6	16.35	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:8	20.45	3207	1.7	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.61	16.23	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:8	20.45	3206	1.69	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.56	16.22	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:9	20.45	3216	1.69	13.44	101	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.56	16.19	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:9	20.45	3196	1.69	13.44	101	197	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.55	16.18	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:9	20.45	3186	1.7	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.53	16.18	1.1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:9	20.45	3184	1.7	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.52	16.18	1.1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:9	20.45	3175	1.69	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.56	16.17	1.1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:9	20.45	3175	1.69	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.58	16.18	1.1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:22:9	20.45	3162	1.69	13.46	101	197	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	16.23	1.11	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:0	20.45	3156	1.69	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	16.37	1.12	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:0	20.45	3127	1.69	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	16.41	1.12	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:0	20.45	3148	1.69	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	16.57	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:0	20.45	3148	1.7	13.44	101	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	16.67	1.14	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:0	20.45	3146	1.7	13.46	101	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	17.13	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:0	20.45	3146	1.7	13.45	101	197	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	17.53	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:1	20.45	3148	1.7	13.46	101	197	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	17.91	1.22	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:1	20.45	3146	1.7	13.46	101	197	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	18.3	1.25	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:1	20.45	3146	1.7	13.45	101	197	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	18.87	1.29	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:1	20.45	3148	1.7	13.44	101	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	19.05	1.3	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:1	20.45	3142	1.7	13.45	101	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	19.4	1.32	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:1	20.45	3142	1.7	13.44	101	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	19.71	1.34	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:1	20.45	3138	1.7	13.44	101	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	19.99	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:2	20.45	3134	1.71	13.45	101	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.16	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:2	20.45	3127	1.71	13.45	101	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:2	20.45	3126	1.71	13.46	101	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:2	20.45	3117	1.71	13.45	101	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:23:2	20.45	3102	1.71	13.45	101	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:2	19.09	3107	1.71	13.46	101	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:3	19.09	3107	1.71	13.46	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:3	20.45	3113	1.71	13.46	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:3	20.45	3097	1.71	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:3	20.45	3095	1.71	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:3	19.09	3082	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:3	19.09	3089	1.71	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:4	19.09	3062	1.71	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:4	19.09	3062	1.71	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:4	19.09	3084	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:4	19.09	3093	1.71	13.44	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:4	19.09	3076	1.71	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:4	19.09	3072	1.71	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:4	19.09	3072	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:5	19.09	3054	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:5	19.09	3062	1.71	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:5	19.09	3061	1.71	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:5	19.09	3058	1.71	13.43	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:5	19.09	3052	1.71	13.44	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:5	19.09	3047	1.71	13.43	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:6	19.09	3046	1.71	13.45	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:6	19.09	3038	1.71	13.43	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:6	19.09	3034	1.71	13.44	101	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:6	19.09	3042	1.71	13.43	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:6	19.09	3027	1.71	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:6	19.09	3027	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:6	19.09	3022	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:7	19.09	3021	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:7	19.09	3021	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:7	19.09	3020	1.71	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:7	19.09	3018	1.71	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:7	19.09	3016	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:7	19.09	3013	1.71	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:8	19.09	3012	1.71	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:8	19.09	3010	1.71	13.45	101	197	Full Load	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:8	19.09	3008	1.71	13.45	101	197	Full Load	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:8	19.09	3005	1.71	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:8	19.09	3004	1.71	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:23:8	10.9	2935	1.72	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:23:9	10.9	3016	1.72	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:23:9	13.63	3010	1.72	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:23:9	16.36	3011	1.73	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:23:9	19.09	3002	1.74	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.43	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:23:9	19.09	3001	1.74	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:23:9	21.81	2998	1.75	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.37	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:23:9	24.54	2996	1.75	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.32	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:24:0	27.27	3002	1.76	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.31	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:24:0	29.99	3009	1.78	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.29	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:24:0	29.99	3010	1.79	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.29	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:0	32.72	3018	1.8	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.27	20.22	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:24:0	35.45	3033	1.81	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.26	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:24:0	36.81	3024	1.81	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:1	36.81	3025	1.82	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.21	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:1	36.81	3029	1.84	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.23	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:24:1	36.81	3026	1.85	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.19	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:1	36.81	3025	1.85	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.22	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:1	36.81	3024	1.86	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.24	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:24:1	36.81	3022	1.86	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.2	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:1	36.81	3020	1.87	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.16	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:2	36.81	3019	1.88	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.13	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:2	36.81	3020	1.88	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.09	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:2	36.81	3014	1.89	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.06	20.26	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:24:2	36.81	3003	1.9	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.04	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:13:24:2	36.81	2987	1.91	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.98	20.25	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:24:2	36.81	2982	1.92	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.91	20.25	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:24:3	36.81	2966	1.92	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.9	20.24	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:24:3	36.81	2953	1.92	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.86	20.16	1.37	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:24:3	36.81	2950	1.92	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.79	19.91	1.36	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:24:3	36.81	2950	1.93	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.73	19.68	1.34	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:24:3	36.81	2946	1.94	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.69	19.42	1.32	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:24:3	36.81	2948	1.95	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.6	18.98	1.29	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:24:4	36.81	2946	1.95	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	18.67	1.27	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:24:4	36.81	2948	1.97	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.49	18.16	1.24	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:24:4	36.81	2953	1.97	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.43	17.81	1.21	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:24:4	36.81	2956	1.98	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.39	17.5	1.19	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:24:4	36.81	2957	1.99	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.34	17.36	1.18	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:24:4	36.81	2960	2.01	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.23	17.13	1.17	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:24:4	36.81	2974	2.01	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.15	16.89	1.15	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:24:5	36.81	2978	2.02	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.08	16.76	1.14	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:24:5	36.81	2980	2.03	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.98	16.7	1.14	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:24:5	36.81	2978	2.04	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.98	16.59	1.13	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:5	36.81	2975	2.06	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.89	16.43	1.12	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:5	36.81	2976	2.07	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.78	16.34	1.11	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:5	36.81	2978	2.07	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.79	16.27	1.11	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:6	36.81	2979	2.09	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.73	16.15	1.1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:6	36.81	2980	2.1	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.7	16.08	1.1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:24:6	36.81	2980	2.11	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	16.01	1.09	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:24:6	36.81	2975	2.12	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.67	15.94	1.09	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:24:6	36.81	2973	2.13	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	15.85	1.08	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:24:6	36.81	2975	2.14	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Rich	1	14.6	-7.58	15.81	1.08	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:24:6	36.81	2976	2.14	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.56	15.79	1.08	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:7	36.81	2977	2.15	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.55	15.73	1.07	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:7	36.81	2975	2.16	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.52	15.69	1.07	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:7	36.81	2974	2.16	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.52	15.64	1.07	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:7	36.81	2968	2.16	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.5	15.65	1.07	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:7	36.81	2962	2.17	13.43	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.5	15.57	1.06	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:7	36.81	2962	2.17	13.43	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.48	15.49	1.06	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:8	35.45	2943	2.17	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.44	15.43	1.05	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:8	35.45	2958	2.18	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.45	15.36	1.05	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:8	35.45	2958	2.18	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.47	15.3	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:8	35.45	2957	2.18	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.47	15.23	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:8	35.45	2962	2.18	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.44	15.19	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:24:8	35.45	2966	2.19	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.41	15.15	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:24:9	35.45	2966	2.19	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.4	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:24:9	35.45	2970	2.19	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.32	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:24:9	35.45	2974	2.2	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.28	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:24:9	35.45	2982	2.2	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.25	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:24:9	35.45	2983	2.2	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.18	Rich	1	14.6	-7.22	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:24:9	35.45	2990	2.2	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.19	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:24:9	35.45	2990	2.21	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.16	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:0	35.45	2985	2.21	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.15	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:0	35.45	2982	2.21	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.12	15.09	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:0	35.45	2976	2.22	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.12	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:0	35.45	2973	2.22	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.1	15.19	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:0	35.45	2969	2.23	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.06	15.24	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:25:0	35.45	2965	2.23	13.43	102	197	Off Idle	41.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.05	15.29	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:1	35.45	2966	2.23	13.43	102	197	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.97	15.33	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:1	35.45	2968	2.24	13.44	101	197	Off Idle	41.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.92	15.33	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:1	35.45	2954	2.24	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.91	15.32	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:1	35.45	2954	2.24	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.93	15.31	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:1	35.45	2968	2.25	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.9	15.28	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:1	35.45	2962	2.25	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.85	15.24	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:1	35.45	2962	2.26	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.93	15.21	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:2	35.45	2964	2.26	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.85	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:2	35.45	2972	2.26	13.44	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.81	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:2	35.45	2978	2.26	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.83	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:2	35.45	2990	2.27	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.77	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:25:2	35.45	2990	2.27	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.82	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:2	35.45	2992	2.27	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.85	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:3	35.45	2993	2.27	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.85	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:3	35.45	2993	2.27	13.4	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.85	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:3	35.45	2992	2.27	13.41	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.85	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:3	35.45	2990	2.27	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.85	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:3	35.45	2990	2.27	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.81	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:3	35.45	2990	2.28	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.81	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:4	35.45	2995	2.28	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.8	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:4	35.45	2996	2.28	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.77	14.9	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:4	35.45	2996	2.28	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.75	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:4	35.45	2997	2.28	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.77	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:4	35.45	2996	2.28	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.74	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:4	35.45	2996	2.29	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.77	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:4	35.45	2994	2.29	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.74	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:5	35.45	2989	2.29	13.4	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.77	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:5	35.45	2990	2.29	13.4	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.73	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:5	35.45	2994	2.29	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.76	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:5	35.45	2992	2.29	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.7	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:5	35.45	2992	2.29	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.74	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:5	35.45	2992	2.29	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.75	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:6	35.45	2994	2.3	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.7	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:6	35.45	2999	2.3	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.73	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:6	35.45	2998	2.3	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.68	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:6	35.45	3002	2.3	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.69	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:6	35.45	3002	2.3	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.69	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:6	35.45	3003	2.3	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.67	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:6	35.45	3004	2.3	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.66	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:7	35.45	3006	2.3	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.65	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:7	35.45	3003	2.3	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.66	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:7	35.45	3002	2.3	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.66	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:7	35.45	3002	2.3	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.68	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:7	35.45	3008	2.3	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.7	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:7	35.45	3013	2.31	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.64	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:8	35.45	3016	2.31	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.61	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:8	35.45	3020	2.31	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.61	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:25:8	35.45	3016	2.32	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.53	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:8	35.45	3016	2.33	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.49	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:8	35.45	3020	2.34	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.37	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:25:8	35.45	3008	2.34	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-6.33	15.08	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:13:25:9	35.45	3006	2.36	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Lean	1	14.6	-6.26	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:13:25:9	35.45	3008	2.36	13.4	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-6.16	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:13:25:9	35.45	3010	2.37	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.09	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:13:25:9	35.45	3020	2.38	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.02	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:25:9	35.45	3028	2.39	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.93	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:25:9	35.45	3028	2.4	13.42	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.9	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:25:9	35.45	3035	2.4	13.41	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.81	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:0	35.45	3041	2.41	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.77	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:0	35.45	3042	2.43	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.74	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:0	35.45	3042	2.44	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.73	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:0	35.45	3060	2.45	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.66	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:0	35.45	3050	2.46	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.61	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:0	35.45	3050	2.47	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.59	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:1	35.45	3051	2.48	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.55	14.97	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:1	35.45	3047	2.49	13.45	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.5	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:1	35.45	3036	2.49	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.44	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:1	35.45	3049	2.5	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.39	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:1	35.45	3046	2.51	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.36	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:26:1	35.45	3053	2.51	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.3	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:1	35.45	3050	2.52	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.31	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:2	35.45	3049	2.52	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.27	14.72	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:2	35.45	3049	2.53	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.28	14.69	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:2	35.45	3058	2.53	13.43	101	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.24	14.61	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:2	35.45	3059	2.54	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.26	14.65	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:2	35.45	3072	2.54	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.21	14.63	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:2	35.45	3061	2.55	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.26	14.61	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:3	35.45	3060	2.55	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.23	14.63	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:3	35.45	3064	2.55	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.26	14.65	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:3	35.45	3066	2.55	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.2	14.66	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:3	35.45	3070	2.55	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.27	14.66	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:3	35.45	3070	2.56	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.21	14.66	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:3	35.45	3070	2.56	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.24	14.64	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:4	35.45	3072	2.56	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.23	14.64	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:4	35.45	3079	2.56	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.21	14.64	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:4	35.45	3079	2.56	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.23	14.64	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:4	35.45	3082	2.56	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.19	14.62	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:4	35.45	3087	2.56	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.2	14.62	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:4	35.45	3092	2.56	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.2	14.63	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:4	35.45	3092	2.56	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.2	14.64	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:5	35.45	3092	2.56	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.25	14.65	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:5	35.45	3100	2.56	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.23	14.68	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:5	35.45	3105	2.56	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.27	14.71	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:5	35.45	3107	2.56	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.3	14.74	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:5	35.45	3109	2.56	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.28	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:5	35.45	3113	2.56	13.44	102	197	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.33	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:6	35.45	3130	2.56	13.45	102	197	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.32	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:6	35.45	3115	2.56	13.44	102	197	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.27	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:26:6	35.45	3116	2.56	13.46	102	197	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.26	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:26:6	35.45	3115	2.56	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.26	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:26:6	35.45	3116	2.56	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.26	14.84	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:26:6	35.45	3125	2.56	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.29	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:26:6	35.45	3125	2.56	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.32	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:13:26:7	35.45	3126	2.56	13.43	102	197	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.3	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:7	35.45	3124	2.56	13.44	102	197	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.33	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:7	35.45	3124	2.56	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.33	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:7	35.45	3124	2.56	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.3	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:7	35.45	3120	2.56	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.35	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:7	35.45	3121	2.56	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.3	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:8	35.45	3123	2.56	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.33	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:8	35.45	3130	2.57	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.3	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:8	35.45	3130	2.57	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.29	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:8	35.45	3124	2.57	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.31	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:8	35.45	3137	2.57	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.27	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:8	35.45	3136	2.57	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.28	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:26:9	35.45	3139	2.57	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.28	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:9	35.45	3140	2.57	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.21	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:9	35.45	3133	2.57	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.26	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:9	35.45	3132	2.57	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.2	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:9	35.45	3131	2.57	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.23	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:9	35.45	3133	2.57	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.21	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:26:9	35.45	3140	2.57	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.25	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:13:27:0	35.45	3148	2.57	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.2	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:27:0	35.45	3148	2.57	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.28	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:27:0	35.45	3154	2.57	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.3	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:27:0	35.45	3170	2.57	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.34	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:27:0	35.45	3170	2.57	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.37	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:13:27:0	35.45	3162	2.57	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.44	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:27:1	35.45	3163	2.56	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.5	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:27:1	35.45	3164	2.56	13.41	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.54	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:13:27:1	35.45	3168	2.55	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.62	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:13:27:1	35.45	3156	2.54	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.78	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:27:1	35.45	3150	2.53	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.84	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:27:1	35.45	3148	2.52	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.91	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:13:27:1	35.45	3138	2.52	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.02	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:2	35.45	3132	2.5	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.12	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:2	35.45	3136	2.49	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.22	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:27:2	35.45	3136	2.48	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Lean	1	14.6	-6.28	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:27:2	35.45	3136	2.46	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.43	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:13:27:2	35.45	3140	2.45	13.42	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.5	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:27:2	36.81	3149	2.43	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.66	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:13:27:3	36.81	3149	2.41	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.78	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:27:3	36.81	3149	2.39	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.85	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:27:3	36.81	3177	2.37	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.96	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:27:3	36.81	3168	2.36	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.06	14.76	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:27:3	36.81	3159	2.34	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.16	14.74	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:27:3	36.81	3160	2.33	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.25	14.73	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:27:4	36.81	3146	2.32	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.34	14.73	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:27:4	36.81	3154	2.29	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.45	14.76	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:13:27:4	36.81	3157	2.27	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.51	14.79	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:27:4	36.81	3157	2.25	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.58	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:27:4	36.81	3170	2.24	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	14.9	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:27:4	36.81	3149	2.22	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.77	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:27:4	36.81	3145	2.19	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.89	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:27:5	36.81	3144	2.19	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.98	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:27:5	36.81	3142	2.16	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.13	15.16	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:27:5	36.81	3138	2.13	13.45	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.32	15.26	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:27:5	36.81	3131	2.1	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.38	15.27	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:27:5	36.81	3124	2.08	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.55	15.32	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:27:5	36.81	3124	2.06	13.43	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.71	15.33	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:27:6	36.81	3121	2.04	13.44	102	197	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.83	15.34	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:27:6	36.81	3118	2.02	13.44	102	197	Full Load	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.01	15.34	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:27:6	36.81	3106	1.98	13.43	102	197	Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.1	15.32	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:6	36.81	3114	1.95	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.3	15.3	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:27:6	36.81	3104	1.92	13.44	101	197	Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.35	15.25	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:27:6	36.81	3097	1.9	13.45	101	197	Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.44	15.22	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:27:6	36.81	3108	1.88	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.48	15.19	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:27:7	36.81	3082	1.85	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.59	15.16	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:27:7	36.81	3077	1.84	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.64	15.15	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:27:7	34.08	3051	1.81	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.75	15.11	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:27:7	28.63	3016	1.8	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.76	15.08	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:27:7	23.18	3013	1.78	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.76	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:7	23.18	3013	1.76	13.42	102	197	Idle	41.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.79	15.05	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:27:8	19.09	3051	1.75	13.43	102	197	Idle	41.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.79	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:8	19.09	3075	1.74	13.43	102	197	Idle	41.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.85	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:8	19.09	3079	1.73	13.43	102	197	Idle	41.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.87	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:8	19.09	3092	1.72	13.43	102	197	Idle	41.6	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.94	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:8	19.09	3110	1.71	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.9	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:8	19.09	3120	1.7	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.9	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:9	19.09	3122	1.7	13.45	102	197	Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.84	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:9	19.09	3128	1.7	13.45	102	197	Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.8	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:9	19.09	3129	1.7	13.45	102	197	Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.75	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:9	19.09	3120	1.7	13.46	102	197	Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.73	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:9	19.09	3118	1.7	13.45	102	197	Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.71	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:9	19.09	3107	1.7	13.45	102	197	Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.69	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:27:9	19.09	3089	1.7	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.7	14.93	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:0	19.09	3089	1.7	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.72	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:0	19.09	3052	1.7	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.66	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:0	19.09	3052	1.7	13.45	102	197	Idle	41.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.71	15.13	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:0	19.09	3016	1.7	13.43	102	197	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.7	15.21	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:0	19.09	3024	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	15.28	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:0	19.09	3028	1.7	13.45	102	197	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	15.35	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:1	19.09	3026	1.7	13.44	102	197	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	15.43	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:1	19.09	3031	1.7	13.44	102	197	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	15.54	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:1	19.09	3034	1.7	13.44	102	197	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	15.71	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:1	19.09	3044	1.7	13.44	102	197	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	16.14	1.1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:1	19.09	3054	1.7	13.42	102	197	Idle	40.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	16.53	1.13	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:1	19.09	3085	1.7	13.43	102	197	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	16.99	1.16	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:1	19.09	3078	1.71	13.44	102	197	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	17.7	1.21	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:2	19.09	3075	1.71	13.44	102	197	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	18.16	1.24	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:2	19.09	3077	1.71	13.44	102	197	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	18.39	1.25	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:2	19.09	3076	1.71	13.44	102	197	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	18.85	1.28	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:2	19.09	3072	1.71	13.44	102	197	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	19.47	1.33	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:2	19.09	3063	1.71	13.43	102	197	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	19.81	1.35	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:2	19.09	3054	1.71	13.43	102	197	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.14	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:3	19.09	3043	1.71	13.44	102	197	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:3	19.09	3040	1.71	13.43	102	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:3	19.09	3026	1.71	13.44	102	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:3	19.09	3006	1.71	13.43	102	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:3	19.09	3010	1.71	13.44	102	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:3	19.09	3008	1.71	13.43	102	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:4	19.09	3001	1.71	13.46	102	197	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:4	19.09	2996	1.71	13.45	102	197	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:4	19.09	2994	1.71	13.46	102	197	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:4	19.09	2992	1.71	13.46	102	197	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:4	19.09	2994	1.71	13.46	102	197	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:4	19.09	2994	1.71	13.46	102	197	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:4	19.09	2996	1.71	13.45	102	197	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:5	19.09	2997	1.71	13.46	102	197	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:5	19.09	2997	1.71	13.46	102	197	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:5	19.09	2996	1.71	13.45	102	197	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:5	19.09	2994	1.71	13.45	102	197	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:5	19.09	2994	1.71	13.44	102	197	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:5	19.09	2994	1.71	13.44	102	197	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:6	19.09	2990	1.71	13.44	102	197	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:6	19.09	2986	1.71	13.44	102	197	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:6	19.09	2981	1.71	13.44	102	197	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:6	19.09	2980	1.71	13.45	102	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:6	19.09	2988	1.71	13.43	102	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:6	19.09	2970	1.71	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:6	19.09	2970	1.71	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:28:7	19.09	2966	1.71	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:7	19.09	2964	1.71	13.43	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:7	19.09	2964	1.71	13.42	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:7	19.09	2959	1.71	13.43	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:7	19.09	2956	1.71	13.42	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:7	19.09	2956	1.71	13.42	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:8	19.09	2956	1.7	13.42	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:8	19.09	2943	1.7	13.43	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:8	19.09	2955	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:8	19.09	2959	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:8	19.09	2960	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:8	19.09	2962	1.7	13.43	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.06	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:9	19.09	2962	1.7	13.43	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.06	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:9	19.09	2960	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.06	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:9	19.09	2947	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.05	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:9	19.09	2957	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.06	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:9	19.09	2954	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.06	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:9	19.09	2952	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.06	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:28:9	19.09	2944	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.06	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:0	19.09	2939	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:0	19.09	2938	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:0	19.09	2930	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:0	19.09	2921	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:0	19.09	2916	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:0	19.09	2904	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:1	19.09	2910	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:1	19.09	2908	1.7	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:1	19.09	2908	1.7	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:1	19.09	2906	1.7	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:1	19.09	2904	1.7	13.44	102	197	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:1	19.09	2902	1.7	13.44	102	197	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:1	19.09	2902	1.7	13.43	102	197	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:2	19.09	2900	1.7	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:2	19.09	2896	1.7	13.44	102	197	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:2	19.09	2893	1.7	13.44	102	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:2	19.09	2893	1.7	13.44	102	197	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:2	19.09	2889	1.7	13.42	102	197	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:2	19.09	2883	1.7	13.43	102	197	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:3	19.09	2882	1.7	13.43	102	197	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:3	19.09	2880	1.7	13.42	102	197	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:3	19.09	2875	1.7	13.42	102	197	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:3	19.09	2876	1.7	13.43	102	197	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:3	19.09	2874	1.7	13.45	102	197	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:3	19.09	2871	1.7	13.41	102	197	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:4	19.09	2868	1.7	13.39	102	197	Idle	42.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:4	19.09	2868	1.7	13.37	102	197	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:4	19.09	2874	1.7	13.37	102	197	Idle	42.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:4	19.09	2862	1.7	13.36	102	197	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:4	19.09	2851	1.7	13.38	102	197	Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:4	19.09	2858	1.69	13.39	102	197	Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:4	19.09	2854	1.69	13.38	102	197	Idle	43.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:5	19.09	2852	1.69	13.39	102	197	Idle	44.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:5	19.09	2852	1.69	13.39	102	197	Idle	44.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:5	19.09	2852	1.69	13.39	102	197	Idle	44.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:5	19.09	2838	1.69	13.39	102	197	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.26	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:5	19.09	2850	1.68	13.39	102	197	Idle	44.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.26	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:5	19.09	2849	1.68	13.39	102	197	Idle	44.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:6	19.09	2845	1.68	13.4	102	197	Idle	44.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.26	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:29:6	19.09	2842	1.68	13.39	102	197	Idle	44.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.26	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:6	19.09	2861	1.68	13.39	102	197	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.26	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:6	19.09	2850	1.68	13.39	102	197	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:6	19.09	2834	1.67	13.39	102	197	Idle	44.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:6	19.09	2831	1.67	13.38	102	197	Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:6	19.09	2826	1.67	13.4	102	197	Idle	45.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:7	19.09	2797	1.67	13.38	102	197	Idle	45.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:7	19.09	2810	1.67	13.38	102	197	Idle	45.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:7	19.09	2801	1.67	13.38	102	197	Idle	45.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:7	19.09	2801	1.66	13.4	102	197	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:7	19.09	2792	1.66	13.41	102	197	Idle	46	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:7	19.09	2781	1.66	13.41	102	197	Idle	46.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:8	19.09	2777	1.66	13.41	102	197	Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:8	19.09	2765	1.65	13.4	102	197	Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:8	19.09	2764	1.65	13.41	102	197	Idle	46.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:8	19.09	2756	1.65	13.39	102	197	Idle	46.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:8	19.09	2730	1.65	13.38	102	197	Idle	46.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:8	19.09	2738	1.65	13.37	102	197	Idle	46.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:9	19.09	2738	1.64	13.37	102	197	Idle	46.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:9	19.09	2730	1.64	13.37	102	197	Idle	46.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:9	19.09	2730	1.64	13.38	102	197	Idle	47	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:9	19.09	2723	1.64	13.38	102	197	Idle	46.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:9	19.09	2718	1.64	13.39	102	197	Idle	46.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:9	19.09	2712	1.63	13.39	102	197	Idle	47.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:29:9	19.09	2705	1.63	13.39	102	197	Idle	47.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:0	19.09	2703	1.63	13.39	102	197	Idle	47.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:0	19.09	2685	1.63	13.4	102	197	Idle	47.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:0	19.09	2686	1.63	13.4	102	197	Idle	47.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:0	19.09	2679	1.62	13.41	102	197	Idle	48.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:0	19.09	2679	1.62	13.41	102	197	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:0	19.09	2669	1.62	13.42	102	197	Idle	48.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:1	19.09	2669	1.61	13.4	102	197	Idle	49.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:1	19.09	2656	1.61	13.4	102	197	Idle	49.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:1	19.09	2638	1.6	13.39	102	197	Idle	49.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:1	19.09	2641	1.6	13.4	102	197	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:1	19.09	2639	1.59	13.4	102	197	Idle	50.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:1	19.09	2639	1.59	13.4	102	197	Idle	51.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:1	19.09	2622	1.58	13.41	102	197	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:2	19.09	2618	1.58	13.4	102	197	Idle	52	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:2	19.09	2590	1.57	13.4	102	197	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:2	19.09	2598	1.57	13.4	102	197	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:2	19.09	2598	1.56	13.39	102	197	Idle	52.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:2	19.09	2591	1.56	13.39	102	197	Idle	53	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:2	19.09	2581	1.55	13.4	102	197	Idle	53.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:3	19.09	2581	1.55	13.4	102	197	Idle	53.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:3	19.09	2572	1.54	13.4	102	197	Idle	53.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:3	19.09	2568	1.53	13.38	102	197	Idle	54	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:3	19.09	2556	1.53	13.39	102	197	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:3	19.09	2558	1.52	13.39	102	197	Idle	54.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:3	19.09	2547	1.52	13.39	102	197	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.26	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:4	19.09	2542	1.51	13.4	102	197	Idle	55	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:4	19.09	2537	1.51	13.4	102	197	Idle	55.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:4	19.09	2536	1.5	13.39	102	197	Idle	55.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:4	19.09	2507	1.49	13.38	102	197	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:4	19.09	2507	1.49	13.38	102	197	Idle	56.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:4	19.09	2525	1.49	13.38	102	197	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:4	19.09	2509	1.48	13.38	102	197	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:5	19.09	2498	1.47	13.37	102	197	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:30:5	19.09	2498	1.47	13.38	102	197	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:5	19.09	2483	1.46	13.38	102	197	Idle	58.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:5	19.09	2482	1.46	13.39	102	197	Idle	58.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:5	19.09	2479	1.45	13.38	102	197	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:5	19.09	2468	1.44	13.38	102	197	Idle	59.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:6	19.09	2460	1.44	13.38	102	197	Idle	59.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:6	19.09	2451	1.43	13.39	102	197	Idle	60.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:6	19.09	2448	1.42	13.39	102	197	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:6	19.09	2437	1.41	13.4	102	197	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:6	19.09	2429	1.4	13.39	102	197	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:6	19.09	2405	1.4	13.39	102	197	Idle	61.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:6	19.09	2412	1.39	13.39	102	197	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:7	19.09	2412	1.38	13.39	102	197	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:7	17.72	2394	1.38	13.39	102	197	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:7	17.72	2379	1.37	13.4	102	197	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:7	17.72	2379	1.36	13.38	102	197	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:7	17.72	2391	1.36	13.37	102	197	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:7	17.72	2404	1.35	13.39	102	197	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:8	17.72	2384	1.35	13.39	102	197	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:8	17.72	2358	1.34	13.4	102	197	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:8	17.72	2358	1.33	13.41	102	197	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:8	17.72	2368	1.32	13.41	102	197	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:8	17.72	2361	1.32	13.4	102	197	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:8	17.72	2353	1.31	13.4	102	197	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:9	17.72	2353	1.3	13.39	102	197	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:9	17.72	2340	1.3	13.39	102	197	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:9	17.72	2332	1.29	13.38	102	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:9	17.72	2320	1.28	13.38	102	197	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:9	17.72	2295	1.27	13.38	102	197	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:9	17.72	2300	1.27	13.38	102	197	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:30:9	17.72	2292	1.26	13.38	102	197	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:0	17.72	2279	1.25	13.4	102	197	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:0	17.72	2279	1.24	13.39	102	197	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:0	17.72	2266	1.23	13.38	102	197	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:0	17.72	2252	1.22	13.38	102	197	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:0	17.72	2243	1.21	13.36	102	197	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:0	17.72	2225	1.2	13.37	102	197	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:1	17.72	2225	1.2	13.37	102	197	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:1	17.72	2206	1.19	13.37	102	197	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:1	17.72	2203	1.18	13.39	102	197	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:1	17.72	2190	1.17	13.39	102	197	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:1	17.72	2190	1.17	13.41	102	197	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:1	17.72	2180	1.16	13.41	102	197	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:1	17.72	2171	1.15	13.41	102	197	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:2	17.72	2165	1.15	13.41	102	197	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:2	17.72	2162	1.15	13.41	102	197	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:2	17.72	2151	1.14	13.39	102	197	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:2	17.72	2144	1.14	13.4	102	197	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:2	17.72	2140	1.13	13.38	102	197	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:2	17.72	2129	1.12	13.38	102	197	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:3	17.72	2118	1.12	13.37	102	197	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:3	17.72	2108	1.11	13.35	102	197	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:3	17.72	2108	1.1	13.35	102	197	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:3	17.72	2087	1.09	13.35	102	197	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:3	17.72	2085	1.09	13.36	102	197	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:3	17.72	2077	1.08	13.37	102	197	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:4	17.72	2074	1.07	13.38	102	197	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:4	17.72	2063	1.07	13.4	102	197	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:31:4	17.72	2057	1.06	13.39	102	197	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:4	17.72	2054	1.06	13.38	102	197	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:4	17.72	2044	1.05	13.38	102	197	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:4	17.72	2022	1.05	13.39	102	197	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:4	17.72	2028	1.04	13.39	102	197	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:5	17.72	2028	1.03	13.4	102	197	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:5	17.72	2019	1.03	13.39	102	197	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:5	17.72	2010	1.03	13.39	102	197	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:5	17.72	2004	1.02	13.39	102	197	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:5	17.72	2002	1.02	13.38	102	197	Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:5	17.72	1992	1.02	13.39	102	197	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:6	17.72	1986	1.02	13.4	102	197	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:6	17.72	1980	1.02	13.4	102	197	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.24	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:6	17.72	1977	1.02	13.39	102	197	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.24	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:6	17.72	1968	1.02	13.39	102	197	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.24	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:6	17.72	1963	1.02	13.4	102	197	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.24	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:6	17.72	1953	1.01	13.39	102	197	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:6	17.72	1955	1.01	13.38	102	197	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:7	17.72	1948	1.01	13.38	102	197	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:7	17.72	1947	1.01	13.39	102	197	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:7	17.72	1946	1	13.39	102	197	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:7	17.72	1940	1	13.4	102	197	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:7	17.72	1934	1	13.4	102	197	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:7	17.72	1934	0.99	13.39	102	197	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:8	17.72	1930	0.99	13.38	102	197	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:8	17.72	1920	0.99	13.38	102	197	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:8	17.72	1920	0.99	13.37	102	197	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:8	17.72	1918	0.99	13.37	102	197	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:8	17.72	1909	0.98	13.37	102	197	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:8	17.72	1906	0.98	13.37	102	197	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:9	17.72	1898	0.98	13.37	102	197	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:9	17.72	1890	0.98	13.38	102	197	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:9	17.72	1882	0.98	13.37	102	197	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:9	17.72	1882	0.97	13.36	102	197	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:9	17.72	1874	0.97	13.35	102	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:9	17.72	1872	0.97	13.37	102	197	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:31:9	17.72	1862	0.97	13.37	102	197	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:0	17.72	1862	0.97	13.37	102	197	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:0	17.72	1858	0.97	13.37	102	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:0	17.72	1852	0.97	13.39	102	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:0	17.72	1831	0.96	13.37	102	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:0	17.72	1831	0.96	13.38	102	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:0	17.72	1841	0.96	13.4	102	197	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:1	17.72	1836	0.96	13.38	102	197	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.24	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:1	17.72	1830	0.96	13.38	102	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.24	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:1	17.72	1830	0.96	13.39	102	197	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.24	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:1	17.72	1826	0.96	13.37	102	197	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.24	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:1	17.72	1823	0.96	13.38	102	197	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:1	17.72	1823	0.96	13.39	102	197	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:1	17.72	1815	0.96	13.37	102	197	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:2	17.72	1810	0.96	13.37	102	197	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:2	17.72	1808	0.96	13.37	102	197	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:2	17.72	1801	0.96	13.39	102	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:2	17.72	1796	0.96	13.37	102	197	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:2	17.72	1792	0.96	13.39	102	197	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:2	17.72	1792	0.96	13.38	102	197	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:3	17.72	1781	0.96	13.37	102	197	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:3	17.72	1778	0.96	13.37	102	197	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:32:3	17.72	1778	0.96	13.37	102	197	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:3	17.72	1775	0.96	13.37	102	197	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:3	17.72	1773	0.96	13.39	102	197	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:3	17.72	1772	0.96	13.38	102	197	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:4	17.72	1772	0.96	13.38	102	197	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:4	17.72	1769	0.96	13.37	102	197	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:4	17.72	1765	0.96	13.36	102	197	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.24	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:4	17.72	1764	0.96	13.37	102	197	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:4	17.72	1760	0.96	13.36	102	197	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:4	17.72	1766	0.96	13.38	102	197	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:4	17.72	1757	0.96	13.38	102	197	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:5	17.72	1754	0.96	13.36	102	197	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:5	17.72	1754	0.95	13.36	102	197	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:5	17.72	1749	0.95	13.35	102	197	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:5	17.72	1745	0.95	13.36	102	197	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:5	17.72	1745	0.95	13.39	102	197	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:5	17.72	1740	0.95	13.4	102	197	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:6	17.72	1739	0.95	13.42	102	197	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:6	17.72	1737	0.95	13.42	102	197	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:6	17.72	1737	0.95	13.42	102	197	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:6	17.72	1734	0.95	13.41	102	197	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:6	17.72	1732	0.95	13.4	102	197	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:6	17.72	1729	0.95	13.41	102	197	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:6	17.72	1728	0.95	13.41	102	197	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:7	17.72	1726	0.95	13.41	102	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:7	17.72	1723	0.95	13.42	102	197	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:7	17.72	1720	0.95	13.42	102	197	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:7	17.72	1720	0.95	13.42	102	197	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:7	17.72	1718	0.94	13.41	102	197	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:7	17.72	1703	0.94	13.41	102	197	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:8	17.72	1708	0.94	13.41	102	197	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:8	17.72	1726	0.94	13.4	102	197	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:8	17.72	1710	0.94	13.41	102	197	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:8	17.72	1709	0.94	13.41	102	197	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:8	17.72	1709	0.94	13.41	102	197	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:8	17.72	1706	0.94	13.42	102	197	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:9	17.72	1702	0.94	13.42	102	197	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.16	1.37	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:9	17.72	1702	0.93	13.42	102	197	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.17	1.37	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:9	17.72	1692	0.93	13.42	102	197	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.17	1.37	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:9	17.72	1697	0.93	13.41	102	197	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.17	1.37	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:9	17.72	1696	0.93	13.41	102	197	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.18	1.37	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:9	17.72	1692	0.93	13.41	102	197	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.18	1.37	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:32:9	17.72	1692	0.93	13.42	102	197	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.18	1.37	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:0	17.72	1687	0.93	13.42	102	197	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.18	1.37	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:0	17.72	1685	0.93	13.43	102	197	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.19	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:0	17.72	1685	0.93	13.43	102	197	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.19	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:0	17.72	1683	0.93	13.43	102	197	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.25	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:0	17.72	1680	0.93	13.42	102	197	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:0	17.72	1680	0.93	13.42	102	197	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:1	17.72	1678	0.93	13.41	102	197	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:1	17.72	1675	0.93	13.43	102	197	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:1	17.72	1674	0.93	13.42	102	197	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:1	17.72	1672	0.93	13.42	102	197	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:1	17.72	1670	0.93	13.41	102	197	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:1	17.72	1667	0.93	13.41	102	197	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:1	17.72	1667	0.93	13.42	102	197	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:2	17.72	1664	0.93	13.41	102	197	Full Load	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:2	17.72	1664	0.93	13.42	102	197	Off Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:33:2	8.18	1578	0.94	13.41	102	197	Off Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:13:33:2	8.18	1671	0.94	13.41	102	197	Off Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:13:33:2	10.9	1671	0.94	13.41	102	197	Off Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:13:33:2	10.9	1670	0.95	13.4	102	197	Off Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:3	10.9	1667	0.95	13.4	102	197	Off Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:3	13.63	1667	0.96	13.41	102	197	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:3	13.63	1663	0.97	13.41	102	197	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.24	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:3	16.36	1663	0.97	13.41	102	197	Off Idle	86	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:3	16.36	1661	0.98	13.42	102	197	Off Idle	86.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.23	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:3	19.09	1659	0.99	13.41	102	197	Off Idle	86.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:4	19.09	1658	1	13.41	102	197	Off Idle	86.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:4	21.81	1661	1	13.41	102	197	Off Idle	86.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:4	21.81	1661	1.01	13.42	102	197	Off Idle	86.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:4	24.54	1666	1.02	13.41	102	197	Off Idle	86.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:4	24.54	1671	1.03	13.42	102	197	Off Idle	86.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:4	24.54	1674	1.04	13.41	102	197	Off Idle	86.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:4	27.27	1678	1.05	13.41	102	197	Off Idle	86.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:5	27.27	1679	1.06	13.42	102	197	Off Idle	86.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:5	29.99	1679	1.07	13.43	102	197	Off Idle	86.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:5	29.99	1674	1.08	13.41	102	197	Off Idle	86.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:5	29.99	1670	1.09	13.41	102	197	Off Idle	86.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:5	29.99	1669	1.1	13.39	102	197	Off Idle	86.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:5	29.99	1679	1.1	13.39	102	197	Off Idle	86.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:6	31.36	1679	1.11	13.39	102	197	Off Idle	86.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:6	31.36	1664	1.11	13.4	102	197	Off Idle	86.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:6	31.36	1660	1.12	13.4	102	197	Off Idle	86.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:6	31.36	1659	1.12	13.42	102	197	Off Idle	86.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:6	31.36	1658	1.12	13.42	102	197	Off Idle	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:6	31.36	1654	1.12	13.4	102	197	Full Load	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:6	31.36	1651	1.11	13.4	102	197	Idle	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:7	31.36	1647	1.1	13.41	102	197	Idle	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.21	1.38	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:33:7	31.36	1629	1.07	13.41	102	197	Idle	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:7	29.99	1629	1.06	13.41	102	197	Idle	86.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:7	29.99	1640	1.05	13.41	102	197	Idle	86.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.21	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:13:33:7	29.99	1637	1.04	13.41	102	197	Idle	86	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.17	20.22	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:13:33:7	29.99	1637	1.04	13.41	102	197	Idle	85.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.18	20.22	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:8	29.99	1628	1.03	13.42	102	197	Idle	85.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.23	20.21	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:8	29.99	1611	1.01	13.4	102	197	Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.24	20.21	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:8	29.99	1594	1	13.42	102	197	Idle	85.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.26	20.21	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:8	29.99	1594	0.99	13.42	102	197	Idle	85.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	20.23	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:8	29.99	1578	0.98	13.42	102	197	Idle	85.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.28	20.23	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:8	28.63	1554	0.97	13.41	102	197	Idle	84.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.31	20.23	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:9	28.63	1554	0.96	13.41	102	197	Idle	84.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.3	20.23	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:33:9	28.63	1567	0.95	13.41	102	197	Idle	84	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.29	20.22	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:9	28.63	1578	0.94	13.41	102	197	Idle	83.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.24	20.22	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:9	28.63	1578	0.93	13.4	102	197	Idle	83.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.21	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:9	28.63	1589	0.92	13.4	102	197	Idle	82.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.19	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:9	28.63	1609	0.93	13.4	102	197	Idle	82.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.17	20.22	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:33:9	28.63	1609	0.94	13.4	102	197	Idle	82.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.18	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:0	28.63	1643	0.95	13.41	102	197	Idle	82.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.18	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:0	27.27	1658	0.96	13.42	102	197	Idle	82.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.19	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:0	27.27	1650	0.96	13.42	102	197	Idle	83	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.2	20.22	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:0	27.27	1666	0.96	13.42	102	197	Idle	83.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.22	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:0	27.27	1668	0.96	13.42	102	197	Idle	83.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.22	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:0	27.27	1663	0.96	13.41	102	197	Idle	84.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.24	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:1	27.27	1660	0.96	13.42	102	197	Idle	84.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.27	20.12	1.37	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:1	27.27	1653	0.96	13.42	102	197	Idle	85.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.29	20.03	1.36	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:1	27.27	1632	0.96	13.42	102	197	Idle	85.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.32	19.89	1.36	4	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:34:1	27.27	1623	0.96	13.42	102	197	Idle	86.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.36	19.71	1.34	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:1	27.27	1623	0.96	13.42	102	197	Idle	86.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	19.5	1.33	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:1	25.9	1600	0.95	13.42	102	197	Idle	87.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.38	19.12	1.3	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:1	25.9	1600	0.95	13.42	102	197	Idle	87.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	18.98	1.29	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:2	25.9	1595	0.95	13.41	102	197	Idle	87.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.4	18.68	1.27	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:2	25.9	1583	0.94	13.42	102	197	Idle	87.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	18.38	1.25	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:2	25.9	1572	0.94	13.43	102	197	Idle	87.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.41	17.97	1.22	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:2	25.9	1563	0.93	13.4	102	197	Idle	86.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.4	17.61	1.2	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:2	25.9	1559	0.93	13.38	102	197	Idle	86.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.37	17.42	1.19	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:2	25.9	1548	0.93	13.37	102	197	Idle	85.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.36	17.19	1.17	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:3	25.9	1556	0.92	13.35	102	197	Idle	85.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.31	17.08	1.16	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:3	24.54	1562	0.92	13.37	102	197	Idle	84.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.3	16.95	1.15	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:3	24.54	1570	0.92	13.38	102	197	Idle	84.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.29	16.88	1.15	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:3	24.54	1583	0.92	13.39	102	198	Idle	83.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.25	16.83	1.15	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:3	24.54	1586	0.93	13.39	102	198	Idle	83.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.22	16.78	1.14	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:3	24.54	1590	0.93	13.39	102	198	Idle	83.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.23	16.74	1.14	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:4	24.54	1605	0.93	13.39	102	197	Idle	83.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.24	16.7	1.14	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:4	24.54	1615	0.93	13.37	102	197	Idle	83.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.24	16.64	1.13	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:4	24.54	1618	0.93	13.39	102	197	Idle	84.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.25	16.6	1.13	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:4	24.54	1618	0.93	13.37	102	197	Idle	85.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.26	16.57	1.13	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:4	24.54	1628	0.93	13.37	102	197	Idle	86	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.27	16.53	1.13	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:4	23.18	1597	0.93	13.36	102	197	Idle	86.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.28	16.5	1.12	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:4	23.18	1600	0.93	13.36	102	197	Idle	87.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.31	16.48	1.12	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:5	23.18	1601	0.93	13.35	102	197	Idle	88.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.33	16.45	1.12	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:5	23.18	1589	0.93	13.36	102	197	Idle	89	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.33	16.42	1.12	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:5	23.18	1573	0.93	13.36	102	197	Idle	90.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.33	16.37	1.12	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:5	23.18	1573	0.92	13.38	102	197	Idle	91.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.33	16.35	1.11	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:5	23.18	1577	0.92	13.38	102	197	Idle	91.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.31	16.31	1.11	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:5	23.18	1570	0.91	13.37	102	197	Idle	92.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.31	16.27	1.11	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:6	23.18	1561	0.91	13.37	102	197	Idle	92.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.32	16.23	1.11	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:6	21.81	1551	0.9	13.37	102	197	Idle	92.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.32	16.19	1.1	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:6	21.81	1548	0.9	13.35	102	197	Idle	92	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.32	15.97	1.09	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:6	21.81	1548	0.89	13.37	102	197	Idle	91.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.33	15.95	1.09	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:6	21.81	1545	0.89	13.36	102	197	Idle	91.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-10.33	15.89	1.08	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:6	21.81	1539	0.88	13.36	102	197	Idle	91.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-10.31	15.82	1.08	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:6	21.81	1536	0.88	13.37	102	197	Idle	91.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.32	15.78	1.08	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:7	21.81	1536	0.87	13.36	102	197	Idle	91.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.3	15.74	1.07	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:7	21.81	1524	0.87	13.36	102	197	Idle	90.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.3	15.7	1.07	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:7	21.81	1521	0.86	13.36	102	197	Idle	90.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.29	15.68	1.07	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:7	21.81	1516	0.86	13.36	102	197	Idle	90.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.29	15.65	1.07	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:7	20.45	1497	0.86	13.36	102	197	Idle	90.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.3	15.77	1.07	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:7	20.45	1478	0.86	13.37	102	197	Idle	90	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.29	15.75	1.07	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:13:34:8	20.45	1474	0.86	13.39	102	197	Idle	89.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.26	15.72	1.07	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:8	20.45	1456	0.86	13.38	102	197	Idle	89.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.25	15.69	1.07	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:8	20.45	1437	0.86	13.37	102	197	Idle	89.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.23	15.65	1.07	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:8	20.45	1437	0.86	13.37	102	197	Idle	89.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.19	15.62	1.06	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:8	20.45	1405	0.86	13.38	102	197	Idle	88.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.18	15.59	1.06	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:8	20.45	1407	0.86	13.36	102	197	Idle	88.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.13	15.53	1.06	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:9	21.81	1394	0.86	13.36	102	197	Idle	88.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.13	15.49	1.06	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:9	21.81	1374	0.87	13.37	102	197	Idle	88.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.1	15.48	1.05	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:13:34:9	21.81	1374	0.87	13.36	102	197	Idle	87.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.05	15.44	1.05	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:34:9	20.45	1335	0.87	13.36	102	197	Idle	87.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.01	15.41	1.05	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:34:9	20.45	1344	0.87	13.35	102	197	Idle	87.7	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.99	15.36	1.05	4.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:34:9	20.45	1333	0.88	13.36	102	197	Idle	87.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.98	15.31	1.04	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:34:9	20.45	1333	0.88	13.36	102	197	Idle	88	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.93	15.28	1.04	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:0	20.45	1330	0.88	13.35	102	197	Idle	88.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.92	15.24	1.04	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:0	20.45	1330	0.88	13.37	102	197	Idle	89	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.89	15.2	1.04	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:0	20.45	1307	0.88	13.37	102	197	Idle	89.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.9	15.16	1.03	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:35:0	20.45	1287	0.88	13.37	102	197	Idle	89.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.91	15.12	1.03	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:0	20.45	1289	0.88	13.38	102	197	Idle	90.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.88	15.07	1.03	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:0	20.45	1289	0.88	13.37	102	197	Idle	91.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.85	15.06	1.03	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:1	20.45	1280	0.88	13.35	102	197	Idle	91.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.83	15.06	1.03	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:35:1	20.45	1271	0.88	13.35	102	197	Idle	92.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.79	15.04	1.02	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:35:1	19.09	1261	0.88	13.35	102	197	Idle	92.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.77	15.01	1.02	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:35:1	19.09	1261	0.88	13.35	102	197	Idle	92.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.77	14.99	1.02	4.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:13:35:1	19.09	1269	0.87	13.36	102	197	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.72	14.97	1.02	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:1	19.09	1252	0.87	13.37	102	197	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.68	14.95	1.02	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:1	19.09	1230	0.86	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.66	14.93	1.02	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:2	19.09	1228	0.86	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.69	14.9	1.02	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:2	19.09	1227	0.85	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.66	14.87	1.01	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:2	19.09	1206	0.85	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.65	14.87	1.01	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:2	19.09	1206	0.84	13.4	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.62	14.86	1.01	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:2	19.09	1199	0.84	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	14.86	1.01	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:2	19.09	1187	0.84	13.41	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.56	14.86	1.01	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:3	19.09	1187	0.84	13.41	102	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.55	14.84	1.01	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:3	17.72	1169	0.84	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.51	14.82	1.01	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:3	17.72	1169	0.83	13.4	102	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.53	14.82	1.01	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:3	17.72	1158	0.83	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.47	14.84	1.01	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:3	17.72	1160	0.83	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.46	14.83	1.01	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:3	17.72	1160	0.83	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.38	14.85	1.01	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:4	17.72	1151	0.83	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.39	14.88	1.01	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:13:35:4	17.72	1148	0.83	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.4	14.91	1.02	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:4	17.72	1148	0.83	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.34	14.95	1.02	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:4	17.72	1148	0.83	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.3	14.98	1.02	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:4	17.72	1129	0.83	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.26	15.01	1.02	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:4	17.72	1111	0.83	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.25	15.05	1.03	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:4	17.72	1112	0.82	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.21	15.07	1.03	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:5	17.72	1112	0.82	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.19	15.08	1.03	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:5	16.36	1104	0.82	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.2	15.11	1.03	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:5	16.36	1095	0.82	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.19	15.14	1.03	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:5	16.36	1095	0.82	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.16	15.15	1.03	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:5	16.36	1095	0.82	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.11	15.16	1.03	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:5	16.36	1093	0.82	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.1	15.18	1.03	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:6	16.36	1091	0.82	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.07	15.2	1.04	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:6	16.36	1088	0.82	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.02	15.11	1.03	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:6	16.36	1078	0.81	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.04	15.11	1.03	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:6	16.36	1070	0.81	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.99	15.12	1.03	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:6	16.36	1073	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.98	15.11	1.03	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:6	16.36	1073	0.81	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.93	15.11	1.03	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:6	16.36	1073	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.95	15.1	1.03	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:7	16.36	1073	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.92	15.09	1.03	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:7	16.36	1060	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.9	15.07	1.03	4.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:7	16.36	1033	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.91	15.04	1.02	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:7	14.99	1033	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.85	15.12	1.03	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:7	14.99	1042	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.86	15.1	1.03	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:7	14.99	1051	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.81	15.08	1.03	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:8	14.99	1040	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.79	15.09	1.03	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:8	14.99	1040	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.78	15.08	1.03	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:13:35:8	14.99	1043	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.78	15.08	1.03	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:35:8	14.99	1043	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.76	15.06	1.03	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:13:35:8	14.99	1031	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.78	15.03	1.02	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:35:8	14.99	1015	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.75	15.01	1.02	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:35:9	14.99	1011	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.73	14.98	1.02	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:35:9	14.99	1019	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.71	14.97	1.02	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:35:9	14.99	1019	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.68	14.95	1.02	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:35:9	14.99	1009	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.65	14.92	1.02	4.7	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:35:9	14.99	999	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.61	14.86	1.01	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:13:35:9	13.63	999	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.62	14.83	1.01	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:13:35:9	13.63	982	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.57	14.8	1.01	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:0	13.63	981	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.59	14.8	1.01	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:0	13.63	981	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.53	14.77	1.01	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:0	13.63	984	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.52	14.74	1	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:0	13.63	986	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.49	14.72	1	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:0	13.63	984	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.48	14.69	1	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:0	13.63	984	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.45	14.67	1	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:1	13.63	985	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.46	14.65	1	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:1	13.63	985	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.41	14.63	1	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:1	13.63	980	0.8	13.33	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.37	14.61	1	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:1	13.63	975	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.39	14.57	0.99	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:1	13.63	975	0.8	13.33	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.34	14.55	0.99	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:1	13.63	975	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.36	14.54	0.99	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:1	13.63	973	0.8	13.33	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.36	14.52	0.99	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:2	13.63	971	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.38	14.51	0.99	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:2	10.9	943	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.34	14.5	0.99	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:2	10.9	943	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.34	14.5	0.99	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:13:36:2	10.9	958	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.29	14.49	0.99	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:2	10.9	958	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.29	14.5	0.99	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:2	12.27	959	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.23	14.51	0.99	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:3	12.27	959	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.25	14.52	0.99	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:3	12.27	948	0.8	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.21	14.55	0.99	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:3	12.27	946	0.8	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.21	14.56	0.99	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:3	12.27	944	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.19	14.56	0.99	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:3	12.27	944	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.21	14.57	0.99	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:3	12.27	936	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.11	14.58	0.99	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:4	12.27	936	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.12	14.59	0.99	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:4	12.27	932	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.14	14.61	1	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:4	12.27	927	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.13	14.63	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:4	12.27	933	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.12	14.63	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:4	12.27	933	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.13	14.65	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:4	10.9	926	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.1	14.64	1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:4	10.9	920	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.1	14.66	1	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:5	10.9	929	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.07	14.67	1	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:5	10.9	929	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.07	14.68	1	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:5	10.9	941	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.06	14.69	1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:5	10.9	953	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.08	14.7	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:5	10.9	944	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.02	14.71	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:5	10.9	934	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.03	14.72	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:6	9.54	937	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.01	14.73	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:6	9.54	937	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.99	14.74	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:6	9.54	936	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8	14.76	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:6	9.54	935	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.01	14.77	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:6	9.54	936	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8	14.78	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:6	9.54	936	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8	14.79	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:6	9.54	934	0.79	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.02	14.81	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:7	9.54	931	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.99	14.83	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:7	8.18	915	0.79	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8	14.83	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:7	8.18	915	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.01	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:7	8.18	918	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:7	8.18	922	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:7	9.54	920	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.98	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:8	9.54	920	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.98	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:8	9.54	917	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.95	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:8	9.54	914	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.93	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:8	9.54	936	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.98	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:36:8	9.54	936	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.95	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:8	9.54	925	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.98	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:9	9.54	914	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.92	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:9	9.54	914	0.79	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.95	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:9	9.54	919	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.91	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:9	9.54	919	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.9	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:9	9.54	924	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.9	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:9	9.54	912	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.94	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:36:9	8.18	899	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.89	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:0	8.18	899	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.92	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:0	8.18	903	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.88	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:0	8.18	903	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.89	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:0	8.18	906	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.89	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:0	8.18	908	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.89	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:0	8.18	893	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.89	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:1	8.18	893	0.8	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.89	14.83	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:1	8.18	864	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.89	14.83	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:1	8.18	864	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.87	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:1	8.18	864	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.85	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:1	8.18	868	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.82	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:1	9.54	873	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:1	9.54	873	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.78	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:2	9.54	873	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:2	9.54	886	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.76	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:2	9.54	880	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:2	10.9	873	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	14.87	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:2	10.9	873	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.86	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:2	10.9	858	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:3	10.9	858	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:3	10.9	881	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:3	10.9	881	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:3	10.9	883	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:3	10.9	883	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:3	10.9	883	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:4	8.18	891	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:4	8.18	900	0.79	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.74	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:4	8.18	900	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.9	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:4	8.18	901	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.92	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:4	8.18	902	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:4	8.18	913	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:4	8.18	913	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:5	8.18	895	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:5	6.81	877	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:5	6.81	877	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:5	6.81	894	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:5	6.81	894	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:5	8.18	897	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.65	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:6	8.18	900	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.67	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:6	8.18	900	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.67	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:6	8.18	900	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.69	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:6	8.18	884	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.71	15.13	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:6	8.18	884	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.74	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:6	8.18	900	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.71	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:6	8.18	900	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.73	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:7	8.18	896	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.74	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:7	8.18	896	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:7	8.18	896	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:37:7	8.18	895	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	15.19	1.04	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:37:7	8.18	903	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	15.2	1.04	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:7	8.18	911	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.21	1.04	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:8	8.18	911	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.21	1.04	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:8	8.18	900	0.79	13.4	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	15.22	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:8	8.18	909	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.21	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:8	9.54	918	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.22	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:8	9.54	918	0.79	13.4	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.22	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:8	9.54	894	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.21	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:9	9.54	894	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.2	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:9	8.18	900	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.2	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:9	8.18	900	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	15.18	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:9	8.18	904	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	15.16	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:9	8.18	908	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.15	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:9	8.18	908	0.79	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	15.13	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:37:9	8.18	911	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	15.12	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:0	8.18	899	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	15.09	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:0	8.18	899	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:0	8.18	899	0.79	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:0	8.18	898	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:0	8.18	885	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:0	8.18	885	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.78	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:1	8.18	885	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.77	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:1	8.18	889	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:1	8.18	891	0.79	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:1	8.18	891	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:1	8.18	891	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:1	8.18	884	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:1	8.18	884	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.7	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:2	8.18	882	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.65	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:2	8.18	879	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.66	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:2	9.54	887	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.66	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:2	9.54	887	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.68	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:2	9.54	887	0.79	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.69	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:2	9.54	878	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:3	10.9	896	0.79	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.69	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:3	10.9	896	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.71	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:3	10.9	896	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.7	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:3	10.9	890	0.79	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:3	10.9	892	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.71	14.88	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:3	10.9	893	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:4	10.9	904	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:4	10.9	904	0.79	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.66	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:4	10.9	904	0.79	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:4	9.54	900	0.79	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:4	9.54	900	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:4	9.54	906	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:4	9.54	906	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:5	9.54	897	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.66	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:5	9.54	897	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:5	9.54	907	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:5	9.54	907	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:5	8.18	894	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:5	8.18	894	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:6	8.18	900	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.74	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:6	8.18	906	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.74	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:6	8.18	918	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.72	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:6	8.18	918	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:6	8.18	918	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:38:6	8.18	917	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.72	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:6	6.81	930	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.74	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:7	6.81	930	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:7	6.81	930	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:7	6.81	931	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:7	6.81	917	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.76	15.05	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:7	6.81	917	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:7	6.81	919	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.8	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:8	6.81	921	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.79	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:8	6.81	920	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.8	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:8	6.81	920	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.74	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:8	6.81	920	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.79	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:8	6.81	919	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.76	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:8	6.81	919	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.81	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:9	6.81	910	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.81	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:9	6.81	910	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.82	15.19	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:38:9	6.81	917	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.78	15.21	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:9	6.81	917	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.81	15.22	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:9	6.81	920	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.78	15.23	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:9	6.81	920	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.82	15.23	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:38:9	6.81	912	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.84	15.23	1.04	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:0	6.81	911	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.84	15.23	1.04	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:0	8.18	911	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.84	15.23	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:0	8.18	911	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	15.22	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:0	8.18	904	0.8	13.36	102	197	Idle	93.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15.22	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:0	8.18	904	0.8	13.36	102	197	Idle	93.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.19	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:0	8.18	898	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15.18	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:1	8.18	893	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.16	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:1	8.18	894	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	15.16	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:1	8.18	894	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	15.15	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:1	9.54	898	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	15.13	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:1	9.54	901	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.12	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:1	9.54	901	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.11	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:39:1	9.54	884	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:2	9.54	884	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:2	8.18	894	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:2	8.18	894	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.77	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:2	8.18	894	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:2	8.18	894	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.74	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:2	8.18	898	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.72	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:3	8.18	901	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.75	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:3	8.18	887	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.73	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:3	8.18	887	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.76	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:3	9.54	894	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.76	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:3	9.54	894	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.76	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:3	9.54	889	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.76	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:4	9.54	889	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.77	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:4	9.54	886	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.74	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:4	9.54	886	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.73	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:4	9.54	890	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.73	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:4	9.54	893	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.71	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:4	9.54	897	0.8	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.74	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:4	9.54	897	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.71	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:5	9.54	897	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.75	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:5	9.54	887	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.71	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:5	9.54	887	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.74	14.9	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:5	10.9	910	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.89	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:5	10.9	910	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.76	14.89	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:39:5	10.9	911	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:6	10.9	911	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:6	8.18	904	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:6	8.18	904	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:6	8.18	902	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.68	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:6	8.18	902	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:6	8.18	914	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:6	8.18	914	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:7	8.18	903	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:7	8.18	903	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:7	8.18	903	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:7	8.18	893	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:7	8.18	896	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:7	8.18	896	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:8	8.18	896	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.78	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:8	8.18	883	0.8	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.72	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:8	8.18	892	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.73	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:8	8.18	892	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:39:8	8.18	892	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.74	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:39:8	8.18	889	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.75	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:39:9	8.18	889	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.78	14.97	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:39:9	8.18	900	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.77	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:9	8.18	910	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.79	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:9	8.18	910	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.76	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:9	8.18	912	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.79	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:9	8.18	913	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.77	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:39:9	8.18	913	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.77	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:0	8.18	921	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.78	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:0	8.18	921	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.77	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:0	8.18	910	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.76	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:0	8.18	910	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.75	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:0	8.18	916	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:0	8.18	923	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:1	8.18	915	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.79	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:1	8.18	915	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:1	8.18	920	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:1	8.18	924	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:1	8.18	921	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:1	8.18	921	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:1	8.18	921	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:2	6.81	911	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:2	6.81	932	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:2	6.81	932	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:2	6.81	932	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.86	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:2	6.81	912	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.83	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:2	6.81	930	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.86	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:3	6.81	930	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:3	6.81	930	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.84	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:3	6.81	919	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:3	6.81	926	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.85	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:3	6.81	926	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:3	6.81	926	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.84	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:4	6.81	922	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:4	6.81	925	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:4	6.81	925	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:4	6.81	925	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:4	8.18	918	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:4	8.18	918	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.84	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:40:4	8.18	925	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:5	8.18	925	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.83	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:5	9.54	922	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:5	9.54	918	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.83	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:40:5	9.54	922	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.8	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:5	9.54	922	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.84	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:5	8.18	920	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.83	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:6	8.18	917	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.87	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:6	8.18	924	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.8	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:6	8.18	924	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.85	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:6	9.54	924	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.82	14.84	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:6	9.54	924	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.85	14.84	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:6	9.54	935	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.85	14.83	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:6	9.54	935	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.88	14.82	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:7	9.54	922	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.89	14.82	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:7	9.54	922	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.87	14.83	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:7	9.54	926	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.86	14.83	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:7	9.54	929	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.88	14.84	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:7	8.18	932	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.86	14.83	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:7	8.18	932	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.87	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:8	8.18	932	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.88	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:8	8.18	933	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.85	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:8	8.18	929	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.88	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:8	8.18	929	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.87	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:8	8.18	921	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.9	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:8	8.18	913	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.89	14.87	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:9	8.18	928	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.95	14.87	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:9	6.81	928	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.9	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:9	6.81	924	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.88	14.88	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:9	6.81	924	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.88	14.88	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:9	6.81	909	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.89	14.88	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:9	8.18	899	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.84	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:40:9	8.18	913	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.87	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:0	8.18	913	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.84	14.88	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:0	8.18	904	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.87	14.88	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:0	8.18	894	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.84	14.89	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:0	8.18	901	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.86	14.89	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:0	8.18	901	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.84	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:0	8.18	901	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.88	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:1	8.18	908	0.8	13.33	102	197	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.83	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:1	8.18	908	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.85	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:1	8.18	908	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.82	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:1	8.18	907	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.82	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:1	8.18	901	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.79	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:1	8.18	901	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.81	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:1	8.18	905	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.83	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:2	8.18	905	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:2	8.18	906	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:2	8.18	908	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:2	8.18	909	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:2	8.18	909	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.8	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:2	8.18	914	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.82	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:3	8.18	919	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.82	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:3	8.18	917	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.83	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:3	8.18	917	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.81	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:3	8.18	916	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.81	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:3	8.18	916	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.79	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:3	8.18	911	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.81	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:41:4	8.18	911	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.79	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:4	8.18	911	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.82	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:4	6.81	912	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.82	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:4	6.81	927	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.85	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:4	6.81	927	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.85	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:4	6.81	927	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.84	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:4	6.81	920	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.79	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:5	6.81	935	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.8	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:41:5	6.81	935	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.77	14.96	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:5	6.81	935	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.82	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:5	8.18	908	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.86	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:5	8.18	918	0.8	13.4	102	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.89	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:5	8.18	927	0.8	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.88	15.02	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:6	8.18	933	0.8	13.4	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.87	15.03	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:6	8.18	933	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.85	15.03	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:6	8.18	933	0.8	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.84	15.04	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:6	8.18	936	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	15.05	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:6	8.18	938	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.87	15.06	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:6	8.18	924	0.8	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.05	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:6	8.18	924	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.87	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:7	8.18	921	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.84	15.04	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:7	8.18	918	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	15.03	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:7	8.18	924	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:7	8.18	924	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:7	8.18	922	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:7	8.18	922	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	14.99	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:8	9.54	936	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:8	9.54	936	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	14.99	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:8	9.54	922	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	14.98	1.02	5.2	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:8	9.54	909	0.81	13.39	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15	1.02	5.2	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:8	8.18	915	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.03	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:8	8.18	915	0.81	13.38	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:9	8.18	922	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:9	8.18	929	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:9	8.18	906	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:9	8.18	906	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:9	8.18	911	0.81	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:9	8.18	916	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	15.02	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:41:9	8.18	929	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.81	15	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:0	8.18	929	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.8	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:0	8.18	927	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.83	14.93	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:0	8.18	925	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.77	14.91	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:0	8.18	903	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.89	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:0	8.18	903	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.76	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:0	8.18	903	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.76	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:1	8.18	902	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.75	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:1	8.18	902	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.79	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:1	8.18	908	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.78	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:1	8.18	901	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.81	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:1	8.18	901	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.81	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:1	8.18	901	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.84	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:1	8.18	895	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.83	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:2	8.18	895	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.84	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:2	8.18	898	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.79	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:2	8.18	902	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.79	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:2	8.18	902	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.78	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:2	8.18	902	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:2	8.18	902	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:42:3	8.18	901	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:3	8.18	899	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.76	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:3	8.18	899	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:3	8.18	894	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.79	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:3	8.18	894	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:3	8.18	894	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.78	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:4	8.18	919	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:4	8.18	900	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.79	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:4	8.18	900	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.75	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:4	8.18	900	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.78	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:4	8.18	896	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:4	8.18	896	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.79	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:4	8.18	896	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:5	8.18	896	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:5	8.18	877	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:5	8.18	877	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.74	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:5	8.18	892	0.81	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.72	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:5	8.18	892	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.72	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:5	9.54	895	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.72	14.9	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:6	9.54	898	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.7	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:6	9.54	879	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.69	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:6	9.54	879	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.67	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:6	9.54	880	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.67	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:6	9.54	881	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.66	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:6	9.54	882	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:6	9.54	884	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.64	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:7	9.54	884	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.7	15.1	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:7	8.18	893	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	15.11	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:7	8.18	893	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	15.13	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:7	8.18	906	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.67	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:7	8.18	906	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.67	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:7	8.18	903	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:8	8.18	903	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:8	8.18	904	0.81	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:8	8.18	904	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:8	8.18	904	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.67	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:8	8.18	903	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.67	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:8	8.18	907	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.68	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:9	8.18	907	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:9	6.81	904	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:9	6.81	904	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:42:9	6.81	914	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:9	6.81	923	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	15.05	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:9	6.81	902	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:42:9	8.18	902	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	15.01	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:0	8.18	897	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:0	8.18	892	0.81	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:0	8.18	894	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:0	8.18	894	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:0	8.18	894	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:0	8.18	902	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:1	8.18	896	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:1	8.18	896	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:1	8.18	896	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:1	8.18	893	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:1	8.18	893	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:1	8.18	903	0.8	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:1	8.18	903	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:43:2	8.18	907	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:2	8.18	907	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	14.96	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:2	9.54	897	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	14.96	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:2	9.54	897	0.8	13.39	102	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.71	14.96	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:2	9.54	888	0.8	13.37	102	197	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.71	14.94	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:2	9.54	878	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.71	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:3	9.54	878	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.7	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:3	9.54	892	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.7	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:3	9.54	895	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:3	9.54	898	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.67	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:3	9.54	898	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.7	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:3	9.54	900	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.7	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:4	9.54	900	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.73	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:4	9.54	904	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:4	9.54	904	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:4	9.54	907	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.68	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:4	9.54	907	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.72	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:4	9.54	913	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:4	9.54	913	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:5	8.18	913	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.71	14.83	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:5	8.18	905	0.8	13.38	103	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.83	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:5	8.18	896	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:5	8.18	896	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:5	8.18	904	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:5	8.18	913	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:6	8.18	923	0.8	13.34	102	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:6	8.18	923	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.7	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:6	8.18	923	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:6	8.18	906	0.8	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.77	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:6	8.18	911	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.79	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:6	8.18	911	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.76	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:6	8.18	911	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.81	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:7	8.18	907	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.74	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:7	8.18	910	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.76	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:7	8.18	910	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.73	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:7	8.18	910	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.76	14.92	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:7	8.18	889	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.73	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:7	8.18	889	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.75	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:8	8.18	904	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:8	8.18	904	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.76	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:8	8.18	907	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.74	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:8	8.18	907	0.8	13.38	103	197	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.79	14.99	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:8	8.18	891	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.76	15	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:8	8.18	891	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.76	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:9	8.18	909	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.76	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:9	8.18	909	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.74	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:43:9	8.18	912	0.8	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.75	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:9	8.18	914	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.75	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:9	6.81	919	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.76	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:9	6.81	919	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:43:9	6.81	919	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:44:0	6.81	914	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:44:0	8.18	900	0.8	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	15.02	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:44:0	8.18	900	0.8	13.38	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.02	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:44:0	8.18	900	0.8	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.02	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:44:0	8.18	887	0.8	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.01	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:0	8.18	884	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:1	9.54	881	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:44:1	9.54	881	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:1	9.54	880	0.81	13.38	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:1	9.54	880	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:1	8.18	893	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:1	8.18	893	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:1	8.18	892	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:2	8.18	892	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:2	9.54	894	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:2	9.54	895	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:2	9.54	890	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.98	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:2	9.54	890	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.97	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:2	9.54	898	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:3	9.54	906	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:3	9.54	891	0.81	13.36	102	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:3	9.54	876	0.81	13.38	103	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.65	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:3	9.54	881	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.63	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:3	8.18	881	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.64	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:3	8.18	887	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.67	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:4	8.18	887	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.64	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:4	8.18	887	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.68	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:4	8.18	895	0.82	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.66	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:4	8.18	895	0.82	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.67	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:4	8.18	888	0.82	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.67	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:4	8.18	888	0.82	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.67	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:4	8.18	894	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.62	14.89	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:5	8.18	894	0.82	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.64	14.89	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:5	8.18	902	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.63	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:5	8.18	910	0.82	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:5	8.18	893	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:5	8.18	893	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:5	8.18	892	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:6	8.18	890	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:6	8.18	886	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:6	9.54	886	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:6	9.54	886	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:6	9.54	871	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:6	9.54	889	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:6	8.18	889	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:7	8.18	889	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:7	8.18	895	0.81	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:7	8.18	895	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:7	8.18	888	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:7	8.18	888	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:7	8.18	895	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.61	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:8	8.18	895	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.58	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:8	10.9	906	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.63	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:8	10.9	906	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.65	14.9	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:8	10.9	876	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:8	10.9	876	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.64	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:8	10.9	889	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.64	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:9	10.9	902	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.59	15.02	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:9	10.9	913	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.59	15.05	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:9	10.9	913	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.61	15.06	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:9	10.9	914	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:9	8.18	914	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.62	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:9	8.18	926	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.68	15.11	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:44:9	8.18	935	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.67	15.12	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:0	8.18	928	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	15.12	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:45:0	9.54	928	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	15.13	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:0	9.54	929	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	15.13	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:0	9.54	930	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:0	9.54	926	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.76	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:0	6.81	926	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:1	6.81	930	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:1	6.81	935	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:1	6.81	935	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:1	6.81	935	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.74	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:1	6.81	934	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.78	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:1	6.81	934	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.73	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:45:1	6.81	933	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.79	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:45:2	6.81	923	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.77	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:45:2	6.81	925	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.8	15.08	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:45:2	6.81	925	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.76	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:2	6.81	910	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.81	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:2	6.81	910	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:2	6.81	910	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.79	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:3	6.81	910	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.78	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:45:3	6.81	910	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.8	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:45:3	6.81	910	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.8	15.14	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:45:3	6.81	910	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.83	15.13	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:45:3	6.81	908	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.81	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:3	6.81	908	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.79	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:4	8.18	914	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.77	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:4	8.18	920	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.76	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:4	8.18	897	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.77	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:4	8.18	897	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.79	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:4	8.18	898	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.76	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:4	8.18	899	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.73	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:4	8.18	910	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.72	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:5	8.18	910	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.7	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:5	8.18	906	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.72	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:5	8.18	903	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.75	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:5	8.18	903	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.78	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:5	8.18	900	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.77	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:6	8.18	907	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.76	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:6	8.18	914	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.72	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:6	8.18	914	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.72	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:6	8.18	899	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.69	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:6	8.18	899	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.7	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:6	8.18	899	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.71	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:6	8.18	899	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:6	8.18	904	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.71	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:7	8.18	909	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:7	8.18	912	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:7	8.18	912	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.77	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:7	8.18	906	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:7	8.18	899	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.79	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:7	6.81	899	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:8	6.81	899	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:8	6.81	908	0.81	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:8	6.81	918	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:8	8.18	888	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:8	8.18	888	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:8	8.18	888	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:9	8.18	892	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:9	8.18	898	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:45:9	8.18	898	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:9	8.18	898	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:9	8.18	898	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:9	8.18	898	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:45:9	8.18	890	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:0	8.18	890	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:0	8.18	890	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:0	8.18	890	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:0	8.18	896	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:0	8.18	896	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:0	8.18	896	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:1	8.18	897	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:1	9.54	897	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:1	9.54	897	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:1	9.54	897	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:1	9.54	892	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:1	9.54	892	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.71	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:1	9.54	900	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.65	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:2	9.54	900	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.71	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:2	9.54	904	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:2	9.54	910	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.74	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:2	9.54	913	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.74	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:2	9.54	915	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.79	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:2	9.54	915	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.74	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:3	9.54	920	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.78	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:3	9.54	926	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.72	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:3	9.54	926	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.74	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:3	9.54	906	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.73	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:3	9.54	906	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.75	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:3	8.18	899	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.73	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:4	8.18	899	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.74	14.85	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:4	8.18	903	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.72	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:4	8.18	903	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.74	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:4	6.81	903	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.72	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:4	6.81	888	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.74	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:4	6.81	918	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.76	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:4	6.81	918	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.77	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:5	8.18	899	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.76	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:5	8.18	899	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.77	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:5	8.18	897	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.77	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:5	8.18	895	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.76	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:5	8.18	915	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.75	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:5	8.18	915	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.72	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:6	8.18	915	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.71	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:6	8.18	894	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.69	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:6	8.18	894	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.72	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:6	8.18	898	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:6	8.18	904	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.7	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:6	8.18	904	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.72	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:6	8.18	906	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:7	8.18	912	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:7	8.18	912	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.7	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:7	8.18	910	0.81	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:7	8.18	907	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.72	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:7	8.18	920	0.81	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.7	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:7	8.18	920	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.73	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:8	8.18	928	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.72	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:8	8.18	928	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.72	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:46:8	9.54	920	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:8	9.54	920	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.7	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:46:8	9.54	919	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.7	14.94	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:8	9.54	919	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	14.95	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:9	8.18	920	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.77	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:9	8.18	922	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.77	14.98	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:9	8.18	936	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	14.98	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:9	8.18	936	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:9	8.18	936	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:9	8.18	927	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:46:9	8.18	923	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:0	8.18	923	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:0	8.18	920	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:0	8.18	916	0.81	13.36	102	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:0	8.18	916	0.81	13.35	102	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.99	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:0	8.18	910	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.99	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:0	8.18	910	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	14.98	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:1	9.54	910	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.98	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:1	9.54	910	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	14.98	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:1	9.54	898	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:1	9.54	907	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:1	8.18	907	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.77	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:1	8.18	907	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.79	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:1	8.18	910	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.74	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:2	8.18	910	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.77	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:2	8.18	916	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.72	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:2	8.18	921	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.74	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:2	8.18	915	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:2	8.18	915	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.72	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:2	6.81	912	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:3	6.81	909	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:3	6.81	916	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:3	6.81	916	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:3	8.18	915	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:3	8.18	914	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:3	8.18	911	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:4	8.18	911	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:4	8.18	911	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.75	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:4	8.18	918	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:4	8.18	919	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.77	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:4	8.18	919	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.77	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:4	8.18	926	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.79	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:4	8.18	933	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.79	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:5	8.18	904	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.79	14.86	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:5	8.18	904	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:5	8.18	908	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.76	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:5	8.18	908	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.75	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:5	8.18	912	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.76	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:5	8.18	912	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.73	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:6	8.18	909	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:6	6.81	922	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:6	6.81	930	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.78	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:6	6.81	930	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:6	6.81	930	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.79	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:6	8.18	919	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:6	8.18	919	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.75	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:7	8.18	928	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:7	8.18	938	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:47:7	8.18	923	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:7	8.18	928	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.78	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:7	8.18	928	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.75	15.1	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:7	8.18	928	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.77	15.11	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:8	9.54	931	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.78	15.12	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:8	9.54	931	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.77	15.12	1.03	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:8	9.54	917	0.81	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.78	15.12	1.03	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:8	9.54	903	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.8	15.12	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:8	9.54	927	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.79	15.13	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:8	9.54	927	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.81	15.14	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:9	9.54	920	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.8	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:9	9.54	913	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.83	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:9	8.18	911	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.81	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:9	8.18	911	0.81	13.37	103	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.81	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:47:9	8.18	918	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.83	15.14	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:9	8.18	925	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15.15	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:47:9	9.54	926	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.13	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:48:0	9.54	926	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.13	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:48:0	9.54	923	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	15.13	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:48:0	9.54	920	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.12	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:48:0	8.18	921	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.11	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:48:0	8.18	921	0.81	13.38	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	15.1	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:48:0	8.18	912	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:1	8.18	902	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:1	8.18	895	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:1	8.18	895	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:1	8.18	895	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:1	8.18	902	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:1	8.18	904	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:1	8.18	904	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:2	8.18	904	0.81	13.38	103	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.82	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:2	8.18	911	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.81	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:2	8.18	914	0.81	13.38	103	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.83	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:2	8.18	917	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.78	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:2	8.18	917	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.79	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:2	8.18	917	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.77	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:3	8.18	917	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.78	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:3	6.81	898	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.8	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:3	6.81	898	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.83	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:3	6.81	904	0.81	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.85	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:3	6.81	904	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.82	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:3	8.18	899	0.81	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:4	8.18	894	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:4	8.18	897	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:4	8.18	897	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.76	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:4	8.18	896	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:4	8.18	895	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.76	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:4	8.18	891	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.77	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:4	8.18	891	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.71	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:5	9.54	900	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.73	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:5	9.54	910	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.7	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:5	9.54	896	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.73	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:5	9.54	896	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.72	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:5	9.54	896	0.81	13.35	103	198	Idle	93.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.75	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:5	8.18	899	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:6	8.18	899	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:6	8.18	908	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:6	8.18	916	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:48:6	8.18	908	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:6	8.18	914	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.74	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:6	8.18	914	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.74	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:6	8.18	914	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.73	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:7	6.81	899	0.81	13.34	103	198	Idle	93.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.72	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:7	6.81	899	0.81	13.36	103	198	Idle	93.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.73	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:7	6.81	908	0.81	13.34	103	198	Idle	93.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.7	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:7	6.81	918	0.81	13.36	103	198	Idle	93.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.72	14.9	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:7	8.18	902	0.81	13.34	103	198	Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.73	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:7	8.18	902	0.81	13.36	103	198	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:8	8.18	900	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:8	8.18	897	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:8	8.18	912	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:8	8.18	912	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:8	8.18	906	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:8	8.18	899	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:9	8.18	899	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:9	8.18	909	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:9	8.18	910	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:9	8.18	911	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:9	8.18	911	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.77	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:9	8.18	922	0.81	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:48:9	8.18	922	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	15.01	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:0	8.18	908	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	14.95	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:0	8.18	895	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:0	8.18	911	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.74	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:0	8.18	911	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.75	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:0	8.18	912	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:0	8.18	912	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:1	8.18	916	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:1	8.18	916	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.74	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:1	8.18	914	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:1	8.18	911	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:1	6.81	903	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:1	6.81	903	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:1	6.81	914	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:2	6.81	924	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:2	6.81	924	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:2	8.18	915	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:2	8.18	908	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:2	8.18	902	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:2	8.18	902	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:3	8.18	898	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:3	8.18	911	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:3	8.18	911	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:3	8.18	911	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:3	8.18	890	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:3	8.18	890	0.81	13.38	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.8	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:4	8.18	890	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:4	8.18	890	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:4	8.18	890	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:4	8.18	890	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:4	8.18	891	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:4	8.18	892	0.81	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:4	8.18	894	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	14.75	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:5	8.18	894	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:5	8.18	898	0.81	13.33	103	198	Idle	93.2	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.73	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:5	8.18	902	0.81	13.36	103	198	Idle	93.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.72	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:49:5	8.18	906	0.81	13.35	103	198	Idle	93.2	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.7	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:5	8.18	911	0.81	13.35	103	198	Idle	93.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.7	14.78	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:5	8.18	896	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.72	14.79	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:6	8.18	896	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	14.8	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:6	8.18	896	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.69	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:6	8.18	899	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.66	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:6	8.18	898	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.66	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:6	8.18	898	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:6	8.18	900	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:6	8.18	902	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:7	8.18	901	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:7	8.18	901	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:7	8.18	901	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:7	9.54	903	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:7	9.54	903	0.81	13.36	103	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:7	9.54	912	0.81	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:8	9.54	912	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:8	9.54	910	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.72	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:8	9.54	910	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:8	9.54	918	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.73	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:8	9.54	927	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:8	8.18	929	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:9	8.18	929	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:9	8.18	932	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:9	8.18	932	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:9	9.54	935	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.74	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:9	9.54	935	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.78	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:49:9	9.54	938	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.78	14.85	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:49:9	9.54	941	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.77	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:0	8.18	918	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.77	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:0	8.18	918	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.78	14.9	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:0	8.18	925	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.78	14.93	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:0	8.18	925	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.79	14.95	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:0	8.18	924	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.82	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:0	8.18	923	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.77	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:1	8.18	923	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.82	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:1	8.18	915	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.77	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:1	9.54	926	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.81	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:1	9.54	926	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.76	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:1	9.54	926	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.81	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:1	9.54	912	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.77	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:1	9.54	927	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.79	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:2	9.54	927	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.76	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:2	9.54	923	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.79	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:2	9.54	919	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.79	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:2	9.54	919	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.8	15.05	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:2	9.54	919	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.76	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:2	9.54	910	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.79	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:3	9.54	902	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.75	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:3	9.54	905	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.78	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:3	8.18	905	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.77	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:3	8.18	905	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.77	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:3	8.18	914	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.75	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:3	8.18	914	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.77	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:4	8.18	910	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:4	8.18	910	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.78	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:4	8.18	902	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:4	8.18	902	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:50:4	8.18	902	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.77	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:4	8.18	902	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.77	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:4	8.18	902	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.77	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:5	8.18	904	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.74	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:5	8.18	905	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.74	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:5	8.18	906	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.74	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:5	8.18	906	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.75	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:5	8.18	912	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.76	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:5	8.18	924	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.75	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:6	8.18	924	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.76	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:6	8.18	924	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.78	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:6	8.18	919	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.74	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:6	6.81	910	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.74	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:6	6.81	900	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.74	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:6	6.81	922	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.73	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:6	6.81	922	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:7	6.81	922	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:7	8.18	901	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:7	8.18	913	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:7	8.18	913	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:7	8.18	913	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:7	8.18	921	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:8	8.18	921	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:8	8.18	914	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:8	8.18	908	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:8	8.18	918	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:8	8.18	918	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:8	8.18	916	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:9	8.18	914	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:9	6.81	925	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:9	6.81	925	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:50:9	6.81	929	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.75	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:9	6.81	929	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	15.03	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:9	8.18	924	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.73	15.02	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:50:9	8.18	918	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.78	15.02	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:0	8.18	910	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.02	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:0	8.18	910	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.78	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:0	9.54	914	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:0	9.54	917	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.76	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:0	9.54	906	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:0	9.54	906	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:1	9.54	908	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	14.97	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:1	8.18	910	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	14.95	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:1	8.18	920	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.92	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:1	8.18	920	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:1	8.18	930	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:1	9.54	941	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:1	9.54	912	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	14.85	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:2	9.54	912	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.84	1.01	5.2	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:2	9.54	912	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.84	1.01	5.2	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:2	8.18	909	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.83	1.01	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:2	8.18	911	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.82	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:2	8.18	911	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.81	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:2	8.18	911	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.8	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:3	9.54	901	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	14.8	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:3	9.54	893	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.79	14.78	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:3	9.54	893	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.78	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:3	9.54	893	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.77	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:51:3	8.18	905	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.74	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:3	8.18	905	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:4	8.18	904	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	14.75	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:4	8.18	902	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.76	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:4	8.18	892	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:4	8.18	892	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.78	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:4	8.18	892	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:4	8.18	891	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.72	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:4	8.18	891	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	14.76	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:5	8.18	878	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.67	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:5	8.18	883	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:5	8.18	883	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:5	8.18	889	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:5	10.9	889	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.68	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:5	10.9	890	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.7	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:6	10.9	880	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.71	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:6	10.9	880	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.71	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:6	9.54	886	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.71	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:6	9.54	893	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.7	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:6	9.54	904	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.71	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:6	9.54	904	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:6	9.54	901	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.66	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:7	9.54	898	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.63	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:7	9.54	905	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.66	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:7	9.54	905	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.63	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:7	9.54	905	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.66	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:7	9.54	914	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:7	9.54	914	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:8	9.54	911	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:8	9.54	909	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.75	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:8	6.81	909	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:8	6.81	909	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.76	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:8	6.81	919	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.73	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:8	8.18	934	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.75	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:9	8.18	934	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.7	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:9	8.18	934	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.73	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:51:9	8.18	915	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:9	8.18	915	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.69	14.85	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:9	6.81	906	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.7	14.85	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:9	6.81	898	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	14.84	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:51:9	6.81	905	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.74	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:0	6.81	905	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.74	14.85	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:0	8.18	888	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.71	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:0	8.18	888	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:0	8.18	898	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:0	8.18	898	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:0	8.18	896	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:1	8.18	895	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:1	8.18	894	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:1	8.18	894	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:1	9.54	894	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.63	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:1	9.54	897	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:1	9.54	897	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:1	9.54	872	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:2	9.54	884	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.67	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:2	9.54	897	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:2	9.54	885	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:2	9.54	885	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.69	15	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:52:2	9.54	885	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.68	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:52:2	8.18	894	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.65	14.99	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:52:3	8.18	894	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.65	14.99	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:52:3	8.18	903	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.62	14.99	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:3	8.18	903	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.63	14.99	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:3	9.54	915	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.65	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:3	9.54	927	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.68	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:3	9.54	900	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.66	15	1.02	5.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:52:4	9.54	900	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.63	15	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:52:4	9.54	900	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.66	15.01	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:52:4	9.54	899	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.61	15	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:52:4	9.54	899	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.65	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:4	9.54	899	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.62	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:4	9.54	899	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:4	8.18	920	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:5	8.18	911	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:5	8.18	911	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:5	8.18	911	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.71	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:5	9.54	915	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.68	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:5	9.54	921	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.69	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:5	9.54	921	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:6	8.18	921	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.72	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:6	8.18	927	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.74	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:6	8.18	931	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.77	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:6	8.18	931	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.72	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:6	8.18	931	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.73	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:6	6.81	920	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.91	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:6	6.81	930	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.93	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:7	6.81	940	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	14.94	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:7	6.81	928	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:7	6.81	928	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:7	6.81	930	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:7	6.81	931	0.82	13.34	103	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:7	6.81	931	0.82	13.35	103	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:8	6.81	940	0.82	13.33	103	197	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:8	6.81	940	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:8	6.81	921	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	14.99	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:8	6.81	921	0.82	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	14.99	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:8	8.18	922	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:8	8.18	922	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.85	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:52:9	8.18	910	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.83	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:9	8.18	910	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.82	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:9	8.18	906	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.83	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:9	8.18	901	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.81	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:9	8.18	913	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.84	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:9	8.18	913	0.82	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:52:9	8.18	903	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:0	8.18	893	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:0	8.18	901	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:0	8.18	909	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:0	8.18	891	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:0	9.54	891	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:0	9.54	891	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:1	9.54	895	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:1	8.18	901	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.77	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:1	8.18	901	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.76	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:1	8.18	903	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.78	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:1	8.18	903	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.72	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:53:1	8.18	905	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.73	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:1	8.18	909	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.7	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:2	8.18	909	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.75	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:2	8.18	906	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.71	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:2	8.18	906	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.75	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:2	8.18	901	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:2	8.18	901	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:2	8.18	886	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:3	8.18	886	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:3	9.54	886	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:3	9.54	908	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:3	9.54	899	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:3	9.54	899	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:3	9.54	899	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:4	8.18	907	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:4	8.18	918	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:4	8.18	918	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:4	8.18	918	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:4	8.18	911	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:4	8.18	918	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.72	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:4	8.18	924	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:5	8.18	924	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:5	9.54	910	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:5	9.54	910	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:5	9.54	914	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:5	9.54	914	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:5	8.18	913	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:6	8.18	913	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:6	8.18	942	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.73	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:6	8.18	942	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.75	14.94	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:6	6.81	905	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.76	14.98	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:6	6.81	910	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.77	15.01	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:6	6.81	914	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.75	15.03	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:6	6.81	914	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.77	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:7	8.18	924	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.75	15.05	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:7	8.18	924	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.79	15.05	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:7	8.18	904	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.79	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:7	8.18	904	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.79	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:7	8.18	908	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.8	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:7	8.18	908	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.8	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:8	8.18	904	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:8	8.18	900	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.79	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:8	8.18	894	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.81	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:8	8.18	894	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.78	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:8	8.18	894	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.8	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:8	8.18	888	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:9	8.18	888	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.75	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:9	9.54	916	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.72	15.03	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:9	9.54	916	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.74	15.04	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:9	9.54	902	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.75	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:9	9.54	904	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.76	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:9	8.18	906	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.75	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:53:9	8.18	910	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.79	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:0	8.18	910	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.74	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:0	8.18	910	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.78	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:0	6.81	900	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.74	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:0	6.81	900	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.74	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:0	6.81	908	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.7	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:54:0	6.81	916	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:1	6.81	907	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:1	6.81	907	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.74	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:1	6.81	914	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.75	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:1	6.81	922	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.77	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:1	9.54	925	0.81	13.31	103	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.76	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:1	9.54	925	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.76	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:1	9.54	924	0.81	13.31	103	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.75	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:2	9.54	924	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.76	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:2	9.54	926	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.75	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:2	9.54	928	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.77	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:2	9.54	927	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.78	14.93	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:2	9.54	927	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.79	14.89	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:2	8.18	926	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.79	14.86	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:3	8.18	925	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.79	14.86	1.01	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:3	8.18	908	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.78	14.84	1.01	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:3	8.18	908	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:3	9.54	914	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:3	9.54	921	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:3	9.54	925	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:4	9.54	925	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.89	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:4	8.18	925	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	14.9	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:4	8.18	925	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	14.94	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:4	8.18	930	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.95	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:4	8.18	934	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	14.96	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:4	8.18	934	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:4	8.18	916	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:5	8.18	916	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	14.98	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:5	8.18	936	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	14.98	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:5	8.18	919	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:5	8.18	919	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:5	8.18	919	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.86	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:54:5	8.18	905	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:6	8.18	905	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.85	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:6	8.18	908	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:6	8.18	911	0.81	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:6	8.18	894	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:6	8.18	894	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:6	8.18	893	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.8	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:6	8.18	892	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:7	8.18	890	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.75	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:7	8.18	890	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.76	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:7	9.54	895	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.75	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:7	9.54	900	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.72	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:7	9.54	894	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.74	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:7	9.54	887	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.75	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:8	8.18	891	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.79	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:8	8.18	891	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.71	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:8	8.18	900	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.76	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:8	8.18	908	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:8	8.18	894	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.71	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:8	8.18	894	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:9	8.18	894	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.72	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:9	8.18	899	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:9	8.18	899	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:9	8.18	906	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:9	8.18	906	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:54:9	8.18	905	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:54:9	8.18	905	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:0	8.18	909	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:0	8.18	909	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.68	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:0	8.18	912	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.65	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:0	8.18	912	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.66	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:0	8.18	921	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.68	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:0	8.18	921	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:1	8.18	912	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:1	8.18	912	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.71	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:1	8.18	916	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.71	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:1	8.18	921	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:1	8.18	922	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:1	8.18	922	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:1	8.18	924	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:2	8.18	926	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:2	8.18	905	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:2	8.18	905	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:2	8.18	919	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.7	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:2	6.81	919	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:2	6.81	919	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.77	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:3	6.81	918	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:3	8.18	933	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.77	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:3	8.18	933	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:3	8.18	914	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.75	15.06	1.03	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:3	8.18	914	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:3	8.18	896	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.73	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:4	8.18	911	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:4	8.18	911	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:4	8.18	922	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:4	8.18	922	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:4	8.18	922	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:4	8.18	903	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:4	8.18	908	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:5	8.18	908	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:5	8.18	910	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:5	8.18	910	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:5	8.18	914	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:5	8.18	914	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:5	8.18	914	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:6	8.18	914	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:6	8.18	923	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:6	8.18	923	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:6	9.54	928	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.8	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:6	9.54	933	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:6	9.54	919	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:6	9.54	919	0.82	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:7	8.18	913	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	14.74	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:7	8.18	907	0.82	13.37	103	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.73	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:7	8.18	907	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	14.73	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:7	8.18	914	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.72	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:7	8.18	914	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	14.71	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:7	8.18	914	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.72	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:8	8.18	914	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	14.73	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:8	8.18	913	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.74	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:8	8.18	913	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	14.75	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:8	9.54	924	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.76	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:8	9.54	924	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	14.77	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:8	9.54	921	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.78	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:55:9	9.54	921	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:9	8.18	915	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:9	8.18	920	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:55:9	8.18	925	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.82	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:55:9	8.18	925	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	14.83	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:55:9	8.18	933	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.83	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:55:9	8.18	933	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.81	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:0	8.18	935	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.79	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:0	8.18	937	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.83	14.85	1.01	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:0	6.81	915	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.85	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:0	6.81	915	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:0	6.81	920	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:0	6.81	925	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.8	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:1	6.81	921	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.8	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:1	6.81	921	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.82	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:1	6.81	926	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.8	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:1	6.81	926	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	14.87	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:1	8.18	913	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	14.87	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:1	8.18	913	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.8	14.88	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:1	8.18	905	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:2	8.18	905	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:2	8.18	913	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.84	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:2	8.18	913	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.81	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:2	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.84	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:2	8.18	908	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:2	8.18	904	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.82	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:3	8.18	904	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:3	8.18	904	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.8	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:3	8.18	927	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:3	8.18	927	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.79	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:3	9.54	906	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.79	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:3	9.54	906	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.8	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:4	9.54	914	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.79	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:4	9.54	914	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.8	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:4	9.54	926	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.75	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:4	9.54	914	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:4	9.54	914	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.75	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:4	9.54	914	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.79	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:4	9.54	921	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.79	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:5	9.54	921	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.8	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:5	9.54	916	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.77	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:5	9.54	912	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.79	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:5	9.54	923	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.75	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:5	9.54	923	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.79	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:5	9.54	922	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.78	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:6	9.54	922	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.8	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:6	8.18	926	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.78	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:6	8.18	926	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.8	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:6	8.18	924	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.79	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:6	8.18	922	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.79	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:6	8.18	931	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.83	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:6	8.18	931	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.8	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:7	8.18	931	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.81	14.83	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:7	8.18	931	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.8	14.83	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:7	6.81	919	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.82	14.83	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:7	6.81	919	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.86	14.84	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:7	6.81	922	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.85	14.84	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:7	6.81	925	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.86	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:56:8	6.81	920	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.86	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:8	6.81	920	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.81	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:8	6.81	921	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.83	14.93	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:8	6.81	922	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.79	14.95	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:8	6.81	916	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.81	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:8	8.18	916	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.76	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:9	8.18	911	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.74	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:56:9	8.18	906	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.73	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:9	8.18	900	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.72	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:9	8.18	900	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.74	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:9	8.18	905	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.8	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:9	8.18	910	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.76	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:56:9	8.18	903	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.81	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:0	8.18	903	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.79	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:0	8.18	903	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:0	8.18	896	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.75	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:0	8.18	904	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.78	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:0	9.54	904	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:0	9.54	904	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.73	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:1	9.54	893	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:1	9.54	893	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:1	8.18	898	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.69	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:1	8.18	903	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.69	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:1	8.18	890	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.69	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:1	8.18	890	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.69	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:1	9.54	898	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.7	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:2	9.54	907	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:2	9.54	907	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.73	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:2	9.54	903	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.71	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:2	9.54	902	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.72	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:2	9.54	902	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.67	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:2	9.54	903	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.67	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:3	9.54	903	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.68	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:3	9.54	903	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.67	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:3	8.18	903	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.7	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:3	8.18	927	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.74	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:3	8.18	927	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.73	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:3	8.18	905	0.82	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.73	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:4	9.54	905	0.82	13.31	103	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:4	9.54	905	0.82	13.31	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:4	9.54	916	0.82	13.31	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.66	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:4	9.54	928	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:4	9.54	928	0.81	13.31	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:4	9.54	928	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.76	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:4	9.54	923	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:5	9.54	923	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.76	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:5	9.54	924	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:5	9.54	924	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.77	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:5	9.54	920	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:5	9.54	920	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.77	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:5	8.18	920	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.77	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:6	8.18	920	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.77	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:6	8.18	924	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.8	14.97	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:6	8.18	927	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.77	14.97	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:6	9.54	940	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.79	14.97	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:6	9.54	940	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.81	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:6	9.54	932	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.8	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:6	9.54	925	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.8	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:57:7	8.18	924	0.81	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.8	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:7	8.18	923	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.82	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:7	8.18	932	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:7	8.18	932	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:7	8.18	926	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.82	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:7	8.18	926	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.8	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:8	8.18	926	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.84	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:8	8.18	921	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.83	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:8	8.18	913	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.84	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:8	8.18	913	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.8	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:8	8.18	913	0.81	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.84	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:57:8	8.18	926	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.79	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:9	8.18	914	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.82	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:9	8.18	914	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.8	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:9	8.18	914	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.82	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:9	8.18	905	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.79	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:9	8.18	905	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.81	14.99	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:9	8.18	911	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.77	14.99	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:57:9	8.18	911	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.82	14.98	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:0	8.18	915	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.76	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:0	8.18	915	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.79	14.96	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:0	6.81	906	0.81	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.77	14.97	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:0	6.81	898	0.81	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.79	14.96	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:0	6.81	902	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.75	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:0	6.81	902	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.79	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:1	8.18	900	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.78	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:1	8.18	899	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.79	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:1	8.18	905	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.76	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:1	8.18	905	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.78	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:1	8.18	896	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.77	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:1	8.18	886	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:1	8.18	886	0.82	13.33	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:2	8.18	886	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:2	8.18	888	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:2	9.54	890	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:2	9.54	893	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:2	9.54	893	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:2	9.54	893	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.73	14.9	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:3	9.54	886	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.91	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:3	9.54	886	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:3	9.54	894	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.66	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:3	9.54	907	0.82	13.36	103	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.68	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:3	9.54	912	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.63	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:3	9.54	912	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.68	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:4	9.54	916	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:4	9.54	916	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.72	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:4	9.54	918	0.81	13.32	103	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.7	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:4	9.54	919	0.81	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.72	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:4	9.54	911	0.81	13.31	103	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.71	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:4	9.54	911	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.69	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:4	9.54	918	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:5	9.54	918	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.71	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:5	9.54	922	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.72	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:5	9.54	922	0.81	13.37	104	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.74	15.06	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:5	9.54	920	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.75	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:5	8.18	917	0.81	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.76	15.08	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:5	8.18	913	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.75	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:6	8.18	913	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.74	15.09	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:58:6	8.18	929	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.76	15.07	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:6	8.18	945	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:6	8.18	904	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.06	1.03	5.2	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:58:6	8.18	904	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:6	8.18	904	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	15.05	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:6	6.81	907	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15.05	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:7	6.81	905	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:7	6.81	905	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:7	6.81	905	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	15.02	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:7	8.18	899	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:7	8.18	900	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:7	8.18	902	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:8	8.18	902	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:8	8.18	896	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:8	8.18	896	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:8	8.18	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.71	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:8	8.18	912	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.73	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:8	8.18	904	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.73	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:9	8.18	904	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.72	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:9	8.18	904	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.72	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:9	8.18	914	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.72	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:9	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.72	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:9	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.7	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:9	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.71	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:58:9	8.18	907	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:0	8.18	911	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:0	8.18	911	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.66	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:0	8.18	911	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.68	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:0	8.18	894	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.65	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:0	8.18	908	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:0	8.18	908	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:1	8.18	908	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.72	14.99	1.02	5.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:1	8.18	882	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.98	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:59:1	8.18	882	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.71	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:59:1	8.18	899	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:59:1	8.18	899	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.91	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:13:59:1	8.18	908	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:1	8.18	908	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:2	8.18	909	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.69	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:2	8.18	909	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:2	8.18	912	0.82	13.34	103	198	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.67	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:2	8.18	912	0.82	13.35	103	198	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.67	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:2	8.18	918	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:2	8.18	918	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:3	8.18	929	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:3	8.18	940	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.72	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:3	9.54	903	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.69	14.88	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:3	9.54	903	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.72	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:3	9.54	912	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:3	9.54	922	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	14.93	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:4	9.54	938	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:4	9.54	938	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:4	9.54	930	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:4	9.54	922	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:4	8.18	935	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.05	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:4	8.18	935	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:4	8.18	940	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:5	8.18	944	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:13:59:5	8.18	940	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:5	8.18	940	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:5	8.18	937	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.77	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:5	8.18	934	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:5	8.18	921	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.83	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:6	8.18	921	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:6	8.18	922	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.82	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:6	8.18	924	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:6	8.18	906	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:6	8.18	906	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:6	8.18	914	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:6	8.18	923	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:7	8.18	923	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.81	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:7	8.18	910	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:7	8.18	916	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:7	8.18	916	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:7	8.18	916	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:7	8.18	926	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:8	8.18	935	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:59:8	8.18	924	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	14.92	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:8	8.18	924	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.84	14.91	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:8	6.81	930	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:8	6.81	924	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.87	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:8	6.81	924	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.8	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:9	6.81	924	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.84	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:9	8.18	939	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	14.84	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:9	8.18	939	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	14.85	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:9	8.18	927	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:9	8.18	927	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:9	8.18	923	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.84	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:13:59:9	8.18	923	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.84	1.01	5.2	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:0	8.18	911	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.84	1.01	5.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:0	8.18	899	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.85	1.01	5.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:0	8.18	894	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.85	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:0	8.18	890	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:0	8.18	912	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:0	8.18	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:1	8.18	900	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:1	8.18	900	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:1	8.18	907	0.82	13.31	104	198	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.83	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:1	8.18	907	0.82	13.34	104	198	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	14.83	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:1	6.81	907	0.82	13.33	104	198	Idle	93.2	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.79	14.83	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:1	6.81	898	0.82	13.34	104	198	Idle	93.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.77	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:1	6.81	918	0.82	13.33	104	198	Idle	93.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.76	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:00:2	6.81	918	0.82	13.34	104	198	Idle	93.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.73	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:2	6.81	904	0.82	13.33	104	198	Idle	93.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.75	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:2	8.18	904	0.82	13.35	104	198	Idle	93.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:2	8.18	890	0.82	13.34	104	198	Idle	93.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.78	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:2	8.18	896	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.74	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:2	8.18	896	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.76	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:3	8.18	900	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.73	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:3	8.18	904	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.73	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:3	8.18	886	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.73	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:3	8.18	886	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.74	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:3	9.54	886	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.72	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:3	9.54	885	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.71	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:4	9.54	882	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.71	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:4	9.54	879	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:00:4	9.54	885	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:4	9.54	885	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:4	9.54	885	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:4	9.54	893	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:4	9.54	893	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.72	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:5	10.9	895	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:5	10.9	898	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.74	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:5	10.9	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.71	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:5	10.9	901	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:5	9.54	907	0.82	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.68	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:5	9.54	907	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:6	9.54	906	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.64	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:6	9.54	905	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:6	6.81	889	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:6	6.81	889	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.71	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:6	6.81	912	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.73	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:6	6.81	912	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.72	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:6	8.18	901	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	14.85	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:7	8.18	890	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:7	8.18	883	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.68	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:7	8.18	883	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:7	8.18	887	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:7	9.54	891	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:7	9.54	877	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:8	9.54	877	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.59	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:8	9.54	877	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.64	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:8	8.18	888	0.81	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:8	8.18	888	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:8	8.18	890	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:8	8.18	892	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:9	8.18	890	0.81	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:9	8.18	890	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:9	8.18	902	0.81	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:9	8.18	902	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:9	8.18	878	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:9	8.18	878	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:00:9	8.18	893	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:0	8.18	893	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:0	8.18	891	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.67	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:0	8.18	889	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:0	8.18	903	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:0	8.18	903	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.65	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:0	8.18	903	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.65	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:1	8.18	888	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:1	8.18	888	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:1	8.18	906	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:1	8.18	906	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:1	8.18	907	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.64	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:1	8.18	908	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:1	8.18	911	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.63	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:2	8.18	911	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:2	8.18	914	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.65	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:2	8.18	918	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:2	8.18	912	0.81	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:2	8.18	912	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:2	8.18	928	0.81	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.71	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:3	8.18	928	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.71	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:3	8.18	908	0.81	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.69	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:01:3	8.18	908	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.71	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:3	8.18	917	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.7	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:3	8.18	917	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.68	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:3	8.18	917	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:4	8.18	916	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.12	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:01:4	6.81	913	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.12	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:01:4	6.81	913	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.13	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:01:4	6.81	913	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.12	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:01:4	6.81	918	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.13	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:4	6.81	904	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:4	8.18	904	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:5	8.18	910	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:5	8.18	917	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:5	8.18	901	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:5	8.18	901	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:5	8.18	901	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:5	8.18	901	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:6	8.18	901	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:6	8.18	909	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:6	8.18	909	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:6	8.18	904	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:6	8.18	904	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:6	8.18	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:6	8.18	901	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:7	8.18	899	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.67	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:7	8.18	899	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:7	8.18	902	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.67	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:7	8.18	902	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.69	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:7	8.18	902	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:7	8.18	902	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:8	8.18	898	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:8	8.18	893	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.67	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:8	8.18	893	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.65	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:8	8.18	894	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.66	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:01:8	8.18	893	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.66	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:01:8	9.54	893	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.68	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:01:9	9.54	894	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.68	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:01:9	9.54	895	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:9	9.54	895	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:9	8.18	901	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:9	8.18	901	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:9	8.18	903	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:01:9	8.18	903	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:0	8.18	910	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:0	8.18	917	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:0	8.18	910	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:0	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:0	8.18	909	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.68	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:0	8.18	908	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.7	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:1	8.18	910	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:1	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.69	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:1	6.81	904	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:1	6.81	899	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:1	6.81	918	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:1	6.81	918	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.66	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:1	8.18	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:2	8.18	907	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.69	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:2	8.18	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:02:2	8.18	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:2	8.18	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:2	8.18	913	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:2	8.18	911	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:3	8.18	911	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:3	8.18	911	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:3	9.54	909	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:3	9.54	909	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:3	9.54	897	0.82	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:3	9.54	897	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:4	9.54	911	0.82	13.31	104	198	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:4	9.54	911	0.82	13.33	104	198	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:4	9.54	923	0.82	13.3	104	198	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:4	9.54	923	0.82	13.33	104	198	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:4	9.54	918	0.82	13.31	104	198	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:4	9.54	918	0.82	13.33	104	198	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:4	9.54	912	0.82	13.32	104	198	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.08	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:5	9.54	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:5	9.54	927	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	15.06	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:5	9.54	927	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.05	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:5	9.54	923	0.82	13.34	104	198	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.05	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:5	9.54	923	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	15.06	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:5	6.81	923	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15.06	1.03	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:6	6.81	910	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.06	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:6	6.81	930	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:6	6.81	930	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:6	8.18	930	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:6	8.18	920	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:6	8.18	907	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:6	8.18	907	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:7	8.18	907	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:7	8.18	898	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	14.91	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:7	8.18	896	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	14.89	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:02:7	8.18	896	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:7	8.18	896	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:7	8.18	893	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:8	8.18	893	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:8	8.18	893	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:8	8.18	893	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:8	8.18	888	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:8	8.18	888	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:8	8.18	886	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:9	8.18	884	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:9	9.54	889	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.71	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:9	9.54	889	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:9	9.54	891	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.69	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:9	9.54	891	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:9	8.18	891	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:02:9	8.18	890	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:0	8.18	890	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:0	8.18	892	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.62	14.73	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:0	9.54	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.67	14.73	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:0	9.54	910	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.64	14.73	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:0	9.54	910	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.73	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:0	9.54	883	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.63	14.72	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:1	9.54	883	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.75	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:1	8.18	888	0.82	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.55	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:1	8.18	893	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.75	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:03:1	8.18	892	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.55	14.74	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:1	8.18	892	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.56	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:1	8.18	892	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:1	8.18	892	0.82	13.37	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:2	8.18	901	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:2	8.18	901	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:2	8.18	899	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:2	8.18	899	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:2	8.18	899	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:2	8.18	900	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:3	9.54	893	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.84	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:3	9.54	893	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:3	9.54	893	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.66	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:3	9.54	896	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.63	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:3	9.54	896	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.66	14.9	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:3	8.18	902	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	14.93	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:4	8.18	909	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:4	8.18	903	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:4	8.18	903	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:4	8.18	904	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:4	8.18	906	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:4	8.18	908	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.67	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:4	8.18	908	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.7	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:5	8.18	908	0.81	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.72	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:5	8.18	908	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.71	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:5	8.18	908	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.71	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:5	8.18	908	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.7	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:5	8.18	913	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.69	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:5	8.18	913	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:6	8.18	914	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.7	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:6	8.18	916	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.13	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:03:6	6.81	910	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	15.12	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:03:6	6.81	910	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.12	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:03:6	6.81	906	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.11	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:03:6	6.81	903	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:6	8.18	903	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:7	8.18	906	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:7	8.18	899	0.81	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:7	8.18	892	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:7	8.18	892	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:7	8.18	901	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:7	8.18	892	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:8	8.18	884	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:8	8.18	884	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.71	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:8	8.18	902	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.69	15.07	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:8	8.18	902	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.72	15.06	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:8	8.18	905	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.69	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:8	8.18	905	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.71	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:9	8.18	889	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.7	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:9	8.18	889	0.81	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.73	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:9	8.18	894	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.7	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:9	8.18	899	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.67	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:9	8.18	891	0.81	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.7	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:9	8.18	891	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:03:9	8.18	898	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:0	8.18	906	0.81	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:0	8.18	893	0.81	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:0	8.18	893	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:04:0	8.18	896	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:0	8.18	900	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:0	8.18	903	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:1	8.18	903	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.68	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:1	8.18	903	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:1	8.18	911	0.81	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.68	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:1	8.18	911	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.66	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:1	8.18	889	0.81	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.67	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:1	8.18	889	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.67	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:1	8.18	892	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.66	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:2	8.18	894	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:2	8.18	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:2	8.18	901	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:2	8.18	901	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.64	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:2	8.18	905	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:04:2	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.65	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:04:3	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:04:3	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.65	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:04:3	8.18	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.63	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:3	8.18	911	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.67	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:3	6.81	912	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.62	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:3	6.81	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.69	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:4	6.81	920	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.66	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:4	6.81	918	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:4	6.81	915	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.64	15.1	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:4	6.81	915	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.69	15.12	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:4	6.81	939	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.65	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:4	6.81	928	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.67	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:4	6.81	918	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.64	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:5	6.81	918	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.72	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:5	6.81	928	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:5	6.81	922	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:5	8.18	917	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:5	8.18	917	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.75	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:5	8.18	911	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:6	8.18	911	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:6	6.81	912	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:6	6.81	920	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:6	6.81	920	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:6	6.81	920	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:6	6.81	897	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:6	6.81	897	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:7	6.81	905	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:7	6.81	913	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:7	8.18	885	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:7	8.18	885	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:7	8.18	890	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:7	8.18	894	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:8	8.18	894	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:8	8.18	872	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:8	8.18	877	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:8	8.18	882	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.63	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:8	8.18	885	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.62	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:8	8.18	885	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.58	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:9	8.18	887	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.58	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:9	8.18	889	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.6	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:9	8.18	889	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.6	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:9	8.18	882	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.6	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:04:9	8.18	882	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.61	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:04:9	8.18	884	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.58	15	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:04:9	8.18	884	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.59	14.99	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:05:0	8.18	895	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.61	14.99	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:05:0	8.18	895	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.62	14.99	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:05:0	8.18	913	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.63	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:0	8.18	913	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.63	14.93	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:0	8.18	912	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.65	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:0	8.18	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.65	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:1	8.18	912	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.68	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:1	8.18	902	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.61	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:1	8.18	902	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.61	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:1	8.18	915	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.61	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:1	8.18	915	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:1	8.18	914	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:1	8.18	914	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:2	8.18	907	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:2	8.18	907	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:2	8.18	902	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:2	8.18	920	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:2	8.18	920	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:2	8.18	920	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:3	8.18	921	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:3	8.18	921	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:3	8.18	905	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:3	8.18	905	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:3	8.18	912	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:3	8.18	912	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:4	8.18	918	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:4	8.18	918	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:4	8.18	915	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:4	8.18	915	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	14.95	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:05:4	9.54	913	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.96	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:05:4	9.54	913	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.97	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:05:4	9.54	913	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:5	9.54	910	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:5	9.54	919	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:5	9.54	919	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:5	9.54	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:05:5	9.54	901	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:05:5	9.54	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.99	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:05:6	8.18	916	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.97	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:05:6	8.18	927	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.75	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:05:6	8.18	927	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.71	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:6	8.18	927	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.75	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:6	8.18	924	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.74	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:6	8.18	923	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.79	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:6	8.18	923	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.74	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:7	8.18	923	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.77	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:7	8.18	910	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.76	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:7	8.18	914	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.79	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:7	8.18	914	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.72	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:7	8.18	914	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.77	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:7	6.81	908	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.75	14.9	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:8	6.81	908	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.76	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:8	6.81	911	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.76	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:8	6.81	911	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.78	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:8	8.18	894	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.74	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:05:8	8.18	894	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.71	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:8	8.18	897	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:9	8.18	900	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.7	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:9	8.18	925	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:9	8.18	925	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:9	8.18	919	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.78	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:9	8.18	913	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.78	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:9	8.18	913	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:05:9	8.18	934	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:0	8.18	920	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	14.84	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:0	8.18	905	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.84	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:0	8.18	908	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:0	8.18	908	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:0	8.18	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:0	8.18	915	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.73	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:1	8.18	923	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.74	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:1	8.18	923	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.93	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:1	8.18	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.68	14.95	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:1	8.18	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.7	14.98	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:1	8.18	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:1	8.18	910	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.72	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:1	8.18	909	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.75	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:2	8.18	908	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.73	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:2	8.18	913	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.77	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:2	6.81	913	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.73	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:2	6.81	913	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.75	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:2	6.81	910	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:2	6.81	910	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:3	8.18	920	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:3	8.18	920	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:3	8.18	925	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.04	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:3	8.18	925	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.05	1.03	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:3	6.81	895	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.06	1.03	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:3	6.81	895	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:4	6.81	921	0.82	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.08	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:4	6.81	921	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.08	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:4	9.54	926	0.82	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:4	9.54	930	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.77	15.1	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:4	9.54	930	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.77	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:4	9.54	912	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:4	8.18	912	0.82	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	15.07	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:5	8.18	911	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.07	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:5	8.18	929	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.05	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:5	8.18	929	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:5	9.54	920	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:5	9.54	920	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15.01	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:5	9.54	920	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	15	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:6	9.54	904	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:6	9.54	917	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:6	9.54	917	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.02	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:6	9.54	917	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:6	9.54	907	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:6	9.54	907	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:6	9.54	906	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:7	9.54	904	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:7	9.54	899	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:7	9.54	899	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:7	8.18	897	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:06:7	8.18	897	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.91	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:06:7	8.18	904	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.66	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:8	8.18	904	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.66	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:8	8.18	896	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.66	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:8	8.18	887	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:8	8.18	887	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:8	8.18	894	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:8	8.18	894	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:9	8.18	893	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.68	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:9	8.18	893	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:9	8.18	891	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:9	8.18	895	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:9	9.54	895	0.82	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:9	9.54	899	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:06:9	9.54	877	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:0	9.54	890	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:0	8.18	890	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:0	8.18	890	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:0	8.18	888	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:0	8.18	888	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:0	9.54	892	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:1	9.54	897	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:1	9.54	897	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:1	9.54	880	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:1	8.18	891	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:1	8.18	902	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:1	8.18	902	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:1	8.18	900	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:2	8.18	902	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:2	8.18	905	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:2	8.18	905	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.64	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:2	8.18	901	0.82	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:2	8.18	901	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:2	8.18	909	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.64	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:3	8.18	917	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:3	8.18	910	0.82	13.3	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.63	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:3	8.18	929	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:3	8.18	929	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:3	8.18	926	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:3	8.18	924	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.67	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:4	8.18	924	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:4	8.18	903	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:4	8.18	903	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:4	8.18	914	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:4	8.18	914	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.68	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:4	8.18	918	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:4	8.18	918	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:5	8.18	922	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:5	8.18	922	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.69	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:5	8.18	919	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.73	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:5	8.18	919	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.7	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:5	8.18	916	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.73	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:5	8.18	913	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.7	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:6	8.18	934	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.72	15.1	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:6	8.18	934	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.1	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:6	8.18	934	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15.1	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:6	8.18	926	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:6	6.81	914	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:07:6	6.81	914	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:6	6.81	919	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:7	6.81	924	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:7	6.81	912	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:7	6.81	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:7	6.81	916	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:7	6.81	919	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:7	6.81	897	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:8	8.18	897	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:8	8.18	897	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:8	8.18	913	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:8	8.18	913	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.05	1.03	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:8	9.54	910	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.04	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:8	9.54	906	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.04	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:9	9.54	897	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:9	9.54	897	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:9	8.18	904	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:9	8.18	912	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:9	8.18	918	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:9	8.18	924	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:07:9	8.18	914	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:0	8.18	914	0.82	13.35	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:0	8.18	918	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:08:0	8.18	921	0.82	13.36	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:08:0	8.18	914	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	14.98	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:08:0	8.18	914	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:08:0	8.18	922	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:1	8.18	931	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:1	9.54	922	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:1	9.54	922	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:1	9.54	915	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:08:1	9.54	908	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:08:1	9.54	921	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	14.88	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:08:1	8.18	921	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:08:2	8.18	912	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	14.88	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:08:2	8.18	902	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:2	8.18	902	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:2	9.54	909	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:2	9.54	909	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:2	9.54	901	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.73	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:3	9.54	901	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.76	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:3	8.18	894	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:3	8.18	894	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	14.86	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:3	8.18	892	0.82	13.34	104	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	14.86	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:3	8.18	892	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:3	8.18	883	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:4	8.18	883	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:4	8.18	896	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:4	8.18	896	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:4	8.18	884	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.86	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:4	8.18	884	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:4	8.18	873	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:4	8.18	881	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:5	8.18	873	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:5	9.54	873	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.6	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:5	9.54	873	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.62	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:5	9.54	883	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.6	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:5	9.54	884	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:08:5	9.54	884	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:6	9.54	884	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.66	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:6	9.54	887	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.65	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:6	9.54	887	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.64	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:6	8.18	893	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.62	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:6	8.18	893	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.61	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:6	8.18	894	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.62	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:6	8.18	894	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.62	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:7	8.18	889	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:7	8.18	889	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:7	8.18	889	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:7	8.18	892	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:7	8.18	905	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.63	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:7	8.18	905	0.82	13.33	104	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.61	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:8	8.18	905	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.62	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:8	8.18	894	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:8	8.18	895	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:8	8.18	895	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:8	8.18	895	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.61	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:8	8.18	895	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:9	8.18	895	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:9	8.18	894	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.59	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:9	8.18	894	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.64	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:9	8.18	917	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.62	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:9	8.18	917	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.66	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:9	8.18	906	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.65	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:08:9	8.18	895	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.64	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:0	8.18	904	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.67	14.83	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:0	8.18	904	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.67	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:0	8.18	910	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:0	8.18	915	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.67	14.88	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:0	8.18	904	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.72	14.9	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:0	8.18	904	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	14.92	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:1	8.18	910	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:1	8.18	916	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:1	8.18	916	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:1	8.18	912	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.05	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:1	8.18	912	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:1	8.18	938	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.07	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:1	8.18	938	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.07	1.03	5.2	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:2	8.18	907	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.08	1.03	5.2	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:2	8.18	907	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.1	1.03	5.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:2	8.18	893	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.09	1.03	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:2	8.18	879	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:2	8.18	892	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:2	8.18	892	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:3	8.18	890	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:3	8.18	889	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.05	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:09:3	8.18	889	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:3	8.18	889	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:3	8.18	889	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:3	8.18	889	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.64	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:4	8.18	889	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.63	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:4	8.18	895	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.61	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:4	8.18	886	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.61	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:4	8.18	886	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.63	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:4	8.18	886	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.67	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:4	8.18	889	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.68	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:09:4	8.18	882	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.68	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:5	8.18	875	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.62	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:5	8.18	875	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:5	8.18	866	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:5	8.18	866	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:5	8.18	866	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:5	8.18	888	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.92	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:6	8.18	882	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.65	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:6	8.18	882	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:6	8.18	882	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.65	14.9	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:6	8.18	896	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.6	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:6	8.18	882	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.61	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:6	8.18	867	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.55	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:6	8.18	867	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.59	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:7	8.18	878	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.57	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:7	8.18	883	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.61	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:09:7	8.18	883	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:7	8.18	883	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:7	6.81	892	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.56	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:7	6.81	892	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.54	14.85	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:8	6.81	887	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.54	14.87	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:8	6.81	887	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.54	14.87	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:8	6.81	887	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.57	14.89	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:8	6.81	882	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.55	14.91	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:8	6.81	887	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.56	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:8	6.81	887	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.54	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:9	6.81	887	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.55	15.01	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:9	8.18	892	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.55	15.04	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:9	8.18	892	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.56	15.07	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:9	8.18	887	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.54	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:9	8.18	887	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.58	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:9	8.18	895	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.55	15.17	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:09:9	8.18	903	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.59	15.19	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:10:0	8.18	903	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.58	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:0	8.18	903	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.6	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:0	8.18	913	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.61	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:0	8.18	913	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.64	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:0	8.18	904	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.64	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:0	8.18	896	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.63	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:1	8.18	919	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.63	15.25	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:1	8.18	919	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.63	15.24	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:1	8.18	918	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.65	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:1	8.18	918	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.6	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:1	8.18	920	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.64	15.21	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:1	8.18	921	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.63	15.19	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:1	8.18	918	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.65	15.18	1.03	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:2	8.18	914	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.66	15.16	1.03	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:2	8.18	922	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.65	15.15	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:2	8.18	922	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.66	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:2	8.18	926	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:2	8.18	930	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	15.12	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:2	8.18	908	0.82	13.31	105	198	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	15.1	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:3	6.81	908	0.82	13.32	105	198	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:3	6.81	908	0.82	13.31	104	198	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:3	6.81	920	0.82	13.33	104	198	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:3	6.81	918	0.82	13.32	104	198	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:3	8.18	915	0.82	13.33	105	198	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:3	8.18	919	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:10:4	8.18	919	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:4	8.18	916	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:4	6.81	913	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:4	6.81	913	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:4	6.81	932	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:4	6.81	928	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:4	8.18	923	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.9	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:5	8.18	923	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.88	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:5	8.18	904	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.88	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:10:5	8.18	904	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	14.89	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:10:5	6.81	907	0.82	13.32	104	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.88	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:10:5	6.81	907	0.82	13.31	104	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	14.89	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:10:5	6.81	920	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.71	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:6	6.81	920	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.73	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:6	9.54	908	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:6	9.54	895	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.73	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:6	9.54	898	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:6	9.54	898	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.71	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:6	9.54	899	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.73	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:6	9.54	900	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.75	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:7	9.54	909	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.75	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:7	9.54	909	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.74	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:7	9.54	909	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.73	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:7	9.54	917	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:7	9.54	913	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:7	9.54	913	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:8	9.54	913	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:8	6.81	920	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:8	6.81	925	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:8	6.81	925	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:8	6.81	925	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:8	6.81	926	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:9	6.81	941	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.79	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:9	6.81	941	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.74	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:9	6.81	941	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.8	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:9	6.81	928	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.77	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:9	6.81	928	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.83	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:10:9	6.81	928	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.77	14.83	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:10:9	6.81	926	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.79	14.83	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:0	6.81	923	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.78	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:0	6.81	923	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.79	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:0	6.81	928	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:0	6.81	920	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.81	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:0	6.81	920	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.81	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:0	6.81	913	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.83	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:1	6.81	932	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:1	6.81	932	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:1	9.54	915	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:1	9.54	915	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:1	9.54	904	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:1	9.54	904	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:1	9.54	901	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:2	9.54	901	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:2	9.54	908	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:2	9.54	908	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:2	9.54	908	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:2	9.54	908	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:2	9.54	905	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:11:3	9.54	905	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:3	9.54	910	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:3	9.54	914	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:3	9.54	914	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:3	9.54	913	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:3	9.54	925	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:4	6.81	925	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:4	6.81	927	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:4	6.81	927	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:4	6.81	927	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	15.01	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:4	8.18	903	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	15	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:4	8.18	902	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	14.99	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:11:4	8.18	902	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:5	8.18	902	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.78	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:5	6.81	883	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.74	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:5	6.81	908	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.75	14.89	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:5	6.81	908	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.71	14.89	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:5	6.81	908	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.73	14.88	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:5	8.18	909	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:6	8.18	909	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.73	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:6	8.18	910	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:6	8.18	910	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:6	8.18	902	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:6	8.18	902	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.68	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:6	8.18	906	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.68	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:6	8.18	909	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:7	8.18	906	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:7	8.18	906	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:7	8.18	896	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.71	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:7	8.18	886	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.7	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:7	8.18	886	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:7	9.54	896	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:8	9.54	884	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.68	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:8	9.54	884	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:8	9.54	884	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:8	8.18	887	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:8	8.18	887	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:8	8.18	887	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.66	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:9	8.18	887	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.63	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:9	8.18	891	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:9	8.18	891	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:9	8.18	892	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.65	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:9	8.18	892	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:9	8.18	894	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:11:9	8.18	894	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:0	8.18	888	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:0	8.18	888	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.94	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:12:0	9.54	889	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:12:0	9.54	890	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:12:0	9.54	890	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:12:0	9.54	894	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:1	9.54	895	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.97	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:1	9.54	895	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:1	9.54	896	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:1	9.54	896	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:1	9.54	901	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:1	10.9	919	0.82	13.29	105	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:1	10.9	923	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.66	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:12:2	10.9	923	0.82	13.29	105	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:2	10.9	923	0.82	13.29	105	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:2	8.18	919	0.82	13.29	105	199	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.68	15.05	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:2	8.18	919	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.68	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:2	8.18	922	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.66	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:2	8.18	925	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.65	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:3	9.54	936	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.66	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:3	9.54	936	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.7	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:3	9.54	930	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	15.1	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:12:3	9.54	930	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.7	15.11	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:12:3	6.81	908	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.72	15.12	1.03	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:12:3	6.81	908	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	15.12	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:12:4	6.81	919	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	15.12	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:12:4	6.81	919	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	15.13	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:12:4	8.18	915	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.13	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:12:4	8.18	915	0.82	13.35	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	15.13	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:12:4	8.18	913	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.13	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:12:4	8.18	913	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:4	8.18	913	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:5	8.18	913	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:5	8.18	913	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:5	8.18	906	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:5	8.18	906	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:5	6.81	913	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:5	6.81	913	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:6	6.81	902	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:6	6.81	902	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:6	8.18	902	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.77	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:6	8.18	911	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.76	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:6	8.18	911	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.73	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:6	8.18	911	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:6	8.18	900	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.71	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:7	8.18	900	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:7	8.18	902	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.69	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:7	8.18	905	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.67	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:7	8.18	897	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.72	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:7	8.18	897	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.73	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:7	8.18	902	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.76	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:8	8.18	906	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:8	8.18	895	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.72	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:8	8.18	895	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:8	8.18	899	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:8	8.18	903	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:8	8.18	910	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:9	8.18	910	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:9	8.18	910	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:9	8.18	897	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:9	8.18	910	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:9	8.18	910	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:9	8.18	910	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.71	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:12:9	8.18	914	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.7	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:0	8.18	918	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.71	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:0	8.18	918	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:0	8.18	915	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.7	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:0	8.18	915	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.68	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:0	8.18	915	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:0	9.54	926	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:1	9.54	926	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.74	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:13:1	9.54	943	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:1	9.54	943	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.76	14.87	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:1	8.18	909	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.77	14.89	1.01	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:1	8.18	909	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	14.94	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:1	8.18	928	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:1	8.18	928	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:2	8.18	911	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:2	8.18	911	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:2	8.18	915	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:2	8.18	919	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.05	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:2	9.54	905	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.07	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:2	9.54	905	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	15.07	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:3	9.54	902	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:3	9.54	900	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:3	9.54	916	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.05	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:3	9.54	916	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.05	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:3	9.54	916	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:3	9.54	903	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:4	9.54	902	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15.02	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:4	8.18	900	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.76	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:4	8.18	904	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.76	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:13:4	8.18	904	0.82	13.29	105	198	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.74	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:4	8.18	904	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.75	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:4	6.81	903	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:4	6.81	903	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.71	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:5	6.81	902	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:5	6.81	900	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.74	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:5	8.18	896	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.72	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:5	8.18	892	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:5	8.18	892	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:5	8.18	880	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:6	9.54	907	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:6	9.54	907	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:6	9.54	907	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.93	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:6	9.54	875	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:6	9.54	898	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:6	9.54	898	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:6	9.54	900	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.68	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:7	9.54	903	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:7	9.54	903	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:7	9.54	910	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:7	9.54	910	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.66	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:7	9.54	908	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:7	9.54	905	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.66	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:8	9.54	924	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.66	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:8	9.54	924	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:8	9.54	923	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:8	9.54	923	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.84	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:8	8.18	910	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:8	8.18	910	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:9	8.18	922	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:9	8.18	934	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.68	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:9	8.18	917	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.67	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:9	8.18	917	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:9	8.18	916	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:9	8.18	916	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:13:9	6.81	915	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.68	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:0	6.81	915	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.69	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:14:0	6.81	922	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.67	15.12	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:0	6.81	922	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:0	8.18	928	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.67	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:0	8.18	933	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.16	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:0	8.18	905	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.16	1.03	5.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:1	8.18	905	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.16	1.03	5.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:1	8.18	891	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.17	1.03	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:1	8.18	891	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	15.17	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:1	8.18	900	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:1	8.18	908	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.7	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:1	8.18	901	0.83	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.19	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:1	8.18	901	0.83	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.19	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:2	8.18	901	0.83	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	15.19	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:2	8.18	903	0.83	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:2	8.18	917	0.83	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:2	8.18	917	0.83	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.66	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:2	8.18	917	0.83	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:2	8.18	916	0.83	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:3	8.18	916	0.83	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.14	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:3	8.18	886	0.83	13.29	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:3	8.18	886	0.83	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:3	8.18	898	0.83	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:3	8.18	898	0.83	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:3	8.18	898	0.83	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:4	8.18	899	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:4	8.18	899	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:4	8.18	899	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:4	9.54	902	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:4	9.54	906	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:4	9.54	906	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:4	9.54	909	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:5	9.54	918	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:5	9.54	918	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:5	9.54	918	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:5	9.54	916	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:5	9.54	922	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:6	9.54	928	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:6	9.54	928	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:6	9.54	916	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	14.87	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:14:6	9.54	917	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:14:6	9.54	918	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.88	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:14:6	9.54	918	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	14.88	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:14:6	9.54	914	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:6	9.54	912	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:7	9.54	912	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:7	9.54	912	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:7	9.54	930	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:7	9.54	930	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.72	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:7	8.18	932	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.7	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:7	8.18	934	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.74	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:8	8.18	926	0.82	13.29	105	199	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.71	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:14:8	8.18	926	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.77	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:14:8	8.18	918	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.76	14.87	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:14:8	8.18	910	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.78	14.87	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:14:8	8.18	896	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.74	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:8	8.18	896	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.75	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:9	9.54	905	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.76	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:9	9.54	905	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.71	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:14:9	9.54	905	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.72	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:9	9.54	893	0.82	13.35	105	199	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.72	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:9	9.54	898	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.75	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:9	6.81	898	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.73	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:14:9	6.81	913	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.76	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:0	6.81	913	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.75	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:0	8.18	910	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:0	8.18	907	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:0	8.18	907	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:0	8.18	909	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:0	8.18	909	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:1	8.18	919	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:1	8.18	919	0.82	13.31	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.73	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:1	8.18	917	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:1	8.18	917	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:1	8.18	923	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:1	8.18	924	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:1	8.18	924	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:2	8.18	924	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:2	8.18	925	0.82	13.28	105	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:2	8.18	925	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	14.94	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:2	8.18	919	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.96	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:2	8.18	913	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:2	6.81	916	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:3	6.81	916	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:3	6.81	939	0.82	13.29	105	199	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.76	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:15:3	6.81	939	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.78	15.04	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:15:3	8.18	915	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.77	15.05	1.03	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:15:3	8.18	915	0.82	13.32	105	198	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.77	15.05	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:15:3	8.18	921	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.77	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:4	8.18	921	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.75	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:4	6.81	908	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.77	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:4	6.81	908	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.77	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:4	6.81	933	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:4	6.81	933	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:4	8.18	933	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:4	8.18	914	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:5	8.18	905	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:5	8.18	905	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:5	8.18	905	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:5	9.54	925	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:5	9.54	902	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:5	9.54	902	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.75	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:6	9.54	902	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.77	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:6	9.54	903	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:6	9.54	903	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.74	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:6	9.54	902	0.82	13.33	105	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:6	9.54	900	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:6	9.54	899	0.82	13.3	105	198	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:6	9.54	899	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:7	9.54	896	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:7	9.54	892	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.7	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:7	8.18	896	0.82	13.28	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:7	8.18	896	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:7	8.18	900	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:7	8.18	903	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:8	9.54	892	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:8	9.54	892	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:15:8	9.54	893	0.82	13.29	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.99	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:8	9.54	894	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.98	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:8	8.18	908	0.82	13.3	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:8	8.18	908	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:9	8.18	910	0.82	13.31	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:9	8.18	911	0.82	13.32	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:9	8.18	901	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:9	8.18	901	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:9	8.18	900	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:9	8.18	899	0.82	13.37	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:15:9	8.18	899	0.82	13.36	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:0	8.18	914	0.82	13.36	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:0	8.18	908	0.82	13.36	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:0	8.18	903	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:0	8.18	903	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:0	8.18	898	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:0	8.18	898	0.82	13.35	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:1	8.18	906	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:1	8.18	906	0.82	13.35	105	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:1	8.18	909	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:1	8.18	909	0.82	13.37	105	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:1	8.18	909	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.63	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:1	8.18	891	0.82	13.37	105	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:1	8.18	893	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.63	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:2	8.18	893	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:2	8.18	893	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:2	8.18	900	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.62	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:2	8.18	888	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	14.85	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:2	8.18	888	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.59	14.85	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:2	8.18	888	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.6	14.86	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:3	8.18	879	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.58	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:3	8.18	887	0.82	13.38	105	199	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.61	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:3	8.18	887	0.82	13.35	105	199	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.58	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:3	8.18	887	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.62	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:3	8.18	879	0.82	13.35	105	199	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.59	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:3	8.18	879	0.82	13.35	105	199	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.59	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:4	8.18	885	0.82	13.33	105	199	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.58	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:4	8.18	891	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.58	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:4	8.18	870	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.58	14.86	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:4	8.18	870	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.58	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:4	9.54	883	0.82	13.34	105	199	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.57	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:4	9.54	883	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.56	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:4	9.54	883	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.56	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:5	9.54	907	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.56	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:5	9.54	897	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.58	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:5	8.18	887	0.82	13.37	105	199	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.57	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:5	8.18	887	0.82	13.36	105	199	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.56	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:5	8.18	899	0.82	13.37	105	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.55	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:5	8.18	912	0.82	13.36	105	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.56	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:6	8.18	924	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.55	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:6	8.18	924	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.59	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:6	8.18	913	0.82	13.34	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:6	8.18	913	0.82	13.35	105	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:6	8.18	908	0.82	13.33	105	198	Full Load	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:6	8.18	903	0.82	13.37	105	198	Off Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:6	8.18	912	0.82	13.35	105	199	Off Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.68	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:7	8.18	912	0.84	13.37	105	199	Off Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.59	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:7	8.18	916	0.85	13.35	105	199	Off Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.51	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:16:7	8.18	921	0.87	13.36	105	199	Off Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.4	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:7	8.18	918	0.89	13.34	105	199	Off Idle	92.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.36	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:7	8.18	918	0.92	13.38	105	199	Off Idle	92.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.16	14.93	1.02	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:16:7	9.54	926	0.94	13.35	105	199	Off Idle	91.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.11	14.94	1.02	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:16:8	9.54	933	0.98	13.37	105	199	Off Idle	90.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.87	14.96	1.02	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:16:8	9.54	922	1.01	13.35	105	198	Off Idle	90	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.72	14.98	1.02	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:16:8	9.54	912	1.04	13.36	105	198	Off Idle	89.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.53	15	1.02	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:16:8	9.54	934	1.08	13.36	105	198	Off Idle	88.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.35	15	1.02	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:16:8	9.54	934	1.11	13.37	105	198	Off Idle	88.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.11	15.02	1.02	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:16:8	9.54	937	1.17	13.35	105	199	Off Idle	87.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.79	15.03	1.02	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:16:9	9.54	940	1.2	13.38	105	199	Off Idle	87.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.6	15.04	1.02	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:16:9	8.18	940	1.26	13.36	105	199	Off Idle	86.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.3	15.06	1.03	4.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:16:9	8.18	950	1.31	13.38	105	199	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.15	15.07	1.03	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:16:9	8.18	988	1.35	13.36	105	199	Off Idle	85.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.93	15.08	1.03	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:9	8.18	988	1.39	13.39	105	199	Off Idle	85.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.77	15.11	1.03	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:9	19.09	1086	1.45	13.35	105	199	Off Idle	85.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.44	15.12	1.03	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:16:9	19.09	1086	1.48	13.37	106	199	Off Idle	85.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.31	15.13	1.03	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:17:0	19.09	1053	1.53	13.38	106	199	Off Idle	85.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.06	15.16	1.03	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:0	19.09	1087	1.55	13.39	105	199	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.98	15.19	1.03	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:0	20.45	1087	1.58	13.4	105	199	Off Idle	85.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.89	15.2	1.04	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:0	20.45	1100	1.6	13.38	105	199	Off Idle	85.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.83	15.21	1.04	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:0	20.45	1128	1.62	13.41	105	199	Off Idle	85.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.73	15.21	1.04	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:0	20.45	1144	1.64	13.38	105	199	Off Idle	85.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.69	15.22	1.04	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:1	20.45	1182	1.66	13.4	105	198	Off Idle	85.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.62	15.19	1.04	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:1	20.45	1182	1.67	13.38	105	198	Off Idle	85.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-3.52	15.18	1.03	4.3	4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:1	20.45	1176	1.68	13.38	105	198	Off Idle	85.9	0	2	132	944 Turbo	0.61	Lean	1	14.6	-3.46	15.17	1.03	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:1	20.45	1202	1.69	13.37	105	199	Off Idle	86	0	2	132	944 Turbo	0.68	Lean	1	14.6	-3.35	15.16	1.03	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:1	20.45	1202	1.71	13.39	105	199	Off Idle	86	0	2	132	944 Turbo	0.76	Lean	1	14.6	-3.21	15.13	1.03	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:17:1	21.81	1210	1.72	13.38	105	199	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.16	15.13	1.03	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:17:1	21.81	1234	1.74	13.38	105	199	Off Idle	86.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.1	15.12	1.03	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:17:2	21.81	1251	1.76	13.39	105	199	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.93	15.11	1.03	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:2	21.81	1258	1.78	13.39	105	199	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.89	15.14	1.03	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:2	21.81	1265	1.8	13.39	105	199	Off Idle	86.3	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.65	15.13	1.03	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:2	21.81	1297	1.82	13.39	105	199	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.46	15.1	1.03	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:2	21.81	1344	1.84	13.37	105	199	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.31	15.05	1.03	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:2	21.81	1344	1.85	13.38	105	199	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2.16	14.92	1.02	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:3	21.81	1376	1.87	13.38	105	199	Off Idle	86.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2.1	14.79	1.01	4.1	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:17:3	21.81	1376	1.88	13.38	105	199	Off Idle	86.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2.02	14.53	0.99	4.1	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:17:3	21.81	1429	1.9	13.38	105	199	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.98	14.33	0.98	4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:3	21.81	1443	1.91	13.36	105	199	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.92	14.13	0.96	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:3	21.81	1443	1.93	13.38	105	199	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.96	13.74	0.94	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:3	21.81	1468	1.95	13.38	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.91	13.49	0.92	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:4	25.9	1493	1.97	13.38	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.9	13.27	0.9	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:4	25.9	1467	1.98	13.38	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.96	13.05	0.89	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:4	25.9	1467	2.01	13.38	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2.01	12.8	0.87	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:17:4	25.9	1472	2.02	13.41	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.99	12.67	0.86	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:17:4	25.9	1470	2.03	13.38	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.97	12.67	0.86	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:17:4	25.9	1462	2.04	13.37	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2.02	12.62	0.86	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:17:4	25.9	1462	2.04	13.37	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2.03	12.58	0.86	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:17:5	25.9	1454	2.05	13.37	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-2	12.59	0.86	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:17:5	25.9	1455	2.05	13.35	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.93	12.6	0.86	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:17:5	25.9	1443	2.06	13.35	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.9	12.62	0.86	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:5	24.54	1418	2.06	13.35	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.9	12.65	0.86	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:5	24.54	1406	2.06	13.36	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.86	12.68	0.86	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:5	24.54	1405	2.06	13.35	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.8	12.7	0.86	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:6	25.9	1400	2.06	13.35	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.83	12.73	0.87	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:6	25.9	1394	2.06	13.37	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.83	12.75	0.87	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:6	25.9	1391	2.06	13.37	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.85	12.75	0.87	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:17:6	25.9	1386	2.06	13.36	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.84	12.76	0.87	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:6	25.9	1378	2.06	13.36	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.86	12.77	0.87	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:6	25.9	1372	2.06	13.37	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.81	12.8	0.87	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:6	25.9	1372	2.06	13.36	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.73	12.83	0.87	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:7	25.9	1366	2.05	13.36	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.69	12.87	0.88	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:7	25.9	1349	2.05	13.36	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.64	12.91	0.88	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:7	25.9	1349	2.05	13.38	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.64	12.91	0.88	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:7	25.9	1355	2.05	13.39	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.65	12.96	0.88	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:7	25.9	1350	2.05	13.38	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.61	13	0.89	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:7	25.9	1341	2.05	13.38	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.61	13.04	0.89	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:17:8	25.9	1341	2.04	13.37	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.6	13.09	0.89	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:8	25.9	1328	2.04	13.38	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.56	13.11	0.89	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:8	25.9	1315	2.04	13.38	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.55	13.11	0.89	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:8	25.9	1283	2.04	13.37	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.55	13.12	0.89	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:8	24.54	1283	2.03	13.37	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.5	13.13	0.89	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:8	24.54	1284	2.03	13.36	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.52	13.12	0.89	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:17:9	24.54	1286	2.03	13.37	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.48	13.1	0.89	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:9	24.54	1268	2.02	13.34	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.42	13.06	0.89	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:9	24.54	1262	2.02	13.35	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.41	13.01	0.89	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:9	24.54	1255	2.02	13.35	105	199	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.39	12.95	0.88	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:9	24.54	1240	2.01	13.35	105	199	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.32	12.9	0.88	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:9	24.54	1226	2.01	13.37	105	199	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.37	12.85	0.88	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:17:9	24.54	1226	2.01	13.37	105	199	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.31	12.81	0.87	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:0	24.54	1201	2	13.37	105	199	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.33	12.76	0.87	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:0	24.54	1199	1.99	13.38	105	199	Off Idle	86.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.3	12.68	0.86	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:0	24.54	1199	1.99	13.36	105	199	Off Idle	86.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.25	12.65	0.86	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:0	24.54	1186	1.98	13.38	105	199	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.23	12.62	0.86	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:0	24.54	1184	1.97	13.39	105	199	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.21	12.57	0.86	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:0	24.54	1184	1.97	13.38	105	199	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.21	12.53	0.85	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:1	24.54	1174	1.97	13.38	105	199	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.22	12.51	0.85	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:1	24.54	1174	1.96	13.38	105	199	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.15	12.49	0.85	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:1	24.54	1152	1.96	13.36	105	199	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.16	12.47	0.85	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:1	24.54	1150	1.95	13.36	105	199	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.14	12.45	0.85	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:1	23.18	1147	1.95	13.35	105	199	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.1	12.43	0.85	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:1	23.18	1147	1.94	13.35	105	199	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.09	12.4	0.84	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:1	23.18	1135	1.93	13.35	105	199	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.08	12.38	0.84	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:2	23.18	1119	1.93	13.35	105	199	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.08	12.36	0.84	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:2	23.18	1114	1.92	13.38	105	199	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.09	12.36	0.84	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:2	23.18	1114	1.91	13.35	105	199	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.08	12.36	0.84	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:2	23.18	1109	1.91	13.36	105	199	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.07	12.33	0.84	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:2	23.18	1104	1.91	13.35	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.03	12.31	0.84	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:2	23.18	1093	1.9	13.35	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.02	12.3	0.84	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:3	23.18	1093	1.89	13.37	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.98	12.29	0.84	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:3	23.18	1081	1.89	13.35	105	199	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1	12.28	0.84	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:3	23.18	1076	1.89	13.39	105	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.99	12.27	0.84	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:3	23.18	1076	1.88	13.37	105	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.96	12.25	0.83	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:3	23.18	1081	1.88	13.39	106	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.02	12.24	0.83	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:3	23.18	1086	1.88	13.37	106	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.95	12.21	0.83	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:4	23.18	1094	1.87	13.37	106	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.01	12.18	0.83	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:4	23.18	1109	1.87	13.37	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.03	12.18	0.83	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:4	23.18	1109	1.87	13.37	106	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.03	12.17	0.83	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:4	23.18	1126	1.86	13.38	105	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.05	12.14	0.83	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:4	23.18	1144	1.87	13.38	105	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.01	12.13	0.83	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:4	21.81	1159	1.87	13.39	105	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.04	12.12	0.83	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:4	21.81	1159	1.87	13.4	106	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.98	12.11	0.82	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:5	21.81	1183	1.88	13.39	106	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.94	12.12	0.83	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:5	21.81	1183	1.88	13.41	106	199	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.95	12.12	0.83	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:5	20.45	1210	1.89	13.4	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.92	12.13	0.83	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:18:5	20.45	1235	1.9	13.39	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.92	12.13	0.83	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:5	21.81	1280	1.91	13.38	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.88	12.15	0.83	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:5	21.81	1280	1.92	13.39	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.87	12.15	0.83	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:18:6	21.81	1284	1.93	13.38	106	199	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.87	12.16	0.83	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:6	21.81	1318	1.94	13.37	105	199	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.88	12.17	0.83	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:6	21.81	1324	1.95	13.37	105	199	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.93	12.17	0.83	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:6	21.81	1329	1.96	13.38	106	199	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.95	12.19	0.83	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:6	21.81	1342	1.97	13.36	106	199	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	-0.97	12.19	0.83	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:6	21.81	1355	1.99	13.37	106	199	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.98	12.2	0.83	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:6	21.81	1362	2	13.37	105	199	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.99	12.22	0.83	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:7	21.81	1367	2.01	13.38	105	199	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.96	12.23	0.83	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:7	21.81	1374	2.03	13.37	105	199	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.97	12.24	0.83	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:7	21.81	1380	2.04	13.36	106	199	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.98	12.26	0.84	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:18:7	21.81	1399	2.04	13.37	106	199	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.93	12.28	0.84	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:18:7	21.81	1393	2.06	13.37	106	199	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-0.98	12.29	0.84	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:7	21.81	1400	2.06	13.36	106	199	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.96	12.33	0.84	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:8	21.81	1400	2.07	13.38	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.93	12.35	0.84	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:8	21.81	1433	2.08	13.38	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.91	12.38	0.84	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:8	23.18	1438	2.09	13.39	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.87	12.4	0.84	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:8	23.18	1448	2.1	13.37	105	199	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.87	12.43	0.85	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:8	24.54	1470	2.12	13.37	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.76	12.47	0.85	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:8	24.54	1484	2.13	13.4	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.7	12.52	0.85	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:9	24.54	1513	2.14	13.39	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.64	12.56	0.86	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:9	24.54	1513	2.14	13.39	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.6	12.61	0.86	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:18:9	24.54	1534	2.15	13.39	106	199	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.63	12.65	0.86	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:9	25.9	1579	2.17	13.38	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.59	12.72	0.87	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:9	25.9	1576	2.18	13.39	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.6	12.78	0.87	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:9	25.9	1576	2.18	13.39	105	199	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.61	12.84	0.87	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:18:9	25.9	1595	2.19	13.37	106	199	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.6	12.91	0.88	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:0	25.9	1622	2.2	13.39	106	199	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.58	12.97	0.88	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:0	24.54	1616	2.21	13.38	106	199	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.63	13.04	0.89	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:0	24.54	1630	2.22	13.38	106	199	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.61	13.14	0.9	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:0	24.54	1639	2.24	13.39	106	199	Off Idle	86.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.63	13.23	0.9	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:0	24.54	1639	2.24	13.37	106	199	Off Idle	86.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.62	13.38	0.91	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:0	24.54	1660	2.25	13.37	105	199	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.63	13.46	0.92	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:1	25.9	1656	2.26	13.37	105	199	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.68	13.54	0.92	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:1	25.9	1661	2.27	13.37	106	199	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.64	13.62	0.93	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:1	25.9	1666	2.28	13.37	106	199	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.69	13.7	0.93	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:1	25.9	1685	2.28	13.37	106	199	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.69	13.78	0.94	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:1	25.9	1697	2.29	13.37	106	199	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.7	13.85	0.94	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:1	25.9	1712	2.3	13.37	106	199	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.66	13.93	0.95	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:1	25.9	1720	2.3	13.36	106	199	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.69	13.98	0.95	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:2	25.9	1751	2.31	13.37	106	199	Off Idle	86.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.73	14.05	0.96	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:2	27.27	1769	2.32	13.37	106	199	Off Idle	86.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.77	14.09	0.96	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:2	27.27	1769	2.33	13.35	106	199	Off Idle	86.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.71	14.15	0.96	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:2	27.27	1788	2.34	13.37	106	199	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.74	14.24	0.97	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:2	27.27	1818	2.34	13.38	106	199	Off Idle	86.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.74	14.29	0.97	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:2	27.27	1835	2.35	13.38	106	199	Off Idle	86.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.72	14.34	0.98	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:3	27.27	1835	2.36	13.38	106	199	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.71	14.4	0.98	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:3	27.27	1854	2.37	13.37	106	199	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.72	14.46	0.98	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:3	27.27	1871	2.38	13.37	106	199	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.69	14.48	0.99	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:3	27.27	1871	2.38	13.37	106	199	Off Idle	86.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.69	14.54	0.99	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:3	27.27	1862	2.4	13.37	106	199	Off Idle	86.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.72	14.61	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:3	27.27	1884	2.41	13.37	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.73	14.66	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:4	27.27	1887	2.42	13.38	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.73	14.7	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:19:4	27.27	1927	2.42	13.39	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-0.76	14.76	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:4	28.63	1927	2.43	13.38	106	199	Off Idle	86.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-0.73	14.79	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:4	28.63	1910	2.44	13.37	105	199	Off Idle	86.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-0.71	14.81	1.01	3.7	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:19:4	28.63	1920	2.45	13.39	105	199	Off Idle	86	0	2	132	944 Turbo	0.45	Lean	1	14.6	-0.64	14.82	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:4	28.63	1938	2.46	13.36	105	199	Off Idle	86	0	2	132	944 Turbo	0.39	Lean	1	14.6	-0.6	14.82	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:4	28.63	1954	2.47	13.36	105	199	Off Idle	86	0	2	132	944 Turbo	0.33	Lean	1	14.6	-0.63	14.85	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:5	28.63	1954	2.47	13.39	105	199	Off Idle	86	0	2	132	944 Turbo	0.28	Lean	1	14.6	-0.65	14.88	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:5	28.63	1982	2.48	13.36	106	199	Off Idle	86	0	2	132	944 Turbo	0.22	Lean	1	14.6	-0.68	14.93	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:5	28.63	2004	2.49	13.37	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-0.66	15.01	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:5	28.63	2004	2.5	13.36	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-0.65	15.04	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:5	28.63	2030	2.5	13.35	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.63	15.13	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:5	28.63	2047	2.51	13.33	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-0.66	15.19	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:6	28.63	2060	2.52	13.35	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-0.66	15.27	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:6	28.63	2070	2.52	13.35	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-0.74	15.36	1.05	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:19:6	28.63	2094	2.53	13.37	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-0.78	15.41	1.05	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:19:6	28.63	2124	2.53	13.36	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-0.78	15.43	1.05	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:19:6	28.63	2136	2.54	13.36	106	199	Off Idle	85.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-0.74	15.43	1.05	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:19:6	28.63	2136	2.54	13.34	106	199	Off Idle	85.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-0.71	15.41	1.05	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:19:6	28.63	2152	2.55	13.36	106	199	Off Idle	85.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.67	15.39	1.05	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:19:7	28.63	2182	2.56	13.35	106	199	Off Idle	85.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-0.63	15.38	1.05	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:7	28.63	2182	2.57	13.38	106	199	Off Idle	85.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-0.64	15.34	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:7	28.63	2176	2.57	13.38	106	199	Off Idle	85.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-0.64	15.33	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:7	28.63	2181	2.58	13.39	106	199	Off Idle	85.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-0.64	15.3	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:7	28.63	2179	2.59	13.38	106	199	Off Idle	85.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-0.66	15.27	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:7	29.99	2189	2.6	13.37	106	199	Off Idle	85.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.65	15.22	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:8	29.99	2194	2.6	13.36	106	199	Off Idle	85.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.67	15.17	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:8	29.99	2204	2.61	13.35	106	199	Off Idle	85	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.66	15.13	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:19:8	29.99	2209	2.61	13.35	106	199	Off Idle	84.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.64	15.09	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:8	29.99	2223	2.62	13.34	106	199	Off Idle	84.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.61	15.02	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:8	29.99	2240	2.62	13.34	105	199	Off Idle	84	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.58	14.99	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:8	29.99	2257	2.63	13.36	105	199	Off Idle	83.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.54	14.93	1.02	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:9	29.99	2275	2.64	13.37	105	199	Off Idle	83.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-0.51	14.87	1.01	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:19:9	29.99	2282	2.64	13.37	106	199	Off Idle	82.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-0.55	14.84	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:9	29.99	2324	2.65	13.39	106	199	Off Idle	82.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-0.6	14.82	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:9	29.99	2324	2.65	13.39	106	199	Off Idle	82	0	2	132	944 Turbo	0.47	Lean	1	14.6	-0.68	14.81	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:9	29.99	2337	2.66	13.39	106	199	Off Idle	81.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-0.66	14.79	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:9	29.99	2344	2.66	13.39	106	199	Off Idle	81.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-0.65	14.79	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:19:9	29.99	2379	2.67	13.38	106	199	Off Idle	79.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-0.68	14.8	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:0	29.99	2389	2.67	13.36	106	199	Off Idle	79.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-0.68	14.81	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:0	29.99	2389	2.68	13.37	106	199	Off Idle	78.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-0.64	14.86	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:20:0	29.99	2410	2.68	13.38	106	199	Off Idle	78	0	2	132	944 Turbo	0.13	Lean	1	14.6	-0.65	14.9	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:0	29.99	2432	2.69	13.38	106	199	Off Idle	77.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-0.68	14.97	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:0	29.99	2436	2.7	13.38	106	199	Off Idle	76.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-0.62	15	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:20:0	31.36	2442	2.71	13.39	106	199	Off Idle	74.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-0.62	15.04	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:1	31.36	2460	2.72	13.39	106	199	Off Idle	74.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-0.6	15.08	1.03	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:1	31.36	2483	2.72	13.39	106	199	Off Idle	73.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-0.71	15.13	1.03	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:1	31.36	2508	2.73	13.37	106	199	Off Idle	73	0	2	132	944 Turbo	0.35	Lean	1	14.6	-0.68	15.17	1.03	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:1	31.36	2503	2.74	13.38	106	199	Off Idle	72.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-0.74	15.19	1.04	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:1	31.36	2510	2.75	13.38	106	199	Off Idle	71.7	0	2	132	944 Turbo	0.51	Lean	1	14.6	-0.76	15.21	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:1	31.36	2520	2.75	13.37	106	199	Off Idle	70.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-0.7	15.18	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:1	31.36	2525	2.76	13.37	106	199	Off Idle	69.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-0.63	15.15	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:2	31.36	2530	2.77	13.38	106	199	Off Idle	69.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.68	15.1	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:2	31.36	2546	2.77	13.38	106	199	Off Idle	68.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.65	15.06	1.03	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:2	31.36	2555	2.78	13.38	106	199	Off Idle	67.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.64	15.02	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:2	31.36	2555	2.79	13.37	106	199	Off Idle	67.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.57	14.97	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:20:2	31.36	2566	2.79	13.38	106	199	Off Idle	67	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.58	14.91	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:20:2	31.36	2582	2.8	13.35	106	199	Off Idle	66.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.57	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:20:3	31.36	2591	2.81	13.35	106	199	Off Idle	65.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.53	14.8	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:20:3	31.36	2612	2.81	13.36	106	199	Off Idle	65.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.51	14.8	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:3	31.36	2612	2.82	13.35	106	199	Off Idle	64.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-0.57	14.79	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:3	31.36	2640	2.82	13.37	106	199	Off Idle	64.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-0.51	14.78	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:20:3	31.36	2654	2.83	13.37	106	199	Off Idle	63.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-0.54	14.79	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:3	31.36	2654	2.83	13.38	106	199	Off Idle	63.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-0.57	14.8	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:4	31.36	2688	2.84	13.38	106	199	Off Idle	62	0	2	132	944 Turbo	0.24	Lean	1	14.6	-0.57	14.84	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:4	31.36	2708	2.85	13.38	106	199	Off Idle	61.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-0.56	14.87	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:4	31.36	2728	2.85	13.4	106	199	Off Idle	60.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-0.56	14.91	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:4	31.36	2744	2.86	13.41	106	199	Off Idle	59.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-0.55	14.94	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:4	31.36	2754	2.87	13.39	106	199	Off Idle	59.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-0.56	14.97	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:20:4	31.36	2760	2.87	13.4	106	199	Off Idle	58.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-0.64	15	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:20:4	31.36	2831	2.88	13.38	106	199	Off Idle	57.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-0.56	15.09	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:20:5	31.36	2798	2.89	13.38	106	199	Off Idle	56.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-0.58	15.14	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:20:5	31.36	2809	2.9	13.36	106	199	Off Idle	55.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-0.52	15.16	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:20:5	31.36	2814	2.9	13.38	106	199	Off Idle	54.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.5	15.14	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:20:5	31.36	2830	2.91	13.37	106	199	Off Idle	53.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.44	15.08	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:5	32.72	2848	2.92	13.37	106	199	Off Idle	53	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.46	15.04	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:5	32.72	2848	2.93	13.38	106	199	Off Idle	51.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.4	15.02	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:6	32.72	2856	2.93	13.36	106	199	Off Idle	51.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.39	15	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:6	32.72	2855	2.94	13.38	106	199	Off Idle	50.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.42	14.95	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:6	32.72	2887	2.95	13.39	106	199	Off Idle	50.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.39	14.9	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:20:6	32.72	2887	2.95	13.38	106	199	Off Idle	49.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-0.34	14.84	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:6	32.72	2885	2.96	13.39	106	199	Off Idle	49.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-0.34	14.83	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:6	32.72	2901	2.97	13.38	106	199	Off Idle	48.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-0.26	14.8	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:20:6	32.72	2908	2.97	13.38	106	199	Off Idle	47.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-0.33	14.8	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:20:7	31.36	2943	2.98	13.38	106	199	Off Idle	47.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-0.37	14.82	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:7	31.36	2968	2.98	13.37	106	199	Off Idle	46.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-0.38	14.86	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:20:7	31.36	2974	2.99	13.37	106	199	Off Idle	46.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-0.37	14.88	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:7	31.36	2996	3	13.38	106	199	Off Idle	45.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-0.36	14.92	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:7	32.72	3015	3.01	13.37	106	199	Off Idle	45.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-0.3	15.03	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:7	32.72	3020	3.01	13.36	106	199	Off Idle	44.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-0.26	15.05	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:8	32.72	3040	3.02	13.37	106	199	Off Idle	44	0	2	132	944 Turbo	0.46	Rich	1	14.6	-0.22	15.05	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:8	32.72	3060	3.03	13.37	106	199	Off Idle	43.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-0.17	15.07	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:8	32.72	3060	3.04	13.35	106	199	Off Idle	43.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.18	15.08	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:8	32.72	3086	3.05	13.35	106	199	Off Idle	42.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.17	15.06	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:20:8	32.72	3086	3.05	13.35	106	199	Off Idle	42	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.13	15.05	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:8	32.72	3092	3.06	13.36	106	199	Off Idle	41.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.19	14.99	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:9	32.72	3099	3.07	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.16	14.95	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:9	32.72	3114	3.08	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.1	14.87	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:9	32.72	3123	3.09	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.07	14.81	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:9	32.72	3139	3.1	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	0	14.78	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:9	32.72	3141	3.1	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.01	14.79	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:9	32.72	3156	3.11	13.35	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	0.01	14.79	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:20:9	32.72	3176	3.12	13.35	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.06	14.82	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:21:0	32.72	3202	3.13	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	0	14.83	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:21:0	32.72	3210	3.13	13.35	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	0.02	14.83	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:21:0	32.72	3237	3.14	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	0.04	14.84	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:21:0	31.36	3265	3.15	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	0.11	14.85	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:21:0	31.36	3267	3.15	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	0.08	14.86	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:0	31.36	3280	3.16	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	0.03	14.9	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:1	31.36	3286	3.16	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	0.04	14.92	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:1	32.72	3328	3.17	13.39	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	0.02	14.96	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:1	32.72	3322	3.18	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.08	14.96	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:1	32.72	3341	3.18	13.39	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.15	14.93	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:1	32.72	3349	3.19	13.39	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.23	14.92	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:1	32.72	3350	3.19	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.33	14.85	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:1	32.72	3358	3.2	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.41	14.8	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:2	32.72	3360	3.2	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.38	14.79	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:2	32.72	3367	3.2	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.41	14.71	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:2	32.72	3382	3.21	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.4	14.65	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:2	32.72	3390	3.21	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.4	14.64	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:21:2	32.72	3396	3.22	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	0.46	14.65	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:2	32.72	3405	3.22	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	0.44	14.65	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:21:3	32.72	3422	3.23	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	0.54	14.69	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:3	32.72	3436	3.23	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	0.59	14.72	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:3	32.72	3464	3.24	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	0.68	14.79	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:3	32.72	3464	3.24	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	0.72	14.78	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:3	32.72	3490	3.25	13.39	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	0.75	14.83	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:3	32.72	3530	3.25	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	0.77	14.91	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:21:4	32.72	3530	3.26	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	0.67	14.98	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:21:4	32.72	3564	3.26	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	0.6	15.07	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:4	32.72	3581	3.26	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	0.69	15.09	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:4	32.72	3591	3.27	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	0.75	15.07	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:4	32.72	3604	3.28	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.79	15.02	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:4	32.72	3604	3.28	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.85	15.01	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:4	32.72	3603	3.29	13.35	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.96	14.96	1.02	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:14:21:5	32.72	3602	3.3	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.85	14.9	1.01	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:14:21:5	32.72	3610	3.3	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.88	14.86	1.01	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:14:21:5	32.72	3622	3.31	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	0.89	14.75	1	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:14:21:5	32.72	3633	3.31	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	0.87	14.72	1	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:5	32.72	3648	3.31	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	0.97	14.67	1	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:21:5	32.72	3664	3.32	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	0.92	14.7	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:6	32.72	3664	3.32	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	0.87	14.71	1	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:21:6	32.72	3692	3.32	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	0.86	14.79	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:21:6	32.72	3714	3.33	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	0.82	14.81	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:21:6	32.72	3738	3.33	13.39	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	0.9	14.86	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:21:6	32.72	3758	3.34	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	0.93	14.92	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:21:6	32.72	3778	3.34	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	0.9	14.94	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:6	32.72	3778	3.34	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	0.91	14.94	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:21:7	32.72	3796	3.35	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	0.84	14.96	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:21:7	32.72	3807	3.35	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	0.84	14.94	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:7	32.72	3807	3.35	13.36	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	0.92	14.89	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:7	34.08	3838	3.36	13.36	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.85	14.88	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:21:7	34.08	3819	3.36	13.35	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	0.85	14.86	1.01	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:7	34.08	3828	3.36	13.34	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	0.79	14.76	1.01	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:8	34.08	3841	3.36	13.33	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	0.71	14.71	1	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:8	34.08	3895	3.37	13.33	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	0.75	14.73	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:21:8	34.08	3895	3.37	13.33	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	0.62	14.75	1	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:8	34.08	3886	3.37	13.36	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	0.54	14.77	1.01	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:8	34.08	3918	3.37	13.37	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	0.58	14.88	1.01	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:8	34.08	3936	3.37	13.37	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	0.49	14.92	1.02	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:14:21:9	34.08	3958	3.38	13.4	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	0.47	14.95	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:9	34.08	3964	3.38	13.38	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	0.49	14.96	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:9	34.08	3979	3.38	13.36	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	0.46	14.94	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:21:9	34.08	4008	3.38	13.36	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.17	14.84	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:14:21:9	34.08	4039	3.38	13.35	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.13	14.71	1	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:21:9	34.08	4026	3.38	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.05	14.57	0.99	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:21:9	34.08	4044	3.37	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.19	14.28	0.97	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:14:22:0	34.08	4056	3.37	13.39	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.32	14.05	0.96	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:0	35.45	4156	3.36	13.39	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.55	13.86	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:22:0	35.45	4066	3.35	13.39	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-0.74	13.68	0.93	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:22:0	35.45	4069	3.34	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.13	13.48	0.92	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:22:0	35.45	4071	3.32	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.38	13.3	0.91	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:22:0	35.45	4070	3.3	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.75	13.1	0.89	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:22:1	35.45	4068	3.27	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.28	12.94	0.88	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:22:1	35.45	4064	3.24	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.66	12.85	0.88	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:22:1	35.45	4061	3.21	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.25	12.77	0.87	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:22:1	35.45	4070	3.15	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.25	12.75	0.87	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:22:1	36.81	4070	3.06	13.39	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-5.03	12.68	0.86	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:22:1	36.81	4028	2.99	13.4	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-5.84	12.62	0.86	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:22:1	36.81	4007	2.83	13.4	106	199	Full Load	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-6.89	12.53	0.85	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:22:2	36.81	4007	2.7	13.41	106	199	Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-7.74	12.48	0.85	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:22:2	36.81	3973	2.61	13.4	106	199	Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-8.32	12.41	0.85	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:22:2	36.81	3971	2.52	13.39	106	199	Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-8.52	12.35	0.84	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:2	36.81	3942	2.39	13.38	106	199	Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-8.92	12.26	0.84	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:2	38.18	3906	2.31	13.37	106	199	Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.16	12.15	0.83	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:2	38.18	3900	2.18	13.36	106	199	Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.46	12.03	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:3	38.18	3856	2.1	13.35	106	199	Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.62	11.83	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:3	38.18	3856	2.02	13.39	106	199	Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-9.72	11.72	0.8	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:3	35.45	3774	1.9	13.39	106	199	Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-9.71	11.5	0.78	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:3	29.99	3692	1.83	13.4	106	199	Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-9.73	11.44	0.78	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:3	24.54	3686	1.71	13.41	106	199	Idle	41.5	0	2	132	944 Turbo	0.81	Lean	1	14.6	-9.77	11.29	0.77	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:3	20.45	3690	1.65	13.4	106	199	Idle	41.5	0	2	132	944 Turbo	0.72	Lean	1	14.6	-9.76	11.26	0.77	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:4	20.45	3680	1.62	13.4	106	199	Idle	41.1	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.77	11.23	0.76	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:4	20.45	3634	1.6	13.4	106	199	Idle	40.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.74	11.23	0.76	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:4	20.45	3634	1.59	13.4	106	199	Idle	40.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.77	11.26	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:4	20.45	3582	1.58	13.42	106	199	Idle	39.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.75	11.3	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:4	20.45	3559	1.59	13.4	106	199	Idle	38.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.74	11.44	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:4	20.45	3529	1.6	13.4	106	199	Idle	37.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.68	11.51	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:4	20.45	3492	1.61	13.4	106	199	Idle	36.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.62	11.69	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:5	20.45	3491	1.62	13.39	106	199	Idle	35	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	11.95	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:5	20.45	3459	1.64	13.39	106	199	Idle	32.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.48	12.42	0.85	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:5	20.45	3428	1.65	13.4	106	199	Idle	31	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.5	12.87	0.88	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:5	20.45	3392	1.66	13.4	106	199	Idle	29.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.46	13.96	0.95	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:5	20.45	3384	1.68	13.4	106	199	Idle	27	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.42	15.21	1.04	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:5	20.45	3327	1.7	13.41	106	199	Idle	25.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.39	16.03	1.09	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:6	20.45	3313	1.71	13.41	106	199	Idle	24.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.32	16.83	1.15	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:6	20.45	3283	1.72	13.4	106	199	Idle	23.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.28	17.58	1.2	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:6	20.45	3262	1.74	13.39	106	199	Idle	22.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.23	18.28	1.25	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:6	20.45	3235	1.75	13.39	106	199	Idle	22	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.15	18.91	1.29	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:6	20.45	3235	1.76	13.39	106	199	Idle	21.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.13	19.75	1.35	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:6	20.45	3180	1.78	13.39	106	199	Idle	21.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.09	20.07	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:6	20.45	3142	1.79	13.4	106	199	Idle	21.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.05	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:7	20.45	3122	1.8	13.39	106	199	Idle	21.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.01	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:7	20.45	3103	1.81	13.39	106	199	Idle	21.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.99	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:7	20.45	3081	1.82	13.4	106	199	Idle	21.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.98	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:7	20.45	3060	1.83	13.39	106	199	Full Load	21.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.91	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:7	19.09	3030	1.84	13.39	106	199	Off Idle	21.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.89	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:22:7	19.09	2919	1.84	13.39	106	199	Off Idle	21.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.83	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:22:8	13.63	2991	1.85	13.38	106	199	Off Idle	22.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.78	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:22:8	13.63	2991	1.87	13.39	106	199	Off Idle	23.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.67	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:22:8	16.36	2961	1.88	13.39	106	199	Off Idle	25.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.57	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:22:8	19.09	2928	1.9	13.39	106	199	Off Idle	26.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.45	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:14:22:8	21.81	2895	1.91	13.38	106	199	Off Idle	27.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.29	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:22:8	21.81	2895	1.93	13.37	106	199	Off Idle	29.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.21	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:22:9	24.54	2873	1.95	13.39	106	199	Off Idle	30.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.91	20.25	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:22:9	27.27	2836	1.98	13.39	106	199	Off Idle	34.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.68	20.26	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:22:9	27.27	2806	2.02	13.39	106	199	Off Idle	35.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.29	20.27	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:22:9	29.99	2794	2.05	13.37	106	199	Off Idle	37.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.04	20.26	1.38	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:22:9	32.72	2786	2.08	13.36	106	199	Off Idle	39.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-6.73	20.26	1.38	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:22:9	35.45	2762	2.11	13.37	106	199	Off Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.43	20.26	1.38	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:22:9	35.45	2732	2.16	13.36	106	199	Off Idle	43.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.02	20.26	1.38	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:23:0	35.45	2732	2.2	13.36	106	199	Off Idle	45.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.73	20.26	1.38	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:23:0	35.45	2715	2.21	13.38	106	199	Off Idle	47.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.52	20.26	1.38	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:23:0	35.45	2692	2.26	13.38	106	199	Off Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.41	20.26	1.38	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:0	35.45	2692	2.28	13.38	106	199	Off Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.36	20.26	1.38	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:0	35.45	2663	2.32	13.39	106	199	Off Idle	49.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.13	20.25	1.38	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:23:0	34.08	2620	2.35	13.38	106	199	Off Idle	50.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-4.98	20.25	1.38	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:1	34.08	2606	2.37	13.36	106	199	Off Idle	51.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.89	20.25	1.38	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:1	34.08	2556	2.4	13.36	106	199	Off Idle	53.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.81	20.26	1.38	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:1	34.08	2526	2.42	13.36	106	199	Off Idle	54.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.74	20.25	1.38	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:1	34.08	2510	2.45	13.34	106	199	Off Idle	55.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.66	20.21	1.38	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:1	34.08	2427	2.47	13.35	106	199	Off Idle	56.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.56	19.95	1.36	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:1	32.72	2417	2.48	13.37	106	199	Off Idle	58.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.36	19.52	1.33	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:1	32.72	2417	2.48	13.37	106	199	Off Idle	59.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.29	19.35	1.32	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:2	32.72	2386	2.47	13.36	106	199	Off Idle	61.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.25	18.77	1.28	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:2	32.72	2362	2.47	13.38	106	199	Off Idle	62.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.2	18.33	1.25	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:2	32.72	2362	2.47	13.37	106	199	Off Idle	63.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.05	17.63	1.2	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:2	32.72	2418	2.47	13.38	106	199	Off Idle	64.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.92	17.13	1.17	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:2	32.72	2430	2.48	13.39	106	199	Off Idle	66.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.73	16.88	1.15	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:23:2	32.72	2474	2.49	13.38	106	199	Off Idle	67.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.39	16.43	1.12	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:23:3	32.72	2534	2.51	13.41	106	199	Off Idle	68.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.15	15.92	1.08	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:23:3	32.72	2545	2.53	13.38	106	199	Off Idle	69	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.91	15.79	1.08	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:23:3	32.72	2545	2.54	13.37	106	199	Off Idle	69.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.65	15.47	1.05	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:23:3	32.72	2568	2.55	13.37	106	199	Off Idle	69.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-2.53	15.31	1.04	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:23:3	32.72	2594	2.57	13.36	106	199	Off Idle	68.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-2.44	15.2	1.04	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:23:3	32.72	2582	2.58	13.38	106	199	Off Idle	68.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-2.38	15.11	1.03	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:23:4	32.72	2578	2.59	13.39	106	199	Off Idle	68	0	2	132	944 Turbo	0.4	Rich	1	14.6	-2.29	15.05	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:4	32.72	2559	2.6	13.37	106	199	Off Idle	67.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-2.25	15.06	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:4	32.72	2559	2.62	13.36	106	199	Off Idle	66.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-2.07	15.09	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:4	32.72	2531	2.63	13.36	106	199	Off Idle	65.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-2.04	15.1	1.03	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:23:4	32.72	2514	2.65	13.36	106	199	Off Idle	65	0	2	132	944 Turbo	0.44	Rich	1	14.6	-1.95	15.13	1.03	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:4	32.72	2514	2.67	13.37	106	199	Off Idle	64.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-1.86	15.15	1.03	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:4	32.72	2510	2.69	13.38	106	199	Off Idle	64.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-1.79	15.24	1.04	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:23:5	31.36	2499	2.71	13.36	106	199	Off Idle	63.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.75	15.23	1.04	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:5	31.36	2527	2.71	13.38	106	199	Off Idle	63.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.75	15.21	1.04	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:5	31.36	2551	2.72	13.39	106	199	Off Idle	63.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.75	15.07	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:5	31.36	2551	2.72	13.38	106	199	Off Idle	63.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.75	14.93	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:5	31.36	2551	2.72	13.38	106	199	Off Idle	63.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.68	14.76	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:5	31.36	2605	2.72	13.39	106	199	Off Idle	63.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.64	14.6	0.99	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:6	31.36	2595	2.72	13.38	106	199	Off Idle	63.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.59	14.36	0.98	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:6	31.36	2598	2.73	13.37	106	199	Off Idle	63.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.54	14.17	0.97	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:23:6	31.36	2600	2.73	13.36	106	199	Off Idle	63.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.52	14	0.95	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:23:6	32.72	2625	2.74	13.36	106	199	Off Idle	63.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.43	13.78	0.94	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:6	32.72	2604	2.74	13.36	106	199	Off Idle	63.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.37	13.68	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:6	32.72	2607	2.75	13.35	106	199	Off Idle	63.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.31	13.62	0.93	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:6	32.72	2606	2.75	13.35	106	199	Off Idle	63.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.27	13.59	0.93	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:7	32.72	2605	2.76	13.37	106	199	Off Idle	63	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.27	13.56	0.92	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:7	31.36	2596	2.76	13.36	106	199	Off Idle	62.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.28	13.54	0.92	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:7	31.36	2609	2.77	13.37	106	199	Off Idle	62.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.24	13.54	0.92	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:7	31.36	2616	2.77	13.37	106	199	Off Idle	61.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.28	13.54	0.92	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:7	31.36	2621	2.78	13.35	106	199	Off Idle	61.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.22	13.55	0.92	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:7	31.36	2625	2.78	13.33	106	199	Off Idle	61	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.19	13.56	0.92	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:8	31.36	2638	2.79	13.35	106	199	Off Idle	60.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.22	13.58	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:8	31.36	2652	2.8	13.36	106	199	Off Idle	60.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.15	13.62	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:8	31.36	2652	2.8	13.36	106	199	Off Idle	60.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.16	13.64	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:8	31.36	2659	2.81	13.36	106	199	Off Idle	59.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.12	13.65	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:8	31.36	2687	2.81	13.38	106	199	Off Idle	59.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.11	13.67	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:8	31.36	2678	2.81	13.36	106	199	Off Idle	59.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.05	13.66	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:9	31.36	2672	2.82	13.35	106	199	Off Idle	58.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.03	13.65	0.93	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:9	31.36	2673	2.82	13.35	106	199	Off Idle	58.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.99	13.65	0.93	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:9	31.36	2674	2.82	13.36	106	199	Off Idle	58	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.98	13.63	0.93	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:9	31.36	2676	2.83	13.37	106	199	Off Idle	57.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.92	13.64	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:9	31.36	2682	2.83	13.37	106	199	Off Idle	57.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.93	13.61	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:23:9	31.36	2684	2.83	13.36	106	199	Off Idle	57.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.81	13.61	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:23:9	31.36	2692	2.84	13.37	106	199	Off Idle	56.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.81	13.62	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:0	31.36	2702	2.84	13.37	106	199	Off Idle	56.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.81	13.62	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:0	31.36	2711	2.85	13.37	106	199	Off Idle	56.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.78	13.61	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:0	31.36	2712	2.85	13.37	106	199	Off Idle	56.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.81	13.62	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:0	31.36	2719	2.85	13.37	106	199	Off Idle	56.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.8	13.64	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:0	31.36	2723	2.86	13.35	106	199	Off Idle	55.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.83	13.66	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:0	31.36	2724	2.86	13.36	106	199	Off Idle	55.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.81	13.66	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:1	31.36	2743	2.87	13.36	106	199	Off Idle	55.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.74	13.68	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:1	31.36	2744	2.87	13.36	106	199	Off Idle	54.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.75	13.68	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:1	31.36	2750	2.88	13.38	106	199	Off Idle	54.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.82	13.7	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:1	31.36	2750	2.88	13.38	106	199	Off Idle	54.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.72	13.72	0.93	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:1	32.72	2777	2.88	13.36	106	199	Off Idle	54.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.7	13.74	0.94	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:1	32.72	2761	2.89	13.37	106	199	Off Idle	54.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.73	13.75	0.94	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:24:1	32.72	2766	2.89	13.38	106	199	Off Idle	54	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.71	13.79	0.94	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:2	32.72	2769	2.89	13.37	106	199	Off Idle	53.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.73	13.76	0.94	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:2	32.72	2771	2.9	13.37	106	199	Off Idle	52.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.66	13.78	0.94	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:2	32.72	2774	2.9	13.38	106	199	Off Idle	52.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.62	13.77	0.94	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:2	32.72	2780	2.91	13.38	106	199	Off Idle	52.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.63	13.77	0.94	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:2	32.72	2793	2.91	13.38	106	199	Off Idle	51.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.57	13.73	0.94	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:2	32.72	2783	2.91	13.38	106	199	Off Idle	51.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.54	13.73	0.94	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:3	32.72	2783	2.92	13.38	106	199	Off Idle	51.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.6	13.75	0.94	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:3	31.36	2811	2.92	13.38	106	199	Off Idle	51.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.52	13.79	0.94	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:24:3	31.36	2813	2.92	13.36	106	199	Off Idle	51.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.5	13.76	0.94	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:24:3	31.36	2808	2.93	13.37	106	199	Off Idle	50.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.48	13.81	0.94	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:3	31.36	2808	2.93	13.37	106	199	Off Idle	50.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.44	13.85	0.94	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:3	31.36	2816	2.94	13.36	106	199	Off Idle	50.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.41	13.9	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:24:4	31.36	2825	2.94	13.38	106	199	Off Idle	50.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.44	13.94	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:24:4	31.36	2827	2.94	13.38	106	199	Off Idle	49.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.4	13.98	0.95	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:4	31.36	2840	2.95	13.38	106	199	Off Idle	49.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.37	14.04	0.96	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:4	31.36	2848	2.95	13.37	106	199	Off Idle	49.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.31	14.1	0.96	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:4	31.36	2854	2.95	13.38	106	199	Off Idle	49.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.34	14.11	0.96	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:4	31.36	2855	2.96	13.38	106	199	Off Idle	48.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.33	14.15	0.96	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:24:4	31.36	2860	2.96	13.38	106	199	Off Idle	48.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.32	14.19	0.97	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:5	31.36	2881	2.96	13.38	106	199	Off Idle	48.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.29	14.22	0.97	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:5	31.36	2881	2.97	13.38	106	199	Off Idle	47.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.34	14.25	0.97	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:5	31.36	2860	2.97	13.38	106	199	Off Idle	47.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.24	14.27	0.97	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:5	31.36	2873	2.97	13.38	106	199	Off Idle	47.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.26	14.3	0.97	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:5	31.36	2873	2.98	13.39	107	199	Off Idle	47	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.24	14.31	0.98	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:5	31.36	2886	2.98	13.4	107	199	Off Idle	46.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.28	14.33	0.98	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:6	31.36	2894	2.98	13.38	107	199	Off Idle	46.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.19	14.36	0.98	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:24:6	31.36	2905	2.99	13.38	107	199	Off Idle	46.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.17	14.44	0.98	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:6	31.36	2908	2.99	13.37	107	199	Off Idle	46	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.17	14.48	0.99	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:6	31.36	2911	2.99	13.37	106	199	Off Idle	45.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.14	14.5	0.99	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:6	31.36	2914	3	13.37	106	199	Off Idle	45.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.18	14.55	0.99	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:6	31.36	2925	3	13.37	106	199	Off Idle	45.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.15	14.58	0.99	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:6	31.36	2932	3	13.38	107	199	Off Idle	45.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.17	14.62	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:7	31.36	2934	3.01	13.38	107	199	Off Idle	45.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.11	14.66	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:7	31.36	2945	3.01	13.37	107	199	Off Idle	44.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.17	14.68	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:7	31.36	2937	3.01	13.38	106	199	Off Idle	44.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.08	14.7	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:7	31.36	2938	3.02	13.38	106	199	Off Idle	44.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.14	14.73	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:7	31.36	2949	3.02	13.36	106	199	Off Idle	44.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.05	14.73	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:7	31.36	2960	3.02	13.38	107	199	Off Idle	43.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.07	14.75	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:8	31.36	2966	3.03	13.37	107	199	Off Idle	43.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.07	14.76	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:8	31.36	2969	3.03	13.39	107	199	Off Idle	43.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.03	14.77	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:8	31.36	2974	3.03	13.38	106	199	Off Idle	43	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.08	14.77	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:8	31.36	2978	3.04	13.39	106	199	Off Idle	42.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.03	14.77	1.01	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:24:8	31.36	2992	3.04	13.38	106	199	Off Idle	42.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.02	14.77	1.01	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:24:8	32.72	2986	3.04	13.39	107	199	Off Idle	42.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.02	14.78	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:24:9	32.72	2986	3.05	13.37	107	199	Off Idle	42.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.06	14.78	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:9	32.72	3000	3.05	13.38	107	199	Off Idle	42	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.01	14.79	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:9	32.72	3001	3.05	13.37	106	199	Off Idle	42	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.04	14.81	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:9	31.36	2991	3.06	13.37	106	199	Off Idle	41.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.06	14.82	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:24:9	31.36	3011	3.06	13.37	106	199	Off Idle	41.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.02	14.82	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:24:9	31.36	3022	3.06	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.08	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:24:9	31.36	3054	3.07	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	0.01	14.82	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:0	32.72	3043	3.07	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	0.08	14.84	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:0	32.72	3032	3.07	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	0.02	14.85	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:0	32.72	3028	3.07	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	0.1	14.87	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:25:0	32.72	3028	3.08	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	0.03	14.89	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:25:0	32.72	3038	3.08	13.35	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	0.14	14.93	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:25:0	32.72	3053	3.08	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	0.1	14.95	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:25:1	32.72	3053	3.08	13.36	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	0.11	14.97	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:25:1	32.72	3064	3.09	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	0.14	15.01	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:25:1	31.36	3049	3.09	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	0.14	15.11	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:25:1	31.36	3085	3.09	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	0.15	15.13	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:25:1	31.36	3088	3.09	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	0.14	15.16	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:25:1	31.36	3098	3.1	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	0.17	15.2	1.04	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:25:1	31.36	3104	3.1	13.37	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	0.1	15.23	1.04	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:2	31.36	3104	3.1	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	0.08	15.21	1.04	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:2	31.36	3104	3.1	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	0.13	15.19	1.03	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:25:2	31.36	3098	3.1	13.36	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	0.11	15.14	1.03	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:25:2	31.36	3102	3.11	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.08	15.07	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:2	31.36	3114	3.11	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.15	14.97	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:2	32.72	3106	3.11	13.38	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.1	14.92	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:3	32.72	3115	3.11	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.12	14.88	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:3	32.72	3120	3.11	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.04	14.81	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:3	32.72	3134	3.11	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.03	14.72	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:3	32.72	3146	3.11	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.03	14.69	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:25:3	32.72	3146	3.11	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.06	14.68	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:25:3	32.72	3159	3.11	13.36	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.04	14.7	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:25:4	32.72	3166	3.12	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	0	14.75	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:25:4	32.72	3168	3.12	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.09	14.76	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:25:4	32.72	3170	3.12	13.39	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.09	14.78	1.01	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:25:4	32.72	3166	3.12	13.4	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.19	14.79	1.01	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:25:4	32.72	3162	3.11	13.39	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.26	14.82	1.01	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:25:4	32.72	3158	3.11	13.39	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.31	14.85	1.01	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:14:25:4	32.72	3154	3.1	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.41	14.86	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:25:5	32.72	3161	3.1	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.51	14.87	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:25:5	32.72	3165	3.09	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-0.66	14.87	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:25:5	32.72	3156	3.09	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-0.64	14.88	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:25:5	32.72	3182	3.09	13.35	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-0.72	14.86	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:14:25:5	32.72	3187	3.08	13.36	106	199	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-0.79	14.86	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:25:5	32.72	3195	3.08	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-0.81	14.84	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:25:6	32.72	3195	3.07	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-0.89	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:25:6	32.72	3206	3.07	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-0.94	14.83	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:25:6	32.72	3221	3.06	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-1	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:25:6	32.72	3222	3.06	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-1.05	14.9	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:25:6	32.72	3230	3.05	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-1.08	14.96	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:25:6	32.72	3234	3.05	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-1.15	15.02	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:14:25:6	32.72	3237	3.04	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-1.23	15.08	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:25:7	34.08	3250	3.03	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-1.32	15.12	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:25:7	34.08	3234	3.03	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-1.43	15.17	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:25:7	34.08	3237	3.02	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-1.53	15.19	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:25:7	34.08	3237	3.01	13.4	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-1.64	15.23	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:25:7	34.08	3268	3	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-1.75	15.24	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:25:7	34.08	3250	3	13.41	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.79	15.23	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:25:8	34.08	3251	2.99	13.4	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-1.93	15.23	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:8	34.08	3260	2.98	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-1.9	15.23	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:8	34.08	3274	2.98	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-2.02	15.19	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:8	34.08	3261	2.97	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-2.04	15.14	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:8	34.08	3243	2.96	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.08	15.09	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:25:8	34.08	3243	2.95	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-2.15	15.04	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:25:9	34.08	3236	2.94	13.39	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-2.25	15	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:25:9	34.08	3252	2.93	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.47	14.95	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:25:9	34.08	3255	2.92	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.56	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:25:9	34.08	3263	2.91	13.39	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-2.71	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:25:9	34.08	3268	2.9	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.74	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:25:9	34.08	3283	2.89	13.4	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-2.93	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:25:9	34.08	3289	2.88	13.39	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.06	14.99	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:0	34.08	3297	2.87	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.07	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:0	35.45	3322	2.86	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.31	15.15	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:26:0	35.45	3301	2.84	13.39	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.44	15.24	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:26:0	35.45	3298	2.84	13.39	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.52	15.27	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:26:0	35.45	3293	2.83	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.67	15.37	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:26:0	35.45	3293	2.82	13.4	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.71	15.39	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:26:1	35.45	3294	2.81	13.4	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.83	15.39	1.05	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:26:1	35.45	3295	2.79	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4	15.39	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:26:1	35.45	3294	2.77	13.4	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.12	15.39	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:26:1	35.45	3295	2.76	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.31	15.4	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:26:1	35.45	3290	2.74	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.52	15.42	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:26:1	35.45	3292	2.72	13.36	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.75	15.44	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:26:1	35.45	3293	2.7	13.37	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.85	15.46	1.05	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:26:2	35.45	3290	2.68	13.36	107	199	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.02	15.47	1.05	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:26:2	35.45	3289	2.65	13.38	107	199	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.21	15.46	1.05	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:26:2	35.45	3284	2.63	13.37	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.48	15.45	1.05	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:26:2	35.45	3287	2.61	13.37	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.69	15.44	1.05	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:26:2	35.45	3293	2.57	13.4	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.01	15.41	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:2	35.45	3290	2.54	13.38	107	199	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.2	15.38	1.05	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:26:3	35.45	3290	2.51	13.39	107	199	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.32	15.36	1.05	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:26:3	35.45	3290	2.48	13.38	107	199	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.68	15.35	1.05	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:26:3	35.45	3277	2.43	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.98	15.34	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:26:3	35.45	3276	2.41	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.22	15.33	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:14:26:3	36.81	3288	2.34	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.69	15.35	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:26:3	36.81	3271	2.28	13.38	107	199	Full Load	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.05	15.37	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:26:4	36.81	3257	2.23	13.4	107	199	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.22	15.4	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:26:4	36.81	3257	2.18	13.38	107	199	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.49	15.45	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:4	36.81	3222	2.13	13.4	107	199	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.63	15.49	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:4	34.08	3177	2.09	13.4	107	199	Idle	41.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.87	15.54	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:4	28.63	3174	2.04	13.38	107	199	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.08	15.6	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:4	23.18	3168	2.02	13.4	107	199	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.2	15.64	1.07	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:4	20.45	3135	1.97	13.39	107	199	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.24	15.69	1.07	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:5	20.45	3135	1.93	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.33	15.73	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:5	20.45	3152	1.88	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.31	15.77	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:5	20.45	3141	1.86	13.4	107	199	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.35	15.78	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:5	20.45	3163	1.83	13.39	107	199	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.41	15.78	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:5	20.45	3170	1.78	13.39	107	199	Idle	41.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.45	15.78	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:5	20.45	3209	1.76	13.39	107	198	Idle	41	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.48	15.78	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:6	20.45	3234	1.73	13.39	107	198	Idle	40.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.48	15.77	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:6	20.45	3262	1.71	13.39	107	199	Idle	40.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.49	15.76	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:6	20.45	3279	1.7	13.39	107	199	Idle	40.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.49	15.76	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:6	20.45	3286	1.69	13.39	107	199	Idle	40.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.49	15.74	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:6	20.45	3316	1.69	13.39	107	198	Idle	40.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.52	15.74	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:6	20.45	3300	1.69	13.4	107	198	Idle	40.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.55	15.74	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:6	20.45	3275	1.69	13.4	107	198	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	15.73	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:26:7	20.45	3252	1.69	13.39	107	198	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	15.75	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:7	20.45	3237	1.69	13.4	107	198	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	15.78	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:7	20.45	3234	1.69	13.39	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	15.83	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:7	20.45	3201	1.69	13.39	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	15.91	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:7	20.45	3175	1.69	13.4	107	198	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	16.06	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:7	20.45	3188	1.69	13.4	107	199	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	16.22	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:8	20.45	3178	1.69	13.4	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	16.83	1.15	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:8	20.45	3172	1.69	13.4	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	17.28	1.18	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:8	20.45	3174	1.69	13.4	107	199	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	17.73	1.21	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:8	20.45	3174	1.69	13.39	107	199	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	18.18	1.24	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:8	20.45	3180	1.7	13.4	107	199	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	18.82	1.28	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:8	20.45	3187	1.7	13.39	107	199	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	19.23	1.31	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:9	20.45	3192	1.7	13.39	107	199	Idle	40.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	19.62	1.34	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:9	20.45	3202	1.7	13.4	107	198	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	19.96	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:9	20.45	3202	1.7	13.39	107	198	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:9	20.45	3212	1.71	13.4	107	198	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:9	20.45	3212	1.71	13.39	107	199	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:9	20.45	3209	1.71	13.39	107	199	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:26:9	20.45	3208	1.71	13.39	107	199	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:0	20.45	3200	1.71	13.4	107	199	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:0	20.45	3188	1.71	13.39	107	199	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:0	20.45	3185	1.71	13.39	107	199	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:0	20.45	3173	1.71	13.39	107	198	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:0	20.45	3159	1.71	13.39	107	198	Idle	40.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:0	20.45	3159	1.71	13.39	107	198	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:1	20.45	3148	1.72	13.38	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:1	20.45	3142	1.72	13.4	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:1	20.45	3128	1.72	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:1	20.45	3140	1.72	13.4	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:1	20.45	3140	1.71	13.4	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.18	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:1	20.45	3140	1.71	13.4	107	199	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.18	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:1	20.45	3141	1.71	13.39	107	199	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:2	20.45	3144	1.71	13.4	107	199	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:2	20.45	3139	1.71	13.4	107	199	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:2	20.45	3150	1.71	13.41	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:2	20.45	3146	1.71	13.41	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:2	20.45	3142	1.7	13.41	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:2	20.45	3140	1.7	13.41	107	199	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:3	20.45	3136	1.7	13.4	107	199	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:3	20.45	3132	1.7	13.4	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:3	20.45	3124	1.7	13.39	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:3	20.45	3117	1.7	13.4	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:3	20.45	3118	1.7	13.41	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:3	19.09	3100	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:4	19.09	3108	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:4	19.09	3104	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:4	19.09	3104	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:4	19.09	3101	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:4	19.09	3095	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:4	19.09	3094	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:4	19.09	3092	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:5	19.09	3089	1.7	13.4	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:5	19.09	3082	1.7	13.39	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:5	19.09	3081	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:5	19.09	3077	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:5	19.09	3054	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:5	19.09	3085	1.7	13.41	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:6	19.09	3078	1.7	13.41	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:27:6	19.09	3064	1.7	13.4	107	199	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:6	19.09	3065	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:6	19.09	3063	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:6	19.09	3063	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:6	19.09	3063	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:6	19.09	3062	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:7	19.09	3064	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:7	19.09	3060	1.7	13.39	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:7	19.09	3057	1.7	13.39	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:7	19.09	3051	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:7	19.09	3048	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:7	19.09	3050	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:8	19.09	3047	1.7	13.39	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:8	19.09	3041	1.7	13.39	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:8	19.09	3041	1.7	13.39	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:8	19.09	3011	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:8	19.09	3030	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:8	19.09	3027	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:9	19.09	3026	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:9	19.09	3023	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:9	19.09	3018	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:9	19.09	3017	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:9	19.09	3017	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:9	19.09	3013	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:27:9	19.09	3011	1.7	13.39	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:0	19.09	3009	1.7	13.39	107	199	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:0	19.09	3009	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:0	19.09	3003	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:0	19.09	2999	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:0	19.09	2999	1.7	13.4	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:0	19.09	2991	1.7	13.39	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:1	19.09	2986	1.7	13.4	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:1	19.09	2980	1.7	13.4	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:1	19.09	2980	1.7	13.4	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:1	19.09	2976	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:1	19.09	2976	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:1	19.09	2972	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:1	19.09	2971	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:2	19.09	2969	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:2	19.09	2969	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:2	19.09	2957	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:2	19.09	2970	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:2	19.09	2970	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:2	19.09	2984	1.7	13.42	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:3	19.09	2975	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:3	19.09	2978	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:3	19.09	2978	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:3	19.09	2977	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:3	19.09	2975	1.7	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:3	19.09	2975	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:4	19.09	2967	1.7	13.4	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:4	19.09	2944	1.7	13.39	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:4	19.09	2945	1.7	13.4	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:4	19.09	2954	1.7	13.4	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:4	19.09	2926	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:4	19.09	2912	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:4	19.09	2879	1.7	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:5	19.09	2888	1.7	13.37	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:28:5	19.09	2862	1.7	13.38	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:5	19.09	2872	1.7	13.37	107	199	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:5	19.09	2872	1.7	13.39	107	199	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:5	19.09	2868	1.7	13.39	107	199	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:5	19.09	2868	1.7	13.4	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:6	19.09	2868	1.7	13.41	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:6	19.09	2868	1.71	13.41	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:6	19.09	2872	1.71	13.39	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:6	19.09	2876	1.71	13.39	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:6	19.09	2879	1.71	13.39	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:6	19.09	2880	1.71	13.4	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:6	19.09	2882	1.71	13.4	107	198	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:7	19.09	2882	1.71	13.4	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:7	19.09	2880	1.71	13.39	107	199	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:7	19.09	2878	1.71	13.39	107	199	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:7	19.09	2874	1.7	13.39	107	199	Idle	42.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:7	19.09	2871	1.7	13.39	107	198	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:7	19.09	2871	1.7	13.37	107	198	Idle	42.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:8	19.09	2866	1.7	13.37	107	198	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:8	19.09	2860	1.7	13.37	107	198	Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:8	19.09	2858	1.7	13.36	107	198	Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:8	19.09	2856	1.7	13.39	107	198	Idle	44	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:8	19.09	2852	1.7	13.39	107	198	Idle	44.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:8	19.09	2848	1.69	13.39	107	198	Idle	44.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:9	19.09	2844	1.69	13.4	107	198	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:9	19.09	2842	1.69	13.39	107	198	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:9	19.09	2841	1.68	13.4	107	198	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:9	19.09	2838	1.68	13.39	107	198	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:9	19.09	2836	1.68	13.39	107	198	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:9	19.09	2835	1.68	13.39	107	198	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:28:9	19.09	2834	1.67	13.38	107	198	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:0	19.09	2830	1.67	13.4	107	198	Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.16	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:0	19.09	2818	1.67	13.4	107	199	Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.15	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:0	19.09	2828	1.67	13.4	107	199	Idle	44.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.15	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:0	19.09	2828	1.67	13.39	107	199	Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.16	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:0	19.09	2829	1.67	13.38	107	198	Idle	45.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.15	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:0	19.09	2829	1.66	13.38	107	198	Idle	45.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.14	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:1	19.09	2838	1.66	13.38	107	198	Idle	45.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.15	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:1	19.09	2838	1.66	13.38	107	198	Idle	45.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.14	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:1	19.09	2837	1.66	13.39	107	198	Idle	46.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.14	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:1	19.09	2836	1.66	13.38	107	198	Idle	46.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:1	19.09	2836	1.66	13.38	107	198	Idle	46.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:1	19.09	2832	1.65	13.38	107	198	Idle	46.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:1	19.09	2819	1.65	13.38	107	198	Idle	46.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:2	19.09	2813	1.65	13.38	107	198	Idle	47.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:2	19.09	2802	1.65	13.38	107	198	Idle	47.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:2	19.09	2800	1.65	13.38	107	198	Idle	47.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:2	19.09	2784	1.64	13.37	107	198	Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:2	19.09	2771	1.64	13.38	107	198	Idle	47.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:2	19.09	2761	1.64	13.38	107	198	Idle	47.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:3	19.09	2758	1.64	13.39	107	199	Idle	47.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:3	19.09	2752	1.64	13.39	107	199	Idle	47.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:3	19.09	2752	1.64	13.39	107	199	Idle	47.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:3	19.09	2728	1.63	13.39	107	198	Idle	47.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:3	19.09	2751	1.63	13.39	107	198	Idle	47.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:3	19.09	2760	1.63	13.39	107	198	Idle	47	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:4	19.09	2762	1.63	13.39	107	198	Idle	46.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:4	19.09	2769	1.63	13.4	107	198	Idle	46.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:29:4	19.09	2774	1.63	13.4	107	198	Idle	47	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:4	19.09	2776	1.63	13.4	107	198	Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:4	19.09	2803	1.63	13.41	107	198	Idle	47.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:4	19.09	2782	1.63	13.41	107	198	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:4	19.09	2782	1.62	13.41	107	198	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:5	19.09	2791	1.62	13.41	107	198	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:5	19.09	2772	1.62	13.4	107	198	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:5	19.09	2764	1.61	13.4	107	198	Idle	49	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:5	19.09	2755	1.61	13.38	107	198	Idle	49.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:5	19.09	2755	1.6	13.38	107	198	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:5	19.09	2741	1.6	13.38	107	198	Idle	50.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:6	19.09	2746	1.6	13.38	107	198	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:6	19.09	2746	1.6	13.39	107	198	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:6	19.09	2742	1.59	13.39	107	198	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:6	19.09	2740	1.59	13.41	107	198	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:6	19.09	2740	1.59	13.41	107	198	Idle	50.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:6	19.09	2739	1.58	13.4	107	198	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:6	19.09	2740	1.58	13.4	107	198	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:7	19.09	2739	1.57	13.39	107	198	Idle	50.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:7	19.09	2739	1.57	13.4	107	198	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:7	19.09	2738	1.57	13.41	107	198	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:7	19.09	2736	1.56	13.4	107	198	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.11	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:7	19.09	2732	1.56	13.39	107	198	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.11	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:7	19.09	2731	1.56	13.4	107	198	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.11	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:8	19.09	2723	1.56	13.4	107	198	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.11	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:8	19.09	2714	1.56	13.4	107	198	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.11	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:8	19.09	2706	1.56	13.4	107	198	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.1	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:8	19.09	2704	1.56	13.4	107	198	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.1	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:8	19.09	2686	1.56	13.4	107	198	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.1	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:8	19.09	2690	1.56	13.39	107	198	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.1	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:9	19.09	2686	1.56	13.4	107	198	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.1	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:9	19.09	2684	1.55	13.4	107	198	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:9	19.09	2684	1.55	13.39	107	198	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:9	19.09	2682	1.55	13.38	107	198	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:9	19.09	2682	1.55	13.37	107	198	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:9	19.09	2681	1.55	13.38	107	198	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:29:9	19.09	2678	1.55	13.39	107	198	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:0	19.09	2679	1.54	13.4	107	198	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:0	19.09	2677	1.54	13.4	107	198	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:0	19.09	2676	1.54	13.41	107	198	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:0	19.09	2696	1.54	13.41	107	198	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:0	19.09	2686	1.54	13.4	107	198	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:0	19.09	2671	1.54	13.39	107	198	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:1	19.09	2647	1.54	13.39	107	198	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:1	19.09	2668	1.53	13.4	107	198	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:1	19.09	2668	1.53	13.39	107	198	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:1	19.09	2669	1.53	13.38	107	198	Idle	53.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:1	19.09	2669	1.53	13.39	107	198	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:1	19.09	2669	1.52	13.4	107	198	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:1	19.09	2670	1.52	13.4	107	198	Full Load	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:2	19.09	2669	1.52	13.4	107	198	Off Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:2	19.09	2670	1.52	13.4	107	198	Off Idle	55.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:2	9.54	2669	1.52	13.4	107	198	Off Idle	55.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:30:2	9.54	2608	1.52	13.4	107	199	Off Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:30:2	12.27	2685	1.52	13.39	107	199	Off Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:2	14.99	2679	1.52	13.38	107	199	Off Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:30:3	14.99	2679	1.52	13.39	107	198	Off Idle	56.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:30:3	17.72	2670	1.53	13.38	107	198	Off Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:30:3	20.45	2666	1.54	13.38	107	198	Off Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:30:3	23.18	2660	1.54	13.4	107	198	Off Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:30:3	23.18	2660	1.55	13.38	107	198	Off Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:30:3	25.9	2660	1.56	13.39	107	198	Off Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:30:4	25.9	2653	1.57	13.39	107	198	Off Idle	57.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:30:4	28.63	2669	1.58	13.38	107	198	Off Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.26	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:30:4	31.36	2673	1.6	13.38	107	198	Off Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:30:4	34.08	2680	1.62	13.38	107	198	Off Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.26	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:4	35.45	2685	1.62	13.39	107	198	Off Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:4	35.45	2685	1.64	13.39	107	198	Off Idle	57.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:4	35.45	2668	1.65	13.4	107	198	Off Idle	57.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:5	35.45	2670	1.66	13.4	107	198	Off Idle	57.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.26	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:30:5	35.45	2673	1.68	13.39	107	198	Off Idle	57.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	20.26	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:5	35.45	2672	1.69	13.39	107	198	Off Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	20.27	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:5	35.45	2670	1.7	13.39	107	199	Off Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.26	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:5	35.45	2665	1.71	13.38	107	199	Off Idle	57.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.41	20.26	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:5	35.45	2667	1.72	13.38	107	199	Off Idle	57.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.41	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:6	35.45	2670	1.73	13.37	107	198	Off Idle	57.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.36	20.26	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:6	35.45	2672	1.75	13.38	107	198	Off Idle	57.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.32	20.26	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:30:6	35.45	2672	1.76	13.38	107	198	Off Idle	57	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.27	20.26	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:6	35.45	2674	1.78	13.4	107	198	Off Idle	57	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.2	20.27	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:6	35.45	2678	1.8	13.38	107	198	Off Idle	56.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.09	20.26	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:6	35.45	2678	1.81	13.39	107	198	Off Idle	56.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	20.25	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:6	35.45	2678	1.82	13.39	107	198	Off Idle	56.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.88	20.26	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:7	35.45	2672	1.83	13.38	107	198	Off Idle	56.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.79	20.26	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:7	35.45	2667	1.84	13.38	107	199	Off Idle	56.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.69	20.27	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:7	35.45	2662	1.85	13.38	107	199	Off Idle	56.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.6	20.24	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:7	35.45	2663	1.86	13.38	107	199	Off Idle	56.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.57	20.13	1.37	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:7	35.45	2666	1.87	13.4	107	198	Off Idle	56.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.54	19.96	1.36	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:7	35.45	2666	1.88	13.41	107	198	Off Idle	55.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.52	19.75	1.35	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:8	35.45	2668	1.89	13.4	107	198	Off Idle	55.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.46	19.49	1.33	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:8	35.45	2670	1.9	13.41	107	199	Off Idle	55.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.4	19.04	1.3	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:30:8	35.45	2672	1.91	13.41	107	199	Off Idle	55.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.35	18.72	1.28	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:8	35.45	2673	1.93	13.4	107	199	Off Idle	55.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.31	18.37	1.25	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:8	35.45	2672	1.94	13.41	107	199	Off Idle	55.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.25	17.82	1.21	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:8	35.45	2672	1.95	13.4	107	199	Off Idle	55.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.27	17.48	1.19	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:9	35.45	2671	1.95	13.39	107	199	Off Idle	56.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.23	17.19	1.17	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:9	35.45	2667	1.96	13.38	107	198	Off Idle	56.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.21	16.96	1.16	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:9	35.45	2664	1.97	13.4	107	198	Off Idle	56.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.2	16.77	1.14	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:9	35.45	2656	1.97	13.41	107	198	Off Idle	56.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.18	16.62	1.13	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:9	35.45	2648	1.97	13.4	107	198	Off Idle	56.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.15	16.45	1.12	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:9	35.45	2641	1.97	13.39	107	198	Off Idle	56.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.1	16.36	1.11	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:30:9	35.45	2629	1.98	13.39	107	198	Off Idle	56.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.09	16.29	1.11	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:31:0	35.45	2630	1.98	13.4	107	198	Off Idle	57.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.06	16.2	1.1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:31:0	35.45	2629	1.98	13.4	107	198	Off Idle	57.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.03	16.13	1.1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:31:0	35.45	2632	1.99	13.39	107	198	Off Idle	57.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.99	16.05	1.09	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:31:0	35.45	2641	1.99	13.4	107	198	Off Idle	57.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.93	15.95	1.09	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:31:0	35.45	2647	1.99	13.39	107	198	Off Idle	57.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.92	15.88	1.08	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:31:0	35.45	2652	1.99	13.4	107	199	Off Idle	58	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.9	15.77	1.07	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:31:1	35.45	2656	1.99	13.41	107	199	Off Idle	58	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.88	15.72	1.07	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:31:1	35.45	2666	2	13.4	107	198	Off Idle	58	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.88	15.59	1.06	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:31:1	35.45	2682	2	13.39	107	198	Off Idle	58	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.84	15.52	1.06	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:31:1	35.45	2689	2.01	13.39	107	198	Off Idle	58.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.79	15.47	1.05	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:31:1	35.45	2692	2.02	13.38	107	198	Off Idle	57.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.7	15.42	1.05	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:31:1	35.45	2701	2.03	13.38	107	198	Off Idle	57.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.61	15.35	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:1	35.45	2712	2.04	13.38	107	198	Off Idle	57.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.56	15.31	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:2	35.45	2712	2.05	13.39	107	199	Off Idle	57.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.45	15.27	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:2	35.45	2716	2.06	13.39	107	199	Off Idle	56.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.37	15.24	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:31:2	35.45	2718	2.07	13.39	107	199	Off Idle	56	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.29	15.23	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:2	35.45	2715	2.09	13.38	107	199	Off Idle	55.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.2	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:2	35.45	2710	2.09	13.38	107	199	Off Idle	55.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.16	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:2	35.45	2709	2.1	13.38	107	199	Off Idle	55.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.11	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:3	35.45	2704	2.12	13.39	107	199	Off Idle	55.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.03	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:3	35.45	2697	2.13	13.39	107	199	Off Idle	54.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:3	35.45	2691	2.15	13.39	107	199	Off Idle	54.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.97	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:3	35.45	2688	2.16	13.39	107	199	Off Idle	54.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.97	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:3	35.45	2684	2.16	13.38	107	199	Off Idle	54.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.95	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:3	35.45	2686	2.17	13.38	107	199	Off Idle	54.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.96	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:4	35.45	2686	2.18	13.39	107	198	Off Idle	54.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.92	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:4	35.45	2687	2.19	13.38	107	198	Off Idle	54.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.86	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:4	35.45	2692	2.19	13.36	107	198	Off Idle	54.7	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.85	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:4	34.08	2682	2.19	13.37	107	199	Off Idle	54.9	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.85	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:4	34.08	2697	2.19	13.38	107	199	Off Idle	55	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.84	15.19	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:4	34.08	2701	2.19	13.38	107	199	Off Idle	55.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.87	15.21	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:4	34.08	2703	2.19	13.39	107	199	Off Idle	55.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.84	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:5	34.08	2708	2.19	13.38	107	199	Off Idle	55.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.82	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:5	34.08	2708	2.19	13.38	107	199	Off Idle	55.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.84	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:5	34.08	2710	2.19	13.38	107	199	Off Idle	55.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.83	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:5	34.08	2735	2.19	13.38	107	199	Off Idle	55.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.84	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:5	34.08	2719	2.2	13.38	107	198	Off Idle	55.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.82	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:5	34.08	2718	2.2	13.38	107	198	Off Idle	55.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.8	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:6	34.08	2718	2.2	13.38	107	198	Off Idle	55.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.83	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:6	34.08	2716	2.19	13.4	107	198	Off Idle	55.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.8	14.66	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:6	34.08	2703	2.19	13.39	107	198	Off Idle	54.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.83	14.6	0.99	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:6	34.08	2714	2.19	13.37	107	198	Off Idle	54.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.82	14.58	0.99	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:6	34.08	2714	2.19	13.38	107	199	Off Idle	54.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.82	14.57	0.99	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:6	34.08	2716	2.19	13.37	107	199	Off Idle	54.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.83	14.55	0.99	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:6	34.08	2739	2.19	13.37	107	199	Off Idle	54.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.86	14.55	0.99	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:7	34.08	2713	2.2	13.35	107	199	Off Idle	54.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.85	14.57	0.99	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:7	34.08	2716	2.2	13.36	107	199	Off Idle	54.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.79	14.59	0.99	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:7	34.08	2720	2.2	13.37	107	198	Off Idle	54.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.84	14.62	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:7	34.08	2720	2.2	13.35	107	198	Off Idle	54.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.8	14.66	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:7	34.08	2722	2.2	13.36	107	198	Off Idle	54.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.79	14.69	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:7	35.45	2737	2.2	13.38	107	198	Off Idle	54	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.82	14.72	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:8	35.45	2731	2.2	13.37	107	198	Off Idle	53.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.79	14.76	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:8	35.45	2735	2.2	13.37	107	198	Off Idle	53.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.82	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:8	35.45	2744	2.2	13.38	107	198	Off Idle	53.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.79	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:8	35.45	2749	2.2	13.36	107	199	Off Idle	53.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.82	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:8	35.45	2755	2.2	13.36	107	199	Off Idle	53.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.85	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:8	35.45	2757	2.2	13.36	107	198	Off Idle	53.4	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.83	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:9	35.45	2760	2.2	13.36	107	198	Off Idle	53.1	0	2	132	944 Turbo	0.18	Rich	1	14.6	-6.85	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:9	35.45	2761	2.2	13.36	107	198	Off Idle	53	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.84	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:31:9	35.45	2756	2.2	13.36	107	199	Off Idle	53	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.79	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:9	35.45	2756	2.2	13.38	107	199	Off Idle	52.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.8	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:9	35.45	2755	2.21	13.39	107	199	Off Idle	52.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.8	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:31:9	35.45	2750	2.21	13.39	107	199	Off Idle	52.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.77	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:31:9	35.45	2748	2.21	13.39	107	199	Off Idle	52.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.78	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:0	35.45	2738	2.21	13.39	107	199	Off Idle	52.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.78	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:0	35.45	2735	2.21	13.39	107	199	Off Idle	52.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.75	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:0	35.45	2735	2.21	13.38	107	199	Off Idle	52.1	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.76	15.12	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:0	35.45	2735	2.21	13.39	107	199	Off Idle	52.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.76	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:0	35.45	2740	2.21	13.39	107	199	Off Idle	52.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.75	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:0	35.45	2746	2.21	13.39	107	199	Off Idle	52.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.75	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:1	35.45	2755	2.21	13.41	107	199	Off Idle	52.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.72	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:1	35.45	2755	2.22	13.41	107	199	Off Idle	52.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.75	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:1	35.45	2767	2.22	13.41	107	199	Off Idle	52.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.75	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:32:1	35.45	2775	2.22	13.39	107	199	Off Idle	52.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.72	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:1	35.45	2779	2.22	13.39	107	199	Off Idle	52.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.73	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:1	35.45	2780	2.22	13.39	107	199	Off Idle	52.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.76	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:1	35.45	2781	2.22	13.38	107	199	Off Idle	52.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.74	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:2	35.45	2781	2.22	13.39	107	199	Off Idle	51.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.78	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:2	35.45	2777	2.22	13.39	107	199	Off Idle	51.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.73	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:2	35.45	2768	2.22	13.41	107	198	Off Idle	51.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.73	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:2	35.45	2768	2.22	13.39	107	198	Off Idle	51.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.74	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:2	35.45	2768	2.22	13.4	107	198	Off Idle	51.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.71	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:2	35.45	2772	2.22	13.38	107	198	Off Idle	51.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.72	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:3	35.45	2777	2.22	13.38	107	198	Off Idle	51	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.71	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:3	35.45	2778	2.22	13.38	107	198	Off Idle	50.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.72	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:3	35.45	2778	2.22	13.39	107	198	Off Idle	50.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.68	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:3	35.45	2784	2.22	13.38	107	198	Off Idle	50.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.7	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:3	35.45	2781	2.23	13.39	107	199	Off Idle	50.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.68	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:3	35.45	2783	2.23	13.37	107	199	Off Idle	50.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.69	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:32:4	35.45	2788	2.23	13.38	107	199	Off Idle	50.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.71	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:32:4	35.45	2797	2.23	13.39	107	198	Off Idle	50.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.73	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:32:4	35.45	2797	2.23	13.39	107	198	Off Idle	50.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.72	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:4	35.45	2794	2.23	13.4	107	198	Off Idle	50.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.71	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:4	35.45	2794	2.23	13.39	107	198	Off Idle	50.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.68	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:4	35.45	2797	2.23	13.39	107	198	Off Idle	50.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.68	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:4	35.45	2803	2.24	13.4	107	199	Off Idle	50	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.64	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:5	35.45	2803	2.24	13.4	107	199	Off Idle	49.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.64	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:5	35.45	2801	2.24	13.4	107	199	Off Idle	49.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.64	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:5	35.45	2828	2.24	13.41	107	199	Off Idle	49.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.62	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:5	35.45	2808	2.24	13.4	107	199	Off Idle	49.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.64	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:5	35.45	2805	2.24	13.41	107	199	Off Idle	49.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.64	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:5	35.45	2805	2.24	13.41	107	199	Off Idle	49.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.65	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:6	35.45	2802	2.24	13.42	107	198	Off Idle	49.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.64	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:6	35.45	2803	2.25	13.41	107	198	Off Idle	49.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.63	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:6	35.45	2804	2.25	13.41	107	198	Off Idle	49.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.61	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:6	35.45	2805	2.25	13.4	107	198	Off Idle	49.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.61	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:6	35.45	2807	2.25	13.38	107	198	Off Idle	49.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.62	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:6	35.45	2807	2.25	13.37	107	198	Off Idle	49.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.62	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:6	35.45	2798	2.25	13.37	107	198	Off Idle	49.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.64	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:7	35.45	2814	2.25	13.36	107	198	Off Idle	49.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.68	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:7	35.45	2812	2.25	13.39	107	198	Off Idle	49.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.67	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:7	35.45	2806	2.25	13.37	107	198	Off Idle	49.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.69	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:7	35.45	2813	2.25	13.37	107	198	Off Idle	49.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.68	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:7	35.45	2812	2.25	13.38	107	199	Off Idle	49.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.68	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:7	35.45	2814	2.25	13.39	107	199	Off Idle	49.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.71	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:8	35.45	2817	2.25	13.39	107	199	Off Idle	49.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.71	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:8	35.45	2818	2.25	13.37	107	199	Off Idle	49.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.67	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:8	35.45	2825	2.25	13.37	107	199	Off Idle	49.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.69	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:8	35.45	2830	2.25	13.39	107	199	Off Idle	49	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.69	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:8	35.45	2830	2.25	13.39	107	199	Off Idle	48.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.67	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:8	35.45	2840	2.25	13.39	107	199	Off Idle	48.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.72	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:9	35.45	2854	2.25	13.39	107	199	Off Idle	48.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.74	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:9	35.45	2854	2.25	13.39	107	198	Off Idle	48.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.73	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:9	35.45	2845	2.25	13.4	107	198	Off Idle	48.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.75	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:9	35.45	2844	2.25	13.38	107	198	Off Idle	47.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.7	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:9	35.45	2844	2.25	13.39	107	199	Off Idle	47.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.7	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:32:9	35.45	2847	2.25	13.38	107	199	Off Idle	47.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.71	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:32:9	35.45	2847	2.25	13.4	107	199	Off Idle	47	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.72	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:0	35.45	2846	2.25	13.4	107	199	Off Idle	47	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.75	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:0	35.45	2842	2.25	13.4	107	199	Off Idle	47	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.73	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:0	35.45	2864	2.25	13.41	107	198	Off Idle	46.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.7	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:33:0	35.45	2852	2.25	13.41	107	198	Off Idle	46.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.7	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:0	35.45	2837	2.25	13.39	107	198	Off Idle	46.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.64	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:0	35.45	2842	2.25	13.39	107	198	Off Idle	46.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.64	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:1	35.45	2845	2.25	13.39	107	199	Off Idle	46.7	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.64	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:1	35.45	2852	2.25	13.37	107	199	Off Idle	46.8	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.64	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:33:1	35.45	2853	2.25	13.37	107	199	Off Idle	46.9	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.64	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:33:1	35.45	2857	2.26	13.39	108	199	Off Idle	46.9	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.65	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:33:1	35.45	2863	2.26	13.39	108	199	Off Idle	46.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.63	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:33:1	35.45	2866	2.26	13.38	108	199	Off Idle	46.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.63	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:33:1	35.45	2882	2.26	13.39	107	199	Off Idle	46.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.67	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:33:2	35.45	2877	2.26	13.39	107	199	Off Idle	47	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.68	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:33:2	35.45	2875	2.26	13.4	107	198	Off Idle	46.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.69	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:2	35.45	2875	2.26	13.39	108	198	Off Idle	46.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.66	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:2	35.45	2884	2.26	13.39	108	198	Off Idle	46.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.64	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:2	35.45	2867	2.26	13.37	108	199	Off Idle	46.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.6	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:2	35.45	2867	2.27	13.39	108	199	Off Idle	46.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.54	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:33:3	35.45	2866	2.27	13.38	108	199	Off Idle	45.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.47	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:33:3	35.45	2858	2.28	13.37	107	199	Off Idle	45.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.41	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:33:3	35.45	2863	2.28	13.37	107	199	Off Idle	45.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.31	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:33:3	35.45	2863	2.29	13.39	107	199	Off Idle	45.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.27	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:33:3	35.45	2872	2.29	13.38	107	199	Off Idle	45.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.2	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:33:3	35.45	2882	2.3	13.38	107	199	Off Idle	45.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.1	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:33:4	35.45	2893	2.31	13.39	107	199	Off Idle	45.1	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.08	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:33:4	35.45	2906	2.32	13.4	107	199	Off Idle	45.1	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:4	35.45	2906	2.33	13.4	107	199	Off Idle	45.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.97	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:4	35.45	2918	2.34	13.39	107	198	Off Idle	45	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.91	14.9	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:4	35.45	2918	2.35	13.39	107	198	Off Idle	45	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.81	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:4	35.45	2943	2.36	13.37	107	198	Off Idle	45	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.77	14.74	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:4	35.45	2921	2.37	13.39	107	198	Off Idle	44.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.71	14.75	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:5	35.45	2920	2.37	13.4	107	198	Off Idle	44.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.65	14.76	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:33:5	35.45	2919	2.39	13.41	107	198	Off Idle	44.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.6	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:5	35.45	2915	2.4	13.39	107	198	Off Idle	44.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.54	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:5	34.08	2903	2.41	13.39	107	198	Off Idle	44.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.49	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:5	34.08	2900	2.41	13.39	107	199	Off Idle	44	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.49	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:5	34.08	2900	2.42	13.38	107	199	Off Idle	43.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.44	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:6	34.08	2899	2.43	13.38	107	199	Off Idle	43.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.45	15.13	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:6	34.08	2883	2.43	13.38	107	198	Off Idle	43.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.4	15.17	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:6	34.08	2883	2.44	13.38	107	198	Off Idle	43.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.38	15.17	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:6	34.08	2913	2.45	13.38	107	198	Off Idle	43.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.3	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:6	34.08	2921	2.46	13.36	107	198	Off Idle	43.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.29	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:6	34.08	2922	2.46	13.38	107	198	Off Idle	43.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.29	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:6	34.08	2940	2.47	13.39	107	198	Off Idle	43.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.3	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:7	34.08	2940	2.47	13.38	107	198	Off Idle	43.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.35	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:7	34.08	2934	2.48	13.38	107	198	Off Idle	43.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.33	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:7	34.08	2938	2.48	13.36	107	199	Off Idle	43.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.31	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:7	34.08	2944	2.48	13.37	107	199	Off Idle	43.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.24	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:33:7	34.08	2944	2.49	13.38	107	199	Off Idle	43.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.19	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:33:7	34.08	2945	2.49	13.4	107	199	Off Idle	43.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.18	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:8	34.08	2942	2.5	13.4	107	199	Off Idle	43	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.12	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:8	34.08	2942	2.5	13.41	107	199	Off Idle	42.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.08	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:8	34.08	2948	2.51	13.41	107	198	Off Idle	42.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.09	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:8	34.08	2953	2.51	13.4	107	198	Off Idle	42.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.03	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:8	34.08	2953	2.52	13.4	108	198	Off Idle	42.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.98	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:33:8	34.08	2960	2.52	13.4	108	198	Off Idle	42.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.93	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:33:9	34.08	2970	2.53	13.41	108	198	Off Idle	41.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.91	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:9	34.08	2970	2.54	13.39	107	198	Off Idle	41.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.87	14.89	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:9	34.08	2967	2.54	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.83	14.91	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:9	34.08	2967	2.54	13.37	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.82	14.96	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:33:9	35.45	2981	2.55	13.35	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.6	-4.79	15.02	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:9	35.45	2968	2.56	13.38	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.67	Lean	1	14.6	-4.75	15.04	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:33:9	35.45	2974	2.56	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.72	15.04	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:0	35.45	2978	2.57	13.37	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.72	15.01	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:0	35.45	2994	2.57	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.66	14.98	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:0	35.45	3002	2.58	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.67	14.93	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:0	35.45	3000	2.58	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.66	14.88	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:0	35.45	3000	2.59	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.66	14.8	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:0	35.45	2996	2.59	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.65	14.75	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:1	35.45	3004	2.6	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.69	14.69	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:34:1	35.45	3004	2.6	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.67	14.66	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:34:1	35.45	3010	2.6	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.65	14.66	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:34:1	35.45	3015	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.65	14.66	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:1	35.45	3014	2.61	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.67	14.69	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:1	35.45	3023	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.67	14.71	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:1	35.45	3010	2.61	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.69	14.74	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:2	35.45	3006	2.61	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.67	14.74	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:2	35.45	3004	2.61	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.66	14.78	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:2	35.45	2994	2.61	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.67	14.76	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:2	35.45	3014	2.61	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.73	14.79	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:2	34.08	3003	2.61	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.76	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:2	34.08	3019	2.61	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.83	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:3	34.08	3024	2.61	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.78	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:3	34.08	3024	2.61	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.82	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:3	34.08	3024	2.61	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.79	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:3	35.45	3040	2.6	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.8	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:3	35.45	3029	2.6	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.84	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:3	35.45	3034	2.6	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.83	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:4	35.45	3040	2.6	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.85	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:4	35.45	3040	2.6	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.89	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:4	35.45	3056	2.6	13.42	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.89	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:4	35.45	3056	2.59	13.41	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.88	14.88	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:4	35.45	3057	2.59	13.41	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.87	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:4	35.45	3057	2.59	13.41	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.87	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:4	35.45	3066	2.59	13.4	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.94	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:5	35.45	3078	2.59	13.41	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.94	14.9	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:5	35.45	3078	2.59	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.95	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:5	35.45	3083	2.59	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.96	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:5	35.45	3090	2.59	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.96	14.94	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:5	35.45	3081	2.59	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.95	14.96	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:5	35.45	3081	2.59	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.95	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:6	35.45	3072	2.6	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.95	15.05	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:6	35.45	3072	2.6	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.94	15.07	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:6	35.45	3072	2.6	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.91	15.05	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:6	35.45	3081	2.6	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.92	15.04	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:6	35.45	3088	2.6	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.92	15.02	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:6	35.45	3098	2.6	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.98	15	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:34:6	35.45	3098	2.6	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.93	14.98	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:34:7	35.45	3101	2.6	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5	14.94	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:34:7	35.45	3109	2.6	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.97	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:7	35.45	3110	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.98	14.84	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:7	35.45	3111	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.98	14.84	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:7	35.45	3111	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.97	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:7	35.45	3110	2.61	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.98	14.87	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:8	35.45	3113	2.61	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.97	14.91	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:8	35.45	3110	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.95	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:8	35.45	3110	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-4.94	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:8	35.45	3101	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.94	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:34:8	35.45	3101	2.61	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-4.97	15.01	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:8	35.45	3109	2.61	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.93	15.03	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:9	35.45	3112	2.61	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.95	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:9	35.45	3129	2.61	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.98	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:9	35.45	3136	2.61	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.98	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:34:9	35.45	3141	2.61	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.98	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:34:9	35.45	3142	2.61	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.94	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:34:9	35.45	3143	2.62	13.41	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.91	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:34:9	35.45	3145	2.62	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.94	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:0	35.45	3148	2.62	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.97	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:0	35.45	3149	2.62	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.98	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:0	35.45	3149	2.62	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.97	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:0	35.45	3153	2.62	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.96	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:0	35.45	3153	2.62	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.97	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:0	35.45	3154	2.62	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.93	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:35:1	35.45	3154	2.62	13.37	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.97	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:35:1	35.45	3143	2.62	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:35:1	35.45	3142	2.62	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.01	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:35:1	35.45	3146	2.62	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.06	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:35:1	35.45	3149	2.62	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.07	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:1	35.45	3166	2.62	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.08	15.15	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:1	35.45	3153	2.62	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.07	15.13	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:2	35.45	3153	2.61	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.08	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:2	35.45	3161	2.61	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.09	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:2	35.45	3175	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.1	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:2	35.45	3177	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.18	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:2	35.45	3182	2.61	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.14	14.89	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:35:2	35.45	3187	2.6	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.18	14.81	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:35:3	35.45	3187	2.6	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.24	14.79	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:3	35.45	3188	2.6	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.21	14.77	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:3	35.45	3196	2.59	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.3	14.76	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:3	35.45	3196	2.59	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.34	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:3	35.45	3200	2.59	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.36	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:3	35.45	3203	2.58	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.4	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:4	35.45	3204	2.58	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.45	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:4	35.45	3204	2.57	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.47	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:4	35.45	3200	2.57	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.5	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:4	35.45	3207	2.57	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.5	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:4	35.45	3207	2.57	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.52	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:4	35.45	3209	2.57	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.5	15.06	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:35:4	35.45	3207	2.57	13.39	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.49	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:35:5	35.45	3194	2.56	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.51	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:35:5	35.45	3206	2.56	13.38	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.51	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:35:5	35.45	3202	2.56	13.39	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.52	15.14	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:35:5	35.45	3213	2.56	13.39	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.59	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:5	35.45	3203	2.56	13.38	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.52	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:5	35.45	3208	2.56	13.39	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.52	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:6	35.45	3208	2.55	13.38	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.53	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:6	35.45	3208	2.55	13.38	107	198	Off Idle	41.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-5.51	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:6	35.45	3216	2.55	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.17	Rich	1	14.6	-5.53	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:6	35.45	3216	2.55	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.57	14.89	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:6	35.45	3228	2.55	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.54	14.89	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:6	35.45	3234	2.55	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.58	14.92	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:6	35.45	3236	2.55	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.55	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:7	35.45	3242	2.55	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.55	15.05	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:7	35.45	3240	2.56	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.54	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:7	35.45	3243	2.56	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.5	15.16	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:7	35.45	3243	2.56	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.43	15.22	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:35:7	35.45	3234	2.57	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.37	15.23	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:7	35.45	3244	2.57	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.36	15.23	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:8	35.45	3247	2.57	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.35	15.25	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:8	35.45	3249	2.58	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.33	15.24	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:8	35.45	3249	2.58	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.29	15.21	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:8	35.45	3253	2.59	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.23	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:8	35.45	3265	2.59	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.11	15.11	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:8	35.45	3265	2.6	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.07	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:35:9	35.45	3266	2.61	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.97	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:35:9	35.45	3266	2.61	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.94	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:35:9	35.45	3272	2.62	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.91	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:35:9	35.45	3272	2.63	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.88	14.91	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:35:9	35.45	3286	2.63	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.86	14.88	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:35:9	35.45	3286	2.64	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.86	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:35:9	35.45	3292	2.65	13.4	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.72	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:36:0	35.45	3296	2.66	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.72	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:36:0	35.45	3299	2.66	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.71	14.9	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:0	35.45	3298	2.67	13.37	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.74	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:0	35.45	3306	2.67	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.73	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:0	35.45	3291	2.68	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.79	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:0	35.45	3289	2.68	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-4.75	15.03	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:36:1	35.45	3290	2.69	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.63	Lean	1	14.6	-4.66	15.04	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:36:1	35.45	3290	2.69	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.61	15.03	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:36:1	35.45	3290	2.7	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.65	15.01	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:36:1	35.45	3287	2.7	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.58	14.99	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:1	35.45	3288	2.7	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.63	14.95	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:1	35.45	3299	2.7	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.64	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:1	35.45	3310	2.71	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.69	14.79	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:2	35.45	3312	2.71	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.63	14.69	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:2	35.45	3318	2.71	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.71	14.63	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:2	35.45	3320	2.7	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.68	14.61	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:2	35.45	3321	2.7	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.75	14.6	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:2	35.45	3322	2.7	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.74	14.59	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:2	35.45	3316	2.7	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.81	14.6	0.99	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:3	35.45	3312	2.7	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.82	14.62	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:3	35.45	3312	2.7	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.87	14.64	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:3	35.45	3312	2.7	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.89	14.63	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:3	35.45	3315	2.7	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.91	14.64	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:3	35.45	3315	2.69	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.93	14.64	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:3	35.45	3322	2.69	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.98	14.63	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:4	35.45	3328	2.69	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.94	14.62	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:4	35.45	3328	2.69	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.93	14.63	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:4	35.45	3338	2.68	13.38	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.95	14.65	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:4	35.45	3344	2.68	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.95	14.69	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:4	35.45	3354	2.68	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.97	14.7	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:4	35.45	3354	2.68	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.98	14.72	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:4	35.45	3386	2.68	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.97	14.74	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:5	35.45	3355	2.68	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.97	14.79	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:5	35.45	3361	2.67	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.98	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:5	35.45	3360	2.67	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.03	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:5	35.45	3360	2.67	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.06	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:5	35.45	3361	2.67	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.1	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:5	35.45	3362	2.67	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.18	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:6	35.45	3363	2.67	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.16	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:6	35.45	3376	2.67	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.18	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:6	35.45	3363	2.67	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.14	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:6	35.45	3363	2.67	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.13	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:6	35.45	3358	2.67	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.15	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:36:6	35.45	3352	2.66	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.18	15.17	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:6	35.45	3354	2.66	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.21	15.18	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:7	35.45	3354	2.66	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.2	15.17	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:7	35.45	3352	2.66	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Lean	1	14.6	-5.2	15.16	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:7	35.45	3361	2.66	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.2	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:7	35.45	3372	2.66	13.41	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.16	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:7	35.45	3372	2.66	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.2	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:7	35.45	3370	2.66	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.19	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:8	35.45	3396	2.66	13.38	107	199	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.27	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:8	35.45	3391	2.66	13.39	108	199	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.2	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:8	35.45	3392	2.66	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.23	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:8	35.45	3400	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.24	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:36:8	35.45	3406	2.65	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.23	14.75	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:8	35.45	3408	2.65	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.24	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:9	35.45	3414	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.29	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:9	35.45	3420	2.65	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.33	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:9	35.45	3414	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.3	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:36:9	35.45	3413	2.65	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.38	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:9	35.45	3406	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.31	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:9	35.45	3408	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.36	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:36:9	35.45	3397	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.33	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:0	35.45	3397	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.36	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:0	35.45	3392	2.65	13.37	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.32	15.17	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:0	35.45	3388	2.65	13.39	107	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.4	15.14	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:0	35.45	3391	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.38	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:0	35.45	3391	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.38	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:0	35.45	3399	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.34	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:1	35.45	3407	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.37	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:37:1	35.45	3430	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.35	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:1	36.81	3434	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.35	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:37:1	36.81	3433	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.33	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:1	36.81	3438	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.34	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:1	36.81	3440	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.33	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:1	35.45	3432	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.37	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:2	35.45	3444	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.37	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:2	35.45	3432	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.41	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:2	35.45	3430	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.38	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:2	36.81	3440	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.44	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:2	36.81	3425	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.38	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:2	36.81	3426	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.37	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:3	36.81	3442	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.35	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:3	36.81	3434	2.65	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.32	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:3	36.81	3427	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-5.41	14.9	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:3	36.81	3430	2.65	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.38	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:3	36.81	3441	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.46	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:3	36.81	3444	2.65	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.46	14.78	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:4	36.81	3456	2.65	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.44	14.76	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:4	36.81	3466	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.49	14.74	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:4	36.81	3470	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.48	14.74	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:4	36.81	3480	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.48	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:4	36.81	3481	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.49	14.77	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:4	36.81	3480	2.65	13.37	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.5	14.79	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:4	36.81	3479	2.65	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.57	14.82	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:5	36.81	3477	2.65	13.39	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.54	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:5	36.81	3440	2.65	13.39	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.57	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:5	35.45	3451	2.65	13.37	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.59	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:5	35.45	3458	2.65	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.57	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:5	35.45	3422	2.65	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.56	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:37:5	35.45	3447	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.55	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:6	36.81	3461	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.54	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:6	36.81	3447	2.65	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.53	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:6	36.81	3447	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.52	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:6	36.81	3468	2.65	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	-5.52	14.9	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:6	36.81	3481	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.6	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:6	35.45	3489	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.53	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:6	35.45	3498	2.65	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.53	14.75	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:7	35.45	3524	2.65	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.54	14.74	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:7	35.45	3498	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.57	14.72	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:7	35.45	3502	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.53	14.71	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:7	35.45	3502	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.59	14.74	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:7	35.45	3491	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.61	14.79	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:7	35.45	3502	2.65	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.61	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:37:8	35.45	3502	2.64	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.64	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:8	35.45	3498	2.64	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.67	14.9	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:8	35.45	3496	2.64	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.69	14.93	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:8	35.45	3490	2.64	13.42	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.67	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:8	36.81	3489	2.64	13.43	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.66	15.04	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:8	36.81	3500	2.64	13.43	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.66	15.08	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:9	36.81	3496	2.64	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.6	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:37:9	36.81	3503	2.64	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.59	15.05	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:9	36.81	3506	2.64	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.63	15.03	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:9	36.81	3512	2.64	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.61	14.99	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:9	36.81	3512	2.64	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.69	14.95	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:9	36.81	3514	2.64	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.69	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:37:9	36.81	3516	2.64	13.43	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.68	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:38:0	36.81	3523	2.64	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.77	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:38:0	36.81	3522	2.63	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.92	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:38:0	36.81	3522	2.62	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.07	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:38:0	36.81	3517	2.59	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.47	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:38:0	36.81	3514	2.57	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.81	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:38:0	36.81	3503	2.51	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.3	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:38:1	36.81	3492	2.47	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.65	14.9	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:38:1	36.81	3492	2.4	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.05	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:38:1	36.81	3478	2.38	13.41	108	198	Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.52	14.95	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:38:1	38.18	3478	2.33	13.4	108	198	Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.83	14.97	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:1	38.18	3453	2.28	13.39	108	198	Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.04	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:1	38.18	3450	2.22	13.39	108	198	Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.37	15.08	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:1	38.18	3434	2.17	13.39	108	198	Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.53	15.08	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:38:2	35.45	3362	2.12	13.41	108	198	Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.62	15.06	1.03	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:2	35.45	3338	2.08	13.41	108	198	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.66	15	1.02	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:2	29.99	3308	2.03	13.41	108	198	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.75	14.91	1.02	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:2	24.54	3310	1.94	13.4	108	198	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.82	14.65	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:2	20.45	3320	1.89	13.39	108	198	Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.86	14.57	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:2	20.45	3298	1.83	13.38	108	198	Idle	41.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.87	14.41	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:3	20.45	3278	1.79	13.39	108	198	Idle	41	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.84	14.09	0.96	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:3	20.45	3262	1.76	13.38	108	198	Idle	40.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.86	13.99	0.95	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:3	20.45	3222	1.74	13.4	108	198	Idle	40	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.81	13.75	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:3	20.45	3145	1.73	13.41	108	198	Idle	39.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.79	13.61	0.93	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:3	20.45	3162	1.72	13.42	108	198	Idle	38.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.75	13.49	0.92	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:3	20.45	3154	1.71	13.41	108	198	Idle	38	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.72	13.43	0.91	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:4	20.45	3154	1.71	13.4	108	198	Idle	37.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.65	13.38	0.91	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:4	20.45	3096	1.72	13.41	108	198	Idle	36.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	13.37	0.91	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:4	20.45	3071	1.72	13.39	108	198	Idle	35.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.51	13.4	0.91	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:4	20.45	3014	1.73	13.39	108	198	Idle	34.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.49	13.45	0.92	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:4	19.09	3018	1.73	13.39	108	198	Idle	33.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.43	13.54	0.92	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:4	19.09	2997	1.74	13.39	108	198	Idle	32.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.44	13.63	0.93	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:38:4	19.09	2928	1.74	13.39	108	198	Idle	30.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.4	13.73	0.94	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:5	19.09	2942	1.75	13.4	108	198	Idle	29.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.35	13.92	0.95	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:5	19.09	2906	1.75	13.4	108	198	Idle	28.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.31	14.02	0.96	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:5	19.09	2894	1.76	13.4	108	198	Idle	28.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.27	14.13	0.96	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:5	19.09	2886	1.77	13.4	108	198	Idle	27.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.22	14.26	0.97	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:5	19.09	2843	1.78	13.4	108	198	Idle	27.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.15	14.51	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:5	19.09	2821	1.78	13.4	108	198	Idle	26.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.12	14.71	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:6	19.09	2774	1.79	13.4	108	198	Idle	26.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.07	14.96	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:6	19.09	2778	1.79	13.39	108	198	Idle	26.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.04	15.26	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:6	19.09	2754	1.8	13.39	108	198	Idle	27	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.02	15.65	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:6	19.09	2722	1.81	13.4	108	198	Idle	27.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.97	16.4	1.12	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:6	19.09	2697	1.81	13.39	108	198	Idle	27.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.95	16.9	1.15	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:6	19.09	2697	1.81	13.4	108	198	Idle	27.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.95	17.47	1.19	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:6	19.09	2634	1.82	13.39	108	198	Idle	28.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	18	1.23	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:7	19.09	2630	1.82	13.38	108	198	Idle	28.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	18.74	1.28	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:7	19.09	2622	1.82	13.38	107	198	Idle	30.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.87	19.17	1.31	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:7	19.09	2579	1.82	13.38	107	198	Idle	31	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.83	19.72	1.34	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:7	19.09	2570	1.82	13.38	108	198	Full Load	31.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.79	19.98	1.36	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:7	19.09	2545	1.82	13.36	108	198	Off Idle	32.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.76	20.13	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:7	19.09	2511	1.82	13.38	108	198	Off Idle	33.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.74	20.18	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:38:8	19.09	2495	1.82	13.38	108	198	Off Idle	34.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.7	20.25	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:38:8	9.54	2422	1.82	13.38	108	198	Off Idle	36.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.63	20.25	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:38:8	12.27	2441	1.83	13.39	108	198	Off Idle	38.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.46	20.26	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:14:38:8	12.27	2442	1.84	13.39	108	198	Off Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.35	20.07	1.37	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:14:38:8	14.99	2428	1.85	13.38	108	198	Off Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.22	20.08	1.37	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:38:8	14.99	2417	1.85	13.38	108	198	Off Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.1	20.08	1.37	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:38:9	17.72	2339	1.86	13.4	108	198	Off Idle	49.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8	20.08	1.37	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:38:9	17.72	2339	1.85	13.4	108	198	Off Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.95	20.07	1.37	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:38:9	20.45	2359	1.85	13.4	108	198	Off Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.9	20.07	1.37	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:38:9	23.18	2369	1.85	13.41	108	198	Off Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.86	20.07	1.37	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:38:9	23.18	2383	1.86	13.39	108	198	Off Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.8	20.06	1.37	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:38:9	25.9	2383	1.89	13.38	108	198	Off Idle	64.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.72	20.06	1.37	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:14:38:9	28.63	2398	1.9	13.38	108	198	Off Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.59	20.24	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:0	28.63	2404	1.92	13.37	108	198	Off Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.38	20.24	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:39:0	31.36	2408	1.93	13.38	108	198	Off Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.16	20.24	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:39:0	34.08	2410	1.95	13.38	108	198	Off Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7	20.25	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:39:0	34.08	2405	1.98	13.37	108	198	Off Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.85	20.25	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:39:0	34.08	2424	2.01	13.37	108	198	Off Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.58	20.25	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:39:0	34.08	2447	2.03	13.39	108	198	Off Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.47	20.25	1.38	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:39:1	34.08	2464	2.04	13.38	108	198	Off Idle	72.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.39	20.25	1.38	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:39:1	34.08	2465	2.06	13.39	108	198	Off Idle	72.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.25	20.26	1.38	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:39:1	34.08	2466	2.07	13.4	108	198	Off Idle	72.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.2	20.25	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:39:1	34.08	2451	2.08	13.39	108	198	Off Idle	72	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.15	20.25	1.38	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:39:1	34.08	2438	2.1	13.38	108	198	Off Idle	70.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.04	20.25	1.38	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:39:1	34.08	2386	2.13	13.37	108	198	Off Idle	70.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.91	20.24	1.38	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:1	34.08	2353	2.16	13.35	108	198	Off Idle	70.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.81	20.16	1.37	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:2	34.08	2353	2.18	13.37	108	198	Off Idle	70.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.61	19.95	1.36	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:2	34.08	2329	2.19	13.38	108	198	Off Idle	70.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.56	19.75	1.35	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:2	34.08	2330	2.21	13.4	108	198	Off Idle	70.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.47	19.39	1.32	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:2	34.08	2332	2.21	13.41	108	198	Off Idle	70.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.41	19.12	1.3	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:2	32.72	2373	2.22	13.42	108	198	Off Idle	70.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.44	18.81	1.28	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:2	32.72	2414	2.22	13.41	108	198	Off Idle	70.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.42	18.27	1.24	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:3	32.72	2421	2.23	13.4	108	198	Off Idle	70.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.39	18.08	1.23	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:3	32.72	2438	2.23	13.4	108	198	Off Idle	71.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.37	17.67	1.2	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:3	32.72	2441	2.23	13.38	108	198	Off Idle	71.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.37	17.31	1.18	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:3	32.72	2444	2.24	13.39	108	198	Off Idle	71.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.31	16.86	1.15	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:3	32.72	2439	2.24	13.38	108	198	Off Idle	71.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.31	16.74	1.14	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:3	32.72	2405	2.25	13.38	108	198	Off Idle	71.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.23	16.39	1.12	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:39:4	32.72	2379	2.25	13.4	108	198	Off Idle	71.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.19	16.28	1.11	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:4	32.72	2379	2.26	13.4	108	198	Off Idle	71.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.15	16.09	1.1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:4	32.72	2373	2.26	13.38	108	198	Off Idle	71.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.11	15.91	1.08	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:4	32.72	2355	2.26	13.39	108	198	Off Idle	71.8	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.08	15.77	1.07	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:4	32.72	2364	2.26	13.4	108	198	Off Idle	71.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-4.98	15.59	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:4	32.72	2385	2.26	13.39	108	198	Off Idle	71.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.99	15.49	1.06	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:4	32.72	2401	2.26	13.4	108	198	Off Idle	71.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.02	15.4	1.05	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:5	32.72	2407	2.26	13.41	108	198	Off Idle	71.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.02	15.33	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:5	32.72	2441	2.27	13.41	108	198	Off Idle	71.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.05	15.25	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:5	32.72	2436	2.27	13.4	108	198	Off Idle	71.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.07	15.2	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:5	32.72	2436	2.28	13.4	108	198	Off Idle	71.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5	15.16	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:5	32.72	2434	2.28	13.4	108	198	Off Idle	71.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.02	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:5	32.72	2425	2.28	13.41	108	198	Off Idle	71.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.01	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:6	32.72	2414	2.28	13.39	108	198	Off Idle	71.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:6	32.72	2410	2.28	13.39	108	198	Off Idle	71.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.97	15.17	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:6	32.72	2400	2.28	13.4	108	198	Off Idle	71.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.96	15.18	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:6	32.72	2392	2.28	13.4	108	198	Off Idle	71.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.94	15.22	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:6	32.72	2406	2.28	13.4	108	198	Off Idle	71	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.93	15.26	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:6	32.72	2411	2.28	13.38	108	198	Off Idle	70.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.95	15.29	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:6	32.72	2414	2.28	13.37	108	198	Off Idle	70.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.93	15.3	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:7	32.72	2424	2.28	13.36	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.93	15.32	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:7	32.72	2431	2.28	13.35	108	198	Off Idle	70.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.94	15.31	1.04	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:7	32.72	2433	2.28	13.37	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.93	15.29	1.04	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:7	32.72	2432	2.28	13.39	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-4.93	15.26	1.04	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:7	32.72	2428	2.28	13.39	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.59	Lean	1	14.6	-4.98	15.23	1.04	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:7	32.72	2442	2.28	13.41	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.98	15.21	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:8	32.72	2433	2.28	13.41	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.01	15.19	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:39:8	32.72	2424	2.28	13.41	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.01	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:8	32.72	2427	2.28	13.39	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.05	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:8	32.72	2425	2.28	13.39	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.01	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:8	32.72	2425	2.28	13.4	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.98	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:8	32.72	2430	2.28	13.4	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:9	32.72	2433	2.28	13.4	108	198	Off Idle	70.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.01	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:9	32.72	2432	2.28	13.4	108	198	Off Idle	70.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.03	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:9	32.72	2430	2.28	13.39	108	198	Off Idle	70.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.06	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:14:39:9	32.72	2427	2.28	13.4	108	198	Off Idle	70.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.04	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:9	32.72	2427	2.28	13.39	108	198	Off Idle	70	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.04	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:9	32.72	2429	2.28	13.37	108	198	Off Idle	70	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.06	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:39:9	32.72	2436	2.28	13.39	108	198	Off Idle	70	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.06	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:0	32.72	2441	2.28	13.38	108	198	Off Idle	70	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.04	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:0	32.72	2443	2.28	13.38	108	198	Off Idle	70	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.08	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:0	32.72	2452	2.28	13.4	108	198	Off Idle	69.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.07	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:0	32.72	2458	2.28	13.41	108	198	Off Idle	69.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.05	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:0	32.72	2456	2.29	13.41	108	198	Off Idle	69.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.02	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:0	32.72	2456	2.29	13.41	108	198	Off Idle	69.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.01	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:1	32.72	2452	2.29	13.41	108	198	Off Idle	69.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:1	32.72	2452	2.29	13.4	108	198	Off Idle	69.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.01	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:40:1	32.72	2445	2.29	13.38	108	198	Off Idle	69	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.98	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:40:1	32.72	2445	2.29	13.39	108	198	Off Idle	68.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.96	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:40:1	32.72	2448	2.29	13.4	108	198	Off Idle	68.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.94	15.16	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:40:1	32.72	2436	2.3	13.39	108	198	Off Idle	68.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.94	15.17	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:40:1	32.72	2436	2.3	13.39	108	198	Off Idle	68.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.92	15.19	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:40:2	32.72	2436	2.3	13.4	108	198	Off Idle	68.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.92	15.2	1.04	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:40:2	32.72	2430	2.3	13.41	108	198	Off Idle	68.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.89	15.14	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:2	32.72	2458	2.31	13.39	108	198	Off Idle	68.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.89	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:2	32.72	2464	2.31	13.38	108	198	Off Idle	69	0	2	132	944 Turbo	0.65	Lean	1	14.6	-4.88	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:40:2	32.72	2467	2.31	13.37	108	198	Off Idle	69.1	0	2	132	944 Turbo	0.59	Lean	1	14.6	-4.85	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:2	32.72	2470	2.32	13.37	108	198	Off Idle	69.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.79	14.98	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:40:3	32.72	2469	2.32	13.36	108	198	Off Idle	69.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.74	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:3	32.72	2468	2.32	13.39	108	198	Off Idle	69.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.72	14.9	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:3	32.72	2466	2.33	13.39	108	198	Off Idle	69.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.68	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:3	32.72	2461	2.33	13.39	108	198	Off Idle	69.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.66	14.79	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:40:3	32.72	2461	2.34	13.39	108	198	Off Idle	69.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.67	14.72	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:40:3	32.72	2461	2.34	13.39	108	198	Off Idle	69.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.66	14.75	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:40:4	32.72	2461	2.34	13.39	108	198	Off Idle	69.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.64	14.8	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:40:4	32.72	2467	2.35	13.4	108	198	Off Idle	69.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.62	14.82	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:40:4	32.72	2475	2.35	13.41	108	198	Off Idle	69.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.56	14.89	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:40:4	32.72	2475	2.35	13.39	108	198	Off Idle	69	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.55	14.92	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:40:4	32.72	2478	2.36	13.39	108	198	Off Idle	68.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.54	14.95	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:4	32.72	2478	2.36	13.39	108	198	Off Idle	68.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.54	14.99	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:4	32.72	2481	2.36	13.39	108	198	Off Idle	68.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.51	15.04	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:5	32.72	2482	2.36	13.4	108	198	Off Idle	68.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.54	15.15	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:5	32.72	2477	2.37	13.38	108	198	Off Idle	68.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.56	15.15	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:5	32.72	2476	2.37	13.38	108	198	Off Idle	68.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-4.56	15.17	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:5	32.72	2476	2.37	13.37	108	198	Off Idle	68.2	0	2	132	944 Turbo	0.63	Lean	1	14.6	-4.54	15.15	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:5	32.72	2474	2.37	13.38	108	198	Off Idle	68.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.53	15.1	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:5	32.72	2475	2.37	13.38	108	198	Off Idle	68	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.49	15.05	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:6	32.72	2475	2.37	13.4	108	198	Off Idle	67.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.48	15.01	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:6	32.72	2478	2.37	13.37	108	198	Off Idle	67.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.47	14.94	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:6	32.72	2484	2.37	13.39	108	198	Off Idle	67.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.46	14.89	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:6	32.72	2490	2.37	13.39	108	198	Off Idle	67.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.49	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:6	32.72	2490	2.38	13.37	108	198	Off Idle	67.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.5	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:6	32.72	2495	2.38	13.37	108	198	Off Idle	67.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.47	14.72	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:6	32.72	2495	2.38	13.37	108	198	Off Idle	67.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.47	14.7	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:7	32.72	2495	2.38	13.37	108	198	Off Idle	67.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.49	14.66	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:7	32.72	2493	2.38	13.36	108	198	Off Idle	67.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.51	14.66	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:7	32.72	2490	2.38	13.38	108	198	Off Idle	67.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.52	14.68	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:7	32.72	2491	2.38	13.38	108	198	Off Idle	67.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.56	14.69	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:7	32.72	2492	2.38	13.38	108	198	Off Idle	67.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.55	14.73	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:7	32.72	2493	2.38	13.38	108	198	Off Idle	67.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.5	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:40:8	32.72	2499	2.38	13.38	108	198	Off Idle	67.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.5	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:40:8	32.72	2499	2.38	13.38	108	198	Off Idle	67.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.46	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:40:8	32.72	2503	2.38	13.38	108	198	Off Idle	67.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.44	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:40:8	32.72	2506	2.39	13.4	108	198	Off Idle	67.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.4	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:40:8	32.72	2509	2.4	13.4	108	198	Off Idle	67.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.33	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:40:8	32.72	2514	2.4	13.4	108	198	Off Idle	67.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.3	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:40:9	32.72	2514	2.41	13.39	108	198	Off Idle	67.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.3	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:40:9	32.72	2520	2.42	13.39	108	198	Off Idle	67.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.15	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:40:9	32.72	2518	2.42	13.39	108	198	Off Idle	66.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.12	14.85	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:40:9	32.72	2515	2.43	13.38	108	198	Off Idle	66.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.07	14.87	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:40:9	32.72	2515	2.44	13.37	108	198	Off Idle	66.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4	14.89	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:40:9	32.72	2517	2.45	13.37	108	198	Off Idle	66.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.92	14.92	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:40:9	32.72	2517	2.45	13.35	108	198	Off Idle	66	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.9	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:0	32.72	2522	2.46	13.37	108	198	Off Idle	65.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-3.84	14.98	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:0	32.72	2522	2.46	13.37	108	198	Off Idle	65.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.78	15.01	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:0	32.72	2518	2.47	13.39	108	198	Off Idle	65.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-3.75	15.05	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:0	32.72	2518	2.48	13.38	108	198	Off Idle	65.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.76	15.1	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:0	32.72	2519	2.49	13.38	108	198	Off Idle	65.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.76	15.11	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:0	32.72	2522	2.5	13.39	108	198	Off Idle	65.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.74	15.09	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:1	32.72	2526	2.5	13.38	108	198	Off Idle	65.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.73	15.07	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:1	32.72	2533	2.51	13.37	108	198	Off Idle	65.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.7	14.98	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:1	32.72	2533	2.51	13.38	108	198	Off Idle	65.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.72	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:1	32.72	2536	2.51	13.38	108	198	Off Idle	64.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.7	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:41:1	32.72	2542	2.51	13.38	108	198	Off Idle	64.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.74	14.73	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:41:1	32.72	2542	2.51	13.38	108	198	Off Idle	64.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.72	14.65	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:41:1	32.72	2560	2.51	13.38	108	198	Off Idle	65.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.7	14.55	0.99	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:41:2	32.72	2560	2.51	13.37	108	198	Off Idle	64.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.68	14.39	0.98	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:41:2	32.72	2541	2.51	13.38	108	198	Off Idle	64.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.67	14.33	0.98	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:41:2	32.72	2540	2.51	13.38	108	198	Off Idle	64.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.65	14.27	0.97	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:41:2	32.72	2542	2.51	13.37	108	198	Off Idle	64.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.62	14.24	0.97	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:41:2	32.72	2542	2.51	13.39	108	198	Off Idle	64.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.61	14.22	0.97	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:41:2	32.72	2546	2.52	13.38	108	198	Off Idle	64.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.62	14.22	0.97	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:3	32.72	2548	2.52	13.38	108	198	Off Idle	64.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.58	14.24	0.97	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:3	32.72	2548	2.53	13.38	108	198	Off Idle	64.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.51	14.26	0.97	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:41:3	32.72	2556	2.53	13.38	108	198	Off Idle	64.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.35	14.28	0.97	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:41:3	32.72	2556	2.54	13.39	108	198	Off Idle	64.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.3	14.29	0.97	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:41:3	32.72	2559	2.55	13.39	108	198	Off Idle	64.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.21	14.31	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:41:3	32.72	2561	2.55	13.39	108	198	Off Idle	63.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.16	14.33	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:41:4	32.72	2560	2.56	13.39	108	198	Off Idle	63.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.07	14.37	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:41:4	32.72	2560	2.57	13.39	108	198	Off Idle	63.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.04	14.39	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:41:4	32.72	2558	2.57	13.38	108	198	Off Idle	63.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.02	14.42	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:41:4	32.72	2568	2.58	13.36	108	198	Off Idle	63.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3	14.47	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:41:4	32.72	2568	2.58	13.38	108	198	Off Idle	63.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3	14.5	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:41:4	32.72	2574	2.59	13.38	108	198	Off Idle	63.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3	14.53	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:4	32.72	2575	2.6	13.38	108	198	Off Idle	63.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.96	14.56	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:5	32.72	2575	2.6	13.4	108	198	Off Idle	63.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.89	14.6	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:41:5	32.72	2577	2.61	13.38	108	198	Off Idle	63.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.85	14.62	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:5	32.72	2576	2.61	13.38	108	198	Off Idle	63.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.79	14.64	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:5	32.72	2597	2.62	13.38	108	198	Off Idle	62.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.78	14.64	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:5	32.72	2587	2.63	13.36	108	198	Off Idle	62.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.76	14.64	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:5	32.72	2580	2.63	13.38	108	198	Off Idle	62.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.69	14.62	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:6	32.72	2580	2.64	13.39	108	198	Off Idle	62.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.63	14.6	0.99	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:6	32.72	2585	2.64	13.37	108	198	Off Idle	62.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.59	14.58	0.99	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:6	32.72	2587	2.64	13.38	108	198	Off Idle	62.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.54	14.54	0.99	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:6	32.72	2594	2.65	13.4	108	198	Off Idle	62	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.51	14.49	0.99	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:6	32.72	2600	2.65	13.39	108	198	Off Idle	61.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.5	14.47	0.99	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:6	32.72	2603	2.65	13.4	108	198	Off Idle	61.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.5	14.44	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:6	32.72	2604	2.65	13.4	108	198	Off Idle	61.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.45	14.42	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:7	32.72	2602	2.66	13.41	108	198	Off Idle	61.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.44	14.41	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:7	32.72	2602	2.66	13.4	108	198	Off Idle	61.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.4	14.4	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:7	32.72	2603	2.67	13.39	108	198	Off Idle	60.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.36	14.4	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:7	32.72	2603	2.67	13.39	108	198	Off Idle	60.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.35	14.41	0.98	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:41:7	32.72	2606	2.67	13.39	108	198	Off Idle	60.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.4	14.4	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:7	32.72	2608	2.67	13.38	108	198	Off Idle	60.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.33	14.41	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:8	32.72	2608	2.68	13.38	108	198	Off Idle	60.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.32	14.42	0.98	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:41:8	32.72	2608	2.68	13.41	108	198	Off Idle	60.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.35	14.42	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:8	32.72	2609	2.68	13.38	108	198	Off Idle	60.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.35	14.43	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:8	32.72	2611	2.68	13.4	108	198	Off Idle	60.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.34	14.42	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:8	32.72	2611	2.68	13.38	108	198	Off Idle	60.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.38	14.41	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:8	32.72	2616	2.69	13.38	108	198	Off Idle	60.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.37	14.42	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:9	32.72	2618	2.69	13.38	108	198	Off Idle	60.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.35	14.41	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:9	32.72	2622	2.69	13.38	108	198	Off Idle	60.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.34	14.42	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:9	32.72	2624	2.69	13.38	108	198	Off Idle	60.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.33	14.44	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:9	32.72	2628	2.69	13.37	108	198	Off Idle	60.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.37	14.44	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:41:9	32.72	2629	2.69	13.38	108	198	Off Idle	60.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.36	14.44	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:41:9	32.72	2626	2.69	13.38	108	198	Off Idle	60.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.37	14.46	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:41:9	32.72	2626	2.69	13.37	108	198	Off Idle	59.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.33	14.46	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:0	32.72	2623	2.69	13.37	108	198	Off Idle	59.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.3	14.47	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:0	32.72	2622	2.69	13.38	108	198	Off Idle	59.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.27	14.47	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:0	32.72	2630	2.7	13.39	108	198	Off Idle	59.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.27	14.49	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:0	32.72	2640	2.7	13.4	108	198	Off Idle	59.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.31	14.49	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:0	32.72	2644	2.7	13.38	108	198	Off Idle	59.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.28	14.49	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:0	32.72	2652	2.7	13.39	108	198	Off Idle	59.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.34	14.49	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:1	32.72	2659	2.7	13.39	108	198	Off Idle	59.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.38	14.5	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:42:1	32.72	2659	2.7	13.38	108	198	Off Idle	59	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.39	14.51	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:1	32.72	2659	2.7	13.38	108	198	Off Idle	59	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.38	14.54	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:1	32.72	2652	2.7	13.39	108	198	Off Idle	58.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.32	14.56	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:1	32.72	2648	2.7	13.39	108	198	Off Idle	58.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.27	14.58	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:1	32.72	2657	2.7	13.4	108	198	Off Idle	58.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.29	14.59	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:1	32.72	2648	2.7	13.39	108	198	Off Idle	58.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.28	14.63	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:2	32.72	2648	2.7	13.4	108	198	Off Idle	58.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.31	14.64	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:2	32.72	2656	2.71	13.39	108	198	Off Idle	58.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.28	14.67	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:2	32.72	2661	2.71	13.4	108	198	Off Idle	58.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.26	14.69	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:2	32.72	2662	2.71	13.4	108	198	Off Idle	58.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.25	14.71	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:2	32.72	2659	2.71	13.4	108	198	Off Idle	58.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.25	14.72	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:2	32.72	2660	2.71	13.4	108	198	Off Idle	58.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.24	14.73	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:3	32.72	2663	2.71	13.39	108	198	Off Idle	57.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.27	14.74	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:3	32.72	2672	2.71	13.4	108	198	Off Idle	57.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.22	14.75	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:3	32.72	2679	2.71	13.39	108	198	Off Idle	57.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.25	14.75	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:3	32.72	2679	2.71	13.38	108	198	Off Idle	57.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.27	14.78	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:42:3	32.72	2678	2.72	13.39	108	198	Off Idle	57.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-2.23	14.79	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:42:3	32.72	2672	2.72	13.38	108	198	Off Idle	57.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.27	14.79	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:4	32.72	2672	2.72	13.38	108	198	Off Idle	57	0	2	132	944 Turbo	0.46	Lean	1	14.6	-2.27	14.78	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:4	32.72	2683	2.72	13.39	108	198	Off Idle	56.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-2.27	14.79	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:4	32.72	2690	2.72	13.39	108	198	Off Idle	56.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.27	14.8	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:42:4	32.72	2690	2.72	13.41	108	198	Off Idle	56.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.29	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:42:4	32.72	2687	2.72	13.4	108	198	Off Idle	56.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-2.29	14.85	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:42:4	32.72	2688	2.72	13.4	108	198	Off Idle	56.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.27	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:4	32.72	2688	2.72	13.41	108	198	Off Idle	56.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.26	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:5	32.72	2689	2.72	13.39	108	198	Off Idle	56	0	2	132	944 Turbo	0.48	Lean	1	14.6	-2.27	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:5	32.72	2691	2.72	13.41	108	198	Off Idle	55.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-2.27	14.98	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:5	32.72	2691	2.72	13.41	108	198	Off Idle	55.9	0	2	132	944 Turbo	0.62	Lean	1	14.6	-2.3	15.02	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:5	32.72	2694	2.72	13.41	108	198	Off Idle	55.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.32	15.03	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:5	32.72	2698	2.72	13.41	108	198	Off Idle	55.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.33	15.03	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:5	32.72	2694	2.72	13.4	108	197	Off Idle	56	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.28	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:6	32.72	2702	2.72	13.39	108	197	Off Idle	56	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.27	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:42:6	32.72	2701	2.72	13.38	108	197	Off Idle	56.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.23	14.92	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:6	32.72	2699	2.73	13.38	108	198	Off Idle	56.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.21	14.89	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:6	32.72	2699	2.73	13.39	108	198	Off Idle	56.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.23	14.83	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:6	32.72	2699	2.73	13.37	108	198	Off Idle	56	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.22	14.8	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:6	32.72	2704	2.73	13.36	108	198	Off Idle	55.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.19	14.78	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:6	32.72	2712	2.73	13.37	108	198	Off Idle	55.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.21	14.77	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:7	32.72	2712	2.73	13.37	108	198	Off Idle	55.9	0	2	132	944 Turbo	0.61	Lean	1	14.6	-2.23	14.78	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:7	32.72	2722	2.73	13.38	108	198	Off Idle	55.9	0	2	132	944 Turbo	0.53	Lean	1	14.6	-2.23	14.83	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:7	32.72	2722	2.73	13.38	108	198	Off Idle	55.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-2.26	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:7	32.72	2722	2.73	13.39	108	198	Off Idle	55.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.25	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:7	32.72	2722	2.73	13.38	108	198	Off Idle	55.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.23	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:7	32.72	2726	2.73	13.38	108	198	Off Idle	55.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-2.25	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:8	32.72	2756	2.73	13.38	108	198	Off Idle	54.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.2	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:8	32.72	2756	2.73	13.37	108	198	Off Idle	54.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.23	14.9	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:8	32.72	2735	2.73	13.38	108	198	Off Idle	54.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.26	14.94	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:8	32.72	2730	2.73	13.38	108	198	Off Idle	54.1	0	2	132	944 Turbo	0.2	Rich	1	14.6	-2.27	14.99	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:8	32.72	2729	2.73	13.37	108	198	Off Idle	54	0	2	132	944 Turbo	0.24	Rich	1	14.6	-2.28	14.99	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:8	32.72	2728	2.73	13.39	108	198	Off Idle	54	0	2	132	944 Turbo	0.29	Rich	1	14.6	-2.4	15.02	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:9	32.72	2729	2.73	13.39	108	198	Off Idle	54	0	2	132	944 Turbo	0.38	Rich	1	14.6	-2.42	15.05	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:9	32.72	2735	2.73	13.37	108	198	Off Idle	54	0	2	132	944 Turbo	0.44	Rich	1	14.6	-2.53	15.13	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:42:9	32.72	2736	2.72	13.39	108	198	Off Idle	53.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-2.55	15.16	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:42:9	32.72	2743	2.71	13.37	108	198	Off Idle	53.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-2.67	15.16	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:42:9	32.72	2744	2.7	13.37	108	198	Off Idle	53.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-2.75	15.15	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:42:9	32.72	2741	2.69	13.38	108	198	Off Idle	53.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.92	15.12	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:42:9	32.72	2741	2.68	13.38	108	198	Off Idle	53.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.05	15.1	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:43:0	32.72	2730	2.66	13.37	108	198	Off Idle	53.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.34	15.02	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:43:0	32.72	2722	2.65	13.4	108	198	Off Idle	53.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.57	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:43:0	32.72	2719	2.64	13.4	108	198	Off Idle	53.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.65	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:43:0	32.72	2722	2.61	13.39	108	198	Off Idle	53.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.96	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:43:0	34.08	2725	2.59	13.37	108	198	Off Idle	53.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.1	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:43:0	34.08	2732	2.57	13.37	108	198	Off Idle	53.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.25	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:43:1	34.08	2736	2.55	13.37	108	198	Off Idle	53.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.4	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:43:1	34.08	2741	2.53	13.39	108	198	Off Idle	53.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.52	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:43:1	34.08	2742	2.51	13.38	108	198	Off Idle	53.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.66	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:43:1	34.08	2739	2.49	13.39	108	198	Off Idle	53.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.77	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:43:1	34.08	2740	2.46	13.41	108	198	Off Idle	53.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.96	14.75	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:43:1	34.08	2747	2.44	13.4	108	198	Off Idle	53.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.05	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:43:1	34.08	2747	2.43	13.39	108	198	Off Idle	53.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.13	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:43:2	34.08	2741	2.4	13.4	108	197	Off Idle	53.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.26	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:43:2	34.08	2746	2.39	13.39	108	197	Off Idle	53.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.35	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:43:2	34.08	2746	2.38	13.38	108	197	Off Idle	53.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.39	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:43:2	34.08	2746	2.37	13.38	108	198	Off Idle	53.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.46	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:43:2	34.08	2747	2.35	13.38	108	198	Off Idle	53	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.6	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:43:2	34.08	2746	2.34	13.38	108	198	Off Idle	52.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.66	15.28	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:43:3	34.08	2746	2.33	13.38	108	198	Off Idle	52.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.81	15.51	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:43:3	34.08	2748	2.32	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.86	15.58	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:43:3	34.08	2749	2.31	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.99	15.83	1.08	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:3	34.08	2750	2.3	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.09	15.97	1.09	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:3	34.08	2745	2.29	13.4	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.23	16.17	1.1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:3	34.08	2743	2.28	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.23	16.27	1.11	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:4	34.08	2754	2.27	13.39	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.3	16.38	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:4	35.45	2738	2.27	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.33	16.43	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:4	35.45	2737	2.26	13.4	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.32	16.45	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:4	35.45	2734	2.25	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.39	16.5	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:4	35.45	2735	2.24	13.39	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.48	16.51	1.12	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:4	35.45	2726	2.24	13.4	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.56	16.54	1.13	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:4	34.08	2726	2.23	13.41	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.58	16.53	1.13	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:5	34.08	2758	2.22	13.39	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.64	16.52	1.13	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:5	34.08	2765	2.22	13.39	108	197	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.65	16.51	1.12	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:5	34.08	2765	2.22	13.37	108	197	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.64	16.5	1.12	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:5	34.08	2752	2.21	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.67	16.49	1.12	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:5	34.08	2762	2.2	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.74	16.46	1.12	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:5	35.45	2751	2.2	13.36	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.75	16.44	1.12	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:6	35.45	2752	2.2	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.77	16.45	1.12	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:6	35.45	2762	2.2	13.38	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.84	16.45	1.12	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:6	35.45	2749	2.19	13.37	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.84	16.46	1.12	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:6	35.45	2750	2.19	13.35	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.85	16.46	1.12	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:14:43:6	35.45	2752	2.19	13.37	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.82	16.46	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:6	35.45	2764	2.19	13.37	108	198	Off Idle	52.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.84	16.46	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:6	35.45	2772	2.18	13.38	108	198	Off Idle	52.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.84	16.44	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:7	35.45	2777	2.18	13.37	108	198	Off Idle	52.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.85	16.43	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:7	35.45	2777	2.18	13.38	108	198	Off Idle	52.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.83	16.4	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:7	35.45	2776	2.18	13.4	108	198	Off Idle	52.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.85	16.37	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:7	35.45	2768	2.18	13.4	108	198	Off Idle	52.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.87	16.36	1.11	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:7	35.45	2766	2.18	13.38	108	198	Off Idle	52.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.84	16.33	1.11	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:7	35.45	2746	2.18	13.38	108	198	Off Idle	52	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.84	16.33	1.11	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:8	35.45	2734	2.19	13.39	108	198	Off Idle	51.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.81	16.33	1.11	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:8	35.45	2731	2.19	13.38	108	198	Off Idle	51.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.8	16.32	1.11	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:8	35.45	2710	2.19	13.38	108	198	Off Idle	52	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.78	16.32	1.11	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:8	35.45	2738	2.19	13.39	108	198	Off Idle	52.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	16.32	1.11	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:8	35.45	2752	2.19	13.4	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.77	16.29	1.11	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:8	35.45	2757	2.19	13.4	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.8	16.28	1.11	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:9	35.45	2758	2.19	13.4	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	16.25	1.11	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:9	35.45	2779	2.19	13.4	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.81	16.21	1.1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:43:9	35.45	2778	2.19	13.4	108	198	Off Idle	52.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.76	16.17	1.1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:9	35.45	2784	2.19	13.4	108	198	Off Idle	52.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.78	16.13	1.1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:9	35.45	2784	2.19	13.39	108	198	Off Idle	52.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.81	16.1	1.1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:9	35.45	2797	2.19	13.38	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.78	16.05	1.09	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:43:9	35.45	2770	2.19	13.38	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	16.03	1.09	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:0	35.45	2760	2.19	13.38	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	16	1.09	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:0	35.45	2756	2.19	13.38	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	15.99	1.09	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:0	35.45	2753	2.2	13.39	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.8	15.97	1.09	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:0	35.45	2750	2.2	13.4	108	198	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.8	15.95	1.09	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:0	35.45	2756	2.2	13.4	108	197	Off Idle	52	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	15.93	1.09	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:0	35.45	2761	2.2	13.4	108	197	Off Idle	51.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	15.9	1.08	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:1	35.45	2761	2.2	13.4	108	197	Off Idle	51.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	15.87	1.08	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:1	35.45	2746	2.2	13.39	108	197	Off Idle	51.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.76	15.85	1.08	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:1	35.45	2774	2.2	13.38	108	197	Off Idle	51.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	15.82	1.08	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:1	35.45	2778	2.2	13.4	108	197	Off Idle	51.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	15.78	1.07	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:1	35.45	2778	2.2	13.39	108	198	Off Idle	51.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.81	15.76	1.07	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:1	35.45	2775	2.2	13.39	108	198	Off Idle	51.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.85	15.74	1.07	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:1	35.45	2775	2.2	13.38	108	198	Off Idle	51.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.85	15.73	1.07	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:2	35.45	2775	2.2	13.38	108	198	Off Idle	51.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.85	15.75	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:2	35.45	2773	2.2	13.38	108	198	Off Idle	51.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.8	15.75	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:2	35.45	2769	2.2	13.39	108	198	Off Idle	51.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.8	15.77	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:2	35.45	2766	2.2	13.37	108	198	Off Idle	51.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.76	15.77	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:2	35.45	2766	2.21	13.37	108	198	Off Idle	51.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.72	15.76	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:2	35.45	2764	2.21	13.36	108	198	Off Idle	51	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.69	15.77	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:3	35.45	2761	2.21	13.37	108	198	Off Idle	51	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.7	15.75	1.07	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:3	35.45	2767	2.21	13.37	108	198	Off Idle	51	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.67	15.72	1.07	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:3	35.45	2767	2.22	13.4	108	198	Off Idle	51	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.66	15.71	1.07	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:3	35.45	2777	2.22	13.39	108	198	Off Idle	50.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.61	15.64	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:3	35.45	2779	2.23	13.41	108	198	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.53	15.59	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:3	35.45	2780	2.23	13.4	108	198	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.46	15.55	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:4	35.45	2779	2.24	13.4	108	197	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.37	15.49	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:4	35.45	2794	2.24	13.41	108	197	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.33	15.45	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:44:4	35.45	2794	2.25	13.4	108	198	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.23	15.4	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:14:44:4	35.45	2782	2.26	13.39	108	198	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.08	15.37	1.05	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:44:4	35.45	2783	2.27	13.39	108	198	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.01	15.35	1.05	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:44:4	35.45	2781	2.28	13.4	108	197	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.91	15.32	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:44:4	35.45	2782	2.29	13.4	108	197	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.81	15.31	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:14:44:5	35.45	2765	2.3	13.4	108	197	Off Idle	50.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.74	15.3	1.04	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:44:5	34.08	2794	2.31	13.4	108	198	Off Idle	50.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.66	15.28	1.04	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:44:5	34.08	2800	2.32	13.41	108	198	Off Idle	50.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.54	15.27	1.04	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:44:5	34.08	2800	2.34	13.39	108	198	Off Idle	50.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.49	15.27	1.04	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:14:44:5	34.08	2801	2.35	13.38	108	198	Off Idle	50.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.39	15.29	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:44:5	34.08	2805	2.37	13.37	108	198	Off Idle	50.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.23	15.31	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:14:44:6	34.08	2802	2.38	13.37	108	198	Off Idle	50.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.1	15.32	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:44:6	34.08	2802	2.4	13.37	108	198	Off Idle	50	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.01	15.32	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:14:44:6	34.08	2798	2.42	13.38	108	198	Off Idle	50	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.9	15.32	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:44:6	34.08	2802	2.43	13.38	108	198	Off Idle	50	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.84	15.32	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:44:6	34.08	2802	2.45	13.38	108	197	Off Idle	50	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.77	15.31	1.04	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:6	34.08	2805	2.46	13.39	108	197	Off Idle	50	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.74	15.3	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:44:6	34.08	2802	2.48	13.39	108	197	Off Idle	50	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.61	15.26	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:44:7	34.08	2800	2.49	13.37	108	198	Off Idle	50	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.51	15.22	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:14:44:7	34.08	2803	2.5	13.38	108	198	Off Idle	49.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.42	15.18	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:7	34.08	2804	2.51	13.37	108	198	Off Idle	49.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.34	15.16	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:7	34.08	2807	2.53	13.38	108	198	Off Idle	49.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.27	15.14	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:7	34.08	2811	2.53	13.38	108	198	Off Idle	49.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.22	15.12	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:14:44:7	34.08	2811	2.55	13.39	108	198	Off Idle	49.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.12	15.06	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:8	34.08	2810	2.56	13.39	108	198	Off Idle	49.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.03	15.01	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:14:44:8	34.08	2809	2.57	13.39	108	198	Off Idle	49.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.92	14.96	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:44:8	34.08	2808	2.58	13.39	108	198	Off Idle	49.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.92	14.94	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:8	34.08	2810	2.58	13.39	108	198	Off Idle	49.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.85	14.9	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:8	34.08	2812	2.6	13.4	108	198	Off Idle	49.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.76	14.85	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:8	34.08	2816	2.6	13.41	108	198	Off Idle	49.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.75	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:9	34.08	2816	2.61	13.41	108	198	Off Idle	49.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.73	14.72	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:44:9	34.08	2812	2.62	13.41	108	198	Off Idle	49.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.7	14.68	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:44:9	34.08	2812	2.62	13.4	108	198	Off Idle	49.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.69	14.66	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:44:9	34.08	2812	2.63	13.38	108	198	Off Idle	49.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.66	14.63	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:44:9	34.08	2808	2.63	13.37	108	198	Off Idle	49.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.66	14.64	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:44:9	34.08	2807	2.64	13.36	108	198	Off Idle	49.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.62	14.64	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:44:9	34.08	2808	2.64	13.37	108	198	Off Idle	49.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.59	14.65	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:0	34.08	2818	2.65	13.36	108	198	Off Idle	49.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.53	14.62	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:0	34.08	2820	2.65	13.38	108	198	Off Idle	49.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.55	14.63	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:0	34.08	2829	2.66	13.39	108	198	Off Idle	49.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.52	14.61	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:0	34.08	2838	2.66	13.39	108	198	Off Idle	49.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.55	14.58	0.99	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:0	34.08	2842	2.66	13.38	108	198	Off Idle	49.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.56	14.53	0.99	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:0	34.08	2844	2.66	13.37	108	198	Off Idle	49	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.56	14.49	0.99	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:1	34.08	2844	2.66	13.37	108	198	Off Idle	48.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.54	14.46	0.99	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:1	34.08	2843	2.66	13.36	108	198	Off Idle	48.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.53	14.44	0.98	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:1	34.08	2838	2.67	13.37	108	198	Off Idle	48.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.52	14.4	0.98	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:1	34.08	2838	2.67	13.38	108	198	Off Idle	48.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.51	14.4	0.98	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:1	34.08	2837	2.67	13.39	108	197	Off Idle	47.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.43	14.35	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:1	34.08	2852	2.67	13.4	108	197	Off Idle	47.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.41	14.34	0.98	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:1	34.08	2876	2.67	13.4	108	197	Off Idle	47.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.33	14.34	0.98	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:2	34.08	2859	2.68	13.41	108	198	Off Idle	47.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.31	14.34	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:2	34.08	2859	2.68	13.39	108	198	Off Idle	46.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.41	14.33	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:2	34.08	2861	2.68	13.38	108	198	Off Idle	46.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.34	14.34	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:2	34.08	2861	2.68	13.36	108	197	Off Idle	46.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.39	14.36	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:2	32.72	2850	2.69	13.37	108	197	Off Idle	46	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.34	14.37	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:2	32.72	2856	2.69	13.38	108	197	Off Idle	45.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.32	14.39	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:3	32.72	2851	2.69	13.4	108	198	Off Idle	45.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.32	14.43	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:3	32.72	2853	2.7	13.39	108	198	Off Idle	45.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.29	14.45	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:3	34.08	2864	2.7	13.4	108	198	Off Idle	45.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.22	14.47	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:3	34.08	2859	2.7	13.39	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.19	14.51	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:3	34.08	2866	2.7	13.39	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.14	14.55	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:3	34.08	2868	2.71	13.4	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.1	14.57	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:4	34.08	2872	2.71	13.38	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.02	14.58	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:4	32.72	2854	2.72	13.39	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3	14.59	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:4	32.72	2864	2.72	13.4	108	197	Off Idle	45.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.96	14.6	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:4	32.72	2876	2.73	13.4	108	197	Off Idle	45.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.85	14.6	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:4	32.72	2871	2.73	13.39	108	197	Off Idle	45.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.69	14.6	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:14:45:4	32.72	2870	2.74	13.39	108	197	Off Idle	45.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.58	14.61	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:14:45:4	32.72	2871	2.75	13.39	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.45	14.61	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:45:5	32.72	2874	2.76	13.39	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.21	14.61	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:14:45:5	32.72	2882	2.78	13.4	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.93	14.61	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:14:45:5	32.72	2886	2.8	13.39	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.66	14.68	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:14:45:5	32.72	2888	2.81	13.38	108	198	Off Idle	45.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.57	14.7	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:5	32.72	2896	2.82	13.38	108	198	Off Idle	45.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-1.47	14.73	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:5	32.72	2907	2.84	13.39	108	198	Off Idle	45.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-1.23	14.77	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:6	32.72	2911	2.85	13.39	108	198	Off Idle	45.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-1.12	14.79	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:6	32.72	2911	2.86	13.4	108	198	Off Idle	45.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-1.1	14.82	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:6	32.72	2911	2.88	13.41	108	198	Off Idle	45	0	2	132	944 Turbo	0.49	Lean	1	14.6	-1.08	14.82	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:6	32.72	2906	2.89	13.39	108	198	Off Idle	44.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-1.06	14.86	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:14:45:6	32.72	2898	2.9	13.39	108	198	Off Idle	44.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-1.06	14.9	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:6	32.72	2898	2.92	13.37	108	198	Off Idle	44.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-1.03	14.92	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:6	32.72	2896	2.93	13.37	108	198	Off Idle	44	0	2	132	944 Turbo	0.57	Lean	1	14.6	-1.02	14.9	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:7	32.72	2896	2.93	13.37	108	198	Off Idle	43.9	0	2	132	944 Turbo	0.62	Lean	1	14.6	-1.01	14.86	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:7	32.72	2898	2.94	13.38	108	198	Off Idle	43.7	0	2	132	944 Turbo	0.68	Lean	1	14.6	-0.96	14.8	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:45:7	32.72	2909	2.95	13.39	108	198	Off Idle	43.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.87	14.66	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:7	32.72	2922	2.96	13.4	108	198	Off Idle	43.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.82	14.57	0.99	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:7	32.72	2922	2.96	13.4	108	198	Off Idle	43.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.87	14.43	0.98	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:7	32.72	2936	2.96	13.39	108	198	Off Idle	43.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.82	14.32	0.98	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:8	32.72	2936	2.96	13.39	108	198	Off Idle	43.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.91	14.11	0.96	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:8	32.72	2936	2.96	13.39	108	198	Off Idle	43.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.84	14.01	0.95	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:8	32.72	2937	2.96	13.38	108	198	Off Idle	43	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.81	13.94	0.95	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:8	32.72	2960	2.96	13.37	108	198	Off Idle	42.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.8	13.88	0.95	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:8	32.72	2960	2.97	13.38	108	198	Off Idle	42.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.8	13.85	0.94	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:8	32.72	2943	2.97	13.38	108	198	Off Idle	42.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.81	13.84	0.94	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:45:9	32.72	2921	2.98	13.38	108	198	Off Idle	42.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.71	13.84	0.94	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:9	31.36	2924	2.98	13.38	108	198	Off Idle	42.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.63	13.85	0.94	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:9	31.36	2954	2.98	13.39	108	198	Off Idle	42.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.55	13.86	0.94	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:9	31.36	2960	2.99	13.38	108	198	Off Idle	42	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.49	13.87	0.94	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:9	31.36	2963	2.99	13.37	108	198	Off Idle	41.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.52	13.87	0.94	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:9	31.36	2962	2.99	13.37	108	197	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.49	13.86	0.94	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:45:9	31.36	2958	3	13.36	108	197	Off Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.52	13.88	0.95	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:0	31.36	2955	3	13.38	108	197	Off Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.43	13.9	0.95	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:0	31.36	2954	3	13.39	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.43	13.89	0.95	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:0	31.36	2927	3.01	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.4	13.89	0.95	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:0	31.36	2927	3.01	13.39	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.38	13.9	0.95	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:0	31.36	2951	3.01	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.32	13.89	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:0	31.36	2966	3.02	13.39	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.28	13.9	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:1	31.36	2966	3.02	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.21	13.92	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:1	31.36	2992	3.02	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.19	13.97	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:1	32.72	2992	3.02	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.2	13.98	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:1	32.72	2994	3.03	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.17	13.99	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:1	32.72	2987	3.03	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.15	14.06	0.96	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:14:46:1	32.72	2987	3.03	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.13	14.11	0.96	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:1	32.72	2991	3.04	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.12	14.14	0.96	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:2	32.72	2989	3.04	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.09	14.18	0.97	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:2	32.72	2990	3.04	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.08	14.21	0.97	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:2	32.72	2996	3.05	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.09	14.24	0.97	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:2	32.72	3001	3.05	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.06	14.27	0.97	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:2	32.72	3010	3.05	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.04	14.33	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:2	32.72	3011	3.05	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.05	14.37	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:3	32.72	3012	3.06	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.07	14.38	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:3	31.36	2999	3.06	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.1	14.41	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:3	31.36	3012	3.06	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.16	14.46	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:14:46:3	31.36	3010	3.07	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.26	14.48	0.99	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:46:3	31.36	3010	3.07	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.25	14.5	0.99	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:46:3	31.36	3015	3.08	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.34	14.52	0.99	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:14:46:4	31.36	3020	3.09	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.4	14.54	0.99	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:46:4	31.36	3027	3.09	13.36	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.45	14.57	0.99	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:46:4	31.36	3030	3.1	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.52	14.6	0.99	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:46:4	31.36	3028	3.1	13.36	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.56	14.63	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:46:4	31.36	3021	3.11	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.63	14.64	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:46:4	31.36	3024	3.11	13.36	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.69	14.66	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:4	31.36	3036	3.12	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.73	14.67	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:5	31.36	3046	3.12	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.76	14.69	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:5	31.36	3038	3.12	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.75	14.7	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:5	29.99	3062	3.13	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.86	14.71	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:5	29.99	3062	3.13	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.9	14.73	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:14:46:5	29.99	3054	3.14	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.92	14.7	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:5	29.99	3059	3.15	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.96	14.71	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:6	29.99	3056	3.15	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.96	14.71	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:6	29.99	3055	3.16	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.07	14.71	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:6	29.99	3055	3.16	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.05	14.72	1	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:46:6	29.99	3060	3.17	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.12	14.73	1	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:46:6	29.99	3076	3.17	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.15	14.73	1	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:46:6	29.99	3090	3.17	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.22	14.78	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:46:6	29.99	3090	3.18	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.25	14.78	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:46:7	29.99	3092	3.18	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.35	14.78	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:46:7	29.99	3080	3.18	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.33	14.81	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:46:7	29.99	3092	3.19	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.33	14.81	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:7	31.36	3075	3.19	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.31	14.8	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:7	31.36	3079	3.19	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.38	14.81	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:46:7	31.36	3076	3.2	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.41	14.81	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:46:8	31.36	3078	3.2	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.5	14.81	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:14:46:8	31.36	3089	3.2	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.53	14.79	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:8	31.36	3093	3.21	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.58	14.79	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:8	31.36	3106	3.21	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	1.65	14.8	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:8	31.36	3108	3.21	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	1.65	14.81	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:8	29.99	3108	3.21	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	1.7	14.82	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:46:9	29.99	3112	3.22	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	1.7	14.83	1.01	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:46:9	29.99	3109	3.22	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	1.74	14.82	1.01	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:46:9	29.99	3120	3.22	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	1.73	14.84	1.01	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:46:9	29.99	3120	3.23	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	1.78	14.83	1.01	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:46:9	29.99	3131	3.23	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	1.78	14.86	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:14:46:9	29.99	3134	3.23	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	1.81	14.9	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:46:9	29.99	3131	3.23	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	1.87	14.96	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:0	29.99	3131	3.24	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	1.95	14.98	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:0	29.99	3132	3.24	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	1.96	15.05	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:0	29.99	3134	3.24	13.41	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	1.96	15.11	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:0	29.99	3132	3.24	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	1.93	15.13	1.03	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:14:47:0	29.99	3133	3.25	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	2.01	15.14	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:0	29.99	3137	3.25	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	2.06	15.09	1.03	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:1	29.99	3145	3.25	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	2.13	15.07	1.03	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:1	29.99	3145	3.26	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	2.16	15.01	1.02	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:1	29.99	3152	3.26	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	2.26	14.91	1.02	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:1	29.99	3152	3.26	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	2.23	14.88	1.01	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:1	29.99	3147	3.26	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	2.23	14.81	1.01	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:1	29.99	3146	3.27	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	2.16	14.72	1	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:14:47:1	29.99	3146	3.27	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	2.21	14.71	1	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:2	29.99	3146	3.27	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	2.28	14.7	1	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:2	29.99	3176	3.27	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	2.34	14.69	1	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:2	29.99	3185	3.28	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	2.33	14.73	1	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:2	29.99	3194	3.28	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	2.42	14.77	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:14:47:2	29.99	3194	3.28	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	2.38	14.82	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:14:47:2	29.99	3188	3.28	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	2.43	14.87	1.01	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:3	29.99	3189	3.29	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	2.48	14.92	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:3	29.99	3188	3.29	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	2.53	15.02	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:3	29.99	3189	3.29	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	2.55	15.03	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:3	29.99	3186	3.29	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	2.61	15.04	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:3	29.99	3186	3.3	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	2.63	15.06	1.03	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:3	29.99	3188	3.3	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	2.66	15.04	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:4	29.99	3186	3.3	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	2.7	15	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:4	28.63	3186	3.3	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	2.74	14.96	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:4	28.63	3203	3.31	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	2.76	14.93	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:4	28.63	3203	3.31	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	2.74	14.88	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:14:47:4	28.63	3215	3.31	13.36	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	2.82	14.76	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:14:47:4	28.63	3215	3.31	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	2.84	14.75	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:14:47:4	28.63	3218	3.32	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	2.92	14.75	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:5	28.63	3226	3.32	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	2.87	14.75	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:5	28.63	3234	3.32	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	2.94	14.79	1.01	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:14:47:5	28.63	3232	3.32	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	2.91	14.84	1.01	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:47:5	28.63	3232	3.33	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	2.97	14.88	1.01	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:5	28.63	3238	3.33	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	2.97	14.94	1.02	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:5	28.63	3235	3.33	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	3.04	14.97	1.02	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:6	28.63	3240	3.33	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	2.99	14.98	1.02	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:6	28.63	3240	3.33	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	3.07	15	1.02	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:14:47:6	28.63	3238	3.34	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	3.07	14.97	1.02	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:14:47:6	28.63	3233	3.34	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	3.07	14.91	1.02	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:14:47:6	28.63	3236	3.34	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	3.1	14.88	1.01	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:6	28.63	3236	3.35	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	3.17	14.85	1.01	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:14:47:6	28.63	3247	3.35	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	3.12	14.81	1.01	3.6	6.1	ON	28 Pin	OFF	Removed	Disabled
03:14:47:7	28.63	3254	3.35	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	3.13	14.76	1.01	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:14:47:7	28.63	3270	3.35	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	3.26	14.68	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:14:47:7	28.63	3282	3.36	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	3.25	14.66	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:14:47:7	28.63	3281	3.36	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	3.33	14.69	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:14:47:7	28.63	3280	3.36	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	3.41	14.71	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:14:47:7	28.63	3280	3.37	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	3.46	14.8	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:14:47:8	28.63	3279	3.37	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	3.51	14.86	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:8	28.63	3284	3.37	13.35	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	3.62	14.88	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:8	28.63	3284	3.38	13.35	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	3.55	14.89	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:8	28.63	3290	3.38	13.36	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	3.66	14.89	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:8	29.99	3284	3.38	13.35	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	3.61	14.91	1.02	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:8	29.99	3284	3.39	13.36	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	3.6	14.9	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:9	29.99	3294	3.39	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.56	14.87	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:14:47:9	29.99	3297	3.39	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.63	14.78	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:14:47:9	28.63	3300	3.4	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.67	14.74	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:14:47:9	28.63	3298	3.4	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.63	14.72	1	3.6	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:47:9	28.63	3298	3.4	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.64	14.72	1	3.6	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:47:9	28.63	3304	3.4	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	3.74	14.7	1	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:47:9	28.63	3316	3.41	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	3.86	14.71	1	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:48:0	28.63	3331	3.41	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	3.79	14.74	1	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:48:0	28.63	3347	3.41	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	3.84	14.76	1.01	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:48:0	28.63	3348	3.41	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	3.97	14.78	1.01	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:48:0	28.63	3355	3.41	13.36	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	3.94	14.74	1	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:48:0	28.63	3355	3.42	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	3.98	14.67	1	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:48:0	28.63	3348	3.42	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	3.98	14.53	0.99	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:48:1	28.63	3345	3.42	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	3.98	14.41	0.98	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:48:1	28.63	3338	3.42	13.4	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	3.89	14.19	0.97	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:48:1	28.63	3350	3.43	13.4	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.9	13.99	0.95	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:48:1	28.63	3342	3.43	13.4	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	3.94	13.73	0.94	3.6	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:48:1	28.63	3346	3.43	13.4	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	3.92	13.52	0.92	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:48:1	28.63	3359	3.43	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4	13.35	0.91	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:48:1	28.63	3359	3.43	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.04	13.23	0.9	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:48:2	28.63	3370	3.44	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.02	13.14	0.89	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:2	28.63	3376	3.44	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.04	13.06	0.89	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:2	28.63	3378	3.44	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.06	13.03	0.89	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:48:2	28.63	3384	3.44	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.01	12.99	0.89	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:2	28.63	3387	3.44	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	3.99	12.98	0.88	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:2	28.63	3382	3.44	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.11	12.94	0.88	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:3	28.63	3382	3.45	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.11	12.93	0.88	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:3	28.63	3389	3.45	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.22	12.89	0.88	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:3	28.63	3391	3.45	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.26	12.86	0.88	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:3	28.63	3399	3.45	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.29	12.83	0.87	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:3	28.63	3398	3.45	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.35	12.77	0.87	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:3	28.63	3409	3.45	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.42	12.76	0.87	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:4	28.63	3406	3.46	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.44	12.72	0.87	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:4	28.63	3422	3.46	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.48	12.67	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:4	28.63	3421	3.46	13.36	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.52	12.67	0.86	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:48:4	28.63	3425	3.46	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.52	12.64	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:48:4	28.63	3428	3.47	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.55	12.63	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:4	28.63	3432	3.47	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.53	12.61	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:4	28.63	3431	3.47	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.56	12.59	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:5	28.63	3436	3.47	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.42	12.59	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:5	28.63	3439	3.47	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.5	12.6	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:5	28.63	3439	3.48	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.37	12.62	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:5	28.63	3446	3.48	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.44	12.66	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:5	28.63	3447	3.48	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.49	12.66	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:5	28.63	3451	3.48	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.43	12.65	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:6	28.63	3450	3.48	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.47	12.67	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:6	28.63	3479	3.48	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.6	12.69	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:6	28.63	3456	3.48	13.4	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.6	12.68	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:6	28.63	3458	3.49	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.61	12.65	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:6	28.63	3460	3.49	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.75	12.62	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:6	28.63	3480	3.49	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.68	12.59	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:6	28.63	3474	3.49	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.66	12.58	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:7	28.63	3486	3.49	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.72	12.59	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:7	28.63	3496	3.5	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.72	12.6	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:7	28.63	3498	3.5	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.72	12.61	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:7	28.63	3502	3.5	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.71	12.62	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:7	28.63	3504	3.5	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.66	12.65	0.86	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:48:7	28.63	3498	3.51	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.63	12.68	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:8	28.63	3498	3.51	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.74	12.68	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:8	28.63	3496	3.51	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.76	12.67	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:8	28.63	3504	3.51	13.41	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.88	12.65	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:8	28.63	3504	3.51	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	5.01	12.6	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:8	28.63	3512	3.51	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.99	12.58	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:8	27.27	3526	3.52	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.97	12.56	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:9	27.27	3526	3.52	13.36	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.99	12.56	0.86	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:9	27.27	3532	3.52	13.35	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.92	12.55	0.85	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:9	27.27	3536	3.52	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.87	12.54	0.85	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:9	27.27	3532	3.52	13.36	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.93	12.55	0.85	3.6	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:48:9	28.63	3536	3.53	13.36	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.92	12.56	0.86	3.6	7.5	ON	28 Pin	OFF	Removed	Disabled
03:14:48:9	28.63	3536	3.53	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.88	12.6	0.86	3.6	7.5	ON	28 Pin	OFF	Removed	Disabled
03:14:48:9	28.63	3539	3.53	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.87	12.63	0.86	3.6	7.6	ON	28 Pin	OFF	Removed	Disabled
03:14:49:0	28.63	3542	3.53	13.41	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.78	12.64	0.86	3.6	7.6	ON	28 Pin	OFF	Removed	Disabled
03:14:49:0	28.63	3547	3.53	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	4.76	12.64	0.86	3.6	7.5	ON	28 Pin	OFF	Removed	Disabled
03:14:49:0	28.63	3552	3.53	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.75	12.64	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:49:0	28.63	3555	3.53	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.69	12.63	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:0	28.63	3556	3.53	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.76	12.63	0.86	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:0	27.27	3572	3.53	13.38	108	197	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.83	12.61	0.86	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:49:1	27.27	3566	3.53	13.39	108	197	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.77	12.58	0.86	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:1	27.27	3566	3.53	13.38	108	197	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.81	12.54	0.85	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:1	27.27	3569	3.53	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.73	12.53	0.85	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:1	27.27	3580	3.53	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.69	12.52	0.85	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:1	28.63	3582	3.53	13.37	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.69	12.54	0.85	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:1	28.63	3584	3.53	13.36	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.71	12.54	0.85	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:1	28.63	3602	3.53	13.38	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.58	12.54	0.85	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:14:49:2	28.63	3616	3.53	13.39	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.68	12.53	0.85	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:2	28.63	3604	3.53	13.38	108	197	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.67	12.54	0.85	3.6	7.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:2	28.63	3596	3.52	13.41	108	197	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.7	12.56	0.86	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:2	28.63	3590	3.52	13.39	108	197	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.7	12.57	0.86	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:2	28.63	3592	3.52	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.63	12.59	0.86	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:2	28.63	3598	3.52	13.39	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.5	12.59	0.86	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:3	28.63	3602	3.52	13.4	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.44	12.59	0.86	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:3	28.63	3603	3.52	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.39	12.57	0.86	3.6	7.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:3	28.63	3614	3.52	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.3	12.55	0.86	3.6	7.1	ON	28 Pin	OFF	Removed	Disabled
03:14:49:3	28.63	3627	3.51	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.28	12.56	0.86	3.6	7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:49:3	28.63	3628	3.51	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.32	12.57	0.86	3.6	7	ON	28 Pin	OFF	Removed	Disabled
03:14:49:3	28.63	3627	3.51	13.36	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.24	12.57	0.86	3.6	7	ON	28 Pin	OFF	Removed	Disabled
03:14:49:4	28.63	3629	3.51	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.11	12.58	0.86	3.6	6.9	ON	28 Pin	OFF	Removed	Disabled
03:14:49:4	28.63	3628	3.5	13.4	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.17	12.58	0.86	3.6	6.9	ON	28 Pin	OFF	Removed	Disabled
03:14:49:4	28.63	3632	3.5	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.19	12.58	0.86	3.6	6.9	ON	28 Pin	OFF	Removed	Disabled
03:14:49:4	28.63	3634	3.5	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.97	12.58	0.86	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:14:49:4	28.63	3635	3.49	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.91	12.61	0.86	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:14:49:4	28.63	3639	3.49	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.7	12.63	0.86	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:14:49:4	28.63	3647	3.49	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.59	12.63	0.86	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:14:49:5	28.63	3646	3.48	13.36	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.52	12.67	0.86	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:14:49:5	28.63	3646	3.48	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.4	12.67	0.86	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:14:49:5	29.99	3660	3.47	13.36	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.27	12.69	0.86	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:14:49:5	29.99	3657	3.46	13.35	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	3.16	12.71	0.87	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:14:49:5	29.99	3659	3.45	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	2.75	12.71	0.87	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:5	29.99	3660	3.44	13.38	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.72	12.71	0.87	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:14:49:6	29.99	3678	3.43	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.47	12.7	0.86	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:14:49:6	29.99	3654	3.41	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.88	12.67	0.86	3.6	5.9	ON	28 Pin	OFF	Removed	Disabled
03:14:49:6	29.99	3657	3.39	13.38	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.57	12.66	0.86	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:14:49:6	29.99	3658	3.36	13.35	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.08	12.63	0.86	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:14:49:6	29.99	3670	3.32	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.34	12.63	0.86	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:6	32.72	3670	3.26	13.37	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.78	12.61	0.86	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:6	32.72	3640	3.2	13.35	108	198	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.73	12.6	0.86	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:49:7	32.72	3632	3.14	13.39	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.22	12.56	0.86	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:14:49:7	32.72	3650	3.03	13.37	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.52	12.52	0.85	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:14:49:7	34.08	3622	2.96	13.36	108	197	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.35	12.46	0.85	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:7	34.08	3623	2.87	13.39	108	198	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.2	12.38	0.84	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:7	34.08	3619	2.77	13.38	108	198	Full Load	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.9	12.32	0.84	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:49:7	34.08	3619	2.62	13.38	108	198	Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-6.59	12.23	0.83	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:49:8	35.45	3608	2.52	13.4	108	198	Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.12	12.13	0.83	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:49:8	35.45	3608	2.42	13.4	108	198	Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.52	12.03	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:8	35.45	3585	2.37	13.37	108	198	Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.92	11.94	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:8	35.45	3561	2.28	13.4	108	197	Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.33	11.86	0.81	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:8	29.99	3477	2.18	13.38	108	197	Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.53	11.81	0.8	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:14:49:8	29.99	3472	2.08	13.41	108	197	Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.69	11.81	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:9	20.45	3466	1.98	13.41	108	197	Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.76	11.83	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:9	20.45	3500	1.85	13.41	108	197	Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.89	11.93	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:9	20.45	3554	1.77	13.4	108	197	Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.95	12.01	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:9	20.45	3597	1.67	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.03	12.21	0.83	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:9	20.45	3621	1.62	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.16	12.35	0.84	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:9	20.45	3636	1.59	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.19	12.5	0.85	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:49:9	20.45	3652	1.54	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.28	12.73	0.87	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:0	20.45	3712	1.51	13.39	108	197	Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.36	12.9	0.88	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:0	20.45	3677	1.49	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.13	Rich	1	14.6	-9.48	13.08	0.89	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:0	20.45	3660	1.48	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.56	13.38	0.91	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:0	20.45	3656	1.48	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.63	13.47	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:0	20.45	3625	1.49	13.42	108	198	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.71	14.11	0.96	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:0	20.45	3597	1.51	13.43	108	198	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	14.74	1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:1	20.45	3597	1.53	13.43	108	198	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	15.42	1.05	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:1	20.45	3567	1.53	13.44	108	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	16.13	1.1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:1	20.45	3556	1.55	13.44	108	197	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	17.16	1.17	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:1	20.45	3553	1.56	13.45	108	197	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	18.13	1.24	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:1	20.45	3554	1.58	13.44	108	197	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	18.44	1.26	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:1	20.45	3565	1.59	13.42	107	197	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	19.32	1.32	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:1	20.45	3581	1.6	13.42	107	197	Idle	40.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	19.81	1.35	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:2	20.45	3587	1.61	13.4	108	197	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.09	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:2	20.45	3610	1.63	13.4	108	197	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:2	20.45	3622	1.63	13.41	108	197	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:2	20.45	3624	1.64	13.42	108	197	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:50:2	20.45	3622	1.65	13.4	108	197	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:2	20.45	3614	1.66	13.41	108	197	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:3	20.45	3599	1.66	13.42	108	197	Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:3	20.45	3598	1.66	13.4	108	197	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:3	20.45	3575	1.67	13.42	108	197	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:3	20.45	3570	1.67	13.41	108	197	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:3	20.45	3550	1.67	13.41	108	197	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:3	20.45	3558	1.68	13.42	108	197	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:4	20.45	3557	1.68	13.42	108	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:4	20.45	3556	1.68	13.42	108	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:4	20.45	3561	1.69	13.41	107	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:4	20.45	3563	1.69	13.41	107	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:4	20.45	3564	1.69	13.42	108	197	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:4	20.45	3570	1.69	13.4	108	197	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:4	20.45	3569	1.69	13.41	108	197	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:5	20.45	3573	1.69	13.41	108	197	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:5	20.45	3572	1.69	13.41	108	197	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:5	20.45	3568	1.69	13.4	108	197	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:5	20.45	3564	1.69	13.4	107	197	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:5	20.45	3564	1.69	13.4	107	197	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:5	20.45	3560	1.69	13.4	107	197	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:6	20.45	3555	1.69	13.39	108	197	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:6	20.45	3554	1.69	13.41	108	197	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:6	20.45	3552	1.69	13.42	108	197	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:6	20.45	3545	1.69	13.42	108	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:6	20.45	3543	1.7	13.41	108	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:6	20.45	3541	1.7	13.43	108	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:6	20.45	3541	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.26	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:7	20.45	3540	1.7	13.41	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:7	20.45	3540	1.7	13.41	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:7	20.45	3541	1.7	13.4	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:7	20.45	3540	1.7	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:7	20.45	3542	1.7	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.26	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:7	20.45	3542	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:8	20.45	3541	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:8	20.45	3541	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:8	20.45	3536	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:8	20.45	3531	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:8	20.45	3530	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:8	20.45	3530	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:9	20.45	3508	1.7	13.43	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:9	20.45	3525	1.7	13.43	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:9	20.45	3516	1.7	13.43	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:9	20.45	3515	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:9	20.45	3508	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:9	20.45	3510	1.7	13.39	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:50:9	20.45	3510	1.7	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:0	20.45	3506	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:0	20.45	3507	1.7	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:0	20.45	3504	1.7	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:0	20.45	3511	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:0	20.45	3511	1.7	13.41	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:0	20.45	3508	1.7	13.41	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:1	20.45	3509	1.7	13.41	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:1	20.45	3494	1.7	13.42	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:1	20.45	3496	1.7	13.42	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:1	20.45	3486	1.7	13.41	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:1	20.45	3481	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:51:1	20.45	3480	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:1	20.45	3478	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:2	20.45	3479	1.7	13.43	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:2	20.45	3485	1.7	13.43	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:2	20.45	3488	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:2	20.45	3493	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:2	20.45	3498	1.7	13.43	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:2	20.45	3498	1.7	13.4	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:3	20.45	3500	1.7	13.41	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:3	20.45	3497	1.7	13.43	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:3	20.45	3494	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:3	20.45	3486	1.7	13.39	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:3	20.45	3485	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:3	20.45	3480	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:4	20.45	3472	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:4	20.45	3466	1.7	13.39	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:4	20.45	3466	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:4	20.45	3462	1.7	13.42	108	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:4	20.45	3460	1.7	13.41	108	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:4	20.45	3458	1.7	13.42	107	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:4	20.45	3455	1.7	13.43	107	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:5	20.45	3456	1.7	13.42	107	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:5	20.45	3467	1.7	13.42	108	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:5	20.45	3452	1.7	13.41	108	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:5	20.45	3425	1.7	13.41	108	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:5	20.45	3436	1.7	13.41	108	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:5	20.45	3446	1.7	13.41	108	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:6	20.45	3446	1.7	13.41	108	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:6	20.45	3448	1.7	13.42	108	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:6	20.45	3448	1.7	13.42	108	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:6	20.45	3446	1.7	13.41	108	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:6	20.45	3448	1.7	13.41	108	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:6	20.45	3451	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:6	20.45	3450	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:7	20.45	3450	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:7	20.45	3450	1.7	13.41	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:7	20.45	3449	1.7	13.42	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.19	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:7	20.45	3446	1.7	13.42	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:7	20.45	3444	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:7	20.45	3437	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:8	20.45	3436	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:8	20.45	3428	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:8	20.45	3425	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:8	20.45	3422	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:8	20.45	3400	1.7	13.42	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:8	20.45	3408	1.7	13.41	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:9	20.45	3404	1.7	13.42	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:9	20.45	3403	1.7	13.42	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:9	20.45	3406	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:9	20.45	3408	1.7	13.42	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:9	20.45	3408	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:9	20.45	3419	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:51:9	20.45	3420	1.7	13.42	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:0	20.45	3422	1.7	13.41	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:0	20.45	3421	1.7	13.41	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:0	20.45	3417	1.7	13.41	108	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:0	20.45	3418	1.7	13.41	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:0	20.45	3412	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:52:0	20.45	3407	1.7	13.42	108	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:1	20.45	3404	1.7	13.42	108	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:1	20.45	3399	1.7	13.42	107	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:1	20.45	3398	1.7	13.41	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:1	20.45	3395	1.7	13.41	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:1	20.45	3392	1.7	13.41	108	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:1	20.45	3389	1.7	13.41	108	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:1	20.45	3388	1.7	13.42	108	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:2	20.45	3382	1.7	13.41	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:2	20.45	3382	1.7	13.41	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:2	20.45	3384	1.7	13.41	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:2	20.45	3386	1.7	13.41	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:2	20.45	3393	1.7	13.41	107	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:2	20.45	3394	1.7	13.4	107	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:3	20.45	3398	1.7	13.41	107	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:3	20.45	3403	1.7	13.42	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:3	20.45	3402	1.7	13.41	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:3	20.45	3401	1.7	13.41	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:3	20.45	3389	1.7	13.41	107	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:3	20.45	3376	1.7	13.42	107	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:4	20.45	3362	1.7	13.41	107	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:4	20.45	3362	1.7	13.42	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:4	20.45	3348	1.7	13.42	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:4	20.45	3342	1.7	13.43	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:4	20.45	3341	1.7	13.42	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:4	20.45	3342	1.7	13.43	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:4	20.45	3329	1.7	13.42	107	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:5	20.45	3366	1.7	13.42	107	197	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:5	20.45	3370	1.7	13.42	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:5	20.45	3387	1.7	13.41	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:5	20.45	3393	1.7	13.41	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:5	20.45	3397	1.7	13.4	107	197	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:5	20.45	3398	1.7	13.41	107	197	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:6	20.45	3390	1.7	13.43	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:6	20.45	3384	1.7	13.43	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:6	20.45	3377	1.7	13.43	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:6	20.45	3361	1.7	13.42	107	198	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:6	20.45	3347	1.7	13.43	107	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:6	20.45	3336	1.7	13.43	107	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:6	20.45	3334	1.7	13.43	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:7	20.45	3316	1.7	13.44	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:7	20.45	3322	1.7	13.44	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:7	20.45	3322	1.7	13.43	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:7	20.45	3318	1.7	13.41	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:7	20.45	3319	1.7	13.41	107	198	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:7	20.45	3319	1.7	13.42	107	197	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:8	20.45	3320	1.7	13.41	107	197	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:8	20.45	3322	1.7	13.4	107	197	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:8	20.45	3322	1.7	13.41	107	197	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:8	20.45	3326	1.7	13.4	107	197	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:8	20.45	3328	1.7	13.39	107	197	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:8	20.45	3328	1.7	13.4	107	198	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:9	20.45	3332	1.7	13.4	107	198	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:9	20.45	3332	1.7	13.41	107	198	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:9	20.45	3333	1.7	13.41	107	198	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:9	20.45	3333	1.7	13.43	107	198	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:9	20.45	3333	1.7	13.42	107	198	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:52:9	20.45	3331	1.7	13.43	107	198	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:52:9	20.45	3331	1.7	13.43	107	198	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:0	20.45	3329	1.7	13.42	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:0	20.45	3327	1.7	13.41	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:0	20.45	3326	1.7	13.43	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:0	20.45	3324	1.7	13.42	107	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:0	20.45	3320	1.7	13.41	107	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:0	20.45	3320	1.7	13.41	108	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:1	20.45	3319	1.7	13.37	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:1	20.45	3328	1.7	13.35	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:1	20.45	3316	1.7	13.35	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:1	20.45	3314	1.7	13.34	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:1	20.45	3298	1.7	13.34	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:1	20.45	3304	1.7	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:1	20.45	3299	1.7	13.38	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:2	20.45	3289	1.7	13.37	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:2	20.45	3289	1.7	13.38	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:2	20.45	3282	1.7	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:2	20.45	3278	1.7	13.37	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:2	20.45	3250	1.7	13.35	108	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:2	20.45	3262	1.7	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:3	20.45	3276	1.7	13.35	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:3	20.45	3276	1.7	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:3	20.45	3280	1.7	13.36	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:3	20.45	3285	1.7	13.36	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:3	20.45	3289	1.7	13.36	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:3	20.45	3289	1.7	13.36	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:4	20.45	3290	1.7	13.36	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:4	20.45	3289	1.7	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:4	20.45	3285	1.7	13.36	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:4	20.45	3283	1.7	13.38	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:4	20.45	3274	1.7	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:4	20.45	3266	1.7	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:4	20.45	3260	1.7	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:5	20.45	3258	1.7	13.38	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:5	20.45	3250	1.7	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:5	20.45	3242	1.7	13.35	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:5	20.45	3239	1.7	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:5	20.45	3214	1.7	13.34	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:5	20.45	3226	1.7	13.36	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:6	20.45	3237	1.7	13.35	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:6	20.45	3264	1.7	13.37	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:6	20.45	3239	1.7	13.36	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:6	20.45	3238	1.7	13.38	107	198	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:6	20.45	3235	1.7	13.36	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:6	20.45	3227	1.7	13.36	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:6	20.45	3174	1.7	13.37	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:7	20.45	3198	1.7	13.37	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:7	20.45	3216	1.7	13.38	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:7	20.45	3210	1.7	13.37	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:7	20.45	3203	1.7	13.37	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:7	20.45	3200	1.7	13.37	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:7	20.45	3197	1.7	13.37	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:8	20.45	3195	1.7	13.37	107	198	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:8	20.45	3194	1.7	13.38	107	198	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:8	20.45	3190	1.7	13.37	107	198	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:8	20.45	3191	1.7	13.38	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:8	20.45	3189	1.7	13.36	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:8	20.45	3186	1.7	13.37	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:53:9	20.45	3184	1.7	13.37	107	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:9	20.45	3178	1.7	13.36	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:9	20.45	3178	1.7	13.37	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:9	20.45	3170	1.7	13.37	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:9	20.45	3165	1.7	13.39	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:9	20.45	3165	1.69	13.38	107	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:53:9	20.45	3160	1.69	13.39	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:0	20.45	3154	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:0	20.45	3126	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:0	20.45	3137	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:0	20.45	3144	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:0	20.45	3144	1.69	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:0	20.45	3138	1.69	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:1	20.45	3138	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:1	20.45	3148	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:1	20.45	3129	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.27	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:1	20.45	3099	1.69	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:1	20.45	3108	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:1	20.45	3113	1.69	13.38	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:1	20.45	3113	1.69	13.37	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:2	20.45	3105	1.69	13.36	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:2	20.45	3105	1.69	13.37	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:2	20.45	3097	1.69	13.37	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:2	20.45	3097	1.69	13.36	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:2	20.45	3096	1.69	13.37	107	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:2	20.45	3097	1.69	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:3	19.09	3082	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:3	19.09	3088	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:3	19.09	3083	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:3	19.09	3080	1.69	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:3	19.09	3073	1.69	13.35	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:3	19.09	3070	1.69	13.35	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:4	19.09	3062	1.69	13.35	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:4	19.09	3053	1.69	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:4	19.09	3020	1.69	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:4	19.09	3032	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:4	19.09	3038	1.69	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:4	19.09	3038	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:4	19.09	3030	1.69	13.36	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:5	19.09	3028	1.69	13.36	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:5	19.09	3046	1.69	13.35	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:5	19.09	3014	1.69	13.36	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:5	19.09	3012	1.69	13.35	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:5	19.09	3007	1.69	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:5	19.09	3006	1.69	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:6	19.09	3016	1.69	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:6	19.09	3006	1.69	13.38	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:6	19.09	3006	1.69	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:6	19.09	3002	1.69	13.37	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:6	19.09	3001	1.69	13.36	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:6	19.09	3019	1.69	13.35	107	198	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:6	19.09	3006	1.69	13.35	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:7	19.09	2980	1.69	13.36	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:7	19.09	2984	1.69	13.35	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:7	19.09	2982	1.69	13.35	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:7	19.09	2980	1.69	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:7	19.09	2974	1.69	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:7	19.09	2969	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:54:8	19.09	2963	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:8	19.09	2962	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:8	19.09	2951	1.69	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:8	19.09	2942	1.69	13.38	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:8	19.09	2914	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:8	19.09	2924	1.69	13.37	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:9	19.09	2931	1.69	13.36	107	198	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:9	19.09	2947	1.69	13.37	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:9	19.09	2947	1.69	13.36	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:9	19.09	2906	1.69	13.36	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:9	19.09	2914	1.69	13.35	107	198	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:9	19.09	2914	1.69	13.35	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:54:9	19.09	2926	1.69	13.34	107	198	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:0	19.09	2912	1.69	13.34	107	198	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:0	19.09	2913	1.69	13.36	107	198	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:0	19.09	2892	1.69	13.35	107	198	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:0	19.09	2914	1.69	13.36	107	198	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:0	19.09	2936	1.69	13.35	107	198	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:0	19.09	2936	1.69	13.37	107	198	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:1	19.09	2914	1.69	13.36	107	198	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:1	19.09	2892	1.69	13.36	107	198	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:1	19.09	2906	1.69	13.36	107	198	Idle	42.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:1	19.09	2895	1.69	13.36	107	198	Idle	42.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:1	19.09	2892	1.69	13.36	107	198	Idle	42.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:1	19.09	2875	1.69	13.36	107	198	Idle	42.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:1	19.09	2875	1.69	13.37	107	198	Idle	42.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:2	19.09	2860	1.69	13.37	107	198	Idle	42.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:2	19.09	2851	1.69	13.35	107	198	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:2	19.09	2843	1.69	13.37	107	198	Idle	42.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:2	19.09	2843	1.69	13.37	107	198	Idle	42.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:2	19.09	2836	1.69	13.38	107	198	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:2	19.09	2830	1.69	13.38	107	198	Idle	42.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:3	19.09	2828	1.68	13.39	107	198	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:3	19.09	2815	1.68	13.37	107	198	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:3	19.09	2822	1.68	13.38	107	198	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:3	19.09	2822	1.68	13.37	107	198	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:3	19.09	2824	1.68	13.37	107	198	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:3	19.09	2823	1.68	13.36	107	198	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:4	19.09	2827	1.68	13.36	107	198	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:4	19.09	2825	1.68	13.35	107	198	Idle	43.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.14	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:4	19.09	2825	1.68	13.36	107	198	Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.15	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:4	19.09	2805	1.68	13.36	107	198	Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.15	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:4	19.09	2827	1.68	13.37	107	198	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.15	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:4	19.09	2827	1.68	13.37	107	198	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.15	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:4	19.09	2826	1.68	13.37	107	198	Idle	44.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.16	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:5	19.09	2827	1.67	13.36	107	198	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.15	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:5	19.09	2822	1.67	13.37	107	198	Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.14	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:5	19.09	2822	1.67	13.36	107	198	Idle	45.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.14	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:5	19.09	2816	1.66	13.35	107	198	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:5	19.09	2807	1.66	13.35	107	198	Idle	46.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:5	19.09	2806	1.66	13.36	107	198	Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:6	19.09	2783	1.65	13.35	107	198	Idle	47	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:6	19.09	2783	1.65	13.36	107	198	Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:6	19.09	2775	1.65	13.35	107	198	Idle	47.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:6	19.09	2775	1.64	13.36	107	198	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:6	19.09	2768	1.64	13.37	107	198	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:6	19.09	2761	1.64	13.36	107	198	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:6	19.09	2761	1.63	13.36	107	198	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:55:7	19.09	2762	1.63	13.36	107	198	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:7	19.09	2754	1.63	13.37	107	198	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:7	19.09	2763	1.63	13.36	107	198	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:7	19.09	2763	1.62	13.36	107	198	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:7	19.09	2766	1.62	13.35	107	198	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.26	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:7	19.09	2746	1.62	13.35	107	198	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:8	19.09	2713	1.61	13.35	107	198	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:8	19.09	2720	1.61	13.34	107	198	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:8	19.09	2720	1.61	13.35	107	198	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:8	19.09	2720	1.61	13.35	107	198	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:8	19.09	2720	1.61	13.36	107	198	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:8	19.09	2722	1.61	13.35	107	198	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:9	19.09	2725	1.61	13.35	107	197	Idle	49.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:9	19.09	2729	1.6	13.37	107	197	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:9	19.09	2731	1.6	13.38	107	197	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:9	19.09	2731	1.6	13.4	107	197	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:9	19.09	2731	1.6	13.41	107	197	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:9	19.09	2734	1.59	13.41	107	197	Idle	50	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:55:9	19.09	2735	1.59	13.41	107	197	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:0	19.09	2735	1.59	13.41	107	197	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:0	19.09	2733	1.59	13.4	107	197	Idle	50.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:0	19.09	2732	1.58	13.4	107	198	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:0	19.09	2724	1.58	13.4	107	198	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:0	19.09	2711	1.58	13.41	107	198	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:0	19.09	2708	1.57	13.39	107	198	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:1	19.09	2696	1.56	13.4	107	198	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:1	19.09	2691	1.56	13.39	107	198	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:1	19.09	2680	1.55	13.41	107	198	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:1	19.09	2692	1.55	13.4	107	198	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:1	19.09	2701	1.54	13.41	107	198	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:1	19.09	2701	1.54	13.41	107	198	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:1	19.09	2720	1.54	13.41	107	198	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:2	19.09	2735	1.53	13.39	107	198	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:2	19.09	2756	1.53	13.4	107	197	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:2	19.09	2769	1.53	13.41	107	197	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:2	19.09	2769	1.53	13.41	107	197	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:2	19.09	2771	1.53	13.41	107	197	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:2	19.09	2760	1.53	13.41	107	197	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:3	19.09	2752	1.52	13.41	107	197	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:3	19.09	2746	1.52	13.42	107	197	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:3	19.09	2734	1.52	13.41	107	197	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:3	19.09	2702	1.52	13.41	107	198	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:3	19.09	2686	1.52	13.41	107	198	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:3	19.09	2673	1.53	13.41	107	197	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:4	19.09	2644	1.53	13.4	107	197	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:4	19.09	2645	1.53	13.4	107	197	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:4	19.09	2644	1.53	13.41	107	198	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:4	19.09	2620	1.53	13.4	107	198	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:4	19.09	2646	1.53	13.4	107	198	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:4	19.09	2682	1.53	13.41	107	198	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:4	19.09	2682	1.53	13.41	107	198	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:5	19.09	2689	1.54	13.42	107	198	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:5	19.09	2706	1.54	13.41	107	198	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:5	19.09	2722	1.54	13.41	107	198	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:5	19.09	2722	1.54	13.4	107	198	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:5	19.09	2732	1.54	13.4	107	198	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:5	19.09	2708	1.54	13.41	107	198	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:6	19.09	2674	1.54	13.4	107	198	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:56:6	19.09	2679	1.54	13.39	107	198	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:6	19.09	2668	1.54	13.39	107	198	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:6	19.09	2652	1.54	13.4	107	198	Idle	52.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:6	19.09	2643	1.53	13.4	107	198	Idle	53.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:6	19.09	2643	1.53	13.41	107	198	Idle	53.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:6	19.09	2637	1.53	13.41	107	197	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:7	19.09	2640	1.53	13.41	107	197	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:7	19.09	2642	1.53	13.41	107	198	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:7	19.09	2652	1.52	13.42	107	198	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:7	19.09	2666	1.52	13.41	107	198	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:7	19.09	2668	1.52	13.41	107	198	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:7	19.09	2686	1.51	13.41	107	198	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:8	19.09	2677	1.51	13.42	107	198	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.26	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:8	19.09	2678	1.51	13.41	107	198	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:8	19.09	2678	1.5	13.41	107	197	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:8	19.09	2674	1.5	13.41	107	197	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:8	19.09	2672	1.5	13.41	107	198	Idle	54.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:8	19.09	2660	1.49	13.4	107	198	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:9	19.09	2653	1.49	13.41	107	198	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:9	19.09	2644	1.49	13.39	107	198	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:9	19.09	2639	1.48	13.4	107	198	Idle	55.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:9	19.09	2638	1.48	13.4	107	198	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:9	19.09	2628	1.48	13.4	107	198	Idle	56.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:9	19.09	2640	1.48	13.4	107	198	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:56:9	19.09	2645	1.47	13.39	107	198	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:0	19.09	2651	1.47	13.39	107	198	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:0	19.09	2651	1.47	13.4	107	198	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:0	19.09	2667	1.47	13.4	107	198	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:0	19.09	2661	1.47	13.41	107	198	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:0	19.09	2663	1.47	13.41	107	198	Idle	56.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:0	19.09	2662	1.47	13.41	107	198	Idle	56.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:1	19.09	2659	1.46	13.39	107	198	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:1	19.09	2654	1.46	13.41	107	197	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:1	19.09	2647	1.46	13.4	107	197	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:1	19.09	2647	1.46	13.4	107	197	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:1	19.09	2640	1.46	13.4	107	198	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:1	19.09	2634	1.45	13.41	107	198	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:1	19.09	2626	1.45	13.41	107	198	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:2	19.09	2625	1.45	13.41	107	197	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:2	19.09	2617	1.45	13.41	107	197	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:2	19.09	2613	1.45	13.41	107	198	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:2	19.09	2612	1.45	13.41	107	198	Idle	57.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:2	19.09	2608	1.45	13.41	107	198	Idle	57.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:2	19.09	2610	1.45	13.4	107	198	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:3	19.09	2612	1.45	13.39	107	198	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:3	19.09	2614	1.45	13.4	107	198	Idle	57.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:3	19.09	2620	1.45	13.4	107	198	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:3	19.09	2625	1.44	13.4	107	198	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:3	19.09	2628	1.44	13.41	107	198	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.26	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:3	19.09	2628	1.44	13.41	107	198	Idle	57.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:4	19.09	2630	1.44	13.4	107	198	Idle	57.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:4	19.09	2629	1.44	13.39	107	198	Idle	58.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:4	19.09	2626	1.43	13.39	107	198	Idle	58.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:4	19.09	2624	1.43	13.39	107	198	Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:4	19.09	2616	1.43	13.4	107	198	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:4	19.09	2608	1.43	13.4	107	198	Idle	58.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:4	19.09	2603	1.43	13.41	107	198	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:5	19.09	2603	1.43	13.41	107	198	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:57:5	19.09	2598	1.43	13.41	107	197	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:5	19.09	2596	1.43	13.42	107	197	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:5	19.09	2592	1.43	13.41	107	198	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:5	19.09	2592	1.42	13.41	107	198	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:5	19.09	2591	1.42	13.41	107	198	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:6	19.09	2592	1.42	13.4	107	198	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:6	19.09	2596	1.42	13.41	107	198	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:6	19.09	2598	1.42	13.4	107	198	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:6	19.09	2599	1.42	13.41	107	198	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:6	19.09	2601	1.42	13.41	107	198	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:6	19.09	2602	1.42	13.41	107	198	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:6	19.09	2602	1.42	13.41	107	197	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:7	19.09	2598	1.42	13.41	107	197	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:7	19.09	2595	1.42	13.41	107	197	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:7	19.09	2593	1.42	13.41	107	198	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:7	19.09	2588	1.42	13.41	107	198	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:7	19.09	2580	1.42	13.4	107	198	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:7	19.09	2577	1.41	13.41	107	198	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:8	19.09	2576	1.41	13.41	107	198	Idle	60	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:8	19.09	2576	1.41	13.42	107	197	Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:8	19.09	2575	1.41	13.42	107	197	Idle	60.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:8	19.09	2575	1.41	13.41	107	197	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:8	19.09	2576	1.41	13.41	107	197	Full Load	60.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:8	19.09	2568	1.41	13.4	107	197	Off Idle	60.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:57:9	19.09	2576	1.41	13.4	107	198	Off Idle	60.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:57:9	9.54	2512	1.41	13.4	107	198	Off Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:57:9	12.27	2606	1.41	13.4	107	198	Off Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:57:9	12.27	2596	1.41	13.39	107	197	Off Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:57:9	14.99	2595	1.42	13.39	107	197	Off Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:57:9	17.72	2591	1.42	13.4	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:57:9	17.72	2590	1.42	13.41	107	198	Off Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:58:0	20.45	2590	1.42	13.42	107	198	Off Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:58:0	23.18	2586	1.43	13.43	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:58:0	23.18	2584	1.43	13.41	107	197	Off Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:58:0	25.9	2588	1.43	13.41	107	197	Off Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:58:0	28.63	2592	1.44	13.4	107	197	Off Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:58:0	28.63	2598	1.45	13.4	107	197	Off Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:58:1	31.36	2601	1.46	13.4	107	197	Off Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:58:1	34.08	2602	1.47	13.41	107	198	Off Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:58:1	34.08	2621	1.48	13.4	107	198	Off Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:1	35.45	2580	1.49	13.4	107	198	Off Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:1	35.45	2586	1.5	13.41	107	198	Off Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:1	35.45	2586	1.5	13.39	107	198	Off Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:1	35.45	2578	1.52	13.41	107	198	Off Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:2	35.45	2572	1.53	13.39	107	198	Off Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:2	35.45	2562	1.54	13.4	107	198	Off Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:2	35.45	2562	1.54	13.39	107	198	Off Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:2	35.45	2552	1.55	13.41	107	198	Off Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:2	35.45	2553	1.56	13.4	107	198	Off Idle	62	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.96	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:2	35.45	2553	1.57	13.41	107	198	Off Idle	62.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.92	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:3	35.45	2549	1.58	13.41	107	198	Off Idle	62.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.89	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:3	35.45	2542	1.59	13.42	107	198	Off Idle	62.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.88	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:3	35.45	2542	1.59	13.4	107	198	Off Idle	62.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.87	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:3	35.45	2546	1.6	13.4	107	198	Off Idle	62.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.88	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:3	35.45	2548	1.6	13.39	107	198	Off Idle	62.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.88	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:3	35.45	2553	1.6	13.4	107	198	Off Idle	62.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.89	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:4	35.45	2561	1.6	13.39	107	198	Off Idle	62.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.9	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:4	35.45	2561	1.6	13.4	107	198	Off Idle	63.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:58:4	35.45	2560	1.6	13.39	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.93	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:4	35.45	2563	1.6	13.39	107	198	Off Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.91	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:4	35.45	2562	1.6	13.39	107	198	Off Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:4	35.45	2561	1.6	13.4	107	198	Off Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.92	20.17	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:4	35.45	2556	1.6	13.38	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.92	20.05	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:5	35.45	2554	1.6	13.39	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.9	19.9	1.36	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:5	35.45	2553	1.6	13.39	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.9	19.81	1.35	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:58:5	35.45	2549	1.6	13.38	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.91	19.43	1.32	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:5	35.45	2549	1.6	13.39	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.88	19.15	1.3	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:5	35.45	2548	1.59	13.39	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.88	18.85	1.28	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:5	35.45	2548	1.59	13.39	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.88	18.53	1.26	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:6	35.45	2553	1.59	13.39	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.86	18.04	1.23	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:6	35.45	2554	1.59	13.4	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.85	17.72	1.21	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:6	35.45	2552	1.6	13.39	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.84	17.45	1.19	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:6	35.45	2549	1.6	13.39	107	197	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.8	17.2	1.17	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:6	35.45	2546	1.6	13.4	107	197	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.77	16.99	1.16	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:6	35.45	2551	1.6	13.39	107	198	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.78	16.78	1.14	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:6	35.45	2552	1.61	13.4	107	198	Off Idle	62.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.77	16.64	1.13	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:7	35.45	2549	1.61	13.4	107	198	Off Idle	63.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.75	16.52	1.13	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:7	35.45	2547	1.61	13.4	107	198	Off Idle	63.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.74	16.47	1.12	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:7	35.45	2547	1.62	13.41	107	198	Off Idle	63.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.73	16.39	1.12	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:58:7	35.45	2547	1.62	13.41	107	198	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.69	16.28	1.11	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:7	35.45	2552	1.63	13.4	107	198	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.67	16.19	1.1	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:7	35.45	2552	1.63	13.38	107	198	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.66	16.12	1.1	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:8	35.45	2556	1.64	13.39	107	198	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.63	16.03	1.09	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:8	35.45	2558	1.64	13.38	107	198	Off Idle	63.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.62	15.97	1.09	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:8	35.45	2560	1.64	13.39	107	198	Off Idle	63.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.63	15.92	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:8	35.45	2560	1.65	13.4	107	198	Off Idle	63.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.6	15.88	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:8	35.45	2561	1.65	13.39	107	198	Off Idle	63.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.62	15.84	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:8	35.45	2554	1.65	13.39	107	198	Off Idle	63.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.61	15.78	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:9	35.45	2554	1.66	13.39	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.61	15.73	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:9	35.45	2554	1.66	13.41	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.63	15.68	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:9	35.45	2555	1.66	13.41	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.62	15.66	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:9	35.45	2551	1.67	13.41	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.6	15.65	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:9	35.45	2552	1.67	13.41	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.6	15.6	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:9	35.45	2543	1.67	13.41	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.59	15.57	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:58:9	35.45	2542	1.67	13.4	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.59	15.54	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:0	35.45	2540	1.67	13.38	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.59	15.53	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:0	35.45	2525	1.67	13.39	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.56	15.49	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:0	35.45	2526	1.67	13.4	107	198	Off Idle	63.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.55	15.46	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:0	35.45	2523	1.67	13.4	107	197	Off Idle	63.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.54	15.45	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:0	35.45	2522	1.67	13.41	107	197	Off Idle	64	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.54	15.43	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:0	35.45	2521	1.67	13.4	107	197	Off Idle	64	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.53	15.39	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:1	35.45	2522	1.67	13.4	107	197	Off Idle	64	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.56	15.34	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:1	35.45	2505	1.67	13.41	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.56	15.31	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:1	35.45	2528	1.67	13.39	107	197	Off Idle	64.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.56	15.26	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:1	35.45	2527	1.67	13.39	107	197	Off Idle	64.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.56	15.2	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:1	35.45	2521	1.67	13.38	107	198	Off Idle	64.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.57	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:1	35.45	2521	1.67	13.37	107	198	Off Idle	64.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.57	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:1	35.45	2524	1.67	13.39	107	198	Off Idle	65.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.56	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:2	35.45	2522	1.66	13.4	107	198	Off Idle	65.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.59	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:2	35.45	2522	1.66	13.39	107	198	Off Idle	65.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.59	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:2	35.45	2524	1.66	13.4	107	198	Off Idle	65.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.6	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:2	35.45	2519	1.66	13.41	107	198	Off Idle	65.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.58	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:2	35.45	2502	1.66	13.41	107	198	Off Idle	65.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.59	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:2	35.45	2511	1.65	13.41	107	198	Off Idle	65.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.6	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:3	35.45	2513	1.65	13.4	107	198	Off Idle	65.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.62	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:3	35.45	2522	1.65	13.4	107	198	Off Idle	65.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.61	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:14:59:3	35.45	2524	1.65	13.39	107	198	Off Idle	65.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.64	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:3	35.45	2533	1.65	13.4	107	198	Off Idle	65.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.65	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:3	35.45	2528	1.64	13.4	107	198	Off Idle	65.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.65	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:3	35.45	2536	1.64	13.41	107	198	Off Idle	65.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.65	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:4	35.45	2537	1.64	13.41	107	198	Off Idle	65.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.65	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:4	35.45	2537	1.64	13.41	107	198	Off Idle	65.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.65	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:4	35.45	2540	1.64	13.41	107	198	Off Idle	65.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.63	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:4	35.45	2538	1.64	13.41	107	198	Off Idle	64.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.66	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:4	35.45	2545	1.64	13.41	107	198	Off Idle	64.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.66	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:4	35.45	2544	1.64	13.41	107	198	Off Idle	64.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.66	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:4	35.45	2547	1.64	13.4	107	198	Off Idle	64.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.64	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:5	35.45	2542	1.64	13.39	107	198	Off Idle	64.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.62	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:14:59:5	35.45	2539	1.64	13.41	107	198	Off Idle	64.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.59	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:5	35.45	2536	1.64	13.39	107	198	Off Idle	64.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.6	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:5	35.45	2533	1.64	13.4	107	198	Off Idle	64.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.6	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:5	35.45	2534	1.64	13.41	107	198	Off Idle	64.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.65	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:5	35.45	2528	1.64	13.41	107	197	Off Idle	64.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.68	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:6	35.45	2518	1.64	13.4	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.69	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:6	35.45	2518	1.64	13.41	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.7	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:6	35.45	2518	1.63	13.39	107	198	Off Idle	64.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.75	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:14:59:6	35.45	2516	1.62	13.38	107	198	Off Idle	64.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.8	15.16	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:14:59:6	35.45	2514	1.61	13.38	107	198	Off Idle	64.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.85	15.17	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:59:6	35.45	2512	1.6	13.39	107	197	Idle	64.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.98	15.17	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:59:6	35.45	2511	1.58	13.39	107	197	Idle	64.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.06	15.16	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:59:7	35.45	2507	1.55	13.41	107	197	Idle	64.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.19	15.13	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:59:7	35.45	2492	1.53	13.41	107	197	Idle	64.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.25	15.12	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:59:7	35.45	2487	1.51	13.4	107	197	Idle	65	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.32	15.14	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:14:59:7	35.45	2481	1.5	13.39	107	197	Idle	65.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.38	15.12	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:59:7	35.45	2478	1.48	13.39	107	197	Idle	64.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.4	15.1	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:59:7	35.45	2460	1.45	13.39	107	197	Idle	64.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.46	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:59:8	35.45	2432	1.44	13.39	107	197	Idle	64.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.47	15.04	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:59:8	32.72	2416	1.42	13.39	107	197	Idle	64.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.45	15.01	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:59:8	32.72	2416	1.4	13.39	107	197	Idle	63.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.46	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:14:59:8	27.27	2432	1.38	13.39	107	197	Idle	63.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.44	14.97	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:59:8	21.81	2460	1.37	13.4	107	197	Idle	62.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.47	14.93	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:14:59:8	21.81	2517	1.36	13.38	107	197	Idle	62.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.47	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:59:9	19.09	2521	1.35	13.38	107	197	Idle	61.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-10.47	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:59:9	19.09	2534	1.35	13.4	107	197	Idle	61.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10.45	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:59:9	19.09	2538	1.34	13.4	107	198	Idle	61.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.44	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:59:9	19.09	2539	1.34	13.4	107	198	Idle	60.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.42	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:59:9	19.09	2534	1.34	13.42	107	198	Idle	60.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.42	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:59:9	19.09	2530	1.35	13.4	107	198	Idle	60.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.43	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:14:59:9	19.09	2530	1.36	13.41	107	198	Idle	60.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.46	14.83	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:0	19.09	2494	1.36	13.41	107	198	Idle	61.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.47	14.83	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:0	19.09	2467	1.36	13.41	107	197	Idle	61.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.48	14.84	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:0	19.09	2467	1.36	13.41	107	197	Idle	61.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.5	14.83	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:0	19.09	2458	1.36	13.42	107	197	Idle	62.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.44	14.85	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:0	19.09	2452	1.36	13.41	107	197	Idle	62.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.42	14.86	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:0	19.09	2434	1.36	13.41	107	197	Idle	63.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	14.86	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:1	19.09	2446	1.37	13.41	107	197	Idle	63.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:1	19.09	2464	1.37	13.4	107	198	Idle	63.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:1	17.72	2478	1.37	13.41	107	198	Idle	63.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.34	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:1	17.72	2486	1.36	13.4	107	198	Idle	63.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	14.86	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:1	17.72	2496	1.36	13.41	107	197	Idle	63.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	14.9	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:1	19.09	2492	1.35	13.41	107	197	Idle	63.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:1	19.09	2494	1.35	13.4	107	197	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:2	19.09	2491	1.35	13.4	107	197	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	15.21	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:2	19.09	2489	1.34	13.41	107	197	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	15.34	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:00:2	19.09	2480	1.34	13.4	107	197	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	15.5	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:2	19.09	2472	1.34	13.4	107	197	Idle	64.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	15.7	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:2	19.09	2464	1.33	13.41	107	197	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	16	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:2	19.09	2464	1.33	13.39	107	197	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	16.2	1.1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:3	19.09	2459	1.32	13.4	107	197	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	16.48	1.12	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:3	19.09	2437	1.32	13.4	107	197	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	16.66	1.13	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:3	19.09	2446	1.32	13.39	107	197	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	16.85	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:3	19.09	2458	1.31	13.4	107	197	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	17.05	1.16	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:3	19.09	2462	1.31	13.41	107	197	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	17.46	1.19	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:3	19.09	2485	1.3	13.41	107	197	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	17.8	1.21	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:4	19.09	2485	1.3	13.41	107	197	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	18.14	1.24	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:4	19.09	2469	1.3	13.41	107	197	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	18.47	1.26	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:4	19.09	2469	1.3	13.41	107	197	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	18.79	1.28	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:4	19.09	2468	1.29	13.41	107	197	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	19.1	1.3	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:4	19.09	2465	1.29	13.4	107	197	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	19.25	1.31	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:4	19.09	2458	1.28	13.4	107	197	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	19.66	1.34	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:4	19.09	2458	1.28	13.4	107	197	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	19.9	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:5	19.09	2452	1.27	13.4	107	197	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.08	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:5	19.09	2446	1.27	13.4	107	197	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:5	19.09	2442	1.27	13.4	107	197	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:5	19.09	2442	1.26	13.41	107	197	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:5	19.09	2421	1.26	13.41	107	197	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:5	19.09	2440	1.26	13.4	107	197	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:6	19.09	2440	1.26	13.41	107	197	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:6	19.09	2442	1.26	13.41	107	197	Full Load	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:6	19.09	2444	1.26	13.39	107	197	Off Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:6	19.09	2446	1.26	13.4	107	197	Off Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:00:6	19.09	2447	1.26	13.39	107	197	Off Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:15:00:6	9.54	2463	1.26	13.4	107	197	Off Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:15:00:6	9.54	2463	1.26	13.41	107	197	Off Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:7	12.27	2460	1.26	13.39	107	197	Off Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:7	14.99	2460	1.27	13.39	107	197	Off Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:7	14.99	2458	1.27	13.39	107	197	Off Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:7	17.72	2454	1.27	13.39	107	197	Off Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:7	20.45	2449	1.27	13.39	107	197	Off Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:7	20.45	2444	1.28	13.4	107	197	Off Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:8	23.18	2445	1.28	13.39	107	197	Off Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:8	25.9	2444	1.28	13.38	107	197	Off Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:8	25.9	2445	1.29	13.38	107	197	Off Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:8	28.63	2445	1.29	13.41	107	197	Off Idle	69.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:00:8	28.63	2445	1.3	13.41	107	197	Off Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:00:8	31.36	2446	1.31	13.42	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:00:9	34.08	2449	1.31	13.43	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:00:9	34.08	2430	1.32	13.41	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:00:9	35.45	2430	1.33	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:00:9	35.45	2424	1.33	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:00:9	35.45	2430	1.33	13.38	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:00:9	35.45	2431	1.34	13.38	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:00:9	35.45	2432	1.34	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:0	35.45	2433	1.34	13.38	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:0	35.45	2432	1.35	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:0	35.45	2432	1.35	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:0	35.45	2428	1.36	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:0	35.45	2421	1.36	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:0	35.45	2421	1.36	13.38	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:1	35.45	2420	1.36	13.37	107	197	Off Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:1	35.45	2418	1.36	13.39	107	197	Off Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:1	35.45	2418	1.36	13.37	107	197	Off Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:01:1	35.45	2413	1.36	13.36	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.34	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:1	35.45	2413	1.37	13.37	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:1	35.45	2414	1.37	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:1	35.45	2417	1.37	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:2	35.45	2415	1.37	13.41	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:2	35.45	2412	1.37	13.41	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:2	35.45	2407	1.37	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:2	35.45	2405	1.37	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:2	35.45	2406	1.37	13.39	107	197	Off Idle	70.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.36	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:2	35.45	2409	1.37	13.38	107	197	Off Idle	70.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.35	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:3	35.45	2398	1.37	13.41	107	197	Off Idle	70.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:3	35.45	2398	1.37	13.41	107	197	Off Idle	70.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:3	35.45	2400	1.37	13.41	107	197	Off Idle	70.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:01:3	35.45	2412	1.37	13.4	107	197	Off Idle	70.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:3	35.45	2407	1.37	13.4	107	197	Off Idle	70.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:3	35.45	2409	1.37	13.42	107	197	Off Idle	71	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:4	35.45	2409	1.37	13.41	107	197	Off Idle	71	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.37	20.17	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:4	35.45	2408	1.37	13.41	107	197	Off Idle	71	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.36	20.01	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:4	35.45	2408	1.37	13.4	107	197	Off Idle	71	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.35	19.86	1.35	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:01:4	35.45	2408	1.37	13.38	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.37	19.7	1.34	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:4	35.45	2407	1.37	13.39	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.34	19.49	1.33	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:4	35.45	2404	1.36	13.39	107	197	Off Idle	71.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.33	19.13	1.3	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:4	35.45	2385	1.36	13.39	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.35	18.87	1.29	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:01:5	35.45	2393	1.36	13.4	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.37	18.6	1.27	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:01:5	35.45	2398	1.36	13.39	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.36	18.34	1.25	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:5	35.45	2395	1.35	13.4	107	197	Off Idle	71.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.41	17.99	1.23	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:5	35.45	2390	1.35	13.41	107	197	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.44	17.79	1.21	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:5	35.45	2398	1.35	13.4	107	197	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.45	17.59	1.2	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:5	35.45	2387	1.34	13.4	107	197	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.47	17.33	1.18	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:6	35.45	2384	1.34	13.4	107	197	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.46	17.18	1.17	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:6	35.45	2383	1.34	13.39	107	197	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.48	17.11	1.17	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:6	35.45	2384	1.34	13.38	107	197	Off Idle	72.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.47	16.97	1.16	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:6	35.45	2388	1.34	13.4	107	197	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.45	16.85	1.15	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:6	35.45	2395	1.33	13.39	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.48	16.68	1.14	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:6	35.45	2400	1.33	13.38	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.45	16.56	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:6	35.45	2392	1.33	13.4	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.44	16.51	1.12	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:7	35.45	2406	1.33	13.4	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.43	16.38	1.12	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:7	35.45	2406	1.32	13.39	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.43	16.29	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:7	35.45	2404	1.32	13.4	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.4	16.22	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:7	35.45	2404	1.32	13.4	107	197	Off Idle	72.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.39	16.15	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:7	35.45	2392	1.32	13.38	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.39	16.08	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:7	35.45	2392	1.32	13.38	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.36	16.03	1.09	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:01:8	35.45	2382	1.33	13.4	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.34	15.95	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:01:8	35.45	2380	1.33	13.4	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.32	15.89	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:01:8	35.45	2380	1.34	13.39	107	197	Off Idle	72.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.31	15.85	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:01:8	35.45	2380	1.35	13.4	107	197	Off Idle	72.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.27	15.78	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:01:8	35.45	2382	1.35	13.4	107	197	Off Idle	72.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.25	15.74	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:01:8	35.45	2388	1.36	13.38	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.23	15.71	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:01:9	35.45	2389	1.36	13.39	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.19	15.67	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:01:9	35.45	2391	1.37	13.4	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.16	15.63	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:01:9	35.45	2394	1.38	13.39	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.15	15.59	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:01:9	35.45	2394	1.39	13.4	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.12	15.54	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:01:9	35.45	2394	1.4	13.4	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.09	15.51	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:01:9	35.45	2392	1.41	13.4	107	197	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.06	15.47	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:01:9	35.45	2390	1.42	13.41	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.02	15.44	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:0	35.45	2387	1.43	13.42	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10	15.4	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:0	35.45	2387	1.44	13.41	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.98	15.38	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:0	35.45	2384	1.45	13.42	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.95	15.36	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:02:0	35.45	2383	1.45	13.41	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.94	15.34	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:0	35.45	2383	1.46	13.38	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.94	15.34	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:0	35.45	2384	1.47	13.39	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.9	15.33	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:1	35.45	2382	1.48	13.39	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.86	15.32	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:1	35.45	2382	1.49	13.39	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.79	15.31	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:1	35.45	2383	1.49	13.4	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.76	15.3	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:1	35.45	2380	1.5	13.41	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.71	15.31	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:1	35.45	2380	1.51	13.4	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.71	15.31	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:1	35.45	2381	1.52	13.39	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.71	15.31	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:1	35.45	2381	1.52	13.38	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.69	15.32	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:2	35.45	2381	1.53	13.38	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.66	15.3	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:2	35.45	2388	1.54	13.39	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.63	15.29	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:2	35.45	2392	1.54	13.37	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.62	15.3	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:2	35.45	2399	1.55	13.4	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.56	15.26	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:2	35.45	2400	1.55	13.4	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.56	15.25	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:2	35.45	2404	1.56	13.39	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.55	15.23	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:3	35.45	2403	1.56	13.4	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.49	15.21	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:3	35.45	2402	1.57	13.39	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.48	15.18	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:3	35.45	2404	1.58	13.39	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.47	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:3	35.45	2409	1.58	13.4	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.47	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:3	35.45	2409	1.58	13.4	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.48	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:3	35.45	2403	1.58	13.41	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.5	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:4	35.45	2403	1.59	13.4	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.52	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:4	35.45	2396	1.59	13.4	107	197	Off Idle	72.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.5	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:4	35.45	2380	1.59	13.41	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.47	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:4	35.45	2372	1.6	13.4	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.46	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:02:4	35.45	2370	1.6	13.41	107	197	Off Idle	72.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.42	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:4	35.45	2364	1.6	13.41	107	197	Off Idle	72.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.4	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:4	35.45	2339	1.6	13.41	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.38	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:5	34.08	2360	1.6	13.4	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.35	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:5	34.08	2361	1.61	13.41	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.32	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:02:5	34.08	2361	1.61	13.4	107	197	Off Idle	73	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.3	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:5	34.08	2361	1.62	13.39	107	197	Off Idle	73.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.28	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:5	34.08	2366	1.62	13.39	107	197	Off Idle	73.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.22	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:5	34.08	2367	1.63	13.4	107	197	Off Idle	73.7	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.14	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:02:6	34.08	2368	1.64	13.39	107	197	Off Idle	73.8	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.06	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:02:6	34.08	2376	1.65	13.41	107	197	Off Idle	73.9	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.99	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:02:6	34.08	2384	1.66	13.39	107	197	Off Idle	74	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.93	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:6	34.08	2407	1.67	13.4	107	197	Off Idle	74.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.83	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:6	34.08	2400	1.68	13.4	107	197	Off Idle	74.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.79	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:6	34.08	2402	1.69	13.4	107	197	Off Idle	74.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.76	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:6	34.08	2404	1.71	13.4	107	197	Off Idle	74.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.67	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:7	34.08	2406	1.72	13.41	107	197	Off Idle	73.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.56	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:7	34.08	2406	1.73	13.4	107	197	Off Idle	73.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.51	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:7	34.08	2395	1.75	13.4	107	197	Off Idle	73.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.44	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:7	34.08	2383	1.76	13.39	107	197	Off Idle	73	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.38	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:7	34.08	2356	1.77	13.41	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.36	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:7	34.08	2356	1.79	13.4	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.33	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:02:8	34.08	2361	1.8	13.39	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.31	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:8	34.08	2354	1.81	13.4	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.25	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:8	34.08	2350	1.82	13.38	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.21	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:8	34.08	2350	1.82	13.37	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.18	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:8	34.08	2356	1.83	13.38	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.16	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:8	34.08	2368	1.84	13.39	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.12	15.14	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:9	34.08	2382	1.84	13.39	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.13	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:9	34.08	2382	1.85	13.39	107	197	Off Idle	73	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.07	15.17	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:9	34.08	2396	1.86	13.4	107	197	Off Idle	73	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.05	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:9	34.08	2405	1.87	13.41	107	197	Off Idle	73.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.02	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:02:9	34.08	2408	1.87	13.41	107	197	Off Idle	73.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.93	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:02:9	34.08	2422	1.88	13.41	107	197	Off Idle	73.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.9	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:02:9	34.08	2409	1.88	13.41	107	197	Off Idle	73.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.89	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:03:0	34.08	2409	1.89	13.4	107	197	Off Idle	73.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:03:0	34.08	2408	1.9	13.4	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.9	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:03:0	34.08	2386	1.9	13.39	107	197	Off Idle	72.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:03:0	34.08	2385	1.91	13.38	107	197	Off Idle	72.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	14.76	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:03:0	34.08	2384	1.91	13.4	107	197	Off Idle	72	0	2	132	944 Turbo	0.68	Lean	1	14.6	-7.64	14.74	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:03:0	34.08	2376	1.92	13.4	107	197	Off Idle	72	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.61	14.72	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:03:1	34.08	2371	1.92	13.39	107	197	Off Idle	72	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.58	14.7	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:03:1	34.08	2371	1.93	13.4	107	197	Off Idle	71.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.47	14.7	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:03:1	34.08	2370	1.94	13.4	107	197	Off Idle	71.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.47	14.72	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:1	34.08	2374	1.94	13.41	107	197	Off Idle	71.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.45	14.74	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:1	34.08	2379	1.95	13.4	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.38	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:1	34.08	2382	1.96	13.4	107	197	Off Idle	72.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.35	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:1	34.08	2388	1.96	13.4	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.28	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:2	34.08	2394	1.97	13.4	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.17	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:2	34.08	2400	1.98	13.41	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.15	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:2	34.08	2399	1.99	13.42	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.04	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:2	34.08	2398	1.99	13.43	107	197	Off Idle	73	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.01	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:03:2	34.08	2400	2	13.42	107	197	Off Idle	73.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.96	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:03:2	34.08	2399	2.01	13.42	107	197	Off Idle	73	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.86	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:3	34.08	2398	2.01	13.41	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.85	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:3	34.08	2398	2.02	13.42	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.85	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:3	34.08	2396	2.02	13.4	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.89	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:3	34.08	2396	2.03	13.39	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-6.9	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:3	34.08	2394	2.03	13.38	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.9	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:3	34.08	2376	2.04	13.37	107	197	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.89	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:4	32.72	2376	2.05	13.36	107	197	Off Idle	71.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.78	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:4	32.72	2395	2.05	13.38	107	197	Off Idle	71.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.73	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:4	32.72	2397	2.06	13.39	107	197	Off Idle	71.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.68	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:4	32.72	2396	2.06	13.4	107	197	Off Idle	71.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.68	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:4	32.72	2421	2.06	13.39	107	197	Off Idle	71.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.7	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:4	32.72	2413	2.07	13.4	107	197	Off Idle	71.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.73	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:4	32.72	2401	2.07	13.39	107	197	Off Idle	71.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.7	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:5	32.72	2400	2.07	13.41	107	197	Off Idle	72	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.69	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:5	32.72	2401	2.07	13.41	107	197	Off Idle	72	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.71	14.75	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:5	32.72	2396	2.07	13.42	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.71	14.72	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:5	32.72	2396	2.07	13.41	107	197	Off Idle	72.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.75	14.7	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:5	32.72	2396	2.07	13.4	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.75	14.71	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:5	32.72	2390	2.07	13.39	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.76	14.7	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:6	32.72	2392	2.07	13.39	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.72	14.71	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:6	32.72	2398	2.07	13.39	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.72	14.73	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:6	32.72	2401	2.07	13.38	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.7	14.75	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:6	32.72	2402	2.07	13.38	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.67	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:6	32.72	2405	2.07	13.4	107	197	Off Idle	72.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.69	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:6	32.72	2418	2.07	13.39	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.69	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:6	32.72	2409	2.07	13.39	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.71	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:7	32.72	2411	2.07	13.39	107	197	Off Idle	71.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.72	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:7	32.72	2411	2.07	13.4	107	197	Off Idle	71.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.75	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:7	32.72	2412	2.07	13.39	107	197	Off Idle	71.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.74	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:7	32.72	2394	2.07	13.39	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.68	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:7	34.08	2408	2.07	13.41	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.65	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:7	34.08	2406	2.07	13.41	107	197	Off Idle	71	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.64	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:03:8	34.08	2408	2.07	13.41	107	197	Off Idle	71	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.6	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:03:8	34.08	2410	2.07	13.39	107	197	Off Idle	71	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.61	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:8	34.08	2420	2.07	13.4	107	197	Off Idle	70.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.63	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:8	34.08	2412	2.07	13.4	107	197	Off Idle	70.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.66	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:03:8	34.08	2411	2.07	13.4	107	197	Off Idle	70.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.65	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:8	34.08	2394	2.07	13.4	107	197	Off Idle	70.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.62	15.17	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:9	34.08	2394	2.07	13.42	107	197	Off Idle	70.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.6	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:9	34.08	2412	2.08	13.4	107	197	Off Idle	70.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.6	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:9	34.08	2405	2.08	13.4	107	197	Off Idle	70.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.59	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:9	34.08	2404	2.08	13.39	107	197	Off Idle	70.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.59	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:03:9	34.08	2405	2.08	13.4	107	197	Off Idle	71	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.59	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:9	32.72	2391	2.08	13.4	107	197	Off Idle	71.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.55	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:03:9	32.72	2391	2.09	13.39	107	197	Off Idle	71.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.55	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:04:0	32.72	2415	2.09	13.39	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.54	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:04:0	32.72	2419	2.09	13.39	107	197	Off Idle	71.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.54	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:0	32.72	2442	2.09	13.39	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.51	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:0	32.72	2434	2.09	13.4	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.49	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:0	34.08	2438	2.1	13.4	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.46	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:0	34.08	2429	2.1	13.4	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.42	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:1	34.08	2430	2.11	13.41	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.36	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:1	34.08	2432	2.11	13.4	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.17	Rich	1	14.6	-6.34	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:1	34.08	2431	2.11	13.4	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.33	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:1	34.08	2430	2.12	13.41	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.32	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:1	34.08	2430	2.12	13.41	107	197	Off Idle	71.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.31	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:1	34.08	2428	2.13	13.41	107	197	Off Idle	70.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.28	14.9	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:1	34.08	2426	2.13	13.42	107	197	Off Idle	70.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.23	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:2	34.08	2423	2.14	13.42	107	197	Off Idle	70.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.19	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:2	34.08	2423	2.14	13.42	107	197	Off Idle	70.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.18	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:2	34.08	2423	2.14	13.41	107	197	Off Idle	70.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.15	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:2	34.08	2429	2.14	13.41	107	197	Off Idle	70.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.18	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:2	34.08	2428	2.15	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.19	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:2	34.08	2428	2.15	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.15	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:3	34.08	2434	2.15	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.14	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:3	34.08	2440	2.15	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.15	15.18	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:3	34.08	2442	2.16	13.41	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.12	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:3	34.08	2445	2.16	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.17	15.14	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:3	34.08	2445	2.16	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.19	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:3	34.08	2444	2.16	13.41	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.16	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:4	34.08	2437	2.16	13.39	107	197	Off Idle	70	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.18	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:4	34.08	2437	2.16	13.39	107	197	Off Idle	70	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.21	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:4	34.08	2432	2.16	13.4	107	197	Off Idle	69.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.14	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:4	34.08	2434	2.16	13.4	107	197	Off Idle	69.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.13	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:4	34.08	2434	2.16	13.38	107	197	Off Idle	69.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.12	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:4	34.08	2441	2.16	13.38	107	197	Off Idle	69.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.12	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:4	34.08	2417	2.16	13.4	107	197	Off Idle	69.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.11	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:5	34.08	2428	2.16	13.4	107	197	Off Idle	69.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.12	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:5	34.08	2441	2.17	13.39	107	197	Off Idle	69.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.1	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:5	34.08	2443	2.17	13.41	107	197	Off Idle	69.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.1	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:5	34.08	2444	2.17	13.39	107	197	Off Idle	69.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.13	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:5	34.08	2457	2.17	13.37	107	197	Off Idle	69.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.12	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:5	34.08	2451	2.17	13.38	107	197	Off Idle	69.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.1	14.83	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:6	34.08	2450	2.17	13.38	107	197	Off Idle	69.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.12	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:6	34.08	2450	2.17	13.38	107	197	Off Idle	69.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.1	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:6	34.08	2450	2.17	13.4	107	197	Off Idle	69.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.09	14.83	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:6	34.08	2448	2.17	13.38	107	197	Off Idle	69.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.12	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:6	34.08	2444	2.17	13.39	107	197	Off Idle	69.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.11	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:6	34.08	2444	2.17	13.4	107	197	Off Idle	69.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.06	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:6	34.08	2448	2.17	13.4	107	197	Off Idle	69.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.07	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:7	34.08	2454	2.17	13.4	107	197	Off Idle	69.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.11	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:7	34.08	2454	2.17	13.41	107	197	Off Idle	69.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.13	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:7	34.08	2456	2.17	13.41	107	197	Off Idle	69.3	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.15	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:7	34.08	2454	2.17	13.4	107	197	Off Idle	69.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.22	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:04:7	34.08	2455	2.17	13.4	107	197	Off Idle	69.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.22	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:7	34.08	2454	2.17	13.4	107	197	Off Idle	69.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.19	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:8	34.08	2450	2.17	13.39	107	197	Off Idle	69	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.24	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:8	34.08	2448	2.17	13.39	107	197	Off Idle	69	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.21	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:8	34.08	2467	2.17	13.38	107	197	Off Idle	69	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.2	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:8	34.08	2457	2.17	13.37	107	197	Off Idle	68.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.23	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:8	34.08	2450	2.17	13.41	107	197	Off Idle	68.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.22	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:8	34.08	2452	2.17	13.4	107	197	Off Idle	68.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.24	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:9	34.08	2453	2.17	13.4	107	197	Off Idle	68.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.21	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:9	34.08	2455	2.16	13.41	107	197	Off Idle	68.7	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.18	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:9	34.08	2460	2.16	13.4	107	197	Off Idle	68.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.23	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:9	34.08	2461	2.16	13.38	107	197	Off Idle	68.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.26	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:04:9	34.08	2462	2.16	13.4	107	197	Off Idle	69	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.24	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:9	34.08	2466	2.16	13.4	107	197	Off Idle	69	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.29	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:04:9	34.08	2466	2.16	13.39	107	197	Off Idle	69	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.32	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:0	34.08	2463	2.16	13.4	107	197	Off Idle	69	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.25	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:0	34.08	2463	2.16	13.41	107	197	Off Idle	69	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.25	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:0	34.08	2462	2.16	13.4	107	197	Off Idle	69	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.28	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:0	34.08	2463	2.16	13.39	107	197	Off Idle	69	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.23	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:0	34.08	2464	2.16	13.39	107	197	Off Idle	69	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.26	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:0	34.08	2471	2.16	13.39	107	197	Off Idle	69	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.29	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:1	34.08	2471	2.16	13.39	107	197	Off Idle	68.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.3	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:1	34.08	2476	2.16	13.4	107	197	Off Idle	68.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.33	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:1	34.08	2475	2.15	13.4	107	197	Off Idle	68.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.39	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:1	34.08	2473	2.15	13.39	107	197	Off Idle	68.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.4	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:1	34.08	2472	2.15	13.4	107	197	Off Idle	67.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.42	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:1	34.08	2470	2.15	13.39	107	197	Off Idle	67.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.39	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:1	34.08	2467	2.15	13.37	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.37	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:2	34.08	2468	2.15	13.37	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.32	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:2	34.08	2468	2.15	13.4	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.29	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:2	34.08	2472	2.15	13.4	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.3	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:2	34.08	2475	2.15	13.39	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.33	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:2	34.08	2475	2.15	13.41	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.31	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:2	34.08	2476	2.15	13.41	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.38	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:3	34.08	2478	2.15	13.41	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.37	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:3	34.08	2479	2.15	13.41	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.38	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:3	34.08	2478	2.15	13.4	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.4	14.77	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:3	34.08	2480	2.15	13.39	107	197	Off Idle	67.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.41	14.76	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:3	34.08	2481	2.15	13.39	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.41	14.75	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:3	34.08	2480	2.15	13.39	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.38	14.74	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:4	34.08	2477	2.15	13.38	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.38	14.73	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:4	34.08	2474	2.15	13.39	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.37	14.74	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:4	34.08	2474	2.15	13.41	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.33	14.74	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:4	34.08	2474	2.15	13.41	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.32	14.78	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:4	34.08	2475	2.15	13.4	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.3	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:4	34.08	2476	2.15	13.4	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.33	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:4	34.08	2480	2.15	13.39	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.32	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:5	34.08	2480	2.15	13.39	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.33	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:5	34.08	2480	2.15	13.41	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.35	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:5	34.08	2485	2.16	13.42	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.34	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:5	34.08	2490	2.16	13.4	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.37	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:5	34.08	2492	2.16	13.39	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.38	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:5	34.08	2492	2.15	13.39	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.38	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:6	34.08	2492	2.16	13.38	107	197	Off Idle	67.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.39	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:6	34.08	2492	2.16	13.38	107	197	Off Idle	67.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.36	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:6	34.08	2493	2.16	13.4	107	197	Off Idle	67.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.36	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:6	34.08	2493	2.16	13.38	107	197	Off Idle	67.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.34	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:6	34.08	2496	2.16	13.4	107	197	Off Idle	67.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.35	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:05:6	34.08	2500	2.16	13.41	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.35	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:6	34.08	2500	2.16	13.39	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.34	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:05:7	34.08	2499	2.16	13.4	107	197	Off Idle	67.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.33	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:7	34.08	2497	2.16	13.41	107	197	Off Idle	67.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.31	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:7	34.08	2501	2.16	13.4	107	197	Off Idle	67.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.28	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:7	34.08	2499	2.16	13.4	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.33	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:7	34.08	2500	2.17	13.39	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.29	14.77	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:7	34.08	2500	2.17	13.39	107	197	Off Idle	67.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.26	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:8	34.08	2497	2.17	13.38	107	197	Off Idle	67	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.24	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:8	34.08	2493	2.18	13.39	107	197	Off Idle	66.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.18	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:8	34.08	2497	2.18	13.39	107	197	Off Idle	66.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.16	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:8	34.08	2496	2.18	13.39	107	197	Off Idle	66.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.12	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:05:8	34.08	2497	2.18	13.39	107	197	Off Idle	66.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.11	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:05:8	34.08	2496	2.19	13.4	107	197	Off Idle	66.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.07	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:9	34.08	2495	2.19	13.41	107	197	Off Idle	66.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.02	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:05:9	34.08	2497	2.2	13.42	107	197	Off Idle	66.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.97	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:9	34.08	2502	2.2	13.42	107	197	Off Idle	66.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.94	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:9	34.08	2502	2.21	13.41	107	197	Off Idle	66	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.91	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:9	34.08	2503	2.21	13.4	107	197	Off Idle	65.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.84	15.05	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:9	34.08	2506	2.22	13.4	107	197	Off Idle	65.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.82	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:05:9	34.08	2508	2.22	13.4	107	197	Off Idle	65.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.77	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:06:0	34.08	2508	2.23	13.39	107	197	Off Idle	65.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.67	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:0	34.08	2513	2.24	13.38	107	197	Off Idle	65.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.6	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:0	34.08	2514	2.25	13.39	107	197	Off Idle	65.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.56	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:0	34.08	2511	2.26	13.38	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.5	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:0	34.08	2512	2.26	13.39	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.46	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:0	32.72	2504	2.27	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.43	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:1	32.72	2514	2.28	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.29	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:1	32.72	2520	2.28	13.42	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.26	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:1	32.72	2520	2.29	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.23	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:1	32.72	2523	2.29	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.19	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:1	32.72	2526	2.3	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.19	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:1	32.72	2527	2.31	13.4	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.18	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:1	32.72	2528	2.32	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.15	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:2	32.72	2526	2.32	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.16	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:2	32.72	2538	2.33	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.1	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:2	32.72	2511	2.33	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.06	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:2	32.72	2511	2.33	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.02	14.97	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:2	32.72	2506	2.34	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5	15.01	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:2	32.72	2509	2.34	13.4	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.99	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:3	32.72	2502	2.34	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5	15.14	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:3	32.72	2522	2.34	13.4	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.03	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:3	32.72	2532	2.35	13.4	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.03	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:3	32.72	2564	2.35	13.41	107	197	Off Idle	65.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.07	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:3	32.72	2549	2.35	13.39	107	197	Off Idle	65.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.06	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:3	32.72	2548	2.35	13.4	107	197	Off Idle	65.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.05	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:4	32.72	2533	2.35	13.4	107	197	Off Idle	65.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.03	14.91	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:4	32.72	2533	2.35	13.4	107	197	Off Idle	64.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.99	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:4	32.72	2526	2.35	13.4	107	197	Off Idle	64.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.97	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:4	32.72	2526	2.35	13.4	107	197	Off Idle	64.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.96	14.72	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:4	32.72	2518	2.36	13.39	107	197	Off Idle	64.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.96	14.7	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:4	32.72	2514	2.36	13.39	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.9	14.7	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:4	32.72	2514	2.36	13.39	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.92	14.7	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:5	32.72	2520	2.36	13.41	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.93	14.73	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:5	32.72	2532	2.36	13.4	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.92	14.75	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:5	32.72	2541	2.36	13.4	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.93	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:5	32.72	2552	2.36	13.41	107	197	Off Idle	63.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.95	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:5	32.72	2547	2.36	13.39	107	197	Off Idle	63.9	0	2	132	944 Turbo	0.62	Lean	1	14.6	-4.95	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:06:5	32.72	2558	2.36	13.38	107	197	Off Idle	64	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:06:6	32.72	2560	2.36	13.41	107	197	Off Idle	63.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:6	32.72	2560	2.36	13.41	107	197	Off Idle	64	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.02	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:6	32.72	2556	2.36	13.4	107	197	Off Idle	64	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.03	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:6	32.72	2556	2.36	13.4	107	197	Off Idle	64	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.02	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:6	32.72	2554	2.36	13.4	107	197	Off Idle	64	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.02	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:6	32.72	2555	2.36	13.39	107	197	Off Idle	64	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.07	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:6	32.72	2550	2.36	13.4	107	197	Off Idle	64	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.08	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:7	32.72	2551	2.35	13.38	107	197	Off Idle	64	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.09	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:7	32.72	2551	2.35	13.38	107	197	Off Idle	63.8	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.09	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:7	32.72	2549	2.35	13.38	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.15	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:06:7	32.72	2548	2.35	13.39	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.19	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:7	32.72	2547	2.34	13.39	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.23	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:7	32.72	2546	2.34	13.4	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.31	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:8	32.72	2546	2.34	13.39	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.29	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:8	32.72	2545	2.33	13.38	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.34	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:8	32.72	2544	2.33	13.39	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.35	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:8	32.72	2543	2.33	13.37	107	197	Off Idle	63.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.37	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:8	32.72	2544	2.32	13.39	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.36	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:06:8	32.72	2544	2.32	13.39	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.42	15.06	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:06:9	32.72	2546	2.32	13.4	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.46	15.03	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:06:9	32.72	2546	2.31	13.4	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.47	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:06:9	32.72	2554	2.31	13.39	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.49	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:06:9	32.72	2556	2.3	13.4	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.52	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:9	32.72	2559	2.3	13.4	107	197	Off Idle	63.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.52	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:9	32.72	2559	2.29	13.4	107	197	Off Idle	63.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.53	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:06:9	32.72	2562	2.29	13.41	107	197	Off Idle	63.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.57	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:0	32.72	2567	2.29	13.41	107	197	Off Idle	63.7	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.6	14.75	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:0	34.08	2586	2.29	13.39	107	197	Off Idle	63.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.58	14.74	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:0	34.08	2570	2.28	13.38	107	197	Off Idle	63.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.64	14.73	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:0	34.08	2574	2.28	13.39	107	197	Off Idle	63.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.66	14.74	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:0	34.08	2571	2.28	13.38	107	197	Off Idle	63.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.69	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:0	34.08	2571	2.28	13.39	107	197	Off Idle	63.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.69	14.82	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:1	34.08	2571	2.28	13.4	107	197	Off Idle	63.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.71	14.86	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:1	34.08	2569	2.27	13.39	107	197	Off Idle	62.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.71	14.94	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:1	34.08	2569	2.27	13.4	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.72	14.99	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:1	34.08	2569	2.27	13.4	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.69	15.04	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:1	34.08	2559	2.27	13.4	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.73	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:1	34.08	2568	2.27	13.41	107	197	Off Idle	62.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.71	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:1	34.08	2564	2.27	13.41	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.76	15.17	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:2	34.08	2560	2.27	13.41	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.73	15.19	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:2	34.08	2565	2.27	13.41	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.72	15.21	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:2	34.08	2565	2.27	13.4	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.75	15.2	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:2	34.08	2565	2.27	13.4	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.78	15.18	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:2	34.08	2566	2.27	13.41	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.79	15.18	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:2	34.08	2571	2.27	13.4	107	197	Off Idle	62.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.79	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:3	34.08	2574	2.27	13.4	107	197	Off Idle	62.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.77	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:3	34.08	2575	2.27	13.41	107	197	Off Idle	62.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.73	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:3	34.08	2578	2.27	13.41	107	197	Off Idle	62.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.76	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:3	34.08	2580	2.27	13.38	107	197	Off Idle	62.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.74	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:3	34.08	2600	2.27	13.39	107	197	Off Idle	62.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.74	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:3	34.08	2590	2.27	13.39	107	197	Off Idle	62.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.8	14.86	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:4	34.08	2580	2.27	13.4	107	197	Off Idle	62.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.8	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:4	34.08	2586	2.27	13.41	107	197	Off Idle	62.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.79	14.82	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:4	34.08	2586	2.27	13.41	107	197	Off Idle	62	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.79	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:4	34.08	2587	2.27	13.41	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.75	14.88	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:4	34.08	2590	2.27	13.4	107	197	Off Idle	61.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.73	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:4	34.08	2590	2.27	13.39	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.73	14.92	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:07:4	34.08	2586	2.27	13.4	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.73	14.96	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:5	34.08	2583	2.27	13.39	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.78	15.06	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:5	34.08	2583	2.27	13.4	107	197	Off Idle	61.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.81	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:5	34.08	2581	2.27	13.4	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.82	15.09	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:5	34.08	2581	2.28	13.39	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.83	15.07	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:5	34.08	2572	2.28	13.39	107	197	Off Idle	61.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.83	15.04	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:5	34.08	2580	2.28	13.41	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.82	15.01	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:6	34.08	2585	2.28	13.39	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.82	14.97	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:6	34.08	2580	2.28	13.4	107	197	Off Idle	61.7	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.81	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:6	34.08	2564	2.28	13.41	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.8	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:6	34.08	2574	2.28	13.41	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.79	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:6	34.08	2582	2.28	13.4	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.79	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:6	34.08	2583	2.28	13.4	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.81	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:6	34.08	2594	2.28	13.39	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.81	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:7	34.08	2615	2.28	13.39	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.79	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:7	34.08	2606	2.28	13.39	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.78	14.78	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:7	34.08	2598	2.28	13.39	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.76	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:7	34.08	2596	2.28	13.39	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.77	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:7	34.08	2596	2.28	13.4	107	197	Off Idle	61.3	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.76	14.86	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:7	34.08	2599	2.28	13.39	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.8	14.92	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:8	34.08	2599	2.28	13.4	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.78	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:07:8	34.08	2599	2.28	13.4	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.79	14.98	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:8	34.08	2598	2.28	13.4	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.76	15.02	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:8	34.08	2593	2.28	13.41	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.75	15.07	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:8	34.08	2592	2.28	13.39	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.75	15.11	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:8	34.08	2590	2.28	13.4	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.73	15.16	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:9	34.08	2588	2.28	13.4	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.75	15.17	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:9	34.08	2595	2.28	13.41	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.72	15.16	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:9	34.08	2595	2.28	13.4	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.73	15.14	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:9	34.08	2597	2.28	13.41	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.69	15.1	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:9	34.08	2600	2.28	13.41	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.69	15.07	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:9	34.08	2606	2.28	13.41	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.68	15.05	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:07:9	34.08	2608	2.28	13.41	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.66	15.03	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:0	34.08	2610	2.29	13.42	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.71	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:0	34.08	2601	2.29	13.42	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.71	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:0	34.08	2601	2.29	13.42	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.7	14.92	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:0	34.08	2600	2.29	13.42	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.65	14.9	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:0	34.08	2601	2.3	13.43	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.61	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:0	34.08	2612	2.3	13.43	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.52	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:1	34.08	2612	2.3	13.42	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.5	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:1	34.08	2617	2.31	13.41	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.48	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:1	34.08	2617	2.31	13.4	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.5	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:1	34.08	2617	2.31	13.4	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.5	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:1	34.08	2613	2.32	13.41	107	197	Off Idle	61	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.49	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:1	34.08	2611	2.32	13.41	107	197	Off Idle	60.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.48	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:1	34.08	2612	2.32	13.41	107	197	Off Idle	60.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.44	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:2	34.08	2610	2.33	13.41	107	197	Off Idle	60.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.39	15.06	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:2	34.08	2610	2.33	13.41	107	197	Off Idle	60.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.4	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:2	34.08	2611	2.33	13.41	107	197	Off Idle	60.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.36	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:2	34.08	2612	2.33	13.4	107	197	Off Idle	60.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.38	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:2	34.08	2612	2.34	13.41	107	197	Off Idle	60.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.36	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:2	34.08	2612	2.34	13.4	107	197	Off Idle	60.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.39	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:3	34.08	2615	2.34	13.41	107	197	Off Idle	60.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.35	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:3	34.08	2615	2.34	13.41	107	197	Off Idle	59.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.35	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:3	34.08	2623	2.34	13.43	107	197	Off Idle	59.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.34	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:3	34.08	2624	2.34	13.43	107	197	Off Idle	59.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.31	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:3	34.08	2627	2.34	13.42	107	197	Off Idle	59.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.29	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:3	34.08	2628	2.34	13.41	107	197	Off Idle	59.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.31	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:08:4	34.08	2627	2.35	13.41	107	197	Off Idle	59.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.32	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:4	34.08	2625	2.35	13.4	107	197	Off Idle	59.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.33	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:4	34.08	2619	2.35	13.4	107	197	Off Idle	59.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.35	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:4	34.08	2618	2.35	13.4	107	197	Off Idle	60	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.4	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:4	34.08	2611	2.35	13.41	107	197	Off Idle	59.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.39	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:4	34.08	2611	2.35	13.42	107	197	Off Idle	59.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.37	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:4	34.08	2616	2.35	13.41	107	197	Off Idle	59.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.33	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:5	34.08	2618	2.35	13.39	107	197	Off Idle	59.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.33	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:5	34.08	2630	2.35	13.39	107	197	Off Idle	59.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.29	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:5	34.08	2639	2.35	13.4	107	197	Off Idle	59.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.31	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:5	34.08	2648	2.35	13.38	107	197	Off Idle	59.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.3	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:5	34.08	2648	2.35	13.4	107	197	Off Idle	59.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.29	14.89	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:5	34.08	2648	2.35	13.38	107	197	Off Idle	58.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.29	14.89	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:6	34.08	2648	2.36	13.41	107	197	Off Idle	58.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.29	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:6	34.08	2623	2.36	13.41	107	197	Off Idle	58.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.28	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:6	34.08	2631	2.36	13.39	107	197	Off Idle	58.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.28	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:6	34.08	2632	2.36	13.39	107	197	Off Idle	58.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.24	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:6	34.08	2629	2.37	13.4	107	197	Off Idle	57.9	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.24	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:6	34.08	2628	2.37	13.4	107	197	Off Idle	57.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.22	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:6	34.08	2627	2.37	13.41	107	197	Off Idle	57.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.24	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:7	34.08	2631	2.37	13.41	107	197	Off Idle	57.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.2	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:7	34.08	2632	2.37	13.4	107	197	Off Idle	57.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.17	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:7	34.08	2640	2.37	13.41	107	197	Off Idle	57.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.14	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:7	34.08	2647	2.37	13.41	107	197	Off Idle	57.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.12	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:7	34.08	2655	2.37	13.42	107	197	Off Idle	57.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.15	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:7	34.08	2655	2.37	13.43	107	197	Off Idle	57.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.17	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:8	34.08	2652	2.38	13.44	107	197	Off Idle	58	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.21	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:8	34.08	2646	2.38	13.41	107	197	Off Idle	58.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.25	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:8	34.08	2643	2.38	13.41	107	197	Off Idle	58.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.23	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:08:8	34.08	2642	2.38	13.39	107	197	Off Idle	58.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.24	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:8	34.08	2638	2.38	13.39	107	197	Off Idle	58.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.26	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:8	34.08	2636	2.38	13.39	107	197	Off Idle	58.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.26	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:9	34.08	2643	2.38	13.4	107	197	Off Idle	58.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.26	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:9	34.08	2645	2.38	13.4	107	197	Off Idle	58.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.23	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:9	34.08	2645	2.38	13.4	107	197	Off Idle	58.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.27	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:08:9	34.08	2650	2.37	13.41	107	197	Off Idle	58.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.25	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:9	34.08	2652	2.37	13.41	107	197	Off Idle	58.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.23	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:9	34.08	2654	2.37	13.41	107	197	Off Idle	58.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.24	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:08:9	34.08	2655	2.37	13.4	107	197	Off Idle	58.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.26	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:0	34.08	2656	2.37	13.39	107	197	Off Idle	58.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.27	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:0	34.08	2657	2.37	13.38	107	197	Off Idle	58.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.24	14.9	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:0	34.08	2640	2.37	13.4	107	197	Off Idle	58.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.24	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:0	34.08	2659	2.37	13.38	107	197	Off Idle	58.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.26	14.77	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:0	34.08	2659	2.37	13.39	107	197	Off Idle	57.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.25	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:0	34.08	2651	2.37	13.38	107	197	Off Idle	57.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.29	14.74	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:1	34.08	2646	2.37	13.39	107	197	Off Idle	57.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.29	14.75	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:1	34.08	2658	2.37	13.4	107	197	Off Idle	57.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.24	14.75	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:1	34.08	2655	2.37	13.38	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.27	14.79	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:1	34.08	2664	2.37	13.38	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.29	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:1	34.08	2676	2.37	13.39	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.33	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:1	34.08	2676	2.37	13.37	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.29	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:1	34.08	2678	2.37	13.4	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.26	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:2	34.08	2676	2.37	13.4	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.21	14.89	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:2	34.08	2671	2.37	13.39	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.22	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:2	34.08	2664	2.37	13.39	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.24	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:2	34.08	2657	2.37	13.39	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.33	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:2	34.08	2650	2.37	13.39	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.33	15.04	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:2	34.08	2649	2.37	13.39	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.33	15.1	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:09:3	34.08	2651	2.38	13.38	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.71	Lean	1	14.6	-5.31	15.11	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:3	34.08	2657	2.38	13.36	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.29	15.16	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:3	34.08	2667	2.38	13.36	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.3	15.15	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:3	34.08	2670	2.38	13.37	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.31	15.13	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:3	34.08	2680	2.37	13.4	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.35	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:3	34.08	2685	2.37	13.41	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.35	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:4	34.08	2683	2.37	13.4	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.35	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:4	34.08	2679	2.37	13.4	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.35	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:4	34.08	2673	2.37	13.4	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.35	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:4	34.08	2669	2.37	13.39	107	196	Off Idle	57.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.33	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:4	34.08	2667	2.38	13.39	107	196	Off Idle	57.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.33	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:4	34.08	2668	2.38	13.38	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.35	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:4	34.08	2675	2.38	13.39	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.35	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:5	34.08	2681	2.38	13.4	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.34	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:5	34.08	2684	2.38	13.41	107	197	Off Idle	57.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.32	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:09:5	34.08	2687	2.38	13.4	107	197	Off Idle	57.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.31	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:5	34.08	2692	2.38	13.41	107	197	Off Idle	56.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.27	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:5	34.08	2696	2.38	13.41	107	197	Off Idle	56.6	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.26	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:5	34.08	2696	2.38	13.4	107	197	Off Idle	56.4	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.31	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:6	34.08	2692	2.38	13.42	107	197	Off Idle	56.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.28	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:6	34.08	2692	2.38	13.41	107	197	Off Idle	55.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.29	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:6	34.08	2694	2.38	13.41	107	197	Off Idle	55.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.35	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:6	34.08	2692	2.38	13.42	107	197	Off Idle	55.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.28	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:6	34.08	2694	2.38	13.43	107	197	Off Idle	55.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.29	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:6	34.08	2692	2.38	13.43	107	197	Off Idle	55.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.23	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:6	34.08	2694	2.38	13.43	107	196	Off Idle	55.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.28	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:7	34.08	2696	2.38	13.43	107	196	Off Idle	55.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.32	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:7	34.08	2695	2.37	13.42	107	196	Off Idle	56.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.38	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:7	34.08	2690	2.37	13.42	107	197	Off Idle	56.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.4	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:7	34.08	2690	2.37	13.42	107	197	Off Idle	56.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.47	15.17	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:7	34.08	2687	2.37	13.42	107	197	Off Idle	56.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.44	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:7	34.08	2683	2.37	13.43	107	197	Off Idle	56.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.43	15.15	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:09:8	34.08	2683	2.37	13.42	107	197	Off Idle	56.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.39	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:8	34.08	2687	2.37	13.42	107	197	Off Idle	56.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.35	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:09:8	34.08	2688	2.37	13.43	107	197	Off Idle	56.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.39	15.09	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:09:8	34.08	2688	2.37	13.41	107	197	Off Idle	56.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.41	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:09:8	34.08	2690	2.37	13.42	107	197	Off Idle	56.1	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.44	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:09:8	34.08	2694	2.36	13.42	107	196	Off Idle	55.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.47	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:09:9	34.08	2692	2.36	13.42	107	196	Off Idle	55.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.48	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:9	34.08	2692	2.36	13.42	107	197	Off Idle	55.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.48	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:9	34.08	2696	2.36	13.42	107	197	Off Idle	55.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.46	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:9	34.08	2696	2.36	13.42	107	197	Off Idle	56	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.44	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:9	34.08	2696	2.36	13.41	107	197	Off Idle	56.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.45	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:9	34.08	2698	2.36	13.41	107	197	Off Idle	56.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.42	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:09:9	34.08	2698	2.36	13.39	107	196	Off Idle	56.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.42	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:0	34.08	2698	2.36	13.39	107	196	Off Idle	56.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.43	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:0	34.08	2703	2.36	13.39	107	196	Off Idle	56.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.44	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:0	34.08	2712	2.36	13.39	107	196	Off Idle	56.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.46	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:0	34.08	2717	2.36	13.38	107	197	Off Idle	56.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.48	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:0	34.08	2720	2.35	13.4	107	197	Off Idle	56.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.5	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:0	34.08	2716	2.35	13.41	107	197	Off Idle	56.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.49	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:1	34.08	2710	2.36	13.39	107	197	Off Idle	55.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.51	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:1	34.08	2708	2.36	13.4	107	197	Off Idle	55.6	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.5	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:1	34.08	2700	2.36	13.38	107	197	Off Idle	55.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.5	15.15	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:1	34.08	2699	2.36	13.38	107	197	Off Idle	55.1	0	2	132	944 Turbo	0.68	Lean	1	14.6	-5.49	15.18	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:1	34.08	2699	2.36	13.38	107	197	Off Idle	55	0	2	132	944 Turbo	0.67	Lean	1	14.6	-5.5	15.18	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:1	34.08	2699	2.36	13.38	107	196	Off Idle	55	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.52	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:1	34.08	2705	2.36	13.4	107	196	Off Idle	55	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.49	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:10:2	34.08	2706	2.36	13.4	107	196	Off Idle	55	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.52	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:2	34.08	2710	2.36	13.41	107	196	Off Idle	55	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.5	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:2	34.08	2712	2.36	13.41	107	196	Off Idle	55	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.5	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:2	34.08	2713	2.36	13.4	107	196	Off Idle	55	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.52	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:2	34.08	2712	2.36	13.38	107	197	Off Idle	55	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.52	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:2	34.08	2720	2.36	13.38	107	197	Off Idle	55	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.53	14.83	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:3	34.08	2711	2.36	13.39	107	197	Off Idle	55	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.49	14.83	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:3	34.08	2711	2.36	13.4	107	196	Off Idle	55	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.49	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:10:3	34.08	2711	2.36	13.43	107	196	Off Idle	55	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.49	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:3	34.08	2713	2.36	13.43	107	196	Off Idle	55	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.53	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:3	34.08	2713	2.36	13.42	107	196	Off Idle	55	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.58	14.91	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:3	34.08	2718	2.36	13.42	107	196	Off Idle	55	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.55	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:4	34.08	2723	2.36	13.41	107	196	Off Idle	54.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.56	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:4	34.08	2723	2.36	13.41	107	196	Off Idle	54.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.61	14.98	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:4	34.08	2705	2.36	13.39	107	196	Off Idle	54.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.58	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:4	34.08	2705	2.36	13.4	107	197	Off Idle	54.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.6	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:4	34.08	2716	2.36	13.4	107	197	Off Idle	54.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.6	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:4	34.08	2726	2.36	13.4	107	197	Off Idle	54.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.55	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:4	34.08	2724	2.36	13.42	107	197	Off Idle	54.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.53	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:5	34.08	2726	2.36	13.41	107	197	Off Idle	54.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.54	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:5	34.08	2721	2.35	13.42	107	197	Off Idle	54.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.59	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:5	34.08	2719	2.35	13.42	107	196	Off Idle	54.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.66	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:5	34.08	2714	2.35	13.41	107	196	Off Idle	54.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.76	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:5	34.08	2716	2.35	13.41	107	196	Off Idle	54.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.79	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:10:5	34.08	2716	2.34	13.4	107	196	Off Idle	54.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.78	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:6	34.08	2711	2.34	13.38	107	196	Off Idle	54.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.81	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:6	34.08	2714	2.34	13.38	107	196	Off Idle	54.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.81	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:6	34.08	2722	2.33	13.39	107	196	Off Idle	54.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.89	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:6	34.08	2726	2.33	13.4	107	196	Off Idle	54.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.94	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:6	34.08	2730	2.33	13.41	107	196	Off Idle	54.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.99	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:6	34.08	2732	2.32	13.39	107	196	Off Idle	54.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.98	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:6	34.08	2734	2.32	13.39	107	196	Off Idle	54	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.99	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:7	34.08	2736	2.32	13.4	107	196	Off Idle	53.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:7	34.08	2734	2.31	13.39	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:7	34.08	2740	2.31	13.41	107	196	Off Idle	53.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.01	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:7	34.08	2726	2.31	13.4	107	196	Off Idle	53.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.97	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:7	34.08	2724	2.31	13.41	107	196	Off Idle	53.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.96	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:7	34.08	2724	2.3	13.41	107	196	Off Idle	53	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.92	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:8	34.08	2728	2.3	13.41	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.91	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:8	34.08	2731	2.3	13.41	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.91	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:10:8	34.08	2734	2.3	13.41	107	196	Off Idle	53	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.96	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:8	35.45	2738	2.3	13.39	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6	15.07	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:8	35.45	2738	2.3	13.39	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.02	15.05	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:8	35.45	2749	2.3	13.39	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.02	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:9	35.45	2750	2.3	13.37	107	197	Off Idle	53	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:9	35.45	2748	2.3	13.35	107	197	Off Idle	53	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.97	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:9	35.45	2746	2.31	13.36	107	196	Off Idle	53	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.93	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:9	35.45	2738	2.31	13.38	107	196	Off Idle	53	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.96	14.88	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:9	35.45	2730	2.31	13.38	107	196	Off Idle	53	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.96	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:9	35.45	2728	2.3	13.39	107	197	Off Idle	53	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6	14.92	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:10:9	35.45	2724	2.3	13.4	107	197	Off Idle	53	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.02	14.98	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:11:0	35.45	2722	2.3	13.4	107	197	Off Idle	53	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.04	15.05	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:11:0	35.45	2724	2.3	13.4	107	196	Off Idle	53	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.02	15.09	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:11:0	35.45	2720	2.3	13.41	107	196	Off Idle	53.2	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.02	15.14	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:11:0	35.45	2737	2.3	13.41	107	196	Off Idle	53.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.03	15.19	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:11:0	35.45	2742	2.29	13.42	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.08	15.22	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:0	35.45	2745	2.29	13.41	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.07	15.22	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:1	35.45	2749	2.29	13.42	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.15	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:11:1	35.45	2754	2.29	13.42	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.13	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:1	35.45	2754	2.29	13.41	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.16	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:1	35.45	2754	2.29	13.41	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.16	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:1	35.45	2752	2.28	13.41	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.24	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:1	35.45	2744	2.28	13.41	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.26	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:1	35.45	2740	2.28	13.4	107	196	Off Idle	53.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.28	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:2	35.45	2725	2.28	13.39	107	196	Off Idle	53.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.24	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:2	35.45	2730	2.28	13.41	107	196	Off Idle	53.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.25	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:2	35.45	2734	2.27	13.39	107	196	Off Idle	53	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.24	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:2	35.45	2736	2.27	13.39	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.27	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:2	35.45	2747	2.27	13.39	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.33	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:2	35.45	2746	2.27	13.39	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.34	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:3	35.45	2748	2.27	13.4	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.14	Rich	1	14.6	-6.38	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:3	35.45	2756	2.27	13.42	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.41	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:3	35.45	2762	2.26	13.43	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.44	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:3	35.45	2761	2.26	13.44	107	196	Off Idle	52.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.41	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:11:3	35.45	2759	2.26	13.44	107	196	Off Idle	52.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.43	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:3	35.45	2750	2.26	13.42	107	196	Off Idle	52.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.46	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:4	35.45	2747	2.26	13.42	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.49	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:4	35.45	2746	2.25	13.42	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.54	15.05	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:4	35.45	2742	2.25	13.4	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.55	15.12	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:11:4	35.45	2745	2.25	13.4	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.59	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:11:4	35.45	2748	2.25	13.41	107	196	Off Idle	52	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.6	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:11:4	35.45	2748	2.24	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.62	15.22	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:11:4	35.45	2750	2.24	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.63	15.22	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:11:5	35.45	2748	2.24	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.67	15.19	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:11:5	35.45	2748	2.24	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.68	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:11:5	35.45	2754	2.23	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.7	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:11:5	35.45	2750	2.23	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.74	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:5	35.45	2750	2.22	13.41	107	196	Off Idle	52	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.74	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:5	35.45	2752	2.22	13.4	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.74	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:6	35.45	2754	2.22	13.39	107	196	Off Idle	52.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.73	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:6	35.45	2756	2.22	13.38	107	196	Off Idle	52.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.75	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:6	35.45	2762	2.21	13.38	107	196	Off Idle	52.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.75	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:6	35.45	2787	2.21	13.38	107	196	Off Idle	52.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.79	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:6	35.45	2770	2.21	13.37	107	196	Off Idle	52.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.82	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:6	35.45	2769	2.2	13.39	107	196	Off Idle	52.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.81	14.72	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:6	35.45	2768	2.2	13.4	107	196	Off Idle	52.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.83	14.72	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:11:7	35.45	2761	2.2	13.41	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.83	14.74	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:11:7	35.45	2755	2.2	13.41	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.79	14.76	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:7	35.45	2754	2.2	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.82	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:7	35.45	2744	2.19	13.38	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.89	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:7	35.45	2740	2.19	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.92	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:7	35.45	2721	2.19	13.39	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.97	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:8	35.45	2740	2.19	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.98	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:8	35.45	2740	2.18	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.03	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:8	35.45	2750	2.17	13.42	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.06	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:8	35.45	2754	2.17	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.12	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:11:8	35.45	2757	2.17	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.15	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:11:8	35.45	2760	2.16	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.24	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:11:9	35.45	2758	2.16	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.23	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:11:9	35.45	2762	2.15	13.39	107	196	Off Idle	52	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.27	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:11:9	35.45	2762	2.15	13.41	107	196	Off Idle	52	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.34	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:11:9	35.45	2746	2.14	13.41	107	196	Off Idle	52	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.32	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:11:9	35.45	2751	2.14	13.4	107	196	Off Idle	52	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.37	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:9	35.45	2751	2.13	13.39	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.37	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:11:9	35.45	2750	2.13	13.4	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.37	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:12:0	35.45	2756	2.12	13.4	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.4	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:12:0	35.45	2763	2.12	13.4	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.43	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:12:0	35.45	2770	2.11	13.41	107	196	Off Idle	52	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.39	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:12:0	35.45	2770	2.11	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.46	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:0	35.45	2761	2.1	13.41	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.48	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:0	35.45	2756	2.1	13.41	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.52	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:1	35.45	2756	2.1	13.41	107	196	Off Idle	51.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.49	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:1	35.45	2746	2.1	13.41	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.5	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:1	35.45	2740	2.1	13.41	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.47	14.96	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:1	35.45	2740	2.09	13.42	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.47	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:1	35.45	2740	2.09	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.48	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:1	35.45	2746	2.09	13.4	107	196	Off Idle	52	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.48	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:1	35.45	2755	2.09	13.39	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.52	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:2	35.45	2764	2.08	13.4	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.52	15.22	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:2	35.45	2772	2.08	13.4	107	196	Off Idle	51.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.58	15.26	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:2	35.45	2772	2.08	13.4	107	196	Off Idle	51.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.6	15.26	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:2	35.45	2786	2.07	13.41	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.65	15.25	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:2	35.45	2773	2.07	13.39	107	196	Off Idle	52.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	15.22	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:2	35.45	2772	2.07	13.41	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.67	15.19	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:3	35.45	2765	2.07	13.4	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	15.19	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:3	35.45	2736	2.07	13.41	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	15.17	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:3	35.45	2742	2.07	13.41	107	196	Off Idle	51.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	15.15	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:3	35.45	2748	2.07	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.69	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:3	35.45	2749	2.07	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.67	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:3	35.45	2750	2.06	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.68	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:4	35.45	2750	2.06	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.69	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:4	35.45	2754	2.06	13.42	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.65	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:4	35.45	2756	2.06	13.44	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:4	35.45	2764	2.06	13.42	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.67	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:4	35.45	2765	2.06	13.43	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:4	35.45	2766	2.06	13.44	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:4	35.45	2760	2.06	13.43	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:5	35.45	2760	2.06	13.42	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.76	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:5	35.45	2761	2.06	13.41	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:5	35.45	2762	2.06	13.4	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:5	35.45	2762	2.06	13.4	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:5	35.45	2762	2.06	13.39	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.79	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:6	35.45	2777	2.05	13.38	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:6	35.45	2760	2.05	13.38	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.77	15.05	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:6	35.45	2756	2.05	13.39	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.79	15.14	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:6	35.45	2758	2.05	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.79	15.18	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:6	35.45	2762	2.05	13.41	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.77	15.2	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:6	35.45	2750	2.05	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.79	15.22	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:6	35.45	2762	2.05	13.41	107	196	Off Idle	52	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.75	15.24	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:6	35.45	2774	2.05	13.41	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.74	15.21	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:7	35.45	2770	2.05	13.4	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.78	15.19	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:7	35.45	2780	2.05	13.41	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15.17	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:7	35.45	2767	2.05	13.39	107	197	Off Idle	52	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.8	15.19	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:7	35.45	2764	2.05	13.4	107	197	Off Idle	51.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.82	15.15	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:7	35.45	2758	2.05	13.4	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.8	15.12	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:7	35.45	2732	2.05	13.4	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:8	35.45	2738	2.05	13.4	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.79	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:8	35.45	2749	2.05	13.42	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.79	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:8	35.45	2754	2.05	13.43	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.78	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:8	35.45	2761	2.05	13.41	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.8	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:8	35.45	2762	2.05	13.43	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.78	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:8	35.45	2760	2.04	13.43	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.79	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:9	35.45	2794	2.04	13.42	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.78	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:9	35.45	2785	2.04	13.42	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.79	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:12:9	35.45	2774	2.04	13.41	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:9	35.45	2772	2.04	13.39	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.83	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:12:9	35.45	2771	2.04	13.39	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.83	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:9	35.45	2758	2.04	13.39	107	196	Off Idle	51.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.84	14.9	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:12:9	35.45	2763	2.04	13.4	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.82	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:0	35.45	2751	2.05	13.39	107	196	Off Idle	51.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.84	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:0	35.45	2750	2.05	13.4	107	196	Off Idle	51.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.82	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:0	35.45	2748	2.05	13.4	107	196	Off Idle	51.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.8	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:0	35.45	2748	2.05	13.4	107	196	Off Idle	51.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.82	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:0	35.45	2755	2.05	13.42	107	196	Off Idle	51.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.83	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:0	35.45	2761	2.05	13.42	107	196	Off Idle	51.1	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.82	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:1	35.45	2783	2.05	13.42	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.8	15.14	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:1	35.45	2783	2.05	13.42	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.8	15.13	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:1	35.45	2766	2.05	13.42	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	15.15	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:1	35.45	2768	2.05	13.4	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.77	15.15	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:1	35.45	2769	2.05	13.41	107	196	Off Idle	52	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.76	15.14	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:1	35.45	2758	2.05	13.41	107	196	Off Idle	52.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.77	15.13	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:1	35.45	2770	2.05	13.4	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.75	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:13:2	35.45	2768	2.05	13.41	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.7	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:2	35.45	2762	2.06	13.42	107	196	Off Idle	52.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.74	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:2	35.45	2756	2.06	13.43	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.68	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:2	35.45	2757	2.06	13.41	107	196	Off Idle	52	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.67	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:2	35.45	2760	2.06	13.4	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.64	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:2	35.45	2768	2.07	13.39	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.63	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:3	35.45	2769	2.07	13.41	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:3	35.45	2776	2.07	13.39	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.59	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:3	35.45	2775	2.08	13.38	107	196	Off Idle	51	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.58	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:3	35.45	2773	2.08	13.4	107	196	Off Idle	50.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.52	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:3	35.45	2769	2.08	13.4	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.51	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:3	35.45	2764	2.09	13.4	107	196	Off Idle	50.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.48	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:4	35.45	2756	2.09	13.41	107	196	Off Idle	50.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.39	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:4	35.45	2756	2.1	13.4	107	196	Off Idle	50.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.4	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:4	35.45	2756	2.1	13.4	107	196	Off Idle	50.9	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.4	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:4	35.45	2744	2.1	13.41	107	196	Off Idle	51	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.37	15.18	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:4	35.45	2755	2.11	13.4	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.37	15.21	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:4	35.45	2771	2.11	13.4	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.36	15.24	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:4	35.45	2777	2.11	13.42	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.34	15.24	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:5	35.45	2778	2.11	13.41	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.33	15.24	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:5	35.45	2790	2.12	13.4	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.29	15.23	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:5	35.45	2776	2.12	13.41	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.29	15.24	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:13:5	35.45	2773	2.12	13.39	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.31	15.24	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:5	35.45	2772	2.13	13.39	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.27	15.24	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:5	35.45	2771	2.13	13.4	107	196	Off Idle	51.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.24	15.17	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:6	35.45	2746	2.14	13.4	107	196	Off Idle	51.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.18	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:6	35.45	2766	2.14	13.41	107	196	Off Idle	51.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.11	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:6	35.45	2766	2.15	13.42	107	196	Off Idle	51.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.04	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:13:6	35.45	2760	2.15	13.42	107	196	Off Idle	51.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.01	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:13:6	35.45	2765	2.16	13.41	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.95	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:13:6	35.45	2789	2.16	13.41	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.9	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:13:6	35.45	2782	2.17	13.4	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.81	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:13:7	35.45	2786	2.18	13.4	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.75	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:13:7	35.45	2784	2.19	13.4	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.68	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:7	35.45	2790	2.19	13.41	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.64	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:7	35.45	2790	2.2	13.41	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.62	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:7	35.45	2788	2.21	13.41	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.58	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:7	35.45	2788	2.22	13.4	107	196	Off Idle	51.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.53	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:8	35.45	2782	2.23	13.4	107	196	Off Idle	51.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.52	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:8	35.45	2780	2.23	13.39	107	196	Off Idle	51.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.47	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:13:8	35.45	2770	2.24	13.4	107	196	Off Idle	50.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.42	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:8	35.45	2769	2.25	13.4	107	196	Off Idle	50.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.42	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:8	35.45	2770	2.26	13.4	107	196	Off Idle	50.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.38	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:8	35.45	2776	2.26	13.4	107	196	Off Idle	50.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.38	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:9	35.45	2778	2.27	13.4	107	196	Off Idle	50.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.31	15.17	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:9	35.45	2778	2.27	13.41	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.27	15.18	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:9	35.45	2782	2.27	13.42	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.24	15.18	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:9	35.45	2787	2.28	13.41	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.24	15.15	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:9	35.45	2790	2.28	13.42	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.25	15.11	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:9	35.45	2792	2.28	13.41	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.24	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:13:9	35.45	2792	2.28	13.4	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.25	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:0	35.45	2788	2.29	13.41	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.28	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:0	35.45	2787	2.29	13.4	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.23	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:0	35.45	2784	2.29	13.4	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.21	14.97	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:0	35.45	2783	2.29	13.4	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.21	14.95	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:0	35.45	2786	2.29	13.4	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.22	14.95	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:0	35.45	2783	2.29	13.41	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.2	14.89	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:1	35.45	2784	2.29	13.42	107	196	Off Idle	50.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.17	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:1	35.45	2785	2.29	13.41	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.17	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:1	35.45	2787	2.3	13.41	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.2	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:1	35.45	2791	2.3	13.4	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.23	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:1	35.45	2790	2.3	13.38	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.19	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:1	35.45	2794	2.3	13.36	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.22	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:1	35.45	2795	2.3	13.37	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.23	14.9	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:2	35.45	2796	2.3	13.39	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.19	14.9	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:2	35.45	2796	2.3	13.38	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.23	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:2	35.45	2787	2.3	13.4	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.21	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:2	35.45	2787	2.3	13.4	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.15	15.05	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:2	35.45	2784	2.3	13.39	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.18	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:2	35.45	2785	2.3	13.39	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.12	15.05	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:3	35.45	2788	2.3	13.39	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.13	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:3	35.45	2788	2.3	13.39	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.16	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:3	35.45	2791	2.3	13.38	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.12	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:3	35.45	2791	2.31	13.4	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.13	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:3	35.45	2795	2.31	13.4	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.12	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:3	35.45	2795	2.31	13.42	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.16	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:4	35.45	2800	2.31	13.41	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.2	14.79	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:4	35.45	2812	2.31	13.41	107	196	Off Idle	50.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.14	14.75	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:4	35.45	2819	2.31	13.42	107	196	Off Idle	50	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.12	14.74	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:4	35.45	2819	2.31	13.41	107	196	Off Idle	50	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.18	14.75	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:4	35.45	2814	2.31	13.41	107	196	Off Idle	49.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.14	14.74	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:4	35.45	2817	2.31	13.39	107	196	Off Idle	49.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.14	14.75	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:4	35.45	2815	2.31	13.39	107	196	Off Idle	49.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.13	14.79	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:5	35.45	2806	2.31	13.39	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.12	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:5	35.45	2803	2.31	13.4	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.11	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:5	35.45	2801	2.31	13.4	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.08	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:5	35.45	2793	2.31	13.4	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.03	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:5	35.45	2790	2.31	13.41	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.06	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:5	35.45	2792	2.32	13.42	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.02	15.05	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:6	35.45	2796	2.32	13.41	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.02	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:6	35.45	2797	2.32	13.41	107	196	Off Idle	49.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.02	15.12	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:6	35.45	2810	2.32	13.41	107	196	Off Idle	49.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.98	15.11	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:6	35.45	2810	2.33	13.42	107	196	Off Idle	49.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.94	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:14:6	35.45	2814	2.33	13.43	107	196	Off Idle	49.8	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.95	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:6	35.45	2819	2.33	13.42	107	196	Off Idle	49.9	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.88	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:6	35.45	2825	2.34	13.41	107	196	Off Idle	50.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.91	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:7	35.45	2824	2.34	13.41	107	196	Off Idle	50.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.89	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:7	35.45	2821	2.34	13.4	107	196	Off Idle	50.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.84	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:14:7	35.45	2820	2.35	13.4	107	196	Off Idle	50.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.81	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:7	35.45	2816	2.35	13.42	107	196	Off Idle	50	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.79	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:14:7	35.45	2809	2.35	13.42	107	196	Off Idle	49.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.73	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:14:7	35.45	2808	2.36	13.41	107	196	Off Idle	49.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.72	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:14:8	35.45	2803	2.36	13.4	107	196	Off Idle	49.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.72	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:8	35.45	2803	2.36	13.4	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.69	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:8	35.45	2809	2.37	13.38	107	196	Off Idle	49.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.69	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:8	35.45	2816	2.37	13.39	107	196	Off Idle	49.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.7	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:8	34.08	2799	2.37	13.4	107	196	Off Idle	49.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.71	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:8	34.08	2826	2.37	13.41	107	196	Off Idle	48.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.7	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:9	34.08	2826	2.38	13.41	107	196	Off Idle	48.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.69	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:9	34.08	2828	2.38	13.41	107	196	Off Idle	48.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.66	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:9	34.08	2830	2.38	13.41	107	196	Off Idle	48.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.61	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:9	34.08	2828	2.38	13.4	107	196	Off Idle	48.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.63	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:9	34.08	2827	2.38	13.4	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.65	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:14:9	34.08	2822	2.38	13.41	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.66	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:14:9	34.08	2822	2.38	13.41	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.71	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:0	34.08	2822	2.38	13.41	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.67	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:15:0	34.08	2824	2.38	13.41	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.69	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:15:0	34.08	2825	2.38	13.4	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.68	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:15:0	34.08	2825	2.38	13.4	107	196	Off Idle	48.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.66	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:15:0	34.08	2830	2.38	13.41	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.68	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:15:0	34.08	2837	2.38	13.41	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.71	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:15:1	34.08	2837	2.38	13.4	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.66	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:15:1	34.08	2836	2.38	13.42	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.73	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:15:1	34.08	2826	2.38	13.42	107	196	Off Idle	48.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.72	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:1	34.08	2825	2.38	13.41	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.73	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:1	34.08	2817	2.38	13.41	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.74	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:1	34.08	2817	2.38	13.4	107	196	Off Idle	48.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.75	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:1	34.08	2826	2.38	13.4	107	196	Off Idle	48.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.76	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:2	35.45	2817	2.38	13.4	107	196	Off Idle	48.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.79	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:2	35.45	2819	2.38	13.4	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.8	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:2	35.45	2829	2.37	13.41	107	196	Off Idle	48.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.83	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:2	35.45	2836	2.37	13.4	107	196	Off Idle	48.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.81	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:15:2	35.45	2841	2.37	13.41	107	196	Off Idle	48.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.86	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:15:2	35.45	2841	2.37	13.41	107	196	Off Idle	48.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.84	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:15:3	35.45	2858	2.37	13.41	107	196	Off Idle	48.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.83	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:15:3	35.45	2847	2.36	13.39	107	196	Off Idle	48.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.88	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:15:3	35.45	2839	2.36	13.41	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.91	14.83	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:3	35.45	2836	2.36	13.41	107	196	Off Idle	48.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.94	14.8	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:3	35.45	2836	2.36	13.41	107	196	Off Idle	48	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.01	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:15:3	35.45	2839	2.35	13.39	107	196	Off Idle	47.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.97	14.8	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:4	35.45	2838	2.35	13.41	107	196	Off Idle	47.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.06	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:4	35.45	2838	2.35	13.4	107	196	Off Idle	47.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.11	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:4	35.45	2845	2.34	13.4	107	196	Off Idle	47.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.11	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:4	35.45	2849	2.34	13.4	107	196	Off Idle	47.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.13	14.83	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:4	35.45	2852	2.34	13.38	107	196	Off Idle	47	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.17	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:4	35.45	2854	2.33	13.39	107	196	Off Idle	46.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.17	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:15:4	35.45	2854	2.33	13.39	107	196	Off Idle	46.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.19	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:15:5	35.45	2847	2.33	13.38	107	196	Off Idle	46.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.22	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:15:5	35.45	2846	2.32	13.38	107	196	Off Idle	46.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.25	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:5	35.45	2844	2.32	13.38	107	196	Off Idle	46.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.28	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:15:5	35.45	2844	2.32	13.4	107	196	Off Idle	46.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.31	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:5	35.45	2844	2.31	13.4	107	196	Off Idle	46.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.33	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:5	35.45	2840	2.31	13.39	107	196	Off Idle	46.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.36	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:6	35.45	2841	2.31	13.39	107	196	Off Idle	46.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.36	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:6	35.45	2842	2.3	13.41	107	196	Off Idle	46.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.37	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:6	35.45	2839	2.29	13.41	107	196	Off Idle	46.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.46	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:15:6	35.45	2842	2.28	13.41	107	196	Off Idle	46.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.61	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:15:6	35.45	2840	2.27	13.42	107	196	Off Idle	47	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.73	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:15:6	35.45	2841	2.25	13.4	107	196	Off Idle	47.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.97	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:15:6	35.45	2842	2.21	13.41	107	196	Off Idle	47.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.32	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:15:7	35.45	2840	2.18	13.4	107	196	Off Idle	47.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.59	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:15:7	35.45	2837	2.15	13.41	107	196	Full Load	47.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.83	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:15:7	35.45	2811	2.09	13.4	107	196	Idle	47.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.26	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:15:7	35.45	2828	2.06	13.41	107	196	Idle	47.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.51	14.81	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:15:7	35.45	2828	2.02	13.4	107	196	Idle	48.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.75	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:15:7	35.45	2824	1.98	13.42	107	196	Idle	48.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.99	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:15:8	35.45	2818	1.95	13.4	107	196	Idle	48.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.14	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:8	35.45	2814	1.91	13.41	107	196	Idle	48.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.25	14.9	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:8	35.45	2800	1.86	13.42	107	196	Idle	48.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.38	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:8	35.45	2792	1.83	13.42	107	196	Idle	48.4	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.46	14.95	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:8	35.45	2752	1.8	13.41	107	196	Idle	48.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.57	14.96	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:15:8	32.72	2752	1.76	13.41	107	196	Idle	48.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.64	15	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:15:9	27.27	2748	1.73	13.41	107	196	Idle	48.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.66	15.09	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:15:9	21.81	2740	1.69	13.39	107	196	Idle	49	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.77	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:9	21.81	2754	1.66	13.4	107	196	Idle	49.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.8	15.1	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:9	19.09	2776	1.64	13.4	107	196	Idle	49.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.87	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:9	19.09	2791	1.62	13.4	107	196	Idle	49.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.91	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:9	19.09	2791	1.61	13.41	107	196	Idle	49.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.94	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:15:9	19.09	2812	1.61	13.42	107	196	Idle	49.8	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.99	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:0	19.09	2833	1.61	13.42	107	196	Idle	49.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.05	14.71	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:0	19.09	2840	1.61	13.42	107	196	Idle	49.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.08	14.55	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:0	19.09	2840	1.61	13.41	107	196	Idle	49.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.08	14.47	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:0	19.09	2838	1.6	13.42	107	196	Idle	49.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.08	14.45	0.98	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:0	19.09	2842	1.6	13.41	107	196	Idle	49.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.05	14.44	0.98	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:0	19.09	2842	1.59	13.42	107	196	Idle	49	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.04	14.47	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:1	19.09	2806	1.59	13.42	107	196	Idle	48.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.99	14.5	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:1	19.09	2808	1.59	13.42	107	196	Idle	48.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.96	14.51	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:1	19.09	2801	1.59	13.42	107	196	Idle	48.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.92	14.6	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:1	19.09	2800	1.59	13.43	107	196	Idle	48.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.89	14.69	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:1	19.09	2796	1.6	13.42	107	196	Idle	48.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.87	14.79	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:1	19.09	2797	1.6	13.44	107	196	Idle	48	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.84	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:1	19.09	2798	1.6	13.42	107	196	Idle	48	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.86	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:2	19.09	2800	1.6	13.42	107	196	Idle	47.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.84	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:2	19.09	2806	1.6	13.41	107	196	Idle	47.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.83	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:2	19.09	2808	1.6	13.42	107	196	Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	15.2	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:2	19.09	2812	1.6	13.41	107	196	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	15.28	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:2	19.09	2812	1.6	13.41	107	196	Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	15.33	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:2	19.09	2813	1.61	13.41	107	196	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	15.39	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:3	19.09	2810	1.61	13.43	107	196	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	15.42	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:3	19.09	2804	1.61	13.42	107	196	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	15.56	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:3	19.09	2804	1.61	13.41	107	196	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	15.73	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:3	19.09	2794	1.61	13.41	107	196	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	16.03	1.09	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:3	19.09	2790	1.62	13.42	107	196	Idle	47.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	16.45	1.12	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:3	19.09	2790	1.62	13.42	107	196	Idle	47.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	16.91	1.15	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:4	19.09	2784	1.62	13.42	107	196	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	17.64	1.2	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:4	19.09	2782	1.62	13.41	107	196	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	18.12	1.23	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:4	19.09	2778	1.62	13.41	107	196	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	18.61	1.27	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:4	19.09	2779	1.62	13.42	107	196	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	19.05	1.3	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:4	19.09	2780	1.62	13.42	107	196	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	19.66	1.34	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:4	19.09	2779	1.62	13.42	107	196	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	19.97	1.36	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:4	19.09	2779	1.62	13.44	107	196	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.17	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:5	19.09	2781	1.62	13.42	107	196	Idle	48.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:5	19.09	2781	1.62	13.42	107	196	Idle	48.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:5	19.09	2784	1.62	13.42	107	196	Idle	48.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:16:5	19.09	2784	1.62	13.4	107	196	Idle	48.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:5	19.09	2784	1.62	13.37	107	196	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:5	19.09	2779	1.62	13.34	107	196	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:6	19.09	2775	1.62	13.33	107	196	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:6	19.09	2768	1.62	13.35	107	196	Idle	48.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:6	19.09	2768	1.61	13.36	107	196	Idle	48.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:6	19.09	2761	1.61	13.35	107	196	Idle	49	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:6	19.09	2757	1.61	13.36	107	196	Idle	49.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:6	19.09	2758	1.61	13.36	107	196	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:6	19.09	2755	1.61	13.35	107	196	Idle	49.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:7	19.09	2752	1.61	13.35	107	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:7	19.09	2751	1.6	13.35	107	196	Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:7	19.09	2751	1.6	13.36	107	196	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:7	19.09	2752	1.6	13.36	107	196	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:7	19.09	2755	1.6	13.35	107	196	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:7	19.09	2772	1.59	13.36	107	196	Idle	50.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:8	19.09	2772	1.59	13.37	107	196	Idle	50.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:8	19.09	2751	1.59	13.37	107	196	Idle	50.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:8	19.09	2723	1.59	13.37	107	196	Idle	50.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:8	19.09	2738	1.58	13.39	107	196	Idle	51.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:8	19.09	2738	1.58	13.37	107	196	Idle	51.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:8	19.09	2730	1.58	13.38	107	196	Idle	51.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:9	19.09	2724	1.58	13.38	107	196	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:9	19.09	2724	1.57	13.39	107	196	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:9	19.09	2714	1.57	13.37	107	196	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:9	19.09	2708	1.57	13.37	107	196	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:9	19.09	2701	1.57	13.38	107	196	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:9	19.09	2701	1.56	13.36	107	196	Idle	51.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:16:9	19.09	2697	1.56	13.35	107	196	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:0	19.09	2696	1.56	13.36	107	196	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:0	19.09	2694	1.56	13.35	107	196	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:0	19.09	2671	1.56	13.35	107	196	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:0	19.09	2691	1.56	13.35	107	196	Idle	51.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:0	19.09	2693	1.56	13.36	107	196	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:0	19.09	2695	1.55	13.38	107	196	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:1	19.09	2696	1.55	13.37	107	196	Idle	51.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:1	19.09	2696	1.55	13.37	107	196	Idle	51.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:1	19.09	2695	1.55	13.38	107	196	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:1	19.09	2693	1.55	13.38	107	196	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:1	19.09	2686	1.55	13.36	107	196	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:1	19.09	2688	1.55	13.36	107	196	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:1	19.09	2671	1.54	13.37	107	196	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:2	19.09	2668	1.54	13.36	107	196	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:2	19.09	2648	1.54	13.36	107	196	Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.25	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:2	19.09	2653	1.54	13.36	107	196	Idle	53.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:2	19.09	2648	1.53	13.37	107	196	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:2	19.09	2636	1.53	13.36	107	196	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:2	19.09	2644	1.53	13.35	107	196	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:3	19.09	2644	1.52	13.37	107	196	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:3	19.09	2652	1.52	13.37	107	196	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:3	19.09	2643	1.52	13.37	107	196	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:3	19.09	2623	1.52	13.39	107	196	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:3	19.09	2623	1.51	13.38	107	196	Idle	55.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:3	19.09	2639	1.51	13.4	107	196	Idle	55.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:4	19.09	2636	1.51	13.4	107	196	Idle	55.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:4	19.09	2636	1.5	13.4	107	196	Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:4	19.09	2629	1.5	13.4	107	196	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:4	19.09	2620	1.5	13.39	107	196	Idle	55.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:17:4	19.09	2616	1.49	13.38	107	196	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:4	19.09	2608	1.49	13.37	107	196	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:4	19.09	2597	1.49	13.36	107	196	Idle	56.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:5	19.09	2592	1.48	13.36	107	196	Idle	56.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:5	19.09	2586	1.48	13.37	107	196	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:5	19.09	2585	1.48	13.36	107	196	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:5	19.09	2583	1.47	13.37	107	196	Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:5	19.09	2586	1.47	13.36	107	196	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:5	19.09	2590	1.47	13.38	107	196	Idle	57.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:6	19.09	2590	1.46	13.36	107	196	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:6	19.09	2592	1.46	13.37	107	196	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:6	19.09	2592	1.45	13.36	107	196	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:6	19.09	2590	1.45	13.37	107	196	Idle	58.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:6	19.09	2590	1.45	13.36	107	196	Idle	58.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:6	19.09	2584	1.45	13.37	107	196	Idle	58.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:6	19.09	2578	1.44	13.35	107	196	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:7	19.09	2565	1.44	13.36	107	196	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:7	19.09	2565	1.43	13.36	107	196	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:7	19.09	2557	1.43	13.36	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:7	19.09	2548	1.43	13.36	107	196	Idle	59.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:7	19.09	2520	1.42	13.36	107	196	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:7	19.09	2520	1.42	13.36	107	196	Idle	59.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:8	19.09	2537	1.42	13.36	107	196	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:8	19.09	2534	1.41	13.35	107	196	Idle	60.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:8	19.09	2534	1.41	13.35	107	196	Idle	60.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:8	19.09	2543	1.41	13.36	107	196	Idle	60.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:8	19.09	2533	1.41	13.36	107	196	Idle	60.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:8	19.09	2530	1.4	13.37	107	196	Idle	60.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:9	19.09	2529	1.4	13.37	107	196	Idle	60.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:9	19.09	2529	1.4	13.37	107	196	Idle	60.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:9	19.09	2504	1.4	13.37	107	196	Idle	60.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:9	19.09	2511	1.39	13.36	107	196	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:9	19.09	2522	1.39	13.38	107	196	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:9	19.09	2508	1.39	13.38	107	196	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:17:9	19.09	2480	1.39	13.38	107	196	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:0	19.09	2480	1.38	13.38	107	196	Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:0	19.09	2490	1.38	13.37	107	196	Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:0	19.09	2484	1.38	13.36	107	196	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:0	19.09	2483	1.37	13.37	107	196	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:0	19.09	2483	1.37	13.36	107	196	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:0	19.09	2483	1.37	13.35	107	196	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:1	19.09	2484	1.37	13.35	107	196	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:1	19.09	2487	1.36	13.36	107	196	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:1	19.09	2488	1.36	13.36	107	196	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:1	19.09	2490	1.36	13.39	107	196	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:1	19.09	2490	1.36	13.4	107	196	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:1	19.09	2490	1.36	13.41	107	196	Idle	63.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:1	19.09	2491	1.35	13.4	107	196	Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:2	19.09	2489	1.35	13.41	107	196	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:2	19.09	2487	1.35	13.41	107	196	Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.2	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:2	19.09	2486	1.35	13.41	107	196	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:2	19.09	2482	1.34	13.41	107	196	Idle	64.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:2	19.09	2482	1.34	13.41	107	196	Idle	64.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:2	19.09	2475	1.34	13.41	107	196	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:3	19.09	2471	1.33	13.41	107	196	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:3	19.09	2467	1.33	13.4	107	196	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:3	19.09	2467	1.33	13.41	107	196	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:3	19.09	2464	1.32	13.4	107	196	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:18:3	19.09	2461	1.32	13.4	107	196	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:3	19.09	2460	1.32	13.4	107	196	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:4	19.09	2458	1.31	13.4	107	196	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:4	19.09	2458	1.31	13.41	107	196	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:4	19.09	2454	1.3	13.41	107	196	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:4	19.09	2433	1.3	13.41	107	196	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:4	19.09	2442	1.3	13.4	107	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:4	19.09	2454	1.29	13.41	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:4	19.09	2453	1.29	13.4	107	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:5	19.09	2473	1.28	13.4	107	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:5	19.09	2473	1.28	13.41	107	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.2	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:5	19.09	2452	1.27	13.4	107	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:5	19.09	2451	1.27	13.4	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:5	19.09	2450	1.26	13.4	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:5	19.09	2430	1.26	13.41	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:6	17.72	2446	1.26	13.41	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:6	17.72	2445	1.26	13.4	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:6	17.72	2445	1.25	13.41	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:6	19.09	2447	1.25	13.4	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:6	19.09	2445	1.25	13.4	107	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:6	19.09	2446	1.25	13.4	107	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:6	19.09	2445	1.25	13.41	107	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:7	19.09	2444	1.25	13.41	107	196	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:7	19.09	2444	1.25	13.41	107	196	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:7	19.09	2450	1.25	13.4	107	196	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:7	19.09	2427	1.25	13.42	107	196	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:7	17.72	2417	1.25	13.42	107	196	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:7	17.72	2417	1.25	13.41	107	196	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:8	17.72	2430	1.25	13.41	107	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:8	17.72	2427	1.25	13.42	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:8	17.72	2427	1.25	13.4	107	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:8	17.72	2423	1.25	13.41	107	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:8	17.72	2425	1.25	13.4	107	196	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:8	17.72	2424	1.25	13.4	107	196	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:9	17.72	2425	1.25	13.4	107	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:9	17.72	2427	1.25	13.4	107	196	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:9	17.72	2426	1.25	13.4	107	196	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:9	17.72	2426	1.24	13.41	107	196	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:9	17.72	2425	1.24	13.41	107	196	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:9	17.72	2422	1.24	13.41	107	196	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:18:9	17.72	2422	1.24	13.41	107	196	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:0	17.72	2420	1.24	13.41	107	196	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:0	17.72	2415	1.24	13.4	107	196	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:0	17.72	2415	1.24	13.4	107	196	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:0	17.72	2410	1.23	13.41	107	196	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:0	17.72	2410	1.23	13.41	107	196	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:0	17.72	2406	1.23	13.41	107	196	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:1	17.72	2394	1.23	13.41	107	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:1	17.72	2394	1.22	13.41	107	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:1	17.72	2400	1.22	13.41	107	196	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:1	17.72	2398	1.22	13.42	107	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:1	17.72	2397	1.21	13.42	107	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:1	17.72	2397	1.21	13.4	107	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:1	17.72	2398	1.21	13.4	107	196	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:2	17.72	2400	1.21	13.41	107	196	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:2	17.72	2404	1.21	13.4	107	196	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:2	17.72	2404	1.21	13.41	107	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:2	17.72	2418	1.2	13.41	107	196	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:19:2	17.72	2410	1.2	13.42	107	196	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:2	17.72	2402	1.2	13.42	107	196	Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:3	17.72	2410	1.2	13.42	107	196	Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:3	17.72	2428	1.19	13.42	107	196	Idle	71.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:3	17.72	2417	1.19	13.42	107	196	Idle	71.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:3	17.72	2391	1.19	13.41	107	196	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:3	17.72	2394	1.19	13.41	107	196	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:3	17.72	2390	1.19	13.39	107	196	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:4	17.72	2388	1.19	13.4	107	196	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:4	17.72	2378	1.19	13.39	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:4	17.72	2373	1.19	13.39	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:4	17.72	2369	1.19	13.4	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:4	17.72	2368	1.18	13.41	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:4	17.72	2367	1.18	13.41	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:4	17.72	2366	1.18	13.41	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:5	17.72	2368	1.18	13.41	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:5	17.72	2370	1.18	13.41	107	196	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:5	17.72	2375	1.18	13.41	107	196	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:5	17.72	2377	1.18	13.4	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:5	17.72	2378	1.18	13.39	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:5	17.72	2379	1.17	13.4	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:6	17.72	2381	1.17	13.39	107	196	Idle	72	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:6	17.72	2381	1.17	13.4	107	196	Idle	72	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:6	17.72	2378	1.17	13.41	107	196	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:6	17.72	2375	1.17	13.41	107	196	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:6	17.72	2371	1.17	13.42	107	196	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:6	17.72	2370	1.17	13.42	107	196	Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:6	17.72	2366	1.17	13.42	107	196	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:7	17.72	2366	1.17	13.42	107	196	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:7	17.72	2362	1.17	13.41	107	196	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:7	17.72	2362	1.17	13.41	107	196	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:7	17.72	2358	1.17	13.42	107	196	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:7	17.72	2356	1.16	13.42	107	196	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:7	17.72	2356	1.16	13.42	107	195	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:8	17.72	2354	1.16	13.41	107	195	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:8	17.72	2353	1.16	13.42	107	195	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:8	17.72	2352	1.16	13.42	107	196	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:8	17.72	2350	1.16	13.42	107	196	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:8	17.72	2346	1.16	13.42	107	196	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:8	17.72	2343	1.16	13.41	107	195	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:9	17.72	2343	1.16	13.41	107	195	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:9	17.72	2341	1.15	13.4	107	195	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:9	17.72	2338	1.15	13.4	107	196	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:9	17.72	2338	1.15	13.4	107	196	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:9	17.72	2341	1.15	13.42	107	196	Idle	73.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:9	17.72	2338	1.15	13.43	107	196	Idle	73.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:19:9	17.72	2338	1.15	13.43	107	196	Idle	73.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:0	17.72	2338	1.15	13.42	107	196	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:0	17.72	2338	1.15	13.42	107	196	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:0	17.72	2336	1.14	13.42	107	196	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:0	17.72	2338	1.14	13.42	107	196	Idle	74.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:0	17.72	2330	1.14	13.42	107	196	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:0	17.72	2337	1.14	13.41	107	196	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:1	17.72	2338	1.14	13.41	107	196	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:1	17.72	2338	1.14	13.4	107	196	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:1	17.72	2334	1.14	13.4	107	196	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:1	17.72	2332	1.14	13.41	107	196	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:1	17.72	2332	1.13	13.41	107	196	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:20:1	17.72	2329	1.13	13.41	107	196	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:1	17.72	2327	1.13	13.4	107	196	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:2	17.72	2326	1.13	13.4	107	196	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:2	17.72	2323	1.13	13.4	107	196	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:2	17.72	2320	1.13	13.4	107	196	Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:2	17.72	2319	1.13	13.41	107	196	Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:2	17.72	2318	1.13	13.42	107	196	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:2	17.72	2317	1.13	13.44	107	196	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:3	17.72	2312	1.13	13.44	107	196	Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:3	17.72	2312	1.13	13.41	107	196	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:3	17.72	2311	1.13	13.41	107	196	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:3	17.72	2309	1.13	13.41	107	196	Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:3	17.72	2308	1.13	13.41	107	196	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:3	17.72	2308	1.12	13.41	107	196	Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:4	17.72	2309	1.12	13.43	107	196	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:4	17.72	2309	1.12	13.43	107	196	Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:4	17.72	2308	1.12	13.43	107	196	Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:4	17.72	2308	1.12	13.44	107	196	Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:4	17.72	2309	1.12	13.43	107	196	Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:4	17.72	2308	1.12	13.41	107	196	Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:4	17.72	2308	1.12	13.4	107	196	Idle	75.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:5	17.72	2308	1.12	13.41	107	196	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:5	17.72	2308	1.12	13.38	107	196	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:5	17.72	2308	1.12	13.39	107	196	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:5	17.72	2308	1.11	13.41	107	196	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:5	17.72	2304	1.11	13.41	107	196	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:5	17.72	2298	1.11	13.42	107	196	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:6	17.72	2298	1.11	13.41	107	196	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:6	17.72	2293	1.11	13.4	107	196	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:6	17.72	2288	1.11	13.39	107	196	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:6	17.72	2287	1.1	13.39	107	195	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:6	17.72	2282	1.1	13.4	107	195	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:6	17.72	2281	1.1	13.41	107	195	Full Load	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:6	17.72	2283	1.1	13.43	107	196	Off Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:20:7	17.72	2224	1.1	13.44	107	196	Off Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:15:20:7	9.54	2300	1.1	13.42	107	196	Off Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:15:20:7	9.54	2300	1.1	13.41	107	196	Off Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:15:20:7	12.27	2300	1.11	13.41	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:15:20:7	14.99	2300	1.11	13.4	107	196	Off Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:15:20:7	14.99	2302	1.12	13.4	107	196	Off Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:8	17.72	2302	1.12	13.4	107	196	Off Idle	78	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:8	20.45	2300	1.13	13.4	107	196	Off Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:8	20.45	2297	1.13	13.4	107	196	Off Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:8	23.18	2297	1.14	13.41	107	196	Off Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:8	23.18	2294	1.15	13.4	107	196	Off Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:8	25.9	2293	1.16	13.41	107	196	Off Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:9	28.63	2291	1.17	13.39	107	196	Off Idle	78.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:9	28.63	2288	1.18	13.38	107	196	Off Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:9	31.36	2290	1.19	13.39	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:20:9	31.36	2292	1.2	13.38	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:20:9	34.08	2293	1.21	13.39	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:20:9	35.45	2295	1.23	13.38	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:20:9	35.45	2280	1.25	13.38	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:21:0	35.45	2285	1.26	13.38	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:21:0	35.45	2285	1.27	13.38	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:0	35.45	2286	1.28	13.38	107	196	Off Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:0	35.45	2284	1.29	13.39	107	196	Off Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:0	35.45	2283	1.31	13.4	107	196	Off Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:21:0	35.45	2282	1.32	13.41	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:1	35.45	2276	1.33	13.43	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:1	35.45	2274	1.34	13.44	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:1	35.45	2275	1.36	13.43	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.92	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:21:1	35.45	2273	1.38	13.42	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.89	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:21:1	35.45	2262	1.4	13.41	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.87	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:21:1	35.45	2264	1.41	13.4	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:21:1	35.45	2266	1.43	13.38	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:21:2	35.45	2266	1.44	13.39	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:21:2	35.45	2263	1.45	13.39	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.69	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:21:2	35.45	2264	1.47	13.39	107	196	Off Idle	78.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.61	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:21:2	35.45	2269	1.48	13.39	107	196	Off Idle	79	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.52	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:21:2	35.45	2275	1.49	13.41	107	196	Off Idle	79.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.45	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:21:2	35.45	2263	1.5	13.41	107	196	Off Idle	79.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.43	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:21:3	34.08	2274	1.51	13.41	107	196	Off Idle	79.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.36	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:21:3	34.08	2284	1.52	13.42	107	196	Off Idle	79.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.31	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:21:3	34.08	2288	1.54	13.41	107	196	Off Idle	79.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.24	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:21:3	34.08	2288	1.55	13.41	107	196	Off Idle	79.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.23	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:3	34.08	2289	1.57	13.41	107	196	Off Idle	78.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.13	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:3	34.08	2288	1.57	13.43	107	196	Off Idle	78.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.01	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:4	34.08	2290	1.6	13.42	107	196	Off Idle	78.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.92	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:4	34.08	2293	1.61	13.41	107	196	Off Idle	78.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.73	20.24	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:4	34.08	2294	1.64	13.37	107	196	Off Idle	78.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.66	20.19	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:4	34.08	2293	1.67	13.38	107	196	Off Idle	78.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.59	20.09	1.37	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:4	34.08	2289	1.69	13.39	107	196	Off Idle	78.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.45	19.96	1.36	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:21:4	34.08	2283	1.72	13.4	107	196	Off Idle	77.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.26	19.77	1.35	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:21:4	34.08	2276	1.74	13.41	107	196	Off Idle	77.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.97	19.4	1.32	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:21:5	34.08	2274	1.76	13.42	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.83	19.12	1.3	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:21:5	34.08	2267	1.78	13.42	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.7	18.79	1.28	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:5	34.08	2269	1.81	13.42	107	196	Off Idle	77.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.53	18.27	1.24	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:5	34.08	2270	1.83	13.43	107	196	Off Idle	78	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.43	17.9	1.22	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:5	34.08	2273	1.87	13.43	107	196	Off Idle	78.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.27	17.56	1.2	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:5	34.08	2278	1.89	13.43	107	196	Off Idle	78.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.14	17.11	1.17	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:21:6	34.08	2280	1.91	13.44	107	196	Off Idle	78.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.03	16.87	1.15	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:21:6	34.08	2280	1.95	13.44	107	196	Off Idle	78.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.82	16.66	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:21:6	34.08	2277	1.98	13.44	107	196	Off Idle	78.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.67	16.48	1.12	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:21:6	34.08	2282	2.01	13.43	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.52	16.33	1.11	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:6	34.08	2282	2.03	13.41	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.4	16.21	1.1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:6	34.08	2284	2.06	13.41	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.18	16.11	1.1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:6	34.08	2276	2.08	13.39	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.85	16.02	1.09	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:7	32.72	2288	2.09	13.38	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.68	15.95	1.09	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:7	32.72	2288	2.11	13.38	107	196	Off Idle	78.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.49	15.91	1.08	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:7	32.72	2296	2.13	13.39	107	196	Off Idle	78.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.39	15.83	1.08	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:7	32.72	2306	2.14	13.39	107	196	Off Idle	78.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.33	15.74	1.07	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:7	32.72	2307	2.16	13.41	107	196	Off Idle	78.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.29	15.66	1.07	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:7	32.72	2305	2.17	13.41	107	196	Off Idle	78.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.18	15.55	1.06	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:8	32.72	2297	2.19	13.4	107	196	Off Idle	78.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.15	15.49	1.06	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:8	32.72	2297	2.2	13.41	107	196	Off Idle	78	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.11	15.44	1.05	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:8	32.72	2282	2.22	13.42	107	196	Off Idle	77.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.04	15.38	1.05	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:8	32.72	2274	2.23	13.41	107	196	Off Idle	77.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5	15.33	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:8	32.72	2274	2.24	13.4	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.98	15.3	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:8	32.72	2273	2.25	13.4	107	196	Off Idle	77.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.94	15.27	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:9	32.72	2276	2.26	13.39	107	196	Off Idle	78	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.89	15.29	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:9	32.72	2284	2.26	13.39	107	196	Off Idle	78	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.85	15.28	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:9	32.72	2294	2.26	13.41	107	196	Off Idle	78	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.79	15.24	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:9	32.72	2297	2.25	13.41	107	196	Off Idle	78	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.75	15.19	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:21:9	32.72	2311	2.26	13.42	107	196	Off Idle	78.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.73	15.15	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:21:9	32.72	2316	2.26	13.41	107	196	Off Idle	78.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.74	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:21:9	32.72	2317	2.26	13.4	107	196	Off Idle	78.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.76	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:0	32.72	2313	2.26	13.4	107	195	Off Idle	78.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.75	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:0	32.72	2304	2.26	13.4	107	195	Off Idle	78.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.79	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:22:0	32.72	2295	2.26	13.39	107	195	Off Idle	78.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.82	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:22:0	32.72	2295	2.26	13.41	107	196	Off Idle	78.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.81	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:0	32.72	2294	2.26	13.41	107	196	Off Idle	78	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.78	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:0	32.72	2295	2.26	13.38	107	195	Off Idle	77.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.8	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:1	32.72	2295	2.26	13.37	107	195	Off Idle	77.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.8	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:1	32.72	2296	2.26	13.37	107	195	Off Idle	77.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.78	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:1	32.72	2305	2.27	13.36	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.78	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:1	32.72	2315	2.27	13.38	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.68	Lean	1	14.6	-4.78	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:1	32.72	2325	2.27	13.37	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-4.78	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:22:1	32.72	2329	2.27	13.37	107	196	Off Idle	77.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.77	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:22:1	32.72	2328	2.28	13.39	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.75	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:22:2	32.72	2327	2.28	13.39	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.66	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:22:2	32.72	2322	2.29	13.38	107	196	Off Idle	77.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.64	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:22:2	32.72	2320	2.29	13.4	107	196	Off Idle	77.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.57	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:2	32.72	2317	2.3	13.38	107	196	Off Idle	77.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.48	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:15:22:2	32.72	2315	2.3	13.39	107	196	Off Idle	77.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.35	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:15:22:2	32.72	2322	2.31	13.39	107	196	Off Idle	77.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.2	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:15:22:3	32.72	2322	2.32	13.39	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.11	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:15:22:3	32.72	2324	2.32	13.4	107	196	Off Idle	77.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.04	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:15:22:3	32.72	2352	2.33	13.38	107	196	Off Idle	77.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-3.97	14.93	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:15:22:3	32.72	2335	2.33	13.4	107	196	Off Idle	76.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.92	14.96	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:15:22:3	32.72	2335	2.34	13.37	107	196	Off Idle	76.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.94	15.01	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:3	32.72	2336	2.35	13.37	107	196	Off Idle	76.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.92	15.03	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:4	32.72	2334	2.35	13.39	107	196	Off Idle	76.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.91	15.07	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:4	32.72	2334	2.36	13.37	107	196	Off Idle	76.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.95	15.11	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:4	31.36	2314	2.37	13.38	107	196	Off Idle	76.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-3.91	15.15	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:4	31.36	2332	2.37	13.39	107	196	Off Idle	76.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-3.93	15.18	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:15:22:4	31.36	2330	2.37	13.38	107	196	Off Idle	75.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.93	15.17	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:4	31.36	2330	2.38	13.37	107	196	Off Idle	75.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.91	15.13	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:4	31.36	2329	2.38	13.4	107	195	Off Idle	75.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.89	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:5	31.36	2343	2.38	13.39	107	195	Off Idle	75.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.87	15	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:5	32.72	2369	2.38	13.37	107	195	Off Idle	75.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.85	14.94	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:5	32.72	2362	2.38	13.38	107	195	Off Idle	75.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.82	14.88	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:5	32.72	2358	2.38	13.4	107	195	Off Idle	75.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.83	14.84	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:5	32.72	2356	2.38	13.39	107	196	Off Idle	75.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.84	14.75	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:5	32.72	2358	2.38	13.39	107	196	Off Idle	75.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.85	14.68	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:6	32.72	2357	2.39	13.4	107	196	Off Idle	75	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.83	14.64	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:6	32.72	2352	2.39	13.4	107	196	Off Idle	74.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.86	14.63	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:6	31.36	2353	2.39	13.39	107	196	Off Idle	74.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.87	14.63	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:6	31.36	2353	2.39	13.4	107	196	Off Idle	74.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.86	14.65	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:6	31.36	2352	2.39	13.4	107	195	Off Idle	74.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.83	14.68	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:6	31.36	2358	2.39	13.41	107	195	Off Idle	74.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.83	14.69	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:6	31.36	2358	2.39	13.4	107	195	Off Idle	74.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.84	14.72	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:7	31.36	2361	2.39	13.39	107	196	Off Idle	74.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.82	14.72	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:7	31.36	2363	2.39	13.4	107	196	Off Idle	74.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.82	14.73	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:7	31.36	2367	2.39	13.41	107	196	Off Idle	74.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.85	14.76	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:7	31.36	2381	2.39	13.39	107	196	Off Idle	74.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.85	14.78	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:7	32.72	2370	2.39	13.39	107	196	Off Idle	74.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.87	14.8	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:7	32.72	2357	2.39	13.39	107	196	Off Idle	74.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.86	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:8	32.72	2357	2.4	13.39	107	196	Off Idle	74.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.82	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:8	32.72	2358	2.4	13.4	107	196	Off Idle	74.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.77	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:8	32.72	2349	2.4	13.39	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.73	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:8	31.36	2372	2.4	13.38	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.63	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:8	31.36	2371	2.41	13.38	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.56	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:8	31.36	2377	2.43	13.36	107	196	Off Idle	73.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.47	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:22:9	31.36	2378	2.44	13.36	107	196	Off Idle	73.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-3.31	14.86	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:22:9	31.36	2381	2.46	13.37	107	196	Off Idle	73.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.06	14.85	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:22:9	31.36	2384	2.47	13.37	107	196	Off Idle	73.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.91	14.83	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:22:9	31.36	2400	2.48	13.37	107	196	Off Idle	73.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-2.76	14.83	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:15:22:9	31.36	2401	2.49	13.37	107	196	Off Idle	73.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.64	14.82	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:15:22:9	31.36	2402	2.5	13.37	107	196	Off Idle	73.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-2.52	14.83	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:15:22:9	31.36	2418	2.51	13.37	107	196	Off Idle	73.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.48	14.86	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:0	31.36	2408	2.52	13.38	107	196	Off Idle	73.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.43	14.9	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:0	31.36	2406	2.53	13.38	107	195	Off Idle	73.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.38	14.93	1.02	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:0	31.36	2401	2.55	13.4	107	195	Off Idle	73.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-2.35	14.97	1.02	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:0	31.36	2394	2.56	13.39	107	195	Off Idle	73	0	2	132	944 Turbo	0.38	Rich	1	14.6	-2.32	15.05	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:0	31.36	2394	2.57	13.38	107	195	Off Idle	72.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-2.34	15.11	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:0	31.36	2391	2.57	13.37	107	195	Off Idle	72.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-2.3	15.18	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:1	31.36	2394	2.58	13.38	107	195	Off Idle	72.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.28	15.21	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:1	31.36	2397	2.6	13.36	107	195	Off Idle	72.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.29	15.15	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:1	31.36	2402	2.61	13.38	107	195	Off Idle	72.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.23	15.06	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:1	31.36	2404	2.61	13.4	107	195	Off Idle	72.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.23	14.93	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:1	31.36	2415	2.61	13.39	107	195	Off Idle	72.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.25	14.8	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:1	31.36	2440	2.61	13.37	107	195	Off Idle	72.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.22	14.65	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:1	31.36	2419	2.6	13.38	107	195	Off Idle	72	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.18	14.41	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:2	31.36	2417	2.6	13.39	107	195	Off Idle	71.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.18	14.26	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:2	31.36	2420	2.6	13.39	107	195	Off Idle	71.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.19	14.09	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:2	31.36	2420	2.61	13.4	107	195	Off Idle	71.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.17	13.95	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:2	31.36	2420	2.61	13.41	107	195	Off Idle	71.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.14	13.9	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:15:23:2	31.36	2420	2.61	13.41	107	196	Off Idle	71.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.17	13.81	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:2	31.36	2423	2.61	13.4	107	196	Off Idle	71.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.2	13.78	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:3	31.36	2424	2.61	13.39	107	196	Off Idle	71	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.17	13.76	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:3	31.36	2427	2.61	13.38	107	196	Off Idle	70.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.21	13.75	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:3	31.36	2432	2.61	13.37	107	196	Off Idle	70.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.24	13.75	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:3	31.36	2431	2.61	13.38	107	196	Off Idle	70.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.25	13.75	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:3	31.36	2430	2.61	13.37	107	195	Off Idle	70.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.24	13.75	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:3	31.36	2431	2.61	13.38	107	195	Off Idle	70.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.24	13.76	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:4	31.36	2434	2.61	13.39	107	195	Off Idle	70.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.2	13.8	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:4	31.36	2435	2.61	13.37	107	195	Off Idle	70.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.2	13.83	0.94	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:15:23:4	31.36	2436	2.61	13.39	107	195	Off Idle	70.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.19	13.85	0.94	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:4	31.36	2443	2.61	13.4	107	195	Off Idle	70.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.24	13.87	0.94	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:4	32.72	2467	2.61	13.39	107	196	Off Idle	70.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.25	13.9	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:4	32.72	2462	2.61	13.37	107	196	Off Idle	70.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.28	13.92	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:4	32.72	2461	2.61	13.39	107	196	Off Idle	70.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.27	13.92	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:5	32.72	2463	2.61	13.39	107	196	Off Idle	70.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.31	13.94	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:5	32.72	2483	2.61	13.41	107	196	Off Idle	69.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.31	13.95	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:5	32.72	2483	2.61	13.41	107	196	Off Idle	69.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.33	13.95	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:5	32.72	2459	2.61	13.41	107	196	Off Idle	69.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.31	13.95	0.95	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:5	32.72	2458	2.61	13.4	107	196	Off Idle	69.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.35	13.94	0.95	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:5	32.72	2458	2.61	13.41	107	196	Off Idle	69.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.37	13.97	0.95	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:6	32.72	2460	2.62	13.4	107	195	Off Idle	69.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.37	13.99	0.95	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:6	31.36	2463	2.62	13.41	107	195	Off Idle	69	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.38	14.01	0.95	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:15:23:6	31.36	2464	2.62	13.41	107	195	Off Idle	68.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.35	14.05	0.96	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:6	31.36	2464	2.62	13.4	107	195	Off Idle	68.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.32	14.07	0.96	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:6	31.36	2466	2.62	13.4	107	195	Off Idle	68.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.32	14.09	0.96	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:6	32.72	2485	2.62	13.4	107	196	Off Idle	68.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.29	14.12	0.96	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:6	32.72	2476	2.62	13.39	107	196	Off Idle	68.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.32	14.17	0.96	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:7	32.72	2476	2.62	13.38	107	196	Off Idle	68.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.3	14.18	0.97	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:7	32.72	2482	2.62	13.38	107	196	Off Idle	68.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.26	14.23	0.97	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:7	32.72	2486	2.63	13.37	107	196	Off Idle	68.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.27	14.26	0.97	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:7	32.72	2486	2.63	13.36	107	196	Off Idle	68.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.27	14.29	0.97	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:7	32.72	2483	2.63	13.38	107	196	Off Idle	68	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.27	14.32	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:7	32.72	2481	2.63	13.4	107	196	Off Idle	67.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.28	14.35	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:23:8	32.72	2486	2.63	13.39	107	195	Off Idle	67.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.28	14.4	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:8	32.72	2486	2.63	13.39	107	195	Off Idle	67.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.28	14.42	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:8	32.72	2490	2.63	13.39	107	195	Off Idle	67.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.27	14.44	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:8	32.72	2490	2.63	13.39	107	195	Off Idle	67.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.3	14.45	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:8	32.72	2502	2.63	13.39	107	195	Off Idle	67.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.25	14.49	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:8	32.72	2503	2.64	13.39	107	195	Off Idle	67.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.26	14.47	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:9	32.72	2506	2.64	13.39	107	195	Off Idle	67.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.26	14.49	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:9	32.72	2507	2.64	13.39	107	195	Off Idle	66.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.23	14.51	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:9	32.72	2508	2.64	13.4	107	195	Off Idle	66.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.23	14.54	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:9	32.72	2508	2.64	13.4	107	195	Off Idle	66.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.27	14.56	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:9	32.72	2509	2.64	13.41	107	195	Off Idle	66.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.25	14.58	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:15:23:9	32.72	2504	2.64	13.41	107	195	Off Idle	66.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.19	14.61	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:23:9	32.72	2504	2.64	13.41	107	195	Off Idle	66.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.2	14.62	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:24:0	32.72	2509	2.64	13.4	107	195	Off Idle	66.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.22	14.66	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:15:24:0	32.72	2510	2.64	13.4	107	195	Off Idle	66.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.21	14.7	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:0	32.72	2519	2.64	13.38	107	196	Off Idle	66.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.28	14.7	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:0	32.72	2519	2.64	13.38	107	196	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.34	14.72	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:0	32.72	2516	2.64	13.38	107	196	Off Idle	65.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.36	14.74	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:0	32.72	2519	2.64	13.38	107	195	Off Idle	65.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.42	14.74	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:1	32.72	2522	2.63	13.39	107	195	Off Idle	65.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.6	14.76	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:1	32.72	2522	2.62	13.41	107	195	Off Idle	65.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.7	14.78	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:24:1	32.72	2524	2.61	13.41	107	195	Off Idle	65.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.77	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:24:1	32.72	2544	2.61	13.41	107	195	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.92	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:24:1	32.72	2535	2.6	13.4	107	195	Off Idle	65.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.01	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:24:1	32.72	2526	2.58	13.4	107	195	Off Idle	65.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.19	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:24:1	32.72	2519	2.56	13.39	107	195	Off Idle	65.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.39	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:24:2	32.72	2511	2.55	13.4	107	195	Off Idle	65.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.61	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:24:2	32.72	2511	2.53	13.39	107	195	Off Idle	65.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.84	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:24:2	32.72	2519	2.51	13.38	107	195	Off Idle	65.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.03	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:2	32.72	2521	2.49	13.39	107	195	Off Idle	65.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.17	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:2	32.72	2521	2.47	13.4	107	195	Off Idle	65	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.32	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:2	32.72	2528	2.45	13.4	107	195	Off Idle	65	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.47	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:3	32.72	2528	2.43	13.41	107	195	Off Idle	64.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.56	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:3	32.72	2531	2.42	13.41	107	195	Off Idle	64.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.65	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:3	32.72	2530	2.4	13.42	107	195	Off Idle	64.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.66	14.79	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:3	32.72	2526	2.39	13.41	107	195	Off Idle	64.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.72	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:3	32.72	2534	2.37	13.4	107	195	Off Idle	64.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.83	14.79	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:3	32.72	2544	2.35	13.4	107	195	Off Idle	64.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.87	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:24:4	32.72	2543	2.34	13.38	107	195	Off Idle	64.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.89	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:4	32.72	2546	2.33	13.39	107	195	Off Idle	64.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.04	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:4	32.72	2552	2.33	13.39	107	195	Off Idle	64.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.11	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:4	32.72	2556	2.31	13.39	107	196	Off Idle	64.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.2	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:24:4	32.72	2544	2.31	13.39	107	196	Off Idle	64.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.3	15.3	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:24:4	32.72	2544	2.3	13.39	107	195	Off Idle	64.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.35	15.46	1.05	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:24:4	32.72	2540	2.3	13.41	107	195	Off Idle	63.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.42	15.75	1.07	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:5	32.72	2528	2.29	13.4	107	195	Off Idle	63.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.43	15.94	1.09	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:5	32.72	2532	2.29	13.4	107	195	Off Idle	63.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.39	16.18	1.1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:24:5	32.72	2533	2.29	13.41	107	195	Off Idle	64.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.42	16.25	1.11	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:5	32.72	2532	2.28	13.42	107	195	Off Idle	64.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.49	16.36	1.11	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:5	32.72	2541	2.28	13.42	107	195	Off Idle	64.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.47	16.47	1.12	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:5	32.72	2531	2.28	13.41	107	195	Off Idle	64.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.52	16.53	1.13	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:6	32.72	2548	2.28	13.41	107	195	Off Idle	64.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.57	16.56	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:6	32.72	2549	2.27	13.41	107	195	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.59	16.56	1.13	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:6	32.72	2552	2.27	13.41	107	195	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.63	16.56	1.13	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:24:6	32.72	2559	2.27	13.4	107	195	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.64	16.54	1.13	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:6	32.72	2561	2.26	13.4	107	195	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.64	16.54	1.13	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:6	32.72	2560	2.26	13.41	107	195	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.65	16.55	1.13	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:6	32.72	2566	2.26	13.4	107	196	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.64	16.55	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:24:7	32.72	2548	2.26	13.41	107	196	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.6	16.54	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:7	32.72	2548	2.26	13.41	107	196	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.6	16.56	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:7	32.72	2546	2.26	13.41	107	195	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.64	16.56	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:7	32.72	2544	2.26	13.42	107	195	Off Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.66	16.56	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:7	34.08	2545	2.26	13.41	107	195	Off Idle	63.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.68	16.56	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:7	34.08	2545	2.26	13.41	107	195	Off Idle	63.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.71	16.55	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:8	34.08	2546	2.26	13.41	107	195	Off Idle	63.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.66	16.52	1.13	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:8	34.08	2554	2.26	13.4	107	195	Off Idle	63.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.66	16.46	1.12	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:8	34.08	2561	2.26	13.4	107	195	Off Idle	63.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.68	16.41	1.12	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:8	34.08	2567	2.26	13.41	107	195	Off Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.7	16.34	1.11	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:8	34.08	2567	2.26	13.4	107	195	Off Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.71	16.29	1.11	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:8	34.08	2578	2.26	13.41	107	195	Off Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.75	16.27	1.11	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:9	34.08	2587	2.26	13.41	107	195	Off Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.75	16.24	1.11	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:9	34.08	2574	2.26	13.41	107	195	Off Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.73	16.21	1.1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:9	34.08	2571	2.26	13.41	107	195	Off Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.75	16.18	1.1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:9	34.08	2567	2.26	13.4	107	195	Off Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.74	16.16	1.1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:9	32.72	2536	2.26	13.39	107	195	Off Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.74	16.14	1.1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:9	32.72	2554	2.26	13.39	107	195	Off Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.72	16.15	1.1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:24:9	32.72	2555	2.26	13.41	107	195	Off Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.71	16.15	1.1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:25:0	32.72	2555	2.26	13.41	107	195	Off Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.72	16.13	1.1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:25:0	32.72	2557	2.26	13.41	107	195	Off Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.76	16.12	1.1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:25:0	32.72	2572	2.26	13.41	107	195	Off Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.76	16.08	1.1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:25:0	34.08	2557	2.26	13.4	107	195	Off Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.77	16.07	1.09	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:0	34.08	2560	2.26	13.41	107	195	Off Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.78	16.03	1.09	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:0	34.08	2572	2.26	13.41	107	195	Off Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.81	16.02	1.09	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:1	34.08	2577	2.26	13.41	107	195	Off Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.8	15.97	1.09	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:1	34.08	2568	2.26	13.41	107	195	Off Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.81	15.91	1.08	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:1	34.08	2580	2.26	13.41	107	195	Off Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.82	15.87	1.08	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:1	34.08	2578	2.26	13.41	107	195	Off Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.81	15.83	1.08	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:1	34.08	2573	2.26	13.41	107	195	Off Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.8	15.78	1.07	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:1	34.08	2586	2.26	13.4	107	195	Off Idle	63	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.8	15.76	1.07	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:1	34.08	2586	2.26	13.4	107	195	Off Idle	63	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.74	15.73	1.07	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:25:2	34.08	2565	2.27	13.39	107	195	Off Idle	63	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.71	15.72	1.07	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:2	34.08	2564	2.27	13.39	107	195	Off Idle	63	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.64	15.7	1.07	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:25:2	34.08	2565	2.28	13.4	107	195	Off Idle	63	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.6	15.68	1.07	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:2	34.08	2557	2.28	13.4	107	195	Off Idle	63	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.56	15.66	1.07	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:2	34.08	2568	2.28	13.41	107	195	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.45	15.63	1.07	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:2	34.08	2577	2.29	13.4	107	195	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.42	15.6	1.06	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:25:3	34.08	2586	2.29	13.41	107	195	Off Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.35	15.56	1.06	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:25:3	34.08	2580	2.3	13.4	107	195	Off Idle	63	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.28	15.54	1.06	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:25:3	32.72	2618	2.31	13.4	107	195	Off Idle	62.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.15	15.49	1.06	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:25:3	32.72	2602	2.33	13.39	107	195	Off Idle	62.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.08	15.46	1.05	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:25:3	32.72	2601	2.33	13.39	107	195	Off Idle	62.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.03	15.44	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:3	32.72	2596	2.35	13.38	107	195	Off Idle	62.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.97	15.45	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:4	32.72	2596	2.36	13.38	107	195	Off Idle	62.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.94	15.44	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:4	32.72	2607	2.37	13.4	107	195	Off Idle	62.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.83	15.46	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:4	34.08	2586	2.38	13.39	107	195	Off Idle	62.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.78	15.48	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:4	34.08	2587	2.39	13.41	107	195	Off Idle	62.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.73	15.5	1.06	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:4	34.08	2594	2.4	13.41	107	195	Off Idle	62	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.63	15.52	1.06	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:4	34.08	2596	2.41	13.41	107	195	Off Idle	61.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.64	15.52	1.06	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:4	34.08	2597	2.42	13.42	107	195	Off Idle	61.7	0	2	132	944 Turbo	0.16	Rich	1	14.6	-4.56	15.51	1.06	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:5	34.08	2598	2.43	13.41	107	195	Off Idle	61.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-4.52	15.48	1.05	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:5	34.08	2600	2.43	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.44	15.45	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:5	34.08	2601	2.44	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.39	15.42	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:5	34.08	2600	2.45	13.41	107	196	Off Idle	61.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.39	15.35	1.05	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:5	34.08	2600	2.46	13.41	107	196	Off Idle	61.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.35	15.33	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:5	34.08	2601	2.47	13.41	107	196	Off Idle	61.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.28	15.29	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:6	32.72	2591	2.47	13.42	107	196	Off Idle	61.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.25	15.25	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:25:6	32.72	2617	2.47	13.41	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.24	15.2	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:6	34.08	2601	2.48	13.38	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.19	15.14	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:6	34.08	2601	2.48	13.39	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.15	15.11	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:25:6	34.08	2604	2.48	13.39	107	195	Off Idle	61	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.21	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:25:6	34.08	2603	2.48	13.4	107	195	Off Idle	60.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.22	15.02	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:6	32.72	2614	2.49	13.4	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.22	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:7	32.72	2614	2.49	13.4	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.21	14.95	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:7	32.72	2614	2.49	13.39	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.19	14.89	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:7	32.72	2614	2.49	13.39	107	196	Off Idle	60.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.22	14.84	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:7	32.72	2615	2.5	13.39	107	196	Off Idle	60.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.19	14.82	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:7	32.72	2616	2.5	13.39	107	196	Off Idle	60.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.14	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:7	32.72	2616	2.5	13.39	107	196	Off Idle	60.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.16	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:25:8	32.72	2618	2.5	13.4	107	196	Off Idle	60.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.2	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:8	32.72	2618	2.5	13.41	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.16	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:8	32.72	2619	2.5	13.41	107	195	Off Idle	60	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.19	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:8	32.72	2624	2.5	13.42	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.21	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:8	32.72	2626	2.49	13.41	107	195	Off Idle	59.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.21	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:8	32.72	2624	2.49	13.4	107	195	Off Idle	59.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.23	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:9	32.72	2629	2.5	13.41	107	195	Off Idle	59.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.22	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:9	32.72	2649	2.5	13.4	107	195	Off Idle	59.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.25	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:25:9	34.08	2633	2.5	13.38	107	195	Off Idle	59.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.27	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:25:9	34.08	2632	2.5	13.4	107	195	Off Idle	59.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.25	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:25:9	34.08	2630	2.5	13.4	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.29	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:25:9	34.08	2632	2.5	13.41	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.25	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:25:9	34.08	2634	2.49	13.4	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.27	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:26:0	34.08	2634	2.49	13.4	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.26	14.8	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:26:0	34.08	2638	2.49	13.39	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.3	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:26:0	34.08	2638	2.49	13.4	107	195	Off Idle	59.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.31	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:26:0	34.08	2642	2.49	13.39	107	195	Off Idle	59	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.3	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:26:0	34.08	2649	2.49	13.41	107	195	Off Idle	59	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.27	14.87	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:26:0	34.08	2649	2.49	13.4	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-4.31	14.88	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:26:1	32.72	2630	2.49	13.41	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.29	14.92	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:1	32.72	2651	2.49	13.41	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-4.32	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:1	32.72	2650	2.49	13.42	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.36	14.98	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:1	32.72	2649	2.49	13.43	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.35	15.06	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:1	32.72	2649	2.49	13.4	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.38	15.12	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:1	32.72	2670	2.49	13.4	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.35	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:1	34.08	2649	2.49	13.41	107	195	Off Idle	58	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.35	15.09	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:2	34.08	2648	2.49	13.4	107	195	Off Idle	57.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.37	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:2	34.08	2649	2.49	13.41	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.38	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:2	34.08	2666	2.49	13.41	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.44	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:2	34.08	2629	2.49	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.43	14.89	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:2	34.08	2629	2.49	13.4	107	195	Off Idle	57.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.5	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:26:2	32.72	2653	2.48	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.52	14.74	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:26:3	32.72	2652	2.48	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.56	14.69	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:26:3	32.72	2652	2.48	13.4	107	195	Off Idle	57.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.62	14.68	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:26:3	32.72	2654	2.47	13.4	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.72	14.68	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:26:3	32.72	2658	2.46	13.4	107	195	Off Idle	57	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.75	14.7	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:26:3	34.08	2661	2.46	13.4	107	195	Off Idle	57	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.79	14.72	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:3	34.08	2664	2.46	13.4	107	195	Off Idle	57	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.84	14.75	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:4	34.08	2664	2.45	13.39	107	195	Off Idle	57	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.87	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:4	34.08	2666	2.44	13.42	107	195	Off Idle	57	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.96	14.81	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:4	34.08	2666	2.43	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.02	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:4	34.08	2664	2.42	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.14	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:4	34.08	2667	2.41	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.23	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:4	34.08	2667	2.4	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.29	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:4	34.08	2663	2.39	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.29	14.86	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:5	34.08	2668	2.38	13.41	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.36	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:26:5	34.08	2666	2.38	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5.41	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:5	34.08	2668	2.37	13.42	107	195	Off Idle	57	0	2	132	944 Turbo	0.17	Rich	1	14.6	-5.42	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:5	34.08	2673	2.36	13.4	107	195	Off Idle	57	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.49	14.9	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:5	34.08	2672	2.36	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.5	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:26:5	34.08	2672	2.35	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.53	14.97	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:6	34.08	2674	2.35	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.54	15.07	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:6	34.08	2674	2.34	13.4	107	195	Off Idle	57	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.59	15.13	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:6	34.08	2674	2.34	13.42	107	195	Off Idle	57	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.59	15.19	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:6	34.08	2677	2.33	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.62	15.23	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:6	34.08	2677	2.33	13.41	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.63	15.35	1.05	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:6	34.08	2679	2.32	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.66	15.4	1.05	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:6	34.08	2679	2.32	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.7	15.44	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:7	34.08	2679	2.32	13.42	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.69	15.46	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:7	34.08	2677	2.32	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.75	15.48	1.05	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:7	34.08	2676	2.32	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.78	15.47	1.05	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:7	34.08	2676	2.31	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.81	15.46	1.05	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:7	34.08	2675	2.31	13.4	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.82	15.46	1.05	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:26:7	34.08	2671	2.3	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.87	15.45	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:8	34.08	2675	2.3	13.39	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.89	15.43	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:8	34.08	2678	2.3	13.39	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.93	15.42	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:8	34.08	2684	2.29	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.96	15.41	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:8	34.08	2684	2.29	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.02	15.4	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:8	34.08	2685	2.28	13.42	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.1	15.39	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:8	34.08	2683	2.28	13.4	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.13	15.37	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:9	34.08	2683	2.27	13.4	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.13	15.35	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:9	34.08	2683	2.27	13.41	107	195	Off Idle	56.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.16	15.32	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:9	34.08	2683	2.27	13.4	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.24	15.31	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:9	34.08	2691	2.26	13.4	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.27	15.27	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:9	34.08	2691	2.26	13.41	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.26	15.25	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:9	34.08	2690	2.26	13.4	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.24	15.23	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:26:9	34.08	2692	2.25	13.4	107	195	Off Idle	56	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.3	15.21	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:27:0	34.08	2692	2.25	13.39	107	195	Off Idle	55.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.32	15.19	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:27:0	34.08	2696	2.24	13.38	107	195	Off Idle	55.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.37	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:27:0	34.08	2701	2.24	13.38	107	195	Off Idle	55.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.42	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:0	34.08	2699	2.24	13.39	107	195	Off Idle	55.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.47	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:0	34.08	2698	2.24	13.39	107	195	Off Idle	55.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.48	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:0	34.08	2694	2.23	13.4	107	195	Off Idle	55.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.47	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:1	34.08	2691	2.23	13.4	107	195	Off Idle	55.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.46	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:1	34.08	2688	2.23	13.41	107	195	Off Idle	56.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.49	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:1	34.08	2688	2.22	13.43	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.52	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:1	34.08	2690	2.22	13.42	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.54	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:1	34.08	2692	2.22	13.42	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.58	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:1	34.08	2691	2.21	13.43	107	195	Off Idle	56.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.66	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:1	34.08	2693	2.21	13.43	107	195	Off Idle	56.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.66	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:2	34.08	2697	2.21	13.42	107	195	Off Idle	56.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.71	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:2	34.08	2704	2.2	13.41	107	195	Off Idle	56.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.7	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:27:2	34.08	2709	2.2	13.42	107	195	Off Idle	56.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.71	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:2	34.08	2709	2.2	13.41	107	195	Off Idle	56.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.73	15.05	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:2	34.08	2712	2.2	13.42	107	195	Off Idle	56.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.76	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:2	34.08	2708	2.19	13.42	107	195	Off Idle	55.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.79	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:3	34.08	2698	2.19	13.42	107	195	Off Idle	55.7	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.79	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:3	34.08	2712	2.19	13.41	107	195	Off Idle	55.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.76	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:3	35.45	2703	2.19	13.42	107	195	Off Idle	55.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.75	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:3	35.45	2690	2.19	13.41	107	195	Off Idle	55.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.71	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:3	35.45	2688	2.2	13.41	107	195	Off Idle	54.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.68	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:3	35.45	2694	2.2	13.43	107	195	Off Idle	54.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.58	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:27:4	35.45	2694	2.2	13.42	107	195	Off Idle	54.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.51	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:27:4	35.45	2690	2.21	13.41	107	195	Off Idle	54.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.38	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:27:4	34.08	2712	2.22	13.41	107	195	Off Idle	54.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.24	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:27:4	34.08	2713	2.23	13.4	107	195	Off Idle	54.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.16	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:27:4	34.08	2720	2.24	13.41	107	195	Off Idle	54.9	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.07	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:27:4	34.08	2724	2.25	13.42	107	195	Off Idle	54.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:27:4	34.08	2724	2.26	13.42	107	195	Off Idle	54.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.88	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:27:5	34.08	2723	2.27	13.41	107	195	Off Idle	54.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.79	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:27:5	34.08	2723	2.28	13.4	107	195	Off Idle	54.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.77	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:27:5	34.08	2721	2.29	13.39	107	195	Off Idle	54.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.63	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:27:5	34.08	2715	2.31	13.41	107	195	Off Idle	54.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.51	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:5	34.08	2708	2.33	13.4	107	195	Off Idle	54.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.45	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:27:5	34.08	2707	2.34	13.38	107	195	Off Idle	54.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.36	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:6	34.08	2707	2.35	13.39	107	195	Off Idle	54.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.3	15.05	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:6	34.08	2712	2.36	13.39	107	195	Off Idle	54.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.21	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:6	34.08	2718	2.38	13.41	107	195	Off Idle	53.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.17	15.16	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:27:6	34.08	2718	2.39	13.4	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.08	15.2	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:27:6	34.08	2722	2.4	13.41	107	195	Off Idle	53.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.05	15.23	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:6	34.08	2733	2.41	13.42	107	195	Off Idle	53.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.01	15.24	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:27:6	34.08	2732	2.42	13.41	107	195	Off Idle	53.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.01	15.24	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:7	34.08	2732	2.42	13.4	107	195	Off Idle	53.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.96	15.22	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:7	34.08	2732	2.43	13.39	107	195	Off Idle	53.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.96	15.16	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:7	34.08	2718	2.43	13.39	107	195	Off Idle	53.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.94	15.13	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:7	34.08	2714	2.44	13.4	107	195	Off Idle	53.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.88	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:7	34.08	2712	2.45	13.39	107	195	Off Idle	53.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.85	15.06	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:7	34.08	2714	2.45	13.41	107	195	Off Idle	53.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.86	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:27:8	34.08	2718	2.46	13.41	107	195	Off Idle	53.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.84	15.01	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:27:8	34.08	2720	2.46	13.41	107	195	Off Idle	53.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.86	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:8	34.08	2728	2.46	13.41	107	195	Off Idle	53.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.84	14.94	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:8	34.08	2729	2.46	13.42	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.84	14.91	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:8	34.08	2740	2.46	13.41	107	195	Off Idle	53.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.83	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:8	34.08	2740	2.46	13.42	107	195	Off Idle	53.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.87	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:9	34.08	2742	2.46	13.41	107	195	Off Idle	53.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.87	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:9	34.08	2742	2.46	13.41	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.85	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:9	34.08	2757	2.46	13.42	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.83	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:9	34.08	2757	2.46	13.41	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.82	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:9	34.08	2735	2.46	13.43	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.85	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:9	34.08	2733	2.47	13.42	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.79	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:27:9	34.08	2734	2.47	13.44	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.81	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:0	34.08	2718	2.47	13.42	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.8	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:0	34.08	2729	2.47	13.42	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.79	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:0	34.08	2745	2.47	13.41	107	195	Off Idle	53.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.75	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:0	34.08	2741	2.47	13.41	107	195	Off Idle	53.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.75	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:0	34.08	2741	2.47	13.41	107	195	Off Idle	53.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.77	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:0	34.08	2747	2.47	13.4	107	195	Off Idle	53.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.76	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:28:1	34.08	2751	2.48	13.4	107	195	Off Idle	53	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.76	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:28:1	34.08	2751	2.48	13.39	107	195	Off Idle	52.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.7	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:28:1	34.08	2752	2.48	13.41	107	195	Off Idle	53	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.74	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:28:1	34.08	2760	2.48	13.42	107	195	Off Idle	52.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.69	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:28:1	34.08	2763	2.48	13.41	107	195	Off Idle	52.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.61	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:28:1	34.08	2764	2.49	13.41	107	195	Off Idle	52.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.62	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:28:1	34.08	2763	2.49	13.42	107	195	Off Idle	52.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.59	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:28:2	34.08	2759	2.49	13.41	107	195	Off Idle	52.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.57	14.87	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:15:28:2	34.08	2760	2.49	13.43	107	195	Off Idle	52.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.57	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:15:28:2	34.08	2756	2.5	13.41	107	195	Off Idle	51.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.59	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:28:2	34.08	2757	2.5	13.4	107	195	Off Idle	51.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.61	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:28:2	34.08	2758	2.5	13.41	107	195	Off Idle	51.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.62	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:28:2	34.08	2758	2.5	13.4	107	195	Off Idle	51.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.64	15.06	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:28:3	34.08	2768	2.5	13.41	107	195	Off Idle	51.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.66	15.1	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:15:28:3	34.08	2754	2.5	13.42	107	195	Off Idle	51	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.7	15.12	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:28:3	34.08	2754	2.5	13.42	107	195	Off Idle	51	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.74	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:3	34.08	2762	2.49	13.4	107	195	Off Idle	51	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.82	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:3	34.08	2760	2.49	13.4	107	195	Off Idle	51	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.82	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:28:3	34.08	2769	2.48	13.4	107	195	Off Idle	50.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.89	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:28:4	34.08	2770	2.47	13.4	107	195	Off Idle	50.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.95	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:28:4	34.08	2771	2.47	13.41	107	195	Off Idle	51	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.09	14.91	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:4	34.08	2772	2.46	13.4	107	195	Off Idle	51	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.2	14.81	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:4	34.08	2764	2.45	13.4	107	195	Off Idle	51	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.29	14.74	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:4	34.08	2757	2.44	13.4	107	195	Off Idle	51	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.36	14.71	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:4	34.08	2757	2.43	13.41	107	195	Off Idle	51	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.4	14.69	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:28:4	34.08	2748	2.42	13.41	107	195	Off Idle	51	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.5	14.68	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:28:5	34.08	2763	2.41	13.41	107	195	Off Idle	51.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.55	14.67	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:28:5	34.08	2768	2.4	13.4	107	195	Off Idle	51.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.57	14.69	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:5	34.08	2769	2.4	13.42	107	195	Off Idle	51.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.57	14.67	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:5	34.08	2790	2.38	13.41	107	195	Off Idle	51.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.62	14.7	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:5	34.08	2779	2.38	13.41	107	195	Off Idle	51	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.61	14.71	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:5	34.08	2786	2.37	13.39	107	195	Off Idle	51	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.65	14.74	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:6	34.08	2786	2.36	13.39	107	195	Off Idle	50.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.72	14.75	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:6	34.08	2794	2.35	13.38	107	195	Off Idle	50.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.69	14.75	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:6	34.08	2798	2.35	13.38	107	195	Off Idle	50.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.78	14.77	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:6	34.08	2795	2.35	13.4	107	195	Off Idle	50.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.88	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:6	34.08	2788	2.34	13.41	107	195	Off Idle	50.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.89	14.89	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:6	34.08	2788	2.34	13.4	107	195	Off Idle	50.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.98	14.94	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:28:6	34.08	2771	2.32	13.42	107	195	Off Idle	50.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.09	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:28:7	34.08	2776	2.31	13.41	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.13	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:28:7	35.45	2770	2.3	13.4	107	195	Off Idle	50.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.32	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:28:7	35.45	2760	2.29	13.4	107	195	Off Idle	50.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.45	15.15	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:28:7	35.45	2772	2.27	13.39	107	195	Off Idle	50.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.64	15.21	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:28:7	35.45	2788	2.26	13.39	107	195	Off Idle	50.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.78	15.22	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:28:7	35.45	2775	2.25	13.41	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.92	15.2	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:28:8	35.45	2777	2.23	13.41	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.08	15.19	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:28:8	35.45	2776	2.22	13.42	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.17	15.18	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:28:8	35.45	2779	2.19	13.43	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.36	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:8	35.45	2772	2.18	13.43	107	195	Off Idle	50.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.43	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:8	35.45	2772	2.16	13.42	107	195	Off Idle	50.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.54	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:8	35.45	2771	2.13	13.43	107	195	Off Idle	50.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.67	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:9	35.45	2770	2.12	13.42	107	195	Off Idle	50.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.72	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:28:9	35.45	2767	2.09	13.4	107	195	Off Idle	50.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.78	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:28:9	35.45	2769	2.08	13.41	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.82	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:28:9	35.45	2769	2.06	13.41	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.86	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:9	35.45	2767	2.05	13.42	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.91	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:9	35.45	2774	2.04	13.41	107	195	Off Idle	50.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.97	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:28:9	35.45	2768	2.03	13.43	107	195	Off Idle	50.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.96	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:0	35.45	2768	2.02	13.42	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.98	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:0	35.45	2771	2.02	13.41	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:0	35.45	2777	2.01	13.42	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.01	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:0	35.45	2783	2	13.39	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.04	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:0	35.45	2769	2	13.4	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.06	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:0	35.45	2782	2	13.39	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.03	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:1	35.45	2783	1.99	13.4	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.05	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:1	35.45	2783	1.99	13.41	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.1	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:1	35.45	2782	1.99	13.41	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.14	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:1	35.45	2784	1.99	13.42	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.2	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:1	35.45	2780	1.98	13.42	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.31	15.2	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:1	35.45	2781	1.97	13.4	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.41	15.24	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:29:1	35.45	2781	1.95	13.4	107	195	Off Idle	50.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.49	15.3	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:2	35.45	2782	1.94	13.39	107	195	Off Idle	50.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.62	15.36	1.05	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:29:2	35.45	2776	1.91	13.41	107	195	Off Idle	50.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.85	15.42	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:29:2	35.45	2778	1.89	13.42	107	195	Idle	50.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.06	15.44	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:29:2	35.45	2778	1.86	13.41	107	195	Idle	50.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.2	15.44	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:2	35.45	2768	1.83	13.43	107	195	Idle	50.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.26	15.43	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:2	35.45	2758	1.81	13.43	107	195	Idle	50.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.48	15.41	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:3	35.45	2758	1.79	13.44	107	195	Idle	50.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.57	15.39	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:3	29.99	2706	1.76	13.42	107	195	Idle	50.7	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.7	15.34	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:3	24.54	2699	1.74	13.41	107	195	Idle	50.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.72	15.31	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:3	24.54	2676	1.71	13.41	107	195	Idle	51.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.75	15.27	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:3	19.09	2704	1.69	13.39	107	195	Idle	51.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.81	15.22	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:3	19.09	2700	1.67	13.41	107	195	Idle	51.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.85	15.19	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:4	19.09	2685	1.64	13.42	107	195	Idle	51.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.87	15.2	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:4	19.09	2701	1.62	13.42	107	195	Idle	51.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.98	15.17	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:4	19.09	2713	1.6	13.44	107	195	Idle	51.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.04	15.13	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:4	19.09	2718	1.58	13.43	107	195	Idle	52	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.07	15.09	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:4	19.09	2743	1.57	13.43	107	195	Idle	52.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.14	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:4	19.09	2802	1.56	13.41	107	195	Idle	52.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-10.14	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:4	19.09	2786	1.56	13.41	107	195	Idle	52.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-10.14	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:5	19.09	2774	1.55	13.4	107	195	Idle	52.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.12	14.87	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:5	19.09	2751	1.55	13.4	107	195	Idle	52.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.09	14.81	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:5	19.09	2751	1.55	13.4	107	195	Idle	52.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.07	14.7	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:5	19.09	2762	1.55	13.42	107	195	Idle	52.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.04	14.56	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:5	19.09	2752	1.54	13.42	107	195	Idle	52.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.03	14.47	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:5	19.09	2737	1.54	13.43	107	195	Idle	51.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.04	14.41	0.98	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:6	19.09	2728	1.54	13.43	107	195	Idle	51.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.02	14.38	0.98	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:6	19.09	2723	1.54	13.43	107	195	Idle	51.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.03	14.34	0.98	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:6	19.09	2723	1.54	13.41	107	195	Idle	51.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10	14.33	0.98	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:6	19.09	2713	1.54	13.41	107	195	Idle	51.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.97	14.35	0.98	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:6	19.09	2726	1.54	13.41	107	195	Idle	51.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.98	14.41	0.98	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:6	19.09	2730	1.54	13.4	107	195	Idle	51.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.98	14.47	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:6	19.09	2731	1.54	13.41	107	195	Idle	51.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.98	14.5	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:7	19.09	2739	1.54	13.41	107	195	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	14.56	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:7	19.09	2752	1.54	13.4	107	195	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	14.64	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:7	19.09	2744	1.54	13.4	107	195	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	14.76	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:7	19.09	2740	1.54	13.42	107	195	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:7	19.09	2740	1.55	13.43	107	195	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	15.35	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:7	19.09	2736	1.55	13.44	107	195	Idle	51.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	15.98	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:8	19.09	2732	1.55	13.42	107	195	Idle	51.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	16.5	1.12	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:8	19.09	2726	1.55	13.42	107	195	Idle	52.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	17.03	1.16	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:8	19.09	2725	1.55	13.42	107	195	Idle	52.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	17.32	1.18	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:8	19.09	2707	1.55	13.41	107	195	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	18.16	1.24	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:8	19.09	2713	1.55	13.41	107	195	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	18.67	1.27	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:8	19.09	2709	1.55	13.41	107	195	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	19.35	1.32	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:9	19.09	2706	1.55	13.41	107	195	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	19.71	1.34	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:9	19.09	2706	1.55	13.42	107	195	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:9	19.09	2706	1.55	13.42	107	195	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.16	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:9	19.09	2707	1.55	13.42	107	195	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:9	19.09	2707	1.55	13.42	107	195	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:9	19.09	2710	1.55	13.42	107	195	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:29:9	19.09	2712	1.55	13.42	107	195	Idle	52.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:0	19.09	2713	1.55	13.41	107	195	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:0	19.09	2714	1.55	13.41	107	195	Idle	52.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:0	19.09	2712	1.55	13.41	107	195	Idle	52.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:0	19.09	2712	1.54	13.41	107	195	Idle	52.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:0	19.09	2711	1.54	13.4	107	195	Idle	52.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:0	19.09	2709	1.54	13.43	107	195	Idle	53	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:1	19.09	2706	1.54	13.43	107	195	Idle	53.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:1	19.09	2703	1.53	13.43	107	195	Idle	53.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:1	19.09	2703	1.53	13.42	107	195	Idle	53.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:30:1	19.09	2704	1.53	13.43	107	195	Idle	54	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:1	19.09	2703	1.53	13.42	107	195	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:1	19.09	2702	1.53	13.42	107	195	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:1	19.09	2702	1.53	13.42	107	195	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:2	19.09	2708	1.52	13.41	107	195	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:2	19.09	2697	1.52	13.42	107	195	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:2	19.09	2697	1.52	13.42	107	195	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:2	19.09	2693	1.52	13.41	107	195	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:2	19.09	2692	1.52	13.41	107	195	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:2	19.09	2688	1.51	13.41	107	195	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:3	19.09	2682	1.51	13.41	107	195	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:3	19.09	2680	1.51	13.39	107	195	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:3	19.09	2680	1.51	13.4	107	195	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:3	19.09	2679	1.51	13.4	107	195	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:3	19.09	2676	1.51	13.4	107	195	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:3	19.09	2676	1.51	13.4	107	195	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:4	19.09	2672	1.51	13.41	107	195	Idle	54.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:4	19.09	2668	1.51	13.4	107	195	Idle	54.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:4	19.09	2663	1.51	13.41	107	195	Idle	54.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:4	19.09	2663	1.51	13.41	107	195	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:4	19.09	2659	1.51	13.41	107	195	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:4	19.09	2659	1.51	13.42	107	195	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:4	19.09	2659	1.51	13.43	107	195	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:5	19.09	2660	1.5	13.43	107	195	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:5	19.09	2661	1.5	13.42	107	195	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:5	19.09	2661	1.5	13.43	107	195	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:5	19.09	2673	1.5	13.42	107	195	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:5	19.09	2662	1.5	13.41	107	195	Idle	54.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:5	19.09	2663	1.5	13.42	107	195	Idle	55.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:6	19.09	2664	1.5	13.41	107	195	Idle	55.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:6	19.09	2665	1.5	13.41	107	195	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:6	19.09	2665	1.5	13.41	107	195	Off Idle	55.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:6	19.09	2665	1.5	13.41	107	195	Off Idle	55.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:6	9.54	2661	1.5	13.41	107	195	Off Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:30:6	9.54	2601	1.5	13.42	107	195	Off Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:30:6	12.27	2671	1.51	13.43	107	195	Off Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:30:7	14.99	2670	1.52	13.42	107	195	Off Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:30:7	14.99	2668	1.52	13.42	107	195	Off Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:7	17.72	2658	1.53	13.42	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:7	20.45	2666	1.53	13.42	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:7	23.18	2668	1.54	13.41	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:7	23.18	2672	1.54	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:8	25.9	2688	1.55	13.42	107	195	Off Idle	57.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:8	28.63	2687	1.56	13.42	107	195	Off Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:8	28.63	2696	1.56	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:8	31.36	2696	1.57	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:30:8	34.08	2691	1.57	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:30:8	35.45	2691	1.58	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:30:9	35.45	2660	1.59	13.42	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:30:9	35.45	2654	1.59	13.43	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.06	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:9	35.45	2648	1.6	13.42	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.03	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:30:9	35.45	2644	1.6	13.43	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.06	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:30:9	35.45	2638	1.6	13.43	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.05	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:30:9	35.45	2633	1.6	13.43	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.05	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:30:9	35.45	2627	1.6	13.43	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.05	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:0	35.45	2627	1.6	13.44	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.04	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:0	35.45	2620	1.6	13.44	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.02	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:0	35.45	2636	1.61	13.44	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:31:0	35.45	2640	1.61	13.41	107	195	Off Idle	57.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:0	35.45	2642	1.61	13.41	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:0	35.45	2648	1.61	13.4	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:1	35.45	2647	1.6	13.41	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.95	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:1	35.45	2646	1.6	13.39	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.96	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:1	35.45	2644	1.61	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.94	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:1	35.45	2643	1.61	13.42	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.96	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:1	35.45	2642	1.61	13.42	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:1	35.45	2642	1.61	13.42	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:1	35.45	2632	1.61	13.42	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.99	20.16	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:2	35.45	2643	1.61	13.41	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.98	19.96	1.36	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:2	35.45	2632	1.61	13.42	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.96	19.77	1.35	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:2	35.45	2632	1.61	13.41	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.95	19.67	1.34	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:2	35.45	2633	1.61	13.41	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.95	19.28	1.31	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:2	35.45	2635	1.61	13.4	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.97	19	1.29	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:2	35.45	2629	1.61	13.41	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.97	18.7	1.27	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:3	35.45	2628	1.61	13.43	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.98	18.38	1.25	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:3	35.45	2630	1.61	13.42	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.99	18.04	1.23	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:3	35.45	2651	1.62	13.44	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10	17.71	1.21	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:3	35.45	2642	1.62	13.42	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.98	17.43	1.19	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:3	35.45	2636	1.62	13.42	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.98	17.2	1.17	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:3	35.45	2639	1.62	13.42	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.98	17	1.16	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:31:4	35.45	2640	1.62	13.42	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.98	16.76	1.14	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:31:4	35.45	2640	1.62	13.41	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.93	16.62	1.13	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:31:4	35.45	2638	1.62	13.42	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.95	16.49	1.12	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:31:4	35.45	2635	1.62	13.41	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.92	16.38	1.12	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:31:4	35.45	2633	1.62	13.41	107	195	Off Idle	58.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.93	16.28	1.11	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:31:4	35.45	2633	1.62	13.41	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.94	16.15	1.1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:31:4	35.45	2628	1.62	13.41	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.92	16.06	1.09	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:31:5	35.45	2627	1.63	13.42	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.87	15.98	1.09	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:31:5	35.45	2627	1.63	13.43	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.87	15.88	1.08	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:31:5	35.45	2627	1.64	13.45	107	195	Off Idle	58.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.73	15.77	1.07	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:31:5	35.45	2628	1.65	13.43	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.68	15.7	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:5	35.45	2628	1.66	13.43	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.6	15.64	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:5	35.45	2629	1.67	13.44	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.55	15.55	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:6	35.45	2631	1.68	13.43	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.46	15.5	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:6	35.45	2638	1.69	13.44	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.38	15.46	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:6	35.45	2643	1.71	13.44	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.33	15.45	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:6	35.45	2643	1.72	13.41	107	195	Off Idle	58.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.25	15.41	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:31:6	35.45	2650	1.73	13.4	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.19	15.38	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:31:6	35.45	2650	1.75	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.09	15.36	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:31:6	35.45	2653	1.77	13.41	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.04	15.32	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:31:7	35.45	2656	1.78	13.43	107	195	Off Idle	58	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.97	15.3	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:7	35.45	2680	1.79	13.42	107	195	Off Idle	57.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.94	15.3	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:7	35.45	2659	1.81	13.43	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.9	15.28	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:31:7	35.45	2659	1.82	13.41	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.87	15.28	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:31:7	35.45	2653	1.84	13.41	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.75	15.27	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:31:7	35.45	2646	1.85	13.42	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.72	15.25	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:31:8	35.45	2639	1.86	13.41	107	195	Off Idle	57.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.66	15.24	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:8	35.45	2631	1.87	13.42	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.58	15.25	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:8	35.45	2628	1.88	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.53	15.25	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:8	35.45	2611	1.89	13.41	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.48	15.24	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:8	35.45	2608	1.89	13.41	107	195	Off Idle	57.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.41	15.23	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:31:8	35.45	2608	1.89	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.41	15.22	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:31:9	35.45	2611	1.9	13.42	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.31	15.23	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:31:9	35.45	2617	1.91	13.42	107	195	Off Idle	57.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.3	15.21	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:31:9	35.45	2618	1.92	13.42	107	195	Off Idle	58	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.28	15.19	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:31:9	35.45	2620	1.92	13.42	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.28	15.18	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:31:9	35.45	2634	1.93	13.42	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.23	15.12	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:31:9	35.45	2644	1.93	13.41	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.26	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:31:9	35.45	2648	1.94	13.41	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.26	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:32:0	35.45	2648	1.94	13.42	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.26	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:32:0	35.45	2643	1.94	13.42	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.3	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:32:0	35.45	2620	1.94	13.41	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.31	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:32:0	35.45	2637	1.94	13.41	107	195	Off Idle	58.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.32	14.8	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:32:0	35.45	2635	1.94	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.46	14.76	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:32:0	35.45	2628	1.93	13.42	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.56	14.77	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:32:1	35.45	2622	1.91	13.42	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.62	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:32:1	35.45	2616	1.9	13.42	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.85	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:32:1	35.45	2615	1.88	13.42	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.98	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:1	35.45	2614	1.86	13.43	107	195	Off Idle	58.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.14	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:1	35.45	2607	1.84	13.43	107	195	Off Idle	58.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.27	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:1	35.45	2594	1.82	13.43	107	195	Off Idle	58.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.39	14.95	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:1	35.45	2592	1.78	13.43	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.57	15	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:2	35.45	2587	1.76	13.43	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.66	15.05	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:2	35.45	2574	1.74	13.43	107	195	Off Idle	59.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.75	15.08	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:2	35.45	2567	1.71	13.44	107	195	Off Idle	59.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.75	15.08	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:2	35.45	2567	1.68	13.41	107	195	Off Idle	59.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.87	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:2	35.45	2545	1.66	13.42	107	195	Off Idle	59.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.94	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:2	35.45	2559	1.63	13.41	107	195	Off Idle	59.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.02	15	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:3	35.45	2564	1.62	13.41	107	195	Off Idle	60.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.05	14.96	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:3	35.45	2575	1.59	13.41	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.09	14.9	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:3	35.45	2600	1.57	13.41	107	195	Off Idle	60.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.13	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:3	35.45	2608	1.55	13.42	107	195	Off Idle	61	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.17	14.78	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:3	35.45	2614	1.52	13.42	107	195	Off Idle	61	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.19	14.67	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:3	35.45	2638	1.51	13.43	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.22	14.63	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:4	35.45	2649	1.5	13.42	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.23	14.58	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:4	35.45	2654	1.5	13.42	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.25	14.53	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:4	35.45	2654	1.5	13.41	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.23	14.5	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:4	35.45	2645	1.5	13.42	107	195	Off Idle	60.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.21	14.48	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:32:4	35.45	2631	1.51	13.41	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.19	14.48	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:4	35.45	2630	1.51	13.42	107	195	Off Idle	60.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.19	14.49	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:4	35.45	2622	1.51	13.44	107	195	Off Idle	60.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.18	14.51	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:5	35.45	2619	1.52	13.44	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.15	14.54	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:5	35.45	2614	1.52	13.45	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.14	14.56	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:5	35.45	2614	1.53	13.44	107	195	Off Idle	59.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.08	14.59	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:5	35.45	2610	1.53	13.43	107	195	Off Idle	59.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.09	14.64	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:5	35.45	2606	1.54	13.41	107	195	Off Idle	59.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.1	14.79	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:5	35.45	2600	1.55	13.4	107	195	Off Idle	59.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.12	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:6	35.45	2598	1.55	13.41	107	195	Off Idle	59.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.11	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:6	35.45	2596	1.55	13.4	107	195	Off Idle	59.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.15	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:6	35.45	2593	1.56	13.41	107	195	Off Idle	59.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.15	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:6	35.45	2590	1.56	13.41	107	195	Off Idle	60	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.13	15.2	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:6	35.45	2588	1.57	13.4	107	195	Off Idle	60.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-10.1	15.28	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:6	35.45	2587	1.57	13.41	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-10.1	15.34	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:6	35.45	2589	1.57	13.42	107	195	Off Idle	60.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-10.06	15.37	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:7	35.45	2588	1.58	13.43	107	195	Off Idle	61	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.01	15.37	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:7	35.45	2588	1.58	13.41	107	195	Off Idle	61.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.97	15.36	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:7	35.45	2590	1.58	13.41	107	195	Off Idle	61.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.96	15.34	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:15:32:7	35.45	2586	1.59	13.42	107	195	Off Idle	61.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.9	15.28	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:7	35.45	2583	1.59	13.41	107	195	Off Idle	61.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.9	15.25	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:7	35.45	2583	1.59	13.4	107	195	Off Idle	61.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.91	15.21	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:8	35.45	2581	1.59	13.41	107	195	Off Idle	61.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.87	15.17	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:8	35.45	2583	1.6	13.41	107	195	Off Idle	61.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.83	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:8	35.45	2580	1.61	13.39	107	195	Off Idle	61.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.82	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:8	35.45	2580	1.61	13.41	107	195	Off Idle	61.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.77	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:32:8	35.45	2586	1.62	13.4	107	195	Off Idle	61.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.73	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:8	35.45	2587	1.63	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.69	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:32:9	35.45	2588	1.63	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.69	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:32:9	35.45	2591	1.64	13.4	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.64	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:32:9	35.45	2594	1.65	13.4	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.62	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:32:9	35.45	2595	1.66	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.59	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:32:9	35.45	2598	1.67	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.56	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:32:9	35.45	2602	1.68	13.42	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.54	14.78	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:32:9	35.45	2600	1.69	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.46	14.73	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:0	35.45	2604	1.7	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.38	14.7	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:0	35.45	2609	1.71	13.42	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.31	14.68	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:0	35.45	2615	1.73	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.2	14.68	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:0	35.45	2619	1.74	13.42	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.13	14.7	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:33:0	35.45	2619	1.76	13.42	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.04	14.72	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:0	35.45	2622	1.77	13.42	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.01	14.74	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:1	35.45	2627	1.78	13.41	107	195	Off Idle	61.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.94	14.77	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:1	35.45	2628	1.8	13.4	107	195	Off Idle	61.2	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.85	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:33:1	35.45	2631	1.81	13.39	107	195	Off Idle	61	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.78	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:33:1	35.45	2631	1.82	13.39	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.72	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:33:1	35.45	2620	1.84	13.39	107	195	Off Idle	60.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.62	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:1	35.45	2608	1.86	13.4	107	195	Off Idle	60.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.52	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:1	35.45	2603	1.86	13.38	107	195	Off Idle	60.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.46	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:2	35.45	2582	1.88	13.38	107	195	Off Idle	60.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.37	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:33:2	35.45	2570	1.9	13.41	107	195	Off Idle	59.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.31	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:2	35.45	2566	1.91	13.41	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.27	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:2	35.45	2546	1.91	13.41	107	195	Off Idle	60	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.18	14.9	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:2	35.45	2574	1.92	13.44	107	195	Off Idle	60	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.14	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:2	35.45	2574	1.93	13.42	107	195	Off Idle	60	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.1	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:3	35.45	2590	1.93	13.42	107	195	Off Idle	60.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.07	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:3	35.45	2573	1.94	13.41	107	195	Off Idle	60.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.08	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:3	34.08	2573	1.94	13.41	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.07	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:3	34.08	2601	1.95	13.41	107	195	Off Idle	60.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.02	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:3	34.08	2604	1.96	13.42	107	195	Off Idle	60.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.97	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:33:3	34.08	2610	1.96	13.41	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.94	14.96	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:33:4	34.08	2610	1.97	13.41	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.89	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:33:4	35.45	2626	1.97	13.41	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.9	14.9	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:33:4	35.45	2615	1.98	13.41	107	195	Off Idle	61.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.86	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:33:4	35.45	2613	1.98	13.39	107	195	Off Idle	60.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.85	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:33:4	35.45	2613	1.99	13.4	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.8	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:4	35.45	2613	1.99	13.4	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.79	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:4	35.45	2621	2	13.4	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:5	35.45	2621	2	13.41	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:5	35.45	2608	2.01	13.41	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:5	35.45	2604	2.01	13.4	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:5	35.45	2605	2.02	13.4	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.56	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:5	35.45	2606	2.02	13.41	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.53	14.9	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:33:5	35.45	2607	2.03	13.41	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.49	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:6	34.08	2598	2.03	13.42	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.48	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:6	34.08	2598	2.04	13.4	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.47	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:6	34.08	2608	2.04	13.39	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.45	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:6	34.08	2608	2.05	13.39	107	195	Off Idle	60.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.46	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:6	34.08	2601	2.05	13.38	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.47	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:6	34.08	2599	2.06	13.4	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.38	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:6	34.08	2599	2.06	13.4	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.37	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:7	34.08	2599	2.07	13.41	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.25	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:33:7	34.08	2599	2.07	13.41	107	195	Off Idle	60.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.21	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:33:7	34.08	2604	2.07	13.39	107	195	Off Idle	60.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.23	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:33:7	34.08	2613	2.08	13.41	107	195	Off Idle	60.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.15	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:33:7	34.08	2613	2.09	13.4	107	195	Off Idle	60	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.13	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:33:7	34.08	2620	2.1	13.4	107	195	Off Idle	60	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.09	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:33:8	34.08	2628	2.1	13.42	107	195	Off Idle	60	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.97	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:33:8	34.08	2628	2.11	13.42	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.89	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:33:8	34.08	2630	2.13	13.42	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.72	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:33:8	34.08	2631	2.14	13.44	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.6	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:8	34.08	2631	2.16	13.41	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.46	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:8	34.08	2634	2.17	13.42	107	195	Off Idle	59.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.37	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:9	34.08	2637	2.18	13.41	107	195	Off Idle	59.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.32	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:9	34.08	2634	2.19	13.41	107	195	Off Idle	59.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.25	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:9	34.08	2635	2.2	13.41	107	195	Off Idle	59	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.21	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:33:9	34.08	2630	2.21	13.41	107	195	Off Idle	59	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.1	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:33:9	34.08	2624	2.22	13.4	107	195	Off Idle	59.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.05	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:33:9	34.08	2617	2.24	13.41	107	195	Off Idle	59.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.97	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:33:9	34.08	2615	2.25	13.41	107	195	Off Idle	59.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.92	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:0	34.08	2614	2.26	13.42	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.91	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:0	34.08	2618	2.28	13.43	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.88	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:0	34.08	2623	2.29	13.42	107	195	Off Idle	59	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.84	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:0	34.08	2628	2.29	13.42	107	195	Off Idle	59	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.82	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:0	34.08	2630	2.3	13.43	107	195	Off Idle	59	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.81	15.16	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:0	34.08	2632	2.3	13.42	106	195	Off Idle	59	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.76	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:1	34.08	2634	2.3	13.42	106	195	Off Idle	59	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.76	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:1	34.08	2631	2.3	13.41	106	195	Off Idle	59	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.74	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:1	34.08	2632	2.31	13.39	107	195	Off Idle	59	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.7	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:1	34.08	2658	2.31	13.38	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.7	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:1	34.08	2646	2.31	13.39	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.65	14.82	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:1	34.08	2633	2.32	13.4	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.66	14.76	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:1	34.08	2637	2.32	13.4	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.6	14.69	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:2	34.08	2640	2.32	13.42	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.56	14.68	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:2	34.08	2632	2.32	13.41	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.59	14.68	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:2	34.08	2655	2.33	13.39	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.58	14.7	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:2	34.08	2658	2.33	13.39	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.58	14.72	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:2	34.08	2659	2.33	13.38	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.58	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:2	34.08	2655	2.33	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.56	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:3	34.08	2655	2.33	13.41	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.56	14.78	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:3	34.08	2649	2.34	13.42	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.54	14.78	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:3	34.08	2644	2.34	13.42	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.55	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:3	34.08	2643	2.34	13.41	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.53	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:3	34.08	2633	2.35	13.41	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.52	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:3	34.08	2644	2.35	13.39	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.5	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:4	34.08	2642	2.35	13.39	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.5	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:4	34.08	2642	2.35	13.39	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.51	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:4	34.08	2673	2.35	13.41	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.53	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:4	34.08	2654	2.35	13.4	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.53	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:4	34.08	2657	2.35	13.4	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.57	15.05	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:4	34.08	2661	2.35	13.4	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.51	15.05	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:4	34.08	2661	2.35	13.4	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.52	15.05	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:15:34:5	34.08	2662	2.35	13.41	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.57	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:5	34.08	2658	2.35	13.41	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.6	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:5	34.08	2654	2.34	13.41	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.65	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:5	34.08	2648	2.34	13.41	106	195	Off Idle	58.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.67	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:5	34.08	2652	2.34	13.42	106	195	Off Idle	58.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.67	14.81	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:34:5	34.08	2656	2.33	13.43	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.72	14.8	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:15:34:6	34.08	2656	2.32	13.44	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.81	14.78	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:15:34:6	34.08	2658	2.31	13.42	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.89	14.75	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:34:6	34.08	2665	2.3	13.42	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.97	14.76	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:15:34:6	34.08	2669	2.28	13.41	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.14	14.75	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:15:34:6	34.08	2668	2.26	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.4	14.76	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:34:6	34.08	2668	2.24	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.65	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:15:34:6	34.08	2666	2.22	13.39	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.81	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:34:7	34.08	2667	2.2	13.39	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.93	14.78	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:34:7	34.08	2667	2.18	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.12	14.78	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:15:34:7	34.08	2653	2.15	13.4	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.18	14.8	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:7	34.08	2653	2.13	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.28	14.8	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:7	34.08	2639	2.11	13.41	107	195	Off Idle	57.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.44	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:7	34.08	2647	2.08	13.4	106	195	Off Idle	57.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.57	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:8	34.08	2649	2.06	13.38	106	195	Off Idle	57.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:8	34.08	2656	2.04	13.37	107	195	Off Idle	57.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.78	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:8	34.08	2656	2.03	13.38	107	195	Off Idle	57.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.8	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:8	35.45	2681	2.01	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.83	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:8	35.45	2670	2	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.91	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:8	35.45	2674	1.99	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.94	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:9	35.45	2681	1.99	13.41	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.16	Rich	1	14.6	-7.94	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:9	35.45	2684	1.98	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.99	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:9	35.45	2682	1.97	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:9	35.45	2678	1.96	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.12	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:9	35.45	2673	1.96	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.14	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:34:9	35.45	2671	1.96	13.4	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.14	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:34:9	35.45	2666	1.96	13.4	107	195	Off Idle	57.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.17	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:0	35.45	2664	1.96	13.4	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.18	14.94	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:0	35.45	2659	1.96	13.39	107	195	Off Idle	57	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.2	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:0	35.45	2650	1.96	13.39	107	195	Off Idle	57	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.21	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:0	35.45	2652	1.96	13.39	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.21	15.17	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:0	35.45	2656	1.96	13.39	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.21	15.23	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:0	35.45	2663	1.96	13.4	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.17	15.28	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:1	35.45	2675	1.96	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.17	15.31	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:1	35.45	2675	1.96	13.43	107	195	Off Idle	57	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.19	15.35	1.05	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:1	35.45	2689	1.96	13.42	107	195	Off Idle	57	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.2	15.34	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:1	35.45	2697	1.96	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.18	15.32	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:1	35.45	2697	1.96	13.41	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.18	15.31	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:1	35.45	2700	1.96	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.15	15.27	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:1	35.45	2695	1.96	13.41	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.16	15.24	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:2	35.45	2689	1.96	13.41	107	195	Off Idle	56.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.21	15.21	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:2	35.45	2689	1.95	13.42	107	195	Off Idle	56.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.22	15.18	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:2	35.45	2678	1.96	13.41	107	195	Off Idle	55.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.21	15.14	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:2	35.45	2665	1.96	13.41	107	195	Off Idle	55.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.2	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:2	35.45	2656	1.96	13.42	107	195	Off Idle	55.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.2	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:2	35.45	2653	1.96	13.42	107	195	Off Idle	55.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.16	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:3	35.45	2651	1.96	13.44	107	195	Off Idle	55.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.13	15.13	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:3	35.45	2656	1.96	13.44	107	195	Off Idle	55.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.13	15.13	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:3	35.45	2661	1.96	13.43	107	195	Off Idle	55.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.12	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:3	35.45	2666	1.96	13.43	107	195	Off Idle	55.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.11	15.06	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:3	35.45	2666	1.96	13.41	107	195	Off Idle	56.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.13	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:3	35.45	2672	1.96	13.41	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.13	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:4	35.45	2680	1.96	13.41	107	195	Off Idle	56.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.17	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:4	35.45	2689	1.96	13.4	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.21	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:4	35.45	2698	1.96	13.41	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.24	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:4	35.45	2698	1.96	13.41	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-8.26	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:35:4	35.45	2702	1.96	13.41	107	195	Off Idle	56.3	0	2	132	944 Turbo	0.15	Rich	1	14.6	-8.3	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:4	35.45	2702	1.95	13.41	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.16	Rich	1	14.6	-8.35	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:4	35.45	2692	1.95	13.42	107	195	Off Idle	56	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.37	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:5	35.45	2680	1.95	13.42	107	195	Off Idle	55.9	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.41	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:35:5	35.45	2669	1.94	13.42	107	195	Off Idle	55.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.44	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:35:5	35.45	2666	1.94	13.41	107	195	Off Idle	55.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.48	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:35:5	35.45	2661	1.93	13.4	107	195	Off Idle	55.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.5	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:35:5	35.45	2657	1.93	13.39	107	195	Off Idle	55.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.49	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:35:8	35.45	2648	1.92	13.41	107	195	Off Idle	55.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.51	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:35:6	35.45	2647	1.91	13.4	106	195	Off Idle	55.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.61	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:35:6	35.45	2648	1.9	13.4	106	195	Off Idle	55.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.67	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:6	35.45	2658	1.88	13.39	107	195	Off Idle	56	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.79	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:6	35.45	2664	1.87	13.39	107	195	Off Idle	56.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.91	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:6	35.45	2675	1.86	13.41	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.93	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:6	35.45	2675	1.85	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.97	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:6	35.45	2678	1.84	13.41	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.03	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:7	35.45	2699	1.83	13.41	106	195	Off Idle	57.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.04	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:7	35.45	2699	1.83	13.4	106	195	Off Idle	57.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.07	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:7	35.45	2680	1.82	13.4	106	195	Off Idle	57.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.15	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:7	35.45	2674	1.81	13.4	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.16	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:7	35.45	2667	1.8	13.41	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.19	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:7	35.45	2664	1.8	13.42	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.21	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:8	35.45	2668	1.79	13.43	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.21	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:8	35.45	2668	1.79	13.41	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.23	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:35:8	35.45	2666	1.79	13.41	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.25	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:8	35.45	2662	1.79	13.4	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.25	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:8	35.45	2665	1.79	13.38	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.24	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:8	35.45	2665	1.78	13.4	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.23	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:9	35.45	2670	1.78	13.39	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.2	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:9	35.45	2672	1.78	13.4	107	195	Off Idle	56.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.19	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:9	35.45	2673	1.78	13.4	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.19	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:9	35.45	2677	1.78	13.43	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.21	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:9	35.45	2682	1.78	13.42	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.19	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:9	35.45	2682	1.78	13.42	107	195	Off Idle	56.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.23	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:35:9	35.45	2689	1.78	13.41	107	195	Off Idle	56.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.22	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:0	35.45	2695	1.79	13.4	107	195	Off Idle	56.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.22	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:0	35.45	2694	1.79	13.37	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.23	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:0	35.45	2694	1.79	13.38	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.23	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:0	35.45	2690	1.79	13.39	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.28	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:0	35.45	2678	1.79	13.42	107	195	Off Idle	56.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.25	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:0	35.45	2669	1.79	13.42	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.26	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:1	35.45	2664	1.79	13.41	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.25	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:1	35.45	2661	1.79	13.41	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.21	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:1	35.45	2653	1.79	13.4	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.21	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:1	35.45	2658	1.79	13.41	107	195	Off Idle	56.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.21	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:1	35.45	2658	1.79	13.42	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.24	15.15	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:1	35.45	2661	1.79	13.41	107	195	Off Idle	56.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.25	15.17	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:1	35.45	2666	1.79	13.41	107	195	Off Idle	56.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.29	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:2	35.45	2659	1.79	13.4	107	195	Off Idle	56.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.28	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:2	35.45	2663	1.79	13.4	107	195	Off Idle	56.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.29	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:2	35.45	2663	1.79	13.39	107	195	Off Idle	56.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.31	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:2	35.45	2669	1.79	13.41	107	195	Off Idle	56.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.28	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:2	35.45	2670	1.79	13.41	107	195	Off Idle	56.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.3	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:2	35.45	2674	1.79	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.29	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:3	35.45	2670	1.78	13.42	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.28	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:3	35.45	2672	1.78	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.28	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:3	35.45	2676	1.78	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.28	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:3	35.45	2676	1.78	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.31	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:3	35.45	2684	1.78	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.29	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:3	35.45	2682	1.78	13.42	107	195	Off Idle	57	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.28	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:4	35.45	2682	1.78	13.39	107	195	Off Idle	57	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.26	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:4	35.45	2684	1.78	13.39	107	195	Off Idle	56.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.28	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:4	35.45	2678	1.78	13.39	107	195	Off Idle	56.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.3	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:4	35.45	2680	1.78	13.37	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.32	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:4	35.45	2680	1.78	13.4	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.31	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:4	35.45	2678	1.78	13.41	107	195	Off Idle	56.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.29	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:36:4	35.45	2653	1.78	13.42	107	195	Off Idle	56.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.29	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:5	35.45	2662	1.78	13.41	107	195	Off Idle	56.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.3	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:5	35.45	2658	1.78	13.41	107	195	Off Idle	56.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.29	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:5	35.45	2653	1.78	13.41	107	195	Off Idle	56.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.3	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:5	35.45	2626	1.78	13.41	107	195	Off Idle	56.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.29	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:36:5	35.45	2646	1.78	13.42	107	195	Off Idle	56.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.29	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:5	35.45	2646	1.78	13.43	107	195	Off Idle	56.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.3	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:6	35.45	2650	1.78	13.43	107	195	Off Idle	56.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.29	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:6	35.45	2655	1.78	13.42	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.35	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:6	35.45	2657	1.78	13.42	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.34	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:6	35.45	2662	1.77	13.42	107	195	Off Idle	57.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.35	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:6	35.45	2662	1.77	13.41	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.36	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:6	35.45	2683	1.77	13.41	106	195	Off Idle	57.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.36	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:6	35.45	2659	1.77	13.41	106	195	Off Idle	57.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.37	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:7	35.45	2658	1.76	13.4	106	195	Off Idle	58	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.38	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:7	35.45	2658	1.76	13.42	107	195	Off Idle	58	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.45	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:7	35.45	2655	1.76	13.41	107	195	Off Idle	58	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.47	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:7	35.45	2658	1.76	13.41	107	195	Off Idle	58	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.47	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:7	35.45	2664	1.75	13.41	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.48	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:7	35.45	2664	1.75	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.46	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:8	35.45	2666	1.74	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.46	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:8	35.45	2670	1.74	13.39	107	195	Off Idle	57.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.46	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:8	35.45	2669	1.74	13.39	107	195	Off Idle	57.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.48	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:8	35.45	2669	1.74	13.4	107	195	Off Idle	57.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.53	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:8	35.45	2667	1.73	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.5	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:8	35.45	2664	1.73	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.49	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:36:9	35.45	2663	1.73	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.49	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:36:9	35.45	2660	1.73	13.42	107	195	Off Idle	57	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.48	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:36:9	35.45	2660	1.73	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.5	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:36:9	35.45	2659	1.73	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.51	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:36:9	35.45	2658	1.73	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.54	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:36:9	35.45	2661	1.73	13.4	107	195	Off Idle	57	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.54	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:36:9	35.45	2660	1.73	13.4	107	195	Off Idle	57	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.53	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:0	35.45	2658	1.73	13.41	107	195	Off Idle	57	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.56	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:0	35.45	2656	1.73	13.42	107	195	Off Idle	57	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.56	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:0	35.45	2654	1.72	13.42	107	195	Off Idle	57	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.58	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:0	35.45	2644	1.72	13.41	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.61	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:0	35.45	2637	1.72	13.43	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.6	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:0	35.45	2637	1.72	13.41	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.63	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:1	35.45	2648	1.72	13.42	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.6	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:1	35.45	2646	1.72	13.42	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.6	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:1	35.45	2644	1.72	13.41	107	195	Off Idle	56.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.6	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:1	35.45	2646	1.72	13.41	107	195	Off Idle	57.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.58	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:1	35.45	2654	1.71	13.41	107	195	Off Idle	57.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.56	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:1	35.45	2657	1.71	13.41	106	195	Off Idle	57.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.57	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:1	35.45	2658	1.71	13.42	106	195	Off Idle	57.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:2	35.45	2660	1.71	13.41	106	195	Off Idle	57.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:2	35.45	2656	1.71	13.42	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.57	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:2	35.45	2656	1.71	13.43	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.15	Rich	1	14.6	-9.59	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:2	35.45	2656	1.71	13.42	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.6	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:2	35.45	2656	1.71	13.41	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.62	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:2	35.45	2650	1.71	13.42	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.64	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:3	35.45	2649	1.71	13.42	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.64	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:3	35.45	2642	1.71	13.41	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.66	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:3	35.45	2642	1.71	13.42	107	195	Off Idle	58	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.66	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:3	35.45	2642	1.7	13.42	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.63	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:3	35.45	2642	1.7	13.42	107	195	Off Idle	58	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.6	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:3	35.45	2634	1.7	13.43	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.62	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:37:4	35.45	2644	1.7	13.42	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.62	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:4	35.45	2643	1.7	13.41	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.6	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:4	35.45	2644	1.7	13.42	107	195	Off Idle	57.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.62	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:4	35.45	2641	1.7	13.42	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.65	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:37:4	35.45	2641	1.7	13.41	107	195	Off Idle	57.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.62	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:4	35.45	2641	1.7	13.41	106	195	Off Idle	58.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.64	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:4	35.45	2643	1.7	13.41	106	195	Off Idle	58.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.62	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:5	35.45	2643	1.7	13.41	106	195	Off Idle	58.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.62	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:5	35.45	2646	1.7	13.41	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.63	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:5	35.45	2646	1.7	13.41	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.61	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:5	35.45	2651	1.7	13.4	107	195	Off Idle	57.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.59	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:5	35.45	2651	1.71	13.4	107	195	Off Idle	57.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.58	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:5	35.45	2652	1.71	13.39	107	195	Off Idle	57.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.54	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:6	35.45	2653	1.71	13.39	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.54	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:6	35.45	2653	1.72	13.39	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.52	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:6	35.45	2651	1.72	13.38	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.46	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:6	35.45	2647	1.73	13.4	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.43	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:6	35.45	2652	1.73	13.41	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.43	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:6	35.45	2656	1.74	13.42	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.41	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:6	35.45	2660	1.74	13.42	106	195	Off Idle	57.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.38	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:7	35.45	2660	1.74	13.43	106	195	Off Idle	57.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.37	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:7	35.45	2659	1.75	13.43	107	195	Off Idle	57.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.35	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:7	35.45	2654	1.75	13.42	107	195	Off Idle	57.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.35	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:7	35.45	2652	1.75	13.41	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.36	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:7	35.45	2648	1.76	13.41	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.35	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:7	35.45	2646	1.76	13.39	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.35	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:8	35.45	2637	1.76	13.41	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.32	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:8	35.45	2637	1.77	13.41	107	195	Off Idle	57.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.33	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:8	35.45	2633	1.77	13.4	107	195	Off Idle	57.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.3	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:8	35.45	2628	1.77	13.4	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.31	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:8	35.45	2629	1.78	13.41	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.31	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:8	35.45	2630	1.78	13.41	107	195	Off Idle	58.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.33	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:9	35.45	2632	1.78	13.41	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.32	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:9	35.45	2635	1.78	13.4	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.3	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:9	35.45	2645	1.78	13.4	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.31	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:9	35.45	2633	1.77	13.4	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.28	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:9	35.45	2631	1.77	13.4	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.28	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:37:9	35.45	2633	1.77	13.4	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.29	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:37:9	35.45	2633	1.77	13.4	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.25	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:0	35.45	2633	1.77	13.42	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.27	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:0	35.45	2638	1.77	13.4	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.27	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:0	35.45	2638	1.77	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.25	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:0	35.45	2637	1.77	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.29	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:0	35.45	2637	1.77	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.29	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:0	35.45	2638	1.77	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.3	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:1	35.45	2638	1.77	13.42	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.3	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:1	35.45	2638	1.77	13.43	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.31	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:1	35.45	2638	1.77	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.3	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:1	35.45	2638	1.77	13.41	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.19	Rich	1	14.6	-9.29	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:1	35.45	2638	1.77	13.42	106	195	Off Idle	58.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.28	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:1	35.45	2637	1.77	13.41	106	195	Off Idle	58.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.31	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:1	35.45	2638	1.77	13.41	106	195	Off Idle	58.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.28	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:2	35.45	2635	1.77	13.4	107	195	Off Idle	58.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.27	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:2	35.45	2636	1.77	13.4	107	195	Off Idle	58.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.26	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:2	35.45	2636	1.77	13.41	107	195	Off Idle	58.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.3	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:2	35.45	2657	1.77	13.41	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.29	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:2	35.45	2630	1.77	13.41	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.28	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:2	35.45	2624	1.77	13.42	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.29	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:38:3	35.45	2624	1.77	13.42	106	195	Off Idle	58.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.31	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:3	35.45	2626	1.77	13.43	106	195	Off Idle	58.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.3	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:3	35.45	2624	1.77	13.42	106	195	Off Idle	58.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.28	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:3	35.45	2623	1.77	13.42	107	195	Off Idle	58.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.29	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:3	35.45	2612	1.77	13.43	107	195	Off Idle	58.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.31	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:3	35.45	2624	1.77	13.42	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.32	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:4	35.45	2623	1.77	13.4	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.31	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:4	35.45	2625	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.29	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:4	35.45	2629	1.77	13.4	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.31	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:4	35.45	2631	1.77	13.4	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.3	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:4	35.45	2631	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.3	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:4	35.45	2634	1.77	13.41	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.3	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:4	35.45	2636	1.77	13.4	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.29	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:5	35.45	2636	1.77	13.41	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.3	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:5	35.45	2635	1.77	13.41	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.29	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:5	35.45	2630	1.77	13.41	107	195	Off Idle	58.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.28	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:5	35.45	2629	1.77	13.43	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.29	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:5	35.45	2628	1.77	13.43	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.27	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:5	35.45	2628	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.27	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:6	35.45	2630	1.77	13.42	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.28	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:6	35.45	2633	1.77	13.43	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.32	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:6	35.45	2634	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.29	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:6	35.45	2640	1.77	13.42	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.28	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:6	35.45	2641	1.77	13.43	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.3	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:6	35.45	2640	1.77	13.43	107	195	Off Idle	58.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.29	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:6	35.45	2636	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.25	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:7	35.45	2632	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.25	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:7	35.45	2624	1.77	13.42	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.27	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:7	35.45	2624	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.29	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:7	35.45	2619	1.77	13.4	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.27	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:7	35.45	2614	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.27	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:7	35.45	2612	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.27	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:8	35.45	2613	1.77	13.41	107	195	Off Idle	58.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.25	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:8	35.45	2612	1.77	13.41	107	195	Off Idle	59	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.26	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:8	35.45	2613	1.77	13.4	107	195	Off Idle	59.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.27	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:8	35.45	2613	1.77	13.41	107	195	Off Idle	59.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.26	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:8	35.45	2619	1.77	13.4	107	195	Off Idle	59.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.26	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:8	35.45	2618	1.77	13.41	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.29	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:9	35.45	2619	1.77	13.39	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.22	Rich	1	14.6	-9.3	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:9	35.45	2624	1.77	13.39	107	195	Off Idle	59.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.31	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:38:9	35.45	2623	1.77	13.4	107	195	Off Idle	60	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.29	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:9	35.45	2631	1.77	13.4	107	195	Off Idle	60	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.27	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:9	35.45	2633	1.77	13.41	107	195	Off Idle	60	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.26	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:9	35.45	2633	1.77	13.41	107	195	Off Idle	60	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.23	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:38:9	35.45	2636	1.77	13.41	106	195	Off Idle	59.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.25	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:39:0	35.45	2628	1.77	13.4	106	195	Off Idle	59.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.26	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:39:0	35.45	2626	1.77	13.4	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.26	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:39:0	35.45	2622	1.77	13.42	107	195	Off Idle	59.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.29	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:39:0	35.45	2619	1.76	13.42	107	195	Off Idle	59	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.3	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:39:0	35.45	2612	1.76	13.42	107	195	Off Idle	59	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.3	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:39:0	35.45	2615	1.76	13.44	107	195	Off Idle	59	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.35	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:39:1	35.45	2617	1.76	13.42	107	195	Off Idle	59	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.38	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:39:1	35.45	2617	1.75	13.41	107	195	Off Idle	59	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.39	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:39:1	35.45	2618	1.73	13.42	107	195	Off Idle	59	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.48	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:39:1	35.45	2616	1.72	13.42	107	195	Full Load	59	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.53	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:15:39:1	35.45	2615	1.7	13.44	107	195	Idle	59	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.62	15.11	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:1	35.45	2614	1.67	13.43	107	195	Idle	59.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.79	15.1	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:1	35.45	2612	1.65	13.4	107	195	Idle	59.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.99	15.09	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:39:2	35.45	2598	1.64	13.39	107	195	Idle	59.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.12	15.09	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:15:39:2	35.45	2590	1.62	13.4	107	195	Idle	59.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.19	14.92	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:39:2	35.45	2585	1.6	13.41	107	195	Idle	59.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.22	14.91	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:39:2	35.45	2566	1.58	13.42	106	195	Idle	59.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.23	14.9	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:39:2	35.45	2548	1.56	13.41	106	195	Idle	59	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.28	14.89	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:39:2	35.45	2514	1.53	13.4	106	195	Idle	58.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.32	14.87	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:39:3	35.45	2536	1.5	13.39	106	195	Idle	58.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.35	14.86	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:39:3	32.72	2521	1.49	13.39	106	195	Idle	58.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.36	14.85	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:39:3	27.27	2513	1.47	13.4	107	195	Idle	57.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.34	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:15:39:3	27.27	2531	1.45	13.4	107	195	Idle	57	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.31	14.95	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:3	21.81	2549	1.44	13.4	107	195	Idle	56.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.32	14.91	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:3	19.09	2600	1.43	13.41	107	195	Idle	56.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.31	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:4	19.09	2645	1.43	13.41	107	195	Idle	56.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.33	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:4	19.09	2638	1.44	13.43	107	195	Idle	56.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-10.33	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:4	19.09	2638	1.44	13.44	107	195	Idle	56.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-10.32	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:4	19.09	2620	1.44	13.43	107	195	Idle	56.7	0	2	132	944 Turbo	0.19	Rich	1	14.6	-10.35	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:4	19.09	2632	1.45	13.44	107	195	Idle	56.7	0	2	132	944 Turbo	0.08	Rich	1	14.6	-10.34	14.82	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:4	19.09	2618	1.44	13.44	107	195	Idle	57.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.34	14.8	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:4	19.09	2567	1.44	13.44	107	195	Idle	57.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.36	14.78	1.01	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:5	19.09	2572	1.44	13.44	107	195	Idle	57.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.36	14.77	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:5	19.09	2570	1.45	13.45	107	195	Idle	58.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.38	14.76	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:5	19.09	2567	1.45	13.44	107	195	Idle	58.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.36	14.76	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:5	19.09	2567	1.45	13.44	107	195	Idle	58.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.33	14.75	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:5	19.09	2569	1.45	13.44	107	195	Idle	59.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.3	14.75	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:5	19.09	2574	1.45	13.44	107	195	Idle	59.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.29	14.74	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:6	19.09	2563	1.45	13.44	107	195	Idle	59.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.28	14.72	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:6	19.09	2563	1.45	13.43	107	195	Idle	59.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.26	14.74	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:6	19.09	2588	1.44	13.42	107	195	Idle	59.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.23	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:6	19.09	2610	1.44	13.41	107	195	Idle	59.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.25	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:6	19.09	2600	1.44	13.4	107	195	Idle	59.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.25	14.98	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:6	19.09	2585	1.43	13.41	107	195	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:6	19.09	2577	1.43	13.4	107	195	Idle	59.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	15.18	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:7	19.09	2570	1.43	13.41	107	195	Idle	59.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	15.29	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:7	19.09	2558	1.43	13.41	107	195	Idle	59.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	15.43	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:7	19.09	2561	1.42	13.42	107	195	Idle	59.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	15.67	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:7	19.09	2555	1.42	13.42	107	195	Idle	60.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	15.82	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:7	19.09	2556	1.42	13.42	107	195	Idle	60.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	16.07	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:7	19.09	2559	1.42	13.41	107	195	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	16.27	1.11	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:8	19.09	2560	1.42	13.41	107	195	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	16.54	1.13	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:8	19.09	2564	1.41	13.42	107	195	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	16.9	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:8	19.09	2566	1.41	13.41	107	195	Idle	60.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	17.31	1.18	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:8	19.09	2569	1.41	13.41	107	195	Idle	60.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	17.94	1.22	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:8	19.09	2569	1.41	13.42	107	195	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	18.34	1.25	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:8	19.09	2579	1.41	13.41	107	195	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	18.74	1.28	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:9	19.09	2579	1.41	13.42	107	195	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	18.93	1.29	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:9	19.09	2566	1.4	13.41	107	195	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	19.63	1.34	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:9	19.09	2566	1.4	13.41	107	195	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	19.92	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:9	19.09	2563	1.4	13.41	106	195	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.11	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:9	19.09	2559	1.4	13.42	106	195	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:9	19.09	2559	1.4	13.42	106	195	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:39:9	19.09	2554	1.39	13.41	107	195	Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:0	19.09	2550	1.39	13.41	107	195	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:0	19.09	2550	1.39	13.41	107	195	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:0	19.09	2546	1.39	13.42	107	195	Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:0	19.09	2542	1.39	13.41	107	195	Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:0	19.09	2542	1.39	13.41	106	195	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:0	19.09	2540	1.39	13.4	106	195	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:1	19.09	2537	1.39	13.41	106	195	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:40:1	19.09	2537	1.39	13.41	107	195	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:1	19.09	2536	1.38	13.41	107	195	Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:1	19.09	2524	1.38	13.41	107	195	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:1	19.09	2545	1.38	13.41	107	195	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:1	19.09	2539	1.38	13.42	107	195	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:1	19.09	2534	1.38	13.41	107	195	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:2	19.09	2534	1.38	13.43	107	195	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:2	19.09	2534	1.38	13.43	107	195	Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:2	19.09	2532	1.38	13.43	107	195	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:2	19.09	2532	1.38	13.44	107	195	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:2	19.09	2531	1.38	13.43	107	195	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:2	19.09	2530	1.38	13.41	107	195	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:3	19.09	2530	1.38	13.41	107	195	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:3	19.09	2529	1.38	13.42	107	195	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:3	19.09	2529	1.37	13.41	106	195	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:3	19.09	2526	1.37	13.41	106	195	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:3	19.09	2524	1.37	13.41	106	195	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:3	19.09	2524	1.37	13.41	107	195	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:4	19.09	2532	1.37	13.41	107	195	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:4	19.09	2520	1.37	13.41	107	195	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:4	19.09	2518	1.37	13.41	107	195	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:4	19.09	2508	1.37	13.41	107	195	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:4	19.09	2515	1.36	13.42	107	195	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:4	19.09	2513	1.36	13.42	107	195	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:4	19.09	2514	1.36	13.43	107	195	Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:5	19.09	2513	1.36	13.44	106	195	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:5	19.09	2511	1.36	13.43	106	195	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:5	19.09	2511	1.36	13.43	106	195	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:5	19.09	2506	1.35	13.42	107	195	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:5	19.09	2504	1.35	13.42	107	195	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:5	19.09	2504	1.35	13.41	107	195	Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:6	19.09	2500	1.35	13.43	107	195	Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:6	19.09	2500	1.35	13.41	107	195	Idle	64.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:6	19.09	2500	1.35	13.42	107	195	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:6	19.09	2499	1.35	13.41	107	195	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:6	19.09	2499	1.35	13.42	107	195	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:6	19.09	2499	1.34	13.41	107	195	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:6	19.09	2498	1.34	13.41	107	195	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:7	19.09	2497	1.34	13.41	107	195	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:7	19.09	2498	1.34	13.43	107	195	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:7	19.09	2496	1.34	13.42	107	195	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:7	19.09	2493	1.34	13.42	107	195	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:7	19.09	2492	1.34	13.41	107	195	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:7	19.09	2490	1.33	13.42	107	195	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:8	19.09	2490	1.33	13.42	107	195	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:8	19.09	2488	1.33	13.41	107	195	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:8	19.09	2487	1.33	13.41	107	195	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:8	19.09	2486	1.33	13.41	107	195	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:8	19.09	2485	1.33	13.41	106	195	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:8	19.09	2483	1.32	13.41	106	195	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:9	19.09	2480	1.32	13.41	106	195	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:9	19.09	2480	1.32	13.42	106	195	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:9	19.09	2476	1.32	13.42	106	195	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:9	19.09	2475	1.32	13.42	106	195	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:9	19.09	2474	1.32	13.43	107	195	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:9	19.09	2469	1.32	13.41	107	195	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:40:9	19.09	2467	1.32	13.42	106	195	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:0	19.09	2466	1.31	13.42	106	195	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:41:0	19.09	2466	1.31	13.41	106	195	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:0	19.09	2466	1.31	13.41	107	195	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:0	19.09	2465	1.31	13.41	107	195	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:0	19.09	2454	1.31	13.4	107	195	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:0	19.09	2463	1.3	13.4	107	195	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:1	19.09	2472	1.3	13.41	107	195	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:1	19.09	2460	1.3	13.42	107	195	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:1	19.09	2460	1.3	13.42	107	195	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:1	19.09	2456	1.3	13.42	107	195	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:1	19.09	2456	1.3	13.42	107	195	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:1	19.09	2452	1.29	13.41	107	195	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:1	19.09	2448	1.29	13.42	107	195	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:2	19.09	2446	1.29	13.42	106	195	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:2	19.09	2434	1.29	13.42	106	195	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:2	19.09	2441	1.28	13.41	106	195	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:2	19.09	2442	1.28	13.41	107	195	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:2	17.72	2442	1.28	13.41	107	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:2	17.72	2433	1.28	13.4	107	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:3	17.72	2443	1.28	13.41	107	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:3	17.72	2444	1.28	13.41	107	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:3	17.72	2444	1.27	13.41	107	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:3	17.72	2442	1.27	13.41	107	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:3	17.72	2441	1.27	13.41	107	195	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:3	17.72	2437	1.27	13.43	107	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:4	17.72	2436	1.27	13.42	106	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:4	17.72	2432	1.27	13.42	106	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:4	17.72	2429	1.26	13.43	107	195	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:4	17.72	2429	1.26	13.43	107	195	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:4	17.72	2419	1.26	13.42	107	195	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:4	17.72	2429	1.26	13.42	107	195	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:4	17.72	2425	1.25	13.43	107	195	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:5	17.72	2412	1.25	13.42	107	195	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:5	17.72	2422	1.25	13.41	107	195	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:5	17.72	2443	1.25	13.43	107	195	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:5	17.72	2433	1.25	13.43	107	195	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:5	17.72	2428	1.24	13.42	107	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:6	17.72	2428	1.24	13.43	107	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:6	17.72	2431	1.24	13.42	107	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:6	17.72	2430	1.24	13.42	107	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:6	17.72	2427	1.24	13.42	107	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:6	17.72	2423	1.23	13.42	107	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:6	17.72	2423	1.23	13.4	107	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:6	17.72	2416	1.23	13.42	107	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:6	17.72	2414	1.23	13.41	107	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:7	17.72	2408	1.23	13.41	107	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:7	17.72	2383	1.22	13.42	107	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:7	17.72	2400	1.22	13.41	107	195	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:7	17.72	2398	1.22	13.41	107	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:7	17.72	2397	1.22	13.42	107	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:7	17.72	2399	1.22	13.42	107	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:8	17.72	2402	1.22	13.42	107	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:8	17.72	2402	1.22	13.42	107	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:8	17.72	2405	1.22	13.42	106	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:8	17.72	2406	1.21	13.42	106	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:8	17.72	2406	1.21	13.42	106	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:8	17.72	2405	1.21	13.43	106	195	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:9	17.72	2403	1.21	13.42	106	195	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:9	17.72	2400	1.21	13.42	106	195	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:41:9	17.72	2400	1.21	13.43	107	195	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:9	17.72	2406	1.21	13.42	107	195	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:9	17.72	2394	1.21	13.42	107	195	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:9	17.72	2392	1.21	13.43	107	195	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:41:9	17.72	2370	1.21	13.41	107	195	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:0	17.72	2386	1.21	13.4	107	195	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:0	17.72	2383	1.2	13.42	107	195	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:0	17.72	2384	1.2	13.42	107	195	Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:0	17.72	2381	1.2	13.42	107	195	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:0	17.72	2382	1.2	13.42	107	195	Idle	71.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:0	17.72	2382	1.2	13.42	107	195	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:1	17.72	2382	1.2	13.43	107	195	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:1	17.72	2382	1.2	13.42	107	195	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:1	17.72	2381	1.2	13.42	107	195	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:1	17.72	2380	1.19	13.42	107	195	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:1	17.72	2380	1.19	13.42	107	195	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:1	17.72	2378	1.19	13.42	107	195	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:1	17.72	2373	1.19	13.42	106	195	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:2	17.72	2373	1.19	13.43	106	195	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:2	17.72	2371	1.19	13.43	106	195	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:2	17.72	2369	1.18	13.42	107	195	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:2	17.72	2366	1.18	13.4	107	195	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:2	17.72	2367	1.18	13.41	107	195	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:2	17.72	2364	1.18	13.41	107	195	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:3	17.72	2363	1.18	13.42	107	195	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:3	17.72	2363	1.18	13.42	107	195	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:3	17.72	2364	1.18	13.43	107	195	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:3	17.72	2363	1.18	13.42	107	195	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:3	17.72	2363	1.17	13.41	107	195	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:3	17.72	2363	1.17	13.41	107	195	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:4	17.72	2360	1.17	13.41	107	195	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:4	17.72	2360	1.17	13.42	107	195	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:4	17.72	2358	1.17	13.41	107	195	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:4	17.72	2355	1.17	13.37	107	195	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:4	17.72	2351	1.17	13.36	107	195	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:4	17.72	2351	1.17	13.35	107	195	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:4	17.72	2346	1.17	13.34	107	195	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:5	17.72	2343	1.16	13.35	107	195	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:5	17.72	2341	1.16	13.35	107	195	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:5	17.72	2340	1.16	13.36	107	195	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:5	17.72	2342	1.16	13.38	107	195	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:5	17.72	2342	1.16	13.37	107	195	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:5	17.72	2345	1.16	13.36	107	195	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:6	17.72	2346	1.16	13.38	107	195	Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:6	17.72	2346	1.16	13.37	107	195	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:6	17.72	2347	1.16	13.36	107	195	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:6	17.72	2343	1.16	13.36	107	195	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:6	17.72	2344	1.16	13.37	107	195	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:6	17.72	2340	1.15	13.37	107	195	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:6	17.72	2328	1.15	13.38	106	195	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:7	17.72	2332	1.15	13.4	106	195	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:7	17.72	2330	1.15	13.39	106	195	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:7	17.72	2325	1.15	13.39	106	195	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:7	17.72	2324	1.15	13.39	106	195	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:7	17.72	2322	1.15	13.39	106	195	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:7	17.72	2320	1.15	13.39	107	195	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:8	17.72	2322	1.14	13.38	107	195	Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:8	17.72	2322	1.14	13.39	107	195	Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:42:8	17.72	2324	1.14	13.37	106	195	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:8	17.72	2324	1.14	13.36	106	195	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:8	17.72	2325	1.14	13.37	107	195	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:8	17.72	2325	1.14	13.38	107	195	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:9	17.72	2322	1.14	13.38	107	195	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:9	17.72	2323	1.14	13.39	107	195	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:9	17.72	2322	1.13	13.41	107	195	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:9	17.72	2318	1.13	13.41	107	195	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:9	17.72	2313	1.13	13.42	107	195	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:9	17.72	2309	1.13	13.41	107	195	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:42:9	17.72	2309	1.13	13.41	107	195	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:0	17.72	2308	1.13	13.41	106	195	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:0	17.72	2308	1.13	13.41	106	195	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:0	17.72	2307	1.13	13.41	107	195	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:0	17.72	2306	1.13	13.42	107	195	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:0	17.72	2307	1.13	13.42	107	195	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:0	17.72	2308	1.12	13.42	107	195	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:1	17.72	2308	1.12	13.41	107	195	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:1	17.72	2310	1.12	13.41	107	195	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:1	17.72	2309	1.12	13.42	106	195	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:1	17.72	2307	1.12	13.41	106	195	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:1	17.72	2303	1.12	13.41	106	195	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:1	17.72	2303	1.12	13.42	106	195	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:1	17.72	2299	1.12	13.4	107	195	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:2	17.72	2295	1.11	13.41	107	195	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:2	17.72	2290	1.11	13.42	106	195	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:2	17.72	2290	1.11	13.41	106	195	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:2	17.72	2286	1.11	13.4	106	195	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:2	17.72	2285	1.11	13.39	107	195	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:2	17.72	2284	1.11	13.37	107	195	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:3	17.72	2284	1.11	13.35	107	195	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:3	17.72	2284	1.11	13.37	106	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:3	17.72	2284	1.1	13.37	106	195	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:3	17.72	2285	1.1	13.36	106	195	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:3	17.72	2284	1.1	13.38	106	195	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:3	17.72	2284	1.1	13.38	106	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:4	17.72	2290	1.1	13.38	107	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:4	17.72	2284	1.1	13.38	107	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:4	17.72	2283	1.1	13.38	107	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:4	17.72	2283	1.1	13.39	107	195	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:4	17.72	2278	1.1	13.39	107	195	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:4	17.72	2276	1.1	13.39	107	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:4	17.72	2272	1.1	13.39	107	195	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:5	17.72	2272	1.1	13.39	107	195	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.13	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:5	17.72	2268	1.1	13.39	107	195	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.13	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:5	17.72	2266	1.1	13.39	107	195	Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.13	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:5	17.72	2266	1.09	13.39	107	195	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.13	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:5	17.72	2263	1.09	13.41	107	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.13	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:5	17.72	2242	1.09	13.41	107	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.13	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:6	17.72	2261	1.09	13.41	106	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.13	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:6	17.72	2261	1.09	13.4	106	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.13	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:6	17.72	2261	1.09	13.39	106	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.13	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:6	17.72	2262	1.09	13.38	107	195	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:6	17.72	2263	1.09	13.39	107	195	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:6	17.72	2263	1.09	13.39	107	195	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:6	17.72	2264	1.08	13.39	107	195	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:7	17.72	2273	1.08	13.4	107	195	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:7	17.72	2264	1.08	13.39	107	195	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:43:7	17.72	2264	1.08	13.39	107	195	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:7	17.72	2262	1.08	13.4	107	195	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:7	17.72	2262	1.08	13.41	107	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:7	17.72	2263	1.08	13.41	107	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:8	17.72	2262	1.08	13.41	107	195	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:8	17.72	2258	1.07	13.4	107	195	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:8	17.72	2255	1.07	13.41	107	195	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:8	17.72	2254	1.07	13.41	107	195	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:8	17.72	2246	1.07	13.43	107	195	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:8	17.72	2240	1.07	13.44	107	195	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:9	17.72	2238	1.07	13.44	107	195	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:9	17.72	2234	1.07	13.44	107	195	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:9	17.72	2232	1.07	13.44	107	195	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:9	17.72	2222	1.06	13.43	107	195	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:9	17.72	2229	1.06	13.42	107	195	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:9	17.72	2231	1.06	13.42	107	195	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:43:9	17.72	2231	1.06	13.43	107	195	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:0	17.72	2230	1.06	13.43	107	195	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:0	17.72	2234	1.06	13.44	107	195	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:0	17.72	2234	1.06	13.45	107	195	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:0	17.72	2234	1.06	13.43	107	195	Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:0	17.72	2234	1.06	13.41	107	195	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:0	17.72	2233	1.06	13.38	107	195	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:1	17.72	2232	1.06	13.37	107	195	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:1	17.72	2230	1.06	13.37	107	195	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:1	17.72	2226	1.06	13.37	107	195	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:1	17.72	2226	1.05	13.38	107	195	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:1	17.72	2222	1.05	13.39	107	195	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:1	17.72	2220	1.05	13.38	107	195	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:1	17.72	2220	1.05	13.38	107	195	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:2	17.72	2218	1.05	13.36	107	195	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:2	17.72	2219	1.05	13.37	107	195	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:2	17.72	2221	1.05	13.35	107	195	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:2	17.72	2221	1.05	13.35	107	195	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:2	17.72	2224	1.04	13.34	107	195	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:2	17.72	2222	1.04	13.34	107	195	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:3	17.72	2222	1.04	13.33	107	195	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:3	17.72	2219	1.04	13.34	107	195	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:3	17.72	2216	1.04	13.35	107	195	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:3	17.72	2216	1.04	13.38	107	195	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:3	17.72	2204	1.04	13.39	107	195	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:3	17.72	2208	1.04	13.4	107	195	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:4	17.72	2206	1.03	13.4	107	195	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:4	17.72	2200	1.03	13.4	107	195	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:4	17.72	2197	1.03	13.38	107	195	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:4	17.72	2196	1.03	13.37	107	195	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:4	17.72	2196	1.03	13.36	107	195	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:4	17.72	2197	1.03	13.35	107	195	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:4	17.72	2198	1.03	13.35	107	195	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:5	17.72	2200	1.03	13.36	107	195	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:5	17.72	2200	1.02	13.35	107	195	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:5	17.72	2200	1.02	13.37	107	195	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:5	17.72	2200	1.02	13.39	107	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:5	17.72	2200	1.02	13.41	107	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:5	17.72	2199	1.02	13.42	107	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:6	17.72	2196	1.02	13.42	107	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:6	17.72	2192	1.02	13.42	107	195	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:6	17.72	2188	1.02	13.41	107	195	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:44:6	17.72	2187	1.02	13.41	107	195	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:6	17.72	2186	1.02	13.4	107	195	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:6	17.72	2184	1.01	13.4	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:6	17.72	2184	1.01	13.4	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:7	17.72	2183	1.01	13.4	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:7	17.72	2182	1.01	13.39	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:7	17.72	2182	1.01	13.39	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:7	17.72	2182	1.01	13.39	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:7	17.72	2182	1.01	13.4	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:7	17.72	2180	1.01	13.41	106	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:8	17.72	2180	1.01	13.43	106	195	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:8	17.72	2178	1.01	13.43	106	195	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:8	17.72	2178	1.01	13.42	107	195	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:8	17.72	2175	1.01	13.42	107	195	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:8	17.72	2176	1.01	13.41	107	195	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:8	17.72	2175	1	13.39	107	195	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:9	17.72	2173	1	13.37	107	195	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:9	17.72	2172	1	13.36	107	195	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:9	17.72	2171	1	13.36	107	195	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:9	17.72	2170	1	13.35	107	195	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:9	17.72	2170	1	13.36	107	195	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:9	17.72	2167	1	13.36	107	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:44:9	17.72	2166	1	13.37	107	195	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:0	17.72	2164	1	13.37	107	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:0	17.72	2160	1	13.38	107	195	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:0	17.72	2160	1	13.38	107	195	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:0	17.72	2159	1	13.39	107	195	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:0	17.72	2159	1	13.39	107	195	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:0	17.72	2156	1	13.39	107	195	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:1	17.72	2153	1	13.38	106	195	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:1	17.72	2152	1	13.37	106	195	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:1	17.72	2152	1	13.36	106	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:1	17.72	2150	1	13.34	107	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:1	17.72	2150	1	13.35	107	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:1	17.72	2151	1	13.35	107	195	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:1	17.72	2151	1	13.36	107	195	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:2	17.72	2151	1	13.36	107	195	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:2	17.72	2150	1	13.37	107	195	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:2	17.72	2150	0.99	13.37	107	195	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:2	17.72	2150	0.99	13.35	106	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:2	17.72	2149	0.99	13.35	106	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:2	17.72	2148	0.99	13.37	106	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:3	17.72	2147	0.99	13.37	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:3	17.72	2146	0.99	13.38	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:3	17.72	2143	0.99	13.37	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:3	17.72	2130	0.99	13.38	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:3	17.72	2137	0.99	13.37	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:3	17.72	2137	0.99	13.36	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:4	17.72	2144	0.99	13.37	107	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:4	17.72	2134	0.99	13.39	107	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:4	17.72	2116	0.99	13.4	107	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:4	17.72	2124	0.99	13.4	107	195	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:4	17.72	2132	0.99	13.41	107	195	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:4	17.72	2127	0.99	13.41	107	195	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:4	17.72	2131	0.99	13.4	107	195	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:5	17.72	2131	0.99	13.39	107	195	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:5	17.72	2130	0.99	13.41	106	195	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:5	17.72	2143	0.99	13.42	106	195	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:45:5	17.72	2126	0.99	13.43	107	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:5	17.72	2116	0.99	13.43	107	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:5	17.72	2123	0.99	13.42	107	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:6	17.72	2122	0.99	13.42	107	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:6	17.72	2119	0.99	13.42	107	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:6	17.72	2119	0.99	13.41	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:6	17.72	2118	0.98	13.4	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:6	17.72	2115	0.98	13.39	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:6	17.72	2115	0.98	13.38	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:6	17.72	2116	0.98	13.38	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:7	17.72	2114	0.98	13.38	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:7	17.72	2114	0.98	13.37	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:7	17.72	2112	0.98	13.38	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:7	17.72	2112	0.98	13.39	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:7	17.72	2109	0.98	13.38	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:7	17.72	2109	0.98	13.38	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:8	17.72	2106	0.98	13.37	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:8	17.72	2104	0.98	13.38	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:8	17.72	2102	0.98	13.38	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:8	17.72	2102	0.98	13.39	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:8	17.72	2102	0.98	13.39	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:8	17.72	2103	0.97	13.39	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:9	17.72	2103	0.97	13.39	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:9	17.72	2104	0.97	13.36	106	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:9	17.72	2101	0.97	13.35	106	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:9	17.72	2101	0.97	13.35	107	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:9	17.72	2100	0.97	13.34	107	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:9	17.72	2096	0.97	13.36	107	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:45:9	17.72	2092	0.97	13.36	106	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:0	17.72	2092	0.97	13.39	106	195	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:0	17.72	2089	0.97	13.4	106	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:0	17.72	2089	0.97	13.38	107	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:0	17.72	2084	0.97	13.39	107	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:0	17.72	2083	0.97	13.39	107	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:0	17.72	2082	0.97	13.39	107	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:1	17.72	2082	0.97	13.4	107	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:1	17.72	2082	0.97	13.4	107	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:1	17.72	2082	0.97	13.4	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:1	17.72	2082	0.97	13.39	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:1	17.72	2083	0.97	13.38	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:1	17.72	2082	0.97	13.38	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:1	17.72	2078	0.97	13.39	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:2	17.72	2078	0.97	13.4	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	19.95	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:2	17.72	2078	0.97	13.41	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	19.95	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:2	17.72	2075	0.97	13.42	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	19.97	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:2	17.72	2073	0.97	13.43	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	19.97	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:2	17.72	2072	0.97	13.42	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	19.96	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:2	17.72	2072	0.97	13.41	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	19.96	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:3	17.72	2070	0.97	13.4	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	19.96	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:3	17.72	2070	0.97	13.39	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	19.96	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:3	17.72	2070	0.97	13.38	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	19.97	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:3	17.72	2062	0.97	13.38	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:3	17.72	2068	0.97	13.38	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:3	17.72	2068	0.97	13.38	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:4	17.72	2074	0.97	13.38	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:4	17.72	2063	0.97	13.38	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:4	17.72	2062	0.97	13.39	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:4	17.72	2058	0.97	13.39	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:46:4	17.72	2058	0.97	13.4	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:4	17.72	2039	0.97	13.41	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.11	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:4	17.72	2054	0.97	13.41	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.1	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:5	17.72	2068	0.97	13.41	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.11	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:5	17.72	2068	0.97	13.42	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.11	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:5	17.72	2052	0.97	13.41	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.1	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:5	17.72	2053	0.97	13.41	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.1	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:5	17.72	2053	0.97	13.41	106	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.07	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:5	17.72	2055	0.97	13.41	106	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.07	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:6	17.72	2055	0.97	13.42	106	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.01	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:6	17.72	2053	0.97	13.43	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.01	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:6	17.72	2053	0.97	13.43	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.01	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:6	17.72	2049	0.97	13.43	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:6	17.72	2047	0.97	13.43	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.01	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:6	17.72	2045	0.97	13.43	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.01	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:6	17.72	2032	0.97	13.43	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.03	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:7	17.72	2036	0.97	13.43	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.04	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:7	17.72	2033	0.97	13.42	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.04	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:7	17.72	2032	0.97	13.41	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:7	17.72	2031	0.97	13.4	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:7	17.72	2031	0.97	13.39	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:7	17.72	2032	0.97	13.38	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:8	17.72	2031	0.97	13.38	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:8	17.72	2032	0.97	13.39	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:8	17.72	2032	0.97	13.41	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:8	17.72	2032	0.97	13.41	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:8	17.72	2031	0.97	13.43	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:8	17.72	2030	0.97	13.43	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:9	17.72	2030	0.97	13.42	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:9	17.72	2029	0.97	13.41	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:9	17.72	2027	0.97	13.4	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:9	17.72	2026	0.97	13.39	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:9	17.72	2026	0.97	13.39	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:9	17.72	2025	0.97	13.38	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:46:9	17.72	2023	0.97	13.4	107	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:0	17.72	2022	0.97	13.41	107	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:0	17.72	2022	0.97	13.42	107	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:0	17.72	2019	0.97	13.43	107	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:0	17.72	2016	0.97	13.44	107	195	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:0	17.72	2016	0.97	13.44	107	195	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:0	17.72	2014	0.97	13.42	107	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:1	17.72	2012	0.97	13.41	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:1	17.72	2012	0.97	13.4	107	195	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:1	17.72	2009	0.97	13.4	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:1	17.72	2007	0.97	13.41	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:1	17.72	2005	0.98	13.43	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:1	17.72	2005	0.98	13.44	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:1	17.72	2004	0.98	13.44	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:2	17.72	2002	0.98	13.44	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:2	17.72	2002	0.98	13.44	107	195	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:2	17.72	2001	0.98	13.44	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:2	17.72	2001	0.98	13.44	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:2	17.72	2000	0.98	13.44	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:2	17.72	2000	0.98	13.45	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:3	17.72	2001	0.98	13.45	107	195	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:3	17.72	2000	0.98	13.45	107	195	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:3	17.72	2000	0.98	13.44	107	195	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:3	17.72	1998	0.98	13.44	107	195	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:47:3	17.72	1996	0.98	13.43	107	195	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:3	17.72	1992	0.98	13.4	107	195	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:4	17.72	1992	0.98	13.38	107	195	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:4	17.72	1990	0.98	13.34	107	195	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:4	17.72	1989	0.98	13.32	107	195	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:4	17.72	1989	0.98	13.32	107	195	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:4	17.72	1986	0.98	13.32	107	195	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:4	17.72	1986	0.98	13.32	107	195	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:4	17.72	1986	0.98	13.33	107	195	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:5	17.72	1986	0.98	13.33	107	195	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:5	17.72	1985	0.97	13.33	107	195	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:5	17.72	1984	0.97	13.35	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:5	17.72	1984	0.97	13.36	107	195	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:5	17.72	1982	0.97	13.37	107	195	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:5	17.72	1962	0.97	13.38	107	195	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:6	17.72	1976	0.97	13.39	107	195	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:6	17.72	1982	0.97	13.39	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:6	17.72	1969	0.97	13.37	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:6	17.72	1949	0.97	13.37	107	195	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:6	17.72	1955	0.97	13.37	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:6	17.72	1957	0.97	13.37	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:6	17.72	1952	0.97	13.36	107	195	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:7	17.72	1947	0.97	13.36	107	195	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:7	17.72	1947	0.97	13.34	107	195	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:7	17.72	1942	0.97	13.34	107	195	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:7	17.72	1937	0.97	13.34	107	195	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:7	17.72	1937	0.97	13.36	107	195	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:7	17.72	1932	0.97	13.38	107	195	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:8	17.72	1926	0.97	13.38	107	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:8	17.72	1921	0.97	13.39	107	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:8	17.72	1921	0.97	13.4	107	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:8	17.72	1914	0.97	13.4	107	195	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:8	17.72	1906	0.97	13.39	107	195	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:8	17.72	1906	0.98	13.36	107	195	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:9	17.72	1900	0.98	13.34	107	195	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:9	17.72	1892	0.98	13.34	107	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:9	17.72	1892	0.98	13.34	107	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:9	17.72	1887	0.98	13.36	107	195	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:9	17.72	1878	0.98	13.37	107	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:9	17.72	1870	0.98	13.38	107	195	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:47:9	17.72	1870	0.98	13.38	107	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:0	17.72	1858	0.98	13.34	107	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:0	17.72	1858	0.99	13.34	107	195	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:0	17.72	1858	0.99	13.34	107	195	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:0	17.72	1855	0.99	13.35	107	195	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:0	17.72	1857	0.99	13.36	107	195	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:0	17.72	1844	0.99	13.37	107	195	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:1	17.72	1844	1	13.37	107	195	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:1	17.72	1831	1	13.36	107	195	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:1	17.72	1831	1	13.35	107	195	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:1	17.72	1831	1	13.36	107	195	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:1	17.72	1827	1	13.36	107	195	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:1	17.72	1820	1.01	13.36	107	195	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.25	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:1	17.72	1813	1.01	13.36	107	195	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.25	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:2	17.72	1813	1.01	13.35	107	195	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:2	17.72	1809	1.01	13.35	107	195	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:2	17.72	1805	1.01	13.34	107	195	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:2	17.72	1803	1.02	13.36	107	195	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:48:2	17.72	1796	1.02	13.35	107	195	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:2	17.72	1794	1.02	13.35	107	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:3	17.72	1790	1.02	13.34	107	195	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:3	17.72	1788	1.02	13.33	107	195	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:3	17.72	1782	1.02	13.35	107	195	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.21	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:3	17.72	1774	1.02	13.34	107	195	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:3	17.72	1774	1.02	13.34	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.21	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:3	17.72	1765	1.02	13.36	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:4	17.72	1755	1.03	13.35	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:4	17.72	1749	1.02	13.36	107	195	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:4	17.72	1749	1.02	13.36	107	195	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.21	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:4	17.72	1744	1.02	13.34	107	195	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:4	17.72	1741	1.02	13.35	107	195	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:4	17.72	1733	1.02	13.36	107	195	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:4	17.72	1728	1.02	13.36	107	195	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:5	17.72	1724	1.02	13.37	107	195	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:5	17.72	1719	1.02	13.37	107	195	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:5	17.72	1717	1.02	13.36	107	195	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:5	17.72	1713	1.02	13.35	107	195	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:5	17.72	1706	1.02	13.34	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:5	17.72	1706	1.01	13.34	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:6	17.72	1703	1.01	13.34	107	195	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:6	17.72	1698	1.01	13.33	107	195	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:6	17.72	1692	1.01	13.35	107	195	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:6	17.72	1682	1.01	13.35	107	195	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.23	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:6	17.72	1677	1.01	13.33	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:6	17.72	1675	1.01	13.34	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:6	17.72	1671	1.01	13.33	107	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:7	17.72	1666	1.01	13.34	107	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:7	17.72	1666	1.01	13.35	107	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:7	17.72	1658	1.01	13.35	107	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:7	17.72	1656	1.01	13.35	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:7	17.72	1652	1.01	13.35	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.16	1.37	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:7	17.72	1649	1.01	13.34	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.16	1.37	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:8	17.72	1640	1.01	13.33	107	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.16	1.37	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:8	17.72	1648	1.01	13.33	107	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.16	1.37	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:8	17.72	1629	1.01	13.33	107	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.16	1.37	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:8	17.72	1629	1.01	13.34	107	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.16	1.37	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:8	17.72	1609	1.01	13.35	107	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.16	1.37	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:8	17.72	1618	1.01	13.34	107	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.16	1.37	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:9	17.72	1618	1.01	13.36	107	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.16	1.37	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:9	17.72	1608	1.01	13.36	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.22	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:9	17.72	1604	1.01	13.35	107	195	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:9	17.72	1598	1.01	13.36	107	195	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:9	17.72	1590	1.01	13.35	107	195	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:9	17.72	1590	1.01	13.35	107	195	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:48:9	17.72	1584	1.01	13.34	107	195	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.24	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:0	17.72	1576	1.01	13.34	107	195	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:0	17.72	1558	1.01	13.35	107	195	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:0	17.72	1558	1.01	13.36	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:0	17.72	1563	1.01	13.37	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:0	17.72	1568	1.01	13.37	107	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:0	17.72	1548	1.01	13.37	107	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:1	17.72	1522	1.01	13.35	107	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:1	17.72	1522	1.01	13.35	107	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:1	17.72	1505	1.01	13.35	107	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:1	17.72	1495	1.01	13.37	107	195	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:1	17.72	1470	1.01	13.36	107	195	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:49:1	17.72	1457	1	13.38	107	195	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.15	1.37	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:1	17.72	1430	1	13.38	107	195	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.15	1.37	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:2	17.72	1417	1.01	13.37	107	195	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.15	1.37	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:2	16.36	1379	1.01	13.35	107	195	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.14	1.37	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:2	16.36	1379	1.01	13.36	107	195	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.15	1.37	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:2	16.36	1362	1.01	13.35	107	195	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.14	1.37	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:49:2	19.09	1334	1.01	13.35	107	195	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.35	20.14	1.37	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:49:2	19.09	1334	1.01	13.34	107	195	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.3	20.14	1.37	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:49:3	19.09	1304	1.02	13.35	107	195	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.21	20.14	1.37	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:3	17.72	1267	1.02	13.34	107	195	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.11	20.14	1.37	4.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:15:49:3	17.72	1246	1.02	13.35	107	195	Idle	77.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.04	20.23	1.38	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:3	17.72	1246	1.03	13.37	107	195	Idle	76.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.97	20.23	1.38	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:3	17.72	1209	1.04	13.37	106	195	Idle	75	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.87	20.23	1.38	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:3	17.72	1200	1.05	13.37	106	195	Idle	74.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.7	20.23	1.38	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:4	17.72	1200	1.05	13.37	107	195	Idle	74	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.58	20.23	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:49:4	17.72	1185	1.06	13.35	107	195	Idle	73.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.49	20.23	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:49:4	17.72	1168	1.07	13.35	107	195	Idle	73.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.38	20.23	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:49:4	17.72	1167	1.08	13.34	107	195	Idle	73.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.31	20.23	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:49:4	17.72	1162	1.08	13.36	107	195	Idle	72.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.25	20.23	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:49:4	17.72	1158	1.09	13.34	107	195	Idle	72.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.21	20.23	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:49:4	17.72	1180	1.1	13.35	107	195	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.15	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:49:5	16.36	1180	1.11	13.35	107	195	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.11	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:49:5	16.36	1184	1.11	13.36	107	195	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.09	20.23	1.38	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:49:5	16.36	1199	1.11	13.35	107	195	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.07	20.23	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:5	16.36	1199	1.12	13.38	107	195	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.05	20.24	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:5	16.36	1197	1.11	13.38	107	195	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.05	20.23	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:5	16.36	1216	1.11	13.37	107	195	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.07	20.24	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:6	16.36	1218	1.11	13.38	107	195	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.06	20.25	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:49:6	16.36	1218	1.11	13.38	107	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.25	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:49:6	16.36	1220	1.1	13.37	107	195	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.11	20.24	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:6	16.36	1220	1.1	13.37	107	195	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.17	20.25	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:6	16.36	1218	1.09	13.35	107	195	Idle	83.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.2	20.25	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:6	16.36	1210	1.08	13.34	107	195	Idle	84.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.24	20.24	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:6	16.36	1210	1.07	13.34	107	195	Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.28	20.24	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:7	13.63	1208	1.06	13.35	107	195	Idle	86.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.31	20.24	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:7	13.63	1208	1.05	13.35	107	195	Idle	87.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.32	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:7	13.63	1211	1.04	13.35	107	195	Idle	87.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.31	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:49:7	12.27	1204	1.03	13.35	107	195	Idle	87.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.34	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:49:7	12.27	1196	1.02	13.37	107	195	Idle	87.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.34	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:15:49:7	12.27	1194	1.01	13.37	107	195	Idle	87.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.39	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:8	14.99	1159	1	13.38	107	195	Idle	87.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.44	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:8	14.99	1160	0.99	13.37	107	195	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.45	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:8	14.99	1160	0.99	13.33	107	195	Idle	88.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.48	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:8	14.99	1151	0.98	13.34	107	195	Idle	88.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.48	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:8	14.99	1142	0.97	13.33	107	195	Idle	89	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.45	20.11	1.37	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:8	14.99	1140	0.97	13.34	107	195	Idle	89.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.49	20.11	1.37	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:9	14.99	1139	0.96	13.34	107	195	Idle	89.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.46	20.11	1.37	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:9	13.63	1124	0.96	13.34	107	195	Idle	89.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.45	20.11	1.37	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:9	13.63	1120	0.95	13.35	107	195	Idle	89.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.47	20.11	1.37	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:9	13.63	1120	0.95	13.35	107	195	Idle	90.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.48	20.11	1.37	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:9	13.63	1109	0.95	13.37	107	195	Idle	90.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	20.11	1.37	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:9	13.63	1098	0.94	13.36	107	195	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.47	20.11	1.37	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:15:49:9	13.63	1085	0.94	13.36	107	195	Idle	91.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.49	20.1	1.37	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:0	13.63	1072	0.94	13.37	107	195	Idle	91.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.43	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:0	13.63	1074	0.93	13.35	107	195	Idle	91.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:0	13.63	1063	0.93	13.35	107	195	Idle	91.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:0	13.63	1063	0.92	13.34	107	195	Idle	91.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.34	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:0	13.63	1067	0.92	13.36	107	195	Idle	91.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.37	20.21	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:50:0	13.63	1067	0.92	13.36	107	195	Idle	92	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.35	20.19	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:1	13.63	1084	0.91	13.34	107	195	Idle	92.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.35	20.05	1.37	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:1	13.63	1084	0.91	13.37	107	195	Idle	92.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.36	19.9	1.36	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:1	12.27	1069	0.91	13.36	107	195	Idle	92.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.37	19.72	1.34	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:1	12.27	1054	0.91	13.38	107	195	Idle	92.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.39	19.49	1.33	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:1	12.27	1045	0.9	13.37	107	195	Idle	92.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.35	19.1	1.3	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:1	12.27	1040	0.9	13.39	106	195	Idle	92.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.39	18.8	1.28	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:1	12.27	1040	0.9	13.37	106	195	Idle	92.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	18.49	1.26	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:2	12.27	1030	0.89	13.35	107	195	Idle	92.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	17.98	1.23	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:2	12.27	1021	0.89	13.37	107	195	Idle	92.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.3	17.68	1.2	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:2	12.27	1021	0.89	13.37	107	195	Idle	92.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	17.68	1.2	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:2	12.27	1021	0.89	13.37	107	195	Idle	92.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.26	17.42	1.19	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:2	12.27	1014	0.88	13.35	107	195	Idle	93	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	17.08	1.16	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:2	12.27	1014	0.88	13.37	107	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	16.88	1.15	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:3	12.27	1006	0.88	13.35	107	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.3	16.65	1.13	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:3	12.27	997	0.88	13.35	107	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.3	16.53	1.13	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:3	12.27	993	0.87	13.34	107	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.29	16.42	1.12	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:3	12.27	993	0.87	13.35	107	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.28	16.33	1.11	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:3	10.9	990	0.87	13.33	107	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.28	16.26	1.11	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:3	10.9	994	0.87	13.36	106	195	Idle	93	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.27	16.19	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:4	10.9	994	0.87	13.34	106	195	Idle	93	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.21	16.16	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:4	10.9	990	0.86	13.36	106	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.22	16.14	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:4	10.9	990	0.86	13.33	106	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.17	16.12	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:4	10.9	982	0.86	13.34	107	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.18	16.11	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:4	10.9	977	0.86	13.35	107	195	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.13	16.1	1.1	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:4	10.9	966	0.86	13.35	107	195	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.17	16.09	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:4	10.9	966	0.86	13.35	107	195	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.13	16.09	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:5	10.9	968	0.86	13.35	107	195	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.16	16.08	1.1	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:5	10.9	971	0.86	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.1	16.08	1.1	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:5	10.9	971	0.86	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.11	16.06	1.09	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:5	10.9	967	0.85	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.09	16.05	1.09	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:5	10.9	949	0.85	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.11	16.02	1.09	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:5	10.9	949	0.85	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.07	16.01	1.09	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:6	9.54	940	0.85	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.09	15.99	1.09	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:6	9.54	932	0.85	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.03	15.97	1.09	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:6	9.54	950	0.85	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.03	15.95	1.09	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:6	9.54	950	0.85	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.99	15.95	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:6	9.54	950	0.85	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.02	15.9	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:6	9.54	949	0.85	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.99	15.88	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:6	9.54	951	0.85	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.02	15.86	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:7	9.54	951	0.84	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.95	15.84	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:7	9.54	951	0.84	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.98	15.82	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:7	9.54	954	0.84	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.93	15.83	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:7	9.54	956	0.84	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.98	15.81	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:7	9.54	956	0.84	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.92	15.78	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:7	9.54	959	0.84	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.99	15.75	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:8	9.54	959	0.84	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.97	15.74	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:8	9.54	945	0.84	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.98	15.7	1.07	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:8	9.54	945	0.84	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.93	15.69	1.07	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:8	8.18	944	0.84	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.94	15.66	1.07	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:8	8.18	943	0.84	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.89	15.62	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:8	8.18	946	0.84	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.89	15.58	1.06	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:9	8.18	946	0.84	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.88	15.56	1.06	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:9	8.18	939	0.84	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.89	15.54	1.06	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:9	6.81	932	0.84	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.89	15.53	1.06	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:9	6.81	932	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.96	15.51	1.06	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:50:9	6.81	941	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.89	15.5	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:50:9	8.18	933	0.83	13.36	107	195	Idle	93.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.94	15.48	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:50:9	8.18	933	0.83	13.36	107	195	Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.88	15.45	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:0	8.18	932	0.83	13.35	107	195	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.9	15.43	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:0	8.18	930	0.83	13.36	107	195	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.85	15.43	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:0	8.18	930	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.88	15.41	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:0	8.18	919	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.81	15.4	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:0	8.18	919	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.86	15.38	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:0	8.18	920	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.81	15.36	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:1	8.18	920	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.83	15.35	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:1	9.54	928	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	15.32	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:1	9.54	936	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.86	15.3	1.04	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:1	9.54	914	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.31	1.04	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:1	9.54	912	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.28	1.04	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:1	9.54	912	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	15.27	1.04	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:1	9.54	912	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.83	15.25	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:2	9.54	915	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:2	9.54	913	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:2	9.54	913	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15.19	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:2	9.54	913	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.19	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:2	9.54	926	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.18	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:2	9.54	926	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.13	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:3	8.18	926	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:3	8.18	926	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:3	8.18	922	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:51:3	8.18	917	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:51:3	8.18	926	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.05	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:51:3	8.18	926	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.03	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:51:4	8.18	928	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:51:4	8.18	929	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:51:4	8.18	903	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	14.98	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:51:4	8.18	903	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.98	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:51:4	8.18	894	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	14.96	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:51:4	8.18	894	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:4	8.18	896	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.74	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:5	8.18	898	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.72	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:5	8.18	901	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.71	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:5	8.18	901	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.69	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:5	8.18	901	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	14.98	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:5	8.18	883	0.82	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.72	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:5	8.18	892	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.71	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:6	8.18	892	0.82	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.72	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:6	8.18	892	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:6	9.54	901	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.68	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:6	9.54	901	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:6	9.54	897	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:51:6	9.54	897	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:51:6	9.54	898	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:51:7	9.54	898	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.79	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:51:7	9.54	910	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:7	9.54	910	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:7	9.54	911	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:7	9.54	911	0.82	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.6	14.76	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:7	9.54	911	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.75	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:8	9.54	910	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:8	9.54	917	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:8	9.54	917	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:8	9.54	917	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:8	9.54	915	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:8	9.54	926	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:51:9	6.81	926	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:9	6.81	926	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:9	6.81	922	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:9	8.18	914	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:9	8.18	914	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.65	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:9	8.18	914	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.64	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:51:9	8.18	930	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.65	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:0	8.18	930	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.67	15.01	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:0	8.18	906	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:0	8.18	923	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.71	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:0	8.18	923	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:0	8.18	918	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.74	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:0	8.18	914	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.71	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:1	8.18	914	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.72	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:1	8.18	920	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.7	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:1	8.18	926	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.72	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:1	8.18	926	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:1	8.18	926	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.74	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:1	8.18	914	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.72	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:1	8.18	917	0.82	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.76	15.14	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:2	8.18	917	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.74	15.14	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:2	8.18	917	0.82	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.74	15.13	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:2	8.18	911	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.74	15.13	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:2	8.18	911	0.82	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:2	9.54	912	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:2	9.54	913	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:3	9.54	912	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:3	9.54	910	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:3	9.54	940	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:3	9.54	940	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.73	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:3	9.54	940	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.75	15.02	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:3	9.54	916	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.73	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:4	9.54	922	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.75	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:4	9.54	928	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.76	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:4	9.54	930	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.77	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:4	9.54	930	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.79	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:4	8.18	922	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.78	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:4	8.18	915	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.79	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:4	8.18	933	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.79	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:5	8.18	933	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.77	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:5	8.18	932	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.79	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:5	9.54	930	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.75	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:5	9.54	930	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.78	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:5	9.54	930	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:5	9.54	930	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.94	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:6	8.18	918	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:6	8.18	926	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.8	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:6	8.18	926	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:6	8.18	926	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:6	8.18	933	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:6	8.18	930	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:6	8.18	930	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:7	8.18	930	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:7	8.18	916	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:7	8.18	916	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:7	8.18	930	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:7	8.18	930	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.78	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:7	6.81	936	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:52:8	6.81	928	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.8	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:8	6.81	928	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.77	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:8	6.81	921	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.79	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:8	6.81	912	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.77	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:8	6.81	912	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.76	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:8	6.81	930	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:9	6.81	928	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.77	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:9	8.18	926	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.74	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:9	8.18	926	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.79	15.09	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:9	8.18	926	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.77	15.1	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:9	8.18	926	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.78	15.09	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:9	8.18	924	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.78	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:52:9	8.18	924	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.82	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:0	8.18	935	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.8	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:0	8.18	935	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.81	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:0	8.18	934	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.79	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:0	8.18	932	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.81	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:0	8.18	939	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.78	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:0	8.18	939	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.8	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:1	8.18	941	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.79	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:1	8.18	941	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.81	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:1	8.18	939	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.81	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:1	8.18	937	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.8	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:1	8.18	938	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.83	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:1	8.18	938	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.83	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:1	8.18	936	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.8	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:2	8.18	933	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.81	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:2	8.18	925	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.82	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:2	8.18	925	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.81	15.05	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:2	8.18	925	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:2	8.18	925	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:2	9.54	934	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:3	9.54	934	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:3	9.54	920	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:3	9.54	920	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:3	9.54	920	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.85	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:3	9.54	929	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:3	9.54	910	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:4	9.54	910	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:4	9.54	925	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:4	8.18	940	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:4	8.18	938	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:4	8.18	938	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:4	8.18	936	0.83	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.85	14.96	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:4	8.18	933	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:5	8.18	933	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:5	8.18	935	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:5	8.18	928	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:5	8.18	928	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:5	8.18	928	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:5	8.18	936	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:6	8.18	936	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:6	8.18	925	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:6	8.18	923	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:6	8.18	921	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:6	8.18	921	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.81	14.94	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:6	8.18	932	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	14.92	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:6	8.18	932	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.84	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:53:7	8.18	945	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.81	14.89	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:7	8.18	945	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.86	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:7	8.18	917	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.83	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:7	8.18	917	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.86	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:53:7	8.18	920	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.83	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:7	8.18	924	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.85	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:8	9.54	932	0.83	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.78	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:8	9.54	932	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.81	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:8	9.54	926	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.81	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:8	9.54	921	0.83	13.39	107	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.85	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:8	6.81	922	0.83	13.39	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.79	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:8	6.81	922	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.82	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:9	6.81	930	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.81	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:9	6.81	930	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.8	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:9	6.81	932	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.78	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:9	6.81	934	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.8	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:9	6.81	936	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.79	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:9	6.81	936	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.82	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:53:9	6.81	932	0.83	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.75	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:0	6.81	932	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.79	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:0	6.81	930	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:0	6.81	930	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.77	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:0	6.81	924	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.75	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:0	6.81	924	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.81	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:0	6.81	934	0.83	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:1	6.81	943	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.81	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:1	9.54	927	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.81	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:1	9.54	927	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.84	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:1	9.54	924	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.82	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:1	9.54	922	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.84	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:1	8.18	920	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.84	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:1	8.18	918	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.83	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:2	8.18	927	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.82	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:2	8.18	927	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.79	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:2	8.18	918	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.84	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:2	8.18	918	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.78	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:2	8.18	926	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.78	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:2	8.18	933	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.8	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:3	8.18	933	0.83	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:3	8.18	930	0.83	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:3	8.18	926	0.83	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:3	8.18	926	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:3	9.54	923	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	15.13	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:3	9.54	920	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:4	9.54	920	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:4	9.54	918	0.83	13.39	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:4	9.54	920	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:4	9.54	922	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:4	9.54	922	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:4	9.54	926	0.83	13.41	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:4	8.18	922	0.83	13.4	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:5	8.18	922	0.83	13.4	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:5	8.18	927	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:5	8.18	932	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:5	8.18	932	0.83	13.35	106	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:5	8.18	938	0.83	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:5	8.18	935	0.83	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:6	8.18	935	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.05	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:54:6	8.18	935	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.05	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:54:6	6.81	917	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:54:6	6.81	923	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.81	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:54:6	6.81	923	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:6	6.81	923	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.81	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:6	6.81	925	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:7	6.81	922	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.8	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:7	6.81	922	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.9	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:54:7	6.81	922	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.81	14.88	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:54:7	8.18	920	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.76	14.87	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:54:7	8.18	920	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.77	14.86	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:54:7	8.18	900	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.73	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:8	8.18	900	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.74	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:8	6.81	920	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.71	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:8	6.81	920	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.74	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:8	6.81	908	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.74	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:8	6.81	908	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.71	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:8	8.18	909	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.74	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:9	8.18	909	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.7	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:9	8.18	904	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.74	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:9	8.18	900	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.67	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:9	8.18	897	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.71	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:9	8.18	897	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:9	8.18	900	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.73	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:54:9	8.18	904	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.68	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:0	8.18	904	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.74	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:0	8.18	901	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:0	8.18	901	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.7	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:0	8.18	914	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:55:0	8.18	914	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.71	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:55:0	8.18	916	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.66	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:55:1	8.18	916	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.7	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:55:1	8.18	919	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:1	8.18	919	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:1	9.54	918	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:1	9.54	917	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.72	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:1	9.54	923	0.82	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.71	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:1	9.54	923	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.74	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:2	8.18	926	0.82	13.32	107	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.71	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:2	8.18	928	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.76	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:2	8.18	931	0.82	13.32	107	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.74	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:2	8.18	931	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.79	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:2	8.18	930	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.77	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:2	8.18	930	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.79	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:3	8.18	918	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.76	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:3	8.18	918	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.76	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:3	9.54	934	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.72	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:3	9.54	934	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:3	9.54	925	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:3	9.54	925	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:4	9.54	945	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:4	9.54	945	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:4	9.54	945	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:4	9.54	925	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:4	8.18	934	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:4	8.18	934	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:4	8.18	931	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:5	8.18	931	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:55:8	9.54	931	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	9.54	924	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	9.54	921	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	9.54	921	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	8.18	921	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	8.18	924	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	8.18	923	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	8.18	923	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	8.18	923	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	8.18	917	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	8.18	910	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:8	8.18	904	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:7	8.18	904	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:7	8.18	938	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:7	8.18	918	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.97	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:7	8.18	918	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.97	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:7	8.18	918	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.94	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:7	6.81	892	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:6	6.81	892	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:6	6.81	921	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:6	6.81	921	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:6	8.18	900	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:6	8.18	900	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:6	8.18	904	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:9	8.18	908	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.71	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:9	8.18	903	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:9	8.18	903	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:9	8.18	904	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.72	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:9	8.18	904	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.71	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:9	8.18	908	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.71	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:55:9	8.18	908	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.69	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:0	8.18	906	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.68	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:0	8.18	905	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.65	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:0	8.18	904	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.66	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:0	8.18	904	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.61	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:0	8.18	890	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.87	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:0	8.18	877	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.65	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:56:1	8.18	877	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:56:1	9.54	895	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.86	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:56:1	9.54	898	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.86	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:56:1	9.54	902	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:56:1	9.54	902	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:56:1	8.18	902	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:56:1	8.18	904	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:56:2	8.18	905	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:2	8.18	905	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:2	8.18	915	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:2	8.18	915	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:2	8.18	922	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:2	8.18	928	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:3	8.18	916	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:3	8.18	916	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:3	8.18	916	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:3	8.18	917	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.92	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:3	8.18	934	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.7	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:3	8.18	934	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.68	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:4	8.18	934	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.7	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:4	8.18	932	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.7	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:56:4	8.18	925	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.71	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:4	8.18	918	0.82	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.69	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:4	8.18	919	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.68	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:4	8.18	919	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:4	8.18	918	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:5	8.18	918	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:5	8.18	935	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.15	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:5	8.18	935	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.16	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:5	8.18	935	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	15.16	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:5	9.54	929	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	15.15	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:5	9.54	936	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.13	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:6	9.54	936	0.82	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:6	9.54	938	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:6	8.18	941	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:6	8.18	936	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:6	8.18	936	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.15	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:6	8.18	936	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.13	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:6	8.18	929	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.13	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:7	8.18	930	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.12	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:7	8.18	930	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.11	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:7	8.18	928	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:7	8.18	926	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.06	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:7	8.18	932	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	15.05	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:7	8.18	932	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.06	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:8	8.18	932	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:8	8.18	927	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.77	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:8	8.18	919	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.77	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:56:8	8.18	919	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.77	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:8	8.18	919	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.79	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:8	9.54	904	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.76	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:9	9.54	920	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.77	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:9	9.54	920	0.82	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.75	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:9	9.54	920	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.77	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:9	8.18	928	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.77	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:9	8.18	928	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.8	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:9	8.18	930	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.77	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:56:9	8.18	931	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.78	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:0	8.18	930	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:0	8.18	929	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:0	8.18	915	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:0	8.18	915	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:0	8.18	912	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:0	8.18	912	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.78	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:1	8.18	913	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:1	8.18	914	0.82	13.38	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:1	8.18	915	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.73	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:1	8.18	915	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:1	8.18	920	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:1	8.18	920	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.76	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:1	6.81	920	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:2	6.81	916	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.78	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:2	6.81	926	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.8	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:2	6.81	926	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:2	6.81	930	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.8	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:2	6.81	934	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:2	6.81	920	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.8	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:3	6.81	920	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:3	6.81	911	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:57:3	8.18	902	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.78	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:3	8.18	908	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.79	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:3	8.18	908	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:3	8.18	908	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.74	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:4	9.54	895	0.82	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.71	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:4	9.54	895	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.69	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:4	9.54	898	0.82	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.71	15.05	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:4	9.54	901	0.82	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.7	15.06	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:4	8.18	920	0.82	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.7	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:4	8.18	920	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.71	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:4	8.18	912	0.82	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.71	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:5	8.18	912	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:5	6.81	905	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:5	6.81	905	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:5	6.81	916	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:5	6.81	916	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:5	9.54	917	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:6	9.54	918	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:6	9.54	911	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:6	9.54	911	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:6	9.54	912	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:6	9.54	912	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:6	9.54	914	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:6	9.54	914	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:7	8.18	914	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:7	8.18	919	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:7	8.18	902	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:7	8.18	902	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:7	9.54	911	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:7	9.54	920	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:8	9.54	920	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:8	9.54	914	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:8	9.54	908	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:8	6.81	903	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:8	6.81	903	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:8	6.81	907	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:9	6.81	907	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:9	8.18	905	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:9	8.18	905	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:9	8.18	899	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:9	8.18	899	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:9	8.18	899	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:57:9	8.18	885	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.61	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:0	8.18	886	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.58	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:0	8.18	886	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.6	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:0	9.54	896	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:0	9.54	896	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.64	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:0	9.54	902	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.65	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:0	9.54	909	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.66	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:1	9.54	888	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.66	14.91	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:1	9.54	888	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.6	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:1	9.54	888	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.64	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:1	9.54	906	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.58	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:1	9.54	906	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.61	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:1	9.54	912	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.61	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:1	9.54	919	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.66	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:2	9.54	909	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.64	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:2	9.54	909	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.67	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:58:2	8.18	909	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.62	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:2	8.18	909	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.64	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:2	8.18	915	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.62	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:2	8.18	915	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.66	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:3	6.81	912	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:3	6.81	912	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:3	6.81	907	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:3	6.81	907	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:3	8.18	899	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:3	8.18	891	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.68	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:4	8.18	903	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.67	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:58:4	8.18	903	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.62	14.87	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:58:4	8.18	903	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.66	14.86	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:58:4	8.18	877	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.62	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:58:4	8.18	899	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.64	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:58:4	8.18	899	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.59	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:58:4	8.18	899	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.66	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:58:5	8.18	902	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:58:5	8.18	902	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.63	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:15:58:5	8.18	913	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.61	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:5	8.18	913	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.62	14.9	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:5	8.18	906	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.61	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:5	8.18	911	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.67	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:6	8.18	916	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.6	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:6	8.18	916	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.64	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:6	8.18	927	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.62	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:6	8.18	923	0.82	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.65	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:6	8.18	923	0.82	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.64	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:6	8.18	919	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:6	6.81	942	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:7	6.81	942	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.97	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:7	6.81	945	0.82	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.98	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:58:7	6.81	948	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:58:7	6.81	939	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:58:7	6.81	939	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15.01	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:58:7	6.81	930	0.82	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.01	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:8	6.81	930	0.82	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.01	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:8	8.18	926	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:8	8.18	923	0.82	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:8	8.18	924	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:8	8.18	924	0.82	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:8	8.18	916	0.82	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:9	8.18	907	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:9	8.18	922	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:9	8.18	922	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:9	9.54	926	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:9	9.54	929	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:58:9	9.54	929	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	14.98	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:58:9	9.54	931	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:0	8.18	926	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:0	8.18	926	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	15.03	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:0	8.18	934	0.83	13.32	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	15.03	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:0	8.18	941	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.04	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:0	8.18	941	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:0	8.18	936	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:1	8.18	934	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:1	8.18	931	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.78	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:1	8.18	914	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.78	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:15:59:1	8.18	914	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.77	14.97	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:1	8.18	918	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	14.94	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:1	8.18	922	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.75	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:1	9.54	922	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.78	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:2	9.54	915	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.74	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:2	9.54	915	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.77	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:2	9.54	916	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.75	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:2	8.18	924	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.79	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:2	8.18	931	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.8	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:2	8.18	931	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.83	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:3	8.18	926	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.81	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:3	8.18	924	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.81	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:3	8.18	924	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.79	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:3	8.18	924	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.79	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:3	8.18	923	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.76	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:3	8.18	923	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.79	14.75	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:4	6.81	934	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.75	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:4	6.81	934	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	14.74	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:4	6.81	934	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.75	14.74	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:4	6.81	934	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.78	14.72	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:4	6.81	929	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.75	14.72	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:4	6.81	929	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.78	14.72	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:4	6.81	910	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	14.72	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:5	6.81	910	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:5	6.81	910	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:5	6.81	910	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:5	6.81	912	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:5	6.81	912	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.79	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:5	8.18	909	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.77	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:6	8.18	906	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.78	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:6	8.18	913	0.83	13.31	107	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.77	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:6	8.18	913	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.74	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:6	8.18	924	0.83	13.31	107	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.75	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:6	8.18	934	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.73	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:6	8.18	919	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.72	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:6	8.18	919	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.75	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:7	8.18	919	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.75	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:7	8.18	919	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.76	15.05	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:7	8.18	919	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.78	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:7	8.18	924	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.77	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:7	8.18	924	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.11	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:7	8.18	923	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	15.11	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:8	8.18	935	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	15.11	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:8	8.18	935	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	15.11	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:8	8.18	935	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	15.11	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:8	8.18	944	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15.12	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:8	8.18	933	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.12	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:8	8.18	933	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15.12	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:9	8.18	933	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.12	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:9	8.18	920	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.12	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:15:59:9	8.18	920	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:9	8.18	920	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:9	8.18	920	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:9	9.54	931	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:15:59:9	9.54	918	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:0	9.54	918	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:0	9.54	918	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:0	8.18	920	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:00:0	8.18	919	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:0	8.18	919	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:0	8.18	919	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:1	9.54	919	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:1	9.54	927	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:1	9.54	923	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:1	9.54	919	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:1	8.18	903	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:1	8.18	903	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:1	8.18	909	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:2	8.18	909	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.83	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:2	8.18	925	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.8	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:2	8.18	925	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:2	8.18	919	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:2	8.18	919	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.74	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:2	8.18	890	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.77	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:3	8.18	890	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.79	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:3	8.18	894	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.79	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:3	8.18	894	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.77	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:3	9.54	894	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.74	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:3	9.54	906	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.73	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:3	9.54	904	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.73	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:4	9.54	904	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:4	9.54	900	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:4	8.18	898	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:4	8.18	898	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.66	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:4	8.18	912	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.66	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:4	8.18	921	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:4	8.18	930	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.68	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:5	8.18	930	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.71	14.85	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:5	8.18	896	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.68	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:5	8.18	896	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:5	6.81	896	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:5	6.81	915	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:5	6.81	931	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:6	6.81	931	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:6	6.81	923	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.66	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:6	6.81	915	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.71	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:6	6.81	925	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:6	6.81	925	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.73	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:6	6.81	922	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.7	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:6	6.81	919	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:7	6.81	920	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.7	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:7	6.81	920	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.72	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:7	8.18	922	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:7	8.18	925	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:7	8.18	920	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:7	8.18	920	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:8	8.18	916	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:8	8.18	911	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:8	8.18	903	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:8	8.18	903	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:8	9.54	904	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:8	9.54	906	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:9	9.54	906	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:9	9.54	913	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:9	9.54	918	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:9	9.54	923	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:00:9	9.54	918	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:9	9.54	918	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:00:9	9.54	918	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:0	8.18	921	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:0	8.18	938	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:0	8.18	938	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:01:0	8.18	931	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:01:0	8.18	924	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.73	15.02	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:01:0	8.18	924	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.75	15.02	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:01:1	8.18	913	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.72	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:1	8.18	913	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.72	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:1	6.81	927	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.72	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:1	6.81	927	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.73	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:1	6.81	914	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.73	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:1	6.81	914	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.76	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:1	8.18	917	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:2	8.18	917	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.77	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:2	8.18	915	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:2	8.18	915	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:2	8.18	918	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:2	8.18	918	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:2	8.18	924	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:3	8.18	929	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:3	6.81	916	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:3	6.81	916	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:3	6.81	919	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:3	6.81	922	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:3	6.81	925	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:4	6.81	925	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:4	6.81	922	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:4	6.81	919	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:4	9.54	919	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:4	9.54	909	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:4	9.54	904	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:4	9.54	899	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:5	9.54	899	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:5	9.54	901	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:5	9.54	901	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:5	9.54	906	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:5	9.54	906	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:5	8.18	904	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:6	8.18	922	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:6	8.18	922	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:6	8.18	922	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:6	9.54	922	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:6	9.54	922	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:6	9.54	919	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:6	9.54	922	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:7	8.18	925	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.76	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:7	8.18	925	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.78	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:7	8.18	901	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:7	8.18	901	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.76	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:7	8.18	914	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.75	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:7	8.18	926	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.74	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:8	8.18	909	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.71	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:8	8.18	909	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.73	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:8	8.18	909	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.75	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:8	8.18	899	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.74	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:01:8	8.18	910	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.73	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:8	8.18	910	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.75	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:9	8.18	912	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.75	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:9	8.18	915	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.7	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:9	8.18	916	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.73	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:9	8.18	916	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:9	8.18	932	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.7	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:9	8.18	932	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:01:9	8.18	932	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	15.1	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:0	8.18	910	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:0	8.18	914	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:0	6.81	918	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:0	6.81	918	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:0	6.81	928	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:0	6.81	928	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:1	8.18	915	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:1	8.18	915	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:1	8.18	913	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:1	8.18	906	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:1	9.54	901	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:1	9.54	901	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:1	9.54	918	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:2	9.54	918	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:2	9.54	900	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:2	9.54	900	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:2	9.54	909	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:2	9.54	909	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:2	9.54	915	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:3	9.54	915	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:3	9.54	914	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:3	9.54	913	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:3	8.18	896	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:3	8.18	896	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:3	8.18	900	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:4	8.18	904	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:4	8.18	920	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:4	8.18	920	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:4	8.18	904	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	14.91	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:4	8.18	889	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	14.91	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:4	8.18	901	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.76	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:4	8.18	901	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.71	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:5	8.18	901	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.72	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:5	8.18	908	0.83	13.31	107	194	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.66	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:5	8.18	908	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:5	8.18	915	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.65	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:5	8.18	915	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.66	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:5	8.18	897	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.66	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:6	8.18	897	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:6	8.18	898	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:6	8.18	898	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:6	8.18	901	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:6	8.18	901	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:6	8.18	906	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:6	8.18	912	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.65	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:7	8.18	912	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:7	8.18	900	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:7	8.18	905	0.83	13.31	107	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:7	8.18	910	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.63	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:02:7	8.18	917	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:7	8.18	917	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.62	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:8	8.18	919	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:8	8.18	921	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:8	8.18	913	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:8	8.18	913	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.67	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:8	8.18	916	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:8	6.81	916	0.83	13.34	107	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.65	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:9	6.81	918	0.83	13.36	107	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:9	6.81	916	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:9	6.81	916	0.83	13.35	107	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.72	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:9	6.81	916	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:9	6.81	916	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.75	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:9	6.81	932	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.71	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:02:9	6.81	932	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.72	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:0	6.81	917	0.83	13.31	107	194	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.68	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:0	6.81	917	0.83	13.31	107	194	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:0	6.81	916	0.83	13.31	107	194	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.65	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:0	6.81	916	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.68	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:0	8.18	917	0.83	13.32	107	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.66	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:0	8.18	917	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:1	8.18	918	0.83	13.31	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:1	8.18	918	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:1	9.54	910	0.83	13.32	107	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:1	9.54	901	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:1	9.54	905	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:1	9.54	905	0.83	13.34	107	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:1	9.54	908	0.83	13.32	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:2	9.54	912	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:2	9.54	913	0.83	13.33	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:2	9.54	913	0.83	13.32	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:2	9.54	910	0.83	13.31	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:2	9.54	908	0.83	13.31	107	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:2	9.54	906	0.83	13.33	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:3	9.54	906	0.83	13.35	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:3	9.54	908	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:3	9.54	911	0.83	13.39	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:3	9.54	923	0.83	13.39	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:3	9.54	923	0.83	13.4	107	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:3	9.54	923	0.83	13.38	107	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:4	6.81	923	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:4	6.81	923	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:4	6.81	933	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:03:4	6.81	928	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:03:4	6.81	924	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:03:4	6.81	924	0.83	13.38	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:03:4	6.81	928	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.72	14.99	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:03:5	6.81	928	0.83	13.4	107	194	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.74	14.97	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:03:5	8.18	916	0.83	13.38	107	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.74	14.96	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:03:5	8.18	916	0.83	13.39	107	194	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.77	14.95	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:03:5	8.18	910	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.73	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:5	8.18	904	0.83	13.38	107	194	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.75	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:5	8.18	904	0.83	13.37	107	194	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.76	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:6	8.18	920	0.83	13.38	107	194	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.73	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:6	8.18	912	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.75	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:6	8.18	912	0.83	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.74	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:6	8.18	916	0.83	13.37	107	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.77	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:6	8.18	916	0.83	13.38	107	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.7	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:03:6	8.18	914	0.83	13.36	107	194	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.73	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:6	8.18	914	0.83	13.38	107	194	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.71	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:7	8.18	917	0.83	13.38	107	194	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.7	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:7	8.18	917	0.83	13.4	107	194	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.74	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:7	8.18	910	0.83	13.39	107	194	Full Load	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.75	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:7	8.18	910	0.83	13.39	107	195	Off Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:7	8.18	910	0.84	13.38	107	195	Off Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.7	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:7	8.18	909	0.84	13.38	107	195	Off Idle	92.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.65	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:8	8.18	909	0.86	13.37	107	194	Off Idle	91.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.6	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:03:8	8.18	911	0.87	13.37	107	194	Off Idle	91.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.5	14.87	1.01	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:03:8	8.18	914	0.89	13.37	107	194	Off Idle	90.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.46	14.88	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:03:8	9.54	918	0.92	13.36	107	194	Off Idle	90	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.27	14.88	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:03:8	9.54	918	0.93	13.36	107	194	Off Idle	89.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.23	14.86	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:03:8	9.54	923	0.96	13.35	107	194	Off Idle	88.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.06	14.85	1.01	4.9	3	ON	28 Pin	OFF	Removed	Disabled
03:16:03:9	9.54	916	0.98	13.38	107	194	Off Idle	87.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.97	14.84	1.01	5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:03:9	9.54	908	1.02	13.36	107	194	Off Idle	87.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.73	14.84	1.01	5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:03:9	9.54	911	1.05	13.37	107	194	Off Idle	86.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.67	14.84	1.01	5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:03:9	9.54	911	1.09	13.35	107	194	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.38	14.85	1.01	4.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:03:9	9.54	911	1.12	13.37	107	194	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.27	14.87	1.01	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:03:9	10.9	944	1.15	13.35	107	194	Off Idle	85	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.09	14.88	1.01	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:03:9	10.9	959	1.18	13.38	107	194	Off Idle	85	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6	14.88	1.01	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:04:0	10.9	959	1.2	13.37	107	194	Off Idle	85	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.84	14.91	1.02	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:04:0	10.9	959	1.23	13.38	107	194	Off Idle	85.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.77	14.93	1.02	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:04:0	8.18	975	1.26	13.38	107	195	Off Idle	85.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.58	14.96	1.02	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:04:0	8.18	1011	1.29	13.36	107	195	Off Idle	85.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.51	14.98	1.02	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:04:0	8.18	1011	1.33	13.39	107	195	Off Idle	85.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.35	14.99	1.02	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:04:0	8.18	1023	1.35	13.38	107	195	Off Idle	85.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.24	15	1.02	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:04:1	8.18	1035	1.37	13.39	107	195	Off Idle	85.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.11	15.01	1.02	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:04:1	8.18	1069	1.4	13.36	107	194	Off Idle	85.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.96	15.03	1.02	4.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:04:1	8.18	1062	1.42	13.38	107	194	Off Idle	85.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.91	15.03	1.02	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:04:1	8.18	1062	1.44	13.35	107	194	Off Idle	85.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.78	15.04	1.02	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:04:1	8.18	1068	1.47	13.38	107	194	Off Idle	85.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.67	15.05	1.03	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:04:1	8.18	1073	1.48	13.36	107	194	Off Idle	85.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.48	15.07	1.03	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:04:1	9.54	1090	1.5	13.38	107	194	Off Idle	85.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.42	15.08	1.03	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:04:2	9.54	1090	1.53	13.37	107	194	Off Idle	85.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.2	15.08	1.03	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:04:2	9.54	1158	1.55	13.36	107	194	Off Idle	85.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.04	15.1	1.03	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:2	9.54	1119	1.58	13.39	107	195	Off Idle	85.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.92	15.11	1.03	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:2	21.81	1119	1.6	13.37	107	195	Off Idle	85.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.83	15.09	1.03	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:2	21.81	1119	1.63	13.38	107	195	Off Idle	85.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.63	15.1	1.03	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:2	21.81	1176	1.66	13.39	107	194	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.45	15.09	1.03	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:04:3	20.45	1176	1.68	13.41	107	194	Off Idle	85.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.33	14.91	1.02	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:04:3	20.45	1188	1.7	13.41	107	194	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.21	14.93	1.02	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:04:3	20.45	1201	1.72	13.4	107	195	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.07	14.95	1.02	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:04:3	20.45	1208	1.75	13.41	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.01	14.92	1.02	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:04:3	20.45	1216	1.76	13.41	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.95	14.86	1.01	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:04:3	20.45	1242	1.78	13.39	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.94	14.78	1.01	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:4	21.81	1254	1.79	13.39	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.91	14.67	1	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:4	21.81	1254	1.8	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.87	14.54	0.99	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:4	21.81	1252	1.81	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.86	14.39	0.98	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:4	21.81	1252	1.82	13.38	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.85	14.41	0.98	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:4	21.81	1252	1.83	13.39	107	194	Off Idle	86.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.82	14.23	0.97	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:4	21.81	1264	1.83	13.39	107	194	Off Idle	86.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.8	14	0.95	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:4	21.81	1254	1.84	13.39	107	194	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.79	13.8	0.94	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:5	21.81	1254	1.84	13.4	107	194	Off Idle	86.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.74	13.62	0.93	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:5	21.81	1247	1.84	13.38	107	194	Off Idle	86.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.72	13.4	0.91	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:5	21.81	1240	1.84	13.38	107	194	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.71	13.28	0.9	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:5	21.81	1226	1.84	13.37	107	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.66	13.19	0.9	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:5	21.81	1219	1.84	13.38	107	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.65	13.12	0.89	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:04:8	21.81	1219	1.84	13.38	107	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.6	13.05	0.89	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:6	21.81	1211	1.84	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.57	13.01	0.89	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:6	21.81	1199	1.84	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.57	12.98	0.88	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:6	21.81	1185	1.84	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.52	12.95	0.88	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:6	21.81	1185	1.84	13.35	107	194	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.47	12.92	0.88	4.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:6	21.81	1170	1.84	13.36	107	194	Off Idle	86.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.46	12.91	0.88	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:6	21.81	1178	1.84	13.38	107	194	Off Idle	86.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.39	12.88	0.88	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:6	23.18	1178	1.84	13.37	107	194	Off Idle	86.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.37	12.84	0.87	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:7	23.18	1169	1.84	13.37	107	194	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.4	12.81	0.87	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:7	23.18	1160	1.84	13.38	107	194	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.37	12.79	0.87	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:7	23.18	1138	1.84	13.37	107	194	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.39	12.76	0.87	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:7	23.18	1148	1.83	13.38	107	194	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.33	12.71	0.87	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:7	23.18	1148	1.83	13.37	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.26	12.69	0.86	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:7	24.54	1131	1.83	13.39	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.27	12.67	0.86	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:8	24.54	1131	1.82	13.39	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.22	12.66	0.86	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:8	24.54	1124	1.82	13.37	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.27	12.64	0.86	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:8	24.54	1118	1.82	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.22	12.64	0.86	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:8	24.54	1109	1.81	13.35	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.24	12.66	0.86	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:8	24.54	1092	1.81	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.22	12.69	0.86	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:04:8	24.54	1083	1.81	13.37	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.15	12.7	0.87	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:04:9	24.54	1076	1.8	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.17	12.7	0.87	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:04:9	24.54	1076	1.8	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.09	12.71	0.87	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:04:9	24.54	1061	1.79	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.11	12.73	0.87	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:04:9	24.54	1061	1.79	13.39	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.01	12.74	0.87	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:04:9	23.18	1033	1.78	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.96	12.76	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:04:9	23.18	1033	1.78	13.39	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.97	12.78	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:04:9	23.18	1028	1.78	13.37	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.9	12.78	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:05:0	23.18	1017	1.77	13.39	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.94	12.79	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:05:0	23.18	1017	1.76	13.36	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.86	12.81	0.87	4.9	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:05:0	23.18	1008	1.76	13.38	107	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.94	12.82	0.87	4.9	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:05:0	23.18	1000	1.75	13.34	107	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.85	12.84	0.87	5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:0	23.18	974	1.75	13.36	107	195	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.89	12.84	0.87	5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:0	23.18	974	1.74	13.36	107	195	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.79	12.84	0.87	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:1	23.18	972	1.73	13.34	107	195	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.78	12.84	0.87	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:1	23.18	971	1.73	13.38	107	195	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.74	12.84	0.87	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:1	23.18	964	1.72	13.38	107	195	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.78	12.84	0.87	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:1	23.18	964	1.72	13.39	107	194	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.72	12.83	0.87	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:1	23.18	952	1.71	13.36	107	194	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.75	12.81	0.87	5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:1	23.18	941	1.71	13.38	107	194	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.66	12.8	0.87	5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:1	21.81	916	1.7	13.36	107	195	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.68	12.79	0.87	5.1	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:2	21.81	916	1.69	13.38	107	195	Off Idle	85.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.63	12.77	0.87	5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:2	21.81	915	1.69	13.37	107	195	Off Idle	85.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.63	12.75	0.87	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:2	21.81	915	1.68	13.41	107	195	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.54	12.74	0.87	5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:2	21.81	907	1.68	13.39	107	195	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.56	12.71	0.87	5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:2	21.81	907	1.67	13.37	107	194	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.51	12.68	0.86	5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:2	21.81	900	1.66	13.41	107	194	Off Idle	85.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.56	12.64	0.86	5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:3	21.81	894	1.66	13.39	107	194	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.5	12.64	0.86	5.1	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:3	21.81	875	1.65	13.41	107	195	Off Idle	85.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.54	12.6	0.86	5.1	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:3	21.81	875	1.65	13.39	107	195	Off Idle	85.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.5	12.6	0.86	5.1	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:3	21.81	875	1.64	13.42	107	195	Off Idle	85.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.47	12.54	0.85	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:3	21.81	880	1.63	13.4	107	195	Off Idle	85	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.44	12.5	0.85	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:3	21.81	880	1.63	13.4	107	195	Off Idle	85	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.47	12.44	0.85	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:4	20.45	890	1.62	13.39	107	195	Off Idle	84.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.45	12.39	0.84	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:4	20.45	900	1.62	13.39	107	195	Off Idle	84.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.49	12.35	0.84	4.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:05:4	20.45	911	1.61	13.37	107	195	Off Idle	84.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.48	12.29	0.84	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:05:4	20.45	911	1.61	13.38	107	195	Off Idle	84.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.46	12.28	0.84	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:05:4	20.45	940	1.61	13.35	107	195	Off Idle	84.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.49	12.16	0.83	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:05:4	20.45	940	1.61	13.39	107	195	Off Idle	84.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.51	12.11	0.83	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:05:4	20.45	979	1.61	13.35	107	195	Off Idle	84.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.52	12.09	0.82	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:05:5	20.45	979	1.61	13.4	107	195	Off Idle	84.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.56	12.04	0.82	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:05:5	19.09	998	1.61	13.39	107	195	Off Idle	85	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.63	12.01	0.82	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:05:5	19.09	1016	1.61	13.41	107	195	Off Idle	85	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.68	11.94	0.81	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:05:5	19.09	1034	1.61	13.4	107	195	Off Idle	85.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.65	11.89	0.81	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:05:5	19.09	1034	1.62	13.42	107	195	Off Idle	85.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.77	11.86	0.81	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:05:5	19.09	1060	1.62	13.42	107	195	Off Idle	85.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.72	11.83	0.81	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:05:6	19.09	1086	1.63	13.39	107	195	Off Idle	85.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.79	11.8	0.8	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:05:6	19.09	1086	1.64	13.42	107	195	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.83	11.77	0.8	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:6	19.09	1096	1.65	13.39	107	195	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.86	11.74	0.8	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:6	19.09	1118	1.66	13.4	107	195	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.91	11.71	0.8	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:6	19.09	1128	1.67	13.37	107	195	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.91	11.67	0.79	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:6	20.45	1128	1.68	13.36	107	195	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.96	11.65	0.79	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:6	20.45	1131	1.69	13.39	107	195	Off Idle	85.7	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.96	11.63	0.79	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:7	20.45	1132	1.7	13.38	107	195	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.98	11.62	0.79	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:7	20.45	1152	1.71	13.4	107	195	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.97	11.59	0.79	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:7	20.45	1152	1.72	13.37	107	195	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.96	11.59	0.79	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:7	20.45	1154	1.72	13.4	107	194	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.03	11.6	0.79	4.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:7	20.45	1154	1.73	13.4	107	194	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.01	11.6	0.79	4.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:7	20.45	1159	1.74	13.38	107	195	Off Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.01	11.61	0.79	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:8	20.45	1172	1.75	13.41	107	195	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.07	11.62	0.79	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:8	20.45	1184	1.76	13.39	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.1	11.63	0.79	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:8	21.81	1195	1.76	13.38	107	195	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.15	11.65	0.79	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:8	21.81	1195	1.77	13.39	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.18	11.66	0.79	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:05:8	21.81	1222	1.77	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.24	11.68	0.8	4.3	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:05:8	20.45	1220	1.77	13.38	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.27	11.72	0.8	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:05:9	20.45	1262	1.78	13.4	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.27	11.73	0.8	4.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:05:9	20.45	1262	1.78	13.39	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.33	11.77	0.8	4.3	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:05:9	21.81	1269	1.78	13.4	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.38	11.82	0.81	4.2	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:05:9	21.81	1284	1.79	13.4	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.5	11.87	0.81	4.2	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:05:9	21.81	1292	1.79	13.4	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.57	11.92	0.81	4.2	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:05:9	23.18	1308	1.79	13.38	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.62	11.99	0.82	4.2	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:05:9	23.18	1319	1.79	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.75	12.06	0.82	4.3	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:06:0	23.18	1322	1.79	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.83	12.15	0.83	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:06:0	23.18	1328	1.79	13.39	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.91	12.23	0.83	4.2	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:06:0	23.18	1333	1.79	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.03	12.31	0.84	4.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:0	23.18	1338	1.79	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.18	12.43	0.85	4.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:0	23.18	1355	1.79	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.25	12.52	0.85	4.3	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:0	23.18	1353	1.79	13.37	107	195	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.32	12.61	0.86	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:1	23.18	1353	1.78	13.38	107	195	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.41	12.72	0.87	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:1	23.18	1362	1.78	13.39	107	195	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.53	12.78	0.87	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:1	23.18	1365	1.78	13.38	107	195	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.6	12.84	0.87	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:06:1	23.18	1367	1.78	13.37	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.71	12.88	0.88	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:06:1	23.18	1367	1.77	13.37	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.83	12.96	0.88	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:06:1	23.18	1375	1.77	13.38	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.92	12.99	0.88	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:1	23.18	1389	1.76	13.4	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.98	13.03	0.89	4.2	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:2	23.18	1402	1.76	13.39	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.05	13.08	0.89	4.2	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:2	23.18	1413	1.75	13.4	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.15	13.1	0.89	4.2	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:2	23.18	1413	1.75	13.4	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.17	13.13	0.89	4.1	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:2	23.18	1429	1.74	13.38	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.27	13.16	0.9	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:06:2	24.54	1451	1.74	13.38	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.38	13.2	0.9	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:06:2	24.54	1477	1.73	13.4	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.5	13.24	0.9	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:06:3	24.54	1477	1.73	13.39	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.58	13.27	0.9	4.1	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:06:3	24.54	1453	1.72	13.38	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.58	13.29	0.91	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:06:3	24.54	1482	1.71	13.39	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.79	13.33	0.91	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:06:3	24.54	1480	1.7	13.4	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.95	13.36	0.91	4.3	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:06:3	24.54	1480	1.69	13.41	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.08	13.4	0.91	4.3	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:06:3	24.54	1486	1.69	13.39	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.17	13.44	0.92	4.3	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:06:4	24.54	1474	1.68	13.39	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.28	13.5	0.92	4.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:06:4	24.54	1474	1.67	13.38	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.39	13.54	0.92	4.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:06:4	25.9	1496	1.66	13.38	107	195	Off Idle	86.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.48	13.57	0.92	4.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:06:4	25.9	1500	1.65	13.39	107	195	Off Idle	86.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.51	13.63	0.93	4.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:06:4	25.9	1500	1.64	13.4	107	195	Off Idle	86.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.69	13.66	0.93	4.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:06:4	25.9	1493	1.64	13.39	107	195	Off Idle	86.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.77	13.76	0.94	4.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:06:4	25.9	1497	1.63	13.38	107	195	Off Idle	86.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.85	13.84	0.94	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:5	25.9	1506	1.62	13.37	107	195	Off Idle	86.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.94	13.91	0.95	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:5	25.9	1506	1.61	13.38	107	195	Off Idle	86.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.05	14.03	0.96	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:5	25.9	1508	1.6	13.38	107	195	Off Idle	86.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.03	14.11	0.96	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:5	25.9	1500	1.6	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.09	14.17	0.97	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:5	25.9	1508	1.59	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.13	14.23	0.97	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:5	27.27	1514	1.58	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.17	14.3	0.97	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:6	27.27	1513	1.58	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.21	14.36	0.98	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:6	27.27	1518	1.57	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.3	14.45	0.98	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:6	27.27	1518	1.57	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.33	14.49	0.99	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:6	27.27	1526	1.56	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.37	14.54	0.99	4.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:6	27.27	1541	1.56	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.38	14.6	0.99	4.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:6	27.27	1557	1.56	13.4	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.44	14.63	1	4.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:6	27.27	1557	1.56	13.4	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.45	14.68	1	4.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:7	27.27	1566	1.55	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.47	14.71	1	4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:06:7	27.27	1577	1.55	13.38	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.56	14.75	1.01	4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:7	27.27	1577	1.55	13.37	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.63	14.77	1.01	4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:7	27.27	1596	1.55	13.37	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.68	14.79	1.01	4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:7	27.27	1598	1.55	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.71	14.83	1.01	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:7	27.27	1598	1.55	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.81	14.87	1.01	4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:8	27.27	1602	1.54	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.88	14.92	1.02	3.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:8	27.27	1619	1.54	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.99	15.02	1.02	4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:8	27.27	1619	1.54	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.06	15.08	1.03	4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:06:8	27.27	1603	1.53	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.13	15.14	1.03	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:06:8	27.27	1604	1.52	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.19	15.21	1.04	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:06:8	27.27	1608	1.52	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.24	15.3	1.04	4.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:9	28.63	1600	1.51	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.32	15.38	1.05	4.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:9	28.63	1587	1.5	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.4	15.46	1.05	4.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:9	28.63	1581	1.5	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.44	15.53	1.06	4.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:9	28.63	1578	1.49	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.48	15.58	1.06	4.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:9	28.63	1578	1.48	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.52	15.62	1.06	4.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:9	28.63	1573	1.47	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.53	15.65	1.07	4.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:06:9	28.63	1567	1.46	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.59	15.7	1.07	4.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:07:0	28.63	1575	1.46	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.63	15.72	1.07	4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:07:0	28.63	1574	1.45	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.66	15.73	1.07	4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:07:0	28.63	1577	1.44	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.7	15.74	1.07	4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:07:0	28.63	1577	1.44	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.72	15.74	1.07	4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:07:0	28.63	1585	1.43	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.74	15.73	1.07	4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:07:0	28.63	1591	1.42	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.77	15.71	1.07	4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:07:1	28.63	1603	1.42	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.81	15.69	1.07	4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:07:1	28.63	1615	1.41	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.82	15.66	1.07	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:07:1	28.63	1618	1.41	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.88	15.65	1.07	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:1	28.63	1622	1.41	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.94	15.6	1.06	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:1	28.63	1643	1.41	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.98	15.57	1.06	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:1	28.63	1643	1.41	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.03	15.52	1.06	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:1	28.63	1646	1.4	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.05	15.49	1.06	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:2	28.63	1655	1.4	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.03	15.46	1.05	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:2	28.63	1655	1.4	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.08	15.46	1.05	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:2	28.63	1657	1.4	13.39	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.11	15.45	1.05	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:2	28.63	1657	1.4	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.14	15.43	1.05	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:2	28.63	1660	1.4	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.18	15.41	1.05	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:2	28.63	1657	1.4	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.24	15.41	1.05	3.9	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:07:3	28.63	1661	1.4	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.3	15.41	1.05	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:3	28.63	1661	1.39	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.32	15.41	1.05	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:3	29.99	1644	1.39	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.42	15.43	1.05	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:07:3	29.99	1638	1.38	13.36	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.46	15.44	1.05	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:07:3	29.99	1635	1.37	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.49	15.46	1.05	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:07:3	29.99	1630	1.36	13.36	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.52	15.47	1.05	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:07:4	29.99	1628	1.36	13.36	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.54	15.48	1.05	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:07:4	29.99	1621	1.35	13.36	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.55	15.5	1.06	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:07:4	29.99	1621	1.34	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.65	15.51	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:4	29.99	1618	1.33	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.69	15.54	1.06	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:4	29.99	1618	1.32	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.73	15.56	1.06	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:4	29.99	1621	1.32	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.75	15.57	1.06	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:4	29.99	1620	1.31	13.35	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.76	15.58	1.06	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:5	29.99	1620	1.31	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.76	15.58	1.06	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:5	29.99	1622	1.3	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.74	15.57	1.06	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:5	29.99	1627	1.29	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.78	15.57	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:5	29.99	1630	1.28	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.78	15.57	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:5	29.99	1631	1.27	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.79	15.56	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:5	29.99	1633	1.27	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.8	15.54	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:6	29.99	1638	1.26	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.83	15.54	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:6	29.99	1643	1.26	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.84	15.53	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:6	29.99	1643	1.26	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.89	15.52	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:6	29.99	1649	1.26	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.96	15.52	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:6	29.99	1652	1.25	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.96	15.52	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:6	29.99	1654	1.25	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9	15.52	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:6	29.99	1654	1.25	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9	15.52	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:7	29.99	1658	1.25	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.01	15.52	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:7	29.99	1662	1.25	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.04	15.53	1.06	3.9	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:7	29.99	1665	1.25	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.04	15.53	1.06	3.9	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:7	29.99	1665	1.25	13.39	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.07	15.53	1.06	3.9	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:7	29.99	1664	1.25	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.09	15.52	1.06	3.9	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:7	29.99	1663	1.24	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	15.52	1.06	3.9	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:8	29.99	1656	1.24	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.1	15.51	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:8	29.99	1656	1.24	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	15.5	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:8	29.99	1654	1.24	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	15.49	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:8	29.99	1654	1.24	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	15.48	1.05	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:8	29.99	1642	1.24	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.12	15.48	1.05	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:8	29.99	1644	1.24	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.17	15.46	1.05	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:9	29.99	1640	1.24	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.16	15.46	1.05	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:9	29.99	1640	1.24	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.16	15.47	1.05	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:9	29.99	1639	1.24	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.15	15.47	1.05	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:9	29.99	1639	1.24	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.14	15.49	1.06	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:9	29.99	1639	1.24	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.14	15.5	1.06	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:9	29.99	1632	1.24	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.14	15.51	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:07:9	29.99	1641	1.24	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.12	15.53	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:0	29.99	1639	1.24	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	15.55	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:0	29.99	1639	1.24	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.12	15.56	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:0	29.99	1644	1.24	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.13	15.6	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:0	29.99	1647	1.24	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.13	15.61	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:0	29.99	1650	1.24	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.14	15.62	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:0	29.99	1652	1.24	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.12	15.62	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:1	29.99	1656	1.25	13.36	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.11	15.63	1.06	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:1	29.99	1659	1.25	13.36	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.13	15.64	1.07	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:1	29.99	1659	1.25	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.13	15.66	1.07	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:1	29.99	1657	1.25	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	15.66	1.07	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:1	29.99	1655	1.25	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.13	15.68	1.07	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:1	29.99	1654	1.25	13.36	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.12	15.69	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:1	29.99	1654	1.25	13.35	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	15.71	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:08:2	29.99	1655	1.25	13.35	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	15.73	1.07	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:2	29.99	1654	1.26	13.34	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.14	15.77	1.07	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:2	29.99	1653	1.26	13.34	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.14	15.79	1.08	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:08:2	29.99	1649	1.26	13.35	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.13	15.81	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:2	29.99	1649	1.26	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.12	15.84	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:2	29.99	1646	1.27	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	15.85	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:3	29.99	1646	1.27	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.08	15.86	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:3	29.99	1646	1.27	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.06	15.87	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:3	29.99	1643	1.27	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.08	15.88	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:3	29.99	1644	1.28	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.04	15.9	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:3	29.99	1642	1.28	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.04	15.93	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:3	29.99	1642	1.28	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.97	15.94	1.09	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:4	29.99	1647	1.29	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.96	15.94	1.09	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:4	29.99	1648	1.29	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.94	15.94	1.09	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:4	29.99	1646	1.29	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.94	15.73	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:4	29.99	1646	1.29	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.98	15.73	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:4	29.99	1646	1.3	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.01	15.73	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:4	29.99	1653	1.3	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.01	15.72	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:4	29.99	1653	1.3	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.98	15.71	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:5	29.99	1653	1.3	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.94	15.69	1.07	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:5	29.99	1648	1.3	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.94	15.67	1.07	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:5	29.99	1649	1.3	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.94	15.64	1.07	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:5	29.99	1650	1.31	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.96	15.63	1.06	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:5	29.99	1656	1.31	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	15.81	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:5	29.99	1656	1.31	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.98	15.8	1.08	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:6	29.99	1660	1.31	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.96	15.8	1.08	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:6	29.99	1661	1.31	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.97	15.79	1.08	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:6	29.99	1662	1.31	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	15.77	1.07	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:6	29.99	1662	1.31	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.97	15.76	1.07	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:6	29.99	1653	1.31	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.98	15.76	1.07	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:6	29.99	1653	1.31	13.4	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	15.75	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:6	29.99	1655	1.31	13.39	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	15.75	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:7	29.99	1656	1.31	13.4	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.96	15.74	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:7	29.99	1656	1.31	13.39	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.96	15.73	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:7	29.99	1656	1.31	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.95	15.72	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:7	29.99	1656	1.31	13.37	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.97	15.71	1.07	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:7	29.99	1654	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9	15.69	1.07	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:7	29.99	1654	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.01	15.69	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:8	29.99	1650	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9	15.67	1.07	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:08:8	29.99	1652	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.99	15.64	1.07	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:8	29.99	1652	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.99	15.63	1.06	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:8	29.99	1653	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.96	15.6	1.06	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:8	29.99	1654	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.97	15.57	1.06	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:8	29.99	1654	1.31	13.35	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.97	15.54	1.06	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:9	29.99	1659	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.96	15.52	1.06	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:9	29.99	1659	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.99	15.5	1.06	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:9	29.99	1665	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.99	15.47	1.05	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:9	29.99	1665	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.99	15.45	1.05	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:9	29.99	1667	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9	15.43	1.05	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:9	29.99	1667	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.01	15.42	1.05	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:08:9	29.99	1668	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.01	15.41	1.05	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:0	29.99	1666	1.31	13.4	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.01	15.39	1.05	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:09:0	29.99	1666	1.31	13.4	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9	15.37	1.05	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:09:0	29.99	1679	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.01	15.35	1.05	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:0	29.99	1671	1.31	13.39	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.01	15.34	1.04	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:0	29.99	1667	1.31	13.39	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.01	15.31	1.04	4.1	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:0	29.99	1667	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.02	15.3	1.04	4.1	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:1	29.99	1656	1.31	13.39	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.04	15.29	1.04	4	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:09:1	29.99	1667	1.31	13.39	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.04	15.28	1.04	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:1	29.99	1667	1.31	13.39	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.05	15.27	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:1	29.99	1664	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.04	15.26	1.04	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:09:1	29.99	1663	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.04	15.25	1.04	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:09:1	29.99	1663	1.31	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.04	15.25	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:1	29.99	1666	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.02	15.25	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:2	29.99	1663	1.31	13.37	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.03	15.25	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:2	29.99	1662	1.31	13.37	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9	15.25	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:2	29.99	1666	1.31	13.35	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.01	15.24	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:2	29.99	1672	1.3	13.36	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.06	15.23	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:2	29.99	1672	1.29	13.35	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.13	15.22	1.04	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:16:09:2	29.99	1678	1.28	13.36	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.17	15.22	1.04	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:09:3	29.99	1671	1.27	13.38	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.3	15.21	1.04	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:09:3	29.99	1665	1.26	13.38	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.35	15.21	1.04	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:3	29.99	1665	1.25	13.38	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.37	15.2	1.04	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:3	29.99	1678	1.24	13.4	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.4	15.19	1.03	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:3	29.99	1677	1.23	13.38	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.44	15.17	1.03	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:3	29.99	1676	1.22	13.39	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.46	15.17	1.03	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:4	29.99	1676	1.21	13.38	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.5	15.17	1.03	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:4	29.99	1676	1.2	13.37	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.51	15.17	1.03	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:4	29.99	1671	1.19	13.37	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.56	15.15	1.03	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:4	29.99	1666	1.18	13.38	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.53	15.14	1.03	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:4	29.99	1669	1.17	13.37	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.53	15.13	1.03	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:4	31.36	1660	1.16	13.37	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.54	15.13	1.03	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:4	31.36	1650	1.15	13.37	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.55	15.11	1.03	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:5	31.36	1646	1.14	13.38	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.57	15.13	1.03	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:5	31.36	1646	1.13	13.39	107	195	Off Idle	86.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.6	15.12	1.03	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:5	31.36	1646	1.13	13.39	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.6	15.11	1.03	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:5	31.36	1648	1.13	13.4	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.59	15.1	1.03	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:5	31.36	1637	1.13	13.39	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.59	15.11	1.03	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:5	31.36	1635	1.13	13.39	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.59	15.1	1.03	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:6	31.36	1628	1.13	13.39	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.57	15.09	1.03	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:6	29.99	1634	1.13	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.56	15.1	1.03	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:6	29.99	1636	1.13	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.57	15.1	1.03	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:6	29.99	1636	1.13	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.57	15.07	1.03	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:6	29.99	1636	1.13	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.57	15.07	1.03	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:6	29.99	1638	1.13	13.39	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.58	15.07	1.03	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:6	29.99	1641	1.13	13.39	108	195	Off Idle	86.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	15.06	1.03	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:7	29.99	1642	1.13	13.39	108	195	Off Idle	86.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.56	15.05	1.02	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:7	29.99	1644	1.13	13.38	108	195	Off Idle	86.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.58	15.04	1.02	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:09:7	29.99	1646	1.12	13.39	107	195	Full Load	86.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.59	15.05	1.03	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:7	29.99	1650	1.12	13.39	107	195	Idle	86.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.66	15.04	1.02	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:7	29.99	1650	1.1	13.39	107	195	Idle	86.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.69	15.04	1.02	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:09:7	29.99	1650	1.08	13.39	107	195	Idle	86.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.77	15.02	1.02	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:8	29.99	1650	1.08	13.38	107	195	Idle	86.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.8	15	1.02	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:8	29.99	1651	1.07	13.39	107	195	Idle	86.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.86	14.99	1.02	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:09:8	29.99	1651	1.07	13.38	107	195	Idle	86.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.9	14.98	1.02	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:09:8	29.99	1646	1.06	13.39	107	195	Idle	86.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.93	14.94	1.02	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:8	29.99	1637	1.05	13.39	107	195	Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.96	14.91	1.02	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:8	29.99	1612	1.04	13.38	107	195	Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10	14.89	1.01	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:9	29.99	1612	1.03	13.38	107	195	Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.01	14.89	1.01	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:9	28.63	1617	1.02	13.38	107	195	Idle	86.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.04	14.89	1.01	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:9	28.63	1607	1.01	13.39	107	195	Idle	86.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.06	14.92	1.02	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:9	28.63	1601	1	13.37	107	195	Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.09	14.98	1.02	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:9	28.63	1601	0.99	13.37	107	195	Idle	86.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.1	15.01	1.02	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:9	28.63	1601	0.99	13.36	107	195	Idle	86.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.08	15.05	1.03	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:09:9	28.63	1607	0.97	13.36	107	195	Idle	86	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.09	15.15	1.03	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:0	28.63	1609	0.96	13.38	107	195	Idle	85.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.08	15.21	1.04	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:10:0	28.63	1609	0.96	13.38	107	195	Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.09	15.21	1.04	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:0	28.63	1602	0.95	13.37	107	195	Idle	85.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.1	15.28	1.04	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:0	27.27	1624	0.96	13.37	107	195	Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.1	15.33	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:0	27.27	1630	0.96	13.38	107	195	Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.11	15.36	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:0	27.27	1630	0.97	13.37	107	195	Idle	85.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.12	15.38	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:1	27.27	1633	0.97	13.37	107	195	Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.08	15.4	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:1	27.27	1636	0.97	13.37	107	195	Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.08	15.4	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:1	27.27	1637	0.96	13.37	107	195	Idle	86	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.1	15.41	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:1	27.27	1639	0.97	13.38	107	195	Idle	86.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.1	15.41	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:1	27.27	1641	0.97	13.39	107	195	Idle	86.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.13	15.4	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:1	27.27	1623	0.97	13.38	107	195	Idle	87	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.17	15.38	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:1	25.9	1635	0.97	13.39	107	195	Idle	87.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.17	15.36	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:2	25.9	1635	0.97	13.38	107	195	Idle	87.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.19	15.34	1.05	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:2	25.9	1631	0.97	13.37	107	195	Idle	87.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.22	15.32	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:2	25.9	1622	0.97	13.37	107	195	Idle	87.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.2	15.31	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:2	25.9	1622	0.97	13.38	107	195	Idle	88	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.22	15.26	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:2	25.9	1618	0.97	13.37	107	195	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.22	15.23	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:2	25.9	1609	0.97	13.39	107	195	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.2	15.19	1.03	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:3	25.9	1599	0.97	13.38	107	195	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.23	15.17	1.03	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:3	25.9	1599	0.97	13.38	107	195	Idle	88.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.23	15.14	1.03	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:3	25.9	1581	0.97	13.36	107	195	Idle	88.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.2	15.12	1.03	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:3	24.54	1584	0.97	13.37	107	195	Idle	88.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.21	15.11	1.03	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:3	24.54	1571	0.97	13.37	107	195	Idle	88.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.2	15.11	1.03	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:3	24.54	1581	0.96	13.38	107	195	Idle	88.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.21	15.1	1.03	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:4	24.54	1579	0.96	13.38	107	195	Idle	88.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.19	15.1	1.03	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:4	24.54	1590	0.96	13.39	107	195	Idle	88.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.18	15.11	1.03	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:4	24.54	1590	0.96	13.37	107	195	Idle	88.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.15	15.13	1.03	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:4	24.54	1568	0.96	13.38	107	195	Idle	88.2	0	2	132	944 Turbo	0.2	Rich	1	14.6	-10.14	15.16	1.03	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:4	24.54	1564	0.95	13.38	107	195	Idle	88.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-10.15	15.18	1.03	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:4	24.54	1552	0.95	13.38	107	195	Idle	88.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-10.15	15.2	1.04	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:4	23.18	1552	0.95	13.38	107	195	Idle	88.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-10.18	15.22	1.04	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:5	23.18	1565	0.95	13.38	107	195	Idle	88.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.19	15.25	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:5	23.18	1566	0.95	13.38	107	195	Idle	88.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.17	15.26	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:5	23.18	1566	0.95	13.37	107	195	Idle	89.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.15	15.27	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:5	23.18	1566	0.95	13.37	107	195	Full Load	89.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.13	15.28	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:5	23.18	1566	0.95	13.37	107	195	Off Idle	89.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.1	15.29	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:6	23.18	1565	0.95	13.37	107	195	Off Idle	90.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.06	15.27	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:6	23.18	1563	0.96	13.38	107	195	Off Idle	90.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.03	15.27	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:6	23.18	1562	0.96	13.39	107	195	Off Idle	91.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.98	15.28	1.04	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:10:6	23.18	1551	0.97	13.38	107	195	Off Idle	91.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.9	15.27	1.04	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:10:6	21.81	1568	0.98	13.38	107	195	Off Idle	90.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.87	15.28	1.04	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:10:6	21.81	1567	0.99	13.37	107	195	Off Idle	90.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.83	15.27	1.04	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:10:6	21.81	1558	1	13.39	107	195	Off Idle	90.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.79	15.25	1.04	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:10:6	21.81	1557	1.01	13.39	107	195	Off Idle	90.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.75	15.23	1.04	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:10:7	21.81	1557	1.02	13.38	107	195	Off Idle	90.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.7	15.22	1.04	4.1	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:10:7	21.81	1559	1.03	13.38	107	195	Off Idle	89.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.66	15.19	1.04	4.1	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:10:7	21.81	1559	1.05	13.38	107	195	Off Idle	89.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.59	15.19	1.03	4.1	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:10:7	21.81	1560	1.06	13.36	107	195	Off Idle	88.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.54	15.15	1.03	4.1	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:10:7	21.81	1560	1.07	13.38	107	195	Off Idle	88.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.48	15.12	1.03	4.1	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:10:7	21.81	1562	1.09	13.37	107	195	Off Idle	87.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.45	15.08	1.03	4.1	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:10:8	23.18	1562	1.11	13.37	107	195	Off Idle	87.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.41	15.06	1.03	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:10:8	23.18	1564	1.11	13.36	107	195	Off Idle	87	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.36	15.06	1.03	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:10:8	23.18	1558	1.14	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.3	15.06	1.03	4.1	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:10:8	23.18	1561	1.14	13.38	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.25	15.06	1.03	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:10:8	23.18	1561	1.16	13.37	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.16	15.05	1.03	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:10:8	23.18	1562	1.17	13.38	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.12	15.03	1.02	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:10:9	23.18	1562	1.19	13.39	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.05	15.02	1.02	4	2	ON	28 Pin	OFF	Removed	Disabled
03:16:10:9	23.18	1560	1.21	13.38	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9	15	1.02	4	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:10:9	23.18	1565	1.22	13.37	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.92	15	1.02	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:10:9	23.18	1557	1.23	13.37	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.83	14.97	1.02	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:10:9	24.54	1559	1.25	13.36	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.74	14.93	1.02	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:10:9	24.54	1559	1.27	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.67	14.9	1.02	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:10:9	24.54	1565	1.28	13.36	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.52	14.84	1.01	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:11:0	24.54	1574	1.3	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.48	14.81	1.01	4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:11:0	24.54	1583	1.31	13.36	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.4	14.8	1.01	4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:11:0	24.54	1600	1.34	13.38	108	196	Off Idle	86.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.24	14.77	1.01	4.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:11:0	24.54	1617	1.36	13.38	107	196	Off Idle	86.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.17	14.75	1	4.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:11:0	24.54	1617	1.39	13.38	107	196	Off Idle	86.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.1	14.75	1	4.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:11:1	25.9	1613	1.41	13.38	107	196	Off Idle	86.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.99	14.76	1.01	4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:11:1	25.9	1620	1.42	13.38	108	196	Off Idle	86.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.89	14.76	1.01	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:11:1	25.9	1625	1.44	13.38	108	196	Off Idle	86.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	14.78	1.01	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:11:1	25.9	1625	1.46	13.38	108	196	Off Idle	86.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	14.8	1.01	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:11:1	25.9	1638	1.48	13.38	107	196	Off Idle	86.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	14.8	1.01	4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:11:1	25.9	1642	1.51	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.57	14.82	1.01	4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:11:1	25.9	1638	1.53	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.49	14.83	1.01	4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:2	25.9	1638	1.54	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.41	14.84	1.01	4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:2	25.9	1643	1.56	13.38	107	195	Off Idle	86.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.34	14.83	1.01	4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:2	27.27	1621	1.56	13.38	108	195	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.27	14.83	1.01	4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:2	27.27	1621	1.58	13.38	108	195	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.17	14.84	1.01	4.1	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:2	27.27	1608	1.59	13.38	108	195	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.08	14.84	1.01	4.1	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:2	27.27	1586	1.6	13.38	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.02	14.83	1.01	4.1	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:3	27.27	1574	1.62	13.39	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.96	14.83	1.01	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:11:3	27.27	1570	1.63	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.89	14.83	1.01	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:11:3	27.27	1566	1.64	13.37	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.89	14.84	1.01	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:11:3	27.27	1560	1.65	13.38	107	195	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.84	14.83	1.01	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:11:3	27.27	1576	1.66	13.37	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.75	14.83	1.01	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:11:3	27.27	1576	1.67	13.39	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.63	14.81	1.01	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:11:4	28.63	1564	1.68	13.37	108	196	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.54	14.78	1.01	4.1	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:11:4	28.63	1587	1.69	13.37	108	196	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.48	14.76	1.01	4	3	ON	28 Pin	OFF	Removed	Disabled
03:16:11:4	28.63	1587	1.7	13.36	108	196	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.39	14.74	1	4	3	ON	28 Pin	OFF	Removed	Disabled
03:16:11:4	28.63	1620	1.71	13.37	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.28	14.7	1	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:4	28.63	1653	1.73	13.37	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.16	14.67	1	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:4	28.63	1661	1.74	13.38	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.97	14.61	0.99	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:4	28.63	1661	1.75	13.38	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.86	14.57	0.99	3.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:11:5	28.63	1685	1.76	13.38	108	195	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.74	14.55	0.99	3.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:11:5	28.63	1685	1.77	13.37	108	195	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.68	14.53	0.99	3.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:11:5	27.27	1715	1.78	13.38	108	196	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.63	14.51	0.99	3.8	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:11:5	27.27	1715	1.79	13.36	107	196	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.58	14.48	0.99	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:5	27.27	1733	1.81	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.56	14.45	0.98	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:5	27.27	1738	1.83	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.54	14.43	0.98	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:6	27.27	1738	1.83	13.38	107	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.54	14.42	0.98	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:6	27.27	1744	1.85	13.37	107	196	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.49	14.39	0.98	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:6	27.27	1730	1.87	13.37	107	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.5	14.35	0.98	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:6	27.27	1731	1.88	13.37	107	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.47	14.31	0.97	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:6	28.63	1731	1.89	13.37	107	196	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.43	14.26	0.97	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:6	28.63	1713	1.9	13.37	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.39	14.23	0.97	4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:11:6	28.63	1704	1.91	13.36	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.32	14.2	0.97	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:11:7	28.63	1700	1.92	13.36	108	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.23	14.17	0.97	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:11:7	28.63	1703	1.92	13.35	108	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.19	14.17	0.97	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:11:7	28.63	1700	1.93	13.35	108	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.14	14.16	0.96	3.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:11:7	28.63	1718	1.94	13.37	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.09	14.15	0.96	3.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:11:7	28.63	1728	1.95	13.37	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.94	14.17	0.96	3.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:11:7	28.63	1741	1.95	13.37	108	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.92	14.16	0.96	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:11:8	28.63	1741	1.96	13.39	108	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.8	14.17	0.97	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:11:8	28.63	1772	1.97	13.36	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.77	14.16	0.96	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:11:8	28.63	1788	1.99	13.37	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.58	14.16	0.96	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:11:8	28.63	1809	2	13.37	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.41	14.17	0.96	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:11:8	28.63	1809	2.02	13.38	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.29	14.18	0.97	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:11:8	28.63	1829	2.03	13.39	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.19	14.19	0.97	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:11:9	28.63	1852	2.05	13.38	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.1	14.21	0.97	3.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:9	28.63	1859	2.06	13.39	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.04	14.24	0.97	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:9	28.63	1884	2.08	13.41	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.02	14.29	0.97	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:9	28.63	1884	2.09	13.41	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.97	14.32	0.98	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:11:9	28.63	1904	2.11	13.41	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.85	14.37	0.98	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:11:9	28.63	1904	2.12	13.38	108	196	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.82	14.41	0.98	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:11:9	28.63	1904	2.13	13.38	108	196	Off Idle	86.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.77	14.45	0.98	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:0	28.63	1907	2.15	13.39	107	196	Off Idle	86.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.78	14.51	0.99	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:0	28.63	1902	2.16	13.4	107	196	Off Idle	86.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.77	14.55	0.99	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:0	28.63	1896	2.17	13.39	107	196	Off Idle	86.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.73	14.58	0.99	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:0	28.63	1896	2.19	13.39	108	196	Off Idle	86.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.66	14.64	1	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:0	28.63	1894	2.19	13.39	108	196	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.61	14.66	1	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:0	28.63	1899	2.2	13.37	108	196	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.52	14.68	1	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:1	28.63	1901	2.21	13.38	107	196	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.49	14.69	1	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:1	28.63	1910	2.22	13.39	107	196	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.47	14.67	1	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:1	28.63	1910	2.22	13.36	108	196	Off Idle	85.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.38	14.65	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:12:1	28.63	1924	2.23	13.38	108	196	Off Idle	85.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.32	14.61	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:1	28.63	1942	2.23	13.38	108	196	Off Idle	85.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.23	14.56	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:1	28.63	1942	2.24	13.37	108	196	Off Idle	85.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.12	14.5	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:1	28.63	1962	2.25	13.39	108	196	Off Idle	85.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.05	14.46	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:2	28.63	1984	2.26	13.38	108	196	Off Idle	85.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.92	14.42	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:2	28.63	1984	2.28	13.38	108	196	Off Idle	85.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.69	14.39	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:2	28.63	2014	2.29	13.39	108	196	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.58	14.36	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:2	28.63	2076	2.3	13.37	108	196	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.47	14.35	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:12:2	29.99	2062	2.31	13.36	108	195	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.37	14.36	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:12:2	29.99	2070	2.33	13.36	108	195	Off Idle	85.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.3	14.37	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:12:3	29.99	2086	2.34	13.36	108	195	Off Idle	85.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.26	14.39	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:12:3	29.99	2100	2.35	13.36	108	196	Off Idle	85.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.23	14.44	0.98	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:3	29.99	2113	2.36	13.37	108	196	Off Idle	85.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.21	14.46	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:3	29.99	2126	2.38	13.37	107	196	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.26	14.51	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:3	29.99	2133	2.39	13.38	107	196	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.28	14.55	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:3	29.99	2134	2.4	13.39	107	196	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.31	14.58	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:4	29.99	2139	2.41	13.39	107	196	Off Idle	85.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.35	14.61	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:4	29.99	2138	2.42	13.39	107	196	Off Idle	85.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.32	14.65	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:4	29.99	2142	2.43	13.39	107	196	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.31	14.66	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:4	29.99	2142	2.44	13.41	108	196	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.3	14.69	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:4	29.99	2161	2.45	13.41	108	196	Off Idle	85.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.27	14.68	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:4	29.99	2146	2.45	13.41	108	196	Off Idle	85.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.27	14.69	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:4	29.99	2156	2.46	13.42	108	196	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.26	14.69	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:5	29.99	2160	2.46	13.41	108	196	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.24	14.7	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:5	29.99	2172	2.46	13.39	108	196	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.23	14.68	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:5	29.99	2193	2.46	13.38	108	196	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.21	14.65	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:12:5	29.99	2212	2.46	13.37	108	196	Off Idle	85.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.2	14.63	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:12:5	29.99	2212	2.46	13.37	108	196	Off Idle	85.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.2	14.59	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:12:5	29.99	2238	2.47	13.38	108	196	Off Idle	84.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.21	14.58	0.99	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:12:6	31.36	2252	2.47	13.39	108	196	Off Idle	84.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.27	14.58	0.99	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:12:6	31.36	2279	2.47	13.41	108	196	Off Idle	84	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.32	14.51	0.99	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:6	31.36	2279	2.47	13.39	108	196	Off Idle	83.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.37	14.5	0.99	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:6	31.36	2300	2.48	13.38	108	196	Off Idle	83.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.33	14.48	0.99	3.3	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:6	31.36	2348	2.48	13.38	108	196	Off Idle	82.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.29	14.46	0.99	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:6	31.36	2331	2.49	13.37	108	196	Off Idle	82.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.27	14.44	0.98	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:6	31.36	2322	2.49	13.36	108	196	Off Idle	81.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.29	14.41	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:7	31.36	2332	2.5	13.37	108	196	Off Idle	81.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.28	14.42	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:7	31.36	2332	2.51	13.39	108	196	Off Idle	79.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.29	14.43	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:7	31.36	2353	2.51	13.4	108	196	Off Idle	78.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.32	14.45	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:12:7	31.36	2363	2.52	13.4	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.34	14.52	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:7	31.36	2363	2.52	13.4	107	196	Off Idle	78	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.37	14.54	0.99	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:7	31.36	2371	2.53	13.4	107	196	Off Idle	77.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.33	14.56	0.99	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:8	31.36	2400	2.53	13.4	107	196	Off Idle	77.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.29	14.62	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:8	31.36	2393	2.54	13.4	107	196	Off Idle	76.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.32	14.66	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:12:8	31.36	2405	2.55	13.38	107	196	Off Idle	75.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.29	14.7	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:12:8	31.36	2409	2.55	13.39	108	196	Off Idle	75.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-2.3	14.73	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:8	31.36	2426	2.56	13.37	108	196	Off Idle	75	0	2	132	944 Turbo	0.57	Lean	1	14.6	-2.33	14.75	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:8	31.36	2450	2.57	13.34	108	196	Off Idle	74.1	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.35	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:12:9	31.36	2454	2.58	13.36	108	196	Off Idle	73.7	0	2	132	944 Turbo	0.51	Lean	1	14.6	-2.36	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:12:9	31.36	2474	2.58	13.37	108	196	Off Idle	73.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-2.35	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:12:9	31.36	2474	2.59	13.38	107	196	Off Idle	73	0	2	132	944 Turbo	0.46	Lean	1	14.6	-2.34	14.85	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:12:9	31.36	2501	2.59	13.38	107	196	Off Idle	72.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.36	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:12:9	31.36	2507	2.6	13.4	107	196	Off Idle	72	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.35	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:12:9	31.36	2525	2.6	13.4	107	196	Off Idle	71.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.37	14.85	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:12:9	31.36	2525	2.6	13.39	107	196	Off Idle	70.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-2.38	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:0	31.36	2537	2.61	13.39	107	196	Off Idle	69.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-2.41	14.88	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:0	32.72	2537	2.61	13.4	107	196	Off Idle	68.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.42	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:0	32.72	2551	2.62	13.39	107	196	Off Idle	68.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-2.48	14.92	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:0	32.72	2556	2.63	13.38	108	196	Off Idle	67.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.48	14.96	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:0	32.72	2587	2.63	13.37	108	196	Off Idle	67.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.47	15.01	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:0	32.72	2578	2.64	13.37	108	196	Off Idle	66.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.5	15.03	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:1	32.72	2572	2.64	13.35	108	196	Off Idle	65.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.48	15.03	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:1	32.72	2572	2.65	13.36	108	196	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.49	15.01	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:1	32.72	2584	2.65	13.36	108	196	Off Idle	64.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.5	14.98	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:1	32.72	2594	2.66	13.37	108	196	Off Idle	64.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.49	14.94	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:1	32.72	2610	2.66	13.4	108	196	Off Idle	63.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.55	14.91	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:1	32.72	2614	2.67	13.41	108	196	Off Idle	63.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.52	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:1	32.72	2628	2.67	13.41	107	196	Off Idle	63.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.55	14.82	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:2	32.72	2647	2.67	13.4	107	196	Off Idle	63.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.56	14.8	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:2	32.72	2647	2.68	13.39	108	196	Off Idle	62.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.56	14.78	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:2	32.72	2669	2.68	13.38	108	196	Off Idle	62.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.56	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:2	32.72	2682	2.69	13.37	108	196	Off Idle	61.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.56	14.8	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:2	32.72	2687	2.69	13.37	108	196	Off Idle	61.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-2.53	14.82	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:2	32.72	2716	2.69	13.38	108	196	Off Idle	60.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-2.51	14.83	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:3	32.72	2722	2.7	13.36	108	196	Off Idle	60	0	2	132	944 Turbo	0.46	Rich	1	14.6	-2.55	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:3	32.72	2724	2.7	13.37	108	196	Off Idle	59.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.52	14.81	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:3	32.72	2735	2.7	13.39	108	196	Off Idle	58.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.51	14.81	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:3	32.72	2743	2.7	13.4	108	196	Off Idle	58.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.54	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:3	32.72	2760	2.71	13.4	108	196	Off Idle	56.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.58	14.85	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:3	32.72	2762	2.71	13.38	108	196	Off Idle	56.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.63	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:4	32.72	2778	2.71	13.38	108	196	Off Idle	55.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.61	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:4	32.72	2816	2.72	13.38	108	196	Off Idle	54.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.59	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:4	32.72	2816	2.72	13.37	107	196	Off Idle	54.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-2.58	14.96	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:4	32.72	2810	2.73	13.37	107	196	Off Idle	53.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-2.6	15.02	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:4	32.72	2833	2.73	13.35	107	196	Off Idle	53.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.66	15.08	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:4	32.72	2833	2.73	13.37	108	196	Off Idle	52.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-2.75	15.1	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:4	32.72	2836	2.74	13.36	108	196	Off Idle	52.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.71	15.13	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:5	32.72	2838	2.74	13.36	108	196	Off Idle	51.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.75	15.11	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:5	32.72	2842	2.74	13.36	108	196	Off Idle	51.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.79	15.09	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:13:5	32.72	2843	2.75	13.38	108	196	Off Idle	50.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.76	15.06	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:13:5	32.72	2871	2.75	13.38	108	196	Off Idle	49.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.77	15.03	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:13:5	34.08	2871	2.75	13.38	108	196	Off Idle	49.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.74	14.98	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:13:5	34.08	2864	2.75	13.4	108	196	Off Idle	48.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.73	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:13:6	34.08	2875	2.75	13.38	108	196	Off Idle	48	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.75	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:13:6	34.08	2880	2.76	13.37	108	196	Off Idle	47.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-2.71	14.9	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:6	32.72	2892	2.76	13.37	108	196	Off Idle	47.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-2.75	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:13:6	32.72	2899	2.76	13.37	108	196	Off Idle	47.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.73	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:13:6	32.72	2910	2.77	13.39	107	196	Off Idle	47	0	2	132	944 Turbo	0.33	Lean	1	14.6	-2.67	14.86	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:6	32.72	2933	2.77	13.41	107	196	Off Idle	46.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-2.69	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:6	32.72	2933	2.77	13.42	108	196	Off Idle	46	0	2	132	944 Turbo	0.2	Lean	1	14.6	-2.68	14.86	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:7	32.72	2950	2.78	13.41	108	195	Off Idle	45.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-2.67	14.92	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:7	32.72	2979	2.78	13.4	108	195	Off Idle	45.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-2.68	14.96	1.02	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:7	32.72	2996	2.79	13.39	107	196	Off Idle	44.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.66	15	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:13:7	34.08	3085	2.79	13.39	107	196	Off Idle	43.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.62	15.04	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:13:7	34.08	3023	2.8	13.39	107	196	Off Idle	43.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.54	15.08	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:13:7	34.08	3025	2.81	13.39	108	196	Off Idle	43.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.52	15.11	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:13:8	34.08	3044	2.81	13.4	108	196	Off Idle	43	0	2	132	944 Turbo	0.11	Lean	1	14.6	-2.48	15.21	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:13:8	34.08	3057	2.82	13.38	108	196	Off Idle	42.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-2.5	15.23	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:13:8	34.08	3095	2.83	13.38	108	196	Off Idle	42.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.53	15.25	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:13:8	34.08	3078	2.84	13.4	108	196	Off Idle	42	0	2	132	944 Turbo	0.33	Lean	1	14.6	-2.48	15.26	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:13:8	34.08	3089	2.85	13.41	108	196	Off Idle	41.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.44	15.27	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:13:8	34.08	3089	2.86	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.41	15.27	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:13:9	34.08	3096	2.87	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-2.3	15.23	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:13:9	34.08	3110	2.88	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-2.27	15.2	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:13:9	34.08	3110	2.9	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-2.22	15.19	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:13:9	34.08	3121	2.91	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.07	15.11	1.03	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:13:9	34.08	3128	2.92	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.97	15.07	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:13:9	34.08	3136	2.93	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.93	15.03	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:13:9	34.08	3145	2.94	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.82	14.97	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:14:0	34.08	3148	2.94	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.75	14.91	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:14:0	34.08	3154	2.96	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.6	14.84	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:14:0	34.08	3162	2.97	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1.42	14.84	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:0	32.72	3207	2.98	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-1.32	14.84	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:14:0	32.72	3207	2.99	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-1.13	14.85	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:14:0	32.72	3223	3.01	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-0.94	14.87	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:14:1	32.72	3242	3.03	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.88	14.9	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:14:1	34.08	3297	3.04	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.69	14.92	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:14:1	34.08	3297	3.05	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.53	14.94	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:14:1	34.08	3300	3.07	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.5	14.95	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:14:1	34.08	3326	3.08	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-0.41	14.96	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:14:1	34.08	3325	3.09	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.36	14.99	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:1	32.72	3350	3.11	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.26	14.98	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:14:2	32.72	3358	3.12	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.24	14.97	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:14:2	32.72	3364	3.14	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.15	14.94	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:2	32.72	3390	3.15	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.14	14.92	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:2	32.72	3386	3.16	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.08	14.88	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:2	32.72	3386	3.17	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.07	14.85	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:2	32.72	3401	3.18	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.02	14.8	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:3	32.72	3418	3.19	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.18	14.73	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:3	32.72	3422	3.2	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.25	14.69	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:3	32.72	3443	3.21	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.29	14.66	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:3	32.72	3462	3.22	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.37	14.64	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:3	32.72	3475	3.22	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.34	14.64	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:3	32.72	3480	3.23	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.41	14.62	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:4	32.72	3523	3.24	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.46	14.6	0.99	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:4	32.72	3504	3.25	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	0.47	14.6	0.99	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:4	32.72	3519	3.25	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.52	14.62	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:4	32.72	3523	3.26	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.6	14.64	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:4	32.72	3544	3.27	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.56	14.65	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:4	32.72	3567	3.28	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	0.7	14.66	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:4	32.72	3570	3.28	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.74	14.66	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:5	32.72	3568	3.29	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.7	14.67	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:5	32.72	3611	3.3	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.86	14.73	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:5	32.72	3628	3.3	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.82	14.78	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:5	32.72	3638	3.31	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.91	14.81	1.01	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:14:8	32.72	3642	3.32	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.92	14.85	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:8	32.72	3664	3.32	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	1	14.87	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:6	32.72	3678	3.33	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.95	14.89	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:6	32.72	3697	3.34	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.92	14.9	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:6	32.72	3701	3.34	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.99	14.92	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:6	32.72	3720	3.35	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	1.04	14.93	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:6	32.72	3735	3.35	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	1.1	14.94	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:6	32.72	3735	3.36	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	1.11	14.94	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:6	32.72	3748	3.36	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	1.06	14.97	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:7	32.72	3758	3.37	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	1.05	14.97	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:7	32.72	3758	3.37	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	1.03	14.97	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:7	32.72	3787	3.38	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	1.04	14.97	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:7	32.72	3816	3.38	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	1.21	14.96	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:7	32.72	3832	3.39	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	1.2	14.94	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:7	32.72	3836	3.39	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	1.09	14.94	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:14:8	32.72	3850	3.4	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	1.1	14.95	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:14:8	32.72	3892	3.41	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	1.11	14.95	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:14:8	32.72	3874	3.41	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	1.18	14.88	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:14:8	32.72	3874	3.42	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	1.19	14.9	1.01	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:14:8	32.72	3903	3.42	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	1.33	14.9	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:8	32.72	3918	3.43	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	1.34	14.93	1.02	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:9	32.72	3924	3.43	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	1.35	14.97	1.02	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:14:9	32.72	3948	3.44	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	1.41	15.06	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:14:9	32.72	3974	3.44	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	1.38	15.11	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:14:9	32.72	3987	3.45	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	1.22	15.11	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:9	32.72	3991	3.45	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	1.18	15.11	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:9	32.72	4012	3.45	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	1.18	15.07	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:14:9	32.72	4018	3.46	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	1.18	15.03	1.02	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:15:0	32.72	4018	3.46	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	1.18	14.95	1.02	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:15:0	32.72	4026	3.47	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.18	14.89	1.01	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:0	32.72	4042	3.47	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	1.11	14.83	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:0	32.72	4054	3.47	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	1.15	14.72	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:0	32.72	4050	3.48	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	1.19	14.67	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:15:0	32.72	4056	3.48	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	1.2	14.64	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:15:1	32.72	4078	3.48	13.33	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	1.18	14.64	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:15:1	32.72	4100	3.48	13.32	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	1.05	14.7	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:15:1	32.72	4100	3.48	13.32	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	1	14.72	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:15:1	32.72	4111	3.48	13.35	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	0.94	14.84	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:15:1	32.72	4168	3.48	13.36	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	1	14.88	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:1	32.72	4173	3.48	13.36	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	1	14.94	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:1	32.72	4200	3.49	13.34	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	0.96	15.01	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:2	32.72	4255	3.49	13.33	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	0.85	15.08	1.03	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:16:15:2	32.72	4273	3.49	13.36	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	0.69	15.13	1.03	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:15:2	34.08	4241	3.49	13.38	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	0.53	15.12	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:15:2	34.08	4247	3.49	13.4	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	0.39	15.11	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:15:2	34.08	4263	3.48	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	0.18	15.04	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:15:2	34.08	4265	3.48	13.37	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	0.02	14.99	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:15:3	34.08	4290	3.47	13.33	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.32	14.97	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:15:3	34.08	4276	3.45	13.31	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.84	14.94	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:15:3	34.08	4274	3.38	13.29	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.67	14.89	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:15:3	34.08	4281	3.31	13.29	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.21	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:3	35.45	4259	3.23	13.3	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.35	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:15:3	35.45	4202	3.14	13.34	108	196	Full Load	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.03	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:15:4	35.45	4166	3.1	13.36	108	196	Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.49	14.77	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:15:4	35.45	4168	2.96	13.37	108	196	Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.69	14.68	1	3.7	1.2	ON	28 Pin	OFF	Removed	Disabled
03:16:15:4	36.81	4066	2.86	13.37	108	196	Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.31	14.57	0.99	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:4	36.81	4083	2.81	13.39	108	196	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.73	14.39	0.98	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:4	36.81	4035	2.66	13.41	108	196	Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-9.13	14.15	0.96	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:15:4	31.36	3997	2.55	13.42	108	196	Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-9.27	13.85	0.94	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:4	25.9	3997	2.45	13.42	108	195	Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-9.39	13.52	0.92	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:5	25.9	3901	2.29	13.41	108	195	Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-9.56	13.04	0.89	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:5	20.45	3924	2.18	13.41	108	195	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.62	12.71	0.87	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:5	20.45	3892	2.08	13.4	108	195	Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.69	12.41	0.85	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:5	20.45	3881	1.99	13.41	108	195	Idle	41.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.72	12.13	0.83	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:5	20.45	3836	1.84	13.41	108	195	Idle	40.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.76	11.81	0.8	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:5	20.45	3806	1.75	13.41	108	196	Idle	40.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.77	11.65	0.79	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:6	20.45	3766	1.64	13.4	108	196	Idle	39.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.76	11.59	0.79	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:6	20.45	3736	1.61	13.41	108	196	Idle	37.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.75	11.59	0.79	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:6	20.45	3728	1.56	13.4	108	196	Idle	36.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.72	11.67	0.79	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:6	20.45	3689	1.54	13.4	108	196	Idle	35.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	11.92	0.81	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:6	20.45	3638	1.54	13.41	108	196	Idle	33.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.62	12.32	0.84	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:6	20.45	3620	1.54	13.41	108	195	Idle	31.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	12.5	0.85	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:6	20.45	3620	1.55	13.41	108	195	Idle	30	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	13.31	0.91	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:7	20.45	3549	1.57	13.41	108	195	Idle	28.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	14.5	0.99	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:7	20.45	3540	1.59	13.4	108	195	Idle	26.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	15.32	1.04	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:7	20.45	3532	1.62	13.4	108	195	Idle	25.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	16.56	1.13	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:7	20.45	3428	1.65	13.41	108	195	Idle	24.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.48	16.94	1.15	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:7	20.45	3448	1.69	13.43	108	196	Idle	23.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	18.04	1.23	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:7	20.45	3442	1.71	13.44	108	196	Idle	23.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.4	18.69	1.27	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:8	20.45	3382	1.72	13.42	108	196	Idle	22.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.33	19.31	1.32	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:8	20.45	3382	1.74	13.42	108	196	Idle	22.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.33	19.71	1.34	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:8	20.45	3351	1.76	13.41	108	196	Idle	22.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.23	20.09	1.37	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:8	20.45	3308	1.76	13.4	108	195	Idle	22.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.17	20.14	1.37	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:8	20.45	3297	1.78	13.42	108	195	Idle	22.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.21	20.16	1.37	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:8	20.45	3267	1.8	13.41	108	196	Idle	22.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.07	20.18	1.37	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:9	20.45	3235	1.81	13.41	108	196	Idle	21.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.12	20.18	1.37	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:9	20.45	3228	1.82	13.41	108	196	Idle	21.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.03	20.18	1.37	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:9	20.45	3160	1.82	13.41	108	196	Idle	21.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.96	20.17	1.37	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:9	20.45	3161	1.83	13.4	108	196	Idle	21.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.98	20.16	1.37	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:9	20.45	3152	1.83	13.4	108	196	Full Load	21.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.96	20.24	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:9	20.45	3108	1.84	13.4	108	195	Off Idle	21.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.94	20.24	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:15:9	20.45	3090	1.84	13.41	108	195	Off Idle	21	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.87	20.24	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:0	10.9	2912	1.85	13.41	108	195	Off Idle	21	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.83	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:16:0	13.63	3055	1.86	13.39	108	196	Off Idle	22.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.7	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:16:0	13.63	3046	1.87	13.4	108	196	Off Idle	23.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.62	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:16:0	16.36	2990	1.88	13.41	108	196	Off Idle	25.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.5	20.25	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:0	19.09	2974	1.9	13.39	108	196	Off Idle	26.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.37	20.25	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:0	21.81	2870	1.93	13.38	108	196	Off Idle	28.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.07	20.24	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:1	21.81	2782	1.95	13.39	108	196	Off Idle	29.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.88	20.24	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:1	24.54	2782	1.97	13.38	108	196	Off Idle	32.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.63	20.24	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:1	27.27	2669	2.01	13.37	108	196	Off Idle	35	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.37	20.24	1.38	3.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:16:1	29.99	2543	2.04	13.38	108	196	Off Idle	37.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-6.96	20.24	1.38	4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:16:1	29.99	2425	2.07	13.38	108	196	Off Idle	39.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-6.68	20.24	1.38	4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:1	32.72	2440	2.09	13.38	108	196	Off Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-6.54	20.24	1.38	3.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:1	32.72	2435	2.12	13.37	108	195	Off Idle	45.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-6.11	20.24	1.38	3.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:16:2	34.08	2426	2.15	13.37	108	195	Off Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-5.8	20.24	1.38	3.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:16:2	34.08	2428	2.18	13.38	108	195	Off Idle	53.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.27	20.24	1.38	3.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:16:2	34.08	2428	2.24	13.41	108	196	Off Idle	55.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-4.85	20.25	1.38	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:16:2	34.08	2506	2.29	13.42	108	196	Off Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-4.23	20.25	1.38	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:16:2	34.08	2543	2.35	13.43	108	196	Off Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-3.73	20.25	1.38	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:16:2	34.08	2568	2.4	13.42	108	196	Off Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-3.51	20.25	1.38	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:16:3	34.08	2644	2.44	13.41	108	196	Off Idle	63.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-2.97	20.24	1.38	3.3	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:3	32.72	2650	2.48	13.41	108	196	Off Idle	64.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-2.51	20.25	1.38	3.3	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:3	32.72	2705	2.54	13.41	108	196	Off Idle	65.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-2.1	20.24	1.38	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:16:3	32.72	2745	2.58	13.4	108	196	Off Idle	65.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-1.77	20.15	1.37	3.3	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:3	32.72	2826	2.63	13.38	108	196	Off Idle	64.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-1.54	19.87	1.35	3.3	5.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:16:3	32.72	2826	2.66	13.4	108	196	Off Idle	63.8	0	2	132	944 Turbo	0.13	Rich	1	14.6	-1.54	19.78	1.35	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:16:16:4	32.72	2743	2.68	13.39	108	196	Off Idle	62.7	0	2	132	944 Turbo	0.2	Rich	1	14.6	-1.46	19.36	1.32	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:16:4	32.72	2708	2.7	13.37	108	196	Off Idle	61.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-1.44	19.04	1.3	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:16:4	32.72	2696	2.72	13.38	108	196	Off Idle	60.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-1.36	18.43	1.26	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:16:4	32.72	2662	2.74	13.39	108	196	Off Idle	58.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-1.27	18	1.23	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:16:4	32.72	2616	2.78	13.39	108	196	Off Idle	57.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-1.17	17.53	1.19	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:16:4	32.72	2588	2.8	13.4	108	196	Off Idle	56.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.08	16.74	1.14	3.7	5	ON	28 Pin	OFF	Removed	Disabled
03:16:16:4	32.72	2573	2.83	13.4	108	196	Off Idle	56	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1	16.25	1.11	3.7	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:5	32.72	2572	2.85	13.39	108	196	Off Idle	55.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.94	15.58	1.06	3.7	5	ON	28 Pin	OFF	Removed	Disabled
03:16:16:5	31.36	2587	2.87	13.38	108	196	Off Idle	55.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.95	15.18	1.03	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:16:16:5	31.36	2587	2.87	13.4	108	196	Off Idle	56	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.9	14.83	1.01	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:16:16:5	31.36	2621	2.86	13.39	108	195	Off Idle	56.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.92	14.4	0.98	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:16:5	31.36	2663	2.85	13.37	108	195	Off Idle	57.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.89	14.18	0.97	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:16:5	31.36	2683	2.85	13.38	108	195	Off Idle	57.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.85	13.96	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:16:6	31.36	2692	2.85	13.39	108	196	Off Idle	58	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.85	13.81	0.94	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:16:6	31.36	2720	2.86	13.4	108	196	Off Idle	58.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.76	13.7	0.93	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:16:6	31.36	2736	2.86	13.4	108	196	Off Idle	58.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.71	13.67	0.93	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:16:6	32.72	2801	2.87	13.4	108	196	Off Idle	58.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.64	13.65	0.93	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:6	32.72	2729	2.87	13.39	108	196	Off Idle	58.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.59	13.63	0.93	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:6	32.72	2726	2.88	13.39	108	196	Off Idle	58.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.58	13.61	0.93	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:6	32.72	2716	2.88	13.38	108	196	Off Idle	58	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.49	13.59	0.93	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:7	32.72	2706	2.89	13.38	108	196	Off Idle	57.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.41	13.58	0.92	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:7	32.72	2702	2.89	13.37	108	196	Off Idle	56.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.28	13.57	0.92	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:7	31.36	2702	2.89	13.38	108	196	Off Idle	56.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.27	13.57	0.92	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:7	31.36	2706	2.9	13.38	108	196	Off Idle	55.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.2	13.61	0.93	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:7	31.36	2713	2.9	13.39	108	196	Off Idle	54.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.18	13.65	0.93	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:7	31.36	2713	2.91	13.39	108	196	Off Idle	54.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.19	13.68	0.93	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:8	31.36	2726	2.91	13.38	108	196	Off Idle	54.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.19	13.7	0.93	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:8	31.36	2743	2.92	13.39	108	196	Off Idle	54	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.12	13.74	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:16:16:8	31.36	2750	2.93	13.38	108	196	Off Idle	53.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.13	13.77	0.94	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:8	31.36	2784	2.93	13.4	108	196	Off Idle	53.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.15	13.78	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:8	31.36	2793	2.94	13.39	108	196	Off Idle	53.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.08	13.78	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:8	31.36	2796	2.95	13.39	108	196	Off Idle	53.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.03	13.76	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:9	31.36	2804	2.96	13.4	108	196	Off Idle	53.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.02	13.74	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:9	31.36	2832	2.96	13.4	108	196	Off Idle	52.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.04	13.71	0.93	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:9	31.36	2832	2.96	13.38	108	196	Off Idle	52.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.08	13.71	0.93	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:9	31.36	2818	2.97	13.39	108	196	Off Idle	52.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.13	13.68	0.93	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:16:16:9	31.36	2816	2.98	13.4	108	196	Off Idle	51.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.18	13.67	0.93	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:16:9	31.36	2814	2.98	13.4	108	196	Off Idle	51.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.13	13.67	0.93	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:16:9	31.36	2806	2.98	13.4	108	196	Off Idle	50.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.2	13.68	0.93	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:17:0	31.36	2806	2.99	13.38	108	196	Off Idle	50.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.23	13.71	0.93	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:17:0	31.36	2824	2.99	13.38	108	196	Off Idle	50.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.24	13.73	0.94	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:17:0	31.36	2830	3	13.36	108	196	Off Idle	49.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.26	13.75	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:0	31.36	2839	3	13.36	108	196	Off Idle	49.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.39	13.77	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:0	31.36	2847	3.01	13.36	108	196	Off Idle	49.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.4	13.8	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:0	31.36	2852	3.02	13.36	108	196	Off Idle	48.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.43	13.8	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:1	31.36	2870	3.03	13.36	108	196	Off Idle	48.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.54	13.83	0.94	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:17:1	31.36	2870	3.04	13.38	108	196	Off Idle	48	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.56	13.85	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:1	31.36	2879	3.04	13.38	108	196	Off Idle	47.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.55	13.85	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:1	29.99	2884	3.05	13.38	108	196	Off Idle	47.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.63	13.84	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:1	29.99	2884	3.06	13.39	108	196	Off Idle	47.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.69	13.83	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:1	29.99	2892	3.06	13.39	108	196	Off Idle	47.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.68	13.84	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:1	29.99	2904	3.07	13.39	108	196	Off Idle	46.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.75	13.84	0.94	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:17:2	29.99	2904	3.08	13.39	108	196	Off Idle	46.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.77	13.84	0.94	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:17:2	29.99	2918	3.08	13.38	108	196	Off Idle	46.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.82	13.86	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:17:2	29.99	2924	3.09	13.39	108	196	Off Idle	45.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.85	13.87	0.94	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:17:2	29.99	2932	3.1	13.39	108	196	Off Idle	45.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.96	13.87	0.94	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:17:2	29.99	2932	3.1	13.4	108	195	Off Idle	45.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.95	13.89	0.95	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:17:2	29.99	2937	3.11	13.4	108	195	Off Idle	45.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.98	13.93	0.95	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:17:3	29.99	2946	3.11	13.39	108	196	Off Idle	44.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.93	13.95	0.95	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:17:3	29.99	2953	3.12	13.4	108	196	Off Idle	44.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.96	13.95	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:3	29.99	2956	3.13	13.39	108	196	Off Idle	44.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.98	13.95	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:3	29.99	2954	3.13	13.4	108	196	Off Idle	44	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.96	13.96	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:3	29.99	2960	3.14	13.38	108	196	Off Idle	43.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.99	13.95	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:3	29.99	2973	3.14	13.38	108	196	Off Idle	43.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.11	13.96	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:4	29.99	2987	3.15	13.39	108	196	Off Idle	43.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.16	13.98	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:4	29.99	2987	3.15	13.38	108	196	Off Idle	42.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.17	13.98	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:4	29.99	2995	3.15	13.39	108	195	Off Idle	42.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.27	13.99	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:4	29.99	3001	3.16	13.37	108	195	Off Idle	42.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.26	13.98	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:4	29.99	3010	3.16	13.37	108	195	Off Idle	41.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.3	14.01	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:4	29.99	3012	3.17	13.38	108	196	Off Idle	41.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.3	14.02	0.96	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:4	29.99	3023	3.17	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.33	14.05	0.96	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:5	29.99	3023	3.18	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.43	14.09	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:17:5	29.99	3023	3.18	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.48	14.11	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:17:5	29.99	3037	3.18	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.48	14.12	0.96	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:5	29.99	3057	3.19	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.52	14.14	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:17:5	29.99	3057	3.19	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.59	14.14	0.96	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:5	29.99	3056	3.2	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	1.65	14.17	0.96	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:17:6	29.99	3066	3.2	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.7	14.19	0.97	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:17:6	29.99	3075	3.21	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.75	14.18	0.97	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:6	29.99	3082	3.21	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.8	14.19	0.97	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:17:6	29.99	3082	3.22	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.86	14.2	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:16:17:6	29.99	3094	3.23	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.9	14.22	0.97	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:17:6	29.99	3122	3.23	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.98	14.26	0.97	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:17:6	29.99	3103	3.24	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	2.03	14.28	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:16:17:7	29.99	3112	3.25	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	2.16	14.29	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:16:17:7	29.99	3115	3.25	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	2.27	14.36	0.98	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:16:17:7	29.99	3112	3.26	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	2.4	14.38	0.98	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:16:17:7	29.99	3115	3.26	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	2.48	14.43	0.98	3.6	5.9	ON	28 Pin	OFF	Removed	Disabled
03:16:17:7	29.99	3121	3.27	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	2.62	14.5	0.99	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:16:17:7	29.99	3136	3.28	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.67	14.57	0.99	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:16:17:8	29.99	3158	3.29	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.75	14.6	0.99	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:8	29.99	3163	3.3	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.83	14.62	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:8	28.63	3182	3.31	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.82	14.65	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:8	28.63	3186	3.31	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.88	14.68	1	3.6	6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:8	28.63	3188	3.32	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.93	14.69	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:8	28.63	3193	3.33	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.04	14.71	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:16:17:9	28.63	3187	3.34	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.04	14.76	1.01	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:16:17:9	28.63	3184	3.34	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.18	14.78	1.01	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:16:17:9	28.63	3187	3.35	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.19	14.69	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:16:17:9	28.63	3202	3.35	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.29	14.7	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:16:17:9	28.63	3202	3.36	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.26	14.7	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:16:17:9	28.63	3222	3.37	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.4	14.7	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:16:17:9	28.63	3232	3.37	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.4	14.71	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:16:18:0	28.63	3234	3.38	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.53	14.72	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:16:18:0	28.63	3247	3.38	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.53	14.71	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:16:18:0	28.63	3280	3.39	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.68	14.68	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:0	28.63	3265	3.39	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.68	14.68	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:0	28.63	3265	3.4	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.73	14.68	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:0	28.63	3270	3.41	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.77	14.74	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:1	28.63	3274	3.41	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	3.75	14.75	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:1	28.63	3287	3.42	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	3.83	14.77	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:1	28.63	3288	3.42	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	3.92	14.77	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:1	28.63	3292	3.43	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	3.93	14.79	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:1	28.63	3317	3.43	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	4.02	14.8	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:1	28.63	3334	3.44	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.17	14.8	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:18:1	28.63	3328	3.45	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.14	14.83	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:2	28.63	3338	3.45	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.3	14.85	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:2	28.63	3346	3.46	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.35	14.86	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:2	28.63	3344	3.46	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.43	14.87	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:2	28.63	3342	3.47	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.55	14.89	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:2	28.63	3350	3.47	13.37	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	4.57	14.89	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:2	28.63	3350	3.48	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	4.72	14.86	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:3	28.63	3348	3.48	13.37	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	4.83	14.88	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:3	27.27	3376	3.49	13.35	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	4.84	14.87	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:3	27.27	3376	3.49	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	4.99	14.87	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:3	27.27	3376	3.5	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	4.95	14.85	1.01	3.6	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:3	27.27	3377	3.51	13.35	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	5.07	14.84	1.01	3.6	6.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:3	27.27	3390	3.51	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	5.13	14.83	1.01	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:4	27.27	3388	3.52	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	5.16	14.83	1.01	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:4	27.27	3427	3.52	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	5.19	14.85	1.01	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:16:18:4	27.27	3427	3.53	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	5.23	14.9	1.01	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:16:18:4	27.27	3439	3.54	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	5.36	14.97	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:16:18:4	27.27	3472	3.54	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	5.33	15.01	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:16:18:4	27.27	3470	3.55	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	5.48	15.03	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:16:18:4	27.27	3474	3.56	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	5.58	15.13	1.03	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:16:18:5	27.27	3476	3.56	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	5.65	15.16	1.03	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:16:18:5	27.27	3486	3.57	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	5.75	15.17	1.03	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:5	27.27	3467	3.57	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	5.8	15.14	1.03	3.6	6.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:5	27.27	3464	3.58	13.37	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	5.97	15.05	1.03	3.6	6.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:5	27.27	3464	3.59	13.35	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	6.09	14.97	1.02	3.6	6.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:5	27.27	3466	3.59	13.36	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	6.19	14.9	1.01	3.6	6.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:6	27.27	3492	3.6	13.35	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	6.34	14.83	1.01	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:16:18:6	27.27	3496	3.6	13.36	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	6.43	14.78	1.01	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:16:18:6	27.27	3527	3.61	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	6.39	14.77	1.01	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:16:18:6	27.27	3534	3.61	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	6.43	14.76	1.01	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:16:18:6	25.9	3569	3.62	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	6.54	14.69	1	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:16:18:6	25.9	3576	3.63	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	6.55	14.67	1	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:16:18:6	25.9	3596	3.64	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	6.75	14.68	1	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:16:18:7	25.9	3605	3.65	13.35	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	6.9	14.61	1	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:16:18:7	25.9	3634	3.66	13.34	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	6.99	14.58	0.99	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:16:18:7	25.9	3604	3.67	13.36	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	7.07	14.48	0.99	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:7	25.9	3604	3.68	13.34	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	7.18	14.32	0.98	3.6	8.9	ON	28 Pin	OFF	Removed	Disabled
03:16:18:7	25.9	3604	3.68	13.35	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.16	14.14	0.96	3.6	9	ON	28 Pin	OFF	Removed	Disabled
03:16:18:7	25.9	3613	3.69	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	7.26	13.94	0.95	3.6	9.1	ON	28 Pin	OFF	Removed	Disabled
03:16:18:8	27.27	3575	3.7	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	7.34	13.59	0.93	3.6	9.1	ON	28 Pin	OFF	Removed	Disabled
03:16:18:8	27.27	3618	3.71	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	7.34	13.35	0.91	3.5	9.1	ON	28 Pin	OFF	Removed	Disabled
03:16:18:8	27.27	3620	3.72	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	7.58	13.08	0.89	3.5	9.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:8	27.27	3634	3.73	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	7.65	12.73	0.87	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:8	25.9	3646	3.73	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	7.81	12.59	0.86	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:8	25.9	3653	3.74	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	7.89	12.46	0.85	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:16:18:9	25.9	3656	3.75	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	7.73	12.38	0.84	3.5	9.2	ON	28 Pin	OFF	Removed	Disabled
03:16:18:9	25.9	3678	3.76	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	7.97	12.31	0.84	3.5	9.4	ON	28 Pin	OFF	Removed	Disabled
03:16:18:9	25.9	3714	3.77	13.37	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	8.03	12.24	0.83	3.5	9.5	ON	28 Pin	OFF	Removed	Disabled
03:16:18:9	25.9	3711	3.77	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.05	12.2	0.83	3.5	9.6	ON	28 Pin	OFF	Removed	Disabled
03:16:18:9	25.9	3714	3.78	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.1	12.18	0.83	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:9	25.9	3726	3.79	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.32	12.17	0.83	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:16:18:9	25.9	3734	3.8	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.31	12.14	0.83	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:0	25.9	3741	3.8	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.38	12.12	0.83	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:0	25.9	3740	3.81	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.64	12.12	0.83	3.5	9.9	ON	28 Pin	OFF	Removed	Disabled
03:16:19:0	25.9	3753	3.82	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.75	12.09	0.82	3.5	9.9	ON	28 Pin	OFF	Removed	Disabled
03:16:19:0	25.9	3766	3.83	13.36	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.68	12.06	0.82	3.5	9.9	ON	28 Pin	OFF	Removed	Disabled
03:16:19:0	24.54	3768	3.84	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.77	12.03	0.82	3.5	10.1	ON	28 Pin	OFF	Removed	Disabled
03:16:19:0	24.54	3799	3.85	13.36	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.91	12.02	0.82	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:19:1	24.54	3792	3.85	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.84	11.99	0.82	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled
03:16:19:1	24.54	3803	3.86	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	9.07	11.97	0.82	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:16:19:1	24.54	3804	3.87	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	9.43	11.92	0.81	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled
03:16:19:1	24.54	3824	3.88	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	9.4	11.89	0.81	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:16:19:1	24.54	3818	3.88	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	9.5	11.83	0.81	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:16:19:1	24.54	3822	3.9	13.37	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	9.71	11.74	0.8	3.5	10.6	ON	28 Pin	OFF	Removed	Disabled
03:16:19:1	24.54	3835	3.91	13.36	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.76	11.68	0.8	3.5	10.6	ON	28 Pin	OFF	Removed	Disabled
03:16:19:2	24.54	3833	3.92	13.36	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.87	11.65	0.79	3.5	10.6	ON	28 Pin	OFF	Removed	Disabled
03:16:19:2	24.54	3846	3.93	13.35	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.88	11.6	0.79	3.5	10.6	ON	28 Pin	OFF	Removed	Disabled
03:16:19:2	24.54	3866	3.93	13.36	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.86	11.58	0.79	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:16:19:2	24.54	3868	3.94	13.36	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.96	11.56	0.79	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:16:19:2	24.54	3904	3.95	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.93	11.56	0.79	3.5	11	ON	28 Pin	OFF	Removed	Disabled
03:16:19:2	24.54	3988	3.96	13.43	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.06	11.58	0.79	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:16:19:3	24.54	3940	3.97	13.42	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.18	11.6	0.79	3.5	11	ON	28 Pin	OFF	Removed	Disabled
03:16:19:3	24.54	3940	3.98	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.4	11.59	0.79	3.6	11.1	ON	28 Pin	OFF	Removed	Disabled
03:16:19:3	24.54	3959	3.99	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.48	11.58	0.79	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:16:19:3	24.54	3964	4	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.7	11.56	0.79	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:16:19:3	24.54	3981	4.01	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	10.77	11.53	0.79	3.6	11.4	ON	28 Pin	OFF	Removed	Disabled
03:16:19:3	24.54	3967	4.01	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	10.96	11.51	0.78	3.6	11.5	ON	28 Pin	OFF	Removed	Disabled
03:16:19:4	24.54	3984	4.03	13.37	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	11.04	11.43	0.78	3.6	11.7	ON	28 Pin	OFF	Removed	Disabled
03:16:19:4	24.54	3986	4.03	13.36	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.17	11.41	0.78	3.6	11.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:4	24.54	3974	4.04	13.35	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.19	11.31	0.77	3.6	11.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:4	24.54	3990	4.05	13.34	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.3	11.25	0.77	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:16:19:4	24.54	4002	4.06	13.33	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.36	11.2	0.76	3.5	11.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:4	24.54	4001	4.06	13.33	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.43	11.19	0.76	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:16:19:4	24.54	4028	4.07	13.32	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.47	11.17	0.76	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:16:19:5	24.54	4026	4.08	13.31	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.7	11.49	11.15	0.76	3.5	12.3	ON	28 Pin	OFF	Removed	Disabled
03:16:19:5	24.54	4030	4.09	13.32	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.4	11.12	0.76	3.5	12.3	ON	28 Pin	OFF	Removed	Disabled
03:16:19:5	24.54	4052	4.09	13.33	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.38	11.09	0.76	3.5	12	ON	28 Pin	OFF	Removed	Disabled
03:16:19:5	24.54	4052	4.1	13.33	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.31	11.09	0.76	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:16:19:5	24.54	4092	4.11	13.34	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.46	11.07	0.75	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:19:5	24.54	4095	4.12	13.34	108	195	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.48	11.03	0.75	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:16:19:6	24.54	4093	4.13	13.36	108	195	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.58	11.01	0.75	3.5	12.3	ON	28 Pin	OFF	Removed	Disabled
03:16:19:6	24.54	4093	4.14	13.36	108	195	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.61	10.99	0.75	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:19:6	23.18	4098	4.15	13.36	108	195	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.5	10.92	0.74	3.5	12.7	ON	28 Pin	OFF	Removed	Disabled
03:16:19:6	23.18	4100	4.15	13.38	108	195	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.7	11.48	10.88	0.74	3.5	12.7	ON	28 Pin	OFF	Removed	Disabled
03:16:19:6	23.18	4104	4.16	13.41	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.91	Rich	1	14.6	11.49	10.82	0.74	3.5	12.9	ON	28 Pin	OFF	Removed	Disabled
03:16:19:6	23.18	4114	4.16	13.41	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.91	Rich	1	14.6	11.62	10.79	0.74	3.5	12.9	ON	28 Pin	OFF	Removed	Disabled
03:16:19:6	23.18	4114	4.17	13.41	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.91	Rich	1	14.6	11.69	10.77	0.73	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:16:19:7	23.18	4134	4.17	13.41	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.92	Rich	1	14.7	11.81	10.74	0.73	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:7	23.18	4158	4.18	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.92	Rich	1	14.6	11.91	10.72	0.73	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:7	23.18	4171	4.19	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.92	Rich	1	14.6	12.07	10.69	0.73	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:16:19:7	23.18	4176	4.19	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.7	12.21	10.66	0.73	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:16:19:7	23.18	4207	4.19	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.21	10.64	0.72	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:7	23.18	4216	4.2	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.38	10.57	0.72	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:8	23.18	4221	4.21	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.41	10.59	0.72	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:8	23.18	4224	4.21	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.5	10.56	0.72	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:8	24.54	4241	4.21	13.34	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	12.49	10.55	0.72	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:8	24.54	4243	4.22	13.33	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	12.55	10.54	0.72	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:8	24.54	4262	4.23	13.33	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	12.61	10.51	0.72	3.5	12.9	ON	28 Pin	OFF	Removed	Disabled
03:16:19:8	24.54	4273	4.23	13.34	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	12.55	10.51	0.72	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:16:19:9	24.54	4303	4.23	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	12.6	10.51	0.72	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:9	24.54	4286	4.23	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	12.52	10.53	0.72	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:9	24.54	4260	4.24	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	12.42	10.56	0.72	3.6	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:19:9	24.54	4266	4.24	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	12.26	10.55	0.72	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:16:19:9	24.54	4297	4.24	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	12.18	10.53	0.72	3.5	13.1	ON	28 Pin	OFF	Removed	Disabled
03:16:19:9	24.54	4302	4.25	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	11.99	10.51	0.72	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:16:19:9	24.54	4304	4.25	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	11.9	10.48	0.71	3.5	12.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:20:0	24.54	4317	4.25	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.78	10.48	0.71	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:16:20:0	24.54	4331	4.25	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.66	10.45	0.71	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:16:20:0	24.54	4334	4.25	13.35	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.53	10.43	0.71	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:0	24.54	4350	4.25	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	11.46	10.38	0.71	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:0	24.54	4359	4.25	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.39	10.37	0.71	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:0	24.54	4364	4.25	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.55	10.35	0.7	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:16:20:1	24.54	4426	4.25	13.36	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.65	10.33	0.7	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:1	24.54	4404	4.25	13.34	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.81	10.34	0.7	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:1	24.54	4410	4.25	13.32	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.02	10.32	0.7	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:1	24.54	4422	4.25	13.33	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.93	10.31	0.7	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:1	24.54	4433	4.25	13.34	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.67	10.34	0.7	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:1	24.54	4430	4.24	13.33	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.47	10.34	0.7	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:1	24.54	4434	4.24	13.32	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.7	11.43	10.34	0.7	3.6	12.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:2	24.54	4434	4.24	13.33	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.91	Rich	1	14.7	11.23	10.34	0.7	3.6	12.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:2	24.54	4435	4.24	13.34	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.19	10.34	0.7	3.6	12.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:2	25.9	4438	4.24	13.36	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	11.09	10.33	0.7	3.6	12	ON	28 Pin	OFF	Removed	Disabled
03:16:20:2	25.9	4445	4.24	13.36	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.7	11.04	10.35	0.7	3.6	12.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:2	25.9	4445	4.24	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.97	10.35	0.7	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:2	25.9	4489	4.24	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.99	10.41	0.71	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:3	25.9	4500	4.24	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.87	10.38	0.71	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:3	25.9	4562	4.24	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.82	10.37	0.71	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:3	25.9	4540	4.24	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.63	10.35	0.7	3.5	11.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:3	25.9	4542	4.24	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	10.49	10.36	0.71	3.5	11.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:3	25.9	4543	4.23	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.44	10.35	0.71	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:16:20:3	25.9	4543	4.23	13.37	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	10.34	10.37	0.71	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:4	25.9	4554	4.23	13.36	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	10.35	10.37	0.71	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:16:20:4	25.9	4552	4.23	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.3	10.37	0.71	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:16:20:4	25.9	4550	4.23	13.4	108	195	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.03	10.37	0.71	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:4	25.9	4569	4.22	13.4	108	195	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.92	10.38	0.71	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:16:20:4	25.9	4590	4.22	13.37	108	195	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.91	10.38	0.71	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:16:20:4	25.9	4580	4.22	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.85	10.45	0.71	3.6	11.5	ON	28 Pin	OFF	Removed	Disabled
03:16:20:4	25.9	4598	4.22	13.38	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.89	10.5	0.72	3.6	11.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:5	25.9	4611	4.22	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.85	10.55	0.72	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:16:20:5	25.9	4616	4.22	13.38	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	9.78	10.61	0.72	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:16:20:5	25.9	4618	4.21	13.38	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.67	10.67	0.73	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:5	25.9	4630	4.21	13.36	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.7	9.63	10.7	0.73	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:16:20:5	25.9	4637	4.21	13.34	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.68	10.74	0.73	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:5	27.27	4686	4.21	13.31	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.77	10.69	0.73	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:6	27.27	4673	4.2	13.32	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.74	10.7	0.73	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:6	27.27	4670	4.2	13.35	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.74	10.67	0.73	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:6	27.27	4678	4.2	13.37	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.7	9.63	10.66	0.73	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:6	27.27	4679	4.2	13.4	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	9.52	10.64	0.72	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:16:20:6	27.27	4690	4.2	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	9.59	10.66	0.73	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:16:20:6	27.27	4692	4.2	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	9.5	10.65	0.73	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:6	27.27	4706	4.2	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.25	10.7	0.73	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:7	27.27	4714	4.19	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.19	10.68	0.73	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:16:20:7	27.27	4714	4.19	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.19	10.74	0.73	3.5	10.7	ON	28 Pin	OFF	Removed	Disabled
03:16:20:7	27.27	4724	4.19	13.38	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.11	10.78	0.73	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:16:20:7	27.27	4742	4.19	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.1	10.8	0.74	3.5	10.7	ON	28 Pin	OFF	Removed	Disabled
03:16:20:7	27.27	4748	4.19	13.39	108	195	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	9.11	10.81	0.74	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:7	27.27	4765	4.19	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	9.09	10.83	0.74	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled
03:16:20:8	27.27	4807	4.18	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.81	10.85	0.74	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:8	27.27	4754	4.18	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.7	10.88	0.74	3.6	10.4	ON	28 Pin	OFF	Removed	Disabled
03:16:20:8	27.27	4756	4.18	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.57	10.84	0.74	3.6	10.3	ON	28 Pin	OFF	Removed	Disabled
03:16:20:8	27.27	4752	4.18	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.58	10.83	0.74	3.6	10.3	ON	28 Pin	OFF	Removed	Disabled
03:16:20:8	28.63	4794	4.18	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.53	10.86	0.74	3.6	10.3	ON	28 Pin	OFF	Removed	Disabled
03:16:20:8	28.63	4769	4.17	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.36	10.9	0.74	3.5	10	ON	28 Pin	OFF	Removed	Disabled
03:16:20:9	28.63	4778	4.17	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	8.36	10.91	0.74	3.5	10	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:20:9	28.63	4797	4.16	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	8.3	10.92	0.74	3.5	9.9	ON	28 Pin	OFF	Removed	Disabled
03:16:20:9	28.63	4824	4.15	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	8.01	10.91	0.74	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:16:20:9	28.63	4824	4.14	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.89	10.91	0.74	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:16:20:9	28.63	4859	4.14	13.43	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	7.63	10.89	0.74	3.5	9.5	ON	28 Pin	OFF	Removed	Disabled
03:16:20:9	28.63	4875	4.13	13.44	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	7.39	10.88	0.74	3.5	9.2	ON	28 Pin	OFF	Removed	Disabled
03:16:20:9	28.63	4877	4.13	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	7.21	10.91	0.74	3.5	9.1	ON	28 Pin	OFF	Removed	Disabled
03:16:21:0	28.63	4954	4.11	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	7.05	10.96	0.75	3.5	9	ON	28 Pin	OFF	Removed	Disabled
03:16:21:0	28.63	4922	4.11	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	6.91	10.96	0.75	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:16:21:0	28.63	4898	4.1	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	6.78	10.93	0.74	3.6	8.9	ON	28 Pin	OFF	Removed	Disabled
03:16:21:0	28.63	4900	4.09	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	6.71	10.94	0.75	3.6	8.8	ON	28 Pin	OFF	Removed	Disabled
03:16:21:0	28.63	4930	4.08	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	6.52	10.96	0.75	3.6	8.7	ON	28 Pin	OFF	Removed	Disabled
03:16:21:0	31.36	4896	4.07	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	6.49	11	0.75	3.6	8.6	ON	28 Pin	OFF	Removed	Disabled
03:16:21:1	31.36	4912	4.06	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	6.38	11.1	0.76	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:16:21:1	31.36	4917	4.05	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	6.29	11.16	0.76	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:16:21:1	31.36	4917	4.05	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.18	11.2	0.76	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:16:21:1	31.36	4920	4.04	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	6.09	11.26	0.77	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:16:21:1	31.36	4928	4.03	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	5.9	11.38	0.77	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:16:21:1	31.36	4932	4.02	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.86	11.43	0.78	3.5	8.2	ON	28 Pin	OFF	Removed	Disabled
03:16:21:1	31.36	4934	4.01	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.77	11.48	0.78	3.5	8.2	ON	28 Pin	OFF	Removed	Disabled
03:16:21:2	31.36	4958	4.01	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.67	11.57	0.79	3.5	8.2	ON	28 Pin	OFF	Removed	Disabled
03:16:21:2	31.36	4952	4	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	5.63	11.58	0.79	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:16:21:2	31.36	4958	4	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.56	11.64	0.79	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:16:21:2	31.36	4961	4	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.54	11.63	0.79	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:16:21:2	31.36	4974	3.99	13.4	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	5.3	11.71	0.8	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:16:21:2	31.36	4981	3.99	13.38	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	5.13	11.75	0.8	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:16:21:3	31.36	4979	3.98	13.38	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.97	11.79	0.8	3.6	7.9	ON	28 Pin	OFF	Removed	Disabled
03:16:21:3	31.36	4992	3.97	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	4.75	11.82	0.81	3.6	7.9	ON	28 Pin	OFF	Removed	Disabled
03:16:21:3	31.36	4996	3.97	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.72	11.84	0.81	3.6	7.8	ON	28 Pin	OFF	Removed	Disabled
03:16:21:3	32.72	5000	3.96	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.68	11.89	0.81	3.6	7.8	ON	28 Pin	OFF	Removed	Disabled
03:16:21:3	32.72	5002	3.96	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.7	11.91	0.81	3.6	7.7	ON	28 Pin	OFF	Removed	Disabled
03:16:21:3	32.72	5030	3.96	13.4	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.69	11.9	0.81	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:16:21:4	32.72	5045	3.95	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.72	11.94	0.81	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:16:21:4	32.72	5047	3.95	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.57	11.94	0.81	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:16:21:4	32.72	5077	3.94	13.41	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.5	11.93	0.81	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:16:21:4	32.72	5058	3.94	13.38	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.29	11.91	0.81	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:16:21:4	32.72	5060	3.93	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.19	11.94	0.81	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:16:21:4	32.72	5056	3.93	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	4.03	11.93	0.81	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:16:21:4	32.72	5062	3.92	13.4	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	4.04	11.96	0.81	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:16:21:5	32.72	5062	3.92	13.41	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.89	11.98	0.82	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:16:21:5	32.72	5066	3.91	13.41	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	3.89	12	0.82	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:5	32.72	5078	3.91	13.41	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.88	12	0.82	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:5	32.72	5087	3.9	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.7	12.01	0.82	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:16:21:5	32.72	5091	3.9	13.38	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.62	12.04	0.82	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:16:21:5	32.72	5091	3.9	13.38	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	3.63	12.06	0.82	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:16:21:6	32.72	5108	3.89	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	3.45	12.06	0.82	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:16:21:6	32.72	5110	3.89	13.39	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	3.39	12.14	0.83	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:16:21:6	32.72	5110	3.88	13.42	108	196	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	3.31	12.14	0.83	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:16:21:6	32.72	5110	3.87	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	2.86	12.14	0.83	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:16:21:6	32.72	5098	3.84	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	1.99	12.17	0.83	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:16:21:6	32.72	5080	3.8	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	0.86	12.19	0.83	3.6	6.6	ON	28 Pin	OFF	Removed	Disabled
03:16:21:6	32.72	5029	3.73	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-0.52	12.19	0.83	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:16:21:7	32.72	5018	3.64	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.12	12.18	0.83	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:21:7	38.18	4922	3.53	13.4	108	196	Full Load	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.68	12.11	0.82	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:21:7	38.18	4918	3.31	13.41	108	196	Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.63	11.93	0.81	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:21:7	38.18	4892	3.13	13.41	108	196	Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.64	11.76	0.8	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:21:7	38.18	4892	2.95	13.42	108	196	Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.33	11.59	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:7	32.72	4810	2.77	13.45	108	196	Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.83	11.45	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:8	27.27	4797	2.56	13.44	108	196	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.53	11.36	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:21:8	21.81	4794	2.43	13.43	108	195	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.88	11.3	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:8	20.45	4814	2.37	13.44	108	195	Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.22	11.31	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:8	20.45	4764	2.24	13.43	108	195	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.45	11.35	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:8	20.45	4739	2.01	13.41	108	196	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.76	11.47	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:8	20.45	4716	1.86	13.4	108	196	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.87	11.55	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:9	20.45	4664	1.71	13.43	108	196	Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.95	11.62	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:9	20.45	4548	1.57	13.43	108	196	Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.06	11.7	0.8	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:9	20.45	4582	1.39	13.42	108	196	Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.07	11.74	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:9	20.45	4560	1.29	13.44	108	196	Idle	41.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.1	11.82	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:9	20.45	4529	1.17	13.43	108	196	Idle	40.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.19	11.87	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:9	20.45	4480	1.11	13.42	108	196	Idle	39.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-10.19	11.91	0.81	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:21:9	20.45	4474	1.08	13.42	108	196	Idle	38.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-10.19	11.94	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:0	20.45	4432	1.08	13.39	108	195	Idle	35.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.16	12.01	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:0	20.45	4397	1.13	13.38	108	195	Idle	34.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.08	12.1	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:0	20.45	4359	1.2	13.36	108	196	Idle	32.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.04	12.32	0.84	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:0	20.45	4350	1.28	13.34	108	196	Idle	31.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.98	12.75	0.87	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:0	20.45	4306	1.37	13.34	108	196	Off Idle	29.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	13.51	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:0	20.45	4232	1.41	13.37	108	196	Off Idle	28	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	14.39	0.98	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:1	20.45	4242	1.43	13.4	108	196	Off Idle	24.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	14.83	1.01	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:1	20.45	4198	1.47	13.43	108	196	Off Idle	23.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	16.12	1.1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:1	20.45	4192	1.54	13.45	108	196	Off Idle	21.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.24	16.93	1.15	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:1	12.27	4180	1.63	13.46	108	196	Off Idle	20.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.77	17.71	1.21	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:22:1	14.99	4180	1.73	13.46	108	196	Off Idle	21.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.16	18.44	1.26	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:22:1	17.72	4112	1.89	13.45	108	196	Off Idle	23.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.76	19.38	1.32	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:22:1	20.45	4059	1.99	13.45	108	196	Off Idle	24.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.42	20.07	1.37	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:22:2	23.18	3987	2.08	13.45	108	196	Off Idle	26.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.5	20.2	1.38	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:22:2	28.63	3972	2.16	13.41	108	196	Off Idle	27.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.01	20.22	1.38	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:22:2	28.63	3874	2.29	13.41	108	196	Off Idle	28.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-3.76	20.24	1.38	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:22:2	31.36	3788	2.38	13.42	108	196	Off Idle	30.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-3.11	20.24	1.38	3.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:22:2	34.08	3695	2.48	13.42	108	196	Off Idle	32	0	2	132	944 Turbo	0.02	Lean	1	14.6	-2.58	20.25	1.38	3.8	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:22:2	36.81	3662	2.57	13.41	108	196	Off Idle	35.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-2.05	20.25	1.38	3.9	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:22:3	36.81	3556	2.69	13.42	108	196	Off Idle	36.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-1.7	20.26	1.38	3.9	5.8	ON	28 Pin	OFF	Removed	Disabled
03:16:22:3	35.45	3476	2.76	13.41	108	196	Off Idle	38.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-1.35	20.28	1.38	3.9	5.8	ON	28 Pin	OFF	Removed	Disabled
03:16:22:3	35.45	3432	2.84	13.4	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-1.09	20.26	1.38	3.7	5.8	ON	28 Pin	OFF	Removed	Disabled
03:16:22:3	35.45	3405	2.91	13.39	108	195	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-0.84	20.14	1.37	3.7	5.8	ON	28 Pin	OFF	Removed	Disabled
03:16:22:3	35.45	3406	2.98	13.38	108	195	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.6	19.71	1.34	3.7	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:3	32.72	3390	3.05	13.39	108	195	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-0.5	19.32	1.32	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:4	32.72	3467	3.1	13.39	108	195	Off Idle	41.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-0.39	18.91	1.29	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:4	32.72	3480	3.17	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-0.33	18.65	1.27	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:22:4	32.72	3544	3.2	13.4	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-0.25	17.73	1.21	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:22:4	32.72	3620	3.22	13.41	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-0.27	17.06	1.16	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:22:4	32.72	3553	3.24	13.4	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.12	16.01	1.09	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:22:4	32.72	3553	3.24	13.4	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.08	15.33	1.04	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:22:4	32.72	3526	3.25	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.07	14.73	1	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:5	32.72	3509	3.25	13.4	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.07	14.28	0.97	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:5	34.08	3488	3.25	13.4	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.23	13.8	0.94	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:22:5	34.08	3491	3.25	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.3	13.51	0.92	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:22:5	34.08	3497	3.25	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.31	13.38	0.91	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:16:22:5	34.08	3504	3.24	13.4	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.4	13.33	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:5	34.08	3532	3.24	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.52	13.32	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:6	32.72	3548	3.24	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.44	13.37	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:6	32.72	3548	3.25	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.54	13.36	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:6	32.72	3557	3.25	13.42	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.58	13.44	0.92	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:6	32.72	3558	3.26	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.61	13.51	0.92	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:6	32.72	3581	3.26	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.7	13.53	0.92	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:6	32.72	3570	3.27	13.41	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.68	13.58	0.93	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:22:6	32.72	3541	3.28	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.8	13.6	0.93	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:22:7	32.72	3536	3.28	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.86	13.62	0.93	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:22:7	32.72	3537	3.28	13.4	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.9	13.66	0.93	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:22:7	32.72	3528	3.29	13.39	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.98	13.69	0.93	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:22:7	32.72	3548	3.29	13.4	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.03	13.74	0.94	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:16:22:7	32.72	3554	3.29	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.03	13.75	0.94	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:22:7	32.72	3554	3.29	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.97	13.76	0.94	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:16:22:8	32.72	3576	3.29	13.37	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.76	13.77	0.94	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:8	32.72	3571	3.29	13.4	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.65	13.76	0.94	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:8	32.72	3571	3.27	13.37	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.28	13.77	0.94	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:8	34.08	3586	3.26	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.21	13.75	0.94	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:8	34.08	3566	3.2	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.25	13.71	0.93	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:8	34.08	3546	3.14	13.39	108	196	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.05	13.67	0.93	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:22:9	34.08	3546	3.05	13.37	108	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.17	13.63	0.93	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:22:9	34.08	3510	2.95	13.39	108	196	Full Load	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.18	13.56	0.92	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:22:9	35.45	3510	2.82	13.37	108	196	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.55	13.44	0.92	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:22:9	35.45	3497	2.75	13.38	107	196	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-6.41	13.37	0.91	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:9	35.45	3493	2.68	13.4	107	196	Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.03	13.26	0.9	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:22:9	35.45	3440	2.57	13.41	108	196	Idle	39.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.46	13.06	0.89	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:22:9	29.99	3424	2.48	13.4	108	196	Idle	37	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.85	12.91	0.88	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:0	24.54	3418	2.4	13.41	108	196	Idle	34.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-8.1	12.72	0.87	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:0	20.45	3420	2.32	13.41	108	196	Idle	32.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-8.18	12.5	0.85	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:0	20.45	3410	2.24	13.41	108	196	Idle	28	0	2	132	944 Turbo	0.85	Rich	1	14.6	-8.22	12.27	0.84	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:0	20.45	3410	2.15	13.4	108	196	Idle	25.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.25	12.05	0.82	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:0	20.45	3416	2.08	13.4	108	196	Idle	23.5	0	2	132	944 Turbo	0.78	Lean	1	14.6	-8.3	11.72	0.8	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:0	20.45	3444	2.01	13.39	108	195	Idle	21.2	0	2	132	944 Turbo	0.7	Lean	1	14.6	-8.31	11.51	0.78	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:1	20.45	3504	1.94	13.4	108	195	Idle	19	0	2	132	944 Turbo	0.63	Lean	1	14.6	-8.34	11.35	0.77	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:1	20.45	3516	1.88	13.41	107	196	Idle	16.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.38	11.23	0.76	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:1	20.45	3563	1.83	13.42	107	196	Idle	16.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.5	11.09	0.76	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:1	20.45	3602	1.79	13.42	107	196	Idle	16.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.55	11.07	0.75	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:1	20.45	3601	1.78	13.42	108	196	Idle	16.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.63	11.12	0.76	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:1	20.45	3584	1.79	13.42	108	196	Idle	18.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.84	11.33	0.77	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:1	20.45	3591	1.8	13.41	108	196	Idle	18.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.97	11.54	0.79	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:2	20.45	3548	1.81	13.4	108	196	Idle	21.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.19	11.68	0.8	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:2	20.45	3533	1.8	13.41	108	196	Idle	25.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.28	12.04	0.82	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:2	20.45	3513	1.78	13.42	107	196	Idle	27.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.4	12.98	0.88	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:2	20.45	3510	1.78	13.41	107	196	Idle	30.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	13.82	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:2	20.45	3485	1.78	13.41	108	196	Idle	32.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	14.72	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:2	20.45	3478	1.79	13.41	108	196	Idle	34.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	16.05	1.09	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:3	20.45	3487	1.78	13.4	108	196	Idle	36.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	16.9	1.15	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:3	20.45	3487	1.77	13.41	108	196	Idle	38.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	17.7	1.21	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:3	20.45	3492	1.75	13.41	108	196	Idle	40.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	18.78	1.28	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:3	20.45	3503	1.74	13.42	108	196	Idle	40	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	19.41	1.32	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:3	20.45	3515	1.73	13.42	108	196	Idle	39.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	19.88	1.35	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:3	20.45	3517	1.73	13.43	108	196	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.04	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:4	20.45	3524	1.72	13.43	108	196	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.2	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:4	20.45	3505	1.71	13.42	108	196	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:4	20.45	3505	1.7	13.42	108	196	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:4	20.45	3512	1.69	13.42	108	196	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:4	20.45	3502	1.69	13.43	108	196	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:4	20.45	3484	1.7	13.42	108	196	Idle	39.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:4	20.45	3482	1.7	13.41	107	196	Idle	39.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:5	20.45	3476	1.7	13.41	107	196	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:5	20.45	3472	1.7	13.41	107	196	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:5	20.45	3447	1.7	13.39	108	195	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:5	20.45	3460	1.7	13.41	108	195	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:5	20.45	3484	1.7	13.41	108	195	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:5	20.45	3493	1.7	13.4	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:6	20.45	3500	1.7	13.4	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:6	20.45	3500	1.7	13.41	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:23:6	20.45	3510	1.7	13.42	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:6	20.45	3488	1.7	13.41	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:6	20.45	3482	1.7	13.42	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:6	20.45	3480	1.7	13.42	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:6	20.45	3468	1.7	13.41	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:7	20.45	3430	1.7	13.43	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:7	20.45	3439	1.7	13.41	108	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:7	20.45	3443	1.7	13.41	108	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:7	20.45	3440	1.7	13.41	108	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:7	20.45	3438	1.7	13.41	108	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:7	20.45	3439	1.7	13.41	108	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:8	20.45	3448	1.7	13.4	108	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:8	20.45	3454	1.7	13.42	108	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.11	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:8	20.45	3458	1.7	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.11	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:8	20.45	3496	1.7	13.39	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.12	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:8	20.45	3475	1.7	13.4	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.12	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:8	20.45	3478	1.7	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.13	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:9	20.45	3476	1.7	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.12	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:9	20.45	3470	1.7	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.12	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:9	20.45	3478	1.7	13.43	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.11	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:9	20.45	3458	1.7	13.42	108	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.11	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:9	20.45	3426	1.7	13.42	108	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:9	20.45	3436	1.7	13.43	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:23:9	20.45	3442	1.71	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:0	20.45	3436	1.71	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:0	20.45	3433	1.71	13.42	108	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:0	20.45	3434	1.71	13.41	108	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:0	20.45	3418	1.71	13.41	108	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:0	20.45	3431	1.71	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:0	20.45	3428	1.71	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:1	20.45	3428	1.71	13.42	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:1	20.45	3425	1.71	13.42	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:1	20.45	3425	1.71	13.41	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:1	20.45	3425	1.71	13.43	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:1	20.45	3428	1.71	13.41	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:1	20.45	3430	1.71	13.41	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:1	20.45	3434	1.71	13.41	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:2	20.45	3434	1.71	13.41	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:2	20.45	3436	1.71	13.41	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:2	20.45	3436	1.71	13.43	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:2	20.45	3433	1.71	13.44	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:2	20.45	3429	1.71	13.44	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:2	20.45	3428	1.71	13.43	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:3	20.45	3424	1.7	13.42	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:3	20.45	3415	1.7	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:3	20.45	3414	1.7	13.43	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:3	20.45	3372	1.71	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:3	20.45	3372	1.71	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:3	20.45	3400	1.7	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:4	20.45	3396	1.7	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:4	20.45	3396	1.7	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:4	20.45	3399	1.71	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:4	20.45	3397	1.71	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:4	20.45	3398	1.71	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:4	20.45	3399	1.71	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:4	20.45	3397	1.71	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:5	20.45	3396	1.71	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:5	20.45	3391	1.71	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:24:5	20.45	3388	1.71	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:5	20.45	3382	1.71	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:5	20.45	3381	1.71	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:5	20.45	3379	1.7	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:6	20.45	3378	1.71	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:6	20.45	3382	1.71	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:6	20.45	3398	1.71	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:6	20.45	3406	1.7	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:6	20.45	3419	1.7	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:6	20.45	3419	1.7	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:6	20.45	3416	1.7	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:7	20.45	3416	1.7	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:7	20.45	3409	1.7	13.4	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:7	20.45	3402	1.7	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:7	20.45	3387	1.7	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:7	20.45	3384	1.7	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:7	20.45	3374	1.7	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:8	20.45	3367	1.7	13.4	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:8	20.45	3353	1.7	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:8	20.45	3352	1.7	13.4	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:8	20.45	3348	1.7	13.41	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:8	20.45	3353	1.7	13.41	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:8	20.45	3354	1.7	13.41	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:9	20.45	3358	1.7	13.41	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:9	20.45	3364	1.7	13.41	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:9	20.45	3363	1.71	13.41	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:9	20.45	3361	1.71	13.42	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:9	20.45	3354	1.71	13.41	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:9	20.45	3350	1.71	13.43	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:24:9	20.45	3344	1.71	13.44	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:0	20.45	3344	1.71	13.43	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:0	20.45	3338	1.71	13.43	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:0	20.45	3334	1.71	13.43	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:0	20.45	3334	1.71	13.42	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:0	20.45	3338	1.71	13.42	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:0	20.45	3346	1.71	13.44	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:1	20.45	3348	1.71	13.43	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:1	20.45	3352	1.71	13.44	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:1	20.45	3352	1.71	13.43	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:1	20.45	3353	1.71	13.44	107	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:1	20.45	3353	1.7	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:1	20.45	3352	1.7	13.42	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:1	20.45	3350	1.7	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:2	20.45	3346	1.7	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:2	20.45	3340	1.7	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:2	20.45	3312	1.7	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:2	20.45	3322	1.7	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:2	20.45	3323	1.7	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:2	20.45	3320	1.7	13.44	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:3	20.45	3320	1.7	13.43	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:3	20.45	3317	1.7	13.43	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:3	20.45	3312	1.7	13.43	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:3	20.45	3307	1.7	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:3	20.45	3308	1.7	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:3	20.45	3306	1.7	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:4	20.45	3307	1.7	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:4	20.45	3311	1.7	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:4	20.45	3312	1.7	13.42	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:25:4	20.45	3314	1.71	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:4	20.45	3313	1.71	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:4	20.45	3317	1.71	13.41	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:4	20.45	3317	1.7	13.39	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:5	20.45	3312	1.7	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:5	20.45	3322	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:5	20.45	3305	1.7	13.35	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:5	20.45	3305	1.7	13.34	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:5	20.45	3299	1.7	13.34	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:5	20.45	3294	1.7	13.35	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:6	20.45	3294	1.7	13.35	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:6	20.45	3295	1.7	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:6	20.45	3300	1.7	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:6	20.45	3304	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:6	20.45	3307	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:6	20.45	3307	1.7	13.37	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.27	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:6	20.45	3304	1.7	13.35	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.27	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:7	20.45	3316	1.7	13.37	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:7	20.45	3325	1.7	13.36	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:7	20.45	3325	1.7	13.37	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:7	20.45	3295	1.7	13.37	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:7	20.45	3288	1.7	13.38	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:7	20.45	3274	1.7	13.38	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:8	20.45	3272	1.7	13.37	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:8	20.45	3252	1.7	13.37	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:8	20.45	3256	1.7	13.38	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:8	20.45	3256	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:8	20.45	3252	1.7	13.38	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:8	20.45	3249	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:9	20.45	3249	1.7	13.38	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:9	20.45	3246	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:9	20.45	3246	1.7	13.38	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:9	20.45	3243	1.7	13.38	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:9	20.45	3243	1.7	13.38	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:9	20.45	3248	1.7	13.38	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:25:9	20.45	3229	1.7	13.38	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:0	20.45	3229	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:0	20.45	3208	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:0	20.45	3212	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:0	20.45	3202	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:0	20.45	3202	1.7	13.38	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:0	20.45	3196	1.7	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:1	20.45	3196	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:1	20.45	3189	1.7	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:1	20.45	3186	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:1	20.45	3180	1.7	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:1	20.45	3180	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:1	20.45	3178	1.7	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:1	20.45	3176	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:2	20.45	3175	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:2	20.45	3167	1.7	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:2	20.45	3162	1.7	13.38	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:2	20.45	3158	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:2	20.45	3144	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:2	20.45	3148	1.69	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:3	20.45	3145	1.69	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:3	20.45	3145	1.69	13.35	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:3	20.45	3137	1.69	13.35	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:26:3	20.45	3152	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:3	20.45	3152	1.7	13.36	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:3	20.45	3121	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:4	20.45	3068	1.69	13.36	107	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:4	19.09	3109	1.69	13.37	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:4	19.09	3106	1.69	13.37	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:4	19.09	3100	1.69	13.36	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:4	19.09	3094	1.69	13.37	107	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:4	19.09	3088	1.69	13.37	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:4	19.09	3080	1.7	13.36	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:5	19.09	3080	1.7	13.37	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:5	19.09	3074	1.7	13.39	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:5	19.09	3069	1.7	13.38	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:5	19.09	3062	1.7	13.39	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:5	19.09	3060	1.7	13.39	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:5	19.09	3054	1.7	13.39	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:6	19.09	3049	1.7	13.38	107	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:6	19.09	3040	1.7	13.38	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:6	19.09	3038	1.7	13.39	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:6	19.09	3029	1.7	13.37	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:6	19.09	3017	1.7	13.37	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:6	19.09	3017	1.7	13.37	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:6	19.09	3008	1.7	13.37	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:7	19.09	3006	1.7	13.37	107	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:7	19.09	2990	1.7	13.38	107	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:7	19.09	2988	1.7	13.37	107	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:7	19.09	2970	1.7	13.37	107	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:7	19.09	2975	1.7	13.37	107	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:7	19.09	2970	1.7	13.37	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:8	19.09	2970	1.7	13.38	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:8	19.09	2967	1.69	13.38	107	196	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:8	19.09	2964	1.7	13.37	107	196	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:8	19.09	2962	1.7	13.38	107	196	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:8	19.09	2956	1.7	13.37	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:8	19.09	2950	1.7	13.37	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:9	19.09	2950	1.7	13.37	107	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:9	19.09	2926	1.7	13.38	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:9	19.09	2931	1.7	13.39	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:9	19.09	2921	1.7	13.38	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:9	19.09	2921	1.7	13.37	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:9	19.09	2916	1.69	13.36	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:26:9	19.09	2906	1.69	13.37	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:0	19.09	2878	1.69	13.37	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:0	19.09	2892	1.69	13.37	107	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:0	19.09	2892	1.69	13.37	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:0	19.09	2886	1.69	13.38	107	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:0	19.09	2881	1.69	13.38	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:0	19.09	2876	1.69	13.38	107	196	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:1	19.09	2876	1.7	13.38	107	196	Idle	40.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:1	19.09	2869	1.7	13.36	107	196	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:1	19.09	2859	1.7	13.37	107	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:1	19.09	2853	1.7	13.36	107	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.57	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:1	19.09	2850	1.7	13.36	107	196	Idle	40.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:1	19.09	2841	1.7	13.36	107	196	Idle	40.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:1	19.09	2811	1.7	13.36	107	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:2	19.09	2821	1.7	13.37	107	196	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:2	19.09	2826	1.7	13.36	107	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.52	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:2	19.09	2818	1.7	13.38	107	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:27:2	19.09	2811	1.7	13.37	107	196	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:2	19.09	2812	1.7	13.38	107	196	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:2	19.09	2819	1.7	13.37	107	196	Idle	42.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:3	19.09	2804	1.7	13.37	107	196	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:3	19.09	2804	1.69	13.35	107	196	Idle	42.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.57	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:3	19.09	2790	1.69	13.37	107	196	Idle	43.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:3	19.09	2796	1.69	13.37	107	196	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:3	19.09	2794	1.69	13.35	107	196	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:3	19.09	2792	1.69	13.35	107	196	Idle	44.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:4	19.09	2788	1.68	13.37	107	196	Idle	44.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:4	19.09	2780	1.68	13.36	107	196	Idle	44.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:4	19.09	2780	1.68	13.37	107	196	Idle	45.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:4	19.09	2774	1.67	13.36	107	196	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:4	19.09	2767	1.67	13.36	107	196	Idle	45.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:4	19.09	2760	1.67	13.37	107	196	Idle	45.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:4	19.09	2757	1.66	13.36	107	196	Idle	46.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:5	19.09	2759	1.66	13.36	107	196	Idle	46.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:5	19.09	2742	1.65	13.35	107	196	Idle	46.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:5	19.09	2738	1.65	13.37	107	196	Idle	46.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:5	19.09	2738	1.64	13.37	107	196	Idle	47.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:5	19.09	2734	1.64	13.37	107	196	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:5	19.09	2731	1.64	13.35	107	196	Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:6	19.09	2726	1.63	13.36	107	196	Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:6	19.09	2726	1.63	13.35	107	196	Idle	48.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:6	19.09	2722	1.63	13.36	107	196	Idle	48.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:6	19.09	2714	1.62	13.37	107	196	Idle	48.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:6	19.09	2714	1.62	13.36	107	196	Idle	48.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.27	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:6	19.09	2694	1.61	13.36	107	196	Idle	48.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:6	19.09	2699	1.61	13.37	107	196	Idle	49.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:7	19.09	2696	1.61	13.37	107	196	Idle	49.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:7	19.09	2690	1.6	13.38	107	196	Idle	49.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:7	19.09	2686	1.6	13.39	107	196	Idle	49.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:7	19.09	2685	1.59	13.37	107	196	Idle	50.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:7	19.09	2681	1.59	13.36	107	196	Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:7	19.09	2681	1.59	13.37	107	196	Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:8	19.09	2682	1.59	13.37	107	196	Idle	50.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:8	19.09	2682	1.58	13.36	107	196	Idle	50.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:8	19.09	2683	1.58	13.35	107	196	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:8	19.09	2681	1.57	13.36	107	196	Idle	51.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:8	19.09	2682	1.57	13.37	107	196	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:8	19.09	2683	1.57	13.37	107	196	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:9	19.09	2679	1.56	13.38	107	196	Idle	52.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:9	19.09	2679	1.56	13.37	107	196	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:9	19.09	2677	1.55	13.36	107	196	Idle	52.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:9	19.09	2674	1.55	13.37	107	196	Idle	53.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:9	19.09	2674	1.54	13.38	107	196	Idle	53.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:9	19.09	2671	1.54	13.4	107	196	Idle	53.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:27:9	19.09	2668	1.53	13.4	107	196	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:0	19.09	2668	1.53	13.41	107	196	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:0	19.09	2669	1.53	13.42	107	196	Idle	54.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:0	19.09	2669	1.52	13.41	107	196	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:0	19.09	2668	1.52	13.42	107	196	Idle	55.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:0	19.09	2668	1.51	13.42	107	196	Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:0	19.09	2668	1.51	13.41	107	196	Idle	55.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:1	19.09	2665	1.5	13.41	107	196	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:1	19.09	2665	1.5	13.4	107	196	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:1	19.09	2664	1.49	13.41	107	196	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:1	19.09	2650	1.49	13.41	107	196	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:28:1	19.09	2656	1.49	13.4	107	196	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:1	19.09	2654	1.48	13.4	107	196	Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:1	19.09	2649	1.48	13.41	107	196	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:2	19.09	2645	1.48	13.41	107	196	Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:2	19.09	2643	1.47	13.41	107	196	Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:2	19.09	2652	1.47	13.42	107	196	Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:2	19.09	2642	1.47	13.43	107	196	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:2	19.09	2646	1.47	13.43	107	196	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:2	19.09	2646	1.47	13.42	107	196	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:3	19.09	2648	1.46	13.4	107	196	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:3	19.09	2630	1.46	13.4	107	196	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:3	19.09	2650	1.46	13.4	107	196	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:3	19.09	2650	1.46	13.4	107	196	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:3	19.09	2649	1.46	13.41	107	196	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:3	19.09	2645	1.46	13.41	107	196	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:4	19.09	2645	1.46	13.41	107	196	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:4	19.09	2640	1.46	13.41	107	196	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:4	19.09	2633	1.46	13.41	107	196	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:4	19.09	2633	1.46	13.42	107	196	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:4	19.09	2625	1.45	13.41	107	196	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:4	19.09	2620	1.45	13.4	107	197	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:4	19.09	2621	1.45	13.41	107	197	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:5	19.09	2620	1.45	13.39	107	197	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:5	19.09	2620	1.45	13.4	107	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:5	19.09	2621	1.45	13.41	107	196	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:5	19.09	2623	1.44	13.39	107	196	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:5	19.09	2625	1.44	13.4	107	196	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:5	19.09	2625	1.44	13.41	107	196	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:6	19.09	2626	1.44	13.41	107	196	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:6	19.09	2626	1.44	13.41	107	196	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:6	19.09	2624	1.44	13.41	107	196	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:6	19.09	2624	1.44	13.41	107	196	Idle	57.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:6	19.09	2620	1.44	13.42	107	196	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:6	19.09	2616	1.44	13.41	107	196	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:6	19.09	2614	1.43	13.41	107	196	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:7	19.09	2608	1.43	13.4	107	196	Idle	58.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:7	19.09	2602	1.43	13.41	107	196	Idle	58.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:7	19.09	2601	1.43	13.41	107	196	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:7	19.09	2601	1.43	13.42	107	197	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:7	19.09	2600	1.43	13.42	107	197	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:7	19.09	2600	1.43	13.42	107	196	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:8	19.09	2601	1.43	13.41	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:8	19.09	2604	1.42	13.41	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:8	19.09	2607	1.42	13.41	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:8	19.09	2608	1.42	13.41	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:8	19.09	2607	1.42	13.41	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:8	19.09	2609	1.42	13.43	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:9	19.09	2607	1.42	13.41	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:9	19.09	2607	1.42	13.41	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:9	19.09	2602	1.42	13.41	107	196	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:9	19.09	2596	1.42	13.4	107	196	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:9	19.09	2592	1.42	13.4	107	196	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:9	19.09	2592	1.42	13.41	107	196	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:28:9	19.09	2587	1.42	13.4	107	196	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:0	19.09	2583	1.42	13.41	107	196	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:0	19.09	2583	1.41	13.42	107	196	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:0	19.09	2582	1.41	13.42	107	196	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:0	19.09	2582	1.41	13.42	107	196	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:29:0	19.09	2584	1.41	13.42	107	196	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:0	19.09	2584	1.41	13.42	107	196	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:1	19.09	2584	1.42	13.42	107	196	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:1	19.09	2582	1.42	13.41	107	196	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:1	19.09	2582	1.42	13.42	107	196	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:1	19.09	2579	1.42	13.41	107	196	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:1	19.09	2578	1.42	13.41	107	196	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:1	19.09	2574	1.42	13.42	107	196	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:1	19.09	2566	1.42	13.42	107	196	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:2	19.09	2566	1.42	13.41	107	196	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:2	19.09	2560	1.41	13.41	107	196	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:2	19.09	2560	1.41	13.41	107	196	Idle	60	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:2	19.09	2554	1.41	13.4	107	196	Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:2	19.09	2554	1.41	13.39	107	196	Idle	60.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:2	19.09	2557	1.41	13.4	107	196	Idle	60.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:3	19.09	2571	1.41	13.4	107	196	Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:3	19.09	2570	1.41	13.39	107	196	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:3	19.09	2570	1.4	13.41	107	196	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:3	19.09	2573	1.4	13.4	107	196	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:3	19.09	2573	1.4	13.4	107	196	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:3	19.09	2593	1.4	13.41	107	196	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:4	19.09	2582	1.39	13.42	107	196	Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:4	19.09	2570	1.39	13.41	107	196	Idle	62.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:4	19.09	2570	1.38	13.42	107	196	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:4	19.09	2561	1.38	13.41	107	196	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:4	19.09	2555	1.38	13.41	107	196	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:4	19.09	2555	1.37	13.41	107	196	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:4	19.09	2549	1.37	13.41	107	196	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:5	19.09	2546	1.37	13.42	107	196	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:5	19.09	2545	1.37	13.41	107	196	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:5	19.09	2544	1.36	13.42	107	196	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:5	19.09	2544	1.36	13.42	107	196	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:5	19.09	2542	1.36	13.41	107	196	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:5	19.09	2524	1.36	13.41	107	196	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:6	19.09	2543	1.35	13.41	107	196	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:6	19.09	2553	1.35	13.41	107	196	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:6	19.09	2542	1.35	13.42	107	196	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:6	19.09	2542	1.35	13.41	107	196	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:6	19.09	2539	1.35	13.4	107	196	Idle	62.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:6	19.09	2538	1.35	13.41	107	196	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:6	19.09	2534	1.35	13.41	107	196	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:7	19.09	2531	1.35	13.4	107	196	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:7	19.09	2527	1.35	13.4	107	196	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:7	19.09	2526	1.35	13.41	107	196	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:7	19.09	2522	1.35	13.4	107	196	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:7	19.09	2511	1.35	13.41	107	196	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:7	19.09	2511	1.34	13.43	107	196	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:8	19.09	2522	1.34	13.42	107	196	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:8	19.09	2522	1.34	13.41	107	196	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:8	19.09	2525	1.34	13.42	107	196	Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:8	19.09	2526	1.34	13.41	107	196	Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:8	19.09	2525	1.33	13.4	107	197	Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:8	19.09	2545	1.33	13.4	107	197	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:9	19.09	2534	1.33	13.39	107	196	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:9	19.09	2522	1.33	13.4	107	196	Idle	64.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:9	19.09	2522	1.33	13.4	107	196	Idle	64.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:9	19.09	2500	1.33	13.41	107	196	Idle	64.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:9	19.09	2508	1.33	13.42	107	196	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:29:9	19.09	2516	1.32	13.41	107	196	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:29:9	19.09	2513	1.32	13.41	107	196	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:0	19.09	2511	1.32	13.41	107	196	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:0	19.09	2510	1.32	13.43	107	197	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:0	19.09	2508	1.32	13.42	107	197	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:0	19.09	2505	1.32	13.43	107	197	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:0	19.09	2506	1.32	13.42	107	196	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:0	19.09	2507	1.32	13.41	107	196	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:1	19.09	2505	1.32	13.41	107	196	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:1	19.09	2505	1.32	13.41	107	196	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:1	19.09	2505	1.32	13.41	106	196	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:1	19.09	2504	1.32	13.41	106	196	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:1	19.09	2504	1.32	13.41	106	196	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:1	19.09	2504	1.31	13.41	107	196	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:1	19.09	2503	1.31	13.42	107	196	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:2	19.09	2501	1.31	13.42	107	196	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:2	19.09	2501	1.31	13.42	107	196	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.03	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:2	19.09	2498	1.31	13.43	107	196	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.02	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:2	19.09	2496	1.31	13.41	107	196	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.02	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:2	19.09	2493	1.3	13.42	107	196	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.02	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:2	19.09	2491	1.3	13.41	107	196	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.03	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:3	19.09	2488	1.3	13.41	107	196	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.03	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:3	19.09	2483	1.3	13.4	107	196	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.03	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:3	19.09	2481	1.3	13.41	107	196	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.03	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:3	19.09	2481	1.3	13.41	107	196	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.02	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:3	19.09	2482	1.3	13.41	107	196	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:3	19.09	2481	1.3	13.42	107	196	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:4	19.09	2482	1.29	13.43	107	196	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:4	19.09	2485	1.29	13.42	107	196	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:4	19.09	2484	1.29	13.42	107	196	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:4	19.09	2485	1.29	13.43	107	196	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:4	19.09	2485	1.29	13.42	107	196	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:4	19.09	2485	1.29	13.41	107	196	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:4	19.09	2483	1.29	13.41	107	196	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:5	19.09	2481	1.28	13.41	107	196	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:5	19.09	2476	1.28	13.41	107	197	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:5	19.09	2472	1.28	13.41	107	197	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:5	19.09	2472	1.28	13.42	107	197	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:5	19.09	2467	1.28	13.4	107	196	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:5	19.09	2466	1.28	13.4	107	196	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:6	19.09	2462	1.27	13.41	107	196	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:6	19.09	2460	1.27	13.41	107	196	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:6	19.09	2460	1.27	13.39	107	196	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:6	19.09	2460	1.27	13.41	107	197	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:6	19.09	2462	1.26	13.41	107	197	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:6	19.09	2463	1.26	13.41	107	197	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:6	19.09	2464	1.26	13.41	107	196	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:7	19.09	2468	1.26	13.41	107	196	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:7	19.09	2469	1.26	13.42	107	196	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:7	19.09	2469	1.25	13.42	107	196	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:7	19.09	2466	1.25	13.42	107	196	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:7	19.09	2466	1.25	13.42	107	196	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:7	19.09	2462	1.25	13.44	107	196	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:8	19.09	2461	1.25	13.43	107	196	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:8	19.09	2458	1.25	13.42	107	196	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:8	19.09	2447	1.25	13.41	107	196	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:8	19.09	2447	1.24	13.41	107	196	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:8	19.09	2430	1.24	13.41	107	196	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:30:8	19.09	2419	1.24	13.39	107	196	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:9	17.72	2419	1.24	13.39	107	196	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:9	17.72	2438	1.24	13.41	107	196	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:9	19.09	2456	1.24	13.41	107	196	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:9	19.09	2448	1.24	13.4	107	196	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:9	19.09	2434	1.24	13.41	107	196	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:9	17.72	2448	1.23	13.42	107	196	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:30:9	17.72	2450	1.23	13.4	107	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:0	17.72	2450	1.23	13.41	107	197	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:0	17.72	2451	1.23	13.42	107	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:0	17.72	2448	1.23	13.41	107	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:0	17.72	2448	1.23	13.41	107	197	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:0	17.72	2452	1.23	13.41	107	196	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:0	17.72	2434	1.23	13.41	107	196	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:1	17.72	2434	1.23	13.42	107	196	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:1	17.72	2412	1.23	13.42	107	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:1	17.72	2420	1.23	13.42	107	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:1	17.72	2420	1.23	13.42	107	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:1	17.72	2416	1.23	13.4	107	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:1	17.72	2414	1.23	13.4	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:1	17.72	2414	1.23	13.39	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:2	17.72	2398	1.23	13.38	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:2	17.72	2408	1.23	13.38	107	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:2	17.72	2420	1.23	13.39	107	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:2	17.72	2423	1.23	13.4	107	196	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:2	17.72	2423	1.23	13.4	107	196	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:2	17.72	2434	1.23	13.39	107	196	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:3	17.72	2425	1.23	13.4	107	196	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:3	17.72	2423	1.23	13.4	107	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:3	17.72	2422	1.23	13.41	107	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:3	17.72	2421	1.23	13.42	107	197	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:3	17.72	2418	1.22	13.42	107	197	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:3	17.72	2416	1.22	13.41	107	197	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:4	17.72	2393	1.22	13.4	107	196	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:4	17.72	2402	1.22	13.4	107	196	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:4	17.72	2411	1.21	13.4	107	196	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:4	17.72	2421	1.21	13.4	107	196	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:4	17.72	2414	1.21	13.39	107	196	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:4	17.72	2414	1.21	13.4	107	196	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:4	17.72	2414	1.21	13.4	107	196	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:5	17.72	2394	1.2	13.41	107	196	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:5	17.72	2411	1.2	13.4	107	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:5	17.72	2420	1.2	13.42	107	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:5	17.72	2406	1.19	13.41	107	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:5	17.72	2384	1.19	13.4	107	196	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:5	17.72	2400	1.19	13.4	107	196	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:6	17.72	2398	1.19	13.4	107	196	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:6	17.72	2391	1.19	13.39	107	197	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:6	17.72	2389	1.19	13.41	106	197	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:6	17.72	2388	1.19	13.4	106	196	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:6	17.72	2386	1.18	13.4	106	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:6	17.72	2386	1.18	13.41	106	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:6	17.72	2386	1.18	13.42	107	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:7	17.72	2387	1.18	13.42	107	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:7	17.72	2389	1.18	13.42	107	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:7	17.72	2390	1.18	13.41	107	196	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:7	17.72	2392	1.18	13.4	107	196	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:7	17.72	2392	1.18	13.41	107	196	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:31:7	17.72	2390	1.18	13.4	107	197	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:8	17.72	2390	1.18	13.41	107	197	Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:8	17.72	2388	1.17	13.42	107	197	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:8	17.72	2384	1.17	13.41	107	196	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:8	17.72	2380	1.17	13.41	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:8	17.72	2376	1.17	13.41	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:8	17.72	2376	1.17	13.4	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:9	17.72	2371	1.17	13.39	107	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:9	17.72	2368	1.17	13.4	107	196	Full Load	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:9	17.72	2368	1.17	13.41	107	196	Off Idle	72	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:9	17.72	2386	1.17	13.41	107	196	Off Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:9	17.72	2309	1.17	13.4	107	196	Off Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:31:9	9.54	2370	1.18	13.38	107	196	Off Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:31:9	9.54	2390	1.18	13.38	107	197	Off Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:32:0	12.27	2390	1.19	13.39	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:16:32:0	14.99	2391	1.2	13.38	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:0	14.99	2390	1.2	13.39	107	196	Off Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:0	14.99	2390	1.21	13.4	107	196	Off Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:0	17.72	2386	1.22	13.41	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:0	20.45	2382	1.23	13.41	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:1	23.18	2380	1.24	13.4	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:1	23.18	2379	1.25	13.41	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:1	25.9	2378	1.26	13.4	107	197	Off Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:1	25.9	2378	1.27	13.39	107	197	Off Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:1	28.63	2378	1.29	13.4	107	197	Off Idle	73.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:1	31.36	2377	1.3	13.43	107	197	Off Idle	73.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:1	31.36	2376	1.31	13.43	107	197	Off Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:2	34.08	2374	1.33	13.42	107	197	Off Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:2	34.08	2374	1.34	13.42	107	197	Off Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:2	35.45	2364	1.35	13.41	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:2	35.45	2368	1.36	13.41	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:2	35.45	2380	1.37	13.41	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:2	35.45	2381	1.38	13.4	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:3	35.45	2382	1.38	13.4	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:3	35.45	2381	1.39	13.41	107	196	Off Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:3	35.45	2381	1.39	13.41	107	196	Off Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:3	35.45	2367	1.4	13.41	107	196	Off Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:3	35.45	2351	1.41	13.42	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:3	35.45	2351	1.42	13.42	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.99	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:32:4	35.45	2350	1.43	13.43	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.98	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:32:4	35.45	2349	1.44	13.41	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.95	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:32:4	35.45	2353	1.45	13.42	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.91	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:32:4	35.45	2353	1.46	13.42	107	196	Off Idle	74.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.86	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:32:4	35.45	2354	1.48	13.42	107	197	Off Idle	74.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:32:4	35.45	2357	1.49	13.42	107	197	Off Idle	74.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:32:4	35.45	2355	1.51	13.42	107	197	Off Idle	74.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.56	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:32:5	35.45	2355	1.53	13.42	107	197	Off Idle	74.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.45	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:32:5	35.45	2362	1.55	13.41	107	196	Off Idle	74.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.36	20.25	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:32:5	35.45	2364	1.56	13.39	107	196	Off Idle	74.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.23	20.26	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:32:5	35.45	2365	1.58	13.41	107	197	Off Idle	74.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	20.26	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:5	35.45	2368	1.6	13.41	107	197	Off Idle	74.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.04	20.25	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:5	35.45	2377	1.62	13.41	107	197	Off Idle	74.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	20.25	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:6	35.45	2385	1.64	13.41	107	196	Off Idle	74.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.88	20.24	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:6	35.45	2390	1.66	13.42	107	196	Off Idle	74.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.75	20.24	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:6	34.08	2384	1.68	13.42	107	196	Off Idle	74.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.7	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:6	34.08	2399	1.7	13.42	107	196	Off Idle	73.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.58	20.19	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:6	34.08	2400	1.72	13.42	107	196	Off Idle	73.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.5	20.09	1.37	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:32:6	34.08	2398	1.76	13.42	107	196	Off Idle	73.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.38	19.83	1.35	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:32:6	34.08	2391	1.77	13.41	107	196	Off Idle	73.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.32	19.64	1.34	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:32:7	34.08	2374	1.79	13.41	107	196	Off Idle	73.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.23	19.39	1.32	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:7	34.08	2361	1.82	13.41	107	196	Off Idle	73.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.17	19.27	1.31	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:7	34.08	2343	1.83	13.41	107	197	Off Idle	73.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.11	18.85	1.28	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:7	34.08	2340	1.85	13.41	107	197	Off Idle	73.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.09	18.53	1.26	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:7	34.08	2335	1.86	13.41	107	197	Off Idle	73.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.99	18.19	1.24	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:7	34.08	2335	1.87	13.41	107	196	Off Idle	73.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.9	17.84	1.22	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:8	34.08	2340	1.88	13.41	107	196	Off Idle	73.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	17.4	1.19	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:32:8	34.08	2355	1.9	13.41	107	196	Off Idle	73.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	17.16	1.17	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:8	34.08	2355	1.92	13.41	107	197	Off Idle	73.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.39	17.04	1.16	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:32:8	34.08	2362	1.94	13.43	107	197	Off Idle	73.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.2	16.81	1.14	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:32:8	34.08	2362	1.96	13.42	107	197	Off Idle	73.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.86	16.49	1.12	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:32:8	34.08	2367	1.98	13.42	107	197	Off Idle	74	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.69	16.29	1.11	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:32:9	34.08	2376	2	13.41	107	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.56	16.12	1.1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:9	34.08	2384	2.02	13.41	107	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.43	15.98	1.09	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:32:9	32.72	2378	2.05	13.4	107	197	Off Idle	74	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.33	15.85	1.08	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:32:9	32.72	2394	2.07	13.4	107	197	Off Idle	74.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.13	15.68	1.07	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:9	32.72	2392	2.08	13.41	107	197	Off Idle	73.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.03	15.58	1.06	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:32:9	32.72	2395	2.09	13.41	107	197	Off Idle	73.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.99	15.51	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:32:9	32.72	2394	2.11	13.41	107	197	Off Idle	73.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.86	15.46	1.05	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:33:0	32.72	2392	2.13	13.41	107	197	Off Idle	73.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.82	15.42	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:33:0	32.72	2392	2.14	13.41	107	197	Off Idle	73.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.79	15.42	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:33:0	32.72	2370	2.16	13.41	107	197	Off Idle	73.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.76	15.44	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:0	32.72	2363	2.17	13.41	107	197	Off Idle	73	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.73	15.49	1.06	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:0	32.72	2363	2.18	13.41	107	196	Off Idle	72.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.7	15.5	1.06	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:0	32.72	2368	2.2	13.4	107	196	Off Idle	72.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.64	15.52	1.06	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:1	32.72	2368	2.21	13.4	107	196	Off Idle	72.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.58	15.53	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:1	32.72	2372	2.21	13.4	107	196	Off Idle	72.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.53	15.52	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:1	32.72	2379	2.21	13.41	107	196	Off Idle	72.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.52	15.51	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:1	32.72	2381	2.21	13.41	107	197	Off Idle	72.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.52	15.54	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:1	32.72	2381	2.21	13.42	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.53	15.5	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:1	32.72	2382	2.21	13.42	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.54	15.42	1.05	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:1	32.72	2382	2.21	13.41	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.55	15.32	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:2	32.72	2382	2.21	13.39	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.53	15.27	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:33:2	32.72	2381	2.21	13.39	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.53	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:2	32.72	2380	2.21	13.39	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.55	15.06	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:2	32.72	2380	2.21	13.37	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.58	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:2	32.72	2378	2.21	13.38	107	197	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.6	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:2	32.72	2390	2.21	13.41	107	197	Off Idle	72.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.6	14.86	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:3	32.72	2384	2.21	13.41	107	197	Off Idle	73	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.59	14.8	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:3	32.72	2391	2.21	13.41	107	197	Off Idle	73.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.59	14.8	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:3	32.72	2393	2.21	13.41	107	197	Off Idle	73.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.6	14.81	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:3	32.72	2396	2.21	13.41	107	197	Off Idle	73.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.57	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:3	32.72	2399	2.21	13.41	107	196	Off Idle	73	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.55	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:3	32.72	2399	2.21	13.38	107	196	Off Idle	73	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.6	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:4	32.72	2398	2.21	13.39	107	196	Off Idle	72.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.56	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:4	32.72	2397	2.21	13.41	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.55	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:4	32.72	2399	2.21	13.41	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.6	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:4	32.72	2398	2.21	13.39	107	197	Off Idle	72.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.6	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:4	32.72	2399	2.21	13.4	106	197	Off Idle	72.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.63	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:4	32.72	2400	2.21	13.39	106	197	Off Idle	72.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.63	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:4	32.72	2403	2.21	13.39	107	197	Off Idle	72.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:5	32.72	2402	2.21	13.38	107	197	Off Idle	72.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.63	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:5	32.72	2401	2.21	13.39	107	197	Off Idle	72.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:5	32.72	2403	2.21	13.4	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.79	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:5	32.72	2408	2.21	13.41	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.66	14.75	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:5	32.72	2425	2.21	13.41	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.67	14.73	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:5	32.72	2406	2.21	13.39	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.71	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:33:6	32.72	2403	2.21	13.39	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.7	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:6	32.72	2403	2.21	13.4	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.68	14.65	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:6	32.72	2401	2.22	13.41	107	197	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.69	14.63	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:6	32.72	2400	2.22	13.41	107	196	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.69	14.6	0.99	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:33:6	32.72	2404	2.22	13.41	107	196	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.67	14.57	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:6	32.72	2404	2.22	13.41	107	196	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.62	14.55	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:6	32.72	2410	2.22	13.41	107	197	Off Idle	71.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.58	14.53	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:7	32.72	2416	2.22	13.4	107	197	Off Idle	71.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.57	14.52	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:7	32.72	2416	2.22	13.4	107	197	Off Idle	71.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.56	14.52	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:7	32.72	2420	2.22	13.39	107	197	Off Idle	71.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.59	14.52	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:7	32.72	2423	2.22	13.41	107	197	Off Idle	71.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.61	14.52	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:7	32.72	2426	2.22	13.4	107	197	Off Idle	71.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.66	14.55	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:7	32.72	2420	2.22	13.4	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.56	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:8	32.72	2420	2.22	13.4	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.63	14.56	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:8	32.72	2422	2.22	13.42	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.63	14.57	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:8	32.72	2414	2.22	13.42	107	197	Off Idle	71	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.65	14.58	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:8	32.72	2416	2.22	13.4	107	197	Off Idle	71	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.65	14.57	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:8	32.72	2416	2.22	13.39	107	197	Off Idle	71	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.62	14.58	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:8	32.72	2421	2.22	13.39	107	197	Off Idle	71	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.6	14.57	0.99	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:9	32.72	2426	2.22	13.38	107	197	Off Idle	71	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.61	14.57	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:9	32.72	2428	2.22	13.38	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.61	14.57	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:9	32.72	2426	2.22	13.39	107	197	Off Idle	71.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.6	14.58	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:9	32.72	2423	2.23	13.38	107	196	Off Idle	71.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.55	14.6	0.99	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:9	32.72	2426	2.23	13.39	107	196	Off Idle	71	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.48	14.61	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:9	32.72	2427	2.23	13.39	107	196	Off Idle	70.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.46	14.62	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:33:9	32.72	2430	2.23	13.39	107	196	Off Idle	70.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.39	14.63	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:34:0	32.72	2430	2.24	13.4	107	196	Off Idle	70.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.39	14.66	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:34:0	32.72	2436	2.24	13.4	107	196	Off Idle	70.9	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.38	14.67	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:34:0	32.72	2438	2.24	13.41	107	197	Off Idle	70.9	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.32	14.68	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:34:0	32.72	2439	2.24	13.42	107	197	Off Idle	70.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.31	14.7	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:0	32.72	2435	2.25	13.41	107	197	Off Idle	70.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.31	14.71	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:0	32.72	2452	2.25	13.41	107	197	Off Idle	70.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.3	14.73	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:1	32.72	2437	2.25	13.41	107	197	Off Idle	70.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.31	14.75	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:1	32.72	2440	2.26	13.4	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.31	14.75	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:1	32.72	2445	2.26	13.4	107	196	Off Idle	70.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.31	14.75	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:1	32.72	2445	2.26	13.4	107	196	Off Idle	70.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.27	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:1	32.72	2444	2.27	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.27	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:1	32.72	2444	2.27	13.41	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.25	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:1	32.72	2446	2.27	13.41	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.22	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:2	32.72	2449	2.28	13.42	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.24	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:2	32.72	2449	2.28	13.43	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.25	14.92	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:2	32.72	2451	2.28	13.42	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.19	14.97	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:2	32.72	2448	2.28	13.43	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.19	15.02	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:2	32.72	2444	2.28	13.42	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.15	15.05	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:2	32.72	2444	2.28	13.43	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.14	15.13	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:3	32.72	2443	2.29	13.43	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.13	15.16	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:3	32.72	2434	2.29	13.41	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.12	15.16	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:3	32.72	2434	2.29	13.41	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.08	15.14	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:3	32.72	2447	2.29	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.08	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:34:3	32.72	2454	2.29	13.39	107	197	Off Idle	70.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.05	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:3	32.72	2458	2.3	13.37	107	196	Off Idle	70.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.01	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:4	32.72	2458	2.3	13.4	107	196	Off Idle	70.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.98	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:34:4	32.72	2464	2.3	13.4	107	196	Off Idle	70	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.98	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:34:4	32.72	2470	2.31	13.41	107	196	Off Idle	69.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.95	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:34:4	32.72	2476	2.32	13.41	107	196	Off Idle	69.7	0	2	132	944 Turbo	0.26	Rich	1	14.6	-4.9	14.9	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:34:4	32.72	2478	2.32	13.4	107	196	Off Idle	69.6	0	2	132	944 Turbo	0.18	Rich	1	14.6	-4.83	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:4	32.72	2474	2.33	13.4	107	196	Off Idle	69.5	0	2	132	944 Turbo	0.14	Rich	1	14.6	-4.76	14.84	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:4	32.72	2474	2.33	13.4	107	197	Off Idle	69.3	0	2	132	944 Turbo	0.12	Rich	1	14.6	-4.69	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:34:5	32.72	2469	2.34	13.4	107	197	Off Idle	69.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.67	14.9	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:5	32.72	2469	2.34	13.39	107	197	Off Idle	69.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.66	14.94	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:5	32.72	2466	2.35	13.4	107	196	Off Idle	68.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.62	14.97	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:5	32.72	2470	2.35	13.4	107	196	Off Idle	68.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.6	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:5	32.72	2471	2.36	13.39	107	196	Off Idle	68.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.56	15.04	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:5	32.72	2478	2.37	13.39	107	196	Off Idle	68.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.49	15.1	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:6	32.72	2484	2.37	13.38	107	196	Off Idle	68.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.4	15.14	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:6	32.72	2480	2.39	13.39	107	196	Off Idle	68.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.34	15.18	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:6	32.72	2480	2.4	13.39	107	196	Off Idle	68.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.25	15.19	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:34:6	32.72	2478	2.41	13.39	107	196	Off Idle	68.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.2	15.19	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:34:6	32.72	2479	2.41	13.39	107	196	Off Idle	68.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.08	15.2	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:34:6	32.72	2479	2.43	13.4	107	196	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.03	15.2	1.04	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:34:6	32.72	2486	2.43	13.4	107	196	Off Idle	68.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.96	15.18	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:34:7	32.72	2493	2.44	13.4	107	197	Off Idle	68.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.83	15.12	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:34:7	32.72	2495	2.45	13.41	107	197	Off Idle	68.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.74	15.06	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:7	32.72	2496	2.46	13.4	107	197	Off Idle	68.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.69	14.99	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:7	32.72	2499	2.47	13.4	107	196	Off Idle	68.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.6	14.94	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:7	32.72	2506	2.48	13.4	107	196	Off Idle	68.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.54	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:7	32.72	2509	2.49	13.41	107	196	Off Idle	68	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.44	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:8	32.72	2509	2.5	13.4	107	196	Off Idle	67.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.41	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:8	32.72	2506	2.51	13.41	107	196	Off Idle	67.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.36	14.78	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:8	32.72	2504	2.52	13.4	107	196	Off Idle	67.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.35	14.77	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:8	32.72	2502	2.53	13.41	107	196	Off Idle	67.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.29	14.78	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:8	32.72	2500	2.53	13.4	107	196	Off Idle	67	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.26	14.81	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:34:8	32.72	2504	2.54	13.41	107	196	Off Idle	66.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.19	14.82	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:34:9	32.72	2506	2.55	13.41	107	196	Off Idle	66.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.06	14.83	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:34:9	32.72	2516	2.56	13.41	107	196	Off Idle	66.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.04	14.81	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:34:9	32.72	2522	2.56	13.4	107	196	Off Idle	66.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.07	14.83	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:34:9	32.72	2522	2.56	13.4	107	196	Off Idle	66.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.09	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:9	32.72	2521	2.57	13.4	107	196	Off Idle	66	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.1	14.8	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:9	32.72	2518	2.57	13.4	107	197	Off Idle	65.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.09	14.77	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:34:9	32.72	2509	2.57	13.41	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.06	14.75	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:35:0	32.72	2509	2.58	13.4	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.02	14.73	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:0	32.72	2513	2.58	13.4	107	196	Off Idle	65.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3	14.72	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:0	32.72	2521	2.58	13.39	107	196	Off Idle	65.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.02	14.71	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:0	32.72	2529	2.58	13.39	107	196	Off Idle	65.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.05	14.73	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:0	32.72	2529	2.58	13.41	107	196	Off Idle	65.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.06	14.72	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:0	32.72	2539	2.59	13.41	107	196	Off Idle	65.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.05	14.71	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:1	32.72	2532	2.59	13.39	107	196	Off Idle	65.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3	14.71	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:35:1	32.72	2550	2.59	13.39	107	196	Off Idle	65.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.95	14.72	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:35:1	32.72	2541	2.59	13.4	107	196	Off Idle	65.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.93	14.72	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:35:1	32.72	2534	2.59	13.38	107	196	Off Idle	65.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.96	14.72	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:35:1	32.72	2531	2.59	13.38	107	196	Off Idle	65	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.93	14.72	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:1	32.72	2532	2.59	13.38	107	196	Off Idle	64.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.93	14.73	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:1	32.72	2533	2.59	13.38	107	197	Off Idle	64.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.9	14.75	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:35:2	32.72	2542	2.6	13.38	107	197	Off Idle	64.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.88	14.75	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:2	32.72	2549	2.6	13.4	107	197	Off Idle	64.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.77	14.75	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:2	32.72	2549	2.61	13.4	107	196	Off Idle	64.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.67	14.76	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:35:2	32.72	2556	2.61	13.41	107	196	Off Idle	63.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.51	14.78	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:35:2	32.72	2564	2.62	13.42	107	196	Off Idle	63.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.37	14.78	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:35:2	32.72	2556	2.63	13.4	107	196	Off Idle	63.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.27	14.8	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:3	32.72	2559	2.63	13.38	107	196	Off Idle	63.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.21	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:3	32.72	2563	2.64	13.38	107	196	Off Idle	63.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-2.07	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:3	32.72	2571	2.65	13.38	107	196	Off Idle	63.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-2.03	14.82	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:35:3	32.72	2572	2.66	13.39	107	196	Off Idle	63.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-2.01	14.83	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:35:3	32.72	2576	2.67	13.39	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-1.99	14.83	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:35:3	32.72	2576	2.67	13.39	107	197	Off Idle	62.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-1.96	14.83	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:35:4	32.72	2577	2.68	13.39	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.29	Rich	1	14.6	-1.99	14.87	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:35:4	32.72	2577	2.69	13.38	107	196	Off Idle	62.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-2.02	14.9	1.02	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:35:4	32.72	2576	2.7	13.41	107	196	Off Idle	62.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-1.98	14.93	1.02	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:4	32.72	2580	2.71	13.4	107	196	Off Idle	62.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-1.96	14.95	1.02	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:4	32.72	2580	2.71	13.4	107	196	Off Idle	62.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-1.86	15.01	1.02	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:4	32.72	2581	2.72	13.41	107	196	Off Idle	62.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.85	15.05	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:4	32.72	2583	2.72	13.39	107	196	Off Idle	62.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.85	15.08	1.03	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:5	32.72	2583	2.73	13.38	107	196	Off Idle	62.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.81	15.08	1.03	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:5	32.72	2584	2.73	13.38	107	197	Off Idle	62.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.81	15.05	1.03	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:5	32.72	2587	2.73	13.39	107	197	Off Idle	61.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.81	14.94	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:5	32.72	2591	2.73	13.39	107	197	Off Idle	61.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.77	14.86	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:5	32.72	2600	2.73	13.4	107	196	Off Idle	61.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.82	14.77	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:5	32.72	2592	2.73	13.39	107	196	Off Idle	61.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.8	14.69	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:6	31.36	2606	2.73	13.4	107	196	Off Idle	61.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.75	14.64	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:6	31.36	2609	2.73	13.41	107	196	Off Idle	61.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.73	14.5	0.99	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:6	31.36	2608	2.74	13.41	107	196	Off Idle	61.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.72	14.45	0.98	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:6	31.36	2604	2.74	13.43	107	196	Off Idle	60.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.69	14.41	0.98	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:6	31.36	2614	2.74	13.42	107	196	Off Idle	60.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.75	14.4	0.98	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:6	32.72	2607	2.74	13.42	107	196	Off Idle	60.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.74	14.43	0.98	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:6	32.72	2607	2.74	13.41	107	196	Off Idle	60.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.76	14.46	0.98	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:7	32.72	2609	2.75	13.41	107	196	Off Idle	60.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.76	14.48	0.99	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:7	32.72	2613	2.75	13.4	107	196	Off Idle	60.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.8	14.51	0.99	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:7	32.72	2613	2.75	13.41	107	196	Off Idle	60.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.78	14.53	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:7	32.72	2616	2.75	13.4	107	196	Off Idle	60.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.72	14.57	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:7	32.72	2624	2.76	13.41	107	196	Off Idle	60.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.66	14.6	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:7	32.72	2624	2.76	13.41	107	196	Off Idle	60.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.62	14.62	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:8	32.72	2621	2.76	13.41	107	196	Off Idle	60.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.58	14.64	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:35:8	31.36	2634	2.76	13.4	107	196	Off Idle	60	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.61	14.65	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:8	31.36	2634	2.76	13.39	107	196	Off Idle	60	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.62	14.64	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:8	31.36	2635	2.76	13.38	107	196	Off Idle	60	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.68	14.65	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:8	31.36	2646	2.77	13.38	107	196	Off Idle	59.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.64	14.66	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:8	32.72	2632	2.77	13.38	107	196	Off Idle	59.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.68	14.67	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:9	32.72	2638	2.77	13.39	107	196	Off Idle	59.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.64	14.67	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:9	32.72	2642	2.77	13.4	107	196	Off Idle	59.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.63	14.69	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:9	32.72	2644	2.77	13.41	107	196	Off Idle	59.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.6	14.68	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:9	32.72	2673	2.77	13.41	107	196	Off Idle	59.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.6	14.69	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:9	32.72	2655	2.77	13.41	107	196	Off Idle	59.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.58	14.7	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:9	32.72	2654	2.77	13.41	107	196	Off Idle	58.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.61	14.7	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:35:9	32.72	2657	2.77	13.42	107	196	Off Idle	58.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.73	14.7	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:0	32.72	2656	2.77	13.41	107	196	Off Idle	58.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.69	14.71	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:36:0	32.72	2645	2.77	13.41	107	196	Off Idle	58.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.75	14.72	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:36:0	32.72	2645	2.77	13.41	107	196	Off Idle	58	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.71	14.74	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:0	32.72	2640	2.77	13.41	107	196	Off Idle	58	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.65	14.75	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:0	32.72	2652	2.77	13.41	107	196	Off Idle	58	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1.64	14.7	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:36:0	31.36	2669	2.77	13.41	107	196	Off Idle	58	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.65	14.71	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:36:1	31.36	2669	2.77	13.41	107	196	Off Idle	57.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-1.68	14.71	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:36:1	31.36	2676	2.77	13.4	107	196	Off Idle	57.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.73	14.73	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:36:1	31.36	2675	2.77	13.41	107	197	Off Idle	57.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-1.73	14.72	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:36:1	31.36	2676	2.77	13.41	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-1.75	14.72	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:36:1	31.36	2676	2.77	13.4	107	197	Off Idle	57.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.75	14.73	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:36:1	31.36	2676	2.77	13.4	107	196	Off Idle	57.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-1.77	14.74	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:36:1	31.36	2675	2.77	13.41	107	196	Off Idle	57.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-1.8	14.75	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:36:2	32.72	2683	2.77	13.39	107	196	Off Idle	57.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-1.86	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:2	32.72	2683	2.76	13.4	107	196	Off Idle	57.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-1.92	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:2	32.72	2683	2.76	13.39	107	196	Off Idle	57.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-1.96	14.94	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:2	32.72	2684	2.76	13.38	107	196	Off Idle	57	0	2	132	944 Turbo	0.52	Lean	1	14.6	-1.96	14.97	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:2	32.72	2683	2.76	13.39	107	196	Off Idle	56.7	0	2	132	944 Turbo	0.58	Lean	1	14.6	-1.99	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:2	32.72	2683	2.76	13.39	107	196	Off Idle	56.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.01	15.01	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:3	32.72	2687	2.75	13.39	107	196	Off Idle	56.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.02	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:36:3	32.72	2687	2.75	13.4	107	196	Off Idle	56.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.06	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:3	32.72	2688	2.75	13.41	107	196	Off Idle	56	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.1	14.96	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:3	32.72	2687	2.75	13.4	107	196	Off Idle	55.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.12	14.93	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:3	32.72	2692	2.74	13.4	107	196	Off Idle	55.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.12	14.89	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:3	32.72	2692	2.74	13.41	107	196	Off Idle	55.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.17	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:4	32.72	2700	2.74	13.39	107	196	Off Idle	55.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-2.17	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:4	32.72	2708	2.74	13.4	107	196	Off Idle	55.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-2.19	14.75	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:4	32.72	2714	2.74	13.39	107	196	Off Idle	55.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-2.27	14.77	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:4	32.72	2716	2.74	13.37	107	196	Off Idle	55.2	0	2	132	944 Turbo	0.21	Rich	1	14.6	-2.23	14.79	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:4	32.72	2717	2.73	13.39	107	196	Off Idle	55.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.27	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:4	32.72	2716	2.73	13.39	107	196	Off Idle	55.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.32	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:4	32.72	2716	2.73	13.41	107	196	Off Idle	55.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-2.34	14.94	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:5	32.72	2716	2.73	13.41	107	196	Off Idle	55.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-2.34	14.98	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:5	32.72	2716	2.73	13.41	107	196	Off Idle	55.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.37	15.02	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:5	32.72	2726	2.73	13.39	107	196	Off Idle	55	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.3	15.06	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:5	32.72	2718	2.73	13.4	107	196	Off Idle	54.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.33	15.1	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:5	32.72	2717	2.72	13.39	107	196	Off Idle	54.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.35	15.14	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:5	32.72	2722	2.72	13.4	107	196	Off Idle	54.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-2.34	15.12	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:6	32.72	2728	2.72	13.41	107	197	Off Idle	54.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-2.36	15.12	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:6	32.72	2728	2.72	13.4	107	197	Off Idle	54.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-2.4	15.11	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:6	32.72	2732	2.72	13.39	107	197	Off Idle	54	0	2	132	944 Turbo	0.47	Rich	1	14.6	-2.32	15.11	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:6	32.72	2736	2.72	13.39	107	196	Off Idle	53.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.36	15.09	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:6	32.72	2736	2.72	13.4	107	196	Off Idle	53.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-2.4	15.08	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:6	32.72	2735	2.72	13.41	107	196	Off Idle	53.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.4	15.07	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:6	32.72	2734	2.73	13.41	107	196	Off Idle	53.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.38	15.05	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:7	32.72	2733	2.73	13.41	107	196	Off Idle	53.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.41	15	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:7	32.72	2737	2.73	13.4	107	196	Off Idle	53.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.36	14.99	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:7	32.72	2736	2.73	13.41	107	196	Off Idle	53	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.36	14.98	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:7	32.72	2721	2.73	13.41	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-2.37	14.95	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:7	32.72	2736	2.73	13.4	107	196	Off Idle	52.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.37	14.9	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:7	32.72	2740	2.73	13.39	107	196	Off Idle	52.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.35	14.88	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:8	32.72	2754	2.73	13.4	107	196	Off Idle	52.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-2.36	14.85	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:8	32.72	2788	2.73	13.4	107	196	Off Idle	52.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.36	14.86	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:8	32.72	2766	2.73	13.39	107	196	Off Idle	52.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.32	14.89	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:8	32.72	2764	2.73	13.4	107	196	Off Idle	52.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.35	14.92	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:8	32.72	2762	2.73	13.4	107	196	Off Idle	52.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.38	14.96	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:36:8	32.72	2758	2.73	13.4	107	196	Off Idle	52.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.38	14.99	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:9	32.72	2756	2.73	13.39	107	196	Off Idle	52.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-2.38	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:9	32.72	2754	2.73	13.4	107	196	Off Idle	52.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-2.4	15.06	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:36:9	32.72	2754	2.73	13.41	107	196	Off Idle	52.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-2.39	15.12	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:9	32.72	2760	2.73	13.41	107	196	Off Idle	52.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.4	15.15	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:9	32.72	2760	2.73	13.43	107	196	Off Idle	52.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.41	15.13	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:9	32.72	2761	2.74	13.42	107	196	Off Idle	52.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.4	15.12	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:36:9	32.72	2766	2.74	13.41	107	196	Off Idle	52.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.37	15.09	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:37:0	32.72	2783	2.74	13.41	107	196	Off Idle	52.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.35	15.05	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:0	32.72	2783	2.74	13.4	107	196	Off Idle	52	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.38	15.02	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:0	32.72	2796	2.74	13.4	107	196	Off Idle	52	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.36	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:0	32.72	2797	2.74	13.4	107	196	Off Idle	51.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.33	14.95	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:0	32.72	2795	2.75	13.4	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-2.32	14.87	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:0	32.72	2788	2.75	13.41	106	196	Off Idle	51.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-2.34	14.81	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:1	32.72	2785	2.75	13.41	106	196	Off Idle	50.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.3	14.79	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:37:1	32.72	2781	2.75	13.41	106	196	Off Idle	50.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-2.25	14.78	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:37:1	32.72	2781	2.75	13.39	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.25	14.78	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:37:1	32.72	2776	2.76	13.41	107	196	Off Idle	50.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.28	14.81	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:37:1	32.72	2792	2.76	13.39	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.27	14.84	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:37:1	32.72	2800	2.76	13.4	107	196	Off Idle	50.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-2.27	14.88	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:1	32.72	2800	2.76	13.4	107	196	Off Idle	50	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.27	14.92	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:2	32.72	2801	2.76	13.41	107	196	Off Idle	50	0	2	132	944 Turbo	0.33	Rich	1	14.6	-2.24	14.97	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:37:2	32.72	2810	2.76	13.41	107	196	Off Idle	50	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.23	15.06	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:37:2	32.72	2807	2.77	13.41	107	196	Off Idle	49.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-2.18	15.1	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:37:2	32.72	2807	2.77	13.41	107	196	Off Idle	49.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-2.26	15.13	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:37:2	32.72	2807	2.77	13.41	107	196	Off Idle	49.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.27	15.12	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:37:2	32.72	2806	2.77	13.41	107	196	Off Idle	49.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.31	15.1	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:37:3	32.72	2806	2.77	13.4	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.29	15.05	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:3	32.72	2806	2.77	13.39	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.33	15.02	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:3	32.72	2809	2.77	13.39	107	196	Off Idle	49.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.29	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:37:3	32.72	2810	2.77	13.4	107	196	Off Idle	49.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.3	14.91	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:3	32.72	2810	2.77	13.39	107	196	Off Idle	49.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.31	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:3	32.72	2814	2.77	13.4	107	196	Off Idle	48.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.29	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:4	32.72	2818	2.77	13.4	107	196	Off Idle	48.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.29	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:4	32.72	2827	2.77	13.4	107	196	Off Idle	48.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.3	14.79	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:4	32.72	2829	2.77	13.41	106	196	Off Idle	48.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.33	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:4	32.72	2832	2.77	13.43	106	196	Off Idle	48.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-2.41	14.79	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:4	32.72	2833	2.77	13.42	107	196	Off Idle	48.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-2.4	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:4	32.72	2833	2.77	13.41	107	196	Off Idle	48.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-2.42	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:4	32.72	2834	2.77	13.4	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-2.4	14.88	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:5	32.72	2835	2.77	13.38	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.4	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:5	32.72	2838	2.77	13.39	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.4	14.96	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:5	32.72	2839	2.77	13.39	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-2.43	14.99	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:5	32.72	2839	2.77	13.41	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-2.43	15.04	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:5	32.72	2835	2.77	13.4	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-2.44	15.08	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:37:5	32.72	2838	2.77	13.4	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.45	15.12	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:6	32.72	2837	2.77	13.41	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-2.4	15.15	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:6	32.72	2837	2.77	13.42	107	196	Off Idle	48.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-2.38	15.16	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:6	32.72	2845	2.77	13.41	107	196	Off Idle	48.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-2.42	15.13	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:6	32.72	2853	2.77	13.4	107	196	Off Idle	48.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.4	15.1	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:6	32.72	2860	2.77	13.4	107	196	Off Idle	47.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.42	15.05	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:6	32.72	2860	2.77	13.4	107	196	Off Idle	47.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-2.48	14.98	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:6	32.72	2862	2.77	13.4	107	196	Off Idle	47.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-2.52	14.94	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:7	32.72	2862	2.77	13.41	107	196	Off Idle	47.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-2.55	14.89	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:7	32.72	2864	2.77	13.41	107	196	Off Idle	47.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.54	14.87	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:37:7	32.72	2864	2.77	13.43	107	196	Off Idle	47.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-2.57	14.8	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:37:7	32.72	2865	2.77	13.42	107	196	Off Idle	47	0	2	132	944 Turbo	0.3	Rich	1	14.6	-2.58	14.78	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:37:7	32.72	2865	2.77	13.43	107	196	Off Idle	46.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-2.62	14.79	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:37:7	32.72	2862	2.76	13.41	106	196	Off Idle	46.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-2.72	14.84	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:37:8	32.72	2862	2.76	13.41	106	196	Off Idle	46.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-2.76	14.88	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:37:8	32.72	2862	2.75	13.39	106	196	Off Idle	46.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-2.84	14.92	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:37:8	32.72	2870	2.75	13.41	107	196	Off Idle	46.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-2.93	14.96	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:37:8	32.72	2867	2.75	13.4	107	196	Off Idle	46.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-2.96	15.02	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:37:8	32.72	2867	2.74	13.41	107	196	Off Idle	45.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3	15.03	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:37:8	32.72	2864	2.74	13.41	107	196	Off Idle	45.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.02	15.05	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:37:9	32.72	2866	2.73	13.42	107	196	Off Idle	45.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.05	15.04	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:37:9	34.08	2877	2.73	13.41	107	196	Off Idle	45.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.06	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:37:9	34.08	2876	2.73	13.43	107	196	Off Idle	45.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.07	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:37:9	34.08	2876	2.72	13.43	107	196	Off Idle	45.8	0	2	132	944 Turbo	0.66	Lean	1	14.6	-3.1	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:37:9	34.08	2878	2.72	13.42	107	196	Off Idle	45.8	0	2	132	944 Turbo	0.57	Lean	1	14.6	-3.18	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:37:9	32.72	2868	2.72	13.41	107	196	Off Idle	45.8	0	2	132	944 Turbo	0.5	Lean	1	14.6	-3.17	14.72	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:37:9	32.72	2884	2.71	13.42	107	196	Off Idle	45.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.21	14.64	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:38:0	32.72	2886	2.71	13.41	107	196	Off Idle	45.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.21	14.6	0.99	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:38:0	32.72	2893	2.7	13.41	107	196	Off Idle	45.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.24	14.59	0.99	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:38:0	32.72	2916	2.7	13.4	107	196	Off Idle	45.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-3.21	14.61	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:38:0	34.08	2916	2.7	13.4	107	196	Off Idle	45.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.21	14.67	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:38:0	34.08	2892	2.7	13.38	107	196	Off Idle	45.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.13	14.74	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:38:0	34.08	2892	2.7	13.36	107	196	Off Idle	45	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.1	14.81	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:38:1	34.08	2896	2.71	13.37	107	196	Off Idle	45	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3	14.93	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:1	34.08	2892	2.71	13.37	107	196	Off Idle	44.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.91	15.04	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:38:1	32.72	2905	2.72	13.37	107	196	Off Idle	44.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.81	15.1	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:38:1	32.72	2907	2.73	13.37	107	196	Off Idle	44.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.75	15.2	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:38:1	32.72	2911	2.73	13.4	107	196	Off Idle	44.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.61	15.25	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:38:1	32.72	2914	2.74	13.38	107	196	Off Idle	44.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.58	15.28	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:38:1	32.72	2916	2.75	13.39	107	196	Off Idle	44.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.54	15.28	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:2	32.72	2923	2.76	13.39	107	196	Off Idle	44.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.38	15.26	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:38:2	32.72	2923	2.77	13.4	107	196	Off Idle	43.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-2.29	15.25	1.04	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:38:2	32.72	2920	2.78	13.42	107	196	Off Idle	43.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-2.22	15.22	1.04	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:2	32.72	2917	2.79	13.42	107	196	Off Idle	43.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.09	15.22	1.04	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:2	32.72	2910	2.8	13.42	107	196	Off Idle	43.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.03	15.19	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:38:2	32.72	2921	2.81	13.42	107	196	Off Idle	43.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-2.04	15.18	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:38:3	32.72	2922	2.82	13.41	107	196	Off Idle	43.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-1.91	15.17	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:3	32.72	2926	2.83	13.4	107	196	Off Idle	43.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-1.91	15.21	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:3	32.72	2936	2.84	13.41	107	196	Off Idle	43.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-1.87	15.2	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:3	32.72	2936	2.85	13.39	107	196	Off Idle	43.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-1.77	15.16	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:3	32.72	2932	2.86	13.39	107	196	Off Idle	43.1	0	2	132	944 Turbo	0.67	Lean	1	14.6	-1.82	15.12	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:3	32.72	2938	2.86	13.4	107	196	Off Idle	42.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.8	15.07	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:4	32.72	2947	2.87	13.41	107	196	Off Idle	42.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.75	15.02	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:4	32.72	2947	2.87	13.41	107	196	Off Idle	42.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.72	14.96	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:4	32.72	2946	2.88	13.42	107	196	Off Idle	42.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.73	14.89	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:4	32.72	2946	2.88	13.42	107	196	Off Idle	42.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.68	14.8	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:4	32.72	2943	2.88	13.41	107	196	Off Idle	42.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.66	14.71	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:4	32.72	2942	2.88	13.41	107	196	Off Idle	42	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.68	14.64	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:4	32.72	2946	2.89	13.4	107	196	Off Idle	41.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.62	14.64	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:5	32.72	2957	2.89	13.41	107	196	Off Idle	41.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.57	14.63	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:5	32.72	2958	2.89	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.55	14.63	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:5	32.72	2970	2.89	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.53	14.65	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:38:5	32.72	2970	2.9	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.51	14.66	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:38:5	32.72	2964	2.9	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.52	14.69	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:38:5	32.72	2968	2.9	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.54	14.7	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:6	32.72	2969	2.9	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.53	14.73	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:6	32.72	2968	2.91	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.51	14.73	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:6	32.72	2968	2.91	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.43	14.72	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:6	32.72	2966	2.91	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.41	14.73	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:38:6	32.72	2966	2.92	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.28	14.73	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:38:6	32.72	2973	2.92	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.24	14.73	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:38:6	32.72	2981	2.93	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.1	14.75	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:38:7	32.72	2986	2.94	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.06	14.76	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:38:7	32.72	2988	2.94	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.96	14.78	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:38:7	32.72	2991	2.95	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-0.91	14.77	1.01	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:38:7	32.72	2997	2.95	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-0.82	14.78	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:7	32.72	2998	2.96	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-0.78	14.78	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:7	32.72	2998	2.96	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-0.68	14.79	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:8	32.72	3002	2.97	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-0.6	14.81	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:16:38:8	32.72	3001	2.98	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-0.57	14.82	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:16:38:8	32.72	3003	2.98	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-0.51	14.81	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:8	32.72	3008	2.99	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-0.56	14.86	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:8	32.72	3011	3	13.42	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-0.6	14.9	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:8	32.72	3012	3	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.6	14.91	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:9	32.72	3010	3.01	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-0.6	14.9	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:9	32.72	3020	3.01	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.58	14.87	1.01	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:38:9	32.72	3008	3.01	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.56	14.82	1.01	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:38:9	32.72	3008	3.02	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.56	14.73	1	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:16:38:9	32.72	3018	3.02	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.51	14.65	1	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:38:9	32.72	3010	3.02	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.6	14.58	0.99	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:38:9	32.72	3030	3.02	13.39	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.59	14.39	0.98	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:0	32.72	3034	3.02	13.38	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.6	14.31	0.97	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:0	32.72	3034	3.02	13.36	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.63	14.25	0.97	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:39:0	32.72	3036	3.02	13.38	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.74	14.21	0.97	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:0	32.72	3036	3.01	13.39	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.87	14.21	0.97	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:39:0	32.72	3042	3.01	13.38	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.08	14.25	0.97	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:39:0	32.72	3043	3	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.15	14.27	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:39:1	32.72	3043	3	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.35	14.31	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:39:1	32.72	3041	2.99	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.41	14.36	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:39:1	32.72	3038	2.98	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.64	14.41	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:39:1	32.72	3037	2.97	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.75	14.45	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:39:1	32.72	3036	2.95	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.12	14.49	0.99	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:1	32.72	3034	2.92	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.48	14.49	0.99	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:1	34.08	3031	2.87	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.02	14.49	0.99	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:39:2	34.08	3031	2.83	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.48	14.48	0.99	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:39:2	34.08	3040	2.78	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.95	14.48	0.99	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:39:2	34.08	3039	2.74	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.39	14.49	0.99	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:39:2	35.45	3052	2.7	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.77	14.5	0.99	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:39:2	35.45	3052	2.66	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.18	14.53	0.99	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:39:2	35.45	3006	2.64	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.54	14.55	0.99	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:39:3	35.45	2970	2.58	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.98	14.57	0.99	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:39:3	35.45	2957	2.54	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.14	14.57	0.99	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:39:3	35.45	2958	2.5	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.3	14.56	0.99	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:39:3	35.45	2953	2.46	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.43	14.55	0.99	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:39:3	35.45	2946	2.4	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.56	14.49	0.99	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:39:3	35.45	2949	2.36	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.66	14.45	0.98	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:39:4	35.45	2949	2.32	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.82	14.43	0.98	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:39:4	35.45	2964	2.28	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.95	14.43	0.98	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:39:4	35.45	3010	2.21	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.17	14.43	0.98	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:4	35.45	3030	2.18	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.29	14.52	0.99	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:4	35.45	3040	2.15	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.38	14.72	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:4	35.45	3050	2.12	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.55	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:4	36.81	3055	2.11	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.61	15.32	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:5	36.81	3049	2.1	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.76	15.86	1.08	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:5	36.81	3049	2.09	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.83	16.05	1.09	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:5	36.81	3052	2.08	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.98	16.65	1.13	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:5	36.81	3052	2.06	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.12	17.02	1.16	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:5	36.81	3047	2.04	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.23	17.53	1.19	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:39:5	36.81	3040	2.02	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.32	17.78	1.21	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:39:6	36.81	3012	2	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.39	17.94	1.22	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:6	36.81	3012	1.98	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.57	18.03	1.23	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:6	36.81	3036	1.96	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.63	18.08	1.23	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:6	36.81	3030	1.95	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.67	18.1	1.23	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:6	36.81	3013	1.93	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.82	18.06	1.23	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:39:6	36.81	3013	1.91	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.92	18.06	1.23	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:39:6	36.81	3009	1.9	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.98	18.07	1.23	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:7	36.81	3009	1.9	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.01	18.09	1.23	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:7	36.81	2995	1.88	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.05	18.13	1.24	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:7	36.81	2996	1.87	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.09	18.15	1.24	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:7	36.81	2998	1.86	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.1	18.16	1.24	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:7	36.81	3007	1.85	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	18.14	1.24	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:7	36.81	3008	1.84	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.14	18.11	1.23	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:8	36.81	3008	1.83	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.15	18.08	1.23	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:8	36.81	3016	1.83	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.2	17.99	1.23	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:8	36.81	3026	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.25	17.91	1.22	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:8	36.81	3031	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.27	17.84	1.22	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:8	36.81	3028	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.29	17.75	1.21	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:8	36.81	3029	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.3	17.69	1.2	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:9	36.81	3058	1.82	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.28	17.62	1.2	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:9	36.81	3027	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.3	17.56	1.2	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:9	36.81	3025	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.28	17.53	1.19	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:39:9	36.81	3018	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.35	17.52	1.19	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:9	36.81	3018	1.82	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.34	17.51	1.19	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:9	36.81	3011	1.82	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.34	17.5	1.19	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:39:9	36.81	3011	1.82	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.36	17.49	1.19	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:0	36.81	3006	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.36	17.5	1.19	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:0	36.81	3001	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.37	17.49	1.19	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:0	36.81	3002	1.82	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.35	17.47	1.19	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:0	36.81	3006	1.82	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.38	17.45	1.19	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:0	36.81	3000	1.82	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.38	17.41	1.19	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:0	36.81	3001	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.41	17.36	1.18	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:1	36.81	3000	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.4	17.3	1.18	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:1	36.81	3000	1.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.38	17.26	1.18	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:1	36.81	3007	1.82	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.39	17.16	1.17	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:1	36.81	3013	1.82	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.37	17.12	1.17	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:1	36.81	3011	1.82	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.33	17.05	1.16	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:1	36.81	3010	1.82	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.38	16.99	1.16	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:1	36.81	3012	1.82	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.35	16.93	1.15	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:40:2	36.81	3012	1.82	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.37	16.87	1.15	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:40:2	36.81	3009	1.83	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.35	16.77	1.14	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:40:2	36.81	3004	1.83	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.34	16.73	1.14	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:40:2	36.81	3000	1.83	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.35	16.7	1.14	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:40:2	36.81	3002	1.83	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.32	16.68	1.14	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:40:2	36.81	3004	1.84	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.3	16.65	1.13	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:40:3	36.81	3004	1.84	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.29	16.62	1.13	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:40:3	36.81	3003	1.84	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.28	16.6	1.13	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:3	36.81	3002	1.85	13.35	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.25	16.58	1.13	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:3	36.81	2998	1.85	13.34	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.21	16.56	1.13	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:3	36.81	3000	1.86	13.35	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.21	16.55	1.13	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:3	36.81	3000	1.86	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.13	16.53	1.13	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:4	36.81	3000	1.87	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.14	16.51	1.12	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:4	36.81	3026	1.87	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.07	16.49	1.12	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:4	36.81	3014	1.88	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.04	16.46	1.12	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:4	36.81	2992	1.88	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.05	16.45	1.12	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:4	36.81	2992	1.88	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.04	16.42	1.12	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:4	36.81	2984	1.89	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.02	16.4	1.12	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:4	36.81	2999	1.9	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	16.38	1.12	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:40:5	36.81	3006	1.9	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.97	16.37	1.12	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:5	36.81	3007	1.91	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.94	16.36	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:5	36.81	3009	1.91	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.91	16.35	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:5	36.81	3012	1.92	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.88	16.33	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:5	36.81	3014	1.92	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.9	16.32	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:5	36.81	3010	1.93	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.88	16.28	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:6	36.81	3013	1.93	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.87	16.27	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:6	36.81	3016	1.93	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.87	16.23	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:6	36.81	3017	1.94	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.86	16.21	1.1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:6	36.81	3014	1.94	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.83	16.18	1.1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:6	36.81	3010	1.94	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.82	16.11	1.1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:6	36.81	3008	1.95	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.83	16.07	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:6	36.81	3003	1.95	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.8	16.04	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:7	36.81	3006	1.95	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.81	16.01	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:7	36.81	3006	1.95	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.78	15.93	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:7	36.81	3004	1.95	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.73	15.9	1.08	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:7	36.81	2996	1.95	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.76	15.86	1.08	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:7	36.81	2992	1.95	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.75	15.82	1.08	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:7	36.81	2994	1.96	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.74	15.8	1.08	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:8	36.81	2995	1.96	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.73	15.76	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:8	36.81	2990	1.96	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.72	15.73	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:8	36.81	2987	1.96	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.7	15.7	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:40:8	36.81	2987	1.96	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.7	15.68	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:8	36.81	2991	1.96	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.68	15.64	1.07	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:40:8	36.81	2990	1.96	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.64	15.6	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:40:9	36.81	2992	1.96	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.63	15.57	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:40:9	36.81	2992	1.96	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.62	15.56	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:40:9	36.81	2986	1.96	13.43	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.62	15.52	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:40:9	36.81	2993	1.96	13.43	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.59	15.51	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:40:9	36.81	2993	1.96	13.43	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.62	15.5	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:9	36.81	2994	1.97	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	15.5	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:40:9	36.81	2996	1.97	13.43	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.62	15.5	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:0	36.81	2996	1.97	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.66	15.51	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:0	36.81	2994	1.97	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.68	15.53	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:0	36.81	2992	1.97	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.67	15.54	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:0	36.81	2991	1.97	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.66	15.53	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:0	36.81	2995	1.96	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.68	15.51	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:0	36.81	2996	1.96	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.71	15.5	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:1	36.81	3000	1.96	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.69	15.5	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:1	36.81	3002	1.96	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.68	15.48	1.05	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:1	36.81	3002	1.96	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.67	15.46	1.05	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:1	36.81	3002	1.96	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.65	15.4	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:1	36.81	3003	1.96	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.66	15.36	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:1	36.81	3004	1.96	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.66	15.33	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:1	36.81	2995	1.96	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.69	15.29	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:2	36.81	2992	1.96	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.67	15.25	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:2	36.81	2992	1.96	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.67	15.24	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:2	36.81	2984	1.96	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.68	15.22	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:2	36.81	2982	1.96	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.67	15.21	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:2	36.81	2982	1.97	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.63	15.19	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:41:2	36.81	2980	1.97	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.58	15.2	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:3	36.81	2975	1.98	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.51	15.19	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:3	36.81	2980	1.98	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.41	15.19	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:41:3	36.81	2982	1.99	13.35	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.35	15.2	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:41:3	36.81	2990	2	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.24	15.2	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:41:3	36.81	2995	2.01	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.1	15.19	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:41:3	36.81	3002	2.02	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8	15.17	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:41:4	36.81	3004	2.03	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.92	15.16	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:41:4	36.81	3011	2.04	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.84	15.14	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:4	36.81	3015	2.05	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.78	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:4	36.81	3015	2.06	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:4	36.81	3014	2.07	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.67	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:4	36.81	3009	2.08	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	15.05	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:41:4	36.81	3007	2.1	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.5	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:41:5	36.81	3000	2.11	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.48	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:5	36.81	2997	2.12	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.44	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:5	35.45	2984	2.14	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.37	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:5	35.45	2994	2.15	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.34	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:5	35.45	2990	2.16	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.33	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:5	35.45	2992	2.17	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.27	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:6	35.45	2991	2.18	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.25	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:6	35.45	2991	2.19	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.21	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:6	35.45	3000	2.2	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.21	15.16	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:41:6	35.45	3001	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.14	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:41:6	35.45	3011	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.08	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:41:6	35.45	3011	2.23	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.07	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:41:6	35.45	3016	2.23	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.04	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:41:7	35.45	3010	2.24	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.96	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:41:7	35.45	3007	2.24	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.93	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:41:7	35.45	3006	2.25	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.93	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:41:7	35.45	3008	2.25	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.83	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:7	35.45	3010	2.26	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.76	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:7	35.45	3017	2.27	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.73	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:8	35.45	3020	2.28	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.74	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:8	35.45	3025	2.28	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.64	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:41:8	35.45	3025	2.29	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.66	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:41:8	35.45	3023	2.3	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.58	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:41:8	35.45	3021	2.3	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.58	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:8	35.45	3021	2.31	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.49	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:9	35.45	3020	2.32	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.47	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:9	35.45	3012	2.32	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.51	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:9	35.45	3005	2.32	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.44	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:9	35.45	3005	2.33	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.47	15.14	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:9	35.45	3002	2.34	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.44	15.17	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:9	35.45	3010	2.34	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.38	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:41:9	35.45	3017	2.34	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.4	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:0	35.45	3018	2.35	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.34	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:0	35.45	3028	2.35	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.38	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:0	35.45	3031	2.35	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.34	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:0	35.45	3031	2.35	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.32	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:0	35.45	3031	2.36	13.37	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.33	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:0	35.45	3026	2.36	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.3	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:1	35.45	3022	2.36	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.33	14.72	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:1	35.45	3020	2.36	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.27	14.69	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:1	35.45	3016	2.37	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.27	14.69	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:1	35.45	3021	2.37	13.36	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.22	14.72	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:1	35.45	3022	2.37	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.27	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:1	35.45	3027	2.37	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.2	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:1	35.45	3027	2.38	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.19	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:2	35.45	3028	2.38	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.2	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:2	35.45	3032	2.38	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.19	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:2	35.45	3024	2.38	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.21	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:2	35.45	3026	2.38	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.23	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:2	35.45	3024	2.38	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.21	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:2	35.45	3002	2.38	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.21	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:3	35.45	3023	2.39	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.23	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:3	35.45	3023	2.39	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.17	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:3	35.45	3019	2.39	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.12	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:3	35.45	3018	2.39	13.37	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.14	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:3	35.45	3014	2.39	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.12	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:3	35.45	3014	2.39	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.14	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:4	35.45	3016	2.39	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.1	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:4	35.45	3018	2.39	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.13	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:4	35.45	3026	2.39	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.11	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:4	35.45	3032	2.39	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.09	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:4	35.45	3032	2.39	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.09	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:4	35.45	3037	2.4	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.03	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:4	35.45	3058	2.4	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.03	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:5	35.45	3040	2.4	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.99	14.73	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:42:5	35.45	3042	2.4	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6	14.7	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:5	35.45	3045	2.4	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.97	14.7	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:5	35.45	3053	2.41	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.98	14.7	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:5	35.45	3052	2.41	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.9	14.71	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:42:5	35.45	3052	2.41	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.84	14.72	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:6	35.45	3049	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.82	14.75	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:6	35.45	3046	2.42	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.82	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:6	35.45	3043	2.42	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.78	14.79	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:6	35.45	3034	2.43	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.8	14.8	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:42:6	35.45	3034	2.43	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.83	14.8	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:42:6	35.45	3034	2.43	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.81	14.8	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:42:6	35.45	3037	2.44	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.83	14.8	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:42:7	35.45	3023	2.45	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.73	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:42:7	35.45	3060	2.45	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.68	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:7	35.45	3060	2.45	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.66	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:7	35.45	3060	2.46	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.64	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:7	35.45	3058	2.46	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.63	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:7	35.45	3054	2.46	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.66	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:8	35.45	3046	2.47	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.63	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:8	35.45	3044	2.47	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.6	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:8	35.45	3044	2.47	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.61	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:42:8	35.45	3044	2.47	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.57	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:42:8	35.45	3051	2.48	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.55	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:42:8	35.45	3057	2.48	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.5	14.92	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:9	35.45	3060	2.48	13.37	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.5	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:9	35.45	3059	2.49	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.49	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:9	35.45	3061	2.49	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.46	14.75	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:9	35.45	3064	2.49	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.5	14.71	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:42:9	35.45	3063	2.5	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.47	14.7	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:42:9	35.45	3062	2.5	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.5	14.71	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:42:9	35.45	3057	2.5	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.45	14.72	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:0	35.45	3057	2.5	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.46	14.72	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:0	35.45	3052	2.51	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.39	14.74	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:0	35.45	3054	2.51	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.37	14.75	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:0	35.45	3054	2.51	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.37	14.78	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:0	35.45	3062	2.52	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.4	14.8	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:43:0	35.45	3066	2.52	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.34	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:43:1	35.45	3078	2.52	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.39	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:43:1	35.45	3078	2.53	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.36	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:43:1	35.45	3081	2.53	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.25	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:43:1	35.45	3080	2.53	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.28	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:1	35.45	3078	2.53	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.18	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:1	35.45	3072	2.54	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.16	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:1	35.45	3066	2.54	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.17	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:2	35.45	3066	2.54	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.11	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:2	35.45	3068	2.55	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.15	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:2	35.45	3070	2.55	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.11	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:2	35.45	3068	2.55	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.11	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:2	35.45	3073	2.55	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.12	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:2	35.45	3069	2.55	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.13	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:3	35.45	3074	2.56	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.14	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:3	35.45	3098	2.56	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.16	14.91	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:3	35.45	3088	2.56	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.13	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:3	35.45	3079	2.56	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.16	14.81	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:3	35.45	3074	2.56	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.13	14.77	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:3	35.45	3074	2.56	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.15	14.75	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:4	35.45	3068	2.56	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.11	14.76	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:4	35.45	3069	2.57	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.14	14.76	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:4	35.45	3068	2.57	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.12	14.79	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:4	35.45	3072	2.57	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.12	14.8	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:4	35.45	3072	2.57	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.13	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:4	35.45	3076	2.57	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.13	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:4	35.45	3087	2.57	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.09	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:5	35.45	3087	2.57	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.13	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:5	35.45	3098	2.57	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.08	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:5	35.45	3089	2.57	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.1	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:5	35.45	3087	2.57	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.03	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:43:5	35.45	3088	2.57	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:5	35.45	3092	2.57	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.02	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:43:6	35.45	3089	2.58	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.92	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:43:6	35.45	3085	2.58	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.91	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:43:6	35.45	3084	2.59	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.83	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:43:6	35.45	3088	2.59	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-4.74	14.84	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:6	35.45	3087	2.6	13.39	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-4.67	14.84	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:6	35.45	3087	2.6	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Rich	1	14.6	-4.57	14.86	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:6	35.45	3093	2.61	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.1	Rich	1	14.6	-4.56	14.89	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:7	35.45	3108	2.62	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.47	14.95	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:7	35.45	3108	2.62	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.48	14.98	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:7	35.45	3108	2.63	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.39	15.03	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:43:7	35.45	3109	2.64	13.4	106	196	Off Idle	41.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.37	15.09	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:7	35.45	3098	2.65	13.4	106	196	Off Idle	41.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.32	15.14	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:7	35.45	3096	2.66	13.41	106	196	Off Idle	41.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.27	15.21	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:8	35.45	3096	2.66	13.4	106	196	Off Idle	41.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.23	15.26	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:8	35.45	3090	2.67	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.25	15.32	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:8	35.45	3090	2.68	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.22	15.3	1.04	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:8	34.08	3083	2.69	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.19	15.26	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:8	34.08	3104	2.69	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.18	15.24	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:8	34.08	3111	2.7	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.14	15.17	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:9	34.08	3109	2.7	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.07	15.08	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:9	34.08	3109	2.7	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.08	15.02	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:43:9	34.08	3113	2.71	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.04	14.96	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:9	34.08	3115	2.71	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.02	14.85	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:9	34.08	3115	2.71	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.95	14.77	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:9	34.08	3103	2.72	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.93	14.72	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:43:9	34.08	3105	2.72	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.89	14.7	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:0	34.08	3106	2.72	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.9	14.68	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:0	34.08	3106	2.72	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.87	14.67	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:0	34.08	3110	2.73	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.93	14.66	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:0	34.08	3111	2.73	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.9	14.65	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:0	34.08	3112	2.73	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.91	14.66	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:0	34.08	3122	2.73	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.86	14.68	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:1	34.08	3128	2.73	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.85	14.68	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:1	34.08	3128	2.73	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.88	14.7	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:1	34.08	3128	2.73	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.81	14.72	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:1	34.08	3128	2.74	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.9	14.73	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:1	34.08	3128	2.74	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.84	14.75	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:1	34.08	3122	2.74	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.92	14.78	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:1	34.08	3117	2.74	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.83	14.78	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:2	34.08	3117	2.74	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.87	14.78	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:2	34.08	3124	2.74	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.83	14.78	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:2	34.08	3126	2.74	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.87	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:2	34.08	3133	2.74	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.81	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:2	34.08	3134	2.74	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.87	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:2	34.08	3142	2.74	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.88	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:3	34.08	3141	2.74	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.9	14.8	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:3	34.08	3140	2.74	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.85	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:3	34.08	3138	2.74	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.84	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:3	34.08	3129	2.74	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.83	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:3	34.08	3126	2.74	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.8	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:3	34.08	3128	2.75	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.82	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:4	34.08	3126	2.75	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.83	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:4	34.08	3124	2.75	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.8	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:4	34.08	3124	2.75	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.78	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:4	34.08	3134	2.75	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-3.73	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:4	34.08	3140	2.75	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.69	14.85	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:44:4	34.08	3148	2.75	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.64	14.85	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:44:4	34.08	3145	2.76	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.63	14.85	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:44:5	34.08	3146	2.76	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.62	14.87	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:44:5	34.08	3146	2.76	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.57	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:5	34.08	3147	2.76	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.55	14.9	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:5	34.08	3149	2.77	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.59	14.92	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:5	34.08	3152	2.77	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.54	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:5	34.08	3151	2.77	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-3.59	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:6	34.08	3152	2.77	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.59	15.03	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:6	34.08	3164	2.77	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.57	15.03	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:6	34.08	3152	2.77	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.64	15	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:6	34.08	3156	2.77	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.56	14.98	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:6	34.08	3133	2.78	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.54	14.93	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:6	34.08	3133	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.59	14.9	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:6	34.08	3158	2.78	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.5	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:7	34.08	3158	2.78	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.54	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:7	34.08	3155	2.78	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.49	14.75	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:7	34.08	3156	2.78	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.52	14.75	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:7	34.08	3153	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.54	14.76	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:7	34.08	3153	2.78	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.55	14.77	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:7	34.08	3144	2.78	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.64	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:8	34.08	3146	2.78	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.61	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:8	34.08	3156	2.78	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.65	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:8	34.08	3162	2.78	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.59	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:8	34.08	3162	2.78	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.59	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:8	34.08	3166	2.78	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.55	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:8	34.08	3178	2.78	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.55	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:9	34.08	3161	2.78	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-3.59	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:44:9	34.08	3161	2.78	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.64	14.86	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:44:9	34.08	3160	2.78	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-3.61	14.86	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:9	34.08	3133	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.68	14.86	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:9	34.08	3146	2.78	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.66	14.85	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:9	34.08	3167	2.78	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.7	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:44:9	34.08	3177	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.62	14.9	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:0	34.08	3206	2.78	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.7	14.93	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:0	34.08	3193	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-3.6	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:0	34.08	3173	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.59	15.01	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:0	34.08	3167	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.54	15.01	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:0	34.08	3166	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.56	15.04	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:0	34.08	3167	2.78	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-3.54	15.08	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:1	34.08	3170	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.56	15.13	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:1	34.08	3175	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.61	15.18	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:1	34.08	3176	2.78	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.57	15.16	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:45:1	34.08	3180	2.78	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.55	15.15	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:45:1	34.08	3182	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.47	15.12	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:45:1	34.08	3182	2.78	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.52	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:45:1	34.08	3181	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.5	15.03	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:45:2	34.08	3180	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.53	15.01	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:2	34.08	3176	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.52	14.98	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:45:2	34.08	3178	2.78	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-3.52	14.92	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:45:2	34.08	3181	2.79	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.52	14.85	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:45:2	34.08	3183	2.79	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.5	14.84	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:45:2	34.08	3182	2.79	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.46	14.82	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:45:3	34.08	3186	2.79	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.42	14.87	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:45:3	34.08	3187	2.79	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.32	14.87	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:45:3	34.08	3188	2.8	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.32	14.9	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:45:3	34.08	3189	2.8	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.29	14.93	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:3	34.08	3188	2.8	13.44	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.33	14.96	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:45:3	34.08	3188	2.8	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.32	15	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:4	34.08	3186	2.81	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.36	15.03	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:4	34.08	3187	2.81	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.4	15.09	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:4	34.08	3188	2.81	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.3	15.08	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:4	34.08	3192	2.81	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.27	15.08	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:4	34.08	3195	2.81	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.26	15.03	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:4	34.08	3195	2.81	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.23	15.01	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:4	34.08	3197	2.81	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.21	14.99	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:5	34.08	3202	2.81	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.24	14.97	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:5	34.08	3204	2.82	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.31	14.94	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:5	34.08	3197	2.82	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.25	14.9	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:5	34.08	3197	2.82	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.28	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:5	34.08	3193	2.82	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.31	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:5	34.08	3192	2.82	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.25	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:6	34.08	3192	2.82	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.32	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:6	34.08	3196	2.82	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.3	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:6	34.08	3198	2.82	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.3	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:6	34.08	3200	2.82	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.29	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:6	34.08	3207	2.82	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.28	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:45:6	34.08	3210	2.82	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.27	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:6	34.08	3218	2.81	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.33	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:7	34.08	3222	2.81	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.39	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:7	34.08	3223	2.81	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.41	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:7	34.08	3226	2.81	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.46	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:7	34.08	3206	2.81	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.43	14.87	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:7	34.08	3203	2.81	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.41	14.9	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:7	34.08	3204	2.81	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.43	14.99	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:8	34.08	3178	2.81	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-3.42	15.02	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:8	34.08	3208	2.81	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.42	15.05	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:8	34.08	3208	2.81	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.45	15.04	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:8	34.08	3217	2.81	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.41	15.04	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:8	34.08	3224	2.81	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.45	15.03	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:45:8	34.08	3222	2.81	13.39	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.44	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:9	34.08	3224	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.47	14.98	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:9	34.08	3224	2.8	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.43	14.94	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:9	34.08	3224	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.45	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:9	34.08	3222	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-3.46	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:9	34.08	3216	2.8	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-3.44	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:9	34.08	3208	2.8	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-3.46	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:45:9	34.08	3210	2.8	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-3.5	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:0	34.08	3211	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-3.47	14.93	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:46:0	34.08	3212	2.8	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-3.5	14.96	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:46:0	34.08	3220	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.52	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:46:0	34.08	3223	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.48	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:46:0	34.08	3223	2.8	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.51	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:46:0	34.08	3220	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.51	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:46:1	34.08	3214	2.8	13.43	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.47	15.05	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:46:1	34.08	3217	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.51	15.02	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:46:1	34.08	3216	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-3.51	14.99	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:46:1	34.08	3212	2.8	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-3.5	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:1	34.08	3215	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.51	14.93	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:1	34.08	3213	2.8	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.55	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:1	34.08	3228	2.8	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.53	14.8	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:2	34.08	3247	2.8	13.44	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3.44	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:2	34.08	3237	2.8	13.43	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.5	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:2	34.08	3238	2.8	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.41	14.84	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:2	34.08	3238	2.81	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.46	14.9	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:2	34.08	3233	2.81	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.35	14.94	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:46:2	35.45	3207	2.81	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-3.4	14.96	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:3	35.45	3221	2.81	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-3.31	14.99	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:3	35.45	3236	2.81	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-3.36	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:3	35.45	3239	2.81	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.36	15.13	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:46:3	35.45	3231	2.82	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.34	15.16	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:3	35.45	3230	2.82	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.34	15.15	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:3	35.45	3229	2.82	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.27	15.13	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:46:4	35.45	3230	2.82	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.21	15.08	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:4	35.45	3229	2.82	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.17	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:4	34.08	3229	2.83	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.19	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:4	34.08	3236	2.83	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.64	Lean	1	14.6	-3.15	14.97	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:4	34.08	3230	2.83	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	-3.17	14.94	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:46:4	34.08	3235	2.83	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-3.09	14.89	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:46:4	34.08	3235	2.83	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.1	14.81	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:46:5	34.08	3228	2.84	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.05	14.79	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:46:5	34.08	3228	2.84	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.04	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:46:5	34.08	3260	2.84	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-2.96	14.81	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:46:5	34.08	3270	2.84	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.03	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:16:46:5	34.08	3293	2.84	13.4	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.08	14.88	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:5	35.45	3262	2.85	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-3.04	14.91	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:6	35.45	3262	2.85	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-3.1	14.96	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:6	35.45	3248	2.85	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.1	15.03	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:6	35.45	3236	2.85	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.06	15.07	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:6	35.45	3227	2.85	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.98	15.07	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:6	35.45	3228	2.85	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.93	15.04	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:6	35.45	3231	2.86	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.95	14.98	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:6	35.45	3237	2.86	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.88	14.9	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:7	35.45	3240	2.86	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.97	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:7	35.45	3251	2.86	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.94	14.76	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:7	35.45	3259	2.86	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.95	14.7	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:7	34.08	3266	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.95	14.67	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:7	34.08	3265	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.95	14.68	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:7	34.08	3256	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3	14.72	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:8	34.08	3248	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3	14.76	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:8	34.08	3248	2.86	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.98	14.79	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:8	35.45	3240	2.86	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.98	14.84	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:8	35.45	3252	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.97	14.85	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:46:8	35.45	3254	2.86	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.97	14.87	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:8	35.45	3260	2.86	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:9	35.45	3259	2.86	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.01	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:9	35.45	3260	2.86	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.98	14.9	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:9	35.45	3258	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-2.98	14.9	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:9	35.45	3256	2.86	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.93	14.89	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:9	35.45	3246	2.86	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-2.95	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:46:9	34.08	3261	2.86	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-2.95	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:46:9	34.08	3267	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-2.95	14.88	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:0	34.08	3266	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.97	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:0	34.08	3278	2.86	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.03	14.91	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:0	35.45	3267	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.94	14.94	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:0	35.45	3267	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.98	14.94	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:0	35.45	3269	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.01	14.99	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:0	35.45	3271	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3	15.01	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:1	35.45	3273	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3	15.03	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:1	35.45	3273	2.86	13.44	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.02	15.06	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:1	35.45	3272	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-3.02	15.12	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:1	35.45	3257	2.86	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-2.98	15.13	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:1	35.45	3259	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.99	15.12	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:1	35.45	3250	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.02	15.08	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:47:1	35.45	3270	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.96	15.05	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:2	35.45	3276	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3	15.01	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:2	35.45	3278	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.02	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:2	35.45	3291	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.01	14.93	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:47:2	35.45	3274	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-2.98	14.88	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:47:2	35.45	3270	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-2.98	14.8	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:2	35.45	3271	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-3	14.79	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:3	35.45	3270	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3	14.79	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:3	35.45	3273	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3	14.79	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:3	35.45	3273	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.05	14.82	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:3	35.45	3275	2.86	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.06	14.85	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:3	35.45	3280	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.06	14.87	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:3	35.45	3283	2.86	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.08	14.92	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:4	35.45	3283	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-3.08	14.97	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:4	35.45	3284	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-3.03	14.99	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:4	35.45	3276	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-3.07	15.01	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:4	34.08	3263	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-3.04	15	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:4	34.08	3275	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.07	14.98	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:4	34.08	3268	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.03	14.95	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:4	34.08	3268	2.86	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.09	14.9	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:5	34.08	3271	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3	14.89	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:5	34.08	3282	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.02	14.85	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:5	34.08	3292	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.07	14.76	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:5	34.08	3300	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.1	14.74	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:5	34.08	3302	2.86	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.07	14.73	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:47:5	35.45	3302	2.86	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-3.1	14.78	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:47:6	35.45	3297	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-3.06	14.8	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:47:6	35.45	3297	2.86	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-3.03	14.82	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:47:6	35.45	3286	2.86	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.05	14.9	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:6	35.45	3265	2.85	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.11	14.97	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:6	34.08	3269	2.85	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.19	14.98	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:6	34.08	3270	2.85	13.44	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.12	14.98	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:6	34.08	3275	2.85	13.44	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.15	14.99	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:47:7	35.45	3299	2.85	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.22	14.99	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:47:7	35.45	3292	2.85	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.19	14.95	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:47:7	35.45	3304	2.85	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.21	14.91	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:47:7	35.45	3304	2.85	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.25	14.9	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:47:7	35.45	3305	2.84	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.28	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:47:7	35.45	3294	2.84	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.31	14.77	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:47:8	35.45	3282	2.84	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.43	14.75	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:47:8	35.45	3282	2.83	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.52	14.75	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:47:8	35.45	3268	2.82	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-3.62	14.77	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:47:8	35.45	3270	2.81	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-3.8	14.78	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:47:8	35.45	3276	2.8	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.87	14.79	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:47:8	35.45	3282	2.79	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-4.03	14.81	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:47:9	35.45	3294	2.78	13.44	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.19	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:47:9	35.45	3294	2.77	13.44	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.32	14.87	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:47:9	35.45	3300	2.76	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.4	14.9	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:47:9	35.45	3294	2.75	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.51	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:47:9	35.45	3293	2.74	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.62	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:47:9	35.45	3278	2.73	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.8	15.02	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:47:9	35.45	3265	2.71	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.95	15.05	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:48:0	35.45	3249	2.69	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.13	15.05	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:48:0	35.45	3261	2.67	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.36	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:48:0	35.45	3277	2.64	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.48	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:48:0	35.45	3274	2.62	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.71	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:48:0	35.45	3277	2.59	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.95	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:48:0	35.45	3269	2.54	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.27	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:48:1	35.45	3268	2.51	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.52	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:48:1	36.81	3279	2.47	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.82	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:48:1	36.81	3258	2.44	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.01	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:48:1	36.81	3262	2.39	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.43	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:48:1	36.81	3258	2.37	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:48:1	36.81	3252	2.31	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.08	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:48:1	36.81	3250	2.27	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.27	15.14	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:2	36.81	3243	2.22	13.42	106	196	Full Load	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.44	15.19	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:2	36.81	3232	2.17	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.7	15.23	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:2	36.81	3230	2.12	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.87	15.24	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:2	34.08	3169	2.08	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.01	15.23	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:48:2	28.63	3157	2.03	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.17	15.24	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:16:48:2	28.63	3138	1.99	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.31	15.24	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:3	23.18	3134	1.95	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.35	15.23	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:3	20.45	3166	1.92	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	15.27	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:3	20.45	3154	1.89	13.41	106	196	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.51	15.27	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:3	20.45	3157	1.86	13.41	106	196	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.56	15.28	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:3	20.45	3159	1.81	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.62	15.28	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:3	20.45	3179	1.79	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.65	15.29	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:4	20.45	3210	1.76	13.42	106	196	Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.7	15.3	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:4	20.45	3236	1.73	13.45	106	196	Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.75	15.32	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:4	20.45	3240	1.72	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.76	15.33	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:4	20.45	3268	1.71	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.74	15.35	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:4	20.45	3268	1.7	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.72	15.36	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:4	20.45	3251	1.69	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	15.38	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:4	20.45	3238	1.69	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.64	15.4	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:5	20.45	3225	1.69	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.62	15.42	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:5	20.45	3220	1.69	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.64	15.46	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:5	20.45	3171	1.69	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.66	15.49	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:5	20.45	3180	1.69	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.62	15.55	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:5	20.45	3173	1.69	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.66	15.6	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:5	20.45	3171	1.69	13.42	106	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	15.66	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:6	20.45	3170	1.69	13.42	106	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	15.72	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:6	20.45	3173	1.69	13.41	106	196	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	15.8	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:6	20.45	3180	1.69	13.42	106	196	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	15.89	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:6	20.45	3180	1.69	13.42	106	196	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	16.1	1.1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:6	20.45	3196	1.69	13.42	106	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	16.32	1.11	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:6	20.45	3203	1.7	13.42	106	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	16.67	1.14	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:6	20.45	3201	1.7	13.42	106	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	17.31	1.18	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:7	20.45	3200	1.7	13.42	106	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	17.75	1.21	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:7	20.45	3193	1.7	13.42	106	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	18.17	1.24	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:7	20.45	3182	1.7	13.43	106	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	18.59	1.27	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:7	20.45	3182	1.71	13.43	106	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	19.19	1.31	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:7	20.45	3166	1.71	13.42	106	196	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	19.56	1.33	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:7	20.45	3156	1.71	13.43	106	196	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	19.87	1.35	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:8	20.45	3148	1.71	13.43	106	196	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.11	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:8	20.45	3146	1.71	13.43	106	196	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:8	20.45	3140	1.71	13.42	106	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:8	20.45	3136	1.71	13.43	106	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:8	20.45	3136	1.71	13.43	106	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:8	20.45	3142	1.71	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:9	20.45	3147	1.71	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:9	20.45	3148	1.71	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:9	20.45	3150	1.71	13.44	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:9	20.45	3152	1.71	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:9	20.45	3148	1.71	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:9	20.45	3145	1.71	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:48:9	20.45	3145	1.71	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:49:0	20.45	3138	1.71	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:0	20.45	3132	1.71	13.41	106	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:0	20.45	3122	1.71	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:0	20.45	3118	1.71	13.41	106	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:0	20.45	3114	1.71	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:0	20.45	3105	1.71	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:1	20.45	3105	1.71	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:1	19.09	3075	1.71	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:1	19.09	3096	1.71	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:1	19.09	3097	1.71	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:1	19.09	3096	1.71	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:1	19.09	3096	1.71	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:1	19.09	3097	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:2	19.09	3098	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:2	19.09	3098	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:2	19.09	3099	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:2	19.09	3098	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:2	19.09	3098	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:2	19.09	3092	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:3	19.09	3092	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:3	19.09	3088	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:3	19.09	3080	1.7	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:3	19.09	3080	1.7	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:3	19.09	3075	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:3	19.09	3056	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:4	19.09	3068	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:4	19.09	3066	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:4	19.09	3063	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:4	19.09	3062	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:4	19.09	3059	1.7	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:4	19.09	3060	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:4	19.09	3060	1.7	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:5	19.09	3054	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:5	19.09	3055	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:5	19.09	3047	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:5	19.09	3047	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:5	19.09	3042	1.7	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:5	19.09	3014	1.7	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:6	19.09	3014	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:6	19.09	3027	1.7	13.4	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:6	19.09	3032	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:6	19.09	3022	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:6	19.09	3018	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:6	19.09	3006	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:6	19.09	3018	1.7	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:7	19.09	3021	1.7	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:7	19.09	3020	1.7	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:7	19.09	3019	1.7	13.42	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:7	19.09	3019	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:7	19.09	3019	1.7	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:7	19.09	3014	1.7	13.44	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:8	19.09	3012	1.7	13.44	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:8	19.09	3012	1.7	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:8	19.09	3004	1.7	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:8	19.09	2999	1.7	13.42	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:8	19.09	2994	1.7	13.41	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:8	19.09	2992	1.7	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:9	19.09	2987	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:49:9	19.09	2985	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:9	19.09	2984	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:9	19.09	2978	1.7	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:9	19.09	2978	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:9	19.09	2978	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:49:9	19.09	2978	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:0	19.09	2976	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:0	19.09	2973	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:0	19.09	2972	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:0	19.09	2967	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:0	19.09	2962	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:0	19.09	2950	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:1	19.09	2958	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:1	19.09	2952	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:1	19.09	2949	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:1	19.09	2948	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:1	19.09	2946	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:1	19.09	2943	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:1	19.09	2943	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:2	19.09	2944	1.7	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:2	19.09	2943	1.7	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:2	19.09	2942	1.7	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:2	19.09	2941	1.7	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:2	19.09	2939	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:2	19.09	2939	1.71	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:3	19.09	2935	1.71	13.4	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:3	19.09	2928	1.71	13.41	106	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:3	19.09	2923	1.71	13.41	106	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:3	19.09	2920	1.71	13.4	106	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:3	19.09	2912	1.7	13.41	106	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:3	19.09	2895	1.7	13.42	106	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:4	19.09	2904	1.7	13.42	106	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:4	19.09	2904	1.7	13.44	106	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:4	19.09	2926	1.7	13.43	106	196	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:4	19.09	2916	1.7	13.42	106	196	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:4	19.09	2898	1.7	13.43	106	196	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:4	19.09	2912	1.7	13.42	106	196	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:4	19.09	2915	1.7	13.41	106	196	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:5	19.09	2916	1.7	13.42	106	196	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:5	19.09	2926	1.7	13.43	106	196	Idle	42	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:5	19.09	2909	1.7	13.42	106	196	Idle	42.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:5	19.09	2902	1.7	13.43	106	196	Idle	42.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:5	19.09	2902	1.7	13.44	106	196	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:5	19.09	2894	1.7	13.42	106	196	Idle	42.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:6	19.09	2884	1.7	13.41	106	196	Idle	42.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:6	19.09	2874	1.7	13.42	106	196	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:6	19.09	2874	1.7	13.43	106	196	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:6	19.09	2868	1.7	13.43	106	196	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:6	19.09	2862	1.69	13.43	106	196	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:6	19.09	2862	1.69	13.43	106	196	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:6	19.09	2862	1.69	13.42	106	196	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:7	19.09	2862	1.69	13.42	106	196	Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:7	19.09	2863	1.69	13.42	106	196	Idle	43.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:7	19.09	2864	1.69	13.41	106	196	Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:7	19.09	2862	1.69	13.41	106	196	Idle	43.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:7	19.09	2862	1.69	13.42	106	196	Idle	43.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:7	19.09	2859	1.69	13.42	106	196	Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:8	19.09	2856	1.69	13.41	106	196	Off Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:50:8	19.09	2856	1.69	13.42	106	196	Off Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:8	10.9	2873	1.69	13.42	106	196	Off Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:8	10.9	2873	1.69	13.42	106	196	Off Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:8	13.63	2869	1.69	13.42	106	196	Off Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:8	16.36	2864	1.69	13.42	106	196	Off Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:9	16.36	2860	1.69	13.41	106	196	Off Idle	45	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:50:9	19.09	2857	1.69	13.41	106	196	Off Idle	45.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:50:9	21.81	2861	1.69	13.42	106	196	Off Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:50:9	24.54	2862	1.69	13.42	106	197	Off Idle	46.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:50:9	27.27	2862	1.69	13.42	106	197	Off Idle	46.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:50:9	27.27	2862	1.7	13.43	106	197	Off Idle	47.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:50:9	29.99	2865	1.7	13.42	106	196	Off Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:0	32.72	2869	1.7	13.42	106	196	Off Idle	47.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:0	35.45	2872	1.7	13.42	106	196	Off Idle	47.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:0	35.45	2858	1.69	13.43	106	196	Off Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:0	36.81	2842	1.69	13.42	106	196	Off Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:0	36.81	2844	1.69	13.44	106	196	Off Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:51:0	36.81	2843	1.69	13.43	106	196	Off Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:51:1	36.81	2837	1.69	13.45	106	196	Off Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:1	36.81	2837	1.69	13.45	106	196	Off Idle	47.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.93	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:1	36.81	2826	1.68	13.44	106	196	Off Idle	47.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.92	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:1	36.81	2823	1.68	13.42	106	196	Off Idle	47.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:1	36.81	2810	1.68	13.41	106	196	Off Idle	47.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.93	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:1	36.81	2817	1.68	13.4	106	196	Off Idle	47.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.92	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:1	36.81	2814	1.68	13.41	106	196	Off Idle	47.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.9	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:2	36.81	2809	1.68	13.39	106	196	Off Idle	47.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.9	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:2	36.81	2809	1.68	13.41	106	196	Off Idle	47.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.88	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:2	36.81	2806	1.68	13.41	106	196	Off Idle	47.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.9	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:2	36.81	2806	1.68	13.41	106	196	Off Idle	47.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.89	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:2	36.81	2809	1.68	13.42	106	196	Off Idle	47.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.89	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:2	36.81	2809	1.68	13.42	106	196	Off Idle	47.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:3	36.81	2805	1.68	13.41	106	196	Off Idle	47.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.88	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:3	36.81	2799	1.68	13.42	106	196	Off Idle	47.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:3	36.81	2796	1.68	13.43	106	196	Off Idle	48.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:51:3	36.81	2796	1.69	13.43	106	196	Off Idle	48.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.84	20.18	1.37	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:3	36.81	2796	1.69	13.42	106	196	Off Idle	48.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.82	20.09	1.37	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:3	36.81	2798	1.69	13.41	106	196	Off Idle	48.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.81	19.89	1.35	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:4	36.81	2797	1.69	13.41	106	196	Off Idle	48.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.82	19.71	1.34	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:4	36.81	2796	1.69	13.4	106	196	Off Idle	48.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.82	19.5	1.33	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:4	36.81	2800	1.7	13.41	106	196	Off Idle	48.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.78	19.38	1.32	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:4	36.81	2800	1.7	13.41	106	196	Off Idle	49	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.78	19.12	1.3	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:4	36.81	2798	1.7	13.42	106	196	Off Idle	49.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.78	18.69	1.27	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:4	36.81	2796	1.7	13.41	106	196	Off Idle	49.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.75	18.38	1.25	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:4	36.81	2797	1.71	13.41	106	196	Off Idle	49.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.73	18.22	1.24	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:5	36.81	2794	1.71	13.42	106	196	Off Idle	49.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.69	17.92	1.22	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:51:5	36.81	2784	1.72	13.42	106	196	Off Idle	49.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.64	17.65	1.2	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:51:5	36.81	2781	1.72	13.42	106	196	Off Idle	49.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.64	17.41	1.19	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:51:5	36.81	2782	1.72	13.41	106	196	Off Idle	49.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.58	17.2	1.17	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:51:5	36.81	2784	1.73	13.41	106	196	Off Idle	49.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.56	17.1	1.16	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:51:5	36.81	2784	1.74	13.42	106	196	Off Idle	49.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.53	16.9	1.15	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:51:6	36.81	2786	1.74	13.42	106	197	Off Idle	50	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.52	16.75	1.14	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:51:6	36.81	2788	1.75	13.41	106	197	Off Idle	49.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.48	16.61	1.13	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:51:6	36.81	2787	1.75	13.42	106	197	Off Idle	49.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	16.48	1.12	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:6	36.81	2787	1.76	13.42	106	197	Off Idle	49.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.45	16.37	1.12	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:51:6	36.81	2790	1.77	13.41	106	197	Off Idle	49.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.39	16.28	1.11	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:51:6	36.81	2792	1.77	13.41	106	197	Off Idle	49.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.35	16.15	1.1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:6	36.81	2793	1.78	13.41	106	196	Off Idle	49.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.33	16.04	1.09	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:7	36.81	2786	1.79	13.4	106	196	Off Idle	49.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.29	15.96	1.09	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:51:7	36.81	2782	1.8	13.41	106	197	Off Idle	49.8	0	2	132	944 Turbo	0.14	Rich	1	14.6	-9.26	15.88	1.08	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:7	36.81	2782	1.8	13.4	106	197	Off Idle	50	0	2	132	944 Turbo	0.19	Rich	1	14.6	-9.24	15.84	1.08	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:7	36.81	2782	1.81	13.41	106	197	Off Idle	49.9	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.19	15.8	1.08	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:7	36.81	2782	1.81	13.43	106	197	Off Idle	49.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.18	15.77	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:7	36.81	2775	1.82	13.43	106	196	Off Idle	49.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.18	15.72	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:8	36.81	2752	1.82	13.42	106	196	Off Idle	49.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.16	15.69	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:8	35.45	2762	1.82	13.41	106	196	Off Idle	49.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.15	15.65	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:8	35.45	2767	1.83	13.41	106	196	Off Idle	49.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.12	15.62	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:8	35.45	2759	1.83	13.41	106	196	Off Idle	50	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.13	15.59	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:8	35.45	2735	1.84	13.41	106	196	Off Idle	50.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.07	15.55	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:8	35.45	2743	1.84	13.4	106	196	Off Idle	50.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.02	15.51	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:9	36.81	2763	1.84	13.42	106	196	Off Idle	50.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.05	15.46	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:9	36.81	2754	1.84	13.42	106	197	Off Idle	50.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.07	15.4	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:9	36.81	2754	1.85	13.41	106	197	Off Idle	51	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.05	15.37	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:9	36.81	2750	1.85	13.41	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.08	15.29	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:9	36.81	2757	1.85	13.42	106	196	Off Idle	51.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.09	15.26	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:9	35.45	2736	1.84	13.42	106	196	Off Idle	51.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.1	15.21	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:51:9	35.45	2755	1.84	13.42	106	196	Off Idle	51.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.07	15.16	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:0	35.45	2755	1.84	13.42	106	196	Off Idle	52.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.1	15.14	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:0	35.45	2756	1.84	13.42	106	196	Off Idle	52.2	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.11	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:0	35.45	2754	1.84	13.43	106	196	Off Idle	52.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.13	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:0	35.45	2752	1.84	13.41	106	196	Off Idle	52.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.12	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:0	36.81	2770	1.84	13.43	106	196	Off Idle	52.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.14	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:0	36.81	2744	1.84	13.43	106	197	Off Idle	52.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.16	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:1	36.81	2744	1.84	13.45	106	197	Off Idle	52.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.18	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:1	36.81	2744	1.84	13.42	106	197	Off Idle	52.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.18	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:1	36.81	2744	1.83	13.43	106	196	Off Idle	52.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.18	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:1	36.81	2739	1.83	13.42	106	196	Off Idle	52.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.13	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:1	36.81	2738	1.83	13.41	106	196	Off Idle	52.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.13	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:52:1	36.81	2733	1.83	13.41	106	197	Off Idle	52.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.14	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:52:1	36.81	2725	1.83	13.42	106	197	Off Idle	52.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.15	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:52:2	36.81	2726	1.83	13.41	106	196	Off Idle	52.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.18	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:52:2	36.81	2723	1.83	13.4	106	196	Off Idle	52.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.14	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:52:2	35.45	2724	1.83	13.4	106	196	Off Idle	53	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.16	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:52:2	35.45	2701	1.83	13.39	106	197	Off Idle	53.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.18	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:52:2	35.45	2712	1.83	13.41	106	197	Off Idle	53.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.16	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:2	35.45	2724	1.83	13.41	106	196	Off Idle	53.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.17	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:3	35.45	2724	1.82	13.41	106	196	Off Idle	53.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.15	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:3	35.45	2724	1.82	13.41	106	196	Off Idle	53.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.15	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:3	35.45	2726	1.82	13.42	106	196	Off Idle	53.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.14	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:3	35.45	2718	1.82	13.41	106	196	Off Idle	53.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.17	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:3	35.45	2747	1.82	13.41	106	196	Off Idle	53.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.17	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:3	35.45	2736	1.82	13.4	106	196	Off Idle	53.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.19	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:4	35.45	2724	1.82	13.4	106	196	Off Idle	53.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.18	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:4	35.45	2726	1.82	13.41	106	196	Off Idle	53.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.16	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:4	35.45	2726	1.82	13.41	106	196	Off Idle	53.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.13	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:4	35.45	2722	1.82	13.42	106	196	Off Idle	53.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.11	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:4	35.45	2723	1.82	13.42	106	196	Off Idle	53	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.13	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:4	35.45	2729	1.82	13.43	106	196	Off Idle	52.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.07	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:4	35.45	2732	1.82	13.42	106	196	Off Idle	52.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.05	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:5	35.45	2733	1.83	13.41	106	197	Off Idle	52.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.03	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:5	35.45	2733	1.83	13.41	106	197	Off Idle	52.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.99	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:5	35.45	2733	1.83	13.41	106	197	Off Idle	52.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.99	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:5	35.45	2727	1.83	13.41	106	197	Off Idle	52.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.94	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:5	35.45	2718	1.84	13.41	106	197	Off Idle	52.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.92	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:5	35.45	2716	1.84	13.42	106	197	Off Idle	52.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.94	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:6	35.45	2710	1.85	13.42	106	197	Off Idle	53	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.91	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:6	35.45	2703	1.85	13.41	106	197	Off Idle	53.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.88	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:52:6	35.45	2685	1.85	13.41	106	197	Off Idle	53.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.87	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:6	35.45	2693	1.85	13.41	106	197	Off Idle	53.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.85	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:6	35.45	2692	1.86	13.41	106	197	Off Idle	53.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.81	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:6	35.45	2698	1.86	13.41	106	197	Off Idle	53.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.8	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:6	35.45	2700	1.86	13.41	106	197	Off Idle	54.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.8	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:7	35.45	2703	1.87	13.4	106	197	Off Idle	54.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.78	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:7	35.45	2706	1.87	13.39	106	197	Off Idle	54.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.79	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:7	35.45	2711	1.87	13.4	106	197	Off Idle	54.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.76	15.05	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:7	35.45	2709	1.88	13.41	106	197	Off Idle	54.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.73	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:7	35.45	2714	1.88	13.41	106	197	Off Idle	54.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.69	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:7	35.45	2711	1.88	13.42	106	197	Off Idle	54.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.65	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:8	35.45	2707	1.88	13.42	106	197	Off Idle	54.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.64	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:8	35.45	2702	1.89	13.42	106	197	Off Idle	54.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.64	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:52:8	35.45	2701	1.89	13.42	106	196	Off Idle	54.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.6	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:8	35.45	2700	1.89	13.43	106	196	Off Idle	54.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.61	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:8	35.45	2696	1.9	13.42	106	196	Off Idle	54.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.58	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:8	35.45	2690	1.9	13.42	106	196	Off Idle	54.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.54	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:9	35.45	2690	1.9	13.41	106	197	Off Idle	54.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.54	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:9	35.45	2686	1.91	13.41	106	197	Off Idle	54.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.52	14.9	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:9	35.45	2690	1.91	13.41	106	197	Off Idle	54.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.51	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:9	35.45	2690	1.91	13.41	106	196	Off Idle	54.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.46	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:9	35.45	2694	1.92	13.42	106	196	Off Idle	54.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.43	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:9	35.45	2694	1.92	13.41	106	196	Off Idle	54.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.41	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:52:9	35.45	2695	1.92	13.42	106	196	Off Idle	54.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.4	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:0	35.45	2690	1.93	13.42	106	196	Off Idle	54.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.37	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:0	35.45	2690	1.93	13.41	106	196	Off Idle	54.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.35	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:0	35.45	2689	1.93	13.41	106	197	Off Idle	54.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.35	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:0	35.45	2689	1.93	13.41	106	197	Off Idle	54.9	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.34	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:0	35.45	2689	1.94	13.41	106	197	Off Idle	54.9	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.37	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:0	35.45	2686	1.94	13.42	106	197	Off Idle	54.9	0	2	132	944 Turbo	0.71	Lean	1	14.6	-8.34	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:1	35.45	2685	1.94	13.43	106	197	Off Idle	54.9	0	2	132	944 Turbo	0.73	Lean	1	14.6	-8.33	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:1	35.45	2685	1.94	13.42	106	197	Off Idle	55.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.3	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:1	35.45	2683	1.95	13.42	106	197	Off Idle	55.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.27	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:1	35.45	2684	1.95	13.42	106	197	Off Idle	55.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.24	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:1	35.45	2686	1.95	13.42	106	197	Off Idle	55.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.22	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:1	35.45	2698	1.95	13.43	106	197	Off Idle	55.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.16	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:1	35.45	2687	1.96	13.42	106	197	Off Idle	55.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.16	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:2	35.45	2686	1.96	13.42	106	197	Off Idle	55.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.13	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:2	35.45	2674	1.97	13.41	106	197	Off Idle	55.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.1	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:53:2	35.45	2687	1.97	13.42	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.06	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:2	35.45	2683	1.98	13.42	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.06	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:2	35.45	2683	1.98	13.42	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.04	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:2	35.45	2683	1.99	13.43	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.02	14.77	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:3	35.45	2679	1.99	13.43	106	197	Off Idle	56	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.98	14.76	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:3	35.45	2681	2	13.42	106	197	Off Idle	56	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.92	14.78	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:3	35.45	2681	2	13.42	106	196	Off Idle	56	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.93	14.78	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:3	35.45	2682	2	13.42	106	196	Off Idle	56	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.87	14.79	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:3	35.45	2680	2.01	13.42	106	196	Off Idle	56	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	14.79	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:3	35.45	2681	2.02	13.4	106	196	Off Idle	56	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	14.78	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:4	35.45	2682	2.02	13.41	106	196	Off Idle	55.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	14.79	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:4	35.45	2683	2.03	13.4	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:4	35.45	2686	2.03	13.41	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:4	35.45	2686	2.04	13.39	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:4	35.45	2686	2.04	13.41	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:4	35.45	2682	2.05	13.41	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.67	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:4	35.45	2674	2.05	13.41	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.62	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:5	35.45	2672	2.06	13.42	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.62	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:5	35.45	2670	2.06	13.41	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.56	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:53:5	35.45	2671	2.06	13.43	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.53	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:53:5	35.45	2670	2.06	13.43	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.52	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:53:5	35.45	2671	2.07	13.42	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.53	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:53:5	35.45	2671	2.07	13.43	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.5	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:53:6	35.45	2672	2.07	13.43	106	196	Off Idle	55.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.53	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:6	35.45	2672	2.07	13.42	106	196	Off Idle	55.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.53	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:6	35.45	2670	2.07	13.43	106	196	Off Idle	56	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.54	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:53:6	34.08	2661	2.07	13.43	106	197	Off Idle	56.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:6	34.08	2669	2.07	13.43	106	197	Off Idle	56.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.59	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:6	34.08	2668	2.07	13.43	106	197	Off Idle	56.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.6	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:6	34.08	2668	2.07	13.44	106	197	Off Idle	56.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.6	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:7	34.08	2666	2.07	13.44	106	197	Off Idle	56.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.58	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:7	34.08	2664	2.07	13.42	106	197	Off Idle	56.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.54	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:7	34.08	2664	2.07	13.41	106	196	Off Idle	56.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.55	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:7	34.08	2678	2.07	13.4	106	196	Off Idle	56.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.52	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:7	34.08	2683	2.07	13.4	106	196	Off Idle	56.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.52	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:7	34.08	2671	2.07	13.42	106	197	Off Idle	56.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.52	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:8	34.08	2666	2.07	13.41	106	197	Off Idle	56.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.52	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:8	34.08	2665	2.07	13.43	106	196	Off Idle	56.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.5	15.04	1.02	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:8	34.08	2654	2.07	13.42	106	196	Off Idle	56.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.54	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:8	34.08	2663	2.07	13.42	106	196	Off Idle	56.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.53	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:8	34.08	2665	2.07	13.42	106	196	Off Idle	56.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.51	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:8	34.08	2664	2.07	13.43	106	197	Off Idle	56.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.51	14.93	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:9	34.08	2667	2.07	13.42	106	197	Off Idle	56.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.48	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:53:9	35.45	2670	2.07	13.41	106	197	Off Idle	56.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.49	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:9	35.45	2673	2.07	13.43	106	197	Off Idle	56.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.48	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:9	35.45	2673	2.07	13.42	106	197	Off Idle	56.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.49	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:53:9	35.45	2676	2.07	13.42	106	197	Off Idle	56.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.5	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:9	35.45	2676	2.07	13.41	106	197	Off Idle	56.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.48	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:53:9	35.45	2674	2.07	13.41	106	197	Off Idle	56.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.51	14.81	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:0	35.45	2670	2.07	13.43	106	197	Off Idle	56.7	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.54	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:54:0	35.45	2668	2.07	13.42	106	197	Off Idle	56.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.55	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:54:0	35.45	2665	2.07	13.42	106	197	Off Idle	56.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.57	14.81	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:0	35.45	2663	2.07	13.43	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.58	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:54:0	35.45	2658	2.07	13.42	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:54:0	35.45	2656	2.07	13.43	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.59	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:54:1	35.45	2638	2.07	13.42	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.55	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:1	35.45	2638	2.07	13.43	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.52	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:1	35.45	2662	2.07	13.44	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.49	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:1	35.45	2660	2.07	13.43	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.48	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:1	35.45	2641	2.07	13.43	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.45	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:1	34.08	2641	2.08	13.41	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.37	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:1	34.08	2672	2.09	13.42	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.28	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:2	34.08	2660	2.1	13.4	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.19	15.09	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:54:2	34.08	2662	2.1	13.4	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.05	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:54:2	34.08	2663	2.12	13.4	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.89	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:54:2	34.08	2663	2.13	13.41	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.79	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:54:2	34.08	2671	2.15	13.42	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.68	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:54:2	34.08	2675	2.16	13.42	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.57	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:54:3	34.08	2678	2.18	13.43	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.44	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:3	34.08	2683	2.2	13.42	106	197	Off Idle	56.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.28	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:3	34.08	2682	2.21	13.43	106	197	Off Idle	56.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.21	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:54:3	34.08	2680	2.23	13.42	106	197	Off Idle	56.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.04	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:54:3	34.08	2680	2.23	13.42	106	197	Off Idle	56.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.97	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:54:3	34.08	2680	2.26	13.43	106	197	Off Idle	56.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.81	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:54:4	34.08	2670	2.27	13.43	106	197	Off Idle	56	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.75	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:54:4	34.08	2665	2.3	13.41	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.63	14.97	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:54:4	34.08	2665	2.31	13.43	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.59	15.03	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:54:4	34.08	2661	2.33	13.41	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.51	15.08	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:4	34.08	2658	2.34	13.41	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.42	15.12	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:16:54:4	34.08	2658	2.34	13.41	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.35	15.14	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:4	34.08	2658	2.35	13.4	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.3	15.2	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:5	34.08	2665	2.36	13.4	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.25	15.28	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:5	34.08	2668	2.37	13.41	106	197	Off Idle	56	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.17	15.26	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:5	34.08	2672	2.38	13.41	106	197	Off Idle	56.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.11	15.2	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:5	34.08	2675	2.38	13.41	106	197	Off Idle	56.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.08	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:5	34.08	2676	2.4	13.4	106	197	Off Idle	56.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.01	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:5	34.08	2682	2.4	13.39	106	197	Off Idle	56.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.97	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:6	34.08	2683	2.41	13.39	106	197	Off Idle	56.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.89	14.9	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:6	34.08	2686	2.41	13.41	106	197	Off Idle	56.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.87	14.88	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:6	34.08	2686	2.42	13.42	106	197	Off Idle	56.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.87	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:6	34.08	2678	2.42	13.42	106	197	Off Idle	56.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.79	14.72	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:6	34.08	2676	2.43	13.41	106	197	Off Idle	56.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.81	14.72	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:6	34.08	2667	2.43	13.41	106	197	Off Idle	56.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.78	14.71	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:6	34.08	2677	2.44	13.42	106	197	Off Idle	56.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.77	14.74	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:7	34.08	2681	2.44	13.41	106	197	Off Idle	56.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.78	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:7	34.08	2683	2.45	13.42	106	197	Off Idle	56.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.76	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:7	34.08	2688	2.45	13.43	106	197	Off Idle	56.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.75	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:7	34.08	2688	2.45	13.43	106	197	Off Idle	56.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.76	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:7	34.08	2691	2.46	13.43	106	197	Off Idle	56.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.71	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:7	34.08	2687	2.46	13.43	106	197	Off Idle	56	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.73	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:8	34.08	2684	2.46	13.42	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.77	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:8	34.08	2682	2.46	13.41	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.77	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:8	34.08	2680	2.46	13.41	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.77	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:8	34.08	2680	2.46	13.4	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.72	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:8	34.08	2681	2.47	13.41	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.66	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:8	34.08	2683	2.47	13.42	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.68	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:9	34.08	2683	2.47	13.41	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.68	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:9	34.08	2686	2.47	13.41	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-4.63	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:9	34.08	2688	2.47	13.39	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-4.63	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:54:9	34.08	2688	2.47	13.41	106	197	Off Idle	55.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.57	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:54:9	34.08	2687	2.48	13.41	106	197	Off Idle	55.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.51	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:9	34.08	2691	2.48	13.39	106	197	Off Idle	55.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.46	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:54:9	34.08	2692	2.49	13.4	106	197	Off Idle	55.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.35	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:16:55:0	34.08	2695	2.5	13.4	106	197	Off Idle	55.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.24	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:0	34.08	2691	2.51	13.4	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.17	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:0	32.72	2701	2.52	13.4	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.06	14.85	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:0	32.72	2701	2.53	13.41	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.98	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:0	32.72	2702	2.54	13.42	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.94	14.87	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:0	32.72	2702	2.55	13.41	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.86	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:1	32.72	2729	2.55	13.42	106	197	Off Idle	55.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-3.8	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:1	34.08	2706	2.56	13.43	106	197	Off Idle	55.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.78	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:1	34.08	2708	2.57	13.42	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-3.76	14.94	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:1	34.08	2712	2.58	13.42	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-3.75	15.01	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:1	34.08	2710	2.59	13.41	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-3.73	15.04	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:1	32.72	2705	2.6	13.41	106	197	Off Idle	55.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-3.68	15.05	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:1	32.72	2705	2.61	13.4	106	197	Off Idle	54.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.66	15.05	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:2	32.72	2704	2.61	13.41	106	197	Off Idle	54.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.57	15.02	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:2	32.72	2701	2.62	13.39	106	197	Off Idle	54.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.56	14.96	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:2	32.72	2686	2.62	13.4	106	197	Off Idle	54.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.52	14.9	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:2	32.72	2696	2.62	13.4	106	197	Off Idle	54.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.5	14.86	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:2	32.72	2696	2.62	13.42	106	197	Off Idle	54.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.43	14.75	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:55:2	32.72	2711	2.63	13.42	106	197	Off Idle	54.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.42	14.65	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:3	32.72	2720	2.63	13.41	106	197	Off Idle	54.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.39	14.6	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:3	32.72	2725	2.63	13.42	106	197	Off Idle	54.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.41	14.51	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:3	32.72	2725	2.63	13.41	106	197	Off Idle	54.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.34	14.47	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:55:3	32.72	2722	2.64	13.4	106	197	Off Idle	54	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.28	14.45	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:3	32.72	2717	2.64	13.39	106	197	Off Idle	53.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.25	14.45	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:3	32.72	2717	2.64	13.4	106	197	Off Idle	53.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.23	14.46	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:4	32.72	2709	2.65	13.41	106	197	Off Idle	53.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.13	14.48	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:4	34.08	2717	2.65	13.4	106	197	Off Idle	53.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.17	14.5	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:4	34.08	2726	2.65	13.4	106	197	Off Idle	54	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.1	14.52	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:4	34.08	2727	2.65	13.4	106	197	Off Idle	54	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.05	14.54	0.99	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:4	34.08	2720	2.66	13.41	106	197	Off Idle	54	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.05	14.57	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:4	32.72	2735	2.66	13.42	106	197	Off Idle	53.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.04	14.59	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:4	32.72	2734	2.66	13.42	106	197	Off Idle	53.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3	14.6	0.99	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:5	32.72	2732	2.67	13.42	106	197	Off Idle	53.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.98	14.65	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:5	32.72	2728	2.67	13.41	106	197	Off Idle	53.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.94	14.66	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:5	32.72	2728	2.67	13.41	106	197	Off Idle	53.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.97	14.67	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:5	34.08	2737	2.68	13.42	106	197	Off Idle	53.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.95	14.68	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:5	34.08	2742	2.68	13.41	106	196	Off Idle	53.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.93	14.69	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:5	34.08	2745	2.68	13.41	106	196	Off Idle	53.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.89	14.7	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:6	34.08	2748	2.69	13.4	106	196	Off Idle	53.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.88	14.71	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:6	32.72	2741	2.69	13.4	106	196	Off Idle	53.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.88	14.71	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:6	32.72	2754	2.69	13.39	106	197	Off Idle	53.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.9	14.69	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:6	32.72	2754	2.69	13.39	106	197	Off Idle	53	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.84	14.69	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:6	32.72	2753	2.69	13.39	106	197	Off Idle	52.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.83	14.69	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:6	34.08	2780	2.69	13.4	106	197	Off Idle	52.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.87	14.66	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:6	34.08	2780	2.7	13.42	106	197	Off Idle	52.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.89	14.65	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:7	34.08	2765	2.7	13.42	106	197	Off Idle	52.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.89	14.66	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:7	34.08	2773	2.7	13.42	106	197	Off Idle	52.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.89	14.65	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:7	34.08	2772	2.7	13.43	106	197	Off Idle	52.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.83	14.66	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:7	34.08	2772	2.7	13.43	106	197	Off Idle	52.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.81	14.66	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:7	34.08	2767	2.7	13.43	106	197	Off Idle	52.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.82	14.67	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:55:7	34.08	2757	2.71	13.43	106	197	Off Idle	52	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.81	14.67	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:8	34.08	2751	2.71	13.44	106	197	Off Idle	51.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.79	14.67	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:8	34.08	2748	2.71	13.43	106	197	Off Idle	51.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.77	14.71	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:8	32.72	2728	2.71	13.43	106	197	Off Idle	51.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.77	14.73	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:8	32.72	2750	2.71	13.43	106	197	Off Idle	51.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.68	14.73	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:8	32.72	2754	2.72	13.41	106	197	Off Idle	51.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.58	14.74	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:8	32.72	2759	2.72	13.39	106	197	Off Idle	51.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.57	14.74	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:9	32.72	2760	2.72	13.4	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.51	14.76	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:9	32.72	2767	2.72	13.4	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.48	14.76	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:9	32.72	2769	2.73	13.4	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.49	14.78	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:9	32.72	2774	2.73	13.41	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.48	14.78	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:9	32.72	2774	2.73	13.41	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.41	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:9	32.72	2784	2.74	13.42	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.47	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:55:9	32.72	2777	2.74	13.39	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.41	14.81	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:0	32.72	2777	2.74	13.39	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.41	14.82	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:0	32.72	2777	2.75	13.39	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.37	14.85	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:0	32.72	2780	2.75	13.39	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.32	14.87	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:0	32.72	2780	2.75	13.38	106	197	Off Idle	51.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.27	14.89	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:0	32.72	2791	2.76	13.41	106	197	Off Idle	51.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.27	14.88	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:0	32.72	2793	2.76	13.41	106	197	Off Idle	51	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.17	14.89	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:1	32.72	2797	2.77	13.41	106	197	Off Idle	50.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-2.12	14.88	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:1	32.72	2796	2.78	13.4	106	197	Off Idle	50.7	0	2	132	944 Turbo	0.57	Lean	1	14.6	-2.01	14.88	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:1	32.72	2797	2.78	13.41	106	197	Off Idle	50.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-1.96	14.88	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:1	32.72	2798	2.78	13.41	106	197	Off Idle	50.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-1.88	14.87	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:1	32.72	2799	2.79	13.41	106	197	Off Idle	50.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-1.75	14.86	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:1	32.72	2799	2.8	13.4	106	197	Off Idle	50.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.72	14.82	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:1	32.72	2803	2.8	13.4	106	197	Off Idle	50.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-1.64	14.83	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:2	32.72	2803	2.81	13.4	106	197	Off Idle	49.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-1.62	14.85	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:56:2	32.72	2805	2.81	13.4	106	197	Off Idle	49.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-1.6	14.84	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:2	32.72	2809	2.82	13.39	106	197	Off Idle	49.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.54	14.89	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:56:2	32.72	2835	2.83	13.4	106	197	Off Idle	49.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-1.52	14.92	1.02	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:2	32.72	2824	2.83	13.41	106	197	Off Idle	49.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-1.46	15.01	1.02	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:2	32.72	2808	2.84	13.41	106	197	Off Idle	49.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.45	15.05	1.03	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:3	32.72	2803	2.84	13.42	106	197	Off Idle	49.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-1.47	15.06	1.03	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:3	32.72	2803	2.85	13.43	106	197	Off Idle	49	0	2	132	944 Turbo	0.62	Rich	1	14.6	-1.37	15.06	1.03	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:3	32.72	2781	2.86	13.41	106	197	Off Idle	49	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.35	14.98	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:56:3	32.72	2810	2.86	13.41	106	197	Off Idle	49	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.3	14.95	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:56:3	32.72	2825	2.86	13.41	106	197	Off Idle	49	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.3	14.9	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:56:3	32.72	2826	2.87	13.41	106	197	Off Idle	48.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.25	14.82	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:4	32.72	2832	2.87	13.41	106	197	Off Idle	48.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.3	14.77	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:4	32.72	2830	2.87	13.41	106	197	Off Idle	48.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.27	14.65	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:4	32.72	2829	2.87	13.41	106	197	Off Idle	48.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.28	14.6	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:4	32.72	2827	2.88	13.38	106	197	Off Idle	48.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.26	14.57	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:4	32.72	2825	2.88	13.4	106	197	Off Idle	48.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.21	14.57	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:4	32.72	2828	2.88	13.39	106	197	Off Idle	48.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.16	14.61	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:4	32.72	2828	2.88	13.4	106	197	Off Idle	48.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.15	14.6	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:5	32.72	2834	2.88	13.42	106	197	Off Idle	48.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.12	14.6	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:5	32.72	2838	2.88	13.4	106	197	Off Idle	48.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.16	14.62	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:5	32.72	2842	2.88	13.41	106	197	Off Idle	48.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.16	14.62	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:5	32.72	2844	2.89	13.41	106	197	Off Idle	48.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.15	14.63	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:5	32.72	2847	2.89	13.41	106	197	Off Idle	48	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.14	14.63	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:5	32.72	2844	2.89	13.39	106	197	Off Idle	47.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.22	14.64	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:6	32.72	2838	2.89	13.39	106	197	Off Idle	47.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.18	14.65	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:6	32.72	2848	2.89	13.39	106	197	Off Idle	47.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.24	14.65	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:6	32.72	2838	2.89	13.4	106	197	Off Idle	47.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.21	14.67	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:6	32.72	2852	2.89	13.41	106	197	Off Idle	47.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.23	14.68	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:6	32.72	2852	2.89	13.42	106	197	Off Idle	47.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.17	14.7	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:6	32.72	2862	2.89	13.42	106	197	Off Idle	47.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.18	14.72	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:6	32.72	2867	2.9	13.41	106	197	Off Idle	47.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.16	14.73	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:7	32.72	2870	2.9	13.41	106	197	Off Idle	47.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.17	14.74	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:7	32.72	2871	2.9	13.41	106	197	Off Idle	47.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-1.17	14.78	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:56:7	32.72	2872	2.9	13.4	106	197	Off Idle	46.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-1.15	14.78	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:56:7	32.72	2868	2.9	13.41	106	197	Off Idle	46.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-1.11	14.8	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:56:7	32.72	2869	2.9	13.41	106	197	Off Idle	46.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-1.13	14.81	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:56:7	32.72	2870	2.9	13.41	106	197	Off Idle	46.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.06	14.82	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:56:8	32.72	2873	2.9	13.42	106	196	Off Idle	46.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.08	14.82	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:56:8	32.72	2876	2.91	13.43	106	196	Off Idle	46.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-1.07	14.83	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:56:8	32.72	2882	2.91	13.41	106	196	Off Idle	46.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-1.07	14.85	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:56:8	32.72	2888	2.91	13.42	106	197	Off Idle	46.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-1.12	14.88	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:8	32.72	2887	2.91	13.41	106	197	Off Idle	45.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-1.12	14.91	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:8	32.72	2886	2.91	13.41	106	197	Off Idle	45.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-1.09	14.96	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:9	32.72	2886	2.91	13.41	106	197	Off Idle	45.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-1.12	15	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:9	32.72	2882	2.92	13.4	106	197	Off Idle	45.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.01	15.02	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:16:56:9	32.72	2879	2.92	13.39	106	197	Off Idle	45.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.97	15.03	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:9	32.72	2880	2.92	13.41	106	197	Off Idle	45.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.94	15.03	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:9	32.72	2884	2.92	13.41	106	197	Off Idle	45.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.95	15.01	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:9	32.72	2890	2.92	13.41	106	197	Off Idle	45.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.92	14.99	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:56:9	31.36	2891	2.92	13.39	106	197	Off Idle	45.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.88	14.96	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:0	31.36	2897	2.92	13.4	106	197	Off Idle	45.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.93	14.91	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:57:0	31.36	2895	2.93	13.41	106	197	Off Idle	45.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.92	14.86	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:57:0	32.72	2897	2.93	13.42	106	197	Off Idle	44.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-0.91	14.79	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:57:0	32.72	2920	2.93	13.44	106	197	Off Idle	44.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-0.91	14.79	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:16:57:0	32.72	2920	2.93	13.44	106	197	Off Idle	44.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-0.96	14.81	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:57:0	32.72	2920	2.93	13.43	106	197	Off Idle	44.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-0.91	14.82	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:57:1	32.72	2920	2.93	13.43	106	197	Off Idle	44.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-0.91	14.84	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:1	31.36	2904	2.93	13.43	106	197	Off Idle	44.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-0.91	14.87	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:1	31.36	2916	2.94	13.42	106	197	Off Idle	43.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-0.88	14.98	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:1	31.36	2910	2.94	13.43	106	197	Off Idle	43.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-0.91	15.02	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:57:1	31.36	2910	2.94	13.43	106	197	Off Idle	43.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-0.91	15.03	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:1	31.36	2909	2.94	13.43	106	197	Off Idle	43.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-0.91	15.06	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:1	31.36	2911	2.94	13.43	106	197	Off Idle	43.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.94	15.05	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:2	31.36	2914	2.94	13.42	106	197	Off Idle	43	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.9	15.03	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:2	31.36	2927	2.94	13.41	106	197	Off Idle	43	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.89	15.02	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:2	31.36	2936	2.94	13.4	106	197	Off Idle	42.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.82	14.99	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:2	31.36	2959	2.95	13.4	106	197	Off Idle	42.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.79	14.96	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:2	32.72	2959	2.95	13.4	106	197	Off Idle	42.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-0.81	14.91	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:2	32.72	2937	2.95	13.4	106	197	Off Idle	42.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-0.81	14.83	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:3	32.72	2937	2.95	13.4	106	197	Off Idle	42.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-0.82	14.8	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:57:3	32.72	2940	2.95	13.41	106	197	Off Idle	42.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.9	14.8	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:3	32.72	2940	2.95	13.42	106	197	Off Idle	42.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-0.91	14.81	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:3	32.72	2943	2.95	13.41	106	197	Off Idle	42.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-0.91	14.84	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:3	32.72	2944	2.96	13.41	106	197	Off Idle	42.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-0.95	14.85	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:16:57:3	32.72	2953	2.96	13.4	106	197	Off Idle	42.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-0.89	14.9	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:4	32.72	2957	2.96	13.41	106	197	Off Idle	41.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-0.91	14.89	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:4	32.72	2957	2.96	13.41	106	197	Off Idle	41.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-0.94	14.92	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:4	32.72	2967	2.96	13.42	106	197	Off Idle	41.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-0.89	14.96	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:4	32.72	2943	2.96	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-0.9	15	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:4	32.72	2943	2.96	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-0.94	15.03	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:4	32.72	2961	2.96	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-0.93	15.03	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:4	32.72	2961	2.96	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-0.91	15.02	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:5	32.72	2962	2.96	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.95	14.99	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:5	32.72	2991	2.96	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.94	14.97	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:5	32.72	2963	2.96	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.92	14.96	1.02	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:5	32.72	2963	2.96	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.98	14.94	1.02	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:5	32.72	2972	2.96	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-1.09	14.88	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:5	32.72	2972	2.96	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-1.11	14.86	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:6	32.72	2972	2.95	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-1.17	14.83	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:6	32.72	2977	2.95	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-1.21	14.82	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:6	32.72	2976	2.95	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-1.31	14.82	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:16:57:6	32.72	2966	2.95	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-1.33	14.88	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:6	32.72	2986	2.94	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-1.38	14.89	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:57:6	32.72	2989	2.94	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-1.46	14.92	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:16:57:6	32.72	3015	2.93	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-1.54	14.97	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:57:7	34.08	2993	2.92	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.65	15.03	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:57:7	34.08	2994	2.92	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-1.72	15.03	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:16:57:7	34.08	2990	2.91	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.8	15.03	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:16:57:7	34.08	2988	2.9	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1.85	15.02	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:57:7	34.08	2988	2.89	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.99	14.98	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:57:7	34.08	2996	2.89	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.07	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:57:8	34.08	2995	2.88	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.16	14.91	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:57:8	34.08	2995	2.88	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.2	14.9	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:57:8	34.08	2993	2.87	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.27	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:57:8	34.08	2994	2.86	13.39	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.3	14.78	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:57:8	34.08	2996	2.85	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-2.36	14.76	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:57:8	34.08	2998	2.84	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-2.38	14.75	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:16:57:9	34.08	3011	2.83	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-2.48	14.78	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:57:9	34.08	3015	2.82	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.19	Rich	1	14.6	-2.57	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:16:57:9	34.08	3017	2.82	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.13	Rich	1	14.6	-2.69	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:57:9	34.08	3018	2.81	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-2.79	14.97	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:16:57:9	34.08	3014	2.79	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.89	15.05	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:57:9	34.08	3007	2.78	13.42	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.09	15.1	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:16:57:9	34.08	3004	2.76	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.25	15.15	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:58:0	34.08	2999	2.75	13.41	106	196	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.32	15.21	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:16:58:0	34.08	3001	2.74	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.62	15.29	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:16:58:0	34.08	2995	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.77	15.29	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:0	34.08	2997	2.7	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.97	15.29	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:58:0	34.08	3005	2.68	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.11	15.26	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:58:0	34.08	3010	2.67	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.35	15.23	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:58:1	34.08	3012	2.66	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.57	15.21	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:58:1	34.08	3011	2.64	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.61	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:16:58:1	34.08	3011	2.63	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.7	15.16	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:58:1	34.08	3006	2.61	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.78	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:58:1	34.08	3006	2.59	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.87	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:58:1	34.08	3006	2.57	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.93	15.09	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:16:58:1	35.45	3032	2.56	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.98	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:58:2	35.45	3018	2.53	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.1	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:58:2	35.45	3020	2.52	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.19	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:16:58:2	35.45	3020	2.5	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.27	15.2	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:2	35.45	3024	2.49	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.4	15.25	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:2	35.45	3022	2.47	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.5	15.32	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:2	35.45	3024	2.45	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.7	15.4	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:16:58:3	35.45	3024	2.43	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.8	15.48	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:58:3	35.45	3021	2.41	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.05	15.57	1.06	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:16:58:3	35.45	3012	2.4	13.45	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.25	15.68	1.07	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:58:3	35.45	3007	2.38	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.41	15.75	1.07	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:16:58:3	35.45	3006	2.36	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.6	15.82	1.08	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:58:3	35.45	2998	2.34	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.79	15.89	1.08	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:58:4	35.45	2998	2.32	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.93	15.92	1.08	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:58:4	35.45	2998	2.3	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.05	15.96	1.09	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:16:58:4	35.45	2998	2.27	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.12	15.98	1.09	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:4	35.45	2999	2.26	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.24	16.02	1.09	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:4	35.45	2998	2.24	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.3	16.04	1.09	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:4	35.45	3002	2.21	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.39	16.04	1.09	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:4	35.45	3007	2.19	13.44	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.45	16.04	1.09	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:5	35.45	3009	2.18	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.48	16.04	1.09	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:5	35.45	3011	2.16	13.44	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.58	16.04	1.09	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:58:5	35.45	3023	2.14	13.44	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.66	16.05	1.09	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:58:5	35.45	3026	2.12	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.8	16.05	1.09	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:16:58:5	35.45	3026	2.12	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.85	16.06	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:5	36.81	3026	2.09	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.93	16.05	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:6	36.81	3020	2.07	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.08	16.06	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:16:58:6	36.81	3016	2.06	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.27	16.08	1.1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:58:6	36.81	3018	2.03	13.44	106	197	Full Load	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.41	16.11	1.1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:16:58:6	36.81	3019	2	13.43	106	197	Full Load	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.58	16.14	1.1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:58:6	36.81	3018	1.97	13.42	106	197	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.83	16.16	1.1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:6	36.81	3017	1.95	13.42	106	197	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.95	16.19	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:58:6	36.81	3008	1.93	13.42	106	197	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.09	16.2	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:58:7	36.81	2997	1.91	13.41	106	197	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.18	16.2	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:58:7	36.81	2990	1.88	13.41	106	197	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.27	16.2	1.1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:7	34.08	2990	1.86	13.41	106	197	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.35	16.21	1.1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:7	34.08	2938	1.83	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.4	16.19	1.1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:7	28.63	2931	1.81	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.48	16.16	1.1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:7	23.18	2930	1.79	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.54	16.1	1.1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:8	19.09	2922	1.77	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.52	16.08	1.1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:8	19.09	2936	1.75	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.58	16.03	1.09	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:8	19.09	2942	1.74	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.56	15.98	1.09	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:8	19.09	2928	1.72	13.43	106	197	Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.6	15.92	1.08	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:8	19.09	2950	1.71	13.43	106	197	Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	15.87	1.08	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:8	19.09	2950	1.71	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.72	15.8	1.08	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:9	19.09	2967	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.7	15.77	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:9	19.09	2990	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.74	15.71	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:9	19.09	3006	1.7	13.45	106	197	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.75	15.65	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:9	19.09	3022	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.72	15.61	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:9	19.09	3020	1.7	13.45	106	197	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.68	15.58	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:58:9	19.09	3014	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.66	15.57	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:58:9	19.09	3005	1.7	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.65	15.57	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:0	19.09	3002	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.63	15.58	1.06	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:0	19.09	2980	1.7	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.62	15.59	1.06	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:0	19.09	2976	1.7	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.62	15.63	1.06	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:0	19.09	2958	1.7	13.43	106	197	Idle	41.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.62	15.66	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:0	19.09	2940	1.7	13.43	106	197	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	15.68	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:0	19.09	2930	1.7	13.43	106	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.57	15.7	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:1	19.09	2930	1.7	13.42	106	197	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	15.71	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:1	19.09	2926	1.7	13.41	106	197	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	15.71	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:1	19.09	2934	1.7	13.4	106	197	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	15.75	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:1	19.09	2934	1.7	13.41	106	197	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	15.78	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:1	19.09	2954	1.7	13.41	106	197	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	16	1.09	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:1	19.09	3004	1.7	13.43	106	197	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	16.3	1.11	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:1	19.09	3004	1.7	13.43	106	197	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	16.7	1.14	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:2	19.09	3002	1.71	13.42	106	197	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	17.36	1.18	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:2	19.09	3023	1.71	13.43	106	197	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	17.8	1.21	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:2	19.09	3015	1.71	13.42	106	197	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	18.26	1.24	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:2	19.09	3014	1.71	13.44	106	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	18.96	1.29	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:2	19.09	3006	1.71	13.44	106	196	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	19.38	1.32	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:2	19.09	2986	1.71	13.45	106	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	19.75	1.35	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:3	19.09	2982	1.71	13.45	106	196	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	19.91	1.36	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:3	19.09	2966	1.71	13.44	106	196	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.19	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:3	19.09	2966	1.71	13.44	106	196	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:3	19.09	2936	1.71	13.42	106	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:3	19.09	2928	1.71	13.42	106	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:3	19.09	2916	1.71	13.42	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:4	19.09	2922	1.71	13.42	106	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:4	19.09	2920	1.71	13.43	106	197	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:4	19.09	2924	1.71	13.43	106	197	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:4	19.09	2927	1.71	13.43	106	197	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:4	19.09	2936	1.71	13.44	106	197	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:4	19.09	2944	1.71	13.44	106	197	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:4	19.09	2970	1.71	13.44	106	197	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:5	19.09	2960	1.71	13.44	106	197	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:5	19.09	2954	1.71	13.42	106	197	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:5	19.09	2966	1.71	13.41	106	197	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:5	19.09	2954	1.71	13.43	106	197	Idle	40	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.51	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:5	19.09	2949	1.71	13.41	106	197	Idle	40.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:5	19.09	2938	1.71	13.43	106	197	Idle	40.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:6	19.09	2938	1.71	13.42	106	197	Idle	40.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:6	19.09	2907	1.71	13.42	106	197	Idle	40.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:6	19.09	2924	1.71	13.43	106	197	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:6	19.09	2922	1.71	13.43	106	197	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:6	19.09	2925	1.71	13.44	106	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:6	19.09	2925	1.71	13.44	106	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:6	19.09	2907	1.71	13.45	106	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:7	19.09	2932	1.71	13.45	106	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:7	19.09	2961	1.71	13.45	106	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:7	19.09	2961	1.71	13.45	106	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:7	19.09	2943	1.71	13.44	106	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:7	19.09	2942	1.71	13.44	106	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:7	19.09	2938	1.71	13.44	106	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:8	19.09	2936	1.71	13.44	106	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:8	19.09	2930	1.7	13.44	106	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:8	19.09	2923	1.7	13.43	106	197	Full Load	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:8	19.09	2915	1.7	13.43	106	197	Off Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:8	19.09	2914	1.71	13.43	106	196	Off Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:16:59:8	9.54	2834	1.71	13.44	106	196	Off Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:59:9	9.54	2914	1.71	13.44	106	196	Off Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:59:9	12.27	2922	1.72	13.44	106	197	Off Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.48	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:16:59:9	14.99	2922	1.72	13.44	106	197	Off Idle	42.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.4	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:16:59:9	17.72	2924	1.73	13.44	106	197	Off Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.31	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:59:9	17.72	2926	1.74	13.43	106	197	Off Idle	42.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.29	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:59:9	20.45	2931	1.75	13.43	106	197	Off Idle	42.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.21	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:16:59:9	23.18	2931	1.76	13.43	106	197	Off Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.15	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:00:0	25.9	2938	1.77	13.42	106	197	Off Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.11	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:00:0	25.9	2949	1.79	13.42	106	197	Off Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.05	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:00:0	28.63	2968	1.8	13.41	106	197	Off Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.01	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:0	31.36	2966	1.81	13.41	106	197	Off Idle	43.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.99	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:0	34.08	2975	1.82	13.42	106	197	Off Idle	43.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.01	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:0	36.81	2975	1.84	13.43	106	197	Off Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.98	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:00:1	36.81	2956	1.85	13.42	106	196	Off Idle	43.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.93	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:00:1	36.81	2959	1.87	13.42	106	196	Off Idle	42.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.91	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:1	36.81	2957	1.89	13.42	106	196	Off Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.87	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:1	36.81	2956	1.9	13.42	106	197	Off Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.83	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:1	36.81	2953	1.91	13.41	106	197	Off Idle	42.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.86	20.24	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:00:1	36.81	2952	1.92	13.43	106	197	Off Idle	42.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.84	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:1	36.81	2952	1.93	13.41	106	197	Off Idle	42	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.79	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:2	36.81	2944	1.93	13.42	106	197	Off Idle	41.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.74	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:2	36.81	2942	1.94	13.42	106	197	Off Idle	41.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.7	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:00:2	36.81	2932	1.95	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.59	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:00:2	36.81	2925	1.96	13.39	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.57	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:00:2	36.81	2924	1.97	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.5	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:00:2	36.81	2906	1.98	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.46	20.19	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:3	36.81	2908	1.98	13.42	106	197	Off Idle	41.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.41	20.05	1.37	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:3	36.81	2902	1.98	13.41	106	197	Off Idle	41.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.4	19.84	1.35	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:3	36.81	2902	1.99	13.42	106	197	Off Idle	41.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.31	19.6	1.34	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:3	36.81	2910	2	13.41	106	197	Off Idle	41.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.25	19.47	1.33	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:3	36.81	2913	2.01	13.41	106	197	Off Idle	41.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.16	19.32	1.32	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:00:3	36.81	2924	2.02	13.41	106	197	Off Idle	42	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.08	18.84	1.28	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:00:4	36.81	2925	2.03	13.4	106	197	Off Idle	42.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.01	18.48	1.26	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:00:4	35.45	2930	2.04	13.41	106	197	Off Idle	42.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8	18.12	1.23	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:00:4	35.45	2935	2.06	13.41	106	197	Off Idle	42.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.92	17.75	1.21	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:00:4	35.45	2941	2.07	13.41	106	197	Off Idle	42.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.86	17.23	1.17	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:00:4	35.45	2940	2.08	13.39	106	197	Off Idle	42.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.74	16.97	1.16	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:00:4	35.45	2946	2.1	13.41	106	197	Off Idle	42.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.65	16.78	1.14	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:00:4	36.81	2946	2.12	13.41	106	197	Off Idle	42.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.5	16.62	1.13	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:00:5	36.81	2944	2.12	13.41	106	197	Off Idle	42.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.42	16.5	1.12	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:00:5	36.81	2949	2.13	13.41	106	197	Off Idle	42.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.33	16.4	1.12	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:00:5	36.81	2948	2.14	13.42	106	197	Off Idle	42.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.25	16.29	1.11	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:00:5	36.81	2946	2.16	13.42	106	197	Off Idle	42.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.23	16.24	1.11	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:00:5	35.45	2919	2.17	13.41	106	197	Off Idle	42.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.17	16.18	1.1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:00:5	35.45	2936	2.18	13.41	106	197	Off Idle	42	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.13	16.12	1.1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:6	35.45	2934	2.2	13.41	106	197	Off Idle	41.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.13	16.09	1.1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:6	35.45	2927	2.21	13.4	106	197	Off Idle	41.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.07	16.06	1.09	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:6	35.45	2928	2.22	13.42	106	197	Off Idle	41.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.99	16.05	1.09	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:6	35.45	2927	2.23	13.41	106	197	Off Idle	41.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7	16.02	1.09	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:6	35.45	2928	2.24	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.97	15.98	1.09	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:6	35.45	2923	2.24	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.92	15.93	1.09	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:6	35.45	2937	2.25	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.88	15.92	1.08	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:7	35.45	2938	2.25	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.81	15.89	1.08	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:7	35.45	2942	2.26	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.8	15.81	1.08	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:00:7	35.45	2965	2.26	13.44	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.75	15.75	1.07	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:00:7	35.45	2946	2.26	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.75	15.69	1.07	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:00:7	35.45	2946	2.27	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.69	15.61	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:00:7	35.45	2948	2.27	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.7	15.53	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:8	35.45	2948	2.27	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.61	15.44	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:8	35.45	2948	2.28	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.58	15.33	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:8	35.45	2948	2.28	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.57	15.27	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:8	35.45	2948	2.29	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.48	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:00:8	35.45	2953	2.3	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.49	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:00:8	35.45	2954	2.3	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.39	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:00:9	35.45	2953	2.31	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.33	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:00:9	35.45	2956	2.32	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.23	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:00:9	35.45	2958	2.33	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.13	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:00:9	35.45	2974	2.33	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.12	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:00:9	35.45	2966	2.34	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.16	Rich	1	14.6	-6.03	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:00:9	35.45	2967	2.35	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.12	Rich	1	14.6	-6.02	15.04	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:00:9	35.45	2968	2.35	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6	15.06	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:01:0	35.45	2959	2.36	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.92	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:0	35.45	2944	2.37	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.86	15.15	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:0	35.45	2952	2.38	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.81	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:0	35.45	2957	2.38	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.77	15.21	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:0	35.45	2957	2.39	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.74	15.24	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:0	35.45	2956	2.4	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.7	15.26	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:1	35.45	2963	2.41	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.73	15.24	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:1	35.45	2967	2.41	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.7	15.23	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:1	35.45	2969	2.42	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.67	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:1	35.45	2968	2.43	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.63	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:1	35.45	2972	2.43	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.62	15.08	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:1	35.45	2972	2.44	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.55	15.02	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:01:1	35.45	2980	2.44	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.54	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:01:2	35.45	2981	2.45	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.48	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:01:2	35.45	2982	2.45	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.47	14.88	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:01:2	35.45	2988	2.46	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.44	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:2	35.45	2988	2.46	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.44	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:2	35.45	2988	2.47	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.39	14.81	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:2	35.45	2992	2.47	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.35	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:01:3	35.45	2990	2.48	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.32	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:01:3	35.45	2990	2.48	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.29	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:01:3	35.45	2990	2.49	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.26	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:01:3	35.45	2985	2.5	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.21	14.87	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:01:3	35.45	2986	2.5	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.17	14.92	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:01:3	35.45	2986	2.51	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.08	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:01:4	35.45	2986	2.52	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.98	15	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:01:4	35.45	2995	2.53	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.98	15.02	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:01:4	35.45	2999	2.54	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.8	15	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:01:4	35.45	3007	2.55	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.76	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:01:4	35.45	3008	2.56	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.63	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:4	35.45	3012	2.57	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.56	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:4	35.45	3015	2.58	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.52	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:5	35.45	3015	2.59	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.43	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:01:5	35.45	3015	2.6	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.43	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:01:5	35.45	3006	2.61	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.38	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:01:5	35.45	3019	2.62	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.37	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:01:5	35.45	3015	2.63	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.33	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:01:5	35.45	3007	2.64	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.3	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:6	35.45	3007	2.64	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.33	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:6	35.45	3013	2.65	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.25	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:6	35.45	3017	2.65	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.26	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:6	35.45	3020	2.66	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.26	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:6	35.45	3020	2.66	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.19	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:6	35.45	3028	2.67	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.19	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:01:8	35.45	3030	2.67	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.16	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:7	34.08	3014	2.67	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.13	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:7	34.08	3029	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.17	14.77	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:7	34.08	3029	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.17	14.75	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:7	34.08	3033	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.16	14.71	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:01:7	34.08	3035	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.14	14.69	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:01:7	34.08	3044	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.18	14.69	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:8	34.08	3046	2.68	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.19	14.69	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:8	34.08	3047	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.14	14.69	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:8	34.08	3074	2.68	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.12	14.71	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:8	34.08	3047	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.16	14.73	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:8	34.08	3048	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.15	14.77	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:8	34.08	3049	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.13	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:9	34.08	3046	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.18	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:9	34.08	3050	2.69	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.18	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:9	34.08	3051	2.69	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.16	14.82	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:9	34.08	3052	2.69	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.14	14.81	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:9	34.08	3054	2.69	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.12	14.82	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:9	34.08	3054	2.69	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.05	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:01:9	34.08	3060	2.69	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.1	14.82	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:0	34.08	3062	2.69	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.07	14.81	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:0	34.08	3069	2.69	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.09	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:0	34.08	3069	2.69	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.12	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:0	34.08	3080	2.7	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.09	14.82	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:0	34.08	3070	2.7	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.13	14.81	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:02:0	34.08	3070	2.7	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.08	14.81	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:1	34.08	3075	2.7	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.06	14.8	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:1	34.08	3078	2.7	13.39	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.01	14.81	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:1	34.08	3079	2.7	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-4	14.83	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:1	34.08	3082	2.7	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4	14.88	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:1	34.08	3082	2.7	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.02	14.9	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:1	34.08	3069	2.7	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-4.04	14.93	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:1	34.08	3079	2.71	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.99	14.94	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:2	34.08	3079	2.71	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.97	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:2	34.08	3088	2.71	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.97	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:2	34.08	3102	2.71	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.94	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:2	34.08	3094	2.71	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.93	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:2	34.08	3092	2.71	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.94	14.97	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:2	34.08	3096	2.71	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.99	14.93	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:3	34.08	3098	2.71	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.95	14.9	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:3	34.08	3096	2.71	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.97	14.86	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:3	34.08	3094	2.71	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.64	Lean	1	14.6	-3.99	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:3	34.08	3096	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.63	Lean	1	14.6	-3.99	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:3	34.08	3100	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.04	14.84	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:3	34.08	3099	2.72	13.4	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4	14.84	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:4	34.08	3107	2.72	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.02	14.84	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:02:4	34.08	3106	2.72	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.95	14.85	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:02:4	34.08	3115	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.98	14.85	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:02:4	34.08	3115	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.94	14.85	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:02:4	34.08	3125	2.72	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.94	14.84	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:02:4	34.08	3128	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.01	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:02:4	34.08	3127	2.72	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-3.95	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:5	34.08	3127	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.02	14.89	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:5	34.08	3121	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.95	14.92	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:5	34.08	3119	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.03	14.99	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:5	34.08	3125	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.02	15	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:5	34.08	3124	2.72	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.98	15.01	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:5	34.08	3126	2.72	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.02	15	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:02:6	34.08	3124	2.73	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.95	14.99	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:6	34.08	3134	2.73	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.94	14.97	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:6	34.08	3134	2.73	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.96	14.94	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:6	34.08	3142	2.73	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.96	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:6	34.08	3142	2.73	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:6	34.08	3145	2.73	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.01	14.77	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:6	34.08	3143	2.73	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.02	14.74	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:02:7	34.08	3157	2.73	13.44	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4	14.73	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:02:7	34.08	3142	2.73	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.98	14.76	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:02:7	34.08	3141	2.73	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4	14.78	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:02:7	34.08	3141	2.73	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.03	14.8	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:7	34.08	3130	2.73	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.02	14.81	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:7	34.08	3152	2.73	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.05	14.82	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:8	34.08	3156	2.73	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.08	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:8	34.08	3163	2.72	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.14	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:02:8	34.08	3164	2.72	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.18	14.93	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:02:8	34.08	3160	2.72	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.24	14.95	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:02:9	34.08	3160	2.71	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.24	14.96	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:02:9	34.08	3148	2.71	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.3	15.01	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:02:9	34.08	3161	2.7	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.35	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:02:9	34.08	3161	2.7	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.44	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:02:9	34.08	3161	2.69	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.5	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:02:9	35.45	3186	2.68	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.62	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:02:9	35.45	3167	2.67	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.77	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:03:0	35.45	3175	2.67	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.79	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:0	35.45	3172	2.66	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.93	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:0	35.45	3174	2.65	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.02	14.9	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:0	35.45	3176	2.64	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.2	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:03:0	35.45	3180	2.63	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.25	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:0	35.45	3181	2.61	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.42	14.83	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:03:1	35.45	3179	2.6	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.46	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:03:1	35.45	3181	2.59	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.57	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:03:1	35.45	3180	2.57	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.64	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:03:1	35.45	3167	2.55	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.78	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:1	35.45	3173	2.53	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.84	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:1	35.45	3173	2.52	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.92	14.9	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:1	35.45	3166	2.51	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.95	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:2	35.45	3169	2.49	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.04	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:2	35.45	3172	2.48	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.09	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:2	35.45	3176	2.47	13.45	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.15	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:2	35.45	3176	2.46	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.13	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:2	35.45	3189	2.45	13.45	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.2	15.25	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:2	35.45	3190	2.44	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.17	15.29	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:3	35.45	3200	2.43	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.23	15.34	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:3	35.45	3209	2.42	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.28	15.37	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:3	35.45	3213	2.41	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.32	15.42	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:3	35.45	3212	2.41	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.33	15.45	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:3	35.45	3199	2.41	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.35	15.47	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:3	35.45	3193	2.4	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.33	15.49	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:4	35.45	3193	2.4	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.35	15.53	1.06	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:4	35.45	3193	2.4	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.32	15.59	1.06	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:4	35.45	3193	2.4	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.31	15.63	1.06	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:4	35.45	3199	2.4	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.37	15.66	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:4	35.45	3209	2.4	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.3	15.68	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:4	35.45	3209	2.4	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.35	15.7	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:4	35.45	3212	2.4	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.32	15.71	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:5	35.45	3212	2.4	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.35	15.7	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:5	35.45	3214	2.4	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.38	15.71	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:03:5	35.45	3220	2.4	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.39	15.71	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:5	35.45	3220	2.4	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.36	15.69	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:5	35.45	3220	2.4	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.39	15.65	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:5	35.45	3219	2.4	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.44	15.62	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:6	35.45	3220	2.4	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.37	15.61	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:6	35.45	3220	2.4	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.45	15.58	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:6	35.45	3220	2.4	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.44	15.58	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:6	36.81	3219	2.4	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.44	15.54	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:03:6	36.81	3224	2.4	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.35	15.52	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:6	36.81	3247	2.4	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.41	15.48	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:03:6	36.81	3236	2.4	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.31	15.46	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:03:7	36.81	3216	2.41	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.34	15.42	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:03:7	35.45	3226	2.41	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.34	15.39	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:03:7	35.45	3226	2.41	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.24	15.36	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:03:7	35.45	3222	2.42	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.24	15.33	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:03:7	35.45	3230	2.42	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.13	15.31	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:03:7	36.81	3237	2.43	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.07	15.3	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:8	36.81	3242	2.44	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.01	15.28	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:8	36.81	3245	2.44	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.91	15.28	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:8	36.81	3251	2.45	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.92	15.29	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:8	36.81	3228	2.46	13.42	105	197	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.85	15.3	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:03:8	35.45	3228	2.46	13.45	105	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.85	15.3	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:03:8	35.45	3273	2.47	13.43	105	197	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.77	15.27	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:03:9	35.45	3242	2.48	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.71	15.25	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:03:9	35.45	3242	2.49	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.74	15.23	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:03:9	35.45	3243	2.5	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.65	15.23	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:9	35.45	3234	2.51	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.6	15.21	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:9	35.45	3247	2.51	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.61	15.22	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:9	35.45	3248	2.52	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.57	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:03:9	35.45	3262	2.53	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.6	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:0	36.81	3262	2.53	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.62	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:0	36.81	3265	2.54	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.6	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:0	36.81	3259	2.54	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.62	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:0	36.81	3259	2.55	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.6	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:0	36.81	3246	2.55	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.58	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:0	35.45	3254	2.55	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.6	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:1	35.45	3252	2.56	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.57	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:1	35.45	3259	2.56	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.5	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:1	35.45	3259	2.56	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.57	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:1	35.45	3275	2.56	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.5	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:1	35.45	3266	2.56	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.55	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:1	35.45	3275	2.56	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.59	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:1	35.45	3274	2.56	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.57	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:2	35.45	3260	2.56	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.52	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:2	35.45	3270	2.56	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.58	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:2	35.45	3270	2.56	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.54	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:04:2	35.45	3277	2.56	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.54	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:2	35.45	3286	2.56	13.44	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.53	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:2	35.45	3286	2.56	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.55	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:3	35.45	3291	2.56	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.58	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:3	35.45	3288	2.56	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.66	14.9	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:3	35.45	3293	2.56	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.6	14.91	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:3	35.45	3295	2.56	13.44	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.64	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:3	35.45	3293	2.56	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.65	15.04	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:3	35.45	3294	2.56	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.6	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:4	35.45	3291	2.56	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.64	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:4	35.45	3284	2.56	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.68	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:4	35.45	3295	2.56	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.7	15.05	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:04:4	36.81	3295	2.56	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.71	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:4	36.81	3300	2.56	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.71	14.98	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:4	36.81	3304	2.55	13.42	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.74	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:4	36.81	3307	2.55	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.76	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:5	35.45	3296	2.55	13.41	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.79	14.86	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:5	35.45	3314	2.55	13.43	106	197	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.87	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:04:5	35.45	3317	2.54	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.95	14.77	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:04:5	35.45	3315	2.54	13.42	105	197	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.99	14.78	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:04:5	35.45	3314	2.53	13.43	105	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.13	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:04:6	36.81	3326	2.52	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.17	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:04:6	36.81	3306	2.51	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.33	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:04:6	36.81	3301	2.49	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.43	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:04:6	36.81	3294	2.47	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.64	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:04:6	36.81	3294	2.44	13.4	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.78	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:04:6	36.81	3297	2.42	13.41	105	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.01	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:04:6	36.81	3300	2.4	13.41	105	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.12	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:04:6	36.81	3300	2.37	13.41	105	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.46	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:04:7	36.81	3298	2.34	13.42	105	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.66	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:04:7	36.81	3304	2.32	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.92	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:04:7	36.81	3301	2.28	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.1	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:04:7	36.81	3302	2.25	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.28	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:04:7	36.81	3301	2.2	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.52	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:04:7	36.81	3311	2.17	13.42	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.69	14.79	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:17:04:8	38.18	3298	2.14	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.78	14.78	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:17:04:8	38.18	3297	2.09	13.41	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.99	14.75	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:17:04:8	38.18	3292	2.05	13.43	106	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.07	14.74	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:17:04:8	38.18	3287	2	13.42	106	197	Full Load	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.22	14.74	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:17:04:8	38.18	3278	1.97	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.35	14.74	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:04:8	38.18	3267	1.94	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.39	14.73	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:04:9	38.18	3268	1.89	13.45	105	197	Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.51	14.72	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:04:9	38.18	3258	1.87	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.6	14.73	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:04:9	38.18	3258	1.85	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.65	14.73	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:04:9	32.72	3211	1.83	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.69	14.73	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:04:9	27.27	3211	1.79	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.76	14.75	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:04:9	27.27	3215	1.78	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.82	14.76	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:04:9	21.81	3260	1.76	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.82	14.75	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:0	20.45	3279	1.75	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.85	14.75	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:0	20.45	3264	1.74	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.88	14.79	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:0	20.45	3282	1.73	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.93	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:0	20.45	3307	1.72	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.91	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:0	20.45	3334	1.71	13.43	106	197	Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.94	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:0	20.45	3320	1.71	13.43	106	197	Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.92	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:1	20.45	3304	1.7	13.43	106	197	Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.88	14.98	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:1	20.45	3298	1.7	13.43	106	197	Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.86	15.01	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:1	20.45	3295	1.7	13.43	106	197	Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.84	15.07	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:1	20.45	3292	1.7	13.43	106	197	Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.82	15.12	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:1	20.45	3286	1.7	13.44	106	197	Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.79	15.16	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:1	20.45	3286	1.7	13.43	106	197	Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.78	15.16	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:1	20.45	3285	1.7	13.44	106	197	Idle	41.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.82	15.17	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:2	20.45	3286	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.74	15.17	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:2	20.45	3290	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.78	15.17	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:2	20.45	3294	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.73	15.19	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:2	20.45	3296	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.75	15.2	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:2	20.45	3296	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.75	15.22	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:2	20.45	3298	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	15.27	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:3	20.45	3299	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	15.34	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:3	20.45	3295	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	15.48	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:3	20.45	3291	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	15.92	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:05:3	20.45	3290	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	16.38	1.12	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:3	20.45	3283	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	16.89	1.15	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:3	20.45	3280	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	17.38	1.18	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:4	20.45	3279	1.7	13.43	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	17.87	1.22	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:4	20.45	3274	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	18.35	1.25	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:4	20.45	3274	1.7	13.43	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	18.83	1.28	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:4	20.45	3247	1.7	13.45	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	19.28	1.31	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:4	20.45	3272	1.7	13.46	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	19.86	1.35	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:4	20.45	3272	1.7	13.45	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.1	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:4	20.45	3288	1.7	13.45	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:5	20.45	3277	1.7	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:5	20.45	3277	1.7	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:5	20.45	3281	1.7	13.42	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:5	20.45	3283	1.7	13.42	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:5	20.45	3257	1.7	13.42	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:5	20.45	3270	1.7	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:6	20.45	3282	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:6	20.45	3279	1.7	13.46	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:6	20.45	3274	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:6	20.45	3274	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:6	20.45	3284	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:6	20.45	3268	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:6	20.45	3265	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:7	20.45	3264	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:7	20.45	3263	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:7	20.45	3236	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:7	20.45	3236	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:7	20.45	3261	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:7	20.45	3275	1.7	13.45	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:8	20.45	3266	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:8	20.45	3266	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:8	20.45	3258	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:8	20.45	3274	1.7	13.46	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:8	20.45	3275	1.7	13.45	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:8	20.45	3277	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:9	20.45	3277	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:9	20.45	3264	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:9	20.45	3264	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:9	20.45	3268	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:9	20.45	3264	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:9	20.45	3260	1.7	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:05:9	20.45	3260	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:0	20.45	3256	1.7	13.41	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:0	20.45	3254	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:0	20.45	3254	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:0	20.45	3254	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:0	20.45	3258	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:0	20.45	3259	1.7	13.47	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:1	20.45	3258	1.7	13.46	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:1	20.45	3260	1.7	13.46	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:1	20.45	3258	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:1	20.45	3256	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:1	20.45	3256	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:1	20.45	3252	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:1	20.45	3249	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:2	20.45	3248	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:2	20.45	3250	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:2	20.45	3250	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:06:2	20.45	3250	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:2	20.45	3249	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:2	20.45	3250	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:3	20.45	3253	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:3	20.45	3252	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:3	20.45	3248	1.7	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:3	20.45	3248	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:3	20.45	3248	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:3	20.45	3235	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:4	20.45	3244	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:4	20.45	3240	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:4	20.45	3240	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:4	20.45	3237	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:4	20.45	3233	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:4	20.45	3230	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:4	20.45	3229	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:5	20.45	3228	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:5	20.45	3228	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:5	20.45	3229	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:5	20.45	3232	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:5	20.45	3238	1.7	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:5	20.45	3243	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:6	20.45	3243	1.7	13.45	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:6	20.45	3246	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:6	20.45	3244	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:6	20.45	3243	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:6	20.45	3244	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:6	20.45	3238	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:6	20.45	3234	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:7	20.45	3252	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:7	20.45	3240	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:7	20.45	3224	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:7	20.45	3222	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:7	20.45	3223	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:7	20.45	3222	1.7	13.41	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:8	20.45	3226	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:8	20.45	3226	1.7	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:8	20.45	3227	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:8	20.45	3227	1.7	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:8	20.45	3229	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:8	20.45	3229	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:9	20.45	3228	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:9	20.45	3227	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:9	20.45	3224	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:9	20.45	3222	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:9	20.45	3222	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:9	20.45	3219	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:06:9	20.45	3215	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:0	20.45	3214	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:0	20.45	3209	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:0	20.45	3210	1.7	13.45	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:0	20.45	3206	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:0	20.45	3206	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:0	20.45	3207	1.7	13.45	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:1	20.45	3206	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:1	20.45	3209	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:1	20.45	3211	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:1	20.45	3211	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:07:1	20.45	3213	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:1	20.45	3215	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:1	20.45	3217	1.7	13.42	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:2	20.45	3216	1.7	13.43	105	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:2	20.45	3213	1.7	13.43	105	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:2	20.45	3210	1.7	13.43	105	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:2	20.45	3210	1.7	13.42	106	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:2	20.45	3206	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:2	20.45	3205	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:3	20.45	3204	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:3	20.45	3200	1.7	13.42	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:3	20.45	3200	1.7	13.43	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:3	20.45	3201	1.7	13.43	106	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:3	20.45	3202	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:3	20.45	3200	1.7	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:4	20.45	3204	1.7	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:4	20.45	3204	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:4	20.45	3202	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:4	20.45	3203	1.71	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:4	20.45	3200	1.71	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:4	20.45	3197	1.71	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:4	20.45	3197	1.71	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:5	20.45	3194	1.71	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:5	20.45	3191	1.71	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:5	20.45	3189	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:5	20.45	3190	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:5	20.45	3190	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:5	20.45	3194	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:6	20.45	3194	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:6	20.45	3198	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:6	20.45	3199	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:6	20.45	3201	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:6	20.45	3201	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:6	20.45	3200	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:6	20.45	3198	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:7	20.45	3198	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:7	20.45	3198	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:7	20.45	3193	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:7	20.45	3190	1.7	13.44	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:7	20.45	3191	1.7	13.44	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:7	20.45	3190	1.7	13.45	106	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:8	20.45	3189	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:8	20.45	3192	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:8	20.45	3191	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:8	20.45	3190	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:8	20.45	3192	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:8	20.45	3192	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:9	20.45	3192	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:9	20.45	3186	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:9	20.45	3189	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:9	20.45	3189	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:9	20.45	3184	1.7	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:9	20.45	3183	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:07:9	20.45	3179	1.7	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:0	20.45	3178	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:0	20.45	3178	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:0	20.45	3176	1.7	13.45	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:0	20.45	3177	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:08:0	20.45	3178	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:0	20.45	3179	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:1	20.45	3182	1.7	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:1	20.45	3181	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:1	20.45	3180	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:1	20.45	3176	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:1	20.45	3174	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:1	20.45	3173	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:1	20.45	3172	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:2	20.45	3168	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:2	20.45	3168	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:2	20.45	3158	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:2	20.45	3172	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:2	20.45	3172	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:2	20.45	3186	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:3	20.45	3171	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:3	20.45	3171	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:3	20.45	3172	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:3	20.45	3170	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:3	20.45	3164	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:3	20.45	3164	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:4	20.45	3161	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:4	20.45	3158	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:4	20.45	3154	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:4	20.45	3151	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:4	20.45	3152	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:4	20.45	3152	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:4	20.45	3140	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:5	20.45	3153	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:5	20.45	3179	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:5	20.45	3167	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:5	20.45	3154	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:5	20.45	3156	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:5	20.45	3154	1.7	13.45	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:6	20.45	3151	1.7	13.44	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:6	20.45	3150	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:6	20.45	3149	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:6	20.45	3131	1.7	13.43	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:6	20.45	3142	1.7	13.42	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:6	20.45	3142	1.7	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:6	20.45	3154	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:7	20.45	3154	1.7	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:7	20.45	3142	1.7	13.42	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:7	20.45	3131	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:7	20.45	3147	1.7	13.43	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:7	20.45	3172	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:7	20.45	3159	1.7	13.43	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:8	20.45	3148	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:8	20.45	3150	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:8	20.45	3148	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:8	20.45	3136	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:8	20.45	3148	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:8	20.45	3142	1.7	13.46	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:9	20.45	3142	1.7	13.45	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:9	20.45	3141	1.7	13.45	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:9	20.45	3138	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:9	20.45	3140	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:9	20.45	3141	1.7	13.45	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:08:9	20.45	3140	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:08:9	20.45	3138	1.7	13.44	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:0	20.45	3136	1.7	13.43	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:0	20.45	3135	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:0	20.45	3135	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:0	20.45	3133	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:0	20.45	3134	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:0	20.45	3134	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:1	20.45	3126	1.7	13.43	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:1	20.45	3129	1.7	13.44	106	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:1	20.45	3123	1.7	13.43	105	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:1	20.45	3121	1.7	13.44	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:1	20.45	3120	1.7	13.42	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:1	20.45	3120	1.7	13.42	105	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:1	20.45	3119	1.7	13.41	105	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:2	19.09	3108	1.7	13.41	105	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:2	19.09	3141	1.7	13.38	105	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:2	20.45	3127	1.7	13.38	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:2	20.45	3110	1.7	13.37	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:2	19.09	3109	1.7	13.37	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:2	19.09	3110	1.7	13.36	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:3	19.09	3086	1.7	13.39	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:3	19.09	3098	1.7	13.4	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:3	19.09	3112	1.7	13.4	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:3	19.09	3119	1.7	13.4	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:3	19.09	3122	1.7	13.41	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:3	20.45	3133	1.7	13.39	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:4	20.45	3122	1.7	13.41	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:4	20.45	3122	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:4	20.45	3122	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:4	20.45	3114	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:4	20.45	3109	1.7	13.41	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:4	20.45	3109	1.7	13.41	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:4	20.45	3101	1.7	13.4	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:5	20.45	3095	1.7	13.41	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:5	20.45	3093	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:5	20.45	3064	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:5	19.09	3075	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:5	19.09	3085	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:5	19.09	3085	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:6	19.09	3085	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:6	19.09	3084	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:6	19.09	3083	1.7	13.39	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:6	19.09	3083	1.7	13.39	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:6	19.09	3081	1.7	13.39	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:6	19.09	3080	1.7	13.4	106	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:6	19.09	3077	1.7	13.41	106	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:7	19.09	3072	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:7	19.09	3074	1.7	13.38	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:7	19.09	3071	1.7	13.38	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:7	19.09	3069	1.7	13.38	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:7	19.09	3069	1.7	13.37	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:7	19.09	3069	1.7	13.37	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:8	19.09	3067	1.7	13.38	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:8	19.09	3067	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:8	19.09	3068	1.7	13.39	106	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:8	19.09	3064	1.7	13.4	106	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:8	19.09	3065	1.7	13.39	105	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:09:8	19.09	3063	1.7	13.4	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:9	19.09	3061	1.7	13.4	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:9	19.09	3054	1.7	13.39	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:9	19.09	3052	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:9	19.09	3048	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:9	19.09	3040	1.7	13.38	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:9	19.09	3033	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:09:9	19.09	3033	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:0	19.09	3026	1.7	13.4	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:0	19.09	3023	1.7	13.4	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:0	19.09	3022	1.7	13.39	105	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:0	19.09	3021	1.7	13.4	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:0	19.09	3020	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:0	19.09	3019	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:1	19.09	3019	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:1	19.09	3028	1.7	13.41	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:1	19.09	3028	1.7	13.41	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:1	19.09	3000	1.7	13.4	105	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:1	19.09	3007	1.7	13.4	105	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:1	19.09	3005	1.7	13.4	105	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:1	19.09	2998	1.7	13.38	105	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:2	19.09	2989	1.7	13.39	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:2	19.09	2982	1.7	13.38	105	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:2	19.09	2980	1.7	13.39	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:2	19.09	2973	1.7	13.38	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:2	19.09	2969	1.7	13.39	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:2	19.09	2969	1.7	13.38	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:3	19.09	2969	1.7	13.38	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:3	19.09	2968	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:3	19.09	2968	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:3	19.09	2970	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:3	19.09	2970	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:3	19.09	2968	1.7	13.4	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:4	19.09	2969	1.7	13.4	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:4	19.09	2967	1.7	13.4	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:4	19.09	2942	1.7	13.38	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:4	19.09	2962	1.7	13.38	105	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:4	19.09	2962	1.7	13.38	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:4	19.09	2954	1.7	13.39	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:4	19.09	2951	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:5	19.09	2946	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:5	19.09	2946	1.7	13.41	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:5	19.09	2941	1.7	13.41	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:5	19.09	2933	1.7	13.41	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:5	19.09	2928	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:5	19.09	2927	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:6	19.09	2924	1.7	13.41	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:6	19.09	2896	1.7	13.41	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:6	19.09	2916	1.7	13.41	105	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:6	19.09	2916	1.7	13.4	105	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:6	19.09	2915	1.7	13.41	105	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:6	19.09	2914	1.7	13.39	105	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:6	19.09	2889	1.7	13.4	105	197	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:7	19.09	2889	1.7	13.39	105	197	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:7	19.09	2904	1.7	13.39	105	197	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:7	19.09	2893	1.7	13.37	105	197	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:7	19.09	2878	1.7	13.39	105	197	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:7	19.09	2878	1.7	13.37	105	197	Idle	42	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:10:7	19.09	2854	1.7	13.38	105	197	Idle	42.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:8	19.09	2854	1.7	13.38	105	197	Idle	42.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:8	19.09	2858	1.7	13.39	105	197	Idle	42.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:8	19.09	2857	1.7	13.4	105	197	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:8	19.09	2858	1.7	13.38	105	197	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:8	19.09	2864	1.7	13.38	105	197	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:8	19.09	2868	1.69	13.38	106	197	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:9	19.09	2874	1.69	13.39	106	196	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:9	19.09	2874	1.69	13.39	106	196	Idle	42.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:9	19.09	2873	1.69	13.39	105	196	Idle	42.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:9	19.09	2873	1.69	13.39	105	197	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:9	19.09	2870	1.69	13.41	105	197	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:9	19.09	2866	1.69	13.39	105	197	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:10:9	19.09	2857	1.69	13.41	105	197	Idle	43.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:0	19.09	2855	1.69	13.39	105	197	Idle	43.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:0	19.09	2846	1.69	13.39	105	197	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:0	19.09	2815	1.69	13.4	105	197	Idle	43.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:0	19.09	2822	1.68	13.39	105	197	Idle	44.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:0	19.09	2831	1.68	13.38	105	197	Idle	44.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:0	19.09	2828	1.68	13.39	105	197	Idle	44.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:1	19.09	2820	1.68	13.39	105	197	Idle	44.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:1	19.09	2840	1.68	13.39	105	196	Idle	44.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:1	19.09	2817	1.68	13.4	105	196	Idle	44.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:1	19.09	2817	1.67	13.4	105	196	Idle	45.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:1	19.09	2806	1.67	13.39	105	197	Idle	45.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:1	19.09	2815	1.67	13.39	105	197	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:1	19.09	2813	1.67	13.39	105	197	Idle	45.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:2	19.09	2812	1.67	13.38	105	197	Idle	45.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:2	19.09	2804	1.66	13.39	105	196	Idle	45.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:2	19.09	2801	1.66	13.39	105	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:2	19.09	2800	1.66	13.38	105	197	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:2	19.09	2790	1.66	13.4	105	197	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:2	19.09	2784	1.65	13.4	105	197	Idle	46.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:3	19.09	2779	1.65	13.4	105	197	Idle	46.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:3	19.09	2779	1.65	13.4	105	197	Idle	47	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:3	19.09	2776	1.64	13.39	106	197	Idle	47.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:3	19.09	2772	1.64	13.39	106	197	Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:3	19.09	2749	1.64	13.39	106	197	Idle	47.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:3	19.09	2760	1.64	13.38	105	197	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:4	19.09	2770	1.64	13.37	105	197	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:4	19.09	2766	1.63	13.37	105	197	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:4	19.09	2768	1.63	13.38	105	196	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:4	19.09	2768	1.63	13.36	105	196	Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:4	19.09	2766	1.63	13.38	105	196	Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:4	19.09	2740	1.62	13.38	105	197	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:4	19.09	2750	1.62	13.38	105	197	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:5	19.09	2752	1.62	13.39	105	197	Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:5	19.09	2755	1.62	13.39	105	196	Idle	48.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:5	19.09	2741	1.61	13.4	105	196	Idle	48.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:5	19.09	2740	1.61	13.39	105	196	Idle	48.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:5	19.09	2713	1.61	13.39	105	196	Idle	49.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:5	19.09	2727	1.6	13.39	105	196	Idle	49.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:6	19.09	2722	1.6	13.4	105	196	Idle	49.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:6	19.09	2722	1.6	13.4	105	197	Idle	49.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:6	19.09	2718	1.59	13.4	105	197	Idle	49.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:6	19.09	2717	1.59	13.4	105	197	Idle	49.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:6	19.09	2713	1.59	13.4	105	196	Idle	50	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:6	19.09	2713	1.59	13.38	105	196	Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:11:6	19.09	2714	1.59	13.38	105	196	Idle	50.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:7	19.09	2710	1.58	13.39	105	196	Idle	50.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:7	19.09	2728	1.58	13.38	105	196	Idle	50.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:7	19.09	2715	1.58	13.38	105	196	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:7	19.09	2696	1.57	13.37	105	196	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:7	19.09	2684	1.57	13.39	105	196	Idle	50.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:7	19.09	2684	1.57	13.37	105	196	Idle	51	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:8	19.09	2655	1.56	13.37	105	196	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:8	19.09	2671	1.56	13.37	105	196	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:8	19.09	2665	1.56	13.38	105	197	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:8	19.09	2662	1.56	13.39	105	197	Idle	51.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:8	19.09	2657	1.55	13.38	105	196	Idle	52	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:8	19.09	2642	1.55	13.39	105	196	Idle	52.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:9	19.09	2649	1.55	13.39	105	196	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:9	19.09	2649	1.55	13.39	105	196	Idle	52.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:9	19.09	2646	1.54	13.39	105	196	Idle	52.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:9	19.09	2648	1.54	13.39	105	196	Idle	52.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:9	19.09	2642	1.54	13.4	105	196	Idle	53	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:9	19.09	2637	1.53	13.4	105	196	Idle	53.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:11:9	19.09	2637	1.53	13.4	105	196	Idle	53.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:0	19.09	2628	1.52	13.39	105	196	Idle	53.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:0	19.09	2617	1.52	13.39	105	196	Idle	53.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:0	19.09	2592	1.51	13.38	105	196	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:0	19.09	2598	1.51	13.38	105	196	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:0	19.09	2596	1.5	13.39	105	196	Idle	54.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:0	19.09	2596	1.5	13.39	105	196	Idle	54.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:1	19.09	2589	1.5	13.38	105	196	Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:1	19.09	2581	1.49	13.39	105	196	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:1	19.09	2578	1.49	13.39	105	196	Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:1	19.09	2577	1.48	13.39	105	196	Idle	56.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:1	19.09	2577	1.48	13.39	105	196	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:1	19.09	2576	1.47	13.4	105	196	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:1	19.09	2564	1.47	13.38	105	196	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:2	19.09	2570	1.47	13.4	105	196	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:2	19.09	2569	1.46	13.4	105	196	Idle	57.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:2	19.09	2573	1.46	13.4	105	196	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:2	19.09	2561	1.46	13.4	105	196	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:2	19.09	2541	1.45	13.41	105	196	Idle	58.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:2	19.09	2541	1.45	13.4	105	196	Idle	58.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:3	19.09	2528	1.44	13.39	105	196	Idle	58.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:3	19.09	2521	1.44	13.38	105	196	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:3	19.09	2506	1.44	13.4	105	196	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:3	19.09	2492	1.43	13.39	105	196	Idle	59.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:3	19.09	2490	1.43	13.39	105	196	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:3	19.09	2485	1.42	13.38	105	196	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:4	19.09	2484	1.42	13.38	105	196	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:4	19.09	2484	1.41	13.37	105	196	Idle	59.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:4	19.09	2484	1.41	13.38	105	196	Idle	59.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:4	19.09	2487	1.41	13.37	105	196	Idle	60.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:4	19.09	2490	1.4	13.37	105	196	Idle	60.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:4	19.09	2492	1.4	13.37	105	196	Idle	60.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:4	19.09	2492	1.4	13.38	105	196	Idle	60.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:5	19.09	2488	1.4	13.37	105	196	Idle	61.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:5	19.09	2481	1.39	13.37	105	196	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:5	19.09	2470	1.39	13.36	105	196	Idle	61.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:5	19.09	2463	1.38	13.37	105	196	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:5	19.09	2458	1.38	13.38	105	196	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:5	19.09	2431	1.37	13.37	105	196	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:12:6	19.09	2422	1.37	13.37	105	196	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:6	19.09	2418	1.36	13.37	105	196	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:6	19.09	2404	1.35	13.37	105	196	Idle	64.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:6	19.09	2379	1.35	13.36	105	196	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:6	19.09	2379	1.34	13.36	105	196	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:6	17.72	2375	1.33	13.36	105	196	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:6	17.72	2381	1.32	13.37	105	196	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:7	17.72	2407	1.32	13.37	105	196	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:7	17.72	2389	1.31	13.38	105	196	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:7	17.72	2388	1.3	13.39	105	196	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:12:7	17.72	2378	1.3	13.38	105	196	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:0	17.72	2378	1.29	13.38	105	196	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:0	17.72	2384	1.28	13.36	105	196	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:0	17.72	2331	1.24	13.38	105	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:1	17.72	2280	1.18	13.39	105	196	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:1	17.72	2250	1.14	13.38	105	196	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:1	17.72	2211	1.13	13.38	105	196	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:1	17.72	2211	1.13	13.39	105	196	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:1	17.72	2211	1.13	13.37	105	196	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:2	17.72	2220	1.12	13.36	105	196	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:2	17.72	2212	1.12	13.37	105	196	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:2	17.72	2212	1.11	13.38	105	196	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:2	17.72	2186	1.11	13.37	105	196	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:2	17.72	2198	1.1	13.38	105	196	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:2	17.72	2196	1.1	13.37	105	196	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:3	17.72	2186	1.09	13.38	105	196	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:3	17.72	2178	1.09	13.37	105	196	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:3	17.72	2175	1.08	13.37	105	196	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:3	17.72	2162	1.07	13.37	105	196	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:3	17.72	2162	1.07	13.38	105	196	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:3	17.72	2153	1.06	13.38	105	196	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:4	17.72	2145	1.06	13.38	105	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:4	17.72	2131	1.05	13.39	105	196	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:4	17.72	2118	1.04	13.38	105	196	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:4	17.72	2117	1.03	13.36	105	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:4	17.72	2111	1.03	13.37	105	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:4	17.72	2108	1.02	13.36	105	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:4	17.72	2100	1.01	13.36	105	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:5	17.72	2096	1.01	13.38	105	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:5	17.72	2094	1.01	13.4	106	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:5	17.72	2085	1	13.41	106	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:5	17.72	2077	1	13.4	106	196	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:5	17.72	2077	1	13.39	105	196	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:5	17.72	2068	0.99	13.38	105	196	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:6	17.72	2058	0.99	13.36	105	196	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:6	17.72	2050	0.99	13.35	105	196	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:6	17.72	2046	0.99	13.34	105	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:6	17.72	2026	0.99	13.34	105	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:6	17.72	2025	0.99	13.34	105	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:6	17.72	2025	0.99	13.34	105	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:6	17.72	2014	0.99	13.34	105	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:7	17.72	2003	0.99	13.34	105	196	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:7	17.72	2003	0.99	13.34	105	196	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:7	17.72	1995	0.99	13.34	105	196	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:7	17.72	1988	0.99	13.34	105	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:7	17.72	1988	0.99	13.34	105	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:7	17.72	1980	0.99	13.35	105	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:8	17.72	1970	0.99	13.35	105	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:13:8	17.72	1963	0.99	13.35	105	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:8	17.72	1960	0.99	13.34	106	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:8	17.72	1946	0.99	13.35	106	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:8	17.72	1920	0.99	13.35	105	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.26	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:8	17.72	1920	0.99	13.35	105	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.26	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:9	17.72	1912	0.98	13.35	105	196	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.26	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:9	17.72	1883	0.98	13.37	105	196	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.25	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:9	17.72	1865	0.98	13.37	105	196	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.26	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:9	17.72	1854	0.98	13.36	105	196	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.26	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:9	17.72	1822	0.98	13.36	105	196	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.26	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:9	17.72	1801	0.98	13.37	105	196	Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.25	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:13:9	17.72	1801	0.98	13.36	105	196	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:0	17.72	1760	0.98	13.38	105	196	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:0	17.72	1733	0.98	13.38	105	196	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.25	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:0	17.72	1733	0.99	13.37	105	196	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:0	17.72	1708	0.99	13.37	105	196	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:0	17.72	1672	1	13.35	105	196	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:0	17.72	1661	1	13.34	105	196	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:1	17.72	1648	1.01	13.34	105	196	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:1	17.72	1618	1.02	13.35	105	196	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.24	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:1	17.72	1592	1.03	13.34	105	196	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.24	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:1	17.72	1586	1.04	13.36	105	196	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:1	17.72	1574	1.06	13.38	105	196	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:1	17.72	1526	1.07	13.37	105	196	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:1	17.72	1511	1.08	13.38	105	196	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:2	17.72	1485	1.09	13.38	105	196	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:2	17.72	1485	1.1	13.38	105	196	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	20.24	1.38	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:2	17.72	1459	1.12	13.38	105	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.33	20.24	1.38	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:2	17.72	1433	1.13	13.37	105	196	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.26	20.23	1.38	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:2	17.72	1406	1.14	13.36	105	196	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.18	20.23	1.38	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:2	17.72	1406	1.15	13.36	105	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.06	20.23	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:3	19.09	1379	1.16	13.36	105	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	20.23	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:14:3	19.09	1341	1.17	13.34	105	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.89	20.24	1.38	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:14:3	17.72	1341	1.18	13.35	105	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.82	20.24	1.38	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:14:3	17.72	1314	1.18	13.37	105	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.72	20.23	1.38	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:14:3	17.72	1295	1.19	13.36	105	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.23	1.38	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:14:3	17.72	1256	1.19	13.37	105	196	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.6	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:14:4	17.72	1256	1.19	13.37	105	196	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.52	20.24	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:14:4	17.72	1228	1.2	13.36	105	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.43	20.23	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:14:4	17.72	1219	1.2	13.36	105	196	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.36	20.23	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:14:4	16.36	1219	1.2	13.37	105	196	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.27	20.23	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:14:4	16.36	1212	1.2	13.37	105	196	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.19	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:14:4	16.36	1217	1.2	13.37	105	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.09	20.21	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:14:4	16.36	1222	1.2	13.37	105	196	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.03	20.22	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:14:5	16.36	1234	1.19	13.37	105	196	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.98	20.23	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:14:5	16.36	1241	1.19	13.37	105	196	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.96	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:14:5	16.36	1236	1.19	13.36	106	196	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.93	20.22	1.38	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:14:5	16.36	1236	1.18	13.35	106	196	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.93	20.22	1.38	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:14:5	16.36	1238	1.17	13.37	106	196	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.99	20.22	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:14:5	16.36	1254	1.16	13.35	105	196	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8	20.23	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:14:6	16.36	1254	1.15	13.35	105	196	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.08	20.23	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:14:6	16.36	1249	1.13	13.36	105	196	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.17	20.24	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:14:6	14.99	1260	1.12	13.36	105	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.18	20.24	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:14:6	14.99	1260	1.12	13.36	105	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.24	20.24	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:14:6	14.99	1256	1.1	13.36	105	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.33	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:6	14.99	1250	1.08	13.36	105	196	Idle	82.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.39	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:6	14.99	1248	1.07	13.36	105	196	Idle	83.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.46	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:7	14.99	1248	1.05	13.36	105	196	Idle	85.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.52	20.24	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:14:7	14.99	1245	1.04	13.37	105	196	Idle	86.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.57	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:7	14.99	1220	1.02	13.36	105	196	Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.62	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:7	14.99	1220	1	13.36	105	196	Idle	87.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.64	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:14:7	14.99	1208	0.99	13.35	105	196	Idle	87.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.66	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:14:7	14.99	1208	0.97	13.36	105	196	Idle	87.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.69	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:14:8	14.99	1191	0.96	13.36	105	196	Idle	87.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.72	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:14:8	14.99	1182	0.95	13.37	105	196	Idle	87.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.76	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:14:8	14.99	1168	0.93	13.37	105	196	Idle	87.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.8	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:17:14:8	14.99	1162	0.92	13.36	105	196	Idle	87.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.78	20.24	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:8	14.99	1162	0.92	13.37	105	196	Idle	87.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.79	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:8	14.99	1144	0.91	13.36	105	196	Idle	87.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.77	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:9	14.99	1133	0.91	13.36	105	196	Idle	87.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.78	20.23	1.38	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:9	14.99	1133	0.9	13.36	105	196	Idle	87.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.73	20.23	1.38	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:9	14.99	1110	0.9	13.36	105	196	Idle	87.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.73	20.23	1.38	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:9	14.99	1108	0.9	13.37	105	196	Idle	87.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.74	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:14:9	14.99	1107	0.89	13.36	105	196	Idle	87.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.7	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:14:9	14.99	1102	0.89	13.38	105	196	Idle	87.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.73	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:14:9	14.99	1097	0.89	13.38	105	196	Idle	87.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.7	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:0	14.99	1081	0.89	13.36	105	196	Idle	87.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.72	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:0	14.99	1081	0.89	13.37	105	196	Idle	88	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.67	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:0	13.63	1073	0.89	13.36	105	196	Idle	88.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.67	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:0	13.63	1070	0.89	13.37	105	196	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.66	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:0	13.63	1067	0.88	13.37	105	196	Idle	88.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.63	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:0	13.63	1057	0.88	13.37	105	196	Idle	89	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.66	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:1	13.63	1047	0.88	13.37	105	196	Idle	89.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.62	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:1	13.63	1040	0.88	13.35	105	196	Idle	89.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.64	20.21	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:1	13.63	1040	0.88	13.36	105	196	Idle	90.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.59	20.15	1.37	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:1	13.63	1032	0.87	13.35	105	196	Idle	90.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.59	20	1.36	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:1	13.63	1032	0.87	13.36	105	196	Idle	91	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.53	19.91	1.36	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:1	13.63	1035	0.87	13.36	105	196	Idle	91.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.51	19.56	1.33	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:1	13.63	1035	0.87	13.38	105	196	Idle	91.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.54	19.27	1.31	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:2	13.63	1019	0.86	13.36	105	196	Idle	91.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.49	18.96	1.29	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:2	13.63	1003	0.86	13.38	106	196	Idle	92.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	18.62	1.27	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:2	13.63	1003	0.86	13.38	106	196	Idle	92.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.5	18.28	1.25	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:2	12.27	1005	0.85	13.37	106	196	Idle	92.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.53	17.91	1.22	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:2	12.27	1007	0.85	13.38	105	196	Idle	92.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.47	17.58	1.2	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:2	12.27	1007	0.85	13.39	105	196	Idle	92.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	17.27	1.18	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:3	12.27	1003	0.84	13.38	105	196	Idle	92.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.44	17.04	1.16	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:3	12.27	1013	0.84	13.37	105	196	Idle	92.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.48	16.8	1.14	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:3	12.27	1048	0.84	13.4	105	196	Idle	92.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.47	16.7	1.14	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:3	12.27	1048	0.83	13.38	105	196	Idle	92.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	16.63	1.13	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:3	10.9	1079	0.83	13.4	105	196	Idle	92.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.49	16.58	1.13	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:3	10.9	1110	0.83	13.38	105	196	Idle	92.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.53	16.54	1.13	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:4	10.9	1110	0.83	13.38	105	196	Idle	92.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.55	16.54	1.13	4.2	2	ON	28 Pin	OFF	Removed	Disabled
03:17:15:4	10.9	1156	0.82	13.37	105	196	Idle	92.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.59	16.52	1.13	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:15:4	9.54	1225	0.82	13.37	105	196	Idle	92.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.63	16.52	1.13	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:15:4	9.54	1260	0.82	13.35	105	196	Idle	92.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.69	16.53	1.13	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:17:15:4	9.54	1260	0.82	13.35	105	196	Idle	92.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.73	16.54	1.13	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:17:15:4	8.18	1346	0.81	13.36	105	196	Idle	92.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.84	16.55	1.13	4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:17:15:4	8.18	1358	0.81	13.35	105	196	Idle	92.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.91	16.56	1.13	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:15:5	8.18	1358	0.81	13.36	105	196	Idle	92.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.05	16.55	1.13	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:15:5	8.18	1402	0.81	13.36	105	196	Idle	93	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.14	16.54	1.13	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:15:5	8.18	1424	0.81	13.35	105	196	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.24	16.52	1.13	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:15:5	8.18	1448	0.81	13.35	105	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.31	16.48	1.12	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:15:5	8.18	1490	0.81	13.36	105	196	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.43	16.45	1.12	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:15:5	8.18	1520	0.81	13.38	105	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.52	16.41	1.12	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:15:6	9.54	1588	0.81	13.37	105	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.57	16.37	1.11	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:15:6	9.54	1588	0.81	13.36	105	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.64	16.31	1.11	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:15:6	10.9	1596	0.81	13.37	105	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.75	16.24	1.11	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:15:6	10.9	1625	0.8	13.37	105	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.79	16.17	1.1	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:15:6	10.9	1642	0.8	13.35	105	196	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.9	16.1	1.1	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:15:6	10.9	1674	0.8	13.36	105	196	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.98	16.04	1.09	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:15:6	10.9	1733	0.8	13.37	105	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.07	15.99	1.09	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:15:7	10.9	1733	0.8	13.35	105	196	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.15	15.91	1.08	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:15:7	10.9	1764	0.8	13.36	105	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.24	15.83	1.08	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:15:7	10.9	1779	0.81	13.37	105	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.27	15.76	1.07	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:15:7	10.9	1800	0.81	13.38	105	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.4	15.64	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:15:7	12.27	1853	0.81	13.39	105	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.48	15.61	1.06	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:15:7	12.27	1868	0.81	13.38	105	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.5	15.55	1.06	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:8	12.27	1939	0.81	13.4	105	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.59	15.46	1.05	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:8	12.27	1939	0.81	13.4	105	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.61	15.41	1.05	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:8	12.27	1966	0.81	13.37	105	196	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.65	15.36	1.05	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:8	12.27	2007	0.81	13.37	105	196	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.67	15.32	1.04	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:8	12.27	2007	0.81	13.35	105	196	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.69	15.3	1.04	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:8	17.72	2072	0.81	13.35	105	196	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.71	15.28	1.04	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:9	17.72	2064	0.81	13.36	105	196	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.74	15.27	1.04	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:9	17.72	2101	0.81	13.38	105	196	Idle	92.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.77	15.26	1.04	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:9	17.72	2085	0.81	13.38	105	196	Idle	92.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.81	15.26	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:9	17.72	2064	0.81	13.39	106	196	Idle	91.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.85	15.28	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:9	17.72	2050	0.82	13.4	106	196	Idle	91.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.86	15.32	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:9	17.72	2042	0.82	13.39	106	196	Idle	90.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.86	15.34	1.05	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:15:9	17.72	2005	0.82	13.38	105	196	Idle	90.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.84	15.42	1.05	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:0	17.72	1960	0.83	13.36	105	196	Idle	89.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.82	15.47	1.05	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:0	17.72	1960	0.83	13.35	105	196	Idle	89.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.79	15.53	1.06	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:0	17.72	1942	0.83	13.34	105	196	Idle	87.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.76	15.6	1.06	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:0	17.72	1896	0.84	13.34	105	196	Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.73	15.68	1.07	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:0	17.72	1896	0.85	13.35	105	196	Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.71	15.76	1.07	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:0	17.72	1887	0.86	13.36	105	196	Idle	84.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.7	15.86	1.08	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:1	17.72	1875	0.87	13.37	105	196	Idle	83.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.69	15.94	1.09	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:1	17.72	1867	0.88	13.37	105	196	Idle	81.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.66	15.99	1.09	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:1	17.72	1867	0.89	13.36	105	196	Idle	80.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.61	16.07	1.09	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:1	17.72	1866	0.9	13.36	105	196	Idle	79.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.55	16.11	1.1	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:1	17.72	1874	0.92	13.36	106	196	Idle	78.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.5	16.15	1.1	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:1	17.72	1886	0.93	13.37	106	196	Idle	78	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.44	16.18	1.1	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:1	17.72	1886	0.95	13.36	106	196	Idle	77.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	16.22	1.1	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:2	17.72	1896	0.96	13.36	105	196	Idle	76.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	16.26	1.11	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:2	17.72	1900	0.98	13.38	105	196	Idle	76.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	16.31	1.11	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:2	17.72	1900	0.99	13.38	105	196	Idle	77	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	16.35	1.11	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:2	17.72	1898	0.99	13.39	105	196	Idle	77.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	16.41	1.12	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:2	17.72	1887	1	13.39	105	196	Idle	77.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	16.44	1.12	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:2	17.72	1869	1	13.38	105	196	Idle	78.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	16.5	1.12	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:3	17.72	1869	1.01	13.37	105	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	16.57	1.13	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:3	17.72	1848	1.01	13.35	105	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	16.65	1.13	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:3	17.72	1823	1.01	13.35	105	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	16.73	1.14	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:3	17.72	1823	1.02	13.37	105	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	16.83	1.15	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:3	17.72	1808	1.02	13.37	105	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	16.99	1.16	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:3	17.72	1780	1.02	13.36	105	196	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	17.04	1.16	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:4	17.72	1782	1.01	13.36	105	196	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	17.23	1.17	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:4	17.72	1776	1.01	13.36	105	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	17.3	1.18	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:4	17.72	1763	1.01	13.35	105	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	17.55	1.2	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:4	17.72	1758	1.01	13.36	105	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	17.74	1.21	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:4	17.72	1758	1.01	13.37	105	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	17.96	1.22	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:4	17.72	1755	1	13.37	105	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	18.22	1.24	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:4	17.72	1755	1	13.35	105	196	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	18.65	1.27	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:5	17.72	1756	1	13.35	105	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	18.92	1.29	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:5	17.72	1756	1	13.36	105	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	19.05	1.3	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:16:5	17.72	1756	1	13.36	105	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	19.31	1.32	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:5	17.72	1754	1	13.35	105	196	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	19.53	1.33	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:5	17.72	1754	1	13.35	105	196	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	19.84	1.35	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:5	17.72	1749	1	13.36	105	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	19.92	1.36	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:6	17.72	1742	1	13.36	105	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.07	1.37	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:6	17.72	1737	1	13.36	105	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.16	1.37	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:6	17.72	1721	1	13.37	105	196	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.21	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:6	17.72	1709	1.01	13.38	105	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:6	17.72	1694	1.01	13.37	105	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.21	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:6	17.72	1690	1.01	13.36	105	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:6	17.72	1674	1.01	13.37	105	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:7	17.72	1666	1.01	13.37	105	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:7	17.72	1666	1.01	13.36	105	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:7	17.72	1660	1.01	13.37	105	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:7	17.72	1655	1.01	13.36	105	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:7	17.72	1652	1	13.35	105	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:7	17.72	1650	1	13.36	105	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:8	17.72	1648	1	13.36	105	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:8	17.72	1648	1	13.33	105	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:8	17.72	1648	1	13.35	105	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:8	17.72	1647	1	13.36	105	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.24	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:8	17.72	1641	0.99	13.35	105	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:8	17.72	1641	0.99	13.36	105	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:9	17.72	1636	0.99	13.37	105	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:9	17.72	1630	0.99	13.35	105	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:9	17.72	1630	0.99	13.36	105	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:9	17.72	1618	0.99	13.36	105	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.24	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:9	17.72	1614	0.99	13.36	105	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:9	17.72	1610	0.99	13.37	105	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:16:9	17.72	1598	0.99	13.37	105	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:0	17.72	1590	0.99	13.36	105	196	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:0	17.72	1585	0.99	13.36	105	196	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:0	17.72	1585	0.99	13.38	105	196	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:0	17.72	1580	0.99	13.37	105	196	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:0	17.72	1563	0.99	13.36	105	196	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:0	17.72	1563	0.99	13.36	105	196	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:1	17.72	1571	0.99	13.35	105	196	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:1	17.72	1568	0.98	13.36	105	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:1	17.72	1568	0.98	13.36	105	196	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:1	17.72	1565	0.98	13.37	105	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:1	17.72	1563	0.98	13.36	105	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:1	17.72	1560	0.98	13.36	105	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:1	17.72	1556	0.98	13.35	105	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:2	17.72	1549	0.98	13.35	105	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:2	17.72	1545	0.98	13.35	105	196	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:2	17.72	1545	0.97	13.36	105	196	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:2	17.72	1538	0.97	13.35	105	196	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:2	17.72	1532	0.97	13.36	105	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:2	17.72	1526	0.97	13.38	105	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:3	17.72	1526	0.97	13.38	105	196	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:3	17.72	1522	0.97	13.38	105	196	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:3	17.72	1518	0.97	13.38	105	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:3	17.72	1516	0.97	13.38	105	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:3	17.72	1513	0.97	13.37	105	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:3	17.72	1510	0.97	13.38	105	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.21	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:4	17.72	1508	0.97	13.38	105	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.21	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:4	17.72	1506	0.97	13.38	105	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:4	17.72	1500	0.97	13.37	105	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:17:4	17.72	1494	0.97	13.36	105	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:4	17.72	1494	0.97	13.37	105	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:4	17.72	1489	0.97	13.37	105	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:4	17.72	1483	0.96	13.36	105	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:5	17.72	1478	0.96	13.35	105	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:5	17.72	1470	0.96	13.37	105	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.21	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:5	17.72	1470	0.96	13.37	105	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:5	17.72	1467	0.96	13.37	105	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:5	17.72	1463	0.96	13.37	105	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.21	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:5	17.72	1471	0.96	13.38	105	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.21	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:6	17.72	1457	0.96	13.38	105	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.21	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:6	17.72	1457	0.96	13.37	105	195	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.21	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:6	17.72	1454	0.96	13.36	105	195	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.21	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:6	17.72	1440	0.96	13.36	105	195	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:6	17.72	1448	0.96	13.36	105	195	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:6	17.72	1448	0.96	13.36	105	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:6	17.72	1455	0.96	13.35	105	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:7	17.72	1427	0.96	13.35	105	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:7	17.72	1427	0.96	13.35	105	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:7	17.72	1431	0.95	13.35	105	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:7	19.09	1436	0.95	13.36	105	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.57	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:7	19.09	1418	0.95	13.36	105	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:7	19.09	1412	0.95	13.36	105	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.23	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:8	19.09	1412	0.95	13.35	105	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.57	20.23	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:8	19.09	1406	0.95	13.34	105	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:8	19.09	1402	0.95	13.35	105	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:8	19.09	1399	0.95	13.34	105	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:8	19.09	1399	0.95	13.35	105	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.22	1.38	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:8	19.09	1390	0.95	13.36	105	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:9	19.09	1375	0.95	13.36	105	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	4.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:9	19.09	1375	0.95	13.36	105	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.22	1.38	4.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:9	19.09	1354	0.95	13.35	105	196	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.22	1.38	4.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:9	19.09	1309	0.95	13.34	105	196	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.44	20.22	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:9	16.36	1291	0.95	13.36	106	196	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	20.22	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:9	16.36	1291	0.95	13.36	106	196	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.4	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:17:9	16.36	1274	0.95	13.37	105	196	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	20.22	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:18:0	16.36	1234	0.95	13.37	105	196	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.3	20.22	1.38	4.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:18:0	16.36	1234	0.95	13.38	105	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.26	20.22	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:18:0	16.36	1234	0.96	13.36	105	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	20.22	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:18:0	16.36	1195	0.96	13.37	105	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:0	14.99	1186	0.96	13.38	105	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	20.22	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:0	14.99	1186	0.96	13.38	105	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:1	14.99	1147	0.97	13.37	105	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:1	14.99	1138	0.97	13.37	105	195	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.87	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:1	14.99	1138	0.98	13.37	105	195	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.7	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:1	14.99	1122	0.99	13.37	105	195	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	20.21	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:1	14.99	1117	0.99	13.38	105	195	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.53	20.21	1.38	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:1	14.99	1117	1	13.37	105	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.44	20.22	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:1	14.99	1118	1	13.36	105	195	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.41	20.22	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:2	14.99	1124	1.01	13.37	105	195	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.37	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:2	14.99	1131	1.01	13.37	105	195	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.34	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:2	14.99	1131	1.02	13.37	105	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.31	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:2	14.99	1132	1.02	13.36	105	195	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.28	20.23	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:2	13.63	1133	1.02	13.35	105	195	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.26	20.23	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:2	13.63	1133	1.02	13.36	105	195	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.21	20.23	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:3	13.63	1134	1.02	13.35	105	195	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.2	20.23	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:3	13.63	1130	1.03	13.37	105	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.21	20.23	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:3	13.63	1130	1.02	13.35	105	195	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.21	20.23	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:18:3	13.63	1130	1.02	13.34	105	195	Idle	82.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.26	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:3	13.63	1130	1.02	13.36	105	195	Idle	83.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.23	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:3	13.63	1132	1.02	13.34	105	195	Idle	84	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.28	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:4	13.63	1135	1.01	13.35	105	196	Idle	84.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.31	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:4	13.63	1136	1	13.36	105	196	Idle	85.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.27	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:4	13.63	1136	1	13.36	105	196	Idle	85.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.3	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:4	13.63	1128	0.99	13.37	105	195	Idle	86.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.31	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:4	13.63	1111	0.98	13.35	105	195	Idle	86.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.31	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:4	13.63	1112	0.98	13.37	105	195	Idle	87.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.33	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:4	12.27	1112	0.97	13.36	105	196	Idle	87.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.36	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:5	12.27	1093	0.96	13.35	105	196	Idle	87.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.39	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:5	12.27	1088	0.95	13.35	105	195	Idle	87.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.39	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:5	12.27	1083	0.94	13.35	105	195	Idle	87.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.41	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:5	12.27	1083	0.94	13.37	105	195	Idle	88.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.41	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:5	12.27	1068	0.93	13.35	105	195	Idle	88.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.37	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:5	12.27	1073	0.93	13.34	105	195	Idle	88.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.38	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:6	12.27	1073	0.93	13.36	105	195	Idle	88.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.33	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:6	12.27	1067	0.92	13.35	105	195	Idle	89.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.34	20.22	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:6	12.27	1061	0.92	13.37	105	195	Idle	89.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.31	20.21	1.38	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:6	10.9	1050	0.91	13.36	105	195	Idle	89.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.34	20.21	1.38	5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:6	10.9	1042	0.91	13.38	105	196	Idle	89.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.34	20.21	1.38	5	2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:6	10.9	1044	0.91	13.35	105	196	Idle	89.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.32	20.21	1.38	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:6	10.9	1044	0.91	13.37	105	196	Idle	90.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.33	20.21	1.38	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:7	10.9	1036	0.9	13.36	105	195	Idle	90.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.31	20.21	1.38	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:7	10.9	1039	0.9	13.37	105	195	Idle	90.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.32	20.21	1.38	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:7	10.9	1039	0.9	13.36	105	195	Idle	90.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.28	20.21	1.38	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:7	10.9	1034	0.9	13.38	105	195	Idle	91	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.32	20.21	1.38	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:7	10.9	1028	0.89	13.37	105	195	Idle	91.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.3	20.22	1.38	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:7	10.9	1028	0.89	13.36	105	195	Idle	91.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.33	20.21	1.38	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:8	10.9	1019	0.89	13.38	105	195	Idle	91.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.31	20.13	1.37	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:8	10.9	1006	0.89	13.35	105	195	Idle	91.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.32	19.98	1.36	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:8	10.9	1005	0.89	13.36	105	195	Idle	91.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.31	19.88	1.35	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:8	10.9	1004	0.88	13.36	105	195	Idle	91.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.24	19.49	1.33	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:8	10.9	1004	0.88	13.37	105	195	Idle	91	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.27	19.18	1.31	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:8	10.9	985	0.88	13.36	105	195	Idle	90.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.2	18.84	1.28	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:9	10.9	978	0.88	13.37	105	195	Idle	90.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.21	18.49	1.26	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:9	10.9	971	0.88	13.35	106	195	Idle	90.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.13	18.11	1.23	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:9	10.9	971	0.87	13.36	106	195	Idle	90.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.13	17.71	1.21	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:9	9.54	960	0.87	13.34	106	195	Idle	90.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.11	17.31	1.18	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:9	9.54	957	0.87	13.36	106	195	Idle	89.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.07	16.98	1.16	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:9	9.54	957	0.87	13.36	105	196	Idle	89.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.05	16.59	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:18:9	9.54	957	0.87	13.37	105	196	Idle	89.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.08	16.4	1.12	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:0	9.54	943	0.87	13.37	105	196	Idle	89.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.05	16.25	1.11	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:0	9.54	943	0.87	13.37	105	196	Idle	89.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.06	16.14	1.1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:0	9.54	940	0.87	13.37	105	195	Idle	89.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.02	16.05	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:0	9.54	937	0.87	13.37	105	195	Idle	89.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.01	15.93	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:0	9.54	936	0.87	13.36	106	195	Idle	90.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.95	15.88	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:0	9.54	936	0.87	13.37	106	195	Idle	90.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.97	15.84	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:1	9.54	926	0.87	13.36	106	195	Idle	90.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.9	15.81	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:1	9.54	926	0.87	13.37	106	195	Idle	90.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.92	15.78	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:1	9.54	925	0.87	13.35	106	195	Idle	91.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.89	15.77	1.07	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:1	9.54	925	0.87	13.37	106	195	Idle	91.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.89	15.77	1.07	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:1	9.54	931	0.86	13.35	106	195	Idle	91.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.87	15.75	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:1	9.54	931	0.86	13.37	106	195	Idle	92	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.88	15.74	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:1	8.18	920	0.86	13.35	106	195	Idle	92.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.85	15.73	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:2	8.18	908	0.86	13.37	105	195	Idle	92.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.84	15.72	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:2	8.18	928	0.86	13.35	105	195	Idle	92.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.85	15.71	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:2	8.18	928	0.86	13.36	105	195	Idle	93.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.83	15.7	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:19:2	8.18	924	0.86	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	15.69	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:2	8.18	919	0.85	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.81	15.68	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:2	8.18	921	0.85	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.8	15.66	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:3	8.18	921	0.85	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.81	15.65	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:3	9.54	929	0.85	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.82	15.63	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:3	9.54	929	0.85	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.8	15.63	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:3	9.54	929	0.84	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.82	15.61	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:3	9.54	908	0.84	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.8	15.6	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:3	8.18	913	0.84	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.83	15.58	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:4	8.18	913	0.84	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.8	15.55	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:4	8.18	916	0.83	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.82	15.52	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:4	8.18	919	0.83	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	15.51	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:4	8.18	927	0.83	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.81	15.49	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:4	9.54	927	0.83	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15.47	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:4	9.54	924	0.83	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.8	15.43	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:4	9.54	920	0.83	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15.41	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:5	9.54	920	0.83	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	15.39	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:5	9.54	912	0.83	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	15.37	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:5	9.54	909	0.82	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	15.35	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:5	9.54	909	0.82	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.34	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:5	9.54	909	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.32	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:5	8.18	921	0.82	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15.3	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:6	8.18	921	0.82	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.83	15.29	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:6	8.18	902	0.82	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15.28	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:6	8.18	906	0.82	13.39	105	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:6	8.18	909	0.82	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:6	8.18	909	0.82	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.24	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:6	8.18	900	0.82	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:6	8.18	900	0.82	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.19	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:7	8.18	902	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:7	8.18	904	0.82	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:7	8.18	905	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:7	8.18	905	0.82	13.39	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:7	8.18	900	0.81	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:7	8.18	896	0.81	13.39	105	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:8	8.18	908	0.81	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:8	8.18	908	0.81	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:8	8.18	906	0.81	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:8	8.18	903	0.81	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:8	8.18	903	0.81	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:8	8.18	899	0.81	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.73	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:19:9	8.18	899	0.81	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.76	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:19:9	8.18	905	0.81	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.78	14.97	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:19:9	8.18	878	0.81	13.39	105	195	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.79	14.97	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:19:9	8.18	878	0.81	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.76	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:9	8.18	878	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.77	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:9	9.54	890	0.81	13.36	106	195	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.73	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:19:9	9.54	863	0.81	13.35	105	195	Idle	93.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.75	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:0	9.54	863	0.81	13.35	105	195	Idle	93	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:0	9.54	863	0.81	13.38	105	195	Idle	93	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:0	8.18	867	0.81	13.36	105	195	Idle	93	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:0	8.18	867	0.81	13.38	105	195	Idle	93	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:0	8.18	888	0.81	13.37	105	195	Idle	93	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:0	8.18	888	0.81	13.37	106	195	Idle	93	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:1	8.18	888	0.81	13.34	106	195	Idle	93	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.94	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:1	8.18	875	0.8	13.36	106	195	Idle	93	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:1	8.18	881	0.8	13.35	105	195	Idle	93	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:1	8.18	881	0.8	13.36	105	195	Idle	93	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:20:1	8.18	881	0.8	13.36	105	195	Idle	93	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:1	8.18	869	0.8	13.36	106	195	Idle	93	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:1	8.18	869	0.8	13.36	106	195	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:2	8.18	892	0.8	13.35	106	195	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:2	8.18	892	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:2	9.54	887	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.82	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:2	9.54	887	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:2	9.54	887	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:2	9.54	880	0.8	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:3	9.54	889	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:3	9.54	889	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.89	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:3	9.54	889	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:3	9.54	863	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:3	9.54	878	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:3	9.54	878	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	15.03	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:4	9.54	878	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.64	15.06	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:4	9.54	878	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.62	15.07	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:4	9.54	878	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	15.08	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:4	6.81	871	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.63	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:4	6.81	864	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.66	15.11	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:4	6.81	884	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.66	15.13	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:4	6.81	884	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.67	15.14	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:5	9.54	892	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.63	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:5	9.54	900	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.61	15.14	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:5	9.54	868	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.62	15.16	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:20:5	9.54	868	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.6	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:5	8.18	870	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.64	15.19	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:5	8.18	873	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.64	15.18	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:6	8.18	873	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.66	15.19	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:6	8.18	908	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.63	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:6	8.18	896	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	15.19	1.04	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:6	8.18	884	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.59	15.19	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:6	8.18	884	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.64	15.19	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:6	8.18	899	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.62	15.19	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:6	8.18	899	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	15.19	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:7	8.18	899	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:7	8.18	899	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.16	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:7	8.18	882	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.16	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:7	8.18	882	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.14	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:20:7	8.18	884	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	15.12	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:20:7	8.18	886	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.12	1.03	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:20:8	8.18	897	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.11	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:20:8	8.18	897	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:8	9.54	882	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:8	9.54	867	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:8	9.54	862	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:8	9.54	862	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:9	9.54	862	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:9	9.54	867	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:9	9.54	867	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:9	9.54	861	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:9	9.54	861	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:9	9.54	861	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.64	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:20:9	9.54	858	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.62	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:0	9.54	861	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.64	14.99	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:0	9.54	861	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.6	15	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:0	9.54	861	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.6	15.01	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:0	9.54	857	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.6	15.01	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:21:0	9.54	860	0.79	13.35	105	195	Idle	93.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.59	15	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:0	9.54	860	0.79	13.33	105	195	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.58	15	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:1	9.54	863	0.79	13.35	105	195	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.59	14.99	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:1	10.9	844	0.79	13.34	105	195	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.56	14.98	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:1	10.9	844	0.79	13.37	105	195	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:1	10.9	853	0.79	13.36	105	195	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.57	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:1	10.9	862	0.79	13.37	105	195	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.56	14.92	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:1	10.9	870	0.79	13.37	105	195	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.57	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:1	9.54	870	0.79	13.36	106	195	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.56	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:2	9.54	870	0.79	13.35	106	195	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:21:2	9.54	878	0.8	13.37	106	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.56	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:2	9.54	864	0.8	13.37	106	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.6	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:2	8.18	864	0.8	13.37	106	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.57	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:2	8.18	864	0.8	13.38	106	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.58	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:2	8.18	887	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.57	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:3	8.18	887	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.58	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:3	8.18	882	0.8	13.35	106	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.59	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:3	8.18	882	0.8	13.36	106	195	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:3	8.18	895	0.8	13.34	106	195	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:3	8.18	895	0.8	13.36	106	195	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:3	8.18	888	0.8	13.35	105	195	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:4	8.18	882	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:4	8.18	883	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.61	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:4	8.18	883	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.59	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:4	8.18	883	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.94	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:4	9.54	895	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.58	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:4	9.54	884	0.8	13.35	105	195	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.62	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:4	9.54	884	0.8	13.35	105	195	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.63	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:5	9.54	884	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.65	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:5	8.18	880	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.62	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:5	8.18	877	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.65	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:5	8.18	877	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.62	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:5	8.18	877	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.64	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:5	10.9	892	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.61	15.19	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:6	10.9	892	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.62	15.21	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:6	10.9	887	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.64	15.22	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:6	10.9	887	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.63	15.25	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:6	9.54	887	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.64	15.25	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:6	9.54	895	0.8	13.39	106	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.62	15.26	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:6	9.54	901	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.62	15.26	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:6	9.54	901	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.6	15.27	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:7	9.54	901	0.8	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.64	15.28	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:7	9.54	888	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.61	15.28	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:7	9.54	904	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.67	15.27	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:7	9.54	904	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.65	15.27	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:7	9.54	904	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.69	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:7	9.54	899	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.65	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:8	9.54	899	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	15.23	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:8	9.54	895	0.79	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.68	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:8	9.54	895	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	15.19	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:8	8.18	904	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:8	8.18	904	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.72	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:8	8.18	902	0.79	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.7	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:9	8.18	901	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.72	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:9	8.18	892	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:9	8.18	892	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:9	8.18	884	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	15.07	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:9	8.18	877	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	15.07	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:21:9	9.54	900	0.79	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:21:9	9.54	900	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:0	9.54	898	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:0	9.54	895	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:0	8.18	882	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:0	8.18	882	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:0	8.18	882	0.79	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:0	8.18	898	0.79	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:1	8.18	893	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:1	8.18	893	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:1	8.18	893	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:1	8.18	893	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:1	8.18	890	0.79	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:1	9.54	902	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:1	9.54	902	0.79	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:2	9.54	884	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:2	9.54	884	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:2	8.18	892	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:2	8.18	899	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:2	8.18	890	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:2	8.18	890	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:3	8.18	892	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	15.06	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:3	8.18	895	0.79	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:3	8.18	895	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:3	8.18	903	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:3	8.18	893	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.73	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:3	8.18	893	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.68	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:4	8.18	893	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:4	8.18	915	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.71	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:4	8.18	915	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.7	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:4	8.18	887	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.73	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:4	8.18	887	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.73	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:4	8.18	894	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.78	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:4	8.18	900	0.79	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:5	8.18	896	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.75	15.09	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:5	8.18	896	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	15.09	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:5	8.18	904	0.79	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	15.09	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:5	8.18	912	0.79	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:5	8.18	902	0.79	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:5	8.18	902	0.79	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:6	8.18	902	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:6	8.18	902	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:6	8.18	912	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:6	8.18	912	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:6	8.18	903	0.79	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:6	8.18	894	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:6	8.18	894	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:7	8.18	889	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:7	8.18	889	0.79	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:7	8.18	889	0.79	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:7	8.18	889	0.79	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:7	8.18	890	0.79	13.33	105	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:7	8.18	890	0.79	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:8	8.18	884	0.79	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:8	8.18	884	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:8	9.54	873	0.79	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:8	9.54	873	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:8	9.54	873	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:22:8	9.54	873	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:9	9.54	873	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:9	9.54	885	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:9	9.54	879	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:9	9.54	879	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:9	9.54	879	0.79	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:9	8.18	870	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.68	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:22:9	8.18	870	0.79	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:0	8.18	880	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.65	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:0	8.18	880	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.66	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:0	9.54	883	0.79	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:0	9.54	883	0.79	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.65	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:0	9.54	881	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.66	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:0	9.54	879	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.66	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:1	9.54	879	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.67	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:1	9.54	868	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.62	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:1	9.54	864	0.79	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.66	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:1	9.54	860	0.79	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.62	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:1	9.54	878	0.79	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.65	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:1	8.18	895	0.79	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.6	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:1	8.18	895	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.64	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:2	8.18	880	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.62	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:2	8.18	880	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.64	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:2	6.81	880	0.79	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.6	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:2	6.81	881	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.62	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:2	6.81	894	0.79	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.61	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:2	6.81	894	0.79	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:3	9.54	898	0.79	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.62	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:3	9.54	903	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:3	9.54	882	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:3	9.54	882	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:3	9.54	884	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:3	9.54	885	0.79	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.6	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:4	9.54	885	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.61	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:4	9.54	881	0.79	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:4	9.54	884	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.62	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:4	9.54	886	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.59	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:4	9.54	886	0.79	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.61	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:4	9.54	902	0.79	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.6	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:4	9.54	902	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.63	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:5	9.54	896	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.59	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:5	9.54	891	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.61	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:5	9.54	891	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:5	9.54	891	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.6	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:5	9.54	892	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:5	9.54	893	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:6	9.54	891	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:6	9.54	891	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:6	9.54	890	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:6	10.9	890	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:6	10.9	890	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:6	10.9	878	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:6	10.9	892	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:7	9.54	905	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:7	9.54	905	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:7	9.54	893	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:7	9.54	893	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:7	10.9	891	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:23:7	10.9	891	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:8	10.9	898	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:8	10.9	898	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.69	14.85	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:8	9.54	883	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:8	9.54	883	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.67	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:8	9.54	883	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.68	14.85	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:23:8	9.54	906	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.68	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:9	9.54	912	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.73	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:9	9.54	912	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:9	9.54	912	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.74	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:9	9.54	911	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.72	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:9	6.81	906	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.72	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:9	6.81	906	0.8	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:23:9	6.81	906	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.73	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:0	6.81	912	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.7	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:0	6.81	891	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.74	14.86	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:0	8.18	891	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:0	8.18	891	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.86	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:0	8.18	898	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:0	8.18	898	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.73	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:1	8.18	898	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.72	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:1	8.18	898	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:1	8.18	904	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.72	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:1	8.18	904	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:1	8.18	915	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.8	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:1	8.18	915	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	14.79	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:1	8.18	904	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	14.81	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:2	8.18	893	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.81	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:2	8.18	892	0.8	13.32	105	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:2	8.18	892	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:2	8.18	894	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:2	8.18	894	0.8	13.32	106	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.71	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:2	9.54	894	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.77	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:3	9.54	888	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.7	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:3	9.54	879	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.72	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:3	9.54	879	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.7	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:3	9.54	870	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.72	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:3	8.18	892	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:3	8.18	892	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	14.97	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:4	8.18	895	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:4	8.18	898	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:4	6.81	895	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:4	6.81	895	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:4	6.81	888	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:4	6.81	880	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:4	6.81	888	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:5	6.81	888	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:5	6.81	886	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:5	6.81	884	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:5	6.81	884	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:5	6.81	867	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:5	6.81	872	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:6	6.81	876	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:6	6.81	876	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:6	6.81	870	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:6	6.81	870	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:6	6.81	877	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:6	6.81	884	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.62	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:24:6	8.18	872	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:7	8.18	872	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:7	8.18	866	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:7	8.18	860	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:7	8.18	878	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:7	8.18	878	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:7	8.18	878	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:8	8.18	887	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:8	8.18	887	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:8	9.54	879	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:8	9.54	879	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:8	9.54	878	0.8	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.63	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:8	9.54	877	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.66	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:9	9.54	879	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.63	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:9	9.54	879	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.65	14.9	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:9	9.54	882	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.65	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:9	9.54	884	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.63	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:9	9.54	872	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.65	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:9	9.54	872	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.59	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:24:9	9.54	872	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.6	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:0	9.54	860	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.59	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:0	9.54	860	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.61	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:0	9.54	880	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.57	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:0	9.54	867	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.61	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:0	9.54	854	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.59	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:0	9.54	854	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.6	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:1	8.18	865	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.6	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:1	8.18	865	0.8	13.38	105	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:1	8.18	865	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:1	8.18	871	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.57	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:1	8.18	877	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:1	8.18	877	0.8	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.56	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:1	8.18	877	0.8	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.57	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:2	8.18	869	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:2	8.18	869	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:2	8.18	878	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.55	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:2	8.18	878	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:2	8.18	875	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.55	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:2	8.18	872	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:3	6.81	885	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.83	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:3	6.81	885	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	14.83	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:3	6.81	891	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.59	14.81	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:3	6.81	897	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:3	6.81	875	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.62	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:3	8.18	875	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.61	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:4	8.18	880	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.65	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:4	8.18	884	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.61	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:4	6.81	905	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.66	14.9	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:4	6.81	905	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.58	14.92	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:4	6.81	906	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.58	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:25:4	6.81	908	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.59	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:4	6.81	908	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.58	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:5	8.18	904	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.58	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:5	8.18	908	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.64	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:5	8.18	913	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.6	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:5	8.18	913	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:5	8.18	925	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:5	8.18	925	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:25:6	8.18	925	0.8	13.33	105	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:6	8.18	925	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:6	6.81	918	0.8	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:6	6.81	918	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:6	6.81	926	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:6	6.81	926	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:6	6.81	921	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:7	6.81	921	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15.1	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:7	6.81	910	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	15.09	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:7	6.81	910	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	15.09	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:7	8.18	910	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.82	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:7	8.18	912	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:7	8.18	906	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	15.05	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:8	8.18	906	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:8	8.18	906	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:8	8.18	898	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:8	8.18	902	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:8	8.18	902	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:8	8.18	902	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:9	8.18	895	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:9	8.18	901	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:9	8.18	901	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:9	8.18	901	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:9	8.18	896	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:9	8.18	896	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:25:9	8.18	882	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:0	8.18	882	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:0	8.18	875	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:0	8.18	875	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:0	8.18	910	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:0	8.18	910	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.7	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:0	9.54	894	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:1	9.54	878	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.72	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:1	9.54	888	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.76	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:1	9.54	898	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.72	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:1	9.54	896	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.75	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:1	9.54	896	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.71	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:1	9.54	904	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.76	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:1	9.54	911	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.72	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:2	9.54	911	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.76	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:2	9.54	912	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.74	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:2	9.54	912	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.77	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:2	9.54	915	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.73	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:2	9.54	899	0.8	13.36	105	195	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.79	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:2	8.18	899	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.76	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:3	8.18	899	0.8	13.37	105	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.78	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:3	8.18	902	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.75	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:3	8.18	902	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.75	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:3	8.18	892	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.71	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:3	8.18	892	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.77	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:3	8.18	896	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:4	8.18	896	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.76	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:4	9.54	908	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.77	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:4	9.54	908	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.74	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:4	9.54	896	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:4	9.54	885	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:4	9.54	885	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:4	8.18	906	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:26:5	8.18	906	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.74	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:5	8.18	906	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.71	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:5	8.18	906	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.75	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:5	8.18	909	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.75	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:5	8.18	904	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.77	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:5	8.18	898	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.73	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:6	8.18	898	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.75	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:6	8.18	906	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.74	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:6	8.18	906	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.77	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:6	8.18	908	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.76	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:6	8.18	909	0.8	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.78	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:6	8.18	909	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.75	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:6	8.18	888	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:7	8.18	901	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:7	8.18	901	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:7	8.18	904	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:7	8.18	907	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:7	8.18	914	0.8	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:7	8.18	914	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:8	6.81	903	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:8	6.81	892	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:8	6.81	910	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:8	6.81	910	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:8	6.81	898	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:8	8.18	885	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:9	8.18	885	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:9	8.18	895	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:9	8.18	894	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:9	9.54	892	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:9	9.54	892	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:9	9.54	883	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:26:9	9.54	883	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:0	8.18	898	0.8	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:0	8.18	898	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:0	8.18	898	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:0	8.18	898	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:0	8.18	896	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:0	8.18	895	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:1	8.18	906	0.8	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:1	8.18	906	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:1	8.18	906	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:1	8.18	897	0.8	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:1	8.18	901	0.8	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:1	8.18	901	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:1	8.18	901	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:2	8.18	894	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:2	8.18	900	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:2	8.18	900	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:2	8.18	908	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:2	8.18	917	0.81	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:2	8.18	917	0.81	13.34	105	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:3	8.18	903	0.81	13.35	105	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:3	8.18	903	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:3	8.18	903	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:3	8.18	903	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:3	8.18	907	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:3	8.18	907	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:4	8.18	912	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:27:4	8.18	912	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.63	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:4	8.18	912	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:4	8.18	906	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:4	8.18	894	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:4	8.18	894	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:4	8.18	894	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:5	8.18	896	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:5	8.18	904	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:5	8.18	904	0.82	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:5	8.18	906	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:5	8.18	907	0.82	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:5	8.18	906	0.82	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:6	8.18	906	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:6	8.18	908	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:6	8.18	909	0.82	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:6	8.18	909	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:6	8.18	906	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:6	8.18	906	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:6	8.18	902	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:7	8.18	902	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:7	9.54	914	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:7	9.54	914	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.89	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:7	9.54	914	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.91	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:7	9.54	889	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.67	14.91	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:7	8.18	903	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.68	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:8	8.18	903	0.82	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.67	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:8	8.18	903	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	14.91	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:27:8	8.18	906	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	14.91	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:27:8	8.18	903	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.72	14.9	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:27:8	8.18	903	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.68	14.9	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:27:8	8.18	896	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.73	14.88	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:27:9	8.18	888	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.68	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:9	8.18	888	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:9	8.18	892	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:9	8.18	892	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.72	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:9	8.18	886	0.82	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.67	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:9	8.18	886	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:27:9	8.18	870	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.65	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:0	8.18	870	0.82	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.62	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:0	8.18	870	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.6	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:0	8.18	870	0.82	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.62	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:0	9.54	875	0.82	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.59	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:0	9.54	875	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.6	14.92	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:0	9.54	875	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.63	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:1	9.54	868	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	14.9	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:28:1	9.54	890	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.61	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:28:1	9.54	890	0.81	13.32	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.62	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:28:1	9.54	890	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.64	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:28:1	9.54	878	0.81	13.32	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.61	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:1	9.54	878	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:1	8.18	884	0.81	13.32	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.86	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:2	8.18	890	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:2	8.18	900	0.81	13.32	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.87	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:2	8.18	910	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:2	8.18	912	0.81	13.32	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:2	8.18	912	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:2	8.18	908	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:3	8.18	904	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:28:3	8.18	917	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:3	8.18	917	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:3	8.18	920	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.68	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:3	8.18	922	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.66	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:3	8.18	929	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.72	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:4	8.18	929	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:4	8.18	919	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.76	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:4	8.18	909	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.75	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:4	6.81	922	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.74	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:4	6.81	922	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.72	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:4	6.81	927	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.76	15.05	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:28:4	6.81	927	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.72	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:28:5	6.81	927	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.76	15.09	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:28:5	8.18	891	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.72	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:28:5	8.18	901	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.79	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:28:5	8.18	901	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.73	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:5	8.18	901	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.75	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:5	8.18	899	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:6	8.18	901	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:6	8.18	901	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:6	8.18	901	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	15.09	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:6	8.18	881	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:6	8.18	881	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:6	8.18	890	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:6	8.18	898	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:7	8.18	891	0.81	13.32	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:7	8.18	891	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:7	8.18	893	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:7	8.18	893	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:7	8.18	898	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.06	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:7	8.18	901	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.05	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:8	8.18	912	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.04	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:8	8.18	912	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:8	8.18	913	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:8	8.18	914	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:8	8.18	897	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.72	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:8	8.18	897	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:9	8.18	896	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.73	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:9	8.18	895	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.7	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:9	8.18	895	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.73	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:9	8.18	891	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.71	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:9	8.18	891	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.74	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:9	8.18	892	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.73	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:28:9	8.18	892	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.72	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:0	8.18	896	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.75	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:0	8.18	901	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.72	14.93	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:0	8.18	906	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	14.9	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:0	8.18	906	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.72	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:0	8.18	903	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:0	8.18	900	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:1	8.18	896	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.73	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:1	8.18	896	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.71	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:1	8.18	892	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.74	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:1	8.18	888	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.73	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:1	8.18	888	0.81	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.74	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:1	8.18	880	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:1	8.18	880	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:2	8.18	884	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:29:2	8.18	889	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:2	8.18	896	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.68	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:2	8.18	896	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.71	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:2	8.18	894	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.69	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:2	8.18	892	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:3	8.18	883	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:3	8.18	883	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:3	8.18	889	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:3	8.18	895	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:3	8.18	896	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:3	8.18	896	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.66	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:4	8.18	898	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:4	8.18	899	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:4	8.18	915	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:4	8.18	915	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:4	8.18	906	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:4	8.18	896	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.7	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:4	8.18	896	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.76	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:5	8.18	906	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:5	8.18	906	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.71	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:5	8.18	906	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.7	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:5	8.18	905	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.7	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:5	8.18	897	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.67	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:5	8.18	901	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.7	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:6	8.18	901	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:6	8.18	901	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:6	6.81	899	0.81	13.33	106	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:6	6.81	899	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.73	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:6	6.81	914	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.74	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:6	6.81	914	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:6	8.18	914	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	14.98	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:7	8.18	889	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:7	8.18	888	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:7	8.18	888	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:7	8.18	892	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:7	8.18	897	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:7	8.18	897	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:8	8.18	904	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:8	8.18	904	0.81	13.35	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:8	8.18	886	0.81	13.34	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:8	8.18	886	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:8	8.18	895	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:8	8.18	895	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:9	8.18	896	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:9	8.18	898	0.81	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:9	8.18	900	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:9	8.18	900	0.81	13.39	106	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:9	9.54	889	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.95	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:9	9.54	878	0.81	13.39	106	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:29:9	9.54	896	0.81	13.39	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:0	9.54	896	0.81	13.39	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:0	9.54	900	0.81	13.39	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:0	10.9	905	0.81	13.39	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.64	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:0	10.9	905	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:0	10.9	904	0.81	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:0	10.9	904	0.81	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:1	9.54	899	0.81	13.36	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:1	9.54	904	0.81	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:30:1	9.54	909	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.95	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:1	9.54	909	0.81	13.39	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	14.94	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:1	9.54	919	0.81	13.37	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	14.92	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:1	9.54	919	0.81	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	14.9	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:1	9.54	912	0.81	13.39	106	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.88	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:2	9.54	905	0.81	13.4	106	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:2	9.54	901	0.81	13.38	106	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:2	9.54	901	0.81	13.4	106	195	Full Load	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:2	9.54	907	0.81	13.39	106	195	Off Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:2	9.54	913	0.82	13.4	106	195	Off Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:2	8.18	898	0.82	13.38	106	195	Off Idle	92.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.68	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:3	8.18	898	0.84	13.4	106	195	Off Idle	92.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.6	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:3	8.18	899	0.86	13.38	106	195	Off Idle	91.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.54	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:3	8.18	900	0.88	13.41	106	195	Off Idle	91.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.36	14.84	1.01	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:30:3	8.18	899	0.91	13.39	106	195	Off Idle	90.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.18	14.85	1.01	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:30:3	8.18	899	0.94	13.41	106	195	Off Idle	89.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7	14.86	1.01	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:30:3	8.18	886	0.97	13.4	106	195	Off Idle	89.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.85	14.86	1.01	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:30:4	8.18	886	1	13.39	106	195	Off Idle	88.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.62	14.86	1.01	4.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:30:4	8.18	886	1.03	13.39	106	195	Off Idle	88.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.44	14.85	1.01	4.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:30:4	8.18	889	1.06	13.37	106	195	Off Idle	87.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.21	14.85	1.01	4.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:30:4	8.18	889	1.09	13.38	106	195	Off Idle	87.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.04	14.86	1.01	4.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:30:4	8.18	889	1.14	13.39	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.81	14.87	1.01	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:30:4	8.18	889	1.16	13.41	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.64	14.87	1.01	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:30:4	8.18	888	1.2	13.41	106	195	Off Idle	85.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.45	14.87	1.01	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:30:5	8.18	888	1.23	13.41	106	195	Off Idle	84.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.24	14.87	1.01	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:30:5	8.18	925	1.28	13.4	106	195	Off Idle	84.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.99	14.87	1.01	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:5	8.18	925	1.32	13.42	106	195	Off Idle	84.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.9	14.87	1.01	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:5	20.45	1014	1.35	13.39	106	195	Off Idle	84.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.75	14.88	1.01	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:5	20.45	997	1.38	13.41	106	195	Off Idle	84.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.69	14.87	1.01	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:30:5	20.45	997	1.41	13.4	106	195	Off Idle	84.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.55	14.86	1.01	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:6	20.45	1022	1.43	13.42	106	195	Off Idle	84.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.54	14.85	1.01	4.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:6	20.45	1048	1.45	13.41	106	195	Off Idle	85	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.44	14.85	1.01	4.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:6	20.45	1070	1.47	13.4	106	195	Off Idle	85.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.44	14.84	1.01	4.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:30:6	20.45	1091	1.48	13.4	106	195	Off Idle	85.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-4.44	14.84	1.01	4.3	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:30:6	20.45	1119	1.49	13.4	106	195	Off Idle	85.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.41	14.85	1.01	4.2	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:30:6	20.45	1160	1.49	13.4	106	195	Off Idle	85.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.43	14.83	1.01	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:30:6	20.45	1160	1.5	13.39	106	195	Off Idle	85.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.43	14.84	1.01	4.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:30:7	21.81	1172	1.5	13.39	106	195	Off Idle	85.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.43	14.84	1.01	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:30:7	21.81	1192	1.5	13.39	106	195	Off Idle	85.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.42	14.86	1.01	4.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:30:7	21.81	1192	1.51	13.39	106	195	Off Idle	85.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.46	14.89	1.01	4.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:30:7	21.81	1200	1.51	13.39	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.48	14.93	1.02	4.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:30:7	21.81	1200	1.51	13.4	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.51	14.97	1.02	4.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:30:7	21.81	1206	1.51	13.39	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.56	14.99	1.02	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:8	21.81	1216	1.52	13.39	106	195	Off Idle	86	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.61	15.01	1.02	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:8	21.81	1218	1.52	13.39	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.66	15.05	1.02	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:8	21.81	1220	1.52	13.38	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.68	15.11	1.03	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:8	21.81	1224	1.52	13.38	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.7	15.09	1.03	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:8	21.81	1225	1.52	13.39	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.74	15.05	1.03	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:8	21.81	1226	1.53	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.74	14.97	1.02	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:9	21.81	1226	1.53	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.78	14.85	1.01	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:9	23.18	1230	1.53	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.77	14.79	1.01	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:9	23.18	1228	1.54	13.38	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.77	14.56	0.99	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:9	23.18	1228	1.54	13.38	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.73	14.3	0.97	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:9	23.18	1224	1.55	13.38	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.7	14.07	0.96	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:30:9	23.18	1221	1.56	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.68	13.85	0.94	4.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:30:9	23.18	1221	1.57	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.63	13.64	0.93	4.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:31:0	23.18	1213	1.58	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.55	13.36	0.91	4.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:31:0	23.18	1212	1.59	13.37	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.49	13.19	0.9	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:31:0	23.18	1212	1.6	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.37	13.05	0.89	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:0	23.18	1213	1.61	13.4	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.3	12.94	0.88	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:0	23.18	1213	1.62	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.23	12.85	0.88	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:0	23.18	1201	1.64	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.1	12.76	0.87	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:31:1	21.81	1199	1.65	13.4	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.07	12.72	0.87	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:31:1	21.81	1222	1.66	13.4	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.04	12.72	0.87	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:31:1	21.81	1222	1.66	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.01	12.72	0.87	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:31:1	23.18	1228	1.67	13.4	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.98	12.74	0.87	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:31:1	23.18	1222	1.68	13.4	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.98	12.77	0.87	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:31:1	23.18	1222	1.69	13.38	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.93	12.83	0.87	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:31:1	21.81	1215	1.7	13.38	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.88	12.92	0.88	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:31:2	21.81	1215	1.7	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.84	12.97	0.88	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:31:2	21.81	1237	1.71	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.85	13.05	0.89	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:2	21.81	1212	1.71	13.38	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.85	13.18	0.9	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:2	21.81	1238	1.72	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.84	13.27	0.9	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:2	21.81	1238	1.72	13.38	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.86	13.34	0.91	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:2	23.18	1224	1.72	13.37	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.87	13.42	0.91	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:3	23.18	1224	1.71	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.88	13.46	0.92	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:3	23.18	1230	1.71	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.87	13.53	0.92	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:3	23.18	1230	1.71	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.87	13.6	0.93	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:3	23.18	1224	1.71	13.4	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.88	13.65	0.93	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:3	23.18	1232	1.71	13.38	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.85	13.71	0.93	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:3	24.54	1240	1.71	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.88	13.75	0.94	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:4	24.54	1239	1.71	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.83	13.77	0.94	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:4	24.54	1230	1.71	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.83	13.78	0.94	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:4	24.54	1234	1.71	13.38	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.83	13.77	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:4	24.54	1245	1.7	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.83	13.76	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:4	24.54	1212	1.7	13.37	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.82	13.74	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:4	23.18	1212	1.7	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.84	13.71	0.93	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:4	23.18	1233	1.7	13.4	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.84	13.68	0.93	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:5	23.18	1210	1.7	13.4	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.85	13.64	0.93	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:5	23.18	1210	1.7	13.4	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.83	13.59	0.93	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:5	23.18	1221	1.7	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.83	13.52	0.92	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:31:5	23.18	1202	1.7	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.82	13.47	0.92	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:5	23.18	1202	1.7	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.81	13.42	0.91	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:5	24.54	1193	1.7	13.38	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.83	13.38	0.91	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:6	24.54	1188	1.7	13.38	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.79	13.33	0.91	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:6	24.54	1191	1.69	13.37	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.77	13.26	0.9	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:6	24.54	1188	1.69	13.36	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.75	13.21	0.9	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:6	24.54	1188	1.69	13.37	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.77	13.17	0.9	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:6	24.54	1188	1.69	13.35	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.74	13.12	0.89	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:6	24.54	1188	1.69	13.38	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.75	13.09	0.89	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:6	24.54	1168	1.69	13.38	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.73	13.07	0.89	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:7	24.54	1166	1.69	13.37	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.67	13.01	0.89	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:7	24.54	1154	1.69	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.63	12.97	0.88	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:7	24.54	1154	1.69	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.6	12.94	0.88	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:7	24.54	1152	1.69	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.64	12.9	0.88	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:7	24.54	1152	1.68	13.37	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.58	12.86	0.88	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:7	24.54	1148	1.68	13.37	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.61	12.81	0.87	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:8	24.54	1141	1.68	13.38	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.6	12.78	0.87	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:8	24.54	1141	1.68	13.37	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.57	12.74	0.87	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:8	24.54	1137	1.68	13.38	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.53	12.7	0.86	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:8	24.54	1134	1.68	13.38	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.53	12.63	0.86	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:8	24.54	1134	1.67	13.36	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.51	12.6	0.86	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:8	24.54	1124	1.67	13.37	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.5	12.59	0.86	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:9	24.54	1117	1.67	13.35	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.49	12.57	0.86	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:9	24.54	1112	1.67	13.36	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.49	12.55	0.86	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:9	24.54	1112	1.67	13.35	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.47	12.54	0.85	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:31:9	23.18	1102	1.67	13.38	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.43	12.53	0.85	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:9	23.18	1103	1.66	13.4	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.42	12.51	0.85	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:9	23.18	1103	1.66	13.38	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.4	12.5	0.85	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:31:9	23.18	1086	1.66	13.4	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.36	12.49	0.85	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:32:0	23.18	1086	1.66	13.38	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.3	12.47	0.85	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:32:0	23.18	1092	1.66	13.38	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.33	12.43	0.85	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:0	23.18	1093	1.65	13.39	106	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.29	12.4	0.84	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:0	24.54	1088	1.65	13.39	106	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.3	12.38	0.84	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:0	24.54	1088	1.65	13.41	106	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.28	12.35	0.84	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:0	24.54	1072	1.65	13.39	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.28	12.33	0.84	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:1	23.18	1067	1.65	13.39	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.27	12.31	0.84	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:1	23.18	1067	1.65	13.39	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.19	12.28	0.84	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:1	23.18	1072	1.64	13.38	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.23	12.27	0.84	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:1	23.18	1072	1.64	13.4	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.16	12.27	0.84	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:1	23.18	1066	1.64	13.37	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.19	12.27	0.84	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:1	23.18	1061	1.64	13.4	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.14	12.27	0.84	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:1	23.18	1035	1.64	13.37	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.1	12.28	0.84	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:2	23.18	1035	1.64	13.39	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.18	12.3	0.84	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:2	23.18	1043	1.63	13.37	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.11	12.3	0.84	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:2	23.18	1041	1.63	13.4	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.19	12.33	0.84	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:2	23.18	1041	1.63	13.38	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.11	12.34	0.84	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:2	23.18	1042	1.63	13.38	106	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.12	12.38	0.84	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:2	23.18	1042	1.63	13.41	106	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.09	12.4	0.84	4.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:3	23.18	1035	1.62	13.39	106	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.06	12.42	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:3	23.18	1029	1.62	13.39	106	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.04	12.45	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:3	23.18	1029	1.62	13.39	106	195	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.05	12.46	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:3	23.18	1030	1.62	13.41	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.04	12.47	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:3	23.18	1030	1.62	13.39	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3	12.48	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:3	23.18	1030	1.61	13.4	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.06	12.49	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:4	23.18	1031	1.61	13.4	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.98	12.5	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:4	23.18	1026	1.61	13.39	106	195	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.03	12.51	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:4	23.18	1026	1.61	13.38	106	195	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.93	12.52	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:4	23.18	1021	1.61	13.38	106	195	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.98	12.53	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:4	23.18	1016	1.6	13.39	106	195	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.9	12.54	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:4	23.18	1014	1.6	13.37	106	195	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.93	12.54	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:4	23.18	1014	1.6	13.4	106	195	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.9	12.56	0.86	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:5	23.18	1026	1.6	13.38	106	195	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.86	12.59	0.86	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:5	23.18	1042	1.6	13.41	106	195	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.89	12.59	0.86	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:32:5	23.18	1042	1.6	13.39	106	195	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.89	12.6	0.86	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:32:5	23.18	1044	1.59	13.41	106	195	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.94	12.62	0.86	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:32:5	20.45	1045	1.59	13.39	106	195	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.89	12.62	0.86	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:32:5	20.45	1045	1.59	13.41	106	195	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.97	12.64	0.86	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:32:6	20.45	1084	1.59	13.4	106	195	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.97	12.65	0.86	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:32:6	20.45	1109	1.59	13.4	106	195	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.04	12.67	0.86	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:32:6	20.45	1109	1.59	13.4	106	195	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.04	12.67	0.86	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:32:6	20.45	1128	1.59	13.4	106	195	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.12	12.7	0.87	4.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:32:6	20.45	1158	1.59	13.39	106	195	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.21	12.71	0.87	4.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:32:6	20.45	1158	1.59	13.38	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.21	12.73	0.87	4.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:32:6	20.45	1165	1.6	13.38	106	195	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.3	12.75	0.87	4.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:32:7	21.81	1178	1.6	13.38	106	195	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.37	12.78	0.87	4.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:32:7	21.81	1184	1.6	13.4	106	195	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.38	12.8	0.87	4.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:32:7	21.81	1194	1.6	13.4	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.43	12.81	0.87	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:32:7	21.81	1194	1.61	13.42	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.47	12.82	0.87	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:32:7	21.81	1196	1.61	13.43	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.49	12.84	0.87	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:32:7	21.81	1203	1.61	13.41	106	195	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.52	12.86	0.88	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:8	21.81	1203	1.62	13.42	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.55	12.87	0.88	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:8	21.81	1198	1.62	13.41	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.55	12.89	0.88	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:8	21.81	1195	1.63	13.4	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.63	12.91	0.88	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:32:8	21.81	1195	1.63	13.4	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.62	12.91	0.88	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:8	21.81	1202	1.63	13.4	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.67	12.92	0.88	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:8	21.81	1216	1.64	13.4	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.67	12.93	0.88	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:9	21.81	1222	1.64	13.39	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.7	12.95	0.88	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:9	21.81	1233	1.65	13.39	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.7	12.97	0.88	4.2	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:9	21.81	1246	1.65	13.39	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.73	12.98	0.88	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:9	21.81	1248	1.65	13.38	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.79	13	0.89	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:9	21.81	1256	1.66	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.82	13.02	0.89	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:9	21.81	1263	1.66	13.39	106	195	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.88	13.05	0.89	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:32:9	21.81	1290	1.67	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.93	13.1	0.89	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:33:0	21.81	1296	1.67	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.95	13.15	0.9	4.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:33:0	21.81	1296	1.67	13.38	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4	13.2	0.9	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:33:0	21.81	1307	1.68	13.39	106	195	Off Idle	86.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4	13.28	0.9	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:33:0	21.81	1317	1.68	13.39	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.02	13.38	0.91	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:33:0	21.81	1340	1.68	13.37	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.03	13.45	0.92	4.2	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:33:0	21.81	1340	1.68	13.39	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.09	13.51	0.92	4.2	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:33:1	23.18	1356	1.69	13.39	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.14	13.59	0.93	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:33:1	23.18	1355	1.69	13.38	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.15	13.67	0.93	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:1	23.18	1355	1.69	13.4	106	195	Off Idle	86.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.21	13.71	0.93	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:1	23.18	1359	1.7	13.39	106	195	Off Idle	86.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.33	13.86	0.94	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:1	23.18	1359	1.7	13.39	106	195	Off Idle	86.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.31	13.9	0.95	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:1	23.18	1359	1.7	13.38	106	195	Off Idle	86.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.36	13.99	0.95	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:1	23.18	1359	1.71	13.37	106	195	Off Idle	86.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.38	14.04	0.96	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:2	23.18	1365	1.71	13.39	106	195	Off Idle	86.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.39	14.1	0.96	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:2	23.18	1368	1.71	13.39	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.4	14.16	0.96	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:2	23.18	1381	1.72	13.37	106	196	Off Idle	86.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.37	14.25	0.97	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:2	23.18	1381	1.72	13.4	106	196	Off Idle	86.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.41	14.28	0.97	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:2	24.54	1379	1.72	13.39	106	196	Off Idle	86.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.4	14.32	0.98	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:2	24.54	1387	1.72	13.38	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.43	14.33	0.98	4.2	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:3	24.54	1389	1.73	13.4	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.5	14.36	0.98	4.2	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:3	24.54	1391	1.73	13.4	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.47	14.38	0.98	4.2	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:3	24.54	1402	1.73	13.4	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.53	14.44	0.98	4.2	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:3	24.54	1414	1.73	13.4	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.56	14.45	0.98	4.2	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:3	24.54	1426	1.74	13.39	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.57	14.47	0.99	4.2	3	ON	28 Pin	OFF	Removed	Disabled
03:17:33:3	24.54	1428	1.74	13.4	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.58	14.5	0.99	4.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:4	25.9	1442	1.74	13.39	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.54	14.53	0.99	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:4	25.9	1473	1.74	13.39	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.59	14.56	0.99	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:4	25.9	1463	1.74	13.4	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.62	14.6	0.99	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:4	25.9	1463	1.74	13.39	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.66	14.63	1	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:4	25.9	1484	1.75	13.39	106	195	Off Idle	86.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.71	14.65	1	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:4	25.9	1498	1.75	13.39	106	196	Off Idle	86.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.72	14.67	1	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:4	25.9	1495	1.75	13.38	106	196	Off Idle	86.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.77	14.74	1	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:5	25.9	1494	1.75	13.37	106	196	Off Idle	86.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.83	14.77	1.01	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:5	25.9	1498	1.75	13.39	106	195	Off Idle	86.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.82	14.79	1.01	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:5	25.9	1498	1.76	13.38	106	195	Off Idle	86.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.84	14.81	1.01	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:5	25.9	1498	1.76	13.39	106	195	Off Idle	86.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-4.88	14.81	1.01	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:5	25.9	1513	1.76	13.38	106	195	Off Idle	86.7	0	2	132	944 Turbo	0.21	Rich	1	14.6	-4.91	14.81	1.01	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:5	27.27	1509	1.76	13.38	106	195	Off Idle	86.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.89	14.83	1.01	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:6	27.27	1509	1.76	13.38	106	195	Off Idle	86.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.88	14.85	1.01	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:6	27.27	1517	1.77	13.38	106	195	Off Idle	86.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.9	14.89	1.01	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:6	27.27	1519	1.77	13.36	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.89	14.93	1.02	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:6	27.27	1528	1.77	13.37	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.93	14.96	1.02	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:6	27.27	1534	1.77	13.38	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.96	14.98	1.02	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:6	27.27	1546	1.77	13.4	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.96	15.01	1.02	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:6	27.27	1554	1.78	13.38	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.95	15.06	1.03	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:7	27.27	1554	1.78	13.4	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5	15.12	1.03	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:7	27.27	1548	1.78	13.4	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.01	15.17	1.03	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:7	25.9	1568	1.78	13.41	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.03	15.19	1.03	4	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:33:7	25.9	1568	1.78	13.4	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.05	15.2	1.04	4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:7	25.9	1571	1.78	13.4	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.05	15.22	1.04	4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:7	25.9	1570	1.79	13.39	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.08	15.22	1.04	4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:8	25.9	1572	1.79	13.39	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.08	15.22	1.04	4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:8	25.9	1585	1.79	13.38	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.12	15.22	1.04	4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:8	25.9	1594	1.79	13.37	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.16	15.22	1.04	4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:8	25.9	1599	1.79	13.4	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.17	15.2	1.04	4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:8	25.9	1599	1.79	13.4	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.18	15.18	1.03	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:8	25.9	1620	1.79	13.4	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.19	15.17	1.03	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:9	27.27	1619	1.79	13.4	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.21	15.16	1.03	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:9	27.27	1622	1.8	13.39	106	195	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.2	15.14	1.03	3.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:33:9	27.27	1633	1.8	13.39	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.24	15.14	1.03	3.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:33:9	27.27	1655	1.8	13.38	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.25	15.12	1.03	3.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:33:9	27.27	1655	1.8	13.4	106	195	Off Idle	86.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.26	15.12	1.03	3.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:33:9	27.27	1658	1.81	13.39	106	196	Off Idle	86.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.27	15.14	1.03	4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:33:9	27.27	1663	1.81	13.4	106	196	Off Idle	86.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.34	15.14	1.03	4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:34:0	27.27	1665	1.81	13.39	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.32	15.17	1.03	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:34:0	27.27	1666	1.82	13.39	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.33	15.15	1.03	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:34:0	27.27	1672	1.82	13.39	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.33	15.17	1.03	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:34:0	27.27	1679	1.83	13.39	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.32	15.17	1.03	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:34:0	27.27	1683	1.83	13.39	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.29	15.17	1.03	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:34:0	27.27	1684	1.84	13.39	106	196	Off Idle	86.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.28	15.18	1.03	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:1	27.27	1690	1.84	13.4	106	196	Off Idle	86.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.29	15.18	1.03	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:1	27.27	1695	1.85	13.39	106	196	Off Idle	86.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.31	15.16	1.03	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:1	27.27	1695	1.85	13.39	106	196	Off Idle	86.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.27	15.14	1.03	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:1	27.27	1706	1.86	13.39	106	196	Off Idle	86.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.29	15.1	1.03	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:1	27.27	1712	1.87	13.39	106	196	Off Idle	86.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.27	15.12	1.03	4	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:1	28.63	1716	1.88	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.27	15.09	1.03	4	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:1	28.63	1716	1.88	13.38	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.26	15.08	1.03	4	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:2	28.63	1723	1.89	13.38	106	195	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.22	15.06	1.03	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:2	28.63	1734	1.89	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.18	15.04	1.02	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:2	28.63	1746	1.9	13.39	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.19	15.02	1.02	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:2	28.63	1750	1.91	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.14	15.02	1.02	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:2	28.63	1759	1.91	13.39	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.12	15.01	1.02	3.9	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:2	28.63	1759	1.92	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.11	15.01	1.02	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:3	28.63	1772	1.93	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.1	15.02	1.02	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:3	28.63	1781	1.93	13.37	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.06	15.03	1.02	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:3	28.63	1784	1.94	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.05	15.05	1.03	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:3	28.63	1784	1.94	13.39	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.05	15.06	1.03	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:3	28.63	1794	1.94	13.39	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.05	15.07	1.03	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:3	28.63	1802	1.95	13.39	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.03	15.11	1.03	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:4	28.63	1802	1.95	13.39	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.07	15.12	1.03	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:4	28.63	1803	1.96	13.41	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.08	15.14	1.03	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:4	28.63	1806	1.96	13.4	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.07	15.15	1.03	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:4	28.63	1808	1.97	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.06	15.14	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:4	28.63	1812	1.97	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.08	15.15	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:4	28.63	1821	1.98	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.01	15.16	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:4	28.63	1828	1.98	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.99	15.15	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:5	28.63	1830	1.98	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.95	15.15	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:5	28.63	1841	1.99	13.36	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.88	15.12	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:5	28.63	1845	1.99	13.37	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.87	15.11	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:5	28.63	1851	2	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.87	15.11	1.03	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:34:5	28.63	1856	2	13.39	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.86	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:34:5	28.63	1871	2.01	13.39	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.85	15.1	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:34:6	28.63	1879	2.01	13.41	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.77	15.1	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:34:6	28.63	1884	2.02	13.39	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.7	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:34:6	28.63	1916	2.03	13.38	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.63	15.07	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:34:6	28.63	1910	2.04	13.36	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.57	15.07	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:34:6	28.63	1912	2.04	13.37	106	196	Off Idle	86.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.6	15.07	1.03	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:34:6	28.63	1937	2.04	13.37	106	196	Off Idle	86.1	0	2	132	944 Turbo	0.24	Rich	1	14.6	-4.57	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:34:6	29.99	1929	2.05	13.39	106	196	Off Idle	86.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-4.56	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:34:7	29.99	1940	2.06	13.4	106	196	Off Idle	86.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.55	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:7	29.99	1942	2.07	13.37	106	196	Off Idle	86.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.52	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:7	29.99	1945	2.07	13.37	106	196	Off Idle	86.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.47	15.1	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:7	29.99	1948	2.08	13.36	106	196	Off Idle	86	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.46	15.11	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:7	29.99	1953	2.08	13.35	106	196	Off Idle	86	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.46	15.14	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:7	29.99	1953	2.09	13.37	106	196	Off Idle	86	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.48	15.14	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:8	29.99	1957	2.1	13.38	106	196	Off Idle	86	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.55	15.14	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:8	29.99	1959	2.1	13.38	106	196	Off Idle	86	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.56	15.1	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:8	29.99	1962	2.11	13.4	106	196	Off Idle	86	0	2	132	944 Turbo	0.59	Lean	1	14.6	-4.55	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:8	29.99	1963	2.11	13.41	106	196	Off Idle	86	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.52	15.05	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:34:8	29.99	1970	2.12	13.42	106	196	Off Idle	86	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.48	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:8	29.99	1984	2.12	13.41	106	196	Off Idle	86	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.47	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:9	29.99	1984	2.13	13.4	106	195	Off Idle	86	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.39	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:9	29.99	2003	2.14	13.39	106	195	Off Idle	86	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.35	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:9	29.99	2013	2.14	13.38	106	195	Off Idle	86	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.27	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:9	29.99	2028	2.15	13.37	106	196	Off Idle	86	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.19	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:9	29.99	2034	2.16	13.37	106	196	Off Idle	86	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.13	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:34:9	29.99	2052	2.16	13.38	106	196	Off Idle	86	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.07	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:34:9	29.99	2061	2.17	13.4	106	196	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.06	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:35:0	29.99	2064	2.18	13.41	106	196	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.05	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:35:0	29.99	2073	2.18	13.42	106	196	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.04	14.94	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:35:0	29.99	2084	2.19	13.42	106	196	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.03	15.02	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:35:0	29.99	2112	2.2	13.42	106	196	Off Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.02	15.08	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:35:0	29.99	2112	2.2	13.43	106	196	Off Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.95	15.15	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:35:0	29.99	2101	2.21	13.42	106	196	Off Idle	85.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.91	15.23	1.04	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:35:1	29.99	2105	2.22	13.42	106	196	Off Idle	85.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.95	15.3	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:35:1	29.99	2105	2.22	13.42	106	196	Off Idle	85.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.94	15.33	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:35:1	29.99	2112	2.23	13.42	106	196	Off Idle	85.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.98	15.34	1.05	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:35:1	31.36	2116	2.24	13.41	106	196	Off Idle	85.6	0	2	132	944 Turbo	0.14	Rich	1	14.6	-4.02	15.35	1.05	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:35:1	31.36	2116	2.24	13.41	106	196	Off Idle	85.6	0	2	132	944 Turbo	0.2	Rich	1	14.6	-4.02	15.34	1.05	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:35:1	31.36	2122	2.24	13.39	106	196	Off Idle	85.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-3.98	15.32	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:35:1	31.36	2133	2.24	13.38	106	196	Off Idle	85.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-3.95	15.31	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:35:2	31.36	2133	2.25	13.37	106	196	Off Idle	85.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.94	15.28	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:35:2	31.36	2146	2.25	13.39	106	196	Off Idle	85.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.95	15.26	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:35:2	31.36	2156	2.25	13.41	106	196	Off Idle	85.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.04	15.26	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:2	31.36	2156	2.25	13.41	106	196	Off Idle	85.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.12	15.22	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:2	29.99	2156	2.25	13.41	106	196	Off Idle	85.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.18	15.19	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:2	29.99	2164	2.25	13.4	106	196	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.19	15.15	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:3	29.99	2174	2.25	13.37	106	196	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.2	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:3	29.99	2174	2.25	13.37	106	195	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.18	15.05	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:3	29.99	2182	2.25	13.38	106	195	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.19	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:35:3	29.99	2193	2.25	13.38	106	195	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.22	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:35:3	29.99	2205	2.24	13.38	106	196	Off Idle	85.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.28	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:35:3	31.36	2205	2.24	13.38	106	196	Off Idle	85.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.29	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:35:4	31.36	2219	2.24	13.37	106	196	Off Idle	84.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.36	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:4	31.36	2219	2.24	13.36	106	196	Off Idle	84.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.34	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:4	31.36	2228	2.24	13.36	106	196	Off Idle	84.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.37	14.74	1	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:4	31.36	2244	2.24	13.37	106	196	Off Idle	84.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.36	14.74	1	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:4	31.36	2272	2.24	13.39	106	196	Off Idle	84	0	2	132	944 Turbo	0.28	Rich	1	14.6	-4.4	14.75	1	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:4	31.36	2269	2.24	13.39	106	196	Off Idle	83.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.46	14.73	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:35:4	31.36	2272	2.24	13.39	106	196	Off Idle	83.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.51	14.75	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:35:5	31.36	2302	2.24	13.39	106	196	Off Idle	82.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.56	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:35:5	31.36	2289	2.24	13.4	106	196	Off Idle	82.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.63	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:35:5	31.36	2291	2.24	13.4	106	196	Off Idle	81.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.72	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:35:5	31.36	2298	2.24	13.38	106	196	Off Idle	81	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.82	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:35:5	31.36	2310	2.23	13.39	106	196	Off Idle	80.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.88	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:35:5	32.72	2296	2.23	13.4	106	196	Off Idle	80.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.96	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:6	32.72	2296	2.23	13.4	106	196	Off Idle	79.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.04	15.09	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:6	32.72	2299	2.22	13.39	106	196	Off Idle	79.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.08	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:6	32.72	2301	2.22	13.39	106	196	Off Idle	79.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.12	15.2	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:6	32.72	2301	2.22	13.41	106	196	Off Idle	79	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.18	15.23	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:6	32.72	2307	2.22	13.41	106	196	Off Idle	78.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.22	15.25	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:6	32.72	2314	2.21	13.4	106	196	Off Idle	78.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.25	15.25	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:6	32.72	2323	2.21	13.4	106	196	Off Idle	78.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.3	15.23	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:7	32.72	2326	2.21	13.4	106	196	Off Idle	78.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.33	15.21	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:7	32.72	2334	2.21	13.39	106	196	Off Idle	78	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.33	15.2	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:7	32.72	2358	2.2	13.39	106	196	Off Idle	77.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.34	15.18	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:7	32.72	2354	2.2	13.41	106	196	Off Idle	77.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.39	15.15	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:7	32.72	2358	2.2	13.4	106	196	Off Idle	77.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.39	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:7	32.72	2371	2.2	13.41	106	196	Off Idle	77	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.39	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:8	32.72	2385	2.19	13.41	106	196	Off Idle	76.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.43	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:8	32.72	2385	2.19	13.39	106	196	Off Idle	76.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.42	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:35:8	32.72	2397	2.19	13.38	106	196	Off Idle	76.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.44	15.17	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:35:8	32.72	2403	2.19	13.4	106	196	Off Idle	75.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.44	15.19	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:8	32.72	2405	2.2	13.4	106	196	Off Idle	75.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.48	15.2	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:8	32.72	2422	2.2	13.4	106	196	Off Idle	74.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.49	15.22	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:9	32.72	2415	2.2	13.4	106	196	Off Idle	74.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.53	15.24	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:9	32.72	2415	2.2	13.41	106	196	Off Idle	74	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.52	15.25	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:9	32.72	2416	2.2	13.4	106	196	Off Idle	73.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.58	15.26	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:9	32.72	2417	2.2	13.39	106	196	Off Idle	73.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.6	15.27	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:9	32.72	2423	2.2	13.39	106	196	Off Idle	73	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.59	15.28	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:35:9	32.72	2423	2.21	13.39	106	196	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.6	15.29	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:35:9	32.72	2428	2.21	13.4	106	196	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.65	15.29	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:0	32.72	2432	2.21	13.41	106	196	Off Idle	71.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.65	15.29	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:0	32.72	2436	2.21	13.41	106	196	Off Idle	71.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.68	15.29	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:0	32.72	2444	2.21	13.41	106	196	Off Idle	71	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.7	15.3	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:0	32.72	2455	2.21	13.41	106	196	Off Idle	70.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.72	15.29	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:0	32.72	2467	2.21	13.41	106	196	Off Idle	70.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.75	15.29	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:0	32.72	2467	2.21	13.41	106	196	Off Idle	70.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.77	15.28	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:1	32.72	2484	2.21	13.4	106	196	Off Idle	70.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.78	15.29	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:1	32.72	2477	2.22	13.41	106	196	Off Idle	70	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.75	15.26	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:1	32.72	2480	2.22	13.41	106	196	Off Idle	69.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.75	15.25	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:1	32.72	2480	2.22	13.41	106	196	Off Idle	69.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.77	15.22	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:1	32.72	2502	2.22	13.4	106	196	Off Idle	69.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.78	15.22	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:1	34.08	2491	2.22	13.41	106	196	Off Idle	69	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.8	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:1	34.08	2491	2.22	13.4	106	196	Off Idle	68.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.81	15.15	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:2	34.08	2499	2.22	13.41	106	196	Off Idle	68.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.8	15.15	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:2	34.08	2503	2.22	13.41	106	196	Off Idle	67.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.81	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:2	34.08	2507	2.22	13.42	106	196	Off Idle	67.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.81	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:2	34.08	2514	2.22	13.4	106	196	Off Idle	67.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.79	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:2	34.08	2522	2.23	13.42	106	196	Off Idle	67	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.78	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:2	34.08	2547	2.23	13.41	106	196	Off Idle	66.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.82	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:3	34.08	2547	2.23	13.41	106	196	Off Idle	66.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.8	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:3	34.08	2540	2.23	13.4	106	196	Off Idle	66.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.81	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:3	34.08	2551	2.23	13.41	106	196	Off Idle	66.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.88	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:3	34.08	2551	2.24	13.41	106	196	Off Idle	65.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.89	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:3	34.08	2564	2.24	13.4	106	196	Off Idle	65.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.9	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:3	34.08	2572	2.24	13.4	106	196	Off Idle	65.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.9	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:4	34.08	2579	2.24	13.4	106	196	Off Idle	64.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.88	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:4	34.08	2581	2.24	13.41	106	196	Off Idle	64.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.88	15.09	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:4	34.08	2598	2.25	13.39	106	196	Off Idle	64.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.89	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:4	34.08	2592	2.25	13.4	106	196	Off Idle	63.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.91	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:4	34.08	2594	2.25	13.39	106	196	Off Idle	63.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.9	15.1	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:36:4	34.08	2594	2.25	13.4	106	196	Off Idle	63.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.92	15.12	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:4	34.08	2594	2.25	13.42	106	196	Off Idle	63.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.93	15.12	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:5	34.08	2596	2.26	13.41	106	196	Off Idle	62.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.95	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:5	34.08	2596	2.26	13.42	106	196	Off Idle	62.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.94	15.07	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:5	34.08	2597	2.26	13.41	106	196	Off Idle	62.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.94	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:5	34.08	2600	2.26	13.42	106	196	Off Idle	61.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.93	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:5	34.08	2600	2.26	13.39	106	196	Off Idle	61.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.93	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:5	34.08	2606	2.27	13.39	106	196	Off Idle	61.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.95	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:6	34.08	2610	2.27	13.39	106	196	Off Idle	61.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.95	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:6	34.08	2620	2.27	13.39	106	196	Off Idle	61.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.94	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:6	34.08	2626	2.27	13.39	106	196	Off Idle	61.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.96	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:6	34.08	2630	2.27	13.39	106	196	Off Idle	61	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.94	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:6	34.08	2645	2.27	13.41	106	196	Off Idle	60.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.92	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:6	34.08	2657	2.27	13.4	106	196	Off Idle	60.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.94	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:6	34.08	2661	2.28	13.41	106	196	Off Idle	60.2	0	2	132	944 Turbo	0.15	Rich	1	14.6	-5.96	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:7	34.08	2684	2.28	13.39	106	196	Off Idle	59.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.95	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:7	34.08	2679	2.28	13.4	106	196	Off Idle	59.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.96	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:36:7	34.08	2690	2.28	13.4	106	196	Off Idle	59.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.01	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:36:7	34.08	2692	2.28	13.38	106	196	Off Idle	59.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:7	34.08	2693	2.28	13.4	106	196	Off Idle	58.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.01	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:7	34.08	2694	2.28	13.41	106	196	Off Idle	58.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.1	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:8	34.08	2696	2.28	13.42	106	196	Off Idle	57.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.18	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:8	34.08	2692	2.27	13.4	106	196	Off Idle	57.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.22	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:36:8	34.08	2693	2.27	13.42	106	196	Off Idle	56.9	0	2	132	944 Turbo	0.65	Lean	1	14.6	-6.26	15.2	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:36:8	34.08	2693	2.27	13.4	106	196	Off Idle	56.9	0	2	132	944 Turbo	0.68	Lean	1	14.6	-6.32	15.2	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:36:8	34.08	2694	2.26	13.39	106	196	Off Idle	56.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.39	15.19	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:36:8	34.08	2691	2.26	13.39	106	196	Off Idle	56.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.41	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:36:9	34.08	2691	2.26	13.4	106	196	Off Idle	56.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.47	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:36:9	34.08	2692	2.25	13.39	106	196	Off Idle	56.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.58	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:36:9	34.08	2694	2.25	13.39	106	196	Off Idle	56.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.6	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:36:9	34.08	2695	2.24	13.41	106	196	Off Idle	56.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.61	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:36:9	34.08	2698	2.24	13.4	106	196	Off Idle	55.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.72	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:36:9	34.08	2722	2.23	13.4	106	196	Off Idle	55.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.72	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:36:9	35.45	2714	2.23	13.41	106	196	Off Idle	55.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.73	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:0	35.45	2717	2.22	13.4	106	196	Off Idle	55.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.79	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:0	35.45	2727	2.22	13.4	106	196	Off Idle	55.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.81	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:0	35.45	2735	2.21	13.38	106	196	Off Idle	55.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.85	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:0	35.45	2745	2.21	13.38	106	196	Off Idle	55.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.86	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:0	34.08	2766	2.2	13.4	106	196	Off Idle	55.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.91	14.87	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:0	34.08	2790	2.2	13.41	106	196	Off Idle	54.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.94	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:1	34.08	2775	2.2	13.41	106	196	Off Idle	54.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.91	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:1	34.08	2782	2.19	13.41	106	196	Off Idle	54.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.9	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:1	34.08	2787	2.19	13.41	106	196	Off Idle	54	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.92	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:1	34.08	2797	2.19	13.4	106	196	Off Idle	53.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.9	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:1	35.45	2787	2.19	13.4	106	196	Off Idle	53	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.88	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:1	35.45	2787	2.19	13.41	106	196	Off Idle	52.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.93	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:1	35.45	2786	2.19	13.4	106	196	Off Idle	52.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.95	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:2	35.45	2786	2.19	13.38	106	196	Off Idle	52.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.94	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:2	35.45	2784	2.2	13.39	106	196	Off Idle	51.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.95	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:2	35.45	2780	2.2	13.4	106	196	Off Idle	51.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.94	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:2	35.45	2782	2.2	13.39	106	196	Off Idle	51.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.92	15.08	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:2	35.45	2776	2.2	13.41	106	196	Off Idle	51.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.91	15.09	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:2	35.45	2782	2.2	13.43	106	196	Off Idle	50.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.89	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:3	35.45	2785	2.2	13.43	106	196	Off Idle	50.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.89	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:3	35.45	2789	2.2	13.45	106	196	Off Idle	50.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.87	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:3	35.45	2789	2.21	13.44	106	196	Off Idle	50.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.89	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:3	35.45	2787	2.21	13.44	106	196	Off Idle	50.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.87	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:3	35.45	2787	2.21	13.43	106	196	Off Idle	50.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.85	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:37:3	35.45	2799	2.21	13.41	106	196	Off Idle	50.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.85	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:4	35.45	2808	2.21	13.4	106	196	Off Idle	50.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.84	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:4	35.45	2808	2.21	13.41	106	196	Off Idle	50.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.82	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:4	35.45	2829	2.21	13.41	106	196	Off Idle	50.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.86	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:4	35.45	2842	2.21	13.4	106	196	Off Idle	50.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.86	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:4	35.45	2849	2.21	13.41	106	196	Off Idle	50	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.88	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:4	35.45	2851	2.22	13.41	106	196	Off Idle	49.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.92	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:4	35.45	2858	2.22	13.4	106	196	Off Idle	49.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.92	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:5	35.45	2861	2.22	13.39	106	196	Off Idle	49.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.91	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:5	35.45	2872	2.22	13.4	106	196	Off Idle	49.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.88	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:5	35.45	2862	2.22	13.4	106	196	Off Idle	48.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.87	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:5	35.45	2863	2.22	13.41	106	196	Off Idle	48.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.89	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:5	35.45	2859	2.22	13.41	106	196	Off Idle	48.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.86	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:5	35.45	2859	2.22	13.41	106	196	Off Idle	48	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.85	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:6	35.45	2854	2.23	13.41	106	196	Off Idle	47.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.86	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:6	35.45	2854	2.23	13.41	106	196	Off Idle	47.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.85	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:6	35.45	2855	2.23	13.41	106	196	Off Idle	46.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.83	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:6	35.45	2854	2.23	13.41	106	196	Off Idle	46.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.85	15.17	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:6	35.45	2854	2.23	13.4	106	196	Off Idle	46.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.82	15.2	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:6	35.45	2859	2.24	13.4	106	196	Off Idle	46.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.81	15.21	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:37:6	35.45	2861	2.24	13.41	106	196	Off Idle	46.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.78	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:7	35.45	2861	2.24	13.4	106	196	Off Idle	46.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.75	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:7	35.45	2864	2.24	13.41	106	196	Off Idle	46.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.71	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:7	35.45	2873	2.25	13.41	106	196	Off Idle	46.2	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.65	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:37:7	35.45	2876	2.25	13.41	106	196	Off Idle	46.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.64	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:7	35.45	2886	2.26	13.41	106	196	Off Idle	46.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.63	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:7	35.45	2899	2.26	13.4	106	196	Off Idle	46.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.55	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:8	35.45	2899	2.26	13.42	106	196	Off Idle	46.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.55	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:8	35.45	2906	2.27	13.43	106	196	Off Idle	46.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.53	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:8	35.45	2920	2.27	13.43	106	196	Off Idle	45.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.48	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:8	35.45	2936	2.28	13.43	106	196	Off Idle	45.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.47	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:8	35.45	2936	2.28	13.42	106	196	Off Idle	45.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.46	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:8	35.45	2954	2.29	13.42	106	196	Off Idle	45.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.39	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:37:9	35.45	2945	2.29	13.42	106	196	Off Idle	44.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.41	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:37:9	35.45	2945	2.3	13.41	106	196	Off Idle	44.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.34	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:9	35.45	2947	2.31	13.41	106	196	Off Idle	43.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.4	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:9	35.45	2950	2.32	13.41	106	196	Off Idle	43.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.29	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:9	35.45	2936	2.32	13.41	106	196	Off Idle	43.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.32	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:9	35.45	2936	2.33	13.41	106	196	Off Idle	43	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.18	15.15	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:37:9	35.45	2936	2.33	13.4	106	196	Off Idle	42.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.17	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:38:0	35.45	2916	2.34	13.41	106	196	Off Idle	42.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.02	15.15	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:38:0	35.45	2916	2.35	13.4	106	196	Off Idle	42.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.02	15.12	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:38:0	35.45	2947	2.36	13.39	106	196	Off Idle	41.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.87	15.08	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:0	35.45	2950	2.38	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.81	15.05	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:0	35.45	2952	2.38	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.75	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:0	35.45	2966	2.39	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.75	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:1	35.45	2976	2.4	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.64	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:1	35.45	2987	2.41	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.64	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:1	35.45	2990	2.42	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.6	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:1	35.45	3006	2.43	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.58	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:1	35.45	3025	2.44	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.53	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:1	35.45	3028	2.45	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.53	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:1	35.45	3043	2.45	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.5	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:2	35.45	3051	2.46	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.51	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:2	35.45	3051	2.47	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.46	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:2	35.45	3056	2.48	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.54	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:2	35.45	3060	2.49	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.48	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:2	35.45	3053	2.49	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.5	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:38:2	35.45	3053	2.5	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.51	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:3	35.45	3047	2.5	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.55	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:3	35.45	3046	2.51	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.57	15.08	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:3	35.45	3048	2.51	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.57	15.02	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:3	35.45	3057	2.51	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.57	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:3	35.45	3056	2.51	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.53	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:3	35.45	3062	2.52	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.5	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:4	35.45	3062	2.52	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.43	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:4	35.45	3073	2.52	13.38	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.39	14.69	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:4	35.45	3085	2.53	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.39	14.66	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:38:4	35.45	3091	2.53	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.32	14.64	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:4	35.45	3096	2.54	13.41	106	196	Off Idle	41.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.28	14.65	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:4	35.45	3103	2.54	13.41	106	196	Off Idle	41.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.27	14.67	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:4	35.45	3142	2.55	13.41	106	196	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.17	14.71	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:5	35.45	3134	2.55	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.16	14.74	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:38:5	35.45	3140	2.56	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.12	14.77	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:38:5	35.45	3150	2.56	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.1	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:38:5	35.45	3152	2.57	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.09	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:38:5	35.45	3166	2.57	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.09	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:38:5	35.45	3176	2.58	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.08	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:38:6	35.45	3178	2.59	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.08	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:6	35.45	3186	2.59	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.09	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:6	35.45	3214	2.6	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.09	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:6	35.45	3195	2.6	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.08	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:6	35.45	3196	2.61	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.12	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:6	35.45	3193	2.61	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.11	15.01	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:6	35.45	3193	2.62	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.1	15.04	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:7	35.45	3192	2.62	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.11	15.04	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:7	35.45	3192	2.62	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Lean	1	14.6	-5.15	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:7	35.45	3193	2.63	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.06	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:7	35.45	3194	2.63	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.1	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:7	35.45	3202	2.63	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.05	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:7	35.45	3212	2.63	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.07	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:8	35.45	3225	2.63	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.02	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:8	35.45	3227	2.64	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.05	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:8	35.45	3234	2.64	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5	14.71	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:38:8	35.45	3247	2.64	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.96	14.72	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:8	35.45	3271	2.65	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.92	14.74	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:38:8	35.45	3273	2.65	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.87	14.75	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:38:9	35.45	3274	2.66	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.81	14.78	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:38:9	35.45	3295	2.66	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.78	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:38:9	35.45	3297	2.67	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.66	14.79	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:38:9	35.45	3314	2.68	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.66	14.78	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:38:9	35.45	3332	2.68	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.58	14.81	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:38:9	35.45	3340	2.69	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.55	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:38:9	35.45	3342	2.69	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.61	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:39:0	35.45	3352	2.7	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.56	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:39:0	35.45	3356	2.7	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.59	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:39:0	35.45	3358	2.71	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.68	15.01	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:39:0	35.45	3365	2.72	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.66	15.03	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:39:0	35.45	3368	2.72	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.67	15.06	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:39:0	35.45	3368	2.73	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.75	15.03	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:39:1	35.45	3368	2.73	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.72	15	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:1	35.45	3382	2.73	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.74	14.93	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:1	35.45	3374	2.73	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.71	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:1	35.45	3374	2.73	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.66	14.79	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:1	35.45	3376	2.74	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.67	14.71	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:1	35.45	3370	2.74	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.7	14.62	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:39:1	35.45	3374	2.74	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.67	14.5	0.99	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:2	35.45	3382	2.73	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.81	14.42	0.98	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:2	35.45	3398	2.73	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.81	14.41	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:2	35.45	3407	2.73	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.81	14.42	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:2	35.45	3410	2.73	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.87	14.44	0.98	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:2	35.45	3426	2.73	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.89	14.47	0.99	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:2	35.45	3438	2.73	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.86	14.52	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:3	35.45	3442	2.73	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.87	14.56	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:3	35.45	3464	2.73	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.96	14.63	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:3	35.45	3459	2.73	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.98	14.68	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:3	35.45	3461	2.73	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.98	14.73	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:3	35.45	3470	2.73	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.03	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:3	35.45	3495	2.72	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.06	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:4	35.45	3490	2.72	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.05	14.81	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:4	35.45	3488	2.72	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.05	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:4	35.45	3496	2.72	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.11	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:4	35.45	3494	2.72	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.15	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:4	35.45	3496	2.72	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.17	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:4	35.45	3491	2.72	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.17	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:4	35.45	3500	2.72	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.22	14.84	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:5	35.45	3512	2.71	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.29	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:39:5	35.45	3520	2.71	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.24	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:39:5	35.45	3531	2.71	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.28	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:39:5	35.45	3530	2.71	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.36	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:39:5	35.45	3536	2.71	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.35	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:39:5	35.45	3541	2.71	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.29	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:6	35.45	3542	2.71	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.37	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:6	35.45	3544	2.7	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.39	15.05	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:6	35.45	3546	2.7	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.39	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:6	35.45	3546	2.7	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.38	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:6	35.45	3548	2.7	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.4	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:6	35.45	3553	2.7	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.41	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:6	35.45	3553	2.7	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.45	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:7	35.45	3562	2.69	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.49	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:7	36.81	3584	2.69	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.5	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:7	36.81	3583	2.69	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.53	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:39:7	36.81	3597	2.69	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.54	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:7	36.81	3598	2.69	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.54	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:7	36.81	3611	2.69	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.53	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:8	36.81	3624	2.69	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.66	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:8	36.81	3624	2.68	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.78	15.06	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:39:8	36.81	3636	2.67	13.4	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.95	15.09	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:39:8	36.81	3637	2.65	13.39	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.22	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:39:8	36.81	3637	2.63	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.55	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:39:8	36.81	3628	2.6	13.43	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.86	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:39:9	36.81	3618	2.54	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.48	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:39:9	36.81	3618	2.49	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.96	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:39:9	38.18	3612	2.44	13.42	106	196	Full Load	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.38	14.97	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:17:39:9	38.18	3570	2.39	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.77	14.93	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:39:9	38.18	3550	2.35	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.08	14.86	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:39:9	38.18	3543	2.3	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.27	14.8	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:17:39:9	35.45	3460	2.25	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.45	14.78	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:0	29.99	3435	2.2	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.58	14.75	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:0	24.54	3416	2.15	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.67	14.7	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:0	20.45	3420	2.11	13.4	106	196	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.73	14.65	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:0	20.45	3415	2.06	13.41	106	196	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.8	14.58	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:0	20.45	3410	2.01	13.43	106	196	Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.77	14.49	0.99	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:0	20.45	3344	1.96	13.41	106	196	Idle	41.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.72	14.39	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:40:1	20.45	3350	1.89	13.43	106	196	Idle	40.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.73	14.3	0.97	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:1	20.45	3342	1.85	13.44	106	196	Idle	40	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.71	14.16	0.96	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:1	20.45	3286	1.81	13.44	106	196	Idle	39.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.67	14.12	0.96	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:1	20.45	3268	1.78	13.43	106	196	Idle	38.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.67	13.96	0.95	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:1	20.45	3231	1.76	13.44	106	196	Idle	37.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.64	13.89	0.95	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:1	20.45	3231	1.74	13.43	106	196	Idle	36.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.6	13.83	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:1	20.45	3168	1.73	13.42	106	196	Idle	35.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.55	13.78	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:2	20.45	3158	1.74	13.42	106	196	Idle	34.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.48	13.74	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:2	20.45	3158	1.74	13.41	106	196	Idle	33.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.46	13.73	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:2	20.45	3120	1.75	13.41	106	196	Idle	32.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.43	13.73	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:2	20.45	3070	1.75	13.41	106	196	Idle	31.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.37	13.75	0.94	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:2	20.45	3060	1.75	13.41	106	196	Idle	30.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.35	13.82	0.94	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:2	20.45	3050	1.76	13.41	106	196	Idle	29.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.28	13.9	0.95	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:3	20.45	2966	1.77	13.41	106	196	Idle	28.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.24	13.98	0.95	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:3	20.45	2980	1.77	13.42	106	196	Idle	27.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	14.09	0.96	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:3	20.45	2972	1.78	13.41	106	196	Idle	27.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.17	14.26	0.97	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:3	20.45	2942	1.78	13.41	106	196	Idle	26.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.13	14.61	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:3	20.45	2900	1.79	13.42	106	196	Idle	25.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	14.94	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:3	19.09	2864	1.8	13.41	106	196	Idle	25.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	15.4	1.05	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:4	19.09	2868	1.8	13.41	106	196	Idle	25	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.06	15.98	1.09	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:4	19.09	2847	1.81	13.41	106	196	Idle	25	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.03	16.58	1.13	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:4	19.09	2800	1.82	13.41	106	196	Idle	24.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.95	17.17	1.17	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:4	19.09	2803	1.82	13.41	106	196	Idle	24.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	17.74	1.21	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:4	19.09	2780	1.83	13.41	106	196	Idle	24.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.91	18.31	1.25	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:4	19.09	2740	1.84	13.41	106	196	Idle	24.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.88	18.57	1.27	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:4	19.09	2707	1.84	13.4	106	196	Idle	24.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.88	19.28	1.31	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:5	19.09	2707	1.84	13.41	106	196	Idle	25.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.89	19.69	1.34	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:5	19.09	2675	1.84	13.41	106	196	Idle	25.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.86	20	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:5	19.09	2641	1.84	13.41	106	196	Idle	26.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.81	20.18	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:5	19.09	2641	1.84	13.41	106	196	Idle	26.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.84	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:5	19.09	2608	1.84	13.42	106	196	Idle	28.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.81	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:5	19.09	2592	1.84	13.41	106	196	Idle	29.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.77	20.25	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:6	19.09	2584	1.84	13.41	106	196	Idle	30.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.8	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:6	19.09	2540	1.84	13.41	106	196	Full Load	31.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.76	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:6	19.09	2524	1.84	13.4	106	196	Off Idle	32.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.73	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:6	19.09	2470	1.83	13.39	106	196	Off Idle	33.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.25	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:6	19.09	2473	1.83	13.4	106	196	Off Idle	35.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.65	20.25	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:6	19.09	2386	1.83	13.41	106	196	Off Idle	36.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.64	20.25	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:40:6	9.54	2386	1.83	13.39	106	196	Off Idle	37.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.57	20.25	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:40:7	9.54	2400	1.83	13.4	106	196	Off Idle	40.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.5	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:17:40:7	12.27	2402	1.83	13.38	106	196	Off Idle	42.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.41	20.24	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:40:7	14.99	2380	1.83	13.38	106	196	Off Idle	45.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.31	20.24	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:40:7	17.72	2368	1.83	13.39	106	196	Off Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.19	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:40:7	17.72	2316	1.83	13.38	106	196	Off Idle	50.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.14	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:40:7	20.45	2276	1.83	13.38	106	196	Off Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.04	20.24	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:40:8	20.45	2263	1.84	13.4	106	196	Off Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.94	20.25	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:40:8	23.18	2219	1.85	13.39	106	196	Off Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.79	20.25	1.38	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:40:8	23.18	2152	1.86	13.38	106	196	Off Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.65	20.25	1.38	3.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:8	25.9	2130	1.86	13.37	106	196	Off Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.54	20.25	1.38	3.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:8	28.63	2130	1.86	13.38	106	196	Off Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.45	20.25	1.38	3.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:8	28.63	2098	1.86	13.37	106	196	Off Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.36	20.25	1.38	3.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:40:9	31.36	2086	1.86	13.38	106	196	Off Idle	75.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.28	20.25	1.38	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:40:9	31.36	2076	1.87	13.41	106	196	Off Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.2	20.25	1.38	3.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:40:9	32.72	2080	1.87	13.41	106	196	Off Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.16	20.26	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:40:9	32.72	2098	1.88	13.42	106	196	Off Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.06	20.25	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:40:9	32.72	2122	1.9	13.41	106	196	Off Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.92	20.25	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:40:9	32.72	2122	1.92	13.4	106	196	Off Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.74	20.25	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:40:9	32.72	2143	1.95	13.39	106	196	Off Idle	83.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.33	20.25	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:41:0	32.72	2161	1.97	13.38	106	196	Off Idle	84.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6	20.26	1.38	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:41:0	32.72	2172	2	13.37	107	196	Off Idle	84.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.7	20.25	1.38	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:0	32.72	2176	2.02	13.36	107	196	Off Idle	84.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.32	20.25	1.38	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:0	32.72	2190	2.05	13.37	107	196	Off Idle	85.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.01	20.26	1.38	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:0	31.36	2217	2.07	13.4	106	196	Off Idle	85.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.76	20.25	1.38	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:0	31.36	2217	2.1	13.41	106	196	Off Idle	85.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.56	20.21	1.38	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:1	31.36	2234	2.12	13.41	106	196	Off Idle	85.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.4	20.05	1.37	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:1	31.36	2276	2.14	13.41	106	196	Off Idle	84.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.32	19.8	1.35	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:1	31.36	2276	2.16	13.41	106	196	Off Idle	84	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.16	19.31	1.32	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:1	31.36	2227	2.18	13.39	106	196	Off Idle	83.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.13	18.98	1.29	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:1	31.36	2208	2.21	13.38	106	196	Off Idle	83.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.07	18.66	1.27	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:1	31.36	2163	2.23	13.38	106	196	Off Idle	83.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4	18.35	1.25	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:1	31.36	2163	2.25	13.39	106	196	Off Idle	83.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.92	18.2	1.24	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:2	31.36	2153	2.29	13.4	106	196	Off Idle	83.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.89	17.73	1.21	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:2	31.36	2149	2.31	13.41	106	196	Off Idle	83.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.75	17.36	1.18	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:2	31.36	2153	2.33	13.41	106	196	Off Idle	83.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.75	17.06	1.16	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:2	31.36	2153	2.34	13.42	106	196	Off Idle	83.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.77	16.82	1.15	3.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:2	31.36	2156	2.34	13.42	106	196	Off Idle	83.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.76	16.64	1.13	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:2	29.99	2194	2.34	13.41	107	196	Off Idle	83.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.73	16.53	1.13	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:3	29.99	2194	2.34	13.41	107	196	Off Idle	83.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.73	16.35	1.11	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:3	29.99	2221	2.33	13.41	107	195	Off Idle	83.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.73	16.13	1.1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:41:3	29.99	2231	2.33	13.42	106	195	Off Idle	83.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.74	15.89	1.08	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:41:3	29.99	2234	2.33	13.41	106	195	Off Idle	83.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.74	15.52	1.06	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:41:3	29.99	2241	2.33	13.4	106	196	Off Idle	84	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.77	15.3	1.04	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:41:3	29.99	2256	2.33	13.4	106	196	Off Idle	84	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.77	15.13	1.03	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:4	31.36	2232	2.33	13.39	106	196	Off Idle	83.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.76	15.01	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:4	31.36	2228	2.33	13.37	106	196	Off Idle	83.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.72	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:4	31.36	2220	2.33	13.38	106	196	Off Idle	83.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.71	14.8	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:4	31.36	2218	2.33	13.39	106	196	Off Idle	83.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.68	14.72	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:4	31.36	2211	2.33	13.39	106	196	Off Idle	83.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.7	14.68	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:4	31.36	2226	2.33	13.39	107	196	Off Idle	83	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.71	14.69	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:4	31.36	2230	2.33	13.39	107	196	Off Idle	82.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.72	14.69	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:5	31.36	2234	2.33	13.39	107	196	Off Idle	82.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.72	14.7	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:5	31.36	2237	2.33	13.39	106	196	Off Idle	82.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.72	14.73	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:5	31.36	2263	2.33	13.39	106	196	Off Idle	82.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.68	14.74	1	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:5	31.36	2257	2.34	13.39	106	196	Off Idle	81.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.66	14.75	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:41:5	31.36	2257	2.35	13.4	106	196	Off Idle	81.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-3.61	14.77	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:5	31.36	2276	2.35	13.41	106	196	Off Idle	81.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-3.62	14.77	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:6	31.36	2281	2.36	13.41	106	196	Off Idle	81.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-3.57	14.8	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:6	31.36	2281	2.36	13.4	106	196	Off Idle	80.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.53	14.82	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:6	31.36	2264	2.37	13.38	106	196	Off Idle	80.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.51	14.85	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:41:6	31.36	2267	2.37	13.37	106	196	Off Idle	80.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.41	14.88	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:41:6	31.36	2267	2.38	13.38	106	196	Off Idle	80.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.38	14.89	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:41:6	31.36	2277	2.38	13.4	106	196	Off Idle	80.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-3.34	14.91	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:41:6	31.36	2277	2.38	13.4	106	196	Off Idle	80.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.28	14.96	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:41:7	31.36	2283	2.39	13.39	106	196	Off Idle	79.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.22	14.97	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:41:7	31.36	2287	2.39	13.41	106	196	Off Idle	79.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-3.26	15.02	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:7	31.36	2290	2.4	13.39	106	196	Off Idle	79.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-3.28	15.06	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:7	31.36	2293	2.4	13.4	106	196	Off Idle	79.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.24	15.08	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:7	31.36	2300	2.4	13.4	106	196	Off Idle	79.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.3	15.09	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:7	31.36	2306	2.41	13.4	106	196	Off Idle	79	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.29	15.12	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:8	31.36	2307	2.41	13.41	106	196	Off Idle	78.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.32	15.13	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:8	31.36	2310	2.42	13.4	106	196	Off Idle	78.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.37	15.12	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:8	31.36	2312	2.42	13.39	107	196	Off Idle	78.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.38	15.09	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:41:8	31.36	2320	2.42	13.39	107	196	Off Idle	78.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.34	15.06	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:8	31.36	2320	2.42	13.39	107	196	Off Idle	78.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.22	15.01	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:8	31.36	2332	2.42	13.39	106	196	Off Idle	78.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.19	14.96	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:9	31.36	2332	2.43	13.4	106	196	Off Idle	78	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.17	14.9	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:41:9	31.36	2337	2.44	13.4	106	196	Off Idle	77.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.08	14.85	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:41:9	31.36	2337	2.45	13.41	106	196	Off Idle	77.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.97	14.79	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:41:9	31.36	2339	2.46	13.4	106	196	Off Idle	77.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.88	14.74	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:17:41:9	31.36	2327	2.47	13.41	106	196	Off Idle	77	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.63	14.7	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:17:41:9	31.36	2330	2.48	13.41	107	196	Off Idle	76.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.56	14.69	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:41:9	31.36	2348	2.49	13.39	107	196	Off Idle	76.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.44	14.69	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:0	31.36	2356	2.5	13.39	107	196	Off Idle	76.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-2.33	14.7	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:17:42:0	31.36	2378	2.51	13.41	107	196	Off Idle	76.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.3	14.7	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:17:42:0	31.36	2378	2.52	13.4	107	196	Off Idle	75.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-2.27	14.7	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:17:42:0	31.36	2371	2.52	13.4	107	196	Off Idle	75.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.23	14.71	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:17:42:0	31.36	2379	2.53	13.42	107	196	Off Idle	75.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-2.22	14.76	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:17:42:0	31.36	2380	2.54	13.42	107	196	Off Idle	74.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-2.24	14.82	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:17:42:1	31.36	2390	2.55	13.41	107	196	Off Idle	74.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.22	14.87	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:1	31.36	2396	2.56	13.41	107	196	Off Idle	74.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-2.18	14.92	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:1	31.36	2398	2.57	13.4	107	196	Off Idle	74	0	2	132	944 Turbo	0.4	Lean	1	14.6	-2.18	14.96	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:1	31.36	2401	2.58	13.4	107	196	Off Idle	73.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-2.2	15.02	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:1	31.36	2400	2.59	13.4	107	196	Off Idle	73.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-2.17	15.04	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:1	31.36	2401	2.59	13.4	107	196	Off Idle	73.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.16	15.04	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:1	31.36	2401	2.6	13.4	107	196	Off Idle	73.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.16	15.04	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:2	31.36	2402	2.6	13.4	107	196	Off Idle	72.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.17	15.01	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:2	31.36	2405	2.6	13.41	107	196	Off Idle	72.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.16	14.94	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:2	31.36	2405	2.6	13.4	107	196	Off Idle	72.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.13	14.84	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:2	31.36	2413	2.6	13.4	106	196	Off Idle	72.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.16	14.69	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:2	31.36	2420	2.6	13.4	106	196	Off Idle	72.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.13	14.48	0.99	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:2	31.36	2431	2.61	13.4	107	196	Off Idle	72.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.14	14.35	0.98	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:3	31.36	2432	2.61	13.41	107	196	Off Idle	72	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.12	14.2	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:3	31.36	2448	2.61	13.4	107	196	Off Idle	71.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.17	14.1	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:3	31.36	2446	2.61	13.4	107	196	Off Idle	71.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.15	14.04	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:3	31.36	2446	2.61	13.39	107	196	Off Idle	71.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.16	14.01	0.95	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:3	31.36	2451	2.62	13.4	107	196	Off Idle	71.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.15	14	0.95	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:3	31.36	2476	2.62	13.4	107	196	Off Idle	70.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.15	14.02	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:4	32.72	2460	2.62	13.41	107	196	Off Idle	70.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.13	14.06	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:4	32.72	2461	2.62	13.41	107	196	Off Idle	70.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.12	14.11	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:4	32.72	2468	2.63	13.41	107	196	Off Idle	70.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.09	14.16	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:4	31.36	2458	2.63	13.41	107	196	Off Idle	69.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.08	14.19	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:4	31.36	2470	2.63	13.41	107	196	Off Idle	69.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.07	14.23	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:4	31.36	2484	2.63	13.41	107	196	Off Idle	69.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.12	14.25	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:4	31.36	2488	2.63	13.41	107	196	Off Idle	69	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.13	14.28	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:5	31.36	2532	2.64	13.41	107	196	Off Idle	68.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.11	14.3	0.97	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:5	32.72	2532	2.64	13.4	107	196	Off Idle	68.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.07	14.33	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:5	32.72	2498	2.64	13.41	107	195	Off Idle	68.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.08	14.34	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:5	32.72	2506	2.65	13.39	107	195	Off Idle	67.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.04	14.35	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:5	32.72	2507	2.65	13.41	107	195	Off Idle	67.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.08	14.37	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:5	32.72	2514	2.65	13.4	107	196	Off Idle	67.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.09	14.4	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:6	32.72	2517	2.66	13.4	106	196	Off Idle	67.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.07	14.4	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:6	32.72	2519	2.66	13.39	106	196	Off Idle	67.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.07	14.42	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:6	32.72	2518	2.66	13.41	106	196	Off Idle	67.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.08	14.44	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:6	32.72	2515	2.67	13.4	107	196	Off Idle	66.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.06	14.47	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:6	32.72	2512	2.67	13.4	107	196	Off Idle	66.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.08	14.5	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:6	32.72	2512	2.67	13.4	107	196	Off Idle	66.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.07	14.5	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:6	32.72	2506	2.67	13.4	107	196	Off Idle	66.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.05	14.51	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:7	32.72	2506	2.68	13.39	107	196	Off Idle	65.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.96	14.52	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:17:42:7	31.36	2506	2.68	13.38	107	195	Off Idle	65.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.95	14.53	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:7	31.36	2515	2.68	13.4	106	195	Off Idle	65.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.92	14.53	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:7	31.36	2529	2.68	13.41	106	195	Off Idle	65.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.96	14.54	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:7	31.36	2529	2.68	13.39	106	196	Off Idle	65.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.95	14.53	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:7	31.36	2547	2.69	13.39	107	196	Off Idle	65.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.97	14.52	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:8	31.36	2559	2.69	13.41	107	196	Off Idle	65.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.02	14.51	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:42:8	31.36	2559	2.69	13.41	107	196	Off Idle	65.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.03	14.51	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:8	31.36	2567	2.69	13.4	107	196	Off Idle	65.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2	14.52	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:8	31.36	2573	2.69	13.37	107	196	Off Idle	64.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.02	14.53	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:8	32.72	2573	2.69	13.39	107	196	Off Idle	64.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.02	14.54	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:8	32.72	2587	2.7	13.41	107	196	Off Idle	64.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2	14.55	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:9	32.72	2590	2.7	13.39	107	196	Off Idle	64.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.01	14.58	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:17:42:9	32.72	2593	2.7	13.4	107	196	Off Idle	64.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.04	14.61	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:17:42:9	32.72	2612	2.7	13.41	107	196	Off Idle	63.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.06	14.63	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:17:42:9	32.72	2602	2.7	13.39	107	196	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.07	14.65	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:17:42:9	32.72	2590	2.7	13.38	107	196	Off Idle	63	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.08	14.67	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:17:42:9	32.72	2584	2.7	13.4	107	196	Off Idle	62.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.11	14.68	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:17:42:9	32.72	2584	2.7	13.39	107	196	Off Idle	62.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.16	14.7	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:17:43:0	32.72	2579	2.7	13.39	107	196	Off Idle	62.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.17	14.72	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:17:43:0	32.72	2580	2.69	13.39	107	196	Off Idle	62.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.24	14.73	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:43:0	32.72	2580	2.69	13.4	107	196	Off Idle	62.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.33	14.74	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:43:0	32.72	2590	2.69	13.4	107	196	Off Idle	61.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.44	14.75	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:0	32.72	2596	2.68	13.39	107	196	Off Idle	61.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.5	14.76	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:0	32.72	2601	2.68	13.4	107	196	Off Idle	61.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.52	14.77	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:1	32.72	2601	2.68	13.42	107	196	Off Idle	61.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.63	14.78	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:1	32.72	2604	2.67	13.41	107	196	Off Idle	61.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.74	14.79	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:1	32.72	2613	2.67	13.42	107	196	Off Idle	60.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.84	14.8	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:1	32.72	2616	2.66	13.41	107	196	Off Idle	61	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.89	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:1	32.72	2622	2.66	13.41	107	196	Off Idle	60.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.97	14.83	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:17:43:1	32.72	2625	2.65	13.39	107	196	Off Idle	60.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:1	32.72	2632	2.64	13.4	107	196	Off Idle	60.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-3	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:2	32.72	2634	2.64	13.4	107	196	Off Idle	60.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-3.03	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:2	32.72	2648	2.63	13.41	107	196	Off Idle	60.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-3.12	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:2	32.72	2656	2.63	13.41	107	195	Off Idle	59.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-3.13	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:2	32.72	2666	2.62	13.41	107	195	Off Idle	59.4	0	2	132	944 Turbo	0.16	Rich	1	14.6	-3.2	14.9	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:2	32.72	2662	2.61	13.4	106	195	Off Idle	59.1	0	2	132	944 Turbo	0.13	Rich	1	14.6	-3.26	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:2	32.72	2655	2.61	13.41	106	196	Off Idle	58.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.31	14.98	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:3	32.72	2658	2.61	13.41	106	196	Off Idle	58.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.29	15.01	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:3	32.72	2658	2.61	13.41	107	196	Off Idle	58.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.3	15.04	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:3	32.72	2656	2.61	13.41	107	196	Off Idle	58.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.31	15.07	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:3	32.72	2656	2.6	13.4	107	196	Off Idle	58.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.34	15.09	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:3	32.72	2656	2.6	13.41	107	196	Off Idle	58.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.35	15.16	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:3	32.72	2654	2.6	13.4	107	196	Off Idle	58.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.38	15.2	1.04	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:4	32.72	2654	2.6	13.39	107	196	Off Idle	57.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.39	15.19	1.04	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:4	32.72	2662	2.6	13.41	107	196	Off Idle	57.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.46	15.19	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:4	32.72	2660	2.6	13.41	107	196	Off Idle	57.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.45	15.19	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:4	32.72	2662	2.6	13.4	107	196	Off Idle	57.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.44	15.18	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:4	32.72	2664	2.6	13.41	107	196	Off Idle	57.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.5	15.17	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:4	32.72	2660	2.6	13.41	107	196	Off Idle	57.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.5	15.15	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:4	32.72	2660	2.6	13.41	107	196	Off Idle	57.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.45	15.14	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:5	32.72	2662	2.6	13.41	107	196	Off Idle	57.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-3.52	15.13	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:5	32.72	2664	2.6	13.41	107	196	Off Idle	57.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.53	15.11	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:5	32.72	2666	2.6	13.4	107	196	Off Idle	57.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.52	15.09	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:5	32.72	2673	2.6	13.41	107	196	Off Idle	57.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.57	15.08	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:5	32.72	2680	2.6	13.39	107	196	Off Idle	57.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.58	15.08	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:5	32.72	2680	2.59	13.39	107	196	Off Idle	57	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.57	15.05	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:43:6	32.72	2681	2.59	13.41	107	196	Off Idle	56.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.59	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:43:6	32.72	2690	2.59	13.41	107	196	Off Idle	56.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.61	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:43:6	32.72	2692	2.59	13.41	107	196	Off Idle	56.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-3.6	15.05	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:43:6	32.72	2692	2.59	13.41	107	196	Off Idle	56.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.62	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:43:6	32.72	2697	2.59	13.41	107	196	Off Idle	56.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.6	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:43:6	32.72	2702	2.59	13.4	107	196	Off Idle	56.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.62	15.04	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:43:6	32.72	2694	2.59	13.39	107	196	Off Idle	56.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.58	15.02	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:43:7	32.72	2696	2.59	13.41	107	196	Off Idle	56.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-3.58	14.99	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:43:7	32.72	2699	2.59	13.39	107	196	Off Idle	56	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.58	14.97	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:7	32.72	2699	2.59	13.4	107	195	Off Idle	55.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-3.63	14.96	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:7	32.72	2705	2.59	13.4	107	195	Off Idle	55.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.66	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:7	32.72	2720	2.59	13.4	107	195	Off Idle	55.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.65	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:7	32.72	2727	2.59	13.39	107	196	Off Idle	55.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.69	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:8	32.72	2727	2.59	13.39	107	196	Off Idle	55.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.69	14.91	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:8	32.72	2753	2.59	13.39	107	196	Off Idle	54.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.62	14.94	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:8	32.72	2735	2.6	13.39	107	196	Off Idle	54.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.63	15	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:8	32.72	2733	2.6	13.4	107	196	Off Idle	54.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.62	15.05	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:43:8	32.72	2733	2.6	13.39	107	196	Off Idle	54.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.62	15.07	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:43:8	32.72	2759	2.6	13.39	107	196	Off Idle	54	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.61	15.12	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:43:9	34.08	2737	2.6	13.41	107	196	Off Idle	54	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.62	15.17	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:43:9	34.08	2737	2.6	13.4	107	196	Off Idle	54	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.58	15.17	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:43:9	34.08	2740	2.61	13.39	107	196	Off Idle	53.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-3.57	15.21	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:43:9	34.08	2746	2.61	13.4	107	196	Off Idle	53.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-3.58	15.26	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:43:9	34.08	2752	2.61	13.41	107	196	Off Idle	53.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.56	15.27	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:43:9	34.08	2753	2.61	13.41	107	196	Off Idle	53.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.6	15.24	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:17:43:9	34.08	2763	2.61	13.41	107	196	Off Idle	53.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.58	15.19	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:44:0	34.08	2772	2.61	13.39	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.61	15.13	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:44:0	34.08	2773	2.61	13.39	107	196	Off Idle	52.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.62	15.1	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:44:0	34.08	2778	2.61	13.4	107	196	Off Idle	52.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.62	15.06	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:0	34.08	2794	2.62	13.4	107	196	Off Idle	52.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.62	15	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:0	34.08	2794	2.62	13.4	107	196	Off Idle	52.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.64	14.96	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:0	34.08	2803	2.62	13.41	107	196	Off Idle	52.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.59	14.9	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:1	34.08	2835	2.62	13.41	107	196	Off Idle	52.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.58	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:1	34.08	2815	2.63	13.42	107	196	Off Idle	51.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-3.6	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:1	34.08	2815	2.63	13.43	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.57	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:1	34.08	2821	2.63	13.41	107	196	Off Idle	51.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.53	14.9	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:1	34.08	2819	2.63	13.41	107	196	Off Idle	50.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.55	14.94	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:1	34.08	2819	2.64	13.42	107	196	Off Idle	50.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-3.52	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:1	34.08	2823	2.64	13.42	107	196	Off Idle	50.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-3.5	15.03	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:2	34.08	2826	2.64	13.41	107	196	Off Idle	50	0	2	132	944 Turbo	0.17	Lean	1	14.6	-3.53	15.06	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:2	34.08	2826	2.64	13.41	107	196	Off Idle	49.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.52	15.1	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:2	34.08	2833	2.64	13.4	107	196	Off Idle	49.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-3.55	15.13	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:2	34.08	2834	2.65	13.4	107	196	Off Idle	49.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-3.55	15.13	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:2	34.08	2834	2.65	13.41	107	196	Off Idle	49	0	2	132	944 Turbo	0.38	Rich	1	14.6	-3.57	15.13	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:2	34.08	2840	2.65	13.41	107	196	Off Idle	48.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.58	15.13	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:3	34.08	2844	2.65	13.41	107	196	Off Idle	48.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-3.58	15.13	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:3	34.08	2848	2.66	13.41	107	196	Off Idle	48	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.61	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:44:3	34.08	2851	2.66	13.41	107	196	Off Idle	47.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.58	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:44:3	34.08	2858	2.66	13.4	107	196	Off Idle	47.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.53	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:44:3	34.08	2856	2.66	13.41	107	196	Off Idle	47.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.55	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:44:3	34.08	2852	2.67	13.39	107	196	Off Idle	47.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.54	15.03	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:44:4	34.08	2856	2.67	13.41	107	196	Off Idle	47.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-3.51	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:4	34.08	2859	2.67	13.4	107	196	Off Idle	47.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.52	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:4	34.08	2878	2.67	13.4	107	196	Off Idle	47.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.57	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:4	34.08	2878	2.67	13.41	107	196	Off Idle	47	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.63	14.9	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:4	34.08	2898	2.67	13.41	107	196	Off Idle	46.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.66	14.87	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:4	34.08	2892	2.66	13.4	107	196	Off Idle	46.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.79	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:17:44:4	34.08	2890	2.66	13.39	107	196	Off Idle	46.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.84	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:5	34.08	2890	2.65	13.4	107	196	Off Idle	46.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.92	14.91	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:17:44:5	34.08	2889	2.65	13.39	107	196	Off Idle	46.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.03	14.97	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:17:44:5	34.08	2890	2.64	13.4	107	196	Off Idle	46.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.06	14.98	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:44:5	34.08	2892	2.63	13.39	107	196	Off Idle	46	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.21	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:5	34.08	2896	2.63	13.39	107	196	Off Idle	45.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.26	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:5	34.08	2898	2.63	13.39	107	196	Off Idle	45.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.39	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:6	34.08	2898	2.62	13.39	107	196	Off Idle	45.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.4	15.18	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:44:6	34.08	2898	2.62	13.39	107	196	Off Idle	45.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.47	15.18	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:44:6	34.08	2897	2.61	13.4	107	196	Off Idle	45	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.51	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:44:6	34.08	2897	2.6	13.41	107	196	Off Idle	44.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.51	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:44:6	34.08	2900	2.59	13.41	107	196	Off Idle	44.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.58	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:44:6	34.08	2906	2.59	13.4	107	196	Off Idle	44.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.6	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:6	34.08	2921	2.58	13.41	107	196	Off Idle	44.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.6	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:7	34.08	2921	2.58	13.39	107	196	Off Idle	44.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.62	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:7	34.08	2940	2.56	13.4	107	196	Off Idle	44.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.66	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:7	34.08	2949	2.56	13.41	107	196	Off Idle	44.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.71	14.68	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:7	34.08	2977	2.55	13.4	107	196	Off Idle	43.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.78	14.65	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:7	34.08	2964	2.54	13.42	107	196	Off Idle	43.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.84	14.68	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:7	34.08	2946	2.54	13.42	107	196	Off Idle	43.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.87	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:8	34.08	2945	2.54	13.42	107	196	Off Idle	43.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.87	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:8	34.08	2945	2.54	13.41	107	196	Off Idle	43.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.9	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:8	34.08	2943	2.54	13.41	107	196	Off Idle	42.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.88	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:8	34.08	2940	2.54	13.42	107	196	Off Idle	42.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.91	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:8	34.08	2947	2.54	13.42	107	196	Off Idle	42.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.9	15.14	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:8	34.08	2947	2.54	13.4	107	196	Off Idle	42.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.88	15.19	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:9	34.08	2965	2.53	13.41	107	196	Off Idle	42.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.87	15.25	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:9	34.08	2961	2.53	13.4	107	196	Off Idle	42	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.87	15.32	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:9	34.08	2971	2.53	13.4	107	196	Off Idle	41.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.91	15.32	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:9	34.08	2974	2.53	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.91	15.32	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:9	34.08	2982	2.53	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.97	15.3	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:9	34.08	2983	2.53	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.99	15.27	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:44:9	34.08	2986	2.53	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.98	15.25	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:0	34.08	2996	2.53	13.39	106	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.03	15.25	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:0	34.08	2996	2.53	13.41	106	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.03	15.25	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:0	34.08	2994	2.53	13.39	106	196	Off Idle	41.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.08	15.25	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:0	34.08	3002	2.53	13.39	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.05	15.25	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:0	34.08	2980	2.54	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.08	15.26	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:0	35.45	2976	2.54	13.39	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.07	15.24	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:1	35.45	2988	2.54	13.39	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.04	15.21	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:1	35.45	2988	2.54	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.08	15.22	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:1	35.45	2995	2.53	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.07	15.21	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:1	35.45	2999	2.53	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.09	15.18	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:1	35.45	3000	2.53	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.08	15.16	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:1	35.45	3006	2.53	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.11	15.14	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:1	35.45	3012	2.53	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.17	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:2	35.45	3014	2.53	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.17	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:2	35.45	3018	2.53	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.2	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:2	35.45	3032	2.53	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.24	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:2	35.45	3025	2.53	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.23	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:2	35.45	3025	2.53	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.24	15.1	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:2	35.45	3023	2.53	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.24	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:3	35.45	3024	2.53	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.29	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:3	35.45	3021	2.52	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.25	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:3	35.45	3018	2.52	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.28	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:3	35.45	3025	2.52	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.29	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:45:3	35.45	3031	2.52	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.3	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:3	35.45	3034	2.52	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.34	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:4	35.45	3045	2.51	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.35	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:4	35.45	3041	2.51	13.41	107	195	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.35	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:4	35.45	3072	2.51	13.41	107	195	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.35	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:4	35.45	3062	2.51	13.41	107	195	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.37	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:4	35.45	3052	2.51	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.41	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:4	35.45	3057	2.51	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.43	15.02	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:4	35.45	3057	2.5	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.45	15.05	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:5	35.45	3038	2.5	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.54	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:45:5	35.45	3059	2.5	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.55	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:45:5	35.45	3061	2.5	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.6	15.21	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:5	35.45	3065	2.5	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.68	15.24	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:45:5	35.45	3075	2.5	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.68	15.25	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:5	35.45	3064	2.49	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.74	15.24	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:6	35.45	3063	2.49	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.73	15.23	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:45:6	35.45	3063	2.49	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.73	15.22	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:45:6	35.45	3074	2.48	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.71	15.19	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:45:6	35.45	3065	2.48	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.78	15.16	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:6	35.45	3063	2.47	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.83	15.12	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:6	35.45	3062	2.47	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.88	15.09	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:6	35.45	3065	2.47	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.91	15.04	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:7	35.45	3065	2.46	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.94	15	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:7	35.45	3068	2.46	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.93	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:7	35.45	3092	2.45	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.93	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:7	35.45	3086	2.45	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.95	14.93	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:7	35.45	3088	2.45	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.96	14.94	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:7	35.45	3093	2.44	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.98	14.95	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:8	35.45	3095	2.44	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.02	14.97	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:8	35.45	3095	2.44	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.07	15.01	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:8	35.45	3095	2.43	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.05	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:8	35.45	3097	2.43	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.1	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:8	35.45	3098	2.43	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.09	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:8	35.45	3112	2.42	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.09	15.14	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:9	35.45	3101	2.42	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.12	15.15	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:9	35.45	3101	2.42	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.15	15.13	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:45:9	35.45	3102	2.42	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.14	15.11	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:45:9	35.45	3104	2.42	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.16	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:45:9	35.45	3106	2.42	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.12	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:45:9	35.45	3104	2.42	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.12	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:45:9	35.45	3102	2.42	13.39	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.13	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:46:0	35.45	3101	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.12	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:46:0	35.45	3099	2.42	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.09	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:46:0	35.45	3104	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.13	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:46:0	35.45	3106	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.09	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:46:0	35.45	3107	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.06	15.01	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:0	35.45	3107	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.05	15	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:1	35.45	3110	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.12	14.98	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:1	35.45	3122	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.12	14.96	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:1	35.45	3132	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.2	14.91	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:1	35.45	3134	2.42	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.23	14.87	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:1	35.45	3142	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.25	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:1	35.45	3144	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.22	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:1	35.45	3149	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.28	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:2	35.45	3150	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.28	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:2	35.45	3152	2.41	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.33	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:46:2	35.45	3145	2.41	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.35	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:46:2	35.45	3142	2.41	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.41	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:46:2	35.45	3136	2.4	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.44	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:46:2	35.45	3130	2.4	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.47	15.2	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:46:3	35.45	3130	2.4	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.54	15.23	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:46:3	35.45	3124	2.39	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.56	15.22	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:46:3	35.45	3123	2.38	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.64	15.2	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:3	35.45	3147	2.38	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.65	15.17	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:3	36.81	3147	2.37	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.72	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:3	36.81	3128	2.36	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.73	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:4	36.81	3155	2.36	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.75	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:4	36.81	3155	2.35	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.78	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:4	36.81	3142	2.35	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.82	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:46:4	36.81	3147	2.34	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.85	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:4	36.81	3150	2.34	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.85	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:4	36.81	3132	2.33	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.91	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:4	36.81	3160	2.32	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.92	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:5	36.81	3161	2.32	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.94	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:5	36.81	3164	2.31	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.96	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:5	36.81	3188	2.31	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.99	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:5	36.81	3160	2.3	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:5	36.81	3160	2.3	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.08	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:5	36.81	3159	2.3	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.01	14.9	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:6	36.81	3158	2.3	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.05	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:6	36.81	3156	2.29	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.01	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:6	36.81	3154	2.29	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.03	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:6	36.81	3154	2.29	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.01	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:6	36.81	3155	2.29	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.08	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:6	36.81	3144	2.29	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.04	15.16	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:6	36.81	3157	2.29	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.06	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:7	36.81	3167	2.29	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.07	15.19	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:7	36.81	3167	2.29	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.1	15.17	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:7	36.81	3180	2.29	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.09	15.15	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:7	36.81	3167	2.29	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.15	15.13	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:7	36.81	3166	2.29	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.14	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:7	36.81	3166	2.29	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.14	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:8	36.81	3151	2.29	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.16	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:8	36.81	3161	2.29	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.13	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:8	36.81	3161	2.29	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.15	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:8	36.81	3158	2.29	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.11	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:8	36.81	3161	2.29	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.15	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:8	36.81	3162	2.28	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.11	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:9	36.81	3170	2.28	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.09	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:9	36.81	3175	2.28	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.09	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:9	36.81	3176	2.28	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.1	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:9	36.81	3184	2.28	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.1	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:9	36.81	3188	2.28	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.13	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:46:9	36.81	3189	2.28	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.15	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:46:9	36.81	3189	2.28	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.11	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:0	36.81	3187	2.28	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.18	14.9	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:0	36.81	3182	2.28	13.44	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.16	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:0	36.81	3179	2.28	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.16	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:0	36.81	3178	2.28	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.12	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:0	36.81	3172	2.28	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.16	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:0	36.81	3172	2.28	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.16	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:1	36.81	3172	2.28	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.19	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:1	36.81	3179	2.28	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.16	15.13	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:1	36.81	3185	2.28	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.2	15.12	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:1	36.81	3190	2.28	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.18	15.09	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:47:1	36.81	3190	2.28	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.17	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:47:1	36.81	3194	2.28	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.17	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:1	36.81	3196	2.28	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.21	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:2	36.81	3196	2.28	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.19	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:2	36.81	3196	2.28	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.22	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:2	36.81	3200	2.27	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.28	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:2	36.81	3200	2.27	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.23	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:47:2	36.81	3200	2.27	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.24	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:47:2	36.81	3200	2.27	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.26	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:3	36.81	3200	2.27	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.27	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:3	36.81	3198	2.27	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.3	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:47:3	36.81	3190	2.26	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.33	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:47:3	36.81	3190	2.26	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.36	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:3	36.81	3186	2.26	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.39	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:3	36.81	3184	2.26	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.44	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:4	36.81	3177	2.25	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.46	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:4	36.81	3178	2.25	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.47	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:4	36.81	3178	2.25	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.45	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:4	36.81	3187	2.24	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.48	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:4	36.81	3199	2.24	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.45	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:4	36.81	3199	2.24	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.53	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:4	36.81	3205	2.24	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.53	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:5	36.81	3212	2.24	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.57	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:5	36.81	3214	2.23	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.58	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:5	36.81	3220	2.23	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.59	14.79	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:5	36.81	3222	2.23	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.6	14.76	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:5	36.81	3222	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.62	14.76	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:5	36.81	3234	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.64	14.74	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:6	36.81	3219	2.22	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.64	14.74	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:6	36.81	3215	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.69	14.75	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:6	36.81	3208	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.69	14.77	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:6	36.81	3200	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.68	14.79	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:6	36.81	3200	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.64	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:6	36.81	3195	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.61	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:6	36.81	3191	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.62	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:7	36.81	3192	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.63	14.9	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:7	36.81	3200	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.67	14.94	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:7	36.81	3204	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:7	36.81	3207	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:7	36.81	3200	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:7	36.81	3217	2.21	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.68	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:8	36.81	3223	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.63	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:8	36.81	3224	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.64	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:8	36.81	3222	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.64	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:8	36.81	3219	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.6	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:8	36.81	3219	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.65	14.9	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:8	36.81	3220	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.65	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:9	36.81	3225	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.64	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:9	36.81	3226	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.66	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:9	36.81	3224	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.65	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:9	36.81	3226	2.21	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.17	Rich	1	14.6	-7.65	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:47:9	36.81	3277	2.21	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.68	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:9	36.81	3252	2.21	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.66	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:47:9	36.81	3227	2.21	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.67	14.91	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:0	36.81	3224	2.21	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.67	14.93	1.02	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:0	36.81	3224	2.21	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.68	14.96	1.02	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:0	36.81	3196	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.67	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:0	36.81	3221	2.21	13.39	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.68	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:0	36.81	3221	2.21	13.4	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:0	36.81	3222	2.21	13.41	107	196	Off Idle	41.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.66	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:1	36.81	3222	2.21	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.64	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:1	36.81	3222	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.66	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:1	36.81	3227	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.62	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:1	36.81	3227	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.64	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:1	36.81	3244	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.67	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:1	36.81	3236	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.65	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:1	36.81	3236	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.65	14.96	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:2	36.81	3234	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.64	14.9	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:2	36.81	3232	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:2	36.81	3232	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.65	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:48:2	36.81	3231	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.67	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:2	36.81	3228	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.69	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:2	36.81	3226	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.68	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:3	36.81	3226	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.65	14.9	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:3	36.81	3222	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.68	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:3	36.81	3221	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.65	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:3	36.81	3221	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:3	36.81	3237	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:3	36.81	3238	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	15.06	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:4	36.81	3242	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.06	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:4	36.81	3242	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:4	36.81	3234	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:4	36.81	3241	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:4	36.81	3238	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:4	36.81	3233	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.68	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:4	36.81	3231	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.69	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:5	36.81	3245	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.69	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:5	36.81	3238	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.72	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:5	36.81	3238	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.75	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:5	36.81	3243	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.71	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:5	36.81	3244	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.74	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:5	36.81	3248	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.75	14.78	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:6	36.81	3254	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.76	14.78	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:6	36.81	3255	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.78	14.81	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:6	36.81	3252	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.78	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:6	36.81	3251	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.76	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:6	36.81	3246	2.21	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.71	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:6	36.81	3234	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.69	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:6	36.81	3225	2.21	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.71	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:7	36.81	3222	2.21	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.69	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:7	36.81	3228	2.21	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.71	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:7	36.81	3228	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.7	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:7	36.81	3232	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.65	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:7	36.81	3261	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.68	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:7	36.81	3247	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.65	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:8	36.81	3250	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.66	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:8	36.81	3253	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.66	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:8	36.81	3257	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.65	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:8	36.81	3257	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.65	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:8	36.81	3256	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.66	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:8	36.81	3256	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Rich	1	14.6	-7.67	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:48:9	36.81	3258	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.68	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:9	36.81	3257	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.66	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:9	36.81	3256	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.66	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:9	36.81	3252	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.7	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:9	36.81	3252	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.69	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:9	36.81	3252	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.69	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:48:9	36.81	3251	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.75	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:0	36.81	3250	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:0	36.81	3258	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.7	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:0	36.81	3246	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.72	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:0	36.81	3244	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.68	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:0	36.81	3247	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.68	15.05	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:0	36.81	3224	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.69	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:1	36.81	3236	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.64	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:1	36.81	3255	2.21	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.67	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:1	36.81	3263	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.64	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:1	36.81	3260	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.66	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:49:1	36.81	3261	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:1	36.81	3260	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.65	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:1	36.81	3259	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.67	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:2	36.81	3259	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.67	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:2	36.81	3257	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.65	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:2	36.81	3255	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.66	14.9	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:2	36.81	3256	2.21	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.67	14.91	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:2	36.81	3254	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.69	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:2	36.81	3252	2.21	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.72	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:3	36.81	3249	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.67	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:3	36.81	3249	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.68	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:3	36.81	3251	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-7.68	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:3	36.81	3252	2.21	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:3	36.81	3254	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	15.06	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:3	36.81	3256	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:4	36.81	3254	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.63	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:4	36.81	3256	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.65	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:4	36.81	3266	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.64	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:4	36.81	3270	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.65	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:4	36.81	3272	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.66	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:4	36.81	3272	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.67	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:4	36.81	3288	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.69	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:5	36.81	3279	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:5	36.81	3279	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.71	14.78	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:5	36.81	3278	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.7	14.81	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:5	36.81	3277	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.71	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:5	36.81	3272	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.75	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:5	36.81	3266	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.7	14.9	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:6	36.81	3263	2.22	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.71	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:6	36.81	3262	2.22	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.71	14.94	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:6	36.81	3256	2.22	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.65	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:6	36.81	3257	2.22	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-7.64	15.05	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:6	36.81	3259	2.22	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:6	36.81	3258	2.23	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.6	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:49:6	36.81	3267	2.23	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.61	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:7	36.81	3267	2.23	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.59	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:7	36.81	3268	2.23	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.58	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:7	36.81	3272	2.23	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.55	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:7	36.81	3274	2.24	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.55	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:7	36.81	3275	2.24	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.48	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:49:7	36.81	3279	2.24	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.46	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:49:8	36.81	3283	2.25	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.42	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:49:8	36.81	3306	2.25	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.36	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:49:8	36.81	3293	2.26	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.35	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:49:8	36.81	3273	2.26	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.27	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:49:8	36.81	3273	2.26	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.24	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:49:8	36.81	3258	2.27	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.19	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:49:9	36.81	3266	2.28	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.15	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:49:9	36.81	3270	2.28	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.13	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:49:9	36.81	3283	2.28	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.09	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:49:9	36.81	3283	2.29	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.06	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:49:9	36.81	3294	2.3	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.06	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:49:9	36.81	3298	2.3	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.02	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:49:9	36.81	3298	2.31	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.03	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:0	36.81	3298	2.31	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.06	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:0	36.81	3298	2.32	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.04	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:0	36.81	3286	2.32	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.02	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:0	36.81	3283	2.33	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.03	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:50:0	36.81	3279	2.33	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.01	15.12	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:0	36.81	3278	2.34	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.96	15.09	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:1	36.81	3271	2.34	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.92	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:1	36.81	3267	2.35	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.86	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:1	36.81	3268	2.35	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.84	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:1	36.81	3268	2.35	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.83	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:50:1	36.81	3275	2.35	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.82	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:1	36.81	3279	2.36	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.81	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:1	36.81	3282	2.36	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.79	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:2	36.81	3294	2.37	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.78	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:2	36.81	3302	2.37	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.75	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:2	36.81	3308	2.38	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.72	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:2	36.81	3308	2.38	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.73	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:2	36.81	3310	2.38	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.7	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:2	36.81	3309	2.39	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.69	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:3	36.81	3309	2.39	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.74	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:3	36.81	3309	2.39	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.65	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:3	36.81	3304	2.4	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.63	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:3	36.81	3302	2.4	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.67	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:3	36.81	3298	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.59	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:3	36.81	3299	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.62	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:4	36.81	3298	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.64	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:4	36.81	3296	2.41	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.59	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:4	36.81	3297	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.58	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:4	36.81	3298	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.58	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:4	36.81	3298	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.54	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:4	36.81	3300	2.42	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.54	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:4	36.81	3300	2.42	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.55	14.9	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:5	36.81	3312	2.43	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.55	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:5	36.81	3312	2.43	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.55	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:5	36.81	3317	2.43	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.54	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:5	36.81	3326	2.43	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.54	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:5	36.81	3329	2.43	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.56	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:5	36.81	3330	2.43	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.55	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:6	36.81	3333	2.43	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.55	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:6	36.81	3331	2.43	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.63	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:6	36.81	3330	2.44	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.57	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:6	36.81	3324	2.44	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.54	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:6	36.81	3320	2.44	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.59	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:6	36.81	3319	2.44	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.54	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:6	36.81	3314	2.44	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.49	14.9	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:7	36.81	3312	2.44	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.53	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:7	36.81	3317	2.44	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.48	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:7	36.81	3317	2.45	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.49	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:7	36.81	3320	2.45	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.51	15.05	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:7	36.81	3323	2.45	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.48	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:7	36.81	3326	2.45	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.51	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:8	36.81	3334	2.45	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.52	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:8	36.81	3340	2.45	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.45	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:8	36.81	3342	2.46	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.51	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:8	36.81	3344	2.46	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.45	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:8	36.81	3348	2.46	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.41	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:8	36.81	3344	2.46	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.46	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:50:9	36.81	3342	2.46	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.45	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:9	36.81	3342	2.46	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.43	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:9	36.81	3342	2.46	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.5	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:50:9	36.81	3342	2.46	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.51	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:50:9	36.81	3343	2.46	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.53	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:50:9	36.81	3348	2.46	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.58	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:50:9	36.81	3350	2.46	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.56	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:0	36.81	3350	2.46	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.56	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:0	36.81	3350	2.46	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.57	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:51:0	36.81	3353	2.46	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.58	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:51:0	36.81	3383	2.46	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.56	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:51:0	36.81	3359	2.46	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.53	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:51:0	36.81	3358	2.46	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.53	14.9	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:51:1	36.81	3356	2.46	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.44	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:51:1	36.81	3360	2.46	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.41	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:51:1	36.81	3360	2.47	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.39	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:51:1	36.81	3358	2.47	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.35	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:51:1	36.81	3358	2.47	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.34	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:51:1	36.81	3363	2.48	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.34	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:51:1	36.81	3364	2.48	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.25	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:2	36.81	3366	2.49	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.23	14.9	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:2	36.81	3366	2.49	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.17	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:2	36.81	3371	2.5	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.12	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:2	36.81	3380	2.5	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.13	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:2	36.81	3379	2.51	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.04	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:2	36.81	3379	2.51	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.05	14.78	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:3	36.81	3379	2.52	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.09	14.82	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:3	36.81	3375	2.52	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:51:3	36.81	3374	2.52	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.99	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:3	36.81	3376	2.53	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.02	14.96	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:3	36.81	3380	2.53	13.43	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.02	15	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:3	36.81	3381	2.54	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.94	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:4	36.81	3382	2.54	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.95	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:4	36.81	3384	2.55	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.97	15.15	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:4	36.81	3385	2.55	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.91	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:4	36.81	3375	2.55	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.91	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:4	36.81	3382	2.56	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.95	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:4	36.81	3388	2.56	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.86	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:4	36.81	3393	2.56	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.81	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:5	36.81	3393	2.56	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.87	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:51:5	36.81	3400	2.56	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.86	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:51:5	36.81	3410	2.57	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.82	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:51:5	36.81	3411	2.57	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.89	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:51:5	36.81	3414	2.57	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.93	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:51:5	36.81	3416	2.57	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.87	14.74	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:6	36.81	3416	2.57	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.83	14.75	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:6	36.81	3415	2.57	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.86	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:6	36.81	3408	2.57	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.81	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:6	36.81	3408	2.58	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.77	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:6	36.81	3408	2.58	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.86	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:6	36.81	3408	2.58	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-5.84	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:6	36.81	3403	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Lean	1	14.6	-5.83	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:7	36.81	3403	2.58	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.89	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:7	36.81	3404	2.58	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.91	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:7	36.81	3411	2.58	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.86	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:7	36.81	3412	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.9	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:7	36.81	3412	2.58	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.91	14.75	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:7	36.81	3418	2.58	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.86	14.69	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:8	36.81	3418	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.89	14.66	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:8	36.81	3419	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.91	14.7	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:8	36.81	3424	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.86	14.7	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:8	36.81	3425	2.58	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.83	14.72	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:8	36.81	3424	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.9	14.73	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:51:8	36.81	3422	2.58	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.91	14.75	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:9	36.81	3421	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.91	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:9	36.81	3418	2.58	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.99	14.79	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:9	36.81	3418	2.58	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.99	14.79	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:51:9	36.81	3448	2.58	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.88	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:9	36.81	3424	2.58	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.92	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:51:9	36.81	3428	2.58	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.88	14.82	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:51:9	36.81	3429	2.58	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.88	14.78	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:0	36.81	3438	2.58	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.92	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:0	36.81	3450	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.92	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:0	36.81	3451	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.93	14.78	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:0	36.81	3452	2.58	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.93	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:0	36.81	3462	2.58	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.88	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:0	36.81	3460	2.58	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.94	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:1	36.81	3457	2.58	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.91	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:1	36.81	3458	2.58	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.85	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:1	36.81	3459	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.91	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:1	36.81	3481	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.92	15.1	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:1	36.81	3466	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.93	15.11	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:1	36.81	3446	2.59	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.94	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:1	36.81	3448	2.59	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.93	15.05	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:2	36.81	3447	2.59	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.96	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:2	36.81	3449	2.59	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.91	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:2	36.81	3452	2.59	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.86	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:2	36.81	3456	2.59	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.89	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:2	36.81	3465	2.59	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.9	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:2	36.81	3471	2.59	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.83	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:3	36.81	3474	2.59	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.81	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:52:3	36.81	3476	2.6	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.8	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:3	36.81	3490	2.6	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.75	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:3	36.81	3486	2.6	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.8	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:3	36.81	3498	2.6	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.79	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:3	36.81	3484	2.6	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.74	15	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:4	36.81	3479	2.6	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.76	15.03	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:4	36.81	3479	2.61	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.8	15.03	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:4	36.81	3466	2.61	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.77	15.05	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:4	36.81	3477	2.61	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.76	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:4	36.81	3476	2.61	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.81	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:4	36.81	3470	2.61	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.73	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:52:4	36.81	3469	2.61	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.69	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:52:5	36.81	3470	2.62	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.71	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:52:5	36.81	3476	2.62	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.72	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:52:5	36.81	3485	2.62	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.69	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:52:5	36.81	3490	2.62	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.76	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:52:5	36.81	3504	2.62	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.74	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:5	36.81	3495	2.62	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.68	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:6	36.81	3496	2.62	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.7	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:6	36.81	3496	2.62	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.77	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:6	36.81	3491	2.62	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.75	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:6	36.81	3489	2.62	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.77	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:6	36.81	3491	2.62	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.85	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:6	36.81	3494	2.62	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.79	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:6	36.81	3492	2.62	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.74	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:7	36.81	3527	2.62	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.8	14.9	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:7	36.81	3512	2.62	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.86	14.89	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:7	36.81	3498	2.62	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.84	14.88	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:7	36.81	3496	2.62	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.84	14.87	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:7	36.81	3497	2.62	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.88	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:52:7	36.81	3487	2.62	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.89	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:8	36.81	3508	2.61	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.88	14.79	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:8	36.81	3513	2.61	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.88	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:8	36.81	3513	2.61	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.97	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:8	36.81	3534	2.61	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.98	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:8	36.81	3527	2.61	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.95	14.86	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:52:8	36.81	3528	2.6	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.09	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:52:9	36.81	3527	2.6	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.16	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:52:9	36.81	3526	2.6	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.13	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:52:9	36.81	3519	2.59	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.21	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:52:9	36.81	3519	2.59	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.31	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:52:9	36.81	3514	2.58	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.25	15.05	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:52:9	36.81	3478	2.57	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.33	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:52:9	36.81	3503	2.57	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.46	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:0	36.81	3502	2.56	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.48	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:0	36.81	3505	2.56	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.45	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:0	36.81	3506	2.55	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.52	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:0	36.81	3508	2.55	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.52	14.9	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:53:0	36.81	3510	2.54	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.52	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:53:0	36.81	3521	2.54	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.6	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:53:1	36.81	3524	2.53	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.63	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:53:1	36.81	3539	2.52	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.72	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:53:1	36.81	3539	2.52	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.73	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:53:1	36.81	3547	2.51	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.74	14.77	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:53:1	36.81	3545	2.51	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.75	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:1	36.81	3600	2.51	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.78	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:1	36.81	3572	2.5	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.75	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:2	36.81	3540	2.5	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.71	14.92	1.02	3.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:2	36.81	3534	2.5	13.41	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.75	14.96	1.02	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:2	36.81	3534	2.49	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.77	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:2	36.81	3528	2.49	13.42	106	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.77	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:2	36.81	3528	2.49	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.77	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:2	36.81	3528	2.49	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.77	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:3	36.81	3525	2.49	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.82	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:3	36.81	3524	2.49	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.78	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:3	36.81	3527	2.48	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.78	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:3	36.81	3532	2.48	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.77	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:3	36.81	3542	2.48	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.76	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:3	36.81	3556	2.48	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.78	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:4	36.81	3556	2.48	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.84	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:4	36.81	3565	2.48	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.85	14.9	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:4	36.81	3565	2.48	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.84	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:4	36.81	3566	2.48	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.85	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:4	36.81	3564	2.48	13.43	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.85	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:4	36.81	3562	2.48	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.87	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:4	36.81	3554	2.48	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.89	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:5	36.81	3552	2.47	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.91	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:5	36.81	3530	2.47	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.89	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:5	36.81	3546	2.47	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.87	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:5	36.81	3546	2.47	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.89	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:5	36.81	3536	2.47	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.89	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:53:5	36.81	3540	2.47	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.88	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:6	36.81	3541	2.47	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.9	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:6	36.81	3547	2.47	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.94	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:6	36.81	3553	2.47	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.92	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:6	36.81	3555	2.47	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.9	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:6	36.81	3570	2.47	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.91	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:53:6	36.81	3564	2.46	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.95	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:53:6	36.81	3563	2.46	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.96	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:53:7	36.81	3564	2.46	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.96	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:53:7	36.81	3560	2.46	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.97	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:7	36.81	3563	2.46	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.01	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:7	36.81	3562	2.46	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.02	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:7	36.81	3564	2.46	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.05	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:7	36.81	3563	2.45	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.08	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:8	36.81	3565	2.45	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.11	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:8	36.81	3564	2.45	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.08	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:8	36.81	3560	2.45	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.07	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:8	36.81	3562	2.45	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.08	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:8	36.81	3564	2.45	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.07	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:8	36.81	3566	2.45	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.1	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:9	36.81	3569	2.44	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.14	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:53:9	36.81	3568	2.44	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.16	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:53:9	36.81	3566	2.44	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.13	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:53:9	36.81	3554	2.44	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.14	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:53:9	36.81	3556	2.44	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.14	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:53:9	36.81	3554	2.44	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.13	15.17	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:53:9	36.81	3554	2.44	13.43	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.07	15.2	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:0	36.81	3536	2.43	13.41	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.07	15.18	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:0	36.81	3550	2.43	13.41	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.13	15.15	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:0	36.81	3550	2.43	13.43	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.14	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:0	36.81	3556	2.43	13.43	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.12	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:0	36.81	3562	2.43	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.16	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:0	36.81	3566	2.43	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.17	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:1	36.81	3568	2.43	13.43	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.16	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:1	36.81	3576	2.43	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.17	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:1	36.81	3577	2.43	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.24	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:1	36.81	3578	2.42	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.25	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:1	36.81	3579	2.42	13.45	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.22	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:1	36.81	3579	2.42	13.45	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.18	14.9	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:1	36.81	3579	2.42	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.21	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:2	36.81	3578	2.42	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.18	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:2	36.81	3565	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.18	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:2	36.81	3563	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.26	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:2	36.81	3579	2.42	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.22	15.12	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:2	36.81	3568	2.42	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.24	15.17	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:2	36.81	3557	2.42	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.19	15.16	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:3	36.81	3560	2.42	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.17	15.12	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:3	36.81	3562	2.42	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.16	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:3	36.81	3570	2.42	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.21	15.08	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:3	36.81	3577	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.15	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:3	36.81	3592	2.42	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.17	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:3	36.81	3586	2.42	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.21	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:4	36.81	3588	2.42	13.43	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.21	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:4	36.81	3585	2.41	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.18	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:4	36.81	3586	2.41	13.4	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.24	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:4	36.81	3569	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.27	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:4	36.81	3581	2.41	13.44	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.25	14.9	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:4	36.81	3582	2.41	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.22	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:4	36.81	3576	2.41	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.21	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:5	36.81	3579	2.41	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.22	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:5	36.81	3575	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.22	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:5	36.81	3577	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.21	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:5	36.81	3574	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.23	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:5	36.81	3574	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.25	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:5	36.81	3574	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.22	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:54:6	36.81	3572	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.2	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:6	36.81	3578	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.21	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:6	36.81	3580	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.26	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:6	36.81	3580	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.26	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:6	36.81	3578	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.27	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:6	36.81	3587	2.41	13.39	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.25	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:6	36.81	3589	2.41	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.31	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:7	36.81	3597	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.32	14.76	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:7	36.81	3602	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.31	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:7	36.81	3602	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.3	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:7	36.81	3602	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.28	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:7	36.81	3630	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.3	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:7	36.81	3593	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.29	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:8	36.81	3594	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.27	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:8	36.81	3590	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.27	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:8	36.81	3593	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.32	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:8	36.81	3585	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.32	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:8	36.81	3586	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.28	15.13	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:8	36.81	3586	2.41	13.4	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.32	15.19	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:9	36.81	3586	2.41	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.31	15.19	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:9	36.81	3593	2.41	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.25	15.16	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:9	36.81	3577	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.2	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:9	36.81	3578	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.21	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:9	36.81	3580	2.41	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.23	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:9	36.81	3582	2.41	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.25	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:54:9	36.81	3598	2.41	13.39	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.28	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:0	36.81	3608	2.41	13.41	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.35	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:0	36.81	3608	2.41	13.41	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.36	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:0	36.81	3610	2.41	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.31	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:0	36.81	3610	2.41	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.31	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:0	36.81	3604	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.24	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:0	36.81	3598	2.41	13.38	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.2	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:1	36.81	3592	2.41	13.36	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.23	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:1	36.81	3592	2.41	13.38	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.3	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:1	36.81	3588	2.41	13.39	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.32	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:1	36.81	3586	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.3	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:1	36.81	3585	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.31	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:1	36.81	3588	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.31	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:1	36.81	3593	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.32	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:2	36.81	3594	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.32	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:2	36.81	3594	2.41	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.31	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:2	36.81	3603	2.41	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.3	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:2	36.81	3579	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.29	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:2	36.81	3594	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.29	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:2	36.81	3612	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.34	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:3	36.81	3618	2.41	13.44	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.33	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:3	36.81	3616	2.41	13.46	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.34	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:3	36.81	3626	2.41	13.46	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.34	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:3	36.81	3602	2.41	13.46	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.34	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:3	36.81	3598	2.41	13.46	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.3	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:3	36.81	3598	2.41	13.44	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.34	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:4	36.81	3597	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.33	15.05	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:4	36.81	3594	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.35	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:4	36.81	3594	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	-7.35	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:4	36.81	3595	2.41	13.42	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Lean	1	14.6	-7.36	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:4	36.81	3601	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.36	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:4	36.81	3601	2.41	13.45	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.36	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:4	36.81	3600	2.41	13.45	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.3	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:55:8	36.81	3599	2.41	13.45	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.29	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3605	2.41	13.45	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.3	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3605	2.41	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.3	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3612	2.41	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.31	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3615	2.41	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.36	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3626	2.41	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.38	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:6	36.81	3626	2.41	13.4	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.38	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:6	38.18	3625	2.41	13.43	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.33	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:6	38.18	3616	2.41	13.4	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.31	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:6	38.18	3618	2.41	13.42	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.32	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:6	38.18	3618	2.41	13.42	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.34	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:6	38.18	3616	2.41	13.42	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.37	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:6	38.18	3613	2.41	13.43	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.37	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:7	38.18	3614	2.41	13.46	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.31	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:7	38.18	3611	2.41	13.44	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.3	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:7	38.18	3608	2.41	13.45	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.26	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:7	38.18	3610	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	-7.23	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:7	38.18	3610	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.28	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:7	38.18	3612	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.32	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	38.18	3613	2.41	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.33	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3614	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.31	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3614	2.41	13.41	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.31	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3618	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.28	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3618	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.3	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:8	36.81	3620	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.31	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:9	36.81	3622	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.34	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:9	36.81	3622	2.41	13.4	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.36	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:9	36.81	3620	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.35	14.78	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:9	36.81	3622	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.35	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:9	36.81	3623	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.38	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:9	36.81	3626	2.41	13.42	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.43	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:55:9	36.81	3642	2.41	13.44	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.42	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:0	38.18	3628	2.41	13.44	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.37	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:0	38.18	3628	2.41	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.36	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:0	38.18	3627	2.41	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.36	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:0	38.18	3629	2.41	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.41	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:0	38.18	3612	2.41	13.41	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.41	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:0	36.81	3622	2.41	13.42	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.41	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:1	36.81	3628	2.41	13.44	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.43	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:1	36.81	3629	2.41	13.44	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.4	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:1	36.81	3626	2.41	13.43	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.33	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:1	36.81	3620	2.41	13.41	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.35	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:1	36.81	3618	2.41	13.42	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.34	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:1	36.81	3621	2.41	13.43	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.31	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:1	36.81	3621	2.41	13.41	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.29	14.9	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:2	36.81	3620	2.41	13.41	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.31	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:2	36.81	3620	2.41	13.42	107	197	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.35	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:2	36.81	3620	2.41	13.42	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.34	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:2	36.81	3628	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.34	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:2	36.81	3638	2.41	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.35	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:2	36.81	3639	2.41	13.43	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.36	14.78	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:3	36.81	3639	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.36	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:3	36.81	3667	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.31	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:3	38.18	3652	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.32	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:3	38.18	3636	2.41	13.4	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.36	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:3	38.18	3632	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.36	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:3	38.18	3630	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.33	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:4	38.18	3630	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.33	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:56:4	38.18	3628	2.41	13.38	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.35	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:4	38.18	3628	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.38	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:4	38.18	3599	2.41	13.42	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.33	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:4	36.81	3612	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.3	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:4	36.81	3628	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.31	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:4	36.81	3622	2.41	13.44	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.37	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:5	36.81	3621	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.35	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:5	38.18	3640	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.32	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:5	38.18	3631	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.37	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:5	38.18	3632	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.43	14.78	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:5	38.18	3644	2.41	13.44	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.39	14.74	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:5	36.81	3652	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.37	14.74	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:6	36.81	3652	2.41	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.37	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:56:6	36.81	3658	2.41	13.42	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.37	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:6	36.81	3659	2.41	13.42	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.37	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:6	36.81	3648	2.41	13.42	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.37	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:6	36.81	3646	2.41	13.42	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.4	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:6	36.81	3646	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.43	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:6	36.81	3640	2.41	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.48	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:7	36.81	3638	2.4	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.65	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:7	38.18	3628	2.38	13.41	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.89	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:17:56:7	38.18	3623	2.35	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.12	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:56:7	38.18	3621	2.3	13.43	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.4	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:56:7	38.18	3612	2.26	13.42	107	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.89	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:17:56:7	38.18	3602	2.22	13.43	107	196	Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.18	14.94	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:8	38.18	3592	2.19	13.43	107	196	Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.41	14.9	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:8	38.18	3590	2.16	13.43	107	196	Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.52	14.88	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:8	38.18	3530	2.12	13.42	107	197	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.72	14.81	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:8	32.72	3501	2.09	13.44	107	197	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.88	14.75	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:8	27.27	3498	2.05	13.43	107	197	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.93	14.74	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:8	27.27	3466	2.03	13.42	107	197	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.97	14.73	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:9	21.81	3468	1.98	13.43	107	197	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-10.1	14.72	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:9	20.45	3462	1.95	13.45	107	197	Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.12	14.67	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:9	20.45	3456	1.91	13.44	107	196	Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.12	14.61	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:9	20.45	3423	1.87	13.42	106	196	Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.14	14.55	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:9	20.45	3395	1.84	13.45	106	196	Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.16	14.44	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:56:9	20.45	3388	1.8	13.45	106	196	Idle	41.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.08	14.34	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:0	20.45	3329	1.74	13.44	107	196	Idle	40.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.98	14.17	0.97	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:0	20.45	3286	1.72	13.44	107	196	Idle	39	0	2	132	944 Turbo	0.17	Rich	1	14.6	-9.84	13.96	0.95	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:0	20.45	3276	1.71	13.42	107	196	Idle	38.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.81	13.81	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:0	20.45	3238	1.71	13.44	107	196	Idle	37.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.77	13.75	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:0	20.45	3190	1.72	13.42	107	196	Idle	36.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.74	13.72	0.93	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:0	20.45	3195	1.72	13.44	107	196	Idle	36	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.75	13.7	0.93	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:1	20.45	3150	1.72	13.43	107	196	Idle	35.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.7	13.73	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:1	20.45	3138	1.73	13.43	107	196	Idle	34.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.65	13.78	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:1	20.45	3130	1.73	13.42	107	196	Idle	33	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.59	13.84	0.94	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:1	20.45	3098	1.74	13.43	107	196	Idle	31.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.56	13.99	0.95	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:1	20.45	3057	1.74	13.42	107	196	Idle	30.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.46	14.09	0.96	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:1	20.45	3008	1.75	13.43	107	196	Idle	29.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.42	14.19	0.97	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:1	20.45	3010	1.75	13.44	107	197	Idle	28.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.39	14.24	0.97	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:2	20.45	2990	1.76	13.42	107	197	Idle	28	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	14.41	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:2	20.45	2967	1.77	13.42	107	197	Idle	27	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.3	14.56	0.99	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:2	19.09	2936	1.77	13.42	107	197	Idle	25.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.29	14.77	1.01	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:2	19.09	2918	1.78	13.42	107	197	Idle	25.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	15.04	1.02	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:2	19.09	2886	1.79	13.42	107	197	Idle	24.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.22	15.4	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:2	19.09	2878	1.8	13.41	107	196	Idle	24.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.14	15.9	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:3	19.09	2847	1.81	13.41	107	196	Idle	24.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.13	16.44	1.12	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:3	19.09	2803	1.81	13.42	107	197	Idle	24.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.06	16.98	1.16	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:57:3	19.09	2804	1.82	13.42	107	197	Idle	24.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.02	17.55	1.2	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:3	19.09	2782	1.82	13.43	107	197	Idle	24.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.02	18.37	1.25	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:3	19.09	2740	1.83	13.44	107	197	Idle	24.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.99	18.87	1.29	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:3	19.09	2726	1.83	13.43	107	197	Idle	24.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.95	19.33	1.32	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:4	19.09	2717	1.83	13.45	107	197	Full Load	25.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.94	19.71	1.34	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:4	19.09	2673	1.84	13.43	107	197	Off Idle	25.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.92	20.02	1.36	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:4	19.09	2655	1.84	13.43	107	197	Off Idle	26.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.83	20.18	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:4	10.9	2576	1.85	13.41	106	197	Off Idle	27.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.78	20.22	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:57:4	10.9	2596	1.86	13.42	106	197	Off Idle	29.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.62	20.22	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:57:4	13.63	2572	1.87	13.42	107	197	Off Idle	32.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.57	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:17:57:4	16.36	2554	1.87	13.41	107	197	Off Idle	34.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.49	20.23	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:57:5	16.36	2484	1.88	13.41	107	197	Off Idle	37.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.37	20.24	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:57:5	19.09	2403	1.88	13.42	107	197	Off Idle	39.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.26	20.24	1.38	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:57:5	19.09	2389	1.87	13.41	107	197	Off Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.21	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:57:5	21.81	2389	1.87	13.41	107	197	Off Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.14	20.25	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:57:5	24.54	2387	1.87	13.41	107	197	Off Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.1	20.25	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:57:5	24.54	2350	1.87	13.41	107	197	Off Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.07	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:57:6	27.27	2402	1.88	13.43	107	196	Off Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.99	20.24	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:57:6	29.99	2411	1.89	13.42	107	196	Off Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.92	20.24	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:17:57:6	32.72	2440	1.9	13.42	107	196	Off Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.8	20.25	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:57:6	32.72	2466	1.91	13.43	107	197	Off Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.69	20.24	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:17:57:6	32.72	2466	1.91	13.44	107	197	Off Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.58	20.24	1.38	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:6	34.08	2485	1.93	13.42	107	197	Off Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.48	20.25	1.38	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:6	34.08	2512	1.94	13.43	107	197	Off Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.34	20.25	1.38	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:57:7	34.08	2512	1.96	13.42	107	197	Off Idle	70.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.25	20.25	1.38	3.3	2.6	ON	28 Pin	OFF	Removed	Disabled
03:17:57:7	34.08	2547	1.99	13.42	107	197	Off Idle	71	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.05	20.24	1.38	3.3	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:57:7	34.08	2553	2	13.41	107	197	Off Idle	71	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.94	20.24	1.38	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:57:7	34.08	2560	2.01	13.41	107	197	Off Idle	70.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.81	20.24	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:17:57:7	34.08	2557	2.02	13.43	107	197	Off Idle	70.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.7	20.24	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:57:7	34.08	2540	2.04	13.43	107	197	Off Idle	69.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.64	20.25	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:57:8	34.08	2491	2.05	13.41	107	197	Off Idle	68.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.54	20.24	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:57:8	34.08	2478	2.07	13.41	107	197	Off Idle	68.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.43	20.23	1.38	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:57:8	34.08	2440	2.09	13.41	106	197	Off Idle	67.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.31	20.15	1.37	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:57:8	34.08	2413	2.11	13.41	106	197	Off Idle	67.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.25	20.02	1.36	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:57:8	34.08	2413	2.14	13.41	106	197	Off Idle	66.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.1	19.79	1.35	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:57:8	34.08	2386	2.16	13.42	107	197	Off Idle	67.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.02	19.56	1.33	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:57:9	34.08	2434	2.17	13.41	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.96	19.32	1.32	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:17:57:9	34.08	2455	2.18	13.42	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.95	19.05	1.3	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:57:9	34.08	2462	2.19	13.42	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.92	18.9	1.29	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:57:9	34.08	2508	2.19	13.42	107	197	Off Idle	67.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.95	18.58	1.27	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:57:9	34.08	2508	2.2	13.41	107	197	Off Idle	67.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.97	18.42	1.25	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:57:9	32.72	2494	2.21	13.42	107	197	Off Idle	67.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.98	18.06	1.23	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:57:9	32.72	2505	2.21	13.41	107	197	Off Idle	68	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.98	17.73	1.21	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:58:0	32.72	2503	2.21	13.4	107	197	Off Idle	68.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.98	17.3	1.18	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:58:0	32.72	2482	2.21	13.41	107	197	Off Idle	68.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.98	17.04	1.16	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:0	32.72	2454	2.21	13.42	107	197	Off Idle	68.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.98	16.83	1.15	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:0	32.72	2421	2.21	13.41	107	197	Off Idle	68.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.95	16.65	1.13	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:0	34.08	2438	2.21	13.42	107	197	Off Idle	68.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.91	16.47	1.12	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:0	34.08	2440	2.21	13.42	107	197	Off Idle	68.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.9	16.29	1.11	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:1	34.08	2454	2.21	13.43	107	197	Off Idle	68.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.91	16.15	1.1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:1	34.08	2454	2.21	13.41	107	197	Off Idle	67.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.9	16.01	1.09	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:1	34.08	2468	2.2	13.42	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.88	15.85	1.08	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:1	34.08	2487	2.2	13.42	107	197	Off Idle	67.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.91	15.76	1.07	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:1	34.08	2497	2.2	13.42	107	197	Off Idle	67.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.92	15.67	1.07	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:1	34.08	2499	2.2	13.42	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.92	15.58	1.06	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:1	34.08	2508	2.2	13.42	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.93	15.5	1.06	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:2	34.08	2494	2.2	13.42	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.93	15.46	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:2	34.08	2486	2.2	13.41	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.96	15.41	1.05	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:58:2	34.08	2483	2.2	13.41	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.96	15.4	1.05	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:2	34.08	2464	2.21	13.41	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.96	15.39	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:2	34.08	2464	2.21	13.42	107	197	Off Idle	67.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.94	15.38	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:2	34.08	2460	2.21	13.42	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.88	15.37	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:3	34.08	2462	2.21	13.42	107	197	Off Idle	67.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.87	15.36	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:3	34.08	2463	2.21	13.41	107	197	Off Idle	67.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.85	15.35	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:3	34.08	2470	2.21	13.43	107	197	Off Idle	67.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.87	15.32	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:3	34.08	2482	2.21	13.42	107	197	Off Idle	67.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.89	15.29	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:3	34.08	2491	2.21	13.41	107	197	Off Idle	67.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.84	15.25	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:3	34.08	2494	2.21	13.41	107	197	Off Idle	67.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.84	15.22	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:4	34.08	2498	2.21	13.42	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.84	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:4	34.08	2497	2.21	13.41	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.86	15.16	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:4	34.08	2496	2.21	13.42	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.87	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:4	34.08	2494	2.21	13.42	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.91	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:4	32.72	2476	2.21	13.42	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.9	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:4	32.72	2478	2.22	13.42	107	197	Off Idle	67.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.92	15.15	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:4	32.72	2473	2.22	13.4	107	197	Off Idle	67.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.92	15.17	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:5	32.72	2473	2.22	13.4	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.91	15.19	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:5	32.72	2470	2.22	13.4	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.85	15.2	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:5	32.72	2487	2.22	13.41	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.81	15.19	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:5	34.08	2492	2.22	13.4	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.81	15.18	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:5	34.08	2484	2.22	13.42	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.8	15.17	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:5	34.08	2489	2.22	13.41	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.8	15.17	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:6	34.08	2491	2.22	13.41	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.81	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:6	34.08	2496	2.22	13.41	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.78	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:6	34.08	2499	2.22	13.41	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.77	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:6	32.72	2497	2.23	13.41	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.71	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:58:6	32.72	2497	2.23	13.4	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.69	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:6	32.72	2492	2.23	13.41	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.67	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:6	32.72	2490	2.23	13.41	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.7	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:7	32.72	2490	2.23	13.41	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.7	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:58:7	32.72	2490	2.24	13.42	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.68	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:58:7	32.72	2494	2.24	13.41	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.65	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:58:7	32.72	2499	2.24	13.42	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.6	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:58:7	32.72	2502	2.24	13.41	106	197	Off Idle	67.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.59	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:58:7	32.72	2502	2.25	13.41	106	197	Off Idle	67.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.55	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:58:8	32.72	2503	2.25	13.41	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.54	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:58:8	32.72	2503	2.25	13.42	106	197	Off Idle	67.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.54	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:58:8	32.72	2503	2.25	13.41	106	197	Off Idle	67	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.58	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:58:8	32.72	2505	2.26	13.41	106	196	Off Idle	66.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.57	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:58:8	32.72	2506	2.26	13.4	107	196	Off Idle	66.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.55	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:58:8	32.72	2506	2.26	13.41	107	196	Off Idle	66.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.54	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:9	32.72	2507	2.26	13.4	107	197	Off Idle	66.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.51	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:9	32.72	2506	2.27	13.39	107	197	Off Idle	66.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.5	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:9	32.72	2503	2.27	13.38	107	197	Off Idle	66.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.5	15.16	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:9	32.72	2503	2.27	13.39	107	197	Off Idle	66.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.51	15.17	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:9	32.72	2498	2.27	13.41	107	197	Off Idle	66.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.53	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:9	32.72	2499	2.27	13.4	107	197	Off Idle	66.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.5	15.2	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:58:9	32.72	2500	2.27	13.4	107	197	Off Idle	66	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.48	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:0	32.72	2504	2.27	13.42	107	197	Off Idle	66	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.47	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:0	32.72	2504	2.27	13.43	107	197	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.46	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:0	32.72	2504	2.27	13.42	107	197	Off Idle	66	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.44	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:0	32.72	2508	2.27	13.41	107	197	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.48	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:0	32.72	2509	2.27	13.42	107	197	Off Idle	66	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.5	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:0	32.72	2511	2.27	13.41	107	197	Off Idle	66	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.52	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:1	32.72	2511	2.27	13.4	107	197	Off Idle	66	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.5	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:1	32.72	2506	2.27	13.4	107	197	Off Idle	65.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.53	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:1	32.72	2504	2.27	13.4	107	197	Off Idle	65.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.51	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:17:59:1	32.72	2505	2.27	13.42	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.52	14.64	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:1	32.72	2513	2.27	13.42	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.49	14.63	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:1	32.72	2516	2.27	13.42	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.5	14.63	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:1	32.72	2518	2.27	13.42	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5.5	14.62	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:2	32.72	2518	2.27	13.42	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.18	Rich	1	14.6	-5.49	14.62	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:2	32.72	2520	2.27	13.42	107	197	Off Idle	65.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.5	14.64	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:2	32.72	2519	2.27	13.4	107	197	Off Idle	65.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.5	14.7	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:2	32.72	2510	2.27	13.4	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.5	14.72	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:2	32.72	2510	2.27	13.4	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.47	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:59:2	32.72	2509	2.27	13.39	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.52	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:17:59:3	32.72	2512	2.27	13.39	107	197	Off Idle	65.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.5	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:3	32.72	2514	2.27	13.41	107	197	Off Idle	65.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.5	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:3	32.72	2520	2.27	13.4	107	197	Off Idle	65.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.52	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:3	32.72	2527	2.27	13.4	107	197	Off Idle	65.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.52	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:3	32.72	2527	2.27	13.41	107	197	Off Idle	65.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.51	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:3	32.72	2528	2.27	13.41	107	197	Off Idle	65.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.56	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:4	32.72	2530	2.27	13.43	107	197	Off Idle	65.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.54	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:4	32.72	2528	2.27	13.42	107	197	Off Idle	65	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.53	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:4	32.72	2526	2.27	13.42	107	197	Off Idle	65	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.56	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:4	32.72	2524	2.27	13.41	107	197	Off Idle	65	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.58	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:4	32.72	2523	2.27	13.4	107	197	Off Idle	65	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.56	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:4	32.72	2538	2.27	13.39	107	197	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.6	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:4	32.72	2538	2.27	13.41	107	197	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.57	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:5	32.72	2515	2.27	13.41	107	197	Off Idle	65.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.56	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:5	32.72	2515	2.27	13.41	107	197	Off Idle	65.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.56	14.91	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:5	32.72	2500	2.27	13.41	107	197	Off Idle	65.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.54	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:5	32.72	2500	2.27	13.41	107	197	Off Idle	65.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.59	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:5	32.72	2529	2.27	13.4	107	197	Off Idle	65	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.59	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:5	34.08	2555	2.27	13.4	107	197	Off Idle	64.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.61	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:6	34.08	2547	2.27	13.42	107	197	Off Idle	64.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.62	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:6	34.08	2556	2.27	13.42	107	197	Off Idle	64.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.64	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:6	34.08	2546	2.27	13.42	107	197	Off Idle	64.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.67	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:6	34.08	2546	2.27	13.41	107	197	Off Idle	64.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.65	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:6	34.08	2545	2.27	13.41	107	197	Off Idle	64.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.66	14.81	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:6	34.08	2539	2.27	13.41	107	197	Off Idle	64.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.67	14.81	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:17:59:6	34.08	2534	2.27	13.4	107	197	Off Idle	64.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.71	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:7	34.08	2532	2.26	13.4	107	197	Off Idle	64.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.71	14.86	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:7	34.08	2528	2.26	13.4	107	197	Off Idle	64.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.74	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:7	34.08	2530	2.26	13.41	107	197	Off Idle	64.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.75	14.89	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:59:7	34.08	2530	2.26	13.41	106	197	Off Idle	64.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.77	14.91	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:59:7	34.08	2532	2.26	13.43	106	197	Off Idle	64.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.75	14.96	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:59:7	34.08	2536	2.25	13.43	107	197	Off Idle	64.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.79	15.03	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:59:8	34.08	2541	2.25	13.42	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.79	15.06	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:59:8	34.08	2540	2.25	13.42	107	197	Off Idle	64.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.81	15.07	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:17:59:8	34.08	2545	2.25	13.41	106	197	Off Idle	64.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.83	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:59:8	34.08	2550	2.25	13.41	106	197	Off Idle	64.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.89	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:59:8	34.08	2550	2.24	13.41	106	197	Off Idle	64.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.87	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:17:59:8	34.08	2550	2.24	13.42	106	197	Off Idle	64.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.9	14.98	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:9	34.08	2548	2.24	13.41	106	197	Off Idle	64.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.91	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:9	34.08	2544	2.24	13.42	106	197	Off Idle	64.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.92	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:9	34.08	2544	2.24	13.41	107	197	Off Idle	64	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.93	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:9	34.08	2546	2.24	13.42	107	197	Off Idle	63.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.91	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:9	34.08	2547	2.24	13.41	107	197	Off Idle	63.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.92	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:9	34.08	2548	2.23	13.41	107	197	Off Idle	63.7	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5.94	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:17:59:9	34.08	2552	2.23	13.42	107	197	Off Idle	63.5	0	2	132	944 Turbo	0.16	Rich	1	14.6	-5.94	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:00:0	34.08	2554	2.23	13.41	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.96	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:00:0	34.08	2554	2.23	13.41	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:00:0	34.08	2554	2.23	13.41	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.03	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:00:0	34.08	2552	2.23	13.41	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.08	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:00:0	34.08	2557	2.23	13.41	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.07	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:0	34.08	2561	2.23	13.43	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.05	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:1	34.08	2561	2.22	13.42	107	197	Off Idle	63.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.12	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:1	34.08	2557	2.22	13.41	107	197	Off Idle	63.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.08	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:1	34.08	2554	2.22	13.41	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.08	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:1	34.08	2552	2.22	13.43	107	197	Off Idle	63.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.12	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:1	34.08	2548	2.22	13.43	107	197	Off Idle	63.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.13	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:1	34.08	2548	2.22	13.42	107	197	Off Idle	63.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.09	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:1	34.08	2550	2.22	13.41	107	197	Off Idle	63.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.07	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:2	34.08	2554	2.22	13.41	107	197	Off Idle	63.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.1	15.13	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:2	34.08	2559	2.22	13.4	107	197	Off Idle	63.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.09	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:2	34.08	2565	2.22	13.39	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.05	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:2	34.08	2566	2.22	13.4	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.06	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:2	34.08	2569	2.22	13.41	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.11	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:2	34.08	2565	2.22	13.4	107	197	Off Idle	63.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.16	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:3	34.08	2565	2.22	13.42	107	197	Off Idle	62.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.17	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:3	34.08	2562	2.22	13.41	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.19	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:3	34.08	2561	2.22	13.41	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.16	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:3	34.08	2559	2.22	13.41	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.12	14.77	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:3	34.08	2560	2.21	13.42	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.12	14.74	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:3	34.08	2558	2.21	13.41	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.13	14.73	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:4	34.08	2561	2.21	13.41	107	197	Off Idle	62.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.13	14.76	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:4	34.08	2565	2.21	13.42	107	197	Off Idle	62.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.16	14.79	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:4	34.08	2566	2.21	13.43	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.15	14.83	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:4	34.08	2569	2.21	13.43	107	197	Off Idle	62.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.14	14.86	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:4	34.08	2570	2.21	13.42	107	197	Off Idle	62.2	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.2	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:4	34.08	2560	2.21	13.42	107	197	Off Idle	62.1	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.2	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:4	34.08	2569	2.21	13.41	107	197	Off Idle	62	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.2	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:5	34.08	2568	2.21	13.4	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.23	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:5	34.08	2564	2.21	13.4	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.23	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:5	34.08	2558	2.21	13.42	107	197	Off Idle	62	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.23	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:5	34.08	2554	2.21	13.4	107	197	Off Idle	62.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.23	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:5	34.08	2552	2.21	13.4	107	197	Off Idle	62.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.2	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:5	34.08	2550	2.21	13.41	107	197	Off Idle	62.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.2	15.12	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:6	34.08	2555	2.21	13.4	107	197	Off Idle	62.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.23	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:6	34.08	2555	2.21	13.41	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.19	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:6	34.08	2564	2.21	13.4	107	197	Off Idle	62.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.17	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:6	34.08	2567	2.21	13.41	107	197	Off Idle	62.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.2	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:6	34.08	2569	2.21	13.41	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.19	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:6	34.08	2586	2.21	13.41	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.17	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:6	34.08	2577	2.21	13.41	107	197	Off Idle	62.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.21	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:7	34.08	2578	2.21	13.41	107	197	Off Idle	62.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.24	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:7	34.08	2578	2.21	13.4	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.29	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:7	34.08	2577	2.21	13.41	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.31	14.81	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:7	34.08	2577	2.21	13.42	107	197	Off Idle	62.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.26	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:7	34.08	2578	2.21	13.43	107	197	Off Idle	62	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.26	14.8	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:7	34.08	2578	2.21	13.43	107	197	Off Idle	61.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.21	14.8	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:00:8	34.08	2578	2.21	13.41	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.17	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:8	34.08	2578	2.21	13.42	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.17	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:8	34.08	2558	2.21	13.42	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.2	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:8	34.08	2568	2.21	13.42	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.2	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:8	34.08	2576	2.21	13.41	106	197	Off Idle	61.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.25	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:8	34.08	2578	2.21	13.42	107	197	Off Idle	62	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.22	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:9	34.08	2578	2.21	13.42	107	197	Off Idle	62	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.25	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:9	34.08	2580	2.21	13.42	107	197	Off Idle	62	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.25	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:9	34.08	2581	2.21	13.41	107	197	Off Idle	62	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.31	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:9	34.08	2584	2.21	13.42	107	197	Off Idle	62	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.28	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:00:9	34.08	2584	2.21	13.43	107	197	Off Idle	62.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.29	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:9	34.08	2593	2.21	13.44	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.27	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:00:9	34.08	2585	2.21	13.43	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.28	15.02	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:0	34.08	2584	2.21	13.43	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.25	15.01	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:0	34.08	2583	2.21	13.43	107	197	Off Idle	62.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.22	15	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:0	34.08	2582	2.21	13.42	107	197	Off Idle	62.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.2	14.98	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:0	34.08	2585	2.21	13.43	107	197	Off Idle	62.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.23	14.94	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:0	34.08	2585	2.21	13.41	107	197	Off Idle	62	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.22	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:0	34.08	2589	2.21	13.41	107	197	Off Idle	61.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.23	14.87	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:1	34.08	2591	2.21	13.41	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.26	14.86	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:1	34.08	2591	2.21	13.42	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.28	14.87	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:1	34.08	2588	2.21	13.42	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.28	14.89	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:1	34.08	2589	2.21	13.42	107	197	Off Idle	61.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.29	14.9	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:01:1	34.08	2594	2.21	13.42	107	197	Off Idle	61.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.27	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:1	34.08	2594	2.21	13.41	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.28	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:1	34.08	2594	2.21	13.41	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.28	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:2	34.08	2594	2.21	13.42	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.28	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:2	34.08	2591	2.21	13.43	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.33	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:2	34.08	2591	2.21	13.42	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.33	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:2	34.08	2590	2.21	13.41	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.3	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:2	34.08	2595	2.21	13.42	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.33	15.12	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:2	34.08	2595	2.21	13.42	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.33	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:3	34.08	2595	2.21	13.4	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.29	15.11	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:3	34.08	2597	2.21	13.41	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.3	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:3	34.08	2598	2.21	13.42	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.27	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:3	34.08	2600	2.21	13.42	107	197	Off Idle	61.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.3	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:3	34.08	2602	2.21	13.42	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.34	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:3	34.08	2602	2.21	13.43	106	197	Off Idle	61	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.32	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:4	34.08	2601	2.21	13.42	106	197	Off Idle	61	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.35	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:4	34.08	2597	2.21	13.41	107	197	Off Idle	61.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.39	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:01:4	34.08	2596	2.21	13.43	107	197	Off Idle	61.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.4	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:01:4	34.08	2592	2.21	13.41	107	197	Off Idle	61.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.42	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:4	34.08	2592	2.2	13.41	106	197	Off Idle	61.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.45	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:4	34.08	2594	2.2	13.41	106	197	Off Idle	61	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.47	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:01:4	34.08	2596	2.19	13.41	106	197	Off Idle	61.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.52	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:01:5	34.08	2601	2.19	13.42	106	197	Off Idle	61.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.58	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:01:5	34.08	2601	2.18	13.43	106	197	Off Idle	61	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.64	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:01:5	34.08	2602	2.18	13.41	106	197	Off Idle	61	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.73	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:01:5	34.08	2606	2.17	13.41	106	197	Off Idle	61	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.8	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:01:5	34.08	2605	2.17	13.41	106	197	Off Idle	61	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.84	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:01:5	34.08	2605	2.16	13.41	107	197	Off Idle	61	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.91	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:01:6	34.08	2606	2.15	13.41	107	197	Off Idle	61.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:01:6	34.08	2603	2.14	13.41	107	197	Off Idle	61.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.02	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:01:6	34.08	2601	2.14	13.41	107	197	Off Idle	61	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.05	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:01:6	34.08	2598	2.13	13.42	107	197	Off Idle	61	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.1	14.9	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:01:6	34.08	2595	2.12	13.41	107	197	Off Idle	61	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.18	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:01:6	34.08	2592	2.11	13.42	107	197	Off Idle	61	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.25	14.94	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:6	34.08	2592	2.1	13.41	107	197	Off Idle	61	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.29	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:7	34.08	2590	2.09	13.42	107	197	Off Idle	61	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.3	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:7	34.08	2592	2.08	13.42	107	197	Off Idle	61	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.34	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:7	34.08	2594	2.07	13.41	107	197	Off Idle	61	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.4	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:7	34.08	2603	2.07	13.41	107	197	Off Idle	61	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.41	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:7	34.08	2604	2.07	13.4	107	197	Off Idle	61	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.43	15.05	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:7	34.08	2611	2.06	13.4	107	197	Off Idle	61	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.5	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:01:8	34.08	2614	2.06	13.41	106	197	Off Idle	60.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.55	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:01:8	34.08	2613	2.05	13.4	106	197	Off Idle	60.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.56	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:01:8	34.08	2616	2.05	13.41	106	197	Off Idle	60.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.57	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:8	34.08	2620	2.04	13.41	106	197	Off Idle	60.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.58	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:01:8	34.08	2620	2.04	13.41	106	197	Off Idle	60.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.6	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:8	35.45	2621	2.03	13.42	106	197	Off Idle	60.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.58	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:9	35.45	2618	2.03	13.42	106	197	Off Idle	60.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.61	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:9	35.45	2608	2.03	13.41	106	197	Off Idle	60.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.66	14.79	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:9	35.45	2604	2.03	13.41	106	197	Off Idle	60.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:9	35.45	2598	2.02	13.42	106	197	Off Idle	60.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:9	35.45	2599	2.02	13.43	106	197	Off Idle	60.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.72	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:9	35.45	2600	2.01	13.43	106	197	Off Idle	59.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.79	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:01:9	35.45	2598	2.01	13.42	106	197	Off Idle	59.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.79	14.96	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:02:0	35.45	2599	2	13.43	106	197	Off Idle	59.9	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.84	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:02:0	35.45	2602	2	13.44	107	197	Off Idle	59.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.9	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:02:0	35.45	2602	1.99	13.43	107	197	Off Idle	60.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.97	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:02:0	35.45	2606	1.99	13.43	107	197	Off Idle	60.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.98	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:0	35.45	2606	1.98	13.44	106	197	Off Idle	60.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.06	15.13	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:0	35.45	2606	1.97	13.44	106	197	Off Idle	60.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.11	15.13	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:1	35.45	2605	1.97	13.43	106	197	Off Idle	60.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.16	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:1	35.45	2599	1.96	13.41	106	197	Off Idle	61.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.19	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:1	35.45	2598	1.95	13.41	106	197	Off Idle	61.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.23	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:1	35.45	2594	1.94	13.42	106	197	Off Idle	61.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.25	15.05	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:1	35.45	2589	1.94	13.43	106	197	Off Idle	61.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.29	15.05	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:1	35.45	2590	1.93	13.43	106	197	Off Idle	61.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.35	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:1	35.45	2594	1.93	13.43	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.38	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:2	35.45	2597	1.92	13.43	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.38	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:2	35.45	2601	1.91	13.43	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.43	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:2	35.45	2601	1.9	13.43	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.47	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:2	35.45	2601	1.9	13.41	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.45	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:2	35.45	2606	1.89	13.41	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.47	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:2	35.45	2606	1.89	13.41	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.52	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:3	35.45	2599	1.88	13.41	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.52	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:3	35.45	2599	1.88	13.4	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.51	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:3	35.45	2598	1.87	13.41	106	197	Off Idle	61.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.6	14.76	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:3	35.45	2598	1.87	13.42	106	197	Off Idle	61.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.64	14.74	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:3	35.45	2601	1.86	13.41	106	197	Off Idle	61.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.71	14.74	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:3	35.45	2602	1.86	13.42	106	197	Off Idle	61.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.74	14.75	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:4	35.45	2604	1.85	13.42	106	197	Off Idle	61.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.82	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:4	35.45	2606	1.85	13.42	106	197	Off Idle	61.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.83	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:4	35.45	2606	1.84	13.43	106	197	Off Idle	61	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.85	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:02:4	35.45	2606	1.84	13.41	106	197	Off Idle	60.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.91	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:4	35.45	2604	1.83	13.41	106	197	Off Idle	60.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.91	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:4	35.45	2600	1.83	13.41	106	197	Off Idle	60.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.94	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:4	35.45	2600	1.82	13.39	106	197	Off Idle	60.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.99	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:5	35.45	2598	1.81	13.4	106	197	Off Idle	60.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.04	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:5	35.45	2597	1.8	13.41	106	197	Off Idle	60.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.1	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:02:5	35.45	2596	1.79	13.41	106	197	Off Idle	60.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.13	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:02:5	35.45	2596	1.79	13.41	106	197	Off Idle	60.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.19	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:02:5	35.45	2594	1.77	13.42	106	197	Off Idle	60.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.25	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:02:5	35.45	2594	1.77	13.42	106	197	Off Idle	60.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.3	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:6	35.45	2589	1.76	13.41	106	197	Off Idle	60.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.34	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:6	35.45	2582	1.75	13.41	106	197	Off Idle	60.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.37	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:6	35.45	2581	1.74	13.42	106	197	Off Idle	60.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.43	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:6	35.45	2572	1.73	13.41	106	197	Off Idle	60.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.49	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:6	35.45	2577	1.72	13.41	106	197	Off Idle	60.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.52	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:6	35.45	2579	1.71	13.41	106	197	Off Idle	61	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.55	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:6	35.45	2579	1.7	13.41	106	197	Off Idle	61.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.6	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:7	35.45	2578	1.69	13.42	106	197	Off Idle	61.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.66	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:7	35.45	2574	1.68	13.42	106	197	Off Idle	61.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.66	14.9	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:7	35.45	2574	1.67	13.41	106	197	Off Idle	61.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.68	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:7	35.45	2580	1.66	13.42	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.73	14.77	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:02:7	35.45	2570	1.65	13.44	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.76	14.72	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:7	35.45	2569	1.65	13.42	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.75	14.71	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:8	35.45	2568	1.64	13.42	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.78	14.7	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:8	35.45	2568	1.63	13.43	106	197	Off Idle	61.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.82	14.69	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:8	35.45	2565	1.63	13.41	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.84	14.7	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:02:8	35.45	2566	1.62	13.4	106	197	Off Idle	61.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.84	14.71	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:8	35.45	2566	1.61	13.41	106	197	Off Idle	62	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.86	14.73	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:8	35.45	2576	1.61	13.41	106	197	Off Idle	62.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.87	14.75	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:9	35.45	2567	1.6	13.41	106	197	Off Idle	62.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.88	14.77	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:9	35.45	2573	1.59	13.41	106	197	Off Idle	62.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.9	14.78	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:9	35.45	2574	1.59	13.42	106	197	Off Idle	62.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.91	14.79	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:9	35.45	2578	1.58	13.42	106	197	Off Idle	62.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.92	14.79	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:9	35.45	2581	1.58	13.42	106	197	Off Idle	62.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.96	14.79	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:9	35.45	2580	1.58	13.42	106	197	Off Idle	62.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.96	14.8	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:02:9	35.45	2580	1.58	13.42	107	197	Off Idle	62.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.97	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:0	35.45	2570	1.57	13.42	107	197	Off Idle	62.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.98	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:0	35.45	2580	1.57	13.42	107	197	Off Idle	62.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.97	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:0	35.45	2578	1.57	13.41	106	197	Off Idle	62.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.98	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:0	35.45	2599	1.56	13.41	106	197	Off Idle	62.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.96	14.94	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:0	35.45	2588	1.56	13.41	106	197	Off Idle	62.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.96	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:0	35.45	2575	1.56	13.41	107	197	Off Idle	62	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.98	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:1	35.45	2576	1.56	13.41	107	197	Off Idle	62	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:1	35.45	2578	1.56	13.43	107	197	Off Idle	62	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.98	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:1	35.45	2578	1.56	13.42	106	197	Off Idle	61.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.98	15.1	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:1	35.45	2581	1.56	13.42	106	197	Off Idle	61.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.97	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:1	35.45	2579	1.56	13.43	106	197	Off Idle	61.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.95	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:1	35.45	2579	1.56	13.42	106	197	Off Idle	61.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.97	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:1	35.45	2578	1.56	13.4	106	197	Off Idle	62	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.99	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:2	35.45	2575	1.56	13.41	106	197	Off Idle	61.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.98	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:2	35.45	2575	1.56	13.41	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:2	35.45	2573	1.56	13.4	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.01	15.14	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:2	35.45	2568	1.56	13.41	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-10	15.1	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:2	35.45	2567	1.56	13.41	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.98	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:2	35.45	2568	1.56	13.43	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.98	15.05	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:3	35.45	2570	1.56	13.43	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.98	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:3	35.45	2570	1.56	13.41	106	197	Off Idle	61.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.98	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:3	35.45	2570	1.56	13.43	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.97	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:3	35.45	2570	1.56	13.43	106	197	Off Idle	61.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.99	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:3	35.45	2571	1.56	13.44	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:3	35.45	2570	1.56	13.42	106	197	Off Idle	61.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.02	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:4	35.45	2558	1.56	13.42	106	197	Off Idle	62	0	2	132	944 Turbo	0.19	Rich	1	14.6	-9.99	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:4	35.45	2569	1.56	13.42	106	197	Off Idle	62	0	2	132	944 Turbo	0.23	Rich	1	14.6	-10	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:4	35.45	2563	1.56	13.42	106	197	Off Idle	62	0	2	132	944 Turbo	0.29	Rich	1	14.6	-10.02	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:4	35.45	2563	1.56	13.41	106	197	Off Idle	62	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.99	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:4	35.45	2556	1.56	13.41	106	197	Off Idle	62	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.98	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:4	35.45	2559	1.56	13.41	106	197	Off Idle	62	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.98	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:4	35.45	2559	1.56	13.42	106	197	Off Idle	62.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.01	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:5	35.45	2558	1.56	13.41	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.98	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:5	35.45	2550	1.56	13.41	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.99	14.9	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:5	35.45	2550	1.56	13.42	106	197	Off Idle	62.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.01	14.9	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:5	35.45	2555	1.56	13.43	106	197	Off Idle	62.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.01	14.95	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:5	35.45	2551	1.56	13.42	106	197	Off Idle	62.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:5	35.45	2562	1.56	13.42	106	197	Off Idle	62.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.99	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:6	35.45	2564	1.56	13.43	106	197	Off Idle	62.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:6	35.45	2571	1.55	13.42	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.02	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:03:6	35.45	2571	1.55	13.43	106	197	Off Idle	62.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:6	35.45	2581	1.55	13.43	106	197	Off Idle	62.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.02	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:6	35.45	2565	1.55	13.41	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.05	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:03:6	35.45	2559	1.55	13.42	106	197	Off Idle	62.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.05	15.01	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:6	35.45	2559	1.55	13.43	106	197	Off Idle	62.7	0	2	132	944 Turbo	0.35	Rich	1	14.6	-10.07	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:7	35.45	2558	1.55	13.43	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-10.06	14.97	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:7	35.45	2558	1.55	13.41	106	197	Off Idle	62.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.04	14.95	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:7	35.45	2557	1.55	13.41	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.02	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:7	35.45	2553	1.55	13.41	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.03	14.9	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:7	35.45	2532	1.55	13.41	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.02	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:7	35.45	2550	1.55	13.41	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.04	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:8	35.45	2550	1.55	13.41	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.01	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:8	35.45	2546	1.55	13.42	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:8	35.45	2546	1.55	13.43	106	197	Off Idle	62.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.01	14.81	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:8	35.45	2542	1.55	13.43	106	197	Off Idle	62.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.02	14.81	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:8	35.45	2541	1.55	13.42	106	197	Off Idle	62.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.01	14.8	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:8	35.45	2542	1.55	13.41	106	197	Off Idle	62.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.03	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:9	35.45	2540	1.55	13.42	106	197	Off Idle	62.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.03	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:9	35.45	2534	1.55	13.41	106	197	Off Idle	62.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.04	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:03:9	35.45	2533	1.55	13.41	106	197	Off Idle	63.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.03	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:03:9	35.45	2532	1.55	13.41	106	197	Off Idle	63.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10	14.9	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:9	35.45	2534	1.55	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:9	35.45	2539	1.55	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:03:9	35.45	2539	1.55	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-10	14.97	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:0	35.45	2540	1.55	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.99	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:0	35.45	2542	1.54	13.43	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-10.03	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:0	35.45	2533	1.54	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.02	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:0	35.45	2542	1.54	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.02	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:0	35.45	2540	1.54	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.02	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:0	35.45	2540	1.54	13.43	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.01	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:1	35.45	2542	1.54	13.43	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.02	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:1	35.45	2544	1.54	13.42	106	197	Off Idle	63.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.02	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:1	35.45	2544	1.54	13.42	106	197	Off Idle	63.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.02	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:1	35.45	2544	1.54	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10	15.05	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:1	35.45	2565	1.54	13.42	106	197	Off Idle	63.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.03	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:1	35.45	2554	1.54	13.44	106	197	Off Idle	63.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.02	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:1	35.45	2543	1.54	13.44	106	197	Off Idle	63.4	0	2	132	944 Turbo	0.62	Lean	1	14.6	-10.02	15.02	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:2	35.45	2536	1.54	13.44	106	197	Off Idle	63.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-10.01	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:2	35.45	2528	1.54	13.44	106	197	Off Idle	63.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-10.01	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:2	35.45	2528	1.54	13.43	106	197	Off Idle	63.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-10.04	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:2	35.45	2526	1.54	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-10.03	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:2	35.45	2523	1.53	13.4	106	197	Off Idle	63.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-10.04	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:2	35.45	2520	1.53	13.4	106	197	Off Idle	64	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.03	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:3	35.45	2512	1.53	13.41	107	197	Off Idle	64	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.02	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:3	35.45	2523	1.53	13.42	107	197	Off Idle	64	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.02	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:3	35.45	2522	1.53	13.42	107	197	Off Idle	64	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.06	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:3	35.45	2521	1.53	13.42	106	197	Off Idle	64	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.04	14.9	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:3	35.45	2520	1.53	13.44	106	197	Off Idle	64.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.04	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:3	35.45	2521	1.53	13.44	106	197	Off Idle	64.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.07	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:4	35.45	2521	1.53	13.42	106	197	Off Idle	64.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.06	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:4	35.45	2526	1.53	13.42	106	197	Off Idle	64.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.04	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:4	35.45	2527	1.53	13.43	106	197	Off Idle	64.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.05	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:4	35.45	2529	1.52	13.41	106	197	Off Idle	65	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.06	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:4	35.45	2530	1.52	13.42	106	197	Off Idle	65	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.05	14.9	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:4	35.45	2530	1.52	13.41	106	197	Off Idle	65	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.06	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:4	35.45	2547	1.52	13.4	106	197	Off Idle	64.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.04	14.95	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:5	35.45	2536	1.52	13.4	106	197	Off Idle	64.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.04	14.95	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:5	35.45	2524	1.52	13.4	106	197	Off Idle	64.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-10.05	14.99	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:5	35.45	2522	1.52	13.39	106	197	Off Idle	64.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.06	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:5	35.45	2520	1.52	13.4	106	197	Off Idle	64.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.06	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:5	35.45	2512	1.52	13.42	106	197	Off Idle	64.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.04	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:04:8	35.45	2512	1.52	13.41	106	197	Off Idle	64.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.03	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:6	35.45	2520	1.52	13.42	106	197	Off Idle	64.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.02	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:6	35.45	2516	1.52	13.42	106	197	Off Idle	64.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.02	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:6	35.45	2514	1.52	13.43	106	197	Off Idle	64.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.02	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:6	35.45	2514	1.52	13.42	106	197	Off Idle	64.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.04	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:6	35.45	2510	1.52	13.43	106	197	Off Idle	64.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.04	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:6	35.45	2508	1.52	13.42	106	197	Off Idle	64.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.03	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:6	35.45	2505	1.52	13.42	106	197	Off Idle	64.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.03	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:7	35.45	2505	1.52	13.41	106	197	Off Idle	65.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.02	15.09	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:04:7	35.45	2506	1.52	13.41	106	197	Off Idle	65.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.03	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:7	35.45	2509	1.52	13.42	106	197	Off Idle	65.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.05	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:7	35.45	2509	1.52	13.43	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-10.06	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:7	35.45	2514	1.52	13.43	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.08	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:7	35.45	2516	1.52	13.42	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.08	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:8	35.45	2516	1.52	13.41	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-10.08	14.9	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:8	35.45	2516	1.52	13.41	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.08	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:8	35.45	2513	1.52	13.42	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.07	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:8	35.45	2509	1.51	13.4	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.08	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:8	35.45	2508	1.51	13.4	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.05	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:8	35.45	2510	1.51	13.4	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.04	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:9	35.45	2508	1.51	13.41	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.03	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:9	35.45	2508	1.51	13.42	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.06	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:9	35.45	2504	1.51	13.41	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.06	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:9	35.45	2505	1.51	13.42	106	198	Off Idle	65.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.05	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:9	35.45	2504	1.51	13.41	106	198	Off Idle	65.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-10.06	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:9	35.45	2504	1.51	13.42	106	198	Off Idle	65.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.06	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:04:9	35.45	2503	1.51	13.41	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.06	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:05:0	35.45	2504	1.51	13.41	106	197	Off Idle	65.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.06	14.9	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:0	35.45	2504	1.51	13.41	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.07	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:0	35.45	2500	1.51	13.41	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.05	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:05:0	35.45	2498	1.51	13.41	106	197	Off Idle	65.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.06	14.95	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:05:0	35.45	2498	1.51	13.42	106	197	Off Idle	65.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.04	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:05:0	35.45	2495	1.51	13.41	106	197	Off Idle	65.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.02	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:05:1	35.45	2495	1.51	13.41	106	197	Off Idle	65.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.02	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:05:1	35.45	2495	1.51	13.41	106	197	Off Idle	65.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.04	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:1	35.45	2493	1.51	13.42	106	197	Off Idle	66.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.04	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:05:1	35.45	2492	1.51	13.41	106	197	Off Idle	66.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.04	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:05:1	35.45	2491	1.51	13.41	106	197	Off Idle	66.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.05	15.05	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:05:1	35.45	2490	1.51	13.41	106	197	Off Idle	66.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.05	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:1	35.45	2490	1.51	13.4	106	197	Off Idle	66.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.04	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:2	35.45	2488	1.51	13.41	106	197	Off Idle	67	0	2	132	944 Turbo	0.49	Rich	1	14.6	-10.07	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:2	35.45	2486	1.51	13.41	106	197	Off Idle	67.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.07	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:2	35.45	2484	1.51	13.39	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.06	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:2	35.45	2485	1.5	13.4	106	197	Off Idle	67.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-10.07	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:2	35.45	2485	1.5	13.4	106	197	Off Idle	67.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-10.08	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:2	35.45	2481	1.5	13.4	106	197	Off Idle	67.6	0	2	132	944 Turbo	0.2	Rich	1	14.6	-10.09	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:3	35.45	2479	1.5	13.4	106	197	Off Idle	67.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.08	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:3	35.45	2480	1.5	13.4	106	197	Off Idle	67.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.08	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:3	35.45	2480	1.5	13.4	106	197	Off Idle	67.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.07	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:3	35.45	2479	1.5	13.4	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.06	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:3	35.45	2478	1.5	13.41	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.03	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:3	35.45	2485	1.5	13.42	107	197	Off Idle	67.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.02	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:4	35.45	2485	1.5	13.41	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.02	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:05:4	35.45	2483	1.51	13.41	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.98	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:05:4	35.45	2484	1.51	13.41	106	197	Off Idle	67.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.98	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:05:4	35.45	2486	1.51	13.41	106	197	Off Idle	67.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.97	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:05:4	35.45	2489	1.51	13.42	106	197	Off Idle	67.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.98	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:05:4	35.45	2490	1.51	13.42	106	197	Off Idle	67.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.96	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:05:4	35.45	2488	1.51	13.42	106	197	Off Idle	67	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.97	14.9	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:5	35.45	2488	1.52	13.42	106	197	Off Idle	67	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.93	14.93	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:5	35.45	2488	1.52	13.41	106	197	Off Idle	67	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.91	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:5	35.45	2481	1.52	13.42	106	197	Off Idle	67.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.9	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:5	35.45	2481	1.53	13.41	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.91	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:5	35.45	2479	1.53	13.43	106	197	Off Idle	67.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.89	15.01	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:5	35.45	2480	1.54	13.43	106	197	Off Idle	67.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.92	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:6	35.45	2478	1.54	13.43	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.9	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:6	35.45	2478	1.54	13.43	106	197	Off Idle	67.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.89	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:6	35.45	2478	1.54	13.43	106	197	Off Idle	67.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.9	15.01	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:6	35.45	2474	1.55	13.42	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.87	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:6	35.45	2472	1.55	13.41	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.86	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:6	35.45	2470	1.55	13.41	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.84	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:6	35.45	2470	1.55	13.41	106	197	Off Idle	67.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.83	15.05	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:7	35.45	2469	1.55	13.43	106	197	Off Idle	67.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.79	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:7	35.45	2469	1.56	13.43	107	197	Off Idle	67.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.8	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:7	35.45	2468	1.56	13.44	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.78	15.01	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:7	35.45	2466	1.56	13.43	107	197	Off Idle	67.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.78	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:05:7	35.45	2465	1.57	13.43	106	197	Off Idle	67.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.74	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:05:7	35.45	2465	1.57	13.43	106	197	Off Idle	67.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.74	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:05:8	35.45	2465	1.58	13.42	106	197	Off Idle	67.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.66	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:8	35.45	2468	1.58	13.43	106	197	Off Idle	67.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.64	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:8	35.45	2466	1.59	13.43	106	197	Off Idle	67.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.63	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:8	35.45	2467	1.59	13.41	106	197	Off Idle	67.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.61	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:8	35.45	2471	1.59	13.41	106	197	Off Idle	67.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.58	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:8	35.45	2473	1.59	13.41	106	197	Off Idle	67.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.57	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:9	35.45	2478	1.6	13.41	106	197	Off Idle	67.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.58	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:9	35.45	2480	1.6	13.4	106	197	Off Idle	68	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:9	35.45	2482	1.61	13.41	106	197	Off Idle	68	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.58	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:9	35.45	2486	1.61	13.41	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.55	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:9	35.45	2488	1.62	13.4	106	197	Off Idle	68	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.53	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:9	35.45	2488	1.62	13.41	106	197	Off Idle	68	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.49	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:05:9	35.45	2488	1.63	13.4	106	197	Off Idle	68	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.46	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:06:0	35.45	2485	1.63	13.4	106	197	Off Idle	68	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.47	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:0	35.45	2484	1.63	13.41	106	197	Off Idle	68	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.47	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:0	35.45	2477	1.64	13.41	106	197	Off Idle	68	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.46	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:0	35.45	2477	1.65	13.4	106	197	Off Idle	68	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.43	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:0	35.45	2464	1.65	13.41	106	197	Off Idle	68	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.44	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:0	35.45	2458	1.65	13.4	106	197	Off Idle	68	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.4	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:1	35.45	2458	1.65	13.4	106	197	Off Idle	68	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.38	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:1	35.45	2454	1.65	13.41	106	197	Off Idle	68	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.38	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:1	35.45	2440	1.66	13.42	106	197	Off Idle	68.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.36	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:1	35.45	2448	1.66	13.42	106	197	Off Idle	68.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:1	35.45	2448	1.66	13.41	106	197	Off Idle	68.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.33	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:1	35.45	2449	1.66	13.41	106	197	Off Idle	68.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.3	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:1	35.45	2451	1.67	13.41	106	197	Off Idle	68.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.27	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:2	35.45	2453	1.67	13.41	106	197	Off Idle	68.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.28	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:2	35.45	2456	1.67	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.29	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:2	35.45	2457	1.67	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.29	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:2	35.45	2476	1.67	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.29	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:2	35.45	2476	1.67	13.42	106	197	Off Idle	69.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.28	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:2	35.45	2456	1.67	13.43	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.26	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:3	35.45	2455	1.68	13.43	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.25	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:3	35.45	2453	1.68	13.41	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.25	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:3	35.45	2440	1.68	13.42	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.23	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:06:3	35.45	2447	1.68	13.41	106	197	Off Idle	69.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.25	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:3	35.45	2444	1.68	13.41	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.21	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:3	35.45	2446	1.68	13.41	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.22	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:06:4	35.45	2449	1.68	13.41	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.2	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:4	35.45	2449	1.68	13.41	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.18	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:4	35.45	2454	1.68	13.41	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.15	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:4	35.45	2458	1.68	13.42	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.14	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:4	35.45	2456	1.69	13.42	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.16	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:4	35.45	2456	1.69	13.41	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.14	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:4	35.45	2452	1.69	13.41	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.14	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:5	35.45	2448	1.69	13.41	106	198	Off Idle	69.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.14	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:5	35.45	2438	1.7	13.42	106	198	Off Idle	69.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.13	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:5	35.45	2442	1.7	13.41	106	198	Off Idle	69.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.1	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:5	35.45	2437	1.71	13.41	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.05	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:06:5	35.45	2438	1.71	13.41	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.01	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:5	35.45	2438	1.71	13.42	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.01	14.9	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:6	35.45	2442	1.72	13.42	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:6	35.45	2447	1.72	13.42	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.96	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:6	35.45	2450	1.72	13.42	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.95	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:6	34.08	2456	1.73	13.42	106	198	Off Idle	69.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.94	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:6	34.08	2460	1.73	13.41	106	198	Off Idle	69.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.9	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:6	34.08	2463	1.73	13.4	106	198	Off Idle	69.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.84	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:6	34.08	2462	1.74	13.4	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.82	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:7	34.08	2461	1.74	13.4	107	197	Off Idle	69.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.78	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:7	34.08	2459	1.75	13.41	107	197	Off Idle	69.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.76	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:7	34.08	2459	1.76	13.4	107	197	Off Idle	69.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.73	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:06:7	34.08	2455	1.76	13.41	106	197	Off Idle	69.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.69	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:06:7	34.08	2453	1.77	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.63	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:06:7	34.08	2454	1.77	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.61	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:06:8	34.08	2445	1.78	13.42	106	197	Off Idle	69	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.56	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:06:8	34.08	2458	1.78	13.42	106	197	Off Idle	68.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.57	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:8	34.08	2472	1.79	13.41	106	197	Off Idle	68.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.56	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:8	35.45	2472	1.79	13.41	106	197	Off Idle	68.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.52	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:8	35.45	2456	1.79	13.41	106	197	Off Idle	68.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.49	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:8	35.45	2457	1.8	13.42	106	197	Off Idle	68.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.51	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:9	35.45	2457	1.8	13.41	106	197	Off Idle	68.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.46	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:9	35.45	2466	1.81	13.41	106	197	Off Idle	68.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.44	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:9	35.45	2466	1.81	13.42	106	197	Off Idle	68.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.47	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:9	35.45	2465	1.82	13.41	106	197	Off Idle	68.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.41	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:9	35.45	2464	1.82	13.42	106	197	Off Idle	68.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.4	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:9	35.45	2463	1.82	13.4	106	197	Off Idle	68.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.41	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:06:9	35.45	2463	1.83	13.4	106	197	Off Idle	68.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.38	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:0	35.45	2460	1.83	13.41	106	197	Off Idle	68.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.38	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:0	35.45	2458	1.84	13.41	106	197	Off Idle	68.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.36	14.91	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:07:0	35.45	2457	1.84	13.4	106	197	Off Idle	68.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.34	14.94	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:07:0	35.45	2444	1.84	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.31	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:07:0	35.45	2450	1.85	13.41	106	197	Off Idle	69.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.32	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:0	35.45	2447	1.85	13.42	106	198	Off Idle	69.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.29	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:1	35.45	2445	1.85	13.41	106	198	Off Idle	69.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.26	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:1	35.45	2454	1.85	13.42	106	198	Off Idle	69.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.23	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:1	34.08	2412	1.85	13.41	106	197	Off Idle	69.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.24	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:1	34.08	2428	1.86	13.41	106	197	Off Idle	69.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.22	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:1	34.08	2426	1.86	13.41	106	197	Off Idle	69.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.21	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:07:1	34.08	2422	1.86	13.41	106	197	Off Idle	69.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.21	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:07:1	34.08	2405	1.86	13.41	106	197	Off Idle	69.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.2	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:2	34.08	2416	1.86	13.42	106	197	Off Idle	69.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.19	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:2	34.08	2430	1.87	13.41	106	197	Off Idle	70.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.14	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:2	34.08	2434	1.87	13.4	106	197	Off Idle	70.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.12	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:2	34.08	2437	1.87	13.41	106	197	Off Idle	70.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.09	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:2	34.08	2446	1.87	13.4	106	197	Off Idle	70.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.08	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:2	34.08	2450	1.87	13.41	106	197	Off Idle	70	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.08	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:07:3	34.08	2452	1.87	13.41	106	197	Off Idle	70	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.08	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:3	34.08	2455	1.87	13.41	106	197	Off Idle	70.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.09	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:3	34.08	2453	1.87	13.41	106	197	Off Idle	70.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.07	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:3	34.08	2453	1.87	13.41	106	197	Off Idle	70.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.05	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:3	34.08	2443	1.87	13.4	106	197	Off Idle	69.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.03	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:3	34.08	2444	1.88	13.37	106	197	Off Idle	69.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:4	34.08	2444	1.88	13.38	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:07:4	34.08	2448	1.88	13.4	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.99	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:07:4	34.08	2453	1.88	13.4	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.96	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:07:4	34.08	2453	1.89	13.41	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.93	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:07:4	34.08	2463	1.89	13.41	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.9	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:4	34.08	2466	1.89	13.42	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.86	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:4	34.08	2468	1.9	13.41	106	197	Off Idle	69.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.84	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:5	34.08	2468	1.9	13.42	106	197	Off Idle	69.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.82	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:5	34.08	2476	1.9	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.84	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:5	34.08	2460	1.91	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.8	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:5	34.08	2455	1.91	13.4	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	14.81	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:5	34.08	2455	1.92	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.76	14.81	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:5	34.08	2454	1.92	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:6	34.08	2451	1.93	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.9	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:6	34.08	2449	1.93	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.65	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:6	34.08	2446	1.94	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.58	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:6	34.08	2446	1.95	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.52	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:6	34.08	2440	1.95	13.42	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.48	15.12	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:6	34.08	2456	1.95	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.47	15.17	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:6	34.08	2460	1.96	13.41	106	197	Off Idle	69.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.46	15.21	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:7	34.08	2460	1.96	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.48	15.22	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:7	34.08	2468	1.96	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.48	15.23	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:7	34.08	2456	1.97	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.5	15.22	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:7	34.08	2456	1.97	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.48	15.2	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:7	34.08	2451	1.97	13.4	106	197	Off Idle	69	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.47	15.16	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:7	34.08	2454	1.97	13.41	106	197	Off Idle	69	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.44	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:8	34.08	2446	1.98	13.41	106	197	Off Idle	69.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.46	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:07:8	34.08	2446	1.98	13.42	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.45	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:8	34.08	2448	1.98	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.47	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:8	34.08	2451	1.98	13.41	106	197	Off Idle	69.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.46	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:8	34.08	2452	1.98	13.4	106	197	Off Idle	69.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.44	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:8	34.08	2455	1.98	13.4	106	197	Off Idle	69	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.45	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:9	34.08	2465	1.98	13.4	106	197	Off Idle	69	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.43	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:9	34.08	2465	1.98	13.41	106	197	Off Idle	69.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.47	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:9	34.08	2471	1.98	13.4	106	197	Off Idle	69.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.48	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:9	34.08	2471	1.98	13.4	106	197	Off Idle	69	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.48	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:9	34.08	2468	1.98	13.39	106	197	Off Idle	69	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.45	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:9	34.08	2466	1.98	13.4	106	198	Off Idle	69	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.43	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:07:9	34.08	2460	1.98	13.4	106	198	Off Idle	69	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.46	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:0	34.08	2454	1.98	13.39	106	198	Off Idle	68.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.42	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:0	34.08	2455	1.98	13.4	106	198	Off Idle	68.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.41	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:0	34.08	2452	1.98	13.41	106	198	Off Idle	68.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.44	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:0	34.08	2449	1.98	13.42	106	198	Off Idle	68.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.43	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:0	34.08	2449	1.98	13.42	106	198	Off Idle	68.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.43	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:0	34.08	2456	1.98	13.4	106	198	Off Idle	68.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.41	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:1	34.08	2459	1.99	13.4	106	197	Off Idle	68.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.38	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:1	34.08	2466	1.99	13.4	106	197	Off Idle	68.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.34	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:1	34.08	2467	1.99	13.4	106	197	Off Idle	68.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.3	15.24	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:1	34.08	2472	2	13.4	106	198	Off Idle	68.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.2	15.22	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:1	34.08	2472	2	13.42	106	198	Off Idle	68.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.16	15.21	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:08:1	34.08	2472	2.02	13.42	106	198	Off Idle	68.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.1	15.19	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:08:1	34.08	2469	2.03	13.41	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.97	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:08:2	34.08	2467	2.04	13.42	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.86	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:08:2	34.08	2467	2.05	13.41	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.75	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:08:2	34.08	2464	2.06	13.42	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.67	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:08:2	34.08	2458	2.06	13.42	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.55	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:2	34.08	2473	2.08	13.43	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.44	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:2	34.08	2474	2.09	13.41	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.39	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:3	34.08	2480	2.1	13.43	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.33	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:3	34.08	2484	2.11	13.42	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.27	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:3	34.08	2484	2.13	13.42	106	197	Off Idle	68	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.17	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:3	34.08	2480	2.14	13.4	106	197	Off Idle	67.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.11	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:3	34.08	2474	2.15	13.4	106	198	Off Idle	67.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.07	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:3	34.08	2467	2.16	13.39	106	198	Off Idle	67.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:08:4	34.08	2466	2.17	13.4	106	198	Off Idle	67.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.96	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:4	34.08	2457	2.19	13.39	106	198	Off Idle	67.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.91	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:4	34.08	2457	2.2	13.39	106	197	Off Idle	67.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.84	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:4	34.08	2458	2.21	13.39	106	197	Off Idle	67.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.8	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:4	34.08	2466	2.21	13.39	106	197	Off Idle	67.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.81	15.17	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:4	34.08	2469	2.22	13.39	106	198	Off Idle	67.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.78	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:4	34.08	2472	2.22	13.39	106	198	Off Idle	67.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.77	15.15	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:5	34.08	2482	2.22	13.41	106	197	Off Idle	67.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.79	15.18	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:5	34.08	2488	2.22	13.42	106	197	Off Idle	67.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.76	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:5	34.08	2488	2.22	13.42	106	197	Off Idle	67.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.73	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:08:5	34.08	2485	2.23	13.4	106	198	Off Idle	67.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.76	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:08:5	34.08	2483	2.23	13.4	106	198	Off Idle	67.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.8	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:5	34.08	2483	2.23	13.42	106	198	Off Idle	68.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.79	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:6	34.08	2473	2.23	13.41	106	198	Off Idle	68.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.81	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:6	34.08	2470	2.23	13.41	106	198	Off Idle	68.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.81	14.77	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:08:6	34.08	2467	2.23	13.41	106	198	Off Idle	68.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.81	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:6	34.08	2468	2.23	13.41	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.8	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:6	34.08	2471	2.23	13.4	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.86	14.73	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:6	34.08	2479	2.23	13.4	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.86	14.72	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:6	34.08	2491	2.23	13.41	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.86	14.74	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:7	34.08	2491	2.23	13.41	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.88	14.72	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:08:7	34.08	2498	2.23	13.41	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.88	14.75	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:08:7	34.08	2498	2.23	13.41	106	197	Off Idle	68.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.87	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:08:7	34.08	2500	2.22	13.41	106	198	Off Idle	67.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.84	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:7	34.08	2498	2.23	13.4	106	198	Off Idle	67.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.84	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:7	34.08	2502	2.23	13.41	106	197	Off Idle	67.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.86	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:8	34.08	2502	2.23	13.41	106	197	Off Idle	67.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.85	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:8	34.08	2505	2.23	13.41	106	197	Off Idle	67.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.81	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:8	34.08	2505	2.23	13.4	106	198	Off Idle	67.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.8	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:8	34.08	2506	2.23	13.41	106	198	Off Idle	67.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.78	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:8	34.08	2508	2.23	13.41	106	198	Off Idle	67	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.79	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:8	34.08	2510	2.23	13.4	106	197	Off Idle	66.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.76	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:9	34.08	2512	2.23	13.41	106	197	Off Idle	66.8	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.78	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:9	34.08	2512	2.23	13.41	106	197	Off Idle	66.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.8	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:9	34.08	2512	2.23	13.41	106	197	Off Idle	66.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.78	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:9	34.08	2511	2.23	13.42	106	197	Off Idle	66.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.73	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:9	32.72	2494	2.24	13.41	106	197	Off Idle	66.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.69	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:9	32.72	2497	2.24	13.41	106	197	Off Idle	66	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.64	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:08:9	32.72	2489	2.24	13.41	106	197	Off Idle	65.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.66	15.05	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:0	32.72	2489	2.24	13.4	106	197	Off Idle	65.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.64	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:0	32.72	2485	2.25	13.41	106	198	Off Idle	65.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.61	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:0	32.72	2486	2.25	13.41	106	198	Off Idle	66	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.59	14.94	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:0	32.72	2487	2.25	13.42	106	198	Off Idle	66.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.6	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:0	32.72	2489	2.26	13.41	106	197	Off Idle	66.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.56	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:0	32.72	2497	2.26	13.41	106	197	Off Idle	66.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.53	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:1	32.72	2499	2.26	13.4	106	197	Off Idle	66.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.52	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:09:1	32.72	2502	2.26	13.4	106	197	Off Idle	66.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.53	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:1	32.72	2503	2.26	13.4	106	197	Off Idle	67.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.52	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:1	32.72	2499	2.27	13.41	106	197	Off Idle	67.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.49	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:1	32.72	2499	2.27	13.4	106	198	Off Idle	67.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.5	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:1	32.72	2498	2.27	13.41	106	198	Off Idle	67.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.5	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:1	32.72	2494	2.27	13.4	106	198	Off Idle	67.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.52	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:2	32.72	2494	2.27	13.41	106	198	Off Idle	67.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.51	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:2	32.72	2494	2.27	13.41	106	198	Off Idle	67.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.52	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:2	32.72	2490	2.27	13.42	106	198	Off Idle	66.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.5	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:2	32.72	2489	2.27	13.41	106	198	Off Idle	66.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.52	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:2	32.72	2489	2.27	13.41	106	198	Off Idle	66.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.49	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:2	32.72	2497	2.27	13.4	106	198	Off Idle	66.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.49	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:3	32.72	2510	2.27	13.41	106	198	Off Idle	66.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.48	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:3	32.72	2517	2.27	13.41	106	198	Off Idle	66.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.48	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:3	32.72	2516	2.27	13.42	106	198	Off Idle	66.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.51	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:3	32.72	2520	2.27	13.42	106	198	Off Idle	66.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.52	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:3	32.72	2520	2.27	13.42	106	198	Off Idle	66.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.52	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:3	32.72	2519	2.27	13.41	106	198	Off Idle	66.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.53	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:4	32.72	2512	2.27	13.41	106	198	Off Idle	66.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.53	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:4	32.72	2508	2.27	13.41	106	197	Off Idle	66.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.54	14.75	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:4	32.72	2506	2.27	13.41	106	197	Off Idle	66.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.5	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:4	32.72	2502	2.27	13.41	106	197	Off Idle	66.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.49	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:4	32.72	2502	2.27	13.41	106	198	Off Idle	66.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.49	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:4	32.72	2511	2.27	13.4	106	198	Off Idle	66.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.5	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:4	32.72	2518	2.27	13.4	106	198	Off Idle	66	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.49	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:5	32.72	2525	2.27	13.4	106	198	Off Idle	65.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.48	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:5	32.72	2526	2.27	13.41	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.49	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:5	32.72	2532	2.27	13.4	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.5	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:5	32.72	2533	2.28	13.4	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.47	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:5	32.72	2532	2.28	13.4	106	198	Off Idle	65.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.46	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:5	32.72	2522	2.28	13.4	106	198	Off Idle	65.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.47	14.9	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:6	32.72	2517	2.28	13.41	106	198	Off Idle	65.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.49	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:6	32.72	2513	2.28	13.41	106	198	Off Idle	64.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.5	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:6	32.72	2513	2.28	13.41	106	197	Off Idle	64.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.46	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:6	32.72	2510	2.28	13.41	106	197	Off Idle	64.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.46	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:6	32.72	2514	2.28	13.42	106	197	Off Idle	64.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.43	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:6	32.72	2514	2.28	13.4	107	198	Off Idle	64.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.45	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:6	32.72	2520	2.28	13.4	107	198	Off Idle	64.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.39	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:7	34.08	2547	2.28	13.41	107	198	Off Idle	64.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.38	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:7	34.08	2538	2.28	13.41	106	197	Off Idle	64.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.37	14.9	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:7	34.08	2534	2.29	13.43	106	197	Off Idle	64.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.35	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:09:7	34.08	2532	2.29	13.43	106	197	Off Idle	64.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.34	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:7	34.08	2529	2.29	13.43	106	197	Off Idle	64.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.38	14.69	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:7	34.08	2529	2.29	13.42	106	197	Off Idle	64.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.36	14.65	1	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:8	32.72	2513	2.29	13.43	106	197	Off Idle	64.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.39	14.65	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:8	32.72	2538	2.29	13.41	106	197	Off Idle	64.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.39	14.65	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:8	32.72	2538	2.29	13.41	106	197	Off Idle	64.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.4	14.67	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:8	32.72	2538	2.29	13.41	106	197	Off Idle	64.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.37	14.69	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:8	32.72	2540	2.29	13.4	106	197	Off Idle	64.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.39	14.72	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:09:8	32.72	2539	2.29	13.39	106	198	Off Idle	64.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.36	14.76	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:9	32.72	2539	2.3	13.4	106	198	Off Idle	64.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.35	14.79	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:9	32.72	2542	2.3	13.41	106	197	Off Idle	64	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.34	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:9	32.72	2542	2.3	13.42	106	197	Off Idle	63.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.39	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:9	32.72	2534	2.3	13.41	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.38	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:9	32.72	2532	2.3	13.41	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.35	14.89	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:9	32.72	2532	2.3	13.41	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.33	14.92	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:09:9	32.72	2533	2.3	13.42	106	197	Off Idle	63.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.37	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:0	32.72	2533	2.3	13.4	106	197	Off Idle	63.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.35	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:10:0	32.72	2542	2.3	13.41	106	198	Off Idle	63.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.36	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:0	32.72	2557	2.3	13.4	106	198	Off Idle	63.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.34	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:0	32.72	2557	2.31	13.39	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.38	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:0	32.72	2558	2.31	13.4	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.34	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:0	32.72	2552	2.31	13.37	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.32	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:1	32.72	2549	2.31	13.39	106	198	Off Idle	63.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.36	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:1	32.72	2549	2.31	13.4	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.37	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:1	32.72	2547	2.31	13.4	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.34	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:1	32.72	2535	2.31	13.4	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.32	14.86	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:1	32.72	2537	2.31	13.42	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.34	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:1	32.72	2537	2.31	13.41	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.38	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:1	32.72	2545	2.31	13.41	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.35	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:2	32.72	2548	2.31	13.42	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.33	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:2	32.72	2548	2.31	13.42	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.39	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:2	32.72	2553	2.31	13.42	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.37	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:2	32.72	2555	2.31	13.42	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.31	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:2	32.72	2557	2.31	13.43	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.35	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:2	32.72	2564	2.31	13.42	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5.33	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:3	32.72	2570	2.31	13.42	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.37	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:3	32.72	2568	2.31	13.4	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.38	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:3	32.72	2568	2.31	13.41	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.39	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:3	32.72	2558	2.31	13.41	106	198	Off Idle	63.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.4	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:3	34.08	2551	2.31	13.4	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.37	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:3	34.08	2548	2.31	13.4	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.37	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:4	34.08	2548	2.31	13.4	107	198	Off Idle	63.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.39	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:4	34.08	2551	2.31	13.39	106	198	Off Idle	63.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.33	15.05	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:4	34.08	2553	2.31	13.4	106	198	Off Idle	63.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.31	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:4	32.72	2554	2.31	13.41	106	198	Off Idle	63.4	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.37	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:4	32.72	2552	2.31	13.41	106	198	Off Idle	63.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.32	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:4	32.72	2572	2.31	13.4	106	198	Off Idle	63.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.34	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:4	32.72	2572	2.32	13.4	106	198	Off Idle	63.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.33	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:5	32.72	2572	2.31	13.4	106	197	Off Idle	63.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.33	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:5	32.72	2568	2.31	13.41	106	197	Off Idle	63.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.36	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:5	32.72	2585	2.32	13.39	106	197	Off Idle	63.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.37	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:5	34.08	2583	2.32	13.38	106	198	Off Idle	63.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.34	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:5	34.08	2563	2.32	13.39	106	198	Off Idle	63.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.33	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:5	34.08	2566	2.32	13.4	106	198	Off Idle	63.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.35	14.82	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:6	34.08	2568	2.32	13.42	106	198	Off Idle	63.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.32	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:6	34.08	2571	2.32	13.41	106	198	Off Idle	63.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.37	14.75	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:6	32.72	2551	2.32	13.42	106	198	Off Idle	62.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.35	14.75	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:6	32.72	2560	2.32	13.43	106	198	Off Idle	62.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.36	14.75	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:6	32.72	2570	2.32	13.42	106	198	Off Idle	62.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.39	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:6	32.72	2572	2.32	13.42	106	198	Off Idle	62.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.37	14.75	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:6	32.72	2572	2.32	13.42	106	198	Off Idle	62.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.35	14.76	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:7	32.72	2564	2.32	13.4	106	198	Off Idle	62.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.36	14.79	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:7	34.08	2595	2.32	13.41	106	198	Off Idle	62.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.35	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:7	34.08	2584	2.32	13.4	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.3	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:7	34.08	2575	2.32	13.41	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.31	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:7	34.08	2594	2.32	13.4	106	197	Off Idle	62.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.33	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:7	34.08	2574	2.32	13.42	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.34	14.8	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:8	34.08	2574	2.32	13.42	106	198	Off Idle	62	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.33	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:8	32.72	2554	2.32	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.34	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:8	32.72	2576	2.33	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.29	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:10:8	32.72	2577	2.33	13.41	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.26	14.9	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:8	32.72	2577	2.33	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.3	14.92	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:8	32.72	2579	2.33	13.41	106	197	Off Idle	61.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.32	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:9	32.72	2581	2.33	13.41	106	197	Off Idle	62.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.28	15.04	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:9	34.08	2591	2.33	13.41	106	197	Off Idle	62.1	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.26	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:10:9	34.08	2583	2.33	13.42	106	198	Off Idle	62	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.3	15.11	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:10:9	34.08	2584	2.33	13.41	106	198	Off Idle	62	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.27	15.12	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:9	34.08	2584	2.33	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.33	15.1	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:9	34.08	2587	2.33	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.34	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:10:9	34.08	2589	2.33	13.4	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.36	15.06	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:0	34.08	2590	2.33	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.39	15.03	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:0	34.08	2592	2.33	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.36	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:0	34.08	2593	2.33	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.33	14.92	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:0	34.08	2589	2.33	13.4	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5.32	14.89	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:0	34.08	2589	2.33	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5.33	14.88	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:0	34.08	2588	2.33	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.34	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:1	34.08	2588	2.33	13.39	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.29	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:1	34.08	2587	2.33	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.32	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:1	34.08	2586	2.33	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.32	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:1	34.08	2589	2.33	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.29	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:1	34.08	2590	2.33	13.4	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.27	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:1	34.08	2596	2.33	13.4	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.3	15.06	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:1	34.08	2601	2.33	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.31	15.1	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:2	34.08	2602	2.33	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.34	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:2	34.08	2605	2.33	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.32	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:2	34.08	2598	2.33	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.32	15.05	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:2	34.08	2599	2.34	13.42	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.32	15.02	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:2	34.08	2600	2.34	13.41	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.31	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:2	34.08	2600	2.34	13.41	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.29	14.93	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:3	34.08	2605	2.34	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.31	14.91	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:3	34.08	2606	2.34	13.42	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.32	14.87	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:3	34.08	2611	2.34	13.41	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.31	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:3	34.08	2618	2.34	13.41	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.34	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:3	34.08	2618	2.34	13.41	106	198	Off Idle	61.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.35	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:3	34.08	2617	2.34	13.4	106	198	Off Idle	61	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.38	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:4	34.08	2617	2.34	13.4	106	198	Off Idle	61	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.36	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:4	34.08	2614	2.34	13.41	106	198	Off Idle	61	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.39	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:4	34.08	2614	2.34	13.4	106	198	Off Idle	60.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.41	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:4	34.08	2611	2.34	13.41	106	198	Off Idle	60.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.38	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:4	34.08	2613	2.34	13.39	106	198	Off Idle	60.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.34	14.9	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:4	34.08	2613	2.34	13.41	106	198	Off Idle	60.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.35	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:4	34.08	2617	2.34	13.41	106	198	Off Idle	60.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.35	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:5	34.08	2618	2.34	13.39	106	198	Off Idle	60.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.3	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:5	34.08	2620	2.34	13.39	106	197	Off Idle	60.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.27	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:5	34.08	2621	2.34	13.41	106	197	Off Idle	60.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.33	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:5	34.08	2618	2.34	13.41	106	197	Off Idle	60.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.34	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:5	34.08	2616	2.34	13.41	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.33	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:5	34.08	2617	2.34	13.42	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.36	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:6	34.08	2615	2.34	13.43	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.31	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:6	34.08	2617	2.34	13.43	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.32	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:6	34.08	2618	2.35	13.42	106	197	Off Idle	59.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.31	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:6	34.08	2619	2.35	13.42	106	197	Off Idle	59.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.3	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:6	34.08	2622	2.35	13.4	106	197	Off Idle	60.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.31	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:6	34.08	2626	2.35	13.41	106	198	Off Idle	60.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.33	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:6	34.08	2627	2.35	13.41	106	198	Off Idle	60.1	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.29	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:7	34.08	2628	2.35	13.4	106	198	Off Idle	60.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.3	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:7	34.08	2622	2.35	13.4	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.32	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:7	34.08	2622	2.35	13.41	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.31	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:7	34.08	2628	2.34	13.42	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.35	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:11:7	34.08	2631	2.34	13.42	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.33	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:7	34.08	2632	2.34	13.42	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.41	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:11:8	34.08	2632	2.34	13.41	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.41	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:8	34.08	2632	2.34	13.42	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.39	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:11:8	34.08	2634	2.34	13.41	106	198	Off Idle	59.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.37	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:8	34.08	2634	2.34	13.4	106	198	Off Idle	59.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.36	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:8	34.08	2639	2.34	13.39	106	198	Off Idle	59	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.37	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:8	34.08	2640	2.34	13.4	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.39	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:9	34.08	2642	2.34	13.39	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.41	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:9	34.08	2642	2.34	13.4	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.41	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:9	34.08	2642	2.34	13.41	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.42	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:9	34.08	2641	2.34	13.41	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.47	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:9	34.08	2639	2.34	13.39	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.47	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:9	34.08	2639	2.33	13.41	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.52	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:11:9	34.08	2642	2.33	13.41	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.62	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:12:0	34.08	2641	2.33	13.39	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.65	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:0	34.08	2641	2.32	13.4	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.71	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:0	34.08	2640	2.32	13.41	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.79	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:0	34.08	2639	2.31	13.41	106	198	Off Idle	59	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.82	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:12:0	34.08	2643	2.31	13.41	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.97	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:12:0	34.08	2642	2.3	13.41	106	197	Off Idle	58.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.03	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:12:1	34.08	2642	2.29	13.41	106	197	Off Idle	58.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.14	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:12:1	34.08	2643	2.28	13.41	106	197	Off Idle	58.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.23	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:12:1	34.08	2653	2.27	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.38	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:12:1	34.08	2638	2.26	13.41	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.4	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:12:1	34.08	2638	2.25	13.41	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.47	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:12:1	34.08	2638	2.24	13.43	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.59	14.73	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:12:1	34.08	2639	2.23	13.42	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.64	14.75	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:2	34.08	2638	2.22	13.43	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.65	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:2	34.08	2638	2.21	13.43	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.75	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:2	34.08	2621	2.2	13.43	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.81	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:2	34.08	2639	2.18	13.41	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.84	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:2	34.08	2639	2.17	13.42	107	198	Off Idle	58.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.91	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:2	34.08	2639	2.17	13.41	107	198	Off Idle	58.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.96	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:3	34.08	2654	2.16	13.4	107	198	Off Idle	58.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:12:3	34.08	2634	2.15	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.01	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:12:3	34.08	2634	2.14	13.42	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.06	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:12:3	34.08	2637	2.13	13.41	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.1	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:3	34.08	2637	2.13	13.42	106	197	Off Idle	58.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.14	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:3	34.08	2626	2.12	13.42	106	197	Off Idle	58.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.18	14.9	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:12:4	34.08	2654	2.12	13.41	106	197	Off Idle	58.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.2	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:4	34.08	2654	2.12	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.22	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:4	34.08	2656	2.11	13.41	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.23	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:12:4	34.08	2655	2.1	13.39	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.26	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:12:4	34.08	2653	2.1	13.4	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.27	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:4	34.08	2644	2.1	13.4	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.16	Rich	1	14.6	-7.27	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:4	34.08	2644	2.09	13.41	106	198	Off Idle	58.1	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.32	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:5	34.08	2661	2.09	13.4	106	198	Off Idle	57.9	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.3	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:12:5	34.08	2636	2.09	13.42	106	198	Off Idle	57.8	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.34	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:5	34.08	2636	2.08	13.41	106	198	Off Idle	57.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.4	15.13	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:5	34.08	2636	2.08	13.41	106	198	Off Idle	57.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.4	15.15	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:5	34.08	2641	2.07	13.42	106	198	Off Idle	57.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.48	15.19	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:5	34.08	2641	2.07	13.43	106	198	Off Idle	57.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.5	15.2	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:6	34.08	2645	2.07	13.42	106	198	Off Idle	57.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.52	15.19	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:6	34.08	2646	2.06	13.43	106	198	Off Idle	57.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.51	15.17	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:6	34.08	2653	2.06	13.42	106	198	Off Idle	57.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.54	15.18	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:6	34.08	2653	2.06	13.42	106	198	Off Idle	57.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.59	15.15	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:6	34.08	2658	2.05	13.41	106	198	Off Idle	57.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.61	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:6	34.08	2654	2.05	13.41	106	197	Off Idle	57.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.6	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:6	34.08	2654	2.05	13.42	106	197	Off Idle	57.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.63	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:7	34.08	2653	2.05	13.41	106	197	Off Idle	57.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.65	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:7	34.08	2650	2.04	13.42	106	198	Off Idle	57.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.63	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:12:7	34.08	2650	2.04	13.42	106	198	Off Idle	57.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.66	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:7	34.08	2639	2.04	13.42	106	198	Off Idle	57.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.69	14.96	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:7	34.08	2618	2.03	13.42	106	198	Off Idle	57.9	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.7	14.91	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:7	34.08	2618	2.03	13.44	106	198	Off Idle	57.9	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.7	14.9	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:8	35.45	2662	2.03	13.44	106	198	Off Idle	58.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:8	35.45	2644	2.03	13.44	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.75	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:8	35.45	2651	2.02	13.44	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:8	35.45	2652	2.02	13.44	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:8	35.45	2656	2.02	13.42	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:8	35.45	2658	2.02	13.42	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.79	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:9	35.45	2658	2.02	13.41	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.76	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:9	35.45	2670	2.02	13.41	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.78	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:12:9	35.45	2658	2.02	13.4	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.83	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:9	35.45	2652	2.01	13.4	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.82	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:9	35.45	2652	2.01	13.42	106	198	Off Idle	58.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.84	15.13	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:9	35.45	2622	2.01	13.41	106	198	Off Idle	57.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.89	15.16	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:12:9	35.45	2636	2.01	13.41	106	198	Off Idle	57.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.88	15.16	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:13:0	35.45	2634	2	13.42	106	198	Off Idle	57.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.91	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:13:0	35.45	2630	2	13.42	106	198	Off Idle	57.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.92	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:13:0	35.45	2636	2	13.4	106	198	Off Idle	57.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.91	15.13	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:0	35.45	2642	1.99	13.41	106	198	Off Idle	57.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.95	15.13	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:0	35.45	2642	1.99	13.42	106	198	Off Idle	57.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.95	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:0	35.45	2649	1.99	13.42	106	198	Off Idle	57.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:1	35.45	2655	1.98	13.4	106	198	Off Idle	57.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.05	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:13:1	35.45	2655	1.98	13.41	106	198	Off Idle	57.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.06	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:13:1	35.45	2657	1.98	13.4	106	198	Off Idle	57.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.1	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:13:1	35.45	2678	1.97	13.41	106	198	Off Idle	57.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.17	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:1	35.45	2668	1.97	13.4	106	198	Off Idle	57.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.17	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:1	35.45	2658	1.96	13.41	106	198	Off Idle	57.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.18	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:1	35.45	2649	1.96	13.42	106	198	Off Idle	57.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.23	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:2	35.45	2649	1.96	13.42	106	198	Off Idle	57.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.27	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:2	35.45	2645	1.95	13.41	106	197	Off Idle	57.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.27	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:2	35.45	2634	1.95	13.41	106	197	Off Idle	58	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.32	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:2	35.45	2634	1.94	13.42	106	198	Off Idle	58	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.36	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:2	35.45	2636	1.93	13.42	106	198	Off Idle	58	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.36	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:2	35.45	2639	1.93	13.4	106	198	Off Idle	58	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.41	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:3	35.45	2638	1.92	13.41	106	198	Off Idle	58.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.42	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:3	35.45	2638	1.92	13.43	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.46	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:3	35.45	2646	1.92	13.41	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.46	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:3	35.45	2647	1.91	13.41	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.47	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:3	35.45	2647	1.91	13.43	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.5	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:3	35.45	2646	1.9	13.43	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.51	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:4	35.45	2656	1.9	13.41	106	197	Off Idle	58.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.52	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:4	35.45	2644	1.9	13.41	106	197	Off Idle	58.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.53	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:4	35.45	2644	1.9	13.41	106	197	Off Idle	58.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.52	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:4	35.45	2643	1.89	13.4	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.53	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:4	35.45	2645	1.89	13.42	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.57	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:4	35.45	2635	1.89	13.42	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.57	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:4	35.45	2646	1.89	13.42	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.52	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:5	35.45	2646	1.89	13.42	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.55	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:5	35.45	2645	1.89	13.41	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.52	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:5	35.45	2641	1.89	13.41	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.52	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:5	35.45	2640	1.89	13.41	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.55	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:5	35.45	2640	1.89	13.4	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.52	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:5	35.45	2640	1.89	13.41	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.53	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:6	35.45	2641	1.89	13.41	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.58	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:6	35.45	2646	1.89	13.4	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.56	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:6	35.45	2646	1.89	13.4	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.59	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:13:6	35.45	2656	1.89	13.41	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.55	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:6	35.45	2645	1.89	13.43	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.56	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:6	35.45	2645	1.89	13.41	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.54	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:6	35.45	2642	1.89	13.42	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.53	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:7	35.45	2628	1.89	13.42	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.52	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:7	35.45	2639	1.89	13.43	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.54	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:7	35.45	2640	1.89	13.42	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.54	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:7	35.45	2643	1.89	13.43	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.54	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:7	35.45	2645	1.89	13.43	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.56	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:7	35.45	2644	1.89	13.42	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.52	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:8	35.45	2644	1.89	13.42	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.51	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:8	35.45	2644	1.89	13.43	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.53	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:8	35.45	2644	1.9	13.41	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.52	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:8	35.45	2651	1.9	13.41	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.49	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:8	35.45	2639	1.9	13.42	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.52	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:8	35.45	2637	1.9	13.41	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.52	15.13	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:9	35.45	2638	1.9	13.41	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.5	15.14	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:9	35.45	2624	1.9	13.42	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.52	15.14	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:9	35.45	2628	1.9	13.41	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.51	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:9	35.45	2628	1.9	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.51	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:9	35.45	2628	1.9	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.52	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:13:9	35.45	2630	1.9	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.5	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:13:9	35.45	2630	1.9	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.48	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:0	35.45	2628	1.9	13.42	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.5	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:0	35.45	2629	1.9	13.42	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.47	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:0	35.45	2632	1.9	13.41	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.48	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:0	35.45	2636	1.9	13.43	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.49	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:0	35.45	2639	1.9	13.43	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.5	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:0	35.45	2640	1.9	13.41	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.49	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:1	35.45	2645	1.9	13.42	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.47	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:1	35.45	2645	1.9	13.41	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.48	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:1	35.45	2647	1.9	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.51	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:1	35.45	2637	1.9	13.4	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.48	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:1	35.45	2636	1.9	13.4	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.46	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:1	35.45	2646	1.9	13.42	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.51	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:1	35.45	2632	1.9	13.42	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.51	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:2	35.45	2633	1.9	13.43	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.48	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:2	35.45	2633	1.9	13.43	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.45	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:2	35.45	2613	1.9	13.44	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.48	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:2	35.45	2629	1.9	13.44	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.46	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:2	35.45	2629	1.9	13.42	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.45	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:2	35.45	2625	1.9	13.41	106	198	Off Idle	58	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.42	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:3	35.45	2625	1.9	13.42	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.45	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:3	35.45	2630	1.9	13.42	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.46	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:3	35.45	2632	1.9	13.41	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.43	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:3	35.45	2634	1.9	13.4	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.46	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:3	35.45	2636	1.9	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.44	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:3	35.45	2636	1.9	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.44	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:4	35.45	2641	1.9	13.4	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.44	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:4	35.45	2640	1.9	13.41	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.46	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:4	35.45	2640	1.9	13.42	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.46	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:4	35.45	2640	1.9	13.4	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.45	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:4	35.45	2638	1.9	13.41	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.47	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:4	35.45	2631	1.9	13.42	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.48	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:4	35.45	2629	1.9	13.42	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.51	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:5	35.45	2627	1.9	13.4	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.5	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:5	35.45	2624	1.9	13.41	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.5	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:5	35.45	2624	1.9	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.54	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:14:8	35.45	2624	1.9	13.41	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.54	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:8	35.45	2624	1.9	13.4	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.52	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:8	35.45	2625	1.89	13.41	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.53	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:6	35.45	2627	1.89	13.41	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.54	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:6	35.45	2630	1.89	13.42	106	197	Off Idle	58.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.57	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:6	35.45	2627	1.89	13.41	106	197	Off Idle	58.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.58	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:6	35.45	2624	1.89	13.43	106	197	Off Idle	58.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.59	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:6	35.45	2626	1.88	13.43	106	197	Off Idle	58.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.61	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:6	35.45	2626	1.88	13.42	106	197	Off Idle	59	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.62	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:6	35.45	2627	1.88	13.42	106	197	Off Idle	59	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.6	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:7	35.45	2626	1.88	13.44	106	198	Off Idle	59	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.63	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:7	35.45	2626	1.87	13.44	106	198	Off Idle	59	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.62	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:7	35.45	2626	1.87	13.43	106	198	Off Idle	59	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.65	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:7	35.45	2629	1.87	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.64	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:7	35.45	2628	1.87	13.43	106	198	Off Idle	59	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.64	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:7	35.45	2628	1.87	13.43	106	198	Off Idle	59	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.65	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:8	35.45	2623	1.86	13.41	106	198	Off Idle	59	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.65	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:8	35.45	2617	1.86	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.66	15.14	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:8	35.45	2617	1.86	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.66	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:14:8	35.45	2620	1.86	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.69	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:8	35.45	2619	1.86	13.41	106	198	Off Idle	59	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.69	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:8	35.45	2619	1.86	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.68	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:9	35.45	2622	1.86	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.74	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:9	35.45	2621	1.85	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.75	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:9	35.45	2623	1.85	13.41	106	198	Off Idle	59	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.73	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:9	35.45	2624	1.85	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.76	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:9	35.45	2623	1.85	13.41	106	198	Off Idle	59	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.73	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:9	35.45	2623	1.85	13.4	106	198	Off Idle	59	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.72	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:14:9	35.45	2623	1.85	13.41	106	198	Off Idle	59	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.75	14.74	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:0	35.45	2618	1.85	13.43	106	198	Off Idle	59	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.76	14.73	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:0	35.45	2613	1.85	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.74	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:0	35.45	2613	1.85	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.74	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:0	35.45	2614	1.85	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.74	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:0	35.45	2618	1.85	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.72	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:0	35.45	2620	1.85	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.7	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:1	35.45	2621	1.85	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.73	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:1	35.45	2621	1.85	13.41	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.71	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:1	35.45	2617	1.85	13.41	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.72	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:1	35.45	2619	1.85	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.74	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:1	35.45	2619	1.85	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.69	Lean	1	14.6	-8.73	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:1	35.45	2614	1.85	13.42	106	198	Off Idle	59.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.75	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:1	35.45	2608	1.85	13.41	106	198	Off Idle	59.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.76	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:2	35.45	2608	1.85	13.42	106	198	Off Idle	59.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.73	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:2	35.45	2605	1.85	13.43	106	198	Off Idle	59.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.73	15.13	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:2	35.45	2601	1.85	13.43	106	198	Off Idle	59.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.76	15.13	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:2	35.45	2613	1.85	13.43	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.73	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:2	35.45	2613	1.85	13.42	106	198	Off Idle	60	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.72	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:2	35.45	2616	1.85	13.42	106	198	Off Idle	60	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.72	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:3	35.45	2614	1.85	13.42	106	198	Off Idle	60	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.73	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:3	35.45	2614	1.85	13.42	106	198	Off Idle	60	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.73	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:3	35.45	2615	1.85	13.41	106	198	Off Idle	60.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.75	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:3	35.45	2609	1.85	13.42	106	198	Off Idle	60.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.73	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:3	35.45	2609	1.85	13.42	106	198	Off Idle	60.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.76	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:3	35.45	2608	1.85	13.43	106	197	Off Idle	60.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.77	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:4	35.45	2607	1.85	13.42	106	197	Off Idle	60.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.76	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:4	35.45	2607	1.85	13.42	106	198	Off Idle	60.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.78	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:4	35.45	2606	1.84	13.42	106	198	Off Idle	60.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.79	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:4	35.45	2608	1.84	13.42	106	198	Off Idle	60.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.79	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:15:4	35.45	2611	1.84	13.42	106	198	Off Idle	60.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.75	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:4	35.45	2612	1.84	13.41	106	198	Off Idle	60.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.77	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:4	35.45	2612	1.84	13.41	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.8	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:5	35.45	2614	1.84	13.41	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.77	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:5	35.45	2614	1.84	13.4	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.75	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:5	35.45	2612	1.84	13.4	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.72	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:5	35.45	2608	1.84	13.42	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.72	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:5	35.45	2604	1.84	13.41	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.73	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:5	35.45	2601	1.84	13.41	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.73	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:6	35.45	2594	1.84	13.42	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.73	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:6	35.45	2594	1.84	13.42	106	198	Off Idle	59.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.75	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:6	35.45	2594	1.84	13.42	106	198	Off Idle	59.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.75	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:6	35.45	2594	1.85	13.41	106	198	Off Idle	59.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.73	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:6	35.45	2599	1.85	13.43	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.73	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:6	35.45	2600	1.85	13.43	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.78	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:6	35.45	2604	1.85	13.41	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.76	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:7	35.45	2606	1.85	13.43	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.73	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:7	35.45	2610	1.85	13.43	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.77	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:7	35.45	2610	1.85	13.42	106	198	Off Idle	60.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.76	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:7	35.45	2605	1.85	13.43	106	198	Off Idle	60.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.72	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:7	35.45	2599	1.85	13.43	106	198	Off Idle	60.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.74	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:7	35.45	2599	1.85	13.43	106	198	Off Idle	60.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.76	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:8	35.45	2596	1.85	13.42	106	198	Off Idle	60.7	0	2	132	944 Turbo	0.2	Rich	1	14.6	-8.78	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:15:8	35.45	2593	1.84	13.42	106	198	Off Idle	60.9	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.75	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:8	35.45	2592	1.84	13.42	106	198	Off Idle	61	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.76	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:8	35.45	2592	1.84	13.44	106	198	Off Idle	61	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.8	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:8	35.45	2592	1.84	13.43	106	198	Off Idle	61	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.75	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:8	35.45	2593	1.84	13.43	106	198	Off Idle	61	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.73	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:9	35.45	2594	1.84	13.43	106	198	Off Idle	61	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.78	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:9	35.45	2596	1.84	13.43	106	198	Off Idle	61	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.8	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:9	35.45	2595	1.84	13.42	106	198	Off Idle	61.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.76	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:9	35.45	2590	1.84	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.81	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:9	35.45	2590	1.84	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.81	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:9	35.45	2589	1.84	13.44	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.83	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:15:9	35.45	2589	1.83	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.82	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:0	35.45	2591	1.83	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.82	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:0	35.45	2593	1.83	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.83	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:0	35.45	2594	1.83	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.84	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:0	35.45	2597	1.83	13.4	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.8	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:0	35.45	2596	1.83	13.4	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.83	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:0	35.45	2596	1.83	13.4	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.82	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:1	35.45	2588	1.83	13.42	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.82	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:1	35.45	2585	1.83	13.42	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.83	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:1	35.45	2583	1.83	13.43	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.79	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:1	35.45	2583	1.83	13.43	106	197	Off Idle	61.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.77	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:1	35.45	2585	1.83	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.75	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:1	35.45	2584	1.83	13.44	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.75	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:1	35.45	2588	1.83	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.76	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:2	35.45	2588	1.83	13.44	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.79	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:2	35.45	2590	1.83	13.44	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.79	14.75	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:2	35.45	2593	1.83	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.79	14.76	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:2	35.45	2592	1.83	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.77	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:2	35.45	2588	1.83	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.74	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:2	35.45	2578	1.83	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.74	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:3	35.45	2578	1.83	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.76	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:3	35.45	2572	1.83	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.78	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:3	35.45	2577	1.83	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.77	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:3	35.45	2584	1.83	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.79	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:16:3	35.45	2584	1.83	13.43	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.8	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:3	35.45	2590	1.83	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.77	15.13	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:4	35.45	2585	1.83	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.73	15.15	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:4	35.45	2585	1.83	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.76	15.16	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:4	35.45	2585	1.83	13.43	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.76	15.17	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:4	35.45	2587	1.83	13.42	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.76	15.17	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:4	35.45	2586	1.83	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.73	15.16	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:4	35.45	2584	1.84	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.72	15.16	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:4	35.45	2582	1.84	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.72	15.17	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:5	35.45	2582	1.84	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.67	15.16	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:5	35.45	2582	1.84	13.43	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.66	15.13	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:5	35.45	2582	1.84	13.43	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.66	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:5	35.45	2581	1.84	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.63	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:5	35.45	2582	1.84	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.62	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:16:5	35.45	2582	1.85	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.6	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:6	35.45	2583	1.85	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.58	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:6	35.45	2583	1.85	13.4	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.56	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:6	35.45	2583	1.86	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.56	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:6	35.45	2583	1.86	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.54	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:6	35.45	2587	1.86	13.39	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.52	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:6	35.45	2585	1.87	13.4	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.49	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:6	35.45	2586	1.87	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.46	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:7	35.45	2586	1.87	13.4	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.44	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:7	35.45	2584	1.87	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.39	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:7	35.45	2581	1.88	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.34	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:7	35.45	2580	1.88	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.33	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:7	35.45	2578	1.88	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.32	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:7	35.45	2576	1.89	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.31	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:8	35.45	2576	1.89	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.31	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:8	35.45	2570	1.9	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.24	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:8	35.45	2570	1.9	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.21	15.05	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:8	35.45	2576	1.9	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.22	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:16:8	35.45	2582	1.91	13.43	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.23	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:16:8	35.45	2582	1.91	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.19	15.05	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:16:9	35.45	2587	1.92	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.17	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:16:9	35.45	2592	1.92	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.14	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:16:9	35.45	2591	1.93	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.11	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:16:9	35.45	2591	1.93	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.04	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:16:9	35.45	2584	1.94	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.03	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:16:9	35.45	2584	1.94	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.01	14.93	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:16:9	35.45	2582	1.95	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.97	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:0	35.45	2578	1.95	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.95	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:0	35.45	2576	1.95	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.92	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:0	35.45	2576	1.96	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.89	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:0	34.08	2554	1.97	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.84	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:0	34.08	2576	1.97	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.82	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:0	34.08	2580	1.97	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.79	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:1	34.08	2580	1.98	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.8	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:1	34.08	2584	1.98	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.82	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:17:1	34.08	2591	1.98	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.81	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:17:1	35.45	2579	1.99	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.78	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:17:1	35.45	2578	1.99	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.75	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:17:1	35.45	2573	1.99	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.75	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:17:1	35.45	2573	2	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:17:2	35.45	2571	2	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:17:2	35.45	2572	2	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:2	35.45	2572	2	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:2	35.45	2578	2	13.43	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:17:2	35.45	2582	2	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.7	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:2	35.45	2582	2	13.43	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.68	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:3	35.45	2564	2	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.69	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:3	35.45	2585	2	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.69	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:3	35.45	2588	2	13.42	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.69	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:3	35.45	2587	2	13.42	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.71	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:3	35.45	2592	2.01	13.42	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.72	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:3	35.45	2580	2.01	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:4	35.45	2579	2.01	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:4	35.45	2576	2.01	13.4	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:4	35.45	2574	2.01	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.68	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:4	35.45	2579	2.01	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.66	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:4	35.45	2579	2.01	13.4	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.67	14.94	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:4	35.45	2584	2.01	13.41	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.68	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:4	35.45	2586	2.01	13.41	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.69	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:5	35.45	2586	2.01	13.43	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.69	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:5	35.45	2587	2.01	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.68	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:5	35.45	2581	2.01	13.44	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.62	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:5	35.45	2580	2.01	13.45	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	15.16	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:5	35.45	2567	2.01	13.44	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.21	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:5	35.45	2574	2.01	13.44	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	15.22	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:6	35.45	2572	2.01	13.43	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15.2	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:6	35.45	2572	2.01	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	15.17	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:6	35.45	2572	2.01	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:6	35.45	2572	2.01	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.67	Lean	1	14.6	-7.66	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:6	35.45	2574	2.01	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.68	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:6	35.45	2572	2.01	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.69	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:6	34.08	2604	2.01	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.66	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:7	34.08	2595	2.01	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.68	14.9	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:7	34.08	2590	2.01	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.67	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:7	34.08	2590	2.01	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:7	34.08	2590	2.01	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:7	34.08	2592	2.01	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.7	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:7	35.45	2587	2.01	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:8	35.45	2583	2.01	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.65	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:17:8	35.45	2576	2.01	13.4	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.62	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:8	35.45	2576	2.01	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.62	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:8	35.45	2575	2.01	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.63	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:8	35.45	2577	2.01	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.64	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:8	34.08	2579	2.01	13.42	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.65	14.9	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:9	34.08	2585	2.01	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.66	14.9	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:9	34.08	2585	2.01	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	14.93	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:9	34.08	2584	2.01	13.4	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.62	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:9	34.08	2582	2.01	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:9	35.45	2582	2.01	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:9	35.45	2579	2.01	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:17:9	35.45	2581	2.01	13.4	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:0	35.45	2581	2.01	13.4	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.62	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:0	35.45	2582	2.01	13.42	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:0	35.45	2584	2.01	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:0	35.45	2583	2.01	13.43	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:0	35.45	2581	2.01	13.42	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.67	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:0	35.45	2580	2.01	13.42	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.65	14.81	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:1	35.45	2576	2.01	13.42	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.66	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:1	35.45	2574	2.01	13.42	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.68	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:18:1	35.45	2572	2.01	13.42	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.68	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:18:1	34.08	2566	2.01	13.43	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.68	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:18:1	34.08	2579	2.01	13.43	106	198	Off Idle	62.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	14.75	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:18:1	34.08	2582	2.01	13.42	106	198	Off Idle	62.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.66	14.74	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:18:1	34.08	2589	2.01	13.42	106	198	Off Idle	62.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.65	14.73	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:18:2	34.08	2590	2.01	13.41	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.67	14.73	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:2	34.08	2590	2.01	13.4	106	198	Off Idle	62	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.67	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:2	35.45	2598	2.01	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.66	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:2	35.45	2588	2.01	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:2	35.45	2584	2	13.43	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.7	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:2	35.45	2581	2	13.43	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.73	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:3	35.45	2580	2	13.43	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.73	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:3	35.45	2580	2	13.43	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.73	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:3	35.45	2577	2	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.76	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:3	35.45	2577	2	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.74	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:3	35.45	2558	2	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	15.06	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:3	35.45	2581	2	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:4	35.45	2581	2	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.72	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:4	35.45	2580	2	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:4	34.08	2601	2	13.43	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.69	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:4	34.08	2581	2	13.41	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.7	14.94	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:4	34.08	2581	2	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.77	14.94	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:4	34.08	2578	2	13.41	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.75	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:18:4	34.08	2580	2	13.41	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.73	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:18:5	35.45	2580	2	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.77	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:5	35.45	2588	2	13.43	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:5	35.45	2581	1.99	13.43	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:5	35.45	2584	1.99	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.76	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:5	35.45	2584	1.99	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.78	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:5	35.45	2584	1.99	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.79	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:6	35.45	2582	1.99	13.43	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.78	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:6	35.45	2572	1.99	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.77	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:6	35.45	2578	1.99	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.77	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:6	35.45	2572	1.99	13.41	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.78	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:6	35.45	2574	1.99	13.4	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.76	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:6	35.45	2574	1.99	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.79	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:6	35.45	2582	1.99	13.41	106	198	Off Idle	62	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:7	35.45	2587	1.99	13.41	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:7	35.45	2587	1.99	13.42	106	198	Off Idle	62.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.12	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:7	35.45	2600	1.99	13.43	106	198	Off Idle	62.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:7	35.45	2588	1.99	13.43	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:7	35.45	2588	1.99	13.42	106	198	Off Idle	62	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:7	35.45	2586	1.99	13.41	106	198	Off Idle	62	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:8	35.45	2580	1.99	13.42	106	198	Off Idle	62	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.78	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:8	35.45	2578	1.99	13.42	106	198	Off Idle	62	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:8	35.45	2577	1.99	13.41	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.79	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:18:8	35.45	2578	1.99	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.79	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:8	35.45	2582	1.99	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.79	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:8	35.45	2580	1.99	13.45	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.79	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:9	35.45	2580	1.99	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.8	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:9	35.45	2584	1.99	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.81	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:9	35.45	2586	1.99	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.79	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:9	35.45	2592	1.99	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.79	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:9	35.45	2593	1.99	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.8	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:9	34.08	2582	1.99	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.77	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:18:9	34.08	2588	1.99	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:19:0	34.08	2582	1.99	13.43	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:19:0	34.08	2574	1.99	13.43	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.78	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:19:0	34.08	2574	1.99	13.44	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.77	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:0	34.08	2572	1.99	13.42	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.79	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:19:0	34.08	2572	1.99	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.81	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:19:0	34.08	2579	1.99	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.79	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:1	34.08	2579	1.99	13.44	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.82	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:1	34.08	2584	1.99	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.79	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:19:1	34.08	2590	1.99	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.77	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:19:1	34.08	2590	1.99	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.78	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:1	34.08	2592	1.99	13.4	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:1	34.08	2593	1.99	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15.14	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:1	34.08	2586	1.99	13.4	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	15.13	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:2	34.08	2585	1.99	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:2	34.08	2578	1.99	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:2	35.45	2593	1.99	13.41	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:2	35.45	2593	1.99	13.44	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:2	35.45	2576	2	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.72	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:2	35.45	2581	2	13.42	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:19:3	35.45	2583	2	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.66	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:19:3	35.45	2582	2	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.66	14.91	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:19:3	34.08	2574	2	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.65	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:19:3	34.08	2586	2.01	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.61	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:3	34.08	2590	2.01	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.6	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:3	34.08	2587	2.01	13.41	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.58	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:4	34.08	2584	2.02	13.41	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.53	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:4	34.08	2588	2.02	13.41	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.51	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:4	34.08	2590	2.02	13.44	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.48	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:4	34.08	2594	2.03	13.43	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.44	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:4	34.08	2596	2.03	13.44	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.37	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:4	34.08	2595	2.04	13.44	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.37	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:4	34.08	2595	2.04	13.42	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.36	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:5	34.08	2591	2.05	13.42	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.34	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:5	34.08	2588	2.05	13.42	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.31	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:5	34.08	2588	2.05	13.42	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.32	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:5	34.08	2587	2.06	13.43	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.29	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:5	34.08	2587	2.06	13.41	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.25	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:5	34.08	2587	2.07	13.41	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.15	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:6	34.08	2588	2.08	13.43	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.15	15.15	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:19:6	34.08	2589	2.08	13.42	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.1	15.18	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:6	34.08	2588	2.09	13.41	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.03	15.18	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:6	34.08	2586	2.09	13.43	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.99	15.19	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:6	34.08	2589	2.1	13.43	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.98	15.21	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:6	34.08	2590	2.1	13.41	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.91	15.22	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:6	34.08	2595	2.11	13.42	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.86	15.2	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:7	34.08	2598	2.11	13.43	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.85	15.16	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:19:7	34.08	2598	2.12	13.44	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.8	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:19:7	34.08	2600	2.13	13.43	106	197	Off Idle	61.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.77	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:7	34.08	2602	2.13	13.44	106	197	Off Idle	61.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.74	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:7	34.08	2602	2.14	13.43	106	197	Off Idle	61.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.75	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:7	34.08	2603	2.14	13.44	106	198	Off Idle	61.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.71	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:8	34.08	2602	2.15	13.42	106	198	Off Idle	61.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.66	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:8	34.08	2601	2.16	13.43	106	198	Off Idle	61.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.65	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:8	34.08	2599	2.16	13.41	106	198	Off Idle	61.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.65	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:8	34.08	2595	2.17	13.42	106	198	Off Idle	60.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.62	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:8	34.08	2594	2.17	13.41	106	198	Off Idle	60.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.6	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:8	34.08	2593	2.18	13.41	106	198	Off Idle	60.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.56	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:19:9	34.08	2595	2.18	13.43	106	198	Off Idle	60.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.54	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:19:9	34.08	2595	2.18	13.43	106	198	Off Idle	60.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.52	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:19:9	34.08	2597	2.18	13.44	106	198	Off Idle	60.9	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.54	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:9	34.08	2597	2.19	13.42	106	198	Off Idle	60.9	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.48	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:19:9	34.08	2602	2.19	13.41	106	198	Off Idle	60.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.47	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:19:9	34.08	2602	2.2	13.42	106	198	Off Idle	60.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.43	15.14	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:19:9	34.08	2602	2.2	13.4	106	198	Off Idle	60.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.39	15.14	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:20:0	34.08	2607	2.2	13.39	106	198	Off Idle	60.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.34	15.14	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:20:0	34.08	2605	2.21	13.4	106	198	Off Idle	60.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.35	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:20:0	34.08	2606	2.21	13.42	106	198	Off Idle	60.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.35	15.11	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:20:0	34.08	2607	2.22	13.43	106	198	Off Idle	60.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.28	15.05	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:0	34.08	2602	2.22	13.44	106	198	Off Idle	60.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.27	15.02	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:0	34.08	2601	2.22	13.43	106	198	Off Idle	60.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.21	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:1	34.08	2602	2.23	13.43	106	198	Off Idle	60	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.13	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:1	34.08	2604	2.23	13.42	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.09	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:1	34.08	2608	2.23	13.42	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.05	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:1	34.08	2608	2.24	13.43	106	198	Off Idle	59.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.04	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:1	34.08	2608	2.24	13.41	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.01	14.79	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:1	34.08	2608	2.25	13.41	106	198	Off Idle	59.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:1	34.08	2610	2.25	13.41	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.98	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:2	34.08	2613	2.25	13.41	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.91	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:2	34.08	2614	2.26	13.41	106	198	Off Idle	59.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.87	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:2	34.08	2618	2.26	13.41	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.91	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:2	34.08	2620	2.27	13.41	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.88	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:2	34.08	2620	2.27	13.41	106	198	Off Idle	60	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.91	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:2	34.08	2618	2.27	13.42	106	198	Off Idle	60.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.9	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:3	34.08	2614	2.27	13.42	106	198	Off Idle	60.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.9	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:3	34.08	2614	2.27	13.42	106	198	Off Idle	60.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.88	15.14	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:3	34.08	2611	2.28	13.42	106	198	Off Idle	60.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.84	15.14	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:3	34.08	2612	2.28	13.41	106	198	Off Idle	60	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.86	15.16	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:3	34.08	2612	2.28	13.4	106	198	Off Idle	60	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.85	15.16	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:3	34.08	2616	2.28	13.4	106	198	Off Idle	60	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.83	15.14	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:4	34.08	2616	2.28	13.4	106	198	Off Idle	60	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.84	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:4	34.08	2618	2.29	13.44	106	198	Off Idle	59.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.84	15.05	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:4	34.08	2621	2.29	13.44	106	198	Off Idle	59.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.82	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:4	34.08	2621	2.29	13.43	106	198	Off Idle	59.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.81	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:4	34.08	2624	2.29	13.42	106	198	Off Idle	59.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.81	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:4	34.08	2623	2.29	13.43	106	198	Off Idle	59.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.8	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:4	34.08	2626	2.29	13.42	106	198	Off Idle	59.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.81	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:5	34.08	2626	2.29	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.86	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:5	34.08	2629	2.29	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.86	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:5	34.08	2629	2.29	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.23	Rich	1	14.6	-5.83	14.75	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:5	34.08	2630	2.29	13.43	106	198	Off Idle	59	0	2	132	944 Turbo	0.18	Rich	1	14.6	-5.84	14.75	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:5	34.08	2630	2.29	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.87	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:5	34.08	2630	2.29	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.83	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:6	34.08	2628	2.29	13.41	106	198	Off Idle	59	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.83	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:6	34.08	2624	2.29	13.41	106	198	Off Idle	59	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.8	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:6	34.08	2624	2.29	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.79	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:6	34.08	2623	2.29	13.4	106	198	Off Idle	59	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.78	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:6	34.08	2623	2.29	13.39	106	198	Off Idle	59	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.74	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:6	34.08	2623	2.29	13.4	106	198	Off Idle	59	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.73	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:20:6	34.08	2625	2.29	13.4	106	198	Off Idle	59	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.74	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:7	34.08	2628	2.3	13.38	106	198	Off Idle	59.2	0	2	132	944 Turbo	0.69	Lean	1	14.6	-5.71	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:7	34.08	2630	2.3	13.38	106	198	Off Idle	59.4	0	2	132	944 Turbo	0.7	Lean	1	14.6	-5.67	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:7	34.08	2634	2.3	13.4	106	198	Off Idle	59.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.65	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:7	34.08	2634	2.3	13.39	106	198	Off Idle	59.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.61	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:7	34.08	2646	2.3	13.39	106	198	Off Idle	59.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.6	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:20:7	34.08	2635	2.31	13.41	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.55	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:20:8	34.08	2637	2.31	13.41	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.56	15.01	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:20:8	34.08	2637	2.31	13.4	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.53	14.97	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:20:8	34.08	2638	2.31	13.4	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.5	14.93	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:20:8	34.08	2644	2.32	13.41	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.49	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:20:8	34.08	2647	2.32	13.42	106	198	Off Idle	59.1	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.47	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:20:8	34.08	2647	2.33	13.42	106	198	Off Idle	58.9	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.5	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:20:9	34.08	2646	2.33	13.42	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.5	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:20:9	34.08	2642	2.33	13.43	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.47	14.89	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:20:9	34.08	2642	2.33	13.43	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.47	14.9	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:20:9	34.08	2640	2.34	13.42	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.48	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:20:9	34.08	2628	2.34	13.41	106	198	Off Idle	58.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.47	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:20:9	34.08	2628	2.34	13.41	106	198	Off Idle	58	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.42	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:20:9	34.08	2634	2.35	13.43	106	198	Off Idle	57.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.41	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:0	34.08	2635	2.35	13.41	106	198	Off Idle	58.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.4	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:0	34.08	2638	2.35	13.42	106	198	Off Idle	58.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.35	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:0	34.08	2638	2.35	13.42	106	198	Off Idle	58.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.33	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:0	34.08	2644	2.35	13.41	106	198	Off Idle	58	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.37	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:0	34.08	2644	2.35	13.41	106	198	Off Idle	58	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.38	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:0	34.08	2655	2.35	13.42	106	198	Off Idle	58	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.43	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:1	34.08	2654	2.35	13.41	106	198	Off Idle	58	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.41	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:1	34.08	2666	2.35	13.42	106	198	Off Idle	58.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.43	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:1	34.08	2656	2.35	13.41	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.47	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:1	34.08	2654	2.35	13.41	106	198	Off Idle	58.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.43	14.74	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:1	34.08	2650	2.35	13.41	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.42	14.7	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:1	34.08	2636	2.35	13.42	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.44	14.69	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:1	34.08	2644	2.35	13.42	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.46	14.69	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:2	34.08	2644	2.35	13.42	106	198	Off Idle	58.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.43	14.71	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:2	34.08	2644	2.35	13.43	106	198	Off Idle	59	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.44	14.75	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:2	34.08	2651	2.35	13.43	106	198	Off Idle	59	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.47	14.77	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:2	34.08	2654	2.35	13.42	106	198	Off Idle	59	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.47	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:2	34.08	2661	2.35	13.42	106	198	Off Idle	58.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.47	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:2	34.08	2661	2.35	13.41	106	198	Off Idle	58.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.41	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:3	34.08	2687	2.35	13.41	106	198	Off Idle	58.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.43	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:3	34.08	2687	2.35	13.4	106	198	Off Idle	58.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.44	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:3	34.08	2664	2.35	13.39	106	198	Off Idle	58.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.39	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:3	34.08	2666	2.35	13.39	106	198	Off Idle	58	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.39	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:3	34.08	2666	2.35	13.4	106	198	Off Idle	57.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.39	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:3	34.08	2665	2.35	13.42	106	198	Off Idle	57.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.37	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:4	34.08	2662	2.35	13.41	106	198	Off Idle	57.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.39	14.9	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:4	34.08	2662	2.35	13.41	106	198	Off Idle	57.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.37	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:4	34.08	2660	2.35	13.42	106	198	Off Idle	57.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.37	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:4	34.08	2658	2.35	13.43	106	198	Off Idle	57	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.39	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:4	34.08	2657	2.35	13.42	106	198	Off Idle	57	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.39	14.97	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:4	34.08	2658	2.36	13.43	106	198	Off Idle	57	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.36	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:4	34.08	2656	2.36	13.42	106	198	Off Idle	57	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.31	15.08	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:5	34.08	2664	2.36	13.43	106	198	Off Idle	57	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.35	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:5	34.08	2668	2.36	13.41	106	198	Off Idle	57	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.33	15.08	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:5	34.08	2669	2.36	13.42	106	198	Off Idle	57.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.34	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:5	34.08	2668	2.36	13.42	106	198	Off Idle	57.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.36	15.04	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:5	34.08	2672	2.36	13.41	106	198	Off Idle	57.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.37	15.03	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:5	34.08	2672	2.36	13.41	106	198	Off Idle	57.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.35	15.02	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:6	34.08	2672	2.37	13.42	106	198	Off Idle	57.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.36	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:6	34.08	2672	2.37	13.42	106	198	Off Idle	57.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.31	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:6	34.08	2682	2.37	13.41	106	198	Off Idle	57.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.29	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:6	34.08	2680	2.37	13.43	106	198	Off Idle	57.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.29	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:6	34.08	2682	2.37	13.43	106	198	Off Idle	57.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.29	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:6	34.08	2680	2.37	13.41	106	198	Off Idle	57.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.27	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:6	34.08	2679	2.38	13.42	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.24	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:7	34.08	2677	2.38	13.43	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.19	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:7	34.08	2674	2.38	13.43	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.2	14.89	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:21:7	34.08	2672	2.38	13.41	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.18	14.9	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:7	34.08	2674	2.38	13.43	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.18	14.92	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:7	34.08	2674	2.39	13.43	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.16	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:7	34.08	2680	2.39	13.42	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.15	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:21:8	34.08	2683	2.39	13.42	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.1	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:8	34.08	2688	2.39	13.42	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.11	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:8	34.08	2688	2.39	13.43	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.13	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:8	34.08	2691	2.4	13.42	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.13	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:21:8	34.08	2688	2.4	13.41	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.08	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:8	34.08	2687	2.4	13.41	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.09	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:9	34.08	2686	2.4	13.41	106	198	Off Idle	56.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.09	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:9	34.08	2687	2.4	13.42	106	198	Off Idle	57	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.06	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:9	34.08	2685	2.4	13.41	106	198	Off Idle	57	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.08	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:9	34.08	2683	2.41	13.43	106	198	Off Idle	56.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.1	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:9	34.08	2677	2.41	13.43	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.08	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:9	34.08	2681	2.41	13.41	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.09	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:21:9	34.08	2681	2.41	13.41	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.05	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:0	34.08	2692	2.41	13.4	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.07	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:0	34.08	2700	2.41	13.4	106	198	Off Idle	56.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.07	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:0	34.08	2704	2.41	13.4	106	198	Off Idle	56.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.1	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:0	34.08	2704	2.41	13.41	106	198	Off Idle	56.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.09	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:0	34.08	2707	2.41	13.42	106	198	Off Idle	56.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.11	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:0	34.08	2702	2.41	13.42	106	198	Off Idle	56.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.1	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:1	34.08	2697	2.41	13.43	106	198	Off Idle	56.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.08	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:1	34.08	2697	2.41	13.41	106	198	Off Idle	56.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.06	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:1	34.08	2698	2.41	13.43	106	198	Off Idle	55.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.02	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:1	34.08	2699	2.41	13.43	106	198	Off Idle	55.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.08	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:1	34.08	2699	2.41	13.43	106	198	Off Idle	55.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.05	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:1	34.08	2700	2.41	13.42	106	198	Off Idle	55.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.04	14.9	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:1	34.08	2702	2.41	13.43	106	198	Off Idle	55.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.08	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:2	34.08	2703	2.41	13.43	106	198	Off Idle	55.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.05	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:2	34.08	2702	2.41	13.42	106	198	Off Idle	55.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.05	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:2	34.08	2707	2.41	13.42	106	198	Off Idle	55.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.04	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:2	34.08	2706	2.41	13.41	106	198	Off Idle	55	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.03	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:2	34.08	2705	2.42	13.41	106	198	Off Idle	54.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.04	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:2	34.08	2704	2.42	13.41	106	198	Off Idle	54.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.1	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:3	34.08	2706	2.42	13.43	106	198	Off Idle	54.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.08	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:3	34.08	2705	2.42	13.42	106	198	Off Idle	54.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.04	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:3	34.08	2700	2.42	13.42	106	198	Off Idle	54.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.06	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:3	34.08	2700	2.42	13.42	106	198	Off Idle	54.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.07	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:3	34.08	2709	2.42	13.41	106	198	Off Idle	54.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.06	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:3	34.08	2709	2.42	13.41	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.04	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:4	34.08	2711	2.42	13.41	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.04	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:4	34.08	2715	2.42	13.4	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.08	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:4	34.08	2716	2.42	13.4	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.03	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:4	34.08	2716	2.42	13.4	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.08	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:4	34.08	2714	2.42	13.4	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.09	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:4	34.08	2714	2.42	13.4	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.09	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:4	34.08	2712	2.42	13.41	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.1	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:5	34.08	2712	2.42	13.41	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.1	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:5	34.08	2712	2.42	13.41	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.08	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:5	34.08	2713	2.42	13.41	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.1	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:5	34.08	2719	2.41	13.42	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.12	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:5	34.08	2722	2.41	13.42	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.16	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:5	34.08	2726	2.41	13.42	106	198	Off Idle	54.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.17	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:6	34.08	2724	2.41	13.42	106	198	Off Idle	54.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.16	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:6	34.08	2718	2.41	13.42	106	198	Off Idle	54.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.16	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:6	34.08	2719	2.41	13.41	106	198	Off Idle	54.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.18	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:6	34.08	2720	2.41	13.41	106	198	Off Idle	54.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.19	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:6	34.08	2726	2.41	13.41	106	198	Off Idle	54.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.2	15.12	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:6	34.08	2749	2.41	13.41	106	198	Off Idle	54.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.22	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:6	34.08	2749	2.4	13.42	106	198	Off Idle	54.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.26	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:22:7	34.08	2723	2.4	13.42	106	198	Off Idle	54.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.25	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:7	34.08	2719	2.4	13.42	106	198	Off Idle	54.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.25	14.96	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:7	34.08	2719	2.4	13.41	106	198	Off Idle	54.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.26	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:7	34.08	2712	2.4	13.4	106	198	Off Idle	54.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.27	14.9	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:7	34.08	2725	2.4	13.4	106	198	Off Idle	54.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.27	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:7	34.08	2726	2.4	13.4	106	198	Off Idle	54.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.29	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:8	34.08	2730	2.4	13.42	106	198	Off Idle	54.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.34	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:8	34.08	2732	2.39	13.42	106	198	Off Idle	54.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.32	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:8	34.08	2728	2.39	13.42	106	198	Off Idle	54.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.37	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:8	34.08	2720	2.39	13.43	106	198	Off Idle	54.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.4	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:8	34.08	2720	2.39	13.42	106	198	Off Idle	54.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.4	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:22:8	34.08	2717	2.39	13.43	106	198	Off Idle	54.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.37	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:9	34.08	2720	2.39	13.42	106	198	Off Idle	54.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.37	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:9	34.08	2719	2.39	13.42	106	198	Off Idle	54.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.37	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:9	34.08	2724	2.39	13.43	106	198	Off Idle	54.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.33	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:9	34.08	2732	2.39	13.42	106	198	Off Idle	54.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.3	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:22:9	34.08	2737	2.39	13.43	106	198	Off Idle	54.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.33	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:9	34.08	2737	2.39	13.44	106	198	Off Idle	54.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.36	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:22:9	34.08	2742	2.39	13.45	106	198	Off Idle	54	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.34	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:0	34.08	2738	2.39	13.44	106	198	Off Idle	53.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.3	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:0	34.08	2738	2.39	13.42	106	198	Off Idle	53.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.31	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:0	34.08	2735	2.39	13.42	106	198	Off Idle	53.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.32	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:0	34.08	2730	2.39	13.42	106	198	Off Idle	53.9	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.34	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:0	34.08	2730	2.39	13.43	106	198	Off Idle	54	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.31	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:0	34.08	2732	2.39	13.43	106	198	Off Idle	54	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.32	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:1	34.08	2733	2.39	13.43	106	198	Off Idle	54	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.31	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:23:1	34.08	2736	2.39	13.43	106	198	Off Idle	54	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.28	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:23:1	34.08	2737	2.39	13.42	106	198	Off Idle	54	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.29	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:23:1	34.08	2748	2.39	13.42	106	198	Off Idle	54	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.32	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:23:1	34.08	2770	2.39	13.42	106	198	Off Idle	53.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.31	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:23:1	34.08	2770	2.39	13.42	106	198	Off Idle	53.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.33	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:23:1	34.08	2746	2.39	13.42	106	198	Off Idle	53.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.37	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:2	34.08	2743	2.39	13.41	106	198	Off Idle	53.5	0	2	132	944 Turbo	0.15	Rich	1	14.6	-5.35	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:2	34.08	2743	2.39	13.41	106	198	Off Idle	53.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.34	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:23:2	34.08	2740	2.39	13.42	106	198	Off Idle	53.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.35	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:2	34.08	2738	2.39	13.42	106	198	Off Idle	53.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.33	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:2	34.08	2742	2.39	13.43	106	198	Off Idle	53.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.33	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:2	34.08	2742	2.4	13.44	106	198	Off Idle	53.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.33	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:3	34.08	2742	2.4	13.44	106	198	Off Idle	53.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.32	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:3	34.08	2744	2.4	13.42	106	198	Off Idle	53.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.34	15.2	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:3	34.08	2746	2.4	13.41	106	198	Off Idle	52.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.35	15.2	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:3	34.08	2757	2.4	13.41	106	198	Off Idle	52.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.37	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:3	34.08	2758	2.4	13.42	106	198	Off Idle	52.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.4	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:3	34.08	2760	2.39	13.4	106	198	Off Idle	52.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.41	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:4	34.08	2756	2.39	13.43	106	198	Off Idle	52.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.4	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:4	34.08	2752	2.39	13.43	106	198	Off Idle	52.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.39	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:4	34.08	2750	2.39	13.41	106	198	Off Idle	52.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.37	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:4	34.08	2761	2.39	13.42	106	198	Off Idle	52.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.35	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:4	34.08	2746	2.39	13.42	106	198	Off Idle	52.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.36	14.89	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:4	34.08	2748	2.39	13.4	106	198	Off Idle	52.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.33	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:4	34.08	2753	2.39	13.41	106	198	Off Idle	52.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.34	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:5	34.08	2735	2.39	13.43	106	198	Off Idle	52.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.38	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:5	34.08	2746	2.39	13.43	106	198	Off Idle	52.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.39	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:5	34.08	2762	2.39	13.41	106	198	Off Idle	52.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.39	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:5	34.08	2766	2.39	13.44	106	198	Off Idle	52.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.44	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:5	34.08	2779	2.39	13.42	106	198	Off Idle	52.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.44	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:5	34.08	2768	2.39	13.42	106	198	Off Idle	52	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.44	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:6	34.08	2766	2.39	13.42	106	198	Off Idle	52	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.47	14.9	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:23:6	34.08	2765	2.39	13.42	106	198	Off Idle	52	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.48	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:6	34.08	2763	2.38	13.42	106	198	Off Idle	52	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.5	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:6	34.08	2738	2.38	13.41	106	198	Off Idle	52.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.51	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:6	34.08	2749	2.38	13.41	106	198	Off Idle	52.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.55	15.04	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:6	34.08	2757	2.38	13.41	106	198	Off Idle	52.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.6	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:6	34.08	2762	2.37	13.41	106	198	Off Idle	52.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.6	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:23:7	34.08	2761	2.37	13.41	106	198	Off Idle	52.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.65	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:23:7	34.08	2761	2.37	13.42	106	198	Off Idle	52.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.68	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:23:7	34.08	2766	2.37	13.43	106	198	Off Idle	52.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.68	15.09	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:23:7	34.08	2769	2.37	13.42	106	198	Off Idle	52.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.7	15.08	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:23:7	34.08	2770	2.36	13.42	106	198	Off Idle	52	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.69	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:7	34.08	2781	2.36	13.41	106	198	Off Idle	51.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.71	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:8	34.08	2781	2.36	13.41	106	198	Off Idle	51.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.67	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:8	34.08	2765	2.36	13.41	106	198	Off Idle	51.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.67	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:8	34.08	2770	2.35	13.4	106	198	Off Idle	51.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.67	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:8	34.08	2770	2.35	13.42	106	198	Off Idle	51.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.69	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:8	34.08	2771	2.35	13.42	106	198	Off Idle	51.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.7	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:8	34.08	2776	2.35	13.42	106	198	Off Idle	51.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.71	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:9	34.08	2775	2.35	13.42	106	198	Off Idle	51.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.73	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:9	34.08	2776	2.35	13.42	106	198	Off Idle	51.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.76	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:9	35.45	2788	2.35	13.41	106	198	Off Idle	51.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.75	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:9	35.45	2783	2.35	13.41	106	198	Off Idle	50.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.71	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:9	35.45	2782	2.35	13.42	106	198	Off Idle	50.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.74	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:23:9	35.45	2780	2.35	13.42	106	198	Off Idle	50.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.71	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:23:9	35.45	2759	2.35	13.43	106	198	Off Idle	50.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.7	15.05	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:0	35.45	2759	2.35	13.42	106	198	Off Idle	50.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.7	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:0	34.08	2761	2.35	13.43	106	198	Off Idle	50.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.71	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:0	34.08	2772	2.35	13.43	106	198	Off Idle	50.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.69	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:0	34.08	2772	2.35	13.43	106	198	Off Idle	50.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.69	15.16	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:0	34.08	2794	2.35	13.42	106	198	Off Idle	51	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.68	15.16	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:0	34.08	2775	2.35	13.43	106	198	Off Idle	51.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.68	15.14	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:1	34.08	2775	2.36	13.42	106	198	Off Idle	51.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.65	15.13	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:1	34.08	2779	2.36	13.42	106	198	Off Idle	51.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.65	15.1	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:1	34.08	2785	2.36	13.43	106	198	Off Idle	51.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.65	15.07	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:1	34.08	2786	2.36	13.43	106	198	Off Idle	51.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.63	15.04	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:1	34.08	2786	2.36	13.43	106	198	Off Idle	51.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.6	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:1	34.08	2801	2.36	13.43	106	198	Off Idle	51.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.63	14.97	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:1	34.08	2793	2.36	13.43	106	198	Off Idle	51.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.61	14.92	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:2	34.08	2792	2.36	13.43	106	198	Off Idle	51.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.6	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:2	34.08	2788	2.36	13.43	106	198	Off Idle	51.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.6	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:2	34.08	2786	2.36	13.41	106	198	Off Idle	50.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.59	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:2	34.08	2786	2.37	13.43	106	198	Off Idle	50.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.57	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:2	34.08	2786	2.37	13.43	106	198	Off Idle	50.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.5	14.92	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:2	34.08	2786	2.37	13.42	106	198	Off Idle	50.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.48	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:3	34.08	2780	2.37	13.41	106	198	Off Idle	50.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.47	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:3	34.08	2780	2.37	13.42	106	198	Off Idle	50.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.5	14.98	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:3	34.08	2784	2.37	13.43	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.47	15	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:3	34.08	2790	2.38	13.43	106	198	Off Idle	50	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.57	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:3	34.08	2790	2.38	13.44	106	198	Off Idle	50	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.54	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:3	34.08	2793	2.38	13.42	106	198	Off Idle	50	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.54	15.1	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:4	34.08	2795	2.38	13.42	106	198	Off Idle	50	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.54	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:4	34.08	2802	2.38	13.42	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.55	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:4	34.08	2802	2.38	13.42	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.51	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:4	34.08	2807	2.39	13.44	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.51	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:4	34.08	2807	2.39	13.44	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.52	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:4	34.08	2807	2.39	13.44	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.5	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:4	34.08	2802	2.39	13.44	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.51	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:5	34.08	2799	2.39	13.43	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.5	14.75	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:24:5	34.08	2799	2.39	13.42	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.47	14.74	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:24:5	34.08	2798	2.39	13.42	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.5	14.78	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:24:5	34.08	2801	2.39	13.42	106	198	Off Idle	50	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.49	14.81	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:24:5	34.08	2802	2.39	13.41	106	198	Off Idle	49.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.46	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:5	34.08	2806	2.39	13.42	106	198	Off Idle	49.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.48	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:6	34.08	2809	2.39	13.41	106	198	Off Idle	49.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.5	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:6	34.08	2809	2.39	13.41	106	198	Off Idle	49.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.46	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:6	34.08	2808	2.39	13.41	106	198	Off Idle	49.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.47	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:6	34.08	2808	2.39	13.41	106	198	Off Idle	49	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.44	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:6	34.08	2802	2.4	13.41	106	198	Off Idle	48.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.44	15.1	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:6	34.08	2802	2.4	13.42	106	198	Off Idle	48.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.42	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:6	34.08	2804	2.4	13.42	106	198	Off Idle	48.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.43	15.04	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:7	34.08	2806	2.4	13.42	106	198	Off Idle	48.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.44	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:7	34.08	2806	2.4	13.42	106	198	Off Idle	48.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.44	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:7	34.08	2808	2.4	13.42	106	198	Off Idle	48.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.43	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:7	34.08	2809	2.4	13.42	106	198	Off Idle	48.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.42	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:7	34.08	2810	2.4	13.42	106	198	Off Idle	48.4	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.44	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:7	34.08	2810	2.4	13.42	106	198	Off Idle	48.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.43	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:8	34.08	2808	2.4	13.42	106	198	Off Idle	48.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.45	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:8	34.08	2810	2.4	13.42	106	198	Off Idle	48.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.45	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:8	34.08	2817	2.4	13.41	106	198	Off Idle	49	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.46	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:24:8	34.08	2821	2.4	13.41	106	198	Off Idle	49	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.47	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:8	34.08	2822	2.4	13.41	106	198	Off Idle	49	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.49	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:8	34.08	2822	2.4	13.43	106	198	Off Idle	49	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.5	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:24:9	34.08	2825	2.4	13.41	106	198	Off Idle	49	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.49	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:24:9	34.08	2817	2.4	13.4	106	198	Off Idle	49	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.48	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:9	34.08	2818	2.4	13.39	106	198	Off Idle	49	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.5	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:9	34.08	2818	2.4	13.41	106	198	Off Idle	49.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.5	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:9	34.08	2814	2.4	13.39	106	198	Off Idle	49.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.44	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:9	34.08	2819	2.4	13.4	106	198	Off Idle	49.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.42	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:24:9	34.08	2820	2.4	13.41	106	198	Off Idle	49.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.47	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:0	34.08	2820	2.4	13.42	106	198	Off Idle	48.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.41	14.9	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:0	34.08	2821	2.4	13.41	106	198	Off Idle	48.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.45	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:0	34.08	2825	2.4	13.42	106	198	Off Idle	48.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.44	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:0	34.08	2826	2.41	13.42	106	198	Off Idle	48.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.47	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:0	34.08	2834	2.41	13.42	106	198	Off Idle	48.8	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.42	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:0	34.08	2836	2.41	13.42	106	198	Off Idle	48.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.47	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:1	34.08	2836	2.41	13.43	106	198	Off Idle	48.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.49	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:1	34.08	2835	2.41	13.42	106	198	Off Idle	48.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.48	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:1	34.08	2835	2.41	13.43	106	198	Off Idle	48.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.45	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:1	34.08	2842	2.41	13.43	106	198	Off Idle	48.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.46	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:1	34.08	2840	2.41	13.42	106	198	Off Idle	48.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.44	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:1	34.08	2838	2.41	13.43	106	198	Off Idle	48.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.43	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:1	34.08	2835	2.41	13.42	106	198	Off Idle	48.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.42	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:2	34.08	2834	2.41	13.42	106	198	Off Idle	47.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.42	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:2	34.08	2833	2.41	13.42	106	198	Off Idle	47.9	0	2	132	944 Turbo	0.18	Rich	1	14.6	-5.4	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:2	34.08	2839	2.41	13.42	106	198	Off Idle	47.9	0	2	132	944 Turbo	0.23	Rich	1	14.6	-5.4	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:2	34.08	2841	2.42	13.41	106	198	Off Idle	47.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.36	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:2	34.08	2842	2.42	13.42	106	198	Off Idle	47.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.41	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:2	34.08	2842	2.42	13.42	106	198	Off Idle	47.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.39	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:3	34.08	2838	2.42	13.41	106	198	Off Idle	47.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.39	15.05	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:3	34.08	2838	2.42	13.41	106	198	Off Idle	47.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.4	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:3	34.08	2838	2.42	13.41	106	198	Off Idle	48	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.43	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:3	34.08	2839	2.42	13.39	106	198	Off Idle	48	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.45	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:3	34.08	2841	2.42	13.41	106	198	Off Idle	48	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.42	15.12	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:3	34.08	2841	2.42	13.4	106	198	Off Idle	47.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.4	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:4	34.08	2848	2.42	13.42	106	198	Off Idle	47.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.42	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:4	34.08	2846	2.42	13.42	106	198	Off Idle	47.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.42	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:25:4	34.08	2847	2.42	13.43	106	198	Off Idle	47.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.39	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:4	34.08	2848	2.42	13.44	106	198	Off Idle	47.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.43	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:4	34.08	2846	2.42	13.42	106	198	Off Idle	47.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.39	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:4	34.08	2845	2.43	13.43	106	198	Off Idle	47.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.4	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:4	34.08	2847	2.43	13.41	106	198	Off Idle	47.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.37	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:5	34.08	2849	2.43	13.42	106	198	Off Idle	47.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.33	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:5	34.08	2858	2.43	13.41	106	198	Off Idle	47.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.35	14.77	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:5	34.08	2863	2.43	13.42	106	198	Off Idle	47.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.39	14.77	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:5	34.08	2864	2.43	13.4	106	198	Off Idle	47.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.37	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:5	34.08	2870	2.43	13.41	106	198	Off Idle	47.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.41	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:5	34.08	2867	2.43	13.41	106	198	Off Idle	47.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.42	14.88	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:6	34.08	2855	2.43	13.4	106	198	Off Idle	47.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.41	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:6	34.08	2855	2.43	13.41	106	198	Off Idle	47.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.4	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:6	34.08	2849	2.43	13.42	106	198	Off Idle	47.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.39	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:6	34.08	2825	2.43	13.42	106	198	Off Idle	47	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.35	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:6	34.08	2834	2.43	13.42	106	198	Off Idle	46.8	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.33	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:6	34.08	2841	2.43	13.43	106	198	Off Idle	46.7	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.35	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:6	34.08	2847	2.43	13.42	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.33	15.16	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:7	34.08	2849	2.43	13.41	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.32	15.12	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:7	34.08	2849	2.43	13.41	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.35	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:7	34.08	2859	2.43	13.42	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.36	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:7	34.08	2859	2.43	13.41	106	198	Off Idle	46.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.42	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:7	34.08	2863	2.43	13.42	106	198	Off Idle	46.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.43	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:7	34.08	2876	2.43	13.4	106	198	Off Idle	46.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.46	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:8	34.08	2870	2.43	13.42	106	198	Off Idle	46.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.47	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:25:8	34.08	2869	2.43	13.4	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.47	14.74	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:8	34.08	2869	2.43	13.41	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.43	14.73	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:8	34.08	2870	2.43	13.41	106	198	Off Idle	46.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.39	14.74	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:8	34.08	2866	2.43	13.42	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.39	14.78	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:8	34.08	2866	2.43	13.43	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.39	14.79	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:9	34.08	2866	2.43	13.42	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.39	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:25:9	34.08	2870	2.43	13.41	106	198	Off Idle	46.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.36	14.81	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:9	34.08	2876	2.44	13.41	106	198	Off Idle	46.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.39	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:9	34.08	2876	2.44	13.41	106	198	Off Idle	46	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.37	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:9	34.08	2874	2.44	13.42	106	198	Off Idle	45.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.38	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:9	34.08	2876	2.44	13.42	106	198	Off Idle	45.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.37	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:25:9	34.08	2876	2.44	13.43	106	198	Off Idle	45.9	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.39	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:26:0	34.08	2875	2.44	13.42	106	198	Off Idle	45.8	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.39	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:26:0	34.08	2879	2.44	13.42	106	198	Off Idle	45.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.44	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:26:0	34.08	2879	2.44	13.42	106	198	Off Idle	45.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.39	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:0	34.08	2878	2.44	13.42	106	198	Off Idle	45.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.45	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:0	34.08	2879	2.44	13.42	106	198	Off Idle	45.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.39	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:0	34.08	2878	2.44	13.44	106	198	Off Idle	45.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.42	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:1	34.08	2878	2.44	13.43	106	198	Off Idle	45.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.37	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:1	34.08	2874	2.44	13.44	106	198	Off Idle	45.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.39	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:1	34.08	2874	2.44	13.42	106	198	Off Idle	45.7	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.4	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:1	34.08	2878	2.44	13.43	106	198	Off Idle	45.7	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.39	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:1	34.08	2879	2.44	13.42	106	198	Off Idle	45.7	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.4	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:1	34.08	2877	2.44	13.42	106	198	Off Idle	45.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.39	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:26:1	34.08	2875	2.44	13.42	106	198	Off Idle	45.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.39	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:26:2	34.08	2888	2.44	13.42	106	198	Off Idle	45.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.35	15.05	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:26:2	34.08	2888	2.44	13.43	106	198	Off Idle	45.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.35	15.01	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:26:2	34.08	2891	2.44	13.42	106	198	Off Idle	45.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.35	14.93	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:26:2	34.08	2893	2.44	13.43	106	198	Off Idle	45.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.37	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:2	34.08	2899	2.44	13.43	106	198	Off Idle	45.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.37	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:2	34.08	2899	2.44	13.42	106	198	Off Idle	45.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.36	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:3	34.08	2898	2.44	13.43	106	198	Off Idle	45.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.36	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:26:3	34.08	2899	2.44	13.41	106	198	Off Idle	45	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.39	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:26:3	34.08	2900	2.44	13.41	106	198	Off Idle	44.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.33	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:3	34.08	2900	2.44	13.43	106	198	Off Idle	44.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.44	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:3	34.08	2897	2.44	13.41	106	198	Off Idle	44.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.41	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:3	34.08	2896	2.44	13.43	106	198	Off Idle	44.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.45	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:4	34.08	2885	2.44	13.42	106	198	Off Idle	44.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.45	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:4	34.08	2887	2.44	13.43	106	198	Off Idle	44	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.42	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:4	34.08	2888	2.44	13.42	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.48	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:4	34.08	2891	2.44	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.47	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:4	34.08	2893	2.44	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.5	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:4	34.08	2893	2.44	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.49	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:4	34.08	2894	2.44	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.53	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:5	34.08	2894	2.43	13.43	106	197	Off Idle	43.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.5	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:5	34.08	2894	2.43	13.42	106	197	Off Idle	43.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.55	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:5	34.08	2894	2.43	13.43	106	197	Off Idle	43.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.6	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:5	34.08	2889	2.43	13.42	106	197	Off Idle	44	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.57	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:5	34.08	2885	2.42	13.43	106	198	Off Idle	44	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.63	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:5	34.08	2885	2.42	13.42	106	198	Off Idle	44	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.62	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:6	34.08	2894	2.42	13.43	106	198	Off Idle	44	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.67	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:26:6	34.08	2921	2.41	13.41	106	198	Off Idle	44.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.7	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:6	34.08	2912	2.41	13.43	106	198	Off Idle	44.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.73	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:6	34.08	2906	2.4	13.42	106	198	Off Idle	44.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.81	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:6	34.08	2885	2.4	13.43	106	198	Off Idle	44.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.81	14.87	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:26:6	35.45	2896	2.4	13.43	106	198	Off Idle	44.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.83	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:6	35.45	2907	2.39	13.43	106	198	Off Idle	44.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.86	14.9	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:7	35.45	2907	2.39	13.43	106	198	Off Idle	44.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.9	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:26:7	35.45	2906	2.38	13.43	106	198	Off Idle	44.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.88	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:26:7	35.45	2902	2.38	13.42	106	198	Off Idle	44.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.94	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:26:7	35.45	2902	2.37	13.42	106	198	Off Idle	44.1	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.95	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:26:7	34.08	2896	2.37	13.43	106	198	Off Idle	44.1	0	2	132	944 Turbo	0.68	Lean	1	14.6	-6	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:26:7	34.08	2900	2.37	13.42	106	198	Off Idle	44.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.02	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:26:8	34.08	2900	2.36	13.42	106	198	Off Idle	44.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.03	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:26:8	34.08	2904	2.36	13.42	106	198	Off Idle	44.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.09	15.06	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:8	34.08	2905	2.36	13.42	106	198	Off Idle	44.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.09	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:8	35.45	2916	2.35	13.42	106	198	Off Idle	44	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.08	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:8	35.45	2908	2.35	13.42	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.12	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:8	35.45	2905	2.35	13.41	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.11	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:9	35.45	2926	2.35	13.42	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.12	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:9	35.45	2927	2.35	13.41	106	198	Off Idle	43.7	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.12	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:9	35.45	2926	2.35	13.41	106	198	Off Idle	43.5	0	2	132	944 Turbo	0.16	Rich	1	14.6	-6.15	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:9	35.45	2919	2.34	13.42	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.15	Rich	1	14.6	-6.12	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:9	35.45	2918	2.34	13.42	106	198	Off Idle	43.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.14	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:9	35.45	2913	2.34	13.42	106	198	Off Idle	43.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.15	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:26:9	35.45	2911	2.34	13.42	106	198	Off Idle	43.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.11	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:27:0	35.45	2911	2.34	13.42	106	198	Off Idle	43.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.14	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:0	35.45	2906	2.34	13.42	106	198	Off Idle	43.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.12	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:0	35.45	2913	2.34	13.42	106	198	Off Idle	43.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.14	15.05	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:0	35.45	2908	2.34	13.42	106	198	Off Idle	43.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.17	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:0	35.45	2909	2.34	13.43	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.16	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:0	35.45	2912	2.34	13.42	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.22	15.14	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:1	35.45	2918	2.34	13.41	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.18	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:1	35.45	2918	2.34	13.42	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.19	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:1	35.45	2926	2.34	13.42	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.22	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:1	35.45	2915	2.34	13.44	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.21	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:27:1	35.45	2907	2.34	13.43	106	198	Off Idle	43.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.23	15.09	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:27:1	35.45	2908	2.33	13.44	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.26	15.05	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:27:1	35.45	2914	2.33	13.44	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.3	15.01	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:27:2	35.45	2922	2.33	13.44	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.26	14.97	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:27:2	35.45	2922	2.33	13.42	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.28	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:27:2	35.45	2934	2.33	13.43	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.28	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:2	35.45	2926	2.33	13.43	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.35	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:2	35.45	2926	2.32	13.42	106	198	Off Idle	43.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.35	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:2	35.45	2931	2.32	13.44	106	198	Off Idle	43.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.41	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:27:3	35.45	2933	2.31	13.43	106	198	Off Idle	43.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.45	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:27:3	35.45	2930	2.31	13.41	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.52	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:27:3	35.45	2928	2.31	13.41	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.55	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:27:3	35.45	2924	2.3	13.41	106	198	Off Idle	42.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.58	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:27:3	35.45	2922	2.3	13.4	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.68	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:27:3	35.45	2921	2.3	13.39	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.69	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:4	35.45	2915	2.29	13.42	106	198	Off Idle	42.8	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.73	15.15	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:4	35.45	2908	2.28	13.43	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.69	Lean	1	14.6	-6.8	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:4	35.45	2890	2.28	13.43	106	198	Off Idle	42.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.79	15.12	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:4	35.45	2902	2.27	13.43	106	198	Off Idle	42.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.8	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:4	35.45	2914	2.27	13.44	106	198	Off Idle	42.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.85	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:4	35.45	2918	2.26	13.44	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.85	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:4	35.45	2919	2.26	13.44	106	198	Off Idle	42.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.84	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:27:5	35.45	2918	2.26	13.43	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.9	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:5	35.45	2920	2.25	13.43	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.91	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:5	35.45	2923	2.25	13.41	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.96	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:5	35.45	2924	2.24	13.41	106	198	Off Idle	43.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.96	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:5	35.45	2935	2.24	13.41	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.99	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:5	35.45	2935	2.23	13.41	106	198	Off Idle	43.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.02	14.75	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:6	35.45	2935	2.23	13.41	106	198	Off Idle	43	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.04	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:6	35.45	2935	2.22	13.42	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.12	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:6	35.45	2929	2.22	13.42	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.11	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:6	35.45	2929	2.21	13.43	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.19	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:27:6	35.45	2924	2.21	13.42	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.22	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:27:6	35.45	2921	2.21	13.42	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.27	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:27:6	35.45	2921	2.2	13.42	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.29	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:27:7	35.45	2918	2.2	13.42	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.31	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:27:7	35.45	2906	2.19	13.42	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.36	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:27:7	35.45	2917	2.19	13.42	106	198	Off Idle	42.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.39	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:27:7	35.45	2918	2.18	13.42	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.44	15.15	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:27:7	35.45	2920	2.17	13.42	106	198	Off Idle	42.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.48	15.18	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:27:7	35.45	2932	2.17	13.41	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.57	15.18	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:27:8	35.45	2924	2.16	13.4	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.56	15.16	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:27:8	35.45	2924	2.15	13.41	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:27:8	35.45	2922	2.15	13.41	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:27:8	35.45	2925	2.14	13.41	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:27:8	35.45	2925	2.13	13.42	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:27:8	35.45	2924	2.12	13.43	106	198	Off Idle	42.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.81	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:27:9	36.81	2944	2.11	13.44	106	198	Off Idle	42	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.92	14.94	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:27:9	36.81	2934	2.1	13.43	106	198	Off Idle	42	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.92	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:27:9	36.81	2922	2.09	13.44	106	198	Off Idle	42	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.96	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:27:9	36.81	2921	2.08	13.42	106	198	Off Idle	42.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.02	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:27:9	36.81	2920	2.07	13.43	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.06	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:27:9	35.45	2897	2.06	13.42	106	198	Off Idle	42.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.12	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:27:9	35.45	2920	2.05	13.42	106	198	Off Idle	42.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.2	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:0	35.45	2913	2.04	13.42	106	198	Off Idle	42.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.21	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:0	35.45	2913	2.03	13.42	106	198	Off Idle	42.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.28	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:0	35.45	2923	2.03	13.44	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.28	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:0	35.45	2913	2.02	13.44	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.33	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:0	35.45	2914	2.01	13.43	106	198	Off Idle	42.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.36	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:0	35.45	2917	2.01	13.44	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.38	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:1	35.45	2917	2	13.44	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.37	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:1	35.45	2920	1.99	13.44	106	198	Off Idle	42.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.36	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:1	36.81	2942	1.99	13.43	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.35	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:28:1	36.81	2942	1.98	13.44	106	198	Off Idle	42.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.36	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:1	36.81	2921	1.98	13.42	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.33	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:1	36.81	2910	1.98	13.42	106	198	Off Idle	42.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.37	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:1	36.81	2920	1.98	13.4	106	198	Off Idle	42.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.39	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:2	36.81	2938	1.98	13.41	106	198	Off Idle	42	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.4	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:2	36.81	2938	1.98	13.41	106	198	Off Idle	42	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.44	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:2	36.81	2915	1.98	13.41	106	198	Off Idle	42	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.44	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:2	36.81	2916	1.98	13.41	106	198	Off Idle	42.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.47	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:2	36.81	2914	1.98	13.41	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.44	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:2	36.81	2900	1.98	13.42	106	198	Off Idle	42.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.41	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:3	36.81	2914	1.98	13.42	106	198	Off Idle	42.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.41	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:3	36.81	2923	1.98	13.44	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.38	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:3	36.81	2923	1.98	13.43	106	198	Off Idle	42.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.43	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:3	36.81	2934	1.98	13.44	106	198	Off Idle	42.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.4	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:3	36.81	2925	1.98	13.44	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.45	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:3	35.45	2911	1.98	13.43	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.41	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:4	35.45	2920	1.98	13.43	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.45	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:4	35.45	2916	1.98	13.42	106	198	Off Idle	42.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.41	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:4	35.45	2905	1.98	13.41	106	198	Off Idle	42.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.48	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:4	35.45	2908	1.97	13.41	106	198	Off Idle	42.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.45	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:4	36.81	2919	1.97	13.42	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.44	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:4	36.81	2898	1.97	13.43	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.43	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:4	36.81	2898	1.97	13.43	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.66	Lean	1	14.6	-8.46	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:5	36.81	2898	1.97	13.44	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:5	36.81	2902	1.97	13.43	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.39	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:5	36.81	2907	1.97	13.42	106	198	Off Idle	43.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.4	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:5	36.81	2908	1.97	13.42	106	198	Off Idle	43.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.39	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:5	36.81	2910	1.97	13.41	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.4	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:5	36.81	2916	1.97	13.42	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.41	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:6	36.81	2916	1.97	13.42	106	198	Off Idle	43.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.45	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:6	36.81	2916	1.97	13.42	106	198	Off Idle	43.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.44	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:6	35.45	2903	1.97	13.42	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.48	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:6	35.45	2914	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.5	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:6	35.45	2912	1.97	13.42	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.47	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:6	35.45	2912	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.45	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:6	35.45	2908	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.44	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:7	36.81	2901	1.97	13.42	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.45	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:7	36.81	2901	1.97	13.42	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.47	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:7	36.81	2901	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.5	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:7	36.81	2901	1.97	13.42	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.5	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:7	36.81	2906	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.51	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:7	36.81	2906	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.49	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:8	36.81	2908	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.47	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:8	36.81	2910	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.5	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:8	36.81	2908	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.47	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:8	36.81	2912	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.5	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:8	35.45	2876	1.97	13.42	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.48	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:8	35.45	2899	1.97	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.5	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:9	35.45	2899	1.97	13.42	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.5	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:9	35.45	2888	1.97	13.44	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.53	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:9	35.45	2900	1.97	13.42	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.52	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:9	35.45	2905	1.97	13.44	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.52	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:28:9	35.45	2904	1.97	13.44	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.52	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:9	35.45	2902	1.97	13.45	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.47	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:28:9	35.45	2904	1.97	13.44	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.48	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:0	35.45	2905	1.97	13.45	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.45	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:0	35.45	2912	1.97	13.44	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.5	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:29:0	36.81	2917	1.97	13.44	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.53	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:29:0	36.81	2914	1.97	13.44	106	198	Off Idle	43.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.58	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:29:0	36.81	2914	1.96	13.42	106	198	Off Idle	43.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.62	14.77	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:29:0	36.81	2906	1.96	13.41	106	198	Off Idle	43.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.64	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:29:1	36.81	2909	1.96	13.42	106	198	Off Idle	43.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.66	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:29:1	36.81	2903	1.95	13.42	106	198	Off Idle	43.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.67	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:29:1	36.81	2903	1.95	13.41	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.71	14.79	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:1	36.81	2899	1.95	13.42	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.67	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:1	36.81	2899	1.95	13.42	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.69	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:1	36.81	2896	1.94	13.43	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.73	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:1	36.81	2897	1.94	13.42	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.75	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:2	36.81	2894	1.93	13.44	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.8	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:2	36.81	2896	1.93	13.43	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.84	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:2	36.81	2902	1.92	13.43	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.92	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:2	36.81	2900	1.92	13.44	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.93	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:2	36.81	2888	1.91	13.43	106	198	Off Idle	43.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.98	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:29:2	35.45	2898	1.9	13.42	106	198	Off Idle	43.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:3	35.45	2909	1.9	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.03	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:29:3	35.45	2898	1.88	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.08	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:29:3	35.45	2889	1.87	13.43	106	198	Off Idle	43.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.18	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:29:3	35.45	2889	1.86	13.42	106	198	Off Idle	44	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.31	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:29:3	36.81	2900	1.84	13.42	106	198	Idle	44	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.38	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:3	36.81	2884	1.83	13.44	106	198	Idle	44	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.49	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:4	36.81	2884	1.82	13.43	106	198	Idle	44.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.54	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:4	36.81	2885	1.81	13.44	106	198	Idle	44.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.61	14.95	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:4	36.81	2872	1.8	13.43	106	198	Idle	44.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.63	14.9	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:4	34.08	2846	1.78	13.44	106	198	Idle	44.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.67	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:4	34.08	2846	1.77	13.42	106	198	Idle	44.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.71	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:4	23.18	2823	1.76	13.42	106	198	Idle	44.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.75	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:4	23.18	2809	1.75	13.42	106	198	Idle	44.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.8	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:5	19.09	2816	1.74	13.42	106	198	Idle	44.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.81	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:5	19.09	2822	1.73	13.44	106	198	Idle	44.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.85	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:5	19.09	2820	1.72	13.43	106	198	Idle	44.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.84	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:5	19.09	2817	1.71	13.43	106	198	Idle	44.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.85	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:5	19.09	2812	1.7	13.44	106	198	Idle	44.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.9	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:5	19.09	2821	1.69	13.43	106	198	Idle	44.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.89	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:6	19.09	2847	1.68	13.43	106	198	Idle	44.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.89	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:6	19.09	2847	1.67	13.43	106	198	Idle	44.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.89	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:6	19.09	2882	1.67	13.43	106	198	Idle	43.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.87	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:6	19.09	2898	1.67	13.42	106	198	Idle	43.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.84	14.88	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:6	19.09	2912	1.67	13.43	106	198	Idle	43.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.83	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:6	19.09	2908	1.67	13.42	106	198	Idle	43.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.79	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:6	19.09	2903	1.67	13.43	106	198	Idle	43.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.8	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:7	19.09	2893	1.67	13.44	106	198	Idle	43.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.77	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:7	19.09	2888	1.67	13.43	106	198	Idle	43.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.76	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:7	19.09	2870	1.67	13.43	106	198	Idle	43.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.74	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:7	19.09	2851	1.67	13.42	106	197	Idle	43.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.74	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:7	19.09	2840	1.67	13.43	106	197	Idle	43.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.71	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:7	19.09	2827	1.67	13.43	106	197	Idle	43.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.68	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:8	19.09	2825	1.67	13.44	106	198	Idle	43.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.68	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:8	19.09	2811	1.67	13.44	106	198	Idle	43.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.69	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:8	19.09	2823	1.67	13.45	106	198	Idle	43.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:8	19.09	2824	1.67	13.44	106	198	Idle	43.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:8	19.09	2836	1.68	13.43	106	198	Idle	43.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	15.33	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:8	19.09	2849	1.68	13.42	106	198	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	15.67	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:9	19.09	2849	1.68	13.42	106	198	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	16.13	1.1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:9	19.09	2858	1.68	13.42	106	198	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	16.9	1.15	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:9	19.09	2861	1.68	13.42	106	198	Idle	43.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	17.42	1.19	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:9	19.09	2880	1.68	13.42	106	198	Idle	43.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	17.94	1.22	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:29:9	19.09	2868	1.68	13.42	106	198	Idle	43.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	18.45	1.26	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:9	19.09	2850	1.68	13.43	106	198	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	18.94	1.29	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:29:9	19.09	2843	1.68	13.42	106	198	Idle	43.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	19.39	1.32	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:0	19.09	2841	1.68	13.44	106	198	Idle	43.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	19.76	1.35	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:0	19.09	2832	1.68	13.44	106	198	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.03	1.36	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:0	19.09	2823	1.68	13.43	106	198	Idle	44.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.19	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:0	19.09	2823	1.68	13.44	106	198	Idle	44.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.2	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:0	19.09	2796	1.67	13.43	106	198	Idle	45	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:0	19.09	2806	1.67	13.43	106	198	Idle	45.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:1	19.09	2816	1.67	13.43	106	198	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:1	19.09	2822	1.67	13.43	106	198	Idle	45.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:1	19.09	2815	1.67	13.43	106	198	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:1	19.09	2824	1.67	13.43	106	198	Idle	46	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:1	19.09	2826	1.66	13.42	106	198	Idle	46.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:1	19.09	2827	1.66	13.43	106	198	Idle	46.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:1	19.09	2828	1.66	13.42	106	198	Idle	46.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:2	19.09	2825	1.66	13.42	106	198	Idle	46.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:2	19.09	2823	1.66	13.42	106	198	Idle	46.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:2	19.09	2819	1.65	13.42	106	198	Idle	46.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:2	19.09	2818	1.65	13.42	106	198	Idle	46.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:2	19.09	2810	1.65	13.43	106	198	Idle	46.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:2	19.09	2808	1.65	13.43	106	198	Idle	47	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:3	19.09	2808	1.64	13.43	106	198	Idle	47.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:3	19.09	2804	1.64	13.43	106	198	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:3	19.09	2804	1.64	13.43	106	198	Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:3	19.09	2802	1.64	13.42	106	198	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:3	19.09	2804	1.64	13.43	106	198	Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:3	19.09	2802	1.64	13.42	106	198	Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:4	19.09	2803	1.63	13.43	106	197	Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:4	19.09	2802	1.63	13.43	105	197	Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:4	19.09	2799	1.63	13.43	105	197	Idle	48.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:4	19.09	2796	1.63	13.44	105	198	Idle	48.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:4	19.09	2796	1.63	13.42	106	198	Idle	48.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:4	19.09	2795	1.63	13.42	106	198	Full Load	48.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:4	19.09	2789	1.63	13.42	106	198	Full Load	48.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:5	9.54	2718	1.63	13.42	106	198	Off Idle	48.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:30:5	12.27	2808	1.63	13.43	106	198	Off Idle	48.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:30:5	12.27	2802	1.63	13.43	106	198	Off Idle	48.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:30:5	14.99	2804	1.63	13.43	106	198	Off Idle	49	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:30:5	17.72	2800	1.63	13.44	106	198	Off Idle	49.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:30:5	20.45	2802	1.64	13.43	106	198	Off Idle	49.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:30:6	20.45	2802	1.64	13.44	106	198	Off Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:30:6	23.18	2799	1.64	13.42	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:6	25.9	2804	1.65	13.43	106	198	Off Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:6	25.9	2812	1.66	13.42	106	198	Off Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:30:6	28.63	2817	1.66	13.41	106	198	Off Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:6	31.36	2834	1.67	13.41	106	198	Off Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:6	31.36	2838	1.68	13.41	106	198	Off Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:7	36.81	2836	1.68	13.42	106	198	Off Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:7	36.81	2828	1.69	13.42	106	198	Off Idle	50.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:7	36.81	2819	1.7	13.43	106	198	Off Idle	50	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:7	36.81	2811	1.71	13.44	106	198	Off Idle	50	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:7	36.81	2811	1.72	13.42	106	198	Off Idle	49.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:7	36.81	2806	1.72	13.44	106	198	Off Idle	49.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.61	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:8	36.81	2806	1.73	13.42	106	198	Off Idle	49.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.57	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:8	36.81	2801	1.74	13.43	106	198	Off Idle	49.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.57	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:8	36.81	2796	1.75	13.44	106	198	Off Idle	49.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.51	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:8	36.81	2796	1.75	13.44	106	198	Off Idle	49.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.46	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:30:8	36.81	2796	1.76	13.43	106	198	Off Idle	49.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.46	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:8	36.81	2784	1.76	13.44	106	198	Off Idle	49.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.49	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:30:9	36.81	2783	1.76	13.42	106	198	Off Idle	49.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.5	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:30:9	36.81	2782	1.77	13.43	105	198	Off Idle	49.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.48	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:30:9	36.81	2777	1.77	13.42	105	198	Off Idle	49.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.48	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:30:9	36.81	2772	1.77	13.42	105	198	Off Idle	49.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.48	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:30:9	36.81	2767	1.77	13.42	106	198	Off Idle	49.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.45	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:30:9	36.81	2767	1.77	13.43	106	198	Off Idle	50	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:30:9	36.81	2767	1.77	13.43	106	198	Off Idle	50.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.47	20.17	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:0	36.81	2771	1.77	13.43	106	198	Off Idle	50.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	20.06	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:0	36.81	2771	1.77	13.43	106	198	Off Idle	50.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.49	19.91	1.36	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:0	36.81	2775	1.77	13.42	106	198	Off Idle	50.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.51	19.73	1.34	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:0	36.81	2778	1.77	13.42	106	198	Off Idle	50.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.48	19.49	1.33	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:0	36.81	2777	1.77	13.43	106	198	Off Idle	50.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.48	19.22	1.31	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:0	36.81	2778	1.76	13.41	106	198	Off Idle	51.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.53	18.94	1.29	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:1	36.81	2777	1.76	13.41	106	198	Off Idle	51.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.55	18.63	1.27	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:1	36.81	2776	1.76	13.41	106	198	Off Idle	51.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.55	18.3	1.25	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:1	36.81	2770	1.76	13.41	106	198	Off Idle	51.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	17.96	1.22	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:1	36.81	2769	1.76	13.42	106	198	Off Idle	51.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.57	17.64	1.2	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:1	36.81	2745	1.76	13.44	106	198	Off Idle	51.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.55	17.37	1.18	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:1	36.81	2765	1.75	13.42	106	198	Off Idle	52	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.55	17.04	1.16	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:1	36.81	2764	1.75	13.42	106	198	Off Idle	52	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.54	16.86	1.15	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:2	36.81	2764	1.75	13.44	106	198	Off Idle	52	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.55	16.72	1.14	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:2	36.81	2763	1.75	13.43	106	198	Off Idle	52	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.56	16.58	1.13	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:2	36.81	2763	1.75	13.43	106	198	Off Idle	51.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.56	16.45	1.12	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:2	36.81	2761	1.74	13.43	106	198	Off Idle	51.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.58	16.34	1.11	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:2	36.81	2763	1.74	13.44	106	198	Off Idle	52	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.59	16.24	1.11	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:2	36.81	2764	1.74	13.45	106	198	Off Idle	52	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.61	16.15	1.1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:3	36.81	2763	1.74	13.45	106	198	Off Idle	52	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.6	16.06	1.09	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:3	36.81	2769	1.74	13.44	106	198	Off Idle	52	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.6	15.92	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:3	36.81	2763	1.74	13.44	106	198	Off Idle	52	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.6	15.84	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:3	36.81	2763	1.74	13.43	105	198	Off Idle	51.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.59	15.77	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:3	36.81	2766	1.73	13.44	105	198	Off Idle	51.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.59	15.7	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:3	36.81	2765	1.73	13.42	105	198	Off Idle	51.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.58	15.65	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:31:4	36.81	2765	1.73	13.44	105	198	Off Idle	51.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.55	15.57	1.06	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:4	36.81	2765	1.74	13.43	105	198	Off Idle	51.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.58	15.52	1.06	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:4	36.81	2765	1.74	13.42	105	198	Off Idle	51.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.54	15.5	1.06	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:4	36.81	2765	1.74	13.42	106	198	Off Idle	51.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.56	15.49	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:4	36.81	2762	1.74	13.42	106	197	Off Idle	51.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.56	15.46	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:4	36.81	2764	1.73	13.43	106	197	Off Idle	51.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.58	15.44	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:4	36.81	2763	1.73	13.43	106	197	Off Idle	51.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.6	15.41	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:5	36.81	2762	1.72	13.43	106	198	Full Load	51.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.66	15.39	1.05	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:31:5	36.81	2760	1.71	13.42	106	198	Idle	51.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.73	15.36	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:5	36.81	2784	1.7	13.42	106	198	Idle	50.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.82	15.32	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:5	36.81	2772	1.69	13.41	106	198	Idle	50.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.87	15.29	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:5	36.81	2754	1.68	13.42	106	198	Idle	50.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.93	15.23	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:31:5	36.81	2736	1.67	13.43	106	198	Idle	50.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.98	15.19	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:31:6	36.81	2729	1.67	13.43	106	198	Idle	50.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.99	15.15	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:6	36.81	2729	1.66	13.44	106	198	Idle	50.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.02	15.1	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:6	36.81	2717	1.65	13.44	106	198	Idle	50.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.06	15.07	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:6	36.81	2669	1.64	13.44	106	198	Idle	50.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.08	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:6	34.08	2669	1.63	13.44	106	198	Idle	50.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.11	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:6	28.63	2673	1.63	13.44	106	198	Idle	50	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.13	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:6	23.18	2674	1.62	13.43	106	198	Idle	49.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.12	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:7	23.18	2674	1.6	13.44	106	198	Idle	49.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.12	15	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:7	19.09	2697	1.59	13.44	106	198	Idle	49.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-10.14	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:31:7	19.09	2722	1.59	13.44	106	198	Idle	49.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.14	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:7	19.09	2736	1.58	13.44	106	198	Idle	49.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-10.13	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:31:7	19.09	2736	1.58	13.45	106	198	Idle	49.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-10.15	14.94	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:7	19.09	2744	1.57	13.46	106	198	Idle	49.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.15	14.92	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:8	19.09	2745	1.57	13.44	106	198	Idle	50	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.19	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:8	19.09	2748	1.57	13.44	106	198	Idle	50.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.18	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:8	19.09	2744	1.58	13.44	106	198	Idle	50.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.21	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:8	19.09	2740	1.58	13.43	106	198	Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.2	14.81	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:8	19.09	2739	1.58	13.43	106	198	Idle	50.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.19	14.8	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:8	19.09	2720	1.57	13.42	106	198	Idle	51.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.17	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:9	19.09	2725	1.57	13.42	105	198	Idle	51.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.13	14.8	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:9	19.09	2724	1.57	13.41	105	198	Idle	51.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.1	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:9	19.09	2727	1.57	13.43	105	198	Idle	51.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.1	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:9	19.09	2711	1.57	13.43	106	198	Idle	51.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.08	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:9	19.09	2711	1.56	13.44	106	198	Idle	52.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.08	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:9	19.09	2687	1.56	13.43	106	198	Idle	52.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.09	14.97	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:31:9	19.09	2709	1.56	13.43	106	198	Idle	52.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.06	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:0	19.09	2710	1.56	13.42	106	198	Idle	52.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.04	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:0	19.09	2710	1.56	13.41	106	198	Idle	52.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.04	15.16	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:0	19.09	2716	1.55	13.43	106	197	Idle	52.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.04	15.29	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:0	19.09	2716	1.55	13.42	106	197	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	15.36	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:0	19.09	2718	1.55	13.43	106	197	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	15.44	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:0	19.09	2719	1.55	13.44	106	197	Idle	52.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	15.52	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:1	19.09	2717	1.54	13.43	106	197	Idle	52.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	15.61	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:1	19.09	2717	1.54	13.44	106	197	Idle	52.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	15.76	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:1	19.09	2712	1.54	13.43	106	198	Idle	52.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	15.99	1.09	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:1	19.09	2705	1.54	13.43	106	198	Idle	53	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	16.33	1.11	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:1	19.09	2705	1.54	13.43	106	198	Idle	53.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	16.77	1.14	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:1	19.09	2697	1.53	13.42	106	198	Idle	53.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	17.23	1.17	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:1	19.09	2693	1.53	13.42	106	198	Idle	53.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	17.68	1.2	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:2	19.09	2693	1.53	13.43	106	198	Idle	53.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	18.14	1.24	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:2	19.09	2689	1.53	13.43	106	198	Idle	53.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	18.61	1.27	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:2	19.09	2686	1.53	13.42	106	198	Idle	53.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	19.05	1.3	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:2	19.09	2686	1.53	13.43	106	198	Idle	53.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	19.46	1.33	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:2	19.09	2684	1.52	13.43	106	198	Idle	53.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	19.8	1.35	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:2	19.09	2685	1.52	13.43	106	198	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	19.93	1.36	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:3	19.09	2685	1.52	13.42	106	198	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.12	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:3	19.09	2686	1.52	13.43	106	198	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:3	19.09	2686	1.52	13.44	106	198	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:3	19.09	2686	1.52	13.43	106	198	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:3	19.09	2686	1.51	13.43	106	198	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:3	19.09	2684	1.51	13.43	106	198	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:4	19.09	2682	1.51	13.43	106	198	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:4	19.09	2677	1.51	13.44	106	198	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:4	19.09	2676	1.51	13.43	106	198	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:4	19.09	2672	1.51	13.44	106	198	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:4	19.09	2670	1.51	13.44	106	198	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:4	19.09	2669	1.5	13.43	106	198	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:4	19.09	2666	1.5	13.43	106	198	Idle	54.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:5	19.09	2666	1.5	13.43	105	198	Idle	55.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:5	19.09	2666	1.5	13.43	105	198	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:5	19.09	2664	1.5	13.41	106	198	Idle	55.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:5	19.09	2665	1.5	13.43	106	198	Idle	55.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:5	19.09	2665	1.5	13.43	106	198	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:5	19.09	2666	1.49	13.42	106	198	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:6	19.09	2664	1.49	13.44	106	198	Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:6	19.09	2664	1.49	13.44	106	198	Idle	56.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:6	19.09	2663	1.49	13.43	106	198	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:6	19.09	2660	1.49	13.44	106	198	Idle	56.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.2	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:6	19.09	2656	1.49	13.43	106	198	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.2	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:32:6	19.09	2656	1.48	13.44	106	198	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.19	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:6	19.09	2654	1.48	13.42	106	198	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.19	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:7	19.09	2652	1.48	13.43	106	198	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:7	19.09	2649	1.48	13.44	106	198	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:7	19.09	2648	1.48	13.43	106	198	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:7	19.09	2645	1.47	13.45	106	198	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:7	19.09	2646	1.47	13.45	106	198	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:7	19.09	2645	1.47	13.43	106	198	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:8	19.09	2652	1.47	13.44	106	198	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:8	19.09	2643	1.47	13.43	106	198	Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:8	19.09	2632	1.47	13.43	106	198	Idle	57.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:8	19.09	2640	1.46	13.42	105	198	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:8	19.09	2638	1.46	13.43	105	198	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:8	19.09	2634	1.46	13.42	105	198	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:9	19.09	2634	1.46	13.42	105	198	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:9	19.09	2630	1.46	13.43	105	198	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:9	19.09	2627	1.46	13.42	105	198	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:9	19.09	2625	1.46	13.44	106	198	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:9	19.09	2625	1.46	13.43	106	198	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:9	19.09	2624	1.46	13.44	106	198	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:32:9	19.09	2623	1.46	13.44	106	198	Idle	57.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:0	19.09	2623	1.46	13.44	106	198	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:0	19.09	2624	1.46	13.42	106	198	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:0	19.09	2622	1.46	13.43	106	198	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:0	19.09	2622	1.46	13.43	106	198	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:0	19.09	2621	1.46	13.43	106	198	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:0	19.09	2620	1.46	13.43	106	198	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:1	19.09	2619	1.46	13.42	106	198	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:1	19.09	2616	1.45	13.43	106	198	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:1	19.09	2614	1.45	13.42	106	198	Idle	57.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:1	19.09	2612	1.45	13.42	106	198	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:1	19.09	2609	1.45	13.43	106	198	Idle	58.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:1	19.09	2608	1.45	13.44	106	198	Idle	58.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:1	19.09	2608	1.45	13.42	106	198	Idle	58.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:2	19.09	2604	1.45	13.43	106	198	Idle	58.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:2	19.09	2604	1.45	13.43	106	198	Idle	58.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:2	19.09	2603	1.45	13.44	106	198	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:2	19.09	2603	1.45	13.43	106	198	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:2	19.09	2600	1.44	13.43	106	198	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:2	19.09	2597	1.44	13.42	106	198	Idle	59.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:3	19.09	2595	1.44	13.42	105	198	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:3	19.09	2595	1.44	13.42	105	198	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:3	19.09	2594	1.43	13.43	105	198	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:3	19.09	2591	1.43	13.44	106	198	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:3	19.09	2590	1.43	13.43	106	198	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:3	19.09	2588	1.43	13.42	106	197	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:4	19.09	2584	1.43	13.43	106	197	Idle	59.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:4	19.09	2584	1.43	13.44	106	197	Idle	59.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:4	19.09	2583	1.42	13.42	106	198	Idle	59.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:4	19.09	2581	1.42	13.42	106	198	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:4	19.09	2570	1.42	13.43	106	198	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:4	19.09	2578	1.42	13.44	106	198	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:4	19.09	2588	1.42	13.44	105	198	Idle	60.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:5	19.09	2588	1.42	13.43	105	198	Idle	60.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:5	19.09	2574	1.41	13.43	105	198	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:5	19.09	2571	1.41	13.42	106	198	Idle	60.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:5	19.09	2571	1.41	13.43	106	198	Idle	60.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:5	19.09	2570	1.41	13.43	106	198	Idle	61.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:33:5	19.09	2568	1.41	13.44	106	198	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:6	19.09	2567	1.4	13.44	105	198	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:6	19.09	2566	1.4	13.44	105	198	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:6	19.09	2565	1.4	13.43	106	198	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:6	19.09	2544	1.4	13.43	106	198	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:6	19.09	2563	1.4	13.43	106	198	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:6	19.09	2563	1.4	13.43	106	198	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:6	19.09	2560	1.39	13.44	106	198	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:7	19.09	2559	1.39	13.43	106	198	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:7	19.09	2558	1.39	13.42	106	198	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:7	19.09	2555	1.39	13.43	106	198	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:7	19.09	2553	1.39	13.41	106	198	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:7	19.09	2552	1.39	13.41	106	198	Idle	61.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:7	19.09	2549	1.39	13.42	106	198	Idle	61.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:8	19.09	2547	1.38	13.42	106	198	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:8	19.09	2544	1.38	13.41	106	198	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:8	19.09	2542	1.38	13.42	106	198	Idle	62	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:8	19.09	2540	1.38	13.43	106	198	Idle	62	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:8	19.09	2537	1.38	13.42	106	198	Idle	62	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:8	19.09	2534	1.38	13.43	106	198	Full Load	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:9	19.09	2534	1.38	13.43	106	198	Off Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:9	19.09	2533	1.38	13.43	106	198	Off Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:33:9	19.09	2531	1.38	13.43	106	198	Off Idle	62.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:33:9	9.54	2466	1.39	13.45	105	198	Off Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:33:9	9.54	2546	1.39	13.44	105	198	Off Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:33:9	12.27	2542	1.39	13.44	105	198	Off Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:33:9	14.99	2544	1.39	13.43	105	198	Off Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:34:0	17.72	2540	1.39	13.43	105	198	Off Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:34:0	17.72	2540	1.4	13.43	105	198	Off Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:34:0	20.45	2530	1.4	13.44	105	198	Off Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:34:0	23.18	2539	1.4	13.43	105	198	Off Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:34:0	23.18	2542	1.41	13.44	106	198	Off Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:34:0	25.9	2542	1.41	13.42	106	198	Off Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:34:1	28.63	2549	1.42	13.43	106	198	Off Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:34:1	28.63	2554	1.43	13.42	105	198	Off Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:34:1	31.36	2559	1.43	13.44	105	198	Off Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:34:1	34.08	2566	1.44	13.42	105	198	Off Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:34:1	34.08	2545	1.45	13.42	105	198	Off Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:34:1	35.45	2545	1.46	13.42	105	198	Off Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:34:1	35.45	2541	1.46	13.43	105	198	Off Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:34:2	35.45	2539	1.47	13.43	106	198	Off Idle	63.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.14	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:34:2	35.45	2539	1.48	13.43	106	198	Off Idle	63.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.13	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:34:2	35.45	2525	1.49	13.43	105	198	Off Idle	63.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.1	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:34:2	35.45	2518	1.49	13.43	105	198	Off Idle	63.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:34:2	35.45	2515	1.5	13.42	105	198	Off Idle	63.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.06	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:34:2	35.45	2515	1.51	13.42	106	198	Off Idle	63.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.02	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:34:3	35.45	2514	1.52	13.41	106	198	Off Idle	63.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.01	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:34:3	35.45	2517	1.53	13.41	106	198	Off Idle	63.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:34:3	35.45	2518	1.54	13.42	106	198	Off Idle	64.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:34:3	35.45	2520	1.55	13.42	106	198	Off Idle	64.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:34:3	35.45	2526	1.56	13.42	106	198	Off Idle	64.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:34:3	35.45	2529	1.56	13.42	106	198	Off Idle	64.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:34:4	35.45	2529	1.57	13.44	106	198	Off Idle	64.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.82	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:34:4	35.45	2538	1.58	13.43	106	198	Off Idle	64.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:34:4	35.45	2527	1.59	13.45	105	198	Off Idle	64.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.75	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:34:4	35.45	2526	1.6	13.43	105	198	Off Idle	64.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.71	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:34:4	35.45	2528	1.61	13.43	105	198	Off Idle	64.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:34:4	35.45	2524	1.62	13.43	106	198	Off Idle	64.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.61	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:34:4	35.45	2524	1.63	13.45	106	198	Off Idle	65.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.58	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:34:5	35.45	2522	1.64	13.43	106	198	Off Idle	65.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.55	20.16	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:34:5	35.45	2525	1.65	13.42	105	198	Off Idle	65.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.51	20.09	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:34:5	35.45	2505	1.66	13.44	105	198	Off Idle	65.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	19.97	1.36	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:5	35.45	2514	1.67	13.43	105	198	Off Idle	65.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.44	19.81	1.35	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:5	35.45	2526	1.68	13.43	106	198	Off Idle	65.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.37	19.62	1.34	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:5	35.45	2526	1.69	13.42	106	198	Off Idle	65.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.29	19.39	1.32	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:6	35.45	2525	1.69	13.41	106	198	Off Idle	65.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.25	19.14	1.3	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:6	35.45	2523	1.71	13.42	105	198	Off Idle	65.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.2	18.86	1.29	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:34:6	35.45	2522	1.72	13.41	105	198	Off Idle	65.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.12	18.57	1.27	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:34:6	35.45	2516	1.74	13.41	105	198	Off Idle	65.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.98	18.07	1.23	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:34:6	35.45	2514	1.75	13.41	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.91	17.82	1.21	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:34:6	35.45	2514	1.76	13.43	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.86	17.68	1.2	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:6	35.45	2511	1.77	13.42	106	197	Off Idle	65.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.74	17.31	1.18	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:7	35.45	2507	1.79	13.42	106	197	Off Idle	65.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.64	17.1	1.16	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:7	35.45	2506	1.8	13.41	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.58	16.84	1.15	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:7	35.45	2508	1.8	13.41	105	198	Off Idle	65.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.57	16.69	1.14	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:7	35.45	2508	1.81	13.4	105	198	Off Idle	65.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.52	16.62	1.13	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:7	35.45	2511	1.82	13.41	105	198	Off Idle	65.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.46	16.44	1.12	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:7	35.45	2517	1.83	13.41	105	198	Off Idle	65.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.43	16.35	1.11	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:8	35.45	2518	1.84	13.42	105	198	Off Idle	65.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.4	16.26	1.11	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:8	35.45	2519	1.85	13.42	105	198	Off Idle	65.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.35	16.17	1.1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:8	35.45	2518	1.86	13.41	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.32	16.08	1.1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:8	35.45	2518	1.87	13.42	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.29	16	1.09	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:8	35.45	2516	1.88	13.41	106	198	Off Idle	65.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.21	15.85	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:8	35.45	2516	1.89	13.42	105	198	Off Idle	65.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.16	15.77	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:34:9	35.45	2510	1.9	13.42	105	198	Off Idle	65.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.09	15.68	1.07	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:9	35.45	2509	1.91	13.44	105	198	Off Idle	65.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.02	15.59	1.06	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:9	34.08	2488	1.91	13.43	105	198	Off Idle	65.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8	15.52	1.06	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:34:9	34.08	2497	1.92	13.44	105	198	Off Idle	65.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.91	15.45	1.05	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:34:9	34.08	2508	1.93	13.43	105	198	Off Idle	65.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.85	15.41	1.05	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:34:9	34.08	2509	1.93	13.45	105	198	Off Idle	65.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.82	15.37	1.05	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:34:9	34.08	2509	1.94	13.44	105	198	Off Idle	65.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.76	15.34	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:35:0	34.08	2511	1.95	13.42	106	198	Off Idle	65.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	15.3	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:35:0	34.08	2511	1.95	13.42	106	198	Off Idle	65.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	15.28	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:35:0	34.08	2511	1.97	13.41	106	197	Off Idle	65.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.59	15.23	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:35:0	34.08	2522	1.98	13.42	105	197	Off Idle	65	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.54	15.2	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:35:0	34.08	2517	1.98	13.43	105	198	Off Idle	64.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.5	15.19	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:35:0	34.08	2517	1.99	13.44	105	198	Off Idle	65	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.45	15.16	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:35:1	34.08	2517	2	13.43	106	198	Off Idle	65.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.35	15.15	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:35:1	34.08	2517	2.01	13.42	106	198	Off Idle	65.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.3	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:35:1	34.08	2518	2.02	13.42	106	198	Off Idle	65.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.26	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:35:1	34.08	2518	2.03	13.43	106	198	Off Idle	65.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.17	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:35:1	34.08	2517	2.03	13.42	106	198	Off Idle	65.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.15	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:35:1	34.08	2513	2.04	13.43	106	198	Off Idle	65.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.13	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:35:1	34.08	2512	2.06	13.44	105	198	Off Idle	65.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.97	15.23	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:35:2	34.08	2512	2.07	13.43	105	198	Off Idle	65.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.87	15.25	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:35:2	34.08	2510	2.08	13.43	105	198	Off Idle	65.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.79	15.26	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:2	34.08	2514	2.09	13.43	106	197	Off Idle	65.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.69	15.27	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:2	34.08	2514	2.1	13.42	106	197	Off Idle	65.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.64	15.27	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:2	34.08	2514	2.12	13.41	106	197	Off Idle	65.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.53	15.27	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:2	34.08	2521	2.13	13.43	105	198	Off Idle	65.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.43	15.24	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:3	34.08	2524	2.14	13.43	105	198	Off Idle	65.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.36	15.23	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:3	34.08	2532	2.15	13.44	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.32	15.21	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:3	34.08	2534	2.16	13.42	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.23	15.19	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:3	34.08	2534	2.17	13.42	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.2	15.15	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:3	34.08	2530	2.18	13.41	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.16	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:3	34.08	2528	2.19	13.42	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.15	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:35:4	34.08	2545	2.19	13.41	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.12	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:4	34.08	2533	2.2	13.42	106	198	Off Idle	65.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.12	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:4	34.08	2517	2.21	13.43	106	198	Off Idle	65.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.09	15.02	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:4	34.08	2517	2.22	13.42	106	198	Off Idle	65.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.02	15.02	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:4	34.08	2522	2.22	13.43	105	198	Off Idle	65.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.02	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:4	34.08	2513	2.23	13.44	105	198	Off Idle	65.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.99	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:4	34.08	2524	2.23	13.44	105	198	Off Idle	65.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.97	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:5	34.08	2530	2.23	13.43	106	198	Off Idle	65.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.96	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:5	34.08	2532	2.23	13.42	106	198	Off Idle	65.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.95	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:5	34.08	2539	2.23	13.42	106	198	Off Idle	65.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.92	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:5	34.08	2543	2.24	13.41	106	198	Off Idle	65.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.93	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:5	34.08	2542	2.24	13.42	106	198	Off Idle	65.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.95	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:5	34.08	2542	2.24	13.41	106	198	Off Idle	65	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.92	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:6	34.08	2534	2.24	13.42	105	198	Off Idle	64.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.91	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:6	34.08	2529	2.24	13.41	105	198	Off Idle	64.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.9	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:6	34.08	2529	2.24	13.43	105	198	Off Idle	64.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.92	14.99	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:6	34.08	2526	2.24	13.41	106	198	Off Idle	64.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.86	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:6	34.08	2527	2.24	13.41	106	198	Off Idle	64.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.86	15.03	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:6	34.08	2509	2.24	13.41	106	198	Off Idle	64.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.85	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:6	34.08	2518	2.24	13.41	105	198	Off Idle	64.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.82	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:7	34.08	2531	2.24	13.42	105	198	Off Idle	64	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.81	15.17	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:7	34.08	2531	2.24	13.43	105	198	Off Idle	63.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.84	15.17	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:7	34.08	2531	2.25	13.44	105	198	Off Idle	63.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.81	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:7	34.08	2538	2.25	13.44	105	198	Off Idle	63.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.83	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:7	34.08	2544	2.25	13.42	105	198	Off Idle	64	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.81	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:35:7	34.08	2551	2.25	13.42	105	198	Off Idle	64	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.81	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:8	34.08	2551	2.25	13.42	105	198	Off Idle	64	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.85	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:8	34.08	2559	2.25	13.42	106	198	Off Idle	64	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.88	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:8	34.08	2542	2.25	13.41	106	198	Off Idle	64	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.87	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:8	34.08	2540	2.25	13.43	106	198	Off Idle	64	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.89	14.78	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:8	34.08	2540	2.25	13.43	105	198	Off Idle	64	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.88	14.75	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:8	34.08	2541	2.25	13.44	105	198	Off Idle	64	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.84	14.75	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:9	34.08	2549	2.25	13.44	105	198	Off Idle	64.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.82	14.74	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:9	34.08	2549	2.25	13.43	105	198	Off Idle	64.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.83	14.76	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:9	34.08	2549	2.25	13.44	105	198	Off Idle	64.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.89	14.77	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:9	34.08	2552	2.25	13.42	105	198	Off Idle	64.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.86	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:35:9	34.08	2557	2.25	13.42	106	198	Off Idle	64.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.89	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:9	34.08	2556	2.26	13.42	106	198	Off Idle	64	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.87	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:35:9	34.08	2556	2.26	13.42	105	198	Off Idle	63.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.89	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:0	34.08	2553	2.26	13.41	105	198	Off Idle	63.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.85	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:0	34.08	2543	2.26	13.41	105	198	Off Idle	63.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.83	14.94	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:0	34.08	2543	2.26	13.41	105	198	Off Idle	63.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.83	14.96	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:0	34.08	2540	2.26	13.41	105	198	Off Idle	63.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.88	15	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:0	34.08	2538	2.26	13.43	105	198	Off Idle	63.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.86	15.05	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:0	34.08	2538	2.26	13.43	105	198	Off Idle	63.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.87	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:1	34.08	2542	2.26	13.43	105	198	Off Idle	63.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.88	15.06	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:1	34.08	2545	2.26	13.43	105	198	Off Idle	63	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.9	15.03	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:1	34.08	2545	2.26	13.43	105	198	Off Idle	63	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.91	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:1	34.08	2558	2.25	13.41	105	198	Off Idle	63	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.91	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:1	34.08	2568	2.25	13.43	105	198	Off Idle	63	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.9	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:1	34.08	2570	2.25	13.43	105	198	Off Idle	63	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.88	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:1	34.08	2570	2.25	13.41	105	198	Off Idle	63.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.87	14.9	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:2	34.08	2568	2.25	13.41	105	198	Off Idle	63.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.86	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:2	34.08	2567	2.25	13.43	105	198	Off Idle	63.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.87	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:2	34.08	2563	2.25	13.43	106	198	Off Idle	63.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.92	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:2	34.08	2563	2.25	13.41	106	198	Off Idle	63.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.91	14.76	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:2	34.08	2556	2.25	13.42	105	198	Off Idle	63.1	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.9	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:2	34.08	2553	2.25	13.42	105	198	Off Idle	62.9	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.91	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:36:3	34.08	2553	2.25	13.41	105	198	Off Idle	62.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.91	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:3	34.08	2552	2.25	13.43	105	198	Off Idle	62.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.87	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:3	34.08	2554	2.25	13.42	105	198	Off Idle	62.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.89	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:3	34.08	2556	2.25	13.43	105	198	Off Idle	62.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.93	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:3	34.08	2568	2.25	13.42	105	198	Off Idle	62.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.93	15.04	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:3	34.08	2568	2.25	13.44	106	198	Off Idle	62.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.93	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:4	34.08	2572	2.25	13.42	106	198	Off Idle	62.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.95	15.17	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:4	34.08	2572	2.25	13.43	106	198	Off Idle	62.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.95	15.17	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:4	34.08	2577	2.25	13.42	106	198	Off Idle	62.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-5.97	15.14	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:4	34.08	2576	2.25	13.42	106	198	Off Idle	62.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.95	15.1	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:4	34.08	2575	2.25	13.41	105	198	Off Idle	62.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.95	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:4	34.08	2574	2.25	13.41	105	198	Off Idle	62.8	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.01	15.04	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:4	34.08	2567	2.25	13.41	105	198	Off Idle	62.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.01	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:5	34.08	2543	2.25	13.42	106	198	Off Idle	63.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:5	34.08	2554	2.25	13.42	106	198	Off Idle	63.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.02	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:5	34.08	2566	2.25	13.42	106	198	Off Idle	62.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.02	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:5	34.08	2572	2.25	13.42	106	198	Off Idle	62.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.05	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:5	34.08	2574	2.25	13.42	106	198	Off Idle	62.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.06	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:5	34.08	2574	2.24	13.42	105	198	Off Idle	62.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.04	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:6	34.08	2574	2.24	13.4	105	198	Off Idle	62.5	0	2	132	944 Turbo	0.23	Rich	1	14.6	-6.04	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:36:6	34.08	2578	2.24	13.41	105	198	Off Idle	62.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.06	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:6	34.08	2579	2.24	13.42	105	198	Off Idle	62.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.02	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:6	34.08	2583	2.24	13.42	105	198	Off Idle	62.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.02	14.95	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:6	34.08	2582	2.24	13.41	105	198	Off Idle	62	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.04	14.97	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:6	34.08	2580	2.24	13.41	105	198	Off Idle	61.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.08	15.01	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:6	34.08	2580	2.24	13.43	105	198	Off Idle	61.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.12	15.05	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:7	34.08	2582	2.24	13.41	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.12	15.09	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:36:7	34.08	2576	2.24	13.41	105	198	Off Idle	61.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.17	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:36:7	34.08	2576	2.24	13.41	105	198	Off Idle	61.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.15	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:36:7	34.08	2571	2.23	13.42	105	198	Off Idle	61.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.18	15.05	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:36:7	34.08	2568	2.23	13.43	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.24	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:36:7	34.08	2574	2.22	13.42	106	198	Off Idle	61.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.32	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:36:8	34.08	2576	2.22	13.42	106	198	Off Idle	61.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.37	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:36:8	34.08	2585	2.21	13.42	105	198	Off Idle	61.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.45	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:36:8	34.08	2588	2.21	13.42	105	198	Off Idle	61.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.54	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:36:8	34.08	2587	2.2	13.41	105	198	Off Idle	61.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.6	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:36:8	34.08	2587	2.19	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.7	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:36:8	34.08	2585	2.18	13.41	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.74	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:36:9	34.08	2583	2.17	13.41	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.77	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:36:9	34.08	2583	2.17	13.41	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.85	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:36:9	34.08	2580	2.16	13.42	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.92	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:36:9	34.08	2574	2.15	13.42	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.96	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:36:9	34.08	2572	2.14	13.43	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.03	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:36:9	34.08	2572	2.13	13.43	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.09	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:36:9	34.08	2576	2.12	13.44	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.12	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:0	34.08	2574	2.11	13.44	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.2	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:0	34.08	2574	2.1	13.44	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.24	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:0	34.08	2583	2.09	13.44	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.32	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:0	34.08	2588	2.08	13.43	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.38	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:0	34.08	2591	2.07	13.43	105	197	Off Idle	61.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.46	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:0	34.08	2591	2.06	13.43	105	197	Off Idle	61.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.52	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:1	34.08	2592	2.05	13.44	105	197	Off Idle	61.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.58	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:37:1	34.08	2588	2.05	13.44	105	198	Off Idle	61.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.64	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:37:1	34.08	2587	2.04	13.43	105	198	Off Idle	61.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.71	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:37:1	35.45	2597	2.03	13.43	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.79	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:37:1	35.45	2584	2.01	13.42	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.89	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:37:1	35.45	2582	2.01	13.42	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.92	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:37:1	35.45	2574	1.99	13.44	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:37:2	35.45	2574	1.98	13.43	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.04	15.13	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:2	35.45	2566	1.97	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.07	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:2	35.45	2571	1.97	13.44	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.15	15.15	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:2	35.45	2571	1.96	13.43	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.19	15.16	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:2	35.45	2572	1.94	13.43	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.2	15.16	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:2	35.45	2568	1.93	13.42	105	198	Off Idle	61.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.3	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:3	35.45	2583	1.92	13.43	105	198	Off Idle	61.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.34	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:3	35.45	2584	1.92	13.43	105	198	Off Idle	61.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.39	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:3	35.45	2598	1.91	13.43	106	198	Off Idle	61.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.46	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:3	35.45	2585	1.9	13.44	106	198	Off Idle	61.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.49	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:3	35.45	2584	1.9	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.51	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:3	35.45	2578	1.88	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.58	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:4	35.45	2572	1.87	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.63	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:4	35.45	2572	1.87	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.66	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:4	35.45	2572	1.86	13.42	106	198	Off Idle	61.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.75	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:4	35.45	2571	1.85	13.43	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.79	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:4	35.45	2594	1.84	13.44	106	197	Off Idle	61.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.85	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:4	35.45	2575	1.83	13.43	105	197	Off Idle	61.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.91	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:4	35.45	2575	1.83	13.43	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.94	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:37:5	35.45	2576	1.82	13.44	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.95	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:5	35.45	2579	1.81	13.43	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.96	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:5	35.45	2580	1.8	13.43	105	198	Off Idle	61.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.99	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:5	35.45	2575	1.8	13.44	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.99	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:5	35.45	2575	1.79	13.43	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.04	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:5	35.45	2552	1.79	13.44	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.09	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:6	35.45	2552	1.78	13.43	105	198	Off Idle	61.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.11	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:6	35.45	2572	1.78	13.43	105	198	Off Idle	61.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.1	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:6	35.45	2578	1.78	13.42	105	197	Off Idle	61.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.12	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:6	35.45	2578	1.77	13.42	106	197	Off Idle	61.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.14	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:6	35.45	2583	1.77	13.41	106	197	Off Idle	62	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.14	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:6	35.45	2582	1.77	13.41	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.14	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:37:6	35.45	2582	1.76	13.42	105	198	Off Idle	62	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.15	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:7	35.45	2576	1.76	13.42	105	198	Off Idle	61.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.18	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:7	35.45	2571	1.76	13.42	105	198	Off Idle	61.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.16	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:7	35.45	2564	1.76	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.16	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:7	35.45	2564	1.76	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.2	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:7	35.45	2554	1.75	13.42	106	198	Off Idle	61.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.22	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:7	35.45	2570	1.75	13.42	106	198	Off Idle	61.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.21	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:8	35.45	2570	1.75	13.43	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.25	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:8	35.45	2568	1.74	13.43	106	198	Off Idle	61.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.31	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:8	35.45	2568	1.74	13.42	106	198	Off Idle	61.8	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.32	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:8	35.45	2567	1.74	13.42	106	198	Off Idle	62	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.36	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:8	35.45	2565	1.73	13.44	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.44	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:8	35.45	2566	1.72	13.44	106	198	Off Idle	62.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.5	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:37:9	35.45	2569	1.71	13.43	106	197	Off Idle	62.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.56	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:37:9	35.45	2571	1.69	13.44	105	197	Off Idle	62.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.59	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:37:9	35.45	2566	1.68	13.45	105	197	Off Idle	62.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.74	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:37:9	35.45	2566	1.66	13.44	105	198	Full Load	62.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.84	14.84	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:9	35.45	2564	1.63	13.43	105	198	Idle	62.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.92	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:9	35.45	2564	1.62	13.44	105	198	Idle	62.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.99	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:37:9	35.45	2561	1.59	13.43	105	198	Idle	62.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.15	14.84	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:38:0	35.45	2548	1.56	13.44	106	198	Idle	62.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.2	14.83	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:38:0	35.45	2542	1.55	13.42	106	198	Idle	62.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.26	14.83	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:38:0	35.45	2538	1.54	13.42	106	197	Idle	63	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.33	14.85	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:0	35.45	2522	1.51	13.44	105	197	Idle	63	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.38	14.85	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:0	32.72	2455	1.5	13.43	105	197	Idle	63.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.39	14.85	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:0	27.27	2464	1.47	13.42	105	197	Idle	63.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.43	14.87	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:1	27.27	2464	1.46	13.44	105	197	Idle	63.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.46	14.88	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:38:1	21.81	2468	1.44	13.43	105	197	Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.48	14.91	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:1	21.81	2515	1.42	13.42	105	197	Idle	63.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.51	14.96	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:1	19.09	2515	1.4	13.42	105	197	Idle	63.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-10.53	14.99	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:1	19.09	2535	1.37	13.43	105	197	Idle	63.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-10.57	15.01	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:1	19.09	2564	1.36	13.43	105	197	Idle	63.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.58	15.02	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:1	19.09	2566	1.35	13.42	105	197	Idle	63.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-10.6	15.02	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:2	19.09	2570	1.35	13.44	105	197	Idle	63.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.63	15.01	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:2	19.09	2572	1.35	13.43	105	197	Idle	63.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.63	14.98	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:2	19.09	2566	1.35	13.42	105	197	Idle	63.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.62	14.97	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:2	19.09	2563	1.35	13.43	105	197	Idle	63.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.62	14.93	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:2	19.09	2549	1.35	13.43	105	197	Idle	63.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.6	14.87	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:2	19.09	2537	1.35	13.42	105	197	Idle	63.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.56	14.79	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:3	19.09	2534	1.35	13.43	105	197	Idle	63.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.53	14.73	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:3	19.09	2522	1.35	13.43	105	197	Idle	63	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.51	14.68	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:3	19.09	2516	1.35	13.44	105	197	Idle	62.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.47	14.65	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:3	19.09	2506	1.34	13.43	105	197	Idle	62.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.46	14.61	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:3	19.09	2518	1.34	13.42	105	198	Idle	62.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.43	14.59	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:3	19.09	2523	1.34	13.43	105	198	Idle	62.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.39	14.58	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:4	19.09	2530	1.35	13.43	105	198	Idle	62.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.39	14.57	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:4	19.09	2530	1.35	13.43	105	197	Idle	62.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.34	14.57	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:4	19.09	2537	1.35	13.43	105	197	Idle	62	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.31	14.58	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:4	19.09	2539	1.35	13.45	105	197	Idle	62.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.31	14.64	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:4	19.09	2542	1.35	13.43	105	198	Idle	62.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.3	14.77	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:4	19.09	2538	1.36	13.44	105	198	Idle	62.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.32	14.88	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:4	19.09	2538	1.36	13.42	105	198	Idle	62.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.32	14.99	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:5	19.09	2542	1.36	13.42	106	197	Idle	62.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.3	15.12	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:5	19.09	2524	1.36	13.42	106	197	Idle	62.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.3	15.24	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:5	19.09	2524	1.36	13.42	106	198	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	15.38	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:5	19.09	2506	1.36	13.42	105	198	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	15.53	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:5	19.09	2508	1.36	13.44	105	198	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	15.79	1.08	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:5	19.09	2505	1.36	13.42	105	197	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	15.97	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:6	19.09	2506	1.36	13.42	106	197	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	16.2	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:6	19.09	2505	1.36	13.43	106	197	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	16.52	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:6	19.09	2506	1.36	13.43	106	198	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	16.9	1.15	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:6	19.09	2506	1.36	13.43	105	198	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	17.33	1.18	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:6	19.09	2510	1.36	13.43	105	198	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	17.77	1.21	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:6	19.09	2511	1.36	13.43	105	197	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	18.41	1.25	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:6	19.09	2513	1.36	13.43	106	197	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	18.82	1.28	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:7	19.09	2512	1.35	13.43	106	197	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	19.21	1.31	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:7	19.09	2510	1.35	13.43	106	197	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	19.57	1.33	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:7	19.09	2510	1.35	13.44	105	197	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	19.86	1.35	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:7	19.09	2503	1.35	13.43	105	197	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.08	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:7	19.09	2504	1.35	13.43	105	198	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:7	19.09	2501	1.35	13.43	105	198	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:8	19.09	2494	1.35	13.43	105	198	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:8	19.09	2491	1.34	13.43	105	197	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:8	19.09	2490	1.34	13.42	105	197	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:8	19.09	2486	1.34	13.42	105	197	Idle	64.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:8	19.09	2486	1.34	13.43	106	197	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:8	19.09	2486	1.34	13.43	106	197	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:9	19.09	2486	1.34	13.43	106	197	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:9	19.09	2488	1.33	13.43	105	197	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:9	19.09	2487	1.33	13.43	105	197	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:9	19.09	2487	1.33	13.43	105	197	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:9	19.09	2486	1.33	13.43	105	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:9	19.09	2486	1.33	13.44	105	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:38:9	19.09	2484	1.33	13.43	105	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:0	19.09	2480	1.32	13.44	105	197	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:39:0	19.09	2480	1.32	13.44	105	197	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:0	19.09	2476	1.32	13.43	105	197	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:0	19.09	2476	1.32	13.42	105	197	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:0	19.09	2473	1.32	13.42	105	197	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:0	19.09	2469	1.31	13.43	105	197	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:1	19.09	2468	1.31	13.42	105	197	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:1	19.09	2463	1.31	13.43	105	197	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:1	19.09	2463	1.31	13.44	105	197	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:1	19.09	2462	1.31	13.44	105	197	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:1	19.09	2460	1.31	13.43	105	197	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:1	19.09	2460	1.31	13.44	105	197	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:1	19.09	2458	1.31	13.42	105	197	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:2	19.09	2438	1.3	13.43	105	197	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:2	17.72	2457	1.3	13.42	105	197	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:2	17.72	2457	1.3	13.43	105	198	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:2	17.72	2456	1.3	13.43	105	198	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:2	17.72	2458	1.3	13.44	105	198	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:2	17.72	2458	1.3	13.43	105	197	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:3	17.72	2458	1.3	13.44	105	197	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:3	17.72	2454	1.3	13.43	105	197	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:3	17.72	2448	1.3	13.43	105	197	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:3	17.72	2448	1.3	13.42	105	197	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:3	17.72	2444	1.3	13.44	105	197	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:3	17.72	2432	1.3	13.42	105	197	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:4	17.72	2439	1.29	13.41	105	197	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:4	17.72	2439	1.29	13.42	105	197	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:4	17.72	2438	1.29	13.44	105	197	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:4	17.72	2458	1.29	13.44	105	197	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:4	17.72	2458	1.29	13.44	105	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:4	19.09	2425	1.29	13.44	105	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:4	17.72	2448	1.28	13.44	105	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:5	17.72	2448	1.28	13.42	105	197	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:5	17.72	2450	1.28	13.44	105	197	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:5	17.72	2458	1.27	13.44	105	197	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:5	17.72	2458	1.27	13.43	105	197	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:5	17.72	2444	1.27	13.43	105	197	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:6	17.72	2423	1.27	13.43	105	197	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:6	17.72	2435	1.26	13.43	105	197	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:6	17.72	2435	1.26	13.42	105	197	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:6	17.72	2432	1.26	13.43	105	197	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:6	17.72	2431	1.25	13.43	105	197	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:6	17.72	2430	1.25	13.43	105	197	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:6	17.72	2426	1.25	13.44	105	197	Full Load	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:6	17.72	2422	1.25	13.43	105	197	Off Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:7	17.72	2293	1.25	13.42	105	197	Off Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:7	17.72	2293	1.25	13.43	105	197	Off Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:18:39:7	9.54	2429	1.25	13.42	105	197	Off Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:18:39:7	12.27	2429	1.25	13.42	105	197	Off Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:18:39:7	14.99	2428	1.25	13.43	105	197	Off Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:7	14.99	2428	1.26	13.41	105	197	Off Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:8	17.72	2413	1.26	13.41	105	197	Off Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:8	17.72	2434	1.26	13.43	105	197	Off Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:8	20.45	2435	1.27	13.42	105	197	Off Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:8	23.18	2440	1.27	13.44	105	197	Off Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:8	23.18	2440	1.27	13.44	105	197	Off Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:8	25.9	2440	1.28	13.44	105	197	Off Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:9	28.63	2446	1.28	13.43	105	197	Off Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:9	28.63	2451	1.29	13.43	105	198	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:39:9	31.36	2468	1.3	13.42	105	198	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:18:39:9	34.08	2468	1.31	13.43	105	198	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:9	34.08	2446	1.31	13.42	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:9	35.45	2418	1.32	13.43	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:39:9	35.45	2418	1.33	13.42	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:40:0	35.45	2414	1.33	13.42	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:40:0	35.45	2412	1.34	13.41	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:40:0	35.45	2412	1.34	13.42	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:40:0	35.45	2412	1.35	13.41	105	197	Off Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:40:0	35.45	2396	1.36	13.43	105	197	Off Idle	70	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:40:0	35.45	2396	1.36	13.42	105	197	Off Idle	70	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:40:1	35.45	2412	1.37	13.43	105	197	Off Idle	70	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:18:40:1	35.45	2411	1.37	13.41	105	197	Off Idle	70	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:1	35.45	2419	1.38	13.43	106	197	Off Idle	70	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:1	35.45	2419	1.39	13.42	106	197	Off Idle	70	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:1	35.45	2399	1.39	13.44	106	197	Off Idle	70.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:1	35.45	2401	1.4	13.43	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:1	35.45	2401	1.4	13.44	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.21	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:2	35.45	2399	1.4	13.43	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.2	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:2	35.45	2400	1.41	13.43	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:2	35.45	2398	1.41	13.42	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.17	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:2	35.45	2398	1.42	13.41	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.14	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:2	35.45	2397	1.42	13.42	105	197	Off Idle	71	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.12	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:2	35.45	2397	1.43	13.43	105	198	Off Idle	71.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:40:3	35.45	2398	1.44	13.43	105	198	Off Idle	71.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:40:3	35.45	2399	1.45	13.44	105	197	Off Idle	71.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:40:3	35.45	2398	1.45	13.43	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.98	20.04	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:40:3	35.45	2396	1.45	13.43	105	197	Off Idle	71.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.97	20.04	1.36	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:40:3	35.45	2397	1.46	13.41	105	197	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.93	20.04	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:40:3	35.45	2398	1.47	13.42	105	197	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.9	20.04	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:40:4	35.45	2398	1.47	13.43	105	197	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.9	20.04	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:40:4	35.45	2396	1.48	13.43	105	197	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.87	19.99	1.36	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:40:4	35.45	2388	1.49	13.42	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.85	19.89	1.36	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:40:4	35.45	2386	1.49	13.42	106	197	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.81	19.68	1.34	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:40:4	35.45	2384	1.5	13.41	106	197	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.77	19.58	1.33	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:40:4	35.45	2389	1.51	13.41	106	198	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.73	19.27	1.31	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:40:4	35.45	2390	1.51	13.41	105	198	Off Idle	72.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.68	19.2	1.31	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:40:5	35.45	2392	1.52	13.43	105	198	Off Idle	72.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.63	19.06	1.3	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:40:5	35.45	2400	1.53	13.42	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.6	18.79	1.28	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:40:5	35.45	2407	1.54	13.41	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.58	18.35	1.25	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:5	35.45	2408	1.54	13.43	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.53	18.06	1.23	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:5	35.45	2410	1.55	13.42	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.55	17.79	1.21	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:5	35.45	2410	1.56	13.43	105	197	Off Idle	71.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.53	17.57	1.2	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:6	35.45	2410	1.57	13.44	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	17.38	1.18	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:6	35.45	2413	1.57	13.43	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	17.12	1.17	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:6	35.45	2415	1.58	13.43	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.43	16.99	1.16	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:6	35.45	2415	1.59	13.43	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.42	16.86	1.15	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:6	35.45	2415	1.59	13.42	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.39	16.75	1.14	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:6	35.45	2387	1.61	13.44	105	197	Off Idle	71.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.38	16.58	1.13	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:6	35.45	2387	1.61	13.43	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.37	16.49	1.12	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:40:7	35.45	2392	1.62	13.43	105	197	Off Idle	71	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.35	16.45	1.12	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:7	35.45	2370	1.62	13.43	105	197	Off Idle	70.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.3	16.36	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:7	35.45	2370	1.63	13.43	105	197	Off Idle	70.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.3	16.29	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:7	34.08	2363	1.63	13.41	106	197	Off Idle	71	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.25	16.22	1.1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:7	34.08	2354	1.64	13.42	106	197	Off Idle	71.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.2	16.11	1.1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:7	34.08	2369	1.64	13.43	106	197	Off Idle	71.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.16	16.04	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:8	34.08	2369	1.64	13.42	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.18	16.01	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:8	34.08	2376	1.65	13.43	105	197	Off Idle	71.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.16	15.93	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:40:8	34.08	2378	1.65	13.43	105	197	Off Idle	72.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.14	15.85	1.08	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:8	34.08	2378	1.66	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.14	15.83	1.08	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:8	34.08	2390	1.66	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.12	15.78	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:8	34.08	2395	1.66	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.1	15.74	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:9	34.08	2395	1.67	13.41	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.09	15.68	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:9	34.08	2394	1.67	13.42	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.07	15.64	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:9	34.08	2391	1.68	13.41	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.06	15.6	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:9	34.08	2382	1.68	13.41	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.04	15.56	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:9	34.08	2371	1.68	13.42	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.99	15.48	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:9	34.08	2371	1.69	13.42	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.96	15.43	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:40:9	34.08	2365	1.69	13.41	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.93	15.37	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:0	34.08	2366	1.69	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.89	15.34	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:0	34.08	2366	1.7	13.41	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.88	15.29	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:0	34.08	2366	1.7	13.41	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.83	15.23	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:0	34.08	2374	1.71	13.42	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.77	15.2	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:0	34.08	2379	1.71	13.41	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.77	15.19	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:0	34.08	2379	1.72	13.41	105	197	Off Idle	73.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.76	15.16	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:1	34.08	2383	1.72	13.42	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.73	15.14	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:1	34.08	2388	1.72	13.42	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.72	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:1	34.08	2388	1.73	13.41	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.73	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:1	34.08	2386	1.73	13.41	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.69	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:1	34.08	2389	1.74	13.43	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.67	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:1	34.08	2387	1.74	13.42	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.68	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:1	34.08	2388	1.74	13.43	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.65	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:2	34.08	2387	1.75	13.43	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.65	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:2	34.08	2379	1.75	13.43	105	197	Off Idle	73.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.62	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:2	34.08	2378	1.75	13.43	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.59	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:2	34.08	2398	1.75	13.43	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.54	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:2	34.08	2379	1.76	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.54	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:2	34.08	2379	1.76	13.44	105	197	Off Idle	73	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.54	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:3	34.08	2372	1.76	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.55	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:3	34.08	2381	1.76	13.43	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.55	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:3	34.08	2380	1.77	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.57	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:3	34.08	2380	1.77	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.52	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:3	34.08	2382	1.77	13.43	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.49	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:3	34.08	2382	1.77	13.43	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.46	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:4	34.08	2378	1.78	13.41	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.44	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:4	34.08	2379	1.78	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.42	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:4	34.08	2375	1.78	13.41	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.43	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:4	34.08	2374	1.78	13.42	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.41	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:4	34.08	2373	1.79	13.42	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.42	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:4	34.08	2373	1.79	13.42	105	197	Off Idle	73	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.41	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:4	34.08	2369	1.79	13.42	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.4	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:5	34.08	2379	1.79	13.42	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.41	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:5	34.08	2379	1.79	13.43	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.41	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:5	34.08	2382	1.79	13.43	105	197	Off Idle	73.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.41	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:5	34.08	2383	1.79	13.44	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-8.38	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:5	34.08	2384	1.79	13.43	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.4	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:5	34.08	2384	1.8	13.42	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.37	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:6	34.08	2383	1.8	13.44	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.36	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:6	34.08	2381	1.8	13.43	105	197	Off Idle	73.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.38	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:6	34.08	2378	1.8	13.42	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.35	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:6	34.08	2378	1.8	13.43	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.33	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:6	34.08	2378	1.8	13.43	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.33	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:6	34.08	2378	1.8	13.41	105	197	Off Idle	73.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.31	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:6	34.08	2376	1.8	13.43	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.29	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:7	34.08	2376	1.8	13.43	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.3	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:7	34.08	2384	1.8	13.42	105	197	Off Idle	73.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.31	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:41:7	34.08	2377	1.8	13.43	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.3	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:7	34.08	2379	1.8	13.44	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.33	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:7	34.08	2379	1.8	13.44	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.31	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:7	34.08	2364	1.8	13.43	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.28	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:41:8	34.08	2364	1.8	13.42	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.26	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:8	34.08	2384	1.81	13.44	105	197	Off Idle	73.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.24	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:8	34.08	2382	1.81	13.44	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.21	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:8	34.08	2380	1.81	13.43	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.2	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:41:8	34.08	2379	1.82	13.42	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.14	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:41:8	34.08	2378	1.83	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.08	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:41:9	34.08	2378	1.83	13.43	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.03	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:41:9	34.08	2378	1.84	13.41	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.97	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:41:9	34.08	2378	1.85	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.89	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:41:9	34.08	2382	1.85	13.44	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.82	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:41:9	34.08	2385	1.86	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.79	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:41:9	34.08	2385	1.87	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:41:9	34.08	2387	1.88	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:0	34.08	2387	1.89	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:0	34.08	2387	1.89	13.42	105	197	Off Idle	73	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:0	34.08	2386	1.9	13.42	106	197	Off Idle	72.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:0	34.08	2388	1.91	13.42	106	197	Off Idle	72.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.57	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:0	34.08	2405	1.92	13.42	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.55	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:0	34.08	2405	1.92	13.42	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.51	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:1	34.08	2384	1.93	13.43	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.47	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:1	34.08	2385	1.94	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.43	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:1	34.08	2384	1.94	13.43	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.41	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:1	34.08	2376	1.95	13.43	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.39	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:1	34.08	2382	1.95	13.42	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.38	15.19	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:1	34.08	2379	1.95	13.43	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.38	15.21	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:1	34.08	2379	1.96	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.39	15.21	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:2	34.08	2381	1.96	13.43	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.37	15.21	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:2	34.08	2381	1.96	13.42	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.41	15.21	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:2	34.08	2382	1.96	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.37	15.19	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:2	34.08	2384	1.96	13.41	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.36	15.19	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:2	34.08	2385	1.96	13.41	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.34	15.18	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:2	34.08	2383	1.96	13.41	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.31	15.14	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:3	34.08	2383	1.96	13.41	105	197	Off Idle	73	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.31	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:3	34.08	2386	1.96	13.41	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.31	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:3	34.08	2390	1.96	13.42	106	197	Off Idle	73.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.28	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:3	34.08	2392	1.96	13.43	106	197	Off Idle	73.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.3	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:3	34.08	2392	1.96	13.43	106	197	Off Idle	73.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.31	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:3	34.08	2392	1.96	13.43	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.31	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:4	34.08	2392	1.96	13.42	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.37	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:4	34.08	2390	1.96	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.36	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:4	34.08	2385	1.96	13.44	105	197	Off Idle	73	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.32	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:4	34.08	2386	1.96	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.32	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:4	34.08	2386	1.96	13.45	105	197	Off Idle	73	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.32	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:4	34.08	2386	1.96	13.44	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.31	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:4	34.08	2384	1.96	13.43	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.31	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:5	34.08	2383	1.96	13.44	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.33	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:5	34.08	2381	1.96	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.36	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:5	34.08	2379	1.96	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.34	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:5	34.08	2384	1.96	13.42	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.32	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:5	34.08	2384	1.96	13.42	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.34	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:5	34.08	2388	1.96	13.41	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.28	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:6	34.08	2397	1.97	13.42	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.27	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:6	34.08	2397	1.97	13.43	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.28	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:6	34.08	2398	1.97	13.41	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.29	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:42:6	34.08	2401	1.97	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.31	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:6	34.08	2400	1.97	13.44	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.35	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:6	34.08	2400	1.97	13.44	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.35	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:6	34.08	2418	1.97	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.34	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:7	34.08	2397	1.97	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.37	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:7	34.08	2396	1.97	13.41	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.35	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:42:7	34.08	2394	1.97	13.41	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.32	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:7	34.08	2382	1.97	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.29	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:7	34.08	2392	1.97	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.3	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:7	34.08	2392	1.97	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.3	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:42:8	34.08	2393	1.97	13.41	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.31	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:8	34.08	2392	1.97	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.3	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:8	34.08	2392	1.97	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.32	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:8	34.08	2391	1.97	13.41	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.35	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:8	34.08	2390	1.97	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.35	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:8	34.08	2392	1.97	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.37	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:9	34.08	2398	1.96	13.41	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.38	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:9	34.08	2397	1.96	13.41	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.39	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:9	34.08	2397	1.96	13.41	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.37	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:9	34.08	2398	1.96	13.41	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.37	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:9	34.08	2395	1.96	13.41	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.34	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:9	34.08	2395	1.96	13.43	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.31	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:42:9	34.08	2390	1.96	13.42	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.31	14.72	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:43:0	34.08	2392	1.96	13.42	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.28	14.67	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:0	34.08	2391	1.97	13.43	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.27	14.64	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:0	34.08	2397	1.97	13.42	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.25	14.63	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:0	34.08	2401	1.97	13.43	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.26	14.63	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:0	34.08	2403	1.98	13.44	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.22	14.65	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:0	34.08	2403	1.98	13.44	105	197	Off Idle	72.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.18	14.67	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:1	34.08	2406	1.98	13.42	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.16	14.7	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:1	34.08	2406	1.99	13.42	105	197	Off Idle	72	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.13	14.72	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:1	34.08	2407	1.99	13.42	105	197	Off Idle	71.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.06	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:1	34.08	2409	2	13.42	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.04	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:1	34.08	2411	2	13.43	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.01	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:1	34.08	2420	2	13.43	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.99	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:1	34.08	2408	2.01	13.43	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:2	34.08	2404	2.01	13.43	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.01	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:2	34.08	2401	2.02	13.43	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.01	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:2	34.08	2390	2.02	13.43	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.98	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:2	34.08	2397	2.02	13.43	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.97	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:2	34.08	2397	2.03	13.43	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.96	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:2	34.08	2394	2.03	13.43	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.92	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:3	34.08	2389	2.03	13.43	105	197	Off Idle	71.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.91	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:3	34.08	2386	2.03	13.43	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.91	15.19	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:3	34.08	2388	2.03	13.43	105	197	Off Idle	71.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.92	15.21	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:3	34.08	2394	2.03	13.43	105	197	Off Idle	71.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.93	15.22	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:3	34.08	2401	2.03	13.43	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.95	15.2	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:3	34.08	2404	2.04	13.43	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.96	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:4	34.08	2411	2.03	13.44	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.91	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:4	34.08	2414	2.03	13.44	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.94	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:4	34.08	2414	2.03	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.94	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:4	34.08	2414	2.03	13.44	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.92	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:4	34.08	2430	2.03	13.43	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.94	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:4	34.08	2418	2.03	13.42	105	197	Off Idle	71.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.96	14.9	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:4	34.08	2406	2.03	13.42	105	197	Off Idle	71.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.93	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:5	34.08	2406	2.03	13.42	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.9	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:5	34.08	2411	2.03	13.42	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.87	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:5	34.08	2411	2.03	13.43	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.9	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:43:5	34.08	2411	2.03	13.41	105	197	Off Idle	71.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.86	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:5	34.08	2412	2.03	13.41	105	197	Off Idle	71.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.9	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:5	34.08	2414	2.03	13.42	105	197	Off Idle	71.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.93	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:6	34.08	2419	2.03	13.39	105	197	Off Idle	71.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.96	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:6	34.08	2420	2.03	13.41	105	197	Off Idle	71.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.96	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:6	34.08	2422	2.03	13.43	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.99	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:6	34.08	2419	2.03	13.42	105	197	Off Idle	71	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.01	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:6	34.08	2419	2.03	13.43	105	197	Off Idle	71	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.99	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:6	34.08	2395	2.03	13.42	105	197	Off Idle	71	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.97	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:43:6	34.08	2404	2.03	13.43	105	197	Off Idle	71	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.96	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:7	34.08	2408	2.03	13.43	105	197	Off Idle	71	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.99	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:7	34.08	2405	2.03	13.43	105	197	Off Idle	71	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:7	34.08	2421	2.03	13.42	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.01	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:7	34.08	2421	2.03	13.44	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:43:7	34.08	2404	2.03	13.42	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.04	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:7	34.08	2404	2.03	13.44	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.06	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:8	34.08	2410	2.02	13.44	105	197	Off Idle	71	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.1	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:8	34.08	2414	2.02	13.44	105	197	Off Idle	70.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.09	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:8	34.08	2418	2.02	13.43	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.14	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:8	34.08	2417	2.02	13.44	105	197	Off Idle	71	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.16	15.15	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:8	34.08	2414	2.01	13.42	105	197	Off Idle	71	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.18	15.15	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:43:8	34.08	2414	2.01	13.4	105	197	Off Idle	71	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.19	15.12	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:43:9	34.08	2403	2.01	13.41	105	197	Off Idle	71	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.19	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:43:9	34.08	2402	2	13.41	105	197	Off Idle	71	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.21	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:43:9	34.08	2406	2	13.41	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.25	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:43:9	34.08	2406	2	13.42	105	197	Off Idle	71.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.25	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:43:9	34.08	2407	2	13.42	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.29	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:43:9	34.08	2410	1.99	13.44	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.3	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:43:9	34.08	2412	1.99	13.43	105	197	Off Idle	71.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.33	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:44:0	34.08	2420	1.98	13.44	105	197	Off Idle	71.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.39	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:44:0	34.08	2420	1.98	13.44	105	197	Off Idle	71.1	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.42	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:44:0	34.08	2420	1.98	13.43	105	197	Off Idle	71.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.44	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:44:0	34.08	2420	1.97	13.41	105	197	Off Idle	71.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.46	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:44:0	34.08	2422	1.97	13.41	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.45	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:44:0	34.08	2412	1.97	13.42	105	197	Off Idle	71.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.48	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:44:1	34.08	2417	1.96	13.41	105	197	Off Idle	71.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.51	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:44:1	34.08	2418	1.96	13.42	105	197	Off Idle	71.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.54	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:44:1	34.08	2418	1.96	13.43	105	197	Off Idle	71.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.58	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:44:1	34.08	2415	1.95	13.43	105	197	Off Idle	71	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.64	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:44:1	34.08	2413	1.94	13.44	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.66	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:44:1	34.08	2414	1.94	13.43	105	197	Off Idle	70.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.72	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:44:1	34.08	2412	1.93	13.44	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.71	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:44:2	34.08	2401	1.93	13.43	105	197	Off Idle	70.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.77	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:44:2	34.08	2410	1.92	13.43	105	197	Off Idle	70.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.81	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:44:2	34.08	2410	1.91	13.43	105	197	Off Idle	70.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.85	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:44:2	34.08	2407	1.91	13.43	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.89	15.13	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:44:2	34.08	2408	1.9	13.42	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.94	15.14	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:44:2	34.08	2416	1.89	13.41	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8	15.16	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:44:3	34.08	2410	1.89	13.41	105	197	Off Idle	70.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.04	15.17	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:44:3	34.08	2412	1.88	13.43	105	197	Off Idle	70.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.11	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:44:3	34.08	2412	1.87	13.42	105	197	Off Idle	70.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.17	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:44:3	34.08	2414	1.86	13.43	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.22	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:44:3	34.08	2414	1.85	13.43	105	197	Off Idle	70.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.28	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:44:3	34.08	2414	1.84	13.42	105	197	Off Idle	71	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.35	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:44:4	34.08	2410	1.83	13.42	105	197	Off Idle	71	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.44	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:44:4	34.08	2409	1.82	13.42	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.52	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:44:4	34.08	2408	1.8	13.42	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.59	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:4	34.08	2394	1.79	13.42	105	197	Off Idle	70.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.68	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:44:4	34.08	2402	1.78	13.41	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.74	14.76	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:4	34.08	2396	1.76	13.42	105	197	Off Idle	71	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.8	14.75	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:4	34.08	2396	1.75	13.41	105	197	Off Idle	71	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.88	14.74	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:5	34.08	2396	1.74	13.41	105	197	Off Idle	71	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.94	14.74	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:5	34.08	2397	1.73	13.41	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.01	14.75	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:5	34.08	2396	1.72	13.42	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.06	14.75	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:5	34.08	2407	1.7	13.4	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.13	14.76	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:5	34.08	2403	1.69	13.4	105	197	Off Idle	71.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.14	14.78	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:5	34.08	2404	1.68	13.41	105	197	Off Idle	71.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.2	14.8	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:6	34.08	2410	1.67	13.42	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.22	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:6	34.08	2390	1.66	13.43	105	197	Off Idle	71.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.28	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:6	34.08	2390	1.65	13.43	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.3	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:6	34.08	2411	1.64	13.44	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.31	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:6	34.08	2416	1.63	13.44	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.34	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:6	34.08	2416	1.63	13.43	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.36	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:6	34.08	2426	1.62	13.43	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.36	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:7	35.45	2431	1.61	13.44	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.41	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:7	35.45	2410	1.61	13.43	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.43	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:7	35.45	2401	1.6	13.43	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.44	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:7	35.45	2392	1.6	13.43	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:44:7	35.45	2399	1.59	13.43	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.51	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:7	35.45	2398	1.59	13.42	105	197	Off Idle	71.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.54	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:8	35.45	2392	1.58	13.42	105	197	Off Idle	71.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.55	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:8	35.45	2392	1.58	13.41	105	197	Off Idle	71.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:8	35.45	2389	1.58	13.42	105	197	Off Idle	71.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:8	35.45	2389	1.57	13.43	105	197	Off Idle	71.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.59	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:8	35.45	2392	1.57	13.43	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.63	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:8	35.45	2395	1.56	13.43	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.66	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:9	35.45	2396	1.56	13.43	105	197	Off Idle	71.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.66	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:9	35.45	2396	1.56	13.43	105	197	Off Idle	71.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.71	15.14	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:9	35.45	2405	1.55	13.44	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.71	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:44:9	35.45	2401	1.55	13.44	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.71	15.14	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:44:9	35.45	2401	1.55	13.44	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.71	15.15	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:44:9	35.45	2398	1.54	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.75	15.15	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:44:9	35.45	2395	1.54	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.7	15.15	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:0	35.45	2393	1.53	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.72	15.14	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:0	35.45	2388	1.53	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.74	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:0	35.45	2385	1.53	13.43	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.71	15.12	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:0	35.45	2384	1.52	13.44	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.73	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:0	35.45	2383	1.52	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.75	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:0	35.45	2383	1.52	13.43	105	197	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.75	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:1	35.45	2386	1.51	13.42	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.75	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:1	35.45	2387	1.51	13.41	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.78	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:1	35.45	2387	1.51	13.41	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.77	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:1	35.45	2387	1.51	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.79	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:1	35.45	2386	1.51	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.78	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:1	35.45	2386	1.51	13.43	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.77	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:1	35.45	2386	1.51	13.43	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.78	15.05	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:2	35.45	2386	1.51	13.44	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.8	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:2	35.45	2389	1.5	13.43	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.79	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:2	35.45	2388	1.5	13.43	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.79	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:2	35.45	2387	1.5	13.43	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.8	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:2	35.45	2384	1.5	13.42	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.81	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:2	35.45	2383	1.5	13.41	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.81	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:3	35.45	2383	1.5	13.43	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.82	14.92	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:3	35.45	2383	1.5	13.43	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.84	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:3	35.45	2379	1.5	13.43	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.83	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:3	35.45	2376	1.5	13.42	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.83	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:45:3	35.45	2377	1.5	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.84	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:3	35.45	2378	1.5	13.42	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.82	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:4	35.45	2378	1.5	13.42	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.83	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:4	35.45	2379	1.49	13.44	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.87	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:4	35.45	2379	1.49	13.45	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.87	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:4	35.45	2379	1.49	13.44	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.87	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:4	35.45	2382	1.49	13.43	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.88	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:4	35.45	2382	1.49	13.42	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.85	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:4	35.45	2382	1.49	13.42	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.85	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:5	35.45	2380	1.49	13.41	105	197	Off Idle	73	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.86	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:5	35.45	2380	1.49	13.42	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.86	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:5	35.45	2374	1.48	13.42	105	197	Off Idle	73	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.85	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:5	35.45	2375	1.48	13.41	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.86	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:5	35.45	2376	1.48	13.41	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.87	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:5	35.45	2376	1.48	13.42	105	197	Off Idle	72.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.86	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:6	35.45	2375	1.48	13.42	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.87	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:6	35.45	2369	1.48	13.42	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.86	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:6	35.45	2368	1.48	13.44	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.86	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:6	35.45	2364	1.47	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.87	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:6	35.45	2363	1.47	13.43	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.87	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:6	35.45	2362	1.47	13.44	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.87	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:6	35.45	2362	1.47	13.42	105	197	Off Idle	73.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.9	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:7	35.45	2360	1.47	13.41	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.9	15.13	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:7	35.45	2360	1.47	13.42	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.87	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:7	35.45	2359	1.47	13.42	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.87	15.1	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:45:7	35.45	2359	1.47	13.4	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.89	15.09	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:18:45:7	35.45	2359	1.47	13.42	105	197	Off Idle	73.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.87	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:7	35.45	2357	1.47	13.42	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.86	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:8	35.45	2360	1.46	13.42	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.87	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:8	35.45	2360	1.46	13.42	105	197	Off Idle	73.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.88	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:8	35.45	2365	1.46	13.41	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.88	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:8	35.45	2365	1.46	13.41	105	197	Off Idle	74	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.87	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:8	35.45	2368	1.46	13.41	105	197	Off Idle	74	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.89	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:8	35.45	2372	1.46	13.41	105	197	Off Idle	74	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.89	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:9	35.45	2375	1.46	13.41	105	197	Off Idle	74	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.91	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:9	35.45	2376	1.46	13.41	105	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.87	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:9	35.45	2378	1.46	13.41	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.88	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:9	35.45	2378	1.46	13.41	105	197	Off Idle	73.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.9	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:9	35.45	2378	1.46	13.43	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.88	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:9	35.45	2382	1.46	13.42	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.89	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:45:9	35.45	2378	1.46	13.43	105	197	Off Idle	73.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.89	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:0	35.45	2377	1.46	13.43	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.89	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:0	35.45	2376	1.47	13.42	105	197	Off Idle	73.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.89	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:0	35.45	2373	1.47	13.41	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.87	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:0	35.45	2372	1.47	13.41	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.85	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:0	35.45	2372	1.47	13.4	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.87	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:0	35.45	2368	1.47	13.41	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.84	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:1	35.45	2360	1.47	13.41	105	197	Off Idle	73.4	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.84	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:1	35.45	2364	1.48	13.41	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.84	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:1	35.45	2356	1.48	13.41	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.83	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:1	35.45	2356	1.48	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.83	15.1	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:1	35.45	2351	1.48	13.44	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.82	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:1	35.45	2351	1.48	13.44	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.81	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:1	35.45	2350	1.49	13.43	105	197	Off Idle	73.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.77	15.13	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:2	35.45	2350	1.49	13.44	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.75	15.13	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:18:46:2	35.45	2346	1.49	13.42	105	197	Off Idle	73.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.72	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:2	35.45	2335	1.5	13.42	105	197	Off Idle	74	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.67	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:2	35.45	2342	1.5	13.42	105	197	Off Idle	74.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.68	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:46:2	35.45	2341	1.51	13.42	105	197	Off Idle	74.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.66	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:2	35.45	2340	1.51	13.43	105	197	Off Idle	74.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.63	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:3	35.45	2344	1.51	13.43	105	197	Off Idle	74.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.64	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:3	35.45	2346	1.51	13.42	105	197	Off Idle	74.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.65	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:3	35.45	2346	1.51	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.63	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:3	35.45	2346	1.51	13.43	105	197	Off Idle	74.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.61	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:3	35.45	2347	1.52	13.43	105	197	Off Idle	74.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.62	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:3	35.45	2359	1.52	13.43	105	197	Off Idle	74.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.64	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:4	35.45	2353	1.52	13.44	105	197	Off Idle	74.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.64	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:4	35.45	2355	1.52	13.43	105	197	Off Idle	74.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.66	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:4	35.45	2356	1.52	13.43	105	197	Off Idle	74.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.67	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:4	35.45	2357	1.52	13.43	105	197	Off Idle	74.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.67	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:4	35.45	2358	1.52	13.44	105	197	Off Idle	74.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.67	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:4	35.45	2356	1.52	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.69	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:4	35.45	2354	1.52	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.67	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:5	35.45	2352	1.52	13.45	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.66	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:5	35.45	2352	1.52	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.68	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:5	35.45	2350	1.52	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.65	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:5	35.45	2346	1.52	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.63	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:5	35.45	2343	1.52	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.62	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:5	35.45	2343	1.52	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.59	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:6	35.45	2341	1.52	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.61	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:6	35.45	2342	1.52	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.6	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:6	35.45	2342	1.52	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.58	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:6	35.45	2341	1.52	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.63	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:6	35.45	2342	1.52	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.6	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:6	35.45	2342	1.52	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.56	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:6	35.45	2342	1.52	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.57	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:7	35.45	2337	1.52	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.6	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:7	35.45	2337	1.52	13.43	105	197	Off Idle	74.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.57	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:7	35.45	2334	1.52	13.42	105	197	Off Idle	74.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.58	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:7	35.45	2334	1.52	13.42	105	197	Off Idle	74.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.59	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:7	35.45	2334	1.52	13.42	105	197	Off Idle	75	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.57	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:7	35.45	2328	1.52	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.62	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:8	35.45	2338	1.52	13.41	105	197	Off Idle	75.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.63	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:8	35.45	2335	1.52	13.44	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.61	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:8	35.45	2334	1.52	13.42	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.6	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:8	35.45	2342	1.52	13.41	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.6	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:8	35.45	2336	1.52	13.42	105	197	Off Idle	75.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.59	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:8	35.45	2336	1.52	13.43	105	197	Off Idle	75.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.61	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:9	35.45	2336	1.52	13.42	105	197	Off Idle	75.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.63	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:9	35.45	2335	1.52	13.42	105	197	Off Idle	75.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.66	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:9	35.45	2333	1.52	13.42	105	197	Off Idle	75.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.64	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:9	35.45	2333	1.52	13.42	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.66	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:9	35.45	2330	1.52	13.42	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.65	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:9	35.45	2326	1.52	13.42	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.65	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:46:9	35.45	2324	1.52	13.41	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.63	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:0	35.45	2324	1.52	13.41	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.61	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:0	35.45	2324	1.52	13.43	105	197	Off Idle	75.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.59	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:0	35.45	2318	1.52	13.42	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.6	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:0	35.45	2329	1.51	13.44	105	197	Off Idle	76	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.59	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:0	35.45	2329	1.51	13.44	105	197	Off Idle	76	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.61	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:0	35.45	2322	1.51	13.43	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.64	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:1	35.45	2323	1.51	13.42	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.64	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:1	35.45	2326	1.51	13.41	105	197	Off Idle	76	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.63	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:1	35.45	2328	1.51	13.41	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.66	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:1	35.45	2345	1.51	13.41	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.66	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:1	35.45	2321	1.51	13.42	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.64	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:47:1	35.45	2315	1.51	13.41	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.65	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:1	35.45	2314	1.51	13.41	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.66	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:2	35.45	2291	1.52	13.41	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.6	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:2	35.45	2306	1.52	13.41	105	197	Off Idle	76.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.58	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:2	35.45	2306	1.52	13.43	105	197	Off Idle	76.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.56	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:2	35.45	2302	1.52	13.41	105	197	Off Idle	76.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.53	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:18:47:2	35.45	2305	1.53	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.46	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:47:2	35.45	2306	1.53	13.43	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.4	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:47:3	35.45	2308	1.54	13.42	105	197	Off Idle	76.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.37	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:47:3	35.45	2316	1.55	13.42	105	197	Off Idle	76.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.33	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:47:3	35.45	2319	1.55	13.43	105	197	Off Idle	76.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.31	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:47:3	35.45	2319	1.56	13.44	105	197	Off Idle	76.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.23	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:47:3	35.45	2331	1.56	13.42	105	197	Off Idle	76.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.25	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:18:47:3	35.45	2331	1.57	13.41	105	197	Off Idle	77.1	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.19	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:4	35.45	2330	1.58	13.42	105	197	Off Idle	76.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.14	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:4	34.08	2330	1.59	13.41	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.09	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:4	34.08	2321	1.6	13.41	105	197	Off Idle	76.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.06	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:4	34.08	2311	1.61	13.42	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.04	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:4	34.08	2311	1.62	13.42	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.02	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:4	34.08	2291	1.63	13.42	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.99	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:4	34.08	2302	1.64	13.43	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.98	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:5	34.08	2305	1.65	13.42	105	197	Off Idle	76.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.96	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:5	34.08	2305	1.66	13.42	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.92	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:5	34.08	2311	1.67	13.41	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.86	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:5	34.08	2317	1.67	13.41	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.79	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:5	34.08	2320	1.68	13.41	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.71	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:5	34.08	2326	1.69	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.62	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:6	34.08	2330	1.7	13.41	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.59	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:6	34.08	2348	1.7	13.4	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.58	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:6	34.08	2338	1.71	13.42	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.54	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:6	34.08	2324	1.72	13.43	105	197	Off Idle	76.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.56	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:6	34.08	2319	1.72	13.42	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.53	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:6	34.08	2308	1.73	13.43	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.53	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:6	34.08	2309	1.73	13.43	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.54	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:7	34.08	2307	1.73	13.43	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.52	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:7	34.08	2306	1.74	13.43	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.48	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:18:47:7	34.08	2302	1.75	13.42	105	197	Off Idle	76.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.48	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:7	34.08	2300	1.75	13.42	105	197	Off Idle	76.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.41	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:7	34.08	2301	1.76	13.42	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.32	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:7	34.08	2305	1.77	13.41	105	197	Off Idle	76.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.31	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:8	34.08	2312	1.77	13.42	105	197	Off Idle	77	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.24	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:18:47:8	34.08	2312	1.78	13.43	105	197	Off Idle	77.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.19	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:8	34.08	2317	1.79	13.43	105	197	Off Idle	77.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.17	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:8	34.08	2318	1.8	13.43	105	197	Off Idle	77	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.07	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:8	34.08	2323	1.8	13.43	105	197	Off Idle	76.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:8	34.08	2323	1.81	13.43	105	197	Off Idle	76.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.96	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:9	34.08	2323	1.81	13.43	105	197	Off Idle	76.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.94	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:9	34.08	2322	1.82	13.43	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.87	14.74	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:9	34.08	2317	1.83	13.44	105	197	Off Idle	76.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.86	14.69	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:9	34.08	2314	1.83	13.44	105	197	Off Idle	76.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.82	14.68	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:9	34.08	2307	1.84	13.43	105	197	Off Idle	76.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.79	14.67	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:9	34.08	2305	1.84	13.42	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.78	14.67	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:47:9	34.08	2305	1.85	13.43	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	14.67	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:0	34.08	2302	1.86	13.41	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.7	14.68	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:0	34.08	2306	1.86	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	14.71	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:0	34.08	2306	1.87	13.42	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.66	14.73	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:0	34.08	2307	1.87	13.43	105	197	Off Idle	76.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	14.75	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:0	34.08	2314	1.87	13.41	105	197	Off Idle	76.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	14.79	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:48:0	34.08	2320	1.87	13.42	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.68	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:1	34.08	2320	1.87	13.43	105	197	Off Idle	76.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:1	34.08	2324	1.87	13.42	105	197	Off Idle	76.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.71	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:1	34.08	2326	1.87	13.42	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.71	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:1	34.08	2321	1.87	13.43	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.71	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:1	34.08	2320	1.87	13.41	105	197	Off Idle	76.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.71	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:1	34.08	2316	1.87	13.42	105	197	Off Idle	76.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.69	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:1	34.08	2317	1.87	13.42	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.66	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:2	34.08	2316	1.87	13.43	105	197	Off Idle	76.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.67	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:2	34.08	2316	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.68	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:2	34.08	2313	1.87	13.42	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.68	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:2	34.08	2310	1.87	13.42	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.66	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:2	34.08	2310	1.87	13.42	105	197	Off Idle	76	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.68	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:2	34.08	2312	1.87	13.42	105	197	Off Idle	76	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:3	34.08	2312	1.87	13.41	105	197	Off Idle	76	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.68	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:3	34.08	2312	1.87	13.42	105	197	Off Idle	76	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.67	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:3	34.08	2313	1.87	13.41	105	197	Off Idle	76	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:3	34.08	2318	1.87	13.41	105	197	Off Idle	76.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.66	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:3	34.08	2318	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.62	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:3	34.08	2319	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.64	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:4	34.08	2320	1.87	13.41	105	197	Off Idle	76.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.63	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:4	34.08	2316	1.87	13.42	105	197	Off Idle	76.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.65	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:4	34.08	2316	1.87	13.4	105	197	Off Idle	76.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.69	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:4	34.08	2322	1.87	13.41	105	197	Off Idle	76.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.67	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:4	34.08	2324	1.87	13.43	105	197	Off Idle	76.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:4	34.08	2326	1.87	13.42	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.68	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:4	34.08	2326	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:5	34.08	2320	1.87	13.42	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.68	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:5	34.08	2318	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.67	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:5	34.08	2316	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.71	15.05	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:5	34.08	2313	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.69	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:5	34.08	2313	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.66	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:5	34.08	2318	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.67	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:6	34.08	2318	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.65	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:6	34.08	2320	1.87	13.42	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.67	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:6	34.08	2320	1.87	13.41	105	197	Off Idle	76.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:6	34.08	2324	1.87	13.43	105	197	Off Idle	76.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:6	34.08	2325	1.87	13.43	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:6	34.08	2326	1.87	13.42	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.75	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:6	34.08	2328	1.87	13.44	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.75	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:7	34.08	2342	1.87	13.43	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.77	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:7	34.08	2321	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.77	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:7	34.08	2321	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.72	14.91	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:7	34.08	2319	1.87	13.43	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.72	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:7	34.08	2321	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.64	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:7	34.08	2303	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.6	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:8	34.08	2313	1.87	13.43	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.63	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:8	34.08	2321	1.87	13.42	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.68	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:8	34.08	2321	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:8	34.08	2321	1.87	13.41	105	197	Off Idle	76.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:8	34.08	2321	1.87	13.41	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:8	34.08	2322	1.87	13.41	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.63	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:9	34.08	2324	1.87	13.42	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:9	34.08	2326	1.87	13.43	105	197	Off Idle	76.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:48:9	34.08	2328	1.87	13.42	105	197	Off Idle	76.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.7	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:9	34.08	2331	1.87	13.43	105	197	Off Idle	76.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.73	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:9	34.08	2331	1.87	13.42	105	197	Off Idle	76	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.75	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:48:9	34.08	2331	1.87	13.41	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.71	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:48:9	34.08	2332	1.87	13.41	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.68	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:0	34.08	2332	1.87	13.41	105	197	Off Idle	75.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.67	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:0	34.08	2327	1.87	13.41	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.63	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:0	34.08	2325	1.87	13.41	105	197	Off Idle	75	0	2	132	944 Turbo	0.15	Rich	1	14.6	-7.65	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:0	34.08	2324	1.87	13.42	105	197	Off Idle	74.9	0	2	132	944 Turbo	0.12	Rich	1	14.6	-7.65	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:0	34.08	2332	1.87	13.42	105	197	Off Idle	74.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:0	34.08	2324	1.87	13.42	105	197	Off Idle	74.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:1	34.08	2326	1.88	13.41	105	197	Off Idle	74.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.65	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:1	34.08	2326	1.88	13.42	105	197	Off Idle	74.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.63	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:1	34.08	2326	1.88	13.41	105	197	Off Idle	74.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.62	14.9	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:1	34.08	2326	1.88	13.41	105	197	Off Idle	75	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.63	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:1	34.08	2327	1.88	13.43	105	197	Off Idle	75	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.63	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:1	34.08	2330	1.88	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.68	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:1	34.08	2331	1.88	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.71	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:2	34.08	2330	1.88	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.73	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:2	34.08	2327	1.88	13.41	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:2	34.08	2327	1.88	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:2	34.08	2345	1.88	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:2	34.08	2334	1.88	13.43	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:2	34.08	2323	1.88	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	15.13	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:3	34.08	2325	1.88	13.42	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	15.13	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:3	34.08	2326	1.88	13.42	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	15.12	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:3	34.08	2327	1.88	13.41	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.67	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:3	34.08	2328	1.88	13.42	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.69	15.05	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:3	34.08	2328	1.88	13.43	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.68	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:3	34.08	2328	1.88	13.43	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.67	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:4	34.08	2313	1.88	13.44	105	197	Off Idle	75.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.66	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:4	34.08	2332	1.88	13.44	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.72	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:4	34.08	2330	1.88	13.43	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.72	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:4	34.08	2330	1.88	13.43	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.75	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:4	34.08	2330	1.88	13.43	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:4	34.08	2327	1.88	13.41	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:4	34.08	2328	1.88	13.41	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.72	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:5	34.08	2332	1.88	13.41	105	197	Off Idle	75.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.73	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:5	34.08	2333	1.88	13.4	105	197	Off Idle	75.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.73	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:5	34.08	2333	1.88	13.41	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.71	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:5	34.08	2335	1.88	13.42	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.71	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:5	34.08	2335	1.88	13.42	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.69	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:5	34.08	2338	1.88	13.41	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.66	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:6	34.08	2338	1.88	13.41	105	197	Off Idle	75.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.65	15.05	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:6	34.08	2333	1.88	13.41	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.65	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:6	34.08	2329	1.88	13.42	105	197	Off Idle	75	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:6	34.08	2329	1.88	13.41	105	197	Off Idle	74.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	15.12	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:6	34.08	2331	1.88	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.12	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:6	34.08	2314	1.88	13.42	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.14	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:6	34.08	2324	1.88	13.42	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:7	34.08	2336	1.88	13.41	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:7	34.08	2336	1.88	13.41	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.63	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:18:49:7	34.08	2343	1.89	13.41	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.58	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:7	34.08	2343	1.89	13.41	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.55	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:49:7	34.08	2346	1.9	13.42	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.53	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:7	34.08	2346	1.9	13.42	105	197	Off Idle	75.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.48	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:8	34.08	2344	1.9	13.41	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.47	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:8	34.08	2362	1.91	13.4	105	197	Off Idle	75	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.42	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:8	34.08	2338	1.91	13.41	105	197	Off Idle	75	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.38	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:8	34.08	2338	1.92	13.41	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.35	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:8	34.08	2337	1.92	13.41	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.33	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:8	34.08	2314	1.93	13.41	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.28	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:49:9	34.08	2323	1.93	13.42	105	197	Off Idle	74.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.25	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:49:9	34.08	2336	1.94	13.41	105	197	Off Idle	74.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.22	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:49:9	34.08	2334	1.94	13.41	105	197	Off Idle	75.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.16	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:9	34.08	2358	1.95	13.43	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.07	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:9	34.08	2358	1.96	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.04	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:49:9	34.08	2346	1.97	13.42	105	197	Off Idle	75.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.99	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:49:9	34.08	2349	1.98	13.41	105	197	Off Idle	75.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.95	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:50:0	34.08	2351	1.98	13.41	105	197	Off Idle	75.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.92	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:50:0	34.08	2351	1.99	13.41	105	197	Off Idle	75.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.91	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:50:0	34.08	2348	2	13.42	105	197	Off Idle	75.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.85	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:50:0	34.08	2346	2	13.42	105	197	Off Idle	75.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.83	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:50:0	34.08	2346	2.01	13.43	105	197	Off Idle	75.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.8	15.17	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:50:0	34.08	2346	2.01	13.42	105	197	Off Idle	75.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.74	15.18	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:50:1	34.08	2338	2.02	13.42	105	197	Off Idle	75.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.65	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:1	34.08	2351	2.03	13.41	105	197	Off Idle	75.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.63	15.13	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:1	34.08	2354	2.03	13.41	105	197	Off Idle	75.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.56	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:1	34.08	2354	2.04	13.42	105	197	Off Idle	75	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.56	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:1	32.72	2356	2.04	13.42	105	197	Off Idle	74.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.56	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:1	32.72	2355	2.05	13.43	105	197	Off Idle	74.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.54	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:1	32.72	2354	2.05	13.42	105	197	Off Idle	74.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.52	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:2	32.72	2355	2.06	13.41	105	197	Off Idle	74.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.51	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:2	32.72	2352	2.06	13.42	105	197	Off Idle	74.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.46	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:2	32.72	2352	2.06	13.4	105	197	Off Idle	74.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.48	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:2	32.72	2351	2.06	13.4	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.49	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:2	32.72	2352	2.07	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.47	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:2	32.72	2355	2.07	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.5	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:3	32.72	2355	2.07	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.48	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:3	32.72	2352	2.07	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.45	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:3	32.72	2350	2.07	13.4	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.45	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:3	32.72	2350	2.07	13.4	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.44	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:3	32.72	2354	2.08	13.4	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.4	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:3	32.72	2355	2.08	13.39	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.39	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:4	32.72	2355	2.08	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.34	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:4	32.72	2355	2.08	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.34	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:4	32.72	2354	2.08	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.37	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:4	32.72	2354	2.08	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.37	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:4	32.72	2347	2.08	13.44	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.36	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:4	32.72	2347	2.08	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.39	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:4	32.72	2353	2.08	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.41	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:5	32.72	2351	2.08	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.39	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:5	32.72	2352	2.08	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.39	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:5	32.72	2351	2.08	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.35	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:5	32.72	2354	2.08	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.4	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:5	32.72	2359	2.08	13.41	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.35	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:5	32.72	2364	2.08	13.43	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.38	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:6	32.72	2364	2.08	13.42	105	197	Off Idle	74.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.36	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:6	32.72	2368	2.08	13.41	105	197	Off Idle	74.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.37	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:6	32.72	2369	2.08	13.42	105	197	Off Idle	74.2	0	2	132	944 Turbo	0.19	Rich	1	14.6	-6.37	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:6	32.72	2370	2.08	13.42	105	197	Off Idle	74.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.39	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:6	32.72	2370	2.08	13.42	105	197	Off Idle	74.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.38	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:6	32.72	2367	2.08	13.42	105	197	Off Idle	74	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.38	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:6	32.72	2367	2.08	13.42	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.36	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:7	32.72	2368	2.08	13.42	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.36	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:7	32.72	2368	2.08	13.41	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.33	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:7	32.72	2366	2.09	13.43	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.29	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:7	32.72	2365	2.09	13.44	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.29	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:50:7	32.72	2365	2.09	13.43	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.28	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:7	32.72	2364	2.09	13.42	105	197	Off Idle	73.9	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.23	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:50:8	32.72	2363	2.09	13.42	105	197	Off Idle	73.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.31	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:8	32.72	2364	2.09	13.42	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.28	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:8	32.72	2367	2.09	13.42	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.24	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:8	32.72	2367	2.09	13.42	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.24	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:8	32.72	2373	2.09	13.41	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.28	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:8	32.72	2371	2.1	13.42	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.18	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:9	32.72	2372	2.1	13.43	105	197	Off Idle	73.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.19	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:9	32.72	2370	2.1	13.43	105	197	Off Idle	73.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.22	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:9	32.72	2369	2.1	13.42	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.18	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:9	32.72	2370	2.1	13.43	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.18	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:9	32.72	2372	2.1	13.43	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.19	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:50:9	32.72	2373	2.11	13.42	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.15	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:50:9	32.72	2373	2.11	13.42	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.14	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:0	32.72	2377	2.11	13.42	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.12	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:0	32.72	2377	2.12	13.42	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.08	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:0	32.72	2378	2.12	13.42	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.04	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:0	32.72	2378	2.12	13.42	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.01	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:0	32.72	2386	2.13	13.42	105	197	Off Idle	73.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.98	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:0	32.72	2389	2.13	13.41	105	197	Off Idle	73.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.92	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:1	32.72	2390	2.14	13.42	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.85	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:1	32.72	2390	2.14	13.41	105	197	Off Idle	73.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.81	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:1	32.72	2386	2.15	13.41	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.76	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:1	32.72	2382	2.15	13.41	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.74	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:1	32.72	2382	2.16	13.41	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.75	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:1	32.72	2380	2.16	13.42	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.71	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:1	32.72	2382	2.17	13.42	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.7	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:2	32.72	2384	2.17	13.43	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.7	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:2	32.72	2388	2.18	13.43	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.69	15.16	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:2	32.72	2389	2.18	13.42	105	197	Off Idle	73.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.66	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:2	32.72	2389	2.19	13.43	105	197	Off Idle	73.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.66	15.19	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:2	32.72	2391	2.19	13.43	105	197	Off Idle	73	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.66	15.21	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:2	32.72	2392	2.19	13.43	105	197	Off Idle	72.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.65	15.22	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:3	32.72	2393	2.19	13.43	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.62	15.24	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:3	32.72	2392	2.2	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.63	15.21	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:3	32.72	2386	2.2	13.43	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.62	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:3	32.72	2387	2.2	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.64	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:3	32.72	2387	2.2	13.41	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.65	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:3	32.72	2392	2.2	13.43	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.64	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:4	32.72	2393	2.2	13.42	105	197	Off Idle	72.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.67	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:4	32.72	2396	2.2	13.42	105	197	Off Idle	72.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.62	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:4	32.72	2400	2.2	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.6	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:4	32.72	2398	2.2	13.44	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.6	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:4	32.72	2398	2.2	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.6	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:4	32.72	2397	2.2	13.41	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.6	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:4	32.72	2398	2.2	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.6	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:5	32.72	2398	2.2	13.41	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.63	14.77	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:5	32.72	2400	2.2	13.41	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.62	14.77	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:5	32.72	2398	2.2	13.42	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.6	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:5	32.72	2400	2.2	13.43	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.6	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:5	32.72	2400	2.2	13.42	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.6	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:5	32.72	2400	2.2	13.42	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.57	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:6	32.72	2401	2.2	13.4	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.6	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:6	32.72	2404	2.21	13.39	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.6	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:6	32.72	2404	2.21	13.39	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.6	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:6	32.72	2404	2.21	13.39	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.6	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:6	32.72	2416	2.21	13.42	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.6	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:6	32.72	2404	2.21	13.42	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.62	14.98	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:51:6	32.72	2404	2.21	13.42	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.6	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:51:7	32.72	2399	2.21	13.42	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.61	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:7	32.72	2383	2.21	13.42	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.55	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:7	32.72	2395	2.22	13.41	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.5	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:7	32.72	2414	2.22	13.43	105	197	Off Idle	72.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.45	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:7	32.72	2420	2.22	13.42	105	197	Off Idle	72.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.45	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:7	32.72	2428	2.22	13.43	105	197	Off Idle	72.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.39	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:8	32.72	2438	2.23	13.44	105	197	Off Idle	72	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.4	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:8	32.72	2430	2.23	13.44	105	197	Off Idle	71.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.36	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:8	32.72	2426	2.23	13.43	105	197	Off Idle	71.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.29	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:8	32.72	2418	2.24	13.44	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.25	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:8	32.72	2406	2.24	13.43	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.23	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:8	32.72	2407	2.25	13.42	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.22	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:9	32.72	2409	2.25	13.43	105	197	Off Idle	71.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.18	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:9	32.72	2410	2.26	13.42	105	197	Off Idle	71.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.15	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:9	32.72	2417	2.26	13.42	105	197	Off Idle	71.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.09	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:9	32.72	2428	2.27	13.43	105	197	Off Idle	71	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.04	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:51:9	32.72	2428	2.27	13.43	105	197	Off Idle	70.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:51:9	32.72	2429	2.28	13.42	105	197	Off Idle	70.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.93	15.15	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:51:9	32.72	2429	2.29	13.42	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.91	15.14	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:0	32.72	2430	2.3	13.42	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.78	15.1	1.03	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:0	32.72	2440	2.31	13.41	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.74	15.07	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:0	32.72	2428	2.31	13.41	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.67	15.04	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:18:52:0	32.72	2428	2.32	13.41	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.61	15	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:0	32.72	2431	2.33	13.41	105	197	Off Idle	70.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.58	14.99	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:0	32.72	2432	2.33	13.41	105	197	Off Idle	70.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.52	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:1	32.72	2437	2.34	13.43	105	197	Off Idle	70.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.46	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:1	32.72	2437	2.34	13.43	105	197	Off Idle	70	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.42	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:1	32.72	2438	2.34	13.43	105	197	Off Idle	70.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.41	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:18:52:1	32.72	2438	2.35	13.42	105	197	Off Idle	70.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.37	14.9	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:18:52:1	32.72	2435	2.36	13.42	105	197	Off Idle	70	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.38	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:1	32.72	2435	2.36	13.42	105	197	Off Idle	69.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.36	14.97	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:1	32.72	2436	2.36	13.41	105	197	Off Idle	69.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.35	15.01	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:2	32.72	2438	2.37	13.41	105	197	Off Idle	69.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.38	15.08	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:2	32.72	2438	2.37	13.4	105	197	Off Idle	69.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.39	15.12	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:2	32.72	2440	2.38	13.4	105	197	Off Idle	69.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.41	15.17	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:2	32.72	2442	2.38	13.4	105	197	Off Idle	69.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.4	15.16	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:2	32.72	2445	2.38	13.42	105	197	Off Idle	69.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.39	15.12	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:2	32.72	2445	2.38	13.41	105	197	Off Idle	69.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.36	15.05	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:3	32.72	2444	2.38	13.41	105	197	Off Idle	69.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.36	14.99	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:3	32.72	2446	2.38	13.42	105	197	Off Idle	69.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.35	14.89	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:3	32.72	2445	2.38	13.42	105	197	Off Idle	69.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.36	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:3	32.72	2450	2.38	13.42	105	197	Off Idle	69.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.39	14.67	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:3	32.72	2454	2.38	13.42	105	197	Off Idle	69.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.38	14.55	0.99	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:3	32.72	2456	2.38	13.43	105	197	Off Idle	69.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.35	14.48	0.99	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:4	32.72	2456	2.38	13.43	105	197	Off Idle	69.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.4	14.44	0.98	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:4	32.72	2451	2.38	13.44	105	197	Off Idle	69.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.39	14.43	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:4	32.72	2449	2.38	13.43	105	197	Off Idle	69.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.39	14.43	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:4	32.72	2457	2.38	13.44	105	197	Off Idle	69.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.41	14.44	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:4	32.72	2457	2.38	13.42	105	197	Off Idle	69.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.41	14.49	0.99	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:4	32.72	2458	2.38	13.43	105	197	Off Idle	69.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.44	14.53	0.99	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:4	32.72	2465	2.38	13.42	105	197	Off Idle	69.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.42	14.56	0.99	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:5	32.72	2488	2.38	13.41	105	197	Off Idle	69.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.42	14.59	0.99	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:5	32.72	2478	2.38	13.41	105	197	Off Idle	69.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.41	14.62	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:5	32.72	2468	2.38	13.42	105	197	Off Idle	69.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.43	14.66	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:5	32.72	2469	2.38	13.41	105	197	Off Idle	69	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.43	14.68	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:5	32.72	2468	2.38	13.41	105	197	Off Idle	69.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.4	14.71	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:5	32.72	2468	2.38	13.41	105	197	Off Idle	69.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.39	14.73	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:6	32.72	2464	2.38	13.41	105	197	Off Idle	68.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.43	14.75	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:52:6	32.72	2464	2.38	13.43	105	197	Off Idle	68.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.42	14.76	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:6	32.72	2464	2.39	13.42	105	197	Off Idle	68.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.45	14.77	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:6	32.72	2464	2.39	13.42	105	197	Off Idle	68.4	0	2	132	944 Turbo	0.68	Lean	1	14.6	-4.4	14.8	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:6	32.72	2465	2.39	13.41	105	197	Off Idle	68.4	0	2	132	944 Turbo	0.66	Lean	1	14.6	-4.41	14.81	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:6	32.72	2468	2.39	13.43	105	197	Off Idle	68.4	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.39	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:6	32.72	2469	2.39	13.42	105	197	Off Idle	68.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-4.38	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:7	32.72	2470	2.39	13.42	105	197	Off Idle	68.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.37	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:7	32.72	2472	2.39	13.41	105	197	Off Idle	68.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.4	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:7	32.72	2473	2.39	13.42	105	197	Off Idle	68.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.38	14.82	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:7	32.72	2472	2.39	13.41	105	197	Off Idle	68.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.39	14.82	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:7	32.72	2472	2.39	13.43	105	197	Off Idle	68.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.38	14.82	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:7	32.72	2476	2.39	13.41	105	197	Off Idle	68.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.38	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:8	32.72	2479	2.39	13.43	105	197	Off Idle	68.3	0	2	132	944 Turbo	0.2	Rich	1	14.6	-4.36	14.86	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:8	32.72	2479	2.39	13.43	105	197	Off Idle	68.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-4.37	14.9	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:52:8	32.72	2480	2.39	13.44	105	197	Off Idle	68.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-4.43	14.92	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:8	32.72	2482	2.39	13.43	105	197	Off Idle	68.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.41	14.94	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:8	32.72	2485	2.39	13.43	105	197	Off Idle	67.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.43	14.98	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:8	32.72	2483	2.39	13.42	105	197	Off Idle	67.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.41	15.01	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:9	32.72	2481	2.4	13.42	105	197	Off Idle	67.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.42	15.07	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:9	32.72	2488	2.4	13.43	105	197	Off Idle	67.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.4	15.13	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:52:9	32.72	2490	2.4	13.43	105	197	Off Idle	67.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.4	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:9	32.72	2496	2.4	13.42	105	197	Off Idle	67.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.38	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:9	32.72	2500	2.4	13.42	105	197	Off Idle	67	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.38	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:9	32.72	2500	2.4	13.42	105	197	Off Idle	66.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.38	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:52:9	32.72	2494	2.4	13.41	105	197	Off Idle	66.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.41	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:0	32.72	2493	2.4	13.39	105	197	Off Idle	66.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.37	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:0	32.72	2492	2.4	13.4	105	197	Off Idle	66.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.36	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:0	32.72	2492	2.4	13.41	105	197	Off Idle	66.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.35	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:0	32.72	2496	2.41	13.42	105	197	Off Idle	66.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.36	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:0	32.72	2492	2.41	13.42	105	197	Off Idle	66.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.34	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:0	32.72	2490	2.41	13.41	105	197	Off Idle	66.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.36	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:1	32.72	2496	2.41	13.42	105	197	Off Idle	66.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.35	14.8	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:1	32.72	2506	2.41	13.41	105	197	Off Idle	66.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.35	14.78	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:1	32.72	2512	2.41	13.43	105	197	Off Idle	66.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.33	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:1	32.72	2512	2.41	13.42	105	197	Off Idle	66.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.37	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:1	32.72	2509	2.41	13.41	105	197	Off Idle	66.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.34	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:1	32.72	2508	2.41	13.41	105	197	Off Idle	66	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.33	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:1	32.72	2507	2.41	13.4	105	197	Off Idle	66	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.35	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:2	32.72	2506	2.41	13.41	105	197	Off Idle	65.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.34	14.94	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:2	32.72	2505	2.41	13.41	105	197	Off Idle	65.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.35	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:2	32.72	2507	2.41	13.41	105	197	Off Idle	65.6	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.35	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:2	32.72	2510	2.41	13.42	105	197	Off Idle	65.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-4.33	15.09	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:2	32.72	2511	2.41	13.43	105	197	Off Idle	65.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.32	15.1	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:2	32.72	2512	2.41	13.42	105	197	Off Idle	65.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.37	15.08	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:3	32.72	2511	2.41	13.43	105	197	Off Idle	65.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.37	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:3	32.72	2512	2.41	13.43	105	197	Off Idle	65.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.39	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:3	32.72	2512	2.41	13.42	105	197	Off Idle	65.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.42	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:3	32.72	2514	2.41	13.43	105	197	Off Idle	65.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.42	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:3	32.72	2515	2.41	13.42	105	197	Off Idle	65.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.4	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:3	32.72	2519	2.41	13.43	105	197	Off Idle	65.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.41	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:4	32.72	2524	2.41	13.42	105	197	Off Idle	65.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.39	14.76	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:4	32.72	2523	2.41	13.43	105	197	Off Idle	65.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.42	14.75	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:4	32.72	2520	2.41	13.43	105	197	Off Idle	65.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.4	14.75	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:4	32.72	2521	2.41	13.43	105	197	Off Idle	65.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.4	14.76	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:4	32.72	2520	2.41	13.42	105	197	Off Idle	65.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.38	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:4	32.72	2517	2.41	13.41	105	197	Off Idle	65.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.42	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:4	32.72	2518	2.42	13.42	105	197	Off Idle	65.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.42	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:5	32.72	2519	2.41	13.42	105	197	Off Idle	65.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.43	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:53:5	32.72	2536	2.41	13.41	105	197	Off Idle	65.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.44	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:5	32.72	2532	2.41	13.41	105	197	Off Idle	65.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.44	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:5	32.72	2540	2.41	13.42	105	197	Off Idle	65.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.4	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:5	32.72	2540	2.41	13.42	105	197	Off Idle	65	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.43	14.81	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:5	32.72	2541	2.41	13.42	105	197	Off Idle	65	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.41	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:6	32.72	2530	2.41	13.42	105	197	Off Idle	65	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.42	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:6	32.72	2541	2.41	13.41	105	197	Off Idle	65	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.46	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:6	32.72	2540	2.41	13.42	105	197	Off Idle	65	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.48	14.91	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:6	32.72	2534	2.42	13.43	105	197	Off Idle	65	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.46	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:6	32.72	2548	2.42	13.42	105	197	Off Idle	64.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.46	15	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:6	32.72	2540	2.42	13.42	105	197	Off Idle	64.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.42	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:6	32.72	2533	2.42	13.41	105	197	Off Idle	64.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.39	15.08	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:7	32.72	2535	2.42	13.42	105	197	Off Idle	64.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.4	15.12	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:7	32.72	2535	2.42	13.42	105	197	Off Idle	64.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.41	15.19	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:7	32.72	2538	2.42	13.42	105	197	Off Idle	64.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.43	15.23	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:7	32.72	2542	2.42	13.42	105	197	Off Idle	64.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.41	15.26	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:7	32.72	2545	2.42	13.41	105	197	Off Idle	64.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.42	15.24	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:7	32.72	2545	2.42	13.42	105	197	Off Idle	63.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.4	15.2	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:8	32.72	2549	2.42	13.42	105	197	Off Idle	63.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.44	15.18	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:8	32.72	2550	2.42	13.43	105	197	Off Idle	63.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.44	15.14	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:8	32.72	2548	2.42	13.42	105	197	Off Idle	63.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.43	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:53:8	32.72	2548	2.42	13.42	105	197	Off Idle	63.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.44	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:8	32.72	2545	2.42	13.42	105	197	Off Idle	63.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.43	15	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:8	32.72	2546	2.42	13.42	105	197	Off Idle	63.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.43	14.98	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:9	32.72	2551	2.42	13.41	105	197	Off Idle	63.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.44	14.95	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:9	32.72	2554	2.43	13.42	105	197	Off Idle	63.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.4	14.88	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:9	32.72	2562	2.43	13.43	105	197	Off Idle	63.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.44	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:9	32.72	2566	2.43	13.42	105	197	Off Idle	63.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.47	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:9	32.72	2566	2.43	13.42	105	197	Off Idle	63.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.47	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:53:9	32.72	2564	2.43	13.43	105	197	Off Idle	63.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.48	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:53:9	32.72	2564	2.43	13.43	105	197	Off Idle	63.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.53	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:54:0	32.72	2561	2.43	13.43	105	197	Off Idle	63.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.51	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:54:0	34.08	2558	2.43	13.43	105	197	Off Idle	63.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.5	14.97	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:18:54:0	34.08	2560	2.43	13.43	105	197	Off Idle	63.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-4.52	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:0	34.08	2565	2.43	13.42	105	197	Off Idle	62.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.52	15.05	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:0	34.08	2565	2.43	13.42	105	197	Off Idle	62.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.51	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:0	34.08	2567	2.43	13.43	105	197	Off Idle	62.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.52	15.19	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:1	34.08	2572	2.43	13.41	105	197	Off Idle	62.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.53	15.19	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:1	32.72	2552	2.43	13.41	105	197	Off Idle	62.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.52	15.2	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:1	32.72	2562	2.43	13.42	105	197	Off Idle	62.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.52	15.17	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:1	32.72	2577	2.43	13.41	105	197	Off Idle	62.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.56	15.13	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:1	32.72	2567	2.43	13.41	105	197	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.54	15.08	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:1	32.72	2568	2.43	13.42	105	197	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.52	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:1	32.72	2567	2.43	13.41	105	197	Off Idle	62.2	0	2	132	944 Turbo	0.69	Lean	1	14.6	-4.52	14.99	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:2	32.72	2566	2.43	13.43	105	197	Off Idle	62.1	0	2	132	944 Turbo	0.64	Lean	1	14.6	-4.55	14.92	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:2	32.72	2566	2.43	13.42	105	197	Off Idle	62	0	2	132	944 Turbo	0.57	Lean	1	14.6	-4.58	14.87	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:54:2	32.72	2568	2.42	13.41	105	197	Off Idle	62	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.55	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:54:2	32.72	2575	2.42	13.42	105	197	Off Idle	62	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.59	14.79	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:54:2	32.72	2584	2.42	13.42	105	197	Off Idle	61.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.57	14.78	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:54:2	32.72	2592	2.42	13.41	105	197	Off Idle	61.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.56	14.77	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:54:3	34.08	2602	2.42	13.42	105	197	Off Idle	61.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.59	14.78	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:54:3	34.08	2596	2.42	13.41	105	197	Off Idle	61.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.61	14.8	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:54:3	34.08	2593	2.42	13.41	105	197	Off Idle	61.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.59	14.84	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:54:3	34.08	2590	2.42	13.42	105	197	Off Idle	61.7	0	2	132	944 Turbo	0.21	Rich	1	14.6	-4.6	14.87	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:54:3	34.08	2584	2.42	13.41	105	197	Off Idle	61.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-4.66	14.9	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:3	34.08	2581	2.42	13.43	105	197	Off Idle	61.4	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.62	14.93	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:4	34.08	2580	2.42	13.42	105	197	Off Idle	61.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.67	14.98	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:4	34.08	2580	2.42	13.42	105	197	Off Idle	61.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.66	15.01	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:54:4	34.08	2579	2.42	13.42	105	197	Off Idle	61.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.68	15.06	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:4	34.08	2583	2.42	13.42	105	197	Off Idle	61.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.7	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:4	34.08	2586	2.41	13.41	105	197	Off Idle	61.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.68	15.12	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:4	34.08	2594	2.41	13.42	105	197	Off Idle	61.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.7	15.1	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:4	34.08	2602	2.41	13.43	105	197	Off Idle	61.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.72	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:5	34.08	2602	2.41	13.42	105	197	Off Idle	61.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-4.73	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:5	34.08	2599	2.41	13.43	105	197	Off Idle	61.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.76	15.06	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:5	34.08	2603	2.41	13.44	105	197	Off Idle	61.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.82	15.02	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:5	34.08	2603	2.41	13.44	105	197	Off Idle	61.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.84	15.02	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:5	34.08	2599	2.4	13.43	105	197	Off Idle	61.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.9	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:5	34.08	2596	2.4	13.43	105	197	Off Idle	61.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.89	14.89	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:6	34.08	2594	2.4	13.43	105	197	Off Idle	61.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.93	14.71	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:6	34.08	2593	2.4	13.42	105	197	Off Idle	61.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.96	14.7	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:6	34.08	2594	2.39	13.41	105	197	Off Idle	61	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.01	14.7	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:6	34.08	2598	2.39	13.42	105	197	Off Idle	60.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.98	14.71	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:6	34.08	2598	2.39	13.42	105	197	Off Idle	60.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.02	14.72	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:6	34.08	2604	2.38	13.41	105	197	Off Idle	60.8	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.03	14.74	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:54:6	34.08	2608	2.38	13.4	105	197	Off Idle	60.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.04	14.77	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:54:7	34.08	2608	2.38	13.41	105	197	Off Idle	60.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.07	14.78	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:54:7	34.08	2609	2.38	13.42	105	197	Off Idle	60.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.09	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:54:7	34.08	2594	2.37	13.41	105	197	Off Idle	60.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.1	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:54:7	34.08	2608	2.37	13.42	105	197	Off Idle	61	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.1	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:54:7	34.08	2605	2.37	13.43	105	197	Off Idle	61.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.13	15.06	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:54:7	34.08	2599	2.37	13.42	105	197	Off Idle	61.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.1	15.06	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:54:8	34.08	2599	2.37	13.43	105	197	Off Idle	61.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.11	15.05	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:54:8	34.08	2604	2.37	13.43	105	197	Off Idle	61.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.08	15.04	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:8	34.08	2605	2.36	13.43	105	197	Off Idle	61.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.1	15.06	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:8	34.08	2611	2.36	13.44	105	197	Off Idle	61.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.14	15.06	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:8	34.08	2611	2.36	13.43	105	197	Off Idle	61.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.16	15.05	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:8	34.08	2618	2.36	13.41	105	197	Off Idle	61.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.15	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:9	34.08	2622	2.36	13.42	105	197	Off Idle	61.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.17	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:9	34.08	2622	2.36	13.42	105	197	Off Idle	60.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.17	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:54:9	34.08	2621	2.37	13.41	105	197	Off Idle	60.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.08	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:9	34.08	2616	2.37	13.39	105	197	Off Idle	60.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.07	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:9	34.08	2615	2.37	13.4	105	197	Off Idle	60.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.01	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:9	34.08	2616	2.37	13.4	105	197	Off Idle	60.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.99	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:54:9	34.08	2621	2.38	13.41	105	197	Off Idle	59.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.97	15.09	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:0	34.08	2622	2.38	13.41	105	197	Off Idle	59.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.92	15.13	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:55:0	34.08	2622	2.38	13.42	105	197	Off Idle	59.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.9	15.16	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:55:0	34.08	2624	2.39	13.44	105	197	Off Idle	59.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.87	15.2	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:55:0	34.08	2628	2.39	13.43	105	197	Off Idle	59.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.87	15.22	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:0	34.08	2632	2.39	13.43	105	197	Off Idle	59.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.86	15.21	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:0	34.08	2634	2.4	13.42	105	197	Off Idle	59.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.8	15.19	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:1	34.08	2634	2.4	13.43	105	197	Off Idle	59	0	2	132	944 Turbo	0.53	Lean	1	14.6	-4.79	15.16	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:1	34.08	2630	2.4	13.42	105	197	Off Idle	58.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.78	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:1	34.08	2630	2.41	13.42	105	197	Off Idle	58.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.83	15.14	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:1	34.08	2622	2.41	13.41	105	197	Off Idle	58.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.81	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:1	34.08	2621	2.41	13.43	105	197	Off Idle	59	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.79	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:1	34.08	2622	2.42	13.42	105	197	Off Idle	59	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.84	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:1	34.08	2621	2.42	13.4	105	197	Off Idle	59	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.83	15.05	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:2	34.08	2625	2.42	13.42	105	197	Off Idle	59	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.81	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:2	34.08	2633	2.42	13.42	105	197	Off Idle	59	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.85	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:2	34.08	2636	2.42	13.4	105	197	Off Idle	59	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.83	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:2	34.08	2644	2.42	13.41	105	197	Off Idle	59	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.8	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:2	34.08	2649	2.42	13.41	105	197	Off Idle	58.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.84	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:55:2	34.08	2660	2.42	13.4	105	197	Off Idle	58.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-4.82	14.87	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:55:3	34.08	2648	2.42	13.4	105	197	Off Idle	58.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.84	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:55:3	34.08	2646	2.42	13.41	105	197	Off Idle	58.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.85	14.83	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:55:3	34.08	2645	2.42	13.42	105	197	Off Idle	58.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.88	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:55:3	34.08	2630	2.42	13.43	105	197	Off Idle	58.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.89	14.79	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:55:3	34.08	2638	2.42	13.41	105	197	Off Idle	58.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.88	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:18:55:3	34.08	2640	2.42	13.42	105	197	Off Idle	58.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.89	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:4	34.08	2640	2.41	13.43	105	197	Off Idle	58.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.93	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:4	34.08	2644	2.41	13.42	105	197	Off Idle	58.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.92	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:4	34.08	2648	2.41	13.41	105	197	Off Idle	58.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.89	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:4	34.08	2648	2.41	13.42	105	197	Off Idle	58	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.98	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:4	34.08	2649	2.41	13.42	105	197	Off Idle	58	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.98	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:4	34.08	2647	2.41	13.41	105	197	Off Idle	57.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.94	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:4	34.08	2649	2.41	13.43	105	197	Off Idle	57.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.99	15.02	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:5	34.08	2649	2.4	13.43	105	197	Off Idle	57.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.04	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:5	34.08	2650	2.4	13.43	105	197	Off Idle	57.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.05	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:5	34.08	2648	2.4	13.42	105	197	Off Idle	57.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.08	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:5	34.08	2648	2.4	13.43	105	197	Off Idle	57.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.1	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:5	34.08	2650	2.4	13.43	105	197	Off Idle	57.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.13	14.9	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:5	34.08	2652	2.39	13.42	105	197	Off Idle	57.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.16	14.89	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:6	34.08	2652	2.39	13.41	105	197	Off Idle	57.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.16	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:6	34.08	2655	2.39	13.42	105	197	Off Idle	57.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.19	14.79	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:6	34.08	2644	2.39	13.42	105	197	Off Idle	57.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.17	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:6	34.08	2658	2.38	13.42	105	197	Off Idle	57.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.19	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:6	34.08	2665	2.38	13.41	105	197	Off Idle	57.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.21	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:6	34.08	2664	2.38	13.43	105	197	Off Idle	57.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.24	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:6	34.08	2674	2.38	13.43	105	197	Off Idle	57.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.29	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:7	34.08	2661	2.37	13.41	105	197	Off Idle	57.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.29	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:7	34.08	2660	2.37	13.42	105	197	Off Idle	57.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.34	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:18:55:7	34.08	2662	2.37	13.42	105	197	Off Idle	57.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.38	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:7	34.08	2665	2.37	13.42	105	197	Off Idle	57.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.4	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:7	34.08	2666	2.36	13.41	105	197	Off Idle	57.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.45	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:7	34.08	2665	2.36	13.42	105	197	Off Idle	57.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.49	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:8	34.08	2662	2.36	13.42	105	197	Off Idle	57.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.5	15	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:8	34.08	2660	2.36	13.41	105	197	Off Idle	57.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.47	15.05	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:8	34.08	2658	2.35	13.42	105	197	Off Idle	57.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.48	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:8	34.08	2660	2.35	13.42	105	197	Off Idle	57.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.5	15.13	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:8	34.08	2664	2.35	13.4	105	197	Off Idle	57.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.48	15.13	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:8	34.08	2664	2.34	13.41	105	197	Off Idle	57	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.53	15.1	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:9	34.08	2663	2.34	13.42	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.52	15.05	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:55:9	34.08	2668	2.34	13.41	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.54	15.02	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:9	34.08	2674	2.34	13.41	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.58	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:9	34.08	2675	2.34	13.43	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.57	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:9	34.08	2675	2.34	13.43	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.56	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:9	34.08	2676	2.33	13.42	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.58	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:55:9	34.08	2670	2.33	13.43	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.55	14.83	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:56:0	34.08	2670	2.33	13.42	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.58	14.79	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:56:0	34.08	2674	2.33	13.43	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.57	14.78	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:56:0	34.08	2675	2.33	13.41	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.56	14.81	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:56:0	34.08	2675	2.33	13.42	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.58	14.83	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:18:56:0	34.08	2677	2.33	13.42	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.61	14.85	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:0	34.08	2691	2.33	13.41	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.58	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:1	34.08	2691	2.33	13.43	105	197	Off Idle	56.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.61	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:1	34.08	2684	2.33	13.43	105	197	Off Idle	56.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.65	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:1	34.08	2682	2.33	13.43	105	197	Off Idle	56.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.64	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:1	34.08	2683	2.32	13.44	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.68	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:1	34.08	2682	2.32	13.45	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.73	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:1	34.08	2680	2.32	13.44	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.73	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:1	34.08	2682	2.32	13.43	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.72	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:2	34.08	2682	2.32	13.45	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.78	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:2	34.08	2682	2.32	13.44	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.8	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:56:2	34.08	2683	2.32	13.43	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.78	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:2	34.08	2682	2.31	13.44	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.84	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:2	34.08	2682	2.31	13.44	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.83	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:2	34.08	2684	2.31	13.44	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.83	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:3	34.08	2687	2.31	13.43	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.85	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:3	34.08	2686	2.31	13.43	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.85	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:3	34.08	2693	2.3	13.42	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.87	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:3	34.08	2691	2.3	13.44	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.9	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:3	34.08	2690	2.3	13.44	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.91	14.9	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:3	34.08	2685	2.3	13.43	105	197	Off Idle	56.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.94	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:18:56:4	34.08	2680	2.3	13.43	105	197	Off Idle	56.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:4	34.08	2682	2.29	13.42	105	197	Off Idle	56.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:4	34.08	2682	2.29	13.42	105	197	Off Idle	55.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:4	34.08	2685	2.29	13.42	105	197	Off Idle	55.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:4	34.08	2683	2.29	13.42	105	197	Off Idle	55.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.02	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:4	34.08	2683	2.29	13.42	105	197	Off Idle	55.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.02	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:4	34.08	2683	2.29	13.42	105	197	Off Idle	55.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.04	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:5	34.08	2686	2.28	13.42	105	197	Off Idle	55.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.02	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:5	34.08	2686	2.28	13.43	105	197	Off Idle	55.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.02	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:5	34.08	2692	2.28	13.44	105	197	Off Idle	55.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.04	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:5	34.08	2693	2.28	13.43	105	197	Off Idle	55.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.04	15.06	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:5	34.08	2690	2.28	13.43	105	197	Off Idle	56	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.03	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:5	34.08	2690	2.28	13.43	105	197	Off Idle	56.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.07	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:6	34.08	2696	2.28	13.43	105	197	Off Idle	56.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.12	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:6	34.08	2697	2.28	13.43	105	197	Off Idle	56.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.11	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:6	34.08	2697	2.27	13.43	105	197	Off Idle	56.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.16	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:6	34.08	2705	2.27	13.43	105	197	Off Idle	56.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.17	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:6	34.08	2703	2.27	13.43	105	197	Off Idle	56.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.15	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:6	34.08	2703	2.27	13.43	105	197	Off Idle	56.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.16	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:6	34.08	2704	2.27	13.43	105	197	Off Idle	56	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.15	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:7	34.08	2696	2.27	13.42	105	197	Off Idle	55.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.16	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:7	34.08	2695	2.27	13.43	105	197	Off Idle	55.7	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.19	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:7	34.08	2695	2.27	13.42	105	197	Off Idle	55.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.23	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:7	34.08	2697	2.27	13.42	105	197	Off Idle	55.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.23	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:7	34.08	2698	2.27	13.43	105	197	Off Idle	55.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.26	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:7	34.08	2696	2.27	13.42	105	197	Off Idle	55.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.26	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:8	34.08	2689	2.27	13.43	105	197	Off Idle	55.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.24	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:8	34.08	2688	2.26	13.44	105	197	Off Idle	55.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.24	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:8	34.08	2689	2.26	13.43	105	197	Off Idle	55.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.23	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:8	34.08	2690	2.26	13.43	105	197	Off Idle	55.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.27	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:8	34.08	2699	2.26	13.44	105	197	Off Idle	55.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-6.28	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:56:8	34.08	2705	2.26	13.44	105	197	Off Idle	55.4	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.3	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:9	34.08	2713	2.26	13.43	105	197	Off Idle	55.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.27	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:9	34.08	2713	2.26	13.43	105	197	Off Idle	55.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.32	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:56:9	34.08	2716	2.26	13.43	105	197	Off Idle	55.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.33	15.04	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:9	34.08	2716	2.25	13.43	105	197	Off Idle	55.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.34	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:9	34.08	2716	2.25	13.43	105	197	Off Idle	55.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.38	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:9	34.08	2714	2.25	13.44	105	197	Off Idle	55	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.42	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:56:9	34.08	2728	2.25	13.43	105	197	Off Idle	54.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.4	14.9	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:18:57:0	34.08	2706	2.25	13.41	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.42	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:57:0	34.08	2705	2.24	13.43	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.41	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:18:57:0	34.08	2702	2.24	13.42	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.47	14.9	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:57:0	34.08	2690	2.24	13.43	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.44	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:57:0	34.08	2690	2.24	13.42	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.45	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:57:0	34.08	2690	2.24	13.45	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.48	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:57:1	34.08	2690	2.23	13.43	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.47	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:57:1	34.08	2690	2.23	13.44	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.54	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:57:1	34.08	2694	2.22	13.44	105	197	Off Idle	54.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.57	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:57:1	34.08	2702	2.22	13.43	105	197	Off Idle	54.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.68	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:1	34.08	2704	2.21	13.42	105	197	Off Idle	54.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.71	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:1	34.08	2708	2.21	13.44	105	197	Off Idle	54.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.77	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:1	34.08	2707	2.21	13.44	105	197	Off Idle	54.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.81	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:2	34.08	2706	2.2	13.45	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.82	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:2	34.08	2704	2.2	13.44	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.87	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:2	34.08	2701	2.19	13.44	105	197	Off Idle	54.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.92	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:2	34.08	2699	2.19	13.43	105	197	Off Idle	54.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.95	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:2	34.08	2698	2.18	13.44	105	197	Off Idle	54.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.95	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:2	34.08	2700	2.18	13.43	105	197	Off Idle	55	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.96	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:3	34.08	2698	2.17	13.42	105	197	Off Idle	55.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.98	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:3	34.08	2698	2.17	13.44	105	197	Off Idle	55	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.97	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:3	35.45	2714	2.16	13.45	105	197	Off Idle	54.8	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.01	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:3	35.45	2711	2.16	13.45	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.06	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:18:57:3	35.45	2721	2.15	13.45	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.06	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:3	35.45	2723	2.15	13.45	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.07	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:4	35.45	2729	2.15	13.46	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.13	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:4	35.45	2730	2.15	13.45	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.11	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:4	35.45	2726	2.15	13.44	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.14	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:4	35.45	2726	2.15	13.44	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.16	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:4	35.45	2716	2.14	13.42	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.17	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:4	35.45	2707	2.14	13.41	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.17	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:4	35.45	2706	2.14	13.44	105	197	Off Idle	54.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.21	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:5	35.45	2704	2.14	13.43	105	197	Off Idle	54.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.19	15.13	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:5	35.45	2700	2.14	13.42	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.18	15.17	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:5	35.45	2698	2.13	13.42	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.2	15.2	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:5	35.45	2690	2.13	13.42	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.2	15.2	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:5	35.45	2704	2.13	13.43	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.17	15.2	1.04	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:5	34.08	2684	2.13	13.41	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.19	15.2	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:6	34.08	2696	2.13	13.42	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.21	15.2	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:6	34.08	2708	2.12	13.43	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.25	15.18	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:6	34.08	2704	2.12	13.44	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.25	15.16	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:57:6	34.08	2706	2.12	13.45	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.28	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:6	34.08	2708	2.12	13.44	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.27	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:6	35.45	2715	2.12	13.45	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.31	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:6	35.45	2715	2.12	13.45	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.32	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:7	35.45	2716	2.11	13.45	105	197	Off Idle	54.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.3	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:7	35.45	2721	2.11	13.44	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.32	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:7	35.45	2721	2.11	13.45	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.34	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:7	35.45	2731	2.11	13.45	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.35	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:7	35.45	2716	2.11	13.46	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.33	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:7	35.45	2713	2.11	13.45	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.36	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:8	35.45	2713	2.11	13.45	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.36	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:8	35.45	2699	2.1	13.44	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.36	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:8	35.45	2709	2.1	13.44	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.36	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:8	35.45	2710	2.1	13.43	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.37	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:57:8	35.45	2713	2.1	13.44	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.38	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:57:8	35.45	2718	2.1	13.44	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.36	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:57:9	35.45	2723	2.1	13.43	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.39	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:57:9	35.45	2722	2.1	13.43	105	197	Off Idle	54.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.37	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:57:9	35.45	2722	2.1	13.44	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.38	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:57:9	35.45	2722	2.1	13.42	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.4	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:57:9	35.45	2719	2.1	13.42	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.4	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:57:9	35.45	2725	2.1	13.43	105	197	Off Idle	54.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.4	15.14	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:57:9	35.45	2713	2.1	13.42	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.39	15.15	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:58:0	35.45	2705	2.1	13.4	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.37	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:58:0	35.45	2706	2.1	13.41	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.32	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:0	35.45	2696	2.1	13.41	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.34	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:58:0	35.45	2710	2.1	13.4	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.32	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:0	35.45	2712	2.1	13.4	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.32	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:0	35.45	2720	2.1	13.42	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.32	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:1	35.45	2725	2.1	13.44	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.31	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:1	35.45	2725	2.1	13.44	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.17	Rich	1	14.6	-7.36	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:1	35.45	2726	2.1	13.44	105	197	Off Idle	54.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.36	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:1	35.45	2721	2.1	13.45	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.36	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:1	35.45	2721	2.1	13.45	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.4	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:1	35.45	2741	2.1	13.44	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.4	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:1	35.45	2717	2.1	13.44	105	197	Off Idle	54.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.39	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:2	35.45	2714	2.1	13.44	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.38	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:2	35.45	2714	2.1	13.45	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.43	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:2	35.45	2717	2.1	13.44	105	197	Off Idle	54.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.39	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:2	35.45	2716	2.1	13.44	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.37	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:18:58:2	35.45	2716	2.1	13.45	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.39	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:2	35.45	2716	2.1	13.43	105	197	Off Idle	54.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.37	15.16	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:3	35.45	2695	2.1	13.43	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.37	15.18	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:3	35.45	2717	2.1	13.42	105	197	Off Idle	54	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.37	15.18	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:3	35.45	2716	2.1	13.42	105	197	Off Idle	54	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.37	15.19	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:3	35.45	2717	2.1	13.41	105	197	Off Idle	53.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.36	15.2	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:3	35.45	2717	2.1	13.42	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.37	15.18	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:3	35.45	2717	2.1	13.41	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.37	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:58:4	35.45	2718	2.1	13.4	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.36	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:58:4	35.45	2718	2.1	13.41	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.33	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:58:4	35.45	2722	2.1	13.41	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.37	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:58:4	35.45	2748	2.1	13.41	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.32	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:4	35.45	2727	2.1	13.42	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.33	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:4	35.45	2727	2.1	13.43	105	197	Off Idle	53.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.35	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:4	35.45	2727	2.1	13.42	105	197	Off Idle	53.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.35	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:58:5	35.45	2710	2.1	13.41	105	197	Off Idle	53.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.37	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:58:5	35.45	2726	2.1	13.43	105	197	Off Idle	54	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.4	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:58:5	35.45	2726	2.1	13.43	105	197	Off Idle	54	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.39	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:5	35.45	2723	2.1	13.42	105	197	Off Idle	54	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.39	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:5	35.45	2719	2.1	13.43	105	197	Off Idle	54	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.38	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:5	35.45	2719	2.1	13.43	105	197	Off Idle	54	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.37	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:6	35.45	2720	2.1	13.41	105	197	Off Idle	54.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.36	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:6	35.45	2716	2.1	13.41	105	197	Off Idle	54	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.34	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:6	35.45	2717	2.1	13.42	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.36	15.14	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:6	35.45	2718	2.1	13.42	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.37	15.17	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:6	35.45	2718	2.1	13.41	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.34	15.17	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:6	35.45	2722	2.1	13.42	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.34	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:6	35.45	2726	2.1	13.43	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.34	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:7	35.45	2728	2.1	13.41	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.32	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:7	35.45	2727	2.1	13.43	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.36	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:7	35.45	2726	2.1	13.43	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.38	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:7	35.45	2732	2.1	13.44	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.39	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:7	35.45	2744	2.1	13.44	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.37	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:7	35.45	2730	2.1	13.44	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.39	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:58:8	35.45	2732	2.1	13.43	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.37	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:58:8	35.45	2732	2.1	13.44	105	197	Off Idle	53.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.39	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:8	35.45	2730	2.1	13.44	105	197	Off Idle	53.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.37	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:8	35.45	2727	2.1	13.44	105	197	Off Idle	53.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.39	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:8	35.45	2727	2.1	13.43	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.39	14.76	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:8	35.45	2721	2.1	13.43	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.38	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:9	35.45	2717	2.1	13.42	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.38	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:9	35.45	2714	2.1	13.42	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.33	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:9	35.45	2714	2.1	13.42	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.34	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:9	35.45	2719	2.1	13.41	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.34	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:58:9	35.45	2724	2.1	13.43	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.34	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:9	35.45	2724	2.1	13.43	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.35	14.9	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:58:9	35.45	2730	2.1	13.42	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.32	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:0	35.45	2729	2.1	13.44	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.37	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:0	35.45	2730	2.1	13.44	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.38	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:0	35.45	2734	2.1	13.45	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.37	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:0	35.45	2729	2.1	13.44	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.37	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:0	35.45	2727	2.11	13.44	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.39	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:0	35.45	2725	2.11	13.44	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.36	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:1	35.45	2712	2.11	13.44	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.35	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:1	35.45	2724	2.11	13.44	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.31	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:1	35.45	2724	2.11	13.45	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.32	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:1	35.45	2726	2.11	13.44	105	197	Off Idle	53.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.3	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:1	35.45	2728	2.11	13.44	105	197	Off Idle	53.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.31	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:1	35.45	2727	2.11	13.43	105	197	Off Idle	53.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.35	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:1	35.45	2728	2.11	13.44	105	197	Off Idle	53.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.37	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:2	35.45	2731	2.11	13.42	105	197	Off Idle	53.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.35	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:2	35.45	2732	2.11	13.44	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.34	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:2	35.45	2737	2.11	13.44	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.36	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:2	35.45	2736	2.11	13.43	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.36	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:2	35.45	2732	2.11	13.44	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.38	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:2	35.45	2729	2.11	13.43	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.37	15.05	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:3	35.45	2736	2.11	13.43	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.39	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:3	35.45	2720	2.11	13.42	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.38	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:3	35.45	2720	2.11	13.43	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.39	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:3	35.45	2718	2.11	13.43	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.39	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:3	35.45	2712	2.11	13.43	105	197	Off Idle	53.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.39	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:3	35.45	2727	2.11	13.44	105	197	Off Idle	53.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.44	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:4	35.45	2727	2.11	13.43	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.42	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:4	35.45	2728	2.11	13.43	105	197	Off Idle	53.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.42	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:4	35.45	2732	2.11	13.42	105	197	Off Idle	53.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.42	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:4	35.45	2732	2.11	13.41	105	197	Off Idle	53.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.42	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:4	35.45	2733	2.11	13.42	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.41	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:4	35.45	2729	2.11	13.45	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.4	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:4	35.45	2728	2.11	13.45	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.39	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:5	35.45	2730	2.11	13.45	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.37	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:5	35.45	2730	2.11	13.45	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.39	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:5	35.45	2734	2.11	13.44	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.37	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:5	35.45	2741	2.11	13.44	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.34	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:5	35.45	2764	2.11	13.44	105	197	Off Idle	53.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.36	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:5	35.45	2753	2.11	13.45	105	197	Off Idle	53.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.36	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:6	35.45	2739	2.11	13.44	105	197	Off Idle	53	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.36	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:6	35.45	2734	2.11	13.43	105	197	Off Idle	53	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.37	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:6	35.45	2720	2.11	13.41	105	197	Off Idle	53.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.36	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:6	35.45	2722	2.11	13.41	105	197	Off Idle	53.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.34	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:6	35.45	2720	2.11	13.41	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.35	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:6	35.45	2720	2.11	13.4	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.37	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:6	35.45	2719	2.11	13.41	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.35	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:7	35.45	2726	2.11	13.43	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.37	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:7	35.45	2729	2.11	13.44	105	197	Off Idle	53.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.36	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:7	35.45	2733	2.11	13.44	105	197	Off Idle	53.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.34	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:7	35.45	2742	2.11	13.43	105	197	Off Idle	53.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.27	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:7	35.45	2766	2.11	13.45	105	197	Off Idle	53.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.32	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:7	35.45	2756	2.11	13.44	105	197	Off Idle	53.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.31	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:8	35.45	2748	2.12	13.42	105	197	Off Idle	53.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.3	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:8	35.45	2744	2.12	13.44	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.33	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:8	35.45	2744	2.12	13.44	105	197	Off Idle	53.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.33	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:8	35.45	2741	2.12	13.42	105	197	Off Idle	53.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.29	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:18:59:8	35.45	2739	2.12	13.42	105	197	Off Idle	53.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.28	14.9	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:8	35.45	2737	2.12	13.43	105	197	Off Idle	52.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.26	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:18:59:9	35.45	2738	2.12	13.42	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.24	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:9	35.45	2724	2.12	13.44	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.24	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:9	35.45	2736	2.13	13.42	105	197	Off Idle	53	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.2	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:9	35.45	2737	2.13	13.44	105	197	Off Idle	53.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.2	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:9	35.45	2742	2.13	13.45	105	197	Off Idle	53.1	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.22	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:9	35.45	2745	2.13	13.43	105	197	Off Idle	52.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.15	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:18:59:9	35.45	2746	2.13	13.44	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.16	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:0	35.45	2742	2.14	13.44	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.15	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:00:0	35.45	2746	2.14	13.43	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.16	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:00:0	35.45	2746	2.14	13.41	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.14	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:0	35.45	2746	2.15	13.41	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.13	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:0	35.45	2749	2.15	13.44	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.13	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:0	35.45	2748	2.15	13.43	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.07	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:1	35.45	2748	2.15	13.43	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.06	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:1	35.45	2746	2.15	13.43	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.02	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:1	35.45	2742	2.16	13.43	105	197	Off Idle	52.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.04	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:1	35.45	2743	2.16	13.43	105	197	Off Idle	52.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.04	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:1	35.45	2743	2.16	13.43	105	197	Off Idle	52.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.05	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:1	35.45	2740	2.16	13.42	105	197	Off Idle	52.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.04	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:1	35.45	2743	2.16	13.43	105	197	Off Idle	52.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.06	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:2	35.45	2744	2.16	13.44	105	197	Off Idle	52.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.07	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:2	35.45	2751	2.17	13.42	105	197	Off Idle	52.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.03	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:2	35.45	2754	2.17	13.44	105	197	Off Idle	52.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.05	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:2	35.45	2756	2.17	13.44	105	197	Off Idle	52.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.06	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:2	35.45	2758	2.17	13.44	105	197	Off Idle	52.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.08	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:2	35.45	2762	2.17	13.43	105	197	Off Idle	52.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.09	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:3	35.45	2745	2.17	13.42	105	197	Off Idle	52.4	0	2	132	944 Turbo	0.18	Rich	1	14.6	-7.1	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:3	35.45	2744	2.17	13.43	105	197	Off Idle	52.2	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.09	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:3	35.45	2745	2.17	13.43	105	197	Off Idle	52.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.08	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:3	35.45	2724	2.17	13.43	105	197	Off Idle	52.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.03	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:3	35.45	2734	2.17	13.42	105	197	Off Idle	52.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.01	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:3	35.45	2750	2.17	13.44	105	197	Off Idle	52.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.02	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:4	35.45	2750	2.17	13.44	105	197	Off Idle	52.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.02	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:4	35.45	2749	2.17	13.43	105	197	Off Idle	52.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.03	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:4	35.45	2749	2.17	13.45	105	197	Off Idle	52.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.03	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:4	35.45	2750	2.17	13.43	105	197	Off Idle	52.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:4	35.45	2755	2.17	13.44	105	197	Off Idle	52.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.01	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:4	35.45	2755	2.17	13.45	105	197	Off Idle	52.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.04	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:4	35.45	2777	2.17	13.44	105	197	Off Idle	52.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:5	35.45	2756	2.17	13.45	105	197	Off Idle	52.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.06	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:5	35.45	2755	2.17	13.44	105	197	Off Idle	52.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.05	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:5	35.45	2758	2.17	13.44	105	197	Off Idle	52.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.06	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:5	35.45	2736	2.17	13.43	105	197	Off Idle	52.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.05	14.9	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:5	35.45	2736	2.17	13.43	105	197	Off Idle	52.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.06	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:5	35.45	2756	2.17	13.43	105	197	Off Idle	52	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.07	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:6	35.45	2755	2.17	13.42	105	197	Off Idle	52	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.09	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:6	35.45	2757	2.17	13.41	105	197	Off Idle	52	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.08	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:6	35.45	2757	2.17	13.42	105	197	Off Idle	52	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.13	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:6	35.45	2757	2.17	13.41	105	197	Off Idle	52	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.1	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:6	35.45	2757	2.17	13.42	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.06	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:6	35.45	2757	2.17	13.43	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.07	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:6	35.45	2757	2.17	13.42	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.02	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:7	35.45	2756	2.17	13.43	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:7	35.45	2755	2.17	13.43	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.03	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:7	35.45	2754	2.17	13.43	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:7	35.45	2751	2.17	13.43	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-7.01	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:00:7	35.45	2751	2.17	13.44	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.04	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:7	35.45	2748	2.17	13.44	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.05	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:8	35.45	2754	2.17	13.43	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.04	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:8	35.45	2753	2.17	13.43	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.03	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:8	35.45	2756	2.18	13.42	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.04	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:8	35.45	2762	2.18	13.42	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:00:8	35.45	2764	2.18	13.41	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.99	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:8	35.45	2769	2.18	13.42	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.98	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:9	35.45	2765	2.18	13.43	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.02	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:9	35.45	2764	2.18	13.44	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:9	35.45	2763	2.18	13.44	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.01	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:9	35.45	2764	2.18	13.44	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.97	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:9	35.45	2765	2.18	13.44	105	197	Off Idle	52	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.97	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:9	35.45	2765	2.18	13.43	105	197	Off Idle	52	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.94	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:00:9	35.45	2765	2.18	13.43	105	197	Off Idle	52	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.93	14.75	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:0	35.45	2762	2.18	13.42	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.91	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:0	35.45	2759	2.19	13.43	104	197	Off Idle	51.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.92	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:0	35.45	2760	2.19	13.42	104	197	Off Idle	51.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.9	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:0	35.45	2760	2.19	13.42	104	197	Off Idle	51.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.92	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:0	35.45	2762	2.19	13.43	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.89	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:0	35.45	2755	2.19	13.43	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.89	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:1	35.45	2758	2.19	13.43	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.89	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:1	35.45	2758	2.19	13.43	105	197	Off Idle	51.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.87	15.08	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:1	35.45	2760	2.19	13.42	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.86	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:1	35.45	2761	2.19	13.43	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.87	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:1	35.45	2768	2.19	13.42	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.88	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:1	35.45	2768	2.19	13.44	105	197	Off Idle	51.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.89	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:1	35.45	2767	2.19	13.43	105	197	Off Idle	51.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.92	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:2	35.45	2766	2.19	13.43	105	197	Off Idle	51.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.89	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:2	35.45	2766	2.19	13.41	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.92	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:2	35.45	2765	2.19	13.42	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.92	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:2	35.45	2762	2.19	13.41	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.96	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:2	35.45	2761	2.19	13.41	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.98	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:2	35.45	2760	2.19	13.43	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.01	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:3	35.45	2760	2.19	13.44	105	197	Off Idle	51.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.02	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:3	35.45	2761	2.19	13.45	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.04	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:3	35.45	2787	2.19	13.44	105	197	Off Idle	51	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.01	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:3	35.45	2787	2.19	13.44	105	197	Off Idle	51	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.02	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:3	35.45	2765	2.19	13.44	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.01	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:3	35.45	2766	2.18	13.44	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.99	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:4	35.45	2766	2.18	13.44	105	197	Off Idle	51.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.01	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:4	35.45	2768	2.18	13.45	105	197	Off Idle	51.1	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.05	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:4	35.45	2768	2.18	13.44	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.03	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:4	35.45	2767	2.18	13.45	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.05	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:4	35.45	2765	2.18	13.44	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.06	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:4	35.45	2761	2.18	13.43	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.07	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:4	35.45	2761	2.18	13.42	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.07	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:5	35.45	2758	2.18	13.42	105	197	Off Idle	51.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.07	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:5	35.45	2757	2.17	13.41	105	197	Off Idle	51.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.11	15.03	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:5	35.45	2758	2.17	13.41	104	197	Off Idle	51.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.08	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:5	35.45	2758	2.17	13.42	104	197	Off Idle	51.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.11	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:5	35.45	2762	2.17	13.4	104	197	Off Idle	51.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.13	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:5	35.45	2762	2.17	13.42	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.1	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:6	35.45	2768	2.17	13.42	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.11	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:6	35.45	2781	2.17	13.43	105	197	Off Idle	51.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.1	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:6	35.45	2781	2.17	13.42	105	197	Off Idle	51.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.15	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:6	35.45	2785	2.16	13.43	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.17	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:6	35.45	2784	2.16	13.42	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.19	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:01:6	35.45	2780	2.16	13.44	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.24	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:6	35.45	2778	2.16	13.45	105	197	Off Idle	51.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.26	14.74	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:7	35.45	2778	2.16	13.44	104	197	Off Idle	51.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.22	14.72	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:7	35.45	2769	2.16	13.44	104	197	Off Idle	51.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.24	14.73	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:7	35.45	2767	2.16	13.44	104	197	Off Idle	51.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.22	14.76	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:7	35.45	2768	2.16	13.44	105	197	Off Idle	51.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.2	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:7	35.45	2768	2.16	13.43	105	197	Off Idle	51.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.22	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:7	35.45	2769	2.16	13.43	105	197	Off Idle	51.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.22	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:8	35.45	2766	2.16	13.42	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.16	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:8	35.45	2768	2.16	13.42	105	197	Off Idle	51.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.18	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:8	35.45	2774	2.15	13.43	105	197	Off Idle	51	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.18	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:8	35.45	2775	2.15	13.43	105	197	Off Idle	50.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.15	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:8	35.45	2775	2.15	13.44	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.17	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:8	35.45	2781	2.15	13.44	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.19	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:9	35.45	2783	2.15	13.45	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.19	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:9	35.45	2781	2.15	13.44	105	197	Off Idle	50.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.22	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:01:9	35.45	2776	2.16	13.44	105	197	Off Idle	50.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.22	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:9	35.45	2773	2.16	13.43	105	197	Off Idle	50.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.22	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:9	35.45	2775	2.16	13.43	105	197	Off Idle	50.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.22	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:01:9	35.45	2776	2.16	13.42	105	197	Off Idle	50.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.18	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:01:9	35.45	2775	2.16	13.42	105	197	Off Idle	50.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.16	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:02:0	35.45	2774	2.16	13.43	105	197	Off Idle	50.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.16	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:0	35.45	2770	2.16	13.43	105	197	Off Idle	50.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.16	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:0	35.45	2770	2.16	13.44	105	197	Off Idle	50.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.16	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:0	35.45	2770	2.16	13.46	105	197	Off Idle	50.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.17	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:0	35.45	2772	2.16	13.45	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.17	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:0	35.45	2776	2.16	13.44	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.16	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:1	35.45	2776	2.15	13.45	105	197	Off Idle	50.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.19	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:1	35.45	2776	2.15	13.43	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.18	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:1	35.45	2776	2.15	13.44	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.16	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:1	35.45	2775	2.15	13.44	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.21	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:1	35.45	2776	2.15	13.44	105	197	Off Idle	51	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.22	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:1	35.45	2783	2.15	13.43	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.24	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:1	35.45	2772	2.15	13.44	105	197	Off Idle	51	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.27	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:2	35.45	2771	2.15	13.43	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.29	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:2	35.45	2764	2.15	13.42	105	197	Off Idle	51	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.25	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:2	35.45	2746	2.15	13.43	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.25	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:2	35.45	2766	2.15	13.44	105	197	Off Idle	51.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.25	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:2	35.45	2767	2.15	13.43	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.22	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:2	35.45	2773	2.15	13.44	105	197	Off Idle	51.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.25	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:3	35.45	2773	2.15	13.44	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.24	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:3	35.45	2788	2.15	13.44	105	197	Off Idle	51.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.27	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:3	35.45	2783	2.15	13.44	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.31	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:3	35.45	2782	2.15	13.44	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.32	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:3	35.45	2782	2.15	13.44	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.3	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:3	35.45	2780	2.15	13.43	105	197	Off Idle	51.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.32	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:4	35.45	2775	2.15	13.41	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.27	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:4	35.45	2769	2.15	13.41	105	197	Off Idle	51.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.24	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:4	35.45	2769	2.15	13.42	104	197	Off Idle	51.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.26	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:4	35.45	2765	2.15	13.41	104	197	Off Idle	51	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.23	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:4	35.45	2767	2.15	13.42	104	197	Off Idle	50.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.23	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:4	35.45	2766	2.15	13.43	105	197	Off Idle	50.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.25	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:4	35.45	2767	2.15	13.44	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.23	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:5	35.45	2782	2.15	13.43	105	197	Off Idle	50.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.23	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:5	35.45	2778	2.15	13.43	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.23	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:5	35.45	2780	2.15	13.43	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.2	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:5	35.45	2787	2.15	13.43	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.19	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:5	35.45	2787	2.15	13.43	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.21	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:02:8	35.45	2786	2.15	13.43	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.19	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:6	35.45	2785	2.15	13.42	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.22	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:6	35.45	2780	2.15	13.42	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.22	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:6	35.45	2780	2.15	13.42	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.25	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:6	35.45	2795	2.15	13.42	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.23	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:6	35.45	2773	2.15	13.42	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.24	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:6	35.45	2772	2.15	13.43	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.21	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:6	35.45	2764	2.15	13.43	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.22	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:7	35.45	2762	2.16	13.43	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.18	15.03	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:7	35.45	2764	2.16	13.44	105	197	Off Idle	50.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.18	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:7	35.45	2770	2.16	13.44	105	197	Off Idle	50.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.21	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:7	35.45	2782	2.16	13.44	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.2	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:7	35.45	2782	2.16	13.44	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.19	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:7	35.45	2782	2.16	13.43	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.2	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:8	35.45	2794	2.16	13.43	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.21	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:8	35.45	2792	2.16	13.43	104	197	Off Idle	50.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.22	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:8	35.45	2791	2.16	13.43	104	197	Off Idle	50.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.2	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:02:8	35.45	2786	2.16	13.43	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.22	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:8	35.45	2787	2.16	13.44	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.27	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:8	35.45	2784	2.16	13.44	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.25	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:9	35.45	2774	2.16	13.44	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.23	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:9	35.45	2768	2.15	13.44	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.22	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:9	35.45	2769	2.15	13.43	105	197	Off Idle	50.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.18	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:9	35.45	2768	2.15	13.43	105	197	Off Idle	50.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.18	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:9	35.45	2774	2.15	13.43	105	197	Off Idle	50.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.17	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:9	35.45	2780	2.15	13.43	105	197	Off Idle	50.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.19	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:02:9	35.45	2782	2.15	13.42	105	197	Off Idle	50.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.2	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:0	35.45	2785	2.15	13.43	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.2	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:0	35.45	2789	2.15	13.43	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.24	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:0	35.45	2787	2.15	13.42	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.19	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:0	35.45	2788	2.15	13.42	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.23	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:0	35.45	2787	2.15	13.43	105	197	Off Idle	50.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.22	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:0	35.45	2783	2.15	13.43	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.22	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:1	35.45	2783	2.15	13.44	105	197	Off Idle	50.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.21	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:1	35.45	2782	2.15	13.45	105	197	Off Idle	50.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.27	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:1	35.45	2782	2.15	13.45	105	197	Off Idle	50.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.23	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:1	35.45	2782	2.15	13.45	105	197	Off Idle	50.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.23	14.75	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:1	35.45	2782	2.15	13.45	105	197	Off Idle	50.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.23	14.75	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:1	35.45	2783	2.16	13.44	104	197	Off Idle	50.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.23	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:1	35.45	2788	2.16	13.44	104	197	Off Idle	50.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.19	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:2	35.45	2793	2.16	13.44	104	197	Off Idle	50	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.2	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:2	35.45	2793	2.16	13.44	104	197	Off Idle	49.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.23	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:2	35.45	2786	2.16	13.42	104	197	Off Idle	49.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.2	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:2	35.45	2779	2.16	13.42	104	197	Off Idle	49.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.2	14.9	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:2	35.45	2780	2.16	13.42	104	197	Off Idle	49.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.2	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:2	35.45	2778	2.16	13.42	104	197	Off Idle	50	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.17	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:3	35.45	2777	2.16	13.42	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.16	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:3	35.45	2772	2.16	13.43	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.17	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:3	35.45	2782	2.16	13.42	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.17	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:3	35.45	2778	2.16	13.43	105	197	Off Idle	50.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.17	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:3	35.45	2784	2.16	13.43	105	197	Off Idle	50.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.2	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:3	35.45	2784	2.16	13.43	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.2	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:4	35.45	2784	2.16	13.41	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.22	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:4	35.45	2784	2.16	13.43	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.22	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:4	35.45	2786	2.15	13.42	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.22	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:4	35.45	2792	2.15	13.43	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.24	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:4	35.45	2795	2.15	13.43	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.26	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:4	35.45	2796	2.15	13.44	105	197	Off Idle	50.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.23	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:03:4	35.45	2792	2.15	13.45	104	197	Off Idle	50.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.23	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:5	35.45	2786	2.15	13.43	104	197	Off Idle	50.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.22	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:5	35.45	2786	2.15	13.42	104	197	Off Idle	50.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.23	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:5	35.45	2784	2.15	13.43	104	197	Off Idle	50.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.2	14.9	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:5	35.45	2780	2.15	13.43	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.2	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:5	35.45	2781	2.15	13.41	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.21	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:5	35.45	2781	2.15	13.43	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.21	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:6	35.45	2787	2.15	13.44	105	197	Off Idle	50	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.21	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:6	35.45	2789	2.15	13.44	105	197	Off Idle	50	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.21	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:6	35.45	2789	2.15	13.44	105	197	Off Idle	50	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.21	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:6	35.45	2794	2.15	13.44	105	197	Off Idle	50	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.23	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:6	35.45	2795	2.15	13.43	105	197	Off Idle	50	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.22	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:6	35.45	2794	2.15	13.43	105	197	Off Idle	50	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.21	15.03	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:6	35.45	2798	2.16	13.42	105	197	Off Idle	50	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.22	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:7	35.45	2795	2.16	13.43	105	197	Off Idle	49.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.22	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:7	35.45	2789	2.16	13.43	104	197	Off Idle	49.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.2	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:7	35.45	2789	2.16	13.44	104	197	Off Idle	49.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.21	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:7	35.45	2787	2.16	13.44	104	197	Off Idle	49.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.23	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:7	35.45	2787	2.16	13.44	105	197	Off Idle	49.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.23	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:7	35.45	2787	2.16	13.42	105	197	Off Idle	49.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.24	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:03:8	35.45	2788	2.16	13.41	105	197	Off Idle	49.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.21	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:03:8	35.45	2791	2.16	13.42	105	197	Off Idle	49.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.22	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:03:8	35.45	2790	2.16	13.41	105	197	Off Idle	49.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.19	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:03:8	35.45	2790	2.16	13.41	105	197	Off Idle	49.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.2	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:8	35.45	2793	2.16	13.43	104	197	Off Idle	49.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.22	14.9	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:8	35.45	2791	2.16	13.42	104	197	Off Idle	49.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.23	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:9	35.45	2791	2.16	13.43	104	197	Off Idle	49.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.27	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:9	35.45	2787	2.16	13.42	105	197	Off Idle	49.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.26	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:9	35.45	2784	2.15	13.42	105	197	Off Idle	49.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.26	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:9	35.45	2784	2.15	13.42	104	197	Off Idle	50	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.27	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:9	35.45	2789	2.15	13.43	104	197	Off Idle	50.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.28	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:9	35.45	2785	2.15	13.43	104	197	Off Idle	50.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.27	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:03:9	35.45	2785	2.15	13.43	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.29	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:04:0	35.45	2793	2.15	13.43	105	197	Off Idle	50.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.3	15.05	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:04:0	35.45	2799	2.15	13.44	105	197	Off Idle	50.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.34	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:04:0	35.45	2797	2.14	13.44	104	197	Off Idle	50	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.38	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:04:0	35.45	2795	2.14	13.44	104	197	Off Idle	50	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.37	14.9	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:04:0	35.45	2793	2.14	13.44	104	197	Off Idle	50	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.4	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:04:0	35.45	2790	2.14	13.44	104	197	Off Idle	50	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.42	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:04:1	35.45	2790	2.13	13.44	104	197	Off Idle	50	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.46	14.74	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:04:1	35.45	2786	2.13	13.43	104	197	Off Idle	49.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.48	14.72	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:04:1	35.45	2786	2.12	13.44	104	197	Off Idle	49.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.57	14.73	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:04:1	35.45	2785	2.11	13.44	104	197	Off Idle	49.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.63	14.73	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:04:1	35.45	2786	2.1	13.44	104	197	Off Idle	49.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.72	14.73	1	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:04:1	35.45	2783	2.09	13.44	104	197	Off Idle	49.9	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.82	14.74	1	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:04:1	35.45	2782	2.08	13.44	104	197	Off Idle	49.9	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.89	14.75	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:04:2	35.45	2782	2.06	13.44	104	197	Off Idle	49.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.06	14.77	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:2	35.45	2783	2.06	13.45	104	197	Off Idle	49.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.14	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:04:2	35.45	2784	2.03	13.44	104	197	Off Idle	50	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.28	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:04:2	35.45	2786	2.02	13.45	104	197	Off Idle	50.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.41	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:2	35.45	2786	2.01	13.44	104	197	Off Idle	50.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.52	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:2	35.45	2781	1.99	13.43	104	197	Off Idle	50.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.56	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:3	35.45	2777	1.98	13.43	104	197	Off Idle	50.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.67	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:3	35.45	2775	1.96	13.43	104	197	Off Idle	50.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.66	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:3	35.45	2773	1.95	13.43	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.75	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:3	35.45	2773	1.93	13.42	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.78	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:3	35.45	2773	1.92	13.42	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.87	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:3	35.45	2776	1.91	13.42	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.91	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:04:4	35.45	2775	1.9	13.42	104	197	Off Idle	50.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.93	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:4	35.45	2776	1.88	13.42	104	197	Off Idle	50.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.95	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:4	35.45	2776	1.87	13.44	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.99	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:4	35.45	2777	1.87	13.45	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.99	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:4	35.45	2782	1.86	13.45	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.02	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:4	35.45	2784	1.85	13.45	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.05	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:4	35.45	2786	1.85	13.45	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.06	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:5	35.45	2785	1.84	13.44	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.05	14.74	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:5	35.45	2789	1.84	13.46	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.12	14.72	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:5	35.45	2790	1.84	13.44	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.14	14.71	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:5	35.45	2790	1.84	13.45	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.14	14.72	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:04:5	35.45	2784	1.83	13.46	105	197	Off Idle	50.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.15	14.72	1	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:5	35.45	2783	1.83	13.46	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.18	14.75	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:6	35.45	2780	1.83	13.45	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.22	14.76	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:6	36.81	2782	1.83	13.45	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.21	14.77	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:6	36.81	2770	1.83	13.43	104	197	Off Idle	50.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.25	14.77	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:6	36.81	2765	1.82	13.42	104	197	Off Idle	50.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.27	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:6	36.81	2764	1.82	13.42	104	197	Off Idle	50.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.3	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:6	36.81	2762	1.82	13.42	104	197	Off Idle	50.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.28	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:6	36.81	2765	1.81	13.42	104	197	Off Idle	50.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.33	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:7	36.81	2765	1.81	13.43	104	197	Off Idle	50.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.34	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:7	36.81	2767	1.8	13.45	104	197	Off Idle	50.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.35	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:7	36.81	2768	1.8	13.43	104	197	Off Idle	50.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.35	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:7	36.81	2768	1.8	13.43	104	197	Off Idle	50.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.36	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:7	36.81	2770	1.79	13.44	104	197	Off Idle	50.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.36	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:04:7	36.81	2769	1.79	13.44	104	197	Off Idle	50.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.35	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:04:8	36.81	2769	1.79	13.42	104	197	Off Idle	50.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.39	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:04:8	36.81	2771	1.78	13.43	104	197	Off Idle	51	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.38	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:8	36.81	2774	1.78	13.44	104	197	Off Idle	51	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.41	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:8	36.81	2774	1.78	13.45	104	197	Off Idle	50.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.43	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:04:8	36.81	2762	1.78	13.44	104	197	Off Idle	50.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.44	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:04:8	36.81	2772	1.77	13.43	104	197	Off Idle	50.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.43	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:9	36.81	2773	1.77	13.45	104	197	Off Idle	50.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.44	14.76	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:9	36.81	2773	1.77	13.43	104	197	Off Idle	50.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.46	14.76	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:9	36.81	2769	1.77	13.42	104	197	Off Idle	50.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.46	14.75	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:9	36.81	2760	1.77	13.43	104	197	Off Idle	50.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.47	14.77	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:9	36.81	2761	1.76	13.43	104	197	Off Idle	51	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.46	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:9	36.81	2761	1.76	13.43	104	197	Off Idle	51.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.49	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:04:9	36.81	2755	1.76	13.42	104	197	Off Idle	51.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.47	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:0	36.81	2753	1.76	13.44	104	197	Off Idle	51.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.48	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:0	36.81	2754	1.76	13.44	104	197	Off Idle	51.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.49	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:0	36.81	2748	1.76	13.44	104	197	Off Idle	51.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.49	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:0	36.81	2762	1.76	13.44	104	197	Off Idle	51.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.5	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:0	36.81	2760	1.76	13.45	104	197	Off Idle	51.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.51	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:0	36.81	2759	1.76	13.44	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.51	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:1	36.81	2762	1.76	13.45	104	197	Off Idle	52	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.49	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:1	36.81	2741	1.76	13.44	104	197	Off Idle	52	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.51	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:1	36.81	2751	1.75	13.44	104	197	Off Idle	52.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.51	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:1	36.81	2757	1.75	13.44	104	197	Off Idle	52.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.49	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:1	36.81	2744	1.75	13.45	104	197	Off Idle	52.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.53	14.9	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:1	36.81	2756	1.75	13.44	104	197	Off Idle	52.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.53	14.9	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:1	36.81	2768	1.75	13.44	104	197	Off Idle	52.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.54	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:2	36.81	2768	1.75	13.45	104	197	Off Idle	52	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.54	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:2	36.81	2757	1.75	13.44	104	197	Off Idle	52	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.56	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:2	36.81	2746	1.75	13.43	104	197	Off Idle	52	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.52	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:2	36.81	2746	1.75	13.43	104	197	Off Idle	52.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.51	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:2	36.81	2747	1.74	13.42	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.51	15.05	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:2	36.81	2740	1.74	13.42	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.49	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:05:3	36.81	2740	1.74	13.42	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.49	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:3	36.81	2737	1.74	13.43	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.52	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:3	36.81	2741	1.74	13.43	104	197	Off Idle	51.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.51	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:3	36.81	2743	1.74	13.44	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.52	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:3	36.81	2742	1.74	13.45	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.56	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:3	36.81	2746	1.74	13.45	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.55	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:4	36.81	2746	1.74	13.45	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.56	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:4	36.81	2750	1.74	13.45	104	197	Off Idle	51.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.57	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:4	36.81	2754	1.74	13.44	104	197	Off Idle	51.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.57	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:4	36.81	2754	1.74	13.45	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.56	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:4	36.81	2754	1.74	13.44	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.57	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:4	36.81	2757	1.74	13.45	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.57	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:4	36.81	2756	1.74	13.45	104	197	Off Idle	52	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.56	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:5	36.81	2775	1.74	13.44	104	197	Off Idle	52.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.57	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:5	36.81	2775	1.74	13.45	104	197	Off Idle	52.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.61	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:5	36.81	2756	1.73	13.44	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.61	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:5	36.81	2755	1.73	13.45	104	197	Off Idle	52	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.59	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:5	36.81	2755	1.73	13.44	104	197	Off Idle	52	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.6	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:5	36.81	2730	1.73	13.44	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.61	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:6	36.81	2752	1.73	13.42	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.6	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:6	36.81	2748	1.73	13.44	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.58	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:6	36.81	2748	1.73	13.44	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.62	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:6	36.81	2742	1.73	13.43	104	197	Off Idle	51.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.6	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:6	36.81	2737	1.73	13.43	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.61	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:6	36.81	2737	1.73	13.45	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.63	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:6	36.81	2734	1.73	13.44	104	197	Off Idle	51.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.6	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:7	36.81	2709	1.73	13.43	104	197	Off Idle	52	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.64	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:7	36.81	2718	1.73	13.43	104	197	Off Idle	52.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.63	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:7	36.81	2731	1.73	13.42	104	197	Off Idle	52	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.62	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:7	36.81	2742	1.73	13.41	104	197	Off Idle	52.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.6	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:7	36.81	2733	1.73	13.42	104	197	Off Idle	52.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.62	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:7	36.81	2734	1.73	13.42	104	197	Off Idle	52.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.6	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:8	36.81	2732	1.73	13.44	104	197	Off Idle	52.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.61	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:8	36.81	2737	1.73	13.45	104	197	Off Idle	52.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.6	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:8	36.81	2738	1.73	13.44	104	197	Off Idle	52.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.6	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:8	36.81	2742	1.73	13.46	104	197	Off Idle	52.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.6	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:8	36.81	2746	1.73	13.44	104	197	Off Idle	52.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.6	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:8	36.81	2746	1.73	13.44	104	197	Off Idle	53	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.59	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:05:9	36.81	2749	1.72	13.44	104	197	Off Idle	53	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.6	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:9	36.81	2749	1.72	13.43	104	197	Off Idle	53	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.62	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:9	36.81	2747	1.72	13.43	104	197	Off Idle	53	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.62	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:9	36.81	2747	1.72	13.44	104	197	Off Idle	52.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.62	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:9	36.81	2747	1.72	13.42	104	197	Off Idle	52.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.64	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:9	36.81	2747	1.72	13.44	104	197	Off Idle	52.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.62	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:05:9	36.81	2747	1.72	13.45	104	197	Off Idle	52.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.61	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:0	36.81	2748	1.72	13.43	104	197	Off Idle	52.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.6	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:0	36.81	2744	1.72	13.43	104	197	Off Idle	52.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.61	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:0	36.81	2744	1.72	13.44	104	197	Off Idle	52.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.6	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:0	36.81	2738	1.72	13.44	104	197	Off Idle	52.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.63	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:0	36.81	2726	1.72	13.43	104	197	Off Idle	52.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.61	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:0	36.81	2721	1.72	13.44	104	197	Off Idle	52.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.63	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:1	36.81	2709	1.72	13.44	104	197	Off Idle	52.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.63	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:1	36.81	2714	1.72	13.43	104	197	Off Idle	52.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.6	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:1	36.81	2713	1.72	13.44	104	197	Off Idle	52.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.62	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:1	36.81	2711	1.72	13.44	104	197	Off Idle	53	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.64	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:1	36.81	2711	1.72	13.43	104	197	Off Idle	53.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.64	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:1	36.81	2712	1.72	13.44	104	197	Off Idle	53.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.62	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:1	36.81	2712	1.72	13.44	104	197	Off Idle	53.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.64	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:06:2	36.81	2713	1.72	13.42	104	197	Off Idle	53.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.66	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:2	36.81	2712	1.72	13.42	104	197	Off Idle	53.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.65	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:2	36.81	2712	1.71	13.42	104	197	Off Idle	53.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.67	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:2	36.81	2705	1.71	13.42	104	197	Off Idle	54	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.67	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:2	36.81	2707	1.71	13.41	104	197	Off Idle	54.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.66	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:2	36.81	2712	1.71	13.43	104	197	Off Idle	54.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.66	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:3	36.81	2712	1.71	13.43	104	197	Off Idle	54.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.67	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:3	36.81	2719	1.71	13.43	104	197	Off Idle	54.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.67	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:3	36.81	2724	1.71	13.43	104	197	Off Idle	54.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.68	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:3	36.81	2724	1.71	13.44	104	197	Off Idle	54.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.71	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:3	36.81	2728	1.71	13.44	104	197	Off Idle	54.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.69	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:3	36.81	2717	1.7	13.43	104	197	Off Idle	54.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.66	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:4	36.81	2720	1.7	13.44	104	197	Off Idle	54.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.67	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:4	36.81	2710	1.7	13.44	104	197	Off Idle	54.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.67	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:4	36.81	2722	1.7	13.43	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.64	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:4	36.81	2720	1.7	13.43	104	197	Off Idle	53.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.67	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:4	36.81	2718	1.7	13.43	104	197	Off Idle	53.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.65	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:4	36.81	2725	1.7	13.43	104	197	Off Idle	53.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.64	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:4	36.81	2712	1.7	13.43	104	197	Off Idle	53.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.64	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:5	36.81	2705	1.7	13.43	104	197	Off Idle	53.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.64	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:5	36.81	2705	1.7	13.41	104	197	Off Idle	53.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.66	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:5	36.81	2696	1.7	13.43	104	197	Off Idle	53.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.63	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:5	36.81	2708	1.7	13.43	104	197	Off Idle	53.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.64	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:5	36.81	2708	1.7	13.42	104	197	Off Idle	53.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.66	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:5	36.81	2704	1.7	13.44	104	197	Off Idle	53.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.65	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:6	36.81	2706	1.7	13.44	104	197	Off Idle	53.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.64	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:6	36.81	2706	1.7	13.42	104	197	Off Idle	53.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.67	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:6	36.81	2709	1.71	13.43	104	197	Off Idle	53.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.68	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:6	36.81	2714	1.71	13.43	104	197	Off Idle	54	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.67	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:6	36.81	2714	1.7	13.44	104	197	Off Idle	54.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.72	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:6	36.81	2719	1.7	13.45	104	197	Off Idle	54.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.69	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:6	36.81	2719	1.7	13.43	104	197	Off Idle	54.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.71	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:7	36.81	2718	1.7	13.44	104	197	Off Idle	54.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.68	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:06:7	36.81	2718	1.7	13.44	104	197	Off Idle	54.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.7	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:7	36.81	2719	1.7	13.43	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.72	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:7	36.81	2714	1.7	13.43	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.68	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:7	36.81	2710	1.7	13.43	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.68	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:7	36.81	2710	1.7	13.43	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.68	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:8	36.81	2706	1.7	13.42	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.66	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:8	36.81	2710	1.7	13.43	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.66	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:8	36.81	2709	1.7	13.43	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.72	Lean	1	14.6	-9.66	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:8	36.81	2710	1.7	13.42	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.62	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:8	36.81	2712	1.7	13.44	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.63	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:8	36.81	2706	1.7	13.44	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.65	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:9	36.81	2705	1.7	13.44	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.65	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:9	36.81	2705	1.7	13.44	104	197	Off Idle	54.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.69	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:9	36.81	2703	1.7	13.44	104	197	Off Idle	54.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.72	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:9	36.81	2700	1.7	13.42	104	197	Off Idle	54.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.72	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:9	36.81	2699	1.7	13.43	104	197	Off Idle	54.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.72	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:9	36.81	2699	1.7	13.44	104	197	Off Idle	54.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.7	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:06:9	36.81	2696	1.7	13.43	104	197	Off Idle	54.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.7	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:0	36.81	2697	1.7	13.45	104	197	Off Idle	54.8	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.71	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:0	36.81	2692	1.7	13.45	104	197	Off Idle	54.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.72	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:0	36.81	2693	1.7	13.44	104	197	Off Idle	54.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.69	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:0	36.81	2692	1.7	13.45	104	197	Off Idle	54.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.68	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:0	36.81	2692	1.7	13.45	104	197	Off Idle	55	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.72	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:0	36.81	2691	1.7	13.44	104	197	Off Idle	55	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.72	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:1	36.81	2690	1.69	13.42	104	197	Off Idle	55	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.72	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:07:1	36.81	2677	1.69	13.44	104	197	Off Idle	55.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.74	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:1	35.45	2664	1.69	13.45	104	197	Off Idle	55.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.77	14.8	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:1	35.45	2677	1.69	13.44	104	197	Off Idle	55.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.73	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:1	35.45	2676	1.69	13.45	104	197	Off Idle	55.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.74	14.8	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:1	35.45	2684	1.69	13.47	104	197	Off Idle	55.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.76	14.79	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:1	35.45	2690	1.69	13.46	104	197	Off Idle	55.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.72	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:07:2	35.45	2690	1.69	13.45	104	197	Off Idle	55.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.7	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:2	35.45	2702	1.69	13.45	104	197	Off Idle	55.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.73	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:2	35.45	2706	1.69	13.44	104	197	Off Idle	55.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.66	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:2	35.45	2706	1.69	13.45	104	197	Off Idle	55.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.66	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:07:2	35.45	2707	1.69	13.44	104	197	Off Idle	55.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.67	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:07:2	35.45	2701	1.69	13.42	104	197	Off Idle	55.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.65	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:3	36.81	2704	1.69	13.43	104	197	Off Idle	55.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.66	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:3	36.81	2704	1.69	13.42	104	197	Off Idle	55.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.72	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:3	36.81	2699	1.69	13.41	104	197	Off Idle	55.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.7	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:3	36.81	2702	1.69	13.41	104	197	Off Idle	54.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.7	14.94	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:3	36.81	2702	1.69	13.42	104	197	Off Idle	54.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.69	14.94	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:3	36.81	2700	1.69	13.43	104	197	Off Idle	54.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.68	14.94	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:4	36.81	2696	1.69	13.42	104	197	Off Idle	54.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.69	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:4	36.81	2693	1.69	13.44	104	197	Off Idle	54.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.66	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:4	36.81	2693	1.69	13.44	104	197	Off Idle	54.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.68	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:4	36.81	2689	1.69	13.42	104	197	Off Idle	54.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.69	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:4	36.81	2681	1.69	13.42	104	197	Off Idle	54.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.72	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:4	36.81	2676	1.69	13.42	105	197	Off Idle	54.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.71	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:4	36.81	2676	1.69	13.43	105	197	Off Idle	54.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.72	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:5	36.81	2673	1.69	13.42	105	197	Off Idle	54.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.75	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:5	36.81	2669	1.69	13.42	104	197	Off Idle	54.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.72	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:5	36.81	2669	1.69	13.43	104	197	Off Idle	55	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.73	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:5	36.81	2665	1.69	13.43	104	197	Off Idle	55.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.72	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:5	35.45	2645	1.69	13.43	104	197	Off Idle	55.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.74	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:5	35.45	2654	1.69	13.42	104	197	Off Idle	55.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.74	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:6	35.45	2658	1.69	13.44	104	197	Off Idle	55.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.74	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:6	35.45	2661	1.69	13.43	104	197	Off Idle	56	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.73	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:6	35.45	2660	1.69	13.43	104	197	Off Idle	56.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.76	14.8	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:6	35.45	2663	1.69	13.43	104	197	Off Idle	56.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.74	14.78	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:6	35.45	2663	1.69	13.43	104	197	Off Idle	56.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.77	14.78	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:6	35.45	2654	1.68	13.43	104	197	Off Idle	56.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.76	14.77	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:6	35.45	2632	1.68	13.42	104	197	Off Idle	57.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.78	14.78	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:7	35.45	2632	1.68	13.43	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.77	14.78	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:7	35.45	2646	1.68	13.43	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.8	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:7	35.45	2649	1.68	13.42	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.8	14.78	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:7	35.45	2671	1.68	13.43	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.77	14.77	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:7	35.45	2671	1.67	13.44	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.8	14.78	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:7	35.45	2656	1.67	13.42	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.79	14.8	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:8	35.45	2661	1.67	13.43	104	197	Off Idle	57.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.78	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:8	35.45	2661	1.67	13.44	104	197	Off Idle	57.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.8	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:8	35.45	2671	1.67	13.44	104	197	Off Idle	57.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.8	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:8	35.45	2674	1.67	13.43	104	197	Off Idle	57.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.81	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:8	35.45	2677	1.66	13.43	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.78	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:8	35.45	2676	1.66	13.43	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.79	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:9	35.45	2677	1.66	13.44	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.81	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:9	35.45	2676	1.66	13.44	104	197	Off Idle	57.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.81	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:9	35.45	2672	1.66	13.44	104	197	Off Idle	56.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.81	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:9	35.45	2664	1.66	13.44	104	197	Off Idle	56.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.84	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:07:9	35.45	2639	1.66	13.45	104	197	Off Idle	56.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.82	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:07:9	35.45	2639	1.66	13.45	104	197	Off Idle	56.8	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.81	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:07:9	35.45	2654	1.66	13.45	104	197	Off Idle	56.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.82	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:0	35.45	2651	1.66	13.45	104	197	Off Idle	57	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.81	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:08:0	35.45	2672	1.66	13.45	104	197	Off Idle	56.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.77	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:0	35.45	2660	1.66	13.45	104	197	Off Idle	56.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.78	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:0	35.45	2646	1.66	13.45	104	197	Off Idle	56.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.79	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:0	35.45	2648	1.66	13.44	104	197	Off Idle	56.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.77	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:0	35.45	2650	1.66	13.46	104	197	Off Idle	56.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.78	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:1	35.45	2654	1.66	13.45	104	197	Off Idle	56.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.81	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:1	35.45	2659	1.66	13.44	104	197	Off Idle	56.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.8	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:1	35.45	2657	1.66	13.43	104	197	Off Idle	57	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.77	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:1	35.45	2658	1.66	13.44	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.79	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:1	35.45	2648	1.66	13.44	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.77	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:1	35.45	2658	1.66	13.44	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.76	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:1	35.45	2658	1.66	13.45	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.77	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:2	35.45	2658	1.66	13.44	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.77	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:2	35.45	2667	1.66	13.44	104	197	Off Idle	57.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.8	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:2	35.45	2658	1.66	13.44	104	197	Off Idle	57.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.8	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:2	35.45	2656	1.66	13.46	104	197	Off Idle	57.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.77	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:2	35.45	2658	1.66	13.45	104	197	Off Idle	57.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.79	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:2	35.45	2657	1.66	13.43	104	197	Off Idle	57.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.78	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:3	35.45	2652	1.66	13.43	104	197	Off Idle	57.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.77	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:3	35.45	2648	1.66	13.44	104	197	Off Idle	57.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.77	15.05	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:3	35.45	2648	1.66	13.43	104	197	Off Idle	57.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.81	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:3	35.45	2636	1.66	13.41	104	197	Off Idle	57.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.79	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:3	35.45	2642	1.66	13.42	104	197	Off Idle	57.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.78	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:3	35.45	2639	1.66	13.43	104	197	Off Idle	57.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.81	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:4	35.45	2639	1.66	13.41	104	197	Off Idle	57.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.81	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:4	35.45	2636	1.66	13.42	104	197	Off Idle	57.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.78	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:4	35.45	2630	1.66	13.43	104	197	Off Idle	57.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.83	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:4	35.45	2630	1.66	13.44	104	197	Off Idle	57.7	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.81	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:4	35.45	2629	1.66	13.43	104	197	Off Idle	57.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.83	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:4	35.45	2625	1.66	13.43	104	197	Off Idle	57.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.82	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:4	35.45	2616	1.66	13.44	104	197	Off Idle	57.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.81	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:5	35.45	2616	1.66	13.44	104	197	Off Idle	57.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.81	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:5	35.45	2612	1.66	13.44	104	197	Off Idle	58.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.82	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:5	35.45	2610	1.65	13.42	104	197	Off Idle	58.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.84	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:5	35.45	2608	1.65	13.44	104	197	Off Idle	58.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.85	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:5	35.45	2610	1.65	13.43	104	197	Off Idle	58.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.83	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:6	35.45	2620	1.65	13.44	104	197	Off Idle	59.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.84	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:6	35.45	2620	1.65	13.44	104	197	Off Idle	59.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.82	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:6	35.45	2632	1.65	13.45	104	197	Off Idle	59.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.84	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:6	35.45	2636	1.64	13.43	104	197	Off Idle	59.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.85	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:6	35.45	2641	1.64	13.43	104	197	Off Idle	59.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.86	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:6	35.45	2641	1.64	13.45	104	197	Off Idle	59.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.86	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:6	35.45	2652	1.64	13.44	104	197	Off Idle	59.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.87	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:6	35.45	2639	1.64	13.43	104	197	Off Idle	59.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.87	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:7	35.45	2639	1.64	13.44	104	197	Off Idle	59.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.84	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:7	35.45	2640	1.64	13.45	104	197	Off Idle	59	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.83	14.9	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:08:7	35.45	2640	1.64	13.43	104	197	Off Idle	58.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.84	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:7	35.45	2639	1.64	13.44	104	197	Off Idle	58.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.81	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:7	35.45	2630	1.64	13.45	104	197	Off Idle	58.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.81	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:7	35.45	2625	1.64	13.44	104	197	Off Idle	58.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.84	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:8	35.45	2625	1.64	13.44	104	197	Off Idle	58.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.84	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:8	35.45	2612	1.64	13.43	104	197	Off Idle	58.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.84	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:8	35.45	2614	1.64	13.43	104	197	Off Idle	58.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.85	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:8	35.45	2604	1.64	13.44	104	197	Off Idle	58.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.87	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:8	35.45	2604	1.64	13.44	104	197	Off Idle	58.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.87	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:8	35.45	2606	1.64	13.43	104	197	Off Idle	58.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.88	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:9	35.45	2604	1.64	13.43	104	197	Off Idle	58.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.87	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:9	35.45	2608	1.64	13.44	104	197	Off Idle	59.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.86	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:08:9	35.45	2607	1.64	13.44	104	197	Off Idle	59.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.86	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:9	35.45	2608	1.64	13.45	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.85	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:9	35.45	2620	1.64	13.44	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.9	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:08:9	35.45	2621	1.64	13.45	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.88	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:08:9	35.45	2626	1.63	13.44	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.88	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:09:0	35.45	2626	1.63	13.44	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.88	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:09:0	35.45	2627	1.63	13.43	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.91	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:09:0	35.45	2627	1.63	13.42	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.89	14.9	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:0	35.45	2620	1.63	13.42	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.91	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:0	35.45	2616	1.63	13.42	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.89	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:0	35.45	2615	1.63	13.42	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.9	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:1	35.45	2615	1.63	13.42	104	197	Off Idle	59.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.87	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:1	35.45	2612	1.63	13.42	104	197	Off Idle	59.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.85	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:1	35.45	2606	1.63	13.42	104	197	Off Idle	59.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.85	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:1	35.45	2604	1.63	13.43	104	197	Off Idle	59.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.87	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:1	35.45	2601	1.63	13.43	104	197	Off Idle	59.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.84	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:1	35.45	2608	1.63	13.44	104	197	Off Idle	59.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.84	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:1	35.45	2598	1.62	13.45	104	197	Off Idle	59.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.87	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:2	35.45	2595	1.62	13.45	104	197	Off Idle	59.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.88	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:2	35.45	2596	1.62	13.45	104	197	Off Idle	59.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.91	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:2	35.45	2600	1.61	13.45	104	197	Off Idle	59.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.93	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:09:2	35.45	2601	1.61	13.45	104	197	Off Idle	59.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.93	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:09:2	35.45	2602	1.6	13.45	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.96	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:09:2	35.45	2590	1.6	13.43	104	197	Off Idle	59.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.99	14.87	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:3	35.45	2597	1.59	13.45	104	197	Off Idle	59.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.02	14.91	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:3	35.45	2596	1.59	13.44	104	197	Off Idle	59.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.04	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:3	35.45	2599	1.58	13.43	104	197	Off Idle	59.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-10.1	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:3	35.45	2599	1.58	13.43	104	197	Off Idle	60	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.12	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:3	35.45	2610	1.57	13.43	104	197	Off Idle	60.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.14	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:3	35.45	2598	1.56	13.44	104	197	Off Idle	60.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.16	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:4	35.45	2597	1.56	13.43	104	197	Off Idle	60.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.19	15.07	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:4	35.45	2594	1.55	13.42	104	197	Off Idle	60.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.19	15.09	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:4	35.45	2590	1.54	13.43	104	197	Off Idle	60.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.2	15.09	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:4	35.45	2590	1.54	13.43	104	197	Off Idle	60.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.21	15.09	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:4	35.45	2590	1.53	13.44	104	197	Off Idle	60.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.23	15.1	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:4	35.45	2592	1.52	13.42	104	197	Off Idle	60.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.24	15.1	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:4	35.45	2587	1.52	13.44	104	197	Off Idle	60.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.23	15.12	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:5	35.45	2586	1.51	13.43	104	197	Off Idle	60.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.27	15.11	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:5	35.45	2583	1.51	13.43	104	197	Off Idle	60.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.28	15.09	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:5	35.45	2582	1.5	13.44	104	197	Off Idle	60.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.33	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:5	35.45	2582	1.49	13.46	104	197	Off Idle	60.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.37	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:5	35.45	2585	1.48	13.44	104	197	Off Idle	60.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-10.39	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:5	35.45	2586	1.48	13.45	104	197	Full Load	60.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-10.41	14.99	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:6	35.45	2611	1.47	13.45	104	197	Idle	60.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.46	14.94	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:6	35.45	2611	1.47	13.44	104	197	Idle	60.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.47	14.93	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:6	36.81	2610	1.46	13.43	104	197	Idle	61.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.5	14.84	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:6	36.81	2585	1.45	13.44	104	197	Idle	61.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.52	14.78	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:6	36.81	2581	1.44	13.42	104	197	Idle	61.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.53	14.76	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:6	36.81	2580	1.44	13.43	104	197	Idle	61.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.51	14.76	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:6	36.81	2578	1.43	13.42	104	197	Idle	61.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.53	14.76	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:7	36.81	2578	1.42	13.43	104	197	Idle	61.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.54	14.75	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:7	34.08	2555	1.41	13.43	104	197	Idle	61.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.58	14.76	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:7	34.08	2534	1.41	13.43	104	197	Idle	61.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.6	14.78	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:09:7	28.63	2533	1.4	13.43	104	197	Idle	61.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.6	14.78	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:7	23.18	2532	1.4	13.43	104	197	Idle	61.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.61	14.78	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:7	19.09	2524	1.39	13.43	104	197	Idle	61.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.6	14.8	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:8	19.09	2557	1.39	13.43	104	197	Idle	61.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.61	14.84	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:8	19.09	2550	1.38	13.45	104	196	Idle	61.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.6	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:09:8	19.09	2550	1.38	13.44	104	196	Idle	61.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.6	14.87	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:8	19.09	2549	1.38	13.44	104	196	Idle	61.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.59	14.89	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:8	19.09	2545	1.38	13.44	104	197	Idle	61.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.6	14.91	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:8	19.09	2545	1.38	13.43	104	197	Idle	61.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.61	14.95	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:9	19.09	2543	1.38	13.44	104	197	Idle	61.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.59	14.99	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:9	19.09	2545	1.38	13.44	104	197	Idle	61.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.6	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:9	19.09	2545	1.38	13.43	104	197	Idle	61.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-10.56	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:9	19.09	2551	1.38	13.43	104	197	Idle	61.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.5	15.06	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:9	19.09	2556	1.38	13.44	104	197	Idle	61.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-10.5	15.09	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:9	19.09	2556	1.38	13.43	104	197	Idle	61.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.5	15.09	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:09:9	19.09	2560	1.38	13.45	104	197	Idle	61.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.45	15.09	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:0	19.09	2570	1.38	13.43	104	197	Idle	61.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-10.45	15.09	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:0	19.09	2559	1.38	13.44	104	197	Idle	62	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.44	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:0	19.09	2558	1.38	13.45	104	197	Idle	62.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.43	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:0	19.09	2553	1.38	13.46	104	197	Idle	62.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.44	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:0	19.09	2548	1.38	13.45	104	197	Idle	62	0	2	132	944 Turbo	0.34	Rich	1	14.6	-10.42	15.05	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:0	19.09	2536	1.38	13.45	104	197	Idle	62.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-10.4	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:1	19.09	2538	1.38	13.44	104	197	Idle	62.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.4	15.03	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:1	19.09	2523	1.38	13.44	104	197	Idle	62.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.41	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:1	19.09	2523	1.38	13.44	104	197	Idle	62.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.39	15	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:1	19.09	2529	1.38	13.43	104	197	Idle	62.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.38	15	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:1	19.09	2529	1.38	13.43	104	197	Idle	63	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	14.98	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:1	19.09	2528	1.37	13.44	104	197	Idle	63	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	14.98	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:1	19.09	2528	1.37	13.43	104	197	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	14.97	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:2	19.09	2539	1.37	13.43	104	197	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	14.97	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:2	19.09	2531	1.37	13.43	104	197	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	15	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:2	19.09	2529	1.37	13.42	104	197	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	15.08	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:2	19.09	2530	1.37	13.41	104	197	Idle	62.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	15.23	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:2	19.09	2538	1.37	13.42	104	197	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	15.5	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:2	19.09	2526	1.37	13.42	104	197	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	15.88	1.08	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:3	19.09	2526	1.37	13.44	104	197	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	16.37	1.11	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:3	19.09	2520	1.37	13.43	104	197	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	16.89	1.15	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:3	19.09	2518	1.37	13.44	104	197	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	17.67	1.2	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:3	19.09	2514	1.36	13.43	104	197	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	18.19	1.24	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:3	19.09	2512	1.36	13.44	104	197	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	18.7	1.27	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:3	19.09	2508	1.36	13.44	104	197	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	19.18	1.31	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:4	19.09	2489	1.36	13.44	104	197	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	19.6	1.33	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:4	19.09	2510	1.36	13.45	104	197	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.03	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:4	19.09	2510	1.36	13.44	104	197	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.17	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:4	19.09	2510	1.36	13.45	104	197	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:4	19.09	2511	1.36	13.44	104	197	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:4	19.09	2512	1.36	13.45	104	197	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:4	19.09	2511	1.36	13.44	104	197	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:5	19.09	2510	1.35	13.45	104	197	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:5	19.09	2510	1.35	13.45	104	197	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:5	19.09	2506	1.35	13.45	104	197	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:5	19.09	2504	1.35	13.46	104	197	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:5	19.09	2498	1.35	13.45	104	197	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:5	19.09	2498	1.35	13.44	104	197	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:6	19.09	2494	1.35	13.45	104	197	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:6	19.09	2492	1.34	13.45	104	197	Idle	64.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:6	19.09	2492	1.34	13.43	104	197	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:6	19.09	2489	1.34	13.44	104	197	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:6	19.09	2488	1.34	13.44	104	197	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:6	19.09	2488	1.34	13.43	104	197	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:6	19.09	2488	1.34	13.45	104	197	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:7	19.09	2488	1.34	13.44	104	197	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:7	19.09	2489	1.34	13.44	104	197	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:10:7	19.09	2488	1.33	13.43	104	197	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:7	19.09	2485	1.33	13.44	104	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:7	19.09	2484	1.33	13.43	104	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:7	19.09	2484	1.33	13.44	104	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:8	19.09	2481	1.33	13.43	104	197	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:8	19.09	2478	1.33	13.44	104	197	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:8	19.09	2478	1.33	13.44	104	197	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:8	19.09	2475	1.33	13.44	104	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:8	19.09	2472	1.32	13.42	104	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:8	19.09	2470	1.32	13.43	104	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:9	19.09	2470	1.32	13.42	104	196	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:9	19.09	2469	1.32	13.44	104	196	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:9	19.09	2468	1.32	13.43	104	196	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:9	19.09	2468	1.32	13.44	104	197	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:9	19.09	2468	1.32	13.43	104	197	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:9	19.09	2465	1.32	13.44	104	197	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:10:9	19.09	2465	1.32	13.43	104	197	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:0	19.09	2463	1.32	13.43	104	197	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:0	19.09	2463	1.32	13.44	104	197	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:0	19.09	2460	1.32	13.44	104	197	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:0	19.09	2457	1.32	13.43	104	197	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:0	19.09	2456	1.31	13.43	104	197	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:0	19.09	2443	1.31	13.42	104	197	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:1	19.09	2450	1.31	13.43	104	197	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:1	19.09	2450	1.31	13.44	104	197	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:1	19.09	2449	1.31	13.44	104	197	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:1	19.09	2448	1.3	13.44	104	197	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:1	19.09	2448	1.3	13.45	104	197	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:1	19.09	2460	1.3	13.46	104	197	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:1	19.09	2450	1.3	13.44	104	197	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:2	19.09	2440	1.3	13.43	104	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:2	19.09	2448	1.29	13.43	104	197	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:2	19.09	2456	1.29	13.43	104	197	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:2	17.72	2424	1.29	13.42	104	197	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:2	17.72	2432	1.28	13.43	104	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:2	19.09	2448	1.28	13.44	104	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:3	19.09	2436	1.28	13.44	104	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:3	19.09	2436	1.28	13.45	104	197	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:3	19.09	2423	1.27	13.44	104	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:3	19.09	2428	1.27	13.43	104	197	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:3	19.09	2427	1.27	13.43	104	197	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:3	19.09	2426	1.27	13.44	104	197	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:4	19.09	2426	1.27	13.43	104	197	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:4	19.09	2416	1.27	13.42	104	197	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:4	17.72	2404	1.26	13.44	104	197	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:4	17.72	2412	1.26	13.43	104	197	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:4	17.72	2428	1.26	13.43	104	197	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:4	17.72	2416	1.26	13.45	104	197	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:4	17.72	2416	1.26	13.45	104	196	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:5	17.72	2413	1.26	13.43	104	196	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:5	17.72	2410	1.26	13.44	104	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:5	17.72	2390	1.26	13.43	104	197	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:5	17.72	2400	1.25	13.43	104	197	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:5	17.72	2418	1.25	13.43	104	197	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:5	17.72	2407	1.25	13.43	104	197	Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:6	17.72	2406	1.25	13.44	104	197	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:6	17.72	2407	1.25	13.44	104	197	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:6	17.72	2407	1.25	13.43	104	197	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:11:6	17.72	2397	1.24	13.44	104	197	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:6	17.72	2405	1.24	13.44	104	197	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:6	17.72	2405	1.24	13.43	104	197	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:6	17.72	2404	1.24	13.45	104	197	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:7	17.72	2402	1.24	13.44	104	197	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:7	17.72	2422	1.23	13.43	104	197	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:7	17.72	2412	1.23	13.44	104	197	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:7	17.72	2390	1.23	13.42	104	197	Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:7	17.72	2396	1.23	13.42	104	197	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:7	17.72	2393	1.22	13.43	104	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:8	17.72	2393	1.22	13.44	104	197	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:8	17.72	2390	1.22	13.44	104	197	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:8	17.72	2386	1.22	13.45	104	197	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:8	17.72	2385	1.22	13.44	104	197	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:8	17.72	2380	1.22	13.44	104	197	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:8	17.72	2377	1.21	13.44	104	197	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:9	17.72	2378	1.21	13.43	104	197	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:9	17.72	2376	1.21	13.43	104	197	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:9	17.72	2375	1.21	13.43	104	197	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:9	17.72	2374	1.21	13.43	104	197	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:9	17.72	2374	1.2	13.43	104	197	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:9	17.72	2372	1.2	13.43	104	197	Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:11:9	17.72	2372	1.2	13.42	104	197	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:0	17.72	2371	1.2	13.42	104	197	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:0	17.72	2372	1.2	13.43	104	197	Idle	71.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:0	17.72	2371	1.2	13.43	104	197	Idle	71.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:0	17.72	2368	1.2	13.43	104	197	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:0	17.72	2367	1.19	13.43	104	197	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:0	17.72	2366	1.19	13.43	104	197	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:1	17.72	2364	1.19	13.43	104	197	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:1	17.72	2362	1.19	13.42	104	197	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:1	17.72	2361	1.19	13.43	104	197	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:1	17.72	2361	1.18	13.43	104	197	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:1	17.72	2358	1.18	13.44	104	197	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:1	17.72	2359	1.18	13.42	104	197	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:1	17.72	2359	1.18	13.43	104	197	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:2	17.72	2356	1.18	13.43	104	197	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:2	17.72	2354	1.17	13.42	104	197	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.03	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:2	17.72	2354	1.17	13.41	104	197	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.03	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:2	17.72	2352	1.17	13.43	104	197	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.04	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:2	17.72	2351	1.17	13.44	104	197	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.04	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:2	17.72	2356	1.17	13.44	104	197	Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.04	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:3	17.72	2356	1.17	13.44	104	197	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.04	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:3	17.72	2350	1.17	13.43	104	197	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.04	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:3	17.72	2347	1.16	13.43	104	197	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.04	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:3	17.72	2346	1.16	13.43	104	197	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.05	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:3	17.72	2345	1.16	13.43	104	197	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.06	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:3	17.72	2342	1.16	13.42	104	197	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:4	17.72	2342	1.16	13.42	104	197	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:4	17.72	2331	1.16	13.44	104	197	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:4	17.72	2336	1.16	13.44	104	197	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:4	17.72	2333	1.15	13.44	104	197	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:4	17.72	2333	1.15	13.45	104	197	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:4	17.72	2331	1.15	13.44	104	197	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:4	17.72	2328	1.15	13.45	104	197	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:5	17.72	2328	1.15	13.43	104	197	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:5	17.72	2334	1.15	13.43	104	197	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:5	17.72	2316	1.15	13.44	104	197	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:12:5	17.72	2314	1.15	13.43	104	197	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:5	17.72	2314	1.14	13.43	104	197	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:5	17.72	2319	1.14	13.43	104	197	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:6	17.72	2319	1.14	13.42	104	197	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:6	17.72	2318	1.14	13.42	104	197	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:6	17.72	2314	1.14	13.43	104	197	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:6	17.72	2311	1.14	13.43	104	197	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:6	17.72	2311	1.14	13.43	104	197	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:6	17.72	2308	1.14	13.44	104	197	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:6	17.72	2307	1.13	13.43	104	197	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:7	17.72	2306	1.13	13.44	104	197	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:7	17.72	2304	1.13	13.42	104	197	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:7	17.72	2303	1.13	13.41	104	197	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:7	17.72	2301	1.13	13.43	104	197	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:7	17.72	2301	1.13	13.43	104	197	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:7	17.72	2300	1.13	13.43	104	197	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:8	17.72	2300	1.12	13.44	104	197	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:8	17.72	2300	1.12	13.43	104	197	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:8	17.72	2297	1.12	13.43	104	197	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:8	17.72	2294	1.12	13.43	104	197	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:8	17.72	2294	1.12	13.42	104	197	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:8	17.72	2290	1.12	13.42	104	197	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:9	17.72	2288	1.11	13.44	104	197	Idle	76.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:9	17.72	2285	1.11	13.43	104	197	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:9	17.72	2285	1.11	13.43	104	196	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:9	17.72	2282	1.11	13.44	104	196	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:9	17.72	2283	1.11	13.43	104	196	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:9	17.72	2282	1.1	13.42	104	197	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:12:9	17.72	2280	1.1	13.44	104	197	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:0	17.72	2279	1.1	13.43	104	197	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:0	17.72	2279	1.1	13.44	104	197	Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:0	17.72	2276	1.1	13.44	104	197	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:0	17.72	2276	1.1	13.43	104	197	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:0	17.72	2276	1.1	13.44	104	197	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:0	17.72	2272	1.1	13.44	104	197	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:1	17.72	2269	1.09	13.42	104	197	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:1	17.72	2267	1.09	13.43	104	197	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:1	17.72	2266	1.09	13.44	104	197	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:1	17.72	2256	1.09	13.43	104	197	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:1	17.72	2263	1.09	13.42	104	197	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:1	17.72	2263	1.09	13.43	104	197	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:1	17.72	2262	1.09	13.42	104	197	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:2	17.72	2261	1.08	13.42	104	197	Idle	78.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:2	17.72	2260	1.08	13.43	104	197	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:2	17.72	2248	1.08	13.42	104	197	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:2	17.72	2256	1.08	13.41	104	196	Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:2	17.72	2256	1.08	13.42	104	196	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:2	17.72	2264	1.08	13.44	104	196	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:3	17.72	2253	1.07	13.43	104	196	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:3	17.72	2252	1.07	13.43	104	196	Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:3	17.72	2252	1.07	13.44	104	196	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:3	17.72	2249	1.07	13.43	104	197	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:3	17.72	2247	1.07	13.42	104	197	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:3	17.72	2246	1.07	13.43	104	197	Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:4	17.72	2234	1.07	13.45	104	197	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:4	17.72	2242	1.07	13.42	104	197	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:4	17.72	2242	1.06	13.43	104	197	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:4	17.72	2240	1.06	13.44	104	196	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:13:4	17.72	2238	1.06	13.43	104	196	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:4	17.72	2237	1.06	13.43	104	196	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:4	17.72	2235	1.06	13.44	104	197	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:5	17.72	2232	1.06	13.43	104	197	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:5	17.72	2232	1.06	13.42	104	197	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:5	17.72	2231	1.06	13.42	104	197	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:5	17.72	2228	1.06	13.44	104	197	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:5	17.72	2226	1.05	13.44	104	197	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:5	17.72	2226	1.05	13.42	104	197	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:6	17.72	2223	1.05	13.43	104	197	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:6	17.72	2223	1.05	13.43	104	197	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:6	17.72	2222	1.05	13.42	104	197	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:6	17.72	2220	1.05	13.43	104	197	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:6	17.72	2221	1.05	13.44	104	197	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:6	17.72	2221	1.05	13.43	104	197	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:6	17.72	2222	1.05	13.42	104	197	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:7	17.72	2221	1.04	13.41	104	196	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:7	17.72	2222	1.04	13.43	104	196	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:7	17.72	2221	1.04	13.42	104	196	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:7	17.72	2220	1.04	13.43	104	197	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:7	17.72	2220	1.04	13.43	104	197	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:7	17.72	2218	1.04	13.43	104	197	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:8	17.72	2215	1.04	13.42	104	197	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:8	17.72	2206	1.04	13.43	104	197	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:8	17.72	2217	1.03	13.43	104	197	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:8	17.72	2205	1.03	13.42	104	197	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:8	17.72	2205	1.03	13.42	104	197	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:8	17.72	2200	1.03	13.42	104	197	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:9	17.72	2195	1.03	13.42	104	197	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:9	17.72	2195	1.03	13.42	104	197	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:9	17.72	2191	1.03	13.44	104	197	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:9	17.72	2191	1.03	13.44	104	197	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:9	17.72	2191	1.02	13.45	104	197	Idle	81.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:9	17.72	2190	1.02	13.45	104	197	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:13:9	17.72	2192	1.02	13.44	104	197	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:0	17.72	2192	1.02	13.44	104	197	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:0	17.72	2193	1.02	13.43	104	197	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:0	17.72	2193	1.02	13.42	104	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:0	17.72	2193	1.02	13.41	104	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:0	17.72	2193	1.02	13.42	104	197	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:0	17.72	2193	1.02	13.43	104	197	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:1	17.72	2192	1.01	13.44	104	197	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:1	17.72	2190	1.01	13.43	104	197	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:1	17.72	2187	1.01	13.42	104	197	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:1	17.72	2187	1.01	13.41	104	197	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:1	17.72	2185	1.01	13.41	104	196	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:1	17.72	2183	1.01	13.44	104	196	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:1	17.72	2182	1.01	13.44	104	197	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:2	17.72	2182	1.01	13.43	104	197	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:2	17.72	2180	1.01	13.43	104	197	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:2	17.72	2180	1.01	13.43	104	196	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:2	17.72	2178	1.01	13.43	104	196	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:2	17.72	2176	1.01	13.45	104	196	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:2	17.72	2175	1.01	13.45	104	197	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:3	17.72	2174	1.01	13.44	104	197	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:3	17.72	2170	1.01	13.44	104	197	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:3	17.72	2168	1	13.44	104	197	Idle	83.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:3	17.72	2167	1	13.43	104	197	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:14:3	17.72	2166	1	13.44	104	197	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:3	17.72	2164	1	13.44	104	197	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:4	17.72	2164	1	13.43	104	197	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:4	17.72	2163	1	13.42	104	197	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:4	17.72	2163	1	13.41	104	197	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:4	17.72	2163	1	13.41	104	197	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:4	17.72	2161	1	13.4	104	197	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:4	17.72	2161	1	13.4	104	197	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:4	17.72	2161	1	13.41	104	197	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:5	17.72	2159	1	13.43	104	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:5	17.72	2157	1	13.42	104	196	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:5	17.72	2157	1	13.44	104	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:5	17.72	2156	1	13.45	104	197	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:5	17.72	2153	1	13.42	104	197	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:5	17.72	2153	0.99	13.42	104	197	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:6	17.72	2151	0.99	13.42	104	197	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:6	17.72	2149	0.99	13.42	104	197	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:6	17.72	2149	0.99	13.44	104	197	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:6	17.72	2145	0.99	13.45	104	197	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:6	17.72	2144	0.99	13.45	104	197	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:6	17.72	2145	0.99	13.44	104	197	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:6	17.72	2145	0.99	13.43	104	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:7	17.72	2146	0.99	13.43	104	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:7	17.72	2146	0.99	13.45	104	197	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:7	17.72	2146	0.98	13.46	104	197	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:7	17.72	2147	0.98	13.45	104	197	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:7	17.72	2146	0.98	13.44	104	197	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:7	17.72	2146	0.98	13.43	104	197	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:8	17.72	2145	0.98	13.42	104	197	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:8	17.72	2144	0.98	13.43	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:8	17.72	2141	0.98	13.44	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:8	17.72	2140	0.98	13.44	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:8	17.72	2138	0.98	13.45	104	197	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:8	17.72	2136	0.98	13.44	104	197	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:9	17.72	2132	0.97	13.43	104	197	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:9	17.72	2132	0.97	13.43	104	197	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:9	17.72	2132	0.97	13.43	104	197	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:9	17.72	2139	0.97	13.42	104	197	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:9	17.72	2129	0.97	13.43	104	197	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:9	17.72	2128	0.97	13.45	104	197	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:14:9	17.72	2128	0.97	13.44	104	197	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:0	17.72	2128	0.97	13.42	104	197	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:0	17.72	2128	0.97	13.42	104	197	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:0	17.72	2126	0.97	13.42	104	197	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:0	17.72	2125	0.97	13.42	104	197	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:0	17.72	2123	0.97	13.42	104	197	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:0	17.72	2123	0.97	13.42	104	197	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:1	17.72	2120	0.97	13.41	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:1	17.72	2120	0.97	13.4	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:1	17.72	2119	0.97	13.4	104	196	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:1	17.72	2117	0.97	13.41	104	196	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:1	17.72	2116	0.97	13.42	104	196	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:1	17.72	2114	0.97	13.44	104	197	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:1	17.72	2114	0.97	13.45	104	197	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:2	17.72	2112	0.97	13.45	104	197	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:2	17.72	2113	0.97	13.43	104	196	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:2	17.72	2112	0.97	13.43	104	196	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:2	17.72	2113	0.97	13.42	104	196	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:15:2	17.72	2112	0.97	13.41	104	197	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:2	17.72	2110	0.97	13.41	104	197	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:3	17.72	2110	0.97	13.41	104	197	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:3	17.72	2110	0.97	13.41	104	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:3	17.72	2108	0.97	13.41	104	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:3	17.72	2108	0.97	13.44	104	196	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:3	17.72	2107	0.97	13.45	104	196	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:3	17.72	2104	0.97	13.45	104	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:4	17.72	2104	0.97	13.45	104	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.72	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:4	17.72	2102	0.97	13.45	104	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:4	17.72	2099	0.97	13.44	104	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.74	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:4	17.72	2098	0.98	13.43	104	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:4	17.72	2098	0.98	13.43	104	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:4	17.72	2097	0.98	13.43	104	196	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:4	17.72	2096	0.98	13.43	104	196	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:5	17.72	2096	0.98	13.44	104	196	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:5	17.72	2096	0.98	13.44	104	197	Off Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:5	17.72	2096	0.98	13.44	104	197	Off Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:5	17.72	2096	0.99	13.44	104	197	Off Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:5	17.72	2096	0.99	13.42	104	197	Off Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:5	17.72	2050	1	13.41	104	197	Off Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:15:6	9.54	2109	1.01	13.41	104	197	Off Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:15:6	9.54	2105	1.01	13.41	104	197	Off Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:15:6	12.27	2106	1.02	13.41	104	197	Off Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:15:6	14.99	2104	1.02	13.42	104	197	Off Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:15:6	14.99	2104	1.03	13.43	104	197	Off Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:6	17.72	2102	1.03	13.45	104	197	Off Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:6	17.72	2100	1.04	13.43	104	197	Off Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:7	20.45	2098	1.05	13.43	104	197	Off Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:7	20.45	2098	1.06	13.43	104	197	Off Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:7	23.18	2094	1.07	13.44	104	197	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:7	25.9	2094	1.08	13.43	104	197	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:7	25.9	2097	1.08	13.43	104	197	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:7	28.63	2096	1.09	13.42	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:8	28.63	2097	1.1	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:8	31.36	2104	1.11	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:8	31.36	2107	1.11	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:8	34.08	2106	1.12	13.42	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:15:8	34.08	2090	1.13	13.43	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:8	34.08	2082	1.13	13.43	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:9	34.08	2082	1.14	13.41	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:9	34.08	2082	1.14	13.4	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:9	34.08	2076	1.15	13.4	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:9	34.08	2076	1.15	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:9	34.08	2066	1.15	13.43	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:9	34.08	2060	1.16	13.44	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:15:9	32.72	2080	1.16	13.46	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.17	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:16:0	32.72	2080	1.16	13.45	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.19	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:16:0	32.72	2079	1.17	13.44	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.19	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:16:0	32.72	2085	1.18	13.42	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.19	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:16:0	32.72	2085	1.19	13.4	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.19	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:16:0	32.72	2077	1.2	13.39	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.17	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:16:0	32.72	2078	1.2	13.4	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.18	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:16:1	34.08	2083	1.21	13.4	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.15	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:16:1	34.08	2071	1.23	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.08	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:16:1	34.08	2071	1.23	13.43	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.07	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:16:1	34.08	2073	1.24	13.43	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.01	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:1	34.08	2079	1.25	13.42	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.98	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:16:1	34.08	2083	1.26	13.42	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.95	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:1	34.08	2083	1.27	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:2	34.08	2086	1.28	13.4	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.87	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:2	34.08	2088	1.29	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.82	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:2	34.08	2088	1.3	13.43	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:2	34.08	2087	1.31	13.44	104	197	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.75	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:2	34.08	2087	1.32	13.45	104	197	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:2	34.08	2086	1.33	13.44	104	197	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.76	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:3	34.08	2085	1.34	13.42	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:3	34.08	2086	1.34	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.74	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:3	34.08	2089	1.35	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.73	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:3	34.08	2089	1.35	13.4	104	197	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.72	20.26	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:3	34.08	2081	1.36	13.4	104	197	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:3	34.08	2078	1.36	13.41	104	197	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.71	20.19	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:4	34.08	2078	1.36	13.42	104	197	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.72	20.11	1.37	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:4	34.08	2076	1.37	13.42	104	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.72	19.99	1.36	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:4	34.08	2072	1.37	13.41	104	196	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.71	19.85	1.35	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:4	34.08	2070	1.37	13.41	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.7	19.68	1.34	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:4	34.08	2062	1.37	13.4	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.67	19.51	1.33	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:4	34.08	2065	1.37	13.4	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.65	19.16	1.3	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:4	34.08	2056	1.37	13.4	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.61	18.9	1.29	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:5	34.08	2057	1.37	13.41	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.61	18.63	1.27	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:5	34.08	2057	1.37	13.43	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.6	18.37	1.25	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:5	34.08	2058	1.37	13.44	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.6	18.11	1.23	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:5	34.08	2057	1.37	13.45	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.62	17.85	1.22	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:5	34.08	2056	1.37	13.45	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.65	17.62	1.2	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:5	34.08	2052	1.37	13.43	104	197	Off Idle	85.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.66	17.38	1.18	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:6	34.08	2066	1.37	13.41	104	197	Off Idle	85.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.68	17.14	1.17	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:6	34.08	2058	1.37	13.4	104	197	Off Idle	85.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.7	16.95	1.15	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:6	34.08	2056	1.36	13.39	104	197	Off Idle	85.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.74	16.67	1.14	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:6	34.08	2057	1.36	13.39	104	197	Off Idle	85.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.73	16.49	1.12	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:6	34.08	2049	1.36	13.38	104	197	Off Idle	85.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.71	16.32	1.11	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:6	34.08	2058	1.36	13.41	104	196	Off Idle	85.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.69	16.18	1.1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:16:6	34.08	2059	1.36	13.41	104	196	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.68	16.07	1.1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:7	34.08	2059	1.35	13.41	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.66	15.97	1.09	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:7	34.08	2072	1.35	13.41	104	197	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.65	15.87	1.08	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:7	34.08	2068	1.35	13.42	104	197	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.69	15.76	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:7	34.08	2069	1.34	13.4	104	197	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.72	15.69	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:7	34.08	2070	1.34	13.41	104	197	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.77	15.65	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:7	34.08	2063	1.34	13.41	104	197	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.77	15.61	1.06	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:8	34.08	2073	1.33	13.4	104	196	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.81	15.59	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:8	34.08	2068	1.33	13.39	104	196	Off Idle	85.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.78	15.56	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:8	34.08	2068	1.33	13.39	104	196	Off Idle	85.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.77	15.53	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:8	34.08	2067	1.32	13.41	104	197	Off Idle	85.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.78	15.51	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:8	34.08	2084	1.32	13.42	104	197	Off Idle	85.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.85	15.48	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:8	34.08	2074	1.31	13.43	104	197	Off Idle	85.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.87	15.46	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:9	32.72	2066	1.3	13.45	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.91	15.44	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:16:9	32.72	2072	1.29	13.44	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.96	15.44	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:16:9	32.72	2070	1.28	13.44	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10	15.41	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:16:9	32.72	2065	1.27	13.44	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.05	15.38	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:16:9	32.72	2063	1.25	13.43	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.17	15.35	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:16:9	32.72	2055	1.23	13.42	104	197	Off Idle	85.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.25	15.33	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:16:9	32.72	2055	1.22	13.41	104	197	Full Load	85.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-10.27	15.32	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:17:0	32.72	2054	1.21	13.41	104	197	Idle	85.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-10.39	15.3	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:0	34.08	2023	1.18	13.39	104	197	Idle	85.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-10.48	15.26	1.04	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:0	34.08	2023	1.16	13.4	104	197	Idle	85.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-10.52	15.24	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:17:0	34.08	2027	1.14	13.41	104	197	Idle	85.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-10.58	15.21	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:17:0	34.08	2026	1.13	13.42	104	197	Idle	85.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-10.61	15.2	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:17:0	34.08	2021	1.11	13.43	104	197	Idle	84.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-10.64	15.18	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:1	34.08	2020	1.1	13.44	104	197	Idle	84.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.66	15.17	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:1	34.08	2017	1.08	13.44	104	197	Idle	84.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.7	15.14	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:1	31.36	2017	1.06	13.43	104	197	Idle	84	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.71	15.12	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:1	31.36	1995	1.05	13.42	104	197	Idle	83.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.68	15.1	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:1	25.9	2008	1.03	13.41	104	196	Idle	83.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.65	15.08	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:1	25.9	2008	1.02	13.4	104	196	Idle	83.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.6	15.08	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:1	20.45	2032	1.01	13.4	104	196	Idle	83.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.58	15.05	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:2	20.45	2035	0.99	13.41	104	196	Idle	83.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.6	15.02	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:2	17.72	2035	0.99	13.42	104	196	Idle	83.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-10.6	15.02	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:2	17.72	2068	0.98	13.43	104	196	Idle	83.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.61	15.01	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:2	17.72	2065	0.98	13.45	104	197	Idle	83.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.59	15	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:2	17.72	2065	0.98	13.45	104	197	Idle	83.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-10.6	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:2	17.72	2057	0.98	13.45	104	197	Idle	83.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.61	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:3	17.72	2040	0.99	13.45	104	196	Idle	84.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.66	14.98	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:3	17.72	2017	0.99	13.44	104	196	Idle	84.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.7	14.98	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:3	17.72	2021	0.99	13.44	104	196	Idle	84.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.72	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:3	17.72	2021	1	13.44	104	197	Idle	84.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.74	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:3	17.72	2021	1	13.43	104	197	Idle	84.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.73	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:3	17.72	2025	1	13.42	104	197	Idle	84.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.71	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:4	17.72	2025	1	13.43	104	196	Idle	84.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.7	14.98	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:4	17.72	2030	1	13.44	104	196	Idle	84.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.69	14.98	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:4	17.72	2037	1	13.44	104	196	Idle	84.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.67	14.98	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:4	17.72	2037	1	13.44	104	196	Idle	84.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.66	14.96	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:4	17.72	2041	1	13.42	104	196	Idle	84.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.66	14.95	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:4	17.72	2040	1	13.42	104	196	Idle	84.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.65	14.91	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:4	17.72	2040	1	13.42	104	196	Idle	84.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.62	14.87	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:5	17.72	2038	1	13.42	104	196	Idle	84.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.6	14.84	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:5	17.72	2034	1	13.4	104	197	Idle	84.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.53	14.82	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:5	17.72	2032	1	13.41	104	197	Idle	84.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.53	14.84	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:5	17.72	2024	1	13.41	104	197	Idle	84.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.56	14.88	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:5	17.72	2019	1	13.41	104	196	Idle	84.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.57	14.93	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:5	17.72	2018	0.99	13.41	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	15.03	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:6	17.72	2013	0.99	13.41	104	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	15.17	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:6	17.72	2012	0.99	13.42	104	197	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	15.34	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:6	17.72	2012	0.99	13.42	104	197	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	15.53	1.06	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:6	17.72	2011	0.99	13.42	104	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	15.84	1.08	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:6	17.72	2014	0.99	13.42	104	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	16.05	1.09	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:6	17.72	2017	0.99	13.42	104	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	16.24	1.11	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:6	17.72	2017	0.99	13.41	104	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	16.41	1.12	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:7	17.72	2018	0.99	13.42	104	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	16.58	1.13	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:7	17.72	2020	0.99	13.43	104	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	16.73	1.14	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:7	17.72	2020	0.99	13.44	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	16.87	1.15	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:7	17.72	2018	0.99	13.44	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	17.02	1.16	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:7	17.72	2016	0.99	13.43	104	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	17.3	1.18	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:7	17.72	2014	0.99	13.44	104	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	17.57	1.2	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:8	17.72	2012	0.99	13.45	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	18.06	1.23	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:8	17.72	2009	0.99	13.45	104	196	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	18.22	1.24	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:8	17.72	2005	0.98	13.45	104	196	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	18.55	1.26	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:8	17.72	2004	0.98	13.46	104	196	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	18.87	1.29	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:8	17.72	2001	0.98	13.46	104	196	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	19.13	1.3	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:8	17.72	2000	0.98	13.46	104	196	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	19.43	1.32	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:9	17.72	2000	0.99	13.46	104	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	19.69	1.34	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:9	17.72	2001	0.99	13.47	104	196	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	19.99	1.36	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:9	17.72	2002	0.99	13.47	104	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.11	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:9	17.72	2005	0.99	13.46	104	196	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.15	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:9	17.72	2005	0.99	13.45	104	196	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.15	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:17:9	17.72	2005	0.99	13.43	104	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.15	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:17:9	17.72	2004	0.98	13.42	104	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.15	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:0	17.72	2004	0.98	13.43	104	197	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:0	17.72	2000	0.98	13.42	104	197	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:0	17.72	1998	0.98	13.43	104	197	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:0	17.72	1993	0.98	13.44	104	196	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:0	17.72	1990	0.98	13.44	104	196	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:0	17.72	1989	0.98	13.42	104	196	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:1	17.72	1984	0.98	13.42	104	196	Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:1	17.72	1968	0.98	13.42	104	196	Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:1	17.72	1976	0.98	13.41	104	196	Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:1	17.72	1997	0.98	13.41	104	196	Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:1	17.72	1981	0.98	13.41	104	196	Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:1	17.72	1982	0.98	13.42	104	196	Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:1	17.72	1981	0.98	13.42	104	196	Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:2	17.72	1974	0.98	13.42	104	196	Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:2	17.72	1979	0.98	13.43	104	196	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.07	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:2	17.72	1979	0.98	13.44	104	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.07	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:2	17.72	1987	0.98	13.44	104	196	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.07	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:2	17.72	1977	0.98	13.45	104	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.07	1.37	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:2	17.72	1977	0.98	13.45	104	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.06	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:3	17.72	1968	0.98	13.45	104	196	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.05	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:3	17.72	1972	0.98	13.45	104	196	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:3	17.72	1972	0.98	13.45	104	196	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.05	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:3	17.72	1970	0.98	13.45	104	196	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.05	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:3	17.72	1968	0.98	13.45	104	196	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.05	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:3	17.72	1968	0.98	13.46	104	196	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:4	17.72	1967	0.98	13.46	104	196	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:4	17.72	1966	0.98	13.46	104	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:4	17.72	1966	0.98	13.45	104	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:4	17.72	1973	0.99	13.45	104	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:4	17.72	1963	0.99	13.45	104	196	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:4	17.72	1948	0.99	13.45	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:4	17.72	1954	0.99	13.45	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:5	17.72	1960	0.99	13.45	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:5	17.72	1959	0.99	13.44	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:5	17.72	1958	0.99	13.43	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:5	17.72	1955	0.99	13.43	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:5	17.72	1950	0.99	13.42	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:5	17.72	1947	0.99	13.41	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:6	17.72	1947	0.99	13.4	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:6	17.72	1944	0.99	13.39	104	196	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:6	17.72	1951	0.99	13.39	104	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:6	17.72	1951	0.99	13.4	104	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:6	17.72	1946	0.99	13.41	104	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:6	17.72	1946	0.99	13.41	104	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:6	17.72	1946	0.99	13.41	104	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:7	17.72	1943	0.99	13.41	104	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:7	17.72	1941	0.99	13.42	104	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:7	17.72	1941	0.99	13.43	104	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:7	17.72	1940	0.99	13.41	104	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:7	17.72	1938	0.99	13.41	104	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:7	17.72	1938	0.99	13.41	104	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:8	17.72	1932	0.99	13.4	104	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:8	17.72	1934	0.99	13.41	104	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:8	17.72	1931	0.99	13.42	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:8	17.72	1931	0.99	13.43	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:8	17.72	1928	0.99	13.43	104	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:8	17.72	1927	0.99	13.43	104	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:18:9	17.72	1926	0.99	13.42	104	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:9	17.72	1926	0.99	13.41	104	196	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:9	17.72	1925	0.99	13.41	104	197	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:9	17.72	1924	0.99	13.42	104	197	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:9	17.72	1924	0.99	13.42	104	196	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:9	17.72	1923	0.99	13.43	104	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:18:9	17.72	1920	0.99	13.42	104	196	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:0	17.72	1918	0.99	13.4	104	197	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:0	17.72	1917	0.99	13.38	104	197	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:0	17.72	1913	0.99	13.36	104	197	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:0	17.72	1911	0.99	13.34	104	197	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:0	17.72	1910	0.99	13.34	104	197	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:0	17.72	1908	0.99	13.35	104	197	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:1	17.72	1908	0.99	13.35	104	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:1	17.72	1908	0.99	13.36	104	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:1	17.72	1906	0.99	13.37	104	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:1	17.72	1905	0.99	13.39	104	197	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:1	17.72	1905	0.99	13.39	104	197	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:1	17.72	1904	0.99	13.4	104	197	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:1	17.72	1903	0.99	13.4	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:2	17.72	1902	0.99	13.4	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:2	17.72	1900	0.99	13.39	104	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:2	17.72	1899	0.99	13.39	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:2	17.72	1895	0.99	13.39	104	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:2	17.72	1886	0.99	13.37	104	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:2	17.72	1880	0.99	13.36	104	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:3	17.72	1856	0.99	13.36	104	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:3	17.72	1836	0.99	13.37	104	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:3	17.72	1814	0.99	13.37	104	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:3	17.72	1796	0.99	13.37	104	196	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:3	17.72	1770	0.99	13.37	104	196	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:3	17.72	1748	0.99	13.37	104	196	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:4	17.72	1748	1	13.35	104	196	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:4	17.72	1712	1	13.36	104	196	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.24	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:4	17.72	1689	1	13.37	104	196	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.24	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:4	17.72	1654	1	13.36	104	196	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:4	17.72	1654	1	13.36	104	197	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:4	17.72	1616	1.01	13.37	104	197	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.24	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:4	17.72	1605	1.01	13.36	104	197	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.24	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:5	17.72	1605	1.02	13.37	104	196	Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:5	17.72	1568	1.03	13.37	104	196	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:5	17.72	1555	1.04	13.38	104	196	Idle	75.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.24	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:5	17.72	1542	1.04	13.37	104	196	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.24	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:5	17.72	1495	1.05	13.38	104	196	Idle	73.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:5	17.72	1480	1.06	13.38	104	196	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:6	17.72	1454	1.07	13.38	104	196	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.23	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:6	17.72	1454	1.09	13.39	104	196	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.39	20.24	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:6	17.72	1427	1.1	13.37	104	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.3	20.24	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:6	17.72	1390	1.11	13.36	104	197	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.15	20.23	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:6	17.72	1374	1.12	13.37	104	197	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	20.23	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:6	17.72	1374	1.13	13.36	104	196	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	20.23	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:6	19.09	1347	1.14	13.35	104	196	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.92	20.23	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:7	19.09	1309	1.15	13.37	104	196	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.87	20.22	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:19:7	19.09	1309	1.17	13.37	104	196	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.77	20.23	1.38	4.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:19:7	17.72	1291	1.18	13.35	104	196	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.67	20.23	1.38	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:19:7	17.72	1262	1.18	13.37	104	196	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.6	20.22	1.38	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:19:7	17.72	1262	1.2	13.37	104	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.49	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:19:7	17.72	1223	1.2	13.39	104	196	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.36	20.21	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:19:8	17.72	1223	1.21	13.39	104	197	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.31	20.21	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:19:8	17.72	1209	1.21	13.4	104	197	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.23	20.21	1.38	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:19:8	16.36	1188	1.21	13.39	104	197	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.11	20.21	1.38	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:19:8	16.36	1190	1.22	13.39	104	197	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.04	20.21	1.38	4.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:19:8	16.36	1199	1.22	13.37	104	196	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.95	20.21	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:19:8	16.36	1202	1.21	13.37	104	196	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.91	20.21	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:19:9	16.36	1206	1.21	13.36	104	196	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.89	20.21	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:19:9	16.36	1209	1.21	13.36	104	197	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.82	20.22	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:19:9	16.36	1220	1.2	13.36	104	197	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.84	20.22	1.38	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:19:9	16.36	1232	1.2	13.37	104	197	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.86	20.23	1.38	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:19:9	16.36	1263	1.19	13.37	104	196	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.82	20.24	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:19:9	16.36	1263	1.18	13.38	104	196	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.85	20.24	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:19:9	16.36	1253	1.18	13.38	104	196	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.91	20.24	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:0	16.36	1255	1.17	13.37	104	196	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.96	20.24	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:20:0	16.36	1266	1.16	13.37	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8	20.24	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:20:0	13.63	1266	1.15	13.38	104	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.08	20.25	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:20:0	13.63	1264	1.14	13.37	104	196	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.25	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:0	12.27	1276	1.12	13.36	104	196	Idle	83.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.19	20.25	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:0	12.27	1276	1.11	13.37	104	196	Idle	84.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.21	20.25	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:1	12.27	1275	1.1	13.37	104	196	Idle	85.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.23	20.24	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:1	12.27	1256	1.08	13.36	104	196	Idle	86.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.3	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:1	12.27	1256	1.07	13.37	104	196	Idle	86.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.37	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:1	12.27	1258	1.06	13.36	104	196	Idle	87.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.4	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:1	12.27	1229	1.05	13.36	104	196	Idle	87.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.45	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:1	12.27	1229	1.04	13.37	104	196	Idle	88	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.51	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:1	12.27	1232	1.03	13.36	104	196	Idle	88.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.54	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:2	12.27	1214	1.02	13.37	104	196	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.58	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:2	13.63	1195	1.01	13.37	104	196	Idle	88.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.61	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:2	13.63	1199	1	13.36	104	196	Idle	88.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.61	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:2	13.63	1190	1	13.37	104	196	Idle	89.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.61	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:2	14.99	1178	0.99	13.37	104	196	Idle	89.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.62	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:2	14.99	1178	0.98	13.37	104	196	Idle	89.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.62	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:3	14.99	1164	0.97	13.37	104	196	Idle	90.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.61	20.24	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:3	14.99	1178	0.97	13.36	104	196	Idle	90.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.64	20.24	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:3	14.99	1178	0.97	13.37	104	196	Idle	90.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.64	20.23	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:3	14.99	1178	0.96	13.37	104	196	Idle	91	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.64	20.23	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:3	14.99	1177	0.96	13.37	104	196	Idle	91.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.65	20.23	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:3	14.99	1181	0.95	13.37	104	196	Idle	91.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.65	20.23	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:19:20:4	14.99	1181	0.95	13.37	104	196	Idle	91.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.63	20.22	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:4	13.63	1208	0.94	13.36	104	196	Idle	92	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.65	20.23	1.38	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:4	13.63	1208	0.94	13.38	104	196	Idle	92.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.68	20.23	1.38	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:4	13.63	1222	0.94	13.38	104	196	Idle	92.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.71	20.23	1.38	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:4	13.63	1248	0.93	13.38	104	196	Idle	92.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.79	20.23	1.38	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:4	12.27	1262	0.93	13.38	104	196	Idle	92.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.85	20.22	1.38	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:20:4	12.27	1274	0.92	13.37	104	196	Idle	92.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.87	20.14	1.37	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:20:5	10.9	1312	0.92	13.36	104	196	Idle	92.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.98	19.94	1.36	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:20:5	10.9	1346	0.91	13.37	104	196	Idle	93.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.05	19.69	1.34	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:20:5	10.9	1354	0.91	13.38	104	196	Idle	93.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.06	19.4	1.32	4.2	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:20:5	10.9	1370	0.91	13.36	104	196	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.13	19.09	1.3	4.2	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:20:5	10.9	1397	0.9	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.2	18.58	1.27	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:20:5	10.9	1409	0.9	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.23	18.41	1.25	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:20:6	12.27	1416	0.9	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.29	17.88	1.22	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:20:6	12.27	1460	0.89	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.35	17.52	1.19	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:20:6	13.63	1493	0.89	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	17.21	1.17	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:20:6	13.63	1516	0.89	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.52	16.99	1.16	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:20:6	13.63	1516	0.88	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	16.89	1.15	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:20:6	13.63	1554	0.88	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	16.84	1.15	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:20:6	13.63	1606	0.88	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.69	16.81	1.14	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:20:7	13.63	1626	0.88	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.77	16.83	1.15	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:20:7	13.63	1673	0.88	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.88	16.85	1.15	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:20:7	14.99	1690	0.87	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.99	16.88	1.15	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:20:7	14.99	1717	0.87	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.08	16.9	1.15	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:20:7	14.99	1760	0.87	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.2	16.9	1.15	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:20:7	14.99	1760	0.87	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.26	16.9	1.15	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:20:8	14.99	1807	0.87	13.39	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.33	16.87	1.15	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:20:8	14.99	1838	0.87	13.39	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.42	16.78	1.14	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:20:8	14.99	1883	0.87	13.39	104	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.46	16.73	1.14	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:20:8	14.99	1883	0.87	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	16.66	1.13	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:20:8	17.72	1942	0.86	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.51	16.53	1.13	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:20:8	17.72	1984	0.86	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.51	16.49	1.12	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:20:9	17.72	1984	0.86	13.36	104	196	Idle	92.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.52	16.41	1.12	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:20:9	17.72	2018	0.86	13.35	104	196	Idle	92.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.56	16.31	1.11	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:20:9	17.72	2076	0.86	13.36	104	196	Idle	91.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.57	16.28	1.11	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:20:9	17.72	2086	0.86	13.36	104	196	Idle	91.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.62	16.15	1.1	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:20:9	17.72	2108	0.87	13.38	104	196	Idle	90.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.65	16.08	1.1	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:20:9	17.72	2140	0.87	13.39	104	196	Idle	90.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.71	16.02	1.09	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:20:9	17.72	2205	0.87	13.4	104	196	Idle	89.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.75	15.96	1.09	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:0	17.72	2205	0.88	13.39	104	196	Idle	88.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.79	15.87	1.08	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:0	17.72	2226	0.88	13.38	104	196	Idle	88.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.8	15.82	1.08	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:0	17.72	2259	0.88	13.38	104	196	Idle	87.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.81	15.78	1.07	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:0	17.72	2309	0.89	13.39	104	196	Idle	86.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.83	15.75	1.07	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:0	17.72	2309	0.89	13.39	104	196	Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.81	15.73	1.07	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:0	17.72	2304	0.9	13.39	104	196	Idle	84.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.82	15.73	1.07	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:1	17.72	2324	0.9	13.39	104	196	Idle	83.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.86	15.73	1.07	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:1	17.72	2312	0.91	13.39	104	196	Idle	83.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.88	15.74	1.07	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:1	17.72	2291	0.92	13.39	104	196	Idle	82.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.87	15.73	1.07	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:1	17.72	2268	0.93	13.38	104	196	Idle	82.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.88	15.74	1.07	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:1	17.72	2252	0.94	13.38	104	196	Idle	81.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.87	15.75	1.07	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:1	17.72	2241	0.95	13.38	104	196	Idle	81.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.83	15.78	1.08	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:1	17.72	2215	0.96	13.37	104	196	Idle	80.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.79	15.82	1.08	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:2	17.72	2182	0.97	13.39	104	196	Idle	80.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.78	15.92	1.08	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:2	17.72	2182	0.97	13.39	104	196	Idle	79.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.74	15.96	1.09	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:2	17.72	2156	0.98	13.39	104	196	Idle	79.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.71	16.06	1.09	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:2	17.72	2149	0.99	13.38	104	196	Idle	79.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.69	16.23	1.11	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:2	17.72	2143	1	13.38	104	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	16.36	1.11	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:2	17.72	2140	1.01	13.37	104	196	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	16.49	1.12	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:3	17.72	2138	1.01	13.37	104	196	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	16.61	1.13	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:3	17.72	2138	1.02	13.38	104	196	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	16.67	1.14	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:3	17.72	2143	1.03	13.37	104	196	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	16.83	1.15	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:3	17.72	2139	1.04	13.38	104	196	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	16.9	1.15	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:3	17.72	2153	1.04	13.39	104	196	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	16.95	1.15	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:3	17.72	2162	1.05	13.4	104	196	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	17.01	1.16	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:4	17.72	2156	1.05	13.38	104	196	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	17.08	1.16	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:4	17.72	2153	1.06	13.38	104	196	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	17.17	1.17	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:4	17.72	2152	1.06	13.38	104	196	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	17.3	1.18	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:4	17.72	2145	1.07	13.38	104	196	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	17.61	1.2	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:4	17.72	2137	1.07	13.37	104	196	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	17.9	1.22	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:4	17.72	2100	1.07	13.37	104	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	18.21	1.24	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:4	17.72	2100	1.07	13.38	104	197	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	18.37	1.25	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:5	17.72	2100	1.07	13.39	104	197	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	18.86	1.28	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:5	17.72	2084	1.07	13.4	104	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	19.18	1.31	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:5	17.72	2084	1.07	13.41	104	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	19.46	1.33	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:5	17.72	2069	1.06	13.41	104	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	19.72	1.34	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:5	17.72	2057	1.06	13.4	104	196	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.04	1.36	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:5	17.72	2055	1.06	13.39	104	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.17	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:6	17.72	2049	1.06	13.37	104	196	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:21:6	17.72	2038	1.06	13.36	104	196	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:6	17.72	2047	1.05	13.35	104	196	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:6	17.72	2047	1.05	13.36	104	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:6	17.72	2046	1.05	13.37	104	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:6	17.72	2046	1.05	13.39	104	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:6	17.72	2046	1.04	13.39	104	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:7	17.72	2043	1.04	13.39	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:7	17.72	2036	1.04	13.4	104	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:7	17.72	2036	1.04	13.39	104	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:7	17.72	2035	1.03	13.39	104	196	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:7	17.72	2002	1.03	13.39	104	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:7	17.72	2008	1.03	13.4	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:8	17.72	2003	1.03	13.4	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:8	17.72	1989	1.04	13.4	104	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:8	17.72	1980	1.04	13.4	104	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:8	17.72	1976	1.04	13.4	104	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:8	17.72	1965	1.04	13.4	104	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:8	17.72	1960	1.04	13.4	104	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:9	17.72	1949	1.04	13.4	104	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:9	17.72	1949	1.04	13.4	104	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:9	17.72	1930	1.04	13.39	104	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:9	17.72	1941	1.04	13.38	104	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:9	17.72	1941	1.04	13.36	104	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:9	17.72	1936	1.04	13.34	104	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:21:9	17.72	1932	1.04	13.35	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:0	17.72	1929	1.04	13.35	104	196	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:0	17.72	1926	1.04	13.36	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:0	17.72	1919	1.04	13.37	104	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:0	17.72	1913	1.04	13.39	104	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:0	17.72	1913	1.04	13.4	104	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:0	17.72	1902	1.04	13.4	104	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:1	17.72	1890	1.04	13.4	104	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:1	17.72	1890	1.04	13.39	104	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:1	17.72	1877	1.04	13.38	104	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:1	17.72	1865	1.04	13.37	104	196	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:1	17.72	1855	1.03	13.38	104	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:1	17.72	1855	1.03	13.39	104	196	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:1	17.72	1839	1.03	13.39	104	196	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:2	17.72	1836	1.03	13.39	104	196	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:2	17.72	1830	1.03	13.39	104	196	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:2	17.72	1830	1.03	13.39	104	196	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:2	17.72	1826	1.03	13.37	104	196	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:2	17.72	1819	1.03	13.38	104	196	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.2	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:2	17.72	1813	1.03	13.38	104	196	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:3	17.72	1813	1.02	13.37	104	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:3	17.72	1808	1.02	13.37	104	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:3	17.72	1803	1.02	13.38	104	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:3	17.72	1800	1.02	13.38	104	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:3	17.72	1790	1.02	13.39	104	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:3	17.72	1782	1.02	13.39	104	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:4	17.72	1774	1.02	13.39	104	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:4	17.72	1770	1.03	13.37	104	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:4	17.72	1761	1.03	13.38	104	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:4	17.72	1750	1.03	13.38	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:4	17.72	1750	1.03	13.36	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:4	17.72	1738	1.03	13.36	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:4	17.72	1727	1.03	13.36	104	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:5	17.72	1722	1.03	13.36	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.21	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:22:5	17.72	1722	1.04	13.36	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.21	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:5	17.72	1713	1.04	13.36	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:5	17.72	1710	1.04	13.37	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:5	17.72	1707	1.04	13.37	104	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:5	17.72	1698	1.04	13.35	104	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:6	17.72	1691	1.04	13.36	104	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.21	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:6	17.72	1691	1.04	13.37	104	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:6	17.72	1673	1.04	13.37	104	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:6	17.72	1668	1.04	13.36	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:6	17.72	1668	1.04	13.38	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:6	17.72	1660	1.04	13.37	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:6	17.72	1653	1.04	13.37	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:7	17.72	1646	1.04	13.38	104	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:7	17.72	1643	1.04	13.36	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:7	17.72	1632	1.04	13.36	104	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:7	17.72	1626	1.04	13.37	104	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:7	17.72	1626	1.04	13.37	104	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:7	17.72	1620	1.04	13.38	104	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:8	17.72	1613	1.04	13.38	104	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:8	17.72	1606	1.04	13.37	104	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:8	17.72	1602	1.04	13.36	104	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:8	17.72	1594	1.04	13.38	104	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:8	17.72	1586	1.04	13.36	104	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:8	17.72	1572	1.04	13.37	104	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:9	17.72	1572	1.04	13.37	104	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:9	17.72	1563	1.04	13.37	104	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:9	17.72	1553	1.04	13.38	104	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:9	17.72	1553	1.04	13.37	104	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:9	17.72	1536	1.04	13.38	104	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:9	17.72	1534	1.04	13.37	104	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.24	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:22:9	17.72	1531	1.04	13.37	104	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:0	17.72	1528	1.04	13.36	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:0	17.72	1521	1.04	13.37	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:0	17.72	1511	1.04	13.37	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:0	17.72	1511	1.04	13.38	104	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:0	17.72	1502	1.04	13.37	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:0	17.72	1495	1.04	13.38	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:1	17.72	1495	1.04	13.37	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	20.22	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:1	17.72	1485	1.04	13.38	104	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.47	20.22	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:1	17.72	1474	1.04	13.38	104	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.47	20.21	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:1	17.72	1469	1.04	13.37	104	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	20.23	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:1	17.72	1443	1.04	13.36	104	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	20.24	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:1	17.72	1445	1.04	13.38	104	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	20.24	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:1	17.72	1445	1.04	13.37	104	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	20.24	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:2	17.72	1438	1.04	13.37	104	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.25	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:2	17.72	1430	1.04	13.36	104	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.24	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:2	17.72	1430	1.04	13.38	104	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	20.24	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:2	17.72	1423	1.04	13.36	104	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.29	20.25	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:2	19.09	1427	1.04	13.36	104	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.29	20.24	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:2	19.09	1427	1.04	13.35	104	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	20.24	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:3	19.09	1398	1.04	13.37	104	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	20.24	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:3	19.09	1412	1.04	13.37	104	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.23	20.24	1.38	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:23:3	19.09	1396	1.04	13.36	104	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	20.24	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:23:3	19.09	1381	1.04	13.36	104	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	20.24	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:23:3	17.72	1370	1.04	13.38	104	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.17	20.23	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:23:3	17.72	1370	1.04	13.37	104	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.23	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:23:4	17.72	1349	1.04	13.36	104	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.23	1.38	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:23:4	17.72	1346	1.04	13.36	104	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	20.22	1.38	4.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:23:4	17.72	1346	1.04	13.37	104	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.22	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:4	16.36	1325	1.04	13.36	104	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	20.21	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:4	16.36	1328	1.04	13.34	104	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	20.21	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:4	16.36	1324	1.04	13.37	104	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.98	20.21	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:4	16.36	1324	1.04	13.38	104	196	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	20.21	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:5	16.36	1315	1.04	13.36	104	196	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.92	20.21	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:5	16.36	1316	1.03	13.37	104	196	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:5	16.36	1316	1.03	13.37	104	196	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.91	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:5	16.36	1322	1.03	13.37	104	196	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	20.22	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:5	16.36	1318	1.03	13.36	104	196	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.95	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:5	16.36	1336	1.03	13.36	104	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	20.23	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:6	16.36	1336	1.03	13.38	104	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:6	16.36	1329	1.03	13.38	104	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.05	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:6	16.36	1322	1.03	13.37	104	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:6	16.36	1301	1.02	13.37	104	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:6	16.36	1298	1.02	13.36	104	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.11	1.37	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:6	16.36	1290	1.02	13.36	104	196	Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.12	1.37	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:6	16.36	1285	1.02	13.37	104	196	Idle	86.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	20.12	1.37	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:7	16.36	1276	1.01	13.37	104	196	Idle	87	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.03	20.12	1.37	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:7	16.36	1268	1.01	13.37	104	196	Idle	87.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.06	20.12	1.37	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:7	16.36	1264	1.01	13.37	104	196	Idle	87.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.07	20.12	1.37	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:7	16.36	1258	1	13.35	104	196	Idle	87.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.06	20.12	1.37	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:7	16.36	1248	1	13.36	104	196	Idle	87.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.04	20.12	1.37	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:7	16.36	1244	1	13.37	104	196	Idle	88	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.01	20.12	1.37	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:8	14.99	1244	0.99	13.36	104	196	Idle	88.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9	20.12	1.37	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:8	14.99	1223	0.99	13.38	104	196	Idle	88.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.98	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:8	14.99	1214	0.99	13.39	104	196	Idle	88.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.99	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:8	14.99	1182	0.98	13.38	104	196	Idle	88.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.99	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:8	14.99	1182	0.98	13.39	104	196	Idle	88.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.98	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:23:8	14.99	1181	0.98	13.38	104	196	Idle	88.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.96	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:9	14.99	1173	0.97	13.38	104	196	Idle	88.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.94	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:9	14.99	1173	0.97	13.38	104	196	Idle	88.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.94	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:9	14.99	1171	0.97	13.37	104	196	Idle	88.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.88	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:9	14.99	1169	0.96	13.37	104	196	Idle	88.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.85	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:9	14.99	1160	0.96	13.37	104	196	Idle	89	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.8	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:9	14.99	1150	0.96	13.38	104	196	Idle	89.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.76	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:23:9	14.99	1148	0.95	13.37	104	196	Idle	89.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.73	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:0	13.63	1125	0.95	13.36	104	196	Idle	89.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.72	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:0	13.63	1125	0.95	13.36	104	196	Idle	89.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.68	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:0	13.63	1128	0.94	13.36	104	196	Idle	90.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.69	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:0	13.63	1116	0.94	13.35	104	196	Idle	90.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.66	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:0	13.63	1116	0.94	13.36	104	196	Idle	90.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.63	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:0	13.63	1112	0.94	13.36	104	196	Idle	91	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.63	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:1	13.63	1104	0.93	13.36	104	196	Idle	91.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:1	13.63	1101	0.93	13.36	104	196	Idle	91.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.6	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:1	13.63	1101	0.92	13.37	104	196	Idle	91.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:1	13.63	1088	0.92	13.36	104	196	Idle	92.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.59	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:1	13.63	1088	0.92	13.37	104	196	Idle	92.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.58	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:1	13.63	1081	0.91	13.37	104	196	Idle	92.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:1	13.63	1070	0.91	13.37	104	196	Idle	92.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:2	13.63	1066	0.91	13.37	104	196	Idle	92.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.5	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:2	12.27	1066	0.9	13.36	104	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:2	12.27	1064	0.9	13.36	104	196	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.53	20.19	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:2	12.27	1064	0.9	13.37	104	196	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	20.11	1.37	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:2	12.27	1052	0.89	13.37	104	196	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.52	19.98	1.36	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:2	12.27	1041	0.89	13.37	104	196	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.48	19.82	1.35	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:3	12.27	1041	0.89	13.38	104	196	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.5	19.64	1.34	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:3	12.27	1036	0.88	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.43	19.45	1.32	4.8	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:24:3	12.27	1032	0.88	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.45	19.11	1.3	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:3	12.27	1032	0.88	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.42	18.98	1.29	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:3	12.27	1022	0.87	13.3	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.44	18.59	1.27	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:3	12.27	1012	0.87	13.3	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.41	18.33	1.25	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:4	12.27	1012	0.87	13.3	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.43	18.22	1.24	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:4	12.27	1004	0.87	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.37	17.81	1.21	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:4	12.27	995	0.86	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.29	17.64	1.2	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:24:4	12.27	986	0.86	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.32	17.48	1.19	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:24:4	10.9	978	0.86	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.28	17.31	1.18	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:24:4	10.9	978	0.86	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.31	17.18	1.17	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:24:4	10.9	972	0.86	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.27	17.03	1.16	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:24:5	10.9	971	0.85	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.28	16.82	1.15	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:24:5	10.9	970	0.85	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.21	16.69	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:24:5	10.9	970	0.85	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.24	16.57	1.13	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:24:5	10.9	965	0.85	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.16	16.45	1.12	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:5	10.9	971	0.85	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.19	16.33	1.11	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:5	10.9	971	0.85	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.12	16.22	1.11	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:6	10.9	964	0.85	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.15	16.13	1.1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:6	10.9	957	0.85	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.08	16.03	1.09	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:6	10.9	957	0.85	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.11	15.96	1.09	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:6	10.9	935	0.84	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.08	15.88	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:6	10.9	941	0.84	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.1	15.81	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:6	10.9	941	0.84	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.03	15.73	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:6	10.9	941	0.84	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.06	15.67	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:7	9.54	939	0.84	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.99	15.62	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:7	9.54	950	0.84	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.02	15.59	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:7	9.54	950	0.84	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.98	15.55	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:7	9.54	940	0.84	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.02	15.52	1.06	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:7	9.54	930	0.84	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.94	15.49	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:7	9.54	930	0.84	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.98	15.46	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:8	9.54	940	0.84	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.9	15.44	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:8	9.54	944	0.84	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.93	15.4	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:8	9.54	944	0.84	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.89	15.37	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:8	9.54	944	0.84	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.95	15.35	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:8	9.54	939	0.84	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.91	15.32	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:8	9.54	945	0.84	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.95	15.32	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:9	8.18	945	0.84	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.93	15.3	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:9	8.18	944	0.84	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.93	15.28	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:9	8.18	944	0.84	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.9	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:9	8.18	944	0.84	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.89	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:9	8.18	943	0.84	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.89	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:9	8.18	941	0.84	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.91	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:24:9	8.18	939	0.84	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.9	15.26	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:0	8.18	939	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.91	15.25	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:0	8.18	934	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.84	15.25	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:0	8.18	934	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	15.24	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:0	8.18	934	0.83	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.25	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:0	8.18	934	0.83	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.24	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:0	8.18	914	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.24	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:1	8.18	929	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	15.24	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:1	8.18	929	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15.23	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:1	8.18	929	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	15.22	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:1	9.54	917	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.23	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:1	9.54	917	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.84	15.23	1.04	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:25:1	9.54	912	0.83	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:1	9.54	914	0.83	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:2	9.54	914	0.83	13.31	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.18	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:2	9.54	917	0.83	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:25:2	9.54	909	0.83	13.31	104	196	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:2	9.54	909	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:2	9.54	914	0.83	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:2	9.54	919	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:3	9.54	895	0.83	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.1	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:3	9.54	895	0.83	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:3	9.54	904	0.83	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:3	9.54	912	0.83	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:3	9.54	902	0.83	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:3	9.54	902	0.83	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:4	6.81	902	0.83	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:4	6.81	903	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.71	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:4	6.81	902	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.72	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:4	6.81	902	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.69	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:4	6.81	902	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.72	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:4	8.18	901	0.83	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.65	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:4	8.18	901	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:5	8.18	907	0.82	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.65	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:5	8.18	907	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.66	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:5	8.18	897	0.82	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:5	8.18	887	0.82	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:5	8.18	902	0.82	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.64	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:5	8.18	902	0.82	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:6	8.18	894	0.82	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:6	8.18	885	0.82	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:6	8.18	911	0.82	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:6	8.18	911	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:6	8.18	883	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.86	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:6	8.18	883	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:6	8.18	883	0.82	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.62	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:7	8.18	891	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:7	8.18	897	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:7	8.18	897	0.82	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:7	8.18	896	0.82	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:7	8.18	896	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.61	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:7	8.18	888	0.82	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:8	8.18	888	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:8	8.18	888	0.82	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:8	8.18	898	0.82	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:8	8.18	895	0.82	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.61	14.9	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:8	8.18	895	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:8	8.18	895	0.82	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.57	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:9	8.18	907	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:9	8.18	907	0.82	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.62	15.04	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:9	8.18	904	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.61	15.07	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:9	8.18	904	0.82	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.59	15.11	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:25:9	8.18	916	0.82	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.61	15.14	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:9	8.18	928	0.82	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.6	15.16	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:25:9	6.81	932	0.82	13.34	104	197	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.59	15.19	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:0	6.81	932	0.82	13.35	104	197	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.63	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:0	6.81	930	0.82	13.32	104	197	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.65	15.19	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:0	6.81	929	0.82	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.63	15.21	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:0	8.18	923	0.82	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.66	15.21	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:0	8.18	923	0.82	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.64	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:0	8.18	922	0.82	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.66	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:1	8.18	920	0.82	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.65	15.23	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:1	8.18	915	0.82	13.32	104	196	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.67	15.23	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:1	8.18	915	0.82	13.34	104	196	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.66	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:26:1	8.18	912	0.82	13.33	104	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	15.23	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:1	8.18	910	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	15.23	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:1	8.18	912	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:1	8.18	912	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.63	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:2	8.18	913	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:2	8.18	914	0.83	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.62	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:2	8.18	914	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:2	8.18	908	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:2	8.18	906	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:2	8.18	904	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:3	8.18	904	0.83	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:3	8.18	917	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:3	8.18	917	0.83	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:3	8.18	909	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:3	8.18	901	0.83	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:3	8.18	911	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:4	8.18	911	0.83	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:4	8.18	912	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:4	8.18	912	0.83	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:4	8.18	884	0.83	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:4	8.18	884	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.66	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:4	8.18	888	0.83	13.42	104	196	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.67	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:4	8.18	893	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.66	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:26:5	10.9	893	0.83	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.65	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:26:5	10.9	908	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.65	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:26:5	10.9	896	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.65	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:26:5	10.9	884	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.62	14.98	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:26:5	10.9	884	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.64	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:26:5	10.9	906	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.62	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:26:6	10.9	906	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.99	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:26:6	10.9	905	0.83	13.42	104	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:6	10.9	893	0.83	13.42	104	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.67	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:6	8.18	893	0.83	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:6	8.18	893	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.68	14.94	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:6	8.18	940	0.83	13.39	104	196	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.64	14.93	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:6	8.18	940	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.64	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:7	8.18	921	0.83	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.63	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:7	8.18	929	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.64	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:7	8.18	937	0.83	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.65	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:7	8.18	937	0.83	13.42	104	196	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:7	6.81	945	0.83	13.4	104	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.66	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:7	6.81	945	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:8	6.81	951	0.83	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:8	6.81	951	0.83	13.38	104	196	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.7	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:8	8.18	936	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.73	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:8	8.18	938	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.74	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:8	8.18	939	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.71	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:8	8.18	939	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.73	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:9	8.18	942	0.83	13.35	104	196	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:9	8.18	942	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.75	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:9	8.18	941	0.83	13.36	104	196	Idle	93.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.75	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:9	8.18	940	0.83	13.39	104	196	Idle	93.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.76	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:9	8.18	930	0.83	13.37	104	196	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.75	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:9	8.18	930	0.83	13.38	104	196	Full Load	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.77	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:26:9	8.18	932	0.83	13.37	104	196	Off Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.7	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:27:0	8.18	932	0.84	13.39	104	196	Off Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.69	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:27:0	9.54	923	0.84	13.37	104	196	Off Idle	92.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.65	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:27:0	9.54	923	0.85	13.39	104	196	Off Idle	91.7	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.62	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:27:0	9.54	915	0.87	13.39	104	196	Off Idle	91.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.55	14.99	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:27:0	9.54	915	0.9	13.4	104	196	Off Idle	90.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.42	15	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:27:0	8.18	915	0.92	13.37	104	196	Off Idle	90	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.28	15.01	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:27:1	8.18	915	0.95	13.4	104	196	Off Idle	89.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.2	15.01	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:27:1	8.18	916	0.98	13.37	104	196	Off Idle	88.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.94	15.01	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:27:1	8.18	916	1.02	13.38	104	196	Off Idle	88.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.72	15.01	1.02	4.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:1	8.18	918	1.06	13.37	104	196	Off Idle	87.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.47	15	1.02	4.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:1	8.18	921	1.08	13.37	104	196	Off Idle	87.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.16	15.01	1.02	4.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:1	8.18	916	1.14	13.36	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.72	15.01	1.02	4.9	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:1	8.18	916	1.17	13.39	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.57	15.01	1.02	5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:27:2	8.18	910	1.21	13.36	104	196	Off Idle	85.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.31	15.01	1.02	5.1	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:27:2	8.18	904	1.25	13.39	104	196	Off Idle	85	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.98	15.01	1.02	5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:27:2	8.18	904	1.32	13.38	104	196	Off Idle	85	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.59	15.01	1.02	5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:27:2	8.18	919	1.37	13.39	104	196	Off Idle	84.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.3	15	1.02	4.9	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:27:2	9.54	938	1.42	13.39	104	196	Off Idle	84.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.07	15	1.02	4.9	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:27:2	9.54	938	1.47	13.4	104	196	Off Idle	85	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.77	15.01	1.02	4.7	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:27:3	9.54	980	1.51	13.4	104	196	Off Idle	85	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.54	15.02	1.02	4.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:27:3	9.54	1023	1.54	13.41	104	196	Off Idle	85	0	2	132	944 Turbo	0.21	Lean	1	14.6	-3.22	15.02	1.02	4.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:3	21.81	1015	1.58	13.43	104	196	Off Idle	85.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.03	15.01	1.02	4.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:3	21.81	1015	1.62	13.45	104	196	Off Idle	85.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.75	15.01	1.02	4.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:3	21.81	1036	1.66	13.43	104	196	Off Idle	85.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-2.59	15.02	1.02	4.3	5.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:3	19.09	1099	1.69	13.44	104	196	Off Idle	85.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.37	15.03	1.02	4.3	5.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:4	19.09	1099	1.72	13.43	104	196	Off Idle	85.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-2.27	15.02	1.02	4.1	5.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:4	19.09	1133	1.75	13.42	104	196	Off Idle	85.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-2.16	15.02	1.02	4.1	5.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:4	19.09	1167	1.78	13.42	104	196	Off Idle	85.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-2.05	15.02	1.02	4.2	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:27:4	20.45	1179	1.8	13.43	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-2.02	15.01	1.02	4.2	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:27:4	20.45	1179	1.81	13.43	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.98	15.02	1.02	4.2	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:27:4	20.45	1226	1.82	13.43	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-1.98	15.03	1.02	4.1	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:27:4	20.45	1249	1.83	13.43	104	196	Off Idle	85.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.96	15.04	1.02	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:27:5	20.45	1249	1.84	13.42	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.97	15.04	1.02	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:27:5	20.45	1288	1.85	13.43	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.99	15.04	1.02	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:27:5	21.81	1293	1.86	13.4	104	196	Off Idle	86	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.98	15.09	1.03	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:27:5	21.81	1293	1.87	13.41	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.06	15.09	1.03	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:27:5	21.81	1301	1.87	13.42	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.06	15.05	1.03	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:5	21.81	1311	1.88	13.41	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.06	14.98	1.02	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:6	21.81	1311	1.89	13.4	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.14	14.87	1.01	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:6	21.81	1316	1.89	13.4	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.16	14.71	1	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:6	21.81	1316	1.9	13.39	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.14	14.51	0.99	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:6	21.81	1327	1.9	13.36	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.16	14.16	0.96	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:6	21.81	1327	1.91	13.37	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.19	13.9	0.95	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:6	23.18	1322	1.91	13.35	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.18	13.6	0.93	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:6	23.18	1335	1.91	13.35	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.14	13.3	0.91	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:7	23.18	1335	1.92	13.37	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.16	13.03	0.89	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:7	23.18	1323	1.92	13.37	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.06	12.79	0.87	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:7	23.18	1325	1.92	13.36	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.06	12.58	0.86	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:7	23.18	1325	1.93	13.38	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.07	12.4	0.84	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:7	23.18	1339	1.93	13.38	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.09	12.27	0.84	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:7	23.18	1327	1.93	13.38	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.08	12.15	0.83	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:8	23.18	1325	1.94	13.36	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.06	12.12	0.83	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:8	23.18	1325	1.94	13.38	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.1	12.12	0.83	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:8	23.18	1316	1.94	13.37	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.06	12.14	0.83	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:8	23.18	1323	1.95	13.37	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.05	12.19	0.83	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:8	23.18	1323	1.95	13.38	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.1	12.25	0.83	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:8	23.18	1315	1.95	13.37	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.06	12.34	0.84	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:9	24.54	1305	1.95	13.37	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.07	12.49	0.85	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:27:9	24.54	1299	1.95	13.37	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.12	12.6	0.86	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:9	24.54	1299	1.95	13.39	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.09	12.73	0.87	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:9	24.54	1292	1.95	13.37	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.04	12.83	0.87	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:27:9	24.54	1289	1.95	13.36	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.07	12.93	0.88	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:9	24.54	1289	1.95	13.36	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.06	13.01	0.89	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:27:9	25.9	1268	1.95	13.36	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.02	13.13	0.89	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:28:0	25.9	1256	1.95	13.35	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.98	13.21	0.9	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:28:0	25.9	1228	1.95	13.36	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.98	13.28	0.9	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:28:0	24.54	1228	1.95	13.36	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.93	13.33	0.91	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:28:0	24.54	1233	1.95	13.35	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.9	13.39	0.91	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:28:0	24.54	1217	1.95	13.38	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.87	13.42	0.91	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:28:0	24.54	1217	1.94	13.39	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.84	13.46	0.92	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:28:1	24.54	1207	1.94	13.4	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.85	13.47	0.92	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:28:1	24.54	1200	1.94	13.41	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.8	13.52	0.92	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:1	24.54	1200	1.93	13.41	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.76	13.55	0.92	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:1	24.54	1195	1.93	13.44	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.79	13.56	0.92	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:1	24.54	1190	1.93	13.42	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.75	13.56	0.92	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:1	24.54	1178	1.92	13.41	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.73	13.57	0.92	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:1	24.54	1167	1.92	13.41	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.7	13.58	0.92	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:2	24.54	1158	1.91	13.39	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.69	13.57	0.92	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:2	24.54	1156	1.91	13.4	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.68	13.55	0.92	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:2	23.18	1156	1.9	13.4	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.68	13.53	0.92	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:2	23.18	1141	1.9	13.37	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.67	13.53	0.92	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:2	23.18	1141	1.89	13.4	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.65	13.5	0.92	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:2	23.18	1119	1.89	13.38	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.55	13.46	0.92	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:3	23.18	1111	1.88	13.41	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.54	13.44	0.92	4.7	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:3	23.18	1103	1.88	13.39	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.47	13.42	0.91	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:3	23.18	1091	1.87	13.4	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.51	13.39	0.91	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:3	23.18	1091	1.87	13.41	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.44	13.34	0.91	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:3	23.18	1077	1.87	13.41	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.46	13.32	0.91	4.8	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:3	23.18	1059	1.86	13.41	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.44	13.29	0.91	4.8	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:4	23.18	1059	1.86	13.4	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.44	13.25	0.9	4.9	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:4	23.18	1056	1.85	13.42	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.44	13.22	0.9	4.9	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:4	23.18	1052	1.85	13.4	104	196	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.35	13.18	0.9	4.9	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:4	23.18	1052	1.84	13.4	104	196	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.39	13.16	0.9	4.9	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:4	23.18	1040	1.84	13.38	104	196	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.28	13.13	0.89	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:4	23.18	1058	1.84	13.36	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.28	13.09	0.89	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:28:4	23.18	1058	1.84	13.36	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.14	13.06	0.89	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:28:5	23.18	1069	1.84	13.35	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.02	13.03	0.89	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:28:5	23.18	1080	1.84	13.39	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1	12.99	0.89	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:28:5	23.18	1096	1.85	13.37	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.9	12.96	0.88	4.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:28:5	21.81	1139	1.85	13.39	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.93	12.94	0.88	4.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:28:5	21.81	1139	1.85	13.38	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.85	12.92	0.88	4.3	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:28:5	21.81	1183	1.86	13.38	104	196	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.89	12.91	0.88	4.3	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:28:6	20.45	1183	1.87	13.38	104	196	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.86	12.89	0.88	4.3	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:28:6	20.45	1197	1.88	13.38	104	196	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.82	12.87	0.88	4.3	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:28:6	20.45	1249	1.89	13.39	104	196	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.82	12.85	0.88	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:6	20.45	1273	1.9	13.39	104	196	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.79	12.84	0.87	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:6	21.81	1273	1.91	13.39	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.79	12.83	0.87	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:6	21.81	1288	1.92	13.39	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.78	12.82	0.87	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:6	20.45	1307	1.94	13.37	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.81	12.81	0.87	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:7	20.45	1321	1.96	13.38	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.76	12.79	0.87	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:7	20.45	1321	1.97	13.35	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.71	12.78	0.87	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:7	20.45	1329	1.98	13.36	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.74	12.76	0.87	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:7	20.45	1329	2	13.36	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.71	12.75	0.87	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:7	20.45	1355	2.01	13.38	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.68	12.74	0.87	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:7	21.81	1340	2.02	13.38	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.75	12.75	0.87	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:8	21.81	1349	2.03	13.39	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.79	12.75	0.87	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:8	21.81	1349	2.04	13.4	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.81	12.75	0.87	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:8	21.81	1362	2.04	13.4	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.79	12.75	0.87	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:8	21.81	1373	2.06	13.39	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.76	12.78	0.87	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:28:8	21.81	1387	2.07	13.41	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.79	12.79	0.87	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:8	21.81	1387	2.08	13.39	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.78	12.81	0.87	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:9	21.81	1403	2.09	13.39	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.74	12.84	0.87	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:9	21.81	1421	2.1	13.41	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.79	12.87	0.88	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:9	21.81	1421	2.1	13.43	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.72	12.89	0.88	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:28:9	21.81	1468	2.11	13.44	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.73	12.94	0.88	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:9	24.54	1472	2.12	13.43	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.72	12.97	0.88	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:9	24.54	1473	2.12	13.41	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.74	12.99	0.89	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:28:9	23.18	1507	2.13	13.4	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.74	13.03	0.89	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:0	23.18	1542	2.14	13.42	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.8	13.08	0.89	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:0	23.18	1542	2.15	13.42	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.81	13.13	0.89	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:0	24.54	1555	2.15	13.4	104	196	Off Idle	86.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.79	13.17	0.9	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:0	24.54	1555	2.16	13.42	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.83	13.22	0.9	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:0	24.54	1562	2.17	13.42	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.85	13.25	0.9	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:0	24.54	1576	2.18	13.42	104	196	Off Idle	86.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.84	13.29	0.91	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:1	24.54	1593	2.19	13.42	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.84	13.34	0.91	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:1	24.54	1593	2.2	13.42	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.84	13.39	0.91	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:1	24.54	1608	2.21	13.42	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.84	13.44	0.92	3.9	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:1	25.9	1650	2.21	13.42	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.85	13.51	0.92	3.9	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:1	25.9	1642	2.22	13.42	104	196	Off Idle	86.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.86	13.54	0.92	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:1	25.9	1648	2.23	13.42	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-0.85	13.58	0.92	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:1	25.9	1667	2.24	13.42	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.85	13.61	0.93	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:2	25.9	1678	2.25	13.42	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-0.86	13.63	0.93	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:2	25.9	1678	2.25	13.42	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.86	13.65	0.93	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:2	25.9	1698	2.26	13.41	104	196	Off Idle	86.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-0.86	13.68	0.93	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:2	25.9	1704	2.27	13.41	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.85	13.71	0.93	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:2	25.9	1711	2.28	13.39	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.94	13.75	0.94	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:2	27.27	1744	2.29	13.38	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-0.91	13.77	0.94	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:3	27.27	1742	2.3	13.37	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.92	13.83	0.94	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:3	27.27	1750	2.3	13.36	104	196	Off Idle	86.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.91	13.88	0.95	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:3	27.27	1754	2.31	13.35	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.93	13.93	0.95	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:3	27.27	1782	2.32	13.35	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-0.91	13.98	0.95	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:3	27.27	1782	2.32	13.36	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.96	14.06	0.96	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:3	27.27	1782	2.33	13.37	104	196	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.96	14.12	0.96	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:4	27.27	1802	2.34	13.37	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.01	14.19	0.97	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:4	27.27	1820	2.35	13.37	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.97	14.26	0.97	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:4	27.27	1820	2.35	13.37	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.96	14.34	0.98	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:4	27.27	1842	2.36	13.38	104	196	Off Idle	86.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.95	14.42	0.98	3.7	4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:4	27.27	1858	2.37	13.38	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1	14.49	0.99	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:4	27.27	1860	2.38	13.39	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1	14.54	0.99	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:29:4	27.27	1860	2.39	13.4	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1	14.59	0.99	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:29:5	27.27	1874	2.39	13.41	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-0.96	14.68	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:29:5	27.27	1892	2.4	13.41	104	196	Off Idle	86.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-0.99	14.7	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:29:5	27.27	1903	2.41	13.39	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-0.98	14.75	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:5	27.27	1903	2.41	13.36	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-0.93	14.79	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:5	28.63	1938	2.42	13.34	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-0.96	14.8	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:5	28.63	1948	2.43	13.34	104	196	Off Idle	86.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-0.97	14.84	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:6	28.63	1966	2.43	13.34	104	196	Off Idle	86	0	2	132	944 Turbo	0.23	Lean	1	14.6	-1	14.87	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:6	28.63	1978	2.44	13.33	104	196	Off Idle	86	0	2	132	944 Turbo	0.18	Lean	1	14.6	-1.03	14.92	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:6	28.63	2004	2.44	13.35	104	196	Off Idle	86	0	2	132	944 Turbo	0.13	Lean	1	14.6	-1.05	14.98	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:6	28.63	2016	2.45	13.35	104	196	Off Idle	86	0	2	132	944 Turbo	0.1	Lean	1	14.6	-1.1	15.04	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:6	28.63	2022	2.46	13.36	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-1.13	15.11	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:6	28.63	2041	2.46	13.36	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-1.14	15.17	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:6	28.63	2064	2.47	13.38	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-1.16	15.23	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:7	28.63	2071	2.48	13.38	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-1.16	15.3	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:7	28.63	2071	2.48	13.39	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-1.16	15.34	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:7	28.63	2088	2.49	13.38	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-1.12	15.36	1.05	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:7	28.63	2136	2.5	13.36	104	196	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-1.09	15.38	1.05	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:29:7	29.99	2136	2.51	13.38	104	196	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-1.02	15.36	1.05	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:7	29.99	2116	2.51	13.38	104	196	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-1.03	15.34	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:8	29.99	2127	2.52	13.38	104	196	Off Idle	85.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-1.02	15.32	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:8	29.99	2134	2.52	13.37	104	196	Off Idle	85.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-1.02	15.29	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:8	29.99	2146	2.53	13.38	104	196	Off Idle	85.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-1.03	15.25	1.04	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:29:8	29.99	2149	2.53	13.39	104	196	Off Idle	85.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-1.03	15.23	1.04	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:8	29.99	2160	2.54	13.41	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-1.06	15.2	1.04	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:8	29.99	2177	2.55	13.41	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.07	15.17	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:9	29.99	2183	2.56	13.41	104	196	Off Idle	85.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-1.07	15.17	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:9	29.99	2202	2.56	13.41	104	196	Off Idle	85.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-1.02	15.16	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:9	29.99	2202	2.57	13.41	104	196	Off Idle	85.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-1.01	15.15	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:9	29.99	2233	2.58	13.41	104	196	Off Idle	84.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-0.97	15.12	1.03	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:29:9	29.99	2266	2.58	13.4	104	196	Off Idle	84.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-0.98	15.09	1.03	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:9	29.99	2265	2.59	13.41	104	196	Off Idle	84.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-0.95	15.07	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:29:9	29.99	2265	2.59	13.41	104	196	Off Idle	83.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.98	15.04	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:30:0	29.99	2290	2.6	13.4	104	196	Off Idle	83.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.97	15.01	1.02	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:30:0	29.99	2310	2.61	13.4	104	196	Off Idle	83.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.91	14.98	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:30:0	29.99	2310	2.62	13.41	104	196	Off Idle	83	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.92	14.94	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:30:0	31.36	2329	2.62	13.41	104	196	Off Idle	82.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-0.93	14.9	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:0	31.36	2339	2.63	13.39	104	196	Off Idle	81.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-0.91	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:0	31.36	2344	2.64	13.39	104	196	Off Idle	81.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-0.87	14.87	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:1	31.36	2374	2.65	13.37	104	196	Off Idle	80.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-0.92	14.86	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:1	31.36	2382	2.65	13.37	104	196	Off Idle	80.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-0.94	14.85	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:1	31.36	2387	2.66	13.35	104	196	Off Idle	78.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-0.95	14.84	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:1	31.36	2400	2.67	13.35	104	196	Off Idle	78	0	2	132	944 Turbo	0.23	Lean	1	14.6	-0.97	14.87	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:1	31.36	2421	2.68	13.35	104	196	Off Idle	77.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-0.97	14.89	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:1	31.36	2448	2.69	13.37	104	196	Off Idle	76.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.96	14.94	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:1	31.36	2442	2.69	13.37	104	196	Off Idle	76	0	2	132	944 Turbo	0.23	Lean	1	14.6	-0.99	14.96	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:2	31.36	2447	2.7	13.38	104	196	Off Idle	75.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-0.96	14.96	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:2	31.36	2457	2.71	13.39	104	196	Off Idle	74.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-0.93	14.97	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:2	31.36	2458	2.72	13.39	104	196	Off Idle	74	0	2	132	944 Turbo	0.36	Rich	1	14.6	-0.92	15.01	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:2	31.36	2474	2.72	13.39	104	196	Off Idle	73.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-0.91	15.09	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:2	31.36	2466	2.73	13.38	104	196	Off Idle	72.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-0.88	15.11	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:2	31.36	2468	2.73	13.4	104	196	Off Idle	71.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.91	15.1	1.03	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:3	31.36	2468	2.74	13.38	104	196	Off Idle	71.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-0.88	15.07	1.03	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:3	31.36	2478	2.75	13.38	104	196	Off Idle	70.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.84	15.04	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:3	31.36	2478	2.75	13.38	104	196	Off Idle	70.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.89	15.01	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:3	31.36	2511	2.76	13.39	104	196	Off Idle	69.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.8	14.96	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:3	31.36	2516	2.77	13.36	104	196	Off Idle	69.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.76	14.95	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:3	31.36	2536	2.77	13.37	104	196	Off Idle	68.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.79	14.94	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:4	31.36	2583	2.78	13.39	104	196	Off Idle	68	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.81	14.86	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:30:4	31.36	2583	2.78	13.38	104	196	Off Idle	67.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.78	14.82	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:30:4	31.36	2589	2.79	13.38	104	196	Off Idle	67.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.81	14.8	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:30:4	31.36	2607	2.8	13.38	104	196	Off Idle	66.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.83	14.8	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:30:4	31.36	2626	2.8	13.39	104	196	Off Idle	66.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.78	14.83	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:30:4	31.36	2626	2.81	13.4	104	196	Off Idle	65.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-0.79	14.85	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:30:4	31.36	2640	2.81	13.38	104	196	Off Idle	65.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-0.75	14.88	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:30:5	31.36	2651	2.81	13.38	104	196	Off Idle	64.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-0.71	14.89	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:5	31.36	2656	2.82	13.4	104	196	Off Idle	63.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-0.71	14.88	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:5	31.36	2700	2.83	13.4	104	196	Off Idle	62.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-0.61	14.86	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:5	31.36	2706	2.84	13.41	104	196	Off Idle	61.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-0.61	14.88	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:5	31.36	2723	2.85	13.39	104	196	Off Idle	60.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-0.51	14.91	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:30:5	31.36	2723	2.86	13.41	104	196	Off Idle	59.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-0.47	14.94	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:30:6	31.36	2743	2.86	13.41	104	196	Off Idle	59.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-0.45	14.97	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:30:6	31.36	2758	2.87	13.41	104	196	Off Idle	58.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-0.46	15.02	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:30:6	31.36	2758	2.88	13.42	104	196	Off Idle	57.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-0.47	15.04	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:30:6	31.36	2775	2.89	13.42	104	196	Off Idle	56.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-0.41	15.06	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:6	31.36	2784	2.9	13.42	104	196	Off Idle	56.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-0.43	15.12	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:30:6	31.36	2797	2.9	13.42	104	196	Off Idle	55.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-0.38	15.17	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:6	31.36	2802	2.91	13.42	104	196	Off Idle	54.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-0.38	15.18	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:7	31.36	2809	2.92	13.42	104	196	Off Idle	54	0	2	132	944 Turbo	0.57	Rich	1	14.6	-0.33	15.16	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:7	31.36	2812	2.93	13.42	104	196	Off Idle	53.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.32	15.11	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:7	31.36	2822	2.94	13.42	104	196	Off Idle	53	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.31	15.05	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:7	31.36	2832	2.95	13.42	104	196	Off Idle	52.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.26	15	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:7	31.36	2859	2.96	13.42	104	196	Off Idle	51.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.26	14.95	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:7	31.36	2859	2.96	13.42	104	196	Off Idle	51.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.26	14.92	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:30:8	31.36	2878	2.97	13.42	104	196	Off Idle	50.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.2	14.88	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:30:8	31.36	2888	2.98	13.42	104	196	Off Idle	50.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-0.2	14.82	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:30:8	31.36	2901	2.99	13.42	104	196	Off Idle	49.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-0.17	14.81	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:30:8	31.36	2903	3	13.42	104	196	Off Idle	48.8	0	2	132	944 Turbo	0.61	Lean	1	14.6	-0.05	14.81	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:30:8	31.36	2916	3.01	13.42	104	196	Off Idle	48.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	0.01	14.83	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:19:30:8	31.36	2929	3.02	13.41	104	196	Off Idle	47	0	2	132	944 Turbo	0.5	Lean	1	14.6	0.02	14.83	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:19:30:9	31.36	2934	3.03	13.4	104	196	Off Idle	46.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	0.17	14.83	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:19:30:9	31.36	2953	3.04	13.39	104	196	Off Idle	45.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	0.35	14.84	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:19:30:9	31.36	2966	3.05	13.38	104	196	Off Idle	45.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	0.38	14.88	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:30:9	31.36	2998	3.06	13.38	104	196	Off Idle	44.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	0.5	14.91	1.02	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:9	31.36	2998	3.07	13.37	104	196	Off Idle	44.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	0.54	14.95	1.02	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:30:9	31.36	3075	3.08	13.38	104	196	Off Idle	44.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	0.65	14.98	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:19:30:9	31.36	3075	3.09	13.38	104	196	Off Idle	43.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	0.7	15.01	1.02	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:0	31.36	3075	3.1	13.38	104	196	Off Idle	43.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	0.76	15.09	1.03	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:0	31.36	3106	3.12	13.38	104	196	Off Idle	42.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	0.79	15.15	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:0	31.36	3146	3.13	13.38	104	196	Off Idle	42.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	0.82	15.19	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:0	31.36	3138	3.14	13.39	104	196	Off Idle	42.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	0.83	15.18	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:0	31.36	3143	3.15	13.37	104	196	Off Idle	42.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	0.88	15.13	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:0	31.36	3162	3.16	13.38	104	196	Off Idle	42.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	0.99	15.05	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:1	31.36	3167	3.17	13.39	104	196	Off Idle	42	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.99	14.95	1.02	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:1	31.36	3187	3.18	13.38	104	196	Off Idle	41.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.09	14.89	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:1	31.36	3187	3.19	13.38	104	196	Off Idle	41.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	1.14	14.81	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:1	31.36	3188	3.21	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	1.21	14.74	1	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:1	31.36	3198	3.22	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	1.22	14.65	1	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:1	31.36	3223	3.23	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	1.25	14.56	0.99	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:1	31.36	3223	3.23	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	1.28	14.55	0.99	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:2	31.36	3246	3.24	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.36	14.55	0.99	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:2	31.36	3263	3.25	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.38	14.58	0.99	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:2	31.36	3265	3.26	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.45	14.63	1	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:2	31.36	3294	3.27	13.36	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	1.48	14.66	1	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:2	31.36	3310	3.28	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.49	14.7	1	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:2	31.36	3325	3.28	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.48	14.72	1	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:31:3	31.36	3339	3.28	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.54	14.73	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:3	31.36	3335	3.29	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.55	14.76	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:3	31.36	3344	3.3	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.58	14.76	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:19:31:3	31.36	3372	3.3	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.7	14.74	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:3	31.36	3377	3.31	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.67	14.73	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:3	31.36	3404	3.31	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.59	14.7	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:4	31.36	3408	3.32	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.71	14.71	1	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:4	31.36	3453	3.32	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	1.83	14.72	1	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:4	31.36	3453	3.33	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.81	14.73	1	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:4	31.36	3490	3.34	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.87	14.73	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:4	31.36	3512	3.34	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	2.03	14.73	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:4	31.36	3524	3.35	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	1.96	14.71	1	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:19:31:4	31.36	3531	3.36	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	1.95	14.72	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:5	31.36	3564	3.36	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	2.12	14.73	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:19:31:5	31.36	3582	3.37	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	2.29	14.74	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:5	31.36	3586	3.38	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	2.26	14.8	1.01	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:5	31.36	3598	3.39	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	2.34	14.84	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:5	31.36	3614	3.4	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	2.41	14.91	1.02	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:31:5	31.36	3621	3.4	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	2.45	14.98	1.02	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:19:31:6	31.36	3619	3.41	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	2.5	15.09	1.03	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:19:31:6	31.36	3619	3.42	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	2.55	15.13	1.03	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:19:31:6	31.36	3627	3.43	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	2.62	15.13	1.03	3.6	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:6	31.36	3628	3.43	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	2.63	15.1	1.03	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:19:31:6	31.36	3638	3.44	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	2.66	15.08	1.03	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:19:31:6	31.36	3649	3.45	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	2.75	15.02	1.02	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:6	31.36	3655	3.46	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.92	14.92	1.02	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:7	31.36	3675	3.47	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	2.97	14.84	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:7	29.99	3710	3.48	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	3.1	14.77	1.01	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:7	29.99	3731	3.49	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	3.13	14.66	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:7	29.99	3736	3.5	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	3.12	14.58	0.99	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:7	29.99	3747	3.51	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	3.16	14.56	0.99	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:7	29.99	3778	3.51	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	3.18	14.57	0.99	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:8	29.99	3782	3.52	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	3.1	14.61	1	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:8	29.99	3810	3.53	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	3.06	14.66	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:8	29.99	3825	3.53	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	3.15	14.7	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:8	29.99	3842	3.54	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	3.33	14.73	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:8	31.36	3857	3.55	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	3.53	14.74	1	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:19:31:8	31.36	3862	3.56	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	3.74	14.77	1.01	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:19:31:9	31.36	3881	3.57	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	3.94	14.79	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:19:31:9	31.36	3886	3.58	13.35	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	4.04	14.8	1.01	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:19:31:9	31.36	3904	3.59	13.32	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	4.05	14.82	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:31:9	29.99	3946	3.6	13.32	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	4.05	14.84	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:31:9	29.99	3968	3.61	13.31	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	4.08	14.88	1.01	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:9	29.99	3974	3.62	13.31	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	4.16	14.92	1.02	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:19:31:9	29.99	4020	3.63	13.31	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	4.3	14.98	1.02	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:19:32:0	29.99	4020	3.64	13.31	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	4.47	15	1.02	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:0	29.99	4096	3.66	13.3	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	4.64	14.99	1.02	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:0	29.99	4062	3.67	13.32	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	4.78	14.96	1.02	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:0	29.99	4065	3.68	13.34	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.58	Lean	1	14.6	4.9	14.9	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:0	29.99	4118	3.69	13.34	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	4.95	14.88	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:0	29.99	4164	3.71	13.37	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Lean	1	14.6	5.13	14.76	1.01	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:19:32:1	29.99	4177	3.72	13.38	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	5.26	14.7	1	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:19:32:1	29.99	4180	3.73	13.38	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	5.47	14.62	1	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:19:32:1	29.99	4206	3.75	13.38	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	5.46	14.54	0.99	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:19:32:1	29.99	4224	3.76	13.39	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	5.61	14.47	0.99	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:19:32:1	29.99	4226	3.79	13.41	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	5.64	14.45	0.98	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:19:32:1	29.99	4247	3.8	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	5.65	14.45	0.98	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:19:32:1	29.99	4283	3.82	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	5.71	14.47	0.99	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:19:32:2	29.99	4312	3.84	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	5.87	14.49	0.99	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:19:32:2	29.99	4316	3.85	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	6.07	14.51	0.99	3.5	7.6	ON	28 Pin	OFF	Removed	Disabled
03:19:32:2	28.63	4354	3.87	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	6.31	14.51	0.99	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:2	28.63	4340	3.88	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	6.52	14.46	0.99	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:2	28.63	4343	3.9	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	6.67	14.45	0.98	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:19:32:2	28.63	4348	3.92	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	6.8	14.39	0.98	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:19:32:3	28.63	4386	3.94	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	6.96	14.35	0.98	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:19:32:3	28.63	4382	3.96	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	7.02	14.33	0.98	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:19:32:3	28.63	4388	3.97	13.36	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.18	14.29	0.97	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:19:32:3	28.63	4416	3.99	13.35	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	7.31	14.23	0.97	3.5	8.2	ON	28 Pin	OFF	Removed	Disabled
03:19:32:3	28.63	4439	4	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.43	14.15	0.96	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:19:32:3	28.63	4440	4.02	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	7.57	14.08	0.96	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:19:32:4	28.63	4456	4.04	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	7.89	13.99	0.95	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:19:32:4	28.63	4487	4.06	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.03	13.94	0.95	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:19:32:4	28.63	4515	4.07	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	8.14	13.88	0.95	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:4	28.63	4516	4.08	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	8.21	13.8	0.94	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:32:4	27.27	4516	4.09	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	8.33	13.78	0.94	3.4	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:32:4	27.27	4600	4.11	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	8.57	13.66	0.93	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:32:4	27.27	4609	4.12	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	8.55	13.61	0.93	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:19:32:5	27.27	4633	4.13	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	8.67	13.59	0.93	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:32:5	27.27	4633	4.14	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	8.89	13.59	0.93	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:32:5	28.63	4712	4.16	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	8.89	13.55	0.92	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:32:5	28.63	4685	4.17	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	8.98	13.53	0.92	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:19:32:5	27.27	4706	4.18	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	9.09	13.47	0.92	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:19:32:5	28.63	4706	4.2	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	9.12	13.45	0.92	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:19:32:6	27.27	4722	4.21	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	9.08	13.45	0.92	3.5	9	ON	28 Pin	OFF	Removed	Disabled
03:19:32:6	27.27	4763	4.22	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	9.12	13.41	0.91	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:19:32:6	27.27	4769	4.22	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	9.17	13.42	0.91	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:32:6	27.27	4788	4.23	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	9.27	13.4	0.91	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:32:6	27.27	4820	4.24	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	9.25	13.39	0.91	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:19:32:6	28.63	4840	4.25	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	9.26	13.38	0.91	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:19:32:6	28.63	4846	4.25	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	9.24	13.37	0.91	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:32:7	28.63	4866	4.25	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	9.19	13.34	0.91	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:32:7	28.63	4892	4.26	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	9.14	13.26	0.9	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:32:7	28.63	4903	4.26	13.38	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	9.12	13.2	0.9	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:32:7	27.27	4947	4.27	13.35	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	9.22	12.99	0.88	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:32:7	27.27	4928	4.28	13.36	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	9.25	12.73	0.87	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:32:7	27.27	4932	4.28	13.34	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.7	9.33	12.59	0.86	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:32:8	27.27	4948	4.29	13.35	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.29	12.3	0.84	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:32:8	27.27	5005	4.29	13.37	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.38	11.83	0.81	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:32:8	28.63	5005	4.3	13.41	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.91	Rich	1	14.6	9.3	11.54	0.79	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:32:8	28.63	5003	4.3	13.41	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.92	Rich	1	14.6	9.32	11.08	0.75	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:8	28.63	5003	4.31	13.39	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.92	Rich	1	14.6	9.33	10.68	0.73	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:8	28.63	5054	4.31	13.38	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.92	Rich	1	14.6	9.46	10.49	0.71	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:9	28.63	5104	4.32	13.38	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.92	Rich	1	14.7	9.39	10.36	0.71	3.4	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:9	28.63	5144	4.32	13.37	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.92	Rich	1	14.6	9.41	10.3	0.7	3.4	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:9	28.63	5146	4.32	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.93	Rich	1	14.7	9.33	10.28	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:9	28.63	5187	4.33	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.93	Rich	1	14.6	9.38	10.26	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:9	28.63	5219	4.33	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.93	Rich	1	14.6	9.4	10.26	0.7	3.4	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:9	28.63	5240	4.33	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.94	Rich	1	14.6	9.31	10.22	0.7	3.4	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:32:9	28.63	5239	4.34	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.93	Rich	1	14.6	9.25	10.21	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:33:0	28.63	5266	4.34	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.93	Rich	1	14.6	9.27	10.21	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:33:0	28.63	5285	4.34	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.93	Rich	1	14.6	9.3	10.21	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:33:0	28.63	5286	4.35	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.93	Rich	1	14.6	9.3	10.21	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:33:0	28.63	5340	4.35	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.93	Rich	1	14.6	9.33	10.23	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:33:0	28.63	5313	4.35	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.93	Rich	1	14.6	9.1	10.24	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:33:0	28.63	5323	4.35	13.4	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.93	Rich	1	14.6	8.51	10.24	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:33:1	28.63	5306	4.33	13.4	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.93	Rich	1	14.6	7.39	10.22	0.7	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:33:1	28.63	5246	4.28	13.4	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.93	Rich	1	14.6	6.48	10.24	0.7	3.6	10.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:1	32.72	5036	4.21	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.92	Rich	1	14.6	4.29	10.24	0.7	3.7	8.4	ON	28 Pin	OFF	Removed	Disabled
03:19:33:1	32.72	5020	4.11	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.92	Rich	1	14.6	1.86	10.23	0.7	3.7	6.5	ON	28 Pin	OFF	Removed	Disabled
03:19:33:1	32.72	4889	3.95	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	-0.47	10.21	0.7	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:33:1	32.72	4830	3.75	13.44	104	196	Full Load	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	-2.59	10.21	0.7	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:33:1	34.08	4831	3.45	13.42	104	196	Full Load	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.68	10.23	0.7	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:33:2	34.08	4755	3.24	13.44	104	196	Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.54	10.32	0.7	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:33:2	34.08	4737	3.03	13.43	104	196	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.95	10.41	0.71	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:2	35.45	4740	2.83	13.46	104	196	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.06	10.85	0.74	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:2	35.45	4744	2.63	13.46	104	196	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.64	11.02	0.75	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:2	35.45	4716	2.35	13.46	104	196	Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.4	11.52	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:2	32.72	4623	2.18	13.48	104	196	Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.82	11.68	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:3	27.27	4578	2	13.45	104	196	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.1	12.11	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:3	21.81	4572	1.81	13.46	104	196	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.34	12.33	0.84	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:3	20.45	4480	1.61	13.45	104	196	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.46	12.45	0.85	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:3	20.45	4537	1.41	13.41	104	196	Idle	41.5	0	2	132	944 Turbo	0.75	Lean	1	14.6	-9.68	12.67	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:3	20.45	4532	1.22	13.4	104	196	Idle	41.5	0	2	132	944 Turbo	0.7	Lean	1	14.6	-9.69	12.71	0.87	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:3	20.45	4476	1.06	13.42	104	196	Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.78	12.61	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:33:4	20.45	4401	0.93	13.41	104	196	Idle	40.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.86	12.42	0.85	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:4	20.45	4410	0.83	13.39	104	196	Idle	39.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.81	12.19	0.83	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:4	20.45	4380	0.75	13.4	104	196	Idle	39.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.8	12	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:4	20.45	4341	0.7	13.42	104	196	Idle	38	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.86	11.9	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:4	20.45	4294	0.74	13.42	104	196	Idle	36.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.87	12	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:4	20.45	4275	0.8	13.42	104	196	Idle	35.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.85	12.19	0.83	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:4	20.45	4224	0.87	13.42	104	196	Idle	34.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.87	12.66	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:5	20.45	4216	0.94	13.39	104	196	Idle	32.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.87	13.4	0.91	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:5	20.45	4162	1.02	13.38	104	196	Idle	31	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.81	14.26	0.97	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:5	20.45	4156	1.09	13.39	104	196	Idle	29.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	15.14	1.03	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:5	20.45	4112	1.16	13.43	104	196	Full Load	27.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	16.04	1.09	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:5	20.45	4071	1.22	13.45	104	196	Off Idle	25.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	16.92	1.15	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:5	20.45	4066	1.25	13.47	104	196	Off Idle	24.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	17.75	1.21	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:6	20.45	4019	1.31	13.49	104	196	Off Idle	22.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	18.5	1.26	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:33:6	13.63	3968	1.42	13.48	104	196	Off Idle	21.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	19.48	1.33	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:33:6	13.63	3968	1.51	13.48	104	196	Off Idle	21.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	19.48	1.33	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:33:6	16.36	3962	1.68	13.46	104	196	Off Idle	22.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.21	20.1	1.37	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:33:6	21.81	3894	1.8	13.45	104	196	Off Idle	23.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.61	20.21	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:33:6	21.81	3815	1.9	13.46	104	196	Off Idle	24.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-6.86	20.22	1.38	3.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:33:6	24.54	3796	1.99	13.46	104	196	Off Idle	25.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-5.99	20.22	1.38	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:33:7	27.27	3652	2.08	13.46	104	196	Off Idle	26.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-4.92	20.23	1.38	3.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:19:33:7	29.99	3581	2.23	13.43	104	196	Off Idle	28.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-3.88	20.24	1.38	3.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:19:33:7	32.72	3550	2.33	13.43	104	196	Off Idle	29.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-2.45	20.25	1.38	3.9	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:33:7	35.45	3386	2.43	13.41	104	196	Off Idle	31.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-1.63	20.25	1.38	4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:19:33:7	34.08	3188	2.52	13.41	104	196	Off Idle	33.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-1.02	20.26	1.38	4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:19:33:7	34.08	3260	2.6	13.41	104	196	Off Idle	36.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-0.51	20.27	1.38	3.9	5.8	ON	28 Pin	OFF	Removed	Disabled
03:19:33:8	34.08	3252	2.72	13.43	104	196	Off Idle	38.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	0.11	20.27	1.38	3.7	6.5	ON	28 Pin	OFF	Removed	Disabled
03:19:33:8	34.08	3194	2.8	13.41	104	196	Off Idle	39.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	0.32	20.27	1.38	3.7	6.5	ON	28 Pin	OFF	Removed	Disabled
03:19:33:8	34.08	3176	2.87	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	0.49	20.27	1.38	3.8	6.6	ON	28 Pin	OFF	Removed	Disabled
03:19:33:8	31.36	3093	2.95	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	0.71	20.15	1.37	3.7	6.2	ON	28 Pin	OFF	Removed	Disabled
03:19:33:8	31.36	3122	3.01	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	0.87	19.86	1.35	3.7	6.2	ON	28 Pin	OFF	Removed	Disabled
03:19:33:8	31.36	3157	3.07	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	1.02	19.46	1.33	3.6	6.2	ON	28 Pin	OFF	Removed	Disabled
03:19:33:9	31.36	3167	3.13	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	1.12	19.03	1.3	3.6	6.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:9	31.36	3173	3.18	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	1.24	18.47	1.26	3.6	6.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:9	31.36	3205	3.24	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	1.37	17.51	1.19	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:9	31.36	3234	3.26	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	1.46	17.17	1.17	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:9	31.36	3255	3.28	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Lean	1	14.6	1.57	16.12	1.1	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:19:33:9	31.36	3258	3.29	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.67	15.4	1.05	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:19:33:9	31.36	3280	3.3	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	1.77	14.75	1	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:19:34:0	31.36	3284	3.3	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.89	14.1	0.97	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:19:34:0	31.36	3285	3.3	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	2	13.96	0.95	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:19:34:0	31.36	3285	3.31	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.06	13.57	0.92	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:19:34:0	31.36	3294	3.31	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.2	13.43	0.91	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:19:34:0	31.36	3280	3.31	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.26	13.35	0.91	3.6	6.5	ON	28 Pin	OFF	Removed	Disabled
03:19:34:0	31.36	3284	3.32	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.31	13.38	0.91	3.6	6.5	ON	28 Pin	OFF	Removed	Disabled
03:19:34:1	31.36	3286	3.32	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.32	13.39	0.91	3.6	6.6	ON	28 Pin	OFF	Removed	Disabled
03:19:34:1	31.36	3285	3.33	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.54	13.44	0.92	3.6	6.6	ON	28 Pin	OFF	Removed	Disabled
03:19:34:1	29.99	3305	3.34	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.63	13.46	0.92	3.6	6.6	ON	28 Pin	OFF	Removed	Disabled
03:19:34:1	29.99	3308	3.35	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.7	13.46	0.92	3.6	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:34:1	29.99	3334	3.35	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	2.86	13.46	0.92	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:34:1	29.99	3340	3.36	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	2.96	13.45	0.92	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:34:1	29.99	3342	3.37	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.94	13.45	0.92	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:19:34:2	29.99	3370	3.38	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.15	13.48	0.92	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:2	29.99	3388	3.39	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.22	13.48	0.92	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:2	29.99	3400	3.4	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	3.25	13.48	0.92	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:2	29.99	3401	3.41	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	3.42	13.48	0.92	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:2	28.63	3402	3.41	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.57	13.48	0.92	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:19:34:2	28.63	3399	3.42	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.55	13.48	0.92	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:34:3	28.63	3400	3.43	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.62	13.48	0.92	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:19:34:3	28.63	3404	3.44	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.85	13.48	0.92	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:19:34:3	28.63	3413	3.44	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.95	13.48	0.92	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:19:34:3	28.63	3413	3.45	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	3.98	13.48	0.92	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:19:34:3	28.63	3422	3.46	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	4.23	13.47	0.92	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:19:34:3	28.63	3427	3.47	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	4.22	13.47	0.92	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:19:34:4	28.63	3441	3.48	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.19	13.45	0.92	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:19:34:4	28.63	3454	3.49	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	4.34	13.46	0.92	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:19:34:4	28.63	3453	3.49	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	4.54	13.45	0.92	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:19:34:4	28.63	3468	3.5	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	4.58	13.46	0.92	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:19:34:4	28.63	3471	3.51	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	4.68	13.44	0.92	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:19:34:4	28.63	3506	3.52	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	4.88	13.45	0.92	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:19:34:4	28.63	3510	3.52	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	5	13.47	0.92	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:19:34:5	28.63	3513	3.53	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.09	13.48	0.92	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:19:34:5	28.63	3516	3.54	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.2	13.47	0.92	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:19:34:5	28.63	3520	3.55	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.37	13.47	0.92	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:19:34:5	27.27	3523	3.56	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.45	13.46	0.92	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:19:34:5	27.27	3523	3.57	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.46	13.44	0.92	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:19:34:5	27.27	3536	3.57	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.6	13.45	0.92	3.5	7.6	ON	28 Pin	OFF	Removed	Disabled
03:19:34:6	27.27	3553	3.58	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.87	13.47	0.92	3.5	7.7	ON	28 Pin	OFF	Removed	Disabled
03:19:34:6	27.27	3557	3.6	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	5.96	13.47	0.92	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:6	27.27	3588	3.6	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	6.05	13.48	0.92	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:6	27.27	3597	3.61	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	6.3	13.48	0.92	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:6	27.27	3598	3.62	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	6.32	13.51	0.92	3.5	7.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:6	27.27	3599	3.63	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	6.37	13.52	0.92	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:19:34:6	27.27	3641	3.65	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	6.59	13.52	0.92	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:7	27.27	3634	3.66	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	6.78	13.54	0.92	3.6	8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:7	27.27	3623	3.67	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	6.87	13.51	0.92	3.6	8.1	ON	28 Pin	OFF	Removed	Disabled
03:19:34:7	27.27	3630	3.68	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	7	13.48	0.92	3.6	8.1	ON	28 Pin	OFF	Removed	Disabled
03:19:34:7	27.27	3646	3.69	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.11	13.48	0.92	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:19:34:7	27.27	3647	3.7	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.25	13.48	0.92	3.5	8.1	ON	28 Pin	OFF	Removed	Disabled
03:19:34:7	27.27	3649	3.71	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.38	13.47	0.92	3.5	8.2	ON	28 Pin	OFF	Removed	Disabled
03:19:34:8	27.27	3650	3.72	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	7.51	13.43	0.91	3.5	8.3	ON	28 Pin	OFF	Removed	Disabled
03:19:34:8	27.27	3660	3.74	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.69	13.4	0.91	3.5	8.4	ON	28 Pin	OFF	Removed	Disabled
03:19:34:8	25.9	3674	3.75	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	7.75	13.38	0.91	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:19:34:8	25.9	3676	3.76	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	7.76	13.35	0.91	3.5	8.5	ON	28 Pin	OFF	Removed	Disabled
03:19:34:8	25.9	3686	3.77	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	7.84	13.35	0.91	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:19:34:8	25.9	3692	3.78	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.13	13.38	0.91	3.5	8.6	ON	28 Pin	OFF	Removed	Disabled
03:19:34:9	25.9	3753	3.79	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.45	13.36	0.91	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:19:34:9	25.9	3740	3.8	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.67	13.31	0.91	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:9	25.9	3757	3.81	13.36	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.88	13.27	0.9	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:9	25.9	3764	3.82	13.35	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.96	13.25	0.9	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:19:34:9	25.9	3762	3.83	13.35	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.91	13.28	0.9	3.5	9	ON	28 Pin	OFF	Removed	Disabled
03:19:34:9	25.9	3775	3.84	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.87	13.27	0.9	3.5	9	ON	28 Pin	OFF	Removed	Disabled
03:19:34:9	25.9	3773	3.85	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	8.93	13.29	0.91	3.5	9.1	ON	28 Pin	OFF	Removed	Disabled
03:19:35:0	25.9	3786	3.86	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.04	13.29	0.91	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:19:35:0	25.9	3807	3.88	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	9.38	13.31	0.91	3.5	9.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:0	25.9	3794	3.89	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.6	13.31	0.91	3.5	9.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:0	24.54	3818	3.91	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	9.83	13.37	0.91	3.5	9.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:0	24.54	3822	3.92	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	10.01	13.42	0.91	3.5	9.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:0	24.54	3824	3.93	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	10.06	13.44	0.92	3.5	9.6	ON	28 Pin	OFF	Removed	Disabled
03:19:35:1	24.54	3830	3.95	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	10.12	13.37	0.91	3.5	9.7	ON	28 Pin	OFF	Removed	Disabled
03:19:35:1	24.54	3830	3.96	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	10.23	13.35	0.91	3.5	9.7	ON	28 Pin	OFF	Removed	Disabled
03:19:35:1	24.54	3849	3.97	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	10.42	13.31	0.91	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:19:35:1	24.54	3869	3.98	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	10.65	13.29	0.91	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:19:35:1	24.54	3878	3.99	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	10.97	13.25	0.9	3.5	10.1	ON	28 Pin	OFF	Removed	Disabled
03:19:35:1	24.54	3880	4	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	11.14	13.21	0.9	3.5	10.2	ON	28 Pin	OFF	Removed	Disabled
03:19:35:1	24.54	3890	4.01	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	11.43	13.17	0.9	3.5	10.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:35:2	24.54	3914	4.02	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	11.55	13.13	0.89	3.5	10.2	ON	28 Pin	OFF	Removed	Disabled
03:19:35:2	24.54	3918	4.03	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	11.78	13.06	0.89	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:2	24.54	3939	4.05	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	11.88	13.06	0.89	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:2	23.18	3957	4.07	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	12.08	13.04	0.89	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:2	23.18	3970	4.08	13.35	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	12.15	13.02	0.89	3.5	10.7	ON	28 Pin	OFF	Removed	Disabled
03:19:35:2	23.18	3970	4.08	13.36	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	12.01	12.98	0.88	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:19:35:3	23.18	3998	4.1	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	12	12.94	0.88	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:19:35:3	23.18	4016	4.1	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	11.98	12.94	0.88	3.4	10.9	ON	28 Pin	OFF	Removed	Disabled
03:19:35:3	24.54	4030	4.11	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	12.08	12.89	0.88	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:19:35:3	24.54	4029	4.13	13.45	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	12.13	12.87	0.88	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:19:35:3	24.54	4036	4.14	13.45	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	12.27	12.84	0.87	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:35:3	24.54	4052	4.15	13.45	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	12.36	12.82	0.87	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:35:4	24.54	4034	4.16	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	12.47	12.79	0.87	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:19:35:4	23.18	4040	4.17	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	12.57	12.75	0.87	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:19:35:4	23.18	4040	4.18	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	12.71	12.74	0.87	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:19:35:4	23.18	4042	4.19	13.34	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	13.06	12.72	0.87	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:4	23.18	4051	4.2	13.31	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	13.32	12.69	0.86	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:4	23.18	4067	4.21	13.3	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	13.42	12.65	0.86	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:35:4	23.18	4070	4.22	13.3	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	13.67	12.63	0.86	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:35:5	23.18	4092	4.24	13.32	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	13.79	12.59	0.86	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:35:5	23.18	4102	4.24	13.34	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	13.87	12.54	0.85	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:19:35:5	23.18	4104	4.25	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	13.94	12.51	0.85	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:5	23.18	4135	4.25	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	14.14	12.48	0.85	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:5	23.18	4151	4.26	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	14.22	12.46	0.85	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:5	23.18	4173	4.27	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	14.13	12.43	0.85	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:6	23.18	4176	4.27	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	14.26	12.41	0.85	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:6	23.18	4212	4.28	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	14.08	12.39	0.84	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:35:6	23.18	4222	4.28	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	14.14	12.39	0.84	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:35:6	23.18	4244	4.29	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	14.13	12.39	0.84	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:35:6	23.18	4251	4.29	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	14.13	12.35	0.84	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:6	23.18	4260	4.3	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	13.95	12.34	0.84	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:6	23.18	4265	4.3	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	13.94	12.35	0.84	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:7	23.18	4270	4.31	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	13.88	12.37	0.84	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:7	23.18	4300	4.31	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	13.81	12.4	0.84	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:7	23.18	4299	4.32	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	13.97	12.46	0.85	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:7	23.18	4300	4.32	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	13.98	12.47	0.85	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:7	23.18	4300	4.32	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	13.81	12.47	0.85	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:7	23.18	4297	4.33	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	13.8	12.48	0.85	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:8	23.18	4296	4.33	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	13.92	12.56	0.86	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:8	23.18	4286	4.34	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	13.89	12.57	0.86	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:8	23.18	4298	4.34	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	13.99	12.59	0.86	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:8	23.18	4308	4.34	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	14	12.62	0.86	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:8	23.18	4310	4.35	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	14.02	12.61	0.86	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:35:8	23.18	4334	4.35	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	14.13	12.61	0.86	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:35:9	23.18	4345	4.35	13.37	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	14.27	12.63	0.86	3.5	11.5	ON	28 Pin	OFF	Removed	Disabled
03:19:35:9	23.18	4368	4.35	13.36	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	14.48	12.68	0.86	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:19:35:9	23.18	4366	4.36	13.36	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	14.7	12.73	0.87	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:19:35:9	23.18	4393	4.36	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	14.76	12.74	0.87	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:19:35:9	23.18	4404	4.36	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	14.66	12.81	0.87	3.4	11.2	ON	28 Pin	OFF	Removed	Disabled
03:19:35:9	23.18	4470	4.36	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	14.46	12.82	0.87	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:19:35:9	23.18	4463	4.37	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	14.5	12.83	0.87	3.5	11.2	ON	28 Pin	OFF	Removed	Disabled
03:19:36:0	23.18	4476	4.37	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	14.36	12.82	0.87	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:0	23.18	4482	4.37	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	14.33	12.85	0.88	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:0	23.18	4509	4.37	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	14.3	12.88	0.88	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:0	23.18	4494	4.37	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	14.22	12.9	0.88	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:0	23.18	4492	4.37	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	14.1	12.86	0.88	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:0	23.18	4498	4.37	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	13.97	12.85	0.88	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:1	23.18	4528	4.38	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	14	12.79	0.87	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:36:1	23.18	4522	4.38	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	14.33	12.68	0.86	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:1	23.18	4522	4.38	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	14.33	12.6	0.86	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:1	23.18	4528	4.38	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	14.31	12.35	0.84	3.6	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:1	23.18	4534	4.38	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	14.34	12.16	0.83	3.6	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:1	23.18	4530	4.38	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	14.29	11.96	0.81	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:1	23.18	4539	4.38	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	14.08	11.75	0.8	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:2	23.18	4585	4.38	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	13.93	11.54	0.79	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:2	23.18	4596	4.39	13.38	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	14.07	11.34	0.77	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:2	24.54	4602	4.38	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	13.67	11.15	0.76	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:2	24.54	4632	4.38	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	13.61	10.95	0.75	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:2	24.54	4632	4.39	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	13.76	10.9	0.74	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:2	24.54	4615	4.39	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	13.45	10.89	0.74	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:3	24.54	4616	4.38	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	13.28	10.87	0.74	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:3	24.54	4604	4.38	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	13.26	10.84	0.74	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:3	24.54	4601	4.38	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	12.98	10.81	0.74	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:3	24.54	4600	4.38	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	12.52	10.78	0.73	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:3	24.54	4603	4.37	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	12.39	10.74	0.73	3.6	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:3	25.9	4601	4.37	13.42	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	12.11	10.71	0.73	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:4	25.9	4632	4.36	13.4	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	11.86	10.65	0.73	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:4	25.9	4660	4.36	13.4	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.6	11.77	10.59	0.72	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:19:36:4	25.9	4662	4.35	13.43	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.69	10.47	0.71	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:4	25.9	4676	4.35	13.41	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.51	10.44	0.71	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:19:36:4	25.9	4685	4.34	13.41	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	11.46	10.38	0.71	3.5	12.3	ON	28 Pin	OFF	Removed	Disabled
03:19:36:4	25.9	4690	4.34	13.42	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	11.34	10.33	0.7	3.5	12.3	ON	28 Pin	OFF	Removed	Disabled
03:19:36:4	25.9	4708	4.33	13.41	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	11.13	10.28	0.7	3.5	12.3	ON	28 Pin	OFF	Removed	Disabled
03:19:36:5	25.9	4719	4.33	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	11.12	10.27	0.7	3.5	12.3	ON	28 Pin	OFF	Removed	Disabled
03:19:36:5	25.9	4723	4.32	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	10.9	10.24	0.7	3.5	12.2	ON	28 Pin	OFF	Removed	Disabled
03:19:36:5	25.9	4720	4.32	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	10.59	10.23	0.7	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:5	25.9	4726	4.31	13.4	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.61	10.25	0.7	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:5	25.9	4729	4.3	13.41	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.34	10.24	0.7	3.5	11.8	ON	28 Pin	OFF	Removed	Disabled
03:19:36:5	25.9	4730	4.29	13.41	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	10.12	10.26	0.7	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:19:36:6	27.27	4760	4.28	13.39	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	9.89	10.25	0.7	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:19:36:6	27.27	4768	4.28	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	9.7	10.29	0.7	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:6	27.27	4768	4.27	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	9.54	10.3	0.7	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:19:36:6	27.27	4800	4.26	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	9.21	10.32	0.7	3.5	10.7	ON	28 Pin	OFF	Removed	Disabled
03:19:36:6	28.63	4824	4.25	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	9.09	10.32	0.7	3.5	10.6	ON	28 Pin	OFF	Removed	Disabled
03:19:36:6	28.63	4825	4.25	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	8.95	10.32	0.7	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:19:36:6	28.63	4840	4.24	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	8.77	10.31	0.7	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:19:36:7	28.63	4854	4.23	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	8.62	10.33	0.7	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled
03:19:36:7	28.63	4853	4.22	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	8.6	10.35	0.7	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled
03:19:36:7	28.63	4855	4.21	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	8.36	10.38	0.71	3.5	10.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:7	28.63	4858	4.2	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	8.2	10.41	0.71	3.5	10.1	ON	28 Pin	OFF	Removed	Disabled
03:19:36:7	28.63	4858	4.19	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	7.98	10.44	0.71	3.5	10	ON	28 Pin	OFF	Removed	Disabled
03:19:36:7	28.63	4845	4.18	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	7.6	10.47	0.71	3.6	9.9	ON	28 Pin	OFF	Removed	Disabled
03:19:36:8	28.63	4846	4.16	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	7.16	10.49	0.71	3.5	9.7	ON	28 Pin	OFF	Removed	Disabled
03:19:36:8	28.63	4833	4.13	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	6.48	10.53	0.72	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:19:36:8	28.63	4800	4.08	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	5.31	10.56	0.72	3.5	7.9	ON	28 Pin	OFF	Removed	Disabled
03:19:36:8	28.63	4779	3.98	13.4	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.6	3.68	10.58	0.72	3.6	6.8	ON	28 Pin	OFF	Removed	Disabled
03:19:36:8	34.08	4762	3.89	13.41	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	0.87	10.54	0.72	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:36:8	34.08	4594	3.77	13.43	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.13	10.51	0.72	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:36:9	34.08	4594	3.63	13.44	104	196	Off Idle	41.4	0	2	132	944 Turbo	0.9	Rich	1	14.6	-2.89	10.47	0.71	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:36:9	34.08	4549	3.44	13.42	104	196	Full Load	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	-4.35	10.43	0.71	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:36:9	34.08	4542	3.15	13.45	104	196	Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-5.89	10.39	0.71	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:36:9	28.63	4451	2.95	13.46	104	196	Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-6.54	10.36	0.71	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:36:9	23.18	4462	2.76	13.46	104	196	Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.13	10.35	0.71	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:36:9	20.45	4515	2.56	13.45	104	196	Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.63	10.36	0.71	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:36:9	20.45	4485	2.37	13.45	104	196	Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.05	10.4	0.71	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:0	20.45	4464	2.18	13.45	104	196	Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.41	10.47	0.71	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:37:0	20.45	4440	2	13.44	104	196	Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.8	10.59	0.72	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:0	20.45	4386	1.81	13.43	104	196	Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.08	10.73	0.73	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:0	20.45	4380	1.54	13.43	104	196	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.33	10.87	0.74	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:0	20.45	4318	1.38	13.43	104	196	Idle	41.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.45	11.07	0.75	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:0	20.45	4297	1.24	13.42	104	196	Idle	40.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.51	11.21	0.76	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:1	20.45	4256	1.12	13.42	104	196	Idle	40.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.53	11.29	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:1	20.45	4248	1.01	13.43	104	196	Idle	39.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.55	11.39	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:1	20.45	4206	0.92	13.46	104	196	Idle	39.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.57	11.51	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:1	20.45	4171	0.84	13.48	104	196	Idle	37	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.63	11.68	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:1	20.45	4146	0.79	13.49	104	196	Idle	37	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.67	11.97	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:1	20.45	4105	0.78	13.49	104	196	Idle	35.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.7	12.33	0.84	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:1	20.45	4078	0.81	13.49	104	196	Idle	34.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.69	12.6	0.86	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:2	20.45	3975	0.88	13.49	104	196	Idle	33.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	13.06	0.89	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:2	20.45	4000	0.96	13.49	104	196	Idle	30.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.65	13.71	0.93	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:2	20.45	3988	1.04	13.49	104	196	Idle	30.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.59	14.53	0.99	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:2	20.45	3922	1.16	13.49	104	196	Idle	27.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.5	15.38	1.05	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:2	20.45	3930	1.23	13.49	104	196	Idle	26.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	16.19	1.1	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:2	20.45	3902	1.27	13.48	104	196	Idle	24.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.37	17.32	1.18	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:3	20.45	3832	1.34	13.48	104	196	Idle	23.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	17.99	1.23	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:3	20.45	3832	1.4	13.47	104	196	Idle	22.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.31	18.62	1.27	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:3	20.45	3802	1.47	13.44	104	195	Idle	21.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	19.23	1.31	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:3	20.45	3752	1.54	13.44	104	195	Idle	20.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	19.75	1.35	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:3	20.45	3758	1.61	13.44	104	195	Idle	20.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.39	20.06	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:3	20.45	3730	1.66	13.44	104	196	Idle	20.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	20.18	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:4	20.45	3634	1.69	13.47	104	196	Off Idle	20.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.39	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:4	20.45	3656	1.71	13.48	104	196	Off Idle	20	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.32	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:4	20.45	3641	1.74	13.46	104	196	Off Idle	20	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.22	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:4	10.9	3515	1.77	13.46	104	196	Off Idle	19.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:4	13.63	3582	1.79	13.46	104	196	Off Idle	19.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:4	16.36	3572	1.83	13.45	104	196	Off Idle	21.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.89	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:37:4	19.09	3491	1.87	13.43	104	196	Off Idle	23.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.69	20.23	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:37:5	21.81	3441	1.89	13.44	104	196	Off Idle	25.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.56	20.22	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:37:5	24.54	3422	1.91	13.44	104	196	Off Idle	26.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.48	20.22	1.38	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:37:5	24.54	3311	1.92	13.42	104	196	Off Idle	26.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.31	20.23	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:37:5	27.27	3246	1.94	13.41	104	196	Off Idle	29.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.25	20.24	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:37:5	29.99	3215	1.96	13.4	104	196	Off Idle	31.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.17	20.25	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:19:37:6	32.72	3205	1.99	13.43	104	196	Off Idle	32.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.07	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:37:6	35.45	3178	2.01	13.43	104	196	Off Idle	34	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.98	20.24	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:37:6	36.81	3150	2.02	13.42	104	196	Off Idle	35.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.87	20.23	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:6	36.81	3151	2.05	13.44	104	196	Off Idle	36.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.64	20.23	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:37:6	36.81	3163	2.08	13.44	104	196	Off Idle	38.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.45	20.24	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:6	36.81	3184	2.11	13.43	104	196	Off Idle	39.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.19	20.24	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:37:6	36.81	3196	2.15	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.96	20.24	1.38	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:37:6	36.81	3200	2.19	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.63	20.24	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:37:7	36.81	3246	2.22	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.33	20.23	1.38	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:7	36.81	3295	2.26	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.02	20.2	1.38	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:37:7	36.81	3294	2.3	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.71	20.2	1.38	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:37:7	35.45	3328	2.35	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.42	20.19	1.38	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:7	35.45	3358	2.38	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.21	20.09	1.37	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:37:7	35.45	3393	2.41	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.12	19.83	1.35	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:37:8	35.45	3419	2.44	13.4	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.95	19.64	1.34	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:37:8	35.45	3386	2.47	13.4	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.94	19.44	1.32	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:37:8	35.45	3334	2.51	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.93	19.2	1.31	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:37:8	35.45	3318	2.54	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.81	18.93	1.29	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:8	35.45	3246	2.56	13.41	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.74	18.64	1.27	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:8	35.45	3201	2.58	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.69	18.28	1.25	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:9	35.45	3198	2.61	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Rich	1	14.6	-4.56	17.88	1.22	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:9	35.45	3196	2.64	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-4.5	17.53	1.19	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:37:9	35.45	3224	2.68	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.41	17.22	1.17	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:9	35.45	3206	2.69	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.38	16.92	1.15	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:9	35.45	3260	2.7	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.4	16.61	1.13	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:37:9	35.45	3298	2.71	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.41	16.23	1.11	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:37:9	35.45	3302	2.72	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.41	15.98	1.09	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:0	35.45	3346	2.72	13.45	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.4	15.73	1.07	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:0	35.45	3323	2.73	13.42	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.34	15.55	1.06	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:0	35.45	3320	2.73	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.34	15.37	1.05	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:0	35.45	3294	2.74	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.28	15.21	1.04	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:0	35.45	3274	2.74	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.19	15.07	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:0	35.45	3270	2.74	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.2	14.98	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:38:1	35.45	3246	2.74	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.08	14.89	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:38:1	35.45	3245	2.75	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.09	14.76	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:38:1	35.45	3254	2.75	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.09	14.7	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:38:1	35.45	3246	2.75	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.06	14.67	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:38:1	35.45	3274	2.75	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.04	14.67	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:38:1	35.45	3274	2.75	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.04	14.63	1	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:38:1	35.45	3291	2.76	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.03	14.62	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:2	35.45	3312	2.76	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.04	14.62	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:2	35.45	3302	2.76	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.99	14.61	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:2	35.45	3302	2.76	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.06	14.6	0.99	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:2	35.45	3287	2.77	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.04	14.56	0.99	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:2	35.45	3276	2.77	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.04	14.52	0.99	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:2	35.45	3271	2.77	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.11	14.46	0.99	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:3	35.45	3272	2.77	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.09	14.42	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:3	35.45	3277	2.77	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.03	14.38	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:3	35.45	3284	2.77	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.06	14.36	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:3	35.45	3289	2.77	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.99	14.32	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:3	35.45	3292	2.77	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.98	14.31	0.97	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:3	35.45	3297	2.77	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.04	14.3	0.97	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:4	35.45	3300	2.77	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.04	14.3	0.97	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:4	35.45	3300	2.77	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.07	14.29	0.97	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:4	35.45	3304	2.77	13.44	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.02	14.32	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:4	35.45	3304	2.77	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.01	14.35	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:4	35.45	3300	2.77	13.4	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4	14.36	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:4	35.45	3297	2.77	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.04	14.37	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:4	35.45	3299	2.78	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.02	14.38	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:5	35.45	3295	2.78	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.99	14.38	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:5	35.45	3296	2.78	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.04	14.39	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:5	35.45	3297	2.78	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.06	14.38	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:5	35.45	3296	2.78	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.05	14.4	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:5	35.45	3293	2.78	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.05	14.38	0.98	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:5	35.45	3303	2.78	13.43	104	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.07	14.38	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:6	35.45	3304	2.78	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.99	14.39	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:6	35.45	3308	2.78	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.98	14.4	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:6	35.45	3315	2.78	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.99	14.41	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:6	35.45	3316	2.78	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.93	14.43	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:6	35.45	3315	2.78	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4	14.44	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:6	35.45	3306	2.78	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.96	14.46	0.98	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:6	35.45	3301	2.78	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.92	14.47	0.99	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:7	35.45	3301	2.78	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4	14.5	0.99	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:7	35.45	3300	2.78	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.95	14.53	0.99	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:7	35.45	3302	2.78	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.95	14.55	0.99	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:7	35.45	3302	2.78	13.46	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.03	14.57	0.99	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:7	35.45	3310	2.78	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.99	14.61	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:7	35.45	3318	2.78	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.01	14.63	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:38:8	35.45	3318	2.78	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.01	14.64	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:38:8	35.45	3316	2.78	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.97	14.67	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:38:8	35.45	3320	2.79	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4	14.69	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:38:8	35.45	3318	2.79	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.94	14.72	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:38:8	35.45	3319	2.79	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.9	14.75	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:38:8	35.45	3317	2.79	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.94	14.77	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:38:9	35.45	3320	2.79	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.83	14.79	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:38:9	35.45	3320	2.79	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.86	14.81	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:38:9	35.45	3320	2.79	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.87	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:38:9	35.45	3324	2.79	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-3.83	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:9	35.45	3317	2.79	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.85	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:9	35.45	3321	2.79	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.84	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:38:9	35.45	3332	2.8	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.82	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:39:0	35.45	3340	2.8	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.77	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:0	35.45	3340	2.8	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.71	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:0	35.45	3339	2.81	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.65	14.88	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:0	35.45	3339	2.81	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.61	14.92	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:19:39:0	35.45	3339	2.81	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.51	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:39:0	35.45	3339	2.82	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.55	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:39:1	35.45	3332	2.82	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.53	15.05	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:39:1	35.45	3332	2.82	13.46	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-3.49	15.09	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:1	35.45	3332	2.83	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.47	15.11	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:1	35.45	3334	2.83	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.52	15.1	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:1	35.45	3335	2.84	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.43	15.04	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:1	35.45	3339	2.84	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.42	14.99	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:1	35.45	3338	2.84	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.41	14.94	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:2	35.45	3336	2.85	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.29	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:2	35.45	3339	2.85	13.4	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.28	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:2	35.45	3340	2.86	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.28	14.76	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:2	35.45	3339	2.86	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.21	14.71	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:19:39:2	35.45	3339	2.87	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.1	14.69	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:19:39:2	35.45	3343	2.87	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-3.11	14.7	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:19:39:3	35.45	3346	2.87	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-3.05	14.73	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:19:39:3	35.45	3343	2.88	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.93	14.76	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:19:39:3	35.45	3346	2.88	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-2.84	14.77	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:19:39:3	35.45	3354	2.89	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.85	14.79	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:3	35.45	3366	2.89	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.79	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:3	34.08	3354	2.9	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-2.68	14.81	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:4	34.08	3368	2.9	13.43	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-2.62	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:4	34.08	3364	2.91	13.44	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-2.59	14.87	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:19:39:4	34.08	3362	2.92	13.43	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.39	14.93	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:19:39:4	34.08	3360	2.92	13.42	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-2.43	14.99	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:4	34.08	3344	2.93	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-2.48	14.99	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:4	34.08	3361	2.93	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.36	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:4	34.08	3361	2.94	13.43	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.34	14.98	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:5	34.08	3367	2.94	13.43	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.37	14.95	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:5	34.08	3389	2.95	13.43	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.26	14.94	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:5	34.08	3389	2.96	13.43	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.23	14.9	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:5	34.08	3372	2.96	13.43	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.24	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:5	34.08	3372	2.97	13.44	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.25	14.8	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:5	34.08	3373	2.97	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.19	14.71	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:6	34.08	3370	2.97	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.16	14.66	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:6	34.08	3362	2.98	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.01	14.65	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:6	34.08	3356	2.98	13.44	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.98	14.63	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:6	34.08	3364	2.99	13.44	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.97	14.63	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:6	34.08	3375	2.99	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.93	14.64	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:6	34.08	3380	2.99	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.97	14.64	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:6	34.08	3390	2.99	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.93	14.66	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:7	34.08	3396	2.99	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.95	14.68	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:7	34.08	3397	3	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.97	14.69	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:39:7	34.08	3396	3	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.98	14.72	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:7	34.08	3396	3	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.06	14.74	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:39:7	34.08	3381	3	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.02	14.75	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:7	34.08	3375	3.01	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.98	14.77	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:8	34.08	3376	3.01	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.01	14.78	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:8	34.08	3384	3.01	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.92	14.81	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:8	34.08	3396	3.01	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.89	14.82	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:8	34.08	3396	3.02	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.96	14.83	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:8	34.08	3410	3.02	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.87	14.83	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:8	34.08	3409	3.02	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.82	14.83	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:9	34.08	3404	3.02	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.89	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:9	34.08	3404	3.02	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.86	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:9	34.08	3401	3.02	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.8	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:9	34.08	3406	3.03	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.88	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:9	34.08	3409	3.03	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.84	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:9	34.08	3415	3.03	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.79	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:39:9	34.08	3417	3.03	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.86	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:40:0	34.08	3411	3.03	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.79	14.86	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:40:0	34.08	3411	3.03	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.76	14.86	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:40:0	34.08	3412	3.04	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-1.78	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:40:0	34.08	3413	3.04	13.47	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-1.7	14.88	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:40:0	34.08	3414	3.04	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-1.63	14.89	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:40:0	34.08	3418	3.04	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-1.65	14.89	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:40:1	34.08	3429	3.05	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-1.52	14.88	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:40:1	34.08	3430	3.05	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.44	14.88	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:40:1	34.08	3432	3.06	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.39	14.91	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:1	34.08	3442	3.06	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.27	14.92	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:1	34.08	3456	3.07	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-1.15	14.95	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:1	34.08	3441	3.07	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-1.15	14.98	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:1	34.08	3440	3.08	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-1.12	15.01	1.02	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:2	34.08	3439	3.09	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-0.97	15.04	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:2	34.08	3436	3.09	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-1	15.11	1.03	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:2	34.08	3439	3.1	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-0.88	15.13	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:2	34.08	3449	3.11	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-0.81	15.14	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:2	34.08	3454	3.11	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-0.83	15.11	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:2	34.08	3451	3.11	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-0.76	15.06	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:3	32.72	3453	3.12	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-0.68	15	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:3	32.72	3456	3.13	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.72	14.94	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:3	32.72	3455	3.13	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.76	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:3	32.72	3456	3.14	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.61	14.81	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:3	32.72	3456	3.15	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.67	14.72	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:3	34.08	3454	3.15	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.6	14.69	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:4	34.08	3454	3.16	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.46	14.67	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:4	34.08	3456	3.16	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.4	14.67	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:4	34.08	3475	3.16	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.4	14.67	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:4	32.72	3447	3.17	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.3	14.69	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:4	32.72	3460	3.17	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.42	14.7	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:4	32.72	3470	3.17	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.4	14.72	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:4	32.72	3468	3.17	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.32	14.74	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:5	32.72	3462	3.18	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-0.43	14.76	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:5	32.72	3464	3.18	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-0.32	14.76	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:5	32.72	3464	3.18	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-0.29	14.77	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:5	32.72	3462	3.18	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-0.34	14.77	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:5	32.72	3470	3.18	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-0.3	14.78	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:40:5	32.72	3475	3.18	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-0.29	14.78	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:40:6	34.08	3482	3.19	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-0.28	14.81	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:40:6	34.08	3488	3.19	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-0.27	14.85	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:40:6	34.08	3490	3.19	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-0.29	14.89	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:40:6	34.08	3504	3.19	13.39	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-0.25	14.93	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:40:6	34.08	3517	3.19	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-0.39	14.99	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:40:6	34.08	3511	3.19	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-0.39	15.02	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:6	34.08	3510	3.19	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-0.26	15.07	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:7	34.08	3502	3.19	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-0.23	15.11	1.03	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:7	34.08	3497	3.19	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-0.27	15.15	1.03	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:7	32.72	3495	3.2	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-0.09	15.14	1.03	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:7	32.72	3485	3.2	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-0.16	15.12	1.03	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:7	32.72	3489	3.2	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-0.21	15.07	1.03	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:7	32.72	3494	3.2	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-0.12	15.03	1.02	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:40:8	32.72	3508	3.2	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-0.11	14.96	1.02	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:40:8	32.72	3509	3.2	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-0.1	14.91	1.02	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:40:8	32.72	3524	3.21	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	0.04	14.87	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:40:8	32.72	3524	3.21	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	0.02	14.86	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:40:8	32.72	3536	3.21	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	0.02	14.87	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:8	34.08	3533	3.21	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	0.04	14.9	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:9	34.08	3533	3.21	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	0.14	14.92	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:19:40:9	34.08	3540	3.22	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	0.09	14.97	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:40:9	34.08	3545	3.22	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	0.08	15.01	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:40:9	34.08	3546	3.22	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	0.09	15.07	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:40:9	34.08	3560	3.22	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	0.19	15.14	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:40:9	34.08	3537	3.23	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	0.16	15.15	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:40:9	34.08	3529	3.23	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	0.18	15.13	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:0	34.08	3530	3.23	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	0.23	15.08	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:0	34.08	3508	3.23	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.33	15.06	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:0	34.08	3518	3.23	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.24	15.01	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:0	34.08	3523	3.24	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.23	14.95	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:0	34.08	3538	3.24	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	0.34	14.92	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:0	32.72	3528	3.24	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	0.39	14.84	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:19:41:1	32.72	3558	3.24	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	0.3	14.8	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:19:41:1	32.72	3558	3.24	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	0.31	14.78	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:19:41:1	32.72	3554	3.24	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	0.35	14.81	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:19:41:1	32.72	3558	3.25	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	0.27	14.85	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:1	32.72	3559	3.25	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	0.36	14.88	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:1	32.72	3558	3.25	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	0.48	14.91	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:1	32.72	3552	3.25	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	0.45	14.94	1.02	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:2	32.72	3564	3.25	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	0.44	15.01	1.02	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:2	32.72	3563	3.25	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	0.49	15.06	1.03	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:2	32.72	3568	3.25	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	0.52	15.1	1.03	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:2	32.72	3576	3.26	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	0.43	15.09	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:2	32.72	3576	3.26	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	0.5	15.06	1.03	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:2	32.72	3580	3.26	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	0.54	14.97	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:3	32.72	3574	3.26	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.46	14.91	1.02	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:3	32.72	3571	3.26	13.4	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	0.54	14.87	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:3	32.72	3571	3.26	13.4	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.54	14.84	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:3	32.72	3577	3.26	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.44	14.76	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:3	32.72	3581	3.26	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	0.53	14.72	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:3	32.72	3595	3.27	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	0.62	14.72	1	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:4	32.72	3581	3.27	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	0.52	14.72	1	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:4	32.72	3583	3.27	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	0.52	14.74	1	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:4	32.72	3593	3.27	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	0.55	14.77	1.01	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:4	32.72	3596	3.27	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	0.59	14.79	1.01	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:4	32.72	3606	3.27	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	0.49	14.82	1.01	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:4	32.72	3612	3.27	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	0.52	14.85	1.01	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:4	32.72	3617	3.27	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	0.57	14.88	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:5	32.72	3617	3.27	13.4	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	0.47	14.92	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:5	32.72	3598	3.26	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	0.32	15	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:5	32.72	3612	3.26	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	0.27	15.02	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:41:8	32.72	3612	3.26	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	0.21	15.01	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:8	32.72	3612	3.26	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	0.17	15	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:41:8	34.08	3603	3.25	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	0.17	15	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:41:6	34.08	3606	3.25	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	0.13	14.98	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:19:41:6	34.08	3618	3.24	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Lean	1	14.6	-0.07	14.94	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:19:41:6	34.08	3634	3.24	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.25	14.92	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:19:41:6	34.08	3634	3.23	13.41	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.42	14.88	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:19:41:6	34.08	3616	3.22	13.46	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-0.63	14.81	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:41:6	34.08	3608	3.21	13.46	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-0.78	14.72	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:19:41:6	34.08	3605	3.2	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-0.83	14.7	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:7	34.08	3602	3.19	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.02	14.71	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:41:7	34.08	3597	3.18	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.14	14.73	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:7	34.08	3598	3.16	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-1.28	14.74	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:7	34.08	3597	3.15	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-1.47	14.78	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:7	34.08	3616	3.14	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.68	14.77	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:41:7	34.08	3621	3.12	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-1.81	14.76	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:19:41:8	34.08	3625	3.11	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-1.96	14.8	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:41:8	34.08	3632	3.09	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-2.12	14.82	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:19:41:8	34.08	3635	3.07	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.24	14.87	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:8	34.08	3636	3.05	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.45	14.94	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:19:41:8	34.08	3640	3.04	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-2.54	14.98	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:19:41:8	34.08	3636	3.02	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.68	15.02	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:41:9	35.45	3632	3	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.81	15.07	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:19:41:9	35.45	3628	2.98	13.42	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.01	15.1	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:19:41:9	35.45	3618	2.96	13.43	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.3	15.14	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:19:41:9	35.45	3617	2.93	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.71	15.24	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:41:9	35.45	3617	2.91	13.46	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.94	15.22	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:41:9	35.45	3614	2.89	13.46	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.14	15.15	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:41:9	35.45	3612	2.88	13.46	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.35	15.07	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:42:0	35.45	3614	2.85	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.63	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:19:42:0	35.45	3615	2.82	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.88	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:42:0	35.45	3617	2.79	13.44	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.13	14.69	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:42:0	35.45	3613	2.77	13.44	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.37	14.56	0.99	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:0	35.45	3613	2.74	13.44	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.62	14.43	0.98	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:0	36.81	3620	2.71	13.48	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.77	14.27	0.97	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:42:1	36.81	3605	2.67	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.9	14.16	0.96	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:42:1	36.81	3602	2.64	13.42	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.16	14.1	0.96	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:42:1	36.81	3599	2.61	13.42	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.36	14.08	0.96	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:42:1	36.81	3587	2.58	13.43	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.51	14.12	0.96	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:42:1	36.81	3600	2.55	13.41	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.67	14.16	0.96	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:42:1	36.81	3600	2.53	13.42	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.83	14.25	0.97	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:42:1	36.81	3608	2.5	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.94	14.34	0.98	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:42:2	36.81	3620	2.47	13.45	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.01	14.4	0.98	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:42:2	36.81	3622	2.45	13.46	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.15	14.47	0.99	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:42:2	36.81	3628	2.43	13.47	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.16	Rich	1	14.6	-7.22	14.56	0.99	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:42:2	36.81	3628	2.4	13.49	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.37	14.74	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:42:2	36.81	3652	2.38	13.49	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.48	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:42:2	38.18	3638	2.36	13.49	103	196	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:42:3	38.18	3623	2.34	13.48	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.8	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:42:3	38.18	3586	2.31	13.45	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8	15.14	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:42:3	38.18	3586	2.27	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.3	15.24	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:42:3	38.18	3605	2.23	13.44	103	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.55	15.33	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:42:3	38.18	3584	2.2	13.43	103	196	Full Load	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.83	15.4	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:3	38.18	3576	2.16	13.44	103	196	Full Load	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.09	15.43	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:42:4	38.18	3571	2.12	13.45	103	196	Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.28	15.44	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:42:4	38.18	3566	2.08	13.46	103	196	Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.47	15.41	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:42:4	38.18	3536	2.05	13.46	103	196	Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.62	15.38	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:42:4	38.18	3536	2	13.46	103	196	Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.73	15.3	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:42:4	38.18	3528	1.97	13.46	103	196	Idle	39.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.81	15.26	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:42:4	38.18	3447	1.94	13.46	103	196	Idle	37.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.78	15.27	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:42:4	32.72	3447	1.92	13.44	103	196	Idle	37.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.78	15.26	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:42:5	27.27	3442	1.88	13.42	103	196	Idle	33.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.77	15.23	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:42:5	21.81	3480	1.86	13.45	103	196	Idle	30	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.77	15.2	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:42:5	20.45	3500	1.85	13.44	103	196	Idle	30	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.7	15.13	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:5	20.45	3538	1.82	13.44	103	196	Idle	26.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.68	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:5	20.45	3582	1.81	13.44	103	196	Idle	26.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.61	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:5	20.45	3604	1.79	13.46	103	196	Idle	26.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.57	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:6	20.45	3608	1.78	13.45	103	196	Idle	26.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.59	14.77	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:6	20.45	3613	1.76	13.44	103	196	Idle	26.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.54	14.68	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:6	20.45	3604	1.76	13.42	103	196	Idle	26.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.57	14.6	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:6	20.45	3604	1.76	13.41	103	196	Idle	26.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.66	14.55	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:6	20.45	3572	1.76	13.43	103	196	Idle	26.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.73	14.54	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:6	20.45	3567	1.76	13.44	103	196	Idle	28.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.81	14.55	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:6	20.45	3563	1.77	13.45	103	196	Idle	30.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.87	14.57	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:7	20.45	3541	1.77	13.46	103	196	Idle	34.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.88	14.67	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:7	20.45	3538	1.77	13.46	103	196	Idle	36.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.9	14.72	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:7	20.45	3520	1.77	13.46	103	196	Idle	38.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.91	14.89	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:7	20.45	3485	1.77	13.46	103	196	Idle	38.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.9	14.95	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:7	20.45	3500	1.77	13.43	103	196	Idle	41.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.93	15.13	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:7	20.45	3515	1.77	13.45	103	196	Idle	41	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.97	15.27	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:8	20.45	3532	1.76	13.45	103	196	Idle	40.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.95	15.45	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:8	20.45	3547	1.76	13.44	103	196	Idle	40.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.95	15.73	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:8	20.45	3547	1.75	13.45	103	196	Idle	40.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.94	16.19	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:8	20.45	3555	1.74	13.45	103	196	Idle	40.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.98	16.96	1.16	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:8	20.45	3560	1.73	13.45	103	196	Idle	40.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.96	17.21	1.17	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:8	20.45	3612	1.72	13.45	103	196	Idle	40.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.95	17.92	1.22	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:9	20.45	3612	1.72	13.45	103	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	18.38	1.25	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:9	20.45	3549	1.71	13.45	103	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	18.83	1.28	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:9	20.45	3540	1.71	13.47	103	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	19.25	1.31	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:9	20.45	3529	1.71	13.48	103	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	19.65	1.34	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:9	20.45	3526	1.71	13.47	103	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	19.83	1.35	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:9	20.45	3485	1.71	13.46	103	196	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.1	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:42:9	20.45	3508	1.7	13.47	103	196	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:0	20.45	3508	1.7	13.47	103	196	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:0	20.45	3500	1.7	13.46	103	196	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:0	20.45	3496	1.7	13.45	103	196	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:0	20.45	3499	1.7	13.47	103	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:0	20.45	3502	1.7	13.46	103	196	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:0	20.45	3504	1.7	13.45	103	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:1	20.45	3506	1.7	13.43	103	196	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:1	20.45	3522	1.7	13.45	103	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:1	20.45	3522	1.7	13.45	103	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:1	20.45	3513	1.7	13.45	103	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:1	20.45	3516	1.7	13.44	103	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:1	20.45	3514	1.7	13.45	103	197	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:1	20.45	3513	1.7	13.43	103	197	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:2	20.45	3511	1.7	13.42	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:2	20.45	3507	1.7	13.45	103	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:2	20.45	3505	1.7	13.45	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:2	20.45	3495	1.7	13.44	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:2	20.45	3491	1.7	13.46	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:2	20.45	3488	1.7	13.46	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:3	20.45	3480	1.7	13.45	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:3	20.45	3453	1.7	13.44	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:3	20.45	3474	1.7	13.46	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:3	20.45	3472	1.7	13.48	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:43:3	20.45	3480	1.7	13.46	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:3	20.45	3468	1.7	13.44	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:4	20.45	3468	1.7	13.45	102	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:4	20.45	3468	1.7	13.45	102	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:4	20.45	3462	1.7	13.44	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:4	20.45	3465	1.7	13.45	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:4	20.45	3452	1.7	13.46	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:4	20.45	3464	1.7	13.46	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:4	20.45	3462	1.7	13.45	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:5	20.45	3462	1.7	13.45	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:5	20.45	3460	1.7	13.46	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.17	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:5	20.45	3459	1.7	13.46	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.17	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:5	20.45	3458	1.7	13.45	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:5	20.45	3458	1.7	13.43	103	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:5	20.45	3457	1.7	13.44	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:6	20.45	3458	1.7	13.44	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:6	20.45	3458	1.7	13.43	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:6	20.45	3454	1.7	13.45	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:6	20.45	3450	1.7	13.46	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:6	20.45	3450	1.7	13.45	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:6	20.45	3446	1.7	13.44	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:6	20.45	3441	1.7	13.44	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:7	20.45	3439	1.7	13.45	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:7	20.45	3435	1.7	13.45	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:7	20.45	3433	1.7	13.47	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:7	20.45	3430	1.7	13.46	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:7	20.45	3430	1.7	13.45	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:7	20.45	3430	1.7	13.46	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:8	20.45	3431	1.7	13.44	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:8	20.45	3433	1.7	13.43	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:8	20.45	3430	1.7	13.46	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:8	20.45	3433	1.7	13.45	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:8	20.45	3433	1.7	13.44	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:8	20.45	3432	1.7	13.44	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:9	20.45	3426	1.7	13.46	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:9	20.45	3425	1.7	13.46	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:9	20.45	3426	1.7	13.46	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:9	20.45	3418	1.7	13.45	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:9	20.45	3416	1.7	13.44	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:9	20.45	3410	1.7	13.46	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:43:9	20.45	3410	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:0	20.45	3377	1.7	13.43	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:0	20.45	3401	1.7	13.45	103	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:0	20.45	3402	1.7	13.45	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:0	20.45	3399	1.7	13.45	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:0	20.45	3398	1.7	13.45	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:0	20.45	3398	1.7	13.46	103	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:1	20.45	3404	1.7	13.47	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:1	20.45	3404	1.7	13.46	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:1	20.45	3403	1.7	13.46	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:1	20.45	3404	1.7	13.47	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:1	20.45	3403	1.7	13.45	103	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:1	20.45	3404	1.7	13.45	103	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:1	20.45	3402	1.7	13.44	103	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:2	20.45	3398	1.7	13.43	103	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:2	20.45	3398	1.7	13.43	103	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:2	20.45	3388	1.7	13.44	103	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:2	20.45	3381	1.7	13.42	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:44:2	20.45	3376	1.7	13.44	103	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:2	20.45	3374	1.7	13.45	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:3	20.45	3367	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:3	20.45	3367	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:3	20.45	3365	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:3	20.45	3364	1.7	13.47	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:3	20.45	3366	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:3	20.45	3365	1.7	13.47	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:4	20.45	3370	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:4	20.45	3370	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:4	20.45	3369	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:4	20.45	3369	1.7	13.45	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:4	20.45	3367	1.7	13.44	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:4	20.45	3363	1.7	13.45	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:4	20.45	3361	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:5	20.45	3360	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:5	20.45	3355	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:5	20.45	3351	1.7	13.45	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:5	20.45	3350	1.7	13.43	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:5	20.45	3347	1.7	13.44	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:5	20.45	3345	1.7	13.45	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:6	20.45	3345	1.7	13.44	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:6	20.45	3342	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:6	20.45	3341	1.7	13.46	103	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:6	20.45	3329	1.7	13.45	103	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:6	20.45	3340	1.7	13.44	103	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:6	20.45	3311	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:6	20.45	3326	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:7	20.45	3341	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:7	20.45	3364	1.7	13.47	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:7	20.45	3350	1.7	13.47	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:7	20.45	3334	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:7	20.45	3332	1.7	13.47	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:7	20.45	3331	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:8	20.45	3331	1.7	13.45	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:8	20.45	3330	1.7	13.45	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:8	20.45	3328	1.7	13.46	102	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:8	20.45	3326	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:8	20.45	3324	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:8	20.45	3325	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:9	20.45	3325	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:9	20.45	3325	1.7	13.47	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:9	20.45	3318	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:9	20.45	3319	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:9	20.45	3317	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:9	20.45	3314	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:44:9	20.45	3309	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:0	20.45	3310	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:0	20.45	3306	1.7	13.45	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:0	20.45	3305	1.7	13.45	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:0	20.45	3299	1.7	13.47	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:0	20.45	3299	1.7	13.46	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:0	20.45	3300	1.7	13.44	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:1	20.45	3298	1.7	13.46	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:1	20.45	3298	1.7	13.45	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:1	20.45	3297	1.7	13.45	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:1	20.45	3296	1.7	13.45	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:1	20.45	3296	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:45:1	20.45	3296	1.7	13.44	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:1	20.45	3294	1.7	13.45	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:2	20.45	3293	1.7	13.47	102	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:2	20.45	3292	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:2	20.45	3293	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:2	20.45	3293	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:2	20.45	3291	1.7	13.47	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:2	20.45	3287	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:3	20.45	3286	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:3	20.45	3257	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:3	20.45	3282	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:3	20.45	3305	1.7	13.44	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:3	20.45	3292	1.7	13.44	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:3	20.45	3275	1.7	13.45	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:4	20.45	3248	1.7	13.44	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:4	20.45	3273	1.7	13.46	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:4	20.45	3272	1.7	13.45	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:4	20.45	3271	1.7	13.45	103	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:4	20.45	3284	1.7	13.45	103	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:4	20.45	3284	1.7	13.45	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:4	20.45	3272	1.7	13.46	102	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:5	20.45	3258	1.7	13.46	102	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:5	20.45	3269	1.7	13.46	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:5	20.45	3268	1.7	13.46	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:5	20.45	3268	1.7	13.47	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:5	20.45	3268	1.7	13.47	102	197	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:5	20.45	3265	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:6	20.45	3263	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:6	20.45	3262	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:6	20.45	3278	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:6	20.45	3250	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:6	20.45	3248	1.7	13.44	103	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:6	20.45	3230	1.7	13.45	103	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:6	20.45	3240	1.7	13.43	103	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:7	20.45	3239	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:7	20.45	3226	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:7	20.45	3239	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:7	20.45	3239	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:7	20.45	3251	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:7	20.45	3242	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:8	20.45	3240	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:8	20.45	3242	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:8	20.45	3242	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:8	20.45	3243	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:8	20.45	3242	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:8	20.45	3242	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:9	20.45	3238	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:9	20.45	3238	1.7	13.46	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:9	20.45	3226	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:9	20.45	3238	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:9	20.45	3236	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:9	20.45	3236	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:45:9	20.45	3238	1.7	13.43	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:0	20.45	3239	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:0	20.45	3238	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:0	20.45	3232	1.7	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:0	20.45	3228	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:0	20.45	3241	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:46:0	20.45	3224	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:1	20.45	3211	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:1	20.45	3218	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:1	20.45	3218	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:1	20.45	3204	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:1	20.45	3217	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:1	20.45	3212	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:1	20.45	3216	1.7	13.47	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:2	20.45	3214	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:2	20.45	3214	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:2	20.45	3215	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:2	20.45	3210	1.7	13.43	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:2	20.45	3204	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:2	20.45	3202	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:3	20.45	3200	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:3	20.45	3194	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:3	20.45	3194	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:3	20.45	3192	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:3	20.45	3190	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:3	20.45	3173	1.7	13.46	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:4	20.45	3173	1.7	13.45	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:4	20.45	3142	1.7	13.44	102	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:4	20.45	3119	1.7	13.44	102	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:4	20.45	3111	1.7	13.44	102	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:4	20.45	3082	1.7	13.43	102	197	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:4	20.45	3019	1.7	13.44	102	197	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:4	19.09	3012	1.7	13.42	102	197	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:5	19.09	3006	1.7	13.43	102	197	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:5	19.09	2952	1.71	13.43	102	197	Idle	39.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:5	19.09	2952	1.71	13.43	102	197	Idle	39.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:5	19.09	2943	1.71	13.44	102	197	Idle	38.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:5	19.09	2904	1.71	13.44	102	197	Idle	37.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:5	19.09	2873	1.72	13.44	102	197	Idle	36.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:6	19.09	2873	1.72	13.44	102	197	Idle	35.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:6	19.09	2842	1.72	13.44	102	197	Idle	35.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:6	19.09	2809	1.73	13.45	102	197	Idle	33.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.45	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:6	19.09	2776	1.73	13.45	102	197	Idle	33	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.43	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:6	19.09	2766	1.74	13.46	102	197	Idle	32.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.4	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:6	19.09	2725	1.74	13.45	102	197	Idle	31.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.33	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:6	19.09	2712	1.75	13.45	102	197	Idle	31.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:7	19.09	2657	1.75	13.46	102	197	Idle	30.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.28	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:7	19.09	2657	1.76	13.45	102	197	Idle	30.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.24	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:7	19.09	2647	1.76	13.44	102	197	Idle	31.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.19	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:7	19.09	2614	1.77	13.45	102	197	Idle	31.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.21	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:7	19.09	2614	1.77	13.44	102	197	Idle	31.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.14	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:7	19.09	2564	1.77	13.44	102	197	Idle	31.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:8	19.09	2550	1.78	13.43	102	197	Idle	32.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:8	19.09	2542	1.78	13.44	102	197	Idle	33.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.06	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:8	19.09	2490	1.78	13.44	102	197	Idle	34.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	20.24	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:8	19.09	2484	1.78	13.44	102	197	Idle	35.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:8	19.09	2484	1.78	13.44	102	197	Idle	35.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:8	19.09	2440	1.77	13.44	102	197	Idle	38	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:9	19.09	2416	1.77	13.45	102	197	Idle	39.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:9	19.09	2416	1.76	13.43	102	197	Idle	40.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.03	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:9	19.09	2382	1.75	13.45	102	197	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.05	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:9	19.09	2356	1.74	13.44	102	197	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:9	19.09	2311	1.73	13.43	102	197	Idle	44	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.06	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:46:9	17.72	2311	1.72	13.44	102	197	Idle	46.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:46:9	17.72	2295	1.71	13.44	102	197	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:0	17.72	2262	1.7	13.43	102	197	Idle	49.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:0	17.72	2261	1.68	13.43	102	197	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.14	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:0	17.72	2247	1.67	13.43	102	197	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.14	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:0	17.72	2231	1.65	13.43	102	197	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.23	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:0	17.72	2230	1.63	13.42	102	197	Idle	54.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.25	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:0	17.72	2235	1.61	13.43	102	197	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:1	17.72	2264	1.59	13.45	102	197	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.34	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:1	17.72	2301	1.57	13.45	102	197	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.4	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:1	17.72	2301	1.55	13.43	102	197	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.44	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:1	17.72	2376	1.53	13.45	102	197	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:1	17.72	2382	1.51	13.43	102	197	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:1	17.72	2390	1.49	13.43	102	197	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:1	17.72	2412	1.46	13.43	102	197	Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:2	17.72	2396	1.44	13.43	102	197	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:2	17.72	2389	1.4	13.43	102	197	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:2	17.72	2371	1.37	13.44	102	197	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:2	17.72	2339	1.35	13.44	102	197	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:2	17.72	2322	1.33	13.43	102	197	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:2	17.72	2316	1.31	13.43	102	197	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:3	17.72	2300	1.29	13.44	102	197	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:3	17.72	2281	1.27	13.43	102	197	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:3	17.72	2281	1.25	13.44	102	197	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:3	17.72	2313	1.22	13.45	102	197	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:3	17.72	2343	1.2	13.44	102	197	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:3	17.72	2343	1.19	13.44	102	197	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:4	17.72	2374	1.18	13.44	102	197	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:4	17.72	2376	1.16	13.44	102	197	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:4	17.72	2376	1.16	13.43	102	197	Idle	72	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:4	17.72	2370	1.15	13.44	102	197	Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:4	17.72	2359	1.15	13.44	102	197	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:4	17.72	2348	1.13	13.44	102	197	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:4	17.72	2344	1.13	13.44	102	197	Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:5	17.72	2323	1.13	13.44	102	197	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:5	17.72	2312	1.13	13.43	102	197	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:5	17.72	2312	1.13	13.44	102	197	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:5	17.72	2307	1.13	13.44	102	197	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:5	17.72	2309	1.13	13.43	102	197	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:5	17.72	2310	1.12	13.44	102	197	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:6	17.72	2320	1.12	13.44	102	197	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:6	17.72	2334	1.12	13.44	102	197	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:6	17.72	2341	1.12	13.45	102	197	Idle	73.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:6	17.72	2341	1.12	13.44	102	197	Idle	73.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:6	17.72	2343	1.12	13.45	102	197	Idle	73.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:6	17.72	2359	1.12	13.44	102	197	Idle	73.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:6	17.72	2348	1.12	13.45	102	197	Idle	73.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:7	17.72	2318	1.12	13.45	102	197	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:7	17.72	2312	1.11	13.44	102	197	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:7	17.72	2306	1.11	13.43	102	197	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:7	17.72	2304	1.1	13.45	102	197	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:7	17.72	2300	1.1	13.43	102	197	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:7	17.72	2303	1.1	13.44	102	197	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:8	17.72	2306	1.1	13.45	102	197	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:8	17.72	2312	1.09	13.44	102	197	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:8	17.72	2319	1.09	13.45	102	197	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:8	17.72	2322	1.09	13.44	102	197	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:8	17.72	2341	1.09	13.43	102	197	Full Load	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:47:8	17.72	2338	1.09	13.43	102	197	Off Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:47:9	8.18	2349	1.1	13.44	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:19:47:9	8.18	2349	1.11	13.44	102	197	Off Idle	75.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:19:47:9	10.9	2342	1.12	13.44	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:47:9	10.9	2342	1.13	13.45	102	197	Off Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:47:9	13.63	2342	1.14	13.43	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:47:9	16.36	2310	1.16	13.44	102	197	Off Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:47:9	19.09	2319	1.17	13.41	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:48:0	19.09	2316	1.19	13.41	102	197	Off Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:48:0	21.81	2316	1.22	13.43	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:48:0	21.81	2320	1.24	13.42	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:0	24.54	2326	1.27	13.42	102	197	Off Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:0	27.27	2333	1.29	13.43	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:0	27.27	2333	1.33	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:48:1	29.99	2342	1.36	13.44	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:48:1	29.99	2353	1.39	13.44	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:48:1	32.72	2357	1.43	13.45	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.45	20.23	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:48:1	35.45	2356	1.46	13.45	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:48:1	35.45	2335	1.49	13.44	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.26	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:48:1	35.45	2352	1.54	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:48:1	35.45	2345	1.56	13.43	102	197	Off Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.03	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:48:2	35.45	2346	1.59	13.43	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.92	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:48:2	35.45	2353	1.6	13.43	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.86	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:48:2	35.45	2354	1.62	13.42	102	197	Off Idle	77	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.76	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:48:2	34.08	2337	1.65	13.43	102	197	Off Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.67	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:48:2	34.08	2346	1.7	13.44	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.44	20.25	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:48:2	34.08	2325	1.73	13.42	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.35	20.24	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:48:3	34.08	2304	1.75	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.21	20.25	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:48:3	34.08	2304	1.77	13.41	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.08	20.24	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:48:3	34.08	2291	1.8	13.41	102	197	Off Idle	75.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.95	20.25	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:48:3	34.08	2292	1.82	13.4	102	197	Off Idle	76	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.8	20.24	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:48:3	34.08	2299	1.84	13.42	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.62	20.24	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:48:3	34.08	2316	1.86	13.43	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.47	20.24	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:48:4	34.08	2316	1.88	13.44	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.37	20.24	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:4	34.08	2328	1.9	13.43	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.19	20.23	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:4	34.08	2328	1.92	13.45	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.08	20.14	1.37	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:4	34.08	2328	1.94	13.44	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.99	19.96	1.36	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:4	34.08	2336	1.95	13.43	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.92	19.72	1.34	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:4	34.08	2334	1.97	13.42	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.85	19.43	1.32	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:4	34.08	2335	1.99	13.43	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.77	19.1	1.3	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:5	34.08	2334	2.01	13.43	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.69	18.74	1.28	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:5	34.08	2326	2.02	13.44	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.63	18.38	1.25	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:48:5	34.08	2315	2.03	13.43	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.54	18	1.23	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:48:5	32.72	2315	2.04	13.44	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.44	17.6	1.2	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:48:5	32.72	2304	2.06	13.43	102	197	Off Idle	76	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.41	17.19	1.17	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:48:5	32.72	2303	2.06	13.43	102	197	Off Idle	75.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.33	16.85	1.15	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:48:6	32.72	2304	2.07	13.43	102	197	Off Idle	75.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.28	16.48	1.12	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:48:6	32.72	2304	2.08	13.41	102	197	Off Idle	76	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.28	16.29	1.11	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:48:6	32.72	2308	2.08	13.41	102	197	Off Idle	76	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.23	16.14	1.1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:6	32.72	2322	2.08	13.43	102	197	Off Idle	76	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.19	16.03	1.09	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:6	32.72	2322	2.09	13.43	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.2	15.91	1.08	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:6	32.72	2326	2.09	13.43	102	197	Off Idle	76.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.19	15.79	1.08	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:6	32.72	2326	2.09	13.44	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.17	15.69	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:7	32.72	2328	2.09	13.43	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.19	15.59	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:7	32.72	2330	2.1	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.17	15.48	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:7	32.72	2326	2.1	13.43	102	197	Off Idle	76.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.16	15.42	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:7	32.72	2326	2.1	13.42	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.16	15.39	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:7	32.72	2326	2.09	13.42	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.18	15.34	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:7	32.72	2322	2.09	13.43	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.2	15.28	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:48:8	32.72	2315	2.09	13.42	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.2	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:8	32.72	2315	2.09	13.43	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.21	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:8	32.72	2313	2.09	13.45	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.23	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:8	32.72	2315	2.09	13.44	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.21	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:8	32.72	2318	2.09	13.44	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.17	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:8	32.72	2323	2.09	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.19	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:9	32.72	2326	2.09	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.17	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:9	32.72	2326	2.09	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.14	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:9	32.72	2330	2.09	13.43	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.18	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:9	32.72	2330	2.09	13.43	102	197	Off Idle	76.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.14	14.76	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:9	32.72	2330	2.09	13.43	102	197	Off Idle	76.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.14	14.76	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:48:9	32.72	2328	2.1	13.42	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.1	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:48:9	32.72	2327	2.1	13.41	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.04	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:0	32.72	2327	2.1	13.42	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:0	32.72	2328	2.11	13.42	102	197	Off Idle	76	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.99	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:0	32.72	2329	2.11	13.43	102	197	Off Idle	75.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.96	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:0	32.72	2328	2.11	13.42	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.9	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:0	32.72	2332	2.12	13.41	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.91	14.77	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:0	32.72	2344	2.12	13.41	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.89	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:1	32.72	2333	2.13	13.42	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.86	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:1	32.72	2332	2.13	13.41	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.81	14.74	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:1	32.72	2334	2.14	13.43	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.77	14.74	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:1	32.72	2330	2.14	13.43	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.72	14.72	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:1	32.72	2330	2.14	13.43	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.73	14.69	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:1	32.72	2320	2.15	13.43	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.72	14.68	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:1	32.72	2328	2.15	13.43	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.71	14.68	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:2	32.72	2329	2.16	13.43	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.71	14.68	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:2	32.72	2328	2.16	13.43	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.71	14.69	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:2	32.72	2327	2.16	13.43	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.77	14.7	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:2	32.72	2324	2.16	13.41	102	197	Off Idle	75.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.74	14.69	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:2	32.72	2326	2.17	13.43	102	197	Off Idle	75.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.72	14.7	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:2	32.72	2328	2.17	13.42	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.73	14.7	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:3	32.72	2326	2.17	13.42	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.69	14.7	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:3	32.72	2330	2.17	13.43	102	197	Off Idle	75.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.66	14.7	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:3	32.72	2330	2.17	13.44	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.68	14.69	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:3	32.72	2333	2.17	13.42	102	197	Off Idle	75	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.66	14.69	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:3	32.72	2335	2.17	13.43	102	197	Off Idle	75	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.63	14.68	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:3	32.72	2328	2.17	13.43	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.65	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:4	32.72	2341	2.17	13.42	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.64	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:4	32.72	2341	2.17	13.43	102	197	Off Idle	75	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.64	14.64	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:4	32.72	2340	2.17	13.43	102	197	Off Idle	75	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.67	14.62	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:4	32.72	2339	2.17	13.41	102	197	Off Idle	75	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.63	14.61	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:4	32.72	2349	2.17	13.42	102	197	Off Idle	75	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.6	14.61	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:4	32.72	2345	2.17	13.43	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.61	14.6	0.99	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:4	32.72	2345	2.17	13.42	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.61	14.6	0.99	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:5	32.72	2346	2.17	13.43	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.59	14.61	0.99	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:5	32.72	2346	2.17	13.43	102	197	Off Idle	74.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.62	14.62	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:5	32.72	2345	2.17	13.42	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.63	14.62	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:5	32.72	2338	2.17	13.42	102	197	Off Idle	75	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.63	14.63	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:5	32.72	2338	2.17	13.42	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.62	14.63	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:5	32.72	2339	2.17	13.41	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.6	14.65	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:6	32.72	2338	2.17	13.43	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.63	14.67	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:6	32.72	2340	2.17	13.42	102	197	Off Idle	75	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.63	14.69	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:6	32.72	2340	2.18	13.43	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.59	14.7	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:6	32.72	2338	2.18	13.44	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.58	14.72	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:6	32.72	2338	2.18	13.44	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.57	14.73	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:6	32.72	2339	2.18	13.43	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.56	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:6	32.72	2340	2.18	13.44	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.55	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:49:7	32.72	2344	2.18	13.42	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.57	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:7	32.72	2345	2.18	13.43	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.54	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:7	32.72	2344	2.18	13.42	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.6	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:7	32.72	2342	2.18	13.42	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.59	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:7	32.72	2353	2.18	13.42	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.57	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:7	32.72	2372	2.18	13.45	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.6	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:8	32.72	2372	2.18	13.44	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.62	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:49:8	32.72	2354	2.18	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.6	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:8	32.72	2353	2.18	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.62	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:8	32.72	2352	2.18	13.42	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.6	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:8	32.72	2352	2.19	13.42	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.57	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:8	32.72	2352	2.19	13.42	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.58	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:9	32.72	2352	2.19	13.41	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.57	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:9	32.72	2352	2.19	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.52	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:9	32.72	2349	2.19	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.55	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:9	32.72	2349	2.19	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.55	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:9	32.72	2350	2.19	13.43	102	197	Off Idle	74.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.55	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:9	32.72	2351	2.19	13.42	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.55	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:49:9	32.72	2352	2.19	13.42	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.53	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:0	32.72	2350	2.19	13.42	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.53	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:0	32.72	2351	2.19	13.42	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.55	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:0	32.72	2352	2.19	13.43	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.51	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:0	32.72	2355	2.19	13.44	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.58	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:0	32.72	2356	2.19	13.42	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.58	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:0	32.72	2356	2.19	13.42	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.54	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:1	32.72	2354	2.19	13.43	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.6	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:1	32.72	2352	2.19	13.43	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.6	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:1	32.72	2352	2.18	13.43	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.61	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:1	32.72	2352	2.18	13.45	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.61	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:1	32.72	2353	2.18	13.44	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.56	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:1	32.72	2355	2.19	13.44	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.56	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:1	32.72	2357	2.19	13.43	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.56	15.05	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:2	32.72	2357	2.19	13.43	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.54	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:2	32.72	2366	2.19	13.44	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.55	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:2	32.72	2368	2.19	13.44	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.54	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:2	32.72	2368	2.19	13.44	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.52	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:2	32.72	2368	2.19	13.43	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.54	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:2	32.72	2366	2.19	13.42	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.58	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:3	32.72	2360	2.19	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.59	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:3	32.72	2362	2.19	13.42	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.59	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:3	32.72	2360	2.19	13.41	102	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.58	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:3	32.72	2361	2.19	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.57	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:3	32.72	2361	2.19	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.55	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:3	32.72	2365	2.19	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.56	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:4	32.72	2362	2.19	13.44	102	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.56	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:4	32.72	2361	2.19	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.57	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:4	32.72	2362	2.19	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.55	15.22	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:4	32.72	2368	2.19	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.59	15.27	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:4	32.72	2370	2.19	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.59	15.29	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:4	32.72	2369	2.19	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.59	15.3	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:4	32.72	2369	2.19	13.44	102	197	Off Idle	74	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.61	15.32	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:5	32.72	2365	2.19	13.44	102	197	Off Idle	74	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.61	15.31	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:5	32.72	2361	2.19	13.44	102	197	Off Idle	74	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.6	15.3	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:5	32.72	2353	2.19	13.44	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.61	15.27	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:5	32.72	2353	2.19	13.43	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.61	15.25	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:5	32.72	2356	2.19	13.43	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.59	15.23	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:5	32.72	2361	2.19	13.44	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.6	15.2	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:6	32.72	2361	2.19	13.44	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.61	15.18	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:50:6	32.72	2365	2.19	13.44	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.58	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:6	32.72	2370	2.19	13.44	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.61	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:6	32.72	2370	2.19	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.59	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:6	32.72	2370	2.19	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.57	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:6	32.72	2369	2.19	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.58	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:6	32.72	2362	2.19	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.6	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:7	32.72	2360	2.19	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.6	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:7	32.72	2360	2.19	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.6	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:7	32.72	2362	2.19	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.59	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:7	32.72	2362	2.19	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.59	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:7	32.72	2366	2.19	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.56	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:7	32.72	2376	2.19	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.56	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:8	32.72	2384	2.19	13.44	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.6	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:8	32.72	2384	2.19	13.44	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.61	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:8	32.72	2390	2.19	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.64	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:8	32.72	2387	2.19	13.44	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.64	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:8	32.72	2386	2.19	13.45	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.65	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:8	32.72	2378	2.19	13.45	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.64	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:9	32.72	2369	2.19	13.44	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.66	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:50:9	32.72	2368	2.19	13.44	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.69	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:9	32.72	2369	2.18	13.44	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.71	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:9	32.72	2388	2.18	13.44	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.78	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:50:9	32.72	2374	2.18	13.44	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.79	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:9	32.72	2376	2.18	13.44	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.81	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:50:9	32.72	2385	2.17	13.44	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.86	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:51:0	32.72	2369	2.17	13.43	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.9	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:51:0	32.72	2376	2.16	13.43	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.96	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:51:0	32.72	2380	2.16	13.41	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.02	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:51:0	32.72	2372	2.15	13.42	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.06	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:51:0	32.72	2372	2.15	13.42	102	197	Off Idle	73.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.11	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:51:0	32.72	2373	2.14	13.42	102	197	Off Idle	73.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.19	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:51:1	32.72	2370	2.13	13.42	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.33	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:51:1	32.72	2369	2.12	13.41	102	197	Off Idle	73.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.37	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:51:1	32.72	2369	2.11	13.42	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.44	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:51:1	32.72	2374	2.1	13.42	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.56	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:51:1	32.72	2375	2.09	13.41	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.6	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:51:1	32.72	2379	2.07	13.42	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.72	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:51:1	32.72	2379	2.06	13.44	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.85	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:51:2	32.72	2379	2.05	13.43	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.93	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:51:2	32.72	2375	2.04	13.42	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:51:2	32.72	2375	2.02	13.44	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.11	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:51:2	32.72	2370	2.01	13.43	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.19	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:51:2	34.08	2378	1.99	13.43	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.26	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:51:2	34.08	2366	1.98	13.42	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.3	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:51:3	34.08	2366	1.97	13.43	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.34	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:51:3	34.08	2367	1.96	13.43	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.41	14.9	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:51:3	34.08	2370	1.95	13.42	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.46	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:3	34.08	2372	1.94	13.42	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.49	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:3	34.08	2378	1.92	13.42	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:3	34.08	2383	1.91	13.42	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:4	34.08	2385	1.9	13.43	102	197	Off Idle	73.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:4	34.08	2385	1.89	13.43	102	197	Off Idle	73.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.81	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:4	34.08	2390	1.88	13.42	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.83	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:4	34.08	2384	1.87	13.44	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.91	15.15	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:4	34.08	2382	1.87	13.42	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.96	15.16	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:4	34.08	2382	1.86	13.43	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.04	15.16	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:51:4	34.08	2376	1.85	13.43	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.13	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:51:5	34.08	2376	1.84	13.44	102	197	Off Idle	73	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.18	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:51:5	34.08	2376	1.83	13.44	102	197	Off Idle	73	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.23	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:5	34.08	2370	1.82	13.44	102	197	Off Idle	72.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.3	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:5	34.08	2370	1.81	13.42	102	197	Off Idle	72.9	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.35	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:5	34.08	2368	1.8	13.43	102	197	Off Idle	72.8	0	2	132	944 Turbo	0.68	Lean	1	14.6	-8.37	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:5	34.08	2371	1.8	13.42	102	197	Off Idle	72.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.42	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:6	34.08	2374	1.79	13.43	102	197	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.45	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:6	34.08	2374	1.78	13.43	102	197	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.48	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:6	34.08	2375	1.77	13.42	102	197	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.52	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:6	34.08	2379	1.77	13.42	102	197	Off Idle	72.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.54	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:6	34.08	2379	1.76	13.41	102	197	Off Idle	72.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.58	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:6	34.08	2383	1.75	13.41	102	197	Off Idle	72.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.62	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:6	34.08	2386	1.74	13.42	102	197	Off Idle	72.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.65	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:7	34.08	2384	1.73	13.43	102	197	Off Idle	72.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.7	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:7	34.08	2384	1.73	13.42	102	197	Off Idle	72.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.77	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:7	34.08	2377	1.72	13.43	102	197	Off Idle	72.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.83	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:51:7	34.08	2370	1.71	13.44	102	197	Off Idle	72.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.86	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:7	34.08	2370	1.71	13.45	102	197	Off Idle	72.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.88	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:7	34.08	2366	1.7	13.42	102	197	Off Idle	72.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.94	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:8	34.08	2364	1.69	13.43	102	197	Off Idle	73	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.93	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:8	34.08	2366	1.69	13.44	102	197	Off Idle	73	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.94	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:8	34.08	2366	1.68	13.43	102	197	Off Idle	73	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.01	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:51:8	34.08	2365	1.67	13.43	102	197	Off Idle	73	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.04	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:51:8	34.08	2369	1.67	13.43	102	197	Off Idle	73	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.08	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:51:8	34.08	2380	1.66	13.42	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.15	14.8	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:51:9	34.08	2371	1.65	13.41	102	197	Off Idle	73.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.2	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:51:9	34.08	2372	1.65	13.41	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.24	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:51:9	34.08	2372	1.64	13.43	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.24	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:51:9	34.08	2370	1.63	13.41	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.26	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:51:9	34.08	2359	1.63	13.43	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.25	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:51:9	34.08	2369	1.62	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.27	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:51:9	34.08	2368	1.61	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.29	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:0	34.08	2368	1.61	13.43	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.3	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:0	34.08	2376	1.6	13.43	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.32	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:0	34.08	2375	1.6	13.43	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.36	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:0	34.08	2373	1.59	13.42	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.39	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:0	34.08	2377	1.59	13.42	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.39	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:0	34.08	2377	1.58	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.41	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:1	34.08	2378	1.58	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.43	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:1	34.08	2381	1.58	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.41	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:1	34.08	2380	1.58	13.43	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.42	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:1	34.08	2381	1.58	13.43	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.42	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:1	35.45	2400	1.57	13.43	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.42	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:1	35.45	2381	1.57	13.43	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-9.44	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:1	35.45	2381	1.57	13.43	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.16	Rich	1	14.6	-9.46	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:2	35.45	2382	1.57	13.43	102	197	Off Idle	73.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.46	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:2	35.45	2379	1.57	13.43	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.47	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:2	35.45	2376	1.57	13.43	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.47	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:2	35.45	2366	1.57	13.44	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.47	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:2	35.45	2362	1.57	13.44	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.47	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:2	35.45	2362	1.57	13.42	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.48	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:3	35.45	2354	1.57	13.44	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.45	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:3	35.45	2356	1.57	13.43	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:3	35.45	2355	1.57	13.43	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.46	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:3	35.45	2357	1.57	13.44	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.46	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:3	35.45	2362	1.57	13.43	102	197	Off Idle	73.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.49	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:3	35.45	2364	1.57	13.43	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.48	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:4	35.45	2364	1.57	13.44	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.49	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:4	35.45	2371	1.57	13.44	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.52	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:52:4	35.45	2373	1.57	13.44	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.52	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:4	35.45	2373	1.56	13.45	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.52	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:4	35.45	2372	1.56	13.44	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.56	15.17	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:19:52:4	35.45	2373	1.56	13.44	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.56	15.18	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:4	35.45	2371	1.56	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.57	15.18	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:5	35.45	2362	1.55	13.44	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.56	15.18	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:5	35.45	2359	1.55	13.43	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.59	15.18	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:5	35.45	2359	1.55	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.58	15.17	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:5	35.45	2356	1.54	13.45	102	197	Off Idle	74	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.57	15.16	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:5	35.45	2358	1.54	13.43	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.6	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:5	35.45	2358	1.54	13.43	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.59	15.14	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:6	35.45	2356	1.54	13.41	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.59	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:6	35.45	2359	1.54	13.42	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.59	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:6	35.45	2359	1.53	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.6	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:6	35.45	2360	1.53	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.61	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:6	35.45	2361	1.53	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.62	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:6	35.45	2360	1.53	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.64	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:6	35.45	2356	1.52	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.66	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:7	35.45	2357	1.52	13.43	102	197	Off Idle	74	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.66	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:7	35.45	2357	1.52	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.66	15.01	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:7	35.45	2355	1.52	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.65	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:7	35.45	2355	1.51	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.66	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:7	35.45	2356	1.51	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.66	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:7	35.45	2357	1.51	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.69	14.9	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:8	35.45	2359	1.51	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.71	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:8	35.45	2361	1.5	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.76	14.8	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:8	35.45	2362	1.5	13.45	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.79	14.76	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:8	35.45	2362	1.5	13.43	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.82	14.75	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:8	35.45	2364	1.49	13.44	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.82	14.74	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:8	35.45	2357	1.49	13.44	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.85	14.74	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:9	35.45	2357	1.48	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.93	14.76	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:52:9	35.45	2356	1.47	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.95	14.76	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:52:9	35.45	2356	1.46	13.41	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.99	14.77	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:52:9	35.45	2356	1.45	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.06	14.77	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:52:9	35.45	2353	1.42	13.41	102	197	Full Load	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.17	14.76	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:52:9	35.45	2353	1.4	13.42	102	197	Idle	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.26	14.78	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:52:9	35.45	2348	1.37	13.43	102	197	Idle	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.34	14.81	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:53:0	35.45	2340	1.35	13.45	102	197	Idle	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.42	14.83	1.01	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:0	35.45	2327	1.33	13.45	102	197	Idle	74.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.52	14.86	1.01	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:0	35.45	2327	1.31	13.43	102	197	Idle	74.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.6	14.89	1.01	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:0	35.45	2312	1.29	13.43	102	197	Idle	74.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.62	14.93	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:53:0	32.72	2263	1.27	13.43	102	197	Idle	74.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.66	14.95	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:53:0	32.72	2272	1.25	13.42	102	197	Idle	74.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.69	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:53:1	27.27	2272	1.23	13.42	102	197	Idle	74.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.71	15.03	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:53:1	27.27	2286	1.21	13.43	102	197	Idle	75	0	2	132	944 Turbo	0.43	Lean	1	14.6	-10.7	15.06	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:1	21.81	2286	1.2	13.43	102	197	Idle	75.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-10.71	15.07	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:1	17.72	2320	1.18	13.45	102	197	Idle	75.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.71	15.11	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:1	17.72	2359	1.15	13.46	102	197	Idle	75.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.71	15.11	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:1	17.72	2364	1.14	13.46	102	197	Idle	75.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.74	15.11	1.03	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:1	17.72	2373	1.12	13.45	102	197	Idle	75.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.75	15.1	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:2	17.72	2360	1.11	13.45	102	197	Idle	75.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-10.75	15.1	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:2	17.72	2348	1.1	13.44	102	197	Idle	75.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-10.8	15.09	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:2	17.72	2348	1.09	13.44	102	197	Idle	75.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-10.79	15.09	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:2	17.72	2339	1.1	13.42	102	197	Idle	75.4	0	2	132	944 Turbo	0.14	Rich	1	14.6	-10.77	15.08	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:2	17.72	2328	1.1	13.44	102	197	Idle	75.2	0	2	132	944 Turbo	0.09	Rich	1	14.6	-10.73	15.06	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:2	17.72	2323	1.1	13.44	102	197	Idle	75.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.73	15.03	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:3	17.72	2323	1.1	13.43	102	197	Idle	75.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.72	15.02	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:3	17.72	2326	1.1	13.43	102	197	Idle	75	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.69	15	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:53:3	17.72	2331	1.09	13.44	102	197	Idle	74.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.68	15	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:3	17.72	2334	1.09	13.43	102	197	Idle	74.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.68	15	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:3	17.72	2335	1.09	13.43	102	197	Idle	74.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.68	14.99	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:3	17.72	2351	1.1	13.43	102	197	Idle	74.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.66	14.98	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:4	17.72	2354	1.1	13.44	102	197	Idle	74.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.71	14.99	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:4	17.72	2373	1.1	13.44	102	197	Idle	74.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.71	15.01	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:4	17.72	2351	1.1	13.44	102	197	Idle	74.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.69	15.01	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:4	17.72	2351	1.1	13.44	102	197	Idle	74.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.68	15.01	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:4	17.72	2344	1.1	13.43	102	197	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	14.99	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:4	17.72	2338	1.1	13.43	102	197	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	15.01	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:4	17.72	2326	1.11	13.43	102	197	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	15.03	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:5	17.72	2326	1.11	13.44	102	197	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	15.06	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:5	17.72	2299	1.11	13.43	102	197	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	15.12	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:5	17.72	2299	1.11	13.43	102	197	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	15.22	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:5	17.72	2331	1.11	13.43	102	197	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	15.32	1.04	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:5	17.72	2315	1.11	13.43	102	197	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	15.57	1.06	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:5	17.72	2318	1.11	13.42	102	197	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	15.79	1.08	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:6	17.72	2312	1.11	13.43	102	197	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	16.09	1.1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:6	17.72	2329	1.11	13.44	102	197	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	16.43	1.12	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:6	17.72	2332	1.11	13.44	102	197	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	16.85	1.15	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:6	17.72	2332	1.11	13.44	102	197	Idle	74.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	17.33	1.18	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:6	17.72	2353	1.11	13.44	102	197	Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	17.81	1.21	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:6	17.72	2335	1.11	13.44	102	197	Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	18.26	1.24	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:6	17.72	2334	1.11	13.44	102	197	Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	18.66	1.27	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:7	17.72	2321	1.11	13.43	102	197	Idle	75.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	19.05	1.3	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:7	17.72	2343	1.11	13.43	102	197	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	19.41	1.32	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:7	17.72	2319	1.1	13.44	102	197	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	19.83	1.35	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:7	17.72	2319	1.1	13.44	102	197	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.05	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:7	17.72	2315	1.1	13.45	102	197	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.18	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:7	17.72	2310	1.1	13.45	102	197	Idle	75.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:8	17.72	2302	1.1	13.44	102	197	Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:8	17.72	2308	1.1	13.44	102	197	Idle	75.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:8	17.72	2308	1.1	13.44	102	197	Idle	75.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:8	17.72	2308	1.1	13.43	102	197	Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:8	17.72	2310	1.1	13.44	102	197	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:8	17.72	2311	1.1	13.45	102	197	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:9	17.72	2312	1.09	13.43	102	197	Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:9	17.72	2312	1.09	13.43	102	197	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:9	17.72	2314	1.09	13.44	102	197	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:9	17.72	2315	1.09	13.44	102	197	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:9	17.72	2316	1.09	13.44	102	197	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:9	17.72	2313	1.09	13.45	102	197	Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:53:9	17.72	2311	1.09	13.45	102	197	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:0	17.72	2311	1.09	13.44	102	197	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:0	17.72	2306	1.09	13.45	102	197	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:0	17.72	2304	1.09	13.45	102	197	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:0	17.72	2304	1.08	13.46	102	197	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:0	17.72	2304	1.08	13.46	102	197	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:0	17.72	2303	1.08	13.44	102	197	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:1	17.72	2303	1.08	13.43	102	197	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:1	17.72	2304	1.08	13.44	102	197	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:1	17.72	2306	1.08	13.44	102	197	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:1	17.72	2307	1.08	13.45	102	197	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:1	17.72	2308	1.08	13.45	102	197	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:1	17.72	2307	1.08	13.44	102	197	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:1	17.72	2304	1.08	13.45	102	197	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:2	17.72	2304	1.08	13.45	102	197	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:2	17.72	2298	1.08	13.43	102	197	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:54:2	17.72	2294	1.08	13.42	102	197	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:2	17.72	2294	1.08	13.43	102	197	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:2	17.72	2286	1.08	13.43	102	197	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:2	17.72	2283	1.08	13.42	102	197	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:3	17.72	2282	1.07	13.43	102	197	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:3	17.72	2282	1.07	13.44	102	197	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:3	17.72	2280	1.07	13.43	102	197	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:3	17.72	2283	1.07	13.43	102	197	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:3	17.72	2283	1.07	13.44	102	197	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:3	17.72	2289	1.07	13.44	102	197	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:4	17.72	2290	1.07	13.44	102	197	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:4	17.72	2292	1.07	13.45	102	197	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:4	17.72	2294	1.07	13.44	102	197	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:4	17.72	2293	1.07	13.43	102	197	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:4	17.72	2287	1.07	13.44	102	197	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:4	17.72	2287	1.07	13.44	102	197	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:4	17.72	2284	1.07	13.43	102	197	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:5	17.72	2280	1.07	13.45	102	197	Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:5	17.72	2280	1.07	13.45	102	197	Idle	77.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:5	17.72	2278	1.07	13.44	102	197	Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:5	17.72	2278	1.07	13.45	102	197	Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:5	17.72	2278	1.07	13.45	102	197	Idle	77.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:5	17.72	2277	1.07	13.44	102	197	Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:6	17.72	2279	1.07	13.44	102	197	Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:6	17.72	2279	1.07	13.44	102	197	Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:6	17.72	2278	1.07	13.44	102	197	Idle	77.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:6	17.72	2276	1.07	13.43	102	197	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:6	17.72	2276	1.07	13.43	102	197	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:6	17.72	2276	1.07	13.44	102	197	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:6	17.72	2275	1.07	13.44	102	197	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:7	17.72	2270	1.07	13.44	102	197	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:7	17.72	2270	1.07	13.44	102	197	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:7	17.72	2270	1.06	13.44	102	197	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:7	17.72	2248	1.06	13.44	102	197	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:7	17.72	2256	1.06	13.43	102	197	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:7	17.72	2263	1.06	13.42	102	197	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:8	17.72	2268	1.06	13.45	102	197	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:8	17.72	2268	1.06	13.44	102	197	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:8	17.72	2255	1.06	13.44	102	197	Idle	77.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:8	17.72	2260	1.06	13.45	102	197	Idle	78	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:8	17.72	2263	1.06	13.46	102	197	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:8	17.72	2263	1.06	13.45	102	197	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:9	17.72	2265	1.06	13.44	102	197	Idle	78.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:9	17.72	2264	1.06	13.44	102	197	Full Load	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:9	17.72	2264	1.06	13.44	102	197	Off Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:9	17.72	2262	1.06	13.43	102	197	Off Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:54:9	8.18	2146	1.06	13.43	102	197	Off Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:19:54:9	8.18	2146	1.07	13.42	102	197	Off Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:19:54:9	10.9	2274	1.08	13.43	102	197	Off Idle	78.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:55:0	10.9	2270	1.08	13.44	102	197	Off Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:55:0	13.63	2270	1.09	13.45	102	197	Off Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:55:0	13.63	2270	1.09	13.45	102	197	Off Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:19:55:0	16.36	2280	1.1	13.46	102	197	Off Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:0	19.09	2270	1.1	13.44	102	197	Off Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:0	19.09	2271	1.11	13.43	102	197	Off Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:1	21.81	2265	1.12	13.43	102	197	Off Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:1	24.54	2276	1.12	13.43	102	197	Off Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:1	24.54	2276	1.13	13.42	102	197	Off Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:55:1	27.27	2274	1.13	13.43	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:1	27.27	2276	1.14	13.43	102	197	Off Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:1	29.99	2290	1.15	13.43	102	197	Off Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:1	29.99	2290	1.16	13.43	102	197	Off Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:2	32.72	2265	1.18	13.42	102	197	Off Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:19:55:2	34.08	2249	1.19	13.41	102	197	Off Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:55:2	34.08	2249	1.2	13.42	102	197	Off Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:55:2	34.08	2251	1.21	13.43	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:55:2	34.08	2246	1.22	13.42	102	197	Off Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:55:2	34.08	2246	1.23	13.4	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:55:3	34.08	2244	1.25	13.4	102	197	Off Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:19:55:3	34.08	2233	1.26	13.39	102	197	Off Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:55:3	35.45	2274	1.28	13.41	102	197	Off Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:19:55:3	35.45	2264	1.3	13.42	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:55:3	35.45	2250	1.34	13.42	102	197	Off Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:19:55:3	35.45	2251	1.37	13.42	102	197	Off Idle	79.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.67	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:55:4	35.45	2251	1.39	13.43	102	197	Off Idle	79.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.56	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:19:55:4	35.45	2260	1.42	13.43	102	197	Off Idle	79.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.46	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:4	35.45	2265	1.44	13.43	102	197	Off Idle	79.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.41	20.25	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:4	34.08	2258	1.47	13.43	102	197	Off Idle	79.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.17	20.24	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:4	34.08	2300	1.5	13.44	102	197	Off Idle	79.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.09	20.24	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:4	34.08	2285	1.53	13.42	102	197	Off Idle	79.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9	20.24	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:4	34.08	2288	1.55	13.43	102	197	Off Idle	79.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.86	20.24	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:5	34.08	2297	1.59	13.44	102	197	Off Idle	79.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.77	20.24	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:5	34.08	2297	1.61	13.42	102	197	Off Idle	79.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.69	20.23	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:5	34.08	2291	1.64	13.43	102	197	Off Idle	79.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.61	20.23	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:5	34.08	2286	1.66	13.45	102	197	Off Idle	79	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.52	20.23	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:5	34.08	2245	1.68	13.45	102	197	Off Idle	78.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.47	20.24	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:5	34.08	2245	1.69	13.44	102	197	Off Idle	78.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.45	20.24	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:6	34.08	2226	1.71	13.43	102	197	Off Idle	78.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.37	20.24	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:6	34.08	2212	1.74	13.42	102	197	Off Idle	78.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.29	20.25	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:55:6	34.08	2212	1.75	13.41	102	197	Off Idle	78.7	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.21	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:6	34.08	2205	1.76	13.42	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.14	20.16	1.37	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:6	34.08	2219	1.77	13.43	102	197	Off Idle	79	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.1	19.99	1.36	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:6	34.08	2228	1.77	13.41	102	197	Off Idle	79.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.08	19.78	1.35	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:6	34.08	2228	1.78	13.41	102	197	Off Idle	79.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.1	19.5	1.33	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:7	34.08	2242	1.78	13.43	102	197	Off Idle	79.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.05	19	1.29	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:7	34.08	2249	1.79	13.43	102	197	Off Idle	79.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.06	18.61	1.27	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:7	34.08	2242	1.79	13.42	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.1	18.2	1.24	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:7	32.72	2242	1.79	13.42	102	197	Off Idle	79.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.07	17.74	1.21	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:7	32.72	2268	1.79	13.43	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.07	17.27	1.18	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:7	32.72	2258	1.79	13.43	102	197	Off Idle	80.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.07	16.84	1.15	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:8	32.72	2258	1.79	13.42	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.07	16.48	1.12	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:8	32.72	2251	1.79	13.43	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.03	16.18	1.1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:8	32.72	2238	1.79	13.44	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.04	15.81	1.08	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:55:8	32.72	2228	1.79	13.44	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.01	15.71	1.07	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:8	34.08	2244	1.79	13.42	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.06	15.47	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:8	34.08	2239	1.78	13.42	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8	15.36	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:9	34.08	2266	1.78	13.44	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8	15.25	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:9	34.08	2266	1.78	13.44	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.02	15.18	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:9	34.08	2255	1.78	13.44	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.04	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:9	34.08	2258	1.78	13.45	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.04	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:9	32.72	2258	1.78	13.45	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.07	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:9	32.72	2258	1.78	13.45	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.09	15.05	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:55:9	32.72	2250	1.78	13.44	102	197	Off Idle	80.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.1	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:0	32.72	2244	1.78	13.42	102	197	Off Idle	80.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.1	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:0	32.72	2225	1.78	13.42	102	197	Off Idle	81	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.16	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:0	32.72	2232	1.78	13.41	102	197	Off Idle	80.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.17	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:56:0	32.72	2236	1.78	13.41	102	197	Off Idle	80.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.13	15.2	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:0	32.72	2236	1.78	13.42	102	197	Off Idle	80.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.1	15.25	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:0	32.72	2240	1.78	13.43	102	197	Off Idle	80.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.1	15.31	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:1	32.72	2242	1.78	13.43	102	197	Off Idle	80.7	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.06	15.33	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:1	32.72	2245	1.77	13.44	102	197	Off Idle	80.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.02	15.38	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:1	32.72	2245	1.77	13.45	102	197	Off Idle	80.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.03	15.37	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:1	32.72	2247	1.77	13.45	102	197	Off Idle	80.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.04	15.38	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:1	32.72	2249	1.77	13.44	102	197	Off Idle	80.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.06	15.38	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:1	32.72	2251	1.77	13.43	102	197	Off Idle	80.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.08	15.36	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:1	32.72	2251	1.77	13.43	102	197	Off Idle	80.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.08	15.35	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:2	32.72	2251	1.77	13.43	102	197	Off Idle	80.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.07	15.31	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:2	32.72	2250	1.77	13.42	102	197	Off Idle	80.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.04	15.27	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:2	32.72	2248	1.77	13.43	102	197	Off Idle	80.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.01	15.23	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:2	32.72	2244	1.77	13.44	102	197	Off Idle	80.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.04	15.19	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:2	34.08	2261	1.77	13.43	102	197	Off Idle	80.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.07	15.15	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:2	34.08	2247	1.77	13.41	102	197	Off Idle	81.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.03	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:56:3	34.08	2246	1.77	13.43	102	197	Off Idle	81.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.02	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:19:56:3	34.08	2248	1.78	13.43	102	197	Off Idle	81.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:3	34.08	2249	1.78	13.43	102	197	Off Idle	81.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.02	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:3	34.08	2249	1.78	13.43	102	197	Off Idle	81.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.95	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:3	34.08	2261	1.79	13.44	102	197	Off Idle	80.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.9	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:3	34.08	2259	1.79	13.43	102	197	Off Idle	80.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.87	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:19:56:4	34.08	2260	1.8	13.43	102	197	Off Idle	80.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.82	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:56:4	34.08	2256	1.81	13.44	102	197	Off Idle	80.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	14.77	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:56:4	34.08	2257	1.82	13.43	102	197	Off Idle	80.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.63	14.7	1	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:19:56:4	34.08	2255	1.83	13.42	102	197	Off Idle	80.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.57	14.68	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:4	34.08	2253	1.83	13.43	102	197	Off Idle	80.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.51	14.67	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:4	34.08	2253	1.85	13.43	102	197	Off Idle	80.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.38	14.63	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:4	32.72	2248	1.85	13.44	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.35	14.61	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:5	32.72	2248	1.86	13.43	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.31	14.6	0.99	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:5	32.72	2245	1.87	13.45	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.24	14.6	0.99	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:5	32.72	2248	1.88	13.45	102	197	Off Idle	80	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.24	14.6	0.99	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:5	32.72	2248	1.89	13.45	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.2	14.61	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:5	32.72	2244	1.89	13.44	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.14	14.63	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:5	32.72	2243	1.9	13.42	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.1	14.63	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:6	32.72	2245	1.91	13.42	102	197	Off Idle	80	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.07	14.63	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:6	32.72	2245	1.92	13.41	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.05	14.64	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:6	32.72	2246	1.93	13.41	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.01	14.67	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:6	32.72	2236	1.94	13.43	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.97	14.7	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:6	32.72	2256	1.94	13.42	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.94	14.72	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:6	32.72	2256	1.95	13.42	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.92	14.73	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:6	34.08	2280	1.95	13.42	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.92	14.76	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:7	34.08	2266	1.96	13.43	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.89	14.78	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:7	34.08	2274	1.96	13.42	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.81	14.79	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:7	34.08	2264	1.96	13.43	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.81	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:19:56:7	34.08	2260	1.96	13.42	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.8	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:56:7	34.08	2260	1.96	13.43	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.77	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:56:7	34.08	2250	1.97	13.41	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.75	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:56:8	32.72	2229	1.97	13.42	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.73	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:56:8	32.72	2245	1.98	13.42	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.69	14.76	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:56:8	32.72	2241	1.98	13.42	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.6	14.74	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:19:56:8	32.72	2240	1.99	13.42	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.54	14.75	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:56:8	32.72	2234	2	13.45	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.46	14.75	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:56:8	32.72	2251	2.01	13.44	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.4	14.75	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:56:9	32.72	2264	2.01	13.43	102	197	Off Idle	80	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.35	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:56:9	32.72	2264	2.02	13.43	102	197	Off Idle	80	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.3	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:56:9	32.72	2268	2.03	13.43	102	197	Off Idle	80	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.26	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:56:9	32.72	2283	2.03	13.41	102	197	Off Idle	80	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.2	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:56:9	32.72	2274	2.04	13.43	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.08	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:56:9	32.72	2265	2.05	13.45	102	197	Off Idle	80	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.03	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:56:9	32.72	2257	2.05	13.45	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.99	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:0	32.72	2257	2.06	13.42	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.98	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:0	32.72	2248	2.07	13.43	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.91	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:0	32.72	2254	2.08	13.43	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.87	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:57:0	32.72	2256	2.08	13.41	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.87	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:0	32.72	2258	2.09	13.4	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.81	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:0	32.72	2257	2.09	13.4	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.78	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:1	32.72	2258	2.1	13.41	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.77	15.2	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:1	32.72	2259	2.1	13.41	102	197	Off Idle	79.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.73	15.23	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:1	32.72	2253	2.11	13.43	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.7	15.24	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:1	32.72	2253	2.11	13.45	102	197	Off Idle	79.9	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.67	15.25	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:1	32.72	2268	2.12	13.45	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.64	15.26	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:1	32.72	2257	2.12	13.44	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.62	15.21	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:1	32.72	2256	2.13	13.44	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.54	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:2	32.72	2259	2.13	13.43	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.5	15.12	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:2	31.36	2252	2.14	13.43	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.5	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:2	31.36	2256	2.14	13.42	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.45	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:2	31.36	2256	2.15	13.42	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.39	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:57:2	31.36	2264	2.15	13.42	102	197	Off Idle	80.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.32	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:2	31.36	2269	2.16	13.42	102	197	Off Idle	80.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.28	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:57:3	31.36	2275	2.16	13.43	102	197	Off Idle	80.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.16	14.89	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:57:3	32.72	2282	2.17	13.43	102	197	Off Idle	80.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.11	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:57:3	32.72	2283	2.17	13.41	102	197	Off Idle	79.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.12	14.83	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:57:3	32.72	2279	2.18	13.42	102	197	Off Idle	79.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.01	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:57:3	32.72	2278	2.19	13.43	102	197	Off Idle	79.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.98	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:57:3	32.72	2277	2.19	13.43	102	197	Off Idle	79.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.98	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:57:4	32.72	2274	2.2	13.41	102	197	Off Idle	79.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.89	14.9	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:57:4	32.72	2274	2.21	13.43	102	197	Off Idle	79.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.81	14.94	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:4	32.72	2274	2.22	13.42	102	197	Off Idle	79.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.81	14.99	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:4	32.72	2275	2.22	13.42	102	197	Off Idle	79	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.75	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:4	32.72	2272	2.23	13.43	102	197	Off Idle	79	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.65	15.09	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:4	32.72	2278	2.24	13.42	102	197	Off Idle	79	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.64	15.16	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:4	32.72	2279	2.24	13.42	102	197	Off Idle	78.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.65	15.18	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:5	32.72	2279	2.25	13.43	102	197	Off Idle	78.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.51	15.23	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:5	32.72	2279	2.25	13.44	102	197	Off Idle	78.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.51	15.23	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:5	32.72	2276	2.26	13.44	102	197	Off Idle	78.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.47	15.21	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:5	32.72	2271	2.26	13.45	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.43	15.19	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:5	32.72	2270	2.27	13.44	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.43	15.17	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:5	32.72	2269	2.27	13.43	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.38	15.14	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:6	32.72	2250	2.28	13.43	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.35	15.13	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:6	32.72	2259	2.28	13.44	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.34	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:6	32.72	2271	2.29	13.41	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.62	Lean	1	14.6	-4.27	15.12	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:6	32.72	2276	2.29	13.42	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.25	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:6	32.72	2278	2.3	13.43	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.25	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:6	32.72	2278	2.3	13.41	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.21	15.02	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:6	32.72	2280	2.3	13.42	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.19	14.99	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:7	32.72	2280	2.31	13.43	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.14	14.96	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:57:7	32.72	2280	2.31	13.42	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.1	14.93	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:7	32.72	2280	2.31	13.41	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.07	14.89	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:7	32.72	2286	2.31	13.44	102	197	Off Idle	78.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.03	14.85	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:57:7	32.72	2287	2.32	13.43	102	197	Off Idle	78.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.97	14.77	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:57:7	32.72	2288	2.32	13.42	102	197	Off Idle	78.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.02	14.71	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:8	32.72	2290	2.32	13.42	102	197	Off Idle	78.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.96	14.7	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:8	32.72	2290	2.33	13.42	102	197	Off Idle	78.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4	14.7	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:8	32.72	2280	2.33	13.43	102	197	Off Idle	78.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.99	14.7	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:8	31.36	2290	2.33	13.43	102	197	Off Idle	78.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.96	14.7	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:57:8	31.36	2290	2.33	13.43	102	197	Off Idle	78.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4	14.71	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:57:8	31.36	2286	2.33	13.42	102	197	Off Idle	78.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.03	14.72	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:9	31.36	2284	2.34	13.4	102	197	Off Idle	78.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.05	14.73	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:9	31.36	2286	2.34	13.4	102	197	Off Idle	78.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.02	14.75	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:9	31.36	2291	2.34	13.41	102	197	Off Idle	78.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:9	31.36	2293	2.34	13.41	102	197	Off Idle	78.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.98	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:9	31.36	2295	2.34	13.42	102	197	Off Idle	78	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.94	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:9	31.36	2294	2.34	13.43	102	197	Off Idle	77.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.93	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:57:9	31.36	2292	2.34	13.43	102	197	Off Idle	77.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.95	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:0	31.36	2292	2.34	13.4	102	197	Off Idle	77.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.99	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:0	31.36	2292	2.34	13.41	102	197	Off Idle	78	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.91	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:0	31.36	2294	2.34	13.41	102	197	Off Idle	78	0	2	132	944 Turbo	0.35	Rich	1	14.6	-3.92	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:0	31.36	2295	2.34	13.42	102	197	Off Idle	78	0	2	132	944 Turbo	0.3	Rich	1	14.6	-3.92	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:0	31.36	2296	2.34	13.41	102	197	Off Idle	77.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-3.89	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:0	31.36	2298	2.34	13.42	102	197	Off Idle	77.8	0	2	132	944 Turbo	0.2	Rich	1	14.6	-3.89	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:1	31.36	2298	2.34	13.42	102	197	Off Idle	77.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.94	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:1	31.36	2297	2.34	13.41	102	197	Off Idle	77.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.94	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:1	31.36	2291	2.34	13.4	102	197	Off Idle	77.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3.94	14.9	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:1	31.36	2291	2.34	13.4	102	197	Off Idle	77.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-3.91	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:1	31.36	2294	2.34	13.4	102	197	Off Idle	77.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.91	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:1	31.36	2297	2.34	13.41	102	197	Off Idle	77.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.86	15	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:58:1	31.36	2297	2.34	13.41	102	197	Off Idle	77.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-3.91	15.06	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:2	31.36	2298	2.34	13.44	102	197	Off Idle	77.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-3.93	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:2	31.36	2307	2.35	13.44	102	197	Off Idle	77.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-3.95	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:2	31.36	2307	2.35	13.43	102	197	Off Idle	77.2	0	2	132	944 Turbo	0.69	Lean	1	14.6	-3.95	14.91	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:58:2	31.36	2306	2.35	13.42	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.94	14.88	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:58:2	31.36	2300	2.35	13.44	102	197	Off Idle	76.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.93	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:58:2	31.36	2300	2.35	13.43	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.95	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:58:3	31.36	2300	2.35	13.41	102	197	Off Idle	77.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.93	14.78	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:58:3	31.36	2299	2.35	13.43	102	197	Off Idle	77.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.94	14.75	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:3	31.36	2301	2.35	13.43	102	197	Off Idle	77.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.97	14.73	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:3	31.36	2304	2.35	13.42	102	197	Off Idle	77.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.94	14.68	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:3	31.36	2312	2.35	13.42	102	197	Off Idle	77.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.94	14.63	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:3	31.36	2311	2.35	13.42	102	197	Off Idle	77.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.94	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:4	31.36	2320	2.35	13.42	102	197	Off Idle	77.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.9	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:4	31.36	2320	2.35	13.43	102	197	Off Idle	77.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.9	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:4	31.36	2328	2.35	13.42	102	197	Off Idle	77.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.92	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:4	31.36	2320	2.35	13.43	102	197	Off Idle	77.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.92	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:4	31.36	2318	2.35	13.44	102	197	Off Idle	77.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.93	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:4	31.36	2310	2.35	13.42	102	197	Off Idle	77.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.92	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:4	31.36	2302	2.35	13.44	102	197	Off Idle	77.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.89	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:5	31.36	2294	2.35	13.43	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.9	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:58:5	31.36	2298	2.35	13.42	102	197	Off Idle	76.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-3.87	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:5	31.36	2311	2.35	13.43	102	197	Off Idle	76.9	0	2	132	944 Turbo	0.27	Rich	1	14.6	-3.85	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:5	31.36	2324	2.35	13.44	102	197	Off Idle	76.9	0	2	132	944 Turbo	0.21	Rich	1	14.6	-3.9	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:5	31.36	2324	2.34	13.43	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.95	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:19:58:5	31.36	2326	2.34	13.41	102	197	Off Idle	76.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.99	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:58:6	31.36	2324	2.34	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.01	14.94	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:19:58:6	31.36	2309	2.34	13.42	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.09	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:6	31.36	2309	2.34	13.41	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.09	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:6	31.36	2298	2.34	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.09	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:6	31.36	2293	2.33	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.15	15.16	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:6	31.36	2296	2.33	13.41	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.19	15.21	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:6	31.36	2301	2.32	13.43	102	197	Off Idle	77.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.22	15.29	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:7	31.36	2310	2.32	13.42	102	197	Off Idle	77.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.29	15.29	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:58:7	31.36	2330	2.31	13.41	102	197	Off Idle	77.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.36	15.27	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:7	31.36	2333	2.31	13.4	102	197	Off Idle	77.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.37	15.22	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:7	31.36	2335	2.3	13.41	102	197	Off Idle	77.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.39	15.17	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:58:7	32.72	2328	2.3	13.42	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.41	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:19:58:7	32.72	2328	2.3	13.42	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.44	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:58:8	32.72	2309	2.29	13.43	102	197	Off Idle	77.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.42	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:58:8	32.72	2310	2.29	13.44	102	197	Off Idle	77.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.45	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:8	32.72	2312	2.29	13.42	102	197	Off Idle	77.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.47	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:8	32.72	2316	2.28	13.43	102	197	Off Idle	77.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-4.47	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:8	32.72	2320	2.28	13.43	102	197	Off Idle	77.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-4.46	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:8	32.72	2321	2.28	13.42	102	197	Off Idle	77.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.53	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:9	32.72	2319	2.28	13.43	102	197	Off Idle	77.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.58	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:9	32.72	2323	2.27	13.43	102	197	Off Idle	77.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.63	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:58:9	32.72	2323	2.27	13.42	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.68	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:58:9	32.72	2319	2.27	13.43	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.73	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:9	32.72	2318	2.26	13.42	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.78	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:9	32.72	2321	2.26	13.42	102	197	Off Idle	76.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.79	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:19:58:9	32.72	2321	2.25	13.42	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.85	15.16	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:19:59:0	32.72	2322	2.25	13.41	102	197	Off Idle	76.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.93	15.22	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:59:0	32.72	2324	2.24	13.4	102	197	Off Idle	76.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.98	15.25	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:19:59:0	32.72	2322	2.24	13.41	102	197	Off Idle	76.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.06	15.26	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:59:0	32.72	2328	2.23	13.41	102	197	Off Idle	76.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.18	15.26	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:59:0	32.72	2320	2.22	13.41	102	197	Off Idle	76.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.28	15.24	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:59:0	32.72	2324	2.21	13.42	102	197	Off Idle	76.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.32	15.22	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:59:1	32.72	2324	2.21	13.42	102	197	Off Idle	76.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.37	15.22	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:59:1	32.72	2312	2.2	13.41	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.41	15.19	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:1	32.72	2319	2.19	13.41	102	197	Off Idle	76	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.48	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:1	32.72	2318	2.18	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.58	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:1	32.72	2316	2.17	13.41	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.61	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:59:1	32.72	2321	2.16	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.7	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:59:1	32.72	2321	2.16	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.7	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:19:59:2	32.72	2314	2.15	13.41	102	197	Off Idle	76	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.82	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:2	32.72	2318	2.14	13.42	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.81	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:2	32.72	2321	2.13	13.43	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.87	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:2	32.72	2321	2.12	13.44	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.92	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:2	32.72	2329	2.12	13.45	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.95	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:2	32.72	2336	2.11	13.44	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:3	32.72	2337	2.1	13.45	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.1	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:3	32.72	2337	2.09	13.44	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.14	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:3	32.72	2333	2.09	13.43	102	197	Off Idle	76.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.21	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:3	32.72	2343	2.08	13.43	102	197	Off Idle	76.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.26	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:3	32.72	2333	2.08	13.43	102	197	Off Idle	76.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.29	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:3	32.72	2330	2.07	13.43	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.33	15.18	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:4	32.72	2330	2.07	13.42	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.36	15.21	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:4	32.72	2332	2.06	13.41	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.39	15.32	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:4	32.72	2332	2.06	13.42	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.36	15.36	1.05	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:4	32.72	2329	2.06	13.42	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.38	15.38	1.05	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:4	32.72	2329	2.06	13.42	102	197	Off Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.39	15.38	1.05	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:4	32.72	2329	2.05	13.43	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.35	15.38	1.05	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:4	32.72	2308	2.05	13.44	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.39	15.37	1.05	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:5	32.72	2315	2.05	13.45	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.43	15.36	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:5	32.72	2319	2.05	13.43	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.41	15.33	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:5	32.72	2323	2.05	13.44	102	197	Off Idle	76.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.41	15.32	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:5	32.72	2321	2.05	13.43	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.44	15.31	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:5	32.72	2320	2.05	13.43	102	197	Off Idle	76.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.43	15.29	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:5	32.72	2324	2.05	13.43	102	197	Off Idle	76	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.41	15.27	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:6	32.72	2326	2.05	13.42	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.44	15.26	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:6	32.72	2326	2.05	13.41	102	197	Off Idle	76	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.43	15.23	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:6	32.72	2329	2.05	13.43	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.43	15.22	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:6	32.72	2331	2.05	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.44	15.19	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:6	32.72	2331	2.05	13.42	102	196	Off Idle	75.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.42	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:19:59:6	32.72	2332	2.05	13.44	102	196	Off Idle	75.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.43	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:6	32.72	2331	2.05	13.43	102	196	Off Idle	75.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.44	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:7	32.72	2330	2.05	13.42	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.41	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:7	32.72	2324	2.05	13.45	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.4	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:7	32.72	2320	2.05	13.43	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.42	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:7	32.72	2320	2.05	13.42	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.41	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:7	32.72	2316	2.05	13.42	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.37	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:7	32.72	2317	2.05	13.43	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.38	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:19:59:8	32.72	2317	2.05	13.42	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.38	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:8	32.72	2322	2.05	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.36	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:8	32.72	2332	2.05	13.42	102	197	Off Idle	76	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.41	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:8	32.72	2343	2.05	13.44	102	197	Off Idle	76	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.45	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:8	32.72	2343	2.05	13.43	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.48	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:8	32.72	2350	2.05	13.43	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.47	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:9	32.72	2354	2.05	13.44	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.51	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:9	32.72	2352	2.05	13.44	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.48	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:9	32.72	2354	2.05	13.43	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.46	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:9	32.72	2339	2.05	13.43	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.45	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:9	32.72	2339	2.05	13.43	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.4	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:9	32.72	2331	2.05	13.44	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.38	14.9	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:19:59:9	32.72	2332	2.06	13.43	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.37	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:0	32.72	2334	2.06	13.44	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.33	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:0	32.72	2336	2.06	13.45	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.33	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:0	32.72	2341	2.06	13.44	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.31	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:00:0	32.72	2344	2.06	13.45	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.25	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:0	32.72	2340	2.07	13.43	102	197	Off Idle	75	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.23	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:0	32.72	2338	2.07	13.42	102	197	Off Idle	75	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.2	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:1	32.72	2335	2.07	13.42	102	197	Off Idle	75	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.18	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:1	32.72	2331	2.08	13.43	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.16	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:1	32.72	2331	2.08	13.41	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.14	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:1	32.72	2333	2.08	13.43	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.13	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:1	32.72	2332	2.09	13.44	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.15	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:1	32.72	2333	2.09	13.42	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.15	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:1	32.72	2337	2.09	13.43	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.12	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:2	32.72	2341	2.1	13.43	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.12	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:2	32.72	2341	2.1	13.42	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.09	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:2	32.72	2344	2.1	13.42	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.08	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:2	32.72	2345	2.1	13.42	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.08	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:2	32.72	2345	2.11	13.42	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.1	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:2	32.72	2354	2.11	13.43	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.04	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:3	32.72	2345	2.11	13.42	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.07	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:3	32.72	2344	2.11	13.41	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.09	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:3	32.72	2339	2.11	13.41	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.07	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:3	32.72	2334	2.12	13.43	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.08	14.87	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:00:3	32.72	2309	2.12	13.42	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.1	14.88	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:00:3	32.72	2316	2.12	13.41	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.06	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:00:4	32.72	2330	2.11	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.02	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:00:4	32.72	2339	2.11	13.41	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.99	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:4	32.72	2339	2.11	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.97	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:4	32.72	2347	2.11	13.43	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.95	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:4	32.72	2352	2.11	13.43	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.96	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:4	32.72	2352	2.11	13.44	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.96	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:4	32.72	2351	2.11	13.44	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:5	32.72	2348	2.11	13.43	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.01	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:5	32.72	2348	2.11	13.44	102	197	Off Idle	76	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.02	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:5	32.72	2340	2.11	13.44	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.03	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:5	32.72	2340	2.11	13.45	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.04	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:5	32.72	2330	2.11	13.46	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.07	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:00:5	32.72	2338	2.11	13.44	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.06	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:6	32.72	2344	2.11	13.44	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.09	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:6	32.72	2344	2.11	13.43	102	197	Off Idle	76.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.11	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:6	32.72	2342	2.11	13.42	102	197	Off Idle	76	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.1	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:6	32.72	2356	2.11	13.43	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.09	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:6	32.72	2345	2.11	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.13	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:6	32.72	2345	2.11	13.42	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.09	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:6	32.72	2346	2.11	13.43	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.06	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:7	32.72	2347	2.11	13.43	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.08	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:7	32.72	2346	2.11	13.44	102	197	Off Idle	75.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.02	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:7	32.72	2344	2.11	13.45	102	197	Off Idle	75.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.98	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:7	32.72	2344	2.11	13.44	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.98	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:7	32.72	2346	2.11	13.44	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.01	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:7	32.72	2346	2.11	13.43	102	197	Off Idle	75.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.01	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:8	32.72	2346	2.11	13.44	102	197	Off Idle	75.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.03	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:8	32.72	2345	2.11	13.44	102	197	Off Idle	75.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.06	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:8	32.72	2345	2.11	13.44	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.05	15.05	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:8	32.72	2348	2.11	13.43	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.02	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:00:8	32.72	2349	2.11	13.44	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.04	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:8	32.72	2350	2.11	13.44	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.05	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:9	32.72	2352	2.11	13.43	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.01	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:9	32.72	2352	2.11	13.42	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.04	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:9	32.72	2348	2.11	13.43	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.01	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:9	32.72	2351	2.11	13.43	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.05	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:9	32.72	2352	2.11	13.42	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.05	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:9	32.72	2350	2.11	13.44	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.04	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:00:9	32.72	2349	2.11	13.44	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.09	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:0	32.72	2349	2.11	13.44	102	197	Off Idle	75	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.09	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:0	32.72	2348	2.11	13.44	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.02	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:0	32.72	2350	2.11	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.03	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:0	32.72	2359	2.11	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.04	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:0	32.72	2358	2.11	13.44	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.04	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:0	32.72	2359	2.11	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.05	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:1	32.72	2365	2.11	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.09	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:1	32.72	2365	2.11	13.42	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.1	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:1	32.72	2360	2.11	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.11	14.73	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:1	32.72	2353	2.11	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.08	14.73	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:1	32.72	2348	2.11	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.1	14.75	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:1	32.72	2348	2.11	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.08	14.78	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:1	32.72	2347	2.11	13.44	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.06	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:2	32.72	2350	2.11	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.07	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:2	32.72	2350	2.11	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.02	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:2	32.72	2349	2.12	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.06	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:2	32.72	2351	2.12	13.41	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.05	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:2	32.72	2350	2.12	13.4	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.04	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:2	32.72	2351	2.12	13.41	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.02	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:3	32.72	2356	2.11	13.41	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.04	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:3	32.72	2356	2.11	13.41	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.04	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:3	32.72	2355	2.11	13.41	102	197	Off Idle	74.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.05	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:3	32.72	2356	2.11	13.42	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.04	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:3	32.72	2352	2.11	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.11	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:3	32.72	2347	2.11	13.43	102	197	Off Idle	74.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.08	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:4	32.72	2346	2.11	13.43	102	197	Off Idle	74.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.1	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:4	32.72	2346	2.11	13.44	102	197	Off Idle	74.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.12	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:4	32.72	2343	2.11	13.43	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.12	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:4	32.72	2347	2.11	13.43	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.06	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:4	32.72	2350	2.11	13.42	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.09	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:4	32.72	2360	2.11	13.42	102	197	Off Idle	75.1	0	2	132	944 Turbo	0.19	Rich	1	14.6	-6.05	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:01:4	32.72	2365	2.11	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.14	Rich	1	14.6	-6.07	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:01:5	32.72	2365	2.11	13.43	102	197	Off Idle	74.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.08	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:01:5	32.72	2366	2.11	13.44	102	197	Off Idle	74.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.09	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:5	32.72	2364	2.11	13.44	102	197	Off Idle	74.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.1	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:5	32.72	2363	2.11	13.43	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.12	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:5	32.72	2360	2.11	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.12	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:5	32.72	2358	2.11	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.08	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:6	32.72	2356	2.11	13.42	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.09	15.08	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:01:6	32.72	2356	2.11	13.42	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.08	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:6	32.72	2352	2.11	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.05	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:6	32.72	2353	2.11	13.42	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.05	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:6	32.72	2354	2.11	13.42	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.07	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:6	32.72	2358	2.11	13.42	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.09	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:6	32.72	2358	2.11	13.42	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.1	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:7	32.72	2362	2.11	13.44	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.12	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:7	32.72	2359	2.11	13.43	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.13	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:7	32.72	2354	2.11	13.44	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.13	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:7	32.72	2356	2.11	13.45	102	196	Off Idle	73.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.1	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:7	32.72	2356	2.11	13.44	102	196	Off Idle	74	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.13	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:7	32.72	2358	2.11	13.43	102	196	Off Idle	74.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.08	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:8	32.72	2363	2.11	13.45	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.09	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:8	32.72	2363	2.11	13.41	102	197	Off Idle	74.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.13	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:8	32.72	2357	2.11	13.42	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.12	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:8	32.72	2352	2.11	13.42	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.11	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:01:8	32.72	2352	2.11	13.41	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.12	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:8	32.72	2354	2.11	13.42	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.1	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:9	32.72	2361	2.11	13.42	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.09	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:9	32.72	2366	2.11	13.43	102	197	Off Idle	74.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.06	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:9	32.72	2366	2.11	13.44	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.1	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:9	32.72	2370	2.11	13.43	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.1	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:9	32.72	2375	2.11	13.44	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.12	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:9	32.72	2375	2.11	13.43	102	197	Off Idle	74.1	0	2	132	944 Turbo	0.17	Rich	1	14.6	-6.12	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:01:9	32.72	2375	2.11	13.43	102	196	Off Idle	74.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.12	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:0	32.72	2369	2.11	13.43	102	196	Off Idle	74.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.13	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:02:0	32.72	2366	2.11	13.42	102	196	Off Idle	74	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.15	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:02:0	32.72	2359	2.12	13.43	102	197	Off Idle	73.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.12	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:02:0	32.72	2353	2.12	13.42	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.11	15	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:02:0	32.72	2353	2.12	13.42	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.1	15.04	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:0	32.72	2354	2.12	13.43	102	196	Off Idle	73.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.04	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:1	32.72	2356	2.12	13.43	102	196	Off Idle	73.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.99	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:1	32.72	2358	2.12	13.43	102	196	Off Idle	73.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.99	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:1	32.72	2363	2.12	13.43	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.01	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:1	32.72	2363	2.12	13.43	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.03	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:1	32.72	2365	2.12	13.42	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.01	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:1	32.72	2362	2.12	13.42	102	196	Off Idle	73.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.97	15.18	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:1	32.72	2361	2.13	13.43	102	196	Off Idle	73.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.95	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:2	32.72	2362	2.13	13.41	102	196	Off Idle	73.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.97	15.14	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:2	32.72	2359	2.13	13.43	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.92	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:2	32.72	2368	2.13	13.44	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.91	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:2	32.72	2368	2.13	13.42	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.98	15.05	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:2	32.72	2370	2.13	13.41	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.93	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:02:2	32.72	2368	2.14	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.88	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:02:3	32.72	2369	2.14	13.42	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.87	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:02:3	32.72	2369	2.14	13.42	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.82	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:3	32.72	2371	2.15	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.76	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:3	32.72	2370	2.15	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.74	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:3	32.72	2370	2.15	13.42	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.71	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:3	32.72	2374	2.16	13.43	102	197	Off Idle	74.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.68	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:02:4	32.72	2379	2.16	13.42	102	197	Off Idle	74	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.67	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:4	32.72	2381	2.16	13.43	102	197	Off Idle	73.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.63	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:4	32.72	2381	2.17	13.43	102	197	Off Idle	73.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.64	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:4	32.72	2376	2.17	13.42	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.61	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:02:4	32.72	2370	2.18	13.43	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.58	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:4	32.72	2368	2.18	13.42	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.5	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:4	32.72	2367	2.18	13.42	102	196	Off Idle	73.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.49	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:5	32.72	2372	2.19	13.43	102	196	Off Idle	73.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.42	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:5	32.72	2370	2.19	13.43	102	196	Off Idle	73.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.39	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:5	32.72	2370	2.2	13.43	102	196	Off Idle	73.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.39	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:5	32.72	2368	2.2	13.42	102	196	Off Idle	73.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.4	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:5	32.72	2368	2.21	13.42	102	196	Off Idle	73.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.39	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:5	32.72	2368	2.21	13.41	102	196	Off Idle	73.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.38	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:6	32.72	2368	2.21	13.42	102	196	Off Idle	73.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.39	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:6	32.72	2366	2.21	13.43	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.34	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:6	32.72	2367	2.21	13.42	102	197	Off Idle	73.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.34	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:6	32.72	2370	2.21	13.41	102	197	Off Idle	73.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.32	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:6	32.72	2372	2.22	13.43	102	196	Off Idle	73.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.3	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:6	32.72	2372	2.22	13.43	102	196	Off Idle	73.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.32	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:6	32.72	2370	2.22	13.42	102	196	Off Idle	73.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.32	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:02:7	32.72	2370	2.22	13.42	102	196	Off Idle	73.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.34	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:7	32.72	2370	2.22	13.42	102	196	Off Idle	73.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.33	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:7	32.72	2369	2.22	13.41	102	196	Off Idle	73.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.31	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:7	32.72	2369	2.22	13.42	102	196	Off Idle	73.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.29	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:7	32.72	2374	2.22	13.42	102	196	Off Idle	73.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.29	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:02:7	32.72	2378	2.23	13.44	102	196	Off Idle	73.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.3	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:02:8	32.72	2382	2.23	13.44	102	196	Off Idle	73.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.31	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:02:8	32.72	2383	2.23	13.45	102	196	Off Idle	73.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.3	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:02:8	32.72	2386	2.23	13.43	102	196	Off Idle	73.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.29	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:02:8	32.72	2389	2.23	13.43	102	196	Off Idle	73.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.3	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:02:8	32.72	2387	2.23	13.42	102	196	Off Idle	73.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.31	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:8	32.72	2386	2.23	13.43	102	196	Off Idle	72.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.3	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:9	32.72	2381	2.23	13.43	102	196	Off Idle	72.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.33	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:9	32.72	2377	2.23	13.45	102	196	Off Idle	73	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.31	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:02:9	32.72	2375	2.23	13.45	102	196	Off Idle	73.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.32	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:02:9	32.72	2377	2.24	13.45	102	197	Off Idle	73.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.29	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:9	32.72	2386	2.24	13.45	102	197	Off Idle	73.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.25	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:9	32.72	2390	2.24	13.45	102	197	Off Idle	73.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.27	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:02:9	32.72	2390	2.24	13.42	102	196	Off Idle	73	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.2	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:0	32.72	2386	2.24	13.44	102	196	Off Idle	73	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.19	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:0	32.72	2382	2.24	13.43	102	196	Off Idle	73	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.2	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:0	32.72	2378	2.24	13.41	102	196	Off Idle	73	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.19	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:0	32.72	2378	2.25	13.41	102	196	Off Idle	73	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.19	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:0	32.72	2375	2.25	13.43	102	197	Off Idle	73	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.21	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:0	32.72	2377	2.25	13.43	102	197	Off Idle	73.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.23	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:1	32.72	2378	2.25	13.42	102	197	Off Idle	73.2	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.19	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:1	32.72	2381	2.25	13.44	102	196	Off Idle	73.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.22	14.74	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:1	32.72	2382	2.25	13.44	102	196	Off Idle	73.2	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.17	14.74	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:1	32.72	2389	2.25	13.43	102	196	Off Idle	73.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.15	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:1	32.72	2389	2.25	13.44	102	197	Off Idle	72.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.14	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:1	32.72	2392	2.25	13.44	102	197	Off Idle	72.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.1	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:1	32.72	2391	2.25	13.44	102	196	Off Idle	72.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.08	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:2	32.72	2387	2.25	13.43	102	196	Off Idle	72.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.09	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:2	32.72	2387	2.25	13.42	102	196	Off Idle	72.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.08	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:2	32.72	2388	2.25	13.43	102	196	Off Idle	72.7	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.12	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:2	32.72	2390	2.25	13.42	102	196	Off Idle	72.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.08	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:2	32.72	2402	2.25	13.43	102	196	Off Idle	72.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.08	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:2	32.72	2392	2.26	13.42	102	196	Off Idle	72.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.08	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:03:3	32.72	2392	2.26	13.42	102	196	Off Idle	72.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.12	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:3	32.72	2381	2.26	13.43	102	196	Off Idle	72.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.09	15.04	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:3	32.72	2390	2.26	13.42	102	196	Off Idle	72.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.11	15.07	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:3	32.72	2361	2.26	13.44	102	196	Off Idle	72.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.1	15.08	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:3	32.72	2378	2.26	13.44	102	196	Off Idle	72.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.09	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:3	32.72	2397	2.26	13.42	102	196	Off Idle	72.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.04	15.06	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:4	32.72	2396	2.26	13.41	102	196	Off Idle	72.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.04	15.03	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:4	32.72	2396	2.26	13.41	102	196	Off Idle	72.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.99	15	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:4	32.72	2412	2.27	13.42	102	196	Off Idle	72.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.93	14.97	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:4	32.72	2394	2.27	13.42	102	196	Off Idle	72.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.87	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:4	32.72	2394	2.27	13.42	102	196	Off Idle	72.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.84	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:03:4	32.72	2395	2.28	13.43	102	196	Off Idle	72	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.81	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:4	32.72	2392	2.28	13.42	102	196	Off Idle	72.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.82	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:5	32.72	2394	2.28	13.41	102	197	Off Idle	72.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.82	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:5	32.72	2398	2.28	13.42	102	197	Off Idle	72.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.77	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:5	32.72	2399	2.29	13.43	102	197	Off Idle	72.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-4.75	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:5	32.72	2399	2.29	13.43	102	196	Off Idle	72.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.75	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:5	32.72	2395	2.29	13.43	102	196	Off Idle	72.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.71	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:5	32.72	2394	2.29	13.43	102	196	Off Idle	72.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.73	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:6	32.72	2395	2.29	13.43	102	196	Off Idle	72.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.74	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:6	32.72	2395	2.3	13.42	102	196	Off Idle	72.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.76	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:6	32.72	2398	2.3	13.43	102	196	Off Idle	72.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.75	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:6	32.72	2400	2.3	13.43	102	197	Off Idle	72.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.76	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:6	32.72	2400	2.3	13.43	102	197	Off Idle	72.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.79	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:6	32.72	2398	2.3	13.43	102	197	Off Idle	72.1	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.78	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:6	32.72	2416	2.31	13.43	102	197	Off Idle	71.9	0	2	132	944 Turbo	0.59	Lean	1	14.6	-4.77	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:7	32.72	2402	2.31	13.42	102	197	Off Idle	72	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.75	15.19	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:7	32.72	2403	2.31	13.42	102	196	Off Idle	72	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.72	15.18	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:7	32.72	2406	2.31	13.43	102	196	Off Idle	72	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.71	15.14	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:7	32.72	2406	2.31	13.43	102	196	Off Idle	71.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.71	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:7	32.72	2398	2.31	13.44	102	196	Off Idle	71.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.7	15.03	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:7	32.72	2406	2.31	13.44	102	196	Off Idle	71.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.69	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:8	32.72	2411	2.31	13.45	102	196	Off Idle	71.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.76	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:8	32.72	2411	2.31	13.43	102	196	Off Idle	71.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.77	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:8	32.72	2410	2.31	13.43	102	196	Off Idle	71.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.75	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:03:8	32.72	2407	2.31	13.44	102	196	Off Idle	71.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.73	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:8	32.72	2402	2.31	13.43	102	196	Off Idle	71.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.71	14.73	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:8	32.72	2401	2.31	13.43	102	196	Off Idle	71.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.66	14.73	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:9	32.72	2406	2.31	13.44	102	196	Off Idle	71.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.65	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:9	32.72	2408	2.31	13.43	102	196	Off Idle	71.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.67	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:9	32.72	2408	2.31	13.44	102	196	Off Idle	71.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.67	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:9	32.72	2411	2.31	13.43	102	196	Off Idle	71.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.67	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:9	32.72	2408	2.31	13.44	102	197	Off Idle	71	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.66	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:9	32.72	2408	2.31	13.42	102	197	Off Idle	71	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.69	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:03:9	32.72	2400	2.31	13.42	102	197	Off Idle	70.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.67	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:0	32.72	2389	2.32	13.42	102	197	Off Idle	70.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.66	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:0	32.72	2393	2.32	13.44	102	197	Off Idle	70.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.65	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:0	32.72	2393	2.32	13.45	102	197	Off Idle	70.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.69	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:0	32.72	2406	2.32	13.47	102	196	Off Idle	70.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.66	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:0	32.72	2409	2.32	13.47	102	196	Off Idle	71	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.68	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:0	32.72	2409	2.32	13.46	102	196	Off Idle	71.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.66	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:1	32.72	2412	2.32	13.46	102	196	Off Idle	71.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.64	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:1	32.72	2411	2.32	13.45	102	196	Off Idle	71.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.62	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:1	32.72	2411	2.32	13.45	102	196	Off Idle	71.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.64	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:1	32.72	2409	2.32	13.44	102	196	Off Idle	71.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.65	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:1	32.72	2405	2.32	13.44	102	196	Off Idle	71.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.61	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:1	32.72	2403	2.32	13.44	102	196	Off Idle	71.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.66	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:1	32.72	2405	2.32	13.43	102	196	Off Idle	71.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.64	14.97	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:04:2	32.72	2399	2.32	13.44	102	196	Off Idle	72.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.61	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:2	32.72	2415	2.32	13.43	102	196	Off Idle	72.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.64	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:2	32.72	2423	2.32	13.43	102	196	Off Idle	72.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.66	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:2	32.72	2423	2.32	13.43	102	196	Off Idle	72.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.67	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:2	32.72	2421	2.32	13.42	102	196	Off Idle	72.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.73	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:2	32.72	2421	2.32	13.41	102	196	Off Idle	72.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.7	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:3	32.72	2416	2.32	13.41	102	196	Off Idle	72	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.72	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:3	32.72	2415	2.32	13.41	102	196	Off Idle	71.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.68	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:3	32.72	2417	2.32	13.43	102	196	Off Idle	71.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.66	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:3	32.72	2418	2.32	13.44	102	196	Off Idle	71.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.67	14.81	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:3	32.72	2422	2.32	13.44	102	196	Off Idle	71.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.68	14.81	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:3	32.72	2425	2.32	13.44	102	196	Off Idle	71.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.67	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:4	32.72	2426	2.32	13.44	102	196	Off Idle	71	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.67	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:4	32.72	2425	2.32	13.43	102	196	Off Idle	70.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.67	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:4	32.72	2425	2.32	13.44	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.66	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:4	32.72	2414	2.32	13.43	102	196	Off Idle	70.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.65	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:4	32.72	2429	2.32	13.43	102	196	Off Idle	70.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.65	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:4	32.72	2429	2.33	13.43	102	196	Off Idle	70	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.66	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:5	32.72	2408	2.33	13.43	102	196	Off Idle	70.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.66	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:5	32.72	2415	2.33	13.43	102	196	Off Idle	70.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.66	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:5	32.72	2415	2.33	13.45	102	196	Off Idle	70	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.64	15.01	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:5	32.72	2422	2.33	13.44	102	196	Off Idle	70	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.64	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:5	32.72	2432	2.33	13.46	102	196	Off Idle	70	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.62	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:5	32.72	2434	2.33	13.44	102	197	Off Idle	70	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.64	14.98	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:6	32.72	2431	2.33	13.43	102	197	Off Idle	70.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.64	14.98	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:6	32.72	2422	2.33	13.41	102	197	Off Idle	70	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.67	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:04:6	32.72	2419	2.33	13.42	102	196	Off Idle	70	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.65	14.94	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:04:6	32.72	2419	2.33	13.43	102	196	Off Idle	70	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.63	14.89	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:04:6	32.72	2410	2.33	13.42	102	196	Off Idle	70.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.63	14.87	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:04:6	32.72	2418	2.33	13.43	102	196	Off Idle	70.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.61	14.83	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:04:6	32.72	2420	2.33	13.43	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.62	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:04:7	32.72	2427	2.33	13.43	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.62	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:04:7	32.72	2438	2.33	13.43	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.65	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:7	32.72	2437	2.33	13.44	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.65	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:7	32.72	2437	2.33	13.43	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.66	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:7	32.72	2432	2.33	13.42	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.66	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:7	32.72	2425	2.33	13.42	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.69	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:8	32.72	2422	2.33	13.43	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.66	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:8	32.72	2419	2.33	13.42	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.68	15.1	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:8	32.72	2422	2.33	13.44	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.66	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:8	32.72	2425	2.33	13.42	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.63	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:8	32.72	2431	2.33	13.42	102	196	Off Idle	70.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.62	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:8	32.72	2437	2.33	13.41	102	196	Off Idle	70.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.64	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:9	32.72	2434	2.33	13.43	102	196	Off Idle	70.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.65	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:9	32.72	2434	2.33	13.43	102	196	Off Idle	70	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.66	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:9	32.72	2439	2.33	13.42	102	196	Off Idle	70	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.68	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:9	32.72	2431	2.33	13.43	102	196	Off Idle	70	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.65	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:9	32.72	2424	2.33	13.44	102	196	Off Idle	70	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.63	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:9	32.72	2424	2.33	13.42	102	196	Off Idle	70	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.65	14.73	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:04:9	32.72	2426	2.33	13.42	102	196	Off Idle	70	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.62	14.72	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:0	32.72	2426	2.33	13.42	102	197	Off Idle	70.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.6	14.72	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:0	32.72	2436	2.33	13.42	102	197	Off Idle	70.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.63	14.75	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:0	32.72	2446	2.33	13.42	102	197	Off Idle	70.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.65	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:0	32.72	2463	2.33	13.42	102	196	Off Idle	70.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.62	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:05:0	32.72	2454	2.34	13.43	102	196	Off Idle	70.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-4.61	14.81	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:0	32.72	2442	2.34	13.42	102	196	Off Idle	70.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.62	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:1	32.72	2437	2.34	13.44	102	196	Off Idle	70	0	2	132	944 Turbo	0.3	Rich	1	14.6	-4.61	14.84	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:05:1	32.72	2436	2.34	13.43	102	196	Off Idle	69.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-4.56	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:05:1	32.72	2414	2.34	13.42	102	196	Off Idle	69.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.53	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:1	32.72	2424	2.34	13.42	102	196	Off Idle	69.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.49	14.92	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:1	32.72	2433	2.35	13.43	102	196	Off Idle	69.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.46	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:1	32.72	2433	2.35	13.42	102	196	Off Idle	69.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.45	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:1	32.72	2436	2.35	13.42	102	196	Off Idle	69.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.41	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:2	32.72	2436	2.35	13.43	102	196	Off Idle	69.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.43	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:2	32.72	2444	2.36	13.42	102	196	Off Idle	69.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.35	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:2	32.72	2452	2.36	13.43	102	196	Off Idle	69.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.31	15.06	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:2	32.72	2448	2.37	13.43	102	196	Off Idle	69.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.25	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:05:2	32.72	2448	2.37	13.44	102	196	Off Idle	69.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.17	15.03	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:05:2	32.72	2441	2.37	13.42	102	196	Off Idle	69.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.17	14.99	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:05:3	32.72	2436	2.38	13.43	102	196	Off Idle	69.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.14	14.93	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:05:3	32.72	2433	2.38	13.42	102	196	Off Idle	69.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.14	14.9	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:05:3	32.72	2432	2.39	13.43	102	196	Off Idle	70	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.09	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:05:3	32.72	2430	2.39	13.42	102	196	Off Idle	70.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.07	14.81	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:05:3	32.72	2445	2.4	13.43	102	196	Off Idle	70.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:05:3	32.72	2445	2.41	13.44	102	196	Off Idle	69.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.95	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:4	32.72	2444	2.41	13.42	102	196	Off Idle	69.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3.87	14.8	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:4	32.72	2454	2.42	13.43	102	196	Off Idle	69.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.84	14.81	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:4	32.72	2452	2.42	13.44	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.83	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:4	32.72	2452	2.43	13.44	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.83	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:4	32.72	2450	2.43	13.44	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.81	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:4	32.72	2450	2.44	13.43	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.77	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:4	32.72	2443	2.45	13.41	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.69	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:5	32.72	2444	2.45	13.42	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-3.71	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:5	32.72	2447	2.45	13.4	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.7	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:5	32.72	2447	2.46	13.41	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-3.67	14.99	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:5	32.72	2451	2.46	13.42	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-3.71	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:5	32.72	2451	2.46	13.41	102	196	Off Idle	69.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.7	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:5	32.72	2451	2.46	13.43	102	196	Off Idle	69.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-3.7	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:6	32.72	2460	2.47	13.43	102	196	Off Idle	69.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.71	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:6	32.72	2464	2.47	13.42	102	196	Off Idle	69.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.64	14.9	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:6	32.72	2482	2.48	13.41	102	196	Off Idle	69.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.6	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:6	32.72	2472	2.48	13.43	102	196	Off Idle	69.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.54	14.78	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:6	32.72	2458	2.48	13.42	102	196	Off Idle	69.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.53	14.7	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:05:6	32.72	2456	2.48	13.42	102	196	Off Idle	69.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.49	14.6	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:6	32.72	2456	2.49	13.41	102	196	Off Idle	69.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.49	14.52	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:7	32.72	2437	2.49	13.41	102	196	Off Idle	69	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.43	14.46	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:7	32.72	2459	2.49	13.4	102	196	Off Idle	68.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.41	14.41	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:7	32.72	2459	2.49	13.4	102	196	Off Idle	68.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.37	14.39	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:7	32.72	2465	2.5	13.41	102	196	Off Idle	68.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.33	14.37	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:7	32.72	2467	2.5	13.42	102	196	Off Idle	68.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.27	14.38	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:7	32.72	2465	2.5	13.44	102	196	Off Idle	68.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.27	14.39	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:8	32.72	2464	2.51	13.44	102	196	Off Idle	68.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.21	14.4	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:8	32.72	2460	2.51	13.43	102	196	Off Idle	68.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.24	14.42	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:8	32.72	2461	2.51	13.43	102	196	Off Idle	68.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.2	14.44	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:8	32.72	2451	2.52	13.43	102	196	Off Idle	68	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.19	14.46	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:8	32.72	2461	2.52	13.44	102	196	Off Idle	68	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.16	14.48	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:8	32.72	2468	2.52	13.44	102	196	Off Idle	68	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.19	14.49	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:9	32.72	2468	2.53	13.44	102	196	Off Idle	68.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.14	14.49	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:9	32.72	2475	2.53	13.43	102	196	Off Idle	68.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.09	14.48	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:9	32.72	2488	2.53	13.43	102	196	Off Idle	68.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.08	14.49	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:9	32.72	2478	2.53	13.42	102	196	Off Idle	68.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.08	14.48	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:9	32.72	2478	2.54	13.43	102	196	Off Idle	68.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.09	14.49	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:9	32.72	2476	2.54	13.42	102	196	Off Idle	68	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.11	14.47	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:05:9	32.72	2474	2.54	13.43	102	196	Off Idle	68	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.13	14.45	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:0	32.72	2473	2.54	13.42	102	196	Off Idle	68	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.1	14.44	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:0	32.72	2472	2.54	13.42	102	196	Off Idle	68	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.1	14.43	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:06:0	32.72	2471	2.54	13.42	102	196	Off Idle	68	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.07	14.43	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:0	32.72	2477	2.54	13.41	102	196	Off Idle	68	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.05	14.44	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:0	32.72	2484	2.55	13.41	102	196	Off Idle	68	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.03	14.44	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:0	32.72	2484	2.55	13.4	102	196	Off Idle	68	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.04	14.44	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:1	32.72	2487	2.55	13.42	102	196	Off Idle	67.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3	14.45	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:1	32.72	2487	2.55	13.42	102	196	Off Idle	67.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.01	14.44	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:1	32.72	2481	2.55	13.42	102	196	Off Idle	67.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.03	14.44	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:1	32.72	2480	2.55	13.44	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3	14.44	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:1	32.72	2469	2.55	13.44	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.03	14.44	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:1	32.72	2469	2.55	13.42	102	196	Off Idle	67.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.04	14.45	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:1	32.72	2471	2.55	13.42	102	196	Off Idle	67.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.04	14.45	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:2	32.72	2482	2.55	13.42	102	196	Off Idle	67.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3	14.48	0.99	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:2	32.72	2486	2.55	13.42	102	196	Off Idle	67.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.03	14.5	0.99	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:2	32.72	2494	2.55	13.42	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.03	14.52	0.99	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:2	32.72	2492	2.55	13.44	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.05	14.55	0.99	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:2	32.72	2493	2.55	13.42	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.1	14.58	0.99	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:06:2	32.72	2493	2.55	13.41	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.11	14.6	0.99	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:06:3	32.72	2491	2.55	13.41	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.11	14.62	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:3	32.72	2491	2.55	13.41	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-3.08	14.62	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:3	32.72	2485	2.55	13.41	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.06	14.65	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:3	32.72	2487	2.55	13.42	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.02	14.66	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:3	32.72	2494	2.55	13.41	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3	14.67	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:3	32.72	2496	2.55	13.41	102	196	Off Idle	67.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.01	14.68	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:4	32.72	2502	2.55	13.41	102	196	Off Idle	67.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.01	14.7	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:4	32.72	2506	2.55	13.42	102	196	Off Idle	67	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.04	14.71	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:06:4	32.72	2504	2.56	13.41	102	196	Off Idle	66.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.1	14.74	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:06:4	32.72	2504	2.56	13.42	102	196	Off Idle	66.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.09	14.75	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:4	32.72	2494	2.56	13.42	102	196	Off Idle	66.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-3.1	14.79	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:4	32.72	2492	2.56	13.41	102	196	Off Idle	66.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.03	14.79	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:4	32.72	2492	2.56	13.41	102	196	Off Idle	66.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-3	14.79	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:5	32.72	2495	2.56	13.44	102	196	Off Idle	66.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.01	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:5	32.72	2500	2.56	13.42	102	196	Off Idle	66.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3	14.81	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:5	32.72	2502	2.56	13.43	102	196	Off Idle	66.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-2.98	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:5	32.72	2502	2.56	13.44	102	196	Off Idle	66.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.01	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:5	32.72	2500	2.56	13.42	102	196	Off Idle	66.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-2.99	14.85	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:5	32.72	2498	2.56	13.42	102	196	Off Idle	66.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-2.94	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:6	32.72	2500	2.56	13.42	102	196	Off Idle	66.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-2.95	14.93	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:6	32.72	2500	2.56	13.41	102	196	Off Idle	66.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.95	14.98	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:6	32.72	2500	2.56	13.42	102	196	Off Idle	66.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-2.94	15.01	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:6	32.72	2507	2.57	13.43	102	196	Off Idle	66.6	0	2	132	944 Turbo	0.67	Lean	1	14.6	-2.93	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:6	32.72	2507	2.57	13.44	102	196	Off Idle	66.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.99	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:6	32.72	2505	2.57	13.42	102	196	Off Idle	66.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.98	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:6	32.72	2508	2.57	13.42	102	196	Off Idle	66.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.94	14.97	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:7	32.72	2508	2.57	13.42	102	196	Off Idle	66.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.89	14.93	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:7	32.72	2509	2.57	13.42	102	196	Off Idle	66.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.84	14.9	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:7	32.72	2511	2.57	13.42	102	196	Off Idle	66.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.83	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:7	32.72	2511	2.58	13.43	102	196	Off Idle	66.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.83	14.78	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:7	32.72	2511	2.58	13.43	102	196	Off Idle	66	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.81	14.75	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:7	32.72	2510	2.58	13.44	102	196	Off Idle	66	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.81	14.73	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:8	32.72	2508	2.58	13.43	102	196	Off Idle	66	0	2	132	944 Turbo	0.61	Rich	1	14.6	-2.81	14.73	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:06:8	32.72	2506	2.58	13.42	102	196	Off Idle	65.8	0	2	132	944 Turbo	0.54	Lean	1	14.6	-2.79	14.77	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:8	32.72	2507	2.58	13.42	102	196	Off Idle	65.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-2.79	14.79	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:8	32.72	2512	2.59	13.43	102	196	Off Idle	65.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-2.74	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:8	32.72	2519	2.59	13.41	102	196	Off Idle	65.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-2.74	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:8	32.72	2519	2.59	13.41	102	196	Off Idle	65.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.76	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:9	32.72	2521	2.59	13.41	102	196	Off Idle	65.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.76	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:06:9	32.72	2518	2.59	13.41	102	196	Off Idle	65.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.75	14.83	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:9	32.72	2518	2.59	13.42	102	196	Off Idle	65.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-2.8	14.85	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:06:9	32.72	2517	2.6	13.42	102	196	Off Idle	65.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.82	14.88	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:9	32.72	2515	2.6	13.42	102	196	Off Idle	65.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-2.76	14.92	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:9	32.72	2499	2.6	13.41	102	196	Off Idle	65.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.76	14.93	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:06:9	32.72	2508	2.6	13.42	102	196	Off Idle	65.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.78	14.96	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:0	32.72	2518	2.6	13.41	102	196	Off Idle	65.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.76	14.97	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:0	32.72	2520	2.6	13.4	102	196	Off Idle	65	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.76	14.99	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:0	32.72	2522	2.6	13.4	102	196	Off Idle	65	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.71	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:0	32.72	2529	2.6	13.4	102	196	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.73	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:0	32.72	2532	2.6	13.42	102	196	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.74	14.96	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:0	32.72	2533	2.6	13.41	102	196	Off Idle	64.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.72	14.94	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:1	32.72	2532	2.6	13.41	102	196	Off Idle	64.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.69	14.92	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:1	32.72	2536	2.6	13.42	102	196	Off Idle	64.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.67	14.82	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:1	32.72	2536	2.6	13.43	102	196	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.7	14.81	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:1	32.72	2524	2.6	13.43	102	196	Off Idle	65.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.68	14.79	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:1	32.72	2524	2.6	13.43	102	196	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.67	14.8	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:1	32.72	2526	2.61	13.43	102	196	Off Idle	64.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.66	14.81	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:1	32.72	2519	2.61	13.43	102	196	Off Idle	64.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.62	14.8	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:2	32.72	2534	2.61	13.44	102	196	Off Idle	64.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.65	14.82	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:2	32.72	2534	2.61	13.43	102	196	Off Idle	64.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.63	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:07:2	32.72	2534	2.61	13.44	102	196	Off Idle	64.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.61	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:07:2	32.72	2534	2.61	13.44	102	196	Off Idle	64.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.62	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:07:2	32.72	2529	2.61	13.45	102	196	Off Idle	64.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.69	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:07:2	32.72	2529	2.61	13.43	102	196	Off Idle	64.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.65	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:3	32.72	2530	2.61	13.43	102	196	Off Idle	64.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.62	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:3	32.72	2529	2.61	13.44	102	196	Off Idle	64.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.62	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:07:3	32.72	2529	2.62	13.43	102	196	Off Idle	64.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-2.64	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:3	32.72	2538	2.62	13.44	102	196	Off Idle	64.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-2.6	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:3	32.72	2544	2.62	13.43	102	196	Off Idle	64.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-2.56	14.83	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:3	32.72	2550	2.62	13.43	102	196	Off Idle	64.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-2.5	14.81	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:4	32.72	2560	2.62	13.42	102	196	Off Idle	64.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-2.47	14.83	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:4	32.72	2553	2.63	13.41	102	196	Off Idle	64.1	0	2	132	944 Turbo	0.2	Rich	1	14.6	-2.43	14.86	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:4	32.72	2549	2.63	13.41	102	196	Off Idle	64	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.4	14.89	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:4	32.72	2548	2.63	13.4	102	196	Off Idle	64	0	2	132	944 Turbo	0.15	Lean	1	14.6	-2.41	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:4	32.72	2542	2.63	13.41	102	196	Off Idle	64	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.38	14.99	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:4	32.72	2539	2.64	13.42	102	196	Off Idle	64	0	2	132	944 Turbo	0.22	Lean	1	14.6	-2.33	15.02	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:4	32.72	2539	2.64	13.43	102	196	Off Idle	64	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.3	15.07	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:5	32.72	2539	2.64	13.43	102	196	Off Idle	64	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.28	15.13	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:5	32.72	2544	2.64	13.44	102	196	Off Idle	64.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-2.26	15.2	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:5	32.72	2552	2.65	13.43	102	196	Off Idle	64.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-2.26	15.24	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:5	32.72	2554	2.65	13.42	102	196	Off Idle	64	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.25	15.22	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:5	32.72	2554	2.65	13.42	102	196	Off Idle	63.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-2.27	15.2	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:5	32.72	2550	2.66	13.43	102	196	Off Idle	63.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.22	15.15	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:6	32.72	2544	2.66	13.44	102	196	Off Idle	63.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.23	15.13	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:07:6	32.72	2544	2.66	13.44	102	196	Off Idle	63.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.2	15.08	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:6	32.72	2550	2.67	13.44	102	196	Off Idle	63.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.17	15.04	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:6	32.72	2550	2.67	13.42	102	196	Off Idle	63.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.18	14.99	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:6	32.72	2545	2.67	13.43	102	196	Off Idle	63.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.12	14.93	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:07:6	32.72	2552	2.67	13.42	102	196	Off Idle	63.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-2.12	14.88	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:07:6	32.72	2562	2.68	13.41	102	196	Off Idle	63.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-2.06	14.86	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:07:7	32.72	2564	2.68	13.41	102	196	Off Idle	63.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-2.06	14.85	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:07:7	32.72	2572	2.68	13.41	102	196	Off Idle	63.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.1	14.85	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:07:7	32.72	2572	2.68	13.42	102	196	Off Idle	63.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-2.05	14.84	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:07:7	32.72	2581	2.68	13.42	102	196	Off Idle	63.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.02	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:7	32.72	2564	2.68	13.43	102	196	Off Idle	63.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-2.06	14.85	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:7	32.72	2558	2.69	13.44	102	196	Off Idle	63.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.06	14.9	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:8	32.72	2558	2.69	13.46	102	196	Off Idle	62.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-2.1	14.94	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:8	32.72	2558	2.69	13.45	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.06	14.95	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:8	32.72	2564	2.69	13.45	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.03	14.94	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:07:8	32.72	2566	2.69	13.45	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.99	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:8	32.72	2568	2.69	13.44	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.99	14.92	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:8	32.72	2570	2.69	13.45	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.98	14.9	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:9	32.72	2571	2.69	13.43	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.03	14.86	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:9	32.72	2568	2.69	13.44	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.98	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:07:9	32.72	2563	2.69	13.45	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.98	14.79	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:07:9	32.72	2570	2.69	13.45	102	196	Off Idle	62.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.02	14.73	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:07:9	32.72	2570	2.7	13.45	102	196	Off Idle	62.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.04	14.7	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:9	32.72	2573	2.7	13.44	102	196	Off Idle	62.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.96	14.68	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:07:9	32.72	2572	2.7	13.42	102	196	Off Idle	62.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.98	14.68	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:0	32.72	2572	2.7	13.42	102	196	Off Idle	62.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.92	14.69	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:0	32.72	2567	2.7	13.43	102	196	Off Idle	62.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.92	14.72	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:0	32.72	2572	2.7	13.42	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.92	14.75	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:0	32.72	2577	2.7	13.43	102	196	Off Idle	62.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.96	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:0	32.72	2582	2.7	13.44	102	196	Off Idle	62.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.98	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:0	32.72	2582	2.7	13.42	102	196	Off Idle	62.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.95	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:1	32.72	2600	2.7	13.41	102	196	Off Idle	62.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.99	14.83	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:1	32.72	2600	2.7	13.43	102	196	Off Idle	62.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2	14.85	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:1	32.72	2579	2.7	13.41	102	196	Off Idle	62.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1.98	14.86	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:1	32.72	2582	2.7	13.43	102	196	Off Idle	61.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-1.97	14.86	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:1	32.72	2582	2.7	13.43	102	196	Off Idle	61.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.98	14.86	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:1	32.72	2582	2.7	13.43	102	196	Off Idle	61.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-1.95	14.85	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:1	32.72	2584	2.7	13.43	102	196	Off Idle	61.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-1.93	14.85	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:2	32.72	2586	2.7	13.43	102	196	Off Idle	61.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-1.96	14.85	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:2	32.72	2584	2.7	13.41	102	196	Off Idle	61.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-1.97	14.85	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:2	32.72	2582	2.7	13.43	102	196	Off Idle	61.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.96	14.85	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:2	32.72	2591	2.7	13.42	102	196	Off Idle	61.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.97	14.85	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:2	32.72	2593	2.7	13.42	102	196	Off Idle	61.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-1.97	14.85	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:2	32.72	2604	2.7	13.41	102	196	Off Idle	61.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-1.94	14.87	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:3	32.72	2614	2.7	13.42	102	196	Off Idle	61.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-1.96	14.91	1.02	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:3	32.72	2614	2.7	13.41	102	196	Off Idle	61.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-2.02	14.92	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:3	32.72	2611	2.7	13.42	102	196	Off Idle	61.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-2.01	14.96	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:3	32.72	2595	2.7	13.42	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-2.03	15	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:3	32.72	2595	2.7	13.43	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-2.06	15.03	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:3	32.72	2588	2.7	13.43	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-2.08	15.1	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:4	32.72	2588	2.7	13.44	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.06	15.13	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:4	32.72	2586	2.7	13.42	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.05	15.12	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:4	32.72	2586	2.7	13.42	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2	15.09	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:4	32.72	2593	2.7	13.41	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.03	15.06	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:4	32.72	2597	2.7	13.41	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.02	14.99	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:4	32.72	2599	2.7	13.4	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.99	14.93	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:4	32.72	2600	2.7	13.41	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.03	14.89	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:5	32.72	2599	2.7	13.42	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.04	14.87	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:5	32.72	2597	2.7	13.42	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.62	Lean	1	14.6	-2.03	14.77	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:5	32.72	2595	2.7	13.43	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.06	14.74	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:5	32.72	2593	2.7	13.43	102	196	Off Idle	61.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-2.05	14.74	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:5	32.72	2596	2.7	13.43	102	196	Off Idle	61.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-1.99	14.75	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:5	32.72	2602	2.7	13.42	102	196	Off Idle	61.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.01	14.75	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:6	32.72	2603	2.7	13.42	102	196	Off Idle	61.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.01	14.77	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:6	32.72	2611	2.71	13.45	102	196	Off Idle	60.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.03	14.78	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:6	32.72	2611	2.71	13.44	102	196	Off Idle	60.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-2.03	14.84	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:6	32.72	2612	2.71	13.45	102	196	Off Idle	60.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-2.03	14.87	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:6	32.72	2609	2.71	13.43	102	196	Off Idle	60.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2	14.91	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:6	32.72	2610	2.71	13.43	102	196	Off Idle	60.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-2	14.95	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:6	32.72	2610	2.71	13.43	102	196	Off Idle	60.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-2.01	14.97	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:7	32.72	2608	2.71	13.44	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-2.05	15.05	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:7	32.72	2606	2.71	13.43	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-2.03	15.09	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:7	32.72	2604	2.71	13.43	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-2	15.1	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:08:7	32.72	2602	2.71	13.44	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-1.99	15.12	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:7	32.72	2607	2.71	13.44	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.01	15.09	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:7	32.72	2609	2.71	13.42	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-1.98	15.05	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:8	32.72	2614	2.71	13.43	102	196	Off Idle	59.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-1.95	15.02	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:8	32.72	2620	2.71	13.44	102	196	Off Idle	59.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.99	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:8	32.72	2621	2.71	13.44	102	196	Off Idle	59.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.96	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:08:8	32.72	2622	2.71	13.42	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1.91	14.88	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:8	32.72	2622	2.71	13.44	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-1.97	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:8	32.72	2613	2.71	13.43	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-1.97	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:08:9	32.72	2612	2.71	13.42	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.95	14.79	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:08:9	32.72	2606	2.71	13.43	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-2.03	14.8	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:9	32.72	2605	2.71	13.44	102	196	Off Idle	60.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-2.01	14.79	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:9	32.72	2607	2.72	13.44	102	196	Off Idle	60.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-1.98	14.81	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:9	32.72	2615	2.72	13.43	102	196	Off Idle	60.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-1.96	14.84	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:9	32.72	2614	2.72	13.44	102	196	Off Idle	60.1	0	2	132	944 Turbo	0.18	Rich	1	14.6	-1.99	14.85	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:08:9	32.72	2618	2.72	13.43	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-1.96	14.9	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:09:0	32.72	2620	2.72	13.42	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-1.95	14.93	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:20:09:0	32.72	2624	2.72	13.44	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.96	14.96	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:0	32.72	2621	2.71	13.44	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-1.98	14.98	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:0	32.72	2619	2.71	13.43	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-1.98	15.02	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:0	32.72	2616	2.71	13.43	102	196	Off Idle	59.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.05	15.14	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:0	32.72	2621	2.71	13.43	102	196	Off Idle	59.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-2.03	15.15	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:1	32.72	2622	2.71	13.44	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.05	15.14	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:1	32.72	2622	2.71	13.44	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-2.11	15.11	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:1	32.72	2624	2.71	13.45	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.14	15.03	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:1	32.72	2627	2.71	13.45	102	196	Off Idle	59.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.15	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:1	32.72	2629	2.71	13.45	102	196	Off Idle	59.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.16	14.97	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:1	32.72	2629	2.71	13.43	102	196	Off Idle	59.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.2	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:1	32.72	2628	2.71	13.45	102	196	Off Idle	59.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.27	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:2	32.72	2630	2.7	13.44	102	196	Off Idle	59.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.24	14.81	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:2	32.72	2631	2.7	13.44	102	196	Off Idle	59.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.2	14.77	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:2	32.72	2624	2.7	13.45	102	196	Off Idle	59	0	2	132	944 Turbo	0.59	Rich	1	14.6	-2.24	14.74	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:2	32.72	2636	2.7	13.46	102	196	Off Idle	59	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.26	14.75	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:2	32.72	2636	2.7	13.46	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-2.26	14.75	1	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:2	32.72	2634	2.7	13.44	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-2.23	14.77	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:3	32.72	2629	2.7	13.46	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.27	14.78	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:3	32.72	2629	2.7	13.45	102	196	Off Idle	59	0	2	132	944 Turbo	0.3	Lean	1	14.6	-2.23	14.79	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:20:09:3	32.72	2640	2.7	13.45	102	196	Off Idle	59	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.22	14.85	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:09:3	32.72	2634	2.7	13.45	102	196	Off Idle	59	0	2	132	944 Turbo	0.22	Lean	1	14.6	-2.24	14.86	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:09:3	32.72	2634	2.7	13.46	102	196	Off Idle	59	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.25	14.89	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:20:09:3	32.72	2634	2.7	13.46	102	196	Off Idle	59	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.27	14.91	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:4	32.72	2633	2.7	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.33	Lean	1	14.6	-2.3	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:4	32.72	2631	2.7	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.39	Lean	1	14.6	-2.32	14.99	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:4	32.72	2630	2.69	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.34	15.04	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:4	32.72	2627	2.69	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.51	Rich	1	14.6	-2.35	15.06	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:4	32.72	2625	2.69	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.37	15.07	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:20:09:4	32.72	2627	2.69	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.46	15.05	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:20:09:4	32.72	2628	2.69	13.42	102	196	Off Idle	59	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.46	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:5	32.72	2632	2.68	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.49	14.99	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:5	32.72	2630	2.68	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.52	14.94	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:5	32.72	2628	2.68	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.52	14.9	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:5	32.72	2630	2.68	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.57	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:5	32.72	2629	2.67	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.6	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:5	32.72	2632	2.67	13.45	102	196	Off Idle	59	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.72	14.77	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:6	32.72	2634	2.66	13.42	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.71	14.75	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:6	32.72	2638	2.66	13.42	102	196	Off Idle	58.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.76	14.75	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:6	32.72	2645	2.66	13.43	102	196	Off Idle	58.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.82	14.77	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:6	32.72	2654	2.65	13.45	102	196	Off Idle	58.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.85	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:09:6	32.72	2641	2.65	13.45	102	196	Off Idle	58.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-2.92	14.79	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:6	32.72	2639	2.65	13.47	102	196	Off Idle	58.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-2.91	14.74	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:6	32.72	2640	2.64	13.46	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-2.91	14.74	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:7	32.72	2640	2.64	13.46	102	196	Off Idle	58.2	0	2	132	944 Turbo	0.23	Rich	1	14.6	-2.94	14.77	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:7	32.72	2643	2.64	13.45	102	196	Off Idle	58.2	0	2	132	944 Turbo	0.18	Rich	1	14.6	-2.98	14.81	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:7	32.72	2644	2.63	13.45	102	196	Off Idle	58.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.98	14.85	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:7	32.72	2645	2.63	13.45	102	196	Off Idle	58.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.04	14.9	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:7	32.72	2646	2.63	13.45	102	196	Off Idle	58.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.03	14.92	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:7	32.72	2648	2.62	13.45	102	196	Off Idle	58	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.06	14.97	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:8	32.72	2650	2.62	13.45	102	196	Off Idle	57.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.08	15.01	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:8	32.72	2643	2.62	13.44	102	196	Off Idle	57.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.04	15.05	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:8	32.72	2643	2.62	13.44	102	196	Off Idle	58	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.06	15.18	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:8	32.72	2639	2.61	13.44	102	196	Off Idle	58	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.1	15.24	1.04	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:8	32.72	2639	2.61	13.43	102	196	Off Idle	58	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.1	15.25	1.04	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:8	32.72	2636	2.61	13.42	102	196	Off Idle	58	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.16	15.25	1.04	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:9	32.72	2635	2.61	13.43	102	196	Off Idle	58	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.24	15.22	1.04	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:9	32.72	2645	2.61	13.42	102	196	Off Idle	58.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.22	15.19	1.03	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:9	32.72	2636	2.61	13.43	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.22	15.18	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:9	32.72	2638	2.6	13.44	102	196	Off Idle	58.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.22	15.16	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:9	32.72	2643	2.6	13.44	102	196	Off Idle	58.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.21	15.13	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:09:9	32.72	2638	2.6	13.45	102	196	Off Idle	58.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.28	15.07	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:09:9	32.72	2638	2.6	13.43	102	196	Off Idle	58.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.3	15.05	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:0	32.72	2636	2.6	13.43	102	196	Off Idle	58.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.3	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:0	32.72	2629	2.6	13.44	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.34	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:0	32.72	2631	2.6	13.43	102	196	Off Idle	58.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-3.34	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:0	32.72	2630	2.59	13.42	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.19	Rich	1	14.6	-3.29	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:0	32.72	2634	2.59	13.41	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.25	Rich	1	14.6	-3.3	15.05	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:0	32.72	2634	2.59	13.42	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-3.24	15.05	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:1	32.72	2637	2.59	13.43	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-3.27	15.03	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:1	32.72	2637	2.59	13.42	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.26	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:1	32.72	2636	2.59	13.43	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-3.3	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:1	32.72	2634	2.59	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.33	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:1	32.72	2634	2.59	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.38	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:1	32.72	2635	2.59	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.32	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:1	32.72	2655	2.59	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.31	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:2	32.72	2643	2.59	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.59	Lean	1	14.6	-3.31	15.02	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:2	32.72	2643	2.59	13.45	102	196	Off Idle	59	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.36	15.01	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:2	32.72	2643	2.58	13.44	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.29	15.01	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:2	32.72	2625	2.58	13.44	102	196	Off Idle	58.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.34	15.01	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:2	32.72	2641	2.58	13.44	102	196	Off Idle	58.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.34	14.99	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:2	32.72	2635	2.58	13.42	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.39	14.93	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:3	32.72	2635	2.58	13.42	102	196	Off Idle	58.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.41	14.92	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:3	32.72	2633	2.58	13.44	102	196	Off Idle	58.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.44	14.92	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:3	32.72	2632	2.59	13.42	102	196	Off Idle	58.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.45	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:3	32.72	2632	2.59	13.43	102	196	Off Idle	58.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.41	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:3	32.72	2629	2.59	13.44	102	196	Off Idle	58.1	0	2	132	944 Turbo	0.24	Rich	1	14.6	-3.4	15.03	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:10:3	32.72	2629	2.59	13.45	102	196	Off Idle	58.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-3.41	15.04	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:10:4	32.72	2636	2.59	13.43	102	196	Off Idle	58.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-3.4	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:4	32.72	2622	2.59	13.44	102	196	Off Idle	58.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.38	15.1	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:4	32.72	2620	2.59	13.45	102	196	Off Idle	58.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-3.41	15.17	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:4	32.72	2620	2.59	13.45	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-3.41	15.2	1.04	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:4	32.72	2623	2.58	13.44	102	196	Off Idle	58.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.45	15.17	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:4	32.72	2630	2.58	13.45	102	196	Off Idle	58.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.44	15.15	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:4	32.72	2634	2.58	13.45	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.51	15.11	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:5	32.72	2640	2.58	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.53	Lean	1	14.6	-3.49	15.06	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:10:5	32.72	2631	2.58	13.43	102	196	Off Idle	59.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.49	15.01	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:5	32.72	2636	2.58	13.45	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.51	14.99	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:5	32.72	2636	2.58	13.44	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.47	14.94	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:10:5	32.72	2642	2.58	13.42	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.41	14.89	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:5	32.72	2639	2.58	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.41	14.86	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:6	32.72	2639	2.58	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.42	14.86	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:6	32.72	2635	2.58	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.45	14.87	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:6	32.72	2631	2.58	13.41	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.46	14.9	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:6	32.72	2631	2.58	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-3.47	14.93	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:6	32.72	2639	2.58	13.43	102	196	Off Idle	59.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-3.5	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:6	32.72	2636	2.58	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.22	Rich	1	14.6	-3.46	15.01	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:6	32.72	2634	2.58	13.44	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.24	Rich	1	14.6	-3.5	15.05	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:7	32.72	2634	2.58	13.45	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-3.5	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:7	32.72	2635	2.58	13.44	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-3.48	15.11	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:7	32.72	2638	2.58	13.43	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.5	15.12	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:7	32.72	2638	2.58	13.43	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-3.45	15.14	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:7	32.72	2636	2.58	13.42	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.48	15.13	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:10:7	32.72	2632	2.58	13.41	102	196	Off Idle	58.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.44	15.1	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:10:8	32.72	2629	2.58	13.42	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.42	15.08	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:10:8	32.72	2629	2.58	13.41	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.44	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:8	32.72	2628	2.58	13.41	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.48	15.03	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:8	32.72	2634	2.58	13.42	102	196	Off Idle	58.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.52	15	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:8	32.72	2634	2.58	13.43	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.5	14.99	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:10:8	32.72	2638	2.58	13.43	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.52	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:9	32.72	2635	2.58	13.44	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.56	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:9	32.72	2635	2.58	13.43	102	196	Off Idle	58.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-3.52	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:10:9	32.72	2638	2.58	13.42	102	196	Off Idle	58.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.48	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:10:9	32.72	2638	2.58	13.43	102	196	Off Idle	58.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-3.45	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:20:10:9	32.72	2639	2.58	13.43	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-3.44	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:9	32.72	2638	2.58	13.43	102	196	Off Idle	58.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-3.52	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:10:9	32.72	2632	2.58	13.43	102	196	Off Idle	58	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.45	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:11:0	32.72	2629	2.58	13.43	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.43	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:20:11:0	32.72	2629	2.58	13.42	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.51	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:0	32.72	2621	2.58	13.43	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.51	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:0	32.72	2634	2.58	13.44	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.55	14.9	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:0	32.72	2634	2.58	13.43	102	196	Off Idle	58.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.49	14.93	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:0	32.72	2634	2.57	13.43	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-3.62	15.01	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:1	32.72	2642	2.57	13.42	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.62	15.05	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:1	32.72	2629	2.57	13.43	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-3.66	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:1	32.72	2628	2.57	13.42	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-3.67	15.06	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:11:1	32.72	2626	2.57	13.43	102	196	Off Idle	58.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.73	15.05	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:11:1	32.72	2605	2.56	13.44	102	196	Off Idle	58.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.76	15.03	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:11:1	32.72	2613	2.56	13.45	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-3.82	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:1	32.72	2622	2.56	13.43	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.83	14.98	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:2	32.72	2626	2.55	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.84	14.96	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:2	32.72	2647	2.55	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.91	14.91	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:2	32.72	2638	2.54	13.42	102	196	Off Idle	59	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.91	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:2	32.72	2630	2.54	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.35	Rich	1	14.6	-3.94	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:11:2	32.72	2628	2.53	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.29	Rich	1	14.6	-3.98	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:11:2	32.72	2628	2.53	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.24	Rich	1	14.6	-4.04	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:11:3	32.72	2626	2.52	13.41	102	196	Off Idle	59	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.04	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:11:3	32.72	2622	2.52	13.43	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.09	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:3	32.72	2625	2.51	13.43	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.17	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:3	32.72	2626	2.5	13.41	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.17	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:3	32.72	2628	2.5	13.42	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.23	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:3	34.08	2651	2.49	13.42	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.3	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:4	34.08	2651	2.48	13.44	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.34	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:4	34.08	2632	2.48	13.43	101	196	Off Idle	59	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.4	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:4	34.08	2628	2.47	13.43	102	196	Off Idle	59	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.43	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:4	34.08	2621	2.47	13.45	102	196	Off Idle	59	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.46	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:11:4	34.08	2621	2.46	13.46	101	196	Off Idle	59	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.51	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:11:4	34.08	2618	2.46	13.46	101	196	Off Idle	59	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.55	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:11:4	34.08	2614	2.45	13.45	101	196	Off Idle	59	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.57	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:11:5	34.08	2616	2.44	13.45	102	196	Off Idle	59.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.64	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:11:5	34.08	2626	2.44	13.45	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.69	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:11:5	34.08	2627	2.43	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.77	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:5	34.08	2625	2.43	13.41	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.81	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:5	34.08	2624	2.42	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.84	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:5	34.08	2621	2.42	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.86	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:6	34.08	2603	2.41	13.44	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.95	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:6	34.08	2614	2.4	13.42	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.93	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:6	34.08	2624	2.4	13.43	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.98	15.08	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:6	34.08	2626	2.39	13.44	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5	15.11	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:6	34.08	2629	2.39	13.43	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.09	15.14	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:6	34.08	2641	2.38	13.44	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.1	15.16	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:6	34.08	2634	2.38	13.45	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.12	15.17	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:7	34.08	2629	2.37	13.45	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.14	15.16	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:7	34.08	2628	2.37	13.46	101	196	Off Idle	59.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.16	15.16	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:7	34.08	2627	2.37	13.45	102	196	Off Idle	59	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.17	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:7	34.08	2630	2.36	13.46	102	196	Off Idle	59	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.18	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:7	34.08	2630	2.36	13.46	102	196	Off Idle	59	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.19	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:7	34.08	2628	2.36	13.45	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.16	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:8	34.08	2601	2.36	13.45	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.17	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:8	34.08	2621	2.36	13.46	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.19	15.16	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:8	34.08	2620	2.36	13.45	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.2	15.18	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:8	34.08	2618	2.36	13.46	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.19	15.18	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:8	34.08	2617	2.35	13.45	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.23	15.18	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:8	34.08	2617	2.35	13.45	101	196	Off Idle	58.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.19	15.2	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:9	34.08	2615	2.35	13.43	101	196	Off Idle	58.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.23	15.2	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:9	34.08	2622	2.35	13.43	101	196	Off Idle	58.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.21	15.21	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:9	34.08	2623	2.35	13.44	101	196	Off Idle	58.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.22	15.22	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:9	34.08	2616	2.35	13.43	101	196	Off Idle	58.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.22	15.2	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:11:9	34.08	2616	2.35	13.44	101	196	Off Idle	58.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.25	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:9	34.08	2616	2.35	13.46	101	196	Off Idle	58.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.25	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:11:9	34.08	2614	2.35	13.45	101	196	Off Idle	58.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.29	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:0	34.08	2616	2.35	13.43	102	196	Off Idle	58.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.29	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:0	34.08	2616	2.34	13.42	102	196	Off Idle	59	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.29	15.17	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:0	34.08	2613	2.34	13.43	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.33	15.14	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:12:0	34.08	2613	2.34	13.44	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.36	15.16	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:12:0	34.08	2612	2.34	13.42	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.35	15.16	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:12:0	34.08	2605	2.34	13.43	101	196	Off Idle	59	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.37	15.14	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:12:1	34.08	2612	2.33	13.45	102	196	Off Idle	59	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.43	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:12:1	34.08	2612	2.33	13.44	102	196	Off Idle	59	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.44	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:12:1	34.08	2614	2.33	13.45	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.5	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:1	34.08	2618	2.33	13.46	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.5	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:1	34.08	2618	2.33	13.46	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.49	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:1	34.08	2627	2.32	13.47	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.53	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:1	34.08	2629	2.32	13.46	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.54	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:2	34.08	2627	2.32	13.46	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.51	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:2	34.08	2627	2.32	13.47	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.16	Rich	1	14.6	-5.55	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:2	34.08	2622	2.32	13.45	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.56	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:2	34.08	2618	2.31	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.54	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:2	34.08	2617	2.31	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.58	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:2	34.08	2618	2.31	13.43	102	196	Off Idle	59.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.57	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:12:3	34.08	2624	2.31	13.42	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.51	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:12:3	34.08	2628	2.31	13.41	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.54	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:12:3	34.08	2628	2.31	13.43	102	196	Off Idle	59.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.53	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:3	34.08	2633	2.31	13.42	102	196	Off Idle	59.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.51	15.2	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:3	34.08	2630	2.31	13.43	102	196	Off Idle	59.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.57	15.24	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:12:3	34.08	2623	2.31	13.46	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.57	15.25	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:4	34.08	2610	2.31	13.46	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.58	15.24	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:12:4	34.08	2612	2.31	13.46	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.56	15.24	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:4	34.08	2604	2.31	13.46	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.59	15.21	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:4	34.08	2604	2.31	13.45	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.58	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:4	34.08	2605	2.31	13.45	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.52	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:4	34.08	2623	2.31	13.45	102	196	Off Idle	59.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.54	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:4	34.08	2614	2.31	13.45	102	196	Off Idle	59.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.5	15.16	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:5	34.08	2609	2.31	13.43	102	196	Off Idle	59.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.46	15.15	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:5	34.08	2609	2.31	13.44	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.43	15.11	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:12:5	34.08	2610	2.31	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.42	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:12:5	34.08	2615	2.31	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.43	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:12:5	34.08	2619	2.32	13.46	101	196	Off Idle	60	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.44	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:12:5	34.08	2618	2.32	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.43	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:12:6	34.08	2618	2.32	13.45	101	196	Off Idle	60	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.41	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:12:6	34.08	2596	2.32	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.4	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:6	34.08	2615	2.33	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.32	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:6	34.08	2614	2.33	13.44	102	196	Off Idle	60	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.26	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:6	34.08	2614	2.34	13.44	102	196	Off Idle	60	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.19	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:6	34.08	2618	2.34	13.42	101	196	Off Idle	60	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.11	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:6	34.08	2632	2.35	13.43	101	196	Off Idle	60	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.05	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:7	34.08	2625	2.35	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:7	34.08	2617	2.36	13.42	102	196	Off Idle	59.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:7	34.08	2616	2.36	13.44	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.94	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:7	34.08	2616	2.36	13.44	102	196	Off Idle	59.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.92	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:7	34.08	2616	2.37	13.44	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.92	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:7	34.08	2616	2.38	13.45	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.88	15.11	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:8	34.08	2617	2.38	13.44	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.64	Lean	1	14.6	-4.86	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:8	34.08	2614	2.39	13.44	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.69	Lean	1	14.6	-4.87	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:8	34.08	2602	2.39	13.46	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.84	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:12:8	34.08	2608	2.4	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.81	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:8	34.08	2609	2.4	13.43	101	196	Off Idle	60.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.86	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:8	34.08	2611	2.4	13.42	101	196	Off Idle	60	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.79	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:9	34.08	2622	2.41	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.78	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:9	34.08	2618	2.41	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.84	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:9	34.08	2619	2.41	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.84	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:9	34.08	2619	2.41	13.45	101	196	Off Idle	60	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.8	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:9	34.08	2616	2.41	13.45	101	196	Off Idle	60	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.88	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:9	34.08	2609	2.41	13.43	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.88	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:12:9	34.08	2606	2.41	13.42	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.85	14.78	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:0	34.08	2600	2.41	13.41	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.87	14.79	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:0	34.08	2600	2.41	13.43	102	196	Off Idle	59.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.87	14.81	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:0	34.08	2608	2.41	13.44	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.82	14.81	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:0	34.08	2609	2.41	13.44	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.82	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:0	34.08	2616	2.41	13.45	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.8	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:0	34.08	2624	2.41	13.47	101	196	Off Idle	59.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.81	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:1	34.08	2624	2.41	13.45	101	196	Off Idle	59	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.81	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:1	34.08	2624	2.41	13.45	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.79	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:1	34.08	2621	2.41	13.43	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.79	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:1	34.08	2621	2.41	13.44	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.79	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:1	34.08	2617	2.41	13.43	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.83	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:1	34.08	2620	2.41	13.42	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.79	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:1	34.08	2618	2.41	13.43	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.77	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:2	34.08	2618	2.41	13.44	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.77	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:2	34.08	2611	2.41	13.43	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.77	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:2	34.08	2617	2.41	13.45	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.71	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:2	34.08	2617	2.41	13.45	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.72	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:2	34.08	2616	2.41	13.43	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.73	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:13:2	34.08	2612	2.41	13.42	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-4.67	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:3	34.08	2610	2.42	13.42	102	196	Off Idle	58.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.65	15.05	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:3	34.08	2612	2.42	13.43	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.68	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:3	34.08	2615	2.42	13.42	101	196	Off Idle	58.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.66	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:3	34.08	2618	2.42	13.43	101	196	Off Idle	59.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.62	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:3	34.08	2620	2.43	13.42	101	196	Off Idle	59.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.63	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:3	34.08	2621	2.43	13.44	101	196	Off Idle	59.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.66	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:4	34.08	2612	2.43	13.46	101	196	Off Idle	59.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.66	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:4	34.08	2612	2.43	13.45	101	196	Off Idle	59.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.62	14.88	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:4	34.08	2610	2.43	13.45	101	196	Off Idle	59.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.64	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:4	34.08	2611	2.43	13.47	101	196	Off Idle	59.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.66	14.79	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:4	34.08	2593	2.43	13.45	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.66	14.78	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:4	32.72	2604	2.44	13.44	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.6	14.77	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:4	32.72	2614	2.44	13.45	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.63	14.77	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:5	32.72	2612	2.44	13.42	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.63	14.79	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:5	32.72	2612	2.44	13.42	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.58	14.8	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:5	32.72	2610	2.44	13.41	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.57	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:5	34.08	2621	2.44	13.41	102	196	Off Idle	59.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.56	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:5	34.08	2613	2.44	13.44	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.59	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:5	34.08	2614	2.44	13.42	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.6	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:6	34.08	2618	2.44	13.43	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.59	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:6	34.08	2615	2.44	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.64	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:6	34.08	2615	2.44	13.43	101	196	Off Idle	60	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.66	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:6	34.08	2613	2.44	13.44	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.62	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:6	34.08	2613	2.44	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.64	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:6	34.08	2617	2.44	13.43	101	196	Off Idle	59.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.64	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:6	34.08	2617	2.44	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.59	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:7	34.08	2618	2.44	13.44	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.59	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:7	34.08	2621	2.44	13.43	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.62	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:7	34.08	2620	2.44	13.42	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.6	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:7	34.08	2616	2.44	13.43	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.6	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:7	34.08	2612	2.44	13.43	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.63	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:7	34.08	2612	2.44	13.42	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.59	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:8	34.08	2611	2.44	13.43	101	196	Off Idle	60	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.6	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:8	34.08	2614	2.44	13.43	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.63	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:8	34.08	2616	2.44	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.62	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:8	34.08	2616	2.44	13.43	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.6	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:8	34.08	2619	2.43	13.42	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.67	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:8	34.08	2621	2.43	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.64	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:9	34.08	2622	2.43	13.43	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.66	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:9	34.08	2619	2.43	13.43	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.64	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:13:9	34.08	2613	2.43	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.65	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:9	34.08	2612	2.43	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.68	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:9	34.08	2612	2.43	13.43	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.67	14.89	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:13:9	34.08	2610	2.43	13.43	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.66	14.91	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:13:9	34.08	2612	2.43	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.66	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:0	34.08	2612	2.43	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.71	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:0	34.08	2613	2.43	13.43	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.66	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:0	34.08	2614	2.43	13.45	101	196	Off Idle	60	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.67	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:0	34.08	2614	2.43	13.45	101	196	Off Idle	60	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.74	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:0	34.08	2614	2.43	13.44	101	196	Off Idle	60	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.77	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:0	34.08	2618	2.43	13.43	102	196	Off Idle	59.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.75	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:1	34.08	2621	2.43	13.43	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.76	15	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:1	34.08	2621	2.42	13.44	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.77	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:1	34.08	2618	2.42	13.42	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.77	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:1	34.08	2617	2.42	13.41	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.74	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:1	34.08	2627	2.42	13.43	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.77	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:1	34.08	2627	2.42	13.41	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.82	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:14:1	34.08	2630	2.42	13.41	102	196	Off Idle	59.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.78	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:2	34.08	2626	2.42	13.41	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.77	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:2	34.08	2624	2.42	13.42	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.82	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:2	34.08	2612	2.42	13.42	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.79	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:2	34.08	2606	2.41	13.44	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.84	14.93	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:2	34.08	2601	2.41	13.45	101	196	Off Idle	59.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.84	14.96	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:2	34.08	2602	2.41	13.44	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.87	15.06	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:3	34.08	2606	2.41	13.41	101	196	Off Idle	59.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.87	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:3	34.08	2606	2.41	13.42	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.88	15.1	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:3	34.08	2609	2.41	13.41	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.92	15.08	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:3	34.08	2609	2.41	13.41	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.88	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:3	34.08	2620	2.4	13.43	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.87	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:3	34.08	2618	2.4	13.43	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.93	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:4	34.08	2618	2.4	13.43	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.98	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:4	34.08	2618	2.4	13.42	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.97	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:4	34.08	2620	2.4	13.43	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-4.99	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:4	34.08	2620	2.39	13.43	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.01	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:4	34.08	2618	2.39	13.43	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.99	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:4	34.08	2617	2.39	13.43	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.98	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:4	34.08	2617	2.39	13.45	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.99	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:5	34.08	2619	2.39	13.45	101	196	Off Idle	59.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.98	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:5	34.08	2619	2.39	13.43	101	196	Off Idle	60	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.95	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:5	34.08	2623	2.39	13.45	101	196	Off Idle	60	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.98	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:5	34.08	2623	2.39	13.44	101	196	Off Idle	59.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:5	34.08	2622	2.38	13.43	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.95	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:5	34.08	2624	2.38	13.43	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.98	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:6	34.08	2622	2.38	13.43	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.98	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:6	34.08	2618	2.38	13.44	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.99	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:6	34.08	2610	2.38	13.42	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:6	34.08	2610	2.38	13.42	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.98	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:6	34.08	2607	2.38	13.43	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.02	15.14	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:6	34.08	2609	2.38	13.43	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.04	15.15	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:6	34.08	2611	2.39	13.43	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.01	15.17	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:7	34.08	2610	2.39	13.43	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.98	15.18	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:7	34.08	2606	2.39	13.43	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5	15.19	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:7	34.08	2605	2.39	13.45	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.99	15.16	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:7	34.08	2610	2.39	13.44	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5	15.14	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:7	34.08	2610	2.38	13.44	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.98	15.12	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:7	34.08	2614	2.38	13.45	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.97	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:8	34.08	2616	2.38	13.44	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:14:8	34.08	2614	2.38	13.45	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.99	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:8	34.08	2611	2.38	13.43	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.01	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:8	34.08	2611	2.38	13.45	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.02	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:8	34.08	2610	2.38	13.44	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5	14.93	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:8	34.08	2610	2.38	13.45	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:9	34.08	2614	2.38	13.45	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.04	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:9	34.08	2614	2.38	13.45	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.03	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:9	34.08	2615	2.38	13.44	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.99	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:9	34.08	2616	2.38	13.44	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.04	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:9	34.08	2617	2.38	13.44	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.03	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:14:9	34.08	2616	2.38	13.42	101	196	Off Idle	59.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.95	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:14:9	34.08	2615	2.38	13.43	101	196	Off Idle	59	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.94	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:0	34.08	2613	2.38	13.43	101	196	Off Idle	59	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.98	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:0	34.08	2612	2.38	13.42	101	196	Off Idle	59	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.96	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:0	34.08	2613	2.39	13.44	101	196	Off Idle	59	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.97	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:0	34.08	2615	2.39	13.44	101	196	Off Idle	59	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.01	15.12	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:0	34.08	2614	2.39	13.43	101	196	Off Idle	59	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.01	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:0	34.08	2615	2.39	13.45	101	196	Off Idle	59	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.99	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:15:1	34.08	2613	2.39	13.44	101	196	Off Idle	59	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.99	15.14	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:1	34.08	2612	2.39	13.44	101	196	Off Idle	59	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5	15.11	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:1	34.08	2614	2.39	13.43	101	196	Off Idle	59.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.98	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:1	34.08	2618	2.39	13.44	101	196	Off Idle	59.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.98	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:1	34.08	2616	2.39	13.44	101	196	Off Idle	59.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.96	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:1	34.08	2615	2.39	13.44	101	196	Off Idle	59.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.96	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:1	34.08	2615	2.39	13.45	101	196	Off Idle	59.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.94	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:2	34.08	2613	2.39	13.44	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.98	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:2	34.08	2611	2.39	13.45	101	196	Off Idle	59.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.97	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:2	34.08	2611	2.39	13.46	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.98	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:2	34.08	2610	2.39	13.45	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.94	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:2	34.08	2608	2.39	13.45	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.92	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:2	34.08	2608	2.39	13.45	101	196	Off Idle	60.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.95	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:3	34.08	2618	2.39	13.43	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.92	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:3	34.08	2618	2.39	13.44	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.91	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:3	34.08	2614	2.39	13.43	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.96	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:3	34.08	2605	2.39	13.45	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.94	14.96	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:3	34.08	2605	2.39	13.45	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.96	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:3	34.08	2603	2.39	13.45	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.94	15.07	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:4	34.08	2610	2.39	13.46	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.93	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:4	34.08	2614	2.39	13.45	101	196	Off Idle	60.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.95	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:4	34.08	2614	2.39	13.45	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.95	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:4	34.08	2614	2.39	13.44	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.92	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:4	34.08	2617	2.39	13.44	101	196	Off Idle	60.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.91	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:4	34.08	2617	2.39	13.46	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.91	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:4	34.08	2616	2.39	13.44	101	196	Off Idle	59.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.93	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:5	34.08	2614	2.39	13.44	101	196	Off Idle	59.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.89	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:5	34.08	2614	2.39	13.44	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.89	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:5	34.08	2612	2.39	13.44	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.9	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:5	34.08	2608	2.39	13.44	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.87	14.76	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:5	34.08	2609	2.4	13.45	101	196	Off Idle	59.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.88	14.76	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:5	34.08	2612	2.4	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.84	14.76	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:15:6	34.08	2609	2.4	13.45	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.85	14.78	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:6	34.08	2609	2.4	13.46	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.88	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:6	34.08	2612	2.4	13.46	101	196	Off Idle	60.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.89	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:6	34.08	2614	2.4	13.45	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.87	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:6	34.08	2611	2.4	13.43	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.88	14.87	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:6	34.08	2608	2.4	13.44	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.85	14.9	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:6	34.08	2604	2.4	13.44	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.84	14.92	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:7	34.08	2602	2.4	13.42	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.84	14.96	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:7	34.08	2600	2.4	13.43	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.84	15.01	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:7	34.08	2596	2.4	13.43	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.85	15.03	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:7	34.08	2599	2.4	13.43	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.86	15.03	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:7	34.08	2600	2.4	13.43	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.81	15.02	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:7	34.08	2606	2.4	13.44	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.79	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:8	34.08	2612	2.4	13.45	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.82	14.97	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:8	34.08	2613	2.4	13.45	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.85	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:8	34.08	2613	2.4	13.44	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.87	14.9	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:8	34.08	2612	2.4	13.44	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.9	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:8	34.08	2607	2.4	13.43	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.93	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:8	34.08	2607	2.4	13.45	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.91	14.8	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:9	34.08	2606	2.4	13.43	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.92	14.79	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:9	34.08	2606	2.4	13.42	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.87	14.81	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:9	34.08	2604	2.4	13.43	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.88	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:15:9	34.08	2606	2.4	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.9	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:9	34.08	2613	2.4	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-4.92	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:9	34.08	2616	2.4	13.44	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.96	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:15:9	34.08	2616	2.39	13.44	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.94	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:16:0	34.08	2611	2.39	13.44	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.92	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:0	34.08	2608	2.39	13.45	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.95	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:0	34.08	2603	2.39	13.45	101	196	Off Idle	60.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.93	14.88	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:0	34.08	2604	2.39	13.45	101	196	Off Idle	60.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.94	14.93	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:0	34.08	2603	2.39	13.45	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.95	14.97	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:0	34.08	2603	2.39	13.45	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.95	14.97	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:1	34.08	2604	2.39	13.43	101	196	Off Idle	60.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.99	15.05	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:1	34.08	2604	2.39	13.43	101	196	Off Idle	60.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.02	15.06	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:1	34.08	2605	2.39	13.43	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5	15.1	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:1	34.08	2600	2.39	13.44	101	196	Off Idle	59.8	0	2	132	944 Turbo	0.34	Rich	1	14.6	-4.99	15.14	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:1	34.08	2600	2.39	13.44	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.02	15.15	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:1	34.08	2595	2.39	13.44	101	196	Off Idle	59.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.01	15.17	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:1	34.08	2593	2.39	13.43	101	196	Off Idle	59.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.02	15.17	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:2	34.08	2597	2.38	13.45	101	196	Off Idle	59.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.97	15.17	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:2	34.08	2597	2.38	13.45	101	196	Off Idle	59.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5	15.16	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:2	34.08	2601	2.38	13.44	101	196	Off Idle	59.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.99	15.12	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:2	34.08	2609	2.38	13.43	101	196	Off Idle	60.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.02	15.1	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:2	34.08	2608	2.38	13.45	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.01	15.04	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:2	34.08	2607	2.38	13.45	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.02	15.02	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:3	34.08	2606	2.38	13.45	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.05	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:3	34.08	2603	2.38	13.45	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.1	14.92	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:3	34.08	2602	2.37	13.45	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.1	14.89	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:3	34.08	2598	2.37	13.45	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.11	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:3	34.08	2571	2.37	13.45	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.15	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:3	34.08	2580	2.37	13.46	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.14	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:4	34.08	2594	2.37	13.44	101	196	Off Idle	61	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.11	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:4	34.08	2603	2.37	13.44	101	196	Off Idle	61	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.08	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:4	34.08	2627	2.37	13.45	101	196	Off Idle	61	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.1	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:4	34.08	2627	2.37	13.44	101	196	Off Idle	61	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.08	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:4	34.08	2608	2.37	13.42	101	196	Off Idle	61	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.07	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:4	34.08	2609	2.36	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.09	14.91	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:4	34.08	2609	2.36	13.42	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.13	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:5	34.08	2584	2.36	13.42	101	196	Off Idle	60.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.1	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:5	34.08	2597	2.36	13.42	101	196	Off Idle	60.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.1	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:5	34.08	2597	2.36	13.43	101	196	Off Idle	60.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.09	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:5	34.08	2593	2.36	13.42	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.1	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:5	34.08	2595	2.36	13.43	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.11	15.12	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:5	34.08	2612	2.36	13.43	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.09	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:6	34.08	2604	2.36	13.44	101	196	Off Idle	60.8	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.11	15.15	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:6	34.08	2599	2.36	13.44	101	196	Off Idle	60.8	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.13	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:6	34.08	2598	2.36	13.44	102	196	Off Idle	60.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-5.1	15.08	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:6	34.08	2600	2.36	13.44	102	196	Off Idle	60.7	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.12	14.91	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:6	34.08	2606	2.36	13.45	101	196	Off Idle	60.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.16	14.87	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:6	34.08	2604	2.36	13.43	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.14	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:6	34.08	2604	2.36	13.44	101	196	Off Idle	60.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.16	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:7	34.08	2602	2.36	13.45	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.13	14.81	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:7	34.08	2594	2.36	13.46	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.17	14.73	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:7	34.08	2605	2.36	13.44	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.15	14.69	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:7	34.08	2605	2.36	13.44	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.18	14.69	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:7	34.08	2602	2.36	13.44	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.18	14.71	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:7	34.08	2620	2.36	13.44	101	196	Off Idle	60.2	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.18	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:8	34.08	2610	2.36	13.45	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.19	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:8	34.08	2598	2.36	13.45	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.19	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:8	34.08	2600	2.36	13.44	101	196	Off Idle	60.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.16	14.97	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:8	34.08	2600	2.36	13.43	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.18	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:8	34.08	2597	2.36	13.43	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.16	15.08	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:8	34.08	2597	2.36	13.42	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.12	15.12	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:16:9	34.08	2592	2.36	13.42	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.17	15.13	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:16:9	34.08	2587	2.36	13.42	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.17	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:9	34.08	2586	2.36	13.42	101	196	Off Idle	60.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.16	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:16:9	34.08	2587	2.36	13.44	101	196	Off Idle	60.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.22	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:9	34.08	2591	2.36	13.44	101	196	Off Idle	60.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.23	15.06	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:9	34.08	2592	2.36	13.43	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.19	15.03	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:16:9	34.08	2594	2.35	13.43	101	196	Off Idle	61	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.23	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:17:0	34.08	2595	2.35	13.45	101	196	Off Idle	61.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.22	14.92	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:17:0	34.08	2594	2.35	13.45	101	196	Off Idle	61	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.23	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:17:0	34.08	2592	2.35	13.44	101	196	Off Idle	61	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.23	14.85	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:17:0	34.08	2590	2.35	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.22	14.83	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:17:0	34.08	2590	2.35	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.25	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:17:0	34.08	2592	2.35	13.45	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.25	14.87	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:17:1	34.08	2593	2.35	13.43	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.22	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:1	34.08	2596	2.35	13.42	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.22	14.9	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:1	34.08	2596	2.34	13.43	101	196	Off Idle	61.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.21	14.94	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:1	34.08	2595	2.34	13.43	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.2	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:1	34.08	2596	2.34	13.45	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.24	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:1	34.08	2595	2.34	13.45	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.29	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:1	34.08	2598	2.34	13.45	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.28	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:2	34.08	2601	2.34	13.45	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.3	15.11	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:2	34.08	2593	2.34	13.46	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.3	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:2	34.08	2593	2.34	13.44	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.35	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:2	34.08	2594	2.33	13.44	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.32	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:2	34.08	2595	2.33	13.44	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.34	15.03	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:2	34.08	2595	2.33	13.44	101	196	Off Idle	61.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.36	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:3	34.08	2596	2.33	13.43	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.37	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:3	34.08	2596	2.33	13.44	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.36	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:3	34.08	2591	2.33	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.39	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:3	34.08	2592	2.33	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.41	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:3	34.08	2591	2.33	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.44	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:3	34.08	2586	2.33	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.47	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:4	34.08	2586	2.32	13.45	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.48	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:4	34.08	2586	2.32	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.5	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:4	34.08	2586	2.32	13.45	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.51	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:17:4	34.08	2588	2.32	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.52	14.91	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:20:17:4	34.08	2592	2.31	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.58	14.96	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:17:4	34.08	2593	2.31	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.61	15	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:17:4	34.08	2596	2.3	13.43	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.7	15.04	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:17:5	34.08	2596	2.3	13.43	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.71	15.09	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:17:5	34.08	2595	2.3	13.42	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.73	15.12	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:5	34.08	2589	2.29	13.43	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.81	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:5	34.08	2587	2.29	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.81	15.18	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:5	34.08	2587	2.28	13.46	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.87	15.21	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:5	34.08	2587	2.28	13.46	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.91	15.2	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:6	34.08	2583	2.27	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.91	15.19	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:6	34.08	2585	2.26	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.94	15.15	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:6	34.08	2587	2.26	13.43	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.01	15.11	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:6	34.08	2588	2.25	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.04	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:6	34.08	2588	2.25	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.13	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:6	34.08	2586	2.24	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.17	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:6	34.08	2586	2.24	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.23	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:7	34.08	2588	2.23	13.44	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.29	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:7	34.08	2588	2.22	13.45	101	196	Off Idle	60.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.33	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:7	34.08	2582	2.22	13.45	101	196	Off Idle	61.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.33	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:7	34.08	2580	2.22	13.43	101	196	Off Idle	61.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.39	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:7	34.08	2578	2.21	13.44	101	196	Off Idle	61.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.4	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:7	34.08	2578	2.2	13.43	101	196	Off Idle	61.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.47	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:17:8	34.08	2576	2.2	13.42	101	196	Off Idle	61.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.52	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:17:8	34.08	2579	2.19	13.44	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.57	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:17:8	34.08	2582	2.19	13.45	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.58	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:8	34.08	2583	2.19	13.44	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.62	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:8	34.08	2565	2.18	13.43	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.63	15.08	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:8	34.08	2584	2.17	13.44	101	196	Off Idle	61.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.66	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:9	34.08	2582	2.17	13.45	101	196	Off Idle	61.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.68	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:9	34.08	2582	2.16	13.44	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.71	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:9	34.08	2590	2.16	13.45	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.71	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:9	34.08	2590	2.15	13.44	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.75	15.16	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:9	34.08	2568	2.15	13.43	101	196	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.75	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:9	34.08	2567	2.15	13.43	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.75	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:17:9	34.08	2549	2.14	13.44	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.81	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:0	34.08	2549	2.14	13.42	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.79	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:0	34.08	2570	2.14	13.42	101	196	Off Idle	61.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.78	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:0	34.08	2573	2.14	13.44	101	196	Off Idle	61.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.78	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:0	34.08	2573	2.13	13.42	101	196	Off Idle	61.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.8	14.9	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:0	34.08	2596	2.13	13.44	101	196	Off Idle	61.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.79	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:0	34.08	2588	2.13	13.42	101	196	Off Idle	61.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.8	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:1	34.08	2578	2.13	13.42	101	196	Off Idle	61.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.81	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:1	34.08	2575	2.13	13.44	101	196	Off Idle	61.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.85	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:1	34.08	2572	2.13	13.44	101	196	Off Idle	62	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.85	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:1	34.08	2572	2.13	13.43	101	196	Off Idle	62	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.83	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:1	34.08	2571	2.12	13.44	101	196	Off Idle	62	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.83	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:1	34.08	2565	2.12	13.44	101	196	Off Idle	62	0	2	132	944 Turbo	0.19	Rich	1	14.6	-6.86	14.9	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:1	34.08	2565	2.12	13.46	101	196	Off Idle	62	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.86	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:2	34.08	2564	2.12	13.46	101	196	Off Idle	62	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.9	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:2	34.08	2566	2.12	13.45	101	196	Off Idle	62	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.86	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:2	34.08	2567	2.12	13.44	101	196	Off Idle	62	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.85	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:2	34.08	2568	2.12	13.44	101	196	Off Idle	62	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.84	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:2	34.08	2572	2.12	13.43	101	196	Off Idle	62.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.83	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:2	34.08	2573	2.12	13.44	101	196	Off Idle	62.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.83	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:3	34.08	2572	2.12	13.43	101	196	Off Idle	62.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.82	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:3	34.08	2570	2.12	13.44	101	196	Off Idle	62.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.82	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:3	34.08	2574	2.12	13.46	101	196	Off Idle	62.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.83	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:3	34.08	2562	2.12	13.45	101	196	Off Idle	62	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.85	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:3	34.08	2562	2.12	13.44	101	196	Off Idle	62	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.86	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:3	34.08	2552	2.12	13.44	101	196	Off Idle	62.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.86	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:4	34.08	2558	2.12	13.44	101	196	Off Idle	62.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.87	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:4	34.08	2558	2.12	13.45	101	196	Off Idle	62.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.87	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:4	34.08	2558	2.12	13.43	101	196	Off Idle	62.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.85	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:4	34.08	2559	2.12	13.42	101	196	Off Idle	62.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.85	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:4	34.08	2558	2.12	13.43	101	196	Off Idle	62.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.85	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:4	34.08	2552	2.12	13.42	101	196	Off Idle	63.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.85	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:4	34.08	2562	2.12	13.42	101	196	Off Idle	63.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.85	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:5	34.08	2560	2.12	13.42	101	196	Off Idle	63.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.87	14.83	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:5	34.08	2560	2.12	13.43	101	196	Off Idle	63.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.88	14.84	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:5	34.08	2599	2.12	13.44	101	196	Off Idle	63.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.9	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:5	34.08	2578	2.11	13.45	101	196	Off Idle	63.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.89	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:5	34.08	2556	2.11	13.44	101	196	Off Idle	63.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.91	14.9	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:5	34.08	2554	2.11	13.46	101	196	Off Idle	62.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.9	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:6	34.08	2553	2.11	13.45	101	196	Off Idle	62.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.88	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:6	34.08	2553	2.11	13.44	101	196	Off Idle	62.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.91	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:6	34.08	2555	2.11	13.43	101	196	Off Idle	62.8	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.88	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:6	34.08	2553	2.11	13.43	101	196	Off Idle	62.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.86	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:6	34.08	2554	2.11	13.43	101	196	Off Idle	62.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.85	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:6	34.08	2557	2.11	13.45	101	196	Off Idle	62.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.81	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:6	34.08	2561	2.11	13.46	101	196	Off Idle	62.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.85	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:7	34.08	2565	2.11	13.44	101	196	Off Idle	62.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.82	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:18:7	34.08	2564	2.11	13.45	101	196	Off Idle	62.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.83	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:7	34.08	2558	2.11	13.46	101	196	Off Idle	62.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.87	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:7	34.08	2558	2.11	13.44	101	196	Off Idle	62.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.9	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:7	34.08	2558	2.11	13.42	101	196	Off Idle	62.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.88	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:7	34.08	2558	2.11	13.42	101	196	Off Idle	62.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.87	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:8	34.08	2557	2.11	13.44	101	196	Off Idle	62.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.92	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:8	34.08	2557	2.11	13.45	101	196	Off Idle	62.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.93	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:8	34.08	2572	2.11	13.44	101	196	Off Idle	62.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.91	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:8	34.08	2547	2.11	13.45	101	196	Off Idle	62.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.9	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:8	34.08	2545	2.11	13.46	101	196	Off Idle	62.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.9	14.9	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:8	34.08	2545	2.11	13.46	101	196	Off Idle	62.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.93	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:9	34.08	2521	2.11	13.45	101	196	Off Idle	62.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.9	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:18:9	34.08	2540	2.11	13.45	101	196	Off Idle	62.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.92	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:9	34.08	2539	2.11	13.46	101	196	Off Idle	62.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.96	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:18:9	34.08	2541	2.1	13.44	101	196	Off Idle	63	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:9	34.08	2526	2.1	13.44	101	196	Off Idle	63.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.01	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:9	34.08	2538	2.1	13.42	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.03	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:18:9	34.08	2551	2.09	13.43	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.06	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:0	34.08	2552	2.09	13.45	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.13	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:0	34.08	2565	2.09	13.43	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.13	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:0	34.08	2556	2.08	13.44	101	196	Off Idle	63.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.15	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:0	34.08	2544	2.08	13.45	101	196	Off Idle	63.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.2	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:0	34.08	2540	2.08	13.44	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.21	15.05	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:0	34.08	2542	2.07	13.44	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.19	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:1	34.08	2545	2.07	13.46	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.18	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:1	34.08	2547	2.06	13.44	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.68	Lean	1	14.6	-7.22	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:1	34.08	2549	2.06	13.45	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.22	14.94	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:1	34.08	2549	2.06	13.46	101	196	Off Idle	63.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.24	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:1	34.08	2548	2.06	13.45	101	196	Off Idle	63.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.28	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:1	34.08	2551	2.05	13.45	101	196	Off Idle	63.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.27	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:1	34.08	2552	2.05	13.45	101	196	Off Idle	63	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.27	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:2	34.08	2552	2.05	13.45	101	196	Off Idle	63	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.27	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:2	34.08	2549	2.05	13.45	101	196	Off Idle	63	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.23	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:2	34.08	2543	2.05	13.44	101	196	Off Idle	63.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.23	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:2	34.08	2542	2.05	13.43	101	196	Off Idle	63.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.21	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:2	34.08	2536	2.05	13.44	101	196	Off Idle	63.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.21	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:2	34.08	2533	2.05	13.45	101	196	Off Idle	63.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.24	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:3	34.08	2533	2.05	13.44	101	196	Off Idle	63.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.2	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:3	34.08	2528	2.05	13.44	101	196	Off Idle	63.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.17	14.9	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:3	34.08	2526	2.05	13.45	101	196	Off Idle	63.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.18	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:3	34.08	2526	2.05	13.46	101	196	Off Idle	63.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.2	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:3	34.08	2533	2.05	13.46	101	196	Off Idle	63.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.23	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:3	34.08	2538	2.05	13.45	101	196	Off Idle	63.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.24	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:4	34.08	2539	2.05	13.46	101	196	Off Idle	63.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.24	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:4	34.08	2540	2.05	13.45	101	196	Off Idle	63.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.25	15.15	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:4	34.08	2542	2.05	13.45	101	196	Off Idle	63.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.26	15.18	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:4	34.08	2536	2.05	13.44	101	196	Off Idle	64	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.23	15.19	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:4	34.08	2536	2.05	13.44	101	196	Off Idle	64.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.23	15.17	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:4	34.08	2531	2.05	13.45	101	196	Off Idle	64.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.26	15.16	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:4	34.08	2530	2.05	13.44	101	196	Off Idle	64.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.24	15.16	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:5	34.08	2528	2.05	13.44	101	196	Off Idle	64.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.27	15.13	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:5	34.08	2529	2.05	13.43	101	196	Off Idle	64.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.28	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:5	34.08	2529	2.05	13.42	101	196	Off Idle	64	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.29	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:5	34.08	2535	2.05	13.43	101	196	Off Idle	63.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.28	15.05	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:5	34.08	2536	2.05	13.43	101	196	Off Idle	63.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.29	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:5	34.08	2535	2.05	13.44	101	196	Off Idle	64	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.3	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:6	34.08	2525	2.05	13.46	101	196	Off Idle	63.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.29	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:6	34.08	2527	2.05	13.44	101	196	Off Idle	63.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.28	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:19:6	34.08	2524	2.05	13.44	101	196	Off Idle	64	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.26	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:6	34.08	2522	2.05	13.44	101	196	Off Idle	64	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.24	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:6	34.08	2524	2.05	13.44	101	196	Off Idle	63.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.21	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:6	34.08	2525	2.05	13.45	101	196	Off Idle	64	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.21	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:6	34.08	2529	2.05	13.45	101	196	Off Idle	64.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.19	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:7	34.08	2530	2.05	13.45	101	196	Off Idle	64.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.25	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:7	34.08	2534	2.05	13.46	101	196	Off Idle	64.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.25	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:7	34.08	2553	2.05	13.46	101	196	Off Idle	64.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.26	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:19:7	34.08	2530	2.05	13.46	101	196	Off Idle	64.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.26	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:7	34.08	2530	2.04	13.43	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.29	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:7	34.08	2528	2.04	13.44	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.3	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:8	34.08	2517	2.04	13.44	101	196	Off Idle	65.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.32	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:8	34.08	2517	2.04	13.44	101	196	Off Idle	65.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.33	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:8	34.08	2511	2.04	13.45	101	196	Off Idle	65.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.31	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:8	34.08	2510	2.04	13.45	101	196	Off Idle	65.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.27	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:8	34.08	2511	2.04	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.27	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:8	34.08	2512	2.04	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.27	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:9	34.08	2518	2.04	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.3	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:9	34.08	2517	2.04	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.27	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:9	34.08	2518	2.04	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.28	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:9	34.08	2532	2.04	13.44	101	196	Off Idle	65.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.32	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:19:9	34.08	2520	2.04	13.43	101	196	Off Idle	65.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.29	15.12	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:9	34.08	2522	2.04	13.43	101	196	Off Idle	65.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.32	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:19:9	34.08	2524	2.03	13.45	101	196	Off Idle	65.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.29	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:0	34.08	2487	2.03	13.43	101	196	Off Idle	65.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.33	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:0	34.08	2506	2.03	13.45	101	196	Off Idle	65.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.29	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:0	34.08	2527	2.03	13.43	101	196	Off Idle	65.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.31	14.97	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:0	34.08	2525	2.03	13.44	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.28	14.95	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:0	34.08	2542	2.03	13.43	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.26	14.89	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:0	34.08	2532	2.03	13.44	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.25	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:1	34.08	2522	2.03	13.45	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.26	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:1	34.08	2529	2.03	13.46	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.28	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:1	34.08	2529	2.03	13.46	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.31	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:1	34.08	2536	2.03	13.45	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.35	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:1	34.08	2524	2.03	13.45	101	196	Off Idle	65	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.34	14.9	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:1	34.08	2523	2.03	13.44	101	196	Off Idle	65.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.34	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:1	34.08	2516	2.03	13.43	101	196	Off Idle	65	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.33	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:2	34.08	2507	2.03	13.44	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.31	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:2	34.08	2507	2.03	13.43	101	196	Off Idle	64.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.32	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:20:2	34.08	2503	2.03	13.44	101	196	Off Idle	64.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.25	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:20:2	34.08	2503	2.03	13.44	101	196	Off Idle	65.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.24	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:2	34.08	2480	2.03	13.42	101	196	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.26	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:2	34.08	2480	2.03	13.44	101	196	Off Idle	65	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.23	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:3	34.08	2504	2.03	13.43	101	196	Off Idle	65	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.2	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:3	34.08	2512	2.04	13.42	101	196	Off Idle	65	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.26	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:3	34.08	2516	2.04	13.42	101	196	Off Idle	65	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.26	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:3	34.08	2516	2.04	13.43	101	196	Off Idle	65	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.27	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:3	34.08	2516	2.04	13.42	101	196	Off Idle	65	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.29	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:3	34.08	2514	2.03	13.42	101	196	Off Idle	65	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.27	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:4	34.08	2514	2.03	13.43	101	196	Off Idle	65.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.27	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:4	34.08	2509	2.03	13.44	101	196	Off Idle	65.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.29	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:4	34.08	2504	2.03	13.45	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.26	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:4	34.08	2507	2.03	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.29	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:4	34.08	2509	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.27	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:4	34.08	2512	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.27	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:4	34.08	2512	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.27	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:5	34.08	2518	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.28	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:5	34.08	2520	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.26	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:20:5	34.08	2518	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.25	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:5	34.08	2518	2.03	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.28	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:5	34.08	2522	2.03	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.29	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:5	34.08	2504	2.03	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.3	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:6	34.08	2502	2.03	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.31	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:6	34.08	2488	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.34	15.15	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:6	34.08	2498	2.03	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.3	15.15	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:6	34.08	2501	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.3	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:6	34.08	2501	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.32	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:6	34.08	2506	2.03	13.42	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.31	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:6	34.08	2506	2.03	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.27	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:7	34.08	2500	2.03	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.3	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:7	34.08	2500	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.29	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:7	34.08	2497	2.03	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.33	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:7	34.08	2498	2.03	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.34	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:7	34.08	2500	2.03	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.33	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:7	34.08	2498	2.03	13.46	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.29	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:8	34.08	2495	2.03	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.27	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:8	34.08	2495	2.03	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.26	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:8	34.08	2496	2.03	13.43	101	196	Off Idle	66.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.25	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:8	34.08	2499	2.03	13.43	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.24	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:8	34.08	2500	2.03	13.44	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.27	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:8	34.08	2498	2.03	13.44	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.28	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:20:9	34.08	2495	2.03	13.45	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.27	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:9	34.08	2499	2.03	13.44	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.29	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:9	34.08	2502	2.03	13.45	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.28	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:9	34.08	2502	2.03	13.45	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.31	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:9	34.08	2506	2.03	13.45	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.29	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:9	34.08	2505	2.03	13.44	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.3	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:20:9	34.08	2502	2.03	13.43	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.3	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:0	34.08	2498	2.03	13.43	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.3	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:0	34.08	2495	2.03	13.44	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.32	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:0	34.08	2490	2.03	13.43	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.34	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:0	34.08	2490	2.02	13.43	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.33	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:0	34.08	2489	2.02	13.45	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.31	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:0	34.08	2487	2.02	13.46	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.33	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:1	34.08	2486	2.02	13.45	101	196	Off Idle	66.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.29	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:1	34.08	2485	2.02	13.44	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.29	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:1	34.08	2489	2.02	13.43	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.27	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:1	34.08	2490	2.02	13.42	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.27	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:21:1	34.08	2494	2.02	13.42	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.27	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:21:1	34.08	2496	2.02	13.42	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.27	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:1	34.08	2498	2.02	13.43	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.27	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:2	34.08	2498	2.02	13.42	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.27	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:2	34.08	2500	2.02	13.43	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.26	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:2	34.08	2500	2.02	13.42	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.28	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:21:2	34.08	2499	2.02	13.43	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.27	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:21:2	34.08	2493	2.02	13.44	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.29	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:21:2	34.08	2490	2.02	13.43	101	196	Off Idle	66.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.31	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:3	34.08	2480	2.02	13.43	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.34	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:3	34.08	2486	2.02	13.43	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.31	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:3	34.08	2486	2.02	13.43	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.28	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:3	34.08	2491	2.02	13.43	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.27	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:3	34.08	2494	2.02	13.44	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.27	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:3	34.08	2494	2.02	13.44	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.28	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:4	34.08	2495	2.02	13.44	101	196	Off Idle	67.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.3	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:4	34.08	2489	2.02	13.43	101	196	Off Idle	67.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.29	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:4	34.08	2489	2.02	13.43	101	196	Off Idle	67.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.31	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:21:4	34.08	2488	2.02	13.42	101	196	Off Idle	67.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.3	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:4	34.08	2486	2.02	13.42	101	196	Off Idle	67.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.27	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:4	34.08	2484	2.02	13.42	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.27	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:4	34.08	2476	2.02	13.44	101	196	Off Idle	67	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.3	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:5	34.08	2476	2.02	13.44	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.27	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:5	34.08	2469	2.02	13.43	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.27	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:5	34.08	2473	2.02	13.44	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.27	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:5	34.08	2473	2.02	13.44	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.27	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:5	34.08	2473	2.02	13.45	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.3	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:5	34.08	2480	2.02	13.43	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.3	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:6	34.08	2485	2.02	13.44	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.28	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:6	34.08	2486	2.02	13.44	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.28	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:6	34.08	2489	2.02	13.43	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.27	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:6	34.08	2482	2.02	13.43	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.32	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:6	34.08	2477	2.02	13.43	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.31	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:6	34.08	2477	2.02	13.43	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.34	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:6	34.08	2470	2.02	13.44	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.36	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:7	34.08	2470	2.01	13.44	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.37	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:7	34.08	2471	2.01	13.44	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.36	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:21:7	34.08	2472	2.01	13.45	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.37	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:7	34.08	2477	2.01	13.45	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.37	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:7	34.08	2479	2.01	13.45	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.38	15.15	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:7	34.08	2478	2.01	13.45	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.38	15.19	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:8	34.08	2474	2.01	13.44	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.39	15.2	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:8	34.08	2474	2	13.44	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.42	15.19	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:8	34.08	2474	2	13.44	101	196	Off Idle	67.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.47	15.21	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:8	34.08	2474	2	13.43	101	196	Off Idle	67.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.47	15.21	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:8	34.08	2476	1.99	13.43	101	196	Off Idle	67.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.51	15.19	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:21:8	34.08	2475	1.99	13.44	101	196	Off Idle	67.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.61	15.15	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:21:9	34.08	2474	1.98	13.43	101	196	Off Idle	67.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.7	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:21:9	34.08	2474	1.97	13.43	101	196	Off Idle	67.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.79	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:21:9	34.08	2476	1.95	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.9	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:21:9	34.08	2477	1.93	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.06	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:21:9	34.08	2477	1.92	13.45	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.2	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:20:21:9	34.08	2476	1.91	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.31	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:20:21:9	34.08	2467	1.89	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.39	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:0	34.08	2462	1.88	13.42	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.46	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:0	35.45	2457	1.86	13.42	101	196	Off Idle	68	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.52	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:0	35.45	2464	1.85	13.44	101	196	Off Idle	68	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.58	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:0	35.45	2447	1.83	13.43	101	196	Off Idle	68	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.67	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:0	35.45	2406	1.82	13.43	101	196	Off Idle	68	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.72	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:0	35.45	2406	1.8	13.44	101	196	Off Idle	68	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.78	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:1	35.45	2448	1.79	13.43	101	196	Off Idle	68	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.85	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:1	35.45	2452	1.77	13.43	101	196	Off Idle	68.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.87	14.85	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:20:22:1	35.45	2452	1.75	13.44	101	196	Off Idle	68.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.94	14.86	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:20:22:1	35.45	2452	1.74	13.44	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.96	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:22:1	35.45	2464	1.73	13.43	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.99	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:22:1	35.45	2464	1.72	13.43	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.01	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:20:22:1	35.45	2465	1.72	13.43	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.05	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:20:22:2	35.45	2470	1.71	13.42	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.17	Rich	1	14.6	-9.09	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:2	35.45	2471	1.71	13.41	101	196	Off Idle	68.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.09	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:2	35.45	2467	1.71	13.43	101	196	Off Idle	68.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.08	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:2	35.45	2467	1.7	13.43	101	196	Off Idle	68.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.13	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:2	35.45	2462	1.7	13.43	101	196	Off Idle	68.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.11	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:2	35.45	2454	1.7	13.43	101	196	Off Idle	68.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.13	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:3	35.45	2452	1.7	13.44	101	196	Off Idle	68.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.15	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:3	35.45	2445	1.7	13.45	101	196	Off Idle	68.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.16	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:3	35.45	2444	1.69	13.45	101	196	Off Idle	68.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.16	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:22:3	35.45	2441	1.69	13.45	101	196	Off Idle	68.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.17	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:3	35.45	2437	1.69	13.45	101	196	Off Idle	68.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.18	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:3	35.45	2438	1.68	13.44	101	196	Off Idle	68.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.19	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:4	35.45	2440	1.68	13.43	101	196	Off Idle	68.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.19	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:4	34.08	2428	1.68	13.45	101	196	Off Idle	69	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.19	15.18	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:4	34.08	2447	1.68	13.45	101	196	Off Idle	69.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.19	15.29	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:4	34.08	2448	1.68	13.45	101	196	Off Idle	69.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.17	15.36	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:4	34.08	2448	1.68	13.45	101	196	Off Idle	69.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.21	15.39	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:4	34.08	2449	1.67	13.45	101	196	Off Idle	69.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.22	15.4	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:4	34.08	2449	1.67	13.44	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.22	15.4	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:5	34.08	2448	1.67	13.43	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.24	15.35	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:5	34.08	2440	1.67	13.44	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.25	15.31	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:5	34.08	2434	1.67	13.45	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.25	15.26	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:5	34.08	2435	1.67	13.44	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.25	15.25	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:5	34.08	2436	1.66	13.43	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.28	15.2	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:22:5	34.08	2441	1.66	13.44	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.31	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:22:6	34.08	2441	1.66	13.43	101	196	Off Idle	69.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.33	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:22:6	35.45	2461	1.66	13.42	101	196	Off Idle	69.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.37	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:22:6	35.45	2440	1.66	13.43	101	196	Off Idle	69.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.36	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:22:6	35.45	2440	1.66	13.43	101	196	Off Idle	69.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.36	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:6	35.45	2438	1.65	13.43	101	196	Off Idle	69.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.34	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:6	35.45	2432	1.65	13.44	101	196	Off Idle	69.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.34	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:6	35.45	2432	1.65	13.43	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.3	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:7	35.45	2432	1.65	13.44	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.31	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:7	35.45	2432	1.65	13.43	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.31	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:7	35.45	2431	1.65	13.43	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.32	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:7	35.45	2430	1.65	13.43	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.35	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:7	35.45	2429	1.65	13.44	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.35	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:7	35.45	2433	1.65	13.44	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.34	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:8	34.08	2425	1.65	13.42	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.34	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:8	34.08	2435	1.65	13.45	101	196	Off Idle	69.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.31	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:8	34.08	2433	1.64	13.45	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.31	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:8	34.08	2433	1.64	13.45	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.34	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:8	34.08	2428	1.64	13.44	101	196	Off Idle	70	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.33	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:8	34.08	2428	1.64	13.44	101	196	Off Idle	70	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.32	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:9	35.45	2428	1.65	13.43	101	196	Off Idle	70	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.35	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:9	35.45	2440	1.65	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.34	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:9	35.45	2434	1.65	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.35	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:9	35.45	2433	1.64	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.37	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:9	35.45	2433	1.64	13.44	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.39	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:9	35.45	2430	1.64	13.45	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.41	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:22:9	35.45	2428	1.64	13.45	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.46	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:23:0	35.45	2443	1.64	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.44	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:23:0	35.45	2425	1.64	13.42	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.4	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:0	35.45	2424	1.63	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.43	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:0	35.45	2419	1.63	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.43	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:0	35.45	2419	1.63	13.44	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.41	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:0	35.45	2419	1.63	13.45	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.44	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:1	35.45	2420	1.63	13.46	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.45	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:1	35.45	2420	1.63	13.44	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.46	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:1	35.45	2417	1.62	13.44	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.45	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:1	35.45	2414	1.62	13.44	101	196	Off Idle	70.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.46	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:1	35.45	2411	1.62	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.45	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:1	35.45	2410	1.62	13.44	101	196	Off Idle	70.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.45	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:1	35.45	2412	1.62	13.44	101	196	Off Idle	70.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.44	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:2	35.45	2413	1.61	13.44	101	196	Off Idle	70.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.43	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:2	35.45	2414	1.61	13.45	101	196	Off Idle	70.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.41	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:2	35.45	2420	1.61	13.45	101	196	Off Idle	70.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.43	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:23:2	35.45	2424	1.61	13.44	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.43	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:2	35.45	2425	1.61	13.44	101	196	Off Idle	70.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.45	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:2	35.45	2426	1.61	13.43	101	196	Off Idle	70.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.45	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:3	35.45	2426	1.61	13.44	101	196	Off Idle	70.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.46	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:3	35.45	2420	1.61	13.44	101	196	Off Idle	70.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.48	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:3	35.45	2420	1.61	13.44	101	196	Off Idle	71	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.5	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:3	35.45	2408	1.6	13.45	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.5	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:3	35.45	2414	1.6	13.45	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.52	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:3	35.45	2412	1.6	13.45	101	196	Off Idle	70.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.52	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:4	35.45	2414	1.6	13.46	101	196	Off Idle	70.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.54	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:4	35.45	2405	1.6	13.46	101	196	Off Idle	71	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.53	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:4	35.45	2404	1.59	13.45	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.57	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:4	35.45	2400	1.59	13.45	101	196	Off Idle	71.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:4	35.45	2404	1.59	13.45	101	196	Off Idle	71.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:4	35.45	2406	1.59	13.43	101	196	Off Idle	71.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.57	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:4	35.45	2407	1.59	13.43	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.57	14.9	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:23:5	35.45	2412	1.59	13.42	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.52	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:23:5	35.45	2413	1.6	13.42	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.46	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:23:5	35.45	2413	1.6	13.42	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.45	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:23:5	35.45	2408	1.6	13.46	101	196	Off Idle	71	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.4	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:5	35.45	2405	1.61	13.44	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.35	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:5	35.45	2405	1.61	13.45	101	196	Off Idle	71	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.3	15.16	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:6	35.45	2404	1.62	13.45	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.28	15.19	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:6	35.45	2407	1.63	13.44	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.25	15.2	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:6	35.45	2408	1.63	13.44	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.22	15.19	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:6	35.45	2406	1.64	13.44	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.19	15.18	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:6	35.45	2404	1.64	13.44	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.17	15.18	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:6	34.08	2401	1.65	13.45	101	196	Off Idle	71	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.14	15.17	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:6	34.08	2383	1.66	13.44	101	196	Off Idle	71	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.13	15.17	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:7	34.08	2391	1.67	13.44	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.08	15.14	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:7	34.08	2392	1.68	13.43	101	196	Off Idle	71.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:7	34.08	2395	1.69	13.44	101	196	Off Idle	71.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.91	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:7	34.08	2393	1.7	13.44	101	196	Off Idle	71.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.79	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:7	34.08	2396	1.71	13.45	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.72	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:7	34.08	2396	1.72	13.44	101	196	Off Idle	72	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.67	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:8	34.08	2400	1.73	13.44	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.6	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:8	34.08	2406	1.74	13.43	101	196	Off Idle	72	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.56	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:8	34.08	2410	1.75	13.45	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.53	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:8	34.08	2410	1.75	13.43	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.49	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:8	34.08	2407	1.76	13.42	101	196	Off Idle	71.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.47	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:8	34.08	2421	1.77	13.42	101	196	Off Idle	71.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.47	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:9	34.08	2410	1.77	13.43	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.42	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:9	34.08	2399	1.78	13.41	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.39	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:9	34.08	2395	1.79	13.43	101	196	Off Idle	71.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.4	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:23:9	34.08	2385	1.79	13.45	101	196	Off Idle	71.4	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.36	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:23:9	34.08	2392	1.8	13.45	101	196	Off Idle	71.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.35	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:23:9	34.08	2391	1.81	13.44	101	196	Off Idle	71.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.29	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:23:9	34.08	2392	1.81	13.44	101	196	Off Idle	71.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.26	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:24:0	34.08	2394	1.82	13.42	101	196	Off Idle	71.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.26	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:24:0	34.08	2398	1.82	13.43	101	196	Off Idle	71.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.23	14.75	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:24:0	34.08	2399	1.82	13.42	101	196	Off Idle	71.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.28	14.72	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:24:0	34.08	2401	1.82	13.42	101	196	Off Idle	71.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.28	14.7	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:24:0	34.08	2400	1.82	13.44	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.27	14.68	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:24:0	34.08	2396	1.82	13.45	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.29	14.67	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:24:1	34.08	2394	1.83	13.44	101	196	Off Idle	72	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.28	14.66	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:24:1	34.08	2392	1.83	13.43	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.25	14.66	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:24:1	34.08	2385	1.83	13.44	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.21	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:24:1	34.08	2389	1.83	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.16	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:24:1	34.08	2389	1.84	13.44	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.12	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:24:1	34.08	2394	1.84	13.44	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.06	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:24:1	34.08	2397	1.84	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.03	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:2	34.08	2401	1.85	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:2	34.08	2401	1.85	13.44	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.97	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:2	34.08	2397	1.85	13.44	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.93	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:24:2	34.08	2394	1.86	13.44	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.85	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:24:2	34.08	2389	1.87	13.45	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.82	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:2	34.08	2389	1.87	13.44	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.79	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:3	34.08	2388	1.88	13.43	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.72	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:3	34.08	2389	1.89	13.44	101	196	Off Idle	72.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.7	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:3	34.08	2389	1.9	13.42	101	196	Off Idle	73	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.66	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:3	34.08	2394	1.9	13.42	101	196	Off Idle	73	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:3	34.08	2398	1.91	13.43	101	196	Off Idle	72.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:3	34.08	2399	1.92	13.42	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.57	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:24:4	34.08	2399	1.92	13.42	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.5	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:4	34.08	2396	1.93	13.41	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.48	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:4	34.08	2392	1.94	13.43	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.41	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:4	34.08	2392	1.94	13.42	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.38	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:4	34.08	2390	1.95	13.42	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.31	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:4	34.08	2383	1.96	13.42	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.27	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:4	34.08	2378	1.97	13.42	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.22	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:5	34.08	2379	1.97	13.43	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.23	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:5	34.08	2379	1.98	13.43	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.17	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:5	34.08	2390	1.98	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.15	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:5	34.08	2390	1.98	13.42	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.16	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:5	34.08	2387	1.99	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.13	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:5	32.72	2401	1.99	13.42	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.08	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:6	32.72	2401	1.99	13.43	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.07	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:6	32.72	2397	2	13.43	101	196	Off Idle	72.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.07	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:6	32.72	2391	2	13.43	101	196	Off Idle	72.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.06	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:6	32.72	2391	2	13.43	101	196	Off Idle	72.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.05	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:6	32.72	2385	2	13.43	101	196	Off Idle	72.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.04	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:6	34.08	2396	2.01	13.43	101	196	Off Idle	72.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:6	34.08	2379	2.01	13.43	101	196	Off Idle	72.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.96	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:7	34.08	2378	2.01	13.44	101	196	Off Idle	72.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.96	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:7	34.08	2368	2.01	13.44	101	196	Off Idle	72.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.96	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:7	34.08	2384	2.01	13.44	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.95	15.13	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:7	34.08	2384	2.01	13.43	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.96	15.16	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:7	32.72	2372	2.01	13.44	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.99	15.18	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:7	32.72	2372	2.01	13.44	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.99	15.19	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:8	32.72	2392	2.01	13.42	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.99	15.24	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:8	32.72	2391	2.01	13.42	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.03	15.22	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:8	32.72	2390	2.01	13.42	101	196	Off Idle	72.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.02	15.18	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:8	32.72	2390	2.01	13.43	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.99	15.15	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:24:8	34.08	2388	2.01	13.43	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.03	15.11	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:8	34.08	2400	2.01	13.43	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.01	15.05	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:9	34.08	2384	2.01	13.45	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.99	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:9	34.08	2388	2.01	13.44	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.98	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:24:9	34.08	2388	2.01	13.44	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.96	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:9	34.08	2386	2.01	13.44	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.94	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:9	34.08	2386	2.01	13.44	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.94	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:24:9	34.08	2388	2.01	13.46	101	196	Off Idle	72.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.94	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:24:9	34.08	2388	2.01	13.45	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.97	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:0	34.08	2386	2.01	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.96	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:0	34.08	2388	2.01	13.45	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.93	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:0	34.08	2388	2.01	13.44	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-6.96	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:25:0	34.08	2388	2.01	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.94	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:25:0	34.08	2383	2.01	13.44	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.91	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:25:0	34.08	2384	2.01	13.45	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.93	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:25:1	34.08	2387	2.01	13.46	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.96	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:25:1	34.08	2385	2.02	13.46	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.96	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:25:1	34.08	2386	2.02	13.46	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.95	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:25:1	34.08	2388	2.02	13.45	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.92	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:25:1	32.72	2369	2.02	13.45	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.9	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:25:1	32.72	2369	2.02	13.44	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.85	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:25:1	32.72	2386	2.02	13.44	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.83	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:25:2	32.72	2381	2.02	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.84	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:25:2	32.72	2378	2.03	13.44	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.8	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:2	32.72	2380	2.03	13.43	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.81	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:2	32.72	2383	2.03	13.42	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.78	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:2	34.08	2383	2.03	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.77	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:2	34.08	2385	2.03	13.42	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.76	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:3	34.08	2391	2.03	13.42	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.79	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:3	34.08	2390	2.04	13.42	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.82	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:3	34.08	2391	2.04	13.42	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.8	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:3	34.08	2392	2.04	13.42	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.78	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:3	34.08	2390	2.04	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.76	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:3	34.08	2389	2.05	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.71	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:25:4	34.08	2389	2.05	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.66	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:25:4	34.08	2387	2.05	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.71	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:4	34.08	2388	2.05	13.42	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.67	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:4	34.08	2386	2.05	13.43	101	196	Off Idle	72.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.65	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:4	34.08	2386	2.06	13.42	101	196	Off Idle	72.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.66	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:4	32.72	2374	2.06	13.41	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.65	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:4	32.72	2380	2.06	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.61	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:5	32.72	2380	2.06	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.61	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:5	32.72	2380	2.06	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.57	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:5	32.72	2382	2.06	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.54	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:5	32.72	2387	2.07	13.46	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.54	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:5	32.72	2387	2.07	13.45	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.54	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:5	32.72	2389	2.07	13.44	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.5	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:6	32.72	2391	2.07	13.43	101	196	Off Idle	72.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.51	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:6	32.72	2390	2.07	13.43	101	196	Off Idle	72.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.5	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:25:6	32.72	2390	2.08	13.43	101	196	Off Idle	72.9	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.47	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:25:6	32.72	2389	2.08	13.43	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.44	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:25:6	32.72	2378	2.08	13.44	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.44	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:25:6	32.72	2382	2.08	13.44	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.4	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:25:6	32.72	2384	2.09	13.42	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.39	14.81	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:25:7	32.72	2384	2.09	13.41	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.37	14.8	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:25:7	32.72	2384	2.1	13.42	101	196	Off Idle	72.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.27	14.82	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:25:7	32.72	2396	2.1	13.42	101	196	Off Idle	72.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.23	14.81	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:25:7	32.72	2396	2.1	13.41	101	196	Off Idle	72.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.21	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:25:7	32.72	2386	2.11	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.12	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:25:7	32.72	2391	2.11	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.16	Rich	1	14.6	-6.08	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:25:8	32.72	2389	2.12	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.19	Rich	1	14.6	-6.06	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:25:8	32.72	2389	2.12	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.02	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:25:8	32.72	2390	2.13	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.99	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:25:8	32.72	2391	2.14	13.44	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.91	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:25:8	32.72	2391	2.14	13.44	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.89	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:25:8	32.72	2392	2.15	13.44	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.82	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:25:9	32.72	2392	2.16	13.45	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.8	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:25:9	32.72	2392	2.17	13.44	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.78	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:25:9	32.72	2396	2.17	13.43	101	196	Off Idle	72.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.74	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:25:9	32.72	2398	2.18	13.45	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.68	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:25:9	32.72	2398	2.18	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.63	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:25:9	32.72	2395	2.19	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.56	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:25:9	32.72	2396	2.19	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.51	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:0	32.72	2396	2.2	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.49	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:0	32.72	2396	2.21	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.44	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:0	32.72	2401	2.21	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.41	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:0	32.72	2399	2.22	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.38	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:0	32.72	2397	2.22	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.35	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:0	32.72	2387	2.22	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.37	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:1	32.72	2381	2.23	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.37	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:1	32.72	2381	2.23	13.45	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.35	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:1	32.72	2386	2.23	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.33	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:1	32.72	2386	2.24	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.32	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:1	32.72	2386	2.24	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.27	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:1	32.72	2395	2.24	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.21	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:1	32.72	2400	2.25	13.42	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.2	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:2	32.72	2399	2.25	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.18	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:2	32.72	2399	2.25	13.43	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.19	14.9	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:2	32.72	2392	2.25	13.43	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.19	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:2	32.72	2387	2.25	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.19	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:2	32.72	2388	2.25	13.43	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.21	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:2	32.72	2390	2.25	13.45	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.21	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:3	32.72	2400	2.25	13.44	101	196	Off Idle	72.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.2	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:3	32.72	2404	2.25	13.44	101	196	Off Idle	72.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.17	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:3	32.72	2404	2.25	13.45	101	196	Off Idle	72.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.19	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:3	32.72	2402	2.25	13.44	101	196	Off Idle	72	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.19	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:3	32.72	2400	2.25	13.44	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.15	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:3	32.72	2401	2.25	13.45	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.14	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:4	32.72	2404	2.25	13.44	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.14	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:4	32.72	2398	2.25	13.46	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.11	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:4	32.72	2398	2.26	13.45	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.11	15.06	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:4	32.72	2400	2.25	13.46	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.13	15.11	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:4	32.72	2391	2.26	13.44	101	196	Off Idle	71.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.11	15.12	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:4	32.72	2412	2.26	13.42	101	196	Off Idle	71.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.11	15.12	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:4	32.72	2414	2.26	13.43	101	196	Off Idle	71.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.13	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:5	32.72	2412	2.26	13.43	101	196	Off Idle	71.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.14	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:5	32.72	2405	2.26	13.43	101	196	Off Idle	71.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.15	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:5	32.72	2413	2.26	13.43	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.16	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:5	32.72	2400	2.26	13.44	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.15	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:5	32.72	2404	2.26	13.44	101	196	Off Idle	72	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.12	14.93	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:5	32.72	2404	2.26	13.42	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.1	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:6	32.72	2402	2.26	13.43	101	196	Off Idle	72.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.05	14.8	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:6	32.72	2396	2.26	13.41	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.05	14.78	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:6	32.72	2402	2.27	13.41	101	196	Off Idle	72	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.06	14.78	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:6	32.72	2402	2.27	13.42	101	196	Off Idle	72	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.02	14.77	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:6	32.72	2404	2.27	13.42	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.03	14.78	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:6	32.72	2394	2.27	13.43	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.05	14.79	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:6	32.72	2400	2.27	13.44	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:7	32.72	2400	2.27	13.44	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.98	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:7	32.72	2404	2.28	13.43	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.98	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:7	32.72	2411	2.28	13.43	101	196	Off Idle	72.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.97	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:7	32.72	2428	2.28	13.42	101	196	Off Idle	72	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.98	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:7	32.72	2418	2.28	13.43	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.98	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:7	32.72	2400	2.28	13.44	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.98	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:8	32.72	2397	2.28	13.44	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.95	14.88	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:26:8	32.72	2397	2.28	13.44	101	196	Off Idle	71.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.94	14.88	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:8	32.72	2381	2.29	13.43	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.92	14.93	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:8	32.72	2398	2.29	13.43	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.88	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:8	32.72	2399	2.29	13.44	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.86	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:26:8	32.72	2406	2.29	13.44	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.9	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:9	32.72	2406	2.29	13.44	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.88	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:9	32.72	2403	2.29	13.43	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.88	15.12	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:9	32.72	2403	2.29	13.42	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.91	15.12	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:9	32.72	2405	2.29	13.43	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.91	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:26:9	32.72	2404	2.29	13.42	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.92	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:9	32.72	2404	2.29	13.41	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.95	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:26:9	32.72	2410	2.29	13.42	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.94	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:0	32.72	2409	2.29	13.44	101	196	Off Idle	71.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.9	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:0	32.72	2405	2.29	13.42	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.89	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:0	32.72	2414	2.29	13.43	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.87	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:0	32.72	2406	2.29	13.44	101	196	Off Idle	71.7	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.85	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:0	32.72	2413	2.29	13.44	101	196	Off Idle	71.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.84	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:0	32.72	2413	2.29	13.43	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.83	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:1	32.72	2414	2.29	13.44	101	196	Off Idle	71	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.87	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:1	32.72	2414	2.29	13.43	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.84	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:1	32.72	2414	2.29	13.45	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.89	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:1	32.72	2415	2.29	13.43	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.88	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:1	32.72	2416	2.29	13.44	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.89	14.91	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:27:1	32.72	2416	2.3	13.44	101	196	Off Idle	70.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.89	14.92	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:27:1	32.72	2414	2.3	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-4.87	14.94	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:2	32.72	2415	2.3	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.85	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:2	32.72	2416	2.3	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.83	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:2	32.72	2417	2.3	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.83	15.02	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:2	32.72	2414	2.3	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.87	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:2	32.72	2414	2.3	13.44	101	196	Off Idle	70.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.87	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:2	32.72	2414	2.3	13.44	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.91	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:3	32.72	2418	2.3	13.45	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.92	15.08	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:3	32.72	2420	2.3	13.43	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.95	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:3	32.72	2402	2.3	13.43	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.94	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:3	32.72	2410	2.3	13.44	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.92	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:3	32.72	2412	2.3	13.42	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.91	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:3	32.72	2410	2.3	13.42	101	196	Off Idle	70.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.87	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:4	32.72	2410	2.3	13.43	101	196	Off Idle	70.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.85	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:4	32.72	2412	2.3	13.45	101	196	Off Idle	70.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.86	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:4	32.72	2411	2.3	13.43	101	196	Off Idle	70.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.87	14.75	1	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:4	32.72	2415	2.3	13.43	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.85	14.76	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:4	32.72	2416	2.3	13.41	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.86	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:4	32.72	2421	2.3	13.41	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.85	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:4	32.72	2420	2.3	13.41	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.83	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:5	32.72	2418	2.3	13.41	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.82	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:5	32.72	2414	2.3	13.42	101	196	Off Idle	71	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.82	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:5	32.72	2413	2.3	13.43	101	196	Off Idle	71	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.84	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:5	32.72	2413	2.3	13.42	101	196	Off Idle	71	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.86	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:5	32.72	2412	2.3	13.43	101	196	Off Idle	71	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.87	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:5	32.72	2414	2.3	13.44	101	196	Off Idle	71	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.9	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:6	32.72	2420	2.3	13.43	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.9	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:6	32.72	2430	2.3	13.42	101	196	Off Idle	71.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.9	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:6	32.72	2420	2.3	13.43	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.88	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:6	32.72	2419	2.3	13.44	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.89	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:6	32.72	2419	2.3	13.44	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.88	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:6	32.72	2418	2.3	13.43	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.85	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:6	32.72	2419	2.3	13.43	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.86	14.82	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:7	32.72	2422	2.3	13.43	101	196	Off Idle	71.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.88	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:7	32.72	2422	2.3	13.42	101	196	Off Idle	71	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.87	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:7	32.72	2426	2.3	13.44	101	196	Off Idle	70.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.89	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:7	32.72	2414	2.3	13.44	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.93	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:27:7	32.72	2414	2.3	13.45	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.92	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:27:7	32.72	2432	2.3	13.44	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.9	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:8	32.72	2426	2.3	13.44	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.88	14.95	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:8	32.72	2426	2.3	13.44	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.87	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:8	32.72	2432	2.3	13.44	101	196	Off Idle	70.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.87	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:8	32.72	2421	2.3	13.44	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.89	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:8	32.72	2422	2.3	13.45	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.93	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:8	32.72	2422	2.3	13.45	101	196	Off Idle	70.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.93	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:9	32.72	2419	2.3	13.44	101	196	Off Idle	70.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.88	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:9	32.72	2420	2.3	13.45	101	196	Off Idle	70.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.87	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:9	32.72	2422	2.3	13.45	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.88	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:9	32.72	2420	2.3	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.86	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:27:9	32.72	2417	2.3	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-4.88	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:9	32.72	2409	2.3	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.89	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:27:9	32.72	2409	2.3	13.43	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.89	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:0	32.72	2429	2.3	13.44	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.89	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:0	32.72	2428	2.3	13.43	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.87	14.86	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:0	32.72	2428	2.3	13.43	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.84	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:0	32.72	2438	2.3	13.42	101	196	Off Idle	70.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.83	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:0	32.72	2429	2.3	13.44	101	196	Off Idle	70.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.83	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:0	32.72	2429	2.31	13.44	101	196	Off Idle	70	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.83	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:1	32.72	2430	2.31	13.45	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.86	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:1	32.72	2429	2.31	13.44	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.88	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:1	32.72	2429	2.31	13.45	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.87	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:1	32.72	2429	2.31	13.45	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.84	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:1	32.72	2426	2.31	13.44	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.78	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:28:1	32.72	2429	2.31	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.76	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:28:1	32.72	2432	2.31	13.44	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.72	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:28:2	32.72	2442	2.32	13.42	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.72	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:2	32.72	2445	2.32	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-4.68	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:2	32.72	2445	2.32	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.66	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:2	32.72	2442	2.32	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.65	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:2	32.72	2438	2.33	13.44	101	196	Off Idle	70	0	2	132	944 Turbo	0.58	Lean	1	14.6	-4.63	15.12	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:2	32.72	2435	2.33	13.44	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.66	15.1	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:3	32.72	2435	2.33	13.43	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.64	15.07	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:3	32.72	2430	2.33	13.43	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.63	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:3	32.72	2432	2.34	13.43	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.61	15	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:28:3	32.72	2434	2.34	13.43	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.58	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:28:3	32.72	2440	2.34	13.43	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.52	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:28:3	32.72	2442	2.35	13.42	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.52	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:28:4	32.72	2442	2.35	13.44	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.49	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:28:4	32.72	2439	2.35	13.43	101	196	Off Idle	69.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.5	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:4	32.72	2432	2.35	13.44	101	196	Off Idle	69.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.5	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:4	32.72	2430	2.36	13.44	101	196	Off Idle	69.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.5	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:4	32.72	2428	2.36	13.45	101	196	Off Idle	69.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.48	14.9	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:4	32.72	2424	2.36	13.44	101	196	Off Idle	69.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.5	14.94	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:4	32.72	2427	2.36	13.43	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.48	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:5	32.72	2430	2.36	13.42	101	196	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.47	15	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:5	32.72	2439	2.36	13.42	101	196	Off Idle	70	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.48	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:5	32.72	2447	2.36	13.42	101	196	Off Idle	70	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.5	14.93	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:5	32.72	2447	2.36	13.41	101	196	Off Idle	70	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.51	14.92	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:5	32.72	2454	2.36	13.42	101	196	Off Idle	69.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.48	14.84	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:5	32.72	2438	2.36	13.42	101	196	Off Idle	69.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.47	14.8	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:6	32.72	2435	2.36	13.42	101	196	Off Idle	69.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.48	14.74	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:6	32.72	2437	2.36	13.42	101	196	Off Idle	70	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.46	14.67	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:6	32.72	2439	2.36	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.46	14.64	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:6	32.72	2443	2.36	13.43	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.5	14.56	0.99	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:6	32.72	2445	2.36	13.44	101	196	Off Idle	70.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.52	14.54	0.99	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:6	32.72	2445	2.36	13.44	101	196	Off Idle	70	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.54	14.54	0.99	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:28:6	32.72	2448	2.36	13.44	101	196	Off Idle	70	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.51	14.55	0.99	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:7	32.72	2445	2.36	13.44	101	196	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.5	14.57	0.99	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:7	32.72	2444	2.36	13.45	101	196	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.45	14.61	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:7	32.72	2443	2.36	13.44	101	196	Off Idle	70	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.45	14.66	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:7	32.72	2443	2.36	13.44	101	196	Off Idle	70	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.44	14.68	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:7	32.72	2442	2.36	13.43	101	196	Off Idle	70	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.45	14.72	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:7	32.72	2449	2.36	13.43	101	196	Off Idle	70	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.44	14.76	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:8	32.72	2449	2.36	13.43	101	196	Off Idle	70	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.46	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:8	32.72	2448	2.36	13.43	101	196	Off Idle	69.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.45	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:8	32.72	2448	2.36	13.44	101	196	Off Idle	69.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.46	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:8	32.72	2448	2.37	13.43	101	196	Off Idle	69.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.46	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:8	32.72	2452	2.37	13.42	101	196	Off Idle	70	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.45	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:8	32.72	2456	2.37	13.43	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-4.45	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:9	32.72	2450	2.37	13.43	101	196	Off Idle	69.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.46	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:9	32.72	2450	2.37	13.43	101	196	Off Idle	69.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.43	14.85	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:28:9	32.72	2444	2.37	13.42	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.4	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:9	32.72	2445	2.37	13.43	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.37	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:28:9	32.72	2446	2.37	13.41	101	196	Off Idle	69.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.35	14.91	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:9	32.72	2446	2.38	13.41	101	196	Off Idle	69.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.3	14.92	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:28:9	32.72	2450	2.38	13.42	101	196	Off Idle	69.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.31	14.95	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:0	32.72	2450	2.38	13.43	101	196	Off Idle	69.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.31	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:0	32.72	2450	2.38	13.42	101	196	Off Idle	69.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-4.34	15.05	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:0	32.72	2456	2.38	13.43	101	196	Off Idle	69	0	2	132	944 Turbo	0.61	Lean	1	14.6	-4.36	15.09	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:0	32.72	2449	2.38	13.43	101	196	Off Idle	68.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.35	15.09	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:0	32.72	2453	2.39	13.43	101	196	Off Idle	68.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.36	15.08	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:0	32.72	2462	2.39	13.43	101	196	Off Idle	68.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.34	15.06	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:1	32.72	2448	2.39	13.43	101	196	Off Idle	68.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.31	15.03	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:1	32.72	2445	2.39	13.41	101	196	Off Idle	68.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.27	15.01	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:1	32.72	2445	2.39	13.41	101	196	Off Idle	69	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.27	14.98	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:1	32.72	2449	2.39	13.4	101	196	Off Idle	69.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.24	14.96	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:1	32.72	2452	2.39	13.41	101	196	Off Idle	69.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.25	14.93	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:1	32.72	2454	2.39	13.41	101	196	Off Idle	69.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.26	14.88	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:1	32.72	2460	2.39	13.4	101	196	Off Idle	69.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.25	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:2	32.72	2463	2.39	13.42	101	196	Off Idle	69	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.32	14.88	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:2	32.72	2460	2.39	13.44	101	196	Off Idle	68.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.28	14.88	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:2	32.72	2458	2.39	13.42	101	196	Off Idle	68.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.29	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:2	32.72	2451	2.39	13.42	101	196	Off Idle	69	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.31	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:2	32.72	2451	2.39	13.43	101	196	Off Idle	69	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.3	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:2	32.72	2438	2.39	13.42	101	196	Off Idle	69	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.33	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:3	32.72	2440	2.39	13.42	101	196	Off Idle	69	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.29	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:3	32.72	2454	2.39	13.44	101	196	Off Idle	69	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.31	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:3	32.72	2454	2.39	13.44	101	196	Off Idle	69	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.3	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:3	32.72	2470	2.39	13.44	101	196	Off Idle	69	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.31	14.87	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:3	32.72	2471	2.39	13.43	101	196	Off Idle	68.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.31	14.87	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:3	32.72	2474	2.39	13.43	101	196	Off Idle	68.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.3	14.87	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:4	32.72	2475	2.39	13.44	101	196	Off Idle	68.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.27	14.86	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:4	32.72	2474	2.39	13.44	101	196	Off Idle	68.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.27	14.86	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:4	32.72	2467	2.39	13.43	101	196	Off Idle	68.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.29	14.87	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:4	32.72	2467	2.39	13.44	101	196	Off Idle	68.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.28	14.89	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:4	32.72	2458	2.39	13.43	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.35	14.93	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:4	32.72	2456	2.39	13.42	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.29	14.97	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:4	32.72	2457	2.4	13.41	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.29	15	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:5	32.72	2459	2.4	13.43	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-4.25	15.04	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:5	32.72	2466	2.4	13.43	101	196	Off Idle	68.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-4.25	15.07	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:5	32.72	2472	2.4	13.44	101	196	Off Idle	68.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-4.25	15.11	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:5	32.72	2473	2.4	13.44	101	196	Off Idle	68.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.29	15.16	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:5	32.72	2473	2.4	13.44	101	196	Off Idle	68	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.27	15.22	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:5	32.72	2466	2.4	13.44	101	196	Off Idle	68	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.3	15.23	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:29:6	32.72	2468	2.4	13.45	101	196	Off Idle	68	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.25	15.21	1.04	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:6	32.72	2468	2.4	13.45	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.25	15.16	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:6	32.72	2464	2.4	13.46	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.25	15.12	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:6	32.72	2464	2.4	13.47	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.28	15.1	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:6	32.72	2466	2.4	13.47	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.27	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:6	32.72	2469	2.4	13.45	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.28	15	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:6	32.72	2454	2.4	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.28	14.96	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:7	32.72	2466	2.4	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.27	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:7	32.72	2477	2.4	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.27	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:7	32.72	2477	2.4	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.25	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:29:7	32.72	2475	2.4	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.25	14.89	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:7	32.72	2491	2.4	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.23	14.92	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:7	32.72	2473	2.4	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.26	14.95	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:29:8	32.72	2473	2.4	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.27	14.99	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:8	32.72	2472	2.4	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.27	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:8	32.72	2472	2.4	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.26	15.09	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:8	32.72	2468	2.4	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.26	15.12	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:8	32.72	2471	2.4	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.25	15.12	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:8	32.72	2480	2.4	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.29	15.1	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:9	32.72	2480	2.4	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.29	15.07	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:9	32.72	2481	2.4	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.28	15.06	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:9	32.72	2481	2.4	13.43	101	196	Off Idle	68	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.32	15.01	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:9	32.72	2481	2.4	13.43	101	196	Off Idle	68	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.34	14.98	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:9	32.72	2477	2.4	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.32	14.96	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:9	32.72	2473	2.4	13.43	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.35	14.91	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:29:9	32.72	2473	2.4	13.42	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.36	14.89	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:0	32.72	2479	2.4	13.44	101	196	Off Idle	68.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.34	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:0	32.72	2473	2.4	13.44	101	196	Off Idle	67.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.31	14.83	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:30:0	32.72	2480	2.4	13.45	101	196	Off Idle	67.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-4.33	14.82	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:30:0	32.72	2480	2.4	13.45	101	196	Off Idle	67.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-4.32	14.81	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:30:0	32.72	2482	2.4	13.44	101	196	Off Idle	67.6	0	2	132	944 Turbo	0.25	Rich	1	14.6	-4.33	14.81	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:30:0	32.72	2482	2.4	13.45	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-4.33	14.82	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:30:1	32.72	2481	2.4	13.44	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.19	Rich	1	14.6	-4.36	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:20:30:1	32.72	2481	2.39	13.44	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.16	Rich	1	14.6	-4.35	14.88	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:30:1	32.72	2482	2.39	13.45	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.14	Rich	1	14.6	-4.41	14.9	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:30:1	32.72	2479	2.39	13.45	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.16	Rich	1	14.6	-4.41	14.93	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:30:1	32.72	2479	2.39	13.44	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-4.42	14.96	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:1	32.72	2481	2.39	13.44	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-4.45	15	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:1	32.72	2482	2.39	13.44	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-4.45	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:2	32.72	2484	2.39	13.44	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.49	15.06	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:2	32.72	2484	2.38	13.45	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.54	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:2	32.72	2484	2.38	13.45	101	196	Off Idle	67.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.56	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:2	32.72	2483	2.38	13.45	101	196	Off Idle	67.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.56	15.11	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:2	32.72	2486	2.38	13.46	101	196	Off Idle	67.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.58	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:2	32.72	2486	2.38	13.45	101	196	Off Idle	67.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.61	15.06	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:3	32.72	2484	2.38	13.45	101	196	Off Idle	67.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.6	15.03	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:3	32.72	2486	2.37	13.44	101	196	Off Idle	67.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.61	14.97	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:3	32.72	2484	2.37	13.43	101	196	Off Idle	67.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.62	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:3	32.72	2482	2.37	13.43	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.62	14.92	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:3	32.72	2483	2.37	13.43	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.62	14.91	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:3	32.72	2478	2.37	13.42	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.36	Rich	1	14.6	-4.6	14.82	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:30:4	32.72	2478	2.37	13.43	101	196	Off Idle	66.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.58	14.78	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:30:4	32.72	2482	2.37	13.42	100	196	Off Idle	66.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-4.59	14.74	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:30:4	32.72	2491	2.37	13.42	100	196	Off Idle	66.7	0	2	132	944 Turbo	0.2	Rich	1	14.6	-4.64	14.76	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:30:4	32.72	2492	2.36	13.44	100	196	Off Idle	66.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.64	14.78	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:20:30:4	32.72	2493	2.36	13.43	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.66	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:4	32.72	2495	2.36	13.45	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.66	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:4	32.72	2495	2.36	13.45	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.67	14.9	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:30:5	32.72	2493	2.36	13.43	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.67	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:5	32.72	2492	2.36	13.42	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.71	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:5	32.72	2492	2.36	13.43	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.72	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:5	32.72	2490	2.36	13.44	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-4.71	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:5	32.72	2490	2.36	13.45	101	196	Off Idle	66.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.66	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:5	32.72	2488	2.36	13.44	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.59	Lean	1	14.6	-4.69	15.17	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:6	32.72	2488	2.36	13.44	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.65	Lean	1	14.6	-4.64	15.16	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:6	32.72	2491	2.36	13.44	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.67	15.13	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:6	32.72	2493	2.36	13.44	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.71	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:6	32.72	2493	2.36	13.44	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.74	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:6	32.72	2497	2.36	13.44	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.75	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:6	32.72	2499	2.36	13.43	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.77	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:6	32.72	2499	2.36	13.43	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.76	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:7	32.72	2494	2.36	13.44	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.77	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:7	32.72	2491	2.36	13.43	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.74	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:7	32.72	2491	2.36	13.42	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-4.74	14.75	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:7	32.72	2490	2.36	13.42	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-4.73	14.73	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:7	32.72	2490	2.36	13.42	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.74	14.74	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:7	32.72	2490	2.36	13.43	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.72	14.75	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:8	32.72	2490	2.36	13.44	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.73	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:8	32.72	2492	2.36	13.44	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.71	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:8	32.72	2499	2.36	13.43	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.76	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:8	32.72	2499	2.36	13.43	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.74	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:8	32.72	2500	2.36	13.42	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.8	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:8	32.72	2498	2.35	13.41	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-4.82	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:9	32.72	2498	2.35	13.42	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.85	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:20:30:9	32.72	2496	2.35	13.43	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-4.87	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:30:9	32.72	2494	2.35	13.45	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.96	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:30:9	32.72	2499	2.34	13.45	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.98	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:9	32.72	2500	2.34	13.46	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.02	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:9	32.72	2502	2.34	13.45	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.01	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:30:9	32.72	2500	2.33	13.45	101	196	Off Idle	66.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.12	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:31:0	32.72	2497	2.32	13.45	101	196	Off Idle	66.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.14	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:31:0	32.72	2497	2.32	13.45	101	196	Off Idle	66.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.23	14.97	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:20:31:0	32.72	2496	2.31	13.45	100	196	Off Idle	66.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.27	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:31:0	32.72	2499	2.3	13.44	100	196	Off Idle	66.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.34	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:31:0	32.72	2501	2.3	13.45	101	196	Off Idle	66.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.39	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:31:0	32.72	2502	2.29	13.44	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.47	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:31:1	32.72	2503	2.29	13.44	101	196	Off Idle	66.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.51	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:1	32.72	2503	2.28	13.44	101	196	Off Idle	66	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.59	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:1	32.72	2502	2.27	13.45	101	196	Off Idle	66	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.6	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:31:1	32.72	2501	2.26	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.65	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:31:1	32.72	2502	2.26	13.43	100	196	Off Idle	65.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.71	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:20:31:1	34.08	2511	2.25	13.44	100	196	Off Idle	65.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.77	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:1	34.08	2502	2.25	13.44	100	196	Off Idle	65.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.79	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:2	34.08	2506	2.24	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.84	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:2	34.08	2506	2.23	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.87	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:2	34.08	2507	2.23	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.89	15.19	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:2	34.08	2512	2.22	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.91	15.24	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:2	34.08	2510	2.22	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.99	15.24	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:2	34.08	2509	2.21	13.46	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.02	15.24	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:3	34.08	2504	2.21	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.11	15.22	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:20:31:3	34.08	2498	2.2	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.12	15.22	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:31:3	34.08	2497	2.2	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.13	15.2	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:31:3	34.08	2496	2.2	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.19	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:31:3	34.08	2497	2.19	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.23	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:3	34.08	2497	2.19	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.23	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:4	34.08	2499	2.18	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.31	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:31:4	34.08	2501	2.18	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.32	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:4	34.08	2502	2.17	13.46	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.33	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:4	34.08	2508	2.17	13.46	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.41	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:4	34.08	2507	2.16	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.44	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:31:4	34.08	2507	2.16	13.46	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.44	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:4	34.08	2506	2.15	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.47	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:5	34.08	2511	2.15	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.51	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:5	34.08	2511	2.14	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.52	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:5	34.08	2513	2.14	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.57	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:5	34.08	2512	2.13	13.44	101	196	Off Idle	65.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.58	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:5	34.08	2502	2.13	13.45	101	196	Off Idle	65.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.58	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:5	34.08	2501	2.13	13.45	101	196	Off Idle	65.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.62	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:6	34.08	2503	2.12	13.44	101	196	Off Idle	65.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.66	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:6	34.08	2505	2.12	13.44	101	196	Off Idle	65.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.73	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:6	34.08	2507	2.11	13.47	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.78	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:6	34.08	2507	2.11	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.78	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:31:6	34.08	2489	2.11	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.79	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:6	34.08	2512	2.1	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.79	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:6	34.08	2512	2.1	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.83	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:7	34.08	2509	2.09	13.42	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.85	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:7	34.08	2516	2.09	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.92	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:7	34.08	2516	2.09	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.92	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:7	34.08	2496	2.08	13.42	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.95	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:7	34.08	2496	2.08	13.42	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.95	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:7	34.08	2500	2.08	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.99	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:8	34.08	2500	2.08	13.43	101	196	Off Idle	65.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.96	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:8	34.08	2507	2.07	13.44	101	196	Off Idle	66	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.97	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:8	34.08	2509	2.07	13.45	101	196	Off Idle	66	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.02	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:31:8	34.08	2509	2.07	13.45	101	196	Off Idle	66	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.04	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:31:8	34.08	2512	2.06	13.46	101	196	Off Idle	66	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.09	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:31:8	34.08	2514	2.06	13.45	101	196	Off Idle	66	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.13	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:9	34.08	2514	2.06	13.45	101	196	Off Idle	66	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.13	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:9	34.08	2514	2.05	13.44	101	196	Off Idle	66	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.14	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:9	34.08	2514	2.05	13.44	101	196	Off Idle	66	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.18	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:9	34.08	2508	2.05	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.21	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:31:9	34.08	2506	2.05	13.44	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.22	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:31:9	34.08	2502	2.04	13.44	100	196	Off Idle	65.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.25	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:31:9	34.08	2480	2.04	13.43	100	196	Off Idle	65.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.26	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:32:0	34.08	2480	2.04	13.43	100	196	Off Idle	65.7	0	2	132	944 Turbo	0.17	Rich	1	14.6	-7.26	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:0	34.08	2502	2.03	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.28	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:0	34.08	2504	2.03	13.44	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.27	14.97	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:0	34.08	2524	2.03	13.44	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.31	14.98	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:0	34.08	2515	2.02	13.46	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.34	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:0	34.08	2509	2.02	13.45	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.4	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:1	34.08	2507	2.01	13.46	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.41	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:1	34.08	2506	2.01	13.43	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.47	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:1	34.08	2500	2.01	13.44	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.45	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:1	34.08	2502	2.01	13.44	101	196	Off Idle	65.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.47	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:1	34.08	2500	2	13.45	101	196	Off Idle	65.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.5	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:1	34.08	2500	2	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.49	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:1	34.08	2505	2	13.44	101	196	Off Idle	66	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.49	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:2	34.08	2509	2	13.46	101	196	Off Idle	66	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.51	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:2	34.08	2509	1.99	13.45	101	196	Off Idle	65.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.56	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:2	34.08	2513	1.99	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.58	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:2	34.08	2513	1.99	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.58	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:2	34.08	2507	1.98	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.63	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:2	34.08	2508	1.98	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.63	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:3	34.08	2508	1.98	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.62	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:32:3	34.08	2504	1.98	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.61	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:3	34.08	2505	1.98	13.42	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.58	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:3	34.08	2506	1.98	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.59	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:3	34.08	2510	1.98	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.61	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:3	34.08	2512	1.98	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.63	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:4	34.08	2512	1.98	13.42	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.64	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:4	34.08	2509	1.97	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.66	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:32:4	34.08	2511	1.97	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.62	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:4	34.08	2504	1.97	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.66	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:4	34.08	2504	1.97	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.65	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:4	34.08	2505	1.97	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.65	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:4	34.08	2505	1.97	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.65	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:5	34.08	2505	1.97	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:5	34.08	2502	1.97	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.64	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:5	34.08	2500	1.97	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.63	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:5	34.08	2498	1.97	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.62	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:5	34.08	2500	1.97	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:5	34.08	2503	1.97	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:6	34.08	2504	1.97	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:6	34.08	2506	1.97	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:6	34.08	2506	1.97	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.69	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:6	34.08	2506	1.97	13.46	101	196	Off Idle	65.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.73	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:6	34.08	2508	1.97	13.45	101	196	Off Idle	65.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.73	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:6	34.08	2512	1.97	13.45	101	196	Off Idle	65.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.73	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:6	34.08	2492	1.97	13.45	101	196	Off Idle	65.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.75	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:7	34.08	2492	1.96	13.46	101	196	Off Idle	65.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.75	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:7	34.08	2510	1.96	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	14.79	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:7	34.08	2510	1.96	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	14.76	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:7	34.08	2515	1.96	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.73	14.76	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:32:7	34.08	2525	1.96	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.73	14.77	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:7	34.08	2514	1.96	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.78	14.78	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:8	34.08	2512	1.96	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.75	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:8	34.08	2512	1.96	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.77	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:8	34.08	2509	1.96	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.78	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:8	34.08	2505	1.95	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.79	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:8	34.08	2505	1.95	13.43	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.81	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:8	34.08	2500	1.95	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.86	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:9	34.08	2502	1.95	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.86	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:9	34.08	2504	1.95	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.87	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:9	34.08	2504	1.95	13.45	100	196	Off Idle	65.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.86	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:9	34.08	2506	1.95	13.45	100	196	Off Idle	66	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.85	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:9	34.08	2509	1.94	13.45	100	196	Off Idle	66.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.87	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:9	34.08	2507	1.94	13.45	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.87	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:32:9	34.08	2507	1.94	13.43	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.89	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:33:0	34.08	2504	1.94	13.43	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.9	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:33:0	34.08	2500	1.93	13.44	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.92	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:33:0	34.08	2500	1.93	13.45	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.96	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:33:0	34.08	2500	1.93	13.44	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:33:0	34.08	2503	1.92	13.44	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.02	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:33:0	34.08	2504	1.92	13.45	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.07	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:33:1	34.08	2507	1.92	13.45	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.12	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:33:1	34.08	2508	1.91	13.44	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.2	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:33:1	34.08	2512	1.91	13.44	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.21	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:1	34.08	2510	1.9	13.44	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.23	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:1	35.45	2514	1.9	13.46	101	196	Off Idle	66.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.25	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:1	35.45	2514	1.89	13.44	101	196	Off Idle	66.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.27	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:1	35.45	2501	1.89	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.31	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:2	35.45	2497	1.88	13.41	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.36	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:33:2	35.45	2498	1.87	13.41	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.44	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:33:2	35.45	2501	1.86	13.42	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.47	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:33:2	35.45	2505	1.85	13.43	100	196	Off Idle	65.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.56	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:33:2	35.45	2506	1.85	13.43	100	196	Off Idle	65.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.56	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:33:2	35.45	2511	1.84	13.44	100	196	Off Idle	65.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.62	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:3	35.45	2512	1.83	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.64	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:3	35.45	2515	1.82	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.66	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:3	35.45	2515	1.82	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.67	15.07	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:3	35.45	2514	1.81	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.72	15.07	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:3	35.45	2511	1.81	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.73	15.06	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:3	35.45	2532	1.8	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.77	15.04	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:4	35.45	2520	1.79	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.78	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:4	35.45	2506	1.79	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.82	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:4	35.45	2506	1.78	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.86	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:4	35.45	2506	1.78	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.9	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:4	35.45	2507	1.78	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.88	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:4	35.45	2511	1.77	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.91	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:4	35.45	2510	1.77	13.45	100	196	Off Idle	65.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.93	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:5	35.45	2510	1.76	13.45	100	196	Off Idle	65.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.96	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:5	35.45	2507	1.76	13.44	100	196	Off Idle	65.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.97	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:5	35.45	2503	1.76	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.01	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:5	35.45	2503	1.76	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.02	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:5	35.45	2506	1.75	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.07	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:5	35.45	2509	1.75	13.45	100	196	Off Idle	65.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.09	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:6	35.45	2510	1.75	13.46	100	196	Off Idle	65.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.11	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:6	35.45	2508	1.74	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.13	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:6	35.45	2501	1.74	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.16	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:6	35.45	2502	1.73	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.15	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:33:6	35.45	2502	1.73	13.44	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.15	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:6	35.45	2502	1.73	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.17	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:6	35.45	2502	1.72	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.19	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:7	35.45	2502	1.72	13.44	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.21	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:7	35.45	2498	1.72	13.45	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.24	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:7	35.45	2501	1.71	13.46	101	196	Off Idle	66	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.25	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:7	35.45	2481	1.71	13.44	101	196	Off Idle	66	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.25	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:7	35.45	2490	1.71	13.44	101	196	Off Idle	66	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.26	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:7	35.45	2495	1.7	13.46	101	196	Off Idle	66	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.28	15	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:8	35.45	2495	1.7	13.47	101	196	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.31	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:8	35.45	2495	1.7	13.47	101	196	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.34	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:33:8	35.45	2496	1.7	13.47	101	196	Off Idle	66	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.34	15.03	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:33:8	35.45	2497	1.69	13.46	101	196	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	15.05	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:33:8	35.45	2497	1.69	13.46	100	196	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	15.05	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:8	35.45	2488	1.69	13.45	100	196	Off Idle	66.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.33	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:33:9	35.45	2492	1.68	13.44	101	196	Off Idle	66	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.36	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:33:9	35.45	2492	1.68	13.45	101	196	Off Idle	66	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.37	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:33:9	35.45	2492	1.68	13.44	101	196	Off Idle	66	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.38	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:33:9	35.45	2494	1.67	13.43	100	196	Off Idle	66.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.46	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:33:9	35.45	2495	1.67	13.45	100	196	Off Idle	66.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.48	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:9	35.45	2500	1.66	13.46	100	196	Off Idle	66.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.49	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:33:9	35.45	2501	1.66	13.46	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.53	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:0	35.45	2500	1.66	13.46	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.55	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:0	35.45	2499	1.65	13.46	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.55	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:0	35.45	2500	1.65	13.47	101	196	Off Idle	66.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.56	14.77	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:0	35.45	2499	1.65	13.47	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.58	14.77	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:0	35.45	2498	1.64	13.47	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.56	14.78	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:0	35.45	2498	1.64	13.45	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.56	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:1	35.45	2493	1.64	13.46	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.56	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:1	35.45	2492	1.63	13.45	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.57	14.8	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:34:1	35.45	2497	1.63	13.45	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.61	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:1	35.45	2497	1.63	13.44	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.63	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:1	35.45	2500	1.62	13.45	100	196	Off Idle	66.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.66	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:1	35.45	2505	1.62	13.45	100	196	Off Idle	66.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.66	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:1	35.45	2507	1.62	13.46	100	196	Off Idle	66.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.66	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:2	35.45	2507	1.62	13.44	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.64	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:2	35.45	2508	1.62	13.45	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.6	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:2	35.45	2508	1.62	13.44	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.59	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:2	35.45	2506	1.62	13.45	100	196	Off Idle	66.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.57	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:2	35.45	2505	1.62	13.45	100	196	Off Idle	66.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.58	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:2	35.45	2503	1.62	13.46	100	196	Off Idle	66.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.59	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:3	35.45	2498	1.62	13.47	101	196	Off Idle	66	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.61	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:3	35.45	2489	1.62	13.46	101	196	Off Idle	65.8	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.6	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:3	35.45	2500	1.62	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.6	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:3	35.45	2491	1.62	13.45	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.6	15.08	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:3	35.45	2512	1.62	13.46	101	196	Off Idle	65.7	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.6	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:3	35.45	2512	1.62	13.45	100	196	Off Idle	65.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.61	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:4	35.45	2486	1.62	13.45	100	196	Off Idle	66	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.59	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:4	35.45	2486	1.63	13.46	100	196	Off Idle	66.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.59	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:4	35.45	2483	1.63	13.45	101	196	Off Idle	66.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.6	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:4	35.45	2484	1.63	13.46	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.59	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:4	35.45	2487	1.63	13.45	101	196	Off Idle	66.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.6	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:4	35.45	2488	1.63	13.44	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.61	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:4	35.45	2490	1.63	13.44	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.6	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:5	35.45	2493	1.63	13.44	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.61	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:5	35.45	2491	1.63	13.45	100	196	Off Idle	67.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.62	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:5	35.45	2491	1.62	13.45	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.64	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:5	35.45	2473	1.62	13.45	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.64	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:5	35.45	2473	1.62	13.44	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.65	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:5	35.45	2496	1.62	13.46	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.66	14.85	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:6	35.45	2497	1.62	13.44	100	196	Off Idle	68	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.65	14.87	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:6	35.45	2496	1.62	13.44	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.65	14.89	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:6	35.45	2504	1.62	13.45	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.66	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:6	35.45	2495	1.62	13.43	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.68	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:6	35.45	2496	1.62	13.44	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.68	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:6	35.45	2492	1.61	13.43	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.66	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:6	35.45	2493	1.61	13.45	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.66	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:7	35.45	2492	1.61	13.44	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.63	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:7	35.45	2487	1.61	13.47	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.6	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:7	35.45	2488	1.61	13.45	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.62	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:7	35.45	2488	1.61	13.45	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.64	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:7	35.45	2485	1.61	13.44	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.64	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:7	35.45	2484	1.61	13.44	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.64	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:8	35.45	2486	1.61	13.45	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.66	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:8	35.45	2488	1.61	13.45	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.66	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:8	35.45	2491	1.61	13.45	101	196	Off Idle	67	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.65	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:8	35.45	2493	1.61	13.45	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.66	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:34:8	35.45	2494	1.61	13.45	101	196	Off Idle	67.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.65	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:8	35.45	2494	1.61	13.46	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.61	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:9	35.45	2499	1.61	13.46	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.62	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:9	35.45	2499	1.61	13.46	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.66	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:9	35.45	2498	1.61	13.46	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.66	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:9	35.45	2498	1.61	13.46	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.66	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:9	35.45	2505	1.61	13.47	100	196	Off Idle	67.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.69	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:9	35.45	2505	1.61	13.46	100	196	Off Idle	67.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.7	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:34:9	35.45	2505	1.61	13.47	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.66	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:0	35.45	2499	1.61	13.46	101	196	Off Idle	67	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.66	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:0	35.45	2496	1.61	13.45	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.66	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:35:0	35.45	2486	1.61	13.45	101	196	Off Idle	66.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.69	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:0	35.45	2481	1.61	13.45	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.68	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:0	35.45	2480	1.61	13.45	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.65	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:0	35.45	2481	1.61	13.46	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.66	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:1	35.45	2478	1.61	13.46	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.63	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:1	35.45	2478	1.61	13.45	101	196	Off Idle	66.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.6	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:1	35.45	2478	1.61	13.45	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.6	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:1	35.45	2478	1.61	13.44	100	196	Off Idle	67	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.63	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:1	35.45	2478	1.61	13.45	100	196	Off Idle	67	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.59	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:35:1	35.45	2478	1.61	13.44	100	196	Off Idle	67	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.62	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:35:1	35.45	2476	1.61	13.44	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.58	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:35:2	35.45	2478	1.61	13.44	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.59	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:35:2	35.45	2480	1.61	13.44	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.59	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:35:2	35.45	2488	1.62	13.44	100	196	Off Idle	67.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.59	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:35:2	35.45	2490	1.62	13.45	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.59	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:2	35.45	2493	1.62	13.43	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.6	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:2	35.45	2495	1.62	13.43	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.61	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:3	35.45	2500	1.62	13.45	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.62	14.99	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:3	35.45	2502	1.62	13.45	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.65	14.94	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:3	35.45	2502	1.62	13.45	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.67	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:3	35.45	2496	1.62	13.45	100	196	Off Idle	67.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.66	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:3	35.45	2496	1.62	13.46	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.66	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:3	35.45	2492	1.62	13.45	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.66	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:4	35.45	2486	1.61	13.46	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.64	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:4	35.45	2479	1.61	13.46	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.65	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:4	35.45	2479	1.61	13.45	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.64	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:4	35.45	2472	1.61	13.45	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.62	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:4	35.45	2448	1.61	13.45	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.62	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:4	35.45	2456	1.62	13.44	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.6	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:4	35.45	2464	1.62	13.45	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.6	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:5	35.45	2466	1.62	13.46	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.62	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:5	35.45	2462	1.61	13.45	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.63	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:5	35.45	2461	1.61	13.45	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.62	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:5	35.45	2461	1.61	13.46	101	196	Off Idle	66.9	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.63	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:5	35.45	2471	1.61	13.47	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.64	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:5	35.45	2471	1.61	13.45	100	196	Off Idle	67.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.63	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:6	35.45	2481	1.61	13.45	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.61	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:6	35.45	2486	1.61	13.44	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.62	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:6	35.45	2486	1.61	13.43	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.61	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:6	35.45	2494	1.61	13.44	100	196	Off Idle	68	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.62	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:6	35.45	2496	1.61	13.44	100	196	Off Idle	68	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.64	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:6	35.45	2495	1.61	13.44	100	196	Off Idle	68	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.69	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:6	35.45	2495	1.61	13.45	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.7	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:7	35.45	2498	1.61	13.45	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.71	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:7	35.45	2495	1.61	13.44	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.7	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:7	35.45	2497	1.61	13.44	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.67	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:7	35.45	2497	1.61	13.44	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.67	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:7	35.45	2497	1.6	13.45	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.69	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:7	35.45	2499	1.6	13.46	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.69	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:8	35.45	2498	1.6	13.45	100	196	Off Idle	67.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.74	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:8	35.45	2500	1.6	13.45	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.75	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:8	35.45	2500	1.6	13.45	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.73	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:8	35.45	2497	1.6	13.46	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.7	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:8	35.45	2496	1.6	13.46	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.69	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:8	35.45	2484	1.6	13.47	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.69	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:9	35.45	2478	1.6	13.45	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.69	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:9	35.45	2476	1.6	13.45	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.68	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:9	35.45	2471	1.61	13.46	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.68	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:35:9	35.45	2469	1.61	13.46	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.69	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:9	35.45	2467	1.61	13.47	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.64	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:9	35.45	2467	1.61	13.45	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.64	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:35:9	35.45	2469	1.61	13.45	101	196	Off Idle	66.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.66	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:0	35.45	2485	1.61	13.45	101	196	Off Idle	67.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.64	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:0	35.45	2476	1.61	13.44	100	196	Off Idle	67.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.65	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:0	35.45	2467	1.61	13.45	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.66	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:0	35.45	2466	1.61	13.46	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.66	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:0	35.45	2466	1.61	13.46	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.63	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:0	35.45	2469	1.61	13.44	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.66	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:1	35.45	2474	1.61	13.46	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.63	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:1	35.45	2474	1.61	13.45	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.65	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:1	35.45	2479	1.61	13.45	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.64	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:1	35.45	2456	1.61	13.44	100	196	Off Idle	68	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.66	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:1	35.45	2468	1.6	13.44	100	196	Off Idle	68	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.65	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:1	35.45	2480	1.6	13.45	100	196	Off Idle	68	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.68	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:1	35.45	2481	1.6	13.46	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.67	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:2	35.45	2482	1.6	13.44	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.67	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:2	35.45	2492	1.6	13.44	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.66	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:2	35.45	2492	1.6	13.45	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.69	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:2	35.45	2492	1.6	13.45	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.68	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:2	35.45	2490	1.6	13.45	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.69	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:2	35.45	2488	1.6	13.46	100	196	Off Idle	67.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.69	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:3	35.45	2488	1.6	13.45	100	196	Off Idle	67.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.69	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:3	35.45	2490	1.6	13.44	100	196	Off Idle	67.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.69	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:3	35.45	2483	1.6	13.44	100	196	Off Idle	67.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.67	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:3	35.45	2480	1.6	13.44	100	196	Off Idle	67.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.68	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:3	35.45	2480	1.6	13.45	101	196	Off Idle	67.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.7	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:3	35.45	2478	1.6	13.45	101	196	Off Idle	67.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.72	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:4	35.45	2474	1.6	13.45	101	196	Off Idle	67.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.72	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:4	35.45	2474	1.6	13.46	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.72	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:4	35.45	2474	1.6	13.46	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.72	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:4	35.45	2467	1.6	13.46	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.7	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:4	35.45	2468	1.6	13.46	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.69	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:4	35.45	2468	1.6	13.45	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.71	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:4	35.45	2470	1.6	13.46	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.7	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:5	35.45	2474	1.6	13.45	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.69	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:5	35.45	2475	1.6	13.46	100	196	Off Idle	68	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.68	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:5	35.45	2475	1.6	13.45	100	196	Off Idle	68	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.67	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:5	35.45	2479	1.6	13.45	100	196	Off Idle	68	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.67	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:5	35.45	2480	1.6	13.43	100	196	Off Idle	68	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.7	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:5	35.45	2480	1.6	13.44	100	196	Off Idle	68	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.67	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:6	35.45	2483	1.6	13.43	100	196	Off Idle	68.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.68	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:6	35.45	2490	1.6	13.45	100	196	Off Idle	68	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.66	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:6	35.45	2490	1.6	13.45	100	196	Off Idle	68	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.68	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:6	35.45	2491	1.6	13.46	100	196	Off Idle	68	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.67	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:6	35.45	2494	1.6	13.44	100	196	Off Idle	68	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.7	14.9	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:6	35.45	2492	1.6	13.43	100	196	Off Idle	68	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.71	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:6	35.45	2488	1.59	13.43	100	196	Off Idle	67.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.73	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:7	35.45	2486	1.59	13.43	100	196	Off Idle	67.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.73	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:7	35.45	2482	1.59	13.43	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.74	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:7	35.45	2482	1.6	13.45	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.72	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:7	35.45	2483	1.6	13.46	100	196	Off Idle	67.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.73	15.15	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:7	35.45	2475	1.6	13.47	100	196	Off Idle	67.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.72	15.15	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:7	35.45	2475	1.6	13.46	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.73	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:8	35.45	2475	1.6	13.45	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.72	15.15	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:8	35.45	2473	1.6	13.44	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.7	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:8	35.45	2452	1.6	13.44	100	196	Off Idle	67.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.67	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:36:8	35.45	2462	1.6	13.45	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.66	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:36:8	35.45	2472	1.6	13.45	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.65	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:36:8	35.45	2472	1.6	13.45	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.62	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:9	35.45	2484	1.6	13.45	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.62	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:36:9	35.45	2478	1.61	13.45	100	196	Off Idle	67.2	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.63	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:36:9	35.45	2478	1.61	13.45	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.16	Rich	1	14.6	-9.63	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:36:9	35.45	2480	1.61	13.44	100	196	Off Idle	67.5	0	2	132	944 Turbo	0.12	Rich	1	14.6	-9.63	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:36:9	35.45	2475	1.61	13.46	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.63	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:9	35.45	2489	1.61	13.44	100	196	Off Idle	67.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.65	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:36:9	35.45	2489	1.61	13.44	100	196	Off Idle	67.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.62	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:0	35.45	2493	1.61	13.44	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.63	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:0	35.45	2495	1.61	13.43	101	196	Off Idle	67.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.64	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:0	35.45	2495	1.61	13.43	101	196	Off Idle	67.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.66	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:0	35.45	2494	1.61	13.45	100	196	Off Idle	67.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.66	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:37:0	35.45	2492	1.61	13.45	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.65	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:0	35.45	2490	1.61	13.45	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.66	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:1	35.45	2490	1.61	13.47	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.66	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:1	35.45	2488	1.61	13.47	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.66	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:1	35.45	2464	1.61	13.47	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.66	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:1	35.45	2464	1.61	13.48	100	196	Off Idle	66.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.64	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:1	35.45	2474	1.61	13.48	100	196	Off Idle	66.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.64	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:1	35.45	2468	1.62	13.48	100	196	Off Idle	66.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.61	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:1	35.45	2468	1.62	13.47	100	196	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.6	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:2	35.45	2476	1.62	13.46	100	196	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.58	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:2	35.45	2466	1.62	13.46	100	196	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.6	15.15	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:2	35.45	2467	1.62	13.44	100	196	Off Idle	66.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.59	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:2	35.45	2473	1.62	13.44	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.59	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:2	35.45	2473	1.62	13.43	100	196	Off Idle	66.9	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.58	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:2	35.45	2478	1.62	13.43	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.59	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:3	35.45	2476	1.62	13.45	100	196	Off Idle	67.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.59	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:3	35.45	2476	1.62	13.45	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.62	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:3	35.45	2480	1.62	13.45	100	196	Off Idle	67.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.62	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:3	35.45	2483	1.62	13.45	100	196	Off Idle	67.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.62	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:37:3	35.45	2486	1.61	13.46	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.62	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:37:3	35.45	2490	1.61	13.44	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.67	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:4	35.45	2496	1.61	13.45	100	196	Off Idle	67.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.68	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:4	35.45	2496	1.6	13.45	100	196	Off Idle	67.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.76	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:4	35.45	2498	1.59	13.44	100	196	Off Idle	67.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.81	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:37:4	35.45	2494	1.58	13.45	100	196	Off Idle	67.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.84	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:37:4	35.45	2495	1.58	13.45	100	196	Off Idle	67	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.89	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:37:4	35.45	2497	1.56	13.45	100	196	Full Load	66.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.03	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:37:4	35.45	2496	1.54	13.46	100	196	Idle	66.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10.1	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:37:5	35.45	2490	1.52	13.46	100	196	Idle	66.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-10.14	14.85	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:37:5	35.45	2489	1.5	13.44	100	196	Idle	66.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-10.24	14.84	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:5	35.45	2482	1.48	13.44	100	196	Idle	66.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-10.31	14.84	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:5	35.45	2480	1.46	13.44	100	196	Idle	66.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	-10.37	14.85	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:5	35.45	2469	1.45	13.43	100	196	Idle	66.1	0	2	132	944 Turbo	0.63	Lean	1	14.6	-10.4	14.86	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:5	35.45	2440	1.43	13.43	100	196	Idle	66.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.42	14.86	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:37:6	35.45	2440	1.42	13.44	100	196	Idle	66.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.45	14.87	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:37:6	35.45	2413	1.4	13.44	100	196	Idle	66.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.5	14.87	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:6	32.72	2374	1.39	13.43	100	196	Idle	66.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.51	14.89	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:6	27.27	2363	1.37	13.44	100	196	Idle	66.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.53	14.91	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:6	27.27	2368	1.36	13.44	100	196	Idle	67.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.54	14.91	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:6	21.81	2386	1.35	13.44	100	196	Idle	67.5	0	2	132	944 Turbo	0.67	Rich	1	14.5	-10.55	14.94	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:6	21.81	2434	1.33	13.42	100	196	Idle	67.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.55	14.98	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:37:7	17.72	2434	1.32	13.43	100	196	Idle	67.9	0	2	132	944 Turbo	0.54	Rich	1	14.5	-10.56	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:37:7	17.72	2492	1.31	13.44	100	196	Idle	68.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.56	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:37:7	19.09	2514	1.3	13.44	100	196	Idle	68.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.6	14.82	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:37:7	19.09	2514	1.28	13.46	100	196	Idle	68.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-10.6	14.8	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:7	19.09	2518	1.28	13.46	100	196	Idle	68.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.63	14.77	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:7	19.09	2510	1.28	13.46	100	196	Idle	68.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.65	14.75	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:8	19.09	2495	1.28	13.46	100	196	Idle	68	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.71	14.72	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:8	19.09	2488	1.28	13.46	100	196	Idle	67.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.7	14.68	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:8	19.09	2457	1.28	13.46	100	196	Idle	67.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.74	14.63	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:8	19.09	2437	1.28	13.44	100	196	Idle	67.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.7	14.59	0.99	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:8	19.09	2437	1.28	13.44	100	196	Idle	67.2	0	2	132	944 Turbo	0.05	Lean	1	14.5	-10.68	14.74	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:8	19.09	2422	1.28	13.44	100	196	Idle	66.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.64	14.73	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:9	19.09	2406	1.28	13.45	100	196	Idle	66.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.6	14.73	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:9	19.09	2432	1.28	13.45	100	196	Idle	66.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.58	14.76	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:9	19.09	2437	1.28	13.45	100	196	Idle	66	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.54	14.76	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:9	19.09	2471	1.28	13.45	100	196	Idle	65.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.5	14.78	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:9	19.09	2480	1.28	13.45	100	196	Idle	65.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.46	14.79	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:9	19.09	2494	1.28	13.44	100	195	Idle	65.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.43	14.81	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:37:9	19.09	2494	1.29	13.44	100	195	Idle	64.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.41	14.86	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:0	19.09	2494	1.29	13.44	101	195	Idle	64.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.42	14.91	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:0	19.09	2483	1.3	13.46	101	196	Idle	65.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.41	15.02	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:0	19.09	2483	1.3	13.44	101	196	Idle	65.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	15.12	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:0	19.09	2470	1.31	13.46	100	196	Idle	65.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	15.23	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:0	19.09	2461	1.31	13.46	100	195	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	15.34	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:0	19.09	2458	1.31	13.46	100	195	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	15.54	1.06	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:1	19.09	2448	1.31	13.46	100	196	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	15.69	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:1	19.09	2447	1.32	13.44	100	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	15.82	1.08	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:1	19.09	2438	1.32	13.44	100	196	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	15.91	1.08	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:1	19.09	2452	1.32	13.44	100	196	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	16.02	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:1	19.09	2480	1.32	13.45	100	196	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	16.09	1.1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:1	17.72	2464	1.32	13.45	100	196	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	16.17	1.1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:1	17.72	2482	1.32	13.46	100	196	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	16.28	1.11	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:2	19.09	2475	1.32	13.45	100	196	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	16.43	1.12	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:2	19.09	2475	1.32	13.45	100	196	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	16.76	1.14	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:2	19.09	2475	1.32	13.44	100	196	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	17.1	1.16	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:2	19.09	2467	1.32	13.45	100	196	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	17.49	1.19	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:2	19.09	2462	1.32	13.43	100	196	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.5	-10.34	17.9	1.22	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:2	19.09	2460	1.32	13.44	100	196	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	18.29	1.25	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:3	19.09	2442	1.32	13.43	100	196	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	18.69	1.27	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:3	19.09	2446	1.31	13.43	100	196	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	19.07	1.3	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:3	19.09	2444	1.31	13.43	100	196	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	19.42	1.32	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:3	19.09	2444	1.31	13.45	100	196	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	19.72	1.34	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:3	19.09	2447	1.31	13.43	100	196	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.06	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:3	19.09	2450	1.3	13.45	100	195	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.18	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:4	19.09	2450	1.3	13.45	100	195	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.5	-10.43	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:4	19.09	2455	1.3	13.45	100	195	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:4	19.09	2436	1.3	13.44	100	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:4	19.09	2446	1.29	13.45	100	196	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:4	19.09	2459	1.29	13.45	101	196	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:4	19.09	2457	1.29	13.45	101	195	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:4	19.09	2457	1.29	13.44	101	195	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:5	19.09	2454	1.29	13.44	100	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:5	19.09	2449	1.29	13.44	100	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:5	19.09	2448	1.28	13.44	100	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:5	19.09	2447	1.28	13.44	100	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:5	19.09	2454	1.28	13.44	100	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:5	19.09	2444	1.28	13.44	100	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:6	19.09	2444	1.28	13.45	100	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:6	19.09	2425	1.27	13.45	100	196	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:6	17.72	2425	1.27	13.46	100	196	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:6	17.72	2447	1.27	13.47	100	196	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:38:6	17.72	2450	1.27	13.45	100	196	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:6	17.72	2435	1.27	13.45	100	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:6	17.72	2444	1.27	13.45	100	196	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:7	17.72	2452	1.27	13.45	100	196	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:7	17.72	2453	1.26	13.46	100	196	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:7	17.72	2461	1.26	13.45	100	195	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.5	-10.49	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:7	17.72	2450	1.26	13.45	100	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:7	17.72	2446	1.26	13.45	100	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:7	17.72	2446	1.26	13.46	100	196	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:8	17.72	2444	1.26	13.45	100	196	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:8	17.72	2432	1.25	13.46	100	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:8	17.72	2440	1.25	13.45	100	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:8	17.72	2440	1.25	13.46	100	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.5	-10.51	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:8	17.72	2440	1.25	13.46	100	195	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:8	17.72	2441	1.25	13.45	100	195	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:9	19.09	2460	1.25	13.45	100	196	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:9	19.09	2443	1.25	13.46	100	196	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:9	19.09	2443	1.25	13.46	100	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:9	19.09	2405	1.24	13.45	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:9	19.09	2443	1.24	13.45	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:9	19.09	2460	1.24	13.46	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:38:9	19.09	2450	1.24	13.44	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:0	19.09	2429	1.24	13.46	100	195	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:0	19.09	2433	1.24	13.45	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:0	19.09	2432	1.25	13.44	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:0	19.09	2431	1.25	13.43	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.5	-10.51	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:0	19.09	2430	1.25	13.43	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:0	19.09	2429	1.25	13.43	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:1	17.72	2430	1.25	13.43	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:1	17.72	2433	1.25	13.44	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:1	17.72	2434	1.25	13.44	100	195	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:1	17.72	2439	1.25	13.44	100	196	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:1	17.72	2440	1.25	13.44	100	196	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:1	17.72	2444	1.25	13.43	101	196	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:1	17.72	2441	1.25	13.44	101	195	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:2	19.09	2441	1.25	13.43	101	195	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:2	19.09	2438	1.24	13.44	101	196	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:2	19.09	2432	1.24	13.46	101	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:2	19.09	2446	1.24	13.45	100	196	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:2	19.09	2446	1.24	13.45	100	195	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:2	19.09	2426	1.24	13.47	100	195	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:3	19.09	2423	1.24	13.46	100	195	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:3	19.09	2423	1.24	13.46	100	195	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:3	17.72	2407	1.23	13.48	100	195	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:3	17.72	2428	1.23	13.47	100	195	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:3	17.72	2469	1.23	13.46	100	196	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:3	17.72	2469	1.23	13.45	100	196	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:4	17.72	2434	1.23	13.45	100	196	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:4	17.72	2425	1.23	13.45	100	195	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:4	17.72	2433	1.23	13.45	100	195	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:4	17.72	2441	1.23	13.45	100	195	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:4	17.72	2430	1.23	13.45	100	195	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:4	17.72	2426	1.23	13.45	100	195	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:4	17.72	2426	1.23	13.45	100	195	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:5	17.72	2423	1.23	13.46	100	195	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:5	17.72	2423	1.23	13.46	100	195	Idle	69.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:5	17.72	2426	1.23	13.45	100	195	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.05	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:5	17.72	2426	1.23	13.46	100	195	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:39:5	17.72	2425	1.23	13.46	100	195	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:5	17.72	2424	1.23	13.44	100	195	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:6	17.72	2424	1.23	13.45	100	195	Idle	69.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:6	17.72	2423	1.23	13.45	100	195	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:6	17.72	2421	1.22	13.46	100	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:6	17.72	2421	1.22	13.45	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:6	17.72	2430	1.22	13.45	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:6	17.72	2418	1.22	13.45	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.5	-10.54	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:6	17.72	2418	1.22	13.44	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:7	17.72	2418	1.22	13.44	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:7	17.72	2418	1.22	13.44	100	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:7	17.72	2420	1.22	13.44	100	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:7	17.72	2420	1.22	13.43	100	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:7	17.72	2420	1.22	13.44	100	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:7	17.72	2422	1.22	13.45	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:8	17.72	2422	1.22	13.45	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:8	17.72	2403	1.21	13.44	100	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:8	17.72	2428	1.21	13.45	100	196	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:8	17.72	2453	1.22	13.45	100	196	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:8	17.72	2437	1.22	13.45	100	195	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:8	17.72	2437	1.22	13.47	100	195	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:9	17.72	2436	1.22	13.46	100	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:9	17.72	2428	1.22	13.46	100	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:9	17.72	2428	1.22	13.45	100	195	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:9	17.72	2422	1.22	13.46	100	195	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:9	17.72	2414	1.22	13.45	100	196	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:9	17.72	2414	1.22	13.46	100	196	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:39:9	17.72	2400	1.22	13.46	100	196	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:0	17.72	2406	1.22	13.46	100	196	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:0	17.72	2406	1.22	13.44	100	196	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:0	17.72	2416	1.22	13.44	100	196	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:0	17.72	2408	1.22	13.44	100	196	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:0	17.72	2408	1.22	13.44	100	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:0	17.72	2408	1.22	13.44	100	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:1	17.72	2411	1.22	13.44	100	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:1	17.72	2411	1.22	13.44	100	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:1	17.72	2411	1.22	13.45	100	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:1	17.72	2422	1.22	13.44	100	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:1	17.72	2415	1.21	13.44	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:1	17.72	2418	1.21	13.45	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:1	17.72	2418	1.21	13.45	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.5	-10.57	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:2	17.72	2419	1.21	13.44	100	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:2	17.72	2419	1.21	13.45	100	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:2	17.72	2440	1.21	13.45	100	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:2	17.72	2420	1.21	13.44	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:2	17.72	2419	1.21	13.43	100	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:2	17.72	2419	1.21	13.44	100	195	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:3	17.72	2408	1.21	13.45	100	195	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:3	17.72	2416	1.21	13.45	100	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:3	17.72	2415	1.21	13.44	100	195	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:3	17.72	2430	1.21	13.44	100	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:3	17.72	2405	1.21	13.44	100	195	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:3	17.72	2405	1.21	13.42	100	195	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:4	17.72	2390	1.21	13.43	100	195	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:4	17.72	2395	1.21	13.45	100	195	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:4	17.72	2397	1.21	13.44	100	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:4	17.72	2397	1.21	13.45	100	195	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:4	17.72	2422	1.21	13.45	100	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:40:4	17.72	2407	1.21	13.46	100	195	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:4	17.72	2407	1.21	13.44	100	195	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:5	17.72	2402	1.21	13.45	100	195	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:5	17.72	2414	1.21	13.44	100	195	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:5	17.72	2414	1.21	13.45	100	195	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:5	17.72	2410	1.21	13.44	100	195	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:5	17.72	2427	1.21	13.45	100	195	Full Load	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:5	17.72	2398	1.21	13.45	100	195	Full Load	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:6	17.72	2398	1.22	13.45	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:6	17.72	2382	1.22	13.44	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:6	8.18	2266	1.22	13.45	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:20:40:6	8.18	2336	1.22	13.44	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:20:40:6	10.9	2409	1.22	13.45	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:20:40:6	13.63	2416	1.22	13.44	100	195	Off Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:20:40:6	13.63	2427	1.23	13.45	100	195	Off Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:7	16.36	2427	1.23	13.45	100	195	Off Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:7	19.09	2431	1.23	13.45	100	196	Off Idle	71.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:7	19.09	2435	1.24	13.45	100	196	Off Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:7	21.81	2444	1.24	13.45	100	195	Off Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:7	21.81	2452	1.25	13.46	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:7	24.54	2438	1.25	13.45	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:8	27.27	2434	1.26	13.45	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:8	29.99	2428	1.26	13.45	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:40:8	29.99	2402	1.27	13.45	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:8	32.72	2409	1.28	13.45	100	196	Off Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:8	32.72	2409	1.28	13.45	100	196	Off Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:8	35.45	2400	1.29	13.45	100	196	Off Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:9	35.45	2393	1.29	13.46	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:9	35.45	2408	1.3	13.46	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:9	35.45	2408	1.3	13.46	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:9	35.45	2412	1.31	13.45	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:9	35.45	2430	1.31	13.45	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:9	35.45	2418	1.32	13.45	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:40:9	35.45	2402	1.32	13.44	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:0	35.45	2399	1.32	13.43	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:0	35.45	2399	1.33	13.45	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:0	35.45	2389	1.33	13.44	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:0	35.45	2391	1.34	13.44	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:0	35.45	2391	1.34	13.44	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:0	35.45	2399	1.34	13.45	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:1	35.45	2403	1.34	13.45	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:1	35.45	2412	1.35	13.45	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:1	35.45	2414	1.35	13.44	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:1	35.45	2396	1.35	13.44	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:1	35.45	2414	1.35	13.45	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:1	35.45	2414	1.36	13.44	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.42	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:1	35.45	2406	1.36	13.44	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.42	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:41:2	35.45	2408	1.36	13.43	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.44	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:2	35.45	2390	1.36	13.43	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.43	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:2	35.45	2390	1.36	13.43	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.41	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:2	35.45	2392	1.36	13.44	100	195	Off Idle	72	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.41	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:2	35.45	2390	1.37	13.45	100	195	Off Idle	72	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.42	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:2	35.45	2392	1.37	13.46	100	195	Off Idle	72	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:3	35.45	2399	1.37	13.45	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:3	35.45	2400	1.37	13.44	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:3	35.45	2405	1.37	13.44	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:3	35.45	2405	1.37	13.44	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.36	20.16	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:3	35.45	2409	1.37	13.44	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.34	20.07	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:41:3	35.45	2409	1.37	13.44	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.34	19.95	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:4	35.45	2412	1.37	13.43	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.36	19.77	1.35	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:4	35.45	2420	1.37	13.43	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.38	19.46	1.33	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:4	35.45	2406	1.37	13.43	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.38	19.22	1.31	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:4	35.45	2405	1.37	13.44	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.39	18.98	1.29	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:4	35.45	2405	1.38	13.43	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.39	18.71	1.27	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:4	35.45	2404	1.38	13.43	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.37	18.32	1.25	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:4	35.45	2404	1.38	13.45	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.36	18.07	1.23	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:5	35.45	2400	1.38	13.45	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.35	17.86	1.22	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:5	35.45	2400	1.38	13.44	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.31	17.75	1.21	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:5	35.45	2385	1.38	13.46	100	195	Off Idle	71.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.26	17.57	1.2	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:5	35.45	2401	1.38	13.48	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.27	17.4	1.19	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:5	35.45	2398	1.39	13.46	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.25	17.26	1.18	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:5	35.45	2400	1.39	13.47	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.24	17.14	1.17	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:6	35.45	2399	1.39	13.45	100	195	Off Idle	71.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.24	17.02	1.16	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:6	35.45	2398	1.39	13.44	100	195	Off Idle	71.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.24	16.9	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:41:6	35.45	2396	1.4	13.44	100	195	Off Idle	71.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.2	16.79	1.14	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:6	35.45	2395	1.4	13.44	100	195	Off Idle	71.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.2	16.62	1.13	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:6	35.45	2392	1.4	13.44	100	195	Off Idle	71.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.2	16.52	1.13	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:6	35.45	2391	1.4	13.44	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.19	16.4	1.12	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:6	35.45	2391	1.41	13.45	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.2	16.32	1.11	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:7	35.45	2396	1.41	13.46	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.18	16.32	1.11	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:7	35.45	2409	1.41	13.46	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.13	16.21	1.1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:7	35.45	2409	1.41	13.46	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.12	16.14	1.1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:7	35.45	2410	1.42	13.45	100	195	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.1	16.06	1.09	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:7	35.45	2405	1.42	13.46	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.08	16	1.09	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:7	35.45	2407	1.42	13.45	100	195	Off Idle	71.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.08	15.94	1.09	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:8	35.45	2394	1.43	13.44	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.12	15.89	1.08	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:8	35.45	2416	1.43	13.43	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.11	15.82	1.08	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:8	35.45	2415	1.43	13.45	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.12	15.77	1.07	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:8	35.45	2415	1.44	13.44	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.12	15.74	1.07	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:8	35.45	2424	1.44	13.43	100	195	Off Idle	71.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.09	15.7	1.07	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:8	35.45	2424	1.44	13.44	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.06	15.67	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:9	35.45	2417	1.44	13.44	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.05	15.64	1.07	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:9	35.45	2417	1.44	13.45	100	195	Off Idle	71.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-10.05	15.63	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:9	35.45	2410	1.45	13.44	100	195	Off Idle	71.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-10.01	15.6	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:9	35.45	2408	1.45	13.45	100	195	Off Idle	71.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.02	15.55	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:9	35.45	2404	1.46	13.46	100	195	Off Idle	70.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.01	15.52	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:9	35.45	2407	1.46	13.44	100	195	Off Idle	70.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10	15.49	1.06	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:41:9	35.45	2407	1.46	13.46	100	195	Off Idle	71.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.99	15.47	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:0	35.45	2402	1.47	13.45	100	195	Off Idle	71.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.98	15.43	1.05	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:0	35.45	2398	1.47	13.44	100	195	Off Idle	71.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.98	15.41	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:0	35.45	2398	1.47	13.45	100	195	Off Idle	70.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.97	15.37	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:0	35.45	2386	1.48	13.45	100	195	Off Idle	70.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.95	15.32	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:0	35.45	2390	1.48	13.43	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.95	15.29	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:0	35.45	2395	1.48	13.43	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.93	15.26	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:1	35.45	2394	1.48	13.44	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.91	15.23	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:1	35.45	2397	1.49	13.44	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.91	15.2	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:1	35.45	2406	1.49	13.43	100	195	Off Idle	71.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.91	15.17	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:1	35.45	2410	1.49	13.44	100	195	Off Idle	71.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.89	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:1	35.45	2420	1.49	13.45	100	195	Off Idle	71.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.91	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:1	35.45	2428	1.5	13.45	100	195	Off Idle	71.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.91	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:1	35.45	2421	1.5	13.45	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.92	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:2	35.45	2421	1.5	13.45	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.92	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:2	35.45	2421	1.5	13.46	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.92	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:2	35.45	2416	1.5	13.45	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.93	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:2	35.45	2412	1.5	13.44	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.91	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:2	35.45	2412	1.5	13.44	100	195	Off Idle	71.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.9	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:42:2	35.45	2407	1.51	13.44	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.9	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:3	35.45	2410	1.51	13.44	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.9	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:3	35.45	2408	1.51	13.44	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.88	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:3	35.45	2407	1.51	13.44	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.87	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:3	35.45	2404	1.51	13.44	100	195	Off Idle	71.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.86	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:3	35.45	2405	1.51	13.46	100	195	Off Idle	71.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.85	15.13	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:3	35.45	2405	1.51	13.44	100	195	Off Idle	71.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.87	15.14	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:4	35.45	2392	1.51	13.44	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.87	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:4	35.45	2401	1.51	13.44	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.87	15.16	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:4	35.45	2404	1.5	13.44	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.9	15.19	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:4	35.45	2404	1.5	13.45	101	195	Off Idle	71.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.92	15.19	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:4	35.45	2410	1.5	13.46	101	195	Off Idle	71.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.92	15.19	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:4	35.45	2416	1.5	13.46	101	195	Off Idle	71.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.92	15.18	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:4	35.45	2416	1.5	13.46	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.92	15.17	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:5	35.45	2419	1.5	13.44	100	195	Off Idle	71.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.91	15.15	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:5	35.45	2437	1.5	13.43	100	195	Off Idle	71.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.87	15.14	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:5	35.45	2428	1.5	13.43	100	195	Off Idle	71.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.87	15.12	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:5	35.45	2419	1.5	13.44	100	195	Off Idle	71.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.87	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:42:5	35.45	2419	1.51	13.44	100	195	Off Idle	71.2	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.87	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:5	35.45	2418	1.51	13.45	100	195	Off Idle	70.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.87	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:6	35.45	2412	1.51	13.45	100	195	Off Idle	71	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.88	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:6	35.45	2407	1.51	13.45	100	195	Off Idle	71	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.87	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:6	35.45	2407	1.51	13.44	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.88	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:6	35.45	2403	1.51	13.45	100	195	Off Idle	70.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.86	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:6	35.45	2391	1.51	13.45	100	195	Off Idle	70.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.84	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:6	35.45	2408	1.51	13.46	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.83	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:6	35.45	2408	1.51	13.45	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.83	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:7	35.45	2408	1.51	13.47	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.8	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:7	35.45	2415	1.52	13.45	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.8	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:7	35.45	2416	1.52	13.46	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.79	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:7	35.45	2417	1.52	13.45	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.81	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:7	35.45	2418	1.52	13.43	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.79	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:7	35.45	2418	1.52	13.44	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.79	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:8	35.45	2435	1.53	13.44	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.77	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:8	35.45	2418	1.53	13.44	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.79	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:8	35.45	2419	1.53	13.45	100	195	Off Idle	70.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.79	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:8	35.45	2418	1.53	13.44	100	195	Off Idle	70.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.79	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:8	35.45	2416	1.52	13.43	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.82	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:8	35.45	2413	1.52	13.44	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.82	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:9	35.45	2412	1.52	13.42	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.83	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:9	35.45	2412	1.52	13.41	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.83	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:9	35.45	2402	1.53	13.44	100	195	Off Idle	70.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.8	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:9	35.45	2410	1.53	13.43	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.82	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:9	35.45	2410	1.53	13.44	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.82	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:9	35.45	2411	1.53	13.45	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.82	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:42:9	35.45	2410	1.53	13.44	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.85	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:0	35.45	2412	1.52	13.44	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.84	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:0	35.45	2416	1.52	13.44	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.85	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:0	35.45	2415	1.52	13.44	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.84	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:0	35.45	2414	1.52	13.45	100	195	Off Idle	70.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.83	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:0	35.45	2429	1.52	13.45	100	195	Off Idle	70.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.86	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:0	35.45	2430	1.52	13.44	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.87	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:1	35.45	2432	1.52	13.44	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.87	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:1	35.45	2439	1.52	13.44	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.89	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:1	35.45	2441	1.52	13.44	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.87	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:1	35.45	2442	1.52	13.45	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.87	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:1	35.45	2442	1.52	13.45	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.87	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:1	35.45	2461	1.51	13.46	100	195	Off Idle	70.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.87	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:43:1	35.45	2434	1.51	13.46	100	195	Off Idle	70.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.86	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:2	35.45	2432	1.51	13.46	100	195	Off Idle	70.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.9	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:2	35.45	2430	1.51	13.45	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.91	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:2	35.45	2427	1.51	13.45	100	195	Off Idle	70	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.91	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:2	35.45	2425	1.51	13.44	100	195	Off Idle	70	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.91	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:2	35.45	2424	1.51	13.45	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.9	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:2	35.45	2423	1.51	13.44	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.88	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:3	35.45	2422	1.51	13.46	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.88	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:3	35.45	2422	1.51	13.44	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.89	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:3	35.45	2416	1.52	13.43	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.87	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:3	35.45	2416	1.52	13.43	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.87	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:3	35.45	2415	1.52	13.44	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.87	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:3	35.45	2413	1.52	13.44	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.85	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:4	35.45	2413	1.52	13.46	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.83	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:4	35.45	2409	1.52	13.46	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.84	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:4	35.45	2406	1.52	13.45	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.8	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:4	35.45	2409	1.52	13.45	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.8	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:4	35.45	2402	1.52	13.45	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.81	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:4	35.45	2414	1.52	13.45	100	195	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.79	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:4	35.45	2412	1.52	13.43	100	195	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.79	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:5	35.45	2412	1.52	13.44	100	195	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.81	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:5	35.45	2410	1.52	13.44	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.81	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:5	35.45	2416	1.52	13.44	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.81	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:5	35.45	2416	1.52	13.44	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.84	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:5	35.45	2431	1.52	13.44	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.86	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:5	35.45	2437	1.52	13.43	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.87	15.04	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:6	35.45	2446	1.51	13.42	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.88	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:6	35.45	2431	1.51	13.43	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.9	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:6	35.45	2431	1.51	13.45	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.93	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:6	35.45	2428	1.51	13.44	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.93	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:6	35.45	2425	1.51	13.45	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.93	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:6	35.45	2420	1.51	13.45	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.92	14.93	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:6	35.45	2421	1.51	13.46	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.94	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:7	35.45	2412	1.51	13.44	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.94	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:7	35.45	2421	1.51	13.45	100	195	Off Idle	70.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.91	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:7	35.45	2423	1.51	13.44	100	195	Off Idle	70.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.93	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:7	35.45	2428	1.51	13.46	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.92	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:7	35.45	2428	1.51	13.46	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.91	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:7	35.45	2428	1.51	13.46	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.92	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:8	35.45	2426	1.51	13.45	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.94	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:8	35.45	2423	1.5	13.45	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.92	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:8	35.45	2432	1.5	13.44	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.93	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:8	35.45	2424	1.5	13.44	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.95	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:8	35.45	2422	1.5	13.44	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.95	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:8	35.45	2422	1.5	13.44	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.95	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:9	35.45	2424	1.5	13.44	100	195	Off Idle	70.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.97	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:9	35.45	2430	1.5	13.45	100	195	Off Idle	70.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.98	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:9	35.45	2436	1.5	13.45	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.98	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:43:9	35.45	2436	1.5	13.44	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.99	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:9	35.45	2434	1.5	13.43	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.98	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:9	35.45	2441	1.49	13.44	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.98	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:43:9	35.45	2441	1.49	13.43	100	195	Off Idle	70.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.99	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:0	35.45	2440	1.49	13.45	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.98	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:0	35.45	2440	1.49	13.45	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.99	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:0	35.45	2436	1.49	13.45	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.03	14.92	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:0	35.45	2437	1.49	13.45	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.06	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:0	35.45	2442	1.48	13.45	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.04	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:0	35.45	2442	1.48	13.43	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.05	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:44:1	35.45	2440	1.48	13.42	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.03	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:1	35.45	2439	1.48	13.44	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.01	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:1	35.45	2440	1.48	13.44	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:1	35.45	2436	1.48	13.44	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.02	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:1	35.45	2450	1.48	13.44	100	195	Off Idle	69.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.03	15.05	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:1	35.45	2428	1.48	13.45	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.07	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:1	35.45	2428	1.48	13.45	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.08	15.07	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:2	35.45	2426	1.48	13.45	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.08	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:2	35.45	2402	1.47	13.45	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.07	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:2	35.45	2418	1.47	13.45	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.06	15.01	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:2	35.45	2418	1.47	13.45	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.05	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:2	35.45	2421	1.47	13.45	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.02	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:2	35.45	2421	1.47	13.45	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-10.04	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:3	35.45	2422	1.47	13.45	101	195	Off Idle	70.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-10.01	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:3	35.45	2426	1.47	13.45	101	195	Off Idle	70.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10.02	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:3	35.45	2425	1.47	13.46	101	195	Off Idle	70.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-10.02	14.81	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:3	35.45	2426	1.47	13.46	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.04	14.8	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:3	35.45	2429	1.47	13.43	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.05	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:3	35.45	2435	1.47	13.44	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.08	14.78	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:4	35.45	2434	1.47	13.43	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.06	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:4	35.45	2421	1.47	13.44	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.07	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:4	35.45	2421	1.47	13.43	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.09	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:4	35.45	2438	1.47	13.45	100	195	Off Idle	70.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.08	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:4	35.45	2437	1.47	13.45	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.08	14.8	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:4	35.45	2437	1.47	13.45	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.09	14.8	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:4	35.45	2438	1.47	13.45	100	195	Off Idle	70.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.09	14.8	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:5	35.45	2436	1.47	13.45	100	195	Off Idle	70	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.13	14.8	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:5	35.45	2433	1.46	13.45	100	195	Off Idle	70	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.11	14.81	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:5	35.45	2433	1.46	13.45	100	195	Off Idle	70	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.15	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:5	35.45	2428	1.46	13.44	100	195	Off Idle	70	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.12	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:5	35.45	2424	1.46	13.45	100	195	Off Idle	70	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.1	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:5	35.45	2420	1.46	13.44	100	195	Off Idle	70	0	2	132	944 Turbo	0.48	Lean	1	14.6	-10.1	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:6	35.45	2420	1.47	13.44	100	195	Off Idle	70	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.08	14.9	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:6	35.45	2420	1.47	13.45	101	195	Off Idle	70	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.08	14.95	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:6	35.45	2424	1.47	13.45	101	195	Off Idle	70	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.08	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:6	35.45	2427	1.47	13.45	101	195	Off Idle	70	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.08	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:6	35.45	2430	1.47	13.45	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.04	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:6	35.45	2436	1.47	13.45	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.06	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:6	35.45	2438	1.47	13.42	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.06	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:7	35.45	2437	1.47	13.42	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.08	15.09	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:7	35.45	2433	1.47	13.41	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.09	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:7	35.45	2433	1.47	13.42	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.09	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:7	35.45	2433	1.47	13.41	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.11	15.11	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:7	35.45	2434	1.47	13.42	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.11	15.11	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:7	35.45	2429	1.47	13.44	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.1	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:8	35.45	2428	1.47	13.45	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.1	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:8	35.45	2428	1.47	13.45	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.11	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:8	35.45	2427	1.47	13.46	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.1	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:8	35.45	2430	1.47	13.45	100	195	Off Idle	70.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.1	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:8	35.45	2430	1.47	13.45	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10.12	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:44:8	35.45	2432	1.47	13.46	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.09	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:9	35.45	2432	1.46	13.45	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.1	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:9	35.45	2434	1.46	13.45	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.11	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:9	35.45	2438	1.46	13.46	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.09	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:9	35.45	2442	1.47	13.46	100	195	Off Idle	70.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.09	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:9	35.45	2442	1.46	13.45	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.09	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:9	35.45	2440	1.47	13.46	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.08	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:44:9	35.45	2439	1.47	13.46	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.08	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:45:0	35.45	2442	1.47	13.46	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.09	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:0	35.45	2442	1.47	13.44	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.11	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:0	35.45	2442	1.47	13.45	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.08	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:0	35.45	2443	1.47	13.44	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.09	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:0	35.45	2439	1.47	13.44	100	195	Off Idle	69.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.1	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:0	35.45	2439	1.47	13.46	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.09	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:1	35.45	2440	1.47	13.45	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.08	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:1	35.45	2430	1.47	13.45	100	195	Off Idle	69.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.08	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:1	35.45	2430	1.47	13.43	100	195	Off Idle	69.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.08	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:1	35.45	2427	1.47	13.43	100	195	Off Idle	69.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.05	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:1	35.45	2428	1.47	13.44	100	195	Off Idle	69.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.05	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:1	35.45	2428	1.47	13.44	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.06	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:1	35.45	2430	1.47	13.42	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.07	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:2	35.45	2430	1.48	13.44	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-10.07	14.94	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:2	35.45	2430	1.48	13.44	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.07	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:2	35.45	2434	1.48	13.44	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10.07	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:2	35.45	2440	1.48	13.45	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.05	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:2	35.45	2441	1.48	13.45	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.04	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:2	35.45	2441	1.48	13.44	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.05	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:3	35.45	2447	1.48	13.45	100	195	Off Idle	69.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.04	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:3	35.45	2447	1.48	13.45	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.06	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:3	35.45	2448	1.48	13.46	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.07	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:3	35.45	2452	1.48	13.44	100	195	Off Idle	69.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.08	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:3	35.45	2451	1.48	13.46	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.05	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:3	35.45	2450	1.48	13.45	100	195	Off Idle	69.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.04	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:4	35.45	2442	1.48	13.46	100	195	Off Idle	69.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.04	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:4	35.45	2430	1.48	13.45	100	195	Off Idle	69.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.05	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:4	35.45	2428	1.48	13.45	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.05	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:4	35.45	2428	1.48	13.45	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.07	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:4	35.45	2428	1.48	13.44	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.07	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:4	35.45	2429	1.48	13.44	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.08	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:4	35.45	2431	1.48	13.44	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-10.04	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:5	35.45	2435	1.48	13.43	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.05	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:5	35.45	2437	1.48	13.45	100	195	Off Idle	69.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.06	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:5	35.45	2438	1.48	13.45	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.31	Rich	1	14.6	-10.04	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:5	35.45	2442	1.48	13.44	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.01	14.9	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:5	35.45	2438	1.48	13.44	100	195	Off Idle	69.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.01	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:5	35.45	2441	1.48	13.45	100	195	Off Idle	69.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.99	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:6	35.45	2441	1.48	13.45	100	195	Off Idle	69.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.99	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:6	35.45	2455	1.48	13.43	100	195	Off Idle	69.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.04	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:6	35.45	2450	1.48	13.45	100	195	Off Idle	69.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.06	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:6	35.45	2450	1.48	13.43	100	195	Off Idle	69.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.07	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:6	35.45	2454	1.48	13.44	100	195	Off Idle	69.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.05	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:6	35.45	2436	1.48	13.45	100	195	Off Idle	69.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.05	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:6	35.45	2455	1.48	13.46	100	195	Off Idle	69.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.04	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:7	35.45	2455	1.48	13.47	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.05	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:7	35.45	2458	1.48	13.46	100	195	Off Idle	68.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.03	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:45:7	35.45	2480	1.48	13.46	100	195	Off Idle	68.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.05	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:7	35.45	2471	1.48	13.45	100	195	Off Idle	68.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.02	14.9	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:7	35.45	2460	1.48	13.45	100	195	Off Idle	68.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.02	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:7	35.45	2450	1.48	13.44	100	195	Off Idle	68.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-10.04	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:8	35.45	2450	1.48	13.44	100	195	Off Idle	68.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-10.05	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:8	35.45	2440	1.48	13.45	100	195	Off Idle	68.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-10.07	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:8	35.45	2440	1.48	13.44	100	195	Off Idle	68.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-10.08	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:8	35.45	2439	1.49	13.45	100	195	Off Idle	68.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.07	15.16	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:8	35.45	2440	1.49	13.45	100	195	Off Idle	68.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.08	15.19	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:8	35.45	2438	1.49	13.44	100	195	Off Idle	68.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.07	15.2	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:9	35.45	2435	1.49	13.44	100	195	Off Idle	68.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.04	15.18	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:45:9	35.45	2436	1.49	13.44	100	195	Off Idle	68.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.03	15.17	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:9	35.45	2438	1.49	13.45	100	195	Off Idle	69	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.03	15.14	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:9	35.45	2418	1.49	13.45	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.03	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:9	35.45	2428	1.49	13.44	100	195	Off Idle	69.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-10.02	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:9	35.45	2443	1.49	13.43	101	195	Off Idle	69.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.01	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:45:9	35.45	2449	1.49	13.45	101	195	Off Idle	69.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-10.01	15.12	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:0	35.45	2456	1.49	13.46	101	195	Off Idle	69.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.01	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:0	35.45	2460	1.49	13.46	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.05	15.05	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:0	35.45	2472	1.49	13.46	100	195	Off Idle	69.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.05	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:0	35.45	2478	1.48	13.46	100	195	Off Idle	69.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.05	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:0	35.45	2488	1.48	13.45	100	195	Off Idle	69.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.06	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:0	35.45	2476	1.48	13.45	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.08	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:1	35.45	2474	1.48	13.46	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.1	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:1	35.45	2451	1.48	13.45	100	195	Off Idle	69.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.15	14.88	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:1	35.45	2451	1.47	13.45	100	195	Off Idle	68.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.17	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:46:1	35.45	2465	1.47	13.44	100	195	Off Idle	68.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.19	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:46:1	35.45	2462	1.46	13.44	100	195	Off Idle	68.7	0	2	132	944 Turbo	0.12	Rich	1	14.6	-10.2	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:46:1	35.45	2470	1.46	13.44	100	195	Off Idle	68.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-10.23	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:46:1	35.45	2450	1.45	13.44	100	195	Off Idle	68.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-10.26	14.83	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:46:2	35.45	2444	1.45	13.45	100	195	Off Idle	68.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-10.27	14.84	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:46:2	35.45	2444	1.44	13.45	100	195	Off Idle	68.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-10.3	14.86	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:46:2	35.45	2436	1.43	13.45	100	195	Off Idle	68	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.34	14.89	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:46:2	35.45	2433	1.42	13.46	100	195	Off Idle	68	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.38	14.91	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:46:2	35.45	2434	1.41	13.45	100	195	Full Load	68	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.43	14.95	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:46:2	35.45	2434	1.4	13.44	100	195	Idle	68.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.46	14.98	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:46:3	35.45	2446	1.39	13.44	100	195	Idle	68.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.48	15.01	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:3	35.45	2450	1.38	13.44	100	195	Idle	68.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.5	15.04	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:3	35.45	2453	1.37	13.45	100	195	Idle	68.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.54	15.06	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:3	35.45	2472	1.36	13.45	100	195	Idle	68.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.55	15.07	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:3	35.45	2466	1.34	13.45	100	195	Idle	68.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.57	15.06	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:3	35.45	2464	1.33	13.45	100	195	Idle	68.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.63	15.05	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:4	35.45	2464	1.32	13.45	100	195	Idle	68.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.64	15.07	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:4	35.45	2462	1.31	13.43	100	195	Idle	68.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.68	15.09	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:4	32.72	2421	1.31	13.42	100	195	Idle	68.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.7	15.09	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:4	32.72	2422	1.3	13.43	100	195	Idle	68.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.71	15.08	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:4	27.27	2421	1.29	13.44	100	195	Idle	68.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.73	15.04	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:4	21.81	2413	1.28	13.44	100	195	Idle	68.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-10.73	15.02	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:4	21.81	2440	1.28	13.46	100	195	Idle	68.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-10.72	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:5	19.09	2440	1.27	13.45	100	195	Idle	68.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10.7	14.96	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:5	19.09	2432	1.27	13.46	100	195	Idle	68.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-10.7	14.95	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:5	19.09	2441	1.26	13.45	100	195	Idle	68.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.7	14.92	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:5	19.09	2451	1.26	13.45	100	195	Idle	68.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.67	14.86	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:5	19.09	2443	1.26	13.44	100	195	Idle	68.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.69	14.82	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:5	19.09	2447	1.26	13.44	100	195	Idle	68	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.66	14.77	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:6	19.09	2435	1.26	13.44	100	195	Idle	68	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.64	14.76	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:6	19.09	2435	1.26	13.43	100	195	Idle	68	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.6	14.76	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:6	17.72	2461	1.26	13.43	100	195	Idle	68	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.58	14.75	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:6	17.72	2463	1.27	13.43	100	195	Idle	68	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.56	14.76	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:6	17.72	2472	1.27	13.43	100	195	Idle	68	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.55	14.75	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:6	17.72	2463	1.27	13.44	100	195	Idle	68	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.53	14.75	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:6	17.72	2461	1.27	13.45	100	195	Idle	68	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.51	14.75	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:7	19.09	2451	1.27	13.45	100	195	Idle	68	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.51	14.74	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:7	19.09	2464	1.27	13.45	100	195	Idle	68	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.5	14.76	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:7	19.09	2460	1.28	13.44	100	195	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	14.77	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:7	19.09	2430	1.28	13.46	100	195	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	14.76	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:7	19.09	2430	1.28	13.44	100	195	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	14.75	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:7	19.09	2453	1.28	13.44	100	195	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	14.79	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:8	19.09	2456	1.28	13.45	100	195	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	14.84	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:46:8	19.09	2456	1.28	13.45	100	195	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	14.91	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:8	19.09	2462	1.28	13.44	100	195	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	14.98	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:8	19.09	2462	1.28	13.44	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	15.03	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:8	19.09	2466	1.28	13.45	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	15.19	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:8	19.09	2478	1.28	13.44	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	15.41	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:9	19.09	2466	1.28	13.45	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	15.61	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:9	19.09	2463	1.28	13.45	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	15.87	1.08	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:9	19.09	2463	1.28	13.44	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	16.17	1.1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:9	19.09	2458	1.28	13.45	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	16.55	1.13	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:9	19.09	2456	1.28	13.45	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	17.02	1.16	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:9	19.09	2454	1.28	13.46	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	17.72	1.21	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:46:9	19.09	2451	1.28	13.45	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	18.16	1.24	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:0	19.09	2451	1.28	13.47	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	18.59	1.27	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:0	19.09	2416	1.28	13.46	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	18.99	1.29	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:0	19.09	2416	1.28	13.44	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	19.19	1.31	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:0	19.09	2459	1.28	13.44	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	19.68	1.34	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:0	19.09	2496	1.28	13.45	100	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	19.95	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:0	19.09	2479	1.28	13.44	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.12	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:1	19.09	2466	1.28	13.45	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:1	19.09	2468	1.28	13.45	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:1	19.09	2464	1.28	13.45	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:1	19.09	2462	1.28	13.45	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:1	19.09	2456	1.28	13.44	100	195	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:1	19.09	2456	1.28	13.44	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:1	19.09	2454	1.28	13.44	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:2	19.09	2442	1.28	13.44	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:2	19.09	2452	1.28	13.44	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:2	19.09	2475	1.28	13.44	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:2	19.09	2466	1.28	13.45	100	195	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:2	19.09	2452	1.28	13.46	100	194	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:2	19.09	2465	1.28	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:3	19.09	2465	1.28	13.46	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:3	17.72	2476	1.28	13.46	100	195	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:3	17.72	2476	1.28	13.46	100	195	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:3	19.09	2465	1.28	13.46	100	195	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:3	19.09	2477	1.28	13.45	100	195	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:3	19.09	2454	1.28	13.47	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:4	19.09	2454	1.28	13.45	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:4	19.09	2451	1.28	13.45	100	195	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:4	19.09	2450	1.27	13.44	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:4	19.09	2452	1.27	13.45	100	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:4	17.72	2444	1.27	13.43	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:4	19.09	2459	1.27	13.45	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:4	19.09	2462	1.27	13.45	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:5	19.09	2462	1.27	13.45	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:5	19.09	2462	1.27	13.46	100	195	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:5	19.09	2463	1.27	13.46	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:5	19.09	2461	1.28	13.45	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:5	19.09	2454	1.28	13.44	100	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:5	19.09	2459	1.28	13.45	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:6	19.09	2444	1.28	13.44	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:6	19.09	2444	1.28	13.45	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:6	19.09	2422	1.27	13.45	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:6	19.09	2439	1.27	13.45	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:6	19.09	2441	1.27	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:6	19.09	2442	1.27	13.44	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:6	19.09	2450	1.27	13.43	100	195	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:7	17.72	2456	1.27	13.43	100	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:47:7	17.72	2456	1.27	13.44	100	195	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:7	17.72	2461	1.27	13.45	100	195	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:7	17.72	2464	1.27	13.46	100	195	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:7	17.72	2463	1.27	13.45	100	195	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:7	17.72	2462	1.27	13.45	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:8	17.72	2461	1.27	13.45	100	195	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:8	19.09	2478	1.27	13.44	100	195	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:8	19.09	2455	1.27	13.44	100	195	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:8	19.09	2454	1.27	13.44	100	195	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:8	19.09	2450	1.27	13.45	100	195	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:8	19.09	2449	1.27	13.44	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:9	19.09	2448	1.27	13.45	100	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:9	19.09	2449	1.27	13.45	100	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:9	19.09	2449	1.27	13.44	100	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:9	17.72	2433	1.27	13.43	100	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:9	19.09	2455	1.27	13.46	100	195	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:9	19.09	2455	1.27	13.46	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:47:9	19.09	2459	1.27	13.46	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:0	17.72	2462	1.27	13.46	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:0	17.72	2462	1.27	13.46	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:0	19.09	2460	1.27	13.46	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:0	19.09	2455	1.27	13.47	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:0	19.09	2440	1.27	13.46	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:0	17.72	2445	1.27	13.46	100	195	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:1	17.72	2444	1.27	13.46	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:1	17.72	2442	1.27	13.46	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:1	17.72	2426	1.27	13.45	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:1	17.72	2435	1.27	13.46	100	195	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:1	17.72	2448	1.27	13.46	100	195	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:1	17.72	2453	1.27	13.45	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:1	17.72	2453	1.27	13.44	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:2	19.09	2468	1.27	13.45	100	195	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:2	19.09	2461	1.27	13.45	100	195	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:2	17.72	2462	1.27	13.46	100	195	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:2	17.72	2462	1.27	13.45	100	195	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:2	17.72	2460	1.27	13.46	100	195	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:2	17.72	2458	1.27	13.46	100	195	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:3	17.72	2456	1.27	13.45	100	195	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:3	17.72	2455	1.27	13.46	100	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:3	17.72	2444	1.27	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:3	19.09	2470	1.27	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:3	19.09	2451	1.27	13.45	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:3	19.09	2451	1.27	13.45	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:4	19.09	2466	1.27	13.43	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:4	19.09	2447	1.27	13.44	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:4	19.09	2416	1.27	13.44	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:4	19.09	2416	1.27	13.45	100	194	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:4	19.09	2455	1.27	13.45	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:4	19.09	2494	1.27	13.45	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:4	19.09	2475	1.27	13.45	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:5	19.09	2456	1.27	13.45	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:5	19.09	2454	1.27	13.45	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:5	19.09	2452	1.27	13.45	100	195	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:5	19.09	2437	1.27	13.44	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:5	19.09	2443	1.27	13.46	100	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:5	19.09	2440	1.27	13.46	100	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:6	19.09	2440	1.27	13.46	100	195	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:6	19.09	2419	1.27	13.45	100	195	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:48:6	19.09	2437	1.26	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:6	19.09	2438	1.26	13.44	100	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:6	17.72	2442	1.26	13.42	100	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:6	17.72	2442	1.26	13.43	100	195	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:6	17.72	2427	1.26	13.44	100	195	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:7	17.72	2427	1.26	13.44	100	195	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:7	17.72	2447	1.26	13.43	100	194	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:7	17.72	2449	1.26	13.45	100	194	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:7	17.72	2448	1.26	13.46	100	194	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:7	17.72	2460	1.26	13.46	100	195	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:7	17.72	2454	1.26	13.45	100	195	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:8	17.72	2454	1.26	13.46	100	195	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:8	17.72	2448	1.26	13.45	100	195	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:8	17.72	2458	1.26	13.45	100	195	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:8	17.72	2466	1.26	13.45	100	195	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:8	19.09	2456	1.26	13.45	100	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:8	19.09	2455	1.26	13.44	100	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:9	19.09	2454	1.26	13.45	100	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:9	19.09	2454	1.26	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:9	19.09	2454	1.26	13.46	100	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:9	19.09	2452	1.26	13.45	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:9	19.09	2441	1.26	13.46	100	194	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:9	17.72	2435	1.26	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:48:9	17.72	2435	1.26	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:0	19.09	2454	1.26	13.44	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:0	19.09	2435	1.26	13.45	100	195	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:0	19.09	2435	1.26	13.46	100	195	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:0	19.09	2456	1.26	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:0	19.09	2457	1.26	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:0	19.09	2459	1.26	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:1	19.09	2470	1.26	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:1	19.09	2459	1.26	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:1	19.09	2456	1.26	13.44	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:1	19.09	2445	1.26	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:1	19.09	2457	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:1	19.09	2450	1.27	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:1	19.09	2450	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:2	19.09	2469	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:2	17.72	2439	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:2	17.72	2432	1.27	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:2	17.72	2432	1.27	13.47	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:2	17.72	2447	1.27	13.46	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:2	17.72	2456	1.27	13.45	100	194	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:3	17.72	2447	1.27	13.46	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:3	17.72	2447	1.27	13.45	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:3	19.09	2447	1.27	13.46	100	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:3	19.09	2447	1.27	13.46	100	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:3	17.72	2447	1.27	13.45	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:3	17.72	2447	1.27	13.44	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:4	17.72	2456	1.27	13.43	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:4	17.72	2448	1.27	13.44	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:4	17.72	2438	1.27	13.44	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:4	17.72	2446	1.27	13.44	100	194	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:4	17.72	2448	1.27	13.45	100	194	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:4	17.72	2451	1.26	13.45	100	194	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:4	17.72	2451	1.26	13.45	100	194	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:5	17.72	2444	1.26	13.45	100	194	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:5	17.72	2455	1.26	13.44	100	194	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:49:5	17.72	2455	1.26	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:5	17.72	2466	1.26	13.45	100	194	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:5	17.72	2466	1.26	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:5	17.72	2478	1.26	13.46	100	194	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:6	17.72	2478	1.26	13.45	100	194	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:6	19.09	2458	1.26	13.45	100	194	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:6	19.09	2460	1.26	13.45	100	194	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:6	19.09	2458	1.26	13.45	100	194	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:6	19.09	2456	1.26	13.46	100	194	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:6	19.09	2444	1.26	13.46	100	194	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:6	19.09	2454	1.26	13.46	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:7	19.09	2454	1.26	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:7	17.72	2450	1.26	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:7	17.72	2448	1.26	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:7	17.72	2448	1.26	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:7	17.72	2457	1.26	13.46	100	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:7	17.72	2457	1.26	13.44	100	194	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:8	17.72	2433	1.26	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:8	17.72	2450	1.26	13.43	100	194	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:8	19.09	2468	1.26	13.43	100	194	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:8	17.72	2449	1.26	13.43	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:8	17.72	2452	1.26	13.45	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:8	19.09	2453	1.26	13.46	100	194	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:9	19.09	2454	1.26	13.46	100	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:9	19.09	2456	1.26	13.46	100	194	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:9	19.09	2458	1.26	13.45	100	194	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:9	19.09	2439	1.26	13.45	100	194	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:9	19.09	2439	1.26	13.44	100	194	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:9	19.09	2456	1.25	13.45	100	194	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:49:9	19.09	2474	1.25	13.44	100	194	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:0	19.09	2451	1.26	13.46	100	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:0	19.09	2448	1.26	13.45	100	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:0	19.09	2445	1.26	13.46	100	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:0	19.09	2445	1.26	13.46	100	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:0	19.09	2439	1.26	13.46	100	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:0	19.09	2434	1.26	13.45	100	194	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:1	19.09	2434	1.26	13.46	100	194	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:1	17.72	2430	1.26	13.46	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:1	17.72	2420	1.25	13.45	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:1	17.72	2434	1.25	13.46	100	194	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:1	17.72	2438	1.25	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:1	17.72	2449	1.26	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:1	17.72	2457	1.26	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:2	17.72	2457	1.26	13.46	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:2	17.72	2464	1.26	13.46	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:2	19.09	2477	1.26	13.47	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:2	19.09	2468	1.26	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:2	19.09	2463	1.26	13.47	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:2	19.09	2463	1.26	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:3	19.09	2459	1.26	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:3	19.09	2453	1.26	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:3	19.09	2450	1.26	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:3	17.72	2450	1.26	13.45	100	195	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:3	17.72	2451	1.26	13.46	100	195	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:3	17.72	2451	1.26	13.45	100	195	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:4	17.72	2451	1.26	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:4	17.72	2452	1.26	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:4	17.72	2454	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:50:4	17.72	2455	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:4	17.72	2454	1.27	13.44	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:4	17.72	2446	1.27	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:4	17.72	2462	1.27	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:5	19.09	2470	1.27	13.45	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:5	19.09	2460	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:5	19.09	2449	1.27	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:5	19.09	2450	1.27	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:5	19.09	2451	1.27	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:5	19.09	2452	1.27	13.47	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:6	19.09	2448	1.27	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:6	19.09	2478	1.27	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:6	19.09	2469	1.27	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:6	19.09	2460	1.27	13.47	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:6	17.72	2456	1.27	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:6	17.72	2456	1.27	13.47	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:6	17.72	2444	1.27	13.45	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:7	19.09	2460	1.27	13.45	100	194	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:7	19.09	2460	1.28	13.45	100	194	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:7	19.09	2456	1.28	13.46	100	194	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:7	19.09	2455	1.28	13.45	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:7	19.09	2453	1.28	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:7	19.09	2453	1.28	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:8	19.09	2434	1.28	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:8	19.09	2452	1.28	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:8	17.72	2443	1.28	13.45	101	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:8	17.72	2491	1.28	13.45	101	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:8	17.72	2453	1.28	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:8	17.72	2455	1.28	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:9	17.72	2455	1.28	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:9	17.72	2439	1.28	13.45	101	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:9	17.72	2439	1.28	13.45	101	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:9	17.72	2456	1.28	13.46	101	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:9	17.72	2461	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:9	17.72	2451	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:50:9	17.72	2450	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:0	17.72	2452	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:0	17.72	2416	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:0	17.72	2416	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:0	19.09	2458	1.28	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.24	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:0	19.09	2477	1.28	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:0	17.72	2468	1.28	13.44	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:1	17.72	2461	1.28	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:1	17.72	2468	1.28	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:1	19.09	2454	1.28	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:1	19.09	2454	1.28	13.44	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:1	19.09	2451	1.28	13.43	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:1	19.09	2450	1.28	13.43	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:1	19.09	2453	1.27	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:2	19.09	2444	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:2	19.09	2458	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:2	17.72	2463	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:2	17.72	2464	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:2	17.72	2467	1.27	13.45	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:2	19.09	2490	1.27	13.44	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:3	19.09	2466	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:3	19.09	2466	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:3	19.09	2452	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:51:3	19.09	2459	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:3	19.09	2460	1.27	13.47	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:3	19.09	2456	1.27	13.47	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:4	19.09	2456	1.27	13.47	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:4	19.09	2454	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:4	19.09	2452	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:4	19.09	2443	1.27	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:4	19.09	2454	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:4	19.09	2458	1.27	13.45	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:4	19.09	2458	1.27	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:5	19.09	2469	1.27	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:5	19.09	2452	1.27	13.46	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:5	17.72	2444	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:5	17.72	2444	1.27	13.44	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:5	17.72	2460	1.27	13.43	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:5	17.72	2459	1.27	13.44	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:6	17.72	2466	1.27	13.44	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:6	17.72	2450	1.27	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:6	17.72	2456	1.27	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:6	17.72	2428	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:6	19.09	2440	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:6	19.09	2459	1.27	13.45	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:6	19.09	2467	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:7	19.09	2467	1.27	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:7	19.09	2472	1.27	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:7	19.09	2483	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:7	19.09	2473	1.27	13.44	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:7	19.09	2482	1.27	13.44	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:7	19.09	2471	1.27	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:8	19.09	2468	1.27	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:8	19.09	2468	1.27	13.46	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:8	19.09	2464	1.27	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:8	19.09	2460	1.27	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:8	19.09	2460	1.27	13.44	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:8	19.09	2458	1.27	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:9	19.09	2453	1.27	13.44	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:9	19.09	2450	1.27	13.46	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:9	19.09	2448	1.27	13.47	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:9	19.09	2445	1.27	13.46	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:9	19.09	2443	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:9	19.09	2440	1.27	13.47	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:51:9	19.09	2448	1.27	13.47	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:0	19.09	2438	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:0	19.09	2432	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:0	17.72	2426	1.27	13.46	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:0	17.72	2440	1.27	13.46	100	194	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:0	17.72	2448	1.27	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:0	17.72	2452	1.27	13.45	100	194	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:1	17.72	2466	1.27	13.44	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:1	17.72	2488	1.27	13.44	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:1	17.72	2517	1.26	13.43	100	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:1	17.72	2509	1.26	13.45	100	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:1	17.72	2502	1.26	13.44	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:1	19.09	2501	1.26	13.44	100	194	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:1	19.09	2498	1.26	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:2	19.09	2496	1.26	13.47	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:2	19.09	2474	1.27	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:2	19.09	2470	1.27	13.47	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:52:2	19.09	2460	1.27	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:2	19.09	2444	1.27	13.46	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:2	19.09	2438	1.28	13.46	100	194	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:3	19.09	2436	1.28	13.45	100	194	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:3	19.09	2418	1.28	13.45	100	194	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:3	19.09	2422	1.28	13.44	101	194	Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:3	19.09	2423	1.28	13.44	101	194	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:3	19.09	2410	1.28	13.43	101	194	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:3	17.72	2442	1.29	13.43	100	194	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:4	17.72	2450	1.29	13.43	100	194	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:4	17.72	2452	1.3	13.45	100	194	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:4	17.72	2460	1.3	13.44	100	194	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:4	17.72	2470	1.3	13.45	100	194	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:4	17.72	2471	1.31	13.46	100	194	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:4	17.72	2480	1.31	13.44	100	194	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:4	17.72	2488	1.31	13.44	100	194	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:5	19.09	2459	1.31	13.46	100	194	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:5	19.09	2459	1.31	13.45	100	194	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:5	19.09	2444	1.31	13.45	100	194	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:5	19.09	2452	1.31	13.43	100	194	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:5	19.09	2454	1.31	13.43	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:5	19.09	2466	1.31	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:6	19.09	2463	1.31	13.43	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:6	17.72	2472	1.31	13.44	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:6	17.72	2472	1.31	13.45	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:6	17.72	2471	1.31	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:6	19.09	2490	1.3	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:6	19.09	2480	1.3	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:6	19.09	2477	1.3	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:7	19.09	2475	1.3	13.46	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:7	19.09	2467	1.3	13.46	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:7	19.09	2474	1.3	13.45	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:7	19.09	2450	1.29	13.45	100	194	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:7	19.09	2432	1.29	13.45	100	194	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:7	19.09	2417	1.29	13.45	100	194	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:8	17.72	2436	1.29	13.45	100	194	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:8	17.72	2436	1.29	13.45	100	194	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:8	17.72	2436	1.29	13.45	100	194	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:8	17.72	2421	1.29	13.44	101	194	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:8	17.72	2446	1.29	13.43	101	194	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:8	17.72	2459	1.29	13.45	101	194	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:9	17.72	2486	1.29	13.44	101	194	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:9	19.09	2479	1.3	13.44	101	194	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:9	19.09	2475	1.3	13.45	101	194	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:9	19.09	2496	1.3	13.45	101	194	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:9	19.09	2496	1.3	13.45	100	194	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:9	19.09	2470	1.3	13.45	100	194	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:52:9	19.09	2462	1.3	13.46	100	194	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:0	19.09	2454	1.3	13.45	100	194	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:0	19.09	2454	1.3	13.45	100	194	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:0	19.09	2446	1.3	13.46	100	194	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:0	19.09	2463	1.3	13.44	100	194	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:0	19.09	2444	1.31	13.44	100	194	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:0	19.09	2444	1.31	13.46	100	194	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:1	19.09	2436	1.31	13.46	100	194	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:1	19.09	2436	1.31	13.45	100	194	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:1	19.09	2455	1.31	13.44	100	194	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:1	19.09	2448	1.31	13.45	100	194	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:53:1	19.09	2452	1.31	13.46	100	194	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:1	19.09	2454	1.31	13.45	100	194	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:1	19.09	2458	1.31	13.46	100	194	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:2	19.09	2494	1.31	13.46	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:2	19.09	2475	1.3	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:2	19.09	2476	1.3	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:2	19.09	2473	1.3	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:2	19.09	2468	1.3	13.44	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:2	19.09	2466	1.3	13.44	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:3	19.09	2460	1.3	13.46	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:3	19.09	2430	1.3	13.44	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:3	19.09	2447	1.3	13.45	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:3	19.09	2446	1.29	13.46	100	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:3	19.09	2446	1.29	13.45	100	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:3	19.09	2449	1.29	13.45	100	194	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:4	19.09	2450	1.29	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:4	19.09	2457	1.29	13.44	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:4	19.09	2484	1.29	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:4	19.09	2476	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:4	17.72	2476	1.28	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:4	19.09	2498	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:4	19.09	2473	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:5	19.09	2473	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:5	19.09	2470	1.28	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:5	19.09	2443	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:5	19.09	2450	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:5	19.09	2456	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:5	19.09	2456	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:6	19.09	2458	1.28	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:6	19.09	2471	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:6	19.09	2465	1.28	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:6	19.09	2466	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:6	19.09	2472	1.28	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:6	19.09	2472	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:6	19.09	2470	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:7	19.09	2470	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:7	19.09	2467	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:7	19.09	2458	1.28	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:7	19.09	2456	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:7	19.09	2447	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:7	19.09	2443	1.28	13.45	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:8	19.09	2442	1.28	13.44	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:8	19.09	2445	1.28	13.45	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:8	19.09	2433	1.28	13.45	100	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:8	19.09	2455	1.28	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:8	19.09	2458	1.28	13.46	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:8	19.09	2478	1.28	13.46	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:9	19.09	2474	1.28	13.46	100	194	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:9	19.09	2472	1.28	13.45	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:9	19.09	2472	1.28	13.45	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:9	19.09	2465	1.28	13.46	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:9	19.09	2460	1.28	13.45	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:9	19.09	2458	1.28	13.45	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:53:9	19.09	2452	1.29	13.45	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:0	19.09	2450	1.29	13.44	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:0	19.09	2449	1.29	13.44	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:0	19.09	2449	1.29	13.44	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:0	19.09	2449	1.29	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:54:0	19.09	2442	1.29	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:0	17.72	2456	1.29	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:1	19.09	2458	1.29	13.47	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:1	19.09	2460	1.29	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:1	19.09	2481	1.29	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:1	19.09	2471	1.29	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:1	19.09	2459	1.29	13.43	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:1	19.09	2460	1.29	13.43	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:1	19.09	2459	1.29	13.43	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:2	19.09	2457	1.29	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:2	19.09	2457	1.29	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:2	17.72	2446	1.29	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:2	17.72	2456	1.29	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:2	17.72	2456	1.29	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:2	17.72	2441	1.29	13.46	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:3	17.72	2458	1.29	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:3	17.72	2458	1.29	13.46	100	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:3	17.72	2458	1.29	13.46	100	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:3	19.09	2466	1.29	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:3	17.72	2434	1.29	13.45	100	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:3	17.72	2444	1.29	13.45	101	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:4	17.72	2458	1.28	13.44	101	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:4	17.72	2465	1.28	13.44	101	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:4	17.72	2472	1.28	13.46	100	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:4	17.72	2472	1.28	13.44	100	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:4	17.72	2478	1.28	13.45	100	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:4	17.72	2482	1.28	13.45	100	194	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:4	19.09	2492	1.28	13.45	100	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:5	19.09	2474	1.28	13.46	100	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:5	19.09	2483	1.27	13.46	100	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:5	19.09	2480	1.27	13.45	100	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:5	19.09	2480	1.27	13.45	100	194	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:5	19.09	2462	1.27	13.46	100	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:5	19.09	2460	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:6	19.09	2460	1.27	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:6	19.09	2463	1.27	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:6	19.09	2468	1.27	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:6	19.09	2468	1.27	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:6	19.09	2472	1.27	13.47	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:6	19.09	2474	1.27	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:6	19.09	2470	1.27	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:7	19.09	2470	1.27	13.44	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:7	19.09	2467	1.27	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:7	19.09	2464	1.27	13.45	100	194	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:7	19.09	2457	1.28	13.46	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:7	19.09	2456	1.28	13.45	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:7	19.09	2450	1.28	13.44	100	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:8	19.09	2450	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:8	19.09	2444	1.28	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:8	19.09	2445	1.28	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:8	19.09	2446	1.28	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:8	19.09	2429	1.28	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:8	19.09	2429	1.28	13.46	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:9	19.09	2451	1.28	13.45	100	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:9	19.09	2456	1.28	13.45	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:9	19.09	2458	1.28	13.46	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:9	19.09	2460	1.28	13.46	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:9	19.09	2465	1.28	13.44	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:54:9	19.09	2468	1.28	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:54:9	19.09	2468	1.28	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:0	19.09	2472	1.28	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:0	19.09	2491	1.28	13.44	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:0	19.09	2482	1.28	13.44	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:0	19.09	2473	1.28	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:0	19.09	2471	1.28	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:0	19.09	2468	1.28	13.44	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:1	19.09	2466	1.28	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:1	19.09	2460	1.28	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:1	19.09	2455	1.28	13.44	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:1	19.09	2452	1.28	13.44	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:1	19.09	2448	1.28	13.45	100	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:1	19.09	2426	1.28	13.44	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:1	17.72	2434	1.28	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:2	19.09	2440	1.28	13.44	100	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:2	19.09	2439	1.28	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:2	19.09	2439	1.28	13.45	100	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:2	19.09	2439	1.28	13.45	100	194	Full Load	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:2	19.09	2378	1.28	13.45	100	194	Off Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:2	9.54	2459	1.28	13.44	100	194	Off Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:3	12.27	2462	1.29	13.45	100	194	Off Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:3	12.27	2468	1.29	13.46	100	194	Off Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:3	14.99	2471	1.29	13.45	100	194	Off Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:3	17.72	2484	1.3	13.45	100	194	Off Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:20:55:3	17.72	2482	1.31	13.46	100	194	Off Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:55:3	20.45	2487	1.31	13.45	100	194	Off Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:55:4	23.18	2487	1.32	13.46	100	194	Off Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:55:4	23.18	2488	1.33	13.44	100	194	Off Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:55:4	25.9	2488	1.33	13.45	100	194	Off Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:55:4	25.9	2488	1.34	13.45	100	194	Off Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:55:4	28.63	2500	1.36	13.46	100	194	Off Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:55:4	31.36	2481	1.38	13.46	100	194	Off Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:55:4	34.08	2481	1.39	13.46	100	194	Off Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:20:55:5	34.08	2497	1.41	13.46	100	194	Off Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:55:5	35.45	2470	1.43	13.47	100	194	Off Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:55:5	35.45	2468	1.44	13.46	100	194	Off Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:55:5	35.45	2478	1.45	13.46	100	194	Off Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:55:5	35.45	2467	1.47	13.45	100	194	Off Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:55:5	35.45	2467	1.49	13.44	100	194	Off Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:55:6	35.45	2474	1.5	13.44	100	194	Off Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:55:6	35.45	2458	1.51	13.44	100	194	Off Idle	68	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:20:55:6	35.45	2468	1.52	13.43	100	194	Off Idle	68	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.88	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:55:6	35.45	2468	1.53	13.42	100	194	Off Idle	68	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.86	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:55:6	35.45	2460	1.54	13.43	100	194	Off Idle	68	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:55:6	35.45	2465	1.55	13.44	100	194	Off Idle	68.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:55:6	35.45	2465	1.56	13.45	100	194	Off Idle	68.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:55:7	35.45	2441	1.57	13.43	100	194	Off Idle	68.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:55:7	35.45	2442	1.58	13.45	100	193	Off Idle	68.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:55:7	35.45	2426	1.58	13.44	100	193	Off Idle	68.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:55:7	35.45	2436	1.59	13.43	100	194	Off Idle	68.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:20:55:7	35.45	2458	1.6	13.45	100	194	Off Idle	68.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:55:7	35.45	2464	1.6	13.45	100	194	Off Idle	68.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:55:8	35.45	2464	1.61	13.46	100	193	Off Idle	68.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.54	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:20:55:8	35.45	2494	1.62	13.46	100	193	Off Idle	68.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.47	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:55:8	35.45	2482	1.63	13.46	100	193	Off Idle	68.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.4	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:55:8	35.45	2482	1.64	13.45	100	193	Off Idle	68.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.35	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:20:55:8	35.45	2484	1.65	13.47	100	193	Off Idle	68.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.28	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:55:8	35.45	2492	1.66	13.46	100	193	Off Idle	68.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.26	20.21	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:20:55:9	35.45	2495	1.67	13.46	100	194	Off Idle	68.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.2	20.14	1.37	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:20:55:9	35.45	2496	1.68	13.46	100	194	Off Idle	68.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.14	20	1.36	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:55:9	35.45	2499	1.7	13.45	100	194	Off Idle	68.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.09	19.83	1.35	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:55:9	35.45	2499	1.71	13.44	100	194	Off Idle	68.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.09	19.5	1.33	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:55:9	35.45	2495	1.72	13.45	100	194	Off Idle	68.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.06	19.25	1.31	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:55:9	35.45	2494	1.73	13.46	100	193	Off Idle	68.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.05	18.97	1.29	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:55:9	35.45	2482	1.74	13.46	100	193	Off Idle	67.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.99	18.68	1.27	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:56:0	35.45	2471	1.74	13.45	100	193	Off Idle	67.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.94	18.38	1.25	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:56:0	35.45	2469	1.75	13.44	100	194	Off Idle	67.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.84	18.22	1.24	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:56:0	35.45	2458	1.76	13.43	100	194	Off Idle	67.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.82	17.89	1.22	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:56:0	35.45	2454	1.78	13.42	100	194	Off Idle	67.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.75	17.48	1.19	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:20:56:0	35.45	2461	1.78	13.44	100	194	Off Idle	67.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.75	17.26	1.18	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:0	35.45	2461	1.79	13.44	100	194	Off Idle	67.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.71	17.07	1.16	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:1	35.45	2466	1.79	13.44	100	194	Off Idle	67.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.68	16.9	1.15	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:1	35.45	2473	1.8	13.45	100	194	Off Idle	67.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.62	16.74	1.14	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:1	35.45	2476	1.8	13.46	100	194	Off Idle	67.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.61	16.59	1.13	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:1	35.45	2481	1.81	13.46	100	194	Off Idle	67.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.58	16.4	1.12	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:1	35.45	2484	1.81	13.47	100	194	Off Idle	67.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.6	16.28	1.11	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:1	35.45	2484	1.81	13.47	100	194	Off Idle	67.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.61	16.23	1.11	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:1	35.45	2487	1.82	13.45	100	194	Off Idle	67.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.58	16.08	1.1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:2	35.45	2474	1.82	13.45	100	194	Off Idle	68	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.59	16.04	1.09	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:2	35.45	2497	1.82	13.46	100	194	Off Idle	67.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.57	15.91	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:2	35.45	2497	1.83	13.44	100	194	Off Idle	67.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.52	15.84	1.08	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:2	35.45	2489	1.83	13.44	100	193	Off Idle	67.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.47	15.77	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:2	35.45	2484	1.84	13.46	100	193	Off Idle	67.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.44	15.7	1.07	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:2	35.45	2488	1.84	13.44	100	193	Off Idle	67.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.42	15.62	1.06	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:3	35.45	2465	1.84	13.44	100	193	Off Idle	67.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.41	15.57	1.06	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:3	35.45	2458	1.85	13.45	100	193	Off Idle	67.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.42	15.53	1.06	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:3	35.45	2456	1.85	13.44	100	194	Off Idle	67.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.4	15.5	1.06	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:3	35.45	2459	1.85	13.44	100	194	Off Idle	67.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.36	15.47	1.05	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:3	35.45	2464	1.85	13.46	100	194	Off Idle	67.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.33	15.43	1.05	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:3	35.45	2471	1.86	13.46	100	193	Off Idle	67.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.34	15.4	1.05	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:4	35.45	2471	1.86	13.45	100	193	Off Idle	67.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.31	15.39	1.05	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:4	35.45	2465	1.86	13.47	100	193	Off Idle	67.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.36	15.36	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:4	35.45	2490	1.86	13.46	100	193	Off Idle	67.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.4	15.32	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:4	35.45	2492	1.86	13.45	100	193	Off Idle	67.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.41	15.3	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:4	35.45	2492	1.86	13.46	100	193	Off Idle	68.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.44	15.27	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:4	35.45	2489	1.86	13.45	100	193	Off Idle	68.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.41	15.24	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:4	35.45	2486	1.86	13.45	100	193	Off Idle	67.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.38	15.21	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:5	35.45	2485	1.86	13.45	100	193	Off Idle	67.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.34	15.19	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:5	35.45	2484	1.86	13.46	100	193	Off Idle	67.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.34	15.16	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:5	35.45	2480	1.87	13.43	100	193	Off Idle	67.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.32	15.15	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:5	35.45	2476	1.87	13.44	100	193	Off Idle	67.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.33	15.13	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:5	35.45	2476	1.87	13.44	100	193	Off Idle	67.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.33	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:5	35.45	2480	1.87	13.44	100	193	Off Idle	67	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.34	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:6	35.45	2489	1.87	13.42	100	193	Off Idle	67.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.33	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:6	35.45	2483	1.87	13.45	100	193	Off Idle	67.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.33	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:20:56:6	35.45	2483	1.87	13.45	100	193	Off Idle	66.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.35	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:6	35.45	2485	1.87	13.44	100	193	Off Idle	66.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.32	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:6	35.45	2485	1.87	13.44	100	194	Off Idle	66.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.31	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:6	35.45	2479	1.87	13.42	100	194	Off Idle	66.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.28	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:6	35.45	2479	1.87	13.43	100	194	Off Idle	67.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.27	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:7	35.45	2482	1.87	13.42	100	193	Off Idle	67.2	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.22	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:7	35.45	2482	1.88	13.44	100	193	Off Idle	67.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.21	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:7	35.45	2489	1.88	13.44	100	193	Off Idle	67.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.22	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:7	34.08	2461	1.88	13.45	100	194	Off Idle	67.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.2	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:7	34.08	2471	1.88	13.46	100	194	Off Idle	67.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.17	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:56:7	34.08	2485	1.89	13.45	100	194	Off Idle	67.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.19	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:8	34.08	2486	1.89	13.45	100	193	Off Idle	67.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.16	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:8	34.08	2494	1.89	13.45	100	193	Off Idle	67.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.15	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:8	34.08	2494	1.89	13.45	100	193	Off Idle	67.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.13	14.9	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:8	34.08	2498	1.89	13.44	100	194	Off Idle	68.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.13	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:8	34.08	2503	1.9	13.45	100	194	Off Idle	67.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.1	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:8	34.08	2503	1.9	13.45	100	194	Off Idle	67.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.11	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:9	34.08	2502	1.9	13.46	100	194	Off Idle	67.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.1	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:9	34.08	2500	1.9	13.44	100	194	Off Idle	67.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.09	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:9	34.08	2499	1.9	13.44	100	194	Off Idle	67.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.08	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:9	35.45	2506	1.9	13.44	100	194	Off Idle	66.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.09	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:9	35.45	2492	1.91	13.45	100	193	Off Idle	66.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.09	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:9	35.45	2494	1.91	13.43	100	193	Off Idle	66.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.1	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:56:9	35.45	2497	1.91	13.43	100	193	Off Idle	66.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.06	15.09	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:0	35.45	2497	1.91	13.43	100	193	Off Idle	66.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.05	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:0	35.45	2504	1.91	13.43	100	193	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.05	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:0	34.08	2479	1.91	13.43	100	193	Off Idle	65.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.07	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:0	34.08	2490	1.91	13.46	100	194	Off Idle	65.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.04	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:0	34.08	2507	1.92	13.46	100	194	Off Idle	65.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.06	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:0	34.08	2504	1.92	13.45	100	194	Off Idle	66	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.04	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:1	34.08	2504	1.92	13.46	100	193	Off Idle	66	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.02	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:1	34.08	2506	1.92	13.46	100	193	Off Idle	66	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.04	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:1	34.08	2501	1.92	13.45	100	193	Off Idle	66	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.04	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:1	34.08	2502	1.92	13.44	100	193	Off Idle	66	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.02	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:1	34.08	2506	1.92	13.45	100	193	Off Idle	66	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.02	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:1	34.08	2506	1.92	13.44	100	193	Off Idle	66	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.03	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:1	34.08	2504	1.92	13.43	100	193	Off Idle	66	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:2	34.08	2504	1.92	13.43	100	193	Off Idle	66	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:2	35.45	2522	1.93	13.44	100	193	Off Idle	66	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:2	35.45	2512	1.93	13.44	100	193	Off Idle	66	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:2	35.45	2495	1.93	13.44	100	193	Off Idle	66	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.01	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:2	35.45	2507	1.93	13.44	100	193	Off Idle	66	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.02	14.85	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:2	35.45	2507	1.93	13.44	100	193	Off Idle	65.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.99	14.89	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:3	35.45	2505	1.93	13.43	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.97	14.92	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:3	35.45	2505	1.93	13.44	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.94	14.97	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:20:57:3	34.08	2505	1.94	13.43	100	193	Off Idle	65.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.89	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:3	34.08	2504	1.94	13.45	100	193	Off Idle	65.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.89	15.05	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:3	34.08	2500	1.94	13.43	100	194	Off Idle	65.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.83	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:3	34.08	2502	1.94	13.45	100	194	Off Idle	65.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.81	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:4	34.08	2503	1.95	13.44	101	194	Off Idle	65.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:4	34.08	2502	1.95	13.46	101	193	Off Idle	65.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:4	34.08	2498	1.96	13.44	101	193	Off Idle	65.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:4	34.08	2501	1.96	13.44	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.65	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:4	34.08	2502	1.97	13.44	100	194	Off Idle	65.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.62	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:4	34.08	2506	1.97	13.44	100	194	Off Idle	65.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.58	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:4	34.08	2513	1.98	13.45	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.58	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:57:5	34.08	2513	1.98	13.44	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.54	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:20:57:5	34.08	2504	1.99	13.45	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.52	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:57:5	34.08	2509	1.99	13.45	100	193	Off Idle	65.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.52	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:57:5	34.08	2505	2	13.45	100	193	Off Idle	65.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.51	14.96	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:57:5	34.08	2505	2	13.45	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.47	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:57:5	34.08	2505	2.01	13.45	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.42	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:57:6	34.08	2507	2.01	13.44	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.38	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:57:6	34.08	2508	2.02	13.44	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.33	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:57:6	34.08	2510	2.02	13.46	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.3	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:57:6	34.08	2512	2.03	13.44	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.29	14.81	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:6	34.08	2516	2.03	13.45	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.24	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:6	34.08	2519	2.04	13.45	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.21	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:57:6	34.08	2520	2.04	13.46	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.21	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:7	34.08	2519	2.05	13.45	100	193	Off Idle	65.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.16	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:7	34.08	2510	2.05	13.46	100	193	Off Idle	65.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.09	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:7	34.08	2516	2.06	13.46	100	193	Off Idle	65.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.06	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:7	34.08	2517	2.06	13.45	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7	15.01	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:7	34.08	2517	2.07	13.45	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.01	15.02	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:7	34.08	2516	2.07	13.44	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.99	15.05	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:8	34.08	2510	2.08	13.44	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.96	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:8	34.08	2508	2.08	13.44	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.96	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:8	34.08	2508	2.09	13.45	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.95	15.07	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:8	34.08	2509	2.09	13.44	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.92	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:8	34.08	2511	2.09	13.47	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.87	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:8	34.08	2520	2.1	13.45	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.9	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:9	34.08	2510	2.1	13.45	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.87	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:9	34.08	2516	2.1	13.45	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.85	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:9	34.08	2516	2.11	13.45	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.88	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:9	34.08	2516	2.11	13.45	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.88	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:9	34.08	2512	2.11	13.45	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.86	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:57:9	34.08	2512	2.11	13.44	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.89	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:57:9	34.08	2512	2.11	13.44	100	193	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.9	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:0	34.08	2516	2.11	13.44	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.88	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:0	34.08	2522	2.11	13.45	100	193	Off Idle	65.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.86	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:0	34.08	2522	2.11	13.46	100	193	Off Idle	65.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.89	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:0	34.08	2521	2.11	13.47	100	193	Off Idle	65.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.86	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:0	34.08	2518	2.11	13.46	100	193	Off Idle	65.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.89	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:0	34.08	2520	2.11	13.46	100	193	Off Idle	65.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.85	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:1	34.08	2520	2.11	13.46	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.85	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:1	34.08	2522	2.11	13.46	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.85	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:1	34.08	2518	2.11	13.46	100	193	Off Idle	65.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.87	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:1	34.08	2511	2.11	13.45	100	193	Off Idle	65	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.87	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:1	34.08	2522	2.11	13.45	100	193	Off Idle	65	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.92	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:1	34.08	2514	2.11	13.45	100	193	Off Idle	65	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.89	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:1	34.08	2514	2.11	13.44	100	193	Off Idle	65	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.88	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:2	34.08	2515	2.11	13.46	100	193	Off Idle	65	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.84	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:2	34.08	2504	2.11	13.46	100	193	Off Idle	65	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.83	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:2	34.08	2523	2.11	13.46	100	193	Off Idle	65.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.77	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:2	34.08	2533	2.11	13.45	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.8	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:2	34.08	2534	2.11	13.44	100	193	Off Idle	65.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.78	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:2	34.08	2535	2.11	13.44	100	193	Off Idle	65.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.83	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:3	34.08	2537	2.11	13.44	100	193	Off Idle	64.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.84	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:3	34.08	2537	2.11	13.44	100	193	Off Idle	64.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.84	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:3	34.08	2533	2.11	13.44	100	193	Off Idle	64.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.85	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:3	34.08	2531	2.11	13.44	100	193	Off Idle	64.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.86	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:3	34.08	2530	2.11	13.44	100	193	Off Idle	64.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.85	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:3	34.08	2527	2.11	13.45	100	193	Off Idle	64.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.86	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:4	34.08	2528	2.11	13.44	100	193	Off Idle	64.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.88	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:4	34.08	2526	2.11	13.43	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.85	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:4	34.08	2524	2.11	13.44	100	193	Off Idle	64.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.83	15.2	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:4	34.08	2517	2.11	13.44	100	193	Off Idle	64.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.86	15.19	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:4	34.08	2514	2.11	13.44	100	193	Off Idle	64.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.82	15.22	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:4	34.08	2512	2.12	13.43	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.82	15.23	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:4	34.08	2515	2.12	13.45	100	193	Off Idle	63.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.82	15.22	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:5	34.08	2520	2.12	13.43	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.79	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:5	34.08	2522	2.12	13.45	100	193	Off Idle	64.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.83	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:5	34.08	2529	2.12	13.45	100	193	Off Idle	64.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.81	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:20:58:5	34.08	2530	2.12	13.44	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.79	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:5	34.08	2530	2.12	13.46	100	193	Off Idle	64.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.78	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:5	34.08	2530	2.12	13.44	100	193	Off Idle	64.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.83	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:58:6	34.08	2526	2.12	13.43	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.8	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:6	34.08	2529	2.12	13.43	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.8	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:6	34.08	2530	2.12	13.45	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.81	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:6	34.08	2535	2.12	13.45	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.83	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:6	34.08	2538	2.12	13.46	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.85	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:6	34.08	2540	2.12	13.46	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.86	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:6	34.08	2534	2.12	13.46	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.85	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:7	34.08	2544	2.12	13.46	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.87	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:7	34.08	2535	2.12	13.45	100	193	Off Idle	64.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.89	14.9	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:7	34.08	2536	2.12	13.44	100	193	Off Idle	64.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.85	14.9	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:7	34.08	2536	2.12	13.44	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.82	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:7	34.08	2533	2.12	13.43	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.83	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:7	34.08	2532	2.12	13.43	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.82	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:8	34.08	2534	2.12	13.45	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.85	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:8	34.08	2537	2.12	13.43	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.85	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:8	34.08	2537	2.12	13.42	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.85	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:8	34.08	2528	2.12	13.43	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.83	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:8	34.08	2526	2.12	13.43	100	193	Off Idle	64.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.86	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:58:8	34.08	2526	2.12	13.45	100	193	Off Idle	64.1	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.82	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:9	34.08	2525	2.12	13.44	100	193	Off Idle	64.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.85	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:9	34.08	2525	2.12	13.44	100	193	Off Idle	64.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.82	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:9	34.08	2525	2.12	13.45	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.84	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:9	34.08	2529	2.12	13.45	100	193	Off Idle	64.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.86	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:9	34.08	2536	2.12	13.44	100	193	Off Idle	64.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.86	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:9	34.08	2563	2.12	13.44	100	193	Off Idle	64.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.86	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:58:9	34.08	2554	2.12	13.45	100	193	Off Idle	64.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.89	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:0	34.08	2546	2.11	13.45	100	193	Off Idle	64.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.91	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:0	34.08	2545	2.11	13.45	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.89	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:0	34.08	2544	2.11	13.44	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.91	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:0	34.08	2536	2.11	13.45	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.92	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:0	34.08	2532	2.11	13.46	100	193	Off Idle	64.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.91	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:0	34.08	2531	2.11	13.46	100	193	Off Idle	64.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.95	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:1	34.08	2531	2.11	13.45	100	193	Off Idle	64.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.93	14.9	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:1	34.08	2532	2.11	13.45	100	193	Off Idle	64.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.93	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:1	34.08	2538	2.11	13.47	100	193	Off Idle	64.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.93	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:1	34.08	2540	2.11	13.46	100	193	Off Idle	64.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.95	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:1	34.08	2540	2.11	13.46	100	193	Off Idle	64.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.93	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:1	34.08	2546	2.11	13.46	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.71	Lean	1	14.6	-6.95	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:1	34.08	2546	2.11	13.47	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.94	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:20:59:2	34.08	2545	2.11	13.45	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.94	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:2	34.08	2547	2.11	13.44	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.94	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:2	34.08	2542	2.11	13.44	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.96	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:2	34.08	2540	2.11	13.45	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.94	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:2	34.08	2542	2.11	13.44	100	193	Off Idle	63.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.94	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:2	34.08	2543	2.11	13.44	100	193	Off Idle	63.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.91	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:3	34.08	2548	2.11	13.45	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.9	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:3	34.08	2548	2.11	13.44	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.92	14.78	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:3	34.08	2548	2.11	13.46	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.9	14.77	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:3	34.08	2548	2.11	13.44	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.9	14.78	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:3	34.08	2547	2.11	13.44	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.91	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:3	34.08	2543	2.11	13.44	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.9	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:4	34.08	2538	2.12	13.45	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.88	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:4	34.08	2538	2.12	13.45	100	193	Off Idle	63.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.9	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:4	34.08	2535	2.12	13.45	100	193	Off Idle	63.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.88	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:4	34.08	2535	2.12	13.46	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.89	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:4	34.08	2534	2.12	13.45	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.91	15.03	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:4	34.08	2536	2.12	13.45	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.9	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:4	34.08	2539	2.12	13.45	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.93	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:20:59:5	34.08	2543	2.12	13.43	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.91	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:5	34.08	2544	2.12	13.44	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.92	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:5	34.08	2546	2.12	13.44	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.93	15.09	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:5	34.08	2546	2.12	13.44	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.94	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:5	34.08	2548	2.12	13.43	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.94	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:5	34.08	2536	2.12	13.45	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.94	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:6	34.08	2543	2.12	13.46	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.95	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:6	34.08	2540	2.12	13.46	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.92	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:6	34.08	2538	2.12	13.45	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.9	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:6	34.08	2542	2.12	13.44	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.88	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:6	34.08	2542	2.12	13.44	100	193	Off Idle	63.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.88	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:6	34.08	2550	2.12	13.44	100	193	Off Idle	63.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.9	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:6	34.08	2552	2.12	13.45	101	193	Off Idle	63.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.89	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:7	34.08	2548	2.12	13.45	101	193	Off Idle	63.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.88	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:7	34.08	2548	2.12	13.46	101	193	Off Idle	63.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.92	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:7	34.08	2550	2.11	13.47	100	193	Off Idle	63.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.96	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:7	34.08	2547	2.11	13.46	100	193	Off Idle	63.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.95	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:7	34.08	2547	2.11	13.45	100	193	Off Idle	63.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.92	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:7	34.08	2550	2.11	13.46	100	193	Off Idle	63.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.96	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:8	34.08	2551	2.11	13.46	100	193	Off Idle	63.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.96	14.9	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:8	34.08	2552	2.11	13.45	100	193	Off Idle	63.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.92	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:8	34.08	2554	2.11	13.45	100	193	Off Idle	63.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.91	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:8	34.08	2551	2.11	13.46	100	193	Off Idle	63.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.88	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:8	34.08	2553	2.11	13.46	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.91	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:8	34.08	2543	2.11	13.45	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.88	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:9	34.08	2552	2.11	13.45	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.87	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:9	34.08	2552	2.11	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.91	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:9	34.08	2550	2.11	13.46	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.96	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:9	34.08	2550	2.11	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.95	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:9	34.08	2547	2.11	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.92	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:20:59:9	34.08	2546	2.11	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.92	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:20:59:9	34.08	2544	2.11	13.43	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.93	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:0	34.08	2545	2.11	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.89	14.9	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:0	34.08	2545	2.12	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.89	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:0	34.08	2546	2.12	13.45	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.89	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:0	34.08	2551	2.12	13.46	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.89	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:0	34.08	2553	2.12	13.45	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.92	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:0	34.08	2554	2.12	13.45	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.89	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:1	34.08	2557	2.12	13.43	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.88	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:1	34.08	2558	2.12	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.88	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:1	34.08	2558	2.12	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.9	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:00:1	34.08	2558	2.12	13.43	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.87	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:1	34.08	2552	2.12	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.9	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:1	34.08	2552	2.12	13.44	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.94	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:1	34.08	2547	2.12	13.44	100	193	Off Idle	63	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.92	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:2	34.08	2545	2.12	13.45	100	193	Off Idle	63	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.96	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:2	34.08	2546	2.11	13.46	100	193	Off Idle	63	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.96	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:2	34.08	2548	2.11	13.46	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.98	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:2	34.08	2555	2.11	13.45	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.99	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:2	34.08	2555	2.11	13.44	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.99	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:2	34.08	2548	2.11	13.45	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.96	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:3	34.08	2548	2.11	13.45	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.97	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:3	34.08	2550	2.11	13.46	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.96	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:3	34.08	2554	2.11	13.46	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:3	34.08	2557	2.11	13.46	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.99	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:3	34.08	2559	2.11	13.45	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.01	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:3	34.08	2566	2.11	13.46	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.04	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:4	34.08	2568	2.1	13.44	100	193	Off Idle	63	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.07	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:00:4	34.08	2568	2.1	13.43	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.08	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:4	34.08	2578	2.1	13.45	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.13	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:4	34.08	2569	2.1	13.45	100	193	Off Idle	63	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.16	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:4	34.08	2566	2.1	13.46	100	193	Off Idle	63	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.17	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:4	34.08	2565	2.09	13.46	100	193	Off Idle	63	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.24	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:4	34.08	2550	2.09	13.46	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.26	14.78	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:00:5	34.08	2554	2.08	13.46	100	193	Off Idle	62.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.27	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:5	34.08	2554	2.08	13.46	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.29	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:5	34.08	2555	2.08	13.45	100	193	Off Idle	62.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.33	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:5	34.08	2554	2.07	13.43	100	193	Off Idle	62.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.31	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:5	34.08	2554	2.07	13.44	100	193	Off Idle	62.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.37	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:5	34.08	2558	2.06	13.45	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.38	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:6	34.08	2561	2.06	13.45	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.41	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:6	34.08	2562	2.06	13.45	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.46	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:6	34.08	2561	2.05	13.48	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.47	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:6	34.08	2557	2.05	13.46	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.48	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:6	34.08	2558	2.04	13.46	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.49	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:6	34.08	2558	2.04	13.46	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.49	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:6	34.08	2556	2.04	13.45	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.51	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:7	34.08	2556	2.03	13.43	100	193	Off Idle	62.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.53	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:7	34.08	2553	2.03	13.45	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.54	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:7	34.08	2553	2.03	13.45	100	193	Off Idle	63	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.55	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:7	34.08	2552	2.02	13.43	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.58	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:7	34.08	2554	2.02	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.56	14.77	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:7	34.08	2554	2.02	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.57	14.75	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:8	34.08	2556	2.02	13.45	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.62	14.73	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:8	34.08	2555	2.02	13.46	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.58	14.75	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:8	34.08	2556	2.02	13.45	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.61	14.77	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:8	34.08	2564	2.01	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.58	14.78	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:8	34.08	2572	2.01	13.45	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.57	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:8	34.08	2572	2.01	13.44	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.57	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:9	34.08	2574	2.01	13.42	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.6	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:9	34.08	2570	2.01	13.42	100	193	Off Idle	63	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.59	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:9	34.08	2570	2.01	13.43	100	193	Off Idle	62.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:9	34.08	2568	2.01	13.45	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:9	35.45	2584	2.01	13.43	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.65	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:00:9	35.45	2564	2.01	13.44	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.62	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:00:9	35.45	2564	2.01	13.45	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.62	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:0	35.45	2560	2.01	13.45	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.66	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:0	35.45	2556	2.01	13.44	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.63	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:01:0	35.45	2557	2.01	13.46	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.65	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:0	35.45	2550	2	13.45	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.71	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:0	35.45	2560	2	13.47	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:0	35.45	2560	2	13.46	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.79	15.14	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:1	35.45	2566	2	13.45	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.8	15.16	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:1	35.45	2566	1.99	13.44	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.85	15.13	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:1	35.45	2580	1.99	13.44	100	193	Off Idle	63	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.87	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:1	35.45	2570	1.98	13.44	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.94	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:1	35.45	2556	1.98	13.45	100	193	Off Idle	63.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.01	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:1	35.45	2553	1.97	13.43	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.07	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:1	35.45	2552	1.97	13.43	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.09	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:01:2	35.45	2550	1.96	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.13	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:2	35.45	2554	1.96	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.2	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:2	35.45	2559	1.95	13.43	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.21	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:2	35.45	2560	1.94	13.43	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.26	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:2	35.45	2560	1.93	13.45	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.26	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:2	35.45	2561	1.92	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.29	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:3	35.45	2562	1.92	13.45	100	193	Off Idle	63.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.34	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:01:3	35.45	2563	1.91	13.45	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.34	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:3	35.45	2560	1.91	13.44	100	193	Off Idle	62.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.36	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:3	35.45	2560	1.91	13.44	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.38	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:3	35.45	2560	1.9	13.45	100	193	Off Idle	62.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.4	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:3	35.45	2561	1.9	13.45	100	193	Off Idle	62.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.38	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:4	35.45	2563	1.9	13.44	100	193	Off Idle	62.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.41	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:4	35.45	2563	1.89	13.44	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.41	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:4	35.45	2566	1.89	13.44	100	192	Off Idle	62.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.39	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:4	35.45	2566	1.89	13.43	100	192	Off Idle	62.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.38	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:4	35.45	2567	1.89	13.43	100	192	Off Idle	62.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.41	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:4	35.45	2565	1.89	13.45	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.41	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:4	35.45	2568	1.89	13.44	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.43	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:5	35.45	2545	1.89	13.44	100	193	Off Idle	62.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.43	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:5	35.45	2554	1.89	13.43	100	193	Off Idle	62.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.43	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:5	35.45	2558	1.89	13.43	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.45	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:5	35.45	2549	1.89	13.43	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.46	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:5	35.45	2549	1.89	13.43	101	192	Off Idle	62.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.46	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:5	35.45	2548	1.89	13.41	101	192	Off Idle	63.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.47	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:6	35.45	2548	1.89	13.41	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.43	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:6	35.45	2548	1.89	13.41	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.43	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:6	35.45	2565	1.89	13.41	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.44	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:6	35.45	2563	1.89	13.42	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.17	Rich	1	14.6	-8.41	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:6	35.45	2568	1.89	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.41	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:6	35.45	2568	1.88	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.44	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:6	35.45	2571	1.88	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.44	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:7	35.45	2571	1.88	13.45	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.43	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:7	35.45	2562	1.88	13.44	100	193	Off Idle	63.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.45	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:7	35.45	2551	1.88	13.45	100	193	Off Idle	63	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.45	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:7	35.45	2566	1.88	13.43	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.46	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:7	35.45	2556	1.88	13.43	100	193	Off Idle	62.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.43	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:7	35.45	2547	1.88	13.44	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.42	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:8	35.45	2553	1.88	13.45	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.43	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:8	35.45	2553	1.88	13.44	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.43	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:8	35.45	2563	1.88	13.44	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.42	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:01:8	35.45	2572	1.88	13.43	100	193	Off Idle	62.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.44	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:8	35.45	2578	1.88	13.43	100	193	Off Idle	62.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.42	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:8	35.45	2600	1.88	13.42	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.45	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:9	35.45	2600	1.88	13.41	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.45	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:9	35.45	2576	1.88	13.41	100	192	Off Idle	62.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.42	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:9	35.45	2565	1.88	13.43	100	192	Off Idle	62.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.42	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:9	35.45	2565	1.88	13.44	100	192	Off Idle	62.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.44	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:9	35.45	2550	1.88	13.44	100	192	Off Idle	61.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.42	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:9	35.45	2550	1.88	13.46	100	193	Off Idle	62	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.43	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:01:9	35.45	2547	1.88	13.45	100	193	Off Idle	62.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.41	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:0	35.45	2551	1.89	13.46	100	193	Off Idle	62.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.41	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:0	35.45	2544	1.89	13.44	100	193	Off Idle	62.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.39	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:0	35.45	2561	1.89	13.45	100	193	Off Idle	61.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.36	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:0	35.45	2564	1.89	13.46	100	193	Off Idle	61.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.37	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:0	35.45	2571	1.89	13.45	100	192	Off Idle	61.7	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.41	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:0	35.45	2573	1.89	13.44	100	192	Off Idle	61.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.38	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:1	35.45	2583	1.89	13.46	100	192	Off Idle	61.7	0	2	132	944 Turbo	0.22	Rich	1	14.6	-8.36	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:1	35.45	2566	1.89	13.45	100	192	Off Idle	61.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.39	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:1	35.45	2560	1.89	13.46	100	192	Off Idle	61.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.39	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:1	35.45	2551	1.89	13.45	100	192	Off Idle	61.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.39	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:1	35.45	2551	1.89	13.45	100	192	Off Idle	61.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.35	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:1	35.45	2551	1.89	13.45	100	192	Off Idle	61.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.37	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:1	35.45	2552	1.89	13.44	100	193	Off Idle	61.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.36	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:2	35.45	2552	1.9	13.45	100	193	Off Idle	62.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.34	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:02:2	35.45	2556	1.89	13.46	100	193	Off Idle	62.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.36	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:2	35.45	2561	1.89	13.45	100	192	Off Idle	62.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.38	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:2	35.45	2563	1.89	13.45	100	192	Off Idle	62.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.37	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:2	35.45	2563	1.89	13.46	100	192	Off Idle	62.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.39	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:2	35.45	2565	1.89	13.45	100	192	Off Idle	62.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.42	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:3	35.45	2565	1.89	13.44	100	192	Off Idle	62.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:3	35.45	2564	1.89	13.45	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.41	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:3	35.45	2555	1.89	13.45	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:3	35.45	2534	1.89	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.4	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:3	35.45	2553	1.89	13.46	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.41	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:3	35.45	2553	1.89	13.45	100	192	Off Idle	63	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.41	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:4	35.45	2551	1.89	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.4	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:4	35.45	2553	1.89	13.43	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.41	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:4	35.45	2553	1.89	13.43	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.41	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:4	35.45	2556	1.89	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.41	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:4	35.45	2571	1.89	13.43	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.41	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:4	35.45	2560	1.89	13.43	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.44	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:4	35.45	2560	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.43	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:5	35.45	2561	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.44	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:5	35.45	2550	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.41	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:5	35.45	2550	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.42	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:5	35.45	2553	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.41	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:5	35.45	2561	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.41	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:5	35.45	2567	1.88	13.47	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.18	Rich	1	14.6	-8.42	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:6	35.45	2567	1.88	13.46	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.44	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:6	35.45	2569	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.42	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:6	35.45	2567	1.88	13.45	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.42	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:6	35.45	2567	1.88	13.45	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.43	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:6	35.45	2559	1.88	13.46	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.42	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:6	35.45	2552	1.88	13.46	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.41	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:6	35.45	2551	1.88	13.47	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.43	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:7	35.45	2547	1.88	13.47	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.43	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:7	35.45	2547	1.88	13.46	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.44	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:7	35.45	2549	1.88	13.45	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.42	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:7	35.45	2552	1.88	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.45	15.17	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:7	35.45	2562	1.88	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.45	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:7	35.45	2564	1.88	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.45	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:8	35.45	2571	1.88	13.45	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.42	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:02:8	35.45	2573	1.88	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.43	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:8	35.45	2573	1.88	13.45	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.42	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:8	35.45	2572	1.88	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.46	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:8	35.45	2572	1.88	13.44	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.46	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:8	35.45	2568	1.88	13.44	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.45	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:9	35.45	2556	1.89	13.46	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.46	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:9	35.45	2553	1.89	13.46	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.44	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:9	35.45	2554	1.89	13.45	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.41	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:9	35.45	2556	1.89	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.41	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:9	35.45	2561	1.89	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.41	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:9	35.45	2561	1.89	13.44	100	192	Off Idle	62.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.42	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:02:9	35.45	2566	1.89	13.43	100	192	Off Idle	62.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.41	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:0	35.45	2566	1.89	13.44	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.39	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:0	35.45	2538	1.89	13.45	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.4	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:0	35.45	2538	1.89	13.45	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.42	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:0	35.45	2553	1.89	13.44	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.41	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:0	35.45	2545	1.89	13.46	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.4	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:0	35.45	2545	1.89	13.46	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.43	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:1	35.45	2550	1.89	13.46	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.42	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:1	35.45	2551	1.89	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.41	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:03:1	35.45	2552	1.89	13.44	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.39	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:1	35.45	2557	1.89	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:1	35.45	2563	1.89	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.4	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:1	35.45	2563	1.89	13.42	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.39	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:1	35.45	2567	1.89	13.44	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.37	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:2	35.45	2566	1.89	13.44	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:2	35.45	2565	1.89	13.42	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.39	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:2	35.45	2564	1.89	13.43	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.36	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:2	35.45	2559	1.89	13.45	100	193	Off Idle	62.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.4	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:2	35.45	2555	1.89	13.45	100	193	Off Idle	62.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.4	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:2	35.45	2561	1.89	13.45	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.42	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:3	35.45	2559	1.89	13.46	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.42	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:3	35.45	2557	1.89	13.46	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.4	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:3	35.45	2565	1.89	13.47	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.41	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:3	35.45	2565	1.89	13.45	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.4	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:3	35.45	2569	1.89	13.44	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.37	14.9	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:3	35.45	2571	1.89	13.42	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.38	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:4	35.45	2571	1.89	13.43	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.41	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:4	35.45	2566	1.89	13.44	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.39	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:4	35.45	2554	1.89	13.43	100	192	Off Idle	62.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.37	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:4	35.45	2554	1.89	13.44	100	192	Off Idle	62.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.4	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:4	35.45	2549	1.89	13.45	100	192	Off Idle	62.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.36	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:4	35.45	2542	1.89	13.44	100	192	Off Idle	62.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.39	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:4	35.45	2520	1.89	13.45	100	192	Off Idle	62.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.36	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:5	35.45	2530	1.89	13.44	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.34	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:5	35.45	2543	1.89	13.45	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.35	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:5	35.45	2546	1.89	13.45	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.34	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:5	35.45	2546	1.89	13.45	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.37	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:5	35.45	2558	1.89	13.44	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.37	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:5	35.45	2557	1.89	13.45	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:6	35.45	2557	1.89	13.46	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.41	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:6	35.45	2566	1.89	13.44	100	192	Off Idle	63	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.44	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:6	35.45	2583	1.89	13.44	100	192	Off Idle	63	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.41	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:6	35.45	2562	1.89	13.45	100	192	Off Idle	63	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.42	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:6	35.45	2562	1.89	13.43	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.42	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:6	35.45	2553	1.89	13.44	100	192	Off Idle	62.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.4	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:6	35.45	2539	1.89	13.44	100	192	Off Idle	62.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.39	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:7	35.45	2547	1.89	13.43	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.41	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:7	35.45	2548	1.89	13.45	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.39	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:7	35.45	2549	1.89	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.41	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:7	35.45	2557	1.89	13.42	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.4	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:7	35.45	2560	1.89	13.43	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.39	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:7	35.45	2570	1.89	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.41	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:8	35.45	2574	1.88	13.43	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.43	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:8	35.45	2562	1.88	13.43	100	192	Off Idle	62.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.41	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:8	35.45	2564	1.88	13.46	100	192	Off Idle	62.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.42	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:8	35.45	2559	1.88	13.45	100	192	Off Idle	62.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.44	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:8	35.45	2556	1.88	13.47	100	192	Off Idle	62.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.4	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:8	35.45	2554	1.88	13.46	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.4	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:9	35.45	2564	1.88	13.47	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.39	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:9	35.45	2540	1.88	13.45	100	192	Off Idle	62.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.4	14.89	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:9	35.45	2543	1.88	13.45	100	192	Off Idle	62.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.38	14.89	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:9	35.45	2547	1.88	13.44	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.38	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:9	35.45	2538	1.88	13.46	100	192	Off Idle	62.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.38	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:03:9	35.45	2563	1.88	13.46	100	192	Off Idle	62.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.36	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:03:9	35.45	2563	1.88	13.45	100	192	Off Idle	62.7	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.36	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:0	35.45	2558	1.88	13.44	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.38	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:0	35.45	2575	1.88	13.44	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.41	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:04:0	35.45	2554	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.43	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:0	35.45	2554	1.88	13.44	100	192	Off Idle	63.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.44	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:0	35.45	2548	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.41	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:0	35.45	2545	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.41	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:1	35.45	2545	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.43	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:1	35.45	2541	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.42	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:1	35.45	2542	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.4	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:1	35.45	2543	1.88	13.45	100	192	Off Idle	63.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.41	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:1	35.45	2548	1.88	13.46	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.44	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:1	35.45	2557	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.43	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:1	35.45	2558	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.41	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:2	35.45	2558	1.88	13.43	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.41	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:2	35.45	2564	1.88	13.45	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.41	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:2	35.45	2545	1.88	13.46	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.42	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:2	35.45	2550	1.88	13.46	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.41	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:2	35.45	2545	1.88	13.45	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.42	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:2	35.45	2525	1.88	13.45	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.43	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:3	35.45	2525	1.88	13.46	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.44	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:3	35.45	2550	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.44	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:3	35.45	2551	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.4	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:3	35.45	2556	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.41	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:3	35.45	2554	1.88	13.46	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.44	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:3	35.45	2552	1.88	13.45	100	192	Off Idle	63.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.44	15.05	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:4	35.45	2556	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.43	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:4	35.45	2556	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.45	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:4	35.45	2544	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.44	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:4	35.45	2544	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.42	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:4	35.45	2546	1.88	13.46	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.44	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:4	35.45	2546	1.88	13.46	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.44	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:4	35.45	2546	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.43	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:5	35.45	2548	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.44	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:5	35.45	2562	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.43	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:5	35.45	2559	1.88	13.46	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.42	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:5	35.45	2559	1.88	13.46	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.42	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:5	35.45	2564	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.41	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:5	35.45	2558	1.88	13.45	100	192	Off Idle	63.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.42	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:6	35.45	2558	1.88	13.45	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.44	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:6	35.45	2550	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.43	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:6	35.45	2549	1.88	13.43	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.41	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:6	35.45	2543	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.41	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:6	35.45	2540	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.41	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:6	35.45	2538	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.4	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:6	35.45	2535	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.39	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:7	35.45	2534	1.88	13.46	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.37	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:7	35.45	2518	1.88	13.46	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.39	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:7	35.45	2544	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.38	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:7	35.45	2546	1.88	13.46	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.37	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:7	35.45	2556	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:7	35.45	2576	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.42	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:8	35.45	2567	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.44	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:8	35.45	2558	1.88	13.46	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.44	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:04:8	35.45	2550	1.88	13.46	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.44	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:8	35.45	2548	1.88	13.46	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.46	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:8	35.45	2548	1.88	13.45	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.46	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:8	35.45	2542	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.46	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:9	35.45	2541	1.88	13.43	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.43	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:9	35.45	2541	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.41	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:9	35.45	2540	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.42	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:04:9	35.45	2546	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.41	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:9	35.45	2546	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.41	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:9	35.45	2548	1.88	13.46	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.41	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:04:9	35.45	2554	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.41	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:0	35.45	2559	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.41	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:0	35.45	2558	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.41	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:0	35.45	2569	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.44	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:0	35.45	2557	1.88	13.42	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.4	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:0	35.45	2557	1.88	13.43	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.38	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:0	35.45	2549	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.34	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:1	35.45	2527	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.38	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:1	35.45	2542	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.38	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:1	35.45	2542	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.38	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:1	35.45	2537	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:1	35.45	2535	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:1	35.45	2535	1.88	13.43	100	192	Off Idle	63.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:1	35.45	2542	1.88	13.44	100	192	Off Idle	63.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.4	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:2	35.45	2534	1.88	13.43	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.41	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:2	35.45	2539	1.88	13.43	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.4	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:2	35.45	2540	1.88	13.43	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.43	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:2	35.45	2544	1.88	13.45	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.41	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:2	35.45	2566	1.88	13.45	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.42	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:2	35.45	2556	1.88	13.45	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.42	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:3	35.45	2541	1.88	13.45	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.42	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:3	35.45	2539	1.88	13.44	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.4	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:3	35.45	2534	1.88	13.46	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.41	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:3	35.45	2534	1.88	13.45	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.4	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:3	35.45	2535	1.88	13.45	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.41	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:3	35.45	2537	1.88	13.46	100	192	Off Idle	63.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.42	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:4	35.45	2548	1.88	13.46	100	192	Off Idle	63.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.42	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:4	35.45	2551	1.88	13.45	100	192	Off Idle	63.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.41	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:4	35.45	2558	1.88	13.47	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.4	14.85	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:4	35.45	2598	1.88	13.46	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.41	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:4	35.45	2578	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.37	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:4	35.45	2554	1.88	13.45	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.37	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:4	35.45	2552	1.88	13.44	100	192	Off Idle	63.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.41	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:5	35.45	2543	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.4	14.98	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:5	35.45	2536	1.88	13.45	100	192	Off Idle	63	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.41	15.01	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:5	35.45	2536	1.88	13.45	100	192	Off Idle	63	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.4	15.04	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:5	35.45	2536	1.88	13.44	100	192	Off Idle	63	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.4	15.07	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:5	35.45	2507	1.88	13.45	100	192	Off Idle	63	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.38	15.08	1.03	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:5	35.45	2536	1.88	13.46	100	192	Off Idle	63	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.41	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:6	35.45	2538	1.88	13.46	100	192	Off Idle	63	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.37	15.1	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:6	35.45	2548	1.88	13.46	100	192	Off Idle	63	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.38	15.11	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:6	35.45	2555	1.88	13.44	100	192	Off Idle	63	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.4	15.13	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:6	35.45	2555	1.88	13.46	100	192	Off Idle	63	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	15.14	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:6	35.45	2558	1.88	13.45	100	192	Off Idle	63	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.41	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:6	35.45	2554	1.88	13.45	100	192	Off Idle	63	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.43	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:6	35.45	2555	1.88	13.45	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.43	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:7	35.45	2552	1.88	13.46	100	192	Off Idle	62.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.42	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:7	35.45	2548	1.89	13.44	100	192	Off Idle	62.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.4	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:7	35.45	2544	1.89	13.45	100	192	Off Idle	63.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.38	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:7	35.45	2540	1.89	13.45	100	192	Off Idle	63	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.39	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:7	35.45	2540	1.89	13.45	100	192	Off Idle	63	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.37	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:7	35.45	2534	1.89	13.44	100	192	Off Idle	63	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.37	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:8	35.45	2531	1.89	13.45	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.37	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:8	35.45	2531	1.89	13.45	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.36	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:8	35.45	2538	1.89	13.46	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.39	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:05:8	35.45	2542	1.89	13.45	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.4	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:8	35.45	2548	1.89	13.45	100	192	Off Idle	63.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.38	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:8	35.45	2548	1.89	13.46	100	192	Off Idle	63.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.39	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:9	35.45	2547	1.89	13.45	100	192	Off Idle	63.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.39	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:9	35.45	2547	1.88	13.47	100	192	Off Idle	63.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.39	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:9	35.45	2547	1.88	13.46	100	192	Off Idle	63.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.4	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:9	35.45	2543	1.88	13.46	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.41	14.9	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:05:9	35.45	2542	1.88	13.46	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.41	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:9	35.45	2537	1.88	13.46	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:05:9	35.45	2534	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.43	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:0	35.45	2536	1.88	13.44	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.4	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:0	35.45	2546	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.4	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:0	35.45	2538	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.41	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:0	35.45	2538	1.88	13.44	100	192	Off Idle	63.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:0	35.45	2542	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.4	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:0	35.45	2544	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.41	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:1	35.45	2543	1.88	13.44	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.41	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:1	35.45	2542	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.41	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:1	35.45	2536	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.41	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:1	35.45	2524	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.38	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:1	35.45	2532	1.88	13.44	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.41	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:1	35.45	2532	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.39	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:1	35.45	2533	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.39	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:2	35.45	2539	1.88	13.45	100	192	Off Idle	63.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.4	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:2	35.45	2539	1.88	13.46	100	192	Off Idle	63.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.41	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:2	35.45	2540	1.88	13.46	100	192	Off Idle	63.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.39	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:2	35.45	2540	1.88	13.45	100	192	Off Idle	63.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.39	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:2	35.45	2534	1.88	13.47	100	192	Off Idle	63.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.39	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:2	35.45	2535	1.88	13.46	100	192	Off Idle	63.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.38	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:3	35.45	2545	1.88	13.46	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.4	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:3	35.45	2536	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.38	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:3	35.45	2535	1.88	13.45	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.41	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:3	35.45	2535	1.88	13.44	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.41	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:3	35.45	2533	1.88	13.44	100	192	Off Idle	63.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.41	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:3	35.45	2532	1.88	13.46	100	192	Off Idle	63.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.4	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:4	35.45	2532	1.88	13.44	100	192	Off Idle	63.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:4	35.45	2534	1.88	13.45	100	192	Off Idle	63.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.38	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:4	35.45	2522	1.88	13.45	100	192	Off Idle	63.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.36	15.05	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:4	35.45	2504	1.88	13.44	100	192	Off Idle	63.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.38	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:4	35.45	2526	1.88	13.46	100	192	Off Idle	63.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.39	15.06	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:4	35.45	2535	1.88	13.45	100	192	Off Idle	64.1	0	2	132	944 Turbo	0.68	Lean	1	14.6	-8.39	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:4	35.45	2535	1.88	13.44	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.41	14.95	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:5	35.45	2537	1.88	13.44	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.43	14.92	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:5	35.45	2536	1.88	13.44	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.44	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:5	35.45	2536	1.88	13.44	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.44	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:5	35.45	2536	1.88	13.44	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.44	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:5	35.45	2546	1.88	13.44	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.43	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:5	35.45	2538	1.88	13.44	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.43	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:6	35.45	2540	1.88	13.44	100	192	Off Idle	64.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.43	14.78	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:6	35.45	2538	1.88	13.44	100	192	Off Idle	64.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.45	14.77	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:6	35.45	2538	1.88	13.43	100	192	Off Idle	64.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.44	14.78	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:6	35.45	2526	1.88	13.44	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.4	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:6	35.45	2516	1.88	13.43	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.4	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:6	35.45	2516	1.88	13.44	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.4	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:6	35.45	2516	1.87	13.45	100	192	Off Idle	64	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.38	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:7	35.45	2521	1.87	13.45	100	192	Off Idle	63.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.41	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:7	35.45	2531	1.87	13.45	100	192	Off Idle	63.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.44	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:7	35.45	2533	1.87	13.45	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.43	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:06:7	35.45	2534	1.87	13.45	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.63	Lean	1	14.6	-8.45	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:7	35.45	2522	1.87	13.45	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.66	Lean	1	14.6	-8.45	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:7	35.45	2538	1.87	13.45	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.42	14.94	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:8	35.45	2533	1.87	13.45	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.41	14.97	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:8	35.45	2528	1.87	13.46	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.43	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:8	35.45	2535	1.87	13.47	100	192	Off Idle	64.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:8	35.45	2527	1.87	13.45	100	192	Off Idle	64.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.42	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:06:8	35.45	2527	1.87	13.45	100	192	Off Idle	64.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:8	35.45	2527	1.87	13.44	100	192	Off Idle	64.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.41	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:9	35.45	2543	1.87	13.44	100	192	Off Idle	64.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:9	35.45	2543	1.87	13.45	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.41	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:9	35.45	2525	1.87	13.45	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.42	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:9	35.45	2530	1.87	13.44	100	192	Off Idle	64.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.42	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:9	35.45	2512	1.87	13.45	100	192	Off Idle	64.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.43	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:9	35.45	2520	1.87	13.46	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.41	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:06:9	35.45	2526	1.87	13.45	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.44	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:0	35.45	2526	1.87	13.44	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.42	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:0	35.45	2526	1.87	13.45	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.41	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:0	35.45	2528	1.87	13.45	100	192	Off Idle	64.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.4	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:0	35.45	2528	1.87	13.46	100	192	Off Idle	64.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.42	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:0	35.45	2528	1.87	13.46	100	192	Off Idle	64.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.4	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:0	35.45	2538	1.87	13.46	100	192	Off Idle	64.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.4	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:1	35.45	2525	1.87	13.45	100	192	Off Idle	64.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.41	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:1	35.45	2523	1.87	13.47	100	192	Off Idle	64.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.41	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:1	35.45	2523	1.87	13.45	100	192	Off Idle	64.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.43	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:1	35.45	2483	1.87	13.43	100	192	Off Idle	64.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.42	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:1	35.45	2522	1.87	13.44	100	192	Off Idle	64.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.41	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:1	35.45	2518	1.87	13.43	100	192	Off Idle	64.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.41	14.87	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:1	35.45	2514	1.87	13.44	100	192	Off Idle	65	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.45	14.88	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:2	35.45	2515	1.87	13.45	100	192	Off Idle	65.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.43	14.89	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:2	35.45	2525	1.87	13.46	100	192	Off Idle	65.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.41	14.92	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:2	35.45	2524	1.87	13.44	100	192	Off Idle	65.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.44	14.95	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:2	35.45	2522	1.87	13.45	100	192	Off Idle	65.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.42	14.97	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:2	35.45	2524	1.87	13.44	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.42	14.97	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:2	35.45	2524	1.87	13.44	100	192	Off Idle	65.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.42	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:3	35.45	2512	1.87	13.43	100	192	Off Idle	65	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.42	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:3	35.45	2509	1.87	13.45	100	192	Off Idle	64.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:3	35.45	2507	1.87	13.44	100	192	Off Idle	64.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.44	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:3	35.45	2499	1.87	13.45	100	192	Off Idle	64.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.42	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:3	35.45	2514	1.87	13.44	100	192	Off Idle	64.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.44	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:3	35.45	2518	1.87	13.45	100	192	Off Idle	64.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.41	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:4	35.45	2520	1.87	13.45	100	192	Off Idle	64.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.41	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:4	35.45	2536	1.87	13.46	100	192	Off Idle	64.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.41	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:4	35.45	2527	1.87	13.46	100	192	Off Idle	64.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.43	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:4	35.45	2527	1.87	13.47	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.43	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:4	35.45	2523	1.86	13.46	100	192	Off Idle	64.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.41	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:4	35.45	2520	1.86	13.45	100	192	Off Idle	64.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.41	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:4	35.45	2520	1.86	13.45	100	192	Off Idle	64.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.4	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:5	35.45	2520	1.87	13.43	100	192	Off Idle	64.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.41	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:5	35.45	2519	1.87	13.43	100	192	Off Idle	64.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.4	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:5	35.45	2538	1.87	13.43	100	192	Off Idle	64.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.42	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:5	35.45	2530	1.87	13.44	100	192	Off Idle	64.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.42	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:5	35.45	2524	1.87	13.43	100	192	Off Idle	64.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.43	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:5	35.45	2512	1.87	13.44	100	192	Off Idle	64.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.41	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:6	35.45	2522	1.87	13.44	100	192	Off Idle	64.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.41	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:6	35.45	2521	1.87	13.44	100	192	Off Idle	64.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.4	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:6	35.45	2516	1.87	13.45	100	192	Off Idle	64.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.41	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:6	35.45	2516	1.87	13.45	100	192	Off Idle	64.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.43	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:07:6	35.45	2516	1.87	13.46	100	192	Off Idle	65	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.41	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:6	35.45	2513	1.87	13.45	100	192	Off Idle	65	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.43	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:6	35.45	2509	1.86	13.45	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.43	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:7	35.45	2508	1.86	13.44	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.43	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:7	35.45	2506	1.86	13.45	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.41	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:7	35.45	2506	1.86	13.44	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:7	35.45	2510	1.86	13.42	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.4	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:7	35.45	2512	1.86	13.44	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.39	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:7	35.45	2512	1.86	13.43	100	192	Off Idle	65.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:8	35.45	2516	1.86	13.43	100	192	Off Idle	65.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.42	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:8	35.45	2507	1.86	13.43	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.41	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:07:8	35.45	2515	1.86	13.45	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.44	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:8	35.45	2515	1.86	13.44	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.45	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:8	35.45	2509	1.86	13.45	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.44	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:8	35.45	2507	1.86	13.46	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.44	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:9	35.45	2502	1.86	13.46	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.47	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:9	35.45	2501	1.86	13.45	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.48	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:9	35.45	2504	1.86	13.45	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.48	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:9	35.45	2504	1.86	13.44	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.45	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:9	35.45	2502	1.86	13.44	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.41	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:9	35.45	2500	1.86	13.44	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.41	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:07:9	35.45	2502	1.86	13.45	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.41	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:0	35.45	2504	1.86	13.45	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.41	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:0	35.45	2510	1.86	13.46	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.41	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:0	35.45	2519	1.86	13.44	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.45	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:0	35.45	2520	1.86	13.45	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.45	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:0	35.45	2513	1.86	13.44	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.46	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:0	35.45	2513	1.86	13.42	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.46	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:1	35.45	2499	1.86	13.42	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.44	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:1	35.45	2495	1.86	13.44	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.42	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:1	35.45	2495	1.86	13.45	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.43	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:1	35.45	2493	1.86	13.45	100	192	Off Idle	65.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.41	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:1	35.45	2494	1.86	13.44	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.43	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:1	35.45	2494	1.86	13.44	100	192	Off Idle	65.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.44	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:1	35.45	2484	1.86	13.45	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.42	15.13	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:2	35.45	2500	1.86	13.45	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	15.13	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:2	35.45	2499	1.86	13.44	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.43	15.11	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:2	35.45	2499	1.86	13.45	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	15.1	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:2	35.45	2523	1.86	13.45	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.4	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:2	35.45	2512	1.86	13.46	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.42	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:2	35.45	2512	1.86	13.46	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.42	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:3	35.45	2509	1.86	13.44	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.4	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:3	35.45	2505	1.86	13.45	100	192	Off Idle	65.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.41	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:3	35.45	2498	1.86	13.44	100	192	Off Idle	65.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.4	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:3	35.45	2498	1.86	13.45	100	192	Off Idle	66	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.4	14.9	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:3	35.45	2492	1.86	13.44	100	192	Off Idle	66.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.45	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:3	35.45	2507	1.86	13.44	100	192	Off Idle	66.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.44	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:4	35.45	2496	1.86	13.45	100	192	Off Idle	65.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.42	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:4	35.45	2486	1.86	13.43	100	192	Off Idle	65.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.44	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:4	35.45	2484	1.86	13.43	100	192	Off Idle	65.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.45	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:4	35.45	2484	1.86	13.45	100	192	Off Idle	65.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.41	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:4	35.45	2490	1.86	13.44	100	192	Off Idle	65.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.41	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:4	35.45	2500	1.86	13.45	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.41	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:4	35.45	2507	1.86	13.45	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.41	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:5	35.45	2507	1.86	13.47	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.43	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:5	35.45	2505	1.86	13.47	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.43	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:5	35.45	2502	1.86	13.46	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.41	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:5	35.45	2500	1.86	13.46	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.41	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:08:5	35.45	2489	1.86	13.44	100	192	Off Idle	65.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.41	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:5	35.45	2483	1.86	13.44	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.41	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:6	35.45	2483	1.86	13.45	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.42	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:6	35.45	2477	1.86	13.43	100	192	Off Idle	65.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:6	35.45	2477	1.86	13.44	100	192	Off Idle	65.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.4	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:6	35.45	2480	1.86	13.43	100	192	Off Idle	66.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.41	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:6	35.45	2492	1.85	13.42	100	192	Off Idle	66.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:6	35.45	2500	1.85	13.42	100	192	Off Idle	66.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.42	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:6	35.45	2509	1.85	13.42	100	192	Off Idle	66.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.43	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:7	35.45	2509	1.85	13.43	100	192	Off Idle	66.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.45	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:7	35.45	2505	1.85	13.44	100	192	Off Idle	66.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.41	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:7	35.45	2500	1.85	13.43	100	192	Off Idle	66.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.41	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:7	35.45	2499	1.85	13.43	100	192	Off Idle	66.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.41	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:7	35.45	2488	1.85	13.42	100	192	Off Idle	66.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.41	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:7	35.45	2479	1.85	13.43	100	192	Off Idle	66.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.38	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:8	35.45	2470	1.85	13.44	100	192	Off Idle	66.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.41	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:8	35.45	2467	1.86	13.43	100	192	Off Idle	66.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.4	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:8	35.45	2456	1.85	13.45	100	192	Off Idle	66.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.39	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:8	35.45	2473	1.85	13.47	100	192	Off Idle	66.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.4	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:8	35.45	2473	1.85	13.45	100	192	Off Idle	66.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.41	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:8	35.45	2482	1.85	13.45	100	192	Off Idle	66.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.4	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:9	35.45	2499	1.85	13.47	100	192	Off Idle	66.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.4	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:9	35.45	2499	1.85	13.46	100	192	Off Idle	67.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.37	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:9	35.45	2480	1.85	13.46	100	192	Off Idle	67.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.37	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:08:9	35.45	2480	1.85	13.46	100	192	Off Idle	67.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.37	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:9	35.45	2472	1.85	13.46	100	192	Off Idle	67.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.4	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:9	35.45	2482	1.85	13.45	100	192	Off Idle	67.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.37	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:08:9	35.45	2483	1.85	13.45	100	192	Off Idle	67.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.39	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:0	35.45	2482	1.85	13.45	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.41	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:0	35.45	2480	1.85	13.46	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.43	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:0	35.45	2490	1.85	13.46	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.45	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:0	35.45	2477	1.85	13.44	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.44	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:0	35.45	2475	1.85	13.44	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.44	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:0	35.45	2476	1.85	13.44	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.43	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:1	35.45	2467	1.85	13.45	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.44	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:1	35.45	2484	1.84	13.44	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.45	15.14	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:1	35.45	2487	1.84	13.45	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.47	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:1	35.45	2487	1.84	13.45	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.52	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:1	35.45	2506	1.84	13.44	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.54	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:1	35.45	2480	1.83	13.44	100	192	Off Idle	67.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.56	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:1	35.45	2477	1.83	13.44	100	192	Off Idle	68	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.55	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:2	35.45	2466	1.83	13.43	100	192	Off Idle	68	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.57	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:2	35.45	2461	1.83	13.44	100	192	Off Idle	68	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.59	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:2	35.45	2460	1.83	13.44	100	192	Off Idle	68	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.6	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:2	35.45	2459	1.82	13.45	100	192	Off Idle	68	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.63	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:2	35.45	2468	1.82	13.44	100	192	Off Idle	68	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.66	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:2	35.45	2471	1.82	13.45	100	192	Off Idle	68.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.64	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:3	35.45	2474	1.81	13.45	100	192	Off Idle	68.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.66	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:3	35.45	2488	1.81	13.46	100	192	Off Idle	68.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.65	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:3	35.45	2489	1.81	13.46	100	192	Off Idle	68.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.65	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:3	35.45	2493	1.81	13.47	100	192	Off Idle	68	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.65	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:3	35.45	2501	1.8	13.45	100	192	Off Idle	67.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.69	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:3	35.45	2500	1.8	13.45	100	192	Off Idle	67.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.7	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:4	35.45	2498	1.8	13.45	100	192	Off Idle	67.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.7	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:4	35.45	2486	1.8	13.43	100	192	Off Idle	67.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.68	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:4	35.45	2469	1.8	13.43	100	192	Off Idle	67.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.68	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:4	35.45	2469	1.8	13.45	100	192	Off Idle	67.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.66	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:4	35.45	2452	1.8	13.45	100	192	Off Idle	67.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.69	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:09:4	35.45	2443	1.8	13.45	100	192	Off Idle	67.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.66	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:4	35.45	2435	1.8	13.47	100	192	Off Idle	67.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.61	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:5	35.45	2440	1.8	13.46	100	192	Off Idle	67.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.62	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:5	35.45	2440	1.8	13.45	100	192	Off Idle	67.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.62	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:5	34.08	2453	1.8	13.46	100	192	Off Idle	67.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.6	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:5	34.08	2463	1.8	13.46	100	192	Off Idle	67.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.62	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:5	34.08	2463	1.8	13.44	100	192	Off Idle	67.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.64	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:5	34.08	2471	1.8	13.46	100	192	Off Idle	68.1	0	2	132	944 Turbo	0.69	Lean	1	14.6	-8.62	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:6	34.08	2482	1.8	13.44	100	192	Off Idle	68.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.63	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:6	35.45	2483	1.8	13.45	100	192	Off Idle	68.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.66	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:6	35.45	2487	1.79	13.45	100	192	Off Idle	68.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.68	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:6	35.45	2475	1.79	13.46	100	192	Off Idle	68.2	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.72	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:6	35.45	2471	1.79	13.44	100	192	Off Idle	68.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.72	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:6	35.45	2471	1.79	13.44	100	192	Off Idle	68.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.74	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:6	35.45	2467	1.79	13.45	100	192	Off Idle	68.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.73	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:7	35.45	2462	1.79	13.43	100	192	Off Idle	68.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.73	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:7	35.45	2458	1.79	13.44	100	192	Off Idle	68.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.72	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:7	35.45	2456	1.79	13.44	100	192	Off Idle	68.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.71	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:7	35.45	2454	1.79	13.45	100	192	Off Idle	68.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.71	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:7	35.45	2455	1.79	13.45	100	192	Off Idle	68.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.72	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:7	35.45	2455	1.79	13.45	100	192	Off Idle	68.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.7	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:09:8	35.45	2461	1.79	13.43	100	192	Off Idle	68.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.72	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:8	35.45	2465	1.79	13.43	100	192	Off Idle	68.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.71	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:8	35.45	2470	1.79	13.42	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.72	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:8	35.45	2472	1.78	13.43	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.72	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:8	35.45	2470	1.78	13.42	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.75	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:8	35.45	2466	1.78	13.43	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.76	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:9	35.45	2474	1.78	13.44	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.76	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:9	35.45	2464	1.78	13.45	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.81	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:9	35.45	2476	1.78	13.45	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.79	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:9	35.45	2463	1.78	13.45	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.8	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:9	35.45	2442	1.78	13.45	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.81	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:9	35.45	2440	1.78	13.45	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.83	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:09:9	35.45	2422	1.77	13.43	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.85	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:10:0	35.45	2438	1.77	13.43	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.85	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:10:0	35.45	2438	1.76	13.43	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.85	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:0	35.45	2441	1.76	13.43	100	192	Off Idle	68.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.87	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:0	35.45	2461	1.75	13.44	100	192	Off Idle	68.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.92	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:0	35.45	2448	1.74	13.45	100	192	Off Idle	68.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.95	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:10:0	35.45	2448	1.74	13.44	100	192	Off Idle	69	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.04	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:10:1	34.08	2442	1.73	13.44	100	192	Off Idle	69	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.04	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:1	34.08	2448	1.73	13.45	100	192	Off Idle	69	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.05	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:1	34.08	2462	1.72	13.46	100	192	Off Idle	69	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.11	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:1	34.08	2462	1.72	13.46	100	192	Off Idle	69	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.12	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:1	34.08	2454	1.71	13.46	100	192	Off Idle	69	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.13	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:1	34.08	2453	1.71	13.46	100	192	Off Idle	69.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.12	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:1	34.08	2462	1.71	13.46	100	192	Off Idle	69.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.16	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:2	35.45	2458	1.7	13.44	100	192	Off Idle	69.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.16	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:2	35.45	2446	1.7	13.43	100	192	Off Idle	69.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.2	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:2	35.45	2446	1.69	13.44	100	192	Off Idle	69.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.2	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:2	35.45	2440	1.69	13.44	100	192	Off Idle	69.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.22	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:2	35.45	2454	1.69	13.45	100	192	Off Idle	69.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.25	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:2	35.45	2452	1.68	13.43	100	192	Off Idle	69	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.29	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:3	35.45	2452	1.68	13.44	100	192	Off Idle	69	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.29	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:3	35.45	2453	1.68	13.43	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.33	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:3	35.45	2450	1.67	13.44	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.33	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:3	35.45	2450	1.67	13.44	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.35	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:3	35.45	2447	1.67	13.46	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.38	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:10:3	35.45	2449	1.66	13.44	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.38	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:4	35.45	2448	1.66	13.44	100	192	Off Idle	68.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.39	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:4	35.45	2443	1.66	13.44	100	192	Off Idle	68.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.4	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:4	35.45	2434	1.65	13.45	100	192	Off Idle	68.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.4	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:4	35.45	2434	1.65	13.44	100	192	Off Idle	68.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.41	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:4	35.45	2445	1.65	13.46	100	192	Off Idle	68.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.45	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:4	35.45	2446	1.64	13.47	100	192	Off Idle	68.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.47	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:4	35.45	2444	1.64	13.47	100	192	Off Idle	68.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.5	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:5	35.45	2444	1.64	13.46	100	192	Off Idle	68.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.51	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:5	35.45	2451	1.63	13.45	100	192	Off Idle	68.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.48	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:5	35.45	2442	1.63	13.45	100	192	Off Idle	68.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.49	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:5	35.45	2442	1.63	13.44	100	192	Off Idle	68.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.48	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:5	35.45	2442	1.63	13.43	100	192	Off Idle	68.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.49	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:5	35.45	2442	1.63	13.44	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.46	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:6	35.45	2440	1.62	13.44	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.48	15.11	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:6	35.45	2437	1.62	13.44	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.49	15.1	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:6	35.45	2436	1.62	13.44	100	192	Off Idle	69.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.53	15.11	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:6	35.45	2435	1.62	13.45	100	192	Off Idle	69.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.53	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:6	35.45	2435	1.62	13.44	100	192	Off Idle	69.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.53	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:6	35.45	2436	1.62	13.44	100	192	Off Idle	69.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.56	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:6	35.45	2432	1.62	13.43	100	192	Off Idle	69.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.56	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:7	35.45	2444	1.62	13.45	100	192	Off Idle	69.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.56	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:7	35.45	2436	1.61	13.45	100	192	Off Idle	69.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.58	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:7	35.45	2438	1.61	13.44	100	192	Off Idle	69.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.58	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:7	35.45	2439	1.61	13.45	100	192	Off Idle	69.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.6	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:10:7	35.45	2439	1.61	13.45	100	192	Off Idle	69.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.61	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:7	35.45	2438	1.61	13.44	100	192	Off Idle	69.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.62	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:8	35.45	2432	1.61	13.45	100	192	Off Idle	69.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.59	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:8	35.45	2426	1.61	13.45	100	192	Off Idle	69.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.62	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:8	35.45	2426	1.6	13.45	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.59	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:8	35.45	2428	1.6	13.45	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.58	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:8	35.45	2429	1.6	13.45	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.58	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:8	35.45	2429	1.6	13.44	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.61	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:9	35.45	2430	1.6	13.45	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.58	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:9	35.45	2430	1.6	13.44	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.61	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:9	35.45	2431	1.6	13.45	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.59	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:9	35.45	2430	1.6	13.45	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.61	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:9	35.45	2430	1.6	13.44	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.61	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:9	35.45	2422	1.6	13.43	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.64	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:10:9	35.45	2424	1.6	13.43	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.63	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:0	35.45	2424	1.6	13.42	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.64	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:0	35.45	2426	1.6	13.41	100	192	Off Idle	70.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.61	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:0	35.45	2424	1.6	13.43	100	192	Off Idle	70.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.58	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:0	35.45	2424	1.59	13.45	100	192	Off Idle	70.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.57	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:0	35.45	2422	1.59	13.45	100	192	Off Idle	70.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.57	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:0	35.45	2421	1.59	13.46	100	192	Off Idle	70.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.58	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:1	35.45	2421	1.59	13.46	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.61	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:1	35.45	2413	1.59	13.45	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.63	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:1	35.45	2411	1.59	13.45	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.63	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:1	35.45	2412	1.59	13.44	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.63	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:1	35.45	2415	1.59	13.45	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.62	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:1	35.45	2411	1.59	13.44	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.6	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:1	35.45	2414	1.59	13.43	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.59	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:2	35.45	2414	1.59	13.45	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.59	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:2	35.45	2412	1.59	13.44	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.58	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:2	35.45	2399	1.59	13.45	100	192	Off Idle	70.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.58	14.7	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:2	35.45	2427	1.59	13.45	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	14.7	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:2	35.45	2427	1.59	13.46	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.62	14.7	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:11:2	35.45	2416	1.59	13.46	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.6	14.69	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:3	35.45	2435	1.59	13.45	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.62	14.68	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:3	35.45	2428	1.59	13.44	100	192	Off Idle	70	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.58	14.7	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:3	35.45	2422	1.59	13.44	100	192	Off Idle	70	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	14.74	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:3	35.45	2428	1.59	13.43	100	192	Off Idle	70	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.57	14.77	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:3	35.45	2427	1.59	13.44	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.56	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:3	35.45	2427	1.59	13.44	100	192	Off Idle	70.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.57	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:4	35.45	2428	1.59	13.47	100	192	Off Idle	70.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.61	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:4	35.45	2424	1.59	13.46	100	192	Off Idle	70.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.61	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:4	35.45	2424	1.59	13.46	100	192	Off Idle	70.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.62	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:4	35.45	2424	1.59	13.45	100	192	Off Idle	70.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.63	15.19	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:4	35.45	2421	1.59	13.45	100	192	Off Idle	70.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.62	15.23	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:4	35.45	2421	1.59	13.43	100	192	Off Idle	70.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.63	15.26	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:4	35.45	2422	1.59	13.44	100	192	Off Idle	70.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.63	15.27	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:5	35.45	2426	1.59	13.44	100	192	Off Idle	70.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.62	15.29	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:5	35.45	2428	1.59	13.44	100	192	Off Idle	70.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.65	15.3	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:5	35.45	2428	1.59	13.45	100	192	Off Idle	70.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.63	15.3	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:5	35.45	2428	1.59	13.43	100	192	Off Idle	70.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.63	15.27	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:5	35.45	2422	1.59	13.44	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.63	15.27	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:5	35.45	2417	1.59	13.45	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.63	15.26	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:6	35.45	2413	1.59	13.44	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.63	15.23	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:6	35.45	2412	1.59	13.44	100	192	Off Idle	70.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.61	15.21	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:6	35.45	2412	1.59	13.45	100	192	Off Idle	70.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.59	15.21	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:6	35.45	2412	1.59	13.45	100	192	Off Idle	70.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.59	15.2	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:6	35.45	2412	1.59	13.44	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.59	15.17	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:6	35.45	2412	1.59	13.45	100	192	Off Idle	70.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.58	15.16	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:6	35.45	2411	1.59	13.45	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.59	15.16	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:7	35.45	2408	1.59	13.44	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.57	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:7	35.45	2404	1.59	13.44	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.58	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:7	35.45	2403	1.59	13.44	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.56	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:7	35.45	2404	1.59	13.43	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.57	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:7	35.45	2405	1.59	13.44	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.56	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:7	35.45	2411	1.59	13.45	100	192	Off Idle	70.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.59	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:8	35.45	2413	1.59	13.46	100	192	Off Idle	70.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.58	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:8	35.45	2413	1.59	13.44	100	192	Off Idle	70.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.59	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:8	35.45	2400	1.59	13.44	100	192	Off Idle	70.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.57	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:8	35.45	2409	1.59	13.45	100	192	Off Idle	70.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.57	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:8	35.45	2408	1.59	13.45	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.56	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:8	35.45	2410	1.59	13.45	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.59	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:9	35.45	2409	1.59	13.47	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.59	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:9	35.45	2405	1.59	13.46	100	192	Off Idle	70.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.58	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:9	35.45	2404	1.59	13.46	100	192	Off Idle	71	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.56	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:9	35.45	2402	1.59	13.45	100	192	Off Idle	71.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:11:9	35.45	2378	1.58	13.45	100	192	Off Idle	71.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.57	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:9	35.45	2386	1.58	13.44	100	192	Off Idle	71.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.59	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:11:9	35.45	2394	1.58	13.45	100	192	Off Idle	71.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.6	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:0	35.45	2392	1.58	13.45	100	192	Off Idle	71.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.62	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:0	35.45	2392	1.58	13.45	100	192	Off Idle	71.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.57	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:0	35.45	2394	1.58	13.45	100	192	Off Idle	71.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.58	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:0	35.45	2398	1.58	13.45	100	192	Off Idle	71.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.58	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:0	35.45	2398	1.58	13.45	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.58	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:0	35.45	2401	1.58	13.46	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.6	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:1	35.45	2399	1.58	13.45	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.61	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:1	35.45	2398	1.58	13.46	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.61	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:1	35.45	2398	1.57	13.44	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.61	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:1	35.45	2396	1.57	13.44	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.6	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:1	35.45	2394	1.57	13.45	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.59	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:1	35.45	2394	1.57	13.44	100	192	Off Idle	71.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.59	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:12:1	35.45	2394	1.57	13.45	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.57	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:2	35.45	2392	1.57	13.46	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.59	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:2	35.45	2392	1.57	13.45	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.59	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:2	35.45	2392	1.57	13.46	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.6	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:2	35.45	2393	1.57	13.46	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.62	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:2	35.45	2390	1.57	13.46	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.61	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:2	35.45	2386	1.57	13.45	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.61	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:3	35.45	2386	1.57	13.45	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.59	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:3	35.45	2388	1.57	13.45	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.57	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:3	35.45	2390	1.57	13.46	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.56	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:3	35.45	2390	1.57	13.45	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.58	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:3	35.45	2395	1.57	13.45	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.6	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:3	35.45	2396	1.57	13.45	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.61	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:4	35.45	2397	1.57	13.45	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.63	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:4	35.45	2392	1.57	13.45	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.64	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:4	35.45	2404	1.57	13.46	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.62	14.86	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:4	35.45	2404	1.57	13.46	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.63	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:4	35.45	2402	1.57	13.46	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.62	14.86	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:4	35.45	2404	1.57	13.46	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.62	14.88	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:4	35.45	2404	1.57	13.45	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.63	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:5	35.45	2412	1.57	13.45	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.63	14.94	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:5	35.45	2404	1.57	13.43	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.62	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:5	35.45	2402	1.57	13.45	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.61	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:5	35.45	2411	1.57	13.44	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.61	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:5	35.45	2402	1.57	13.46	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.62	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:5	35.45	2392	1.57	13.45	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.64	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:6	35.45	2392	1.57	13.45	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.66	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:6	35.45	2381	1.57	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.63	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:6	35.45	2373	1.57	13.47	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.62	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:6	35.45	2373	1.57	13.46	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.63	15.14	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:6	35.45	2373	1.57	13.46	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.6	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:6	35.45	2374	1.57	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.58	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:6	35.45	2371	1.57	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.58	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:12:7	35.45	2371	1.57	13.44	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.59	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:7	35.45	2373	1.57	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.56	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:7	35.45	2367	1.57	13.46	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.55	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:7	35.45	2370	1.57	13.45	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.55	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:7	35.45	2375	1.57	13.45	100	192	Off Idle	72.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.54	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:7	35.45	2379	1.57	13.44	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.53	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:8	35.45	2380	1.57	13.43	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.52	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:8	35.45	2381	1.58	13.43	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.19	Rich	1	14.6	-9.52	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:8	35.45	2388	1.58	13.42	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.15	Rich	1	14.6	-9.54	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:8	35.45	2392	1.58	13.44	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.56	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:8	35.45	2396	1.58	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.56	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:8	35.45	2396	1.58	13.44	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.57	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:9	35.45	2390	1.58	13.42	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.56	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:9	35.45	2405	1.58	13.41	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.54	14.86	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:9	35.45	2406	1.58	13.42	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.51	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:9	35.45	2409	1.58	13.43	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.52	14.84	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:9	35.45	2433	1.59	13.45	100	192	Off Idle	73	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.51	14.86	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:9	35.45	2422	1.59	13.44	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.53	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:12:9	35.45	2399	1.59	13.44	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.54	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:0	35.45	2382	1.59	13.45	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.5	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:0	35.45	2382	1.59	13.45	100	192	Off Idle	72.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.5	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:0	35.45	2360	1.59	13.44	100	192	Off Idle	72	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.47	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:0	35.45	2348	1.6	13.45	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.46	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:0	35.45	2350	1.6	13.46	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.45	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:0	35.45	2350	1.6	13.45	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.42	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:13:1	35.45	2356	1.6	13.47	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.39	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:1	35.45	2356	1.6	13.45	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.4	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:1	35.45	2361	1.6	13.45	100	192	Off Idle	72.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.39	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:1	35.45	2363	1.6	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.4	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:1	35.45	2367	1.6	13.44	100	192	Off Idle	73	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.41	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:1	35.45	2367	1.6	13.44	100	192	Off Idle	73	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.4	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:1	35.45	2377	1.6	13.45	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.39	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:2	35.45	2382	1.6	13.44	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.44	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:2	35.45	2369	1.6	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.43	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:2	34.08	2390	1.6	13.46	100	192	Off Idle	74	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.47	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:2	34.08	2390	1.6	13.46	100	192	Off Idle	74	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.48	14.95	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:2	34.08	2387	1.59	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.49	14.91	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:2	34.08	2403	1.59	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.47	14.85	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:3	34.08	2403	1.59	13.44	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.49	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:3	34.08	2384	1.59	13.44	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.46	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:3	35.45	2398	1.59	13.43	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.48	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:3	35.45	2380	1.59	13.44	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.47	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:3	35.45	2380	1.59	13.44	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.5	14.8	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:3	35.45	2380	1.59	13.44	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.49	14.81	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:4	35.45	2383	1.59	13.45	100	192	Off Idle	73	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.48	14.82	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:4	35.45	2399	1.59	13.45	100	192	Off Idle	72.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.47	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:4	35.45	2384	1.59	13.45	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.49	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:4	35.45	2388	1.59	13.45	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.49	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:4	35.45	2389	1.59	13.44	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.49	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:4	35.45	2386	1.59	13.44	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.48	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:4	35.45	2382	1.59	13.45	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.48	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:5	35.45	2382	1.59	13.45	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.46	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:5	35.45	2373	1.59	13.43	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.46	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:5	35.45	2367	1.59	13.44	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.45	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:5	35.45	2365	1.59	13.44	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.46	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:5	35.45	2362	1.59	13.44	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.45	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:5	35.45	2364	1.59	13.44	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.41	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:6	35.45	2371	1.6	13.46	100	192	Off Idle	72.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.37	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:6	35.45	2371	1.6	13.46	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.4	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:6	35.45	2375	1.6	13.46	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.42	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:6	35.45	2378	1.6	13.47	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.39	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:6	35.45	2380	1.6	13.46	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.45	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:6	35.45	2387	1.6	13.46	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.45	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:6	35.45	2390	1.6	13.45	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.43	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:7	35.45	2392	1.6	13.45	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.44	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:7	35.45	2392	1.6	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.45	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:7	35.45	2386	1.6	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.45	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:7	35.45	2380	1.6	13.45	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.44	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:7	35.45	2376	1.6	13.43	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.45	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:7	35.45	2358	1.6	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.41	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:13:8	35.45	2347	1.6	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.43	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:8	35.45	2347	1.6	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.41	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:8	34.08	2339	1.6	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.37	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:8	34.08	2350	1.6	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.37	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:8	34.08	2350	1.6	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.38	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:8	34.08	2350	1.6	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.37	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:9	34.08	2350	1.6	13.43	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.42	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:9	34.08	2351	1.6	13.44	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.43	15.05	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:9	34.08	2354	1.6	13.44	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.44	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:9	34.08	2354	1.6	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.44	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:9	34.08	2357	1.6	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.42	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:9	34.08	2363	1.59	13.46	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.41	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:13:9	34.08	2363	1.59	13.46	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.45	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:14:0	34.08	2369	1.59	13.45	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.45	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:0	34.08	2371	1.59	13.45	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.42	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:0	35.45	2381	1.59	13.46	100	192	Off Idle	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.42	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:0	35.45	2373	1.59	13.46	100	192	Off Idle	74	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.42	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:0	35.45	2374	1.59	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.42	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:0	35.45	2374	1.59	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.43	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:1	35.45	2381	1.59	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.42	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:1	35.45	2385	1.59	13.45	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.43	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:1	35.45	2388	1.59	13.45	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.43	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:1	35.45	2390	1.59	13.45	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.43	14.9	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:1	35.45	2382	1.59	13.46	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.45	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:1	35.45	2369	1.59	13.46	100	192	Off Idle	73	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.44	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:1	35.45	2369	1.59	13.46	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.44	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:2	35.45	2362	1.6	13.46	100	192	Off Idle	72.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.42	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:2	35.45	2358	1.6	13.44	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.42	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:2	35.45	2351	1.6	13.45	100	192	Off Idle	72.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.38	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:2	35.45	2348	1.6	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.38	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:2	35.45	2343	1.6	13.44	100	192	Off Idle	73	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.39	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:2	35.45	2344	1.6	13.44	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.35	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:3	35.45	2346	1.6	13.46	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.35	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:3	35.45	2348	1.6	13.45	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.38	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:3	34.08	2331	1.6	13.44	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.38	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:3	34.08	2356	1.6	13.45	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.37	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:3	34.08	2356	1.6	13.44	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.39	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:3	34.08	2358	1.6	13.43	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.4	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:4	34.08	2363	1.6	13.43	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.4	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:4	34.08	2366	1.6	13.43	100	192	Off Idle	74	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.41	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:4	34.08	2377	1.6	13.43	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.42	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:4	35.45	2369	1.6	13.43	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.4	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:4	35.45	2371	1.6	13.45	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.41	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:4	35.45	2371	1.6	13.46	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.44	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:4	35.45	2374	1.6	13.46	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.46	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:5	35.45	2375	1.6	13.45	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.45	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:5	35.45	2374	1.6	13.44	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.46	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:5	35.45	2364	1.6	13.45	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.45	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:5	35.45	2352	1.59	13.43	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.43	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:5	35.45	2352	1.59	13.44	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.43	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:5	35.45	2347	1.59	13.45	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.42	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:6	35.45	2348	1.59	13.43	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.4	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:6	35.45	2348	1.59	13.45	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.41	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:6	34.08	2328	1.59	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.45	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:6	34.08	2347	1.59	13.44	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.43	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:6	34.08	2349	1.59	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.41	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:6	34.08	2352	1.59	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.42	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:6	34.08	2352	1.59	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.4	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:7	34.08	2354	1.59	13.46	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.37	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:14:7	34.08	2357	1.6	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.66	Lean	1	14.6	-9.37	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:7	34.08	2359	1.6	13.44	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.34	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:7	34.08	2356	1.6	13.44	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.36	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:7	34.08	2356	1.6	13.44	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.35	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:7	34.08	2366	1.6	13.44	100	191	Off Idle	74.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.34	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:8	34.08	2371	1.6	13.43	100	191	Off Idle	74	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.35	14.96	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:8	34.08	2371	1.6	13.45	100	191	Off Idle	73.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.37	14.94	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:8	34.08	2392	1.6	13.45	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.37	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:8	34.08	2374	1.6	13.45	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.35	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:8	34.08	2373	1.6	13.45	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.38	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:8	34.08	2362	1.6	13.45	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.36	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:9	34.08	2352	1.6	13.45	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.35	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:14:9	34.08	2349	1.6	13.45	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.34	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:14:9	34.08	2349	1.61	13.45	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.33	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:9	35.45	2356	1.61	13.46	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.29	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:9	35.45	2351	1.61	13.47	100	191	Off Idle	73.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.29	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:9	35.45	2343	1.61	13.45	100	191	Off Idle	73.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.27	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:14:9	35.45	2358	1.61	13.45	100	191	Off Idle	73.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.26	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:0	35.45	2361	1.61	13.44	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.28	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:0	35.45	2358	1.61	13.43	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.33	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:0	34.08	2359	1.61	13.43	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.33	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:0	34.08	2361	1.61	13.42	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.36	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:0	34.08	2360	1.61	13.44	100	192	Off Idle	74	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.35	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:0	34.08	2360	1.61	13.45	100	192	Off Idle	74.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.32	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:1	34.08	2348	1.61	13.44	100	192	Off Idle	74.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.33	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:1	34.08	2350	1.61	13.43	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.35	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:1	34.08	2350	1.61	13.43	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.33	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:1	35.45	2351	1.61	13.46	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.33	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:1	35.45	2352	1.61	13.44	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.32	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:1	35.45	2354	1.61	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.29	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:1	35.45	2355	1.61	13.47	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.28	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:2	35.45	2360	1.61	13.46	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.29	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:2	35.45	2360	1.61	13.46	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.3	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:15:2	34.08	2346	1.61	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.27	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:15:2	34.08	2349	1.61	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.29	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:15:2	34.08	2349	1.61	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.32	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:2	34.08	2344	1.61	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.27	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:3	34.08	2342	1.61	13.45	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.3	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:3	34.08	2346	1.61	13.43	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.33	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:3	35.45	2355	1.61	13.45	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.29	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:3	35.45	2355	1.61	13.43	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.31	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:3	35.45	2359	1.61	13.42	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.31	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:3	35.45	2359	1.61	13.43	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.28	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:4	35.45	2358	1.61	13.44	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.29	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:4	35.45	2361	1.61	13.43	100	192	Off Idle	74.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.29	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:4	34.08	2362	1.61	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.28	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:4	34.08	2352	1.61	13.44	100	192	Off Idle	74	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.27	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:4	34.08	2360	1.61	13.43	100	192	Off Idle	74	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.25	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:15:4	34.08	2351	1.62	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.22	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:4	34.08	2351	1.62	13.44	100	192	Off Idle	74	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.23	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:5	34.08	2350	1.62	13.44	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.19	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:5	34.08	2343	1.62	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.17	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:5	34.08	2339	1.63	13.46	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.15	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:5	34.08	2339	1.63	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.15	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:5	34.08	2344	1.64	13.44	100	192	Off Idle	74.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.13	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:5	34.08	2351	1.64	13.44	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.08	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:6	34.08	2360	1.64	13.44	100	192	Off Idle	74.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.03	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:6	34.08	2360	1.65	13.43	100	192	Off Idle	74.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:6	34.08	2365	1.65	13.44	100	192	Off Idle	74.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.96	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:6	34.08	2369	1.66	13.47	100	192	Off Idle	74.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.94	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:6	34.08	2372	1.67	13.47	100	192	Off Idle	74.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.92	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:6	34.08	2372	1.67	13.47	100	192	Off Idle	74.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.93	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:6	34.08	2368	1.67	13.46	100	192	Off Idle	74.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.91	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:7	34.08	2362	1.68	13.46	100	192	Off Idle	74.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.92	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:7	34.08	2360	1.69	13.45	100	192	Off Idle	74.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.92	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:7	34.08	2349	1.69	13.46	100	192	Off Idle	74.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.84	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:7	34.08	2341	1.7	13.46	100	192	Off Idle	74.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.81	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:7	34.08	2338	1.7	13.44	100	192	Off Idle	74.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.79	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:7	34.08	2337	1.7	13.44	100	192	Off Idle	74.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.73	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:8	34.08	2342	1.71	13.44	100	192	Off Idle	74.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.72	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:15:8	34.08	2349	1.71	13.43	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.72	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:8	34.08	2351	1.71	13.42	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.71	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:8	34.08	2340	1.72	13.42	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.7	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:8	34.08	2340	1.72	13.44	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.69	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:8	34.08	2360	1.73	13.44	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.72	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:9	34.08	2360	1.73	13.43	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.71	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:9	34.08	2377	1.73	13.44	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.63	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:9	34.08	2366	1.74	13.46	100	192	Off Idle	74.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.62	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:9	34.08	2340	1.74	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.6	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:9	34.08	2342	1.75	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.51	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:15:9	34.08	2342	1.76	13.47	100	192	Off Idle	74	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.44	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:15:9	34.08	2347	1.76	13.46	100	192	Off Idle	74	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.45	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:0	34.08	2359	1.77	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.38	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:0	34.08	2369	1.77	13.43	100	192	Off Idle	74	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.34	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:0	34.08	2370	1.78	13.43	100	192	Off Idle	74	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.29	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:0	34.08	2379	1.78	13.43	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.22	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:0	34.08	2380	1.78	13.43	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.2	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:0	34.08	2374	1.8	13.45	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.14	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:1	34.08	2372	1.8	13.44	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.13	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:1	34.08	2363	1.81	13.43	100	192	Off Idle	73	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.12	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:1	34.08	2344	1.82	13.44	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.07	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:1	34.08	2341	1.83	13.42	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.04	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:1	34.08	2339	1.83	13.43	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.98	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:1	34.08	2322	1.84	13.45	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.96	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:1	34.08	2322	1.85	13.46	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.96	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:2	34.08	2344	1.85	13.44	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.98	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:2	34.08	2350	1.86	13.46	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.97	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:2	34.08	2352	1.86	13.45	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:2	34.08	2376	1.86	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.98	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:2	34.08	2363	1.86	13.44	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.95	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:2	34.08	2361	1.86	13.44	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.96	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:3	34.08	2357	1.86	13.44	100	192	Off Idle	74	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.93	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:3	34.08	2366	1.86	13.44	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.92	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:3	34.08	2358	1.87	13.44	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.96	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:3	34.08	2357	1.87	13.44	100	192	Off Idle	74.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.93	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:3	34.08	2357	1.87	13.44	100	192	Off Idle	74	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.95	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:3	34.08	2356	1.87	13.43	100	192	Off Idle	74	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.94	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:4	34.08	2356	1.87	13.44	100	192	Off Idle	74	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.9	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:4	34.08	2353	1.87	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.9	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:4	34.08	2352	1.86	13.45	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.89	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:4	34.08	2352	1.86	13.45	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.86	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:4	34.08	2353	1.86	13.44	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.9	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:4	34.08	2356	1.86	13.44	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.91	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:4	34.08	2358	1.86	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.92	14.78	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:5	34.08	2358	1.86	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.93	14.77	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:5	34.08	2358	1.86	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.94	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:5	34.08	2358	1.86	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.95	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:5	34.08	2360	1.86	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.93	14.78	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:5	34.08	2376	1.86	13.44	100	192	Off Idle	74	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.94	14.78	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:5	34.08	2363	1.86	13.45	100	192	Off Idle	74	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.98	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:6	34.08	2367	1.86	13.43	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.96	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:6	34.08	2366	1.86	13.44	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.95	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:6	34.08	2364	1.86	13.45	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.98	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:6	34.08	2359	1.86	13.45	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.97	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:6	34.08	2360	1.86	13.45	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.92	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:6	34.08	2358	1.86	13.46	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.92	14.81	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:6	34.08	2356	1.86	13.44	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.93	14.81	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:7	34.08	2357	1.86	13.45	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.93	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:16:7	34.08	2357	1.87	13.44	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.91	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:7	34.08	2350	1.87	13.44	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.94	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:7	34.08	2352	1.87	13.43	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.94	14.9	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:7	34.08	2357	1.87	13.44	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.92	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:7	34.08	2356	1.87	13.44	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.97	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:8	34.08	2358	1.87	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.95	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:8	34.08	2360	1.87	13.46	100	192	Off Idle	74	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.94	15.05	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:16:8	34.08	2360	1.87	13.45	99	192	Off Idle	74.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.96	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:8	34.08	2356	1.87	13.43	99	192	Off Idle	74.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.94	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:8	34.08	2358	1.87	13.43	99	192	Off Idle	74.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.9	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:8	34.08	2357	1.87	13.42	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.93	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:9	34.08	2354	1.87	13.43	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.94	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:9	34.08	2353	1.87	13.43	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.92	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:9	34.08	2359	1.87	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.94	15.15	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:9	34.08	2359	1.87	13.44	100	192	Off Idle	74	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.96	15.14	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:9	34.08	2366	1.87	13.43	100	192	Off Idle	74	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.92	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:9	34.08	2370	1.86	13.43	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.9	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:16:9	34.08	2369	1.86	13.44	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.9	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:0	34.08	2369	1.87	13.43	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.91	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:0	34.08	2363	1.86	13.46	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.93	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:0	34.08	2362	1.86	13.46	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.94	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:0	34.08	2364	1.86	13.45	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.94	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:0	34.08	2365	1.87	13.45	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.94	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:0	34.08	2365	1.87	13.44	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.93	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:1	34.08	2363	1.87	13.45	99	192	Off Idle	73.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.9	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:1	34.08	2363	1.87	13.45	99	192	Off Idle	73.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.89	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:1	34.08	2363	1.87	13.44	99	192	Off Idle	73.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.9	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:1	34.08	2363	1.87	13.45	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.89	14.79	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:1	34.08	2366	1.87	13.46	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.89	14.79	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:1	34.08	2364	1.87	13.45	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.88	14.81	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:1	34.08	2362	1.87	13.45	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.87	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:2	34.08	2360	1.87	13.45	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.85	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:2	34.08	2361	1.87	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.87	14.9	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:2	34.08	2364	1.87	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.9	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:2	34.08	2364	1.87	13.44	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.91	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:2	34.08	2366	1.87	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.91	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:2	34.08	2365	1.87	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.91	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:3	34.08	2366	1.87	13.44	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.89	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:3	34.08	2366	1.88	13.43	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.88	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:3	34.08	2363	1.88	13.42	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.88	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:3	34.08	2363	1.88	13.43	100	192	Off Idle	74	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.89	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:3	34.08	2357	1.88	13.42	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.88	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:3	34.08	2354	1.87	13.43	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.89	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:4	34.08	2350	1.87	13.42	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.87	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:4	34.08	2350	1.87	13.42	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.85	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:4	34.08	2350	1.87	13.43	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.86	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:4	34.08	2353	1.87	13.45	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.86	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:4	34.08	2353	1.87	13.44	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.85	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:4	34.08	2361	1.87	13.45	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.86	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:4	34.08	2361	1.87	13.46	100	192	Off Idle	74.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.89	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:5	34.08	2362	1.87	13.47	100	192	Off Idle	74.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.87	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:5	34.08	2370	1.87	13.46	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.87	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:5	34.08	2373	1.87	13.46	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.86	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:5	34.08	2381	1.87	13.46	100	192	Off Idle	74.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.84	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:5	34.08	2381	1.87	13.46	100	192	Off Idle	74	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.85	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:5	34.08	2383	1.87	13.46	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.86	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:6	34.08	2379	1.87	13.46	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.87	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:6	34.08	2372	1.87	13.45	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.89	14.84	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:17:6	34.08	2372	1.87	13.44	100	191	Off Idle	73.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.88	14.85	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:6	34.08	2373	1.87	13.44	100	191	Off Idle	73.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.9	14.87	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:6	34.08	2390	1.87	13.44	100	191	Off Idle	73.2	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.9	14.9	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:6	34.08	2382	1.87	13.45	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.9	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:6	34.08	2382	1.87	13.47	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.93	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:7	34.08	2376	1.87	13.47	100	192	Off Idle	73	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.93	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:7	34.08	2378	1.87	13.45	100	192	Off Idle	73	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.93	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:7	34.08	2372	1.87	13.47	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.89	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:7	34.08	2372	1.87	13.47	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.89	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:7	34.08	2367	1.87	13.45	100	192	Off Idle	73	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.92	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:7	34.08	2357	1.87	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.89	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:8	34.08	2354	1.87	13.45	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.89	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:8	34.08	2349	1.88	13.44	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.89	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:8	34.08	2349	1.88	13.46	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.87	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:17:8	34.08	2350	1.88	13.44	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.83	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:8	34.08	2352	1.88	13.45	100	192	Off Idle	73.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.83	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:8	34.08	2359	1.88	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.85	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:9	34.08	2365	1.88	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.88	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:9	34.08	2368	1.88	13.44	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.86	15.02	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:9	34.08	2384	1.88	13.46	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.85	15.01	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:9	34.08	2377	1.88	13.45	100	192	Off Idle	73.9	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.86	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:9	34.08	2377	1.88	13.45	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.17	Rich	1	14.6	-7.86	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:9	34.08	2378	1.88	13.44	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.84	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:17:9	34.08	2374	1.88	13.45	100	192	Off Idle	73.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.84	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:0	34.08	2373	1.88	13.44	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.85	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:0	34.08	2373	1.87	13.43	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.83	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:0	34.08	2370	1.87	13.43	100	192	Off Idle	73.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.85	14.9	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:0	34.08	2370	1.87	13.44	100	192	Off Idle	73.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.85	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:0	34.08	2368	1.87	13.45	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.87	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:0	34.08	2367	1.87	13.45	100	191	Off Idle	73.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.89	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:1	34.08	2368	1.87	13.44	100	191	Off Idle	73.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.87	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:18:1	34.08	2368	1.87	13.44	100	191	Off Idle	73.1	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.85	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:18:1	34.08	2373	1.87	13.44	100	192	Off Idle	73.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.87	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:18:1	34.08	2368	1.87	13.44	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.86	15.13	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:18:1	34.08	2378	1.87	13.45	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.84	15.14	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:18:1	34.08	2370	1.88	13.44	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.87	15.16	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:18:1	34.08	2370	1.88	13.43	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.85	15.18	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:18:2	34.08	2387	1.88	13.42	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.86	15.18	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:18:2	34.08	2368	1.88	13.43	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.84	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:2	34.08	2366	1.88	13.44	100	192	Off Idle	73	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.82	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:2	34.08	2370	1.88	13.44	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.83	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:2	34.08	2374	1.88	13.45	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.83	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:2	34.08	2374	1.88	13.46	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.85	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:3	34.08	2377	1.88	13.45	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.85	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:3	34.08	2378	1.88	13.45	100	192	Off Idle	73.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.85	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:3	34.08	2376	1.88	13.44	100	192	Off Idle	73.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.84	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:3	34.08	2376	1.88	13.44	100	192	Off Idle	73.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.81	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:3	34.08	2374	1.88	13.43	100	192	Off Idle	73	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.81	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:3	34.08	2368	1.88	13.44	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.8	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:4	34.08	2366	1.88	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:4	34.08	2362	1.88	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:4	34.08	2371	1.88	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.73	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:4	34.08	2371	1.88	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.7	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:4	34.08	2375	1.89	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.72	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:4	34.08	2372	1.89	13.45	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.76	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:4	34.08	2381	1.89	13.45	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.74	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:5	34.08	2380	1.89	13.45	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.74	15.08	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:5	34.08	2379	1.89	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.74	15.1	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:18:5	34.08	2369	1.89	13.44	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	15.1	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:5	34.08	2369	1.89	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.11	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:5	34.08	2376	1.9	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15.12	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:5	34.08	2368	1.9	13.44	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.12	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:6	34.08	2370	1.9	13.44	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	15.09	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:6	34.08	2368	1.9	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:6	34.08	2373	1.9	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.69	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:6	34.08	2379	1.91	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.67	15.03	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:6	34.08	2379	1.91	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.63	15.01	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:6	34.08	2391	1.91	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.61	14.98	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:6	34.08	2386	1.91	13.45	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.59	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:7	34.08	2386	1.91	13.44	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.55	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:7	34.08	2382	1.92	13.44	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.56	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:7	34.08	2381	1.92	13.44	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.55	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:7	34.08	2381	1.92	13.44	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.57	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:7	34.08	2379	1.92	13.44	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.53	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:7	34.08	2379	1.92	13.44	100	192	Off Idle	72.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.52	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:8	34.08	2379	1.92	13.45	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.53	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:8	34.08	2381	1.92	13.45	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.54	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:8	34.08	2384	1.93	13.45	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.56	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:8	34.08	2384	1.93	13.45	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.55	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:8	34.08	2386	1.93	13.45	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.56	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:8	34.08	2386	1.93	13.45	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.53	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:18:9	34.08	2386	1.93	13.46	99	192	Off Idle	72.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-7.51	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:9	34.08	2385	1.94	13.45	99	192	Off Idle	72.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.48	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:9	34.08	2378	1.94	13.44	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.46	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:9	34.08	2372	1.94	13.45	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.4	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:9	34.08	2374	1.94	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.39	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:9	34.08	2374	1.95	13.45	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.38	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:18:9	34.08	2371	1.95	13.46	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.34	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:0	34.08	2379	1.95	13.45	100	192	Off Idle	72.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.35	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:0	34.08	2391	1.95	13.44	99	192	Off Idle	73	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.36	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:0	34.08	2394	1.96	13.45	99	192	Off Idle	73	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.33	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:0	34.08	2400	1.96	13.45	99	192	Off Idle	73	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.34	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:0	34.08	2398	1.96	13.43	99	192	Off Idle	73	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.37	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:0	34.08	2393	1.96	13.43	99	192	Off Idle	72.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.36	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:1	34.08	2393	1.96	13.44	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.36	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:1	34.08	2384	1.96	13.42	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.37	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:1	34.08	2377	1.97	13.43	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.32	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:1	34.08	2377	1.97	13.44	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.28	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:1	34.08	2376	1.97	13.44	100	192	Off Idle	72.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.27	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:1	34.08	2377	1.97	13.44	100	192	Off Idle	72.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.27	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:1	34.08	2377	1.97	13.45	99	192	Off Idle	72.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.27	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:2	34.08	2379	1.97	13.45	99	192	Off Idle	72.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.29	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:2	34.08	2382	1.97	13.47	99	192	Off Idle	72.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.3	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:2	34.08	2382	1.97	13.46	100	192	Off Idle	72.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.32	15.07	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:2	34.08	2391	1.97	13.46	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.29	15.11	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:2	34.08	2412	1.97	13.46	100	192	Off Idle	72.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.31	15.13	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:2	34.08	2412	1.97	13.46	99	192	Off Idle	72.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.32	15.16	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:3	34.08	2395	1.97	13.45	99	192	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.33	15.2	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:3	34.08	2386	1.97	13.45	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.35	15.18	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:3	34.08	2367	1.97	13.44	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.38	15.14	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:3	34.08	2367	1.97	13.45	100	192	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.37	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:3	34.08	2388	1.97	13.44	99	192	Off Idle	72.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.4	15.08	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:3	34.08	2389	1.97	13.45	99	192	Off Idle	72.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.36	15.05	1.03	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:4	34.08	2393	1.97	13.45	99	192	Off Idle	72.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.33	15.01	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:4	34.08	2411	1.97	13.45	99	192	Off Idle	72.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.31	14.99	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:19:4	34.08	2396	1.97	13.44	99	192	Off Idle	72.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.27	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:19:4	34.08	2396	1.97	13.44	99	192	Off Idle	72.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.27	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:4	34.08	2400	1.97	13.43	99	192	Off Idle	72.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.29	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:4	34.08	2400	1.97	13.44	99	192	Off Idle	72.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.28	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:4	34.08	2400	1.97	13.44	99	192	Off Idle	72.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.3	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:5	34.08	2396	1.97	13.44	99	192	Off Idle	72.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.32	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:5	34.08	2388	1.97	13.42	100	192	Off Idle	72.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.31	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:5	34.08	2388	1.97	13.43	100	192	Off Idle	72.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.31	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:5	34.08	2383	1.97	13.44	100	192	Off Idle	72.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.28	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:5	34.08	2384	1.97	13.43	99	192	Off Idle	72.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.28	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:5	34.08	2385	1.97	13.45	99	192	Off Idle	72.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.23	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:19:6	34.08	2386	1.98	13.45	99	192	Off Idle	72	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.22	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:19:6	34.08	2389	1.98	13.45	99	192	Off Idle	72	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.19	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:6	34.08	2395	1.98	13.44	99	192	Off Idle	72	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.17	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:6	34.08	2398	1.98	13.44	99	192	Off Idle	72	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.16	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:6	34.08	2398	1.98	13.44	99	192	Off Idle	72	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.16	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:6	34.08	2394	1.98	13.44	99	192	Off Idle	72	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.16	15.15	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:6	34.08	2388	1.98	13.44	99	192	Off Idle	72	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.15	15.17	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:7	34.08	2388	1.99	13.44	100	192	Off Idle	71.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.14	15.17	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:7	34.08	2392	1.99	13.44	100	192	Off Idle	71.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.14	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:7	34.08	2397	1.99	13.44	100	192	Off Idle	72	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.13	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:7	34.08	2397	1.99	13.44	100	192	Off Idle	72	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.1	15.17	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:7	34.08	2402	2	13.44	100	192	Off Idle	72	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.06	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:7	34.08	2400	2	13.44	100	192	Off Idle	72	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.06	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:8	34.08	2404	2	13.44	99	192	Off Idle	72	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.04	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:8	34.08	2404	2	13.46	99	192	Off Idle	72	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.01	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:19:8	34.08	2405	2.01	13.44	99	192	Off Idle	72	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.01	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:19:8	34.08	2405	2.01	13.45	100	192	Off Idle	71.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.01	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:19:8	34.08	2406	2.01	13.45	100	192	Off Idle	71.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.96	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:19:8	34.08	2403	2.02	13.46	100	192	Off Idle	71.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.95	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:19:9	34.08	2407	2.02	13.46	100	192	Off Idle	71.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.94	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:19:9	34.08	2407	2.02	13.46	100	192	Off Idle	71.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.95	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:19:9	34.08	2399	2.03	13.46	100	192	Off Idle	71.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.94	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:19:9	34.08	2411	2.03	13.46	99	192	Off Idle	71.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.89	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:19:9	34.08	2412	2.04	13.45	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.85	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:19:9	34.08	2407	2.04	13.46	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.8	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:19:9	34.08	2407	2.04	13.45	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.76	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:0	34.08	2398	2.05	13.45	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.72	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:0	34.08	2398	2.05	13.44	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.72	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:0	34.08	2400	2.05	13.44	99	192	Off Idle	71	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.71	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:0	34.08	2403	2.06	13.43	99	192	Off Idle	71	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.7	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:0	34.08	2404	2.06	13.44	99	192	Off Idle	71	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.67	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:0	34.08	2406	2.06	13.44	99	192	Off Idle	70.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.65	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:1	34.08	2408	2.07	13.44	99	192	Off Idle	70.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.64	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:1	32.72	2407	2.07	13.45	99	192	Off Idle	70.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.6	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:1	32.72	2407	2.07	13.45	99	192	Off Idle	71.1	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.59	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:1	32.72	2408	2.07	13.44	99	192	Off Idle	71.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.61	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:1	32.72	2407	2.07	13.43	100	192	Off Idle	71.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.62	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:1	32.72	2406	2.07	13.44	100	192	Off Idle	71.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.61	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:1	32.72	2404	2.07	13.43	100	192	Off Idle	71.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.64	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:2	34.08	2423	2.08	13.44	99	192	Off Idle	71	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.63	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:2	34.08	2423	2.08	13.43	99	192	Off Idle	71	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.6	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:2	34.08	2413	2.08	13.42	99	192	Off Idle	70.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.58	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:2	34.08	2414	2.08	13.42	99	192	Off Idle	70.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.59	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:2	34.08	2414	2.08	13.42	99	192	Off Idle	70.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.58	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:2	34.08	2437	2.08	13.42	99	192	Off Idle	70.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.61	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:3	34.08	2411	2.08	13.46	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.6	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:3	34.08	2409	2.08	13.45	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.63	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:3	34.08	2408	2.08	13.44	100	192	Off Idle	70.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.6	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:20:3	34.08	2408	2.08	13.45	100	192	Off Idle	71.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.57	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:3	34.08	2410	2.08	13.46	100	192	Off Idle	71.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.55	14.78	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:3	34.08	2414	2.08	13.45	100	192	Off Idle	70.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.56	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:4	34.08	2414	2.08	13.47	99	192	Off Idle	70.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.53	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:4	32.72	2396	2.09	13.48	99	192	Off Idle	71.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.55	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:4	32.72	2416	2.09	13.46	99	192	Off Idle	71.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.58	14.78	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:4	32.72	2416	2.09	13.45	100	192	Off Idle	71.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.59	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:4	32.72	2419	2.09	13.45	100	192	Off Idle	71.1	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.61	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:4	32.72	2422	2.09	13.45	100	192	Off Idle	71.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.61	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:4	32.72	2424	2.09	13.45	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.57	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:5	32.72	2423	2.09	13.44	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.6	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:5	32.72	2420	2.09	13.44	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.55	14.9	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:5	32.72	2415	2.09	13.45	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.54	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:5	32.72	2415	2.09	13.44	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.53	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:5	32.72	2412	2.09	13.43	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.54	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:5	32.72	2393	2.09	13.43	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.51	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:20:6	34.08	2404	2.09	13.43	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.52	15.05	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:6	34.08	2428	2.09	13.44	99	192	Off Idle	71.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.5	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:6	34.08	2427	2.09	13.44	99	192	Off Idle	71.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.52	15.02	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:20:6	34.08	2446	2.1	13.44	99	192	Off Idle	71.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.49	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:6	34.08	2436	2.1	13.44	100	192	Off Idle	71.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.48	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:6	34.08	2430	2.1	13.44	100	192	Off Idle	71.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.44	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:6	34.08	2429	2.1	13.44	100	192	Off Idle	71.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.42	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:7	34.08	2429	2.11	13.44	99	192	Off Idle	71.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.42	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:7	34.08	2430	2.11	13.45	99	192	Off Idle	71	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.39	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:7	34.08	2429	2.11	13.45	99	192	Off Idle	71	0	2	132	944 Turbo	0.18	Rich	1	14.6	-6.34	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:7	34.08	2427	2.12	13.46	100	192	Off Idle	71	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.3	14.76	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:20:7	34.08	2428	2.12	13.45	100	192	Off Idle	70.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.27	14.76	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:20:7	34.08	2428	2.12	13.46	100	192	Off Idle	70.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.24	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:20:8	34.08	2431	2.13	13.47	99	192	Off Idle	70.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.23	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:20:8	34.08	2431	2.13	13.46	99	192	Off Idle	70.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.21	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:8	34.08	2434	2.14	13.45	99	192	Off Idle	70	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.21	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:8	34.08	2433	2.14	13.46	100	192	Off Idle	70	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.21	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:8	34.08	2432	2.14	13.46	100	192	Off Idle	70	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.19	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:8	34.08	2425	2.15	13.45	100	192	Off Idle	70	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.16	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:9	34.08	2425	2.15	13.45	100	192	Off Idle	70	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.13	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:9	34.08	2425	2.15	13.44	100	192	Off Idle	70	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.1	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:9	34.08	2426	2.16	13.43	99	192	Off Idle	70	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.09	15.18	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:9	34.08	2428	2.16	13.44	99	192	Off Idle	70	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.07	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:9	34.08	2429	2.16	13.45	99	192	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.05	15.13	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:9	34.08	2429	2.16	13.44	99	192	Off Idle	70	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.03	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:20:9	34.08	2431	2.17	13.45	99	192	Off Idle	70	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.05	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:21:0	34.08	2435	2.17	13.45	99	192	Off Idle	70	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.02	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:21:0	34.08	2439	2.17	13.44	99	192	Off Idle	70	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.99	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:21:0	34.08	2433	2.17	13.45	99	192	Off Idle	70.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.02	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:21:0	34.08	2432	2.17	13.43	99	192	Off Idle	70.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.97	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:21:0	34.08	2430	2.18	13.43	99	192	Off Idle	70.1	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.99	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:21:0	34.08	2433	2.18	13.43	99	192	Off Idle	70.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.96	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:1	34.08	2433	2.18	13.44	99	192	Off Idle	70	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.9	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:1	34.08	2440	2.18	13.44	99	192	Off Idle	70	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.88	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:1	34.08	2442	2.19	13.44	99	192	Off Idle	69.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.83	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:1	34.08	2441	2.19	13.43	99	192	Off Idle	69.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.79	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:1	34.08	2442	2.19	13.44	99	192	Off Idle	69.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.76	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:1	34.08	2447	2.2	13.45	99	192	Off Idle	69.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.78	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:1	34.08	2445	2.2	13.45	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.75	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:2	34.08	2446	2.2	13.45	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.72	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:2	34.08	2450	2.21	13.45	100	192	Off Idle	69.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.71	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:2	34.08	2449	2.21	13.45	99	192	Off Idle	69.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.69	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:21:2	34.08	2449	2.21	13.43	99	192	Off Idle	69.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.67	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:2	34.08	2451	2.22	13.44	99	192	Off Idle	69.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.61	15	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:2	34.08	2447	2.22	13.44	100	192	Off Idle	69.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.59	15.03	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:3	34.08	2436	2.23	13.44	100	192	Off Idle	69.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.57	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:3	34.08	2442	2.23	13.45	100	192	Off Idle	69.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.53	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:3	34.08	2442	2.23	13.46	100	192	Off Idle	69.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.53	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:3	34.08	2442	2.24	13.45	100	192	Off Idle	69.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.5	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:3	34.08	2443	2.24	13.46	100	192	Off Idle	69.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.51	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:3	34.08	2445	2.24	13.47	99	192	Off Idle	69.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.48	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:4	34.08	2445	2.24	13.46	99	192	Off Idle	69.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.48	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:4	34.08	2450	2.25	13.47	100	192	Off Idle	69	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.49	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:4	34.08	2446	2.25	13.46	100	192	Off Idle	68.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.5	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:4	34.08	2429	2.25	13.46	100	192	Off Idle	68.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.5	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:4	34.08	2439	2.25	13.46	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.49	14.98	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:4	32.72	2441	2.25	13.46	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.47	14.92	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:4	32.72	2449	2.25	13.45	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.46	14.89	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:5	32.72	2467	2.25	13.45	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.43	14.86	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:5	32.72	2458	2.25	13.45	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.43	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:5	32.72	2449	2.25	13.45	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.43	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:5	32.72	2455	2.25	13.46	99	192	Off Idle	68.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.48	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:5	32.72	2455	2.25	13.44	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.5	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:5	32.72	2451	2.25	13.43	99	192	Off Idle	69	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.5	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:6	32.72	2473	2.25	13.43	99	192	Off Idle	69.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.52	14.78	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:6	32.72	2476	2.25	13.43	99	192	Off Idle	69.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.59	14.81	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:6	32.72	2474	2.25	13.45	99	192	Off Idle	69.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.6	14.86	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:6	32.72	2480	2.25	13.45	99	192	Off Idle	69	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.64	14.9	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:6	32.72	2469	2.25	13.44	99	192	Off Idle	68.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.62	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:21:21:6	34.08	2460	2.25	13.44	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.6	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:6	34.08	2451	2.25	13.44	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.59	14.98	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:7	34.08	2441	2.24	13.43	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.6	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:7	34.08	2441	2.24	13.44	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.63	15.05	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:7	34.08	2460	2.24	13.44	100	192	Off Idle	69.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.63	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:7	34.08	2463	2.24	13.44	100	192	Off Idle	69.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.63	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:7	34.08	2464	2.24	13.44	100	192	Off Idle	69.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.67	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:7	34.08	2474	2.24	13.45	100	192	Off Idle	69.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.67	15.08	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:21:8	34.08	2463	2.24	13.44	100	192	Off Idle	68.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.7	15.05	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:21:8	34.08	2461	2.24	13.43	99	192	Off Idle	68.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.68	15.01	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:21:8	34.08	2461	2.24	13.43	99	192	Off Idle	68.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.68	14.97	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:21:8	34.08	2461	2.24	13.43	99	192	Off Idle	68.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.67	14.96	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:21:8	32.72	2461	2.23	13.44	99	192	Off Idle	68.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.65	14.91	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:21:8	32.72	2454	2.23	13.45	99	192	Off Idle	68.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.67	14.86	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:21:9	32.72	2459	2.23	13.45	99	192	Off Idle	68.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.68	14.79	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:21:9	32.72	2465	2.23	13.44	100	192	Off Idle	68.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.71	14.75	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:9	32.72	2465	2.23	13.45	100	192	Off Idle	68.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.73	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:9	32.72	2467	2.23	13.44	100	192	Off Idle	68.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.77	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:9	32.72	2466	2.23	13.45	99	192	Off Idle	68.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.8	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:9	32.72	2470	2.23	13.44	99	192	Off Idle	68.1	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.8	14.79	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:21:9	32.72	2471	2.23	13.44	99	192	Off Idle	68.1	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.8	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:0	32.72	2470	2.22	13.45	99	192	Off Idle	68	0	2	132	944 Turbo	0.15	Rich	1	14.6	-5.79	14.78	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:0	32.72	2470	2.22	13.45	99	192	Off Idle	68	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.81	14.81	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:0	32.72	2466	2.22	13.44	99	192	Off Idle	68	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.81	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:0	34.08	2481	2.22	13.43	99	192	Off Idle	68	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.84	14.89	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:0	34.08	2472	2.22	13.43	99	192	Off Idle	68	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.86	14.92	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:0	34.08	2465	2.22	13.43	99	192	Off Idle	68	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.89	14.96	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:1	34.08	2465	2.22	13.44	99	192	Off Idle	68.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.88	14.99	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:1	34.08	2474	2.21	13.42	99	192	Off Idle	68.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.91	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:1	34.08	2472	2.21	13.42	99	192	Off Idle	68.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.93	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:1	34.08	2485	2.21	13.43	99	192	Off Idle	68.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.92	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:22:1	34.08	2486	2.21	13.45	99	192	Off Idle	68.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.95	15.14	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:1	34.08	2489	2.21	13.44	99	192	Off Idle	68.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:1	34.08	2503	2.2	13.46	99	192	Off Idle	68	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.01	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:2	34.08	2494	2.2	13.46	99	192	Off Idle	67.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.02	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:2	34.08	2484	2.2	13.45	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6	15.13	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:2	34.08	2484	2.2	13.45	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.06	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:2	34.08	2489	2.2	13.46	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.02	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:2	34.08	2489	2.2	13.45	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.02	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:2	34.08	2481	2.2	13.45	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.01	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:3	34.08	2478	2.2	13.45	99	192	Off Idle	67.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.99	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:3	34.08	2478	2.2	13.45	99	192	Off Idle	67.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.02	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:3	34.08	2480	2.2	13.44	99	192	Off Idle	67.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.03	14.74	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:3	34.08	2485	2.2	13.45	99	192	Off Idle	67.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.01	14.71	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:3	34.08	2486	2.2	13.44	99	192	Off Idle	67.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.02	14.67	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:3	34.08	2489	2.2	13.45	99	192	Off Idle	67.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.03	14.68	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:4	34.08	2493	2.2	13.46	99	192	Off Idle	67.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6	14.7	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:4	34.08	2492	2.2	13.47	99	192	Off Idle	67.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.02	14.7	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:4	34.08	2492	2.2	13.45	99	192	Off Idle	67.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.04	14.69	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:4	34.08	2487	2.2	13.46	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.02	14.73	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:4	34.08	2482	2.2	13.44	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.03	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:4	34.08	2473	2.2	13.45	99	192	Off Idle	67.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.02	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:4	34.08	2472	2.2	13.45	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.01	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:5	34.08	2470	2.2	13.43	99	192	Off Idle	67.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.01	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:5	34.08	2476	2.2	13.43	99	192	Off Idle	67.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.01	14.94	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:5	34.08	2476	2.2	13.43	99	192	Off Idle	67.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.01	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:5	34.08	2488	2.2	13.43	99	192	Off Idle	67.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.01	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:5	34.08	2492	2.2	13.44	99	192	Off Idle	67.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.01	15.06	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:5	34.08	2494	2.2	13.44	99	192	Off Idle	67.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.99	15.1	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:6	34.08	2498	2.2	13.44	99	192	Off Idle	67.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6	15.11	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:6	34.08	2517	2.2	13.44	99	192	Off Idle	67.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.02	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:6	34.08	2499	2.2	13.44	99	192	Off Idle	67.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.99	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:6	34.08	2498	2.2	13.44	99	192	Off Idle	67	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6	15.05	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:6	34.08	2495	2.2	13.44	99	192	Off Idle	67	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.01	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:6	34.08	2492	2.2	13.45	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.98	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:6	34.08	2495	2.2	13.45	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.97	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:7	34.08	2497	2.2	13.45	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.04	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:7	34.08	2500	2.2	13.44	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.04	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:7	34.08	2499	2.2	13.44	99	192	Off Idle	66.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.03	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:7	34.08	2498	2.2	13.44	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.02	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:7	34.08	2496	2.2	13.44	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.01	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:7	34.08	2496	2.2	13.44	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.95	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:22:8	34.08	2497	2.2	13.44	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.98	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:8	34.08	2497	2.2	13.44	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.93	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:8	34.08	2495	2.2	13.43	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.94	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:8	34.08	2497	2.2	13.43	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.95	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:8	34.08	2498	2.21	13.42	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.94	14.9	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:8	34.08	2498	2.21	13.42	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.96	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:9	34.08	2498	2.21	13.44	99	192	Off Idle	66	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.02	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:9	34.08	2499	2.21	13.43	99	192	Off Idle	66	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.02	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:9	34.08	2500	2.21	13.44	99	192	Off Idle	66	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.02	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:22:9	34.08	2503	2.21	13.45	99	192	Off Idle	66	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.02	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:9	34.08	2506	2.21	13.45	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.06	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:9	34.08	2506	2.21	13.44	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.02	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:22:9	34.08	2511	2.21	13.44	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:0	34.08	2507	2.21	13.44	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.99	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:0	34.08	2507	2.21	13.44	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.02	14.9	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:23:0	34.08	2508	2.21	13.45	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.99	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:0	34.08	2510	2.21	13.44	100	192	Off Idle	66.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.02	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:23:0	34.08	2511	2.21	13.44	100	192	Off Idle	66.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.02	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:23:0	34.08	2510	2.21	13.44	100	192	Off Idle	66.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:23:1	34.08	2510	2.21	13.45	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.06	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:23:1	34.08	2510	2.21	13.44	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.05	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:1	34.08	2509	2.21	13.44	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.02	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:23:1	34.08	2505	2.21	13.44	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.02	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:21:23:1	34.08	2503	2.21	13.44	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:1	34.08	2501	2.21	13.44	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.01	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:1	34.08	2502	2.21	13.44	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.99	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:2	34.08	2501	2.21	13.44	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:2	34.08	2500	2.21	13.43	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.01	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:2	34.08	2498	2.21	13.45	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.02	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:2	34.08	2500	2.21	13.44	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.69	Lean	1	14.6	-6.03	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:2	34.08	2503	2.21	13.45	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.03	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:2	34.08	2512	2.21	13.44	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.08	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:3	34.08	2512	2.21	13.45	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.05	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:3	34.08	2523	2.21	13.44	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.07	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:3	34.08	2529	2.21	13.45	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.07	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:3	34.08	2529	2.21	13.44	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.09	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:3	34.08	2525	2.21	13.45	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.06	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:3	34.08	2527	2.21	13.45	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.1	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:4	34.08	2526	2.21	13.49	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.1	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:4	34.08	2524	2.21	13.52	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.13	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:4	34.08	2501	2.21	13.54	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.12	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:4	34.08	2501	2.21	13.57	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.13	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:4	34.08	2515	2.2	13.58	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.13	14.86	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:4	34.08	2514	2.2	13.56	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.17	14.84	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:4	34.08	2506	2.2	13.57	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.16	14.83	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:5	34.08	2506	2.2	13.57	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.17	14.84	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:5	34.08	2506	2.2	13.58	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.23	14.84	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:5	34.08	2504	2.2	13.56	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.23	14.86	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:21:23:5	34.08	2504	2.2	13.56	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.23	14.87	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:5	34.08	2501	2.2	13.56	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.24	14.89	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:5	34.08	2505	2.19	13.56	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.23	14.88	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:6	34.08	2507	2.19	13.56	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.23	14.89	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:6	34.08	2506	2.19	13.56	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.2	14.92	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:6	34.08	2510	2.19	13.56	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.23	14.96	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:6	34.08	2537	2.19	13.56	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.27	15.01	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:6	34.08	2530	2.18	13.56	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.27	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:6	34.08	2530	2.18	13.56	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.31	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:6	34.08	2549	2.18	13.57	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.36	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:7	34.08	2538	2.18	13.56	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.37	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:7	34.08	2526	2.18	13.57	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.37	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:7	34.08	2524	2.18	13.58	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.38	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:7	34.08	2500	2.17	13.59	99	191	Off Idle	64.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.4	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:7	34.08	2500	2.17	13.58	99	191	Off Idle	64.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.39	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:7	34.08	2522	2.17	13.57	100	191	Off Idle	64.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.4	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:8	34.08	2521	2.17	13.58	100	192	Off Idle	64.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.39	14.75	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:8	34.08	2520	2.17	13.57	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.4	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:8	34.08	2519	2.17	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.39	14.73	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:8	34.08	2532	2.17	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.41	14.74	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:8	34.08	2535	2.17	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.18	Rich	1	14.6	-6.41	14.73	1	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:8	34.08	2536	2.17	13.56	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.46	14.76	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:9	34.08	2552	2.17	13.56	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.46	14.78	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:9	34.08	2528	2.17	13.56	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.49	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:23:9	34.08	2528	2.17	13.56	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.47	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:9	34.08	2523	2.17	13.56	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.5	14.9	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:9	34.08	2516	2.17	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.48	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:23:9	34.08	2516	2.17	13.57	99	192	Off Idle	65	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.51	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:23:9	34.08	2516	2.17	13.59	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.54	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:0	34.08	2521	2.17	13.57	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.52	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:0	34.08	2524	2.16	13.57	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.49	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:0	34.08	2530	2.16	13.57	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.5	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:0	34.08	2534	2.16	13.57	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.49	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:0	34.08	2534	2.16	13.58	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.53	15.09	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:0	34.08	2532	2.16	13.58	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.56	15.06	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:1	34.08	2570	2.16	13.57	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.54	15.05	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:1	34.08	2552	2.16	13.57	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.57	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:1	34.08	2530	2.16	13.58	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.56	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:1	34.08	2529	2.16	13.57	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.54	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:1	34.08	2530	2.16	13.59	99	192	Off Idle	64.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.53	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:1	34.08	2533	2.16	13.57	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.53	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:1	34.08	2540	2.16	13.57	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.51	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:2	34.08	2540	2.16	13.59	99	191	Off Idle	64.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.56	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:2	34.08	2541	2.16	13.58	99	191	Off Idle	64	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.6	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:2	34.08	2541	2.16	13.57	99	191	Off Idle	63.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.58	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:2	34.08	2534	2.16	13.57	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.58	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:2	34.08	2532	2.16	13.59	100	192	Off Idle	63.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.57	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:2	34.08	2528	2.16	13.58	100	192	Off Idle	63.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.56	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:3	34.08	2529	2.16	13.56	100	192	Off Idle	63.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.54	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:3	34.08	2531	2.16	13.55	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.51	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:3	34.08	2536	2.16	13.56	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.53	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:3	34.08	2541	2.16	13.54	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.5	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:3	34.08	2543	2.16	13.54	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.48	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:3	34.08	2542	2.16	13.55	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.51	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:4	34.08	2543	2.16	13.57	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.5	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:4	34.08	2543	2.16	13.56	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.56	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:4	34.08	2543	2.16	13.56	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.55	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:4	34.08	2540	2.16	13.58	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.57	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:4	34.08	2528	2.16	13.59	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.61	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:4	34.08	2528	2.16	13.59	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.63	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:4	34.08	2508	2.16	13.58	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.69	Lean	1	14.6	-6.6	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:5	34.08	2528	2.16	13.57	99	191	Off Idle	63.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.58	15.16	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:5	34.08	2531	2.16	13.56	99	191	Off Idle	63.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.55	15.13	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:5	34.08	2532	2.16	13.57	99	191	Off Idle	63.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.56	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:5	34.08	2537	2.16	13.56	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.54	15.05	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:5	34.08	2562	2.16	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.51	15.03	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:5	34.08	2554	2.16	13.59	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.51	14.97	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:6	34.08	2545	2.16	13.59	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.55	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:6	34.08	2546	2.16	13.59	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.54	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:6	34.08	2545	2.16	13.58	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.53	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:6	34.08	2553	2.16	13.59	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.55	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:6	34.08	2542	2.16	13.58	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.58	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:6	34.08	2542	2.16	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.59	14.74	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:6	34.08	2542	2.16	13.56	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.58	14.73	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:7	34.08	2538	2.16	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.57	14.72	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:7	34.08	2540	2.16	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.54	14.74	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:7	34.08	2542	2.16	13.56	99	191	Off Idle	63.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.54	14.78	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:7	34.08	2546	2.16	13.58	99	191	Off Idle	63.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.54	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:7	34.08	2540	2.16	13.58	99	191	Off Idle	63.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.56	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:7	34.08	2547	2.16	13.56	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.53	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:8	34.08	2546	2.16	13.56	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.54	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:8	34.08	2546	2.16	13.56	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.54	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:8	34.08	2540	2.17	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.51	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:8	34.08	2539	2.17	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.51	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:8	34.08	2540	2.17	13.57	99	191	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.49	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:24:8	34.08	2541	2.17	13.59	99	191	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.45	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:9	34.08	2544	2.17	13.59	99	191	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.44	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:9	34.08	2548	2.17	13.58	99	191	Off Idle	63.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.43	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:9	34.08	2550	2.17	13.6	99	191	Off Idle	63.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.41	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:9	34.08	2555	2.17	13.6	99	191	Off Idle	63.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.41	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:24:9	34.08	2555	2.18	13.58	99	191	Off Idle	63.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.44	14.91	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:9	34.08	2558	2.18	13.57	99	191	Off Idle	63.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.42	14.86	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:24:9	34.08	2558	2.18	13.56	99	191	Off Idle	63.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.43	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:0	34.08	2560	2.18	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.42	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:0	34.08	2558	2.18	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.4	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:0	34.08	2552	2.18	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.44	14.83	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:0	34.08	2552	2.18	13.58	99	191	Off Idle	63.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.44	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:0	34.08	2549	2.18	13.58	99	191	Off Idle	63	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.41	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:0	34.08	2553	2.19	13.58	99	191	Off Idle	63	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.43	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:1	34.08	2553	2.19	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.43	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:1	34.08	2558	2.19	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.37	14.92	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:1	34.08	2561	2.19	13.58	99	191	Off Idle	63	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.35	14.96	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:1	34.08	2558	2.19	13.59	99	191	Off Idle	63.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.37	14.99	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:1	34.08	2554	2.19	13.58	99	191	Off Idle	63.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.34	15.02	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:1	34.08	2553	2.19	13.59	99	192	Off Idle	63.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.41	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:1	34.08	2553	2.19	13.59	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.42	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:2	34.08	2551	2.19	13.58	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.41	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:2	34.08	2550	2.19	13.58	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.39	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:2	34.08	2549	2.19	13.58	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.38	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:2	34.08	2550	2.19	13.58	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.4	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:2	34.08	2556	2.19	13.58	99	191	Off Idle	63.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.39	15.14	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:2	34.08	2556	2.19	13.58	99	191	Off Idle	63.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.4	15.12	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:3	34.08	2556	2.19	13.59	99	191	Off Idle	63.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.38	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:3	34.08	2561	2.19	13.58	99	191	Off Idle	63.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.44	15.05	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:3	34.08	2562	2.19	13.59	99	191	Off Idle	63.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.44	15.03	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:3	34.08	2562	2.19	13.57	99	191	Off Idle	63.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.44	15.01	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:3	34.08	2562	2.19	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.44	15	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:3	34.08	2560	2.19	13.56	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.45	14.96	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:4	34.08	2562	2.19	13.56	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.44	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:4	34.08	2562	2.19	13.56	99	191	Off Idle	62.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.47	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:4	34.08	2552	2.19	13.58	99	191	Off Idle	63	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.47	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:4	34.08	2552	2.19	13.57	99	191	Off Idle	63	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.44	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:4	34.08	2552	2.19	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.44	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:4	34.08	2559	2.19	13.6	99	192	Off Idle	63	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.48	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:4	34.08	2563	2.19	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.46	14.88	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:5	34.08	2568	2.19	13.58	99	191	Off Idle	63	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.45	14.87	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:5	34.08	2568	2.19	13.59	99	191	Off Idle	63	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.51	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:5	34.08	2574	2.18	13.58	99	191	Off Idle	63	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.51	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:5	34.08	2572	2.18	13.58	99	192	Off Idle	63.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.52	14.9	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:5	34.08	2569	2.18	13.59	99	192	Off Idle	63.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.48	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:5	34.08	2558	2.18	13.59	99	192	Off Idle	63.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.49	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:6	34.08	2513	2.18	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.46	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:6	34.08	2554	2.18	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.44	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:6	34.08	2555	2.18	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.44	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:6	34.08	2556	2.18	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.44	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:6	34.08	2561	2.18	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.46	15.07	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:6	34.08	2562	2.18	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.45	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:6	34.08	2569	2.18	13.58	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.47	15.09	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:7	34.08	2575	2.18	13.58	99	192	Off Idle	63.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.52	15.11	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:7	34.08	2575	2.18	13.59	99	191	Off Idle	63	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.51	15.09	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:7	34.08	2596	2.18	13.57	99	191	Off Idle	62.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.49	15.07	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:7	34.08	2572	2.18	13.57	99	191	Off Idle	62.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.47	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:7	34.08	2572	2.18	13.58	99	191	Off Idle	62.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.5	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:25:7	34.08	2568	2.18	13.57	99	191	Off Idle	62.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.52	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:25:8	34.08	2544	2.18	13.56	99	191	Off Idle	62.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.46	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:8	34.08	2544	2.18	13.58	99	192	Off Idle	62.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.48	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:8	34.08	2556	2.18	13.57	99	192	Off Idle	61.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.47	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:8	34.08	2554	2.18	13.58	99	192	Off Idle	61.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.42	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:8	34.08	2559	2.18	13.58	99	191	Off Idle	61.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.41	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:8	34.08	2562	2.18	13.57	99	191	Off Idle	61.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.44	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:9	34.08	2575	2.19	13.59	99	192	Off Idle	61.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.45	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:9	34.08	2572	2.19	13.59	99	192	Off Idle	61.9	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.49	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:9	34.08	2575	2.19	13.59	99	192	Off Idle	61.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.5	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:9	34.08	2575	2.19	13.6	99	191	Off Idle	61.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.49	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:9	34.08	2576	2.19	13.58	99	191	Off Idle	61.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.45	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:9	34.08	2576	2.19	13.59	99	191	Off Idle	61.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.44	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:25:9	34.08	2573	2.19	13.58	99	191	Off Idle	61.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.43	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:0	34.08	2574	2.19	13.58	99	191	Off Idle	61.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.49	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:0	34.08	2572	2.19	13.58	99	191	Off Idle	61.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.48	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:0	34.08	2569	2.19	13.57	99	192	Off Idle	61.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.48	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:0	34.08	2569	2.19	13.56	99	192	Off Idle	61.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.5	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:0	34.08	2566	2.19	13.56	100	192	Off Idle	61.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.46	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:0	34.08	2554	2.19	13.56	100	192	Off Idle	61.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.5	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:1	34.08	2568	2.19	13.56	100	192	Off Idle	61.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.5	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:1	34.08	2570	2.19	13.56	99	192	Off Idle	61.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.52	15.11	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:1	34.08	2575	2.19	13.57	99	192	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.52	15.12	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:1	34.08	2577	2.19	13.57	99	192	Off Idle	61.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.54	15.11	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:1	34.08	2575	2.19	13.59	99	192	Off Idle	61.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.53	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:1	34.08	2575	2.19	13.57	99	192	Off Idle	61.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.53	15.03	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:1	34.08	2576	2.18	13.57	99	192	Off Idle	61.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.54	15	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:2	34.08	2576	2.18	13.57	99	192	Off Idle	61.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.6	14.96	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:2	34.08	2574	2.17	13.56	99	192	Off Idle	61.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.74	14.94	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:2	34.08	2582	2.16	13.56	99	192	Off Idle	61.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.88	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:26:2	34.08	2571	2.14	13.58	99	191	Off Idle	61.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.07	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:26:2	34.08	2572	2.11	13.56	99	191	Off Idle	61.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.31	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:26:2	34.08	2572	2.07	13.58	99	191	Off Idle	61.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.69	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:26:3	34.08	2568	2.06	13.56	99	192	Off Idle	62	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.82	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:26:3	34.08	2561	2.02	13.56	99	192	Off Idle	62.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.2	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:3	34.08	2560	2	13.58	99	192	Off Idle	62.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.4	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:3	34.08	2544	1.97	13.6	99	192	Off Idle	62.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.62	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:3	34.08	2549	1.94	13.59	99	192	Off Idle	62.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.79	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:3	34.08	2548	1.91	13.58	99	192	Off Idle	62.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.92	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:4	34.08	2536	1.89	13.6	99	192	Off Idle	62.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.06	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:4	34.08	2548	1.86	13.59	99	191	Off Idle	62.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.19	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:4	34.08	2548	1.83	13.58	99	191	Off Idle	62.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.29	14.92	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:4	35.45	2546	1.8	13.57	99	192	Off Idle	62.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.37	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:4	35.45	2526	1.77	13.57	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.46	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:4	35.45	2539	1.74	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.51	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:4	35.45	2539	1.71	13.57	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.6	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:5	35.45	2547	1.68	13.58	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.63	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:26:5	35.45	2547	1.66	13.58	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.69	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:5	35.45	2596	1.63	13.6	99	191	Off Idle	63.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.73	14.82	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:5	35.45	2589	1.61	13.59	99	191	Off Idle	63.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.77	14.77	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:5	35.45	2591	1.6	13.58	99	191	Off Idle	63.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.82	14.68	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:5	35.45	2592	1.6	13.57	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.8	14.59	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:6	35.45	2569	1.59	13.58	99	192	Off Idle	63.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.83	14.5	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:6	35.45	2589	1.59	13.56	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.87	14.48	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:6	35.45	2586	1.58	13.56	99	192	Off Idle	63.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.87	14.47	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:6	35.45	2582	1.58	13.56	99	192	Off Idle	63	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.88	14.48	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:6	35.45	2572	1.57	13.58	99	192	Off Idle	62.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.96	14.5	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:6	35.45	2572	1.57	13.56	99	192	Off Idle	62.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.99	14.55	0.99	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:26:6	35.45	2567	1.55	13.58	99	192	Full Load	62.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.04	14.67	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:26:7	35.45	2564	1.54	13.58	99	192	Idle	61.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.08	14.74	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:26:7	35.45	2564	1.53	13.58	99	191	Idle	61.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.15	14.87	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:7	35.45	2556	1.52	13.58	99	191	Idle	61.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.24	15.05	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:7	35.45	2541	1.51	13.59	99	191	Idle	61.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.29	15.15	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:7	35.45	2533	1.49	13.57	99	191	Idle	61.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.33	15.25	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:7	35.45	2520	1.48	13.58	99	191	Idle	61.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.37	15.36	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:8	32.72	2491	1.48	13.57	99	191	Idle	61.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.41	15.46	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:8	32.72	2456	1.47	13.57	99	192	Idle	62	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.4	15.53	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:26:8	27.27	2456	1.46	13.57	99	192	Idle	62.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-10.42	15.57	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:26:8	21.81	2454	1.45	13.57	99	192	Idle	62.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-10.43	15.59	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:26:8	21.81	2454	1.44	13.57	99	192	Idle	62.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.45	15.56	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:26:8	19.09	2474	1.43	13.58	99	192	Idle	62.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.43	15.54	1.06	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:9	19.09	2542	1.41	13.58	99	192	Idle	63.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.47	15.5	1.06	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:9	19.09	2574	1.4	13.58	99	192	Idle	63.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.48	15.43	1.05	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:9	19.09	2586	1.39	13.57	99	192	Idle	63.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-10.5	15.36	1.05	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:9	19.09	2598	1.38	13.58	99	192	Idle	63.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.54	15.29	1.04	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:9	19.09	2590	1.37	13.57	99	192	Idle	63.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.53	15.22	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:9	19.09	2601	1.36	13.56	99	191	Idle	63.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-10.55	15.17	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:26:9	19.09	2588	1.36	13.57	99	191	Idle	63.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-10.57	15.14	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:0	19.09	2560	1.36	13.58	99	191	Idle	63.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.57	15.12	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:0	19.09	2539	1.36	13.58	99	191	Idle	63.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.57	15.07	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:0	19.09	2525	1.36	13.57	99	191	Idle	63.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.52	15.03	1.02	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:0	19.09	2493	1.36	13.58	99	192	Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.48	15	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:0	19.09	2512	1.36	13.59	99	192	Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.45	14.98	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:0	19.09	2512	1.36	13.58	99	192	Idle	62.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.4	14.96	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:1	19.09	2514	1.36	13.59	99	191	Idle	62.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.34	14.94	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:1	19.09	2528	1.36	13.58	99	191	Idle	62	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.32	14.92	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:1	19.09	2546	1.36	13.57	99	191	Idle	62	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.32	14.9	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:1	19.09	2546	1.36	13.59	99	192	Idle	61.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	14.86	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:1	19.09	2576	1.36	13.6	99	192	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	14.81	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:1	19.09	2558	1.36	13.59	99	192	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	14.8	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:1	19.09	2557	1.37	13.58	99	191	Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	14.81	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:2	19.09	2565	1.37	13.59	99	191	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	14.86	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:2	19.09	2546	1.37	13.59	99	191	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	14.93	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:2	19.09	2515	1.37	13.58	99	191	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	15.02	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:2	19.09	2522	1.37	13.58	99	191	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	15.22	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:2	19.09	2517	1.37	13.56	99	191	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	15.41	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:2	19.09	2510	1.37	13.58	99	191	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	15.64	1.07	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:3	19.09	2509	1.37	13.59	99	191	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	15.95	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:3	19.09	2509	1.37	13.59	99	192	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	16.36	1.11	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:3	19.09	2515	1.37	13.59	99	192	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	16.84	1.15	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:3	19.09	2544	1.37	13.59	99	192	Idle	63	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	17.57	1.2	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:3	19.09	2537	1.37	13.58	99	192	Full Load	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	18.03	1.23	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:3	19.09	2534	1.37	13.58	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	18.48	1.26	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:4	19.09	2537	1.37	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	18.9	1.29	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:4	19.09	2537	1.38	13.56	99	192	Off Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	19.29	1.31	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:4	19.09	2472	1.38	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	19.77	1.35	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:4	10.9	2547	1.39	13.56	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.01	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:4	13.63	2544	1.39	13.56	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.16	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:27:4	13.63	2540	1.4	13.56	99	191	Off Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:27:4	16.36	2539	1.41	13.57	99	191	Off Idle	63.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:27:5	19.09	2538	1.41	13.57	99	191	Off Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:27:5	19.09	2543	1.42	13.59	99	191	Off Idle	63.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:27:5	21.81	2543	1.43	13.58	99	191	Off Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:27:5	24.54	2550	1.43	13.6	99	191	Off Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:27:5	24.54	2540	1.44	13.6	99	191	Off Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:27:5	27.27	2552	1.45	13.58	99	192	Off Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:27:6	29.99	2571	1.46	13.59	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:27:6	29.99	2568	1.47	13.58	99	192	Off Idle	64.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:27:6	32.72	2584	1.49	13.58	99	192	Off Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:6	35.45	2570	1.5	13.57	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:6	35.45	2532	1.51	13.59	99	192	Off Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:6	35.45	2529	1.52	13.58	99	191	Off Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:6	35.45	2528	1.53	13.59	99	191	Off Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:7	35.45	2529	1.54	13.58	99	191	Off Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:7	35.45	2526	1.55	13.59	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:7	35.45	2526	1.56	13.6	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:7	35.45	2519	1.56	13.59	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:7	35.45	2516	1.57	13.58	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:27:7	35.45	2516	1.58	13.59	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:8	35.45	2507	1.58	13.58	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:8	35.45	2505	1.59	13.56	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:8	35.45	2503	1.6	13.56	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:8	35.45	2502	1.6	13.57	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:8	35.45	2504	1.61	13.57	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:8	35.45	2507	1.62	13.59	99	192	Off Idle	64.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:9	35.45	2496	1.62	13.58	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:9	35.45	2504	1.62	13.59	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:9	35.45	2506	1.62	13.59	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	20.24	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:9	35.45	2510	1.62	13.59	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:9	35.45	2510	1.62	13.57	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	20.2	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:9	35.45	2512	1.63	13.57	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	20.1	1.37	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:27:9	35.45	2518	1.63	13.59	99	192	Off Idle	65	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.66	19.94	1.36	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:0	35.45	2520	1.63	13.58	99	191	Off Idle	65	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.67	19.73	1.34	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:0	35.45	2520	1.63	13.59	99	191	Off Idle	65.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.66	19.36	1.32	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:0	35.45	2518	1.63	13.58	99	191	Off Idle	65.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.65	19.06	1.3	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:0	35.45	2514	1.63	13.57	99	191	Off Idle	65.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.65	18.91	1.29	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:0	35.45	2509	1.63	13.57	99	191	Off Idle	65.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.64	18.41	1.25	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:0	35.45	2509	1.63	13.59	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.64	18.06	1.23	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:1	35.45	2509	1.63	13.57	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.65	17.71	1.21	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:1	35.45	2509	1.63	13.58	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.63	17.41	1.19	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:1	35.45	2504	1.64	13.59	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.6	17.16	1.17	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:1	35.45	2507	1.64	13.58	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.6	16.96	1.16	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:1	35.45	2514	1.64	13.58	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.57	16.72	1.14	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:1	35.45	2522	1.64	13.58	99	191	Off Idle	65.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.57	16.59	1.13	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:1	35.45	2522	1.64	13.59	99	191	Off Idle	65.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	16.53	1.13	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:2	35.45	2540	1.65	13.57	99	191	Off Idle	65	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.56	16.37	1.11	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:2	35.45	2534	1.65	13.57	99	191	Off Idle	65	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.56	16.27	1.11	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:2	35.45	2539	1.65	13.57	99	191	Off Idle	65	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.56	16.17	1.1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:2	35.45	2540	1.66	13.57	99	191	Off Idle	64.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.55	16.06	1.09	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:2	35.45	2548	1.66	13.57	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.52	15.97	1.09	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:2	35.45	2540	1.66	13.57	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.51	15.88	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:3	35.45	2540	1.66	13.6	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.48	15.78	1.07	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:3	35.45	2526	1.67	13.58	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.47	15.7	1.07	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:3	35.45	2494	1.67	13.59	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.46	15.65	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:28:3	35.45	2491	1.68	13.59	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.46	15.6	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:28:3	35.45	2488	1.68	13.59	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.45	15.58	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:3	35.45	2483	1.68	13.58	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.46	15.56	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:4	35.45	2483	1.69	13.59	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.41	15.54	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:4	35.45	2486	1.69	13.58	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.39	15.54	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:4	35.45	2492	1.69	13.57	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.39	15.53	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:4	35.45	2495	1.69	13.57	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.38	15.53	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:4	35.45	2496	1.69	13.58	99	192	Off Idle	65.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.39	15.51	1.06	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:4	35.45	2500	1.69	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.41	15.49	1.06	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:4	35.45	2507	1.69	13.59	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.42	15.46	1.05	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:28:5	35.45	2511	1.69	13.6	99	191	Off Idle	66.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.41	15.42	1.05	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:5	35.45	2511	1.68	13.59	99	191	Off Idle	66.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.46	15.37	1.05	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:5	35.45	2519	1.68	13.59	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.44	15.33	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:5	35.45	2508	1.68	13.57	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.44	15.29	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:5	35.45	2509	1.68	13.56	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.45	15.24	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:5	35.45	2512	1.68	13.56	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.44	15.19	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:6	35.45	2495	1.68	13.57	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.42	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:6	35.45	2518	1.68	13.56	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.45	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:28:6	35.45	2518	1.68	13.56	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.45	15.07	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:6	35.45	2505	1.68	13.58	99	191	Off Idle	65.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.45	15.06	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:6	35.45	2505	1.68	13.59	99	191	Off Idle	65.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.46	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:6	35.45	2509	1.68	13.6	99	191	Off Idle	65.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.46	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:6	35.45	2494	1.68	13.61	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.45	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:7	35.45	2494	1.68	13.59	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.42	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:7	35.45	2485	1.68	13.59	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.43	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:7	35.45	2499	1.68	13.59	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.43	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:7	35.45	2500	1.68	13.59	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.46	14.97	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:7	35.45	2499	1.68	13.58	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.46	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:7	35.45	2500	1.68	13.59	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	14.92	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:8	35.45	2502	1.68	13.61	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.46	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:8	35.45	2507	1.68	13.59	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.47	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:8	35.45	2509	1.68	13.58	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.45	14.9	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:8	35.45	2513	1.68	13.57	99	191	Off Idle	65.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	14.91	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:8	35.45	2516	1.68	13.57	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.46	14.93	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:8	35.45	2515	1.68	13.57	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.43	14.93	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:9	35.45	2514	1.68	13.56	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.41	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:9	35.45	2502	1.68	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.43	14.98	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:9	35.45	2493	1.68	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.39	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:9	35.45	2493	1.68	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.41	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:9	35.45	2489	1.68	13.6	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.38	15.17	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:9	35.45	2486	1.68	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.37	15.2	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:28:9	35.45	2486	1.68	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.35	15.22	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:0	35.45	2488	1.68	13.58	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.66	Lean	1	14.6	-9.36	15.22	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:0	35.45	2489	1.68	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.37	15.21	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:0	35.45	2495	1.68	13.58	99	192	Off Idle	66.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.4	15.2	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:0	35.45	2495	1.68	13.58	99	192	Off Idle	66.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.4	15.18	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:0	35.45	2497	1.68	13.57	99	192	Off Idle	66.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.41	15.16	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:29:0	35.45	2497	1.68	13.58	99	192	Off Idle	66.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.44	15.13	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:29:1	35.45	2497	1.68	13.56	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.45	15.12	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:29:1	35.45	2490	1.68	13.56	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.46	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:29:1	35.45	2485	1.68	13.56	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.46	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:29:1	35.45	2482	1.68	13.57	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.47	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:29:1	35.45	2482	1.68	13.55	99	192	Off Idle	67	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.46	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:29:1	35.45	2503	1.68	13.56	99	192	Off Idle	67	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.42	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:29:1	35.45	2482	1.68	13.56	99	192	Off Idle	67	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.41	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:2	35.45	2482	1.68	13.57	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.39	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:2	35.45	2480	1.68	13.57	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.39	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:2	35.45	2461	1.68	13.57	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.38	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:2	35.45	2471	1.68	13.57	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.37	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:2	35.45	2482	1.68	13.57	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.36	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:2	35.45	2488	1.68	13.58	99	192	Off Idle	67.1	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.37	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:3	35.45	2516	1.68	13.57	99	192	Off Idle	67.2	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.38	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:3	35.45	2508	1.68	13.58	99	192	Off Idle	67.2	0	2	132	944 Turbo	0.17	Rich	1	14.6	-9.37	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:3	35.45	2501	1.68	13.59	99	192	Off Idle	67.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.38	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:3	35.45	2501	1.68	13.58	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.38	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:3	35.45	2501	1.68	13.58	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.35	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:3	35.45	2507	1.68	13.58	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.35	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:4	35.45	2512	1.69	13.57	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.32	14.85	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:29:4	35.45	2512	1.69	13.57	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.32	14.86	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:4	35.45	2516	1.69	13.57	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.31	14.89	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:4	35.45	2512	1.69	13.57	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.33	14.93	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:4	35.45	2507	1.69	13.57	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.3	14.96	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:4	35.45	2504	1.69	13.58	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.29	14.99	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:4	35.45	2484	1.7	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.26	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:5	35.45	2480	1.7	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.25	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:5	35.45	2480	1.7	13.58	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.24	15.17	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:5	35.45	2477	1.7	13.58	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.23	15.18	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:5	35.45	2480	1.7	13.58	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.22	15.2	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:5	35.45	2505	1.71	13.57	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.2	15.21	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:5	35.45	2494	1.71	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.2	15.21	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:6	35.45	2488	1.71	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.19	15.19	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:6	35.45	2489	1.71	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.17	15.17	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:6	35.45	2480	1.71	13.57	99	191	Off Idle	66	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.17	15.15	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:6	35.45	2495	1.71	13.57	99	191	Off Idle	66.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.17	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:6	35.45	2498	1.71	13.57	99	191	Off Idle	66.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.17	15.1	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:6	35.45	2498	1.71	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.17	15.08	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:6	35.45	2508	1.71	13.57	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.2	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:7	35.45	2494	1.71	13.56	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.21	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:7	35.45	2490	1.71	13.58	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.22	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:7	35.45	2488	1.71	13.57	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.23	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:7	35.45	2470	1.71	13.56	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.22	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:7	35.45	2480	1.71	13.57	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.25	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:7	35.45	2495	1.71	13.57	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.23	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:8	35.45	2497	1.71	13.57	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.2	14.9	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:29:8	35.45	2498	1.71	13.59	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.19	14.88	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:8	35.45	2499	1.72	13.59	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.16	14.89	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:8	35.45	2496	1.72	13.59	99	191	Off Idle	66.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.11	14.91	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:8	35.45	2493	1.72	13.59	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.05	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:8	35.45	2488	1.73	13.59	99	191	Off Idle	66.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.04	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:9	35.45	2487	1.73	13.59	99	191	Off Idle	66.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:9	35.45	2485	1.73	13.59	99	191	Off Idle	66.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.94	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:9	35.45	2481	1.74	13.6	99	191	Off Idle	66.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.91	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:9	35.45	2489	1.74	13.59	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.9	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:9	35.45	2489	1.75	13.6	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.88	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:29:9	35.45	2489	1.75	13.59	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.88	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:29:9	35.45	2490	1.76	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.84	15.05	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:0	35.45	2487	1.76	13.59	99	192	Off Idle	66.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.83	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:0	35.45	2487	1.77	13.57	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.83	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:0	35.45	2486	1.77	13.59	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.79	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:0	35.45	2482	1.78	13.57	99	192	Off Idle	67.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.78	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:0	35.45	2482	1.78	13.57	99	192	Off Idle	67.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.79	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:0	35.45	2478	1.79	13.56	99	192	Off Idle	67.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.76	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:1	35.45	2479	1.79	13.56	99	192	Off Idle	67.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.71	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:1	35.45	2481	1.79	13.57	99	192	Off Idle	67.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.69	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:1	35.45	2481	1.79	13.57	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.69	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:1	35.45	2482	1.8	13.58	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.66	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:1	35.45	2482	1.8	13.57	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.63	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:1	35.45	2490	1.8	13.58	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.61	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:1	35.45	2466	1.81	13.58	99	192	Off Idle	67.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.59	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:2	35.45	2483	1.81	13.57	99	192	Off Idle	67.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.57	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:2	35.45	2482	1.81	13.57	99	192	Off Idle	67.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.52	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:2	35.45	2480	1.82	13.56	99	192	Off Idle	67.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.52	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:30:2	35.45	2480	1.82	13.57	99	192	Off Idle	67.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.44	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:2	35.45	2483	1.83	13.58	99	192	Off Idle	67.1	0	2	132	944 Turbo	0.66	Lean	1	14.6	-8.39	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:30:2	35.45	2492	1.83	13.59	99	192	Off Idle	67.1	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.33	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:3	35.45	2493	1.84	13.59	99	192	Off Idle	67.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.32	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:30:3	35.45	2496	1.85	13.59	99	191	Off Idle	66.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.26	14.99	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:3	35.45	2497	1.85	13.58	99	191	Off Idle	66.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.22	14.97	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:3	35.45	2498	1.86	13.58	99	191	Off Idle	66.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.18	14.96	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:3	35.45	2499	1.87	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.14	14.96	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:3	35.45	2500	1.88	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.12	14.94	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:4	35.45	2504	1.88	13.59	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.09	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:4	35.45	2492	1.89	13.59	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.02	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:4	35.45	2492	1.9	13.59	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.98	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:4	35.45	2476	1.9	13.57	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.93	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:4	35.45	2488	1.91	13.58	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.88	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:4	35.45	2485	1.92	13.56	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.89	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:4	35.45	2485	1.93	13.56	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.85	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:5	34.08	2465	1.93	13.56	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.83	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:5	34.08	2480	1.93	13.56	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.8	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:5	34.08	2480	1.94	13.55	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.79	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:5	34.08	2482	1.95	13.55	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.78	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:5	34.08	2487	1.95	13.54	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.77	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:5	34.08	2486	1.95	13.55	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.74	15.14	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:6	34.08	2484	1.96	13.55	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.69	15.16	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:6	34.08	2484	1.96	13.57	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	15.16	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:6	34.08	2481	1.96	13.59	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.72	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:6	34.08	2504	1.96	13.59	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	15.14	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:6	34.08	2497	1.96	13.58	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:6	34.08	2492	1.96	13.56	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:6	34.08	2496	1.96	13.58	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:7	34.08	2486	1.96	13.56	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:7	34.08	2486	1.96	13.56	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.73	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:30:7	34.08	2492	1.96	13.57	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.71	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:7	34.08	2492	1.96	13.58	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.69	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:7	34.08	2488	1.97	13.58	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.66	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:7	34.08	2484	1.97	13.6	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.64	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:8	34.08	2485	1.97	13.59	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.64	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:8	34.08	2490	1.97	13.59	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.61	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:8	34.08	2490	1.97	13.58	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.18	Rich	1	14.6	-7.66	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:8	34.08	2496	1.97	13.59	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	14.81	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:8	34.08	2496	1.97	13.59	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.8	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:8	34.08	2496	1.97	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.8	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:9	34.08	2496	1.97	13.6	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.82	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:9	34.08	2495	1.97	13.61	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.84	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:9	34.08	2495	1.97	13.61	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.63	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:9	34.08	2491	1.97	13.61	99	191	Off Idle	65.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:30:9	34.08	2486	1.97	13.61	99	191	Off Idle	65.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.64	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:9	34.08	2503	1.97	13.59	99	191	Off Idle	65.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.62	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:30:9	34.08	2503	1.97	13.59	99	191	Off Idle	65.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.65	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:31:0	34.08	2484	1.98	13.59	99	191	Off Idle	66	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.65	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:31:0	34.08	2485	1.98	13.59	99	191	Off Idle	66.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.64	15.16	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:31:0	34.08	2471	1.98	13.57	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.62	15.18	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:31:0	34.08	2480	1.98	13.59	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.62	15.18	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:31:0	34.08	2488	1.98	13.58	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.6	15.16	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:31:0	34.08	2485	1.98	13.57	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.58	15.15	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:31:1	34.08	2485	1.98	13.57	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.57	15.14	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:31:1	34.08	2482	1.98	13.57	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.57	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:1	34.08	2482	1.98	13.58	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.58	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:1	34.08	2480	1.98	13.58	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.58	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:31:1	34.08	2473	1.98	13.58	99	191	Off Idle	66.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.57	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:1	34.08	2489	1.98	13.57	99	192	Off Idle	66.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.59	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:1	34.08	2490	1.98	13.58	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.58	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:2	34.08	2491	1.98	13.58	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.58	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:31:2	34.08	2495	1.98	13.59	99	192	Off Idle	67.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.6	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:2	34.08	2494	1.98	13.58	99	192	Off Idle	67.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	14.9	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:2	34.08	2496	1.98	13.6	99	192	Off Idle	66.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:2	34.08	2500	1.98	13.59	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:2	34.08	2500	1.98	13.61	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.9	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:3	34.08	2498	1.98	13.59	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.56	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:3	34.08	2495	1.98	13.6	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.53	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:3	34.08	2488	1.99	13.59	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.52	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:3	34.08	2489	1.99	13.59	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.48	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:3	34.08	2494	1.99	13.58	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.47	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:3	34.08	2494	1.99	13.59	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.43	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:4	34.08	2495	2	13.57	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.39	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:4	34.08	2496	2	13.56	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.37	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:4	34.08	2493	2	13.57	99	192	Off Idle	66.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.37	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:4	34.08	2493	2.01	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.34	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:4	34.08	2495	2.01	13.57	99	192	Off Idle	66	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.3	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:4	34.08	2492	2.01	13.58	99	192	Off Idle	66.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.32	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:4	34.08	2492	2.01	13.58	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.29	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:5	34.08	2492	2.02	13.58	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.32	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:5	34.08	2492	2.02	13.59	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.31	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:5	34.08	2489	2.02	13.57	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.31	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:5	34.08	2492	2.02	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.31	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:5	34.08	2492	2.02	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.32	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:5	34.08	2491	2.03	13.56	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.29	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:6	34.08	2492	2.03	13.57	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.26	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:6	34.08	2488	2.03	13.57	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.26	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:6	34.08	2488	2.03	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.25	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:6	34.08	2483	2.03	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.27	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:6	34.08	2484	2.03	13.58	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.26	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:6	34.08	2490	2.03	13.6	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.24	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:6	34.08	2492	2.03	13.59	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.23	14.83	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:7	34.08	2502	2.03	13.58	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.23	14.83	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:7	34.08	2506	2.03	13.6	99	192	Off Idle	66.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.24	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:7	34.08	2506	2.03	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.25	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:7	34.08	2506	2.03	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.26	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:7	34.08	2506	2.03	13.6	99	192	Off Idle	66	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.24	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:7	34.08	2504	2.03	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.23	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:8	34.08	2502	2.03	13.6	99	192	Off Idle	66	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.24	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:8	34.08	2490	2.03	13.58	99	191	Off Idle	66	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.24	14.96	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:8	34.08	2489	2.03	13.58	99	191	Off Idle	66.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.25	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:8	34.08	2489	2.03	13.57	99	191	Off Idle	66.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.23	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:8	34.08	2489	2.03	13.56	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.24	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:8	34.08	2492	2.03	13.57	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.26	15	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:9	34.08	2495	2.03	13.57	99	192	Off Idle	66.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.3	15	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:9	34.08	2492	2.03	13.57	99	192	Off Idle	66.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.32	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:9	34.08	2494	2.03	13.59	99	192	Off Idle	66.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.32	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:9	34.08	2495	2.03	13.59	99	192	Off Idle	66.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.32	14.97	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:9	34.08	2494	2.03	13.59	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.3	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:31:9	34.08	2492	2.03	13.59	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.25	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:31:9	34.08	2485	2.03	13.59	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.23	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:0	34.08	2487	2.03	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.24	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:0	34.08	2487	2.03	13.6	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.23	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:0	34.08	2495	2.04	13.58	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.25	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:0	34.08	2505	2.04	13.59	99	192	Off Idle	66.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.27	14.78	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:0	34.08	2505	2.03	13.59	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.27	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:0	34.08	2512	2.03	13.58	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.28	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:1	34.08	2512	2.03	13.57	99	192	Off Idle	66.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.25	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:1	34.08	2508	2.03	13.57	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.2	14.84	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:32:1	34.08	2502	2.03	13.58	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.2	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:1	34.08	2499	2.03	13.57	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.23	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:1	34.08	2499	2.03	13.58	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.21	14.92	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:1	34.08	2497	2.04	13.57	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.22	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:1	34.08	2488	2.04	13.57	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.22	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:2	34.08	2488	2.04	13.58	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.24	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:2	34.08	2489	2.04	13.59	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.21	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:2	34.08	2490	2.04	13.57	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.23	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:2	34.08	2497	2.04	13.58	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.22	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:2	34.08	2498	2.04	13.58	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.24	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:2	34.08	2490	2.04	13.58	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.21	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:3	34.08	2503	2.04	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.19	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:3	34.08	2502	2.04	13.57	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.16	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:3	34.08	2502	2.04	13.57	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.16	14.97	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:3	34.08	2520	2.04	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.15	14.96	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:3	34.08	2496	2.04	13.59	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.13	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:3	34.08	2496	2.05	13.58	99	192	Off Idle	66.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.15	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:4	34.08	2492	2.05	13.57	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.13	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:4	34.08	2491	2.05	13.56	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.14	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:4	34.08	2481	2.05	13.58	99	191	Off Idle	66.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.11	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:4	34.08	2496	2.05	13.57	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.13	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:4	34.08	2501	2.05	13.59	99	192	Off Idle	66.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.1	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:4	34.08	2502	2.05	13.58	99	192	Off Idle	66.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.08	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:4	34.08	2516	2.05	13.6	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.06	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:5	34.08	2507	2.05	13.6	99	192	Off Idle	66	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.06	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:5	34.08	2504	2.05	13.6	99	192	Off Idle	66	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.06	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:5	34.08	2504	2.05	13.58	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.06	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:32:5	34.08	2508	2.06	13.57	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.06	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:32:5	34.08	2489	2.06	13.57	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.05	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:32:5	34.08	2496	2.06	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.04	14.86	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:32:6	34.08	2502	2.06	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.07	14.87	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:32:6	34.08	2498	2.06	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.05	14.89	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:32:6	34.08	2501	2.06	13.61	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.02	14.91	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:6	34.08	2500	2.06	13.6	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.04	14.94	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:6	34.08	2498	2.06	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.03	14.95	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:6	34.08	2499	2.06	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.03	14.97	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:6	34.08	2499	2.06	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.01	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:7	34.08	2501	2.06	13.58	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:7	34.08	2502	2.07	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7	15.05	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:7	34.08	2502	2.07	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.02	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:7	34.08	2494	2.07	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.99	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:7	34.08	2500	2.07	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.04	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:7	34.08	2500	2.07	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.02	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:8	34.08	2502	2.07	13.58	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.04	15.04	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:8	34.08	2503	2.07	13.59	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.05	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:8	34.08	2504	2.07	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.06	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:8	34.08	2506	2.07	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.05	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:8	34.08	2508	2.07	13.59	99	191	Off Idle	65.8	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.06	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:32:8	34.08	2509	2.07	13.59	99	191	Off Idle	65.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.05	14.84	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:9	34.08	2507	2.07	13.58	99	191	Off Idle	65.8	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.05	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:9	34.08	2502	2.07	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.04	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:9	34.08	2501	2.06	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.06	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:9	34.08	2501	2.06	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.02	14.79	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:32:9	34.08	2504	2.06	13.57	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.01	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:9	34.08	2507	2.06	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.01	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:32:9	34.08	2506	2.06	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.01	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:0	34.08	2508	2.06	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.02	14.79	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:33:0	34.08	2511	2.06	13.57	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.06	14.81	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:33:0	34.08	2509	2.06	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.05	14.82	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:33:0	34.08	2509	2.06	13.6	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.05	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:0	34.08	2507	2.06	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.06	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:0	34.08	2506	2.06	13.61	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.06	14.82	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:1	34.08	2506	2.06	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.05	14.84	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:1	34.08	2513	2.06	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.06	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:1	34.08	2501	2.06	13.6	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.03	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:1	34.08	2504	2.06	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.07	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:1	34.08	2504	2.06	13.57	99	192	Off Idle	66	0	2	132	944 Turbo	0.71	Lean	1	14.6	-7.06	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:1	34.08	2484	2.06	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.07	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:1	34.08	2504	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.06	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:2	34.08	2504	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.1	14.99	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:2	34.08	2506	2.06	13.59	99	191	Off Idle	66	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.07	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:2	34.08	2507	2.06	13.57	99	191	Off Idle	66	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.08	14.94	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:2	34.08	2508	2.06	13.57	99	191	Off Idle	66	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.04	14.92	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:2	34.08	2507	2.06	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.05	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:2	34.08	2510	2.06	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.06	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:3	34.08	2510	2.06	13.57	99	192	Off Idle	66	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.08	14.81	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:3	34.08	2504	2.06	13.57	99	192	Off Idle	66	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.07	14.75	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:3	34.08	2499	2.06	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.08	14.73	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:3	34.08	2503	2.06	13.57	99	192	Off Idle	66	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.07	14.74	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:3	34.08	2504	2.06	13.58	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.06	14.73	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:3	34.08	2508	2.06	13.6	99	192	Off Idle	66.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.05	14.75	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:4	34.08	2516	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.06	14.76	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:4	34.08	2516	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.08	14.77	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:4	34.08	2520	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.1	14.78	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:4	34.08	2516	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.11	14.78	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:4	34.08	2514	2.06	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.14	14.78	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:4	34.08	2511	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.13	14.78	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:4	34.08	2507	2.06	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.13	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:5	34.08	2507	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.09	14.82	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:33:5	34.08	2506	2.06	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.06	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:5	34.08	2507	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.06	14.87	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:5	34.08	2508	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.08	14.88	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:5	34.08	2508	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.08	14.92	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:5	34.08	2512	2.06	13.58	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.1	14.94	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:6	34.08	2512	2.06	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.1	14.97	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:6	34.08	2510	2.06	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.08	14.99	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:6	34.08	2509	2.06	13.6	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.08	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:6	34.08	2503	2.06	13.58	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.1	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:6	34.08	2503	2.06	13.58	99	191	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.08	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:6	34.08	2503	2.07	13.58	99	192	Off Idle	65.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.06	15.04	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:6	34.08	2504	2.07	13.57	99	192	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.09	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:7	34.08	2504	2.07	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.06	15	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:7	34.08	2507	2.07	13.57	99	192	Off Idle	66	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.07	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:7	34.08	2510	2.07	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.05	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:7	34.08	2510	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.05	14.91	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:7	34.08	2509	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.06	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:7	34.08	2510	2.06	13.6	99	192	Off Idle	66	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.07	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:8	34.08	2515	2.06	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.06	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:8	34.08	2516	2.07	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.06	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:8	34.08	2520	2.07	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.09	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:8	34.08	2519	2.07	13.58	99	192	Off Idle	66	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.05	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:8	34.08	2519	2.07	13.57	99	192	Off Idle	66	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.03	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:8	34.08	2514	2.07	13.59	99	192	Off Idle	66	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.03	14.77	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:33:9	34.08	2506	2.07	13.59	99	192	Off Idle	65.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.03	14.77	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:33:9	34.08	2510	2.07	13.59	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.03	14.78	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:9	34.08	2510	2.07	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.06	14.82	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:33:9	34.08	2508	2.07	13.59	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.06	14.84	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:9	34.08	2513	2.07	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.08	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:33:9	34.08	2514	2.07	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.06	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:33:9	34.08	2516	2.07	13.59	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.05	14.87	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:0	34.08	2518	2.07	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.02	14.9	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:0	34.08	2515	2.07	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.04	14.97	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:0	34.08	2515	2.07	13.59	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.04	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:0	34.08	2513	2.07	13.59	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.05	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:0	34.08	2513	2.07	13.58	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.03	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:0	34.08	2512	2.07	13.59	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.04	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:1	34.08	2508	2.07	13.61	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.05	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:1	34.08	2508	2.07	13.58	99	192	Off Idle	65.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.03	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:1	34.08	2508	2.07	13.58	99	192	Off Idle	65.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.05	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:1	34.08	2512	2.07	13.58	99	192	Off Idle	65.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.03	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:1	34.08	2504	2.07	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.06	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:1	34.08	2516	2.07	13.57	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.05	14.77	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:1	34.08	2520	2.07	13.58	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.06	14.76	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:2	34.08	2520	2.07	13.59	99	192	Off Idle	65.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.06	14.75	1	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:2	34.08	2522	2.07	13.58	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.03	14.75	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:2	34.08	2522	2.07	13.58	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.02	14.77	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:2	34.08	2518	2.07	13.58	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.15	Rich	1	14.6	-7.04	14.82	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:2	34.08	2516	2.07	13.56	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.01	14.84	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:2	34.08	2510	2.07	13.56	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.02	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:3	34.08	2510	2.07	13.56	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7	14.92	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:3	34.08	2506	2.07	13.58	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.99	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:3	34.08	2510	2.07	13.58	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.03	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:3	34.08	2512	2.07	13.58	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.03	15.01	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:3	34.08	2513	2.08	13.58	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.01	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:3	34.08	2515	2.08	13.58	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.02	15.12	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:4	34.08	2520	2.08	13.57	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.03	15.14	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:4	34.08	2523	2.08	13.57	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.05	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:4	34.08	2523	2.08	13.57	99	192	Off Idle	65.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.01	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:4	34.08	2520	2.08	13.57	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.06	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:4	34.08	2514	2.08	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.06	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:4	34.08	2512	2.08	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.04	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:4	34.08	2509	2.08	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.06	14.87	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:5	34.08	2508	2.07	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.05	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:5	34.08	2514	2.07	13.6	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.06	14.77	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:5	34.08	2514	2.07	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.07	14.72	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:5	34.08	2520	2.07	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.06	14.68	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:5	34.08	2524	2.07	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.05	14.68	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:5	34.08	2548	2.07	13.58	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.06	14.78	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:6	34.08	2538	2.07	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.05	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:6	34.08	2528	2.07	13.59	99	192	Off Idle	65.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.05	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:6	34.08	2522	2.07	13.58	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.07	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:6	34.08	2499	2.07	13.57	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.05	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:6	34.08	2507	2.07	13.57	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.06	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:6	34.08	2512	2.07	13.57	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.01	14.9	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:6	34.08	2510	2.07	13.58	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.01	14.96	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:7	34.08	2510	2.07	13.58	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.01	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:7	34.08	2513	2.07	13.59	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.01	15	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:7	34.08	2518	2.07	13.59	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.99	15.05	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:7	34.08	2528	2.07	13.6	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.01	15.06	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:7	34.08	2528	2.07	13.58	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.02	15.1	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:34:7	34.08	2526	2.07	13.58	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.98	15.12	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:8	34.08	2532	2.08	13.57	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.97	15.12	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:34:8	34.08	2532	2.08	13.58	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7	15.1	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:8	34.08	2530	2.08	13.59	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:34:8	34.08	2526	2.08	13.59	99	192	Off Idle	64.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7	15.05	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:8	34.08	2520	2.08	13.58	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7	15.02	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:8	34.08	2520	2.08	13.58	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.99	15	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:9	34.08	2519	2.08	13.59	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.98	14.97	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:9	34.08	2519	2.08	13.59	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.02	14.95	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:9	34.08	2519	2.08	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.99	14.92	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:9	34.08	2516	2.08	13.58	98	192	Off Idle	64.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.01	14.9	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:9	34.08	2517	2.08	13.58	98	192	Off Idle	64.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.04	14.9	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:9	34.08	2517	2.08	13.6	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.03	14.9	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:34:9	34.08	2516	2.08	13.6	99	192	Off Idle	65	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.01	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:0	34.08	2526	2.08	13.58	99	192	Off Idle	65	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.03	14.94	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:0	34.08	2518	2.08	13.58	99	192	Off Idle	65	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.03	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:0	34.08	2519	2.08	13.59	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.01	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:0	34.08	2522	2.08	13.58	99	191	Off Idle	65.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.02	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:0	34.08	2504	2.08	13.58	99	191	Off Idle	65.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.06	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:0	34.08	2504	2.08	13.6	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.05	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:1	34.08	2525	2.08	13.6	99	192	Off Idle	65	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.05	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:1	34.08	2527	2.08	13.59	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.03	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:1	34.08	2528	2.08	13.59	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.98	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:1	34.08	2528	2.08	13.59	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.02	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:1	34.08	2525	2.08	13.59	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7	15.07	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:1	34.08	2525	2.08	13.57	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.03	15.04	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:1	34.08	2524	2.08	13.58	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.02	15	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:2	34.08	2530	2.08	13.58	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.02	14.95	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:2	34.08	2524	2.08	13.59	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.03	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:2	34.08	2524	2.08	13.58	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.01	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:2	34.08	2528	2.08	13.58	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.02	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:2	34.08	2530	2.08	13.59	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.01	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:2	34.08	2522	2.08	13.59	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:3	34.08	2534	2.08	13.58	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.01	14.8	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:3	34.08	2534	2.08	13.59	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.01	14.79	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:3	34.08	2533	2.08	13.59	99	192	Off Idle	65	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.02	14.83	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:3	34.08	2542	2.08	13.57	99	192	Off Idle	65	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.01	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:3	34.08	2528	2.08	13.57	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.03	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:3	34.08	2524	2.08	13.56	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.06	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:4	34.08	2524	2.08	13.56	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.03	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:4	34.08	2523	2.08	13.57	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.03	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:4	34.08	2514	2.08	13.58	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.03	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:4	34.08	2521	2.08	13.57	99	192	Off Idle	65	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.99	15.05	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:4	34.08	2522	2.08	13.58	99	192	Off Idle	65	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.96	15.09	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:4	34.08	2526	2.08	13.58	99	192	Off Idle	65	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.97	15.07	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:4	34.08	2550	2.08	13.59	99	192	Off Idle	65	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.97	15.06	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:5	34.08	2542	2.08	13.58	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7	15.04	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:5	34.08	2528	2.08	13.59	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.01	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:5	34.08	2524	2.08	13.59	99	192	Off Idle	65	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.01	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:5	34.08	2520	2.08	13.6	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.04	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:5	34.08	2520	2.08	13.58	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.04	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:5	34.08	2520	2.08	13.58	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.02	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:6	34.08	2521	2.08	13.58	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.02	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:6	34.08	2519	2.08	13.59	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.01	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:6	34.08	2521	2.08	13.6	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.99	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:6	34.08	2526	2.08	13.6	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.01	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:6	34.08	2530	2.08	13.6	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:6	34.08	2532	2.08	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:6	34.08	2537	2.08	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:7	34.08	2530	2.08	13.57	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.02	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:7	34.08	2536	2.08	13.56	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.02	14.87	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:7	34.08	2535	2.08	13.58	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.04	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:35:7	34.08	2538	2.08	13.57	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.05	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:7	34.08	2525	2.08	13.59	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.04	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:7	34.08	2519	2.08	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.06	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:35:8	34.08	2519	2.08	13.58	99	192	Off Idle	65	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.03	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:8	34.08	2518	2.08	13.58	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.01	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:8	34.08	2500	2.08	13.59	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.99	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:8	34.08	2523	2.08	13.57	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.01	14.99	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:8	34.08	2526	2.08	13.59	99	192	Off Idle	65	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.03	14.97	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:8	34.08	2534	2.08	13.59	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.05	14.95	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:9	34.08	2540	2.08	13.58	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.06	14.91	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:9	34.08	2540	2.08	13.58	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.06	14.87	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:9	34.08	2543	2.08	13.58	99	192	Off Idle	64.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.05	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:35:9	34.08	2542	2.08	13.59	99	192	Off Idle	64.2	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.06	14.77	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:9	34.08	2540	2.08	13.6	99	192	Off Idle	64.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.06	14.78	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:9	34.08	2554	2.08	13.6	99	192	Off Idle	64.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.06	14.76	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:35:9	34.08	2529	2.08	13.58	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.06	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:0	34.08	2529	2.08	13.58	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.04	14.76	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:0	34.08	2527	2.08	13.58	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.98	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:0	34.08	2509	2.09	13.58	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.98	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:0	34.08	2529	2.09	13.59	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.96	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:0	34.08	2532	2.09	13.6	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.96	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:0	34.08	2534	2.09	13.59	99	192	Off Idle	64.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.97	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:1	34.08	2531	2.09	13.6	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.97	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:1	34.08	2523	2.09	13.6	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.96	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:1	34.08	2528	2.09	13.6	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.97	15.07	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:1	34.08	2528	2.09	13.61	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.96	15.11	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:1	34.08	2528	2.09	13.61	99	192	Off Idle	65	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.96	15.13	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:1	34.08	2528	2.09	13.6	99	192	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.94	15.14	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:1	34.08	2528	2.09	13.58	99	192	Off Idle	65.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.94	15.08	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:2	34.08	2528	2.09	13.57	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.96	15.06	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:2	34.08	2530	2.09	13.57	99	192	Off Idle	65.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.97	15.02	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:2	34.08	2544	2.09	13.58	99	192	Off Idle	65	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.95	14.97	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:2	34.08	2536	2.09	13.58	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.95	14.94	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:2	34.08	2536	2.09	13.59	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.93	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:36:2	34.08	2538	2.09	13.61	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.9	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:3	34.08	2533	2.09	13.59	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.93	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:3	34.08	2533	2.09	13.58	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.91	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:3	34.08	2530	2.09	13.58	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.91	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:3	34.08	2529	2.09	13.58	99	192	Off Idle	64.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.88	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:3	34.08	2530	2.09	13.59	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.89	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:3	34.08	2530	2.1	13.6	99	192	Off Idle	64.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.9	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:4	34.08	2535	2.1	13.58	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.91	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:4	34.08	2534	2.1	13.59	99	192	Off Idle	63.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.91	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:4	34.08	2535	2.1	13.59	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.91	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:4	34.08	2537	2.1	13.58	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.19	Rich	1	14.6	-6.91	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:4	34.08	2539	2.1	13.6	98	192	Off Idle	63.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.92	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:4	34.08	2535	2.1	13.59	98	192	Off Idle	63.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.91	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:4	34.08	2535	2.1	13.58	98	192	Off Idle	63.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.89	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:5	34.08	2537	2.1	13.58	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.9	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:5	34.08	2539	2.1	13.59	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.88	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:5	34.08	2541	2.1	13.58	99	192	Off Idle	63.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.87	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:5	34.08	2540	2.1	13.58	99	192	Off Idle	63.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.88	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:5	34.08	2538	2.1	13.58	99	192	Off Idle	63.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.88	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:5	34.08	2535	2.1	13.59	99	192	Off Idle	63.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.86	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:6	34.08	2536	2.1	13.58	99	192	Off Idle	63.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.88	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:6	34.08	2532	2.1	13.58	99	192	Off Idle	63.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.9	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:6	34.08	2531	2.1	13.6	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.92	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:6	34.08	2531	2.1	13.59	99	192	Off Idle	64	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.89	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:36:6	34.08	2527	2.1	13.58	99	192	Off Idle	64.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.89	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:6	34.08	2516	2.1	13.58	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.9	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:6	34.08	2540	2.1	13.59	99	192	Off Idle	64.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.9	14.94	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:7	34.08	2540	2.1	13.58	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.94	14.92	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:7	34.08	2545	2.1	13.57	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.93	14.87	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:7	34.08	2544	2.1	13.57	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.92	14.83	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:7	34.08	2544	2.1	13.57	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.93	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:7	34.08	2546	2.1	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.94	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:7	34.08	2542	2.1	13.58	99	192	Off Idle	64.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.92	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:8	34.08	2541	2.1	13.58	99	192	Off Idle	64.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.89	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:8	34.08	2539	2.1	13.58	99	192	Off Idle	64.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.92	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:8	34.08	2536	2.1	13.58	99	192	Off Idle	64.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.89	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:8	34.08	2532	2.1	13.58	99	192	Off Idle	64.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.93	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:8	34.08	2532	2.1	13.59	99	192	Off Idle	64	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.91	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:36:8	34.08	2533	2.1	13.58	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.9	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:9	34.08	2537	2.1	13.59	99	192	Off Idle	63.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.88	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:9	34.08	2539	2.1	13.59	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.87	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:9	34.08	2540	2.1	13.6	99	192	Off Idle	63.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.91	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:9	34.08	2540	2.1	13.58	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.92	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:9	34.08	2540	2.1	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.91	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:9	34.08	2540	2.1	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.91	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:36:9	34.08	2538	2.1	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.93	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:0	34.08	2540	2.1	13.59	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.88	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:0	34.08	2537	2.1	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.88	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:0	34.08	2537	2.1	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.86	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:0	34.08	2540	2.11	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.87	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:0	34.08	2539	2.11	13.59	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.85	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:0	34.08	2539	2.11	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.85	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:1	34.08	2544	2.11	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.89	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:1	34.08	2543	2.11	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.88	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:1	34.08	2544	2.11	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.88	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:1	34.08	2543	2.11	13.6	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.87	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:1	34.08	2540	2.11	13.6	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.89	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:1	34.08	2542	2.11	13.59	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.86	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:1	34.08	2542	2.11	13.58	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.87	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:2	34.08	2548	2.11	13.59	99	192	Off Idle	63.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.86	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:2	34.08	2552	2.11	13.58	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.87	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:2	34.08	2552	2.11	13.59	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.88	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:2	34.08	2554	2.11	13.57	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.9	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:2	34.08	2549	2.11	13.58	99	191	Off Idle	63.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.89	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:2	34.08	2540	2.11	13.58	99	191	Off Idle	63.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.91	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:3	34.08	2540	2.11	13.58	99	191	Off Idle	63.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.96	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:3	34.08	2528	2.11	13.57	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.92	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:3	34.08	2529	2.11	13.58	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.91	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:3	34.08	2530	2.11	13.58	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.93	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:3	34.08	2536	2.11	13.57	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.9	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:3	34.08	2539	2.11	13.58	99	192	Off Idle	63.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.91	15.01	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:4	34.08	2539	2.11	13.57	98	192	Off Idle	63.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.91	15.05	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:4	34.08	2547	2.11	13.57	98	192	Off Idle	63.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.91	15.08	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:4	34.08	2551	2.11	13.58	98	192	Off Idle	63.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.89	15.08	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:4	34.08	2551	2.11	13.58	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.93	15.07	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:4	34.08	2554	2.11	13.59	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.92	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:4	34.08	2550	2.11	13.59	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.89	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:4	34.08	2550	2.11	13.59	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.92	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:5	34.08	2555	2.11	13.6	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.92	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:37:5	34.08	2539	2.11	13.59	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.93	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:37:5	34.08	2535	2.11	13.58	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.89	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:37:5	34.08	2534	2.11	13.57	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.9	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:37:5	34.08	2526	2.11	13.58	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.88	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:5	34.08	2539	2.11	13.57	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.87	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:6	34.08	2539	2.11	13.58	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.87	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:6	34.08	2545	2.11	13.58	99	192	Off Idle	63.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.89	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:6	34.08	2571	2.11	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.88	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:6	34.08	2555	2.11	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.89	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:6	34.08	2555	2.11	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.89	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:6	34.08	2551	2.11	13.59	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.92	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:6	34.08	2541	2.11	13.59	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.92	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:7	34.08	2541	2.11	13.6	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.92	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:7	34.08	2547	2.11	13.59	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.92	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:7	34.08	2551	2.11	13.59	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.91	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:7	34.08	2552	2.11	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.9	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:7	34.08	2573	2.11	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.87	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:7	34.08	2553	2.11	13.57	99	192	Off Idle	63	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.88	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:8	34.08	2552	2.11	13.57	99	192	Off Idle	63	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.93	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:8	34.08	2548	2.11	13.57	99	192	Off Idle	63	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.91	15.12	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:8	34.08	2542	2.11	13.57	99	192	Off Idle	63	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.89	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:8	34.08	2539	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.9	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:8	34.08	2536	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.88	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:8	34.08	2535	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.84	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:9	34.08	2544	2.11	13.56	99	192	Off Idle	63	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.87	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:9	34.08	2544	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.91	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:37:9	34.08	2549	2.11	13.57	99	192	Off Idle	63	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.94	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:9	34.08	2548	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.92	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:9	34.08	2545	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.91	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:9	34.08	2544	2.11	13.6	99	192	Off Idle	63	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.93	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:37:9	34.08	2547	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.9	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:0	34.08	2555	2.11	13.57	99	192	Off Idle	63	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.88	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:0	34.08	2556	2.11	13.56	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.88	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:0	34.08	2558	2.11	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.86	14.84	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:0	34.08	2569	2.11	13.57	99	192	Off Idle	63.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.87	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:0	34.08	2555	2.11	13.57	99	192	Off Idle	63	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.88	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:0	34.08	2552	2.11	13.57	99	192	Off Idle	63	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.86	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:1	34.08	2548	2.11	13.6	99	192	Off Idle	63	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.86	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:1	34.08	2528	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.88	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:1	34.08	2538	2.11	13.59	98	192	Off Idle	63	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.89	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:1	34.08	2546	2.11	13.6	98	192	Off Idle	63	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.89	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:1	34.08	2547	2.11	13.59	98	192	Off Idle	63	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.92	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:1	34.08	2547	2.11	13.61	99	192	Off Idle	63	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.92	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:1	34.08	2551	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.94	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:2	34.08	2557	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.92	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:2	34.08	2556	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.9	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:2	34.08	2553	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.93	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:2	34.08	2555	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.93	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:2	34.08	2574	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.95	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:2	34.08	2554	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.96	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:3	34.08	2555	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.97	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:3	34.08	2553	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.93	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:3	34.08	2550	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.95	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:3	34.08	2552	2.11	13.56	99	192	Off Idle	62.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.94	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:3	34.08	2550	2.11	13.57	99	192	Off Idle	62.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.92	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:3	34.08	2552	2.11	13.59	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.89	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:4	34.08	2555	2.11	13.58	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.91	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:4	34.08	2562	2.11	13.59	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.87	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:4	34.08	2562	2.11	13.59	99	192	Off Idle	62.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.87	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:4	34.08	2560	2.11	13.58	99	192	Off Idle	62.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.9	14.83	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:4	34.08	2558	2.11	13.57	99	192	Off Idle	62.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.94	14.84	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:38:4	34.08	2555	2.11	13.57	99	192	Off Idle	62.8	0	2	132	944 Turbo	0.16	Rich	1	14.6	-6.93	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:4	34.08	2554	2.11	13.57	99	192	Off Idle	62.8	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.94	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:5	34.08	2552	2.11	13.59	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.94	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:5	34.08	2549	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.92	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:5	34.08	2548	2.11	13.58	99	192	Off Idle	63	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.89	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:5	34.08	2547	2.11	13.57	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.9	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:5	34.08	2550	2.11	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.89	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:5	34.08	2550	2.11	13.58	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.92	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:6	34.08	2556	2.11	13.57	99	192	Off Idle	63.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.91	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:6	34.08	2557	2.11	13.59	98	192	Off Idle	63.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.9	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:6	34.08	2557	2.11	13.59	98	192	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.89	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:6	34.08	2554	2.11	13.59	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.93	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:6	34.08	2554	2.11	13.6	98	192	Off Idle	63	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.92	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:6	34.08	2555	2.11	13.58	98	192	Off Idle	63	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.94	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:6	34.08	2556	2.11	13.58	98	192	Off Idle	63	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.93	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:7	34.08	2556	2.11	13.57	98	192	Off Idle	63	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.95	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:7	34.08	2555	2.11	13.58	98	192	Off Idle	63.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.98	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:7	34.08	2561	2.11	13.57	98	192	Off Idle	63.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.95	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:7	34.08	2558	2.11	13.58	99	192	Off Idle	63.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.95	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:7	34.08	2564	2.11	13.58	99	192	Off Idle	63.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:7	34.08	2562	2.11	13.59	99	192	Off Idle	63	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:8	34.08	2561	2.11	13.58	98	192	Off Idle	63	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.97	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:8	34.08	2560	2.11	13.59	98	192	Off Idle	63	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.97	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:8	34.08	2549	2.11	13.59	98	192	Off Idle	63	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.01	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:8	34.08	2558	2.11	13.59	98	192	Off Idle	63	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.98	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:38:8	34.08	2555	2.11	13.58	98	192	Off Idle	63	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7	14.9	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:8	34.08	2556	2.11	13.58	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.98	14.94	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:9	34.08	2560	2.11	13.58	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.97	14.97	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:9	34.08	2558	2.11	13.56	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.99	15	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:9	34.08	2557	2.1	13.56	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.96	15.02	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:9	34.08	2557	2.1	13.57	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.96	15.06	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:9	34.08	2560	2.1	13.57	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.99	15.12	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:9	34.08	2560	2.1	13.6	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.01	15.13	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:38:9	34.08	2559	2.1	13.59	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.02	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:0	34.08	2556	2.1	13.58	98	192	Off Idle	63.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:0	34.08	2556	2.1	13.59	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.98	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:0	34.08	2556	2.1	13.6	99	192	Off Idle	63.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.01	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:0	34.08	2555	2.1	13.6	99	192	Off Idle	63	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.01	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:0	34.08	2553	2.1	13.6	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.01	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:0	34.08	2555	2.1	13.6	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.03	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:1	34.08	2570	2.1	13.6	99	192	Off Idle	62.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.03	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:1	34.08	2558	2.1	13.6	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7	14.74	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:1	34.08	2560	2.1	13.59	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.02	14.71	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:1	34.08	2562	2.1	13.59	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.99	14.7	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:1	34.08	2562	2.1	13.59	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.98	14.71	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:1	34.08	2563	2.1	13.6	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.98	14.72	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:1	34.08	2562	2.1	13.6	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7	14.73	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:2	34.08	2562	2.1	13.59	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.98	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:2	34.08	2561	2.1	13.61	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7	14.75	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:2	34.08	2560	2.1	13.6	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.99	14.76	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:2	34.08	2559	2.1	13.61	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:2	34.08	2560	2.1	13.6	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.04	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:2	34.08	2559	2.1	13.59	99	192	Off Idle	62.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.02	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:3	34.08	2560	2.1	13.59	99	192	Off Idle	62.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.04	14.87	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:3	34.08	2560	2.1	13.59	99	192	Off Idle	62.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.02	14.9	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:3	34.08	2556	2.1	13.59	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.01	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:3	34.08	2559	2.1	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:3	34.08	2526	2.1	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.01	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:39:3	34.08	2546	2.1	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.04	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:4	34.08	2565	2.1	13.58	98	192	Off Idle	61.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.06	15.05	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:4	34.08	2562	2.1	13.57	98	192	Off Idle	61.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.04	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:4	34.08	2564	2.1	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.03	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:4	34.08	2576	2.09	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.06	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:4	34.08	2566	2.09	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.03	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:4	34.08	2566	2.09	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.03	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:4	34.08	2565	2.09	13.58	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.03	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:5	34.08	2564	2.09	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.02	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:5	34.08	2564	2.09	13.59	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.02	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:5	34.08	2568	2.09	13.58	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:5	34.08	2570	2.09	13.57	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.05	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:5	34.08	2568	2.09	13.56	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.06	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:5	34.08	2572	2.09	13.57	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.06	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:6	34.08	2563	2.09	13.59	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.08	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:6	34.08	2561	2.09	13.58	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.06	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:6	34.08	2560	2.09	13.58	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.05	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:6	34.08	2542	2.09	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.04	14.76	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:6	34.08	2559	2.09	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.07	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:6	34.08	2560	2.09	13.6	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.05	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:6	34.08	2563	2.09	13.59	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.05	14.84	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:7	34.08	2569	2.09	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.02	14.9	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:7	34.08	2569	2.09	13.58	98	192	Off Idle	62	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.02	14.92	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:7	34.08	2570	2.09	13.57	98	192	Off Idle	61.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.01	14.93	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:7	34.08	2571	2.09	13.56	98	192	Off Idle	61.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.01	14.96	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:7	34.08	2565	2.09	13.56	98	192	Off Idle	61.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.04	14.99	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:7	34.08	2565	2.09	13.57	98	192	Off Idle	61.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.06	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:8	34.08	2562	2.09	13.56	98	192	Off Idle	61.8	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.06	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:8	34.08	2562	2.09	13.57	98	192	Off Idle	62	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.03	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:8	34.08	2562	2.09	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.05	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:8	34.08	2563	2.09	13.58	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.02	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:8	34.08	2567	2.09	13.56	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.04	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:8	34.08	2556	2.09	13.57	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.05	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:9	34.08	2562	2.09	13.58	98	192	Off Idle	62.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.06	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:9	34.08	2568	2.09	13.58	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.09	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:9	34.08	2570	2.09	13.58	98	192	Off Idle	63	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.07	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:39:9	34.08	2572	2.09	13.59	98	192	Off Idle	63	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.11	15.02	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:9	34.08	2574	2.09	13.58	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.13	15	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:39:9	34.08	2572	2.09	13.58	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.13	14.97	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:39:9	34.08	2572	2.09	13.59	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.1	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:0	34.08	2565	2.09	13.58	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.11	14.89	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:0	34.08	2554	2.09	13.58	99	192	Off Idle	62.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.12	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:0	34.08	2559	2.09	13.59	99	192	Off Idle	62.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.1	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:0	34.08	2559	2.09	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.13	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:0	34.08	2557	2.09	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.11	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:0	34.08	2550	2.09	13.6	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.08	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:1	34.08	2568	2.09	13.6	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.09	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:1	34.08	2572	2.09	13.6	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.07	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:1	34.08	2568	2.09	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.1	14.88	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:1	34.08	2577	2.09	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.07	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:1	34.08	2561	2.09	13.56	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.08	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:1	34.08	2557	2.09	13.57	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.06	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:1	34.08	2556	2.09	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.09	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:2	34.08	2554	2.09	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.08	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:2	34.08	2538	2.09	13.58	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.11	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:2	34.08	2549	2.09	13.58	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.11	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:2	34.08	2565	2.09	13.59	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.11	15.09	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:2	34.08	2570	2.09	13.58	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.11	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:40:2	34.08	2595	2.09	13.57	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.14	15.05	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:3	34.08	2584	2.09	13.59	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.11	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:3	34.08	2576	2.09	13.59	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.11	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:3	34.08	2577	2.08	13.6	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.1	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:3	34.08	2558	2.08	13.58	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.16	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:3	34.08	2568	2.08	13.59	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.15	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:3	34.08	2571	2.08	13.58	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.14	14.82	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:4	34.08	2571	2.08	13.6	98	192	Off Idle	62.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.16	14.8	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:4	34.08	2571	2.08	13.6	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.15	14.78	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:4	34.08	2576	2.08	13.6	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.12	14.76	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:4	34.08	2578	2.08	13.59	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.11	14.78	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:4	34.08	2578	2.08	13.61	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.14	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:4	34.08	2580	2.08	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.11	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:4	34.08	2595	2.08	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.08	14.87	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:5	34.08	2582	2.09	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.06	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:5	34.08	2566	2.09	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.1	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:5	34.08	2562	2.09	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.09	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:5	34.08	2560	2.09	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.08	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:5	34.08	2557	2.09	13.58	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.14	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:5	34.08	2556	2.09	13.59	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.13	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:6	34.08	2559	2.09	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.13	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:6	34.08	2560	2.09	13.58	98	192	Off Idle	62	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.11	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:6	34.08	2556	2.09	13.59	98	192	Off Idle	62	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.15	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:6	34.08	2572	2.09	13.61	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.1	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:6	34.08	2572	2.09	13.6	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.1	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:6	34.08	2576	2.09	13.61	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.1	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:6	34.08	2574	2.09	13.61	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.12	14.91	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:7	34.08	2569	2.09	13.6	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.13	14.88	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:7	34.08	2568	2.09	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.11	14.83	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:7	34.08	2566	2.09	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.11	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:7	34.08	2565	2.09	13.57	98	192	Off Idle	62	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.12	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:7	34.08	2586	2.09	13.56	98	192	Off Idle	62	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.09	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:7	34.08	2564	2.09	13.57	98	192	Off Idle	62	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.09	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:8	34.08	2564	2.09	13.56	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.12	14.78	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:8	34.08	2565	2.09	13.56	98	191	Off Idle	62.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.11	14.78	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:8	34.08	2570	2.08	13.56	98	191	Off Idle	62.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.11	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:40:8	34.08	2550	2.08	13.58	98	191	Off Idle	62.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.11	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:8	34.08	2576	2.08	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.1	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:8	34.08	2578	2.08	13.57	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.09	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:40:9	34.08	2584	2.08	13.56	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.1	14.9	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:9	34.08	2595	2.08	13.56	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.12	14.92	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:9	34.08	2581	2.08	13.56	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.16	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:9	34.08	2578	2.09	13.56	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.11	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:9	34.08	2573	2.09	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.12	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:9	34.08	2567	2.09	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.12	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:40:9	34.08	2564	2.09	13.6	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.1	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:0	34.08	2560	2.09	13.6	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.09	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:0	34.08	2557	2.09	13.6	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.12	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:0	34.08	2557	2.09	13.62	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.12	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:0	34.08	2559	2.09	13.6	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.11	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:0	34.08	2566	2.09	13.59	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.08	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:0	34.08	2572	2.09	13.59	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.06	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:1	34.08	2572	2.09	13.57	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.06	14.9	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:1	34.08	2576	2.09	13.56	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.09	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:1	34.08	2578	2.09	13.57	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.08	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:1	34.08	2578	2.09	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.08	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:1	34.08	2579	2.09	13.57	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.1	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:1	34.08	2571	2.09	13.58	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.12	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:41:1	34.08	2562	2.09	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.1	14.77	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:2	34.08	2569	2.09	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.12	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:2	34.08	2565	2.09	13.58	98	192	Off Idle	62	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.13	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:2	34.08	2565	2.09	13.59	98	192	Off Idle	62	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.15	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:2	34.08	2562	2.09	13.59	98	192	Off Idle	62	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.14	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:2	34.08	2554	2.09	13.58	98	192	Off Idle	62	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.14	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:2	34.08	2569	2.09	13.58	98	192	Off Idle	62	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.12	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:3	34.08	2568	2.09	13.58	98	192	Off Idle	62	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.13	14.99	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:3	34.08	2568	2.09	13.59	98	192	Off Idle	62	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.14	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:3	34.08	2584	2.09	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.11	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:3	34.08	2574	2.09	13.6	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.1	15.12	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:3	34.08	2567	2.09	13.6	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.11	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:3	34.08	2571	2.09	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.11	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:4	34.08	2576	2.09	13.58	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.12	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:4	34.08	2566	2.09	13.56	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.12	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:4	34.08	2574	2.09	13.56	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.11	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:4	34.08	2570	2.09	13.57	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.12	14.95	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:4	34.08	2570	2.09	13.59	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.14	14.92	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:4	34.08	2567	2.08	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.16	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:4	34.08	2589	2.08	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.13	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:5	34.08	2570	2.08	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.11	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:5	34.08	2572	2.08	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.13	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:5	34.08	2575	2.08	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.13	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:5	34.08	2575	2.08	13.58	98	192	Off Idle	61.9	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.15	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:5	34.08	2568	2.08	13.58	98	192	Off Idle	61.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.16	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:5	34.08	2568	2.08	13.57	98	192	Off Idle	61.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.15	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:6	34.08	2587	2.08	13.57	98	192	Off Idle	61.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.12	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:6	34.08	2575	2.08	13.57	98	192	Off Idle	61.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.11	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:6	34.08	2575	2.08	13.56	98	192	Off Idle	61.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.12	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:6	34.08	2571	2.09	13.59	98	192	Off Idle	61.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.12	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:6	34.08	2568	2.09	13.57	98	192	Off Idle	61.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.15	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:6	34.08	2566	2.09	13.58	98	192	Off Idle	61.4	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.16	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:6	34.08	2557	2.09	13.6	98	192	Off Idle	61.4	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.14	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:7	34.08	2570	2.09	13.6	98	192	Off Idle	61.6	0	2	132	944 Turbo	0.7	Lean	1	14.6	-7.17	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:7	34.08	2570	2.09	13.61	98	192	Off Idle	61.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.15	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:7	34.08	2576	2.09	13.61	98	192	Off Idle	61.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.15	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:7	34.08	2576	2.09	13.61	98	192	Off Idle	61.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.14	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:7	34.08	2584	2.09	13.61	98	192	Off Idle	62	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.14	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:7	34.08	2568	2.09	13.6	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.1	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:8	34.08	2566	2.09	13.6	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.14	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:41:8	34.08	2564	2.09	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.14	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:8	34.08	2570	2.09	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.16	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:8	34.08	2564	2.09	13.6	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.16	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:8	34.08	2570	2.09	13.61	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.16	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:8	34.08	2570	2.09	13.58	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.16	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:9	34.08	2576	2.09	13.57	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.16	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:9	34.08	2584	2.09	13.58	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.14	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:9	34.08	2584	2.09	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.15	14.77	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:9	34.08	2582	2.09	13.58	98	192	Off Idle	62	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.16	14.76	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:9	34.08	2580	2.09	13.57	98	192	Off Idle	61.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.14	14.78	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:41:9	34.08	2578	2.09	13.58	98	192	Off Idle	61.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.1	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:41:9	34.08	2584	2.09	13.59	98	192	Off Idle	61.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.15	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:0	34.08	2570	2.09	13.59	98	192	Off Idle	61.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.16	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:0	34.08	2566	2.09	13.57	98	192	Off Idle	61.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.12	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:0	34.08	2565	2.09	13.58	98	192	Off Idle	61.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.11	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:0	34.08	2568	2.09	13.59	98	192	Off Idle	61.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.15	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:0	34.08	2568	2.09	13.59	98	192	Off Idle	61.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.11	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:0	34.08	2573	2.09	13.6	98	192	Off Idle	61.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.14	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:42:1	34.08	2575	2.09	13.61	98	192	Off Idle	62	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.12	15.05	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:1	34.08	2578	2.09	13.61	98	192	Off Idle	62	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.15	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:1	34.08	2580	2.09	13.62	98	192	Off Idle	62	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.17	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:1	34.08	2580	2.09	13.6	98	192	Off Idle	62	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.16	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:42:1	34.08	2581	2.09	13.6	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.16	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:42:1	34.08	2575	2.09	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.17	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:42:1	34.08	2575	2.09	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.16	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:42:2	34.08	2571	2.09	13.58	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.14	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:42:2	34.08	2565	2.09	13.57	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.15	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:42:2	34.08	2565	2.09	13.59	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.15	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:42:2	34.08	2564	2.09	13.59	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.13	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:42:2	34.08	2562	2.09	13.61	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.17	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:42:2	34.08	2562	2.08	13.6	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.18	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:42:3	34.08	2570	2.08	13.61	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.2	14.83	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:21:42:3	34.08	2576	2.08	13.6	98	192	Off Idle	62.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.21	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:21:42:3	34.08	2576	2.08	13.59	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.2	14.9	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:3	34.08	2579	2.08	13.6	98	192	Off Idle	63	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.21	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:3	34.08	2578	2.08	13.6	98	192	Off Idle	63	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.19	14.92	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:3	34.08	2575	2.08	13.6	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.2	14.94	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:4	34.08	2575	2.07	13.6	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.23	14.96	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:4	34.08	2567	2.07	13.61	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.23	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:4	34.08	2566	2.07	13.6	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.24	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:4	34.08	2566	2.07	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.25	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:4	34.08	2568	2.07	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.24	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:4	34.08	2573	2.07	13.58	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.25	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:4	34.08	2575	2.07	13.58	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.27	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:5	34.08	2574	2.07	13.57	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.27	15	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:5	34.08	2588	2.07	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.29	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:5	34.08	2579	2.06	13.58	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.32	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:5	34.08	2578	2.06	13.59	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.33	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:5	34.08	2577	2.06	13.57	98	192	Off Idle	62	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.37	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:5	34.08	2577	2.05	13.59	98	192	Off Idle	62	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.39	14.76	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:6	34.08	2564	2.05	13.58	98	192	Off Idle	62	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.45	14.68	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:6	34.08	2570	2.05	13.57	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.5	14.66	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:21:42:6	34.08	2566	2.04	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.52	14.66	1	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:6	34.08	2570	2.04	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.55	14.67	1	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:6	34.08	2567	2.03	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.62	14.7	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:6	34.08	2578	2.03	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.68	14.73	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:6	34.08	2564	2.03	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.68	14.75	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:7	35.45	2564	2.02	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.69	14.76	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:7	35.45	2547	2.02	13.57	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.71	14.77	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:7	35.45	2565	2.01	13.59	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	14.77	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:7	35.45	2566	2	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.73	14.78	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:7	35.45	2572	2	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.75	14.8	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:7	35.45	2594	2	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.77	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:8	35.45	2582	1.99	13.6	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.79	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:8	35.45	2581	1.98	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.84	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:8	35.45	2564	1.98	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.86	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:8	35.45	2567	1.98	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.88	14.9	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:8	35.45	2565	1.98	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.86	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:8	35.45	2554	1.97	13.56	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.84	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:9	35.45	2556	1.97	13.57	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.84	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:9	35.45	2564	1.97	13.57	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.86	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:9	35.45	2564	1.97	13.56	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.82	15.05	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:9	35.45	2574	1.97	13.57	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.82	15.05	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:42:9	35.45	2582	1.97	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.83	15.04	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:9	35.45	2606	1.97	13.57	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.83	15.02	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:42:9	35.45	2597	1.97	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.86	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:43:0	35.45	2588	1.97	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.88	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:0	35.45	2582	1.97	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.87	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:0	35.45	2582	1.97	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.88	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:0	35.45	2568	1.97	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.92	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:0	35.45	2568	1.97	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.89	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:0	35.45	2567	1.97	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.9	14.83	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:1	35.45	2577	1.97	13.58	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.89	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:1	35.45	2570	1.97	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.88	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:1	35.45	2571	1.97	13.6	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.87	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:1	35.45	2571	1.97	13.59	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.89	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:1	35.45	2574	1.97	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.89	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:1	34.08	2565	1.97	13.56	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.9	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:1	34.08	2575	1.97	13.56	98	192	Off Idle	61.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.91	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:2	34.08	2575	1.97	13.59	98	192	Off Idle	61.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.91	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:2	34.08	2570	1.97	13.57	98	192	Off Idle	61.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.94	15.09	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:2	34.08	2561	1.97	13.59	98	192	Off Idle	62	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.92	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:2	34.08	2559	1.97	13.61	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.9	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:2	34.08	2556	1.97	13.6	98	192	Off Idle	62.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.92	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:2	34.08	2549	1.97	13.6	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.91	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:3	34.08	2552	1.97	13.6	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.91	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:3	34.08	2560	1.97	13.58	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.9	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:3	34.08	2560	1.97	13.58	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.91	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:3	35.45	2574	1.97	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.92	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:3	35.45	2580	1.97	13.59	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.93	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:3	35.45	2580	1.96	13.6	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.94	14.91	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:4	35.45	2572	1.96	13.6	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.97	14.88	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:4	35.45	2585	1.96	13.6	98	192	Off Idle	62.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.95	14.8	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:4	35.45	2576	1.96	13.6	98	192	Off Idle	62.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.97	14.77	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:4	35.45	2568	1.96	13.6	98	192	Off Idle	62.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.98	14.77	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:4	35.45	2570	1.96	13.59	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.99	14.76	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:4	35.45	2570	1.96	13.59	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.99	14.75	1	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:4	35.45	2568	1.96	13.58	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8	14.74	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:21:43:5	35.45	2566	1.96	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.01	14.75	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:5	35.45	2565	1.96	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.01	14.78	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:5	34.08	2549	1.95	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.02	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:5	34.08	2558	1.95	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.04	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:5	34.08	2576	1.95	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.08	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:5	34.08	2567	1.95	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.07	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:43:6	34.08	2568	1.95	13.59	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.05	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:6	34.08	2548	1.94	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.1	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:6	35.45	2587	1.94	13.6	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.14	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:6	35.45	2578	1.94	13.58	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.15	15.01	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:6	35.45	2580	1.94	13.58	98	192	Off Idle	62.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.19	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:6	35.45	2570	1.93	13.59	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.22	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:6	35.45	2566	1.93	13.59	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.26	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:7	35.45	2566	1.93	13.59	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.23	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:7	35.45	2565	1.92	13.6	98	192	Off Idle	62.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.26	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:7	35.45	2560	1.92	13.6	98	192	Off Idle	62.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.31	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:7	35.45	2555	1.91	13.6	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.36	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:7	35.45	2556	1.91	13.61	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.35	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:7	35.45	2556	1.91	13.6	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.41	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:8	35.45	2554	1.9	13.6	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.46	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:8	35.45	2560	1.89	13.61	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.51	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:8	35.45	2561	1.88	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.58	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:43:8	35.45	2562	1.87	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.62	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:43:8	35.45	2557	1.86	13.58	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.72	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:43:8	35.45	2555	1.85	13.57	98	192	Off Idle	62.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.83	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:9	35.45	2554	1.84	13.59	98	192	Off Idle	62.3	0	2	132	944 Turbo	0.16	Rich	1	14.6	-8.84	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:43:9	35.45	2555	1.82	13.57	98	192	Off Idle	62.4	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.95	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:43:9	35.45	2551	1.8	13.58	98	192	Off Idle	62.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.16	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:43:9	35.45	2550	1.78	13.6	98	192	Off Idle	62.7	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.3	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:43:9	35.45	2550	1.76	13.6	98	192	Off Idle	62.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.38	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:43:9	35.45	2550	1.72	13.59	98	192	Full Load	62.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.6	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:43:9	35.45	2552	1.7	13.59	98	192	Idle	63.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.71	14.88	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:0	35.45	2552	1.67	13.6	98	192	Idle	63.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.84	14.89	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:0	35.45	2545	1.63	13.57	98	192	Idle	63.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.98	14.93	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:44:0	35.45	2532	1.6	13.58	98	192	Idle	63.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.05	14.94	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:0	35.45	2532	1.58	13.57	98	192	Idle	63.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.16	14.94	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:0	35.45	2516	1.55	13.58	98	192	Idle	63.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.22	14.98	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:0	35.45	2484	1.53	13.58	98	192	Idle	63.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.26	15.01	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:1	32.72	2475	1.5	13.59	98	192	Idle	63.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.32	15.03	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:1	27.27	2475	1.48	13.57	98	192	Idle	63.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.39	15.01	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:1	27.27	2487	1.46	13.58	98	192	Idle	63.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.4	14.99	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:1	21.81	2524	1.43	13.58	98	192	Idle	63.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.45	14.97	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:1	19.09	2556	1.41	13.59	98	192	Idle	63.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.47	14.91	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:1	19.09	2557	1.39	13.59	98	192	Idle	63.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.5	14.88	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:1	19.09	2560	1.38	13.61	98	192	Idle	63.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.54	14.83	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:2	19.09	2559	1.37	13.6	98	192	Idle	63.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-10.56	14.76	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:2	19.09	2557	1.36	13.6	98	192	Idle	63.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.58	14.67	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:2	19.09	2546	1.35	13.59	98	192	Idle	63.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.6	14.59	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:2	19.09	2536	1.35	13.59	98	192	Idle	63.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.59	14.55	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:2	19.09	2536	1.35	13.6	98	192	Idle	63.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.55	14.51	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:2	19.09	2528	1.35	13.59	98	192	Idle	63.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.53	14.47	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:3	19.09	2521	1.35	13.58	98	192	Idle	63.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.51	14.43	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:3	19.09	2524	1.35	13.59	98	192	Idle	63.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.48	14.41	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:3	19.09	2524	1.35	13.59	98	192	Idle	63.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.49	14.39	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:3	19.09	2527	1.35	13.58	98	192	Idle	63.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.44	14.39	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:3	19.09	2533	1.35	13.58	98	192	Idle	62.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.41	14.39	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:3	19.09	2535	1.35	13.58	98	192	Idle	62.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	14.41	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:4	19.09	2529	1.35	13.59	98	192	Idle	62.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.37	14.44	0.98	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:4	19.09	2541	1.36	13.58	98	192	Idle	62.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.38	14.48	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:4	19.09	2540	1.36	13.58	98	192	Idle	62.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	14.52	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:4	19.09	2550	1.36	13.59	98	192	Idle	62.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	14.54	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:4	19.09	2536	1.36	13.6	98	192	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	14.55	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:4	19.09	2535	1.36	13.59	98	192	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	14.6	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:4	19.09	2530	1.36	13.61	98	192	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	14.72	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:5	19.09	2528	1.36	13.6	98	192	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	14.82	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:5	19.09	2526	1.36	13.59	98	192	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	14.88	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:5	19.09	2526	1.36	13.6	98	192	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	14.99	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:5	19.09	2548	1.36	13.6	98	192	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	15.19	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:5	19.09	2532	1.36	13.6	98	192	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	15.36	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:5	19.09	2534	1.36	13.59	98	192	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	15.56	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:6	19.09	2514	1.36	13.6	98	192	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	15.87	1.08	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:6	19.09	2531	1.36	13.61	98	192	Idle	63.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	16.23	1.11	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:6	19.09	2531	1.36	13.61	98	192	Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	16.66	1.14	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:6	19.09	2526	1.36	13.6	98	192	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	17.15	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:6	19.09	2504	1.36	13.61	98	192	Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	17.63	1.2	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:6	19.09	2521	1.36	13.59	98	192	Idle	63.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	18.32	1.25	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:6	19.09	2518	1.36	13.6	98	192	Idle	63.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	18.76	1.28	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:7	19.09	2502	1.36	13.58	98	192	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	19.16	1.31	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:7	19.09	2512	1.35	13.58	98	192	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	19.52	1.33	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:7	19.09	2512	1.35	13.58	98	192	Idle	64.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	19.8	1.35	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:7	19.09	2512	1.35	13.6	98	192	Idle	64.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.02	1.36	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:7	19.09	2511	1.35	13.6	98	192	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.16	1.37	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:7	19.09	2511	1.35	13.59	98	192	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:8	19.09	2514	1.35	13.6	98	192	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:44:8	19.09	2515	1.35	13.59	98	192	Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:8	19.09	2514	1.35	13.6	98	192	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:8	19.09	2514	1.34	13.58	98	192	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:8	19.09	2514	1.34	13.58	98	192	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:8	19.09	2513	1.34	13.58	98	192	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:9	19.09	2512	1.34	13.58	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:9	19.09	2509	1.34	13.57	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:9	19.09	2505	1.34	13.58	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:9	19.09	2504	1.34	13.59	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:9	19.09	2502	1.34	13.59	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:9	19.09	2510	1.33	13.59	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:44:9	19.09	2510	1.33	13.59	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:0	19.09	2502	1.33	13.57	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:0	19.09	2506	1.33	13.58	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:0	19.09	2510	1.33	13.58	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:0	19.09	2510	1.33	13.57	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:0	19.09	2511	1.33	13.58	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:0	19.09	2514	1.33	13.58	98	192	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:1	19.09	2511	1.33	13.58	98	192	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:1	19.09	2510	1.33	13.59	98	192	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:1	19.09	2506	1.33	13.59	98	192	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:1	19.09	2501	1.33	13.58	98	192	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:1	19.09	2498	1.33	13.59	98	192	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:1	19.09	2494	1.33	13.59	98	192	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:1	19.09	2484	1.33	13.6	98	192	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:2	19.09	2482	1.33	13.59	98	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:2	19.09	2481	1.32	13.59	98	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:2	19.09	2478	1.32	13.59	98	192	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:2	19.09	2478	1.32	13.58	98	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:2	19.09	2480	1.32	13.58	98	192	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:2	19.09	2484	1.32	13.59	98	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:3	19.09	2506	1.32	13.58	98	192	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:3	19.09	2490	1.32	13.59	98	192	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:3	19.09	2490	1.32	13.59	98	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:3	19.09	2484	1.32	13.6	98	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:3	19.09	2506	1.32	13.59	98	192	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:3	19.09	2494	1.32	13.6	98	192	Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:4	19.09	2494	1.32	13.6	98	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:4	19.09	2467	1.32	13.59	98	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:4	19.09	2482	1.32	13.59	98	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:4	19.09	2482	1.32	13.58	98	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:4	19.09	2477	1.32	13.59	98	192	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:4	19.09	2476	1.32	13.58	98	192	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:4	19.09	2469	1.32	13.57	98	192	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:5	19.09	2470	1.32	13.58	98	192	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:5	19.09	2470	1.32	13.58	98	192	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:5	19.09	2469	1.32	13.58	98	192	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:5	19.09	2469	1.32	13.59	98	192	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:5	19.09	2474	1.32	13.58	98	192	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:5	19.09	2478	1.32	13.58	98	192	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:6	19.09	2481	1.32	13.59	98	192	Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:6	19.09	2482	1.32	13.59	98	192	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:6	19.09	2492	1.32	13.61	98	192	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:6	19.09	2479	1.32	13.61	98	192	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:6	19.09	2468	1.32	13.6	98	192	Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:6	19.09	2474	1.32	13.59	98	192	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:6	19.09	2469	1.32	13.59	98	192	Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:7	19.09	2462	1.32	13.6	98	192	Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:45:7	19.09	2460	1.31	13.6	98	192	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:7	19.09	2460	1.31	13.59	98	192	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:7	19.09	2457	1.31	13.59	98	192	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:7	19.09	2455	1.31	13.6	98	192	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:7	19.09	2457	1.31	13.6	98	192	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:8	19.09	2457	1.31	13.58	98	192	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:8	19.09	2462	1.31	13.59	98	192	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:8	19.09	2463	1.31	13.59	98	192	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:8	19.09	2464	1.31	13.59	98	192	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:8	19.09	2466	1.31	13.6	98	192	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:8	19.09	2456	1.31	13.6	98	192	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:9	19.09	2463	1.31	13.6	98	192	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:9	19.09	2462	1.31	13.59	98	192	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:9	19.09	2460	1.31	13.6	98	192	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:9	19.09	2447	1.31	13.6	98	192	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:9	19.09	2447	1.31	13.59	98	192	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:9	19.09	2446	1.31	13.59	98	192	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:45:9	19.09	2449	1.31	13.6	98	192	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:0	17.72	2431	1.3	13.58	98	192	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:0	17.72	2454	1.3	13.6	98	192	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:0	17.72	2468	1.3	13.58	98	192	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:0	17.72	2460	1.3	13.59	98	192	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:0	19.09	2460	1.3	13.58	98	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:0	19.09	2478	1.3	13.58	98	192	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:1	19.09	2480	1.3	13.59	98	192	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:1	19.09	2480	1.29	13.59	98	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:1	19.09	2456	1.29	13.59	98	192	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:1	19.09	2433	1.29	13.58	98	192	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:1	19.09	2450	1.29	13.59	98	192	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:1	17.72	2440	1.29	13.6	98	192	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:1	17.72	2455	1.29	13.61	98	192	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:2	19.09	2445	1.29	13.59	98	192	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:2	17.72	2436	1.28	13.58	98	192	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:2	17.72	2440	1.28	13.58	98	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:2	17.72	2438	1.28	13.58	98	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:2	17.72	2438	1.28	13.58	98	192	Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:2	17.72	2440	1.28	13.58	98	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:3	17.72	2441	1.28	13.59	98	192	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:3	17.72	2441	1.28	13.58	98	192	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:3	17.72	2439	1.28	13.58	98	192	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:3	17.72	2435	1.28	13.59	98	192	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:3	17.72	2437	1.28	13.58	98	192	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.18	1.37	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:3	17.72	2434	1.28	13.58	98	192	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:4	17.72	2432	1.28	13.59	98	192	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:4	17.72	2428	1.28	13.58	98	192	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:4	17.72	2428	1.28	13.58	98	192	Idle	68.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:4	17.72	2426	1.27	13.58	98	192	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:4	17.72	2427	1.27	13.58	98	192	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:4	17.72	2428	1.27	13.59	98	192	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:4	17.72	2429	1.27	13.59	98	192	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:5	17.72	2430	1.27	13.59	98	192	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:5	17.72	2432	1.26	13.6	98	192	Idle	69.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:5	17.72	2432	1.26	13.59	98	192	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:5	17.72	2432	1.26	13.58	98	192	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:5	17.72	2431	1.26	13.59	98	192	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:5	17.72	2430	1.25	13.59	98	192	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:6	17.72	2427	1.25	13.59	98	192	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:6	17.72	2424	1.25	13.59	98	192	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:46:6	17.72	2422	1.24	13.59	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:6	17.72	2420	1.24	13.59	98	192	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.18	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:6	17.72	2420	1.24	13.59	98	192	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:6	17.72	2420	1.24	13.59	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:6	17.72	2420	1.24	13.58	98	192	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:7	17.72	2422	1.23	13.58	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:7	17.72	2423	1.23	13.59	98	192	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:7	17.72	2407	1.23	13.6	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:7	17.72	2421	1.23	13.6	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:7	17.72	2421	1.23	13.61	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:7	17.72	2430	1.22	13.61	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:8	17.72	2412	1.22	13.6	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:8	17.72	2419	1.22	13.59	98	192	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:8	17.72	2419	1.22	13.6	98	192	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:8	17.72	2433	1.22	13.59	98	192	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:8	17.72	2415	1.22	13.59	98	192	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:8	17.72	2414	1.22	13.6	98	192	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:9	17.72	2403	1.22	13.6	98	192	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:9	17.72	2410	1.22	13.6	98	192	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:9	17.72	2410	1.22	13.59	98	192	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:9	17.72	2410	1.22	13.58	98	192	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:9	17.72	2409	1.21	13.59	98	192	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:9	17.72	2406	1.21	13.59	98	192	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:46:9	17.72	2406	1.21	13.58	98	192	Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:0	17.72	2402	1.21	13.6	98	192	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:0	17.72	2401	1.21	13.6	98	192	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:0	17.72	2411	1.21	13.6	98	192	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:0	17.72	2384	1.21	13.59	98	192	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:0	17.72	2401	1.21	13.59	98	192	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:0	17.72	2402	1.21	13.6	98	192	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:1	17.72	2402	1.21	13.59	98	192	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:1	17.72	2400	1.21	13.6	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:1	17.72	2402	1.21	13.6	98	192	Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:1	17.72	2402	1.21	13.6	98	192	Idle	70.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:1	17.72	2404	1.21	13.61	98	192	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:1	17.72	2421	1.21	13.61	98	192	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:1	17.72	2410	1.21	13.6	98	192	Idle	70.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:2	17.72	2380	1.21	13.61	98	192	Idle	70.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:2	17.72	2395	1.21	13.6	98	192	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:2	17.72	2395	1.21	13.6	98	192	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:2	17.72	2391	1.21	13.6	98	192	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:2	17.72	2390	1.21	13.6	98	192	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:2	17.72	2390	1.21	13.59	98	192	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:3	17.72	2391	1.21	13.59	98	192	Idle	70.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:3	17.72	2390	1.21	13.58	98	192	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:3	17.72	2391	1.21	13.57	98	192	Idle	71.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:3	17.72	2394	1.21	13.58	98	192	Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:3	17.72	2394	1.21	13.58	98	192	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:3	17.72	2394	1.2	13.59	98	192	Idle	71.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:4	17.72	2396	1.2	13.59	98	192	Idle	71.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:4	17.72	2396	1.2	13.6	98	192	Idle	71.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:4	17.72	2406	1.2	13.6	98	192	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:4	17.72	2396	1.2	13.6	98	192	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:4	17.72	2375	1.2	13.6	98	192	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:4	17.72	2392	1.2	13.59	98	192	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:4	17.72	2390	1.2	13.59	98	192	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:5	17.72	2382	1.2	13.59	98	192	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:5	17.72	2378	1.2	13.6	98	192	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:47:5	17.72	2376	1.2	13.59	98	192	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:5	17.72	2370	1.19	13.59	98	192	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:5	17.72	2365	1.19	13.6	98	192	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:5	17.72	2365	1.19	13.59	98	192	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:6	17.72	2363	1.19	13.59	98	192	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:6	17.72	2374	1.19	13.6	98	192	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:6	17.72	2351	1.19	13.59	98	192	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:6	17.72	2372	1.19	13.58	98	192	Idle	72	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:6	17.72	2372	1.19	13.58	98	192	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:6	17.72	2377	1.19	13.59	98	192	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:6	17.72	2377	1.19	13.59	98	192	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:7	17.72	2383	1.19	13.59	98	192	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:7	17.72	2385	1.19	13.6	98	192	Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:7	17.72	2384	1.19	13.58	98	192	Idle	71.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:7	17.72	2379	1.19	13.59	98	192	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:7	17.72	2378	1.19	13.59	98	192	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:7	17.72	2373	1.19	13.58	98	192	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:8	17.72	2373	1.19	13.59	98	192	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:8	17.72	2368	1.19	13.59	98	192	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:8	17.72	2364	1.19	13.57	98	192	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:8	17.72	2362	1.19	13.58	98	192	Idle	72.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:8	17.72	2362	1.19	13.6	98	192	Idle	72.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:8	17.72	2361	1.19	13.6	98	192	Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:9	17.72	2380	1.19	13.6	98	192	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:9	17.72	2347	1.19	13.61	98	192	Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:9	17.72	2347	1.19	13.6	98	192	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:9	17.72	2364	1.19	13.6	98	192	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:9	17.72	2366	1.19	13.59	98	192	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:9	17.72	2366	1.19	13.59	98	192	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:47:9	17.72	2365	1.19	13.6	98	192	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:0	17.72	2364	1.19	13.6	98	192	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:0	17.72	2364	1.18	13.61	98	192	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:0	17.72	2362	1.18	13.6	98	192	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:0	17.72	2359	1.18	13.61	98	192	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:0	17.72	2359	1.18	13.59	98	192	Idle	72.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:0	17.72	2356	1.18	13.6	98	192	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:1	17.72	2351	1.18	13.6	98	192	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:1	17.72	2344	1.18	13.6	98	192	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:1	17.72	2344	1.18	13.59	98	192	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:1	17.72	2342	1.18	13.57	98	192	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:1	17.72	2341	1.18	13.57	98	192	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:1	17.72	2342	1.18	13.57	98	192	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:1	17.72	2342	1.18	13.57	98	192	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:2	17.72	2344	1.18	13.58	98	192	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:2	17.72	2347	1.18	13.6	98	192	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:2	17.72	2348	1.18	13.6	98	192	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:2	17.72	2354	1.18	13.61	98	192	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:2	17.72	2361	1.18	13.61	98	192	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.19	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:2	17.72	2362	1.17	13.61	98	192	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:3	17.72	2362	1.17	13.6	98	192	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:3	17.72	2360	1.17	13.59	98	192	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:3	17.72	2356	1.17	13.58	98	192	Idle	73.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:3	17.72	2356	1.17	13.59	98	192	Idle	73.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:3	17.72	2355	1.17	13.59	98	192	Idle	73.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:3	17.72	2353	1.17	13.6	98	192	Idle	73.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:4	17.72	2346	1.17	13.6	98	192	Idle	73.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:4	17.72	2344	1.17	13.59	98	192	Idle	73.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:4	17.72	2334	1.17	13.6	98	192	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:48:4	17.72	2345	1.16	13.6	98	192	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:4	17.72	2345	1.16	13.6	98	192	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:4	17.72	2342	1.16	13.6	98	192	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:4	17.72	2341	1.16	13.61	98	192	Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:5	17.72	2342	1.16	13.61	98	192	Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:5	17.72	2342	1.16	13.6	98	192	Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:5	17.72	2320	1.16	13.6	98	192	Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:5	17.72	2330	1.16	13.61	98	192	Idle	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:5	17.72	2353	1.16	13.6	98	192	Full Load	74.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:5	17.72	2331	1.16	13.6	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:21:48:6	8.18	2210	1.16	13.61	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:21:48:6	8.18	2278	1.16	13.6	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:21:48:6	10.9	2344	1.16	13.6	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:21:48:6	10.9	2342	1.16	13.6	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:21:48:6	13.63	2342	1.17	13.59	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:21:48:6	16.36	2336	1.17	13.58	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:21:48:6	16.36	2344	1.18	13.6	98	192	Off Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:48:7	19.09	2347	1.18	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:48:7	21.81	2348	1.19	13.6	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:48:7	21.81	2352	1.2	13.59	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:48:7	24.54	2372	1.2	13.59	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:48:7	24.54	2364	1.21	13.6	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:48:7	27.27	2357	1.22	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:48:8	29.99	2357	1.23	13.6	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:21:48:8	29.99	2358	1.24	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:8	32.72	2355	1.25	13.61	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:8	35.45	2352	1.26	13.61	98	192	Off Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:8	35.45	2352	1.27	13.61	98	192	Off Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:8	35.45	2334	1.28	13.61	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:9	35.45	2326	1.29	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:9	35.45	2331	1.3	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:9	35.45	2331	1.31	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:9	35.45	2332	1.31	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:9	35.45	2348	1.32	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:9	35.45	2337	1.33	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:48:9	35.45	2317	1.33	13.57	98	192	Off Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:49:0	35.45	2319	1.33	13.56	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:49:0	35.45	2306	1.34	13.57	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:49:0	35.45	2312	1.34	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:49:0	35.45	2314	1.35	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.23	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:49:0	35.45	2319	1.35	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.2	20.2	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:0	35.45	2318	1.35	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.19	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:1	35.45	2329	1.36	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.17	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:1	35.45	2341	1.36	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.18	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:1	35.45	2341	1.36	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.18	20.2	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:1	35.45	2342	1.37	13.6	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.16	20.19	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:1	35.45	2355	1.37	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.12	20.19	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:1	35.45	2345	1.37	13.6	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.12	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:1	35.45	2329	1.38	13.61	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.08	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:2	35.45	2321	1.38	13.59	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.08	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:2	35.45	2312	1.39	13.59	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.08	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:2	35.45	2312	1.4	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.07	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:49:2	35.45	2318	1.4	13.57	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.04	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:2	35.45	2319	1.41	13.56	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.01	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:2	35.45	2319	1.41	13.56	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.99	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:3	35.45	2323	1.42	13.59	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.95	20.22	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:3	35.45	2326	1.43	13.59	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.91	20.23	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:3	35.45	2326	1.43	13.58	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.91	20.17	1.37	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:49:3	35.45	2322	1.44	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.89	20.09	1.37	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:3	35.45	2327	1.44	13.6	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.85	19.9	1.36	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:3	35.45	2312	1.45	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.84	19.73	1.34	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:4	35.45	2312	1.45	13.61	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.82	19.55	1.33	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:4	35.45	2312	1.46	13.6	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.84	19.34	1.32	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:4	35.45	2297	1.46	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.8	19.12	1.3	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:4	35.45	2314	1.47	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.79	18.76	1.28	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:4	35.45	2314	1.47	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.77	18.5	1.26	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:49:4	35.45	2315	1.47	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.79	18.28	1.25	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:4	35.45	2330	1.48	13.56	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.79	18.08	1.23	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:5	35.45	2322	1.48	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.75	17.91	1.22	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:5	35.45	2315	1.48	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.73	17.75	1.21	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:5	35.45	2316	1.48	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.74	17.62	1.2	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:5	35.45	2316	1.49	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.7	17.48	1.19	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:5	35.45	2298	1.49	13.61	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.67	17.42	1.19	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:5	35.45	2312	1.49	13.6	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.67	17.23	1.17	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:6	35.45	2310	1.5	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.64	17.13	1.17	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:6	35.45	2310	1.5	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.62	17.01	1.16	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:6	35.45	2310	1.5	13.61	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.6	16.92	1.15	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:6	35.45	2318	1.51	13.61	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.6	16.77	1.14	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:6	35.45	2324	1.51	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.59	16.67	1.14	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:6	35.45	2325	1.51	13.59	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.6	16.57	1.13	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:6	35.45	2325	1.52	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.61	16.48	1.12	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:7	35.45	2329	1.52	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.58	16.39	1.12	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:7	35.45	2330	1.52	13.59	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.56	16.32	1.11	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:7	35.45	2330	1.53	13.57	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.58	16.21	1.1	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:7	35.45	2350	1.53	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.59	16.14	1.1	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:7	35.45	2344	1.53	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.57	16.07	1.09	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:7	35.45	2338	1.53	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	16.02	1.09	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:8	35.45	2338	1.54	13.57	98	192	Off Idle	76	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.57	15.92	1.08	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:49:8	35.45	2335	1.54	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.55	15.88	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:8	35.45	2334	1.54	13.59	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.5	15.85	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:8	35.45	2321	1.55	13.59	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.5	15.82	1.08	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:8	35.45	2311	1.55	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.49	15.77	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:8	35.45	2301	1.55	13.59	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.46	15.73	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:9	35.45	2299	1.56	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.43	15.69	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:9	35.45	2297	1.56	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.42	15.65	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:9	35.45	2297	1.56	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.4	15.61	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:9	35.45	2304	1.56	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.43	15.56	1.06	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:9	35.45	2309	1.56	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.39	15.51	1.06	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:9	35.45	2317	1.56	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.4	15.47	1.05	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:49:9	35.45	2317	1.56	13.6	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.4	15.43	1.05	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:0	35.45	2322	1.56	13.59	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.4	15.38	1.05	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:0	35.45	2328	1.56	13.61	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.37	15.34	1.05	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:0	35.45	2328	1.57	13.6	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.39	15.31	1.04	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:50:0	35.45	2318	1.57	13.59	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.39	15.27	1.04	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:50:0	35.45	2307	1.57	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.39	15.26	1.04	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:0	34.08	2311	1.57	13.57	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.37	15.23	1.04	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:1	34.08	2311	1.58	13.57	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.35	15.19	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:1	34.08	2304	1.58	13.57	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.31	15.17	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:1	34.08	2306	1.58	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.27	15.14	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:1	34.08	2325	1.58	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.26	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:1	34.08	2316	1.58	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.24	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:1	35.45	2329	1.58	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.23	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:1	35.45	2318	1.58	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.22	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:2	35.45	2318	1.59	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.25	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:2	35.45	2310	1.59	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.26	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:2	35.45	2320	1.59	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.28	14.99	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:50:2	35.45	2320	1.59	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.31	14.99	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:2	35.45	2319	1.59	13.59	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.28	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:2	34.08	2315	1.6	13.58	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.29	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:3	34.08	2309	1.6	13.57	98	192	Off Idle	76.9	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.3	14.96	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:3	34.08	2307	1.6	13.58	98	192	Off Idle	76.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.26	14.96	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:3	34.08	2302	1.6	13.59	98	192	Off Idle	76.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.25	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:3	34.08	2302	1.6	13.58	98	192	Off Idle	76.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.25	14.93	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:3	34.08	2302	1.6	13.59	98	192	Off Idle	76.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.21	14.92	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:3	34.08	2308	1.6	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.21	14.91	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:4	34.08	2312	1.6	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.23	14.9	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:4	34.08	2317	1.6	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.19	14.91	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:4	34.08	2317	1.6	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.18	14.91	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:4	34.08	2325	1.6	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.2	14.92	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:4	34.08	2327	1.6	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.21	14.92	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:4	34.08	2326	1.6	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.19	14.92	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:4	34.08	2322	1.6	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.21	14.94	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:5	34.08	2311	1.6	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.24	14.97	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:5	34.08	2311	1.61	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.21	15	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:5	34.08	2303	1.61	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.2	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:5	34.08	2295	1.61	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.18	15.05	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:5	34.08	2293	1.61	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.14	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:5	34.08	2294	1.61	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.16	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:6	34.08	2297	1.61	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.12	15.05	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:6	34.08	2302	1.61	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.07	15.04	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:6	34.08	2302	1.61	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.06	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:6	34.08	2305	1.62	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.06	15	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:50:6	34.08	2305	1.62	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.96	15.01	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:6	34.08	2336	1.63	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.94	15.01	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:6	34.08	2336	1.63	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.93	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:7	34.08	2324	1.64	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.87	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:7	34.08	2328	1.64	13.6	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.84	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:7	34.08	2330	1.65	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.83	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:7	34.08	2317	1.65	13.59	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.79	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:7	34.08	2342	1.66	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.76	14.95	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:7	34.08	2342	1.67	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.76	14.94	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:8	34.08	2340	1.68	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.73	14.92	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:8	34.08	2322	1.68	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.73	14.89	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:8	34.08	2310	1.69	13.57	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.73	14.86	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:8	34.08	2310	1.69	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.73	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:8	34.08	2293	1.69	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.74	14.81	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:8	34.08	2289	1.7	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.71	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:9	34.08	2288	1.71	13.6	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.66	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:50:9	34.08	2289	1.71	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.64	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:9	34.08	2296	1.72	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.62	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:9	34.08	2301	1.72	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.59	14.87	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:9	34.08	2314	1.73	13.61	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.6	14.9	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:9	34.08	2323	1.73	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.62	14.93	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:50:9	34.08	2323	1.73	13.58	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.61	14.96	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:0	34.08	2330	1.73	13.58	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.62	15.01	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:0	34.08	2329	1.73	13.57	98	192	Off Idle	76.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.62	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:0	34.08	2330	1.73	13.59	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.62	15.05	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:0	34.08	2332	1.73	13.58	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.61	15.07	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:0	34.08	2327	1.73	13.58	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.63	15.11	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:0	34.08	2327	1.73	13.57	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.63	15.1	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:1	34.08	2321	1.73	13.58	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.61	15.08	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:1	34.08	2317	1.73	13.57	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.59	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:1	34.08	2308	1.73	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.57	15	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:1	34.08	2308	1.73	13.61	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.56	14.96	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:51:1	34.08	2311	1.73	13.6	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.55	14.93	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:1	34.08	2311	1.73	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.57	14.89	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:1	34.08	2315	1.73	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.57	14.78	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:2	34.08	2314	1.73	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.58	14.7	1	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:2	34.08	2307	1.73	13.56	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.6	14.65	1	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:2	34.08	2306	1.73	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.57	14.59	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:2	34.08	2309	1.73	13.59	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.57	14.55	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:2	34.08	2318	1.74	13.58	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.56	14.48	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:2	34.08	2318	1.74	13.58	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.57	14.47	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:3	34.08	2317	1.74	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.54	14.43	0.98	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:3	34.08	2316	1.74	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.57	14.44	0.98	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:3	34.08	2308	1.74	13.58	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.6	14.45	0.98	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:3	34.08	2308	1.74	13.58	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.59	14.48	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:3	34.08	2318	1.74	13.59	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.59	14.51	0.99	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:3	34.08	2307	1.73	13.59	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.56	14.54	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:4	34.08	2311	1.73	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.54	14.59	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:4	34.08	2311	1.73	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.54	14.63	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:4	34.08	2308	1.73	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.51	14.68	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:4	34.08	2321	1.73	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.52	14.71	1	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:4	34.08	2324	1.73	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.53	14.74	1	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:4	34.08	2324	1.73	13.59	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.52	14.76	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:4	34.08	2339	1.73	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.53	14.79	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:5	34.08	2318	1.73	13.57	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.54	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:5	34.08	2318	1.73	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.52	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:51:5	34.08	2313	1.73	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.51	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:51:5	34.08	2312	1.73	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.52	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:51:5	34.08	2312	1.74	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.5	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:51:5	34.08	2311	1.74	13.6	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.52	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:51:6	34.08	2316	1.74	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.52	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:6	34.08	2324	1.74	13.6	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.52	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:6	34.08	2318	1.74	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.57	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:6	34.08	2332	1.74	13.57	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.55	14.83	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:6	34.08	2332	1.74	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.53	14.83	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:6	34.08	2325	1.74	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.54	14.87	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:6	34.08	2336	1.74	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.53	14.89	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:7	34.08	2316	1.74	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.5	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:7	34.08	2314	1.74	13.59	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.52	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:7	34.08	2308	1.74	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.55	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:7	34.08	2309	1.74	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.54	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:7	34.08	2309	1.74	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.54	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:7	34.08	2312	1.74	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.58	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:8	34.08	2317	1.74	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.55	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:8	34.08	2318	1.74	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.56	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:8	34.08	2318	1.74	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.56	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:8	34.08	2321	1.74	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.55	15.05	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:8	34.08	2327	1.74	13.58	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.52	15.03	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:8	34.08	2327	1.74	13.6	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.51	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:9	34.08	2328	1.74	13.6	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.52	14.99	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:9	34.08	2360	1.74	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.54	14.98	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:9	34.08	2340	1.74	13.59	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.54	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:9	34.08	2317	1.74	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.54	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:9	34.08	2314	1.74	13.58	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.51	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:9	34.08	2296	1.74	13.57	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.52	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:51:9	34.08	2311	1.74	13.56	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.53	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:0	34.08	2315	1.74	13.55	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.5	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:0	34.08	2318	1.74	13.56	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.52	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:0	34.08	2319	1.74	13.57	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.54	14.81	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:0	34.08	2316	1.74	13.56	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.52	14.83	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:52:0	34.08	2317	1.74	13.59	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.51	14.85	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:0	34.08	2316	1.74	13.58	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.52	14.88	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:1	34.08	2317	1.74	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.53	14.92	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:1	34.08	2320	1.74	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.5	14.95	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:1	34.08	2320	1.74	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.52	14.98	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:1	34.08	2324	1.74	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.52	15.01	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:1	34.08	2328	1.74	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.5	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:1	34.08	2329	1.74	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.52	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:1	34.08	2330	1.74	13.58	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.51	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:2	34.08	2330	1.74	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.5	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:2	34.08	2327	1.74	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.52	15	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:2	34.08	2327	1.74	13.58	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.5	15.01	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:2	34.08	2339	1.74	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.48	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:2	34.08	2321	1.74	13.57	98	192	Off Idle	76	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.52	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:2	34.08	2320	1.74	13.57	98	192	Off Idle	76	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.52	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:3	34.08	2320	1.74	13.58	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.52	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:3	34.08	2306	1.74	13.58	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.5	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:3	34.08	2322	1.74	13.58	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.47	14.99	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:3	34.08	2322	1.74	13.59	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.42	14.98	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:3	34.08	2322	1.75	13.58	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.44	14.96	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:3	34.08	2324	1.75	13.58	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.43	14.95	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:4	34.08	2324	1.75	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.44	14.91	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:4	34.08	2322	1.75	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.44	14.89	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:4	34.08	2325	1.75	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.43	14.89	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:4	34.08	2321	1.75	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.46	14.9	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:4	34.08	2320	1.75	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.45	14.9	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:4	34.08	2319	1.75	13.57	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.44	14.89	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:4	34.08	2319	1.75	13.57	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.46	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:5	34.08	2319	1.75	13.58	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.45	14.87	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:5	34.08	2320	1.75	13.58	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.44	14.87	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:5	34.08	2321	1.75	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.45	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:5	34.08	2322	1.76	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.44	14.9	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:5	34.08	2329	1.76	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.45	14.91	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:5	34.08	2330	1.76	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.46	14.9	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:6	34.08	2346	1.76	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.47	14.93	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:6	34.08	2324	1.76	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.44	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:6	34.08	2322	1.76	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.45	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:6	34.08	2318	1.76	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.47	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:6	34.08	2301	1.76	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.43	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:6	34.08	2312	1.76	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.42	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:6	34.08	2322	1.76	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.44	15.07	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:7	34.08	2321	1.76	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.46	15.08	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:7	34.08	2321	1.76	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.43	15.09	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:7	34.08	2317	1.76	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.44	15.09	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:7	34.08	2317	1.76	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.41	15.08	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:7	34.08	2317	1.76	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.39	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:52:7	34.08	2320	1.76	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.41	15.02	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:8	34.08	2326	1.76	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.35	15	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:8	34.08	2339	1.76	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.35	14.97	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:8	34.08	2339	1.77	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.37	14.95	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:8	34.08	2343	1.77	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.34	14.93	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:8	34.08	2361	1.77	13.6	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.31	14.89	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:8	34.08	2352	1.77	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.32	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:9	34.08	2338	1.77	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.3	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:9	34.08	2325	1.77	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.28	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:9	34.08	2303	1.77	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.28	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:9	34.08	2311	1.78	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.25	14.79	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:52:9	34.08	2317	1.78	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.23	14.79	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:52:9	34.08	2319	1.78	13.57	98	192	Off Idle	76	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.26	14.79	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:52:9	34.08	2319	1.78	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.25	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:0	34.08	2314	1.78	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.26	14.81	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:0	34.08	2317	1.78	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.25	14.87	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:53:0	34.08	2327	1.79	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.26	14.9	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:0	34.08	2330	1.79	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.28	14.94	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:0	34.08	2333	1.79	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.28	14.97	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:0	34.08	2333	1.79	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.27	14.99	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:1	34.08	2338	1.79	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.29	15.02	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:1	34.08	2337	1.79	13.58	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.3	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:1	34.08	2336	1.79	13.59	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.28	15.08	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:1	34.08	2343	1.79	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.28	15.1	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:1	34.08	2327	1.79	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.3	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:1	34.08	2324	1.79	13.59	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.26	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:1	34.08	2324	1.8	13.59	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.27	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:2	34.08	2314	1.8	13.58	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.28	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:2	34.08	2325	1.8	13.59	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.25	15.06	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:2	34.08	2328	1.8	13.58	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.24	15.06	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:2	34.08	2328	1.8	13.57	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.27	15.05	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:2	34.08	2328	1.8	13.56	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.25	15.03	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:2	34.08	2323	1.8	13.58	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.25	15.01	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:3	34.08	2323	1.8	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.28	15	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:53:3	34.08	2322	1.8	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.28	14.98	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:53:3	34.08	2323	1.8	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.26	14.96	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:3	34.08	2322	1.8	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.28	14.94	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:3	34.08	2326	1.8	13.59	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.27	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:3	34.08	2334	1.8	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.25	14.86	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:4	34.08	2334	1.8	13.58	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.28	14.85	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:4	34.08	2336	1.8	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.25	14.84	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:4	34.08	2334	1.8	13.58	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.26	14.84	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:4	34.08	2327	1.8	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.28	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:4	34.08	2327	1.8	13.57	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.26	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:4	34.08	2322	1.8	13.59	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.26	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:4	34.08	2326	1.8	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.25	14.83	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:53:5	34.08	2326	1.8	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.24	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:5	34.08	2328	1.8	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.21	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:5	34.08	2336	1.8	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.21	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:53:5	34.08	2328	1.8	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.22	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:5	34.08	2340	1.8	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.21	14.9	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:5	34.08	2339	1.79	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.21	14.93	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:6	34.08	2339	1.79	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.24	14.96	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:6	34.08	2328	1.79	13.59	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.27	14.98	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:6	34.08	2324	1.79	13.59	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.28	15.02	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:6	34.08	2324	1.79	13.6	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.29	15.03	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:6	34.08	2318	1.79	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.27	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:6	34.08	2313	1.79	13.59	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.27	15.06	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:6	34.08	2320	1.79	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.21	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:7	34.08	2326	1.79	13.6	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.21	15.03	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:7	34.08	2326	1.79	13.61	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.2	15.03	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:7	34.08	2331	1.79	13.6	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.2	15.04	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:7	34.08	2332	1.79	13.61	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.16	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:53:7	34.08	2331	1.79	13.61	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.17	15.03	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:53:7	34.08	2336	1.79	13.6	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.18	15.01	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:8	34.08	2344	1.79	13.6	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.21	15	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:8	34.08	2357	1.79	13.61	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.17	14.98	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:8	34.08	2357	1.79	13.6	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.21	14.98	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:8	34.08	2336	1.79	13.59	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.22	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:8	34.08	2332	1.79	13.59	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.21	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:53:8	34.08	2330	1.79	13.57	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.21	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:9	34.08	2310	1.79	13.58	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.22	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:9	34.08	2326	1.8	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.19	14.86	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:9	34.08	2326	1.8	13.58	98	192	Off Idle	75	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.18	14.85	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:9	34.08	2326	1.8	13.57	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.19	14.84	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:9	34.08	2325	1.8	13.59	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.18	14.82	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:9	34.08	2334	1.8	13.59	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.15	14.7	1	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:53:9	34.08	2326	1.8	13.58	98	192	Off Idle	75	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.18	14.68	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:0	34.08	2330	1.8	13.58	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.16	14.68	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:0	34.08	2330	1.8	13.6	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.15	14.7	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:0	34.08	2332	1.8	13.58	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.16	14.72	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:0	34.08	2333	1.8	13.58	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.19	14.73	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:0	34.08	2331	1.8	13.58	97	192	Off Idle	75.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.21	14.76	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:0	34.08	2332	1.8	13.57	97	192	Off Idle	75.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.22	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:1	34.08	2334	1.8	13.57	97	192	Off Idle	75.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.22	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:1	34.08	2332	1.8	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.24	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:1	34.08	2332	1.8	13.58	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.27	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:1	34.08	2332	1.8	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.27	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:1	34.08	2327	1.8	13.59	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.28	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:54:1	34.08	2321	1.8	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.26	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:1	34.08	2322	1.8	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.23	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:2	34.08	2327	1.8	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.25	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:2	34.08	2327	1.8	13.59	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.22	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:2	34.08	2330	1.8	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.21	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:2	34.08	2341	1.8	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.24	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:2	34.08	2344	1.8	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.26	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:2	34.08	2346	1.8	13.59	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.25	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:3	34.08	2348	1.79	13.59	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.26	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:3	34.08	2344	1.79	13.59	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.23	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:3	34.08	2344	1.79	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.23	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:3	34.08	2342	1.8	13.56	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.21	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:3	34.08	2336	1.8	13.58	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.21	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:3	34.08	2332	1.8	13.57	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.2	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:4	34.08	2332	1.8	13.58	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.23	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:4	34.08	2328	1.8	13.59	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.21	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:4	34.08	2329	1.8	13.59	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.24	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:4	34.08	2347	1.8	13.57	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.21	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:54:4	34.08	2340	1.8	13.58	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.24	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:54:4	34.08	2331	1.8	13.58	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.23	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:54:4	34.08	2332	1.8	13.58	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.21	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:5	34.08	2332	1.8	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.23	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:5	34.08	2326	1.8	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.21	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:5	34.08	2335	1.8	13.6	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.19	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:5	34.08	2334	1.8	13.6	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.21	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:5	34.08	2334	1.8	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.21	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:5	34.08	2335	1.8	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.22	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:6	34.08	2331	1.8	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.21	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:6	34.08	2340	1.8	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.21	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:6	34.08	2339	1.8	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.2	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:6	34.08	2337	1.8	13.6	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.19	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:6	34.08	2338	1.8	13.59	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.21	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:54:6	34.08	2336	1.8	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.2	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:54:6	34.08	2337	1.8	13.6	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.19	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:54:7	34.08	2337	1.8	13.6	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.21	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:54:7	34.08	2333	1.8	13.59	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.22	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:7	34.08	2336	1.8	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.2	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:7	34.08	2336	1.8	13.61	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.21	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:7	34.08	2337	1.8	13.59	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.24	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:54:7	34.08	2326	1.8	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.23	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:8	34.08	2336	1.8	13.59	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.21	14.93	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:8	34.08	2349	1.8	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.24	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:8	34.08	2349	1.8	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.21	14.84	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:8	34.08	2346	1.8	13.6	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.22	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:8	34.08	2346	1.8	13.58	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.24	14.81	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:8	34.08	2328	1.8	13.58	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.23	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:9	34.08	2328	1.8	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.21	14.78	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:54:9	34.08	2328	1.8	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.27	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:54:9	34.08	2326	1.8	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.24	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:21:54:9	34.08	2328	1.8	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.23	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:9	34.08	2330	1.8	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.23	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:9	34.08	2342	1.8	13.57	98	192	Off Idle	76	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.22	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:54:9	34.08	2346	1.8	13.57	98	192	Off Idle	76	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.22	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:0	34.08	2346	1.8	13.57	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.27	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:0	34.08	2342	1.8	13.57	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.28	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:0	34.08	2338	1.8	13.58	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.3	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:0	34.08	2330	1.8	13.58	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.28	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:0	34.08	2320	1.8	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.3	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:0	34.08	2323	1.8	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.27	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:1	34.08	2323	1.8	13.59	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.23	15.04	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:1	34.08	2324	1.8	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.23	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:1	34.08	2336	1.8	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.21	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:1	34.08	2333	1.79	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.22	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:1	34.08	2336	1.79	13.58	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.23	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:1	34.08	2345	1.79	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.24	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:1	34.08	2348	1.79	13.6	98	192	Off Idle	76.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.25	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:2	34.08	2366	1.79	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.28	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:2	34.08	2356	1.79	13.6	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.28	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:2	34.08	2344	1.79	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.31	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:2	34.08	2341	1.79	13.59	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.31	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:2	34.08	2332	1.79	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.31	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:2	34.08	2338	1.79	13.58	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.34	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:3	34.08	2336	1.79	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.32	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:3	34.08	2359	1.79	13.57	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.31	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:3	34.08	2350	1.79	13.57	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.33	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:3	34.08	2343	1.79	13.58	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.31	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:3	34.08	2343	1.79	13.58	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.3	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:3	34.08	2343	1.79	13.56	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.32	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:4	34.08	2337	1.79	13.58	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.29	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:4	34.08	2344	1.79	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.29	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:4	34.08	2344	1.79	13.58	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.31	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:4	34.08	2336	1.79	13.58	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.32	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:4	34.08	2350	1.79	13.58	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.31	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:4	34.08	2341	1.79	13.58	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.31	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:4	34.08	2329	1.79	13.58	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.3	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:5	34.08	2328	1.79	13.58	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.32	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:5	34.08	2298	1.79	13.56	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.36	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:5	34.08	2318	1.79	13.58	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.32	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:5	34.08	2343	1.79	13.58	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.34	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:5	34.08	2349	1.79	13.59	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.39	15.05	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:5	34.08	2349	1.79	13.58	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.4	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:6	34.08	2349	1.78	13.58	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.38	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:6	34.08	2347	1.78	13.57	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.37	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:6	34.08	2345	1.78	13.57	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.42	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:6	34.08	2326	1.78	13.58	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.41	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:6	34.08	2330	1.78	13.58	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.42	14.96	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:6	34.08	2324	1.78	13.59	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.42	14.93	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:55:6	34.08	2324	1.78	13.59	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.43	14.91	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:7	34.08	2328	1.78	13.59	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.41	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:7	34.08	2331	1.77	13.58	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.43	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:7	34.08	2334	1.77	13.57	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.43	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:7	34.08	2339	1.77	13.57	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.41	14.79	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:7	34.08	2350	1.77	13.58	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.44	14.78	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:7	34.08	2368	1.77	13.58	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.44	14.79	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:8	34.08	2360	1.77	13.59	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.43	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:8	34.08	2350	1.77	13.61	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.43	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:8	34.08	2350	1.77	13.6	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.45	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:8	34.08	2347	1.77	13.59	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.43	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:55:8	34.08	2358	1.77	13.6	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.44	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:8	34.08	2348	1.77	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.43	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:9	34.08	2336	1.77	13.6	98	192	Off Idle	75	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.42	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:9	34.08	2332	1.77	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.41	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:9	34.08	2321	1.76	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.41	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:9	34.08	2329	1.76	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.4	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:9	34.08	2340	1.76	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.42	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:9	34.08	2340	1.76	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.44	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:55:9	34.08	2344	1.76	13.59	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.47	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:0	34.08	2346	1.76	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.47	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:0	34.08	2349	1.76	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.49	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:0	34.08	2349	1.76	13.58	98	192	Off Idle	75	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.52	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:0	34.08	2344	1.76	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.51	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:0	34.08	2338	1.76	13.6	98	192	Off Idle	75	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.49	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:0	34.08	2327	1.76	13.59	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.46	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:1	34.08	2327	1.76	13.59	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.42	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:1	34.08	2335	1.76	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.42	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:1	34.08	2335	1.76	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.42	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:1	34.08	2320	1.76	13.59	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.41	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:1	34.08	2346	1.76	13.6	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.44	14.96	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:1	34.08	2347	1.76	13.6	98	192	Off Idle	75.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.48	14.95	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:1	34.08	2364	1.76	13.6	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.44	14.91	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:2	34.08	2346	1.76	13.6	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.43	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:2	34.08	2344	1.76	13.6	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.46	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:2	34.08	2344	1.76	13.6	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.45	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:2	34.08	2340	1.76	13.6	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.41	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:2	34.08	2320	1.76	13.59	98	192	Off Idle	75.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.41	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:2	34.08	2328	1.76	13.59	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.43	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:3	34.08	2335	1.77	13.59	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.43	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:3	34.08	2339	1.77	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.43	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:3	34.08	2340	1.77	13.59	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.47	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:3	34.08	2339	1.77	13.59	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.46	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:3	34.08	2339	1.77	13.59	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.45	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:3	34.08	2344	1.77	13.58	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.45	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:4	34.08	2331	1.77	13.6	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.42	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:4	34.08	2331	1.77	13.58	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.46	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:4	34.08	2352	1.77	13.58	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.47	15.07	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:4	34.08	2354	1.77	13.58	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.47	15.07	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:4	34.08	2354	1.77	13.59	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.46	15.07	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:4	34.08	2372	1.77	13.61	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.48	15.08	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:4	34.08	2347	1.77	13.61	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.48	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:5	34.08	2339	1.77	13.59	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.46	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:5	34.08	2338	1.77	13.61	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.42	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:5	34.08	2341	1.77	13.61	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.42	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:5	34.08	2331	1.77	13.6	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.44	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:5	34.08	2333	1.77	13.58	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.43	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:5	34.08	2334	1.77	13.6	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.41	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:56:6	34.08	2330	1.77	13.6	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.42	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:6	34.08	2342	1.77	13.59	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.41	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:6	34.08	2342	1.77	13.6	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.41	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:6	34.08	2342	1.77	13.6	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.44	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:6	34.08	2343	1.77	13.6	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.45	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:6	34.08	2343	1.77	13.58	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.46	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:6	34.08	2350	1.77	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.45	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:7	34.08	2338	1.77	13.57	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.45	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:7	34.08	2338	1.77	13.57	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.41	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:7	34.08	2337	1.77	13.59	98	192	Off Idle	75	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.41	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:7	34.08	2331	1.77	13.57	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.44	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:7	34.08	2335	1.77	13.56	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.43	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:7	34.08	2337	1.77	13.58	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.41	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:8	34.08	2345	1.77	13.6	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.43	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:8	34.08	2389	1.77	13.58	98	192	Off Idle	74.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.45	14.82	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:8	34.08	2389	1.77	13.6	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.44	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:8	34.08	2358	1.77	13.6	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.48	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:21:56:8	34.08	2358	1.77	13.59	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.49	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:8	34.08	2337	1.77	13.6	98	192	Off Idle	74.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.5	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:9	34.08	2343	1.77	13.59	98	192	Off Idle	74.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.54	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:9	34.08	2343	1.77	13.59	98	192	Off Idle	74.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.54	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:9	34.08	2337	1.76	13.6	98	192	Off Idle	74.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.55	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:9	34.08	2337	1.76	13.6	98	192	Off Idle	74.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.55	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:9	34.08	2331	1.75	13.61	98	192	Off Idle	74.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.59	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:9	34.08	2332	1.75	13.62	98	192	Off Idle	74.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.61	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:56:9	34.08	2335	1.75	13.6	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.22	Rich	1	14.6	-8.67	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:21:57:0	34.08	2341	1.74	13.58	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.7	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:57:0	34.08	2342	1.73	13.58	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.74	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:21:57:0	34.08	2345	1.73	13.57	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.77	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:0	34.08	2347	1.72	13.58	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.85	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:0	34.08	2347	1.71	13.59	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.86	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:0	34.08	2346	1.71	13.57	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.89	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:1	34.08	2339	1.7	13.57	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.91	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:1	34.08	2334	1.7	13.59	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.91	15.15	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:1	34.08	2334	1.69	13.59	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.95	15.15	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:1	34.08	2327	1.68	13.57	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.01	15.14	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:1	34.08	2324	1.67	13.59	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.04	15.13	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:1	34.08	2334	1.66	13.6	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.08	15.15	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:21:57:1	34.08	2334	1.65	13.58	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.14	15.14	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:2	34.08	2333	1.64	13.57	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.16	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:2	34.08	2334	1.64	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.19	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:2	34.08	2334	1.63	13.57	98	192	Off Idle	76	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.24	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:2	34.08	2338	1.62	13.57	98	192	Off Idle	76	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.25	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:2	34.08	2343	1.62	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.27	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:2	34.08	2346	1.61	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.33	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:3	34.08	2336	1.61	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.35	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:3	34.08	2347	1.6	13.59	97	192	Off Idle	75.8	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.36	14.9	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:3	34.08	2350	1.59	13.59	97	192	Off Idle	75.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.41	14.84	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:3	34.08	2350	1.58	13.59	97	192	Off Idle	75.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.45	14.77	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:3	34.08	2359	1.58	13.6	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.46	14.73	1	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:3	35.45	2350	1.57	13.61	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.46	14.71	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:4	35.45	2332	1.57	13.59	98	192	Off Idle	74.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.51	14.68	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:4	35.45	2332	1.56	13.59	98	192	Off Idle	74.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.52	14.68	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:4	35.45	2326	1.55	13.6	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.56	14.7	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:4	35.45	2328	1.55	13.58	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.56	14.71	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:4	35.45	2326	1.54	13.6	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.58	14.74	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:4	35.45	2315	1.54	13.6	98	192	Off Idle	74.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.61	14.77	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:4	35.45	2324	1.53	13.6	98	192	Off Idle	74.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.62	14.79	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:57:5	35.45	2321	1.53	13.6	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.61	14.78	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:5	35.45	2321	1.52	13.6	98	192	Off Idle	74.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.63	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:5	35.45	2316	1.52	13.6	98	192	Off Idle	75.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.65	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:5	35.45	2329	1.51	13.6	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.65	14.82	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:5	35.45	2330	1.51	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.67	14.83	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:5	35.45	2333	1.5	13.6	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.71	14.85	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:21:57:6	35.45	2337	1.5	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.75	14.88	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:6	35.45	2341	1.49	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.75	14.89	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:6	35.45	2341	1.49	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.76	14.92	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:6	35.45	2346	1.49	13.6	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.77	14.95	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:6	35.45	2345	1.49	13.6	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.76	15	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:6	35.45	2344	1.48	13.61	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.75	15.03	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:6	35.45	2344	1.48	13.61	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.77	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:7	35.45	2344	1.48	13.61	98	192	Off Idle	75	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.76	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:7	35.45	2344	1.48	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.77	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:7	35.45	2341	1.47	13.59	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.78	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:7	35.45	2334	1.47	13.6	98	192	Off Idle	75	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.79	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:7	35.45	2333	1.47	13.58	98	192	Off Idle	75	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.82	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:7	35.45	2331	1.47	13.57	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.86	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:8	35.45	2328	1.47	13.58	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.86	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:8	35.45	2326	1.47	13.59	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.85	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:8	35.45	2326	1.47	13.59	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.85	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:8	35.45	2322	1.46	13.61	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.83	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:8	35.45	2298	1.46	13.62	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.82	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:57:8	35.45	2315	1.46	13.61	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.86	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:57:9	35.45	2314	1.46	13.6	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.85	15.04	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:9	35.45	2303	1.46	13.6	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.82	15.04	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:9	35.45	2307	1.46	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.84	15.06	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:9	35.45	2307	1.46	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.85	15.06	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:9	35.45	2310	1.46	13.59	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.82	15.05	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:9	35.45	2322	1.45	13.58	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.83	15.03	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:57:9	35.45	2333	1.45	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.84	15.01	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:0	35.45	2333	1.45	13.6	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.85	14.98	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:0	35.45	2343	1.45	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.87	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:0	35.45	2345	1.45	13.59	98	192	Off Idle	76.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.87	14.96	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:0	35.45	2346	1.45	13.6	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.87	14.93	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:0	35.45	2338	1.45	13.61	98	192	Off Idle	76	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.87	14.9	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:0	35.45	2348	1.45	13.61	97	192	Off Idle	75.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.89	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:1	35.45	2340	1.45	13.61	97	192	Off Idle	75.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.9	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:1	35.45	2340	1.45	13.6	97	192	Off Idle	75.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.92	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:1	35.45	2342	1.45	13.59	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.93	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:1	35.45	2342	1.45	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.92	14.83	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:1	35.45	2338	1.45	13.61	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.9	14.82	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:1	35.45	2326	1.45	13.6	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.89	14.81	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:1	35.45	2326	1.45	13.6	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.89	14.81	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:2	35.45	2326	1.45	13.6	97	192	Off Idle	75.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.87	14.8	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:2	35.45	2322	1.45	13.59	97	192	Off Idle	75.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.89	14.8	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:2	35.45	2324	1.44	13.59	97	192	Off Idle	75.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.91	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:2	35.45	2322	1.44	13.61	98	192	Off Idle	75	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.93	14.81	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:2	35.45	2306	1.44	13.61	98	192	Off Idle	75.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.98	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:2	35.45	2314	1.43	13.59	98	192	Off Idle	75.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.01	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:3	35.45	2316	1.43	13.61	98	192	Off Idle	75.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.03	14.86	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:3	35.45	2316	1.42	13.6	98	192	Off Idle	75.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.06	14.9	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:58:3	35.45	2319	1.42	13.61	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.06	14.93	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:3	35.45	2324	1.41	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.1	14.96	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:3	35.45	2324	1.41	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.11	14.99	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:3	35.45	2326	1.41	13.6	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.17	Rich	1	14.6	-10.12	15.01	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:4	35.45	2364	1.4	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.25	Rich	1	14.6	-10.15	15.03	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:58:4	35.45	2364	1.39	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.28	Rich	1	14.6	-10.17	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:4	35.45	2326	1.38	13.61	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.15	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:4	35.45	2325	1.38	13.61	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-10.19	15.08	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:4	35.45	2324	1.37	13.59	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.19	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:4	35.45	2302	1.37	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.19	15.07	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:4	35.45	2320	1.36	13.59	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.22	15.08	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:5	35.45	2318	1.35	13.58	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.21	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:5	35.45	2316	1.35	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.19	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:5	35.45	2306	1.34	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.22	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:5	35.45	2323	1.34	13.59	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.24	15.07	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:5	35.45	2323	1.34	13.59	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.25	15.06	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:5	35.45	2322	1.34	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.25	15.06	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:6	35.45	2328	1.33	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.27	15.04	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:6	35.45	2328	1.33	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.28	15.04	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:6	35.45	2328	1.33	13.61	98	192	Off Idle	76	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.25	15.07	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:6	35.45	2328	1.33	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.29	15.06	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:6	35.45	2324	1.33	13.59	97	192	Off Idle	76	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.29	15.05	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:6	35.45	2323	1.33	13.59	97	192	Off Idle	76	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.27	15.02	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:6	35.45	2323	1.33	13.58	97	192	Off Idle	76	0	2	132	944 Turbo	0.54	Lean	1	14.6	-10.28	14.99	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:7	35.45	2320	1.33	13.58	98	192	Off Idle	76	0	2	132	944 Turbo	0.48	Lean	1	14.6	-10.29	14.96	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:7	35.45	2321	1.33	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.27	14.94	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:7	35.45	2321	1.33	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.28	14.92	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:7	35.45	2322	1.33	13.61	98	192	Off Idle	75.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.29	14.9	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:7	35.45	2320	1.33	13.6	98	192	Off Idle	76	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.3	14.86	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:7	35.45	2318	1.33	13.59	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.3	14.79	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:8	35.45	2331	1.33	13.6	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.29	14.74	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:8	35.45	2308	1.33	13.59	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.3	14.74	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:8	35.45	2305	1.33	13.58	98	192	Off Idle	75.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.29	14.73	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:8	35.45	2306	1.33	13.59	98	192	Off Idle	76	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.29	14.73	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:8	35.45	2300	1.33	13.6	98	192	Off Idle	76.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.31	14.73	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:8	35.45	2312	1.33	13.61	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.33	14.72	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:9	35.45	2312	1.33	13.61	98	192	Off Idle	76.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.32	14.74	1	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:9	35.45	2316	1.33	13.61	97	192	Off Idle	76.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.33	14.75	1	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:9	35.45	2316	1.33	13.61	97	192	Off Idle	76.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.33	14.75	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:9	35.45	2318	1.33	13.61	97	192	Off Idle	76.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.31	14.8	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:9	35.45	2318	1.33	13.6	97	192	Off Idle	76.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.34	14.81	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:58:9	35.45	2314	1.33	13.6	97	192	Off Idle	76.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.34	14.81	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:58:9	35.45	2314	1.32	13.6	97	192	Off Idle	76.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.3	14.8	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:59:0	35.45	2310	1.33	13.6	97	192	Off Idle	76.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.28	14.82	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:59:0	35.45	2307	1.33	13.58	97	192	Off Idle	76.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.29	14.83	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:59:0	35.45	2306	1.33	13.59	97	192	Off Idle	76.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.29	14.84	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:21:59:0	35.45	2306	1.33	13.59	97	192	Off Idle	76.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.29	14.85	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:0	35.45	2310	1.33	13.6	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.29	14.86	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:0	35.45	2310	1.33	13.6	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.29	14.86	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:1	35.45	2316	1.33	13.61	98	192	Off Idle	76.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.26	14.89	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:1	35.45	2318	1.33	13.61	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.27	14.91	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:1	35.45	2314	1.33	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.28	14.95	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:1	35.45	2305	1.33	13.59	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.24	14.96	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:1	35.45	2304	1.33	13.6	98	192	Off Idle	76.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.26	14.97	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:1	35.45	2314	1.33	13.59	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.26	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:1	35.45	2293	1.33	13.6	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.24	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:2	35.45	2294	1.33	13.61	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.22	15	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:2	35.45	2300	1.33	13.61	98	192	Off Idle	77	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.24	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:2	35.45	2293	1.34	13.6	98	192	Off Idle	77.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.23	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:2	35.45	2293	1.34	13.61	98	192	Off Idle	77.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10.21	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:2	35.45	2320	1.34	13.6	97	192	Off Idle	77	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.22	15	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:2	35.45	2322	1.34	13.61	97	192	Off Idle	76.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.19	14.98	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:3	35.45	2344	1.35	13.61	98	192	Off Idle	76.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.18	14.96	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:21:59:3	35.45	2334	1.35	13.6	98	192	Off Idle	76.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-10.19	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:3	35.45	2321	1.35	13.61	98	192	Off Idle	76.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.19	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:3	35.45	2318	1.35	13.59	97	192	Off Idle	76.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.2	14.9	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:3	35.45	2299	1.36	13.58	97	192	Off Idle	76.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.21	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:3	35.45	2299	1.36	13.57	97	192	Off Idle	76.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.19	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:4	35.45	2313	1.36	13.59	97	192	Off Idle	76.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.17	14.8	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:4	35.45	2313	1.37	13.57	97	192	Off Idle	76.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.14	14.8	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:4	35.45	2312	1.37	13.58	97	192	Off Idle	76.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.09	14.81	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:4	35.45	2310	1.37	13.58	97	192	Off Idle	76.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.1	14.81	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:4	35.45	2309	1.37	13.58	97	192	Off Idle	76.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.08	14.81	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:4	35.45	2309	1.37	13.58	97	192	Off Idle	76.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.07	14.82	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:4	35.45	2306	1.38	13.59	97	192	Off Idle	76.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.03	14.81	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:5	35.45	2302	1.38	13.59	97	192	Off Idle	76.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.05	14.81	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:5	35.45	2303	1.38	13.59	97	192	Off Idle	76.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-10.05	14.81	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:5	35.45	2302	1.38	13.6	97	192	Off Idle	76.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-10.02	14.81	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:5	35.45	2302	1.38	13.61	97	192	Off Idle	76.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-10.04	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:5	35.45	2302	1.38	13.6	97	192	Off Idle	77	0	2	132	944 Turbo	0.53	Lean	1	14.6	-10.07	14.82	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:5	35.45	2299	1.39	13.59	97	192	Off Idle	77	0	2	132	944 Turbo	0.62	Lean	1	14.6	-10.04	14.82	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:6	35.45	2296	1.39	13.6	97	192	Off Idle	77.1	0	2	132	944 Turbo	0.67	Lean	1	14.6	-10.02	14.82	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:6	35.45	2304	1.39	13.59	97	192	Off Idle	77.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.04	14.84	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:6	35.45	2295	1.39	13.59	97	192	Off Idle	77.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.03	14.86	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:6	35.45	2292	1.39	13.6	97	192	Off Idle	77.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.03	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:6	35.45	2291	1.39	13.6	97	192	Off Idle	77.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.04	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:6	35.45	2290	1.39	13.59	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.06	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:6	35.45	2290	1.39	13.6	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.07	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:7	35.45	2292	1.39	13.59	98	192	Off Idle	77.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.08	14.96	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:7	35.45	2312	1.39	13.6	98	192	Off Idle	77.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.08	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:7	35.45	2304	1.39	13.6	98	192	Off Idle	77.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.11	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:7	35.45	2300	1.39	13.59	97	192	Off Idle	77.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.09	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:7	35.45	2302	1.38	13.59	97	192	Off Idle	77.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.09	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:7	35.45	2296	1.38	13.59	97	192	Off Idle	77.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.08	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:8	35.45	2296	1.38	13.58	97	192	Off Idle	77.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.1	14.96	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:8	35.45	2297	1.38	13.59	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.08	14.95	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:8	35.45	2302	1.38	13.59	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.07	14.94	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:8	35.45	2306	1.38	13.6	97	192	Off Idle	77.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.08	14.93	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:8	35.45	2306	1.38	13.6	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.08	14.9	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:8	35.45	2311	1.38	13.6	98	192	Off Idle	77.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-10.07	14.84	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:9	35.45	2314	1.38	13.59	98	192	Off Idle	77.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.08	14.81	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:9	35.45	2314	1.38	13.59	98	192	Off Idle	77.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.08	14.77	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:9	35.45	2307	1.38	13.6	97	192	Off Idle	77.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.07	14.75	1	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:21:59:9	35.45	2303	1.38	13.6	97	192	Off Idle	77.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.08	14.74	1	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:9	35.45	2303	1.38	13.58	97	192	Off Idle	77.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.08	14.72	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:9	35.45	2304	1.38	13.59	97	192	Off Idle	77.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.07	14.71	1	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:21:59:9	35.45	2310	1.38	13.59	97	192	Off Idle	77.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.07	14.73	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:0	35.45	2293	1.38	13.58	97	192	Off Idle	77.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.08	14.73	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:0	35.45	2295	1.38	13.57	98	192	Off Idle	77.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.08	14.75	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:0	35.45	2291	1.38	13.58	98	192	Off Idle	77.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.04	14.76	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:0	35.45	2287	1.38	13.59	98	192	Off Idle	76.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.03	14.78	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:0	35.45	2287	1.38	13.57	98	192	Off Idle	76.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.02	14.8	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:0	35.45	2286	1.38	13.57	98	192	Off Idle	77.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.01	14.8	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:1	35.45	2285	1.38	13.58	98	192	Off Idle	77.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.99	14.8	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:1	35.45	2284	1.38	13.57	98	192	Off Idle	77.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.98	14.81	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:1	35.45	2282	1.38	13.56	98	192	Off Idle	77.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.98	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:1	35.45	2282	1.38	13.58	98	192	Off Idle	77.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.97	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:1	35.45	2282	1.38	13.58	98	192	Off Idle	77.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.99	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:1	35.45	2282	1.38	13.58	98	192	Off Idle	78	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.01	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:1	35.45	2282	1.38	13.57	98	192	Off Idle	78	0	2	132	944 Turbo	0.45	Lean	1	14.6	-10.01	14.9	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:2	35.45	2286	1.38	13.6	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.98	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:00:2	35.45	2292	1.38	13.59	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.61	Lean	1	14.6	-10.02	14.95	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:2	35.45	2296	1.38	13.58	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.02	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:2	35.45	2296	1.38	13.58	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.03	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:2	35.45	2302	1.38	13.59	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.07	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:2	35.45	2304	1.38	13.57	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.06	15.06	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:3	35.45	2313	1.38	13.58	97	192	Off Idle	78	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.07	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:3	35.45	2304	1.38	13.59	97	192	Off Idle	78	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.05	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:3	35.45	2296	1.38	13.59	97	192	Off Idle	77.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.03	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:3	35.45	2294	1.38	13.6	97	192	Off Idle	77.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.02	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:3	35.45	2294	1.38	13.61	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.01	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:3	35.45	2282	1.38	13.6	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.02	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:4	35.45	2288	1.38	13.59	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.05	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:4	35.45	2288	1.38	13.59	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:4	35.45	2284	1.38	13.58	98	192	Off Idle	77.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.01	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:4	35.45	2282	1.38	13.57	98	192	Off Idle	77.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.01	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:4	35.45	2280	1.38	13.58	98	192	Off Idle	77.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:4	35.45	2281	1.38	13.57	98	192	Off Idle	77.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.02	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:4	35.45	2282	1.38	13.56	98	192	Off Idle	77.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.04	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:5	35.45	2286	1.38	13.6	98	192	Off Idle	77.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:5	35.45	2288	1.38	13.58	98	192	Off Idle	78	0	2	132	944 Turbo	0.45	Rich	1	14.6	-10	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:5	35.45	2298	1.38	13.57	98	192	Off Idle	78.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-10.04	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:5	35.45	2294	1.38	13.57	97	192	Off Idle	78	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.01	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:5	35.45	2288	1.38	13.58	97	192	Off Idle	77.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10	14.8	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:5	35.45	2288	1.38	13.57	97	192	Off Idle	78	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.03	14.77	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:6	35.45	2288	1.38	13.57	97	192	Off Idle	78.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.04	14.76	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:6	35.45	2289	1.38	13.57	97	192	Off Idle	78.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.01	14.76	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:6	35.45	2290	1.38	13.57	97	192	Off Idle	78.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.02	14.76	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:6	35.45	2293	1.38	13.58	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.04	14.77	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:00:6	35.45	2290	1.38	13.58	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.06	14.78	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:6	35.45	2290	1.38	13.59	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.07	14.79	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:6	35.45	2290	1.38	13.6	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.07	14.79	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:7	35.45	2288	1.38	13.62	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.07	14.79	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:7	35.45	2288	1.38	13.61	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.06	14.79	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:7	35.45	2288	1.38	13.61	97	192	Off Idle	78.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.07	14.79	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:7	35.45	2286	1.38	13.61	97	192	Off Idle	78.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.08	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:7	35.45	2279	1.38	13.59	98	192	Off Idle	78	0	2	132	944 Turbo	0.32	Lean	1	14.6	-10.09	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:7	35.45	2281	1.38	13.59	98	192	Off Idle	78	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10.07	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:8	35.45	2280	1.38	13.6	98	192	Off Idle	78.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.06	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:8	35.45	2271	1.37	13.59	98	192	Off Idle	78.1	0	2	132	944 Turbo	0.52	Lean	1	14.6	-10.06	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:8	35.45	2271	1.37	13.58	98	192	Off Idle	78.1	0	2	132	944 Turbo	0.58	Lean	1	14.6	-10.03	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:8	35.45	2272	1.37	13.59	98	192	Off Idle	78.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.03	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:8	35.45	2271	1.37	13.57	98	192	Off Idle	78.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.04	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:8	35.45	2276	1.37	13.6	98	192	Off Idle	78.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.01	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:9	35.45	2280	1.37	13.6	98	192	Off Idle	78.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:9	35.45	2290	1.37	13.59	98	192	Off Idle	78.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.05	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:9	35.45	2291	1.37	13.6	98	192	Off Idle	78.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.04	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:9	35.45	2291	1.37	13.59	98	192	Off Idle	78.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.05	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:9	35.45	2291	1.37	13.58	98	192	Off Idle	78.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.07	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:9	35.45	2283	1.37	13.58	98	192	Off Idle	78.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.06	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:00:9	35.45	2283	1.37	13.58	98	192	Off Idle	78.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.08	15.09	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:0	35.45	2282	1.37	13.57	98	192	Off Idle	78.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-10.08	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:0	35.45	2282	1.37	13.6	98	192	Off Idle	78.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-10.06	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:0	35.45	2281	1.37	13.61	98	192	Off Idle	78.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-10.06	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:0	35.45	2281	1.37	13.59	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.07	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:0	35.45	2280	1.37	13.6	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.03	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:0	35.45	2277	1.37	13.61	98	192	Off Idle	78.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.02	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:1	35.45	2278	1.37	13.59	98	192	Off Idle	78.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.02	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:1	35.45	2278	1.37	13.6	98	192	Off Idle	78.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.02	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:01:1	35.45	2274	1.37	13.6	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.02	14.9	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:1	35.45	2274	1.37	13.59	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.03	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:1	35.45	2276	1.37	13.57	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.03	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:1	35.45	2274	1.37	13.58	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.99	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:1	35.45	2272	1.37	13.59	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:2	35.45	2274	1.37	13.59	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.98	14.8	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:2	35.45	2273	1.37	13.59	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.01	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:2	35.45	2269	1.37	13.59	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.98	14.79	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:2	35.45	2273	1.37	13.6	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.99	14.8	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:2	35.45	2273	1.37	13.59	97	192	Off Idle	78.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.01	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:2	35.45	2274	1.37	13.59	97	192	Off Idle	78.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:3	35.45	2275	1.37	13.6	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.98	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:3	35.45	2275	1.37	13.61	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.98	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:3	35.45	2280	1.37	13.6	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.98	14.91	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:3	35.45	2274	1.37	13.59	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.95	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:3	35.45	2274	1.37	13.59	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.02	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:3	35.45	2275	1.37	13.58	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.05	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:4	35.45	2274	1.37	13.58	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.05	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:4	35.45	2272	1.37	13.59	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.06	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:4	35.45	2272	1.37	13.59	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.08	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:4	35.45	2272	1.37	13.59	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.06	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:4	35.45	2271	1.37	13.6	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.04	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:4	35.45	2270	1.37	13.59	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.05	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:4	35.45	2270	1.37	13.58	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.04	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:5	35.45	2288	1.37	13.6	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.01	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:5	35.45	2275	1.37	13.58	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.04	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:5	35.45	2273	1.37	13.58	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:5	35.45	2274	1.37	13.59	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.98	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:5	35.45	2268	1.37	13.6	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.98	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:5	35.45	2274	1.37	13.59	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.01	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:6	35.45	2272	1.37	13.57	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.02	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:6	35.45	2267	1.37	13.57	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.05	14.91	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:6	35.45	2268	1.37	13.56	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-10.03	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:01:6	35.45	2276	1.37	13.57	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-10	14.81	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:6	35.45	2277	1.38	13.59	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.98	14.77	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:6	35.45	2277	1.38	13.6	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.96	14.74	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:6	35.45	2281	1.38	13.61	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.95	14.73	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:7	35.45	2285	1.38	13.61	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.93	14.72	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:7	35.45	2286	1.38	13.62	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.93	14.7	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:7	35.45	2286	1.39	13.59	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.93	14.69	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:7	35.45	2282	1.39	13.6	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.92	14.69	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:7	35.45	2282	1.39	13.61	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.9	14.71	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:7	35.45	2283	1.39	13.61	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.9	14.72	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:8	35.45	2282	1.4	13.61	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.9	14.73	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:8	35.45	2282	1.4	13.61	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.88	14.74	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:8	35.45	2280	1.4	13.6	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.88	14.75	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:8	35.45	2276	1.4	13.59	97	192	Off Idle	78.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.87	14.75	1	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:8	35.45	2287	1.41	13.6	97	192	Off Idle	78	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.87	14.77	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:8	35.45	2287	1.41	13.59	97	192	Off Idle	78	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.87	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:01:9	35.45	2267	1.41	13.59	97	192	Off Idle	78	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.86	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:9	35.45	2262	1.42	13.6	97	192	Off Idle	78	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.86	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:9	35.45	2252	1.42	13.58	97	192	Off Idle	78	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.87	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:9	35.45	2255	1.42	13.57	97	192	Off Idle	78	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.86	14.9	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:9	35.45	2254	1.42	13.59	97	192	Off Idle	78	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.81	14.93	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:9	35.45	2255	1.42	13.58	97	192	Off Idle	78.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.78	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:01:9	35.45	2246	1.43	13.57	98	192	Off Idle	78.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.77	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:02:0	35.45	2256	1.43	13.57	98	192	Off Idle	78.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.73	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:02:0	35.45	2256	1.43	13.58	98	192	Off Idle	78.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.69	15.06	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:02:0	35.45	2254	1.43	13.59	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.69	15.08	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:02:0	35.45	2258	1.44	13.58	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.72	15.09	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:02:0	35.45	2258	1.44	13.59	97	192	Off Idle	78.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.7	15.09	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:02:0	35.45	2260	1.45	13.6	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.67	15.09	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:1	34.08	2243	1.45	13.59	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.67	15.07	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:1	34.08	2252	1.45	13.59	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.68	15.06	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:02:1	34.08	2275	1.45	13.6	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.63	15.06	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:02:1	34.08	2257	1.46	13.59	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.65	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:1	34.08	2257	1.46	13.59	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.62	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:1	34.08	2256	1.46	13.6	97	192	Off Idle	78.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.59	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:1	34.08	2252	1.47	13.61	97	192	Off Idle	78.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.56	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:2	34.08	2251	1.47	13.6	97	192	Off Idle	78.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.57	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:2	34.08	2251	1.47	13.6	97	192	Off Idle	78.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.53	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:2	34.08	2253	1.48	13.6	97	192	Off Idle	79.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.53	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:2	34.08	2244	1.48	13.6	98	192	Off Idle	79.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.54	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:2	34.08	2254	1.48	13.59	98	192	Off Idle	79.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.49	14.93	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:2	34.08	2265	1.49	13.6	98	192	Off Idle	79.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.49	14.91	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:3	34.08	2271	1.49	13.59	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.5	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:3	34.08	2289	1.49	13.58	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.48	14.83	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:3	34.08	2283	1.49	13.59	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.43	14.82	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:3	34.08	2279	1.5	13.61	98	192	Off Idle	79.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.45	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:3	34.08	2279	1.5	13.6	98	192	Off Idle	79.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.47	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:3	34.08	2279	1.5	13.6	98	192	Off Idle	79.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.46	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:4	34.08	2282	1.5	13.61	97	192	Off Idle	79.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.45	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:4	34.08	2285	1.51	13.6	97	192	Off Idle	79.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.46	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:4	34.08	2282	1.51	13.6	97	192	Off Idle	79.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.46	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:4	34.08	2282	1.51	13.6	97	192	Off Idle	79.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.44	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:4	34.08	2269	1.51	13.59	97	192	Off Idle	78.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.46	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:4	34.08	2261	1.51	13.57	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.46	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:4	34.08	2256	1.52	13.57	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.45	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:5	34.08	2247	1.52	13.58	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.4	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:5	35.45	2253	1.52	13.58	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.43	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:5	35.45	2244	1.52	13.58	98	192	Off Idle	78.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.39	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:5	35.45	2246	1.52	13.6	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.36	15.05	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:5	35.45	2249	1.53	13.59	98	192	Off Idle	78.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.33	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:5	35.45	2234	1.53	13.6	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.33	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:6	35.45	2244	1.53	13.59	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.3	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:6	35.45	2259	1.53	13.59	97	192	Off Idle	79	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.3	15.11	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:6	35.45	2265	1.53	13.6	97	192	Off Idle	79.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.28	15.1	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:6	35.45	2271	1.53	13.61	97	192	Off Idle	79.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.25	15.12	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:6	35.45	2271	1.54	13.6	97	192	Off Idle	79.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.26	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:6	35.45	2270	1.54	13.59	97	192	Off Idle	79.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.26	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:6	35.45	2258	1.54	13.58	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.25	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:7	35.45	2258	1.54	13.58	98	192	Off Idle	79.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.26	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:7	34.08	2247	1.54	13.59	98	192	Off Idle	80	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.27	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:02:7	34.08	2253	1.54	13.59	98	192	Off Idle	80	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.27	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:7	34.08	2252	1.55	13.59	97	192	Off Idle	80	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.25	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:7	34.08	2252	1.55	13.59	97	192	Off Idle	80	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.27	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:7	34.08	2254	1.55	13.58	97	192	Off Idle	80	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.27	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:8	34.08	2254	1.55	13.58	97	192	Off Idle	80	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.24	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:8	34.08	2250	1.55	13.59	97	192	Off Idle	80	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.21	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:8	34.08	2250	1.55	13.61	97	192	Off Idle	80	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.25	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:8	34.08	2256	1.55	13.61	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.25	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:8	34.08	2259	1.55	13.61	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.26	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:8	34.08	2259	1.55	13.6	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.28	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:9	34.08	2262	1.55	13.6	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.26	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:9	34.08	2258	1.55	13.6	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.24	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:9	34.08	2260	1.55	13.58	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.24	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:02:9	34.08	2260	1.56	13.58	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.21	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:9	34.08	2264	1.56	13.59	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.23	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:9	34.08	2265	1.56	13.58	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.23	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:02:9	34.08	2265	1.56	13.59	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.24	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:0	34.08	2263	1.56	13.6	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.23	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:0	34.08	2263	1.56	13.58	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.25	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:0	34.08	2262	1.56	13.59	98	192	Off Idle	79.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.23	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:0	34.08	2258	1.56	13.6	98	192	Off Idle	79.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.23	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:0	34.08	2252	1.56	13.6	98	192	Off Idle	79.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.24	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:0	34.08	2252	1.56	13.59	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.22	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:1	34.08	2251	1.56	13.61	97	192	Off Idle	80	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.22	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:1	34.08	2267	1.57	13.6	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.22	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:1	34.08	2257	1.57	13.59	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.19	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:1	34.08	2252	1.57	13.6	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.16	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:1	34.08	2245	1.57	13.61	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.17	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:1	34.08	2245	1.57	13.6	98	192	Off Idle	80.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.18	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:1	34.08	2232	1.57	13.58	98	192	Off Idle	80.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.17	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:2	34.08	2253	1.57	13.58	97	192	Off Idle	80.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.2	15.05	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:2	34.08	2252	1.58	13.58	97	192	Off Idle	80.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.21	15.05	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:2	34.08	2270	1.58	13.58	97	192	Off Idle	80.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.17	15.04	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:2	34.08	2270	1.58	13.56	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.15	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:2	34.08	2254	1.58	13.58	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.11	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:2	34.08	2250	1.58	13.59	97	192	Off Idle	81	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.04	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:3	34.08	2232	1.58	13.6	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.06	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:3	34.08	2232	1.58	13.59	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.1	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:3	34.08	2244	1.58	13.58	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.14	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:3	34.08	2245	1.58	13.59	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.15	14.93	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:3	34.08	2245	1.58	13.59	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.17	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:3	34.08	2249	1.58	13.58	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.16	14.86	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:4	34.08	2258	1.58	13.58	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.14	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:4	34.08	2263	1.58	13.58	97	192	Off Idle	81	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.14	14.83	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:03:4	34.08	2261	1.58	13.59	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.14	14.84	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:03:4	34.08	2259	1.58	13.59	98	192	Off Idle	80.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.15	14.84	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:4	34.08	2259	1.58	13.59	98	192	Off Idle	80.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.14	14.84	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:4	34.08	2258	1.58	13.61	98	192	Off Idle	80.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.14	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:4	34.08	2248	1.58	13.61	98	192	Off Idle	80.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.11	14.84	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:5	34.08	2240	1.58	13.6	98	192	Off Idle	80.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.09	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:5	34.08	2238	1.58	13.6	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.08	14.84	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:03:5	34.08	2238	1.58	13.6	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.08	14.84	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:03:5	34.08	2244	1.58	13.59	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.11	14.84	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:03:5	34.08	2246	1.58	13.58	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.14	14.86	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:03:5	34.08	2254	1.58	13.57	97	192	Off Idle	80	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.15	14.86	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:03:6	34.08	2260	1.58	13.58	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.13	14.87	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:6	34.08	2277	1.58	13.59	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.11	14.86	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:6	34.08	2268	1.58	13.61	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.13	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:6	34.08	2254	1.58	13.6	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.14	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:6	34.08	2248	1.58	13.6	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.12	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:6	34.08	2248	1.58	13.61	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.13	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:03:6	34.08	2233	1.58	13.6	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.14	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:03:7	34.08	2232	1.58	13.58	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.14	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:7	34.08	2241	1.58	13.57	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.14	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:7	34.08	2241	1.58	13.58	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.12	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:7	34.08	2244	1.58	13.58	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.08	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:7	34.08	2251	1.58	13.58	97	192	Off Idle	79.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.06	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:7	34.08	2253	1.58	13.59	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.05	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:8	34.08	2256	1.58	13.61	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.03	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:8	34.08	2241	1.58	13.62	97	192	Off Idle	80	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.05	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:8	34.08	2251	1.58	13.6	97	192	Off Idle	80	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.1	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:03:8	34.08	2257	1.58	13.6	97	192	Off Idle	80	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.13	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:8	34.08	2252	1.58	13.6	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.14	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:8	34.08	2256	1.58	13.59	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.13	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:9	34.08	2239	1.58	13.59	97	192	Off Idle	80.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.14	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:9	34.08	2231	1.58	13.6	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.1	15.05	1.03	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:9	34.08	2232	1.58	13.59	98	192	Off Idle	80.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.09	15.07	1.03	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:9	34.08	2217	1.58	13.59	98	192	Off Idle	80.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.1	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:9	34.08	2236	1.58	13.58	98	192	Off Idle	80.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.1	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:9	34.08	2238	1.58	13.58	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.08	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:03:9	34.08	2248	1.58	13.57	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.14	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:0	34.08	2248	1.58	13.57	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.12	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:0	34.08	2253	1.58	13.59	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.09	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:0	34.08	2258	1.58	13.61	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.12	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:0	34.08	2257	1.58	13.59	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.14	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:0	34.08	2257	1.58	13.59	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.13	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:0	34.08	2246	1.58	13.6	97	192	Off Idle	80.7	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.11	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:1	34.08	2250	1.58	13.6	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.13	14.88	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:1	34.08	2248	1.58	13.6	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.14	14.87	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:1	34.08	2240	1.58	13.58	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.13	14.86	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:1	34.08	2232	1.58	13.6	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.12	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:1	34.08	2225	1.58	13.59	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.15	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:1	34.08	2226	1.58	13.57	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.14	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:1	34.08	2229	1.58	13.59	98	192	Off Idle	80.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.09	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:2	34.08	2236	1.58	13.6	98	192	Off Idle	80.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.08	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:2	34.08	2236	1.58	13.6	98	192	Off Idle	80.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.1	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:2	34.08	2246	1.58	13.6	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.06	14.85	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:2	34.08	2252	1.58	13.61	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.04	14.87	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:2	34.08	2262	1.58	13.6	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.04	14.89	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:2	34.08	2261	1.58	13.6	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.04	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:3	34.08	2259	1.59	13.6	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:3	34.08	2253	1.59	13.6	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.99	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:04:3	34.08	2242	1.6	13.59	97	192	Off Idle	81	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.94	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:3	34.08	2238	1.6	13.58	97	192	Off Idle	81	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.9	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:3	34.08	2228	1.61	13.59	97	192	Off Idle	81	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.87	15.07	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:3	34.08	2228	1.61	13.59	97	192	Off Idle	81	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.86	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:4	34.08	2228	1.61	13.57	97	192	Off Idle	81	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.84	15.08	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:4	34.08	2234	1.62	13.59	97	192	Off Idle	81	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.82	15.08	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:4	34.08	2234	1.62	13.6	97	192	Off Idle	81	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.74	15.08	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:4	34.08	2235	1.63	13.6	97	192	Off Idle	81	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.73	15.07	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:4	34.08	2236	1.64	13.6	97	192	Off Idle	81	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.68	15.04	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:4	34.08	2242	1.64	13.62	97	192	Off Idle	81	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.68	15.04	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:4	34.08	2251	1.65	13.61	97	192	Off Idle	81	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.64	15.05	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:5	34.08	2251	1.65	13.6	97	192	Off Idle	80.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.63	15.06	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:5	34.08	2255	1.66	13.59	97	192	Off Idle	80.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.62	15.07	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:04:5	34.08	2255	1.66	13.58	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.58	15.05	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:04:5	34.08	2264	1.67	13.6	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.52	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:04:5	34.08	2256	1.68	13.6	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.52	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:04:5	34.08	2246	1.69	13.58	97	192	Off Idle	80.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.49	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:04:6	34.08	2246	1.69	13.59	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.43	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:04:6	34.08	2232	1.7	13.6	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.41	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:04:6	34.08	2238	1.7	13.6	98	192	Off Idle	80.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.4	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:6	34.08	2238	1.71	13.59	98	192	Off Idle	80.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.36	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:6	34.08	2244	1.72	13.6	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.3	14.84	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:6	34.08	2246	1.73	13.59	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.28	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:6	34.08	2246	1.73	13.59	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.19	14.82	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:7	34.08	2257	1.74	13.6	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.11	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:7	34.08	2257	1.75	13.6	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.05	14.8	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:04:7	34.08	2262	1.76	13.59	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.01	14.8	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:04:7	34.08	2251	1.77	13.6	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.94	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:04:7	34.08	2250	1.77	13.6	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.95	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:04:7	34.08	2244	1.79	13.59	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.93	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:04:8	34.08	2216	1.79	13.59	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.87	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:04:8	32.72	2216	1.8	13.6	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.84	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:04:8	32.72	2222	1.81	13.58	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.81	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:04:8	32.72	2233	1.81	13.59	98	192	Off Idle	80.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.75	14.89	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:04:8	32.72	2233	1.82	13.6	98	192	Off Idle	80.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.71	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:04:8	32.72	2237	1.82	13.59	98	192	Off Idle	80.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.71	14.9	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:04:9	32.72	2241	1.83	13.57	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.72	14.91	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:04:9	32.72	2243	1.83	13.57	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.7	14.91	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:04:9	32.72	2243	1.84	13.58	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.7	14.91	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:04:9	32.72	2262	1.84	13.58	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.69	14.92	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:04:9	32.72	2244	1.84	13.59	97	192	Off Idle	80	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.69	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:04:9	32.72	2241	1.84	13.6	97	192	Off Idle	80	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:04:9	32.72	2241	1.85	13.58	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:0	32.72	2238	1.85	13.58	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:0	32.72	2224	1.85	13.59	97	192	Off Idle	80.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:0	32.72	2232	1.85	13.58	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:0	32.72	2241	1.85	13.59	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	15.01	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:0	32.72	2237	1.85	13.58	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.6	15.02	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:0	32.72	2244	1.85	13.58	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	15.04	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:1	32.72	2246	1.85	13.57	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	15.02	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:1	32.72	2245	1.85	13.57	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:1	32.72	2246	1.85	13.58	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.6	14.98	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:1	32.72	2246	1.85	13.58	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.63	14.96	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:05:1	32.72	2248	1.85	13.56	97	192	Off Idle	80.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.64	14.94	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:05:1	32.72	2250	1.85	13.57	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.63	14.89	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:05:1	32.72	2250	1.85	13.59	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.6	14.84	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:05:2	32.72	2249	1.85	13.59	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.57	14.8	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:05:2	32.72	2245	1.85	13.58	97	192	Off Idle	80.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.55	14.75	1	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:05:2	32.72	2245	1.86	13.59	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.48	14.76	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:2	32.72	2246	1.86	13.59	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.46	14.75	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:2	32.72	2246	1.87	13.57	97	192	Off Idle	80.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.42	14.75	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:2	32.72	2252	1.87	13.57	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.37	14.74	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:3	32.72	2265	1.87	13.59	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.32	14.74	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:3	32.72	2265	1.88	13.56	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.3	14.75	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:3	32.72	2261	1.89	13.57	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.27	14.77	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:3	32.72	2261	1.9	13.59	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.2	14.81	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:3	32.72	2268	1.9	13.57	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.18	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:3	32.72	2255	1.91	13.57	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.08	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:4	32.72	2249	1.91	13.59	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.02	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:4	32.72	2243	1.92	13.58	97	192	Off Idle	80.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.02	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:4	32.72	2240	1.93	13.56	97	192	Off Idle	80	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.97	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:4	32.72	2233	1.93	13.58	97	192	Off Idle	80	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.93	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:4	32.72	2233	1.93	13.59	97	192	Off Idle	80	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.95	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:4	32.72	2231	1.94	13.58	97	192	Off Idle	80.1	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.94	15.08	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:4	32.72	2232	1.95	13.56	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.9	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:5	32.72	2220	1.95	13.57	97	193	Off Idle	80.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.89	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:05:5	32.72	2232	1.95	13.58	97	193	Off Idle	80.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.89	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:5	32.72	2248	1.95	13.56	97	192	Off Idle	80.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.87	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:5	32.72	2254	1.96	13.58	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.83	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:5	32.72	2258	1.96	13.58	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.82	15.05	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:5	32.72	2258	1.96	13.58	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.81	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:6	32.72	2252	1.96	13.58	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.8	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:6	32.72	2252	1.96	13.6	97	192	Off Idle	80.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.81	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:6	32.72	2248	1.96	13.59	98	192	Off Idle	80.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.81	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:05:6	32.72	2240	1.96	13.59	98	192	Off Idle	80.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.78	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:05:6	32.72	2261	1.96	13.6	98	192	Off Idle	80.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.77	14.81	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:6	34.08	2253	1.97	13.58	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.77	14.79	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:6	34.08	2248	1.97	13.58	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.75	14.79	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:7	34.08	2252	1.97	13.58	97	192	Off Idle	81.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.76	14.78	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:7	34.08	2260	1.97	13.57	97	192	Off Idle	80.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.78	14.8	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:7	34.08	2260	1.97	13.57	97	192	Off Idle	80.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.75	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:7	34.08	2263	1.98	13.59	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.69	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:7	32.72	2245	1.98	13.59	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.64	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:7	32.72	2252	1.98	13.58	97	192	Off Idle	80.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.6	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:05:8	32.72	2258	1.99	13.57	97	192	Off Idle	80.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.58	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:05:8	32.72	2241	1.99	13.56	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.56	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:05:8	32.72	2241	1.99	13.57	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.48	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:05:8	32.72	2237	2	13.58	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.43	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:05:8	32.72	2226	2	13.6	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.44	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:05:8	32.72	2252	2	13.6	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.44	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:05:9	32.72	2252	2.01	13.6	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.41	15.03	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:05:9	32.72	2256	2.01	13.6	97	192	Off Idle	80	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.41	15.07	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:9	32.72	2279	2.01	13.59	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.43	15.1	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:9	32.72	2272	2.02	13.58	97	192	Off Idle	80	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.4	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:9	32.72	2266	2.02	13.58	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.38	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:9	32.72	2258	2.02	13.6	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.37	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:05:9	32.72	2254	2.02	13.59	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.44	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:0	32.72	2260	2.02	13.58	97	192	Off Idle	80	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.42	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:0	32.72	2250	2.03	13.59	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.43	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:0	32.72	2253	2.03	13.59	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.44	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:0	32.72	2253	2.03	13.57	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.46	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:0	32.72	2248	2.03	13.58	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.47	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:0	32.72	2260	2.03	13.59	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.45	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:1	32.72	2260	2.02	13.6	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.48	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:1	32.72	2256	2.02	13.58	97	192	Off Idle	79.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.49	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:1	32.72	2246	2.02	13.59	97	192	Off Idle	80	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.45	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:1	32.72	2246	2.02	13.6	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.44	14.96	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:1	32.72	2258	2.02	13.6	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.45	14.94	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:1	32.72	2256	2.02	13.58	97	192	Off Idle	80	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.46	14.89	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:06:1	32.72	2264	2.02	13.58	97	192	Off Idle	80.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.47	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:06:2	32.72	2264	2.02	13.59	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.48	14.83	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:2	32.72	2286	2.02	13.59	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.46	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:2	32.72	2286	2.02	13.59	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.45	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:2	32.72	2274	2.02	13.59	97	192	Off Idle	80.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.42	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:2	32.72	2260	2.02	13.59	97	193	Off Idle	80.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.47	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:2	32.72	2262	2.02	13.58	97	193	Off Idle	79.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.46	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:3	32.72	2260	2.02	13.59	97	193	Off Idle	79.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.45	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:3	32.72	2252	2.02	13.56	97	193	Off Idle	79.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.48	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:3	32.72	2255	2.02	13.57	97	193	Off Idle	79.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.43	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:3	32.72	2255	2.02	13.58	97	193	Off Idle	79.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.41	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:3	32.72	2248	2.02	13.58	97	192	Off Idle	79.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.4	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:3	32.72	2266	2.02	13.58	97	192	Off Idle	79	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.4	14.87	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:4	32.72	2266	2.03	13.6	97	192	Off Idle	79.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.36	14.89	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:4	32.72	2270	2.03	13.6	97	192	Off Idle	79.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.35	14.94	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:4	32.72	2279	2.03	13.59	97	192	Off Idle	79.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.37	14.97	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:4	32.72	2272	2.03	13.59	97	192	Off Idle	79.1	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.37	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:4	32.72	2272	2.03	13.58	97	192	Off Idle	79.1	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.39	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:4	32.72	2268	2.03	13.59	97	192	Off Idle	79.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.33	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:4	32.72	2276	2.03	13.59	97	192	Off Idle	79.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.32	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:5	32.72	2283	2.03	13.6	97	192	Off Idle	79.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.31	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:5	32.72	2274	2.03	13.62	97	192	Off Idle	79.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.29	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:5	32.72	2262	2.03	13.59	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.33	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:5	32.72	2260	2.04	13.6	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.33	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:06:5	32.72	2260	2.04	13.6	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.36	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:5	32.72	2262	2.04	13.58	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.41	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:6	32.72	2260	2.04	13.58	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.4	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:6	32.72	2264	2.04	13.6	97	192	Off Idle	79.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.43	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:6	32.72	2265	2.03	13.59	97	192	Off Idle	79.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.44	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:6	32.72	2269	2.03	13.59	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.4	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:6	32.72	2273	2.03	13.61	97	192	Off Idle	79.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.4	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:6	32.72	2273	2.03	13.62	97	192	Off Idle	80.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.42	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:6	32.72	2272	2.03	13.6	98	192	Off Idle	80	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.44	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:7	32.72	2273	2.03	13.61	98	192	Off Idle	80.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.4	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:7	32.72	2275	2.03	13.61	98	192	Off Idle	79.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.39	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:7	32.72	2276	2.03	13.61	98	192	Off Idle	79.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.39	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:7	32.72	2278	2.03	13.58	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.4	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:7	32.72	2277	2.03	13.57	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.42	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:7	32.72	2277	2.03	13.58	97	192	Off Idle	79.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.45	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:8	32.72	2276	2.03	13.56	97	192	Off Idle	79.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.41	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:8	32.72	2274	2.03	13.56	97	192	Off Idle	79.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.4	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:06:8	32.72	2274	2.03	13.57	97	192	Off Idle	79.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.42	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:8	32.72	2274	2.03	13.58	97	192	Off Idle	79	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.41	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:8	32.72	2274	2.03	13.59	97	192	Off Idle	78.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.41	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:8	32.72	2276	2.03	13.6	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.4	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:9	32.72	2271	2.03	13.61	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.35	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:9	32.72	2269	2.03	13.62	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.34	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:9	32.72	2272	2.03	13.61	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.34	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:9	32.72	2272	2.03	13.59	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.36	14.9	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:9	32.72	2276	2.03	13.59	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.35	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:9	32.72	2281	2.04	13.59	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.39	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:06:9	32.72	2281	2.04	13.59	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.41	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:0	32.72	2278	2.04	13.58	97	192	Off Idle	78.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.41	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:0	32.72	2280	2.04	13.6	97	192	Off Idle	78.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.39	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:0	32.72	2279	2.04	13.58	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.4	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:0	32.72	2276	2.04	13.58	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.38	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:0	32.72	2275	2.04	13.58	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.37	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:0	32.72	2284	2.04	13.59	97	192	Off Idle	78.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.38	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:1	32.72	2278	2.04	13.56	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.42	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:1	32.72	2278	2.04	13.58	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.38	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:1	32.72	2267	2.04	13.6	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.4	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:1	32.72	2267	2.04	13.58	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.42	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:1	32.72	2281	2.04	13.58	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.37	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:1	32.72	2282	2.04	13.6	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.38	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:1	32.72	2281	2.04	13.6	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.41	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:2	32.72	2281	2.04	13.57	97	192	Off Idle	78.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.44	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:2	32.72	2282	2.04	13.58	97	193	Off Idle	78.7	0	2	132	944 Turbo	0.19	Rich	1	14.6	-6.43	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:2	32.72	2281	2.04	13.58	97	193	Off Idle	78.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.44	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:2	32.72	2281	2.04	13.57	97	193	Off Idle	78.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.42	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:2	32.72	2275	2.04	13.57	97	193	Off Idle	78.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.4	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:2	32.72	2274	2.04	13.57	97	193	Off Idle	78.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.38	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:3	32.72	2274	2.04	13.59	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.38	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:3	32.72	2275	2.04	13.59	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.42	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:3	32.72	2279	2.03	13.58	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.4	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:3	32.72	2280	2.03	13.58	97	193	Off Idle	78.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.37	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:3	32.72	2280	2.03	13.59	97	193	Off Idle	78.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.37	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:3	32.72	2282	2.03	13.56	97	193	Off Idle	78.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.38	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:4	32.72	2285	2.03	13.57	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.33	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:4	32.72	2285	2.03	13.58	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.33	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:4	32.72	2286	2.03	13.58	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.36	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:4	32.72	2287	2.03	13.57	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.39	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:4	32.72	2284	2.03	13.57	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.41	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:07:4	32.72	2284	2.03	13.59	97	192	Off Idle	78.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.42	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:4	32.72	2286	2.03	13.59	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.45	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:5	32.72	2295	2.03	13.6	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.43	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:5	32.72	2295	2.03	13.6	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.44	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:5	32.72	2286	2.03	13.6	97	192	Off Idle	78.1	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.45	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:5	32.72	2288	2.03	13.6	97	192	Off Idle	77.9	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.47	14.74	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:5	32.72	2288	2.03	13.59	97	192	Off Idle	78	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.48	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:5	32.72	2288	2.03	13.58	97	192	Off Idle	78	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.46	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:6	32.72	2287	2.03	13.6	97	192	Off Idle	78	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.48	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:6	32.72	2287	2.03	13.6	97	192	Off Idle	78	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.5	14.75	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:6	32.72	2288	2.03	13.6	97	192	Off Idle	77.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.49	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:6	32.72	2291	2.03	13.6	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.46	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:6	32.72	2292	2.04	13.62	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.44	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:07:6	32.72	2291	2.04	13.61	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.48	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:6	32.72	2290	2.04	13.61	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.47	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:7	32.72	2291	2.04	13.6	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.4	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:7	32.72	2291	2.04	13.6	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.4	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:7	32.72	2292	2.04	13.59	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.41	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:7	32.72	2290	2.04	13.58	97	193	Off Idle	77.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.43	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:7	32.72	2287	2.04	13.58	97	193	Off Idle	77.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.37	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:7	32.72	2285	2.04	13.59	97	193	Off Idle	77.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.38	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:8	32.72	2284	2.04	13.6	97	192	Off Idle	77.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.39	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:07:8	32.72	2285	2.04	13.58	97	192	Off Idle	77.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.38	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:8	32.72	2291	2.04	13.59	97	192	Off Idle	77.8	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.38	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:8	32.72	2291	2.04	13.6	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.42	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:8	32.72	2298	2.04	13.59	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.44	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:8	32.72	2298	2.04	13.58	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.45	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:9	32.72	2295	2.04	13.59	97	193	Off Idle	77.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.43	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:9	32.72	2288	2.04	13.59	97	193	Off Idle	78	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.45	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:9	32.72	2297	2.04	13.58	97	193	Off Idle	77.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.41	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:9	32.72	2294	2.04	13.59	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.38	14.91	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:9	32.72	2294	2.04	13.6	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.39	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:9	32.72	2290	2.04	13.6	97	192	Off Idle	77.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.41	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:07:9	32.72	2288	2.04	13.61	97	192	Off Idle	77.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.37	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:0	32.72	2289	2.04	13.61	97	192	Off Idle	78	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.39	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:0	32.72	2290	2.04	13.62	97	193	Off Idle	78.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.41	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:0	32.72	2290	2.04	13.6	97	193	Off Idle	78.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.43	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:0	32.72	2289	2.04	13.6	97	193	Off Idle	78.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.44	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:0	32.72	2290	2.04	13.6	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.43	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:0	32.72	2292	2.04	13.6	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.42	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:1	32.72	2296	2.04	13.61	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.4	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:1	32.72	2297	2.04	13.6	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.42	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:1	32.72	2296	2.04	13.61	97	193	Off Idle	78.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.43	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:1	32.72	2293	2.04	13.6	97	193	Off Idle	78.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.39	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:1	32.72	2297	2.04	13.6	97	193	Off Idle	78.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.41	15.18	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:1	32.72	2297	2.04	13.6	97	192	Off Idle	78.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.44	15.16	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:1	32.72	2296	2.04	13.59	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.44	15.14	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:2	32.72	2298	2.03	13.6	97	192	Off Idle	78.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.48	15.11	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:2	32.72	2293	2.03	13.6	97	192	Off Idle	78.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.52	15.11	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:2	32.72	2293	2.03	13.6	97	192	Off Idle	78	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.52	15.11	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:2	32.72	2304	2.03	13.59	97	192	Off Idle	78	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.53	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:2	32.72	2298	2.03	13.59	97	193	Off Idle	78	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.51	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:2	32.72	2298	2.03	13.6	97	193	Off Idle	77.9	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.55	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:3	32.72	2302	2.03	13.59	97	193	Off Idle	77.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.52	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:3	32.72	2296	2.03	13.59	97	193	Off Idle	77.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.5	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:3	32.72	2303	2.03	13.6	97	193	Off Idle	77.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.49	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:08:3	32.72	2304	2.03	13.59	97	193	Off Idle	77.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.53	14.92	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:3	32.72	2306	2.03	13.58	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.54	14.89	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:08:3	32.72	2326	2.03	13.59	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.55	14.86	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:4	32.72	2326	2.03	13.6	97	192	Off Idle	77.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.6	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:4	32.72	2306	2.03	13.59	97	192	Off Idle	77.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.6	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:4	32.72	2305	2.02	13.6	97	192	Off Idle	77.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.61	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:4	32.72	2297	2.02	13.6	97	193	Off Idle	77.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.63	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:4	32.72	2306	2.02	13.6	97	193	Off Idle	77.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.61	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:4	32.72	2307	2.02	13.59	97	193	Off Idle	77.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.63	14.84	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:4	32.72	2305	2.02	13.58	97	193	Off Idle	77.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.64	14.87	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:5	32.72	2304	2.02	13.58	97	193	Off Idle	77.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.62	14.89	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:5	32.72	2298	2.02	13.59	97	193	Off Idle	77.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.61	14.91	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:5	32.72	2291	2.02	13.58	97	193	Off Idle	77.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.65	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:5	32.72	2291	2.02	13.59	97	193	Off Idle	77.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.63	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:5	32.72	2297	2.01	13.6	97	193	Off Idle	77.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.65	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:5	32.72	2298	2.01	13.58	97	193	Off Idle	77.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.69	15	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:6	32.72	2298	2.01	13.59	97	193	Off Idle	77.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.64	15.02	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:6	32.72	2300	2.01	13.6	97	193	Off Idle	77.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.68	15.02	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:6	32.72	2303	2.01	13.59	97	193	Off Idle	77.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.68	15.01	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:6	32.72	2303	2	13.59	97	193	Off Idle	77.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.69	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:08:6	32.72	2312	2	13.6	97	193	Off Idle	77.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.7	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:08:6	32.72	2307	2	13.59	97	193	Off Idle	77.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.78	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:08:6	32.72	2304	2	13.6	97	193	Off Idle	77	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.77	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:08:7	32.72	2304	2	13.6	97	193	Off Idle	77	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.79	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:7	32.72	2291	1.99	13.6	97	192	Off Idle	76.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.81	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:7	32.72	2308	1.99	13.6	97	192	Off Idle	76.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.78	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:7	32.72	2306	1.99	13.6	97	192	Off Idle	76.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.75	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:7	32.72	2304	1.99	13.58	97	193	Off Idle	76.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.85	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:7	32.72	2308	1.98	13.58	97	193	Off Idle	76.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.82	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:8	32.72	2312	1.98	13.6	97	193	Off Idle	76.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.84	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:8	32.72	2312	1.98	13.59	97	193	Off Idle	76.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.87	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:8	32.72	2312	1.98	13.59	97	193	Off Idle	76.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.9	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:8	32.72	2311	1.98	13.6	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.9	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:08:8	32.72	2302	1.98	13.58	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.91	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:8	34.08	2329	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.89	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:9	34.08	2313	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.9	14.87	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:9	34.08	2313	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.92	14.88	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:9	34.08	2313	1.98	13.6	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.23	Rich	1	14.6	-6.89	14.88	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:08:9	34.08	2309	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.93	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:08:9	34.08	2308	1.98	13.58	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.93	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:08:9	34.08	2308	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.91	14.99	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:08:9	34.08	2304	1.98	13.58	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.92	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:0	34.08	2304	1.98	13.57	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.87	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:0	34.08	2304	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.84	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:0	34.08	2310	1.98	13.6	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.85	15.03	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:0	34.08	2311	1.98	13.58	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.83	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:0	34.08	2311	1.98	13.6	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.84	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:0	34.08	2314	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.88	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:1	34.08	2315	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.85	15.05	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:1	34.08	2314	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.83	15.04	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:1	34.08	2310	1.98	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.87	14.99	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:1	34.08	2309	1.98	13.58	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.86	14.96	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:1	34.08	2309	1.98	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.86	14.95	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:1	34.08	2309	1.98	13.58	97	192	Off Idle	76.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.88	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:1	34.08	2312	1.98	13.59	97	192	Off Idle	76.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.9	14.89	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:2	34.08	2316	1.98	13.59	97	192	Off Idle	76.7	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.92	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:2	34.08	2316	1.98	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.91	14.83	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:2	34.08	2326	1.98	13.61	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.91	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:2	34.08	2310	1.98	13.6	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.94	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:2	34.08	2310	1.98	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.95	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:09:2	34.08	2308	1.98	13.6	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.91	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:3	34.08	2296	1.98	13.6	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.95	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:3	34.08	2308	1.98	13.58	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.95	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:3	34.08	2310	1.98	13.6	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.91	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:3	34.08	2313	1.98	13.59	97	192	Off Idle	76.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.92	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:3	34.08	2314	1.98	13.59	97	192	Off Idle	76.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.89	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:3	34.08	2314	1.98	13.59	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.89	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:4	32.72	2307	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.88	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:4	32.72	2309	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.89	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:4	32.72	2308	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.91	15.14	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:4	32.72	2309	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.93	15.15	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:4	32.72	2305	1.98	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.97	15.17	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:4	32.72	2305	1.98	13.58	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.99	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:4	34.08	2320	1.98	13.57	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.02	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:5	34.08	2295	1.97	13.57	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.01	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:5	34.08	2314	1.97	13.57	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.03	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:5	34.08	2312	1.97	13.57	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.04	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:5	34.08	2310	1.97	13.57	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.06	14.99	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:5	34.08	2309	1.97	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.03	14.97	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:5	34.08	2309	1.97	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.03	14.97	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:6	34.08	2314	1.97	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.1	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:6	34.08	2320	1.96	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.07	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:6	34.08	2326	1.96	13.6	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.07	14.75	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:6	34.08	2326	1.96	13.6	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.09	14.74	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:6	34.08	2326	1.96	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.1	14.73	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:6	34.08	2324	1.96	13.61	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.11	14.73	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:6	34.08	2324	1.96	13.61	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.1	14.73	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:7	34.08	2322	1.96	13.6	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.14	14.76	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:7	34.08	2318	1.96	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.16	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:7	34.08	2313	1.95	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.16	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:7	34.08	2313	1.95	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.17	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:7	34.08	2310	1.95	13.58	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.17	14.96	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:7	34.08	2310	1.95	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.16	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:8	34.08	2307	1.95	13.6	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.16	15.04	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:8	34.08	2310	1.95	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.16	15.05	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:8	34.08	2313	1.95	13.58	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.15	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:8	34.08	2314	1.95	13.59	97	193	Off Idle	76.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.11	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:8	34.08	2328	1.95	13.6	97	192	Off Idle	76.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.13	15.12	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:8	34.08	2323	1.95	13.58	97	192	Off Idle	76.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.16	15.12	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:9	34.08	2323	1.95	13.59	97	193	Off Idle	76.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.12	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:9	34.08	2322	1.95	13.6	97	193	Off Idle	76.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.15	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:9	34.08	2319	1.95	13.59	97	193	Off Idle	76.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.16	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:09:9	34.08	2315	1.95	13.59	97	193	Off Idle	76.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.16	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:09:9	34.08	2315	1.95	13.59	97	193	Off Idle	76.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.16	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:9	34.08	2312	1.95	13.58	97	193	Off Idle	76	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.19	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:09:9	34.08	2315	1.95	13.58	97	192	Off Idle	76	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.16	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:0	34.08	2315	1.95	13.59	97	192	Off Idle	76	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.13	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:0	34.08	2310	1.96	13.58	97	192	Off Idle	76	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.13	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:0	34.08	2323	1.96	13.58	97	193	Off Idle	76	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.09	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:0	34.08	2329	1.96	13.59	97	193	Off Idle	75.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.08	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:0	34.08	2329	1.96	13.58	97	193	Off Idle	75.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.1	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:0	34.08	2339	1.96	13.58	97	192	Off Idle	75.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.12	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:1	34.08	2330	1.96	13.58	97	192	Off Idle	75.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.1	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:1	34.08	2328	1.96	13.59	97	193	Off Idle	75.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.16	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:1	34.08	2318	1.96	13.58	97	193	Off Idle	75.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.18	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:1	34.08	2304	1.96	13.59	97	193	Off Idle	75.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.17	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:10:1	34.08	2309	1.96	13.6	97	193	Off Idle	75.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.18	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:10:1	34.08	2309	1.96	13.59	97	193	Off Idle	75.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.25	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:10:1	34.08	2310	1.95	13.58	97	193	Off Idle	75.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.26	14.98	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:2	34.08	2310	1.94	13.59	97	193	Off Idle	75.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.29	15.02	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:2	34.08	2310	1.94	13.6	97	193	Off Idle	75.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.38	15.07	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:10:2	34.08	2312	1.92	13.6	97	193	Off Idle	75.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.54	15.12	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:10:2	34.08	2320	1.91	13.61	97	193	Off Idle	75.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.13	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:10:2	34.08	2319	1.89	13.61	97	193	Off Idle	75.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.12	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:10:2	34.08	2319	1.88	13.6	97	193	Off Idle	75.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.94	15.16	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:10:3	34.08	2320	1.86	13.61	97	193	Off Idle	76	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.07	15.16	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:10:3	34.08	2321	1.84	13.6	97	193	Off Idle	76	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.21	15.15	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:10:3	34.08	2322	1.81	13.6	97	193	Off Idle	76	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.34	15.12	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:10:3	34.08	2322	1.77	13.6	97	193	Off Idle	76.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.59	15.07	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:10:3	34.08	2321	1.74	13.6	97	193	Off Idle	76.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.78	15.02	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:3	34.08	2321	1.72	13.6	97	193	Off Idle	76.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.87	15	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:4	34.08	2312	1.67	13.6	97	193	Off Idle	76.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.18	14.96	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:4	34.08	2310	1.63	13.6	97	193	Full Load	76.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.38	14.94	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:10:4	34.08	2306	1.59	13.6	97	193	Full Load	76.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.56	14.93	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:10:4	34.08	2290	1.54	13.59	97	193	Idle	76.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.73	14.83	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:4	34.08	2289	1.5	13.59	97	193	Idle	76.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.87	14.79	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:4	34.08	2286	1.46	13.59	97	193	Idle	76.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.98	14.78	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:10:4	34.08	2282	1.42	13.59	97	193	Idle	76.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.1	14.77	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:10:5	31.36	2248	1.38	13.58	97	193	Idle	76.6	0	2	132	944 Turbo	0.68	Lean	1	14.6	-10.19	14.76	1.01	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:10:5	31.36	2216	1.35	13.59	97	193	Idle	76.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-10.25	14.75	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:5	31.36	2216	1.32	13.6	97	193	Idle	76.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-10.3	14.73	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:5	25.9	2208	1.28	13.61	97	193	Idle	76.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-10.37	14.73	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:5	20.45	2195	1.27	13.6	97	193	Idle	76.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-10.39	14.73	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:5	20.45	2277	1.23	13.61	97	193	Idle	75.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.42	14.72	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:6	17.72	2277	1.21	13.61	97	193	Idle	75.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.41	14.72	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:6	17.72	2337	1.18	13.6	97	193	Idle	75.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.44	14.72	1	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:6	17.72	2333	1.17	13.58	97	193	Idle	74.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.41	14.71	1	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:6	17.72	2344	1.15	13.59	97	193	Idle	74.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.41	14.71	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:6	17.72	2359	1.14	13.59	97	193	Idle	74.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.44	14.7	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:6	17.72	2343	1.13	13.59	97	192	Idle	74.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.47	14.7	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:6	17.72	2324	1.12	13.59	97	192	Idle	74.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	14.69	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:7	17.72	2324	1.12	13.59	97	192	Idle	74	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.5	14.69	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:7	17.72	2299	1.12	13.59	97	193	Idle	74	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.49	14.7	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:7	17.72	2291	1.13	13.59	97	193	Idle	73.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.51	14.71	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:7	17.72	2289	1.13	13.59	97	193	Idle	74	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.51	14.73	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:7	17.72	2280	1.13	13.59	97	193	Idle	74	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.5	14.73	1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:7	17.72	2275	1.14	13.59	97	193	Idle	74.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.49	14.75	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:8	17.72	2275	1.14	13.59	97	193	Idle	74.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.51	14.76	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:8	17.72	2280	1.14	13.58	97	193	Idle	75	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.47	14.77	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:8	17.72	2284	1.14	13.58	97	193	Idle	75	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.48	14.77	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:8	17.72	2284	1.14	13.58	97	193	Idle	75.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.47	14.77	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:8	17.72	2291	1.15	13.6	97	193	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	14.78	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:8	17.72	2298	1.15	13.59	97	193	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	14.81	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:9	17.72	2303	1.15	13.6	97	193	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	14.86	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:9	17.72	2303	1.15	13.61	97	193	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	14.92	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:9	17.72	2301	1.15	13.6	97	193	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	15.05	1.03	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:9	17.72	2296	1.15	13.61	97	193	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	15.16	1.03	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:9	17.72	2291	1.15	13.61	97	193	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	15.31	1.04	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:9	17.72	2291	1.14	13.59	97	193	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	15.51	1.06	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:10:9	17.72	2288	1.14	13.59	97	193	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	15.73	1.07	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:0	17.72	2287	1.14	13.6	97	193	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	15.97	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:0	17.72	2287	1.14	13.59	97	193	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	16.23	1.11	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:0	17.72	2288	1.13	13.59	97	193	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	16.51	1.12	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:0	17.72	2290	1.13	13.6	97	193	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	16.85	1.15	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:0	17.72	2290	1.13	13.59	97	193	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	17.43	1.19	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:0	17.72	2291	1.13	13.58	97	193	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	17.65	1.2	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:11:1	17.72	2292	1.13	13.6	97	193	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	18.26	1.24	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:1	17.72	2290	1.13	13.59	97	193	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	18.64	1.27	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:1	17.72	2286	1.12	13.58	97	193	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	18.99	1.29	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:1	17.72	2282	1.12	13.59	97	193	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	19.3	1.31	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:1	17.72	2279	1.12	13.59	97	193	Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	19.57	1.33	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:1	17.72	2268	1.12	13.58	97	193	Idle	77.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	19.81	1.35	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:1	17.72	2263	1.12	13.58	97	193	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.06	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:2	17.72	2258	1.12	13.59	97	193	Idle	77	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.14	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:2	17.72	2255	1.12	13.59	97	193	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.14	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:2	17.72	2250	1.12	13.6	97	193	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.16	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:2	17.72	2251	1.12	13.61	97	193	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.16	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:2	17.72	2253	1.11	13.62	97	193	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.17	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:2	17.72	2262	1.11	13.63	97	193	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.17	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:3	17.72	2270	1.11	13.62	97	193	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.17	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:3	17.72	2308	1.11	13.61	97	193	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.18	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:3	17.72	2308	1.11	13.61	97	193	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.18	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:3	17.72	2297	1.11	13.61	97	193	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.18	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:3	17.72	2298	1.11	13.6	97	193	Idle	76.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:3	17.72	2296	1.11	13.61	97	193	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:4	17.72	2290	1.11	13.62	97	193	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:4	17.72	2278	1.11	13.6	97	193	Idle	76.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:4	17.72	2270	1.11	13.59	97	193	Idle	76.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:4	17.72	2268	1.11	13.59	97	193	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:4	17.72	2258	1.11	13.6	97	193	Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:4	17.72	2253	1.11	13.59	97	193	Idle	77.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:4	17.72	2253	1.11	13.59	97	193	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:5	17.72	2253	1.11	13.6	97	193	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:5	17.72	2255	1.11	13.58	97	193	Idle	77.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:5	17.72	2239	1.11	13.58	97	193	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:5	17.72	2249	1.11	13.58	97	193	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:5	17.72	2270	1.11	13.58	97	193	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:5	17.72	2264	1.11	13.59	97	193	Idle	78.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:6	17.72	2264	1.11	13.6	97	193	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:6	17.72	2260	1.11	13.6	97	193	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:6	17.72	2256	1.11	13.59	97	193	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:6	17.72	2249	1.1	13.6	97	193	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:6	17.72	2246	1.1	13.6	97	193	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:6	17.72	2225	1.1	13.59	97	193	Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:6	17.72	2230	1.1	13.59	97	193	Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:7	17.72	2237	1.1	13.61	97	193	Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:7	17.72	2237	1.1	13.6	97	193	Idle	78.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:7	17.72	2242	1.09	13.6	97	193	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:7	17.72	2244	1.09	13.62	97	193	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:7	17.72	2251	1.09	13.6	97	193	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:7	17.72	2271	1.09	13.6	97	193	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:8	17.72	2264	1.09	13.61	97	193	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:8	17.72	2249	1.09	13.6	97	193	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:8	17.72	2252	1.09	13.58	97	193	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:8	17.72	2274	1.08	13.59	97	193	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:8	17.72	2262	1.08	13.61	97	193	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:8	17.72	2236	1.08	13.6	97	193	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:9	17.72	2241	1.08	13.6	97	193	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:9	17.72	2241	1.08	13.61	97	193	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:9	17.72	2238	1.08	13.61	97	193	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:9	17.72	2241	1.08	13.61	97	193	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:9	17.72	2248	1.07	13.61	97	193	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:9	17.72	2248	1.07	13.6	97	193	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:11:9	17.72	2252	1.07	13.6	97	193	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:12:0	17.72	2252	1.07	13.58	97	193	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:0	17.72	2252	1.07	13.58	97	193	Idle	80.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:0	17.72	2252	1.07	13.6	97	193	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:0	17.72	2262	1.07	13.59	97	193	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:0	17.72	2262	1.07	13.58	97	193	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:0	17.72	2237	1.07	13.6	97	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:1	17.72	2229	1.06	13.6	97	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:1	17.72	2182	1.06	13.59	97	193	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:1	17.72	2182	1.06	13.59	97	193	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:1	17.72	2210	1.06	13.59	97	193	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:1	17.72	2206	1.06	13.59	97	193	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:1	17.72	2206	1.06	13.59	97	193	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:1	17.72	2209	1.06	13.62	97	193	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:2	17.72	2214	1.06	13.62	97	193	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:2	17.72	2222	1.06	13.62	97	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:2	17.72	2222	1.06	13.6	97	193	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.19	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:2	17.72	2228	1.06	13.6	97	193	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.18	1.37	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:2	17.72	2253	1.06	13.6	97	193	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:2	17.72	2244	1.06	13.6	97	193	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.18	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:3	17.72	2237	1.06	13.6	97	193	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.18	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:3	17.72	2234	1.06	13.59	97	193	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.18	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:3	17.72	2227	1.06	13.58	97	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.18	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:3	17.72	2227	1.05	13.58	97	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.18	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:3	17.72	2218	1.05	13.58	97	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.18	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:3	17.72	2200	1.05	13.6	97	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.18	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:4	17.72	2200	1.05	13.6	97	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.18	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:4	17.72	2203	1.05	13.6	97	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:4	17.72	2201	1.05	13.59	97	193	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:4	17.72	2204	1.05	13.58	97	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:4	17.72	2209	1.05	13.58	97	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:4	17.72	2220	1.05	13.59	97	193	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:4	17.72	2222	1.05	13.6	97	193	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:5	17.72	2229	1.05	13.61	97	193	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:5	17.72	2229	1.05	13.59	97	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:5	17.72	2230	1.05	13.59	97	193	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:5	17.72	2228	1.05	13.58	97	193	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:5	17.72	2223	1.05	13.58	97	193	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:5	17.72	2220	1.05	13.59	97	193	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:6	17.72	2208	1.05	13.6	97	193	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:6	17.72	2197	1.05	13.61	97	193	Idle	80.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:6	17.72	2194	1.05	13.61	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:6	17.72	2186	1.05	13.61	97	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:6	17.72	2169	1.05	13.61	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:6	17.72	2177	1.05	13.61	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:6	17.72	2188	1.05	13.6	97	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:7	17.72	2196	1.05	13.59	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:7	17.72	2196	1.05	13.59	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:7	17.72	2201	1.05	13.56	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:7	17.72	2205	1.05	13.54	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:7	17.72	2206	1.05	13.53	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:7	17.72	2206	1.05	13.52	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:8	17.72	2212	1.05	13.5	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:8	17.72	2218	1.05	13.5	97	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:8	17.72	2200	1.05	13.51	97	193	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:8	17.72	2199	1.05	13.5	97	193	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:8	17.72	2162	1.05	13.52	97	193	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:8	17.72	2192	1.04	13.53	97	193	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:9	17.72	2184	1.04	13.54	97	193	Idle	81.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:12:9	17.72	2182	1.04	13.53	97	193	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:9	17.72	2177	1.04	13.53	97	193	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:9	17.72	2171	1.04	13.53	97	193	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:9	17.72	2170	1.04	13.53	97	193	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:9	17.72	2162	1.04	13.53	97	193	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:12:9	17.72	2158	1.04	13.55	97	193	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:0	17.72	2158	1.04	13.54	97	193	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:0	17.72	2152	1.04	13.54	97	193	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:0	17.72	2144	1.03	13.55	97	193	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:0	17.72	2135	1.03	13.56	97	193	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:0	17.72	2135	1.03	13.56	97	193	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:0	17.72	2129	1.03	13.55	97	193	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:1	17.72	2116	1.03	13.54	97	193	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:1	17.72	2116	1.03	13.5	97	193	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:1	17.72	2100	1.03	13.51	97	193	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:1	17.72	2100	1.03	13.51	97	193	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:1	17.72	2095	1.02	13.51	97	193	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:1	17.72	2093	1.02	13.52	97	193	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:1	17.72	2085	1.02	13.52	97	193	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:2	17.72	2080	1.02	13.53	97	193	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:2	17.72	2078	1.02	13.53	97	193	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:2	17.72	2072	1.02	13.55	97	193	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:2	17.72	2069	1.02	13.56	97	193	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:2	17.72	2063	1.02	13.56	97	193	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:2	17.72	2061	1.02	13.56	97	193	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:3	17.72	2055	1.02	13.56	97	193	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:3	17.72	2034	1.02	13.55	97	193	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:3	17.72	2040	1.02	13.55	97	193	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.18	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:3	17.72	2055	1.02	13.54	97	193	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:3	17.72	2034	1.02	13.54	97	193	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:3	17.72	2004	1.02	13.53	97	193	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.18	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:4	17.72	2004	1.02	13.52	97	193	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:4	17.72	2009	1.02	13.52	97	193	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:4	17.72	2006	1.02	13.54	97	193	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:4	17.72	2002	1.02	13.55	97	193	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:4	17.72	1982	1.02	13.54	97	193	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:4	17.72	1946	1.02	13.54	97	193	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:4	17.72	1946	1.02	13.53	97	193	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:5	17.72	1907	1.02	13.51	97	193	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:5	17.72	1882	1.03	13.52	97	193	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:5	17.72	1882	1.03	13.52	97	193	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:5	17.72	1846	1.03	13.53	97	193	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:5	17.72	1827	1.03	13.51	97	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:5	17.72	1816	1.03	13.52	97	193	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:6	17.72	1805	1.03	13.52	97	193	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:6	17.72	1771	1.03	13.52	97	193	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.2	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:6	17.72	1749	1.03	13.53	97	193	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.2	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:6	17.72	1712	1.04	13.53	97	193	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:6	17.72	1708	1.04	13.51	97	193	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:6	17.72	1678	1.05	13.5	97	193	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.2	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:6	17.72	1656	1.05	13.52	97	193	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.2	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:7	17.72	1632	1.07	13.51	97	193	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.21	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:7	17.72	1632	1.07	13.52	97	193	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.2	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:7	17.72	1608	1.09	13.53	97	193	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.2	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:7	17.72	1572	1.1	13.53	97	193	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.2	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:7	17.72	1566	1.11	13.54	97	193	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.2	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:7	17.72	1534	1.12	13.53	97	193	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	20.2	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:8	17.72	1510	1.13	13.54	97	193	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.4	20.19	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:13:8	17.72	1510	1.14	13.54	97	193	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.28	20.19	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:8	17.72	1485	1.15	13.52	97	193	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.24	20.2	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:8	17.72	1460	1.17	13.52	97	193	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.14	20.19	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:8	17.72	1434	1.18	13.53	97	193	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9	20.2	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:8	17.72	1434	1.2	13.53	97	193	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.9	20.21	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:9	17.72	1398	1.21	13.53	97	193	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.85	20.21	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:9	17.72	1382	1.22	13.52	97	193	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.74	20.21	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:9	17.72	1382	1.23	13.54	97	193	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.21	1.38	4.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:9	19.09	1366	1.23	13.53	97	193	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.62	20.21	1.38	4.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:13:9	19.09	1328	1.25	13.51	97	193	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.49	20.22	1.38	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:13:9	17.72	1328	1.25	13.51	97	193	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.42	20.22	1.38	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:22:13:9	17.72	1290	1.26	13.53	97	193	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.33	20.22	1.38	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:0	17.72	1254	1.26	13.52	97	193	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.2	20.21	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:14:0	16.36	1254	1.26	13.52	97	193	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.13	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:14:0	16.36	1248	1.26	13.54	97	193	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.07	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:14:0	16.36	1219	1.26	13.54	97	193	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.99	20.2	1.38	4.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:14:0	16.36	1232	1.26	13.53	97	193	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.96	20.21	1.38	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:14:0	16.36	1232	1.26	13.54	97	193	Idle	69.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.9	20.2	1.38	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:14:1	16.36	1275	1.26	13.53	97	193	Idle	70.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.85	20.21	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:1	16.36	1326	1.25	13.52	97	193	Idle	71.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.87	20.21	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:1	16.36	1326	1.25	13.54	97	193	Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.84	20.2	1.38	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:1	16.36	1379	1.24	13.55	97	193	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.82	20.2	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:14:1	14.99	1465	1.23	13.54	97	193	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.89	20.2	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:14:1	14.99	1509	1.22	13.55	97	193	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.98	20.2	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:14:1	14.99	1509	1.21	13.57	97	193	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.09	20.2	1.38	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:14:2	14.99	1630	1.2	13.56	97	193	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.2	20.2	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:14:2	14.99	1664	1.19	13.57	97	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.36	20.2	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:14:2	14.99	1678	1.18	13.58	97	193	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.52	20.21	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:14:2	14.99	1747	1.16	13.57	97	193	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:14:2	14.99	1813	1.14	13.56	97	193	Idle	84.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.94	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:14:2	14.99	1848	1.13	13.56	97	193	Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.14	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:14:3	14.99	1870	1.12	13.56	97	193	Idle	86.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.31	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:14:3	14.99	1980	1.11	13.57	97	193	Idle	87.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.47	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:14:3	16.36	2019	1.09	13.58	97	193	Idle	88.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.65	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:14:3	16.36	2019	1.08	13.59	97	193	Idle	90.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.8	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:3	16.36	2099	1.05	13.57	97	193	Idle	90.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.96	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:3	16.36	2148	1.04	13.56	97	193	Idle	90.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.03	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:4	16.36	2189	1.03	13.55	97	193	Idle	90.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.09	20.19	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:4	16.36	2211	1.01	13.54	97	193	Idle	91.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.16	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:4	16.36	2320	1	13.54	97	193	Idle	90.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.23	20.19	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:4	17.72	2350	0.99	13.56	97	193	Idle	90.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.31	20.19	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:4	17.72	2350	0.98	13.55	97	193	Idle	89.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.38	20.19	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:4	17.72	2436	0.97	13.56	97	193	Idle	88.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.47	20.2	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:4	17.72	2408	0.96	13.55	97	193	Idle	87.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.54	20.19	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:5	17.72	2409	0.96	13.54	97	193	Idle	85.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.63	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:5	17.72	2398	0.96	13.54	97	193	Idle	84.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.63	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:5	17.72	2366	0.96	13.53	97	193	Idle	83.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.66	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:5	17.72	2340	0.97	13.54	97	193	Idle	81.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:5	17.72	2340	0.98	13.54	97	193	Idle	80.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:5	17.72	2293	0.98	13.54	97	193	Idle	79.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.63	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:6	17.72	2282	0.99	13.54	97	193	Idle	77.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.61	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:6	17.72	2274	1	13.53	97	193	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:6	17.72	2251	1.01	13.53	97	193	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:6	17.72	2238	1.02	13.54	97	193	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.13	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:6	17.72	2238	1.03	13.53	97	193	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.08	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:6	17.72	2236	1.04	13.52	97	193	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	19.94	1.36	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:6	17.72	2246	1.05	13.53	97	193	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	19.8	1.35	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:7	17.72	2272	1.07	13.54	97	193	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	19.6	1.34	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:14:7	17.72	2278	1.09	13.54	97	193	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	19.49	1.33	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:7	17.72	2282	1.1	13.54	97	193	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	19.44	1.32	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:7	17.72	2269	1.12	13.55	97	193	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	19.42	1.32	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:7	17.72	2278	1.13	13.55	97	193	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	19.42	1.32	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:7	17.72	2278	1.14	13.55	97	193	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	19.44	1.32	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:8	17.72	2264	1.15	13.54	97	193	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	19.5	1.33	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:8	17.72	2247	1.15	13.52	97	193	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	19.68	1.34	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:8	17.72	2235	1.15	13.53	97	193	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	19.82	1.35	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:8	17.72	2230	1.15	13.54	97	193	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	19.82	1.35	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:8	17.72	2212	1.15	13.55	97	193	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.02	1.36	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:8	17.72	2212	1.15	13.55	97	193	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.13	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:9	17.72	2196	1.15	13.54	97	193	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.19	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:9	17.72	2203	1.15	13.54	97	193	Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:9	17.72	2203	1.15	13.54	97	193	Idle	77.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:9	17.72	2194	1.15	13.54	97	193	Idle	78.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:9	17.72	2216	1.15	13.54	97	193	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:9	17.72	2227	1.14	13.55	97	193	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:14:9	17.72	2226	1.14	13.54	97	193	Idle	78.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:0	17.72	2229	1.13	13.53	97	193	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:0	17.72	2228	1.13	13.54	97	193	Idle	78.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:0	17.72	2241	1.12	13.54	97	193	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:0	17.72	2220	1.12	13.55	97	193	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:0	17.72	2217	1.11	13.56	97	193	Idle	78.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:0	17.72	2194	1.11	13.56	97	193	Idle	78.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:1	17.72	2189	1.11	13.56	97	193	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:1	17.72	2163	1.1	13.55	97	193	Idle	79.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:1	17.72	2167	1.1	13.55	97	193	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:1	17.72	2165	1.1	13.55	97	193	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:1	17.72	2162	1.09	13.56	97	193	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:1	17.72	2156	1.09	13.56	97	193	Idle	79.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:1	17.72	2155	1.09	13.55	97	193	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:2	17.72	2153	1.09	13.53	97	193	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:2	17.72	2154	1.09	13.52	97	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:2	17.72	2155	1.09	13.52	97	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:2	17.72	2159	1.08	13.53	97	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:2	17.72	2159	1.08	13.55	97	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:2	17.72	2161	1.08	13.56	97	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:3	17.72	2161	1.08	13.57	97	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:3	17.72	2164	1.08	13.58	97	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:3	17.72	2167	1.08	13.59	97	193	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:3	17.72	2165	1.07	13.59	97	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:3	17.72	2166	1.07	13.6	97	193	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:3	17.72	2161	1.07	13.61	97	193	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:4	17.72	2159	1.06	13.59	97	193	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:4	17.72	2154	1.06	13.59	97	193	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:4	17.72	2152	1.06	13.58	97	193	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:4	17.72	2150	1.06	13.57	97	193	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:4	17.72	2149	1.05	13.57	97	193	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:4	17.72	2148	1.05	13.58	97	193	Idle	83.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:4	17.72	2136	1.05	13.58	97	193	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:5	17.72	2144	1.05	13.58	97	193	Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:5	17.72	2144	1.04	13.59	97	193	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:5	17.72	2152	1.04	13.6	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:5	17.72	2143	1.04	13.62	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:5	17.72	2142	1.03	13.62	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:5	17.72	2142	1.03	13.61	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:6	17.72	2132	1.03	13.6	97	193	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:6	17.72	2138	1.03	13.59	97	193	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:15:6	17.72	2138	1.02	13.57	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:6	17.72	2135	1.02	13.56	97	193	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:6	17.72	2130	1.02	13.56	97	193	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:6	17.72	2130	1.02	13.56	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:6	17.72	2142	1.02	13.56	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:7	17.72	2126	1.02	13.57	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.49	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:7	17.72	2126	1.01	13.58	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:7	17.72	2121	1.01	13.58	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:7	17.72	2102	1.01	13.6	97	193	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:7	17.72	2102	1.01	13.59	97	193	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:7	17.72	2118	1.01	13.58	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:8	17.72	2116	1.01	13.57	97	193	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:8	17.72	2116	1.01	13.56	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:8	17.72	2117	1.01	13.56	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:8	17.72	2119	1.01	13.57	97	193	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:8	17.72	2120	1.01	13.58	97	193	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:8	17.72	2120	1.01	13.6	97	193	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:9	17.72	2118	1.01	13.61	97	193	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:9	17.72	2116	1.01	13.59	97	193	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:9	17.72	2115	1.01	13.58	97	193	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:9	17.72	2111	1.01	13.57	97	193	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:9	17.72	2109	1.01	13.56	97	193	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:9	17.72	2104	1.01	13.56	97	193	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:15:9	17.72	2104	1	13.56	97	193	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:0	17.72	2100	1	13.57	97	193	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:0	17.72	2097	1	13.58	97	193	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:0	17.72	2096	1	13.59	97	193	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:0	17.72	2094	1	13.59	97	193	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:0	17.72	2094	1	13.59	97	193	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:0	17.72	2094	1	13.58	97	193	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:1	17.72	2093	1	13.57	97	193	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:1	17.72	2092	1	13.56	97	193	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:1	17.72	2091	1	13.56	97	193	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:1	17.72	2091	1	13.57	97	193	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:1	17.72	2090	1	13.58	97	193	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:1	17.72	2088	1	13.6	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:1	17.72	2088	1	13.6	97	193	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:2	17.72	2090	1	13.6	97	193	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:2	17.72	2090	1	13.58	97	193	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:2	17.72	2091	1	13.57	97	193	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:2	17.72	2092	1	13.56	97	193	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:2	17.72	2093	1	13.56	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:2	17.72	2093	1	13.58	97	193	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:3	17.72	2094	1	13.59	97	193	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:3	17.72	2091	1	13.6	97	193	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:3	17.72	2091	1	13.6	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:3	17.72	2090	1	13.59	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:3	17.72	2087	1	13.57	97	193	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:3	17.72	2086	1	13.57	97	193	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:4	17.72	2085	1	13.57	97	193	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:4	17.72	2081	1	13.58	97	193	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:4	17.72	2079	1	13.61	97	193	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:4	17.72	2073	1	13.62	97	193	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:4	17.72	2073	1	13.62	97	193	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:4	17.72	2067	1	13.62	97	193	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:4	17.72	2065	1	13.61	97	193	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:5	17.72	2064	1	13.6	97	193	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:5	17.72	2060	1	13.59	97	193	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:16:5	17.72	2060	1	13.57	97	193	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:5	17.72	2060	1	13.56	97	193	Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:5	17.72	2041	1	13.56	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:5	17.72	2055	1	13.56	97	193	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.19	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:6	17.72	2063	1	13.56	97	193	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:6	17.72	2053	1	13.56	97	193	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:6	17.72	2052	1	13.56	97	193	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:6	17.72	2051	1	13.57	97	193	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:6	17.72	2048	1	13.58	97	193	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:6	17.72	2047	1	13.59	97	193	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:6	17.72	2031	1	13.62	97	193	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:7	17.72	2031	1	13.61	97	193	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:7	17.72	2045	1	13.61	97	193	Full Load	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:7	17.72	2052	1	13.61	97	193	Off Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:7	17.72	1939	1.01	13.6	97	193	Off Idle	83.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:7	8.18	1939	1.01	13.59	97	193	Off Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:7	8.18	2052	1.02	13.58	97	193	Off Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:8	10.9	2059	1.03	13.57	97	193	Off Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:22:16:8	10.9	2059	1.04	13.56	97	193	Off Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:16:8	13.63	2060	1.05	13.56	97	193	Off Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:16:8	16.36	2060	1.06	13.56	97	193	Off Idle	84.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:22:16:8	16.36	2058	1.07	13.57	97	193	Off Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:16:8	19.09	2059	1.07	13.59	97	193	Off Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:16:9	19.09	2059	1.09	13.6	97	193	Off Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:16:9	21.81	2060	1.1	13.61	97	193	Off Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:16:9	21.81	2058	1.11	13.6	97	193	Off Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:16:9	24.54	2058	1.12	13.61	97	193	Off Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:16:9	27.27	2060	1.14	13.59	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:16:9	27.27	2057	1.15	13.58	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:16:9	27.27	2064	1.17	13.59	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:17:0	29.99	2064	1.19	13.6	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:17:0	29.99	2071	1.21	13.59	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:17:0	32.72	2060	1.22	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:17:0	34.08	2060	1.24	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:17:0	34.08	2065	1.26	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:17:0	34.08	2053	1.27	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.21	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:17:1	34.08	2052	1.28	13.6	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.2	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:17:1	34.08	2044	1.3	13.59	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.2	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:17:1	34.08	2044	1.31	13.58	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.2	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:17:1	34.08	2038	1.33	13.57	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.52	20.2	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:17:1	34.08	2038	1.35	13.58	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	20.21	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:17:1	34.08	2032	1.37	13.59	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	20.2	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:17:1	34.08	2032	1.4	13.59	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.26	20.2	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:2	34.08	2032	1.41	13.59	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.25	20.2	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:2	34.08	2031	1.43	13.58	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.22	20.2	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:2	34.08	2032	1.44	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.19	20.2	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:2	34.08	2033	1.46	13.56	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.15	20.21	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:2	34.08	2038	1.47	13.57	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.1	20.21	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:2	32.72	2038	1.49	13.59	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.01	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:3	32.72	2052	1.5	13.58	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.97	20.21	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:3	32.72	2052	1.51	13.59	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.93	20.21	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:3	32.72	2052	1.52	13.57	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.89	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:3	32.72	2055	1.53	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.86	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:3	32.72	2055	1.54	13.55	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.81	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:3	32.72	2054	1.55	13.55	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.75	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:4	32.72	2062	1.56	13.55	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.71	20.22	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:4	32.72	2062	1.57	13.56	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.62	20.19	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:4	32.72	2039	1.57	13.56	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.58	20.11	1.37	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:17:4	32.72	2031	1.57	13.57	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	19.97	1.36	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:4	32.72	2010	1.58	13.58	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	19.78	1.35	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:4	32.72	2016	1.58	13.59	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	19.53	1.33	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:4	32.72	2020	1.58	13.6	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	19.25	1.31	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:5	32.72	2020	1.58	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	18.95	1.29	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:5	32.72	2018	1.59	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.54	18.62	1.27	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:5	32.72	2016	1.59	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.54	18.26	1.24	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:5	32.72	2020	1.59	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	17.88	1.22	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:5	32.72	2020	1.59	13.6	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	17.51	1.19	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:5	32.72	2024	1.59	13.58	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	17.03	1.16	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:6	32.72	2032	1.6	13.57	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	16.77	1.14	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:6	32.72	2035	1.6	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.51	16.56	1.13	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:6	32.72	2036	1.6	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.52	16.47	1.12	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:6	32.72	2039	1.6	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.5	16.31	1.11	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:6	32.72	2040	1.6	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.47	16.17	1.1	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:17:6	32.72	2038	1.6	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.45	16.04	1.09	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:6	32.72	2029	1.61	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.43	15.9	1.08	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:7	32.72	2026	1.61	13.54	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.41	15.83	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:7	32.72	2021	1.61	13.55	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.4	15.76	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:7	32.72	2021	1.61	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.41	15.7	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:7	32.72	2018	1.61	13.57	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.41	15.65	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:7	32.72	2023	1.62	13.57	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.39	15.61	1.06	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:7	32.72	2023	1.62	13.57	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.35	15.55	1.06	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:8	32.72	2028	1.63	13.56	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.34	15.5	1.06	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:8	32.72	2037	1.63	13.55	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.3	15.47	1.05	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:17:8	32.72	2037	1.63	13.55	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.22	15.44	1.05	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:8	32.72	2044	1.64	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.14	15.38	1.05	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:8	32.72	2064	1.64	13.57	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.1	15.34	1.05	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:8	32.72	2052	1.65	13.58	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.05	15.31	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:9	32.72	2052	1.65	13.59	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.05	15.28	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:9	32.72	2049	1.66	13.6	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.04	15.25	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:9	32.72	2042	1.66	13.61	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.04	15.25	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:9	32.72	2040	1.67	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.06	15.23	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:9	32.72	2032	1.67	13.6	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.05	15.21	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:9	31.36	2008	1.68	13.57	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.04	15.18	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:17:9	31.36	2008	1.68	13.56	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.04	15.16	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:0	31.36	2014	1.68	13.55	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8	15.14	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:0	31.36	2026	1.69	13.54	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.98	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:0	31.36	2025	1.69	13.55	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.95	15.12	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:0	31.36	2028	1.69	13.56	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.91	15.11	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:0	31.36	2037	1.7	13.57	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.89	15.1	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:0	31.36	2037	1.7	13.57	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.87	15.07	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:1	31.36	2040	1.7	13.58	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.84	15.05	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:1	31.36	2045	1.7	13.59	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.04	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:1	31.36	2046	1.7	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.87	15.04	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:1	31.36	2054	1.7	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.88	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:1	31.36	2042	1.7	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.92	15.05	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:1	31.36	2040	1.7	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.96	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:1	31.36	2038	1.7	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.97	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:2	31.36	2027	1.7	13.6	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.98	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:2	31.36	2033	1.7	13.59	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.98	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:2	31.36	2035	1.7	13.58	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.98	14.96	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:2	31.36	2034	1.7	13.57	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.97	14.94	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:2	31.36	2025	1.7	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.97	14.91	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:2	31.36	2026	1.7	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.98	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:3	31.36	2028	1.7	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.97	14.84	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:3	31.36	2031	1.7	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.98	14.81	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:3	31.36	2031	1.7	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.95	14.77	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:18:3	31.36	2033	1.7	13.59	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.94	14.72	1	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:3	31.36	2032	1.7	13.59	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.93	14.73	1	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:3	31.36	2033	1.7	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.92	14.73	1	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:4	31.36	2028	1.7	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.91	14.73	1	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:4	31.36	2028	1.7	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.92	14.74	1	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:4	31.36	2028	1.7	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.92	14.75	1	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:4	31.36	2030	1.7	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.9	14.76	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:4	31.36	2038	1.7	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.89	14.77	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:4	31.36	2045	1.7	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.88	14.78	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:4	31.36	2048	1.7	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.87	14.8	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:5	31.36	2047	1.7	13.61	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.84	14.81	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:5	31.36	2047	1.7	13.61	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.8	14.8	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:5	31.36	2046	1.7	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.82	14.79	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:5	31.36	2043	1.7	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.83	14.79	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:5	31.36	2053	1.7	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.85	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:5	31.36	2044	1.7	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.86	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:6	31.36	2034	1.7	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.88	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:6	31.36	2028	1.71	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.87	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:6	31.36	2038	1.71	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.88	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:18:6	31.36	2038	1.71	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.89	14.87	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:18:6	31.36	2039	1.71	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.9	14.91	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:6	31.36	2037	1.71	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.9	14.95	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:6	31.36	2037	1.71	13.6	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.9	14.99	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:7	31.36	2038	1.71	13.59	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.89	15.02	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:7	31.36	2038	1.71	13.57	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.89	15.06	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:7	31.36	2033	1.71	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.89	15.06	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:7	31.36	2033	1.71	13.55	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.85	15.07	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:7	31.36	2034	1.71	13.55	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.83	15.07	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:7	31.36	2031	1.71	13.55	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	15.07	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:8	31.36	2031	1.71	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.1	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:8	31.36	2038	1.71	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.1	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:8	31.36	2052	1.71	13.58	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.84	15.08	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:8	31.36	2043	1.72	13.59	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:8	31.36	2044	1.72	13.6	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:8	31.36	2044	1.72	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:9	31.36	2027	1.72	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:9	31.36	2037	1.72	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:9	31.36	2034	1.72	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.89	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:9	31.36	2031	1.72	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	14.82	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:18:9	31.36	2032	1.72	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	14.75	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:9	31.36	2032	1.72	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	14.76	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:18:9	31.36	2033	1.72	13.61	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.78	14.75	1	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:19:0	31.36	2034	1.72	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.79	14.74	1	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:19:0	31.36	2038	1.72	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.77	14.75	1	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:19:0	31.36	2038	1.72	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.75	14.75	1	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:19:0	31.36	2038	1.72	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.76	14.76	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:19:0	31.36	2050	1.72	13.62	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.74	14.78	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:19:0	31.36	2041	1.72	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.74	14.79	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:19:1	31.36	2042	1.73	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.74	14.81	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:19:1	31.36	2063	1.73	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.36	Lean	1	14.7	-7.76	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:19:1	31.36	2049	1.73	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.73	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:1	31.36	2048	1.73	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.72	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:1	31.36	2048	1.73	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:1	31.36	2039	1.73	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	14.79	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:1	31.36	2045	1.73	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.8	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:2	31.36	2045	1.74	13.62	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.8	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:2	31.36	2043	1.74	13.61	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.8	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:2	31.36	2041	1.74	13.6	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.68	14.82	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:19:2	31.36	2040	1.75	13.58	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.64	14.84	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:19:2	31.36	2040	1.75	13.57	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.64	14.85	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:2	31.36	2039	1.75	13.55	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.59	14.87	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:3	31.36	2040	1.76	13.54	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.55	14.91	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:3	31.36	2040	1.76	13.55	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.48	14.96	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:3	31.36	2043	1.77	13.56	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.46	15	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:3	31.36	2050	1.78	13.57	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.39	15.03	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:3	31.36	2050	1.79	13.57	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.68	Lean	1	14.6	-7.31	15.04	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:3	31.36	2048	1.79	13.57	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.71	Lean	1	14.6	-7.27	15.04	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:19:4	31.36	2047	1.8	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.19	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:19:4	31.36	2047	1.81	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.06	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:19:4	31.36	2046	1.82	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.05	15.09	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:4	31.36	2046	1.83	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.03	15.07	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:4	31.36	2044	1.83	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.98	15.05	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:4	31.36	2045	1.84	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.97	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:19:4	31.36	2046	1.85	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.96	14.97	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:19:5	31.36	2051	1.85	13.56	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.92	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:5	31.36	2066	1.86	13.59	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.91	14.9	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:5	31.36	2066	1.86	13.59	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.9	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:5	31.36	2050	1.87	13.59	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.88	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:5	31.36	2059	1.87	13.57	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.84	14.75	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:5	31.36	2059	1.88	13.56	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.79	14.76	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:6	31.36	2052	1.89	13.57	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.64	14.74	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:19:6	31.36	2066	1.89	13.58	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.58	14.73	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:19:6	31.36	2066	1.9	13.6	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.56	14.73	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:6	31.36	2068	1.9	13.61	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.56	14.77	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:6	31.36	2070	1.91	13.62	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.55	14.77	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:19:6	31.36	2061	1.91	13.6	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.56	14.77	1.01	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:19:6	31.36	2061	1.91	13.6	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.54	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:19:7	31.36	2064	1.92	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.5	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:19:7	31.36	2064	1.92	13.55	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.46	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:19:7	31.36	2064	1.93	13.55	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.39	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:7	31.36	2060	1.93	13.55	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.27	14.83	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:7	31.36	2072	1.94	13.56	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.2	14.83	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:7	31.36	2074	1.94	13.57	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.15	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:8	31.36	2074	1.95	13.58	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.14	14.8	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:8	31.36	2088	1.95	13.6	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.15	14.8	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:8	31.36	2066	1.95	13.6	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.14	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:8	31.36	2063	1.96	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.15	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:8	31.36	2050	1.96	13.61	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.17	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:8	31.36	2049	1.97	13.6	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.18	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:9	31.36	2049	1.97	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.18	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:9	31.36	2052	1.97	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.15	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:9	31.36	2059	1.97	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.17	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:9	31.36	2060	1.97	13.55	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.16	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:9	31.36	2064	1.97	13.55	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.14	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:19:9	31.36	2087	1.97	13.55	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.09	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:19:9	31.36	2079	1.97	13.56	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.06	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:0	31.36	2080	1.97	13.56	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.68	Lean	1	14.7	-6.01	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:0	31.36	2082	1.97	13.58	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.99	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:0	31.36	2081	1.97	13.59	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.02	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:0	31.36	2081	1.97	13.6	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.05	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:0	31.36	2074	1.97	13.58	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.12	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:0	31.36	2070	1.97	13.58	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.17	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:1	31.36	2068	1.97	13.56	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.17	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:1	31.36	2059	1.97	13.55	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.16	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:1	31.36	2066	1.97	13.54	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.16	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:1	31.36	2071	1.97	13.55	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.1	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:20:1	31.36	2074	1.97	13.55	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.07	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:1	31.36	2079	1.97	13.56	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.05	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:1	31.36	2081	1.97	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.05	14.72	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:2	31.36	2082	1.97	13.58	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.07	14.7	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:2	31.36	2084	1.97	13.59	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.12	14.71	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:2	31.36	2085	1.97	13.6	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.15	14.72	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:2	31.36	2085	1.97	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.18	14.73	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:2	31.36	2086	1.97	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.18	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:2	31.36	2083	1.97	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.18	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:3	31.36	2084	1.97	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.18	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:3	31.36	2086	1.97	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.15	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:3	31.36	2092	1.97	13.56	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.12	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:3	31.36	2092	1.97	13.56	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.06	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:3	31.36	2097	1.97	13.57	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.02	14.83	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:3	31.36	2097	1.97	13.57	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.02	14.86	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:4	31.36	2103	1.97	13.58	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.05	14.89	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:4	31.36	2104	1.97	13.58	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.1	14.91	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:4	31.36	2102	1.97	13.58	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.15	14.95	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:4	31.36	2095	1.97	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.16	14.99	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:4	31.36	2080	1.97	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.2	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:4	31.36	2082	1.97	13.56	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.15	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:4	31.36	2082	1.97	13.54	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.13	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:5	31.36	2077	1.98	13.55	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	-6.11	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:5	31.36	2076	1.98	13.56	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.06	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:5	31.36	2076	1.98	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.03	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:5	31.36	2080	1.98	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.06	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:5	31.36	2085	1.98	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.09	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:5	31.36	2088	1.98	13.62	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.14	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:6	31.36	2097	1.98	13.62	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.15	15.08	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:6	31.36	2100	1.97	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.15	15.05	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:6	31.36	2100	1.97	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.15	15.02	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:6	31.36	2104	1.98	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.12	15	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:6	31.36	2104	1.98	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.12	14.98	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:6	31.36	2104	1.98	13.58	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.11	14.98	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:6	31.36	2100	1.98	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.09	14.95	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:7	31.36	2098	1.98	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.1	14.87	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:7	31.36	2098	1.98	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.12	14.85	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:7	31.36	2096	1.98	13.58	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.17	14.83	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:7	31.36	2094	1.98	13.56	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.19	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:7	31.36	2097	1.98	13.55	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.21	14.82	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:7	31.36	2097	1.98	13.55	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.17	14.81	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:8	31.36	2099	1.97	13.56	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.13	14.8	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:8	31.36	2101	1.97	13.57	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.1	14.8	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:8	31.36	2101	1.97	13.59	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.12	14.81	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:8	31.36	2106	1.97	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.13	14.83	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:8	31.36	2107	1.97	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.17	14.84	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:8	31.36	2108	1.97	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.24	14.89	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:20:9	31.36	2124	1.97	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.2	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:9	31.36	2114	1.97	13.56	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.15	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:9	31.36	2112	1.97	13.56	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.13	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:9	31.36	2112	1.97	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.14	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:9	31.36	2105	1.97	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.12	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:9	31.36	2115	1.97	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.16	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:20:9	31.36	2114	1.97	13.62	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.21	15.07	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:21:0	31.36	2117	1.97	13.62	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.23	15.09	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:0	31.36	2113	1.96	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.23	15.09	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:0	31.36	2112	1.96	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.22	15.06	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:0	31.36	2112	1.96	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.33	15.03	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:21:0	31.36	2113	1.95	13.61	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.35	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:0	31.36	2114	1.95	13.6	97	193	Off Idle	85.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.48	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:1	31.36	2114	1.95	13.59	97	193	Off Idle	85.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.53	14.91	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:1	31.36	2114	1.94	13.57	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.53	14.87	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:1	31.36	2109	1.94	13.57	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.53	14.83	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:1	31.36	2108	1.94	13.57	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.54	14.76	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:1	31.36	2109	1.93	13.59	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.54	14.7	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:1	31.36	2115	1.92	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.64	14.67	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:1	31.36	2114	1.92	13.59	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.71	14.64	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:2	31.36	2111	1.92	13.6	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.76	14.63	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:2	31.36	2131	1.91	13.59	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.77	14.63	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:2	31.36	2111	1.91	13.59	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.77	14.63	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:2	31.36	2108	1.9	13.59	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.8	14.64	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:2	31.36	2105	1.9	13.59	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.75	14.66	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:2	31.36	2087	1.89	13.6	97	193	Off Idle	85.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.75	14.67	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:3	31.36	2087	1.89	13.62	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.79	14.7	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:3	31.36	2107	1.89	13.6	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.84	14.71	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:3	31.36	2118	1.89	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.89	14.73	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:3	31.36	2123	1.89	13.58	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.9	14.75	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:3	31.36	2124	1.89	13.56	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.89	14.79	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:3	31.36	2127	1.88	13.56	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.86	14.83	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:4	31.36	2126	1.88	13.57	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.85	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:4	31.36	2119	1.88	13.57	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.81	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:4	31.36	2121	1.88	13.58	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.8	14.93	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:4	31.36	2129	1.88	13.59	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.81	14.95	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:4	31.36	2129	1.88	13.6	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.82	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:4	31.36	2130	1.88	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.82	15.03	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:4	31.36	2130	1.88	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.85	15.07	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:5	31.36	2132	1.88	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.88	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:5	32.72	2144	1.88	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.85	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:5	32.72	2124	1.88	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.85	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:5	32.72	2124	1.88	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.88	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:5	32.72	2124	1.89	13.6	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.85	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:5	32.72	2118	1.89	13.62	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.85	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:6	32.72	2112	1.89	13.61	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.86	15.05	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:6	32.72	2110	1.89	13.61	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.88	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:6	32.72	2105	1.89	13.6	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.89	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:6	32.72	2107	1.89	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.91	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:6	32.72	2108	1.89	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.94	15.04	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:6	32.72	2111	1.89	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.92	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:6	32.72	2113	1.89	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.86	14.99	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:7	32.72	2113	1.89	13.57	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.83	14.97	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:7	32.72	2120	1.89	13.59	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.83	14.94	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:7	31.36	2110	1.89	13.61	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.81	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:7	31.36	2110	1.89	13.61	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.84	14.84	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:7	31.36	2126	1.89	13.62	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.87	14.77	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:21:7	31.36	2132	1.89	13.63	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.88	14.74	1	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:8	31.36	2122	1.89	13.63	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.89	14.73	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:8	31.36	2122	1.89	13.61	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.93	14.73	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:8	31.36	2123	1.89	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.95	14.72	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:8	32.72	2143	1.89	13.57	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.91	14.73	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:8	32.72	2143	1.89	13.57	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.87	14.74	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:8	32.72	2130	1.89	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.18	Rich	1	14.6	-6.84	14.76	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:9	32.72	2128	1.89	13.61	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.84	14.76	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:9	32.72	2127	1.89	13.62	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.88	14.77	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:21:9	32.72	2127	1.89	13.61	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.92	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:9	32.72	2140	1.89	13.6	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.92	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:9	32.72	2132	1.89	13.6	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.89	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:21:9	32.72	2134	1.89	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.9	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:21:9	32.72	2141	1.89	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.88	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:0	32.72	2109	1.89	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.88	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:0	32.72	2124	1.89	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.86	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:0	32.72	2136	1.89	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.85	15.03	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:0	32.72	2136	1.89	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.22	Rich	1	14.6	-6.84	15.1	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:0	32.72	2133	1.89	13.59	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.82	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:0	31.36	2123	1.89	13.61	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.79	15.15	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:1	31.36	2123	1.89	13.62	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.82	15.14	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:1	31.36	2125	1.89	13.62	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.84	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:1	31.36	2119	1.9	13.63	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.86	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:1	31.36	2119	1.9	13.62	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.85	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:1	31.36	2137	1.9	13.61	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.89	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:1	31.36	2125	1.9	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.88	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:1	32.72	2134	1.9	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.85	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:2	32.72	2134	1.9	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.8	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:2	32.72	2125	1.9	13.56	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.78	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:2	32.72	2125	1.9	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.72	15.01	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:2	32.72	2141	1.9	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.7	15	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:2	32.72	2142	1.9	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.73	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:2	31.36	2123	1.9	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.77	14.95	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:3	31.36	2123	1.9	13.6	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.83	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:3	31.36	2136	1.9	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.83	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:3	31.36	2132	1.9	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.83	14.83	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:3	31.36	2132	1.9	13.56	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.8	14.8	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:3	31.36	2124	1.9	13.58	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.71	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:3	31.36	2159	1.91	13.58	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.71	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:4	31.36	2132	1.91	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.74	14.78	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:4	32.72	2142	1.91	13.62	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.74	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:4	32.72	2140	1.91	13.62	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.78	14.78	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:4	32.72	2145	1.91	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.79	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:4	32.72	2145	1.91	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.77	14.81	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:4	32.72	2144	1.91	13.59	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.76	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:4	32.72	2145	1.91	13.6	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.75	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:5	32.72	2138	1.91	13.59	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.76	14.9	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:5	31.36	2128	1.91	13.59	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.81	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:5	31.36	2136	1.91	13.58	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.82	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:5	31.36	2131	1.91	13.57	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.84	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:5	31.36	2131	1.91	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.81	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:5	31.36	2120	1.91	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.77	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:6	31.36	2133	1.91	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.76	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:6	31.36	2136	1.91	13.6	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.78	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:6	31.36	2142	1.91	13.59	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.8	15.14	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:6	31.36	2150	1.91	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.78	15.16	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:6	31.36	2146	1.91	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.79	15.15	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:6	31.36	2151	1.91	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.75	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:6	31.36	2156	1.91	13.57	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.73	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:7	31.36	2156	1.91	13.58	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.7	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:7	31.36	2160	1.91	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.72	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:7	32.72	2168	1.91	13.6	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.73	14.89	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:7	32.72	2158	1.91	13.61	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.74	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:7	32.72	2158	1.91	13.6	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.75	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:7	32.72	2152	1.91	13.6	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.75	14.72	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:8	32.72	2152	1.91	13.6	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.72	14.67	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:8	32.72	2152	1.92	13.6	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.7	14.65	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:8	32.72	2155	1.92	13.61	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.69	14.65	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:8	32.72	2169	1.92	13.61	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.74	14.68	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:8	32.72	2152	1.92	13.6	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.75	14.69	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:22:8	32.72	2152	1.92	13.59	97	194	Off Idle	85.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.74	14.7	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:9	32.72	2149	1.92	13.59	97	194	Off Idle	85.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.73	14.71	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:9	32.72	2132	1.92	13.6	97	194	Off Idle	85.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.69	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:9	32.72	2140	1.92	13.6	97	194	Off Idle	85.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.66	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:22:9	32.72	2137	1.92	13.62	97	194	Off Idle	85.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.66	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:9	31.36	2137	1.92	13.62	97	194	Off Idle	85.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.71	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:9	31.36	2146	1.92	13.6	97	194	Off Idle	85.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.72	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:22:9	31.36	2142	1.93	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.71	14.98	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:0	31.36	2150	1.93	13.57	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.68	15.02	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:0	31.36	2150	1.93	13.56	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.65	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:0	31.36	2151	1.93	13.58	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.63	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:0	31.36	2170	1.93	13.58	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.64	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:0	31.36	2163	1.93	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.67	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:0	31.36	2159	1.93	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.73	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:1	31.36	2156	1.93	13.59	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.73	15.08	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:1	31.36	2155	1.93	13.58	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.71	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:1	31.36	2155	1.93	13.57	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.68	15.05	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:1	31.36	2158	1.93	13.6	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.65	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:1	31.36	2159	1.93	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.63	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:1	31.36	2158	1.93	13.62	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.65	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:1	31.36	2156	1.93	13.62	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.71	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:2	31.36	2151	1.93	13.61	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.71	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:2	31.36	2151	1.93	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.7	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:2	31.36	2153	1.93	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.68	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:2	31.36	2163	1.93	13.58	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.67	14.77	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:2	31.36	2164	1.93	13.6	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.65	14.76	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:2	32.72	2185	1.93	13.61	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.7	14.74	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:3	32.72	2172	1.93	13.6	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-6.74	14.75	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:3	32.72	2172	1.93	13.59	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.74	14.75	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:3	32.72	2174	1.93	13.58	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.74	14.75	1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:3	32.72	2172	1.93	13.59	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.72	14.77	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:3	32.72	2168	1.93	13.61	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.68	14.79	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:3	32.72	2167	1.93	13.59	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.68	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:4	31.36	2146	1.93	13.6	96	194	Off Idle	85.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.7	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:4	31.36	2161	1.93	13.59	96	194	Off Idle	85.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.69	14.9	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:23:4	31.36	2160	1.93	13.59	96	194	Off Idle	84.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.7	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:23:4	31.36	2159	1.93	13.57	96	194	Off Idle	84.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.7	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:4	31.36	2161	1.93	13.57	96	194	Off Idle	84.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.68	15.02	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:4	31.36	2161	1.93	13.57	97	194	Off Idle	84.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.67	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:4	31.36	2164	1.94	13.58	97	193	Off Idle	84.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.63	15.1	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:5	31.36	2161	1.94	13.59	97	193	Off Idle	84.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.57	15.11	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:23:5	31.36	2162	1.94	13.59	97	193	Off Idle	84.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.54	15.11	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:5	31.36	2162	1.95	13.6	97	194	Off Idle	84.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.51	15.1	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:23:5	31.36	2161	1.95	13.59	97	194	Off Idle	84.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.52	15.1	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:23:5	31.36	2162	1.95	13.58	97	194	Off Idle	84.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.47	15.11	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:23:5	31.36	2163	1.96	13.56	97	194	Off Idle	84.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.4	15.1	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:23:6	31.36	2164	1.96	13.57	97	194	Off Idle	84.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.35	15.07	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:23:6	31.36	2164	1.97	13.58	97	194	Off Idle	84.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.3	15.04	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:23:6	31.36	2165	1.97	13.59	97	194	Off Idle	84.9	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.23	15.03	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:23:6	31.36	2165	1.98	13.6	97	194	Off Idle	85.1	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.2	15.01	1.02	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:23:6	31.36	2164	1.99	13.61	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.21	14.99	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:23:6	31.36	2169	1.99	13.6	97	194	Off Idle	85.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.17	14.97	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:23:6	31.36	2174	2	13.59	97	194	Off Idle	84.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.07	14.95	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:23:7	31.36	2176	2.01	13.58	97	194	Off Idle	84.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.01	14.93	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:23:7	32.72	2197	2.02	13.57	97	194	Off Idle	85	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.89	14.89	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:23:7	32.72	2184	2.04	13.58	97	194	Off Idle	85	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.69	14.85	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:22:23:7	32.72	2186	2.05	13.59	97	194	Off Idle	85	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.63	14.84	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:22:23:7	32.72	2192	2.06	13.58	97	194	Off Idle	84.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.53	14.82	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:23:7	32.72	2194	2.07	13.58	97	194	Off Idle	84.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.4	14.81	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:23:8	32.72	2194	2.08	13.59	96	194	Off Idle	84.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.37	14.82	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:23:8	32.72	2191	2.09	13.59	96	194	Off Idle	84.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.24	14.84	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:23:8	31.36	2178	2.11	13.59	96	194	Off Idle	84.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.18	14.85	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:23:8	31.36	2182	2.12	13.59	97	194	Off Idle	84.1	0	2	132	944 Turbo	0.11	Lean	1	14.7	-5.12	14.87	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:23:8	31.36	2182	2.13	13.58	97	194	Off Idle	84.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.08	14.9	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:23:8	31.36	2184	2.14	13.58	97	194	Off Idle	83.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5	14.94	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:23:9	31.36	2186	2.15	13.58	97	194	Off Idle	83.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.96	14.96	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:23:9	31.36	2187	2.16	13.58	97	194	Off Idle	84	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.91	14.99	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:23:9	31.36	2186	2.17	13.59	97	194	Off Idle	84	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.89	15.02	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:23:9	31.36	2186	2.18	13.6	97	194	Off Idle	83.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.89	15.03	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:23:9	31.36	2190	2.18	13.6	97	194	Off Idle	83.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.89	15.04	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:23:9	31.36	2190	2.19	13.59	97	194	Off Idle	83.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-4.87	15.05	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:23:9	31.36	2192	2.19	13.59	97	194	Off Idle	83.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.85	15.09	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:0	31.36	2188	2.2	13.6	97	194	Off Idle	83.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.77	15.08	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:0	31.36	2185	2.2	13.61	97	194	Off Idle	83.7	0	2	132	944 Turbo	0.74	Rich	1	14.7	-4.77	14.92	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:0	31.36	2185	2.2	13.61	97	194	Off Idle	83.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.81	14.91	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:0	31.36	2188	2.2	13.58	97	194	Off Idle	83.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.83	14.87	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:0	31.36	2195	2.2	13.57	97	194	Off Idle	83.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.82	14.82	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:0	31.36	2195	2.2	13.57	97	194	Off Idle	83.8	0	2	132	944 Turbo	0.78	Rich	1	14.7	-4.81	14.75	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:1	31.36	2206	2.2	13.58	97	194	Off Idle	83.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.8	14.69	1	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:1	31.36	2207	2.2	13.57	97	194	Off Idle	83.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.77	14.59	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:1	31.36	2207	2.2	13.58	97	194	Off Idle	83.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.75	14.49	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:1	31.36	2207	2.2	13.58	97	194	Off Idle	83.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.77	14.42	0.98	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:1	31.36	2203	2.2	13.59	97	194	Off Idle	83.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.74	14.48	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:1	31.36	2198	2.2	13.59	97	194	Off Idle	83.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.7	14.44	0.98	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:1	31.36	2198	2.2	13.59	97	194	Off Idle	83.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.68	14.42	0.98	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:2	31.36	2194	2.2	13.59	97	194	Off Idle	82.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.7	14.41	0.98	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:2	31.36	2196	2.21	13.59	97	194	Off Idle	82.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.69	14.44	0.98	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:2	31.36	2196	2.21	13.58	97	194	Off Idle	82.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.67	14.48	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:2	31.36	2200	2.21	13.57	97	194	Off Idle	82.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.66	14.49	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:2	31.36	2207	2.21	13.57	97	194	Off Idle	82.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.6	14.55	0.99	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:2	31.36	2207	2.22	13.57	97	194	Off Idle	82.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.57	14.57	0.99	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:24:3	31.36	2218	2.22	13.6	96	194	Off Idle	82.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.51	14.63	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:24:3	31.36	2214	2.22	13.6	96	194	Off Idle	82.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.49	14.67	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:24:3	31.36	2235	2.23	13.59	96	194	Off Idle	82.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.45	14.71	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:24:3	31.36	2235	2.23	13.59	97	194	Off Idle	82.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.42	14.73	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:24:3	31.36	2218	2.24	13.59	97	194	Off Idle	82.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.36	14.77	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:3	31.36	2212	2.25	13.57	97	194	Off Idle	82.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.25	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:24:4	31.36	2213	2.25	13.57	97	194	Off Idle	82.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.17	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:24:4	31.36	2215	2.26	13.58	97	194	Off Idle	82.2	0	2	132	944 Turbo	0.36	Lean	1	14.7	-4.11	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:24:4	31.36	2213	2.27	13.58	97	194	Off Idle	82.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.1	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:24:4	31.36	2213	2.28	13.57	97	194	Off Idle	82.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.04	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:24:4	31.36	2222	2.29	13.58	97	194	Off Idle	82.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.93	14.81	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:24:4	31.36	2226	2.29	13.58	97	194	Off Idle	81.9	0	2	132	944 Turbo	0.14	Lean	1	14.7	-3.86	14.82	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:24:4	31.36	2229	2.3	13.58	97	194	Off Idle	81.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-3.83	14.86	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:24:5	31.36	2229	2.31	13.59	97	194	Off Idle	81.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.75	14.89	1.01	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:24:5	31.36	2232	2.32	13.59	97	194	Off Idle	81.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.7	14.9	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:24:5	31.36	2232	2.33	13.59	97	194	Off Idle	81.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	-3.55	14.94	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:24:5	31.36	2231	2.33	13.58	97	194	Off Idle	81.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.49	14.97	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:24:5	31.36	2227	2.34	13.59	97	194	Off Idle	81.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-3.43	15.01	1.02	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:24:5	31.36	2224	2.35	13.59	97	194	Off Idle	81.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.42	15.06	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:24:6	31.36	2224	2.36	13.59	97	194	Off Idle	81.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-3.37	15.1	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:24:6	31.36	2228	2.37	13.59	97	194	Off Idle	81.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-3.31	15.1	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:24:6	31.36	2236	2.37	13.6	97	194	Off Idle	81.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.26	15.09	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:24:6	31.36	2238	2.39	13.61	97	194	Off Idle	81.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.05	15.02	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:24:6	31.36	2238	2.39	13.63	97	194	Off Idle	81.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.96	14.97	1.02	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:24:6	31.36	2244	2.4	13.61	97	194	Off Idle	81.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.88	14.91	1.02	3.4	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:24:6	31.36	2248	2.41	13.6	97	194	Off Idle	81.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.79	14.84	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:7	31.36	2248	2.42	13.59	97	193	Off Idle	81.1	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.76	14.77	1.01	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:7	31.36	2254	2.43	13.58	97	193	Off Idle	81.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.71	14.71	1	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:7	31.36	2257	2.44	13.56	97	194	Off Idle	81.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.65	14.56	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:7	31.36	2279	2.45	13.57	97	194	Off Idle	81.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.61	14.51	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:7	31.36	2279	2.45	13.57	97	194	Off Idle	81.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.59	14.46	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:7	31.36	2265	2.46	13.58	97	194	Off Idle	81.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.56	14.43	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:8	31.36	2263	2.47	13.57	97	194	Off Idle	81.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.5	14.43	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:24:8	31.36	2262	2.48	13.59	97	194	Off Idle	81.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.42	14.44	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:24:8	31.36	2260	2.49	13.6	97	194	Off Idle	80.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.37	14.46	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:24:8	31.36	2259	2.5	13.59	97	194	Off Idle	80.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.36	14.47	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:8	31.36	2259	2.5	13.58	97	194	Off Idle	80.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.24	14.47	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:8	31.36	2261	2.51	13.58	96	194	Off Idle	80.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.22	14.48	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:9	31.36	2272	2.52	13.58	96	194	Off Idle	80.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.12	14.48	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:9	31.36	2280	2.52	13.57	96	194	Off Idle	80.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.09	14.47	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:9	31.36	2280	2.53	13.56	97	194	Off Idle	80.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.01	14.46	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:24:9	31.36	2282	2.53	13.59	97	194	Off Idle	80	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.93	14.45	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:24:9	31.36	2280	2.54	13.59	97	194	Off Idle	79.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.87	14.42	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:9	31.36	2280	2.54	13.59	97	194	Off Idle	79.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.85	14.4	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:24:9	31.36	2278	2.55	13.59	97	194	Off Idle	79.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.75	14.38	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:0	31.36	2274	2.56	13.6	97	194	Off Idle	79.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.72	14.37	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:0	31.36	2276	2.56	13.59	97	194	Off Idle	79	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.7	14.35	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:0	31.36	2277	2.57	13.59	97	194	Off Idle	78.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.62	14.33	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:0	31.36	2279	2.57	13.6	97	194	Off Idle	78.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.6	14.31	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:0	31.36	2287	2.58	13.6	96	194	Off Idle	78.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.62	14.3	0.97	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:0	31.36	2287	2.58	13.59	96	194	Off Idle	78.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.67	14.29	0.97	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:1	31.36	2294	2.58	13.58	97	194	Off Idle	78.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.57	14.26	0.97	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:1	31.36	2300	2.59	13.59	97	194	Off Idle	78.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.56	14.22	0.97	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:1	31.36	2305	2.59	13.59	97	194	Off Idle	78.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.57	14.19	0.97	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:1	31.36	2305	2.59	13.57	97	194	Off Idle	78.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.58	14.19	0.97	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:1	31.36	2305	2.59	13.59	97	194	Off Idle	78.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.49	14.15	0.96	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:1	31.36	2305	2.6	13.59	97	194	Off Idle	78.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.53	14.11	0.96	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:1	31.36	2304	2.6	13.58	97	194	Off Idle	78.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.51	14.07	0.96	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:2	31.36	2305	2.6	13.59	97	194	Off Idle	78.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.48	14.02	0.96	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:2	31.36	2306	2.6	13.59	97	194	Off Idle	78.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.47	13.99	0.95	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:2	31.36	2306	2.61	13.58	97	194	Off Idle	78.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.52	13.94	0.95	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:2	31.36	2312	2.61	13.58	97	194	Off Idle	78.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	-1.52	13.91	0.95	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:25:2	31.36	2318	2.61	13.58	97	194	Off Idle	77.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.49	13.87	0.95	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:2	31.36	2318	2.61	13.57	97	194	Off Idle	77.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.53	13.87	0.94	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:3	31.36	2323	2.61	13.58	97	194	Off Idle	77.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.5	13.86	0.94	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:3	31.36	2328	2.61	13.58	97	194	Off Idle	77.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.5	13.86	0.94	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:3	31.36	2330	2.61	13.57	97	194	Off Idle	77.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.48	13.86	0.94	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:3	31.36	2332	2.62	13.59	97	194	Off Idle	77.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.5	13.87	0.94	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:25:3	31.36	2332	2.62	13.58	97	194	Off Idle	77	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.45	13.89	0.95	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:25:3	31.36	2335	2.62	13.59	97	194	Off Idle	76.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.5	13.91	0.95	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:4	31.36	2353	2.62	13.6	97	194	Off Idle	76.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.41	13.95	0.95	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:25:4	31.36	2344	2.63	13.6	97	194	Off Idle	76.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.43	13.98	0.95	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:25:4	31.36	2335	2.63	13.58	97	194	Off Idle	76.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.4	14.01	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:4	31.36	2341	2.63	13.59	97	194	Off Idle	76	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.42	14.03	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:4	31.36	2342	2.63	13.58	97	194	Off Idle	75.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.44	14.04	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:4	31.36	2342	2.63	13.58	97	194	Off Idle	75.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.44	14.04	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:4	31.36	2348	2.64	13.59	97	194	Off Idle	75.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.43	14.07	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:5	31.36	2350	2.64	13.6	97	194	Off Idle	75.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.42	14.09	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:5	31.36	2351	2.64	13.59	97	194	Off Idle	75.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.37	14.12	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:5	31.36	2352	2.64	13.59	97	194	Off Idle	75	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.33	14.14	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:5	31.36	2354	2.65	13.6	96	194	Off Idle	74.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.37	14.18	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:5	31.36	2354	2.65	13.59	96	194	Off Idle	74.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.36	14.21	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:5	31.36	2354	2.65	13.59	97	194	Off Idle	74.7	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.33	14.27	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:25:6	31.36	2354	2.65	13.6	97	194	Off Idle	74.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.33	14.3	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:6	31.36	2354	2.65	13.6	97	194	Off Idle	74.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.33	14.35	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:6	31.36	2354	2.65	13.58	97	194	Off Idle	74.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.3	14.39	0.98	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:6	31.36	2361	2.66	13.59	97	194	Off Idle	74.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.3	14.43	0.98	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:6	31.36	2366	2.66	13.59	97	194	Off Idle	74.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.3	14.45	0.98	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:6	31.36	2369	2.66	13.58	97	194	Off Idle	74.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.26	14.47	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:6	31.36	2371	2.66	13.57	97	194	Off Idle	74.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.25	14.49	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:7	31.36	2374	2.66	13.58	97	194	Off Idle	74.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.24	14.5	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:7	31.36	2375	2.67	13.58	97	194	Off Idle	74.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.22	14.51	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:7	31.36	2376	2.67	13.58	97	194	Off Idle	74.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.23	14.52	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:7	31.36	2379	2.67	13.58	97	194	Off Idle	74.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.2	14.53	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:7	31.36	2378	2.67	13.6	97	194	Off Idle	74.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.2	14.54	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:7	31.36	2377	2.67	13.6	97	194	Off Idle	74.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.23	14.54	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:8	31.36	2382	2.68	13.59	97	194	Off Idle	74.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-1.23	14.53	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:8	31.36	2387	2.68	13.59	97	194	Off Idle	74.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.19	14.54	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:8	31.36	2389	2.68	13.58	97	194	Off Idle	73.8	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.19	14.54	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:8	31.36	2416	2.68	13.59	97	194	Off Idle	73.8	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.17	14.55	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:8	31.36	2416	2.68	13.59	97	194	Off Idle	73.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.17	14.55	0.99	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:8	31.36	2406	2.69	13.59	97	194	Off Idle	73.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.21	14.56	0.99	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:9	31.36	2408	2.69	13.58	97	194	Off Idle	73.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.19	14.6	0.99	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:9	31.36	2408	2.69	13.58	97	194	Off Idle	72.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.14	14.6	0.99	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:9	31.36	2405	2.69	13.58	97	194	Off Idle	72.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.13	14.62	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:9	31.36	2410	2.69	13.57	97	194	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.13	14.65	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:9	31.36	2409	2.7	13.59	97	194	Off Idle	72.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.05	14.66	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:9	31.36	2409	2.7	13.58	97	194	Off Idle	72.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.03	14.66	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:25:9	31.36	2412	2.7	13.59	97	194	Off Idle	72	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.01	14.68	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:26:0	29.99	2408	2.71	13.58	97	194	Off Idle	72	0	2	132	944 Turbo	0.75	Rich	1	14.6	-0.96	14.71	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:26:0	29.99	2406	2.71	13.59	97	194	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.86	14.72	1	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:26:0	29.99	2401	2.71	13.58	97	194	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.6	-0.86	14.72	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:26:0	29.99	2408	2.72	13.59	97	194	Off Idle	72	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.7	14.71	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:26:0	29.99	2426	2.73	13.59	97	194	Off Idle	72	0	2	132	944 Turbo	0.67	Rich	1	14.6	-0.62	14.73	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:22:26:0	29.99	2426	2.73	13.59	97	194	Off Idle	71.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-0.54	14.74	1	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:22:26:1	29.99	2437	2.74	13.58	97	194	Off Idle	71.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-0.46	14.75	1	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:1	29.99	2440	2.74	13.59	97	194	Off Idle	71.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-0.35	14.76	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:1	29.99	2440	2.75	13.59	97	194	Off Idle	71.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-0.35	14.77	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:1	29.99	2442	2.76	13.57	97	194	Off Idle	71.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-0.28	14.78	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:1	29.99	2457	2.77	13.59	97	194	Off Idle	71.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-0.21	14.78	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:1	29.99	2447	2.77	13.59	97	194	Off Idle	71.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-0.17	14.84	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:22:26:1	29.99	2438	2.78	13.59	97	194	Off Idle	71.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-0.13	14.9	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:22:26:2	29.99	2433	2.78	13.59	97	194	Off Idle	71	0	2	132	944 Turbo	0.17	Lean	1	14.6	-0.08	14.95	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:22:26:2	29.99	2440	2.79	13.59	97	194	Off Idle	70.8	0	2	132	944 Turbo	0.21	Lean	1	14.7	-0.08	14.98	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:22:26:2	29.99	2440	2.79	13.58	97	194	Off Idle	70.6	0	2	132	944 Turbo	0.29	Lean	1	14.7	-0.12	15.03	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:2	29.99	2446	2.8	13.58	97	194	Off Idle	70.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-0.03	15.06	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:2	29.99	2456	2.8	13.57	97	194	Off Idle	70.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-0.02	15.11	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:2	29.99	2458	2.8	13.59	97	194	Off Idle	70.2	0	2	132	944 Turbo	0.46	Rich	1	14.7	0	15.18	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:3	29.99	2472	2.81	13.58	97	194	Off Idle	70	0	2	132	944 Turbo	0.53	Rich	1	14.7	-0.05	15.19	1.04	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:3	29.99	2466	2.81	13.6	97	194	Off Idle	70	0	2	132	944 Turbo	0.63	Rich	1	14.7	-0.04	15.18	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:3	29.99	2468	2.82	13.59	97	194	Off Idle	70	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.03	15.09	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:3	29.99	2468	2.82	13.59	97	194	Off Idle	69.9	0	2	132	944 Turbo	0.73	Rich	1	14.7	0.04	15.02	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:3	29.99	2465	2.82	13.58	97	194	Off Idle	69.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	0.05	14.93	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:3	29.99	2466	2.82	13.59	97	194	Off Idle	69.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.08	14.85	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:4	29.99	2458	2.82	13.59	97	194	Off Idle	69.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	0.08	14.79	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:4	29.99	2458	2.82	13.59	97	194	Off Idle	69.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	0.11	14.73	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:4	29.99	2460	2.83	13.57	97	194	Off Idle	69.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	0.1	14.64	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:4	29.99	2463	2.83	13.58	97	194	Off Idle	69.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.16	14.58	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:4	29.99	2478	2.83	13.57	97	194	Off Idle	69	0	2	132	944 Turbo	0.67	Rich	1	14.6	0.19	14.58	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:4	29.99	2491	2.83	13.58	97	194	Off Idle	68.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	0.19	14.59	0.99	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:22:26:4	29.99	2491	2.83	13.59	97	194	Off Idle	68.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	0.17	14.61	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:26:5	29.99	2502	2.83	13.59	97	194	Off Idle	68.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	0.2	14.65	1	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:22:26:5	29.99	2493	2.84	13.59	97	194	Off Idle	68.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	0.17	14.67	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:26:5	29.99	2492	2.84	13.59	97	194	Off Idle	67.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	0.2	14.69	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:26:5	29.99	2493	2.84	13.59	97	194	Off Idle	67.5	0	2	132	944 Turbo	0.36	Rich	1	14.7	0.18	14.71	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:26:5	29.99	2496	2.84	13.59	97	194	Off Idle	67.4	0	2	132	944 Turbo	0.35	Rich	1	14.7	0.2	14.76	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:26:5	29.99	2495	2.85	13.58	97	194	Off Idle	67.2	0	2	132	944 Turbo	0.36	Rich	1	14.7	0.24	14.8	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:6	29.99	2496	2.85	13.59	97	194	Off Idle	67.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	0.27	14.84	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:6	29.99	2504	2.85	13.58	96	194	Off Idle	67.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	0.28	14.91	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:6	29.99	2504	2.85	13.59	96	194	Off Idle	67.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	0.3	14.94	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:6	29.99	2504	2.85	13.57	96	194	Off Idle	67.1	0	2	132	944 Turbo	0.54	Rich	1	14.7	0.28	14.94	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:6	29.99	2506	2.85	13.58	96	194	Off Idle	66.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	0.33	14.96	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:6	29.99	2514	2.86	13.57	96	194	Off Idle	66.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	0.34	14.96	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:6	29.99	2514	2.86	13.57	96	194	Off Idle	66.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	0.35	14.95	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:7	29.99	2512	2.86	13.58	96	194	Off Idle	66.1	0	2	132	944 Turbo	0.73	Rich	1	14.7	0.38	14.92	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:26:7	29.99	2512	2.86	13.59	96	194	Off Idle	66.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	0.38	14.89	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:7	29.99	2518	2.87	13.58	96	194	Off Idle	66.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	0.42	14.87	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:7	29.99	2520	2.87	13.58	96	194	Off Idle	66.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	0.41	14.82	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:7	29.99	2527	2.87	13.59	96	194	Off Idle	66.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	0.47	14.77	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:22:26:7	29.99	2535	2.88	13.58	96	194	Off Idle	66.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	0.47	14.78	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:26:8	29.99	2535	2.88	13.57	97	194	Off Idle	66.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	0.57	14.77	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:26:8	29.99	2548	2.89	13.58	97	194	Off Idle	66	0	2	132	944 Turbo	0.51	Rich	1	14.7	0.57	14.77	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:26:8	29.99	2548	2.89	13.59	97	194	Off Idle	65.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	0.64	14.77	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:26:8	29.99	2546	2.89	13.59	97	194	Off Idle	65.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	0.69	14.79	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:26:8	29.99	2572	2.9	13.59	97	194	Off Idle	65.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	0.71	14.81	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:26:8	29.99	2557	2.9	13.58	97	194	Off Idle	65.2	0	2	132	944 Turbo	0.32	Rich	1	14.7	0.75	14.85	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:26:9	29.99	2558	2.9	13.58	97	194	Off Idle	65.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	0.82	14.87	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:26:9	29.99	2555	2.91	13.59	97	194	Off Idle	64.9	0	2	132	944 Turbo	0.34	Rich	1	14.6	0.81	14.9	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:26:9	29.99	2535	2.91	13.59	97	194	Off Idle	64.7	0	2	132	944 Turbo	0.36	Rich	1	14.7	0.79	14.92	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:26:9	28.63	2552	2.92	13.58	96	194	Off Idle	64.2	0	2	132	944 Turbo	0.42	Rich	1	14.7	0.82	15	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:26:9	28.63	2552	2.92	13.57	96	194	Off Idle	64	0	2	132	944 Turbo	0.49	Rich	1	14.6	0.91	15.01	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:26:9	28.63	2554	2.93	13.57	96	194	Off Idle	63.9	0	2	132	944 Turbo	0.55	Rich	1	14.7	0.96	15.04	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:26:9	28.63	2551	2.93	13.57	96	194	Off Idle	63.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	1.02	15.04	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:27:0	29.99	2551	2.93	13.58	96	194	Off Idle	63.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	0.99	15.02	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:27:0	29.99	2554	2.93	13.58	96	194	Off Idle	63.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	1.03	14.99	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:0	29.99	2567	2.94	13.58	96	194	Off Idle	63.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	1	14.95	1.02	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:0	29.99	2570	2.94	13.57	96	194	Off Idle	63	0	2	132	944 Turbo	0.75	Rich	1	14.7	1	14.91	1.02	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:0	28.63	2579	2.94	13.57	97	194	Off Idle	63	0	2	132	944 Turbo	0.76	Rich	1	14.6	0.98	14.82	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:0	28.63	2584	2.94	13.56	97	194	Off Idle	62.9	0	2	132	944 Turbo	0.76	Rich	1	14.7	1.03	14.8	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:1	28.63	2583	2.95	13.56	97	194	Off Idle	62.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	1.05	14.73	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:1	28.63	2581	2.95	13.58	96	194	Off Idle	62.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	1.03	14.72	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:1	28.63	2584	2.95	13.59	96	194	Off Idle	62.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	1.05	14.71	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:1	29.99	2583	2.95	13.58	96	194	Off Idle	62.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.11	14.71	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:1	29.99	2583	2.95	13.6	96	194	Off Idle	62.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	1.12	14.72	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:1	29.99	2592	2.96	13.61	96	194	Off Idle	62.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	1.08	14.73	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:1	29.99	2599	2.96	13.61	96	194	Off Idle	62.1	0	2	132	944 Turbo	0.6	Rich	1	14.7	1.1	14.75	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:2	28.63	2592	2.96	13.6	97	194	Off Idle	62.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	1.17	14.79	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:2	28.63	2608	2.96	13.6	97	194	Off Idle	61.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	1.09	14.8	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:2	28.63	2612	2.97	13.59	97	194	Off Idle	61.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	1.19	14.79	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:2	28.63	2612	2.97	13.58	97	194	Off Idle	61.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	1.22	14.78	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:2	28.63	2620	2.97	13.59	97	194	Off Idle	61.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	1.18	14.8	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:27:2	28.63	2622	2.97	13.59	97	194	Off Idle	61	0	2	132	944 Turbo	0.23	Lean	1	14.6	1.2	14.83	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:27:3	28.63	2622	2.97	13.6	97	194	Off Idle	61	0	2	132	944 Turbo	0.22	Lean	1	14.6	1.22	14.86	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:27:3	28.63	2625	2.98	13.58	97	194	Off Idle	60.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	1.25	14.89	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:27:3	28.63	2624	2.98	13.56	97	194	Off Idle	60.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	1.21	14.91	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:3	28.63	2634	2.98	13.56	97	194	Off Idle	60	0	2	132	944 Turbo	0.37	Rich	1	14.7	1.3	14.98	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:3	28.63	2634	2.99	13.56	97	194	Off Idle	59.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	1.32	15	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:3	28.63	2634	2.99	13.56	97	194	Off Idle	59.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	1.34	15.04	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:4	28.63	2644	2.99	13.57	96	194	Off Idle	59.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	1.33	15.06	1.03	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:27:4	28.63	2635	3	13.6	96	194	Off Idle	59.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	1.31	15.04	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:4	28.63	2644	3	13.59	96	194	Off Idle	59.2	0	2	132	944 Turbo	0.68	Rich	1	14.7	1.35	15.01	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:4	28.63	2639	3	13.59	96	194	Off Idle	59.1	0	2	132	944 Turbo	0.72	Rich	1	14.7	1.43	14.96	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:4	28.63	2642	3	13.59	96	194	Off Idle	58.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.39	14.91	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:4	28.63	2644	3	13.58	96	194	Off Idle	58.8	0	2	132	944 Turbo	0.74	Rich	1	14.7	1.42	14.88	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:4	28.63	2656	3.01	13.58	96	194	Off Idle	58.7	0	2	132	944 Turbo	0.75	Rich	1	14.7	1.48	14.83	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:5	28.63	2639	3.01	13.59	96	194	Off Idle	58.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.43	14.75	1	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:5	28.63	2642	3.01	13.58	96	194	Off Idle	58.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.44	14.7	1	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:5	28.63	2642	3.01	13.57	96	194	Off Idle	58.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	1.44	14.7	1	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:5	28.63	2651	3.01	13.57	96	194	Off Idle	58.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	1.51	14.7	1	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:5	28.63	2652	3.01	13.56	96	194	Off Idle	58.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	1.53	14.7	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:27:5	28.63	2652	3.02	13.57	96	194	Off Idle	58.2	0	2	132	944 Turbo	0.67	Rich	1	14.7	1.53	14.72	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:27:6	28.63	2665	3.02	13.59	96	194	Off Idle	58.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	1.59	14.74	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:27:6	28.63	2671	3.02	13.57	96	194	Off Idle	58	0	2	132	944 Turbo	0.59	Rich	1	14.6	1.59	14.77	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:27:6	28.63	2677	3.02	13.57	96	194	Off Idle	58	0	2	132	944 Turbo	0.51	Rich	1	14.7	1.57	14.78	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:27:6	28.63	2679	3.02	13.59	96	194	Off Idle	57.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	1.53	14.81	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:27:6	28.63	2687	3.03	13.58	96	194	Off Idle	57.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	1.51	14.81	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:27:6	28.63	2686	3.03	13.58	96	194	Off Idle	57.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	1.59	14.8	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:27:6	28.63	2686	3.03	13.58	96	194	Off Idle	57.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	1.58	14.81	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:7	28.63	2692	3.03	13.58	96	194	Off Idle	57.3	0	2	132	944 Turbo	0.27	Lean	1	14.7	1.6	14.85	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:7	28.63	2705	3.03	13.57	96	194	Off Idle	57.3	0	2	132	944 Turbo	0.27	Lean	1	14.7	1.68	14.86	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:7	28.63	2705	3.04	13.57	97	194	Off Idle	57.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	1.7	14.9	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:7	28.63	2711	3.04	13.56	97	194	Off Idle	57.2	0	2	132	944 Turbo	0.32	Lean	1	14.7	1.68	14.94	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:7	28.63	2709	3.04	13.55	97	194	Off Idle	57	0	2	132	944 Turbo	0.36	Lean	1	14.6	1.73	15.02	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:7	28.63	2700	3.05	13.57	96	194	Off Idle	56.9	0	2	132	944 Turbo	0.41	Lean	1	14.7	1.73	15.03	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:8	28.63	2700	3.05	13.58	96	194	Off Idle	56.7	0	2	132	944 Turbo	0.47	Lean	1	14.7	1.73	15.04	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:27:8	28.63	2687	3.05	13.58	96	194	Off Idle	56.1	0	2	132	944 Turbo	0.53	Rich	1	14.7	1.78	15.05	1.03	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:8	28.63	2695	3.05	13.58	96	194	Off Idle	55.8	0	2	132	944 Turbo	0.59	Rich	1	14.7	1.8	15.06	1.03	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:8	28.63	2695	3.06	13.57	96	194	Off Idle	55.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	1.87	15.03	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:8	28.63	2703	3.06	13.58	96	194	Off Idle	55.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	1.83	14.98	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:8	28.63	2716	3.06	13.56	96	194	Off Idle	55.2	0	2	132	944 Turbo	0.62	Rich	1	14.7	1.86	14.97	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:27:9	28.63	2701	3.06	13.58	96	194	Off Idle	55.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	1.88	14.95	1.02	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:27:9	28.63	2701	3.07	13.58	96	194	Off Idle	55	0	2	132	944 Turbo	0.52	Rich	1	14.7	1.87	14.9	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:22:27:9	27.27	2725	3.07	13.57	96	194	Off Idle	54.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	1.89	14.86	1.01	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:22:27:9	27.27	2728	3.07	13.58	96	194	Off Idle	54.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	1.94	14.81	1.01	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:22:27:9	27.27	2728	3.08	13.58	96	194	Off Idle	54.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	1.97	14.81	1.01	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:22:27:9	27.27	2738	3.08	13.58	96	194	Off Idle	54.5	0	2	132	944 Turbo	0.27	Lean	1	14.7	1.95	14.83	1.01	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:22:27:9	28.63	2740	3.08	13.56	96	194	Off Idle	54.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	2.01	14.85	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:0	28.63	2743	3.08	13.57	96	194	Off Idle	54.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	1.98	14.9	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:0	28.63	2743	3.09	13.57	96	194	Off Idle	54.1	0	2	132	944 Turbo	0.31	Lean	1	14.7	1.98	14.93	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:0	28.63	2741	3.09	13.56	96	194	Off Idle	54	0	2	132	944 Turbo	0.36	Lean	1	14.6	2	14.99	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:0	28.63	2751	3.09	13.56	96	194	Off Idle	53.9	0	2	132	944 Turbo	0.44	Lean	1	14.7	2.01	15.02	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:0	28.63	2744	3.09	13.58	96	194	Off Idle	53.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	1.99	15.01	1.02	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:0	28.63	2744	3.1	13.56	96	194	Off Idle	53.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	1.99	15.02	1.02	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:1	28.63	2745	3.1	13.56	96	194	Off Idle	53.5	0	2	132	944 Turbo	0.63	Lean	1	14.7	2	14.99	1.02	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:1	28.63	2755	3.1	13.58	96	194	Off Idle	53.4	0	2	132	944 Turbo	0.69	Lean	1	14.7	1.98	14.95	1.02	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:1	28.63	2758	3.1	13.58	96	194	Off Idle	53.2	0	2	132	944 Turbo	0.73	Rich	1	14.7	2.04	14.89	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:1	28.63	2768	3.1	13.58	96	194	Off Idle	53.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.05	14.84	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:1	28.63	2773	3.11	13.59	96	194	Off Idle	52.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	2.1	14.8	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:1	28.63	2773	3.11	13.58	96	194	Off Idle	52.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.08	14.74	1	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:1	28.63	2777	3.11	13.57	97	194	Off Idle	52.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.13	14.69	1	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:2	28.63	2770	3.12	13.56	97	194	Off Idle	51.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.15	14.66	1	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:2	28.63	2771	3.12	13.56	97	194	Off Idle	51.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	2.14	14.67	1	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:28:2	28.63	2771	3.12	13.56	96	194	Off Idle	51.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.19	14.67	1	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:2	28.63	2781	3.12	13.57	96	194	Off Idle	51.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	2.21	14.7	1	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:2	28.63	2782	3.13	13.58	96	194	Off Idle	51.1	0	2	132	944 Turbo	0.74	Rich	1	14.7	2.13	14.71	1	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:2	28.63	2786	3.13	13.57	96	194	Off Idle	51	0	2	132	944 Turbo	0.75	Rich	1	14.6	2.16	14.68	1	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:3	28.63	2800	3.13	13.58	96	194	Off Idle	50.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	2.11	14.73	1	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:28:3	28.63	2808	3.13	13.57	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	2.2	14.7	1	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:3	28.63	2827	3.13	13.57	96	194	Off Idle	50.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	2.21	14.67	1	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:3	28.63	2827	3.14	13.56	96	194	Off Idle	50.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	2.23	14.61	0.99	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:3	28.63	2837	3.14	13.58	96	194	Off Idle	49.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	2.26	14.56	0.99	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:3	28.63	2855	3.14	13.58	96	194	Off Idle	49.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	2.29	14.49	0.99	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:4	28.63	2829	3.14	13.59	96	194	Off Idle	49.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	2.3	14.28	0.97	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:4	28.63	2829	3.15	13.58	96	194	Off Idle	49.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	2.3	14.13	0.96	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:4	28.63	2826	3.15	13.58	96	194	Off Idle	48.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.36	13.98	0.95	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:4	28.63	2825	3.15	13.57	96	194	Off Idle	48.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.32	13.87	0.95	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:4	28.63	2825	3.16	13.58	96	194	Off Idle	48.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.38	13.63	0.93	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:28:4	28.63	2826	3.16	13.58	96	194	Off Idle	48.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	2.36	13.52	0.92	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:4	28.63	2835	3.16	13.57	96	194	Off Idle	48.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.42	13.4	0.91	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:5	28.63	2843	3.16	13.57	96	194	Off Idle	48.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.42	13.3	0.91	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:5	28.63	2844	3.16	13.57	96	194	Off Idle	48.1	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.44	13.25	0.9	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:5	28.63	2846	3.16	13.57	96	194	Off Idle	48	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.4	13.22	0.9	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:5	28.63	2844	3.17	13.57	96	194	Off Idle	47.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.47	13.2	0.9	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:5	28.63	2844	3.17	13.57	96	194	Off Idle	47.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.42	13.19	0.9	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:5	28.63	2842	3.17	13.57	96	194	Off Idle	47.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.49	13.17	0.9	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:6	28.63	2846	3.17	13.56	96	194	Off Idle	47.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	2.52	13.16	0.9	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:6	28.63	2846	3.18	13.56	96	194	Off Idle	47.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	2.54	13.12	0.89	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:6	28.63	2846	3.18	13.56	96	194	Off Idle	47.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	2.59	13.08	0.89	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:6	28.63	2862	3.18	13.56	96	194	Off Idle	48	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.56	13.08	0.89	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:6	28.63	2865	3.18	13.56	96	194	Off Idle	48	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.56	13.06	0.89	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:6	28.63	2869	3.18	13.57	96	194	Off Idle	48	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.55	13.05	0.89	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:6	28.63	2880	3.18	13.59	96	194	Off Idle	47.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.48	13.03	0.89	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:7	28.63	2882	3.18	13.56	96	194	Off Idle	47.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.49	13.02	0.89	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:7	28.63	2884	3.19	13.58	96	194	Off Idle	47.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.44	13	0.89	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:7	28.63	2890	3.19	13.57	96	194	Off Idle	46.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.38	12.98	0.88	3.4	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:28:7	28.63	2885	3.19	13.57	96	194	Off Idle	46.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.46	12.97	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:7	28.63	2892	3.19	13.57	96	194	Off Idle	46.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.39	12.95	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:7	28.63	2881	3.19	13.57	96	194	Off Idle	46.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.44	12.93	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:8	27.27	2895	3.19	13.57	96	194	Off Idle	46.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.47	12.9	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:8	27.27	2899	3.19	13.58	96	194	Off Idle	45.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.5	12.89	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:8	27.27	2900	3.19	13.57	96	194	Off Idle	45.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.53	12.88	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:8	27.27	2904	3.2	13.57	96	194	Off Idle	45.3	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.63	12.87	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:8	27.27	2911	3.2	13.57	96	194	Off Idle	44.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.55	12.86	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:8	27.27	2911	3.2	13.58	96	194	Off Idle	44.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.63	12.87	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:9	27.27	2916	3.2	13.57	96	194	Off Idle	44.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.59	12.87	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:9	27.27	2917	3.2	13.58	96	194	Off Idle	44.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.54	12.89	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:9	27.27	2955	3.2	13.58	96	194	Off Idle	43.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.53	12.94	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:28:9	28.63	2944	3.2	13.56	96	194	Off Idle	43.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.6	12.95	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:28:9	28.63	2936	3.21	13.56	96	194	Off Idle	43.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.62	12.96	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:28:9	28.63	2936	3.21	13.55	96	194	Off Idle	43.3	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.59	12.98	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:28:9	28.63	2935	3.21	13.55	96	194	Off Idle	43	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.63	12.98	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:0	28.63	2936	3.21	13.56	96	194	Off Idle	42.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.63	12.97	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:0	28.63	2936	3.22	13.57	96	194	Off Idle	42.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.71	12.97	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:0	28.63	2939	3.22	13.57	96	194	Off Idle	42.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.7	12.97	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:0	28.63	2950	3.22	13.58	96	194	Off Idle	42.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.77	12.96	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:0	28.63	2971	3.22	13.57	96	194	Off Idle	42.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.73	12.93	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:0	28.63	2955	3.23	13.57	96	194	Off Idle	41.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.71	12.91	0.88	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:29:1	28.63	2955	3.23	13.58	96	194	Off Idle	41.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.71	12.9	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:1	28.63	2957	3.23	13.56	96	194	Off Idle	41.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.74	12.9	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:1	28.63	2961	3.23	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.72	12.89	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:1	28.63	2968	3.23	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.79	12.89	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:1	28.63	2971	3.23	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.73	12.89	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:1	28.63	2984	3.23	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.8	12.88	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:1	28.63	2994	3.24	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.72	12.89	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:2	28.63	2998	3.24	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.74	12.9	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:29:2	28.63	3002	3.24	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.73	12.91	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:2	28.63	3000	3.24	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.75	12.91	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:2	28.63	3002	3.24	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.77	12.91	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:2	28.63	3016	3.25	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.81	12.92	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:2	28.63	3003	3.25	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.88	12.92	0.88	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:3	28.63	3005	3.25	13.57	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.85	12.92	0.88	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:22:29:3	28.63	3004	3.25	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.94	12.93	0.88	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:22:29:3	28.63	2998	3.25	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.9	12.94	0.88	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:22:29:3	28.63	3011	3.25	13.55	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.99	12.95	0.88	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:22:29:3	28.63	3012	3.26	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	3	12.95	0.88	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:22:29:3	28.63	3012	3.26	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.97	12.95	0.88	3.4	6.8	ON	28 Pin	OFF	Removed	Disabled
03:22:29:4	28.63	3020	3.26	13.57	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.94	12.95	0.88	3.4	6.8	ON	28 Pin	OFF	Removed	Disabled
03:22:29:4	28.63	3021	3.26	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.93	12.96	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:4	28.63	3023	3.26	13.58	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.7	2.94	12.95	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:4	28.63	3030	3.26	13.57	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	2.85	12.97	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:4	28.63	3040	3.26	13.57	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	2.91	12.98	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:4	28.63	3040	3.26	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	2.84	12.99	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:4	28.63	3047	3.26	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	2.74	12.97	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:5	28.63	3047	3.26	13.55	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	2.62	12.95	0.88	3.4	6.7	ON	28 Pin	OFF	Removed	Disabled
03:22:29:5	28.63	3096	3.26	13.55	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	2.65	12.94	0.88	3.4	6.6	ON	28 Pin	OFF	Removed	Disabled
03:22:29:5	28.63	3073	3.26	13.55	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	2.46	12.95	0.88	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:29:5	28.63	3052	3.26	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.39	12.96	0.88	3.6	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:29:5	28.63	3053	3.26	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.33	12.95	0.88	3.6	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:29:5	28.63	3052	3.25	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.33	12.94	0.88	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:29:6	28.63	3052	3.25	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.29	12.91	0.88	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:29:6	28.63	3062	3.25	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.28	12.91	0.88	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:29:6	28.63	3071	3.25	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.25	12.91	0.88	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:22:29:6	28.63	3071	3.25	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.29	12.9	0.88	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:29:6	29.99	3082	3.24	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.21	12.9	0.88	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:29:6	29.99	3091	3.24	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.21	12.89	0.88	3.6	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:29:6	29.99	3090	3.24	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.25	12.87	0.88	3.6	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:29:7	29.99	3045	3.24	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.21	12.87	0.88	3.6	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:29:7	29.99	3100	3.24	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.28	12.87	0.88	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:29:7	29.99	3101	3.24	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.22	12.88	0.88	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:7	29.99	3103	3.23	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.18	12.89	0.88	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:29:7	29.99	3127	3.23	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.17	12.91	0.88	3.4	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:29:7	29.99	3105	3.23	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	2.13	12.93	0.88	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:8	29.99	3106	3.23	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.12	12.96	0.88	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:22:29:8	29.99	3106	3.23	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	2.03	12.96	0.88	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:8	29.99	3109	3.23	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	2.1	12.98	0.88	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:8	29.99	3109	3.23	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	2	12.99	0.88	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:8	29.99	3114	3.23	13.55	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.99	13	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:8	29.99	3124	3.23	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.97	13.02	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:9	29.99	3133	3.23	13.55	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	2	13.03	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:9	29.99	3133	3.24	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.91	13.05	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:9	29.99	3140	3.24	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.98	13.05	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:9	29.99	3142	3.24	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	1.9	13.06	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:9	29.99	3142	3.23	13.58	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	1.82	13.08	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:9	29.99	3148	3.23	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	1.84	13.09	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:29:9	29.99	3135	3.23	13.57	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.8	13.1	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:22:30:0	29.99	3134	3.23	13.55	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	1.71	13.11	0.89	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:0	29.99	3130	3.23	13.55	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.55	13.12	0.89	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:0	29.99	3137	3.22	13.55	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.52	13.13	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:22:30:0	29.99	3147	3.22	13.57	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.38	13.12	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:22:30:0	29.99	3148	3.21	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.3	13.11	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:22:30:0	31.36	3170	3.2	13.58	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.05	13.09	0.89	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:22:30:1	31.36	3167	3.2	13.57	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.93	13.06	0.89	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:22:30:1	31.36	3168	3.19	13.58	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.81	13.02	0.89	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:30:1	31.36	3179	3.19	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.68	12.98	0.88	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:22:30:1	31.36	3170	3.18	13.58	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.6	12.96	0.88	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:22:30:1	31.36	3173	3.17	13.57	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.54	12.94	0.88	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:22:30:1	31.36	3172	3.17	13.58	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.53	12.89	0.88	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:22:30:1	31.36	3168	3.16	13.56	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.45	12.86	0.88	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:30:2	31.36	3175	3.16	13.58	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.38	12.86	0.88	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:22:30:2	31.36	3178	3.15	13.58	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.34	12.85	0.88	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:2	31.36	3182	3.14	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.27	12.87	0.88	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:2	31.36	3183	3.14	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.2	12.91	0.88	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:2	31.36	3183	3.13	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.16	12.95	0.88	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:2	31.36	3187	3.12	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.13	13	0.89	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:3	31.36	3194	3.12	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.13	13.03	0.89	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:3	31.36	3198	3.11	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.02	13.06	0.89	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:3	32.72	3206	3.11	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.01	13.12	0.89	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:30:3	32.72	3214	3.1	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.11	13.15	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:30:3	32.72	3220	3.1	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.14	13.17	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:22:30:3	31.36	3206	3.1	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.21	13.19	0.9	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:4	31.36	3210	3.09	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.2	13.22	0.9	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:4	31.36	3204	3.09	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.24	13.25	0.9	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:4	31.36	3204	3.09	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.22	13.23	0.9	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:4	31.36	3228	3.09	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.29	13.22	0.9	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:4	32.72	3217	3.08	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.34	13.24	0.9	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:4	32.72	3217	3.08	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.38	13.24	0.9	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:4	32.72	3227	3.08	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.41	13.26	0.9	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:5	32.72	3222	3.08	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.48	13.27	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:5	32.72	3235	3.08	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.45	13.29	0.91	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:5	32.72	3235	3.07	13.55	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.46	13.31	0.91	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:5	32.72	3234	3.07	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.56	13.33	0.91	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:5	32.72	3233	3.07	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.59	13.35	0.91	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:5	32.72	3232	3.07	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.59	13.38	0.91	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:6	32.72	3229	3.07	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.72	13.4	0.91	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:6	32.72	3229	3.06	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.77	13.41	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:30:6	32.72	3234	3.06	13.58	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.81	13.42	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:30:6	32.72	3236	3.06	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.91	13.43	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:30:6	32.72	3242	3.05	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.98	13.43	0.92	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:22:30:6	32.72	3251	3.04	13.57	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.02	13.44	0.92	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:22:30:6	34.08	3251	3.04	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.22	13.44	0.92	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:30:7	34.08	3254	3.03	13.53	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.38	13.45	0.92	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:22:30:7	34.08	3254	3.02	13.51	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.54	13.43	0.92	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:22:30:7	34.08	3250	3.01	13.48	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.68	13.42	0.91	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:7	34.08	3252	3	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.79	13.42	0.91	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:7	34.08	3268	2.99	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.87	13.4	0.91	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:30:7	34.08	3255	2.98	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.91	13.38	0.91	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:8	34.08	3260	2.97	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.96	13.37	0.91	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:30:8	34.08	3262	2.96	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.02	13.36	0.91	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:30:8	34.08	3270	2.95	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.08	13.34	0.91	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:8	34.08	3272	2.94	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.21	13.32	0.91	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:8	34.08	3274	2.94	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.27	13.32	0.91	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:8	34.08	3278	2.93	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.41	13.35	0.91	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:9	34.08	3278	2.91	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.59	13.38	0.91	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:30:9	34.08	3277	2.9	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.63	13.43	0.91	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:30:9	34.08	3274	2.89	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.8	13.48	0.92	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:22:30:9	34.08	3296	2.87	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.99	13.58	0.93	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:30:9	34.08	3282	2.86	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.04	13.66	0.93	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:30:9	34.08	3263	2.84	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.2	13.73	0.94	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:30:9	34.08	3261	2.81	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.52	13.83	0.94	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:31:0	34.08	3283	2.79	13.42	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.77	13.89	0.95	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:31:0	35.45	3270	2.76	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.13	13.8	0.94	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:31:0	35.45	3252	2.74	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.52	13.82	0.94	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:31:0	35.45	3252	2.71	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.87	13.82	0.94	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:31:0	35.45	3252	2.68	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.19	13.82	0.94	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:31:0	35.45	3252	2.65	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.46	13.8	0.94	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:1	35.45	3234	2.62	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.7	13.78	0.94	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:31:1	35.45	3234	2.59	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.93	13.74	0.94	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:31:1	35.45	3232	2.54	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.11	13.7	0.93	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:31:1	35.45	3249	2.51	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.33	13.66	0.93	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:31:1	35.45	3250	2.48	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.45	13.66	0.93	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:31:1	35.45	3250	2.45	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.52	13.77	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:31:1	35.45	3256	2.42	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.64	13.79	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:31:2	35.45	3253	2.39	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.74	13.82	0.94	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:31:2	35.45	3253	2.36	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.85	13.88	0.95	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:31:2	36.81	3256	2.33	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.94	13.95	0.95	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:31:2	36.81	3265	2.31	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.04	14.05	0.96	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:31:2	36.81	3265	2.27	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.18	14.15	0.96	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:31:2	36.81	3266	2.25	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.28	14.31	0.97	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:31:3	36.81	3269	2.24	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.33	14.36	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:31:3	36.81	3267	2.22	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.48	14.55	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:31:3	36.81	3267	2.2	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.71	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:31:3	36.81	3268	2.18	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:31:3	36.81	3258	2.17	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.88	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:31:3	36.81	3256	2.14	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.04	15.24	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:31:4	36.81	3252	2.11	13.45	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.29	15.47	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:31:4	36.81	3253	2.08	13.44	96	195	Full Load	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.48	15.62	1.06	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:31:4	36.81	3251	2.06	13.44	96	195	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.7	15.75	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:4	36.81	3258	2.03	13.44	96	195	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.83	15.89	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:4	38.18	3239	2	13.43	96	195	Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.01	15.98	1.09	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:31:4	38.18	3236	1.97	13.44	96	195	Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.15	16.04	1.09	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:31:4	38.18	3219	1.95	13.46	96	195	Idle	41.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.22	16.05	1.09	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:31:5	38.18	3209	1.92	13.46	96	195	Idle	41.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.31	16.03	1.09	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:31:5	32.72	3180	1.9	13.45	96	195	Idle	41.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.38	15.99	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:5	32.72	3140	1.87	13.47	96	195	Idle	41.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	15.94	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:5	27.27	3121	1.84	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.54	15.83	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:5	21.81	3142	1.81	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.58	15.76	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:5	20.45	3154	1.79	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	15.68	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:6	20.45	3181	1.77	13.45	96	195	Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.6	15.65	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:6	20.45	3206	1.75	13.44	96	195	Idle	41.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.62	15.54	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:6	20.45	3210	1.73	13.46	96	195	Idle	41.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.65	15.46	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:6	20.45	3228	1.73	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.65	15.39	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:6	20.45	3260	1.71	13.46	96	194	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.7	15.33	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:6	20.45	3250	1.7	13.46	96	194	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.71	15.29	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:6	20.45	3242	1.7	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.7	15.29	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:7	20.45	3241	1.69	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	15.3	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:7	20.45	3236	1.69	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.64	15.34	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:7	20.45	3234	1.69	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.64	15.35	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:7	20.45	3226	1.69	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.6	15.41	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:7	20.45	3222	1.69	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.61	15.49	1.06	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:7	20.45	3222	1.69	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.59	15.57	1.06	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:8	20.45	3220	1.69	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.59	15.68	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:8	20.45	3215	1.69	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.59	15.79	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:8	20.45	3214	1.69	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.58	15.87	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:8	20.45	3209	1.69	13.45	96	195	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.57	15.97	1.09	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:8	20.45	3204	1.69	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	16.04	1.09	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:8	20.45	3203	1.69	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	16.07	1.09	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:9	20.45	3200	1.69	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	16.24	1.11	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:9	20.45	3188	1.69	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	16.4	1.12	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:9	20.45	3199	1.69	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	16.65	1.13	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:31:9	20.45	3197	1.7	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	17.19	1.17	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:9	20.45	3197	1.7	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	17.39	1.18	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:9	20.45	3198	1.7	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	17.98	1.22	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:31:9	20.45	3199	1.7	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	18.36	1.25	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:0	20.45	3199	1.7	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	18.55	1.26	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:0	20.45	3197	1.7	13.48	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	18.95	1.29	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:0	20.45	3221	1.7	13.47	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	19.32	1.32	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:0	20.45	3221	1.7	13.47	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	19.67	1.34	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:0	20.45	3192	1.7	13.47	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.07	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:0	20.45	3188	1.7	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:1	20.45	3186	1.7	13.49	96	195	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:1	20.45	3186	1.7	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:1	20.45	3176	1.7	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:1	20.45	3196	1.7	13.48	96	195	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:1	20.45	3189	1.7	13.46	96	195	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:1	20.45	3165	1.7	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:1	20.45	3171	1.7	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:2	20.45	3171	1.7	13.45	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:2	20.45	3166	1.71	13.46	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:2	20.45	3161	1.71	13.45	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:2	20.45	3158	1.71	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:2	20.45	3151	1.71	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:2	20.45	3198	1.71	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:3	20.45	3174	1.71	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:3	20.45	3148	1.71	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:3	20.45	3150	1.71	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:3	20.45	3150	1.71	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:3	20.45	3166	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:3	20.45	3159	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:4	20.45	3159	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:4	20.45	3160	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:4	20.45	3159	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:4	20.45	3158	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:4	20.45	3141	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:4	20.45	3147	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:4	20.45	3140	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:5	20.45	3140	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:5	20.45	3134	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:5	20.45	3138	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:5	20.45	3136	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:5	20.45	3138	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:5	20.45	3141	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:6	20.45	3143	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:6	20.45	3160	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:6	20.45	3150	1.71	13.45	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:6	20.45	3150	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:6	20.45	3150	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:6	20.45	3148	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:6	20.45	3142	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:7	20.45	3134	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:7	20.45	3134	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:7	20.45	3113	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:7	20.45	3118	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:7	20.45	3109	1.71	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:7	20.45	3107	1.71	13.48	96	195	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:8	20.45	3101	1.71	13.47	96	195	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:8	19.09	3121	1.71	13.48	96	195	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:8	19.09	3109	1.71	13.47	96	195	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:32:8	19.09	3097	1.71	13.46	96	195	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:8	19.09	3088	1.71	13.47	96	195	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:8	19.09	3099	1.71	13.46	96	195	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:9	19.09	3098	1.71	13.47	96	195	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:9	19.09	3090	1.71	13.47	96	195	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:9	19.09	3084	1.71	13.48	96	195	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:9	19.09	3113	1.71	13.47	96	195	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:9	19.09	3102	1.71	13.49	96	195	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:9	19.09	3104	1.71	13.47	96	195	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:32:9	19.09	3112	1.71	13.49	96	195	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:0	19.09	3114	1.71	13.48	96	195	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:0	19.09	3106	1.71	13.49	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:0	19.09	3119	1.71	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:0	19.09	3140	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:0	20.45	3128	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:0	20.45	3108	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:1	20.45	3099	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:1	20.45	3099	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:1	20.45	3088	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:1	20.45	3034	1.71	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:1	19.09	3054	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:1	19.09	3068	1.71	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:1	19.09	3057	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:2	19.09	3055	1.71	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:2	19.09	3056	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:2	19.09	3078	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:2	19.09	3046	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.17	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:2	19.09	3056	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:2	19.09	3080	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:3	19.09	3079	1.71	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:3	19.09	3080	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:3	19.09	3082	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:3	19.09	3130	1.71	13.5	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:3	19.09	3105	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:3	19.09	3054	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.18	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:4	19.09	3074	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:4	19.09	3074	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:4	19.09	3076	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:4	19.09	3061	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:4	19.09	3058	1.71	13.45	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:4	19.09	3053	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:4	19.09	3047	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:5	19.09	3023	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:5	19.09	3034	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:5	19.09	3048	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:5	19.09	3052	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:5	19.09	3055	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:5	19.09	3056	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:6	19.09	3073	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:6	19.09	3068	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:6	19.09	3058	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:6	19.09	3068	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:6	19.09	3085	1.71	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:6	19.09	3074	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:6	19.09	3058	1.71	13.49	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:7	19.09	3050	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:7	19.09	3043	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:7	19.09	3043	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:33:7	19.09	3032	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:7	19.09	3030	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:7	19.09	3029	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:8	19.09	3024	1.7	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:8	19.09	3026	1.7	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:8	19.09	3015	1.7	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:8	19.09	3028	1.7	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:8	19.09	3058	1.7	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:8	19.09	3058	1.7	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:9	19.09	3036	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:9	19.09	3036	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:9	19.09	3036	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:9	19.09	3036	1.7	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:9	19.09	3029	1.7	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:9	19.09	3024	1.7	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:33:9	19.09	3024	1.7	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:0	19.09	3030	1.7	13.49	96	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:0	19.09	2988	1.7	13.5	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:0	19.09	3000	1.7	13.51	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:0	19.09	3007	1.7	13.5	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:0	19.09	3005	1.71	13.49	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:0	19.09	3001	1.71	13.49	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:1	19.09	3001	1.71	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:1	19.09	2998	1.71	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:1	19.09	2996	1.71	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:1	19.09	2983	1.71	13.49	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:1	19.09	2994	1.71	13.48	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:1	19.09	2988	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:1	19.09	2988	1.71	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:2	19.09	2990	1.71	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:2	19.09	2966	1.71	13.47	96	195	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.26	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:2	19.09	2993	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:2	19.09	2995	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:2	19.09	3022	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:2	19.09	3002	1.71	13.49	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:3	19.09	3002	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:3	19.09	3002	1.71	13.5	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:3	19.09	2998	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:3	19.09	3018	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:3	19.09	3004	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:3	19.09	2968	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:4	19.09	2972	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:4	19.09	2962	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:4	19.09	2960	1.71	13.45	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:4	19.09	2960	1.71	13.45	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:4	19.09	2897	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:4	19.09	2938	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:4	19.09	2938	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:5	19.09	2961	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:5	19.09	2948	1.71	13.48	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:5	19.09	2933	1.71	13.47	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:5	19.09	2946	1.71	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:5	19.09	2967	1.71	13.46	96	195	Full Load	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:5	19.09	3016	1.71	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:6	19.09	2994	1.71	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:6	19.09	2823	1.71	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:6	10.9	2989	1.72	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:34:6	13.63	2988	1.73	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:34:6	16.36	2978	1.74	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.38	20.24	1.38	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:34:6	19.09	2968	1.75	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.29	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:34:6	19.09	2957	1.76	13.49	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.24	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:34:7	21.81	2957	1.77	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.12	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:34:7	24.54	2956	1.78	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.08	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:34:7	27.27	2956	1.79	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.03	20.26	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:34:7	29.99	2978	1.81	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.99	20.27	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:34:7	29.99	2987	1.83	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.98	20.26	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:34:7	32.72	2987	1.83	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.94	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:34:8	35.45	2986	1.84	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.93	20.25	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:34:8	36.81	2965	1.85	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.89	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:34:8	36.81	2969	1.87	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.87	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:34:8	36.81	2974	1.89	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.83	20.26	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:34:8	36.81	2974	1.91	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:34:8	36.81	2977	1.93	13.45	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.78	20.25	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:34:9	36.81	2979	1.94	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.73	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:34:9	36.81	2980	1.95	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.71	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:34:9	36.81	2980	1.96	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.68	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:34:9	36.81	2983	1.96	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.62	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:34:9	36.81	2983	1.98	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.58	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:34:9	36.81	2976	1.98	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.48	20.25	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:34:9	36.81	2974	1.99	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.43	20.24	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:35:0	36.81	2970	2	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.35	20.24	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:35:0	36.81	2957	2.01	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.3	20.21	1.38	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:35:0	36.81	2959	2.02	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.19	20.14	1.37	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:35:0	36.81	2957	2.03	13.49	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.1	20	1.36	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:0	36.81	2957	2.04	13.48	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.03	19.8	1.35	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:35:0	36.81	2980	2.05	13.49	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.94	19.56	1.33	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:35:1	36.81	2952	2.06	13.48	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.84	19.29	1.31	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:35:1	36.81	2954	2.08	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.77	18.97	1.29	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:35:1	36.81	2969	2.09	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.69	18.65	1.27	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:35:1	36.81	2970	2.1	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.6	18.32	1.25	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:35:1	36.81	2970	2.12	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.5	17.98	1.22	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:35:1	36.81	2968	2.13	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.37	17.51	1.19	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:35:1	36.81	2962	2.15	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.27	17.25	1.18	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:35:2	36.81	2937	2.16	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.16	17.05	1.16	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:35:2	35.45	2937	2.18	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.12	16.9	1.15	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:35:2	35.45	2950	2.19	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.99	16.77	1.14	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:35:2	35.45	2948	2.2	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.93	16.67	1.14	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:35:2	35.45	2946	2.22	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.87	16.59	1.13	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:35:2	35.45	2948	2.23	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.85	16.51	1.12	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:35:3	35.45	2927	2.25	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.75	16.43	1.12	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:3	35.45	2963	2.26	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.72	16.3	1.11	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:3	35.45	2963	2.26	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.68	16.22	1.1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:3	35.45	2967	2.27	13.46	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.63	16.15	1.1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:3	35.45	2967	2.28	13.45	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.63	16.07	1.09	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:3	35.45	2981	2.29	13.45	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.56	15.99	1.09	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:4	35.45	2985	2.3	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.55	15.93	1.09	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:4	35.45	2987	2.3	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.53	15.86	1.08	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:35:4	35.45	2998	2.31	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.55	15.8	1.08	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:35:4	35.45	2981	2.32	13.46	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.45	15.7	1.07	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:35:4	35.45	2980	2.32	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.42	15.65	1.07	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:4	35.45	2980	2.32	13.46	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.36	15.59	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:4	35.45	2978	2.33	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.31	15.52	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:5	35.45	2976	2.33	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.31	15.45	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:5	35.45	2984	2.34	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.29	15.39	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:5	35.45	2982	2.35	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.18	15.29	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:35:5	35.45	2984	2.35	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.13	15.26	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:35:8	35.45	2988	2.36	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.05	15.18	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:35:8	35.45	2995	2.37	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.97	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:35:6	35.45	3003	2.38	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.91	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:6	35.45	3002	2.39	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.91	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:6	35.45	3003	2.39	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.9	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:6	35.45	3001	2.4	13.49	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.79	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:6	35.45	3000	2.41	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.79	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:6	35.45	2998	2.42	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.71	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:35:6	35.45	2998	2.43	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.67	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:35:7	35.45	2988	2.43	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.66	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:7	35.45	2985	2.44	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.62	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:7	35.45	2984	2.45	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.6	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:7	35.45	2975	2.45	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.58	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:7	35.45	2979	2.46	13.48	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.58	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:7	35.45	2989	2.47	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.59	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:8	35.45	2992	2.47	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.53	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:8	35.45	3001	2.48	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.55	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:8	35.45	3019	2.48	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.53	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:8	35.45	3011	2.48	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.62	15.1	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:8	35.45	3011	2.48	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.56	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:8	35.45	3007	2.48	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.6	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:9	35.45	3009	2.48	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.57	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:9	35.45	3009	2.48	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.58	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:9	35.45	2988	2.48	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.52	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:35:9	35.45	2986	2.49	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.51	14.79	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:9	35.45	2992	2.49	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.51	14.71	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:9	35.45	2992	2.49	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.52	14.67	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:35:9	35.45	2999	2.49	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.48	14.67	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:0	35.45	3000	2.49	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.5	14.68	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:0	35.45	2997	2.49	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.48	14.7	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:0	35.45	2995	2.49	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.45	14.75	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:0	35.45	2995	2.49	13.49	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.44	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:0	35.45	2991	2.49	13.49	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.43	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:0	35.45	2993	2.49	13.48	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.46	14.83	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:1	35.45	2995	2.49	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.42	14.86	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:1	35.45	2995	2.49	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.46	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:1	35.45	3002	2.49	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.39	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:1	35.45	3004	2.49	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.45	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:1	35.45	3008	2.49	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.4	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:1	35.45	3010	2.49	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.47	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:1	35.45	3016	2.49	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.47	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:2	35.45	3016	2.49	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.5	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:2	35.45	3019	2.5	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.5	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:2	35.45	3017	2.5	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.54	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:2	35.45	3013	2.5	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.47	14.9	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:2	35.45	3010	2.5	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.5	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:2	35.45	3008	2.5	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.43	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:3	35.45	3027	2.5	13.46	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.4	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:3	35.45	3027	2.5	13.46	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.45	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:3	35.45	3020	2.5	13.46	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.7	-5.41	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:3	35.45	3020	2.5	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.7	-5.4	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:3	35.45	3018	2.5	13.45	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.4	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:3	35.45	3018	2.5	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.4	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:4	35.45	3018	2.5	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.39	15.05	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:4	35.45	3014	2.5	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.41	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:4	35.45	3014	2.5	13.46	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.39	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:4	35.45	3013	2.5	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.45	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:4	35.45	3010	2.5	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.44	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:36:4	35.45	3006	2.5	13.45	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.5	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:4	35.45	3006	2.51	13.45	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.44	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:5	35.45	3012	2.51	13.47	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.46	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:5	35.45	3026	2.51	13.47	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.46	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:5	35.45	3036	2.51	13.47	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.44	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:5	35.45	3038	2.51	13.48	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.38	14.89	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:5	35.45	3041	2.51	13.47	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.45	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:5	35.45	3041	2.51	13.46	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.45	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:6	35.45	3046	2.51	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.48	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:6	35.45	3022	2.51	13.46	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.46	14.97	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:6	35.45	3019	2.51	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.5	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:6	35.45	3018	2.51	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.47	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:6	35.45	3005	2.51	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.47	15.12	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:6	35.45	3015	2.51	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Lean	1	14.6	-5.5	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:6	35.45	3015	2.51	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.46	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:7	35.45	3024	2.51	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.49	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:7	35.45	3027	2.51	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.5	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:7	35.45	3028	2.51	13.48	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.46	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:7	35.45	3036	2.51	13.46	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.45	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:7	35.45	3048	2.51	13.48	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.42	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:7	35.45	3078	2.51	13.46	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.44	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:8	35.45	3068	2.51	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.39	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:8	35.45	3059	2.51	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.39	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:8	35.45	3051	2.51	13.47	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.42	14.82	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:36:8	35.45	3051	2.51	13.48	96	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.44	14.86	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:8	35.45	3041	2.51	13.47	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.45	14.88	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:8	35.45	3029	2.51	13.48	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.42	14.92	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:9	35.45	3028	2.51	13.49	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.43	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:9	35.45	3026	2.51	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.36	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:9	35.45	3002	2.51	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.36	15.04	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:36:9	35.45	3030	2.51	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.34	15.08	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:9	35.45	3034	2.51	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.39	15.08	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:9	35.45	3038	2.51	13.45	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.41	15.07	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:36:9	35.45	3064	2.51	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-5.44	15.03	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:22:37:0	35.45	3057	2.51	13.46	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.41	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:0	35.45	3058	2.51	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.46	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:0	35.45	3059	2.51	13.45	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.41	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:0	35.45	3057	2.51	13.48	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.4	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:0	35.45	3066	2.51	13.46	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.35	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:0	35.45	3053	2.51	13.46	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.38	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:1	35.45	3047	2.51	13.45	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.35	14.8	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:1	35.45	3047	2.52	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.36	14.81	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:1	35.45	3035	2.52	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.34	14.83	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:37:1	35.45	3052	2.52	13.48	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.32	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:37:1	35.45	3055	2.53	13.49	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.27	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:37:1	35.45	3062	2.53	13.49	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.17	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:1	35.45	3081	2.54	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	-5.09	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:37:2	35.45	3072	2.54	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.03	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:2	35.45	3066	2.55	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.97	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:37:2	35.45	3072	2.56	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.95	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:37:2	35.45	3072	2.56	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.86	15.02	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:37:2	35.45	3068	2.57	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.84	15.01	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:37:2	35.45	3070	2.58	13.46	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-4.75	15	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:37:3	35.45	3070	2.59	13.45	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-4.62	14.97	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:37:3	35.45	3073	2.6	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.57	14.95	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:37:3	35.45	3058	2.6	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.52	14.93	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:37:3	35.45	3073	2.61	13.47	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.54	14.94	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:37:3	35.45	3074	2.61	13.46	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.44	14.94	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:37:3	35.45	3074	2.62	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.46	14.95	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:37:4	35.45	3079	2.63	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.37	14.97	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:37:4	34.08	3079	2.64	13.48	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-4.34	15	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:37:4	34.08	3078	2.66	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.2	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:37:4	34.08	3086	2.66	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-4.19	15.05	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:37:4	34.08	3086	2.67	13.46	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.07	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:37:4	34.08	3086	2.68	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.02	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:37:4	34.08	3090	2.69	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-3.91	14.92	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:37:5	34.08	3088	2.7	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.9	14.85	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:37:5	34.08	3088	2.7	13.46	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.84	14.79	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:5	34.08	3084	2.71	13.44	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.84	14.7	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:5	34.08	3082	2.72	13.46	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.84	14.65	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:5	34.08	3084	2.72	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.81	14.57	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:37:5	34.08	3088	2.73	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.79	14.53	0.99	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:6	34.08	3088	2.74	13.44	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.77	14.51	0.99	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:6	34.08	3094	2.74	13.46	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.73	14.46	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:6	34.08	3098	2.74	13.44	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.7	14.45	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:6	34.08	3099	2.75	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.73	14.46	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:6	34.08	3100	2.76	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.64	14.44	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:37:6	34.08	3102	2.76	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.65	14.44	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:6	34.08	3102	2.76	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.6	14.44	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:37:7	34.08	3102	2.77	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-3.59	14.4	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:37:7	34.08	3105	2.77	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.54	14.38	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:7	34.08	3104	2.77	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.54	14.35	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:7	34.08	3103	2.78	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.52	14.34	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:7	34.08	3102	2.78	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.5	14.33	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:7	34.08	3106	2.77	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.47	14.33	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:8	34.08	3106	2.78	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.48	14.34	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:8	34.08	3126	2.78	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.48	14.37	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:8	34.08	3115	2.78	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-3.44	14.39	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:8	34.08	3115	2.78	13.46	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.43	14.4	0.98	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:8	34.08	3126	2.79	13.45	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.33	14.42	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:8	34.08	3131	2.79	13.47	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.3	14.46	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:37:9	34.08	3132	2.8	13.46	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-3.19	14.46	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:37:9	34.08	3131	2.81	13.47	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-3.16	14.47	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:22:37:9	34.08	3128	2.81	13.48	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-3.07	14.47	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:37:9	34.08	3128	2.81	13.48	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	-3.03	14.47	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:37:9	34.08	3127	2.82	13.46	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.9	14.5	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:37:9	34.08	3121	2.83	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.88	14.51	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:37:9	34.08	3117	2.83	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.84	14.53	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:0	34.08	3118	2.84	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.85	14.57	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:0	34.08	3123	2.84	13.46	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.77	14.6	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:0	34.08	3128	2.85	13.48	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.74	14.63	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:0	34.08	3131	2.85	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.69	14.65	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:0	34.08	3142	2.86	13.47	96	196	Off Idle	41.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.64	14.68	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:0	34.08	3157	2.86	13.47	96	196	Off Idle	41.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.61	14.68	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:1	34.08	3159	2.87	13.48	96	196	Off Idle	41.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.59	14.65	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:1	34.08	3154	2.88	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.52	14.64	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:1	34.08	3150	2.88	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.57	14.62	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:1	34.08	3150	2.89	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.52	14.59	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:1	34.08	3147	2.89	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.54	14.54	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:1	34.08	3141	2.89	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.47	14.5	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:1	34.08	3142	2.89	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.47	14.46	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:2	34.08	3146	2.89	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.39	14.4	0.98	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:2	34.08	3157	2.9	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.44	14.36	0.98	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:2	34.08	3186	2.9	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.41	14.35	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:2	34.08	3170	2.9	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.39	14.31	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:2	34.08	3174	2.9	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.39	14.29	0.97	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:38:2	34.08	3172	2.9	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.37	14.27	0.97	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:3	34.08	3170	2.91	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.36	14.25	0.97	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:3	34.08	3166	2.91	13.46	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.37	14.28	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:3	34.08	3164	2.91	13.48	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.4	14.28	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:3	34.08	3165	2.91	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.35	14.28	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:3	34.08	3168	2.91	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.43	14.31	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:3	34.08	3184	2.92	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.38	14.32	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:4	34.08	3177	2.92	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.32	14.32	0.98	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:4	34.08	3177	2.92	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.31	14.33	0.98	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:4	34.08	3183	2.92	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.37	14.36	0.98	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:4	34.08	3178	2.92	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.33	14.39	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:4	34.08	3199	2.92	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.37	14.4	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:4	34.08	3201	2.92	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.36	14.41	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:4	34.08	3202	2.92	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.37	14.43	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:5	34.08	3221	2.93	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.27	14.45	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:5	34.08	3221	2.93	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.3	14.49	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:5	34.08	3190	2.93	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.27	14.51	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:5	34.08	3190	2.93	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.25	14.54	0.99	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:5	34.08	3190	2.93	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.22	14.56	0.99	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:5	34.08	3184	2.93	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.21	14.57	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:6	34.08	3198	2.93	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.16	14.6	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:6	34.08	3200	2.93	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.08	14.63	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:6	34.08	3208	2.94	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.13	14.65	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:6	34.08	3242	2.94	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.05	14.66	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:6	34.08	3213	2.94	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.06	14.67	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:6	34.08	3212	2.94	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.09	14.69	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:6	34.08	3209	2.94	13.45	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.06	14.7	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:7	34.08	3205	2.95	13.46	96	196	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.99	14.71	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:38:7	34.08	3195	2.95	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.02	14.72	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:7	34.08	3214	2.95	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-1.9	14.74	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:38:7	34.08	3222	2.96	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-1.77	14.75	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:7	34.08	3222	2.96	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-1.77	14.75	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:7	34.08	3236	2.96	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-1.75	14.77	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:8	34.08	3246	2.97	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-1.71	14.77	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:8	34.08	3244	2.97	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-1.65	14.78	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:22:38:8	34.08	3243	2.98	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-1.61	14.8	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:22:38:8	34.08	3236	2.98	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-1.51	14.83	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:8	32.72	3238	2.99	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.7	-1.47	14.89	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:8	32.72	3238	2.99	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-1.43	14.92	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:9	32.72	3241	3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.4	15	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:9	32.72	3238	3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.7	-1.4	15.01	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:22:38:9	34.08	3217	3.01	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.7	-1.3	15.01	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:22:38:9	34.08	3217	3.01	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-1.28	15.02	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:22:38:9	34.08	3261	3.02	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.3	15	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:22:38:9	34.08	3272	3.02	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.27	14.97	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:38:9	34.08	3275	3.02	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-1.28	14.92	1.02	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:0	34.08	3290	3.03	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.28	14.87	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:0	34.08	3274	3.03	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.3	14.77	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:0	34.08	3274	3.04	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.29	14.73	1	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:0	34.08	3264	3.04	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.25	14.65	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:0	34.08	3264	3.04	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.29	14.62	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:0	34.08	3252	3.05	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.27	14.6	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:1	34.08	3252	3.05	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-1.19	14.59	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:1	34.08	3252	3.05	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.23	14.61	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:1	34.08	3266	3.05	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.21	14.63	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:1	34.08	3281	3.05	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.15	14.63	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:39:1	34.08	3282	3.05	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-1.16	14.64	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:39:1	34.08	3292	3.05	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.13	14.65	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:39:1	34.08	3294	3.05	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.15	14.67	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:2	34.08	3294	3.05	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.18	14.69	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:39:2	34.08	3294	3.05	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.16	14.72	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:39:2	34.08	3294	3.05	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.25	14.73	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:2	34.08	3288	3.05	13.5	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.26	14.75	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:39:2	34.08	3291	3.05	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-1.3	14.78	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:39:2	34.08	3297	3.05	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-1.3	14.79	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:39:3	34.08	3298	3.05	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-1.29	14.81	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:39:3	34.08	3292	3.05	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.31	14.82	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:39:3	34.08	3296	3.05	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-1.33	14.85	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:39:3	34.08	3270	3.05	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-1.34	14.86	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:39:3	34.08	3284	3.05	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-1.44	14.87	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:22:39:3	34.08	3308	3.05	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-1.38	14.86	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:4	34.08	3314	3.05	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-1.32	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:4	34.08	3318	3.05	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-1.39	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:4	34.08	3321	3.05	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-1.35	14.87	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:4	34.08	3314	3.05	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-1.31	14.91	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:4	34.08	3314	3.04	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-1.44	14.92	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:4	34.08	3312	3.04	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-1.44	14.96	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:4	34.08	3328	3.04	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-1.49	14.97	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:22:39:5	34.08	3319	3.04	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-1.59	15	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:22:39:5	34.08	3318	3.04	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-1.59	15.04	1.02	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:22:39:5	34.08	3319	3.03	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-1.69	15.12	1.03	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:39:5	34.08	3325	3.03	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-1.75	15.15	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:39:5	34.08	3322	3.02	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-1.76	15.16	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:39:5	34.08	3318	3.02	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-1.8	15.14	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:22:39:6	34.08	3321	3.01	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-1.87	15.1	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:6	34.08	3324	3.01	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-1.93	15.09	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:6	34.08	3326	3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-1.97	15.07	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:6	34.08	3330	2.99	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.09	15.05	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:39:6	34.08	3339	2.99	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.19	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:6	34.08	3340	2.98	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.24	14.97	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:6	34.08	3339	2.98	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-2.35	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:7	34.08	3334	2.97	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-2.32	14.85	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:7	34.08	3364	2.96	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-2.33	14.88	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:7	34.08	3356	2.96	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-2.41	14.9	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:7	34.08	3352	2.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-2.42	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:7	34.08	3356	2.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Rich	1	14.6	-2.45	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:7	34.08	3354	2.94	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-2.53	15.05	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:8	34.08	3353	2.94	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-2.58	15.11	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:8	34.08	3354	2.93	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.55	15.17	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:8	34.08	3363	2.93	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.56	15.24	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:8	34.08	3363	2.93	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.59	15.29	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:8	34.08	3363	2.93	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-2.63	15.28	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:8	34.08	3360	2.92	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-2.63	15.28	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:9	34.08	3355	2.92	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.65	15.27	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:9	34.08	3355	2.92	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.66	15.24	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:9	34.08	3355	2.92	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-2.68	15.25	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:9	34.08	3352	2.92	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-2.69	15.23	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:39:9	34.08	3357	2.92	13.47	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-2.67	15.21	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:39:9	34.08	3362	2.92	13.48	96	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-2.73	15.19	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:39:9	34.08	3368	2.92	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.75	15.16	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:40:0	34.08	3373	2.92	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-2.71	15.12	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:40:0	34.08	3372	2.92	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-2.76	15.11	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:22:40:0	34.08	3370	2.91	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-2.79	15.1	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:40:0	34.08	3370	2.91	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-2.79	15.1	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:40:0	34.08	3369	2.91	13.5	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.8	15.09	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:40:0	35.45	3400	2.91	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-2.8	15.03	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:40:1	35.45	3369	2.91	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-2.83	15	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:22:40:1	35.45	3372	2.91	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.92	14.96	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:22:40:1	35.45	3382	2.91	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.89	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:1	35.45	3389	2.9	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.86	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:1	35.45	3390	2.9	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-2.9	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:1	35.45	3388	2.9	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-2.92	14.97	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:1	35.45	3390	2.9	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.93	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:2	35.45	3393	2.9	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-3	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:2	35.45	3394	2.89	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-3.1	14.95	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:2	35.45	3390	2.89	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-3.11	14.95	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:2	35.45	3388	2.89	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-3.2	14.98	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:40:2	35.45	3388	2.88	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-3.31	14.96	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:40:2	35.45	3374	2.88	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-3.33	14.93	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:3	35.45	3391	2.88	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.4	14.91	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:3	35.45	3393	2.87	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.54	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:3	35.45	3393	2.87	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.55	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:40:3	35.45	3394	2.86	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.54	14.88	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:40:3	35.45	3403	2.85	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-3.69	14.91	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:40:3	35.45	3403	2.85	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.7	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:40:4	35.45	3405	2.84	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-3.78	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:22:40:4	35.45	3388	2.83	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.98	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:22:40:4	35.45	3401	2.82	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.03	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:40:4	35.45	3401	2.81	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.16	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:40:4	35.45	3403	2.8	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.29	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:40:4	35.45	3394	2.77	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.56	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:40:4	35.45	3404	2.76	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.66	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:40:5	35.45	3382	2.74	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.05	15.09	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:40:5	35.45	3383	2.72	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.21	15.08	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:5	35.45	3383	2.68	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.44	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:5	35.45	3380	2.67	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-5.66	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:5	35.45	3363	2.65	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.81	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:40:5	35.45	3363	2.62	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.02	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:40:6	35.45	3368	2.58	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.3	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:40:6	35.45	3404	2.55	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.58	14.9	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:40:6	36.81	3392	2.52	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.85	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:40:6	36.81	3388	2.5	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.98	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:40:6	36.81	3382	2.46	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.17	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:40:6	36.81	3382	2.44	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.22	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:40:6	36.81	3392	2.4	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.47	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:40:7	36.81	3388	2.37	13.5	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.52	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:40:7	36.81	3381	2.35	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.58	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:40:7	36.81	3381	2.32	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.71	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:40:7	36.81	3390	2.29	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.85	15.14	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:40:7	38.18	3376	2.26	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.97	15.22	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:40:7	38.18	3409	2.24	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.08	15.28	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:40:8	38.18	3398	2.21	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.19	15.36	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:40:8	38.18	3388	2.18	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	15.41	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:40:8	38.18	3382	2.15	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.4	15.48	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:40:8	38.18	3384	2.14	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.51	15.66	1.07	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:40:8	38.18	3384	2.11	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.65	15.7	1.07	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:40:8	38.18	3382	2.09	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.73	15.8	1.08	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:9	38.18	3370	2.07	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.82	15.87	1.08	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:40:9	38.18	3369	2.05	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.95	15.94	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:9	38.18	3356	2.03	13.5	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.02	16	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:9	38.18	3353	2.02	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.1	16.05	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:9	38.18	3351	2	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.21	16.09	1.1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:9	38.18	3342	1.96	13.5	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.29	16.11	1.1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:40:9	38.18	3341	1.94	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.38	16.11	1.1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:41:0	38.18	3342	1.92	13.49	95	196	Full Load	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.46	16.08	1.1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:41:0	38.18	3342	1.9	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.5	16.06	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:41:0	38.18	3359	1.88	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.6	16.02	1.09	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:0	38.18	3362	1.86	13.5	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.69	15.99	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:0	38.18	3371	1.84	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.69	15.96	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:0	38.18	3400	1.82	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.83	15.93	1.08	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:1	38.18	3336	1.8	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.82	15.88	1.08	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:1	38.18	3336	1.79	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.87	15.85	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:1	32.72	3329	1.77	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.9	15.83	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:1	27.27	3315	1.76	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.94	15.8	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:1	21.81	3358	1.74	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.95	15.79	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:1	20.45	3354	1.74	13.5	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.97	15.78	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:1	20.45	3293	1.73	13.5	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.96	15.77	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:2	20.45	3317	1.72	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.97	15.76	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:2	20.45	3337	1.72	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.96	15.75	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:2	20.45	3334	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.94	15.73	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:2	20.45	3334	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.91	15.72	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:2	20.45	3337	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.89	15.71	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:2	20.45	3348	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.84	15.7	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:3	20.45	3348	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.79	15.68	1.07	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:3	20.45	3353	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.83	15.66	1.07	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:3	20.45	3353	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.8	15.63	1.06	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:3	20.45	3354	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.85	15.63	1.06	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:3	20.45	3352	1.7	13.51	95	196	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.87	15.63	1.06	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:3	20.45	3352	1.7	13.5	95	196	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.81	15.64	1.07	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:4	20.45	3345	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.82	15.64	1.07	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:4	20.45	3338	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.84	15.65	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:4	20.45	3340	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.78	15.66	1.07	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:4	20.45	3340	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.79	15.67	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:4	20.45	3330	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	15.7	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:4	20.45	3330	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	15.78	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:4	20.45	3326	1.7	13.49	95	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	16.01	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:5	20.45	3324	1.7	13.49	95	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	16.28	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:5	20.45	3325	1.7	13.49	95	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	16.68	1.14	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:5	20.45	3326	1.7	13.48	95	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	17.12	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:5	20.45	3326	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	17.35	1.18	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:5	20.45	3327	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	17.8	1.21	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:5	20.45	3326	1.7	13.51	95	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	18.25	1.24	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:6	20.45	3331	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	18.7	1.27	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:6	20.45	3335	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	19.12	1.3	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:6	20.45	3336	1.7	13.5	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	19.68	1.34	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:6	20.45	3341	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	19.83	1.35	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:6	20.45	3344	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.16	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:6	20.45	3342	1.7	13.5	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:6	20.45	3364	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:7	20.45	3364	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:7	20.45	3337	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:7	20.45	3336	1.7	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:7	20.45	3300	1.71	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:7	20.45	3311	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:7	20.45	3305	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:8	20.45	3288	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:8	20.45	3268	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:8	20.45	3258	1.71	13.49	95	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:8	20.45	3258	1.71	13.49	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:8	20.45	3257	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:8	20.45	3263	1.71	13.48	95	196	Idle	41	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:9	20.45	3266	1.71	13.48	95	196	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:41:9	20.45	3285	1.71	13.47	95	196	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:9	20.45	3306	1.71	13.46	95	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:9	20.45	3317	1.71	13.46	95	196	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:9	20.45	3333	1.71	13.47	95	196	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:9	20.45	3328	1.71	13.47	95	196	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:41:9	20.45	3324	1.71	13.48	95	196	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:0	20.45	3322	1.71	13.49	95	196	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:0	20.45	3302	1.71	13.49	95	196	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:0	20.45	3291	1.71	13.48	95	196	Idle	40.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:0	20.45	3263	1.71	13.49	95	196	Idle	40.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.1	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:0	20.45	3260	1.71	13.48	95	196	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.1	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:0	20.45	3231	1.71	13.48	95	196	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.1	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:1	20.45	3234	1.71	13.48	95	196	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.1	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:1	20.45	3234	1.71	13.48	95	196	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.12	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:1	20.45	3242	1.71	13.47	95	196	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.12	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:1	20.45	3252	1.71	13.48	95	196	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.13	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:1	20.45	3283	1.71	13.47	95	196	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.14	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:1	20.45	3288	1.72	13.49	95	196	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.13	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:1	20.45	3307	1.72	13.48	95	196	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.13	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:2	20.45	3314	1.72	13.49	95	196	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:2	20.45	3314	1.72	13.49	95	196	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:2	20.45	3305	1.72	13.47	95	196	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:2	20.45	3294	1.72	13.48	95	196	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:2	20.45	3290	1.71	13.49	95	196	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:2	20.45	3270	1.71	13.48	95	196	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:3	20.45	3258	1.71	13.47	95	196	Idle	40.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:3	20.45	3255	1.71	13.49	95	196	Idle	40.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:3	20.45	3216	1.71	13.48	95	196	Idle	40.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:3	20.45	3216	1.71	13.48	95	196	Idle	40.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:3	20.45	3236	1.71	13.48	95	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:3	20.45	3231	1.71	13.49	95	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:4	20.45	3238	1.71	13.5	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:4	20.45	3226	1.71	13.49	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.27	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:4	20.45	3240	1.71	13.49	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:4	20.45	3243	1.71	13.5	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.26	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:4	20.45	3245	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:4	20.45	3246	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:4	20.45	3245	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:5	20.45	3245	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:5	20.45	3244	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:5	20.45	3221	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:5	20.45	3243	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:5	20.45	3244	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:5	20.45	3241	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:6	20.45	3237	1.71	13.5	95	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:6	20.45	3237	1.71	13.5	95	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:6	20.45	3234	1.71	13.49	95	196	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:6	20.45	3228	1.71	13.5	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:6	20.45	3226	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:6	20.45	3226	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:6	20.45	3224	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:7	20.45	3224	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:7	20.45	3222	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:7	20.45	3222	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:7	20.45	3218	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:7	20.45	3220	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:7	20.45	3222	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:8	20.45	3222	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:42:8	20.45	3228	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:8	20.45	3255	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:8	20.45	3244	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:8	20.45	3233	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:8	20.45	3228	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:9	20.45	3228	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:9	20.45	3194	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:9	20.45	3209	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:9	20.45	3204	1.71	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:9	20.45	3202	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:9	20.45	3193	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:42:9	20.45	3189	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:0	20.45	3187	1.71	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:0	20.45	3184	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:0	20.45	3184	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:0	20.45	3185	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:0	20.45	3186	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:0	20.45	3193	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:1	20.45	3196	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:1	20.45	3198	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:1	20.45	3200	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:1	20.45	3203	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:1	20.45	3201	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:1	20.45	3202	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:1	20.45	3200	1.7	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:2	20.45	3197	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:2	20.45	3196	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:2	20.45	3188	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:2	20.45	3181	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:2	20.45	3173	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:2	20.45	3171	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:3	20.45	3167	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:3	20.45	3160	1.71	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:3	20.45	3172	1.71	13.46	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:3	20.45	3158	1.71	13.47	95	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:3	20.45	3157	1.71	13.46	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:3	20.45	3157	1.71	13.47	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:4	20.45	3160	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:4	20.45	3163	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:4	20.45	3164	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:4	20.45	3156	1.71	13.47	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:4	20.45	3166	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:4	20.45	3186	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:4	20.45	3186	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:5	20.45	3159	1.71	13.49	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:5	20.45	3157	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:5	20.45	3156	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:5	20.45	3156	1.71	13.47	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:5	20.45	3156	1.71	13.48	95	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:5	20.45	3155	1.71	13.48	95	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:6	20.45	3155	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:6	20.45	3155	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:6	20.45	3154	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:6	20.45	3153	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:6	20.45	3152	1.71	13.5	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:6	20.45	3155	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:6	20.45	3154	1.71	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:7	20.45	3152	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:43:7	20.45	3154	1.71	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:7	20.45	3165	1.71	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:7	20.45	3152	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:7	20.45	3125	1.7	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:7	20.45	3148	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:8	20.45	3147	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:8	20.45	3136	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:8	20.45	3133	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:8	20.45	3134	1.7	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:8	20.45	3115	1.71	13.49	95	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:8	20.45	3110	1.71	13.48	95	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:9	20.45	3098	1.71	13.48	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:9	19.09	3105	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:9	19.09	3102	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:9	20.45	3102	1.71	13.48	95	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:9	20.45	3100	1.71	13.47	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:9	20.45	3056	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:43:9	19.09	3079	1.71	13.47	95	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:0	19.09	3109	1.71	13.47	95	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:0	19.09	3120	1.71	13.47	95	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:0	19.09	3119	1.71	13.46	95	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:0	19.09	3118	1.71	13.48	95	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:0	19.09	3128	1.71	13.47	95	196	Idle	41.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:0	19.09	3115	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:1	19.09	3114	1.71	13.48	95	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:1	19.09	3114	1.71	13.49	95	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:1	19.09	3117	1.71	13.49	95	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:1	19.09	3106	1.71	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:1	19.09	3118	1.71	13.48	95	196	Full Load	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:1	20.45	3136	1.71	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:1	20.45	3120	1.71	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:2	20.45	3120	1.71	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:2	20.45	2958	1.71	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:44:2	14.99	3136	1.72	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:44:2	14.99	3134	1.72	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:44:2	17.72	3122	1.73	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:44:2	20.45	3116	1.73	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:44:3	23.18	3116	1.74	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:44:3	23.18	3110	1.74	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:44:3	25.9	3106	1.75	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.44	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:44:3	28.63	3114	1.75	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:44:3	31.36	3106	1.77	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.38	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:44:3	34.08	3129	1.78	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.4	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:44:4	36.81	3131	1.79	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.39	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:4	36.81	3111	1.8	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:4	38.18	3126	1.8	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	20.26	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:44:4	38.18	3122	1.81	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.39	20.26	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:44:4	38.18	3130	1.82	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:44:4	38.18	3130	1.83	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.37	20.26	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:44:4	38.18	3116	1.84	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.36	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:5	38.18	3123	1.85	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.36	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:5	38.18	3116	1.85	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.31	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:5	38.18	3116	1.85	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.31	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:5	38.18	3111	1.86	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.28	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:22:44:5	36.81	3084	1.87	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.29	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:5	36.81	3094	1.87	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.26	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:6	36.81	3099	1.88	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.27	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:6	36.81	3099	1.88	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.21	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:44:6	36.81	3097	1.89	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.23	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:6	38.18	3096	1.89	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.22	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:6	38.18	3077	1.89	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.25	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:6	38.18	3078	1.89	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.22	20.1	1.37	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:6	38.18	3077	1.89	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.23	19.94	1.36	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:7	38.18	3070	1.89	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.16	19.71	1.34	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:7	36.81	3061	1.89	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.15	19.46	1.33	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:7	36.81	3087	1.9	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.15	19.19	1.31	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:22:44:7	36.81	3073	1.9	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.14	18.72	1.28	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:7	36.81	3074	1.9	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.11	18.38	1.25	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:7	36.81	3078	1.9	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.12	18.03	1.23	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:8	36.81	3084	1.9	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.12	17.68	1.2	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:8	36.81	3084	1.91	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.08	17.52	1.19	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:8	36.81	3091	1.91	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.1	17.13	1.17	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:8	36.81	3092	1.91	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.04	16.93	1.15	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:8	36.81	3085	1.91	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.09	16.77	1.14	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:8	36.81	3098	1.92	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.04	16.64	1.13	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:9	36.81	3098	1.92	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.04	16.53	1.13	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:9	36.81	3094	1.92	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.02	16.43	1.12	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:9	36.81	3097	1.92	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.04	16.31	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:9	36.81	3116	1.92	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.97	16.22	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:9	38.18	3116	1.93	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.02	16.14	1.1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:9	38.18	3094	1.93	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.94	16.08	1.1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:44:9	38.18	3094	1.93	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.98	16.01	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:0	38.18	3092	1.93	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.91	15.95	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:0	38.18	3094	1.93	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.98	15.88	1.08	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:0	36.81	3110	1.93	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.94	15.82	1.08	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:0	36.81	3099	1.94	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.97	15.77	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:0	36.81	3098	1.94	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.99	15.71	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:0	36.81	3098	1.94	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.98	15.66	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:1	36.81	3094	1.94	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.95	15.61	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:1	36.81	3094	1.94	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.98	15.55	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:1	36.81	3096	1.94	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.98	15.5	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:1	36.81	3094	1.94	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.92	15.48	1.05	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:1	36.81	3094	1.94	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.96	15.45	1.05	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:1	36.81	3092	1.94	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.94	15.38	1.05	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:45:1	36.81	3087	1.95	13.5	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.93	15.35	1.05	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:2	36.81	3089	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.9	15.32	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:2	36.81	3089	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.88	15.3	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:2	36.81	3084	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.87	15.29	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:2	36.81	3085	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.88	15.28	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:2	36.81	3084	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.91	15.27	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:2	36.81	3077	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.92	15.24	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:3	36.81	3066	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.94	15.2	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:3	36.81	3062	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.92	15.18	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:3	36.81	3064	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.89	15.16	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:3	36.81	3064	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.94	15.15	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:3	36.81	3063	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.89	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:3	36.81	3063	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.92	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:4	36.81	3060	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.88	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:4	36.81	3062	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.88	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:4	36.81	3063	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.89	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:4	36.81	3066	1.95	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.92	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:4	36.81	3069	1.95	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.89	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:4	36.81	3069	1.95	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.92	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:4	36.81	3071	1.95	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.89	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:5	36.81	3067	1.95	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.9	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:5	36.81	3067	1.95	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.87	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:45:5	36.81	3068	1.95	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.83	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:5	36.81	3070	1.95	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.9	14.9	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:5	36.81	3073	1.95	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.9	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:5	36.81	3062	1.95	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.88	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:6	36.81	3079	1.95	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.91	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:6	36.81	3083	1.95	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.9	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:6	36.81	3082	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.89	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:6	36.81	3081	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.84	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:6	36.81	3088	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.83	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:6	36.81	3090	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.85	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:6	36.81	3091	1.95	13.5	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.83	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:45:7	36.81	3120	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.86	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:7	36.81	3096	1.95	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.86	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:7	36.81	3096	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Rich	1	14.6	-8.85	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:7	36.81	3095	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.91	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:7	36.81	3111	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.92	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:7	36.81	3111	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.89	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:8	36.81	3083	1.95	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.92	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:8	36.81	3068	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.92	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:8	36.81	3062	1.95	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.87	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:8	36.81	3040	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.92	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:8	36.81	3064	1.95	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.89	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:8	36.81	3068	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.9	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:9	36.81	3068	1.95	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.87	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:9	36.81	3066	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.91	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:9	36.81	3077	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.89	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:9	36.81	3078	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.9	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:45:9	36.81	3094	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.86	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:9	36.81	3082	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.89	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:45:9	36.81	3092	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.83	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:0	36.81	3092	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.89	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:0	36.81	3094	1.95	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.84	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:0	36.81	3094	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Rich	1	14.6	-8.87	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:0	36.81	3076	1.95	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-8.83	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:0	36.81	3066	1.95	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.83	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:0	36.81	3066	1.95	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.8	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:1	36.81	3027	1.95	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.81	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:1	36.81	3046	1.96	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.75	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:1	36.81	3047	1.96	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.77	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:1	36.81	3048	1.96	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.76	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:1	36.81	3060	1.96	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.73	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:1	36.81	3046	1.96	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.72	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:1	36.81	3056	1.96	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.73	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:2	36.81	3056	1.96	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.75	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:2	36.81	3052	1.96	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.76	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:2	36.81	3057	1.96	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.74	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:2	36.81	3055	1.97	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.75	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:2	36.81	3058	1.97	13.5	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.77	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:2	36.81	3066	1.97	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.7	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:3	36.81	3073	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.75	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:3	36.81	3073	1.97	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.75	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:3	36.81	3076	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.72	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:3	36.81	3078	1.97	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.7	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:3	36.81	3105	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.72	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:3	36.81	3088	1.97	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.72	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:4	36.81	3089	1.97	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.72	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:4	36.81	3089	1.97	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.67	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:4	36.81	3096	1.97	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.73	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:46:4	36.81	3100	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.67	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:4	36.81	3100	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.67	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:4	36.81	3094	1.97	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.68	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:4	36.81	3068	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.7	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:5	36.81	3074	1.97	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.68	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:5	36.81	3067	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.73	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:5	36.81	3060	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.7	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:5	36.81	3031	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.75	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:5	36.81	3041	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.73	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:5	36.81	3049	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.73	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:6	36.81	3047	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.7	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:6	36.81	3047	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.74	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:6	36.81	3041	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.69	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:6	36.81	3058	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.73	14.99	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:6	36.81	3063	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.71	14.99	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:6	36.81	3064	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.73	14.97	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:6	36.81	3097	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.7	14.97	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:7	36.81	3074	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.72	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:7	36.81	3069	1.97	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.7	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:7	36.81	3070	1.97	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.66	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:7	36.81	3070	1.98	13.5	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.62	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:7	36.81	3070	1.98	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.62	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:7	36.81	3069	1.98	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.56	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:8	36.81	3068	1.98	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.6	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:8	36.81	3067	1.98	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.54	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:8	36.81	3058	1.99	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.52	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:8	36.81	3058	1.99	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.55	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:8	36.81	3058	1.99	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.52	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:8	36.81	3058	2	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.5	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:9	36.81	3045	2	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.42	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:9	36.81	3045	2.01	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.41	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:9	36.81	3059	2.02	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.36	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:9	36.81	3060	2.02	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.32	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:9	36.81	3060	2.03	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.28	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:22:46:9	36.81	3051	2.03	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.28	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:46:9	36.81	3074	2.04	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.2	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:0	36.81	3074	2.05	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.21	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:0	36.81	3077	2.06	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.12	15.09	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:0	36.81	3081	2.06	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.1	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:0	36.81	3075	2.07	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.04	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:0	36.81	3075	2.08	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.01	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:0	36.81	3068	2.08	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.91	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:1	36.81	3068	2.08	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.91	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:1	36.81	3056	2.1	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.84	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:1	36.81	3049	2.11	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.84	14.91	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:1	36.81	3030	2.11	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.77	14.9	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:1	36.81	3030	2.12	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.79	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:1	36.81	3062	2.13	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.69	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:1	36.81	3070	2.14	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:2	36.81	3078	2.14	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.67	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:2	36.81	3092	2.15	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.68	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:2	36.81	3084	2.15	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:2	36.81	3087	2.16	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:2	36.81	3087	2.16	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:2	36.81	3090	2.16	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:3	36.81	3072	2.17	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.05	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:3	36.81	3064	2.17	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:3	36.81	3065	2.17	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:47:3	36.81	3059	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	14.94	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:3	36.81	3073	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:3	36.81	3078	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.59	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:4	36.81	3088	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.62	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:4	36.81	3069	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.62	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:4	36.81	3082	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.66	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:4	36.81	3096	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.62	14.81	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:4	36.81	3101	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.65	14.81	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:4	36.81	3112	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.62	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:4	36.81	3098	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.64	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:5	36.81	3083	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.65	14.79	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:5	36.81	3076	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.66	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:5	36.81	3074	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.64	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:5	36.81	3070	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.67	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:5	36.81	3061	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.62	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:5	36.81	3061	2.18	13.44	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.66	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:6	36.81	3044	2.18	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.63	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:6	36.81	3058	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.64	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:6	36.81	3050	2.18	13.44	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.63	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:6	36.81	3052	2.18	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.62	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:6	36.81	3057	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.6	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:6	36.81	3059	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.64	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:6	36.81	3058	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.61	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:7	36.81	3058	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.65	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:7	35.45	3070	2.18	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.62	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:7	35.45	3070	2.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.65	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:7	35.45	3079	2.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.62	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:7	35.45	3085	2.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.64	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:7	35.45	3112	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.6	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:8	36.81	3112	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.63	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:8	36.81	3092	2.18	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.58	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:8	36.81	3092	2.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.63	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:8	36.81	3092	2.18	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.58	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:8	36.81	3091	2.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.62	14.9	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:8	36.81	3085	2.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.63	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:9	36.81	3082	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.64	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:9	36.81	3084	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.65	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:9	36.81	3058	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.64	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:9	36.81	3053	2.18	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.61	15.05	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:47:9	36.81	3049	2.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.62	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:9	36.81	3001	2.18	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.58	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:47:9	36.81	3026	2.18	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.55	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:0	36.81	3059	2.19	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.58	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:0	36.81	3074	2.19	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.54	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:0	36.81	3074	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.57	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:0	36.81	3102	2.19	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.53	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:0	36.81	3095	2.19	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.55	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:0	36.81	3095	2.19	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.54	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:1	36.81	3095	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.57	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:1	36.81	3093	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.57	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:1	36.81	3087	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.6	14.79	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:1	36.81	3079	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.58	14.79	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:1	36.81	3081	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.61	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:1	35.45	3040	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.58	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:1	35.45	3050	2.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.59	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:2	35.45	3056	2.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.54	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:2	35.45	3055	2.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.54	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:2	35.45	3056	2.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.53	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:48:2	36.81	3072	2.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.55	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:2	36.81	3070	2.19	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.52	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:2	36.81	3077	2.19	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.54	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:3	36.81	3080	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.56	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:3	36.81	3085	2.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.55	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:48:3	36.81	3081	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.57	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:48:3	36.81	3080	2.19	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.55	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:48:3	36.81	3078	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.59	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:48:3	36.81	3080	2.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.57	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:4	36.81	3081	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.55	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:4	36.81	3082	2.19	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.54	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:4	36.81	3087	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.54	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:4	36.81	3095	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.53	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:4	36.81	3096	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.54	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:4	36.81	3094	2.19	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.53	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:4	36.81	3112	2.2	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.53	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:5	36.81	3112	2.2	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.55	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:5	36.81	3079	2.2	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.53	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:5	36.81	3078	2.2	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.49	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:5	36.81	3076	2.2	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.49	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:5	36.81	3056	2.2	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.51	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:5	36.81	3069	2.2	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.48	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:6	36.81	3065	2.2	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.52	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:6	36.81	3064	2.2	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.48	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:6	36.81	3062	2.2	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.54	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:6	36.81	3071	2.2	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.49	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:6	36.81	3071	2.2	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.57	15.11	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:6	36.81	3080	2.2	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.5	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:48:6	36.81	3088	2.2	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.53	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:48:7	36.81	3070	2.19	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.48	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:48:7	35.45	3070	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.51	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:7	35.45	3099	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.48	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:7	35.45	3095	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.5	14.94	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:7	35.45	3095	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.48	14.91	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:7	35.45	3088	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.51	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:8	36.81	3078	2.19	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.51	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:8	36.81	3094	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.56	14.81	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:8	36.81	3098	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.51	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:8	36.81	3100	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:8	36.81	3097	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Rich	1	14.6	-7.52	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:48:8	36.81	3097	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Rich	1	14.6	-7.57	14.93	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:9	36.81	3095	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.51	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:9	36.81	3095	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.52	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:9	36.81	3090	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.52	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:9	36.81	3079	2.19	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.54	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:9	36.81	3051	2.19	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.54	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:9	36.81	3075	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.56	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:48:9	36.81	3076	2.19	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.58	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:0	36.81	3068	2.19	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.57	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:0	36.81	3085	2.19	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	15.05	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:0	36.81	3074	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.56	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:0	36.81	3066	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.59	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:0	36.81	3066	2.19	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.55	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:0	36.81	3076	2.19	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.57	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:1	36.81	3083	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.55	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:1	36.81	3083	2.18	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.57	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:1	36.81	3083	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.58	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:1	36.81	3089	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.61	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:49:1	36.81	3095	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.6	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:1	35.45	3097	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.61	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:1	35.45	3105	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.63	14.8	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:2	35.45	3104	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.63	14.79	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:2	35.45	3127	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.64	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:2	35.45	3112	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.6	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:2	36.81	3121	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.63	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:2	36.81	3094	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.64	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:2	36.81	3073	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.66	14.9	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:3	36.81	3084	2.18	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.66	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:3	36.81	3092	2.18	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.65	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:3	36.81	3091	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.67	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:3	36.81	3091	2.18	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.61	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:3	36.81	3086	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.61	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:3	36.81	3082	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.62	15.09	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:4	36.81	3076	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:4	36.81	3077	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.64	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:4	36.81	3078	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.65	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:4	36.81	3084	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.62	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:4	36.81	3085	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.65	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:4	36.81	3087	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.6	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:4	36.81	3086	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.61	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:5	36.81	3089	2.17	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.62	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:5	36.81	3090	2.17	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.64	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:5	36.81	3092	2.17	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.63	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:5	36.81	3090	2.17	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.65	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:5	36.81	3089	2.17	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:5	36.81	3086	2.17	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.65	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:6	36.81	3080	2.17	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.64	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:6	36.81	3079	2.17	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.64	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:6	36.81	3079	2.17	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.68	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:6	36.81	3086	2.17	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.64	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:6	36.81	3087	2.17	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.69	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:6	36.81	3086	2.17	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.69	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:6	36.81	3086	2.17	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:7	36.81	3090	2.17	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	15.04	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:7	36.81	3094	2.17	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	15.04	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:7	36.81	3105	2.17	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.67	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:7	36.81	3088	2.17	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:7	36.81	3085	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:7	36.81	3086	2.17	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.65	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:8	36.81	3084	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.68	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:8	36.81	3080	2.17	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.65	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:8	36.81	3083	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.63	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:8	36.81	3094	2.17	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.67	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:8	36.81	3095	2.17	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.63	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:8	36.81	3095	2.17	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.65	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:9	36.81	3105	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.66	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:9	36.81	3108	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.64	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:9	36.81	3096	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.69	14.83	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:49:9	36.81	3096	2.17	13.5	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.63	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:9	36.81	3094	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.67	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:9	36.81	3086	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.62	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:49:9	36.81	3086	2.17	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.64	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:50:0	36.81	3091	2.17	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.62	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:50:0	36.81	3082	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.65	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:50:0	36.81	3088	2.17	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:50:0	36.81	3085	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:50:0	36.81	3085	2.17	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:50:0	36.81	3085	2.17	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Lean	1	14.6	-7.69	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:50:1	36.81	3086	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.65	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:50:1	36.81	3088	2.17	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.69	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:1	36.81	3092	2.17	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.65	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:1	36.81	3101	2.17	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.63	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:1	36.81	3102	2.17	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.6	14.93	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:1	36.81	3102	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.6	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:1	36.81	3103	2.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.58	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:2	36.81	3103	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.62	14.81	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:2	36.81	3096	2.18	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:2	36.81	3092	2.18	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.65	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:2	36.81	3090	2.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.66	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:2	36.81	3087	2.18	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.67	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:2	36.81	3089	2.18	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.64	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:3	36.81	3090	2.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.63	14.91	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:3	36.81	3091	2.18	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.59	14.93	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:3	36.81	3100	2.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.58	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:3	36.81	3098	2.18	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.56	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:3	36.81	3097	2.19	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.5	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:3	36.81	3097	2.19	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.51	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:4	36.81	3092	2.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.46	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:4	36.81	3088	2.19	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.46	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:4	36.81	3093	2.2	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.38	15.05	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:50:4	36.81	3100	2.2	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.38	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:4	36.81	3098	2.2	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.37	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:4	36.81	3100	2.21	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.37	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:4	36.81	3108	2.21	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.35	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:5	36.81	3107	2.21	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.36	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:5	36.81	3110	2.21	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.38	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:5	36.81	3110	2.22	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.33	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:5	36.81	3110	2.22	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.17	Rich	1	14.6	-7.33	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:5	36.81	3108	2.22	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.32	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:5	36.81	3092	2.22	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.29	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:6	36.81	3094	2.23	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.29	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:6	36.81	3091	2.23	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.27	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:6	36.81	3088	2.23	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.27	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:6	36.81	3090	2.23	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.43	Lean	1	14.7	-7.31	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:6	36.81	3073	2.23	13.48	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.26	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:6	36.81	3073	2.23	13.46	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.55	Lean	1	14.7	-7.27	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:6	36.81	3101	2.23	13.48	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.27	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:7	36.81	3104	2.24	13.46	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.23	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:7	36.81	3106	2.24	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.22	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:7	36.81	3125	2.24	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.2	15.1	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:50:7	36.81	3107	2.24	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.16	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:50:7	36.81	3107	2.24	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.16	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:50:7	36.81	3114	2.25	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.07	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:50:8	36.81	3100	2.25	13.47	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.06	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:50:8	36.81	3112	2.25	13.48	95	196	Off Idle	41.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.04	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:50:8	36.81	3117	2.26	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.07	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:50:8	36.81	3116	2.26	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.03	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:50:8	36.81	3114	2.26	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.04	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:50:8	36.81	3112	2.26	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.01	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:50:9	36.81	3112	2.27	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.99	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:50:9	36.81	3108	2.27	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.96	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:50:9	36.81	3106	2.27	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.96	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:50:9	36.81	3118	2.27	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.89	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:50:9	36.81	3105	2.28	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.96	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:50:9	36.81	3105	2.28	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.88	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:50:9	36.81	3105	2.29	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.7	-6.93	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:0	36.81	3094	2.29	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.87	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:0	36.81	3098	2.29	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.89	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:0	36.81	3096	2.3	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.84	15.03	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:0	36.81	3098	2.3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.85	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:0	36.81	3105	2.3	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.8	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:0	36.81	3112	2.31	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.8	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:1	36.81	3110	2.31	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.79	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:1	36.81	3111	2.31	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.68	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:1	36.81	3121	2.31	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.7	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:1	36.81	3134	2.32	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.66	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:1	35.45	3123	2.32	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.64	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:1	35.45	3134	2.32	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.62	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:1	35.45	3133	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.7	-6.63	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:2	35.45	3133	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.61	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:2	35.45	3137	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.61	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:2	36.81	3117	2.33	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.59	14.77	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:2	36.81	3117	2.34	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.6	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:2	36.81	3116	2.34	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.61	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:2	36.81	3094	2.34	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.62	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:3	36.81	3106	2.34	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.62	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:3	36.81	3109	2.35	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.64	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:3	36.81	3114	2.35	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.63	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:3	36.81	3118	2.35	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.67	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:3	36.81	3118	2.35	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.64	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:3	36.81	3120	2.35	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.65	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:4	36.81	3123	2.35	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.67	15.05	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:4	36.81	3123	2.35	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.65	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:4	36.81	3136	2.35	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.62	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:4	36.81	3128	2.35	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.66	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:4	36.81	3128	2.35	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.64	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:4	35.45	3117	2.34	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.68	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:4	35.45	3122	2.34	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-6.64	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:5	35.45	3122	2.34	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-6.68	14.78	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:5	35.45	3121	2.34	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.65	14.76	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:5	35.45	3116	2.34	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.68	14.76	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:5	35.45	3116	2.34	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.71	14.77	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:5	35.45	3120	2.34	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.66	14.78	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:5	35.45	3123	2.34	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.68	14.78	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:6	35.45	3131	2.34	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.64	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:6	36.81	3142	2.34	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.65	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:6	36.81	3122	2.34	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.63	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:6	36.81	3139	2.34	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.73	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:6	36.81	3141	2.34	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.74	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:6	36.81	3175	2.34	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.78	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:6	36.81	3143	2.34	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.76	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:7	36.81	3140	2.34	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.76	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:7	36.81	3135	2.34	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.75	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:51:7	36.81	3134	2.34	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.76	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:7	36.81	3118	2.34	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.78	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:7	36.81	3124	2.34	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.72	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:7	36.81	3126	2.34	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.77	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:8	36.81	3126	2.34	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.71	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:8	36.81	3138	2.33	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.75	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:8	36.81	3122	2.33	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.69	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:8	36.81	3126	2.33	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.71	15.15	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:8	36.81	3126	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.7	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:51:8	36.81	3133	2.33	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.69	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:9	36.81	3142	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.67	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:9	36.81	3143	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.7	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:9	36.81	3146	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.72	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:9	36.81	3172	2.33	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.74	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:51:9	36.81	3149	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.8	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:9	36.81	3147	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.79	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:51:9	36.81	3142	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.83	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:0	36.81	3138	2.33	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.81	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:0	36.81	3113	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.81	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:0	36.81	3132	2.33	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.81	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:0	36.81	3128	2.33	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.83	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:0	36.81	3128	2.33	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.85	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:0	36.81	3132	2.33	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.82	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:1	36.81	3137	2.33	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.85	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:1	36.81	3138	2.33	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.86	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:1	36.81	3138	2.33	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.87	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:1	36.81	3147	2.33	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.85	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:1	36.81	3148	2.33	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.86	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:1	36.81	3153	2.32	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.85	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:1	36.81	3152	2.32	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.82	15.11	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:2	36.81	3152	2.32	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.8	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:2	36.81	3146	2.32	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.83	15.19	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:2	36.81	3144	2.32	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.84	15.17	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:2	36.81	3142	2.32	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.81	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:2	36.81	3143	2.32	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.84	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:2	36.81	3142	2.32	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.85	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:3	36.81	3145	2.32	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.84	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:3	36.81	3144	2.32	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.81	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:3	36.81	3145	2.32	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.84	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:3	36.81	3145	2.32	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.82	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:3	36.81	3145	2.32	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.85	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:3	36.81	3145	2.32	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.83	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:4	36.81	3123	2.32	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.83	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:4	36.81	3147	2.32	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.84	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:4	36.81	3148	2.32	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Rich	1	14.6	-6.86	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:4	36.81	3152	2.32	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.83	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:4	36.81	3171	2.32	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.85	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:4	36.81	3171	2.32	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.9	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:4	36.81	3155	2.32	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.91	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:5	36.81	3155	2.32	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.9	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:5	36.81	3180	2.31	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.9	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:5	36.81	3180	2.31	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.94	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:5	36.81	3152	2.31	13.44	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.91	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:5	36.81	3149	2.31	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.87	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:5	36.81	3149	2.31	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.89	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:6	36.81	3128	2.31	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.94	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:6	36.81	3155	2.31	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.9	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:6	36.81	3155	2.31	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.93	14.98	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:6	36.81	3181	2.31	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.99	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:6	36.81	3158	2.31	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.98	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:6	36.81	3160	2.31	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.02	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:6	36.81	3160	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.02	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:7	36.81	3162	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:7	36.81	3162	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.03	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:52:7	36.81	3164	2.3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.01	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:7	36.81	3162	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.99	14.86	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:7	36.81	3155	2.3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.05	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:52:7	36.81	3147	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.02	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:8	36.81	3146	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:8	36.81	3149	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.97	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:8	36.81	3174	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.98	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:8	36.81	3174	2.3	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.97	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:8	36.81	3153	2.3	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.96	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:8	36.81	3153	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-6.96	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:9	36.81	3166	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.92	15.13	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:9	36.81	3164	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.91	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:52:9	36.81	3164	2.3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.94	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:9	36.81	3168	2.3	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.96	15.02	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:9	36.81	3165	2.3	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.01	14.99	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:9	36.81	3166	2.29	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.02	14.96	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:52:9	36.81	3169	2.29	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.04	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:0	36.81	3174	2.29	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.02	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:0	36.81	3175	2.3	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.02	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:0	36.81	3174	2.3	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.02	14.88	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:0	36.81	3165	2.3	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.18	Rich	1	14.6	-7.01	14.9	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:53:0	36.81	3156	2.3	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.01	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:53:0	36.81	3156	2.3	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.97	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:1	36.81	3151	2.3	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.98	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:1	36.81	3178	2.3	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.98	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:1	36.81	3168	2.3	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.97	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:1	36.81	3158	2.3	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.91	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:1	36.81	3162	2.3	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.96	15.17	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:1	36.81	3162	2.3	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.95	15.2	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:1	36.81	3166	2.3	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.97	15.18	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:2	36.81	3171	2.3	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.96	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:2	36.81	3172	2.3	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.01	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:2	36.81	3172	2.3	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.97	15.02	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:2	36.81	3172	2.3	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.03	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:2	36.81	3168	2.3	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.98	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:2	36.81	3167	2.3	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.04	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:3	36.81	3168	2.3	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.98	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:3	36.81	3173	2.3	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:53:3	36.81	3177	2.3	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.96	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:3	36.81	3177	2.3	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.96	14.75	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:3	36.81	3176	2.3	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.96	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:3	36.81	3176	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:53:4	36.81	3168	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.7	-6.99	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:4	36.81	3168	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.02	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:4	36.81	3167	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.99	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:4	36.81	3162	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.98	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:4	36.81	3163	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.98	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:4	36.81	3163	2.3	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.97	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:4	36.81	3169	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.96	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:5	36.81	3172	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.98	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:5	36.81	3179	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.96	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:5	36.81	3186	2.3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.97	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:5	36.81	3187	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.99	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:5	36.81	3186	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.95	15.03	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:5	36.81	3186	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:6	36.81	3176	2.3	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:6	36.81	3171	2.3	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.98	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:6	36.81	3157	2.3	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.99	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:6	36.81	3158	2.3	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.99	14.89	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:6	36.81	3158	2.3	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.96	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:6	36.81	3160	2.3	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.96	14.83	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:53:6	36.81	3171	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:7	36.81	3172	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.95	14.8	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:7	36.81	3179	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.96	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:7	36.81	3162	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.95	14.84	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:7	36.81	3176	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.95	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:7	36.81	3188	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.96	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:7	36.81	3183	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.03	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:8	36.81	3203	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.97	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:8	36.81	3203	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.07	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:8	36.81	3172	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:8	36.81	3166	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.04	15.08	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:8	36.81	3169	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7	15.08	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:8	36.81	3168	2.3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:9	36.81	3172	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.97	15.05	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:9	36.81	3180	2.3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:9	36.81	3181	2.3	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.99	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:53:9	36.81	3188	2.3	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.97	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:9	36.81	3189	2.3	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7	14.93	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:9	36.81	3192	2.3	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.04	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:53:9	36.81	3201	2.3	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.97	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:0	36.81	3227	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.01	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:0	36.81	3192	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.02	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:0	36.81	3192	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.05	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:0	36.81	3187	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.04	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:0	36.81	3161	2.3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.04	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:0	36.81	3172	2.3	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.02	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:1	36.81	3185	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.01	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:1	36.81	3187	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.02	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:1	36.81	3188	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.04	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:1	36.81	3199	2.3	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.05	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:1	36.81	3182	2.3	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.02	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:1	36.81	3178	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.03	15.1	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:1	36.81	3180	2.3	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.01	15.11	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:2	36.81	3161	2.3	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7	15.13	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:2	36.81	3186	2.3	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7	15.14	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:2	36.81	3184	2.3	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.02	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:2	36.81	3185	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.98	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:2	36.81	3199	2.3	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.95	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:2	36.81	3199	2.3	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	-6.98	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:54:3	36.81	3184	2.3	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-6.93	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:3	36.81	3188	2.3	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.92	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:3	36.81	3193	2.31	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.87	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:3	36.81	3182	2.31	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.91	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:3	36.81	3196	2.31	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.85	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:3	36.81	3198	2.31	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.86	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:4	36.81	3203	2.31	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.83	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:4	36.81	3202	2.31	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.82	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:4	36.81	3224	2.31	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.82	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:4	36.81	3214	2.32	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.8	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:4	36.81	3200	2.32	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.81	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:4	36.81	3158	2.32	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.8	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:4	36.81	3158	2.33	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.83	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:5	36.81	3196	2.33	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.78	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:5	36.81	3190	2.33	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.84	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:5	36.81	3190	2.33	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.7	-6.82	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:5	36.81	3191	2.33	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.81	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:5	36.81	3190	2.34	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.8	15.05	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:5	36.81	3191	2.34	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.81	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:54:6	36.81	3194	2.34	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.73	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:6	36.81	3197	2.34	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.73	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:6	36.81	3191	2.34	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.76	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:6	36.81	3192	2.34	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.74	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:6	36.81	3197	2.35	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.75	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:6	36.81	3187	2.35	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.81	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:6	36.81	3199	2.35	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.76	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:7	36.81	3186	2.35	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.78	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:7	36.81	3194	2.35	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.78	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:7	36.81	3199	2.35	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.76	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:7	36.81	3201	2.35	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.72	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:7	36.81	3213	2.35	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.73	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:54:7	36.81	3216	2.35	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.74	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:54:8	36.81	3218	2.35	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.75	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:8	36.81	3222	2.35	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.75	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:8	36.81	3222	2.35	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.78	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:8	36.81	3221	2.35	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.76	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:8	36.81	3220	2.35	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.73	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:8	36.81	3214	2.35	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.77	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:9	36.81	3204	2.36	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.75	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:9	36.81	3204	2.36	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.75	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:54:9	36.81	3196	2.36	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.75	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:9	36.81	3193	2.36	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.77	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:9	36.81	3192	2.36	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.77	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:9	36.81	3178	2.36	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.77	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:54:9	36.81	3198	2.36	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.75	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:55:0	36.81	3209	2.36	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.74	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:0	36.81	3210	2.36	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.69	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:0	36.81	3235	2.36	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.68	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:0	35.45	3222	2.36	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.69	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:0	35.45	3222	2.36	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.68	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:0	35.45	3225	2.37	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.66	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:1	35.45	3200	2.37	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.7	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:1	36.81	3208	2.37	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.6	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:1	36.81	3226	2.37	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.56	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:1	36.81	3213	2.37	13.5	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.56	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:1	36.81	3212	2.37	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.51	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:55:1	36.81	3228	2.38	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.53	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:1	35.45	3186	2.38	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.54	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:55:2	35.45	3211	2.38	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.53	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:55:2	35.45	3206	2.39	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.49	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:2	35.45	3208	2.39	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.42	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:2	35.45	3218	2.4	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.39	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:2	36.81	3218	2.4	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.39	15.05	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:2	36.81	3220	2.4	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.27	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:3	36.81	3225	2.41	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.28	15.02	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:3	36.81	3228	2.41	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.3	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:3	36.81	3224	2.42	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.2	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:3	35.45	3212	2.42	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.17	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:3	35.45	3218	2.43	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.17	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:3	35.45	3219	2.43	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.13	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:4	35.45	3196	2.43	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-6.13	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:4	35.45	3223	2.44	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.1	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:4	35.45	3226	2.44	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.09	14.83	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:4	35.45	3226	2.45	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.04	14.82	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:4	35.45	3238	2.45	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.08	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:4	35.45	3224	2.45	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.08	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:4	35.45	3223	2.46	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.13	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:55:8	35.45	3220	2.46	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.06	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3216	2.46	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.13	14.9	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3213	2.46	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.1	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3214	2.47	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.1	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3218	2.47	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.09	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3225	2.47	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.1	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3225	2.47	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.08	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3233	2.47	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.08	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3239	2.47	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.05	14.9	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3239	2.48	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.04	14.88	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3264	2.48	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.02	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3232	2.48	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.02	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3229	2.48	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.98	14.77	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:55:7	35.45	3235	2.48	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.99	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:7	35.45	3234	2.48	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.95	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:7	35.45	3232	2.48	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.99	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:7	35.45	3236	2.48	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.98	14.79	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:7	35.45	3238	2.48	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.96	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:7	35.45	3242	2.48	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.95	14.8	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3227	2.49	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-5.97	14.84	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3227	2.49	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.97	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3252	2.49	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-5.87	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3249	2.49	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.89	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3246	2.5	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.85	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:8	35.45	3236	2.5	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.86	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:9	35.45	3236	2.5	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.84	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:9	35.45	3240	2.51	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-5.81	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:9	36.81	3240	2.51	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.81	15.09	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:9	36.81	3245	2.51	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.82	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:9	36.81	3248	2.51	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.73	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:9	36.81	3252	2.52	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.77	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:55:9	36.81	3251	2.52	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.71	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:0	35.45	3238	2.52	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.67	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:0	35.45	3248	2.53	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.66	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:0	35.45	3249	2.53	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.61	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:0	35.45	3254	2.53	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.6	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:0	35.45	3254	2.54	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.6	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:0	35.45	3266	2.54	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.56	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:1	35.45	3257	2.54	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.54	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:1	35.45	3267	2.55	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.53	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:1	35.45	3268	2.55	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.51	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:1	36.81	3272	2.55	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.5	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:1	36.81	3275	2.55	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.51	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:1	36.81	3274	2.56	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.7	-5.56	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:1	36.81	3269	2.56	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.53	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:2	36.81	3263	2.56	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.55	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:2	36.81	3260	2.57	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.54	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:2	36.81	3252	2.57	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.56	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:2	36.81	3244	2.57	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.56	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:2	36.81	3244	2.57	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.53	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:2	36.81	3244	2.57	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.55	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:3	35.45	3248	2.57	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.54	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:3	35.45	3252	2.57	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.51	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:3	35.45	3254	2.57	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.56	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:3	35.45	3266	2.57	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.55	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:3	35.45	3245	2.57	13.47	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.51	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:3	35.45	3274	2.57	13.49	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.52	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:4	35.45	3274	2.57	13.47	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.5	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:56:4	35.45	3276	2.57	13.47	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.51	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:4	35.45	3297	2.57	13.49	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.5	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:4	36.81	3280	2.58	13.47	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.5	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:4	36.81	3270	2.58	13.46	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.49	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:4	36.81	3276	2.58	13.48	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.51	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:4	36.81	3277	2.58	13.47	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.46	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:5	35.45	3293	2.58	13.48	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.53	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:5	35.45	3281	2.58	13.48	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.5	14.83	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:5	35.45	3281	2.58	13.46	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.52	14.85	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:5	35.45	3280	2.58	13.47	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.55	14.87	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:5	35.45	3273	2.58	13.47	94	196	Off Idle	41.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.48	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:5	35.45	3269	2.58	13.46	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.47	14.9	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:6	35.45	3267	2.58	13.47	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.47	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:6	35.45	3256	2.58	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.43	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:6	35.45	3261	2.58	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.43	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:6	35.45	3236	2.58	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.4	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:6	35.45	3268	2.59	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.36	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:6	35.45	3278	2.59	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.38	15	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:6	35.45	3281	2.59	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.37	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:7	35.45	3284	2.59	13.44	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.37	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:7	36.81	3299	2.59	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.37	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:7	36.81	3288	2.59	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.33	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:7	36.81	3288	2.6	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.31	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:7	36.81	3292	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.33	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:7	36.81	3282	2.6	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.22	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:8	35.45	3307	2.61	13.47	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.19	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:8	35.45	3308	2.61	13.48	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.21	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:8	35.45	3313	2.61	13.49	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.16	14.83	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:8	35.45	3314	2.61	13.49	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.18	14.84	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:8	35.45	3314	2.62	13.5	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.19	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:22:56:8	35.45	3306	2.62	13.5	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.18	14.89	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:9	35.45	3299	2.62	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.2	14.92	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:9	35.45	3297	2.62	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.16	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:9	35.45	3294	2.63	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.2	14.98	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:9	35.45	3285	2.63	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.2	15.03	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:56:9	35.45	3278	2.63	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.19	15.06	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:9	35.45	3277	2.63	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.22	15.09	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:56:9	35.45	3279	2.63	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.24	15.07	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:0	35.45	3291	2.63	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.21	15.07	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:0	35.45	3298	2.63	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.22	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:0	35.45	3295	2.63	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.2	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:0	35.45	3295	2.63	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-5.2	14.95	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:0	35.45	3302	2.63	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.22	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:0	35.45	3305	2.63	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.2	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:1	35.45	3305	2.63	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.22	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:57:1	35.45	3320	2.62	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.3	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:57:1	35.45	3312	2.62	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.3	14.78	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:57:1	35.45	3311	2.62	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.39	14.75	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:1	35.45	3311	2.62	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.39	14.75	1	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:1	35.45	3300	2.62	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.39	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:1	35.45	3317	2.61	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.41	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:2	35.45	3316	2.61	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.39	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:57:2	35.45	3315	2.61	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.39	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:57:2	35.45	3318	2.61	13.5	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.37	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:2	35.45	3318	2.61	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.35	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:2	35.45	3324	2.61	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.43	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:2	35.45	3338	2.6	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.39	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:3	36.81	3327	2.6	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.44	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:57:3	36.81	3316	2.6	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.47	15.04	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:3	36.81	3317	2.6	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.46	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:3	36.81	3317	2.6	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.46	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:3	35.45	3316	2.6	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.5	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:3	35.45	3322	2.6	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.49	14.94	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:4	35.45	3319	2.6	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.56	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:4	35.45	3320	2.59	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.57	14.88	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:4	35.45	3324	2.59	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.5	14.82	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:4	35.45	3326	2.59	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.54	14.78	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:4	35.45	3324	2.59	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.55	14.76	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:4	35.45	3318	2.59	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.52	14.75	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:4	35.45	3320	2.59	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.55	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:5	36.81	3324	2.59	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.55	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:5	36.81	3331	2.58	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.56	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:5	36.81	3336	2.58	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.58	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:5	36.81	3338	2.58	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.57	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:5	36.81	3356	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.62	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:5	35.45	3353	2.58	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.65	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:6	35.45	3348	2.58	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.6	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:6	35.45	3337	2.58	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.66	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:6	35.45	3332	2.58	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.7	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:6	35.45	3333	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.63	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:6	35.45	3332	2.58	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.71	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:6	35.45	3327	2.58	13.5	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.68	14.98	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:6	35.45	3323	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.65	14.95	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:7	35.45	3323	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.7	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:7	35.45	3324	2.58	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.71	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:7	35.45	3327	2.58	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.65	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:7	35.45	3327	2.58	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.69	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:7	35.45	3335	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.66	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:7	35.45	3363	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.69	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:8	36.81	3352	2.58	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.73	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:8	36.81	3345	2.58	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.68	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:8	36.81	3342	2.58	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.68	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:8	36.81	3341	2.58	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.7	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:8	36.81	3334	2.57	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.61	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:8	36.81	3336	2.58	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.61	15.08	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:9	36.81	3336	2.58	13.5	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.66	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:9	36.81	3336	2.58	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.6	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:57:9	36.81	3328	2.58	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.66	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:9	36.81	3328	2.58	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.66	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:9	36.81	3345	2.58	13.5	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.69	14.95	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:9	36.81	3356	2.58	13.5	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.68	14.93	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:57:9	36.81	3394	2.58	13.5	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.7	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:58:0	36.81	3372	2.58	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.68	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:58:0	36.81	3371	2.58	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.65	14.79	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:58:0	36.81	3367	2.58	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.66	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:0	36.81	3384	2.58	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.68	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:22:58:0	36.81	3350	2.58	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.6	14.92	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:0	36.81	3348	2.59	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.6	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:1	36.81	3342	2.59	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.56	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:1	36.81	3342	2.59	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.52	15.03	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:1	36.81	3344	2.59	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.49	15.11	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:1	35.45	3338	2.59	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	-5.44	15.16	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:1	35.45	3352	2.59	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-5.5	15.18	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:1	35.45	3351	2.59	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Lean	1	14.7	-5.55	15.16	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:1	35.45	3353	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Lean	1	14.6	-5.55	15.1	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:2	35.45	3352	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.61	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:58:2	35.45	3356	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.62	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:2	35.45	3362	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.57	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:2	35.45	3363	2.6	13.44	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.58	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:2	35.45	3396	2.6	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.58	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:2	35.45	3373	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.58	14.74	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:3	35.45	3370	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.57	14.74	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:3	35.45	3367	2.6	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.6	14.74	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:3	35.45	3346	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.63	14.74	1	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:3	35.45	3367	2.6	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.56	14.8	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:3	36.81	3366	2.6	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.55	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:3	36.81	3348	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.6	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:4	36.81	3356	2.6	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.54	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:4	36.81	3368	2.6	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.59	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:4	36.81	3369	2.6	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.61	14.84	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:4	36.81	3385	2.6	13.5	94	196	Off Idle	41.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.59	14.85	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:4	36.81	3387	2.6	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.61	14.86	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:4	36.81	3416	2.6	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.64	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:4	36.81	3385	2.6	13.49	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.62	14.92	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:5	36.81	3384	2.6	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.61	14.95	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:5	36.81	3379	2.6	13.5	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.69	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:5	36.81	3375	2.6	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.65	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:5	36.81	3370	2.6	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.71	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:5	36.81	3364	2.59	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.72	15.07	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:5	36.81	3369	2.59	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.65	15.09	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:6	36.81	3370	2.59	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.67	15.09	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:58:6	36.81	3379	2.59	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.71	15.08	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:6	36.81	3388	2.59	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.64	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:6	36.81	3390	2.59	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.65	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:6	36.81	3390	2.59	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-5.72	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:6	36.81	3362	2.59	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.67	14.95	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:6	36.81	3379	2.59	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.71	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:7	36.81	3380	2.59	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-5.74	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:7	36.81	3386	2.59	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.7	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:7	36.81	3390	2.59	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.74	14.82	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:7	36.81	3391	2.59	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.81	14.79	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:7	36.81	3394	2.59	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.75	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:7	36.81	3394	2.59	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.75	14.81	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:22:58:8	36.81	3394	2.59	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.74	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:8	36.81	3386	2.59	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-5.7	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:8	36.81	3382	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.75	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:8	36.81	3380	2.58	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.74	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:58:8	36.81	3378	2.58	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.73	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:58:8	36.81	3402	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.83	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:58:9	36.81	3390	2.58	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-5.81	15.05	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:58:9	36.81	3384	2.58	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.81	15.03	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:58:9	36.81	3388	2.58	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.86	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:58:9	36.81	3389	2.58	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.85	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:58:9	36.81	3392	2.58	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.81	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:58:9	36.81	3410	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.9	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:58:9	36.81	3404	2.58	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5.91	14.89	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:59:0	36.81	3392	2.58	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.86	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:59:0	36.81	3380	2.57	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.93	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:59:0	36.81	3398	2.57	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.92	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:59:0	36.81	3398	2.57	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.95	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:59:0	36.81	3404	2.57	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.98	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:59:0	36.81	3404	2.57	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-5.91	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:59:1	36.81	3399	2.57	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.88	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:22:59:1	36.81	3399	2.57	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.95	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:22:59:1	36.81	3400	2.56	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.93	14.9	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:1	36.81	3398	2.56	13.48	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.98	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:1	36.81	3404	2.56	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:1	36.81	3398	2.56	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.99	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:1	36.81	3395	2.56	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.02	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:59:2	36.81	3392	2.55	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.03	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:59:2	36.81	3401	2.55	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.09	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:59:2	36.81	3390	2.55	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.13	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:2	36.81	3388	2.55	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.11	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:2	36.81	3392	2.54	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.19	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:2	36.81	3404	2.54	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.12	15.01	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:3	36.81	3406	2.54	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.11	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:3	36.81	3416	2.54	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.2	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:3	36.81	3418	2.53	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.19	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:3	36.81	3421	2.53	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.2	14.81	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:3	36.81	3421	2.53	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.32	14.83	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:3	36.81	3424	2.53	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.33	14.86	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:22:59:4	36.81	3425	2.52	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.38	14.86	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:59:4	36.81	3434	2.52	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.42	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:59:4	36.81	3414	2.51	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.45	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:22:59:4	36.81	3406	2.51	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.44	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:59:4	36.81	3400	2.5	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.54	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:59:4	36.81	3402	2.5	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.58	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:22:59:4	36.81	3400	2.49	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.56	15.05	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:5	36.81	3398	2.49	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.64	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:5	36.81	3402	2.48	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.69	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:5	36.81	3408	2.48	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.66	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:5	36.81	3408	2.47	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.72	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:5	36.81	3408	2.46	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.81	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:5	36.81	3398	2.46	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.82	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:6	36.81	3403	2.45	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.84	14.9	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:6	36.81	3402	2.45	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.93	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:6	36.81	3400	2.44	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.9	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:6	36.81	3398	2.44	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.89	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:6	36.81	3404	2.43	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.96	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:6	36.81	3416	2.42	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.96	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:6	36.81	3416	2.41	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.96	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:7	36.81	3426	2.41	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.04	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:7	36.81	3409	2.4	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.01	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:7	36.81	3418	2.4	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.06	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:7	36.81	3426	2.39	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.13	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:7	36.81	3418	2.39	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.12	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:7	36.81	3418	2.38	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.12	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:8	36.81	3440	2.38	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.23	15.14	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:8	36.81	3408	2.36	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.35	15.18	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:22:59:8	36.81	3408	2.34	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.48	15.21	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:22:59:8	36.81	3409	2.32	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.73	15.22	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:59:8	36.81	3404	2.3	13.49	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.98	15.2	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:22:59:8	36.81	3437	2.26	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.19	15.17	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:22:59:9	38.18	3424	2.23	13.46	94	196	Full Load	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.53	15.13	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:9	38.18	3406	2.21	13.47	94	196	Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.68	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:22:59:9	38.18	3397	2.16	13.46	94	196	Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.06	15.07	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:9	38.18	3391	2.13	13.45	94	196	Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.32	15.01	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:9	38.18	3374	2.08	13.49	94	196	Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.44	14.99	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:9	38.18	3356	2.05	13.5	94	196	Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.63	14.93	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:22:59:9	38.18	3344	2.01	13.5	94	196	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.72	14.89	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:00:0	38.18	3327	1.98	13.5	94	196	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.77	14.88	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:0	38.18	3322	1.93	13.5	94	196	Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.82	14.85	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:00:0	35.45	3256	1.9	13.5	94	196	Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.84	14.82	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:00:0	29.99	3235	1.87	13.48	94	196	Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.86	14.78	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:0	24.54	3220	1.83	13.49	94	196	Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.89	14.73	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:0	20.45	3228	1.8	13.5	94	196	Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.9	14.67	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:1	20.45	3235	1.78	13.48	94	196	Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.89	14.61	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:1	20.45	3214	1.75	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.93	14.55	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:1	20.45	3205	1.73	13.49	94	196	Idle	40.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.92	14.5	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:1	20.45	3176	1.71	13.49	94	196	Idle	40.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.93	14.46	0.98	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:1	20.45	3139	1.71	13.49	94	196	Idle	40	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.87	14.44	0.98	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:1	20.45	3139	1.71	13.49	94	196	Idle	39.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.87	14.44	0.98	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:1	20.45	3098	1.71	13.47	94	196	Idle	38.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.8	14.45	0.98	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:2	20.45	3074	1.71	13.48	94	196	Idle	38.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.71	14.5	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:2	20.45	3027	1.72	13.48	94	196	Idle	37.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.61	14.54	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:2	20.45	3027	1.72	13.48	94	196	Idle	36.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.58	14.58	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:2	19.09	2978	1.72	13.48	94	196	Idle	36.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.52	14.63	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:2	19.09	2965	1.72	13.48	94	196	Idle	35.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.52	14.7	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:2	19.09	2956	1.73	13.48	94	196	Idle	34.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.46	14.78	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:3	19.09	2936	1.73	13.48	94	196	Idle	33.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.45	14.87	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:3	19.09	2902	1.73	13.46	94	196	Idle	32.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.37	14.93	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:3	19.09	2853	1.74	13.47	94	196	Idle	32	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.35	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:3	19.09	2853	1.75	13.47	94	196	Idle	31.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.31	15.15	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:3	19.09	2820	1.75	13.47	94	196	Idle	30.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.24	15.24	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:3	19.09	2788	1.76	13.47	94	196	Idle	30	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	15.34	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:4	19.09	2780	1.76	13.47	94	196	Idle	29.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.16	15.49	1.06	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:4	19.09	2740	1.77	13.47	94	196	Idle	29.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	15.66	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:4	19.09	2740	1.78	13.46	94	196	Idle	29.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	16.04	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:4	19.09	2714	1.78	13.48	94	195	Idle	29.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.03	16.45	1.12	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:4	19.09	2672	1.79	13.46	94	195	Idle	29.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9	16.92	1.15	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:4	19.09	2659	1.79	13.46	94	195	Idle	29.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.98	17.38	1.18	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:4	19.09	2640	1.8	13.47	94	196	Idle	29.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9	17.84	1.21	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:5	19.09	2615	1.8	13.47	94	196	Idle	29.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.99	18.29	1.25	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:5	19.09	2615	1.8	13.47	94	196	Idle	30	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	18.73	1.28	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:5	19.09	2555	1.81	13.46	94	196	Idle	30.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	19.16	1.31	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:5	19.09	2540	1.81	13.45	94	196	Full Load	31.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	19.74	1.34	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:5	19.09	2532	1.81	13.47	94	196	Off Idle	32.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.89	20.03	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:5	19.09	2489	1.81	13.47	94	196	Off Idle	33.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.85	20.19	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:6	19.09	2473	1.81	13.47	94	196	Off Idle	34.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.78	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:6	19.09	2402	1.81	13.46	94	196	Off Idle	36.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.74	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:00:6	10.9	2438	1.81	13.47	94	196	Off Idle	39	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.62	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:00:6	13.63	2423	1.81	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.54	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:00:6	13.63	2407	1.82	13.45	94	196	Off Idle	44.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.47	20.24	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:00:6	16.36	2400	1.82	13.45	94	196	Off Idle	46.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.39	20.24	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:00:6	16.36	2361	1.82	13.49	94	196	Off Idle	49.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.35	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:00:7	19.09	2378	1.81	13.48	94	196	Off Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.31	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:00:7	21.81	2381	1.81	13.48	94	196	Off Idle	54.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.29	20.23	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:00:7	21.81	2410	1.81	13.48	94	196	Off Idle	57.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.24	20.24	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:00:7	24.54	2475	1.82	13.49	94	196	Off Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.2	20.24	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:00:7	27.27	2475	1.84	13.47	94	196	Off Idle	62	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.1	20.24	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:00:7	27.27	2521	1.85	13.48	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.05	20.25	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:00:8	29.99	2574	1.86	13.48	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.99	20.25	1.38	3.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:00:8	32.72	2634	1.87	13.47	94	196	Off Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.93	20.25	1.38	3.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:00:8	32.72	2620	1.88	13.49	94	196	Off Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.87	20.24	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:00:8	34.08	2598	1.9	13.48	94	196	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.79	20.25	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:00:8	34.08	2601	1.92	13.49	94	196	Off Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.75	20.26	1.38	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:00:8	34.08	2601	1.93	13.48	94	196	Off Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.67	20.26	1.38	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:00:9	34.08	2588	1.96	13.48	94	196	Off Idle	67.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.53	20.26	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:00:9	34.08	2516	1.97	13.49	94	196	Off Idle	67	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.44	20.26	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:00:9	34.08	2471	1.98	13.46	94	196	Off Idle	66.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.37	20.26	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:00:9	34.08	2471	2	13.46	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.25	20.26	1.38	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:00:9	34.08	2404	2.01	13.47	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.14	20.26	1.38	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:00:9	34.08	2448	2.02	13.48	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.06	20.26	1.38	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:00:9	34.08	2448	2.03	13.47	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.99	20.25	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:0	34.08	2478	2.05	13.48	94	196	Off Idle	64	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.91	20.18	1.37	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:0	34.08	2497	2.07	13.48	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.87	20.05	1.37	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:0	34.08	2514	2.08	13.47	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.89	19.95	1.36	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:0	34.08	2542	2.08	13.47	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.9	19.7	1.34	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:0	34.08	2549	2.08	13.48	94	196	Off Idle	64.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.88	19.41	1.32	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:0	34.08	2559	2.09	13.48	94	196	Off Idle	65	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.96	19.11	1.3	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:1	34.08	2573	2.09	13.48	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.99	18.76	1.28	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:1	34.08	2555	2.1	13.48	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.01	18.41	1.25	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:1	34.08	2508	2.1	13.48	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.05	18.03	1.23	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:1	34.08	2481	2.1	13.48	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.03	17.65	1.2	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:1	34.08	2475	2.09	13.46	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.01	17.31	1.18	3.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:1	34.08	2452	2.09	13.47	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.97	16.86	1.15	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:1	34.08	2463	2.09	13.45	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.96	16.57	1.13	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:2	34.08	2463	2.09	13.46	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.97	16.49	1.12	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:2	34.08	2475	2.08	13.48	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.94	16.25	1.11	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:2	34.08	2494	2.08	13.47	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.92	16.12	1.1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:2	34.08	2513	2.08	13.47	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.92	16	1.09	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:2	34.08	2521	2.07	13.48	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.94	15.81	1.08	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:2	34.08	2546	2.07	13.48	94	196	Off Idle	65.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.99	15.75	1.07	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:3	34.08	2566	2.07	13.48	94	196	Off Idle	66	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.04	15.59	1.06	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:3	34.08	2566	2.07	13.47	94	196	Off Idle	66	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.08	15.5	1.06	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:3	34.08	2548	2.07	13.47	94	196	Off Idle	66	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.09	15.42	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:3	34.08	2543	2.07	13.46	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.08	15.36	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:3	34.08	2508	2.07	13.46	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.07	15.34	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:3	34.08	2496	2.07	13.47	94	196	Off Idle	65.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.03	15.35	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:4	34.08	2496	2.07	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.01	15.38	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:4	34.08	2478	2.07	13.47	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.01	15.42	1.05	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:4	34.08	2450	2.07	13.46	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.99	15.47	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:4	34.08	2468	2.07	13.47	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.96	15.52	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:4	34.08	2487	2.07	13.46	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.96	15.56	1.06	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:4	34.08	2506	2.07	13.47	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.94	15.6	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:4	34.08	2538	2.07	13.49	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.94	15.61	1.06	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:5	34.08	2543	2.07	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.96	15.59	1.06	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:5	34.08	2546	2.07	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.99	15.56	1.06	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:5	34.08	2546	2.07	13.49	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.03	15.54	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:5	34.08	2539	2.07	13.47	94	196	Off Idle	65	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.05	15.48	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:5	34.08	2539	2.07	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.08	15.45	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:5	34.08	2518	2.07	13.47	94	196	Off Idle	65.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.12	15.4	1.05	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:6	34.08	2505	2.07	13.47	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.08	15.38	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:6	34.08	2505	2.07	13.46	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.07	15.36	1.05	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:6	34.08	2494	2.07	13.48	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.07	15.34	1.05	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:6	34.08	2485	2.07	13.46	94	196	Off Idle	65.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.06	15.33	1.04	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:6	34.08	2499	2.07	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.03	15.31	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:01:6	34.08	2502	2.07	13.47	94	196	Off Idle	65	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.05	15.29	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:6	34.08	2510	2.07	13.46	94	196	Off Idle	65	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.06	15.28	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:7	34.08	2527	2.06	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.09	15.29	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:7	34.08	2527	2.06	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.08	15.24	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:7	34.08	2537	2.06	13.46	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.06	15.22	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:7	34.08	2564	2.06	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.06	15.15	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:7	34.08	2545	2.06	13.49	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.06	15.1	1.03	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:7	34.08	2543	2.06	13.48	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.09	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:8	34.08	2539	2.06	13.48	94	196	Off Idle	65	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.11	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:8	34.08	2525	2.07	13.47	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.13	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:8	34.08	2510	2.07	13.47	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.1	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:01:8	34.08	2492	2.07	13.46	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.08	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:8	34.08	2481	2.07	13.45	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.06	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:8	34.08	2481	2.07	13.46	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.06	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:9	34.08	2481	2.07	13.47	94	196	Off Idle	65	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.04	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:9	34.08	2487	2.07	13.46	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.03	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:9	34.08	2499	2.06	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.04	15.17	1.03	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:9	34.08	2505	2.06	13.47	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.08	15.24	1.04	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:01:9	34.08	2526	2.06	13.48	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.09	15.27	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:9	34.08	2539	2.06	13.48	94	196	Off Idle	65.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.16	15.27	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:01:9	34.08	2541	2.06	13.48	94	196	Off Idle	65.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.16	15.28	1.04	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:0	34.08	2538	2.06	13.49	94	196	Off Idle	65.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.19	15.26	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:0	34.08	2550	2.06	13.48	94	196	Off Idle	65.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.21	15.23	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:0	34.08	2550	2.06	13.47	94	196	Off Idle	65.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.19	15.22	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:0	34.08	2518	2.06	13.48	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.18	15.18	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:0	34.08	2506	2.06	13.49	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.18	15.16	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:0	34.08	2496	2.06	13.47	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.19	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:1	34.08	2496	2.06	13.47	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.16	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:1	34.08	2495	2.05	13.46	94	196	Off Idle	65.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.13	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:1	34.08	2503	2.05	13.47	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.12	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:1	34.08	2511	2.05	13.47	94	196	Off Idle	65	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.11	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:1	34.08	2516	2.05	13.48	94	196	Off Idle	64.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.13	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:1	34.08	2528	2.05	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.14	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:1	34.08	2536	2.05	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.13	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:2	34.08	2536	2.05	13.45	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.16	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:2	34.08	2539	2.05	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.16	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:2	34.08	2537	2.05	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.16	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:2	34.08	2531	2.05	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.19	14.9	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:2	34.08	2522	2.05	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.18	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:2	34.08	2511	2.05	13.44	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.16	14.8	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:3	34.08	2510	2.06	13.44	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.17	14.78	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:3	34.08	2504	2.06	13.45	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.16	14.77	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:3	34.08	2507	2.06	13.45	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.14	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:3	34.08	2509	2.05	13.46	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.16	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:3	34.08	2516	2.05	13.46	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.16	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:3	34.08	2522	2.05	13.46	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.16	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:4	34.08	2525	2.05	13.45	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.2	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:4	34.08	2535	2.05	13.45	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.23	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:4	34.08	2554	2.05	13.47	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.26	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:4	34.08	2546	2.05	13.46	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.27	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:4	34.08	2545	2.05	13.46	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.27	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:4	34.08	2539	2.05	13.46	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.29	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:4	34.08	2532	2.05	13.49	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.29	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:02:5	34.08	2532	2.05	13.47	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.27	14.98	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:5	34.08	2512	2.05	13.48	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.25	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:5	34.08	2488	2.05	13.48	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.21	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:5	34.08	2509	2.05	13.5	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.19	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:5	34.08	2512	2.05	13.48	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.19	14.85	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:5	34.08	2527	2.05	13.48	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.18	14.84	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:6	34.08	2536	2.05	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.19	14.83	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:6	34.08	2536	2.05	13.49	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.22	14.82	1.01	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:6	34.08	2548	2.04	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.26	14.82	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:6	34.08	2548	2.04	13.47	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.26	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:6	34.08	2545	2.04	13.48	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.27	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:6	34.08	2545	2.04	13.48	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.3	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:6	34.08	2524	2.04	13.47	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.28	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:7	34.08	2520	2.04	13.48	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.27	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:7	34.08	2518	2.04	13.49	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.27	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:02:7	34.08	2504	2.04	13.49	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.23	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:02:7	34.08	2516	2.05	13.49	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.26	15.06	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:7	34.08	2522	2.04	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.23	15.09	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:7	34.08	2524	2.04	13.47	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.24	15.14	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:8	34.08	2530	2.04	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.23	15.17	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:8	34.08	2530	2.04	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.27	15.19	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:8	34.08	2530	2.04	13.47	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.27	15.2	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:8	34.08	2523	2.04	13.48	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.27	15.2	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:8	34.08	2520	2.04	13.49	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.29	15.2	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:8	34.08	2520	2.04	13.5	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.31	15.16	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:9	34.08	2514	2.04	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.32	15.13	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:9	34.08	2513	2.04	13.47	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.35	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:9	34.08	2511	2.03	13.47	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.4	15.07	1.03	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:02:9	34.08	2512	2.02	13.47	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.42	15.03	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:02:9	34.08	2530	2.02	13.47	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.48	15.01	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:02:9	34.08	2531	2.02	13.48	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.53	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:02:9	34.08	2535	2.01	13.49	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.57	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:0	34.08	2535	2.01	13.48	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.58	14.92	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:0	34.08	2540	2	13.49	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.61	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:0	34.08	2545	2	13.49	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.63	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:0	34.08	2545	2	13.49	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.68	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:0	34.08	2544	1.99	13.49	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.67	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:0	34.08	2541	1.99	13.48	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:1	34.08	2539	1.98	13.48	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.73	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:1	34.08	2531	1.98	13.48	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.75	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:1	34.08	2499	1.97	13.49	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.76	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:1	34.08	2499	1.97	13.48	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.81	14.91	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:03:1	34.08	2512	1.96	13.48	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.86	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:1	34.08	2514	1.96	13.48	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.86	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:1	34.08	2514	1.95	13.47	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.89	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:2	34.08	2538	1.95	13.47	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.91	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:2	34.08	2520	1.95	13.47	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.93	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:2	34.08	2530	1.95	13.45	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.96	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:2	34.08	2532	1.95	13.46	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.98	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:2	34.08	2526	1.94	13.46	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:2	34.08	2540	1.94	13.45	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.04	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:3	34.08	2540	1.94	13.46	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.03	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:3	34.08	2533	1.93	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.02	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:3	34.08	2549	1.93	13.46	94	196	Off Idle	64.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.07	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:3	34.08	2522	1.93	13.45	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.06	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:3	34.08	2523	1.93	13.47	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.1	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:3	34.08	2526	1.92	13.46	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.09	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:4	35.45	2504	1.92	13.47	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.11	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:4	35.45	2515	1.92	13.49	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.1	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:4	35.45	2529	1.91	13.49	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.14	14.9	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:4	35.45	2534	1.91	13.49	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.16	14.89	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:4	35.45	2536	1.91	13.49	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.17	14.88	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:4	35.45	2557	1.91	13.49	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.17	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:4	35.45	2540	1.91	13.48	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.2	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:5	35.45	2539	1.91	13.47	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.21	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:5	35.45	2534	1.91	13.48	94	196	Off Idle	65	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.22	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:5	35.45	2536	1.9	13.49	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.23	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:5	35.45	2534	1.9	13.48	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.22	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:5	35.45	2534	1.9	13.48	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.23	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:5	35.45	2532	1.9	13.49	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.23	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:6	35.45	2520	1.9	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.25	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:6	35.45	2529	1.9	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.24	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:6	35.45	2526	1.9	13.46	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.24	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:6	35.45	2527	1.9	13.48	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.26	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:03:6	35.45	2535	1.9	13.46	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.24	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:6	35.45	2536	1.89	13.46	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.25	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:6	35.45	2536	1.89	13.47	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.22	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:7	35.45	2536	1.89	13.48	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.25	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:7	35.45	2535	1.89	13.47	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.28	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:7	35.45	2533	1.89	13.46	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.25	15.05	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:7	35.45	2525	1.89	13.46	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.27	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:7	35.45	2522	1.89	13.46	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.26	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:7	35.45	2522	1.89	13.47	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.26	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:8	35.45	2522	1.89	13.47	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.24	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:8	35.45	2521	1.89	13.47	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.21	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:8	35.45	2529	1.89	13.49	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.21	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:8	35.45	2529	1.89	13.48	94	196	Off Idle	64	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.2	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:8	35.45	2552	1.89	13.48	94	196	Off Idle	64	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.22	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:8	35.45	2535	1.89	13.47	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.21	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:9	35.45	2535	1.89	13.48	94	196	Off Idle	63.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.25	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:9	35.45	2532	1.89	13.47	94	196	Off Idle	63.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.29	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:03:9	35.45	2530	1.89	13.47	94	196	Off Idle	63.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.29	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:9	35.45	2530	1.89	13.46	94	196	Off Idle	63.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.31	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:9	35.45	2530	1.89	13.47	94	196	Off Idle	63.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.31	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:9	35.45	2489	1.88	13.46	94	196	Off Idle	63.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.37	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:03:9	35.45	2508	1.88	13.48	94	196	Off Idle	63.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.35	14.89	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:0	35.45	2523	1.88	13.46	94	196	Off Idle	63.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.39	14.89	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:0	35.45	2529	1.88	13.47	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.41	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:0	35.45	2529	1.87	13.49	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.44	14.85	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:0	35.45	2536	1.87	13.49	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.51	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:0	35.45	2538	1.86	13.48	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.56	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:0	35.45	2537	1.86	13.48	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.59	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:1	35.45	2532	1.85	13.49	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.61	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:1	35.45	2524	1.85	13.48	94	196	Off Idle	64	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.65	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:1	35.45	2527	1.84	13.47	94	196	Off Idle	64	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.64	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:1	35.45	2524	1.84	13.47	94	196	Off Idle	64	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.65	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:1	35.45	2524	1.84	13.46	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.66	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:1	35.45	2528	1.83	13.45	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.69	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:1	35.45	2528	1.83	13.46	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.67	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:2	35.45	2528	1.83	13.47	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.71	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:2	35.45	2523	1.82	13.47	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.7	15.07	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:2	35.45	2534	1.82	13.49	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.73	15.06	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:2	35.45	2535	1.81	13.49	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.73	15.04	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:2	35.45	2536	1.81	13.48	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.76	15.03	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:2	35.45	2546	1.81	13.49	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.76	15.01	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:3	35.45	2538	1.81	13.47	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.8	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:3	35.45	2537	1.8	13.45	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.79	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:3	35.45	2526	1.8	13.45	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.79	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:3	35.45	2534	1.8	13.46	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.81	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:3	35.45	2532	1.8	13.46	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.82	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:3	35.45	2527	1.8	13.46	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.8	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:4	35.45	2526	1.8	13.48	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.8	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:4	35.45	2526	1.8	13.48	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.8	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:4	35.45	2528	1.8	13.47	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.83	14.83	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:4	35.45	2525	1.8	13.47	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.8	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:4	35.45	2520	1.8	13.48	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.81	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:4	35.45	2520	1.8	13.48	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.83	14.82	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:4	35.45	2533	1.8	13.46	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.81	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:5	35.45	2524	1.8	13.46	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.79	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:5	35.45	2523	1.8	13.48	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.79	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:5	35.45	2524	1.8	13.45	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.79	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:5	35.45	2524	1.8	13.47	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.8	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:04:8	35.45	2526	1.8	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.83	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2528	1.8	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.83	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2532	1.8	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.84	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2534	1.8	13.49	94	196	Off Idle	65	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.81	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2539	1.8	13.49	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.8	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2538	1.8	13.49	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.8	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2531	1.8	13.48	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.8	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2542	1.8	13.48	94	196	Off Idle	65	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.81	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2531	1.8	13.45	94	196	Off Idle	65	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.85	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:7	35.45	2515	1.8	13.46	94	196	Off Idle	65	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.83	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:7	35.45	2519	1.8	13.46	94	196	Off Idle	65	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.83	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:7	35.45	2516	1.8	13.46	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.82	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:7	35.45	2509	1.8	13.46	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.79	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:7	35.45	2528	1.8	13.46	94	196	Off Idle	65	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.8	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:7	35.45	2537	1.79	13.46	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.86	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2539	1.79	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.83	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2546	1.79	13.46	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.84	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2538	1.79	13.48	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.83	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2542	1.79	13.48	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.85	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2536	1.79	13.46	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.81	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:8	35.45	2530	1.79	13.47	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.81	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:9	35.45	2519	1.8	13.48	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.83	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:9	35.45	2519	1.8	13.48	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.83	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:9	35.45	2520	1.8	13.46	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.79	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:9	35.45	2519	1.8	13.46	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.76	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:9	35.45	2524	1.8	13.46	94	196	Off Idle	63.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.78	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:9	35.45	2525	1.8	13.47	94	196	Off Idle	63.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.74	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:04:9	35.45	2526	1.8	13.47	94	196	Off Idle	63.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.76	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:0	35.45	2527	1.8	13.48	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.76	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:0	35.45	2528	1.8	13.47	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.79	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:0	35.45	2531	1.8	13.46	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.79	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:0	35.45	2530	1.8	13.47	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.82	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:0	35.45	2524	1.8	13.46	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.83	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:0	35.45	2524	1.8	13.46	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.83	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:1	35.45	2517	1.8	13.47	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.81	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:1	35.45	2517	1.8	13.47	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.81	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:1	35.45	2516	1.8	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.78	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:1	35.45	2524	1.8	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.77	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:1	35.45	2521	1.8	13.46	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.78	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:1	35.45	2522	1.8	13.46	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.75	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:1	35.45	2507	1.8	13.46	94	196	Off Idle	65	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.73	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:2	35.45	2534	1.8	13.48	94	196	Off Idle	65	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.77	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:2	35.45	2541	1.8	13.47	94	196	Off Idle	65	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.77	15.02	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:2	35.45	2539	1.8	13.47	94	196	Off Idle	65	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.76	15.03	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:2	35.45	2544	1.8	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.77	15.03	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:2	35.45	2529	1.8	13.46	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.76	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:2	35.45	2529	1.8	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.74	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:3	35.45	2520	1.8	13.46	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.71	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:3	35.45	2512	1.81	13.47	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.71	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:3	35.45	2513	1.81	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.7	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:3	35.45	2514	1.81	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.72	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:3	35.45	2518	1.81	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.69	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:3	35.45	2528	1.81	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.7	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:4	35.45	2531	1.81	13.48	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.67	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:4	35.45	2536	1.81	13.48	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.7	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:4	35.45	2540	1.81	13.5	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.68	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:4	35.45	2540	1.81	13.49	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.72	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:4	35.45	2542	1.81	13.48	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.74	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:05:4	35.45	2541	1.81	13.48	94	196	Off Idle	64.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.74	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:4	35.45	2531	1.81	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.16	Rich	1	14.6	-8.76	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:5	35.45	2531	1.81	13.46	94	196	Off Idle	64.8	0	2	132	944 Turbo	0.2	Rich	1	14.6	-8.79	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:05:5	35.45	2526	1.81	13.47	94	196	Off Idle	65	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.77	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:5	35.45	2522	1.81	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.83	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:5	35.45	2514	1.8	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.85	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:5	35.45	2514	1.8	13.46	94	196	Off Idle	65	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.89	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:5	35.45	2501	1.79	13.48	94	196	Off Idle	64.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.93	15.05	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:6	35.45	2510	1.78	13.46	94	196	Off Idle	64.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.01	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:05:6	35.45	2511	1.78	13.47	94	196	Off Idle	64.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.05	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:05:6	35.45	2516	1.77	13.46	94	196	Off Idle	64.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.12	15.12	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:05:6	35.45	2518	1.76	13.47	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.17	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:05:6	35.45	2518	1.75	13.48	94	196	Off Idle	64.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.22	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:05:6	35.45	2515	1.75	13.47	94	196	Off Idle	65	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.25	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:05:6	35.45	2512	1.74	13.46	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.25	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:05:7	35.45	2512	1.74	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.27	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:05:7	35.45	2518	1.73	13.48	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.32	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:05:7	35.45	2519	1.72	13.46	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.32	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:05:7	35.45	2520	1.71	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.36	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:05:7	35.45	2521	1.7	13.48	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.44	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:05:7	35.45	2522	1.68	13.48	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.56	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:05:8	35.45	2519	1.64	13.49	94	196	Off Idle	65.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.65	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:05:8	35.45	2519	1.63	13.49	94	196	Full Load	65.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.78	14.95	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:05:8	35.45	2513	1.6	13.48	94	196	Idle	65.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.94	14.91	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:05:8	35.45	2513	1.58	13.48	94	196	Idle	65.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.98	14.89	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:05:8	35.45	2503	1.56	13.48	94	196	Idle	63.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.14	14.87	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:05:8	35.45	2480	1.53	13.47	94	196	Idle	62.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.26	14.87	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:05:9	35.45	2475	1.52	13.47	94	196	Idle	61.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.27	14.87	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:05:9	35.45	2471	1.5	13.48	94	196	Idle	60.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.29	14.87	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:05:9	32.72	2414	1.49	13.46	94	196	Idle	59.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.28	14.87	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:05:9	27.27	2408	1.48	13.45	94	196	Idle	58.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-10.26	14.87	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:05:9	27.27	2408	1.47	13.47	94	196	Idle	57.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-10.21	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:05:9	21.81	2419	1.47	13.46	94	196	Idle	57.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.17	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:05:9	19.09	2470	1.46	13.46	94	196	Idle	56.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.13	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:0	19.09	2470	1.45	13.48	94	196	Idle	56.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.12	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:0	19.09	2534	1.44	13.48	94	196	Idle	56.1	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.13	14.91	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:0	19.09	2544	1.43	13.47	94	196	Idle	56.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.14	14.93	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:0	19.09	2585	1.42	13.48	94	196	Idle	56	0	2	132	944 Turbo	0.35	Rich	1	14.6	-10.17	14.96	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:0	19.09	2564	1.41	13.48	94	196	Idle	55.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-10.19	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:0	19.09	2532	1.41	13.48	94	196	Idle	56.8	0	2	132	944 Turbo	0.23	Rich	1	14.6	-10.21	15.01	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:1	19.09	2518	1.41	13.49	94	196	Idle	57.9	0	2	132	944 Turbo	0.13	Rich	1	14.6	-10.27	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:1	19.09	2477	1.41	13.48	94	196	Idle	59.1	0	2	132	944 Turbo	0.08	Rich	1	14.6	-10.29	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:1	19.09	2477	1.42	13.47	94	196	Idle	60.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.29	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:1	19.09	2479	1.42	13.47	94	196	Idle	61.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.3	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:1	19.09	2473	1.42	13.47	94	196	Idle	62	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.3	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:1	19.09	2471	1.42	13.47	94	196	Idle	62.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.3	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:1	19.09	2462	1.42	13.48	94	196	Idle	63.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.29	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:2	19.09	2477	1.42	13.47	94	196	Idle	63.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.3	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:2	19.09	2480	1.41	13.47	94	196	Idle	64.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.31	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:2	19.09	2493	1.41	13.48	94	196	Idle	64.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.34	15.03	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:2	19.09	2506	1.39	13.48	94	196	Idle	64.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	14.99	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:2	19.09	2514	1.38	13.48	94	196	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	14.96	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:2	19.09	2514	1.37	13.48	94	196	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	14.95	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:3	19.09	2510	1.37	13.48	94	196	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	14.96	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:3	19.09	2506	1.36	13.48	94	196	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	14.97	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:3	19.09	2492	1.35	13.49	94	196	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	15.02	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:3	19.09	2498	1.35	13.49	94	196	Idle	64.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:3	19.09	2472	1.34	13.49	94	196	Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	15.24	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:06:3	19.09	2463	1.34	13.48	94	196	Idle	64.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	15.44	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:4	19.09	2462	1.33	13.48	94	196	Idle	65	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	15.71	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:4	19.09	2459	1.33	13.47	94	196	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	16.1	1.1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:4	19.09	2464	1.33	13.47	94	196	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	16.83	1.15	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:4	19.09	2464	1.32	13.48	94	196	Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	17.32	1.18	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:4	19.09	2472	1.32	13.47	94	196	Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	17.81	1.21	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:4	19.09	2483	1.31	13.47	94	196	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	18.28	1.25	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:4	19.09	2483	1.31	13.47	94	196	Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	18.94	1.29	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:5	19.09	2490	1.31	13.48	94	196	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	19.34	1.32	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:5	19.09	2490	1.31	13.48	94	196	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	19.68	1.34	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:5	19.09	2489	1.31	13.48	94	196	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	19.95	1.36	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:5	19.09	2487	1.31	13.48	94	196	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.12	1.37	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:5	19.09	2480	1.31	13.47	94	196	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.19	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:5	19.09	2474	1.31	13.47	94	196	Full Load	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:6	19.09	2472	1.31	13.47	94	196	Full Load	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:6	19.09	2468	1.31	13.46	94	196	Off Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:6	9.54	2341	1.31	13.47	94	196	Off Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:06:6	9.54	2504	1.32	13.47	94	196	Off Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:06:6	12.27	2495	1.33	13.48	94	196	Off Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:06:6	12.27	2492	1.34	13.49	94	196	Off Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:06:6	14.99	2499	1.35	13.49	94	196	Off Idle	66.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:06:7	17.72	2502	1.36	13.49	94	196	Off Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:06:7	20.45	2509	1.38	13.48	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:7	20.45	2512	1.4	13.48	94	196	Off Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:7	23.18	2512	1.43	13.47	94	196	Off Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:06:7	23.18	2517	1.44	13.47	94	196	Off Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:06:7	25.9	2513	1.48	13.47	94	196	Off Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:06:8	28.63	2519	1.5	13.49	94	196	Off Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	20.24	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:06:8	28.63	2519	1.53	13.48	94	196	Off Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.3	20.23	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:06:8	31.36	2522	1.58	13.49	94	196	Off Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.19	20.23	1.38	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:06:8	34.08	2525	1.6	13.47	94	196	Off Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.06	20.23	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:06:8	35.45	2525	1.64	13.47	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.85	20.24	1.38	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:06:8	35.45	2511	1.67	13.47	94	196	Off Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.7	20.23	1.38	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:06:9	35.45	2524	1.71	13.48	94	196	Off Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.55	20.23	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:06:9	35.45	2547	1.74	13.46	94	196	Off Idle	66.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.44	20.23	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:06:9	35.45	2538	1.77	13.46	94	196	Off Idle	66	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.28	20.24	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:06:9	35.45	2524	1.81	13.47	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.14	20.24	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:06:9	35.45	2488	1.84	13.48	94	196	Off Idle	65.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8	20.24	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:06:9	35.45	2488	1.88	13.48	94	196	Off Idle	65.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.86	20.24	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:06:9	35.45	2448	1.91	13.47	94	196	Off Idle	65.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.62	20.24	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:07:0	35.45	2458	1.94	13.48	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.44	20.24	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:07:0	35.45	2455	1.97	13.46	94	196	Off Idle	65.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.27	20.24	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:07:0	35.45	2458	1.99	13.47	94	196	Off Idle	65.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.13	20.24	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:07:0	35.45	2463	2.01	13.46	94	196	Off Idle	65.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.98	20.24	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:07:0	34.08	2485	2.04	13.45	94	196	Off Idle	66.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.81	20.23	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:07:0	34.08	2490	2.07	13.47	94	196	Off Idle	66.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.65	20.17	1.37	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:07:1	34.08	2504	2.09	13.47	94	196	Off Idle	66.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.43	19.9	1.36	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:07:1	34.08	2510	2.11	13.48	94	196	Off Idle	66.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.33	19.64	1.34	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:07:1	34.08	2510	2.14	13.48	94	196	Off Idle	66.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.12	19.35	1.32	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:07:1	34.08	2509	2.16	13.46	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.92	19.04	1.3	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:07:1	34.08	2496	2.19	13.46	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.74	18.7	1.27	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:07:1	34.08	2496	2.23	13.46	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.41	18.17	1.24	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:23:07:1	34.08	2487	2.25	13.45	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.23	17.99	1.23	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:23:07:2	34.08	2482	2.27	13.45	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.02	17.42	1.19	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:23:07:2	34.08	2482	2.29	13.46	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.83	17.07	1.16	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:23:07:2	34.08	2487	2.31	13.48	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.67	16.8	1.14	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:23:07:2	32.72	2488	2.33	13.46	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.55	16.61	1.13	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:23:07:2	32.72	2501	2.35	13.48	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.37	16.45	1.12	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:07:2	32.72	2500	2.37	13.46	94	196	Off Idle	66.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.22	16.32	1.11	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:23:07:3	32.72	2496	2.39	13.45	94	196	Off Idle	66.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.07	16.22	1.1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:23:07:3	32.72	2494	2.43	13.46	94	196	Off Idle	66.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-3.92	16.12	1.1	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:3	32.72	2494	2.45	13.45	94	196	Off Idle	66.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.69	16.08	1.1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:23:07:3	32.72	2496	2.47	13.45	94	196	Off Idle	66.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.43	15.91	1.08	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:23:07:3	32.72	2498	2.48	13.45	94	196	Off Idle	66.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-3.28	15.8	1.08	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:23:07:3	32.72	2505	2.5	13.47	94	196	Off Idle	66.6	0	2	132	944 Turbo	0.47	Rich	1	14.7	-3.14	15.72	1.07	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:23:07:4	32.72	2505	2.52	13.46	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.08	15.64	1.07	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:23:07:4	32.72	2510	2.53	13.46	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.98	15.59	1.06	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:23:07:4	32.72	2537	2.55	13.45	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.94	15.51	1.06	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:23:07:4	32.72	2525	2.56	13.45	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.86	15.42	1.05	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:23:07:4	32.72	2512	2.57	13.44	94	196	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-2.79	15.32	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:23:07:4	32.72	2509	2.59	13.44	94	196	Off Idle	66.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.64	15.21	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:23:07:4	32.72	2508	2.6	13.45	94	196	Off Idle	66.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.5	15.08	1.03	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:23:07:5	32.72	2510	2.61	13.45	94	196	Off Idle	66.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.47	15.07	1.03	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:23:07:5	32.72	2511	2.62	13.47	94	196	Off Idle	66.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.34	15.01	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:23:07:5	32.72	2511	2.63	13.46	94	196	Off Idle	66.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.31	14.96	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:5	32.72	2512	2.64	13.46	94	196	Off Idle	66.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-2.22	14.9	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:5	32.72	2518	2.66	13.46	94	196	Off Idle	66.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.09	14.76	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:5	32.72	2519	2.67	13.48	94	196	Off Idle	66	0	2	132	944 Turbo	0.79	Rich	1	14.6	-1.98	14.7	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:6	32.72	2519	2.67	13.46	94	196	Off Idle	65.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.88	14.64	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:23:07:6	32.72	2523	2.68	13.45	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.73	14.6	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:23:07:6	32.72	2489	2.69	13.45	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.59	14.55	0.99	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:23:07:6	31.36	2489	2.7	13.46	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.53	14.49	0.99	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:23:07:6	31.36	2528	2.71	13.47	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.44	14.42	0.98	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:23:07:6	31.36	2527	2.72	13.45	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.27	14.37	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:6	31.36	2527	2.72	13.45	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.27	14.34	0.98	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:7	31.36	2527	2.74	13.47	94	196	Off Idle	65.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-1.12	14.26	0.97	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:7	31.36	2528	2.74	13.47	94	196	Off Idle	65	0	2	132	944 Turbo	0.81	Rich	1	14.6	-1.1	14.25	0.97	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:7	31.36	2528	2.75	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.97	14.2	0.97	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:7	31.36	2532	2.76	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.95	14.13	0.96	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:7	31.36	2531	2.77	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.85	14.09	0.96	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:7	31.36	2568	2.78	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-0.83	14.05	0.96	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:8	31.36	2568	2.79	13.48	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.81	13.99	0.95	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:8	31.36	2528	2.79	13.46	94	196	Off Idle	64.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.73	13.95	0.95	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:8	31.36	2532	2.79	13.48	94	196	Off Idle	64.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-0.7	13.93	0.95	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:8	31.36	2539	2.8	13.46	94	196	Off Idle	64.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.67	13.87	0.95	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:8	31.36	2539	2.8	13.47	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.7	13.85	0.94	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:8	31.36	2540	2.81	13.45	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.62	13.82	0.94	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:07:9	31.36	2544	2.81	13.45	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.63	13.79	0.94	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:9	31.36	2545	2.82	13.45	94	196	Off Idle	64.3	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.58	13.77	0.94	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:9	31.36	2548	2.82	13.46	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.6	13.78	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:9	31.36	2549	2.82	13.47	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.56	13.78	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:9	31.36	2549	2.82	13.46	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.45	13.75	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:9	31.36	2549	2.83	13.47	94	196	Off Idle	64.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.48	13.75	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:23:07:9	31.36	2552	2.83	13.47	94	196	Off Idle	64.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.49	13.74	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:23:08:0	31.36	2558	2.83	13.46	94	196	Off Idle	63.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.45	13.74	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:0	31.36	2559	2.83	13.46	94	196	Off Idle	63.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.37	13.74	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:0	31.36	2561	2.84	13.46	94	196	Off Idle	63.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.39	13.73	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:0	31.36	2561	2.84	13.45	94	196	Off Idle	63.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.31	13.76	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:0	29.99	2542	2.84	13.47	94	196	Off Idle	63.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.28	13.76	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:0	29.99	2565	2.85	13.45	94	196	Off Idle	63.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.28	13.74	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:1	29.99	2562	2.85	13.45	94	196	Off Idle	63.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-0.19	13.74	0.94	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:1	29.99	2562	2.85	13.46	94	196	Off Idle	63.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-0.17	13.77	0.94	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:1	31.36	2570	2.86	13.47	94	196	Off Idle	63.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.12	13.77	0.94	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:1	31.36	2580	2.86	13.46	94	196	Off Idle	63	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.09	13.76	0.94	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:1	31.36	2571	2.86	13.46	94	196	Off Idle	62.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.08	13.76	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:1	31.36	2571	2.87	13.46	94	196	Off Idle	62.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.08	13.74	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:08:1	31.36	2576	2.87	13.45	94	196	Off Idle	62.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.01	13.72	0.93	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:2	31.36	2577	2.87	13.46	94	196	Off Idle	62.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.02	13.72	0.93	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:2	31.36	2586	2.88	13.47	94	196	Off Idle	62.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	0.05	13.74	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:2	31.36	2574	2.88	13.46	94	196	Off Idle	62.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	0.1	13.75	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:2	31.36	2572	2.88	13.46	94	196	Off Idle	62.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	0.08	13.75	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:2	31.36	2566	2.88	13.46	94	196	Off Idle	62	0	2	132	944 Turbo	0.82	Rich	1	14.7	0.12	13.74	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:2	31.36	2556	2.89	13.45	94	196	Off Idle	62	0	2	132	944 Turbo	0.81	Rich	1	14.7	0.18	13.75	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:3	29.99	2569	2.89	13.44	94	196	Off Idle	62	0	2	132	944 Turbo	0.81	Rich	1	14.7	0.22	13.77	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:3	29.99	2580	2.89	13.45	94	196	Off Idle	62	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.2	13.76	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:3	29.99	2586	2.89	13.45	94	196	Off Idle	61.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.3	13.77	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:3	29.99	2586	2.9	13.46	94	196	Off Idle	61.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	0.26	13.78	0.94	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:3	29.99	2585	2.9	13.46	94	196	Off Idle	61.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.31	13.78	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:3	29.99	2587	2.9	13.47	94	196	Off Idle	61.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.32	13.79	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:4	29.99	2587	2.9	13.47	94	196	Off Idle	61.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.36	13.79	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:4	29.99	2584	2.91	13.46	94	196	Off Idle	61.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.34	13.81	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:4	29.99	2586	2.91	13.46	94	196	Off Idle	61.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.37	13.85	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:4	29.99	2589	2.91	13.47	94	196	Off Idle	61.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.38	13.87	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:4	29.99	2594	2.92	13.47	94	196	Off Idle	61.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.41	13.89	0.95	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:4	29.99	2600	2.92	13.45	94	196	Off Idle	61.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.45	13.98	0.95	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:4	29.99	2604	2.92	13.44	94	196	Off Idle	61.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	0.53	14.02	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:5	29.99	2614	2.92	13.45	94	196	Off Idle	61.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	0.51	14.04	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:5	29.99	2602	2.92	13.44	94	196	Off Idle	61.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.55	14.06	0.96	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:5	29.99	2592	2.93	13.44	94	196	Off Idle	60.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	0.58	14.08	0.96	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:5	29.99	2592	2.93	13.45	94	196	Off Idle	60.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.64	14.1	0.96	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:5	29.99	2604	2.93	13.47	94	196	Off Idle	60.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	0.63	14.13	0.96	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:5	29.99	2618	2.94	13.47	94	196	Off Idle	60.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.66	14.17	0.97	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:6	29.99	2622	2.94	13.47	94	196	Off Idle	60.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.63	14.2	0.97	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:6	29.99	2622	2.94	13.46	94	196	Off Idle	60.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	0.66	14.22	0.97	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:6	29.99	2621	2.94	13.45	94	196	Off Idle	60.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.65	14.24	0.97	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:6	29.99	2616	2.95	13.46	94	196	Off Idle	60.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	0.72	14.25	0.97	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:6	29.99	2609	2.95	13.46	94	196	Off Idle	60	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.75	14.28	0.97	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:6	29.99	2607	2.95	13.46	94	196	Off Idle	59.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.78	14.32	0.98	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:6	29.99	2597	2.95	13.46	94	196	Off Idle	59.7	0	2	132	944 Turbo	0.79	Rich	1	14.7	0.84	14.34	0.98	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:7	28.63	2557	2.96	13.47	94	196	Off Idle	59.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.86	14.36	0.98	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:7	28.63	2580	2.96	13.47	94	196	Off Idle	59.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	0.77	14.35	0.98	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:7	28.63	2616	2.96	13.47	94	196	Off Idle	60.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	0.76	14.34	0.98	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:7	28.63	2634	2.96	13.48	94	196	Off Idle	60.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	0.8	14.33	0.98	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:7	28.63	2622	2.96	13.46	94	196	Off Idle	60	0	2	132	944 Turbo	0.79	Rich	1	14.7	0.8	14.33	0.98	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:7	29.99	2622	2.97	13.46	94	196	Off Idle	59.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	0.8	14.34	0.98	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:8	29.99	2632	2.97	13.47	94	196	Off Idle	59.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.85	14.35	0.98	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:8	29.99	2634	2.97	13.45	94	196	Off Idle	59.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.87	14.32	0.98	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:8	29.99	2635	2.97	13.46	94	196	Off Idle	59.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	0.94	14.34	0.98	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:8	29.99	2647	2.97	13.44	94	196	Off Idle	59.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	0.98	14.36	0.98	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:08:8	29.99	2630	2.97	13.45	94	196	Off Idle	59.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.03	14.38	0.98	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:8	29.99	2629	2.97	13.46	94	196	Off Idle	59.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.05	14.39	0.98	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:9	29.99	2626	2.97	13.45	94	196	Off Idle	59.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	1	14.41	0.98	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:9	29.99	2626	2.98	13.46	94	196	Off Idle	59.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	1.06	14.44	0.98	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:9	29.99	2627	2.98	13.46	94	196	Off Idle	59	0	2	132	944 Turbo	0.77	Rich	1	14.6	1.1	14.45	0.98	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:9	29.99	2628	2.98	13.45	94	196	Off Idle	58.9	0	2	132	944 Turbo	0.77	Rich	1	14.7	1.05	14.45	0.98	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:9	29.99	2634	2.98	13.45	94	196	Off Idle	58.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	1.13	14.5	0.99	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:9	29.99	2628	2.98	13.44	94	196	Off Idle	58.7	0	2	132	944 Turbo	0.76	Rich	1	14.7	1.12	14.51	0.99	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:08:9	28.63	2632	2.98	13.43	94	196	Off Idle	58.7	0	2	132	944 Turbo	0.76	Rich	1	14.7	1.15	14.53	0.99	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:0	28.63	2660	2.98	13.43	94	196	Off Idle	58.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	1.19	14.56	0.99	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:0	28.63	2649	2.99	13.44	94	196	Off Idle	58.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	1.2	14.59	0.99	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:0	28.63	2641	2.99	13.45	94	196	Off Idle	58.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	1.15	14.63	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:0	28.63	2656	2.99	13.44	94	196	Off Idle	58.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	1.21	14.64	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:0	28.63	2625	2.99	13.44	94	196	Off Idle	58.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	1.22	14.7	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:0	28.63	2628	2.99	13.44	94	196	Off Idle	58.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	1.16	14.73	1	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:09:1	28.63	2628	2.99	13.46	94	196	Off Idle	58.4	0	2	132	944 Turbo	0.68	Lean	1	14.6	1.22	14.76	1.01	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:1	28.63	2651	3	13.45	94	196	Off Idle	58.4	0	2	132	944 Turbo	0.64	Lean	1	14.6	1.27	14.78	1.01	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:1	28.63	2631	3	13.44	94	196	Off Idle	58.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	1.27	14.81	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:09:1	28.63	2631	3	13.46	94	196	Off Idle	58.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	1.24	14.83	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:09:1	28.63	2680	3	13.46	94	196	Off Idle	58.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	1.25	14.84	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:09:1	28.63	2674	3	13.45	94	196	Off Idle	58.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	1.3	14.85	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:09:1	28.63	2708	3	13.47	94	196	Off Idle	58	0	2	132	944 Turbo	0.44	Lean	1	14.6	1.27	14.87	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:2	28.63	2708	3	13.45	94	196	Off Idle	58	0	2	132	944 Turbo	0.44	Lean	1	14.7	1.33	14.88	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:2	28.63	2652	3.01	13.44	94	196	Off Idle	57.8	0	2	132	944 Turbo	0.45	Lean	1	14.7	1.31	14.94	1.02	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:2	28.63	2652	3.01	13.45	94	196	Off Idle	57.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	1.32	14.99	1.02	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:2	28.63	2652	3.01	13.45	94	196	Off Idle	57.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	1.31	15.02	1.02	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:2	28.63	2668	3.01	13.44	94	196	Off Idle	57.8	0	2	132	944 Turbo	0.57	Rich	1	14.7	1.28	15.02	1.02	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:2	28.63	2672	3.01	13.45	94	196	Off Idle	57.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	1.36	15.01	1.02	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:3	28.63	2685	3.01	13.45	94	196	Off Idle	57.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	1.3	15.02	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:3	28.63	2682	3.01	13.45	94	196	Off Idle	57.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.31	15.02	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:3	28.63	2668	3.01	13.45	94	196	Off Idle	56.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.31	14.99	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:3	28.63	2672	3.01	13.44	94	196	Off Idle	56.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	1.37	14.98	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:23:09:3	28.63	2667	3.01	13.45	94	196	Off Idle	56.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.36	14.95	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:23:09:3	28.63	2668	3.02	13.45	94	196	Off Idle	56.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	1.38	14.88	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:4	28.63	2672	3.02	13.44	94	196	Off Idle	56.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	1.43	14.83	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:4	28.63	2680	3.02	13.45	94	196	Off Idle	56.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	1.47	14.84	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:4	28.63	2683	3.02	13.45	94	196	Off Idle	56.3	0	2	132	944 Turbo	0.63	Rich	1	14.7	1.45	14.86	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:4	28.63	2685	3.02	13.44	94	196	Off Idle	56.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	1.5	14.86	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:09:4	28.63	2696	3.02	13.45	94	196	Off Idle	56.3	0	2	132	944 Turbo	0.52	Rich	1	14.7	1.5	14.86	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:09:4	28.63	2696	3.02	13.45	94	196	Off Idle	56.3	0	2	132	944 Turbo	0.52	Rich	1	14.7	1.5	14.85	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:09:4	28.63	2688	3.02	13.47	94	196	Off Idle	56	0	2	132	944 Turbo	0.44	Rich	1	14.6	1.48	14.84	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:09:5	28.63	2694	3.02	13.46	94	196	Off Idle	55.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	1.49	14.83	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:09:5	28.63	2694	3.03	13.46	94	196	Off Idle	55.7	0	2	132	944 Turbo	0.33	Rich	1	14.7	1.46	14.85	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:09:5	28.63	2694	3.03	13.45	94	196	Off Idle	55.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	1.5	14.88	1.01	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:09:5	28.63	2706	3.03	13.46	94	196	Off Idle	55.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	1.54	14.92	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:09:5	28.63	2696	3.03	13.45	94	196	Off Idle	55.5	0	2	132	944 Turbo	0.31	Rich	1	14.7	1.53	14.93	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:5	28.63	2692	3.03	13.44	94	196	Off Idle	55.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	1.56	15	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:6	28.63	2693	3.04	13.45	94	196	Off Idle	55.5	0	2	132	944 Turbo	0.4	Rich	1	14.7	1.52	15.05	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:6	28.63	2700	3.04	13.45	94	196	Off Idle	55.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	1.52	15.09	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:6	28.63	2702	3.04	13.43	94	196	Off Idle	55.2	0	2	132	944 Turbo	0.49	Rich	1	14.7	1.56	15.12	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:6	28.63	2702	3.04	13.45	94	196	Off Idle	55.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	1.52	15.13	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:6	28.63	2706	3.04	13.45	94	196	Off Idle	55.2	0	2	132	944 Turbo	0.62	Rich	1	14.7	1.57	15.1	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:6	28.63	2697	3.04	13.45	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	1.62	15.05	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:6	28.63	2710	3.04	13.45	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.66	15.03	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:7	28.63	2708	3.04	13.48	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	1.67	14.98	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:7	28.63	2704	3.05	13.46	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.69	Rich	1	14.7	1.74	14.96	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:7	28.63	2701	3.05	13.48	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	1.69	14.86	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:7	28.63	2701	3.05	13.46	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	1.69	14.83	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:7	28.63	2714	3.05	13.46	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	1.69	14.82	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:09:7	28.63	2716	3.05	13.46	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	1.68	14.78	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:09:8	28.63	2716	3.05	13.46	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	1.69	14.79	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:09:8	28.63	2728	3.05	13.44	94	196	Off Idle	54.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	1.79	14.79	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:09:8	28.63	2730	3.06	13.46	94	196	Off Idle	54.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	1.79	14.81	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:09:8	28.63	2730	3.06	13.46	94	196	Off Idle	54.5	0	2	132	944 Turbo	0.36	Rich	1	14.7	1.77	14.82	1.01	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:09:8	28.63	2728	3.06	13.45	94	196	Off Idle	54.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	1.76	14.88	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:09:8	28.63	2718	3.06	13.46	94	196	Off Idle	54.1	0	2	132	944 Turbo	0.41	Rich	1	14.7	1.72	14.9	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:09:9	28.63	2759	3.06	13.46	94	197	Off Idle	53.9	0	2	132	944 Turbo	0.44	Rich	1	14.7	1.77	14.95	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:09:9	28.63	2736	3.06	13.44	94	197	Off Idle	53.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	1.75	14.97	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:09:9	28.63	2721	3.06	13.45	94	197	Off Idle	53.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	1.75	14.98	1.02	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:09:9	28.63	2730	3.07	13.45	94	196	Off Idle	53.9	0	2	132	944 Turbo	0.58	Rich	1	14.7	1.77	14.99	1.02	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:09:9	28.63	2734	3.07	13.45	94	196	Off Idle	53.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	1.82	15	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:09:9	28.63	2716	3.07	13.45	94	196	Off Idle	53.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	1.81	15	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:09:9	28.63	2739	3.07	13.46	94	196	Off Idle	53.9	0	2	132	944 Turbo	0.69	Rich	1	14.7	1.84	14.99	1.02	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:10:0	28.63	2740	3.07	13.46	94	196	Off Idle	53.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	1.82	14.97	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:0	28.63	2746	3.08	13.45	94	196	Off Idle	53.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	1.85	14.93	1.02	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:0	28.63	2813	3.08	13.45	94	196	Off Idle	53.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	1.8	14.89	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:0	29.99	2813	3.08	13.45	94	196	Off Idle	53.3	0	2	132	944 Turbo	0.67	Rich	1	14.7	1.81	14.89	1.01	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:10:0	29.99	2739	3.08	13.44	94	196	Off Idle	53.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	1.86	14.87	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:10:0	29.99	2730	3.08	13.43	94	196	Off Idle	53.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	1.85	14.87	1.01	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:10:1	29.99	2715	3.08	13.44	94	196	Off Idle	53.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	1.96	14.87	1.01	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:10:1	28.63	2715	3.08	13.44	94	196	Off Idle	53.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	1.91	14.87	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:10:1	28.63	2747	3.09	13.44	94	196	Off Idle	53.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	1.94	14.85	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:10:1	28.63	2751	3.09	13.43	94	196	Off Idle	53.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	1.92	14.87	1.01	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:1	28.63	2753	3.09	13.44	94	196	Off Idle	53	0	2	132	944 Turbo	0.33	Rich	1	14.6	1.95	14.9	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:1	28.63	2762	3.09	13.44	94	196	Off Idle	53	0	2	132	944 Turbo	0.31	Rich	1	14.6	1.98	14.91	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:1	28.63	2763	3.09	13.43	94	196	Off Idle	52.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	1.95	14.92	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:2	28.63	2761	3.09	13.43	94	196	Off Idle	52.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	1.9	14.95	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:2	28.63	2761	3.1	13.44	94	196	Off Idle	52.2	0	2	132	944 Turbo	0.26	Lean	1	14.7	1.98	14.96	1.02	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:2	28.63	2771	3.1	13.44	94	196	Off Idle	52.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	1.96	14.97	1.02	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:10:2	28.63	2746	3.1	13.45	94	196	Off Idle	51.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	2	15.04	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:10:2	28.63	2744	3.1	13.45	94	196	Off Idle	51.9	0	2	132	944 Turbo	0.45	Lean	1	14.7	2	15.07	1.03	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:10:2	28.63	2751	3.1	13.46	94	196	Off Idle	51.9	0	2	132	944 Turbo	0.52	Lean	1	14.7	2.02	15.09	1.03	3.6	6.4	ON	28 Pin	OFF	Removed	Disabled
03:23:10:3	28.63	2756	3.1	13.44	94	196	Off Idle	51.9	0	2	132	944 Turbo	0.58	Lean	1	14.6	2.07	15.08	1.03	3.6	6.4	ON	28 Pin	OFF	Removed	Disabled
03:23:10:3	28.63	2778	3.1	13.44	94	196	Off Idle	51.8	0	2	132	944 Turbo	0.63	Lean	1	14.7	2.08	15.04	1.02	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:23:10:3	28.63	2782	3.1	13.44	94	196	Off Idle	51.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	2.06	15.03	1.02	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:23:10:3	28.63	2782	3.1	13.43	94	196	Off Idle	51.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	2.03	14.96	1.02	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:3	28.63	2771	3.1	13.43	94	196	Off Idle	51.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	1.96	14.9	1.02	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:3	28.63	2771	3.1	13.44	94	196	Off Idle	51.1	0	2	132	944 Turbo	0.77	Rich	1	14.7	1.92	14.87	1.01	3.6	6.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:4	28.63	2767	3.1	13.44	94	196	Off Idle	50.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	1.84	14.83	1.01	3.6	6.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:4	28.63	2769	3.1	13.43	94	196	Off Idle	50.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	1.84	14.72	1	3.6	6.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:4	28.63	2769	3.1	13.44	94	196	Off Idle	50.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	1.76	14.58	0.99	3.6	6.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:4	28.63	2776	3.1	13.45	94	196	Off Idle	50.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.74	14.39	0.98	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:23:10:4	28.63	2784	3.09	13.43	94	196	Off Idle	50.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.77	14.26	0.97	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:23:10:4	28.63	2786	3.09	13.44	94	196	Off Idle	50.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	1.71	14.11	0.96	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:23:10:4	28.63	2790	3.09	13.45	94	196	Off Idle	50.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.69	13.9	0.95	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:23:10:5	28.63	2792	3.09	13.46	94	196	Off Idle	50.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	1.61	13.74	0.94	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:5	28.63	2793	3.09	13.46	94	196	Off Idle	50.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	1.59	13.59	0.93	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:5	28.63	2791	3.08	13.46	94	196	Off Idle	50.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	1.58	13.44	0.92	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:23:10:5	29.99	2793	3.08	13.45	94	196	Off Idle	50.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	1.52	13.38	0.91	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:23:10:5	29.99	2792	3.08	13.47	94	196	Off Idle	50.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	1.49	13.24	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:5	29.99	2792	3.08	13.45	94	196	Off Idle	50.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.48	13.18	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:6	29.99	2793	3.08	13.45	94	196	Off Idle	50.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.42	13.14	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:6	29.99	2816	3.07	13.45	94	196	Off Idle	50.2	0	2	132	944 Turbo	0.84	Rich	1	14.7	1.33	13.12	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:6	29.99	2808	3.07	13.44	94	196	Off Idle	50.2	0	2	132	944 Turbo	0.84	Rich	1	14.7	1.35	13.11	0.89	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:23:10:6	29.99	2802	3.07	13.44	94	196	Off Idle	50.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	1.24	13.12	0.89	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:6	29.99	2782	3.06	13.44	94	196	Off Idle	50.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	1.21	13.15	0.9	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:6	29.99	2802	3.06	13.44	94	196	Off Idle	49.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.15	13.14	0.9	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:23:10:6	29.99	2801	3.06	13.44	94	196	Off Idle	49.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.15	13.14	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:23:10:7	29.99	2794	3.05	13.44	94	196	Off Idle	49.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.1	13.13	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:23:10:7	29.99	2810	3.05	13.45	94	196	Off Idle	49.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.05	13.12	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:23:10:7	29.99	2808	3.05	13.45	94	196	Off Idle	49.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	1.02	13.09	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:23:10:7	29.99	2810	3.05	13.45	94	196	Off Idle	49.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	1.02	13.07	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:23:10:7	29.99	2818	3.04	13.46	94	196	Off Idle	49.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.94	13.06	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:23:10:7	29.99	2800	3.04	13.45	94	196	Off Idle	49.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.92	13.06	0.89	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:23:10:8	29.99	2810	3.04	13.45	94	196	Off Idle	49.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	0.87	13.05	0.89	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:23:10:8	29.99	2818	3.04	13.45	94	196	Off Idle	49.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.86	13.04	0.89	3.4	5.7	ON	28 Pin	OFF	Removed	Disabled
03:23:10:8	29.99	2813	3.03	13.45	94	196	Off Idle	49.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.81	13.05	0.89	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:23:10:8	29.99	2813	3.03	13.45	94	196	Off Idle	49.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.77	13.06	0.89	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:23:10:8	29.99	2832	3.03	13.45	94	196	Off Idle	48.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.77	13.07	0.89	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:23:10:8	29.99	2813	3.02	13.45	94	196	Off Idle	48.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.74	13.07	0.89	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:9	29.99	2845	3.02	13.44	94	196	Off Idle	48.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.68	13.09	0.89	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:10:9	31.36	2835	3.02	13.44	94	196	Off Idle	48.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.65	13.1	0.89	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:9	31.36	2832	3.02	13.44	94	196	Off Idle	48.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.6	13.12	0.89	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:9	31.36	2833	3.02	13.44	94	196	Off Idle	48.3	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.58	13.11	0.89	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:9	31.36	2835	3.02	13.43	94	196	Off Idle	48.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.54	13.11	0.89	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:9	31.36	2824	3.01	13.44	94	196	Off Idle	48	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.52	13.12	0.89	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:10:9	29.99	2834	3.01	13.46	94	196	Off Idle	48	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.45	13.14	0.89	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:0	29.99	2838	3.01	13.44	94	196	Off Idle	47.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.45	13.15	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:0	29.99	2837	3.01	13.46	94	196	Off Idle	47.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.48	13.16	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:0	29.99	2831	3.01	13.45	94	196	Off Idle	47.9	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.5	13.18	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:0	29.99	2835	3.01	13.44	94	196	Off Idle	47.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.47	13.2	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:0	29.99	2835	3.01	13.44	94	196	Off Idle	47.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.5	13.2	0.9	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:0	29.99	2838	3.01	13.44	94	196	Off Idle	47.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.53	13.22	0.9	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:1	29.99	2843	3.01	13.45	94	196	Off Idle	47.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.46	13.23	0.9	3.4	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:1	29.99	2841	3.01	13.44	94	196	Off Idle	47.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.46	13.23	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:1	29.99	2842	3.01	13.45	94	196	Off Idle	47.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.48	13.22	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:1	29.99	2848	3.01	13.46	94	196	Off Idle	47.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.42	13.23	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:1	29.99	2849	3.01	13.45	94	196	Off Idle	47.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.43	13.23	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:1	29.99	2809	3.01	13.45	94	196	Off Idle	47.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.39	13.26	0.9	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:1	29.99	2829	3.01	13.47	94	196	Off Idle	48	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.34	13.27	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:2	29.99	2851	3.01	13.45	94	196	Off Idle	48	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.33	13.26	0.9	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:2	29.99	2851	3.01	13.46	94	196	Off Idle	48	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.29	13.25	0.9	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:2	29.99	2873	3.01	13.46	94	196	Off Idle	47.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.32	13.25	0.9	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:2	31.36	2854	3.01	13.46	94	196	Off Idle	47.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.34	13.26	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:2	31.36	2854	3	13.46	94	196	Off Idle	47.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.34	13.25	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:2	31.36	2865	3	13.44	94	196	Off Idle	47.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.33	13.25	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:3	31.36	2866	3	13.43	94	197	Off Idle	47.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.32	13.24	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:3	31.36	2878	3	13.44	94	197	Off Idle	47.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.29	13.23	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:3	31.36	2868	3	13.45	94	197	Off Idle	47.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.34	13.22	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:3	31.36	2867	3	13.46	94	196	Off Idle	47.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	0.24	13.19	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:3	31.36	2865	3	13.46	94	196	Off Idle	47.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.31	13.19	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:3	31.36	2866	3	13.46	94	196	Off Idle	47	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.32	13.2	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:4	31.36	2860	3	13.45	94	196	Off Idle	46.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	0.31	13.2	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:4	31.36	2872	3	13.46	94	196	Off Idle	46.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.27	13.19	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:4	31.36	2875	3	13.44	94	196	Off Idle	46.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.26	13.2	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:4	29.99	2862	3	13.45	94	196	Off Idle	46.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.2	13.21	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:4	29.99	2870	3	13.45	94	196	Off Idle	46.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	0.23	13.21	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:4	29.99	2864	3	13.47	94	196	Off Idle	46.1	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.19	13.22	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:4	29.99	2864	3	13.46	94	196	Off Idle	45.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	0.26	13.24	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:5	29.99	2871	3	13.45	94	196	Off Idle	45.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	0.25	13.26	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:5	29.99	2877	3	13.46	94	196	Off Idle	45.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.27	13.28	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:5	29.99	2878	3	13.45	94	196	Off Idle	45.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.25	13.29	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:5	29.99	2882	3	13.46	94	196	Off Idle	45.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.23	13.28	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:5	29.99	2880	3	13.44	94	196	Off Idle	45.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.21	13.29	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:5	31.36	2902	3	13.47	94	196	Off Idle	45.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.15	13.29	0.91	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:6	31.36	2891	3	13.45	94	196	Off Idle	45.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.18	13.26	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:6	31.36	2902	3	13.47	94	196	Off Idle	45.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.15	13.27	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:6	31.36	2908	3	13.45	94	196	Off Idle	45.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.16	13.26	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:6	29.99	2908	3	13.47	94	196	Off Idle	45.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.17	13.26	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:6	29.99	2902	3	13.45	94	196	Off Idle	45.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.16	13.25	0.9	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:6	29.99	2895	3	13.45	94	196	Off Idle	45	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.16	13.23	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:6	29.99	2892	3	13.45	94	196	Off Idle	44.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.14	13.22	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:7	29.99	2885	3.01	13.45	94	196	Off Idle	44.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.17	13.2	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:7	31.36	2887	3.01	13.45	94	196	Off Idle	44.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.16	13.21	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:7	31.36	2899	3.01	13.45	94	196	Off Idle	44.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.2	13.23	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:7	31.36	2899	3.01	13.46	94	196	Off Idle	44.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.2	13.25	0.9	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:23:11:7	31.36	2906	3.01	13.45	94	196	Off Idle	44.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.22	13.26	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:7	31.36	2904	3.01	13.45	94	196	Off Idle	44.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.25	13.27	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:8	31.36	2906	3.01	13.45	94	196	Off Idle	44	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.21	13.28	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:11:8	31.36	2906	3.01	13.44	94	196	Off Idle	43.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.23	13.3	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:8	31.36	2909	3.01	13.44	94	196	Off Idle	43.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.24	13.32	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:8	31.36	2912	3.01	13.45	94	196	Off Idle	43.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.22	13.36	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:8	31.36	2912	3.01	13.45	94	196	Off Idle	43.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.22	13.36	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:8	31.36	2918	3.01	13.45	94	196	Off Idle	43.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.23	13.35	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:9	31.36	2917	3.01	13.45	94	196	Off Idle	43.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.23	13.32	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:9	31.36	2922	3.02	13.45	94	196	Off Idle	43.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.23	13.3	0.91	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:9	31.36	2922	3.02	13.45	94	196	Off Idle	43.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.24	13.3	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:11:9	31.36	2918	3.02	13.46	94	196	Off Idle	43.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.17	13.28	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:9	31.36	2917	3.02	13.45	94	196	Off Idle	43.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.13	13.25	0.9	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:9	31.36	2917	3.02	13.46	94	196	Off Idle	43.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.13	13.24	0.9	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:11:9	29.99	2906	3.02	13.46	94	196	Off Idle	43.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.15	13.21	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:0	29.99	2922	3.02	13.45	94	196	Off Idle	43.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.16	13.22	0.9	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:0	29.99	2930	3.02	13.45	94	196	Off Idle	43.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.23	13.22	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:0	29.99	2930	3.02	13.45	94	196	Off Idle	43.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.23	13.23	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:0	31.36	2954	3.02	13.46	94	196	Off Idle	43.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.25	13.24	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:0	31.36	2913	3.02	13.45	94	196	Off Idle	43.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.29	13.26	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:0	31.36	2923	3.03	13.46	94	196	Off Idle	42.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.29	13.26	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:1	31.36	2924	3.03	13.47	94	196	Off Idle	42.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.21	13.28	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:1	31.36	2930	3.03	13.46	94	196	Off Idle	42.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.24	13.28	0.9	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:1	31.36	2936	3.03	13.46	94	196	Off Idle	43.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.19	13.31	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:1	31.36	2938	3.03	13.46	94	196	Off Idle	43.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.23	13.31	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:1	31.36	2940	3.03	13.48	94	196	Off Idle	42.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.17	13.3	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:1	31.36	2937	3.03	13.47	94	196	Off Idle	42.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.21	13.3	0.91	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:1	31.36	2939	3.03	13.48	94	196	Off Idle	42.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.15	13.29	0.91	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:2	31.36	2939	3.03	13.47	94	196	Off Idle	42.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.15	13.28	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:2	31.36	2944	3.03	13.47	94	196	Off Idle	42.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.12	13.28	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:2	31.36	2948	3.03	13.46	94	196	Off Idle	42.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.13	13.27	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:2	31.36	2948	3.03	13.46	94	196	Off Idle	42.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.13	13.25	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:2	31.36	2949	3.03	13.45	94	196	Off Idle	42.2	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.12	13.19	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:2	31.36	2952	3.03	13.45	94	196	Off Idle	42	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.11	13.17	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:3	31.36	2929	3.03	13.46	94	196	Off Idle	42	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.05	13.13	0.89	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:3	31.36	2929	3.03	13.45	94	196	Off Idle	41.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.05	13.11	0.89	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:3	31.36	2960	3.03	13.47	94	196	Off Idle	41.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.05	13.09	0.89	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:3	31.36	2964	3.02	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.08	13.08	0.89	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:3	31.36	2964	3.02	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.03	13.06	0.89	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:3	31.36	2960	3.02	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.03	13.04	0.89	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:4	31.36	2955	3.02	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.04	13.06	0.89	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:4	31.36	2955	3.02	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.01	13.08	0.89	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:4	31.36	2956	3.02	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0	13.11	0.89	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:4	31.36	2958	3.02	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.01	13.15	0.9	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:4	31.36	2980	3.03	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.03	13.18	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:4	31.36	2960	3.03	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.02	13.24	0.9	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:4	31.36	2965	3.03	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.04	13.26	0.9	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:5	31.36	2963	3.03	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.02	13.27	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:5	31.36	2941	3.03	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.03	13.28	0.9	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:5	31.36	2962	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.01	13.28	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:5	31.36	2966	3.03	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.05	13.29	0.91	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:5	31.36	2968	3.03	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.01	13.28	0.9	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:5	31.36	2982	3.03	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.04	13.27	0.9	3.4	5.5	ON	28 Pin	OFF	Removed	Disabled
03:23:12:6	31.36	2970	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.07	13.27	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:6	31.36	2971	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.03	13.25	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:6	31.36	2972	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.02	13.23	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:6	31.36	2984	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.04	13.21	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:6	31.36	2974	3.03	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.03	13.23	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:6	31.36	2976	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.02	13.24	0.9	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:6	31.36	2988	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	0.04	13.25	0.9	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:7	31.36	2992	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.04	13.23	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:12:7	31.36	2994	3.03	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.04	13.22	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:7	31.36	2994	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.05	13.21	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:7	31.36	2998	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.04	13.2	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:7	31.36	2994	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.03	13.21	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:7	31.36	2994	3.03	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.04	13.22	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:8	31.36	2992	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.01	13.24	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:8	31.36	2998	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.02	13.22	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:8	31.36	3002	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	0.02	13.22	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:8	31.36	3003	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.01	13.24	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:8	31.36	3006	3.03	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.02	13.25	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:8	31.36	3007	3.03	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.06	13.27	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:9	31.36	3007	3.03	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.11	13.28	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:9	31.36	2993	3.04	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.08	13.29	0.91	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:9	31.36	2992	3.04	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.08	13.29	0.91	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:9	31.36	2991	3.04	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.08	13.29	0.91	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:9	31.36	3003	3.04	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.13	13.29	0.91	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:9	31.36	3022	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.08	13.3	0.91	3.4	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:12:9	31.36	3030	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.15	13.3	0.91	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:0	31.36	3027	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-0.1	13.29	0.91	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:0	31.36	3022	3.03	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.16	13.27	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:0	31.36	3017	3.03	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.1	13.26	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:0	31.36	3014	3.03	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.13	13.24	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:0	32.72	3003	3.03	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.11	13.24	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:13:0	32.72	3005	3.03	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.17	13.23	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:13:1	32.72	3007	3.03	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.12	13.21	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:1	32.72	3027	3.03	13.47	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.19	13.21	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:1	32.72	3046	3.03	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.19	13.2	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:1	32.72	3048	3.03	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.19	13.2	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:13:1	32.72	3048	3.03	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.15	13.21	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:1	32.72	3032	3.03	13.44	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.19	13.25	0.9	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:1	31.36	3012	3.03	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.17	13.27	0.9	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:2	31.36	3012	3.03	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.21	13.29	0.91	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:2	31.36	3002	3.03	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.23	13.32	0.91	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:13:2	31.36	2961	3.03	13.44	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.24	13.33	0.91	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:13:2	31.36	2986	3.03	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.27	13.23	0.9	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:23:13:2	31.36	3030	3.03	13.44	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.28	13.24	0.9	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:2	31.36	3044	3.03	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.35	13.24	0.9	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:3	32.72	3080	3.03	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.32	13.24	0.9	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:3	32.72	3047	3.03	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.42	13.22	0.9	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:3	32.72	3038	3.03	13.45	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.41	13.21	0.9	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:3	32.72	3011	3.02	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.54	13.19	0.9	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:3	32.72	3021	3.02	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.53	13.15	0.9	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:3	32.72	3034	3.02	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.59	13.13	0.89	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:4	32.72	3036	3.02	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.6	13.19	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:4	32.72	3040	3.01	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.7	13.18	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:4	32.72	3043	3.01	13.44	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.65	13.17	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:4	32.72	3061	3.01	13.46	94	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.77	13.18	0.9	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:4	32.72	3060	3.01	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.75	13.19	0.9	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:23:13:4	32.72	3060	3	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-0.81	13.2	0.9	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:4	32.72	3046	3	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.78	13.21	0.9	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:5	32.72	3035	3	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.86	13.22	0.9	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:5	32.72	3032	3	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.81	13.26	0.9	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:5	32.72	3031	2.99	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.84	13.28	0.9	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:5	32.72	3040	2.99	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.81	13.29	0.91	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:5	32.72	3033	2.99	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.88	13.3	0.91	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:5	32.72	3062	2.99	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.83	13.31	0.91	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:6	32.72	3064	2.99	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-0.98	13.32	0.91	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:23:13:6	32.72	3065	2.98	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.09	13.32	0.91	3.5	5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:13:6	32.72	3063	2.98	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.17	13.33	0.91	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:23:13:6	32.72	3049	2.97	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.26	13.34	0.91	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:23:13:6	32.72	3033	2.96	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.51	13.34	0.91	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:23:13:6	32.72	3054	2.95	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.68	13.33	0.91	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:23:13:6	34.08	3032	2.93	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.93	13.34	0.91	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:23:13:7	34.08	3038	2.91	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.19	13.35	0.91	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:7	34.08	3042	2.89	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.56	13.32	0.91	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:23:13:7	34.08	3035	2.87	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.81	13.28	0.9	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:23:13:7	34.08	3056	2.84	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.23	13.24	0.9	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:7	34.08	3054	2.79	13.45	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.79	13.19	0.9	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:7	34.08	3052	2.75	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.24	13.14	0.89	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:8	34.08	3063	2.7	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.61	13.08	0.89	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:13:8	34.08	3029	2.65	13.47	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.17	13.03	0.89	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:13:8	34.08	3026	2.59	13.46	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.6	12.97	0.88	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:8	34.08	3025	2.56	13.48	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.14	12.94	0.88	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:13:8	34.08	3016	2.5	13.47	94	196	Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.62	12.92	0.88	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:13:8	35.45	3000	2.44	13.48	94	196	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.08	12.91	0.88	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:13:9	35.45	3000	2.37	13.46	94	196	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.45	12.92	0.88	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:13:9	35.45	2999	2.34	13.47	94	196	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.64	12.92	0.88	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:13:9	35.45	3001	2.25	13.46	94	196	Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.08	12.93	0.88	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:13:9	35.45	3000	2.19	13.46	94	196	Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.25	12.95	0.88	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:13:9	29.99	2933	2.13	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.46	13	0.89	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:13:9	29.99	2939	2.05	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.56	13.05	0.89	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:13:9	24.54	2939	1.99	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.78	13.14	0.9	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:0	19.09	2946	1.95	13.49	94	196	Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.89	13.22	0.9	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:0	19.09	2992	1.9	13.49	94	196	Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.94	13.26	0.9	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:0	19.09	2996	1.86	13.5	94	196	Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.03	13.34	0.91	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:0	19.09	3016	1.82	13.5	94	196	Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.19	13.5	0.92	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:0	19.09	3034	1.78	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.25	13.62	0.93	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:0	19.09	3043	1.75	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-9.31	13.78	0.94	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:1	19.09	3044	1.72	13.46	94	196	Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.34	13.92	0.95	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:1	19.09	3054	1.7	13.47	94	196	Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.36	14.06	0.96	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:1	19.09	3036	1.68	13.47	94	196	Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.35	14.19	0.97	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:1	19.09	3033	1.68	13.47	94	196	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.35	14.38	0.98	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:1	19.09	3020	1.67	13.46	94	196	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.37	14.51	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:1	19.09	3014	1.67	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.39	14.59	0.99	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:1	19.09	2986	1.67	13.46	94	196	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.32	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:2	19.09	2996	1.67	13.47	94	196	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.35	14.9	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:2	19.09	3007	1.67	13.46	94	196	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.32	15.13	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:2	19.09	3037	1.67	13.47	94	196	Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.35	15.29	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:2	19.09	3024	1.67	13.46	94	196	Idle	41.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.33	15.47	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:2	19.09	3006	1.67	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	15.65	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:2	19.09	3006	1.68	13.47	94	196	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	15.87	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:3	19.09	3028	1.68	13.48	94	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	16.3	1.11	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:3	19.09	3028	1.68	13.47	94	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	16.48	1.12	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:3	19.09	3034	1.68	13.49	93	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.4	17.16	1.17	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:3	19.09	3006	1.68	13.47	93	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	17.61	1.2	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:3	19.09	3006	1.68	13.49	94	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.42	18.05	1.23	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:3	19.09	3007	1.68	13.47	94	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.44	18.47	1.26	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:4	19.09	3026	1.69	13.48	94	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.42	18.85	1.28	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:4	19.09	3012	1.69	13.47	94	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	19.23	1.31	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:4	19.09	3002	1.69	13.48	94	196	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	19.58	1.33	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:4	19.09	3007	1.69	13.47	94	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.41	19.89	1.35	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:4	19.09	3008	1.7	13.48	94	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.45	20.01	1.36	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:4	19.09	3015	1.7	13.47	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:4	19.09	3022	1.7	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.42	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:5	19.09	3025	1.7	13.47	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:5	19.09	3047	1.7	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:14:5	19.09	3020	1.7	13.47	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.47	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:5	19.09	2968	1.7	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:5	19.09	2968	1.7	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:5	19.09	3004	1.7	13.49	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:6	19.09	3025	1.7	13.49	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:6	19.09	3011	1.7	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.47	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:6	19.09	2992	1.7	13.5	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:6	19.09	2990	1.7	13.5	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:6	19.09	2991	1.7	13.51	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.48	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:6	19.09	3002	1.7	13.5	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.44	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:6	19.09	2994	1.7	13.5	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:7	19.09	2994	1.7	13.49	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.47	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:7	19.09	2984	1.7	13.49	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.49	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:7	19.09	2999	1.71	13.49	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:7	19.09	2998	1.71	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.52	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:7	19.09	2996	1.71	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:7	19.09	2995	1.71	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:8	19.09	3002	1.71	13.47	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:8	19.09	2978	1.71	13.47	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:8	19.09	2978	1.71	13.47	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:8	19.09	2969	1.71	13.46	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:8	19.09	2968	1.71	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:8	19.09	2975	1.71	13.46	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:9	19.09	2977	1.71	13.47	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:9	19.09	2963	1.71	13.45	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:9	19.09	2963	1.71	13.47	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:9	19.09	2991	1.71	13.46	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:9	19.09	3007	1.71	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:9	19.09	2992	1.71	13.47	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:14:9	19.09	2991	1.71	13.49	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:0	19.09	2982	1.71	13.48	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:0	19.09	2978	1.71	13.49	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:0	19.09	2988	1.71	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:0	19.09	2958	1.7	13.49	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:0	19.09	2957	1.7	13.48	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:0	19.09	2958	1.7	13.49	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:1	19.09	2966	1.7	13.47	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:1	19.09	2981	1.7	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:1	19.09	2984	1.7	13.47	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:1	19.09	2982	1.7	13.49	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:1	19.09	2997	1.7	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:1	19.09	2994	1.7	13.5	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:1	19.09	3013	1.71	13.49	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:2	19.09	2976	1.71	13.5	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:2	19.09	2960	1.71	13.49	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:2	19.09	2958	1.71	13.49	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:2	19.09	2948	1.71	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:2	19.09	2938	1.71	13.49	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:2	19.09	2938	1.7	13.49	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:3	19.09	2914	1.7	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:3	19.09	2939	1.7	13.49	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:3	19.09	2941	1.7	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:3	19.09	2958	1.71	13.49	93	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:3	19.09	2956	1.71	13.48	93	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:3	19.09	2956	1.71	13.5	93	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:4	19.09	2963	1.71	13.49	93	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:4	19.09	2965	1.71	13.5	93	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:4	19.09	2988	1.71	13.49	93	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:15:4	19.09	2962	1.71	13.5	94	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:4	19.09	2948	1.71	13.49	94	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:4	19.09	2954	1.71	13.5	94	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:4	19.09	2954	1.71	13.49	94	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:5	19.09	2960	1.71	13.5	94	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:5	19.09	2945	1.71	13.48	94	196	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:5	19.09	2946	1.71	13.49	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:5	19.09	2923	1.71	13.47	93	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:5	19.09	2945	1.71	13.47	94	197	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:5	19.09	2945	1.71	13.49	94	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:6	19.09	2950	1.71	13.48	94	197	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:6	19.09	2949	1.71	13.49	94	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:6	19.09	2938	1.71	13.49	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.57	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:6	19.09	2943	1.71	13.48	94	196	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:6	19.09	2944	1.71	13.48	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:6	19.09	2930	1.71	13.49	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:6	19.09	2928	1.71	13.48	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:7	19.09	2901	1.71	13.48	93	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:7	19.09	2924	1.71	13.48	93	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:7	19.09	2922	1.71	13.46	93	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:7	19.09	2934	1.71	13.47	93	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:7	19.09	2927	1.71	13.46	93	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:7	19.09	2933	1.71	13.47	93	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.58	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:8	19.09	2934	1.7	13.46	94	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:8	19.09	2950	1.7	13.48	94	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:8	19.09	2941	1.7	13.47	94	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.56	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:8	19.09	2941	1.7	13.48	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:8	19.09	2919	1.7	13.46	93	196	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:8	19.09	2938	1.7	13.48	93	196	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:9	19.09	2936	1.7	13.46	93	196	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:9	19.09	2943	1.7	13.48	93	196	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:9	19.09	2929	1.7	13.47	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:9	19.09	2926	1.7	13.48	93	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:9	19.09	2926	1.7	13.47	93	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:9	19.09	2918	1.7	13.48	94	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:15:9	19.09	2930	1.7	13.48	94	197	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:0	19.09	2931	1.7	13.48	94	197	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:0	19.09	2942	1.7	13.48	93	197	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:0	19.09	2934	1.7	13.48	93	196	Idle	41.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:0	19.09	2922	1.7	13.47	93	196	Idle	41.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:0	19.09	2929	1.7	13.48	93	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:0	19.09	2925	1.7	13.46	93	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:1	19.09	2922	1.7	13.48	93	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:1	19.09	2914	1.7	13.47	94	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:1	19.09	2881	1.7	13.48	94	196	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:1	19.09	2881	1.7	13.49	94	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:1	19.09	2898	1.7	13.48	94	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:1	19.09	2908	1.7	13.49	94	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:1	19.09	2908	1.7	13.48	94	196	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:2	19.09	2900	1.7	13.48	93	196	Idle	41.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:2	19.09	2896	1.7	13.48	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:2	19.09	2909	1.7	13.47	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:2	19.09	2910	1.7	13.47	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:2	19.09	2936	1.7	13.48	93	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:2	19.09	2912	1.7	13.48	93	196	Idle	41.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:3	19.09	2914	1.7	13.48	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:3	19.09	2912	1.7	13.48	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:3	19.09	2912	1.7	13.48	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:16:3	19.09	2932	1.7	13.48	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:3	19.09	2921	1.7	13.49	93	196	Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:3	19.09	2896	1.7	13.49	93	196	Idle	42.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:4	19.09	2905	1.7	13.48	93	196	Idle	42.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:4	19.09	2904	1.7	13.48	93	196	Idle	42.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:4	19.09	2888	1.7	13.48	93	196	Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:4	19.09	2895	1.7	13.48	93	196	Idle	42.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:4	19.09	2895	1.69	13.49	93	196	Idle	42.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.2	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:4	19.09	2915	1.69	13.47	93	196	Idle	43	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.63	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:4	19.09	2892	1.69	13.47	93	196	Idle	43	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:5	19.09	2880	1.69	13.47	93	196	Idle	43.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:5	19.09	2890	1.69	13.48	93	196	Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.64	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:5	19.09	2892	1.69	13.47	93	196	Idle	43.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.19	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:5	19.09	2915	1.69	13.48	93	196	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:5	19.09	2904	1.69	13.48	93	196	Idle	43.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:5	19.09	2895	1.69	13.48	93	196	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:6	19.09	2897	1.69	13.47	94	196	Idle	43.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:6	19.09	2897	1.69	13.48	94	196	Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:6	19.09	2904	1.69	13.48	94	196	Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:6	19.09	2890	1.69	13.5	93	196	Idle	43.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:6	19.09	2889	1.69	13.49	93	196	Idle	43.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:6	19.09	2876	1.69	13.5	93	196	Idle	43.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:6	19.09	2882	1.68	13.49	93	196	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:7	19.09	2881	1.68	13.49	93	196	Idle	43.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:7	19.09	2882	1.68	13.48	93	196	Idle	43.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:7	19.09	2884	1.68	13.49	93	196	Idle	43.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:7	19.09	2905	1.68	13.48	93	196	Idle	43.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:7	19.09	2880	1.68	13.48	94	196	Idle	43.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:7	19.09	2880	1.68	13.47	94	196	Idle	43.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:8	19.09	2854	1.68	13.48	94	196	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:8	19.09	2875	1.68	13.48	93	196	Idle	44.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:8	19.09	2896	1.68	13.47	93	196	Idle	44.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:8	19.09	2884	1.68	13.47	93	196	Idle	44.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:8	19.09	2872	1.68	13.47	94	196	Idle	44.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:8	19.09	2850	1.68	13.48	94	196	Idle	44.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:9	19.09	2860	1.68	13.48	94	196	Idle	44	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:9	19.09	2870	1.68	13.5	93	196	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:9	19.09	2877	1.68	13.5	93	196	Idle	44	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:9	19.09	2863	1.68	13.49	94	196	Idle	44.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:9	19.09	2863	1.68	13.48	94	196	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:9	19.09	2863	1.68	13.48	94	196	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:16:9	19.09	2865	1.68	13.48	93	196	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:0	19.09	2865	1.68	13.48	93	196	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.04	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:0	19.09	2866	1.68	13.48	93	196	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.05	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:0	19.09	2880	1.67	13.49	93	196	Idle	44.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.05	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:0	19.09	2870	1.67	13.5	93	196	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.05	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:0	19.09	2870	1.67	13.49	93	196	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.06	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:0	19.09	2870	1.67	13.49	93	196	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.06	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:1	19.09	2870	1.67	13.48	93	196	Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.05	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:1	19.09	2870	1.67	13.49	93	196	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.06	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:1	19.09	2866	1.67	13.49	93	196	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.06	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:1	19.09	2866	1.67	13.48	93	196	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.06	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:1	19.09	2864	1.67	13.49	93	196	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:1	19.09	2870	1.67	13.49	93	196	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.68	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:1	19.09	2856	1.67	13.5	93	196	Idle	44.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:2	19.09	2832	1.67	13.48	93	196	Idle	44.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:2	19.09	2842	1.67	13.5	93	196	Idle	44.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:2	19.09	2849	1.67	13.49	93	196	Idle	45.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:17:2	19.09	2850	1.67	13.49	93	196	Idle	45.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:2	19.09	2850	1.67	13.48	93	196	Idle	45.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:2	19.09	2860	1.67	13.48	93	196	Idle	45.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:3	19.09	2848	1.66	13.48	93	196	Idle	45.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:3	19.09	2848	1.66	13.49	93	196	Idle	45.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:3	19.09	2847	1.66	13.48	93	196	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:3	19.09	2848	1.66	13.48	93	196	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:3	19.09	2871	1.66	13.48	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:3	19.09	2871	1.66	13.48	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:4	19.09	2849	1.66	13.48	93	196	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:4	19.09	2847	1.66	13.48	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:4	19.09	2846	1.66	13.48	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:4	19.09	2834	1.65	13.48	94	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:4	19.09	2843	1.65	13.48	94	196	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:4	19.09	2844	1.65	13.46	94	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:4	19.09	2842	1.65	13.47	93	196	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:5	19.09	2840	1.65	13.47	93	196	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:5	19.09	2843	1.65	13.47	93	196	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:5	19.09	2831	1.65	13.48	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:5	19.09	2842	1.65	13.49	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:5	19.09	2862	1.65	13.5	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:5	19.09	2854	1.65	13.48	94	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:6	19.09	2842	1.65	13.47	94	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:6	19.09	2843	1.65	13.48	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:6	19.09	2853	1.65	13.47	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:6	19.09	2838	1.65	13.48	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:6	19.09	2814	1.65	13.49	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:6	19.09	2835	1.65	13.49	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:6	19.09	2834	1.65	13.47	93	196	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:7	19.09	2828	1.65	13.49	93	196	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:7	19.09	2822	1.65	13.49	94	196	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:7	19.09	2840	1.65	13.47	94	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:7	19.09	2830	1.65	13.48	94	196	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:7	19.09	2815	1.65	13.48	94	196	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:7	19.09	2815	1.65	13.47	94	196	Idle	46	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:8	19.09	2815	1.65	13.47	93	196	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:8	19.09	2819	1.65	13.47	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:8	19.09	2824	1.64	13.48	93	196	Idle	45.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:8	19.09	2824	1.64	13.47	93	196	Idle	45.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:8	19.09	2842	1.65	13.48	93	196	Idle	45.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:8	19.09	2833	1.65	13.48	93	196	Idle	45.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:9	19.09	2837	1.65	13.48	93	196	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:9	19.09	2824	1.65	13.48	93	196	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:9	19.09	2832	1.65	13.48	93	196	Idle	46.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:9	19.09	2825	1.65	13.47	94	196	Idle	46.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:9	19.09	2820	1.65	13.47	94	196	Idle	46.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:9	19.09	2818	1.65	13.48	94	196	Idle	46.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:17:9	19.09	2833	1.65	13.48	93	196	Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:0	19.09	2810	1.64	13.48	93	196	Idle	46.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:0	19.09	2810	1.64	13.48	93	196	Idle	46.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:0	19.09	2808	1.64	13.48	93	196	Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:0	19.09	2807	1.64	13.48	93	196	Idle	47.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:0	19.09	2800	1.64	13.48	94	196	Idle	47.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:0	19.09	2814	1.64	13.48	94	196	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:1	19.09	2820	1.64	13.47	94	196	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:1	19.09	2820	1.63	13.48	94	196	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:1	19.09	2824	1.63	13.48	94	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:1	19.09	2804	1.63	13.48	94	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:18:1	19.09	2804	1.63	13.49	94	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:1	19.09	2820	1.63	13.5	94	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:1	19.09	2816	1.63	13.49	94	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:2	19.09	2814	1.62	13.49	94	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:2	19.09	2812	1.62	13.49	94	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:2	19.09	2819	1.62	13.47	94	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:2	19.09	2802	1.62	13.48	93	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:2	19.09	2802	1.62	13.47	93	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:2	19.09	2799	1.62	13.47	93	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:3	19.09	2797	1.62	13.47	93	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:3	19.09	2797	1.62	13.48	93	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:3	19.09	2794	1.62	13.48	93	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:3	19.09	2793	1.62	13.48	93	196	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:3	19.09	2796	1.62	13.48	93	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:3	19.09	2794	1.62	13.48	93	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:4	19.09	2794	1.62	13.48	93	196	Idle	47.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:4	19.09	2792	1.62	13.48	93	196	Idle	47.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:4	19.09	2790	1.62	13.48	93	196	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:4	19.09	2778	1.62	13.48	93	196	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.26	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:4	19.09	2784	1.62	13.48	93	196	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.26	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:4	19.09	2804	1.62	13.47	93	196	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:4	19.09	2792	1.62	13.47	93	196	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:5	19.09	2782	1.62	13.47	93	196	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:5	19.09	2784	1.61	13.46	93	196	Idle	48.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:5	19.09	2784	1.61	13.47	93	196	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:5	19.09	2784	1.61	13.47	93	196	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:5	19.09	2784	1.61	13.46	93	196	Idle	48.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:5	19.09	2785	1.61	13.46	93	196	Idle	49	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:6	19.09	2776	1.61	13.46	93	196	Idle	49.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:6	19.09	2790	1.61	13.47	93	196	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:6	19.09	2788	1.6	13.45	93	196	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:6	19.09	2787	1.6	13.46	93	196	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:6	19.09	2787	1.6	13.47	93	196	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:6	19.09	2805	1.6	13.47	93	196	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:6	19.09	2795	1.6	13.47	93	196	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:7	19.09	2782	1.6	13.48	93	196	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:7	19.09	2780	1.6	13.48	93	196	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:7	19.09	2780	1.59	13.48	93	196	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:7	19.09	2777	1.59	13.49	93	196	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:7	19.09	2770	1.59	13.47	93	196	Idle	49.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:7	19.09	2766	1.59	13.49	93	196	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:8	19.09	2766	1.59	13.49	93	196	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:8	19.09	2763	1.59	13.49	93	196	Idle	49.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:8	19.09	2785	1.59	13.5	93	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:8	19.09	2778	1.59	13.48	93	196	Idle	49.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:8	19.09	2775	1.59	13.49	93	196	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:8	19.09	2762	1.59	13.5	93	196	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:9	19.09	2773	1.59	13.48	93	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:9	19.09	2785	1.59	13.48	93	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:9	19.09	2787	1.58	13.48	93	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:9	19.09	2784	1.58	13.49	93	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:9	19.09	2784	1.58	13.49	93	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:9	19.09	2778	1.58	13.49	93	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:18:9	19.09	2774	1.58	13.49	94	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:0	19.09	2768	1.58	13.48	94	196	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:0	19.09	2761	1.58	13.49	93	196	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:0	19.09	2750	1.58	13.47	93	196	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:0	19.09	2756	1.58	13.48	93	196	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:19:0	19.09	2753	1.58	13.48	93	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:0	19.09	2742	1.58	13.47	93	196	Idle	49.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:1	19.09	2749	1.58	13.48	93	196	Idle	50	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:1	19.09	2748	1.58	13.48	93	196	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:1	19.09	2760	1.58	13.48	93	196	Idle	50.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:1	19.09	2749	1.58	13.48	93	196	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:1	19.09	2749	1.58	13.48	93	196	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:1	19.09	2748	1.58	13.48	93	196	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:1	19.09	2748	1.58	13.49	93	196	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:2	19.09	2736	1.58	13.49	93	196	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:2	19.09	2744	1.58	13.49	93	196	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:2	19.09	2746	1.58	13.5	93	196	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:2	19.09	2749	1.58	13.49	93	196	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:2	19.09	2749	1.58	13.47	93	196	Idle	50.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:2	19.09	2749	1.58	13.49	93	196	Idle	50.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:3	19.09	2751	1.58	13.47	93	196	Idle	50.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:3	19.09	2761	1.58	13.47	93	196	Idle	50.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:3	19.09	2750	1.58	13.48	93	196	Idle	50.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:3	19.09	2750	1.57	13.48	93	196	Idle	50.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:3	19.09	2737	1.57	13.48	93	196	Idle	50.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:3	19.09	2750	1.57	13.5	93	196	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:4	19.09	2748	1.57	13.49	93	196	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:4	19.09	2746	1.57	13.49	93	196	Idle	51.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:4	19.09	2745	1.57	13.5	93	196	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:4	19.09	2742	1.56	13.49	93	196	Idle	51.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:4	19.09	2740	1.56	13.49	93	196	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:4	19.09	2750	1.56	13.48	93	196	Idle	51.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:4	19.09	2735	1.56	13.48	93	196	Idle	51.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:5	19.09	2734	1.56	13.48	93	196	Idle	52	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:5	19.09	2722	1.56	13.47	94	196	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:5	19.09	2731	1.56	13.46	94	196	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:5	19.09	2731	1.55	13.46	94	196	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:5	19.09	2740	1.55	13.47	94	196	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:5	19.09	2728	1.55	13.47	94	196	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:6	19.09	2709	1.55	13.47	93	196	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:6	19.09	2720	1.55	13.47	93	196	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:6	19.09	2729	1.55	13.49	93	196	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:6	19.09	2730	1.55	13.49	93	196	Idle	52.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:6	19.09	2730	1.54	13.49	93	196	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:6	19.09	2730	1.54	13.5	93	196	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:6	19.09	2729	1.54	13.49	93	196	Idle	52.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:7	19.09	2726	1.54	13.49	93	196	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:7	19.09	2726	1.54	13.48	93	196	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:7	19.09	2725	1.54	13.47	93	196	Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:7	19.09	2723	1.54	13.46	93	196	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.1	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:7	19.09	2723	1.54	13.47	93	196	Idle	52.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.1	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:7	19.09	2722	1.54	13.46	93	196	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.1	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:8	19.09	2682	1.54	13.46	93	196	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.1	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:8	19.09	2721	1.54	13.48	93	196	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.11	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:8	19.09	2721	1.54	13.49	93	196	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.12	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:8	19.09	2720	1.54	13.48	93	196	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.12	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:8	19.09	2717	1.53	13.47	93	196	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.11	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:8	19.09	2717	1.53	13.48	93	196	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.12	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:9	19.09	2714	1.53	13.48	93	196	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:9	19.09	2714	1.53	13.46	93	196	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:9	19.09	2711	1.53	13.47	93	196	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:9	19.09	2711	1.53	13.47	93	196	Idle	52.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:9	19.09	2713	1.53	13.48	93	196	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:19:9	19.09	2711	1.53	13.48	93	196	Idle	53.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:19:9	19.09	2711	1.53	13.48	93	196	Idle	53.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:0	19.09	2695	1.53	13.47	93	196	Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:0	19.09	2715	1.53	13.47	93	196	Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:0	19.09	2716	1.52	13.47	93	196	Idle	53.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:0	19.09	2712	1.52	13.47	93	196	Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:0	19.09	2710	1.52	13.47	93	196	Idle	53.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:0	19.09	2707	1.52	13.48	93	196	Idle	53.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:1	19.09	2706	1.52	13.48	93	196	Idle	53.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:1	19.09	2703	1.52	13.46	93	196	Idle	53.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:1	19.09	2703	1.52	13.48	93	196	Idle	53.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:1	19.09	2703	1.51	13.48	93	196	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:1	19.09	2705	1.51	13.48	93	196	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:1	19.09	2704	1.51	13.49	93	196	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:1	19.09	2704	1.51	13.49	93	196	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.15	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:2	19.09	2727	1.51	13.49	93	196	Idle	53.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.15	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:2	19.09	2716	1.51	13.48	93	196	Idle	53.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.15	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:2	19.09	2684	1.51	13.49	93	196	Idle	53.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.14	1.37	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:2	19.09	2705	1.51	13.48	93	196	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.14	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:2	19.09	2704	1.51	13.47	93	196	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.14	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:2	19.09	2702	1.51	13.48	93	196	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.13	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:3	19.09	2699	1.51	13.47	94	196	Idle	54.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.13	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:3	19.09	2696	1.51	13.48	94	196	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.14	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:3	19.09	2696	1.51	13.49	94	196	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.15	1.37	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:3	19.09	2693	1.51	13.49	93	196	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.25	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:3	19.09	2691	1.51	13.48	93	196	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:3	19.09	2691	1.51	13.48	93	196	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:4	19.09	2689	1.51	13.48	93	196	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:4	19.09	2686	1.51	13.47	93	196	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.26	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:4	19.09	2683	1.51	13.48	93	196	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:4	19.09	2683	1.5	13.48	93	196	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:4	19.09	2687	1.5	13.47	93	196	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.25	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:4	19.09	2687	1.5	13.48	93	196	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:4	19.09	2686	1.5	13.48	93	196	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:5	19.09	2686	1.5	13.48	93	196	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:5	19.09	2685	1.5	13.48	93	196	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:5	19.09	2684	1.5	13.48	93	196	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:5	19.09	2672	1.5	13.48	93	196	Idle	54.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:5	19.09	2682	1.5	13.49	93	196	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:5	19.09	2681	1.5	13.49	93	196	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:6	19.09	2680	1.5	13.48	93	196	Idle	54.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:6	19.09	2678	1.5	13.49	93	196	Idle	54.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:6	19.09	2679	1.5	13.49	93	196	Idle	54.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:6	19.09	2677	1.5	13.48	93	196	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:6	19.09	2676	1.5	13.49	93	196	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:6	19.09	2694	1.5	13.48	93	196	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:6	19.09	2684	1.5	13.49	93	196	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:7	19.09	2672	1.49	13.5	93	196	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:7	19.09	2672	1.49	13.48	93	196	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:7	19.09	2672	1.49	13.48	93	196	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:7	19.09	2673	1.49	13.47	93	196	Idle	55.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:7	19.09	2671	1.49	13.49	93	196	Idle	55.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:7	19.09	2671	1.49	13.48	93	196	Idle	55.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:8	19.09	2669	1.49	13.48	93	196	Idle	55.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:8	19.09	2668	1.49	13.47	93	196	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:8	19.09	2663	1.49	13.47	93	196	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:8	19.09	2663	1.48	13.48	93	196	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:8	19.09	2660	1.48	13.48	93	196	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:20:8	19.09	2660	1.48	13.48	93	196	Idle	56.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:9	19.09	2660	1.48	13.47	93	196	Idle	56.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:9	19.09	2660	1.48	13.47	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:9	19.09	2664	1.48	13.48	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:9	19.09	2670	1.48	13.47	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:9	19.09	2671	1.48	13.47	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:9	19.09	2676	1.48	13.47	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:20:9	19.09	2678	1.48	13.47	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:0	19.09	2677	1.47	13.47	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:0	19.09	2686	1.47	13.47	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:0	19.09	2670	1.47	13.48	93	196	Idle	56.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:0	19.09	2665	1.47	13.48	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:0	19.09	2653	1.47	13.47	93	196	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:0	19.09	2655	1.47	13.49	93	196	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:1	19.09	2650	1.47	13.49	93	196	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:1	19.09	2658	1.47	13.48	93	196	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:1	19.09	2643	1.47	13.48	93	196	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:1	19.09	2642	1.47	13.48	93	196	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:1	19.09	2641	1.47	13.49	93	196	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:1	19.09	2644	1.47	13.48	93	196	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:1	19.09	2644	1.47	13.49	93	196	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:2	19.09	2648	1.47	13.49	93	196	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:2	19.09	2634	1.47	13.49	93	196	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:2	19.09	2658	1.47	13.49	93	196	Idle	55.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:2	19.09	2668	1.47	13.48	94	196	Idle	55.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:2	19.09	2656	1.47	13.49	94	196	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:2	19.09	2653	1.47	13.49	94	196	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:3	19.09	2652	1.47	13.47	93	196	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:3	19.09	2648	1.47	13.48	93	196	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:3	19.09	2644	1.47	13.47	93	196	Idle	56.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:3	19.09	2642	1.47	13.46	93	196	Idle	56.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:3	19.09	2638	1.47	13.46	93	196	Idle	56.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:3	19.09	2624	1.47	13.48	93	196	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:4	19.09	2633	1.47	13.47	93	196	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:4	19.09	2633	1.47	13.49	93	196	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:4	19.09	2632	1.46	13.48	93	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:4	19.09	2630	1.46	13.47	93	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:4	19.09	2632	1.46	13.47	93	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:4	19.09	2634	1.46	13.48	94	196	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:4	19.09	2646	1.46	13.48	94	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:5	19.09	2640	1.46	13.49	94	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:5	19.09	2643	1.46	13.47	93	196	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:5	19.09	2644	1.46	13.49	93	196	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:5	19.09	2644	1.46	13.48	93	196	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:5	19.09	2643	1.46	13.49	93	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:5	19.09	2652	1.46	13.48	93	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:6	19.09	2639	1.45	13.48	93	196	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:6	19.09	2624	1.45	13.48	93	196	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:6	19.09	2629	1.45	13.48	93	196	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:6	19.09	2628	1.45	13.46	93	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:6	19.09	2635	1.45	13.47	93	196	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:6	19.09	2623	1.45	13.47	93	196	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:6	19.09	2612	1.45	13.46	93	196	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:7	19.09	2618	1.45	13.48	93	196	Idle	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:7	19.09	2618	1.45	13.46	93	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:7	19.09	2615	1.45	13.46	93	196	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:7	19.09	2615	1.45	13.46	93	196	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:7	19.09	2615	1.46	13.48	93	196	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:21:7	19.09	2616	1.46	13.48	93	196	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:8	19.09	2616	1.46	13.48	93	196	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:8	19.09	2604	1.46	13.49	93	196	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:8	19.09	2626	1.46	13.48	93	196	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:8	19.09	2616	1.45	13.47	93	196	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:8	19.09	2616	1.45	13.48	93	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:8	19.09	2602	1.45	13.48	93	196	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:9	19.09	2614	1.45	13.47	93	196	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:9	19.09	2614	1.45	13.46	93	196	Idle	57.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:9	19.09	2614	1.45	13.47	93	196	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:9	19.09	2614	1.45	13.48	93	196	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:9	19.09	2614	1.45	13.47	93	196	Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:9	19.09	2616	1.45	13.48	93	196	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:21:9	19.09	2616	1.45	13.48	93	196	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:0	19.09	2617	1.44	13.5	93	196	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:0	19.09	2616	1.44	13.5	93	196	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:0	19.09	2614	1.44	13.49	93	196	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:0	19.09	2613	1.44	13.5	93	196	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:0	19.09	2612	1.43	13.49	93	196	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:0	19.09	2608	1.43	13.48	93	196	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:1	19.09	2605	1.43	13.48	93	196	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:1	19.09	2605	1.43	13.48	93	196	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:1	19.09	2600	1.43	13.49	93	196	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:1	19.09	2593	1.42	13.49	93	196	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:1	19.09	2602	1.42	13.48	93	196	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:1	19.09	2602	1.42	13.48	93	196	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:1	19.09	2595	1.42	13.46	93	196	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:2	19.09	2596	1.42	13.45	93	196	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:2	19.09	2598	1.42	13.46	93	196	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:2	19.09	2598	1.42	13.47	93	196	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:2	19.09	2601	1.41	13.47	93	196	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:2	19.09	2602	1.41	13.48	93	196	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:2	19.09	2602	1.41	13.46	93	196	Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:3	19.09	2604	1.41	13.47	93	196	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:3	19.09	2604	1.41	13.49	93	196	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:3	19.09	2601	1.41	13.47	93	196	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:3	19.09	2600	1.41	13.49	93	196	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:3	19.09	2596	1.41	13.48	93	196	Idle	59.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:3	19.09	2596	1.41	13.48	93	196	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:4	19.09	2592	1.41	13.48	93	196	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:4	19.09	2592	1.41	13.49	93	196	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:4	19.09	2590	1.41	13.48	93	196	Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:4	19.09	2590	1.41	13.49	93	196	Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:4	19.09	2590	1.41	13.5	93	196	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:4	19.09	2589	1.41	13.5	93	196	Idle	60	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:4	19.09	2609	1.41	13.49	93	196	Idle	60.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:5	19.09	2585	1.41	13.48	93	196	Idle	60.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:5	19.09	2584	1.41	13.48	93	196	Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:5	19.09	2572	1.41	13.48	93	196	Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:5	19.09	2580	1.41	13.47	93	196	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:5	19.09	2578	1.4	13.47	93	196	Idle	60.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:5	19.09	2578	1.4	13.47	93	196	Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:6	19.09	2576	1.4	13.49	93	196	Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:6	19.09	2577	1.4	13.48	93	196	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:6	19.09	2577	1.4	13.47	93	196	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:6	19.09	2577	1.4	13.47	93	196	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:6	19.09	2582	1.4	13.48	93	196	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:6	19.09	2582	1.39	13.47	93	196	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:22:6	19.09	2584	1.39	13.48	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:7	19.09	2624	1.39	13.46	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:7	19.09	2624	1.39	13.47	93	196	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:7	19.09	2582	1.39	13.47	93	196	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:7	19.09	2559	1.39	13.46	93	196	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:7	19.09	2578	1.39	13.47	93	196	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:7	19.09	2578	1.39	13.48	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:8	19.09	2576	1.39	13.48	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:8	19.09	2576	1.39	13.48	93	196	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:8	19.09	2573	1.38	13.48	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:8	19.09	2572	1.38	13.48	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:8	19.09	2572	1.38	13.48	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:8	19.09	2572	1.38	13.48	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:9	19.09	2571	1.38	13.48	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:9	19.09	2570	1.38	13.48	93	196	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:9	19.09	2569	1.38	13.47	93	196	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:9	19.09	2558	1.38	13.47	93	196	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:9	19.09	2564	1.38	13.47	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:9	19.09	2564	1.38	13.47	93	196	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:22:9	19.09	2570	1.38	13.47	93	196	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:0	19.09	2556	1.38	13.48	93	196	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:0	19.09	2553	1.38	13.47	93	196	Idle	61.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:0	19.09	2552	1.38	13.48	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:0	19.09	2551	1.38	13.48	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:0	19.09	2550	1.38	13.47	93	196	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:0	19.09	2552	1.38	13.47	93	196	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:1	19.09	2566	1.38	13.49	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:1	19.09	2561	1.38	13.47	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:1	19.09	2545	1.38	13.48	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:1	19.09	2545	1.38	13.48	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:1	19.09	2565	1.38	13.47	93	196	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:1	19.09	2585	1.38	13.48	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:1	19.09	2564	1.38	13.48	93	196	Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:2	19.09	2564	1.38	13.47	94	196	Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:2	19.09	2563	1.37	13.47	94	196	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:2	19.09	2558	1.37	13.47	94	196	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:2	19.09	2552	1.37	13.48	93	196	Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:2	19.09	2552	1.37	13.47	93	196	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:2	19.09	2563	1.37	13.46	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:3	19.09	2539	1.37	13.47	93	196	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:3	19.09	2539	1.37	13.48	93	196	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:3	19.09	2536	1.37	13.46	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:3	19.09	2532	1.37	13.48	93	196	Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:3	19.09	2532	1.37	13.49	93	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:3	19.09	2532	1.37	13.48	93	196	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:4	19.09	2529	1.37	13.48	93	196	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:4	19.09	2531	1.37	13.48	93	196	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:4	19.09	2531	1.37	13.48	94	196	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:4	19.09	2530	1.37	13.49	94	196	Idle	61.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:4	19.09	2532	1.37	13.47	94	196	Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:4	19.09	2532	1.37	13.48	93	196	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:4	19.09	2534	1.37	13.48	93	196	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:5	19.09	2538	1.37	13.48	93	196	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:5	19.09	2542	1.37	13.46	94	196	Idle	61.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:5	19.09	2542	1.37	13.48	94	196	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:5	19.09	2545	1.37	13.48	94	196	Idle	61.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:5	19.09	2548	1.37	13.48	93	196	Idle	61.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:5	19.09	2548	1.37	13.48	93	196	Idle	62.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:23:6	19.09	2540	1.37	13.48	93	196	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:6	19.09	2549	1.37	13.49	93	196	Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:6	19.09	2543	1.37	13.49	93	196	Idle	62.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:6	19.09	2543	1.37	13.48	93	196	Idle	62.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:6	19.09	2555	1.37	13.48	93	196	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:6	19.09	2555	1.37	13.48	93	196	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:6	19.09	2527	1.37	13.47	93	196	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:7	19.09	2480	1.37	13.46	94	196	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:7	19.09	2496	1.37	13.47	94	196	Idle	62.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:7	19.09	2510	1.36	13.47	94	196	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:7	19.09	2509	1.36	13.49	93	196	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:7	19.09	2508	1.36	13.49	93	196	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:7	19.09	2509	1.36	13.49	93	196	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:8	19.09	2512	1.36	13.49	93	196	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:8	19.09	2515	1.36	13.48	93	196	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:8	19.09	2518	1.36	13.47	93	196	Idle	63.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:8	19.09	2546	1.36	13.47	93	196	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:8	19.09	2527	1.36	13.47	93	196	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:8	19.09	2527	1.36	13.47	93	196	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:9	19.09	2525	1.36	13.47	93	196	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:9	19.09	2525	1.35	13.46	93	196	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:9	19.09	2524	1.35	13.46	93	196	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:9	19.09	2528	1.35	13.47	93	196	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:9	19.09	2514	1.35	13.46	93	196	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:9	19.09	2510	1.35	13.47	93	196	Idle	63.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:23:9	19.09	2510	1.35	13.47	93	196	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:0	19.09	2500	1.35	13.47	93	196	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:0	19.09	2510	1.35	13.48	93	196	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:0	19.09	2511	1.35	13.47	93	196	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:0	19.09	2512	1.35	13.47	93	196	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:0	19.09	2514	1.34	13.47	93	196	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:0	19.09	2515	1.34	13.48	93	196	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:1	19.09	2515	1.34	13.47	93	196	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:1	19.09	2504	1.34	13.48	93	196	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:1	19.09	2515	1.34	13.46	93	196	Full Load	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:1	19.09	2530	1.34	13.47	93	196	Full Load	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:1	19.09	2530	1.34	13.47	93	196	Off Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:1	9.54	2444	1.34	13.46	93	196	Off Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:24:1	9.54	2516	1.34	13.47	93	196	Off Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:24:2	12.27	2525	1.35	13.48	93	196	Off Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:24:2	14.99	2524	1.35	13.47	93	196	Off Idle	64.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:24:2	14.99	2521	1.35	13.48	93	196	Off Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:24:2	17.72	2538	1.35	13.49	93	196	Off Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:24:2	20.45	2538	1.36	13.48	93	196	Off Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:24:2	20.45	2518	1.36	13.47	93	196	Off Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:24:3	23.18	2515	1.36	13.46	93	196	Off Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:24:3	25.9	2515	1.37	13.46	93	196	Off Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:24:3	25.9	2512	1.38	13.48	93	196	Off Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:24:3	28.63	2514	1.38	13.46	93	196	Off Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:24:3	31.36	2514	1.39	13.47	93	196	Off Idle	65.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:24:3	31.36	2515	1.4	13.49	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:4	34.08	2528	1.41	13.48	93	196	Off Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:4	35.45	2528	1.42	13.5	93	196	Off Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:4	35.45	2513	1.43	13.48	93	196	Off Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:4	35.45	2513	1.44	13.48	93	196	Off Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:4	35.45	2531	1.45	13.47	94	196	Off Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.21	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:24:4	35.45	2520	1.46	13.47	94	196	Off Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:24:4	35.45	2513	1.48	13.48	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:24:5	35.45	2513	1.49	13.5	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:24:5	35.45	2508	1.5	13.49	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:5	35.45	2500	1.51	13.49	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:5	35.45	2500	1.52	13.49	93	196	Off Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:24:5	35.45	2496	1.53	13.47	93	196	Off Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:5	35.45	2469	1.54	13.45	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.92	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:6	35.45	2487	1.55	13.46	93	196	Off Idle	65.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.9	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:6	35.45	2487	1.56	13.47	93	196	Off Idle	65.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:6	35.45	2488	1.57	13.46	93	196	Off Idle	65.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.87	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:6	35.45	2506	1.57	13.47	93	196	Off Idle	66	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:6	35.45	2496	1.58	13.47	93	196	Off Idle	66.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:6	35.45	2484	1.59	13.46	93	196	Off Idle	66.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:6	35.45	2489	1.59	13.46	93	196	Off Idle	66.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:7	35.45	2476	1.6	13.46	93	196	Off Idle	66.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.77	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:7	35.45	2488	1.61	13.45	93	196	Off Idle	66.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:24:7	35.45	2501	1.61	13.48	93	196	Off Idle	66.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.71	20.24	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:24:7	35.45	2509	1.62	13.47	93	196	Off Idle	66.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.69	20.24	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:24:7	35.45	2509	1.63	13.47	93	196	Off Idle	66.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	20.23	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:24:7	35.45	2514	1.63	13.47	93	196	Off Idle	66.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.62	20.13	1.37	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:24:8	35.45	2503	1.64	13.49	93	196	Off Idle	66.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.54	19.93	1.36	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:24:8	35.45	2504	1.65	13.48	93	196	Off Idle	66.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.52	19.74	1.34	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:24:8	35.45	2504	1.65	13.49	93	196	Off Idle	66.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.48	19.62	1.34	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:24:8	35.45	2503	1.66	13.48	93	196	Off Idle	66.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.45	19.24	1.31	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:24:8	35.45	2509	1.66	13.49	93	196	Off Idle	66.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.44	18.94	1.29	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:24:8	35.45	2509	1.67	13.47	94	196	Off Idle	66	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.43	18.64	1.27	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:24:9	35.45	2515	1.68	13.48	94	196	Off Idle	65.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.37	18.31	1.25	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:24:9	35.45	2534	1.69	13.46	93	196	Off Idle	65.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.34	17.97	1.22	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:24:9	35.45	2525	1.69	13.47	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.3	17.66	1.2	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:24:9	35.45	2517	1.7	13.48	93	196	Off Idle	65.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.26	17.28	1.18	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:24:9	35.45	2516	1.71	13.49	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.25	17.07	1.16	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:24:9	35.45	2489	1.71	13.48	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.22	16.9	1.15	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:24:9	35.45	2495	1.72	13.48	94	196	Off Idle	65.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.18	16.76	1.14	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:0	35.45	2491	1.73	13.47	93	196	Off Idle	65.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.18	16.64	1.13	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:0	35.45	2481	1.73	13.46	93	196	Off Idle	65.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.14	16.54	1.13	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:0	35.45	2481	1.74	13.47	93	196	Off Idle	65.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.08	16.41	1.12	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:0	35.45	2478	1.74	13.46	93	196	Off Idle	65.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.06	16.38	1.12	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:0	35.45	2476	1.75	13.47	93	196	Off Idle	65.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.01	16.28	1.11	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:0	35.45	2479	1.75	13.48	93	196	Off Idle	65.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.96	16.21	1.1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:1	35.45	2478	1.76	13.46	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.96	16.12	1.1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:1	35.45	2495	1.77	13.47	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.93	16.04	1.09	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:1	35.45	2493	1.77	13.47	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.9	15.92	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:1	35.45	2498	1.78	13.47	93	196	Off Idle	66	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.84	15.85	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:1	35.45	2498	1.78	13.46	93	196	Off Idle	66.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.83	15.78	1.08	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:1	35.45	2498	1.79	13.46	93	196	Off Idle	66.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.78	15.7	1.07	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:1	35.45	2515	1.79	13.46	93	196	Off Idle	66.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.75	15.63	1.06	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:2	35.45	2514	1.79	13.47	93	196	Off Idle	66.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.72	15.56	1.06	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:2	35.45	2510	1.8	13.47	93	196	Off Idle	66.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.73	15.51	1.06	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:2	35.45	2521	1.8	13.48	93	196	Off Idle	66	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.7	15.44	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:2	35.45	2508	1.8	13.46	93	196	Off Idle	66	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.69	15.4	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:2	35.45	2481	1.81	13.47	93	196	Off Idle	65.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.68	15.33	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:2	35.45	2472	1.81	13.46	93	196	Off Idle	65.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.66	15.29	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:3	35.45	2471	1.82	13.47	93	196	Off Idle	65.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.64	15.26	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:25:3	35.45	2475	1.82	13.46	93	196	Off Idle	65.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.59	15.23	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:3	35.45	2481	1.83	13.47	93	196	Off Idle	66	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.59	15.18	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:3	35.45	2495	1.83	13.47	93	196	Off Idle	66.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.55	15.16	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:3	35.45	2495	1.83	13.47	93	196	Off Idle	66	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.54	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:3	35.45	2494	1.83	13.47	93	196	Off Idle	66	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.52	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:4	35.45	2509	1.84	13.47	93	196	Off Idle	66	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.51	15.08	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:25:4	35.45	2510	1.84	13.47	93	196	Off Idle	66	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.51	15.06	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:4	35.45	2520	1.84	13.47	93	196	Off Idle	66	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.49	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:4	35.45	2503	1.85	13.48	93	196	Off Idle	66	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.48	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:4	35.45	2498	1.85	13.47	93	196	Off Idle	66.2	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.48	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:4	35.45	2496	1.85	13.48	93	196	Off Idle	66.3	0	2	132	944 Turbo	0.19	Rich	1	14.6	-8.43	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:4	35.45	2483	1.86	13.49	93	196	Off Idle	66.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.41	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:5	35.45	2489	1.86	13.49	93	196	Off Idle	66.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.41	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:5	35.45	2489	1.86	13.49	93	196	Off Idle	66.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.41	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:5	35.45	2487	1.87	13.47	93	196	Off Idle	66.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.37	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:5	35.45	2489	1.87	13.47	93	196	Off Idle	66.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.34	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:5	35.45	2488	1.87	13.46	93	196	Off Idle	66.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.33	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:5	35.45	2482	1.87	13.48	93	196	Off Idle	66.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.29	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:6	35.45	2484	1.87	13.47	93	196	Off Idle	66.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.31	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:6	35.45	2486	1.88	13.48	93	196	Off Idle	66.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.26	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:6	35.45	2503	1.88	13.49	93	196	Off Idle	66.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.26	15.1	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:6	35.45	2499	1.88	13.48	93	196	Off Idle	67	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.19	15.12	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:6	35.45	2498	1.88	13.48	93	196	Off Idle	67	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.18	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:6	35.45	2477	1.89	13.48	93	196	Off Idle	67.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.17	15.13	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:25:6	35.45	2477	1.89	13.48	93	196	Off Idle	67.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.17	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:7	35.45	2496	1.9	13.48	93	196	Off Idle	67.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.15	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:7	35.45	2496	1.9	13.48	93	196	Off Idle	67.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.12	15.11	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:7	35.45	2494	1.9	13.48	93	196	Off Idle	67.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.1	15.1	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:7	35.45	2488	1.91	13.46	93	196	Off Idle	67.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.1	15.09	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:7	35.45	2488	1.91	13.46	93	196	Off Idle	67.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.06	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:7	35.45	2491	1.91	13.47	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.06	15.03	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:8	35.45	2491	1.91	13.47	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.03	15	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:8	35.45	2492	1.92	13.48	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.01	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:8	35.45	2517	1.92	13.48	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.97	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:8	35.45	2508	1.92	13.48	94	196	Off Idle	66.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.99	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:8	35.45	2499	1.92	13.47	94	196	Off Idle	66.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.98	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:8	35.45	2501	1.93	13.46	93	196	Off Idle	66.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:9	35.45	2494	1.93	13.47	93	196	Off Idle	66.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.96	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:9	35.45	2494	1.93	13.47	93	196	Off Idle	66.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.93	14.81	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:9	34.08	2483	1.94	13.48	93	196	Off Idle	66.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.91	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:9	34.08	2491	1.94	13.48	93	196	Off Idle	66.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.89	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:9	34.08	2490	1.94	13.47	93	196	Off Idle	66.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.86	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:25:9	34.08	2490	1.94	13.47	93	196	Off Idle	66.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.84	14.91	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:25:9	34.08	2492	1.95	13.48	93	196	Off Idle	67.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.87	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:0	34.08	2495	1.95	13.46	93	196	Off Idle	67.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.83	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:26:0	34.08	2494	1.95	13.47	93	196	Off Idle	67.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	14.98	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:26:0	34.08	2495	1.95	13.48	93	196	Off Idle	67.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.01	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:26:0	34.08	2516	1.96	13.47	93	196	Off Idle	67.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.04	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:26:0	34.08	2516	1.96	13.48	93	196	Off Idle	67.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:26:0	34.08	2503	1.97	13.46	93	196	Off Idle	67.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:26:1	34.08	2503	1.97	13.46	93	196	Off Idle	67.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	15.06	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:26:1	34.08	2501	1.98	13.46	93	196	Off Idle	67.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.49	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:26:1	34.08	2501	1.98	13.47	93	196	Off Idle	67.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.44	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:26:1	34.08	2498	1.99	13.47	93	196	Off Idle	67.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.41	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:26:1	34.08	2497	2	13.49	93	196	Off Idle	67.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.33	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:26:1	34.08	2497	2.01	13.47	93	196	Off Idle	67.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.3	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:26:1	34.08	2497	2.02	13.48	93	196	Off Idle	66.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.24	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:26:2	34.08	2500	2.02	13.48	93	196	Off Idle	66.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.17	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:26:2	34.08	2506	2.03	13.48	93	196	Off Idle	66.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.11	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:26:2	34.08	2509	2.04	13.47	93	196	Off Idle	66.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.07	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:26:2	34.08	2509	2.05	13.48	93	196	Off Idle	66.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.02	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:26:2	34.08	2512	2.06	13.47	93	196	Off Idle	66.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:2	34.08	2509	2.07	13.46	94	196	Off Idle	66.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.96	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:3	34.08	2509	2.08	13.47	94	196	Off Idle	66.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.92	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:26:3	34.08	2506	2.09	13.48	94	196	Off Idle	66	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.89	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:26:3	34.08	2504	2.09	13.46	93	196	Off Idle	65.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.86	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:26:3	34.08	2504	2.1	13.48	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.42	Lean	1	14.7	-6.82	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:26:3	34.08	2502	2.11	13.48	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-6.79	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:3	34.08	2496	2.11	13.47	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.74	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:4	34.08	2496	2.12	13.47	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.64	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:4	34.08	2498	2.13	13.48	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.6	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:4	34.08	2499	2.14	13.46	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.55	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:4	34.08	2506	2.14	13.47	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.5	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:4	34.08	2508	2.15	13.46	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.47	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:4	34.08	2513	2.15	13.47	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.41	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:4	34.08	2512	2.16	13.47	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.34	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:5	34.08	2512	2.17	13.48	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.23	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:5	34.08	2511	2.18	13.46	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.19	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:26:5	34.08	2510	2.18	13.47	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.1	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:26:5	34.08	2508	2.19	13.46	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.04	14.84	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:5	34.08	2508	2.2	13.47	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.98	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:5	34.08	2498	2.21	13.46	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.95	14.8	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:6	34.08	2507	2.22	13.46	94	196	Off Idle	65.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.84	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:6	34.08	2508	2.23	13.46	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.75	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:6	34.08	2524	2.24	13.45	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.7	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:6	34.08	2533	2.25	13.45	93	196	Off Idle	65.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.6	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:6	34.08	2535	2.25	13.46	93	196	Off Idle	65.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.57	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:6	34.08	2533	2.26	13.45	93	196	Off Idle	65.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.51	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:6	34.08	2540	2.27	13.45	93	196	Off Idle	65.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.48	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:7	34.08	2514	2.28	13.47	93	196	Off Idle	65	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.42	14.85	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:7	34.08	2507	2.29	13.45	93	196	Off Idle	65	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.4	14.87	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:7	34.08	2507	2.29	13.46	93	195	Off Idle	65	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5.31	14.9	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:7	34.08	2496	2.3	13.45	93	195	Off Idle	65	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.3	14.94	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:26:7	32.72	2482	2.31	13.45	93	195	Off Idle	65	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.28	14.96	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:7	32.72	2511	2.31	13.46	93	195	Off Idle	65	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.27	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:8	32.72	2513	2.31	13.47	93	195	Off Idle	65	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.26	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:8	32.72	2524	2.31	13.46	93	195	Off Idle	65	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.27	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:8	32.72	2531	2.32	13.46	93	196	Off Idle	65	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.24	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:8	32.72	2531	2.32	13.46	93	196	Off Idle	65	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.24	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:8	32.72	2524	2.32	13.45	93	196	Off Idle	65	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.23	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:26:8	32.72	2516	2.32	13.47	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.26	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:26:9	32.72	2514	2.32	13.46	94	196	Off Idle	64.9	0	2	132	944 Turbo	0.75	Rich	1	14.7	-5.26	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:26:9	32.72	2514	2.33	13.46	94	195	Off Idle	64.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.24	15.02	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:26:9	32.72	2511	2.33	13.47	93	195	Off Idle	65	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.22	14.97	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:26:9	32.72	2510	2.33	13.49	93	195	Off Idle	65.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.24	14.92	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:26:9	32.72	2510	2.33	13.47	93	196	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.24	14.87	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:9	32.72	2519	2.33	13.47	93	196	Off Idle	65.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.21	14.83	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:26:9	32.72	2523	2.33	13.46	93	196	Off Idle	64.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.19	14.79	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:0	32.72	2524	2.33	13.46	93	196	Off Idle	64.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.19	14.75	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:0	32.72	2528	2.33	13.47	93	196	Off Idle	64.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.16	14.71	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:0	32.72	2528	2.33	13.46	93	196	Off Idle	64.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.16	14.71	1	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:0	32.72	2528	2.33	13.46	93	196	Off Idle	64.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.14	14.69	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:0	32.72	2526	2.33	13.48	93	196	Off Idle	64.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.15	14.69	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:0	32.72	2520	2.33	13.47	93	196	Off Idle	64.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.18	14.7	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:1	32.72	2519	2.33	13.47	93	195	Off Idle	64.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.19	14.73	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:1	32.72	2520	2.33	13.47	93	195	Off Idle	64.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.18	14.78	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:1	32.72	2521	2.33	13.47	93	195	Off Idle	64.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.18	14.83	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:1	32.72	2522	2.33	13.46	93	195	Off Idle	64.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.17	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:1	32.72	2527	2.33	13.47	93	195	Off Idle	64.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.15	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:1	32.72	2527	2.33	13.47	93	195	Off Idle	64.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.17	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:1	32.72	2529	2.33	13.46	93	195	Off Idle	64.6	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.19	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:2	32.72	2531	2.33	13.46	93	195	Off Idle	64.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.19	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:27:2	32.72	2530	2.33	13.47	93	196	Off Idle	64.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.24	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:2	32.72	2520	2.34	13.46	93	196	Off Idle	64.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.24	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:2	32.72	2534	2.34	13.47	93	196	Off Idle	64.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.23	15.08	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:2	32.72	2537	2.34	13.48	93	195	Off Idle	64.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.18	15.05	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:27:2	32.72	2537	2.34	13.46	93	195	Off Idle	64.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.19	15.01	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:27:3	32.72	2540	2.34	13.46	93	195	Off Idle	64.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	-5.14	14.95	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:27:3	32.72	2548	2.34	13.46	93	195	Off Idle	64.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-5.15	14.91	1.02	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:27:3	32.72	2539	2.34	13.46	93	195	Off Idle	64.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.17	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:3	32.72	2540	2.34	13.46	93	195	Off Idle	64.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.19	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:3	32.72	2534	2.34	13.47	93	195	Off Idle	64.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.18	14.79	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:3	32.72	2533	2.34	13.46	93	195	Off Idle	64	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.19	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:4	32.72	2533	2.34	13.46	93	195	Off Idle	64	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.19	14.75	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:4	32.72	2535	2.34	13.46	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.17	14.74	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:4	32.72	2539	2.34	13.46	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.16	14.75	1	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:4	32.72	2540	2.34	13.46	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.16	14.77	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:4	32.72	2538	2.34	13.48	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.19	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:4	32.72	2537	2.34	13.47	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.15	14.82	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:4	32.72	2539	2.34	13.48	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.19	14.86	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:5	32.72	2538	2.34	13.48	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.15	14.91	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:5	32.72	2528	2.34	13.47	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.12	14.93	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:5	32.72	2540	2.34	13.46	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.14	14.96	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:5	32.72	2540	2.35	13.47	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.09	14.98	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:5	32.72	2536	2.35	13.46	93	195	Off Idle	64.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.05	15.06	1.03	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:27:5	32.72	2547	2.35	13.46	93	195	Off Idle	63.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.05	15.08	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:6	32.72	2539	2.35	13.47	93	195	Off Idle	63.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.08	15.07	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:6	32.72	2539	2.35	13.48	93	195	Off Idle	63.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.04	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:6	32.72	2547	2.35	13.46	93	195	Off Idle	63.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.07	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:6	32.72	2543	2.35	13.47	93	195	Off Idle	63.9	0	2	132	944 Turbo	0.63	Rich	1	14.7	-5.03	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:6	32.72	2541	2.35	13.45	93	195	Off Idle	63.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.05	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:6	32.72	2541	2.35	13.46	93	195	Off Idle	63.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.05	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:6	32.72	2538	2.36	13.45	93	195	Off Idle	63.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.03	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:7	32.72	2538	2.36	13.46	93	195	Off Idle	63.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.01	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:7	32.72	2564	2.36	13.47	93	195	Off Idle	63.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.03	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:23:27:7	32.72	2564	2.36	13.47	93	195	Off Idle	63.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.03	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:23:27:7	32.72	2552	2.36	13.49	93	195	Off Idle	63.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-4.98	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:23:27:7	32.72	2554	2.36	13.47	93	196	Off Idle	63.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.98	14.83	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:23:27:7	32.72	2554	2.36	13.47	93	196	Off Idle	63.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-4.94	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:23:27:8	32.72	2540	2.37	13.48	93	196	Off Idle	63.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.96	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:8	32.72	2550	2.37	13.47	93	195	Off Idle	63.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.98	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:8	32.72	2549	2.37	13.46	93	195	Off Idle	63	0	2	132	944 Turbo	0.34	Rich	1	14.6	-4.94	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:8	32.72	2549	2.37	13.46	93	195	Off Idle	63	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.93	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:8	32.72	2550	2.37	13.48	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.99	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:8	32.72	2547	2.37	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.95	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:9	32.72	2548	2.37	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.6	Rich	1	14.7	-4.93	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:27:9	32.72	2548	2.37	13.48	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.94	15.15	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:9	32.72	2542	2.37	13.48	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.98	15.12	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:9	32.72	2546	2.37	13.48	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.97	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:9	32.72	2546	2.37	13.48	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.97	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:9	32.72	2549	2.37	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.96	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:27:9	32.72	2554	2.37	13.48	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.98	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:0	32.72	2554	2.37	13.46	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.99	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:0	32.72	2552	2.37	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.97	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:0	32.72	2551	2.37	13.46	93	195	Off Idle	63	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.04	14.8	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:0	32.72	2550	2.36	13.46	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.08	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:0	32.72	2552	2.36	13.46	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.12	14.77	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:0	32.72	2554	2.36	13.48	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.2	14.78	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:1	32.72	2554	2.34	13.47	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.39	14.77	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:1	32.72	2554	2.34	13.46	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.5	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:28:1	32.72	2566	2.33	13.47	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.63	14.8	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:28:1	32.72	2552	2.32	13.47	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.74	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:28:1	32.72	2552	2.3	13.47	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.83	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:28:1	34.08	2562	2.29	13.45	93	195	Off Idle	63	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.97	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:28:1	34.08	2550	2.27	13.46	93	195	Off Idle	63	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.13	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:28:2	34.08	2550	2.26	13.45	93	195	Off Idle	63	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.29	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:28:2	34.08	2556	2.24	13.44	93	195	Off Idle	63	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.47	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:28:2	34.08	2538	2.22	13.44	93	195	Off Idle	63	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.6	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:28:2	34.08	2557	2.2	13.46	93	195	Off Idle	63	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.75	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:28:2	34.08	2557	2.19	13.46	93	195	Off Idle	63	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.91	15	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:28:2	34.08	2554	2.17	13.48	93	195	Off Idle	63	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.01	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:3	34.08	2571	2.14	13.48	93	195	Off Idle	63	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.17	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:3	34.08	2560	2.12	13.48	93	195	Off Idle	63	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.24	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:3	34.08	2550	2.1	13.49	94	195	Off Idle	63	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.32	14.94	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:3	34.08	2549	2.09	13.47	94	195	Off Idle	63	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.41	14.9	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:28:3	34.08	2550	2.07	13.45	94	195	Off Idle	63	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.47	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:28:3	34.08	2543	2.06	13.45	94	195	Off Idle	63	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.53	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:28:4	34.08	2547	2.05	13.46	94	195	Off Idle	63	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.58	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:28:4	34.08	2547	2.03	13.45	94	195	Off Idle	63.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.66	14.78	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:4	34.08	2530	2.02	13.46	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.71	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:4	34.08	2558	2	13.46	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.75	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:4	34.08	2558	2	13.48	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.82	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:4	34.08	2560	1.99	13.49	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.92	14.8	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:4	34.08	2562	1.98	13.47	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.98	14.8	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:5	34.08	2557	1.97	13.47	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:5	34.08	2554	1.96	13.49	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.09	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:5	34.08	2544	1.95	13.48	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.16	14.9	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:5	34.08	2518	1.94	13.46	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.18	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:5	34.08	2527	1.93	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.21	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:5	34.08	2536	1.93	13.46	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.26	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:6	34.08	2535	1.92	13.45	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.29	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:6	34.08	2554	1.91	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.3	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:6	34.08	2554	1.91	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.33	15.2	1.04	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:6	35.45	2532	1.9	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.38	15.24	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:6	35.45	2540	1.89	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.41	15.26	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:6	35.45	2540	1.89	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.4	15.25	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:6	35.45	2546	1.88	13.47	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15.23	1.04	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:7	35.45	2562	1.88	13.48	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	15.23	1.04	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:7	35.45	2564	1.87	13.48	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.43	15.23	1.04	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:28:7	35.45	2570	1.87	13.48	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.44	15.2	1.04	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:7	35.45	2572	1.87	13.47	93	195	Off Idle	63	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.47	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:7	35.45	2572	1.86	13.48	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.48	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:7	35.45	2562	1.86	13.47	93	195	Off Idle	62.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.48	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:8	35.45	2554	1.86	13.47	93	195	Off Idle	62.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.49	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:8	35.45	2536	1.86	13.46	93	195	Off Idle	62.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.46	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:8	35.45	2545	1.86	13.46	94	195	Off Idle	62.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.45	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:8	35.45	2556	1.87	13.46	94	195	Off Idle	62.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.39	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:8	35.45	2559	1.87	13.46	94	195	Off Idle	62.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.35	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:8	35.45	2597	1.87	13.48	93	195	Off Idle	62.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.32	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:9	35.45	2597	1.88	13.47	93	195	Off Idle	62.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.31	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:9	35.45	2562	1.88	13.48	93	195	Off Idle	62.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.26	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:9	35.45	2562	1.89	13.48	93	195	Off Idle	62.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.24	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:9	35.45	2562	1.89	13.49	93	195	Off Idle	62.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.25	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:28:9	35.45	2562	1.9	13.48	93	195	Off Idle	62.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.19	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:9	35.45	2559	1.9	13.48	94	195	Off Idle	62.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.15	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:28:9	35.45	2558	1.91	13.47	94	195	Off Idle	63	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.1	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:0	35.45	2556	1.91	13.47	94	195	Off Idle	63.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.08	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:0	35.45	2529	1.92	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.05	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:29:0	35.45	2529	1.93	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.06	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:0	35.45	2549	1.93	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:0	35.45	2548	1.94	13.48	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:0	35.45	2528	1.94	13.47	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.98	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:1	34.08	2530	1.94	13.48	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.94	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:1	34.08	2554	1.95	13.47	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.96	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:1	34.08	2558	1.95	13.46	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.92	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:1	34.08	2560	1.96	13.46	94	195	Off Idle	63.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.91	15.03	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:1	34.08	2560	1.96	13.46	94	195	Off Idle	63.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.93	14.98	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:29:1	34.08	2558	1.96	13.47	94	195	Off Idle	63.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.94	14.96	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:29:1	35.45	2557	1.96	13.48	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.96	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:29:2	35.45	2556	1.96	13.47	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.95	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:29:2	35.45	2571	1.96	13.46	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.94	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:29:2	35.45	2550	1.96	13.47	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.98	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:29:2	35.45	2550	1.96	13.47	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.01	14.84	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:29:2	35.45	2550	1.96	13.46	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.02	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:2	35.45	2553	1.95	13.46	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.08	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:29:3	35.45	2553	1.95	13.48	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.12	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:3	35.45	2552	1.94	13.49	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.15	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:3	35.45	2554	1.94	13.48	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.21	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:3	35.45	2592	1.93	13.48	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.25	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:3	35.45	2572	1.93	13.48	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.31	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:3	35.45	2532	1.92	13.47	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.37	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:4	35.45	2550	1.92	13.48	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.4	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:4	35.45	2550	1.91	13.47	94	195	Off Idle	63.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.43	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:4	35.45	2552	1.9	13.47	94	195	Off Idle	63.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.48	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:4	35.45	2574	1.9	13.46	94	195	Off Idle	63.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.5	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:4	35.45	2553	1.89	13.48	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.52	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:4	35.45	2553	1.89	13.47	93	195	Off Idle	63.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.53	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:4	35.45	2550	1.88	13.47	93	195	Off Idle	63	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.54	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:5	35.45	2550	1.87	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.54	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:5	35.45	2550	1.87	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.67	Lean	1	14.6	-8.58	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:5	35.45	2549	1.86	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.63	Lean	1	14.6	-8.57	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:5	35.45	2548	1.86	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.57	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:5	35.45	2549	1.85	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.56	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:5	35.45	2524	1.85	13.47	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.58	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:6	35.45	2539	1.85	13.46	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.59	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:6	35.45	2540	1.85	13.45	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.61	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:6	35.45	2544	1.85	13.46	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.6	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:6	35.45	2551	1.85	13.46	93	195	Off Idle	62.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.6	14.77	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:6	35.45	2551	1.85	13.46	93	195	Off Idle	63	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.56	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:6	35.45	2558	1.85	13.46	93	195	Off Idle	63	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.55	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:6	35.45	2561	1.85	13.47	93	195	Off Idle	63	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.57	14.77	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:7	35.45	2561	1.85	13.47	93	195	Off Idle	63	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.62	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:7	35.45	2553	1.85	13.46	93	195	Off Idle	63	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.66	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:7	35.45	2551	1.84	13.47	93	195	Off Idle	63	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.69	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:7	35.45	2512	1.84	13.48	93	195	Off Idle	63	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.72	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:29:7	35.45	2512	1.84	13.48	93	195	Off Idle	63	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.78	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:7	35.45	2552	1.83	13.47	93	195	Off Idle	63	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.83	14.75	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:8	35.45	2553	1.83	13.47	93	195	Off Idle	63	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.86	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:8	35.45	2552	1.82	13.49	94	195	Off Idle	62.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.93	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:29:8	35.45	2561	1.81	13.48	94	195	Off Idle	62.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.01	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:29:8	35.45	2552	1.8	13.49	94	195	Off Idle	62.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.06	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:29:8	35.45	2550	1.79	13.48	93	195	Off Idle	62.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.12	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:29:8	35.45	2550	1.79	13.48	93	195	Off Idle	62.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.19	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:29:9	35.45	2567	1.78	13.48	93	195	Off Idle	62.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.23	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:29:9	35.45	2539	1.77	13.49	93	195	Off Idle	62.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.31	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:29:9	35.45	2539	1.76	13.47	93	195	Off Idle	62.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.38	14.9	1.01	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:29:9	35.45	2540	1.73	13.47	93	195	Off Idle	63.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.5	15.04	1.02	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:29:9	35.45	2510	1.71	13.46	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.58	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:29:9	35.45	2537	1.69	13.46	93	195	Off Idle	63.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.69	14.96	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:29:9	35.45	2538	1.67	13.46	93	195	Full Load	63.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.8	14.94	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:30:0	35.45	2536	1.66	13.46	93	195	Idle	63.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.87	14.92	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:30:0	35.45	2532	1.62	13.47	93	195	Idle	63.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.01	14.87	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:0	35.45	2533	1.59	13.48	93	195	Idle	63.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.1	14.83	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:30:0	35.45	2543	1.57	13.48	94	195	Idle	63.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.19	14.77	1.01	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:30:0	35.45	2512	1.54	13.48	94	195	Idle	63.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.3	14.73	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:30:0	35.45	2486	1.52	13.48	93	195	Idle	64	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.38	14.72	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:1	35.45	2486	1.5	13.48	93	195	Idle	64.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.42	14.7	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:1	32.72	2439	1.48	13.47	93	195	Idle	64.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.45	14.7	1	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:1	32.72	2403	1.46	13.48	93	195	Idle	64.7	0	2	132	944 Turbo	0.68	Lean	1	14.6	-10.47	14.71	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:1	27.27	2425	1.44	13.48	93	195	Idle	64.7	0	2	132	944 Turbo	0.63	Lean	1	14.6	-10.51	14.69	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:1	27.27	2466	1.43	13.47	93	195	Idle	64.8	0	2	132	944 Turbo	0.57	Lean	1	14.6	-10.53	14.7	1	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:1	21.81	2491	1.41	13.47	93	195	Idle	64.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-10.55	14.72	1	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:1	19.09	2520	1.38	13.47	93	195	Idle	64.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-10.58	14.74	1	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:2	19.09	2561	1.37	13.47	93	195	Idle	64.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.6	14.75	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:2	19.09	2588	1.36	13.48	93	195	Idle	64.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-10.63	14.76	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:2	19.09	2562	1.35	13.48	93	195	Idle	64.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.66	14.78	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:2	19.09	2534	1.33	13.48	93	195	Idle	64.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.67	14.79	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:2	19.09	2538	1.33	13.49	94	195	Idle	63.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.66	14.8	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:2	19.09	2536	1.33	13.48	94	195	Idle	63.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.63	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:3	19.09	2512	1.33	13.48	94	195	Idle	63.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.6	14.84	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:3	19.09	2508	1.33	13.48	94	195	Idle	63.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.57	14.84	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:3	19.09	2480	1.34	13.48	94	195	Idle	63.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.51	14.83	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:3	19.09	2497	1.34	13.47	94	195	Idle	63.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.46	14.84	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:3	19.09	2498	1.34	13.48	93	195	Idle	63	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.43	14.84	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:3	19.09	2500	1.33	13.49	93	195	Idle	62.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.42	14.77	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:4	19.09	2513	1.34	13.47	93	195	Idle	62.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.4	14.77	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:4	19.09	2522	1.34	13.47	93	195	Idle	62.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.42	14.76	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:4	19.09	2539	1.34	13.48	93	195	Idle	62.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.4	14.74	1	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:4	19.09	2550	1.35	13.47	93	195	Idle	62	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	14.75	1	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:4	19.09	2541	1.35	13.48	93	195	Idle	62.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	14.78	1.01	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:4	19.09	2534	1.35	13.49	93	195	Idle	62.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	14.82	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:4	19.09	2534	1.36	13.48	93	195	Idle	62.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.34	14.87	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:5	19.09	2522	1.36	13.49	93	195	Idle	62.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.34	14.93	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:5	19.09	2507	1.36	13.49	93	195	Idle	62.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	15.08	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:5	19.09	2507	1.36	13.49	93	195	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	15.18	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:5	19.09	2500	1.36	13.49	93	195	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	15.39	1.05	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:5	19.09	2507	1.36	13.49	93	195	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	15.55	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:5	19.09	2507	1.36	13.49	93	195	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	15.64	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:6	19.09	2501	1.36	13.48	93	195	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	15.96	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:6	19.09	2508	1.36	13.48	93	195	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	16.23	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:6	19.09	2528	1.36	13.47	94	195	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	16.55	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:6	19.09	2527	1.35	13.47	94	195	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	16.97	1.16	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:6	19.09	2527	1.35	13.47	94	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	17.42	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:6	19.09	2527	1.35	13.48	93	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	17.86	1.22	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:6	19.09	2522	1.35	13.48	93	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	18.49	1.26	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:7	19.09	2522	1.35	13.47	93	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	18.89	1.29	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:7	19.09	2512	1.35	13.48	94	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	19.08	1.3	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:7	19.09	2509	1.35	13.49	94	195	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	19.43	1.32	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:7	19.09	2501	1.35	13.49	93	195	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	19.86	1.35	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:7	19.09	2493	1.35	13.48	93	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.06	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:7	19.09	2489	1.34	13.48	93	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.18	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:8	19.09	2488	1.34	13.48	93	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:8	19.09	2482	1.34	13.47	93	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:8	19.09	2491	1.34	13.46	93	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:30:8	19.09	2494	1.34	13.46	93	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:8	19.09	2502	1.34	13.46	93	195	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:8	19.09	2506	1.34	13.46	93	195	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:9	19.09	2507	1.34	13.47	93	195	Idle	64	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:9	19.09	2507	1.34	13.47	93	195	Idle	64.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:9	19.09	2510	1.34	13.48	93	195	Idle	64.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:9	19.09	2504	1.34	13.47	93	195	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:9	19.09	2504	1.34	13.47	93	195	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:9	19.09	2510	1.34	13.49	93	195	Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:30:9	19.09	2496	1.34	13.47	93	195	Full Load	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:0	19.09	2491	1.34	13.47	93	195	Off Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:0	19.09	2490	1.34	13.48	93	195	Off Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:0	9.54	2364	1.34	13.49	93	195	Off Idle	64.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:31:0	9.54	2509	1.34	13.49	93	195	Off Idle	64.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:31:0	12.27	2513	1.35	13.48	93	195	Off Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:31:0	14.99	2512	1.35	13.48	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:31:1	17.72	2506	1.35	13.48	93	195	Off Idle	65.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:1	17.72	2516	1.35	13.48	93	195	Off Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:1	20.45	2518	1.36	13.47	93	195	Off Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:1	20.45	2518	1.36	13.48	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.25	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:1	23.18	2520	1.37	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:1	25.9	2520	1.37	13.48	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:1	25.9	2520	1.38	13.48	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:2	28.63	2516	1.39	13.48	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.24	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:31:2	31.36	2511	1.4	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:31:2	34.08	2508	1.41	13.48	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:31:2	34.08	2516	1.43	13.49	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:31:2	35.45	2491	1.44	13.48	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:31:2	35.45	2501	1.45	13.47	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:31:3	35.45	2492	1.47	13.46	93	195	Off Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:31:3	35.45	2502	1.48	13.46	93	195	Off Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:31:3	35.45	2504	1.5	13.46	93	195	Off Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:31:3	35.45	2504	1.52	13.46	93	195	Off Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:31:3	35.45	2501	1.53	13.47	93	195	Off Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:31:3	35.45	2502	1.55	13.48	93	195	Off Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:31:4	35.45	2500	1.57	13.49	93	195	Off Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:31:4	35.45	2492	1.58	13.5	93	195	Off Idle	66.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.6	20.23	1.38	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:31:4	35.45	2492	1.6	13.48	93	195	Off Idle	66.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:31:4	35.45	2506	1.61	13.48	93	195	Off Idle	66.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.56	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:31:4	35.45	2492	1.63	13.47	93	195	Off Idle	66.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.53	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:31:4	35.45	2489	1.64	13.48	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.47	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:31:4	35.45	2476	1.65	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.45	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:31:5	35.45	2486	1.67	13.47	93	195	Off Idle	66.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.37	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:31:5	35.45	2488	1.68	13.47	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.26	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:31:5	35.45	2490	1.69	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.21	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:31:5	35.45	2490	1.71	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.13	20.24	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:31:5	35.45	2490	1.72	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.06	20.24	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:31:5	35.45	2493	1.73	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.96	20.26	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:31:6	35.45	2498	1.74	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.89	20.21	1.38	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:31:6	35.45	2500	1.76	13.48	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.81	20.1	1.37	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:31:6	35.45	2500	1.77	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.73	20.01	1.36	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:31:6	35.45	2515	1.78	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.59	19.81	1.35	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:31:6	35.45	2506	1.8	13.46	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.5	19.55	1.33	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:31:6	35.45	2506	1.81	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.4	19.29	1.31	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:31:6	35.45	2487	1.83	13.45	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	18.99	1.29	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:31:7	35.45	2489	1.85	13.47	93	195	Off Idle	66.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.19	18.66	1.27	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:31:7	35.45	2488	1.87	13.46	94	195	Off Idle	66	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.04	18.31	1.25	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:31:7	35.45	2480	1.88	13.46	94	195	Off Idle	65.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.94	17.73	1.21	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:31:7	35.45	2478	1.9	13.48	94	195	Off Idle	65.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.82	17.36	1.18	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:7	35.45	2478	1.92	13.48	93	195	Off Idle	66	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.75	17.06	1.16	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:7	35.45	2484	1.93	13.47	93	195	Off Idle	66.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.69	16.83	1.15	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:31:8	35.45	2492	1.95	13.46	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.59	16.63	1.13	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:31:8	35.45	2492	1.97	13.46	93	195	Off Idle	66.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.44	16.44	1.12	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:31:8	34.08	2488	1.98	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.37	16.2	1.1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:31:8	34.08	2499	1.99	13.45	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.3	16.08	1.1	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:31:8	34.08	2499	2.01	13.45	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.31	16.03	1.09	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:31:8	34.08	2499	2.02	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.27	15.93	1.09	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:31:9	34.08	2494	2.03	13.47	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.25	15.83	1.08	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:31:9	34.08	2492	2.04	13.48	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.22	15.8	1.08	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:31:9	34.08	2487	2.04	13.47	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.21	15.74	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:31:9	34.08	2487	2.05	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.16	15.68	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:31:9	34.08	2488	2.06	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.11	15.61	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:31:9	34.08	2488	2.06	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.09	15.57	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:23:31:9	34.08	2486	2.07	13.47	94	195	Off Idle	66.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.06	15.55	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:0	34.08	2484	2.07	13.48	94	195	Off Idle	66.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.05	15.52	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:0	34.08	2486	2.07	13.45	94	195	Off Idle	66.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.06	15.5	1.06	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:0	34.08	2491	2.07	13.45	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.02	15.48	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:0	34.08	2492	2.08	13.45	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7	15.45	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:0	34.08	2490	2.08	13.46	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.99	15.4	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:0	34.08	2490	2.08	13.45	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.98	15.36	1.05	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:1	34.08	2490	2.08	13.45	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.96	15.32	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:1	34.08	2489	2.08	13.46	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.93	15.28	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:1	34.08	2487	2.09	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.88	15.24	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:1	34.08	2487	2.09	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.87	15.22	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:1	34.08	2490	2.09	13.45	93	195	Off Idle	66.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.82	15.19	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:1	34.08	2488	2.1	13.46	93	195	Off Idle	66.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.78	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:32:1	34.08	2470	2.1	13.46	93	195	Off Idle	67.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.7	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:2	34.08	2482	2.11	13.48	93	195	Off Idle	67.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.68	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:2	34.08	2498	2.11	13.46	93	195	Off Idle	67.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.64	15.01	1.02	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:2	34.08	2504	2.12	13.47	93	195	Off Idle	67.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.59	14.99	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:2	34.08	2506	2.12	13.47	93	195	Off Idle	67.1	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.58	14.97	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:2	34.08	2512	2.12	13.46	93	195	Off Idle	66.9	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.61	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:2	34.08	2496	2.13	13.47	93	195	Off Idle	66.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.58	14.9	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:3	34.08	2494	2.13	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.57	14.9	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:3	34.08	2488	2.14	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.55	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:3	34.08	2489	2.14	13.46	93	195	Off Idle	66.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.52	14.97	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:3	34.08	2488	2.14	13.49	93	195	Off Idle	66.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.52	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:3	34.08	2488	2.15	13.47	94	195	Off Idle	66.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.5	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:3	34.08	2492	2.15	13.49	94	195	Off Idle	66.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.47	15.16	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:4	34.08	2493	2.16	13.49	93	195	Off Idle	66.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.47	15.21	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:4	34.08	2493	2.16	13.49	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.49	15.28	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:4	34.08	2496	2.16	13.48	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.47	15.33	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:4	34.08	2496	2.16	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.47	15.35	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:4	34.08	2494	2.17	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.44	15.35	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:4	34.08	2488	2.17	13.47	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.44	15.35	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:4	34.08	2498	2.17	13.46	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.42	15.36	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:5	34.08	2497	2.17	13.45	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.41	15.3	1.04	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:5	34.08	2498	2.17	13.46	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.38	15.27	1.04	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:5	34.08	2498	2.17	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-6.41	15.21	1.04	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:5	34.08	2495	2.17	13.46	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.43	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:5	34.08	2494	2.17	13.45	93	195	Off Idle	66.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.39	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:5	34.08	2492	2.17	13.46	93	194	Off Idle	66.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.38	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:6	34.08	2491	2.17	13.47	93	194	Off Idle	66.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.4	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:6	34.08	2491	2.17	13.46	93	194	Off Idle	66.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.39	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:6	34.08	2496	2.17	13.47	94	195	Off Idle	66.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.37	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:6	34.08	2497	2.17	13.46	94	195	Off Idle	66.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.4	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:32:6	34.08	2501	2.17	13.46	93	195	Off Idle	66.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.42	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:6	34.08	2502	2.17	13.45	93	195	Off Idle	66.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.43	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:6	34.08	2502	2.17	13.46	93	195	Off Idle	66.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.39	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:7	34.08	2504	2.17	13.46	93	195	Off Idle	66.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.37	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:7	34.08	2506	2.17	13.47	93	195	Off Idle	66.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.38	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:7	34.08	2507	2.17	13.47	93	195	Off Idle	66.5	0	2	132	944 Turbo	0.15	Rich	1	14.6	-6.33	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:7	34.08	2500	2.17	13.47	94	195	Off Idle	66.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.33	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:7	34.08	2506	2.17	13.46	94	195	Off Idle	66.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.35	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:7	34.08	2504	2.17	13.46	94	195	Off Idle	66.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.36	14.9	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:8	34.08	2501	2.17	13.46	93	195	Off Idle	66.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.33	14.94	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:8	34.08	2502	2.18	13.47	93	195	Off Idle	66.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.32	15.03	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:32:8	34.08	2501	2.18	13.48	93	195	Off Idle	66	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.33	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:8	34.08	2501	2.18	13.46	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.29	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:8	34.08	2504	2.18	13.46	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.29	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:8	34.08	2488	2.18	13.48	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.26	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:9	34.08	2488	2.18	13.47	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.29	15.18	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:9	34.08	2506	2.18	13.46	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.28	15.19	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:9	34.08	2506	2.18	13.46	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.3	15.18	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:9	34.08	2504	2.18	13.48	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.3	15.19	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:9	34.08	2500	2.19	13.46	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.27	15.18	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:9	34.08	2499	2.19	13.47	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.3	15.15	1.03	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:32:9	34.08	2500	2.19	13.46	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.23	15.12	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:0	34.08	2504	2.19	13.48	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.18	15.09	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:0	34.08	2509	2.19	13.47	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.14	15.07	1.03	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:0	34.08	2510	2.2	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.46	Rich	1	14.7	-6.12	15.04	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:0	34.08	2516	2.2	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.4	Rich	1	14.7	-6.04	15.01	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:0	34.08	2517	2.2	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.01	14.97	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:0	34.08	2521	2.21	13.46	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.02	14.92	1.02	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:1	34.08	2521	2.21	13.46	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.98	14.88	1.01	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:1	34.08	2517	2.21	13.45	94	194	Off Idle	65.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.99	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:1	34.08	2517	2.21	13.46	94	194	Off Idle	65.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.97	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:1	34.08	2517	2.21	13.45	94	194	Off Idle	65.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.01	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:1	34.08	2513	2.22	13.47	93	194	Off Idle	65.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.99	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:1	34.08	2509	2.22	13.47	93	194	Off Idle	65.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.96	14.93	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:1	34.08	2509	2.22	13.47	93	194	Off Idle	65.6	0	2	132	944 Turbo	0.29	Lean	1	14.7	-5.96	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:2	34.08	2508	2.22	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.93	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:2	34.08	2509	2.23	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.96	15.05	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:2	34.08	2493	2.23	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.97	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:2	34.08	2502	2.23	13.46	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.53	Rich	1	14.7	-6	15.09	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:2	34.08	2510	2.23	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.99	15.12	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:2	34.08	2512	2.23	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.99	15.13	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:3	34.08	2512	2.23	13.48	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.97	15.1	1.03	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:3	34.08	2509	2.23	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-5.95	15.05	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:3	34.08	2505	2.23	13.46	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.91	15.03	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:3	34.08	2507	2.23	13.46	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-5.88	14.98	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:3	34.08	2507	2.23	13.47	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.91	14.94	1.02	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:3	34.08	2519	2.23	13.45	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.91	14.9	1.01	3.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:4	34.08	2519	2.23	13.45	94	195	Off Idle	65.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.91	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:4	34.08	2511	2.23	13.47	94	195	Off Idle	65.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.93	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:33:4	34.08	2514	2.23	13.47	94	195	Off Idle	65.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:33:4	34.08	2517	2.23	13.47	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:33:4	34.08	2519	2.23	13.47	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.03	14.79	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:4	34.08	2528	2.22	13.47	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.08	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:4	34.08	2530	2.22	13.47	93	195	Off Idle	65.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.12	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:5	34.08	2535	2.22	13.47	93	195	Off Idle	65.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.2	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:5	34.08	2535	2.21	13.46	94	195	Off Idle	65.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.23	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:5	34.08	2530	2.21	13.46	94	195	Off Idle	65	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.3	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:5	34.08	2522	2.21	13.48	94	195	Off Idle	65	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.36	14.88	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:33:5	34.08	2517	2.2	13.47	93	194	Off Idle	65	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.44	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:33:5	34.08	2517	2.19	13.48	93	194	Off Idle	65	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.49	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:23:33:6	34.08	2515	2.18	13.47	93	195	Off Idle	65	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.63	14.94	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:33:6	34.08	2517	2.17	13.46	93	195	Off Idle	65	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.72	14.96	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:33:6	34.08	2516	2.15	13.46	93	195	Off Idle	65	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.82	14.99	1.02	3.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:23:33:6	34.08	2514	2.14	13.46	93	194	Off Idle	65	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.96	15.03	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:33:6	34.08	2510	2.12	13.45	93	194	Off Idle	65	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.06	15.05	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:6	34.08	2517	2.11	13.45	93	194	Off Idle	65	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.17	15.07	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:6	34.08	2504	2.1	13.47	93	195	Off Idle	65	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.29	15.09	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:7	34.08	2485	2.07	13.46	93	195	Off Idle	65.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.45	15.08	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:7	34.08	2498	2.06	13.47	93	195	Off Idle	65.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:33:7	34.08	2500	2.05	13.47	93	195	Off Idle	65.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.1	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:33:7	34.08	2504	2.03	13.47	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.08	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:33:7	34.08	2509	2.01	13.48	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.89	15.05	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:33:7	34.08	2512	1.99	13.48	94	194	Off Idle	65.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.99	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:33:8	34.08	2520	1.97	13.47	94	194	Off Idle	65.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.11	14.98	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:33:8	34.08	2524	1.95	13.47	94	194	Off Idle	65.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.21	14.93	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:33:8	34.08	2519	1.93	13.48	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.31	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:33:8	34.08	2519	1.91	13.47	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.38	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:33:8	34.08	2515	1.9	13.47	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.44	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:33:8	34.08	2494	1.88	13.48	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.56	14.72	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:33:9	34.08	2511	1.86	13.48	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.64	14.69	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:33:9	35.45	2518	1.85	13.46	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.73	14.68	1	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:33:9	35.45	2504	1.83	13.48	93	195	Off Idle	65.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.79	14.67	1	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:33:9	35.45	2529	1.82	13.48	93	195	Off Idle	65.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.86	14.67	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:33:9	35.45	2519	1.81	13.48	93	195	Off Idle	65.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.9	14.69	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:33:9	35.45	2508	1.8	13.47	93	195	Off Idle	65.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.96	14.7	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:33:9	35.45	2513	1.79	13.47	93	195	Off Idle	65.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.01	14.71	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:0	35.45	2513	1.78	13.47	93	195	Off Idle	65.3	0	2	132	944 Turbo	0.14	Rich	1	14.6	-9.04	14.74	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:0	35.45	2516	1.77	13.46	93	194	Off Idle	65.3	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.03	14.76	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:0	35.45	2520	1.76	13.46	93	194	Off Idle	65.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.04	14.81	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:0	35.45	2520	1.75	13.47	93	194	Off Idle	65.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.09	14.84	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:0	35.45	2519	1.75	13.47	93	195	Off Idle	65.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.13	14.87	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:0	35.45	2520	1.75	13.47	93	195	Off Idle	65.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.16	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:1	35.45	2520	1.74	13.48	93	195	Off Idle	65.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.2	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:1	35.45	2521	1.73	13.47	93	195	Off Idle	65.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.23	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:1	35.45	2522	1.73	13.48	93	195	Off Idle	65.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.24	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:1	35.45	2510	1.72	13.49	93	195	Off Idle	65	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.25	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:1	35.45	2510	1.72	13.48	93	195	Off Idle	65	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.25	15.06	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:1	35.45	2504	1.71	13.47	93	195	Off Idle	65.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.27	15.06	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:1	35.45	2501	1.71	13.47	93	194	Off Idle	65.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.25	15.06	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:2	35.45	2510	1.71	13.47	93	194	Off Idle	65.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.23	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:2	35.45	2502	1.71	13.48	93	194	Off Idle	65.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.22	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:2	35.45	2505	1.72	13.48	93	194	Off Idle	65.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.24	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:2	35.45	2506	1.72	13.47	93	194	Off Idle	65.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.21	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:2	35.45	2500	1.71	13.46	93	194	Off Idle	65.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.21	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:2	35.45	2514	1.71	13.46	93	194	Off Idle	65.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.21	15.01	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:3	35.45	2516	1.71	13.47	93	194	Off Idle	65.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.21	14.99	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:3	35.45	2516	1.71	13.46	93	194	Off Idle	65.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.24	14.99	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:3	35.45	2545	1.71	13.46	93	195	Off Idle	65.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.22	14.99	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:3	35.45	2526	1.71	13.47	93	195	Off Idle	65.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.24	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:3	35.45	2526	1.71	13.48	93	195	Off Idle	65.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.26	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:3	35.45	2524	1.71	13.49	93	195	Off Idle	65.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.28	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:4	35.45	2494	1.71	13.47	94	195	Off Idle	65.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.29	14.9	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:4	35.45	2506	1.72	13.47	94	195	Off Idle	65.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.33	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:4	35.45	2503	1.72	13.46	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.33	14.85	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:4	35.45	2496	1.72	13.47	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.32	14.86	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:23:34:4	35.45	2514	1.72	13.47	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.33	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:34:4	35.45	2514	1.72	13.48	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.31	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:4	35.45	2492	1.72	13.47	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.28	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:5	35.45	2491	1.72	13.46	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.3	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:5	35.45	2491	1.71	13.47	93	195	Off Idle	65.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.32	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:5	35.45	2485	1.71	13.48	93	195	Off Idle	65.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.31	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:5	35.45	2501	1.7	13.47	93	195	Off Idle	66	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.39	14.92	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:34:5	35.45	2500	1.68	13.48	93	194	Off Idle	66	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.48	14.95	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:34:5	35.45	2500	1.67	13.49	93	194	Off Idle	66	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.57	15	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:34:6	35.45	2503	1.64	13.49	93	194	Full Load	66	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.71	15.01	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:34:6	35.45	2501	1.62	13.49	93	194	Idle	66	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.88	15.01	1.02	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:6	35.45	2510	1.6	13.49	93	194	Idle	66	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.98	15	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:34:6	35.45	2500	1.58	13.49	93	194	Idle	66	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.08	14.96	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:34:6	35.45	2497	1.55	13.48	93	194	Idle	66	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.19	14.94	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:34:6	35.45	2497	1.53	13.49	93	194	Idle	66.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.29	14.95	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:34:6	35.45	2480	1.5	13.48	93	194	Idle	66	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.36	14.95	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:34:7	35.45	2474	1.47	13.48	93	194	Idle	66.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.43	14.93	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:7	35.45	2458	1.45	13.46	94	194	Idle	66.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.45	14.9	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:7	35.45	2459	1.43	13.48	94	194	Idle	66.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.47	14.82	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:7	35.45	2437	1.41	13.46	94	194	Idle	66.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.5	14.79	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:7	32.72	2437	1.39	13.47	93	194	Idle	66	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.51	14.77	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:7	27.27	2464	1.37	13.47	93	195	Idle	65.8	0	2	132	944 Turbo	0.7	Lean	1	14.6	-10.53	14.74	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:8	21.81	2474	1.35	13.48	93	195	Idle	65.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-10.56	14.75	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:8	21.81	2474	1.33	13.47	93	195	Idle	65.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-10.59	14.74	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:8	19.09	2517	1.32	13.48	93	194	Idle	65.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-10.59	14.73	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:8	19.09	2509	1.31	13.48	93	194	Idle	65.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.6	14.71	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:8	19.09	2509	1.3	13.48	93	194	Idle	65.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.62	14.7	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:8	19.09	2500	1.3	13.49	93	194	Idle	65.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.65	14.69	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:9	19.09	2482	1.3	13.48	93	194	Idle	65.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.66	14.68	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:9	19.09	2471	1.3	13.47	93	194	Idle	65.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.64	14.66	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:9	19.09	2468	1.31	13.47	93	194	Idle	65.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.63	14.66	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:9	19.09	2441	1.31	13.47	93	194	Idle	65.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.6	14.63	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:9	19.09	2462	1.31	13.46	93	194	Idle	65.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.56	14.61	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:9	19.09	2462	1.31	13.47	93	194	Idle	65.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.55	14.58	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:34:9	19.09	2471	1.31	13.49	94	194	Idle	65.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.52	14.57	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:0	19.09	2485	1.31	13.48	94	194	Idle	65.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.52	14.56	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:0	19.09	2496	1.31	13.48	94	194	Idle	65.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.51	14.57	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:0	19.09	2498	1.31	13.48	93	194	Idle	65.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.5	14.57	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:0	19.09	2503	1.31	13.47	93	194	Idle	65.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.48	14.57	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:0	19.09	2503	1.31	13.46	93	194	Idle	65.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.45	14.59	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:0	19.09	2494	1.31	13.48	93	194	Idle	65.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.45	14.57	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:1	19.09	2494	1.31	13.47	93	194	Idle	65.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.47	14.6	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:1	19.09	2495	1.31	13.47	93	194	Full Load	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	14.67	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:1	19.09	2474	1.31	13.47	93	194	Off Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	14.75	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:1	19.09	2472	1.31	13.48	93	194	Off Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	14.86	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:1	9.54	2398	1.32	13.48	93	194	Off Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.43	14.98	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:35:1	9.54	2478	1.32	13.48	94	194	Off Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	15.19	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:35:1	12.27	2477	1.32	13.48	94	194	Off Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	15.34	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:35:2	14.99	2477	1.33	13.48	93	194	Off Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	15.5	1.06	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:35:2	14.99	2481	1.33	13.48	93	194	Off Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	15.67	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:35:2	17.72	2481	1.34	13.47	93	194	Off Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	15.86	1.08	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:2	20.45	2486	1.34	13.46	93	194	Off Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	16.03	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:2	20.45	2494	1.35	13.45	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	16.31	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:2	23.18	2499	1.35	13.45	93	194	Off Idle	67.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	16.54	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:3	23.18	2500	1.36	13.46	93	194	Off Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	16.84	1.15	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:3	25.9	2500	1.36	13.46	93	194	Off Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	17.22	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:3	28.63	2502	1.37	13.46	93	194	Off Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	17.63	1.2	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:3	28.63	2504	1.38	13.47	93	194	Off Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	18.04	1.23	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:35:3	31.36	2502	1.39	13.46	93	194	Off Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	18.42	1.25	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:35:3	34.08	2515	1.4	13.44	93	194	Off Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	18.81	1.28	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:35:4	34.08	2506	1.41	13.45	94	194	Off Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	19.18	1.31	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:35:4	35.45	2479	1.41	13.45	94	194	Off Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	19.51	1.33	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:35:4	35.45	2484	1.42	13.44	94	194	Off Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	19.94	1.36	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:35:4	35.45	2481	1.43	13.47	93	194	Off Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.04	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:35:4	35.45	2481	1.43	13.48	93	194	Off Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.19	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:35:4	35.45	2470	1.44	13.48	93	194	Off Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:35:4	35.45	2461	1.45	13.47	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:35:5	35.45	2462	1.46	13.46	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:35:5	35.45	2466	1.47	13.46	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:35:5	35.45	2474	1.48	13.46	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.03	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:35:5	35.45	2484	1.49	13.45	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.96	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:35:5	35.45	2496	1.5	13.45	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.92	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:35:5	35.45	2495	1.52	13.46	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:35:6	35.45	2498	1.53	13.47	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:35:6	35.45	2496	1.54	13.47	93	194	Off Idle	67.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:35:6	35.45	2494	1.55	13.46	93	194	Off Idle	67.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.77	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:35:6	35.45	2470	1.56	13.46	93	194	Off Idle	67.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.75	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:35:6	35.45	2490	1.57	13.47	94	194	Off Idle	67.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.73	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:6	35.45	2490	1.58	13.47	94	194	Off Idle	67.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.7	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:6	35.45	2491	1.59	13.47	93	194	Off Idle	67.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:7	35.45	2490	1.61	13.48	93	194	Off Idle	67.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.63	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:7	35.45	2487	1.61	13.47	93	194	Off Idle	67.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.59	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:7	35.45	2486	1.62	13.47	93	194	Off Idle	67.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.55	20.19	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:7	35.45	2501	1.63	13.47	93	195	Off Idle	67.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.55	20.08	1.37	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:7	35.45	2484	1.64	13.47	93	195	Off Idle	67.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.56	19.91	1.36	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:7	35.45	2458	1.64	13.47	93	194	Off Idle	67.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.55	19.59	1.33	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:8	35.45	2426	1.64	13.47	93	194	Off Idle	67.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.55	19.34	1.32	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:8	35.45	2426	1.65	13.46	93	194	Off Idle	67.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.54	19.08	1.3	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:8	35.45	2444	1.65	13.48	93	194	Off Idle	67.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.52	18.79	1.28	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:8	35.45	2445	1.65	13.46	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.52	18.48	1.26	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:8	35.45	2442	1.65	13.47	93	194	Off Idle	67.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.53	18.01	1.23	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:8	35.45	2442	1.65	13.47	93	194	Off Idle	67.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.53	17.86	1.22	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:9	35.45	2447	1.65	13.48	93	194	Off Idle	68	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.48	17.45	1.19	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:9	35.45	2447	1.65	13.47	93	194	Off Idle	68.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.5	17.23	1.17	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:9	35.45	2452	1.65	13.48	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.47	17.03	1.16	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:9	35.45	2450	1.65	13.47	93	194	Off Idle	68.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.49	16.86	1.15	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:9	35.45	2458	1.65	13.49	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.49	16.71	1.14	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:9	35.45	2462	1.65	13.49	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.48	16.62	1.13	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:35:9	35.45	2480	1.65	13.49	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.48	16.31	1.11	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:0	35.45	2470	1.64	13.48	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.52	16.17	1.1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:0	35.45	2470	1.64	13.49	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.52	16.02	1.09	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:0	35.45	2474	1.64	13.49	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.54	15.91	1.08	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:36:0	35.45	2471	1.64	13.49	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.55	15.81	1.08	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:36:0	35.45	2474	1.64	13.48	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.53	15.67	1.07	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:0	35.45	2474	1.64	13.48	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.52	15.6	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:1	35.45	2472	1.64	13.47	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.5	15.5	1.06	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:36:1	35.45	2472	1.64	13.47	93	194	Off Idle	68.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.51	15.45	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:36:1	35.45	2465	1.64	13.47	94	194	Off Idle	68	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.51	15.38	1.05	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:36:1	35.45	2460	1.64	13.48	94	194	Off Idle	67.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.51	15.34	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:36:1	35.45	2452	1.64	13.48	94	194	Off Idle	67.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.52	15.31	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:1	35.45	2451	1.64	13.47	93	194	Off Idle	68	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.51	15.27	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:1	35.45	2451	1.64	13.46	93	194	Off Idle	68.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.5	15.24	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:2	35.45	2452	1.64	13.47	93	194	Off Idle	68.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.48	15.22	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:2	35.45	2452	1.64	13.47	93	194	Off Idle	68.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.5	15.18	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:2	35.45	2452	1.64	13.48	93	194	Off Idle	68.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.49	15.16	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:2	35.45	2432	1.64	13.46	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.47	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:2	35.45	2457	1.64	13.47	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.46	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:36:2	35.45	2457	1.64	13.46	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.48	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:3	35.45	2456	1.64	13.46	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.46	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:3	35.45	2461	1.64	13.47	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.49	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:3	35.45	2458	1.64	13.48	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.46	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:3	35.45	2458	1.64	13.46	93	194	Off Idle	69.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.45	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:3	35.45	2462	1.64	13.46	93	194	Off Idle	69.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.42	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:3	35.45	2483	1.64	13.47	93	194	Off Idle	69.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.45	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:4	35.45	2483	1.64	13.48	93	194	Off Idle	69	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.43	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:4	35.45	2458	1.64	13.47	93	194	Off Idle	69	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:4	35.45	2450	1.64	13.48	93	194	Off Idle	68.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:4	35.45	2428	1.64	13.48	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.46	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:4	35.45	2438	1.64	13.48	93	194	Off Idle	68.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.46	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:4	35.45	2450	1.64	13.49	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.47	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:4	35.45	2448	1.64	13.49	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.47	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:5	35.45	2448	1.64	13.48	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:5	35.45	2461	1.64	13.48	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.46	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:5	35.45	2461	1.64	13.48	93	194	Off Idle	68.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.46	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:5	35.45	2452	1.64	13.47	94	194	Off Idle	68.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.46	15.15	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:5	35.45	2456	1.64	13.47	94	194	Off Idle	68.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.46	15.17	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:5	35.45	2450	1.64	13.47	94	194	Off Idle	68.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.47	15.18	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:6	35.45	2462	1.64	13.47	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.47	15.19	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:6	35.45	2462	1.64	13.47	93	194	Off Idle	69	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.48	15.19	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:6	35.45	2456	1.64	13.47	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.48	15.2	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:6	35.45	2471	1.64	13.46	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.48	15.2	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:6	35.45	2471	1.64	13.46	93	194	Off Idle	68.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.46	15.19	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:6	35.45	2444	1.64	13.45	93	194	Off Idle	69.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.46	15.17	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:6	35.45	2440	1.64	13.46	93	194	Off Idle	69.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.44	15.15	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:7	35.45	2417	1.64	13.47	93	194	Off Idle	69.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.45	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:7	35.45	2426	1.64	13.47	93	194	Off Idle	69.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.45	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:7	35.45	2438	1.64	13.48	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.44	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:7	35.45	2439	1.64	13.46	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.46	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:7	35.45	2439	1.64	13.47	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.43	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:7	35.45	2438	1.64	13.46	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.41	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:8	35.45	2440	1.64	13.45	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.42	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:8	35.45	2438	1.64	13.45	93	194	Off Idle	69.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.44	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:8	35.45	2438	1.64	13.45	93	194	Off Idle	69.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.42	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:36:8	35.45	2445	1.63	13.46	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.45	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:36:8	35.45	2445	1.63	13.46	93	194	Off Idle	69.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.46	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:8	35.45	2446	1.63	13.47	93	194	Off Idle	69.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.45	15.01	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:9	35.45	2443	1.63	13.47	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.45	14.99	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:9	35.45	2444	1.63	13.48	93	194	Off Idle	69.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.46	14.96	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:9	35.45	2444	1.63	13.48	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.44	14.97	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:9	35.45	2446	1.63	13.49	93	194	Off Idle	69.8	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.45	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:9	35.45	2446	1.63	13.48	94	194	Off Idle	69.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.46	14.94	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:9	35.45	2464	1.63	13.47	94	194	Off Idle	69.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.46	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:36:9	35.45	2450	1.63	13.48	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.46	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:0	35.45	2449	1.63	13.48	93	194	Off Idle	69.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.47	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:0	35.45	2450	1.63	13.48	93	194	Off Idle	69.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.46	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:0	35.45	2451	1.63	13.47	93	194	Off Idle	69.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.46	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:0	35.45	2451	1.63	13.47	93	194	Off Idle	69.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.45	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:0	35.45	2449	1.63	13.46	93	194	Off Idle	69.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.46	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:0	35.45	2446	1.63	13.46	93	194	Off Idle	69	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.45	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:1	35.45	2446	1.63	13.47	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.44	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:1	35.45	2440	1.63	13.46	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.45	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:1	35.45	2440	1.63	13.47	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.46	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:1	35.45	2440	1.63	13.46	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.47	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:1	35.45	2439	1.63	13.44	93	194	Off Idle	68.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.46	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:1	35.45	2437	1.63	13.45	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.46	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:37:1	35.45	2437	1.63	13.45	93	194	Off Idle	68.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.45	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:2	35.45	2437	1.63	13.47	93	194	Off Idle	69	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.4	15.05	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:2	35.45	2438	1.63	13.47	93	194	Off Idle	69	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.41	15.06	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:2	35.45	2453	1.63	13.48	93	194	Off Idle	69	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.4	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:2	35.45	2442	1.63	13.48	93	194	Off Idle	69	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.4	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:2	35.45	2430	1.63	13.47	93	194	Off Idle	69	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.42	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:2	35.45	2437	1.64	13.46	93	194	Off Idle	69	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.44	15.05	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:3	35.45	2437	1.63	13.47	94	194	Off Idle	69.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.44	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:3	35.45	2440	1.63	13.47	94	194	Off Idle	69.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.46	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:3	35.45	2442	1.63	13.47	94	194	Off Idle	69.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.44	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:3	35.45	2446	1.63	13.48	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.45	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:3	35.45	2437	1.63	13.48	93	194	Off Idle	69.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.43	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:3	35.45	2448	1.63	13.48	93	194	Off Idle	69.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.45	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:4	35.45	2446	1.63	13.47	93	194	Off Idle	69.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.47	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:37:4	35.45	2442	1.63	13.47	93	194	Off Idle	69.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.47	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:37:4	35.45	2442	1.63	13.47	93	194	Off Idle	68.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.46	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:37:4	35.45	2440	1.63	13.47	93	194	Off Idle	69.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.48	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:37:4	35.45	2439	1.63	13.46	93	194	Off Idle	69.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.46	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:4	35.45	2440	1.63	13.46	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.45	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:4	35.45	2432	1.63	13.45	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.46	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:5	35.45	2426	1.63	13.46	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.48	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:5	35.45	2426	1.63	13.46	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.49	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:37:5	35.45	2430	1.63	13.48	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.47	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:5	35.45	2432	1.63	13.48	93	194	Off Idle	68.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.46	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:5	35.45	2433	1.63	13.48	93	194	Off Idle	68.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.43	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:5	35.45	2433	1.63	13.48	93	194	Off Idle	69	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.44	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:6	35.45	2433	1.63	13.47	93	194	Off Idle	69.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.41	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:6	35.45	2436	1.63	13.47	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.42	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:6	35.45	2437	1.63	13.46	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.45	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:6	35.45	2440	1.63	13.47	93	194	Off Idle	69.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.42	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:6	35.45	2419	1.63	13.46	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.44	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:6	35.45	2419	1.63	13.46	93	194	Off Idle	69.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.45	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:6	35.45	2429	1.63	13.46	93	194	Off Idle	69.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.45	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:7	35.45	2426	1.63	13.46	93	194	Off Idle	69.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.45	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:7	35.45	2426	1.63	13.46	93	194	Off Idle	69.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.47	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:7	35.45	2429	1.63	13.47	93	194	Off Idle	69.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.46	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:7	35.45	2416	1.63	13.46	93	194	Off Idle	69.7	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.46	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:7	35.45	2416	1.63	13.46	93	194	Off Idle	69.7	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.44	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:7	35.45	2417	1.63	13.46	93	194	Off Idle	69.7	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.43	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:8	35.45	2384	1.63	13.46	93	194	Off Idle	69.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.4	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:8	35.45	2425	1.63	13.46	93	194	Off Idle	70	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.42	14.94	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:8	35.45	2425	1.63	13.47	93	194	Off Idle	70.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.45	15	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:8	35.45	2424	1.63	13.48	94	194	Off Idle	70.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.46	15.05	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:8	35.45	2424	1.63	13.49	94	194	Off Idle	70.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.46	15.09	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:8	35.45	2444	1.62	13.48	94	194	Off Idle	70.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.46	15.12	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:9	35.45	2427	1.62	13.48	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.49	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:9	35.45	2427	1.62	13.49	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.47	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:37:9	35.45	2434	1.62	13.47	93	194	Off Idle	70.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.51	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:37:9	35.45	2436	1.62	13.47	94	194	Off Idle	70.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.51	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:37:9	35.45	2440	1.62	13.48	94	194	Off Idle	70.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.5	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:37:9	35.45	2441	1.62	13.47	94	194	Off Idle	70.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.49	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:37:9	35.45	2441	1.62	13.47	93	194	Off Idle	70.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.5	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:0	35.45	2443	1.62	13.47	93	194	Off Idle	70.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.49	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:0	35.45	2445	1.62	13.45	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.51	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:0	35.45	2446	1.62	13.46	93	194	Off Idle	70	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.52	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:0	35.45	2456	1.62	13.46	93	194	Off Idle	69.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.54	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:0	35.45	2445	1.62	13.47	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.53	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:0	35.45	2438	1.62	13.46	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.54	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:38:1	35.45	2438	1.62	13.47	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.53	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:1	35.45	2400	1.62	13.46	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.53	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:1	35.45	2433	1.62	13.46	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.52	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:1	35.45	2432	1.62	13.46	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.52	14.97	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:1	35.45	2429	1.62	13.47	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.53	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:1	35.45	2419	1.62	13.48	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.51	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:1	35.45	2415	1.62	13.48	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.51	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:2	35.45	2415	1.62	13.48	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.52	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:2	35.45	2411	1.62	13.47	93	194	Off Idle	69.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.53	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:2	35.45	2397	1.62	13.47	93	194	Off Idle	69.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.54	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:2	35.45	2397	1.62	13.46	93	194	Off Idle	70	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:2	35.45	2412	1.61	13.46	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.54	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:2	35.45	2411	1.61	13.45	93	194	Off Idle	70.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.53	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:3	35.45	2412	1.61	13.45	93	194	Off Idle	70.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.52	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:3	35.45	2416	1.61	13.46	93	194	Off Idle	70.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.55	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:3	35.45	2420	1.61	13.47	93	194	Off Idle	71.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.56	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:3	35.45	2422	1.61	13.47	93	194	Off Idle	71.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.57	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:3	35.45	2422	1.6	13.47	93	194	Off Idle	71.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.59	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:3	35.45	2420	1.6	13.47	93	194	Off Idle	71.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.58	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:4	35.45	2419	1.6	13.47	93	194	Off Idle	71.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.58	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:4	35.45	2419	1.6	13.47	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.6	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:4	35.45	2419	1.6	13.47	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.58	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:4	35.45	2399	1.59	13.47	93	194	Off Idle	71.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.59	15.16	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:4	35.45	2417	1.59	13.47	93	194	Off Idle	71.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.59	15.19	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:4	35.45	2413	1.59	13.48	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.59	15.19	1.04	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:4	35.45	2412	1.59	13.48	93	194	Off Idle	71.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.59	15.21	1.04	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:5	35.45	2415	1.59	13.47	93	194	Off Idle	71.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.63	15.21	1.04	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:5	35.45	2424	1.59	13.47	93	194	Off Idle	71.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.64	15.2	1.04	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:5	35.45	2417	1.59	13.47	93	194	Off Idle	71	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.63	15.2	1.04	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:5	35.45	2420	1.59	13.47	93	194	Off Idle	70.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.64	15.17	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:5	35.45	2405	1.59	13.47	93	194	Off Idle	70.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.61	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:6	35.45	2405	1.59	13.46	93	194	Off Idle	70.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.59	15.12	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:6	35.45	2429	1.59	13.47	93	194	Off Idle	71	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.59	15.09	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:6	35.45	2429	1.59	13.46	93	194	Off Idle	71	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.63	15.08	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:6	35.45	2428	1.59	13.48	93	194	Off Idle	70.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.6	15.06	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:6	35.45	2443	1.59	13.47	93	194	Off Idle	70.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.64	15.03	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:6	35.45	2429	1.59	13.48	93	194	Off Idle	70.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.61	15.01	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:6	35.45	2430	1.59	13.46	93	194	Off Idle	70.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.58	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:6	35.45	2430	1.59	13.46	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.57	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:7	35.45	2441	1.59	13.45	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.57	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:7	35.45	2421	1.59	13.45	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:7	35.45	2418	1.59	13.46	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.58	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:7	35.45	2408	1.59	13.46	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.57	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:7	35.45	2365	1.59	13.46	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:7	35.45	2384	1.59	13.45	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.56	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:8	35.45	2404	1.59	13.46	93	194	Off Idle	70.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.56	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:8	35.45	2405	1.59	13.46	93	194	Off Idle	70	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.54	15.13	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:8	35.45	2408	1.59	13.46	93	194	Off Idle	70	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.53	15.18	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:38:8	35.45	2418	1.59	13.46	93	194	Off Idle	70.1	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.54	15.22	1.04	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:8	35.45	2410	1.59	13.47	93	194	Off Idle	70.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.56	15.22	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:8	35.45	2410	1.59	13.47	93	194	Off Idle	70.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.56	15.23	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:9	35.45	2407	1.59	13.47	93	194	Off Idle	70.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.57	15.24	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:9	35.45	2422	1.59	13.48	93	194	Off Idle	70.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.61	15.23	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:9	35.45	2412	1.59	13.48	93	194	Off Idle	71.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.58	15.23	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:9	35.45	2404	1.59	13.47	93	194	Off Idle	71.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.59	15.2	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:9	35.45	2402	1.59	13.47	93	194	Off Idle	71.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.59	15.21	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:9	35.45	2408	1.59	13.48	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.59	15.19	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:38:9	35.45	2408	1.59	13.46	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.6	15.18	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:39:0	35.45	2406	1.59	13.46	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.61	15.15	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:0	35.45	2407	1.59	13.46	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.58	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:0	35.45	2408	1.59	13.46	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.59	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:0	35.45	2400	1.59	13.46	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.58	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:0	35.45	2410	1.59	13.45	93	194	Off Idle	71.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.6	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:0	35.45	2413	1.59	13.45	93	194	Off Idle	71.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.61	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:1	35.45	2414	1.58	13.45	94	194	Off Idle	71.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.6	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:1	35.45	2407	1.59	13.45	94	194	Off Idle	71.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.63	15.05	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:1	35.45	2418	1.58	13.46	94	194	Off Idle	71.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.62	15.04	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:1	35.45	2418	1.58	13.46	93	194	Off Idle	71.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.62	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:1	35.45	2412	1.58	13.46	93	194	Off Idle	71	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.63	15.01	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:1	35.45	2435	1.58	13.46	93	194	Off Idle	71	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.6	14.99	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:1	35.45	2415	1.58	13.46	93	194	Off Idle	70.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.6	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:2	35.45	2415	1.58	13.46	93	194	Off Idle	70.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.62	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:2	35.45	2414	1.58	13.46	93	194	Off Idle	70.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.59	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:2	35.45	2395	1.59	13.46	93	194	Off Idle	70.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:2	35.45	2403	1.59	13.46	93	194	Off Idle	70.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.57	14.87	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:2	35.45	2407	1.59	13.45	93	194	Off Idle	71.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.59	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:2	35.45	2402	1.59	13.47	93	194	Off Idle	71.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.57	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:3	35.45	2400	1.59	13.46	93	194	Off Idle	71.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.57	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:3	35.45	2417	1.59	13.47	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.57	14.87	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:3	35.45	2393	1.59	13.47	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.59	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:3	35.45	2393	1.59	13.48	93	194	Off Idle	71.2	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.58	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:3	35.45	2394	1.59	13.47	93	194	Off Idle	71.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.6	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:3	35.45	2377	1.59	13.47	93	194	Off Idle	71.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.57	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:4	35.45	2399	1.59	13.47	93	194	Off Idle	71.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.57	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:4	35.45	2401	1.59	13.46	93	194	Off Idle	71.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.57	15.05	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:4	35.45	2401	1.59	13.47	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.56	15.07	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:4	35.45	2413	1.59	13.46	93	194	Off Idle	71.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.56	15.08	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:4	35.45	2405	1.59	13.46	93	194	Off Idle	71.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.56	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:4	35.45	2405	1.58	13.46	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.57	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:4	35.45	2405	1.58	13.47	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.57	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:5	35.45	2387	1.58	13.47	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.58	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:5	35.45	2387	1.58	13.48	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.57	15.07	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:5	35.45	2406	1.58	13.48	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.6	15.09	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:5	35.45	2401	1.58	13.48	94	194	Off Idle	71.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.6	15.08	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:5	35.45	2414	1.58	13.47	94	194	Off Idle	71.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.61	15.06	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:5	35.45	2404	1.58	13.47	94	194	Off Idle	71.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.63	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:6	35.45	2392	1.58	13.48	93	194	Off Idle	72	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.63	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:6	35.45	2390	1.58	13.45	93	194	Off Idle	72	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.64	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:6	35.45	2390	1.58	13.46	93	194	Off Idle	72.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.62	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:6	35.45	2383	1.58	13.46	94	194	Off Idle	72.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.62	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:6	35.45	2380	1.58	13.46	94	194	Off Idle	72.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.59	14.96	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:6	35.45	2378	1.58	13.46	94	194	Off Idle	72.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.62	14.92	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:6	35.45	2374	1.57	13.46	93	194	Off Idle	72.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.62	14.87	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:7	35.45	2392	1.57	13.45	93	194	Off Idle	72.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.62	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:7	35.45	2382	1.57	13.45	93	194	Off Idle	72.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.62	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:39:7	35.45	2376	1.57	13.46	93	194	Off Idle	72.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.62	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:7	35.45	2379	1.57	13.47	93	194	Off Idle	72.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.6	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:7	35.45	2379	1.57	13.47	93	194	Off Idle	72.5	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.64	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:7	35.45	2386	1.56	13.48	94	194	Off Idle	72.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.62	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:8	35.45	2389	1.56	13.47	94	194	Off Idle	72.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.61	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:8	35.45	2394	1.56	13.46	94	194	Off Idle	72.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.63	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:8	35.45	2398	1.56	13.47	93	194	Off Idle	72.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.66	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:8	35.45	2406	1.56	13.47	93	194	Off Idle	72.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.66	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:8	35.45	2410	1.55	13.48	93	194	Off Idle	72.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.68	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:8	35.45	2410	1.55	13.47	94	194	Off Idle	72.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.7	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:9	35.45	2409	1.55	13.48	94	194	Off Idle	72.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.71	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:39:9	35.45	2409	1.55	13.48	94	194	Off Idle	71.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.7	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:9	35.45	2405	1.55	13.47	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.7	14.9	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:9	35.45	2406	1.55	13.47	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.15	Rich	1	14.6	-9.7	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:9	35.45	2406	1.55	13.46	94	194	Off Idle	71.2	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.69	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:9	35.45	2404	1.55	13.47	94	194	Off Idle	71	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.69	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:39:9	35.45	2404	1.55	13.47	94	194	Off Idle	71	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.69	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:0	35.45	2403	1.55	13.46	93	194	Off Idle	71	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.69	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:0	35.45	2404	1.55	13.45	93	194	Off Idle	71	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.66	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:0	35.45	2381	1.55	13.47	93	194	Off Idle	71	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.67	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:0	35.45	2390	1.55	13.47	93	194	Off Idle	71	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.67	15.18	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:0	35.45	2397	1.55	13.48	93	194	Off Idle	71.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.68	15.18	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:0	35.45	2392	1.55	13.48	93	194	Off Idle	71.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.69	15.18	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:1	35.45	2392	1.55	13.47	93	194	Off Idle	71.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.69	15.18	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:1	35.45	2400	1.55	13.46	93	194	Off Idle	71.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.71	15.17	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:1	35.45	2388	1.55	13.46	93	194	Off Idle	71.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.73	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:1	35.45	2376	1.55	13.46	93	194	Off Idle	71.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.7	15.15	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:1	35.45	2368	1.55	13.46	93	194	Off Idle	72	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.71	15.14	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:40:1	35.45	2378	1.55	13.45	93	194	Off Idle	72.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.72	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:1	35.45	2374	1.55	13.46	93	194	Off Idle	72.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.75	15.11	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:2	35.45	2375	1.54	13.45	93	194	Off Idle	72.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.73	15.1	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:2	35.45	2375	1.54	13.44	93	194	Off Idle	72.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.74	15.1	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:2	35.45	2374	1.54	13.45	93	194	Off Idle	72.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.77	15.07	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:2	35.45	2372	1.54	13.47	93	194	Off Idle	72.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.73	15.04	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:2	35.45	2373	1.54	13.46	93	194	Off Idle	72.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.73	15.02	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:2	35.45	2374	1.54	13.47	93	194	Off Idle	72.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.76	15.02	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:3	35.45	2383	1.53	13.47	93	194	Off Idle	72.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.77	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:3	35.45	2375	1.53	13.46	93	194	Off Idle	72.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.73	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:3	35.45	2373	1.53	13.46	93	194	Off Idle	72.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.74	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:3	35.45	2375	1.53	13.47	93	194	Off Idle	72.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.75	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:3	35.45	2372	1.53	13.47	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.74	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:3	35.45	2382	1.52	13.5	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.73	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:4	35.45	2386	1.52	13.5	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.72	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:40:4	35.45	2395	1.52	13.49	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.7	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:40:4	35.45	2387	1.52	13.48	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.71	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:4	35.45	2400	1.52	13.47	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.69	14.94	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:4	35.45	2400	1.52	13.47	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.72	14.98	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:4	35.45	2400	1.52	13.46	93	194	Off Idle	72.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.76	15.02	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:4	35.45	2401	1.52	13.46	93	194	Off Idle	72.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.77	15.04	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:5	35.45	2400	1.52	13.46	93	194	Off Idle	72.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.76	15.05	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:5	35.45	2398	1.52	13.46	93	194	Off Idle	72.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.77	15.06	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:5	35.45	2396	1.52	13.47	93	194	Off Idle	72.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.77	15.08	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:5	35.45	2416	1.52	13.48	93	194	Off Idle	72.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.76	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:5	35.45	2396	1.52	13.47	93	194	Off Idle	72.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.74	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:5	35.45	2394	1.52	13.48	93	194	Off Idle	72.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.74	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:6	35.45	2374	1.52	13.47	93	194	Off Idle	72.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.74	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:6	35.45	2389	1.52	13.47	93	194	Off Idle	72	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.76	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:6	35.45	2389	1.52	13.47	93	194	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.76	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:6	35.45	2378	1.52	13.47	93	194	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.73	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:6	35.45	2370	1.52	13.47	93	194	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.74	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:6	35.45	2363	1.53	13.47	93	194	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.75	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:6	35.45	2363	1.53	13.47	93	194	Off Idle	72.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.73	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:7	35.45	2364	1.53	13.47	93	194	Off Idle	72.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.74	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:7	35.45	2363	1.53	13.47	93	194	Off Idle	72.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.73	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:7	35.45	2354	1.53	13.45	93	194	Off Idle	72.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.7	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:7	35.45	2366	1.53	13.46	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.7	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:7	35.45	2365	1.53	13.46	93	194	Off Idle	73.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.69	15.01	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:7	35.45	2366	1.53	13.47	93	194	Off Idle	73.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.7	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:8	35.45	2366	1.53	13.46	93	194	Off Idle	73.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.71	14.98	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:40:8	35.45	2370	1.52	13.45	93	194	Off Idle	73.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.73	14.95	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:8	35.45	2374	1.52	13.45	93	194	Off Idle	73.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.73	14.91	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:8	35.45	2375	1.52	13.46	93	194	Off Idle	73.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.74	14.88	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:8	35.45	2387	1.52	13.45	93	194	Off Idle	73.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.74	14.86	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:8	35.45	2378	1.52	13.45	93	194	Off Idle	73.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.74	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:9	35.45	2378	1.52	13.46	93	194	Off Idle	73.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.74	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:9	35.45	2381	1.52	13.46	93	194	Off Idle	73.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.74	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:9	35.45	2380	1.52	13.46	93	194	Off Idle	73.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.73	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:9	35.45	2376	1.52	13.46	93	194	Off Idle	73.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.72	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:9	35.45	2376	1.52	13.44	93	194	Off Idle	73.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.72	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:9	35.45	2376	1.52	13.45	93	194	Off Idle	73.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.72	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:40:9	35.45	2376	1.52	13.47	93	194	Off Idle	73.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.72	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:0	35.45	2376	1.52	13.46	93	194	Off Idle	73.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.76	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:0	35.45	2379	1.52	13.48	93	194	Off Idle	73.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.78	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:0	35.45	2376	1.51	13.48	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.81	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:0	35.45	2376	1.51	13.48	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.81	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:0	35.45	2361	1.51	13.48	93	194	Off Idle	72.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.8	14.9	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:0	35.45	2366	1.51	13.48	93	194	Off Idle	72.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.78	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:1	35.45	2374	1.51	13.48	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.76	14.93	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:1	35.45	2377	1.51	13.48	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.78	14.96	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:1	35.45	2377	1.51	13.46	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.77	14.98	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:1	35.45	2375	1.51	13.46	93	194	Off Idle	72.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.75	15.01	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:1	35.45	2374	1.51	13.46	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.77	15.01	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:1	35.45	2374	1.51	13.46	94	194	Off Idle	72.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.77	14.99	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:1	35.45	2374	1.51	13.47	94	194	Off Idle	72.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.77	14.99	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:2	35.45	2393	1.51	13.48	94	194	Off Idle	72.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.78	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:2	35.45	2374	1.51	13.48	93	194	Off Idle	72.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.79	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:2	35.45	2372	1.51	13.47	93	194	Off Idle	73	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.79	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:2	35.45	2373	1.51	13.47	93	194	Off Idle	73.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.77	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:2	35.45	2372	1.51	13.46	93	194	Off Idle	73.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.8	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:2	35.45	2372	1.51	13.45	93	194	Off Idle	73.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.81	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:3	35.45	2371	1.51	13.46	93	194	Off Idle	73.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.81	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:3	35.45	2370	1.51	13.46	93	194	Off Idle	73.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.81	14.99	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:3	35.45	2370	1.51	13.47	93	194	Off Idle	73.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.82	14.98	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:3	35.45	2390	1.51	13.47	93	194	Off Idle	73.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.82	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:3	35.45	2371	1.51	13.47	93	194	Off Idle	73.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.84	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:3	35.45	2370	1.5	13.47	93	194	Off Idle	73.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.81	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:4	35.45	2370	1.5	13.47	93	194	Off Idle	73.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.84	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:4	35.45	2362	1.5	13.47	93	194	Off Idle	73.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.84	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:4	35.45	2371	1.5	13.48	93	194	Off Idle	73.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.83	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:4	35.45	2370	1.5	13.48	93	194	Off Idle	73.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.81	14.88	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:4	35.45	2366	1.5	13.47	93	194	Off Idle	73.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.84	14.88	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:4	35.45	2364	1.5	13.48	93	194	Off Idle	73.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.81	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:4	35.45	2356	1.5	13.47	93	194	Off Idle	73.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.82	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:5	35.45	2353	1.5	13.47	93	194	Off Idle	73.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.82	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:5	35.45	2367	1.5	13.46	93	194	Off Idle	73.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.82	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:5	35.45	2367	1.5	13.46	93	194	Off Idle	73.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.83	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:5	35.45	2349	1.5	13.46	93	194	Off Idle	73.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.83	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:5	35.45	2349	1.5	13.45	93	194	Off Idle	73.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.83	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:5	35.45	2350	1.5	13.45	93	194	Off Idle	73.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.86	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:6	35.45	2352	1.49	13.47	93	194	Off Idle	73.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.8	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:6	35.45	2351	1.49	13.46	93	194	Off Idle	74	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.82	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:6	35.45	2350	1.49	13.44	93	194	Off Idle	74.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.79	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:6	35.45	2360	1.49	13.46	93	194	Off Idle	74.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.77	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:6	35.45	2354	1.49	13.46	93	194	Off Idle	74.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.78	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:6	35.45	2354	1.49	13.45	93	194	Off Idle	74.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.78	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:6	35.45	2361	1.49	13.45	93	194	Off Idle	74.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.77	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:7	35.45	2353	1.49	13.45	93	194	Off Idle	74.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.78	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:41:7	35.45	2365	1.49	13.45	93	194	Off Idle	74.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.8	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:7	35.45	2382	1.49	13.46	93	194	Off Idle	74.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.82	15.05	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:7	35.45	2389	1.49	13.47	94	194	Off Idle	74.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.84	15.05	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:7	35.45	2388	1.48	13.47	94	194	Off Idle	74.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.87	15.04	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:7	35.45	2407	1.48	13.47	94	194	Off Idle	74.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.87	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:8	35.45	2384	1.48	13.47	93	194	Off Idle	74	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.86	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:8	35.45	2385	1.48	13.47	93	194	Off Idle	74	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.85	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:8	35.45	2385	1.48	13.47	93	194	Off Idle	74	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.84	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:8	35.45	2382	1.48	13.46	93	194	Off Idle	73.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.82	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:8	35.45	2376	1.48	13.47	93	194	Off Idle	73.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.84	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:8	35.45	2372	1.48	13.48	93	194	Off Idle	73.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.85	14.97	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:41:9	35.45	2358	1.48	13.47	93	194	Off Idle	73.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.86	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:9	35.45	2331	1.48	13.47	93	194	Off Idle	73.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.84	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:9	35.45	2329	1.48	13.47	93	194	Off Idle	73.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.88	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:9	35.45	2328	1.48	13.46	93	194	Off Idle	73.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.87	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:9	35.45	2328	1.49	13.46	93	194	Off Idle	73.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.86	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:9	35.45	2328	1.49	13.47	93	194	Off Idle	73.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.85	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:41:9	35.45	2328	1.49	13.44	94	194	Off Idle	74	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.84	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:0	35.45	2328	1.49	13.45	94	194	Off Idle	74.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.81	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:0	35.45	2330	1.49	13.46	94	194	Off Idle	74.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.8	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:0	35.45	2332	1.48	13.45	93	194	Off Idle	74.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.82	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:0	35.45	2337	1.48	13.45	93	194	Off Idle	74.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.81	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:0	35.45	2339	1.48	13.46	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.81	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:0	35.45	2348	1.48	13.46	93	194	Off Idle	74.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.83	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:1	35.45	2354	1.48	13.47	93	194	Off Idle	74.7	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.85	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:1	35.45	2366	1.48	13.48	93	194	Off Idle	74.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.84	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:1	35.45	2368	1.48	13.47	93	194	Off Idle	74.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.87	15.1	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:1	35.45	2371	1.48	13.46	93	194	Off Idle	74.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.87	15.09	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:1	35.45	2371	1.48	13.48	93	194	Off Idle	74.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.86	15.08	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:1	35.45	2371	1.48	13.45	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.87	15.07	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:1	35.45	2362	1.48	13.45	93	194	Off Idle	74.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.87	15.06	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:2	35.45	2358	1.48	13.45	93	194	Off Idle	74.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.86	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:2	35.45	2357	1.48	13.45	93	194	Off Idle	74.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.87	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:2	35.45	2362	1.48	13.45	93	194	Off Idle	74.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.86	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:2	35.45	2351	1.48	13.45	93	194	Off Idle	74.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.84	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:2	35.45	2349	1.48	13.45	93	194	Off Idle	74.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.83	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:2	35.45	2349	1.48	13.46	93	194	Off Idle	74.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.81	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:3	35.45	2349	1.48	13.46	93	194	Off Idle	74.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.82	14.97	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:3	35.45	2348	1.48	13.47	93	194	Off Idle	74.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.83	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:3	35.45	2346	1.48	13.47	93	194	Off Idle	74.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.86	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:3	35.45	2342	1.48	13.47	93	194	Off Idle	74.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.86	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:3	35.45	2342	1.48	13.46	93	194	Off Idle	74.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.85	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:3	35.45	2342	1.48	13.46	93	194	Off Idle	74.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.86	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:4	35.45	2339	1.48	13.47	94	194	Off Idle	74.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.83	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:4	35.45	2341	1.48	13.47	94	194	Off Idle	74.2	0	2	132	944 Turbo	0.22	Rich	1	14.6	-9.82	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:4	35.45	2337	1.48	13.47	94	194	Off Idle	74.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.8	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:4	35.45	2338	1.48	13.49	94	194	Off Idle	74.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.78	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:4	35.45	2338	1.48	13.48	94	194	Off Idle	74.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.8	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:4	35.45	2342	1.48	13.47	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.81	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:4	35.45	2339	1.48	13.46	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.78	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:5	35.45	2356	1.48	13.45	93	194	Off Idle	74.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.82	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:5	35.45	2356	1.48	13.45	94	194	Off Idle	74.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.83	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:5	35.45	2357	1.48	13.46	94	194	Off Idle	74.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.86	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:5	35.45	2359	1.48	13.46	94	194	Off Idle	74.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.84	14.81	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:5	35.45	2359	1.48	13.47	94	194	Off Idle	74.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.86	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:5	35.45	2360	1.48	13.47	94	194	Off Idle	74.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.86	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:6	35.45	2356	1.48	13.46	94	194	Off Idle	74.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.85	14.86	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:6	35.45	2370	1.48	13.48	93	194	Off Idle	74.9	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.86	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:42:6	35.45	2356	1.48	13.47	93	194	Off Idle	74.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.89	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:6	35.45	2356	1.48	13.48	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.87	14.91	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:6	35.45	2352	1.48	13.48	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.86	14.94	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:6	35.45	2352	1.48	13.47	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.84	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:6	35.45	2350	1.48	13.47	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.82	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:7	35.45	2350	1.48	13.47	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.85	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:7	35.45	2348	1.48	13.47	93	194	Off Idle	74.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.85	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:7	35.45	2360	1.48	13.46	94	194	Off Idle	74.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.83	15.05	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:7	35.45	2360	1.48	13.45	94	194	Off Idle	74.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.84	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:7	35.45	2335	1.48	13.46	94	194	Off Idle	74.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.83	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:7	35.45	2330	1.48	13.48	93	194	Off Idle	74.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.82	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:42:8	35.45	2328	1.48	13.48	93	194	Off Idle	74.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.81	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:8	35.45	2315	1.48	13.48	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.81	15.05	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:8	35.45	2321	1.48	13.46	93	194	Off Idle	74.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.81	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:8	35.45	2321	1.48	13.46	93	194	Off Idle	74.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.79	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:8	35.45	2322	1.48	13.47	93	194	Off Idle	75	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.77	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:8	35.45	2314	1.48	13.47	93	194	Off Idle	75.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.8	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:9	35.45	2323	1.48	13.46	93	194	Off Idle	75.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.8	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:9	35.45	2323	1.48	13.47	93	194	Off Idle	75.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.78	14.88	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:9	35.45	2330	1.49	13.47	93	194	Off Idle	75.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.78	14.83	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:9	35.45	2344	1.49	13.46	93	194	Off Idle	75.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.79	14.82	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:9	35.45	2344	1.49	13.47	93	194	Off Idle	75.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.76	14.81	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:9	35.45	2346	1.49	13.46	93	194	Off Idle	76	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.74	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:42:9	35.45	2348	1.49	13.47	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.76	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:0	35.45	2350	1.49	13.47	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.74	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:0	35.45	2350	1.49	13.48	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.71	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:0	35.45	2349	1.49	13.48	93	194	Off Idle	76.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.74	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:0	35.45	2348	1.49	13.46	93	194	Off Idle	76	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.74	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:0	35.45	2348	1.49	13.46	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.71	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:0	35.45	2344	1.49	13.48	93	194	Off Idle	75.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.72	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:1	35.45	2355	1.5	13.46	94	194	Off Idle	75.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.73	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:1	35.45	2355	1.5	13.47	94	194	Off Idle	75.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.71	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:1	35.45	2356	1.5	13.47	94	194	Off Idle	75.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.71	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:1	35.45	2354	1.5	13.46	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.69	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:1	35.45	2371	1.51	13.46	93	194	Off Idle	75	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.66	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:1	35.45	2362	1.51	13.46	93	194	Off Idle	74.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.67	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:1	35.45	2345	1.51	13.47	93	194	Off Idle	74.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.65	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:2	35.45	2344	1.51	13.47	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.63	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:2	35.45	2344	1.52	13.47	93	194	Off Idle	74.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.64	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:2	35.45	2332	1.52	13.47	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.59	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:2	35.45	2339	1.52	13.48	93	194	Off Idle	74.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.57	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:2	35.45	2339	1.52	13.47	94	194	Off Idle	74.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.6	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:2	35.45	2339	1.53	13.46	94	194	Off Idle	74.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.58	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:3	35.45	2337	1.53	13.47	94	194	Off Idle	74.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.6	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:3	35.45	2336	1.53	13.46	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.6	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:3	35.45	2335	1.53	13.46	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.6	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:3	35.45	2328	1.53	13.46	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.61	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:3	35.45	2309	1.53	13.46	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.59	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:3	35.45	2323	1.53	13.47	93	194	Off Idle	75.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.6	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:4	35.45	2323	1.54	13.46	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.61	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:4	35.45	2323	1.54	13.46	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.59	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:4	35.45	2306	1.54	13.47	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.59	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:4	35.45	2316	1.54	13.48	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.6	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:4	35.45	2329	1.54	13.47	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.57	14.82	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:4	35.45	2330	1.54	13.46	93	194	Off Idle	75.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.59	14.83	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:4	35.45	2330	1.53	13.46	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.58	14.81	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:5	35.45	2331	1.53	13.45	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.6	14.81	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:5	35.45	2332	1.53	13.45	93	194	Off Idle	75.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.59	14.82	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:43:5	35.45	2332	1.53	13.45	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.6	14.84	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:5	35.45	2333	1.53	13.45	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.6	14.86	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:5	35.45	2334	1.53	13.47	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.6	14.87	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:5	35.45	2337	1.53	13.47	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.58	14.91	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:6	35.45	2337	1.53	13.48	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.58	14.92	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:6	35.45	2338	1.53	13.48	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.6	14.94	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:6	35.45	2376	1.53	13.48	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.61	14.97	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:6	35.45	2353	1.53	13.47	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.62	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:6	35.45	2330	1.53	13.46	93	194	Off Idle	75.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.62	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:6	35.45	2329	1.53	13.46	93	194	Off Idle	75.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.6	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:6	35.45	2310	1.53	13.44	93	194	Off Idle	75.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.65	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:7	35.45	2317	1.53	13.45	93	194	Off Idle	75.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.63	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:7	35.45	2325	1.53	13.45	93	194	Off Idle	75.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.61	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:7	35.45	2327	1.53	13.45	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.63	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:7	35.45	2327	1.53	13.45	93	194	Off Idle	75.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.61	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:7	35.45	2318	1.53	13.44	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.58	14.91	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:7	35.45	2326	1.53	13.48	93	194	Off Idle	75.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.6	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:8	35.45	2328	1.53	13.47	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.62	14.83	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:43:8	35.45	2328	1.53	13.46	93	194	Off Idle	76	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.63	14.78	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:8	35.45	2331	1.53	13.46	93	194	Off Idle	76.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.64	14.75	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:8	35.45	2326	1.53	13.46	93	194	Off Idle	76.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.67	14.73	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:8	35.45	2327	1.52	13.47	93	194	Off Idle	76.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.66	14.72	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:8	35.45	2316	1.52	13.45	93	194	Off Idle	76.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.64	14.73	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:9	35.45	2322	1.52	13.44	93	194	Off Idle	76	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.65	14.75	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:9	35.45	2328	1.52	13.45	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.6	14.75	1	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:9	35.45	2328	1.52	13.47	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.57	14.77	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:9	35.45	2328	1.52	13.46	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.59	14.77	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:9	35.45	2328	1.52	13.47	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.57	14.79	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:9	35.45	2330	1.52	13.47	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.57	14.79	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:43:9	35.45	2333	1.52	13.46	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.61	14.8	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:0	35.45	2334	1.52	13.47	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.59	14.81	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:0	35.45	2336	1.52	13.46	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.62	14.84	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:0	35.45	2352	1.52	13.46	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.61	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:0	35.45	2332	1.52	13.47	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.61	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:0	35.45	2330	1.52	13.47	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.62	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:0	35.45	2330	1.52	13.47	94	194	Off Idle	75.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.63	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:1	35.45	2322	1.52	13.47	94	194	Off Idle	75.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.62	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:1	35.45	2320	1.52	13.47	94	194	Off Idle	76.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.64	14.95	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:1	35.45	2319	1.52	13.46	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.62	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:1	35.45	2316	1.52	13.48	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.62	15.06	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:1	35.45	2315	1.52	13.48	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.62	15.07	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:1	35.45	2314	1.52	13.47	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.62	15.06	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:1	35.45	2315	1.52	13.48	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.62	15.05	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:2	35.45	2314	1.51	13.48	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.62	15.04	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:2	35.45	2330	1.51	13.46	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.64	15.03	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:2	35.45	2310	1.51	13.44	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.63	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:2	35.45	2309	1.51	13.45	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.58	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:2	35.45	2310	1.51	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.58	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:2	35.45	2312	1.51	13.45	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.61	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:3	35.45	2312	1.51	13.46	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.59	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:3	35.45	2314	1.51	13.47	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.58	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:3	35.45	2317	1.51	13.46	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.62	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:3	35.45	2294	1.51	13.47	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.59	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:3	35.45	2304	1.51	13.45	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.59	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:3	35.45	2313	1.51	13.43	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.6	14.88	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:4	35.45	2313	1.51	13.44	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.6	14.87	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:4	35.45	2313	1.51	13.45	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.56	14.86	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:4	35.45	2328	1.51	13.44	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.58	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:44:4	35.45	2324	1.51	13.45	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.6	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:4	35.45	2324	1.51	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.6	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:4	35.45	2326	1.51	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.58	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:4	35.45	2342	1.51	13.46	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.61	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:5	35.45	2337	1.51	13.46	93	194	Off Idle	76	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.57	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:5	35.45	2339	1.51	13.47	93	194	Off Idle	76	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.56	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:5	35.45	2339	1.51	13.47	93	194	Off Idle	75.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.58	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:5	35.45	2338	1.51	13.46	93	194	Off Idle	75.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.61	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:5	35.45	2334	1.51	13.47	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.6	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:5	35.45	2332	1.51	13.46	93	194	Off Idle	75.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.62	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:6	35.45	2326	1.51	13.45	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.64	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:6	35.45	2320	1.51	13.45	93	194	Off Idle	75.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.61	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:6	35.45	2318	1.51	13.46	93	194	Off Idle	75.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.6	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:6	35.45	2313	1.52	13.45	93	194	Off Idle	75.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.6	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:6	35.45	2267	1.52	13.45	93	194	Off Idle	75.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.59	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:6	35.45	2299	1.52	13.46	93	194	Off Idle	75.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.58	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:6	35.45	2300	1.52	13.44	93	194	Off Idle	75.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.57	15.15	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:7	35.45	2302	1.53	13.44	93	194	Off Idle	75.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.56	15.12	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:7	35.45	2304	1.53	13.45	93	194	Off Idle	75.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.51	15.12	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:44:7	35.45	2310	1.54	13.46	93	194	Off Idle	76	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.46	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:7	35.45	2310	1.54	13.45	94	194	Off Idle	76.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.44	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:7	35.45	2312	1.55	13.45	94	194	Off Idle	76.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.39	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:7	35.45	2314	1.55	13.46	94	194	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.34	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:8	35.45	2314	1.56	13.46	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.33	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:8	35.45	2322	1.57	13.46	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.29	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:8	35.45	2325	1.58	13.45	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.24	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:8	35.45	2325	1.58	13.46	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.2	15.05	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:8	35.45	2329	1.59	13.46	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.15	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:8	35.45	2326	1.6	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.1	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:9	34.08	2339	1.6	13.48	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.08	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:44:9	34.08	2339	1.61	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.03	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:44:9	34.08	2346	1.63	13.49	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.96	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:44:9	34.08	2346	1.64	13.49	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.9	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:44:9	34.08	2323	1.66	13.49	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.73	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:44:9	34.08	2314	1.68	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.62	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:44:9	34.08	2310	1.7	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.51	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:45:0	34.08	2290	1.71	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.39	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:45:0	34.08	2300	1.73	13.46	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.29	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:45:0	34.08	2301	1.74	13.45	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.19	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:0	34.08	2301	1.75	13.46	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.1	14.84	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:0	34.08	2334	1.77	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.05	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:0	34.08	2321	1.78	13.46	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.96	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:1	34.08	2325	1.8	13.46	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.87	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:1	34.08	2336	1.82	13.45	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.81	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:1	34.08	2320	1.84	13.45	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:1	34.08	2331	1.85	13.46	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.85	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:1	34.08	2331	1.87	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	14.86	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:1	34.08	2324	1.88	13.47	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.63	14.88	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:1	34.08	2319	1.89	13.48	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.57	14.93	1.02	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:2	34.08	2334	1.9	13.46	94	194	Off Idle	76	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.56	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:2	34.08	2306	1.91	13.47	94	194	Off Idle	75.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.54	15.04	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:2	34.08	2306	1.92	13.46	94	194	Off Idle	75.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.48	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:2	34.08	2305	1.92	13.47	94	194	Off Idle	75.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.48	15.13	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:2	34.08	2305	1.92	13.47	94	194	Off Idle	75.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.47	15.18	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:2	34.08	2306	1.93	13.47	94	194	Off Idle	75.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.44	15.22	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:3	34.08	2310	1.93	13.46	94	194	Off Idle	75.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.38	15.24	1.04	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:3	34.08	2312	1.93	13.46	94	194	Off Idle	75.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.4	15.27	1.04	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:3	34.08	2324	1.93	13.45	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.4	15.25	1.04	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:45:3	34.08	2323	1.93	13.45	93	194	Off Idle	75.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.37	15.21	1.04	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:3	34.08	2323	1.93	13.47	93	194	Off Idle	76	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.37	15.14	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:3	34.08	2323	1.93	13.47	93	194	Off Idle	75.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.4	15.09	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:4	34.08	2324	1.93	13.47	93	194	Off Idle	75.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.39	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:4	34.08	2321	1.93	13.46	93	194	Off Idle	75.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.38	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:4	34.08	2314	1.93	13.47	93	194	Off Idle	76.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.42	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:4	34.08	2302	1.93	13.45	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.4	14.89	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:4	34.08	2306	1.93	13.46	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.43	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:4	34.08	2308	1.93	13.44	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.46	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:4	34.08	2315	1.93	13.44	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.43	14.77	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:5	34.08	2323	1.93	13.46	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.44	14.77	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:5	34.08	2323	1.92	13.46	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.48	14.78	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:5	34.08	2313	1.92	13.46	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.5	14.77	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:5	34.08	2326	1.92	13.47	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.48	14.78	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:5	34.08	2325	1.92	13.47	93	194	Off Idle	76.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.5	14.79	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:5	34.08	2320	1.92	13.46	93	194	Off Idle	76.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.52	14.83	1.01	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:45:6	34.08	2320	1.91	13.47	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.5	14.86	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:6	34.08	2322	1.91	13.45	94	194	Off Idle	76.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.53	14.89	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:6	34.08	2321	1.91	13.45	94	194	Off Idle	76.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.58	14.93	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:6	34.08	2318	1.91	13.46	94	194	Off Idle	76.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.58	14.94	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:6	34.08	2317	1.91	13.46	94	194	Off Idle	76.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.58	14.96	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:6	34.08	2317	1.9	13.44	94	194	Off Idle	76.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.59	15.02	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:6	34.08	2318	1.9	13.46	94	194	Off Idle	76.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.61	15.04	1.02	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:45:7	34.08	2339	1.9	13.47	94	194	Off Idle	76.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.62	15.08	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:45:7	34.08	2339	1.89	13.46	94	194	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.12	1.03	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:45:7	34.08	2320	1.88	13.45	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:45:7	34.08	2322	1.88	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:45:7	34.08	2341	1.87	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:45:7	34.08	2341	1.87	13.46	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.89	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:45:8	34.08	2320	1.86	13.46	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.92	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:45:8	34.08	2320	1.85	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.99	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:45:8	34.08	2319	1.85	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.08	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:45:8	34.08	2319	1.84	13.46	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.09	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:45:8	34.08	2319	1.83	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.18	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:45:8	34.08	2319	1.82	13.47	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.28	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:45:9	34.08	2314	1.81	13.48	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.34	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:45:9	34.08	2314	1.8	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.39	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:23:45:9	34.08	2312	1.79	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.47	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:45:9	34.08	2312	1.78	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.5	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:45:9	34.08	2308	1.77	13.48	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.52	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:23:45:9	34.08	2308	1.75	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.58	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:45:9	34.08	2308	1.74	13.46	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.61	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:0	34.08	2312	1.72	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.63	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:0	34.08	2311	1.71	13.46	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.72	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:0	34.08	2309	1.7	13.45	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.75	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:0	34.08	2312	1.69	13.46	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.78	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:0	34.08	2318	1.69	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.84	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:0	34.08	2318	1.67	13.45	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.92	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:1	34.08	2322	1.66	13.45	94	194	Off Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.94	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:1	34.08	2321	1.66	13.46	94	194	Off Idle	76.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.98	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:1	34.08	2320	1.65	13.45	94	194	Off Idle	76.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.04	14.9	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:1	34.08	2312	1.64	13.45	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.06	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:23:46:1	34.08	2315	1.64	13.46	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.04	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:1	34.08	2318	1.64	13.46	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.08	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:1	34.08	2319	1.63	13.47	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.11	15.05	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:2	34.08	2319	1.63	13.46	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.11	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:2	34.08	2322	1.63	13.45	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.14	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:2	34.08	2319	1.62	13.44	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.14	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:46:2	34.08	2318	1.62	13.44	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.15	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:2	34.08	2306	1.62	13.43	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.14	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:2	34.08	2316	1.62	13.44	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.14	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:3	34.08	2313	1.62	13.44	93	194	Off Idle	76.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.18	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:3	34.08	2293	1.62	13.44	93	194	Off Idle	76	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.17	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:3	34.08	2315	1.62	13.46	93	194	Off Idle	76	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.15	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:3	34.08	2314	1.61	13.47	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.15	15.07	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:3	34.08	2318	1.61	13.46	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.2	15.04	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:3	34.08	2335	1.61	13.45	93	193	Off Idle	76.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.2	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:4	34.08	2335	1.61	13.46	93	193	Off Idle	76.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.19	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:4	34.08	2300	1.61	13.46	93	193	Off Idle	76.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.25	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:4	34.08	2295	1.61	13.45	94	193	Off Idle	76.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.25	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:4	34.08	2295	1.6	13.46	94	194	Off Idle	76.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.23	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:4	34.08	2299	1.6	13.46	94	194	Off Idle	76.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.24	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:4	34.08	2300	1.6	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.27	15.01	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:4	34.08	2300	1.59	13.48	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.28	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:5	34.08	2302	1.59	13.47	93	194	Off Idle	76.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.3	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:5	34.08	2300	1.59	13.47	93	193	Off Idle	76.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.31	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:5	34.08	2306	1.58	13.48	93	193	Off Idle	76.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.32	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:5	34.08	2306	1.58	13.46	93	193	Off Idle	76.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.3	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:5	34.08	2312	1.58	13.47	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.29	15	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:5	34.08	2316	1.58	13.46	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.3	14.99	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:6	34.08	2316	1.57	13.45	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.32	14.97	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:6	34.08	2319	1.57	13.45	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.3	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:6	34.08	2320	1.57	13.45	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.33	14.92	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:6	34.08	2332	1.57	13.46	94	194	Off Idle	76.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.37	14.88	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:6	34.08	2326	1.56	13.45	94	194	Off Idle	76.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.37	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:6	34.08	2329	1.56	13.47	94	194	Off Idle	76.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.38	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:6	34.08	2330	1.56	13.48	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.41	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:7	34.08	2330	1.56	13.46	93	194	Off Idle	76.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.43	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:7	35.45	2344	1.56	13.47	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.43	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:7	35.45	2333	1.56	13.46	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.42	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:7	35.45	2314	1.56	13.46	93	194	Off Idle	76.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.41	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:7	35.45	2285	1.56	13.46	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.4	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:7	35.45	2285	1.56	13.46	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.4	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:8	35.45	2295	1.57	13.47	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.35	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:8	35.45	2293	1.57	13.49	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.35	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:8	34.08	2284	1.57	13.48	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.38	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:8	34.08	2303	1.57	13.45	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.38	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:8	34.08	2298	1.57	13.45	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.34	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:8	34.08	2298	1.57	13.45	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.35	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:9	34.08	2305	1.57	13.46	93	194	Off Idle	76.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.36	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:9	34.08	2306	1.57	13.46	94	194	Off Idle	76.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:46:9	35.45	2306	1.57	13.47	94	194	Off Idle	76.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.34	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:9	35.45	2322	1.57	13.47	94	194	Off Idle	76.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:9	35.45	2316	1.57	13.46	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:9	35.45	2318	1.57	13.47	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.34	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:46:9	35.45	2318	1.57	13.46	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.37	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:0	35.45	2319	1.57	13.46	93	194	Off Idle	76.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.36	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:0	35.45	2314	1.57	13.47	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.36	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:0	34.08	2302	1.57	13.46	93	194	Off Idle	76.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.38	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:0	34.08	2301	1.57	13.47	94	194	Off Idle	76.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.39	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:0	34.08	2289	1.57	13.48	94	194	Off Idle	76.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.4	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:0	34.08	2290	1.57	13.46	94	194	Off Idle	76.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.42	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:1	34.08	2289	1.56	13.47	93	194	Off Idle	77	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.4	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:1	34.08	2287	1.56	13.48	93	194	Off Idle	77.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.4	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:1	34.08	2287	1.56	13.47	94	194	Off Idle	77.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.44	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:1	34.08	2290	1.56	13.47	94	194	Off Idle	77.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.44	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:47:1	34.08	2291	1.56	13.47	94	194	Off Idle	77.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.46	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:1	34.08	2284	1.55	13.46	93	194	Off Idle	77.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.48	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:1	34.08	2299	1.55	13.45	93	194	Off Idle	77.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.48	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:2	34.08	2302	1.55	13.46	93	194	Off Idle	77.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.5	14.83	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:2	34.08	2302	1.55	13.46	93	194	Off Idle	77.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.48	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:2	35.45	2326	1.55	13.47	93	194	Off Idle	77.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.46	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:2	35.45	2309	1.54	13.48	93	194	Off Idle	77.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.45	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:2	35.45	2312	1.54	13.47	93	193	Off Idle	77.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.46	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:2	35.45	2310	1.54	13.48	93	193	Off Idle	77.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.46	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:3	35.45	2323	1.54	13.49	93	194	Off Idle	77.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.46	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:3	35.45	2321	1.54	13.48	93	194	Off Idle	77.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.48	14.84	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:3	35.45	2321	1.53	13.47	93	194	Off Idle	77.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.5	14.84	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:3	35.45	2327	1.53	13.47	93	194	Off Idle	77.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.52	14.83	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:3	35.45	2327	1.53	13.47	93	193	Off Idle	77.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.53	14.82	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:3	35.45	2335	1.53	13.45	93	193	Off Idle	76.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.52	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:4	35.45	2305	1.53	13.45	93	193	Off Idle	76.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.5	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:4	35.45	2295	1.53	13.46	93	194	Off Idle	76.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.51	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:4	35.45	2295	1.53	13.45	93	194	Off Idle	76.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.54	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:4	35.45	2276	1.53	13.47	93	193	Off Idle	76.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.5	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:47:4	35.45	2295	1.53	13.47	93	193	Off Idle	76.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.52	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:47:4	35.45	2299	1.53	13.46	94	193	Off Idle	76.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.51	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:47:4	35.45	2299	1.53	13.46	94	193	Off Idle	76.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.49	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:47:5	35.45	2304	1.53	13.45	94	194	Off Idle	77	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.49	15.05	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:47:5	35.45	2306	1.53	13.44	93	194	Off Idle	77.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.5	15.08	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:47:5	35.45	2308	1.54	13.44	93	194	Off Idle	77.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.48	15.09	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:47:5	35.45	2322	1.54	13.46	93	194	Off Idle	77.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.49	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:47:5	35.45	2310	1.54	13.44	93	194	Off Idle	77.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.53	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:5	35.45	2310	1.54	13.44	93	194	Off Idle	77.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.54	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:6	35.45	2307	1.54	13.44	93	194	Off Idle	77.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.51	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:6	35.45	2298	1.54	13.46	93	194	Off Idle	77.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.52	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:6	35.45	2298	1.54	13.46	93	194	Off Idle	77.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.53	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:6	35.45	2292	1.54	13.45	93	194	Off Idle	77.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.51	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:6	35.45	2286	1.54	13.45	94	194	Off Idle	77.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.49	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:6	35.45	2279	1.54	13.48	94	194	Off Idle	77.1	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.46	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:6	35.45	2279	1.53	13.48	94	194	Off Idle	77.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.46	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:7	35.45	2284	1.53	13.45	94	194	Off Idle	77.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.47	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:7	35.45	2286	1.53	13.46	94	194	Off Idle	77.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.45	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:7	35.45	2287	1.53	13.44	94	194	Off Idle	77.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.45	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:7	35.45	2292	1.53	13.44	93	194	Off Idle	77.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.46	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:7	35.45	2293	1.53	13.44	93	194	Off Idle	77.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.46	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:7	35.45	2293	1.53	13.45	93	194	Off Idle	77.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.47	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:8	35.45	2293	1.53	13.45	93	194	Off Idle	77.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.49	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:8	35.45	2286	1.53	13.47	93	193	Off Idle	77.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.47	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:8	35.45	2298	1.53	13.47	93	193	Off Idle	77.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.52	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:8	34.08	2298	1.53	13.46	93	193	Off Idle	77.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.53	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:8	34.08	2304	1.52	13.43	93	194	Off Idle	77.7	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.52	15	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:8	34.08	2310	1.53	13.43	93	194	Off Idle	77.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.52	14.98	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:9	34.08	2310	1.52	13.44	94	194	Off Idle	77.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.51	14.96	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:9	34.08	2314	1.52	13.43	94	194	Off Idle	77.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.52	14.95	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:9	34.08	2309	1.52	13.43	94	194	Off Idle	77.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.52	14.94	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:9	34.08	2309	1.52	13.46	94	194	Off Idle	77.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.54	14.92	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:9	35.45	2330	1.51	13.47	94	194	Off Idle	77.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.57	14.88	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:9	35.45	2313	1.51	13.45	93	194	Off Idle	77.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.65	14.86	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:47:9	35.45	2314	1.49	13.45	93	193	Off Idle	77.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.7	14.85	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:23:48:0	35.45	2315	1.48	13.46	93	193	Off Idle	77.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.8	14.83	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:48:0	35.45	2312	1.47	13.44	93	193	Off Idle	77.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.87	14.83	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:48:0	35.45	2305	1.46	13.44	93	194	Off Idle	77.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.89	14.82	1.01	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:48:0	35.45	2302	1.44	13.46	93	194	Off Idle	77.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.02	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:48:0	35.45	2301	1.43	13.46	93	194	Off Idle	77	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.06	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:48:0	35.45	2277	1.42	13.46	93	194	Off Idle	77	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.08	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:48:1	35.45	2274	1.41	13.46	93	193	Off Idle	77.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.14	14.88	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:1	35.45	2266	1.39	13.45	93	193	Off Idle	77.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.16	14.92	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:1	35.45	2263	1.38	13.44	93	193	Off Idle	77.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-10.17	14.94	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:1	35.45	2261	1.37	13.43	93	194	Off Idle	77.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-10.18	14.97	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:1	35.45	2260	1.35	13.43	93	194	Off Idle	77.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.2	15.01	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:1	35.45	2251	1.34	13.44	93	194	Off Idle	77.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10.21	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:1	35.45	2244	1.33	13.45	94	194	Off Idle	78	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.22	15.09	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:2	35.45	2244	1.31	13.45	94	194	Off Idle	78.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.29	15.11	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:2	35.45	2254	1.29	13.47	94	193	Off Idle	78.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.3	15.12	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:2	35.45	2269	1.28	13.48	93	193	Off Idle	79.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.3	15.12	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:2	35.45	2269	1.27	13.47	93	193	Off Idle	79.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.32	15.12	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:2	34.08	2265	1.27	13.47	93	194	Off Idle	79.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.38	15.11	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:48:2	34.08	2298	1.26	13.47	93	194	Off Idle	79.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.4	15.12	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:3	34.08	2306	1.26	13.46	94	194	Off Idle	79.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.43	15.11	1.03	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:3	34.08	2306	1.25	13.47	94	194	Off Idle	79.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.47	15.11	1.03	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:3	34.08	2342	1.24	13.47	93	194	Off Idle	79.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.51	15.12	1.03	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:3	34.08	2322	1.23	13.46	93	194	Off Idle	79.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.55	15.12	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:3	35.45	2320	1.22	13.47	93	193	Full Load	79	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.6	15.09	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:3	35.45	2306	1.21	13.46	94	193	Idle	78.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.65	15.06	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:48:4	35.45	2293	1.2	13.45	94	193	Idle	78.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-10.66	15.04	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:48:4	35.45	2274	1.19	13.47	94	194	Idle	78.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-10.69	14.99	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:48:4	35.45	2274	1.18	13.47	94	194	Idle	78.1	0	2	132	944 Turbo	0.24	Rich	1	14.6	-10.74	14.96	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:48:4	35.45	2272	1.17	13.46	94	194	Idle	77.5	0	2	132	944 Turbo	0.18	Rich	1	14.6	-10.75	14.94	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:4	35.45	2253	1.17	13.47	94	194	Idle	76.8	0	2	132	944 Turbo	0.13	Rich	1	14.6	-10.75	14.91	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:4	32.72	2236	1.16	13.47	93	194	Idle	75.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.76	14.86	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:4	32.72	2222	1.15	13.47	93	194	Idle	74.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.76	14.82	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:5	27.27	2206	1.14	13.48	93	194	Idle	73.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.71	14.81	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:5	27.27	2233	1.14	13.48	93	194	Idle	72.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.67	14.8	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:5	21.81	2233	1.14	13.47	93	194	Idle	71.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.63	14.81	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:5	17.72	2273	1.15	13.48	93	193	Idle	71.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.6	14.81	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:5	17.72	2273	1.15	13.49	93	193	Idle	69.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.56	14.82	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:5	17.72	2274	1.16	13.47	93	193	Idle	69.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.5	14.81	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:6	17.72	2272	1.17	13.46	93	193	Idle	69.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.44	14.8	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:6	17.72	2271	1.18	13.46	93	193	Idle	69.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.37	14.82	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:6	17.72	2269	1.19	13.47	93	193	Idle	69.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.3	14.85	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:6	17.72	2263	1.19	13.48	94	193	Idle	70	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.31	14.87	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:6	17.72	2250	1.19	13.48	94	193	Idle	70.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.34	14.89	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:6	17.72	2257	1.2	13.47	94	193	Idle	70.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.35	14.91	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:6	17.72	2257	1.2	13.47	93	193	Idle	71.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	14.94	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:7	17.72	2272	1.21	13.47	93	193	Idle	71.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	14.97	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:7	17.72	2255	1.21	13.47	93	193	Idle	74.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	15.02	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:7	17.72	2247	1.21	13.48	93	193	Idle	75.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	15.07	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:7	17.72	2260	1.21	13.48	93	193	Idle	76.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	15.12	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:7	17.72	2284	1.21	13.48	93	193	Idle	77.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	15.14	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:7	17.72	2267	1.21	13.47	93	193	Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	15.16	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:8	17.72	2268	1.2	13.48	93	193	Idle	78.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.43	15.19	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:8	17.72	2252	1.2	13.48	93	193	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	15.23	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:8	17.72	2260	1.18	13.48	94	193	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	15.3	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:8	17.72	2278	1.17	13.47	94	193	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	15.37	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:8	17.72	2267	1.16	13.48	93	193	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	15.44	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:8	17.72	2256	1.15	13.48	93	193	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	15.52	1.06	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:9	17.72	2261	1.14	13.47	93	193	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	15.67	1.07	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:9	17.72	2260	1.13	13.46	94	193	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	15.8	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:9	17.72	2260	1.12	13.47	94	193	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	15.95	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:9	17.72	2258	1.11	13.47	94	193	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	16.12	1.1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:9	17.72	2257	1.11	13.48	93	193	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	16.3	1.11	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:48:9	17.72	2257	1.1	13.48	93	193	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	16.64	1.13	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:48:9	17.72	2257	1.1	13.48	93	193	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	16.78	1.14	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:0	17.72	2259	1.1	13.46	93	193	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	17.1	1.16	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:0	17.72	2260	1.1	13.46	93	193	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	17.49	1.19	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:0	17.72	2260	1.09	13.47	94	193	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	17.88	1.22	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:0	17.72	2260	1.09	13.46	94	193	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	18.46	1.26	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:0	17.72	2258	1.09	13.47	94	193	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	18.64	1.27	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:0	17.72	2255	1.09	13.46	94	193	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	18.99	1.29	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:1	17.72	2255	1.08	13.46	94	193	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	19.45	1.33	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:1	17.72	2251	1.08	13.45	94	193	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	19.73	1.34	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:1	17.72	2231	1.08	13.46	94	193	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	19.96	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:1	17.72	2261	1.08	13.47	94	193	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.11	1.37	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:1	17.72	2261	1.08	13.46	94	193	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:1	17.72	2244	1.08	13.46	93	193	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:1	17.72	2244	1.08	13.47	93	193	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:2	17.72	2246	1.07	13.47	93	193	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:2	17.72	2246	1.07	13.47	94	193	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:2	17.72	2246	1.07	13.46	94	193	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:2	17.72	2248	1.07	13.47	94	193	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:2	17.72	2248	1.07	13.47	93	193	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:2	17.72	2246	1.07	13.47	93	193	Idle	79	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:3	17.72	2244	1.07	13.47	93	193	Idle	79.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:3	17.72	2240	1.06	13.47	93	193	Idle	79.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:3	17.72	2240	1.06	13.45	93	193	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:3	17.72	2228	1.06	13.45	94	193	Idle	79.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:3	17.72	2235	1.06	13.46	94	193	Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:3	17.72	2234	1.06	13.46	94	193	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:4	17.72	2231	1.06	13.45	93	193	Idle	79.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:4	17.72	2236	1.06	13.46	93	193	Idle	79.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:4	17.72	2227	1.06	13.45	93	193	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:4	17.72	2220	1.06	13.44	93	193	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:4	17.72	2230	1.06	13.44	93	193	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:4	17.72	2233	1.06	13.46	93	193	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:4	17.72	2244	1.05	13.45	93	193	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:5	17.72	2234	1.05	13.46	93	193	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:5	17.72	2245	1.05	13.46	93	193	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:5	17.72	2247	1.05	13.47	93	193	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:5	17.72	2255	1.05	13.47	93	193	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:5	17.72	2254	1.05	13.47	93	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.01	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:5	17.72	2243	1.05	13.46	93	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.01	1.36	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:6	17.72	2243	1.05	13.46	93	193	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.01	1.36	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:6	17.72	2220	1.05	13.46	93	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.02	1.36	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:6	17.72	2228	1.05	13.46	93	193	Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.01	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:6	17.72	2237	1.05	13.46	93	193	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.02	1.36	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:6	17.72	2227	1.05	13.46	94	193	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.02	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:6	17.72	2217	1.05	13.46	94	194	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.01	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:6	17.72	2219	1.05	13.46	94	194	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.02	1.36	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:7	17.72	2221	1.05	13.46	94	194	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:7	17.72	2222	1.05	13.47	94	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:7	17.72	2253	1.05	13.46	94	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:7	17.72	2253	1.05	13.45	93	193	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:7	17.72	2240	1.05	13.47	93	193	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:7	17.72	2240	1.05	13.46	93	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:8	17.72	2246	1.05	13.46	93	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:8	17.72	2229	1.05	13.48	93	193	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:8	17.72	2203	1.05	13.48	93	193	Idle	80.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:8	17.72	2190	1.05	13.47	93	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:8	17.72	2195	1.04	13.46	93	193	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:49:8	17.72	2197	1.04	13.46	93	193	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:9	17.72	2196	1.04	13.46	93	193	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:9	17.72	2199	1.04	13.46	93	193	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:9	17.72	2205	1.04	13.47	93	193	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:9	17.72	2205	1.04	13.45	93	193	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:9	17.72	2209	1.04	13.46	93	193	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:9	17.72	2231	1.04	13.46	93	193	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:49:9	17.72	2218	1.04	13.46	93	193	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:0	17.72	2204	1.04	13.46	93	193	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:0	17.72	2226	1.04	13.47	94	193	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:0	17.72	2225	1.04	13.46	94	193	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:0	17.72	2222	1.05	13.46	94	193	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:0	17.72	2238	1.04	13.47	94	193	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:0	17.72	2214	1.04	13.48	94	193	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:1	17.72	2211	1.04	13.48	93	193	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:1	17.72	2192	1.04	13.47	93	193	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:1	17.72	2211	1.04	13.49	93	193	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:1	17.72	2190	1.04	13.49	93	193	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:1	17.72	2190	1.04	13.49	93	193	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:1	17.72	2153	1.04	13.48	93	193	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:1	17.72	2188	1.04	13.48	93	193	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:2	17.72	2209	1.04	13.46	93	193	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:2	17.72	2209	1.04	13.45	93	193	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:2	17.72	2195	1.04	13.45	93	193	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:2	17.72	2188	1.04	13.45	93	193	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:2	17.72	2204	1.04	13.48	93	193	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:2	17.72	2205	1.04	13.5	94	193	Idle	81.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:3	17.72	2205	1.04	13.47	94	193	Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:3	17.72	2212	1.04	13.46	94	193	Idle	81.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:3	17.72	2199	1.04	13.46	93	193	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:3	17.72	2196	1.03	13.45	93	193	Idle	82	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:3	17.72	2194	1.03	13.45	93	193	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:3	17.72	2189	1.03	13.47	93	193	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:4	17.72	2187	1.03	13.48	93	193	Idle	82.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:4	17.72	2187	1.03	13.48	94	193	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:4	17.72	2178	1.03	13.48	94	193	Idle	82.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:4	17.72	2187	1.03	13.46	94	193	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:4	17.72	2187	1.03	13.46	94	193	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.65	20.23	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:4	17.72	2196	1.03	13.44	93	193	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:4	17.72	2187	1.03	13.45	93	193	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:5	17.72	2187	1.03	13.46	93	193	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:5	17.72	2187	1.03	13.48	93	194	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:5	17.72	2184	1.03	13.48	93	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:5	17.72	2163	1.02	13.49	93	194	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:5	17.72	2172	1.02	13.48	93	193	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.7	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:5	17.72	2172	1.02	13.46	93	193	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:6	17.72	2164	1.02	13.45	93	193	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:6	17.72	2129	1.02	13.44	93	193	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:6	17.72	2129	1.02	13.45	93	193	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:6	17.72	2102	1.02	13.46	94	193	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:6	17.72	2102	1.02	13.47	94	193	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:6	17.72	2051	1.02	13.48	94	193	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:6	17.72	2030	1.02	13.48	93	193	Idle	82.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:7	17.72	2012	1.02	13.47	93	193	Idle	81.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.63	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:7	17.72	1979	1.02	13.47	93	193	Idle	81.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:7	17.72	1949	1.02	13.46	93	193	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:7	17.72	1949	1.02	13.47	93	193	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:7	17.72	1912	1.03	13.47	93	193	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:50:7	17.72	1906	1.03	13.47	94	193	Idle	77.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:8	17.72	1896	1.04	13.47	94	193	Idle	76.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:8	17.72	1849	1.05	13.45	93	193	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:8	17.72	1841	1.06	13.45	93	194	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:8	17.72	1820	1.07	13.44	93	194	Idle	74.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:8	17.72	1808	1.07	13.44	93	194	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.2	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:8	17.72	1776	1.08	13.42	93	194	Idle	72.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:9	17.72	1753	1.1	13.45	93	194	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:9	17.72	1753	1.1	13.44	93	194	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:9	17.72	1719	1.11	13.44	93	193	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:9	17.72	1696	1.13	13.45	93	193	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:9	17.72	1696	1.14	13.46	93	193	Idle	69.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.8	20.22	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:9	17.72	1662	1.15	13.45	93	193	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:50:9	17.72	1625	1.16	13.46	93	193	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.67	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:0	17.72	1614	1.18	13.45	93	193	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:0	17.72	1602	1.2	13.45	93	193	Idle	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.53	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:0	17.72	1578	1.2	13.45	93	193	Idle	67.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.46	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:0	17.72	1548	1.22	13.45	93	193	Idle	67.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.32	20.23	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:0	17.72	1518	1.23	13.45	93	193	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.29	20.23	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:0	17.72	1518	1.23	13.47	93	193	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.22	20.22	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:1	17.72	1493	1.24	13.46	93	193	Idle	66.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.15	20.22	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:1	17.72	1469	1.25	13.46	93	193	Idle	66.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.06	20.21	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:1	17.72	1444	1.25	13.47	94	193	Idle	66.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.01	20.22	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:1	17.72	1444	1.26	13.46	94	193	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.89	20.22	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:1	17.72	1417	1.26	13.43	94	193	Idle	67.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.81	20.22	1.38	4.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:1	17.72	1392	1.27	13.45	94	193	Idle	67.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.73	20.22	1.38	4.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:1	17.72	1392	1.27	13.43	94	194	Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.66	20.21	1.38	4.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:2	19.09	1366	1.28	13.43	94	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.57	20.22	1.38	4.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:2	19.09	1320	1.28	13.42	93	194	Idle	68.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.54	20.22	1.38	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:2	19.09	1322	1.28	13.44	93	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.47	20.22	1.38	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:2	17.72	1322	1.28	13.46	94	194	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.37	20.22	1.38	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:2	17.72	1317	1.28	13.45	94	193	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.32	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:51:2	16.36	1318	1.28	13.45	94	193	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.29	20.22	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:51:3	16.36	1320	1.28	13.47	94	193	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.26	20.23	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:51:3	16.36	1340	1.27	13.44	94	193	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.22	20.22	1.38	4.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:3	16.36	1385	1.27	13.44	94	193	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.24	20.21	1.38	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:3	16.36	1475	1.26	13.46	93	193	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.25	20.21	1.38	4.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:3	16.36	1475	1.26	13.47	93	193	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.27	20.21	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:23:51:3	14.99	1560	1.25	13.47	93	193	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.36	20.21	1.38	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:23:51:4	14.99	1657	1.24	13.48	93	193	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.36	20.21	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:51:4	14.99	1674	1.23	13.47	93	194	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.48	20.22	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:51:4	14.99	1721	1.21	13.49	93	194	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.68	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:51:4	16.36	1838	1.2	13.48	93	194	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.84	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:51:4	16.36	1858	1.19	13.49	93	193	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:51:4	16.36	1883	1.17	13.5	93	193	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.22	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:51:4	16.36	1988	1.16	13.5	93	193	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.37	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:51:5	16.36	2003	1.14	13.49	93	193	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:51:5	16.36	2090	1.13	13.49	93	193	Idle	86.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.68	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:5	16.36	2090	1.11	13.47	93	193	Idle	87.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.82	20.21	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:51:5	16.36	2180	1.1	13.46	93	193	Idle	88.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.95	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:5	17.72	2220	1.08	13.46	93	193	Idle	89.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.09	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:5	17.72	2220	1.06	13.47	93	193	Idle	89.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.23	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:6	17.72	2349	1.04	13.47	93	193	Idle	88.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.38	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:6	17.72	2384	1.03	13.49	94	193	Idle	88.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.47	20.23	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:6	17.72	2478	1.02	13.48	94	193	Idle	87.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.54	20.23	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:6	17.72	2492	1.01	13.48	94	193	Idle	86	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.62	20.23	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:6	17.72	2596	1	13.47	94	193	Idle	84.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.7	20.23	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:6	17.72	2646	0.99	13.47	94	193	Idle	82.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.76	20.22	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:51:6	17.72	2669	0.99	13.48	94	193	Idle	80.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.83	20.22	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:7	19.09	2845	0.99	13.48	93	193	Idle	78.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.88	20.22	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:7	19.09	2856	0.99	13.48	93	193	Idle	76.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.88	20.22	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:7	19.09	2856	1.01	13.48	93	193	Idle	73.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.85	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:7	19.09	2952	1.02	13.49	93	193	Idle	70.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.84	20.23	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:7	19.09	2952	1.03	13.48	93	193	Idle	70.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.81	20.23	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:7	19.09	2941	1.08	13.48	93	193	Idle	64.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.7	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:8	19.09	2909	1.11	13.48	93	193	Idle	61.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.65	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:8	19.09	2888	1.12	13.47	93	193	Idle	55.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:8	19.09	2890	1.15	13.46	93	193	Idle	53.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:8	19.09	2848	1.19	13.47	93	193	Idle	51.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:8	19.09	2824	1.22	13.47	93	193	Idle	50	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:8	19.09	2806	1.26	13.47	93	193	Idle	50	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:9	19.09	2782	1.31	13.48	93	193	Idle	47.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.25	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:9	19.09	2769	1.33	13.48	93	193	Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:9	19.09	2769	1.38	13.47	93	193	Idle	45.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:9	19.09	2771	1.42	13.48	94	194	Idle	44.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:9	19.09	2796	1.45	13.48	94	194	Idle	44	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:9	19.09	2817	1.48	13.47	94	194	Idle	43.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:51:9	19.09	2824	1.51	13.48	93	193	Idle	43.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:0	19.09	2858	1.54	13.48	93	193	Idle	43.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:0	19.09	2857	1.57	13.47	93	193	Idle	43	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:0	19.09	2859	1.6	13.48	93	193	Idle	43.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:0	19.09	2858	1.62	13.48	93	193	Idle	43.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:0	19.09	2843	1.64	13.47	94	193	Idle	43.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:0	19.09	2843	1.65	13.48	94	193	Idle	43.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:1	19.09	2826	1.65	13.47	94	193	Idle	43.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:1	19.09	2806	1.66	13.47	93	193	Idle	43.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:1	19.09	2794	1.66	13.46	93	193	Idle	43.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:1	19.09	2790	1.66	13.47	93	193	Idle	44.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:1	19.09	2772	1.66	13.48	93	193	Idle	44.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:1	19.09	2781	1.66	13.48	93	193	Idle	45.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.73	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:1	19.09	2781	1.66	13.48	93	193	Idle	45.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:2	19.09	2786	1.66	13.47	93	194	Idle	45.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:2	19.09	2796	1.66	13.47	93	194	Idle	45.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.72	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:2	19.09	2826	1.66	13.46	93	194	Idle	46.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.71	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:2	19.09	2818	1.66	13.47	94	193	Idle	46.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:2	19.09	2817	1.66	13.48	94	193	Idle	46.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:2	19.09	2815	1.66	13.49	94	193	Idle	46.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:3	19.09	2815	1.66	13.48	93	193	Idle	46.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:3	19.09	2788	1.65	13.48	93	193	Idle	46.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.75	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:3	19.09	2804	1.65	13.48	93	193	Idle	47.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:3	19.09	2812	1.64	13.47	94	193	Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.76	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:3	19.09	2812	1.64	13.48	94	193	Idle	47.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:3	19.09	2779	1.64	13.47	94	193	Idle	47.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:4	19.09	2771	1.64	13.47	94	193	Idle	47.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:4	19.09	2771	1.63	13.47	94	193	Idle	47.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:4	19.09	2769	1.63	13.47	94	193	Idle	48	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:4	19.09	2747	1.63	13.46	94	193	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:4	19.09	2760	1.63	13.47	94	193	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:4	19.09	2774	1.63	13.47	94	193	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:4	19.09	2778	1.62	13.48	93	193	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:5	19.09	2781	1.62	13.47	93	193	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:5	19.09	2794	1.62	13.48	93	193	Idle	48.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:5	19.09	2786	1.62	13.47	93	193	Idle	48.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.81	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:5	19.09	2786	1.62	13.48	93	193	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:5	19.09	2784	1.62	13.46	94	193	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:5	19.09	2782	1.62	13.48	94	193	Idle	48.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:52:6	19.09	2768	1.62	13.47	94	193	Idle	48.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.84	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:6	19.09	2772	1.61	13.49	93	193	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:6	19.09	2768	1.61	13.47	93	193	Idle	48.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:6	19.09	2768	1.61	13.48	93	193	Idle	48.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:6	19.09	2765	1.61	13.48	93	193	Idle	49	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:6	19.09	2763	1.61	13.48	93	193	Idle	49.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.9	20.14	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:6	19.09	2762	1.61	13.47	93	193	Idle	49.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.13	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:7	19.09	2762	1.61	13.48	93	193	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.89	20.14	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:7	19.09	2764	1.6	13.48	93	193	Idle	49.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.14	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:7	19.09	2774	1.6	13.47	93	193	Idle	49.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.14	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:7	19.09	2766	1.6	13.48	94	193	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.15	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:7	19.09	2745	1.6	13.49	94	193	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.14	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:7	19.09	2766	1.6	13.49	93	193	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.14	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:8	19.09	2764	1.59	13.48	93	193	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.14	1.37	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:8	19.09	2774	1.59	13.49	93	193	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:8	19.09	2758	1.59	13.48	94	193	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:8	19.09	2756	1.59	13.47	94	193	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:8	19.09	2752	1.59	13.47	94	193	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:8	19.09	2747	1.59	13.48	93	193	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:9	19.09	2754	1.58	13.47	93	193	Idle	50.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:9	19.09	2738	1.58	13.47	93	193	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:9	19.09	2733	1.58	13.47	93	193	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:9	19.09	2733	1.58	13.47	93	193	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:9	19.09	2733	1.58	13.49	93	194	Idle	50.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:9	19.09	2734	1.58	13.49	93	194	Idle	50.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:52:9	19.09	2734	1.58	13.5	93	194	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.96	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:0	19.09	2747	1.58	13.49	93	194	Idle	50.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:0	19.09	2740	1.58	13.47	93	194	Idle	50.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:0	19.09	2740	1.57	13.48	93	194	Idle	50.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:0	19.09	2742	1.57	13.47	93	193	Idle	50.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:0	19.09	2742	1.57	13.48	94	193	Idle	50.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:0	19.09	2742	1.57	13.48	94	193	Idle	51	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:1	19.09	2740	1.57	13.48	94	193	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:1	19.09	2738	1.57	13.48	93	193	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:1	19.09	2737	1.57	13.49	93	193	Idle	51.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:1	19.09	2734	1.57	13.49	93	193	Idle	51.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.93	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:1	19.09	2708	1.57	13.48	93	193	Idle	51.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.94	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:1	19.09	2726	1.57	13.48	93	193	Idle	51.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:1	19.09	2726	1.57	13.47	94	193	Idle	51.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.97	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:2	19.09	2731	1.57	13.48	94	193	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:2	19.09	2720	1.56	13.47	94	193	Idle	52.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:2	19.09	2720	1.56	13.48	94	193	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:2	19.09	2719	1.56	13.48	94	193	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:2	19.09	2718	1.56	13.48	94	193	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:2	19.09	2718	1.56	13.48	94	193	Idle	52.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:3	19.09	2717	1.56	13.49	94	193	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.03	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:3	19.09	2717	1.56	13.49	94	194	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.04	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:3	19.09	2706	1.55	13.48	93	194	Idle	52.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:3	19.09	2716	1.55	13.48	93	194	Idle	52.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:3	19.09	2716	1.55	13.48	93	194	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:3	19.09	2716	1.55	13.48	93	193	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:4	19.09	2704	1.54	13.48	93	193	Idle	53.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.02	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:4	19.09	2713	1.54	13.49	93	193	Idle	53.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:4	19.09	2710	1.54	13.48	93	193	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:4	19.09	2710	1.54	13.47	93	193	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:4	19.09	2710	1.54	13.47	93	193	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:4	19.09	2709	1.54	13.48	93	193	Idle	53	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:4	19.09	2725	1.54	13.48	93	193	Idle	53.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:53:5	19.09	2703	1.54	13.47	94	193	Idle	53.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:5	19.09	2703	1.54	13.49	94	194	Idle	53.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:5	19.09	2702	1.54	13.49	94	194	Idle	53.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:5	19.09	2701	1.54	13.48	93	194	Idle	53.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:5	19.09	2698	1.53	13.49	93	193	Idle	53.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:5	19.09	2698	1.53	13.49	93	193	Idle	53.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:6	19.09	2705	1.53	13.48	93	193	Idle	53.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:6	19.09	2692	1.53	13.47	93	193	Idle	53.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:6	19.09	2692	1.53	13.49	93	193	Idle	53.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:6	19.09	2671	1.53	13.48	94	193	Idle	54	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:6	19.09	2687	1.53	13.48	94	193	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:6	19.09	2687	1.53	13.47	94	193	Idle	54.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:6	19.09	2693	1.52	13.47	94	193	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:7	19.09	2681	1.52	13.47	94	193	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:7	19.09	2675	1.52	13.47	94	193	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:7	19.09	2675	1.52	13.48	93	193	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.08	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:7	19.09	2671	1.52	13.48	93	193	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:7	19.09	2668	1.52	13.47	93	193	Idle	54.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:7	19.09	2672	1.51	13.48	93	193	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:8	19.09	2672	1.51	13.47	93	193	Idle	54.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:8	19.09	2685	1.51	13.48	93	193	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:8	19.09	2685	1.51	13.45	93	193	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.05	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:8	19.09	2693	1.51	13.46	93	193	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.07	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:8	19.09	2697	1.51	13.47	94	193	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:8	19.09	2688	1.51	13.47	94	193	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:9	19.09	2697	1.51	13.47	94	193	Idle	55	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:9	19.09	2693	1.51	13.48	94	193	Idle	55	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:9	19.09	2690	1.5	13.48	94	193	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:9	19.09	2680	1.5	13.48	94	193	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:9	19.09	2670	1.5	13.5	94	193	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:9	19.09	2668	1.5	13.49	94	193	Idle	55.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:53:9	19.09	2654	1.5	13.48	94	193	Idle	55.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:0	19.09	2646	1.5	13.48	93	193	Idle	55.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:0	19.09	2641	1.5	13.48	93	193	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:0	19.09	2640	1.5	13.47	93	193	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:0	19.09	2640	1.5	13.49	93	193	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:0	19.09	2641	1.5	13.48	93	193	Idle	54.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:0	19.09	2642	1.5	13.47	93	193	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:1	19.09	2647	1.5	13.48	94	193	Idle	55	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:1	19.09	2671	1.5	13.48	94	193	Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:1	19.09	2662	1.5	13.48	93	193	Idle	55.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:1	19.09	2656	1.5	13.47	93	193	Idle	55.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.18	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:1	19.09	2657	1.5	13.48	93	193	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.17	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:1	19.09	2656	1.5	13.49	94	193	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.17	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:1	19.09	2646	1.5	13.48	94	193	Idle	55.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.1	20.18	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:2	19.09	2654	1.5	13.48	94	193	Idle	55.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:2	19.09	2651	1.5	13.47	94	193	Idle	55.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:2	19.09	2649	1.5	13.48	94	193	Idle	55.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:2	19.09	2644	1.49	13.48	94	193	Idle	55.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.18	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:2	19.09	2640	1.49	13.48	94	193	Idle	56	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.19	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:2	19.09	2640	1.49	13.48	93	193	Idle	56.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:3	19.09	2637	1.49	13.48	93	193	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:3	19.09	2614	1.49	13.48	94	193	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.12	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:3	19.09	2633	1.49	13.47	94	193	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:3	19.09	2633	1.49	13.47	94	193	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:3	19.09	2632	1.49	13.48	93	193	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:3	19.09	2633	1.49	13.48	93	193	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:4	19.09	2632	1.48	13.47	93	193	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:54:4	19.09	2630	1.48	13.46	94	193	Idle	56.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:4	19.09	2630	1.48	13.47	94	193	Idle	56.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:4	19.09	2627	1.48	13.48	94	193	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:4	19.09	2626	1.48	13.48	93	193	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.16	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:4	19.09	2623	1.48	13.48	93	193	Idle	56.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:4	19.09	2624	1.48	13.48	93	193	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:5	19.09	2634	1.47	13.47	93	193	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.13	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:5	19.09	2620	1.47	13.47	93	193	Idle	56.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:5	19.09	2599	1.47	13.47	93	193	Idle	57	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.11	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:5	19.09	2610	1.47	13.47	93	193	Idle	57.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.15	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:5	19.09	2630	1.47	13.48	93	193	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:5	19.09	2630	1.47	13.47	93	193	Idle	57.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.17	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:6	19.09	2618	1.47	13.47	93	193	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:6	19.09	2607	1.47	13.48	93	193	Idle	57.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:6	19.09	2616	1.47	13.48	94	193	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:6	19.09	2613	1.46	13.47	94	193	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:6	19.09	2623	1.46	13.47	94	193	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:6	19.09	2611	1.46	13.48	94	193	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:6	19.09	2587	1.46	13.48	94	193	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:7	19.09	2587	1.46	13.48	94	193	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:7	19.09	2608	1.46	13.49	94	193	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:7	19.09	2616	1.46	13.49	94	193	Idle	58.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:7	19.09	2604	1.45	13.48	94	193	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:7	19.09	2604	1.45	13.48	93	193	Idle	58.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:7	19.09	2602	1.45	13.49	93	193	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:8	19.09	2602	1.45	13.48	93	193	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:8	19.09	2601	1.44	13.47	93	193	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:8	19.09	2602	1.44	13.48	93	193	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:8	19.09	2601	1.44	13.48	93	193	Idle	59	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:8	19.09	2600	1.44	13.47	93	193	Idle	59.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:8	19.09	2600	1.44	13.47	93	193	Idle	59.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:9	19.09	2599	1.44	13.48	93	193	Idle	59.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:9	19.09	2598	1.44	13.49	93	193	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:9	19.09	2598	1.43	13.48	93	193	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:9	19.09	2596	1.43	13.48	94	193	Idle	59.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:9	19.09	2595	1.43	13.47	94	193	Idle	59.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:9	19.09	2583	1.43	13.48	94	193	Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:54:9	19.09	2583	1.43	13.47	94	193	Idle	59.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:0	19.09	2590	1.43	13.47	94	193	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:0	19.09	2589	1.43	13.47	93	193	Idle	59.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:0	19.09	2589	1.42	13.48	93	193	Idle	60.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:0	19.09	2588	1.42	13.49	93	193	Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:0	19.09	2586	1.42	13.48	94	193	Idle	60.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:0	19.09	2586	1.42	13.48	94	193	Idle	60.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:1	19.09	2582	1.42	13.48	94	193	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:1	19.09	2582	1.42	13.48	93	193	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:1	19.09	2581	1.42	13.47	93	193	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:1	19.09	2580	1.42	13.48	93	193	Idle	60.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:1	19.09	2576	1.42	13.42	94	193	Idle	60.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:1	19.09	2566	1.42	13.42	94	193	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:1	19.09	2572	1.41	13.4	94	193	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:2	19.09	2567	1.41	13.4	93	193	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:2	19.09	2554	1.41	13.39	93	193	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:2	19.09	2563	1.41	13.41	93	193	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:2	19.09	2563	1.41	13.41	94	193	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:2	19.09	2564	1.41	13.41	94	193	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:2	19.09	2563	1.41	13.42	94	193	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:3	19.09	2563	1.41	13.41	93	193	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:55:3	19.09	2564	1.4	13.41	93	193	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:3	19.09	2565	1.4	13.41	93	193	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:3	19.09	2565	1.4	13.41	93	193	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:3	19.09	2565	1.4	13.43	93	193	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:3	19.09	2565	1.4	13.43	94	193	Idle	61.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:4	19.09	2544	1.4	13.43	94	193	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:4	19.09	2554	1.4	13.43	94	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:4	19.09	2574	1.4	13.43	94	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:4	19.09	2564	1.39	13.43	94	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:4	19.09	2564	1.39	13.41	94	193	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:4	19.09	2562	1.39	13.42	93	193	Idle	61.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:4	19.09	2562	1.39	13.44	93	193	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:5	19.09	2560	1.39	13.42	93	193	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:5	19.09	2555	1.39	13.42	93	193	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:5	19.09	2555	1.39	13.43	93	193	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:5	19.09	2549	1.39	13.43	93	193	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:5	19.09	2548	1.39	13.44	93	193	Idle	61.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:5	19.09	2524	1.39	13.43	93	193	Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:6	19.09	2539	1.39	13.42	93	193	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:6	19.09	2538	1.39	13.42	93	193	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:6	19.09	2536	1.39	13.43	93	193	Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:6	19.09	2530	1.39	13.42	93	193	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:6	19.09	2526	1.39	13.43	94	193	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:6	19.09	2525	1.38	13.42	94	193	Idle	62.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:6	19.09	2513	1.38	13.42	94	193	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:7	19.09	2519	1.38	13.42	93	193	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:7	19.09	2519	1.38	13.42	93	193	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:7	19.09	2519	1.38	13.42	93	193	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:7	19.09	2517	1.38	13.42	94	193	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:7	19.09	2517	1.38	13.42	94	193	Idle	63.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:7	19.09	2516	1.38	13.41	94	193	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:8	19.09	2516	1.38	13.41	94	193	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:8	19.09	2514	1.37	13.41	94	193	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:8	19.09	2511	1.37	13.41	94	193	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:8	19.09	2511	1.37	13.42	94	193	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:8	19.09	2507	1.37	13.42	94	193	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:8	19.09	2502	1.37	13.43	94	193	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:9	19.09	2499	1.37	13.42	93	193	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:9	19.09	2498	1.37	13.43	93	193	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:9	19.09	2494	1.37	13.42	93	193	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:9	19.09	2490	1.37	13.42	94	193	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:9	19.09	2488	1.37	13.41	94	193	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:9	19.09	2484	1.36	13.41	94	193	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:55:9	19.09	2482	1.36	13.42	93	193	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:0	19.09	2482	1.36	13.43	93	193	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:0	19.09	2480	1.36	13.42	93	193	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:0	19.09	2478	1.36	13.43	94	193	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:0	19.09	2479	1.35	13.42	94	193	Idle	64.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:0	19.09	2478	1.35	13.43	94	193	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:0	19.09	2474	1.35	13.44	93	193	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:1	19.09	2473	1.35	13.44	93	193	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:1	19.09	2469	1.35	13.44	93	193	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:1	19.09	2469	1.35	13.44	94	193	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:1	19.09	2465	1.35	13.43	94	193	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:1	19.09	2462	1.34	13.43	94	193	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:1	19.09	2461	1.34	13.42	93	193	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:1	19.09	2456	1.34	13.41	93	193	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:2	19.09	2450	1.34	13.42	93	193	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:56:2	19.09	2446	1.33	13.42	94	193	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:2	19.09	2435	1.33	13.43	94	193	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:2	19.09	2440	1.33	13.42	94	193	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:2	19.09	2433	1.33	13.43	93	193	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:2	19.09	2433	1.33	13.42	93	193	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:3	19.09	2432	1.32	13.41	94	193	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:3	19.09	2420	1.32	13.41	94	193	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:3	19.09	2427	1.32	13.42	94	193	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:3	17.72	2427	1.32	13.42	93	193	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:3	17.72	2427	1.31	13.43	93	193	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:3	17.72	2426	1.31	13.43	93	193	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:4	17.72	2422	1.31	13.43	94	193	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:4	17.72	2422	1.31	13.43	94	193	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:4	17.72	2399	1.3	13.44	94	193	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:4	17.72	2412	1.3	13.44	94	193	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:4	17.72	2412	1.3	13.44	94	193	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:4	17.72	2410	1.3	13.44	94	193	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:4	17.72	2405	1.3	13.43	94	193	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:5	17.72	2394	1.29	13.43	94	193	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:5	17.72	2384	1.29	13.43	94	193	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:5	17.72	2379	1.29	13.43	94	193	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:5	17.72	2368	1.29	13.42	94	193	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:5	17.72	2372	1.28	13.43	93	193	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:5	17.72	2367	1.28	13.43	93	193	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:6	17.72	2363	1.28	13.41	93	193	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:6	17.72	2360	1.28	13.42	93	193	Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:6	17.72	2360	1.28	13.42	93	193	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:6	17.72	2358	1.27	13.43	93	193	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:6	17.72	2358	1.27	13.44	93	193	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:6	17.72	2357	1.27	13.43	93	193	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:6	17.72	2354	1.27	13.43	93	193	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:7	17.72	2350	1.27	13.44	94	193	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:7	17.72	2347	1.26	13.42	94	193	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:7	17.72	2346	1.26	13.41	94	193	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:7	17.72	2340	1.26	13.42	93	193	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:7	17.72	2334	1.25	13.41	93	193	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:7	17.72	2334	1.25	13.43	94	193	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:8	17.72	2321	1.25	13.43	94	193	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:8	17.72	2323	1.24	13.42	94	193	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:8	17.72	2323	1.24	13.42	94	193	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:8	17.72	2327	1.24	13.42	94	193	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:8	17.72	2300	1.23	13.41	94	193	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:8	17.72	2314	1.23	13.41	93	193	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:9	17.72	2314	1.22	13.41	93	193	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:9	17.72	2311	1.22	13.41	93	193	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.26	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:9	17.72	2308	1.22	13.41	93	193	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:9	17.72	2306	1.21	13.41	93	193	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:9	17.72	2303	1.21	13.41	93	193	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:9	17.72	2298	1.2	13.42	94	193	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:56:9	17.72	2293	1.2	13.41	94	193	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:0	17.72	2290	1.19	13.41	94	193	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:0	17.72	2272	1.19	13.42	94	193	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:0	17.72	2251	1.19	13.42	94	193	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:0	17.72	2251	1.18	13.4	94	193	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:0	17.72	2226	1.18	13.4	94	193	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:0	17.72	2182	1.17	13.41	94	193	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:1	17.72	2160	1.17	13.42	94	193	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:1	17.72	2160	1.17	13.42	94	193	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:57:1	17.72	2122	1.16	13.42	94	193	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:1	17.72	2101	1.16	13.42	94	193	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:1	17.72	2101	1.16	13.41	94	193	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:1	17.72	2062	1.15	13.4	94	193	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:1	17.72	2039	1.15	13.4	93	193	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:2	17.72	2039	1.15	13.42	93	193	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:2	17.72	2000	1.15	13.43	93	193	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:2	17.72	1976	1.15	13.43	93	193	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:2	17.72	1976	1.15	13.43	93	193	Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:2	17.72	1937	1.15	13.43	93	193	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:2	17.72	1912	1.15	13.43	94	193	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:3	17.72	1891	1.15	13.41	94	193	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:3	17.72	1880	1.16	13.4	94	193	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:3	17.72	1848	1.16	13.39	93	193	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:3	17.72	1825	1.17	13.39	93	193	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.24	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:3	17.72	1825	1.17	13.39	93	193	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:3	17.72	1785	1.18	13.41	94	193	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:4	17.72	1758	1.19	13.39	94	193	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:4	17.72	1758	1.19	13.41	93	193	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:4	17.72	1734	1.2	13.41	93	193	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:4	17.72	1700	1.21	13.41	93	193	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:4	17.72	1700	1.21	13.42	93	193	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.22	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:4	17.72	1665	1.22	13.42	93	193	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:4	17.72	1629	1.23	13.41	93	193	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:5	17.72	1618	1.24	13.41	94	193	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:5	17.72	1618	1.25	13.41	94	193	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:5	17.72	1583	1.25	13.42	94	193	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.27	20.22	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:5	17.72	1552	1.26	13.41	93	193	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.22	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:5	17.72	1534	1.26	13.41	93	193	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:5	17.72	1528	1.27	13.4	93	193	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:6	17.72	1496	1.27	13.41	94	193	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.06	20.24	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:6	17.72	1470	1.27	13.41	94	193	Idle	67	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.97	20.23	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:6	17.72	1470	1.28	13.41	94	193	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.87	20.24	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:6	17.72	1444	1.28	13.41	94	193	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.82	20.24	1.38	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:6	17.72	1419	1.28	13.41	94	193	Idle	66.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.74	20.23	1.38	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:6	17.72	1419	1.28	13.39	94	193	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.64	20.24	1.38	4.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:6	17.72	1382	1.29	13.41	93	193	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.59	20.25	1.38	4.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:57:7	17.72	1365	1.29	13.39	93	193	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.5	20.25	1.38	4.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:57:7	17.72	1365	1.29	13.39	94	193	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.48	20.24	1.38	4.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:23:57:7	17.72	1321	1.29	13.4	94	193	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.38	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:57:7	17.72	1312	1.29	13.41	94	193	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.28	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:57:7	17.72	1312	1.28	13.41	94	193	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.25	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:57:7	17.72	1273	1.28	13.41	94	193	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.19	20.23	1.38	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:57:8	16.36	1256	1.28	13.41	94	193	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.23	1.38	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:57:8	16.36	1256	1.28	13.4	93	193	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.07	20.23	1.38	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:23:57:8	16.36	1271	1.27	13.4	93	193	Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.98	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:8	16.36	1277	1.27	13.4	93	193	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.9	20.22	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:8	16.36	1282	1.27	13.38	93	193	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.89	20.22	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:8	16.36	1282	1.26	13.4	93	193	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.91	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:9	16.36	1281	1.26	13.4	93	193	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.93	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:23:57:9	16.36	1294	1.25	13.41	94	193	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.98	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:57:9	16.36	1294	1.25	13.41	94	193	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.01	20.24	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:57:9	16.36	1313	1.23	13.42	93	193	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.09	20.24	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:23:57:9	16.36	1338	1.22	13.41	93	193	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.13	20.24	1.38	4.2	2	ON	28 Pin	OFF	Removed	Disabled
03:23:57:9	16.36	1359	1.2	13.41	93	193	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.21	20.24	1.38	4.2	2	ON	28 Pin	OFF	Removed	Disabled
03:23:57:9	14.99	1359	1.19	13.41	93	193	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.29	20.25	1.38	4.1	2	ON	28 Pin	OFF	Removed	Disabled
03:23:58:0	14.99	1403	1.17	13.41	93	193	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.35	20.25	1.38	4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:58:0	13.63	1470	1.15	13.41	93	193	Idle	82.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.43	20.25	1.38	4	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:58:0	13.63	1470	1.14	13.4	93	193	Idle	83.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.52	20.24	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:23:58:0	14.99	1540	1.12	13.41	93	193	Idle	84.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.65	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:58:0	14.99	1576	1.11	13.41	93	193	Idle	86	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.78	20.24	1.38	3.9	1.7	ON	28 Pin	OFF	Removed	Disabled
03:23:58:0	14.99	1626	1.09	13.41	94	193	Idle	86.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.93	20.24	1.38	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:58:1	14.99	1626	1.07	13.42	94	193	Idle	88	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.15	20.24	1.38	3.9	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:58:1	14.99	1666	1.06	13.42	93	193	Idle	88.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.26	20.24	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:58:1	16.36	1729	1.05	13.42	93	193	Idle	88.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.33	20.23	1.38	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:23:58:1	16.36	1740	1.03	13.42	93	193	Idle	89	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.53	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:58:1	16.36	1760	1.01	13.41	94	193	Idle	89.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.66	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:58:1	16.36	1829	1	13.4	94	193	Idle	89.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.76	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:58:1	16.36	1854	0.99	13.4	94	193	Idle	90	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.89	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:23:58:2	16.36	1872	0.98	13.39	93	193	Idle	90.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:58:2	16.36	1947	0.97	13.39	93	193	Idle	90.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.04	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:23:58:2	16.36	1975	0.96	13.39	93	193	Idle	90.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.11	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:2	17.72	2006	0.95	13.39	94	193	Idle	91.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:2	17.72	2066	0.94	13.39	94	193	Idle	91.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.26	20.24	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:2	17.72	2132	0.94	13.4	94	193	Idle	91.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.33	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:3	17.72	2207	0.93	13.4	94	193	Idle	91.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.43	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:3	17.72	2207	0.93	13.4	94	193	Idle	91.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.46	20.22	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:3	17.72	2288	0.92	13.41	94	193	Idle	90.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.52	20.21	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:3	17.72	2331	0.92	13.41	93	193	Idle	90.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.58	20.2	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:3	17.72	2352	0.91	13.41	93	193	Idle	89.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.66	20.13	1.37	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:3	17.72	2455	0.91	13.42	93	193	Idle	88	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.73	19.94	1.36	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:4	17.72	2496	0.91	13.42	93	193	Idle	86.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.78	19.77	1.35	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:4	17.72	2575	0.92	13.42	93	193	Idle	85.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.82	19.54	1.33	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:4	17.72	2575	0.92	13.42	93	193	Idle	83.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.85	19.29	1.31	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:4	17.72	2693	0.93	13.43	93	193	Idle	80	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.89	19.02	1.3	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:4	17.72	2725	0.94	13.43	93	193	Idle	77.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.9	18.72	1.28	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:4	17.72	2823	0.96	13.43	93	193	Idle	75.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.91	18.22	1.24	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:4	19.09	2830	0.97	13.42	94	193	Idle	72.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.89	17.87	1.22	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:5	19.09	2897	0.99	13.44	94	193	Idle	70.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.85	17.57	1.2	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:5	19.09	2934	1.01	13.44	94	193	Idle	67.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.81	17.31	1.18	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:5	19.09	2948	1.04	13.45	94	193	Idle	64.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.78	17.1	1.17	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:5	19.09	3019	1.07	13.44	94	193	Idle	62.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.71	16.93	1.15	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:5	19.09	3017	1.11	13.44	94	193	Idle	59.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.59	16.79	1.14	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:5	19.09	3059	1.15	13.45	94	193	Idle	57	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.54	16.66	1.13	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:6	19.09	3044	1.18	13.44	94	193	Idle	54.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.46	16.64	1.13	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:6	19.09	3015	1.22	13.45	94	193	Idle	52.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	16.69	1.14	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:6	19.09	2997	1.26	13.43	94	193	Idle	50.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	16.81	1.14	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:6	19.09	2989	1.3	13.45	94	193	Idle	49.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	17.03	1.16	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:6	19.09	2950	1.35	13.44	94	193	Idle	45.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	17.5	1.19	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:6	19.09	2918	1.39	13.43	93	193	Idle	44.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	17.68	1.2	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:6	19.09	2910	1.41	13.44	93	193	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	18.04	1.23	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:7	19.09	2882	1.44	13.45	93	192	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	18.43	1.26	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:7	19.09	2844	1.47	13.43	94	192	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	18.81	1.28	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:7	19.09	2850	1.5	13.43	94	192	Idle	40.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	18.99	1.29	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:7	19.09	2837	1.55	13.43	93	193	Idle	40.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	19.15	1.3	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:7	19.09	2840	1.56	13.43	93	193	Idle	39.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	19.47	1.33	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:7	19.09	2840	1.59	13.43	93	192	Idle	38.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	19.76	1.35	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:8	19.09	2823	1.62	13.43	94	192	Idle	38.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	19.99	1.36	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:8	19.09	2862	1.64	13.44	94	192	Idle	37.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.14	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:8	19.09	2876	1.66	13.43	94	193	Idle	37.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:8	19.09	2876	1.67	13.44	94	193	Idle	37.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:8	19.09	2876	1.69	13.43	93	193	Idle	36.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.52	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:8	19.09	2885	1.7	13.43	93	193	Idle	37	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:9	19.09	2884	1.71	13.43	94	193	Idle	37.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.48	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:9	19.09	2878	1.71	13.43	94	193	Idle	37.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.48	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:9	19.09	2875	1.71	13.43	94	193	Idle	37.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.48	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:58:9	19.09	2866	1.71	13.42	94	193	Idle	37.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.47	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:9	19.09	2861	1.72	13.42	94	193	Idle	38.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:9	19.09	2842	1.72	13.43	94	193	Idle	38.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:58:9	19.09	2827	1.72	13.42	93	193	Idle	39.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:0	19.09	2827	1.72	13.42	93	193	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:0	19.09	2816	1.72	13.44	93	193	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:0	19.09	2808	1.71	13.43	94	193	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:0	19.09	2807	1.71	13.44	94	192	Idle	42.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:0	19.09	2808	1.71	13.43	94	192	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:0	19.09	2812	1.71	13.44	94	192	Idle	43.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:1	19.09	2811	1.7	13.43	94	193	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:1	19.09	2814	1.7	13.43	94	193	Idle	43.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:1	19.09	2816	1.7	13.43	93	193	Idle	43.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:1	19.09	2816	1.69	13.43	93	192	Idle	43.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:1	19.09	2813	1.69	13.42	93	192	Idle	43.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:1	19.09	2813	1.69	13.44	94	192	Idle	44.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:1	19.09	2804	1.68	13.44	94	192	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:2	19.09	2793	1.68	13.44	93	192	Idle	44.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:2	19.09	2785	1.67	13.43	93	192	Idle	44.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:2	19.09	2782	1.67	13.44	93	192	Idle	44.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:2	19.09	2762	1.67	13.43	94	192	Idle	45.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:2	19.09	2750	1.66	13.42	94	192	Idle	45.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:2	19.09	2750	1.66	13.43	94	192	Idle	46.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.77	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:3	19.09	2742	1.66	13.43	94	192	Idle	46.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:3	19.09	2739	1.65	13.43	94	192	Idle	47.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:3	19.09	2739	1.65	13.43	94	192	Idle	47.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:3	19.09	2738	1.65	13.43	93	192	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:3	19.09	2740	1.64	13.43	93	192	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:3	19.09	2744	1.64	13.42	93	192	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:4	19.09	2744	1.64	13.43	93	192	Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:4	19.09	2746	1.64	13.43	93	193	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:4	19.09	2747	1.63	13.42	93	193	Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:4	19.09	2746	1.63	13.43	94	193	Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:4	19.09	2743	1.63	13.43	94	193	Idle	48.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:4	19.09	2737	1.62	13.43	94	193	Idle	48.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:4	19.09	2737	1.62	13.43	94	193	Idle	48.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:5	19.09	2724	1.62	13.43	94	193	Idle	48.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:5	19.09	2711	1.61	13.43	93	193	Idle	49	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:5	19.09	2698	1.61	13.41	93	193	Idle	49.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:5	19.09	2696	1.61	13.42	93	192	Idle	49.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:5	19.09	2685	1.6	13.41	93	192	Idle	50.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:5	19.09	2683	1.6	13.41	93	192	Idle	50.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:6	19.09	2674	1.6	13.42	93	192	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:6	19.09	2666	1.6	13.43	94	192	Idle	51.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:6	19.09	2659	1.59	13.43	94	192	Idle	51.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:6	19.09	2659	1.59	13.42	94	192	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:6	19.09	2656	1.59	13.44	93	192	Idle	51.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:6	19.09	2654	1.58	13.43	93	193	Idle	51.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:6	19.09	2654	1.58	13.43	93	193	Idle	51.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:7	19.09	2654	1.57	13.41	94	193	Idle	51.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:7	19.09	2652	1.57	13.42	94	192	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:7	19.09	2650	1.57	13.43	94	192	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:7	19.09	2650	1.56	13.42	94	192	Idle	51.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:7	19.09	2645	1.56	13.42	94	192	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:7	19.09	2638	1.56	13.41	94	192	Idle	52.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:8	19.09	2638	1.55	13.43	94	192	Idle	53.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:8	19.09	2628	1.55	13.41	94	192	Idle	53.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:8	19.09	2621	1.55	13.42	93	192	Idle	53.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:23:59:8	19.09	2602	1.54	13.44	93	192	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:8	19.09	2602	1.53	13.44	93	192	Idle	54.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:8	19.09	2594	1.53	13.45	93	192	Idle	55.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:9	19.09	2586	1.53	13.45	93	192	Idle	55.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:9	19.09	2580	1.52	13.44	93	192	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:9	19.09	2580	1.52	13.45	93	192	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:9	19.09	2574	1.51	13.45	93	192	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:9	19.09	2572	1.51	13.44	94	192	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:9	19.09	2570	1.5	13.42	94	192	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:23:59:9	19.09	2570	1.5	13.42	93	192	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:0	19.09	2557	1.5	13.41	93	192	Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:0	19.09	2564	1.49	13.41	93	192	Idle	57.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:0	19.09	2573	1.49	13.42	93	192	Idle	57.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:0	19.09	2556	1.48	13.42	93	192	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:0	19.09	2551	1.48	13.41	93	192	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:0	19.09	2539	1.48	13.42	94	192	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:1	19.09	2538	1.47	13.42	94	192	Idle	57.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:1	19.09	2526	1.47	13.44	94	192	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:1	19.09	2514	1.47	13.42	94	192	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:1	19.09	2510	1.46	13.43	94	192	Idle	58.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:1	19.09	2508	1.46	13.43	94	192	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:1	19.09	2502	1.46	13.43	93	192	Idle	59.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:1	19.09	2481	1.45	13.42	93	192	Idle	59.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:2	19.09	2483	1.45	13.44	93	192	Idle	59.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:2	19.09	2480	1.44	13.43	94	192	Idle	60.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:2	19.09	2480	1.44	13.42	94	192	Idle	60.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:2	19.09	2479	1.44	13.41	94	192	Idle	60.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:2	19.09	2480	1.43	13.42	94	192	Idle	60.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.25	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:2	19.09	2480	1.43	13.42	94	192	Idle	61.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:3	19.09	2479	1.42	13.43	94	193	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:3	19.09	2480	1.42	13.42	93	193	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:3	19.09	2479	1.41	13.43	93	193	Idle	61.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:3	19.09	2479	1.41	13.43	94	192	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:3	19.09	2476	1.41	13.42	94	192	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:3	19.09	2472	1.4	13.43	94	192	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:4	19.09	2468	1.4	13.42	94	192	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:4	19.09	2452	1.39	13.41	94	192	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:4	19.09	2455	1.39	13.42	94	192	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:4	19.09	2455	1.38	13.42	94	192	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:4	19.09	2435	1.38	13.42	94	192	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:4	19.09	2424	1.37	13.43	94	192	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:4	19.09	2424	1.37	13.43	94	192	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:5	19.09	2415	1.36	13.43	94	192	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:5	19.09	2391	1.36	13.42	94	192	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:5	17.72	2389	1.35	13.43	93	192	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:5	17.72	2398	1.35	13.42	93	192	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:5	17.72	2392	1.35	13.42	93	192	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:5	17.72	2390	1.34	13.42	94	192	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:6	17.72	2385	1.34	13.42	94	192	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:6	17.72	2380	1.33	13.43	93	192	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:6	17.72	2375	1.33	13.43	93	192	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:6	17.72	2374	1.33	13.42	93	192	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:6	17.72	2368	1.32	13.43	93	192	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:6	17.72	2364	1.32	13.43	93	192	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:6	17.72	2364	1.31	13.43	93	192	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:7	17.72	2357	1.31	13.43	93	192	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:7	17.72	2352	1.31	13.43	93	192	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:7	17.72	2352	1.31	13.43	93	192	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:00:7	17.72	2346	1.3	13.43	94	192	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:7	17.72	2340	1.3	13.43	94	192	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:7	17.72	2333	1.29	13.43	94	192	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:8	17.72	2333	1.29	13.41	93	192	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:8	17.72	2320	1.28	13.42	93	192	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:8	17.72	2325	1.28	13.42	94	192	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.25	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:8	17.72	2331	1.28	13.42	94	192	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:8	17.72	2318	1.27	13.42	94	192	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:8	17.72	2318	1.27	13.42	94	192	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:9	17.72	2293	1.26	13.42	94	192	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:9	17.72	2299	1.25	13.42	94	192	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:9	17.72	2296	1.24	13.42	93	192	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:9	17.72	2288	1.24	13.42	93	192	Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:9	17.72	2286	1.23	13.41	93	192	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:9	17.72	2281	1.22	13.41	94	192	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:00:9	17.72	2276	1.22	13.43	94	192	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:0	17.72	2274	1.21	13.42	94	192	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:0	17.72	2266	1.2	13.41	93	192	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:0	17.72	2261	1.2	13.41	93	192	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:0	17.72	2257	1.19	13.42	93	192	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:0	17.72	2256	1.18	13.42	93	192	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:0	17.72	2248	1.18	13.42	93	192	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:1	17.72	2227	1.17	13.42	93	192	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:1	17.72	2234	1.17	13.41	93	192	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:1	17.72	2237	1.16	13.41	93	192	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:1	17.72	2235	1.16	13.41	93	192	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:1	17.72	2232	1.15	13.41	93	192	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:1	17.72	2222	1.15	13.4	93	192	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:1	17.72	2197	1.15	13.4	94	192	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:2	17.72	2209	1.14	13.42	94	192	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:2	17.72	2206	1.14	13.42	94	192	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:2	17.72	2202	1.14	13.42	93	192	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:2	17.72	2185	1.14	13.42	93	192	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:2	17.72	2185	1.13	13.42	93	192	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:2	17.72	2171	1.13	13.41	94	192	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:3	17.72	2172	1.12	13.41	94	192	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:3	17.72	2171	1.12	13.41	94	192	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:3	17.72	2165	1.12	13.42	94	192	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:3	17.72	2160	1.11	13.42	94	192	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:3	17.72	2160	1.11	13.42	94	192	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:3	17.72	2155	1.1	13.42	94	192	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:4	17.72	2149	1.1	13.43	94	192	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:4	17.72	2147	1.1	13.41	93	192	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:4	17.72	2145	1.09	13.41	93	192	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:4	17.72	2139	1.09	13.42	93	192	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:4	17.72	2134	1.09	13.42	94	192	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:4	17.72	2132	1.08	13.41	94	192	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:4	17.72	2125	1.08	13.43	94	192	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:5	17.72	2110	1.08	13.44	93	192	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:5	17.72	2110	1.07	13.44	93	192	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:5	17.72	2110	1.07	13.44	93	192	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:5	17.72	2100	1.06	13.45	94	192	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:5	17.72	2092	1.06	13.45	94	192	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:5	17.72	2092	1.06	13.44	94	192	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:6	17.72	2083	1.06	13.44	93	192	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:6	17.72	2078	1.05	13.44	93	192	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:6	17.72	2073	1.05	13.44	94	192	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:6	17.72	2071	1.05	13.44	94	192	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:01:6	17.72	2064	1.05	13.44	94	192	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:6	17.72	2058	1.05	13.45	94	192	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:6	17.72	2039	1.04	13.43	94	192	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:7	17.72	2050	1.04	13.42	94	192	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:7	17.72	2056	1.04	13.42	94	192	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:7	17.72	2052	1.04	13.42	94	192	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:7	17.72	2038	1.03	13.42	94	192	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:7	17.72	2017	1.03	13.43	94	192	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:7	17.72	2022	1.03	13.44	94	192	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:8	17.72	2021	1.03	13.45	94	192	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:8	17.72	2016	1.03	13.44	94	192	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:8	17.72	2014	1.03	13.45	94	192	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:8	17.72	2004	1.03	13.45	94	192	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:8	17.72	1997	1.03	13.45	94	192	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:8	17.72	1990	1.03	13.44	94	192	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:9	17.72	1990	1.03	13.44	94	192	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:9	17.72	1980	1.03	13.44	94	192	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:9	17.72	1972	1.03	13.42	94	192	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:9	17.72	1960	1.03	13.42	93	192	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:9	17.72	1953	1.02	13.42	93	192	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:9	17.72	1948	1.02	13.42	93	192	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:01:9	17.72	1948	1.02	13.41	93	192	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:0	17.72	1938	1.02	13.42	93	192	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:0	17.72	1927	1.02	13.43	93	192	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:0	17.72	1927	1.02	13.42	94	192	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:0	17.72	1916	1.02	13.41	94	192	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:0	17.72	1905	1.02	13.41	94	192	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:0	17.72	1896	1.02	13.41	94	192	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:1	17.72	1896	1.02	13.41	94	192	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:1	17.72	1884	1.02	13.42	94	192	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:1	17.72	1873	1.02	13.43	93	192	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:1	17.72	1864	1.02	13.42	93	192	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:1	17.72	1860	1.02	13.41	93	192	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:1	17.72	1851	1.02	13.4	94	192	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.25	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:1	17.72	1829	1.03	13.39	94	192	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:2	17.72	1832	1.03	13.39	94	192	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:2	17.72	1831	1.03	13.39	94	192	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:2	17.72	1820	1.03	13.39	94	192	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:2	17.72	1820	1.03	13.39	94	192	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:2	17.72	1810	1.03	13.39	94	192	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:2	17.72	1802	1.03	13.4	94	192	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:3	17.72	1791	1.03	13.41	94	192	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:3	17.72	1791	1.03	13.41	94	192	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:3	17.72	1780	1.03	13.41	94	192	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:3	17.72	1779	1.04	13.41	93	192	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:3	17.72	1759	1.04	13.41	93	192	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:3	17.72	1759	1.04	13.41	93	192	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.24	1.38	3.8	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:4	17.72	1748	1.04	13.4	94	192	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:4	17.72	1734	1.04	13.4	94	192	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.23	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:4	17.72	1726	1.04	13.4	94	192	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.24	1.38	3.9	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:4	17.72	1700	1.04	13.41	94	192	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.19	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:4	17.72	1678	1.04	13.41	94	192	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.19	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:4	17.72	1642	1.04	13.41	94	192	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.19	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:4	17.72	1642	1.04	13.41	94	192	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.19	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:5	17.72	1631	1.04	13.41	94	192	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.2	1.38	4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:5	17.72	1608	1.04	13.41	94	192	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.2	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:5	17.72	1596	1.04	13.41	94	192	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.2	1.38	4.1	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:5	17.72	1570	1.04	13.41	94	192	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.2	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:02:8	17.72	1532	1.04	13.41	94	192	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.19	1.38	4.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:8	17.72	1495	1.05	13.41	94	192	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:6	17.72	1495	1.05	13.4	94	192	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:6	17.72	1480	1.06	13.41	94	192	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:6	17.72	1453	1.06	13.41	94	192	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.08	1.37	4.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:6	17.72	1453	1.07	13.41	93	192	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.52	20.09	1.37	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:6	17.72	1426	1.07	13.42	93	192	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.45	20.09	1.37	4.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:6	17.72	1388	1.08	13.41	93	192	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.33	20.08	1.37	4.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:6	17.72	1385	1.09	13.41	93	192	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.28	20.08	1.37	4.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:7	17.72	1342	1.1	13.4	93	192	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.18	20.09	1.37	4.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:7	19.09	1342	1.11	13.41	94	192	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	20.08	1.37	4.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:7	19.09	1295	1.12	13.41	94	192	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	20.08	1.37	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:02:7	19.09	1295	1.13	13.41	94	192	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	20.09	1.37	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:02:7	16.36	1286	1.14	13.41	94	192	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	20.09	1.37	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:02:7	16.36	1262	1.15	13.41	94	192	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.67	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:02:8	16.36	1236	1.15	13.41	94	192	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.57	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:02:8	16.36	1226	1.16	13.41	93	192	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.47	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:02:8	16.36	1226	1.17	13.41	93	192	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.34	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:02:8	16.36	1195	1.17	13.41	93	192	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.25	20.22	1.38	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:02:8	16.36	1164	1.18	13.41	93	192	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.2	20.22	1.38	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:02:8	16.36	1171	1.18	13.41	93	192	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.12	20.22	1.38	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:02:9	16.36	1171	1.18	13.41	93	192	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.02	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:9	16.36	1176	1.18	13.41	94	192	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.98	20.23	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:9	16.36	1176	1.18	13.41	94	192	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.92	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:9	16.36	1182	1.18	13.41	94	192	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.87	20.21	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:9	14.99	1176	1.18	13.43	94	192	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.85	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:9	14.99	1171	1.18	13.41	94	192	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.86	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:02:9	14.99	1189	1.17	13.4	94	192	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.84	20.22	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:0	14.99	1189	1.17	13.4	94	192	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.87	20.22	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:0	14.99	1191	1.16	13.41	94	192	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.85	20.22	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:0	14.99	1188	1.14	13.41	94	192	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.89	20.22	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:0	14.99	1188	1.14	13.4	94	192	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.93	20.22	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:0	14.99	1205	1.12	13.41	94	192	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.97	20.22	1.38	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:0	14.99	1201	1.11	13.41	94	192	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8	20.23	1.38	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:1	14.99	1199	1.1	13.4	94	192	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.05	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:1	13.63	1199	1.09	13.4	94	192	Idle	84.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.07	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:1	13.63	1198	1.08	13.41	94	192	Idle	85	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.1	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:1	13.63	1197	1.07	13.4	94	192	Idle	85.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.14	20.22	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:1	12.27	1187	1.06	13.4	94	192	Idle	86.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.19	20.22	1.38	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:1	12.27	1182	1.05	13.41	93	192	Idle	86.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.21	20.22	1.38	4.3	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:1	12.27	1186	1.04	13.41	93	192	Idle	86.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.25	20.22	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:2	13.63	1186	1.03	13.41	93	192	Idle	87	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.27	20.22	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:2	13.63	1173	1.02	13.41	94	192	Idle	87.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.28	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:2	13.63	1147	1.01	13.4	94	192	Idle	87.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.26	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:2	13.63	1133	1	13.41	94	192	Idle	87.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.27	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:2	13.63	1133	0.99	13.4	94	192	Idle	87.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:2	13.63	1122	0.98	13.39	94	192	Idle	88.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.34	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:3	13.63	1122	0.97	13.41	94	192	Idle	88.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.33	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:3	13.63	1111	0.97	13.39	94	192	Idle	88.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.35	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:3	13.63	1111	0.96	13.41	94	192	Idle	88.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.35	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:3	13.63	1109	0.96	13.4	94	192	Idle	88.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.32	20.22	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:3	13.63	1109	0.96	13.41	94	192	Idle	88.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	20.22	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:3	12.27	1095	0.95	13.4	94	192	Idle	88.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	20.22	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:4	12.27	1095	0.95	13.4	94	192	Idle	88.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.36	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:4	12.27	1095	0.95	13.4	94	192	Idle	88.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:4	12.27	1082	0.95	13.4	94	192	Idle	89	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.33	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:4	12.27	1066	0.94	13.41	94	192	Idle	89.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:4	12.27	1061	0.94	13.41	94	192	Idle	89.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	20.22	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:03:4	12.27	1047	0.94	13.41	94	192	Idle	89.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.32	20.21	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:4	12.27	1047	0.94	13.41	94	192	Idle	89.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	20.21	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:5	12.27	1041	0.93	13.41	93	192	Idle	90	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	20.22	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:5	12.27	1041	0.93	13.41	93	192	Idle	90.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.27	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:5	12.27	1030	0.93	13.41	93	192	Idle	90.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.28	20.13	1.37	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:5	12.27	1019	0.92	13.41	93	192	Idle	90.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.26	19.97	1.36	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:5	12.27	1014	0.92	13.4	93	192	Idle	90.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.28	19.81	1.35	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:5	12.27	1014	0.92	13.41	93	192	Idle	90.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.24	19.71	1.34	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:6	10.9	1000	0.91	13.4	94	192	Idle	90	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.26	19.34	1.32	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:6	10.9	999	0.91	13.41	94	192	Idle	90.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.25	19.03	1.3	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:03:6	10.9	999	0.91	13.4	94	192	Idle	90.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	18.86	1.28	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:6	10.9	987	0.91	13.42	94	192	Idle	89.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.18	18.33	1.25	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:6	10.9	975	0.91	13.41	94	192	Idle	89.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.09	17.97	1.22	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:6	10.9	975	0.91	13.42	94	192	Idle	89.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.09	17.59	1.2	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:6	10.9	961	0.9	13.42	94	192	Idle	89.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.01	17.3	1.18	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:7	10.9	967	0.9	13.41	94	192	Idle	89.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.03	17.08	1.16	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:7	10.9	967	0.9	13.41	94	192	Idle	89.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.97	16.75	1.14	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:7	10.9	967	0.9	13.4	93	192	Idle	89	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8	16.58	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:7	10.9	959	0.9	13.41	93	192	Idle	89	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.95	16.47	1.12	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:7	10.9	943	0.9	13.41	93	192	Idle	89.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.98	16.39	1.12	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:7	10.9	943	0.9	13.4	94	192	Idle	89.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.9	16.34	1.11	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:8	10.9	940	0.9	13.41	94	192	Idle	89.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.92	16.3	1.11	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:03:8	10.9	938	0.9	13.41	94	192	Idle	90	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.86	16.25	1.11	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:8	10.9	935	0.9	13.41	94	192	Idle	90.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.85	16.21	1.1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:8	9.54	935	0.89	13.41	94	192	Idle	90.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.85	16.2	1.1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:8	9.54	938	0.89	13.4	94	192	Idle	91.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.85	16.18	1.1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:8	9.54	940	0.89	13.41	94	192	Idle	91.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.81	16.19	1.1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:9	9.54	927	0.89	13.4	94	192	Idle	92	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.82	16.18	1.1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:9	9.54	927	0.89	13.41	94	192	Idle	92.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.79	16.17	1.1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:9	9.54	924	0.89	13.41	93	192	Idle	92.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.82	16.16	1.1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:9	9.54	921	0.89	13.41	93	192	Idle	92.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.77	16.16	1.1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:9	9.54	921	0.88	13.41	93	192	Idle	92.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.79	16.15	1.1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:9	9.54	921	0.88	13.42	94	192	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.76	16.15	1.1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:03:9	9.54	921	0.88	13.41	94	192	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.77	16.13	1.1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:0	9.54	930	0.88	13.41	94	192	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.72	16.01	1.09	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:0	9.54	930	0.87	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	16	1.09	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:0	8.18	920	0.87	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.77	15.99	1.09	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:0	8.18	920	0.87	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.82	15.95	1.09	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:0	8.18	930	0.87	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.76	15.94	1.09	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:0	8.18	930	0.86	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.79	15.91	1.08	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:1	8.18	936	0.86	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	15.89	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:1	8.18	936	0.86	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.77	15.85	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:1	8.18	930	0.86	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.74	15.84	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:1	8.18	925	0.85	13.43	94	192	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.77	15.93	1.09	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:1	9.54	920	0.85	13.41	93	192	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.75	15.89	1.08	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:1	9.54	920	0.85	13.42	93	192	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.74	15.84	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:1	9.54	913	0.85	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.71	15.82	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:2	9.54	913	0.85	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.73	15.81	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:2	9.54	913	0.85	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.71	15.79	1.08	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:2	9.54	930	0.84	13.41	93	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.75	15.78	1.08	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:2	9.54	932	0.84	13.39	93	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	15.78	1.07	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:2	9.54	932	0.84	13.41	93	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	15.77	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:2	8.18	925	0.84	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.74	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:3	8.18	925	0.84	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.74	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:3	8.18	923	0.84	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.72	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:3	8.18	921	0.84	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.72	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:3	8.18	924	0.84	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.69	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:3	8.18	924	0.84	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.67	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:04:3	8.18	926	0.84	13.38	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.64	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:4	8.18	927	0.84	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	15.63	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:4	9.54	905	0.84	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.57	1.06	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:4	9.54	905	0.84	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.54	1.06	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:4	9.54	905	0.83	13.43	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.51	1.06	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:4	9.54	899	0.83	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.5	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:4	9.54	922	0.83	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.48	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:4	8.18	922	0.83	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	15.44	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:5	8.18	922	0.83	13.42	93	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	15.4	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:5	8.18	907	0.83	13.42	93	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.38	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:5	8.18	898	0.83	13.43	93	192	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.33	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:5	8.18	889	0.83	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	15.29	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:5	8.18	889	0.83	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.75	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:04:5	8.18	893	0.83	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	15.21	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:6	8.18	893	0.83	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.72	15.17	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:6	9.54	898	0.83	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.7	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:6	9.54	904	0.83	13.43	94	192	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.74	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:6	9.54	891	0.83	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.7	15.05	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:6	9.54	891	0.83	13.43	94	192	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.7	15.03	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:6	8.18	891	0.83	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	15	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:6	8.18	891	0.83	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.69	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:7	8.18	890	0.83	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.66	14.98	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:7	8.18	890	0.83	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.63	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:7	9.54	894	0.83	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.62	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:7	9.54	898	0.83	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.63	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:7	9.54	898	0.83	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.68	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:7	9.54	879	0.83	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.92	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:8	9.54	879	0.83	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.66	14.92	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:8	8.18	900	0.83	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.92	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:8	8.18	900	0.82	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.92	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:8	8.18	889	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	14.91	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:8	8.18	906	0.82	13.41	93	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.9	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:8	9.54	906	0.82	13.4	93	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.9	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:9	9.54	906	0.82	13.41	93	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.91	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:9	9.54	909	0.82	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:9	9.54	909	0.82	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.94	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:9	9.54	869	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	14.94	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:9	9.54	869	0.82	13.43	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.65	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:9	9.54	869	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.94	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:04:9	9.54	894	0.82	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.64	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:0	9.54	892	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.61	14.96	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:0	9.54	892	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.61	14.97	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:0	9.54	898	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.65	14.98	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:0	9.54	904	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.62	14.99	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:0	9.54	909	0.82	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.66	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:0	9.54	909	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.67	15.02	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:1	9.54	905	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.67	15.04	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:1	9.54	905	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.66	15.06	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:1	6.81	902	0.82	13.4	93	192	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.67	15.08	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:1	6.81	898	0.82	13.41	93	192	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.62	15.09	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:1	6.81	898	0.82	13.41	93	192	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.66	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:1	6.81	914	0.82	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.63	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:1	6.81	914	0.82	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.66	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:2	8.18	886	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.68	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:2	8.18	886	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:2	8.18	890	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.66	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:2	8.18	890	0.82	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.66	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:2	8.18	893	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.62	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:05:2	8.18	896	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.66	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:3	8.18	898	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.64	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:3	8.18	898	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.66	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:3	8.18	898	0.82	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.67	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:3	8.18	898	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.66	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:3	8.18	897	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.68	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:3	8.18	897	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.64	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:4	8.18	896	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:4	8.18	894	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.67	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:4	8.18	894	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:4	8.18	891	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:4	8.18	888	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:4	9.54	884	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.62	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:4	9.54	884	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:5	9.54	867	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:5	9.54	867	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:5	8.18	881	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:5	8.18	895	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:5	8.18	885	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.62	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:5	8.18	885	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:6	8.18	882	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.62	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:6	8.18	878	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.6	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:6	8.18	878	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.6	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:6	8.18	887	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:6	9.54	884	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.61	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:6	9.54	880	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.56	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:6	9.54	880	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	14.94	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:7	9.54	881	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:7	9.54	888	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	14.94	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:7	9.54	896	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.61	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:7	9.54	896	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:7	9.54	886	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:7	9.54	886	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.6	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:8	8.18	876	0.81	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.57	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:8	8.18	876	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.58	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:8	8.18	888	0.81	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.58	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:8	8.18	888	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.59	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:8	8.18	888	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.61	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:8	8.18	873	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.59	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:9	8.18	866	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.63	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:05:9	8.18	859	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.58	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:9	8.18	859	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.58	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:9	10.9	869	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.57	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:9	10.9	857	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.57	14.9	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:9	10.9	857	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.56	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:05:9	10.9	857	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.57	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:0	9.54	866	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.55	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:0	9.54	866	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.55	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:0	9.54	873	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.57	14.84	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:0	9.54	873	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.52	14.85	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:0	9.54	866	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:0	9.54	860	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.52	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:1	9.54	868	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:1	9.54	868	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.48	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:1	9.54	868	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.52	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:1	9.54	865	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.51	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:1	9.54	865	0.81	13.43	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.54	14.88	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:1	9.54	863	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.52	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:06:1	9.54	861	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.54	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:2	9.54	880	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.52	14.89	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:2	9.54	880	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.51	14.91	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:2	9.54	879	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.52	14.92	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:2	9.54	878	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.49	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:2	9.54	881	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.53	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:2	10.9	881	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.49	14.98	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:3	10.9	878	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.51	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:3	10.9	875	0.81	13.43	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.48	15	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:3	10.9	875	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.48	15.02	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:3	9.54	898	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.49	15.04	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:3	9.54	898	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.56	15.05	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:3	9.54	901	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.54	15.06	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:4	9.54	904	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.6	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:4	9.54	902	0.81	13.43	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.57	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:4	9.54	902	0.81	13.45	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:4	9.54	906	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.57	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:4	9.54	906	0.81	13.43	94	192	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	15.12	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:4	8.18	906	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	15.12	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:4	8.18	906	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.59	15.14	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:5	8.18	909	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.58	15.16	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:5	8.18	909	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.59	15.17	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:5	8.18	892	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.62	15.19	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:5	8.18	892	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.64	15.17	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:5	8.18	893	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.62	15.21	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:5	8.18	893	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.64	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:6	8.18	893	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.64	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:6	8.18	899	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.6	15.27	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:6	8.18	903	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.63	15.28	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:6	8.18	903	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.59	15.29	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:6	8.18	903	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.65	15.3	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:6	8.18	897	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.64	15.3	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:6	8.18	897	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.67	15.3	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:7	8.18	893	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.64	15.2	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:7	8.18	893	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.68	15.2	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:7	8.18	894	0.81	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.62	15.19	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:7	8.18	894	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.63	15.19	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:7	8.18	884	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.66	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:7	8.18	884	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.66	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:8	8.18	885	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.68	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:8	8.18	886	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.68	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:06:8	8.18	892	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.66	15.12	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:8	8.18	892	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.65	15.21	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:8	8.18	890	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.61	15.17	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:8	8.18	888	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.61	15.16	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:9	8.18	884	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.61	15.15	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:9	8.18	884	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.6	15.12	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:9	8.18	891	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.61	15.1	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:9	8.18	891	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.59	15.08	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:9	8.18	891	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.58	15.07	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:9	8.18	887	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.57	15.06	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:06:9	8.18	882	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.6	15.06	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:0	8.18	882	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.58	15.06	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:0	8.18	882	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.62	15.06	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:0	8.18	890	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.61	15.05	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:0	8.18	890	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.62	15.04	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:0	8.18	880	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.58	15.04	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:0	8.18	871	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.58	15.04	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:07:1	8.18	871	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.61	15.03	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:1	8.18	885	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.57	15.02	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:1	6.81	882	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.58	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:1	6.81	882	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.58	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:1	6.81	882	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.6	14.99	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:1	6.81	893	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.59	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:1	6.81	876	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.62	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:2	6.81	876	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.6	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:2	6.81	876	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.63	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:2	6.81	880	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.7	-7.59	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:2	6.81	880	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.6	15	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:2	9.54	887	0.81	13.38	94	191	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.55	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:2	9.54	887	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.57	15	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:3	9.54	887	0.81	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.58	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:3	9.54	872	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.58	15	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:3	9.54	872	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	15	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:3	9.54	872	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.58	15.01	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:3	9.54	872	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.58	15.01	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:3	9.54	877	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.55	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:4	9.54	889	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:4	9.54	889	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.54	15.01	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:4	9.54	889	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.57	15.02	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:07:4	9.54	905	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.56	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:4	9.54	905	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.59	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:4	9.54	901	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.57	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:4	9.54	901	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.59	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:5	9.54	914	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.58	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:5	9.54	914	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.61	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:5	8.18	904	0.81	13.38	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.61	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:5	8.18	904	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.64	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:5	8.18	919	0.81	13.38	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.62	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:5	8.18	919	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.66	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:6	8.18	911	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:6	8.18	903	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:6	8.18	899	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:6	8.18	899	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:6	8.18	904	0.81	13.38	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:6	8.18	910	0.81	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:6	8.18	910	0.81	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:7	8.18	897	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:7	8.18	904	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:7	8.18	904	0.81	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:7	8.18	904	0.81	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:7	8.18	910	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:7	8.18	918	0.81	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:8	8.18	918	0.81	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:8	8.18	918	0.81	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:8	8.18	897	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:8	8.18	892	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:8	8.18	892	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:8	8.18	900	0.81	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:9	8.18	909	0.81	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:9	8.18	909	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:9	8.18	887	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:9	8.18	893	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:9	8.18	899	0.82	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:9	8.18	899	0.82	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:07:9	8.18	890	0.82	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:08:0	8.18	890	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:0	8.18	890	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:0	8.18	896	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:0	9.54	883	0.82	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:0	9.54	883	0.82	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:0	9.54	885	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:1	9.54	887	0.82	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:1	9.54	887	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:1	8.18	880	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:1	8.18	888	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:1	8.18	897	0.82	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.83	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:1	8.18	897	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.84	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:1	8.18	873	0.82	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	14.84	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:2	8.18	873	0.82	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:2	8.18	892	0.82	13.38	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.62	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:2	8.18	892	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:2	9.54	882	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.66	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:2	9.54	882	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:2	9.54	880	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:3	9.54	880	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:3	8.18	892	0.82	13.38	94	192	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.7	14.85	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:3	8.18	904	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.64	14.85	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:3	8.18	904	0.82	13.39	94	191	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.67	14.85	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:3	8.18	898	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.63	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:3	8.18	898	0.82	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.66	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:4	8.18	898	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.63	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:4	8.18	899	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.66	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:4	8.18	892	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.62	14.88	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:4	8.18	892	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.64	14.89	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:4	8.18	892	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.63	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:4	8.18	891	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.68	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:4	8.18	895	0.82	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.66	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:5	8.18	895	0.82	13.42	94	191	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.67	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:5	8.18	888	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.63	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:5	8.18	880	0.82	13.42	94	191	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.64	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:5	8.18	883	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.63	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:5	8.18	883	0.82	13.42	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.59	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:5	8.18	884	0.82	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.63	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:6	8.18	884	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.61	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:6	8.18	892	0.82	13.4	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:6	8.18	899	0.82	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:6	8.18	900	0.82	13.4	94	191	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:6	9.54	900	0.82	13.41	94	191	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:6	9.54	886	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.84	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:6	9.54	873	0.82	13.39	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	14.87	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:7	9.54	873	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:7	8.18	889	0.82	13.41	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:7	8.18	889	0.82	13.44	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:7	8.18	886	0.82	13.46	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:7	8.18	884	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:7	8.18	873	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:8	8.18	873	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:8	8.18	873	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.6	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:8	8.18	866	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.58	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:8	9.54	902	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	14.97	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:8	9.54	902	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.55	14.96	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:8	9.54	902	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.59	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:08:9	9.54	893	0.82	13.48	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.57	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:08:9	9.54	881	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.59	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:9	9.54	881	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.57	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:9	9.54	881	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.6	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:9	9.54	877	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.59	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:9	9.54	877	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.6	14.93	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:08:9	8.18	901	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.59	14.94	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:0	8.18	901	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.6	14.95	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:0	8.18	907	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:0	8.18	907	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.6	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:0	9.54	896	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:0	9.54	896	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.6	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:0	9.54	896	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:1	9.54	896	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:1	9.54	896	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:1	9.54	913	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:1	9.54	909	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:1	9.54	909	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:1	9.54	909	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:1	8.18	936	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:2	8.18	912	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.72	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:2	8.18	912	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.68	14.89	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:09:2	8.18	916	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	14.88	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:09:2	8.18	920	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:09:2	8.18	920	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:09:2	8.18	905	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:3	8.18	905	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:3	8.18	894	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:3	8.18	882	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.71	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:3	8.18	890	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.67	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:3	8.18	890	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:3	8.18	892	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:4	8.18	893	0.82	13.51	93	191	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.7	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:4	8.18	893	0.82	13.49	93	191	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.73	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:4	8.18	892	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.72	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:4	8.18	888	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.7	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:4	8.18	888	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:4	8.18	888	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.6	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:4	8.18	894	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.59	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:09:5	8.18	901	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.63	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:09:5	8.18	901	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.65	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:09:5	8.18	901	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:09:5	8.18	897	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:5	8.18	897	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:5	8.18	889	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:6	8.18	889	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:6	8.18	891	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:09:6	8.18	891	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:09:6	9.54	909	0.82	13.48	94	191	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:09:6	9.54	909	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:09:6	9.54	909	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:09:6	9.54	898	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:7	8.18	899	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:7	8.18	899	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:7	8.18	899	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:7	8.18	901	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:7	8.18	905	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:7	8.18	905	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:8	8.18	903	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:09:8	8.18	901	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:8	8.18	901	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:8	8.18	919	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:8	8.18	910	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:8	8.18	902	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:9	8.18	902	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:9	8.18	911	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:9	8.18	906	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.73	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:9	8.18	900	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.68	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:9	8.18	900	0.82	13.54	94	191	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.74	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:9	8.18	904	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.72	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:09:9	8.18	904	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.73	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:0	8.18	898	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.7	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:0	8.18	898	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.71	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:0	8.18	900	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:0	8.18	902	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:0	8.18	901	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:0	8.18	901	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.68	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:1	8.18	896	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:1	8.18	891	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:1	8.18	894	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:1	8.18	894	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:1	8.18	899	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.68	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:1	8.18	899	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:1	8.18	899	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.75	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:2	8.18	895	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:2	8.18	895	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.75	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:2	8.18	892	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.71	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:2	8.18	888	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.74	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:2	8.18	893	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:2	8.18	893	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:3	8.18	903	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:3	8.18	903	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:3	8.18	904	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.66	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:3	8.18	906	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:3	8.18	901	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:3	8.18	901	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:4	8.18	900	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:4	8.18	900	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:4	8.18	903	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:4	8.18	903	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:4	8.18	902	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:4	8.18	901	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:4	8.18	901	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:5	8.18	893	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:5	8.18	893	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:5	8.18	893	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:5	8.18	893	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:5	8.18	890	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:5	8.18	890	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:6	8.18	884	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.66	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:10:6	8.18	879	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	14.82	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:10:6	8.18	877	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.67	14.81	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:10:6	8.18	877	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.69	14.82	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:10:6	8.18	881	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.66	14.81	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:10:6	8.18	885	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.64	14.81	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:10:6	9.54	904	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.63	14.8	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:10:7	9.54	904	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.59	14.79	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:10:7	9.54	902	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.59	14.79	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:10:7	9.54	900	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.58	14.81	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:7	9.54	904	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.65	14.8	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:7	10.9	904	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.65	14.8	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:7	10.9	905	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.7	14.81	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:8	10.9	906	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.67	14.81	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:8	8.18	906	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.71	14.82	1.01	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:8	8.18	924	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.68	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:8	8.18	934	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.68	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:8	8.18	934	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:10:8	8.18	934	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.69	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:10:9	8.18	920	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.68	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:10:9	8.18	925	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.73	14.82	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:10:9	8.18	925	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.67	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:9	8.18	924	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.71	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:9	6.81	924	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.68	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:9	6.81	924	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.7	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:10:9	6.81	928	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.68	14.81	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:11:0	6.81	928	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.73	14.83	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:11:0	8.18	918	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.67	14.84	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:11:0	8.18	909	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.7	14.85	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:11:0	8.18	906	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:0	8.18	906	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:0	8.18	910	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:1	8.18	914	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:1	8.18	913	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:1	8.18	913	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:1	8.18	910	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:1	8.18	906	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:1	8.18	908	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.73	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:1	8.18	910	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.74	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:2	8.18	896	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.74	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:2	8.18	896	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.69	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:2	8.18	898	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.73	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:2	8.18	901	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.69	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:2	8.18	896	0.82	13.54	94	191	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.72	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:2	8.18	896	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:3	8.18	896	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.7	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:3	8.18	902	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.69	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:3	8.18	914	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.7	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:3	8.18	914	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.7	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:3	8.18	914	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.7	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:3	8.18	913	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.75	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:4	8.18	913	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.74	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:4	6.81	898	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.73	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:4	6.81	898	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	14.91	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:4	6.81	898	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.7	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:4	6.81	897	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:4	9.54	898	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.9	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:4	9.54	898	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.9	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:5	9.54	902	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:5	9.54	907	0.82	13.54	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:5	9.54	898	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:5	9.54	898	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:5	9.54	902	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:5	9.54	907	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:6	9.54	907	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:6	9.54	919	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:11:6	9.54	920	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.94	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:6	9.54	920	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:6	9.54	917	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.75	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:6	9.54	914	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:6	9.54	914	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.77	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:7	9.54	917	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.75	14.94	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:7	6.81	924	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.79	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:7	6.81	931	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.76	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:7	6.81	931	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.76	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:7	6.81	918	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.77	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:7	6.81	920	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.79	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:8	9.54	922	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.74	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:8	9.54	922	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.75	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:8	9.54	911	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.74	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:8	9.54	911	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.76	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:8	9.54	917	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.71	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:8	9.54	923	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.78	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:9	9.54	931	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.76	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:9	9.54	931	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.76	15.11	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:9	8.18	922	0.82	13.49	94	191	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.76	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:9	8.18	922	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.79	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:9	8.18	924	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.79	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:9	8.18	925	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.83	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:11:9	8.18	933	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.79	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:0	8.18	933	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.79	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:0	8.18	925	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.76	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:12:0	8.18	925	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:12:0	8.18	908	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	15.04	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:12:0	8.18	908	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.8	15.04	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:12:0	8.18	929	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:1	8.18	929	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.83	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:1	9.54	916	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.87	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:1	9.54	916	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.83	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:1	9.54	912	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.86	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:1	9.54	907	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:1	8.18	907	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:1	8.18	902	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:2	8.18	899	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:2	8.18	899	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:2	8.18	899	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:2	8.18	910	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:2	8.18	910	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:2	8.18	910	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:3	8.18	914	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:3	8.18	919	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.78	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:3	8.18	904	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.79	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:3	8.18	904	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.77	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:3	8.18	904	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.81	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:3	8.18	922	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.79	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:4	8.18	922	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.82	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:4	8.18	906	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.79	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:4	8.18	906	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.81	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:4	6.81	887	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.79	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:4	6.81	887	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.81	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:4	6.81	906	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.8	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:4	6.81	906	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.81	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:5	9.54	914	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:5	9.54	914	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:12:5	9.54	912	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.78	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:5	9.54	912	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:5	8.18	912	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:5	8.18	917	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:6	8.18	917	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.78	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:6	8.18	932	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:6	8.18	933	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.79	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:6	9.54	934	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:6	9.54	936	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.78	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:6	9.54	936	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.75	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:6	9.54	929	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.79	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:7	9.54	922	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.79	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:7	9.54	910	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.83	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:7	9.54	910	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.81	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:7	9.54	918	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.83	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:7	9.54	926	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.78	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:7	9.54	926	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.81	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:8	9.54	909	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.77	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:8	9.54	905	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.79	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:8	8.18	905	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.75	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:8	8.18	909	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Lean	1	14.6	-7.78	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:8	8.18	913	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:8	8.18	913	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:9	9.54	899	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:9	9.54	908	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:9	9.54	908	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:9	9.54	908	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:9	9.54	900	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:9	9.54	900	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.76	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:12:9	9.54	890	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:0	9.54	890	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.74	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:0	8.18	891	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:0	8.18	891	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:0	8.18	894	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.72	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:0	8.18	894	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.71	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:0	8.18	898	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.74	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:1	8.18	883	0.82	13.53	94	191	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.7	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:1	8.18	883	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.72	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:1	8.18	889	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:1	8.18	898	0.82	13.52	94	191	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.7	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:1	9.54	908	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.66	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:1	9.54	908	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.71	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:1	9.54	898	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:2	9.54	898	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.7	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:2	8.18	896	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:2	8.18	895	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:2	8.18	904	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.66	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:2	8.18	904	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.7	-7.68	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:2	8.18	899	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.67	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:3	8.18	894	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:3	8.18	899	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:3	8.18	899	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:3	8.18	894	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:3	8.18	889	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:3	8.18	880	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:4	8.18	880	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:4	8.18	887	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:4	9.54	894	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:13:4	9.54	894	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:4	9.54	880	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.64	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:4	9.54	880	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:4	8.18	881	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:5	8.18	882	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:5	8.18	877	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:5	8.18	877	0.82	13.51	94	191	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:5	9.54	886	0.82	13.48	94	191	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:5	9.54	895	0.82	13.5	94	191	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:5	9.54	883	0.82	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.6	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:6	9.54	883	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.61	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:6	9.54	888	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.64	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:6	9.54	888	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.67	Lean	1	14.6	-7.63	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:6	9.54	888	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.66	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:6	9.54	886	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.64	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:13:6	9.54	891	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.68	14.94	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:13:6	6.81	891	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.63	14.95	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:13:7	6.81	891	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.66	14.95	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:13:7	6.81	905	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.61	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:7	6.81	905	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.64	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:7	6.81	902	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.63	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:7	6.81	900	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.65	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:7	6.81	900	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.64	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:8	6.81	898	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.65	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:8	6.81	887	0.82	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.61	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:8	6.81	887	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.61	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:8	6.81	890	0.82	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.58	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:8	6.81	893	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.6	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:8	6.81	892	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.63	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:9	8.18	892	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.61	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:9	8.18	888	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.64	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:9	8.18	888	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.61	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:9	8.18	888	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.6	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:9	9.54	899	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.58	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:9	9.54	899	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.61	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:13:9	9.54	887	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.6	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:14:0	9.54	887	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.62	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:14:0	9.54	894	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.63	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:14:0	9.54	900	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.62	14.8	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:14:0	9.54	895	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.63	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:0	9.54	895	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:0	8.18	912	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.62	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:1	8.18	912	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.66	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:1	8.18	913	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.63	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:1	8.18	914	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.66	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:1	8.18	913	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.64	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:1	8.18	913	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.65	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:1	8.18	918	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.67	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:1	8.18	918	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.67	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:2	8.18	920	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.69	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:2	8.18	922	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.7	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:2	8.18	915	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.68	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:2	8.18	915	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.7	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:2	6.81	922	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.73	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:2	6.81	922	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:3	6.81	922	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.71	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:3	6.81	914	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:3	6.81	909	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.72	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:14:3	6.81	909	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.72	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:3	6.81	914	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.75	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:3	6.81	920	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:4	6.81	920	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.75	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:4	6.81	895	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:4	6.81	911	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.74	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:4	6.81	911	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:4	6.81	911	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:4	8.18	911	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:4	8.18	911	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:5	8.18	908	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:5	8.18	906	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:5	8.18	918	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:5	8.18	918	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:5	8.18	907	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.68	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:5	8.18	896	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:6	8.18	902	0.82	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.67	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:6	8.18	902	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:6	8.18	900	0.82	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:6	8.18	897	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.7	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:6	8.18	893	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.72	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:6	8.18	893	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.73	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:6	8.18	898	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.73	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:7	8.18	902	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.73	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:7	6.81	902	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:7	6.81	900	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:7	6.81	910	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	14.91	1.02	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:7	6.81	920	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.91	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:7	6.81	920	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	14.9	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:8	8.18	916	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:8	8.18	901	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:8	8.18	901	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:8	8.18	901	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:8	8.18	900	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:8	8.18	900	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:9	8.18	909	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:14:9	8.18	909	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.71	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:14:9	6.81	894	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:14:9	6.81	894	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.74	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:14:9	6.81	906	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.74	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:9	6.81	906	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.71	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:14:9	8.18	904	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.73	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:0	8.18	901	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:0	8.18	902	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:0	8.18	902	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:0	8.18	902	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.72	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:0	8.18	901	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.71	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:0	8.18	905	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:1	8.18	905	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:1	8.18	908	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:1	8.18	910	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:1	8.18	910	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:1	8.18	906	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:1	8.18	906	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:1	8.18	908	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:2	6.81	911	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:2	6.81	923	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:2	6.81	923	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:15:2	8.18	923	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.73	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:2	8.18	923	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.76	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:2	8.18	925	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.74	15.04	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:3	8.18	930	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:3	8.18	930	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.77	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:3	8.18	930	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.79	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:3	8.18	936	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.77	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:3	8.18	926	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.8	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:3	8.18	926	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.76	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:4	8.18	930	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.79	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:4	8.18	934	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.75	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:4	8.18	934	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.79	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:4	8.18	921	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.77	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:4	8.18	921	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.79	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:4	8.18	913	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.79	14.96	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:4	8.18	913	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.79	14.94	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:5	9.54	914	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.8	14.93	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:5	9.54	916	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.81	14.89	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:15:5	9.54	910	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.79	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:5	9.54	910	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.8	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:5	9.54	895	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:5	9.54	895	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:6	9.54	900	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:6	9.54	905	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:6	8.18	905	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:6	8.18	905	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:6	8.18	908	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:6	8.18	910	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:6	8.18	908	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:7	8.18	908	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	14.77	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:7	8.18	901	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.78	14.77	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:7	8.18	894	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.72	14.76	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:7	8.18	894	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.76	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:7	8.18	909	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.73	14.75	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:7	8.18	909	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.76	14.75	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:8	8.18	903	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.75	14.74	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:8	8.18	903	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.79	14.74	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:8	8.18	908	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.77	14.75	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:8	8.18	908	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.78	14.74	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:8	8.18	897	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.75	14.74	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:8	8.18	897	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.75	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:9	9.54	901	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:9	9.54	905	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:9	9.54	894	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.76	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:9	9.54	894	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.77	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:9	8.18	898	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:9	8.18	902	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:15:9	8.18	902	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:0	8.18	909	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:0	8.18	917	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:0	8.18	917	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:0	8.18	917	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:0	8.18	907	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.72	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:0	8.18	911	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.76	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:1	8.18	911	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.7	14.8	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:1	8.18	911	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.73	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:1	8.18	911	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.69	14.78	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:1	8.18	910	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.7	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:16:1	8.18	923	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.68	14.68	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:1	8.18	918	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.73	14.69	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:1	8.18	918	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.69	14.71	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:2	8.18	910	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.74	14.73	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:2	8.18	903	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.74	14.76	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:2	8.18	903	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.74	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:2	8.18	908	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.74	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:2	8.18	908	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:2	6.81	910	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:3	6.81	912	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:3	6.81	918	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:3	6.81	918	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:3	8.18	916	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:3	8.18	915	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:3	8.18	918	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.75	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:4	8.18	918	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.73	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:4	6.81	909	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:4	6.81	900	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.72	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:4	6.81	907	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.72	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:4	6.81	907	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:4	8.18	902	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.74	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:4	8.18	898	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:5	8.18	898	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.73	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:5	8.18	892	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:5	8.18	892	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:5	8.18	886	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.71	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:5	8.18	886	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.74	14.96	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:5	8.18	897	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.7	14.98	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:6	8.18	897	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.99	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:6	8.18	899	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:6	8.18	901	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:6	8.18	893	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:6	8.18	893	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:6	9.54	895	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:6	9.54	897	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:7	9.54	893	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:7	9.54	893	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:7	8.18	888	0.82	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:7	8.18	884	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.67	Lean	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:7	8.18	884	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:7	8.18	877	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:8	8.18	877	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.7	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:8	9.54	908	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.67	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:8	9.54	908	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.69	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:8	9.54	890	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.62	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:8	9.54	890	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.69	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:8	9.54	899	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.67	Lean	1	14.6	-7.63	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:9	9.54	895	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Lean	1	14.6	-7.65	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:9	9.54	895	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	14.78	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:9	9.54	891	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:9	8.18	903	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:9	8.18	903	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	14.82	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:16:9	8.18	908	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.83	1.01	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:16:9	8.18	912	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	14.84	1.01	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:17:0	6.81	912	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	14.85	1.01	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:17:0	6.81	903	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.64	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:17:0	6.81	907	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:17:0	6.81	907	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.61	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:17:0	6.81	907	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.62	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:0	8.18	905	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:1	8.18	905	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:1	8.18	905	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:1	8.18	905	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.66	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:1	8.18	897	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.61	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:1	8.18	880	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	14.85	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:1	8.18	880	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.6	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:1	8.18	880	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:2	9.54	895	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.59	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:2	9.54	895	0.83	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:2	9.54	904	0.83	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.62	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:2	9.54	904	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.62	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:2	10.9	902	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.6	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:2	10.9	901	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.62	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:3	10.9	878	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.61	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:3	10.9	878	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.6	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:3	9.54	884	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.59	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:3	9.54	890	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.63	14.82	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:3	9.54	900	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.65	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:3	9.54	900	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.63	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:4	9.54	888	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.67	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:4	9.54	876	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.61	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:4	9.54	875	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.6	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:4	9.54	875	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.56	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:4	9.54	880	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.58	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:4	10.9	885	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.56	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:4	10.9	885	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.61	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:5	10.9	892	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:5	10.9	892	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:5	10.9	905	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:5	10.9	905	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:5	10.9	907	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:5	10.9	907	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.61	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:6	9.54	930	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.61	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:6	9.54	930	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.62	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:6	9.54	939	0.83	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:6	9.54	939	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.65	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:6	8.18	930	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.63	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:6	8.18	920	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.63	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:6	8.18	920	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.63	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:7	8.18	933	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:7	8.18	938	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.68	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:7	8.18	938	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:7	8.18	931	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:7	8.18	931	0.83	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:7	6.81	928	0.83	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.75	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:8	6.81	925	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:8	6.81	924	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:8	6.81	924	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.76	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:8	8.18	926	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.78	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:8	8.18	927	0.83	13.54	94	192	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:8	8.18	938	0.83	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:9	8.18	938	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:9	8.18	938	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:9	9.54	934	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:9	9.54	918	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	15.21	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:9	9.54	918	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	15.23	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:17:9	9.54	928	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	15.24	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:17:9	9.54	937	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.78	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:0	9.54	923	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.8	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:0	9.54	923	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.78	15.28	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:0	9.54	922	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.8	15.29	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:0	8.18	921	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	15.29	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:0	8.18	921	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.83	15.28	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:0	8.18	942	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	15.28	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:1	8.18	929	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.84	15.27	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:1	9.54	929	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	15.26	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:1	9.54	928	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.8	15.26	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:1	9.54	926	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	15.27	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:1	9.54	911	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.79	15.24	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:1	8.18	911	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.75	15.23	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:1	8.18	920	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.79	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:2	8.18	930	0.83	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.74	15.18	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:2	8.18	930	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.78	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:2	8.18	919	0.83	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.76	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:2	8.18	919	0.83	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.81	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:2	8.18	921	0.83	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:2	8.18	921	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.78	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:3	8.18	899	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.78	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:3	8.18	899	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.79	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:3	8.18	904	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.78	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:3	8.18	910	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.79	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:3	8.18	917	0.83	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.77	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:3	8.18	917	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.79	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:4	8.18	917	0.83	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.76	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:4	8.18	917	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.79	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:4	6.81	912	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.78	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:4	6.81	906	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.77	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:4	6.81	923	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.79	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:4	6.81	923	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.76	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:4	6.81	916	0.83	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:5	6.81	909	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:5	6.81	914	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.79	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:5	6.81	914	0.83	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:5	6.81	904	0.83	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.08	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:5	6.81	895	0.83	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.07	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:5	6.81	895	0.83	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:6	6.81	897	0.83	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:6	6.81	897	0.83	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:6	8.18	897	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:6	8.18	897	0.82	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:6	8.18	897	0.82	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:6	8.18	897	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:6	8.18	890	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	14.99	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:7	8.18	890	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	14.98	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:7	8.18	902	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:7	8.18	913	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:7	8.18	916	0.82	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:7	8.18	916	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:7	8.18	918	0.82	13.48	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:8	8.18	919	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:8	8.18	920	0.82	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:8	8.18	920	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:8	8.18	914	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:8	8.18	907	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.71	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:18:8	8.18	917	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.75	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:9	8.18	927	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.72	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:9	8.18	920	0.82	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.75	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:18:9	8.18	920	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:18:9	8.18	916	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.77	14.98	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:18:9	8.18	911	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	14.97	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:18:9	8.18	901	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	14.95	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:18:9	8.18	901	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-7.7	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:0	8.18	902	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:0	8.18	903	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:0	8.18	903	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:0	8.18	897	0.82	13.53	94	192	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:0	8.18	897	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:0	8.18	892	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:1	8.18	886	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:1	8.18	879	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:1	8.18	879	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:1	8.18	880	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:1	8.18	881	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:1	8.18	889	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.8	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:1	8.18	889	0.82	13.51	94	192	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:2	9.54	882	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:2	9.54	875	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:2	9.54	875	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.68	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:2	9.54	881	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:2	9.54	894	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.65	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:2	10.9	907	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.62	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:3	10.9	907	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.66	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:3	10.9	894	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.62	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:3	10.9	894	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.65	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:3	9.54	902	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.63	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:3	9.54	910	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.67	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:3	9.54	904	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.65	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:4	9.54	898	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:4	9.54	918	0.82	13.48	94	193	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.62	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:4	9.54	918	0.82	13.5	94	192	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.67	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:4	9.54	919	0.82	13.49	94	192	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.65	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:4	9.54	920	0.82	13.52	94	192	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.68	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:4	8.18	913	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:4	8.18	913	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.68	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:5	8.18	917	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.7	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:5	8.18	917	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:5	8.18	924	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:5	8.18	924	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:5	8.18	917	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:5	8.18	917	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:6	8.18	917	0.82	13.49	94	193	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:6	8.18	889	0.82	13.51	94	193	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:6	8.18	889	0.82	13.52	94	193	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:6	8.18	893	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:6	8.18	893	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:6	8.18	896	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:6	8.18	896	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:7	8.18	896	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:7	8.18	896	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:7	9.54	898	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:7	9.54	898	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:7	9.54	896	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:19:7	9.54	894	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:8	8.18	903	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.64	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:8	8.18	903	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:8	8.18	914	0.82	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:8	8.18	914	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:8	8.18	905	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:8	8.18	896	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:9	8.18	904	0.82	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:9	8.18	904	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:9	8.18	909	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:9	8.18	914	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:9	8.18	914	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.73	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:9	8.18	914	0.82	13.54	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:19:9	8.18	910	0.82	13.55	94	193	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:0	8.18	905	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:0	8.18	907	0.82	13.54	94	193	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.73	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:0	8.18	907	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:0	8.18	913	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.71	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:0	8.18	913	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.67	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:0	8.18	911	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.71	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:1	8.18	909	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.68	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:1	8.18	909	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.71	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:1	8.18	926	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.68	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:1	8.18	914	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.7	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:1	8.18	903	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.68	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:1	8.18	903	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:1	8.18	928	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:2	8.18	928	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:2	8.18	923	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:2	8.18	918	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:2	9.54	915	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:2	9.54	915	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:2	9.54	914	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:3	9.54	912	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:3	8.18	923	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:3	8.18	923	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:3	8.18	928	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.74	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:3	8.18	928	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.74	15.08	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:3	8.18	900	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	15.07	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:4	8.18	900	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.07	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:4	8.18	907	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	15.06	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:4	8.18	914	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:4	9.54	914	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:4	9.54	925	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:4	9.54	922	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:4	9.54	922	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.01	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:5	9.54	922	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:5	8.18	923	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:5	8.18	920	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:5	8.18	920	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:5	8.18	924	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:5	8.18	928	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:6	8.18	903	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	14.95	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:6	8.18	903	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.94	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:6	8.18	905	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	14.91	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:6	8.18	907	0.82	13.49	94	193	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:6	8.18	907	0.82	13.51	94	193	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:20:6	8.18	898	0.82	13.49	94	193	Idle	93.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.71	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:20:6	8.18	898	0.82	13.51	94	193	Idle	93.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.73	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:7	8.18	898	0.82	13.49	94	193	Idle	93.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.72	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:7	8.18	898	0.82	13.51	94	193	Idle	93.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.72	14.81	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:7	8.18	911	0.82	13.49	94	193	Idle	93.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.77	14.81	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:7	8.18	911	0.82	13.51	94	193	Idle	93.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.77	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:7	8.18	899	0.82	13.5	94	193	Idle	93.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.76	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:7	8.18	899	0.82	13.52	94	193	Idle	93.2	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.74	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:8	8.18	903	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.74	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:8	8.18	903	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.75	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:8	8.18	903	0.82	13.48	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.71	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:8	8.18	907	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.73	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:8	8.18	906	0.82	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:8	8.18	906	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:9	8.18	906	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:9	6.81	896	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.7	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:9	6.81	918	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.73	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:9	6.81	918	0.82	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:9	8.18	918	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:9	8.18	918	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:20:9	8.18	918	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.71	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:0	8.18	920	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:0	8.18	916	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.73	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:0	6.81	913	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.67	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:0	6.81	913	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.71	14.8	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:0	6.81	933	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.67	14.8	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:0	6.81	933	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.68	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:1	8.18	930	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.68	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:1	8.18	926	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.72	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:1	8.18	921	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.71	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:1	8.18	921	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.74	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:1	8.18	920	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.7	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:1	8.18	920	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.7	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:1	8.18	920	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:2	8.18	920	0.83	13.54	94	193	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:2	9.54	922	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:2	9.54	923	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:2	9.54	917	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:2	9.54	917	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:2	9.54	925	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:3	9.54	925	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:3	9.54	898	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:3	9.54	898	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:3	9.54	907	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:3	9.54	907	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:3	9.54	907	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:4	9.54	910	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:4	9.54	911	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:4	9.54	911	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:4	9.54	911	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:4	9.54	909	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:4	8.18	945	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:4	8.18	945	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.74	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:5	8.18	931	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.78	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:5	8.18	917	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.74	14.95	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:21:5	8.18	904	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.77	14.95	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:21:5	6.81	904	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.71	14.95	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:21:5	6.81	904	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.73	14.95	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:21:5	6.81	908	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.69	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:21:6	6.81	895	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.73	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:6	8.18	895	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.72	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:6	8.18	895	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.76	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:6	8.18	903	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.73	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:6	8.18	903	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.74	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:6	8.18	903	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:6	8.18	903	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:7	8.18	909	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:7	8.18	909	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:7	8.18	916	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:7	8.18	923	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:7	8.18	901	0.83	13.48	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:7	8.18	901	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:8	8.18	904	0.83	13.48	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:8	8.18	907	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.73	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:8	8.18	899	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:8	8.18	899	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:8	8.18	902	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:8	8.18	906	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:9	8.18	906	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:9	8.18	905	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:9	8.18	905	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:9	6.81	897	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.72	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:9	6.81	889	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:9	6.81	904	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:21:9	6.81	903	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:0	8.18	903	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:0	8.18	903	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:0	8.18	903	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:0	8.18	906	0.83	13.54	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:0	8.18	906	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:0	8.18	907	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:1	8.18	905	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:1	8.18	905	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:1	8.18	913	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:1	8.18	921	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:1	8.18	921	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:1	8.18	916	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.67	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:1	8.18	911	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.72	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:2	8.18	911	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:2	8.18	911	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:2	8.18	906	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.68	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:2	8.18	909	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:2	8.18	909	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.65	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:2	8.18	909	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:3	8.18	900	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.66	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:3	8.18	901	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.69	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:3	8.18	901	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.7	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:3	8.18	901	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.72	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:3	8.18	909	0.82	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.7	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:3	8.18	909	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.71	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:4	6.81	917	0.82	13.48	94	193	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:4	6.81	917	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:4	6.81	917	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:4	6.81	931	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:4	8.18	919	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.07	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:4	8.18	918	0.82	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:4	8.18	918	0.82	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:22:5	8.18	918	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:5	9.54	927	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.06	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:5	9.54	927	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:5	9.54	924	0.83	13.48	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:5	9.54	920	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:5	8.18	921	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:6	8.18	921	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:6	8.18	925	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:6	8.18	929	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:6	8.18	921	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:6	8.18	921	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:6	8.18	938	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:6	8.18	938	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:7	9.54	938	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:7	9.54	903	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:7	9.54	919	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:7	9.54	919	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:7	9.54	924	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:7	9.54	928	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:8	9.54	908	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.78	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:8	9.54	908	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.73	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:8	9.54	902	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.76	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:8	6.81	895	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.69	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:8	6.81	895	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.72	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:8	6.81	913	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.68	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:9	6.81	913	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.7	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:9	8.18	914	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.7	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:9	8.18	914	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.76	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:9	8.18	901	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.7	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:9	8.18	901	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.74	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:9	8.18	906	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.71	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:22:9	8.18	906	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.75	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:0	8.18	912	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.73	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:0	8.18	918	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.79	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:0	8.18	929	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.76	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:0	8.18	929	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.78	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:0	8.18	926	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.75	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:0	8.18	922	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.75	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:1	6.81	926	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.76	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:1	6.81	926	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.73	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:1	6.81	919	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:1	6.81	919	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.73	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:1	8.18	902	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.74	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:1	8.18	902	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	14.8	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:1	8.18	903	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.78	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:2	8.18	903	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.77	14.8	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:2	8.18	906	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.76	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:2	8.18	906	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.75	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:2	8.18	898	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.78	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:2	8.18	898	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.72	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:2	8.18	898	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.75	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:3	8.18	905	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.7	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:3	8.18	905	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.74	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:3	8.18	902	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:3	8.18	902	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.72	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:3	8.18	900	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:3	8.18	897	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:4	8.18	897	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:23:4	8.18	901	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:4	9.54	911	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:4	9.54	911	0.83	13.53	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:4	9.54	912	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:4	9.54	912	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:4	9.54	914	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:5	9.54	914	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:5	9.54	916	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:5	9.54	918	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:5	9.54	928	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:5	9.54	928	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:5	9.54	926	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.7	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:6	9.54	923	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:23:6	10.9	939	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:23:6	10.9	939	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:23:6	10.9	910	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.71	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:6	10.9	910	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:6	9.54	910	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:6	9.54	914	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.72	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:7	9.54	918	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.74	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:7	9.54	918	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:7	9.54	918	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:7	9.54	915	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:7	9.54	907	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:7	9.54	907	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:8	9.54	904	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.74	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:8	9.54	902	0.84	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.7	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:8	9.54	902	0.84	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.73	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:8	9.54	911	0.84	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:8	9.54	906	0.84	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.71	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:8	8.18	900	0.84	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.69	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:9	8.18	900	0.84	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.71	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:9	8.18	910	0.84	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.7	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:9	8.18	910	0.84	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.73	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:9	6.81	911	0.84	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.71	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:9	6.81	911	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:9	6.81	915	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:23:9	6.81	915	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:0	8.18	908	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:0	8.18	902	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.7	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:0	8.18	894	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:0	8.18	894	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:0	8.18	893	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:0	8.18	892	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:1	8.18	903	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:1	8.18	903	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.67	14.84	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:1	8.18	910	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.7	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:1	8.18	916	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.65	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:1	8.18	916	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.67	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:1	8.18	917	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:1	8.18	916	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:2	6.81	914	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.66	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:2	6.81	914	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.72	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:2	6.81	926	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.68	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:2	6.81	920	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:2	8.18	920	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:2	8.18	920	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.73	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:3	8.18	909	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:24:3	8.18	909	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.71	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:3	8.18	922	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.67	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:3	8.18	921	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.72	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:3	8.18	920	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.71	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:3	8.18	920	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.74	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:4	8.18	914	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.7	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:4	8.18	914	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.74	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:4	8.18	910	0.83	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.74	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:4	8.18	905	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.73	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:4	8.18	918	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.73	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:4	8.18	918	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.71	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:4	8.18	918	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.74	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:5	8.18	922	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:5	6.81	915	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.7	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:5	6.81	915	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:5	6.81	924	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.01	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:5	6.81	934	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:5	9.54	944	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:6	9.54	944	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:6	9.54	931	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:6	9.54	918	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:6	8.18	910	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.97	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:6	8.18	910	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	14.96	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:6	8.18	914	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	14.97	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:6	8.18	919	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:7	8.18	901	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:7	8.18	901	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:7	8.18	912	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:7	8.18	912	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:7	8.18	924	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:7	8.18	913	0.83	13.48	94	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:8	8.18	939	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:8	8.18	939	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:8	8.18	939	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:8	9.54	928	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:8	9.54	928	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:8	9.54	921	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:9	9.54	916	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	14.97	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:9	8.18	910	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	14.98	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:9	8.18	910	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.78	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:24:9	8.18	917	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.74	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:9	8.18	917	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.78	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:9	6.81	918	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.75	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:24:9	6.81	920	0.83	13.5	94	193	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.77	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:0	6.81	922	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.74	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:0	6.81	922	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.77	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:0	8.18	916	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.75	14.92	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:0	8.18	911	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.75	14.91	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:0	8.18	910	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.78	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:0	8.18	910	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.75	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:1	8.18	924	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.77	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:1	8.18	924	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.73	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:1	8.18	924	0.83	13.48	94	194	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.75	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:1	8.18	924	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.7	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:1	8.18	925	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.77	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:1	8.18	925	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.74	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:1	8.18	922	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.78	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:2	8.18	919	0.83	13.52	94	193	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.74	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:25:2	8.18	919	0.83	13.49	94	193	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.76	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:2	8.18	933	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:2	8.18	930	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.79	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:2	8.18	930	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.76	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:2	8.18	930	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.79	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:3	6.81	924	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.78	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:3	6.81	935	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.81	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:3	6.81	935	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.77	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:3	8.18	934	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.82	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:3	8.18	933	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.79	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:3	8.18	933	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.81	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:4	8.18	924	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.78	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:4	8.18	925	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.79	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:4	8.18	925	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.74	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:4	8.18	928	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.77	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:4	8.18	928	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.75	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:4	8.18	932	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.78	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:4	9.54	931	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.77	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:5	9.54	925	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.82	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:5	9.54	925	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.76	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:5	8.18	924	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.79	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:5	8.18	922	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:5	8.18	946	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.81	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:5	8.18	946	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:6	8.18	938	0.83	13.52	94	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.84	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:6	9.54	929	0.83	13.49	94	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:6	9.54	929	0.83	13.5	94	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:6	9.54	932	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:6	9.54	936	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	14.99	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:6	8.18	941	0.83	13.51	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	14.99	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:6	8.18	941	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:7	8.18	946	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:7	8.18	946	0.83	13.57	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:7	8.18	944	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	14.97	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:7	8.18	941	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:7	8.18	941	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.95	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:7	8.18	920	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.94	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:8	6.81	920	0.83	13.54	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	14.95	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:8	6.81	920	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.94	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:25:8	6.81	919	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:8	6.81	919	0.83	13.57	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:8	9.54	908	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:8	9.54	908	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:9	9.54	904	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:9	9.54	904	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:9	9.54	913	0.83	13.54	94	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:9	9.54	913	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:9	9.54	913	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:9	9.54	909	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:25:9	8.18	933	0.83	13.54	94	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:0	8.18	933	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.78	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:0	8.18	925	0.83	13.54	94	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.78	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:0	8.18	917	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.75	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:0	8.18	894	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.76	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:0	6.81	894	0.83	13.56	94	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.75	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:0	6.81	902	0.83	13.54	94	193	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.77	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:1	6.81	909	0.83	13.55	94	193	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.73	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:1	8.18	909	0.83	13.55	94	193	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.77	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:26:1	8.18	904	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.73	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:1	8.18	904	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.74	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:1	8.18	910	0.83	13.55	94	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:1	8.18	910	0.83	13.54	94	194	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.73	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:1	6.81	907	0.83	13.54	94	194	Full Load	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.68	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:2	6.81	918	0.83	13.55	94	194	Off Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.71	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:2	6.81	918	0.83	13.55	94	194	Off Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:2	6.81	918	0.84	13.57	94	194	Off Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.7	-7.69	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:2	8.18	924	0.84	13.55	94	194	Off Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.7	-7.67	14.8	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:2	8.18	924	0.85	13.56	94	194	Off Idle	92.8	0	2	132	944 Turbo	0.16	Lean	1	14.7	-7.66	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:2	8.18	907	0.85	13.56	94	194	Off Idle	92.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.6	14.81	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:26:3	8.18	907	0.86	13.56	94	194	Off Idle	91.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.59	14.83	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:26:3	8.18	914	0.87	13.54	94	194	Off Idle	91.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.53	14.82	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:26:3	8.18	914	0.88	13.55	94	194	Off Idle	90	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.49	14.83	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:26:3	8.18	910	0.89	13.53	94	194	Off Idle	89.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.38	14.82	1.01	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:26:3	8.18	910	0.91	13.55	94	194	Off Idle	88.9	0	2	132	944 Turbo	0.34	Lean	1	14.7	-7.34	14.81	1.01	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:26:3	8.18	919	0.92	13.52	94	194	Off Idle	88.4	0	2	132	944 Turbo	0.39	Rich	1	14.7	-7.25	14.8	1.01	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:26:4	8.18	919	0.94	13.54	94	194	Off Idle	87.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.19	14.83	1.01	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:26:4	8.18	934	0.95	13.52	94	194	Off Idle	87.3	0	2	132	944 Turbo	0.49	Rich	1	14.7	-7.09	14.83	1.01	4.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:26:4	8.18	934	0.97	13.55	94	194	Off Idle	86.8	0	2	132	944 Turbo	0.52	Rich	1	14.7	-7.02	14.85	1.01	4.8	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:26:4	6.81	928	0.99	13.56	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.95	14.86	1.01	4.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:26:4	6.81	922	1.02	13.56	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.63	Rich	1	14.7	-6.79	14.87	1.01	4.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:26:4	6.81	939	1.03	13.55	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.74	14.88	1.01	4.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:4	6.81	939	1.05	13.55	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.61	14.9	1.01	4.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:5	9.54	973	1.08	13.54	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.5	14.94	1.02	4.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:5	9.54	973	1.08	13.56	94	194	Off Idle	85.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.45	14.96	1.02	4.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:5	9.54	971	1.11	13.54	94	194	Off Idle	85.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.42	14.98	1.02	4.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:5	9.54	971	1.13	13.57	94	194	Off Idle	85.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.38	15.02	1.02	4.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:5	8.18	974	1.14	13.55	94	194	Off Idle	85.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-6.31	15.02	1.02	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:5	8.18	974	1.16	13.55	94	194	Off Idle	85.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.27	15.02	1.02	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:6	8.18	988	1.17	13.55	94	194	Off Idle	85.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.23	15.01	1.02	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:24:26:6	8.18	1002	1.19	13.56	94	194	Off Idle	85.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.16	15.01	1.02	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:24:26:6	8.18	1017	1.2	13.55	94	194	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.11	15	1.02	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:24:26:6	8.18	1017	1.22	13.56	94	194	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.07	14.99	1.02	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:24:26:6	8.18	1028	1.23	13.54	94	194	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.98	14.99	1.02	4.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:6	8.18	1044	1.24	13.54	94	194	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.92	15	1.02	4.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:6	8.18	1044	1.26	13.54	94	194	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-5.72	14.99	1.02	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:7	8.18	1047	1.28	13.54	94	194	Off Idle	85.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-5.63	14.99	1.02	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:26:7	8.18	1050	1.31	13.55	94	194	Off Idle	85.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.47	14.97	1.02	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:26:7	9.54	1062	1.33	13.54	94	194	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.35	14.96	1.02	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:26:7	9.54	1074	1.37	13.56	94	194	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.17	14.96	1.02	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:26:7	9.54	1075	1.39	13.54	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-4.96	14.95	1.02	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:24:26:7	9.54	1085	1.41	13.56	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.89	14.95	1.02	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:24:26:8	9.54	1085	1.44	13.55	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.71	14.94	1.02	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:24:26:8	9.54	1085	1.45	13.55	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.63	14.93	1.02	4.3	4	ON	28 Pin	OFF	Removed	Disabled
03:24:26:8	9.54	1172	1.47	13.56	94	194	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.29	14.9	1.01	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:8	21.81	1139	1.5	13.57	94	194	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-4.17	14.88	1.01	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:8	21.81	1139	1.52	13.58	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.14	14.87	1.01	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:26:8	21.81	1164	1.54	13.58	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-4.04	14.85	1.01	4.1	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:9	21.81	1211	1.58	13.58	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.02	14.83	1.01	4.1	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:9	21.81	1211	1.6	13.58	94	194	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.97	14.82	1.01	4.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:26:9	21.81	1226	1.62	13.58	94	194	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-3.94	14.76	1.01	4.2	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:26:9	21.81	1267	1.64	13.58	94	194	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-3.89	14.71	1	4.2	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:26:9	21.81	1281	1.66	13.56	94	194	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.88	14.63	1	4.2	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:26:9	21.81	1281	1.68	13.57	94	194	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-3.9	14.55	0.99	4.2	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:26:9	21.81	1311	1.7	13.58	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-3.88	14.45	0.98	4.2	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:27:0	21.81	1331	1.71	13.57	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-3.92	14.35	0.98	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:0	21.81	1331	1.72	13.58	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.94	14.24	0.97	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:27:0	23.18	1340	1.72	13.58	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.92	14.11	0.96	4.2	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:0	23.18	1361	1.73	13.58	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.96	13.99	0.95	4.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:0	23.18	1361	1.73	13.58	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	-4.02	13.9	0.95	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:0	23.18	1357	1.73	13.58	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	-4.06	13.78	0.94	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:1	23.18	1362	1.74	13.58	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.08	13.72	0.93	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:1	23.18	1364	1.74	13.58	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.86	Rich	1	14.7	-4.14	13.69	0.93	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:1	23.18	1365	1.75	13.58	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.16	13.63	0.93	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:1	23.18	1368	1.75	13.57	94	194	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.7	-4.15	13.59	0.93	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:1	23.18	1369	1.76	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.14	13.56	0.92	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:1	23.18	1369	1.76	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-4.15	13.55	0.92	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:1	23.18	1369	1.76	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-4.15	13.49	0.92	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:2	23.18	1371	1.77	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-4.15	13.44	0.92	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:2	23.18	1371	1.77	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-4.2	13.38	0.91	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:2	23.18	1371	1.77	13.57	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-4.24	13.33	0.91	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:2	23.18	1368	1.78	13.58	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-4.25	13.21	0.9	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:2	23.18	1368	1.78	13.57	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.21	13.17	0.9	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:2	23.18	1367	1.78	13.57	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-4.25	13.12	0.89	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:3	23.18	1364	1.78	13.57	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-4.24	13.09	0.89	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:3	23.18	1360	1.78	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-4.24	13.06	0.89	4.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:3	23.18	1345	1.78	13.55	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-4.2	13.05	0.89	4.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:3	23.18	1345	1.78	13.55	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-4.2	13.06	0.89	4.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:3	23.18	1352	1.78	13.54	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-4.16	13.08	0.89	4.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:3	25.9	1323	1.78	13.55	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-4.12	13.11	0.89	4.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:4	25.9	1323	1.78	13.55	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-4.13	13.17	0.9	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:4	25.9	1310	1.78	13.55	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.1	13.25	0.9	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:4	25.9	1293	1.78	13.55	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.09	13.3	0.91	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:4	25.9	1290	1.78	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.14	13.37	0.91	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:4	25.9	1290	1.78	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.13	13.43	0.91	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:4	27.27	1271	1.77	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.13	13.5	0.92	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:4	27.27	1249	1.77	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.16	13.56	0.92	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:5	27.27	1246	1.76	13.55	94	194	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.12	13.64	0.93	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:5	27.27	1246	1.76	13.55	94	194	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.09	13.67	0.93	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:5	27.27	1223	1.76	13.54	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.07	13.72	0.93	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:5	27.27	1222	1.75	13.55	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.06	13.74	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:5	25.9	1222	1.75	13.55	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.06	13.77	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:5	25.9	1214	1.74	13.55	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.07	13.79	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:6	25.9	1206	1.74	13.55	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.02	13.81	0.94	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:6	25.9	1194	1.73	13.54	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.04	13.81	0.94	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:6	25.9	1180	1.73	13.55	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-4	13.81	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:6	25.9	1179	1.72	13.55	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.95	13.82	0.94	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:27:6	25.9	1170	1.71	13.53	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.94	13.83	0.94	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:27:6	25.9	1170	1.71	13.55	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.94	13.83	0.94	4.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:27:6	25.9	1137	1.7	13.55	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-3.95	13.83	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:7	25.9	1139	1.69	13.55	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-3.94	13.83	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:7	24.54	1139	1.68	13.54	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.7	-3.94	13.83	0.94	4.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:7	24.54	1132	1.67	13.56	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.94	13.83	0.94	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:7	24.54	1126	1.67	13.53	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.92	13.83	0.94	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:7	24.54	1120	1.66	13.52	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-3.93	13.82	0.94	4.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:7	24.54	1107	1.65	13.52	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	-3.9	13.8	0.94	4.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:8	24.54	1100	1.65	13.51	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	-3.87	13.78	0.94	4.7	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:8	24.54	1100	1.64	13.54	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.87	13.77	0.94	4.8	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:8	24.54	1083	1.63	13.53	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	-3.85	13.76	0.94	4.8	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:27:8	24.54	1071	1.63	13.54	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.86	13.72	0.93	4.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:8	24.54	1071	1.62	13.56	94	194	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.83	13.69	0.93	4.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:8	24.54	1044	1.61	13.53	95	194	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.83	13.66	0.93	4.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:9	24.54	1040	1.61	13.56	95	194	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.82	13.62	0.93	4.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:27:9	24.54	1036	1.6	13.53	95	194	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.78	13.59	0.93	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:27:9	24.54	1036	1.6	13.57	94	194	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.74	13.54	0.92	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:27:9	24.54	1014	1.59	13.54	94	194	Off Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.7	13.49	0.92	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:27:9	24.54	1004	1.59	13.58	94	194	Off Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.66	13.42	0.91	4.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:27:9	24.54	1004	1.58	13.55	94	194	Off Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.58	13.35	0.91	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:27:9	23.18	998	1.58	13.55	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.56	13.27	0.9	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:0	23.18	992	1.58	13.56	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.48	13.21	0.9	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:0	23.18	981	1.57	13.54	94	194	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.5	13.1	0.89	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:0	23.18	981	1.57	13.56	94	194	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.39	13.03	0.89	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:0	23.18	971	1.57	13.54	94	194	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.39	12.92	0.88	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:0	23.18	961	1.57	13.56	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.31	12.86	0.88	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:0	23.18	949	1.56	13.53	94	194	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.29	12.78	0.87	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:1	23.18	949	1.56	13.53	94	194	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.26	12.76	0.87	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:1	23.18	942	1.55	13.55	94	194	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.22	12.7	0.87	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:1	23.18	934	1.55	13.55	94	194	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.18	12.66	0.86	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:1	23.18	917	1.55	13.56	94	194	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.19	12.62	0.86	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:1	23.18	917	1.54	13.57	95	194	Off Idle	85.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.11	12.57	0.86	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:1	21.81	916	1.53	13.57	95	194	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.11	12.54	0.85	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:1	21.81	915	1.53	13.55	95	194	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.08	12.51	0.85	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:2	21.81	924	1.52	13.58	94	194	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.11	12.49	0.85	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:2	21.81	924	1.52	13.56	94	194	Off Idle	85.2	0	2	132	944 Turbo	0.88	Rich	1	14.7	-3.05	12.46	0.85	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:2	21.81	926	1.51	13.6	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.1	12.45	0.85	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:2	21.81	929	1.51	13.58	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.88	Rich	1	14.7	-3.04	12.44	0.85	4.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:2	21.81	929	1.5	13.61	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-3.09	12.42	0.85	4.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:28:2	21.81	959	1.5	13.6	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.05	12.4	0.84	4.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:28:3	20.45	974	1.49	13.59	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.13	12.38	0.84	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:28:3	20.45	990	1.49	13.61	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.87	Rich	1	14.7	-3.1	12.36	0.84	4.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:28:3	20.45	1030	1.49	13.6	94	194	Off Idle	85.1	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.19	12.35	0.84	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:28:3	20.45	1030	1.48	13.61	94	194	Off Idle	85.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.18	12.34	0.84	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:28:3	20.45	1058	1.48	13.59	94	194	Off Idle	85.2	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.25	12.33	0.84	4.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:28:3	20.45	1058	1.48	13.6	94	194	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.25	12.32	0.84	4.2	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:28:4	20.45	1074	1.48	13.58	95	194	Off Idle	85.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.34	12.3	0.84	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:4	20.45	1093	1.48	13.57	95	194	Off Idle	85.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-3.39	12.28	0.84	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:4	20.45	1096	1.48	13.56	95	194	Off Idle	85.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	-3.46	12.28	0.84	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:4	20.45	1096	1.48	13.56	94	194	Off Idle	85.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	-3.54	12.27	0.84	4.3	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:4	20.45	1114	1.48	13.56	94	194	Off Idle	85.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.62	12.26	0.83	4.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:4	20.45	1112	1.49	13.56	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.67	12.25	0.83	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:4	20.45	1112	1.49	13.57	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.89	Rich	1	14.7	-3.7	12.24	0.83	4.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:5	20.45	1120	1.49	13.55	94	194	Off Idle	85.8	0	2	132	944 Turbo	0.89	Rich	1	14.7	-3.74	12.21	0.83	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:5	20.45	1112	1.5	13.56	94	194	Off Idle	85.8	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.8	12.19	0.83	4.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:5	20.45	1112	1.5	13.55	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.89	Rich	1	14.7	-3.79	12.17	0.83	4.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:5	20.45	1116	1.5	13.56	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.85	12.15	0.83	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:5	20.45	1128	1.51	13.57	94	194	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.86	12.12	0.83	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:5	20.45	1134	1.51	13.57	94	194	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.7	-3.91	12.08	0.82	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:6	20.45	1134	1.51	13.57	94	194	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.95	12.05	0.82	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:6	20.45	1145	1.52	13.57	94	194	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.97	12.01	0.82	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:6	20.45	1157	1.52	13.57	94	194	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-3.99	11.98	0.82	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:6	20.45	1177	1.52	13.57	94	194	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.6	-4.06	11.94	0.81	4.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:6	20.45	1177	1.53	13.57	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.6	-4.07	11.92	0.81	4.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:6	20.45	1199	1.53	13.58	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.1	11.91	0.81	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:6	20.45	1208	1.54	13.58	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.16	11.89	0.81	4.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:28:7	20.45	1216	1.54	13.57	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.7	-4.17	11.88	0.81	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:28:7	20.45	1227	1.54	13.58	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.23	11.88	0.81	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:28:7	20.45	1238	1.55	13.58	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.7	-4.29	11.87	0.81	4.3	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:28:7	20.45	1247	1.55	13.57	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.32	11.88	0.81	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:7	20.45	1247	1.56	13.58	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.7	-4.38	11.89	0.81	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:7	20.45	1274	1.56	13.57	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.45	11.9	0.81	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:24:28:8	20.45	1272	1.56	13.56	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.47	11.92	0.81	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:8	21.81	1288	1.56	13.55	95	194	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.48	11.94	0.81	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:8	21.81	1288	1.57	13.56	95	194	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.54	11.98	0.82	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:28:8	21.81	1285	1.57	13.56	95	194	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.53	12.02	0.82	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:8	21.81	1287	1.58	13.54	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.56	12.07	0.82	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:8	21.81	1287	1.58	13.53	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.6	12.12	0.83	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:9	21.81	1285	1.59	13.55	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.59	12.18	0.83	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:9	21.81	1285	1.59	13.55	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.7	12.23	0.83	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:9	21.81	1289	1.59	13.56	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.8	12.33	0.84	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:9	21.81	1299	1.6	13.58	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.79	12.38	0.84	4.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:9	21.81	1310	1.6	13.56	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.85	12.47	0.85	4.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:9	21.81	1320	1.6	13.57	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.87	12.52	0.85	4.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:28:9	21.81	1320	1.6	13.57	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-4.87	12.54	0.85	4.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:29:0	23.18	1341	1.61	13.55	94	194	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.87	12.62	0.86	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:29:0	23.18	1357	1.61	13.55	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.91	12.65	0.86	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:29:0	23.18	1357	1.61	13.56	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.93	12.66	0.86	4.3	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:29:0	23.18	1364	1.62	13.56	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.95	12.69	0.86	4.3	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:29:0	23.18	1381	1.62	13.57	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.7	-4.98	12.71	0.87	4.3	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:29:0	23.18	1381	1.62	13.55	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.05	12.73	0.87	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:29:1	23.18	1396	1.62	13.57	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.86	Rich	1	14.7	-5.11	12.78	0.87	4.2	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:29:1	23.18	1409	1.63	13.57	94	194	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.16	12.79	0.87	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:1	23.18	1416	1.63	13.57	94	194	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.7	-5.17	12.8	0.87	4.1	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:1	23.18	1441	1.63	13.57	94	194	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.25	12.84	0.87	4.1	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:1	25.9	1456	1.63	13.57	95	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-5.27	12.87	0.88	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:1	25.9	1456	1.64	13.57	95	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.31	12.9	0.88	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:1	25.9	1452	1.64	13.57	95	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.33	12.93	0.88	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:2	27.27	1447	1.64	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.38	12.97	0.88	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:2	27.27	1440	1.64	13.57	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.42	13	0.89	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:2	25.9	1440	1.65	13.57	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.42	13.02	0.89	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:2	25.9	1453	1.65	13.58	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.5	13.04	0.89	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:2	25.9	1457	1.65	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.5	13.07	0.89	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:2	25.9	1460	1.65	13.56	95	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.55	13.08	0.89	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:3	25.9	1462	1.65	13.57	95	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.54	13.09	0.89	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:3	25.9	1463	1.66	13.56	95	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.54	13.11	0.89	4.2	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:3	25.9	1464	1.66	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.54	13.13	0.89	4.2	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:3	25.9	1470	1.66	13.57	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.53	13.16	0.9	4.1	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:3	25.9	1483	1.66	13.58	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.52	13.18	0.9	4.1	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:3	25.9	1483	1.66	13.58	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.57	13.2	0.9	4.1	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:4	25.9	1505	1.66	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.59	13.22	0.9	4.2	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:4	25.9	1503	1.66	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.62	13.24	0.9	4.2	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:4	25.9	1518	1.66	13.56	94	194	Off Idle	86.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.65	13.25	0.9	4.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:4	25.9	1518	1.67	13.56	94	194	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.65	13.28	0.9	4.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:4	25.9	1533	1.67	13.58	94	194	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.66	13.3	0.91	4.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:4	25.9	1555	1.67	13.57	95	194	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.68	13.35	0.91	4.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:4	27.27	1566	1.67	13.57	95	194	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.73	13.39	0.91	4.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:5	27.27	1566	1.67	13.56	95	194	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-5.76	13.4	0.91	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:5	27.27	1575	1.68	13.56	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-5.81	13.46	0.92	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:5	27.27	1580	1.68	13.55	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.82	13.47	0.92	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:5	27.27	1580	1.68	13.56	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.86	13.51	0.92	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:5	27.27	1579	1.69	13.56	94	194	Off Idle	86.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.87	13.56	0.92	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:5	27.27	1582	1.69	13.56	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.89	13.6	0.93	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:6	27.27	1590	1.69	13.55	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.9	13.63	0.93	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:6	27.27	1592	1.7	13.54	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.91	13.66	0.93	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:6	27.27	1594	1.7	13.55	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.91	13.69	0.93	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:6	27.27	1601	1.7	13.53	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.91	13.72	0.93	4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:6	27.27	1601	1.71	13.55	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.91	13.75	0.94	3.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:6	27.27	1604	1.71	13.55	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.89	13.8	0.94	3.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:6	27.27	1608	1.72	13.56	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.88	13.85	0.94	3.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:7	27.27	1610	1.72	13.56	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.86	13.9	0.95	3.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:7	27.27	1612	1.73	13.55	94	194	Off Idle	86.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.81	13.94	0.95	3.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:7	27.27	1619	1.74	13.55	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-5.79	13.98	0.95	3.9	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:29:7	27.27	1632	1.75	13.55	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-5.77	14.03	0.96	3.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:29:7	27.27	1632	1.76	13.54	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-5.71	14.09	0.96	3.9	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:7	28.63	1652	1.76	13.55	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	-5.67	14.14	0.96	3.9	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:8	28.63	1650	1.77	13.56	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	-5.62	14.2	0.97	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:8	28.63	1658	1.78	13.56	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.56	14.23	0.97	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:8	28.63	1671	1.8	13.58	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-5.47	14.31	0.97	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:8	28.63	1688	1.8	13.57	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-5.46	14.35	0.98	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:8	28.63	1710	1.81	13.57	95	194	Off Idle	86.6	0	2	132	944 Turbo	0.74	Rich	1	14.7	-5.43	14.38	0.98	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:8	28.63	1710	1.82	13.58	95	194	Off Idle	86.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-5.43	14.43	0.98	3.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:9	28.63	1718	1.83	13.57	95	194	Off Idle	86.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-5.42	14.48	0.99	3.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:29:9	28.63	1721	1.84	13.58	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.44	14.53	0.99	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:9	28.63	1722	1.85	13.57	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-5.43	14.57	0.99	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:9	28.63	1731	1.86	13.57	94	194	Off Idle	86.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-5.44	14.59	0.99	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:9	28.63	1738	1.87	13.57	95	194	Off Idle	86.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-5.44	14.61	1	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:9	28.63	1736	1.88	13.56	95	194	Off Idle	86.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.47	14.66	1	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:29:9	28.63	1731	1.88	13.57	95	194	Off Idle	86.3	0	2	132	944 Turbo	0.6	Rich	1	14.7	-5.44	14.69	1	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:0	28.63	1726	1.89	13.56	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.44	14.73	1	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:0	28.63	1724	1.89	13.55	94	194	Off Idle	86.3	0	2	132	944 Turbo	0.54	Rich	1	14.7	-5.46	14.76	1.01	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:0	28.63	1722	1.89	13.57	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.52	Rich	1	14.7	-5.46	14.76	1.01	3.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:0	28.63	1719	1.9	13.58	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.47	14.77	1.01	3.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:0	28.63	1720	1.9	13.56	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.41	Rich	1	14.7	-5.41	14.78	1.01	3.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:0	28.63	1720	1.9	13.57	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.38	14.8	1.01	3.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:1	28.63	1729	1.9	13.58	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.4	14.82	1.01	3.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:1	28.63	1744	1.9	13.58	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.37	14.86	1.01	3.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:1	28.63	1749	1.9	13.58	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.21	Lean	1	14.7	-5.38	14.88	1.01	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:1	28.63	1756	1.91	13.6	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.39	14.9	1.01	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:1	28.63	1779	1.91	13.58	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.14	Lean	1	14.7	-5.37	14.92	1.02	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:1	28.63	1793	1.92	13.57	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.32	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:30:1	29.99	1816	1.92	13.57	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.09	Lean	1	14.7	-5.25	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:30:2	29.99	1823	1.93	13.57	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.16	15.06	1.03	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:30:2	29.99	1832	1.93	13.56	94	194	Off Idle	86.2	0	2	132	944 Turbo	0.08	Lean	1	14.7	-5.15	15.11	1.03	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:30:2	29.99	1839	1.95	13.56	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.06	15.16	1.03	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:30:2	29.99	1858	1.95	13.58	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.02	15.18	1.03	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:30:2	29.99	1866	1.97	13.57	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.92	15.25	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:30:2	29.99	1866	1.98	13.57	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.87	15.29	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:30:3	29.99	1868	1.99	13.56	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.75	15.39	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:24:30:3	28.63	1859	2	13.55	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.67	15.44	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:24:30:3	28.63	1873	2.01	13.56	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.66	15.5	1.06	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:24:30:3	28.63	1873	2.02	13.57	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.61	15.55	1.06	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:24:30:3	28.63	1874	2.04	13.58	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.56	15.58	1.06	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:24:30:3	28.63	1880	2.05	13.6	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.53	15.63	1.06	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:30:4	28.63	1880	2.06	13.61	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.53	15.64	1.07	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:30:4	28.63	1886	2.07	13.59	95	194	Off Idle	86.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.44	15.64	1.07	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:30:4	28.63	1896	2.08	13.57	95	194	Off Idle	86.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.39	15.65	1.07	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:30:4	29.99	1913	2.09	13.56	95	194	Off Idle	86.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.35	15.64	1.07	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:30:4	29.99	1908	2.1	13.55	95	194	Off Idle	86.1	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.33	15.62	1.06	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:30:4	29.99	1920	2.11	13.56	95	194	Off Idle	86.1	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.3	15.61	1.06	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:30:4	29.99	1935	2.12	13.57	95	194	Off Idle	86.1	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.25	15.59	1.06	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:30:5	29.99	1940	2.13	13.59	95	195	Off Idle	86	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.24	15.57	1.06	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:30:5	29.99	1951	2.14	13.6	95	195	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.18	15.55	1.06	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:30:5	29.99	1951	2.14	13.61	95	195	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.17	15.55	1.06	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:30:5	29.99	1969	2.15	13.59	95	195	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.04	15.53	1.06	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:30:5	29.99	1972	2.16	13.56	95	194	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.96	15.5	1.06	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:30:5	29.99	1999	2.17	13.55	95	194	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.88	15.47	1.05	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:30:6	29.99	1990	2.18	13.54	95	194	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.74	15.45	1.05	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:30:6	29.99	2001	2.2	13.55	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.6	15.44	1.05	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:30:6	29.99	2012	2.21	13.56	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.47	15.39	1.05	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:30:6	29.99	2012	2.21	13.56	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.36	15.36	1.05	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:30:6	29.99	2026	2.22	13.54	95	194	Off Idle	85.9	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.31	15.34	1.05	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:6	29.99	2036	2.23	13.53	95	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.24	15.33	1.04	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:6	29.99	2036	2.25	13.52	95	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-3.18	15.33	1.04	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:7	29.99	2061	2.26	13.53	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-3.12	15.32	1.04	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:7	29.99	2070	2.27	13.54	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-3.06	15.33	1.04	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:7	29.99	2077	2.29	13.54	94	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-3	15.34	1.05	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:7	29.99	2080	2.3	13.54	95	194	Off Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.7	-2.97	15.37	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:7	29.99	2091	2.31	13.55	95	194	Off Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.7	-2.95	15.4	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:7	29.99	2098	2.32	13.57	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-2.9	15.44	1.05	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:8	29.99	2106	2.33	13.58	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.07	Lean	1	14.7	-2.88	15.47	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:8	29.99	2105	2.34	13.57	94	194	Off Idle	85.7	0	2	132	944 Turbo	0.08	Lean	1	14.7	-2.89	15.47	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:8	29.99	2125	2.35	13.58	95	194	Off Idle	85.7	0	2	132	944 Turbo	0.1	Lean	1	14.7	-2.89	15.44	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:8	29.99	2114	2.35	13.57	95	194	Off Idle	85.7	0	2	132	944 Turbo	0.14	Lean	1	14.7	-2.87	15.43	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:30:8	29.99	2126	2.36	13.56	95	194	Off Idle	85.6	0	2	132	944 Turbo	0.19	Lean	1	14.7	-2.83	15.4	1.05	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:30:8	29.99	2143	2.36	13.55	95	194	Off Idle	85.6	0	2	132	944 Turbo	0.25	Lean	1	14.7	-2.82	15.38	1.05	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:30:9	29.99	2155	2.37	13.56	95	194	Off Idle	85.6	0	2	132	944 Turbo	0.31	Lean	1	14.7	-2.77	15.35	1.05	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:30:9	29.99	2159	2.38	13.57	95	195	Off Idle	85.6	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.69	15.3	1.04	3.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:30:9	29.99	2184	2.39	13.57	94	195	Off Idle	85.6	0	2	132	944 Turbo	0.46	Lean	1	14.7	-2.59	15.26	1.04	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:30:9	29.99	2190	2.41	13.57	94	195	Off Idle	85.6	0	2	132	944 Turbo	0.52	Lean	1	14.7	-2.5	15.22	1.04	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:30:9	29.99	2190	2.42	13.56	94	194	Off Idle	85.4	0	2	132	944 Turbo	0.57	Lean	1	14.7	-2.36	15.18	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:30:9	29.99	2205	2.43	13.56	94	194	Off Idle	85.2	0	2	132	944 Turbo	0.6	Rich	1	14.7	-2.34	15.15	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:30:9	29.99	2213	2.44	13.56	94	194	Off Idle	84.9	0	2	132	944 Turbo	0.62	Rich	1	14.7	-2.14	15.11	1.03	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:24:31:0	29.99	2228	2.45	13.56	94	194	Off Idle	84.9	0	2	132	944 Turbo	0.59	Rich	1	14.7	-2.05	15.07	1.03	3.3	4	ON	28 Pin	OFF	Removed	Disabled
03:24:31:0	31.36	2256	2.46	13.58	95	195	Off Idle	84.6	0	2	132	944 Turbo	0.54	Rich	1	14.7	-2	15.04	1.02	3.3	4	ON	28 Pin	OFF	Removed	Disabled
03:24:31:0	31.36	2256	2.47	13.57	95	195	Off Idle	84.3	0	2	132	944 Turbo	0.52	Rich	1	14.7	-1.98	15.01	1.02	3.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:0	31.36	2271	2.48	13.57	95	195	Off Idle	84	0	2	132	944 Turbo	0.46	Rich	1	14.6	-1.92	14.99	1.02	3.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:0	31.36	2326	2.5	13.57	94	195	Off Idle	83.2	0	2	132	944 Turbo	0.37	Rich	1	14.7	-1.86	14.91	1.02	3.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:0	31.36	2326	2.5	13.55	94	195	Off Idle	82.8	0	2	132	944 Turbo	0.34	Rich	1	14.7	-1.83	14.88	1.01	3.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:1	31.36	2334	2.52	13.56	95	195	Off Idle	82.1	0	2	132	944 Turbo	0.29	Rich	1	14.7	-1.78	14.86	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:31:1	31.36	2349	2.53	13.56	95	195	Off Idle	81.3	0	2	132	944 Turbo	0.27	Rich	1	14.7	-1.77	14.87	1.01	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:31:1	31.36	2382	2.55	13.56	95	195	Off Idle	80.6	0	2	132	944 Turbo	0.27	Rich	1	14.7	-1.76	14.91	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:1	31.36	2382	2.56	13.55	95	195	Off Idle	79.8	0	2	132	944 Turbo	0.3	Rich	1	14.7	-1.74	14.95	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:1	31.36	2378	2.57	13.56	95	195	Off Idle	79.1	0	2	132	944 Turbo	0.36	Rich	1	14.7	-1.74	14.98	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:1	31.36	2383	2.58	13.56	95	195	Off Idle	78.4	0	2	132	944 Turbo	0.42	Rich	1	14.7	-1.74	15.02	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:1	31.36	2384	2.6	13.56	95	195	Off Idle	77.6	0	2	132	944 Turbo	0.49	Rich	1	14.7	-1.75	15.07	1.03	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:2	31.36	2389	2.61	13.56	95	195	Off Idle	76.9	0	2	132	944 Turbo	0.59	Rich	1	14.7	-1.79	15.09	1.03	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:2	31.36	2396	2.61	13.57	95	195	Off Idle	76.2	0	2	132	944 Turbo	0.62	Rich	1	14.7	-1.77	15.12	1.03	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:2	31.36	2398	2.62	13.56	95	194	Off Idle	75.6	0	2	132	944 Turbo	0.68	Rich	1	14.7	-1.75	15.11	1.03	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:2	31.36	2408	2.62	13.56	95	194	Off Idle	75.1	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.72	15.09	1.03	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:2	31.36	2422	2.63	13.54	95	194	Off Idle	74.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.71	15.03	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:2	31.36	2431	2.64	13.54	95	194	Off Idle	73.9	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.65	14.93	1.02	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:3	31.36	2437	2.64	13.55	95	194	Off Idle	73.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.67	14.86	1.01	3.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:3	31.36	2458	2.65	13.55	95	194	Off Idle	72.9	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.68	14.81	1.01	3.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:3	31.36	2467	2.65	13.57	95	194	Off Idle	72.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.66	14.72	1	3.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:3	31.36	2492	2.66	13.56	95	194	Off Idle	72.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.62	14.67	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:3	31.36	2495	2.67	13.59	95	194	Off Idle	72	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.64	14.63	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:3	31.36	2511	2.68	13.58	94	195	Off Idle	71.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.6	14.63	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:4	31.36	2518	2.68	13.58	94	195	Off Idle	70.9	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.56	14.62	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:4	31.36	2537	2.69	13.57	95	195	Off Idle	70.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.51	14.61	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:4	31.36	2562	2.7	13.56	95	195	Off Idle	69.7	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.48	14.65	1	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:31:4	31.36	2568	2.7	13.58	95	195	Off Idle	69.1	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.44	14.67	1	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:4	31.36	2584	2.71	13.57	95	195	Off Idle	68.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.44	14.69	1	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:4	31.36	2593	2.72	13.58	95	194	Off Idle	67.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.41	14.71	1	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:4	31.36	2618	2.73	13.57	95	194	Off Idle	67	0	2	132	944 Turbo	0.69	Rich	1	14.7	-1.4	14.73	1	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:5	32.72	2612	2.73	13.57	95	195	Off Idle	66.3	0	2	132	944 Turbo	0.66	Rich	1	14.7	-1.36	14.74	1	3.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:5	32.72	2618	2.74	13.57	95	195	Off Idle	64.9	0	2	132	944 Turbo	0.61	Rich	1	14.7	-1.33	14.77	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:31:5	32.72	2621	2.75	13.57	95	195	Off Idle	64.2	0	2	132	944 Turbo	0.56	Rich	1	14.7	-1.24	14.77	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:31:5	32.72	2632	2.76	13.59	94	195	Off Idle	63.5	0	2	132	944 Turbo	0.52	Rich	1	14.7	-1.25	14.77	1.01	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:31:5	31.36	2659	2.78	13.58	94	195	Off Idle	62.7	0	2	132	944 Turbo	0.45	Rich	1	14.7	-1.2	14.76	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:31:5	31.36	2678	2.78	13.57	94	195	Off Idle	62.1	0	2	132	944 Turbo	0.42	Lean	1	14.7	-1.14	14.8	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:31:6	31.36	2684	2.79	13.58	95	195	Off Idle	61.4	0	2	132	944 Turbo	0.39	Lean	1	14.7	-1.08	14.8	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:6	31.36	2708	2.8	13.57	95	195	Off Idle	60.7	0	2	132	944 Turbo	0.39	Lean	1	14.7	-1.04	14.81	1.01	3.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:6	32.72	2755	2.82	13.58	94	195	Off Idle	60.1	0	2	132	944 Turbo	0.41	Lean	1	14.7	-0.9	14.85	1.01	3.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:31:6	32.72	2755	2.83	13.56	94	195	Off Idle	59.5	0	2	132	944 Turbo	0.43	Lean	1	14.7	-0.85	14.87	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:31:6	32.72	2758	2.84	13.55	94	195	Off Idle	59.5	0	2	132	944 Turbo	0.47	Lean	1	14.7	-0.81	14.93	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:6	32.72	2772	2.86	13.55	94	195	Off Idle	58.2	0	2	132	944 Turbo	0.51	Lean	1	14.7	-0.71	14.95	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:6	32.72	2788	2.86	13.55	94	195	Off Idle	57.6	0	2	132	944 Turbo	0.57	Lean	1	14.7	-0.71	14.98	1.02	3.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:7	32.72	2814	2.87	13.55	94	195	Off Idle	56.9	0	2	132	944 Turbo	0.62	Lean	1	14.7	-0.71	15	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:7	32.72	2806	2.89	13.57	95	195	Off Idle	56.1	0	2	132	944 Turbo	0.68	Lean	1	14.7	-0.69	14.98	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:7	32.72	2821	2.9	13.58	95	195	Off Idle	55.2	0	2	132	944 Turbo	0.72	Lean	1	14.7	-0.64	14.98	1.02	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:7	32.72	2827	2.91	13.57	95	195	Off Idle	54.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.63	14.94	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:7	32.72	2830	2.91	13.58	95	195	Off Idle	53.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.57	14.91	1.02	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:7	31.36	2852	2.92	13.57	95	195	Off Idle	52.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.56	14.9	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:8	31.36	2857	2.93	13.56	95	195	Off Idle	51.1	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.5	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:8	31.36	2857	2.94	13.56	95	195	Off Idle	50.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.51	14.8	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:8	31.36	2874	2.95	13.55	95	195	Off Idle	49.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-0.48	14.78	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:8	31.36	2888	2.96	13.55	95	195	Off Idle	49.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	-0.46	14.74	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:8	31.36	2888	2.97	13.56	95	195	Off Idle	48.7	0	2	132	944 Turbo	0.76	Rich	1	14.7	-0.4	14.74	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:8	31.36	2906	2.98	13.55	95	195	Off Idle	48.1	0	2	132	944 Turbo	0.76	Rich	1	14.7	-0.41	14.75	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:9	31.36	2923	2.98	13.55	95	195	Off Idle	47.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	-0.36	14.76	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:9	31.36	2923	2.99	13.56	95	195	Off Idle	46.9	0	2	132	944 Turbo	0.76	Rich	1	14.7	-0.36	14.77	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:9	31.36	2964	2.99	13.56	95	195	Off Idle	46.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	-0.38	14.74	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:31:9	31.36	2959	3	13.57	95	195	Off Idle	46	0	2	132	944 Turbo	0.76	Rich	1	14.7	-0.38	14.75	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:9	31.36	2970	3.01	13.57	94	195	Off Idle	45.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.34	14.76	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:9	31.36	2996	3.02	13.56	94	195	Off Idle	45.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.34	14.75	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:31:9	31.36	3008	3.02	13.57	95	195	Off Idle	44.9	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.26	14.74	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:32:0	31.36	3008	3.03	13.56	95	195	Off Idle	44.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.26	14.75	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:32:0	31.36	3026	3.04	13.55	95	195	Off Idle	44.1	0	2	132	944 Turbo	0.64	Rich	1	14.7	-0.24	14.71	1	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:32:0	31.36	3057	3.04	13.56	95	195	Off Idle	43.6	0	2	132	944 Turbo	0.6	Rich	1	14.7	-0.2	14.74	1	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:24:32:0	31.36	3057	3.04	13.56	95	195	Off Idle	43.2	0	2	132	944 Turbo	0.57	Lean	1	14.7	-0.22	14.73	1	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:24:32:0	32.72	3082	3.05	13.54	95	195	Off Idle	42.6	0	2	132	944 Turbo	0.48	Lean	1	14.7	-0.16	14.73	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:0	32.72	3104	3.06	13.56	95	195	Off Idle	42.3	0	2	132	944 Turbo	0.42	Lean	1	14.7	-0.2	14.73	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:1	32.72	3122	3.07	13.55	95	195	Off Idle	42.3	0	2	132	944 Turbo	0.36	Lean	1	14.7	-0.11	14.74	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:1	32.72	3130	3.08	13.56	95	195	Off Idle	41.8	0	2	132	944 Turbo	0.33	Lean	1	14.7	-0.12	14.8	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:1	32.72	3173	3.09	13.55	95	195	Off Idle	41.7	0	2	132	944 Turbo	0.34	Lean	1	14.7	-0.08	14.84	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:1	32.72	3186	3.09	13.57	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.7	-0.11	14.86	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:1	32.72	3211	3.1	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.7	-0.08	14.95	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:1	32.72	3211	3.11	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	-0.08	14.97	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:1	32.72	3231	3.11	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	-0.13	14.96	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:2	32.72	3223	3.12	13.57	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-0.11	14.96	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:2	32.72	3223	3.13	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-0.04	14.96	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:2	32.72	3231	3.13	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-0.1	14.93	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:2	32.72	3237	3.14	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.01	14.86	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:2	32.72	3237	3.15	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	0.02	14.82	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:2	32.72	3248	3.15	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	0.02	14.78	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:3	32.72	3252	3.16	13.57	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	0.1	14.74	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:3	32.72	3272	3.17	13.57	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	0.13	14.7	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:3	32.72	3286	3.17	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	0.19	14.69	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:3	32.72	3290	3.18	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	0.2	14.69	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:3	32.72	3300	3.18	13.57	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.65	Lean	1	14.7	0.18	14.7	1	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:3	32.72	3306	3.19	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.7	0.32	14.73	1	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:4	32.72	3373	3.19	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.7	0.34	14.78	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:4	32.72	3378	3.2	13.55	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.7	0.45	14.79	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:4	32.72	3378	3.2	13.54	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.7	0.48	14.81	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:24:32:4	32.72	3414	3.21	13.54	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.7	0.46	14.82	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:24:32:4	32.72	3452	3.21	13.56	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	0.51	14.85	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:32:4	32.72	3470	3.22	13.55	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	0.5	14.88	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:4	32.72	3475	3.22	13.57	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	0.48	14.89	1.01	3.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:24:32:5	32.72	3506	3.23	13.55	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.7	0.56	14.96	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:5	32.72	3521	3.23	13.55	95	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.7	0.53	15.01	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:5	32.72	3525	3.24	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.7	0.5	15.03	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:5	32.72	3537	3.24	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.7	0.59	15.03	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:5	32.72	3544	3.25	13.54	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	0.64	15.04	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:5	32.72	3544	3.25	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	0.56	15.02	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:6	32.72	3549	3.26	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	0.56	14.99	1.02	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:24:32:6	32.72	3557	3.27	13.55	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	0.64	14.94	1.02	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:24:32:6	32.72	3559	3.27	13.53	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	0.57	14.93	1.02	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:24:32:6	32.72	3574	3.27	13.55	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	0.54	14.91	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:6	32.72	3588	3.28	13.55	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	0.54	14.83	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:6	32.72	3651	3.28	13.55	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	0.54	14.81	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:6	32.72	3625	3.28	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.7	0.44	14.81	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:7	32.72	3618	3.29	13.58	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	0.52	14.82	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:7	32.72	3633	3.29	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	0.59	14.85	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:7	32.72	3633	3.29	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	0.6	14.87	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:7	32.72	3662	3.29	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.7	0.55	14.88	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:7	32.72	3662	3.3	13.54	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.7	0.56	14.89	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:7	32.72	3668	3.3	13.53	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.7	0.49	14.88	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:8	32.72	3683	3.3	13.54	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.7	0.45	14.88	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:8	32.72	3735	3.3	13.54	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.7	0.41	14.9	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:8	32.72	3728	3.3	13.54	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.7	0.38	14.93	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:8	32.72	3732	3.3	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.7	0.42	14.96	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:8	32.72	3758	3.31	13.59	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	0.44	14.97	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:32:8	32.72	3764	3.31	13.57	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	0.52	14.99	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:32:9	32.72	3793	3.31	13.55	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.7	0.61	15.04	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:9	32.72	3816	3.31	13.52	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.7	0.59	15.09	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:32:9	32.72	3836	3.31	13.5	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.7	0.48	15.1	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:32:9	32.72	3836	3.31	13.5	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.7	0.29	15.08	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:32:9	32.72	3876	3.31	13.51	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.7	0.15	15.06	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:32:9	34.08	3834	3.32	13.53	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.7	0.02	15.01	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:32:9	34.08	3838	3.32	13.56	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-0.12	14.97	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:33:0	34.08	3856	3.32	13.57	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	-0.12	14.94	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:33:0	34.08	3881	3.32	13.59	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.7	-0.16	14.9	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:33:0	34.08	3885	3.32	13.6	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.7	-0.19	14.83	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:33:0	34.08	3914	3.32	13.6	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.7	-0.27	14.78	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:33:0	34.08	3931	3.31	13.6	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-0.5	14.77	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:33:0	34.08	3941	3.3	13.6	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.7	-0.74	14.81	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:33:1	35.45	3986	3.29	13.6	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.7	-1.18	14.84	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:33:1	35.45	3958	3.26	13.6	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-1.72	14.93	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:1	35.45	3958	3.21	13.6	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.51	14.97	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:33:1	35.45	3960	3.16	13.6	94	195	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.7	-3.41	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:1	36.81	3913	3.09	13.6	94	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.7	-4.4	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:33:1	36.81	3926	3.02	13.59	94	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.35	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:33:1	36.81	3907	2.9	13.59	95	195	Full Load	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.68	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:33:2	36.81	3860	2.82	13.58	95	195	Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.37	14.66	1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:24:33:2	36.81	3823	2.73	13.56	95	195	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-7.96	14.5	0.99	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:24:33:2	36.81	3811	2.64	13.53	95	195	Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.44	14.31	0.97	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:24:33:2	36.81	3768	2.55	13.54	95	195	Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.6	-8.83	14.07	0.96	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:2	36.81	3723	2.42	13.54	95	195	Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-9.14	13.81	0.94	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:2	34.08	3688	2.32	13.54	95	195	Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-9.3	13.69	0.93	3.7	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:3	28.63	3607	2.23	13.55	95	195	Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-9.41	13.46	0.92	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:3	23.18	3577	2.14	13.57	95	195	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.46	13.26	0.9	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:3	20.45	3598	2.1	13.58	95	195	Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.46	13.15	0.9	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:3	20.45	3569	1.98	13.58	95	195	Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.51	12.89	0.88	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:3	20.45	3541	1.9	13.57	95	195	Idle	41	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.5	12.74	0.87	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:33:3	20.45	3511	1.78	13.57	95	195	Idle	39.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.48	12.58	0.86	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:4	20.45	3489	1.72	13.56	95	195	Idle	38.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.44	12.52	0.85	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:4	20.45	3464	1.67	13.55	95	195	Idle	37.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.47	12.49	0.85	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:4	20.45	3440	1.65	13.56	95	195	Idle	36.6	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.52	12.52	0.85	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:4	20.45	3406	1.63	13.58	95	195	Idle	35.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.47	12.59	0.86	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:4	20.45	3384	1.62	13.56	95	195	Idle	34.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.39	12.71	0.87	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:4	20.45	3362	1.62	13.56	95	195	Idle	32.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.41	12.88	0.88	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:4	20.45	3343	1.62	13.57	95	195	Idle	31.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.36	13.13	0.89	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:5	20.45	3310	1.63	13.57	95	195	Idle	30	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	13.61	0.93	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:5	20.45	3261	1.64	13.56	95	195	Idle	28.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.19	14.28	0.97	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:5	20.45	3267	1.66	13.58	95	195	Idle	27.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.18	14.67	1	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:5	20.45	3234	1.67	13.58	95	195	Idle	26	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	15.43	1.05	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:5	20.45	3192	1.69	13.57	95	195	Idle	24.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	16.55	1.13	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:5	20.45	3192	1.7	13.57	95	195	Idle	24	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	16.92	1.15	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:6	20.45	3167	1.73	13.57	95	195	Idle	23.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.95	17.98	1.22	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:6	20.45	3128	1.75	13.57	95	195	Idle	22.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.88	18.63	1.27	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:6	20.45	3103	1.76	13.56	95	195	Idle	22.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.87	19.24	1.31	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:6	20.45	3094	1.77	13.57	95	195	Idle	22.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.86	19.77	1.35	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:6	20.45	3056	1.79	13.56	95	195	Idle	22.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.85	20.16	1.37	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:6	20.45	3025	1.8	13.56	95	195	Idle	22.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.8	20.18	1.37	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:6	20.45	2993	1.81	13.57	95	195	Idle	22.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.86	20.2	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:7	19.09	2976	1.82	13.57	95	195	Idle	22.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.76	20.2	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:7	19.09	2944	1.83	13.57	95	195	Idle	22.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.81	20.2	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:7	19.09	2933	1.83	13.57	95	195	Idle	22.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.75	20.2	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:7	19.09	2926	1.83	13.57	95	195	Idle	22.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.77	20.2	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:7	19.09	2884	1.84	13.57	95	195	Idle	23.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.73	20.2	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:7	19.09	2857	1.84	13.57	95	195	Idle	23.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.71	20.2	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:8	19.09	2825	1.85	13.57	95	195	Idle	23.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.75	20.2	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:8	19.09	2817	1.85	13.56	95	195	Idle	23.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.7	20.2	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:8	19.09	2785	1.85	13.57	95	195	Full Load	23.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.68	20.21	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:8	19.09	2720	1.85	13.57	95	195	Off Idle	23.7	0	2	132	944 Turbo	0.01	Lean	1	14.7	-8.62	20.21	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:8	19.09	2732	1.85	13.57	95	195	Off Idle	23.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.61	20.22	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:8	19.09	2652	1.86	13.57	95	195	Off Idle	24.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.52	20.21	1.38	3.6	1.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:9	19.09	2677	1.87	13.57	95	195	Off Idle	25	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.46	20.21	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:33:9	10.9	2688	1.87	13.57	95	195	Off Idle	27.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.37	20.21	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:33:9	13.63	2668	1.88	13.57	95	195	Off Idle	27.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.29	20.22	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:33:9	16.36	2631	1.89	13.57	95	195	Off Idle	32.1	0	2	132	944 Turbo	0.01	Lean	1	14.7	-8.2	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:33:9	19.09	2618	1.9	13.57	95	195	Off Idle	34.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.11	20.23	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:33:9	19.09	2540	1.91	13.58	95	195	Off Idle	36.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.9	20.23	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:33:9	21.81	2452	1.94	13.59	95	195	Off Idle	39.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.5	20.23	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:0	21.81	2377	1.97	13.58	95	195	Off Idle	41.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.37	20.23	1.38	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:34:0	24.54	2377	1.98	13.57	95	195	Off Idle	44.5	0	2	132	944 Turbo	0.01	Lean	1	14.7	-6.96	20.23	1.38	3.9	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:34:0	24.54	2312	2.01	13.58	95	195	Off Idle	47.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-6.62	20.23	1.38	3.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:34:0	27.27	2197	2.03	13.56	95	195	Off Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.7	-6.26	20.24	1.38	3.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:0	29.99	2226	2.05	13.54	95	195	Off Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.93	20.24	1.38	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:0	29.99	2265	2.07	13.56	95	195	Off Idle	61.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.63	20.24	1.38	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:1	32.72	2285	2.09	13.57	95	195	Off Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.41	20.24	1.38	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:1	32.72	2285	2.12	13.54	95	195	Off Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-5.17	20.24	1.38	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:1	32.72	2310	2.15	13.56	95	195	Off Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.7	-5.01	20.24	1.38	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:1	32.72	2382	2.16	13.57	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-4.9	20.24	1.38	3.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:1	32.72	2428	2.19	13.56	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-4.81	20.22	1.38	3.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:1	32.72	2428	2.2	13.57	95	195	Off Idle	72.7	0	2	132	944 Turbo	0.03	Lean	1	14.7	-4.73	20.22	1.38	3.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:1	32.72	2550	2.24	13.58	95	195	Off Idle	73.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.66	20.23	1.38	3.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:2	32.72	2487	2.26	13.57	95	195	Off Idle	73.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.51	20.22	1.38	3.3	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:34:2	32.72	2493	2.28	13.56	95	195	Off Idle	74.3	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.41	20.21	1.38	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:34:2	32.72	2490	2.3	13.58	95	195	Off Idle	74.7	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.35	20.21	1.38	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:34:2	32.72	2466	2.33	13.57	95	195	Off Idle	74.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-4.17	20.01	1.36	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:34:2	32.72	2438	2.36	13.55	95	195	Off Idle	73.9	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.04	19.74	1.34	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:34:2	32.72	2424	2.38	13.55	95	195	Off Idle	73.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.89	19.41	1.32	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:34:3	32.72	2389	2.4	13.56	95	195	Off Idle	72.8	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.72	19.04	1.3	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:3	32.72	2350	2.41	13.56	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.62	18.64	1.27	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:3	31.36	2350	2.42	13.52	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.49	18.24	1.24	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:34:3	31.36	2312	2.43	13.49	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.32	17.81	1.21	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:34:3	31.36	2342	2.44	13.46	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.26	17.38	1.18	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:3	31.36	2347	2.45	13.41	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.15	16.95	1.15	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:4	31.36	2394	2.46	13.39	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.08	16.39	1.12	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:4	31.36	2402	2.48	13.39	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.24	Lean	1	14.7	-3.05	16.09	1.1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:4	31.36	2422	2.49	13.39	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.3	Lean	1	14.7	-3	15.98	1.09	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:4	31.36	2461	2.51	13.4	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.94	15.89	1.08	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:4	31.36	2466	2.52	13.38	95	195	Off Idle	72.5	0	2	132	944 Turbo	0.44	Lean	1	14.7	-2.87	15.81	1.08	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:4	31.36	2501	2.53	13.4	95	195	Off Idle	72.5	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.83	15.76	1.07	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:4	31.36	2490	2.54	13.4	95	195	Off Idle	72.5	0	2	132	944 Turbo	0.58	Lean	1	14.7	-2.75	15.7	1.07	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:5	31.36	2490	2.55	13.41	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.65	Lean	1	14.7	-2.68	15.61	1.06	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:5	31.36	2481	2.56	13.4	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.71	Lean	1	14.6	-2.66	15.52	1.06	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:5	31.36	2489	2.57	13.4	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.58	15.33	1.04	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:5	31.36	2489	2.57	13.38	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.53	15.18	1.03	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:5	32.72	2457	2.58	13.37	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.51	15.03	1.02	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:5	32.72	2453	2.58	13.37	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.43	14.91	1.02	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:6	32.72	2453	2.58	13.38	95	195	Off Idle	70.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.41	14.8	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:6	32.72	2458	2.59	13.39	95	195	Off Idle	69.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.41	14.73	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:34:6	32.72	2466	2.59	13.4	95	195	Off Idle	69	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.41	14.62	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:6	32.72	2469	2.6	13.4	95	195	Off Idle	68.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.36	14.51	0.99	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:6	32.72	2485	2.61	13.41	94	195	Off Idle	68.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.33	14.45	0.98	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:6	32.72	2501	2.61	13.41	94	195	Off Idle	67.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.37	14.42	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:6	32.72	2510	2.62	13.4	94	195	Off Idle	67.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-2.34	14.41	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:7	32.72	2512	2.63	13.39	95	195	Off Idle	67.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.33	14.39	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:7	32.72	2518	2.64	13.4	95	195	Off Idle	67.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.31	14.36	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:7	32.72	2517	2.64	13.4	95	195	Off Idle	67.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.31	14.32	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:7	32.72	2517	2.64	13.41	95	195	Off Idle	67.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.22	14.26	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:7	32.72	2523	2.65	13.42	95	195	Off Idle	67.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.23	14.19	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:7	32.72	2522	2.65	13.42	95	195	Off Idle	67.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.19	14.09	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:8	32.72	2524	2.65	13.41	95	195	Off Idle	67.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.21	14.04	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:8	32.72	2526	2.65	13.41	95	195	Off Idle	67.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.21	14.01	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:8	32.72	2546	2.66	13.4	95	195	Off Idle	66.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.19	13.97	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:8	32.72	2536	2.66	13.4	95	195	Off Idle	66.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.16	13.91	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:8	32.72	2540	2.66	13.4	95	195	Off Idle	66.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.16	13.9	0.95	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:8	32.72	2548	2.66	13.4	95	195	Off Idle	65.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.12	13.9	0.95	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:9	32.72	2554	2.67	13.41	95	195	Off Idle	65.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.11	13.93	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:9	32.72	2564	2.67	13.42	95	195	Off Idle	65.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.15	13.96	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:9	32.72	2564	2.68	13.41	95	195	Off Idle	64.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.1	14	0.95	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:9	32.72	2578	2.68	13.42	95	195	Off Idle	64.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.14	14.04	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:9	32.72	2582	2.68	13.42	95	195	Off Idle	64.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.17	14.09	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:34:9	32.72	2588	2.69	13.43	95	195	Off Idle	63.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.16	14.13	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:34:9	32.72	2588	2.69	13.44	95	195	Off Idle	63.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.11	14.16	0.96	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:0	32.72	2598	2.69	13.43	95	195	Off Idle	63.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.11	14.18	0.97	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:0	32.72	2601	2.7	13.41	95	195	Off Idle	63.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.05	14.2	0.97	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:0	32.72	2602	2.7	13.42	95	195	Off Idle	62.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.04	14.2	0.97	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:0	32.72	2602	2.7	13.41	95	195	Off Idle	62.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.08	14.18	0.97	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:0	32.72	2608	2.7	13.41	95	195	Off Idle	62.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.08	14.17	0.97	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:0	32.72	2612	2.7	13.42	95	195	Off Idle	62.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.06	14.17	0.97	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:1	32.72	2614	2.71	13.43	95	195	Off Idle	62.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.04	14.18	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:1	32.72	2624	2.71	13.43	95	195	Off Idle	61.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.04	14.18	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:1	32.72	2633	2.71	13.42	95	195	Off Idle	61.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.03	14.18	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:1	32.72	2634	2.71	13.41	95	195	Off Idle	61.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.98	14.19	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:1	32.72	2642	2.72	13.41	95	195	Off Idle	60.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.98	14.2	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:1	32.72	2649	2.72	13.4	95	195	Off Idle	60.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.03	14.23	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:35:1	32.72	2650	2.72	13.41	95	195	Off Idle	60.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.01	14.26	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:2	32.72	2653	2.73	13.41	95	195	Off Idle	59.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.04	14.27	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:2	32.72	2659	2.73	13.42	95	195	Off Idle	59.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.02	14.28	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:2	32.72	2660	2.73	13.44	95	196	Off Idle	59.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.01	14.27	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:2	32.72	2678	2.74	13.43	95	196	Off Idle	58.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.01	14.27	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:2	32.72	2672	2.74	13.44	95	195	Off Idle	58.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.03	14.29	0.97	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:2	32.72	2673	2.74	13.42	95	195	Off Idle	58.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2	14.31	0.97	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:3	32.72	2676	2.75	13.42	95	195	Off Idle	58	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.97	14.32	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:3	32.72	2686	2.75	13.43	95	196	Off Idle	57.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.98	14.32	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:3	32.72	2695	2.75	13.43	95	196	Off Idle	57.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.97	14.33	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:3	32.72	2696	2.75	13.42	95	196	Off Idle	57.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.94	14.34	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:3	32.72	2705	2.76	13.41	95	195	Off Idle	57.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.92	14.34	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:3	32.72	2710	2.76	13.42	95	195	Off Idle	57.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.9	14.35	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:4	32.72	2712	2.77	13.41	95	195	Off Idle	56.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.89	14.37	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:4	32.72	2714	2.77	13.43	95	195	Off Idle	56.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.85	14.37	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:4	32.72	2720	2.77	13.42	95	195	Off Idle	56.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.88	14.38	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:4	32.72	2727	2.78	13.42	95	195	Off Idle	56	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.84	14.37	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:4	32.72	2750	2.78	13.41	95	195	Off Idle	55.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.77	14.38	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:4	32.72	2742	2.78	13.41	95	195	Off Idle	55.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.81	14.38	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:4	32.72	2742	2.79	13.42	95	195	Off Idle	55.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.78	14.39	0.98	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:5	32.72	2743	2.79	13.42	95	195	Off Idle	55.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.76	14.39	0.98	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:5	32.72	2745	2.79	13.43	95	195	Off Idle	54.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.75	14.4	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:5	32.72	2748	2.8	13.41	95	195	Off Idle	54.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.75	14.42	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:5	32.72	2756	2.8	13.43	95	195	Off Idle	54.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.73	14.44	0.98	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:5	32.72	2767	2.8	13.42	95	195	Off Idle	54	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.7	14.45	0.98	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:5	32.72	2767	2.8	13.41	95	195	Off Idle	53.7	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.64	14.47	0.99	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:6	32.72	2775	2.81	13.42	95	195	Off Idle	53.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.65	14.47	0.99	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:6	32.72	2780	2.81	13.42	95	195	Off Idle	53.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.63	14.48	0.99	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:35:6	32.72	2782	2.81	13.43	95	195	Off Idle	52.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.64	14.51	0.99	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:6	32.72	2783	2.81	13.41	95	195	Off Idle	52.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.63	14.55	0.99	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:6	32.72	2782	2.82	13.43	95	195	Off Idle	52.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.65	14.56	0.99	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:6	32.72	2787	2.82	13.42	95	195	Off Idle	52	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.64	14.58	0.99	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:6	32.72	2798	2.82	13.43	95	195	Off Idle	51.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.63	14.6	0.99	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:7	32.72	2800	2.82	13.44	95	195	Off Idle	51.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.6	14.63	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:7	32.72	2814	2.83	13.45	95	195	Off Idle	51.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.63	14.65	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:7	32.72	2818	2.83	13.43	95	196	Off Idle	51	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.62	14.68	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:7	32.72	2820	2.83	13.45	95	196	Off Idle	50.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.64	14.72	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:7	32.72	2820	2.83	13.45	95	196	Off Idle	50.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.64	14.73	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:7	32.72	2824	2.84	13.43	95	195	Off Idle	49.9	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.6	14.74	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:8	32.72	2827	2.84	13.44	95	195	Off Idle	49.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.62	14.74	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:8	32.72	2824	2.84	13.43	95	195	Off Idle	49.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.62	14.75	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:8	32.72	2844	2.84	13.43	95	195	Off Idle	49	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.62	14.76	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:8	32.72	2852	2.85	13.43	95	195	Off Idle	48.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.59	14.77	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:8	32.72	2852	2.85	13.42	95	196	Off Idle	48.6	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.61	14.78	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:8	32.72	2869	2.85	13.42	95	196	Off Idle	48.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-1.56	14.79	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:9	32.72	2864	2.85	13.44	95	196	Off Idle	48	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.55	14.8	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:9	32.72	2866	2.85	13.44	95	195	Off Idle	47.7	0	2	132	944 Turbo	0.64	Rich	1	14.7	-1.56	14.81	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:35:9	32.72	2868	2.86	13.45	95	195	Off Idle	47.4	0	2	132	944 Turbo	0.57	Lean	1	14.7	-1.59	14.81	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:35:9	32.72	2870	2.86	13.43	95	195	Off Idle	47.3	0	2	132	944 Turbo	0.52	Lean	1	14.7	-1.57	14.82	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:35:9	32.72	2875	2.86	13.43	95	195	Off Idle	47.1	0	2	132	944 Turbo	0.47	Lean	1	14.7	-1.54	14.81	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:35:9	32.72	2877	2.87	13.43	95	195	Off Idle	46.9	0	2	132	944 Turbo	0.42	Lean	1	14.7	-1.56	14.81	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:35:9	32.72	2889	2.87	13.42	95	195	Off Idle	46.6	0	2	132	944 Turbo	0.39	Lean	1	14.7	-1.54	14.83	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:36:0	32.72	2895	2.87	13.43	95	195	Off Idle	46.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-1.53	14.84	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:36:0	32.72	2895	2.87	13.44	95	195	Off Idle	45.7	0	2	132	944 Turbo	0.38	Lean	1	14.7	-1.52	14.85	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:36:0	32.72	2911	2.88	13.44	95	196	Off Idle	45.5	0	2	132	944 Turbo	0.4	Lean	1	14.7	-1.54	14.88	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:0	32.72	2919	2.88	13.44	95	196	Off Idle	45.2	0	2	132	944 Turbo	0.43	Lean	1	14.7	-1.51	14.91	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:0	32.72	2923	2.88	13.43	95	196	Off Idle	44.9	0	2	132	944 Turbo	0.5	Lean	1	14.7	-1.53	14.99	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:0	32.72	2924	2.88	13.44	95	195	Off Idle	44.8	0	2	132	944 Turbo	0.56	Rich	1	14.7	-1.63	15.01	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:36:1	32.72	2947	2.88	13.42	95	195	Off Idle	44.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.6	15.02	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:36:1	32.72	2923	2.89	13.43	95	195	Off Idle	44.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-1.6	15	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:36:1	32.72	2923	2.89	13.42	95	195	Off Idle	44.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-1.59	14.97	1.02	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:36:1	32.72	2927	2.89	13.43	95	195	Off Idle	44.1	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.57	14.94	1.02	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:36:1	32.72	2931	2.89	13.42	95	195	Off Idle	43.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-1.54	14.91	1.02	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:36:1	32.72	2932	2.9	13.42	95	195	Off Idle	43.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-1.5	14.87	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:36:1	32.72	2936	2.9	13.42	95	195	Off Idle	43.2	0	2	132	944 Turbo	0.7	Rich	1	14.7	-1.52	14.82	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:36:2	32.72	2946	2.9	13.42	95	195	Off Idle	43.2	0	2	132	944 Turbo	0.63	Rich	1	14.7	-1.45	14.73	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:36:2	32.72	2980	2.9	13.42	95	196	Off Idle	43.1	0	2	132	944 Turbo	0.57	Rich	1	14.7	-1.48	14.68	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:36:2	32.72	2970	2.9	13.41	95	196	Off Idle	43	0	2	132	944 Turbo	0.5	Lean	1	14.7	-1.44	14.66	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:36:2	32.72	2965	2.9	13.43	95	196	Off Idle	42.8	0	2	132	944 Turbo	0.43	Lean	1	14.7	-1.47	14.67	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:36:2	32.72	2972	2.91	13.43	95	196	Off Idle	42.7	0	2	132	944 Turbo	0.37	Lean	1	14.7	-1.46	14.69	1	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:36:2	32.72	2988	2.91	13.43	95	196	Off Idle	42.5	0	2	132	944 Turbo	0.31	Lean	1	14.7	-1.5	14.73	1	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:36:3	32.72	2993	2.91	13.43	95	195	Off Idle	42.2	0	2	132	944 Turbo	0.25	Lean	1	14.7	-1.49	14.77	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:36:3	32.72	2996	2.91	13.43	95	195	Off Idle	42	0	2	132	944 Turbo	0.22	Lean	1	14.7	-1.51	14.83	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:36:3	32.72	3006	2.92	13.43	95	195	Off Idle	41.9	0	2	132	944 Turbo	0.23	Lean	1	14.7	-1.49	14.87	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:36:3	32.72	3017	2.92	13.42	95	195	Off Idle	41.7	0	2	132	944 Turbo	0.28	Lean	1	14.7	-1.51	14.93	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:3	32.72	3041	2.92	13.44	95	195	Off Idle	41.7	0	2	132	944 Turbo	0.33	Lean	1	14.7	-1.55	14.97	1.02	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:3	32.72	3030	2.92	13.42	95	195	Off Idle	41.7	0	2	132	944 Turbo	0.39	Lean	1	14.7	-1.49	15.01	1.02	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:4	32.72	3020	2.92	13.43	95	195	Off Idle	41.7	0	2	132	944 Turbo	0.45	Rich	1	14.7	-1.53	15.05	1.03	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:4	32.72	3010	2.93	13.43	95	195	Off Idle	41.7	0	2	132	944 Turbo	0.55	Rich	1	14.7	-1.5	15.07	1.03	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:4	32.72	3011	2.93	13.44	95	195	Off Idle	41.7	0	2	132	944 Turbo	0.58	Rich	1	14.7	-1.5	15.08	1.03	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:4	32.72	2986	2.93	13.43	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-1.44	15.06	1.03	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:4	32.72	3012	2.93	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.43	14.99	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:36:4	32.72	3009	2.94	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.49	14.94	1.02	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:36:4	32.72	3014	2.94	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.44	14.89	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:5	32.72	3030	2.94	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.45	14.86	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:5	32.72	3041	2.94	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.44	14.82	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:5	32.72	3041	2.94	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.44	14.76	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:5	32.72	3064	2.95	13.42	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.37	14.74	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:5	32.72	3072	2.95	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.38	14.73	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:6	34.08	3098	2.95	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.33	14.74	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:6	34.08	3080	2.95	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.27	14.77	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:6	34.08	3080	2.96	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-1.19	14.79	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:6	34.08	3079	2.96	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-1.22	14.81	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:36:6	32.72	3067	2.97	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	-1.18	14.82	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:36:6	32.72	3082	2.97	13.42	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.7	-1.19	14.84	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:36:6	32.72	3089	2.98	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.7	-1.18	14.84	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:36:6	32.72	3092	2.98	13.42	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.7	-1.13	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:36:7	32.72	3101	2.98	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.7	-1.13	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:36:7	32.72	3115	2.99	13.42	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-1.02	14.85	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:36:7	32.72	3125	2.99	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-0.99	14.88	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:36:7	32.72	3126	3	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.7	-0.94	14.91	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:36:7	32.72	3137	3.01	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.7	-0.88	14.95	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:36:7	32.72	3137	3.01	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-0.86	14.95	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:36:8	32.72	3148	3.02	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-0.81	15	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:36:8	32.72	3149	3.03	13.44	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.7	-0.75	15.06	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:36:8	32.72	3147	3.03	13.43	95	195	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.7	-0.69	15.09	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:36:8	32.72	3150	3.05	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.7	-0.71	15.1	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:36:8	32.72	3170	3.05	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.7	-0.6	15.11	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:36:8	32.72	3165	3.06	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	-0.55	15.1	1.03	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:36:9	32.72	3166	3.07	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.45	15.08	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:36:9	32.72	3166	3.07	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.41	15.03	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:36:9	32.72	3170	3.08	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.4	14.98	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:36:9	32.72	3188	3.08	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.34	14.94	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:36:9	32.72	3190	3.09	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.32	14.9	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:36:9	32.72	3196	3.09	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.28	14.84	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:36:9	32.72	3201	3.1	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.25	14.81	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:37:0	32.72	3216	3.1	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.19	14.8	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:0	32.72	3216	3.11	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.21	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:37:0	32.72	3217	3.12	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.19	14.83	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:0	32.72	3220	3.12	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.24	14.83	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:0	32.72	3232	3.12	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.21	14.86	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:37:0	32.72	3232	3.13	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	-0.19	14.87	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:37:1	32.72	3240	3.13	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-0.15	14.87	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:37:1	32.72	3237	3.13	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.7	-0.17	14.87	1.01	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:1	32.72	3228	3.13	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-0.15	14.86	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:1	32.72	3244	3.14	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	-0.09	14.86	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:1	32.72	3254	3.14	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.7	-0.09	14.85	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:1	32.72	3260	3.14	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.7	-0.1	14.83	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:1	32.72	3277	3.14	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.7	-0.03	14.86	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:2	32.72	3319	3.15	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-0.09	14.87	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:37:2	32.72	3301	3.15	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-0.04	14.96	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:2	32.72	3301	3.15	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	0	14.97	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:2	32.72	3310	3.15	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-0.05	14.97	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:2	32.72	3306	3.15	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.7	0.04	14.96	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:2	32.72	3306	3.16	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	0.02	14.94	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:3	32.72	3292	3.16	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	0.05	14.92	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:3	32.72	3292	3.16	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	0.07	14.9	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:3	32.72	3296	3.16	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	0.11	14.85	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:3	32.72	3308	3.16	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	0.12	14.84	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:3	32.72	3314	3.16	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	0.1	14.77	1.01	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:37:3	32.72	3310	3.17	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	0.13	14.74	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:4	32.72	3337	3.17	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	0.13	14.71	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:4	32.72	3343	3.17	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.7	0.04	14.7	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:4	32.72	3350	3.17	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.7	0.1	14.73	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:4	32.72	3370	3.17	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.7	0.1	14.78	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:4	32.72	3383	3.17	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.7	0.03	14.84	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:4	32.72	3380	3.17	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.7	0.09	14.86	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:4	32.72	3407	3.18	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.7	0.12	14.94	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:5	32.72	3391	3.18	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.7	0.03	15	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:5	32.72	3391	3.18	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.7	0.07	15.01	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:5	32.72	3388	3.18	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.7	0.13	15.03	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:5	32.72	3386	3.18	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.7	0.02	15.06	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:5	32.72	3391	3.19	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.7	0.06	15.05	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:5	32.72	3392	3.19	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	0.08	15.03	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:6	32.72	3398	3.19	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	0.03	14.98	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:6	32.72	3405	3.19	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	0.14	14.92	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:6	32.72	3416	3.19	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	0.15	14.89	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:6	32.72	3415	3.19	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.7	0.11	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:37:6	32.72	3414	3.19	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.7	0.16	14.78	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:6	32.72	3426	3.2	13.42	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.7	0.13	14.77	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:6	32.72	3428	3.2	13.43	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.7	0.08	14.77	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:7	32.72	3448	3.2	13.44	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	0.11	14.79	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:7	32.72	3458	3.2	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.7	0.13	14.82	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:7	32.72	3469	3.2	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	0.06	14.85	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:7	32.72	3472	3.2	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	0.1	14.9	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:37:7	32.72	3478	3.2	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	0.16	14.93	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:7	32.72	3474	3.21	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.7	0.11	14.97	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:8	32.72	3474	3.21	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.7	0.09	15.04	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:8	32.72	3479	3.21	13.44	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	0.07	15.06	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:8	32.72	3477	3.21	13.43	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.7	0.1	15.05	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:8	32.72	3473	3.21	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	0.06	15.04	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:8	32.72	3472	3.21	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.7	0.01	15.03	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:8	32.72	3478	3.21	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	0.01	15	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:37:9	32.72	3494	3.21	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	0.04	14.97	1.02	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:37:9	32.72	3498	3.21	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.7	0.08	14.93	1.02	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:9	32.72	3508	3.21	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.7	0.02	14.89	1.01	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:9	32.72	3526	3.21	13.42	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.7	0.06	14.87	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:9	32.72	3528	3.21	13.42	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	0.08	14.83	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:9	32.72	3557	3.21	13.44	94	196	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-0.08	14.84	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:37:9	34.08	3558	3.21	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-0.04	14.87	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:0	34.08	3558	3.21	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-0.04	14.87	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:0	34.08	3565	3.21	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	-0.06	14.96	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:38:0	34.08	3566	3.21	13.43	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	0.06	15.03	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:0	32.72	3562	3.21	13.42	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	-0.03	15.04	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:0	32.72	3557	3.21	13.42	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.7	-0.11	15.04	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:0	32.72	3552	3.21	13.41	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	-0.09	15.04	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:1	32.72	3534	3.21	13.41	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.6	Lean	1	14.7	-0.14	15.03	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:1	34.08	3481	3.21	13.43	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Lean	1	14.7	-0.22	14.98	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:1	34.08	3509	3.21	13.44	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.25	14.94	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:1	34.08	3552	3.21	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.2	14.9	1.01	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:1	34.08	3561	3.21	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-0.23	14.86	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:38:1	34.08	3583	3.21	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-0.21	14.78	1.01	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:38:1	34.08	3608	3.21	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.7	-0.27	14.72	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:38:2	34.08	3613	3.21	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-0.39	14.7	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:38:2	34.08	3638	3.21	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.7	-0.36	14.72	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:38:2	34.08	3655	3.21	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.7	-0.31	14.76	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:2	34.08	3668	3.21	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-0.3	14.8	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:2	34.08	3648	3.21	13.42	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.4	Rich	1	14.7	-0.26	14.86	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:2	34.08	3639	3.21	13.41	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.7	-0.3	14.93	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:3	34.08	3636	3.2	13.42	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.7	-0.49	14.93	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:3	34.08	3626	3.2	13.42	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-0.54	14.95	1.02	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:24:38:3	34.08	3619	3.2	13.41	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.7	-0.68	14.97	1.02	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:24:38:3	34.08	3621	3.2	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.7	-0.79	14.96	1.02	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:24:38:3	34.08	3624	3.2	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-0.79	14.94	1.02	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:24:38:3	34.08	3640	3.2	13.42	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.71	14.89	1.01	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:24:38:4	34.08	3664	3.19	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.77	14.88	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:38:4	34.08	3682	3.19	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.71	14.84	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:38:4	34.08	3685	3.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.75	14.81	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:38:4	34.08	3698	3.19	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.74	14.81	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:38:4	34.08	3729	3.19	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-0.88	14.72	1	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:38:4	34.08	3714	3.19	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-0.98	14.64	1	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:4	34.08	3702	3.19	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.06	14.55	0.99	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:38:5	34.08	3694	3.18	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.06	14.45	0.98	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:24:38:5	34.08	3694	3.18	13.47	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.04	14.34	0.98	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:5	34.08	3692	3.18	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.08	14.2	0.97	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:5	34.08	3688	3.18	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.12	14.08	0.96	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:5	34.08	3689	3.17	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.18	13.92	0.95	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:5	34.08	3690	3.17	13.46	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.29	13.77	0.94	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:38:6	34.08	3700	3.17	13.5	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.34	13.62	0.93	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:38:6	34.08	3718	3.16	13.49	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.28	13.54	0.92	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:24:38:6	34.08	3718	3.16	13.48	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.23	13.51	0.92	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:38:6	34.08	3734	3.16	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.23	13.46	0.92	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:38:6	35.45	3748	3.16	13.43	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.26	13.4	0.91	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:38:6	35.45	3759	3.15	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.37	13.39	0.91	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:24:38:6	35.45	3760	3.15	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.54	13.35	0.91	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:7	35.45	3768	3.15	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.61	13.32	0.91	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:7	34.08	3768	3.14	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.69	13.31	0.91	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:24:38:7	34.08	3763	3.14	13.45	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.61	13.3	0.91	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:7	34.08	3762	3.14	13.44	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.54	13.3	0.91	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:7	35.45	3766	3.13	13.41	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.5	13.31	0.91	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:7	35.45	3772	3.13	13.38	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.54	13.3	0.91	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:8	35.45	3773	3.13	13.37	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.63	13.29	0.91	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:38:8	35.45	3781	3.13	13.38	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.78	13.33	0.91	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:8	35.45	3780	3.12	13.39	95	196	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.93	13.36	0.91	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:8	35.45	3796	3.12	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.04	13.4	0.91	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:8	35.45	3794	3.12	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.04	13.46	0.92	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:8	35.45	3807	3.12	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.03	13.48	0.92	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:9	35.45	3817	3.12	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.93	13.51	0.92	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:9	35.45	3817	3.12	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.89	13.52	0.92	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:9	35.45	3822	3.11	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.9	13.54	0.92	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:9	35.45	3829	3.11	13.42	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.92	13.57	0.92	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:24:38:9	35.45	3830	3.11	13.41	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.07	13.58	0.93	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:9	35.45	3830	3.11	13.41	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.17	13.58	0.93	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:38:9	35.45	3846	3.11	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.31	13.56	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:0	35.45	3830	3.11	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.35	13.53	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:0	35.45	3830	3.11	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.33	13.49	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:0	35.45	3834	3.11	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.25	13.48	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:0	35.45	3843	3.11	13.49	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.18	13.45	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:0	35.45	3845	3.11	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.08	13.45	0.92	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:39:0	35.45	3846	3.11	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.06	13.45	0.92	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:24:39:1	35.45	3853	3.11	13.45	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.03	13.46	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:1	35.45	3864	3.11	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.07	13.49	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:1	35.45	3865	3.11	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.07	13.53	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:1	35.45	3865	3.11	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.12	13.57	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:1	35.45	3872	3.1	13.42	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.18	13.58	0.92	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:1	35.45	3878	3.1	13.43	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.25	13.61	0.93	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:1	35.45	3880	3.1	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.27	13.63	0.93	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:39:2	35.45	3883	3.1	13.44	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.34	13.65	0.93	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:2	35.45	3885	3.09	13.46	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.69	13.69	0.93	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:24:39:2	35.45	3887	3.08	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.08	13.69	0.93	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:39:2	35.45	3916	3.05	13.47	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.63	13.71	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:2	35.45	3880	3.01	13.48	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.32	13.71	0.93	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:39:2	35.45	3868	2.96	13.5	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-5.1	13.69	0.93	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:39:3	35.45	3865	2.9	13.5	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.88	13.7	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:39:3	36.81	3812	2.84	13.5	95	196	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.25	13.68	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:39:3	36.81	3819	2.73	13.5	95	196	Full Load	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.01	13.65	0.93	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:39:3	36.81	3818	2.66	13.46	95	196	Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.97	13.57	0.92	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:24:39:3	36.81	3745	2.59	13.45	95	196	Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-8.46	13.5	0.92	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:3	31.36	3734	2.52	13.45	95	196	Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-8.87	13.39	0.91	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:4	25.9	3731	2.45	13.45	95	196	Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-9.17	13.25	0.9	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:4	20.45	3725	2.38	13.45	95	196	Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.36	13.09	0.89	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:4	20.45	3720	2.31	13.48	95	196	Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.48	12.92	0.88	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:4	20.45	3714	2.23	13.49	95	196	Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.54	12.73	0.87	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:4	20.45	3673	2.12	13.47	95	196	Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-9.58	12.55	0.86	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:4	20.45	3667	2.05	13.45	95	196	Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-9.65	12.31	0.84	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:4	20.45	3608	1.98	13.45	95	196	Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-9.74	12.17	0.83	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:5	20.45	3594	1.91	13.45	95	196	Idle	41.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.78	12.04	0.82	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:5	20.45	3564	1.87	13.45	95	196	Idle	40.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.82	11.89	0.81	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:5	20.45	3481	1.81	13.47	95	196	Idle	39.8	0	2	132	944 Turbo	0.67	Lean	1	14.6	-9.84	11.84	0.81	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:5	20.45	3494	1.74	13.47	95	196	Idle	39.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.77	11.8	0.8	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:5	20.45	3494	1.71	13.47	95	196	Idle	38.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.68	11.82	0.81	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:5	20.45	3435	1.69	13.47	95	196	Idle	37.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.67	11.83	0.81	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:6	20.45	3419	1.68	13.47	95	196	Idle	36.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.63	11.87	0.81	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:6	20.45	3345	1.68	13.46	95	196	Idle	35.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.56	11.93	0.81	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:6	20.45	3364	1.68	13.46	95	196	Idle	33.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.56	12.03	0.82	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:6	20.45	3336	1.69	13.47	94	196	Idle	32.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.52	12.22	0.83	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:6	20.45	3307	1.69	13.47	94	196	Idle	31.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.46	12.38	0.84	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:6	20.45	3298	1.7	13.46	94	196	Idle	30.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.39	12.59	0.86	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:6	20.45	3268	1.71	13.47	95	196	Idle	29.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.33	12.96	0.88	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:7	20.45	3234	1.72	13.46	95	196	Idle	27.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.27	13.29	0.91	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:39:7	20.45	3200	1.73	13.46	95	196	Idle	26.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	13.83	0.94	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:7	20.45	3170	1.73	13.45	95	196	Idle	26	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.23	14.56	0.99	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:7	20.45	3163	1.74	13.47	95	196	Idle	24.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.16	15.71	1.07	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:7	20.45	3143	1.75	13.47	95	196	Idle	24	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.16	16.45	1.12	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:7	20.45	3095	1.77	13.46	95	196	Idle	23.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.06	17.16	1.17	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:8	20.45	3095	1.78	13.46	95	196	Idle	23.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.03	17.84	1.22	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:8	20.45	3046	1.79	13.46	95	196	Idle	23.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	18.48	1.26	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:8	20.45	3034	1.8	13.46	95	196	Idle	23.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	19.08	1.3	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:8	19.09	3014	1.81	13.47	95	196	Idle	23.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	19.83	1.35	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:8	19.09	2974	1.82	13.48	95	196	Idle	23.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	20	1.36	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:8	19.09	2955	1.83	13.46	95	196	Idle	23	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	20.16	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:9	19.09	2955	1.83	13.48	95	196	Idle	22.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.89	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:9	19.09	2929	1.84	13.47	95	196	Idle	22.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.84	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:9	19.09	2895	1.84	13.47	95	196	Full Load	22.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.8	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:9	19.09	2886	1.84	13.46	95	196	Off Idle	22.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.75	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:9	19.09	2832	1.85	13.47	95	196	Off Idle	22.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.72	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:9	19.09	2750	1.85	13.45	95	196	Off Idle	23.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.66	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:39:9	10.9	2798	1.86	13.45	95	196	Off Idle	24.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.58	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:24:40:0	10.9	2800	1.87	13.45	95	196	Off Idle	24.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.52	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:40:0	13.63	2774	1.89	13.44	95	196	Off Idle	28.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.42	20.26	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:40:0	16.36	2744	1.89	13.45	95	196	Off Idle	30.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.37	20.26	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:40:0	19.09	2737	1.91	13.45	95	196	Off Idle	32.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.19	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:40:0	19.09	2658	1.91	13.44	95	196	Off Idle	32.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.12	20.25	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:40:0	21.81	2640	1.93	13.45	95	196	Off Idle	36.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.87	20.24	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:40:1	24.54	2604	1.96	13.45	95	196	Off Idle	39.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.6	20.24	1.38	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:40:1	24.54	2596	1.97	13.45	95	196	Off Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.55	20.24	1.38	3.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:1	27.27	2552	1.99	13.44	95	196	Off Idle	44.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.39	20.23	1.38	3.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:1	29.99	2588	2.01	13.45	95	196	Off Idle	47.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.26	20.23	1.38	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:40:1	32.72	2592	2.03	13.44	95	196	Off Idle	49.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.13	20.22	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:40:1	32.72	2609	2.04	13.45	95	196	Off Idle	52.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.94	20.23	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:40:1	34.08	2620	2.07	13.46	95	196	Off Idle	54.7	0	2	132	944 Turbo	0.03	Lean	1	14.7	-6.75	20.23	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:40:2	34.08	2620	2.1	13.44	95	196	Off Idle	57.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.52	20.23	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:40:2	34.08	2652	2.13	13.46	95	196	Off Idle	57.9	0	2	132	944 Turbo	0.03	Lean	1	14.7	-6.27	20.24	1.38	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:40:2	34.08	2680	2.16	13.46	95	196	Off Idle	58.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-5.99	20.24	1.38	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:24:40:2	34.08	2688	2.19	13.45	95	196	Off Idle	59.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.72	20.24	1.38	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:40:2	34.08	2716	2.22	13.45	95	196	Off Idle	59.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.48	20.25	1.38	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:2	34.08	2722	2.25	13.44	95	196	Off Idle	59.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-5.32	20.25	1.38	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:3	34.08	2735	2.29	13.44	95	196	Off Idle	59.3	0	2	132	944 Turbo	0.05	Lean	1	14.7	-5.14	20.25	1.38	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:3	34.08	2725	2.31	13.44	95	196	Off Idle	59	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.95	20.26	1.38	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:3	34.08	2717	2.34	13.45	95	196	Off Idle	58.7	0	2	132	944 Turbo	0.05	Lean	1	14.7	-4.86	20.22	1.38	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:3	34.08	2680	2.35	13.44	95	196	Off Idle	58.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.82	20.16	1.37	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:3	34.08	2627	2.38	13.44	95	196	Off Idle	57.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.67	19.87	1.35	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:3	34.08	2616	2.39	13.45	95	196	Off Idle	57.3	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.61	19.61	1.34	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:40:4	34.08	2592	2.41	13.46	95	196	Off Idle	57	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.56	19.34	1.32	3.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:40:4	34.08	2579	2.43	13.44	95	196	Off Idle	56.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.44	19.06	1.3	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:40:4	34.08	2597	2.43	13.44	95	196	Off Idle	56.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.36	18.71	1.27	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:40:4	34.08	2637	2.45	13.43	95	197	Off Idle	57	0	2	132	944 Turbo	0.23	Lean	1	14.7	-4.31	18.53	1.26	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:40:4	32.72	2661	2.47	13.44	95	197	Off Idle	57	0	2	132	944 Turbo	0.29	Rich	1	14.6	-4.34	18.14	1.24	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:4	32.72	2689	2.48	13.44	95	197	Off Idle	57	0	2	132	944 Turbo	0.35	Rich	1	14.6	-4.35	17.69	1.21	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:4	32.72	2693	2.5	13.45	95	196	Off Idle	57	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.35	17.24	1.17	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:5	32.72	2699	2.51	13.46	95	196	Off Idle	57	0	2	132	944 Turbo	0.48	Rich	1	14.7	-4.37	16.86	1.15	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:5	34.08	2731	2.51	13.46	95	196	Off Idle	57	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.38	16.54	1.13	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:5	34.08	2704	2.51	13.46	95	197	Off Idle	57	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.33	16.27	1.11	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:5	34.08	2660	2.51	13.46	95	197	Off Idle	57.1	0	2	132	944 Turbo	0.65	Rich	1	14.7	-4.32	16.04	1.09	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:5	34.08	2644	2.51	13.46	95	197	Off Idle	57.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.28	15.81	1.08	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:5	32.72	2642	2.52	13.45	95	196	Off Idle	57.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.23	15.64	1.07	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:6	32.72	2619	2.52	13.46	95	196	Off Idle	57.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.21	15.49	1.06	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:6	32.72	2644	2.52	13.46	95	196	Off Idle	57.7	0	2	132	944 Turbo	0.75	Rich	1	14.7	-4.18	15.35	1.05	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:40:6	32.72	2659	2.52	13.45	95	196	Off Idle	57.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.15	15.2	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:6	32.72	2664	2.52	13.46	95	196	Off Idle	57.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.11	15.12	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:6	32.72	2685	2.52	13.45	95	196	Off Idle	57.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.14	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:6	32.72	2699	2.52	13.45	95	196	Off Idle	57.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-4.17	15.01	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:6	32.72	2699	2.52	13.45	95	196	Off Idle	57.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.18	14.96	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:7	32.72	2691	2.52	13.43	95	196	Off Idle	56.8	0	2	132	944 Turbo	0.7	Rich	1	14.7	-4.18	14.93	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:40:7	32.72	2678	2.52	13.43	95	197	Off Idle	56.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-4.19	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:40:7	32.72	2678	2.52	13.44	95	197	Off Idle	56.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4.16	14.81	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:7	32.72	2664	2.52	13.43	95	197	Off Idle	56.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.13	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:7	32.72	2661	2.53	13.42	95	196	Off Idle	57	0	2	132	944 Turbo	0.68	Rich	1	14.7	-4.1	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:7	32.72	2661	2.53	13.44	95	196	Off Idle	57	0	2	132	944 Turbo	0.67	Rich	1	14.7	-4.11	14.84	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:8	32.72	2658	2.53	13.43	95	197	Off Idle	57	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.08	14.87	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:8	32.72	2673	2.53	13.42	95	197	Off Idle	57	0	2	132	944 Turbo	0.64	Rich	1	14.7	-4.08	14.89	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:40:8	32.72	2693	2.53	13.43	95	197	Off Idle	56.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.06	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:8	32.72	2693	2.53	13.43	95	197	Off Idle	56.7	0	2	132	944 Turbo	0.53	Rich	1	14.7	-4.1	14.9	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:40:8	32.72	2707	2.53	13.44	95	197	Off Idle	56.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.11	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:40:8	32.72	2713	2.53	13.43	95	197	Off Idle	56.3	0	2	132	944 Turbo	0.38	Rich	1	14.7	-4.08	14.9	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:40:9	32.72	2713	2.53	13.45	95	197	Off Idle	56	0	2	132	944 Turbo	0.35	Rich	1	14.7	-4.1	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:40:9	32.72	2714	2.53	13.45	95	197	Off Idle	55.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-4.13	14.95	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:40:9	32.72	2731	2.53	13.43	95	197	Off Idle	55.7	0	2	132	944 Turbo	0.28	Rich	1	14.7	-4.07	14.95	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:40:9	34.08	2703	2.53	13.43	95	197	Off Idle	55.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-4.06	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:9	34.08	2702	2.53	13.43	95	197	Off Idle	55.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-4.14	14.97	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:9	34.08	2698	2.54	13.45	95	197	Off Idle	55.7	0	2	132	944 Turbo	0.33	Rich	1	14.7	-4.11	15.01	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:40:9	34.08	2695	2.54	13.43	95	197	Off Idle	55.7	0	2	132	944 Turbo	0.38	Rich	1	14.7	-4.14	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:0	34.08	2696	2.54	13.43	95	197	Off Idle	55.5	0	2	132	944 Turbo	0.45	Rich	1	14.7	-4.12	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:0	34.08	2698	2.54	13.45	95	197	Off Idle	55.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-4.12	15.13	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:0	34.08	2703	2.54	13.44	95	197	Off Idle	55.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-4.11	15.16	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:0	34.08	2704	2.54	13.43	95	197	Off Idle	55.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.07	15.16	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:0	32.72	2685	2.54	13.44	95	197	Off Idle	55.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.08	15.12	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:0	32.72	2708	2.54	13.44	95	197	Off Idle	54.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-4.07	15.08	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:1	32.72	2708	2.54	13.44	95	197	Off Idle	54.7	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.04	15.04	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:1	32.72	2704	2.55	13.43	95	197	Off Idle	54.7	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.06	14.97	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:1	32.72	2716	2.55	13.44	95	197	Off Idle	54.7	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.14	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:1	32.72	2706	2.55	13.44	95	197	Off Idle	54.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.11	14.9	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:1	32.72	2707	2.55	13.45	95	197	Off Idle	54.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-4.08	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:1	32.72	2715	2.55	13.46	95	197	Off Idle	54.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.12	14.79	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:1	32.72	2727	2.55	13.46	95	197	Off Idle	54.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-4.14	14.76	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:2	34.08	2721	2.55	13.45	95	197	Off Idle	54.7	0	2	132	944 Turbo	0.7	Rich	1	14.7	-4.11	14.76	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:2	34.08	2722	2.55	13.44	95	197	Off Idle	54.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.11	14.78	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:2	34.08	2724	2.55	13.44	95	197	Off Idle	54.6	0	2	132	944 Turbo	0.65	Lean	1	14.7	-4.14	14.8	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:2	34.08	2728	2.55	13.44	95	197	Off Idle	54.5	0	2	132	944 Turbo	0.61	Lean	1	14.7	-4.13	14.79	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:2	34.08	2729	2.55	13.43	95	197	Off Idle	54.2	0	2	132	944 Turbo	0.57	Lean	1	14.7	-4.07	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:2	34.08	2734	2.55	13.44	95	197	Off Idle	54	0	2	132	944 Turbo	0.52	Lean	1	14.7	-4.09	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:3	34.08	2737	2.55	13.43	95	197	Off Idle	53.9	0	2	132	944 Turbo	0.47	Lean	1	14.7	-4.09	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:3	34.08	2736	2.55	13.43	95	197	Off Idle	53.8	0	2	132	944 Turbo	0.42	Lean	1	14.7	-4.04	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:3	34.08	2734	2.55	13.43	95	197	Off Idle	53.6	0	2	132	944 Turbo	0.36	Lean	1	14.7	-4.02	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:3	34.08	2735	2.55	13.43	95	197	Off Idle	53.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-4.02	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:41:3	34.08	2740	2.55	13.43	95	197	Off Idle	53.4	0	2	132	944 Turbo	0.35	Lean	1	14.7	-4.01	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:41:3	34.08	2740	2.56	13.44	95	197	Off Idle	53.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.01	14.83	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:4	34.08	2745	2.56	13.45	95	197	Off Idle	53.1	0	2	132	944 Turbo	0.39	Rich	1	14.7	-4.04	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:4	34.08	2746	2.56	13.45	95	197	Off Idle	53	0	2	132	944 Turbo	0.44	Rich	1	14.6	-4.02	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:4	34.08	2746	2.56	13.45	95	197	Off Idle	52.9	0	2	132	944 Turbo	0.49	Rich	1	14.7	-4.04	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:4	34.08	2744	2.56	13.45	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.54	Rich	1	14.7	-4.03	14.94	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:4	34.08	2736	2.56	13.44	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.98	14.99	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:4	34.08	2736	2.56	13.44	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.65	Rich	1	14.7	-4	15.02	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:4	34.08	2738	2.56	13.44	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.69	Rich	1	14.7	-4.03	15.01	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:5	34.08	2727	2.57	13.44	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.04	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:5	34.08	2744	2.57	13.43	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.11	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:41:5	34.08	2747	2.57	13.43	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.09	14.99	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:5	34.08	2753	2.57	13.44	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.1	14.97	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:5	34.08	2753	2.57	13.44	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-4.08	14.94	1.02	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:5	34.08	2760	2.57	13.44	95	197	Off Idle	52.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-4.05	14.9	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:6	34.08	2765	2.57	13.43	95	197	Off Idle	52.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-3.99	14.84	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:6	34.08	2760	2.57	13.44	95	197	Off Idle	52.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-4.03	14.82	1.01	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:41:6	34.08	2780	2.57	13.43	95	197	Off Idle	52.2	0	2	132	944 Turbo	0.66	Rich	1	14.7	-4.02	14.82	1.01	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:6	34.08	2758	2.57	13.44	95	197	Off Idle	52	0	2	132	944 Turbo	0.61	Rich	1	14.7	-4.03	14.82	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:6	34.08	2755	2.57	13.44	94	197	Off Idle	51.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.06	14.82	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:6	34.08	2756	2.57	13.45	94	197	Off Idle	51.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4	14.81	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:6	34.08	2748	2.57	13.45	95	197	Off Idle	51.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-4.01	14.81	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:41:7	34.08	2763	2.57	13.45	95	197	Off Idle	51.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-4.04	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:41:7	34.08	2762	2.57	13.46	95	197	Off Idle	51.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.01	14.8	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:7	34.08	2770	2.57	13.45	95	197	Off Idle	51.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.03	14.82	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:7	34.08	2782	2.57	13.45	95	197	Off Idle	51.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.01	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:41:7	34.08	2779	2.57	13.45	95	197	Off Idle	51.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.03	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:41:7	34.08	2781	2.57	13.45	95	197	Off Idle	51.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.02	14.91	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:8	34.08	2782	2.58	13.45	95	197	Off Idle	51.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.04	14.96	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:41:8	34.08	2772	2.58	13.46	95	197	Off Idle	51.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.03	15	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:8	34.08	2780	2.58	13.46	95	197	Off Idle	51.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.09	15.02	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:8	34.08	2779	2.58	13.46	95	197	Off Idle	51.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.04	15.05	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:8	34.08	2777	2.58	13.45	95	197	Off Idle	51.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.01	15.08	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:8	34.08	2771	2.58	13.45	95	197	Off Idle	51.3	0	2	132	944 Turbo	0.45	Rich	1	14.7	-4	15.15	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:9	34.08	2794	2.58	13.44	95	197	Off Idle	51.2	0	2	132	944 Turbo	0.52	Rich	1	14.7	-4.02	15.17	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:9	34.08	2782	2.58	13.44	95	197	Off Idle	51	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.01	15.16	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:9	34.08	2774	2.58	13.44	94	197	Off Idle	51	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.01	15.11	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:9	34.08	2780	2.58	13.43	94	197	Off Idle	51	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.03	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:9	34.08	2784	2.58	13.43	94	197	Off Idle	51	0	2	132	944 Turbo	0.67	Rich	1	14.7	-4.05	15.04	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:41:9	34.08	2792	2.58	13.43	95	197	Off Idle	51	0	2	132	944 Turbo	0.67	Rich	1	14.7	-4.03	15	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:41:9	34.08	2796	2.58	13.44	95	197	Off Idle	50.9	0	2	132	944 Turbo	0.64	Rich	1	14.7	-4.04	14.99	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:0	34.08	2796	2.58	13.45	95	197	Off Idle	50.7	0	2	132	944 Turbo	0.61	Rich	1	14.7	-4.03	14.97	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:0	34.08	2790	2.58	13.45	95	197	Off Idle	50.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4	14.94	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:0	34.08	2764	2.58	13.46	95	197	Off Idle	50.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-3.98	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:0	34.08	2795	2.59	13.45	95	197	Off Idle	50.6	0	2	132	944 Turbo	0.44	Lean	1	14.7	-3.96	14.84	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:0	34.08	2795	2.59	13.45	95	197	Off Idle	50.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.98	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:0	34.08	2797	2.59	13.46	95	197	Off Idle	50.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.96	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:1	34.08	2800	2.59	13.45	95	197	Off Idle	50.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:1	34.08	2812	2.59	13.44	95	197	Off Idle	50.6	0	2	132	944 Turbo	0.26	Lean	1	14.7	-4	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:1	34.08	2812	2.59	13.42	95	197	Off Idle	50.6	0	2	132	944 Turbo	0.27	Lean	1	14.7	-4.03	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:1	34.08	2815	2.59	13.43	95	197	Off Idle	50.3	0	2	132	944 Turbo	0.29	Lean	1	14.7	-4.01	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:1	34.08	2815	2.59	13.46	95	197	Off Idle	50	0	2	132	944 Turbo	0.32	Lean	1	14.7	-4.04	14.87	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:1	34.08	2813	2.59	13.45	95	197	Off Idle	49.8	0	2	132	944 Turbo	0.38	Rich	1	14.7	-3.98	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:1	34.08	2808	2.59	13.45	95	197	Off Idle	49.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-3.96	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:2	34.08	2806	2.59	13.47	95	197	Off Idle	49.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	-4	15.02	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:2	34.08	2806	2.59	13.44	95	197	Off Idle	49.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	-3.98	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:2	34.08	2804	2.59	13.43	95	197	Off Idle	49.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-3.99	15.05	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:2	34.08	2807	2.6	13.44	95	197	Off Idle	49.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-4.03	15.04	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:2	34.08	2804	2.6	13.44	95	197	Off Idle	49.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-4	15.03	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:2	34.08	2807	2.6	13.44	95	197	Off Idle	49.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.02	15.01	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:3	34.08	2814	2.6	13.45	95	197	Off Idle	49	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.96	14.99	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:3	34.08	2814	2.6	13.46	95	197	Off Idle	49	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.97	14.98	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:3	34.08	2814	2.6	13.45	95	197	Off Idle	48.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-3.92	14.96	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:3	34.08	2820	2.6	13.44	95	197	Off Idle	48.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.94	14.91	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:3	34.08	2827	2.6	13.44	95	197	Off Idle	48.7	0	2	132	944 Turbo	0.37	Lean	1	14.7	-3.9	14.85	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:3	34.08	2830	2.6	13.44	95	197	Off Idle	48.7	0	2	132	944 Turbo	0.31	Lean	1	14.7	-3.96	14.81	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:4	34.08	2829	2.6	13.44	95	197	Off Idle	48.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.92	14.83	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:4	34.08	2832	2.6	13.44	95	197	Off Idle	48.6	0	2	132	944 Turbo	0.22	Lean	1	14.7	-3.95	14.85	1.01	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:42:4	34.08	2828	2.6	13.45	95	197	Off Idle	48.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.95	14.87	1.01	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:42:4	34.08	2826	2.6	13.44	95	197	Off Idle	48.3	0	2	132	944 Turbo	0.27	Lean	1	14.7	-3.98	14.91	1.02	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:4	34.08	2836	2.6	13.44	95	197	Off Idle	48.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.97	14.94	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:4	34.08	2836	2.61	13.44	94	197	Off Idle	48.2	0	2	132	944 Turbo	0.35	Lean	1	14.7	-3.96	14.94	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:4	34.08	2827	2.61	13.44	94	197	Off Idle	48.2	0	2	132	944 Turbo	0.42	Rich	1	14.7	-3.94	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:5	34.08	2830	2.61	13.44	94	197	Off Idle	48.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-3.94	15.02	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:5	34.08	2834	2.61	13.44	95	197	Off Idle	48.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-3.92	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:5	34.08	2836	2.61	13.44	95	197	Off Idle	48.2	0	2	132	944 Turbo	0.65	Rich	1	14.7	-3.95	15.06	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:5	34.08	2844	2.61	13.43	95	197	Off Idle	48.2	0	2	132	944 Turbo	0.68	Rich	1	14.7	-3.96	15.05	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:5	34.08	2844	2.61	13.44	95	197	Off Idle	48.2	0	2	132	944 Turbo	0.68	Rich	1	14.7	-3.98	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:5	34.08	2846	2.61	13.44	95	197	Off Idle	47.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.03	15.01	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:6	34.08	2868	2.61	13.44	95	197	Off Idle	47.6	0	2	132	944 Turbo	0.65	Rich	1	14.7	-4	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:6	34.08	2848	2.61	13.44	95	197	Off Idle	47.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-3.99	14.92	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:6	34.08	2848	2.61	13.44	95	197	Off Idle	47.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-4.03	14.91	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:6	34.08	2841	2.61	13.44	95	197	Off Idle	47.1	0	2	132	944 Turbo	0.56	Lean	1	14.7	-3.94	14.85	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:6	34.08	2825	2.61	13.44	95	197	Off Idle	47.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-3.97	14.81	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:42:6	34.08	2836	2.61	13.43	95	197	Off Idle	47.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-3.93	14.78	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:42:6	34.08	2848	2.62	13.44	95	197	Off Idle	47.1	0	2	132	944 Turbo	0.42	Lean	1	14.7	-3.95	14.8	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:42:7	34.08	2853	2.62	13.44	95	197	Off Idle	46.9	0	2	132	944 Turbo	0.35	Lean	1	14.7	-3.95	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:42:7	34.08	2854	2.62	13.43	95	197	Off Idle	46.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-3.94	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:42:7	34.08	2866	2.62	13.44	95	197	Off Idle	46.6	0	2	132	944 Turbo	0.35	Lean	1	14.7	-3.96	14.84	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:7	34.08	2858	2.62	13.44	95	197	Off Idle	46.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-3.98	14.86	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:7	34.08	2860	2.62	13.45	95	197	Off Idle	46.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.97	14.87	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:7	34.08	2860	2.62	13.43	95	197	Off Idle	46.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-3.96	14.89	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:8	34.08	2860	2.62	13.43	95	197	Off Idle	46.1	0	2	132	944 Turbo	0.47	Rich	1	14.7	-3.92	14.94	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:8	34.08	2861	2.62	13.43	95	197	Off Idle	46	0	2	132	944 Turbo	0.53	Rich	1	14.7	-3.94	15.01	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:8	34.08	2860	2.62	13.42	95	197	Off Idle	46.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.95	15.03	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:8	34.08	2858	2.62	13.43	95	197	Off Idle	46.1	0	2	132	944 Turbo	0.67	Rich	1	14.7	-3.94	15.01	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:8	34.08	2864	2.62	13.44	95	197	Off Idle	46.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.95	15	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:8	34.08	2869	2.62	13.44	95	197	Off Idle	46.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.01	14.97	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:9	34.08	2870	2.62	13.45	95	197	Off Idle	46.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-4	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:9	34.08	2879	2.62	13.45	95	197	Off Idle	46.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-3.96	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:9	34.08	2879	2.62	13.44	95	197	Off Idle	46.1	0	2	132	944 Turbo	0.74	Rich	1	14.7	-4.02	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:9	34.08	2880	2.62	13.44	95	197	Off Idle	46	0	2	132	944 Turbo	0.73	Rich	1	14.6	-3.99	14.81	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:9	34.08	2851	2.62	13.43	95	197	Off Idle	46	0	2	132	944 Turbo	0.72	Rich	1	14.7	-4.03	14.74	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:42:9	34.08	2858	2.62	13.43	95	197	Off Idle	46	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.95	14.71	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:42:9	34.08	2869	2.62	13.42	95	197	Off Idle	46	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4	14.68	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:0	34.08	2874	2.62	13.43	95	197	Off Idle	46	0	2	132	944 Turbo	0.7	Rich	1	14.7	-3.95	14.68	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:0	34.08	2877	2.62	13.43	95	197	Off Idle	46	0	2	132	944 Turbo	0.69	Rich	1	14.6	-3.97	14.71	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:0	34.08	2877	2.63	13.43	95	197	Off Idle	46.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.94	14.73	1	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:0	34.08	2877	2.63	13.44	95	197	Off Idle	46.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.91	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:0	34.08	2884	2.63	13.43	95	197	Off Idle	46.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.91	14.8	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:43:0	34.08	2886	2.63	13.44	95	197	Off Idle	46.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.94	14.81	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:43:1	34.08	2896	2.63	13.45	95	197	Off Idle	45.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.9	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:1	34.08	2894	2.63	13.45	95	197	Off Idle	45.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.97	14.82	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:1	34.08	2898	2.63	13.45	95	197	Off Idle	45.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.95	14.83	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:1	34.08	2900	2.63	13.46	95	197	Off Idle	45.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.98	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:1	34.08	2905	2.63	13.45	95	197	Off Idle	45.1	0	2	132	944 Turbo	0.2	Lean	1	14.7	-3.94	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:1	34.08	2901	2.63	13.45	95	197	Off Idle	45.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.99	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:1	34.08	2892	2.63	13.44	95	197	Off Idle	44.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.95	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:2	34.08	2879	2.63	13.43	95	197	Off Idle	44.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.93	14.95	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:2	34.08	2876	2.63	13.44	95	197	Off Idle	44.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-3.94	14.97	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:2	34.08	2876	2.63	13.43	95	197	Off Idle	44.5	0	2	132	944 Turbo	0.43	Lean	1	14.7	-3.9	15.02	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:2	34.08	2890	2.63	13.45	95	197	Off Idle	44.5	0	2	132	944 Turbo	0.49	Lean	1	14.7	-3.94	15.07	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:2	34.08	2898	2.63	13.43	95	197	Off Idle	44.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-3.92	15.09	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:2	34.08	2901	2.63	13.45	95	197	Off Idle	44.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.94	15.08	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:3	34.08	2908	2.63	13.44	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.94	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:3	34.08	2912	2.63	13.45	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-3.94	15.06	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:43:3	34.08	2912	2.63	13.43	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-3.97	15.03	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:43:3	34.08	2912	2.63	13.43	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.96	15.02	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:43:3	34.08	2907	2.63	13.45	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-3.96	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:43:3	34.08	2926	2.64	13.44	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-3.92	14.95	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:43:4	34.08	2915	2.64	13.46	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.93	14.9	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:43:4	34.08	2900	2.64	13.44	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.93	14.89	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:4	34.08	2907	2.64	13.45	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	-3.93	14.89	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:4	34.08	2907	2.64	13.43	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	-3.96	14.88	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:4	34.08	2908	2.64	13.43	95	197	Off Idle	44.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.97	14.87	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:4	34.08	2926	2.64	13.42	95	197	Off Idle	44.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.98	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:4	34.08	2929	2.64	13.42	95	197	Off Idle	43.8	0	2	132	944 Turbo	0.26	Lean	1	14.7	-3.94	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:5	34.08	2936	2.64	13.45	95	197	Off Idle	43.5	0	2	132	944 Turbo	0.22	Lean	1	14.7	-3.99	14.9	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:43:5	34.08	2948	2.64	13.43	95	197	Off Idle	43.4	0	2	132	944 Turbo	0.2	Lean	1	14.7	-3.94	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:43:5	34.08	2935	2.64	13.44	95	197	Off Idle	43.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-3.97	15.03	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:43:5	34.08	2929	2.64	13.43	95	197	Off Idle	43.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-3.96	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:5	34.08	2929	2.64	13.45	95	197	Off Idle	42.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.01	15.08	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:5	34.08	2921	2.64	13.43	95	197	Off Idle	42.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-3.93	15.1	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:6	34.08	2905	2.64	13.43	95	197	Off Idle	42.8	0	2	132	944 Turbo	0.45	Rich	1	14.7	-3.91	15.12	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:6	34.08	2915	2.64	13.43	95	197	Off Idle	42.8	0	2	132	944 Turbo	0.48	Rich	1	14.7	-3.95	15.15	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:6	34.08	2917	2.64	13.43	95	197	Off Idle	42.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.9	15.18	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:6	34.08	2919	2.64	13.46	95	197	Off Idle	42.8	0	2	132	944 Turbo	0.61	Rich	1	14.7	-3.94	15.18	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:6	34.08	2930	2.64	13.43	95	197	Off Idle	42.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.93	15.14	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:6	34.08	2939	2.64	13.44	95	197	Off Idle	42.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.93	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:6	34.08	2944	2.64	13.43	95	197	Off Idle	42.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.99	15.02	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:7	34.08	2944	2.64	13.43	95	197	Off Idle	42.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-3.94	14.97	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:7	34.08	2959	2.64	13.43	95	197	Off Idle	42.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-3.98	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:7	34.08	2945	2.65	13.44	95	197	Off Idle	42.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-3.95	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:7	34.08	2944	2.65	13.44	95	197	Off Idle	42.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-3.92	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:7	34.08	2942	2.65	13.45	95	197	Off Idle	42.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.95	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:7	34.08	2930	2.65	13.44	95	197	Off Idle	42.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.94	14.8	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:43:8	34.08	2929	2.65	13.44	95	197	Off Idle	42.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-3.98	14.83	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:8	34.08	2930	2.65	13.44	95	197	Off Idle	42.3	0	2	132	944 Turbo	0.3	Lean	1	14.7	-3.93	14.86	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:8	34.08	2930	2.65	13.45	95	197	Off Idle	42.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.97	14.87	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:8	34.08	2942	2.65	13.43	95	197	Off Idle	42	0	2	132	944 Turbo	0.41	Lean	1	14.7	-3.92	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:8	34.08	2950	2.65	13.44	95	197	Off Idle	41.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.95	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:8	34.08	2955	2.65	13.42	95	197	Off Idle	41.7	0	2	132	944 Turbo	0.54	Rich	1	14.7	-3.96	15	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:9	34.08	2957	2.65	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.98	15.02	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:9	34.08	2964	2.65	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	-3.95	15.04	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:43:9	34.08	2972	2.65	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-3.96	15.03	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:43:9	34.08	2956	2.65	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-4	15	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:43:9	34.08	2957	2.65	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-3.94	14.96	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:43:9	34.08	2951	2.65	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.04	14.94	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:43:9	34.08	2951	2.65	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-3.99	14.9	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:44:0	34.08	2928	2.65	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.7	-4.04	14.84	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:0	34.08	2948	2.66	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.7	-3.99	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:0	34.08	2959	2.66	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-4.04	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:0	34.08	2964	2.66	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.96	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:0	34.08	2985	2.66	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4	14.77	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:0	34.08	2984	2.66	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-3.96	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:1	34.08	2984	2.66	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.02	14.81	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:1	34.08	2977	2.66	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-3.99	14.83	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:1	34.08	2971	2.66	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.06	14.9	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:1	34.08	2971	2.66	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.02	14.95	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:44:1	34.08	2965	2.66	13.46	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.04	15	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:1	34.08	2964	2.66	13.45	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.04	15.02	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:1	34.08	2970	2.66	13.43	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	-4	15.05	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:44:2	34.08	2970	2.66	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.7	-4.04	15.11	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:44:2	34.08	2974	2.66	13.43	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-4.02	15.13	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:44:2	34.08	2981	2.66	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.03	15.13	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:44:2	34.08	2986	2.66	13.43	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.03	15.1	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:2	34.08	2986	2.66	13.46	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.01	15.05	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:2	34.08	2987	2.66	13.45	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-4	15.01	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:44:3	34.08	2984	2.66	13.46	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.04	14.98	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:3	34.08	2986	2.66	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-4.04	14.94	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:3	34.08	2989	2.66	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.06	14.92	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:3	34.08	2991	2.66	13.43	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-4.03	14.9	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:3	34.08	2993	2.66	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-3.98	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:3	34.08	2995	2.66	13.42	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.04	14.8	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:4	34.08	2995	2.66	13.42	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.7	-3.97	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:4	34.08	2999	2.66	13.42	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-3.98	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:4	34.08	2998	2.67	13.42	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.96	14.81	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:4	34.08	3000	2.67	13.42	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-3.99	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:4	34.08	3005	2.67	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.7	-3.92	14.88	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:4	34.08	3005	2.67	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.7	-3.89	14.92	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:4	34.08	3009	2.68	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-3.89	14.95	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:5	34.08	2998	2.68	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-3.83	14.98	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:44:5	34.08	2998	2.68	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-3.75	15.04	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:5	34.08	2992	2.69	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-3.6	15.11	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:5	34.08	3001	2.7	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-3.48	15.14	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:44:5	34.08	3011	2.71	13.44	94	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.39	15.13	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:44:5	34.08	3010	2.71	13.44	94	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.31	15.07	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:6	34.08	3022	2.72	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.31	15.04	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:6	34.08	3030	2.72	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-3.16	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:6	34.08	3030	2.73	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.7	-3.17	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:6	34.08	3036	2.74	13.41	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3.09	14.92	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:6	34.08	3029	2.74	13.42	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.7	-3.1	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:6	34.08	3026	2.76	13.42	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3	14.81	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:6	34.08	3020	2.76	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-3	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:7	34.08	3018	2.77	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.91	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:44:7	34.08	3018	2.77	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.92	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:44:7	34.08	3024	2.78	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.82	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:7	34.08	3033	2.79	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-2.85	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:7	34.08	3039	2.8	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-2.74	14.86	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:7	34.08	3039	2.8	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.76	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:8	34.08	3056	2.81	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.69	14.88	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:8	34.08	3038	2.81	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.69	14.85	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:8	34.08	3038	2.81	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.67	14.82	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:8	34.08	3040	2.82	13.44	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.64	14.79	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:8	34.08	3039	2.82	13.44	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.63	14.77	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:8	34.08	3038	2.82	13.44	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.64	14.77	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:9	34.08	3036	2.82	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.65	14.7	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:9	34.08	3039	2.83	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.65	14.68	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:9	34.08	3044	2.83	13.45	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.68	14.65	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:9	34.08	3033	2.83	13.42	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.65	14.64	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:9	34.08	3046	2.83	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.69	14.65	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:44:9	34.08	3048	2.84	13.43	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-2.65	14.66	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:44:9	34.08	3056	2.84	13.43	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.6	14.66	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:0	34.08	3057	2.84	13.43	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.64	14.66	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:0	34.08	3065	2.84	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.65	14.66	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:0	34.08	3068	2.84	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.67	14.71	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:0	34.08	3066	2.84	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.64	14.73	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:0	34.08	3066	2.84	13.46	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-2.65	14.74	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:0	34.08	3062	2.84	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.63	14.74	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:1	34.08	3065	2.84	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.59	14.76	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:45:1	34.08	3072	2.84	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.61	14.78	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:45:1	34.08	3078	2.84	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.62	14.78	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:1	34.08	3077	2.84	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.59	14.78	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:45:1	34.08	3086	2.84	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.6	14.79	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:1	34.08	3072	2.84	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.64	14.79	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:45:1	34.08	3066	2.84	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-2.6	14.8	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:2	34.08	3066	2.84	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	-2.65	14.81	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:2	34.08	3058	2.84	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	-2.58	14.83	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:2	34.08	3071	2.85	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-2.64	14.81	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:2	34.08	3075	2.85	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.7	-2.57	14.81	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:2	34.08	3084	2.85	13.46	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-2.65	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:2	34.08	3094	2.85	13.46	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-2.65	14.85	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:3	34.08	3093	2.85	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-2.64	14.89	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:3	34.08	3092	2.85	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.7	-2.63	14.92	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:3	34.08	3089	2.85	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.7	-2.63	14.96	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:3	34.08	3084	2.85	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.59	14.99	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:45:3	34.08	3082	2.85	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.7	-2.61	15.05	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:3	34.08	3086	2.85	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.7	-2.59	15.07	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:4	34.08	3086	2.85	13.43	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-2.57	15.09	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:4	34.08	3088	2.85	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-2.6	15.08	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:4	34.08	3100	2.85	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Lean	1	14.7	-2.54	15.06	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:4	34.08	3108	2.85	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.7	-2.58	15	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:4	34.08	3122	2.85	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.7	-2.5	14.94	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:4	34.08	3121	2.85	13.43	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.7	-2.55	14.92	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:4	34.08	3114	2.85	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.7	-2.49	14.87	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:5	34.08	3107	2.85	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-2.55	14.79	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:5	34.08	3110	2.85	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.7	-2.53	14.76	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:5	34.08	3110	2.86	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.54	14.75	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:5	34.08	3120	2.86	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.53	14.77	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:5	34.08	3115	2.86	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.52	14.79	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:45:5	34.08	3115	2.86	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.57	14.82	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:6	34.08	3124	2.86	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.54	14.87	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:6	34.08	3124	2.86	13.45	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-2.58	14.9	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:6	34.08	3136	2.86	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.56	14.96	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:6	34.08	3135	2.86	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	-2.61	14.97	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:6	34.08	3133	2.86	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	-2.53	14.98	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:6	34.08	3133	2.86	13.43	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-2.58	14.99	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:6	34.08	3126	2.86	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.52	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:7	34.08	3124	2.87	13.41	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-2.56	14.95	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:7	34.08	3123	2.87	13.43	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-2.52	14.91	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:7	34.08	3127	2.87	13.44	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.52	14.88	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:7	34.08	3132	2.87	13.44	95	197	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.49	14.83	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:7	34.08	3136	2.87	13.44	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-2.5	14.77	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:7	34.08	3140	2.87	13.45	95	197	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.51	14.76	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:8	34.08	3141	2.87	13.44	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.7	-2.48	14.75	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:45:8	34.08	3145	2.87	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-2.47	14.74	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:45:8	34.08	3146	2.87	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.7	-2.44	14.74	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:45:8	34.08	3150	2.87	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-2.5	14.74	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:45:8	34.08	3152	2.87	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.7	-2.46	14.76	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:45:8	34.08	3147	2.88	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.7	-2.51	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:9	34.08	3148	2.88	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.7	-2.44	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:9	34.08	3147	2.88	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-2.49	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:9	34.08	3157	2.88	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.7	-2.48	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:45:9	34.08	3156	2.88	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	-2.48	14.94	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:9	34.08	3152	2.88	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.48	14.96	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:9	34.08	3152	2.88	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.48	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:45:9	34.08	3152	2.88	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.45	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:0	34.08	3154	2.88	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-2.48	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:0	34.08	3159	2.88	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-2.45	14.84	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:0	34.08	3174	2.88	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-2.44	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:0	34.08	3174	2.88	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-2.42	14.77	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:46:0	34.08	3177	2.88	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-2.43	14.75	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:0	34.08	3177	2.88	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-2.44	14.7	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:1	34.08	3176	2.88	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-2.41	14.68	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:1	34.08	3178	2.88	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.7	-2.46	14.69	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:1	34.08	3179	2.88	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.7	-2.4	14.71	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:1	34.08	3179	2.88	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.48	14.72	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:46:1	34.08	3182	2.89	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-2.4	14.75	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:46:1	34.08	3184	2.89	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.47	14.82	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:1	34.08	3184	2.89	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.44	14.84	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:2	34.08	3185	2.89	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.46	14.91	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:2	34.08	3183	2.89	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.7	-2.37	14.93	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:2	34.08	3183	2.89	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.7	-2.43	14.92	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:2	34.08	3184	2.89	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.7	-2.36	14.92	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:2	34.08	3187	2.89	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-2.34	14.91	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:2	34.08	3188	2.89	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.36	14.9	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:3	34.08	3190	2.89	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.41	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:3	34.08	3198	2.89	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.39	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:3	34.08	3202	2.89	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-2.47	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:3	34.08	3205	2.89	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.45	14.77	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:3	34.08	3202	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.48	14.75	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:3	34.08	3203	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.39	14.74	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:4	34.08	3200	2.9	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.47	14.75	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:4	34.08	3200	2.9	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-2.38	14.77	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:4	34.08	3207	2.9	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-2.4	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:4	34.08	3211	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.42	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:4	34.08	3216	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.7	-2.4	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:4	34.08	3222	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-2.46	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:4	34.08	3220	2.9	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-2.46	14.81	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:5	34.08	3220	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-2.48	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:5	34.08	3216	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.26	Rich	1	14.7	-2.51	14.88	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:5	34.08	3221	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-2.49	14.91	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:5	34.08	3213	2.9	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.6	-2.48	14.92	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:5	34.08	3216	2.9	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-2.49	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:5	34.08	3221	2.9	13.42	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-2.45	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:6	34.08	3218	2.9	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-2.46	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:6	34.08	3218	2.9	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-2.44	15.03	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:6	34.08	3218	2.9	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.42	15.05	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:6	34.08	3229	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-2.42	15.06	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:6	34.08	3235	2.9	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-2.38	15.02	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:6	34.08	3238	2.9	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.39	14.99	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:6	34.08	3245	2.9	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Lean	1	14.7	-2.39	14.97	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:7	34.08	3250	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.65	Lean	1	14.6	-2.37	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:7	34.08	3250	2.9	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.6	-2.39	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:7	34.08	3249	2.9	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.39	14.91	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:7	34.08	3243	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.7	-2.35	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:7	34.08	3244	2.91	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-2.37	14.83	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:7	34.08	3259	2.91	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.7	-2.4	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:46:8	34.08	3250	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.33	14.88	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:8	34.08	3255	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-2.42	14.91	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:8	34.08	3252	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.7	-2.43	14.95	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:46:8	34.08	3252	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.25	Rich	1	14.7	-2.41	14.98	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:8	34.08	3257	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-2.43	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:8	34.08	3258	2.91	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-2.43	15.03	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:9	34.08	3259	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-2.43	15.08	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:9	34.08	3273	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	-2.47	15.1	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:9	34.08	3273	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-2.51	15.11	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:9	34.08	3254	2.91	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.46	15.09	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:9	34.08	3256	2.91	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.5	15.04	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:46:9	34.08	3256	2.91	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-2.46	15.01	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:46:9	34.08	3254	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.46	14.96	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:0	34.08	3270	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-2.45	14.94	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:0	34.08	3270	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-2.47	14.91	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:47:0	34.08	3274	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.46	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:47:0	34.08	3308	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-2.43	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:0	34.08	3281	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.45	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:0	34.08	3279	2.91	13.45	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.7	-2.38	14.84	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:1	34.08	3273	2.91	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-2.43	14.86	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:24:47:1	34.08	3282	2.91	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-2.44	14.9	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:1	34.08	3284	2.91	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-2.43	14.93	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:47:1	34.08	3289	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.42	14.95	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:47:1	34.08	3298	2.91	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-2.41	14.98	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:47:1	34.08	3296	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.36	15.05	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:1	34.08	3294	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.39	15.09	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:2	34.08	3283	2.91	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-2.36	15.09	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:2	34.08	3291	2.92	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.36	15.05	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:2	34.08	3292	2.92	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-2.45	15.02	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:2	34.08	3300	2.92	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.42	14.98	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:47:2	34.08	3268	2.92	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.44	14.94	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:47:2	34.08	3281	2.92	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.47	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:3	34.08	3302	2.92	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-2.45	14.87	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:3	34.08	3301	2.92	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-2.46	14.76	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:3	34.08	3304	2.92	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-2.46	14.73	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:3	34.08	3305	2.92	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-2.41	14.72	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:3	34.08	3307	2.92	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-2.48	14.72	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:3	34.08	3305	2.92	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-2.41	14.77	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:4	34.08	3305	2.92	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-2.39	14.81	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:4	34.08	3309	2.92	13.46	95	198	Off Idle	41.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.39	14.85	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:4	34.08	3308	2.92	13.47	95	198	Off Idle	41.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-2.39	14.87	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:4	34.08	3310	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.37	14.99	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:4	34.08	3310	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.38	15.01	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:4	34.08	3309	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.7	-2.42	15.06	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:4	34.08	3314	2.93	13.41	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.4	15.07	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:5	34.08	3312	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.4	15.06	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:5	34.08	3313	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.39	15.01	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:5	34.08	3314	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.38	14.94	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:5	34.08	3317	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.38	14.91	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:5	34.08	3322	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.37	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:5	34.08	3341	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-2.34	14.83	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:6	34.08	3342	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.47	14.77	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:6	34.08	3342	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-2.48	14.74	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:6	34.08	3336	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.49	14.72	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:6	34.08	3338	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.7	-2.53	14.72	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:6	34.08	3338	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-2.54	14.73	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:6	34.08	3336	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.7	-2.48	14.76	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:6	34.08	3338	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.7	-2.41	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:47:7	34.08	3338	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-2.48	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:47:7	34.08	3344	2.93	13.42	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-2.39	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:7	34.08	3344	2.93	13.42	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.7	-2.45	14.92	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:7	34.08	3360	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.7	-2.48	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:7	34.08	3351	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.7	-2.51	14.94	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:7	34.08	3348	2.93	13.44	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-2.51	14.97	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:8	34.08	3345	2.93	13.44	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.54	14.96	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:8	34.08	3340	2.93	13.44	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-2.54	14.96	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:8	34.08	3344	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.54	14.94	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:8	34.08	3344	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-2.48	14.94	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:47:8	34.08	3350	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-2.48	14.92	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:47:8	34.08	3350	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-2.48	14.86	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:9	34.08	3359	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.46	14.84	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:9	34.08	3360	2.93	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-2.45	14.82	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:9	34.08	3367	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-2.48	14.81	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:9	34.08	3369	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.7	-2.54	14.81	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:47:9	34.08	3366	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.7	-2.53	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:47:9	34.08	3365	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-2.47	14.88	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:47:9	34.08	3364	2.93	13.43	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-2.55	14.91	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:0	34.08	3362	2.93	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.58	14.94	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:0	34.08	3363	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-2.48	15	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:0	34.08	3363	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.7	-2.54	15.04	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:0	34.08	3364	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-2.46	15.05	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:0	34.08	3368	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-2.39	15.05	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:0	34.08	3366	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-2.41	15.04	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:1	34.08	3380	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.66	Lean	1	14.6	-2.44	15.01	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:1	34.08	3382	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.7	-2.51	14.99	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:1	34.08	3385	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.7	-2.52	14.93	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:1	34.08	3390	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.7	-2.56	14.89	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:1	34.08	3388	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-2.62	14.81	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:1	34.08	3397	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-2.6	14.79	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:1	34.08	3396	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-2.58	14.78	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:2	34.08	3402	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.62	14.8	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:2	34.08	3402	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.52	14.84	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:2	34.08	3400	2.93	13.42	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.48	14.91	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:2	34.08	3396	2.94	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-2.54	14.97	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:2	34.08	3392	2.94	13.44	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-2.47	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:2	34.08	3385	2.94	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.49	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:3	34.08	3391	2.94	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.7	-2.54	15.01	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:3	34.08	3391	2.94	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.58	15.01	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:3	34.08	3400	2.94	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.57	15	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:3	34.08	3403	2.94	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.58	14.97	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:3	34.08	3403	2.94	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.59	14.95	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:3	34.08	3403	2.94	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-2.66	14.92	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:4	34.08	3409	2.94	13.45	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-2.56	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:4	34.08	3410	2.94	13.44	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-2.61	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:48:4	34.08	3416	2.94	13.47	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.7	-2.63	14.79	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:48:4	34.08	3414	2.94	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-2.55	14.79	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:48:4	34.08	3418	2.94	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-2.58	14.8	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:4	34.08	3420	2.94	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-2.66	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:4	34.08	3424	2.94	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	-2.61	14.87	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:5	34.08	3444	2.94	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-2.63	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:5	34.08	3444	2.94	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-2.67	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:5	34.08	3410	2.94	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-2.58	15.01	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:5	34.08	3400	2.94	13.41	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.7	-2.56	15.05	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:5	34.08	3400	2.94	13.41	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.66	15.06	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:5	34.08	3372	2.94	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-2.66	15.07	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:6	34.08	3388	2.94	13.44	95	198	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-2.58	15.05	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:6	34.08	3417	2.94	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-2.64	15.03	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:6	34.08	3433	2.94	13.47	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-2.69	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:6	34.08	3434	2.94	13.47	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.64	14.98	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:6	34.08	3442	2.94	13.45	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-2.68	14.94	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:6	34.08	3445	2.94	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.75	14.9	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:6	34.08	3441	2.94	13.48	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-2.82	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:7	34.08	3430	2.94	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-2.77	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:48:7	34.08	3442	2.94	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.7	-2.81	14.76	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:24:48:7	34.08	3427	2.94	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.7	-2.8	14.77	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:7	34.08	3434	2.94	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.52	Rich	1	14.7	-2.78	14.77	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:7	34.08	3435	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-2.73	14.82	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:48:7	34.08	3434	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-2.73	14.87	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:8	34.08	3444	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.7	-2.81	14.9	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:8	34.08	3441	2.93	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-2.72	14.91	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:8	34.08	3442	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-2.7	14.93	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:8	34.08	3442	2.93	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-2.8	14.93	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:8	34.08	3444	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-2.83	14.94	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:48:8	34.08	3440	2.93	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.83	14.94	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:48:9	34.08	3445	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	-2.9	14.94	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:48:9	34.08	3448	2.93	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-2.87	14.94	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:24:48:9	34.08	3451	2.93	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.7	-2.89	14.9	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:24:48:9	34.08	3464	2.93	13.48	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.7	-2.83	14.87	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:9	34.08	3466	2.93	13.45	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-2.81	14.84	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:9	34.08	3468	2.93	13.47	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.7	-2.9	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:48:9	34.08	3468	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-2.89	14.87	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:0	34.08	3462	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-2.83	14.88	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:0	34.08	3462	2.93	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.92	14.9	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:0	34.08	3457	2.93	13.47	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-2.94	14.94	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:49:0	34.08	3453	2.93	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-2.89	15	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:49:0	34.08	3458	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.7	-2.89	15.05	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:0	34.08	3457	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-2.94	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:1	34.08	3460	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-2.9	15.05	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:49:1	34.08	3468	2.93	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-2.81	15.04	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:49:1	34.08	3470	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-2.9	15.02	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:49:1	34.08	3482	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-2.97	15.01	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:49:1	34.08	3487	2.93	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.7	-2.89	14.98	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:1	34.08	3488	2.93	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	-2.89	14.94	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:1	34.08	3481	2.92	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-3	14.87	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:2	34.08	3481	2.92	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-3.02	14.85	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:2	34.08	3480	2.92	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-2.9	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:49:2	34.08	3482	2.92	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-2.99	14.87	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:49:2	34.08	3470	2.92	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.01	14.91	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:24:49:2	35.45	3490	2.92	13.45	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-2.95	14.94	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:2	35.45	3480	2.92	13.44	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-3	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:3	35.45	3481	2.92	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-3.08	15.01	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:3	35.45	3482	2.92	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-3.01	15.07	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:3	35.45	3480	2.92	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-3.04	15.11	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:3	35.45	3479	2.92	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.15	15.12	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:3	35.45	3476	2.92	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-3.15	15.1	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:49:3	35.45	3476	2.91	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.7	-3.11	15.07	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:4	35.45	3488	2.91	13.44	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.18	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:4	35.45	3482	2.91	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-3.3	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:4	35.45	3482	2.9	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-3.29	14.98	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:4	35.45	3491	2.9	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-3.29	14.95	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:4	35.45	3499	2.9	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-3.38	14.92	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:4	35.45	3503	2.9	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.48	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:4	35.45	3504	2.89	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-3.48	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:5	35.45	3508	2.89	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-3.5	14.86	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:5	35.45	3510	2.88	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.62	14.89	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:5	35.45	3508	2.88	13.47	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.7	-3.63	14.9	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:5	35.45	3506	2.88	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-3.56	14.93	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:24:49:5	35.45	3500	2.88	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	-3.58	14.93	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:5	35.45	3499	2.87	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-3.66	14.94	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:6	35.45	3496	2.87	13.46	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-3.61	14.98	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:6	35.45	3500	2.87	13.44	94	198	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.62	15	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:6	35.45	3505	2.86	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-3.74	15.02	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:6	35.45	3515	2.86	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-3.71	15.01	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:6	35.45	3515	2.86	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.7	-3.71	14.98	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:24:49:6	35.45	3518	2.86	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-3.8	14.97	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:49:6	35.45	3513	2.86	13.46	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-3.8	14.95	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:24:49:7	35.45	3512	2.85	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-3.79	14.92	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:7	35.45	3514	2.85	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.94	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:7	35.45	3517	2.83	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-4.25	14.87	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:7	35.45	3516	2.81	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.55	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:24:49:7	35.45	3512	2.76	13.44	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.21	14.88	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:7	35.45	3502	2.72	13.43	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.72	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:49:8	35.45	3495	2.67	13.45	95	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.33	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:8	36.81	3490	2.61	13.45	95	198	Full Load	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.92	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:49:8	36.81	3467	2.55	13.46	95	198	Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.44	15.02	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:24:49:8	36.81	3437	2.49	13.43	95	198	Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.93	15.1	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:49:8	36.81	3382	2.44	13.46	95	198	Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.44	15.14	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:49:8	31.36	3382	2.38	13.45	95	198	Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.71	15.15	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:9	25.9	3365	2.32	13.45	95	198	Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.83	15.12	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:9	20.45	3350	2.26	13.45	95	198	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.11	14.99	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:49:9	20.45	3354	2.2	13.46	95	198	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.2	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:24:49:9	20.45	3338	2.14	13.46	95	198	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.31	14.68	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:49:9	20.45	3302	2.08	13.46	95	198	Idle	41.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.33	14.52	0.99	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:49:9	20.45	3302	2	13.46	95	198	Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-9.38	14.33	0.98	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:49:9	20.45	3269	1.94	13.45	94	198	Idle	41.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.4	14.03	0.96	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:0	20.45	3239	1.89	13.47	94	198	Idle	41.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.4	13.8	0.94	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:0	20.45	3152	1.84	13.46	94	198	Idle	40.9	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.39	13.61	0.93	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:0	20.45	3152	1.79	13.46	95	198	Idle	40.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.38	13.47	0.92	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:0	20.45	3161	1.76	13.47	95	198	Idle	39.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.36	13.36	0.91	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:0	20.45	3138	1.73	13.46	95	198	Idle	39.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.35	13.29	0.91	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:0	20.45	3091	1.71	13.46	95	198	Idle	38.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.3	13.23	0.9	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:1	20.45	3091	1.7	13.46	95	198	Idle	37.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.31	13.22	0.9	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:1	20.45	3043	1.71	13.47	95	198	Idle	36.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.22	13.25	0.9	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:1	19.09	3030	1.71	13.47	94	198	Idle	34.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.24	13.3	0.91	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:1	19.09	3022	1.72	13.46	94	198	Idle	34.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.15	13.38	0.91	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:1	19.09	2968	1.72	13.46	95	198	Idle	32.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.14	13.5	0.92	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:1	19.09	2950	1.72	13.44	95	198	Idle	31.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.08	13.64	0.93	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:1	19.09	2950	1.73	13.45	95	198	Idle	30.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.08	13.78	0.94	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:2	19.09	2911	1.74	13.44	94	198	Idle	29.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	13.94	0.95	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:2	19.09	2889	1.75	13.46	94	198	Idle	28.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.03	14.37	0.98	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:2	19.09	2857	1.76	13.45	94	198	Idle	27.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	14.81	1.01	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:2	19.09	2849	1.77	13.46	95	198	Idle	27	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.95	15.37	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:2	19.09	2825	1.77	13.44	95	198	Idle	26.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	16.01	1.09	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:2	19.09	2769	1.78	13.45	95	198	Idle	26.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.86	16.65	1.13	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:3	19.09	2772	1.78	13.45	94	198	Idle	25.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.82	17.27	1.18	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:3	19.09	2743	1.79	13.45	94	198	Idle	26	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.78	17.85	1.22	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:3	19.09	2735	1.8	13.46	94	198	Idle	26.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	18.4	1.25	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:3	19.09	2703	1.81	13.46	94	198	Idle	26.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.73	18.97	1.29	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:3	19.09	2679	1.82	13.46	95	198	Idle	26.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.72	19.47	1.33	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:3	19.09	2650	1.82	13.46	95	198	Idle	27.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.72	19.99	1.36	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:4	19.09	2638	1.82	13.47	95	198	Full Load	27.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.68	20.17	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:4	19.09	2585	1.83	13.48	95	198	Off Idle	28.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:4	19.09	2579	1.83	13.47	95	198	Off Idle	29.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.65	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:24:50:4	19.09	2505	1.83	13.47	95	198	Off Idle	30.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.57	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:50:4	10.9	2559	1.84	13.48	95	198	Off Idle	31.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.51	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:50:4	10.9	2539	1.85	13.46	95	198	Off Idle	32.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.41	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:50:4	13.63	2537	1.86	13.46	95	198	Off Idle	37.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.3	20.25	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:50:5	16.36	2530	1.87	13.44	95	198	Off Idle	39.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.17	20.26	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:50:5	19.09	2495	1.88	13.44	95	198	Off Idle	42.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.06	20.26	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:50:5	19.09	2495	1.89	13.46	95	198	Off Idle	45	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.87	20.26	1.38	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:50:5	21.81	2556	1.9	13.45	95	198	Off Idle	47.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.72	20.25	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:50:5	24.54	2595	1.91	13.44	95	198	Off Idle	49.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.57	20.25	1.38	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:50:5	24.54	2690	1.93	13.45	94	198	Off Idle	51.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.42	20.25	1.38	3.3	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:50:6	27.27	2690	1.96	13.46	94	198	Off Idle	53.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.32	20.25	1.38	3.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:50:6	29.99	2654	1.98	13.45	94	198	Off Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.17	20.25	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:50:6	29.99	2663	2	13.45	95	198	Off Idle	57.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.05	20.26	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:6	32.72	2665	2.01	13.44	95	198	Off Idle	58.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.96	20.26	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:6	34.08	2668	2.02	13.45	95	198	Off Idle	59.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.96	20.26	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:6	34.08	2671	2.05	13.44	95	198	Off Idle	61.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.87	20.26	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:50:6	34.08	2664	2.07	13.44	95	198	Off Idle	62.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.81	20.26	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:7	34.08	2652	2.09	13.45	95	198	Off Idle	62.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.77	20.25	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:7	34.08	2596	2.11	13.45	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.75	20.26	1.38	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:7	34.08	2546	2.13	13.42	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.64	20.26	1.38	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:7	34.08	2534	2.14	13.43	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.59	20.27	1.38	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:7	34.08	2504	2.16	13.43	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.53	20.27	1.38	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:7	34.08	2517	2.16	13.45	94	198	Off Idle	60.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.5	20.26	1.38	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:8	34.08	2502	2.17	13.44	94	198	Off Idle	60.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.45	20.21	1.38	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:8	34.08	2502	2.18	13.45	94	198	Off Idle	60.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.47	20.09	1.37	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:8	34.08	2570	2.19	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.46	19.99	1.36	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:8	34.08	2603	2.2	13.45	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.48	19.6	1.33	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:8	34.08	2663	2.2	13.46	94	198	Off Idle	61.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.5	19.28	1.31	3.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:8	34.08	2646	2.19	13.44	95	198	Off Idle	61.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.5	18.93	1.29	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:9	34.08	2628	2.18	13.44	95	198	Off Idle	61.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.52	18.37	1.25	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:9	34.08	2609	2.18	13.44	95	198	Off Idle	62.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.5	18.01	1.23	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:9	34.08	2576	2.18	13.45	94	198	Off Idle	62.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.5	17.62	1.2	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:9	34.08	2576	2.19	13.44	94	198	Off Idle	62.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.52	17.25	1.17	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:9	34.08	2549	2.19	13.44	94	198	Off Idle	62.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.5	16.95	1.15	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:50:9	34.08	2539	2.19	13.44	95	198	Off Idle	62.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.47	16.73	1.14	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:50:9	34.08	2539	2.18	13.45	95	198	Off Idle	62.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.42	16.5	1.12	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:0	34.08	2531	2.18	13.44	95	198	Off Idle	62.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.44	16.44	1.12	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:0	34.08	2561	2.18	13.44	95	198	Off Idle	62.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.42	16.34	1.11	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:0	34.08	2582	2.18	13.44	95	198	Off Idle	62.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.4	16.19	1.1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:0	34.08	2586	2.18	13.44	95	198	Off Idle	62.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.37	16.08	1.1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:0	34.08	2600	2.18	13.44	95	198	Off Idle	61.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.43	16	1.09	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:51:0	34.08	2608	2.18	13.44	95	198	Off Idle	61.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.42	15.9	1.08	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:1	34.08	2608	2.18	13.43	95	198	Off Idle	61.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.43	15.82	1.08	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:1	34.08	2602	2.18	13.43	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.45	15.74	1.07	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:1	34.08	2590	2.18	13.43	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.49	15.68	1.07	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:1	34.08	2567	2.18	13.43	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.46	15.61	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:1	34.08	2564	2.18	13.44	94	198	Off Idle	61.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.43	15.59	1.06	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:1	34.08	2555	2.18	13.44	94	198	Off Idle	61.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.41	15.56	1.06	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:1	34.08	2515	2.18	13.45	94	198	Off Idle	61.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.41	15.54	1.06	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:2	34.08	2515	2.18	13.45	94	198	Off Idle	61.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.41	15.51	1.06	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:2	34.08	2565	2.18	13.44	94	198	Off Idle	61.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.4	15.5	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:2	34.08	2575	2.18	13.45	94	198	Off Idle	61.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.41	15.48	1.05	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:2	34.08	2595	2.18	13.45	94	198	Off Idle	61.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.43	15.42	1.05	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:2	34.08	2598	2.18	13.46	94	198	Off Idle	61.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.41	15.38	1.05	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:2	34.08	2628	2.18	13.46	95	198	Off Idle	61.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.42	15.33	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:3	34.08	2608	2.19	13.46	95	198	Off Idle	61.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.42	15.29	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:3	34.08	2600	2.19	13.45	95	198	Off Idle	61.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.4	15.24	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:3	34.08	2594	2.19	13.44	95	198	Off Idle	61.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.37	15.22	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:3	34.08	2576	2.19	13.44	95	198	Off Idle	61.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.36	15.21	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:3	34.08	2571	2.2	13.43	95	198	Off Idle	61.8	0	2	132	944 Turbo	0.27	Lean	1	14.7	-6.37	15.2	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:3	34.08	2571	2.2	13.43	95	198	Off Idle	61.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.28	15.21	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:4	34.08	2569	2.2	13.44	95	198	Off Idle	61.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.3	15.21	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:4	34.08	2570	2.2	13.43	95	198	Off Idle	61.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.26	15.23	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:4	34.08	2562	2.2	13.44	95	198	Off Idle	61.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.25	15.24	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:4	34.08	2578	2.2	13.45	95	198	Off Idle	61.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.28	15.21	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:4	34.08	2582	2.2	13.46	95	198	Off Idle	61.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.3	15.2	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:4	34.08	2584	2.2	13.46	95	198	Off Idle	61.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.28	15.2	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:4	34.08	2602	2.2	13.46	95	198	Off Idle	61.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.31	15.19	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:51:5	34.08	2592	2.2	13.47	95	198	Off Idle	61.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.27	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:5	34.08	2593	2.2	13.45	95	198	Off Idle	61.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.28	15.13	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:5	34.08	2592	2.2	13.43	95	198	Off Idle	61.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.31	15.09	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:5	34.08	2590	2.21	13.44	95	198	Off Idle	61.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.3	15.02	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:5	34.08	2586	2.21	13.45	94	198	Off Idle	61.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.29	14.96	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:5	34.08	2586	2.21	13.43	94	198	Off Idle	61.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.34	14.93	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:6	34.08	2584	2.21	13.44	94	198	Off Idle	61.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.28	14.91	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:6	34.08	2588	2.21	13.44	94	198	Off Idle	61.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.29	14.89	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:6	34.08	2589	2.21	13.43	94	198	Off Idle	61.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.32	14.88	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:6	34.08	2590	2.21	13.44	94	198	Off Idle	61.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.3	14.89	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:6	34.08	2594	2.2	13.44	94	198	Off Idle	61.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.31	14.91	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:6	34.08	2596	2.2	13.43	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.33	14.94	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:6	34.08	2596	2.2	13.44	94	198	Off Idle	61.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.31	14.98	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:7	34.08	2594	2.2	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.33	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:7	34.08	2594	2.2	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.33	Rich	1	14.7	-6.36	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:7	34.08	2587	2.2	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.33	15.12	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:7	34.08	2583	2.21	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.3	15.15	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:7	34.08	2583	2.21	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.33	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:7	34.08	2583	2.21	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.32	15.16	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:8	34.08	2582	2.21	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.26	15.18	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:8	34.08	2586	2.21	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.33	15.17	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:8	34.08	2586	2.2	13.44	95	198	Off Idle	61.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.34	15.13	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:8	34.08	2591	2.2	13.44	95	198	Off Idle	61.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.33	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:8	34.08	2587	2.2	13.45	95	198	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.33	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:8	34.08	2587	2.2	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.39	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:9	34.08	2588	2.2	13.44	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.35	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:9	34.08	2587	2.2	13.44	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.35	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:9	34.08	2587	2.2	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.39	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:9	34.08	2584	2.2	13.46	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.41	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:9	34.08	2583	2.2	13.46	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.35	14.87	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:51:9	34.08	2585	2.2	13.47	95	198	Off Idle	61.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.37	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:51:9	34.08	2585	2.2	13.47	95	198	Off Idle	61.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.36	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:52:0	34.08	2590	2.2	13.46	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.37	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:52:0	34.08	2594	2.2	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.38	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:52:0	34.08	2595	2.2	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.44	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:52:0	34.08	2595	2.2	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.44	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:24:52:0	34.08	2594	2.19	13.44	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.44	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:52:0	34.08	2594	2.19	13.43	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.48	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:52:1	34.08	2592	2.19	13.44	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.51	14.87	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:24:52:1	34.08	2582	2.19	13.44	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.5	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:52:1	34.08	2589	2.19	13.44	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.52	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:52:1	34.08	2584	2.19	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.53	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:52:1	34.08	2585	2.19	13.46	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.54	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:52:1	34.08	2602	2.18	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.54	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:52:1	34.08	2596	2.18	13.46	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.57	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:52:2	34.08	2599	2.18	13.44	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.62	15.05	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:52:2	34.08	2606	2.18	13.43	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.62	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:52:2	34.08	2598	2.18	13.43	94	198	Off Idle	61	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.63	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:24:52:2	34.08	2604	2.17	13.45	94	198	Off Idle	60.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.7	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:52:2	34.08	2602	2.17	13.44	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.7	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:52:2	34.08	2594	2.17	13.45	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.72	15.02	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:52:3	34.08	2610	2.16	13.45	94	198	Off Idle	60.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.77	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:52:3	34.08	2610	2.16	13.45	94	199	Off Idle	60.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.84	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:52:3	34.08	2590	2.15	13.45	94	199	Off Idle	60.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.88	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:52:3	34.08	2582	2.14	13.45	94	199	Off Idle	60.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.93	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:52:3	34.08	2577	2.14	13.45	95	198	Off Idle	60.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:52:3	34.08	2577	2.13	13.45	95	198	Off Idle	60.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.08	14.89	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:24:52:4	34.08	2584	2.12	13.44	95	198	Off Idle	60.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.1	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:52:4	34.08	2591	2.11	13.45	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.17	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:52:4	34.08	2591	2.11	13.45	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.23	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:52:4	34.08	2607	2.1	13.46	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.31	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:52:4	34.08	2602	2.09	13.44	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.37	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:4	34.08	2604	2.08	13.43	94	198	Off Idle	60.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.39	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:4	34.08	2602	2.07	13.43	94	198	Off Idle	60.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.43	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:5	34.08	2594	2.07	13.43	95	198	Off Idle	60.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.51	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:24:52:5	34.08	2590	2.06	13.42	95	198	Off Idle	60.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.52	14.86	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:5	34.08	2588	2.05	13.43	95	198	Off Idle	61.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.53	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:5	34.08	2581	2.04	13.43	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.57	14.9	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:5	34.08	2582	2.03	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.62	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:5	34.08	2580	2.02	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.65	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:6	34.08	2583	2.01	13.43	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.68	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:6	34.08	2582	2.01	13.43	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:6	34.08	2586	2	13.43	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:6	34.08	2591	2	13.43	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:6	34.08	2583	1.99	13.42	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.77	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:6	34.08	2598	1.99	13.41	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.81	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:6	35.45	2615	1.99	13.43	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.82	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:7	35.45	2615	1.99	13.44	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.82	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:7	35.45	2605	1.98	13.44	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.89	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:7	35.45	2603	1.98	13.44	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.89	14.98	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:7	35.45	2601	1.98	13.44	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.89	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:7	35.45	2597	1.98	13.45	95	198	Off Idle	61.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.92	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:7	35.45	2595	1.98	13.43	95	198	Off Idle	61.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.91	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:8	35.45	2592	1.98	13.44	95	198	Off Idle	60.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.88	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:8	35.45	2593	1.98	13.46	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.86	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:8	35.45	2594	1.98	13.46	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.86	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:8	35.45	2597	1.98	13.44	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.85	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:8	35.45	2588	1.98	13.46	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.84	14.9	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:8	34.08	2582	1.97	13.46	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.89	14.92	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:24:52:9	34.08	2592	1.97	13.44	94	198	Off Idle	60.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.89	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:9	34.08	2599	1.97	13.45	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.85	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:9	34.08	2594	1.97	13.46	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.88	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:9	34.08	2594	1.97	13.45	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.88	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:9	34.08	2613	1.97	13.45	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.86	15.09	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:9	35.45	2590	1.97	13.46	94	198	Off Idle	60.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.86	15.11	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:52:9	35.45	2590	1.97	13.47	95	198	Off Idle	60.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.89	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:0	35.45	2590	1.97	13.45	95	198	Off Idle	60.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.9	15.12	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:0	35.45	2569	1.97	13.44	95	198	Off Idle	61	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.88	15.14	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:0	35.45	2593	1.97	13.46	95	198	Off Idle	61	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.91	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:0	35.45	2593	1.97	13.45	95	198	Off Idle	61	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.97	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:0	35.45	2594	1.97	13.43	95	198	Off Idle	61	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.96	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:0	35.45	2596	1.96	13.44	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.69	Lean	1	14.6	-7.98	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:1	35.45	2606	1.96	13.45	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.66	Lean	1	14.6	-8.01	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:1	35.45	2592	1.96	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.04	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:1	35.45	2590	1.96	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.02	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:1	35.45	2590	1.95	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.09	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:1	35.45	2587	1.95	13.46	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.1	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:1	35.45	2591	1.95	13.46	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.11	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:1	35.45	2596	1.95	13.44	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.11	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:2	35.45	2598	1.95	13.46	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.12	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:2	35.45	2594	1.95	13.46	95	198	Off Idle	61.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.11	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:2	35.45	2604	1.94	13.45	95	199	Off Idle	61.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.12	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:2	35.45	2604	1.94	13.46	95	199	Off Idle	61.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.12	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:2	35.45	2600	1.94	13.45	94	199	Off Idle	61.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.11	14.77	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:2	35.45	2586	1.94	13.47	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.1	14.79	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:3	35.45	2582	1.94	13.45	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.1	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:53:3	35.45	2582	1.94	13.44	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.08	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:3	35.45	2584	1.94	13.44	94	199	Off Idle	61.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.1	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:3	35.45	2594	1.94	13.44	94	199	Off Idle	61.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.1	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:3	35.45	2594	1.94	13.45	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.11	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:3	35.45	2600	1.94	13.45	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.11	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:4	35.45	2604	1.94	13.45	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.11	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:4	35.45	2609	1.94	13.45	94	198	Off Idle	60.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.1	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:4	35.45	2608	1.94	13.46	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.1	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:4	35.45	2610	1.94	13.45	94	198	Off Idle	60.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.1	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:4	35.45	2611	1.94	13.44	94	198	Off Idle	60.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.14	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:4	35.45	2598	1.94	13.45	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.12	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:4	35.45	2596	1.94	13.43	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.1	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:5	35.45	2590	1.94	13.45	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.11	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:5	35.45	2588	1.94	13.43	94	198	Off Idle	60.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.12	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:5	35.45	2586	1.94	13.44	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.1	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:5	35.45	2586	1.94	13.44	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.1	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:5	35.45	2587	1.94	13.44	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.13	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:5	35.45	2591	1.94	13.45	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.11	14.91	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:6	35.45	2593	1.94	13.45	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.11	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:6	35.45	2596	1.94	13.46	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.1	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:6	35.45	2595	1.94	13.47	94	199	Off Idle	60.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.12	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:6	35.45	2594	1.94	13.46	94	199	Off Idle	60.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.1	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:6	35.45	2594	1.94	13.45	94	199	Off Idle	60.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.1	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:6	35.45	2597	1.94	13.46	94	199	Off Idle	60.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.11	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:6	35.45	2596	1.94	13.45	94	199	Off Idle	60.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.13	14.91	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:7	35.45	2594	1.94	13.46	94	199	Off Idle	60.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.12	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:7	35.45	2594	1.94	13.45	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.14	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:7	35.45	2589	1.94	13.46	94	198	Off Idle	60.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.12	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:7	35.45	2586	1.94	13.47	94	198	Off Idle	60.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.1	15.09	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:7	35.45	2582	1.94	13.45	94	198	Off Idle	60.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.13	15.13	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:7	35.45	2582	1.94	13.45	94	198	Off Idle	60.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.1	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:8	35.45	2591	1.94	13.44	94	198	Off Idle	60.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.13	15.14	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:53:8	35.45	2596	1.94	13.44	94	198	Off Idle	60.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.13	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:8	35.45	2596	1.94	13.43	94	198	Off Idle	60.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.16	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:8	35.45	2598	1.94	13.45	94	198	Off Idle	60.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.16	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:8	35.45	2598	1.94	13.45	94	198	Off Idle	60.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.2	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:8	35.45	2598	1.94	13.45	94	198	Off Idle	60.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.2	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:9	35.45	2596	1.94	13.44	94	198	Off Idle	61	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.18	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:9	35.45	2595	1.94	13.45	94	198	Off Idle	61	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.15	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:9	35.45	2593	1.94	13.44	94	198	Off Idle	61	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.17	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:9	35.45	2589	1.94	13.44	94	198	Off Idle	61	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.17	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:9	35.45	2594	1.94	13.46	94	198	Off Idle	61	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.17	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:9	35.45	2594	1.94	13.46	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.2	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:53:9	35.45	2594	1.94	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.2	14.9	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:0	35.45	2595	1.94	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.17	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:0	35.45	2596	1.93	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.16	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:0	35.45	2596	1.93	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.17	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:0	35.45	2598	1.93	13.46	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.15	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:0	35.45	2601	1.93	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.2	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:0	35.45	2598	1.93	13.45	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.21	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:1	35.45	2598	1.93	13.45	94	199	Off Idle	60.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.21	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:1	35.45	2592	1.93	13.46	94	199	Off Idle	60.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.22	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:1	35.45	2586	1.93	13.47	94	199	Off Idle	60.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.23	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:1	35.45	2586	1.93	13.46	94	199	Off Idle	61.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.21	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:1	35.45	2583	1.93	13.45	94	199	Off Idle	61.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.2	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:1	35.45	2584	1.93	13.46	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.21	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:1	35.45	2564	1.93	13.44	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.24	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:2	35.45	2576	1.93	13.43	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.21	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:54:2	35.45	2590	1.93	13.43	94	198	Off Idle	61.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.22	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:2	35.45	2590	1.92	13.43	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.26	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:2	35.45	2590	1.92	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.26	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:2	35.45	2589	1.92	13.44	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.29	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:2	35.45	2592	1.92	13.44	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.26	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:3	35.45	2592	1.92	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.26	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:3	35.45	2591	1.92	13.45	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.27	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:3	35.45	2612	1.92	13.44	94	198	Off Idle	61.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.27	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:3	35.45	2595	1.92	13.45	94	198	Off Idle	61.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.28	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:3	35.45	2595	1.91	13.46	94	198	Off Idle	61.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.33	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:54:3	35.45	2595	1.91	13.45	94	198	Off Idle	61.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.32	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:54:4	35.45	2589	1.91	13.45	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.31	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:4	35.45	2589	1.91	13.46	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.32	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:4	35.45	2587	1.91	13.47	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.31	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:4	35.45	2589	1.91	13.46	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.3	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:4	35.45	2595	1.91	13.45	94	199	Off Idle	61	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.3	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:4	35.45	2594	1.91	13.46	94	199	Off Idle	61	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.31	14.79	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:4	35.45	2592	1.91	13.45	94	199	Off Idle	61	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.31	14.81	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:5	35.45	2595	1.91	13.44	94	199	Off Idle	61	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.31	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:5	35.45	2596	1.91	13.43	94	199	Off Idle	61	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.3	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:5	35.45	2597	1.91	13.44	94	199	Off Idle	61	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.28	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:5	35.45	2600	1.91	13.46	94	199	Off Idle	61	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.27	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:5	35.45	2599	1.91	13.44	94	198	Off Idle	61	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.3	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:5	35.45	2598	1.91	13.45	94	198	Off Idle	61	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.29	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:6	35.45	2596	1.91	13.46	94	198	Off Idle	61.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.28	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:6	35.45	2594	1.91	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.29	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:6	35.45	2586	1.91	13.47	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.3	14.9	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:6	35.45	2584	1.91	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.3	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:6	35.45	2582	1.91	13.46	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.28	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:6	35.45	2578	1.91	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.3	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:6	35.45	2580	1.91	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.31	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:7	35.45	2582	1.91	13.43	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.27	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:7	35.45	2588	1.91	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.25	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:7	35.45	2585	1.91	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.29	15.17	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:7	35.45	2585	1.91	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.23	15.16	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:7	35.45	2590	1.91	13.44	95	199	Off Idle	61.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.26	15.16	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:7	35.45	2592	1.91	13.44	95	199	Off Idle	61.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.25	15.16	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:8	35.45	2592	1.91	13.45	95	199	Off Idle	61.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.26	15.16	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:8	35.45	2589	1.91	13.46	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.28	15.15	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:8	35.45	2587	1.91	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.31	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:8	35.45	2586	1.91	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.29	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:8	35.45	2584	1.91	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.3	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:54:8	35.45	2581	1.91	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.29	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:9	35.45	2582	1.91	13.44	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.28	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:9	35.45	2582	1.91	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.31	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:9	35.45	2587	1.91	13.46	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.29	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:9	35.45	2588	1.91	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.28	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:9	35.45	2593	1.91	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.3	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:9	35.45	2593	1.91	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.29	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:54:9	35.45	2598	1.91	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.28	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:0	35.45	2600	1.91	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.31	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:0	35.45	2595	1.91	13.46	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.3	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:0	35.45	2591	1.91	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.31	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:0	35.45	2590	1.91	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.29	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:0	35.45	2587	1.91	13.46	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.28	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:0	35.45	2586	1.91	13.45	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.3	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:1	35.45	2596	1.91	13.43	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.28	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:1	35.45	2584	1.91	13.43	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.27	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:55:1	35.45	2585	1.91	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.29	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:1	35.45	2586	1.91	13.44	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.29	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:1	35.45	2587	1.91	13.43	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.27	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:1	35.45	2592	1.91	13.43	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.27	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:1	35.45	2597	1.91	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.3	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:2	35.45	2597	1.91	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.31	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:2	35.45	2595	1.91	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.31	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:2	35.45	2586	1.91	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.32	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:2	35.45	2586	1.91	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.34	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:2	35.45	2585	1.91	13.46	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.31	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:2	35.45	2580	1.91	13.46	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.35	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:3	35.45	2578	1.91	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.33	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:3	35.45	2578	1.91	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.33	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:3	35.45	2581	1.91	13.44	95	199	Off Idle	61.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.31	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:3	35.45	2584	1.91	13.44	95	199	Off Idle	61.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.29	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:3	35.45	2584	1.91	13.44	95	199	Off Idle	61.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.29	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:3	35.45	2584	1.91	13.44	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.31	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:4	35.45	2587	1.91	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.29	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:4	35.45	2588	1.91	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.31	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:4	35.45	2592	1.91	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.17	Rich	1	14.6	-8.32	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:4	35.45	2592	1.91	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.29	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:4	35.45	2592	1.91	13.44	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.31	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:4	35.45	2590	1.91	13.44	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.3	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:4	35.45	2578	1.91	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.3	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:5	35.45	2585	1.91	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.31	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:5	35.45	2584	1.91	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.3	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:5	35.45	2583	1.91	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.31	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:5	35.45	2584	1.91	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.32	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:5	35.45	2584	1.91	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.34	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:5	35.45	2584	1.91	13.43	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.34	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:6	35.45	2548	1.91	13.43	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.31	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:6	35.45	2589	1.91	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.29	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:6	35.45	2590	1.91	13.43	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.3	15.08	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:6	35.45	2616	1.91	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.31	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:6	35.45	2598	1.91	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.3	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:6	35.45	2598	1.91	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.31	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:6	35.45	2594	1.91	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.33	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:7	35.45	2586	1.91	13.46	94	199	Off Idle	61.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.35	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:7	35.45	2584	1.91	13.45	94	199	Off Idle	61	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.31	14.91	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:7	35.45	2584	1.91	13.45	94	199	Off Idle	61	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.32	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:7	35.45	2578	1.91	13.45	94	199	Off Idle	61	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.3	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:7	35.45	2573	1.91	13.45	94	199	Off Idle	61	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.27	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:7	35.45	2552	1.91	13.46	94	199	Off Idle	61	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.28	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:8	34.08	2552	1.91	13.46	94	199	Off Idle	61	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.29	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:8	34.08	2575	1.91	13.45	94	199	Off Idle	61	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.28	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:8	34.08	2579	1.91	13.45	94	199	Off Idle	60.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.28	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:8	34.08	2579	1.91	13.45	94	198	Off Idle	60.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.3	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:8	34.08	2581	1.91	13.46	94	198	Off Idle	60.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.29	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:8	34.08	2588	1.91	13.46	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.26	14.91	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:9	35.45	2598	1.91	13.46	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.22	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:55:9	35.45	2594	1.91	13.47	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.25	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:9	35.45	2588	1.91	13.45	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.26	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:9	35.45	2602	1.91	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.24	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:9	35.45	2585	1.91	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.27	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:9	35.45	2583	1.91	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.26	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:55:9	35.45	2580	1.91	13.47	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.25	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:0	35.45	2578	1.91	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.26	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:0	35.45	2578	1.91	13.45	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.27	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:56:0	35.45	2571	1.91	13.45	94	198	Off Idle	61.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.24	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:0	35.45	2577	1.91	13.44	94	198	Off Idle	61.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.25	15.13	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:0	35.45	2577	1.91	13.44	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.23	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:0	35.45	2582	1.91	13.44	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.22	15.13	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:1	35.45	2588	1.91	13.43	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.21	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:1	35.45	2590	1.91	13.45	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.23	15.06	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:1	35.45	2591	1.91	13.46	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.21	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:1	35.45	2594	1.91	13.48	94	198	Off Idle	61.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.22	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:1	35.45	2588	1.92	13.48	94	198	Off Idle	61.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.2	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:1	35.45	2588	1.92	13.47	94	198	Off Idle	61.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.22	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:1	35.45	2584	1.92	13.46	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.21	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:2	35.45	2577	1.92	13.47	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.21	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:2	35.45	2578	1.92	13.46	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.2	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:2	35.45	2580	1.92	13.45	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.22	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:2	35.45	2582	1.92	13.47	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.21	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:2	35.45	2583	1.92	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.19	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:2	35.45	2587	1.92	13.46	94	198	Off Idle	61.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.19	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:3	35.45	2586	1.92	13.47	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.22	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:3	35.45	2586	1.92	13.44	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.19	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:3	35.45	2584	1.92	13.46	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.19	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:3	35.45	2582	1.92	13.46	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.21	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:3	35.45	2582	1.92	13.44	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.21	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:3	35.45	2582	1.92	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.17	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:4	35.45	2582	1.93	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.21	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:4	35.45	2581	1.93	13.45	94	198	Off Idle	61.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.2	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:4	35.45	2582	1.93	13.46	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.17	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:4	35.45	2587	1.93	13.44	94	198	Off Idle	61.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.2	15.05	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:4	35.45	2587	1.93	13.46	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.2	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:4	35.45	2588	1.93	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.18	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:4	35.45	2587	1.93	13.43	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.18	15.01	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:5	35.45	2586	1.93	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.19	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:5	35.45	2582	1.93	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.2	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:5	35.45	2582	1.93	13.44	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.16	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:5	35.45	2580	1.93	13.45	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.15	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:5	35.45	2575	1.93	13.45	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.17	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:5	35.45	2575	1.93	13.45	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.14	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:6	35.45	2574	1.93	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.14	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:6	35.45	2575	1.93	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.16	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:6	35.45	2578	1.93	13.45	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.17	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:6	35.45	2580	1.93	13.45	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.18	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:6	35.45	2609	1.93	13.45	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.17	14.9	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:6	35.45	2591	1.93	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.18	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:6	35.45	2590	1.93	13.46	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.21	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:7	35.45	2579	1.93	13.45	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.21	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:7	35.45	2581	1.93	13.44	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.19	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:7	35.45	2580	1.93	13.42	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.18	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:7	35.45	2574	1.92	13.44	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.2	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:7	35.45	2582	1.92	13.44	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.19	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:7	35.45	2574	1.92	13.43	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.18	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:8	35.45	2572	1.92	13.43	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.21	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:8	35.45	2576	1.92	13.46	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.22	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:8	35.45	2582	1.92	13.46	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.21	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:56:8	35.45	2582	1.92	13.46	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.2	15.04	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:8	35.45	2585	1.92	13.46	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.21	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:8	35.45	2585	1.92	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.21	14.99	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:9	35.45	2586	1.92	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.21	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:9	35.45	2586	1.92	13.44	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.22	14.94	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:9	35.45	2583	1.92	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.21	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:56:9	35.45	2575	1.92	13.44	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.21	14.89	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:9	35.45	2574	1.92	13.43	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.18	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:9	35.45	2560	1.92	13.44	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.21	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:56:9	35.45	2571	1.92	13.45	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.21	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:0	35.45	2576	1.92	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.21	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:0	35.45	2579	1.92	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.2	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:0	35.45	2585	1.92	13.46	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.23	14.9	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:0	35.45	2587	1.92	13.46	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.25	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:0	35.45	2588	1.92	13.46	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.22	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:0	35.45	2583	1.92	13.45	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.19	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:1	35.45	2600	1.92	13.45	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.19	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:1	35.45	2588	1.92	13.46	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.2	15.05	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:1	35.45	2574	1.92	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.19	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:1	35.45	2574	1.92	13.44	94	199	Off Idle	61.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.17	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:1	35.45	2572	1.92	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.2	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:1	35.45	2570	1.92	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.22	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:1	35.45	2573	1.92	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.21	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:2	35.45	2575	1.92	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.21	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:2	35.45	2577	1.92	13.45	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.21	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:2	35.45	2560	1.92	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.22	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:2	35.45	2572	1.92	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.21	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:2	35.45	2584	1.92	13.45	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.2	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:2	35.45	2587	1.92	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.22	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:3	35.45	2585	1.92	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.24	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:3	35.45	2583	1.92	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.23	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:3	35.45	2574	1.92	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.27	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:3	35.45	2575	1.92	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.24	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:3	35.45	2575	1.91	13.47	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.26	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:3	35.45	2578	1.91	13.47	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.21	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:4	35.45	2578	1.91	13.47	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.23	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:4	35.45	2583	1.91	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.21	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:4	35.45	2584	1.91	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.21	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:4	35.45	2598	1.91	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.21	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:4	35.45	2588	1.91	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.23	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:4	35.45	2586	1.91	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.26	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:4	35.45	2585	1.91	13.44	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.28	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:57:5	35.45	2580	1.91	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.3	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:5	35.45	2574	1.91	13.43	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.32	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:5	35.45	2571	1.91	13.45	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.34	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:5	35.45	2571	1.91	13.43	94	199	Off Idle	61.3	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.34	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:5	35.45	2573	1.9	13.43	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.35	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:5	35.45	2574	1.9	13.43	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.36	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:6	35.45	2573	1.9	13.43	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.37	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:24:57:6	35.45	2555	1.9	13.41	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.39	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:6	35.45	2575	1.89	13.42	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.41	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:6	35.45	2577	1.89	13.43	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.44	15.04	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:6	35.45	2577	1.89	13.44	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.48	15.07	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:6	35.45	2577	1.88	13.45	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.51	15.08	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:6	35.45	2578	1.88	13.45	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.51	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:7	35.45	2577	1.88	13.45	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.53	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:7	35.45	2577	1.87	13.45	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.58	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:7	35.45	2575	1.87	13.46	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.56	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:7	35.45	2575	1.87	13.45	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.63	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:7	35.45	2574	1.86	13.45	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.62	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:7	35.45	2571	1.86	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.63	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:8	35.45	2571	1.86	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.62	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:8	35.45	2571	1.86	13.44	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.62	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:8	35.45	2570	1.85	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.62	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:57:8	35.45	2575	1.85	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.66	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:8	35.45	2560	1.85	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.67	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:8	35.45	2570	1.85	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.64	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:9	35.45	2580	1.85	13.44	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.66	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:9	35.45	2579	1.85	13.45	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.67	14.83	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:9	35.45	2585	1.85	13.46	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.69	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:9	35.45	2569	1.84	13.46	94	199	Off Idle	61.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.69	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:9	35.45	2566	1.84	13.45	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.69	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:9	35.45	2565	1.84	13.46	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.67	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:57:9	35.45	2574	1.84	13.45	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.73	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:58:0	35.45	2563	1.84	13.47	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.74	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:58:0	35.45	2561	1.83	13.46	94	199	Off Idle	62	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.81	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:58:0	35.45	2561	1.83	13.46	94	199	Off Idle	62	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.8	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:58:0	35.45	2563	1.83	13.45	94	199	Off Idle	62	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.78	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:58:0	35.45	2566	1.83	13.46	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.82	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:24:58:0	35.45	2566	1.82	13.45	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.19	Rich	1	14.6	-8.86	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:1	35.45	2571	1.82	13.45	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.84	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:1	35.45	2536	1.82	13.44	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.9	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:1	35.45	2576	1.81	13.44	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.93	14.97	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:1	35.45	2574	1.81	13.45	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.94	14.98	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:1	35.45	2567	1.81	13.44	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.98	15.02	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:1	35.45	2602	1.8	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.97	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:1	35.45	2582	1.8	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.98	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:2	35.45	2562	1.8	13.45	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:2	35.45	2563	1.79	13.45	94	199	Off Idle	61.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.03	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:2	35.45	2565	1.79	13.46	94	199	Off Idle	61.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.03	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:2	35.45	2565	1.79	13.45	94	199	Off Idle	61.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.05	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:2	35.45	2567	1.78	13.45	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.04	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:2	35.45	2570	1.78	13.45	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.06	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:3	35.45	2561	1.78	13.45	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.04	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:3	35.45	2576	1.78	13.47	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.05	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:3	35.45	2576	1.78	13.46	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.05	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:3	35.45	2575	1.78	13.44	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.11	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:3	35.45	2570	1.78	13.45	94	199	Off Idle	61.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.1	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:3	35.45	2573	1.78	13.45	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.11	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:4	35.45	2572	1.78	13.45	94	199	Off Idle	62	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.12	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:4	35.45	2567	1.77	13.44	94	199	Off Idle	62.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.13	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:4	35.45	2563	1.77	13.45	94	199	Off Idle	62.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.11	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:4	35.45	2563	1.77	13.47	94	199	Off Idle	62.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.14	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:4	35.45	2557	1.77	13.46	94	199	Off Idle	62	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.16	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:4	35.45	2553	1.77	13.46	95	199	Off Idle	61.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.14	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:4	35.45	2531	1.76	13.47	95	199	Off Idle	61.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.14	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:5	35.45	2531	1.76	13.47	95	199	Off Idle	61.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.18	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:5	35.45	2547	1.76	13.46	94	199	Off Idle	61.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.18	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:5	35.45	2550	1.76	13.47	94	199	Off Idle	62.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.21	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:5	35.45	2551	1.76	13.46	94	199	Off Idle	62.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.2	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:5	35.45	2547	1.75	13.46	94	199	Off Idle	62.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.22	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:5	35.45	2562	1.75	13.46	94	199	Off Idle	62.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.24	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:6	35.45	2563	1.75	13.47	94	199	Off Idle	62.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.25	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:6	35.45	2563	1.75	13.47	94	199	Off Idle	62.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.24	15.01	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:6	35.45	2565	1.74	13.48	94	199	Off Idle	62.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.25	15.01	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:6	35.45	2564	1.74	13.47	94	199	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.27	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:6	35.45	2564	1.74	13.47	94	199	Off Idle	62.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.28	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:6	35.45	2562	1.74	13.46	94	199	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.26	15.05	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:6	35.45	2552	1.74	13.46	94	199	Off Idle	62.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.27	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:7	35.45	2552	1.73	13.46	94	199	Off Idle	62.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.28	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:7	35.45	2558	1.73	13.46	94	199	Off Idle	62.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.28	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:7	35.45	2558	1.73	13.46	94	199	Off Idle	62.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.27	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:58:7	35.45	2540	1.73	13.46	95	199	Off Idle	62.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.25	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:7	35.45	2560	1.73	13.44	95	199	Off Idle	62.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.25	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:7	35.45	2560	1.73	13.45	95	199	Off Idle	62.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.25	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:8	35.45	2561	1.73	13.46	95	199	Off Idle	62.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.3	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:8	35.45	2570	1.73	13.44	95	199	Off Idle	62.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.32	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:8	35.45	2556	1.73	13.45	94	199	Off Idle	62.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.3	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:8	35.45	2558	1.73	13.46	94	199	Off Idle	62.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.33	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:8	35.45	2564	1.73	13.46	94	199	Off Idle	62.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.35	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:8	35.45	2568	1.73	13.46	94	199	Off Idle	62.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.32	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:9	35.45	2568	1.73	13.46	94	199	Off Idle	62.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.31	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:9	35.45	2567	1.73	13.46	94	199	Off Idle	63	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.34	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:9	35.45	2562	1.73	13.45	94	199	Off Idle	63.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.35	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:9	35.45	2552	1.73	13.46	94	199	Off Idle	63.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.35	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:58:9	35.45	2552	1.73	13.46	94	199	Off Idle	63	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.35	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:9	35.45	2544	1.73	13.45	94	199	Off Idle	63	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.33	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:58:9	35.45	2542	1.73	13.46	94	199	Off Idle	63	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.34	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:0	35.45	2542	1.73	13.45	94	199	Off Idle	63	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.34	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:0	35.45	2543	1.73	13.45	94	199	Off Idle	63.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.31	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:0	35.45	2544	1.73	13.43	94	199	Off Idle	63.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.3	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:0	35.45	2544	1.73	13.43	94	199	Off Idle	63.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.32	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:0	35.45	2547	1.72	13.44	94	199	Off Idle	63.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.29	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:0	35.45	2538	1.72	13.44	94	199	Off Idle	63.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.32	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:1	35.45	2544	1.72	13.46	94	199	Off Idle	63.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.32	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:1	35.45	2545	1.72	13.45	94	199	Off Idle	63.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.35	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:1	35.45	2560	1.72	13.45	94	199	Off Idle	63.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.35	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:1	35.45	2549	1.72	13.44	94	199	Off Idle	63.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.36	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:1	35.45	2554	1.72	13.46	94	199	Off Idle	63.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.36	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:1	35.45	2554	1.72	13.45	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.35	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:1	35.45	2559	1.72	13.46	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.36	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:2	35.45	2562	1.72	13.46	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.37	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:59:2	35.45	2562	1.72	13.46	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.4	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:59:2	35.45	2555	1.72	13.45	94	199	Off Idle	63.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.39	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:2	35.45	2552	1.72	13.46	94	199	Off Idle	63.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.38	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:2	35.45	2552	1.72	13.47	94	199	Off Idle	62.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.37	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:2	35.45	2548	1.71	13.46	94	199	Off Idle	62.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.35	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:3	35.45	2544	1.71	13.45	94	199	Off Idle	62.8	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.36	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:59:3	35.45	2543	1.71	13.44	94	199	Off Idle	62.8	0	2	132	944 Turbo	0.16	Rich	1	14.6	-9.34	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:59:3	35.45	2544	1.71	13.45	94	199	Off Idle	62.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.33	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:59:3	35.45	2542	1.71	13.45	94	199	Off Idle	62.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.34	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:3	35.45	2542	1.71	13.44	94	199	Off Idle	62.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.35	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:59:3	35.45	2544	1.72	13.44	94	199	Off Idle	62.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.32	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:24:59:4	35.45	2527	1.71	13.45	94	199	Off Idle	62.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.33	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:24:59:4	35.45	2549	1.72	13.44	94	199	Off Idle	62.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.35	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:4	35.45	2551	1.72	13.45	94	199	Off Idle	62.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.36	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:4	35.45	2551	1.72	13.42	94	199	Off Idle	62.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.39	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:4	35.45	2568	1.71	13.43	94	199	Off Idle	63	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.37	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:4	35.45	2552	1.72	13.43	94	199	Off Idle	63.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.37	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:4	35.45	2551	1.71	13.44	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.37	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:5	35.45	2551	1.71	13.46	94	199	Off Idle	63.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.39	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:5	35.45	2547	1.72	13.45	94	199	Off Idle	63.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.36	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:5	35.45	2545	1.72	13.45	94	199	Off Idle	63.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.37	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:5	35.45	2540	1.72	13.46	94	199	Off Idle	63.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.37	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:5	35.45	2538	1.72	13.46	94	198	Off Idle	63.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.39	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:5	35.45	2502	1.72	13.45	94	198	Off Idle	63.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.39	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:6	35.45	2522	1.72	13.45	94	198	Off Idle	63.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:6	35.45	2542	1.72	13.46	94	199	Off Idle	63.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.35	15.05	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:6	35.45	2543	1.71	13.45	94	199	Off Idle	63.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.36	15.06	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:6	35.45	2543	1.71	13.45	94	199	Off Idle	63.8	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.35	15.06	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:24:59:6	35.45	2560	1.71	13.45	94	199	Off Idle	63.8	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.34	15.05	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:6	35.45	2542	1.71	13.45	95	199	Off Idle	63.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.36	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:6	35.45	2542	1.71	13.47	95	199	Off Idle	63.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.38	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:7	35.45	2546	1.71	13.46	95	199	Off Idle	63.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.39	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:7	35.45	2548	1.71	13.45	95	199	Off Idle	63.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.36	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:7	35.45	2547	1.71	13.46	95	199	Off Idle	63.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.36	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:7	35.45	2547	1.71	13.46	95	199	Off Idle	63.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.38	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:7	35.45	2543	1.71	13.46	94	199	Off Idle	63.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.35	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:7	35.45	2541	1.71	13.46	94	199	Off Idle	63.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.35	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:8	35.45	2537	1.71	13.46	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.34	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:8	35.45	2538	1.71	13.46	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.35	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:8	35.45	2540	1.71	13.46	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.35	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:8	35.45	2541	1.71	13.46	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.38	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:8	35.45	2540	1.71	13.45	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.36	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:8	35.45	2542	1.71	13.46	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.39	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:9	35.45	2541	1.71	13.47	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.4	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:9	35.45	2541	1.71	13.46	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.4	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:9	35.45	2545	1.71	13.44	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.38	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:9	35.45	2538	1.71	13.43	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.39	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:9	35.45	2536	1.71	13.44	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.4	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:9	35.45	2534	1.71	13.46	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.4	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:24:59:9	35.45	2525	1.71	13.44	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.36	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:0	35.45	2525	1.71	13.46	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.36	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:0	35.45	2526	1.71	13.44	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.35	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:0	35.45	2526	1.71	13.42	94	199	Off Idle	63.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.34	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:0	35.45	2527	1.71	13.43	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.34	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:0	35.45	2527	1.71	13.42	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.35	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:0	35.45	2528	1.71	13.43	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.38	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:1	35.45	2528	1.71	13.44	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.36	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:1	35.45	2530	1.71	13.44	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.37	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:1	35.45	2532	1.71	13.44	94	199	Off Idle	63.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.35	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:1	35.45	2534	1.71	13.44	94	199	Off Idle	63.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.32	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:1	35.45	2540	1.71	13.44	94	199	Off Idle	63.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.33	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:1	35.45	2540	1.71	13.43	94	199	Off Idle	63.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.33	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:1	35.45	2542	1.71	13.44	94	199	Off Idle	64	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.33	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:2	35.45	2547	1.71	13.43	94	199	Off Idle	64	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.35	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:2	35.45	2547	1.71	13.45	94	199	Off Idle	64	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.38	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:2	35.45	2560	1.71	13.45	94	199	Off Idle	64	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.36	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:2	35.45	2548	1.71	13.46	94	199	Off Idle	64	0	2	132	944 Turbo	0.15	Rich	1	14.6	-9.39	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:2	35.45	2542	1.71	13.46	94	199	Off Idle	63.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.35	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:2	35.45	2540	1.71	13.46	94	199	Off Idle	63.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.35	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:3	35.45	2530	1.71	13.48	94	199	Off Idle	63.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.36	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:3	35.45	2524	1.71	13.47	94	199	Off Idle	63.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.38	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:3	35.45	2524	1.71	13.46	94	199	Off Idle	63.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.37	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:3	35.45	2506	1.71	13.45	95	199	Off Idle	63.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.4	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:3	35.45	2526	1.71	13.44	95	198	Off Idle	63.9	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.39	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:3	35.45	2526	1.71	13.46	95	198	Off Idle	63.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.37	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:4	35.45	2526	1.71	13.46	94	198	Off Idle	63.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.38	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:4	35.45	2542	1.71	13.46	94	199	Off Idle	63.9	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.35	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:4	35.45	2534	1.71	13.46	94	199	Off Idle	64.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.35	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:4	35.45	2530	1.71	13.46	94	199	Off Idle	64.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.37	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:4	35.45	2534	1.7	13.46	94	199	Off Idle	64.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.38	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:4	35.45	2513	1.7	13.45	94	199	Off Idle	64.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.38	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:4	35.45	2533	1.7	13.46	94	199	Off Idle	64.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.4	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:5	35.45	2530	1.7	13.45	94	199	Off Idle	64.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.42	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:5	35.45	2532	1.7	13.45	95	199	Off Idle	64.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.4	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:5	35.45	2542	1.7	13.45	95	199	Off Idle	64.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.43	15.07	1.03	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:5	35.45	2542	1.7	13.44	95	199	Off Idle	64.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.43	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:00:5	35.45	2528	1.7	13.44	94	199	Off Idle	64.9	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.45	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:5	35.45	2529	1.7	13.45	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.46	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:6	35.45	2528	1.7	13.44	94	199	Off Idle	64.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.45	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:6	35.45	2528	1.7	13.45	94	199	Off Idle	64.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.41	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:6	35.45	2526	1.7	13.45	94	199	Off Idle	64.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.43	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:6	35.45	2524	1.7	13.43	94	199	Off Idle	64.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.39	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:6	35.45	2524	1.7	13.43	94	199	Off Idle	64.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.36	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:00:6	35.45	2523	1.7	13.44	94	199	Off Idle	64.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.36	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:6	35.45	2522	1.7	13.45	94	199	Off Idle	64.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.36	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:7	35.45	2523	1.7	13.44	94	199	Off Idle	64.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.34	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:7	35.45	2532	1.7	13.44	94	199	Off Idle	64.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.35	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:7	35.45	2519	1.7	13.45	94	199	Off Idle	64.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.35	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:7	35.45	2520	1.7	13.46	95	199	Off Idle	64.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.37	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:7	35.45	2520	1.7	13.45	95	199	Off Idle	64.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.39	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:7	35.45	2515	1.7	13.45	95	199	Off Idle	64.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.4	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:8	35.45	2521	1.7	13.45	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.42	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:8	35.45	2521	1.7	13.45	94	199	Off Idle	64.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.42	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:8	35.45	2524	1.7	13.44	94	199	Off Idle	65	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.41	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:8	35.45	2510	1.7	13.44	94	199	Off Idle	65	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.38	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:8	35.45	2520	1.7	13.45	94	199	Off Idle	64.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.4	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:8	35.45	2531	1.7	13.46	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.41	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:9	35.45	2530	1.7	13.45	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.41	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:9	35.45	2524	1.7	13.44	94	198	Off Idle	64.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.42	14.97	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:00:9	35.45	2526	1.7	13.44	94	198	Off Idle	65	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.42	14.96	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:9	35.45	2524	1.7	13.45	94	198	Off Idle	65	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.4	14.95	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:9	35.45	2521	1.7	13.44	94	199	Off Idle	64.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.42	14.92	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:9	35.45	2521	1.69	13.44	95	199	Off Idle	64.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.39	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:00:9	35.45	2516	1.69	13.44	95	199	Off Idle	64.9	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.37	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:0	35.45	2516	1.69	13.45	95	199	Off Idle	65	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.37	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:0	35.45	2519	1.69	13.46	94	199	Off Idle	65	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.37	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:0	35.45	2519	1.69	13.47	94	199	Off Idle	65	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.4	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:0	35.45	2512	1.69	13.45	94	199	Off Idle	65	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.41	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:0	35.45	2522	1.69	13.46	95	199	Off Idle	65	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.39	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:0	35.45	2523	1.69	13.46	95	199	Off Idle	65.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.39	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:1	35.45	2525	1.69	13.47	95	199	Off Idle	65.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.42	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:1	35.45	2524	1.69	13.47	94	199	Off Idle	65.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.42	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:1	35.45	2524	1.69	13.46	94	199	Off Idle	65.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.41	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:1	35.45	2516	1.69	13.45	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.43	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:1	35.45	2510	1.69	13.45	94	199	Off Idle	65.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.42	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:1	35.45	2510	1.69	13.46	94	199	Off Idle	65.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.41	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:1	35.45	2506	1.69	13.45	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.42	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:2	35.45	2507	1.69	13.44	94	199	Off Idle	65.3	0	2	132	944 Turbo	0.17	Rich	1	14.6	-9.39	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:2	35.45	2511	1.69	13.44	94	199	Off Idle	65.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-9.39	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:2	35.45	2512	1.69	13.44	94	199	Off Idle	65.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.41	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:2	35.45	2514	1.69	13.46	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.42	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:2	35.45	2516	1.69	13.44	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.43	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:2	35.45	2517	1.69	13.46	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.42	15.16	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:3	35.45	2520	1.69	13.45	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.41	15.18	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:3	35.45	2523	1.69	13.47	94	199	Off Idle	65.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.39	15.19	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:3	35.45	2520	1.69	13.44	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.41	15.18	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:3	35.45	2520	1.69	13.44	94	199	Off Idle	65.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.4	15.18	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:3	35.45	2518	1.69	13.44	94	199	Off Idle	65.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.4	15.18	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:3	35.45	2513	1.69	13.45	95	199	Off Idle	65.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.43	15.16	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:4	35.45	2513	1.69	13.43	95	199	Off Idle	65.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.42	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:4	35.45	2510	1.69	13.45	95	199	Off Idle	65.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.41	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:4	35.45	2513	1.69	13.45	95	199	Off Idle	65.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.39	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:4	35.45	2514	1.69	13.46	95	199	Off Idle	65.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.41	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:4	35.45	2516	1.69	13.46	95	199	Off Idle	65.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.42	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:01:4	35.45	2517	1.69	13.44	94	199	Off Idle	65	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.43	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:4	35.45	2517	1.69	13.44	94	199	Off Idle	65	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.44	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:5	35.45	2516	1.69	13.44	95	199	Off Idle	64.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.43	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:5	35.45	2518	1.69	13.45	95	199	Off Idle	64.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.44	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:5	35.45	2519	1.69	13.45	95	199	Off Idle	64.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.44	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:5	35.45	2518	1.69	13.47	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.42	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:5	35.45	2535	1.69	13.47	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.41	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:5	35.45	2515	1.69	13.46	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.4	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:6	35.45	2507	1.69	13.45	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.36	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:6	35.45	2507	1.69	13.45	94	199	Off Idle	64.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.38	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:01:6	35.45	2495	1.69	13.44	94	199	Off Idle	64.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.37	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:01:6	35.45	2504	1.69	13.44	94	199	Off Idle	64.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.36	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:01:6	35.45	2506	1.69	13.45	94	199	Off Idle	64.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.36	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:01:6	35.45	2508	1.69	13.45	94	199	Off Idle	64.6	0	2	132	944 Turbo	0.16	Rich	1	14.6	-9.39	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:01:6	35.45	2511	1.69	13.46	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.37	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:01:7	35.45	2510	1.69	13.45	94	199	Off Idle	64.7	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.35	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:7	35.45	2512	1.7	13.45	94	199	Off Idle	64.9	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.37	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:7	35.45	2516	1.69	13.46	94	198	Off Idle	65	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.36	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:7	35.45	2514	1.69	13.46	94	198	Off Idle	65	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.37	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:7	35.45	2514	1.69	13.45	94	198	Off Idle	64.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.35	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:7	35.45	2506	1.69	13.45	94	199	Off Idle	65	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.35	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:8	35.45	2507	1.69	13.46	94	199	Off Idle	65.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.36	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:8	35.45	2506	1.69	13.45	95	199	Off Idle	65.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.36	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:8	35.45	2506	1.69	13.46	95	199	Off Idle	65.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.36	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:8	35.45	2505	1.69	13.45	95	199	Off Idle	65.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.36	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:8	35.45	2494	1.69	13.46	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.36	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:8	35.45	2506	1.69	13.44	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.35	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:9	35.45	2506	1.69	13.46	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.35	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:9	35.45	2506	1.69	13.45	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.37	15.08	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:9	35.45	2507	1.69	13.46	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.37	15.06	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:9	35.45	2518	1.69	13.44	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.39	15.04	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:9	35.45	2504	1.69	13.44	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.37	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:9	35.45	2503	1.69	13.44	94	199	Off Idle	65.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.36	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:01:9	35.45	2486	1.69	13.46	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.36	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:0	35.45	2486	1.69	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.39	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:0	35.45	2510	1.69	13.46	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.38	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:0	35.45	2512	1.69	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.41	14.81	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:0	35.45	2506	1.69	13.46	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.4	14.79	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:0	35.45	2506	1.69	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.4	14.79	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:0	35.45	2506	1.69	13.46	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.4	14.79	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:02:1	35.45	2509	1.69	13.45	95	199	Off Idle	65.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.43	14.77	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:02:1	35.45	2509	1.69	13.46	95	199	Off Idle	65.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.41	14.75	1	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:1	35.45	2529	1.69	13.44	95	199	Off Idle	65.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.42	14.74	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:02:1	35.45	2504	1.69	13.44	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.42	14.74	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:02:1	35.45	2504	1.69	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.44	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:1	35.45	2503	1.69	13.44	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.44	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:1	35.45	2480	1.69	13.43	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.33	Lean	1	14.7	-9.42	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:2	35.45	2490	1.69	13.43	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.41	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:2	35.45	2506	1.69	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.39	14.89	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:2	35.45	2506	1.69	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.4	14.93	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:2	35.45	2526	1.69	13.46	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.38	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:2	35.45	2516	1.69	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.4	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:2	35.45	2502	1.69	13.44	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.38	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:3	35.45	2502	1.69	13.44	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.69	Lean	1	14.6	-9.38	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:3	35.45	2500	1.68	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.37	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:3	35.45	2492	1.68	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.38	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:3	35.45	2486	1.68	13.44	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.36	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:3	35.45	2487	1.68	13.44	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.38	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:02:3	35.45	2492	1.68	13.45	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.38	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:4	35.45	2494	1.68	13.44	94	199	Off Idle	65.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.38	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:4	35.45	2494	1.68	13.45	94	198	Off Idle	65.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.38	15.05	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:4	35.45	2497	1.68	13.46	94	198	Off Idle	66	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.36	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:4	35.45	2494	1.68	13.46	94	198	Off Idle	66.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.36	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:4	35.45	2497	1.68	13.45	94	199	Off Idle	66.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.38	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:4	35.45	2498	1.68	13.45	94	199	Off Idle	66.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.39	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:4	35.45	2506	1.68	13.44	94	199	Off Idle	66.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.38	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:5	35.45	2508	1.68	13.46	94	199	Off Idle	66.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.4	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:5	35.45	2505	1.68	13.46	94	199	Off Idle	66.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.41	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:5	35.45	2505	1.68	13.45	94	199	Off Idle	66.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.42	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:5	35.45	2507	1.68	13.44	95	199	Off Idle	66.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.41	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:5	35.45	2506	1.68	13.46	95	199	Off Idle	66.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.41	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:5	35.45	2506	1.68	13.44	95	199	Off Idle	66.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.43	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:6	35.45	2500	1.68	13.43	95	199	Off Idle	66.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.43	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:6	35.45	2492	1.68	13.44	95	199	Off Idle	66.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.41	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:6	35.45	2491	1.68	13.45	95	199	Off Idle	66.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.4	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:6	35.45	2488	1.68	13.44	95	199	Off Idle	66.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.39	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:6	35.45	2492	1.68	13.45	95	199	Off Idle	66.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.38	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:6	35.45	2493	1.68	13.45	95	199	Off Idle	66.4	0	2	132	944 Turbo	0.46	Rich	1	14.7	-9.37	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:6	35.45	2494	1.68	13.45	95	199	Off Idle	66.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.39	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:7	35.45	2496	1.68	13.45	95	199	Off Idle	66.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.4	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:7	35.45	2502	1.68	13.45	94	199	Off Idle	66.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.4	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:7	35.45	2504	1.68	13.47	94	199	Off Idle	67.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.42	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:7	35.45	2495	1.68	13.45	94	199	Off Idle	67.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.45	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:7	35.45	2505	1.68	13.47	94	199	Off Idle	67.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.46	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:7	35.45	2495	1.68	13.47	94	199	Off Idle	67.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.47	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:8	35.45	2495	1.67	13.47	94	199	Off Idle	67.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.49	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:8	35.45	2486	1.67	13.46	94	199	Off Idle	67.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.46	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:8	35.45	2488	1.67	13.46	94	199	Off Idle	67.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.45	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:8	35.45	2478	1.67	13.46	94	199	Off Idle	67.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.42	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:8	35.45	2478	1.67	13.47	95	199	Off Idle	67.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.39	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:02:8	35.45	2480	1.67	13.45	95	199	Off Idle	67.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.44	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:02:9	35.45	2481	1.67	13.47	94	199	Off Idle	67.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.39	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:02:9	35.45	2483	1.67	13.45	94	199	Off Idle	67.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.42	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:9	35.45	2488	1.67	13.44	94	199	Off Idle	67.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.42	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:9	35.45	2491	1.67	13.44	94	199	Off Idle	67.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.44	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:9	35.45	2488	1.67	13.45	94	199	Off Idle	67.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.45	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:9	35.45	2488	1.67	13.45	94	199	Off Idle	67.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.47	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:02:9	35.45	2492	1.66	13.45	94	199	Off Idle	67.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.47	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:0	35.45	2494	1.66	13.46	94	199	Off Idle	67.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.47	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:0	35.45	2496	1.66	13.47	94	199	Off Idle	67.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.49	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:0	35.45	2496	1.66	13.47	94	199	Off Idle	67.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.49	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:0	35.45	2502	1.66	13.46	94	199	Off Idle	67.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.49	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:0	35.45	2502	1.66	13.44	94	199	Off Idle	67.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.48	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:0	35.45	2502	1.66	13.44	94	199	Off Idle	67.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.51	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:1	35.45	2498	1.66	13.43	94	199	Off Idle	67	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.51	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:1	35.45	2494	1.66	13.43	94	199	Off Idle	66.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.52	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:1	35.45	2493	1.66	13.43	94	199	Off Idle	66.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.52	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:1	35.45	2484	1.66	13.45	94	199	Off Idle	66.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.49	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:1	35.45	2481	1.66	13.45	94	199	Off Idle	66.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.43	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:1	35.45	2482	1.66	13.44	94	199	Off Idle	66.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.43	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:1	35.45	2482	1.66	13.45	94	199	Off Idle	66.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.41	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:2	35.45	2486	1.66	13.45	94	199	Off Idle	66.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.44	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:2	35.45	2487	1.66	13.44	94	199	Off Idle	67.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.44	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:2	35.45	2488	1.66	13.44	94	199	Off Idle	67.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.45	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:2	35.45	2492	1.66	13.44	94	199	Off Idle	67.2	0	2	132	944 Turbo	0.57	Rich	1	14.7	-9.45	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:2	35.45	2492	1.66	13.44	95	199	Off Idle	67.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.46	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:03:2	35.45	2494	1.66	13.45	95	199	Off Idle	66.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.46	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:3	35.45	2496	1.66	13.46	95	199	Off Idle	66.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.47	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:3	35.45	2494	1.66	13.46	95	199	Off Idle	66.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.47	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:3	35.45	2490	1.66	13.45	95	199	Off Idle	66.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.46	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:3	35.45	2486	1.66	13.45	95	199	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.45	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:3	35.45	2479	1.66	13.44	95	199	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.45	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:3	35.45	2479	1.66	13.45	95	199	Off Idle	66.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.46	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:4	35.45	2475	1.66	13.45	94	199	Off Idle	66.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.43	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:4	35.45	2456	1.67	13.46	94	199	Off Idle	66.6	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.45	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:4	35.45	2467	1.67	13.46	94	198	Off Idle	66.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.41	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:4	35.45	2468	1.67	13.46	95	198	Off Idle	66.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.41	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:4	35.45	2482	1.67	13.46	95	198	Off Idle	66.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.43	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:4	35.45	2473	1.67	13.46	95	199	Off Idle	66.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.42	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:4	35.45	2474	1.67	13.45	95	199	Off Idle	66.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.44	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:5	35.45	2477	1.67	13.45	95	199	Off Idle	67	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.46	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:5	35.45	2478	1.67	13.45	95	198	Off Idle	67.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.48	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:5	35.45	2484	1.67	13.46	95	198	Off Idle	67.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.46	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:5	35.45	2489	1.67	13.45	95	199	Off Idle	67.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.47	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:5	35.45	2490	1.66	13.45	94	199	Off Idle	67.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.46	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:5	35.45	2496	1.66	13.46	94	199	Off Idle	67.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.46	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:6	35.45	2499	1.66	13.45	94	199	Off Idle	67.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.47	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:6	35.45	2501	1.66	13.44	94	199	Off Idle	67.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.46	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:6	35.45	2502	1.66	13.45	94	199	Off Idle	67.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.46	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:6	35.45	2497	1.66	13.46	94	198	Off Idle	67.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.47	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:6	35.45	2494	1.66	13.45	95	198	Off Idle	67.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.47	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:6	35.45	2494	1.66	13.46	95	198	Off Idle	67.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.46	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:6	35.45	2490	1.66	13.45	95	198	Off Idle	67.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.49	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:03:7	35.45	2482	1.66	13.46	94	198	Off Idle	67.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.48	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:03:7	35.45	2482	1.66	13.45	94	198	Off Idle	67.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.49	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:7	35.45	2473	1.66	13.43	94	198	Off Idle	67.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.48	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:7	35.45	2446	1.66	13.42	95	198	Off Idle	67.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.48	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:7	35.45	2454	1.66	13.43	95	199	Off Idle	67.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.47	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:7	35.45	2464	1.65	13.44	94	199	Off Idle	67.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.46	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:8	35.45	2468	1.65	13.44	94	199	Off Idle	67.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.49	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:03:8	35.45	2468	1.65	13.45	94	199	Off Idle	67.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.48	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:8	35.45	2480	1.65	13.45	95	199	Off Idle	67.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.5	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:03:8	35.45	2467	1.65	13.46	95	199	Off Idle	67.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.49	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:03:8	35.45	2451	1.65	13.46	95	199	Off Idle	67.9	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.49	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:8	35.45	2451	1.65	13.46	94	199	Off Idle	68	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.51	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:9	35.45	2474	1.65	13.46	94	199	Off Idle	68	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.5	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:9	35.45	2477	1.65	13.46	94	199	Off Idle	68	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.5	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:9	35.45	2480	1.64	13.46	95	199	Off Idle	68	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.53	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:9	35.45	2491	1.64	13.45	95	199	Off Idle	68	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.53	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:9	35.45	2485	1.64	13.45	95	199	Off Idle	68	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.55	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:9	35.45	2491	1.64	13.44	95	199	Off Idle	67.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.56	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:03:9	35.45	2470	1.64	13.45	95	199	Off Idle	67.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.59	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:0	35.45	2480	1.63	13.45	95	199	Off Idle	67.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.62	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:0	35.45	2495	1.63	13.45	95	198	Off Idle	67.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.63	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:0	35.45	2515	1.63	13.44	95	198	Off Idle	67.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.62	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:0	35.45	2502	1.63	13.46	95	198	Off Idle	67.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.62	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:0	35.45	2488	1.63	13.46	95	198	Off Idle	67.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.63	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:0	35.45	2479	1.62	13.45	95	198	Off Idle	67	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.62	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:1	35.45	2476	1.62	13.45	95	198	Off Idle	66.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.61	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:1	35.45	2468	1.62	13.45	95	199	Off Idle	66.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.61	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:1	35.45	2465	1.62	13.44	95	199	Off Idle	66.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.62	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:1	35.45	2465	1.62	13.45	94	199	Off Idle	66.6	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.61	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:1	35.45	2467	1.62	13.44	94	199	Off Idle	66.6	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.61	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:1	35.45	2467	1.62	13.44	94	199	Off Idle	66.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.59	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:04:1	35.45	2462	1.62	13.43	95	199	Off Idle	66.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.56	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:2	35.45	2463	1.62	13.43	95	198	Off Idle	66.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.56	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:2	35.45	2466	1.62	13.43	95	198	Off Idle	67.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.58	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:2	35.45	2466	1.62	13.45	95	198	Off Idle	67.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.59	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:2	35.45	2468	1.61	13.44	95	198	Off Idle	67.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.6	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:2	35.45	2469	1.61	13.45	95	198	Off Idle	67.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.61	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:2	35.45	2466	1.61	13.45	95	198	Off Idle	67.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.61	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:3	35.45	2467	1.61	13.46	95	198	Off Idle	67.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.62	15.05	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:3	35.45	2469	1.61	13.45	95	198	Off Idle	68	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.65	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:3	35.45	2468	1.61	13.45	94	199	Off Idle	68.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.64	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:3	35.45	2469	1.61	13.44	94	199	Off Idle	68.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.66	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:3	35.45	2473	1.6	13.46	94	199	Off Idle	68.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.67	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:3	35.45	2475	1.6	13.45	94	198	Off Idle	68.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.69	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:4	35.45	2475	1.6	13.47	94	198	Off Idle	68.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.69	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:4	35.45	2480	1.6	13.45	95	198	Off Idle	68.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.73	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:4	35.45	2480	1.6	13.46	95	198	Off Idle	68.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.7	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:4	35.45	2481	1.59	13.45	95	198	Off Idle	68.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.7	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:4	35.45	2481	1.59	13.44	95	198	Off Idle	68.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.74	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:4	35.45	2482	1.59	13.43	95	198	Off Idle	68.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.71	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:4	35.45	2481	1.59	13.44	95	198	Off Idle	68	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.74	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:5	35.45	2481	1.59	13.43	94	198	Off Idle	68	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.76	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:5	35.45	2474	1.59	13.44	94	198	Off Idle	68	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.76	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:5	35.45	2473	1.59	13.44	94	198	Off Idle	68	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.73	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:5	35.45	2472	1.59	13.44	95	199	Off Idle	68	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.76	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:5	35.45	2470	1.59	13.44	95	199	Off Idle	68	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.74	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:5	35.45	2464	1.59	13.44	95	199	Off Idle	68	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.73	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:6	35.45	2460	1.59	13.45	95	198	Off Idle	68	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.72	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:6	35.45	2458	1.59	13.44	95	198	Off Idle	68	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.72	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:6	35.45	2458	1.59	13.44	95	198	Off Idle	68	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.71	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:6	35.45	2456	1.58	13.44	95	198	Off Idle	68	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.71	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:6	35.45	2453	1.58	13.45	95	198	Off Idle	68.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.69	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:6	35.45	2453	1.58	13.45	95	198	Off Idle	68.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.71	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:6	35.45	2456	1.58	13.44	95	198	Off Idle	68.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.69	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:7	35.45	2455	1.58	13.44	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.7	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:7	35.45	2456	1.58	13.45	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.7	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:7	35.45	2446	1.58	13.45	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.72	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:7	35.45	2457	1.58	13.45	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.72	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:7	35.45	2457	1.58	13.44	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.72	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:7	35.45	2456	1.58	13.44	95	199	Off Idle	68.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.72	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:8	35.45	2472	1.58	13.43	95	199	Off Idle	68.6	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.75	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:8	35.45	2458	1.58	13.43	95	199	Off Idle	68.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.74	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:8	35.45	2458	1.58	13.44	95	198	Off Idle	68.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.77	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:8	35.45	2458	1.58	13.46	95	198	Off Idle	68.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.74	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:8	35.45	2420	1.58	13.45	95	198	Off Idle	68.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.72	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:8	35.45	2440	1.58	13.46	95	198	Off Idle	68.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.69	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:9	35.45	2464	1.58	13.45	95	198	Off Idle	68.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.72	14.88	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:9	35.45	2467	1.58	13.46	95	198	Off Idle	68.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.69	14.86	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:9	35.45	2468	1.58	13.45	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.7	14.85	1.01	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:9	35.45	2486	1.58	13.46	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.69	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:9	35.45	2467	1.58	13.45	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.68	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:9	35.45	2468	1.58	13.47	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.7	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:04:9	35.45	2468	1.58	13.45	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.74	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:0	35.45	2467	1.58	13.44	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.72	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:0	35.45	2464	1.58	13.44	95	198	Off Idle	68.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.73	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:0	35.45	2464	1.58	13.45	95	198	Off Idle	68.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.73	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:0	35.45	2464	1.58	13.45	95	198	Off Idle	68.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.73	14.9	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:0	35.45	2467	1.58	13.45	95	198	Off Idle	68.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.72	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:0	35.45	2468	1.58	13.46	95	198	Off Idle	68.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.74	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:05:1	35.45	2463	1.58	13.46	94	198	Off Idle	67.9	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.72	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:1	35.45	2455	1.58	13.44	94	198	Off Idle	68	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.72	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:1	35.45	2454	1.58	13.45	94	198	Off Idle	68	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.71	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:1	35.45	2454	1.58	13.44	95	198	Off Idle	68	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.73	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:1	35.45	2451	1.58	13.45	95	198	Off Idle	68.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.7	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:1	35.45	2449	1.58	13.44	95	198	Off Idle	68.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.72	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:1	35.45	2444	1.58	13.46	95	198	Off Idle	68.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.72	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:2	35.45	2438	1.58	13.45	95	198	Off Idle	68.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.72	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:2	35.45	2438	1.58	13.45	94	198	Off Idle	68.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.72	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:2	35.45	2440	1.58	13.44	94	198	Off Idle	68.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.74	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:2	35.45	2442	1.58	13.45	94	198	Off Idle	68.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.72	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:2	35.45	2442	1.58	13.47	94	198	Off Idle	68.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.73	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:2	35.45	2447	1.58	13.45	94	198	Off Idle	68.9	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.75	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:3	35.45	2446	1.58	13.46	94	198	Off Idle	69.1	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.75	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:3	35.45	2445	1.57	13.46	95	198	Off Idle	69.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.74	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:3	35.45	2447	1.57	13.46	95	198	Off Idle	69.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.72	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:3	35.45	2448	1.57	13.45	95	198	Off Idle	69.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.75	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:3	35.45	2450	1.57	13.45	95	198	Off Idle	69.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.74	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:3	35.45	2448	1.57	13.44	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.76	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:4	35.45	2446	1.57	13.45	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.78	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:4	35.45	2450	1.56	13.45	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.81	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:4	35.45	2450	1.56	13.46	95	198	Off Idle	69.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.81	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:05:4	35.45	2453	1.56	13.45	95	198	Off Idle	69.1	0	2	132	944 Turbo	0.19	Rich	1	14.6	-9.81	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:4	35.45	2438	1.56	13.45	95	198	Off Idle	69	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.81	14.83	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:4	35.45	2448	1.55	13.45	95	198	Off Idle	69	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.85	14.83	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:4	35.45	2450	1.55	13.46	95	198	Off Idle	69	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.83	14.82	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:5	35.45	2449	1.55	13.45	95	198	Off Idle	68.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.86	14.84	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:5	35.45	2480	1.55	13.45	95	198	Off Idle	68.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.87	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:5	35.45	2460	1.55	13.45	95	198	Off Idle	68.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.86	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:5	35.45	2440	1.55	13.44	95	198	Off Idle	68.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.84	14.88	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:5	35.45	2436	1.54	13.44	95	198	Off Idle	68.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.86	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:6	35.45	2436	1.54	13.44	95	198	Off Idle	68.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.88	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:6	35.45	2414	1.54	13.45	95	198	Off Idle	68.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.86	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:6	35.45	2435	1.53	13.44	95	198	Off Idle	68.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.87	14.93	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:6	35.45	2434	1.53	13.44	94	198	Off Idle	68.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.88	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:6	35.45	2432	1.52	13.45	94	198	Off Idle	69	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.9	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:6	35.45	2432	1.52	13.45	94	198	Off Idle	69.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.94	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:6	35.45	2430	1.51	13.44	94	198	Off Idle	69.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.97	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:6	35.45	2430	1.51	13.46	94	198	Off Idle	69.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.98	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:7	35.45	2427	1.51	13.46	94	198	Off Idle	69.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.02	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:7	35.45	2428	1.5	13.46	95	198	Off Idle	69.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-10.01	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:7	35.45	2428	1.5	13.45	95	198	Off Idle	69.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-10.02	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:05:7	35.45	2434	1.49	13.45	95	198	Off Idle	69.9	0	2	132	944 Turbo	0.2	Rich	1	14.6	-10	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:05:7	35.45	2442	1.49	13.45	95	198	Off Idle	70.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.01	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:7	35.45	2448	1.48	13.45	95	198	Off Idle	70.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.02	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:8	35.45	2450	1.48	13.45	95	198	Off Idle	70.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.06	14.95	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:8	35.45	2454	1.48	13.45	95	198	Off Idle	70.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.06	14.92	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:8	35.45	2448	1.47	13.46	95	198	Off Idle	70.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.07	14.9	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:8	35.45	2448	1.47	13.44	95	198	Off Idle	69.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.07	14.88	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:8	35.45	2438	1.46	13.44	95	198	Off Idle	69.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.08	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:8	35.45	2437	1.46	13.44	95	198	Off Idle	69.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.07	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:9	35.45	2438	1.46	13.43	95	198	Off Idle	69.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.08	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:9	35.45	2428	1.46	13.43	95	198	Off Idle	69.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.09	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:9	35.45	2438	1.46	13.44	95	198	Off Idle	69.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.08	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:9	35.45	2438	1.46	13.43	95	198	Off Idle	69.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.08	14.92	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:9	35.45	2438	1.46	13.44	95	198	Off Idle	69.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.08	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:9	35.45	2435	1.46	13.45	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.07	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:05:9	35.45	2435	1.46	13.46	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.07	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:06:0	35.45	2435	1.46	13.44	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-10.08	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:06:0	35.45	2434	1.46	13.45	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-10.07	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:06:0	35.45	2433	1.46	13.44	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-10.07	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:06:0	35.45	2433	1.46	13.45	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-10.08	15.15	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:06:0	35.45	2434	1.46	13.46	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10.07	15.14	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:0	35.45	2438	1.46	13.45	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.08	15.14	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:1	35.45	2438	1.46	13.45	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.07	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:06:1	35.45	2428	1.46	13.46	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.08	15.12	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:06:1	35.45	2434	1.46	13.45	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.08	15.11	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:1	35.45	2434	1.46	13.45	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.09	15.1	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:1	35.45	2433	1.46	13.45	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.08	15.1	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:1	35.45	2431	1.46	13.44	95	198	Off Idle	69.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.08	15.06	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:1	35.45	2431	1.46	13.46	95	198	Off Idle	69.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.08	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:2	35.45	2422	1.46	13.46	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.08	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:2	35.45	2416	1.46	13.46	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.07	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:2	35.45	2416	1.46	13.46	95	198	Off Idle	69.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.08	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:2	35.45	2412	1.46	13.46	95	198	Off Idle	69.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.09	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:2	35.45	2430	1.46	13.46	95	198	Off Idle	69.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.11	15.02	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:2	35.45	2430	1.46	13.46	95	198	Off Idle	70	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.09	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:3	35.45	2430	1.46	13.46	94	198	Off Idle	70	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.08	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:3	35.45	2434	1.45	13.44	94	198	Off Idle	70	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.08	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:3	35.45	2436	1.45	13.45	94	198	Off Idle	70.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.08	14.96	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:3	35.45	2430	1.45	13.44	95	198	Off Idle	70.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.08	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:3	35.45	2428	1.45	13.44	95	198	Off Idle	70.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.08	14.91	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:3	35.45	2429	1.45	13.44	95	198	Off Idle	70.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-10.11	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:4	35.45	2427	1.45	13.44	95	198	Off Idle	70.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-10.12	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:06:4	35.45	2426	1.45	13.45	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-10.12	14.86	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:4	35.45	2427	1.45	13.45	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.14	14.85	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:4	35.45	2422	1.44	13.44	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-10.14	14.85	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:4	35.45	2417	1.44	13.45	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.13	14.84	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:4	35.45	2419	1.44	13.44	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.13	14.84	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:4	35.45	2426	1.44	13.45	95	198	Off Idle	70.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.13	14.83	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:5	35.45	2428	1.44	13.45	95	198	Off Idle	70	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.15	14.83	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:5	35.45	2428	1.44	13.45	95	198	Off Idle	70	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.18	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:5	35.45	2432	1.43	13.45	95	198	Off Idle	70	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.18	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:5	35.45	2429	1.43	13.45	95	198	Off Idle	70	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.2	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:5	35.45	2429	1.43	13.46	95	198	Off Idle	70	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.21	14.8	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:5	35.45	2424	1.43	13.44	95	198	Off Idle	70	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.23	14.83	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:6	35.45	2422	1.42	13.44	95	198	Off Idle	70	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.22	14.84	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:6	35.45	2416	1.42	13.44	95	198	Off Idle	70	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.21	14.87	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:6	35.45	2415	1.42	13.44	95	198	Off Idle	70	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.21	14.87	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:6	35.45	2415	1.42	13.43	95	198	Off Idle	70.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.22	14.92	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:6	35.45	2415	1.41	13.45	94	198	Off Idle	70.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.21	14.96	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:6	35.45	2416	1.41	13.45	94	198	Off Idle	70.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.25	14.99	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:6	35.45	2420	1.41	13.46	94	198	Off Idle	70.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.26	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:7	35.45	2421	1.4	13.46	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.25	15.07	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:7	35.45	2405	1.4	13.45	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-10.27	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:7	35.45	2413	1.4	13.45	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-10.3	15.13	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:7	35.45	2414	1.4	13.44	95	198	Off Idle	70.7	0	2	132	944 Turbo	0.45	Lean	1	14.6	-10.29	15.15	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:7	35.45	2414	1.39	13.45	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-10.29	15.17	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:7	35.45	2411	1.39	13.45	95	198	Off Idle	71	0	2	132	944 Turbo	0.57	Lean	1	14.6	-10.3	15.17	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:06:8	35.45	2411	1.39	13.45	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-10.3	15.18	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:8	35.45	2418	1.39	13.45	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.68	Lean	1	14.6	-10.29	15.17	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:8	35.45	2424	1.38	13.45	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.31	15.16	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:8	35.45	2424	1.38	13.46	95	198	Off Idle	71.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.3	15.16	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:8	35.45	2422	1.38	13.47	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.29	15.15	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:8	35.45	2414	1.38	13.47	95	198	Off Idle	71	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.29	15.14	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:06:9	35.45	2414	1.38	13.47	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.3	15.11	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:06:9	35.45	2402	1.38	13.46	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.32	15.09	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:06:9	35.45	2408	1.37	13.45	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.34	15.08	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:06:9	35.45	2407	1.37	13.46	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10.32	15.07	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:06:9	35.45	2404	1.37	13.44	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.32	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:9	35.45	2422	1.37	13.45	95	198	Off Idle	70.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.31	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:06:9	35.45	2404	1.37	13.44	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-10.3	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:0	35.45	2404	1.37	13.45	95	198	Off Idle	70.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.29	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:0	35.45	2409	1.37	13.44	95	198	Off Idle	70.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.3	15	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:0	35.45	2411	1.37	13.44	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.31	14.98	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:0	35.45	2412	1.37	13.44	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.31	14.96	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:0	35.45	2414	1.37	13.44	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.34	14.94	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:0	35.45	2413	1.37	13.45	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.34	14.93	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:1	35.45	2410	1.37	13.45	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.33	14.9	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:1	35.45	2410	1.37	13.45	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.33	14.88	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:1	35.45	2408	1.37	13.45	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.33	14.86	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:1	35.45	2403	1.37	13.45	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.3	14.85	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:1	35.45	2403	1.38	13.44	95	198	Off Idle	70.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.29	14.86	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:1	35.45	2401	1.38	13.46	95	198	Off Idle	70.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.28	14.85	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:1	35.45	2395	1.38	13.45	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.25	14.84	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:2	35.45	2397	1.38	13.44	95	198	Off Idle	71.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.25	14.85	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:2	35.45	2390	1.38	13.44	95	198	Off Idle	71.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.24	14.86	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:2	35.45	2402	1.38	13.46	95	198	Off Idle	71.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.24	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:2	35.45	2406	1.38	13.42	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.27	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:2	35.45	2406	1.38	13.42	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.27	14.9	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:2	35.45	2383	1.38	13.44	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-10.29	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:3	35.45	2396	1.38	13.43	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.29	14.97	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:3	35.45	2405	1.37	13.44	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.41	Rich	1	14.6	-10.27	15	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:3	35.45	2397	1.37	13.45	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-10.25	15.04	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:3	35.45	2397	1.37	13.44	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.27	15.07	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:3	35.45	2402	1.37	13.44	95	198	Off Idle	71.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.27	15.09	1.03	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:3	35.45	2391	1.37	13.45	95	198	Off Idle	71.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.28	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:4	35.45	2390	1.38	13.45	95	198	Off Idle	71.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	-10.29	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:4	35.45	2385	1.38	13.45	95	198	Off Idle	71.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.31	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:4	35.45	2382	1.38	13.45	95	198	Off Idle	71.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.33	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:4	35.45	2383	1.38	13.45	95	198	Off Idle	71.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.35	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:4	35.45	2396	1.37	13.45	95	198	Off Idle	71.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.33	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:4	35.45	2409	1.37	13.44	95	198	Off Idle	71.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.35	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:4	35.45	2411	1.37	13.43	95	198	Off Idle	71.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.34	15.04	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:07:5	35.45	2417	1.37	13.43	95	198	Off Idle	71.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.31	15.03	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:07:5	35.45	2410	1.37	13.45	95	198	Off Idle	71.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.32	15.02	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:07:5	35.45	2410	1.37	13.44	95	198	Off Idle	71.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.33	15.01	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:07:5	35.45	2418	1.37	13.46	95	198	Off Idle	71.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.35	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:5	35.45	2401	1.37	13.46	95	198	Off Idle	71.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-10.37	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:5	35.45	2393	1.37	13.46	95	198	Off Idle	71.6	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.37	15.07	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:6	35.45	2393	1.37	13.45	95	198	Off Idle	71.7	0	2	132	944 Turbo	0.32	Rich	1	14.6	-10.35	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:6	35.45	2393	1.37	13.45	95	198	Off Idle	71.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-10.35	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:6	35.45	2384	1.37	13.45	95	198	Off Idle	71.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.32	15.01	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:6	35.45	2396	1.37	13.45	95	198	Off Idle	71.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.31	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:6	35.45	2399	1.37	13.45	95	198	Off Idle	71.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.31	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:6	35.45	2400	1.37	13.46	95	198	Off Idle	71.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.32	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:6	35.45	2400	1.37	13.46	95	198	Off Idle	71.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.31	14.96	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:7	35.45	2398	1.37	13.46	95	198	Off Idle	71.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.34	14.91	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:7	35.45	2395	1.37	13.45	95	198	Off Idle	71.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.34	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:7	35.45	2394	1.37	13.45	95	198	Off Idle	71.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.34	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:7	35.45	2390	1.37	13.45	95	198	Off Idle	71.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.33	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:7	35.45	2388	1.37	13.45	95	198	Off Idle	71.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.35	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:7	35.45	2388	1.37	13.44	95	198	Off Idle	72.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.33	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:8	35.45	2384	1.37	13.44	95	198	Off Idle	72.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.33	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:07:8	35.45	2378	1.37	13.45	95	198	Off Idle	72.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.31	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:8	35.45	2380	1.37	13.45	95	198	Off Idle	72.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.28	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:8	35.45	2382	1.37	13.45	95	198	Off Idle	72.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.29	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:8	35.45	2390	1.37	13.44	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10.29	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:8	35.45	2396	1.37	13.44	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-10.28	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:9	35.45	2396	1.37	13.44	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-10.3	14.9	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:9	35.45	2394	1.36	13.43	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-10.31	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:9	35.45	2386	1.36	13.43	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-10.31	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:9	35.45	2386	1.36	13.44	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.31	14.99	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:9	35.45	2384	1.36	13.45	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.3	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:9	35.45	2382	1.36	13.43	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.29	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:07:9	35.45	2382	1.36	13.44	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.29	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:0	35.45	2382	1.36	13.45	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.31	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:0	35.45	2382	1.36	13.46	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.3	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:0	35.45	2380	1.36	13.46	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.32	15.07	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:0	35.45	2378	1.36	13.47	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.34	15.05	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:0	35.45	2359	1.36	13.47	95	198	Off Idle	72.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.35	15.06	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:0	35.45	2379	1.36	13.45	95	198	Off Idle	72.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.35	15.09	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:1	35.45	2380	1.36	13.45	95	198	Off Idle	72.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.34	15.09	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:1	35.45	2378	1.36	13.45	95	198	Off Idle	72.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.35	15.08	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:1	35.45	2372	1.36	13.43	95	198	Off Idle	72.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.32	15.06	1.03	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:1	35.45	2380	1.36	13.44	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.3	15.03	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:1	35.45	2376	1.36	13.44	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.3	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:1	35.45	2380	1.36	13.43	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-10.31	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:1	35.45	2380	1.36	13.44	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-10.31	14.98	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:2	35.45	2389	1.36	13.43	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.34	14.95	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:2	35.45	2390	1.36	13.43	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.36	Rich	1	14.6	-10.34	14.91	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:2	35.45	2391	1.36	13.43	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.33	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:2	35.45	2388	1.36	13.43	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.32	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:2	35.45	2385	1.36	13.43	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.32	14.79	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:2	35.45	2384	1.36	13.44	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.33	14.78	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:3	35.45	2384	1.35	13.44	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.33	14.76	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:3	35.45	2376	1.35	13.45	95	198	Off Idle	72.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.32	14.75	1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:3	35.45	2375	1.35	13.44	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.32	14.76	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:3	35.45	2374	1.35	13.45	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.32	14.78	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:3	35.45	2372	1.35	13.46	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.31	14.8	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:3	35.45	2371	1.35	13.46	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.31	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:4	35.45	2372	1.35	13.44	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.31	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:4	35.45	2372	1.35	13.45	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.24	Rich	1	14.6	-10.29	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:4	35.45	2374	1.35	13.45	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-10.28	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:4	35.45	2371	1.35	13.45	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.29	14.81	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:4	35.45	2368	1.35	13.45	94	198	Off Idle	72.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-10.29	14.82	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:4	35.45	2364	1.35	13.46	94	198	Off Idle	72.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.29	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:4	35.45	2368	1.35	13.45	94	198	Off Idle	72.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.3	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:5	35.45	2370	1.35	13.45	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.32	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:5	35.45	2374	1.35	13.44	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.33	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:5	35.45	2378	1.35	13.44	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.31	14.9	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:5	35.45	2378	1.36	13.44	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.3	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:5	35.45	2374	1.36	13.43	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.29	14.97	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:5	35.45	2372	1.36	13.43	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.29	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:6	35.45	2370	1.36	13.44	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.27	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:6	35.45	2364	1.36	13.44	95	198	Off Idle	72.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.3	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:6	35.45	2361	1.36	13.44	95	198	Off Idle	72.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.31	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:6	35.45	2362	1.36	13.44	95	198	Off Idle	72.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.32	15.05	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:6	35.45	2362	1.36	13.44	95	198	Off Idle	72.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.31	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:08:6	35.45	2364	1.36	13.44	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.32	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:6	35.45	2366	1.36	13.46	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.3	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:7	35.45	2364	1.36	13.46	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.29	15.05	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:08:7	35.45	2362	1.36	13.45	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.65	Lean	1	14.6	-10.28	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:7	35.45	2362	1.36	13.45	95	198	Off Idle	72.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-10.28	15	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:7	35.45	2362	1.36	13.46	95	198	Off Idle	73	0	2	132	944 Turbo	0.52	Lean	1	14.6	-10.26	14.97	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:7	35.45	2360	1.36	13.45	95	198	Off Idle	73	0	2	132	944 Turbo	0.45	Lean	1	14.6	-10.25	14.96	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:7	35.45	2360	1.36	13.45	95	198	Off Idle	73	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.25	14.94	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:8	35.45	2361	1.37	13.44	95	198	Off Idle	73.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-10.24	14.88	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:8	35.45	2362	1.37	13.46	95	198	Off Idle	73.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-10.23	14.86	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:8	35.45	2365	1.37	13.44	95	198	Off Idle	73.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.22	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:08:8	35.45	2364	1.37	13.44	95	198	Off Idle	73.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.19	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:08:8	35.45	2364	1.37	13.46	95	198	Off Idle	73.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.2	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:8	35.45	2364	1.37	13.45	95	198	Off Idle	73.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.19	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:9	35.45	2368	1.38	13.45	95	198	Off Idle	73.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.19	14.84	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:9	35.45	2368	1.38	13.45	95	198	Off Idle	73.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.17	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:9	35.45	2366	1.38	13.44	95	198	Off Idle	73.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.16	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:08:9	35.45	2356	1.38	13.44	95	198	Off Idle	73.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.11	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:08:9	35.45	2355	1.39	13.44	95	198	Off Idle	73.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.11	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:08:9	35.45	2355	1.39	13.44	95	198	Off Idle	73.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.08	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:08:9	35.45	2357	1.39	13.44	95	198	Off Idle	73.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.1	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:0	35.45	2361	1.39	13.45	95	198	Off Idle	73.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.09	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:0	35.45	2360	1.4	13.45	95	198	Off Idle	73.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.12	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:0	35.45	2361	1.4	13.45	95	198	Off Idle	73.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-10.1	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:0	35.45	2362	1.4	13.43	95	198	Off Idle	73.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-10.09	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:0	35.45	2361	1.41	13.44	95	198	Off Idle	73.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.09	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:0	35.45	2362	1.41	13.45	95	198	Off Idle	73.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.08	14.96	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:09:1	35.45	2362	1.41	13.46	95	198	Off Idle	73.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.06	15	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:09:1	35.45	2345	1.41	13.45	95	198	Off Idle	73.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.06	15.03	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:09:1	35.45	2352	1.41	13.46	95	198	Off Idle	73.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.03	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:1	35.45	2356	1.42	13.45	95	198	Off Idle	73.7	0	2	132	944 Turbo	0.7	Rich	1	14.7	-10.01	15.09	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:1	35.45	2354	1.42	13.45	95	198	Off Idle	73.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.99	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:09:1	35.45	2352	1.42	13.45	95	198	Off Idle	73.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.98	15.11	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:1	35.45	2366	1.42	13.44	95	198	Off Idle	73.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:2	35.45	2347	1.42	13.46	95	198	Off Idle	73.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.97	15.09	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:09:2	35.45	2345	1.43	13.44	95	198	Off Idle	73.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.94	15.06	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:09:2	35.45	2344	1.43	13.44	95	198	Off Idle	73.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.96	15.05	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:2	35.45	2349	1.43	13.45	95	198	Off Idle	73.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.97	15.07	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:2	35.45	2353	1.43	13.45	95	198	Off Idle	73.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.97	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:2	35.45	2361	1.43	13.45	95	198	Off Idle	74.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.98	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:3	35.45	2362	1.43	13.45	95	198	Off Idle	74.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.98	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:3	35.45	2368	1.44	13.44	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.98	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:09:3	35.45	2371	1.44	13.44	95	198	Off Idle	74.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.97	14.99	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:3	35.45	2370	1.44	13.44	95	198	Off Idle	74.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.95	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:3	35.45	2370	1.44	13.43	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.94	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:3	35.45	2361	1.44	13.43	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.93	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:4	35.45	2360	1.45	13.44	95	198	Off Idle	74.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.92	14.92	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:4	35.45	2359	1.45	13.44	95	198	Off Idle	74.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.94	14.89	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:4	35.45	2356	1.45	13.44	95	198	Off Idle	74.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.94	14.87	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:4	35.45	2353	1.45	13.44	95	198	Off Idle	74.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.92	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:4	35.45	2353	1.45	13.46	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.92	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:4	35.45	2352	1.46	13.45	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.94	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:4	35.45	2354	1.46	13.45	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.9	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:5	35.45	2352	1.46	13.45	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.88	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:5	35.45	2350	1.46	13.45	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.87	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:5	35.45	2346	1.46	13.46	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.87	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:5	35.45	2346	1.46	13.45	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.85	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:5	35.45	2346	1.46	13.45	95	198	Off Idle	74.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.82	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:5	35.45	2345	1.47	13.46	95	198	Off Idle	74.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.81	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:6	35.45	2325	1.47	13.45	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.81	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:6	35.45	2333	1.47	13.44	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.79	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:09:6	35.45	2339	1.47	13.44	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.79	14.9	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:6	35.45	2339	1.47	13.44	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.79	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:6	35.45	2339	1.47	13.44	95	198	Off Idle	74.8	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.78	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:6	35.45	2339	1.48	13.45	95	198	Off Idle	75	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.8	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:6	35.45	2340	1.48	13.45	95	198	Off Idle	75.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.79	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:7	35.45	2341	1.48	13.45	95	198	Off Idle	75.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.77	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:7	35.45	2339	1.48	13.44	95	198	Off Idle	75.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.79	15.05	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:7	35.45	2339	1.48	13.44	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.77	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:7	35.45	2337	1.48	13.45	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.77	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:7	35.45	2336	1.49	13.44	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.74	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:7	35.45	2336	1.49	13.45	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.72	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:8	35.45	2338	1.49	13.45	95	198	Off Idle	75.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.7	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:8	35.45	2342	1.49	13.45	95	198	Off Idle	75.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.68	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:8	35.45	2344	1.49	13.44	95	198	Off Idle	75.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.66	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:8	35.45	2348	1.49	13.44	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.66	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:8	35.45	2350	1.5	13.43	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.67	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:8	35.45	2350	1.5	13.43	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.69	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:9	35.45	2350	1.5	13.43	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.7	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:9	35.45	2351	1.5	13.43	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.72	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:9	35.45	2350	1.5	13.44	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.76	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:09:9	35.45	2340	1.5	13.44	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.75	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:9	35.45	2333	1.5	13.46	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.72	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:9	35.45	2333	1.5	13.46	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.7	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:09:9	35.45	2331	1.5	13.45	94	198	Off Idle	75.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.68	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:10:0	35.45	2329	1.5	13.45	94	198	Off Idle	75.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.66	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:10:0	35.45	2347	1.5	13.44	94	198	Off Idle	75.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.66	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:10:0	35.45	2349	1.5	13.44	95	198	Off Idle	75	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.66	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:10:0	35.45	2363	1.51	13.44	95	198	Off Idle	74.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.66	14.91	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:10:0	35.45	2349	1.51	13.44	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.65	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:10:0	35.45	2349	1.51	13.43	95	198	Off Idle	74.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.63	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:10:1	35.45	2349	1.51	13.44	95	198	Off Idle	74.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.64	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:1	35.45	2350	1.52	13.44	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.63	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:1	35.45	2350	1.52	13.45	95	198	Off Idle	74.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.63	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:1	35.45	2353	1.52	13.46	95	198	Off Idle	74.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.6	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:1	35.45	2355	1.52	13.45	95	198	Off Idle	74.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.58	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:1	35.45	2356	1.53	13.45	95	198	Off Idle	74.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.55	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:1	35.45	2361	1.53	13.46	95	198	Off Idle	74.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.52	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:2	35.45	2361	1.53	13.46	95	198	Off Idle	74.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.52	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:2	35.45	2358	1.54	13.44	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.48	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:2	35.45	2355	1.55	13.45	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.45	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:2	35.45	2347	1.55	13.43	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.44	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:2	35.45	2337	1.56	13.43	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.56	Lean	1	14.6	-9.43	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:2	35.45	2334	1.56	13.41	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.42	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:3	35.45	2324	1.57	13.43	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.4	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:3	35.45	2310	1.57	13.42	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.39	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:3	35.45	2310	1.57	13.4	95	198	Off Idle	74.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.38	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:3	35.45	2303	1.58	13.42	95	198	Off Idle	74.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.35	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:3	35.45	2317	1.58	13.44	95	198	Off Idle	74.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.35	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:3	35.45	2318	1.58	13.45	95	198	Off Idle	75.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.32	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:4	35.45	2323	1.59	13.46	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.32	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:4	35.45	2326	1.59	13.45	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.34	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:4	35.45	2329	1.59	13.45	95	198	Off Idle	75.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.31	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:4	35.45	2331	1.59	13.46	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.3	15.05	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:4	35.45	2348	1.59	13.45	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.33	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:4	35.45	2321	1.59	13.46	95	198	Off Idle	76	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.31	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:4	34.08	2330	1.59	13.44	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.28	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:5	34.08	2342	1.59	13.43	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.29	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:5	34.08	2325	1.59	13.44	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.28	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:10:5	34.08	2325	1.59	13.43	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.3	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:5	34.08	2342	1.59	13.43	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.32	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:5	34.08	2336	1.59	13.46	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.35	14.75	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:5	34.08	2329	1.59	13.46	95	198	Off Idle	76	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.37	14.74	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:6	34.08	2329	1.59	13.45	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.35	14.73	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:6	34.08	2316	1.59	13.45	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.34	14.72	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:6	34.08	2312	1.59	13.44	95	198	Off Idle	75.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	14.72	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:6	34.08	2314	1.59	13.44	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.32	14.73	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:6	34.08	2321	1.59	13.44	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.33	14.73	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:6	34.08	2327	1.59	13.44	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.32	14.75	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:6	34.08	2328	1.59	13.44	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.28	14.75	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:7	34.08	2330	1.59	13.45	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.26	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:7	34.08	2336	1.59	13.44	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.29	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:7	34.08	2340	1.59	13.43	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.27	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:7	34.08	2341	1.59	13.44	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.27	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:7	34.08	2345	1.59	13.44	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.25	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:7	35.45	2359	1.59	13.44	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.25	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:8	35.45	2359	1.59	13.44	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.25	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:8	35.45	2338	1.59	13.43	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.26	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:8	35.45	2329	1.59	13.43	95	198	Off Idle	75.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.26	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:8	35.45	2326	1.59	13.42	95	198	Off Idle	75.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.28	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:8	35.45	2325	1.59	13.44	95	198	Off Idle	75.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.29	14.79	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:10:8	35.45	2303	1.59	13.44	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.28	14.79	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:10:9	34.08	2321	1.59	13.44	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.3	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:9	34.08	2322	1.59	13.45	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.25	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:9	34.08	2324	1.59	13.46	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.23	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:9	34.08	2324	1.59	13.45	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.25	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:9	34.08	2326	1.59	13.44	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.26	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:9	34.08	2325	1.59	13.45	95	198	Off Idle	76	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.23	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:10:9	34.08	2325	1.59	13.44	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.26	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:0	34.08	2325	1.59	13.42	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.25	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:0	34.08	2324	1.59	13.43	95	198	Off Idle	76.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.26	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:0	34.08	2318	1.59	13.45	95	198	Off Idle	76.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.25	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:0	34.08	2318	1.59	13.44	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.26	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:0	34.08	2319	1.59	13.45	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.26	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:0	35.45	2336	1.59	13.46	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.28	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:1	35.45	2322	1.59	13.44	95	198	Off Idle	76.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.27	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:1	35.45	2322	1.59	13.44	95	198	Off Idle	76	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.26	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:1	35.45	2322	1.59	13.45	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.25	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:1	35.45	2321	1.59	13.43	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.25	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:1	35.45	2326	1.59	13.44	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.23	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:1	35.45	2326	1.59	13.46	95	198	Off Idle	75.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.24	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:1	34.08	2330	1.6	13.45	95	198	Off Idle	75.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.22	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:2	34.08	2333	1.6	13.46	95	198	Off Idle	75.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.19	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:2	34.08	2333	1.6	13.46	95	198	Off Idle	75.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.18	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:2	34.08	2333	1.6	13.46	95	198	Off Idle	75.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.14	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:2	34.08	2321	1.6	13.46	95	198	Off Idle	75.7	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.14	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:2	34.08	2327	1.61	13.46	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.14	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:2	34.08	2327	1.61	13.46	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.1	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:3	34.08	2323	1.61	13.47	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.06	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:3	34.08	2321	1.61	13.46	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.09	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:3	34.08	2320	1.62	13.47	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.04	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:3	34.08	2315	1.62	13.46	95	198	Off Idle	76	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.04	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:3	34.08	2321	1.62	13.45	95	198	Off Idle	76.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.05	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:3	34.08	2319	1.62	13.46	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.04	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:4	34.08	2318	1.62	13.46	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.02	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:4	34.08	2317	1.62	13.43	95	198	Off Idle	76.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.05	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:4	34.08	2318	1.63	13.44	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.06	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:11:4	34.08	2318	1.63	13.45	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.07	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:4	34.08	2319	1.63	13.43	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.07	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:4	34.08	2322	1.63	13.45	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.05	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:4	34.08	2322	1.63	13.45	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.09	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:5	34.08	2320	1.63	13.45	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.08	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:5	34.08	2318	1.63	13.45	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.08	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:5	34.08	2315	1.63	13.45	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-9.11	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:5	34.08	2315	1.63	13.44	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.11	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:5	34.08	2314	1.63	13.45	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.07	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:5	34.08	2316	1.63	13.44	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.09	15.16	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:6	34.08	2316	1.63	13.44	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.05	15.16	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:6	34.08	2313	1.63	13.45	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.06	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:6	34.08	2314	1.63	13.45	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.06	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:6	34.08	2314	1.63	13.42	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.09	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:6	34.08	2312	1.63	13.43	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.04	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:6	34.08	2317	1.63	13.44	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.07	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:6	34.08	2313	1.63	13.43	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9.05	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:7	34.08	2313	1.63	13.45	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.03	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:7	34.08	2316	1.63	13.45	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.06	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:7	34.08	2317	1.63	13.44	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.05	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:7	34.08	2312	1.63	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.04	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:11:7	34.08	2310	1.63	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.08	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:7	34.08	2317	1.63	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.07	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:8	34.08	2317	1.63	13.47	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.03	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:8	34.08	2324	1.63	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.04	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:8	34.08	2329	1.63	13.44	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.04	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:8	34.08	2331	1.63	13.44	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.04	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:8	34.08	2332	1.63	13.44	95	198	Off Idle	76.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.04	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:8	34.08	2326	1.63	13.44	95	198	Off Idle	76.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.08	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:9	34.08	2319	1.63	13.45	95	198	Off Idle	76	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.1	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:9	34.08	2319	1.63	13.45	95	198	Off Idle	76	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.08	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:9	34.08	2307	1.63	13.45	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.07	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:9	34.08	2306	1.63	13.44	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.07	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:9	34.08	2304	1.63	13.45	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.04	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:9	34.08	2308	1.64	13.45	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.04	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:11:9	34.08	2315	1.64	13.43	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.04	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:0	34.08	2316	1.64	13.43	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.01	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:0	34.08	2318	1.64	13.45	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.01	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:0	34.08	2324	1.64	13.44	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.04	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:0	34.08	2325	1.64	13.45	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.99	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:0	34.08	2325	1.64	13.45	95	198	Off Idle	75.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.96	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:0	34.08	2322	1.64	13.44	95	198	Off Idle	75.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.99	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:1	34.08	2318	1.64	13.45	95	198	Off Idle	76.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.98	15.05	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:1	34.08	2311	1.64	13.45	95	198	Off Idle	76.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:1	34.08	2310	1.64	13.43	95	198	Off Idle	76.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.04	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:1	34.08	2307	1.64	13.45	95	198	Off Idle	76.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:1	34.08	2301	1.64	13.46	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.99	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:1	34.08	2301	1.64	13.44	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.01	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:1	34.08	2298	1.64	13.44	95	198	Off Idle	76.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:2	34.08	2298	1.64	13.46	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:2	34.08	2299	1.64	13.45	95	198	Off Idle	77	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.02	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:2	34.08	2304	1.64	13.46	95	198	Off Idle	77	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:2	34.08	2312	1.64	13.46	95	198	Off Idle	77	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.04	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:2	34.08	2313	1.64	13.45	95	198	Off Idle	77.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.04	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:2	34.08	2317	1.64	13.44	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.04	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:3	34.08	2317	1.64	13.45	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.04	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:3	34.08	2313	1.64	13.45	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.09	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:3	34.08	2310	1.64	13.45	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.05	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:12:3	34.08	2307	1.63	13.44	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.07	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:3	34.08	2305	1.63	13.43	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.08	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:3	34.08	2301	1.63	13.43	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.06	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:4	34.08	2307	1.63	13.44	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.09	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:4	34.08	2309	1.63	13.42	95	198	Off Idle	77.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.1	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:4	34.08	2310	1.63	13.43	95	198	Off Idle	77	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.08	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:4	34.08	2312	1.63	13.44	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.07	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:4	34.08	2310	1.63	13.41	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.09	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:4	34.08	2310	1.63	13.42	94	198	Off Idle	76.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.08	14.75	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:4	34.08	2315	1.63	13.44	94	198	Off Idle	76.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.05	14.74	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:5	34.08	2318	1.63	13.44	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.06	14.76	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:5	34.08	2319	1.63	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.04	14.77	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:5	34.08	2318	1.63	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.02	14.76	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:5	34.08	2316	1.63	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.01	14.77	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:5	34.08	2311	1.63	13.43	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.03	14.77	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:5	34.08	2309	1.63	13.43	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.03	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:6	34.08	2305	1.63	13.44	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.04	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:6	34.08	2303	1.63	13.43	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.04	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:6	34.08	2305	1.63	13.44	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.03	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:6	34.08	2306	1.63	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.02	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:6	34.08	2314	1.63	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.04	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:6	34.08	2320	1.64	13.44	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.06	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:6	34.08	2320	1.64	13.45	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.04	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:7	34.08	2324	1.64	13.45	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.05	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:7	34.08	2328	1.64	13.45	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.07	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:7	34.08	2313	1.64	13.44	95	198	Off Idle	76.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.04	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:7	34.08	2308	1.64	13.45	95	198	Off Idle	76.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.04	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:7	34.08	2298	1.64	13.46	95	198	Off Idle	76.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.99	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:7	34.08	2258	1.64	13.45	95	198	Off Idle	76.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.98	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:8	34.08	2275	1.64	13.45	95	198	Off Idle	76.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.97	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:8	34.08	2288	1.64	13.45	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.4	Rich	1	14.7	-8.95	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:8	34.08	2289	1.64	13.43	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.95	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:8	34.08	2310	1.64	13.42	95	198	Off Idle	76.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.95	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:8	34.08	2302	1.64	13.44	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.9	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:8	34.08	2301	1.64	13.44	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.92	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:9	34.08	2309	1.64	13.43	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.92	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:9	34.08	2312	1.64	13.44	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.93	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:9	34.08	2313	1.64	13.44	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.97	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:12:9	34.08	2317	1.64	13.45	95	198	Off Idle	77	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.01	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:9	34.08	2320	1.64	13.45	95	198	Off Idle	77.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.03	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:9	34.08	2323	1.64	13.44	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:12:9	34.08	2320	1.64	13.45	95	198	Off Idle	77.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.98	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:0	34.08	2318	1.64	13.45	95	198	Off Idle	77	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.96	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:0	34.08	2318	1.64	13.44	95	198	Off Idle	77	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.98	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:0	34.08	2314	1.64	13.45	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.94	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:0	34.08	2308	1.64	13.44	95	198	Off Idle	76.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.98	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:0	34.08	2306	1.64	13.44	95	198	Off Idle	76.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.97	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:0	34.08	2292	1.64	13.44	95	198	Off Idle	76.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.94	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:1	34.08	2287	1.64	13.44	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.94	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:1	34.08	2289	1.64	13.43	95	198	Off Idle	76.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.94	14.76	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:1	34.08	2290	1.64	13.44	95	198	Off Idle	76.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.87	14.75	1	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:1	34.08	2296	1.64	13.45	95	198	Off Idle	76.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.85	14.74	1	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:1	34.08	2296	1.64	13.44	95	198	Off Idle	76.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.89	14.73	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:1	34.08	2303	1.65	13.43	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.87	14.75	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:1	34.08	2307	1.65	13.44	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.91	14.75	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:2	34.08	2315	1.65	13.44	95	198	Off Idle	77.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.94	14.75	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:2	34.08	2315	1.65	13.44	95	198	Off Idle	77.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.97	14.77	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:2	34.08	2325	1.65	13.44	95	198	Off Idle	77.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.96	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:13:2	34.08	2326	1.65	13.45	95	198	Off Idle	77.4	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.97	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:2	34.08	2330	1.65	13.43	95	198	Off Idle	77.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.97	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:2	34.08	2326	1.65	13.45	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.95	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:3	34.08	2323	1.65	13.45	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.99	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:3	34.08	2312	1.65	13.44	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.01	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:3	34.08	2297	1.65	13.44	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.97	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:3	34.08	2297	1.64	13.46	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.98	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:3	34.08	2283	1.64	13.46	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.99	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:3	34.08	2280	1.64	13.43	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.99	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:4	34.08	2280	1.64	13.45	95	197	Off Idle	77.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.92	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:4	34.08	2291	1.64	13.46	95	197	Off Idle	77.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.95	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:4	34.08	2300	1.64	13.44	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.94	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:4	34.08	2306	1.64	13.45	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.93	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:4	34.08	2307	1.64	13.45	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.95	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:4	34.08	2312	1.64	13.43	95	197	Off Idle	77.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.96	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:4	34.08	2311	1.64	13.43	95	197	Off Idle	77.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.93	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:5	34.08	2308	1.64	13.45	95	197	Off Idle	77.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.92	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:5	34.08	2302	1.64	13.45	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.97	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:5	34.08	2296	1.64	13.45	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.98	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:5	34.08	2295	1.64	13.45	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.99	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:5	34.08	2291	1.64	13.45	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:5	34.08	2289	1.64	13.42	95	198	Off Idle	77.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:6	34.08	2289	1.64	13.43	95	198	Off Idle	77.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.96	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:6	34.08	2289	1.64	13.43	95	197	Off Idle	77.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.94	15.05	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:6	34.08	2291	1.64	13.43	95	197	Off Idle	77.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.96	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:6	34.08	2292	1.64	13.44	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.94	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:6	34.08	2297	1.64	13.45	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.92	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:6	34.08	2301	1.64	13.43	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.96	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:6	34.08	2302	1.64	13.43	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.97	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:7	34.08	2305	1.64	13.44	95	198	Off Idle	77.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.94	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:7	34.08	2311	1.64	13.45	95	198	Off Idle	77.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.98	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:7	34.08	2311	1.64	13.44	95	198	Off Idle	77.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-9.02	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:7	34.08	2308	1.64	13.45	95	198	Off Idle	77.5	0	2	132	944 Turbo	0.19	Rich	1	14.6	-9.04	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:7	34.08	2306	1.64	13.46	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.02	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:7	34.08	2304	1.64	13.46	95	197	Off Idle	77.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.04	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:8	34.08	2294	1.64	13.45	95	197	Off Idle	77.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.02	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:8	34.08	2290	1.64	13.46	95	197	Off Idle	77.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.98	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:8	34.08	2286	1.64	13.46	95	197	Off Idle	77.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.97	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:8	34.08	2284	1.64	13.45	95	197	Off Idle	77.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.98	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:8	34.08	2282	1.64	13.45	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.99	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:8	34.08	2288	1.64	13.45	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.99	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:9	34.08	2294	1.64	13.44	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.99	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:9	34.08	2297	1.64	13.43	95	198	Off Idle	77.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.97	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:9	34.08	2298	1.64	13.44	95	198	Off Idle	78	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.95	14.9	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:13:9	34.08	2312	1.64	13.44	95	198	Off Idle	78	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.98	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:9	34.08	2312	1.63	13.43	95	198	Off Idle	78	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9	14.99	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:9	34.08	2311	1.63	13.44	95	198	Off Idle	78	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.01	15.07	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:13:9	34.08	2300	1.63	13.45	95	198	Off Idle	78	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.04	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:0	34.08	2300	1.63	13.45	95	198	Off Idle	77.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.05	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:0	34.08	2291	1.63	13.45	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.04	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:0	34.08	2287	1.63	13.45	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.04	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:0	34.08	2285	1.63	13.44	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.05	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:0	34.08	2285	1.63	13.43	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.04	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:0	34.08	2285	1.63	13.44	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.99	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:1	34.08	2286	1.63	13.44	95	197	Off Idle	77.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:1	34.08	2292	1.63	13.42	95	197	Off Idle	77.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.98	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:1	34.08	2292	1.63	13.42	95	197	Off Idle	77.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.96	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:1	34.08	2298	1.63	13.44	95	197	Off Idle	77.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.92	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:14:1	34.08	2299	1.63	13.45	95	197	Off Idle	77.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.92	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:1	34.08	2297	1.63	13.42	95	197	Off Idle	77.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.94	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:1	34.08	2297	1.63	13.43	95	197	Off Idle	77.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.94	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:2	34.08	2306	1.63	13.43	95	197	Off Idle	77.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.94	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:2	34.08	2310	1.63	13.43	95	197	Off Idle	77.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.97	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:2	34.08	2297	1.63	13.43	95	197	Off Idle	77.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-8.99	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:2	34.08	2297	1.63	13.44	95	197	Off Idle	77.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.96	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:2	34.08	2285	1.63	13.43	95	197	Off Idle	77.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:2	34.08	2287	1.63	13.42	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.01	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:3	34.08	2288	1.63	13.43	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.98	14.79	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:3	34.08	2290	1.63	13.43	95	198	Off Idle	77	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.96	14.79	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:3	34.08	2296	1.63	13.43	95	198	Off Idle	77	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.98	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:3	34.08	2296	1.63	13.43	95	198	Off Idle	77	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.97	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:3	34.08	2297	1.63	13.44	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.99	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:3	34.08	2300	1.63	13.44	95	197	Off Idle	76.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.98	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:4	34.08	2300	1.63	13.44	95	197	Off Idle	76.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:4	34.08	2296	1.63	13.43	95	197	Off Idle	76.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.03	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:4	34.08	2292	1.63	13.43	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:4	34.08	2291	1.63	13.43	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.98	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:4	34.08	2291	1.63	13.43	95	198	Off Idle	76.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.97	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:4	34.08	2286	1.63	13.43	95	198	Off Idle	76.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:4	34.08	2286	1.63	13.43	95	198	Off Idle	77.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.95	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:5	34.08	2285	1.63	13.45	95	198	Off Idle	77.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.95	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:5	34.08	2286	1.63	13.45	95	198	Off Idle	77.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.97	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:5	34.08	2286	1.63	13.44	95	198	Off Idle	77.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.99	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:14:5	34.08	2288	1.63	13.45	95	198	Off Idle	77.8	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.98	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:5	34.08	2289	1.63	13.45	95	198	Off Idle	77.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.01	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:5	34.08	2291	1.62	13.44	95	198	Off Idle	77.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.06	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:6	34.08	2297	1.62	13.44	95	197	Off Idle	77.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.05	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:6	34.08	2294	1.62	13.45	95	197	Off Idle	77.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.11	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:6	34.08	2292	1.62	13.44	95	197	Off Idle	77.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.13	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:6	34.08	2290	1.62	13.44	95	197	Off Idle	77.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.12	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:6	34.08	2280	1.61	13.45	95	197	Off Idle	77.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.11	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:6	34.08	2280	1.61	13.46	95	197	Off Idle	77.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.14	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:6	34.08	2280	1.61	13.43	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.16	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:7	34.08	2282	1.6	13.45	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.17	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:14:7	34.08	2283	1.6	13.45	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.18	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:7	34.08	2284	1.59	13.45	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.22	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:7	34.08	2290	1.59	13.43	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.26	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:7	34.08	2290	1.58	13.45	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.3	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:7	34.08	2289	1.57	13.45	95	197	Off Idle	77.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.35	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:8	34.08	2291	1.57	13.44	95	197	Off Idle	77.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.37	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:8	34.08	2290	1.56	13.44	95	197	Off Idle	77.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.4	15.01	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:14:8	34.08	2290	1.56	13.45	95	198	Off Idle	77.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.42	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:14:8	34.08	2291	1.55	13.43	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.43	14.97	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:14:8	34.08	2290	1.54	13.44	95	198	Off Idle	78	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.44	14.97	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:14:8	35.45	2296	1.54	13.43	95	197	Off Idle	77.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.5	14.96	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:14:9	35.45	2284	1.53	13.43	95	197	Off Idle	77.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.49	14.93	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:14:9	35.45	2277	1.52	13.44	95	197	Off Idle	78	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.52	14.9	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:9	35.45	2274	1.52	13.43	95	197	Off Idle	78	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.55	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:9	35.45	2274	1.51	13.42	95	197	Off Idle	77.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.56	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:9	35.45	2276	1.51	13.43	95	197	Off Idle	77.7	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.54	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:9	35.45	2279	1.5	13.44	95	198	Off Idle	77.7	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.56	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:14:9	35.45	2278	1.5	13.44	95	198	Off Idle	77.9	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.56	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:0	35.45	2279	1.5	13.42	95	198	Off Idle	78	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.56	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:0	35.45	2279	1.49	13.44	95	198	Off Idle	78.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.56	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:0	35.45	2282	1.49	13.45	95	198	Off Idle	78.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.55	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:0	35.45	2282	1.49	13.43	95	197	Off Idle	78.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.57	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:15:0	35.45	2282	1.49	13.42	95	197	Off Idle	78.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.59	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:0	35.45	2281	1.49	13.43	95	197	Off Idle	78.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.6	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:1	35.45	2282	1.49	13.43	95	197	Off Idle	78.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.6	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:1	35.45	2287	1.48	13.44	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.66	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:1	35.45	2286	1.48	13.45	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.64	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:1	35.45	2286	1.48	13.45	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.61	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:1	35.45	2283	1.48	13.45	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.64	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:1	35.45	2285	1.48	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.67	14.93	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:1	35.45	2286	1.48	13.44	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.64	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:2	35.45	2286	1.48	13.44	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.65	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:2	35.45	2284	1.47	13.45	95	197	Off Idle	78.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.66	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:2	35.45	2279	1.47	13.45	95	197	Off Idle	78.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.66	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:2	35.45	2278	1.47	13.46	95	197	Off Idle	78.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.65	15.17	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:2	35.45	2274	1.47	13.45	95	197	Off Idle	78.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.64	15.22	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:2	35.45	2273	1.47	13.44	95	197	Off Idle	78.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.64	15.27	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:3	35.45	2273	1.47	13.44	95	197	Off Idle	78.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.66	15.3	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:3	35.45	2274	1.47	13.44	95	197	Off Idle	78.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.64	15.32	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:3	35.45	2273	1.47	13.46	95	197	Off Idle	78.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.63	15.34	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:3	35.45	2275	1.47	13.46	95	197	Off Idle	78.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.65	15.34	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:3	35.45	2275	1.47	13.44	95	198	Off Idle	78.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.65	15.34	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:3	35.45	2278	1.47	13.45	95	198	Off Idle	78.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.66	15.33	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:4	35.45	2279	1.47	13.45	95	198	Off Idle	78.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.66	15.3	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:4	35.45	2278	1.47	13.43	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.66	15.27	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:4	35.45	2278	1.47	13.43	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.65	15.21	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:4	35.45	2275	1.47	13.43	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.65	15.18	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:4	35.45	2273	1.47	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.62	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:4	35.45	2274	1.47	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.63	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:4	35.45	2274	1.47	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.59	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:5	35.45	2271	1.47	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.49	Lean	1	14.7	-9.56	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:5	35.45	2270	1.47	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.57	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:5	35.45	2270	1.47	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.59	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:5	35.45	2273	1.47	13.46	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.6	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:5	35.45	2273	1.47	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.61	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:5	35.45	2274	1.47	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.63	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:6	35.45	2277	1.47	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.65	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:6	35.45	2277	1.47	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.67	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:6	35.45	2277	1.47	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.65	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:6	35.45	2280	1.47	13.46	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.67	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:6	35.45	2279	1.47	13.46	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.66	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:6	35.45	2281	1.47	13.45	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.67	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:6	35.45	2275	1.47	13.44	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.66	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:7	35.45	2273	1.48	13.44	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.62	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:7	35.45	2265	1.48	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.6	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:7	35.45	2265	1.48	13.43	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:7	35.45	2263	1.48	13.42	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.59	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:7	35.45	2262	1.48	13.42	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.6	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:7	35.45	2266	1.48	13.42	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.6	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:8	35.45	2247	1.48	13.42	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.59	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:8	34.08	2247	1.48	13.42	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.6	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:8	34.08	2263	1.48	13.43	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.58	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:8	34.08	2266	1.48	13.42	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.57	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:8	34.08	2266	1.48	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.56	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:15:8	34.08	2269	1.48	13.43	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.56	15.1	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:9	34.08	2273	1.48	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.57	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:9	34.08	2289	1.48	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.56	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:9	35.45	2280	1.48	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.57	15.13	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:9	35.45	2274	1.48	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.57	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:9	35.45	2274	1.48	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.53	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:15:9	35.45	2275	1.48	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.56	15.11	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:15:9	35.45	2275	1.48	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.56	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:0	35.45	2276	1.48	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.55	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:16:0	35.45	2278	1.48	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.56	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:16:0	35.45	2278	1.48	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.57	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:0	35.45	2278	1.48	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.56	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:0	35.45	2280	1.48	13.44	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.56	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:16:0	35.45	2276	1.48	13.45	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.6	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:16:1	35.45	2276	1.48	13.43	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.59	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:16:1	35.45	2271	1.48	13.43	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.59	15.05	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:1	35.45	2265	1.48	13.42	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.6	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:1	35.45	2258	1.48	13.41	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.62	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:1	35.45	2257	1.48	13.41	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.61	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:1	35.45	2255	1.48	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.59	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:1	35.45	2258	1.48	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.56	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:2	35.45	2258	1.48	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.56	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:2	35.45	2254	1.48	13.44	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.56	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:2	35.45	2255	1.48	13.45	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.54	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:2	35.45	2255	1.48	13.45	95	198	Off Idle	79.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.56	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:2	35.45	2259	1.48	13.45	95	198	Off Idle	79.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.57	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:2	35.45	2257	1.48	13.45	95	198	Off Idle	79.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.53	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:3	35.45	2276	1.48	13.45	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.55	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:3	35.45	2270	1.48	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.56	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:3	34.08	2249	1.48	13.43	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.54	14.8	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:3	34.08	2271	1.48	13.45	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.52	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:3	34.08	2271	1.48	13.46	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.55	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:3	34.08	2271	1.48	13.45	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.56	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:4	34.08	2275	1.48	13.46	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.54	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:4	34.08	2276	1.48	13.47	95	197	Off Idle	79.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.57	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:4	34.08	2278	1.48	13.45	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.59	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:4	35.45	2292	1.48	13.46	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.56	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:4	35.45	2269	1.48	13.46	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.58	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:4	35.45	2266	1.48	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.56	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:4	35.45	2258	1.48	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.53	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:5	35.45	2246	1.48	13.47	95	197	Off Idle	79	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.51	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:5	35.45	2246	1.48	13.47	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.53	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:5	35.45	2245	1.48	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.52	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:5	35.45	2244	1.48	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.55	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:5	35.45	2235	1.48	13.43	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.52	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:5	35.45	2246	1.48	13.43	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.52	15.1	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:16:6	35.45	2246	1.48	13.43	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.51	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:16:6	35.45	2246	1.48	13.45	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.5	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:6	35.45	2256	1.48	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.55	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:6	34.08	2229	1.48	13.44	95	197	Off Idle	80	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.53	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:6	34.08	2249	1.48	13.42	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.54	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:6	34.08	2251	1.48	13.42	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.54	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:6	34.08	2239	1.48	13.43	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.53	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:7	34.08	2249	1.47	13.44	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.36	Rich	1	14.7	-9.49	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:7	34.08	2264	1.47	13.45	95	197	Off Idle	81	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.53	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:7	34.08	2268	1.47	13.43	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.54	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:7	35.45	2289	1.47	13.45	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.52	14.89	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:7	35.45	2274	1.47	13.45	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.52	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:7	35.45	2274	1.47	13.45	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.53	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:8	35.45	2273	1.47	13.45	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.53	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:8	35.45	2293	1.47	13.46	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.51	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:8	35.45	2286	1.47	13.47	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.53	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:8	35.45	2278	1.48	13.45	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:8	35.45	2274	1.48	13.43	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.55	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:16:8	35.45	2274	1.48	13.43	95	197	Off Idle	79.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.54	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:9	35.45	2270	1.48	13.44	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.53	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:9	35.45	2256	1.48	13.43	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.55	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:9	35.45	2256	1.48	13.44	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.55	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:9	35.45	2244	1.48	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.55	14.9	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:9	34.08	2222	1.48	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.53	14.93	1.02	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:9	34.08	2230	1.48	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.51	14.96	1.02	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:16:9	34.08	2235	1.49	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.47	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:0	34.08	2225	1.49	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.49	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:0	34.08	2239	1.49	13.44	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.47	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:0	34.08	2239	1.49	13.43	95	197	Off Idle	79.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.47	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:0	34.08	2243	1.49	13.45	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.48	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:0	34.08	2242	1.49	13.46	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.49	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:0	34.08	2242	1.49	13.45	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.44	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:1	34.08	2244	1.49	13.45	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.42	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:1	34.08	2247	1.49	13.43	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.42	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:1	34.08	2247	1.5	13.42	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.41	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:1	34.08	2249	1.5	13.42	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.39	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:1	34.08	2250	1.5	13.43	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.4	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:1	34.08	2248	1.5	13.44	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.4	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:1	34.08	2252	1.5	13.43	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.41	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:2	34.08	2256	1.5	13.43	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.41	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:2	34.08	2259	1.5	13.44	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.37	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:2	34.08	2260	1.5	13.44	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.36	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:2	34.08	2267	1.5	13.44	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.38	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:17:2	34.08	2285	1.51	13.43	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.38	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:2	34.08	2285	1.51	13.42	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.36	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:3	34.08	2268	1.51	13.43	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.37	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:3	34.08	2266	1.51	13.42	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.37	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:3	34.08	2266	1.51	13.42	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.37	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:3	34.08	2266	1.52	13.42	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.35	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:3	34.08	2266	1.52	13.43	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.36	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:3	34.08	2264	1.52	13.42	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.37	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:4	34.08	2256	1.52	13.45	95	197	Off Idle	79.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.35	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:4	34.08	2233	1.52	13.46	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.3	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:4	34.08	2242	1.53	13.46	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.31	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:4	34.08	2241	1.53	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.31	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:4	34.08	2238	1.53	13.44	95	197	Off Idle	80	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.26	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:4	34.08	2238	1.53	13.45	95	197	Off Idle	80	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.24	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:4	34.08	2236	1.54	13.45	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.21	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:5	34.08	2238	1.54	13.44	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	-9.19	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:5	34.08	2239	1.55	13.44	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.15	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:17:5	34.08	2239	1.55	13.44	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.11	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:5	34.08	2245	1.56	13.45	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.03	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:5	34.08	2250	1.56	13.46	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.02	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:5	34.08	2251	1.57	13.46	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.99	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:6	34.08	2251	1.58	13.45	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:6	34.08	2267	1.58	13.45	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.97	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:6	34.08	2265	1.59	13.43	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.96	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:6	34.08	2265	1.6	13.42	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.9	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:6	34.08	2266	1.6	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.83	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:6	34.08	2259	1.61	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.81	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:6	34.08	2259	1.62	13.42	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.8	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:7	34.08	2236	1.63	13.42	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.73	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:7	34.08	2235	1.64	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.69	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:7	34.08	2226	1.64	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.66	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:7	34.08	2226	1.65	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.64	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:7	34.08	2229	1.66	13.43	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.6	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:17:7	34.08	2221	1.67	13.44	95	197	Off Idle	80	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.57	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:8	34.08	2244	1.67	13.45	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.51	14.93	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:8	34.08	2247	1.68	13.45	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.48	14.9	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:8	34.08	2261	1.68	13.46	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.47	14.85	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:8	34.08	2298	1.69	13.45	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.45	14.82	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:8	34.08	2298	1.69	13.45	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.42	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:8	34.08	2259	1.7	13.45	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.38	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:17:9	34.08	2254	1.71	13.44	95	197	Off Idle	81	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.36	14.78	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:9	34.08	2254	1.72	13.44	95	197	Off Idle	80.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.35	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:9	34.08	2249	1.72	13.43	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.31	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:9	34.08	2247	1.73	13.43	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.31	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:9	34.08	2247	1.73	13.43	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.28	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:9	34.08	2237	1.74	13.45	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.23	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:17:9	34.08	2230	1.74	13.45	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.21	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:18:0	34.08	2239	1.75	13.44	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.18	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:18:0	34.08	2239	1.75	13.45	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.15	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:0	34.08	2245	1.75	13.45	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.12	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:0	34.08	2267	1.76	13.45	95	197	Off Idle	80.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.08	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:0	34.08	2256	1.77	13.45	95	197	Off Idle	80.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.02	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:0	34.08	2255	1.77	13.46	95	197	Off Idle	80.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:1	34.08	2262	1.78	13.44	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.99	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:1	32.72	2243	1.78	13.43	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.93	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:1	32.72	2243	1.79	13.45	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.89	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:1	32.72	2253	1.79	13.45	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.89	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:1	32.72	2253	1.79	13.43	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.89	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:1	32.72	2245	1.8	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.82	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:1	32.72	2240	1.8	13.45	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.8	14.78	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:2	32.72	2239	1.81	13.43	95	197	Off Idle	80	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.78	14.79	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:2	34.08	2246	1.81	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.73	14.8	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:2	34.08	2240	1.81	13.43	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.69	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:2	34.08	2243	1.82	13.43	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:2	34.08	2249	1.82	13.42	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:2	34.08	2252	1.83	13.42	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-7.69	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:3	34.08	2258	1.83	13.44	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:3	34.08	2251	1.83	13.45	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:3	34.08	2251	1.84	13.44	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:3	34.08	2250	1.84	13.44	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:3	34.08	2252	1.85	13.46	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:3	34.08	2250	1.85	13.46	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:4	34.08	2252	1.85	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.61	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:4	34.08	2254	1.85	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.59	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:4	34.08	2247	1.85	13.44	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.61	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:4	34.08	2247	1.85	13.44	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.6	14.89	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:4	34.08	2230	1.85	13.43	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.58	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:4	34.08	2242	1.85	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.64	Rich	1	14.7	-7.57	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:4	34.08	2242	1.85	13.46	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.57	14.83	1.01	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:5	34.08	2243	1.85	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.57	14.83	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:5	34.08	2260	1.85	13.44	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.58	14.84	1.01	3.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:5	34.08	2260	1.85	13.46	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.51	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:5	34.08	2242	1.85	13.45	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.53	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:5	34.08	2246	1.85	13.44	95	197	Off Idle	80.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.54	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:5	34.08	2249	1.85	13.42	95	197	Off Idle	80.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.54	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:6	34.08	2250	1.85	13.42	95	197	Off Idle	80.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.54	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:6	34.08	2250	1.85	13.43	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.58	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:6	34.08	2249	1.85	13.44	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.59	14.88	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:6	32.72	2240	1.85	13.46	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.57	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:6	32.72	2253	1.85	13.46	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.58	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:6	32.72	2245	1.85	13.45	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.58	14.9	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:18:6	32.72	2245	1.85	13.45	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.58	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:7	32.72	2243	1.85	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.51	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:7	32.72	2231	1.85	13.42	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.55	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:7	32.72	2256	1.85	13.43	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.5	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:7	32.72	2256	1.85	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.51	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:7	32.72	2265	1.85	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.53	15.05	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:7	32.72	2281	1.85	13.44	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.53	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:8	32.72	2271	1.86	13.44	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.67	Rich	1	14.7	-7.47	15.06	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:18:8	32.72	2260	1.86	13.46	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.48	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:8	32.72	2259	1.86	13.44	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.46	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:8	32.72	2254	1.87	13.42	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.39	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:8	32.72	2246	1.87	13.43	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.35	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:8	32.72	2255	1.87	13.44	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.36	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:9	32.72	2250	1.88	13.44	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.37	15.02	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:9	32.72	2250	1.88	13.43	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.35	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:18:9	32.72	2248	1.88	13.45	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.33	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:18:9	32.72	2249	1.89	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.33	14.96	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:18:9	34.08	2256	1.89	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.33	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:18:9	34.08	2247	1.89	13.43	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.27	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:18:9	34.08	2247	1.9	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.27	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:0	34.08	2250	1.9	13.44	95	197	Off Idle	80	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.28	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:0	34.08	2251	1.9	13.43	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.15	Lean	1	14.7	-7.25	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:0	34.08	2255	1.9	13.44	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.22	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:0	34.08	2241	1.91	13.46	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.23	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:0	32.72	2241	1.91	13.43	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.26	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:0	32.72	2262	1.91	13.43	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.26	14.88	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:1	32.72	2255	1.91	13.43	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.28	Rich	1	14.7	-7.21	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:1	32.72	2255	1.91	13.43	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.24	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:1	32.72	2254	1.91	13.42	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.2	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:1	32.72	2256	1.91	13.42	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.17	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:1	32.72	2254	1.91	13.43	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.13	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:1	32.72	2254	1.91	13.43	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.14	15.05	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:1	32.72	2254	1.91	13.46	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.14	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:2	32.72	2254	1.91	13.47	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.16	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:2	32.72	2255	1.91	13.46	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.23	15.12	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:2	32.72	2255	1.91	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.22	15.12	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:2	32.72	2243	1.91	13.43	95	197	Off Idle	80	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.23	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:2	32.72	2243	1.91	13.43	95	197	Off Idle	80	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.24	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:2	32.72	2251	1.91	13.42	95	197	Off Idle	80	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.25	15.04	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:3	32.72	2255	1.91	13.43	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.21	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:3	32.72	2256	1.91	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.27	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:3	32.72	2266	1.91	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.27	14.91	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:3	32.72	2263	1.91	13.42	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.22	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:3	32.72	2260	1.91	13.44	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.24	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:3	32.72	2255	1.91	13.44	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.2	14.77	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:4	32.72	2249	1.91	13.44	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.18	14.74	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:4	32.72	2249	1.91	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.22	14.73	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:4	32.72	2248	1.91	13.45	95	197	Off Idle	80	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.2	14.74	1	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:4	32.72	2248	1.91	13.46	95	197	Off Idle	80	0	2	132	944 Turbo	0.67	Rich	1	14.7	-7.2	14.76	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:4	32.72	2254	1.91	13.47	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.64	Rich	1	14.7	-7.22	14.77	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:4	32.72	2257	1.9	13.45	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.25	14.77	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:4	32.72	2257	1.9	13.45	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.21	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:5	32.72	2264	1.9	13.46	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.23	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:5	32.72	2268	1.9	13.45	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.25	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:5	32.72	2258	1.9	13.43	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.22	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:5	32.72	2261	1.9	13.45	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.24	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:5	32.72	2255	1.9	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.29	Lean	1	14.7	-7.22	14.85	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:5	34.08	2270	1.9	13.42	95	197	Off Idle	80	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.25	14.84	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:19:6	34.08	2270	1.9	13.43	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.22	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:6	34.08	2252	1.9	13.43	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.25	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:6	34.08	2248	1.9	13.42	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.25	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:6	34.08	2248	1.9	13.42	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.25	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:6	34.08	2242	1.9	13.43	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.25	14.88	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:6	34.08	2257	1.9	13.44	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.26	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:6	34.08	2258	1.9	13.45	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.28	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:7	34.08	2261	1.9	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.27	14.95	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:7	34.08	2272	1.9	13.41	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.25	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:7	34.08	2261	1.9	13.41	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.3	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:7	34.08	2260	1.9	13.4	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.3	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:7	34.08	2259	1.9	13.41	95	197	Off Idle	80	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.26	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:7	34.08	2252	1.9	13.41	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.27	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:8	34.08	2252	1.9	13.41	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.31	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:8	34.08	2252	1.9	13.43	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-7.27	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:8	34.08	2254	1.9	13.44	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.27	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:8	34.08	2254	1.9	13.45	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.32	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:8	34.08	2257	1.9	13.44	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.32	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:19:8	34.08	2250	1.9	13.45	95	197	Off Idle	80.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.32	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:9	32.72	2242	1.9	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.35	15.01	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:9	32.72	2248	1.9	13.43	95	197	Off Idle	80	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.34	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:9	32.72	2257	1.9	13.43	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.31	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:9	32.72	2262	1.9	13.45	95	197	Off Idle	80	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.32	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:9	32.72	2262	1.9	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.35	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:9	32.72	2266	1.9	13.43	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.32	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:19:9	32.72	2266	1.9	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.32	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:0	34.08	2282	1.9	13.45	95	197	Off Idle	80	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.34	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:0	34.08	2261	1.9	13.45	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.34	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:0	34.08	2261	1.9	13.46	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.32	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:0	34.08	2260	1.9	13.46	95	197	Off Idle	79.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.34	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:0	34.08	2242	1.9	13.44	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.36	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:0	34.08	2252	1.9	13.45	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.34	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:1	34.08	2261	1.9	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.33	14.9	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:1	34.08	2258	1.9	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.36	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:1	34.08	2279	1.9	13.41	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.31	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:1	34.08	2279	1.9	13.42	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.3	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:1	34.08	2262	1.9	13.43	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.34	15.05	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:1	34.08	2261	1.9	13.44	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.32	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:1	34.08	2261	1.9	13.44	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.3	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:2	34.08	2260	1.9	13.45	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.6	Rich	1	14.7	-7.33	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:2	34.08	2257	1.9	13.43	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.33	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:2	34.08	2261	1.9	13.43	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.31	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:2	34.08	2262	1.9	13.43	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.31	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:2	34.08	2262	1.9	13.42	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.28	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:2	34.08	2266	1.9	13.41	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.27	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:3	34.08	2269	1.9	13.42	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.24	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:3	32.72	2260	1.9	13.43	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.23	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:3	32.72	2268	1.9	13.45	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.25	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:3	32.72	2262	1.9	13.45	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.31	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:3	32.72	2262	1.9	13.44	95	197	Off Idle	79.5	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.31	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:3	32.72	2249	1.9	13.45	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.28	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:4	32.72	2260	1.9	13.45	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.3	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:4	32.72	2260	1.9	13.44	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.32	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:4	34.08	2280	1.9	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.28	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:4	34.08	2276	1.9	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.28	14.81	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:4	34.08	2270	1.9	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.32	14.79	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:4	34.08	2270	1.9	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.29	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:4	34.08	2270	1.9	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.27	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:20:5	34.08	2270	1.9	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.29	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:5	34.08	2270	1.9	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.31	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:5	34.08	2264	1.89	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.27	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:5	34.08	2263	1.89	13.46	95	197	Off Idle	79	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.29	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:5	34.08	2259	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.3	14.9	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:5	34.08	2259	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.29	14.93	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:6	34.08	2264	1.89	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.33	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:6	34.08	2269	1.89	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.35	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:6	34.08	2270	1.89	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.63	Lean	1	14.7	-7.3	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:6	34.08	2272	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.29	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:6	34.08	2271	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.34	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:6	34.08	2271	1.89	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.35	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:6	34.08	2265	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.33	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:7	34.08	2259	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.37	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:7	34.08	2258	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.36	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:7	34.08	2254	1.89	13.45	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.33	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:7	34.08	2254	1.89	13.45	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.3	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:7	34.08	2261	1.89	13.43	95	197	Off Idle	79.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.36	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:7	34.08	2260	1.89	13.43	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.31	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:8	34.08	2267	1.89	13.44	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.32	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:8	34.08	2267	1.89	13.44	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.33	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:8	34.08	2272	1.89	13.42	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.37	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:8	34.08	2273	1.89	13.43	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.44	Lean	1	14.7	-7.37	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:8	34.08	2274	1.89	13.43	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.38	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:8	34.08	2274	1.89	13.43	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.41	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:9	34.08	2275	1.89	13.42	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.44	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:9	34.08	2275	1.89	13.42	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.44	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:9	34.08	2272	1.89	13.43	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.42	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:9	34.08	2265	1.89	13.43	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.4	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:20:9	34.08	2264	1.89	13.44	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.38	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:9	34.08	2262	1.89	13.43	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.33	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:20:9	34.08	2258	1.89	13.45	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.29	14.85	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:0	34.08	2259	1.89	13.45	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.28	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:0	34.08	2262	1.89	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.3	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:0	34.08	2271	1.89	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.28	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:0	34.08	2275	1.89	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.32	14.91	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:0	34.08	2276	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.65	Rich	1	14.7	-7.36	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:0	34.08	2278	1.89	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.36	14.97	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:1	34.08	2276	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.71	Rich	1	14.7	-7.33	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:1	34.08	2271	1.89	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.34	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:1	34.08	2271	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.37	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:1	34.08	2266	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.36	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:1	34.08	2243	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.34	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:1	34.08	2253	1.89	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.36	15.03	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:1	34.08	2261	1.89	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.33	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:21:2	34.08	2253	1.89	13.46	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.3	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:21:2	34.08	2267	1.89	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.35	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:21:2	34.08	2268	1.89	13.45	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.36	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:21:2	34.08	2270	1.89	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.59	Rich	1	14.7	-7.28	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:21:2	34.08	2295	1.89	13.46	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.28	14.87	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:2	34.08	2295	1.89	13.46	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.29	14.85	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:3	34.08	2275	1.89	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.3	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:3	34.08	2273	1.89	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.28	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:3	34.08	2273	1.89	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.32	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:3	34.08	2275	1.89	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.36	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:3	34.08	2274	1.89	13.42	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.3	14.84	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:3	34.08	2275	1.89	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.3	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:4	34.08	2275	1.9	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.32	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:21:4	34.08	2271	1.9	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.34	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:4	34.08	2272	1.9	13.44	95	197	Off Idle	79	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.32	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:4	34.08	2271	1.9	13.46	95	197	Off Idle	79	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.33	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:4	34.08	2268	1.9	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.18	Lean	1	14.7	-7.33	14.92	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:4	34.08	2269	1.9	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.3	14.95	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:4	34.08	2270	1.9	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.26	14.99	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:5	34.08	2272	1.9	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.3	Lean	1	14.7	-7.25	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:5	34.08	2272	1.9	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.26	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:5	34.08	2272	1.91	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.24	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:5	34.08	2271	1.91	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.24	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:5	34.08	2268	1.91	13.43	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.52	Lean	1	14.7	-7.21	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:5	34.08	2270	1.91	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.2	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:6	34.08	2274	1.91	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.18	15.13	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:6	34.08	2274	1.91	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.16	15.12	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:6	34.08	2272	1.91	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.18	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:6	34.08	2274	1.91	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.18	15.05	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:6	34.08	2274	1.91	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.69	Rich	1	14.7	-7.19	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:6	34.08	2275	1.91	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.2	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:6	34.08	2275	1.91	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.22	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:7	34.08	2276	1.91	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.23	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:7	34.08	2267	1.91	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.24	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:7	34.08	2267	1.91	13.44	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.21	15.01	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:7	34.08	2267	1.91	13.44	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.19	15	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:7	34.08	2262	1.91	13.45	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.19	14.98	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:7	34.08	2274	1.91	13.44	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.18	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:8	34.08	2276	1.91	13.44	95	197	Off Idle	79	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.18	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:8	34.08	2281	1.92	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.17	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:8	34.08	2290	1.92	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.18	14.91	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:8	34.08	2282	1.92	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.21	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:8	34.08	2282	1.91	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.17	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:8	34.08	2280	1.91	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.16	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:9	34.08	2277	1.91	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.2	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:9	34.08	2277	1.91	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.21	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:9	34.08	2276	1.91	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.2	14.91	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:9	34.08	2276	1.91	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.22	14.94	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:9	34.08	2276	1.91	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.23	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:21:9	34.08	2276	1.91	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.27	Lean	1	14.7	-7.24	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:21:9	34.08	2277	1.91	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.28	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:0	34.08	2277	1.91	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.25	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:0	34.08	2278	1.91	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.25	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:0	34.08	2276	1.91	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.27	15.15	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:0	34.08	2275	1.91	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.6	Rich	1	14.7	-7.27	15.16	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:0	34.08	2275	1.91	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.28	15.16	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:0	34.08	2272	1.91	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.29	15.15	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:1	34.08	2272	1.91	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.3	15.15	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:1	34.08	2272	1.91	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.28	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:1	34.08	2271	1.91	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-7.27	15.13	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:1	34.08	2272	1.91	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.28	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:1	34.08	2272	1.91	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.29	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:22:1	34.08	2276	1.91	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.27	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:22:1	34.08	2276	1.91	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.3	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:22:2	34.08	2278	1.9	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.66	Lean	1	14.6	-7.33	14.97	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:22:2	34.08	2283	1.9	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.32	14.93	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:22:2	34.08	2286	1.9	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.36	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:25:22:2	34.08	2287	1.9	13.43	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.37	14.83	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:2	34.08	2288	1.9	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.39	Lean	1	14.7	-7.36	14.81	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:2	34.08	2288	1.9	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.35	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:3	34.08	2277	1.9	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.38	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:22:3	34.08	2277	1.9	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.39	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:3	34.08	2278	1.89	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.41	14.82	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:3	34.08	2278	1.89	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.46	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:3	34.08	2279	1.89	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.48	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:22:3	34.08	2279	1.89	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.52	14.81	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:22:4	34.08	2278	1.88	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.57	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:22:4	34.08	2280	1.88	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.59	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:22:4	34.08	2280	1.87	13.44	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.48	Rich	1	14.7	-7.62	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:22:4	34.08	2279	1.87	13.44	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.62	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:4	34.08	2278	1.86	13.44	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.64	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:4	34.08	2276	1.85	13.43	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:4	34.08	2279	1.85	13.41	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:5	34.08	2280	1.84	13.43	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:5	34.08	2280	1.83	13.43	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:5	34.08	2278	1.82	13.42	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.95	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:5	34.08	2278	1.82	13.43	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.99	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:5	34.08	2276	1.81	13.45	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.04	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:5	34.08	2276	1.8	13.45	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.09	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:6	34.08	2272	1.79	13.44	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.12	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:6	34.08	2272	1.78	13.44	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.14	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:6	34.08	2272	1.78	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.18	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:6	34.08	2273	1.77	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.21	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:6	34.08	2274	1.76	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.24	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:6	34.08	2274	1.76	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.24	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:6	34.08	2277	1.75	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.28	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:7	34.08	2276	1.75	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.31	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:7	34.08	2276	1.75	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.31	14.78	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:7	34.08	2277	1.75	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.3	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:7	34.08	2275	1.74	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.32	14.77	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:7	34.08	2275	1.74	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.35	14.78	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:7	34.08	2278	1.74	13.43	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.32	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:8	34.08	2278	1.74	13.44	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.35	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:8	34.08	2277	1.74	13.43	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.38	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:8	34.08	2277	1.74	13.43	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.35	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:8	34.08	2276	1.74	13.45	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.37	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:8	34.08	2275	1.74	13.44	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.37	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:22:8	34.08	2275	1.74	13.42	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.34	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:9	34.08	2276	1.74	13.44	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.35	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:9	34.08	2275	1.74	13.44	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.33	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:9	34.08	2277	1.74	13.43	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.38	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:9	34.08	2278	1.74	13.43	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.35	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:9	34.08	2278	1.74	13.43	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.35	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:9	34.08	2275	1.74	13.43	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.33	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:22:9	34.08	2276	1.74	13.44	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.35	15.18	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:0	34.08	2276	1.74	13.47	95	197	Off Idle	78.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.34	15.18	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:0	34.08	2259	1.74	13.45	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.36	15.18	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:0	34.08	2264	1.74	13.46	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.35	15.17	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:0	34.08	2265	1.74	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.36	15.2	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:0	34.08	2269	1.74	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.37	15.18	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:0	34.08	2272	1.74	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.35	15.16	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:1	34.08	2277	1.74	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.32	15.13	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:1	34.08	2278	1.74	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.33	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:1	34.08	2278	1.74	13.46	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.35	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:1	34.08	2275	1.74	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.36	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:1	34.08	2275	1.74	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.35	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:1	34.08	2267	1.74	13.46	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.38	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:1	34.08	2266	1.74	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.4	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:2	34.08	2267	1.74	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.4	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:23:2	34.08	2267	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.4	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:2	34.08	2271	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.38	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:2	34.08	2275	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.37	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:2	34.08	2274	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.32	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:2	34.08	2273	1.73	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.32	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:3	34.08	2281	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.34	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:3	34.08	2283	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.3	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:3	34.08	2284	1.73	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.28	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:3	34.08	2285	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.33	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:3	34.08	2282	1.73	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.37	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:3	34.08	2282	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.35	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:4	34.08	2272	1.73	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.38	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:4	34.08	2269	1.73	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.4	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:4	34.08	2269	1.73	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.36	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:4	34.08	2268	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.37	Rich	1	14.7	-8.38	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:4	34.08	2274	1.73	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.39	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:4	34.08	2277	1.73	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.36	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:4	34.08	2277	1.73	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.33	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:5	34.08	2276	1.73	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.34	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:5	34.08	2274	1.73	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.39	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:5	34.08	2274	1.73	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.37	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:5	34.08	2272	1.73	13.46	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.37	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:5	34.08	2274	1.73	13.46	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.38	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:5	34.08	2267	1.73	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.4	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:6	34.08	2267	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.41	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:6	34.08	2268	1.73	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.44	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:6	34.08	2270	1.72	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.49	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:6	34.08	2268	1.72	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.51	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:23:6	34.08	2269	1.72	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.54	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:6	34.08	2273	1.71	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.59	15.05	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:6	34.08	2273	1.71	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.61	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:7	34.08	2272	1.71	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.41	Rich	1	14.7	-8.64	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:7	34.08	2278	1.7	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.64	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:7	34.08	2279	1.69	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.69	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:7	34.08	2279	1.69	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.73	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:7	34.08	2280	1.69	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.72	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:7	34.08	2279	1.68	13.45	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.76	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:8	34.08	2276	1.67	13.44	95	197	Off Idle	78.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.82	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:8	34.08	2268	1.67	13.45	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.82	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:8	34.08	2269	1.66	13.44	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.84	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:23:8	34.08	2268	1.66	13.43	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.87	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:23:8	34.08	2261	1.65	13.43	95	197	Off Idle	78.4	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.84	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:23:8	34.08	2276	1.65	13.45	95	197	Off Idle	78.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.84	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:23:9	34.08	2278	1.65	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.56	Lean	1	14.7	-8.86	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:23:9	34.08	2278	1.64	13.41	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.88	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:23:9	34.08	2288	1.64	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.87	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:23:9	34.08	2280	1.64	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.9	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:23:9	34.08	2276	1.64	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.93	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:23:9	34.08	2266	1.64	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.94	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:23:9	34.08	2260	1.63	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.93	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:0	34.08	2256	1.63	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.94	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:0	34.08	2256	1.63	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.94	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:0	34.08	2260	1.63	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.9	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:24:0	34.08	2264	1.63	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.88	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:24:0	34.08	2270	1.63	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.94	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:24:0	34.08	2270	1.63	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.94	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:24:1	34.08	2276	1.62	13.45	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.97	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:1	34.08	2280	1.62	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:24:1	34.08	2284	1.62	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.99	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:1	34.08	2282	1.62	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.03	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:1	34.08	2277	1.62	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.05	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:1	34.08	2277	1.62	13.42	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.05	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:1	34.08	2267	1.61	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.09	Lean	1	14.7	-9.06	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:2	34.08	2256	1.61	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.1	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:2	34.08	2255	1.61	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.09	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:2	34.08	2255	1.61	13.44	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.09	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:2	34.08	2257	1.6	13.43	95	197	Off Idle	78.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.11	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:2	34.08	2258	1.6	13.44	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-9.07	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:2	34.08	2260	1.6	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.06	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:3	34.08	2272	1.6	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.12	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:3	34.08	2277	1.59	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.12	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:3	34.08	2284	1.59	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.11	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:3	34.08	2284	1.59	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.15	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:3	34.08	2280	1.59	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.16	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:3	34.08	2280	1.58	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.15	15.17	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:4	34.08	2271	1.58	13.46	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.16	15.19	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:4	34.08	2264	1.58	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.16	15.2	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:4	34.08	2256	1.58	13.46	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.18	15.2	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:4	34.08	2256	1.58	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.18	15.2	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:4	34.08	2246	1.58	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.16	15.18	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:4	34.08	2254	1.58	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.16	15.17	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:4	34.08	2255	1.57	13.44	95	197	Off Idle	79	0	2	132	944 Turbo	0.64	Rich	1	14.7	-9.13	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:5	34.08	2257	1.57	13.44	95	197	Off Idle	79	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.09	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:5	34.08	2261	1.57	13.45	95	197	Off Idle	79	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.09	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:5	34.08	2264	1.57	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.12	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:5	34.08	2266	1.57	13.42	95	197	Off Idle	79	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.14	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:5	34.08	2268	1.57	13.42	95	197	Off Idle	79	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.14	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:5	34.08	2265	1.57	13.42	95	197	Off Idle	79	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.14	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:6	34.08	2266	1.57	13.42	95	197	Off Idle	79	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.16	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:6	34.08	2268	1.57	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.17	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:6	34.08	2265	1.57	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.17	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:6	34.08	2263	1.57	13.44	95	197	Off Idle	79	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.14	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:6	34.08	2262	1.57	13.45	95	197	Off Idle	79	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.16	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:6	34.08	2260	1.57	13.44	95	197	Off Idle	79	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.18	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:6	34.08	2260	1.57	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.17	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:7	34.08	2260	1.57	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.18	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:7	34.08	2241	1.57	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.21	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:7	34.08	2249	1.56	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.19	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:7	34.08	2255	1.56	13.45	95	197	Off Idle	78.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.2	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:7	34.08	2271	1.56	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.21	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:7	34.08	2263	1.56	13.44	95	197	Off Idle	79	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.2	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:8	34.08	2263	1.56	13.42	95	197	Off Idle	79	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.22	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:8	34.08	2263	1.56	13.42	95	197	Off Idle	79	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.28	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:8	34.08	2259	1.56	13.4	95	197	Off Idle	79	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.27	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:8	34.08	2257	1.56	13.41	95	197	Off Idle	79	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.25	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:8	34.08	2257	1.56	13.42	95	197	Off Idle	79	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.25	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:8	34.08	2263	1.56	13.43	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.23	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:9	34.08	2265	1.56	13.45	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.24	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:9	34.08	2267	1.56	13.45	95	197	Off Idle	79.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.26	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:9	34.08	2267	1.55	13.45	95	196	Off Idle	79.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.28	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:9	34.08	2264	1.55	13.44	95	196	Off Idle	79	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.28	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:24:9	34.08	2261	1.55	13.44	95	196	Off Idle	79	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.27	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:9	34.08	2270	1.55	13.44	95	197	Off Idle	79	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.26	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:24:9	34.08	2259	1.55	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.24	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:0	34.08	2252	1.55	13.44	95	197	Off Idle	79	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.26	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:0	34.08	2252	1.55	13.43	95	197	Off Idle	79	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.25	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:25:0	34.08	2248	1.55	13.44	95	197	Off Idle	79.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.22	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:0	34.08	2244	1.55	13.44	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.22	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:0	34.08	2249	1.55	13.45	95	197	Off Idle	79.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.23	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:0	34.08	2249	1.55	13.44	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.25	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:1	34.08	2252	1.55	13.44	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.25	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:1	34.08	2234	1.55	13.45	95	196	Off Idle	79.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.26	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:1	34.08	2243	1.54	13.45	95	196	Off Idle	79.9	0	2	132	944 Turbo	0.4	Lean	1	14.7	-9.28	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:1	34.08	2255	1.54	13.44	95	196	Off Idle	80.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.27	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:1	34.08	2258	1.54	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.25	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:1	34.08	2285	1.54	13.44	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.26	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:1	34.08	2271	1.54	13.43	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.27	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:2	34.08	2272	1.54	13.42	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.29	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:2	34.08	2273	1.54	13.43	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.28	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:2	34.08	2265	1.53	13.41	95	196	Off Idle	80.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.3	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:2	34.08	2265	1.53	13.41	95	196	Off Idle	80.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.35	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:2	34.08	2256	1.53	13.42	95	196	Off Idle	80.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.32	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:2	34.08	2250	1.53	13.44	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.3	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:3	34.08	2250	1.53	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.31	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:3	34.08	2230	1.53	13.45	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.34	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:3	34.08	2248	1.53	13.45	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.31	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:3	34.08	2250	1.53	13.46	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.32	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:3	34.08	2250	1.53	13.45	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.5	Rich	1	14.7	-9.34	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:3	34.08	2254	1.53	13.44	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.56	Rich	1	14.7	-9.32	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:4	34.08	2255	1.53	13.45	95	197	Off Idle	79.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.3	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:4	34.08	2256	1.53	13.44	95	197	Off Idle	79.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.31	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:4	34.08	2254	1.53	13.43	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.31	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:4	34.08	2256	1.53	13.44	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.27	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:4	34.08	2253	1.54	13.45	95	197	Off Idle	79.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.28	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:4	34.08	2253	1.54	13.45	95	196	Off Idle	79.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.29	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:4	34.08	2250	1.54	13.43	95	196	Off Idle	79.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.29	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:5	34.08	2251	1.54	13.44	95	196	Off Idle	79.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.3	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:5	34.08	2249	1.54	13.46	95	196	Off Idle	79.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.31	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:5	34.08	2247	1.54	13.45	95	196	Off Idle	80	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.32	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:5	34.08	2248	1.54	13.45	95	196	Off Idle	80.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.29	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:5	34.08	2241	1.54	13.44	95	196	Off Idle	80.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.32	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:5	34.08	2241	1.54	13.44	95	196	Off Idle	80.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.31	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:6	34.08	2244	1.54	13.44	95	196	Off Idle	80.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.31	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:25:6	34.08	2246	1.54	13.44	95	196	Off Idle	80.3	0	2	132	944 Turbo	0.6	Rich	1	14.7	-9.3	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:6	34.08	2241	1.54	13.44	95	196	Off Idle	80.1	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.3	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:6	34.08	2271	1.54	13.46	95	196	Off Idle	79.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.31	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:6	34.08	2249	1.54	13.45	95	196	Off Idle	79.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.35	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:6	34.08	2249	1.54	13.43	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.35	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:6	34.08	2246	1.54	13.45	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.31	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:7	34.08	2260	1.54	13.45	95	196	Off Idle	80.2	0	2	132	944 Turbo	0.2	Lean	1	14.7	-9.31	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:7	34.08	2263	1.54	13.45	95	196	Off Idle	80.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.29	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:7	34.08	2263	1.54	13.46	95	196	Off Idle	80.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.29	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:7	34.08	2265	1.54	13.46	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.3	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:7	34.08	2268	1.54	13.45	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.31	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:7	34.08	2268	1.54	13.45	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.31	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:8	34.08	2264	1.54	13.44	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.33	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:8	34.08	2264	1.54	13.42	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.34	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:8	34.08	2268	1.54	13.43	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.32	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:8	34.08	2248	1.54	13.41	95	196	Off Idle	79.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.32	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:8	34.08	2240	1.54	13.41	95	196	Off Idle	79.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.28	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:8	34.08	2238	1.54	13.42	95	196	Off Idle	79.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.24	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:9	34.08	2213	1.54	13.43	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.24	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:9	34.08	2233	1.54	13.44	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.22	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:9	34.08	2234	1.54	13.45	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.22	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:25:9	34.08	2234	1.54	13.45	95	197	Off Idle	79.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.21	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:9	34.08	2239	1.54	13.46	95	197	Off Idle	79.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.2	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:9	34.08	2241	1.54	13.46	95	197	Off Idle	79.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.24	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:25:9	34.08	2249	1.54	13.45	95	197	Off Idle	80.1	0	2	132	944 Turbo	0.59	Rich	1	14.7	-9.22	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:0	34.08	2249	1.54	13.44	95	197	Off Idle	80.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.19	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:0	34.08	2262	1.54	13.45	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.22	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:0	34.08	2256	1.54	13.44	95	197	Off Idle	80.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.24	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:0	34.08	2256	1.54	13.44	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.25	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:0	34.08	2258	1.54	13.44	95	196	Off Idle	80.7	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.26	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:0	34.08	2239	1.54	13.44	95	196	Off Idle	80.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.29	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:1	34.08	2246	1.54	13.43	95	196	Off Idle	81	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.29	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:1	34.08	2245	1.54	13.45	95	197	Off Idle	81	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.29	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:1	34.08	2239	1.54	13.44	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.26	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:1	34.08	2236	1.54	13.45	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.26	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:1	34.08	2226	1.54	13.44	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.26	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:1	34.08	2225	1.54	13.44	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.25	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:1	34.08	2227	1.54	13.44	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.24	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:2	34.08	2226	1.54	13.43	95	196	Off Idle	80.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.23	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:2	34.08	2228	1.54	13.44	95	196	Off Idle	80.9	0	2	132	944 Turbo	0.66	Rich	1	14.7	-9.23	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:2	34.08	2231	1.54	13.45	95	196	Off Idle	80.9	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.24	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:2	34.08	2231	1.54	13.44	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.24	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:2	34.08	2228	1.54	13.45	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.24	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:2	34.08	2230	1.54	13.44	95	196	Off Idle	81	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.25	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:3	34.08	2231	1.54	13.44	95	196	Off Idle	81	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.24	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:3	34.08	2234	1.54	13.45	95	196	Off Idle	81	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.25	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:3	34.08	2240	1.54	13.44	95	196	Off Idle	81	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.27	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:3	34.08	2240	1.54	13.44	95	196	Off Idle	81.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.27	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:3	34.08	2246	1.54	13.42	95	196	Off Idle	81.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.29	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:3	34.08	2251	1.54	13.42	95	196	Off Idle	81.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.28	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:4	34.08	2253	1.54	13.42	95	196	Off Idle	81.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.27	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:4	34.08	2268	1.54	13.43	95	196	Off Idle	81.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.26	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:4	34.08	2260	1.54	13.44	95	196	Off Idle	81	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.26	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:4	34.08	2262	1.54	13.44	95	196	Off Idle	80.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.27	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:4	34.08	2261	1.54	13.45	95	196	Off Idle	80.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.3	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:4	34.08	2254	1.54	13.44	95	196	Off Idle	80.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.26	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:4	34.08	2243	1.54	13.44	95	196	Off Idle	80.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.25	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:5	34.08	2233	1.54	13.45	95	196	Off Idle	80.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.25	14.9	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:5	34.08	2233	1.54	13.46	95	196	Off Idle	80.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.22	14.95	1.02	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:5	34.08	2202	1.54	13.46	95	196	Off Idle	80.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.25	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:5	34.08	2215	1.54	13.46	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.25	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:5	34.08	2211	1.54	13.44	95	197	Off Idle	80.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.24	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:5	34.08	2211	1.54	13.44	95	197	Off Idle	80.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.21	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:6	34.08	2200	1.54	13.45	95	197	Off Idle	80.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.22	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:6	34.08	2217	1.54	13.44	95	196	Off Idle	80.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.2	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:6	34.08	2219	1.54	13.44	95	196	Off Idle	80.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.19	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:6	34.08	2225	1.54	13.44	95	196	Off Idle	81.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.19	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:6	34.08	2225	1.54	13.44	95	196	Off Idle	81.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.25	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:6	34.08	2234	1.54	13.42	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.25	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:6	34.08	2234	1.54	13.42	95	196	Off Idle	81.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.25	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:7	34.08	2241	1.53	13.44	95	196	Off Idle	81.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.25	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:7	34.08	2246	1.53	13.45	95	196	Off Idle	81.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.28	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:7	34.08	2246	1.53	13.44	95	196	Off Idle	81.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.3	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:7	34.08	2247	1.53	13.44	95	196	Off Idle	81.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.31	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:7	34.08	2248	1.53	13.45	95	196	Off Idle	81.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.3	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:7	34.08	2248	1.53	13.45	95	197	Off Idle	81.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.32	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:8	34.08	2248	1.53	13.44	95	197	Off Idle	81.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.32	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:8	34.08	2249	1.53	13.44	95	197	Off Idle	81.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.29	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:8	34.08	2250	1.53	13.43	95	196	Off Idle	81.1	0	2	132	944 Turbo	0.35	Rich	1	14.7	-9.31	14.96	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:26:8	34.08	2260	1.53	13.41	95	196	Off Idle	81.1	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.33	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:8	34.08	2249	1.53	13.42	95	196	Off Idle	81	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.3	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:26:8	34.08	2248	1.53	13.43	95	196	Off Idle	80.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.31	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:9	34.08	2234	1.53	13.45	95	196	Off Idle	80.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.32	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:9	34.08	2209	1.53	13.43	95	196	Off Idle	80.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.31	14.85	1.01	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:9	34.08	2209	1.53	13.44	95	196	Off Idle	80.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.28	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:9	34.08	2220	1.53	13.45	95	196	Off Idle	80.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.3	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:9	34.08	2218	1.53	13.45	95	196	Off Idle	81	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.25	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:9	34.08	2218	1.53	13.45	95	196	Off Idle	81.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.25	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:26:9	34.08	2205	1.53	13.45	95	196	Off Idle	81.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.26	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:0	34.08	2224	1.53	13.45	95	196	Off Idle	81.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.25	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:0	34.08	2233	1.53	13.44	95	196	Off Idle	81.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.27	14.87	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:0	34.08	2234	1.53	13.44	95	197	Off Idle	81.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.25	14.91	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:0	34.08	2246	1.53	13.44	95	197	Off Idle	81.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.21	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:0	34.08	2240	1.53	13.45	95	197	Off Idle	81.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.22	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:0	34.08	2240	1.53	13.44	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.25	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:1	34.08	2239	1.53	13.44	95	196	Off Idle	81.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.25	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:1	34.08	2231	1.53	13.45	95	196	Off Idle	81.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.25	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:1	34.08	2229	1.53	13.45	95	196	Off Idle	81.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.27	15.15	1.03	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:1	34.08	2227	1.53	13.45	95	196	Off Idle	81.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.26	15.18	1.03	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:1	34.08	2225	1.53	13.46	95	196	Off Idle	81.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.23	15.21	1.04	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:1	34.08	2225	1.53	13.45	95	196	Off Idle	81.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.27	15.24	1.04	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:1	34.08	2220	1.53	13.43	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.29	15.25	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:2	34.08	2229	1.53	13.42	95	196	Off Idle	81.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.28	15.26	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:2	34.08	2230	1.53	13.42	95	196	Off Idle	81.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.29	15.25	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:2	34.08	2230	1.53	13.42	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.29	15.24	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:2	34.08	2228	1.53	13.43	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.28	15.24	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:2	34.08	2229	1.53	13.43	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.29	15.22	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:2	34.08	2229	1.53	13.43	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.27	15.2	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:3	34.08	2230	1.53	13.45	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.27	15.15	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:3	34.08	2224	1.52	13.45	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.25	15.15	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:3	34.08	2224	1.52	13.45	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.25	15.15	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:3	34.08	2224	1.52	13.45	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.25	15.14	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:3	34.08	2223	1.52	13.45	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.27	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:3	34.08	2223	1.52	13.44	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.25	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:4	34.08	2218	1.52	13.44	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.29	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:4	34.08	2227	1.52	13.45	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.27	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:4	34.08	2227	1.52	13.45	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.29	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:4	34.08	2236	1.52	13.44	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.29	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:4	34.08	2235	1.52	13.44	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.31	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:4	34.08	2235	1.52	13.44	95	196	Off Idle	81.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.26	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:4	34.08	2237	1.52	13.45	95	196	Off Idle	81.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.25	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:5	34.08	2236	1.52	13.46	95	196	Off Idle	81.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.25	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:5	34.08	2231	1.52	13.46	95	196	Off Idle	81.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.25	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:5	34.08	2231	1.52	13.46	95	196	Off Idle	81.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.25	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:5	34.08	2226	1.52	13.45	95	196	Off Idle	81.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.27	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:5	34.08	2223	1.52	13.44	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.28	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:5	34.08	2220	1.52	13.44	95	196	Off Idle	81.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.25	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:6	34.08	2214	1.52	13.44	95	196	Off Idle	81.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.25	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:6	34.08	2214	1.52	13.43	95	196	Off Idle	81.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.31	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:6	34.08	2212	1.52	13.44	95	196	Off Idle	81.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.32	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:6	34.08	2196	1.51	13.45	95	196	Off Idle	82	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.33	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:6	34.08	2217	1.51	13.45	95	196	Off Idle	82.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.36	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:27:6	34.08	2218	1.51	13.46	95	196	Off Idle	82.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.39	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:6	34.08	2219	1.5	13.45	95	196	Off Idle	82.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.42	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:7	34.08	2238	1.5	13.45	95	196	Off Idle	82.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.41	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:7	34.08	2238	1.5	13.45	95	196	Off Idle	82.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.43	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:7	34.08	2222	1.5	13.44	95	196	Off Idle	82.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.44	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:27:7	34.08	2222	1.49	13.46	95	196	Off Idle	82.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.42	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:7	34.08	2221	1.49	13.45	95	196	Off Idle	82.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.44	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:27:7	34.08	2220	1.49	13.45	95	196	Off Idle	82.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.49	15.12	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:8	34.08	2221	1.48	13.43	95	196	Off Idle	82.4	0	2	132	944 Turbo	0.7	Lean	1	14.6	-9.52	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:8	34.08	2221	1.48	13.43	95	196	Off Idle	82.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.54	15.16	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:8	34.08	2221	1.47	13.43	95	196	Off Idle	82.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.55	15.17	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:8	34.08	2208	1.46	13.44	95	196	Off Idle	82.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.52	15.16	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:8	34.08	2208	1.46	13.45	95	196	Off Idle	82.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.53	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:8	34.08	2194	1.46	13.45	95	196	Off Idle	82.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.55	15.14	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:9	34.08	2194	1.45	13.44	95	196	Off Idle	82.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.55	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:9	34.08	2205	1.45	13.43	95	196	Off Idle	82.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.55	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:9	34.08	2207	1.45	13.43	95	196	Off Idle	82	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.59	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:9	34.08	2208	1.44	13.43	95	196	Off Idle	82	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.6	15.08	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:9	34.08	2213	1.44	13.45	95	196	Off Idle	82.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.62	15.05	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:9	34.08	2205	1.44	13.45	95	196	Off Idle	82.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.65	15.04	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:27:9	34.08	2205	1.43	13.45	95	196	Off Idle	82.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.66	15.01	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:0	34.08	2210	1.43	13.45	95	196	Off Idle	82.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.66	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:0	34.08	2197	1.43	13.44	95	196	Off Idle	82.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.67	14.97	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:0	34.08	2206	1.42	13.44	95	196	Off Idle	82.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.65	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:0	34.08	2217	1.42	13.45	95	196	Off Idle	82.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.64	14.92	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:0	34.08	2212	1.42	13.44	95	196	Off Idle	82.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.65	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:0	34.08	2212	1.42	13.43	95	196	Off Idle	82.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.66	14.85	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:1	34.08	2222	1.41	13.44	95	196	Off Idle	82.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.65	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:1	34.08	2214	1.41	13.45	95	196	Off Idle	82.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.65	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:1	34.08	2212	1.41	13.44	95	196	Off Idle	82.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.69	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:1	34.08	2213	1.41	13.43	95	196	Off Idle	82.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.68	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:1	34.08	2199	1.41	13.43	95	196	Off Idle	82.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.66	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:1	34.08	2213	1.41	13.43	95	196	Off Idle	82.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.67	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:1	34.08	2213	1.4	13.43	95	196	Off Idle	82.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.67	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:2	34.08	2218	1.4	13.43	95	196	Off Idle	82.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.68	14.82	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:2	34.08	2218	1.4	13.43	95	196	Off Idle	82.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.7	14.84	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:2	34.08	2218	1.4	13.44	95	196	Off Idle	82.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.71	14.87	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:2	34.08	2218	1.4	13.45	95	196	Off Idle	82.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.76	14.89	1.01	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:2	34.08	2220	1.4	13.44	95	196	Off Idle	82.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.78	14.92	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:2	34.08	2221	1.39	13.44	95	196	Off Idle	82.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.79	14.95	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:3	34.08	2221	1.39	13.45	95	196	Off Idle	82.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.79	14.98	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:3	34.08	2221	1.39	13.45	95	196	Off Idle	82.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.82	15.02	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:3	34.08	2221	1.38	13.46	95	196	Off Idle	82	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.86	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:3	34.08	2226	1.38	13.45	95	196	Off Idle	82	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.85	15.08	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:28:3	34.08	2215	1.38	13.45	95	196	Off Idle	81.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.87	15.09	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:28:3	34.08	2215	1.37	13.46	95	196	Off Idle	81.7	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.93	15.09	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:28:4	34.08	2215	1.36	13.44	95	196	Off Idle	81.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.98	15.1	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:28:4	34.08	2196	1.35	13.43	95	196	Off Idle	81.7	0	2	132	944 Turbo	0.5	Lean	1	14.6	-10.03	15.1	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:28:4	34.08	2207	1.32	13.43	95	196	Full Load	82	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.09	15.09	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:28:4	34.08	2202	1.3	13.43	95	196	Idle	82.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.15	15.09	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:28:4	34.08	2202	1.27	13.43	95	196	Idle	82.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.24	15.08	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:28:4	34.08	2198	1.25	13.45	95	196	Idle	82.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.35	15.08	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:28:4	34.08	2182	1.23	13.45	95	196	Idle	82.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.42	15.07	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:28:5	34.08	2169	1.21	13.45	95	196	Idle	82.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.51	15.07	1.03	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:28:5	34.08	2169	1.19	13.45	95	196	Idle	80.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.58	15.08	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:28:5	34.08	2148	1.17	13.44	95	196	Idle	78.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.6	15.06	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:28:5	34.08	2132	1.16	13.44	95	196	Idle	75.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.61	15.05	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:28:5	34.08	2133	1.14	13.44	95	196	Idle	72.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.51	15.02	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:28:5	34.08	2138	1.14	13.45	95	196	Idle	69.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.5	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:28:6	31.36	2139	1.15	13.46	95	196	Idle	66.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.3	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:28:6	31.36	2177	1.17	13.47	95	196	Idle	63.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.17	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:6	25.9	2177	1.19	13.48	95	196	Idle	59.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.03	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:28:6	25.9	2205	1.21	13.46	95	196	Idle	59.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.87	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:28:6	20.45	2220	1.22	13.46	95	196	Idle	59.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.77	15	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:6	17.72	2240	1.24	13.45	95	196	Idle	59.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.7	15.01	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:6	17.72	2299	1.24	13.44	95	196	Idle	59.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.66	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:7	17.72	2258	1.23	13.46	95	196	Idle	59.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.7	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:7	17.72	2250	1.21	13.46	95	196	Idle	59.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.84	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:7	17.72	2214	1.21	13.44	95	196	Idle	61.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.07	14.94	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:7	17.72	2187	1.22	13.43	95	196	Idle	63.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-10.13	14.92	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:7	17.72	2153	1.23	13.42	95	196	Idle	65.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.23	14.93	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:7	17.72	2153	1.24	13.42	95	196	Idle	68.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.32	14.96	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:8	17.72	2118	1.24	13.41	95	196	Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.34	15	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:8	17.72	2120	1.24	13.42	95	196	Idle	75.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.38	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:8	17.72	2103	1.23	13.41	95	196	Idle	78.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.39	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:8	17.72	2103	1.23	13.42	95	196	Idle	81.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.4	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:8	17.72	2146	1.23	13.43	95	196	Idle	81.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.42	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:8	17.72	2180	1.22	13.44	95	196	Idle	80.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.44	15.18	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:9	17.72	2192	1.19	13.47	95	196	Idle	80.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.47	15.23	1.04	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:9	17.72	2234	1.16	13.47	95	196	Idle	81	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.52	15.29	1.04	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:9	17.72	2228	1.12	13.46	95	196	Idle	81	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.55	15.34	1.05	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:9	17.72	2228	1.09	13.44	95	196	Idle	81	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.53	15.42	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:9	17.72	2226	1.06	13.45	95	196	Idle	81	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.54	15.52	1.06	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:9	17.72	2200	1.03	13.45	95	196	Idle	80.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.52	15.67	1.07	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:28:9	17.72	2192	1.04	13.44	95	196	Idle	80.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.55	15.73	1.07	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:0	17.72	2172	1.05	13.46	95	196	Idle	80.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.54	15.85	1.08	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:0	17.72	2142	1.06	13.45	95	196	Idle	81	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.56	15.96	1.09	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:0	17.72	2145	1.06	13.44	95	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	16.13	1.1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:0	17.72	2145	1.05	13.44	95	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	16.23	1.11	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:0	17.72	2144	1.04	13.45	95	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	16.35	1.11	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:0	17.72	2153	1.03	13.46	95	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	16.45	1.12	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:1	17.72	2158	1.03	13.45	95	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	16.54	1.13	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:1	17.72	2177	1.03	13.44	95	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	16.65	1.13	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:1	17.72	2188	1.04	13.44	95	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	16.78	1.14	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:1	17.72	2192	1.04	13.43	95	196	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	16.91	1.15	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:1	17.72	2198	1.04	13.43	95	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	17.08	1.16	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:1	17.72	2196	1.04	13.43	95	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	17.43	1.19	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:1	17.72	2190	1.03	13.43	95	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	17.74	1.21	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:2	17.72	2186	1.03	13.43	95	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	18.07	1.23	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:2	17.72	2175	1.03	13.43	95	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	18.43	1.26	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:2	17.72	2168	1.03	13.45	95	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	18.75	1.28	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:2	17.72	2156	1.03	13.46	95	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	19.21	1.31	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:2	17.72	2154	1.03	13.46	95	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	19.49	1.33	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:2	17.72	2137	1.03	13.45	95	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	19.74	1.34	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:3	17.72	2156	1.03	13.44	95	196	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	19.95	1.36	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:3	17.72	2156	1.03	13.44	95	196	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.11	1.37	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:3	17.72	2170	1.03	13.45	95	196	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:3	17.72	2167	1.03	13.45	95	196	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:3	17.72	2167	1.03	13.45	95	196	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:3	17.72	2170	1.03	13.45	95	196	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:4	17.72	2169	1.03	13.45	95	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:4	17.72	2168	1.03	13.45	95	196	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:4	17.72	2163	1.03	13.45	95	196	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:4	17.72	2154	1.03	13.43	95	196	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:4	17.72	2154	1.02	13.43	95	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:4	17.72	2148	1.02	13.43	95	196	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:4	17.72	2145	1.02	13.42	95	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:5	17.72	2145	1.02	13.43	95	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:5	17.72	2144	1.02	13.42	95	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:5	17.72	2145	1.02	13.43	95	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:5	17.72	2147	1.02	13.44	95	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:29:5	17.72	2148	1.02	13.46	95	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:5	17.72	2144	1.01	13.48	95	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:6	17.72	2171	1.01	13.45	95	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:6	17.72	2171	1.01	13.44	95	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:6	17.72	2154	1.01	13.44	95	196	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:6	17.72	2152	1.01	13.44	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:6	17.72	2149	1.01	13.45	95	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:6	17.72	2149	1.01	13.45	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:6	17.72	2146	1.01	13.45	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:7	17.72	2144	1.01	13.45	95	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:7	17.72	2144	1.01	13.45	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:7	17.72	2142	1.01	13.45	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:7	17.72	2144	1.01	13.45	95	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.19	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:7	17.72	2144	1.01	13.46	95	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:7	17.72	2144	1.01	13.47	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:8	17.72	2138	1.01	13.47	95	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:8	17.72	2144	1.01	13.47	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:8	17.72	2145	1.01	13.47	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:8	17.72	2152	1.01	13.46	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:8	17.72	2141	1.01	13.45	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:8	17.72	2138	1.01	13.44	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:9	17.72	2136	1.01	13.44	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:9	17.72	2122	1.01	13.45	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:9	17.72	2127	1	13.45	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:9	17.72	2127	1	13.45	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:9	17.72	2134	1	13.45	95	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:9	17.72	2126	1	13.44	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:29:9	17.72	2110	1	13.44	95	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:0	17.72	2118	1	13.44	95	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:0	17.72	2127	1	13.45	95	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:0	17.72	2129	1	13.46	95	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:0	17.72	2129	1	13.46	95	196	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:0	17.72	2129	1	13.44	95	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:0	17.72	2146	1	13.43	95	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:1	17.72	2146	1	13.43	95	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:1	17.72	2129	1	13.42	95	196	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:1	17.72	2112	1	13.41	95	196	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:1	17.72	2120	1.01	13.42	95	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:1	17.72	2128	1.01	13.43	95	196	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:1	17.72	2128	1.01	13.43	95	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:1	17.72	2144	1.01	13.45	95	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:2	17.72	2136	1.01	13.45	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:2	17.72	2127	1.01	13.45	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:2	17.72	2118	1.01	13.44	95	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:2	17.72	2125	1.01	13.44	95	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:2	17.72	2125	1.01	13.44	95	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:2	17.72	2124	1.01	13.44	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:3	17.72	2120	1.01	13.45	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:3	17.72	2118	1.01	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:3	17.72	2118	1.01	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:3	17.72	2116	1.01	13.47	95	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:3	17.72	2113	1.01	13.48	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:3	17.72	2111	1	13.48	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:4	17.72	2110	1	13.48	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:4	17.72	2108	1	13.49	95	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:4	17.72	2107	1	13.47	95	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.67	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:4	17.72	2107	1	13.46	95	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:4	17.72	2106	1	13.44	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:30:4	17.72	2104	1	13.43	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:4	17.72	2102	1	13.41	95	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:5	17.72	2102	1	13.42	95	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:5	17.72	2101	1	13.42	95	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:5	17.72	2100	1	13.43	95	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:5	17.72	2100	1	13.43	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:5	17.72	2100	1	13.43	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:5	17.72	2100	1	13.42	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:6	17.72	2100	1	13.42	95	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:6	17.72	2100	1	13.43	95	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:6	17.72	2102	1	13.42	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.19	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:6	17.72	2100	1	13.42	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.19	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:6	17.72	2100	1	13.43	95	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:6	17.72	2099	1	13.43	95	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:6	17.72	2096	1	13.43	95	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:7	17.72	2096	1	13.45	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:7	17.72	2096	1	13.45	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:7	17.72	2096	1	13.44	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:7	17.72	2096	1	13.43	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:7	17.72	2096	1	13.43	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:7	17.72	2096	1	13.41	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:8	17.72	2098	1	13.41	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:8	17.72	2098	1	13.42	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:8	17.72	2100	1	13.43	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:8	17.72	2100	1	13.43	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:8	17.72	2100	1	13.44	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:8	17.72	2098	1	13.45	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:9	17.72	2097	1	13.46	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:9	17.72	2094	1	13.45	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:9	17.72	2093	1	13.45	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:9	17.72	2092	1	13.44	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:9	17.72	2089	1	13.43	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:9	17.72	2087	1	13.41	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:30:9	17.72	2085	1	13.41	95	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:0	17.72	2085	1	13.42	95	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:0	17.72	2084	1	13.42	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:0	17.72	2085	1	13.43	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:0	17.72	2086	1	13.46	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:0	17.72	2086	1	13.44	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:0	17.72	2086	1	13.44	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:1	17.72	2086	1	13.43	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:1	17.72	2086	1	13.43	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:1	17.72	2086	1	13.44	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:1	17.72	2086	1	13.45	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:1	17.72	2082	1	13.43	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:1	17.72	2080	1	13.44	95	196	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:1	17.72	2080	1	13.41	95	196	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:2	17.72	2076	1	13.41	95	196	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:2	17.72	2075	1	13.41	95	196	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:2	17.72	2075	1	13.41	95	196	Idle	85	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:2	17.72	2074	1	13.43	95	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:2	17.72	2075	1	13.45	95	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:2	17.72	2074	1	13.46	95	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:3	17.72	2074	1	13.46	95	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:3	17.72	2073	1	13.46	95	196	Idle	85.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:3	17.72	2072	1	13.47	95	196	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:3	17.72	2071	1	13.47	95	196	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:3	17.72	2071	1	13.47	95	196	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.19	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:31:3	17.72	2070	1	13.47	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:4	17.72	2067	0.99	13.47	95	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	19.95	1.36	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:4	17.72	2064	0.99	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	19.95	1.36	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:4	17.72	2064	0.99	13.46	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	19.95	1.36	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:4	17.72	2063	0.99	13.46	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	19.96	1.36	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:4	17.72	2047	0.99	13.47	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	19.96	1.36	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:4	17.72	2047	0.99	13.47	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	19.96	1.36	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:4	17.72	2064	0.99	13.46	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	19.97	1.36	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:5	17.72	2063	0.99	13.45	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	19.97	1.36	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:5	17.72	2065	0.99	13.44	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	19.98	1.36	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:5	17.72	2065	0.99	13.44	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:5	17.72	2065	0.99	13.43	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:5	17.72	2065	0.99	13.42	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:5	17.72	2064	0.99	13.42	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:6	17.72	2064	0.99	13.42	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:6	17.72	2064	0.99	13.42	95	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:6	17.72	2062	1	13.43	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:6	17.72	2062	1	13.44	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:6	17.72	2075	1	13.45	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:6	17.72	2057	1	13.46	95	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:6	17.72	2057	1	13.47	95	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:7	17.72	2054	1	13.47	95	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:7	17.72	2038	1	13.46	95	196	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:7	17.72	2053	1	13.45	95	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:7	17.72	2052	1	13.43	95	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:7	17.72	2051	1	13.42	95	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:7	17.72	2066	1	13.41	95	196	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:8	17.72	2058	1	13.42	95	196	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:8	17.72	2049	1	13.43	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:8	17.72	2048	1	13.44	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:8	17.72	2048	1	13.45	95	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:8	17.72	2052	1	13.46	95	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:8	17.72	2052	1	13.47	95	196	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:9	17.72	2036	1	13.46	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:9	17.72	2043	1	13.46	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:9	17.72	2043	1	13.47	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:9	17.72	2042	1	13.47	95	196	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:9	17.72	2042	1	13.47	95	196	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:9	17.72	2042	1	13.47	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:31:9	17.72	2039	1	13.46	95	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:0	17.72	2039	1	13.46	95	196	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:0	17.72	2039	1	13.46	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.19	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:0	17.72	2039	1	13.46	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:0	17.72	2037	1	13.46	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:0	17.72	2035	1	13.46	95	196	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:0	17.72	2035	1	13.46	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:1	17.72	2034	1	13.45	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:1	17.72	2033	1	13.45	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:1	17.72	2032	1	13.44	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:1	17.72	2032	1	13.44	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:1	17.72	2033	1	13.44	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:1	17.72	2033	1	13.44	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:1	17.72	2032	1	13.44	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:2	17.72	2033	1	13.44	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:2	17.72	2033	1	13.45	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:2	17.72	2032	1	13.45	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:2	17.72	2032	1	13.44	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:2	17.72	2031	1	13.43	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:32:2	17.72	2028	1	13.42	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:3	17.72	2024	1	13.41	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:3	17.72	2024	0.99	13.4	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:3	17.72	2021	0.99	13.39	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:3	17.72	2020	0.99	13.39	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:3	17.72	2020	0.99	13.4	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:3	17.72	2020	0.99	13.41	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:4	17.72	2021	0.99	13.42	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:4	17.72	2023	0.99	13.43	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:4	17.72	2025	0.99	13.44	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:4	17.72	2028	0.99	13.44	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:4	17.72	2028	0.99	13.45	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:4	17.72	2027	0.99	13.45	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:4	17.72	2026	0.99	13.45	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:5	17.72	2026	0.99	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:5	17.72	2022	0.99	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:5	17.72	2018	0.99	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:5	17.72	2018	0.99	13.47	95	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:5	17.72	2014	0.99	13.47	95	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:5	17.72	2010	0.99	13.47	95	196	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:6	17.72	2010	0.99	13.47	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:6	17.72	2007	0.99	13.47	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:6	17.72	2006	0.99	13.47	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:6	17.72	2006	0.99	13.47	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:6	17.72	2008	0.99	13.47	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:6	17.72	2008	0.99	13.47	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:6	17.72	2008	0.99	13.47	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:7	17.72	2006	0.99	13.46	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:7	17.72	2005	0.99	13.45	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:7	17.72	2005	0.99	13.44	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:7	17.72	2006	0.99	13.42	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:7	17.72	2006	0.99	13.41	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:7	17.72	2005	0.99	13.41	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:8	17.72	2005	0.99	13.4	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:8	17.72	2004	0.99	13.4	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:8	17.72	2005	0.99	13.41	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:8	17.72	2005	0.99	13.41	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:8	17.72	2005	1	13.41	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:8	17.72	2005	1	13.41	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:9	17.72	2000	1	13.41	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:9	17.72	2000	1	13.41	95	196	Idle	85.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.48	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:9	17.72	1999	1	13.41	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:9	17.72	1998	1	13.42	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:9	17.72	1995	1	13.43	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:9	17.72	1993	1	13.43	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:32:9	17.72	1993	1	13.45	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:0	17.72	1992	1	13.45	95	196	Idle	85.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:0	17.72	1989	1	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:0	17.72	1989	1	13.47	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:0	17.72	1981	1	13.47	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:0	17.72	1987	1	13.47	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:0	17.72	1987	1	13.47	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:1	17.72	1995	1	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:1	17.72	1986	1	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:1	17.72	1987	0.99	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:1	17.72	1988	0.99	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:1	17.72	1989	0.99	13.46	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:1	17.72	1989	0.99	13.46	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:33:1	17.72	1989	0.99	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:2	17.72	1990	0.99	13.45	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:2	17.72	1988	0.99	13.45	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:2	17.72	1988	0.99	13.44	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:2	17.72	1986	0.99	13.44	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:2	17.72	1984	0.99	13.44	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:2	17.72	1982	0.99	13.46	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:3	17.72	1982	0.99	13.46	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:3	17.72	1980	0.99	13.46	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:3	17.72	1981	0.99	13.46	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:3	17.72	1981	0.99	13.46	95	196	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:3	17.72	1979	0.99	13.46	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:3	17.72	1980	0.99	13.45	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:4	17.72	1972	0.99	13.44	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:4	17.72	1978	0.99	13.43	95	196	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:4	17.72	1993	0.99	13.42	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:4	17.72	1986	0.99	13.41	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:4	17.72	1977	0.99	13.41	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:4	17.72	1967	0.99	13.41	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:4	17.72	1988	0.99	13.41	95	196	Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:5	17.72	1988	0.99	13.42	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:5	17.72	1962	0.99	13.42	95	196	Full Load	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:5	17.72	1966	0.99	13.43	95	196	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:5	17.72	1966	0.99	13.45	95	196	Off Idle	85.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:5	17.72	1918	1	13.45	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:33:5	9.54	1869	1.01	13.46	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:33:6	9.54	1925	1.01	13.47	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.46	20.24	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:33:6	9.54	1982	1.02	13.47	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.44	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:6	12.27	1980	1.02	13.48	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:6	14.99	1978	1.03	13.48	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.35	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:6	14.99	1978	1.03	13.48	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:6	17.72	1980	1.04	13.45	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:6	17.72	1981	1.04	13.43	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:7	20.45	1979	1.05	13.42	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:7	20.45	1980	1.05	13.42	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:7	23.18	1980	1.06	13.41	95	196	Off Idle	85.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:7	23.18	1980	1.06	13.41	95	196	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:7	25.9	1979	1.07	13.41	95	196	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:7	25.9	1980	1.07	13.41	95	196	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:8	28.63	1978	1.07	13.41	95	196	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:8	28.63	1978	1.07	13.41	95	196	Off Idle	85.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:8	31.36	1980	1.07	13.41	95	196	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:8	31.36	1978	1.07	13.41	95	196	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:8	32.72	1963	1.06	13.41	95	196	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:8	32.72	1963	1.06	13.41	95	196	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:9	32.72	1954	1.06	13.41	95	196	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:9	32.72	1949	1.05	13.42	95	196	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:9	32.72	1949	1.05	13.43	95	196	Full Load	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:9	32.72	1944	1.05	13.43	95	196	Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:9	32.72	1944	1.04	13.45	95	196	Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:9	32.72	1941	1.03	13.45	95	196	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:33:9	32.72	1941	1.03	13.47	95	196	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:34:0	32.72	1933	1.03	13.46	95	196	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:34:0	29.99	1925	1.02	13.46	95	196	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:34:0	29.99	1925	1.02	13.44	95	196	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:34:0	24.54	1932	1.02	13.43	95	196	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:34:0	19.09	1930	1.02	13.41	95	196	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:34:0	19.09	1930	1.02	13.41	95	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:34:1	17.72	1944	1.02	13.41	95	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:1	17.72	1942	1.02	13.41	95	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:1	17.72	1936	1.02	13.41	95	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:1	17.72	1934	1.02	13.41	95	196	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:1	17.72	1929	1.02	13.41	95	196	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:1	17.72	1927	1.02	13.41	95	196	Idle	83.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:1	17.72	1928	1.02	13.43	95	196	Idle	83.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:2	17.72	1930	1.02	13.44	95	196	Idle	83.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:2	17.72	1933	1.02	13.46	95	196	Idle	83.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:2	17.72	1933	1.02	13.47	95	196	Idle	83.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:2	17.72	1938	1.02	13.48	95	196	Idle	84.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:2	17.72	1942	1.02	13.48	95	196	Idle	84.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:2	17.72	1941	1.02	13.47	95	196	Idle	84.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:3	17.72	1937	1.02	13.47	95	196	Idle	84.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.49	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:3	17.72	1916	1.02	13.46	95	196	Idle	84.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:3	17.72	1897	1.02	13.45	95	196	Idle	84.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.45	20.21	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:3	17.72	1886	1.02	13.43	95	196	Idle	84.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.44	20.2	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:3	17.72	1852	1.02	13.43	95	196	Idle	84.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.44	20.2	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:3	17.72	1817	1.02	13.43	95	196	Idle	84.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:4	17.72	1808	1.02	13.43	95	196	Idle	84.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:4	17.72	1797	1.01	13.42	95	196	Idle	84	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:4	17.72	1763	1.01	13.43	95	196	Idle	83.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:4	17.72	1741	1.01	13.44	95	196	Idle	83	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:4	17.72	1741	1.01	13.43	95	196	Idle	83	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.3	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:4	17.72	1718	1.02	13.43	95	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:4	17.72	1684	1.02	13.44	95	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.2	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:5	17.72	1672	1.02	13.44	95	196	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.2	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:5	17.72	1654	1.03	13.43	95	196	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:5	17.72	1623	1.03	13.43	95	196	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:5	17.72	1600	1.04	13.41	95	196	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:5	17.72	1600	1.04	13.42	95	196	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:5	17.72	1575	1.05	13.42	95	196	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:6	17.72	1551	1.06	13.43	95	196	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:6	17.72	1538	1.07	13.43	95	196	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:6	17.72	1508	1.09	13.43	95	196	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.23	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:6	17.72	1476	1.1	13.44	95	196	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.23	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:6	17.72	1450	1.11	13.44	95	196	Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.38	20.23	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:6	17.72	1450	1.12	13.44	95	196	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.35	20.23	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:6	17.72	1424	1.14	13.43	95	196	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.17	20.22	1.38	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:7	17.72	1398	1.15	13.44	95	196	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.1	20.22	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:7	19.09	1398	1.17	13.43	95	196	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	20.22	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:7	19.09	1372	1.18	13.43	95	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.85	20.22	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:7	19.09	1345	1.2	13.42	95	196	Idle	68.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.74	20.22	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:7	19.09	1345	1.21	13.44	95	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.69	20.22	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:34:7	19.09	1308	1.21	13.42	95	196	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.56	20.22	1.38	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:25:34:8	16.36	1271	1.22	13.44	95	196	Idle	68.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.49	20.22	1.38	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:25:34:8	16.36	1271	1.23	13.44	95	196	Idle	69.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.44	20.22	1.38	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:25:34:8	16.36	1261	1.24	13.44	95	196	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.33	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:34:8	16.36	1225	1.24	13.42	95	196	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.28	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:34:8	16.36	1205	1.24	13.44	95	196	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.2	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:34:8	16.36	1205	1.25	13.45	95	196	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.11	20.21	1.38	4.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:25:34:9	16.36	1189	1.25	13.44	95	196	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.02	20.21	1.38	4.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:25:34:9	16.36	1173	1.25	13.45	95	196	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.96	20.21	1.38	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:25:34:9	16.36	1188	1.24	13.45	95	196	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.87	20.22	1.38	4.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:34:9	16.36	1212	1.24	13.44	95	196	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.85	20.22	1.38	4.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:34:9	16.36	1221	1.24	13.44	95	196	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.78	20.22	1.38	4.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:34:9	16.36	1238	1.23	13.44	95	196	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.7	20.22	1.38	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:34:9	14.99	1266	1.23	13.42	95	196	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.7	20.23	1.38	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:35:0	14.99	1304	1.22	13.43	95	196	Idle	74	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.75	20.22	1.38	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:0	14.99	1332	1.22	13.43	95	196	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.79	20.23	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:35:0	12.27	1353	1.21	13.43	95	196	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.87	20.23	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:35:0	12.27	1410	1.19	13.44	95	196	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.01	20.23	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:35:0	12.27	1488	1.18	13.46	95	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.22	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:35:0	12.27	1529	1.17	13.46	95	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.15	20.21	1.38	3.9	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:35:1	12.27	1553	1.16	13.45	95	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.27	20.21	1.38	3.9	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:35:1	13.63	1617	1.15	13.45	95	196	Idle	82	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.45	20.2	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:35:1	13.63	1701	1.13	13.45	95	196	Idle	84.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.62	20.2	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:35:1	14.99	1701	1.12	13.45	95	196	Idle	85.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.72	20.2	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:35:1	14.99	1768	1.11	13.44	95	196	Idle	86.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	20.2	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:35:1	14.99	1859	1.09	13.45	95	196	Idle	87.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.18	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:35:1	14.99	1899	1.08	13.45	95	196	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.37	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:35:2	14.99	1899	1.07	13.47	95	196	Idle	89.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.54	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:35:2	14.99	1976	1.06	13.48	95	196	Idle	89.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.66	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:35:2	14.99	2066	1.04	13.49	95	196	Idle	89.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.87	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:35:2	14.99	2066	1.03	13.49	95	196	Idle	90.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10	20.21	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:2	17.72	2185	1.02	13.48	95	196	Idle	90.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.09	20.21	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:2	17.72	2252	1.01	13.46	95	196	Idle	90.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.19	20.21	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:3	17.72	2297	1	13.46	95	196	Idle	90.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.26	20.2	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:3	17.72	2322	0.99	13.46	95	196	Idle	90.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.34	20.2	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:3	17.72	2392	0.98	13.45	95	196	Idle	89.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.4	20.2	1.38	3.2	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:3	17.72	2479	0.98	13.45	95	196	Idle	87.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.5	20.2	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:3	17.72	2479	0.97	13.47	95	196	Idle	86.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.58	20.19	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:3	17.72	2597	0.97	13.46	95	196	Idle	84.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.71	20.21	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:4	17.72	2606	0.97	13.46	95	196	Idle	83	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.73	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:4	17.72	2639	0.97	13.46	95	196	Idle	81	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.79	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:4	17.72	2629	0.98	13.47	95	196	Idle	78.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.83	20.2	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:4	17.72	2610	0.99	13.45	95	196	Idle	76.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.82	20.12	1.37	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:4	17.72	2591	1	13.45	95	196	Idle	74.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.81	19.96	1.36	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:4	19.09	2582	1.03	13.45	95	196	Idle	72.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.8	19.74	1.34	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:4	19.09	2559	1.04	13.45	95	196	Idle	70.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.75	19.31	1.32	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:5	19.09	2514	1.06	13.45	95	196	Idle	68.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.72	18.97	1.29	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:5	19.09	2451	1.08	13.44	95	196	Idle	67.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.7	18.6	1.27	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:5	19.09	2463	1.1	13.44	95	196	Idle	65.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.64	18.21	1.24	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:5	19.09	2466	1.12	13.44	95	196	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	17.82	1.21	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:5	19.09	2456	1.14	13.44	95	196	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	17.4	1.19	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:5	19.09	2456	1.16	13.44	95	196	Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	17.02	1.16	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:6	19.09	2464	1.18	13.46	95	196	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	16.73	1.14	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:6	19.09	2502	1.21	13.45	95	196	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	16.51	1.12	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:6	19.09	2517	1.23	13.45	95	196	Idle	60.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	16.5	1.12	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:6	19.09	2526	1.25	13.44	95	196	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	16.59	1.13	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:6	19.09	2552	1.27	13.45	95	196	Idle	60.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	16.82	1.15	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:6	19.09	2559	1.3	13.44	95	196	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	17.15	1.17	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:6	19.09	2560	1.32	13.44	95	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	17.53	1.19	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:7	19.09	2564	1.34	13.43	95	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	18.14	1.24	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:7	19.09	2541	1.35	13.44	95	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	18.56	1.26	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:7	19.09	2536	1.36	13.44	95	196	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	18.97	1.29	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:7	19.09	2504	1.36	13.44	95	196	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	19.36	1.32	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:7	19.09	2496	1.37	13.44	95	196	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	19.71	1.34	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:7	19.09	2490	1.37	13.46	95	196	Idle	61.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	19.96	1.36	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:8	19.09	2478	1.37	13.45	95	196	Idle	62	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.06	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:8	19.09	2448	1.37	13.46	95	196	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:8	19.09	2467	1.37	13.45	95	196	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:8	19.09	2466	1.38	13.45	95	196	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:8	19.09	2480	1.38	13.45	95	196	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:8	19.09	2480	1.38	13.45	95	196	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:9	19.09	2483	1.38	13.45	95	196	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:35:9	19.09	2493	1.38	13.46	95	196	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:9	19.09	2505	1.38	13.46	95	196	Idle	62.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:9	19.09	2506	1.38	13.45	95	196	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:9	19.09	2507	1.38	13.46	95	196	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:9	19.09	2505	1.37	13.45	95	196	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:35:9	19.09	2499	1.37	13.44	95	196	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:0	19.09	2489	1.37	13.44	95	196	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:0	19.09	2489	1.37	13.45	95	196	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:0	19.09	2476	1.37	13.45	95	196	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:0	19.09	2473	1.36	13.45	95	196	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:0	19.09	2467	1.36	13.46	95	196	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:0	19.09	2460	1.36	13.46	95	196	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:1	19.09	2470	1.36	13.46	95	196	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:1	19.09	2468	1.35	13.46	95	196	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.2	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:1	19.09	2468	1.35	13.45	95	196	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:1	19.09	2474	1.35	13.46	95	196	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:1	19.09	2469	1.35	13.46	95	196	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.2	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:1	19.09	2482	1.35	13.46	95	196	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:1	19.09	2494	1.35	13.46	95	196	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:2	19.09	2486	1.34	13.45	95	196	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:2	19.09	2485	1.34	13.46	95	196	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:2	19.09	2484	1.34	13.45	95	196	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:2	19.09	2478	1.33	13.46	95	196	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:2	19.09	2472	1.33	13.46	95	196	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:2	19.09	2472	1.33	13.46	95	196	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:3	19.09	2465	1.33	13.46	95	196	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:3	19.09	2460	1.33	13.46	95	196	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:3	19.09	2457	1.33	13.45	95	196	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:3	19.09	2438	1.33	13.46	95	196	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:3	17.72	2454	1.33	13.46	95	196	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:3	17.72	2473	1.33	13.46	95	196	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:4	17.72	2454	1.33	13.46	95	196	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:4	17.72	2454	1.32	13.46	95	196	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:4	17.72	2454	1.32	13.46	95	196	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:4	17.72	2455	1.32	13.45	95	196	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:4	17.72	2455	1.32	13.46	95	196	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:4	17.72	2454	1.32	13.45	95	196	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:4	17.72	2434	1.32	13.44	95	196	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:5	17.72	2447	1.32	13.45	95	196	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:5	17.72	2447	1.32	13.44	95	196	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:5	17.72	2443	1.32	13.45	95	196	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:5	17.72	2443	1.31	13.45	95	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:5	17.72	2433	1.31	13.46	95	196	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:5	19.09	2450	1.31	13.46	95	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:6	19.09	2441	1.31	13.46	95	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:6	19.09	2442	1.31	13.45	95	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:6	19.09	2442	1.31	13.45	95	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:6	19.09	2439	1.31	13.45	95	196	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:6	19.09	2439	1.3	13.46	95	196	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:6	19.09	2458	1.3	13.46	95	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:6	19.09	2437	1.3	13.46	95	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:7	19.09	2427	1.3	13.46	95	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:7	19.09	2435	1.3	13.45	95	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:7	19.09	2435	1.29	13.46	95	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:7	19.09	2435	1.29	13.45	95	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:7	19.09	2432	1.29	13.44	95	196	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:7	19.09	2432	1.29	13.44	95	196	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:8	17.72	2424	1.29	13.42	95	196	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:36:8	17.72	2422	1.29	13.44	95	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:8	17.72	2429	1.29	13.43	95	196	Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:8	17.72	2428	1.29	13.45	95	196	Full Load	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:8	17.72	2434	1.29	13.45	95	196	Full Load	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:25:36:8	17.72	2420	1.29	13.46	95	196	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:36:9	8.18	2413	1.29	13.45	95	196	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.35	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:36:9	8.18	2413	1.29	13.45	95	196	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.33	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:36:9	10.9	2427	1.3	13.45	95	196	Off Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:36:9	13.63	2423	1.3	13.45	95	196	Off Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.25	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:36:9	16.36	2422	1.3	13.45	95	196	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:36:9	16.36	2418	1.31	13.46	95	196	Off Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:36:9	19.09	2418	1.31	13.46	95	196	Off Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:0	19.09	2418	1.32	13.44	95	196	Off Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:0	21.81	2418	1.32	13.45	95	196	Off Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:0	24.54	2422	1.32	13.43	95	196	Off Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:0	24.54	2430	1.33	13.44	95	196	Off Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:0	27.27	2430	1.33	13.45	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:0	29.99	2441	1.33	13.45	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:1	29.99	2446	1.34	13.46	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:1	32.72	2469	1.34	13.46	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.23	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:1	35.45	2447	1.35	13.45	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:1	35.45	2423	1.35	13.45	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:1	35.45	2420	1.35	13.45	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:1	35.45	2402	1.36	13.43	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.37	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:1	35.45	2400	1.36	13.44	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:2	35.45	2397	1.36	13.45	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:2	35.45	2386	1.36	13.44	95	196	Off Idle	71.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:2	35.45	2394	1.35	13.44	95	196	Off Idle	71.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:2	35.45	2394	1.35	13.44	95	196	Off Idle	71.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:2	35.45	2398	1.35	13.44	95	196	Off Idle	71.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:2	35.45	2402	1.35	13.44	95	196	Off Idle	71.4	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10.4	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:3	35.45	2401	1.35	13.45	95	196	Off Idle	71.4	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.41	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:3	35.45	2402	1.35	13.45	95	196	Off Idle	71.6	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.41	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:3	35.45	2404	1.35	13.46	95	196	Off Idle	71.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:3	35.45	2400	1.35	13.46	95	196	Off Idle	71.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:3	35.45	2400	1.35	13.45	95	196	Off Idle	71.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:3	35.45	2396	1.35	13.45	95	196	Off Idle	71.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:37:4	35.45	2382	1.36	13.45	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:37:4	35.45	2380	1.36	13.44	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:37:4	35.45	2380	1.36	13.44	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:37:4	35.45	2379	1.37	13.45	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:37:4	35.45	2377	1.37	13.45	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:37:4	35.45	2376	1.38	13.45	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10.18	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:4	35.45	2387	1.39	13.44	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.13	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:5	35.45	2393	1.39	13.45	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10.12	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:5	35.45	2396	1.4	13.45	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10.1	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:5	35.45	2408	1.41	13.45	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.09	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:5	35.45	2414	1.41	13.45	95	196	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10.06	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:5	35.45	2438	1.42	13.47	95	196	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.06	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:5	35.45	2438	1.43	13.45	95	196	Off Idle	72.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:6	35.45	2416	1.43	13.47	95	196	Off Idle	72.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.01	20.17	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:6	35.45	2407	1.44	13.45	95	196	Off Idle	72.2	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.99	20.05	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:6	35.45	2405	1.45	13.44	95	196	Off Idle	72	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.98	19.91	1.36	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:37:6	35.45	2386	1.46	13.43	95	196	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.96	19.73	1.34	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:6	35.45	2388	1.47	13.44	95	196	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.93	19.4	1.32	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:6	35.45	2384	1.48	13.44	95	196	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.93	19.16	1.3	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:6	35.45	2384	1.48	13.44	95	196	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.9	18.9	1.29	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:7	35.45	2379	1.49	13.44	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.92	18.64	1.27	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:37:7	35.45	2379	1.49	13.43	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.88	18.36	1.25	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:7	35.45	2373	1.49	13.44	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.88	18.11	1.23	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:7	35.45	2371	1.5	13.45	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.07	Lean	1	14.7	-9.86	17.91	1.22	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:7	35.45	2368	1.5	13.45	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.82	17.74	1.21	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:7	35.45	2368	1.51	13.45	95	196	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.77	17.52	1.19	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:8	35.45	2367	1.51	13.45	95	196	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.75	17.42	1.19	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:8	35.45	2376	1.52	13.45	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.72	17.32	1.18	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:37:8	35.45	2376	1.53	13.44	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.07	Lean	1	14.7	-9.7	17.22	1.17	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:37:8	35.45	2386	1.53	13.43	95	196	Off Idle	73.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.66	17.12	1.17	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:37:8	35.45	2391	1.54	13.43	95	196	Off Idle	73.1	0	2	132	944 Turbo	0.07	Lean	1	14.7	-9.65	17.02	1.16	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:37:8	35.45	2394	1.54	13.43	95	196	Off Idle	73.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.63	16.97	1.16	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:37:9	35.45	2400	1.55	13.45	95	196	Off Idle	73.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.62	16.81	1.15	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:37:9	35.45	2405	1.56	13.45	95	196	Off Idle	73.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.58	16.66	1.13	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:37:9	35.45	2405	1.56	13.45	95	196	Off Idle	72.9	0	2	132	944 Turbo	0.08	Lean	1	14.7	-9.56	16.6	1.13	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:37:9	35.45	2414	1.57	13.46	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.51	16.49	1.12	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:37:9	35.45	2416	1.58	13.46	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.45	16.32	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:37:9	35.45	2418	1.59	13.46	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.45	16.23	1.11	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:37:9	35.45	2418	1.59	13.44	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.09	Lean	1	14.7	-9.42	16.19	1.1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:0	35.45	2418	1.6	13.44	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.41	16.06	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:0	35.45	2419	1.6	13.44	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.4	15.99	1.09	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:0	35.45	2428	1.61	13.44	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.37	15.92	1.08	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:0	35.45	2408	1.62	13.43	95	196	Off Idle	72	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.34	15.86	1.08	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:0	35.45	2394	1.63	13.44	95	196	Off Idle	71.7	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.31	15.81	1.08	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:38:0	35.45	2386	1.64	13.44	95	196	Off Idle	71.6	0	2	132	944 Turbo	0.32	Rich	1	14.7	-9.3	15.79	1.08	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:1	35.45	2374	1.64	13.44	95	196	Off Idle	71.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.24	15.74	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:1	34.08	2359	1.65	13.43	95	196	Off Idle	71.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.2	15.69	1.07	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:1	34.08	2359	1.66	13.42	95	196	Off Idle	71.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.16	15.62	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:1	34.08	2358	1.66	13.42	95	196	Off Idle	71.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.12	15.57	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:1	34.08	2358	1.67	13.43	95	196	Off Idle	71.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.09	15.5	1.06	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:1	34.08	2364	1.67	13.43	95	196	Off Idle	71.8	0	2	132	944 Turbo	0.7	Rich	1	14.7	-9.1	15.44	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:1	34.08	2369	1.67	13.43	95	196	Off Idle	72	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.09	15.39	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:2	34.08	2370	1.67	13.42	95	196	Off Idle	72	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.09	15.35	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:2	34.08	2376	1.67	13.43	95	196	Off Idle	72.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.09	15.31	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:2	34.08	2385	1.67	13.45	95	196	Off Idle	72.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.08	15.27	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:2	34.08	2385	1.67	13.46	95	196	Off Idle	72.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.11	15.24	1.04	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:2	34.08	2391	1.67	13.46	95	196	Off Idle	72.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-9.12	15.17	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:38:2	34.08	2398	1.67	13.46	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.14	15.16	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:38:3	34.08	2399	1.67	13.46	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.63	Rich	1	14.7	-9.14	15.16	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:3	34.08	2400	1.67	13.45	95	196	Off Idle	73	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.13	15.15	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:3	34.08	2401	1.67	13.45	95	196	Off Idle	73.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.12	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:3	34.08	2398	1.67	13.45	95	196	Off Idle	73.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.14	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:3	34.08	2398	1.68	13.45	95	196	Off Idle	73.2	0	2	132	944 Turbo	0.56	Rich	1	14.7	-9.14	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:3	34.08	2390	1.68	13.45	95	196	Off Idle	72.9	0	2	132	944 Turbo	0.51	Rich	1	14.7	-9.14	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:38:4	34.08	2381	1.68	13.46	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.14	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:38:4	34.08	2373	1.68	13.44	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.12	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:4	34.08	2373	1.68	13.45	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.41	Rich	1	14.7	-9.1	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:4	34.08	2370	1.68	13.45	95	196	Off Idle	72.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.07	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:4	34.08	2370	1.68	13.44	95	196	Off Idle	72.5	0	2	132	944 Turbo	0.33	Rich	1	14.7	-9.02	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:4	34.08	2370	1.68	13.46	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:4	34.08	2371	1.69	13.45	95	196	Off Idle	72.9	0	2	132	944 Turbo	0.21	Rich	1	14.7	-9	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:5	34.08	2374	1.69	13.45	95	196	Off Idle	73	0	2	132	944 Turbo	0.18	Rich	1	14.6	-8.99	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:5	34.08	2383	1.69	13.45	95	196	Off Idle	73	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.94	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:5	34.08	2387	1.7	13.46	95	196	Off Idle	73	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.91	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:5	34.08	2387	1.7	13.45	95	196	Off Idle	73.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.88	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:5	34.08	2390	1.71	13.46	95	196	Off Idle	73.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.84	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:5	34.08	2390	1.71	13.45	95	196	Off Idle	73.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.82	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:6	34.08	2388	1.71	13.44	95	196	Off Idle	73.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.78	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:6	34.08	2384	1.72	13.45	95	196	Off Idle	73.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.78	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:38:6	34.08	2377	1.72	13.45	95	196	Off Idle	73.5	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.79	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:6	34.08	2377	1.72	13.45	95	196	Off Idle	73.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.76	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:6	34.08	2382	1.73	13.44	95	196	Off Idle	73.2	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.74	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:6	34.08	2385	1.73	13.44	95	196	Off Idle	73.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.74	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:6	34.08	2386	1.73	13.44	95	196	Off Idle	73.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.73	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:7	34.08	2392	1.73	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.71	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:7	34.08	2393	1.74	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.69	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:7	34.08	2385	1.74	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.64	15.17	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:7	34.08	2386	1.75	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.62	15.16	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:7	34.08	2382	1.75	13.45	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.63	15.16	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:7	34.08	2384	1.75	13.43	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.62	15.16	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:8	34.08	2382	1.75	13.43	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.6	15.17	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:8	34.08	2384	1.76	13.43	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.6	15.18	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:8	34.08	2385	1.76	13.43	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.58	15.17	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:8	34.08	2385	1.76	13.43	95	196	Off Idle	72.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.56	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:8	34.08	2392	1.77	13.44	95	196	Off Idle	72.9	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.53	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:8	34.08	2390	1.77	13.44	95	196	Off Idle	72.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.53	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:9	34.08	2391	1.77	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.5	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:9	34.08	2391	1.78	13.45	95	196	Off Idle	73	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.47	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:38:9	34.08	2390	1.78	13.45	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.47	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:9	34.08	2386	1.78	13.46	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.48	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:9	34.08	2386	1.78	13.46	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.45	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:9	34.08	2385	1.79	13.46	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.46	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:38:9	34.08	2381	1.79	13.45	95	196	Off Idle	73	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.46	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:39:0	34.08	2379	1.79	13.46	95	196	Off Idle	73	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.44	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:0	34.08	2379	1.8	13.45	95	196	Off Idle	73.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.42	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:0	34.08	2368	1.8	13.47	95	196	Off Idle	73.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.42	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:0	34.08	2377	1.8	13.46	95	196	Off Idle	73	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.4	14.81	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:0	34.08	2378	1.8	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.35	14.83	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:0	34.08	2379	1.8	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.34	14.84	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:1	34.08	2402	1.8	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.33	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:1	34.08	2402	1.81	13.43	95	196	Off Idle	73	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.32	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:1	34.08	2386	1.81	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.49	Lean	1	14.7	-8.34	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:1	34.08	2386	1.81	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.44	Lean	1	14.7	-8.34	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:1	34.08	2389	1.81	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.38	Lean	1	14.7	-8.32	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:1	34.08	2390	1.81	13.44	95	196	Off Idle	73	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.31	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:1	34.08	2390	1.81	13.43	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.29	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:2	34.08	2392	1.81	13.44	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.25	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:2	34.08	2380	1.81	13.44	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.24	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:2	34.08	2380	1.81	13.45	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.22	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:2	34.08	2379	1.82	13.45	95	196	Off Idle	72.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.24	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:2	34.08	2381	1.82	13.45	95	196	Off Idle	72.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.24	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:2	34.08	2382	1.82	13.46	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.22	14.85	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:3	34.08	2382	1.82	13.44	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.21	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:3	34.08	2384	1.82	13.44	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.37	Rich	1	14.7	-8.21	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:3	34.08	2385	1.82	13.44	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.42	Rich	1	14.7	-8.24	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:3	34.08	2386	1.82	13.44	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.24	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:3	34.08	2370	1.82	13.44	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.52	Rich	1	14.7	-8.23	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:3	34.08	2385	1.82	13.44	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.57	Rich	1	14.7	-8.24	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:4	34.08	2386	1.83	13.43	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.23	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:4	34.08	2387	1.83	13.43	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.2	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:4	34.08	2395	1.83	13.43	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.19	15.05	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:4	34.08	2395	1.83	13.43	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.18	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:4	34.08	2376	1.83	13.43	95	196	Off Idle	72.7	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.19	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:4	34.08	2380	1.83	13.45	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.15	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:4	34.08	2386	1.83	13.45	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.18	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:5	34.08	2386	1.83	13.46	95	196	Off Idle	72.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.16	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:5	34.08	2397	1.83	13.46	95	196	Off Idle	72.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.16	15.03	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:39:5	34.08	2399	1.83	13.46	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.14	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:5	34.08	2407	1.84	13.45	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.14	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:5	34.08	2407	1.84	13.45	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.15	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:5	34.08	2406	1.84	13.45	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.24	Rich	1	14.7	-8.11	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:6	34.08	2405	1.84	13.46	95	196	Off Idle	71.8	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.11	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:6	34.08	2405	1.84	13.44	95	196	Off Idle	71.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.12	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:6	34.08	2394	1.84	13.44	95	196	Off Idle	71.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.08	14.9	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:6	34.08	2386	1.85	13.45	95	196	Off Idle	71.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.06	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:6	34.08	2386	1.85	13.44	95	196	Off Idle	71.8	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.08	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:6	34.08	2386	1.85	13.45	95	196	Off Idle	71.8	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.07	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:6	34.08	2389	1.85	13.45	95	196	Off Idle	71.8	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.05	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:7	34.08	2389	1.85	13.44	95	196	Off Idle	72	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.08	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:7	34.08	2390	1.85	13.45	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.38	Lean	1	14.7	-8.09	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:7	34.08	2390	1.85	13.45	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.44	Lean	1	14.7	-8.08	14.95	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:7	34.08	2392	1.86	13.45	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.54	Rich	1	14.7	-8.05	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:7	34.08	2398	1.86	13.45	95	196	Off Idle	72.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.06	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:7	34.08	2398	1.86	13.44	95	196	Off Idle	72.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.03	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:8	34.08	2401	1.86	13.44	95	196	Off Idle	72.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.02	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:8	34.08	2400	1.86	13.44	95	195	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.02	15.05	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:8	34.08	2400	1.86	13.45	95	195	Off Idle	72.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.01	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:8	34.08	2399	1.86	13.43	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:8	34.08	2399	1.87	13.43	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.03	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:39:8	34.08	2395	1.87	13.43	95	196	Off Idle	72.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.04	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:9	34.08	2392	1.87	13.43	95	195	Off Idle	72.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.05	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:9	34.08	2394	1.87	13.42	95	195	Off Idle	72.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.07	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:9	34.08	2394	1.87	13.43	95	195	Off Idle	72.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.07	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:9	34.08	2394	1.87	13.44	95	196	Off Idle	72.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.03	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:9	34.08	2394	1.87	13.45	95	196	Off Idle	72.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:9	34.08	2395	1.87	13.44	95	196	Off Idle	72.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.02	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:39:9	34.08	2395	1.87	13.46	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8	14.73	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:0	34.08	2396	1.87	13.46	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8	14.69	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:0	34.08	2398	1.87	13.46	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.57	Rich	1	14.7	-8.02	14.65	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:0	34.08	2400	1.87	13.45	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8	14.66	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:0	34.08	2410	1.87	13.44	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.53	Rich	1	14.7	-8.01	14.67	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:0	34.08	2400	1.87	13.46	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.99	14.66	1	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:0	34.08	2401	1.87	13.44	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8	14.67	1	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:1	34.08	2401	1.87	13.43	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8	14.67	1	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:1	34.08	2392	1.87	13.45	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8	14.66	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:1	34.08	2396	1.87	13.44	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:1	34.08	2396	1.87	13.44	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.62	Rich	1	14.7	-7.99	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:1	34.08	2396	1.87	13.44	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.99	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:1	34.08	2392	1.87	13.46	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.97	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:1	34.08	2397	1.87	13.44	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.68	Rich	1	14.7	-7.99	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:2	34.08	2397	1.87	13.45	95	196	Off Idle	71.9	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.99	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:2	34.08	2398	1.87	13.45	95	196	Off Idle	72.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.97	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:2	34.08	2383	1.87	13.45	95	196	Off Idle	72.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.96	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:2	34.08	2383	1.87	13.45	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.68	Rich	1	14.7	-7.98	14.88	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:2	34.08	2404	1.87	13.45	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8	14.93	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:2	34.08	2409	1.87	13.44	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.01	14.95	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:3	34.08	2408	1.87	13.44	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.04	14.97	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:3	34.08	2425	1.87	13.44	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.07	14.98	1.02	3.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:3	34.08	2406	1.87	13.44	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.08	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:3	34.08	2406	1.87	13.44	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.07	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:3	34.08	2404	1.87	13.44	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.37	Lean	1	14.7	-8.08	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:3	34.08	2377	1.87	13.43	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.09	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:4	34.08	2396	1.86	13.44	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.1	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:4	34.08	2395	1.86	13.45	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.12	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:4	34.08	2395	1.86	13.44	95	196	Off Idle	72.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.17	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:40:4	34.08	2395	1.86	13.44	95	196	Off Idle	72.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.21	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:40:4	34.08	2395	1.85	13.46	95	196	Off Idle	72.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.21	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:4	34.08	2398	1.85	13.45	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.27	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:4	34.08	2404	1.85	13.46	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.26	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:5	34.08	2408	1.84	13.46	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.3	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:5	34.08	2398	1.84	13.45	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.3	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:5	34.08	2411	1.84	13.44	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.28	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:5	34.08	2409	1.83	13.44	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.32	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:5	34.08	2402	1.83	13.44	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.31	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:5	34.08	2402	1.83	13.44	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.3	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:6	34.08	2405	1.82	13.43	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.34	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:6	34.08	2408	1.82	13.43	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.34	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:6	34.08	2415	1.82	13.43	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	-8.31	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:6	34.08	2415	1.82	13.44	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.77	Rich	1	14.7	-8.35	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:6	34.08	2416	1.82	13.44	95	195	Off Idle	71.9	0	2	132	944 Turbo	0.77	Rich	1	14.7	-8.34	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:6	34.08	2417	1.81	13.45	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.33	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:6	34.08	2416	1.81	13.46	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.35	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:7	34.08	2394	1.81	13.47	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.37	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:7	34.08	2412	1.81	13.46	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.32	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:7	34.08	2411	1.81	13.45	95	196	Off Idle	71.3	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.33	14.93	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:7	34.08	2405	1.81	13.46	95	196	Off Idle	71.2	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.32	14.9	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:7	34.08	2401	1.81	13.44	95	195	Off Idle	71	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.31	14.85	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:7	34.08	2417	1.81	13.42	95	195	Off Idle	71	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.31	14.77	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:8	34.08	2410	1.81	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.39	Rich	1	14.7	-8.31	14.73	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:8	34.08	2406	1.82	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.31	14.72	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:8	34.08	2395	1.82	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.33	14.71	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:8	34.08	2406	1.81	13.43	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.36	14.71	1	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:8	34.08	2415	1.81	13.45	95	195	Off Idle	71.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.36	14.71	1	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:8	34.08	2415	1.81	13.44	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.37	14.76	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:9	34.08	2415	1.81	13.45	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.4	14.77	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:9	34.08	2413	1.81	13.45	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.4	14.77	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:9	34.08	2413	1.81	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.4	14.78	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:9	34.08	2413	1.81	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.43	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:9	34.08	2412	1.81	13.46	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.46	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:40:9	34.08	2412	1.81	13.47	95	195	Off Idle	72	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.47	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:40:9	34.08	2411	1.81	13.47	95	195	Off Idle	72	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.48	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:0	34.08	2411	1.81	13.47	95	195	Off Idle	72	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.48	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:0	34.08	2410	1.81	13.47	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.48	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:0	34.08	2410	1.81	13.47	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.47	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:0	34.08	2405	1.81	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.48	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:0	34.08	2405	1.8	13.45	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.47	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:0	34.08	2396	1.8	13.46	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.46	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:1	34.08	2408	1.8	13.46	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.49	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:1	34.08	2408	1.8	13.45	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.5	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:1	34.08	2414	1.8	13.45	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.5	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:1	34.08	2419	1.8	13.45	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.52	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:1	34.08	2427	1.8	13.45	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.49	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:1	34.08	2428	1.8	13.45	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.5	15.09	1.03	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:1	34.08	2425	1.8	13.45	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.49	15.09	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:2	34.08	2421	1.8	13.46	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.47	15.07	1.03	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:2	34.08	2421	1.8	13.46	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.47	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:2	34.08	2416	1.8	13.46	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.5	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:2	34.08	2410	1.8	13.46	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.37	Rich	1	14.7	-8.5	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:2	34.08	2410	1.8	13.46	95	195	Off Idle	71.4	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.51	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:2	34.08	2409	1.8	13.46	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.52	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:3	34.08	2420	1.8	13.46	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.53	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:3	34.08	2412	1.8	13.44	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.55	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:3	34.08	2416	1.8	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.55	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:41:3	34.08	2416	1.8	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.55	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:3	34.08	2417	1.8	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.55	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:3	34.08	2419	1.8	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.34	Lean	1	14.7	-8.54	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:4	34.08	2416	1.79	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.52	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:4	34.08	2418	1.79	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.46	Lean	1	14.7	-8.54	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:4	34.08	2413	1.79	13.46	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.55	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:4	34.08	2423	1.79	13.46	95	196	Off Idle	71.1	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.58	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:4	34.08	2423	1.79	13.46	95	196	Off Idle	70.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.6	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:4	34.08	2423	1.79	13.46	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.62	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:4	34.08	2429	1.79	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.62	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:5	34.08	2416	1.79	13.44	95	195	Off Idle	71	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.64	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:5	34.08	2416	1.79	13.44	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.62	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:5	34.08	2412	1.79	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.64	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:5	34.08	2408	1.79	13.46	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.66	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:5	34.08	2409	1.79	13.46	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.63	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:5	34.08	2409	1.79	13.47	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.62	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:6	34.08	2412	1.79	13.46	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.62	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:6	34.08	2416	1.78	13.46	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.65	Lean	1	14.7	-8.62	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:6	34.08	2418	1.78	13.46	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.64	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:6	34.08	2418	1.78	13.45	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.49	Lean	1	14.7	-8.64	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:6	34.08	2421	1.78	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.62	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:6	34.08	2420	1.78	13.44	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.33	Lean	1	14.7	-8.63	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:6	34.08	2398	1.78	13.44	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.62	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:7	34.08	2407	1.78	13.46	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.6	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:7	34.08	2412	1.78	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.64	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:7	34.08	2408	1.78	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.62	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:7	34.08	2408	1.78	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.62	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:7	34.08	2410	1.78	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.65	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:7	34.08	2414	1.78	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.66	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:8	34.08	2417	1.77	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.67	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:8	34.08	2418	1.77	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.7	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:8	34.08	2419	1.77	13.44	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.7	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:41:8	34.08	2422	1.77	13.46	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.46	Lean	1	14.7	-8.69	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:8	34.08	2424	1.77	13.44	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.53	Lean	1	14.7	-8.68	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:8	34.08	2436	1.77	13.45	95	195	Off Idle	70.2	0	2	132	944 Turbo	0.59	Lean	1	14.7	-8.69	14.91	1.02	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:9	34.08	2425	1.77	13.44	95	195	Off Idle	70.2	0	2	132	944 Turbo	0.66	Lean	1	14.7	-8.72	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:9	34.08	2425	1.77	13.45	95	195	Off Idle	70.2	0	2	132	944 Turbo	0.74	Lean	1	14.6	-8.71	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:9	34.08	2427	1.76	13.44	95	195	Off Idle	70.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.74	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:9	34.08	2428	1.76	13.45	95	195	Off Idle	70.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.79	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:9	34.08	2427	1.76	13.44	95	195	Off Idle	70.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.79	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:9	34.08	2422	1.76	13.46	95	195	Off Idle	70	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.79	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:41:9	34.08	2422	1.76	13.46	95	195	Off Idle	70	0	2	132	944 Turbo	0.78	Rich	1	14.7	-8.77	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:0	34.08	2417	1.76	13.45	95	195	Off Idle	70	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.73	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:0	34.08	2417	1.76	13.45	95	195	Off Idle	70	0	2	132	944 Turbo	0.77	Rich	1	14.7	-8.73	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:0	34.08	2411	1.76	13.46	95	195	Off Idle	70	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.71	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:0	34.08	2413	1.76	13.45	95	195	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.71	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:0	34.08	2417	1.76	13.46	95	195	Off Idle	70.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.73	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:0	34.08	2417	1.76	13.45	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.72	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:1	34.08	2414	1.76	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.73	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:1	34.08	2417	1.76	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.75	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:42:1	34.08	2415	1.76	13.44	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.77	14.75	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:42:1	34.08	2416	1.76	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.79	14.74	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:1	34.08	2410	1.76	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.41	Rich	1	14.7	-8.82	14.73	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:1	34.08	2423	1.75	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.83	14.73	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:42:1	34.08	2422	1.75	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.85	14.74	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:2	34.08	2422	1.75	13.46	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.23	Rich	1	14.7	-8.83	14.75	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:2	34.08	2430	1.75	13.46	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.18	Rich	1	14.6	-8.86	14.77	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:42:2	34.08	2416	1.75	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.86	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:42:2	34.08	2416	1.75	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.81	14.79	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:2	34.08	2418	1.75	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.83	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:42:2	34.08	2419	1.75	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.83	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:42:3	34.08	2419	1.75	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.81	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:42:3	34.08	2425	1.75	13.46	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.82	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:3	34.08	2426	1.75	13.47	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.78	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:3	34.08	2427	1.75	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.8	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:3	34.08	2428	1.75	13.47	95	195	Off Idle	70.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.8	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:3	34.08	2424	1.75	13.46	95	195	Off Idle	70.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.84	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:4	34.08	2420	1.74	13.46	95	195	Off Idle	70.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.83	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:4	34.08	2418	1.74	13.45	95	195	Off Idle	70.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.87	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:4	34.08	2410	1.74	13.45	95	195	Off Idle	70.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.89	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:4	34.08	2409	1.74	13.45	95	195	Off Idle	70.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.88	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:4	34.08	2409	1.74	13.46	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.87	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:4	34.08	2409	1.74	13.46	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.87	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:4	34.08	2407	1.74	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.86	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:5	34.08	2399	1.74	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.86	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:5	34.08	2414	1.74	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.89	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:5	34.08	2419	1.74	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.89	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:5	34.08	2446	1.73	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.69	Lean	1	14.6	-8.92	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:5	34.08	2446	1.73	13.46	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.66	Lean	1	14.7	-8.94	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:5	34.08	2426	1.73	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.95	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:6	34.08	2428	1.73	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.58	Lean	1	14.7	-8.95	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:6	34.08	2428	1.73	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.53	Lean	1	14.7	-8.95	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:6	34.08	2421	1.73	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.94	14.76	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:6	34.08	2421	1.72	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.98	14.73	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:6	34.08	2420	1.72	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.98	14.73	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:6	34.08	2414	1.72	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.98	14.72	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:6	34.08	2414	1.72	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.99	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:7	34.08	2413	1.72	13.46	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.22	Lean	1	14.7	-9.02	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:7	34.08	2414	1.72	13.46	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:7	34.08	2417	1.71	13.46	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:7	34.08	2416	1.71	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.02	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:7	34.08	2412	1.71	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.98	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:7	34.08	2411	1.71	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.98	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:8	34.08	2411	1.71	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.97	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:8	34.08	2413	1.71	13.43	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.99	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:8	34.08	2421	1.71	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.97	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:8	34.08	2421	1.71	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.33	Lean	1	14.7	-9.02	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:42:8	34.08	2422	1.71	13.46	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.99	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:8	34.08	2421	1.71	13.44	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:9	34.08	2423	1.71	13.45	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.99	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:9	34.08	2414	1.71	13.44	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-9.03	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:9	34.08	2421	1.71	13.45	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.05	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:9	34.08	2421	1.71	13.45	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.08	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:9	34.08	2421	1.71	13.46	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.09	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:9	34.08	2415	1.71	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.1	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:42:9	34.08	2417	1.71	13.47	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.05	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:0	34.08	2410	1.71	13.46	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.07	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:0	34.08	2410	1.7	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.72	Lean	1	14.7	-9.07	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:0	34.08	2413	1.7	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.66	Lean	1	14.7	-9.04	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:0	34.08	2434	1.7	13.43	95	195	Off Idle	71	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.04	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:0	34.08	2425	1.7	13.43	95	195	Off Idle	71	0	2	132	944 Turbo	0.55	Lean	1	14.7	-9.01	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:0	34.08	2415	1.7	13.44	95	195	Off Idle	71	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.99	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:1	34.08	2415	1.7	13.43	95	195	Off Idle	71	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.03	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:1	34.08	2414	1.7	13.43	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.03	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:1	34.08	2412	1.7	13.44	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.04	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:1	34.08	2413	1.7	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.06	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:43:1	34.08	2412	1.7	13.46	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.05	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:1	34.08	2402	1.7	13.46	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.14	Lean	1	14.7	-9.07	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:1	34.08	2415	1.7	13.47	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.02	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:2	34.08	2414	1.7	13.46	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.03	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:2	34.08	2415	1.7	13.46	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.04	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:2	34.08	2416	1.7	13.46	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.04	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:2	34.08	2433	1.7	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.06	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:2	34.08	2422	1.7	13.44	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.07	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:2	34.08	2419	1.7	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-9.06	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:3	34.08	2424	1.7	13.46	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.17	Lean	1	14.7	-9.04	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:3	34.08	2427	1.7	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.02	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:3	34.08	2418	1.7	13.43	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.02	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:3	34.08	2426	1.7	13.43	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.04	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:3	34.08	2425	1.7	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.36	Rich	1	14.7	-9.09	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:3	34.08	2425	1.7	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.39	Rich	1	14.7	-9.09	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:4	34.08	2447	1.7	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.11	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:4	34.08	2424	1.7	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.09	15.16	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:4	34.08	2419	1.7	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.06	15.17	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:4	34.08	2420	1.7	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.65	Rich	1	14.7	-9.06	15.18	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:4	34.08	2408	1.7	13.46	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-9.06	15.17	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:4	34.08	2415	1.7	13.46	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.08	15.17	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:4	34.08	2412	1.7	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.1	15.17	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:5	34.08	2414	1.7	13.46	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.08	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:5	34.08	2430	1.7	13.46	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.11	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:5	35.45	2421	1.7	13.46	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.07	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:5	35.45	2407	1.7	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.08	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:5	35.45	2407	1.69	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9.07	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:5	35.45	2408	1.69	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.1	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:6	35.45	2427	1.69	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.67	Rich	1	14.7	-9.09	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:6	35.45	2410	1.69	13.45	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.1	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:6	34.08	2403	1.69	13.44	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.11	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:6	34.08	2416	1.69	13.44	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	-9.07	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:6	34.08	2416	1.69	13.45	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	-9.05	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:6	34.08	2418	1.69	13.45	95	195	Off Idle	71.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.08	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:6	34.08	2416	1.69	13.45	95	195	Off Idle	71.4	0	2	132	944 Turbo	0.41	Rich	1	14.7	-9.09	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:7	34.08	2416	1.69	13.46	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.37	Rich	1	14.7	-9.09	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:7	34.08	2419	1.69	13.46	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.33	Rich	1	14.7	-9.12	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:7	34.08	2420	1.69	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.29	Rich	1	14.7	-9.14	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:7	34.08	2424	1.69	13.44	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.24	Rich	1	14.7	-9.14	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:7	34.08	2428	1.69	13.44	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.21	Rich	1	14.7	-9.14	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:7	34.08	2428	1.69	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.15	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:8	34.08	2426	1.69	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.15	Lean	1	14.7	-9.18	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:8	35.45	2432	1.69	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.17	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:8	35.45	2422	1.69	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.16	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:8	35.45	2422	1.69	13.44	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.16	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:8	35.45	2408	1.69	13.45	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.16	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:8	35.45	2417	1.69	13.46	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.15	Lean	1	14.7	-9.14	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:9	35.45	2408	1.69	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.15	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:43:9	35.45	2417	1.69	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.12	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:9	35.45	2416	1.69	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.28	Lean	1	14.7	-9.14	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:9	35.45	2424	1.69	13.44	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.34	Lean	1	14.7	-9.12	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:9	35.45	2414	1.69	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.39	Rich	1	14.7	-9.13	15.05	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:9	35.45	2413	1.69	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.42	Rich	1	14.7	-9.13	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:43:9	35.45	2412	1.69	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.48	Rich	1	14.7	-9.12	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:0	35.45	2373	1.69	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.13	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:0	34.08	2403	1.69	13.44	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.14	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:0	34.08	2412	1.69	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.13	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:0	34.08	2414	1.69	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.13	15.1	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:44:0	34.08	2420	1.69	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.15	15.09	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:0	34.08	2426	1.69	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.13	15.08	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:1	34.08	2430	1.69	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.12	15.04	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:1	34.08	2430	1.69	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.14	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:1	34.08	2436	1.69	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.69	Rich	1	14.7	-9.14	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:1	34.08	2425	1.69	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.14	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:1	34.08	2423	1.69	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.15	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:1	34.08	2417	1.69	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.16	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:1	34.08	2415	1.68	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.47	Rich	1	14.7	-9.18	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:2	34.08	2415	1.68	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.15	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:2	35.45	2412	1.68	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.17	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:2	35.45	2408	1.68	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.15	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:2	35.45	2410	1.68	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.24	Rich	1	14.7	-9.15	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:2	35.45	2401	1.68	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.17	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:2	35.45	2412	1.68	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.15	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:3	34.08	2399	1.68	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.15	Lean	1	14.7	-9.14	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:3	34.08	2399	1.68	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.16	Lean	1	14.7	-9.15	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:3	34.08	2421	1.68	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.16	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:3	34.08	2441	1.68	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.15	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:3	34.08	2432	1.68	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.18	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:3	34.08	2418	1.68	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.31	Lean	1	14.7	-9.2	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:4	34.08	2420	1.68	13.46	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.18	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:4	34.08	2420	1.68	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.16	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:4	34.08	2420	1.68	13.44	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.15	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:4	34.08	2420	1.68	13.45	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.16	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:4	34.08	2420	1.68	13.44	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.18	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:4	34.08	2408	1.68	13.43	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.2	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:4	34.08	2411	1.68	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.2	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:5	35.45	2408	1.68	13.44	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.21	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:5	35.45	2408	1.67	13.43	95	195	Off Idle	71	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.19	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:5	35.45	2429	1.67	13.44	95	195	Off Idle	71	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.19	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:5	35.45	2413	1.67	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.2	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:5	35.45	2414	1.67	13.45	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.2	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:5	35.45	2416	1.67	13.45	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.21	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:6	34.08	2400	1.67	13.45	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.25	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:6	34.08	2400	1.67	13.45	95	195	Off Idle	71.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.28	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:6	34.08	2415	1.67	13.47	95	195	Off Idle	71.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.29	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:6	34.08	2416	1.66	13.46	95	195	Off Idle	71.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.31	14.78	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:44:6	34.08	2416	1.66	13.45	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.29	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:6	34.08	2406	1.66	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.56	Rich	1	14.7	-9.27	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:6	34.08	2423	1.66	13.45	95	195	Off Idle	71.9	0	2	132	944 Turbo	0.5	Rich	1	14.7	-9.27	14.76	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:7	35.45	2408	1.66	13.43	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.25	14.72	1	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:7	35.45	2407	1.66	13.44	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.39	Rich	1	14.7	-9.24	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:7	35.45	2407	1.66	13.43	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.3	Lean	1	14.7	-9.25	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:44:7	35.45	2411	1.66	13.44	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.24	Lean	1	14.7	-9.26	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:7	35.45	2413	1.66	13.45	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.19	Lean	1	14.7	-9.27	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:7	35.45	2414	1.65	13.45	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.29	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:8	35.45	2426	1.65	13.45	95	195	Off Idle	71.9	0	2	132	944 Turbo	0.14	Lean	1	14.7	-9.28	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:8	35.45	2417	1.65	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.32	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:8	35.45	2417	1.65	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.31	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:8	35.45	2420	1.65	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.3	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:8	35.45	2421	1.65	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.27	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:8	35.45	2421	1.65	13.45	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.25	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:9	34.08	2412	1.65	13.45	95	195	Off Idle	71.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.25	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:9	34.08	2418	1.65	13.44	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.17	Lean	1	14.7	-9.26	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:9	34.08	2417	1.65	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.26	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:9	34.08	2417	1.65	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.28	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:9	34.08	2410	1.65	13.44	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.35	Lean	1	14.7	-9.3	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:44:9	34.08	2404	1.65	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.42	Lean	1	14.7	-9.29	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:44:9	35.45	2421	1.65	13.44	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.48	Lean	1	14.7	-9.27	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:0	35.45	2414	1.65	13.44	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.28	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:0	35.45	2409	1.65	13.45	95	195	Off Idle	70.2	0	2	132	944 Turbo	0.62	Lean	1	14.7	-9.25	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:0	35.45	2412	1.65	13.45	95	195	Off Idle	70.4	0	2	132	944 Turbo	0.65	Lean	1	14.7	-9.24	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:0	35.45	2413	1.65	13.44	95	195	Off Idle	70.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.25	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:0	35.45	2413	1.65	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.23	15.15	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:0	35.45	2414	1.65	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.23	15.16	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:1	35.45	2414	1.65	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.25	15.15	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:1	35.45	2415	1.65	13.44	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.27	15.14	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:1	35.45	2415	1.65	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.27	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:1	35.45	2416	1.65	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.31	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:1	35.45	2418	1.65	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.31	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:1	35.45	2418	1.65	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.27	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:1	35.45	2422	1.65	13.47	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.25	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:2	35.45	2424	1.65	13.46	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.27	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:2	35.45	2424	1.65	13.46	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.27	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:2	35.45	2424	1.65	13.45	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.26	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:2	35.45	2402	1.65	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.29	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:2	35.45	2402	1.65	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.28	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:2	35.45	2414	1.65	13.46	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.29	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:3	35.45	2412	1.65	13.44	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.31	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:3	35.45	2412	1.65	13.45	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.29	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:3	35.45	2420	1.65	13.44	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.28	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:45:3	35.45	2400	1.65	13.44	95	195	Off Idle	71	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.27	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:45:3	35.45	2400	1.65	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.24	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:45:3	34.08	2391	1.65	13.44	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.22	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:45:4	34.08	2383	1.65	13.45	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.2	Lean	1	14.7	-9.22	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:45:4	34.08	2402	1.65	13.46	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.26	Lean	1	14.7	-9.24	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:45:4	34.08	2402	1.65	13.48	95	195	Off Idle	70.8	0	2	132	944 Turbo	0.31	Lean	1	14.7	-9.24	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:4	34.08	2406	1.65	13.48	95	195	Off Idle	71	0	2	132	944 Turbo	0.37	Lean	1	14.7	-9.26	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:4	34.08	2412	1.65	13.47	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.46	Lean	1	14.7	-9.24	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:4	34.08	2412	1.65	13.47	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.25	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:4	35.45	2435	1.65	13.47	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.27	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:5	35.45	2415	1.65	13.47	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.61	Lean	1	14.7	-9.25	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:5	35.45	2424	1.65	13.46	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-9.27	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:5	35.45	2424	1.65	13.46	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.3	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:5	35.45	2412	1.65	13.46	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.29	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:5	35.45	2409	1.65	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.32	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:5	34.08	2374	1.65	13.46	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.31	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:6	34.08	2374	1.65	13.46	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.32	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:6	34.08	2410	1.65	13.46	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.31	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:6	34.08	2412	1.65	13.46	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.32	15.04	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:6	34.08	2414	1.65	13.44	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.33	15.04	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:6	34.08	2426	1.65	13.45	95	195	Off Idle	71.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.33	15.03	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:6	35.45	2439	1.65	13.44	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.32	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:6	35.45	2421	1.64	13.44	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.32	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:7	35.45	2420	1.64	13.45	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9.32	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:7	35.45	2420	1.64	13.45	95	195	Off Idle	71	0	2	132	944 Turbo	0.67	Rich	1	14.7	-9.32	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:7	35.45	2418	1.64	13.46	95	195	Off Idle	71	0	2	132	944 Turbo	0.66	Rich	1	14.7	-9.32	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:7	35.45	2413	1.64	13.47	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.31	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:7	35.45	2413	1.64	13.47	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.58	Rich	1	14.7	-9.32	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:7	35.45	2408	1.64	13.47	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.34	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:8	35.45	2416	1.64	13.48	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.33	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:8	35.45	2409	1.64	13.46	95	195	Off Idle	71.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.35	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:8	35.45	2409	1.64	13.45	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.35	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:8	35.45	2411	1.64	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.31	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:8	35.45	2393	1.64	13.44	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.38	Lean	1	14.7	-9.34	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:45:8	35.45	2418	1.64	13.44	95	195	Off Idle	72	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.35	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:9	35.45	2418	1.64	13.45	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.31	Lean	1	14.7	-9.36	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:9	35.45	2419	1.64	13.43	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.37	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:9	35.45	2422	1.63	13.45	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.4	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:9	35.45	2431	1.63	13.45	95	195	Off Idle	72	0	2	132	944 Turbo	0.23	Lean	1	14.7	-9.41	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:9	35.45	2422	1.63	13.45	95	195	Off Idle	72	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.42	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:9	35.45	2423	1.63	13.45	95	195	Off Idle	72	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.41	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:45:9	35.45	2421	1.63	13.45	95	195	Off Idle	71.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.41	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:0	35.45	2420	1.63	13.44	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.21	Lean	1	14.7	-9.43	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:0	35.45	2419	1.63	13.43	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.41	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:0	35.45	2417	1.63	13.43	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.39	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:0	35.45	2408	1.63	13.43	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.42	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:0	35.45	2414	1.63	13.43	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.43	Lean	1	14.7	-9.44	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:0	35.45	2406	1.63	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.49	Lean	1	14.7	-9.45	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:1	35.45	2403	1.63	13.45	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.47	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:1	35.45	2403	1.63	13.44	95	195	Off Idle	70.6	0	2	132	944 Turbo	0.6	Lean	1	14.7	-9.46	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:1	35.45	2402	1.63	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.65	Rich	1	14.7	-9.46	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:1	35.45	2404	1.63	13.45	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.68	Rich	1	14.7	-9.45	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:1	35.45	2404	1.63	13.43	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.45	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:1	35.45	2410	1.63	13.43	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.7	Rich	1	14.7	-9.41	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:1	35.45	2410	1.63	13.45	95	195	Off Idle	70.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.42	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:2	35.45	2410	1.63	13.43	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.41	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:2	35.45	2411	1.63	13.44	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.42	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:2	35.45	2431	1.62	13.43	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.46	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:2	35.45	2408	1.62	13.44	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.46	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:2	35.45	2407	1.62	13.42	95	195	Off Idle	70.9	0	2	132	944 Turbo	0.53	Rich	1	14.7	-9.47	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:2	35.45	2400	1.62	13.42	95	195	Off Idle	71.1	0	2	132	944 Turbo	0.47	Lean	1	14.7	-9.51	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:3	35.45	2378	1.62	13.43	95	195	Off Idle	71.2	0	2	132	944 Turbo	0.41	Lean	1	14.7	-9.51	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:3	35.45	2386	1.62	13.44	95	195	Off Idle	71.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.5	15	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:3	35.45	2391	1.62	13.45	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.5	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:3	35.45	2391	1.61	13.46	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.2	Lean	1	14.7	-9.5	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:3	35.45	2392	1.61	13.47	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-9.53	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:46:3	35.45	2392	1.61	13.46	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.55	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:4	35.45	2394	1.6	13.45	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.12	Lean	1	14.7	-9.55	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:4	35.45	2392	1.6	13.44	95	195	Off Idle	71.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:4	35.45	2392	1.6	13.45	95	195	Off Idle	71.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:4	35.45	2394	1.6	13.45	95	195	Off Idle	71.9	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.56	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:4	35.45	2400	1.59	13.46	95	195	Off Idle	72	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.56	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:4	35.45	2400	1.59	13.45	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.57	14.79	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:4	35.45	2402	1.59	13.45	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.59	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:5	35.45	2403	1.58	13.46	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.58	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:5	35.45	2403	1.58	13.46	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.17	Lean	1	14.7	-9.59	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:5	35.45	2400	1.58	13.46	95	195	Off Idle	72	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.59	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:5	35.45	2405	1.58	13.45	95	195	Off Idle	72	0	2	132	944 Turbo	0.29	Lean	1	14.7	-9.62	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:5	35.45	2390	1.57	13.44	95	195	Off Idle	71.8	0	2	132	944 Turbo	0.35	Lean	1	14.7	-9.62	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:5	35.45	2399	1.57	13.44	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.63	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:6	35.45	2410	1.57	13.45	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.64	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:6	35.45	2406	1.57	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.66	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:6	35.45	2406	1.57	13.44	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.55	Rich	1	14.7	-9.64	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:6	35.45	2402	1.57	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.6	Rich	1	14.7	-9.64	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:6	35.45	2405	1.57	13.45	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.63	Rich	1	14.7	-9.61	15.12	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:6	35.45	2405	1.57	13.46	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.6	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:6	35.45	2405	1.57	13.45	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.62	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:7	35.45	2395	1.57	13.47	95	195	Off Idle	71.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.62	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:7	35.45	2406	1.57	13.47	95	195	Off Idle	71.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.66	15.09	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:7	35.45	2406	1.57	13.47	95	195	Off Idle	71.9	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.68	15.08	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:7	35.45	2406	1.56	13.46	95	195	Off Idle	72	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.7	15.06	1.03	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:7	35.45	2407	1.56	13.47	95	195	Off Idle	72	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.71	15.04	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:46:7	35.45	2419	1.56	13.46	95	195	Off Idle	72.2	0	2	132	944 Turbo	0.36	Lean	1	14.7	-9.73	15.02	1.02	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:8	35.45	2413	1.56	13.45	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.3	Lean	1	14.7	-9.73	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:8	35.45	2413	1.56	13.44	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.72	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:8	35.45	2411	1.56	13.44	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.75	15.01	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:8	35.45	2430	1.56	13.44	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.75	14.98	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:8	35.45	2421	1.55	13.44	95	194	Off Idle	72.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.79	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:8	35.45	2408	1.55	13.44	95	194	Off Idle	72.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.8	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:46:9	35.45	2399	1.54	13.44	95	194	Off Idle	72.1	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.82	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:46:9	35.45	2391	1.53	13.44	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.86	14.9	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:46:9	35.45	2398	1.53	13.44	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.88	14.9	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:46:9	35.45	2394	1.52	13.45	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.89	14.9	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:46:9	35.45	2391	1.52	13.45	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.21	Lean	1	14.7	-9.89	14.89	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:46:9	35.45	2391	1.51	13.46	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.93	14.9	1.01	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:46:9	35.45	2388	1.51	13.46	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.93	14.91	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:0	35.45	2388	1.5	13.45	95	194	Off Idle	72.3	0	2	132	944 Turbo	0.41	Lean	1	14.7	-9.95	14.95	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:0	35.45	2405	1.5	13.45	95	194	Off Idle	72.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.96	14.99	1.02	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:0	35.45	2405	1.49	13.44	95	194	Off Idle	72.3	0	2	132	944 Turbo	0.54	Lean	1	14.7	-9.97	15.04	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:0	35.45	2383	1.49	13.45	95	194	Off Idle	72.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.96	15.07	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:0	35.45	2377	1.48	13.44	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.64	Rich	1	14.7	-9.98	15.1	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:0	35.45	2378	1.48	13.45	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.66	Rich	1	14.7	-9.97	15.12	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:1	35.45	2362	1.47	13.46	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.98	15.13	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:1	35.45	2372	1.47	13.45	95	195	Off Idle	72.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.98	15.15	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:1	35.45	2377	1.46	13.45	95	195	Off Idle	72.7	0	2	132	944 Turbo	0.56	Rich	1	14.7	-9.98	15.15	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:1	35.45	2377	1.46	13.45	95	195	Off Idle	72.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.99	15.15	1.03	3.4	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:1	35.45	2401	1.45	13.45	95	195	Off Idle	72.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-10.03	15.16	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:1	35.45	2396	1.45	13.45	95	195	Off Idle	72.7	0	2	132	944 Turbo	0.39	Rich	1	14.7	-10.02	15.13	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:1	35.45	2395	1.45	13.44	95	195	Off Idle	72.9	0	2	132	944 Turbo	0.36	Rich	1	14.7	-10.06	15.12	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:2	35.45	2398	1.45	13.44	95	195	Off Idle	72.9	0	2	132	944 Turbo	0.3	Lean	1	14.6	-10.07	15.1	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:2	35.45	2400	1.44	13.44	95	195	Off Idle	72.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.08	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:2	35.45	2398	1.44	13.45	95	195	Off Idle	72.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.08	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:2	35.45	2390	1.44	13.46	95	195	Off Idle	72.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.07	15.03	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:47:2	35.45	2398	1.44	13.46	95	195	Off Idle	72.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.08	15.01	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:2	35.45	2398	1.43	13.46	95	195	Off Idle	72.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.09	15	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:3	35.45	2396	1.43	13.46	95	194	Off Idle	72.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.11	14.99	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:3	35.45	2395	1.43	13.45	95	194	Off Idle	72.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-10.15	14.95	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:3	35.45	2402	1.42	13.45	95	194	Off Idle	72.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-10.16	14.93	1.02	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:3	35.45	2388	1.42	13.45	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-10.18	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:3	35.45	2382	1.41	13.44	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.22	Rich	1	14.7	-10.2	14.91	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:3	35.45	2379	1.41	13.44	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-10.22	14.9	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:4	35.45	2379	1.4	13.44	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.34	Rich	1	14.7	-10.25	14.91	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:4	35.45	2372	1.4	13.45	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.28	14.92	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:4	35.45	2372	1.39	13.45	95	195	Off Idle	72.1	0	2	132	944 Turbo	0.49	Rich	1	14.7	-10.29	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:47:4	35.45	2369	1.38	13.44	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.32	14.96	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:4	35.45	2368	1.38	13.45	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.61	Rich	1	14.7	-10.33	14.99	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:4	35.45	2371	1.38	13.44	95	195	Off Idle	72.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.36	15.03	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:4	35.45	2372	1.37	13.44	95	195	Off Idle	72.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.38	15.03	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:5	35.45	2376	1.36	13.43	95	195	Off Idle	72.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.4	15.07	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:5	35.45	2382	1.36	13.44	95	195	Off Idle	73	0	2	132	944 Turbo	0.69	Rich	1	14.7	-10.43	15.1	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:5	35.45	2381	1.35	13.45	95	195	Off Idle	73.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.43	15.11	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:5	35.45	2383	1.34	13.46	95	195	Off Idle	73.1	0	2	132	944 Turbo	0.68	Rich	1	14.7	-10.47	15.12	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:5	35.45	2384	1.33	13.46	95	195	Off Idle	73.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.46	15.12	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:5	35.45	2371	1.32	13.46	95	195	Off Idle	73.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10.48	15.12	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:6	35.45	2368	1.31	13.46	95	195	Off Idle	73.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.51	15.12	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:6	35.45	2366	1.31	13.46	95	195	Off Idle	73.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-10.52	15.1	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:6	35.45	2362	1.3	13.45	95	195	Full Load	73.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-10.54	15.08	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:6	35.45	2364	1.29	13.45	95	195	Idle	73.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.58	15.06	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:47:6	35.45	2368	1.28	13.45	95	195	Idle	73.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-10.62	15.05	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:47:6	35.45	2371	1.27	13.45	95	195	Idle	73.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.64	15.04	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:47:6	35.45	2375	1.27	13.45	95	195	Idle	73.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.66	15.03	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:47:7	35.45	2377	1.25	13.45	95	195	Idle	73.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.71	15.02	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:47:7	35.45	2375	1.25	13.45	95	195	Idle	73.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.71	15.01	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:47:7	35.45	2355	1.24	13.47	95	195	Idle	72.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.71	14.99	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:47:7	32.72	2335	1.23	13.46	95	194	Idle	72.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.74	14.97	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:47:7	32.72	2335	1.23	13.45	95	194	Idle	72.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.75	14.96	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:47:7	27.27	2324	1.22	13.45	95	194	Idle	71.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.71	14.94	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:8	21.81	2323	1.22	13.44	95	195	Idle	71.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.71	14.92	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:8	21.81	2320	1.22	13.44	95	195	Idle	71.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.7	14.89	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:8	17.72	2336	1.22	13.45	95	195	Idle	71.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.69	14.87	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:8	17.72	2340	1.21	13.44	95	194	Idle	71.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.68	14.83	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:8	17.72	2336	1.21	13.45	95	194	Idle	71.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.67	14.85	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:8	17.72	2336	1.21	13.45	95	194	Idle	71.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.7	14.86	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:9	17.72	2325	1.2	13.44	95	194	Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.69	14.88	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:9	17.72	2335	1.2	13.44	95	194	Idle	71.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.7	14.91	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:9	17.72	2336	1.2	13.44	95	194	Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.68	14.92	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:9	17.72	2341	1.2	13.44	95	194	Idle	71.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.66	14.95	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:9	17.72	2350	1.2	13.45	95	194	Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.64	15	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:9	17.72	2350	1.2	13.45	95	194	Idle	72.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.6	15.04	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:47:9	17.72	2356	1.2	13.44	95	194	Idle	72.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.58	15.08	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:0	17.72	2357	1.2	13.45	95	194	Idle	72.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.58	15.12	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:0	17.72	2358	1.2	13.45	95	194	Idle	73.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.58	15.13	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:0	17.72	2356	1.2	13.43	95	194	Idle	73.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.58	15.18	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:0	17.72	2352	1.2	13.44	95	194	Idle	73.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.57	15.21	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:0	17.72	2328	1.2	13.45	95	194	Idle	73.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.57	15.23	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:0	17.72	2328	1.2	13.45	95	194	Idle	73.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.57	15.24	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:1	17.72	2338	1.2	13.44	95	194	Idle	73.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.54	15.26	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:1	17.72	2348	1.19	13.46	95	194	Idle	74	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.52	15.28	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:1	17.72	2340	1.19	13.45	95	195	Idle	74	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.51	15.31	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:1	17.72	2329	1.19	13.46	95	195	Idle	74	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.5	15.35	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:1	17.72	2331	1.18	13.46	95	195	Idle	74	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.51	15.21	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:1	17.72	2333	1.18	13.45	95	195	Idle	73.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.49	15.24	1.04	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:1	17.72	2352	1.18	13.45	95	195	Idle	73.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.47	15.28	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:2	17.72	2328	1.18	13.47	95	195	Idle	73.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.49	15.3	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:2	17.72	2340	1.17	13.46	95	194	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	15.35	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:2	17.72	2340	1.17	13.47	95	194	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	15.4	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:2	17.72	2355	1.17	13.46	95	194	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	15.45	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:2	17.72	2337	1.17	13.45	95	195	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	15.51	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:2	17.72	2334	1.17	13.44	95	195	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	15.62	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:3	17.72	2333	1.17	13.45	95	195	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	15.91	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:3	17.72	2327	1.17	13.44	95	194	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	16.05	1.09	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:3	17.72	2323	1.17	13.45	95	194	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	16.26	1.11	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:3	17.72	2323	1.17	13.45	95	194	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	16.55	1.13	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:3	17.72	2321	1.17	13.45	95	194	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	16.92	1.15	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:3	17.72	2316	1.17	13.45	95	194	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	17.34	1.18	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:4	17.72	2308	1.17	13.45	95	194	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	17.77	1.21	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:4	17.72	2315	1.17	13.45	95	195	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	18.21	1.24	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:4	17.72	2315	1.17	13.46	95	195	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	18.82	1.28	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:4	17.72	2333	1.17	13.45	95	194	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	19.2	1.31	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:4	17.72	2326	1.17	13.43	95	194	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	19.55	1.33	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:4	17.72	2312	1.17	13.45	95	194	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	19.84	1.35	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:4	17.72	2322	1.17	13.46	95	194	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.04	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:5	17.72	2322	1.17	13.45	95	194	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.12	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:5	17.72	2322	1.17	13.46	95	194	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:5	17.72	2321	1.17	13.46	95	194	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:5	17.72	2319	1.17	13.46	95	194	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:5	17.72	2313	1.16	13.47	95	194	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:5	17.72	2304	1.16	13.47	95	194	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:48:6	17.72	2299	1.16	13.45	95	194	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:6	17.72	2298	1.16	13.46	95	194	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:6	17.72	2292	1.16	13.46	95	194	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:6	17.72	2272	1.16	13.44	95	194	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:6	17.72	2272	1.16	13.44	95	194	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:6	17.72	2298	1.16	13.45	95	194	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:6	17.72	2289	1.16	13.44	95	194	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:7	17.72	2290	1.16	13.42	95	194	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:7	17.72	2290	1.16	13.44	95	195	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:7	17.72	2290	1.16	13.44	95	195	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:7	17.72	2289	1.16	13.44	95	195	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:7	17.72	2290	1.16	13.44	95	194	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:7	17.72	2292	1.16	13.44	95	194	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:8	17.72	2292	1.16	13.45	95	194	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:8	17.72	2292	1.15	13.44	95	194	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:8	17.72	2292	1.15	13.44	95	194	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:8	17.72	2294	1.15	13.46	95	194	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:8	17.72	2295	1.15	13.44	95	194	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:8	17.72	2295	1.15	13.45	95	194	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:9	17.72	2296	1.15	13.46	95	194	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:9	17.72	2295	1.15	13.45	95	195	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:9	17.72	2275	1.15	13.45	95	195	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:9	17.72	2283	1.15	13.45	95	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:9	17.72	2289	1.14	13.44	95	194	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:9	17.72	2301	1.14	13.44	95	194	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:48:9	17.72	2290	1.14	13.45	95	194	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:0	17.72	2274	1.14	13.45	95	194	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:0	17.72	2270	1.14	13.44	95	194	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.18	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:0	17.72	2270	1.14	13.45	95	194	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.18	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:0	17.72	2265	1.14	13.45	95	194	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:0	17.72	2244	1.13	13.44	95	194	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:0	17.72	2252	1.13	13.44	95	194	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:1	17.72	2272	1.13	13.44	95	194	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:1	17.72	2262	1.13	13.44	95	194	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:1	17.72	2263	1.13	13.45	95	194	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:1	17.72	2263	1.13	13.45	95	194	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:1	17.72	2266	1.12	13.45	95	194	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:1	17.72	2265	1.12	13.45	95	194	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:1	17.72	2265	1.12	13.45	95	194	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:2	17.72	2265	1.12	13.45	95	194	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:2	17.72	2264	1.12	13.44	95	194	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:2	17.72	2264	1.12	13.45	95	194	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:2	17.72	2252	1.12	13.44	95	194	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:2	17.72	2260	1.12	13.43	95	194	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:2	17.72	2259	1.12	13.44	95	194	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:3	17.72	2258	1.11	13.46	95	194	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:3	17.72	2254	1.11	13.46	95	194	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:3	17.72	2252	1.11	13.46	95	194	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:3	17.72	2262	1.11	13.46	95	194	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:3	17.72	2250	1.11	13.45	95	194	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:3	17.72	2249	1.11	13.45	95	194	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:4	17.72	2240	1.11	13.46	95	194	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:4	17.72	2249	1.11	13.45	95	194	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:4	17.72	2264	1.11	13.44	95	194	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:4	17.72	2245	1.11	13.45	95	194	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:4	17.72	2244	1.11	13.45	95	194	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:4	17.72	2244	1.11	13.46	95	194	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:4	17.72	2241	1.11	13.44	95	194	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:49:5	17.72	2241	1.11	13.45	95	194	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:5	17.72	2232	1.11	13.46	95	194	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:5	17.72	2237	1.11	13.46	95	195	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:5	17.72	2253	1.11	13.46	95	195	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:5	17.72	2253	1.1	13.45	95	195	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:5	17.72	2235	1.1	13.45	95	194	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:6	17.72	2217	1.1	13.45	95	194	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:6	17.72	2224	1.1	13.44	95	194	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:6	17.72	2231	1.1	13.44	95	194	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:6	17.72	2228	1.1	13.45	95	194	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:6	17.72	2228	1.1	13.45	95	194	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:6	17.72	2226	1.1	13.44	95	194	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:6	17.72	2226	1.1	13.44	95	194	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:7	17.72	2209	1.1	13.45	95	194	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:7	17.72	2217	1.1	13.45	95	194	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:7	17.72	2225	1.09	13.45	95	194	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:7	17.72	2224	1.09	13.47	95	194	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:7	17.72	2215	1.09	13.48	95	194	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:7	17.72	2222	1.09	13.47	95	194	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:8	17.72	2221	1.09	13.46	95	194	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:8	17.72	2229	1.09	13.43	95	194	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:8	17.72	2220	1.08	13.43	95	194	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:8	17.72	2212	1.08	13.44	95	194	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:8	17.72	2212	1.08	13.45	95	194	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:8	17.72	2209	1.08	13.44	95	194	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:9	17.72	2215	1.08	13.45	95	194	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:9	17.72	2249	1.08	13.45	95	194	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:9	17.72	2232	1.07	13.44	95	194	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:9	17.72	2206	1.07	13.44	95	194	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:9	17.72	2211	1.07	13.44	95	194	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:9	17.72	2212	1.07	13.45	95	194	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:49:9	17.72	2220	1.07	13.45	95	194	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:0	17.72	2212	1.07	13.45	95	194	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:0	17.72	2212	1.07	13.45	95	194	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:0	17.72	2212	1.06	13.46	95	194	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:0	17.72	2193	1.06	13.46	95	194	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:0	17.72	2208	1.06	13.46	95	194	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:0	17.72	2203	1.06	13.46	95	194	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:1	17.72	2203	1.06	13.45	95	194	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:1	17.72	2200	1.06	13.43	95	194	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:1	17.72	2199	1.06	13.42	95	194	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:1	17.72	2195	1.06	13.42	95	194	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:1	17.72	2174	1.06	13.43	95	194	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:1	17.72	2188	1.06	13.44	95	194	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:1	17.72	2188	1.05	13.46	95	194	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:2	17.72	2186	1.05	13.46	95	194	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:2	17.72	2186	1.05	13.44	95	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:2	17.72	2188	1.05	13.43	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:2	17.72	2186	1.05	13.43	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:2	17.72	2186	1.05	13.44	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:2	17.72	2186	1.05	13.45	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:3	17.72	2188	1.05	13.45	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:3	17.72	2189	1.05	13.45	95	194	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:3	17.72	2191	1.05	13.42	95	194	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:3	17.72	2191	1.04	13.42	95	194	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:3	17.72	2190	1.04	13.41	95	194	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:3	17.72	2188	1.04	13.42	95	195	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:4	17.72	2186	1.04	13.45	95	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:50:4	17.72	2181	1.04	13.45	95	195	Idle	82.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:4	17.72	2178	1.04	13.45	95	194	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:4	17.72	2178	1.04	13.44	95	194	Idle	82.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:4	17.72	2174	1.04	13.44	95	194	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:4	17.72	2171	1.04	13.44	95	194	Idle	82.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:4	17.72	2167	1.04	13.44	95	194	Idle	82.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:5	17.72	2167	1.04	13.44	95	194	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:5	17.72	2166	1.04	13.42	95	194	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:5	17.72	2166	1.04	13.43	95	194	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:5	17.72	2166	1.04	13.43	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:5	17.72	2166	1.04	13.44	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:5	17.72	2167	1.03	13.46	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:6	17.72	2166	1.03	13.46	95	195	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:6	17.72	2166	1.03	13.45	95	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:6	17.72	2166	1.03	13.45	95	195	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:6	17.72	2166	1.03	13.45	95	194	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:6	17.72	2166	1.03	13.43	95	194	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:6	17.72	2163	1.03	13.44	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:6	17.72	2163	1.03	13.44	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:7	17.72	2162	1.03	13.44	95	194	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:7	17.72	2162	1.03	13.43	95	194	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:7	17.72	2159	1.03	13.43	95	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:7	17.72	2158	1.03	13.42	95	194	Idle	83.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:7	17.72	2158	1.03	13.42	95	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:7	17.72	2156	1.02	13.42	95	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:8	17.72	2155	1.02	13.43	95	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:8	17.72	2155	1.02	13.44	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:8	17.72	2154	1.02	13.44	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:8	17.72	2153	1.02	13.47	95	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:8	17.72	2150	1.02	13.46	95	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:8	17.72	2150	1.02	13.45	95	194	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:9	17.72	2150	1.02	13.44	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:9	17.72	2150	1.02	13.42	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:9	17.72	2150	1.02	13.43	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:9	17.72	2148	1.02	13.43	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:9	17.72	2143	1.01	13.43	95	194	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:9	17.72	2143	1.01	13.43	95	194	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:50:9	17.72	2136	1.01	13.43	95	194	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:0	17.72	2130	1.01	13.42	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:0	17.72	2108	1.01	13.43	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:0	17.72	2115	1.01	13.43	95	194	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:0	17.72	2118	1.01	13.43	95	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:0	17.72	2118	1.01	13.44	95	194	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:0	17.72	2119	1.01	13.43	95	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:1	17.72	2119	1.01	13.43	95	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:1	17.72	2122	1.01	13.45	95	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:1	17.72	2124	1.01	13.45	95	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:1	17.72	2126	1.01	13.47	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:1	17.72	2146	1.01	13.46	95	194	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:1	17.72	2130	1.01	13.44	95	194	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:1	17.72	2130	1.01	13.45	95	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:2	17.72	2131	1.01	13.44	95	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:2	17.72	2112	1.01	13.42	95	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:2	17.72	2128	1.01	13.43	95	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:2	17.72	2126	1.01	13.43	95	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:2	17.72	2123	1.01	13.43	95	195	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:2	17.72	2121	1.01	13.44	95	195	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:3	17.72	2120	1.01	13.46	95	195	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:51:3	17.72	2117	1.01	13.47	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:3	17.72	2115	1.01	13.47	95	194	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:3	17.72	2111	1.01	13.48	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:3	17.72	2111	1.01	13.47	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:3	17.72	2108	1.01	13.46	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:4	17.72	2111	1.01	13.44	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:4	17.72	2109	1.01	13.43	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:4	17.72	2107	1.01	13.42	95	194	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:4	17.72	2106	1.01	13.42	95	194	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:4	17.72	2105	1.01	13.41	95	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:4	17.72	2105	1.01	13.41	95	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:4	17.72	2101	1.01	13.41	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:5	17.72	2099	1.01	13.43	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:5	17.72	2098	1	13.44	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:5	17.72	2097	1	13.44	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:5	17.72	2096	1	13.46	95	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:5	17.72	2094	1	13.47	95	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:5	17.72	2094	1	13.48	95	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:6	17.72	2095	1.01	13.48	95	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:6	17.72	2096	1.01	13.48	95	194	Idle	84.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:6	17.72	2097	1.01	13.48	95	194	Idle	84.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:6	17.72	2096	1.01	13.47	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:6	17.72	2095	1.01	13.45	95	194	Idle	84.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:6	17.72	2095	1.01	13.44	95	194	Idle	84.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:6	17.72	2094	1.01	13.43	95	194	Idle	84	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:7	17.72	2091	1.01	13.43	95	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:7	17.72	2088	1.01	13.44	95	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:7	17.72	2088	1.01	13.45	95	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:7	17.72	2086	1.01	13.46	95	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:7	17.72	2085	1.01	13.47	95	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:7	17.72	2084	1.01	13.47	95	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:8	17.72	2084	1.01	13.47	95	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:8	17.72	2083	1.01	13.46	95	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:8	17.72	2084	1.01	13.45	95	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:8	17.72	2084	1.01	13.44	95	194	Idle	84.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:8	17.72	2083	1.01	13.44	95	194	Idle	84.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:8	17.72	2081	1.01	13.44	95	194	Idle	84.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:9	17.72	2080	1.01	13.45	95	194	Idle	84.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:9	17.72	2076	1.01	13.46	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:9	17.72	2072	1.01	13.45	95	194	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:9	17.72	2070	1.01	13.44	95	194	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:9	17.72	2068	1.01	13.43	95	195	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:9	17.72	2065	1.01	13.43	95	195	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:51:9	17.72	2064	1.01	13.42	95	195	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:0	17.72	2061	1	13.44	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:0	17.72	2060	1	13.43	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:0	17.72	2052	1	13.41	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:0	17.72	2059	1	13.4	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:0	17.72	2066	1	13.4	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:0	17.72	2059	1	13.38	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:1	17.72	2059	1	13.39	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:1	17.72	2059	1	13.41	95	194	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:1	17.72	2060	1	13.42	95	194	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:1	17.72	2060	1	13.43	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:1	17.72	2058	1	13.42	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:1	17.72	2041	1	13.42	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:1	17.72	2055	1	13.42	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:2	17.72	2062	1	13.41	95	194	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:52:2	17.72	2053	1	13.4	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:2	17.72	2051	1	13.41	95	194	Idle	85.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:2	17.72	2049	1	13.39	95	194	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:2	17.72	2049	1	13.38	95	194	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:2	17.72	2040	1	13.37	95	194	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:3	17.72	2046	1	13.37	95	194	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:3	17.72	2060	1	13.37	95	194	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:3	17.72	2052	1	13.37	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:3	17.72	2026	1	13.36	95	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:3	17.72	2040	1	13.36	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:3	17.72	2038	1	13.36	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:4	17.72	2037	1	13.36	95	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:4	17.72	2036	1	13.37	95	194	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:4	17.72	2036	1	13.37	95	194	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:4	17.72	2036	1	13.37	95	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:4	17.72	2033	1	13.37	95	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:4	17.72	2031	1	13.37	95	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:4	17.72	2031	1	13.36	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:5	17.72	2026	1	13.37	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:5	17.72	2021	1	13.38	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:5	17.72	2019	1	13.39	95	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:5	17.72	2018	1	13.4	95	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:5	17.72	2012	1	13.41	96	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:5	17.72	2011	1	13.41	96	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:6	17.72	2010	1	13.41	96	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:6	17.72	2006	1	13.41	96	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:6	17.72	2001	1	13.41	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:6	17.72	1996	1	13.42	95	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:6	17.72	1974	1	13.42	95	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:6	17.72	1956	1	13.43	95	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:6	17.72	1946	1	13.42	95	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:7	17.72	1915	1	13.41	95	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:7	17.72	1875	1	13.41	95	194	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:7	17.72	1871	1	13.41	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:7	17.72	1827	1	13.4	95	194	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:7	17.72	1827	1.01	13.38	95	194	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:7	17.72	1792	1.01	13.39	95	194	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:8	17.72	1770	1.01	13.38	95	194	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:8	17.72	1759	1.02	13.36	95	194	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:8	17.72	1748	1.02	13.38	95	194	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:8	17.72	1712	1.03	13.38	95	194	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:8	17.72	1689	1.04	13.39	95	194	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.24	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:8	17.72	1689	1.04	13.38	95	194	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:9	17.72	1646	1.05	13.38	95	194	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:9	17.72	1641	1.07	13.38	95	194	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:9	17.72	1629	1.08	13.39	95	194	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:9	17.72	1592	1.09	13.39	95	194	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:9	17.72	1565	1.1	13.4	95	194	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:9	17.72	1565	1.11	13.39	95	194	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:52:9	17.72	1546	1.12	13.39	95	194	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.22	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:53:0	17.72	1499	1.13	13.4	95	195	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.45	20.22	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:53:0	17.72	1491	1.14	13.4	95	195	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.37	20.23	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:53:0	17.72	1478	1.15	13.39	95	195	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.27	20.23	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:53:0	17.72	1453	1.16	13.38	95	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.18	20.23	1.38	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:53:0	17.72	1427	1.18	13.38	95	194	Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.09	20.23	1.38	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:53:0	17.72	1427	1.19	13.37	95	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.98	20.23	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:53:1	17.72	1397	1.2	13.37	95	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.9	20.23	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:53:1	19.09	1350	1.21	13.37	95	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.82	20.23	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:53:1	19.09	1350	1.22	13.39	95	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.71	20.23	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:53:1	19.09	1322	1.22	13.39	95	194	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.61	20.23	1.38	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:25:53:1	17.72	1296	1.23	13.4	95	194	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.58	20.23	1.38	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:25:53:1	17.72	1296	1.24	13.4	95	194	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.42	20.23	1.38	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:25:53:1	17.72	1275	1.25	13.39	95	194	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.33	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:2	17.72	1256	1.25	13.39	95	194	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.27	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:2	17.72	1237	1.25	13.39	95	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.24	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:2	17.72	1223	1.26	13.39	95	194	Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.05	20.25	1.38	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:25:53:2	16.36	1206	1.26	13.4	95	194	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.98	20.25	1.38	4.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:25:53:2	16.36	1202	1.26	13.4	95	195	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.89	20.25	1.38	4.7	2.6	ON	28 Pin	OFF	Removed	Disabled
03:25:53:2	16.36	1202	1.26	13.4	95	195	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.84	20.26	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:53:3	16.36	1210	1.26	13.41	95	195	Idle	69.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.77	20.25	1.38	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:53:3	16.36	1217	1.26	13.4	95	195	Idle	69.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.7	20.25	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:53:3	16.36	1217	1.26	13.39	95	195	Idle	70.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.68	20.24	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:53:3	16.36	1229	1.25	13.39	95	194	Idle	71.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.67	20.24	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:53:3	16.36	1242	1.25	13.38	95	194	Idle	72.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.68	20.23	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:53:3	16.36	1265	1.24	13.38	95	194	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.71	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:4	16.36	1265	1.24	13.38	95	194	Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.75	20.21	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:4	16.36	1262	1.23	13.39	95	194	Idle	76.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.75	20.21	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:4	16.36	1258	1.22	13.37	95	194	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.79	20.2	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:53:4	16.36	1258	1.2	13.38	95	195	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.82	20.2	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:53:4	13.63	1268	1.19	13.39	95	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.88	20.2	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:53:4	13.63	1279	1.17	13.39	95	195	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.97	20.2	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:4	13.63	1279	1.17	13.39	95	194	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.06	20.2	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:5	13.63	1273	1.15	13.4	95	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.12	20.2	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:5	13.63	1281	1.13	13.38	95	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.24	20.21	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:5	13.63	1268	1.12	13.38	95	194	Idle	85.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.33	20.21	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:5	14.99	1268	1.1	13.38	95	194	Idle	86.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.38	20.21	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:5	14.99	1251	1.09	13.37	95	194	Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.41	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:5	14.99	1238	1.08	13.38	95	194	Idle	87.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.44	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:6	13.63	1238	1.06	13.4	95	194	Idle	87.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.45	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:6	13.63	1233	1.05	13.4	95	194	Idle	87.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.49	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:6	13.63	1233	1.04	13.4	95	194	Idle	87.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.49	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:6	14.99	1223	1.03	13.4	95	194	Idle	88	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.52	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:6	14.99	1204	1.02	13.39	95	194	Idle	88.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.53	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:53:6	14.99	1193	1.01	13.39	95	194	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:6	14.99	1190	1	13.4	95	194	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.56	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:7	14.99	1190	0.99	13.4	95	194	Idle	88.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.6	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:7	14.99	1170	0.99	13.41	95	194	Idle	89	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.6	20.21	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:7	14.99	1161	0.98	13.41	95	194	Idle	89.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:7	14.99	1161	0.98	13.4	95	194	Idle	89.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.61	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:7	14.99	1151	0.98	13.39	95	195	Idle	89.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.62	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:7	14.99	1133	0.97	13.4	95	195	Idle	89.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.59	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:8	14.99	1133	0.97	13.39	95	194	Idle	90.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.58	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:8	14.99	1126	0.96	13.39	95	194	Idle	90.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.6	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:8	14.99	1118	0.96	13.39	95	194	Idle	90.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.58	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:8	13.63	1119	0.96	13.39	95	194	Idle	90.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.58	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:8	13.63	1119	0.96	13.4	95	194	Idle	90.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.57	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:8	13.63	1110	0.96	13.38	95	194	Idle	90.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.54	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:9	13.63	1103	0.95	13.4	95	194	Idle	91	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.55	20.15	1.37	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:9	13.63	1103	0.95	13.39	95	194	Idle	91.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.53	20.06	1.37	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:9	13.63	1103	0.95	13.38	95	194	Idle	91.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.53	19.93	1.36	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:9	13.63	1135	0.94	13.4	95	195	Idle	91.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.53	19.79	1.35	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:9	13.63	1135	0.94	13.39	95	195	Idle	91.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	19.51	1.33	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:9	13.63	1147	0.93	13.39	95	195	Idle	92	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.53	19.39	1.32	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:53:9	13.63	1165	0.93	13.39	95	195	Idle	92.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.54	19.15	1.3	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:54:0	10.9	1171	0.93	13.4	95	195	Idle	92.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.59	18.88	1.29	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:25:54:0	10.9	1171	0.92	13.4	95	195	Idle	92.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.62	18.59	1.27	4.3	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:54:0	10.9	1195	0.92	13.4	95	194	Idle	92.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.64	18.3	1.25	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:54:0	9.54	1230	0.92	13.4	95	194	Idle	93.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.69	18.04	1.23	4.3	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:54:0	9.54	1230	0.91	13.4	95	194	Idle	93.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.71	17.81	1.21	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:25:54:0	9.54	1238	0.91	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.72	17.59	1.2	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:54:1	9.54	1253	0.91	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.75	17.39	1.18	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:54:1	9.54	1253	0.91	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.79	17.23	1.17	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:54:1	9.54	1271	0.9	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.87	17.07	1.16	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:54:1	9.54	1302	0.9	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.94	16.98	1.16	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:54:1	9.54	1302	0.9	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.02	16.89	1.15	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:54:1	9.54	1330	0.89	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.1	16.86	1.15	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:54:1	9.54	1330	0.89	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.13	16.84	1.15	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:54:2	9.54	1357	0.89	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.21	16.82	1.15	4.2	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:54:2	10.9	1387	0.89	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.27	16.81	1.15	4.1	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:54:2	10.9	1408	0.89	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.33	16.82	1.15	4.1	1.7	ON	28 Pin	OFF	Removed	Disabled
03:25:54:2	10.9	1415	0.88	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.36	16.81	1.15	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:54:2	10.9	1434	0.88	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.39	16.8	1.14	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:54:2	10.9	1458	0.88	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	16.8	1.14	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:54:3	10.9	1465	0.88	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.48	16.79	1.14	4.2	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:54:3	12.27	1482	0.88	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.56	16.76	1.14	4.1	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:54:3	12.27	1512	0.88	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.61	16.73	1.14	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:54:3	12.27	1533	0.88	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.69	16.69	1.14	4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:25:54:3	12.27	1575	0.88	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.76	16.64	1.13	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:3	12.27	1575	0.88	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.81	16.57	1.13	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:4	13.63	1572	0.87	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.88	16.53	1.13	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:4	13.63	1593	0.87	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.96	16.45	1.12	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:4	13.63	1627	0.87	13.38	95	195	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.01	16.38	1.12	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:4	13.63	1632	0.87	13.37	95	195	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.08	16.29	1.11	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:4	13.63	1660	0.87	13.36	95	195	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.13	16.2	1.1	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:4	13.63	1677	0.87	13.36	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.2	16.12	1.1	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:4	13.63	1695	0.87	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.29	15.97	1.09	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:5	13.63	1695	0.87	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.31	15.93	1.09	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:25:54:5	14.99	1728	0.87	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.39	15.81	1.08	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:5	14.99	1750	0.87	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.43	15.75	1.07	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:5	14.99	1750	0.87	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.51	15.67	1.07	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:5	14.99	1780	0.87	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.53	15.62	1.06	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:5	14.99	1784	0.87	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.57	15.59	1.06	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:6	14.99	1793	0.87	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.59	15.57	1.06	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:6	14.99	1817	0.87	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.61	15.57	1.06	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:6	14.99	1834	0.86	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.6	15.58	1.06	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:6	14.99	1857	0.86	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.6	15.6	1.06	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:6	17.72	1867	0.86	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.6	15.63	1.06	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:6	17.72	1883	0.86	13.36	95	194	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.6	15.65	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:6	17.72	1892	0.86	13.37	95	194	Idle	92.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.61	15.69	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:7	17.72	1933	0.86	13.37	95	194	Idle	92.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.65	15.75	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:7	17.72	1950	0.86	13.38	95	194	Idle	91.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.71	15.8	1.08	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:7	17.72	1976	0.86	13.4	95	194	Idle	91.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.75	15.85	1.08	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:7	17.72	1976	0.87	13.41	95	194	Idle	90.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.77	15.89	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:7	17.72	2000	0.87	13.41	95	194	Idle	90.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.8	15.94	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:7	17.72	2025	0.87	13.41	95	194	Idle	89.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.79	15.97	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:8	17.72	2025	0.87	13.4	95	194	Idle	89.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.78	16	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:8	17.72	2056	0.88	13.39	96	194	Idle	88.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.77	16.03	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:8	17.72	2065	0.88	13.38	96	195	Idle	87.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.72	16.06	1.09	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:8	17.72	2084	0.88	13.38	96	195	Idle	87.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.74	16.09	1.1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:8	17.72	2084	0.89	13.41	95	195	Idle	86.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.73	16.12	1.1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:8	17.72	2116	0.89	13.42	95	194	Idle	86.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.75	16.13	1.1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:9	17.72	2153	0.9	13.41	95	194	Idle	85.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.75	16.14	1.1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:9	17.72	2169	0.9	13.42	95	194	Idle	85.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.78	16.15	1.1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:9	17.72	2169	0.91	13.41	95	194	Idle	85.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.77	16.18	1.1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:54:9	17.72	2192	0.91	13.4	95	194	Idle	85.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.76	16.21	1.1	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:9	17.72	2232	0.92	13.39	95	194	Idle	85.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.74	16.23	1.11	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:9	17.72	2232	0.92	13.39	95	194	Idle	85.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.74	16.27	1.11	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:54:9	17.72	2246	0.92	13.39	95	194	Idle	85.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.74	16.31	1.11	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:0	17.72	2262	0.93	13.4	95	194	Idle	85.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.77	16.37	1.12	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:0	17.72	2270	0.94	13.4	95	194	Idle	84.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.81	16.48	1.12	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:0	17.72	2316	0.94	13.39	95	194	Idle	83.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.81	16.53	1.13	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:0	17.72	2328	0.95	13.4	95	194	Idle	83.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.79	16.69	1.14	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:0	17.72	2349	0.96	13.41	95	194	Idle	82.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.81	16.79	1.14	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:0	17.72	2349	0.96	13.4	95	194	Idle	82.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.8	16.88	1.15	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:1	17.72	2395	0.97	13.4	95	194	Idle	81.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.79	16.99	1.16	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:1	17.72	2391	0.97	13.39	95	194	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	17.1	1.16	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:1	17.72	2398	0.98	13.39	95	194	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	17.19	1.17	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:1	17.72	2425	0.99	13.38	95	194	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	17.27	1.18	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:1	17.72	2444	0.99	13.4	95	194	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.8	17.34	1.18	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:1	17.72	2460	1	13.39	95	194	Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	17.41	1.19	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:1	17.72	2466	1.02	13.41	95	194	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.8	17.5	1.19	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:2	17.72	2503	1.03	13.41	95	194	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.8	17.5	1.19	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:2	19.09	2514	1.04	13.41	95	194	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	17.71	1.21	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:2	19.09	2506	1.05	13.41	95	194	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	17.99	1.23	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:2	19.09	2500	1.06	13.42	95	194	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	18.27	1.24	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:2	19.09	2498	1.08	13.42	95	194	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	18.69	1.27	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:2	19.09	2488	1.09	13.41	95	194	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	18.96	1.29	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:3	19.09	2475	1.1	13.4	95	194	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	19.24	1.31	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:3	19.09	2470	1.11	13.39	95	194	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	19.51	1.33	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:3	19.09	2453	1.13	13.39	95	194	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	19.77	1.35	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:3	19.09	2411	1.15	13.38	95	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.11	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:3	19.09	2420	1.16	13.39	95	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:3	19.09	2415	1.17	13.41	95	194	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:4	19.09	2400	1.18	13.41	95	194	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:4	19.09	2393	1.19	13.4	95	194	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:4	19.09	2393	1.2	13.41	95	194	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:4	17.72	2371	1.21	13.41	95	194	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:4	17.72	2390	1.22	13.4	95	194	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:4	17.72	2394	1.23	13.41	95	194	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:4	17.72	2396	1.23	13.4	95	194	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:5	17.72	2401	1.24	13.4	95	194	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:5	17.72	2408	1.25	13.4	95	194	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:5	17.72	2408	1.26	13.41	95	194	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:5	17.72	2410	1.27	13.4	95	194	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:5	17.72	2410	1.27	13.41	95	194	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:5	17.72	2404	1.28	13.4	95	194	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:6	17.72	2402	1.28	13.41	95	194	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:6	17.72	2401	1.29	13.41	95	194	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:6	17.72	2383	1.29	13.4	95	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:6	17.72	2383	1.29	13.41	95	194	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:6	17.72	2371	1.29	13.4	95	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:6	17.72	2362	1.29	13.41	95	194	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:6	17.72	2362	1.28	13.4	95	194	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:7	17.72	2358	1.28	13.4	95	194	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:7	17.72	2351	1.28	13.4	95	194	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:7	17.72	2352	1.28	13.41	95	194	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:7	17.72	2349	1.28	13.41	95	194	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:7	17.72	2348	1.27	13.41	95	194	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:7	17.72	2345	1.27	13.41	95	194	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:8	17.72	2345	1.26	13.41	95	194	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:8	17.72	2345	1.26	13.41	95	194	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:8	17.72	2341	1.25	13.41	95	194	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:55:8	17.72	2340	1.25	13.41	95	194	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:8	17.72	2336	1.24	13.4	95	194	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:8	17.72	2330	1.24	13.39	95	194	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:9	17.72	2330	1.23	13.39	95	195	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:9	17.72	2323	1.23	13.39	95	195	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:9	17.72	2313	1.23	13.39	95	194	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:9	17.72	2304	1.22	13.4	95	194	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:9	17.72	2303	1.22	13.41	95	194	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:9	17.72	2295	1.22	13.39	95	194	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:55:9	17.72	2291	1.21	13.39	95	194	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:0	17.72	2289	1.21	13.4	95	194	Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:0	17.72	2284	1.21	13.4	95	194	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:0	17.72	2279	1.2	13.39	95	194	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:0	17.72	2278	1.2	13.4	95	194	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:0	17.72	2276	1.2	13.39	95	194	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:0	17.72	2274	1.2	13.4	95	194	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:1	17.72	2274	1.19	13.41	95	194	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:1	17.72	2270	1.19	13.41	95	194	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:1	17.72	2267	1.19	13.4	95	194	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:1	17.72	2265	1.19	13.41	95	194	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:1	17.72	2261	1.18	13.41	95	194	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:1	17.72	2257	1.18	13.4	95	194	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:1	17.72	2256	1.18	13.41	96	194	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:2	17.72	2246	1.18	13.41	96	194	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:2	17.72	2221	1.17	13.39	96	194	Idle	76.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:2	17.72	2233	1.17	13.4	96	194	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:2	17.72	2231	1.17	13.41	96	194	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:2	17.72	2224	1.17	13.4	96	194	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:2	17.72	2216	1.16	13.4	95	194	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:3	17.72	2216	1.16	13.4	95	194	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:3	17.72	2210	1.16	13.41	95	194	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:3	17.72	2192	1.15	13.39	95	194	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:3	17.72	2199	1.15	13.39	95	194	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:3	17.72	2219	1.15	13.39	95	194	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:3	17.72	2198	1.14	13.39	95	194	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:4	17.72	2178	1.14	13.39	95	194	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:4	17.72	2184	1.14	13.41	96	194	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:4	17.72	2188	1.14	13.4	96	194	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:4	17.72	2184	1.13	13.39	96	194	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:4	17.72	2178	1.13	13.38	96	194	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:4	17.72	2178	1.13	13.38	96	194	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:4	17.72	2173	1.13	13.39	96	194	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:5	17.72	2166	1.12	13.4	95	194	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:5	17.72	2164	1.12	13.41	95	194	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:5	17.72	2158	1.12	13.41	95	194	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:5	17.72	2155	1.11	13.42	95	194	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:5	17.72	2152	1.11	13.42	95	194	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:5	17.72	2144	1.11	13.41	95	194	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:6	17.72	2140	1.1	13.41	95	194	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:6	17.72	2140	1.1	13.39	95	194	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:6	17.72	2135	1.1	13.37	95	194	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:6	17.72	2131	1.1	13.37	95	194	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:6	17.72	2128	1.09	13.38	95	194	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:6	17.72	2118	1.09	13.39	95	194	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:6	17.72	2122	1.08	13.4	95	194	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:7	17.72	2118	1.08	13.41	95	194	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:7	17.72	2113	1.08	13.41	95	194	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:7	17.72	2112	1.08	13.41	95	194	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:56:7	17.72	2107	1.07	13.4	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:7	17.72	2103	1.07	13.39	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:7	17.72	2102	1.07	13.37	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:8	17.72	2097	1.06	13.38	95	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:8	17.72	2094	1.06	13.39	95	194	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:8	17.72	2086	1.06	13.4	95	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:8	17.72	2086	1.06	13.4	95	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:8	17.72	2079	1.05	13.41	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:8	17.72	2079	1.05	13.41	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:9	17.72	2076	1.05	13.41	95	194	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:9	17.72	2072	1.05	13.41	95	194	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:9	17.72	2069	1.05	13.41	95	194	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:9	17.72	2068	1.05	13.42	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:9	17.72	2049	1.05	13.42	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:9	17.72	2061	1.04	13.42	96	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:56:9	17.72	2060	1.04	13.42	96	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:0	17.72	2054	1.04	13.42	96	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:0	17.72	2066	1.04	13.42	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:0	17.72	2048	1.04	13.42	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:0	17.72	2046	1.04	13.42	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:0	17.72	2026	1.04	13.43	95	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:0	17.72	2026	1.04	13.43	95	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:1	17.72	2035	1.04	13.43	95	194	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:1	17.72	2029	1.04	13.43	95	194	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:1	17.72	2026	1.04	13.43	95	194	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:1	17.72	2024	1.04	13.42	95	194	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:1	17.72	2018	1.04	13.43	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:1	17.72	2015	1.03	13.43	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:1	17.72	2013	1.03	13.42	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:2	17.72	2006	1.03	13.42	95	194	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:2	17.72	2002	1.03	13.42	95	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:2	17.72	2002	1.03	13.41	95	195	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:2	17.72	1999	1.03	13.41	95	195	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:2	17.72	1996	1.03	13.41	95	194	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:2	17.72	1992	1.03	13.4	95	194	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:3	17.72	1992	1.03	13.4	95	194	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:3	17.72	1981	1.03	13.4	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:3	17.72	1982	1.03	13.39	95	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:3	17.72	1994	1.03	13.38	95	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:3	17.72	1986	1.03	13.37	95	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:3	17.72	1972	1.03	13.37	95	194	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:4	17.72	1970	1.03	13.36	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:4	17.72	1968	1.02	13.36	96	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:4	17.72	1964	1.02	13.36	96	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:4	17.72	1961	1.02	13.37	96	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:4	17.72	1952	1.02	13.36	95	194	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:4	17.72	1956	1.02	13.36	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:4	17.72	1954	1.02	13.35	95	194	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:5	17.72	1950	1.02	13.36	95	194	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:5	17.72	1950	1.02	13.36	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:5	17.72	1946	1.02	13.36	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:5	17.72	1942	1.02	13.37	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:5	17.72	1942	1.02	13.37	95	194	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:5	17.72	1936	1.02	13.37	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:6	17.72	1935	1.02	13.39	95	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:6	17.72	1929	1.02	13.4	95	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:6	17.72	1929	1.02	13.41	95	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:6	17.72	1926	1.02	13.42	95	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:57:6	17.72	1915	1.02	13.41	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:6	17.72	1915	1.02	13.39	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:6	17.72	1916	1.02	13.38	95	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:7	17.72	1909	1.02	13.36	95	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:7	17.72	1909	1.02	13.36	95	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:7	17.72	1905	1.01	13.36	95	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:7	17.72	1901	1.01	13.37	95	194	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:7	17.72	1901	1.01	13.37	95	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:7	17.72	1895	1.01	13.38	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.25	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:8	17.72	1890	1.01	13.39	95	194	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:8	17.72	1886	1.02	13.4	95	194	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:8	17.72	1886	1.02	13.39	95	194	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:8	17.72	1880	1.02	13.39	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:8	17.72	1877	1.02	13.4	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:8	17.72	1877	1.02	13.4	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:9	17.72	1873	1.02	13.39	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:9	17.72	1869	1.02	13.37	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:9	17.72	1869	1.02	13.38	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:9	17.72	1865	1.02	13.39	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:9	17.72	1864	1.02	13.41	95	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:9	17.72	1856	1.02	13.42	96	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:57:9	17.72	1856	1.02	13.43	96	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:0	17.72	1848	1.02	13.42	96	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:0	17.72	1827	1.02	13.41	95	194	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:0	17.72	1827	1.03	13.4	95	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:0	17.72	1832	1.03	13.4	95	194	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:0	17.72	1824	1.03	13.38	95	194	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:0	17.72	1811	1.03	13.38	95	194	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:1	17.72	1811	1.03	13.39	95	194	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:1	17.72	1813	1.03	13.38	95	194	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:1	17.72	1805	1.03	13.37	95	194	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:1	17.72	1805	1.03	13.38	95	194	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:1	17.72	1802	1.02	13.39	96	194	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:1	17.72	1799	1.02	13.38	96	194	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:1	17.72	1797	1.02	13.38	96	194	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:2	17.72	1791	1.02	13.39	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:2	17.72	1785	1.02	13.39	95	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:2	17.72	1785	1.02	13.38	96	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:2	17.72	1776	1.02	13.38	96	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:2	17.72	1767	1.02	13.39	96	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:2	17.72	1760	1.02	13.39	96	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:3	17.72	1760	1.02	13.39	96	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:3	17.72	1752	1.02	13.4	96	194	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:3	17.72	1744	1.02	13.4	95	194	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:3	17.72	1744	1.02	13.4	95	194	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:3	17.72	1739	1.02	13.4	95	194	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:3	17.72	1735	1.02	13.4	95	194	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:4	17.72	1733	1.02	13.4	95	194	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:4	17.72	1728	1.02	13.4	95	194	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.2	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:4	17.72	1714	1.02	13.38	95	194	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.19	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:4	17.72	1699	1.02	13.38	95	194	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.19	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:4	17.72	1690	1.02	13.39	95	194	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.19	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:4	17.72	1670	1.02	13.41	96	194	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.2	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:4	17.72	1625	1.02	13.39	96	194	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.2	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:5	17.72	1625	1.02	13.37	96	194	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.21	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:5	17.72	1615	1.03	13.38	95	194	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:5	17.72	1591	1.03	13.37	95	194	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:5	17.72	1591	1.03	13.38	95	194	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:58:5	17.72	1554	1.03	13.38	95	194	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.22	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:5	17.72	1543	1.03	13.38	95	194	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.22	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:6	17.72	1505	1.03	13.38	95	194	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:6	17.72	1498	1.04	13.39	95	194	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.24	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:6	17.72	1466	1.04	13.39	95	194	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:6	17.72	1439	1.05	13.4	95	194	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	4.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:6	17.72	1439	1.05	13.39	96	194	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	20.23	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:6	17.72	1402	1.06	13.38	96	194	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.23	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:6	19.09	1396	1.06	13.38	95	194	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	20.23	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:7	19.09	1396	1.08	13.38	95	194	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.29	20.23	1.38	4.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:7	19.09	1358	1.08	13.38	95	194	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	20.24	1.38	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:25:58:7	16.36	1300	1.09	13.37	95	194	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.11	20.23	1.38	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:25:58:7	16.36	1312	1.1	13.38	95	194	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	20.23	1.38	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:25:58:7	16.36	1312	1.1	13.39	95	194	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.88	20.23	1.38	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:58:7	17.72	1274	1.11	13.4	95	194	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:58:8	17.72	1274	1.12	13.4	95	194	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:25:58:8	17.72	1225	1.13	13.4	95	194	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.59	20.23	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:8	16.36	1224	1.14	13.4	95	194	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.52	20.23	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:8	16.36	1218	1.15	13.4	95	194	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.4	20.22	1.38	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:25:58:8	16.36	1218	1.16	13.4	95	194	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.3	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:58:8	16.36	1211	1.16	13.4	95	194	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.21	20.22	1.38	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:58:9	16.36	1211	1.17	13.4	95	194	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.14	20.22	1.38	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:58:9	16.36	1206	1.18	13.39	95	194	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.06	20.23	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:58:9	16.36	1204	1.18	13.41	95	194	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.02	20.23	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:58:9	16.36	1207	1.18	13.4	95	194	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.99	20.23	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:58:9	16.36	1207	1.18	13.4	95	194	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.99	20.23	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:58:9	16.36	1226	1.18	13.38	96	194	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.96	20.24	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:58:9	16.36	1226	1.18	13.39	96	194	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.96	20.24	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:25:59:0	16.36	1222	1.18	13.38	96	194	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.96	20.25	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:0	13.63	1222	1.18	13.37	95	194	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.97	20.25	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:0	13.63	1231	1.17	13.39	95	194	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.97	20.25	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:0	13.63	1237	1.16	13.39	95	194	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8	20.25	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:0	13.63	1237	1.15	13.38	95	194	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.03	20.25	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:0	14.99	1228	1.14	13.39	95	194	Idle	81.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.1	20.25	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:1	14.99	1218	1.13	13.38	95	194	Idle	82.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.1	20.24	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:1	14.99	1235	1.12	13.38	95	194	Idle	83.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.14	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:1	14.99	1235	1.11	13.39	95	194	Idle	84	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.16	20.24	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:1	14.99	1224	1.11	13.39	95	194	Idle	84.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.19	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:1	14.99	1214	1.1	13.38	95	194	Idle	86.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.22	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:1	14.99	1218	1.09	13.39	95	194	Idle	86.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.26	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:1	14.99	1210	1.08	13.38	95	194	Idle	86.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.31	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:2	14.99	1197	1.07	13.39	95	194	Idle	87.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.33	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:2	13.63	1190	1.06	13.37	95	194	Idle	87.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.36	20.21	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:2	13.63	1184	1.04	13.39	95	194	Idle	87.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.38	20.2	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:2	13.63	1159	1.03	13.39	95	194	Idle	87.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.4	20.21	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:2	13.63	1159	1.02	13.39	95	194	Idle	87.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.41	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:2	13.63	1149	1.01	13.39	95	194	Idle	88	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.39	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:3	13.63	1130	1	13.39	95	194	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:3	13.63	1123	0.99	13.39	95	194	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:3	13.63	1123	0.99	13.39	95	194	Idle	88.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.38	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:3	13.63	1121	0.98	13.39	95	194	Idle	88.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.39	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:3	13.63	1119	0.98	13.39	95	194	Idle	88.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.38	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:3	13.63	1117	0.97	13.39	95	194	Idle	88.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.37	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:4	13.63	1115	0.97	13.38	95	194	Idle	88.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.37	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:4	13.63	1099	0.97	13.38	95	194	Idle	89	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.38	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:4	13.63	1099	0.97	13.38	95	194	Idle	89.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.35	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:4	12.27	1094	0.96	13.38	95	194	Idle	89.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.3	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:4	12.27	1085	0.96	13.37	95	194	Idle	89.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:25:59:4	12.27	1076	0.96	13.38	95	194	Idle	90	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.28	20.23	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:4	12.27	1076	0.95	13.39	95	194	Idle	90.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	20.23	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:5	12.27	1076	0.95	13.38	96	194	Idle	90.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.31	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:5	12.27	1070	0.95	13.37	96	194	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.32	20.23	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:5	12.27	1055	0.95	13.39	96	194	Idle	91.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.35	20.16	1.37	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:5	12.27	1055	0.94	13.37	95	194	Idle	91.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.32	20.06	1.37	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:5	12.27	1049	0.94	13.38	95	194	Idle	92	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.35	19.91	1.36	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:5	12.27	1043	0.93	13.39	95	194	Idle	92.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.3	19.82	1.35	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:6	12.27	1042	0.93	13.38	95	194	Idle	92.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	19.57	1.33	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:6	12.27	1042	0.93	13.38	95	194	Idle	92.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.29	19.3	1.32	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:6	12.27	1018	0.93	13.38	95	194	Idle	92.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.27	19	1.29	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:6	12.27	1018	0.92	13.41	95	194	Idle	92.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.28	18.51	1.26	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:6	10.9	1016	0.92	13.39	95	194	Idle	92.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.25	18.33	1.25	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:6	10.9	1013	0.92	13.4	95	194	Idle	92.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	17.97	1.22	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:6	10.9	1009	0.91	13.39	95	194	Idle	92.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.18	17.48	1.19	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:7	10.9	1003	0.91	13.4	95	194	Idle	92.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	17.2	1.17	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:7	10.9	1003	0.91	13.38	95	194	Idle	92.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.2	17.08	1.16	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:7	10.9	1003	0.9	13.4	95	194	Idle	92.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	16.78	1.14	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:7	10.9	1000	0.9	13.39	95	194	Idle	92	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.14	16.65	1.13	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:7	10.9	1000	0.89	13.39	95	194	Idle	91.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.19	16.52	1.13	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:7	10.9	992	0.89	13.4	95	194	Idle	91.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.12	16.44	1.12	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:8	10.9	995	0.89	13.38	95	194	Idle	91.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.11	16.35	1.11	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:25:59:8	10.9	995	0.89	13.4	96	194	Idle	91.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.1	16.31	1.11	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:8	10.9	998	0.89	13.37	96	194	Idle	91.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.1	16.27	1.11	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:8	10.9	1001	0.88	13.39	96	194	Idle	91.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.08	16.26	1.11	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:8	10.9	986	0.88	13.38	96	194	Idle	91.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.1	16.24	1.11	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:8	10.9	986	0.88	13.4	96	194	Idle	91.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.09	16.22	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:9	9.54	995	0.88	13.38	96	194	Idle	92.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.09	16.2	1.1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:9	9.54	995	0.88	13.4	95	194	Idle	92.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.08	16.19	1.1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:9	9.54	990	0.88	13.39	95	194	Idle	92.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.09	16.18	1.1	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:9	9.54	986	0.88	13.4	95	194	Idle	92.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.1	16.15	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:9	8.18	990	0.88	13.39	95	194	Idle	92.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.08	16.15	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:9	8.18	986	0.88	13.41	95	194	Idle	92.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.08	16.13	1.1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:25:59:9	8.18	986	0.88	13.39	95	194	Idle	93	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.01	16.12	1.1	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:00:0	8.18	976	0.88	13.41	95	194	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.05	16.09	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:00:0	9.54	976	0.88	13.4	95	194	Idle	93.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.01	16.07	1.09	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:00:0	9.54	966	0.88	13.39	95	194	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.08	16.04	1.09	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:00:0	9.54	961	0.87	13.39	95	194	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.04	16.02	1.09	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:0	9.54	956	0.87	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.05	15.98	1.09	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:0	8.18	956	0.87	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.99	15.93	1.09	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:1	8.18	960	0.87	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8	15.89	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:1	8.18	965	0.87	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.93	15.85	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:1	8.18	965	0.87	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.96	15.8	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:1	8.18	938	0.87	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.93	15.74	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:1	8.18	944	0.87	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.97	15.71	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:1	8.18	949	0.86	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.9	15.68	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:1	9.54	949	0.86	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.96	15.66	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:2	9.54	937	0.86	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.91	15.63	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:2	9.54	938	0.86	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.92	15.61	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:2	9.54	938	0.86	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.85	15.6	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:2	9.54	938	0.86	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.89	15.58	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:2	9.54	937	0.86	13.36	95	194	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.86	15.59	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:2	9.54	937	0.86	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.87	15.58	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:3	9.54	936	0.85	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.84	15.57	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:3	9.54	936	0.85	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.89	15.55	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:3	8.18	945	0.85	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.84	15.53	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:3	8.18	945	0.85	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.88	15.51	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:3	8.18	939	0.85	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	15.49	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:00:3	8.18	929	0.85	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.85	15.48	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:4	8.18	929	0.85	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	15.46	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:4	8.18	929	0.85	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.83	15.42	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:4	8.18	922	0.85	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.8	15.39	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:4	8.18	922	0.85	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.83	15.35	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:4	9.54	916	0.85	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15.33	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:4	9.54	916	0.85	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	15.32	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:4	9.54	923	0.84	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15.3	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:5	9.54	923	0.84	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15.28	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:5	9.54	905	0.84	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.74	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:5	9.54	905	0.84	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:5	9.54	906	0.84	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.7	-7.73	15.2	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:5	9.54	906	0.84	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:5	8.18	920	0.84	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:6	8.18	920	0.84	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:6	8.18	917	0.84	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.76	15.13	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:6	8.18	914	0.84	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:6	9.54	889	0.84	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.75	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:6	9.54	889	0.84	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:6	9.54	894	0.84	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:6	9.54	898	0.84	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:7	9.54	898	0.84	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:7	8.18	894	0.84	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:7	8.18	894	0.84	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.66	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:7	8.18	886	0.84	13.37	95	194	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:7	8.18	907	0.84	13.39	95	194	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:7	8.18	907	0.84	13.38	95	194	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:8	8.18	896	0.84	13.4	95	194	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:00:8	8.18	886	0.84	13.39	95	194	Idle	93.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.64	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:8	8.18	886	0.84	13.4	96	194	Idle	93.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.67	14.96	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:8	8.18	888	0.84	13.39	96	194	Idle	93.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.64	14.96	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:8	8.18	888	0.84	13.4	96	194	Idle	93.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.66	14.95	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:8	8.18	875	0.84	13.39	96	194	Idle	93.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.6	14.95	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:9	8.18	875	0.84	13.4	96	194	Idle	93.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.58	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:9	8.18	878	0.83	13.39	95	194	Idle	93.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.56	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:9	8.18	882	0.83	13.4	95	194	Idle	93.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.54	14.9	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:9	8.18	893	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.54	14.9	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:9	8.18	893	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.55	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:9	8.18	890	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.58	14.9	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:00:9	8.18	888	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.54	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:0	8.18	888	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.58	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:0	8.18	890	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.55	14.9	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:0	8.18	890	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	14.9	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:0	8.18	891	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.51	14.9	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:0	8.18	891	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	14.96	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:0	8.18	910	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.54	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:1	8.18	910	0.83	13.42	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:1	8.18	901	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:1	8.18	901	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:1	8.18	907	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.61	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:1	8.18	907	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:1	8.18	900	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:1	8.18	893	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.57	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:2	8.18	903	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.57	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:2	8.18	903	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.57	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:2	8.18	903	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.57	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:2	8.18	903	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:2	8.18	896	0.83	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.61	14.98	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:01:2	8.18	896	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:3	8.18	894	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:3	8.18	892	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.55	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:3	8.18	892	0.83	13.4	95	194	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:3	8.18	893	0.83	13.4	95	194	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.56	15.07	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:3	8.18	896	0.83	13.39	95	194	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.59	15.08	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:3	8.18	898	0.83	13.38	95	194	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:4	8.18	898	0.83	13.38	95	194	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	15.11	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:4	8.18	895	0.83	13.38	95	194	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.12	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:4	8.18	895	0.83	13.39	95	194	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	15.13	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:4	8.18	887	0.83	13.37	95	194	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	15.13	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:4	8.18	879	0.83	13.39	95	194	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	15.14	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:4	8.18	894	0.83	13.37	95	194	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	15.15	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:4	8.18	894	0.83	13.37	96	194	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.59	15.15	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:5	9.54	888	0.83	13.36	96	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.15	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:5	9.54	882	0.83	13.36	96	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	15.16	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:5	9.54	901	0.83	13.36	96	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.57	15.16	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:5	9.54	901	0.83	13.36	96	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.54	15.16	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:5	9.54	904	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.59	15.15	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:5	8.18	904	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.57	15.15	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:6	8.18	904	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	15.15	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:6	8.18	897	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.57	15.14	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:6	8.18	891	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:6	8.18	891	0.83	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:6	8.18	891	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.6	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:6	8.18	903	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.57	15.12	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:6	8.18	895	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.6	15.11	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:7	9.54	895	0.83	13.36	95	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.56	15.12	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:7	9.54	895	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.53	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:7	9.54	903	0.83	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.58	15.12	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:7	9.54	903	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.54	15.12	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:7	9.54	909	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.58	15.13	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:7	9.54	909	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.59	15.13	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:8	9.54	910	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.59	15.13	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:8	9.54	912	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.6	15.13	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:8	9.54	921	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.61	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:8	9.54	921	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.6	15.12	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:8	9.54	918	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.61	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:01:8	9.54	914	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.64	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:9	9.54	928	0.82	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.61	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:9	9.54	928	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.62	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:9	9.54	907	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.7	-7.66	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:9	9.54	907	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.62	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:9	9.54	907	0.82	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.67	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:9	6.81	900	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.66	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:01:9	6.81	908	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.69	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:0	6.81	908	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.67	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:0	6.81	908	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.68	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:0	8.18	911	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.63	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:0	8.18	910	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	15.11	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:0	8.18	910	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.62	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:0	8.18	910	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:1	8.18	900	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:1	8.18	902	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:1	8.18	902	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:1	8.18	902	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:1	8.18	908	0.83	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:1	8.18	908	0.83	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:02:1	8.18	909	0.83	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:2	8.18	909	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:2	8.18	903	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:2	8.18	903	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:2	8.18	903	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:2	8.18	903	0.83	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:2	8.18	902	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:3	8.18	900	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.64	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:3	8.18	897	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:3	8.18	897	0.83	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.64	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:3	8.18	894	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:3	8.18	890	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.62	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:3	8.18	893	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.63	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:4	8.18	893	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.58	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:4	8.18	901	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.6	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:4	9.54	909	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.55	14.93	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:4	9.54	909	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.6	14.93	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:4	9.54	888	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.59	14.92	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:4	9.54	888	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.61	14.93	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:4	8.18	886	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.6	14.92	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:5	8.18	884	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.61	14.91	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:5	8.18	900	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	14.9	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:5	8.18	900	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.58	14.9	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:5	8.18	904	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.62	14.9	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:5	8.18	908	0.82	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.63	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:5	8.18	905	0.82	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.6	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:6	8.18	905	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.6	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:6	8.18	900	0.82	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.63	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:6	8.18	900	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.62	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:6	8.18	900	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.62	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:6	8.18	906	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.63	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:6	8.18	920	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.65	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:6	8.18	920	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.62	14.9	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:7	8.18	914	0.82	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.66	14.9	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:7	8.18	908	0.82	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.63	14.9	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:7	8.18	910	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.91	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:7	8.18	910	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.65	14.92	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:7	8.18	915	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.67	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:7	8.18	920	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.65	14.94	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:8	8.18	920	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.67	14.94	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:8	6.81	914	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.65	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:8	6.81	929	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.69	14.96	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:02:8	6.81	929	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.67	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:8	6.81	929	0.83	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.69	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:8	6.81	903	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.65	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:9	6.81	930	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.68	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:9	6.81	930	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.62	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:9	6.81	930	0.82	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:9	8.18	922	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:9	8.18	913	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:9	8.18	919	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:02:9	8.18	919	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:0	6.81	912	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:0	6.81	912	0.82	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:0	6.81	912	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:0	6.81	912	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:0	8.18	921	0.82	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:0	8.18	921	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:03:1	8.18	914	0.82	13.36	96	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:1	8.18	907	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:1	8.18	907	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-7.67	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:1	8.18	889	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:1	8.18	889	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:1	8.18	899	0.82	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.62	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:1	8.18	899	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:2	8.18	900	0.82	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.61	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:2	8.18	905	0.82	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:2	8.18	905	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.63	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:2	8.18	905	0.82	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:2	8.18	887	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.6	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:2	8.18	887	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:3	8.18	897	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.6	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:3	8.18	897	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:3	8.18	899	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:3	8.18	899	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:3	8.18	894	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:3	8.18	894	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	14.94	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:4	8.18	906	0.83	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.61	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:4	8.18	906	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.65	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:4	8.18	899	0.83	13.36	95	194	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:4	8.18	899	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.68	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:4	8.18	900	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:4	8.18	902	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.65	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:4	8.18	891	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.66	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:5	8.18	891	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.62	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:5	8.18	886	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.66	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:5	9.54	880	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.63	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:5	9.54	880	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.64	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:03:5	9.54	897	0.83	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.62	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:6	9.54	897	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.63	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:6	9.54	887	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.6	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:6	9.54	887	0.83	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.63	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:6	9.54	907	0.83	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.61	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:6	9.54	904	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.64	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:6	9.54	901	0.83	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:6	9.54	901	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.65	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:6	9.54	906	0.83	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.63	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:7	9.54	906	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.7	-7.64	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:7	9.54	911	0.83	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.65	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:7	9.54	916	0.83	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.6	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:7	9.54	895	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.63	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:7	9.54	895	0.83	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.65	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:7	8.18	902	0.83	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.65	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:8	8.18	910	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.64	14.82	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:8	8.18	906	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.65	14.81	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:8	8.18	906	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.61	14.81	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:8	8.18	906	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.62	14.82	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:8	8.18	906	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.62	14.83	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:8	8.18	895	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.67	14.84	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:9	8.18	895	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.63	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:9	8.18	894	0.82	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.67	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:9	8.18	894	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.61	14.9	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:9	8.18	894	0.82	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.64	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:9	8.18	897	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.6	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:9	8.18	897	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.63	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:03:9	8.18	913	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.61	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:04:0	8.18	913	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.65	14.98	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:04:0	8.18	901	0.82	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.61	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:0	8.18	901	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.63	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:0	8.18	905	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.66	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:0	8.18	905	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.7	-7.65	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:0	8.18	905	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:1	8.18	916	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:1	8.18	930	0.82	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:1	8.18	930	0.82	13.4	95	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:1	8.18	922	0.82	13.37	95	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:1	8.18	914	0.82	13.4	96	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:1	8.18	921	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:1	8.18	921	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:2	8.18	918	0.82	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:2	8.18	918	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.64	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:2	6.81	918	0.82	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:2	6.81	905	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.64	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:2	6.81	919	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.71	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:2	6.81	919	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.66	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:3	6.81	907	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.7	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:3	6.81	895	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-7.67	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:3	6.81	884	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:3	6.81	884	0.82	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.65	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:3	6.81	884	0.82	13.38	95	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.67	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:3	8.18	895	0.82	13.36	95	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.64	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:4	8.18	895	0.82	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.65	15.03	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:4	8.18	905	0.83	13.37	96	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.61	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:4	8.18	905	0.83	13.39	96	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.64	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:4	8.18	905	0.83	13.38	96	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.67	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:4	8.18	905	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.66	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:4	8.18	894	0.83	13.39	95	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.65	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:4	8.18	894	0.83	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.67	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:5	8.18	895	0.83	13.41	95	194	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-7.65	14.93	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:5	8.18	896	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.65	14.9	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:5	8.18	910	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	14.89	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:5	8.18	910	0.83	13.43	96	194	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.61	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:5	8.18	902	0.83	13.43	95	194	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:5	8.18	893	0.83	13.43	95	194	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.61	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:6	8.18	893	0.83	13.42	95	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:6	8.18	903	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.6	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:04:6	8.18	903	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.66	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:04:6	8.18	894	0.83	13.42	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:04:6	8.18	894	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.85	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:04:6	8.18	917	0.83	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:6	8.18	917	0.83	13.44	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:7	8.18	905	0.83	13.44	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:7	8.18	913	0.83	13.45	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:7	8.18	913	0.83	13.43	96	194	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:7	8.18	913	0.83	13.43	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:7	8.18	917	0.84	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:7	8.18	917	0.84	13.41	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:8	8.18	920	0.84	13.42	96	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:8	8.18	920	0.84	13.44	96	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:8	8.18	905	0.84	13.44	96	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:8	8.18	905	0.84	13.46	96	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:8	8.18	899	0.83	13.43	96	194	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:8	8.18	899	0.83	13.45	96	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:9	9.54	906	0.83	13.42	96	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:04:9	9.54	906	0.83	13.42	96	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:9	9.54	899	0.83	13.41	96	194	Full Load	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:9	9.54	899	0.83	13.43	96	194	Off Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.7	-7.59	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:9	9.54	899	0.84	13.42	96	194	Off Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.7	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:9	9.54	896	0.84	13.42	96	194	Off Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.61	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:04:9	9.54	899	0.85	13.43	96	194	Off Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.62	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:05:0	9.54	899	0.85	13.42	96	194	Off Idle	92.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.53	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:0	9.54	900	0.86	13.43	96	194	Off Idle	92.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.55	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:0	9.54	900	0.87	13.41	96	194	Off Idle	91.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.46	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:0	9.54	900	0.88	13.42	96	194	Off Idle	91.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.4	14.85	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:0	9.54	907	0.89	13.41	96	194	Off Idle	90.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.33	14.85	1.01	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:05:0	9.54	912	0.9	13.44	95	194	Off Idle	90.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-7.3	14.85	1.01	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:05:1	9.54	916	0.91	13.41	95	194	Off Idle	90	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.18	14.86	1.01	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:05:1	9.54	916	0.93	13.44	95	194	Off Idle	89.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-7.16	14.86	1.01	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:05:1	9.54	917	0.94	13.42	95	194	Off Idle	88.8	0	2	132	944 Turbo	0.61	Lean	1	14.7	-7.06	14.86	1.01	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:1	9.54	917	0.95	13.44	95	194	Off Idle	88.3	0	2	132	944 Turbo	0.6	Lean	1	14.7	-7.02	14.86	1.01	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:1	8.18	943	0.97	13.41	95	194	Off Idle	87.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-6.91	14.86	1.01	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:1	8.18	943	0.99	13.44	95	194	Off Idle	87.2	0	2	132	944 Turbo	0.51	Lean	1	14.7	-6.87	14.86	1.01	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:1	8.18	968	1.01	13.43	95	194	Off Idle	86.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.78	14.85	1.01	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:2	8.18	968	1.03	13.45	95	194	Off Idle	85.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.72	14.86	1.01	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:2	8.18	981	1.06	13.44	96	194	Off Idle	85.1	0	2	132	944 Turbo	0.32	Lean	1	14.7	-6.57	14.85	1.01	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:2	8.18	981	1.08	13.44	96	194	Off Idle	85.1	0	2	132	944 Turbo	0.29	Lean	1	14.7	-6.56	14.85	1.01	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:2	8.18	994	1.1	13.43	96	194	Off Idle	85.2	0	2	132	944 Turbo	0.26	Lean	1	14.7	-6.45	14.84	1.01	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:05:2	8.18	1020	1.12	13.44	96	194	Off Idle	85.2	0	2	132	944 Turbo	0.23	Lean	1	14.7	-6.42	14.85	1.01	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:05:2	8.18	1020	1.14	13.42	96	194	Off Idle	85.2	0	2	132	944 Turbo	0.2	Lean	1	14.7	-6.32	14.86	1.01	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:05:3	8.18	1042	1.15	13.42	96	194	Off Idle	85.3	0	2	132	944 Turbo	0.18	Lean	1	14.7	-6.32	14.86	1.01	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:05:3	8.18	1051	1.17	13.42	96	194	Off Idle	85.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.24	14.87	1.01	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:05:3	9.54	1053	1.18	13.42	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-6.26	14.87	1.01	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:05:3	9.54	1053	1.2	13.43	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.18	Lean	1	14.7	-6.23	14.87	1.01	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:05:3	9.54	1072	1.22	13.43	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.24	14.86	1.01	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:3	9.54	1094	1.23	13.43	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.3	Lean	1	14.7	-6.2	14.86	1.01	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:4	9.54	1094	1.24	13.43	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.18	14.85	1.01	4.3	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:4	9.54	1103	1.25	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.17	14.85	1.01	4.3	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:4	9.54	1129	1.26	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.5	Lean	1	14.7	-6.15	14.85	1.01	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:4	9.54	1146	1.26	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.2	14.86	1.01	4.4	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:4	9.54	1146	1.27	13.44	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.22	14.86	1.01	4.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:4	9.54	1136	1.27	13.43	96	194	Off Idle	86	0	2	132	944 Turbo	0.71	Rich	1	14.7	-6.23	14.87	1.01	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:4	9.54	1129	1.28	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.26	14.9	1.01	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:5	9.54	1129	1.28	13.4	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.26	14.93	1.02	4.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:5	9.54	1119	1.28	13.4	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.24	14.96	1.02	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:5	9.54	1104	1.28	13.42	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.26	14.99	1.02	4.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:5	10.9	1089	1.28	13.41	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.24	15.01	1.02	4.8	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:5	10.9	1086	1.28	13.41	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-6.27	15.03	1.02	4.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:5	10.9	1083	1.28	13.41	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.84	Rich	1	14.7	-6.18	15.05	1.03	4.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:6	10.9	1040	1.28	13.4	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.84	Rich	1	14.7	-6.21	15.06	1.03	4.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:6	10.9	1040	1.28	13.42	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.14	15.09	1.03	4.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:05:6	10.9	1045	1.28	13.39	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.13	15.12	1.03	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:6	10.9	1045	1.28	13.41	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.09	15.11	1.03	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:6	13.63	1027	1.28	13.4	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6	15.08	1.03	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:6	13.63	1027	1.28	13.42	96	194	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.02	15.04	1.02	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:6	13.63	1027	1.28	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.94	14.98	1.02	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:7	13.63	1030	1.28	13.43	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6	14.91	1.02	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:7	13.63	1030	1.28	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.96	14.83	1.01	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:7	13.63	1035	1.28	13.41	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.97	14.73	1	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:7	13.63	1040	1.28	13.43	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.98	14.62	1	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:7	14.99	1042	1.28	13.42	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.96	14.4	0.98	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:7	14.99	1044	1.27	13.43	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.93	14.27	0.97	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:8	14.99	1058	1.27	13.42	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.89	14.16	0.96	4.4	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:05:8	13.63	1058	1.27	13.43	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.91	14.06	0.96	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:8	13.63	1083	1.27	13.42	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.92	13.97	0.95	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:8	13.63	1088	1.27	13.43	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.94	13.88	0.95	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:26:05:8	13.63	1088	1.27	13.42	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6	13.77	0.94	4.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:8	12.27	1086	1.27	13.42	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.02	13.72	0.93	4.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:9	12.27	1088	1.27	13.42	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-6.01	13.68	0.93	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:9	12.27	1091	1.27	13.42	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-6.04	13.64	0.93	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:9	12.27	1091	1.27	13.42	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.05	13.6	0.93	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:9	12.27	1096	1.26	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-6.04	13.58	0.93	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:9	12.27	1114	1.26	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.12	13.56	0.92	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:9	12.27	1114	1.26	13.42	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.1	13.54	0.92	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:05:9	13.63	1092	1.26	13.43	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.14	13.55	0.92	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:06:0	13.63	1104	1.26	13.44	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.14	13.56	0.92	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:06:0	13.63	1116	1.26	13.42	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.13	13.58	0.92	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:06:0	13.63	1114	1.26	13.43	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.17	13.59	0.93	4.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:06:0	13.63	1111	1.26	13.42	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.15	13.61	0.93	4.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:06:0	13.63	1109	1.26	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.2	13.64	0.93	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:06:0	13.63	1107	1.26	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.18	13.65	0.93	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:06:1	14.99	1106	1.26	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.21	13.67	0.93	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:06:1	14.99	1118	1.26	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.25	13.71	0.93	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:1	14.99	1118	1.26	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.19	13.72	0.93	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:1	14.99	1126	1.26	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.23	13.73	0.94	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:1	14.99	1126	1.26	13.42	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.19	13.73	0.94	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:1	14.99	1128	1.26	13.42	96	194	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.23	13.74	0.94	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:1	14.99	1136	1.26	13.42	96	194	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.7	-6.23	13.76	0.94	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:2	14.99	1141	1.26	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.25	13.76	0.94	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:2	14.99	1133	1.26	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.31	13.77	0.94	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:2	14.99	1133	1.26	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.31	13.76	0.94	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:2	14.99	1133	1.27	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.31	13.75	0.94	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:2	14.99	1131	1.27	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.6	-6.32	13.74	0.94	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:2	14.99	1131	1.27	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.7	-6.28	13.72	0.93	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:3	14.99	1130	1.27	13.41	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-6.29	13.71	0.93	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:3	14.99	1129	1.27	13.41	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-6.28	13.7	0.93	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:3	14.99	1132	1.27	13.41	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-6.31	13.67	0.93	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:3	14.99	1136	1.27	13.43	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.34	13.67	0.93	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:3	14.99	1138	1.27	13.41	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.33	13.67	0.93	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:3	14.99	1162	1.27	13.4	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.38	13.68	0.93	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:4	14.99	1162	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.34	13.69	0.93	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:4	17.72	1145	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.36	13.73	0.94	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:4	17.72	1158	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.43	13.74	0.94	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:4	17.72	1158	1.27	13.4	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.41	13.77	0.94	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:4	17.72	1164	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-6.43	13.8	0.94	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:4	17.72	1172	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.44	13.82	0.94	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:06:4	17.72	1172	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.46	13.85	0.94	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:5	16.36	1178	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-6.46	13.87	0.95	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:5	16.36	1186	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-6.49	13.9	0.95	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:5	16.36	1188	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-6.51	13.94	0.95	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:5	16.36	1188	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.54	13.97	0.95	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:5	16.36	1193	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.61	14	0.95	4.3	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:5	16.36	1208	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-6.63	14.05	0.96	4.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:6	17.72	1208	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-6.64	14.08	0.96	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:6	17.72	1181	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.66	14.14	0.96	4.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:6	17.72	1188	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-6.65	14.15	0.96	4.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:6	17.72	1176	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-6.64	14.21	0.97	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:6	19.09	1176	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.66	14.24	0.97	4.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:6	19.09	1185	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.69	14.26	0.97	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:6	19.09	1185	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.68	14.29	0.97	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:7	17.72	1180	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.68	14.31	0.97	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:06:7	17.72	1183	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.66	14.32	0.98	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:7	17.72	1192	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-6.65	14.35	0.98	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:7	19.09	1188	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.69	14.36	0.98	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:7	19.09	1188	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.69	14.39	0.98	4.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:7	19.09	1203	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-6.72	14.41	0.98	4.3	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:8	20.45	1202	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.73	14.42	0.98	4.3	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:8	20.45	1202	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.7	-6.75	14.44	0.98	4.3	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:06:8	20.45	1209	1.27	13.42	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.76	14.46	0.99	4.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:8	19.09	1243	1.27	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.75	14.47	0.99	4.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:8	19.09	1245	1.27	13.43	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.8	14.49	0.99	4.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:8	19.09	1245	1.27	13.41	96	194	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	-6.82	14.51	0.99	4.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:9	19.09	1261	1.27	13.41	96	194	Off Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.84	14.51	0.99	4.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:9	19.09	1261	1.27	13.42	96	194	Off Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.9	14.53	0.99	4.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:06:9	19.09	1257	1.27	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.96	14.55	0.99	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:06:9	19.09	1251	1.27	13.42	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7	14.55	0.99	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:06:9	19.09	1251	1.27	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-7.03	14.58	0.99	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:06:9	19.09	1252	1.27	13.42	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.04	14.61	1	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:06:9	19.09	1229	1.27	13.42	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.06	14.63	1	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:0	20.45	1229	1.27	13.42	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-7.06	14.65	1	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:0	20.45	1228	1.26	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.07	14.66	1	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:0	21.81	1230	1.26	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-7.12	14.67	1	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:0	21.81	1233	1.26	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.09	14.69	1	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:0	21.81	1234	1.26	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.12	14.71	1	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:0	21.81	1233	1.26	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-7.11	14.72	1	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:1	21.81	1232	1.26	13.42	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-7.13	14.73	1	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:1	21.81	1229	1.26	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.14	14.74	1	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:1	20.45	1229	1.26	13.42	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-7.17	14.74	1	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:1	20.45	1251	1.26	13.42	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-7.16	14.76	1.01	4.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:1	20.45	1277	1.26	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.68	Lean	1	14.6	-7.17	14.77	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:1	20.45	1272	1.25	13.42	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.63	Lean	1	14.7	-7.21	14.79	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:1	23.18	1272	1.25	13.43	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.23	14.8	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:2	23.18	1278	1.25	13.42	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.48	Lean	1	14.7	-7.25	14.82	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:2	21.81	1285	1.25	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.3	14.84	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:2	21.81	1285	1.25	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.36	Lean	1	14.7	-7.34	14.85	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:2	21.81	1296	1.25	13.43	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-7.37	14.87	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:2	21.81	1285	1.25	13.43	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.24	Lean	1	14.7	-7.43	14.87	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:2	21.81	1285	1.25	13.44	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.2	Lean	1	14.7	-7.48	14.87	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:3	21.81	1280	1.25	13.44	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.15	Lean	1	14.7	-7.48	14.88	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:3	21.81	1281	1.24	13.44	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-7.54	14.89	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:3	21.81	1281	1.24	13.44	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-7.55	14.9	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:3	21.81	1294	1.24	13.44	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.11	Lean	1	14.7	-7.56	14.89	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:3	23.18	1253	1.24	13.45	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	14.88	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:3	23.18	1253	1.24	13.43	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-7.59	14.86	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:4	23.18	1275	1.24	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-7.6	14.85	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:4	24.54	1271	1.24	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.7	-7.61	14.84	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:4	24.54	1271	1.24	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.86	1.01	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:4	24.54	1273	1.23	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-7.58	14.89	1.01	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:4	23.18	1267	1.23	13.4	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.54	14.91	1.02	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:4	23.18	1287	1.23	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-7.54	14.93	1.02	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:07:4	23.18	1287	1.23	13.4	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.52	14.94	1.02	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:5	23.18	1295	1.23	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-7.54	14.99	1.02	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:5	23.18	1320	1.23	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.6	15.06	1.03	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:5	23.18	1320	1.23	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.58	15.08	1.03	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:5	24.54	1301	1.23	13.41	95	194	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.66	15.13	1.03	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:5	24.54	1317	1.23	13.43	95	194	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.74	15.14	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:5	24.54	1317	1.22	13.41	95	194	Off Idle	86.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.72	15.14	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:6	25.9	1312	1.22	13.4	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.08	Lean	1	14.7	-7.73	15.14	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:6	25.9	1305	1.22	13.4	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.75	15.14	1.03	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:07:6	25.9	1305	1.22	13.41	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.08	Lean	1	14.7	-7.76	15.14	1.03	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:6	24.54	1306	1.22	13.39	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	15.14	1.03	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:6	24.54	1314	1.22	13.39	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.79	15.14	1.03	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:6	24.54	1314	1.22	13.41	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.11	Lean	1	14.7	-7.77	15.15	1.03	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:6	25.9	1323	1.22	13.41	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.77	15.16	1.03	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:7	25.9	1309	1.22	13.41	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.77	15.16	1.03	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:7	25.9	1316	1.22	13.43	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.25	Lean	1	14.7	-7.75	15.19	1.03	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:7	25.9	1316	1.22	13.43	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.3	Lean	1	14.7	-7.73	15.2	1.04	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:07:7	25.9	1322	1.23	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.38	Lean	1	14.7	-7.76	15.22	1.04	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:7	27.27	1319	1.23	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.44	Lean	1	14.7	-7.79	15.22	1.04	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:7	27.27	1313	1.23	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.79	15.21	1.04	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:8	27.27	1313	1.23	13.4	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.55	Rich	1	14.7	-7.79	15.22	1.04	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:8	25.9	1326	1.23	13.4	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.6	Rich	1	14.7	-7.82	15.22	1.04	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:8	25.9	1326	1.23	13.41	96	194	Off Idle	86.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	15.22	1.04	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:8	25.9	1331	1.23	13.41	96	194	Off Idle	86.7	0	2	132	944 Turbo	0.65	Rich	1	14.7	-7.82	15.21	1.04	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:8	25.9	1334	1.23	13.41	96	194	Off Idle	86.7	0	2	132	944 Turbo	0.65	Rich	1	14.7	-7.84	15.2	1.04	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:8	25.9	1334	1.23	13.42	96	194	Off Idle	86.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.87	15.18	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:9	25.9	1334	1.23	13.41	96	194	Off Idle	86.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	-7.87	15.18	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:9	27.27	1343	1.23	13.41	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.65	Rich	1	14.7	-7.86	15.16	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:9	27.27	1334	1.23	13.41	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.88	15.15	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:9	27.27	1334	1.23	13.41	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.86	15.13	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:9	27.27	1337	1.23	13.42	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.51	Lean	1	14.7	-7.85	15.1	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:9	27.27	1338	1.23	13.4	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.83	15.1	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:07:9	27.27	1338	1.23	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.41	Lean	1	14.7	-7.86	15.1	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:0	27.27	1338	1.23	13.4	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.86	15.1	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:0	27.27	1340	1.23	13.4	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.3	Lean	1	14.7	-7.86	15.09	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:0	27.27	1340	1.23	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.24	Lean	1	14.7	-7.89	15.07	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:0	27.27	1343	1.23	13.4	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.88	15.04	1.02	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:0	27.27	1341	1.23	13.4	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.87	15.02	1.02	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:0	27.27	1366	1.23	13.4	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.13	Lean	1	14.7	-7.88	14.99	1.02	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:1	27.27	1366	1.23	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-7.91	14.97	1.02	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:1	27.27	1354	1.23	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.9	14.94	1.02	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:1	25.9	1368	1.23	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.09	Lean	1	14.7	-7.92	14.9	1.02	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:1	25.9	1368	1.23	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8	14.87	1.01	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:1	25.9	1368	1.23	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.01	14.85	1.01	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:1	25.9	1368	1.23	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.02	14.83	1.01	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:1	25.9	1373	1.23	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.03	14.84	1.01	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:2	25.9	1374	1.23	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.04	14.86	1.01	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:2	25.9	1374	1.23	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.02	14.87	1.01	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:2	25.9	1376	1.23	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8	14.9	1.01	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:2	25.9	1378	1.23	13.4	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.7	-7.99	14.92	1.02	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:2	25.9	1378	1.23	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.01	14.95	1.02	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:2	25.9	1393	1.23	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8	14.99	1.02	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:3	27.27	1398	1.23	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.01	15.02	1.02	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:3	27.27	1375	1.23	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.06	15.06	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:3	27.27	1375	1.23	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.07	15.09	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:3	25.9	1390	1.23	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.07	15.11	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:3	25.9	1402	1.23	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.1	15.13	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:3	25.9	1395	1.23	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.09	15.16	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:4	27.27	1395	1.23	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.1	15.18	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:4	27.27	1381	1.23	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.08	15.18	1.03	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:4	25.9	1384	1.23	13.43	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.06	15.2	1.04	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:4	25.9	1397	1.23	13.43	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.3	Rich	1	14.7	-8.08	15.19	1.03	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:08:4	25.9	1397	1.23	13.41	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.35	Rich	1	14.7	-8.06	15.19	1.03	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:08:4	25.9	1367	1.23	13.41	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.05	15.19	1.03	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:08:4	25.9	1391	1.23	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.07	15.19	1.04	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:5	25.9	1391	1.24	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.51	Rich	1	14.7	-8.1	15.18	1.03	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:5	25.9	1391	1.24	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.06	15.18	1.03	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:08:5	25.9	1406	1.24	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.03	15.18	1.03	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:5	25.9	1390	1.24	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.03	15.17	1.03	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:5	25.9	1390	1.25	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.04	15.15	1.03	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:5	25.9	1412	1.25	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.66	Rich	1	14.7	-7.99	15.15	1.03	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:6	25.9	1403	1.26	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.66	Rich	1	14.7	-7.97	15.16	1.03	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:6	25.9	1403	1.26	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.64	Rich	1	14.7	-7.95	15.14	1.03	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:6	25.9	1423	1.26	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.58	Rich	1	14.7	-7.91	15.11	1.03	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:6	27.27	1420	1.27	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.89	15.09	1.03	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:08:6	27.27	1420	1.27	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.91	15.08	1.03	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:6	27.27	1431	1.28	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.47	Rich	1	14.7	-7.93	15.06	1.03	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:6	27.27	1433	1.29	13.44	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.38	Rich	1	14.7	-7.9	15.03	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:7	27.27	1450	1.29	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.89	15.03	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:7	28.63	1458	1.29	13.44	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.26	Lean	1	14.7	-7.85	15.02	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:7	28.63	1448	1.3	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.89	14.99	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:7	27.27	1444	1.3	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.89	14.98	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:7	27.27	1450	1.31	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.14	Lean	1	14.7	-7.85	14.96	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:7	27.27	1450	1.31	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-7.85	14.95	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:8	27.27	1444	1.32	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.11	Lean	1	14.7	-7.87	14.95	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:8	27.27	1441	1.32	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.86	14.94	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:8	27.27	1438	1.33	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.86	14.94	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:8	27.27	1438	1.33	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.09	Lean	1	14.7	-7.86	14.95	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:8	27.27	1437	1.33	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.7	-7.87	14.95	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:8	27.27	1437	1.33	13.42	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.89	14.94	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:9	27.27	1437	1.33	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.84	14.95	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:9	27.27	1451	1.34	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.13	Lean	1	14.7	-7.83	14.97	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:9	28.63	1441	1.34	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.16	Lean	1	14.7	-7.82	14.99	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:9	28.63	1441	1.34	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.79	15	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:9	28.63	1452	1.34	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.24	Lean	1	14.7	-7.74	15.01	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:9	28.63	1455	1.35	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.29	Lean	1	14.7	-7.71	15.03	1.02	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:08:9	28.63	1458	1.35	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.67	15.05	1.03	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:0	28.63	1464	1.36	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.66	15.06	1.03	4.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:0	28.63	1469	1.36	13.41	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.47	Lean	1	14.7	-7.63	15.06	1.03	4.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:0	28.63	1499	1.36	13.43	96	194	Off Idle	86.9	0	2	132	944 Turbo	0.54	Rich	1	14.7	-7.58	15.09	1.03	4.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:0	28.63	1499	1.37	13.43	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.59	15.11	1.03	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:0	28.63	1493	1.38	13.42	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.59	Rich	1	14.7	-7.58	15.12	1.03	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:0	28.63	1493	1.38	13.42	96	194	Off Idle	86.8	0	2	132	944 Turbo	0.61	Rich	1	14.7	-7.58	15.12	1.03	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:1	28.63	1493	1.39	13.41	96	194	Off Idle	86.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.53	15.13	1.03	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:1	28.63	1496	1.4	13.42	96	194	Off Idle	86.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.48	15.15	1.03	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:1	28.63	1501	1.41	13.4	96	194	Off Idle	86.7	0	2	132	944 Turbo	0.59	Rich	1	14.7	-7.39	15.14	1.03	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:1	28.63	1501	1.42	13.41	96	194	Off Idle	86.7	0	2	132	944 Turbo	0.59	Rich	1	14.7	-7.42	15.13	1.03	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:1	28.63	1501	1.42	13.41	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.57	Rich	1	14.7	-7.38	15.13	1.03	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:1	28.63	1498	1.43	13.4	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.52	Rich	1	14.7	-7.3	15.13	1.03	4.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:1	28.63	1496	1.44	13.41	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.5	Rich	1	14.7	-7.27	15.1	1.03	4.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:09:2	28.63	1498	1.45	13.41	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.47	Lean	1	14.7	-7.21	15.08	1.03	4.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:09:2	28.63	1498	1.46	13.4	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.17	15.06	1.03	4.2	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:09:2	28.63	1500	1.47	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.16	15.04	1.02	4.2	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:09:2	28.63	1504	1.48	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.42	Lean	1	14.7	-7.11	15.01	1.02	4.2	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:09:2	28.63	1516	1.5	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.41	Lean	1	14.7	-7.04	15	1.02	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:2	28.63	1516	1.51	13.43	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.4	Lean	1	14.7	-6.96	14.98	1.02	4.2	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:3	28.63	1523	1.53	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.86	14.97	1.02	4.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:09:3	28.63	1530	1.54	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.42	Lean	1	14.7	-6.75	14.95	1.02	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:09:3	28.63	1530	1.57	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.43	Lean	1	14.7	-6.59	14.94	1.02	4.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:09:3	28.63	1543	1.59	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.45	Lean	1	14.7	-6.5	14.94	1.02	4.1	3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:3	28.63	1556	1.6	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.46	Rich	1	14.7	-6.34	14.94	1.02	4.1	3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:3	28.63	1556	1.62	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.47	Rich	1	14.7	-6.23	14.95	1.02	4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:09:4	27.27	1566	1.64	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.49	Rich	1	14.7	-6.09	14.95	1.02	4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:09:4	27.27	1588	1.66	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.52	Rich	1	14.7	-5.97	14.96	1.02	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:09:4	27.27	1597	1.68	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.54	Rich	1	14.7	-5.86	14.96	1.02	4	3.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:09:4	27.27	1597	1.7	13.41	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.56	Rich	1	14.7	-5.73	14.97	1.02	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:09:4	27.27	1603	1.73	13.42	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.57	Rich	1	14.7	-5.61	14.98	1.02	3.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:4	27.27	1612	1.74	13.41	96	194	Off Idle	86.6	0	2	132	944 Turbo	0.59	Rich	1	14.7	-5.56	14.98	1.02	4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:4	27.27	1615	1.76	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-5.42	14.98	1.02	4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:5	27.27	1621	1.78	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.36	14.97	1.02	4.1	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:5	27.27	1624	1.8	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-5.29	14.98	1.02	4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:5	27.27	1624	1.81	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-5.23	14.98	1.02	4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:5	27.27	1627	1.83	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-5.19	14.98	1.02	4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:5	27.27	1629	1.85	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	-5.15	14.97	1.02	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:09:6	27.27	1631	1.86	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-5.14	14.98	1.02	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:09:6	27.27	1635	1.87	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.1	15.01	1.02	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:09:6	27.27	1636	1.88	13.43	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.07	15	1.02	4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:09:6	27.27	1642	1.88	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.02	15	1.02	4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:6	27.27	1647	1.89	13.43	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-4.98	14.98	1.02	4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:6	27.27	1655	1.9	13.43	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-4.91	14.96	1.02	4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:6	27.27	1670	1.91	13.43	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-4.85	14.93	1.02	3.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:6	27.27	1670	1.92	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-4.83	14.89	1.01	3.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:7	27.27	1680	1.93	13.42	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-4.75	14.85	1.01	3.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:7	27.27	1686	1.94	13.41	96	194	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-4.64	14.77	1.01	3.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:09:7	27.27	1709	1.95	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-4.54	14.68	1	3.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:7	27.27	1701	1.96	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-4.46	14.6	0.99	4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:7	27.27	1701	1.97	13.4	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-4.32	14.54	0.99	4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:09:7	27.27	1716	1.98	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-4.23	14.48	0.99	3.9	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:8	27.27	1734	1.99	13.43	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-4.14	14.43	0.98	3.9	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:8	27.27	1731	2	13.41	96	194	Off Idle	86.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-4.06	14.38	0.98	3.9	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:8	27.27	1731	2.01	13.41	96	194	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.94	14.33	0.98	3.9	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:8	27.27	1760	2.03	13.43	96	194	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.84	14.31	0.97	3.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:8	27.27	1792	2.05	13.43	96	194	Off Idle	86.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-3.8	14.27	0.97	3.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:8	27.27	1792	2.06	13.42	96	194	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.66	14.25	0.97	3.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:9	28.63	1819	2.07	13.43	96	194	Off Idle	86.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-3.6	14.25	0.97	3.7	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:09:9	28.63	1818	2.09	13.44	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.51	14.25	0.97	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:09:9	28.63	1824	2.11	13.43	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.42	14.26	0.97	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:09:9	28.63	1841	2.13	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.3	14.28	0.97	3.7	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:09:9	28.63	1852	2.15	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.21	14.3	0.97	3.7	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:09:9	28.63	1855	2.15	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-3.13	14.31	0.97	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:09:9	28.63	1858	2.17	13.41	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-3.09	14.34	0.98	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:10:0	28.63	1868	2.19	13.4	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-3.04	14.37	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:0	28.63	1873	2.2	13.4	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-3.01	14.38	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:0	28.63	1884	2.2	13.4	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.95	14.37	0.98	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:0	28.63	1884	2.21	13.4	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.9	14.35	0.98	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:0	28.63	1890	2.22	13.4	96	194	Off Idle	86.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.91	14.31	0.97	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:0	28.63	1891	2.22	13.43	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.94	14.25	0.97	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:1	28.63	1898	2.23	13.43	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.93	14.21	0.97	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:1	28.63	1905	2.24	13.44	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.94	14.15	0.96	3.7	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:1	28.63	1910	2.25	13.42	96	194	Off Idle	86.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.9	14.03	0.96	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:1	28.63	1925	2.25	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.91	13.98	0.95	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:1	28.63	1938	2.26	13.4	96	194	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.89	13.88	0.95	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:1	28.63	1957	2.26	13.4	96	194	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.88	13.85	0.94	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:1	28.63	1957	2.27	13.39	96	194	Off Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.9	13.78	0.94	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:2	28.63	1983	2.27	13.4	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.94	13.72	0.93	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:2	28.63	1995	2.27	13.39	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.95	13.66	0.93	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:2	29.99	1995	2.27	13.38	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.98	13.63	0.93	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:2	29.99	2014	2.27	13.38	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-3.02	13.58	0.92	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:2	29.99	2047	2.27	13.38	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-3.06	13.54	0.92	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:2	29.99	2042	2.28	13.38	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.07	13.52	0.92	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:3	29.99	2048	2.28	13.39	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.07	13.5	0.92	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:3	29.99	2053	2.28	13.4	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.02	13.49	0.92	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:3	29.99	2073	2.28	13.41	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.01	13.5	0.92	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:10:3	29.99	2080	2.29	13.42	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.02	13.51	0.92	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:10:3	29.99	2076	2.29	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.04	13.54	0.92	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:10:3	29.99	2082	2.29	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-3.1	13.55	0.92	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:10:4	29.99	2082	2.3	13.43	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-3.16	13.58	0.93	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:10:4	29.99	2087	2.3	13.42	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-3.23	13.63	0.93	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:10:4	29.99	2106	2.3	13.43	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-3.25	13.66	0.93	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:10:4	29.99	2112	2.31	13.41	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-3.27	13.7	0.93	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:10:4	29.99	2114	2.31	13.41	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-3.25	13.72	0.93	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:10:4	29.99	2124	2.31	13.43	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-3.26	13.78	0.94	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:10:4	29.99	2146	2.32	13.44	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-3.28	13.83	0.94	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:10:5	29.99	2159	2.32	13.44	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-3.29	13.86	0.94	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:10:5	29.99	2159	2.32	13.42	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.29	13.92	0.95	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:10:5	29.99	2170	2.33	13.41	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-3.26	13.98	0.95	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:10:5	29.99	2199	2.34	13.41	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-3.12	14.06	0.96	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:10:5	29.99	2199	2.34	13.42	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-3.06	14.11	0.96	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:10:5	29.99	2196	2.35	13.43	96	194	Off Idle	85.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-3	14.17	0.97	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:6	29.99	2208	2.35	13.43	96	194	Off Idle	85.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-3	14.19	0.97	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:6	29.99	2264	2.37	13.45	96	194	Off Idle	85	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.98	14.27	0.97	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:6	31.36	2264	2.37	13.44	96	194	Off Idle	84.9	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.91	14.32	0.98	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:6	31.36	2244	2.38	13.44	96	194	Off Idle	84.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-2.88	14.37	0.98	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:6	31.36	2253	2.39	13.43	96	194	Off Idle	84.2	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.82	14.41	0.98	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:6	31.36	2256	2.4	13.42	96	194	Off Idle	83.8	0	2	132	944 Turbo	0.65	Rich	1	14.7	-2.77	14.47	0.99	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:6	31.36	2271	2.41	13.4	96	194	Off Idle	83.3	0	2	132	944 Turbo	0.59	Rich	1	14.7	-2.77	14.52	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:7	31.36	2287	2.41	13.41	96	194	Off Idle	82.9	0	2	132	944 Turbo	0.54	Rich	1	14.7	-2.78	14.56	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:7	31.36	2288	2.42	13.41	96	194	Off Idle	82	0	2	132	944 Turbo	0.5	Rich	1	14.7	-2.81	14.62	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:7	31.36	2294	2.43	13.4	96	194	Off Idle	81.4	0	2	132	944 Turbo	0.46	Rich	1	14.7	-2.79	14.67	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:10:7	31.36	2306	2.43	13.43	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.44	Lean	1	14.7	-2.75	14.74	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:10:7	31.36	2323	2.45	13.43	96	194	Off Idle	80.8	0	2	132	944 Turbo	0.43	Lean	1	14.7	-2.81	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:7	31.36	2332	2.45	13.42	96	194	Off Idle	80.2	0	2	132	944 Turbo	0.43	Lean	1	14.7	-2.8	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:8	31.36	2336	2.46	13.42	96	194	Off Idle	79.5	0	2	132	944 Turbo	0.44	Lean	1	14.7	-2.73	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:8	31.36	2346	2.47	13.44	96	194	Off Idle	78.9	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.72	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:8	31.36	2360	2.48	13.43	96	194	Off Idle	78.3	0	2	132	944 Turbo	0.53	Lean	1	14.7	-2.77	14.97	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:8	31.36	2360	2.48	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.56	Lean	1	14.7	-2.78	14.99	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:8	31.36	2370	2.49	13.43	96	194	Off Idle	77	0	2	132	944 Turbo	0.62	Lean	1	14.7	-2.75	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:10:8	31.36	2384	2.49	13.43	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.66	Lean	1	14.7	-2.81	15.04	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:9	31.36	2384	2.49	13.42	96	194	Off Idle	75.9	0	2	132	944 Turbo	0.68	Lean	1	14.7	-2.81	15.04	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:9	31.36	2398	2.5	13.41	96	194	Off Idle	75.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.82	15.04	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:9	31.36	2406	2.5	13.41	96	194	Off Idle	75.1	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.81	15.03	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:9	31.36	2416	2.51	13.42	96	194	Off Idle	74.2	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.85	15.01	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:9	31.36	2420	2.51	13.4	96	194	Off Idle	73.8	0	2	132	944 Turbo	0.62	Rich	1	14.7	-2.88	14.98	1.02	3.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:10:9	31.36	2430	2.52	13.4	96	194	Off Idle	73.3	0	2	132	944 Turbo	0.57	Rich	1	14.7	-2.86	14.95	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:10:9	31.36	2431	2.52	13.42	96	194	Off Idle	72.9	0	2	132	944 Turbo	0.51	Rich	1	14.7	-2.84	14.89	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:0	31.36	2431	2.53	13.41	96	194	Off Idle	72.4	0	2	132	944 Turbo	0.44	Rich	1	14.7	-2.85	14.85	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:0	31.36	2438	2.53	13.42	96	194	Off Idle	72.1	0	2	132	944 Turbo	0.38	Rich	1	14.7	-2.83	14.82	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:0	31.36	2451	2.54	13.42	96	194	Off Idle	71.8	0	2	132	944 Turbo	0.32	Rich	1	14.7	-2.82	14.81	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:0	31.36	2456	2.54	13.42	96	194	Off Idle	71.5	0	2	132	944 Turbo	0.26	Rich	1	14.7	-2.8	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:0	31.36	2480	2.55	13.42	96	194	Off Idle	71.1	0	2	132	944 Turbo	0.17	Lean	1	14.7	-2.76	14.82	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:0	31.36	2508	2.56	13.43	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.14	Lean	1	14.7	-2.79	14.87	1.01	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:1	31.36	2527	2.56	13.42	96	195	Off Idle	70.6	0	2	132	944 Turbo	0.12	Lean	1	14.7	-2.79	14.91	1.02	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:1	32.72	2561	2.57	13.42	96	195	Off Idle	70.3	0	2	132	944 Turbo	0.14	Lean	1	14.7	-2.78	14.96	1.02	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:1	32.72	2548	2.57	13.42	95	195	Off Idle	69.6	0	2	132	944 Turbo	0.18	Lean	1	14.7	-2.78	14.99	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:1	32.72	2569	2.58	13.43	95	195	Off Idle	69	0	2	132	944 Turbo	0.23	Lean	1	14.7	-2.83	15.03	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:1	32.72	2569	2.58	13.42	95	195	Off Idle	67.8	0	2	132	944 Turbo	0.28	Lean	1	14.7	-2.79	15.06	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:1	32.72	2586	2.59	13.42	95	194	Off Idle	67.2	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.79	15.1	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:1	32.72	2595	2.6	13.42	96	194	Off Idle	66.8	0	2	132	944 Turbo	0.41	Lean	1	14.7	-2.79	15.15	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:2	32.72	2595	2.6	13.43	96	194	Off Idle	66.2	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.78	15.21	1.04	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:2	32.72	2606	2.61	13.43	96	195	Off Idle	65.6	0	2	132	944 Turbo	0.53	Rich	1	14.7	-2.76	15.22	1.04	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:2	32.72	2611	2.61	13.41	96	195	Off Idle	65	0	2	132	944 Turbo	0.59	Rich	1	14.7	-2.79	15.21	1.04	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:11:2	32.72	2617	2.62	13.43	96	195	Off Idle	64.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-2.78	15.13	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:2	32.72	2617	2.63	13.42	96	194	Off Idle	63.9	0	2	132	944 Turbo	0.65	Rich	1	14.7	-2.81	15.1	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:2	32.72	2626	2.64	13.43	96	194	Off Idle	63.9	0	2	132	944 Turbo	0.65	Rich	1	14.7	-2.77	15.07	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:3	32.72	2634	2.64	13.44	96	194	Off Idle	63.3	0	2	132	944 Turbo	0.62	Rich	1	14.7	-2.78	15.02	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:3	32.72	2646	2.65	13.42	96	195	Off Idle	62.7	0	2	132	944 Turbo	0.57	Rich	1	14.7	-2.75	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:3	32.72	2648	2.65	13.43	96	195	Off Idle	62.1	0	2	132	944 Turbo	0.51	Rich	1	14.7	-2.7	14.96	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:3	32.72	2658	2.66	13.43	96	195	Off Idle	61.5	0	2	132	944 Turbo	0.45	Rich	1	14.7	-2.7	14.9	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:3	32.72	2667	2.66	13.44	96	194	Off Idle	60.6	0	2	132	944 Turbo	0.4	Rich	1	14.7	-2.69	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:3	32.72	2672	2.67	13.44	96	194	Off Idle	60.6	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.67	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:4	32.72	2702	2.67	13.43	96	194	Off Idle	60.2	0	2	132	944 Turbo	0.28	Lean	1	14.7	-2.69	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:4	32.72	2707	2.68	13.43	96	194	Off Idle	59.3	0	2	132	944 Turbo	0.24	Lean	1	14.7	-2.69	14.88	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:4	32.72	2710	2.68	13.43	96	194	Off Idle	58.6	0	2	132	944 Turbo	0.21	Lean	1	14.7	-2.68	14.91	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:4	32.72	2728	2.69	13.43	96	194	Off Idle	58	0	2	132	944 Turbo	0.21	Lean	1	14.7	-2.66	14.94	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:4	32.72	2743	2.69	13.42	96	194	Off Idle	57.5	0	2	132	944 Turbo	0.25	Lean	1	14.7	-2.74	14.96	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:4	32.72	2754	2.69	13.43	96	194	Off Idle	56.9	0	2	132	944 Turbo	0.3	Lean	1	14.7	-2.69	14.97	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:4	32.72	2766	2.7	13.43	96	194	Off Idle	56.3	0	2	132	944 Turbo	0.38	Lean	1	14.7	-2.7	15.02	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:5	32.72	2768	2.7	13.42	96	194	Off Idle	55.7	0	2	132	944 Turbo	0.44	Lean	1	14.7	-2.73	15.07	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:5	32.72	2777	2.7	13.43	96	194	Off Idle	55.3	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.74	15.1	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:5	32.72	2780	2.71	13.42	96	194	Off Idle	54.9	0	2	132	944 Turbo	0.52	Rich	1	14.7	-2.74	15.15	1.03	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:5	32.72	2811	2.71	13.42	96	194	Off Idle	53.7	0	2	132	944 Turbo	0.58	Rich	1	14.7	-2.79	15.15	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:5	32.72	2796	2.71	13.42	96	194	Off Idle	53.3	0	2	132	944 Turbo	0.59	Rich	1	14.7	-2.78	15.12	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:5	32.72	2801	2.72	13.43	96	194	Off Idle	52.8	0	2	132	944 Turbo	0.56	Rich	1	14.7	-2.77	15.09	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:6	32.72	2803	2.72	13.43	96	195	Off Idle	52.2	0	2	132	944 Turbo	0.49	Rich	1	14.7	-2.75	15.05	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:6	32.72	2808	2.72	13.42	96	195	Off Idle	52.2	0	2	132	944 Turbo	0.46	Rich	1	14.7	-2.79	15.03	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:6	32.72	2829	2.73	13.43	96	195	Off Idle	51.2	0	2	132	944 Turbo	0.38	Rich	1	14.7	-2.74	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:11:6	32.72	2851	2.73	13.43	96	195	Off Idle	51.1	0	2	132	944 Turbo	0.32	Rich	1	14.7	-2.78	14.95	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:11:6	32.72	2851	2.73	13.43	96	195	Off Idle	50.8	0	2	132	944 Turbo	0.27	Rich	1	14.7	-2.77	14.91	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:11:6	32.72	2888	2.74	13.43	96	195	Off Idle	50.5	0	2	132	944 Turbo	0.23	Rich	1	14.7	-2.78	14.91	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:11:6	32.72	2894	2.74	13.43	96	195	Off Idle	50.1	0	2	132	944 Turbo	0.22	Rich	1	14.7	-2.75	14.94	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:11:7	32.72	2913	2.74	13.44	96	195	Off Idle	49.6	0	2	132	944 Turbo	0.25	Rich	1	14.7	-2.82	14.96	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:11:7	32.72	2916	2.74	13.44	96	195	Off Idle	49	0	2	132	944 Turbo	0.3	Rich	1	14.7	-2.84	14.98	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:7	32.72	2936	2.75	13.45	96	194	Off Idle	48.4	0	2	132	944 Turbo	0.33	Rich	1	14.7	-2.88	15.02	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:7	32.72	2962	2.75	13.45	96	194	Off Idle	47.4	0	2	132	944 Turbo	0.39	Rich	1	14.7	-2.91	15.07	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:7	32.72	2952	2.76	13.44	96	194	Off Idle	46.9	0	2	132	944 Turbo	0.49	Rich	1	14.7	-2.96	15.15	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:7	32.72	2947	2.76	13.44	96	194	Off Idle	46.3	0	2	132	944 Turbo	0.55	Rich	1	14.7	-2.98	15.17	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:8	32.72	2950	2.76	13.43	96	194	Off Idle	45.7	0	2	132	944 Turbo	0.61	Rich	1	14.7	-3.02	15.16	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:8	32.72	2960	2.76	13.44	96	194	Off Idle	45.2	0	2	132	944 Turbo	0.67	Rich	1	14.7	-3.05	15.15	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:11:8	34.08	2960	2.76	13.42	96	195	Off Idle	44.8	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.99	15.11	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:11:8	34.08	2964	2.76	13.42	96	195	Off Idle	44.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	-3.09	15.06	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:11:8	34.08	2969	2.76	13.42	96	195	Off Idle	43.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-3.07	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:11:8	32.72	2972	2.77	13.43	96	195	Off Idle	43.1	0	2	132	944 Turbo	0.67	Rich	1	14.7	-3.08	14.98	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:11:9	32.72	2976	2.77	13.43	96	195	Off Idle	42.7	0	2	132	944 Turbo	0.58	Rich	1	14.7	-3.14	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:11:9	32.72	2989	2.77	13.43	96	195	Off Idle	42.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-3.16	14.85	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:11:9	32.72	3000	2.77	13.44	96	195	Off Idle	42.1	0	2	132	944 Turbo	0.45	Rich	1	14.7	-3.24	14.81	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:9	34.08	3013	2.77	13.43	96	195	Off Idle	41.8	0	2	132	944 Turbo	0.39	Rich	1	14.7	-3.29	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:9	34.08	3016	2.77	13.45	96	195	Off Idle	41.8	0	2	132	944 Turbo	0.32	Rich	1	14.7	-3.39	14.77	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:11:9	34.08	3031	2.77	13.43	96	195	Off Idle	41.6	0	2	132	944 Turbo	0.29	Rich	1	14.7	-3.38	14.77	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:11:9	34.08	3036	2.77	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.23	Rich	1	14.7	-3.42	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:0	34.08	3046	2.76	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.14	Rich	1	14.7	-3.41	14.83	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:0	34.08	3061	2.76	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-3.47	14.87	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:0	34.08	3066	2.76	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.47	14.91	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:0	34.08	3082	2.76	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.48	14.97	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:0	34.08	3112	2.76	13.42	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.55	15	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:0	34.08	3105	2.76	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.6	15.03	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:1	34.08	3108	2.76	13.42	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-3.66	15.08	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:1	34.08	3123	2.76	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-3.74	15.1	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:1	34.08	3138	2.75	13.42	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.7	-3.79	15.12	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:1	34.08	3138	2.75	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.7	-3.83	15.12	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:12:1	34.08	3156	2.75	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-3.9	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:1	34.08	3162	2.75	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.7	-3.94	15.08	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:1	34.08	3161	2.75	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.7	-4.01	15.08	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:2	34.08	3160	2.75	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-4.06	15.08	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:2	34.08	3158	2.74	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.7	-4.07	15.06	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:2	34.08	3166	2.74	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	-4.14	15.04	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:2	34.08	3168	2.74	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	-4.12	15.03	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:2	34.08	3167	2.74	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.7	-4.15	15	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:2	34.08	3178	2.74	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.7	-4.12	14.97	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:3	34.08	3183	2.73	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.7	-4.15	14.96	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:3	34.08	3187	2.73	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.7	-4.11	14.92	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:3	34.08	3202	2.73	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-4.19	14.91	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:3	34.08	3214	2.73	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.7	-4.21	14.9	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:3	34.08	3217	2.73	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-4.22	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:3	34.08	3224	2.73	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.24	14.98	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:4	35.45	3258	2.73	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.25	15.03	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:4	35.45	3258	2.72	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.22	15.08	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:4	35.45	3264	2.72	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.27	15.13	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:4	35.45	3308	2.72	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.31	15.18	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:4	35.45	3308	2.73	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.28	15.24	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:4	35.45	3296	2.73	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.37	15.29	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:4	35.45	3300	2.73	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.42	15.3	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:5	35.45	3308	2.73	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.35	15.28	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:5	35.45	3308	2.73	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.44	15.24	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:5	35.45	3315	2.73	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.48	15.22	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:5	35.45	3318	2.73	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.42	15.16	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:5	35.45	3324	2.73	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.49	15.14	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:12:5	35.45	3326	2.73	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.42	15.11	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:6	35.45	3334	2.73	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.36	15.1	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:6	35.45	3344	2.73	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.35	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:6	35.45	3346	2.74	13.47	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.27	15.09	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:12:6	35.45	3363	2.74	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.18	15.08	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:12:6	35.45	3396	2.75	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.2	15.08	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:6	35.45	3388	2.75	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.14	15.08	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:6	35.45	3382	2.75	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.03	15.09	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:7	35.45	3393	2.77	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-3.99	15.1	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:7	35.45	3396	2.77	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.94	15.1	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:7	35.45	3411	2.77	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.91	15.13	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:7	35.45	3424	2.78	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-3.85	15.15	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:12:7	35.45	3430	2.79	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.7	-3.88	15.15	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:12:7	35.45	3432	2.8	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.2	Rich	1	14.7	-3.79	15.17	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:8	35.45	3457	2.81	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.7	-3.73	15.17	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:8	35.45	3457	2.81	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.7	-3.8	15.19	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:8	35.45	3472	2.82	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.7	-3.73	15.19	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:8	35.45	3474	2.83	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.7	-3.64	15.18	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:8	35.45	3476	2.84	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	-3.66	15.16	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:8	35.45	3482	2.85	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	-3.62	15.12	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:12:9	35.45	3493	2.86	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	-3.6	15.09	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:9	35.45	3496	2.86	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-3.67	15.04	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:9	35.45	3500	2.87	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-3.67	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:9	35.45	3522	2.87	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-3.69	14.9	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:9	35.45	3512	2.88	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-3.74	14.84	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:9	35.45	3513	2.88	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-3.74	14.78	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:12:9	35.45	3521	2.88	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-3.65	14.74	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:13:0	35.45	3531	2.88	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-3.68	14.73	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:13:0	35.45	3532	2.88	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-3.71	14.73	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:0	35.45	3536	2.89	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-3.72	14.75	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:0	35.45	3551	2.89	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-3.7	14.75	1	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:13:0	35.45	3551	2.89	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-3.73	14.75	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:13:0	35.45	3568	2.89	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-3.77	14.76	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:13:1	35.45	3580	2.89	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.49	Lean	1	14.7	-3.72	14.76	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:13:1	35.45	3600	2.89	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.7	-3.67	14.77	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:13:1	35.45	3604	2.89	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.7	-3.7	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:13:1	35.45	3614	2.89	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-3.83	14.81	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:13:1	35.45	3634	2.89	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.7	-3.81	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:13:1	35.45	3647	2.89	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.37	Lean	1	14.7	-3.84	14.84	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:1	35.45	3649	2.89	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.7	-3.87	14.89	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:2	35.45	3651	2.89	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.7	-3.91	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:13:2	35.45	3656	2.89	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.7	-3.94	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:13:2	35.45	3656	2.89	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.7	-4.04	14.92	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:13:2	35.45	3660	2.89	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-4.04	14.93	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:13:2	35.45	3662	2.89	13.44	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-3.99	14.9	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:13:2	35.45	3662	2.89	13.42	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-3.99	14.9	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:13:3	35.45	3655	2.89	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	-4.02	14.89	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:13:3	35.45	3659	2.89	13.42	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-4.07	14.87	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:3	35.45	3659	2.89	13.42	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.7	-4.14	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:3	35.45	3668	2.89	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.7	-4.17	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:3	35.45	3698	2.89	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.7	-4.13	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:3	35.45	3701	2.89	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.7	-4.13	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:4	35.45	3701	2.89	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.7	-4.17	14.84	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:13:4	35.45	3715	2.88	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-4.14	14.93	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:4	35.45	3738	2.88	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.7	-4.21	14.98	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:4	35.45	3751	2.88	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-4.3	14.99	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:4	35.45	3751	2.88	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.7	-4.41	15.04	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:4	35.45	3762	2.87	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-4.51	15.08	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:13:4	36.81	3800	2.85	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.7	-4.98	15.16	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:13:5	36.81	3769	2.81	13.46	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.46	Lean	1	14.7	-5.44	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:13:5	36.81	3766	2.77	13.47	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.99	15.19	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:5	36.81	3753	2.69	13.45	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.7	-6.64	15.15	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:13:5	36.81	3726	2.63	13.45	96	195	Full Load	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.55	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:13:5	36.81	3722	2.6	13.46	96	195	Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:13:5	36.81	3690	2.51	13.45	96	195	Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.56	14.92	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:6	36.81	3599	2.45	13.45	96	195	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-8.94	14.89	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:6	36.81	3599	2.4	13.45	96	195	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.23	14.79	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:6	25.9	3564	2.34	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.42	14.68	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:6	20.45	3526	2.28	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.58	14.53	0.99	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:6	20.45	3546	2.22	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-9.67	14.4	0.98	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:6	20.45	3523	2.13	13.47	96	194	Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-9.69	14.28	0.97	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:6	20.45	3523	2.07	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.75	14.16	0.96	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:7	20.45	3486	2.01	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.77	14	0.95	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:7	20.45	3428	1.95	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.67	Lean	1	14.6	-9.78	13.88	0.95	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:7	20.45	3428	1.87	13.46	96	194	Idle	41.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.82	13.88	0.95	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:7	20.45	3402	1.84	13.46	96	194	Idle	41.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.82	13.77	0.94	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:7	20.45	3354	1.77	13.45	96	194	Idle	40.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.8	13.59	0.93	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:7	20.45	3334	1.74	13.45	96	194	Idle	39.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.79	13.5	0.92	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:8	20.45	3319	1.72	13.46	96	194	Idle	38.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.77	13.42	0.91	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:8	20.45	3255	1.71	13.47	96	194	Idle	37.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.71	13.34	0.91	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:8	20.45	3255	1.71	13.47	96	194	Idle	36.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.65	13.29	0.91	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:8	20.45	3240	1.72	13.46	96	194	Idle	35.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.63	13.25	0.9	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:8	20.45	3218	1.72	13.46	96	194	Idle	34.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.51	13.26	0.9	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:8	20.45	3170	1.72	13.46	96	194	Idle	33.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.47	13.31	0.91	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:9	20.45	3164	1.73	13.46	96	194	Idle	32	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.4	13.4	0.91	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:9	20.45	3122	1.73	13.45	96	194	Idle	29.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	13.53	0.92	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:9	20.45	3106	1.74	13.45	96	194	Idle	28.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.28	13.82	0.94	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:9	20.45	3050	1.75	13.45	96	194	Idle	27.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.22	14.62	1	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:9	20.45	3056	1.76	13.45	96	194	Idle	26.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.21	15.31	1.04	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:13:9	19.09	3029	1.77	13.45	96	194	Idle	26.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	15.66	1.07	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:13:9	19.09	2973	1.78	13.44	96	194	Idle	25.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.16	16.72	1.14	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:0	19.09	2976	1.78	13.44	96	194	Idle	25.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	17.39	1.18	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:0	19.09	2959	1.79	13.44	96	194	Idle	25	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.11	18.05	1.23	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:0	19.09	2919	1.8	13.43	96	194	Idle	24.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	18.66	1.27	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:0	19.09	2919	1.8	13.46	96	194	Idle	24.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	19.25	1.31	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:0	19.09	2886	1.82	13.44	96	194	Idle	24.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	19.75	1.35	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:0	19.09	2853	1.82	13.44	96	194	Idle	24.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.92	20.07	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:1	19.09	2853	1.83	13.44	96	194	Idle	24.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:1	19.09	2822	1.83	13.44	96	194	Idle	24.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.88	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:1	19.09	2789	1.84	13.43	96	194	Idle	24.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.85	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:1	19.09	2757	1.84	13.44	96	194	Idle	24.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.84	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:1	19.09	2758	1.84	13.45	96	194	Idle	25.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.82	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:1	19.09	2715	1.85	13.45	96	194	Idle	25.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.77	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:1	19.09	2672	1.85	13.45	96	194	Idle	25.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.74	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:2	19.09	2657	1.85	13.45	96	194	Idle	26.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.76	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:2	19.09	2657	1.85	13.45	96	194	Idle	26.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.74	20.24	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:2	19.09	2624	1.85	13.44	96	194	Idle	27.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:2	19.09	2590	1.85	13.43	96	194	Idle	28.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.74	20.23	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:2	19.09	2590	1.85	13.43	96	194	Idle	29.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:2	19.09	2558	1.84	13.43	96	194	Idle	30.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:3	19.09	2513	1.84	13.43	96	194	Idle	31.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.7	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:3	19.09	2507	1.83	13.44	96	194	Idle	33.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.71	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:3	19.09	2498	1.83	13.44	96	194	Idle	35.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:3	19.09	2454	1.82	13.44	96	194	Idle	36.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.03	1.36	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:3	19.09	2439	1.82	13.43	96	194	Idle	38	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.75	20.04	1.36	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:3	19.09	2420	1.81	13.42	96	194	Idle	39.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.04	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:4	19.09	2412	1.8	13.44	96	194	Idle	40.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.74	20.04	1.37	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:4	19.09	2368	1.79	13.44	96	194	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.77	20.05	1.37	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:4	19.09	2350	1.78	13.43	96	194	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.8	20.04	1.37	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:4	17.72	2350	1.77	13.44	96	194	Idle	44.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.82	20.03	1.36	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:4	17.72	2296	1.75	13.44	96	194	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.86	20.02	1.36	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:4	17.72	2298	1.74	13.42	96	194	Idle	46.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.83	20.02	1.36	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:4	17.72	2288	1.72	13.42	96	194	Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.86	20.02	1.36	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:5	17.72	2242	1.7	13.41	96	194	Idle	49.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.88	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:5	17.72	2223	1.68	13.4	96	194	Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.9	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:5	17.72	2186	1.66	13.42	96	194	Idle	51.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:5	17.72	2186	1.65	13.44	96	194	Idle	52.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:5	17.72	2150	1.63	13.44	96	194	Idle	53.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:5	17.72	2133	1.61	13.42	96	194	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.11	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:6	17.72	2133	1.59	13.42	96	194	Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.12	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:6	17.72	2116	1.58	13.42	96	194	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.12	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:6	17.72	2106	1.56	13.44	96	194	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.12	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:6	17.72	2097	1.54	13.44	96	194	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.15	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:6	17.72	2105	1.51	13.44	96	194	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.18	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:6	17.72	2105	1.49	13.43	96	194	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.27	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:6	17.72	2106	1.47	13.42	96	194	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.32	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:7	17.72	2109	1.45	13.42	96	194	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:7	17.72	2112	1.43	13.43	96	194	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:7	17.72	2115	1.41	13.45	96	194	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.45	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:7	17.72	2115	1.37	13.46	96	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:7	17.72	2118	1.35	13.46	96	194	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:7	17.72	2124	1.33	13.46	96	194	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:8	17.72	2128	1.31	13.46	96	194	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:8	17.72	2128	1.29	13.47	96	194	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:8	17.72	2136	1.27	13.46	96	194	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:8	17.72	2144	1.25	13.46	96	194	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:8	17.72	2148	1.21	13.44	96	194	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:14:8	17.72	2150	1.19	13.44	96	194	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:9	17.72	2169	1.17	13.42	96	194	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:9	17.72	2153	1.15	13.42	96	194	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:9	17.72	2152	1.12	13.43	96	194	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:9	17.72	2151	1.1	13.44	96	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:9	17.72	2136	1.08	13.44	96	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:9	17.72	2137	1.07	13.44	96	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:14:9	17.72	2134	1.06	13.44	96	194	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:0	17.72	2125	1.03	13.44	96	194	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:0	17.72	2118	1.02	13.42	96	194	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:0	17.72	2118	1.02	13.41	96	194	Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:0	17.72	2112	1	13.41	96	194	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:0	17.72	2108	0.98	13.4	96	194	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:0	17.72	2107	0.97	13.4	96	194	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:1	17.72	2107	0.96	13.42	96	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:1	17.72	2108	0.96	13.42	96	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:1	17.72	2111	0.95	13.43	96	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:1	17.72	2111	0.95	13.43	96	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:1	17.72	2112	0.95	13.44	96	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:1	17.72	2112	0.95	13.44	96	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:1	17.72	2113	0.95	13.44	96	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:2	17.72	2113	0.95	13.44	96	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:2	17.72	2112	0.95	13.42	96	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:2	17.72	2109	0.95	13.41	96	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:2	17.72	2102	0.95	13.41	96	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:2	17.72	2105	0.96	13.4	96	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:2	17.72	2098	0.96	13.41	96	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:3	17.72	2094	0.96	13.41	96	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:3	17.72	2092	0.96	13.41	96	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:3	17.72	2086	0.96	13.41	96	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:3	17.72	2082	0.96	13.42	96	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:3	17.72	2077	0.96	13.44	96	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:3	17.72	2077	0.96	13.45	96	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:4	17.72	2077	0.96	13.45	96	194	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:4	17.72	2070	0.96	13.45	96	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:4	17.72	2070	0.96	13.43	96	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:4	17.72	2068	0.96	13.42	96	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:4	17.72	2069	0.96	13.42	96	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:4	17.72	2068	0.96	13.41	96	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:4	17.72	2066	0.96	13.42	96	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:5	17.72	2066	0.96	13.44	96	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:5	17.72	2065	0.96	13.45	96	194	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:5	17.72	2062	0.96	13.46	96	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:5	17.72	2060	0.96	13.45	96	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:5	17.72	2060	0.96	13.46	96	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:5	17.72	2048	0.96	13.43	96	194	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:6	17.72	2052	0.96	13.43	96	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:6	17.72	2048	0.96	13.42	96	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:6	17.72	2046	0.97	13.42	96	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:6	17.72	2045	0.97	13.43	96	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:6	17.72	2042	0.97	13.45	96	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:6	17.72	2041	0.97	13.45	96	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:6	17.72	2041	0.97	13.46	96	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:7	17.72	2039	0.97	13.45	96	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:7	17.72	2038	0.97	13.44	96	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:7	17.72	2038	0.97	13.42	96	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:7	17.72	2036	0.97	13.42	96	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:7	17.72	2035	0.97	13.43	96	194	Full Load	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:15:7	17.72	2035	0.97	13.42	96	194	Off Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:8	17.72	2034	0.97	13.45	96	194	Off Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:8	17.72	2032	0.98	13.45	96	194	Off Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:8	17.72	1927	0.98	13.44	96	194	Off Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:15:8	9.54	1986	0.99	13.45	96	194	Off Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.52	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:15:8	9.54	2042	0.99	13.45	96	194	Off Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:15:8	12.27	2039	1	13.45	96	194	Off Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:15:9	12.27	2038	1.01	13.45	96	194	Off Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:9	14.99	2033	1.02	13.46	96	194	Off Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:9	17.72	2028	1.03	13.45	96	194	Off Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.38	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:9	17.72	2028	1.04	13.44	96	194	Off Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.31	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:9	20.45	2021	1.05	13.43	96	194	Off Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:15:9	20.45	2016	1.07	13.41	96	194	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:15:9	23.18	2014	1.08	13.4	96	194	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.12	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:16:0	23.18	2012	1.1	13.39	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.05	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:16:0	25.9	2011	1.12	13.4	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:16:0	25.9	2010	1.14	13.39	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.84	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:16:0	28.63	2010	1.16	13.4	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:16:0	28.63	2017	1.19	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:0	31.36	2027	1.22	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.59	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:1	31.36	2030	1.24	13.43	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:16:1	32.72	2021	1.25	13.44	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:16:1	32.72	2029	1.29	13.45	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.39	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:16:1	32.72	2035	1.31	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.33	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:16:1	32.72	2035	1.33	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.28	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:16:1	32.72	2040	1.36	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:16:1	32.72	2043	1.38	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.19	20.22	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:16:2	32.72	2045	1.41	13.45	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.13	20.22	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:16:2	32.72	2046	1.43	13.44	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.05	20.21	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:16:2	32.72	2050	1.45	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.97	20.21	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:16:2	32.72	2046	1.48	13.43	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.89	20.21	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:16:2	32.72	2048	1.5	13.43	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.03	Lean	1	14.7	-8.79	20.2	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:16:2	32.72	2050	1.51	13.43	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.03	Lean	1	14.7	-8.73	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:16:3	32.72	2046	1.53	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.64	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:16:3	32.72	2042	1.55	13.45	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.53	20.21	1.38	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:16:3	32.72	2028	1.58	13.45	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.37	20.22	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:16:3	32.72	2012	1.6	13.45	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-8.25	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:16:3	32.72	2002	1.63	13.45	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-8.09	20.22	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:16:3	32.72	2002	1.64	13.45	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-8.01	20.23	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:16:4	32.72	2001	1.67	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.79	20.23	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:16:4	32.72	2003	1.69	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-7.65	20.22	1.38	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:4	32.72	2003	1.71	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-7.48	20.23	1.38	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:4	32.72	2009	1.73	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.33	20.23	1.38	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:4	32.72	2017	1.76	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.2	20.2	1.38	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:4	32.72	2021	1.77	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-7.07	20.09	1.37	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:4	31.36	2017	1.8	13.46	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-6.95	19.77	1.35	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:5	31.36	2043	1.82	13.45	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-6.85	19.49	1.33	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:5	31.36	2050	1.84	13.44	96	194	Off Idle	86	0	2	132	944 Turbo	0.06	Lean	1	14.7	-6.77	19.18	1.31	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:5	31.36	2050	1.86	13.43	96	194	Off Idle	86	0	2	132	944 Turbo	0.06	Lean	1	14.7	-6.74	18.83	1.28	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:5	31.36	2050	1.88	13.41	96	194	Off Idle	86	0	2	132	944 Turbo	0.07	Lean	1	14.7	-6.7	18.46	1.26	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:5	31.36	2048	1.9	13.4	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.7	-6.63	18.08	1.23	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:5	31.36	2048	1.91	13.4	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.7	-6.58	17.69	1.2	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:6	31.36	2038	1.92	13.39	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.2	Lean	1	14.7	-6.54	17.3	1.18	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:6	31.36	2030	1.94	13.39	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.29	Lean	1	14.7	-6.41	16.97	1.16	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:6	31.36	2030	1.94	13.4	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.36	Lean	1	14.7	-6.33	16.72	1.14	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:6	31.36	2026	1.95	13.4	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.39	Lean	1	14.7	-6.34	16.51	1.12	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:6	31.36	2020	1.95	13.41	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.49	Lean	1	14.7	-6.29	16.34	1.11	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:6	31.36	2017	1.95	13.43	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.56	Rich	1	14.7	-6.27	16.13	1.1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:16:6	31.36	2018	1.95	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.63	Rich	1	14.7	-6.29	16.01	1.09	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:7	31.36	2022	1.95	13.44	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.68	Rich	1	14.7	-6.27	15.88	1.08	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:7	31.36	2024	1.95	13.45	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.7	-6.26	15.77	1.07	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:7	31.36	2026	1.95	13.46	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.7	-6.28	15.65	1.07	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:7	31.36	2029	1.95	13.46	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.32	15.57	1.06	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:7	31.36	2039	1.95	13.46	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.7	-6.3	15.4	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:7	31.36	2051	1.95	13.46	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.3	15.31	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:8	31.36	2051	1.95	13.46	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.7	-6.33	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:8	31.36	2058	1.95	13.46	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.69	Lean	1	14.7	-6.32	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:8	31.36	2057	1.95	13.45	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.64	Lean	1	14.7	-6.32	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:16:8	31.36	2058	1.95	13.43	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.59	Lean	1	14.7	-6.33	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:8	31.36	2060	1.95	13.42	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.53	Lean	1	14.7	-6.33	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:8	31.36	2062	1.95	13.4	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.29	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:9	31.36	2060	1.95	13.4	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.4	Lean	1	14.7	-6.25	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:9	31.36	2059	1.95	13.41	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.34	Lean	1	14.7	-6.21	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:9	31.36	2059	1.95	13.41	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.25	Lean	1	14.7	-6.18	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:9	31.36	2060	1.95	13.42	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.2	Lean	1	14.7	-6.2	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:9	31.36	2058	1.95	13.42	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.17	Lean	1	14.7	-6.19	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:9	31.36	2064	1.95	13.43	96	194	Off Idle	85.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-6.23	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:16:9	31.36	2071	1.95	13.43	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.23	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:0	31.36	2071	1.95	13.41	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.7	-6.3	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:0	31.36	2080	1.95	13.41	96	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.7	-6.32	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:0	31.36	2082	1.95	13.43	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.11	Lean	1	14.7	-6.34	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:0	31.36	2078	1.95	13.43	96	194	Off Idle	85.7	0	2	132	944 Turbo	0.14	Lean	1	14.7	-6.34	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:0	31.36	2079	1.95	13.43	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.18	Lean	1	14.7	-6.31	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:0	31.36	2080	1.95	13.44	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.24	Lean	1	14.7	-6.27	15.14	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:1	31.36	2082	1.96	13.46	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.3	Lean	1	14.7	-6.25	15.18	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:1	31.36	2084	1.96	13.46	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.36	Lean	1	14.7	-6.24	15.2	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:17:1	31.36	2084	1.97	13.44	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.46	Rich	1	14.7	-6.21	15.21	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:17:1	31.36	2089	1.97	13.42	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.52	Rich	1	14.7	-6.14	15.23	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:1	31.36	2095	1.97	13.41	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.58	Rich	1	14.7	-6.09	15.2	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:1	31.36	2095	1.98	13.39	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	-6.08	15.2	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:1	31.36	2096	1.98	13.39	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-5.96	15.2	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:2	31.36	2101	1.99	13.4	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-5.89	15.2	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:2	31.36	2105	1.99	13.4	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-5.81	15.19	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:2	31.36	2106	2	13.41	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-5.72	15.13	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:2	31.36	2114	2.01	13.42	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-5.68	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:17:2	31.36	2128	2.02	13.44	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-5.62	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:17:2	31.36	2138	2.03	13.44	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.57	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:17:3	31.36	2133	2.04	13.45	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.6	Lean	1	14.7	-5.5	15	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:17:3	31.36	2135	2.05	13.42	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.54	Lean	1	14.7	-5.39	14.98	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:17:3	31.36	2139	2.07	13.42	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.47	Lean	1	14.7	-5.26	14.96	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:17:3	31.36	2147	2.09	13.42	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.41	Lean	1	14.7	-5.08	14.91	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:17:3	31.36	2156	2.1	13.43	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.34	Lean	1	14.7	-4.89	14.86	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:17:3	31.36	2156	2.13	13.42	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.25	Lean	1	14.7	-4.71	14.83	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:17:4	31.36	2158	2.14	13.45	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.22	Lean	1	14.7	-4.56	14.82	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:17:4	31.36	2160	2.17	13.43	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.23	14.83	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:17:4	31.36	2163	2.19	13.43	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.7	-4.04	14.84	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:17:4	31.36	2166	2.21	13.43	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.83	14.86	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:4	31.36	2168	2.23	13.43	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.65	14.89	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:4	31.36	2166	2.25	13.44	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.52	14.92	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:4	31.36	2166	2.28	13.43	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.34	14.96	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:5	31.36	2169	2.29	13.43	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-3.29	15.01	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:5	31.36	2175	2.32	13.41	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-3.05	15.1	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:5	31.36	2182	2.34	13.42	96	194	Off Idle	85.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-2.94	15.15	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:5	31.36	2182	2.36	13.42	96	194	Off Idle	85.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	-2.9	15.18	1.03	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:5	31.36	2187	2.37	13.41	96	194	Off Idle	85.4	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.79	15.22	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:5	31.36	2199	2.4	13.44	96	194	Off Idle	85.1	0	2	132	944 Turbo	0.48	Lean	1	14.7	-2.62	15.26	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:17:6	31.36	2199	2.42	13.44	96	194	Off Idle	84.9	0	2	132	944 Turbo	0.55	Lean	1	14.7	-2.52	15.3	1.04	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:6	31.36	2215	2.44	13.44	96	194	Off Idle	84.7	0	2	132	944 Turbo	0.62	Rich	1	14.7	-2.42	15.29	1.04	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:17:6	31.36	2219	2.45	13.43	96	194	Off Idle	84.6	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.29	15.22	1.04	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:17:6	31.36	2220	2.47	13.42	96	194	Off Idle	84.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.29	15.12	1.03	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:17:6	31.36	2228	2.49	13.41	96	194	Off Idle	84.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.16	14.95	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:17:6	31.36	2232	2.5	13.39	96	194	Off Idle	84	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.09	14.82	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:17:6	31.36	2236	2.5	13.39	96	194	Off Idle	83.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.98	14.67	1	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:17:7	31.36	2236	2.52	13.4	96	194	Off Idle	83.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.84	14.52	0.99	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:17:7	31.36	2241	2.52	13.41	96	194	Off Idle	83.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.81	14.38	0.98	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:17:7	31.36	2243	2.53	13.4	96	194	Off Idle	83.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.67	14.22	0.97	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:17:7	29.99	2250	2.55	13.42	96	194	Off Idle	82.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.53	14.02	0.95	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:17:7	29.99	2250	2.57	13.44	96	194	Off Idle	82.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.38	13.95	0.95	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:7	29.99	2254	2.57	13.44	96	194	Off Idle	82.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.21	13.9	0.95	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:17:8	29.99	2258	2.59	13.43	96	194	Off Idle	82.1	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.03	13.85	0.94	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:26:17:8	29.99	2277	2.6	13.43	96	194	Off Idle	81.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.9	13.84	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:8	31.36	2268	2.61	13.43	96	194	Off Idle	81.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.72	13.82	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:8	31.36	2287	2.63	13.42	96	194	Off Idle	81.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.64	13.82	0.94	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:8	31.36	2297	2.64	13.41	96	194	Off Idle	81	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.56	13.82	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:8	31.36	2300	2.65	13.42	96	194	Off Idle	80.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.41	13.8	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:9	31.36	2312	2.66	13.43	96	194	Off Idle	80.1	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.43	13.8	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:9	31.36	2325	2.67	13.42	96	194	Off Idle	79.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.39	13.79	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:9	31.36	2325	2.68	13.43	96	194	Off Idle	79.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.34	13.79	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:9	31.36	2331	2.69	13.43	96	194	Off Idle	78.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.29	13.79	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:9	29.99	2312	2.7	13.44	96	194	Off Idle	78.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.3	13.79	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:17:9	29.99	2324	2.71	13.44	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.27	13.78	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:17:9	29.99	2333	2.72	13.44	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.24	13.78	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:18:0	29.99	2337	2.73	13.44	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.19	13.75	0.94	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:18:0	29.99	2341	2.74	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-0.17	13.72	0.93	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:18:0	29.99	2341	2.75	13.41	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-0.16	13.7	0.93	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:18:0	29.99	2347	2.75	13.41	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-0.15	13.66	0.93	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:18:0	29.99	2355	2.76	13.41	96	194	Off Idle	76.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-0.11	13.64	0.93	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:18:0	29.99	2358	2.76	13.41	96	194	Off Idle	76.3	0	2	132	944 Turbo	0.85	Rich	1	14.7	-0.06	13.6	0.93	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:18:1	29.99	2385	2.77	13.42	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.07	13.55	0.92	3.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:18:1	29.99	2389	2.77	13.41	96	194	Off Idle	76	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.13	13.51	0.92	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:18:1	29.99	2402	2.78	13.41	96	194	Off Idle	75.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.23	13.48	0.92	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:18:1	29.99	2402	2.79	13.43	96	194	Off Idle	75.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.24	13.46	0.92	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:18:1	29.99	2412	2.79	13.43	96	194	Off Idle	75.3	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.24	13.44	0.92	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:18:1	29.99	2432	2.8	13.42	96	194	Off Idle	75	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.24	13.43	0.92	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:18:1	29.99	2426	2.81	13.43	96	194	Off Idle	74.7	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.29	13.43	0.91	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:2	29.99	2424	2.81	13.44	96	194	Off Idle	74.3	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.26	13.44	0.92	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:2	29.99	2427	2.82	13.42	96	194	Off Idle	73.4	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.34	13.44	0.92	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:2	29.99	2430	2.82	13.42	96	194	Off Idle	73.4	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.4	13.44	0.92	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:2	28.63	2422	2.83	13.42	96	194	Off Idle	72.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	0.44	13.44	0.92	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:2	28.63	2442	2.84	13.42	96	194	Off Idle	72.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.46	13.45	0.92	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:2	28.63	2450	2.85	13.42	96	194	Off Idle	71.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.52	13.47	0.92	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:3	28.63	2452	2.85	13.41	96	194	Off Idle	71.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.5	13.49	0.92	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:3	28.63	2473	2.86	13.4	96	194	Off Idle	71.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.55	13.53	0.92	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:3	28.63	2471	2.87	13.4	96	194	Off Idle	70.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.62	13.55	0.92	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:3	28.63	2474	2.87	13.4	96	194	Off Idle	70.3	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.67	13.56	0.92	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:3	28.63	2482	2.88	13.41	96	194	Off Idle	70	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.71	13.57	0.92	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:3	28.63	2496	2.89	13.43	96	194	Off Idle	70	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.74	13.6	0.93	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:4	29.99	2496	2.89	13.43	96	194	Off Idle	69.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.73	13.63	0.93	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:4	29.99	2514	2.9	13.41	96	194	Off Idle	69.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.78	13.66	0.93	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:4	29.99	2526	2.9	13.41	96	194	Off Idle	68.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	0.77	13.69	0.93	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:4	29.99	2536	2.91	13.43	96	194	Off Idle	68.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.8	13.69	0.93	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:4	29.99	2536	2.91	13.42	96	194	Off Idle	68.1	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.82	13.69	0.93	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:4	29.99	2541	2.92	13.42	96	194	Off Idle	67.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.86	13.7	0.93	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:4	29.99	2545	2.92	13.42	96	194	Off Idle	67.2	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.87	13.72	0.93	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:18:5	29.99	2546	2.93	13.44	96	194	Off Idle	66.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.94	13.74	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:5	29.99	2548	2.93	13.43	96	194	Off Idle	66.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.94	13.74	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:5	28.63	2556	2.94	13.44	96	194	Off Idle	65.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	0.91	13.74	0.94	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:26:18:5	28.63	2561	2.94	13.44	96	194	Off Idle	65.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	0.93	13.75	0.94	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:5	28.63	2562	2.95	13.43	96	194	Off Idle	65.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	1	13.75	0.94	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:5	28.63	2569	2.95	13.42	96	194	Off Idle	64.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	1.03	13.75	0.94	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:6	28.63	2578	2.95	13.42	96	194	Off Idle	64.3	0	2	132	944 Turbo	0.83	Rich	1	14.7	1.04	13.75	0.94	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:6	28.63	2602	2.96	13.4	96	194	Off Idle	63.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	1.09	13.77	0.94	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:6	28.63	2598	2.96	13.42	96	194	Off Idle	63.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	1.12	13.77	0.94	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:26:18:6	28.63	2608	2.97	13.4	96	194	Off Idle	63.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	1.11	13.79	0.94	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:26:18:6	28.63	2621	2.98	13.39	96	194	Off Idle	62.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	1.12	13.8	0.94	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:26:18:6	28.63	2635	2.98	13.4	96	194	Off Idle	62.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	1.17	13.84	0.94	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:26:18:6	28.63	2635	2.99	13.4	96	194	Off Idle	62.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	1.24	13.87	0.94	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:26:18:7	28.63	2642	2.99	13.4	96	194	Off Idle	62.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.25	13.93	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:26:18:7	28.63	2644	3	13.41	96	194	Off Idle	61.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.24	13.98	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:26:18:7	28.63	2642	3	13.41	96	194	Off Idle	61.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.29	14.01	0.95	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:26:18:7	28.63	2642	3.01	13.42	96	194	Off Idle	60.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.33	14.05	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:7	28.63	2643	3.01	13.41	96	194	Off Idle	60.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.43	14.05	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:7	28.63	2645	3.02	13.42	96	194	Off Idle	60	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.47	14.09	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:8	28.63	2645	3.03	13.4	96	194	Off Idle	59.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.54	14.1	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:8	28.63	2668	3.03	13.42	96	194	Off Idle	59.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.59	14.12	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:8	28.63	2696	3.04	13.41	96	194	Off Idle	58.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.67	14.15	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:8	28.63	2706	3.05	13.41	96	194	Off Idle	58.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.69	14.12	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:8	28.63	2707	3.05	13.44	96	194	Off Idle	58.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.63	14.13	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:8	28.63	2726	3.06	13.42	96	194	Off Idle	57.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.7	14.13	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:9	28.63	2734	3.06	13.44	96	194	Off Idle	57.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	1.72	14.13	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:9	28.63	2734	3.07	13.43	96	194	Off Idle	57	0	2	132	944 Turbo	0.81	Rich	1	14.7	1.69	14.16	0.96	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:26:18:9	28.63	2740	3.08	13.43	96	194	Off Idle	56.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	1.74	14.19	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:18:9	28.63	2738	3.08	13.42	96	194	Off Idle	56.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	1.79	14.21	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:18:9	28.63	2738	3.09	13.43	96	194	Off Idle	55.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	1.83	14.21	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:18:9	28.63	2746	3.09	13.41	96	194	Off Idle	55.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	1.93	14.2	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:18:9	28.63	2753	3.1	13.41	96	194	Off Idle	55.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	2.05	14.21	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:19:0	28.63	2756	3.11	13.42	96	194	Off Idle	54.9	0	2	132	944 Turbo	0.78	Rich	1	14.7	2.03	14.21	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:19:0	28.63	2760	3.11	13.41	96	194	Off Idle	54.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	2.1	14.21	0.97	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:26:19:0	28.63	2774	3.12	13.41	96	194	Off Idle	54.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	2.19	14.24	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:19:0	28.63	2780	3.12	13.41	96	194	Off Idle	53.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	2.17	14.25	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:19:0	28.63	2798	3.13	13.41	96	194	Off Idle	53.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	2.21	14.25	0.97	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:26:19:0	28.63	2814	3.13	13.41	96	194	Off Idle	52.7	0	2	132	944 Turbo	0.8	Rich	1	14.7	2.35	14.28	0.97	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:19:1	28.63	2824	3.14	13.4	96	194	Off Idle	52.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	2.4	14.3	0.97	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:19:1	28.63	2824	3.14	13.42	96	194	Off Idle	51.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	2.42	14.33	0.98	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:19:1	28.63	2829	3.15	13.41	96	194	Off Idle	51.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	2.49	14.37	0.98	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:26:19:1	28.63	2828	3.16	13.42	96	194	Off Idle	50.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	2.53	14.37	0.98	3.5	5.9	ON	28 Pin	OFF	Removed	Disabled
03:26:19:1	28.63	2826	3.17	13.42	96	194	Off Idle	50.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	2.59	14.39	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:1	28.63	2820	3.17	13.42	96	194	Off Idle	50.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	2.55	14.41	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:1	28.63	2828	3.18	13.42	96	194	Off Idle	49.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	2.67	14.42	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:2	28.63	2832	3.18	13.42	96	194	Off Idle	49.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	2.7	14.44	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:2	28.63	2841	3.19	13.42	96	194	Off Idle	49.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	2.83	14.44	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:2	28.63	2854	3.2	13.43	96	194	Off Idle	48.9	0	2	132	944 Turbo	0.78	Rich	1	14.7	2.85	14.45	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:2	28.63	2881	3.2	13.43	96	194	Off Idle	48.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	2.91	14.46	0.98	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:2	28.63	2881	3.21	13.42	96	194	Off Idle	48.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	2.97	14.48	0.99	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:2	27.27	2894	3.22	13.42	96	194	Off Idle	48.1	0	2	132	944 Turbo	0.78	Rich	1	14.7	2.93	14.51	0.99	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:3	27.27	2901	3.22	13.43	96	194	Off Idle	47.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	2.94	14.52	0.99	3.5	6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:3	27.27	2908	3.23	13.43	96	194	Off Idle	47.1	0	2	132	944 Turbo	0.77	Rich	1	14.7	3.04	14.53	0.99	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:26:19:3	27.27	2918	3.24	13.44	96	194	Off Idle	46.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	3.08	14.53	0.99	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:26:19:3	27.27	2918	3.24	13.42	96	194	Off Idle	46	0	2	132	944 Turbo	0.77	Rich	1	14.7	3.18	14.54	0.99	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:26:19:3	27.27	2928	3.25	13.42	96	194	Off Idle	45.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	3.33	14.57	0.99	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:26:19:3	27.27	2928	3.25	13.42	96	194	Off Idle	45.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	3.3	14.59	0.99	3.5	6.1	ON	28 Pin	OFF	Removed	Disabled
03:26:19:4	27.27	2930	3.26	13.42	96	194	Off Idle	45	0	2	132	944 Turbo	0.76	Rich	1	14.7	3.45	14.61	1	3.5	6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:19:4	28.63	2960	3.27	13.42	96	194	Off Idle	44.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	3.5	14.63	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:26:19:4	28.63	2933	3.28	13.42	96	194	Off Idle	44.1	0	2	132	944 Turbo	0.76	Rich	1	14.7	3.57	14.63	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:26:19:4	28.63	2951	3.28	13.42	96	194	Off Idle	43.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	3.57	14.63	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:26:19:4	28.63	2952	3.29	13.42	96	194	Off Idle	43.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	3.71	14.65	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:26:19:4	27.27	2962	3.29	13.42	96	194	Off Idle	43	0	2	132	944 Turbo	0.73	Rich	1	14.7	3.77	14.67	1	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:26:19:4	27.27	2986	3.3	13.42	96	194	Off Idle	42.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	3.78	14.7	1	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:26:19:5	27.27	2986	3.31	13.42	96	194	Off Idle	42.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	3.84	14.74	1	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:26:19:5	27.27	2994	3.32	13.41	96	194	Off Idle	42.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	3.99	14.77	1.01	3.5	6.2	ON	28 Pin	OFF	Removed	Disabled
03:26:19:5	27.27	3015	3.33	13.42	96	194	Off Idle	42	0	2	132	944 Turbo	0.7	Rich	1	14.7	3.96	14.8	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:26:19:5	27.27	3009	3.33	13.41	96	194	Off Idle	41.8	0	2	132	944 Turbo	0.69	Rich	1	14.7	4.11	14.81	1.01	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:26:19:5	27.27	3009	3.34	13.41	96	194	Off Idle	41.8	0	2	132	944 Turbo	0.68	Rich	1	14.7	4.1	14.84	1.01	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:26:19:5	27.27	3024	3.35	13.41	96	194	Off Idle	41.8	0	2	132	944 Turbo	0.67	Rich	1	14.7	4.32	14.86	1.01	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:26:19:6	27.27	3030	3.35	13.41	96	194	Off Idle	41.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	4.33	14.87	1.01	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:26:19:6	27.27	3033	3.36	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	4.5	14.88	1.01	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:26:19:6	27.27	3040	3.37	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	4.58	14.92	1.02	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:26:19:6	27.27	3053	3.37	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	4.55	14.92	1.02	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:6	27.27	3057	3.38	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.7	4.67	14.94	1.02	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:6	27.27	3085	3.39	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	4.71	14.94	1.02	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:26:19:6	27.27	3073	3.4	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	4.85	14.95	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:19:7	27.27	3076	3.41	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.7	4.99	14.94	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:19:7	27.27	3076	3.41	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.7	5.02	14.95	1.02	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:26:19:7	25.9	3076	3.42	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	5.12	14.98	1.02	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:26:19:7	25.9	3107	3.43	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.7	5.18	14.99	1.02	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:26:19:7	25.9	3108	3.44	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.46	Rich	1	14.7	5.33	14.99	1.02	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:26:19:7	25.9	3111	3.45	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	5.39	15.04	1.02	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:26:19:8	25.9	3137	3.46	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.7	5.55	15.06	1.03	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:19:8	25.9	3151	3.47	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.7	5.54	15.04	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:19:8	27.27	3154	3.47	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	5.67	15.01	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:19:8	27.27	3163	3.48	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	5.75	14.95	1.02	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:19:8	27.27	3171	3.49	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	5.79	14.93	1.02	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:26:19:8	25.9	3162	3.49	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	5.91	14.9	1.01	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:26:19:9	25.9	3188	3.51	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	6.03	14.84	1.01	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:26:19:9	25.9	3190	3.51	13.41	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	6.16	14.84	1.01	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:26:19:9	25.9	3190	3.52	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	6.17	14.79	1.01	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:26:19:9	25.9	3182	3.53	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	6.36	14.72	1	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:26:19:9	24.54	3208	3.53	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	6.35	14.68	1	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:26:19:9	24.54	3215	3.54	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	6.38	14.68	1	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:26:19:9	24.54	3219	3.55	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	6.44	14.69	1	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:0	24.54	3234	3.55	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	6.5	14.71	1	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:0	24.54	3251	3.56	13.41	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	6.55	14.7	1	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:0	24.54	3263	3.57	13.42	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	6.58	14.64	1	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:0	24.54	3267	3.57	13.4	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	6.7	14.53	0.99	3.5	8.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:0	24.54	3282	3.58	13.42	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	6.65	14.35	0.98	3.4	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:0	24.54	3298	3.59	13.42	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	6.78	14.18	0.97	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:1	24.54	3300	3.59	13.41	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	6.88	13.99	0.95	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:1	24.54	3316	3.6	13.41	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.83	Rich	1	14.7	6.95	13.78	0.94	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:1	24.54	3327	3.6	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	6.9	13.54	0.92	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:1	25.9	3340	3.61	13.41	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	7.11	13.33	0.91	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:1	25.9	3328	3.61	13.41	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	7.13	13.12	0.89	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:1	25.9	3342	3.62	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	7.16	12.81	0.87	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:1	25.9	3359	3.63	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	7.31	12.73	0.87	3.5	9.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:2	25.9	3362	3.63	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	7.36	12.58	0.86	3.5	9.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:2	24.54	3376	3.64	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	7.36	12.51	0.85	3.5	9.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:2	24.54	3406	3.64	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	7.5	12.47	0.85	3.5	9.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:2	24.54	3404	3.65	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	7.61	12.41	0.85	3.5	9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:2	24.54	3408	3.65	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	7.65	12.39	0.84	3.5	9.2	ON	28 Pin	OFF	Removed	Disabled
03:26:20:2	24.54	3418	3.66	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	7.72	12.39	0.84	3.5	9.2	ON	28 Pin	OFF	Removed	Disabled
03:26:20:3	24.54	3415	3.67	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	7.94	12.35	0.84	3.5	9.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:20:3	24.54	3415	3.67	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	7.92	12.32	0.84	3.5	9.4	ON	28 Pin	OFF	Removed	Disabled
03:26:20:3	24.54	3420	3.68	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	8.01	12.34	0.84	3.5	9.5	ON	28 Pin	OFF	Removed	Disabled
03:26:20:3	24.54	3435	3.69	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	8.16	12.32	0.84	3.5	9.6	ON	28 Pin	OFF	Removed	Disabled
03:26:20:3	24.54	3442	3.7	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	8.18	12.32	0.84	3.5	9.7	ON	28 Pin	OFF	Removed	Disabled
03:26:20:3	24.54	3446	3.71	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	8.25	12.3	0.84	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:4	24.54	3474	3.71	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	8.5	12.29	0.84	3.5	9.7	ON	28 Pin	OFF	Removed	Disabled
03:26:20:4	24.54	3534	3.72	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	8.46	12.3	0.84	3.5	9.7	ON	28 Pin	OFF	Removed	Disabled
03:26:20:4	24.54	3517	3.73	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	8.58	12.27	0.84	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:4	24.54	3506	3.74	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	8.78	12.28	0.84	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:4	24.54	3497	3.75	13.38	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	8.73	12.27	0.84	3.5	9.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:4	24.54	3502	3.76	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	8.76	12.23	0.83	3.5	9.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:4	23.18	3517	3.77	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	9.05	12.19	0.83	3.5	10.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:5	23.18	3531	3.77	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	9.14	12.16	0.83	3.5	10.2	ON	28 Pin	OFF	Removed	Disabled
03:26:20:5	23.18	3529	3.79	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	9.17	12.12	0.83	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:26:20:5	23.18	3565	3.8	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	9.37	12.12	0.83	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:26:20:5	24.54	3557	3.8	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	9.52	12.08	0.82	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:26:20:5	24.54	3564	3.81	13.39	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	9.57	12.06	0.82	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:26:20:5	24.54	3584	3.82	13.39	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	9.7	12.04	0.82	3.5	10.4	ON	28 Pin	OFF	Removed	Disabled
03:26:20:6	24.54	3605	3.83	13.38	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	9.81	12.02	0.82	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:26:20:6	23.18	3598	3.84	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	9.81	12.02	0.82	3.5	10.7	ON	28 Pin	OFF	Removed	Disabled
03:26:20:6	23.18	3644	3.84	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	9.77	12	0.82	3.5	10.7	ON	28 Pin	OFF	Removed	Disabled
03:26:20:6	23.18	3659	3.85	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	9.97	11.93	0.81	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:6	23.18	3666	3.86	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	10.21	11.89	0.81	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:6	23.18	3683	3.88	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	10.38	11.84	0.81	3.5	10.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:6	23.18	3702	3.89	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	10.54	11.81	0.8	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:7	23.18	3703	3.9	13.38	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	10.77	11.78	0.8	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:7	23.18	3717	3.91	13.38	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	10.77	11.74	0.8	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:26:20:7	23.18	3715	3.92	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	10.74	11.71	0.8	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:26:20:7	24.54	3717	3.93	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	10.81	11.7	0.8	3.5	11.3	ON	28 Pin	OFF	Removed	Disabled
03:26:20:7	24.54	3730	3.94	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	10.92	11.64	0.79	3.6	11.5	ON	28 Pin	OFF	Removed	Disabled
03:26:20:7	24.54	3742	3.95	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	11.1	11.66	0.79	3.6	11.8	ON	28 Pin	OFF	Removed	Disabled
03:26:20:8	24.54	3748	3.96	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	11.42	11.66	0.79	3.6	11.7	ON	28 Pin	OFF	Removed	Disabled
03:26:20:8	24.54	3731	3.97	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.65	11.65	0.79	3.6	11.7	ON	28 Pin	OFF	Removed	Disabled
03:26:20:8	23.18	3750	3.98	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.78	11.61	0.79	3.6	11.7	ON	28 Pin	OFF	Removed	Disabled
03:26:20:8	23.18	3752	3.99	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.76	11.59	0.79	3.5	11.9	ON	28 Pin	OFF	Removed	Disabled
03:26:20:8	23.18	3768	4	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.79	11.52	0.78	3.5	12.4	ON	28 Pin	OFF	Removed	Disabled
03:26:20:8	23.18	3796	4	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.88	11.48	0.78	3.5	12.3	ON	28 Pin	OFF	Removed	Disabled
03:26:20:9	23.18	3798	4.01	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12	11.44	0.78	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:9	23.18	3798	4.02	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.03	11.39	0.78	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:9	23.18	3808	4.03	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.04	11.36	0.77	3.6	12.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:9	23.18	3822	4.04	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	11.94	11.33	0.77	3.6	12.1	ON	28 Pin	OFF	Removed	Disabled
03:26:20:9	23.18	3828	4.05	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.86	11.29	0.77	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:26:20:9	23.18	3860	4.06	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.92	11.29	0.77	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:26:20:9	23.18	3894	4.07	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.22	11.25	0.77	3.5	12.7	ON	28 Pin	OFF	Removed	Disabled
03:26:21:0	23.18	3903	4.07	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.41	11.23	0.76	3.5	12.6	ON	28 Pin	OFF	Removed	Disabled
03:26:21:0	23.18	3905	4.08	13.38	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.44	11.21	0.76	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:26:21:0	23.18	3937	4.09	13.36	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.48	11.19	0.76	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:26:21:0	23.18	3937	4.1	13.35	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.42	11.16	0.76	3.5	12.6	ON	28 Pin	OFF	Removed	Disabled
03:26:21:0	23.18	3946	4.1	13.38	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.27	11.14	0.76	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:26:21:0	23.18	3956	4.11	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.26	11.09	0.76	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:1	23.18	3995	4.12	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.22	11.05	0.75	3.5	13.1	ON	28 Pin	OFF	Removed	Disabled
03:26:21:1	23.18	3980	4.12	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.33	11	0.75	3.5	12.7	ON	28 Pin	OFF	Removed	Disabled
03:26:21:1	23.18	3949	4.13	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.39	10.96	0.75	3.5	12.8	ON	28 Pin	OFF	Removed	Disabled
03:26:21:1	23.18	3957	4.14	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.61	10.94	0.75	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:26:21:1	23.18	3960	4.14	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.71	10.93	0.74	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:26:21:1	23.18	3974	4.15	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.91	10.89	0.74	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:1	23.18	4020	4.16	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.83	10.87	0.74	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:2	23.18	4015	4.16	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.95	10.85	0.74	3.5	13.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:21:2	23.18	4020	4.17	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.83	10.85	0.74	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:26:21:2	23.18	4062	4.17	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.88	10.83	0.74	3.5	13	ON	28 Pin	OFF	Removed	Disabled
03:26:21:2	23.18	4061	4.18	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.93	10.79	0.74	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:26:21:2	23.18	4064	4.18	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.93	10.78	0.73	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:2	23.18	4076	4.19	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.85	10.72	0.73	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:3	23.18	4102	4.19	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.72	10.7	0.73	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:26:21:3	23.18	4108	4.2	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.72	10.68	0.73	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:3	23.18	4111	4.2	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.56	10.69	0.73	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:3	23.18	4115	4.2	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.55	10.67	0.73	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:26:21:3	23.18	4118	4.21	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.5	10.64	0.73	3.5	13.1	ON	28 Pin	OFF	Removed	Disabled
03:26:21:3	23.18	4134	4.21	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.43	10.62	0.72	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:26:21:4	23.18	4132	4.22	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.41	10.64	0.72	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:26:21:4	23.18	4138	4.22	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.41	10.64	0.72	3.6	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:4	23.18	4140	4.22	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.51	10.63	0.72	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:4	23.18	4142	4.23	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.59	10.61	0.72	3.6	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:4	23.18	4168	4.23	13.37	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.92	10.61	0.72	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:4	23.18	4175	4.23	13.36	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.95	10.57	0.72	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:4	23.18	4178	4.24	13.38	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	13.13	10.52	0.72	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:5	24.54	4223	4.24	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	13	10.49	0.71	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:5	24.54	4237	4.24	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.81	10.47	0.71	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:5	24.54	4241	4.25	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.51	10.45	0.71	3.5	13.5	ON	28 Pin	OFF	Removed	Disabled
03:26:21:5	24.54	4260	4.25	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.41	10.42	0.71	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:5	24.54	4314	4.26	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.31	10.39	0.71	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:5	24.54	4314	4.26	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.42	10.37	0.71	3.5	13.2	ON	28 Pin	OFF	Removed	Disabled
03:26:21:6	24.54	4314	4.26	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.48	10.35	0.7	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:6	24.54	4316	4.27	13.38	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.7	12.54	10.34	0.7	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:6	24.54	4316	4.27	13.37	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.7	12.71	10.33	0.7	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:6	23.18	4316	4.27	13.37	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.7	12.67	10.29	0.7	3.5	13.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:6	23.18	4302	4.28	13.38	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.7	12.77	10.28	0.7	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:6	23.18	4282	4.28	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.91	Rich	1	14.7	12.94	10.28	0.7	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:6	23.18	4283	4.29	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.94	10.3	0.7	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:7	24.54	4301	4.29	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	12.99	10.29	0.7	3.5	13.6	ON	28 Pin	OFF	Removed	Disabled
03:26:21:7	24.54	4288	4.29	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.87	10.3	0.7	3.5	13.6	ON	28 Pin	OFF	Removed	Disabled
03:26:21:7	24.54	4329	4.29	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.77	10.29	0.7	3.5	13.4	ON	28 Pin	OFF	Removed	Disabled
03:26:21:7	24.54	4336	4.3	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	12.69	10.32	0.7	3.5	13.5	ON	28 Pin	OFF	Removed	Disabled
03:26:21:7	24.54	4371	4.3	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	12.74	10.31	0.7	3.5	13.5	ON	28 Pin	OFF	Removed	Disabled
03:26:21:7	24.54	4395	4.3	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	12.58	10.32	0.7	3.5	13.5	ON	28 Pin	OFF	Removed	Disabled
03:26:21:8	24.54	4400	4.3	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	12.48	10.33	0.7	3.5	13.5	ON	28 Pin	OFF	Removed	Disabled
03:26:21:8	24.54	4434	4.31	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	12.41	10.3	0.7	3.5	13.5	ON	28 Pin	OFF	Removed	Disabled
03:26:21:8	24.54	4447	4.31	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	12.17	10.25	0.7	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:21:8	24.54	4453	4.31	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	12.29	10.24	0.7	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:21:8	24.54	4454	4.31	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	12.22	10.24	0.7	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:21:8	24.54	4468	4.31	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.08	10.2	0.7	3.5	7	ON	28 Pin	OFF	Removed	Disabled
03:26:21:9	24.54	4472	4.31	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	12.02	10.2	0.69	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:26:21:9	25.9	4488	4.31	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	11.85	10.19	0.69	3.5	12.9	ON	28 Pin	OFF	Removed	Disabled
03:26:21:9	25.9	4502	4.3	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.64	10.23	0.7	3.5	12.7	ON	28 Pin	OFF	Removed	Disabled
03:26:21:9	25.9	4477	4.3	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	11.62	10.22	0.7	3.5	12.5	ON	28 Pin	OFF	Removed	Disabled
03:26:21:9	25.9	4482	4.29	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	11.43	10.23	0.7	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:26:21:9	25.9	4496	4.29	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	11.29	10.23	0.7	3.5	12.1	ON	28 Pin	OFF	Removed	Disabled
03:26:21:9	25.9	4510	4.28	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.17	10.22	0.7	3.5	12	ON	28 Pin	OFF	Removed	Disabled
03:26:22:0	25.9	4512	4.28	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	11.07	10.22	0.7	3.5	12	ON	28 Pin	OFF	Removed	Disabled
03:26:22:0	25.9	4533	4.27	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.78	10.22	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:26:22:0	25.9	4539	4.27	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.66	10.23	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:26:22:0	25.9	4536	4.27	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	10.7	10.26	0.7	3.5	11.7	ON	28 Pin	OFF	Removed	Disabled
03:26:22:0	25.9	4551	4.26	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.73	10.27	0.7	3.5	11.8	ON	28 Pin	OFF	Removed	Disabled
03:26:22:0	25.9	4556	4.26	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.88	10.3	0.7	3.5	11.8	ON	28 Pin	OFF	Removed	Disabled
03:26:22:1	25.9	4562	4.25	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.96	10.34	0.7	3.5	11.8	ON	28 Pin	OFF	Removed	Disabled
03:26:22:1	25.9	4574	4.25	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	10.9	10.39	0.71	3.5	11.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:22:1	25.9	4591	4.24	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	10.78	10.47	0.71	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:26:22:1	25.9	4593	4.24	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	10.61	10.54	0.72	3.6	11.7	ON	28 Pin	OFF	Removed	Disabled
03:26:22:1	25.9	4598	4.23	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.26	10.59	0.72	3.6	11.7	ON	28 Pin	OFF	Removed	Disabled
03:26:22:1	25.9	4590	4.23	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.23	10.64	0.72	3.6	11.6	ON	28 Pin	OFF	Removed	Disabled
03:26:22:1	25.9	4612	4.23	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	10.14	10.62	0.72	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:26:22:2	27.27	4619	4.23	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.88	10.61	0.72	3.5	11.6	ON	28 Pin	OFF	Removed	Disabled
03:26:22:2	27.27	4622	4.22	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	9.76	10.66	0.73	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:26:22:2	27.27	4636	4.22	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.82	10.68	0.73	3.5	11.4	ON	28 Pin	OFF	Removed	Disabled
03:26:22:2	27.27	4650	4.22	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.62	10.68	0.73	3.5	11.1	ON	28 Pin	OFF	Removed	Disabled
03:26:22:2	27.27	4657	4.21	13.41	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.35	10.67	0.73	3.5	10.9	ON	28 Pin	OFF	Removed	Disabled
03:26:22:2	27.27	4676	4.21	13.43	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.28	10.66	0.73	3.5	10.6	ON	28 Pin	OFF	Removed	Disabled
03:26:22:3	27.27	4698	4.2	13.42	96	195	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.12	10.65	0.73	3.5	10.6	ON	28 Pin	OFF	Removed	Disabled
03:26:22:3	27.27	4714	4.2	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	9.08	10.62	0.72	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:26:22:3	27.27	4732	4.19	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	8.87	10.6	0.72	3.5	10.5	ON	28 Pin	OFF	Removed	Disabled
03:26:22:3	27.27	4720	4.19	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	8.66	10.64	0.72	3.5	10.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:3	27.27	4712	4.18	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	8.43	10.66	0.73	3.5	10.1	ON	28 Pin	OFF	Removed	Disabled
03:26:22:3	27.27	4712	4.17	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	8.01	10.67	0.73	3.5	10	ON	28 Pin	OFF	Removed	Disabled
03:26:22:4	28.63	4730	4.14	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	7.11	10.68	0.73	3.5	9.4	ON	28 Pin	OFF	Removed	Disabled
03:26:22:4	28.63	4687	4.13	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	6.42	10.7	0.73	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:26:22:4	28.63	4648	4.08	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	5.23	10.7	0.73	3.5	8	ON	28 Pin	OFF	Removed	Disabled
03:26:22:4	28.63	4628	4.01	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	3.68	10.71	0.73	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:22:4	28.63	4565	3.92	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	2	10.69	0.73	3.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:26:22:4	34.08	4522	3.81	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	0.13	10.68	0.73	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:4	34.08	4464	3.67	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.9	Rich	1	14.6	-1.77	10.66	0.73	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:22:5	34.08	4448	3.4	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.38	10.6	0.72	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:22:5	34.08	4452	3.21	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-4.59	10.54	0.72	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:22:5	35.45	4463	3.01	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.87	Rich	1	14.6	-6.17	10.45	0.71	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:22:5	35.45	4452	2.82	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-6.85	10.41	0.71	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:22:5	35.45	4456	2.63	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-7.16	10.44	0.71	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:5	36.81	4464	2.36	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-8.03	10.49	0.71	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:6	36.81	4426	2.18	13.39	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-8.53	10.61	0.72	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:6	36.81	4393	2	13.39	96	194	Full Load	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.87	10.71	0.73	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:6	38.18	4385	1.73	13.4	96	194	Idle	41.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-9.2	10.81	0.74	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:6	38.18	4346	1.64	13.4	96	194	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.4	11.03	0.75	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:6	38.18	4253	1.47	13.39	96	194	Idle	41.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.5	11.21	0.76	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:26:22:6	38.18	4267	1.32	13.39	96	194	Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.56	11.39	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:6	35.45	4228	1.19	13.42	96	194	Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.59	11.53	0.79	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:7	29.99	4146	1.07	13.43	96	194	Idle	41.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.59	11.65	0.79	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:7	24.54	4138	0.94	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.67	11.87	0.81	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:7	20.45	4140	0.91	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.72	11.99	0.82	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:7	20.45	4120	0.86	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.79	12.25	0.83	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:7	20.45	4080	0.82	13.47	96	194	Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.87	12.7	0.86	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:7	20.45	4071	0.83	13.48	96	194	Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.92	13.02	0.89	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:8	20.45	4026	0.87	13.49	96	194	Idle	40.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.89	13.44	0.92	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:8	20.45	3991	0.96	13.48	96	194	Idle	40.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.87	13.67	0.93	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:8	20.45	3966	1.02	13.48	96	194	Idle	39.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.87	14.42	0.98	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:8	20.45	3938	1.09	13.48	96	194	Idle	38.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.87	14.97	1.02	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:8	20.45	3866	1.18	13.48	96	194	Idle	36	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.85	15.54	1.06	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:8	20.45	3859	1.23	13.45	96	194	Idle	34.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.81	16.11	1.1	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:9	20.45	3852	1.29	13.43	96	194	Idle	33.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.77	16.65	1.13	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:9	20.45	3794	1.35	13.42	96	194	Idle	32.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.74	17.22	1.17	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:9	20.45	3787	1.42	13.41	96	194	Idle	31	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.7	17.8	1.21	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:9	20.45	3772	1.5	13.43	96	194	Idle	29.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.67	18.3	1.25	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:9	20.45	3736	1.54	13.45	96	194	Idle	28.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	18.7	1.27	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:9	20.45	3690	1.57	13.46	96	194	Idle	26.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	19.03	1.3	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:22:9	20.45	3690	1.59	13.46	96	194	Idle	25.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.47	19.33	1.32	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:23:0	20.45	3634	1.62	13.46	96	194	Idle	23	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.42	19.57	1.33	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:23:0	20.45	3615	1.64	13.45	96	194	Idle	22.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.32	19.75	1.35	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:23:0	20.45	3606	1.66	13.43	96	194	Idle	21.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.27	19.93	1.36	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:23:0	20.45	3567	1.69	13.45	96	194	Idle	21.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.3	19.98	1.36	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:23:0	20.45	3539	1.72	13.46	96	194	Full Load	21.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.29	19.99	1.36	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:23:0	10.9	3522	1.76	13.45	96	194	Off Idle	21	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.23	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:23:1	10.9	3488	1.78	13.45	96	194	Off Idle	20.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.23	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:23:1	13.63	3435	1.8	13.46	96	194	Off Idle	20.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.15	20.07	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:23:1	16.36	3424	1.81	13.44	96	194	Off Idle	22.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.1	20.06	1.37	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:23:1	19.09	3348	1.83	13.43	96	194	Off Idle	23.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	20.06	1.37	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:23:1	21.81	3277	1.84	13.43	96	194	Off Idle	24.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	20.06	1.37	3.8	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:23:1	24.54	3200	1.86	13.44	96	194	Off Idle	26.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	20.07	1.37	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:1	24.54	3180	1.87	13.44	96	194	Off Idle	27.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.06	1.37	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:2	27.27	3100	1.88	13.45	96	194	Off Idle	28.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.7	20.05	1.37	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:2	29.99	3080	1.89	13.44	96	194	Off Idle	30.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	20.05	1.37	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:2	32.72	3032	1.9	13.44	96	194	Off Idle	31.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.67	20.04	1.37	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:2	35.45	3067	1.9	13.45	96	194	Off Idle	34.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.21	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:23:2	36.81	3050	1.9	13.45	96	194	Off Idle	36.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.78	20.21	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:23:2	36.81	3058	1.9	13.44	96	194	Off Idle	37.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.83	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:3	36.81	3104	1.9	13.45	96	194	Off Idle	38.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.84	20.2	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:3	36.81	3128	1.9	13.45	96	194	Off Idle	40.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.9	20.2	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:23:3	36.81	3170	1.9	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.86	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:3	36.81	3178	1.9	13.47	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.9	20.22	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:3	36.81	3226	1.9	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.92	20.22	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:3	36.81	3208	1.9	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.91	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:4	36.81	3208	1.9	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.94	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:4	36.81	3203	1.9	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:4	38.18	3207	1.89	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:4	38.18	3189	1.89	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.04	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:4	38.18	3189	1.88	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.06	20.2	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:4	38.18	3181	1.88	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.05	20.07	1.37	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:4	38.18	3173	1.88	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.08	19.87	1.35	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:5	38.18	3172	1.87	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.09	19.63	1.34	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:5	38.18	3160	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.14	19.19	1.31	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:5	38.18	3151	1.85	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.16	18.87	1.29	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:5	38.18	3145	1.85	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.14	18.7	1.27	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:5	38.18	3116	1.86	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.21	18.19	1.24	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:5	36.81	3116	1.86	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.2	17.83	1.21	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:6	36.81	3113	1.86	13.47	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.17	17.5	1.19	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:6	36.81	3112	1.86	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.19	17.14	1.17	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:6	36.81	3110	1.86	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.13	16.98	1.16	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:6	36.81	3107	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.13	16.91	1.15	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:6	36.81	3112	1.86	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.16	16.78	1.14	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:6	36.81	3112	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.21	16.68	1.14	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:6	36.81	3127	1.86	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.2	16.63	1.13	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:7	36.81	3139	1.86	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.2	16.58	1.13	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:7	36.81	3139	1.86	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.19	16.54	1.13	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:7	36.81	3154	1.86	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.16	16.47	1.12	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:7	36.81	3161	1.86	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.21	16.42	1.12	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:7	36.81	3161	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.22	16.39	1.12	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:7	36.81	3162	1.86	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.26	16.32	1.11	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:8	38.18	3184	1.86	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.26	16.28	1.11	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:8	38.18	3154	1.86	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-9.28	16.24	1.11	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:8	38.18	3154	1.86	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-9.25	16.19	1.1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:8	38.18	3154	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.27	16.16	1.1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:8	38.18	3155	1.86	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.27	16.11	1.1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:8	38.18	3156	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.26	16.06	1.09	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:9	38.18	3153	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.29	16.01	1.09	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:9	38.18	3146	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.31	15.92	1.08	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:23:9	38.18	3141	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.29	15.85	1.08	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:23:9	38.18	3130	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.29	15.78	1.08	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:9	36.81	3143	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.31	15.74	1.07	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:9	36.81	3137	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.27	15.67	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:23:9	36.81	3138	1.86	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.25	15.62	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:0	36.81	3144	1.86	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-9.26	15.55	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:0	36.81	3129	1.86	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-9.25	15.49	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:0	36.81	3130	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.26	15.44	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:0	36.81	3130	1.86	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.29	15.41	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:0	36.81	3105	1.86	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.31	15.38	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:0	36.81	3105	1.86	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.31	15.35	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:1	38.18	3142	1.86	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.7	-9.33	15.33	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:1	38.18	3134	1.85	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.35	15.29	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:1	38.18	3131	1.85	13.4	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.39	15.29	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:24:1	38.18	3131	1.84	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-9.45	15.26	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:24:1	38.18	3134	1.84	13.41	96	194	Full Load	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.52	15.25	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:24:1	38.18	3133	1.83	13.41	96	194	Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.56	15.24	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:24:1	38.18	3128	1.82	13.43	96	194	Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.61	15.21	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:24:2	38.18	3126	1.81	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.66	15.18	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:24:2	38.18	3126	1.8	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.71	15.16	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:24:2	38.18	3124	1.8	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.75	15.15	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:24:2	35.45	3098	1.79	13.45	96	194	Idle	39.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.76	15.13	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:24:2	29.99	3068	1.78	13.45	96	194	Idle	37	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.77	15.11	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:24:2	24.54	3054	1.78	13.46	96	194	Idle	32.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.74	15.09	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:24:3	24.54	3052	1.78	13.44	96	194	Idle	30.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.71	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:24:3	20.45	3079	1.79	13.45	96	194	Idle	28	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.64	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:24:3	20.45	3084	1.79	13.44	96	194	Idle	28	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.56	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:3	20.45	3064	1.8	13.43	96	194	Idle	23.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.47	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:24:3	19.09	3080	1.8	13.41	96	194	Idle	23.5	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.45	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:24:3	19.09	3109	1.8	13.43	96	194	Idle	23.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.45	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:4	19.09	3123	1.8	13.42	96	194	Idle	23.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.39	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:4	19.09	3124	1.8	13.44	96	194	Idle	23.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.43	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:4	19.09	3134	1.8	13.44	96	194	Idle	23.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.45	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:4	19.09	3133	1.79	13.45	96	194	Idle	23.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.51	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:4	19.09	3130	1.79	13.44	96	194	Idle	23.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.58	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:4	19.09	3120	1.79	13.46	96	194	Idle	25.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.63	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:4	19.09	3129	1.79	13.46	96	194	Idle	28	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.66	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:5	20.45	3074	1.79	13.45	96	194	Idle	30.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.69	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:5	19.09	3082	1.79	13.46	96	194	Idle	32.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.66	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:5	19.09	3075	1.79	13.45	96	194	Idle	34.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.69	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:5	19.09	3080	1.79	13.47	96	194	Idle	37	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.69	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:5	19.09	3080	1.79	13.46	96	194	Idle	39.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.71	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:5	19.09	3086	1.79	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.71	15.16	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:6	19.09	3088	1.78	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.7	15.25	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:6	19.09	3090	1.76	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.66	15.35	1.05	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:6	19.09	3098	1.75	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	15.49	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:6	19.09	3104	1.74	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.64	15.55	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:6	19.09	3080	1.73	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.63	15.61	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:6	19.09	3094	1.72	13.47	96	194	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.65	15.66	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:6	19.09	3106	1.72	13.47	96	194	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.63	15.73	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:7	19.09	3123	1.71	13.47	96	194	Idle	41.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.65	15.77	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:7	19.09	3110	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	15.94	1.09	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:7	19.09	3094	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	16.4	1.12	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:7	19.09	3087	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	16.82	1.15	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:7	19.09	3080	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	17.27	1.18	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:7	19.09	3078	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	17.71	1.21	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:8	19.09	3072	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	18.15	1.24	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:8	19.09	3068	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	18.6	1.27	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:8	19.09	3067	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	19.04	1.3	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:24:8	19.09	3065	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	19.66	1.34	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:8	19.09	3063	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	19.82	1.35	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:8	19.09	3052	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.15	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:9	19.09	3064	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.19	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:9	19.09	3066	1.71	13.43	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:9	19.09	3067	1.71	13.44	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:9	19.09	3068	1.71	13.44	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:9	19.09	3080	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:9	19.09	3071	1.71	13.46	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:24:9	19.09	3059	1.71	13.46	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:0	19.09	3066	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:0	19.09	3066	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:0	19.09	3066	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:0	19.09	3063	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:0	19.09	3049	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:0	19.09	3056	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:1	19.09	3055	1.71	13.47	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:1	19.09	3052	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:1	19.09	3049	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:1	19.09	3060	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:1	19.09	3048	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:1	19.09	3046	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:1	19.09	3046	1.71	13.46	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:2	19.09	3046	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:2	19.09	3033	1.71	13.46	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:2	19.09	3043	1.71	13.44	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:2	19.09	3043	1.71	13.46	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:2	19.09	3041	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:2	19.09	3038	1.71	13.46	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:3	19.09	3037	1.71	13.46	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:3	19.09	3035	1.71	13.47	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:3	19.09	3030	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:3	19.09	3025	1.71	13.47	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:3	19.09	3025	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:3	19.09	3024	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:4	19.09	3022	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:4	19.09	3022	1.71	13.47	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:4	19.09	3022	1.71	13.47	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:4	19.09	3024	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:4	19.09	3025	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:4	19.09	3026	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:4	19.09	3029	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:5	19.09	3028	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:5	19.09	3028	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:5	19.09	3026	1.71	13.47	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:5	19.09	3019	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.26	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:5	19.09	3018	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.26	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:5	19.09	3013	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.26	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:6	19.09	3008	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:6	19.09	3005	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:6	19.09	3004	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:6	19.09	3003	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:6	19.09	3008	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:6	19.09	3008	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:6	19.09	3007	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:7	19.09	3007	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:7	19.09	3008	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:7	19.09	3006	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:25:7	19.09	3001	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:7	19.09	3000	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:7	19.09	2998	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:8	19.09	2992	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:8	19.09	2992	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:8	19.09	2979	1.71	13.43	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:8	19.09	2989	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:8	19.09	3014	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:8	19.09	2989	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:9	19.09	2989	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:9	19.09	2994	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:9	19.09	2996	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:9	19.09	2995	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:9	19.09	2994	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:9	19.09	2991	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:25:9	19.09	2984	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:0	19.09	2984	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:0	19.09	2978	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:0	19.09	2971	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:0	19.09	2941	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:0	19.09	2950	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:0	19.09	2958	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:1	19.09	2954	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:1	19.09	2951	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:1	19.09	2952	1.71	13.44	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:1	19.09	2954	1.71	13.44	96	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:1	19.09	2956	1.71	13.44	96	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:1	19.09	2958	1.71	13.45	96	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:1	19.09	2986	1.71	13.45	96	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.2	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:2	19.09	2975	1.71	13.45	96	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.21	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:2	19.09	2954	1.71	13.43	96	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:2	19.09	2965	1.71	13.45	96	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.2	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:2	19.09	2964	1.71	13.45	96	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.2	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:2	19.09	2976	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.19	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:2	19.09	2959	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.2	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:3	19.09	2942	1.71	13.44	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.19	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:3	19.09	2949	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.2	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:3	19.09	2949	1.71	13.45	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.2	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:3	19.09	2944	1.71	13.43	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:3	19.09	2941	1.71	13.44	96	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:3	19.09	2938	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:4	19.09	2938	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:4	19.09	2937	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:4	19.09	2936	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:4	19.09	2936	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:4	19.09	2924	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:4	19.09	2934	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:4	19.09	2956	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:5	19.09	2956	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:5	19.09	2935	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:5	19.09	2935	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:5	19.09	2933	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:5	19.09	2933	1.71	13.43	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:5	19.09	2930	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:6	19.09	2930	1.71	13.43	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:6	19.09	2903	1.71	13.44	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.57	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:6	19.09	2917	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:6	19.09	2925	1.71	13.46	96	194	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:26:6	19.09	2908	1.71	13.47	96	194	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:6	19.09	2902	1.71	13.47	96	194	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.21	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:6	19.09	2899	1.71	13.46	96	194	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:7	19.09	2898	1.71	13.45	96	194	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:7	19.09	2890	1.71	13.45	96	194	Idle	42	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:7	19.09	2904	1.71	13.45	96	194	Idle	42	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:7	19.09	2905	1.71	13.45	96	194	Idle	42	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:7	19.09	2924	1.71	13.45	96	194	Idle	42.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:7	19.09	2921	1.71	13.45	96	194	Idle	42.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:8	19.09	2922	1.71	13.44	96	194	Idle	42.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:8	19.09	2927	1.7	13.44	96	194	Idle	42.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:8	19.09	2927	1.7	13.44	96	194	Idle	42.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:8	19.09	2921	1.7	13.45	96	194	Idle	42.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:8	19.09	2918	1.7	13.45	96	194	Idle	42.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:8	19.09	2908	1.7	13.44	96	194	Idle	42.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:9	19.09	2885	1.7	13.44	96	194	Idle	42.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:9	19.09	2885	1.7	13.44	96	194	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:9	19.09	2883	1.7	13.43	96	194	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:9	19.09	2872	1.7	13.44	96	194	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:9	19.09	2868	1.7	13.44	96	194	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:9	19.09	2869	1.7	13.44	96	194	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:26:9	19.09	2869	1.7	13.44	96	194	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:0	19.09	2868	1.7	13.45	96	194	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:0	19.09	2873	1.7	13.44	96	194	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:0	19.09	2874	1.7	13.43	96	194	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:0	19.09	2877	1.7	13.43	96	194	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:0	19.09	2878	1.7	13.44	96	194	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:0	19.09	2880	1.7	13.43	96	194	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:1	19.09	2879	1.7	13.44	96	194	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:1	19.09	2878	1.7	13.45	96	194	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:1	19.09	2873	1.7	13.44	96	194	Idle	42.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:1	19.09	2873	1.7	13.45	96	194	Idle	42.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:1	19.09	2868	1.7	13.45	96	194	Idle	43	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:1	19.09	2840	1.7	13.45	96	194	Idle	43.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:1	19.09	2850	1.7	13.45	96	194	Idle	43.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:2	19.09	2861	1.69	13.46	96	194	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:2	19.09	2856	1.69	13.45	96	194	Idle	43.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:2	19.09	2858	1.69	13.45	96	194	Idle	44.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:2	19.09	2858	1.69	13.45	96	194	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:2	19.09	2881	1.69	13.45	96	194	Idle	44.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:2	19.09	2858	1.69	13.46	96	194	Idle	44.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.14	1.37	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:3	19.09	2858	1.68	13.45	96	194	Idle	45	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.13	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:3	19.09	2858	1.68	13.43	96	194	Idle	45.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.14	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:3	19.09	2860	1.68	13.4	96	194	Idle	45.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.14	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:3	19.09	2858	1.68	13.38	96	194	Idle	45.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.14	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:3	19.09	2855	1.68	13.37	96	194	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.14	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:3	19.09	2852	1.68	13.38	96	194	Idle	45.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.14	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:4	19.09	2850	1.67	13.39	96	194	Idle	45.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.13	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:4	19.09	2844	1.67	13.39	96	194	Idle	45.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.13	1.37	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:4	19.09	2838	1.67	13.4	96	194	Idle	45.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:4	19.09	2841	1.67	13.4	96	194	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:4	19.09	2839	1.66	13.4	96	194	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:4	19.09	2833	1.66	13.4	96	194	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:4	19.09	2828	1.66	13.4	96	194	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:5	19.09	2824	1.66	13.4	96	194	Idle	45.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:5	19.09	2823	1.66	13.41	96	194	Idle	45.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:5	19.09	2817	1.66	13.41	96	194	Idle	45.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:5	19.09	2813	1.66	13.41	96	194	Idle	45.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:27:5	19.09	2812	1.66	13.41	96	194	Idle	46	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:5	19.09	2806	1.65	13.4	96	194	Idle	46.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:6	19.09	2801	1.65	13.41	96	194	Idle	46.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:6	19.09	2801	1.65	13.41	96	194	Idle	46.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:6	19.09	2796	1.65	13.41	96	194	Idle	46	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:6	19.09	2790	1.65	13.41	96	194	Idle	46	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:6	19.09	2785	1.65	13.41	96	194	Idle	46	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:6	19.09	2784	1.64	13.41	96	194	Idle	46.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:6	19.09	2775	1.64	13.42	96	194	Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:7	19.09	2772	1.64	13.41	96	194	Idle	46.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:7	19.09	2772	1.64	13.42	96	194	Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:7	19.09	2768	1.64	13.41	96	194	Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:7	19.09	2762	1.64	13.41	96	194	Idle	46.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:7	19.09	2758	1.64	13.4	96	194	Idle	46.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:7	19.09	2758	1.64	13.41	96	194	Idle	46.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:8	19.09	2755	1.64	13.4	96	194	Idle	46.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:8	19.09	2749	1.63	13.41	96	194	Idle	46.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:8	19.09	2736	1.63	13.41	96	194	Idle	47.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:8	19.09	2738	1.63	13.41	96	194	Idle	47.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:8	19.09	2733	1.63	13.41	96	194	Idle	47.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:8	19.09	2726	1.63	13.41	96	194	Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:9	19.09	2724	1.62	13.41	96	194	Idle	48.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:9	19.09	2718	1.62	13.4	96	194	Idle	48.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:9	19.09	2713	1.62	13.42	96	194	Idle	48.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:9	19.09	2708	1.62	13.42	96	194	Idle	49	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:9	19.09	2716	1.61	13.41	96	194	Idle	49.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:9	19.09	2716	1.61	13.41	96	194	Idle	49.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:27:9	19.09	2702	1.61	13.41	96	194	Idle	49.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:0	19.09	2701	1.6	13.4	96	194	Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:0	19.09	2698	1.6	13.4	96	194	Idle	50.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:0	19.09	2698	1.59	13.41	96	195	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:0	19.09	2696	1.59	13.4	96	195	Idle	51	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.26	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:0	19.09	2691	1.59	13.4	96	195	Idle	51.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.27	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:0	19.09	2685	1.58	13.41	96	194	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.26	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:1	19.09	2685	1.58	13.4	96	194	Idle	51.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.9	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:1	19.09	2678	1.57	13.4	96	194	Idle	51.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:1	19.09	2674	1.57	13.41	96	194	Idle	51.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:1	19.09	2674	1.57	13.41	96	194	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.26	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:1	19.09	2668	1.56	13.4	96	194	Idle	52.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:1	19.09	2665	1.56	13.4	96	194	Idle	52.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:1	19.09	2662	1.55	13.41	96	194	Idle	52.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:2	19.09	2662	1.55	13.41	96	194	Idle	53.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:2	19.09	2658	1.54	13.4	96	195	Idle	53.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:2	19.09	2653	1.54	13.41	96	195	Idle	53.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:2	19.09	2653	1.53	13.41	96	195	Idle	54	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:2	19.09	2650	1.53	13.41	96	195	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:2	19.09	2644	1.52	13.4	96	195	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:3	19.09	2644	1.52	13.41	96	195	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:3	19.09	2620	1.51	13.41	96	194	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:3	19.09	2636	1.51	13.41	96	194	Idle	55	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:3	19.09	2632	1.51	13.41	96	195	Idle	55.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:3	19.09	2630	1.5	13.42	96	195	Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:3	19.09	2628	1.5	13.41	96	195	Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:4	19.09	2628	1.5	13.4	96	195	Idle	55.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:4	19.09	2625	1.49	13.41	96	195	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:4	19.09	2621	1.49	13.4	96	195	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:4	19.09	2620	1.49	13.4	96	195	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:4	19.09	2620	1.48	13.39	96	195	Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:28:4	19.09	2614	1.48	13.39	96	195	Idle	56.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:4	19.09	2608	1.47	13.39	96	195	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:5	19.09	2608	1.47	13.4	96	195	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:5	19.09	2603	1.47	13.41	96	195	Idle	57.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:5	19.09	2598	1.47	13.4	96	195	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:5	19.09	2594	1.46	13.41	96	195	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:5	19.09	2592	1.46	13.41	96	195	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:5	19.09	2584	1.46	13.41	96	195	Idle	58.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:6	19.09	2579	1.45	13.42	96	195	Idle	58.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:6	19.09	2576	1.45	13.41	96	195	Idle	58.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:6	19.09	2570	1.44	13.42	96	195	Idle	58.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:6	19.09	2565	1.44	13.41	96	195	Idle	58.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.26	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:6	19.09	2561	1.44	13.4	96	194	Idle	58.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.26	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:6	19.09	2559	1.43	13.41	96	194	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.26	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:6	19.09	2555	1.43	13.41	96	194	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.25	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:7	19.09	2549	1.43	13.4	96	194	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:7	19.09	2549	1.42	13.4	96	194	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:7	19.09	2545	1.42	13.4	96	194	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:7	19.09	2540	1.42	13.41	96	194	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:7	19.09	2538	1.42	13.4	96	194	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:7	19.09	2536	1.42	13.41	96	195	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:8	19.09	2534	1.41	13.42	96	195	Idle	59.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:8	19.09	2530	1.41	13.42	96	195	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:8	19.09	2526	1.41	13.41	96	195	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:8	19.09	2506	1.41	13.41	96	195	Idle	59.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:8	19.09	2514	1.41	13.41	96	195	Idle	59.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:8	19.09	2520	1.4	13.4	96	195	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:9	19.09	2516	1.4	13.4	96	194	Idle	60.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:9	19.09	2515	1.4	13.39	96	194	Idle	60.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:9	19.09	2515	1.4	13.41	96	194	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:9	19.09	2516	1.4	13.4	96	195	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:9	19.09	2516	1.39	13.4	96	195	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:9	19.09	2514	1.39	13.42	96	195	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:28:9	19.09	2514	1.39	13.43	96	195	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:0	19.09	2512	1.39	13.43	96	195	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:0	19.09	2512	1.38	13.43	96	195	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:0	19.09	2511	1.38	13.43	96	194	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:0	19.09	2509	1.38	13.43	96	194	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:0	19.09	2508	1.37	13.44	96	194	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:0	19.09	2502	1.37	13.45	96	195	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:1	19.09	2499	1.36	13.45	96	195	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:1	19.09	2498	1.36	13.44	96	195	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:1	19.09	2495	1.36	13.44	96	195	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:1	19.09	2492	1.35	13.44	96	195	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:1	19.09	2490	1.35	13.44	96	195	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:1	19.09	2490	1.34	13.44	96	195	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:1	19.09	2490	1.34	13.44	96	195	Idle	64.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:2	19.09	2490	1.34	13.46	96	195	Idle	64.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:2	19.09	2490	1.33	13.45	96	195	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:2	19.09	2490	1.33	13.45	96	195	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:2	19.09	2488	1.33	13.45	96	195	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:2	19.09	2487	1.33	13.45	96	195	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:2	19.09	2487	1.32	13.44	96	195	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:3	19.09	2486	1.32	13.44	96	195	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:3	19.09	2472	1.32	13.43	96	195	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:3	19.09	2472	1.31	13.45	96	195	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:3	19.09	2478	1.31	13.44	96	195	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:3	19.09	2484	1.31	13.45	96	195	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:29:3	19.09	2471	1.31	13.44	96	195	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:4	19.09	2471	1.3	13.45	96	195	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:4	19.09	2469	1.3	13.44	96	195	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:4	19.09	2465	1.3	13.44	96	195	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:4	19.09	2446	1.3	13.44	96	195	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:4	19.09	2455	1.3	13.43	96	195	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:4	19.09	2474	1.3	13.43	96	195	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:4	19.09	2463	1.3	13.43	96	195	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:5	19.09	2462	1.29	13.44	96	195	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:5	19.09	2462	1.29	13.43	96	195	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:5	19.09	2461	1.29	13.43	96	195	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:5	19.09	2458	1.29	13.44	96	195	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:5	19.09	2457	1.28	13.44	96	194	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:5	19.09	2451	1.28	13.44	96	194	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:6	19.09	2451	1.28	13.44	96	195	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:6	19.09	2448	1.28	13.45	96	195	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:6	19.09	2444	1.28	13.45	96	195	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:6	19.09	2442	1.28	13.44	96	195	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:6	19.09	2442	1.28	13.46	96	195	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:6	19.09	2441	1.27	13.45	96	195	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:6	19.09	2442	1.27	13.44	96	195	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:7	19.09	2442	1.27	13.45	96	195	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:7	19.09	2443	1.26	13.46	96	195	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.43	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:7	19.09	2443	1.26	13.44	96	195	Off Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:7	19.09	2443	1.26	13.45	96	195	Off Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:29:7	19.09	2320	1.26	13.45	96	195	Off Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:29:7	10.9	2459	1.26	13.45	96	195	Off Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.45	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:29:8	10.9	2459	1.27	13.43	96	195	Off Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.24	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:29:8	13.63	2455	1.27	13.43	96	195	Off Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:29:8	16.36	2452	1.27	13.43	96	195	Off Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:29:8	16.36	2452	1.27	13.44	96	195	Off Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:29:8	19.09	2448	1.28	13.43	96	195	Off Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.25	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:29:8	21.81	2447	1.28	13.43	96	195	Off Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:29:9	21.81	2446	1.29	13.44	96	195	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:29:9	24.54	2448	1.29	13.43	96	195	Off Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:29:9	27.27	2448	1.29	13.45	96	195	Off Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:29:9	27.27	2448	1.3	13.44	96	195	Off Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.27	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:29:9	29.99	2448	1.31	13.45	96	195	Off Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:29:9	32.72	2455	1.31	13.44	96	195	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:29:9	32.72	2458	1.32	13.45	96	195	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:0	35.45	2461	1.33	13.43	96	195	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:0	35.45	2446	1.33	13.44	96	195	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.27	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:0	35.45	2438	1.34	13.43	96	195	Off Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:0	35.45	2444	1.35	13.42	96	195	Off Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.32	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:0	35.45	2430	1.36	13.43	96	195	Off Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:0	35.45	2428	1.36	13.41	96	195	Off Idle	69.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:1	35.45	2419	1.36	13.43	96	195	Off Idle	69.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	20.25	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:1	35.45	2419	1.37	13.44	96	195	Off Idle	69.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	20.25	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:1	35.45	2404	1.37	13.44	96	195	Off Idle	69.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:1	35.45	2403	1.37	13.44	96	195	Off Idle	70.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.37	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:1	35.45	2402	1.37	13.44	96	195	Off Idle	70.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:1	35.45	2399	1.37	13.43	96	195	Off Idle	70.4	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.38	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:1	35.45	2399	1.37	13.43	96	195	Off Idle	70.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:2	35.45	2399	1.37	13.43	96	195	Off Idle	70.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:2	35.45	2404	1.37	13.44	96	195	Off Idle	70.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:2	35.45	2398	1.37	13.43	96	195	Off Idle	71	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.41	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:2	35.45	2418	1.37	13.43	96	195	Off Idle	71	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.4	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:2	35.45	2421	1.37	13.45	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:30:2	35.45	2424	1.37	13.45	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.43	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:3	35.45	2442	1.36	13.45	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.46	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:3	35.45	2434	1.36	13.46	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:3	35.45	2432	1.36	13.47	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:3	35.45	2425	1.36	13.46	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:3	35.45	2417	1.36	13.47	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:3	35.45	2417	1.36	13.47	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:4	35.45	2403	1.36	13.48	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:4	35.45	2384	1.36	13.46	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.06	Lean	1	14.7	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:4	35.45	2381	1.36	13.46	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:30:4	35.45	2380	1.36	13.44	96	195	Off Idle	71.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:30:4	35.45	2379	1.36	13.44	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:30:4	35.45	2382	1.36	13.45	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:4	35.45	2391	1.36	13.44	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.44	20.18	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:5	35.45	2394	1.35	13.46	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.43	20.11	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:5	35.45	2395	1.35	13.46	96	195	Off Idle	71.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.41	19.95	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:5	35.45	2396	1.35	13.46	96	195	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.42	19.81	1.35	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:5	35.45	2399	1.35	13.45	96	195	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.44	19.64	1.34	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:5	35.45	2400	1.35	13.46	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.44	19.44	1.32	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:5	35.45	2400	1.35	13.42	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.48	19.21	1.31	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:6	35.45	2418	1.34	13.42	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.48	18.96	1.29	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:6	35.45	2407	1.34	13.42	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.48	18.58	1.27	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:6	35.45	2392	1.34	13.43	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.47	18.33	1.25	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:6	35.45	2395	1.34	13.45	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.45	18.12	1.23	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:6	35.45	2385	1.34	13.45	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.43	17.92	1.22	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:6	35.45	2390	1.34	13.45	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.43	17.72	1.21	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:6	35.45	2386	1.34	13.44	96	195	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.44	17.54	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:7	35.45	2386	1.33	13.44	96	195	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.43	17.39	1.18	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:7	35.45	2384	1.33	13.42	96	195	Off Idle	72	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.44	17.26	1.18	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:7	35.45	2383	1.33	13.42	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.44	17.15	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:7	35.45	2382	1.33	13.43	96	195	Off Idle	72.2	0	2	132	944 Turbo	0.08	Lean	1	14.7	-10.47	17.05	1.16	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:7	35.45	2386	1.33	13.43	96	195	Off Idle	72.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.47	16.95	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:30:7	35.45	2391	1.33	13.43	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.48	16.87	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:30:8	35.45	2391	1.33	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	16.79	1.14	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:8	35.45	2394	1.33	13.43	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.07	Lean	1	14.7	-10.5	16.67	1.14	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:8	35.45	2394	1.33	13.44	96	195	Off Idle	72.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.52	16.64	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:8	35.45	2397	1.33	13.43	96	195	Off Idle	72.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.51	16.58	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:8	35.45	2398	1.33	13.43	96	195	Off Idle	72.9	0	2	132	944 Turbo	0.07	Lean	1	14.7	-10.53	16.52	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:8	35.45	2400	1.33	13.44	96	195	Off Idle	72.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.52	16.42	1.12	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:9	35.45	2402	1.33	13.44	96	195	Off Idle	72.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.5	16.35	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:9	35.45	2418	1.33	13.45	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	16.28	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:9	35.45	2418	1.33	13.44	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.5	16.2	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:30:9	35.45	2398	1.33	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-10.46	16.13	1.1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:9	35.45	2391	1.33	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.46	16.08	1.1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:9	35.45	2388	1.33	13.43	96	195	Off Idle	72.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.44	16.03	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:30:9	35.45	2370	1.33	13.43	96	195	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.41	15.97	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:31:0	35.45	2374	1.33	13.43	96	195	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.41	15.94	1.09	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:31:0	35.45	2366	1.33	13.43	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.45	15.87	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:31:0	35.45	2366	1.32	13.44	96	195	Full Load	71.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.48	15.85	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:31:0	35.45	2368	1.31	13.44	96	195	Idle	71.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.52	15.82	1.08	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:31:0	35.45	2373	1.29	13.45	96	195	Idle	72.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.58	15.8	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:0	35.45	2374	1.28	13.44	96	195	Idle	72.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.65	15.8	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:1	35.45	2376	1.27	13.44	96	195	Idle	72.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.69	15.79	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:1	32.72	2340	1.26	13.44	96	195	Idle	72.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.71	15.79	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:1	27.27	2334	1.25	13.44	96	195	Idle	72.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.75	15.77	1.07	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:1	27.27	2334	1.24	13.44	96	195	Idle	72.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.78	15.75	1.07	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:1	21.81	2322	1.23	13.44	96	195	Idle	72	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.77	15.75	1.07	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:1	21.81	2315	1.22	13.44	96	195	Idle	71.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.78	15.74	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:31:1	17.72	2340	1.22	13.44	96	195	Idle	71.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.78	15.74	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:2	17.72	2338	1.21	13.44	96	195	Idle	71.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.79	15.73	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:2	17.72	2337	1.2	13.44	96	195	Idle	71	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.76	15.7	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:2	17.72	2326	1.2	13.46	96	195	Idle	70.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-10.75	15.66	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:2	17.72	2326	1.19	13.45	96	195	Idle	70.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-10.71	15.63	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:2	17.72	2356	1.19	13.46	96	195	Idle	69.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-10.68	15.6	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:2	17.72	2381	1.18	13.45	96	195	Idle	69	0	2	132	944 Turbo	0.48	Lean	1	14.6	-10.64	15.57	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:3	17.72	2374	1.17	13.44	96	195	Idle	69	0	2	132	944 Turbo	0.57	Lean	1	14.6	-10.61	15.53	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:3	17.72	2376	1.17	13.44	96	195	Idle	69.1	0	2	132	944 Turbo	0.6	Lean	1	14.6	-10.58	15.5	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:3	17.72	2379	1.18	13.45	96	195	Idle	69.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-10.58	15.45	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:3	17.72	2378	1.18	13.45	96	195	Idle	69.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-10.56	15.41	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:3	17.72	2377	1.18	13.45	96	195	Idle	69.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-10.56	15.38	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:3	17.72	2366	1.19	13.45	96	195	Idle	69.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-10.57	15.36	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:4	17.72	2359	1.19	13.45	96	195	Idle	70.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-10.54	15.35	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:4	17.72	2356	1.19	13.45	96	195	Idle	70.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.56	15.33	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:4	17.72	2346	1.19	13.44	96	195	Idle	71.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.57	15.32	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:4	17.72	2338	1.19	13.45	96	195	Idle	71.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.56	15.31	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:4	17.72	2330	1.19	13.45	96	195	Idle	72	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.55	15.3	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:4	17.72	2334	1.18	13.44	96	195	Idle	72.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.56	15.29	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:4	17.72	2335	1.18	13.44	96	195	Idle	72.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.55	15.28	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:5	17.72	2335	1.18	13.44	96	195	Idle	73.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.56	15.28	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:5	17.72	2339	1.17	13.43	96	195	Idle	72.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.57	15.27	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:5	17.72	2360	1.17	13.43	96	195	Idle	72.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.56	15.25	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:5	17.72	2349	1.17	13.44	96	195	Idle	73.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.57	15.21	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:5	17.72	2349	1.16	13.43	96	195	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	15.2	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:5	17.72	2351	1.16	13.43	96	195	Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	15.17	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:6	17.72	2349	1.15	13.43	96	195	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	15.15	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:6	17.72	2350	1.15	13.43	96	195	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	15.15	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:6	17.72	2344	1.14	13.43	96	195	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	15.17	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:6	17.72	2338	1.13	13.43	96	195	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	15.27	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:6	17.72	2336	1.13	13.44	96	195	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	15.41	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:6	17.72	2334	1.13	13.45	96	195	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	15.64	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:6	17.72	2328	1.13	13.44	96	195	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	15.98	1.09	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:7	17.72	2307	1.13	13.44	96	195	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	16.41	1.12	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:7	17.72	2323	1.12	13.45	96	195	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	17.16	1.17	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:7	17.72	2323	1.12	13.44	96	195	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	17.67	1.2	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:7	17.72	2319	1.12	13.45	96	195	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	18.16	1.24	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:7	17.72	2319	1.12	13.45	96	195	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	18.64	1.27	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:7	17.72	2320	1.12	13.44	96	195	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	19.09	1.3	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:8	17.72	2320	1.12	13.43	96	195	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	19.49	1.33	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:8	17.72	2321	1.12	13.45	96	195	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	19.82	1.35	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:8	17.72	2320	1.12	13.43	96	195	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.04	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:8	17.72	2322	1.12	13.43	96	195	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.16	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:8	17.72	2321	1.12	13.44	96	195	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:8	17.72	2321	1.12	13.45	96	195	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:9	17.72	2319	1.12	13.43	96	195	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:9	17.72	2318	1.11	13.42	96	195	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:9	17.72	2318	1.11	13.44	96	195	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:9	17.72	2316	1.11	13.42	96	195	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:9	17.72	2316	1.11	13.42	96	195	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:9	17.72	2316	1.11	13.44	96	195	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:31:9	17.72	2315	1.1	13.43	96	195	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:0	17.72	2312	1.1	13.42	96	195	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:0	17.72	2312	1.1	13.43	96	195	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:0	17.72	2311	1.1	13.44	96	195	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:0	17.72	2310	1.1	13.41	96	195	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:0	17.72	2310	1.1	13.42	96	195	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:0	17.72	2310	1.1	13.44	96	195	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:32:1	17.72	2308	1.09	13.43	96	195	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:1	17.72	2304	1.09	13.43	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:1	17.72	2301	1.09	13.44	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:1	17.72	2302	1.08	13.43	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:1	17.72	2299	1.08	13.44	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:1	17.72	2295	1.08	13.45	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:1	17.72	2295	1.08	13.44	96	195	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:2	17.72	2293	1.08	13.42	96	195	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:2	17.72	2290	1.07	13.44	96	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:2	17.72	2289	1.07	13.44	96	195	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:2	17.72	2289	1.07	13.43	96	195	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:2	17.72	2287	1.07	13.44	96	195	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:2	17.72	2286	1.07	13.44	96	195	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:3	17.72	2286	1.07	13.43	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:3	17.72	2286	1.07	13.45	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:3	17.72	2285	1.07	13.43	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:3	17.72	2285	1.07	13.44	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:3	17.72	2284	1.07	13.45	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:3	17.72	2283	1.06	13.45	96	195	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:4	17.72	2282	1.06	13.45	96	195	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:4	17.72	2282	1.06	13.45	96	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:4	17.72	2280	1.06	13.45	96	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:4	17.72	2279	1.06	13.43	96	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:4	17.72	2279	1.06	13.43	96	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:4	17.72	2279	1.06	13.44	96	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:4	17.72	2278	1.06	13.44	96	195	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:5	17.72	2278	1.06	13.43	96	195	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:5	17.72	2278	1.06	13.44	96	195	Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:5	17.72	2276	1.06	13.44	96	195	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:5	17.72	2275	1.06	13.44	96	195	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:5	17.72	2275	1.06	13.45	96	195	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:5	17.72	2272	1.06	13.44	96	195	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:6	17.72	2270	1.06	13.45	96	195	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:6	17.72	2264	1.06	13.45	96	195	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:6	17.72	2264	1.05	13.44	96	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:6	17.72	2263	1.05	13.43	96	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:6	17.72	2258	1.05	13.42	96	195	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:6	17.72	2257	1.05	13.42	96	195	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:6	17.72	2256	1.05	13.43	96	195	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:7	17.72	2256	1.05	13.44	96	195	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:7	17.72	2255	1.05	13.45	96	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:7	17.72	2237	1.05	13.45	96	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:7	17.72	2237	1.05	13.46	96	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:7	17.72	2266	1.05	13.45	96	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:7	17.72	2255	1.05	13.45	96	195	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:8	17.72	2255	1.05	13.44	96	195	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:8	17.72	2248	1.04	13.42	96	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:8	17.72	2255	1.04	13.42	96	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:8	17.72	2255	1.04	13.43	96	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:8	17.72	2251	1.04	13.41	96	195	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:8	17.72	2250	1.04	13.41	96	195	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:9	17.72	2247	1.04	13.43	96	195	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:9	17.72	2247	1.04	13.44	96	195	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:9	17.72	2253	1.04	13.44	96	195	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:9	17.72	2242	1.04	13.45	96	195	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:9	17.72	2223	1.04	13.45	96	195	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:9	17.72	2223	1.04	13.44	96	195	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:32:9	17.72	2240	1.03	13.44	96	195	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:33:0	17.72	2241	1.03	13.43	96	195	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:0	17.72	2240	1.03	13.43	96	195	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:0	17.72	2240	1.03	13.44	96	195	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:0	17.72	2240	1.03	13.42	96	195	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:0	17.72	2240	1.03	13.42	96	195	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:0	17.72	2239	1.03	13.43	96	195	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:1	17.72	2235	1.03	13.44	96	195	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:1	17.72	2232	1.03	13.44	96	195	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:1	17.72	2232	1.03	13.44	96	195	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:1	17.72	2228	1.03	13.42	96	195	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:1	17.72	2225	1.03	13.42	96	195	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:1	17.72	2223	1.02	13.42	96	195	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:1	17.72	2222	1.02	13.44	96	195	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:2	17.72	2220	1.02	13.44	96	195	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.73	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:2	17.72	2219	1.02	13.45	96	195	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:2	17.72	2219	1.02	13.45	96	195	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:2	17.72	2217	1.02	13.44	96	195	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:2	17.72	2216	1.02	13.43	96	195	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:2	17.72	2216	1.02	13.43	96	195	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:3	17.72	2208	1.02	13.45	96	195	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:3	17.72	2215	1.02	13.43	96	195	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:3	17.72	2215	1.02	13.44	96	195	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:3	17.72	2224	1.02	13.44	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:3	17.72	2212	1.01	13.44	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:3	17.72	2212	1.01	13.45	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:4	17.72	2212	1.01	13.44	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:4	17.72	2211	1.01	13.43	96	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:4	17.72	2212	1.01	13.44	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:4	17.72	2210	1.01	13.43	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:4	17.72	2237	1.01	13.42	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:4	17.72	2215	1	13.45	96	195	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:4	17.72	2214	1	13.44	96	195	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:5	17.72	2211	1	13.43	96	195	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:5	17.72	2193	1	13.42	96	195	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:5	17.72	2193	1	13.44	96	195	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:5	17.72	2206	1	13.43	96	195	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:5	17.72	2200	1	13.44	96	195	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:5	17.72	2212	1	13.44	96	195	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:6	17.72	2212	0.99	13.44	96	195	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:6	17.72	2184	0.99	13.43	96	195	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:6	17.72	2188	0.99	13.43	96	195	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:6	17.72	2185	0.99	13.43	96	195	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:6	17.72	2185	0.99	13.44	96	195	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:6	17.72	2185	0.99	13.45	96	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:6	17.72	2186	0.99	13.45	96	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:7	17.72	2186	0.99	13.45	96	195	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:7	17.72	2186	0.99	13.45	96	195	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:7	17.72	2185	0.98	13.44	96	195	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:7	17.72	2185	0.98	13.43	96	195	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:7	17.72	2184	0.98	13.44	96	195	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:7	17.72	2183	0.98	13.44	96	195	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:8	17.72	2183	0.98	13.43	96	195	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:8	17.72	2184	0.98	13.43	96	195	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:8	17.72	2185	0.98	13.43	96	195	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:8	17.72	2185	0.98	13.44	96	195	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:8	17.72	2183	0.97	13.44	96	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:8	17.72	2184	0.97	13.43	96	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.8	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:9	17.72	2181	0.97	13.43	96	195	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:33:9	17.72	2181	0.97	13.44	96	195	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:9	17.72	2180	0.97	13.43	96	195	Idle	82.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:9	17.72	2179	0.97	13.43	96	195	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:9	17.72	2178	0.97	13.44	96	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:9	17.72	2178	0.97	13.44	96	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:33:9	17.72	2176	0.97	13.44	96	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:0	17.72	2176	0.97	13.43	96	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:0	17.72	2173	0.97	13.43	96	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:0	17.72	2168	0.97	13.43	96	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:0	17.72	2168	0.97	13.44	96	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:0	17.72	2164	0.97	13.44	96	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:0	17.72	2160	0.97	13.45	96	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:1	17.72	2158	0.97	13.46	96	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:1	17.72	2152	0.97	13.46	96	195	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:1	17.72	2145	0.97	13.46	96	195	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:1	17.72	2139	0.97	13.46	96	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:1	17.72	2134	0.97	13.46	96	195	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.75	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:1	17.72	2124	0.97	13.46	96	195	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:1	17.72	2126	0.97	13.47	96	195	Idle	83.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.78	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:2	17.72	2141	0.97	13.46	96	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.77	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:2	17.72	2141	0.96	13.44	96	195	Idle	83.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.8	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:2	17.72	2122	0.96	13.44	96	195	Idle	83.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.79	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:2	17.72	2122	0.96	13.42	96	195	Idle	83.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.76	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:2	17.72	2122	0.96	13.41	96	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:2	17.72	2108	0.96	13.41	96	195	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:3	17.72	2122	0.96	13.42	96	195	Idle	83	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:3	17.72	2128	0.96	13.42	96	195	Idle	83.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:3	17.72	2149	0.96	13.44	96	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:3	17.72	2134	0.96	13.44	96	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:3	17.72	2134	0.96	13.43	96	195	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:3	17.72	2136	0.96	13.42	96	195	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:4	17.72	2120	0.96	13.42	96	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:4	17.72	2120	0.96	13.42	96	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:4	17.72	2144	0.96	13.43	96	195	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:4	17.72	2134	0.96	13.43	96	195	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:4	17.72	2115	0.96	13.44	96	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:4	17.72	2115	0.96	13.44	96	195	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:4	17.72	2130	0.96	13.43	96	195	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.78	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:5	17.72	2128	0.96	13.42	96	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:5	17.72	2128	0.96	13.43	96	195	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:5	17.72	2138	0.96	13.43	96	195	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:5	17.72	2128	0.96	13.44	96	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:5	17.72	2129	0.96	13.46	96	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:5	17.72	2130	0.95	13.46	96	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:6	17.72	2124	0.95	13.46	96	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:6	17.72	2130	0.95	13.46	96	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.76	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:6	17.72	2130	0.95	13.44	96	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:6	17.72	2138	0.95	13.44	96	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:6	17.72	2125	0.95	13.42	96	195	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.75	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:6	17.72	2121	0.95	13.42	96	195	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:6	17.72	2120	0.95	13.42	96	195	Full Load	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:7	17.72	2106	0.95	13.43	96	195	Full Load	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:7	17.72	2110	0.95	13.43	96	195	Off Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:7	8.18	2110	0.96	13.44	96	195	Off Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.23	1.38	3.6	1.2	ON	28 Pin	OFF	Removed	Disabled
03:26:34:7	8.18	2064	0.97	13.42	96	195	Off Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:26:34:7	10.9	2125	0.98	13.41	96	195	Off Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.24	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:26:34:7	10.9	2123	0.99	13.41	96	195	Off Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:34:8	13.63	2124	1.01	13.41	96	195	Off Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.46	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:34:8	13.63	2122	1.02	13.42	96	195	Off Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:8	16.36	2123	1.04	13.44	96	195	Off Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.33	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:34:8	19.09	2122	1.05	13.45	96	195	Off Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.28	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:34:8	19.09	2122	1.07	13.44	96	195	Off Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:34:8	21.81	2124	1.09	13.45	96	195	Off Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:34:9	21.81	2124	1.11	13.45	96	195	Off Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:34:9	24.54	2124	1.14	13.43	96	195	Off Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:34:9	24.54	2128	1.16	13.43	96	195	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:34:9	27.27	2128	1.18	13.44	96	195	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:34:9	27.27	2137	1.21	13.45	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:34:9	29.99	2152	1.25	13.44	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.66	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:34:9	32.72	2152	1.27	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.66	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:0	32.72	2164	1.3	13.44	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.63	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:0	34.08	2144	1.32	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:35:0	34.08	2162	1.35	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.52	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:35:0	34.08	2150	1.36	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:35:0	34.08	2140	1.38	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.41	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:35:0	34.08	2139	1.4	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.37	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:35:1	34.08	2139	1.41	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.36	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:35:1	34.08	2137	1.44	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.32	20.24	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:35:1	34.08	2138	1.45	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.24	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:35:1	34.08	2138	1.47	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.15	20.24	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:35:1	34.08	2139	1.49	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.04	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:35:1	34.08	2154	1.51	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.92	20.25	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:35:1	34.08	2144	1.54	13.44	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.7	-8.8	20.14	1.37	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:35:2	34.08	2123	1.55	13.44	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.71	20.14	1.37	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:35:2	34.08	2112	1.58	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.59	20.14	1.37	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:35:2	32.72	2112	1.6	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.52	20.14	1.37	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:2	32.72	2085	1.61	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.41	20.14	1.37	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:2	32.72	2093	1.63	13.4	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.31	20.15	1.37	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:2	32.72	2093	1.65	13.4	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.2	20.15	1.37	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:3	32.72	2094	1.66	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.08	20.14	1.37	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:35:3	32.72	2095	1.68	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.7	-7.97	20.14	1.37	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:35:3	32.72	2099	1.7	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.7	-7.89	20.24	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:35:3	32.72	2099	1.72	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.7	-7.81	20.21	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:35:3	32.72	2108	1.74	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.75	20.12	1.37	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:35:3	32.72	2114	1.76	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-7.6	19.95	1.36	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:35:4	32.72	2114	1.77	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-7.58	19.71	1.34	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:35:4	32.72	2118	1.79	13.44	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-7.49	19.44	1.32	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:35:4	32.72	2124	1.81	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-7.35	18.98	1.29	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:35:4	32.72	2124	1.83	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.27	18.65	1.27	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:35:4	32.72	2123	1.84	13.44	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-7.18	18.29	1.25	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:4	32.72	2124	1.85	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.09	17.92	1.22	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:4	32.72	2124	1.86	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-7.02	17.53	1.19	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:5	32.72	2124	1.87	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-6.93	17.18	1.17	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:5	32.72	2127	1.88	13.44	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-6.86	16.88	1.15	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:5	32.72	2128	1.89	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.85	16.64	1.13	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:5	32.72	2128	1.9	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-6.84	16.33	1.11	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:5	32.72	2128	1.91	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.2	Lean	1	14.7	-6.8	16.15	1.1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:5	32.72	2126	1.92	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.25	Lean	1	14.7	-6.77	16.01	1.09	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:6	32.72	2125	1.92	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-6.74	15.87	1.08	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:6	32.72	2125	1.93	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-6.67	15.75	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:6	32.72	2124	1.94	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.41	Lean	1	14.7	-6.6	15.63	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:35:6	32.72	2125	1.95	13.4	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.5	Lean	1	14.7	-6.49	15.5	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:35:6	32.72	2125	1.96	13.39	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.56	Lean	1	14.7	-6.42	15.43	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:35:6	32.72	2127	1.98	13.39	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.61	Lean	1	14.7	-6.26	15.37	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:35:6	31.36	2120	1.99	13.39	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-6.14	15.32	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:35:7	31.36	2133	2	13.39	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-5.95	15.29	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:35:7	31.36	2128	2.01	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-5.82	15.24	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:7	31.36	2127	2.01	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-5.77	15.2	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:7	31.36	2138	2.03	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-5.71	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:7	31.36	2128	2.03	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-5.66	15.17	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:7	31.36	2130	2.04	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.58	Rich	1	14.7	-5.64	15.15	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:35:8	31.36	2132	2.05	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.53	Rich	1	14.7	-5.61	15.13	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:35:8	31.36	2136	2.06	13.4	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.47	Rich	1	14.7	-5.57	15.08	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:35:8	31.36	2140	2.07	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.42	Rich	1	14.7	-5.46	15.04	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:35:8	31.36	2140	2.08	13.4	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.41	Rich	1	14.7	-5.41	15	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:35:8	31.36	2139	2.08	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.41	Rich	1	14.7	-5.37	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:35:8	31.36	2139	2.09	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.4	Rich	1	14.7	-5.37	14.93	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:9	31.36	2140	2.1	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.43	Rich	1	14.7	-5.38	14.91	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:9	31.36	2141	2.11	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.48	Rich	1	14.7	-5.37	14.9	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:9	31.36	2142	2.11	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-5.35	14.9	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:9	31.36	2137	2.11	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-5.32	14.91	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:9	31.36	2128	2.11	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-5.3	14.97	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:9	31.36	2138	2.11	13.44	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-5.3	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:35:9	31.36	2140	2.11	13.45	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	-5.35	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:36:0	31.36	2140	2.11	13.43	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-5.37	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:36:0	31.36	2148	2.11	13.42	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.32	15.01	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:36:0	31.36	2168	2.11	13.42	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:36:0	31.36	2150	2.11	13.43	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.88	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:36:0	31.36	2150	2.11	13.42	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.79	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:0	31.36	2149	2.11	13.42	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.31	14.7	1	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:1	31.36	2149	2.11	13.42	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.32	14.56	0.99	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:1	31.36	2151	2.11	13.42	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.31	14.41	0.98	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:1	31.36	2154	2.11	13.41	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.24	14.29	0.97	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:1	31.36	2154	2.11	13.42	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.23	14.19	0.97	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:1	31.36	2158	2.11	13.44	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.26	14.11	0.96	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:1	31.36	2165	2.11	13.44	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.31	14.03	0.96	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:1	31.36	2165	2.11	13.43	96	195	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.31	14	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:2	31.36	2168	2.11	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.33	13.93	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:2	31.36	2163	2.11	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-5.27	13.88	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:2	31.36	2154	2.11	13.42	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-5.26	13.86	0.94	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:2	31.36	2158	2.11	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-5.24	13.85	0.94	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:2	31.36	2156	2.11	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-5.22	13.85	0.94	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:2	31.36	2155	2.11	13.41	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.23	13.86	0.94	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:3	31.36	2157	2.11	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.29	13.87	0.94	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:3	31.36	2167	2.12	13.43	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.29	13.86	0.94	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:3	31.36	2170	2.12	13.45	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.29	13.85	0.94	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:3	31.36	2173	2.12	13.45	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.33	13.85	0.94	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:3	31.36	2174	2.12	13.44	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.34	13.85	0.94	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:3	31.36	2174	2.12	13.43	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.29	13.86	0.94	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:4	31.36	2174	2.12	13.43	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.28	13.86	0.94	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:4	31.36	2174	2.12	13.41	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	13.87	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:4	31.36	2174	2.12	13.41	96	195	Off Idle	85.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	13.89	0.95	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:4	31.36	2168	2.12	13.41	96	195	Off Idle	85.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.28	13.91	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:4	31.36	2166	2.12	13.41	96	195	Off Idle	84.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	13.92	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:4	31.36	2169	2.12	13.41	96	195	Off Idle	84.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.26	13.95	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:4	31.36	2172	2.12	13.43	96	195	Off Idle	84.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.22	13.97	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:5	31.36	2179	2.12	13.44	96	195	Off Idle	84.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.23	14	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:5	31.36	2182	2.12	13.45	96	195	Off Idle	84.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.27	14.02	0.95	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:5	31.36	2182	2.12	13.45	96	195	Off Idle	84.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.32	14.04	0.96	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:5	31.36	2184	2.12	13.43	96	195	Off Idle	84.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.32	14.05	0.96	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:5	31.36	2185	2.12	13.43	96	195	Off Idle	84.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.07	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:5	31.36	2185	2.12	13.43	96	195	Off Idle	84.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.09	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:6	31.36	2183	2.12	13.44	96	195	Off Idle	84.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.25	14.1	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:6	31.36	2182	2.12	13.45	96	195	Off Idle	84.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.11	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:36:6	31.36	2182	2.12	13.45	96	195	Off Idle	84.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.11	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:6	31.36	2179	2.12	13.43	96	195	Off Idle	84.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.3	14.1	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:6	31.36	2179	2.12	13.42	96	195	Off Idle	84.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.1	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:6	31.36	2182	2.12	13.42	96	195	Off Idle	84.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.12	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:6	31.36	2184	2.12	13.42	96	195	Off Idle	84.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.13	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:7	31.36	2192	2.13	13.44	96	195	Off Idle	84.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.29	14.14	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:7	31.36	2198	2.13	13.44	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.31	14.16	0.96	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:7	31.36	2198	2.13	13.43	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-5.32	14.17	0.97	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:7	31.36	2200	2.13	13.43	96	195	Off Idle	83.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.31	14.17	0.97	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:7	31.36	2200	2.13	13.44	96	195	Off Idle	83.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.24	14.19	0.97	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:7	31.36	2196	2.13	13.45	96	195	Off Idle	83.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.22	14.21	0.97	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:8	31.36	2196	2.13	13.45	96	195	Off Idle	83.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.22	14.23	0.97	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:8	31.36	2190	2.14	13.44	96	195	Off Idle	83.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.19	14.24	0.97	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:8	31.36	2192	2.14	13.41	96	195	Off Idle	83.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.17	14.26	0.97	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:36:8	31.36	2196	2.15	13.41	96	195	Off Idle	83.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.01	14.28	0.97	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:8	31.36	2196	2.16	13.41	96	195	Off Idle	83.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-4.95	14.3	0.97	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:36:8	31.36	2204	2.17	13.4	96	195	Off Idle	83.1	0	2	132	944 Turbo	0.78	Rich	1	14.7	-4.83	14.31	0.97	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:36:9	31.36	2208	2.18	13.41	96	195	Off Idle	82.9	0	2	132	944 Turbo	0.77	Rich	1	14.7	-4.76	14.34	0.98	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:36:9	31.36	2208	2.19	13.4	96	195	Off Idle	82.9	0	2	132	944 Turbo	0.77	Rich	1	14.7	-4.65	14.35	0.98	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:36:9	31.36	2208	2.2	13.42	96	195	Off Idle	82.8	0	2	132	944 Turbo	0.77	Rich	1	14.7	-4.55	14.4	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:36:9	31.36	2208	2.21	13.42	96	195	Off Idle	82.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-4.43	14.42	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:36:9	31.36	2209	2.22	13.45	96	195	Off Idle	82.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-4.33	14.43	0.98	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:36:9	31.36	2210	2.23	13.45	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.21	14.48	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:36:9	31.36	2218	2.24	13.46	96	195	Off Idle	82.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-4.19	14.52	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:37:0	31.36	2236	2.25	13.44	96	195	Off Idle	82.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-4.14	14.56	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:37:0	31.36	2236	2.26	13.43	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	-4.08	14.6	0.99	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:37:0	31.36	2214	2.28	13.42	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-3.95	14.64	1	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:37:0	31.36	2210	2.29	13.44	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.62	Rich	1	14.7	-3.92	14.66	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:0	31.36	2198	2.3	13.43	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	-3.88	14.7	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:0	31.36	2198	2.31	13.43	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-3.84	14.71	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:1	31.36	2210	2.31	13.42	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-3.81	14.73	1	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:1	31.36	2212	2.32	13.43	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	-3.8	14.77	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:1	31.36	2212	2.33	13.42	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.61	Rich	1	14.7	-3.78	14.8	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:1	31.36	2217	2.33	13.44	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-3.75	14.84	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:1	31.36	2224	2.34	13.43	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.65	Rich	1	14.7	-3.72	14.86	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:1	31.36	2228	2.34	13.43	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-3.7	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:1	31.36	2236	2.34	13.42	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-3.68	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:2	31.36	2237	2.34	13.42	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-3.67	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:2	31.36	2237	2.34	13.44	96	195	Off Idle	82.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-3.64	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:2	31.36	2237	2.34	13.43	96	195	Off Idle	82.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-3.66	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:2	31.36	2235	2.34	13.42	96	195	Off Idle	82.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-3.63	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:2	31.36	2234	2.34	13.44	96	195	Off Idle	82.1	0	2	132	944 Turbo	0.71	Rich	1	14.7	-3.66	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:2	31.36	2233	2.35	13.44	96	195	Off Idle	82	0	2	132	944 Turbo	0.72	Rich	1	14.7	-3.68	14.88	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:37:3	31.36	2234	2.35	13.42	96	195	Off Idle	81.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-3.67	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:37:3	31.36	2236	2.35	13.43	96	195	Off Idle	81.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-3.63	14.87	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:37:3	31.36	2242	2.35	13.43	96	195	Off Idle	81.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-3.62	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:3	31.36	2244	2.35	13.42	96	195	Off Idle	81.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-3.63	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:3	31.36	2254	2.35	13.41	96	195	Off Idle	81.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-3.62	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:37:3	31.36	2261	2.35	13.41	96	195	Off Idle	81.2	0	2	132	944 Turbo	0.62	Rich	1	14.7	-3.58	14.86	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:37:4	31.36	2262	2.35	13.42	96	195	Off Idle	81.2	0	2	132	944 Turbo	0.57	Rich	1	14.7	-3.6	14.85	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:37:4	31.36	2258	2.35	13.42	96	195	Off Idle	81.2	0	2	132	944 Turbo	0.51	Lean	1	14.7	-3.62	14.75	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:37:4	31.36	2262	2.35	13.42	96	195	Off Idle	81.2	0	2	132	944 Turbo	0.45	Lean	1	14.7	-3.64	14.76	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:37:4	31.36	2252	2.35	13.42	96	195	Off Idle	81.2	0	2	132	944 Turbo	0.39	Lean	1	14.7	-3.62	14.74	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:37:4	31.36	2252	2.36	13.44	96	194	Off Idle	81.2	0	2	132	944 Turbo	0.32	Lean	1	14.7	-3.61	14.73	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:37:4	31.36	2252	2.36	13.43	96	194	Off Idle	80.9	0	2	132	944 Turbo	0.27	Lean	1	14.7	-3.61	14.72	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:37:4	31.36	2252	2.36	13.43	96	194	Off Idle	80.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-3.52	14.73	1	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:37:5	31.36	2238	2.37	13.44	96	195	Off Idle	80.9	0	2	132	944 Turbo	0.15	Lean	1	14.7	-3.41	14.75	1	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:37:5	31.36	2258	2.37	13.44	96	195	Off Idle	80.9	0	2	132	944 Turbo	0.13	Lean	1	14.7	-3.32	14.77	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:37:5	31.36	2257	2.39	13.42	96	195	Off Idle	80.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-3.22	14.82	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:5	31.36	2257	2.39	13.42	96	195	Off Idle	80.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-3.17	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:5	31.36	2261	2.4	13.4	96	195	Off Idle	80.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-3.04	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:5	31.36	2276	2.41	13.42	96	195	Off Idle	80.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-2.99	15.02	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:6	31.36	2274	2.41	13.41	96	195	Off Idle	80.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-2.94	15.04	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:6	31.36	2274	2.42	13.4	96	195	Off Idle	80.7	0	2	132	944 Turbo	0.13	Lean	1	14.7	-2.84	15.06	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:6	31.36	2276	2.43	13.41	96	195	Off Idle	80.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-2.7	15.09	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:37:6	31.36	2280	2.44	13.42	96	195	Off Idle	80.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-2.68	15.09	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:6	31.36	2280	2.45	13.41	96	195	Off Idle	80.2	0	2	132	944 Turbo	0.29	Lean	1	14.7	-2.59	15.09	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:6	31.36	2277	2.46	13.42	96	195	Off Idle	80.1	0	2	132	944 Turbo	0.35	Lean	1	14.7	-2.55	15.09	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:6	31.36	2278	2.47	13.41	96	195	Off Idle	80.1	0	2	132	944 Turbo	0.41	Lean	1	14.7	-2.53	15.1	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:7	31.36	2280	2.47	13.4	96	195	Off Idle	80.1	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.45	15.13	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:7	31.36	2281	2.48	13.4	96	195	Off Idle	79.9	0	2	132	944 Turbo	0.51	Rich	1	14.7	-2.38	15.13	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:7	31.36	2284	2.49	13.43	96	195	Off Idle	79.6	0	2	132	944 Turbo	0.61	Rich	1	14.7	-2.37	15.11	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:7	31.36	2285	2.5	13.42	96	195	Off Idle	79.3	0	2	132	944 Turbo	0.64	Rich	1	14.7	-2.36	15.09	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:37:7	31.36	2284	2.51	13.41	96	195	Off Idle	79	0	2	132	944 Turbo	0.7	Rich	1	14.7	-2.33	15.07	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:7	31.36	2286	2.51	13.41	96	195	Off Idle	78.7	0	2	132	944 Turbo	0.73	Rich	1	14.7	-2.31	15.03	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:8	31.36	2290	2.52	13.42	96	195	Off Idle	78.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.29	14.99	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:8	31.36	2296	2.52	13.41	96	195	Off Idle	78.1	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.31	14.95	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:8	31.36	2296	2.52	13.41	96	195	Off Idle	78.1	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.27	14.9	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:8	31.36	2306	2.53	13.42	96	195	Off Idle	78.1	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.23	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:8	31.36	2312	2.53	13.43	96	195	Off Idle	78	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.26	14.74	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:8	31.36	2310	2.53	13.42	96	195	Off Idle	77.9	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.27	14.7	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:9	31.36	2310	2.53	13.41	96	195	Off Idle	77.7	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.26	14.69	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:9	31.36	2302	2.53	13.43	96	195	Off Idle	77.6	0	2	132	944 Turbo	0.74	Rich	1	14.7	-2.29	14.67	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:9	31.36	2302	2.54	13.42	96	195	Off Idle	77.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-2.31	14.67	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:9	31.36	2296	2.54	13.42	96	195	Off Idle	77.2	0	2	132	944 Turbo	0.73	Rich	1	14.7	-2.26	14.68	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:9	31.36	2300	2.54	13.42	96	195	Off Idle	77	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.24	14.69	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:9	31.36	2313	2.54	13.41	96	195	Off Idle	77	0	2	132	944 Turbo	0.7	Rich	1	14.7	-2.18	14.72	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:37:9	31.36	2314	2.54	13.42	96	195	Off Idle	77	0	2	132	944 Turbo	0.7	Rich	1	14.7	-2.17	14.72	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:0	31.36	2319	2.55	13.42	96	195	Off Idle	77	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.11	14.77	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:0	31.36	2319	2.55	13.43	96	195	Off Idle	77	0	2	132	944 Turbo	0.68	Rich	1	14.7	-2.13	14.8	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:0	31.36	2319	2.55	13.41	96	195	Off Idle	77	0	2	132	944 Turbo	0.67	Rich	1	14.7	-2.16	14.81	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:0	31.36	2316	2.55	13.42	96	195	Off Idle	76.9	0	2	132	944 Turbo	0.61	Rich	1	14.7	-2.17	14.83	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:0	31.36	2322	2.55	13.43	96	195	Off Idle	76.8	0	2	132	944 Turbo	0.56	Rich	1	14.7	-2.1	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:38:0	31.36	2322	2.55	13.43	96	195	Off Idle	76.8	0	2	132	944 Turbo	0.53	Rich	1	14.7	-2.16	14.85	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:38:1	31.36	2323	2.56	13.43	96	195	Off Idle	76.8	0	2	132	944 Turbo	0.45	Rich	1	14.7	-2.14	14.87	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:38:1	31.36	2326	2.56	13.43	96	195	Off Idle	76.8	0	2	132	944 Turbo	0.4	Rich	1	14.7	-2.13	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:38:1	31.36	2330	2.56	13.42	96	195	Off Idle	76.6	0	2	132	944 Turbo	0.35	Rich	1	14.7	-2.13	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:38:1	31.36	2341	2.56	13.42	96	195	Off Idle	76.5	0	2	132	944 Turbo	0.31	Rich	1	14.7	-2.14	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:38:1	31.36	2340	2.56	13.42	96	195	Off Idle	76.5	0	2	132	944 Turbo	0.29	Rich	1	14.7	-2.09	14.86	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:38:1	31.36	2342	2.56	13.43	96	195	Off Idle	76.3	0	2	132	944 Turbo	0.28	Rich	1	14.7	-2.16	14.89	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:38:1	31.36	2343	2.56	13.42	96	195	Off Idle	76.2	0	2	132	944 Turbo	0.32	Rich	1	14.7	-2.16	14.92	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:2	31.36	2342	2.56	13.43	96	195	Off Idle	76	0	2	132	944 Turbo	0.36	Rich	1	14.7	-2.15	14.93	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:2	31.36	2342	2.56	13.43	96	195	Off Idle	76	0	2	132	944 Turbo	0.41	Rich	1	14.7	-2.17	14.97	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:2	31.36	2341	2.56	13.41	96	195	Off Idle	76	0	2	132	944 Turbo	0.47	Rich	1	14.7	-2.16	15.01	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:2	31.36	2342	2.56	13.42	96	195	Off Idle	75.9	0	2	132	944 Turbo	0.53	Rich	1	14.7	-2.17	15.02	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:2	31.36	2340	2.56	13.41	96	195	Off Idle	75.7	0	2	132	944 Turbo	0.59	Rich	1	14.7	-2.15	15.04	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:2	31.36	2341	2.57	13.42	96	195	Off Idle	75.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	-2.12	15.04	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:3	31.36	2342	2.57	13.42	96	195	Off Idle	75.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-2.14	15.04	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:3	31.36	2349	2.57	13.41	96	195	Off Idle	75.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.1	15.02	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:3	31.36	2354	2.57	13.42	96	195	Off Idle	75	0	2	132	944 Turbo	0.72	Rich	1	14.7	-2.09	14.98	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:3	31.36	2354	2.57	13.42	96	195	Off Idle	74.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-2.15	14.96	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:3	31.36	2360	2.57	13.41	96	195	Off Idle	74.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.15	14.91	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:3	31.36	2363	2.57	13.41	96	195	Off Idle	74.9	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.16	14.85	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:4	31.36	2363	2.57	13.41	96	195	Off Idle	74.9	0	2	132	944 Turbo	0.66	Rich	1	14.7	-2.22	14.8	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:4	31.36	2364	2.56	13.41	96	195	Off Idle	74.7	0	2	132	944 Turbo	0.61	Rich	1	14.7	-2.28	14.8	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:4	31.36	2362	2.56	13.41	96	195	Off Idle	74.6	0	2	132	944 Turbo	0.56	Rich	1	14.7	-2.34	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:38:4	31.36	2359	2.55	13.42	96	195	Off Idle	74.4	0	2	132	944 Turbo	0.5	Rich	1	14.7	-2.43	14.78	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:4	31.36	2360	2.55	13.42	96	195	Off Idle	74	0	2	132	944 Turbo	0.44	Rich	1	14.6	-2.55	14.76	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:38:4	31.36	2364	2.54	13.43	96	195	Off Idle	73.9	0	2	132	944 Turbo	0.39	Rich	1	14.7	-2.64	14.77	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:38:4	31.36	2370	2.54	13.44	96	195	Off Idle	73.9	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.76	14.77	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:38:5	31.36	2370	2.53	13.44	96	195	Off Idle	73.9	0	2	132	944 Turbo	0.3	Lean	1	14.7	-2.85	14.78	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:38:5	31.36	2376	2.52	13.44	96	195	Off Idle	73.9	0	2	132	944 Turbo	0.31	Lean	1	14.7	-3.02	14.79	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:38:5	31.36	2376	2.51	13.44	96	195	Off Idle	73.9	0	2	132	944 Turbo	0.34	Lean	1	14.7	-3.09	14.84	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:38:5	31.36	2380	2.5	13.44	96	195	Off Idle	73.9	0	2	132	944 Turbo	0.37	Lean	1	14.7	-3.17	14.87	1.01	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:38:5	31.36	2380	2.5	13.45	96	195	Off Idle	73.9	0	2	132	944 Turbo	0.41	Lean	1	14.7	-3.24	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:38:5	31.36	2376	2.49	13.43	96	195	Off Idle	73.7	0	2	132	944 Turbo	0.46	Lean	1	14.7	-3.31	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:38:6	31.36	2370	2.48	13.43	96	195	Off Idle	73.6	0	2	132	944 Turbo	0.51	Lean	1	14.7	-3.34	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:38:6	31.36	2370	2.47	13.42	96	195	Off Idle	73.4	0	2	132	944 Turbo	0.56	Lean	1	14.7	-3.43	15.05	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:38:6	31.36	2370	2.46	13.43	96	195	Off Idle	73.3	0	2	132	944 Turbo	0.57	Lean	1	14.7	-3.54	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:38:6	31.36	2372	2.45	13.42	96	195	Off Idle	73.2	0	2	132	944 Turbo	0.56	Lean	1	14.7	-3.57	15.05	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:38:6	31.36	2377	2.43	13.42	96	195	Off Idle	73.2	0	2	132	944 Turbo	0.5	Lean	1	14.7	-3.67	15.05	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:38:6	31.36	2388	2.42	13.42	96	195	Off Idle	73.2	0	2	132	944 Turbo	0.45	Lean	1	14.7	-3.73	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:38:6	31.36	2394	2.41	13.42	96	195	Off Idle	73	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.82	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:38:7	31.36	2393	2.4	13.42	96	195	Off Idle	73	0	2	132	944 Turbo	0.32	Lean	1	14.7	-3.93	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:38:7	31.36	2393	2.39	13.42	96	195	Off Idle	73.1	0	2	132	944 Turbo	0.29	Lean	1	14.7	-4.04	14.94	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:38:7	31.36	2391	2.39	13.42	96	195	Off Idle	72.9	0	2	132	944 Turbo	0.26	Lean	1	14.7	-4.07	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:38:7	31.36	2390	2.37	13.43	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.27	14.9	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:38:7	31.36	2386	2.37	13.43	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.12	Lean	1	14.7	-4.32	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:38:7	31.36	2380	2.35	13.44	96	195	Off Idle	72.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.5	14.99	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:38:8	31.36	2379	2.34	13.44	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.59	15.06	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:8	31.36	2379	2.34	13.44	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.66	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:8	31.36	2380	2.32	13.44	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.72	15.21	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:8	31.36	2396	2.3	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.8	15.29	1.04	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:38:8	32.72	2390	2.3	13.42	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.91	15.39	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:8	32.72	2390	2.28	13.44	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.04	15.47	1.05	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:9	32.72	2391	2.27	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.17	15.56	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:38:9	32.72	2389	2.26	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.28	15.58	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:38:9	32.72	2391	2.25	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.37	15.6	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:38:9	32.72	2392	2.24	13.44	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.47	15.62	1.06	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:38:9	32.72	2400	2.23	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.54	15.64	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:38:9	32.72	2401	2.22	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.61	15.65	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:38:9	32.72	2401	2.2	13.43	96	195	Off Idle	72.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.67	15.67	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:39:0	32.72	2418	2.2	13.43	96	195	Off Idle	72.2	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.75	15.69	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:39:0	32.72	2401	2.19	13.42	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.8	15.7	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:39:0	32.72	2405	2.18	13.41	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.85	15.72	1.07	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:39:0	32.72	2407	2.17	13.42	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.91	15.74	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:39:0	32.72	2408	2.16	13.42	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-6	15.75	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:39:0	32.72	2407	2.15	13.42	96	195	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.7	-6.08	15.77	1.07	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:39:1	32.72	2407	2.14	13.42	96	195	Off Idle	71.8	0	2	132	944 Turbo	0.05	Lean	1	14.7	-6.19	15.78	1.08	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:39:1	32.72	2403	2.13	13.43	96	195	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.24	15.8	1.08	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:39:1	32.72	2403	2.12	13.43	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.38	15.83	1.08	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:39:1	32.72	2403	2.11	13.43	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.51	15.85	1.08	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:39:1	34.08	2406	2.09	13.43	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-6.62	15.85	1.08	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:1	34.08	2393	2.08	13.45	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.75	15.86	1.08	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:39:1	34.08	2393	2.05	13.44	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-6.95	15.86	1.08	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:39:2	34.08	2385	2.04	13.45	96	195	Off Idle	71.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-7.11	15.86	1.08	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:2	34.08	2394	2.02	13.45	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.2	15.86	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:2	34.08	2394	2.01	13.44	96	195	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.7	-7.34	15.85	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:2	34.08	2392	1.99	13.44	96	195	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.7	-7.52	15.81	1.08	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:2	34.08	2387	1.98	13.42	96	195	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.7	-7.6	15.77	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:2	34.08	2384	1.96	13.44	96	195	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.72	15.74	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:3	34.08	2384	1.94	13.42	96	195	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.84	15.71	1.07	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:39:3	34.08	2388	1.92	13.42	96	195	Off Idle	72	0	2	132	944 Turbo	0.07	Lean	1	14.7	-7.9	15.68	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:3	34.08	2395	1.9	13.43	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.07	Lean	1	14.7	-7.98	15.65	1.07	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:39:3	34.08	2398	1.87	13.42	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.11	15.59	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:3	34.08	2404	1.86	13.42	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.16	15.57	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:3	34.08	2405	1.84	13.43	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.22	15.54	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:4	34.08	2405	1.83	13.45	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.26	15.52	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:4	34.08	2408	1.81	13.44	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.34	15.49	1.06	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:4	34.08	2406	1.8	13.44	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.37	15.48	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:4	34.08	2403	1.79	13.42	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.44	15.46	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:4	34.08	2413	1.78	13.43	96	195	Off Idle	72.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.46	15.43	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:4	34.08	2405	1.78	13.43	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	15.41	1.05	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:4	34.08	2406	1.77	13.43	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.58	15.4	1.05	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:5	34.08	2404	1.75	13.43	96	195	Off Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.7	15.4	1.05	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:39:5	34.08	2404	1.74	13.43	96	195	Off Idle	71.8	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.78	15.41	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:39:5	34.08	2403	1.71	13.45	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.94	15.42	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:39:5	34.08	2402	1.69	13.44	96	195	Off Idle	71.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.11	15.43	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:39:5	34.08	2402	1.65	13.45	96	195	Full Load	71.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.26	15.43	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:39:5	34.08	2397	1.62	13.45	96	195	Idle	71.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.46	15.44	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:39:6	34.08	2383	1.57	13.44	96	195	Idle	71.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.65	15.45	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:6	34.08	2383	1.54	13.44	96	195	Idle	71.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.87	15.46	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:6	34.08	2365	1.51	13.44	96	195	Idle	71.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.01	15.48	1.05	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:39:6	34.08	2325	1.49	13.44	96	195	Idle	71.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.11	15.47	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:6	28.63	2302	1.46	13.44	96	195	Idle	71.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.22	15.47	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:6	23.18	2302	1.43	13.44	96	195	Idle	71.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.29	15.46	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:6	23.18	2271	1.38	13.45	96	195	Idle	72	0	2	132	944 Turbo	0.35	Lean	1	14.6	-10.33	15.46	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:7	17.72	2261	1.35	13.44	96	195	Idle	72.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.39	15.45	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:7	17.72	2277	1.34	13.44	96	195	Idle	72.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-10.4	15.45	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:7	17.72	2308	1.3	13.45	96	195	Idle	73.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-10.41	15.45	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:7	17.72	2343	1.27	13.44	96	195	Idle	73.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-10.43	15.46	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:7	17.72	2343	1.23	13.45	96	195	Idle	73.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.46	15.43	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:7	17.72	2417	1.2	13.46	96	195	Idle	73.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.48	15.43	1.05	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:8	17.72	2431	1.17	13.45	96	195	Idle	73.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.5	15.44	1.05	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:8	17.72	2431	1.15	13.45	96	195	Idle	73.6	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.51	15.44	1.05	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:8	17.72	2457	1.14	13.46	96	195	Idle	73.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.56	15.43	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:8	17.72	2438	1.13	13.45	96	195	Idle	73.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-10.58	15.42	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:8	17.72	2420	1.13	13.45	96	195	Idle	72.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.58	15.42	1.05	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:8	17.72	2412	1.13	13.45	96	195	Idle	72.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-10.58	15.41	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:9	17.72	2390	1.14	13.45	96	195	Idle	72.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-10.58	15.4	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:9	17.72	2355	1.14	13.45	96	195	Idle	72.2	0	2	132	944 Turbo	0.11	Rich	1	14.6	-10.54	15.38	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:9	17.72	2355	1.14	13.45	96	195	Idle	72	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.51	15.37	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:9	17.72	2324	1.14	13.44	96	195	Idle	71.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.5	15.34	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:9	17.72	2308	1.14	13.44	96	195	Idle	71.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.46	15.3	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:9	17.72	2312	1.14	13.44	96	195	Idle	70.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.45	15.28	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:39:9	17.72	2312	1.14	13.43	96	195	Idle	70	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.45	15.26	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:0	17.72	2320	1.15	13.43	96	195	Idle	69.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.43	15.23	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:0	17.72	2336	1.15	13.45	96	195	Idle	69.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.42	15.18	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:0	17.72	2367	1.16	13.44	96	195	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	15.09	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:0	17.72	2367	1.16	13.44	96	195	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	15.06	1.03	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:0	17.72	2401	1.17	13.44	96	195	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	14.99	1.02	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:0	17.72	2400	1.17	13.44	96	195	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	14.99	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:1	17.72	2396	1.18	13.43	96	195	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	15.07	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:1	17.72	2388	1.19	13.43	96	195	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	15.21	1.04	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:1	17.72	2376	1.19	13.43	96	195	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	15.51	1.06	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:1	17.72	2357	1.19	13.43	96	195	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	15.84	1.08	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:1	17.72	2357	1.19	13.43	96	195	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	16.3	1.11	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:1	17.72	2352	1.19	13.44	96	195	Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	16.83	1.15	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:1	17.72	2331	1.19	13.44	96	195	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	17.37	1.18	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:2	17.72	2329	1.19	13.44	96	195	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	17.92	1.22	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:2	17.72	2325	1.19	13.46	96	195	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	18.45	1.26	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:2	17.72	2310	1.19	13.44	96	195	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	18.92	1.29	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:40:2	17.72	2310	1.18	13.44	96	195	Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	19.34	1.32	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:2	17.72	2332	1.18	13.44	96	195	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	19.68	1.34	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:2	17.72	2358	1.18	13.43	96	195	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	19.96	1.36	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:3	17.72	2352	1.18	13.43	96	194	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:3	17.72	2352	1.18	13.44	96	194	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:3	17.72	2354	1.17	13.45	96	194	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:3	17.72	2352	1.17	13.45	96	195	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:3	17.72	2346	1.17	13.44	96	195	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:3	17.72	2343	1.16	13.43	96	195	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:4	17.72	2333	1.16	13.43	96	195	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:4	17.72	2305	1.16	13.43	96	195	Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:4	17.72	2305	1.15	13.44	96	195	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:4	17.72	2316	1.15	13.44	96	195	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:4	17.72	2313	1.15	13.45	96	195	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:4	17.72	2312	1.14	13.45	96	195	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:4	17.72	2312	1.14	13.44	96	195	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:5	17.72	2317	1.14	13.45	96	195	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:5	17.72	2319	1.14	13.44	96	195	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:5	17.72	2321	1.14	13.44	96	195	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:5	17.72	2328	1.14	13.45	96	195	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:5	17.72	2328	1.13	13.45	96	195	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:5	17.72	2330	1.13	13.45	96	195	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:6	17.72	2346	1.13	13.46	96	195	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:6	17.72	2330	1.13	13.44	96	195	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:6	17.72	2327	1.13	13.43	96	195	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:6	17.72	2311	1.13	13.44	96	195	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:6	17.72	2313	1.12	13.43	96	195	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:6	17.72	2327	1.12	13.43	96	195	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:6	17.72	2317	1.12	13.46	96	195	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:7	17.72	2294	1.12	13.44	96	195	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:7	17.72	2300	1.12	13.44	96	195	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:7	17.72	2300	1.12	13.44	96	195	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:7	17.72	2300	1.12	13.46	96	195	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:7	17.72	2301	1.12	13.45	96	195	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:7	17.72	2304	1.12	13.46	96	195	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:8	17.72	2304	1.12	13.46	96	195	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:8	17.72	2305	1.12	13.45	96	195	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:8	17.72	2305	1.12	13.45	96	195	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:8	17.72	2306	1.12	13.45	96	195	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:8	17.72	2304	1.12	13.46	96	195	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:8	17.72	2300	1.12	13.47	96	195	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:9	17.72	2308	1.11	13.47	96	195	Idle	75.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:9	17.72	2294	1.11	13.46	96	195	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:9	17.72	2282	1.11	13.43	96	195	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:9	17.72	2282	1.11	13.43	96	195	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:9	17.72	2284	1.11	13.43	96	195	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:9	17.72	2282	1.11	13.44	96	195	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:40:9	17.72	2280	1.11	13.43	96	195	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:0	17.72	2280	1.11	13.45	96	195	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:0	17.72	2283	1.11	13.45	96	195	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:0	17.72	2283	1.1	13.44	96	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:0	17.72	2285	1.1	13.45	96	195	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:0	17.72	2284	1.1	13.45	96	195	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:0	17.72	2284	1.1	13.43	96	195	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:1	17.72	2284	1.1	13.42	96	195	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:1	17.72	2281	1.09	13.43	96	195	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:1	17.72	2278	1.09	13.44	96	195	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:1	17.72	2278	1.09	13.44	96	195	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:41:1	17.72	2274	1.09	13.44	96	195	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:1	17.72	2273	1.09	13.45	96	195	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:1	17.72	2270	1.08	13.45	96	195	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:2	17.72	2270	1.08	13.45	96	195	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:2	17.72	2268	1.08	13.45	96	195	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:2	17.72	2267	1.07	13.44	96	194	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:2	17.72	2267	1.07	13.44	96	194	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:2	17.72	2267	1.07	13.44	96	194	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:2	17.72	2267	1.07	13.44	96	195	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:3	17.72	2267	1.06	13.45	96	195	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:3	17.72	2266	1.06	13.44	96	195	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:3	17.72	2267	1.06	13.43	96	195	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:3	17.72	2265	1.06	13.44	96	195	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:3	17.72	2264	1.06	13.45	96	195	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:3	17.72	2262	1.06	13.43	96	195	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:4	17.72	2260	1.06	13.43	96	195	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:4	17.72	2260	1.05	13.44	96	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:4	17.72	2257	1.05	13.44	96	195	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:4	17.72	2257	1.05	13.43	96	195	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:4	17.72	2257	1.05	13.43	96	195	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:4	17.72	2257	1.05	13.44	96	195	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:4	17.72	2254	1.05	13.44	96	195	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:5	17.72	2253	1.05	13.43	96	195	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:5	17.72	2252	1.05	13.44	96	195	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:5	17.72	2240	1.05	13.45	96	195	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:5	17.72	2263	1.05	13.43	96	195	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:5	17.72	2263	1.04	13.43	96	195	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:5	17.72	2242	1.04	13.44	96	195	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:6	17.72	2239	1.04	13.45	96	195	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:6	17.72	2219	1.04	13.43	96	195	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:6	17.72	2219	1.04	13.43	96	195	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:6	17.72	2234	1.04	13.44	96	195	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:6	17.72	2231	1.04	13.45	96	194	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:6	17.72	2231	1.04	13.44	96	194	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:6	17.72	2232	1.04	13.44	96	194	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:7	17.72	2234	1.04	13.44	96	195	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:7	17.72	2236	1.04	13.45	96	195	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:7	17.72	2236	1.04	13.44	96	195	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:7	17.72	2236	1.04	13.42	96	195	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:7	17.72	2237	1.03	13.43	96	195	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:7	17.72	2237	1.03	13.43	96	195	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:8	17.72	2236	1.03	13.43	96	195	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:8	17.72	2235	1.03	13.43	96	195	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:8	17.72	2233	1.03	13.43	96	195	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:8	17.72	2232	1.03	13.44	96	195	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:8	17.72	2228	1.03	13.44	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:8	17.72	2222	1.03	13.44	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:9	17.72	2222	1.03	13.44	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:9	17.72	2209	1.02	13.44	96	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:9	17.72	2211	1.02	13.44	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:9	17.72	2210	1.02	13.43	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:9	17.72	2207	1.02	13.43	96	195	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:9	17.72	2206	1.02	13.44	96	195	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:41:9	17.72	2205	1.02	13.42	96	195	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:0	17.72	2206	1.02	13.42	96	195	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:0	17.72	2209	1.02	13.43	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:0	17.72	2227	1.02	13.43	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:0	17.72	2227	1.02	13.43	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:42:0	17.72	2212	1.02	13.43	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:0	17.72	2197	1.01	13.44	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:1	17.72	2204	1.01	13.44	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:1	17.72	2226	1.01	13.43	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:1	17.72	2208	1.01	13.42	96	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:1	17.72	2206	1.01	13.44	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:1	17.72	2190	1.01	13.43	96	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:1	17.72	2193	1.01	13.42	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:1	17.72	2193	1.01	13.43	96	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:2	17.72	2187	1.01	13.42	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:2	17.72	2184	1.01	13.41	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:2	17.72	2184	1.01	13.41	96	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:2	17.72	2184	1.01	13.41	96	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:2	17.72	2185	1.01	13.42	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:2	17.72	2186	1.01	13.43	96	195	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:3	17.72	2186	1.01	13.45	96	195	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:3	17.72	2188	1.01	13.44	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:3	17.72	2189	1.01	13.45	96	195	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:3	17.72	2190	1.01	13.45	96	195	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:3	17.72	2190	1.01	13.44	96	195	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:3	17.72	2190	1.01	13.44	96	194	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:4	17.72	2190	1.01	13.46	96	194	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:4	17.72	2186	1.01	13.46	96	194	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:4	17.72	2184	1.01	13.47	96	195	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:4	17.72	2182	1.01	13.47	96	195	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:4	17.72	2178	1.01	13.46	96	195	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:4	17.72	2177	1.01	13.45	96	195	Idle	82.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:4	17.72	2177	1.01	13.44	96	195	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:5	17.72	2176	1.01	13.44	96	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:5	17.72	2174	1.01	13.44	96	195	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:5	17.72	2173	1.01	13.44	96	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:5	17.72	2173	1.01	13.44	96	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:5	17.72	2172	1	13.44	96	195	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:5	17.72	2172	1	13.44	96	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:6	17.72	2172	1	13.44	96	195	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:6	17.72	2168	1	13.44	96	195	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:6	17.72	2167	1	13.45	96	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:6	17.72	2166	1	13.45	96	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:6	17.72	2162	1	13.43	96	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:6	17.72	2155	1	13.44	96	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:6	17.72	2155	0.99	13.43	96	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.69	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:7	17.72	2152	0.99	13.43	96	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:7	17.72	2149	0.99	13.43	96	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:7	17.72	2149	0.99	13.44	96	194	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:7	17.72	2149	0.99	13.45	96	195	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.7	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:7	17.72	2150	0.99	13.45	96	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:7	17.72	2150	0.99	13.44	96	195	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:8	17.72	2152	0.99	13.43	96	195	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:8	17.72	2154	0.99	13.43	96	195	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:8	17.72	2155	0.98	13.44	96	195	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:8	17.72	2156	0.98	13.44	96	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:8	17.72	2154	0.98	13.44	96	195	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:8	17.72	2154	0.98	13.43	96	195	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:9	17.72	2152	0.98	13.42	96	195	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:9	17.72	2149	0.98	13.42	96	195	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:9	17.72	2148	0.98	13.43	96	195	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:9	17.72	2146	0.97	13.43	96	195	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.72	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:9	17.72	2144	0.97	13.42	96	195	Full Load	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:42:9	17.72	2143	0.97	13.43	96	195	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.25	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:42:9	17.72	2016	0.98	13.43	96	195	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.24	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:0	9.54	2153	0.98	13.43	96	195	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.25	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:0	12.27	2153	0.99	13.41	96	195	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.24	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:0	12.27	2151	1.01	13.41	96	195	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.24	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:0	14.99	2149	1.03	13.41	96	195	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:43:0	14.99	2147	1.05	13.41	96	195	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.28	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:43:0	17.72	2146	1.07	13.43	96	195	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:43:1	17.72	2145	1.09	13.44	96	195	Off Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:43:1	20.45	2144	1.12	13.44	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.01	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:43:1	23.18	2144	1.16	13.45	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:43:1	23.18	2142	1.19	13.44	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:43:1	25.9	2142	1.23	13.42	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.59	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:1	25.9	2146	1.27	13.41	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	20.22	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:1	28.63	2160	1.33	13.41	96	195	Off Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.06	20.22	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:2	28.63	2172	1.35	13.4	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.95	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:2	31.36	2178	1.42	13.39	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.71	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:2	31.36	2184	1.47	13.4	96	195	Off Idle	85.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.49	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:43:2	34.08	2179	1.52	13.41	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.28	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:43:2	34.08	2156	1.55	13.43	96	194	Off Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.16	20.24	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:43:2	32.72	2182	1.62	13.41	96	194	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.85	20.24	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:43:3	32.72	2186	1.67	13.41	96	195	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.61	20.24	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:43:3	32.72	2206	1.73	13.42	96	195	Off Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.31	20.24	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:3	32.72	2214	1.77	13.41	96	195	Off Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.1	20.24	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:3	32.72	2218	1.8	13.41	96	195	Off Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-6.91	20.24	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:3	32.72	2218	1.84	13.44	96	195	Off Idle	84.3	0	2	132	944 Turbo	0.03	Lean	1	14.7	-6.76	20.25	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:3	32.72	2195	1.88	13.46	96	195	Off Idle	84.2	0	2	132	944 Turbo	0.03	Lean	1	14.7	-6.67	20.24	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:4	32.72	2173	1.91	13.45	96	195	Off Idle	84	0	2	132	944 Turbo	0.03	Lean	1	14.7	-6.56	20.25	1.38	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:4	32.72	2162	1.95	13.44	96	195	Off Idle	83.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.41	20.25	1.38	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:4	32.72	2127	1.98	13.43	96	195	Off Idle	83.7	0	2	132	944 Turbo	0.04	Lean	1	14.7	-6.23	20.26	1.38	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:4	32.72	2108	2.01	13.42	96	195	Off Idle	83.7	0	2	132	944 Turbo	0.04	Lean	1	14.7	-6.04	20.25	1.38	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:4	32.72	2107	2.03	13.42	96	195	Off Idle	83.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.86	20.25	1.38	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:43:4	32.72	2107	2.05	13.42	96	195	Off Idle	83.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.7	20.24	1.38	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:4	31.36	2089	2.07	13.43	96	195	Off Idle	83.9	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.56	20.19	1.38	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:5	31.36	2134	2.09	13.44	96	195	Off Idle	84	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.45	20.04	1.37	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:43:5	31.36	2143	2.11	13.42	96	195	Off Idle	84	0	2	132	944 Turbo	0.08	Lean	1	14.7	-5.31	19.82	1.35	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:43:5	31.36	2168	2.13	13.41	96	195	Off Idle	84	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.07	19.38	1.32	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:43:5	31.36	2184	2.15	13.41	96	195	Off Idle	84.2	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.85	19.01	1.3	3.4	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:43:5	31.36	2208	2.17	13.42	96	195	Off Idle	84.2	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.64	18.61	1.27	3.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:43:5	31.36	2208	2.18	13.43	96	195	Off Idle	84.2	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.45	18.19	1.24	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:43:6	31.36	2185	2.21	13.45	96	195	Off Idle	84.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.28	17.75	1.21	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:43:6	31.36	2177	2.22	13.45	96	195	Off Idle	84.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.14	17.3	1.18	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:6	31.36	2172	2.23	13.44	96	195	Off Idle	84.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4.03	16.87	1.15	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:6	31.36	2159	2.25	13.43	96	195	Off Idle	84.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.86	16.36	1.11	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:6	31.36	2145	2.27	13.42	96	195	Off Idle	84.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.74	16.11	1.1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:6	31.36	2145	2.28	13.41	96	195	Off Idle	84.3	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.64	15.92	1.08	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:6	31.36	2154	2.29	13.44	96	195	Off Idle	84.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.55	15.79	1.08	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:7	29.99	2151	2.3	13.44	96	195	Off Idle	84.3	0	2	132	944 Turbo	0.15	Lean	1	14.7	-3.51	15.71	1.07	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:7	29.99	2162	2.32	13.43	96	195	Off Idle	84.3	0	2	132	944 Turbo	0.2	Lean	1	14.7	-3.47	15.67	1.07	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:7	29.99	2178	2.33	13.43	96	195	Off Idle	84.3	0	2	132	944 Turbo	0.27	Lean	1	14.7	-3.41	15.61	1.06	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:7	29.99	2185	2.35	13.43	96	195	Off Idle	84.1	0	2	132	944 Turbo	0.36	Lean	1	14.7	-3.32	15.58	1.06	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:7	29.99	2186	2.36	13.43	96	195	Off Idle	84	0	2	132	944 Turbo	0.44	Lean	1	14.7	-3.24	15.51	1.06	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:43:7	29.99	2198	2.37	13.42	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.47	Lean	1	14.7	-3.16	15.49	1.05	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:8	31.36	2192	2.38	13.42	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.58	Lean	1	14.7	-3.09	15.47	1.05	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:43:8	31.36	2191	2.39	13.44	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.61	Lean	1	14.7	-3.05	15.44	1.05	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:43:8	31.36	2192	2.4	13.42	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.71	Lean	1	14.7	-2.94	15.34	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:43:8	31.36	2191	2.41	13.41	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.89	15.23	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:43:8	31.36	2188	2.41	13.41	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.81	15.12	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:43:8	31.36	2188	2.42	13.39	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.7	15.01	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:43:9	31.36	2192	2.43	13.4	96	195	Off Idle	83.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.58	14.87	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:9	31.36	2199	2.44	13.41	96	195	Off Idle	83.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.33	14.68	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:26:43:9	31.36	2205	2.45	13.43	96	195	Off Idle	83.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.22	14.56	0.99	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:43:9	31.36	2205	2.46	13.43	96	195	Off Idle	83.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.11	14.48	0.99	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:43:9	31.36	2212	2.47	13.43	96	195	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.04	14.35	0.98	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:43:9	31.36	2213	2.48	13.43	96	195	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.96	14.25	0.97	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:43:9	31.36	2213	2.49	13.44	96	195	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.88	14.17	0.97	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:44:0	29.99	2197	2.5	13.44	96	195	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.83	14.11	0.96	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:0	29.99	2214	2.51	13.44	96	195	Off Idle	83	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.82	14.01	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:0	29.99	2214	2.52	13.43	96	195	Off Idle	83	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.79	13.98	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:0	29.99	2215	2.53	13.43	96	195	Off Idle	83.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.82	13.95	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:0	29.99	2237	2.53	13.43	96	195	Off Idle	83.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.8	13.93	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:0	31.36	2225	2.53	13.42	96	195	Off Idle	83	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.8	13.9	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:1	31.36	2226	2.54	13.41	96	195	Off Idle	83	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.76	13.86	0.94	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:44:1	31.36	2228	2.54	13.42	96	195	Off Idle	82.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.75	13.82	0.94	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:44:1	29.99	2212	2.55	13.43	96	195	Off Idle	82.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.76	13.78	0.94	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:44:1	29.99	2212	2.55	13.43	96	195	Off Idle	82.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.76	13.75	0.94	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:44:1	29.99	2225	2.56	13.41	96	195	Off Idle	82.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.7	13.72	0.93	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:1	29.99	2226	2.56	13.42	96	195	Off Idle	82.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.67	13.71	0.93	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:1	29.99	2226	2.56	13.42	96	195	Off Idle	82.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.64	13.68	0.93	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:2	29.99	2234	2.56	13.43	96	195	Off Idle	82.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.62	13.67	0.93	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:44:2	29.99	2240	2.56	13.44	96	195	Off Idle	82.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.59	13.64	0.93	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:44:2	29.99	2242	2.56	13.44	96	195	Off Idle	82.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.63	13.63	0.93	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:2	29.99	2243	2.56	13.44	96	195	Off Idle	82.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.62	13.63	0.93	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:44:2	29.99	2263	2.56	13.43	96	195	Off Idle	81.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.66	13.62	0.93	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:44:2	29.99	2250	2.56	13.44	96	195	Off Idle	81.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.61	13.62	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:3	29.99	2252	2.57	13.44	96	195	Off Idle	81.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.62	13.61	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:3	29.99	2254	2.57	13.43	96	195	Off Idle	81.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.58	13.62	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:3	29.99	2258	2.57	13.43	96	195	Off Idle	81.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.57	13.62	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:3	29.99	2260	2.57	13.43	96	195	Off Idle	81.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.49	13.64	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:3	29.99	2264	2.58	13.43	96	195	Off Idle	81.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.51	13.65	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:3	29.99	2268	2.58	13.42	96	195	Off Idle	81.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.49	13.66	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:4	29.99	2268	2.58	13.41	96	195	Off Idle	80.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.5	13.67	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:4	29.99	2265	2.59	13.43	96	195	Off Idle	80.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.44	13.69	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:4	29.99	2264	2.59	13.43	96	195	Off Idle	80.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.44	13.72	0.93	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:4	29.99	2264	2.59	13.42	96	195	Off Idle	80.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.43	13.73	0.94	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:4	29.99	2270	2.59	13.42	96	195	Off Idle	80	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.42	13.75	0.94	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:4	29.99	2272	2.6	13.44	96	195	Off Idle	79.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.37	13.78	0.94	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:4	29.99	2299	2.6	13.42	96	195	Off Idle	79.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.37	13.8	0.94	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:5	31.36	2292	2.6	13.41	96	195	Off Idle	79.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.32	13.82	0.94	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:5	31.36	2293	2.6	13.42	96	195	Off Idle	79.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.3	13.84	0.94	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:5	31.36	2296	2.61	13.43	96	195	Off Idle	79.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.33	13.87	0.94	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:5	31.36	2295	2.61	13.42	96	194	Off Idle	79.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.35	13.91	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:5	31.36	2292	2.61	13.42	96	194	Off Idle	79.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.33	13.94	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:5	31.36	2287	2.61	13.42	96	194	Off Idle	79.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.35	13.97	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:6	31.36	2287	2.61	13.43	96	195	Off Idle	78.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.35	13.98	0.95	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:6	31.36	2287	2.62	13.42	96	195	Off Idle	78.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.32	13.98	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:6	31.36	2292	2.62	13.41	96	195	Off Idle	78.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.25	13.98	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:6	31.36	2296	2.62	13.44	96	195	Off Idle	78.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.23	14	0.95	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:44:6	31.36	2298	2.63	13.43	96	195	Off Idle	78	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.17	14.02	0.96	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:44:6	31.36	2306	2.63	13.41	96	195	Off Idle	77.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.08	14.03	0.96	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:44:6	31.36	2316	2.64	13.43	96	195	Off Idle	77.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.02	14.03	0.96	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:44:7	31.36	2323	2.65	13.43	96	195	Off Idle	77.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.94	14.04	0.96	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:7	31.36	2324	2.65	13.4	96	195	Off Idle	77.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.86	14.04	0.96	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:44:7	31.36	2326	2.66	13.41	96	195	Off Idle	77.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.78	14.05	0.96	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:44:7	31.36	2316	2.66	13.41	96	195	Off Idle	77.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.75	14.08	0.96	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:44:7	31.36	2316	2.67	13.4	96	195	Off Idle	77	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.63	14.12	0.96	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:44:7	31.36	2322	2.68	13.41	96	195	Off Idle	76.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.6	14.15	0.96	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:44:8	31.36	2322	2.68	13.43	96	195	Off Idle	76.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-0.62	14.17	0.96	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:44:8	31.36	2325	2.68	13.43	96	195	Off Idle	76.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	-0.59	14.2	0.97	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:44:8	31.36	2329	2.69	13.44	96	195	Off Idle	76.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.54	14.24	0.97	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:44:8	31.36	2319	2.69	13.44	96	195	Off Idle	76.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.57	14.26	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:8	29.99	2338	2.7	13.44	96	195	Off Idle	76.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.48	14.28	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:8	29.99	2338	2.7	13.44	96	195	Off Idle	76.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.47	14.31	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:9	29.99	2345	2.71	13.44	96	195	Off Idle	76.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.49	14.32	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:9	29.99	2347	2.72	13.44	96	195	Off Idle	76.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.45	14.33	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:9	29.99	2366	2.72	13.43	96	195	Off Idle	76	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.46	14.34	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:9	31.36	2350	2.72	13.43	96	195	Off Idle	75.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.48	14.33	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:9	31.36	2354	2.73	13.42	96	195	Off Idle	75.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.43	14.29	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:9	31.36	2354	2.73	13.42	96	195	Off Idle	75.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.45	14.27	0.97	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:44:9	29.99	2344	2.73	13.43	96	195	Off Idle	75.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.46	14.22	0.97	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:0	29.99	2352	2.73	13.42	96	195	Off Idle	75.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-0.41	14.21	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:0	29.99	2353	2.73	13.42	96	195	Off Idle	75.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-0.38	14.18	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:0	29.99	2354	2.73	13.42	96	195	Off Idle	75.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.33	14.16	0.96	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:0	29.99	2356	2.73	13.43	96	195	Off Idle	75.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.35	14.15	0.96	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:0	29.99	2364	2.74	13.43	96	195	Off Idle	74.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.38	14.15	0.96	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:0	29.99	2373	2.74	13.43	96	195	Off Idle	74.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.39	14.16	0.96	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:1	29.99	2373	2.74	13.43	96	195	Off Idle	74.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-0.41	14.19	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:1	29.99	2381	2.74	13.43	96	195	Off Idle	74.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-0.37	14.25	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:1	29.99	2384	2.74	13.42	96	195	Off Idle	74.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-0.33	14.28	0.97	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:1	29.99	2380	2.75	13.43	96	195	Off Idle	74	0	2	132	944 Turbo	0.77	Rich	1	14.7	-0.34	14.33	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:1	29.99	2378	2.75	13.42	96	195	Off Idle	73.9	0	2	132	944 Turbo	0.77	Rich	1	14.7	-0.34	14.37	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:1	29.99	2374	2.75	13.42	96	195	Off Idle	73.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-0.3	14.41	0.98	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:1	29.99	2369	2.75	13.42	96	195	Off Idle	73.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.26	14.47	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:2	29.99	2369	2.75	13.43	96	195	Off Idle	73.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.23	14.52	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:2	29.99	2374	2.76	13.43	96	195	Off Idle	73.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.2	14.57	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:2	29.99	2381	2.76	13.43	96	195	Off Idle	73.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.18	14.6	0.99	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:2	29.99	2386	2.76	13.43	96	195	Off Idle	73.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.19	14.63	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:2	29.99	2401	2.76	13.43	96	195	Off Idle	73.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.2	14.68	1	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:2	29.99	2417	2.76	13.42	96	195	Off Idle	73.1	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.22	14.71	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:45:3	29.99	2424	2.77	13.43	96	195	Off Idle	72.9	0	2	132	944 Turbo	0.7	Rich	1	14.7	-0.23	14.74	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:45:3	29.99	2424	2.77	13.44	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-0.22	14.77	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:45:3	29.99	2421	2.77	13.44	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.2	14.8	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:45:3	29.99	2420	2.77	13.44	96	195	Off Idle	72	0	2	132	944 Turbo	0.68	Rich	1	14.7	-0.19	14.8	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:3	29.99	2420	2.78	13.43	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.65	Rich	1	14.7	-0.17	14.81	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:3	29.99	2416	2.78	13.43	96	195	Off Idle	71.9	0	2	132	944 Turbo	0.64	Rich	1	14.7	-0.15	14.83	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:4	29.99	2419	2.78	13.42	96	195	Off Idle	71.7	0	2	132	944 Turbo	0.59	Rich	1	14.7	-0.16	14.86	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:4	29.99	2420	2.78	13.41	96	195	Off Idle	71.6	0	2	132	944 Turbo	0.55	Rich	1	14.7	-0.13	14.86	1.01	3.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:4	29.99	2438	2.78	13.42	96	195	Off Idle	71.3	0	2	132	944 Turbo	0.51	Lean	1	14.7	-0.1	14.86	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:4	29.99	2428	2.78	13.42	96	195	Off Idle	71.1	0	2	132	944 Turbo	0.48	Lean	1	14.7	-0.14	14.87	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:4	29.99	2427	2.79	13.44	96	195	Off Idle	71	0	2	132	944 Turbo	0.4	Lean	1	14.7	-0.09	14.86	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:4	29.99	2427	2.79	13.42	96	195	Off Idle	71	0	2	132	944 Turbo	0.35	Lean	1	14.7	-0.08	14.86	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:45:4	29.99	2407	2.79	13.43	96	195	Off Idle	71	0	2	132	944 Turbo	0.3	Lean	1	14.7	-0.04	14.88	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:45:5	28.63	2428	2.79	13.42	96	195	Off Idle	71	0	2	132	944 Turbo	0.26	Lean	1	14.7	-0.01	14.91	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:5	28.63	2430	2.8	13.44	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.24	Lean	1	14.7	0	14.92	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:5	28.63	2458	2.8	13.43	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.24	Lean	1	14.7	0.01	14.94	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:5	28.63	2443	2.8	13.43	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.27	Lean	1	14.7	0.04	14.97	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:45:5	29.99	2444	2.8	13.42	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.32	Lean	1	14.7	0.04	15	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:5	29.99	2446	2.8	13.43	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.37	Rich	1	14.7	0.01	15.03	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:6	29.99	2449	2.81	13.42	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.43	Rich	1	14.7	0	15.09	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:6	29.99	2449	2.81	13.43	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.52	Rich	1	14.7	0.04	15.12	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:6	29.99	2453	2.81	13.42	96	195	Off Idle	70.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	0.07	15.12	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:45:6	29.99	2453	2.81	13.43	96	195	Off Idle	70.3	0	2	132	944 Turbo	0.61	Rich	1	14.7	0.1	15.09	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:6	29.99	2454	2.81	13.43	96	195	Off Idle	70.1	0	2	132	944 Turbo	0.66	Rich	1	14.7	0.08	15.06	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:6	29.99	2458	2.81	13.44	96	195	Off Idle	70.1	0	2	132	944 Turbo	0.7	Rich	1	14.7	0.06	15.03	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:45:6	29.99	2471	2.82	13.42	96	195	Off Idle	70	0	2	132	944 Turbo	0.69	Rich	1	14.7	0.06	15	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:45:7	29.99	2467	2.82	13.43	96	195	Off Idle	69.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	0.11	14.96	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:45:7	29.99	2469	2.82	13.42	96	195	Off Idle	69.1	0	2	132	944 Turbo	0.64	Rich	1	14.7	0.13	14.93	1.02	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:45:7	29.99	2476	2.82	13.42	96	195	Off Idle	69	0	2	132	944 Turbo	0.59	Lean	1	14.7	0.1	14.87	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:45:7	29.99	2477	2.82	13.43	96	195	Off Idle	68.9	0	2	132	944 Turbo	0.53	Lean	1	14.7	0.11	14.84	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:45:7	29.99	2477	2.83	13.44	96	195	Off Idle	68.7	0	2	132	944 Turbo	0.44	Lean	1	14.7	0.09	14.81	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:45:7	29.99	2481	2.83	13.42	96	195	Off Idle	68.6	0	2	132	944 Turbo	0.38	Lean	1	14.7	0.13	14.8	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:45:8	29.99	2489	2.83	13.42	96	195	Off Idle	68.3	0	2	132	944 Turbo	0.32	Lean	1	14.7	0.1	14.79	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:45:8	29.99	2498	2.83	13.43	96	195	Off Idle	68.1	0	2	132	944 Turbo	0.28	Lean	1	14.7	0.13	14.82	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:45:8	29.99	2498	2.83	13.43	96	195	Off Idle	68	0	2	132	944 Turbo	0.26	Lean	1	14.7	0.13	14.85	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:26:45:8	29.99	2496	2.83	13.42	96	195	Off Idle	68	0	2	132	944 Turbo	0.27	Lean	1	14.7	0.19	14.87	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:26:45:8	29.99	2498	2.84	13.42	96	195	Off Idle	68	0	2	132	944 Turbo	0.3	Lean	1	14.7	0.22	14.9	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:45:8	29.99	2500	2.84	13.42	96	195	Off Idle	68	0	2	132	944 Turbo	0.34	Lean	1	14.7	0.24	14.93	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:9	29.99	2498	2.84	13.42	96	195	Off Idle	67.9	0	2	132	944 Turbo	0.39	Rich	1	14.7	0.24	14.96	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:9	29.99	2492	2.84	13.43	96	195	Off Idle	67.6	0	2	132	944 Turbo	0.48	Rich	1	14.7	0.22	15.03	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:9	29.99	2489	2.85	13.43	96	195	Off Idle	67.4	0	2	132	944 Turbo	0.54	Rich	1	14.7	0.18	15.04	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:9	29.99	2489	2.85	13.43	96	195	Off Idle	67.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	0.25	15.04	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:9	29.99	2496	2.85	13.43	96	195	Off Idle	67.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	0.29	15.02	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:9	29.99	2497	2.85	13.44	96	195	Off Idle	67.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	0.33	15	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:45:9	29.99	2496	2.85	13.44	96	195	Off Idle	67.1	0	2	132	944 Turbo	0.71	Rich	1	14.7	0.28	14.96	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:46:0	29.99	2506	2.85	13.43	96	195	Off Idle	66.9	0	2	132	944 Turbo	0.73	Rich	1	14.7	0.32	14.94	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:0	29.99	2518	2.85	13.43	96	195	Off Idle	66.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	0.28	14.9	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:0	29.99	2522	2.86	13.43	96	195	Off Idle	66.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	0.24	14.86	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:0	29.99	2534	2.86	13.44	96	195	Off Idle	66.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	0.21	14.81	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:0	29.99	2540	2.86	13.43	96	195	Off Idle	66.3	0	2	132	944 Turbo	0.68	Rich	1	14.7	0.23	14.78	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:46:0	29.99	2562	2.86	13.42	96	195	Off Idle	66	0	2	132	944 Turbo	0.67	Rich	1	14.7	0.28	14.77	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:46:1	29.99	2553	2.86	13.42	96	195	Off Idle	65.7	0	2	132	944 Turbo	0.65	Rich	1	14.7	0.31	14.78	1.01	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:46:1	29.99	2537	2.86	13.43	96	195	Off Idle	65.5	0	2	132	944 Turbo	0.62	Rich	1	14.7	0.28	14.79	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:1	29.99	2529	2.86	13.42	96	195	Off Idle	65.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	0.29	14.79	1.01	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:1	29.99	2532	2.87	13.42	96	195	Off Idle	65.2	0	2	132	944 Turbo	0.53	Rich	1	14.7	0.34	14.81	1.01	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:1	29.99	2537	2.87	13.43	96	195	Off Idle	64.9	0	2	132	944 Turbo	0.5	Rich	1	14.7	0.25	14.82	1.01	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:1	29.99	2545	2.87	13.42	96	195	Off Idle	64.6	0	2	132	944 Turbo	0.45	Rich	1	14.7	0.26	14.82	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:1	29.99	2558	2.87	13.43	96	195	Off Idle	64.4	0	2	132	944 Turbo	0.4	Rich	1	14.7	0.31	14.81	1.01	3.5	5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:2	29.99	2558	2.87	13.41	96	195	Off Idle	64.3	0	2	132	944 Turbo	0.34	Lean	1	14.7	0.29	14.84	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:2	29.99	2582	2.87	13.42	96	195	Off Idle	64.1	0	2	132	944 Turbo	0.3	Lean	1	14.7	0.35	14.87	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:2	29.99	2564	2.87	13.42	96	195	Off Idle	64	0	2	132	944 Turbo	0.27	Lean	1	14.7	0.34	14.91	1.02	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:2	29.99	2566	2.88	13.42	96	195	Off Idle	63.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	0.26	14.95	1.02	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:2	29.99	2566	2.88	13.42	96	195	Off Idle	63.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	0.35	14.98	1.02	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:2	29.99	2566	2.88	13.45	96	195	Off Idle	62.9	0	2	132	944 Turbo	0.19	Lean	1	14.7	0.35	15	1.02	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:3	29.99	2566	2.88	13.44	96	195	Off Idle	63	0	2	132	944 Turbo	0.23	Lean	1	14.7	0.35	15.06	1.03	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:3	29.99	2563	2.89	13.44	96	195	Off Idle	62.9	0	2	132	944 Turbo	0.26	Lean	1	14.7	0.32	15.08	1.03	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:3	29.99	2564	2.89	13.44	96	195	Off Idle	62.9	0	2	132	944 Turbo	0.34	Lean	1	14.7	0.34	15.14	1.03	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:46:3	29.99	2564	2.89	13.44	96	195	Off Idle	62.9	0	2	132	944 Turbo	0.41	Lean	1	14.7	0.34	15.19	1.04	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:46:3	29.99	2559	2.89	13.42	96	195	Off Idle	62.9	0	2	132	944 Turbo	0.47	Rich	1	14.7	0.36	15.2	1.04	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:46:3	29.99	2576	2.89	13.43	96	195	Off Idle	62.9	0	2	132	944 Turbo	0.54	Rich	1	14.7	0.34	15.18	1.03	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:46:4	29.99	2578	2.89	13.42	96	195	Off Idle	62.8	0	2	132	944 Turbo	0.6	Rich	1	14.7	0.34	15.16	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:4	29.99	2580	2.89	13.4	96	195	Off Idle	62.7	0	2	132	944 Turbo	0.65	Rich	1	14.7	0.38	15.12	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:4	29.99	2596	2.89	13.41	96	195	Off Idle	62.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	0.37	15.08	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:4	29.99	2585	2.9	13.42	96	195	Off Idle	62.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	0.32	15.02	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:4	29.99	2585	2.9	13.42	96	195	Off Idle	62.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	0.36	14.96	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:4	29.99	2589	2.9	13.41	96	195	Off Idle	62.1	0	2	132	944 Turbo	0.66	Rich	1	14.7	0.39	14.93	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:4	29.99	2596	2.9	13.42	96	195	Off Idle	62.1	0	2	132	944 Turbo	0.62	Rich	1	14.7	0.34	14.86	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:5	29.99	2599	2.9	13.43	96	195	Off Idle	62.1	0	2	132	944 Turbo	0.57	Rich	1	14.7	0.32	14.82	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:5	29.99	2599	2.9	13.43	96	195	Off Idle	62.2	0	2	132	944 Turbo	0.51	Lean	1	14.7	0.28	14.8	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:5	29.99	2604	2.9	13.42	96	195	Off Idle	61.9	0	2	132	944 Turbo	0.46	Lean	1	14.7	0.28	14.77	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:5	29.99	2605	2.9	13.43	96	195	Off Idle	61.6	0	2	132	944 Turbo	0.4	Lean	1	14.7	0.3	14.76	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:5	29.99	2605	2.9	13.42	96	195	Off Idle	61.3	0	2	132	944 Turbo	0.35	Lean	1	14.7	0.25	14.77	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:46:5	29.99	2607	2.9	13.42	96	195	Off Idle	61	0	2	132	944 Turbo	0.32	Lean	1	14.7	0.24	14.8	1.01	3.6	4.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:46:6	29.99	2608	2.9	13.42	96	195	Off Idle	60.6	0	2	132	944 Turbo	0.32	Lean	1	14.7	0.23	14.82	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:46:6	29.99	2608	2.9	13.43	96	195	Off Idle	60.6	0	2	132	944 Turbo	0.35	Lean	1	14.7	0.19	14.86	1.01	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:26:46:6	29.99	2609	2.9	13.44	96	195	Off Idle	60.6	0	2	132	944 Turbo	0.39	Lean	1	14.7	0.08	14.93	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:6	29.99	2609	2.9	13.43	96	195	Off Idle	60.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	0.08	14.98	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:6	29.99	2613	2.9	13.43	96	195	Off Idle	60.2	0	2	132	944 Turbo	0.49	Lean	1	14.7	0.09	14.99	1.02	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:46:6	29.99	2613	2.9	13.44	96	195	Off Idle	60.1	0	2	132	944 Turbo	0.54	Rich	1	14.7	0	15	1.02	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:46:6	29.99	2630	2.9	13.42	96	195	Off Idle	59.9	0	2	132	944 Turbo	0.61	Rich	1	14.7	-0.06	15.01	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:7	31.36	2627	2.89	13.42	96	195	Off Idle	59.7	0	2	132	944 Turbo	0.66	Rich	1	14.7	-0.03	15.02	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:7	31.36	2626	2.89	13.41	96	195	Off Idle	59.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-0.12	14.99	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:7	31.36	2631	2.89	13.42	96	195	Off Idle	59.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.18	14.96	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:7	31.36	2636	2.89	13.43	96	195	Off Idle	59.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.21	14.92	1.02	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:7	29.99	2627	2.89	13.41	96	195	Off Idle	59.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.21	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:7	29.99	2634	2.88	13.42	96	195	Off Idle	59.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-0.28	14.83	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:8	29.99	2638	2.88	13.42	96	195	Off Idle	59.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-0.3	14.8	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:46:8	29.99	2638	2.88	13.42	96	195	Off Idle	59.3	0	2	132	944 Turbo	0.61	Rich	1	14.7	-0.25	14.79	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:26:46:8	31.36	2650	2.88	13.41	96	195	Off Idle	59	0	2	132	944 Turbo	0.52	Lean	1	14.7	-0.28	14.8	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:8	31.36	2646	2.88	13.41	96	195	Off Idle	59	0	2	132	944 Turbo	0.46	Lean	1	14.7	-0.28	14.78	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:8	31.36	2648	2.87	13.41	96	195	Off Idle	58.6	0	2	132	944 Turbo	0.43	Lean	1	14.7	-0.24	14.76	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:8	31.36	2658	2.87	13.41	96	195	Off Idle	58.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	-0.3	14.79	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:9	31.36	2688	2.87	13.41	96	195	Off Idle	58.3	0	2	132	944 Turbo	0.28	Lean	1	14.7	-0.27	14.83	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:9	31.36	2688	2.87	13.41	96	195	Off Idle	58.2	0	2	132	944 Turbo	0.22	Lean	1	14.7	-0.35	14.84	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:9	31.36	2670	2.87	13.42	96	195	Off Idle	58	0	2	132	944 Turbo	0.18	Lean	1	14.7	-0.38	14.87	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:9	31.36	2668	2.87	13.43	96	195	Off Idle	57.9	0	2	132	944 Turbo	0.18	Lean	1	14.7	-0.34	14.91	1.02	3.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:46:9	29.99	2668	2.87	13.43	96	195	Off Idle	57.8	0	2	132	944 Turbo	0.19	Lean	1	14.7	-0.39	14.94	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:9	29.99	2653	2.87	13.42	96	195	Off Idle	57.6	0	2	132	944 Turbo	0.23	Lean	1	14.7	-0.39	14.95	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:46:9	29.99	2657	2.87	13.42	96	195	Off Idle	57.5	0	2	132	944 Turbo	0.29	Rich	1	14.7	-0.33	15	1.02	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:0	29.99	2657	2.87	13.43	96	195	Off Idle	57.3	0	2	132	944 Turbo	0.37	Rich	1	14.7	-0.31	15.11	1.03	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:47:0	29.99	2661	2.87	13.43	96	195	Off Idle	57.2	0	2	132	944 Turbo	0.43	Rich	1	14.7	-0.39	15.12	1.03	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:47:0	29.99	2686	2.87	13.43	96	195	Off Idle	57.2	0	2	132	944 Turbo	0.49	Rich	1	14.7	-0.36	15.11	1.03	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:47:0	31.36	2666	2.87	13.43	96	195	Off Idle	57	0	2	132	944 Turbo	0.55	Rich	1	14.7	-0.33	15.11	1.03	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:0	31.36	2670	2.87	13.43	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.59	Rich	1	14.7	-0.43	15.08	1.03	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:47:0	31.36	2684	2.87	13.44	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.61	Rich	1	14.7	-0.41	15.07	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:26:47:1	31.36	2695	2.87	13.42	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.64	Rich	1	14.7	-0.44	15	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:1	31.36	2698	2.88	13.42	96	195	Off Idle	56.8	0	2	132	944 Turbo	0.64	Rich	1	14.7	-0.4	14.98	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:1	31.36	2708	2.88	13.43	96	195	Off Idle	56.6	0	2	132	944 Turbo	0.65	Rich	1	14.7	-0.41	14.98	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:1	31.36	2710	2.88	13.42	96	195	Off Idle	56.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-0.4	14.93	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:1	31.36	2710	2.88	13.42	96	195	Off Idle	56.3	0	2	132	944 Turbo	0.68	Rich	1	14.7	-0.39	14.94	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:1	31.36	2702	2.88	13.42	96	195	Off Idle	56.1	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.37	14.92	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:1	31.36	2693	2.88	13.43	96	195	Off Idle	56	0	2	132	944 Turbo	0.7	Rich	1	14.7	-0.36	14.9	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:2	31.36	2688	2.88	13.42	96	195	Off Idle	55.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.37	14.85	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:2	31.36	2692	2.88	13.44	96	195	Off Idle	55.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-0.41	14.69	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:2	31.36	2692	2.88	13.46	96	195	Off Idle	55.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.49	14.65	1	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:2	31.36	2706	2.88	13.44	96	195	Off Idle	55.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.47	14.48	0.99	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:2	31.36	2722	2.88	13.44	96	195	Off Idle	55.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-0.45	14.36	0.98	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:2	31.36	2722	2.88	13.45	96	195	Off Idle	55.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-0.54	14.23	0.97	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:47:3	31.36	2724	2.88	13.44	96	195	Off Idle	54.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-0.53	14.09	0.96	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:47:3	31.36	2746	2.88	13.43	96	195	Off Idle	54.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.54	13.94	0.95	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:47:3	32.72	2746	2.88	13.44	96	195	Off Idle	54.3	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.65	13.8	0.94	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:26:47:3	32.72	2728	2.87	13.43	96	195	Off Idle	54.3	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.73	13.69	0.93	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:47:3	32.72	2730	2.87	13.42	96	195	Off Idle	54.2	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.88	13.63	0.93	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:26:47:3	32.72	2730	2.86	13.44	96	195	Off Idle	54.1	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.18	13.58	0.93	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:26:47:4	32.72	2724	2.85	13.44	96	195	Off Idle	53.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.37	13.51	0.92	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:26:47:4	32.72	2730	2.84	13.43	96	195	Off Idle	53.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.54	13.48	0.92	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:47:4	32.72	2730	2.83	13.44	96	194	Off Idle	53.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.66	13.43	0.91	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:26:47:4	32.72	2731	2.82	13.44	96	194	Off Idle	53.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.8	13.39	0.91	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:4	32.72	2736	2.81	13.44	96	194	Off Idle	53.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.96	13.34	0.91	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:47:4	32.72	2741	2.79	13.45	96	195	Off Idle	53.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.1	13.3	0.91	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:47:4	32.72	2752	2.78	13.44	96	195	Off Idle	53.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.25	13.23	0.9	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:47:5	32.72	2747	2.77	13.44	96	195	Off Idle	53.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.31	13.18	0.9	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:47:5	32.72	2750	2.76	13.44	96	195	Off Idle	53.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.41	13.13	0.89	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:47:5	32.72	2754	2.74	13.44	96	195	Off Idle	53.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.54	13.08	0.89	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:47:5	32.72	2754	2.73	13.44	96	195	Off Idle	53.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.65	13.06	0.89	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:47:5	32.72	2753	2.71	13.44	96	195	Off Idle	53.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.79	13.04	0.89	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:47:5	32.72	2749	2.69	13.43	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.94	13.05	0.89	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:47:6	32.72	2746	2.68	13.43	96	195	Off Idle	52.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-3.04	13.06	0.89	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:47:6	32.72	2740	2.66	13.43	96	195	Off Idle	52.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.19	13.14	0.89	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:6	32.72	2736	2.65	13.43	96	195	Off Idle	52.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.23	13.17	0.9	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:6	32.72	2734	2.63	13.42	96	195	Off Idle	52.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.33	13.24	0.9	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:6	32.72	2734	2.62	13.44	96	195	Off Idle	52.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.45	13.35	0.91	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:47:6	34.08	2742	2.62	13.44	96	195	Off Idle	52.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.57	13.47	0.92	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:6	34.08	2756	2.61	13.44	96	195	Off Idle	52.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-3.62	13.56	0.92	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:47:7	34.08	2756	2.59	13.44	96	195	Off Idle	52.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-3.8	13.64	0.93	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:47:7	34.08	2780	2.58	13.44	96	195	Off Idle	52.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-3.94	13.7	0.93	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:47:7	34.08	2768	2.55	13.45	96	195	Off Idle	52	0	2	132	944 Turbo	0.79	Rich	1	14.7	-4.19	13.77	0.94	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:47:7	34.08	2770	2.53	13.44	96	195	Off Idle	51.8	0	2	132	944 Turbo	0.78	Rich	1	14.7	-4.52	13.84	0.94	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:47:7	34.08	2762	2.47	13.42	96	195	Off Idle	51.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	-4.69	13.91	0.95	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:47:7	34.08	2729	2.42	13.43	96	195	Off Idle	51.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.25	13.98	0.95	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:47:8	34.08	2742	2.39	13.42	96	195	Full Load	51.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.12	14.08	0.96	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:47:8	34.08	2739	2.33	13.4	96	195	Idle	51.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.66	14.16	0.96	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:8	34.08	2730	2.27	13.43	96	195	Idle	51.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.18	14.25	0.97	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:8	34.08	2721	2.21	13.43	96	195	Idle	52.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.62	14.33	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:8	34.08	2712	2.16	13.42	96	195	Idle	52.2	0	2	132	944 Turbo	0.77	Rich	1	14.7	-7.91	14.42	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:8	34.08	2692	2.14	13.42	96	195	Idle	52.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.07	14.49	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:9	34.08	2674	2.09	13.44	96	195	Idle	52.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.38	14.55	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:9	34.08	2637	2.01	13.43	96	195	Idle	52.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	-8.7	14.61	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:47:9	28.63	2600	1.98	13.44	96	195	Idle	53.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.81	14.62	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:47:9	23.18	2592	1.89	13.44	96	195	Idle	53.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.1	14.64	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:9	23.18	2592	1.84	13.44	96	195	Idle	53.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.24	14.62	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:9	19.09	2626	1.78	13.43	96	195	Idle	54.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.36	14.61	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:47:9	19.09	2682	1.73	13.45	96	195	Idle	54.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.48	14.59	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:0	19.09	2727	1.71	13.44	96	195	Idle	54.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.58	14.55	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:0	19.09	2748	1.66	13.45	96	195	Idle	54.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.67	14.5	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:0	19.09	2772	1.6	13.45	96	195	Idle	54.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.77	14.47	0.99	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:0	19.09	2786	1.56	13.47	96	195	Idle	54.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.86	14.45	0.98	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:0	19.09	2784	1.52	13.47	96	195	Idle	54.8	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.94	14.42	0.98	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:0	19.09	2796	1.49	13.47	96	195	Idle	54.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.95	14.4	0.98	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:1	19.09	2752	1.48	13.46	96	195	Idle	54.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.96	14.41	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:1	19.09	2734	1.48	13.44	96	195	Idle	54	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.92	14.41	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:1	19.09	2726	1.48	13.45	96	195	Idle	53.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.91	14.42	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:1	19.09	2676	1.49	13.44	96	195	Idle	53.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.88	14.44	0.98	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:1	19.09	2682	1.49	13.44	96	195	Idle	53.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.85	14.48	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:1	19.09	2678	1.48	13.44	96	195	Idle	53.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.84	14.53	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:1	19.09	2665	1.48	13.45	96	195	Idle	52.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.86	14.55	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:2	19.09	2663	1.48	13.44	96	195	Idle	52.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.82	14.61	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:2	19.09	2669	1.48	13.44	96	195	Idle	51.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.81	14.8	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:2	19.09	2673	1.49	13.46	96	195	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	14.98	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:2	19.09	2695	1.49	13.46	96	195	Idle	51	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	15.19	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:2	19.09	2716	1.5	13.45	96	195	Idle	50.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	15.43	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:2	19.09	2716	1.5	13.45	96	194	Idle	50.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	15.71	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:3	19.09	2728	1.51	13.46	96	194	Idle	50.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	15.99	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:3	19.09	2735	1.51	13.45	96	194	Idle	50.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	16.3	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:3	19.09	2735	1.51	13.45	96	195	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	16.67	1.14	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:3	19.09	2731	1.51	13.45	96	195	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	17.11	1.17	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:3	19.09	2724	1.52	13.44	96	195	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	17.58	1.2	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:3	19.09	2722	1.53	13.44	96	195	Idle	50.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	18.02	1.23	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:4	19.09	2712	1.53	13.45	96	195	Idle	51	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	18.6	1.27	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:48:4	19.09	2680	1.53	13.46	96	195	Idle	51.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	18.93	1.29	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:4	19.09	2680	1.53	13.46	96	194	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	19.24	1.31	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:4	19.09	2695	1.53	13.46	96	194	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	19.52	1.33	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:4	19.09	2691	1.53	13.46	96	194	Idle	52.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	19.79	1.35	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:4	19.09	2691	1.53	13.46	96	195	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.01	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:4	19.09	2686	1.53	13.45	96	195	Idle	52.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:5	19.09	2681	1.53	13.44	96	195	Idle	53.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:5	19.09	2679	1.52	13.45	96	194	Idle	53.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:5	19.09	2679	1.52	13.46	96	194	Idle	53.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:5	19.09	2679	1.52	13.45	96	194	Idle	53.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:5	19.09	2683	1.52	13.45	96	194	Idle	54	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:5	19.09	2683	1.52	13.45	96	194	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:6	19.09	2689	1.52	13.44	96	194	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:6	19.09	2693	1.51	13.44	96	194	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:6	19.09	2693	1.51	13.45	96	194	Idle	54	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:6	19.09	2692	1.51	13.44	96	194	Idle	53.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:6	19.09	2689	1.5	13.45	96	194	Idle	53.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:6	19.09	2681	1.5	13.46	96	194	Idle	53.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:6	19.09	2688	1.5	13.46	96	195	Idle	53.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:7	19.09	2670	1.5	13.45	96	195	Idle	53.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:7	19.09	2666	1.5	13.46	96	195	Idle	53.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:7	19.09	2666	1.5	13.45	96	195	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:7	19.09	2659	1.5	13.45	96	194	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:7	19.09	2658	1.5	13.45	96	194	Idle	54.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:7	19.09	2656	1.5	13.45	96	194	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:8	19.09	2657	1.49	13.45	96	194	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:8	19.09	2662	1.49	13.44	96	194	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:8	19.09	2662	1.49	13.46	96	194	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:8	19.09	2666	1.49	13.46	96	194	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:8	19.09	2670	1.49	13.46	96	194	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:8	19.09	2670	1.49	13.46	96	195	Idle	54.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:9	19.09	2673	1.49	13.47	96	195	Idle	54.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:9	19.09	2674	1.49	13.45	96	195	Idle	54.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:9	19.09	2674	1.49	13.44	96	195	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:9	19.09	2674	1.49	13.45	96	195	Idle	54.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:9	19.09	2673	1.49	13.45	96	195	Idle	55	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:9	19.09	2671	1.49	13.46	96	194	Idle	55	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:48:9	19.09	2665	1.49	13.45	96	194	Idle	55.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:0	19.09	2664	1.49	13.45	96	194	Idle	55.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:0	19.09	2656	1.49	13.46	96	194	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:0	19.09	2650	1.48	13.45	96	195	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:0	19.09	2648	1.48	13.44	96	195	Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:0	19.09	2642	1.48	13.45	96	195	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:0	19.09	2638	1.48	13.44	96	195	Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:1	19.09	2633	1.48	13.45	96	195	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:1	19.09	2633	1.48	13.45	96	195	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:1	19.09	2619	1.48	13.45	96	195	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:1	19.09	2625	1.48	13.45	96	195	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:1	19.09	2625	1.47	13.45	96	195	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:1	19.09	2620	1.47	13.44	96	194	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:1	19.09	2623	1.47	13.44	96	194	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:2	19.09	2629	1.47	13.45	96	194	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:2	19.09	2629	1.46	13.46	96	194	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:2	19.09	2637	1.46	13.45	96	194	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:2	19.09	2643	1.46	13.46	96	195	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:2	19.09	2643	1.46	13.46	96	195	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:2	19.09	2646	1.46	13.46	96	195	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:3	19.09	2656	1.46	13.46	96	195	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.09	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:49:3	19.09	2656	1.46	13.46	96	195	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.08	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:3	19.09	2634	1.46	13.46	96	195	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.09	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:3	19.09	2638	1.46	13.45	96	194	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.08	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:3	19.09	2653	1.46	13.44	96	194	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.09	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:3	19.09	2642	1.46	13.44	96	194	Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.09	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:4	19.09	2627	1.46	13.44	96	194	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.08	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:4	19.09	2611	1.46	13.45	96	194	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.08	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:4	19.09	2617	1.45	13.45	96	194	Idle	57.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.09	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:4	19.09	2617	1.45	13.46	96	194	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.08	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:4	19.09	2614	1.45	13.45	96	194	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:4	19.09	2634	1.45	13.46	96	195	Idle	58.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:4	19.09	2614	1.45	13.46	96	195	Idle	58.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:5	19.09	2614	1.45	13.46	96	195	Idle	58.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:5	19.09	2617	1.45	13.45	96	195	Idle	58.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:5	19.09	2618	1.44	13.46	96	194	Idle	58.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:5	19.09	2618	1.44	13.45	96	194	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:5	19.09	2606	1.44	13.46	96	194	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:5	19.09	2614	1.44	13.45	96	194	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:6	19.09	2631	1.43	13.44	96	194	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:6	19.09	2614	1.43	13.45	96	194	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:6	19.09	2608	1.43	13.45	96	194	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:6	19.09	2598	1.43	13.46	96	194	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:6	19.09	2592	1.43	13.46	96	194	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:6	19.09	2592	1.43	13.46	96	195	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:6	19.09	2588	1.42	13.45	96	195	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:7	19.09	2606	1.42	13.46	96	195	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:7	19.09	2606	1.42	13.45	96	195	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:7	19.09	2584	1.42	13.45	96	195	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:7	19.09	2585	1.42	13.45	96	195	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:7	19.09	2586	1.42	13.45	96	195	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:7	19.09	2587	1.42	13.44	96	194	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:8	19.09	2591	1.42	13.44	96	194	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:8	19.09	2594	1.42	13.44	96	194	Idle	58.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:8	19.09	2597	1.42	13.46	96	194	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:8	19.09	2597	1.42	13.44	96	195	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:8	19.09	2596	1.42	13.45	96	195	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:8	19.09	2592	1.42	13.44	96	195	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:9	19.09	2589	1.42	13.45	96	195	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:9	19.09	2586	1.42	13.44	96	195	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:9	19.09	2579	1.42	13.44	96	195	Idle	59.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:9	19.09	2575	1.42	13.43	96	195	Idle	59.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:9	19.09	2569	1.42	13.45	96	195	Idle	59.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:9	19.09	2569	1.42	13.44	96	195	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:49:9	19.09	2562	1.42	13.44	96	195	Idle	60.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:0	19.09	2557	1.42	13.45	96	195	Idle	60.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:0	19.09	2557	1.42	13.45	96	194	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:0	19.09	2554	1.41	13.44	96	194	Idle	61	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:0	19.09	2556	1.41	13.44	96	194	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:0	19.09	2556	1.41	13.44	96	194	Idle	60.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:0	19.09	2556	1.41	13.46	96	194	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:1	19.09	2516	1.41	13.46	96	194	Idle	61.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:1	19.09	2536	1.41	13.46	96	194	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:1	19.09	2554	1.4	13.47	96	195	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:1	19.09	2564	1.4	13.45	96	195	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:1	19.09	2557	1.4	13.44	96	195	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:1	19.09	2557	1.4	13.45	96	194	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:1	19.09	2558	1.39	13.44	96	194	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:2	19.09	2558	1.39	13.44	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:50:2	19.09	2558	1.39	13.44	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:2	19.09	2558	1.39	13.44	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:2	19.09	2555	1.38	13.45	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:2	19.09	2554	1.38	13.44	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:2	19.09	2560	1.38	13.44	96	194	Idle	61.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:3	19.09	2546	1.38	13.45	96	194	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:3	19.09	2524	1.38	13.46	96	194	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:3	19.09	2532	1.38	13.45	96	194	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:3	19.09	2539	1.38	13.45	96	195	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:3	19.09	2519	1.38	13.46	96	195	Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:3	19.09	2519	1.38	13.46	96	195	Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:4	19.09	2538	1.37	13.46	96	195	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:4	19.09	2548	1.37	13.45	96	195	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:4	19.09	2548	1.37	13.45	96	195	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:4	19.09	2540	1.37	13.46	96	194	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:4	19.09	2542	1.37	13.45	96	194	Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:4	19.09	2540	1.37	13.44	96	194	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:4	19.09	2540	1.37	13.45	96	194	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:5	19.09	2536	1.37	13.46	96	194	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:5	19.09	2536	1.37	13.46	96	194	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:5	19.09	2534	1.37	13.45	96	195	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:5	19.09	2530	1.37	13.44	96	195	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:5	19.09	2528	1.37	13.44	96	195	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:5	19.09	2526	1.37	13.44	96	195	Idle	62.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:6	19.09	2508	1.37	13.42	96	195	Idle	62.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:6	19.09	2526	1.37	13.42	96	195	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:6	19.09	2524	1.37	13.44	96	194	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:6	19.09	2524	1.37	13.43	96	194	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:6	19.09	2521	1.36	13.43	96	194	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:6	19.09	2519	1.36	13.43	96	194	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:6	19.09	2519	1.36	13.45	96	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:7	19.09	2509	1.36	13.46	96	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:7	19.09	2514	1.36	13.44	96	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:7	19.09	2524	1.36	13.44	96	194	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:7	19.09	2512	1.36	13.45	96	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:7	19.09	2500	1.36	13.45	96	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:7	19.09	2500	1.36	13.43	96	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:8	19.09	2506	1.36	13.42	96	194	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:8	19.09	2504	1.36	13.43	96	194	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:8	19.09	2500	1.36	13.43	96	194	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:8	19.09	2500	1.36	13.43	96	194	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:8	19.09	2502	1.35	13.43	96	194	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:8	19.09	2502	1.35	13.43	96	194	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:9	19.09	2502	1.35	13.43	96	194	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:9	19.09	2507	1.35	13.43	96	194	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:9	19.09	2513	1.35	13.43	96	194	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:9	19.09	2515	1.35	13.43	96	194	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:9	19.09	2515	1.35	13.43	96	194	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:9	19.09	2516	1.35	13.44	96	194	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:50:9	19.09	2514	1.34	13.45	96	194	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:0	19.09	2522	1.34	13.44	96	194	Idle	64.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:0	19.09	2508	1.34	13.45	96	195	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:0	19.09	2496	1.34	13.45	96	195	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:0	19.09	2496	1.34	13.45	96	195	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:0	19.09	2493	1.34	13.45	96	194	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:0	19.09	2491	1.34	13.46	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:1	19.09	2486	1.33	13.45	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:1	19.09	2480	1.33	13.45	96	194	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:51:1	19.09	2480	1.33	13.44	96	194	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:1	19.09	2480	1.33	13.44	96	194	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:1	19.09	2478	1.33	13.44	96	194	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:1	19.09	2478	1.33	13.45	96	194	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:1	19.09	2477	1.33	13.44	96	195	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:2	19.09	2478	1.33	13.46	96	195	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:2	19.09	2478	1.32	13.44	96	195	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:2	19.09	2479	1.32	13.45	96	194	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:2	19.09	2479	1.32	13.46	96	194	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:2	19.09	2479	1.32	13.44	96	194	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:2	19.09	2479	1.32	13.44	96	194	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:3	19.09	2479	1.32	13.44	96	194	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:3	19.09	2478	1.32	13.45	96	194	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:3	19.09	2476	1.32	13.44	96	194	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:3	19.09	2474	1.32	13.46	96	194	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:3	19.09	2473	1.31	13.45	96	194	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:3	19.09	2469	1.31	13.45	96	194	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:4	19.09	2467	1.31	13.44	96	194	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:4	19.09	2465	1.31	13.46	96	194	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:4	19.09	2462	1.31	13.46	96	194	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:4	19.09	2440	1.31	13.45	96	194	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:4	19.09	2448	1.31	13.44	96	194	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:4	19.09	2455	1.31	13.45	96	194	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:4	19.09	2479	1.3	13.44	96	194	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:5	19.09	2453	1.3	13.45	96	194	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:5	19.09	2453	1.3	13.45	96	194	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:5	19.09	2451	1.3	13.44	96	194	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:5	19.09	2451	1.3	13.43	96	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:5	19.09	2461	1.29	13.43	96	194	Idle	67.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:5	19.09	2441	1.29	13.43	96	194	Idle	68	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:6	19.09	2450	1.29	13.43	96	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:6	19.09	2450	1.29	13.44	96	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:6	19.09	2471	1.29	13.44	96	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:6	19.09	2450	1.28	13.44	96	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:6	19.09	2450	1.28	13.45	96	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:6	19.09	2438	1.28	13.45	96	195	Off Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:6	19.09	2323	1.28	13.44	96	195	Off Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:51:7	10.9	2392	1.29	13.44	96	195	Off Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:51:7	10.9	2460	1.29	13.45	96	194	Off Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:51:7	13.63	2457	1.3	13.44	96	194	Off Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:51:7	16.36	2457	1.32	13.45	96	194	Off Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.19	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:51:7	16.36	2452	1.33	13.44	96	194	Off Idle	68.3	0	2	132	944 Turbo	0.01	Lean	1	14.7	-10.13	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:51:7	19.09	2452	1.34	13.44	96	194	Off Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:51:8	21.81	2449	1.35	13.43	96	194	Off Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.98	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:51:8	21.81	2450	1.37	13.44	96	194	Off Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:51:8	24.54	2452	1.39	13.45	96	194	Off Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.79	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:51:8	24.54	2456	1.41	13.43	96	194	Off Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:51:8	27.27	2459	1.43	13.44	96	194	Off Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:51:8	29.99	2465	1.47	13.44	96	194	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.59	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:51:9	32.72	2477	1.49	13.45	96	194	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.48	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:51:9	32.72	2504	1.52	13.45	96	194	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	20.22	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:51:9	35.45	2494	1.54	13.45	96	194	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.23	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:26:51:9	35.45	2476	1.57	13.44	96	194	Off Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.31	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:51:9	35.45	2476	1.58	13.45	96	194	Off Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:51:9	35.45	2484	1.62	13.44	96	194	Off Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.18	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:51:9	35.45	2486	1.65	13.44	96	194	Off Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	20.24	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:26:52:0	35.45	2484	1.68	13.44	96	194	Off Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.99	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:0	35.45	2482	1.69	13.44	96	194	Off Idle	68.1	0	2	132	944 Turbo	0.03	Lean	1	14.7	-8.89	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:52:0	35.45	2482	1.72	13.45	96	194	Off Idle	67.8	0	2	132	944 Turbo	0.03	Lean	1	14.7	-8.78	20.23	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:52:0	35.45	2478	1.74	13.45	96	195	Off Idle	67.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.71	20.23	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:52:0	35.45	2467	1.76	13.44	96	195	Off Idle	67.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.56	20.23	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:52:0	35.45	2463	1.8	13.44	96	195	Off Idle	67.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.32	20.24	1.38	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:52:1	35.45	2453	1.83	13.45	96	195	Off Idle	67	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.16	20.22	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:52:1	35.45	2435	1.86	13.44	96	195	Off Idle	67	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8	20.23	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:52:1	35.45	2427	1.88	13.45	96	195	Off Idle	67	0	2	132	944 Turbo	0.04	Lean	1	14.7	-7.8	20.23	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:52:1	35.45	2427	1.9	13.44	96	195	Off Idle	67.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.63	20.22	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:26:52:1	35.45	2426	1.93	13.45	96	195	Off Idle	67.3	0	2	132	944 Turbo	0.05	Lean	1	14.7	-7.33	20.23	1.38	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:52:1	35.45	2433	1.93	13.43	96	195	Off Idle	67.5	0	2	132	944 Turbo	0.05	Lean	1	14.7	-7.24	20.23	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:52:1	35.45	2437	1.96	13.44	96	194	Off Idle	67.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.02	20.23	1.38	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:52:2	35.45	2450	2	13.43	96	194	Off Idle	67.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.76	20.22	1.38	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:52:2	35.45	2458	2.03	13.42	96	194	Off Idle	68.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.54	20.12	1.37	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:52:2	34.08	2470	2.06	13.42	96	195	Off Idle	68.5	0	2	132	944 Turbo	0.05	Lean	1	14.7	-6.36	19.94	1.36	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:52:2	34.08	2470	2.09	13.43	96	195	Off Idle	68.6	0	2	132	944 Turbo	0.05	Lean	1	14.7	-6.14	19.72	1.34	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:52:2	34.08	2479	2.12	13.43	96	195	Off Idle	68.8	0	2	132	944 Turbo	0.05	Lean	1	14.7	-5.93	19.46	1.33	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:52:2	34.08	2472	2.14	13.43	96	195	Off Idle	68.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-5.72	19.18	1.31	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:52:3	34.08	2474	2.18	13.44	96	195	Off Idle	68.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-5.5	18.86	1.28	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:52:3	34.08	2470	2.2	13.43	96	195	Off Idle	68.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-5.35	18.37	1.25	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:52:3	32.72	2454	2.23	13.44	96	195	Off Idle	68.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-5.23	18.01	1.23	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:52:3	32.72	2454	2.24	13.43	96	195	Off Idle	68.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-5.18	17.83	1.21	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:52:3	32.72	2452	2.27	13.43	96	195	Off Idle	68.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.03	17.32	1.18	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:52:3	32.72	2448	2.29	13.42	96	195	Off Idle	68.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.91	17.06	1.16	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:52:4	32.72	2449	2.31	13.43	96	195	Off Idle	68.8	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.8	16.85	1.15	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:52:4	32.72	2440	2.33	13.42	96	194	Off Idle	68.7	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.65	16.69	1.14	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:52:4	32.72	2455	2.35	13.42	96	194	Off Idle	68.5	0	2	132	944 Turbo	0.24	Lean	1	14.7	-4.46	16.46	1.12	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:52:4	32.72	2464	2.36	13.42	96	194	Off Idle	68.5	0	2	132	944 Turbo	0.27	Lean	1	14.7	-4.38	16.4	1.12	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:52:4	32.72	2473	2.39	13.43	96	194	Off Idle	68.3	0	2	132	944 Turbo	0.37	Rich	1	14.7	-4.15	16.21	1.1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:52:4	32.72	2485	2.41	13.44	96	195	Off Idle	68.3	0	2	132	944 Turbo	0.43	Rich	1	14.7	-3.97	16.08	1.1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:52:4	32.72	2479	2.43	13.44	96	195	Off Idle	68.3	0	2	132	944 Turbo	0.5	Rich	1	14.7	-3.79	15.94	1.09	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:52:5	32.72	2479	2.44	13.46	96	195	Off Idle	68.2	0	2	132	944 Turbo	0.57	Rich	1	14.7	-3.65	15.81	1.08	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:52:5	32.72	2480	2.46	13.44	96	195	Off Idle	68.3	0	2	132	944 Turbo	0.63	Rich	1	14.7	-3.52	15.71	1.07	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:5	32.72	2482	2.48	13.44	96	195	Off Idle	68.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-3.33	15.58	1.06	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:5	32.72	2486	2.49	13.42	96	195	Off Idle	68.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-3.25	15.46	1.05	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:5	32.72	2488	2.5	13.43	96	195	Off Idle	68.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-3.19	15.34	1.05	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:5	32.72	2491	2.51	13.44	96	195	Off Idle	68.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-3.11	15.25	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:6	32.72	2492	2.52	13.45	96	195	Off Idle	68.1	0	2	132	944 Turbo	0.75	Rich	1	14.7	-3.1	15.16	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:6	32.72	2492	2.53	13.43	96	195	Off Idle	67.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-3.03	15.09	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:6	32.72	2493	2.54	13.44	96	195	Off Idle	67.7	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.98	15.04	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:6	32.72	2491	2.56	13.44	96	195	Off Idle	67.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.96	14.99	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:6	32.72	2491	2.57	13.43	96	195	Off Idle	67.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.93	14.95	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:6	32.72	2492	2.58	13.43	96	195	Off Idle	67.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.91	14.86	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:6	32.72	2495	2.59	13.42	96	195	Off Idle	67.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.94	14.79	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:7	32.72	2503	2.6	13.43	96	195	Off Idle	67.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.9	14.72	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:7	32.72	2503	2.6	13.43	96	195	Off Idle	67.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.89	14.64	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:7	32.72	2506	2.6	13.43	96	195	Off Idle	67.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.83	14.53	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:7	32.72	2509	2.6	13.43	96	195	Off Idle	67.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.83	14.44	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:7	32.72	2509	2.6	13.43	96	195	Off Idle	66.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.8	14.33	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:7	32.72	2512	2.6	13.42	96	195	Off Idle	66.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.81	14.22	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:8	32.72	2511	2.6	13.43	96	195	Off Idle	66.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.81	14.06	0.96	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:52:8	32.72	2511	2.6	13.43	96	195	Off Idle	66.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.81	13.96	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:8	32.72	2511	2.61	13.43	96	195	Off Idle	66.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.77	13.92	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:8	32.72	2512	2.61	13.42	96	195	Off Idle	66.3	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.78	13.8	0.94	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:8	32.72	2510	2.61	13.41	96	195	Off Idle	66.3	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.78	13.74	0.94	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:8	32.72	2515	2.61	13.42	96	195	Off Idle	66.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.74	13.7	0.93	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:9	32.72	2516	2.61	13.41	96	194	Off Idle	66	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.78	13.64	0.93	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:9	32.72	2519	2.61	13.41	96	194	Off Idle	65.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.74	13.63	0.93	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:9	32.72	2522	2.61	13.44	96	194	Off Idle	65.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.73	13.61	0.93	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:52:9	32.72	2529	2.62	13.43	96	195	Off Idle	65.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.76	13.59	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:52:9	32.72	2532	2.62	13.42	96	195	Off Idle	65.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.71	13.57	0.92	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:9	32.72	2554	2.62	13.42	96	195	Off Idle	65.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.69	13.58	0.92	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:52:9	32.72	2554	2.62	13.43	96	195	Off Idle	65.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.68	13.59	0.93	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:53:0	32.72	2539	2.62	13.43	96	195	Off Idle	65.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.66	13.6	0.93	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:0	32.72	2538	2.62	13.44	96	195	Off Idle	65.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.67	13.61	0.93	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:0	32.72	2529	2.63	13.44	96	195	Off Idle	65.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.68	13.63	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:0	32.72	2541	2.63	13.44	96	195	Off Idle	65.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.69	13.66	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:0	32.72	2542	2.63	13.43	96	195	Off Idle	65.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.6	13.67	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:0	32.72	2543	2.63	13.42	96	194	Off Idle	65	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.65	13.71	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:1	32.72	2557	2.63	13.44	96	194	Off Idle	64.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.58	13.75	0.94	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:1	32.72	2551	2.63	13.43	96	194	Off Idle	64.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.58	13.76	0.94	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:1	32.72	2551	2.64	13.43	96	194	Off Idle	64.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.56	13.77	0.94	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:1	32.72	2551	2.64	13.41	96	195	Off Idle	64.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.57	13.81	0.94	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:1	32.72	2550	2.64	13.42	96	195	Off Idle	64.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.61	13.84	0.94	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:1	32.72	2550	2.64	13.41	96	195	Off Idle	64.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.59	13.88	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:1	32.72	2552	2.64	13.4	96	195	Off Idle	63.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.55	13.93	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:2	32.72	2564	2.65	13.41	96	195	Off Idle	63.7	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.54	13.97	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:2	32.72	2564	2.65	13.42	96	195	Off Idle	63.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.58	14	0.95	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:53:2	32.72	2570	2.65	13.43	96	195	Off Idle	63.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.56	14.04	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:53:2	32.72	2571	2.65	13.42	96	195	Off Idle	63.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.53	14.09	0.96	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:26:53:2	32.72	2571	2.66	13.44	96	195	Off Idle	63	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.52	14.14	0.96	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:2	32.72	2570	2.66	13.45	96	195	Off Idle	62.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.57	14.22	0.97	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:3	32.72	2568	2.66	13.44	96	195	Off Idle	62.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.49	14.28	0.97	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:3	32.72	2549	2.66	13.44	96	195	Off Idle	62.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.46	14.33	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:3	32.72	2559	2.66	13.45	96	195	Off Idle	62.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.56	14.37	0.98	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:3	32.72	2571	2.66	13.44	96	195	Off Idle	62.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.57	14.4	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:3	32.72	2569	2.66	13.44	96	195	Off Idle	62.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.54	14.46	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:53:3	32.72	2572	2.66	13.44	96	195	Off Idle	62.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.6	14.48	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:53:4	32.72	2588	2.66	13.43	96	195	Off Idle	62.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.68	14.51	0.99	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:53:4	32.72	2578	2.66	13.43	96	195	Off Idle	62.5	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.64	14.53	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:4	32.72	2579	2.66	13.43	96	195	Off Idle	62.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.69	14.55	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:4	32.72	2572	2.66	13.43	96	195	Off Idle	62.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.68	14.55	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:4	32.72	2586	2.66	13.44	96	195	Off Idle	62.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.7	14.52	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:4	32.72	2586	2.66	13.43	96	195	Off Idle	62.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.69	14.52	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:4	32.72	2605	2.65	13.41	96	195	Off Idle	62.2	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.71	14.49	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:5	32.72	2596	2.65	13.43	96	195	Off Idle	62.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.77	14.49	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:5	32.72	2600	2.65	13.43	96	195	Off Idle	61.9	0	2	132	944 Turbo	0.76	Rich	1	14.7	-2.81	14.49	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:5	32.72	2600	2.65	13.42	96	195	Off Idle	61.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-2.79	14.5	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:5	32.72	2604	2.65	13.44	96	195	Off Idle	61.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-2.83	14.51	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:5	32.72	2604	2.65	13.43	96	195	Off Idle	61	0	2	132	944 Turbo	0.73	Rich	1	14.7	-2.84	14.54	0.99	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:53:5	32.72	2606	2.65	13.42	96	195	Off Idle	60.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-2.79	14.57	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:6	32.72	2608	2.65	13.41	96	195	Off Idle	60.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.8	14.62	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:6	32.72	2599	2.65	13.43	96	195	Off Idle	60.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.76	14.66	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:53:6	32.72	2596	2.64	13.43	96	195	Off Idle	60.3	0	2	132	944 Turbo	0.68	Rich	1	14.7	-2.76	14.72	1	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:53:6	32.72	2594	2.65	13.41	96	195	Off Idle	60.3	0	2	132	944 Turbo	0.65	Rich	1	14.7	-2.74	14.77	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:53:6	32.72	2606	2.65	13.42	96	195	Off Idle	60.3	0	2	132	944 Turbo	0.62	Rich	1	14.7	-2.72	14.79	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:53:6	32.72	2612	2.65	13.43	96	195	Off Idle	60.3	0	2	132	944 Turbo	0.56	Rich	1	14.7	-2.77	14.83	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:53:6	32.72	2612	2.65	13.42	96	195	Off Idle	60	0	2	132	944 Turbo	0.5	Rich	1	14.7	-2.8	14.85	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:53:7	32.72	2620	2.65	13.42	96	195	Off Idle	59.8	0	2	132	944 Turbo	0.42	Lean	1	14.7	-2.82	14.87	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:53:7	32.72	2620	2.65	13.43	96	195	Off Idle	59.7	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.83	14.87	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:53:7	32.72	2620	2.65	13.45	96	195	Off Idle	59.7	0	2	132	944 Turbo	0.31	Lean	1	14.7	-2.84	14.84	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:53:7	32.72	2626	2.65	13.45	96	195	Off Idle	59.7	0	2	132	944 Turbo	0.26	Lean	1	14.7	-2.87	14.84	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:53:7	32.72	2626	2.65	13.45	96	195	Off Idle	59.7	0	2	132	944 Turbo	0.23	Lean	1	14.7	-2.81	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:7	32.72	2626	2.65	13.44	96	195	Off Idle	59.7	0	2	132	944 Turbo	0.16	Lean	1	14.7	-2.78	14.89	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:8	32.72	2625	2.65	13.45	96	195	Off Idle	59.7	0	2	132	944 Turbo	0.14	Lean	1	14.7	-2.84	14.91	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:8	32.72	2621	2.65	13.44	96	195	Off Idle	59.7	0	2	132	944 Turbo	0.16	Lean	1	14.7	-2.83	14.95	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:26:53:8	32.72	2625	2.65	13.44	96	195	Off Idle	59.5	0	2	132	944 Turbo	0.2	Lean	1	14.7	-2.85	14.96	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:53:8	32.72	2625	2.65	13.45	96	195	Off Idle	59.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	-2.84	14.97	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:8	32.72	2633	2.65	13.44	96	194	Off Idle	59	0	2	132	944 Turbo	0.31	Rich	1	14.7	-2.87	15	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:8	32.72	2641	2.65	13.44	96	194	Off Idle	58.9	0	2	132	944 Turbo	0.38	Rich	1	14.7	-2.89	15.04	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:9	32.72	2641	2.65	13.45	96	194	Off Idle	58.9	0	2	132	944 Turbo	0.44	Rich	1	14.7	-2.9	15.08	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:9	32.72	2643	2.65	13.43	96	195	Off Idle	58.9	0	2	132	944 Turbo	0.54	Rich	1	14.7	-2.92	15.12	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:9	32.72	2644	2.65	13.43	96	195	Off Idle	58.9	0	2	132	944 Turbo	0.61	Rich	1	14.7	-2.89	15.12	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:53:9	32.72	2644	2.65	13.42	96	195	Off Idle	58.8	0	2	132	944 Turbo	0.66	Rich	1	14.7	-2.86	15.1	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:53:9	32.72	2656	2.65	13.43	96	195	Off Idle	58.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.9	15.02	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:53:9	32.72	2646	2.65	13.41	96	195	Off Idle	58.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-2.92	14.97	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:53:9	32.72	2649	2.65	13.43	96	195	Off Idle	58.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-2.95	14.93	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:0	32.72	2649	2.65	13.43	96	195	Off Idle	58.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-2.98	14.89	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:0	32.72	2652	2.65	13.42	96	195	Off Idle	58.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-2.96	14.84	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:0	32.72	2651	2.65	13.43	96	195	Off Idle	58	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.96	14.78	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:0	32.72	2651	2.65	13.45	96	195	Off Idle	57.9	0	2	132	944 Turbo	0.68	Rich	1	14.7	-2.99	14.76	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:0	32.72	2651	2.65	13.44	96	195	Off Idle	57.7	0	2	132	944 Turbo	0.65	Rich	1	14.7	-3.01	14.72	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:0	32.72	2650	2.65	13.44	96	195	Off Idle	57.6	0	2	132	944 Turbo	0.61	Rich	1	14.7	-2.98	14.71	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:1	32.72	2660	2.65	13.43	96	195	Off Idle	57.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	-3.01	14.72	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:1	32.72	2650	2.65	13.42	96	195	Off Idle	57.3	0	2	132	944 Turbo	0.49	Rich	1	14.7	-3.06	14.73	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:54:1	32.72	2646	2.65	13.43	96	195	Off Idle	57.2	0	2	132	944 Turbo	0.43	Rich	1	14.7	-3.03	14.74	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:1	32.72	2649	2.65	13.43	96	195	Off Idle	57.1	0	2	132	944 Turbo	0.37	Rich	1	14.7	-3.01	14.76	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:1	32.72	2660	2.64	13.43	96	195	Off Idle	57	0	2	132	944 Turbo	0.31	Rich	1	14.7	-3.05	14.78	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:1	32.72	2667	2.64	13.44	96	195	Off Idle	57	0	2	132	944 Turbo	0.23	Lean	1	14.7	-3.08	14.82	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:1	32.72	2681	2.64	13.44	96	195	Off Idle	57	0	2	132	944 Turbo	0.18	Lean	1	14.7	-3.1	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:2	32.72	2682	2.64	13.44	96	195	Off Idle	57	0	2	132	944 Turbo	0.16	Lean	1	14.7	-3.08	14.9	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:2	32.72	2682	2.64	13.44	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.15	Lean	1	14.7	-3.1	14.95	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:2	32.72	2682	2.64	13.43	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.18	Lean	1	14.7	-3.1	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:2	32.72	2680	2.64	13.44	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.22	Lean	1	14.7	-3.07	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:2	32.72	2675	2.64	13.44	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.28	Lean	1	14.7	-3.11	15.03	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:2	32.72	2673	2.64	13.44	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.34	Lean	1	14.7	-3.13	15.06	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:3	32.72	2672	2.64	13.44	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.43	Lean	1	14.7	-3.15	15.11	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:3	32.72	2670	2.64	13.45	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.49	Lean	1	14.7	-3.1	15.15	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:3	32.72	2672	2.64	13.44	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.55	Rich	1	14.7	-3.17	15.16	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:3	32.72	2676	2.64	13.44	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.6	Rich	1	14.7	-3.17	15.15	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:3	32.72	2678	2.64	13.45	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.63	Rich	1	14.7	-3.18	15.11	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:3	32.72	2681	2.64	13.44	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.66	Rich	1	14.7	-3.22	15.08	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:4	32.72	2681	2.64	13.43	96	195	Off Idle	56.9	0	2	132	944 Turbo	0.66	Rich	1	14.7	-3.22	15.05	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:4	32.72	2691	2.64	13.43	96	195	Off Idle	56.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-3.21	15.02	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:4	32.72	2696	2.64	13.44	96	195	Off Idle	56.6	0	2	132	944 Turbo	0.55	Rich	1	14.7	-3.21	14.98	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:4	32.72	2692	2.64	13.45	96	195	Off Idle	56.4	0	2	132	944 Turbo	0.49	Rich	1	14.7	-3.22	14.95	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:4	32.72	2692	2.64	13.44	96	195	Off Idle	56.3	0	2	132	944 Turbo	0.43	Rich	1	14.7	-3.23	14.91	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:4	32.72	2692	2.64	13.45	96	195	Off Idle	56.1	0	2	132	944 Turbo	0.37	Rich	1	14.7	-3.23	14.85	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:4	32.72	2700	2.64	13.45	96	195	Off Idle	56.1	0	2	132	944 Turbo	0.3	Lean	1	14.7	-3.22	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:5	32.72	2701	2.64	13.45	96	195	Off Idle	56.1	0	2	132	944 Turbo	0.27	Lean	1	14.7	-3.21	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:5	32.72	2708	2.64	13.45	96	195	Off Idle	56.1	0	2	132	944 Turbo	0.19	Lean	1	14.7	-3.21	14.87	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:5	32.72	2715	2.64	13.43	96	195	Off Idle	56	0	2	132	944 Turbo	0.14	Lean	1	14.7	-3.21	14.91	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:5	32.72	2716	2.64	13.44	96	195	Off Idle	56	0	2	132	944 Turbo	0.11	Lean	1	14.7	-3.19	14.95	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:5	32.72	2716	2.64	13.43	96	195	Off Idle	55.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-3.23	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:26:54:5	32.72	2735	2.64	13.43	96	195	Off Idle	55.2	0	2	132	944 Turbo	0.16	Lean	1	14.7	-3.29	15.02	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:54:6	34.08	2722	2.64	13.41	96	195	Off Idle	55.1	0	2	132	944 Turbo	0.21	Lean	1	14.7	-3.25	15.09	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:26:54:6	34.08	2706	2.64	13.41	96	195	Off Idle	54.9	0	2	132	944 Turbo	0.28	Lean	1	14.7	-3.22	15.13	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:6	34.08	2708	2.64	13.42	96	195	Off Idle	54.7	0	2	132	944 Turbo	0.34	Lean	1	14.7	-3.27	15.16	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:6	34.08	2711	2.64	13.43	96	195	Off Idle	54.7	0	2	132	944 Turbo	0.44	Rich	1	14.7	-3.27	15.17	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:6	32.72	2711	2.64	13.42	96	195	Off Idle	54.6	0	2	132	944 Turbo	0.47	Rich	1	14.7	-3.2	15.2	1.04	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:6	32.72	2718	2.64	13.43	96	195	Off Idle	54.5	0	2	132	944 Turbo	0.54	Rich	1	14.7	-3.3	15.21	1.04	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:6	32.72	2721	2.64	13.44	96	195	Off Idle	54.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-3.31	15.15	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:54:7	32.72	2724	2.64	13.43	96	195	Off Idle	54.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-3.34	15.11	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:54:7	32.72	2724	2.64	13.42	96	195	Off Idle	54.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	-3.34	15.09	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:54:7	32.72	2722	2.64	13.42	96	195	Off Idle	54	0	2	132	944 Turbo	0.69	Rich	1	14.7	-3.33	15.06	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:54:7	32.72	2722	2.64	13.43	96	195	Off Idle	54	0	2	132	944 Turbo	0.64	Rich	1	14.7	-3.34	15	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:54:7	32.72	2730	2.64	13.42	96	195	Off Idle	53.9	0	2	132	944 Turbo	0.59	Rich	1	14.7	-3.38	14.98	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:54:7	32.72	2730	2.64	13.43	96	195	Off Idle	53.9	0	2	132	944 Turbo	0.53	Rich	1	14.7	-3.36	14.97	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:8	32.72	2734	2.63	13.44	96	195	Off Idle	53.9	0	2	132	944 Turbo	0.47	Lean	1	14.7	-3.44	14.91	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:26:54:8	32.72	2736	2.63	13.44	96	195	Off Idle	53.7	0	2	132	944 Turbo	0.4	Lean	1	14.7	-3.52	14.85	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:8	32.72	2734	2.63	13.45	96	195	Off Idle	53.6	0	2	132	944 Turbo	0.34	Lean	1	14.7	-3.53	14.86	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:8	34.08	2736	2.62	13.44	96	194	Off Idle	53.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-3.64	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:8	34.08	2732	2.62	13.45	96	194	Off Idle	53.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-3.68	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:8	34.08	2732	2.62	13.45	96	194	Off Idle	53.3	0	2	132	944 Turbo	0.13	Lean	1	14.7	-3.73	14.91	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:9	34.08	2733	2.61	13.44	96	195	Off Idle	53.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.74	14.94	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:9	34.08	2732	2.61	13.43	96	195	Off Idle	53	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.75	15	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:9	34.08	2736	2.61	13.43	96	195	Off Idle	53	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.79	15.02	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:9	34.08	2736	2.6	13.43	96	195	Off Idle	53	0	2	132	944 Turbo	0.11	Lean	1	14.7	-3.81	15.06	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:9	34.08	2738	2.6	13.42	96	195	Off Idle	52.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-3.83	15.12	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:26:54:9	34.08	2768	2.6	13.41	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-3.85	15.15	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:54:9	34.08	2748	2.59	13.42	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.15	Lean	1	14.7	-3.89	15.16	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:55:0	34.08	2746	2.58	13.41	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.16	Lean	1	14.7	-3.94	15.16	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:26:55:0	34.08	2744	2.58	13.42	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.18	Lean	1	14.7	-4.04	15.14	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:55:0	34.08	2743	2.57	13.41	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.2	Lean	1	14.7	-4.06	15.13	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:55:0	34.08	2744	2.57	13.41	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.27	Lean	1	14.7	-4.14	15.09	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:55:0	34.08	2744	2.56	13.43	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.29	Lean	1	14.7	-4.21	15.07	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:26:55:0	34.08	2742	2.55	13.42	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.37	Lean	1	14.7	-4.25	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:55:1	34.08	2751	2.55	13.42	96	195	Off Idle	52.8	0	2	132	944 Turbo	0.41	Lean	1	14.7	-4.3	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:55:1	34.08	2754	2.54	13.43	96	194	Off Idle	52.8	0	2	132	944 Turbo	0.43	Lean	1	14.7	-4.3	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:55:1	34.08	2764	2.54	13.43	96	194	Off Idle	52.8	0	2	132	944 Turbo	0.51	Rich	1	14.7	-4.38	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:55:1	34.08	2764	2.53	13.42	96	194	Off Idle	52.7	0	2	132	944 Turbo	0.55	Rich	1	14.7	-4.45	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:55:1	34.08	2758	2.53	13.42	96	194	Off Idle	52.5	0	2	132	944 Turbo	0.57	Rich	1	14.7	-4.46	15.05	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:55:1	34.08	2747	2.52	13.42	96	194	Off Idle	52.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-4.47	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:55:1	34.08	2759	2.52	13.42	96	194	Off Idle	52.2	0	2	132	944 Turbo	0.53	Rich	1	14.7	-4.54	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:55:2	34.08	2760	2.51	13.42	96	195	Off Idle	52.2	0	2	132	944 Turbo	0.48	Rich	1	14.7	-4.55	15.01	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:2	34.08	2766	2.51	13.41	96	195	Off Idle	52.2	0	2	132	944 Turbo	0.4	Rich	1	14.7	-4.58	15	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:2	34.08	2774	2.5	13.44	96	195	Off Idle	52.2	0	2	132	944 Turbo	0.34	Rich	1	14.7	-4.61	14.96	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:55:2	34.08	2779	2.5	13.44	96	195	Off Idle	52	0	2	132	944 Turbo	0.29	Rich	1	14.7	-4.66	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:2	34.08	2780	2.5	13.43	96	195	Off Idle	51.9	0	2	132	944 Turbo	0.23	Lean	1	14.7	-4.69	14.9	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:55:2	34.08	2780	2.49	13.41	96	195	Off Idle	51.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.68	14.9	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:55:3	34.08	2777	2.49	13.42	96	195	Off Idle	51.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.73	14.95	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:55:3	34.08	2767	2.49	13.42	96	194	Off Idle	51.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.77	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:3	34.08	2764	2.49	13.41	96	194	Off Idle	51.2	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4.77	15.1	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:3	34.08	2759	2.48	13.43	96	194	Off Idle	50.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.79	15.19	1.03	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:3	34.08	2756	2.48	13.43	96	195	Off Idle	50.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.84	15.26	1.04	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:26:55:3	34.08	2755	2.48	13.43	96	195	Off Idle	51	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.89	15.34	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:55:4	34.08	2755	2.47	13.43	96	195	Off Idle	51.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.98	15.42	1.05	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:26:55:4	34.08	2766	2.46	13.44	96	194	Off Idle	51.1	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.02	15.49	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:4	34.08	2769	2.45	13.44	96	194	Off Idle	50.9	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.13	15.54	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:4	34.08	2764	2.45	13.45	96	194	Off Idle	50.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.14	15.54	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:4	34.08	2764	2.44	13.45	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.08	Lean	1	14.7	-5.24	15.54	1.06	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:4	34.08	2764	2.44	13.44	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.28	15.5	1.06	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:4	34.08	2763	2.43	13.44	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.09	Lean	1	14.7	-5.34	15.46	1.05	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:5	34.08	2763	2.43	13.43	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.38	15.41	1.05	3.4	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:5	34.08	2786	2.42	13.44	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-5.45	15.36	1.05	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:5	34.08	2765	2.41	13.44	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-5.44	15.32	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:5	34.08	2766	2.41	13.44	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.49	15.28	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:5	34.08	2776	2.4	13.44	96	194	Off Idle	50.8	0	2	132	944 Turbo	0.09	Lean	1	14.7	-5.5	15.23	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:5	34.08	2757	2.39	13.45	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.09	Lean	1	14.7	-5.56	15.2	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:6	34.08	2770	2.38	13.43	96	194	Off Idle	50.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-5.56	15.16	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:55:6	34.08	2784	2.38	13.45	96	194	Off Idle	50.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.59	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:6	34.08	2787	2.37	13.43	96	195	Off Idle	50.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.6	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:6	34.08	2812	2.37	13.44	96	195	Off Idle	50.1	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.63	15.13	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:55:6	34.08	2812	2.37	13.43	96	195	Off Idle	50	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.62	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:6	34.08	2788	2.36	13.43	96	195	Off Idle	49.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.65	15.16	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:6	34.08	2788	2.36	13.43	96	195	Off Idle	49.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.64	15.17	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:7	34.08	2788	2.36	13.44	96	195	Off Idle	49.7	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.67	15.2	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:7	34.08	2786	2.36	13.45	96	195	Off Idle	49.6	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.64	15.22	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:7	34.08	2780	2.36	13.45	96	195	Off Idle	49.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-5.63	15.24	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:7	34.08	2782	2.36	13.45	96	195	Off Idle	49.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.67	15.26	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:7	34.08	2782	2.36	13.44	96	195	Off Idle	49.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.68	15.28	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:7	34.08	2783	2.36	13.45	96	195	Off Idle	49.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.66	15.3	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:8	34.08	2784	2.36	13.44	96	194	Off Idle	49.3	0	2	132	944 Turbo	0.08	Lean	1	14.7	-5.73	15.31	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:8	35.45	2796	2.36	13.43	96	194	Off Idle	49.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.77	15.3	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:8	35.45	2790	2.35	13.43	96	194	Off Idle	49.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-5.79	15.29	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:26:55:8	35.45	2785	2.35	13.43	96	195	Off Idle	49.3	0	2	132	944 Turbo	0.12	Lean	1	14.7	-5.81	15.28	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:55:8	35.45	2786	2.35	13.43	96	195	Off Idle	49.3	0	2	132	944 Turbo	0.13	Lean	1	14.7	-5.84	15.28	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:55:8	35.45	2783	2.35	13.43	96	195	Off Idle	49.6	0	2	132	944 Turbo	0.2	Lean	1	14.7	-5.91	15.26	1.04	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:26:55:9	34.08	2765	2.34	13.44	96	194	Off Idle	49.7	0	2	132	944 Turbo	0.25	Lean	1	14.7	-5.96	15.24	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:26:55:9	34.08	2783	2.34	13.44	96	194	Off Idle	49.7	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.05	15.21	1.04	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:55:9	34.08	2783	2.33	13.44	96	194	Off Idle	49.9	0	2	132	944 Turbo	0.37	Rich	1	14.7	-6.17	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:55:9	34.08	2777	2.32	13.45	96	194	Off Idle	50	0	2	132	944 Turbo	0.43	Rich	1	14.7	-6.28	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:26:55:9	34.08	2776	2.31	13.44	96	194	Off Idle	50.1	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.46	15.12	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:55:9	34.08	2796	2.3	13.45	96	194	Off Idle	50.1	0	2	132	944 Turbo	0.57	Rich	1	14.7	-6.56	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:55:9	35.45	2790	2.29	13.45	96	195	Off Idle	50.1	0	2	132	944 Turbo	0.6	Rich	1	14.7	-6.7	15.14	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:56:0	35.45	2784	2.28	13.43	96	195	Off Idle	50.1	0	2	132	944 Turbo	0.64	Rich	1	14.7	-6.82	15.12	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:26:56:0	35.45	2788	2.26	13.44	96	195	Off Idle	50.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.87	15.1	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:26:56:0	35.45	2793	2.24	13.45	96	194	Off Idle	50.1	0	2	132	944 Turbo	0.66	Rich	1	14.7	-7.02	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:56:0	35.45	2795	2.21	13.44	96	194	Off Idle	50.1	0	2	132	944 Turbo	0.62	Rich	1	14.7	-7.3	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:26:56:0	35.45	2795	2.2	13.44	96	194	Off Idle	50.1	0	2	132	944 Turbo	0.6	Lean	1	14.7	-7.43	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:26:56:0	35.45	2797	2.16	13.44	96	195	Off Idle	50	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.77	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:26:56:1	35.45	2787	2.13	13.43	96	195	Off Idle	49.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.98	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:56:1	35.45	2782	2.11	13.43	96	194	Off Idle	49.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.2	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:26:56:1	35.45	2782	2.06	13.43	96	194	Off Idle	49.8	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.41	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:56:1	35.45	2766	2.03	13.43	96	194	Off Idle	49.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.66	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:56:1	35.45	2761	2.01	13.43	96	194	Full Load	49.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.75	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:56:1	35.45	2731	1.95	13.44	96	194	Idle	49.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.04	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:56:1	35.45	2740	1.91	13.45	96	194	Idle	49.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.18	14.86	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:2	35.45	2749	1.88	13.44	96	194	Idle	49.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.33	14.86	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:56:2	35.45	2740	1.85	13.45	96	194	Idle	50	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.47	14.87	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:56:2	32.72	2715	1.82	13.44	96	194	Idle	50.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.56	14.89	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:56:2	32.72	2680	1.78	13.45	96	194	Idle	50.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.62	14.91	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:2	27.27	2672	1.75	13.45	96	194	Idle	50.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.7	14.92	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:2	21.81	2669	1.71	13.45	96	194	Idle	51.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.76	14.94	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:3	19.09	2680	1.68	13.45	96	194	Idle	51.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.81	15.01	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:3	19.09	2716	1.67	13.45	96	194	Idle	51.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.87	15.04	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:3	19.09	2716	1.63	13.46	96	194	Idle	52.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.94	15.06	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:3	19.09	2752	1.6	13.46	96	194	Idle	52.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-10.05	15.04	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:3	19.09	2796	1.58	13.45	96	194	Idle	52.6	0	2	132	944 Turbo	0.27	Lean	1	14.6	-10.1	15.02	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:3	19.09	2796	1.58	13.44	96	194	Idle	52.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.13	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:4	19.09	2807	1.56	13.45	96	194	Idle	52.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.19	14.97	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:4	19.09	2812	1.55	13.45	96	194	Idle	52.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.19	14.95	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:4	19.09	2794	1.54	13.44	96	194	Idle	52.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.2	14.93	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:4	19.09	2788	1.53	13.44	96	194	Idle	52.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.19	14.89	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:4	19.09	2765	1.53	13.44	96	194	Idle	52.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.17	14.83	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:4	19.09	2748	1.53	13.45	96	194	Idle	52	0	2	132	944 Turbo	0.06	Lean	1	14.7	-10.12	14.8	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:4	19.09	2686	1.53	13.45	96	194	Idle	51.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.06	14.81	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:5	19.09	2686	1.53	13.45	96	194	Idle	51.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.06	14.82	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:5	19.09	2712	1.53	13.45	96	194	Idle	51.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.02	14.85	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:5	19.09	2706	1.53	13.46	96	194	Idle	51.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10	14.87	1.01	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:5	19.09	2706	1.53	13.44	96	194	Idle	50.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.98	14.9	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:56:5	19.09	2712	1.53	13.45	96	194	Idle	50.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.96	14.94	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:5	19.09	2745	1.53	13.45	96	194	Idle	50.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.91	15	1.02	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:6	19.09	2741	1.53	13.45	96	194	Idle	49.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.89	15.13	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:6	19.09	2745	1.54	13.44	96	194	Idle	49.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.87	15.22	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:6	19.09	2758	1.54	13.45	96	194	Idle	49.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	15.32	1.04	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:6	19.09	2761	1.55	13.44	96	194	Idle	49.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	15.41	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:6	19.09	2761	1.55	13.43	96	194	Idle	49.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	15.52	1.06	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:6	19.09	2760	1.56	13.45	96	194	Idle	49.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	15.65	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:6	19.09	2758	1.56	13.43	96	194	Idle	50.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	15.79	1.08	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:7	19.09	2756	1.57	13.44	96	194	Idle	50.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	15.97	1.09	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:7	19.09	2746	1.57	13.45	96	194	Idle	50.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	16.21	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:7	19.09	2733	1.57	13.44	96	194	Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	16.74	1.14	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:7	19.09	2733	1.57	13.44	96	194	Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	17.19	1.17	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:7	19.09	2724	1.57	13.45	96	194	Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	17.63	1.2	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:7	19.09	2717	1.57	13.44	96	194	Idle	50.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	18.07	1.23	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:8	19.09	2722	1.56	13.45	96	195	Idle	51.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	18.49	1.26	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:8	19.09	2722	1.56	13.45	96	195	Full Load	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.88	18.9	1.29	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:8	19.09	2726	1.56	13.44	96	195	Off Idle	51.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	19.28	1.31	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:8	19.09	2592	1.57	13.43	96	194	Off Idle	52.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	19.78	1.35	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:8	10.9	2592	1.57	13.45	96	194	Off Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	19.92	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:56:8	13.63	2747	1.57	13.45	96	194	Off Idle	52.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:56:9	13.63	2742	1.58	13.45	96	194	Off Idle	52.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:9	16.36	2742	1.59	13.45	96	194	Off Idle	52.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.75	20.24	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:56:9	19.09	2723	1.59	13.45	96	194	Off Idle	52.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:56:9	19.09	2729	1.59	13.45	96	194	Off Idle	53.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:56:9	21.81	2726	1.6	13.44	96	194	Off Idle	53.2	0	2	132	944 Turbo	0.01	Lean	1	14.7	-9.62	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:56:9	24.54	2719	1.6	13.45	96	194	Off Idle	53.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:56:9	27.27	2719	1.61	13.45	96	194	Off Idle	53.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:57:0	27.27	2729	1.62	13.44	96	194	Off Idle	53.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:57:0	29.99	2734	1.63	13.46	96	194	Off Idle	54	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:57:0	32.72	2754	1.63	13.47	96	194	Off Idle	54	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:0	35.45	2778	1.64	13.46	96	194	Off Idle	54	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:0	35.45	2775	1.64	13.45	96	194	Off Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:0	36.81	2775	1.65	13.46	96	194	Off Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:57:1	36.81	2773	1.66	13.45	96	194	Off Idle	54	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:57:1	36.81	2772	1.67	13.45	96	194	Off Idle	53.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:57:1	36.81	2772	1.68	13.45	96	194	Off Idle	53.4	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.76	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:1	36.81	2766	1.69	13.45	96	194	Off Idle	52.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.73	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:1	36.81	2761	1.69	13.45	96	194	Off Idle	52.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:1	36.81	2738	1.69	13.44	96	194	Off Idle	52.7	0	2	132	944 Turbo	0.04	Lean	1	14.7	-9.74	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:1	36.81	2728	1.7	13.44	96	194	Off Idle	52.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.71	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:2	36.81	2716	1.7	13.44	96	194	Off Idle	52.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:2	36.81	2716	1.7	13.44	96	194	Off Idle	52.1	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.67	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:2	36.81	2705	1.7	13.42	96	194	Off Idle	51.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:2	36.81	2694	1.71	13.44	96	194	Off Idle	52.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.65	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:2	36.81	2691	1.71	13.44	96	194	Off Idle	52.2	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.65	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:2	36.81	2690	1.71	13.43	96	194	Off Idle	52.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.67	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:3	36.81	2684	1.7	13.43	96	194	Off Idle	52.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.7	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:3	36.81	2683	1.7	13.45	96	194	Off Idle	53.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.71	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:3	36.81	2676	1.7	13.43	96	194	Off Idle	53.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.75	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:3	36.81	2675	1.7	13.43	96	194	Off Idle	54	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.76	20.2	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:3	36.81	2676	1.7	13.45	96	194	Off Idle	54.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.8	20.1	1.37	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:26:57:3	36.81	2667	1.68	13.45	96	194	Full Load	54.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.86	19.94	1.36	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:26:57:4	36.81	2664	1.67	13.44	96	195	Idle	55.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.9	19.73	1.34	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:4	36.81	2664	1.65	13.44	96	195	Idle	55.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.96	19.49	1.33	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:4	34.08	2630	1.64	13.45	96	195	Idle	55.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.06	19.22	1.31	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:57:4	34.08	2632	1.62	13.45	96	194	Idle	55.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.08	18.93	1.29	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:57:4	28.63	2635	1.61	13.43	96	194	Idle	55.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.17	18.43	1.26	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:57:4	23.18	2632	1.6	13.45	96	194	Idle	55.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.22	17.96	1.22	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:4	23.18	2657	1.59	13.45	96	195	Idle	55.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.25	17.62	1.2	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:5	19.09	2670	1.58	13.44	96	195	Idle	55	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.27	17.32	1.18	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:5	19.09	2686	1.57	13.45	96	195	Idle	55	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.29	17.18	1.17	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:5	19.09	2697	1.56	13.46	96	194	Idle	54.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.29	16.85	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:5	19.09	2700	1.55	13.44	96	194	Idle	53.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.31	16.75	1.14	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:5	19.09	2705	1.54	13.44	96	194	Idle	53.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.29	16.51	1.12	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:5	19.09	2705	1.53	13.46	96	195	Idle	53.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.29	16.35	1.11	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:6	19.09	2695	1.52	13.45	96	195	Idle	53.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.29	16.22	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:6	19.09	2688	1.52	13.45	96	195	Idle	53.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.29	16.09	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:6	19.09	2685	1.5	13.45	96	194	Idle	53.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.29	16.1	1.1	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:6	19.09	2678	1.5	13.45	96	194	Idle	53.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.29	15.95	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:6	19.09	2669	1.49	13.44	96	194	Idle	53.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.24	15.86	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:6	19.09	2665	1.5	13.44	96	194	Idle	53.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.24	15.77	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:6	19.09	2665	1.5	13.44	96	194	Idle	53.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.23	15.7	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:7	19.09	2662	1.5	13.44	96	194	Idle	54	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.2	15.6	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:7	19.09	2666	1.5	13.44	96	194	Idle	54.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.19	15.57	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:7	19.09	2669	1.51	13.45	96	194	Idle	54.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.18	15.53	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:7	19.09	2669	1.51	13.44	96	194	Idle	54.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.16	15.49	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:7	19.09	2674	1.5	13.46	96	194	Idle	54.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.15	15.46	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:7	19.09	2679	1.51	13.45	96	194	Idle	54.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.12	15.43	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:8	19.09	2679	1.51	13.45	96	194	Idle	54.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.09	15.39	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:8	19.09	2680	1.5	13.46	96	194	Idle	54.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.1	15.39	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:8	19.09	2680	1.5	13.46	96	194	Idle	54.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.08	15.42	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:8	19.09	2677	1.5	13.45	96	194	Idle	54.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.08	15.44	1.05	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:8	19.09	2677	1.5	13.45	96	194	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	15.48	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:8	19.09	2672	1.5	13.46	96	194	Idle	54.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	15.53	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:9	19.09	2667	1.5	13.46	96	194	Idle	54.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	15.61	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:9	19.09	2667	1.49	13.46	96	194	Idle	55.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	15.74	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:9	19.09	2661	1.49	13.46	96	194	Idle	55.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	15.94	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:9	19.09	2636	1.49	13.45	96	194	Idle	55.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	16.25	1.11	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:9	19.09	2636	1.49	13.45	96	194	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	16.89	1.15	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:9	19.09	2654	1.49	13.45	96	194	Idle	55.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	17.33	1.18	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:57:9	19.09	2650	1.49	13.44	96	194	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	17.8	1.21	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:0	19.09	2650	1.49	13.45	96	194	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	18.25	1.24	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:0	19.09	2650	1.49	13.45	96	194	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	18.68	1.27	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:0	19.09	2650	1.49	13.44	96	194	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	19.11	1.3	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:0	19.09	2610	1.49	13.44	96	194	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	19.49	1.33	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:0	19.09	2610	1.48	13.44	96	194	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	19.82	1.35	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:0	19.09	2648	1.48	13.44	96	194	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.06	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:1	19.09	2647	1.48	13.45	96	194	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.18	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:1	19.09	2647	1.48	13.45	96	194	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:1	19.09	2645	1.48	13.45	96	194	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:1	19.09	2642	1.48	13.45	96	194	Idle	56.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:1	19.09	2639	1.48	13.45	96	194	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:1	19.09	2639	1.48	13.45	96	194	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:1	19.09	2636	1.47	13.44	96	194	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:2	19.09	2634	1.47	13.45	96	194	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:2	19.09	2634	1.47	13.46	96	194	Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:2	19.09	2633	1.46	13.45	96	194	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:2	19.09	2644	1.46	13.46	96	194	Idle	57.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:2	19.09	2644	1.46	13.46	96	194	Idle	57.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:2	19.09	2633	1.46	13.46	96	194	Idle	57.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:3	19.09	2632	1.46	13.45	96	194	Idle	57.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:3	19.09	2629	1.45	13.45	96	194	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:3	19.09	2630	1.45	13.44	96	194	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:3	19.09	2630	1.45	13.44	96	194	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:3	19.09	2620	1.45	13.46	96	194	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:58:3	19.09	2627	1.45	13.45	96	194	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:4	19.09	2627	1.45	13.46	96	194	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:4	19.09	2628	1.44	13.45	96	194	Idle	57.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:4	19.09	2626	1.44	13.44	96	194	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:4	19.09	2624	1.44	13.44	96	194	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:4	19.09	2623	1.44	13.44	96	194	Idle	57.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:4	19.09	2622	1.44	13.44	96	194	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.2	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:4	19.09	2620	1.44	13.46	96	194	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:5	19.09	2620	1.44	13.46	96	194	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:5	19.09	2594	1.44	13.44	96	194	Idle	58.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:5	19.09	2611	1.44	13.44	96	194	Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:5	19.09	2610	1.44	13.45	96	194	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:5	19.09	2618	1.44	13.44	96	194	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:5	19.09	2604	1.44	13.45	96	194	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:6	19.09	2604	1.43	13.45	96	194	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.27	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:6	19.09	2603	1.43	13.44	96	194	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:6	19.09	2599	1.43	13.43	96	194	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:6	19.09	2599	1.43	13.44	96	194	Idle	58.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:6	19.09	2598	1.43	13.44	96	194	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.28	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:6	19.09	2625	1.43	13.43	96	194	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:6	19.09	2601	1.43	13.45	96	194	Idle	58.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:7	19.09	2601	1.43	13.45	96	195	Idle	58.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.26	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:7	19.09	2601	1.43	13.44	96	195	Idle	58.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:7	19.09	2599	1.43	13.44	96	195	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:7	19.09	2599	1.43	13.45	96	194	Idle	58.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:7	19.09	2598	1.43	13.44	96	194	Idle	58.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:7	19.09	2596	1.43	13.43	96	194	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:8	19.09	2595	1.43	13.45	96	194	Idle	59.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:8	19.09	2595	1.43	13.45	96	194	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:8	19.09	2594	1.43	13.45	96	194	Idle	59.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:8	19.09	2594	1.42	13.45	96	194	Idle	59.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:8	19.09	2603	1.42	13.45	96	194	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:8	19.09	2593	1.42	13.45	96	194	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:9	19.09	2593	1.42	13.46	96	194	Idle	59.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:9	19.09	2592	1.42	13.45	96	194	Idle	59.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:9	19.09	2592	1.42	13.45	96	194	Idle	60.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:9	19.09	2592	1.42	13.45	96	194	Idle	60.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:9	19.09	2590	1.42	13.45	96	194	Idle	60.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:9	19.09	2590	1.41	13.44	96	194	Idle	60.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:58:9	19.09	2586	1.41	13.45	96	194	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:0	19.09	2586	1.41	13.44	96	194	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:0	19.09	2582	1.41	13.44	96	194	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:0	19.09	2577	1.41	13.44	96	194	Idle	60.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:0	19.09	2577	1.41	13.44	96	194	Idle	60.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:0	19.09	2573	1.41	13.45	96	194	Idle	60.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:0	19.09	2569	1.4	13.44	96	194	Idle	60.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:1	19.09	2569	1.4	13.45	96	194	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:1	19.09	2566	1.4	13.44	96	194	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:1	19.09	2543	1.4	13.43	96	194	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:1	19.09	2543	1.4	13.43	96	194	Idle	61.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:1	19.09	2563	1.4	13.45	96	194	Idle	61.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:1	19.09	2562	1.4	13.44	96	194	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:1	19.09	2563	1.4	13.44	96	194	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:2	19.09	2564	1.39	13.46	96	194	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:2	19.09	2576	1.39	13.45	96	194	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:2	19.09	2568	1.39	13.45	96	194	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:2	19.09	2558	1.39	13.44	96	194	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:2	19.09	2567	1.39	13.45	96	194	Idle	61.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:26:59:2	19.09	2562	1.39	13.45	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:3	19.09	2562	1.39	13.44	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:3	19.09	2558	1.39	13.44	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:3	19.09	2554	1.39	13.46	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:3	19.09	2554	1.38	13.44	96	194	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:3	19.09	2548	1.38	13.44	96	194	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:3	19.09	2543	1.38	13.44	96	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:4	19.09	2543	1.38	13.43	96	194	Idle	61.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:4	19.09	2540	1.38	13.43	96	194	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:4	19.09	2541	1.38	13.44	96	194	Idle	62	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:4	19.09	2542	1.38	13.45	96	194	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:4	19.09	2542	1.38	13.45	96	194	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:4	19.09	2544	1.38	13.47	96	194	Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:4	19.09	2546	1.38	13.45	96	194	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:5	19.09	2546	1.37	13.46	96	194	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:5	19.09	2543	1.37	13.44	96	194	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:5	19.09	2542	1.37	13.44	96	194	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:5	19.09	2539	1.37	13.45	96	194	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:5	19.09	2539	1.37	13.44	96	194	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:5	19.09	2532	1.37	13.44	96	194	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:6	19.09	2529	1.37	13.44	96	194	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:6	19.09	2528	1.37	13.44	96	194	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:6	19.09	2523	1.36	13.46	96	194	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:6	19.09	2522	1.36	13.45	96	194	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:6	19.09	2521	1.36	13.43	96	194	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:6	19.09	2519	1.36	13.44	96	194	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:6	19.09	2508	1.36	13.45	96	194	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:7	19.09	2519	1.36	13.44	96	194	Idle	63.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:7	19.09	2519	1.36	13.44	96	194	Idle	63.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.34	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:7	19.09	2521	1.36	13.46	96	194	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:7	19.09	2521	1.36	13.44	96	194	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:7	19.09	2524	1.36	13.44	96	194	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:7	19.09	2527	1.36	13.44	96	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:8	19.09	2527	1.36	13.44	96	194	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:8	19.09	2527	1.35	13.44	96	194	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:8	19.09	2527	1.35	13.44	96	194	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:8	19.09	2538	1.35	13.44	96	194	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:8	19.09	2515	1.35	13.45	96	194	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:8	19.09	2514	1.35	13.45	96	194	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:9	19.09	2508	1.35	13.46	96	194	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:9	19.09	2504	1.35	13.45	96	194	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:9	19.09	2483	1.34	13.45	96	194	Idle	64.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:9	19.09	2492	1.34	13.45	96	194	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:9	19.09	2500	1.34	13.45	96	194	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:9	19.09	2499	1.34	13.46	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:26:59:9	19.09	2501	1.34	13.46	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:0	19.09	2501	1.34	13.46	96	194	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:0	19.09	2502	1.34	13.47	96	194	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:0	19.09	2502	1.33	13.46	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:0	19.09	2502	1.33	13.46	96	194	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:0	19.09	2504	1.33	13.46	96	194	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:0	19.09	2504	1.33	13.45	96	194	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:1	19.09	2501	1.32	13.45	96	194	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:1	19.09	2501	1.32	13.44	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:1	19.09	2497	1.32	13.45	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:1	19.09	2492	1.32	13.45	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:1	19.09	2487	1.32	13.44	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:1	19.09	2487	1.32	13.44	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:00:1	19.09	2484	1.32	13.44	96	194	Idle	65.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:2	19.09	2481	1.32	13.44	96	194	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:2	19.09	2480	1.32	13.44	96	194	Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:2	19.09	2478	1.32	13.44	96	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:2	19.09	2477	1.32	13.44	96	194	Idle	65.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:2	19.09	2468	1.32	13.45	96	194	Idle	65.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:2	19.09	2475	1.32	13.45	96	194	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:3	19.09	2495	1.32	13.45	96	194	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:3	19.09	2484	1.32	13.45	96	194	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:3	19.09	2475	1.32	13.47	96	194	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:3	19.09	2475	1.32	13.46	96	194	Idle	65.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:3	19.09	2473	1.32	13.45	96	194	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:3	19.09	2472	1.32	13.46	96	194	Idle	66	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:4	19.09	2470	1.32	13.44	96	194	Idle	66.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:4	19.09	2469	1.32	13.45	96	194	Idle	66.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:4	19.09	2469	1.32	13.45	96	194	Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:4	19.09	2469	1.31	13.45	96	194	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:4	19.09	2469	1.31	13.44	96	194	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:4	19.09	2469	1.31	13.45	96	194	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:4	19.09	2468	1.31	13.46	96	194	Idle	66.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:5	19.09	2465	1.31	13.46	96	194	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:5	19.09	2466	1.31	13.46	96	194	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:5	19.09	2465	1.31	13.45	96	194	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:5	19.09	2445	1.31	13.45	96	194	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:5	19.09	2462	1.31	13.46	96	194	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:5	19.09	2462	1.3	13.45	96	194	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:6	19.09	2470	1.3	13.45	96	194	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:6	19.09	2458	1.3	13.45	96	194	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:6	19.09	2458	1.3	13.45	96	194	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:6	19.09	2457	1.3	13.44	96	194	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:6	19.09	2436	1.29	13.45	96	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:6	19.09	2436	1.29	13.44	96	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:6	19.09	2453	1.29	13.45	96	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:7	19.09	2452	1.29	13.43	96	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:7	19.09	2450	1.28	13.42	96	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:7	19.09	2469	1.28	13.42	96	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:7	17.72	2428	1.28	13.43	96	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:7	17.72	2446	1.28	13.43	96	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:7	19.09	2446	1.27	13.44	96	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:8	19.09	2444	1.27	13.43	96	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:8	19.09	2424	1.27	13.45	96	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:8	17.72	2432	1.27	13.44	96	194	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:8	17.72	2448	1.27	13.46	96	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:8	17.72	2438	1.26	13.44	96	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:8	17.72	2429	1.26	13.45	96	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.2	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:9	17.72	2437	1.26	13.44	96	194	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:9	17.72	2434	1.26	13.44	96	194	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:9	17.72	2434	1.26	13.43	96	194	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:9	17.72	2424	1.26	13.44	96	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:9	17.72	2451	1.25	13.44	96	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:9	17.72	2430	1.25	13.44	96	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:00:9	17.72	2430	1.25	13.44	96	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:0	17.72	2418	1.25	13.46	96	194	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:0	17.72	2424	1.25	13.45	96	194	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:0	17.72	2424	1.25	13.45	96	194	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:0	17.72	2421	1.25	13.44	96	194	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:0	17.72	2420	1.24	13.45	96	194	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:0	17.72	2420	1.24	13.44	96	194	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:01:1	17.72	2418	1.24	13.45	96	194	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:1	17.72	2419	1.23	13.44	96	194	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:1	17.72	2418	1.23	13.45	96	194	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:1	17.72	2418	1.23	13.44	96	194	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:1	17.72	2417	1.23	13.45	96	194	Idle	69.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:1	17.72	2416	1.23	13.45	96	194	Idle	69.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:1	17.72	2416	1.23	13.44	96	194	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:2	17.72	2413	1.22	13.44	96	194	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:2	17.72	2413	1.22	13.44	96	194	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:2	17.72	2411	1.22	13.43	96	194	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:2	17.72	2408	1.22	13.44	96	194	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:2	17.72	2409	1.22	13.45	96	194	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:2	17.72	2408	1.22	13.43	96	194	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:3	17.72	2406	1.22	13.44	96	194	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:3	17.72	2402	1.21	13.45	96	194	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:3	17.72	2403	1.21	13.44	96	194	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:3	17.72	2403	1.21	13.43	96	194	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:3	17.72	2404	1.21	13.45	96	194	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:3	17.72	2405	1.21	13.45	96	194	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:4	17.72	2408	1.21	13.46	96	194	Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:4	17.72	2406	1.21	13.45	96	194	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:4	17.72	2402	1.21	13.45	96	194	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:4	17.72	2402	1.2	13.45	96	194	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:4	17.72	2400	1.2	13.44	96	194	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:4	17.72	2398	1.2	13.45	96	194	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:4	17.72	2395	1.2	13.44	96	194	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:5	17.72	2394	1.2	13.44	96	194	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:5	17.72	2389	1.2	13.47	96	194	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:5	17.72	2389	1.2	13.47	96	194	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:5	17.72	2388	1.19	13.48	96	194	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:5	17.72	2386	1.19	13.46	96	194	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:6	17.72	2386	1.19	13.46	96	194	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:6	17.72	2386	1.19	13.47	96	194	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:6	17.72	2385	1.19	13.46	96	194	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:6	17.72	2384	1.19	13.45	96	194	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:6	17.72	2366	1.19	13.45	96	194	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:6	17.72	2366	1.19	13.45	96	194	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:6	17.72	2382	1.19	13.45	96	194	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:6	17.72	2389	1.19	13.45	96	194	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:7	17.72	2378	1.19	13.44	96	194	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:7	17.72	2377	1.19	13.44	96	194	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:7	17.72	2375	1.19	13.45	96	194	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:7	17.72	2371	1.19	13.44	96	194	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:7	17.72	2371	1.18	13.45	96	194	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:7	17.72	2368	1.18	13.45	96	194	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:8	17.72	2366	1.18	13.45	96	194	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:8	17.72	2366	1.18	13.44	96	194	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:8	17.72	2365	1.18	13.45	96	194	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:8	17.72	2364	1.18	13.44	96	194	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:8	17.72	2365	1.18	13.44	96	194	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:8	17.72	2365	1.18	13.44	96	194	Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:9	17.72	2366	1.17	13.44	96	194	Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:9	17.72	2366	1.17	13.45	96	194	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:9	17.72	2366	1.17	13.45	96	194	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:9	17.72	2364	1.17	13.45	96	194	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:9	17.72	2362	1.17	13.45	96	194	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:9	17.72	2362	1.17	13.45	96	194	Idle	72.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.57	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:01:9	17.72	2360	1.17	13.45	96	194	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:02:0	17.72	2359	1.17	13.44	96	194	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:0	17.72	2358	1.17	13.45	96	194	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:0	17.72	2354	1.17	13.45	96	194	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:0	17.72	2350	1.17	13.45	96	194	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:0	17.72	2359	1.16	13.45	96	194	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:0	17.72	2359	1.16	13.44	96	194	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:1	17.72	2350	1.16	13.44	96	194	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:1	17.72	2350	1.16	13.44	96	194	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:1	17.72	2348	1.16	13.45	96	194	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:1	17.72	2347	1.16	13.44	96	194	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:1	17.72	2343	1.16	13.44	96	194	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:1	17.72	2341	1.16	13.44	96	194	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:1	17.72	2340	1.16	13.43	96	194	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:2	17.72	2340	1.15	13.43	96	194	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:2	17.72	2339	1.15	13.43	96	194	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:2	17.72	2339	1.15	13.44	96	194	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:2	17.72	2337	1.15	13.45	96	194	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:2	17.72	2337	1.15	13.44	96	194	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:2	17.72	2336	1.14	13.44	96	194	Idle	74.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:3	17.72	2334	1.14	13.43	96	194	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:3	17.72	2321	1.14	13.43	96	194	Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:3	17.72	2326	1.14	13.44	96	194	Idle	74.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:3	17.72	2326	1.14	13.44	96	194	Idle	74.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:3	17.72	2341	1.14	13.44	96	194	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:3	17.72	2324	1.14	13.45	96	194	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:4	17.72	2324	1.13	13.44	96	194	Full Load	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:4	17.72	2325	1.13	13.45	96	194	Off Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.58	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:4	17.72	2206	1.14	13.44	96	194	Off Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:4	9.54	2206	1.14	13.43	96	194	Off Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:02:4	9.54	2333	1.15	13.44	96	194	Off Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:02:4	12.27	2342	1.15	13.45	96	194	Off Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:02:4	12.27	2342	1.16	13.44	96	194	Off Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:5	14.99	2340	1.16	13.45	96	194	Off Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:5	17.72	2339	1.17	13.45	96	194	Off Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:5	17.72	2336	1.18	13.43	96	194	Off Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:5	20.45	2336	1.18	13.44	96	194	Off Idle	75.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:5	23.18	2333	1.19	13.44	96	194	Off Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:5	23.18	2330	1.2	13.43	96	194	Off Idle	75.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:6	25.9	2330	1.2	13.45	96	194	Off Idle	75.7	0	2	132	944 Turbo	0.01	Lean	1	14.7	-10.27	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:6	28.63	2328	1.21	13.44	96	194	Off Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.7	-10.25	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:6	28.63	2328	1.22	13.43	96	194	Off Idle	76	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:6	28.63	2328	1.22	13.43	96	194	Off Idle	76.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:02:6	31.36	2328	1.24	13.45	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.22	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:6	34.08	2328	1.25	13.43	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:6	34.08	2320	1.26	13.43	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:7	35.45	2314	1.27	13.42	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:7	35.45	2317	1.28	13.44	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:7	35.45	2331	1.28	13.43	96	194	Off Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:7	35.45	2338	1.29	13.43	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:7	35.45	2338	1.29	13.43	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:7	35.45	2333	1.3	13.44	96	194	Off Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:8	35.45	2334	1.3	13.44	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.28	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:8	35.45	2324	1.3	13.45	96	194	Off Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:8	35.45	2320	1.31	13.45	96	195	Off Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:8	35.45	2333	1.31	13.45	96	195	Off Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:8	35.45	2305	1.32	13.45	96	195	Off Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:8	35.45	2305	1.32	13.45	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:02:9	35.45	2299	1.34	13.45	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.25	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:02:9	35.45	2267	1.34	13.46	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.22	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:9	35.45	2274	1.35	13.45	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10.21	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:02:9	35.45	2275	1.36	13.44	96	194	Off Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10.15	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:02:9	35.45	2276	1.37	13.45	96	194	Off Idle	76.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.06	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:02:9	35.45	2284	1.38	13.44	96	194	Off Idle	76.7	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:02:9	35.45	2288	1.39	13.43	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.93	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:0	35.45	2302	1.4	13.43	96	194	Off Idle	77	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:0	35.45	2320	1.41	13.45	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.83	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:0	35.45	2320	1.42	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.04	Lean	1	14.7	-9.82	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:0	35.45	2340	1.43	13.44	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.8	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:03:0	35.45	2337	1.44	13.45	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.04	Lean	1	14.7	-9.8	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:0	35.45	2334	1.45	13.45	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:1	35.45	2331	1.46	13.45	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.78	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:1	35.45	2326	1.47	13.45	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.04	Lean	1	14.7	-9.77	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:1	35.45	2326	1.48	13.45	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.74	20.26	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:1	35.45	2325	1.49	13.45	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.04	Lean	1	14.7	-9.7	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:1	35.45	2324	1.5	13.45	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.04	Lean	1	14.7	-9.69	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:1	35.45	2322	1.5	13.45	96	194	Off Idle	76.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:1	35.45	2320	1.51	13.45	96	194	Off Idle	76.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.64	20.14	1.37	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:2	35.45	2316	1.52	13.44	96	194	Off Idle	76	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.61	20.02	1.36	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:2	35.45	2304	1.52	13.44	96	194	Off Idle	75.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.61	19.86	1.35	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:2	35.45	2304	1.52	13.45	96	194	Off Idle	75.6	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.6	19.67	1.34	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:2	35.45	2283	1.52	13.43	96	194	Off Idle	75.5	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.59	19.45	1.32	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:2	35.45	2283	1.52	13.43	96	194	Off Idle	75.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.58	19.09	1.3	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:2	35.45	2276	1.53	13.43	96	194	Off Idle	75.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.56	18.84	1.28	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:3	35.45	2277	1.53	13.43	96	194	Off Idle	75.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.54	18.58	1.27	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:3	35.45	2280	1.53	13.44	96	194	Off Idle	76.3	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.55	18.32	1.25	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:3	35.45	2281	1.54	13.43	96	194	Off Idle	76.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.54	18.08	1.23	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:3	35.45	2281	1.54	13.45	96	194	Off Idle	76.8	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.5	17.76	1.21	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:3	35.45	2287	1.54	13.44	96	194	Off Idle	76.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.52	17.57	1.2	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:3	35.45	2291	1.54	13.43	96	194	Off Idle	76.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.52	17.48	1.19	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:4	35.45	2291	1.54	13.43	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.52	17.23	1.17	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:4	35.45	2292	1.53	13.42	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.53	17.07	1.16	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:4	35.45	2295	1.53	13.41	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.52	16.92	1.15	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:4	35.45	2297	1.53	13.43	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.07	Lean	1	14.7	-9.52	16.75	1.14	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:4	35.45	2297	1.53	13.45	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.56	16.6	1.13	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:4	35.45	2300	1.53	13.44	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.55	16.46	1.12	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:4	35.45	2301	1.53	13.45	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.55	16.28	1.11	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:5	35.45	2303	1.53	13.46	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.56	16.18	1.1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:5	35.45	2303	1.52	13.45	96	194	Off Idle	78	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.56	16.1	1.1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:5	35.45	2303	1.52	13.44	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.12	Lean	1	14.7	-9.55	16.03	1.09	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:5	35.45	2304	1.52	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.55	15.96	1.09	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:5	35.45	2290	1.52	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.56	15.91	1.08	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:5	35.45	2306	1.52	13.42	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.2	Lean	1	14.7	-9.55	15.86	1.08	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:6	35.45	2306	1.51	13.44	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.52	15.83	1.08	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:6	35.45	2306	1.51	13.43	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	-9.56	15.79	1.08	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:6	35.45	2324	1.51	13.42	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-9.55	15.74	1.07	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:6	35.45	2303	1.51	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.52	15.71	1.07	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:6	35.45	2303	1.51	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.51	15.67	1.07	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:6	35.45	2299	1.51	13.45	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.52	15.61	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:6	35.45	2295	1.51	13.45	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.16	Lean	1	14.7	-9.51	15.59	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:7	35.45	2290	1.51	13.45	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.13	Lean	1	14.7	-9.51	15.55	1.06	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:7	35.45	2288	1.51	13.45	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.52	15.51	1.06	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:7	35.45	2280	1.51	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.53	15.47	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:7	35.45	2277	1.52	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.49	15.42	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:7	35.45	2277	1.52	13.44	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.09	Lean	1	14.7	-9.47	15.4	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:7	35.45	2282	1.52	13.45	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.48	15.37	1.05	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:8	35.45	2281	1.52	13.46	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.48	15.33	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:03:8	35.45	2287	1.52	13.46	96	194	Off Idle	78	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.5	15.3	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:8	35.45	2287	1.52	13.45	96	194	Off Idle	78	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.51	15.27	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:8	35.45	2292	1.52	13.44	96	194	Off Idle	78	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.52	15.24	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:8	35.45	2297	1.52	13.43	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.21	Lean	1	14.7	-9.5	15.22	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:8	35.45	2298	1.53	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.27	Rich	1	14.7	-9.47	15.24	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:9	35.45	2304	1.53	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.45	15.24	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:9	35.45	2306	1.53	13.41	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-9.45	15.23	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:9	35.45	2306	1.53	13.42	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.45	Rich	1	14.7	-9.43	15.24	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:9	35.45	2305	1.53	13.43	96	194	Off Idle	78	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.44	15.24	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:9	35.45	2298	1.53	13.44	96	194	Off Idle	78	0	2	132	944 Turbo	0.57	Rich	1	14.7	-9.44	15.25	1.04	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:03:9	35.45	2291	1.54	13.44	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.41	15.23	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:03:9	35.45	2291	1.54	13.45	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.66	Rich	1	14.7	-9.41	15.22	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:04:0	35.45	2284	1.54	13.46	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.35	15.21	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:04:0	35.45	2265	1.55	13.46	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.33	15.17	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:04:0	34.08	2265	1.55	13.46	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.33	15.16	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:04:0	34.08	2278	1.56	13.46	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.3	15.15	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:04:0	34.08	2277	1.56	13.45	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.26	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:04:0	34.08	2279	1.57	13.44	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.24	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:04:1	34.08	2281	1.57	13.43	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.17	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:1	34.08	2281	1.59	13.43	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.09	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:1	34.08	2279	1.6	13.42	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.02	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:1	34.08	2281	1.61	13.43	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.9	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:04:1	34.08	2281	1.62	13.44	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.82	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:04:1	34.08	2294	1.63	13.44	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.74	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:1	34.08	2294	1.64	13.44	96	194	Off Idle	78.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.72	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:2	34.08	2302	1.65	13.43	96	194	Off Idle	78.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.65	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:2	34.08	2306	1.66	13.45	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.38	Lean	1	14.7	-8.61	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:2	34.08	2308	1.68	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.55	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:2	34.08	2309	1.69	13.44	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.52	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:2	34.08	2303	1.7	13.44	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.47	14.92	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:2	34.08	2302	1.71	13.43	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.44	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:3	34.08	2302	1.72	13.43	96	194	Off Idle	78	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.39	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:3	34.08	2289	1.73	13.45	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.33	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:3	34.08	2287	1.75	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.23	Rich	1	14.7	-8.33	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:3	34.08	2287	1.76	13.44	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.29	Rich	1	14.7	-8.3	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:3	34.08	2284	1.77	13.45	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.35	Rich	1	14.7	-8.28	14.83	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:3	34.08	2288	1.77	13.45	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.41	Rich	1	14.7	-8.28	14.86	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:4	34.08	2288	1.78	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.28	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:4	34.08	2288	1.78	13.41	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.27	14.91	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:4	34.08	2288	1.79	13.43	96	194	Off Idle	77	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.21	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:4	34.08	2292	1.79	13.43	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.23	14.98	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:04:4	34.08	2295	1.79	13.42	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.22	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:4	34.08	2294	1.79	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-8.21	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:4	34.08	2293	1.79	13.43	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.22	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:5	34.08	2294	1.79	13.42	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.24	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:5	34.08	2293	1.79	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.8	Rich	1	14.7	-8.22	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:5	34.08	2294	1.79	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.22	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:5	34.08	2295	1.79	13.42	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.24	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:5	34.08	2295	1.79	13.42	96	194	Off Idle	78	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.26	14.9	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:5	34.08	2296	1.79	13.43	96	194	Off Idle	78	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.25	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:6	34.08	2295	1.79	13.44	96	194	Off Idle	78	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.27	14.76	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:6	34.08	2292	1.79	13.42	96	194	Off Idle	78	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.3	14.69	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:6	34.08	2289	1.79	13.43	96	194	Off Idle	78	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.3	14.61	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:6	34.08	2289	1.78	13.43	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.28	14.52	0.99	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:6	34.08	2287	1.78	13.42	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.27	14.42	0.98	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:6	34.08	2286	1.78	13.43	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-8.28	14.4	0.98	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:6	34.08	2288	1.78	13.44	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.25	14.36	0.98	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:7	34.08	2288	1.78	13.42	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.26	14.32	0.98	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:04:7	34.08	2284	1.78	13.41	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-8.25	14.31	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:7	34.08	2284	1.78	13.43	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.24	14.3	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:7	34.08	2285	1.78	13.44	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.24	14.28	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:7	34.08	2292	1.78	13.41	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.27	14.28	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:7	34.08	2296	1.78	13.41	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.3	14.27	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:8	34.08	2296	1.78	13.43	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.28	14.27	0.97	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:8	34.08	2306	1.78	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.29	14.29	0.97	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:8	34.08	2308	1.78	13.43	96	194	Off Idle	78.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.31	14.28	0.97	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:8	34.08	2308	1.78	13.43	96	194	Off Idle	78.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.29	14.3	0.97	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:8	34.08	2308	1.78	13.44	96	194	Off Idle	78.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.31	14.29	0.97	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:04:8	34.08	2301	1.78	13.44	96	194	Off Idle	78.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.32	14.29	0.97	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:04:9	34.08	2296	1.78	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.32	14.29	0.97	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:04:9	34.08	2294	1.78	13.44	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.32	14.3	0.97	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:04:9	34.08	2288	1.78	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.33	14.29	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:9	34.08	2285	1.78	13.41	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.3	14.28	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:9	34.08	2282	1.78	13.42	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.27	14.28	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:9	34.08	2283	1.78	13.44	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.29	14.27	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:04:9	34.08	2285	1.78	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.6	-8.3	14.26	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:0	34.08	2290	1.78	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.3	14.26	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:0	34.08	2290	1.78	13.44	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.3	14.26	0.97	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:0	34.08	2292	1.78	13.44	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.31	14.26	0.97	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:0	34.08	2296	1.78	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.34	14.26	0.97	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:0	34.08	2299	1.78	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.31	14.29	0.97	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:0	34.08	2298	1.78	13.44	96	194	Off Idle	78.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.29	14.29	0.97	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:1	34.08	2298	1.78	13.43	96	194	Off Idle	78.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.29	14.3	0.97	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:1	34.08	2302	1.77	13.43	96	194	Off Idle	78.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.28	14.31	0.97	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:1	34.08	2301	1.77	13.44	96	194	Off Idle	78.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.24	14.33	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:1	34.08	2296	1.77	13.43	96	194	Off Idle	78.7	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.26	14.34	0.98	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:1	34.08	2296	1.77	13.41	96	194	Off Idle	78.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-8.25	14.34	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:1	34.08	2299	1.77	13.42	96	194	Off Idle	78.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-8.23	14.35	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:1	34.08	2298	1.77	13.44	96	194	Off Idle	78.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-8.22	14.36	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:2	34.08	2296	1.77	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.24	14.36	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:2	34.08	2293	1.77	13.43	96	194	Off Idle	78.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-8.28	14.37	0.98	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:2	34.08	2293	1.77	13.44	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-8.29	14.39	0.98	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:2	34.08	2281	1.77	13.43	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.29	14.38	0.98	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:2	34.08	2281	1.77	13.43	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.29	14.38	0.98	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:2	34.08	2282	1.77	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.79	Rich	1	14.7	-8.25	14.39	0.98	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:3	34.08	2284	1.77	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	-8.25	14.41	0.98	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:3	34.08	2291	1.77	13.41	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.23	14.42	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:3	34.08	2300	1.77	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	-8.21	14.42	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:3	34.08	2300	1.78	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-8.23	14.43	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:3	34.08	2304	1.78	13.43	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.78	Rich	1	14.7	-8.24	14.43	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:3	34.08	2304	1.78	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-8.26	14.45	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:4	34.08	2302	1.78	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-8.29	14.47	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:4	34.08	2300	1.78	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.28	14.5	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:4	34.08	2302	1.78	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.27	14.52	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:4	34.08	2297	1.78	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.31	14.54	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:4	34.08	2296	1.78	13.42	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.3	14.56	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:4	34.08	2297	1.78	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.29	14.57	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:4	34.08	2291	1.78	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.31	14.61	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:5	34.08	2291	1.78	13.43	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.3	14.63	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:5	34.08	2288	1.78	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.27	14.64	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:5	34.08	2284	1.78	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.29	14.65	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:5	34.08	2282	1.78	13.42	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.25	14.66	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:5	34.08	2281	1.78	13.42	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.4	Rich	1	14.7	-8.24	14.68	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:5	34.08	2289	1.78	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.34	Lean	1	14.7	-8.25	14.7	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:6	34.08	2294	1.78	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.25	14.71	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:6	34.08	2298	1.78	13.46	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.24	14.74	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:05:6	34.08	2308	1.78	13.46	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.28	14.77	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:6	34.08	2312	1.78	13.45	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.26	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:6	34.08	2312	1.78	13.45	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.25	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:6	34.08	2312	1.78	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.24	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:6	34.08	2308	1.78	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.23	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:7	34.08	2297	1.78	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.21	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:7	34.08	2297	1.78	13.43	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.24	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:7	34.08	2292	1.78	13.42	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.24	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:7	34.08	2284	1.78	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.23	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:7	34.08	2288	1.78	13.43	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.24	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:7	34.08	2288	1.78	13.45	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.25	14.93	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:05:8	34.08	2292	1.78	13.42	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.33	Lean	1	14.7	-8.25	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:8	34.08	2295	1.78	13.44	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.21	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:8	34.08	2295	1.78	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.27	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:8	34.08	2296	1.78	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.55	Lean	1	14.7	-8.26	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:8	34.08	2296	1.78	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.23	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:8	34.08	2297	1.78	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.66	Lean	1	14.7	-8.26	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:9	34.08	2296	1.78	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.7	Lean	1	14.7	-8.23	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:9	34.08	2290	1.78	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.2	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:9	34.08	2290	1.78	13.45	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.19	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:9	34.08	2299	1.78	13.43	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.25	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:9	34.08	2300	1.78	13.42	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.23	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:9	34.08	2302	1.78	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.25	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:05:9	34.08	2302	1.78	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.3	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:0	34.08	2302	1.78	13.42	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.31	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:0	34.08	2294	1.78	13.42	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.28	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:0	34.08	2295	1.78	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.29	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:0	34.08	2296	1.78	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.31	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:0	34.08	2295	1.78	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.52	Lean	1	14.7	-8.27	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:0	34.08	2293	1.78	13.45	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.29	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:1	34.08	2293	1.78	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.28	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:1	34.08	2295	1.78	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.25	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:1	34.08	2296	1.78	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.22	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:1	34.08	2298	1.78	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.25	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:1	34.08	2298	1.78	13.43	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.26	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:1	34.08	2296	1.78	13.43	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.24	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:1	34.08	2299	1.78	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.27	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:2	34.08	2300	1.78	13.43	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.29	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:2	34.08	2300	1.78	13.43	96	194	Off Idle	77	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.26	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:2	34.08	2299	1.78	13.43	96	194	Off Idle	77	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.3	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:2	34.08	2298	1.78	13.42	96	194	Off Idle	77	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.27	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:2	34.08	2296	1.78	13.42	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.25	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:2	34.08	2290	1.78	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.24	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:3	34.08	2287	1.78	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.25	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:3	34.08	2287	1.78	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.33	Lean	1	14.7	-8.24	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:3	34.08	2288	1.78	13.43	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.25	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:3	34.08	2287	1.78	13.43	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.45	Lean	1	14.7	-8.25	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:3	34.08	2288	1.78	13.44	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.51	Lean	1	14.7	-8.23	15.13	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:3	34.08	2294	1.78	13.43	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.6	Lean	1	14.7	-8.24	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:4	34.08	2301	1.78	13.43	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.28	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:4	34.08	2305	1.78	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.28	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:4	34.08	2305	1.78	13.45	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.31	15.16	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:4	34.08	2303	1.77	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.31	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:4	34.08	2306	1.77	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.32	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:4	34.08	2305	1.77	13.44	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.32	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:4	34.08	2304	1.77	13.44	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.33	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:5	34.08	2304	1.77	13.44	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.35	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:5	34.08	2299	1.77	13.44	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.38	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:06:5	34.08	2298	1.77	13.42	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.38	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:5	34.08	2298	1.77	13.43	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.66	Lean	1	14.7	-8.34	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:5	34.08	2293	1.77	13.44	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.61	Lean	1	14.7	-8.36	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:5	34.08	2293	1.77	13.43	96	194	Off Idle	77	0	2	132	944 Turbo	0.55	Lean	1	14.7	-8.37	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:6	34.08	2288	1.77	13.43	96	194	Off Idle	77	0	2	132	944 Turbo	0.49	Lean	1	14.7	-8.34	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:6	34.08	2289	1.77	13.44	96	194	Off Idle	77	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.29	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:6	34.08	2292	1.77	13.45	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.33	Lean	1	14.7	-8.28	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:6	34.08	2292	1.77	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.26	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:6	34.08	2300	1.77	13.45	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.29	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:6	34.08	2305	1.77	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.28	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:6	34.08	2305	1.77	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.29	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:7	34.08	2309	1.77	13.44	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.33	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:7	34.08	2306	1.77	13.44	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.3	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:7	34.08	2297	1.77	13.44	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.29	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:7	34.08	2294	1.77	13.44	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.32	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:7	34.08	2288	1.77	13.43	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.31	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:7	34.08	2287	1.77	13.43	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.28	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:06:8	34.08	2287	1.77	13.43	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.32	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:8	34.08	2288	1.77	13.42	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.33	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:8	34.08	2288	1.77	13.41	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.41	Lean	1	14.7	-8.31	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:8	34.08	2288	1.77	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.5	Lean	1	14.7	-8.32	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:8	34.08	2295	1.77	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.35	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:8	34.08	2295	1.76	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.34	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:9	34.08	2296	1.76	13.45	96	194	Off Idle	78	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.37	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:9	34.08	2302	1.76	13.46	96	194	Off Idle	78.1	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.37	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:9	34.08	2303	1.76	13.44	96	194	Off Idle	78	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.38	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:9	34.08	2304	1.76	13.45	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.36	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:9	34.08	2301	1.76	13.43	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.37	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:9	34.08	2301	1.76	13.43	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.38	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:06:9	34.08	2296	1.76	13.44	96	194	Off Idle	77.8	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.37	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:0	34.08	2290	1.76	13.43	96	194	Off Idle	77.7	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.41	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:0	34.08	2286	1.76	13.42	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.56	Lean	1	14.7	-8.41	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:0	34.08	2286	1.76	13.43	96	194	Off Idle	77.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.41	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:0	34.08	2285	1.76	13.44	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.44	Lean	1	14.7	-8.39	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:0	34.08	2288	1.76	13.43	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.37	Lean	1	14.7	-8.35	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:0	34.08	2290	1.76	13.45	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.35	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:1	34.08	2295	1.76	13.47	96	194	Off Idle	77.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.34	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:1	34.08	2300	1.76	13.47	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.34	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:1	34.08	2302	1.76	13.47	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.33	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:1	34.08	2307	1.76	13.47	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.33	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:1	34.08	2310	1.76	13.46	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.32	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:1	34.08	2306	1.76	13.45	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.35	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:1	34.08	2304	1.76	13.45	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.38	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:2	34.08	2297	1.76	13.44	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.38	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:2	34.08	2293	1.76	13.44	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.38	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:2	34.08	2288	1.76	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.4	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:2	34.08	2285	1.76	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.4	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:2	34.08	2292	1.76	13.43	96	194	Off Idle	77.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.36	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:2	34.08	2291	1.76	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.37	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:3	34.08	2293	1.76	13.42	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.36	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:3	34.08	2296	1.76	13.41	96	194	Off Idle	77	0	2	132	944 Turbo	0.34	Rich	1	14.7	-8.35	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:3	34.08	2296	1.76	13.43	96	194	Off Idle	77	0	2	132	944 Turbo	0.4	Rich	1	14.7	-8.34	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:3	34.08	2304	1.76	13.44	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.46	Rich	1	14.7	-8.36	15.14	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:3	34.08	2311	1.76	13.44	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.52	Rich	1	14.7	-8.34	15.16	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:3	34.08	2313	1.76	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.36	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:4	34.08	2314	1.76	13.42	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.41	15.14	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:4	34.08	2311	1.76	13.41	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.4	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:4	34.08	2309	1.76	13.42	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.41	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:07:4	34.08	2309	1.76	13.43	96	194	Off Idle	77.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.45	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:4	34.08	2303	1.76	13.41	96	194	Off Idle	77.2	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.43	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:4	34.08	2299	1.76	13.44	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.42	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:4	34.08	2294	1.76	13.43	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.41	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:5	34.08	2294	1.76	13.44	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.41	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:5	34.08	2292	1.76	13.44	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.43	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:5	34.08	2292	1.76	13.42	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.45	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:5	34.08	2286	1.75	13.42	96	194	Off Idle	77.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.41	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:5	34.08	2289	1.75	13.43	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.41	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:5	34.08	2293	1.75	13.42	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.41	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:6	34.08	2293	1.75	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.38	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:6	34.08	2299	1.75	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.37	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:6	34.08	2304	1.75	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.4	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:6	34.08	2306	1.75	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.38	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:6	34.08	2310	1.75	13.45	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.35	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:6	34.08	2311	1.75	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.4	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:6	34.08	2312	1.75	13.43	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.44	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:7	34.08	2312	1.75	13.42	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.42	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:7	34.08	2310	1.75	13.42	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.44	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:7	34.08	2310	1.75	13.43	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.47	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:7	34.08	2310	1.75	13.43	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.48	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:7	34.08	2304	1.75	13.45	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.46	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:7	34.08	2304	1.75	13.46	96	194	Off Idle	77	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.48	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:07:8	34.08	2301	1.75	13.45	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.49	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:8	34.08	2301	1.75	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.46	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:8	34.08	2300	1.75	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.45	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:8	34.08	2300	1.75	13.43	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.49	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:8	34.08	2302	1.74	13.42	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.52	14.9	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:8	34.08	2310	1.74	13.43	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.54	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:9	34.08	2311	1.73	13.43	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.62	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:9	34.08	2310	1.73	13.43	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.72	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:07:9	34.08	2311	1.72	13.45	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.78	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:07:9	34.08	2309	1.7	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.82	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:07:9	34.08	2307	1.69	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.96	15.02	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:07:9	34.08	2306	1.68	13.45	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.02	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:07:9	34.08	2301	1.66	13.45	96	194	Off Idle	76.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.11	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:08:0	34.08	2296	1.65	13.44	96	194	Off Idle	76.8	0	2	132	944 Turbo	0.52	Rich	1	14.7	-9.18	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:08:0	34.08	2293	1.62	13.45	96	194	Off Idle	76.8	0	2	132	944 Turbo	0.47	Rich	1	14.7	-9.29	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:08:0	34.08	2284	1.6	13.44	96	194	Off Idle	76.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.46	14.97	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:08:0	34.08	2282	1.58	13.43	96	194	Off Idle	76.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.54	14.91	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:08:0	34.08	2279	1.55	13.44	96	194	Off Idle	76.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.64	14.89	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:08:0	34.08	2279	1.51	13.44	96	194	Full Load	77	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.78	14.86	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:08:1	34.08	2278	1.48	13.43	96	194	Idle	77.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.93	14.86	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:1	34.08	2275	1.45	13.44	96	194	Idle	77.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.04	14.86	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:1	34.08	2272	1.41	13.44	96	194	Idle	77.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.18	14.85	1.01	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:08:1	31.36	2235	1.37	13.44	96	194	Idle	77.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.3	14.83	1.01	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:08:1	31.36	2231	1.34	13.44	96	194	Idle	77.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.38	14.82	1.01	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:08:1	25.9	2204	1.31	13.43	96	194	Idle	77.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.44	14.82	1.01	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:08:1	25.9	2204	1.28	13.42	96	194	Idle	77.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.5	14.82	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:2	20.45	2190	1.25	13.43	96	194	Idle	77.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.53	14.83	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:2	17.72	2221	1.23	13.43	96	194	Idle	77.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.56	14.84	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:2	17.72	2224	1.21	13.43	96	194	Idle	76.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.56	14.84	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:2	17.72	2239	1.19	13.44	96	194	Idle	76.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.56	14.86	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:2	17.72	2276	1.17	13.44	96	194	Idle	76.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.55	14.88	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:2	17.72	2276	1.15	13.45	96	194	Idle	76.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.53	14.91	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:3	17.72	2304	1.13	13.46	96	194	Idle	75.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.51	14.94	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:3	17.72	2315	1.12	13.46	96	194	Idle	75.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.55	14.99	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:3	17.72	2315	1.11	13.44	96	194	Idle	75.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.55	15.01	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:08:3	17.72	2314	1.1	13.43	96	194	Idle	75.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.58	15.03	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:3	17.72	2306	1.09	13.42	96	194	Idle	75.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.59	15.04	1.02	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:3	17.72	2301	1.09	13.42	96	194	Idle	75.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.56	15.07	1.03	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:4	17.72	2287	1.09	13.43	96	194	Idle	75.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.53	15.08	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:4	17.72	2265	1.1	13.44	96	194	Idle	75.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.56	15.09	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:4	17.72	2265	1.1	13.44	96	194	Idle	75.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.56	15.11	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:4	17.72	2253	1.1	13.44	96	194	Idle	76.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.53	15.14	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:4	17.72	2244	1.1	13.45	96	194	Idle	76.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.55	15.15	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:4	17.72	2243	1.1	13.45	96	194	Idle	76.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.55	15.17	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:4	17.72	2243	1.1	13.45	96	194	Idle	76.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.56	15.18	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:5	17.72	2247	1.1	13.43	96	194	Idle	76.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.54	15.19	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:5	17.72	2256	1.11	13.43	96	194	Idle	77	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.55	15.2	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:5	17.72	2260	1.11	13.44	96	194	Idle	76.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.57	15.22	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:5	17.72	2269	1.11	13.43	96	194	Idle	76.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.56	15.22	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:5	17.72	2281	1.11	13.43	96	194	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	15.24	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:5	17.72	2282	1.11	13.45	96	194	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	15.25	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:6	17.72	2283	1.11	13.43	96	194	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	15.27	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:6	17.72	2281	1.11	13.42	96	194	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	15.33	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:6	17.72	2280	1.1	13.44	96	194	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	15.4	1.05	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:6	17.72	2274	1.1	13.44	96	194	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	15.52	1.06	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:6	17.72	2262	1.1	13.42	96	194	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	15.77	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:6	17.72	2255	1.1	13.42	96	194	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	16	1.09	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:6	17.72	2252	1.1	13.44	96	194	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	16.3	1.11	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:7	17.72	2243	1.1	13.44	96	194	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	16.68	1.14	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:7	17.72	2238	1.1	13.43	96	194	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	17.14	1.17	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:7	17.72	2238	1.1	13.43	96	194	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	17.6	1.2	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:7	17.72	2237	1.09	13.44	96	194	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	18.06	1.23	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:7	17.72	2238	1.09	13.44	96	194	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	18.49	1.26	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:7	17.72	2230	1.09	13.45	96	194	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	18.89	1.29	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:8	17.72	2243	1.09	13.45	96	194	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	19.27	1.31	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:8	17.72	2264	1.09	13.46	96	194	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	19.59	1.33	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:8	17.72	2249	1.09	13.45	96	194	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	19.96	1.36	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:8	17.72	2241	1.08	13.45	96	194	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.12	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:8	17.72	2250	1.08	13.44	96	194	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:8	17.72	2249	1.08	13.45	96	194	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:9	17.72	2256	1.08	13.45	96	194	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:9	17.72	2236	1.08	13.44	96	194	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:9	17.72	2242	1.07	13.45	96	194	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:9	17.72	2240	1.07	13.46	96	194	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:9	17.72	2237	1.07	13.44	96	194	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:9	17.72	2234	1.07	13.43	96	194	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:08:9	17.72	2231	1.06	13.43	96	194	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:0	17.72	2231	1.06	13.43	96	194	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:0	17.72	2229	1.06	13.43	96	194	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:0	17.72	2229	1.06	13.43	96	194	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:0	17.72	2228	1.06	13.45	96	194	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:0	17.72	2228	1.06	13.44	96	194	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:0	17.72	2228	1.06	13.42	96	194	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.2	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:1	17.72	2228	1.05	13.43	96	194	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:1	17.72	2229	1.05	13.44	96	194	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:1	17.72	2228	1.05	13.44	96	194	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:1	17.72	2227	1.05	13.44	96	194	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:1	17.72	2227	1.05	13.44	96	194	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:1	17.72	2222	1.05	13.45	96	194	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:1	17.72	2204	1.05	13.45	96	194	Idle	79.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:2	17.72	2210	1.05	13.45	96	194	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.67	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:2	17.72	2220	1.05	13.45	96	194	Idle	80.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.68	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:2	17.72	2203	1.05	13.44	96	194	Idle	80.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:09:2	17.72	2203	1.05	13.43	96	194	Idle	80.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.66	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:2	17.72	2173	1.05	13.43	96	194	Idle	80.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:2	17.72	2153	1.05	13.44	96	194	Idle	81	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:3	17.72	2153	1.05	13.45	96	194	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:3	17.72	2115	1.04	13.46	96	194	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:3	17.72	2076	1.04	13.46	96	194	Idle	81.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:3	17.72	2076	1.04	13.45	96	194	Idle	81.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.61	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:3	17.72	2046	1.04	13.44	96	194	Idle	80.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:3	17.72	2017	1.04	13.42	96	194	Idle	80	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.59	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:4	17.72	1981	1.04	13.42	96	194	Idle	79.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.21	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:4	17.72	1981	1.04	13.41	96	194	Idle	78.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.47	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:4	17.72	1964	1.05	13.42	96	194	Idle	78.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.45	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:4	17.72	1934	1.05	13.43	96	194	Idle	77.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:4	17.72	1934	1.05	13.43	96	194	Idle	76.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.41	20.22	1.38	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:4	17.72	1912	1.06	13.45	96	194	Idle	75.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:4	17.72	1873	1.07	13.45	96	194	Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.32	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:5	17.72	1858	1.07	13.46	96	194	Idle	72.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.29	20.2	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:5	17.72	1826	1.08	13.44	96	194	Idle	71.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.21	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:5	17.72	1826	1.09	13.45	96	194	Idle	71	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.14	20.21	1.38	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:5	17.72	1787	1.1	13.43	96	194	Idle	70.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.06	20.2	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:5	17.72	1769	1.11	13.43	96	194	Idle	69.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.99	20.21	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:5	17.72	1764	1.12	13.43	96	194	Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.92	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:6	17.72	1737	1.14	13.42	96	194	Idle	68.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.87	20.22	1.38	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:6	17.72	1715	1.15	13.42	96	194	Idle	68.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.82	20.22	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:6	17.72	1692	1.16	13.42	96	194	Idle	68.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.22	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:6	17.72	1680	1.17	13.41	96	194	Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.74	20.22	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:6	17.72	1651	1.18	13.42	96	194	Full Load	67.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.22	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:6	17.72	1622	1.2	13.43	96	194	Off Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.54	20.22	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:6	17.72	1622	1.21	13.43	96	194	Off Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.7	-9.41	20.23	1.38	4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:7	17.72	1587	1.24	13.42	96	194	Off Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.7	-9.21	20.23	1.38	4.1	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:7	17.72	1575	1.28	13.44	96	194	Off Idle	67.7	0	2	132	944 Turbo	0.01	Lean	1	14.7	-8.85	20.24	1.38	4.2	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:09:7	17.72	1518	1.35	13.43	96	194	Off Idle	69	0	2	132	944 Turbo	0.01	Lean	1	14.7	-8.26	20.23	1.38	4.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:09:7	9.54	1499	1.44	13.44	96	194	Off Idle	70.3	0	2	132	944 Turbo	0.01	Lean	1	14.7	-7.29	20.23	1.38	4.2	0.7	ON	28 Pin	OFF	Removed	Disabled
03:27:09:7	9.54	1512	1.54	13.43	96	194	Off Idle	71.6	0	2	132	944 Turbo	0.01	Lean	1	14.7	-5.96	20.24	1.38	4.2	0.7	ON	28 Pin	OFF	Removed	Disabled
03:27:09:7	9.54	1512	1.65	13.43	96	194	Off Idle	73	0	2	132	944 Turbo	0.01	Lean	1	14.7	-4.46	20.25	1.38	4.2	9.3	ON	28 Pin	OFF	Removed	Disabled
03:27:09:8	12.27	1490	1.72	13.41	96	194	Off Idle	74.2	0	2	132	944 Turbo	0.01	Lean	1	14.7	-2.32	20.25	1.38	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:09:8	12.27	1466	1.77	13.41	96	194	Off Idle	75.4	0	2	132	944 Turbo	0.01	Lean	1	14.7	-1.32	20.26	1.38	4.3	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:09:8	14.99	1477	1.81	13.42	96	194	Off Idle	76.7	0	2	132	944 Turbo	0.05	Lean	1	14.7	-0.74	20.25	1.38	4.4	9.9	ON	28 Pin	OFF	Removed	Disabled
03:27:09:8	14.99	1477	1.86	13.43	96	194	Off Idle	77.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-0.45	20.25	1.38	4.3	9.9	ON	28 Pin	OFF	Removed	Disabled
03:27:09:8	14.99	1551	1.91	13.44	96	194	Off Idle	79.1	0	2	132	944 Turbo	0.05	Lean	1	14.7	-0.5	20.25	1.38	4.1	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:09:8	17.72	1615	1.98	13.45	96	194	Off Idle	80.4	0	2	132	944 Turbo	0.05	Lean	1	14.7	-0.51	20.24	1.38	3.9	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:09:9	17.72	1672	2.05	13.45	96	194	Off Idle	81.7	0	2	132	944 Turbo	0.05	Lean	1	14.7	-0.56	20.25	1.38	3.8	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:09:9	20.45	1698	2.11	13.44	96	194	Off Idle	82.9	0	2	132	944 Turbo	0.08	Lean	1	14.7	-0.69	20.25	1.38	3.7	0.7	ON	28 Pin	OFF	Removed	Disabled
03:27:09:9	20.45	1698	2.13	13.44	96	194	Off Idle	84.2	0	2	132	944 Turbo	0.1	Lean	1	14.7	-0.77	20.25	1.38	3.7	0.7	ON	28 Pin	OFF	Removed	Disabled
03:27:09:9	23.18	1791	2.15	13.43	96	194	Off Idle	85.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-1.29	20.25	1.38	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:09:9	23.18	1840	2.12	13.43	96	194	Full Load	86.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-1.96	20.24	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:27:09:9	25.9	1902	2.04	13.43	96	194	Idle	86.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-3.21	20.24	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:27:09:9	25.9	1930	2	13.43	96	194	Idle	86.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.07	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:10:0	24.54	1932	1.98	13.44	96	194	Idle	86.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.84	20.04	1.37	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:10:0	24.54	1950	1.95	13.42	96	194	Idle	86.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.52	19.68	1.34	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:0	19.09	1972	1.9	13.41	96	194	Idle	86.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.35	18.9	1.29	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:0	19.09	1972	1.85	13.41	96	194	Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.7	-6.82	18.26	1.24	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:0	17.72	2033	1.67	13.42	96	194	Idle	86.1	0	2	132	944 Turbo	0.88	Rich	1	14.6	-7.49	17.49	1.19	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:0	17.72	2016	1.49	13.42	96	194	Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.6	-8.03	16.19	1.1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:1	17.72	2016	1.44	13.44	96	194	Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.6	-8.18	15.75	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:1	17.72	1988	1.38	13.45	96	194	Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.6	-8.5	14.86	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:1	17.72	1979	1.35	13.46	96	194	Idle	85.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-8.81	13.92	0.95	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:1	17.72	1970	1.31	13.46	96	194	Idle	85.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-9.04	13.04	0.89	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:10:1	17.72	1939	1.28	13.45	96	194	Idle	85.9	0	2	132	944 Turbo	0.89	Rich	1	14.6	-9.23	12.39	0.84	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:1	17.72	1902	1.16	13.45	96	194	Idle	85.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.38	11.61	0.79	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:1	17.72	1878	1.07	13.43	96	194	Idle	85.5	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.48	11.4	0.78	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:2	17.72	1878	0.95	13.41	96	194	Idle	85.2	0	2	132	944 Turbo	0.88	Rich	1	14.6	-9.57	11.05	0.75	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:2	17.72	1859	0.9	13.42	96	194	Idle	84.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-9.7	10.74	0.73	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:2	17.72	1819	0.88	13.41	96	194	Idle	84.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-9.75	10.62	0.72	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:2	17.72	1795	0.9	13.41	96	194	Idle	83.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.79	10.52	0.72	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:2	17.72	1795	0.94	13.41	96	194	Idle	82.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.84	10.44	0.71	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:2	17.72	1777	0.98	13.42	96	194	Idle	81.8	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.87	10.38	0.71	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:3	17.72	1762	0.98	13.41	96	194	Idle	80.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.88	10.33	0.7	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:3	17.72	1756	0.96	13.42	96	194	Idle	79	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.88	10.28	0.7	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:3	17.72	1745	0.96	13.43	96	194	Idle	78	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.89	10.26	0.7	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:3	17.72	1745	0.97	13.43	96	194	Idle	77	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.87	10.23	0.7	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:3	17.72	1746	0.99	13.42	96	194	Idle	76.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.86	10.23	0.7	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:3	17.72	1750	1.02	13.42	96	194	Idle	75.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.84	10.22	0.7	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:4	17.72	1763	1.03	13.42	96	194	Idle	74.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.82	10.23	0.7	3.9	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:4	17.72	1774	1.04	13.42	96	194	Idle	74	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.8	10.25	0.7	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:4	17.72	1774	1.04	13.43	96	194	Idle	74	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.78	10.28	0.7	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:4	17.72	1788	1.04	13.43	96	194	Idle	74.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.77	10.32	0.7	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:4	17.72	1803	1.05	13.42	96	194	Idle	74.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.75	10.4	0.71	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:4	17.72	1803	1.08	13.43	96	194	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	10.48	0.71	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:4	17.72	1813	1.09	13.43	96	194	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	10.59	0.72	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:5	17.72	1828	1.1	13.43	96	194	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	10.84	0.74	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:5	17.72	1845	1.1	13.43	96	194	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	11.06	0.75	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:5	17.72	1845	1.09	13.45	96	194	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	11.34	0.77	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:5	17.72	1866	1.09	13.44	96	194	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	11.68	0.8	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:5	17.72	1903	1.09	13.42	96	194	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	12.07	0.82	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:5	17.72	1903	1.09	13.42	96	194	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	12.55	0.86	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:6	17.72	1912	1.09	13.42	96	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	13.24	0.9	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:6	17.72	1920	1.09	13.44	96	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	14.09	0.96	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:6	17.72	1928	1.08	13.44	96	194	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	14.98	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:6	17.72	1955	1.07	13.47	96	194	Idle	86.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	15.84	1.08	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:6	17.72	1967	1.06	13.47	96	194	Idle	86.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	16.25	1.11	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:6	17.72	1982	1.05	13.48	96	194	Idle	86.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	17.05	1.16	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:6	17.72	2027	1.04	13.48	96	194	Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	18.16	1.24	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:7	17.72	2042	1.03	13.48	96	194	Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	18.8	1.28	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:7	17.72	2072	1.02	13.47	96	194	Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	19.37	1.32	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:7	17.72	2082	1.02	13.46	96	194	Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	19.85	1.35	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:7	17.72	2130	1.01	13.44	96	194	Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.11	1.37	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:7	17.72	2145	1	13.44	96	194	Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.19	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:7	17.72	2177	0.99	13.42	96	194	Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:8	17.72	2177	0.99	13.42	96	194	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:8	17.72	2244	0.98	13.43	96	194	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:8	17.72	2250	0.98	13.45	96	194	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:8	17.72	2271	0.98	13.46	96	194	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:8	17.72	2316	0.98	13.46	96	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:8	17.72	2373	0.98	13.45	96	194	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.68	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:9	17.72	2376	0.98	13.45	96	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.71	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:9	17.72	2407	0.98	13.44	96	194	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.73	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:9	17.72	2480	0.98	13.44	96	194	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:9	17.72	2480	0.98	13.45	96	194	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.77	20.21	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:9	17.72	2505	0.99	13.45	96	194	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.79	20.21	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:9	17.72	2582	0.99	13.44	96	194	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.8	20.22	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:10:9	17.72	2606	1	13.44	96	194	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.83	20.22	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:11:0	19.09	2642	1.01	13.44	96	194	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.83	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:11:0	19.09	2688	1.02	13.44	96	194	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.85	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:11:0	19.09	2777	1.04	13.45	96	194	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.88	20.21	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:11:0	19.09	2812	1.05	13.44	96	194	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.84	20.2	1.38	3.3	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:11:0	19.09	2812	1.07	13.45	96	194	Full Load	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.8	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:11:0	19.09	2931	1.1	13.46	96	194	Off Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.74	20.2	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:11:1	19.09	2978	1.13	13.46	96	194	Off Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.65	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:11:1	19.09	2875	1.16	13.47	96	194	Off Idle	60.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.59	20.21	1.38	3.3	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:11:1	10.9	3012	1.2	13.47	96	194	Off Idle	58.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.49	20.21	1.38	3.4	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:11:1	13.63	3110	1.24	13.46	96	194	Off Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.4	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:11:1	13.63	3122	1.28	13.47	96	194	Off Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.26	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:11:1	19.09	3118	1.34	13.44	96	194	Off Idle	52.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.1	20.2	1.38	3.4	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:11:1	19.09	3130	1.38	13.44	96	194	Off Idle	50.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.93	20.21	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:11:2	21.81	3066	1.42	13.45	96	194	Off Idle	49.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.82	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:11:2	24.54	3066	1.46	13.44	96	194	Off Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.72	20.22	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:11:2	27.27	3039	1.5	13.43	96	194	Off Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:11:2	29.99	2973	1.56	13.46	96	194	Off Idle	45.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.2	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:11:2	29.99	2973	1.58	13.46	96	194	Off Idle	44.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.51	20.2	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:11:2	32.72	2999	1.64	13.45	96	194	Off Idle	43.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.48	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:11:3	35.45	2987	1.67	13.46	96	194	Off Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:3	36.81	2959	1.7	13.45	96	194	Off Idle	42.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.45	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:3	36.81	2958	1.73	13.46	96	194	Off Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.49	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:3	36.81	2956	1.76	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.44	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:3	36.81	2956	1.79	13.47	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.46	20.21	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:3	36.81	2956	1.81	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.4	20.21	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:4	36.81	2944	1.84	13.46	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.03	Lean	1	14.7	-9.4	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:4	36.81	2951	1.85	13.45	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.38	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:4	36.81	2959	1.85	13.44	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.32	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:4	36.81	2959	1.86	13.43	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.33	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:4	36.81	2968	1.86	13.43	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.27	20.21	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:4	36.81	2973	1.87	13.43	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.27	20.21	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:4	36.81	2974	1.87	13.44	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.23	20.21	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:5	36.81	2982	1.88	13.44	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.24	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:5	36.81	2984	1.88	13.44	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.19	20.22	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:11:5	36.81	2980	1.89	13.45	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.11	20.22	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:5	36.81	2973	1.89	13.44	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.14	20.22	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:5	36.81	2975	1.89	13.44	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.07	20.19	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:5	36.81	2982	1.89	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.07	20.09	1.37	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:6	36.81	2982	1.9	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9	19.95	1.36	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:6	36.81	2984	1.9	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.98	19.65	1.34	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:6	36.81	2984	1.91	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.96	19.41	1.32	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:6	36.81	3005	1.91	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.94	19.13	1.3	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:6	36.81	2996	1.92	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.93	18.84	1.28	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:6	36.81	2978	1.92	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.93	18.52	1.26	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:6	36.81	2984	1.92	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.91	18.18	1.24	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:7	36.81	2984	1.93	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.94	17.69	1.21	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:7	36.81	2985	1.93	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.88	17.43	1.19	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:7	36.81	2984	1.94	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.87	17.22	1.17	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:7	36.81	2980	1.94	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.82	17.04	1.16	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:7	36.81	2982	1.95	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.84	16.9	1.15	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:7	36.81	2989	1.95	13.47	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.79	16.78	1.14	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:8	36.81	2988	1.95	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.72	16.61	1.13	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:8	36.81	2990	1.96	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.74	16.58	1.13	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:8	36.81	2994	1.96	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.67	16.46	1.12	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:8	36.81	2990	1.96	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.64	16.38	1.12	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:8	36.81	2985	1.96	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.65	16.32	1.11	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:8	36.81	2987	1.97	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.67	16.23	1.11	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:9	36.81	2986	1.97	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.63	16.17	1.1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:9	36.81	2977	1.97	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.64	16.11	1.1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:9	36.81	2969	1.97	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.65	16.06	1.09	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:9	36.81	2967	1.97	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.62	16.01	1.09	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:11:9	36.81	2958	1.98	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.61	15.97	1.09	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:11:9	36.81	2958	1.98	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.62	15.9	1.08	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:11:9	36.81	2953	1.98	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.57	15.86	1.08	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:0	36.81	2955	1.98	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.6	15.82	1.08	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:0	36.81	2962	1.98	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.58	15.77	1.07	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:0	36.81	2938	1.98	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.58	15.73	1.07	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:0	36.81	2973	1.98	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.53	15.66	1.07	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:0	36.81	2973	1.99	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.56	15.61	1.06	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:0	36.81	2974	1.99	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.52	15.59	1.06	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:1	36.81	2978	1.99	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.52	15.53	1.06	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:1	36.81	2976	1.99	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.48	15.5	1.06	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:1	36.81	2974	1.99	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.47	15.46	1.05	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:1	36.81	2977	1.99	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.2	Rich	1	14.7	-8.49	15.44	1.05	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:1	36.81	2976	1.99	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.22	Rich	1	14.7	-8.5	15.41	1.05	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:1	36.81	2979	1.99	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.7	-8.52	15.37	1.05	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:1	36.81	2976	1.99	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.46	15.34	1.05	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:2	36.81	2972	2	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.52	15.32	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:2	36.81	2970	2	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.7	-8.46	15.3	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:2	36.81	2964	2	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.49	15.28	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:2	36.81	2965	2	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-8.44	15.24	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:2	36.81	2965	2	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.5	15.22	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:2	36.81	2958	2	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.42	15.18	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:3	36.81	2970	2	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.46	15.15	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:3	36.81	2971	2	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.42	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:3	36.81	2972	2	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.42	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:3	36.81	3001	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.42	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:3	36.81	2982	2.01	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.45	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:3	36.81	2984	2.01	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-8.43	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:4	36.81	2981	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.46	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:4	36.81	2981	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.43	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:4	36.81	2983	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.7	-8.41	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:4	36.81	2984	2.01	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.7	-8.39	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:4	36.81	2984	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.4	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:4	36.81	2977	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.38	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:4	36.81	2978	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.41	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:5	36.81	2982	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.41	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:5	36.81	2982	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.43	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:5	36.81	2982	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.42	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:5	36.81	2976	2.02	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.48	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:5	36.81	2973	2.02	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.45	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:5	36.81	2978	2.02	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.49	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:6	36.81	2979	2.02	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.43	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:6	36.81	2983	2.02	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.47	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:6	36.81	2982	2.02	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.46	15.14	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:6	36.81	2983	2.02	13.45	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.7	-8.42	15.17	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:6	36.81	2985	2.02	13.45	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-8.42	15.19	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:6	36.81	2987	2.02	13.44	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.7	-8.44	15.2	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:6	36.81	2985	2.02	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.44	15.19	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:7	36.81	2984	2.02	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.41	15.16	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:7	36.81	2978	2.02	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.41	15.14	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:7	36.81	2968	2.02	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.4	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:7	36.81	2966	2.02	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.41	15.13	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:7	36.81	2966	2.02	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.44	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:7	36.81	2964	2.02	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.7	Lean	1	14.7	-8.43	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:8	36.81	2964	2.02	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.67	Lean	1	14.6	-8.43	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:8	36.81	2956	2.02	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.61	Lean	1	14.7	-8.44	15.05	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:8	36.81	2968	2.02	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.52	Lean	1	14.7	-8.41	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:8	36.81	2970	2.02	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.7	-8.42	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:8	36.81	2976	2.02	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.41	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:12:8	36.81	2994	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.42	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:9	36.81	2989	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.36	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:9	36.81	2989	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.44	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:9	36.81	2997	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.4	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:9	36.81	3000	2.01	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.47	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:9	36.81	3002	2.01	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.42	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:12:9	36.81	3004	2.01	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.48	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:12:9	36.81	3003	2.01	13.42	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.7	-8.41	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:0	36.81	3003	2.01	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.41	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:0	36.81	3006	2.01	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.4	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:0	36.81	3003	2.01	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.7	-8.44	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:0	36.81	2998	2.01	13.41	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.42	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:0	36.81	2998	2.01	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.65	Lean	1	14.7	-8.48	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:0	36.81	2992	2.01	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.71	Lean	1	14.7	-8.43	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:1	36.81	2989	2.01	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.5	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:1	36.81	2986	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.46	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:1	36.81	2982	2.01	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.47	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:1	36.81	2984	2.01	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.43	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:1	36.81	2985	2.01	13.47	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.46	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:1	36.81	2991	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.43	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:1	36.81	2992	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.44	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:2	36.81	2994	2.01	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.46	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:2	36.81	2994	2.01	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-8.43	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:2	36.81	2998	2.01	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.7	-8.42	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:2	36.81	2999	2.01	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.44	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:2	36.81	3002	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.44	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:2	36.81	3002	2.01	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.44	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:3	36.81	3001	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.46	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:3	36.81	3001	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.44	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:3	36.81	2999	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.48	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:3	36.81	2995	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.46	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:3	36.81	2993	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.47	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:3	36.81	2988	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.42	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:4	36.81	2984	2.01	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.47	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:4	36.81	2984	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.42	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:4	36.81	2984	2.01	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.47	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:4	36.81	2988	2.01	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.43	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:4	36.81	2988	2.01	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.45	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:4	36.81	2985	2.01	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.43	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:4	36.81	2992	2.01	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.44	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:5	36.81	2992	2.01	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.44	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:5	36.81	2989	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.43	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:5	36.81	2995	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.46	15.05	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:5	36.81	3003	2.01	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.7	-8.44	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:5	36.81	3003	2.01	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.7	-8.46	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:5	36.81	3004	2.01	13.42	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	-8.44	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:6	36.81	3005	2.01	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.7	-8.49	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:6	36.81	3005	2.01	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.47	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:6	36.81	3005	2.01	13.44	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.51	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:6	36.81	3009	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.51	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:6	36.81	3008	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.5	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:6	36.81	3005	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.46	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:6	36.81	3002	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.49	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:7	36.81	3003	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.45	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:7	36.81	3000	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.46	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:7	36.81	2997	2.01	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.48	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:7	36.81	2993	2.01	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.46	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:7	36.81	2993	2.01	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.48	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:13:7	36.81	2990	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.47	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:8	36.81	2990	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.47	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:8	36.81	2986	2.01	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.49	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:8	36.81	2984	2.01	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.49	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:8	36.81	2989	2.01	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.51	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:13:8	36.81	2988	2.01	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.5	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:8	36.81	2993	2.01	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.58	Lean	1	14.7	-8.46	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:9	36.81	3000	2.01	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.49	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:9	36.81	3000	2.01	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.5	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:9	36.81	3008	2.01	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.53	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:9	36.81	3011	2	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.6	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:9	36.81	3020	2	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.58	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:9	36.81	3021	2	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.61	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:13:9	36.81	3024	2	13.44	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.59	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:0	36.81	3019	2	13.45	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.63	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:0	36.81	3016	2	13.45	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.34	Rich	1	14.7	-8.62	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:0	36.81	3012	1.99	13.45	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.39	Rich	1	14.7	-8.65	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:0	36.81	3008	1.99	13.45	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.45	Rich	1	14.7	-8.65	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:0	36.81	3008	1.99	13.45	96	194	Off Idle	41.3	0	2	132	944 Turbo	0.52	Rich	1	14.7	-8.67	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:0	36.81	3002	1.99	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.68	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:1	36.81	2988	1.98	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.67	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:1	36.81	2988	1.98	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.7	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:1	36.81	2989	1.98	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.69	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:1	36.81	2990	1.98	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.73	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:1	36.81	2990	1.98	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.73	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:1	36.81	2990	1.97	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-8.77	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:1	36.81	2991	1.97	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.78	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:2	36.81	2990	1.97	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.76	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:2	36.81	2992	1.97	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.79	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:2	36.81	2996	1.97	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.79	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:2	36.81	3004	1.96	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.76	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:2	36.81	3004	1.96	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.79	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:2	36.81	3007	1.96	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.74	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:3	36.81	2997	1.96	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.7	-8.78	14.77	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:3	36.81	3010	1.96	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.7	-8.74	14.75	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:3	36.81	3014	1.96	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.7	-8.8	14.75	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:3	36.81	3017	1.96	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.79	14.75	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:3	36.81	3014	1.96	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.82	14.75	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:3	36.81	3011	1.96	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.8	14.77	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:4	36.81	3011	1.96	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.83	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:4	36.81	3011	1.96	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.75	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:4	36.81	3011	1.96	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.77	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:4	36.81	3008	1.95	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.73	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:4	36.81	3005	1.95	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.83	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:4	36.81	3004	1.95	13.47	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.84	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:14:4	36.81	3000	1.95	13.47	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.24	Rich	1	14.7	-8.87	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:5	36.81	2994	1.95	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.3	Rich	1	14.7	-8.94	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:5	36.81	2992	1.95	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.36	Rich	1	14.7	-8.94	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:5	36.81	2988	1.94	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.94	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:5	36.81	2988	1.94	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.7	-8.95	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:5	36.81	2982	1.94	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.98	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:5	36.81	2985	1.94	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.98	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:6	36.81	2986	1.93	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.96	15.13	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:14:6	36.81	2987	1.93	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:6	36.81	2992	1.93	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.01	15.16	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:6	36.81	2994	1.92	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.03	15.16	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:6	36.81	3001	1.92	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.12	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:6	36.81	3003	1.91	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.11	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:14:6	36.81	3003	1.91	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.19	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:7	36.81	3002	1.91	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.15	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:7	36.81	2998	1.9	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.21	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:7	36.81	2997	1.9	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.18	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:7	36.81	2997	1.9	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-9.24	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:7	36.81	2990	1.89	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-9.19	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:7	36.81	2990	1.89	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-9.23	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:8	36.81	2989	1.89	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.7	-9.25	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:8	36.81	2991	1.88	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.25	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:8	36.81	2998	1.88	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.7	-9.28	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:8	36.81	2997	1.88	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	-9.27	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:8	36.81	2997	1.88	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-9.31	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:8	36.81	2998	1.87	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.7	-9.28	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:9	36.81	3005	1.87	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.29	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:9	36.81	3006	1.87	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.27	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:9	36.81	3007	1.86	13.47	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.29	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:9	36.81	3006	1.86	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-9.29	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:9	36.81	2997	1.86	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.31	Rich	1	14.7	-9.31	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:9	36.81	2997	1.86	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.7	-9.29	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:14:9	36.81	2994	1.86	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	-9.32	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:0	36.81	2990	1.86	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.34	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:0	36.81	2990	1.86	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-9.31	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:0	36.81	2980	1.86	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.38	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:0	36.81	2977	1.85	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.35	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:0	36.81	2977	1.85	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.38	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:0	36.81	2978	1.85	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.36	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:1	36.81	2974	1.85	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.42	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:1	36.81	2966	1.85	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.39	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:1	36.81	2966	1.85	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.44	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:1	36.81	2967	1.85	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-9.46	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:1	36.81	2961	1.85	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-9.45	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:1	36.81	2963	1.84	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-9.45	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:1	36.81	2963	1.84	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.7	-9.41	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:2	36.81	2964	1.84	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.7	-9.44	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:2	36.81	2965	1.84	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.4	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:2	36.81	2965	1.84	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.34	Rich	1	14.7	-9.46	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:2	36.81	2961	1.83	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.44	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:2	36.81	2961	1.83	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-9.5	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:15:2	36.81	2962	1.83	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.48	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:3	36.81	2971	1.82	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.52	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:3	36.81	2972	1.82	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.57	14.81	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:3	36.81	2984	1.82	13.47	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.55	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:3	36.81	2977	1.81	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-9.58	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:3	36.81	2976	1.81	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-9.61	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:3	36.81	2978	1.81	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-9.61	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:4	36.81	2976	1.8	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.57	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:4	36.81	2978	1.8	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-9.6	14.9	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:4	36.81	2982	1.8	13.45	97	193	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.7	-9.6	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:4	36.81	2982	1.79	13.45	97	193	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.7	-9.6	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:4	36.81	2984	1.79	13.45	97	193	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.61	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:4	36.81	2982	1.79	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.65	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:4	36.81	2982	1.79	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.65	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:5	36.81	2979	1.78	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-9.66	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:5	36.81	2979	1.78	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-9.68	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:5	36.81	2983	1.78	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.67	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:5	36.81	2981	1.78	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-9.69	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:5	36.81	2972	1.78	13.44	96	193	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-9.71	15.05	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:5	36.81	2971	1.78	13.45	96	193	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-9.73	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:15:6	36.81	2968	1.78	13.45	96	193	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.7	-9.72	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:6	36.81	2960	1.77	13.44	96	193	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.76	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:6	36.81	2961	1.77	13.45	96	193	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.7	-9.73	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:6	36.81	2962	1.77	13.44	96	193	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.74	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:6	36.81	2966	1.77	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.74	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:6	36.81	2970	1.77	13.45	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.72	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:6	36.81	2972	1.77	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.72	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:7	36.81	2973	1.77	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-9.72	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:7	36.81	2962	1.77	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-9.74	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:7	36.81	2975	1.76	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-9.72	14.9	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:7	36.81	2975	1.76	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.77	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:7	36.81	2976	1.76	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.77	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:7	36.81	3000	1.76	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.75	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:8	36.81	3000	1.76	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.75	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:8	36.81	2970	1.76	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-9.77	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:8	36.81	2967	1.76	13.43	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	-9.76	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:15:8	36.81	2946	1.76	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-9.76	14.9	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:15:8	36.81	2956	1.75	13.44	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.7	-9.77	14.94	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:15:8	36.81	2957	1.75	13.46	96	194	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	-9.78	14.96	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:15:9	36.81	2958	1.75	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.75	15	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:15:9	36.81	2959	1.75	13.46	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-9.79	15.01	1.02	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:15:9	36.81	2952	1.75	13.44	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.77	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:15:9	36.81	2947	1.75	13.45	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.78	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:15:9	36.81	2947	1.74	13.45	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.83	15.03	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:15:9	36.81	2934	1.74	13.44	97	194	Full Load	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.85	15.06	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:15:9	36.81	2949	1.74	13.46	97	194	Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.85	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:16:0	36.81	2955	1.74	13.46	97	193	Idle	41.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.85	15.07	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:16:0	36.81	2957	1.73	13.46	97	193	Idle	41.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.87	15.06	1.03	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:16:0	36.81	2970	1.73	13.45	96	193	Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.7	-9.9	15.02	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:16:0	36.81	2962	1.73	13.44	96	193	Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.87	15	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:16:0	36.81	2962	1.73	13.44	96	193	Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.88	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:0	34.08	2923	1.72	13.44	97	193	Idle	41.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.89	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:1	28.63	2918	1.72	13.45	97	194	Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.7	-9.9	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:1	23.18	2901	1.72	13.45	97	194	Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.9	14.93	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:1	19.09	2910	1.72	13.45	97	194	Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.9	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:1	19.09	2920	1.71	13.45	96	194	Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.9	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:1	19.09	2923	1.71	13.46	96	194	Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.93	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:1	19.09	2911	1.71	13.46	96	193	Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.94	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:1	19.09	2906	1.71	13.46	96	193	Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.94	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:2	19.09	2880	1.71	13.46	96	193	Idle	41.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.93	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:2	19.09	2882	1.7	13.44	97	193	Idle	41.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.93	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:2	19.09	2882	1.7	13.46	97	193	Idle	41.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.91	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:2	19.09	2882	1.7	13.44	97	193	Idle	41.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.86	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:2	19.09	2890	1.7	13.46	97	193	Idle	41.2	0	2	132	944 Turbo	0.5	Rich	1	14.7	-9.83	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:2	19.09	2901	1.7	13.45	97	193	Idle	41	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.77	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:3	19.09	2904	1.7	13.46	97	193	Idle	40.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.73	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:3	19.09	2914	1.7	13.46	97	193	Idle	40.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.72	14.92	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:3	19.09	2942	1.7	13.46	97	193	Idle	40.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.67	14.97	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:3	19.09	2934	1.7	13.46	97	193	Idle	40.9	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.67	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:3	19.09	2928	1.7	13.46	97	193	Idle	41	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.65	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:3	19.09	2926	1.7	13.45	97	193	Idle	41	0	2	132	944 Turbo	0.17	Lean	1	14.7	-9.64	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:4	19.09	2897	1.7	13.45	96	193	Idle	41	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.64	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:4	19.09	2897	1.7	13.46	96	193	Idle	41.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.63	15.05	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:4	19.09	2906	1.7	13.44	96	193	Idle	41.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.64	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:4	19.09	2894	1.7	13.46	97	193	Idle	41.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.61	15.05	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:4	19.09	2888	1.7	13.45	97	193	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:4	19.09	2884	1.7	13.44	97	193	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.63	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:4	19.09	2870	1.7	13.44	97	193	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:16:5	19.09	2862	1.7	13.45	97	193	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	15.28	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:5	19.09	2862	1.7	13.44	97	193	Idle	42	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	15.54	1.06	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:5	19.09	2860	1.7	13.45	97	193	Idle	42.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	15.96	1.09	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:5	19.09	2859	1.7	13.45	97	194	Idle	42.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	16.45	1.12	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:5	19.09	2860	1.7	13.45	97	194	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	16.97	1.16	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:5	19.09	2862	1.7	13.46	96	194	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	17.5	1.19	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:6	19.09	2868	1.7	13.46	96	194	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.61	18.29	1.25	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:6	19.09	2861	1.7	13.46	96	194	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.57	18.79	1.28	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:6	19.09	2878	1.7	13.45	97	194	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.57	19.26	1.31	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:6	19.09	2878	1.7	13.45	97	194	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	19.67	1.34	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:6	19.09	2900	1.7	13.46	97	194	Idle	42.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.57	19.98	1.36	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:6	19.09	2876	1.7	13.46	97	193	Idle	42.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.17	1.37	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:6	19.09	2875	1.7	13.45	97	193	Idle	42.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:7	19.09	2856	1.69	13.46	97	193	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:7	19.09	2864	1.69	13.46	97	194	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.6	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:7	19.09	2878	1.69	13.45	97	194	Idle	43	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:7	19.09	2864	1.69	13.45	97	194	Idle	43.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:7	19.09	2846	1.69	13.45	97	193	Idle	43.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:7	19.09	2840	1.69	13.45	97	193	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:8	19.09	2835	1.69	13.44	96	193	Idle	44.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:8	19.09	2834	1.68	13.45	96	193	Idle	44.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:8	19.09	2829	1.68	13.44	96	193	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:8	19.09	2829	1.68	13.45	97	193	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:8	19.09	2829	1.68	13.46	97	193	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:8	19.09	2828	1.68	13.44	97	193	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:9	19.09	2828	1.67	13.46	97	193	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:9	19.09	2828	1.67	13.47	97	193	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:9	19.09	2828	1.67	13.47	97	193	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:9	19.09	2826	1.66	13.47	97	193	Idle	45.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:9	19.09	2825	1.66	13.47	97	193	Idle	45.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:9	19.09	2824	1.66	13.46	97	193	Idle	45.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:16:9	19.09	2820	1.66	13.45	97	193	Idle	45.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:0	19.09	2815	1.66	13.46	97	193	Idle	46.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:0	19.09	2816	1.65	13.46	96	193	Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:0	19.09	2810	1.65	13.46	96	193	Idle	46.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.75	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:0	19.09	2806	1.65	13.46	96	193	Idle	46.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:0	19.09	2782	1.65	13.46	97	193	Idle	46.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:0	19.09	2791	1.65	13.45	97	193	Idle	46.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:1	19.09	2795	1.64	13.46	96	193	Idle	46.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:1	19.09	2792	1.64	13.45	96	193	Idle	47	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:1	19.09	2792	1.64	13.44	96	193	Idle	47.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:1	19.09	2790	1.64	13.45	97	193	Idle	47.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:1	19.09	2790	1.64	13.45	97	193	Idle	47.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:1	19.09	2788	1.64	13.46	97	193	Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:1	19.09	2788	1.63	13.46	97	193	Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:2	19.09	2789	1.63	13.46	97	193	Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:2	19.09	2787	1.63	13.45	97	193	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:2	19.09	2787	1.63	13.46	97	193	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:2	19.09	2782	1.63	13.44	97	193	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:2	19.09	2779	1.63	13.45	97	193	Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.77	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:2	19.09	2779	1.63	13.44	97	193	Idle	47.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.76	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:3	19.09	2774	1.62	13.45	97	193	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:3	19.09	2774	1.62	13.45	96	194	Idle	47.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:3	19.09	2774	1.62	13.45	96	194	Idle	48.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.77	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:3	19.09	2754	1.62	13.45	96	194	Idle	48.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:3	19.09	2754	1.62	13.44	96	194	Idle	48.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:3	19.09	2758	1.62	13.45	97	193	Idle	48.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:4	19.09	2756	1.62	13.44	97	193	Idle	49	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:17:4	19.09	2755	1.61	13.45	97	193	Idle	49.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:4	19.09	2753	1.61	13.45	97	193	Idle	49.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.86	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:4	19.09	2752	1.61	13.45	97	193	Idle	49.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:4	19.09	2752	1.61	13.45	97	193	Idle	49.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:4	19.09	2749	1.61	13.46	97	193	Idle	50	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:4	19.09	2748	1.6	13.44	97	193	Idle	50.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.88	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:5	19.09	2758	1.6	13.45	97	193	Idle	50.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:5	19.09	2746	1.6	13.46	97	193	Idle	50.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.19	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:5	19.09	2746	1.6	13.46	97	193	Idle	50.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.19	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:5	19.09	2730	1.59	13.46	97	193	Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.19	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:5	19.09	2736	1.59	13.47	96	193	Idle	50.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.19	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:5	19.09	2735	1.59	13.46	96	193	Idle	50.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.19	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:6	19.09	2730	1.59	13.46	97	193	Idle	51.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.2	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:6	19.09	2726	1.58	13.46	97	193	Idle	51.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:6	19.09	2720	1.58	13.46	97	193	Idle	51.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:6	19.09	2720	1.58	13.46	97	193	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.2	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:6	19.09	2716	1.57	13.46	97	193	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.98	20.2	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:6	19.09	2692	1.57	13.44	97	193	Idle	51.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.98	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:6	19.09	2701	1.57	13.46	97	193	Idle	51.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:7	19.09	2710	1.57	13.45	97	193	Idle	51.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:7	19.09	2709	1.57	13.45	97	193	Idle	51.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:7	19.09	2709	1.56	13.45	97	193	Idle	52	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.98	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:7	19.09	2689	1.56	13.44	97	193	Idle	52	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:7	19.09	2706	1.56	13.45	97	193	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:7	19.09	2704	1.56	13.44	96	193	Idle	52.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:8	19.09	2704	1.55	13.45	96	193	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:8	19.09	2700	1.55	13.43	96	193	Idle	52.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:8	19.09	2697	1.55	13.45	96	193	Idle	52.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:8	19.09	2697	1.55	13.45	96	193	Idle	52.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:8	19.09	2694	1.54	13.45	97	193	Idle	52.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.01	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:8	19.09	2691	1.54	13.44	97	193	Idle	53.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:9	19.09	2690	1.54	13.44	97	193	Idle	53.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:9	19.09	2686	1.53	13.45	97	193	Idle	53.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:9	19.09	2682	1.53	13.45	97	193	Idle	53.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:9	19.09	2680	1.53	13.46	97	193	Idle	53.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:9	19.09	2680	1.53	13.44	96	193	Idle	54	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:9	19.09	2675	1.53	13.45	96	193	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:17:9	19.09	2675	1.53	13.44	96	193	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:0	19.09	2672	1.52	13.45	96	193	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:0	19.09	2672	1.52	13.46	96	193	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:0	19.09	2670	1.52	13.46	96	193	Idle	54.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:0	19.09	2670	1.51	13.46	97	193	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.08	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:0	19.09	2668	1.51	13.45	97	193	Idle	54.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:0	19.09	2666	1.51	13.46	97	193	Idle	54.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:1	19.09	2666	1.51	13.45	97	193	Idle	54.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:1	19.09	2652	1.51	13.45	97	193	Idle	54.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:1	19.09	2659	1.5	13.46	97	193	Idle	55	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:1	19.09	2655	1.5	13.46	97	193	Idle	55.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:1	19.09	2654	1.5	13.44	97	193	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:1	19.09	2648	1.5	13.45	97	193	Idle	55.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:1	19.09	2646	1.5	13.45	97	193	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:2	19.09	2641	1.5	13.46	97	193	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:2	19.09	2650	1.5	13.45	97	193	Idle	56	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:2	19.09	2637	1.5	13.45	97	193	Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:2	19.09	2634	1.49	13.47	97	193	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:2	19.09	2624	1.49	13.46	97	193	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:2	19.09	2632	1.49	13.46	97	193	Idle	56.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:3	19.09	2632	1.49	13.47	97	193	Idle	56.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:18:3	19.09	2632	1.49	13.46	97	193	Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:3	19.09	2631	1.48	13.45	97	193	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:3	19.09	2630	1.48	13.45	97	193	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:3	19.09	2630	1.48	13.44	97	193	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:3	19.09	2628	1.48	13.44	97	193	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:4	19.09	2626	1.48	13.45	96	193	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:4	19.09	2612	1.48	13.45	96	193	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:4	19.09	2618	1.47	13.45	96	193	Idle	56.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:4	19.09	2616	1.47	13.45	97	193	Idle	57	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:4	19.09	2622	1.47	13.45	97	193	Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:4	19.09	2606	1.47	13.45	97	193	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:4	19.09	2604	1.47	13.45	97	193	Idle	57.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.25	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:5	19.09	2598	1.47	13.44	97	193	Idle	57.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:5	19.09	2594	1.46	13.44	97	193	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:5	19.09	2590	1.46	13.46	97	193	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:5	19.09	2590	1.46	13.45	97	193	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:5	19.09	2585	1.46	13.46	96	193	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:5	19.09	2582	1.46	13.45	96	193	Idle	57.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:6	19.09	2582	1.46	13.46	96	193	Idle	58	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:6	19.09	2580	1.45	13.46	97	193	Idle	58.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:6	19.09	2578	1.45	13.45	97	193	Idle	58.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:6	19.09	2576	1.45	13.45	97	193	Idle	58.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:6	19.09	2576	1.45	13.47	97	193	Idle	58.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:6	19.09	2576	1.44	13.45	97	193	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:6	19.09	2577	1.44	13.45	97	193	Idle	58.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:7	19.09	2576	1.44	13.45	96	193	Idle	59.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:7	19.09	2578	1.43	13.45	96	193	Idle	59.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:7	19.09	2576	1.43	13.44	96	193	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:7	19.09	2576	1.43	13.45	97	193	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:7	19.09	2566	1.43	13.44	97	193	Idle	59.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:7	19.09	2572	1.42	13.45	97	193	Idle	59.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:8	19.09	2551	1.42	13.45	97	193	Idle	60.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:8	19.09	2561	1.42	13.44	97	193	Idle	60.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:8	19.09	2576	1.42	13.46	97	193	Idle	60.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:8	19.09	2563	1.42	13.45	97	193	Idle	60.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:8	19.09	2563	1.41	13.46	97	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:8	19.09	2577	1.41	13.45	96	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:9	19.09	2549	1.41	13.45	96	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:9	19.09	2549	1.41	13.46	96	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:9	19.09	2524	1.4	13.45	97	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:9	19.09	2539	1.4	13.44	97	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:9	19.09	2535	1.4	13.44	97	193	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:9	19.09	2534	1.4	13.45	97	193	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.2	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:18:9	19.09	2532	1.4	13.44	97	193	Idle	61.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:0	19.09	2521	1.4	13.44	96	193	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:0	19.09	2525	1.4	13.44	96	193	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:0	19.09	2522	1.39	13.45	96	193	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:0	19.09	2519	1.39	13.44	96	193	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:0	19.09	2518	1.39	13.43	97	193	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:0	19.09	2517	1.39	13.44	97	193	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:1	19.09	2518	1.39	13.44	96	193	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:1	19.09	2508	1.38	13.44	96	193	Idle	61.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:1	19.09	2508	1.38	13.44	96	193	Idle	61.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:1	19.09	2516	1.38	13.45	97	193	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:1	19.09	2516	1.38	13.45	97	193	Idle	62.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:1	19.09	2513	1.38	13.45	97	193	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:1	19.09	2513	1.38	13.46	97	193	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:2	19.09	2512	1.38	13.44	97	193	Idle	63.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:19:2	19.09	2509	1.37	13.45	97	193	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:2	19.09	2504	1.37	13.45	97	193	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:2	19.09	2504	1.37	13.45	97	193	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:2	19.09	2503	1.37	13.44	97	193	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:2	19.09	2500	1.37	13.44	97	193	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:3	19.09	2498	1.36	13.45	97	193	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:3	19.09	2493	1.36	13.45	97	193	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:3	19.09	2490	1.36	13.46	97	193	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:3	19.09	2490	1.36	13.45	97	193	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:3	19.09	2486	1.35	13.45	97	193	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:3	19.09	2484	1.35	13.44	96	193	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:4	19.09	2483	1.35	13.45	96	193	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.32	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:4	19.09	2480	1.35	13.46	96	193	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:4	19.09	2479	1.35	13.47	97	193	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:4	19.09	2478	1.35	13.45	97	193	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:4	19.09	2474	1.34	13.46	97	193	Idle	64.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:4	19.09	2473	1.34	13.45	97	193	Idle	64.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:4	19.09	2465	1.34	13.45	97	193	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:5	19.09	2465	1.34	13.45	97	193	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:5	19.09	2467	1.34	13.45	97	193	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:5	19.09	2467	1.34	13.44	97	193	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:5	19.09	2461	1.34	13.46	97	193	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:5	19.09	2457	1.33	13.45	97	193	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:5	19.09	2453	1.33	13.45	97	193	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:6	19.09	2453	1.33	13.45	97	193	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:6	19.09	2450	1.33	13.45	97	193	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:6	19.09	2447	1.33	13.45	97	193	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:6	19.09	2447	1.33	13.46	97	193	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:6	19.09	2445	1.32	13.44	97	193	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:6	19.09	2434	1.32	13.45	97	193	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:6	19.09	2461	1.32	13.44	97	193	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:7	19.09	2450	1.32	13.45	97	193	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:7	19.09	2440	1.32	13.44	97	193	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:7	19.09	2437	1.31	13.45	97	193	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:7	19.09	2436	1.31	13.44	97	193	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:7	17.72	2415	1.31	13.46	97	193	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:7	17.72	2431	1.31	13.46	96	193	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:8	17.72	2431	1.31	13.46	96	193	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:8	17.72	2427	1.3	13.45	96	193	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:8	17.72	2423	1.3	13.46	97	193	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:8	17.72	2419	1.3	13.47	97	193	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:8	17.72	2418	1.3	13.46	97	193	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:8	17.72	2414	1.29	13.46	97	193	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:9	17.72	2411	1.29	13.45	97	193	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:9	17.72	2410	1.29	13.45	97	193	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:9	17.72	2389	1.28	13.43	97	193	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:9	17.72	2405	1.28	13.44	97	193	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:9	17.72	2405	1.28	13.45	97	193	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:9	17.72	2412	1.27	13.45	97	193	Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:19:9	17.72	2400	1.27	13.46	97	193	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.2	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:0	17.72	2399	1.27	13.46	97	193	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.19	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:0	17.72	2399	1.26	13.45	97	193	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.19	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:0	17.72	2388	1.26	13.46	97	193	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.19	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:0	17.72	2394	1.26	13.45	97	193	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:0	17.72	2390	1.25	13.45	97	193	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.19	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:0	17.72	2389	1.25	13.46	97	193	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.19	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:1	17.72	2388	1.24	13.45	97	193	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.2	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:1	17.72	2387	1.24	13.45	97	193	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.2	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:20:1	17.72	2386	1.24	13.45	97	193	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:1	17.72	2380	1.23	13.44	97	193	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:1	17.72	2389	1.23	13.44	97	193	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:1	17.72	2378	1.23	13.46	97	193	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:1	17.72	2378	1.22	13.44	97	193	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:2	17.72	2373	1.22	13.44	97	193	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:2	17.72	2368	1.22	13.46	97	193	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:2	17.72	2368	1.22	13.44	97	193	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:2	17.72	2366	1.22	13.46	97	193	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:2	17.72	2366	1.21	13.45	97	193	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:2	17.72	2365	1.21	13.45	97	193	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:3	17.72	2363	1.21	13.45	97	193	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:3	17.72	2363	1.21	13.47	97	193	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:3	17.72	2361	1.2	13.46	97	193	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:3	17.72	2360	1.2	13.46	97	193	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:3	17.72	2360	1.2	13.46	96	193	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:3	17.72	2356	1.2	13.44	96	193	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:4	17.72	2334	1.2	13.45	97	193	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:4	17.72	2344	1.19	13.46	97	193	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:4	17.72	2344	1.19	13.46	97	193	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:4	17.72	2349	1.19	13.47	97	193	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:4	17.72	2329	1.19	13.47	97	193	Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:4	17.72	2334	1.19	13.46	97	193	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:4	17.72	2332	1.19	13.46	97	193	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:5	17.72	2328	1.18	13.45	97	193	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:5	17.72	2328	1.18	13.44	97	193	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:5	17.72	2314	1.18	13.45	97	193	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:5	17.72	2320	1.18	13.45	97	193	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:5	17.72	2314	1.18	13.44	97	193	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:5	17.72	2314	1.17	13.45	97	193	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:6	17.72	2311	1.17	13.45	97	193	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:6	17.72	2305	1.17	13.45	97	193	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:6	17.72	2302	1.17	13.45	97	193	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:6	17.72	2302	1.16	13.45	97	193	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:6	17.72	2301	1.16	13.46	97	193	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:6	17.72	2298	1.16	13.44	96	193	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:6	17.72	2298	1.16	13.44	96	193	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:7	17.72	2296	1.15	13.43	97	193	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:7	17.72	2294	1.15	13.41	97	193	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:7	17.72	2293	1.15	13.39	97	193	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:7	17.72	2292	1.15	13.38	97	193	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:7	17.72	2288	1.15	13.37	97	193	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:7	17.72	2284	1.14	13.38	97	193	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:8	17.72	2281	1.14	13.39	97	193	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:8	17.72	2281	1.14	13.4	97	193	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:8	17.72	2280	1.13	13.38	97	193	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:8	17.72	2280	1.13	13.39	97	193	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:8	17.72	2280	1.13	13.4	97	193	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:8	17.72	2281	1.13	13.38	97	193	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:9	17.72	2280	1.13	13.4	97	193	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:9	17.72	2280	1.13	13.4	97	193	Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:9	17.72	2277	1.12	13.41	97	193	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:9	17.72	2272	1.12	13.4	97	193	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:9	17.72	2267	1.12	13.4	97	193	Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:9	17.72	2267	1.12	13.4	97	193	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:20:9	17.72	2262	1.11	13.4	97	193	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:0	17.72	2254	1.11	13.39	97	193	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:0	17.72	2247	1.11	13.4	97	193	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:21:0	17.72	2244	1.11	13.41	97	193	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:0	17.72	2238	1.1	13.39	97	193	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:0	17.72	2216	1.1	13.4	97	193	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:0	17.72	2223	1.1	13.41	97	193	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:1	17.72	2226	1.1	13.41	97	193	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:1	17.72	2218	1.09	13.39	97	193	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:1	17.72	2218	1.09	13.39	97	193	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:1	17.72	2212	1.09	13.4	97	193	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:1	17.72	2205	1.09	13.39	97	193	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:1	17.72	2183	1.08	13.39	97	193	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:1	17.72	2190	1.08	13.41	97	193	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:2	17.72	2192	1.08	13.42	97	193	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:2	17.72	2183	1.08	13.42	97	193	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:2	17.72	2180	1.08	13.42	97	193	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.25	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:2	17.72	2177	1.07	13.41	97	193	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:2	17.72	2170	1.07	13.4	97	193	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:2	17.72	2163	1.07	13.38	97	193	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.24	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:3	17.72	2157	1.07	13.37	97	193	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:3	17.72	2157	1.07	13.37	97	193	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:3	17.72	2151	1.06	13.38	97	193	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:3	17.72	2151	1.06	13.39	97	193	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:3	17.72	2146	1.06	13.41	97	193	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:3	17.72	2142	1.06	13.41	97	193	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:4	17.72	2138	1.05	13.42	97	193	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:4	17.72	2136	1.05	13.42	97	193	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:4	17.72	2128	1.05	13.42	97	193	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:4	17.72	2104	1.05	13.41	97	193	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:4	17.72	2116	1.05	13.4	97	193	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:4	17.72	2113	1.04	13.38	97	193	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:4	17.72	2106	1.04	13.37	97	193	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:5	17.72	2101	1.04	13.36	97	193	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:5	17.72	2098	1.03	13.36	97	193	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:5	17.72	2089	1.03	13.37	97	193	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:5	17.72	2084	1.03	13.39	97	193	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:5	17.72	2071	1.03	13.4	97	193	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:5	17.72	2071	1.02	13.41	97	193	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:6	17.72	2061	1.02	13.42	97	193	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:6	17.72	2054	1.02	13.42	97	193	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:6	17.72	2044	1.02	13.42	97	193	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:6	17.72	2041	1.02	13.41	97	193	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:6	17.72	2034	1.02	13.41	97	193	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:6	17.72	2031	1.02	13.4	97	193	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:6	17.72	2022	1.02	13.39	97	193	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:7	17.72	2010	1.02	13.39	97	193	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:7	17.72	2003	1.02	13.38	97	193	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:7	17.72	2003	1.02	13.38	97	193	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:7	17.72	1994	1.02	13.39	96	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:7	17.72	1991	1.02	13.4	96	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:7	17.72	1979	1.02	13.4	97	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:8	17.72	1979	1.02	13.41	97	193	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:8	17.72	1968	1.02	13.41	97	193	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:8	17.72	1957	1.02	13.41	97	193	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:8	17.72	1957	1.02	13.4	97	193	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:8	17.72	1938	1.02	13.39	97	193	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:8	17.72	1934	1.02	13.38	97	193	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:9	17.72	1934	1.02	13.38	97	193	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:9	17.72	1922	1.02	13.37	97	193	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:9	17.72	1910	1.02	13.37	97	193	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:21:9	17.72	1902	1.01	13.37	97	193	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:9	17.72	1898	1.01	13.38	97	193	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.23	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:9	17.72	1886	1.01	13.39	97	193	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:21:9	17.72	1878	1.01	13.39	97	193	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:0	17.72	1878	1.01	13.4	97	193	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:0	17.72	1866	1.02	13.4	97	193	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:0	17.72	1851	1.02	13.39	97	193	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.21	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:0	17.72	1851	1.02	13.38	97	193	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:0	17.72	1838	1.02	13.37	97	193	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:0	17.72	1821	1.02	13.37	97	193	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:1	17.72	1813	1.02	13.37	97	193	Idle	78.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:1	17.72	1813	1.02	13.37	97	193	Idle	78.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.21	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:1	17.72	1798	1.03	13.39	97	193	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:1	17.72	1793	1.03	13.4	97	193	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:1	17.72	1786	1.03	13.4	97	193	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:1	17.72	1763	1.03	13.4	97	193	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.8	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:1	17.72	1732	1.03	13.4	97	193	Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.9	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:2	17.72	1721	1.03	13.4	97	193	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.22	1.38	3.9	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:2	17.72	1710	1.04	13.38	97	193	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.22	1.38	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:2	17.72	1675	1.04	13.37	97	193	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.22	1.38	4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:2	17.72	1650	1.04	13.38	97	193	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:2	17.72	1650	1.04	13.39	97	193	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:2	17.72	1612	1.05	13.39	97	193	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:3	17.72	1601	1.05	13.38	97	193	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	4.1	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:3	17.72	1576	1.05	13.39	97	193	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.22	1.38	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:3	17.72	1563	1.05	13.38	97	193	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.23	1.38	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:3	17.72	1532	1.06	13.38	97	193	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.21	1.38	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:3	17.72	1506	1.07	13.4	97	193	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:3	17.72	1498	1.07	13.39	97	193	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.21	1.38	4.2	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:4	17.72	1472	1.08	13.39	97	193	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.22	1.38	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:4	17.72	1458	1.08	13.37	97	193	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	20.22	1.38	4.3	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:4	17.72	1445	1.09	13.39	97	193	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.22	1.38	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:4	17.72	1391	1.09	13.37	97	193	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.26	20.22	1.38	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:4	19.09	1391	1.1	13.38	97	193	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.18	20.22	1.38	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:4	19.09	1363	1.11	13.39	97	193	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.17	20.22	1.38	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:4	19.09	1335	1.12	13.38	97	193	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.1	20.23	1.38	4.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:5	19.09	1335	1.12	13.39	97	193	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:5	19.09	1296	1.13	13.4	97	193	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	20.22	1.38	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:5	19.09	1296	1.14	13.4	97	193	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	20.22	1.38	4.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:5	16.36	1249	1.15	13.41	97	193	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.68	20.22	1.38	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:5	16.36	1248	1.15	13.41	97	193	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.63	20.22	1.38	4.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:22:5	16.36	1231	1.16	13.39	97	193	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.46	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:22:6	16.36	1231	1.17	13.39	97	193	Idle	68.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.36	20.21	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:22:6	16.36	1201	1.18	13.39	97	193	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.28	20.21	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:22:6	16.36	1150	1.18	13.39	97	193	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.12	20.22	1.38	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:22:6	16.36	1150	1.19	13.41	97	193	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.22	1.38	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:22:6	16.36	1160	1.19	13.41	97	193	Idle	69	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.99	20.22	1.38	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:22:6	16.36	1171	1.19	13.4	96	193	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.88	20.22	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:22:6	16.36	1175	1.2	13.39	96	193	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.84	20.22	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:22:7	16.36	1179	1.2	13.4	97	193	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.79	20.22	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:22:7	16.36	1191	1.2	13.38	97	193	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.72	20.22	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:22:7	16.36	1187	1.2	13.38	97	193	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.69	20.22	1.38	4.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:22:7	14.99	1187	1.19	13.38	97	193	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.69	20.22	1.38	4.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:22:7	14.99	1214	1.19	13.37	97	193	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.66	20.21	1.38	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:22:7	14.99	1214	1.18	13.39	97	193	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.68	20.21	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:22:8	14.99	1214	1.17	13.38	97	193	Idle	76.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.71	20.21	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:22:8	14.99	1218	1.17	13.38	97	193	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.75	20.2	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:22:8	13.63	1222	1.16	13.38	97	193	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.82	20.21	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:22:8	13.63	1220	1.14	13.37	97	193	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.91	20.2	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:22:8	13.63	1238	1.12	13.37	97	193	Idle	81.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.97	20.2	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:27:22:8	13.63	1238	1.11	13.39	97	193	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.03	20.21	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:27:22:9	13.63	1219	1.11	13.37	97	193	Idle	83.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.05	20.21	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:22:9	13.63	1214	1.09	13.36	97	193	Idle	84.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.09	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:22:9	13.63	1214	1.09	13.38	97	193	Idle	85.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.12	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:22:9	12.27	1187	1.07	13.38	97	193	Idle	85.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.17	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:22:9	12.27	1197	1.06	13.38	97	193	Idle	86.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.2	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:22:9	12.27	1197	1.05	13.38	97	193	Idle	86.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.22	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:22:9	13.63	1190	1.03	13.38	97	193	Idle	86.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.23	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:0	13.63	1168	1.02	13.39	97	193	Idle	86.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.25	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:0	13.63	1155	1.01	13.39	97	193	Idle	86.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.27	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:0	13.63	1155	1	13.38	97	193	Idle	87	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.29	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:0	13.63	1125	0.99	13.39	97	193	Idle	87	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:0	13.63	1119	0.98	13.38	97	193	Idle	86.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.34	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:0	13.63	1088	0.97	13.4	97	193	Idle	86.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.34	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:1	13.63	1088	0.97	13.38	97	193	Idle	86.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.36	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:1	13.63	1085	0.96	13.38	97	193	Idle	86.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.35	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:1	13.63	1082	0.96	13.38	97	193	Idle	86.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:1	13.63	1082	0.96	13.4	97	193	Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.3	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:1	12.27	1063	0.95	13.39	97	193	Idle	86.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.25	20.23	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:1	12.27	1056	0.95	13.38	97	193	Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.25	20.23	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:1	12.27	1039	0.95	13.4	97	193	Idle	86.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.23	20.23	1.38	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:2	12.27	1039	0.95	13.39	97	193	Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.23	20.24	1.38	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:2	12.27	1035	0.94	13.4	97	193	Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.23	20.23	1.38	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:2	12.27	1031	0.94	13.38	97	193	Idle	86.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.19	20.24	1.38	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:2	12.27	1031	0.94	13.39	97	193	Idle	86.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.17	20.24	1.38	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:2	12.27	1018	0.94	13.39	97	193	Idle	87	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.12	20.24	1.38	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:2	12.27	1020	0.94	13.38	97	193	Idle	87.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.11	20.21	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:3	12.27	1020	0.94	13.39	97	193	Idle	87.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.07	20.11	1.37	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:3	12.27	1012	0.94	13.4	97	193	Idle	87.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.07	19.95	1.36	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:3	12.27	1005	0.94	13.4	97	193	Idle	87.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.04	19.74	1.34	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:3	12.27	1005	0.93	13.41	97	193	Idle	88.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.04	19.5	1.33	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:3	12.27	1000	0.93	13.42	97	193	Idle	88.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.98	19.23	1.31	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:3	10.9	1000	0.93	13.4	97	193	Idle	88.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8	18.94	1.29	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:4	10.9	991	0.93	13.4	97	193	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8	18.47	1.26	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:4	10.9	994	0.93	13.4	97	193	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.97	18.13	1.23	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:4	10.9	988	0.92	13.4	96	193	Idle	88.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8	17.95	1.22	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:4	10.9	988	0.92	13.39	96	193	Idle	89	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.96	17.63	1.2	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:4	10.9	985	0.92	13.4	96	193	Idle	89.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.97	17.34	1.18	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:4	10.9	982	0.92	13.39	97	193	Idle	89.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.92	17.13	1.17	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:4	9.54	982	0.91	13.4	97	193	Idle	89.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.94	16.95	1.15	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:5	9.54	983	0.91	13.39	97	193	Idle	89.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.92	16.82	1.15	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:5	9.54	994	0.91	13.39	97	193	Idle	89.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.96	16.71	1.14	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:5	9.54	994	0.9	13.39	97	193	Idle	89.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.92	16.64	1.13	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:5	10.9	986	0.9	13.41	97	193	Idle	89.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.97	16.53	1.13	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:5	10.9	978	0.9	13.39	97	193	Idle	90	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.92	16.51	1.12	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:5	10.9	987	0.9	13.41	97	193	Idle	90.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.95	16.49	1.12	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:6	10.9	987	0.89	13.4	97	193	Idle	90.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.89	16.49	1.12	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:6	9.54	988	0.89	13.4	97	193	Idle	90.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.93	16.5	1.12	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:6	9.54	988	0.89	13.38	97	193	Idle	90.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.89	16.51	1.12	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:6	9.54	988	0.89	13.39	97	193	Idle	91.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.94	16.52	1.13	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:6	9.54	994	0.89	13.39	97	193	Idle	91.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.89	16.54	1.13	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:6	8.18	979	0.88	13.39	97	193	Idle	91.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.92	16.56	1.13	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:6	8.18	979	0.88	13.4	97	193	Idle	91.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.95	16.59	1.13	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:7	8.18	970	0.88	13.38	97	193	Idle	91.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.95	16.59	1.13	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:23:7	8.18	961	0.88	13.39	97	193	Idle	92	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.93	16.59	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:7	8.18	964	0.87	13.37	97	193	Idle	92.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.93	16.59	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:23:7	8.18	964	0.87	13.39	97	193	Idle	92.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.92	16.58	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:7	8.18	957	0.87	13.38	97	193	Idle	92.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.9	16.57	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:7	8.18	957	0.87	13.4	96	193	Idle	92.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.86	16.56	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:8	9.54	954	0.86	13.39	96	193	Idle	93	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.9	16.53	1.13	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:8	9.54	951	0.86	13.41	96	193	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.87	16.51	1.12	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:8	9.54	943	0.86	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.86	16.45	1.12	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:8	9.54	943	0.86	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.89	16.43	1.12	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:8	8.18	940	0.85	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.87	16.39	1.12	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:8	8.18	938	0.85	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.87	16.34	1.11	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:9	8.18	943	0.85	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.88	16.12	1.1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:9	8.18	943	0.85	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.85	16.08	1.1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:9	8.18	931	0.84	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.88	16.02	1.09	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:9	8.18	931	0.84	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.87	15.94	1.09	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:9	8.18	924	0.84	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.84	15.88	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:9	8.18	924	0.84	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.87	15.82	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:23:9	8.18	935	0.84	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.89	15.79	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:0	8.18	935	0.84	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.85	15.72	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:0	8.18	929	0.83	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.87	15.68	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:0	8.18	923	0.83	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.82	15.63	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:0	6.81	908	0.83	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.84	15.76	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:0	6.81	908	0.83	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.8	15.69	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:0	6.81	914	0.83	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.8	15.65	1.07	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:1	6.81	919	0.83	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.78	15.61	1.06	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:1	9.54	920	0.83	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.79	15.58	1.06	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:1	9.54	920	0.83	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.77	15.55	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:1	9.54	912	0.83	13.38	96	193	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.79	15.51	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:1	9.54	905	0.82	13.4	96	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.76	15.48	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:1	9.54	912	0.82	13.39	96	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	15.44	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:1	9.54	912	0.82	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	15.42	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:2	9.54	909	0.82	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	15.38	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:2	9.54	906	0.82	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	15.36	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:2	9.54	929	0.82	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	15.34	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:2	9.54	929	0.82	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	15.33	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:2	9.54	920	0.82	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	15.28	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:2	9.54	910	0.82	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	15.25	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:3	9.54	910	0.82	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	15.23	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:3	6.81	906	0.82	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:3	6.81	906	0.82	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.73	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:3	6.81	908	0.82	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	15.16	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:3	6.81	909	0.82	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	15.15	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:3	8.18	899	0.82	13.39	96	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	15.14	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:4	8.18	899	0.82	13.4	96	193	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	15.11	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:4	8.18	902	0.82	13.39	96	193	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.72	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:4	8.18	905	0.82	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.75	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:4	9.54	889	0.82	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.72	15.1	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:4	9.54	889	0.82	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.7	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:4	9.54	887	0.82	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.68	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:4	9.54	887	0.82	13.41	97	193	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.67	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:5	8.18	894	0.82	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.66	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:5	8.18	901	0.82	13.38	97	193	Idle	93.2	0	2	132	944 Turbo	0.35	Lean	1	14.7	-7.65	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:5	8.18	904	0.82	13.4	97	193	Idle	93.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.69	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:5	8.18	904	0.82	13.4	97	193	Idle	93.2	0	2	132	944 Turbo	0.4	Lean	1	14.7	-7.68	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:5	8.18	904	0.82	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.69	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:5	8.18	905	0.82	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.67	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:6	8.18	905	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.72	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:6	8.18	903	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.68	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:6	8.18	903	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.7	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:6	8.18	899	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.69	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:24:6	8.18	895	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.71	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:6	8.18	892	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.64	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:6	8.18	884	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.69	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:7	8.18	884	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.69	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:7	8.18	884	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.68	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:24:7	8.18	886	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.65	15.15	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:7	8.18	886	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.66	15.13	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:7	8.18	882	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.65	15.13	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:7	8.18	877	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.61	15.12	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:8	8.18	877	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.64	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:8	8.18	877	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.61	15.09	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:8	8.18	870	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.66	15.08	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:8	8.18	864	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.65	15.04	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:8	8.18	871	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.65	15.03	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:8	8.18	871	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.6	15.03	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:9	8.18	871	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.7	-7.61	15.02	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:9	8.18	877	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.58	15.01	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:9	8.18	877	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.58	15	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:9	8.18	871	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.58	15.01	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:9	8.18	871	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.58	15	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:9	9.54	871	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.55	14.98	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:24:9	9.54	857	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.55	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:0	9.54	863	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.55	14.98	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:0	9.54	863	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.54	14.98	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:0	9.54	863	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.58	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:0	8.18	867	0.81	13.4	96	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.56	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:0	8.18	880	0.81	13.4	96	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.6	14.97	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:0	8.18	880	0.81	13.39	96	193	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.58	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:1	8.18	880	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.59	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:1	8.18	862	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.58	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:1	8.18	862	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.59	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:1	8.18	869	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.57	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:1	8.18	869	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.54	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:1	9.54	869	0.81	13.38	97	193	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.56	14.96	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:1	9.54	893	0.81	13.38	97	193	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.51	14.96	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:2	9.54	890	0.81	13.36	97	193	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.54	14.96	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:2	9.54	890	0.81	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.52	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:2	9.54	890	0.81	13.38	97	193	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:2	8.18	882	0.81	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.55	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:2	8.18	882	0.81	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:2	8.18	900	0.81	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.56	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:3	8.18	917	0.81	13.4	97	193	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.61	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:3	8.18	917	0.81	13.38	97	193	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.7	-7.58	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:3	8.18	917	0.81	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.6	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:3	8.18	909	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.58	14.98	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:3	8.18	909	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.61	14.99	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:3	9.54	905	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.56	14.99	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:4	9.54	905	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.58	15.01	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:4	9.54	896	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.58	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:4	9.54	896	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.59	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:4	8.18	901	0.81	13.36	97	193	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.62	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:4	8.18	901	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.67	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:4	8.18	900	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.65	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:4	8.18	899	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.66	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:5	8.18	904	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.68	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:5	8.18	904	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.69	Lean	1	14.6	-7.66	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:5	8.18	900	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:5	8.18	896	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:25:5	8.18	896	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:5	8.18	897	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:6	8.18	896	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:6	8.18	894	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:6	8.18	894	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:6	8.18	889	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:6	8.18	889	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:6	8.18	888	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.11	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:6	8.18	888	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:7	9.54	893	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.61	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:7	9.54	893	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.64	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:7	9.54	887	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.62	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:7	9.54	881	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.64	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:7	9.54	891	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:7	9.54	891	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:8	9.54	886	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:8	9.54	882	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	15.03	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:8	8.18	891	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.67	Lean	1	14.6	-7.67	15.02	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:8	8.18	891	0.81	13.39	96	193	Idle	93.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-7.64	15.02	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:8	8.18	897	0.81	13.38	96	193	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.68	15	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:8	8.18	903	0.81	13.39	96	193	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.68	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:9	8.18	903	0.81	13.38	96	193	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.7	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:9	8.18	893	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.68	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:9	8.18	892	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.71	14.94	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:25:9	8.18	890	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.66	14.94	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:9	8.18	890	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.92	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:9	8.18	886	0.81	13.36	97	193	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.66	14.88	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:25:9	8.18	886	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.69	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:0	8.18	888	0.81	13.36	97	193	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.65	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:0	8.18	890	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.67	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:0	8.18	883	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.63	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:0	8.18	883	0.81	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.64	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:0	8.18	884	0.81	13.38	97	193	Idle	93.2	0	2	132	944 Turbo	0.38	Rich	1	14.7	-7.64	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:0	8.18	885	0.81	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.61	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:1	8.18	895	0.81	13.37	97	193	Idle	93.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.61	14.82	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:1	8.18	895	0.81	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.64	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:1	8.18	895	0.81	13.39	97	193	Idle	93.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.65	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:1	8.18	897	0.81	13.38	97	193	Idle	93.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.64	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:1	8.18	888	0.81	13.4	97	193	Idle	93.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.67	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:1	8.18	888	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.64	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:1	8.18	888	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.64	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:2	8.18	890	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.62	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:2	8.18	890	0.81	13.38	97	193	Idle	93.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.6	14.8	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:2	9.54	902	0.81	13.37	97	193	Idle	93.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.61	14.79	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:2	9.54	903	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.62	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:2	9.54	904	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.63	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:2	9.54	904	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.66	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:3	10.9	898	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.63	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:3	10.9	898	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.7	-7.66	14.85	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:3	10.9	892	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.67	14.87	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:3	10.9	886	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.64	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:3	9.54	910	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:3	9.54	910	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:4	9.54	914	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:4	9.54	917	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:4	9.54	901	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:4	8.18	901	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:4	8.18	906	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:26:4	8.18	911	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:4	8.18	911	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:5	8.18	906	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.7	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:5	8.18	908	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:5	8.18	909	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:5	8.18	909	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:5	6.81	892	0.81	13.36	97	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:5	6.81	892	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:6	6.81	898	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:6	6.81	903	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-7.73	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:6	9.54	902	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:6	9.54	902	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:6	9.54	900	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:6	9.54	898	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:6	8.18	886	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:7	8.18	886	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:7	8.18	892	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:7	8.18	897	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.64	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:7	9.54	897	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:7	9.54	898	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.62	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:7	9.54	898	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:8	9.54	898	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.63	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:8	9.54	898	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.67	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:8	9.54	887	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.62	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:8	9.54	895	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.67	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:8	9.54	895	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.65	15.01	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:8	9.54	895	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.7	15.01	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:9	10.9	907	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.66	14.98	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:9	10.9	907	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.69	14.97	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:26:9	10.9	899	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.68	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:9	10.9	891	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.68	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:9	9.54	903	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.65	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:9	9.54	903	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.68	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:26:9	9.54	908	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.7	-7.71	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:0	9.54	908	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.68	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:0	8.18	920	0.81	13.36	97	193	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.7	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:0	8.18	933	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:0	8.18	920	0.81	13.36	97	193	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:0	8.18	920	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:0	6.81	920	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.7	-7.78	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:1	6.81	921	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:1	6.81	931	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.78	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:1	6.81	931	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:1	6.81	931	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.81	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:1	6.81	916	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:1	6.81	926	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.78	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:1	6.81	926	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.75	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:2	6.81	926	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.79	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:2	8.18	910	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.75	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:2	8.18	900	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.81	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:2	8.18	900	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.76	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:2	8.18	905	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.79	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:2	8.18	910	0.81	13.36	97	193	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.76	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:3	8.18	906	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.78	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:3	8.18	906	0.81	13.36	97	193	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:3	8.18	899	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.78	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:3	8.18	892	0.81	13.36	97	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:3	8.18	892	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.95	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:27:3	8.18	875	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:4	8.18	875	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:4	8.18	878	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:4	8.18	881	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:4	8.18	891	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:4	8.18	891	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:4	8.18	890	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:4	8.18	888	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:5	8.18	888	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:5	8.18	884	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-7.68	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:5	8.18	894	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:5	9.54	894	0.81	13.35	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	14.99	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:5	9.54	904	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:5	9.54	892	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:6	9.54	892	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:6	10.9	885	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:6	10.9	885	0.81	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:6	10.9	879	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-7.66	15	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:6	10.9	879	0.81	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:6	9.54	884	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:6	9.54	890	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	15	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:27:7	9.54	907	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:7	9.54	907	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:7	9.54	908	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:7	9.54	910	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-7.68	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:7	9.54	897	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:7	9.54	897	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.66	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:8	8.18	900	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:8	8.18	903	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.66	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:8	8.18	906	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:8	8.18	908	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:8	8.18	903	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.72	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:8	8.18	903	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.68	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:9	8.18	903	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.67	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:9	8.18	906	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.64	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:9	8.18	906	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.64	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:9	8.18	911	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.68	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:9	8.18	911	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.71	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:9	8.18	916	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.7	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:27:9	8.18	891	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.77	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:0	6.81	891	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.76	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:0	6.81	891	0.81	13.39	97	193	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.77	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:0	6.81	905	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.74	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:0	6.81	905	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.73	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:0	8.18	898	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.72	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:0	8.18	898	0.81	13.37	97	193	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:1	8.18	898	0.81	13.38	97	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:1	8.18	904	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.7	-7.71	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:1	8.18	895	0.81	13.4	97	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.72	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:1	8.18	895	0.81	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:1	8.18	895	0.81	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.72	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:1	8.18	899	0.81	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.67	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:1	8.18	911	0.81	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:2	8.18	911	0.81	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.64	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:2	8.18	911	0.82	13.42	96	193	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:2	8.18	898	0.82	13.41	96	193	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.65	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:2	8.18	900	0.82	13.43	96	193	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:2	8.18	900	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:28:2	8.18	900	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.71	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:3	8.18	899	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:3	8.18	899	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:3	8.18	895	0.82	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:3	8.18	895	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:3	8.18	890	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.66	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:3	8.18	885	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:4	8.18	884	0.82	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:4	8.18	884	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:4	8.18	886	0.82	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.63	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:4	8.18	888	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.63	14.96	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:4	8.18	892	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.67	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:4	8.18	892	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.61	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:4	8.18	886	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.66	14.93	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:5	8.18	879	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.61	14.94	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:5	8.18	879	0.82	13.44	97	193	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.65	14.94	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:5	8.18	871	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.59	14.93	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:5	8.18	871	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.6	14.93	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:5	8.18	868	0.82	13.44	97	193	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.58	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:5	8.18	868	0.82	13.44	97	193	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.58	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:6	9.54	880	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.58	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:6	9.54	892	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.59	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:6	9.54	876	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.58	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:6	9.54	876	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.59	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:6	9.54	882	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.59	14.93	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:6	9.54	889	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.58	14.94	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:6	9.54	889	0.82	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.6	14.94	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:7	9.54	898	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.59	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:7	9.54	907	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.59	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:7	8.18	907	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.61	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:7	8.18	907	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.64	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:28:7	8.18	912	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.62	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:7	8.18	917	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.67	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:8	8.18	917	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.62	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:8	8.18	920	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.66	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:8	8.18	922	0.82	13.43	97	193	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.64	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:8	8.18	922	0.82	13.42	97	193	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.67	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:8	8.18	923	0.82	13.41	97	193	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.66	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:8	8.18	917	0.82	13.43	97	193	Full Load	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.7	-7.72	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:9	8.18	911	0.82	13.42	97	193	Off Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.66	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:9	8.18	911	0.82	13.43	97	193	Off Idle	92.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.7	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:9	6.81	912	0.83	13.42	97	193	Off Idle	92.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:9	6.81	912	0.83	13.43	97	193	Off Idle	91.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-7.64	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:28:9	6.81	904	0.85	13.43	97	193	Off Idle	91	0	2	132	944 Turbo	0.75	Rich	1	14.7	-7.58	14.94	1.02	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:28:9	6.81	896	0.86	13.44	97	193	Off Idle	90.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.53	14.95	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:28:9	8.18	886	0.87	13.43	97	193	Off Idle	89.9	0	2	132	944 Turbo	0.77	Rich	1	14.7	-7.42	14.95	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:29:0	8.18	886	0.88	13.43	97	193	Off Idle	89.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-7.36	14.97	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:29:0	8.18	886	0.9	13.42	97	193	Off Idle	88.8	0	2	132	944 Turbo	0.78	Rich	1	14.7	-7.24	14.98	1.02	4.8	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:29:0	8.18	885	0.92	13.43	97	193	Off Idle	88.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.2	14.98	1.02	4.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:29:0	9.54	882	0.95	13.41	97	193	Off Idle	87.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-7.05	14.99	1.02	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:29:0	9.54	882	0.97	13.42	97	193	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.93	14.99	1.02	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:29:0	9.54	886	0.99	13.42	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.83	14.98	1.02	4.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:29:1	9.54	890	1.01	13.42	97	193	Off Idle	85.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.64	14.99	1.02	4.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:29:1	9.54	890	1.04	13.42	97	193	Off Idle	84.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.52	14.98	1.02	4.8	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:29:1	9.54	907	1.07	13.42	97	193	Off Idle	84.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.34	14.97	1.02	4.8	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:29:1	9.54	901	1.11	13.43	97	193	Off Idle	84.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.17	14.97	1.02	4.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:29:1	9.54	901	1.13	13.42	97	193	Off Idle	84.8	0	2	132	944 Turbo	0.78	Rich	1	14.7	-6.03	14.97	1.02	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:27:29:1	9.54	901	1.16	13.44	97	193	Off Idle	84.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-5.96	14.96	1.02	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:29:1	9.54	917	1.18	13.42	97	193	Off Idle	84.7	0	2	132	944 Turbo	0.76	Rich	1	14.7	-5.83	14.97	1.02	4.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:27:29:2	9.54	940	1.2	13.43	97	193	Off Idle	84.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	-5.81	14.99	1.02	4.4	3.5	ON	28 Pin	OFF	Removed	Disabled
03:27:29:2	9.54	940	1.22	13.4	97	193	Off Idle	84.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-5.67	15.01	1.02	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:27:29:2	9.54	954	1.24	13.42	97	193	Off Idle	84.9	0	2	132	944 Turbo	0.7	Rich	1	14.7	-5.66	15.01	1.02	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:27:29:2	9.54	969	1.26	13.41	97	193	Off Idle	84.9	0	2	132	944 Turbo	0.69	Rich	1	14.7	-5.53	15.01	1.02	4.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:27:29:2	9.54	969	1.28	13.41	97	193	Off Idle	84.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.54	15.01	1.02	4.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:27:29:2	9.54	976	1.29	13.41	97	193	Off Idle	85	0	2	132	944 Turbo	0.68	Rich	1	14.7	-5.43	15	1.02	4.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:27:29:3	8.18	988	1.3	13.4	97	193	Off Idle	85	0	2	132	944 Turbo	0.67	Rich	1	14.7	-5.44	14.99	1.02	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:27:29:3	8.18	988	1.31	13.4	97	193	Off Idle	85.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.38	14.97	1.02	4.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:27:29:3	8.18	998	1.32	13.42	97	193	Off Idle	85.1	0	2	132	944 Turbo	0.7	Rich	1	14.7	-5.4	14.95	1.02	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:3	8.18	1007	1.32	13.4	97	193	Off Idle	85.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	-5.36	14.91	1.02	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:3	9.54	1017	1.33	13.42	97	193	Off Idle	85.2	0	2	132	944 Turbo	0.73	Rich	1	14.7	-5.37	14.86	1.01	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:3	9.54	1017	1.33	13.42	97	193	Off Idle	85.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-5.32	14.84	1.01	4.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:4	9.54	1019	1.33	13.43	97	193	Off Idle	85.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.35	14.83	1.01	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:4	9.54	1019	1.33	13.43	97	193	Off Idle	85.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.3	14.82	1.01	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:4	9.54	1022	1.33	13.42	97	193	Off Idle	85.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.32	14.82	1.01	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:4	9.54	1026	1.32	13.43	97	193	Off Idle	85.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.36	14.82	1.01	4.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:4	9.54	1040	1.32	13.41	97	193	Off Idle	85.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.33	14.82	1.01	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:29:4	9.54	1054	1.32	13.43	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.42	14.83	1.01	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:29:4	9.54	1054	1.32	13.41	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	-5.38	14.84	1.01	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:29:5	9.54	1067	1.32	13.43	97	193	Off Idle	85.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.42	14.84	1.01	4.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:29:5	9.54	1067	1.32	13.42	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	-5.4	14.85	1.01	4.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:5	9.54	1075	1.32	13.41	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-5.44	14.86	1.01	4.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:5	9.54	1075	1.32	13.41	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-5.43	14.84	1.01	4.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:5	9.54	1088	1.32	13.41	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-5.5	14.83	1.01	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:5	10.9	1102	1.32	13.42	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.87	Rich	1	14.7	-5.53	14.8	1.01	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:6	10.9	1103	1.32	13.41	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-5.52	14.75	1.01	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:6	10.9	1090	1.32	13.41	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-5.58	14.7	1	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:6	10.9	1090	1.32	13.42	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-5.57	14.61	1	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:6	10.9	1099	1.32	13.41	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-5.6	14.52	0.99	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:6	10.9	1104	1.32	13.43	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-5.65	14.35	0.98	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:6	10.9	1108	1.32	13.41	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-5.62	14.23	0.97	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:6	10.9	1104	1.32	13.42	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-5.71	14.11	0.96	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:7	10.9	1099	1.32	13.41	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-5.67	13.99	0.95	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:7	10.9	1099	1.32	13.41	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-5.71	13.93	0.95	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:7	10.9	1094	1.32	13.42	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-5.68	13.75	0.94	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:7	10.9	1073	1.32	13.41	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-5.69	13.63	0.93	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:7	10.9	1085	1.32	13.42	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-5.73	13.49	0.92	4.6	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:7	10.9	1085	1.32	13.41	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-5.68	13.4	0.91	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:8	12.27	1076	1.32	13.42	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.72	13.32	0.91	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:8	12.27	1067	1.32	13.41	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-5.68	13.25	0.9	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:8	12.27	1068	1.32	13.41	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-5.69	13.19	0.9	4.4	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:8	12.27	1068	1.32	13.41	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-5.65	13.13	0.89	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:8	13.63	1064	1.32	13.4	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.68	13.1	0.89	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:8	13.63	1056	1.32	13.42	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.68	13.05	0.89	4.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:29:9	13.63	1047	1.32	13.41	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.62	13.02	0.89	4.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:9	13.63	1048	1.32	13.43	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.68	13.02	0.89	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:9	14.99	1048	1.32	13.41	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.6	13.01	0.89	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:9	14.99	1044	1.32	13.4	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.65	13.02	0.89	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:9	14.99	1041	1.32	13.42	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-5.6	13.04	0.89	4.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:9	14.99	1028	1.32	13.4	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.61	13.08	0.89	4.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:29:9	14.99	1019	1.32	13.43	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-5.6	13.12	0.89	4.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:0	14.99	1019	1.32	13.41	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.63	13.15	0.9	4.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:0	14.99	1026	1.32	13.43	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.58	13.21	0.9	4.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:0	16.36	1033	1.32	13.41	97	193	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.57	13.27	0.9	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:0	16.36	1023	1.32	13.43	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.58	13.35	0.91	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:0	16.36	1023	1.32	13.41	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.53	13.4	0.91	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:0	16.36	1021	1.32	13.42	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.52	13.43	0.91	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:30:1	16.36	1021	1.32	13.41	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.5	13.51	0.92	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:1	16.36	1022	1.32	13.42	97	193	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-5.52	13.57	0.92	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:1	16.36	1022	1.32	13.41	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.44	13.61	0.93	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:1	16.36	1026	1.32	13.41	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-5.42	13.68	0.93	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:1	16.36	1026	1.32	13.44	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.43	13.7	0.93	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:1	16.36	1024	1.32	13.42	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.42	13.74	0.94	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:1	16.36	1022	1.32	13.44	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.43	13.77	0.94	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:2	16.36	1020	1.32	13.42	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-5.4	13.8	0.94	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:2	16.36	1020	1.32	13.44	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.43	13.83	0.94	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:2	16.36	1023	1.32	13.42	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-5.38	13.84	0.94	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:2	17.72	1036	1.32	13.45	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-5.39	13.86	0.94	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:2	17.72	1036	1.31	13.43	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-5.38	13.87	0.94	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:2	17.72	1034	1.31	13.41	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-5.43	13.88	0.95	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:3	17.72	1033	1.3	13.42	97	193	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-5.5	13.91	0.95	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:3	17.72	1033	1.28	13.41	97	193	Full Load	85.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.62	13.92	0.95	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:3	17.72	1033	1.25	13.43	97	193	Idle	85.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.76	13.92	0.95	4.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:3	17.72	1029	1.21	13.41	97	193	Idle	85.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.95	13.92	0.95	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:30:3	17.72	1029	1.19	13.44	97	193	Idle	85.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.11	13.91	0.95	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:30:3	14.99	1029	1.17	13.42	97	193	Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.23	13.9	0.95	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:30:4	14.99	1040	1.14	13.42	97	193	Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.46	13.89	0.95	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:30:4	14.99	1040	1.14	13.42	97	193	Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-6.48	13.89	0.95	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:4	16.36	1034	1.12	13.42	97	193	Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.57	13.88	0.95	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:4	16.36	1028	1.08	13.42	97	193	Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.68	13.84	0.94	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:4	16.36	1028	1.06	13.43	97	193	Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.79	13.83	0.94	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:4	16.36	1026	1.04	13.42	97	193	Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.78	13.82	0.94	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:4	13.63	1014	1.01	13.42	97	193	Idle	85.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.89	13.82	0.94	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:5	13.63	1014	1	13.43	97	193	Idle	85.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.91	13.8	0.94	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:5	13.63	1021	0.97	13.41	97	193	Idle	85.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.96	13.8	0.94	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:5	13.63	1028	0.95	13.43	97	193	Idle	85.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.02	13.81	0.94	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:5	16.36	995	0.93	13.41	97	193	Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.07	13.8	0.94	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:5	16.36	995	0.91	13.43	97	193	Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-7.12	13.82	0.94	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:5	16.36	980	0.9	13.42	97	193	Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.6	-7.17	13.81	0.94	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:6	16.36	965	0.88	13.43	97	193	Idle	85.5	0	2	132	944 Turbo	0.86	Rich	1	14.6	-7.25	13.81	0.94	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:6	16.36	972	0.89	13.42	97	193	Idle	85.3	0	2	132	944 Turbo	0.86	Rich	1	14.7	-7.27	13.81	0.94	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:6	16.36	972	0.9	13.44	97	193	Idle	85.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-7.3	13.8	0.94	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:30:6	16.36	954	0.91	13.42	97	193	Idle	84.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-7.24	13.82	0.94	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:6	16.36	954	0.92	13.45	97	193	Idle	84.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.27	13.82	0.94	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:6	16.36	932	0.91	13.43	97	193	Idle	84.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.23	13.81	0.94	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:6	16.36	932	0.91	13.44	97	193	Idle	84.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.24	13.81	0.94	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:7	16.36	937	0.91	13.42	97	193	Idle	83.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.19	13.81	0.94	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:7	16.36	937	0.91	13.44	97	193	Idle	84	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.2	13.8	0.94	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:7	14.99	934	0.92	13.41	97	193	Idle	84.1	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.17	13.8	0.94	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:7	14.99	932	0.93	13.43	97	193	Idle	84.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-7.17	13.8	0.94	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:7	14.99	942	0.93	13.43	97	193	Idle	84.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.17	13.81	0.94	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:30:7	14.99	942	0.93	13.45	97	193	Idle	84.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.2	13.8	0.94	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:30:8	14.99	957	0.93	13.42	97	193	Idle	84.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.18	13.8	0.94	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:30:8	14.99	957	0.93	13.44	97	193	Idle	84.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.21	13.8	0.94	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:30:8	14.99	982	0.93	13.42	97	193	Idle	84.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.19	13.81	0.94	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:30:8	14.99	982	0.93	13.42	97	193	Idle	85.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.25	13.79	0.94	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:30:8	13.63	976	0.94	13.42	97	193	Idle	85.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.25	13.79	0.94	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:30:8	13.63	974	0.94	13.42	97	193	Idle	86.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.28	13.78	0.94	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:30:9	13.63	977	0.94	13.42	97	193	Idle	86.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.3	13.78	0.94	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:9	13.63	985	0.94	13.42	97	193	Idle	86.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.37	13.76	0.94	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:9	13.63	985	0.94	13.41	97	193	Idle	87.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.36	13.75	0.94	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:9	13.63	987	0.94	13.42	97	193	Idle	87.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.41	13.75	0.94	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:9	13.63	989	0.94	13.41	97	193	Idle	87.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.37	13.77	0.94	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:9	13.63	990	0.94	13.43	97	193	Idle	87.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.44	13.78	0.94	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:30:9	12.27	990	0.93	13.41	97	193	Idle	87.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.41	13.81	0.94	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:31:0	12.27	1003	0.93	13.43	97	193	Idle	87.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.49	13.85	0.94	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:0	12.27	1003	0.93	13.45	97	193	Idle	88	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.48	13.91	0.95	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:0	10.9	1000	0.92	13.43	97	193	Idle	88.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.55	13.98	0.95	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:0	10.9	997	0.92	13.44	97	193	Idle	88.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.52	14.14	0.96	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:0	10.9	1006	0.92	13.43	97	193	Idle	88.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.58	14.25	0.97	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:0	10.9	1006	0.92	13.43	97	193	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.56	14.33	0.98	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:1	12.27	998	0.92	13.42	97	193	Idle	88.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.61	14.43	0.98	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:1	12.27	998	0.91	13.41	97	193	Idle	88.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.6	14.56	0.99	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:1	12.27	998	0.91	13.42	97	193	Idle	88.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.65	14.74	1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:1	12.27	998	0.91	13.43	97	193	Idle	88.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.68	14.92	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:1	10.9	980	0.91	13.41	97	193	Idle	88.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.63	15.22	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:1	10.9	993	0.91	13.43	97	193	Idle	88.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.67	15.43	1.05	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:1	10.9	993	0.91	13.42	97	193	Idle	89	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.61	15.61	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:2	10.9	979	0.9	13.43	97	193	Idle	89.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.64	15.82	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:2	10.9	965	0.9	13.41	97	193	Idle	89.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.61	16.04	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:2	10.9	965	0.9	13.41	97	193	Idle	89.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.63	16.29	1.11	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:2	10.9	981	0.9	13.43	97	193	Idle	89.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.58	16.39	1.12	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:2	10.9	969	0.9	13.42	97	193	Idle	89.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.64	16.6	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:2	10.9	969	0.9	13.42	97	193	Idle	89.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.62	16.66	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:3	10.9	969	0.9	13.42	97	193	Idle	89.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.67	16.76	1.14	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:3	10.9	968	0.9	13.43	97	193	Idle	89.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.66	16.79	1.14	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:3	10.9	972	0.9	13.42	97	193	Idle	89.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.71	16.79	1.14	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:3	10.9	972	0.9	13.41	97	193	Idle	89.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.68	16.76	1.14	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:3	10.9	974	0.9	13.42	97	193	Idle	89.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.7	16.74	1.14	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:3	10.9	975	0.9	13.41	97	193	Idle	89.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.65	16.69	1.14	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:4	10.9	946	0.9	13.42	97	194	Idle	89.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.69	16.55	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:4	10.9	946	0.9	13.41	97	194	Idle	89.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.67	16.49	1.12	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:4	10.9	951	0.9	13.41	97	193	Idle	90	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.69	16.38	1.12	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:4	10.9	951	0.9	13.43	97	193	Idle	90.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.69	16.34	1.11	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:4	9.54	942	0.9	13.42	97	193	Idle	90.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.69	16.28	1.11	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:4	9.54	942	0.9	13.43	97	193	Idle	90.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.67	16.23	1.11	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:4	9.54	942	0.9	13.42	97	193	Idle	90.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.69	16.17	1.1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:5	9.54	960	0.89	13.43	97	193	Idle	90.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.67	16.13	1.1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:5	10.9	951	0.89	13.4	97	193	Idle	90.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.69	16.05	1.09	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:5	10.9	951	0.89	13.41	97	193	Idle	90.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.65	16.04	1.09	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:5	10.9	952	0.89	13.41	97	193	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.68	15.98	1.09	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:5	10.9	953	0.89	13.42	97	194	Idle	91	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.64	15.94	1.09	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:5	10.9	951	0.89	13.41	97	194	Idle	91.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.66	15.9	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:6	10.9	951	0.89	13.42	97	194	Idle	91.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.64	15.87	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:6	10.9	935	0.89	13.41	97	193	Idle	91.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.69	15.84	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:6	10.9	935	0.88	13.42	97	193	Idle	91.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.66	15.82	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:6	9.54	935	0.88	13.41	97	193	Idle	91.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.7	15.79	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:6	9.54	952	0.88	13.42	97	193	Idle	91.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	15.77	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:6	9.54	947	0.88	13.41	97	193	Idle	91.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	15.76	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:6	9.54	947	0.88	13.43	97	193	Idle	91.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	15.72	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:7	8.18	946	0.88	13.41	97	193	Idle	91.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	15.71	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:7	8.18	945	0.88	13.43	97	193	Idle	92	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	15.7	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:7	8.18	948	0.87	13.41	97	193	Idle	92	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	15.69	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:7	8.18	948	0.87	13.44	97	193	Idle	92.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	15.69	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:7	8.18	941	0.87	13.43	97	193	Idle	92.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.67	15.66	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:7	8.18	934	0.87	13.42	97	194	Idle	92.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.68	15.66	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:8	8.18	934	0.87	13.42	97	194	Idle	92.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.67	15.66	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:8	8.18	934	0.87	13.41	97	194	Idle	92.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	15.66	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:8	8.18	931	0.87	13.41	97	194	Idle	92.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.67	15.66	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:8	8.18	931	0.87	13.41	97	194	Idle	92.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.65	15.68	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:8	8.18	931	0.86	13.41	97	194	Idle	92.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	15.69	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:8	8.18	925	0.86	13.44	97	193	Idle	92.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	15.69	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:9	8.18	903	0.86	13.42	97	193	Idle	92.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	15.69	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:31:9	8.18	903	0.86	13.44	97	193	Idle	92.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	15.69	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:9	8.18	908	0.86	13.41	97	193	Idle	92.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	15.68	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:9	8.18	912	0.86	13.42	97	193	Idle	92.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.61	15.66	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:9	8.18	912	0.86	13.42	97	193	Idle	92.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	15.66	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:9	9.54	908	0.86	13.42	97	193	Idle	92.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.64	15.64	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:31:9	9.54	908	0.86	13.42	97	193	Idle	92.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.65	15.63	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:0	9.54	910	0.86	13.43	97	193	Idle	92.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.61	15.59	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:0	9.54	910	0.86	13.43	97	194	Idle	92.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.66	15.56	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:0	9.54	904	0.86	13.41	97	194	Full Load	92.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.58	15.54	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:0	9.54	903	0.86	13.42	97	194	Off Idle	92.9	0	2	132	944 Turbo	0.18	Lean	1	14.7	-7.59	15.51	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:0	9.54	903	0.86	13.42	97	193	Off Idle	93	0	2	132	944 Turbo	0.18	Lean	1	14.7	-7.53	15.5	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:0	9.54	903	0.87	13.44	97	193	Off Idle	93	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.51	15.48	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:1	9.54	912	0.88	13.43	97	193	Off Idle	93	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.44	15.45	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:1	9.54	912	0.89	13.43	97	193	Off Idle	92.5	0	2	132	944 Turbo	0.2	Lean	1	14.7	-7.4	15.43	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:1	9.54	898	0.91	13.41	97	193	Off Idle	92	0	2	132	944 Turbo	0.24	Lean	1	14.7	-7.27	15.4	1.05	4.9	2.7	ON	28 Pin	OFF	Removed	Disabled
03:27:32:1	9.54	898	0.92	13.43	97	193	Off Idle	91.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.22	15.37	1.05	4.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:27:32:1	8.18	889	0.94	13.4	97	193	Off Idle	90.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.07	15.36	1.05	4.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:27:32:1	8.18	889	0.96	13.42	97	193	Off Idle	90.4	0	2	132	944 Turbo	0.24	Lean	1	14.7	-6.99	15.35	1.05	4.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:27:32:1	8.18	884	0.99	13.42	97	193	Off Idle	89.8	0	2	132	944 Turbo	0.26	Lean	1	14.7	-6.85	15.34	1.04	4.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:2	8.18	884	1.01	13.42	97	193	Off Idle	89.3	0	2	132	944 Turbo	0.28	Lean	1	14.7	-6.66	15.33	1.04	4.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:2	10.9	884	1.04	13.41	97	193	Off Idle	88.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.41	15.3	1.04	4.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:2	10.9	888	1.05	13.43	97	193	Off Idle	88.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.31	15.3	1.04	4.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:2	10.9	848	1.08	13.43	97	193	Off Idle	87.6	0	2	132	944 Turbo	0.41	Rich	1	14.7	-6.13	15.29	1.04	4.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:2	10.9	848	1.12	13.43	97	193	Off Idle	86.5	0	2	132	944 Turbo	0.43	Rich	1	14.7	-5.82	15.27	1.04	4.9	3.7	ON	28 Pin	OFF	Removed	Disabled
03:27:32:2	10.9	848	1.15	13.43	97	193	Off Idle	85.9	0	2	132	944 Turbo	0.43	Rich	1	14.7	-5.69	15.26	1.04	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:27:32:3	10.9	857	1.18	13.42	97	193	Off Idle	85.2	0	2	132	944 Turbo	0.43	Rich	1	14.7	-5.46	15.25	1.04	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:27:32:3	10.9	857	1.22	13.44	97	193	Off Idle	84.6	0	2	132	944 Turbo	0.43	Rich	1	14.7	-5.31	15.23	1.04	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:27:32:3	10.9	863	1.25	13.43	97	194	Off Idle	84.6	0	2	132	944 Turbo	0.43	Rich	1	14.7	-5.12	15.21	1.04	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:3	10.9	869	1.28	13.43	97	194	Off Idle	84.6	0	2	132	944 Turbo	0.41	Rich	1	14.7	-4.97	15.19	1.04	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:3	10.9	889	1.33	13.42	97	194	Off Idle	84.6	0	2	132	944 Turbo	0.35	Rich	1	14.7	-4.78	15.17	1.03	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:3	10.9	889	1.36	13.43	97	193	Off Idle	84.6	0	2	132	944 Turbo	0.3	Rich	1	14.7	-4.54	15.14	1.03	4.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:4	10.9	898	1.39	13.4	97	193	Off Idle	84.6	0	2	132	944 Turbo	0.24	Rich	1	14.7	-4.3	15.12	1.03	4.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:27:32:4	10.9	906	1.43	13.44	97	193	Off Idle	84.5	0	2	132	944 Turbo	0.18	Rich	1	14.7	-4.11	15.12	1.03	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:32:4	20.45	975	1.46	13.41	97	194	Off Idle	84.5	0	2	132	944 Turbo	0.15	Lean	1	14.7	-3.88	15.1	1.03	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:32:4	20.45	975	1.49	13.44	97	194	Off Idle	84.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-3.66	15.09	1.03	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:32:4	20.45	968	1.52	13.43	97	194	Off Idle	84.6	0	2	132	944 Turbo	0.2	Lean	1	14.7	-3.48	15.08	1.03	4.3	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:32:4	20.45	968	1.56	13.47	97	194	Off Idle	84.7	0	2	132	944 Turbo	0.28	Lean	1	14.7	-3.21	15.07	1.03	4.3	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:32:4	20.45	1006	1.58	13.45	97	194	Off Idle	84.7	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.98	15.05	1.02	4.3	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:32:5	20.45	1006	1.6	13.47	97	194	Off Idle	84.8	0	2	132	944 Turbo	0.41	Lean	1	14.7	-2.89	15.04	1.02	4.2	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:32:5	20.45	1065	1.62	13.44	97	194	Off Idle	85	0	2	132	944 Turbo	0.48	Lean	1	14.7	-2.69	15.03	1.02	4.3	5	ON	28 Pin	OFF	Removed	Disabled
03:27:32:5	20.45	1065	1.63	13.44	97	194	Off Idle	85	0	2	132	944 Turbo	0.51	Lean	1	14.7	-2.66	15.04	1.02	4.4	5	ON	28 Pin	OFF	Removed	Disabled
03:27:32:5	20.45	1095	1.66	13.42	97	194	Off Idle	85.1	0	2	132	944 Turbo	0.62	Lean	1	14.7	-2.55	15.02	1.02	4.3	5	ON	28 Pin	OFF	Removed	Disabled
03:27:32:5	20.45	1149	1.68	13.43	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.7	Lean	1	14.7	-2.52	15.02	1.02	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:32:5	20.45	1174	1.7	13.45	97	194	Off Idle	85.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-2.47	15.02	1.02	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:32:6	20.45	1174	1.72	13.43	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.47	15.02	1.02	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:32:6	20.45	1192	1.74	13.42	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.48	15.03	1.02	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:32:6	21.81	1222	1.75	13.43	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.38	15.05	1.03	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:32:6	21.81	1233	1.78	13.43	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.36	15.1	1.03	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:32:6	21.81	1233	1.78	13.43	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.32	15.12	1.03	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:32:6	21.81	1265	1.81	13.43	97	194	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.3	15.08	1.03	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:6	21.81	1265	1.82	13.42	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.29	15.01	1.02	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:7	21.81	1268	1.82	13.41	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.28	14.91	1.02	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:7	21.81	1276	1.83	13.42	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.31	14.78	1.01	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:7	23.18	1281	1.84	13.42	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.26	14.64	1	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:7	23.18	1278	1.84	13.41	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.26	14.48	0.99	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:7	23.18	1276	1.85	13.42	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.28	14.28	0.97	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:7	23.18	1277	1.85	13.43	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.25	14.17	0.97	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:8	23.18	1275	1.86	13.4	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.27	13.91	0.95	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:32:8	23.18	1273	1.86	13.42	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.32	13.56	0.92	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:8	23.18	1259	1.87	13.41	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.25	13.37	0.91	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:8	23.18	1241	1.87	13.4	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.27	13.21	0.9	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:8	23.18	1241	1.88	13.41	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.29	13.04	0.89	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:8	21.81	1239	1.88	13.4	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.27	12.96	0.88	4.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:9	21.81	1219	1.88	13.4	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.21	12.75	0.87	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:9	21.81	1219	1.89	13.39	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.23	12.63	0.86	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:9	21.81	1201	1.89	13.39	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.17	12.54	0.85	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:9	21.81	1198	1.89	13.39	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.14	12.48	0.85	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:32:9	21.81	1198	1.89	13.4	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.1	12.44	0.85	4.7	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:32:9	23.18	1160	1.88	13.4	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.07	12.41	0.85	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:32:9	23.18	1155	1.88	13.42	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.03	12.41	0.85	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:33:0	23.18	1155	1.88	13.4	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.99	12.41	0.85	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:33:0	23.18	1152	1.88	13.41	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.98	12.42	0.85	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:33:0	23.18	1148	1.88	13.4	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.94	12.46	0.85	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:33:0	23.18	1132	1.87	13.41	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.94	12.51	0.85	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:0	23.18	1116	1.87	13.41	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.87	12.58	0.86	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:0	23.18	1111	1.87	13.4	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.84	12.63	0.86	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:1	23.18	1072	1.86	13.41	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.86	12.66	0.86	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:1	23.18	1072	1.86	13.39	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.79	12.72	0.87	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:1	23.18	1046	1.85	13.41	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.82	12.76	0.87	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:1	23.18	1046	1.85	13.42	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.73	12.81	0.87	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:1	23.18	1034	1.84	13.42	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.77	12.85	0.88	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:1	23.18	1023	1.83	13.43	97	194	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.65	12.88	0.88	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:1	23.18	990	1.82	13.43	97	194	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.61	12.92	0.88	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:2	23.18	990	1.81	13.44	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.58	12.95	0.88	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:2	23.18	971	1.81	13.41	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.54	12.98	0.88	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:2	23.18	956	1.8	13.44	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.51	13	0.89	4.9	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:33:2	23.18	942	1.79	13.41	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.47	13.01	0.89	4.9	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:33:2	23.18	942	1.78	13.44	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.44	13.01	0.89	4.8	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:33:2	23.18	940	1.77	13.41	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.44	13.03	0.89	4.8	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:33:3	23.18	940	1.76	13.44	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.35	13.02	0.89	4.7	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:33:3	21.81	952	1.75	13.41	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.37	13.02	0.89	4.7	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:33:3	21.81	976	1.75	13.45	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.31	13	0.89	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:33:3	21.81	990	1.75	13.42	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.3	12.99	0.88	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:33:3	21.81	990	1.74	13.45	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.31	12.97	0.88	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:3	21.81	1034	1.74	13.44	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.23	12.95	0.88	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:4	21.81	1071	1.74	13.47	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.27	12.92	0.88	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:4	21.81	1071	1.75	13.45	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.22	12.9	0.88	4.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:33:4	21.81	1116	1.75	13.46	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.24	12.86	0.88	4.3	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:33:4	21.81	1116	1.75	13.46	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.23	12.82	0.87	4.2	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:33:4	21.81	1128	1.76	13.44	97	194	Off Idle	85.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.27	12.78	0.87	4.1	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:4	20.45	1166	1.77	13.42	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.26	12.73	0.87	4.1	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:4	20.45	1192	1.78	13.44	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.24	12.66	0.86	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:5	20.45	1192	1.79	13.43	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.23	12.61	0.86	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:5	20.45	1192	1.79	13.44	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.23	12.59	0.86	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:5	20.45	1202	1.81	13.44	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.22	12.49	0.85	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:5	20.45	1218	1.82	13.43	97	194	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.21	12.42	0.85	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:5	20.45	1218	1.83	13.43	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.23	12.36	0.84	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:5	21.81	1214	1.85	13.43	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.18	12.31	0.84	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:6	21.81	1233	1.86	13.41	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.14	12.25	0.83	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:6	21.81	1233	1.88	13.42	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.11	12.18	0.83	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:6	21.81	1235	1.9	13.43	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.04	12.09	0.82	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:6	21.81	1242	1.91	13.42	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.02	12.01	0.82	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:6	21.81	1256	1.92	13.43	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.02	11.94	0.81	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:6	21.81	1256	1.93	13.44	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.01	11.89	0.81	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:6	21.81	1273	1.94	13.43	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.95	11.84	0.81	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:7	21.81	1287	1.95	13.43	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.98	11.79	0.8	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:33:7	21.81	1287	1.96	13.43	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.92	11.74	0.8	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:7	21.81	1310	1.97	13.43	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.91	11.7	0.8	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:7	21.81	1322	1.98	13.41	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.93	11.67	0.79	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:7	21.81	1322	1.99	13.43	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.92	11.64	0.79	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:33:7	21.81	1350	2	13.43	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.93	11.61	0.79	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:8	21.81	1388	2.01	13.42	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.96	11.6	0.79	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:8	21.81	1388	2.02	13.43	97	194	Off Idle	86.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.99	11.59	0.79	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:8	21.81	1398	2.03	13.42	97	194	Off Idle	86.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.97	11.6	0.79	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:8	21.81	1411	2.04	13.42	97	194	Off Idle	86.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.94	11.63	0.79	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:8	21.81	1411	2.05	13.43	97	194	Off Idle	86.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.99	11.64	0.79	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:8	23.18	1438	2.05	13.43	97	194	Off Idle	86.7	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.01	11.68	0.8	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:33:9	23.18	1454	2.06	13.43	97	194	Off Idle	86.7	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.99	11.72	0.8	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:33:9	23.18	1467	2.07	13.41	97	194	Off Idle	86.7	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.99	11.77	0.8	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:33:9	24.54	1474	2.08	13.43	97	194	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.05	11.81	0.8	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:33:9	24.54	1482	2.09	13.43	97	194	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.07	11.84	0.81	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:33:9	24.54	1483	2.1	13.43	97	194	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.03	11.88	0.81	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:9	24.54	1490	2.11	13.44	97	194	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.01	11.91	0.81	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:33:9	24.54	1520	2.12	13.44	97	194	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.01	11.95	0.81	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:0	24.54	1520	2.13	13.41	97	194	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1	11.99	0.82	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:0	24.54	1524	2.14	13.43	97	194	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.01	12.01	0.82	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:0	24.54	1538	2.15	13.43	97	194	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.98	12.04	0.82	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:0	24.54	1538	2.15	13.42	97	194	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.98	12.06	0.82	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:0	24.54	1571	2.17	13.43	97	194	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.93	12.12	0.83	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:0	25.9	1573	2.18	13.41	97	194	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.92	12.16	0.83	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:1	25.9	1592	2.19	13.44	97	194	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-0.86	12.21	0.83	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:1	25.9	1592	2.2	13.44	97	194	Off Idle	86.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-0.82	12.27	0.84	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:1	25.9	1618	2.2	13.41	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-0.81	12.34	0.84	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:1	25.9	1614	2.21	13.42	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	-0.78	12.41	0.85	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:1	24.54	1626	2.23	13.42	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.86	Rich	1	14.7	-0.8	12.52	0.85	4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:1	24.54	1665	2.24	13.41	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-0.79	12.59	0.86	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:1	25.9	1671	2.24	13.41	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-0.77	12.63	0.86	3.9	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:2	25.9	1684	2.25	13.42	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-0.77	12.72	0.87	3.9	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:2	25.9	1690	2.26	13.42	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-0.78	12.78	0.87	3.9	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:2	25.9	1709	2.27	13.41	97	194	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.79	12.84	0.87	3.8	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:2	25.9	1729	2.28	13.42	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.82	12.93	0.88	3.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:2	25.9	1729	2.29	13.42	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.85	13	0.89	3.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:2	25.9	1756	2.3	13.42	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.85	13.05	0.89	3.8	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:3	25.9	1777	2.32	13.42	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-0.75	13.11	0.89	3.8	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:3	27.27	1777	2.33	13.42	97	194	Off Idle	86.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.7	13.19	0.9	3.8	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:3	27.27	1774	2.33	13.43	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.83	Rich	1	14.7	-0.68	13.27	0.9	3.8	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:3	27.27	1787	2.35	13.43	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.68	13.38	0.91	3.8	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:3	27.27	1787	2.35	13.43	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.66	13.46	0.92	3.8	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:3	27.27	1803	2.36	13.43	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-0.65	13.54	0.92	3.7	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:4	27.27	1816	2.37	13.42	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-0.65	13.56	0.92	3.7	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:4	27.27	1832	2.38	13.41	97	194	Off Idle	86.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-0.62	13.68	0.93	3.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:4	27.27	1840	2.39	13.42	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-0.6	13.75	0.94	3.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:4	27.27	1861	2.4	13.43	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.7	-0.62	13.83	0.94	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:4	27.27	1878	2.41	13.43	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.66	13.91	0.95	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:4	27.27	1888	2.42	13.42	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.63	14.03	0.96	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:4	27.27	1910	2.43	13.41	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.62	14.12	0.96	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:5	27.27	1938	2.44	13.4	97	194	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.6	14.19	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:5	27.27	1953	2.44	13.4	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.6	14.28	0.97	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:5	27.27	1952	2.45	13.39	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.6	14.39	0.98	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:5	27.27	1958	2.46	13.4	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.67	Rich	1	14.7	-0.6	14.47	0.99	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:34:5	27.27	1960	2.47	13.42	97	194	Off Idle	86.1	0	2	132	944 Turbo	0.65	Rich	1	14.7	-0.58	14.57	0.99	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:5	28.63	1972	2.48	13.42	97	194	Off Idle	86	0	2	132	944 Turbo	0.61	Rich	1	14.7	-0.57	14.64	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:6	28.63	1979	2.49	13.44	97	194	Off Idle	86	0	2	132	944 Turbo	0.54	Rich	1	14.7	-0.56	14.71	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:34:6	28.63	1992	2.5	13.45	97	194	Off Idle	86	0	2	132	944 Turbo	0.49	Lean	1	14.7	-0.53	14.75	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:34:6	28.63	2010	2.5	13.45	97	194	Off Idle	86	0	2	132	944 Turbo	0.43	Lean	1	14.7	-0.49	14.77	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:6	28.63	2010	2.51	13.45	97	194	Off Idle	86	0	2	132	944 Turbo	0.37	Lean	1	14.7	-0.48	14.82	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:6	28.63	2040	2.52	13.45	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.32	Lean	1	14.7	-0.47	14.86	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:6	28.63	2052	2.53	13.44	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.27	Lean	1	14.7	-0.47	14.93	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:6	28.63	2060	2.54	13.43	97	194	Off Idle	85.9	0	2	132	944 Turbo	0.21	Lean	1	14.7	-0.46	14.96	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:7	28.63	2088	2.54	13.42	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.17	Lean	1	14.7	-0.45	14.96	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:34:7	28.63	2102	2.55	13.41	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.7	-0.41	15.01	1.02	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:34:7	28.63	2111	2.56	13.39	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.7	-0.4	15.09	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:7	28.63	2137	2.57	13.4	97	194	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.7	-0.39	15.15	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:7	28.63	2158	2.58	13.41	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.13	Lean	1	14.7	-0.38	15.21	1.04	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:7	28.63	2158	2.58	13.41	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.18	Lean	1	14.7	-0.39	15.26	1.04	3.3	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:8	28.63	2200	2.59	13.41	97	194	Off Idle	85.7	0	2	132	944 Turbo	0.24	Lean	1	14.7	-0.42	15.28	1.04	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:34:8	28.63	2196	2.6	13.41	97	194	Off Idle	85.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-0.4	15.27	1.04	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:8	28.63	2205	2.61	13.42	97	194	Off Idle	85.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-0.36	15.25	1.04	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:8	29.99	2210	2.61	13.42	97	194	Off Idle	85.2	0	2	132	944 Turbo	0.43	Lean	1	14.7	-0.34	15.27	1.04	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:8	29.99	2232	2.62	13.41	97	194	Off Idle	85	0	2	132	944 Turbo	0.53	Lean	1	14.7	-0.39	15.29	1.04	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:8	29.99	2233	2.63	13.41	97	194	Off Idle	84.8	0	2	132	944 Turbo	0.6	Lean	1	14.7	-0.31	15.24	1.04	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:9	29.99	2245	2.63	13.42	97	194	Off Idle	84.6	0	2	132	944 Turbo	0.66	Lean	1	14.7	-0.32	15.17	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:9	29.99	2253	2.64	13.42	97	194	Off Idle	84.3	0	2	132	944 Turbo	0.68	Lean	1	14.7	-0.33	15.12	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:9	29.99	2287	2.65	13.41	97	194	Off Idle	84	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.34	15.06	1.03	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:9	29.99	2294	2.65	13.41	97	194	Off Idle	83.7	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.34	14.99	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:9	29.99	2294	2.66	13.42	97	194	Off Idle	82.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.36	14.92	1.02	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:9	29.99	2320	2.67	13.41	97	194	Off Idle	82.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.37	14.86	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:34:9	29.99	2329	2.67	13.4	97	194	Off Idle	81.7	0	2	132	944 Turbo	0.75	Rich	1	14.7	-0.31	14.78	1.01	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:35:0	29.99	2343	2.68	13.41	97	194	Off Idle	80.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-0.28	14.7	1	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:35:0	29.99	2350	2.69	13.41	97	194	Off Idle	80.2	0	2	132	944 Turbo	0.73	Rich	1	14.7	-0.26	14.65	1	3.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:35:0	29.99	2362	2.7	13.41	97	194	Off Idle	79.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.24	14.64	1	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:35:0	29.99	2378	2.71	13.41	97	194	Off Idle	79	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.24	14.63	1	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:35:0	29.99	2378	2.72	13.41	97	194	Off Idle	78.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-0.29	14.63	1	3.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:35:0	29.99	2394	2.72	13.42	97	194	Off Idle	77.7	0	2	132	944 Turbo	0.64	Lean	1	14.7	-0.28	14.66	1	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:35:1	29.99	2405	2.73	13.41	97	194	Off Idle	77	0	2	132	944 Turbo	0.59	Lean	1	14.7	-0.23	14.7	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:1	29.99	2410	2.74	13.42	97	194	Off Idle	76.2	0	2	132	944 Turbo	0.53	Lean	1	14.7	-0.25	14.75	1	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:1	29.99	2432	2.75	13.42	97	194	Off Idle	75.7	0	2	132	944 Turbo	0.47	Lean	1	14.7	-0.24	14.79	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:1	29.99	2461	2.75	13.42	97	194	Off Idle	74.9	0	2	132	944 Turbo	0.39	Lean	1	14.7	-0.19	14.81	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:1	29.99	2467	2.76	13.41	97	194	Off Idle	74.2	0	2	132	944 Turbo	0.33	Lean	1	14.7	-0.15	14.82	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:1	29.99	2476	2.77	13.42	97	194	Off Idle	73.4	0	2	132	944 Turbo	0.29	Lean	1	14.7	-0.15	14.83	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:1	29.99	2495	2.77	13.41	97	194	Off Idle	73	0	2	132	944 Turbo	0.21	Lean	1	14.7	-0.11	14.9	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:2	29.99	2557	2.78	13.42	97	194	Off Idle	72.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-0.13	14.95	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:35:2	29.99	2557	2.79	13.41	97	194	Off Idle	71.7	0	2	132	944 Turbo	0.17	Lean	1	14.7	-0.17	14.98	1.02	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:35:2	31.36	2536	2.79	13.42	97	194	Off Idle	70.5	0	2	132	944 Turbo	0.18	Lean	1	14.7	-0.13	15.02	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:35:2	31.36	2552	2.8	13.41	97	194	Off Idle	70.5	0	2	132	944 Turbo	0.22	Rich	1	14.7	-0.13	15.05	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:2	31.36	2558	2.81	13.42	97	194	Off Idle	69.2	0	2	132	944 Turbo	0.3	Rich	1	14.7	-0.11	15.08	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:2	31.36	2602	2.82	13.43	97	194	Off Idle	68.5	0	2	132	944 Turbo	0.36	Rich	1	14.7	-0.1	15.13	1.03	3.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:3	31.36	2608	2.83	13.43	97	194	Off Idle	67.9	0	2	132	944 Turbo	0.42	Rich	1	14.7	-0.08	15.18	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:3	31.36	2631	2.83	13.41	97	194	Off Idle	67.3	0	2	132	944 Turbo	0.49	Rich	1	14.7	-0.12	15.19	1.04	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:3	31.36	2639	2.84	13.42	97	194	Off Idle	66.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	-0.14	15.16	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:35:3	31.36	2663	2.84	13.41	97	194	Off Idle	66.5	0	2	132	944 Turbo	0.59	Rich	1	14.7	-0.08	15.15	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:35:3	29.99	2692	2.85	13.41	97	194	Off Idle	65	0	2	132	944 Turbo	0.67	Rich	1	14.7	-0.08	15.09	1.03	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:3	29.99	2697	2.86	13.41	97	194	Off Idle	64.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-0.07	15.04	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:4	29.99	2718	2.87	13.42	97	194	Off Idle	63.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.07	14.98	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:4	29.99	2726	2.88	13.42	97	194	Off Idle	62.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.01	14.94	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:4	31.36	2738	2.89	13.43	97	194	Off Idle	61.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	0.05	14.9	1.01	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:4	31.36	2744	2.9	13.43	97	194	Off Idle	60.6	0	2	132	944 Turbo	0.65	Rich	1	14.7	0.07	14.84	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:4	31.36	2765	2.91	13.43	97	194	Off Idle	59.7	0	2	132	944 Turbo	0.59	Rich	1	14.7	0.09	14.8	1.01	3.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:4	31.36	2780	2.92	13.43	97	194	Off Idle	58.8	0	2	132	944 Turbo	0.54	Rich	1	14.7	0.21	14.79	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:35:4	31.36	2782	2.93	13.42	97	194	Off Idle	57.2	0	2	132	944 Turbo	0.48	Rich	1	14.7	0.22	14.8	1.01	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:35:5	31.36	2802	2.94	13.43	97	194	Off Idle	56.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	0.35	14.79	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:35:5	31.36	2818	2.95	13.43	97	194	Off Idle	55.6	0	2	132	944 Turbo	0.32	Rich	1	14.7	0.37	14.81	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:35:5	31.36	2832	2.96	13.43	97	194	Off Idle	54.7	0	2	132	944 Turbo	0.27	Rich	1	14.7	0.43	14.83	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:35:5	31.36	2836	2.97	13.42	97	194	Off Idle	54	0	2	132	944 Turbo	0.22	Lean	1	14.7	0.46	14.86	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:35:5	31.36	2885	2.99	13.41	97	194	Off Idle	53.3	0	2	132	944 Turbo	0.21	Lean	1	14.7	0.52	14.91	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:35:5	31.36	2880	2.99	13.4	97	194	Off Idle	52.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	0.55	14.96	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:35:6	31.36	2895	3	13.4	97	194	Off Idle	51	0	2	132	944 Turbo	0.27	Lean	1	14.7	0.71	14.99	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:35:6	31.36	2902	3.01	13.41	97	194	Off Idle	50.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	0.71	15.05	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:35:6	31.36	2934	3.03	13.4	97	194	Off Idle	50.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	0.86	15.08	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:35:6	29.99	2982	3.04	13.42	97	194	Off Idle	49	0	2	132	944 Turbo	0.44	Lean	1	14.7	0.94	15.1	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:35:6	29.99	2976	3.06	13.42	97	194	Off Idle	48.2	0	2	132	944 Turbo	0.5	Lean	1	14.7	1.02	15.11	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:35:6	29.99	2980	3.07	13.43	97	194	Off Idle	47.5	0	2	132	944 Turbo	0.57	Lean	1	14.7	1.1	15.09	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:35:6	29.99	3003	3.08	13.41	97	194	Off Idle	46.7	0	2	132	944 Turbo	0.63	Lean	1	14.7	1.19	15.08	1.03	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:35:7	29.99	3044	3.09	13.42	97	194	Off Idle	46	0	2	132	944 Turbo	0.67	Rich	1	14.7	1.25	15.02	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:35:7	29.99	3044	3.11	13.41	97	194	Off Idle	45.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	1.36	14.97	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:35:7	29.99	3036	3.12	13.41	97	194	Off Idle	44.7	0	2	132	944 Turbo	0.7	Rich	1	14.7	1.41	14.93	1.02	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:35:7	29.99	3062	3.14	13.41	97	194	Off Idle	44.1	0	2	132	944 Turbo	0.7	Rich	1	14.7	1.5	14.87	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:35:7	29.99	3068	3.15	13.42	97	194	Off Idle	43.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	1.64	14.85	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:35:7	29.99	3110	3.17	13.42	97	194	Off Idle	42.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	1.64	14.84	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:35:8	29.99	3126	3.18	13.41	97	194	Off Idle	42.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	1.8	14.83	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:8	29.99	3126	3.19	13.41	97	194	Off Idle	42.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	1.76	14.81	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:8	29.99	3142	3.2	13.42	97	194	Off Idle	42.1	0	2	132	944 Turbo	0.74	Rich	1	14.7	1.77	14.82	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:8	29.99	3205	3.22	13.41	97	194	Off Idle	41.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	1.89	14.82	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:8	29.99	3185	3.23	13.41	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	1.92	14.83	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:8	29.99	3187	3.24	13.41	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	1.93	14.83	1.01	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:9	29.99	3200	3.26	13.41	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	2	14.79	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:9	29.99	3221	3.27	13.4	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	2.13	14.81	1.01	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:9	29.99	3221	3.28	13.42	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	2.22	14.81	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:9	29.99	3254	3.29	13.41	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	2.33	14.8	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:35:9	29.99	3276	3.3	13.41	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	2.41	14.81	1.01	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:9	29.99	3286	3.3	13.41	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	2.39	14.81	1.01	3.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:27:35:9	29.99	3352	3.31	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	2.4	14.83	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:36:0	29.99	3333	3.32	13.41	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	2.48	14.85	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:36:0	29.99	3340	3.33	13.42	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.68	Lean	1	14.7	2.52	14.85	1.01	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:0	29.99	3366	3.35	13.42	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.62	Lean	1	14.7	2.73	14.86	1.01	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:0	29.99	3412	3.36	13.41	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.7	2.93	14.85	1.01	3.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:0	29.99	3401	3.37	13.42	97	194	Off Idle	41.5	0	2	132	944 Turbo	0.52	Lean	1	14.7	3.07	14.83	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:0	29.99	3408	3.37	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.7	3.22	14.83	1.01	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:1	29.99	3431	3.38	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	3.32	14.86	1.01	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:27:36:1	29.99	3434	3.4	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	3.26	14.87	1.01	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:27:36:1	29.99	3472	3.41	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	3.36	14.91	1.02	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:27:36:1	29.99	3491	3.42	13.41	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	3.48	14.9	1.02	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:27:36:1	29.99	3505	3.43	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	3.54	14.95	1.02	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:27:36:1	29.99	3507	3.44	13.41	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.7	3.71	15.04	1.02	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:1	29.99	3555	3.45	13.39	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.7	3.87	15.07	1.03	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:2	29.99	3561	3.46	13.4	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	3.82	15.07	1.03	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:2	29.99	3565	3.47	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.7	3.84	15.05	1.03	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:2	29.99	3604	3.48	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	3.96	15.02	1.02	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:2	29.99	3642	3.49	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	4.05	14.98	1.02	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:2	29.99	3650	3.5	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	4.26	14.86	1.01	3.4	6.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:2	29.99	3680	3.51	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	4.36	14.81	1.01	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:27:36:3	29.99	3703	3.53	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	4.5	14.76	1.01	3.5	6.4	ON	28 Pin	OFF	Removed	Disabled
03:27:36:3	29.99	3717	3.54	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	4.52	14.7	1	3.5	6.5	ON	28 Pin	OFF	Removed	Disabled
03:27:36:3	29.99	3721	3.55	13.41	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	4.64	14.66	1	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:27:36:3	28.63	3752	3.56	13.41	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	4.78	14.65	1	3.5	6.6	ON	28 Pin	OFF	Removed	Disabled
03:27:36:3	28.63	3748	3.57	13.41	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	4.92	14.67	1	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:27:36:3	28.63	3757	3.59	13.41	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	4.98	14.7	1	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:27:36:4	28.63	3762	3.6	13.41	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	5.11	14.72	1	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:4	28.63	3804	3.61	13.42	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	5.06	14.76	1.01	3.5	6.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:4	28.63	3797	3.62	13.43	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	5.15	14.78	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:36:4	28.63	3802	3.63	13.42	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	5.19	14.79	1.01	3.5	6.7	ON	28 Pin	OFF	Removed	Disabled
03:27:36:4	28.63	3824	3.65	13.42	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	5.24	14.77	1.01	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:27:36:4	28.63	3834	3.65	13.42	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	5.2	14.75	1	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:27:36:4	28.63	3874	3.67	13.42	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	5.23	14.73	1	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:27:36:5	28.63	3878	3.68	13.43	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	5.47	14.68	1	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:27:36:5	28.63	3908	3.69	13.4	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	5.63	14.67	1	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:27:36:5	28.63	3927	3.7	13.4	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	5.75	14.66	1	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:27:36:5	28.63	3953	3.72	13.37	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	5.94	14.68	1	3.5	6.9	ON	28 Pin	OFF	Removed	Disabled
03:27:36:5	28.63	3953	3.73	13.38	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	5.92	14.68	1	3.5	7.1	ON	28 Pin	OFF	Removed	Disabled
03:27:36:5	28.63	3972	3.74	13.39	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	5.96	14.69	1	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:27:36:6	28.63	3995	3.75	13.42	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	6.03	14.7	1	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:6	28.63	4031	3.77	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	6.16	14.69	1	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:27:36:6	28.63	4040	3.78	13.46	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	6.19	14.71	1	3.4	7.4	ON	28 Pin	OFF	Removed	Disabled
03:27:36:6	28.63	4090	3.79	13.46	97	195	Off Idle	41.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	6.17	14.72	1	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:6	28.63	4135	3.8	13.46	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	6.21	14.71	1	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:27:36:6	28.63	4144	3.81	13.46	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	6.13	14.72	1	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:27:36:6	28.63	4228	3.82	13.43	97	194	Off Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	6.06	14.7	1	3.4	7.2	ON	28 Pin	OFF	Removed	Disabled
03:27:36:7	28.63	4198	3.83	13.4	97	194	Off Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	6.13	14.63	1	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:27:36:7	28.63	4178	3.84	13.37	97	194	Off Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	6.22	14.61	1	3.5	7.2	ON	28 Pin	OFF	Removed	Disabled
03:27:36:7	28.63	4177	3.86	13.35	97	195	Off Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	6.56	14.57	0.99	3.5	7.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:7	28.63	4180	3.87	13.37	97	195	Off Idle	41.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	6.69	14.55	0.99	3.5	7.4	ON	28 Pin	OFF	Removed	Disabled
03:27:36:7	28.63	4210	3.88	13.39	97	194	Off Idle	41.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	6.92	14.55	0.99	3.5	7.5	ON	28 Pin	OFF	Removed	Disabled
03:27:36:7	28.63	4191	3.89	13.41	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	7.07	14.51	0.99	3.6	9.5	ON	28 Pin	OFF	Removed	Disabled
03:27:36:8	28.63	4209	3.9	13.44	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	7.05	14.5	0.99	3.6	9.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:8	28.63	4226	3.92	13.45	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	7	14.53	0.99	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:8	28.63	4279	3.92	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	6.99	14.55	0.99	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:8	28.63	4322	3.93	13.41	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	7.16	14.53	0.99	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:8	28.63	4330	3.94	13.41	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	7.18	14.46	0.99	3.5	9.8	ON	28 Pin	OFF	Removed	Disabled
03:27:36:8	28.63	4364	3.94	13.41	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	7.11	14.33	0.98	3.5	9.7	ON	28 Pin	OFF	Removed	Disabled
03:27:36:9	28.63	4403	3.95	13.4	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	7	14.11	0.96	3.5	9.6	ON	28 Pin	OFF	Removed	Disabled
03:27:36:9	29.99	4462	3.96	13.41	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	6.89	13.73	0.94	3.5	9.5	ON	28 Pin	OFF	Removed	Disabled
03:27:36:9	29.99	4453	3.96	13.41	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	6.79	13.45	0.92	3.5	9.3	ON	28 Pin	OFF	Removed	Disabled
03:27:36:9	29.99	4495	3.96	13.4	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.86	Rich	1	14.7	6.82	13.16	0.9	3.5	9.2	ON	28 Pin	OFF	Removed	Disabled
03:27:36:9	29.99	4530	3.97	13.41	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	6.74	12.82	0.87	3.5	9.2	ON	28 Pin	OFF	Removed	Disabled
03:27:36:9	29.99	4542	3.97	13.43	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	6.58	12.45	0.85	3.5	9	ON	28 Pin	OFF	Removed	Disabled
03:27:36:9	29.99	4592	3.97	13.42	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	6.29	11.99	0.82	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:27:37:0	29.99	4622	3.97	13.43	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.7	5.79	11.73	0.8	3.5	8.9	ON	28 Pin	OFF	Removed	Disabled
03:27:37:0	29.99	4631	3.96	13.43	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.7	5.35	11.67	0.79	3.5	8.7	ON	28 Pin	OFF	Removed	Disabled
03:27:37:0	29.99	4670	3.93	13.4	97	195	Off Idle	41.4	0	2	132	944 Turbo	0.88	Rich	1	14.7	4.29	11.54	0.79	3.5	8.2	ON	28 Pin	OFF	Removed	Disabled
03:27:37:0	31.36	4586	3.83	13.4	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.7	2.01	11.45	0.78	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:37:0	31.36	4433	3.72	13.43	97	194	Off Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.1	11.4	0.78	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:37:0	31.36	4410	3.59	13.42	97	194	Full Load	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	-2.14	11.35	0.77	3.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:37:1	31.36	4284	3.44	13.41	97	194	Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	-3.81	11.29	0.77	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:27:37:1	28.63	4000	3.25	13.42	97	194	Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	-5.12	11.22	0.76	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:37:1	23.18	4068	3.06	13.43	97	194	Idle	41.4	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.11	11.13	0.76	3.8	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:37:1	20.45	4179	2.89	13.44	97	194	Idle	41.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.78	11.01	0.75	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:1	20.45	4158	2.67	13.47	97	194	Idle	41.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-7.55	11.02	0.75	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:1	20.45	4150	2.54	13.48	97	194	Idle	41.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-8.02	11.09	0.76	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:1	20.45	4112	2.41	13.47	97	194	Idle	41.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-8.4	11.21	0.76	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:2	20.45	4067	2.26	13.45	97	194	Idle	41.3	0	2	132	944 Turbo	0.88	Rich	1	14.6	-8.71	11.31	0.77	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:2	20.45	3974	2.09	13.43	97	194	Idle	41.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-8.82	11.42	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:2	20.45	3996	1.91	13.41	97	194	Idle	41.3	0	2	132	944 Turbo	0.87	Rich	1	14.6	-8.95	11.53	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:2	20.45	3982	1.75	13.4	97	194	Idle	40.8	0	2	132	944 Turbo	0.84	Lean	1	14.6	-9.08	11.63	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:2	20.45	3941	1.6	13.41	97	194	Idle	40.2	0	2	132	944 Turbo	0.78	Lean	1	14.6	-9.14	11.71	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:2	20.45	3920	1.47	13.43	97	194	Idle	39.6	0	2	132	944 Turbo	0.71	Lean	1	14.6	-9.17	11.77	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:3	20.45	3889	1.36	13.45	97	194	Idle	38.9	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.17	11.79	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:3	20.45	3850	1.21	13.46	97	194	Idle	38	0	2	132	944 Turbo	0.59	Lean	1	14.6	-9.18	11.72	0.8	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:3	20.45	3808	1.13	13.44	97	194	Idle	36.9	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.15	11.52	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:37:3	20.45	3799	1.09	13.42	97	194	Idle	35.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.19	11.47	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:3	20.45	3777	1.08	13.42	97	194	Idle	34.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-9.23	11.46	0.78	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:3	20.45	3731	1.09	13.42	97	194	Idle	33.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.28	11.59	0.79	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:4	20.45	3726	1.13	13.42	97	194	Idle	31.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.29	11.85	0.81	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:4	20.45	3688	1.17	13.44	97	194	Idle	30.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.29	12.08	0.82	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:4	20.45	3643	1.32	13.45	97	194	Idle	28.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.21	13.25	0.9	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:4	20.45	3635	1.35	13.44	97	194	Idle	26.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.14	14.18	0.97	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:4	20.45	3606	1.39	13.44	97	194	Idle	25.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.13	15.12	1.03	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:4	20.45	3543	1.43	13.44	97	194	Idle	24.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.12	15.58	1.06	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:4	20.45	3548	1.43	13.43	97	194	Idle	24	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	16.51	1.12	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:5	20.45	3518	1.47	13.43	97	194	Idle	23.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	17.8	1.21	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:5	20.45	3460	1.53	13.44	97	194	Idle	22.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	18.57	1.26	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:5	20.45	3451	1.6	13.45	97	194	Idle	21.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	19.25	1.31	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:5	20.45	3444	1.66	13.43	97	194	Idle	21.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	19.83	1.35	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:5	20.45	3400	1.71	13.42	97	194	Idle	20.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	20.14	1.37	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:5	20.45	3375	1.74	13.44	97	194	Idle	20.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:6	20.45	3368	1.76	13.44	97	194	Idle	20.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:6	20.45	3324	1.77	13.42	97	194	Idle	20.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.91	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:6	20.45	3291	1.78	13.46	97	194	Idle	20.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.89	20.21	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:6	20.45	3242	1.8	13.44	97	194	Idle	20.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.85	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:6	20.45	3244	1.82	13.44	97	194	Full Load	20.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.83	20.23	1.38	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:6	20.45	3102	1.83	13.44	97	194	Off Idle	20.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.79	20.23	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:37:6	10.9	3111	1.84	13.44	97	194	Off Idle	20.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.76	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:37:7	13.63	3117	1.85	13.44	97	194	Off Idle	21.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.7	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:37:7	13.63	3064	1.86	13.43	97	194	Off Idle	21.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.6	20.23	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:37:7	19.09	2953	1.87	13.43	97	194	Off Idle	24.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.51	20.24	1.38	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:37:7	19.09	2931	1.88	13.44	97	194	Off Idle	25.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.36	20.23	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:27:37:7	21.81	2803	1.88	13.43	97	194	Off Idle	27.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.31	20.24	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:27:37:7	24.54	2803	1.89	13.45	97	194	Off Idle	28.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.19	20.24	1.38	3.9	2	ON	28 Pin	OFF	Removed	Disabled
03:27:37:8	24.54	2715	1.9	13.42	97	194	Off Idle	30.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.24	1.38	4	2	ON	28 Pin	OFF	Removed	Disabled
03:27:37:8	27.27	2638	1.91	13.42	97	194	Off Idle	32.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.04	20.23	1.38	4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:37:8	29.99	2592	1.92	13.43	97	194	Off Idle	35.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.99	20.23	1.38	3.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:37:8	29.99	2592	1.93	13.41	97	194	Off Idle	37.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8	20.23	1.38	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:37:8	32.72	2571	1.94	13.42	97	194	Off Idle	43.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.02	20.24	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:8	35.45	2568	1.94	13.43	97	194	Off Idle	45.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.04	20.24	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:9	34.08	2559	1.93	13.43	97	194	Off Idle	48.6	0	2	132	944 Turbo	0.03	Lean	1	14.7	-8.12	20.23	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:37:9	34.08	2530	1.92	13.43	97	194	Off Idle	51.3	0	2	132	944 Turbo	0.03	Lean	1	14.7	-8.24	20.24	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:27:37:9	34.08	2569	1.91	13.43	97	194	Off Idle	51.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.32	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:37:9	34.08	2574	1.89	13.43	97	194	Off Idle	54.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.42	20.22	1.38	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:37:9	34.08	2600	1.89	13.44	97	194	Off Idle	55.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.58	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:37:9	34.08	2640	1.89	13.43	97	194	Off Idle	55.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.62	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:37:9	35.45	2670	1.87	13.42	97	194	Off Idle	58.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.69	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:38:0	35.45	2668	1.86	13.43	97	194	Off Idle	59.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.78	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:38:0	35.45	2703	1.85	13.43	97	194	Off Idle	60.1	0	2	132	944 Turbo	0.05	Lean	1	14.7	-8.83	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:38:0	35.45	2702	1.84	13.43	97	194	Off Idle	60.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.83	20.21	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:38:0	35.45	2702	1.83	13.43	97	194	Off Idle	60.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.86	20.23	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:38:0	35.45	2709	1.83	13.43	97	194	Off Idle	60.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.85	20.22	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:38:0	35.45	2709	1.82	13.42	97	194	Off Idle	60	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.81	20.24	1.38	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:38:1	35.45	2709	1.82	13.42	97	194	Off Idle	59.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.82	20.22	1.38	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:1	35.45	2702	1.81	13.43	97	194	Off Idle	59	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.82	20.14	1.37	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:1	35.45	2702	1.81	13.44	97	194	Off Idle	58.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.83	20.08	1.37	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:1	35.45	2702	1.79	13.45	97	194	Off Idle	57.2	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.81	19.86	1.35	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:1	35.45	2704	1.79	13.44	97	194	Off Idle	56.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.73	19.59	1.33	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:1	35.45	2706	1.79	13.43	97	194	Off Idle	56.1	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.72	19.28	1.31	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:1	35.45	2705	1.8	13.43	97	194	Off Idle	55.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.7	18.96	1.29	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:2	35.45	2694	1.81	13.44	97	194	Off Idle	55.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.67	18.62	1.27	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:2	35.45	2685	1.82	13.43	97	194	Off Idle	55.1	0	2	132	944 Turbo	0.05	Lean	1	14.7	-8.65	18.31	1.25	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:2	35.45	2680	1.83	13.42	97	194	Off Idle	54.9	0	2	132	944 Turbo	0.05	Lean	1	14.7	-8.66	17.98	1.23	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:38:2	35.45	2666	1.83	13.43	97	194	Off Idle	54.7	0	2	132	944 Turbo	0.05	Lean	1	14.7	-8.65	17.53	1.19	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:2	35.45	2651	1.84	13.43	97	194	Off Idle	54.7	0	2	132	944 Turbo	0.05	Lean	1	14.7	-8.64	17.3	1.18	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:2	35.45	2638	1.85	13.42	97	194	Off Idle	54.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.64	17.15	1.17	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:3	35.45	2632	1.85	13.44	97	194	Off Idle	55	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.65	17.1	1.16	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:3	35.45	2632	1.86	13.44	97	194	Off Idle	55.3	0	2	132	944 Turbo	0.06	Lean	1	14.7	-8.72	17.08	1.16	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:3	35.45	2619	1.86	13.44	97	194	Off Idle	55.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.69	17.08	1.16	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:3	35.45	2623	1.86	13.43	98	194	Off Idle	55.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.72	17.07	1.16	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:3	35.45	2623	1.86	13.44	98	194	Off Idle	55.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.71	17.03	1.16	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:3	35.45	2628	1.86	13.43	98	194	Off Idle	56.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.7	17.02	1.16	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:4	35.45	2633	1.86	13.43	97	194	Off Idle	56.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.73	16.99	1.16	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:4	35.45	2633	1.85	13.43	97	194	Off Idle	56.8	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.71	16.89	1.15	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:4	35.45	2659	1.85	13.43	97	194	Off Idle	57.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.73	16.81	1.15	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:4	35.45	2648	1.85	13.41	97	194	Off Idle	57.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-8.73	16.77	1.14	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:4	35.45	2655	1.85	13.43	97	194	Off Idle	57.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.74	16.61	1.13	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:4	35.45	2655	1.84	13.43	97	194	Off Idle	58.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.77	16.5	1.12	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:4	35.45	2662	1.84	13.44	97	194	Off Idle	58.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.83	16.4	1.12	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:5	35.45	2660	1.84	13.43	97	194	Off Idle	58.1	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.86	16.26	1.11	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:5	35.45	2664	1.84	13.44	97	194	Off Idle	58.1	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.86	16.18	1.1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:5	35.45	2671	1.83	13.45	97	194	Off Idle	58	0	2	132	944 Turbo	0.08	Lean	1	14.7	-8.89	16.11	1.1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:5	35.45	2675	1.83	13.44	97	194	Off Idle	57.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.92	16.04	1.09	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:5	35.45	2676	1.83	13.44	97	194	Off Idle	57.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.88	15.97	1.09	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:5	35.45	2680	1.83	13.44	97	194	Off Idle	57.8	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.87	15.92	1.08	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:6	35.45	2670	1.83	13.43	97	194	Off Idle	57.7	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.88	15.87	1.08	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:6	35.45	2670	1.83	13.43	97	194	Off Idle	57.6	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.89	15.83	1.08	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:6	35.45	2664	1.83	13.44	97	194	Off Idle	57.4	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.87	15.79	1.08	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:6	35.45	2660	1.83	13.42	97	194	Off Idle	57.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.87	15.76	1.07	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:6	35.45	2659	1.83	13.43	98	194	Off Idle	57.2	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.9	15.72	1.07	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:6	35.45	2644	1.83	13.44	98	194	Off Idle	57	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.9	15.67	1.07	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:6	35.45	2638	1.83	13.43	98	194	Off Idle	57.2	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.89	15.63	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:7	35.45	2638	1.83	13.43	98	194	Off Idle	57.3	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.91	15.57	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:7	35.45	2628	1.83	13.45	98	194	Off Idle	57.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.89	15.52	1.06	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:7	35.45	2634	1.83	13.43	97	194	Off Idle	57.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.89	15.47	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:7	35.45	2635	1.83	13.43	97	194	Off Idle	57.6	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.91	15.43	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:7	35.45	2634	1.83	13.43	97	194	Off Idle	57.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.9	15.42	1.05	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:38:7	35.45	2646	1.83	13.43	97	194	Off Idle	57.9	0	2	132	944 Turbo	0.33	Lean	1	14.7	-8.9	15.38	1.05	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:8	35.45	2640	1.83	13.45	97	194	Off Idle	57.9	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.95	15.33	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:8	35.45	2644	1.83	13.44	97	194	Off Idle	57.9	0	2	132	944 Turbo	0.45	Lean	1	14.7	-8.94	15.32	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:8	35.45	2644	1.83	13.44	97	194	Off Idle	57.9	0	2	132	944 Turbo	0.51	Lean	1	14.7	-8.89	15.3	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:8	35.45	2647	1.83	13.44	97	194	Off Idle	57.9	0	2	132	944 Turbo	0.57	Rich	1	14.7	-8.91	15.27	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:8	35.45	2649	1.83	13.44	97	194	Off Idle	58.1	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.92	15.25	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:8	35.45	2648	1.83	13.44	97	194	Off Idle	58.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.9	15.23	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:9	35.45	2652	1.83	13.44	97	194	Off Idle	58.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.91	15.2	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:9	35.45	2653	1.82	13.45	97	194	Off Idle	58.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.95	15.17	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:9	35.45	2654	1.82	13.44	97	194	Off Idle	58.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.94	15.15	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:9	35.45	2656	1.82	13.42	97	194	Off Idle	58	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.95	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:9	35.45	2658	1.82	13.44	97	194	Off Idle	57.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.97	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:9	35.45	2662	1.82	13.44	97	194	Off Idle	57.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.02	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:38:9	35.45	2664	1.82	13.43	97	194	Off Idle	57.7	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.99	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:39:0	35.45	2664	1.82	13.43	97	194	Off Idle	57.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.01	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:39:0	35.45	2665	1.82	13.45	97	194	Off Idle	57.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.04	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:39:0	35.45	2666	1.82	13.43	97	194	Off Idle	57.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.02	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:39:0	35.45	2664	1.82	13.43	97	194	Off Idle	57.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.04	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:39:0	35.45	2659	1.82	13.44	97	194	Off Idle	57.6	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.03	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:39:0	35.45	2655	1.82	13.45	97	194	Off Idle	57.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.04	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:39:1	35.45	2646	1.81	13.43	97	194	Off Idle	57.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.06	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:39:1	35.45	2620	1.81	13.44	97	194	Off Idle	57.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.08	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:1	35.45	2636	1.81	13.43	97	194	Off Idle	57	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.1	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:1	35.45	2633	1.81	13.43	97	194	Off Idle	56.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.09	14.85	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:39:1	35.45	2629	1.8	13.43	97	194	Off Idle	57.1	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.14	14.86	1.01	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:1	35.45	2619	1.8	13.42	97	194	Off Idle	57.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.14	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:1	35.45	2621	1.8	13.44	98	194	Off Idle	57.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.14	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:2	35.45	2621	1.79	13.42	98	194	Off Idle	57.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-9.2	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:2	35.45	2619	1.79	13.42	98	194	Off Idle	57.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	-9.21	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:2	35.45	2621	1.78	13.43	97	194	Off Idle	57.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.25	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:2	35.45	2621	1.78	13.43	97	194	Off Idle	57.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.32	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:2	35.45	2619	1.77	13.44	97	194	Off Idle	58	0	2	132	944 Turbo	0.78	Rich	1	14.7	-9.32	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:2	35.45	2622	1.77	13.41	97	194	Off Idle	58.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.35	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:39:3	35.45	2622	1.76	13.43	97	194	Off Idle	58.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-9.37	14.88	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:3	35.45	2625	1.75	13.43	97	194	Off Idle	58.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-9.4	14.87	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:3	35.45	2626	1.75	13.41	97	194	Off Idle	58.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.44	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:3	35.45	2628	1.75	13.41	97	194	Off Idle	58.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.43	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:3	35.45	2629	1.74	13.43	97	194	Off Idle	58.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.43	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:3	35.45	2632	1.74	13.44	97	194	Off Idle	58.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.46	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:4	35.45	2629	1.73	13.45	97	194	Off Idle	58.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.45	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:4	35.45	2630	1.73	13.45	97	194	Off Idle	58.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.46	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:4	35.45	2635	1.73	13.45	97	194	Off Idle	59	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.47	14.86	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:4	35.45	2635	1.72	13.45	97	194	Off Idle	58.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.52	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:4	35.45	2635	1.72	13.44	97	194	Off Idle	58.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.54	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:4	35.45	2635	1.72	13.45	97	194	Off Idle	58.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.52	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:4	35.45	2638	1.72	13.45	97	194	Off Idle	58.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.54	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:5	35.45	2639	1.72	13.46	97	194	Off Idle	59	0	2	132	944 Turbo	0.79	Rich	1	14.6	-9.56	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:5	35.45	2639	1.72	13.47	97	194	Off Idle	59	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.53	14.82	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:5	35.45	2639	1.72	13.46	97	194	Off Idle	59	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.56	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:5	35.45	2645	1.72	13.46	97	194	Off Idle	59	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.55	14.8	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:5	35.45	2643	1.71	13.46	97	194	Off Idle	59	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.55	14.76	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:5	35.45	2652	1.71	13.44	97	194	Off Idle	58.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.51	14.76	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:6	35.45	2640	1.71	13.44	97	194	Off Idle	58.7	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.51	14.76	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:6	35.45	2638	1.71	13.43	97	194	Off Idle	58.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.52	14.75	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:6	35.45	2636	1.71	13.43	97	194	Off Idle	58.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.51	14.74	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:6	35.45	2622	1.71	13.42	97	194	Off Idle	58.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-9.54	14.74	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:6	35.45	2626	1.71	13.44	97	194	Off Idle	58.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.52	14.75	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:6	35.45	2621	1.71	13.46	97	194	Off Idle	58.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.54	14.74	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:6	35.45	2621	1.71	13.45	97	194	Off Idle	58.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.56	14.74	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:7	35.45	2620	1.71	13.44	97	194	Off Idle	58.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.56	14.74	1	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:7	35.45	2611	1.71	13.44	97	194	Off Idle	58.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.56	14.73	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:7	35.45	2611	1.71	13.45	97	194	Off Idle	58.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.58	14.72	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:39:7	35.45	2608	1.71	13.44	97	194	Off Idle	58.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.59	14.71	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:39:7	35.45	2608	1.7	13.43	97	194	Off Idle	58.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-9.59	14.71	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:7	35.45	2608	1.7	13.44	97	194	Off Idle	58.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.6	14.69	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:8	35.45	2602	1.7	13.44	97	194	Off Idle	58.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.66	14.69	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:39:8	35.45	2597	1.69	13.43	97	194	Off Idle	59	0	2	132	944 Turbo	0.48	Lean	1	14.7	-9.66	14.68	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:39:8	35.45	2597	1.69	13.44	97	194	Off Idle	59.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.67	14.67	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:39:8	35.45	2597	1.69	13.43	97	194	Off Idle	59.6	0	2	132	944 Turbo	0.34	Lean	1	14.7	-9.71	14.66	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:39:8	35.45	2592	1.68	13.43	97	194	Off Idle	59.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.77	14.67	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:39:8	35.45	2589	1.67	13.43	97	194	Off Idle	59.9	0	2	132	944 Turbo	0.19	Lean	1	14.7	-9.83	14.68	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:39:9	35.45	2588	1.66	13.42	97	194	Off Idle	60.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.85	14.69	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:39:9	35.45	2591	1.65	13.44	97	194	Off Idle	60.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.93	14.7	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:39:9	35.45	2591	1.62	13.43	97	194	Full Load	60.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.06	14.72	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:39:9	35.45	2591	1.61	13.41	97	194	Idle	60.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.07	14.74	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:39:9	35.45	2588	1.58	13.43	97	194	Idle	60.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.18	14.75	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:39:9	35.45	2580	1.57	13.43	97	194	Idle	60.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.26	14.75	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:39:9	35.45	2578	1.55	13.42	97	194	Idle	60.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.29	14.77	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:0	35.45	2576	1.54	13.42	97	194	Idle	58.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.31	14.8	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:0	35.45	2569	1.52	13.43	97	194	Idle	52.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.32	14.83	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:40:0	35.45	2569	1.53	13.43	98	194	Idle	49	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.2	14.88	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:40:0	32.72	2524	1.54	13.44	98	194	Idle	45.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-10.12	14.9	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:40:0	27.27	2518	1.58	13.43	98	194	Idle	45.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.87	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:40:0	27.27	2518	1.59	13.43	98	194	Idle	41.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.66	14.98	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:1	21.81	2514	1.6	13.44	98	194	Idle	38.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.46	15.01	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:1	21.81	2566	1.61	13.43	98	194	Idle	34.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.29	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:1	19.09	2574	1.62	13.43	97	194	Idle	32.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.13	15.1	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:1	19.09	2590	1.64	13.43	97	194	Idle	27.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.98	15.12	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:1	19.09	2607	1.66	13.44	97	194	Idle	27.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.9	15.13	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:1	19.09	2607	1.68	13.43	97	194	Idle	27.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.83	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:1	19.09	2575	1.71	13.43	97	194	Idle	27.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.81	15.14	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:2	19.09	2564	1.71	13.42	97	194	Idle	27.4	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.94	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:2	19.09	2564	1.71	13.43	97	194	Idle	29.9	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.06	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:2	19.09	2553	1.7	13.43	97	194	Idle	33.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.26	15.07	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:2	19.09	2528	1.68	13.42	97	194	Idle	36.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.42	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:2	19.09	2544	1.67	13.42	97	194	Idle	40	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.57	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:2	19.09	2543	1.67	13.42	97	194	Idle	43.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.73	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:3	19.09	2540	1.67	13.44	98	194	Idle	47.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.85	15	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:3	19.09	2539	1.66	13.44	98	194	Idle	50.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.89	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:3	19.09	2540	1.64	13.43	98	194	Idle	54.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.97	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:3	19.09	2541	1.62	13.45	98	194	Idle	56.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.03	15.23	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:3	19.09	2542	1.56	13.45	97	194	Idle	59.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.08	15.44	1.05	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:3	19.09	2545	1.52	13.45	97	194	Idle	61.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.08	15.49	1.06	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:4	19.09	2545	1.5	13.45	97	194	Idle	61.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.12	15.69	1.07	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:4	19.09	2554	1.48	13.46	97	194	Idle	61.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.16	15.89	1.08	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:4	19.09	2544	1.46	13.46	97	194	Idle	61.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.18	16.09	1.1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:4	19.09	2540	1.43	13.44	97	194	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	16.32	1.11	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:4	19.09	2539	1.4	13.44	98	194	Idle	61.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	16.52	1.13	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:4	19.09	2530	1.37	13.45	98	194	Idle	61.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	16.74	1.14	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:4	19.09	2525	1.35	13.43	98	194	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	17.03	1.16	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:5	19.09	2497	1.33	13.43	98	194	Idle	62	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	17.56	1.2	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:5	19.09	2497	1.34	13.44	98	194	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	17.74	1.21	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:5	19.09	2508	1.35	13.44	98	194	Idle	62.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	18.29	1.25	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:5	19.09	2498	1.36	13.45	97	194	Idle	62.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	18.63	1.27	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:5	19.09	2504	1.37	13.44	97	194	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	18.95	1.29	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:5	19.09	2504	1.36	13.45	98	194	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	19.27	1.31	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:6	19.09	2474	1.35	13.44	98	194	Idle	63	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	19.7	1.34	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:6	19.09	2493	1.34	13.44	98	194	Idle	63.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	19.83	1.35	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:6	19.09	2511	1.34	13.44	98	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.13	1.37	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:6	19.09	2500	1.34	13.44	97	194	Idle	63.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.2	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:6	19.09	2488	1.35	13.44	97	194	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:6	19.09	2488	1.35	13.44	97	194	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:6	19.09	2488	1.34	13.44	97	194	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:7	19.09	2490	1.34	13.44	97	194	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:7	19.09	2490	1.33	13.44	97	194	Idle	64	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:7	19.09	2490	1.33	13.45	97	194	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:7	19.09	2490	1.33	13.44	97	194	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:7	19.09	2487	1.33	13.45	97	194	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.2	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:7	19.09	2484	1.33	13.46	97	194	Idle	64.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.2	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:8	19.09	2483	1.32	13.44	97	194	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.2	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:8	19.09	2476	1.32	13.44	97	194	Idle	64.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.19	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:8	19.09	2470	1.32	13.44	97	194	Idle	64.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:8	19.09	2463	1.32	13.44	97	194	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:8	19.09	2463	1.32	13.44	97	194	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:8	19.09	2457	1.32	13.44	97	194	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:9	19.09	2451	1.31	13.44	97	194	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:9	19.09	2451	1.31	13.45	97	194	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:9	19.09	2447	1.31	13.43	97	194	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:9	19.09	2442	1.31	13.44	98	194	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:9	19.09	2417	1.31	13.45	98	194	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:40:9	19.09	2417	1.3	13.44	98	194	Idle	66.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:40:9	19.09	2432	1.3	13.45	98	194	Idle	66.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.24	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:0	19.09	2430	1.29	13.45	98	194	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:0	19.09	2430	1.29	13.43	98	194	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:0	19.09	2430	1.29	13.43	97	194	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:0	19.09	2420	1.28	13.43	97	194	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:0	17.72	2420	1.28	13.43	97	194	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:0	17.72	2428	1.28	13.42	98	194	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:1	17.72	2425	1.27	13.43	98	194	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:1	17.72	2425	1.27	13.43	98	194	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:1	17.72	2424	1.27	13.44	98	194	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:1	17.72	2410	1.27	13.45	98	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:1	17.72	2415	1.26	13.45	98	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:1	17.72	2414	1.26	13.45	98	194	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.42	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:1	17.72	2409	1.25	13.45	98	194	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:2	17.72	2406	1.25	13.44	97	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:2	17.72	2406	1.24	13.44	97	194	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:2	17.72	2404	1.24	13.43	97	194	Idle	68.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.2	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:2	17.72	2399	1.23	13.44	97	194	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:2	17.72	2396	1.23	13.44	97	194	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:2	17.72	2396	1.22	13.44	97	194	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:3	17.72	2393	1.22	13.44	97	194	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:3	17.72	2388	1.22	13.45	97	194	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:3	17.72	2388	1.21	13.45	97	194	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:3	17.72	2386	1.21	13.45	97	194	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:3	17.72	2382	1.21	13.45	97	194	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:3	17.72	2381	1.21	13.44	97	194	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:4	17.72	2380	1.2	13.45	98	194	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:4	17.72	2378	1.2	13.43	98	194	Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:4	17.72	2374	1.19	13.43	98	194	Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:4	17.72	2374	1.19	13.44	98	194	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:4	17.72	2373	1.19	13.44	98	194	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:4	17.72	2371	1.18	13.43	98	194	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:4	17.72	2371	1.18	13.44	98	194	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:5	17.72	2367	1.18	13.44	98	194	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:5	17.72	2367	1.18	13.44	98	194	Idle	70.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:5	17.72	2363	1.18	13.43	98	194	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:5	17.72	2359	1.17	13.43	98	194	Idle	71.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:5	17.72	2352	1.17	13.44	98	194	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:5	17.72	2352	1.17	13.42	97	194	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:6	17.72	2350	1.17	13.42	97	194	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:6	17.72	2344	1.17	13.44	97	194	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:6	17.72	2341	1.16	13.43	98	194	Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:6	17.72	2341	1.16	13.43	98	194	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:6	17.72	2337	1.16	13.44	98	194	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:6	17.72	2331	1.16	13.44	98	194	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.22	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:6	17.72	2328	1.15	13.44	98	194	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:7	17.72	2326	1.15	13.44	97	194	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:7	17.72	2308	1.15	13.43	97	194	Full Load	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.59	20.22	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:7	17.72	2324	1.15	13.43	97	194	Off Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:41:7	9.54	2264	1.14	13.44	97	194	Off Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.6	20.23	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:27:41:7	9.54	2338	1.14	13.43	97	194	Off Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.2	ON	28 Pin	OFF	Removed	Disabled
03:27:41:7	12.27	2335	1.14	13.44	97	194	Off Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:8	12.27	2332	1.14	13.45	97	194	Off Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:8	14.99	2332	1.14	13.44	97	194	Off Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.53	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:8	14.99	2329	1.14	13.44	97	194	Off Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:8	17.72	2324	1.14	13.43	98	194	Off Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.52	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:8	20.45	2325	1.14	13.42	98	194	Off Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:41:8	20.45	2323	1.14	13.44	98	194	Off Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:9	23.18	2318	1.14	13.42	98	194	Off Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:9	25.9	2315	1.14	13.43	98	194	Off Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:9	25.9	2311	1.14	13.44	98	194	Off Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:9	28.63	2311	1.14	13.44	98	194	Off Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:9	28.63	2308	1.14	13.43	98	194	Off Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:9	31.36	2308	1.14	13.43	98	194	Off Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:41:9	34.08	2304	1.13	13.45	98	194	Off Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:42:0	34.08	2302	1.13	13.43	98	194	Off Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.5	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:42:0	35.45	2284	1.13	13.42	98	194	Off Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:42:0	35.45	2281	1.13	13.43	98	194	Off Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:42:0	35.45	2281	1.13	13.43	98	194	Off Idle	77.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:42:0	35.45	2278	1.13	13.43	97	194	Off Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.3	ON	28 Pin	OFF	Removed	Disabled
03:27:42:0	35.45	2276	1.14	13.44	97	194	Off Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.42	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:42:1	35.45	2276	1.14	13.43	97	194	Off Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:42:1	35.45	2279	1.14	13.43	98	194	Off Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:42:1	35.45	2278	1.14	13.43	98	194	Off Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:42:1	35.45	2283	1.15	13.45	98	194	Off Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:42:1	35.45	2277	1.15	13.43	98	194	Off Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.39	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:42:1	35.45	2277	1.16	13.42	98	194	Off Idle	78.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.41	20.23	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:42:1	35.45	2263	1.17	13.41	98	194	Off Idle	78.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:2	35.45	2263	1.17	13.39	98	194	Off Idle	78.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:2	35.45	2254	1.18	13.4	98	194	Off Idle	78.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:2	35.45	2252	1.18	13.42	98	194	Off Idle	78.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:2	35.45	2252	1.19	13.44	98	194	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:2	35.45	2249	1.2	13.45	98	194	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:2	35.45	2224	1.21	13.46	97	194	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10.33	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:3	35.45	2238	1.22	13.47	97	194	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:3	35.45	2238	1.22	13.46	97	194	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.36	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:3	35.45	2236	1.23	13.44	98	194	Off Idle	78.8	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10.34	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:3	35.45	2235	1.24	13.45	98	194	Off Idle	79	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.32	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:42:3	35.45	2241	1.26	13.44	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.31	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:42:3	35.45	2245	1.26	13.42	98	194	Off Idle	79.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:42:4	35.45	2255	1.27	13.43	98	194	Off Idle	79.6	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.28	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:42:4	35.45	2256	1.28	13.44	98	194	Off Idle	79.9	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.25	20.24	1.38	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:42:4	34.08	2267	1.28	13.43	98	194	Off Idle	80	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.22	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:42:4	34.08	2256	1.29	13.43	98	194	Off Idle	80.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.2	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:42:4	34.08	2266	1.3	13.42	97	194	Off Idle	80.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.16	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:42:4	34.08	2266	1.3	13.43	97	194	Off Idle	80.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:42:4	34.08	2264	1.31	13.43	97	194	Off Idle	80.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.12	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:42:5	34.08	2241	1.32	13.42	98	194	Off Idle	80.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.13	20.21	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:5	34.08	2247	1.33	13.41	98	194	Off Idle	80.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.13	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:5	35.45	2247	1.34	13.42	98	194	Off Idle	80.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.03	20.22	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:5	35.45	2256	1.34	13.42	98	194	Off Idle	80.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:5	35.45	2242	1.35	13.43	98	194	Off Idle	80.6	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10	20.23	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:5	35.45	2238	1.36	13.43	98	194	Off Idle	80.6	0	2	132	944 Turbo	0.05	Lean	1	14.7	-9.98	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:6	35.45	2238	1.36	13.43	98	194	Off Idle	80.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.97	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:6	35.45	2240	1.37	13.43	98	194	Off Idle	80.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.97	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:6	35.45	2238	1.37	13.42	98	194	Off Idle	80.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.96	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:6	34.08	2228	1.37	13.41	98	194	Off Idle	80.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.96	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:6	34.08	2233	1.38	13.41	98	194	Off Idle	80.3	0	2	132	944 Turbo	0.06	Lean	1	14.7	-9.93	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:6	34.08	2230	1.38	13.42	98	194	Off Idle	80.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.93	20.24	1.38	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:6	34.08	2226	1.38	13.42	98	194	Off Idle	80.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-9.94	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:7	34.08	2226	1.39	13.41	98	194	Off Idle	80.5	0	2	132	944 Turbo	0.07	Lean	1	14.7	-9.93	20.18	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:7	34.08	2225	1.39	13.42	98	194	Off Idle	80.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.87	20.11	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:7	34.08	2224	1.39	13.45	98	194	Off Idle	80.8	0	2	132	944 Turbo	0.08	Lean	1	14.7	-9.87	20.01	1.36	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:7	34.08	2222	1.39	13.45	98	194	Off Idle	80.8	0	2	132	944 Turbo	0.09	Lean	1	14.7	-9.85	19.87	1.35	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:7	34.08	2220	1.39	13.43	98	194	Off Idle	80.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.84	19.67	1.34	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:42:7	34.08	2216	1.39	13.43	98	194	Off Idle	81.1	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.83	19.33	1.32	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:8	34.08	2216	1.39	13.44	98	194	Off Idle	81.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.84	19.07	1.3	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:8	34.08	2200	1.39	13.44	98	194	Off Idle	81.2	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.83	18.78	1.28	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:8	34.08	2201	1.39	13.44	98	194	Off Idle	81.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.86	18.62	1.27	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:8	34.08	2198	1.39	13.44	98	194	Off Idle	81.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-9.83	18.16	1.24	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:8	34.08	2198	1.39	13.44	98	194	Off Idle	81.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-9.83	17.87	1.22	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:8	34.08	2200	1.39	13.43	98	194	Off Idle	81.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.82	17.59	1.2	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:9	34.08	2200	1.39	13.41	98	194	Off Idle	82	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.82	17.46	1.19	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:9	34.08	2203	1.39	13.41	98	194	Off Idle	82.1	0	2	132	944 Turbo	0.15	Lean	1	14.7	-9.81	17.21	1.17	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:9	34.08	2204	1.39	13.42	98	194	Off Idle	82.3	0	2	132	944 Turbo	0.16	Lean	1	14.7	-9.77	16.99	1.16	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:9	34.08	2219	1.39	13.42	98	194	Off Idle	82.3	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.77	16.77	1.14	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:9	34.08	2221	1.39	13.43	98	194	Off Idle	82.1	0	2	132	944 Turbo	0.21	Lean	1	14.7	-9.76	16.49	1.12	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:9	34.08	2217	1.39	13.43	98	194	Off Idle	82	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.75	16.32	1.11	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:42:9	34.08	2217	1.39	13.44	98	194	Off Idle	82	0	2	132	944 Turbo	0.3	Lean	1	14.7	-9.76	16.17	1.1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:0	34.08	2221	1.39	13.43	98	194	Off Idle	82	0	2	132	944 Turbo	0.34	Rich	1	14.7	-9.77	16.04	1.09	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:0	34.08	2222	1.39	13.42	98	194	Off Idle	82.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.79	15.91	1.08	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:0	34.08	2223	1.39	13.41	98	194	Off Idle	82.1	0	2	132	944 Turbo	0.47	Rich	1	14.7	-9.79	15.79	1.08	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:0	34.08	2222	1.39	13.42	98	194	Off Idle	82	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.82	15.69	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:0	34.08	2218	1.39	13.42	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.57	Rich	1	14.7	-9.83	15.61	1.06	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:0	34.08	2218	1.39	13.43	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.62	Rich	1	14.7	-9.83	15.55	1.06	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:1	34.08	2218	1.39	13.43	97	194	Off Idle	81.8	0	2	132	944 Turbo	0.66	Rich	1	14.7	-9.81	15.52	1.06	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:1	34.08	2216	1.39	13.43	97	194	Off Idle	81.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.81	15.46	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:1	34.08	2210	1.39	13.43	97	194	Off Idle	81.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.78	15.42	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:1	34.08	2210	1.39	13.41	98	194	Off Idle	81.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.8	15.38	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:1	34.08	2200	1.39	13.41	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.77	15.32	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:1	34.08	2208	1.39	13.42	98	194	Off Idle	81.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.75	15.29	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:1	34.08	2204	1.39	13.42	98	194	Off Idle	82.1	0	2	132	944 Turbo	0.7	Rich	1	14.7	-9.75	15.26	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:2	34.08	2202	1.39	13.43	98	194	Off Idle	82.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.74	15.24	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:2	34.08	2202	1.39	13.42	98	194	Off Idle	82.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.73	15.2	1.04	3.5	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:2	34.08	2192	1.4	13.42	98	194	Off Idle	82.2	0	2	132	944 Turbo	0.59	Rich	1	14.7	-9.71	15.17	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:2	34.08	2192	1.4	13.41	98	194	Off Idle	82.2	0	2	132	944 Turbo	0.53	Rich	1	14.7	-9.69	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:2	34.08	2188	1.41	13.41	98	194	Off Idle	82.4	0	2	132	944 Turbo	0.45	Rich	1	14.7	-9.66	15.13	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:43:2	34.08	2177	1.41	13.42	98	194	Off Idle	82.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-9.62	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:3	34.08	2181	1.42	13.43	98	194	Off Idle	82.6	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.58	15.08	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:3	34.08	2181	1.42	13.43	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.56	15.09	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:3	34.08	2179	1.42	13.44	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.22	Lean	1	14.7	-9.59	15.07	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:3	34.08	2179	1.43	13.44	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.58	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:3	34.08	2180	1.43	13.43	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.53	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:3	34.08	2184	1.44	13.43	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.5	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:4	34.08	2191	1.44	13.44	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.1	Lean	1	14.7	-9.46	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:4	34.08	2191	1.44	13.43	98	194	Off Idle	83.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.46	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:4	34.08	2198	1.44	13.42	98	194	Off Idle	83.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.46	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:4	34.08	2203	1.45	13.41	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.44	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:4	34.08	2205	1.45	13.41	98	194	Off Idle	83.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.4	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:4	34.08	2210	1.46	13.4	98	194	Off Idle	83.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.4	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:4	34.08	2212	1.46	13.41	98	194	Off Idle	83.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.39	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:5	34.08	2214	1.46	13.4	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.4	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:5	34.08	2214	1.47	13.4	98	194	Off Idle	83.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.43	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:5	34.08	2217	1.47	13.38	98	194	Off Idle	83.1	0	2	132	944 Turbo	0.19	Lean	1	14.7	-9.45	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:5	34.08	2214	1.48	13.39	98	194	Off Idle	83.1	0	2	132	944 Turbo	0.28	Lean	1	14.7	-9.4	15.11	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:5	34.08	2214	1.48	13.41	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.34	Lean	1	14.7	-9.37	15.13	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:5	34.08	2218	1.48	13.42	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.4	Lean	1	14.7	-9.35	15.16	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:6	34.08	2227	1.48	13.43	98	194	Off Idle	82.6	0	2	132	944 Turbo	0.47	Lean	1	14.7	-9.34	15.17	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:6	34.08	2215	1.48	13.42	98	194	Off Idle	82.5	0	2	132	944 Turbo	0.53	Lean	1	14.7	-9.35	15.19	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:6	34.08	2215	1.48	13.43	98	194	Off Idle	82.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-9.35	15.21	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:6	34.08	2204	1.49	13.43	98	194	Off Idle	81.9	0	2	132	944 Turbo	0.65	Rich	1	14.7	-9.35	15.21	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:6	34.08	2192	1.49	13.44	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.34	15.22	1.04	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:6	34.08	2182	1.49	13.44	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.32	15.24	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:43:6	34.08	2186	1.49	13.42	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.29	15.25	1.04	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:7	34.08	2182	1.5	13.42	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.28	15.24	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:7	34.08	2174	1.5	13.42	98	194	Off Idle	81.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.26	15.21	1.04	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:7	34.08	2174	1.5	13.42	98	194	Off Idle	82	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.25	15.19	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:7	34.08	2174	1.5	13.43	98	194	Off Idle	82.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.22	15.17	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:7	34.08	2175	1.51	13.43	98	194	Off Idle	82	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.25	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:7	34.08	2177	1.51	13.41	98	194	Off Idle	82.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.25	15.15	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:8	34.08	2182	1.51	13.41	98	194	Off Idle	82.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.24	15.14	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:8	34.08	2186	1.51	13.42	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.21	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:8	34.08	2187	1.51	13.42	98	194	Off Idle	83	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.21	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:8	34.08	2188	1.52	13.43	98	194	Off Idle	83.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.17	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:8	34.08	2190	1.52	13.44	98	194	Off Idle	83.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.18	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:8	34.08	2192	1.52	13.43	98	194	Off Idle	83.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.19	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:9	34.08	2192	1.52	13.42	98	194	Off Idle	83.6	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.18	14.95	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:9	34.08	2194	1.52	13.43	98	194	Off Idle	83.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.2	14.93	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:9	34.08	2193	1.52	13.43	98	194	Off Idle	83.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.21	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:9	34.08	2195	1.52	13.42	98	194	Off Idle	83.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.2	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:9	34.08	2195	1.52	13.43	98	194	Off Idle	83.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.19	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:43:9	34.08	2194	1.52	13.43	98	194	Off Idle	83.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-9.18	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:43:9	34.08	2192	1.52	13.44	98	194	Off Idle	83.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.19	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:44:0	34.08	2192	1.53	13.43	98	194	Off Idle	83.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.19	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:44:0	34.08	2189	1.53	13.43	98	194	Off Idle	83.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-9.15	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:44:0	34.08	2185	1.53	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.13	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:0	34.08	2185	1.53	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.13	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:0	34.08	2185	1.53	13.43	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.12	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:0	34.08	2184	1.53	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.79	Rich	1	14.7	-9.09	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:1	34.08	2183	1.53	13.43	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.08	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:1	34.08	2184	1.54	13.43	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.09	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:1	34.08	2185	1.54	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-9.06	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:1	32.72	2167	1.54	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-9	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:1	32.72	2177	1.55	13.43	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.94	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:1	32.72	2188	1.56	13.43	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.93	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:44:1	32.72	2189	1.56	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.89	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:2	32.72	2189	1.57	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-8.85	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:2	32.72	2194	1.58	13.41	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.82	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:2	32.72	2199	1.58	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.8	14.79	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:2	34.08	2208	1.59	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.78	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:2	34.08	2199	1.6	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.73	14.77	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:2	34.08	2203	1.61	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.66	14.75	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:3	34.08	2203	1.61	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.65	14.73	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:3	34.08	2207	1.62	13.42	98	194	Off Idle	83.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.61	14.71	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:3	34.08	2210	1.63	13.41	98	194	Off Idle	83.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.58	14.71	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:3	34.08	2210	1.64	13.43	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.56	14.67	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:3	34.08	2210	1.65	13.43	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-8.58	14.63	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:3	34.08	2208	1.65	13.42	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.57	14.61	1	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:4	34.08	2207	1.66	13.41	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-8.56	14.59	0.99	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:4	34.08	2207	1.66	13.41	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-8.52	14.56	0.99	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:4	34.08	2208	1.67	13.42	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-8.48	14.54	0.99	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:4	34.08	2206	1.68	13.45	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-8.41	14.51	0.99	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:4	34.08	2204	1.68	13.44	98	194	Off Idle	82.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-8.39	14.49	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:44:4	34.08	2201	1.69	13.43	98	194	Off Idle	82.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.39	14.48	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:44:4	34.08	2198	1.69	13.43	98	194	Off Idle	82.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.37	14.47	0.99	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:44:5	34.08	2193	1.69	13.43	98	194	Off Idle	82.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.38	14.45	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:44:5	34.08	2193	1.7	13.44	98	194	Off Idle	82.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.34	14.44	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:44:5	34.08	2190	1.7	13.45	98	194	Off Idle	82.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.29	14.43	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:44:5	34.08	2193	1.71	13.44	98	194	Off Idle	82.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.28	14.41	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:44:5	34.08	2193	1.72	13.43	98	194	Off Idle	82.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.23	14.39	0.98	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:5	34.08	2197	1.72	13.43	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.21	14.36	0.98	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:44:6	34.08	2204	1.72	13.43	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.18	14.33	0.98	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:44:6	34.08	2211	1.73	13.41	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.14	14.29	0.97	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:6	34.08	2212	1.74	13.41	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-8.1	14.24	0.97	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:6	34.08	2214	1.74	13.41	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-8.08	14.19	0.97	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:6	34.08	2214	1.75	13.42	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-8.06	14.14	0.96	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:6	34.08	2214	1.75	13.39	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-8.06	14.1	0.96	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:6	34.08	2210	1.76	13.39	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-8.02	14.05	0.96	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:7	34.08	2206	1.77	13.4	98	194	Off Idle	82.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.99	13.98	0.95	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:7	34.08	2205	1.77	13.41	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.98	13.94	0.95	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:7	34.08	2204	1.77	13.42	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.97	13.91	0.95	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:7	34.08	2202	1.78	13.42	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.93	13.88	0.95	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:7	34.08	2202	1.78	13.42	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.88	13.86	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:7	34.08	2202	1.79	13.43	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.88	13.85	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:8	34.08	2206	1.79	13.42	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.84	13.83	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:8	34.08	2211	1.79	13.41	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.82	13.82	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:8	34.08	2211	1.79	13.42	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.84	13.8	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:8	34.08	2210	1.8	13.41	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.88	13.79	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:8	34.08	2224	1.8	13.4	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.88	13.76	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:8	34.08	2222	1.8	13.41	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.89	13.75	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:9	32.72	2214	1.8	13.41	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.87	13.74	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:9	32.72	2224	1.8	13.42	98	194	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.84	13.72	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:9	32.72	2225	1.81	13.43	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.81	13.7	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:9	32.72	2225	1.81	13.43	98	194	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.81	13.71	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:9	32.72	2226	1.81	13.43	98	194	Off Idle	82.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.79	13.69	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:9	32.72	2227	1.81	13.44	98	194	Off Idle	82.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.76	13.67	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:44:9	32.72	2226	1.81	13.43	98	194	Off Idle	82.3	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.76	13.67	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:0	32.72	2225	1.81	13.42	98	194	Off Idle	82.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.75	13.67	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:0	32.72	2224	1.82	13.43	98	194	Off Idle	82.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.73	13.68	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:0	32.72	2222	1.82	13.42	98	194	Off Idle	81.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.74	13.69	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:0	32.72	2220	1.82	13.43	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.75	13.69	0.93	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:0	32.72	2212	1.82	13.44	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.69	13.71	0.93	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:0	32.72	2224	1.83	13.44	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.68	13.68	0.93	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:1	32.72	2231	1.83	13.44	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.67	13.69	0.93	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:1	32.72	2231	1.83	13.44	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.65	13.69	0.93	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:1	32.72	2243	1.83	13.45	98	194	Off Idle	81.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.66	13.72	0.93	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:1	32.72	2246	1.83	13.45	98	194	Off Idle	81.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.69	13.72	0.93	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:1	32.72	2240	1.83	13.45	98	194	Off Idle	81.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.69	13.73	0.93	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:1	32.72	2242	1.84	13.44	98	194	Off Idle	81.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.69	13.74	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:1	32.72	2246	1.84	13.44	98	194	Off Idle	81.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.67	13.74	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:2	32.72	2252	1.84	13.44	98	194	Off Idle	81.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.66	13.76	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:2	34.08	2243	1.84	13.42	98	194	Off Idle	81.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.66	13.76	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:2	34.08	2242	1.84	13.42	98	194	Off Idle	81.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.66	13.78	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:2	34.08	2241	1.85	13.42	98	194	Off Idle	81.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.69	13.8	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:2	34.08	2236	1.85	13.41	98	194	Off Idle	81.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.71	13.8	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:2	34.08	2237	1.85	13.4	98	194	Off Idle	81.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.69	13.8	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:3	34.08	2237	1.85	13.41	98	194	Off Idle	81.1	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.65	13.81	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:3	32.72	2233	1.85	13.42	98	194	Off Idle	81	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.63	13.82	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:3	32.72	2245	1.85	13.42	98	194	Off Idle	80.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.62	13.83	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:3	32.72	2245	1.85	13.42	98	194	Off Idle	80.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.59	13.83	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:3	32.72	2242	1.86	13.43	98	194	Off Idle	80.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.6	13.83	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:3	32.72	2239	1.86	13.41	98	194	Off Idle	80.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.63	13.83	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:4	32.72	2239	1.86	13.4	98	194	Off Idle	80.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.63	13.85	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:4	32.72	2240	1.86	13.42	98	194	Off Idle	80.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.59	13.84	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:4	32.72	2242	1.86	13.42	98	194	Off Idle	80.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.6	13.85	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:4	32.72	2246	1.86	13.41	98	194	Off Idle	80.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.58	13.87	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:4	32.72	2246	1.86	13.41	98	194	Off Idle	80.9	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.55	13.86	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:4	32.72	2258	1.87	13.43	98	194	Off Idle	81	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.56	13.87	0.94	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:4	32.72	2255	1.87	13.43	98	194	Off Idle	80.9	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.55	13.84	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:45:5	32.72	2256	1.87	13.43	98	194	Off Idle	80.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-7.55	13.84	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:5	32.72	2258	1.87	13.43	98	194	Off Idle	80.5	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.53	13.84	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:5	32.72	2258	1.87	13.43	98	194	Off Idle	80.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.51	13.85	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:5	32.72	2258	1.87	13.44	98	194	Off Idle	80.4	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.54	13.84	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:5	32.72	2258	1.87	13.45	98	194	Off Idle	80	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.53	13.84	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:5	32.72	2257	1.87	13.44	98	194	Off Idle	79.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.55	13.85	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:6	32.72	2257	1.87	13.44	98	194	Off Idle	80	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.59	13.84	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:6	32.72	2258	1.87	13.43	98	194	Off Idle	79.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-7.63	13.84	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:6	32.72	2273	1.87	13.41	98	194	Off Idle	79.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.62	13.85	0.94	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:45:6	34.08	2273	1.87	13.41	98	194	Off Idle	79.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-7.6	13.88	0.95	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:6	34.08	2256	1.87	13.41	98	194	Off Idle	79.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.59	13.89	0.95	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:6	34.08	2257	1.87	13.41	98	194	Off Idle	79.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-7.59	13.9	0.95	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:6	34.08	2249	1.87	13.43	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.59	13.92	0.95	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:7	34.08	2262	1.87	13.42	98	194	Off Idle	79	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.62	13.93	0.95	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:7	34.08	2267	1.87	13.41	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-7.65	13.95	0.95	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:7	34.08	2267	1.87	13.43	98	194	Off Idle	79.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.6	13.96	0.95	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:7	34.08	2278	1.87	13.44	98	194	Off Idle	79.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.61	13.97	0.95	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:7	34.08	2270	1.86	13.42	98	194	Off Idle	79.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.62	13.98	0.95	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:7	34.08	2270	1.86	13.42	98	194	Off Idle	79.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.65	14	0.95	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:8	34.08	2268	1.86	13.43	98	194	Off Idle	79.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.63	14	0.95	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:8	34.08	2269	1.86	13.43	98	194	Off Idle	79.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.67	14.01	0.95	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:8	34.08	2270	1.86	13.42	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.68	14.01	0.95	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:8	34.08	2269	1.86	13.43	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.64	14.03	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:8	34.08	2272	1.86	13.44	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.65	14.03	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:8	34.08	2272	1.86	13.43	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.83	Rich	1	14.7	-7.64	14.03	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:9	34.08	2272	1.86	13.43	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-7.63	14.05	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:9	34.08	2275	1.86	13.43	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-7.63	14.05	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:9	34.08	2278	1.86	13.42	98	194	Off Idle	79.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-7.66	14.05	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:9	34.08	2277	1.86	13.41	98	194	Off Idle	79.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-7.65	14.06	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:9	34.08	2278	1.86	13.4	98	194	Off Idle	78.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-7.64	14.08	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:9	34.08	2282	1.86	13.4	98	194	Off Idle	78.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-7.62	14.09	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:45:9	34.08	2282	1.86	13.41	98	194	Off Idle	78.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-7.61	14.1	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:0	34.08	2280	1.87	13.42	98	194	Off Idle	78.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-7.58	14.12	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:0	34.08	2281	1.87	13.41	98	194	Off Idle	78.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-7.58	14.14	0.96	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:0	34.08	2281	1.87	13.43	98	194	Off Idle	78.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-7.5	14.17	0.97	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:0	34.08	2286	1.88	13.43	98	194	Off Idle	78.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-7.46	14.2	0.97	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:0	34.08	2289	1.88	13.43	98	194	Off Idle	78.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-7.42	14.22	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:46:0	34.08	2289	1.89	13.42	98	194	Off Idle	78.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-7.38	14.25	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:46:1	34.08	2289	1.9	13.41	98	194	Off Idle	78	0	2	132	944 Turbo	0.81	Rich	1	14.7	-7.23	14.27	0.97	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:46:1	34.08	2288	1.91	13.43	98	194	Off Idle	77.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	-7.14	14.33	0.98	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:1	34.08	2292	1.92	13.42	98	194	Off Idle	77.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	-7.07	14.34	0.98	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:1	34.08	2277	1.93	13.41	98	194	Off Idle	77.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	-6.99	14.37	0.98	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:1	32.72	2277	1.95	13.4	98	194	Off Idle	77.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	-6.91	14.39	0.98	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:1	32.72	2299	1.96	13.4	98	194	Off Idle	77.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-6.82	14.4	0.98	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:1	32.72	2300	1.97	13.4	98	194	Off Idle	77.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	-6.75	14.43	0.98	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:2	32.72	2299	1.98	13.4	98	194	Off Idle	77.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	-6.69	14.45	0.98	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:2	32.72	2299	1.99	13.4	98	194	Off Idle	77.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	-6.59	14.48	0.99	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:46:2	32.72	2306	2.01	13.42	98	194	Off Idle	77.6	0	2	132	944 Turbo	0.77	Rich	1	14.7	-6.56	14.49	0.99	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:46:2	32.72	2309	2.02	13.43	98	194	Off Idle	77.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-6.53	14.51	0.99	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:46:2	32.72	2308	2.03	13.41	98	194	Off Idle	77.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.44	14.51	0.99	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:46:2	32.72	2313	2.04	13.41	98	194	Off Idle	77.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.42	14.56	0.99	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:46:3	32.72	2313	2.05	13.41	98	194	Off Idle	77.4	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.33	14.59	0.99	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:46:3	32.72	2313	2.06	13.41	98	194	Off Idle	77.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.29	14.62	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:46:3	32.72	2311	2.07	13.39	98	194	Off Idle	77.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.23	14.66	1	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:46:3	32.72	2313	2.08	13.43	98	194	Off Idle	77.2	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.15	14.69	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:46:3	32.72	2312	2.09	13.43	98	194	Off Idle	77.2	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.1	14.72	1	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:46:3	32.72	2313	2.1	13.41	98	194	Off Idle	76.9	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.06	14.76	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:46:4	32.72	2316	2.11	13.43	98	194	Off Idle	76.8	0	2	132	944 Turbo	0.74	Rich	1	14.7	-5.95	14.77	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:46:4	32.72	2318	2.11	13.44	98	194	Off Idle	76.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-5.9	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:27:46:4	32.72	2318	2.12	13.42	98	194	Off Idle	76.8	0	2	132	944 Turbo	0.71	Rich	1	14.7	-5.8	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:27:46:4	32.72	2334	2.14	13.43	98	194	Off Idle	76.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	-5.7	14.84	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:27:46:4	32.72	2323	2.15	13.44	98	194	Off Idle	76.7	0	2	132	944 Turbo	0.63	Rich	1	14.7	-5.6	14.85	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:27:46:4	32.72	2324	2.16	13.42	98	194	Off Idle	76.8	0	2	132	944 Turbo	0.58	Lean	1	14.7	-5.52	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:46:4	32.72	2330	2.18	13.43	98	194	Off Idle	76.8	0	2	132	944 Turbo	0.5	Lean	1	14.7	-5.35	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:46:5	32.72	2336	2.19	13.43	98	194	Off Idle	76.8	0	2	132	944 Turbo	0.44	Lean	1	14.7	-5.25	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:27:46:5	32.72	2342	2.2	13.41	98	194	Off Idle	76.8	0	2	132	944 Turbo	0.38	Lean	1	14.7	-5.16	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:27:46:5	32.72	2344	2.22	13.42	98	194	Off Idle	76.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-5.04	14.82	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:5	32.72	2351	2.22	13.42	98	194	Off Idle	76.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-4.99	14.82	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:5	32.72	2356	2.24	13.42	98	194	Off Idle	76.1	0	2	132	944 Turbo	0.22	Lean	1	14.7	-4.86	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:5	32.72	2362	2.25	13.42	98	194	Off Idle	76	0	2	132	944 Turbo	0.17	Lean	1	14.7	-4.78	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:6	32.72	2364	2.26	13.42	98	194	Off Idle	75.8	0	2	132	944 Turbo	0.15	Lean	1	14.7	-4.7	14.87	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:6	32.72	2365	2.28	13.43	98	194	Off Idle	75.7	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.59	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:6	32.72	2365	2.29	13.43	98	194	Off Idle	75.5	0	2	132	944 Turbo	0.15	Lean	1	14.7	-4.55	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:6	32.72	2365	2.3	13.43	98	194	Off Idle	75.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-4.55	14.97	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:6	32.72	2364	2.31	13.42	98	194	Off Idle	75.2	0	2	132	944 Turbo	0.26	Lean	1	14.7	-4.46	15.03	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:6	32.72	2362	2.32	13.43	98	194	Off Idle	75	0	2	132	944 Turbo	0.31	Lean	1	14.7	-4.43	15.07	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:6	32.72	2361	2.33	13.42	98	194	Off Idle	74.7	0	2	132	944 Turbo	0.37	Lean	1	14.7	-4.41	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:7	32.72	2361	2.34	13.43	98	194	Off Idle	74.6	0	2	132	944 Turbo	0.44	Lean	1	14.7	-4.36	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:7	32.72	2363	2.35	13.44	98	194	Off Idle	74.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	-4.34	15.17	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:7	32.72	2370	2.35	13.43	98	194	Off Idle	74.3	0	2	132	944 Turbo	0.57	Lean	1	14.7	-4.28	15.2	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:7	32.72	2372	2.36	13.42	98	194	Off Idle	74.3	0	2	132	944 Turbo	0.63	Lean	1	14.7	-4.23	15.21	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:7	32.72	2374	2.36	13.41	98	194	Off Idle	74.3	0	2	132	944 Turbo	0.68	Rich	1	14.7	-4.18	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:7	32.72	2381	2.36	13.41	98	194	Off Idle	74.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-4.18	15.15	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:8	32.72	2383	2.37	13.41	98	194	Off Idle	74.1	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.14	15.11	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:8	32.72	2380	2.37	13.42	98	194	Off Idle	74	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.11	15.06	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:8	32.72	2382	2.38	13.42	98	194	Off Idle	73.9	0	2	132	944 Turbo	0.73	Rich	1	14.7	-4.14	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:46:8	32.72	2391	2.38	13.44	98	194	Off Idle	73.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-4.13	14.97	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:8	32.72	2392	2.38	13.43	98	194	Off Idle	73.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-4.14	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:8	32.72	2399	2.38	13.43	98	194	Off Idle	73.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-4.14	14.91	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:9	32.72	2407	2.39	13.41	98	194	Off Idle	73.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-4.14	14.83	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:9	32.72	2404	2.39	13.43	98	194	Off Idle	73.3	0	2	132	944 Turbo	0.55	Rich	1	14.7	-4.13	14.82	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:46:9	32.72	2406	2.39	13.42	98	194	Off Idle	73	0	2	132	944 Turbo	0.49	Lean	1	14.7	-4.12	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:46:9	32.72	2412	2.39	13.42	98	194	Off Idle	72.7	0	2	132	944 Turbo	0.43	Lean	1	14.7	-4.12	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:46:9	32.72	2424	2.39	13.42	98	194	Off Idle	72.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-4.13	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:46:9	32.72	2424	2.39	13.42	98	194	Off Idle	72.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-4.13	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:46:9	32.72	2412	2.4	13.43	98	194	Off Idle	72.3	0	2	132	944 Turbo	0.26	Lean	1	14.7	-4.14	14.84	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:0	32.72	2415	2.4	13.42	98	194	Off Idle	72	0	2	132	944 Turbo	0.21	Lean	1	14.7	-4.14	14.86	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:0	32.72	2415	2.4	13.42	98	194	Off Idle	72	0	2	132	944 Turbo	0.16	Lean	1	14.7	-4.1	14.88	1.01	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:0	32.72	2407	2.4	13.41	98	194	Off Idle	71.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-4.09	14.92	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:0	32.72	2433	2.4	13.42	98	194	Off Idle	71.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-4.08	14.96	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:0	32.72	2443	2.4	13.43	98	194	Off Idle	71.2	0	2	132	944 Turbo	0.12	Lean	1	14.7	-4.07	14.98	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:0	32.72	2445	2.4	13.45	98	194	Off Idle	71.1	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.12	15.03	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:1	32.72	2469	2.4	13.44	98	194	Off Idle	70.9	0	2	132	944 Turbo	0.17	Lean	1	14.7	-4.14	15.08	1.03	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:1	32.72	2458	2.41	13.43	98	194	Off Idle	70.8	0	2	132	944 Turbo	0.22	Lean	1	14.7	-4.14	15.12	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:1	32.72	2458	2.41	13.42	98	194	Off Idle	70.6	0	2	132	944 Turbo	0.28	Lean	1	14.7	-4.15	15.15	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:1	32.72	2456	2.41	13.42	98	194	Off Idle	70.3	0	2	132	944 Turbo	0.37	Lean	1	14.7	-4.18	15.17	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:1	32.72	2452	2.41	13.42	98	194	Off Idle	70.1	0	2	132	944 Turbo	0.43	Lean	1	14.7	-4.17	15.18	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:1	32.72	2452	2.41	13.43	98	194	Off Idle	69.9	0	2	132	944 Turbo	0.49	Lean	1	14.7	-4.19	15.17	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:1	32.72	2449	2.41	13.42	98	194	Off Idle	69.8	0	2	132	944 Turbo	0.56	Lean	1	14.7	-4.16	15.18	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:2	32.72	2450	2.41	13.43	98	194	Off Idle	69.8	0	2	132	944 Turbo	0.6	Lean	1	14.7	-4.14	15.2	1.04	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:2	32.72	2451	2.42	13.43	98	194	Off Idle	69.5	0	2	132	944 Turbo	0.64	Lean	1	14.7	-4.1	15.18	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:2	32.72	2446	2.42	13.42	98	194	Off Idle	69.1	0	2	132	944 Turbo	0.66	Lean	1	14.7	-4.1	15.13	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:2	32.72	2461	2.42	13.41	98	194	Off Idle	69.1	0	2	132	944 Turbo	0.65	Lean	1	14.7	-4.08	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:2	32.72	2462	2.42	13.4	98	194	Off Idle	69.1	0	2	132	944 Turbo	0.61	Lean	1	14.7	-4.09	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:2	32.72	2470	2.42	13.41	98	194	Off Idle	69	0	2	132	944 Turbo	0.55	Lean	1	14.7	-4.04	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:3	32.72	2475	2.42	13.42	98	194	Off Idle	68.8	0	2	132	944 Turbo	0.49	Lean	1	14.7	-4.08	15.03	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:47:3	32.72	2475	2.43	13.43	98	194	Off Idle	68.7	0	2	132	944 Turbo	0.43	Lean	1	14.7	-4.06	15.02	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:3	32.72	2488	2.43	13.42	98	194	Off Idle	68.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-4.08	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:3	32.72	2493	2.43	13.44	98	194	Off Idle	68.1	0	2	132	944 Turbo	0.3	Lean	1	14.7	-4.08	14.9	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:3	32.72	2493	2.43	13.42	98	194	Off Idle	68.1	0	2	132	944 Turbo	0.25	Lean	1	14.7	-4.13	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:3	32.72	2490	2.44	13.42	98	194	Off Idle	68.1	0	2	132	944 Turbo	0.18	Lean	1	14.7	-4.1	14.87	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:4	32.72	2490	2.44	13.41	98	194	Off Idle	68.1	0	2	132	944 Turbo	0.17	Lean	1	14.7	-4.08	14.9	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:4	32.72	2490	2.44	13.41	98	194	Off Idle	68.1	0	2	132	944 Turbo	0.19	Lean	1	14.7	-4.05	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:4	32.72	2490	2.44	13.42	98	194	Off Idle	67.8	0	2	132	944 Turbo	0.23	Lean	1	14.7	-4.04	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:4	32.72	2492	2.44	13.43	98	194	Off Idle	67.7	0	2	132	944 Turbo	0.28	Lean	1	14.7	-4.07	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:4	32.72	2494	2.45	13.42	98	194	Off Idle	67.7	0	2	132	944 Turbo	0.34	Lean	1	14.7	-4.04	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:4	32.72	2496	2.45	13.42	98	194	Off Idle	67.5	0	2	132	944 Turbo	0.4	Lean	1	14.7	-4.05	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:4	32.72	2496	2.45	13.41	98	194	Off Idle	67.4	0	2	132	944 Turbo	0.47	Lean	1	14.7	-4.05	15.08	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:5	32.72	2499	2.45	13.41	98	194	Off Idle	67.2	0	2	132	944 Turbo	0.53	Lean	1	14.7	-4.06	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:5	32.72	2499	2.45	13.43	98	194	Off Idle	67.1	0	2	132	944 Turbo	0.62	Lean	1	14.7	-4.08	15.16	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:5	32.72	2507	2.45	13.41	98	194	Off Idle	66.9	0	2	132	944 Turbo	0.66	Lean	1	14.7	-4.09	15.17	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:5	32.72	2511	2.45	13.42	98	194	Off Idle	66.9	0	2	132	944 Turbo	0.68	Rich	1	14.7	-4.07	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:5	32.72	2519	2.46	13.43	98	194	Off Idle	66.9	0	2	132	944 Turbo	0.66	Rich	1	14.7	-4.07	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:5	32.72	2519	2.46	13.43	98	194	Off Idle	66.8	0	2	132	944 Turbo	0.64	Rich	1	14.7	-4.1	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:47:6	32.72	2528	2.46	13.43	98	194	Off Idle	66.6	0	2	132	944 Turbo	0.61	Rich	1	14.7	-4.05	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:6	32.72	2528	2.46	13.42	98	194	Off Idle	66.5	0	2	132	944 Turbo	0.56	Rich	1	14.7	-4.06	14.98	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:6	32.72	2536	2.46	13.43	98	194	Off Idle	66.3	0	2	132	944 Turbo	0.5	Rich	1	14.7	-4.05	14.96	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:6	32.72	2540	2.46	13.42	98	194	Off Idle	66.1	0	2	132	944 Turbo	0.4	Rich	1	14.7	-4.04	14.92	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:6	32.72	2540	2.47	13.43	98	194	Off Idle	65.9	0	2	132	944 Turbo	0.34	Rich	1	14.7	-4.07	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:6	32.72	2543	2.47	13.41	98	194	Off Idle	65.6	0	2	132	944 Turbo	0.28	Rich	1	14.7	-4.04	14.81	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:6	32.72	2546	2.47	13.42	98	194	Off Idle	65.3	0	2	132	944 Turbo	0.22	Rich	1	14.7	-4.02	14.81	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:7	32.72	2548	2.47	13.42	98	194	Off Idle	65	0	2	132	944 Turbo	0.17	Lean	1	14.7	-4.02	14.83	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:47:7	32.72	2548	2.47	13.43	98	194	Off Idle	64.7	0	2	132	944 Turbo	0.15	Lean	1	14.7	-4.03	14.87	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:47:7	32.72	2550	2.47	13.43	98	194	Off Idle	64.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-4.02	14.91	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:47:7	32.72	2554	2.48	13.43	98	194	Off Idle	64.2	0	2	132	944 Turbo	0.19	Lean	1	14.7	-4.04	14.95	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:47:7	32.72	2561	2.48	13.43	98	194	Off Idle	64	0	2	132	944 Turbo	0.24	Lean	1	14.7	-3.98	15	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:47:7	32.72	2562	2.48	13.42	98	194	Off Idle	64	0	2	132	944 Turbo	0.3	Lean	1	14.7	-3.97	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:8	32.72	2578	2.48	13.44	98	194	Off Idle	63.9	0	2	132	944 Turbo	0.36	Lean	1	14.7	-3.96	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:8	32.72	2569	2.48	13.43	98	194	Off Idle	63.6	0	2	132	944 Turbo	0.42	Lean	1	14.7	-4	15.09	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:8	32.72	2570	2.49	13.42	98	194	Off Idle	63.3	0	2	132	944 Turbo	0.48	Lean	1	14.7	-3.95	15.13	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:8	32.72	2570	2.49	13.43	98	194	Off Idle	63	0	2	132	944 Turbo	0.54	Lean	1	14.7	-3.97	15.16	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:8	32.72	2548	2.49	13.44	98	194	Off Idle	62.7	0	2	132	944 Turbo	0.6	Rich	1	14.7	-4.02	15.16	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:8	32.72	2548	2.49	13.44	98	194	Off Idle	62.6	0	2	132	944 Turbo	0.67	Rich	1	14.7	-4.01	15.14	1.03	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:9	32.72	2575	2.49	13.44	98	194	Off Idle	62.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-4.01	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:9	32.72	2577	2.5	13.43	98	194	Off Idle	62.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-4	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:9	32.72	2585	2.5	13.43	98	194	Off Idle	62.2	0	2	132	944 Turbo	0.7	Rich	1	14.7	-4.02	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:9	32.72	2585	2.5	13.44	98	194	Off Idle	62.1	0	2	132	944 Turbo	0.68	Rich	1	14.7	-4.04	15.03	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:9	32.72	2584	2.5	13.42	98	194	Off Idle	61.9	0	2	132	944 Turbo	0.61	Rich	1	14.7	-4.06	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:47:9	32.72	2586	2.5	13.43	98	194	Off Idle	61.7	0	2	132	944 Turbo	0.55	Rich	1	14.7	-4.06	14.98	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:47:9	32.72	2588	2.5	13.44	98	194	Off Idle	61.6	0	2	132	944 Turbo	0.49	Rich	1	14.7	-4.05	14.93	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:0	32.72	2595	2.5	13.43	98	194	Off Idle	61.5	0	2	132	944 Turbo	0.43	Rich	1	14.7	-4.03	14.9	1.01	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:0	32.72	2600	2.51	13.44	98	194	Off Idle	61.3	0	2	132	944 Turbo	0.37	Lean	1	14.7	-4.01	14.81	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:0	32.72	2600	2.51	13.43	98	194	Off Idle	61.3	0	2	132	944 Turbo	0.31	Lean	1	14.7	-4	14.8	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:0	32.72	2606	2.51	13.42	98	194	Off Idle	61.3	0	2	132	944 Turbo	0.25	Lean	1	14.7	-3.94	14.8	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:0	32.72	2614	2.51	13.41	98	194	Off Idle	61.3	0	2	132	944 Turbo	0.2	Lean	1	14.7	-3.94	14.82	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:0	32.72	2614	2.52	13.42	98	194	Off Idle	61.3	0	2	132	944 Turbo	0.16	Lean	1	14.7	-3.82	14.87	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:27:48:1	32.72	2614	2.53	13.42	98	194	Off Idle	61.3	0	2	132	944 Turbo	0.16	Lean	1	14.7	-3.73	14.9	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:27:48:1	32.72	2622	2.54	13.42	98	194	Off Idle	61.3	0	2	132	944 Turbo	0.18	Lean	1	14.7	-3.66	14.94	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:27:48:1	32.72	2626	2.55	13.42	98	194	Off Idle	61.3	0	2	132	944 Turbo	0.24	Lean	1	14.7	-3.52	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:1	32.72	2627	2.56	13.43	98	194	Off Idle	61.1	0	2	132	944 Turbo	0.26	Lean	1	14.7	-3.45	15.01	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:1	32.72	2633	2.56	13.43	98	194	Off Idle	61	0	2	132	944 Turbo	0.3	Lean	1	14.7	-3.4	15.05	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:1	32.72	2639	2.57	13.44	98	194	Off Idle	60.8	0	2	132	944 Turbo	0.35	Lean	1	14.7	-3.29	15.09	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:27:48:1	32.72	2639	2.58	13.42	98	194	Off Idle	60.6	0	2	132	944 Turbo	0.4	Lean	1	14.7	-3.2	15.12	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:27:48:2	32.72	2646	2.59	13.43	98	194	Off Idle	60.5	0	2	132	944 Turbo	0.46	Lean	1	14.7	-3.05	15.13	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:48:2	32.72	2664	2.6	13.41	98	194	Off Idle	60.3	0	2	132	944 Turbo	0.52	Lean	1	14.7	-3.03	15.11	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:2	32.72	2658	2.6	13.42	98	194	Off Idle	60	0	2	132	944 Turbo	0.57	Lean	1	14.7	-2.98	15.09	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:2	32.72	2658	2.61	13.41	98	194	Off Idle	59.7	0	2	132	944 Turbo	0.61	Lean	1	14.7	-2.87	15.09	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:2	32.72	2658	2.62	13.42	98	194	Off Idle	59.4	0	2	132	944 Turbo	0.65	Lean	1	14.7	-2.86	15.07	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:2	32.72	2657	2.63	13.43	98	194	Off Idle	59.1	0	2	132	944 Turbo	0.67	Lean	1	14.7	-2.83	15.06	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:3	32.72	2658	2.65	13.44	98	194	Off Idle	58.8	0	2	132	944 Turbo	0.72	Lean	1	14.7	-2.77	15.04	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:3	32.72	2662	2.66	13.43	98	194	Off Idle	58.5	0	2	132	944 Turbo	0.75	Lean	1	14.7	-2.7	14.98	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:3	32.72	2665	2.67	13.45	98	194	Off Idle	58.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.71	14.93	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:3	32.72	2668	2.68	13.46	98	194	Off Idle	58	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.67	14.89	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:3	32.72	2672	2.68	13.44	98	194	Off Idle	57.5	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.57	14.83	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:3	32.72	2681	2.69	13.43	98	194	Off Idle	57.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.46	14.77	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:4	32.72	2692	2.69	13.44	98	194	Off Idle	57.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.47	14.75	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:27:48:4	32.72	2693	2.7	13.42	98	194	Off Idle	57.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.37	14.69	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:27:48:4	32.72	2696	2.7	13.41	98	194	Off Idle	57	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.36	14.65	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:27:48:4	32.72	2701	2.71	13.43	98	194	Off Idle	56.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.33	14.61	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:27:48:4	32.72	2705	2.72	13.43	98	194	Off Idle	56.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.3	14.62	1	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:27:48:4	32.72	2707	2.72	13.42	98	194	Off Idle	56.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.25	14.61	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:4	32.72	2714	2.73	13.44	98	194	Off Idle	56.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.25	14.61	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:5	32.72	2717	2.74	13.44	98	194	Off Idle	56.1	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.18	14.62	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:5	32.72	2718	2.74	13.43	98	194	Off Idle	56	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.07	14.62	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:5	32.72	2727	2.75	13.43	98	194	Off Idle	55.8	0	2	132	944 Turbo	0.77	Rich	1	14.7	-2.01	14.63	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:5	32.72	2725	2.76	13.43	98	194	Off Idle	55.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.85	14.64	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:5	32.72	2724	2.77	13.42	98	194	Off Idle	55.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.72	14.67	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:27:48:5	32.72	2733	2.77	13.43	98	194	Off Idle	55	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.63	14.68	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:27:48:6	32.72	2770	2.78	13.42	98	194	Off Idle	54.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.59	14.69	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:27:48:6	32.72	2753	2.79	13.43	98	194	Off Idle	54.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	-1.48	14.7	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:27:48:6	32.72	2753	2.8	13.42	98	194	Off Idle	54.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-1.42	14.72	1	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:6	32.72	2764	2.81	13.42	98	194	Off Idle	54.1	0	2	132	944 Turbo	0.63	Rich	1	14.7	-1.39	14.75	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:27:48:6	32.72	2775	2.82	13.42	98	194	Off Idle	53.9	0	2	132	944 Turbo	0.62	Rich	1	14.7	-1.36	14.77	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:27:48:6	32.72	2786	2.82	13.43	98	194	Off Idle	53.7	0	2	132	944 Turbo	0.62	Rich	1	14.7	-1.28	14.78	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:6	32.72	2784	2.83	13.42	98	194	Off Idle	53.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-1.28	14.8	1.01	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:7	32.72	2786	2.84	13.43	98	194	Off Idle	53.1	0	2	132	944 Turbo	0.63	Rich	1	14.7	-1.21	14.81	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:7	32.72	2789	2.85	13.42	98	194	Off Idle	52.8	0	2	132	944 Turbo	0.64	Rich	1	14.7	-1.15	14.84	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:7	32.72	2791	2.86	13.42	98	194	Off Idle	52.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	-1.12	14.86	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:7	32.72	2786	2.86	13.42	98	194	Off Idle	52.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-1.05	14.89	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:7	32.72	2788	2.88	13.42	98	194	Off Idle	51.8	0	2	132	944 Turbo	0.7	Rich	1	14.7	-1.03	14.89	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:48:7	32.72	2791	2.88	13.4	98	194	Off Idle	51.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.93	14.88	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:8	32.72	2795	2.89	13.41	98	194	Off Idle	51.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.9	14.87	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:48:8	32.72	2790	2.9	13.41	98	194	Off Idle	51.1	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.85	14.88	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:8	31.36	2814	2.9	13.41	98	194	Off Idle	50.8	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.81	14.88	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:8	31.36	2822	2.91	13.4	98	194	Off Idle	50.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.72	14.87	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:8	31.36	2824	2.91	13.42	98	194	Off Idle	50	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.71	14.87	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:8	31.36	2830	2.92	13.41	98	194	Off Idle	49.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.68	14.87	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:9	31.36	2835	2.92	13.41	98	194	Off Idle	49.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.68	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:9	31.36	2831	2.92	13.42	98	194	Off Idle	49	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.62	14.85	1.01	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:48:9	31.36	2831	2.93	13.41	98	194	Off Idle	48.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.62	14.86	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:48:9	31.36	2837	2.93	13.41	98	194	Off Idle	48.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.6	14.86	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:48:9	31.36	2850	2.94	13.4	98	194	Off Idle	48.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.55	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:48:9	31.36	2861	2.95	13.41	98	194	Off Idle	48.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.5	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:48:9	31.36	2861	2.95	13.42	98	194	Off Idle	48.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.5	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:0	31.36	2857	2.95	13.42	98	194	Off Idle	48.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.43	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:0	31.36	2875	2.96	13.41	98	194	Off Idle	48.2	0	2	132	944 Turbo	0.7	Rich	1	14.7	-0.41	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:0	31.36	2875	2.96	13.42	98	194	Off Idle	47.9	0	2	132	944 Turbo	0.7	Rich	1	14.7	-0.35	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:0	31.36	2900	2.97	13.42	98	194	Off Idle	47.2	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.31	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:0	31.36	2896	2.97	13.42	98	194	Off Idle	46.7	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.31	14.87	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:0	31.36	2898	2.98	13.41	98	194	Off Idle	46.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.27	14.88	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:1	31.36	2898	2.98	13.43	98	194	Off Idle	46.2	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.26	14.89	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:1	31.36	2900	2.99	13.42	98	194	Off Idle	45.7	0	2	132	944 Turbo	0.66	Rich	1	14.7	-0.24	14.89	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:49:1	31.36	2902	2.99	13.42	98	194	Off Idle	45.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-0.19	14.89	1.01	3.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:1	31.36	2898	3	13.41	98	194	Off Idle	45.1	0	2	132	944 Turbo	0.56	Rich	1	14.7	-0.05	14.88	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:49:1	31.36	2898	3	13.42	98	194	Off Idle	44.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	-0.11	14.85	1.01	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:49:1	31.36	2894	3.01	13.42	98	194	Off Idle	44.2	0	2	132	944 Turbo	0.44	Rich	1	14.7	0.01	14.82	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:49:1	31.36	2908	3.02	13.42	98	194	Off Idle	44.2	0	2	132	944 Turbo	0.38	Rich	1	14.7	0	14.85	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:49:2	31.36	2926	3.02	13.42	98	194	Off Idle	43.9	0	2	132	944 Turbo	0.28	Rich	1	14.7	0.02	14.89	1.01	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:49:2	31.36	2930	3.03	13.41	98	194	Off Idle	43.6	0	2	132	944 Turbo	0.22	Rich	1	14.7	0.1	14.94	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:49:2	31.36	2948	3.03	13.42	98	194	Off Idle	43.3	0	2	132	944 Turbo	0.16	Rich	1	14.7	0.13	14.99	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:49:2	31.36	2961	3.04	13.41	98	194	Off Idle	43	0	2	132	944 Turbo	0.11	Lean	1	14.7	0.23	15.04	1.02	3.4	5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:2	31.36	2976	3.05	13.41	98	194	Off Idle	42.7	0	2	132	944 Turbo	0.09	Lean	1	14.7	0.28	15.12	1.03	3.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:2	31.36	2993	3.06	13.43	98	194	Off Idle	42.7	0	2	132	944 Turbo	0.08	Lean	1	14.7	0.36	15.19	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:3	31.36	2996	3.06	13.44	98	194	Off Idle	42.6	0	2	132	944 Turbo	0.08	Lean	1	14.7	0.39	15.26	1.04	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:3	31.36	2998	3.07	13.44	98	194	Off Idle	42.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	0.45	15.34	1.04	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:49:3	31.36	3012	3.08	13.45	98	194	Off Idle	42.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	0.5	15.4	1.05	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:49:3	31.36	3002	3.08	13.45	98	194	Off Idle	42.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	0.44	15.42	1.05	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:49:3	31.36	2989	3.09	13.43	98	194	Off Idle	42.3	0	2	132	944 Turbo	0.14	Lean	1	14.7	0.49	15.41	1.05	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:3	31.36	2989	3.1	13.44	98	194	Off Idle	42.1	0	2	132	944 Turbo	0.19	Lean	1	14.7	0.52	15.38	1.05	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:4	29.99	2978	3.1	13.43	98	194	Off Idle	42	0	2	132	944 Turbo	0.25	Rich	1	14.7	0.55	15.37	1.05	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:4	29.99	2987	3.11	13.43	98	194	Off Idle	41.8	0	2	132	944 Turbo	0.31	Rich	1	14.7	0.59	15.37	1.05	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:4	29.99	2986	3.11	13.41	98	194	Off Idle	41.7	0	2	132	944 Turbo	0.38	Rich	1	14.7	0.7	15.32	1.04	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:4	29.99	2990	3.12	13.43	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.7	0.72	15.22	1.04	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:4	29.99	3002	3.13	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.7	0.75	15.15	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:4	29.99	3007	3.13	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.7	0.78	15.09	1.03	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:4	29.99	3012	3.14	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	0.89	15.03	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:5	29.99	3032	3.14	13.44	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	0.88	14.99	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:5	29.99	3032	3.14	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	0.91	14.94	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:5	29.99	3034	3.15	13.42	98	194	Off Idle	41.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	0.85	14.91	1.02	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:5	29.99	3045	3.15	13.42	98	194	Off Idle	41.3	0	2	132	944 Turbo	0.67	Rich	1	14.7	0.87	14.83	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:5	29.99	3057	3.16	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.7	0.84	14.8	1.01	3.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:49:5	29.99	3060	3.16	13.41	98	194	Off Idle	41.3	0	2	132	944 Turbo	0.57	Lean	1	14.7	0.88	14.8	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:49:6	29.99	3064	3.16	13.43	98	194	Off Idle	41.3	0	2	132	944 Turbo	0.51	Lean	1	14.7	0.92	14.79	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:49:6	29.99	3071	3.17	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	1	14.8	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:49:6	29.99	3086	3.17	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.7	1.03	14.83	1.01	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:49:6	29.99	3090	3.17	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	1.08	14.86	1.01	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:6	29.99	3110	3.18	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	1.07	14.9	1.01	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:6	31.36	3106	3.18	13.4	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	1.19	14.94	1.02	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:6	31.36	3106	3.18	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	1.25	14.98	1.02	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:49:7	31.36	3116	3.19	13.39	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	1.24	15.02	1.02	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:49:7	31.36	3124	3.19	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.25	Rich	1	14.7	1.29	15.03	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:7	29.99	3120	3.2	13.4	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Rich	1	14.7	1.27	15.11	1.03	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:49:7	29.99	3124	3.2	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.7	1.23	15.16	1.03	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:49:7	29.99	3141	3.2	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	1.27	15.17	1.03	3.6	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:49:7	29.99	3138	3.21	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.7	1.4	15.15	1.03	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:8	29.99	3148	3.21	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	1.37	15.13	1.03	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:8	31.36	3147	3.22	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	1.42	15.13	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:8	31.36	3144	3.22	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	1.47	15.07	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:8	31.36	3152	3.22	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	1.45	15.01	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:8	31.36	3152	3.23	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	1.49	15	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:8	29.99	3152	3.23	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	1.5	14.92	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:9	29.99	3160	3.23	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	1.63	14.88	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:49:9	29.99	3163	3.24	13.4	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	1.6	14.87	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:49:9	29.99	3166	3.24	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	1.61	14.87	1.01	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:49:9	29.99	3186	3.24	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	1.66	14.87	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:49:9	29.99	3182	3.25	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.7	1.69	14.82	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:49:9	29.99	3181	3.25	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.7	1.65	14.85	1.01	3.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:49:9	29.99	3184	3.25	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.7	1.71	14.85	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:50:0	29.99	3207	3.25	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.36	Rich	1	14.7	1.7	14.88	1.01	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:50:0	29.99	3228	3.26	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	1.78	14.91	1.02	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:50:0	29.99	3239	3.26	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	1.84	14.94	1.02	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:50:0	29.99	3241	3.26	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	1.81	14.98	1.02	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:50:0	29.99	3266	3.26	13.45	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	1.83	15	1.02	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:50:0	29.99	3252	3.27	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	1.88	15.03	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:1	29.99	3262	3.27	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	1.86	15.08	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:1	29.99	3262	3.27	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.7	1.87	15.1	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:1	29.99	3259	3.27	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	1.87	15.07	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:1	29.99	3261	3.28	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.7	1.85	15.06	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:1	29.99	3258	3.28	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.57	Lean	1	14.7	1.88	15.01	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:1	29.99	3266	3.28	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	1.87	14.92	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:1	29.99	3279	3.28	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	1.87	14.87	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:2	29.99	3277	3.28	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	1.88	14.83	1.01	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:2	29.99	3278	3.28	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	1.84	14.76	1.01	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:2	29.99	3300	3.28	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	1.83	14.72	1	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:50:2	29.99	3296	3.29	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	1.83	14.68	1	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:50:2	31.36	3308	3.29	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.7	1.77	14.72	1	3.6	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:50:2	31.36	3306	3.29	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.7	1.73	14.76	1.01	3.6	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:50:3	31.36	3321	3.29	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.34	Rich	1	14.7	1.73	14.77	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:50:3	31.36	3334	3.29	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.29	Rich	1	14.7	1.78	14.81	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:50:3	31.36	3334	3.29	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	1.78	14.87	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:50:3	31.36	3354	3.29	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	1.74	14.9	1.02	3.5	5.7	ON	28 Pin	OFF	Removed	Disabled
03:27:50:3	31.36	3358	3.29	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.7	1.85	14.96	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:3	31.36	3358	3.3	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	1.81	14.99	1.02	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:4	31.36	3366	3.3	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	1.81	15.07	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:4	31.36	3372	3.3	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	1.79	15.11	1.03	3.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:27:50:4	31.36	3363	3.3	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.7	1.77	15.09	1.03	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:4	31.36	3363	3.3	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.7	1.79	15.05	1.03	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:4	31.36	3368	3.3	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.7	1.73	15.01	1.02	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:4	29.99	3375	3.3	13.4	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Lean	1	14.7	1.83	15	1.02	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:4	29.99	3375	3.3	13.39	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	1.84	14.94	1.02	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:5	29.99	3383	3.3	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	1.72	14.92	1.02	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:5	29.99	3385	3.31	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	1.7	14.84	1.01	3.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:5	29.99	3391	3.31	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	1.74	14.79	1.01	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:5	29.99	3391	3.31	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	1.63	14.79	1.01	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:5	29.99	3400	3.31	13.45	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.7	1.65	14.77	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:50:5	31.36	3433	3.31	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.7	1.73	14.77	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:50:6	31.36	3433	3.31	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.7	1.72	14.76	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:50:6	31.36	3426	3.31	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.7	1.68	14.81	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:50:6	31.36	3444	3.31	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Rich	1	14.7	1.6	14.83	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:50:6	31.36	3490	3.31	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	1.66	14.89	1.01	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:50:6	31.36	3490	3.31	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	1.56	14.94	1.02	3.5	5.5	ON	28 Pin	OFF	Removed	Disabled
03:27:50:6	31.36	3474	3.31	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	1.54	14.95	1.02	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:6	31.36	3476	3.31	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	1.52	15.05	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:7	31.36	3481	3.31	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	1.63	15.08	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:7	31.36	3481	3.31	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	1.52	15.09	1.03	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:7	31.36	3465	3.31	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	1.44	15.12	1.03	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:7	31.36	3461	3.31	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	1.52	15.12	1.03	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:7	31.36	3469	3.31	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.7	1.54	15.06	1.03	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:7	31.36	3443	3.31	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	1.39	14.99	1.02	3.6	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:8	31.36	3458	3.31	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	1.29	14.96	1.02	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:8	31.36	3483	3.3	13.4	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.7	1.23	14.87	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:8	31.36	3493	3.3	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	1.15	14.83	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:8	31.36	3535	3.3	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.7	1.11	14.79	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:8	31.36	3522	3.29	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.7	1.1	14.79	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:8	31.36	3517	3.29	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	1.06	14.81	1.01	3.5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:27:50:9	31.36	3530	3.29	13.44	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	0.96	14.84	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:9	31.36	3547	3.29	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	1.01	14.86	1.01	3.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:27:50:9	31.36	3549	3.28	13.4	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	0.92	14.92	1.02	3.5	5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:50:9	31.36	3562	3.28	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	0.86	14.92	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:50:9	31.36	3559	3.27	13.38	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.7	0.79	14.99	1.02	3.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:27:50:9	31.36	3559	3.27	13.39	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.7	0.61	15.01	1.02	3.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:50:9	31.36	3574	3.26	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	0.44	15	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:51:0	32.72	3574	3.26	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	0.34	14.99	1.02	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:51:0	32.72	3547	3.24	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	0.02	14.94	1.02	3.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:27:51:0	32.72	3551	3.24	13.45	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.1	14.89	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:51:0	34.08	3564	3.23	13.45	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.12	14.82	1.01	3.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:27:51:0	34.08	3556	3.22	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-0.22	14.77	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:51:0	34.08	3562	3.22	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-0.43	14.74	1	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:51:1	34.08	3562	3.21	13.43	98	195	Off Idle	41.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	-0.51	14.73	1	3.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:27:51:1	34.08	3572	3.2	13.42	98	195	Off Idle	41.3	0	2	132	944 Turbo	0.64	Lean	1	14.7	-0.55	14.7	1	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:27:51:1	34.08	3583	3.19	13.41	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Lean	1	14.7	-0.76	14.67	1	3.6	5	ON	28 Pin	OFF	Removed	Disabled
03:27:51:1	34.08	3583	3.17	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	-0.96	14.68	1	3.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:27:51:1	34.08	3596	3.17	13.45	98	195	Off Idle	41.3	0	2	132	944 Turbo	0.53	Lean	1	14.7	-1.13	14.68	1	3.5	4.7	ON	28 Pin	OFF	Removed	Disabled
03:27:51:1	34.08	3603	3.15	13.44	98	195	Off Idle	41.3	0	2	132	944 Turbo	0.53	Lean	1	14.7	-1.32	14.7	1	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:51:1	34.08	3606	3.13	13.45	98	195	Off Idle	41.3	0	2	132	944 Turbo	0.54	Lean	1	14.7	-1.62	14.82	1.01	3.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:27:51:2	34.08	3620	3.12	13.45	98	194	Off Idle	41.3	0	2	132	944 Turbo	0.56	Lean	1	14.7	-1.74	14.85	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:2	34.08	3638	3.1	13.44	98	194	Off Idle	41.3	0	2	132	944 Turbo	0.58	Lean	1	14.7	-1.93	14.82	1.01	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:2	35.45	3623	3.07	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.61	Lean	1	14.7	-2.16	14.76	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:27:51:2	35.45	3622	3.05	13.42	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Lean	1	14.7	-2.47	14.65	1	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:27:51:2	35.45	3622	3.03	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.79	14.52	0.99	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:27:51:2	35.45	3615	3.01	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-3.05	14.42	0.98	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:27:51:3	35.45	3616	2.99	13.45	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-3.17	14.31	0.97	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:27:51:3	35.45	3610	2.95	13.44	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-3.39	14.21	0.97	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:3	35.45	3606	2.93	13.44	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-3.74	14.09	0.96	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:3	35.45	3595	2.91	13.44	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-3.87	13.85	0.94	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:3	35.45	3594	2.89	13.44	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-4.06	13.79	0.94	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:3	35.45	3588	2.87	13.43	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-4.21	13.71	0.93	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:4	35.45	3594	2.84	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-4.28	13.72	0.93	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:4	35.45	3605	2.81	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-4.36	13.76	0.94	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:4	35.45	3607	2.8	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.68	Lean	1	14.7	-4.51	13.81	0.94	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:51:4	35.45	3615	2.79	13.4	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.64	Lean	1	14.7	-4.58	13.84	0.94	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:4	35.45	3639	2.76	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	-4.85	13.95	0.95	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:4	35.45	3644	2.75	13.44	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.95	14.04	0.96	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:27:51:4	35.45	3668	2.73	13.45	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.7	-5.1	14.13	0.96	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:5	36.81	3656	2.71	13.45	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-5.18	14.22	0.97	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:5	36.81	3658	2.7	13.47	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-5.19	14.36	0.98	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:5	36.81	3662	2.69	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-5.3	14.5	0.99	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:5	36.81	3661	2.69	13.42	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.34	14.63	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:5	36.81	3661	2.67	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-5.48	14.75	1	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:5	36.81	3652	2.66	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.7	-5.66	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:6	36.81	3648	2.65	13.44	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.7	-5.85	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:27:51:6	36.81	3644	2.64	13.47	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-6.02	15.05	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:27:51:6	36.81	3633	2.62	13.48	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-6.15	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:27:51:6	36.81	3628	2.6	13.45	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-6.33	15.17	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:27:51:6	36.81	3627	2.58	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	-6.54	15.21	1.04	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:27:51:6	36.81	3624	2.56	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-6.72	15.21	1.04	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:27:51:6	36.81	3620	2.53	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	-6.94	15.21	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:7	36.81	3616	2.5	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Lean	1	14.7	-7.23	15.21	1.04	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:7	36.81	3610	2.48	13.46	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.7	-7.32	15.19	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:7	36.81	3609	2.46	13.47	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-7.4	15.15	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:7	36.81	3635	2.44	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-7.52	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:7	38.18	3621	2.42	13.46	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-7.6	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:7	38.18	3612	2.4	13.46	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-7.69	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:51:8	38.18	3616	2.38	13.46	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.79	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:51:8	38.18	3618	2.35	13.46	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-7.94	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:51:8	38.18	3627	2.33	13.48	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8	14.76	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:51:8	38.18	3633	2.29	13.48	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.09	14.71	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:51:8	38.18	3635	2.27	13.48	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.16	14.64	1	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:8	38.18	3636	2.24	13.47	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.31	14.57	0.99	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:9	38.18	3636	2.21	13.48	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.41	14.55	0.99	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:27:51:9	38.18	3634	2.2	13.48	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.52	14.59	0.99	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:51:9	38.18	3634	2.19	13.48	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.51	14.61	1	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:27:51:9	38.18	3624	2.17	13.46	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.64	14.72	1	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:51:9	38.18	3617	2.15	13.44	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.73	14.79	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:51:9	38.18	3616	2.14	13.44	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.82	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:51:9	38.18	3616	2.13	13.44	98	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.89	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:52:0	38.18	3607	2.11	13.42	98	195	Off Idle	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.7	-9.05	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:52:0	38.18	3605	2.09	13.46	98	195	Off Idle	41.5	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.11	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:52:0	38.18	3604	2.08	13.46	98	195	Off Idle	41.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.14	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:27:52:0	38.18	3608	2.06	13.47	98	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.17	15.08	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:52:0	38.18	3605	2.05	13.44	98	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.25	15.05	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:52:0	38.18	3605	2.03	13.46	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.24	15.01	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:52:1	38.18	3598	2.02	13.43	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.28	14.98	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:52:1	38.18	3598	2	13.42	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.34	14.93	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:52:1	38.18	3593	1.99	13.41	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.38	14.9	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:27:52:1	38.18	3593	1.98	13.41	98	194	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.42	14.89	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:52:1	38.18	3588	1.97	13.41	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.54	14.83	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:52:1	38.18	3586	1.96	13.45	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.6	14.79	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:52:1	38.18	3586	1.95	13.46	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.65	14.79	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:52:2	38.18	3598	1.93	13.45	98	194	Off Idle	41.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.77	14.8	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:27:52:2	39.54	3585	1.91	13.47	98	194	Full Load	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.87	14.81	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:2	39.54	3586	1.89	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.96	14.81	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:2	39.54	3587	1.87	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.01	14.81	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:2	39.54	3587	1.85	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.07	14.82	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:2	39.54	3577	1.84	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-10.12	14.81	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:3	39.54	3575	1.82	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-10.15	14.79	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:3	39.54	3574	1.81	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-10.19	14.76	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:3	39.54	3574	1.8	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-10.2	14.76	1.01	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:3	34.08	3518	1.78	13.43	98	194	Idle	41.4	0	2	132	944 Turbo	0.81	Rich	1	14.6	-10.24	14.74	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:3	34.08	3513	1.77	13.46	98	194	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-10.24	14.72	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:3	28.63	3512	1.76	13.46	98	194	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.24	14.68	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:4	23.18	3511	1.75	13.44	98	194	Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.23	14.65	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:4	20.45	3557	1.74	13.42	98	194	Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.22	14.62	1	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:27:52:4	20.45	3553	1.72	13.43	98	194	Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.25	14.56	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:4	20.45	3553	1.72	13.43	98	195	Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.23	14.54	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:4	20.45	3552	1.71	13.42	98	195	Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.21	14.51	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:4	20.45	3554	1.71	13.45	98	195	Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-10.25	14.48	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:4	20.45	3552	1.7	13.47	98	194	Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-10.25	14.45	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:5	20.45	3553	1.7	13.47	98	194	Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-10.2	14.43	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:5	20.45	3552	1.7	13.47	98	194	Idle	41.5	0	2	132	944 Turbo	0.24	Rich	1	14.6	-10.19	14.43	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:5	20.45	3532	1.7	13.46	98	195	Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.17	14.46	0.98	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:5	20.45	3532	1.7	13.46	98	195	Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.16	14.48	0.99	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:5	20.45	3538	1.7	13.46	98	195	Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.1	14.51	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:5	20.45	3532	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.14	14.57	0.99	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:6	20.45	3531	1.7	13.48	98	194	Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.19	14.61	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:6	20.45	3524	1.7	13.48	98	194	Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.16	14.64	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:6	20.45	3519	1.7	13.48	98	194	Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.12	14.66	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:6	20.45	3518	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.16	14.69	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:6	20.45	3516	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.15	14.77	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:6	20.45	3515	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.14	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:6	20.45	3516	1.7	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.11	14.87	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:7	20.45	3518	1.7	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.16	14.95	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:7	20.45	3516	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.12	14.98	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:7	20.45	3512	1.7	13.47	98	194	Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.11	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:52:7	20.45	3508	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.09	15.35	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:7	20.45	3508	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.12	15.73	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:7	20.45	3508	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	16.22	1.11	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:8	20.45	3500	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	16.75	1.14	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:8	20.45	3496	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	17.25	1.18	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:8	20.45	3496	1.7	13.45	98	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	17.74	1.21	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:8	20.45	3490	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	18	1.23	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:8	20.45	3484	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	18.49	1.26	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:8	20.45	3484	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	18.74	1.28	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:9	20.45	3479	1.7	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	19.46	1.33	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:9	20.45	3473	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	19.84	1.35	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:9	20.45	3473	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	19.99	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:9	20.45	3466	1.7	13.47	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:9	20.45	3464	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:9	20.45	3466	1.7	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:52:9	20.45	3467	1.7	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:0	20.45	3464	1.7	13.47	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:0	20.45	3440	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:0	20.45	3453	1.7	13.48	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:0	20.45	3462	1.7	13.48	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:0	20.45	3459	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:0	20.45	3460	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:1	20.45	3454	1.7	13.48	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:1	20.45	3448	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:1	20.45	3448	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:1	20.45	3429	1.7	13.47	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:1	20.45	3435	1.7	13.44	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:1	20.45	3427	1.7	13.44	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:1	20.45	3424	1.7	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:2	20.45	3420	1.7	13.43	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:2	20.45	3415	1.7	13.44	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:2	20.45	3416	1.7	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:2	20.45	3411	1.7	13.43	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:2	20.45	3412	1.7	13.45	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:2	20.45	3410	1.7	13.46	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:3	20.45	3410	1.7	13.43	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:3	20.45	3398	1.7	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:3	20.45	3411	1.7	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:3	20.45	3411	1.7	13.43	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:3	20.45	3398	1.7	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:3	20.45	3410	1.7	13.46	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:4	20.45	3408	1.7	13.44	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:4	20.45	3420	1.7	13.44	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:4	20.45	3404	1.7	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:4	20.45	3402	1.7	13.45	98	195	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:4	20.45	3398	1.7	13.45	98	195	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:4	20.45	3396	1.7	13.44	98	195	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:4	20.45	3392	1.7	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:5	20.45	3389	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:5	20.45	3388	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:5	20.45	3379	1.7	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:5	20.45	3376	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:5	20.45	3370	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:5	20.45	3367	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:6	20.45	3364	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:6	20.45	3359	1.7	13.46	98	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:6	20.45	3358	1.7	13.43	98	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:6	20.45	3354	1.7	13.44	98	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:53:6	20.45	3347	1.7	13.45	98	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:6	20.45	3346	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:6	20.45	3344	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:7	20.45	3339	1.7	13.48	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:7	20.45	3338	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:7	20.45	3334	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:7	20.45	3321	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:7	20.45	3326	1.7	13.44	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.93	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:7	20.45	3322	1.7	13.44	98	194	Idle	41.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.95	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:8	20.45	3312	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:8	20.45	3310	1.7	13.44	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:8	20.45	3310	1.7	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:8	20.45	3303	1.7	13.46	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:8	20.45	3296	1.7	13.44	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:8	20.45	3296	1.7	13.44	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:9	20.45	3289	1.7	13.45	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:9	20.45	3285	1.7	13.45	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:9	20.45	3283	1.7	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:9	20.45	3282	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:9	20.45	3256	1.7	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:9	20.45	3285	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:53:9	20.45	3298	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:0	20.45	3286	1.7	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:0	20.45	3292	1.7	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.9	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:0	20.45	3293	1.7	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:0	20.45	3298	1.7	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:0	20.45	3296	1.7	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:0	20.45	3294	1.7	13.46	98	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:1	20.45	3286	1.7	13.45	98	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:1	20.45	3286	1.7	13.47	98	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:1	20.45	3265	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:1	20.45	3276	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:1	20.45	3243	1.7	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:1	20.45	3229	1.7	13.43	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:1	20.45	3229	1.7	13.44	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:2	20.45	3226	1.7	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:2	20.45	3215	1.7	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:2	20.45	3214	1.7	13.43	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:2	20.45	3228	1.7	13.45	98	194	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:2	20.45	3226	1.71	13.45	98	194	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:2	20.45	3243	1.71	13.45	98	194	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:3	20.45	3245	1.71	13.45	98	194	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:3	20.45	3234	1.71	13.45	98	194	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:3	20.45	3250	1.71	13.45	98	194	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:3	20.45	3250	1.71	13.45	98	194	Idle	41	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:3	20.45	3245	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:3	20.45	3242	1.71	13.46	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:4	20.45	3240	1.71	13.47	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:4	20.45	3225	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:4	20.45	3218	1.71	13.46	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:4	20.45	3166	1.71	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:4	20.45	3166	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:4	20.45	3195	1.71	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:4	20.45	3188	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:5	20.45	3187	1.71	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:5	20.45	3182	1.71	13.46	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:5	20.45	3181	1.71	13.45	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:5	20.45	3182	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:54:5	20.45	3181	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:5	20.45	3182	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:6	20.45	3182	1.71	13.44	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:6	20.45	3182	1.71	13.47	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:6	20.45	3184	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:6	20.45	3182	1.71	13.47	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:6	20.45	3176	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:6	20.45	3172	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:6	20.45	3167	1.71	13.44	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:7	20.45	3166	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:7	20.45	3159	1.71	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:7	20.45	3153	1.71	13.45	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:7	20.45	3153	1.71	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:7	20.45	3146	1.71	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:7	20.45	3141	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:8	20.45	3140	1.71	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:8	20.45	3152	1.71	13.45	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:8	20.45	3135	1.71	13.45	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:8	20.45	3135	1.71	13.45	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:8	20.45	3123	1.71	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:8	20.45	3137	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:9	20.45	3135	1.71	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:9	20.45	3135	1.71	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:9	20.45	3136	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:9	20.45	3134	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:9	20.45	3132	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:9	20.45	3127	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:54:9	20.45	3118	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:0	20.45	3106	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:0	20.45	3106	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:0	20.45	3098	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.75	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:0	20.45	3091	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:0	20.45	3088	1.71	13.44	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:0	20.45	3084	1.71	13.43	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:1	19.09	3052	1.71	13.43	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:1	19.09	3064	1.71	13.43	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:1	19.09	3077	1.71	13.45	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:1	19.09	3075	1.71	13.44	98	194	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:1	19.09	3075	1.71	13.45	98	194	Idle	40.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:1	19.09	3078	1.71	13.45	98	194	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:1	19.09	3091	1.71	13.45	98	194	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:2	19.09	3082	1.71	13.45	98	194	Idle	40.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:2	19.09	3082	1.71	13.45	98	194	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:2	19.09	3081	1.71	13.43	98	194	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:2	19.09	3080	1.71	13.44	98	194	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:2	19.09	3078	1.71	13.45	98	194	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:2	19.09	3072	1.71	13.45	98	194	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:3	19.09	3071	1.71	13.45	98	194	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:3	19.09	3070	1.71	13.45	98	194	Idle	40.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:3	19.09	3064	1.71	13.44	98	194	Idle	40.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:3	19.09	3054	1.71	13.43	98	194	Idle	40.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:3	19.09	3051	1.71	13.44	98	194	Idle	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:3	19.09	3048	1.71	13.43	98	194	Idle	41.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:4	19.09	3046	1.71	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:4	19.09	3040	1.71	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:4	19.09	3040	1.71	13.44	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:4	19.09	3034	1.71	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:4	19.09	3042	1.71	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:55:4	19.09	3030	1.71	13.42	98	194	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.66	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:4	19.09	3029	1.71	13.43	98	194	Idle	41.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:5	19.09	3014	1.71	13.43	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:5	19.09	3022	1.71	13.45	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:5	19.09	3022	1.71	13.45	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:5	19.09	3018	1.71	13.45	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:5	19.09	3016	1.71	13.46	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.71	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:5	19.09	3013	1.71	13.46	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:6	19.09	3012	1.71	13.46	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:6	19.09	3008	1.71	13.45	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:6	19.09	3004	1.71	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:6	19.09	3003	1.71	13.44	98	194	Idle	41.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:6	19.09	3002	1.71	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:6	19.09	2998	1.71	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:6	19.09	2995	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.73	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:7	19.09	2996	1.71	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:7	19.09	2994	1.71	13.46	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:7	19.09	2994	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:7	19.09	2993	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:7	19.09	2992	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:7	19.09	2990	1.71	13.43	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:8	19.09	2990	1.7	13.43	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:8	19.09	2988	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:8	19.09	2984	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:8	19.09	2980	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:8	19.09	2980	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:8	19.09	2976	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:9	19.09	2968	1.71	13.45	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:9	19.09	2968	1.71	13.45	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:9	19.09	2965	1.71	13.45	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:9	19.09	2958	1.71	13.45	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:9	19.09	2955	1.71	13.45	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:9	19.09	2953	1.71	13.44	98	195	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:55:9	19.09	2948	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:0	19.09	2943	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:0	19.09	2943	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:0	19.09	2941	1.71	13.43	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:0	19.09	2938	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:0	19.09	2937	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:0	19.09	2938	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:1	19.09	2934	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:1	19.09	2931	1.71	13.45	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:1	19.09	2930	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:1	19.09	2928	1.71	13.45	98	194	Idle	41.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:1	19.09	2927	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:1	19.09	2926	1.71	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:1	19.09	2926	1.7	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:2	19.09	2923	1.7	13.44	98	194	Idle	41.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:2	19.09	2921	1.7	13.44	98	194	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:2	19.09	2921	1.7	13.44	98	194	Idle	41.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:2	19.09	2918	1.7	13.44	98	194	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:2	19.09	2913	1.7	13.45	98	194	Idle	41.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:2	19.09	2912	1.7	13.45	98	194	Idle	41.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.61	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:3	19.09	2916	1.7	13.45	98	194	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:3	19.09	2902	1.7	13.45	98	195	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:3	19.09	2897	1.7	13.44	98	195	Idle	41.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:3	19.09	2886	1.7	13.43	98	195	Idle	42.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:3	19.09	2892	1.7	13.44	98	194	Idle	42.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:56:3	19.09	2889	1.7	13.44	98	194	Idle	42.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:4	19.09	2885	1.7	13.44	98	194	Idle	42.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:4	19.09	2884	1.7	13.45	98	194	Idle	42.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:4	19.09	2883	1.7	13.45	98	194	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:4	19.09	2882	1.7	13.46	98	195	Idle	42.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:4	19.09	2880	1.7	13.47	98	195	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:4	19.09	2875	1.7	13.46	98	195	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.67	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:4	19.09	2874	1.69	13.47	98	194	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:5	19.09	2873	1.69	13.45	98	194	Idle	42.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:5	19.09	2870	1.69	13.44	98	194	Idle	42.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:5	19.09	2870	1.69	13.44	98	194	Idle	43.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:5	19.09	2866	1.69	13.44	98	194	Idle	43.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:5	19.09	2862	1.69	13.43	98	194	Idle	43.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:5	19.09	2860	1.69	13.44	98	195	Idle	43.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:6	19.09	2859	1.69	13.43	98	195	Idle	43.5	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.68	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:6	19.09	2854	1.69	13.45	98	195	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.69	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:6	19.09	2852	1.69	13.43	98	195	Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:6	19.09	2851	1.69	13.45	98	195	Idle	43.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.67	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:6	19.09	2848	1.69	13.44	98	195	Idle	43.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:6	19.09	2822	1.69	13.44	98	195	Idle	43.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:6	19.09	2822	1.68	13.44	98	195	Idle	44	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:7	19.09	2841	1.68	13.44	98	195	Idle	44.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.67	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:7	19.09	2837	1.68	13.44	98	195	Idle	44.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:7	19.09	2834	1.68	13.43	98	195	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:7	19.09	2836	1.68	13.44	98	195	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:7	19.09	2832	1.68	13.44	98	194	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:7	19.09	2827	1.68	13.44	98	194	Idle	44.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:8	19.09	2828	1.68	13.45	98	194	Idle	44.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:8	19.09	2825	1.68	13.44	98	194	Idle	44.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:8	19.09	2823	1.68	13.43	98	194	Idle	44.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:8	19.09	2821	1.67	13.43	98	194	Idle	45	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.65	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:8	19.09	2818	1.67	13.43	98	194	Idle	45.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:8	19.09	2819	1.67	13.45	98	195	Idle	45.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:9	19.09	2816	1.67	13.45	98	195	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:9	19.09	2814	1.67	13.45	98	194	Idle	45.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.66	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:9	19.09	2812	1.66	13.45	98	194	Idle	45.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:9	19.09	2814	1.66	13.44	98	194	Idle	45.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:9	19.09	2812	1.66	13.44	98	194	Idle	45.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:9	19.09	2812	1.66	13.44	98	194	Idle	45.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:56:9	19.09	2808	1.66	13.44	98	194	Idle	46.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:0	19.09	2808	1.66	13.44	98	195	Idle	46.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:0	19.09	2806	1.65	13.45	98	195	Idle	46.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:0	19.09	2790	1.65	13.45	98	195	Idle	46.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.76	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:0	19.09	2796	1.65	13.45	98	195	Idle	46.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:0	19.09	2796	1.65	13.44	98	195	Idle	46.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:0	19.09	2791	1.65	13.44	98	195	Idle	47	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:1	19.09	2785	1.65	13.44	98	195	Idle	47.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:1	19.09	2785	1.64	13.45	98	195	Idle	47.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.78	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:1	19.09	2778	1.64	13.44	98	195	Idle	47.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:1	19.09	2772	1.64	13.44	98	195	Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:1	19.09	2768	1.63	13.44	98	195	Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:1	19.09	2768	1.63	13.44	98	195	Idle	48	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.8	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:1	19.09	2764	1.63	13.44	98	195	Idle	48.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.77	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:2	19.09	2739	1.63	13.43	98	195	Idle	48.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-9.8	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:2	19.09	2749	1.63	13.43	98	195	Idle	48.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:2	19.09	2759	1.62	13.43	98	195	Idle	48.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:2	19.09	2754	1.62	13.45	98	195	Idle	48.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:2	19.09	2754	1.62	13.44	98	194	Idle	48.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:57:2	19.09	2742	1.62	13.46	98	194	Idle	48.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:3	19.09	2748	1.62	13.46	98	194	Idle	48.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:3	19.09	2745	1.61	13.46	98	195	Idle	48.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:3	19.09	2745	1.61	13.45	98	195	Idle	48.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:3	19.09	2742	1.61	13.46	98	195	Idle	48.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:3	19.09	2739	1.61	13.45	98	195	Idle	49	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:3	19.09	2738	1.61	13.43	98	195	Idle	49.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:4	19.09	2733	1.61	13.45	98	195	Idle	49.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:4	19.09	2730	1.61	13.45	98	195	Idle	49.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:4	19.09	2728	1.6	13.45	98	195	Idle	49.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:4	19.09	2728	1.6	13.45	98	195	Idle	50.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:4	19.09	2727	1.6	13.45	98	195	Idle	50.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.86	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:4	19.09	2702	1.6	13.44	98	195	Idle	50.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:4	19.09	2702	1.59	13.45	98	195	Idle	50.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:5	19.09	2721	1.59	13.44	98	195	Idle	50.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:5	19.09	2741	1.59	13.45	98	195	Idle	51	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:5	19.09	2730	1.58	13.45	98	195	Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:5	19.09	2714	1.58	13.45	98	195	Idle	51.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:5	19.09	2714	1.58	13.45	98	195	Idle	51.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:5	19.09	2709	1.58	13.45	98	195	Idle	52.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:6	19.09	2707	1.57	13.45	98	195	Idle	52.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.96	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:6	19.09	2692	1.57	13.45	98	195	Idle	52.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:6	19.09	2700	1.56	13.45	98	195	Idle	52.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:6	19.09	2698	1.56	13.45	98	195	Idle	52.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:6	19.09	2694	1.56	13.45	98	195	Idle	52.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:6	19.09	2689	1.55	13.45	98	195	Idle	52.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:6	19.09	2684	1.55	13.44	98	195	Idle	53	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:7	19.09	2682	1.54	13.45	98	195	Idle	53	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:7	19.09	2678	1.54	13.45	98	195	Idle	53	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:7	19.09	2675	1.54	13.45	98	195	Idle	53.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:7	19.09	2674	1.53	13.44	98	195	Idle	53.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:7	19.09	2671	1.53	13.45	98	195	Idle	53.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:7	19.09	2668	1.53	13.45	98	195	Idle	53.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:8	19.09	2667	1.53	13.44	98	195	Idle	53.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:8	19.09	2666	1.53	13.43	98	195	Idle	53.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:8	19.09	2664	1.52	13.45	98	195	Idle	53.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:8	19.09	2662	1.52	13.44	98	195	Idle	53.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:8	19.09	2661	1.52	13.44	98	195	Idle	53.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:8	19.09	2658	1.52	13.45	98	195	Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:9	19.09	2651	1.52	13.44	98	194	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:9	19.09	2656	1.51	13.44	98	194	Idle	54.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:9	19.09	2644	1.51	13.45	98	194	Idle	54.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.09	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:9	19.09	2651	1.51	13.45	98	195	Idle	54.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.1	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:9	19.09	2667	1.51	13.45	98	195	Idle	55	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.1	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:9	19.09	2656	1.51	13.44	98	195	Idle	55.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.1	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:57:9	19.09	2644	1.51	13.45	98	195	Idle	55.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.11	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:0	19.09	2639	1.5	13.46	98	195	Idle	55.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.11	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:0	19.09	2638	1.5	13.46	98	195	Idle	55.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.11	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:0	19.09	2642	1.5	13.46	98	195	Idle	55.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.1	1.37	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:0	19.09	2629	1.5	13.47	98	194	Idle	56.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.1	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:0	19.09	2628	1.49	13.45	98	194	Idle	56.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:0	19.09	2612	1.49	13.45	98	194	Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:1	19.09	2619	1.49	13.45	98	195	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:1	19.09	2614	1.48	13.45	98	195	Idle	56.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:1	19.09	2613	1.48	13.44	98	195	Idle	56.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:1	19.09	2610	1.48	13.44	98	194	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:1	19.09	2605	1.47	13.45	98	194	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:1	19.09	2604	1.47	13.45	98	194	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:58:1	19.09	2602	1.47	13.45	98	195	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:2	19.09	2601	1.47	13.44	98	195	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:2	19.09	2600	1.46	13.44	98	195	Idle	56.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:2	19.09	2600	1.46	13.45	98	195	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:2	19.09	2598	1.46	13.43	98	195	Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:2	19.09	2598	1.46	13.44	98	195	Idle	57.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:2	19.09	2598	1.46	13.44	98	195	Idle	57.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:3	19.09	2594	1.45	13.45	98	195	Idle	57.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:3	19.09	2592	1.45	13.45	98	195	Idle	57.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:3	19.09	2586	1.45	13.45	98	195	Idle	58	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.18	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:3	19.09	2585	1.45	13.44	98	195	Idle	58.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:3	19.09	2580	1.45	13.45	98	195	Idle	58.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:3	19.09	2576	1.44	13.44	98	195	Idle	58.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:4	19.09	2574	1.44	13.44	98	195	Idle	58.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:4	19.09	2569	1.44	13.42	98	195	Idle	59	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:4	19.09	2565	1.44	13.44	98	195	Idle	59.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:4	19.09	2564	1.44	13.44	98	195	Idle	59.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:4	19.09	2550	1.43	13.43	98	195	Idle	59.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:4	19.09	2557	1.43	13.44	98	195	Idle	59.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:4	19.09	2555	1.43	13.44	98	195	Idle	59.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:5	19.09	2554	1.42	13.44	98	194	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:5	19.09	2552	1.42	13.45	98	194	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:5	19.09	2530	1.42	13.45	98	194	Idle	60	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:5	19.09	2530	1.41	13.45	98	195	Idle	60.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:5	19.09	2548	1.41	13.46	98	195	Idle	60.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:5	19.09	2566	1.41	13.46	98	195	Idle	60.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:6	19.09	2554	1.4	13.44	98	195	Idle	60.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:6	19.09	2542	1.4	13.45	98	195	Idle	61	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:6	19.09	2538	1.4	13.46	98	195	Idle	61.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:6	19.09	2536	1.4	13.45	98	195	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:6	19.09	2536	1.39	13.44	98	195	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:6	19.09	2531	1.39	13.45	98	194	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:6	19.09	2520	1.39	13.44	98	194	Idle	61.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:7	19.09	2525	1.39	13.45	98	194	Idle	61.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:7	19.09	2525	1.38	13.45	98	195	Idle	62	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:7	19.09	2531	1.38	13.44	98	195	Idle	62.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:7	19.09	2510	1.38	13.45	98	195	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:7	19.09	2516	1.38	13.44	98	195	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:7	19.09	2516	1.38	13.43	98	195	Idle	62.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:8	19.09	2513	1.37	13.45	98	195	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:8	19.09	2511	1.37	13.45	98	195	Idle	62.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:8	19.09	2511	1.37	13.44	98	195	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:8	19.09	2509	1.37	13.44	98	195	Idle	63.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:8	19.09	2486	1.37	13.45	98	194	Idle	63.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:8	19.09	2486	1.36	13.44	98	194	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:9	19.09	2504	1.36	13.45	98	194	Idle	63.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:9	19.09	2502	1.36	13.44	98	194	Idle	63.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:9	19.09	2500	1.35	13.45	98	194	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:9	19.09	2497	1.35	13.44	98	195	Idle	64.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.01	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:9	19.09	2492	1.35	13.45	98	195	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.01	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:9	19.09	2488	1.35	13.44	98	195	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.01	1.36	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:58:9	19.09	2486	1.35	13.44	98	195	Idle	64.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:0	19.09	2484	1.34	13.45	98	195	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	19.99	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:0	19.09	2481	1.34	13.44	98	195	Idle	65.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:0	19.09	2481	1.34	13.44	98	195	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	19.99	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:0	19.09	2474	1.33	13.43	98	195	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.01	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:0	19.09	2473	1.33	13.44	98	195	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:0	19.09	2473	1.33	13.45	98	195	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:27:59:1	19.09	2466	1.33	13.45	98	195	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:1	19.09	2463	1.32	13.44	98	195	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:1	19.09	2462	1.32	13.44	98	195	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:1	19.09	2458	1.32	13.45	98	195	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:1	19.09	2455	1.31	13.45	98	195	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:1	19.09	2455	1.31	13.44	98	195	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:1	17.72	2432	1.31	13.43	98	195	Idle	65.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:2	17.72	2429	1.31	13.44	98	195	Idle	65.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:2	17.72	2438	1.31	13.45	98	195	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:2	17.72	2454	1.31	13.45	98	194	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:2	17.72	2444	1.3	13.46	98	194	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:2	17.72	2444	1.3	13.47	98	194	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:2	17.72	2442	1.3	13.46	98	195	Idle	66.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:3	17.72	2439	1.3	13.47	98	195	Idle	66.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:3	17.72	2438	1.29	13.46	98	195	Idle	66.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:3	17.72	2438	1.29	13.46	98	195	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:3	17.72	2435	1.29	13.46	98	195	Idle	67	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:3	17.72	2415	1.28	13.46	98	195	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:3	17.72	2430	1.28	13.46	98	195	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:4	17.72	2430	1.28	13.46	98	195	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:4	17.72	2428	1.28	13.46	98	195	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:4	17.72	2425	1.27	13.45	98	195	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:4	17.72	2426	1.27	13.44	98	195	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:4	17.72	2424	1.27	13.44	98	195	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:4	17.72	2420	1.26	13.44	98	195	Idle	68.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:4	17.72	2417	1.26	13.44	98	195	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:5	17.72	2417	1.26	13.45	98	195	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:5	17.72	2413	1.25	13.44	98	194	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:5	17.72	2412	1.25	13.44	98	194	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:5	17.72	2402	1.24	13.44	98	195	Idle	69.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:5	17.72	2417	1.24	13.45	98	195	Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:5	17.72	2406	1.24	13.44	98	195	Idle	69.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:6	17.72	2404	1.23	13.44	98	195	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:6	17.72	2400	1.23	13.44	98	195	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:6	17.72	2396	1.23	13.44	98	195	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:6	17.72	2390	1.23	13.44	98	195	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:6	17.72	2390	1.22	13.43	98	195	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:6	17.72	2384	1.22	13.43	98	195	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:6	17.72	2378	1.22	13.43	98	195	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:7	17.72	2376	1.22	13.44	98	195	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:7	17.72	2368	1.21	13.44	98	195	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:7	17.72	2362	1.21	13.44	98	195	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:7	17.72	2360	1.21	13.45	98	195	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:7	17.72	2354	1.21	13.44	98	195	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:7	17.72	2354	1.2	13.44	98	195	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:8	17.72	2353	1.2	13.43	98	195	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:8	17.72	2348	1.2	13.43	98	195	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:8	17.72	2346	1.2	13.43	98	195	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:8	17.72	2343	1.2	13.44	98	195	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:8	17.72	2343	1.19	13.43	98	195	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:8	17.72	2335	1.19	13.44	98	195	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:9	17.72	2333	1.19	13.44	98	195	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:9	17.72	2331	1.19	13.44	98	195	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:9	17.72	2322	1.19	13.44	98	195	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:9	17.72	2316	1.18	13.44	98	194	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:9	17.72	2316	1.18	13.44	98	194	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:9	17.72	2295	1.18	13.45	98	195	Off Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:27:59:9	17.72	2246	1.18	13.44	98	195	Off Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:00:0	17.72	2318	1.18	13.45	98	195	Off Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:28:00:0	9.54	2318	1.17	13.45	98	195	Off Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:28:00:0	12.27	2312	1.17	13.46	98	195	Off Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:28:00:0	12.27	2311	1.18	13.45	98	195	Off Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:28:00:0	14.99	2310	1.18	13.45	98	195	Off Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:28:00:0	14.99	2310	1.18	13.44	98	195	Off Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:1	17.72	2311	1.18	13.43	98	195	Off Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.41	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:1	20.45	2313	1.18	13.42	98	195	Off Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:1	23.18	2312	1.19	13.44	98	195	Off Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:1	23.18	2314	1.19	13.42	98	195	Off Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:1	25.9	2314	1.19	13.41	98	195	Off Idle	76.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:1	25.9	2318	1.19	13.42	98	195	Off Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:1	28.63	2318	1.19	13.44	98	195	Off Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:2	28.63	2323	1.19	13.42	98	195	Off Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.24	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:2	31.36	2324	1.2	13.43	98	195	Off Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:2	34.08	2324	1.2	13.43	98	195	Off Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:2	34.08	2321	1.2	13.45	98	195	Off Idle	78.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.23	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:2	35.45	2304	1.21	13.45	98	195	Off Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:2	35.45	2301	1.21	13.45	98	195	Off Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.5	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:00:3	35.45	2301	1.22	13.44	98	195	Off Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:3	35.45	2292	1.22	13.44	98	195	Off Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:3	35.45	2285	1.22	13.44	98	195	Off Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:3	35.45	2285	1.23	13.43	98	195	Off Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.7	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:3	35.45	2275	1.23	13.43	98	195	Off Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:3	35.45	2268	1.23	13.42	98	195	Off Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:4	35.45	2261	1.23	13.42	98	195	Off Idle	77.6	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:4	35.45	2261	1.24	13.43	98	195	Off Idle	77.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:4	35.45	2259	1.24	13.42	98	195	Off Idle	77.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:4	35.45	2262	1.24	13.44	98	195	Off Idle	77.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:4	35.45	2259	1.25	13.44	98	195	Off Idle	77.8	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:4	35.45	2253	1.25	13.44	98	195	Off Idle	78	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.41	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:4	35.45	2253	1.25	13.44	98	195	Off Idle	78.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:5	35.45	2252	1.25	13.42	98	195	Off Idle	78.3	0	2	132	944 Turbo	0.03	Lean	1	14.7	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:5	35.45	2246	1.26	13.41	98	195	Off Idle	78.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:5	35.45	2246	1.26	13.41	98	195	Off Idle	78.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.44	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:5	35.45	2228	1.26	13.41	98	195	Off Idle	78.7	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.4	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:5	35.45	2236	1.26	13.41	98	195	Off Idle	78.9	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.41	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:5	35.45	2244	1.26	13.43	98	195	Off Idle	79	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.42	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:6	35.45	2249	1.26	13.43	98	195	Off Idle	79.2	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.41	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:6	35.45	2249	1.26	13.44	98	195	Off Idle	79.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:6	35.45	2254	1.25	13.45	98	195	Off Idle	79.2	0	2	132	944 Turbo	0.04	Lean	1	14.7	-10.41	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:6	35.45	2241	1.25	13.45	98	195	Off Idle	79.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.4	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:6	35.45	2243	1.25	13.45	98	195	Off Idle	79.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.41	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:6	35.45	2243	1.25	13.45	98	195	Off Idle	79.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:6	34.08	2238	1.25	13.45	98	195	Off Idle	79.7	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10.42	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:7	34.08	2243	1.25	13.45	98	195	Off Idle	79.8	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10.47	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:7	34.08	2240	1.25	13.44	98	195	Off Idle	80	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:7	34.08	2239	1.25	13.44	98	195	Off Idle	80.1	0	2	132	944 Turbo	0.05	Lean	1	14.7	-10.45	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:7	34.08	2228	1.24	13.44	98	195	Off Idle	80.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:7	34.08	2234	1.24	13.43	98	195	Off Idle	80.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:7	34.08	2234	1.24	13.43	98	195	Off Idle	80.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.43	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:8	34.08	2226	1.24	13.44	98	194	Off Idle	80.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:8	34.08	2228	1.24	13.44	98	194	Off Idle	80.4	0	2	132	944 Turbo	0.06	Lean	1	14.7	-10.43	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:8	34.08	2224	1.24	13.44	98	194	Off Idle	80.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:8	34.08	2224	1.24	13.44	98	194	Off Idle	80.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:8	34.08	2221	1.23	13.44	98	194	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.47	20.17	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:8	34.08	2218	1.23	13.44	98	195	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.45	20.11	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:9	34.08	2218	1.23	13.44	98	195	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.44	20.07	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:00:9	34.08	2218	1.23	13.45	98	195	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.44	19.97	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:9	34.08	2212	1.23	13.45	98	195	Off Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-10.43	19.83	1.35	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:9	34.08	2218	1.23	13.45	98	195	Off Idle	81.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.43	19.66	1.34	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:9	34.08	2218	1.23	13.45	98	195	Off Idle	81.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.43	19.47	1.33	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:9	34.08	2219	1.23	13.43	98	195	Off Idle	81.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-10.45	19.26	1.31	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:00:9	34.08	2216	1.22	13.43	98	195	Off Idle	81.8	0	2	132	944 Turbo	0.06	Lean	1	14.7	-10.49	19.02	1.3	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:0	34.08	2223	1.22	13.43	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.45	18.66	1.27	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:0	34.08	2213	1.22	13.43	98	194	Off Idle	81.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.47	18.42	1.25	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:0	34.08	2207	1.22	13.42	98	194	Off Idle	81.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.48	18.2	1.24	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:0	34.08	2201	1.21	13.41	98	195	Off Idle	82.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.47	18	1.23	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:0	34.08	2192	1.21	13.41	98	195	Off Idle	82.2	0	2	132	944 Turbo	0.07	Lean	1	14.7	-10.48	17.82	1.21	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:0	34.08	2199	1.21	13.43	98	195	Off Idle	82.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.47	17.66	1.2	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:1	34.08	2200	1.21	13.43	98	195	Off Idle	82.3	0	2	132	944 Turbo	0.07	Lean	1	14.7	-10.48	17.59	1.2	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:1	34.08	2200	1.21	13.44	98	195	Off Idle	82.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.5	17.46	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:1	34.08	2206	1.2	13.44	98	195	Off Idle	82.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.47	17.33	1.18	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:1	34.08	2206	1.2	13.45	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.48	17.21	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:1	34.08	2204	1.2	13.45	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	17.1	1.17	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:1	34.08	2203	1.2	13.44	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	17	1.16	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:1	34.08	2204	1.2	13.44	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.7	-10.46	16.9	1.15	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:2	34.08	2205	1.2	13.43	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.47	16.82	1.15	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:2	34.08	2207	1.19	13.43	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.48	16.7	1.14	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:2	34.08	2214	1.19	13.43	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.47	16.61	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:2	34.08	2210	1.19	13.45	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.46	16.52	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:2	34.08	2211	1.19	13.44	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.46	16.44	1.12	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:2	34.08	2212	1.19	13.43	98	195	Off Idle	82.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	16.34	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:3	34.08	2212	1.19	13.43	98	195	Off Idle	82.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.5	16.3	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:3	34.08	2211	1.19	13.42	98	195	Off Idle	82.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.5	16.25	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:3	34.08	2210	1.19	13.44	98	195	Off Idle	82.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.5	16.2	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:3	34.08	2208	1.19	13.43	98	195	Off Idle	82.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.46	16.13	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:3	34.08	2204	1.19	13.44	98	195	Off Idle	82.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.46	16.08	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:3	34.08	2202	1.19	13.44	98	195	Off Idle	82.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.44	16.02	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:4	34.08	2206	1.19	13.42	98	195	Off Idle	82.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.44	15.97	1.09	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:4	34.08	2194	1.19	13.44	98	195	Off Idle	81.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.42	15.93	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:4	34.08	2191	1.19	13.44	98	195	Off Idle	81.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.46	15.87	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:4	34.08	2188	1.19	13.44	98	195	Off Idle	81.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.45	15.83	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:4	34.08	2163	1.19	13.45	98	195	Off Idle	82.2	0	2	132	944 Turbo	0.08	Lean	1	14.7	-10.46	15.78	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:4	34.08	2172	1.19	13.45	98	195	Off Idle	82.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.46	15.74	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:4	34.08	2172	1.19	13.46	98	195	Off Idle	82.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.45	15.72	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:5	34.08	2169	1.19	13.45	98	195	Off Idle	82.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-10.44	15.7	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:5	34.08	2171	1.19	13.44	98	195	Off Idle	82.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.48	15.68	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:01:5	34.08	2170	1.19	13.42	98	195	Off Idle	83.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.49	15.68	1.07	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:01:5	34.08	2172	1.19	13.42	98	195	Off Idle	83.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.48	15.68	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:5	34.08	2174	1.19	13.43	98	195	Off Idle	83.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.47	15.67	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:5	34.08	2176	1.19	13.44	98	195	Off Idle	83.9	0	2	132	944 Turbo	0.09	Lean	1	14.7	-10.46	15.66	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:6	34.08	2176	1.19	13.45	98	195	Off Idle	84.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.42	15.65	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:6	34.08	2174	1.19	13.46	98	195	Off Idle	84.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-10.4	15.66	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:6	34.08	2172	1.18	13.46	98	195	Off Idle	84.6	0	2	132	944 Turbo	0.11	Lean	1	14.7	-10.4	15.65	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:6	34.08	2173	1.18	13.46	98	195	Off Idle	84.6	0	2	132	944 Turbo	0.13	Lean	1	14.7	-10.39	15.64	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:6	34.08	2174	1.18	13.45	98	195	Off Idle	84.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.42	15.63	1.07	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:6	34.08	2173	1.18	13.45	98	195	Off Idle	84.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.42	15.62	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:6	34.08	2171	1.18	13.43	98	195	Off Idle	84.6	0	2	132	944 Turbo	0.24	Lean	1	14.7	-10.45	15.61	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:7	34.08	2171	1.18	13.41	98	195	Off Idle	84.6	0	2	132	944 Turbo	0.32	Rich	1	14.7	-10.47	15.6	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:7	34.08	2175	1.17	13.4	98	195	Off Idle	84.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-10.49	15.58	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:7	34.08	2173	1.17	13.38	98	195	Off Idle	84.4	0	2	132	944 Turbo	0.44	Rich	1	14.7	-10.5	15.55	1.06	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:7	34.08	2170	1.17	13.37	98	195	Off Idle	84.3	0	2	132	944 Turbo	0.5	Rich	1	14.7	-10.49	15.53	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:7	34.08	2163	1.17	13.39	98	195	Off Idle	84.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-10.46	15.51	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:7	34.08	2161	1.17	13.41	98	195	Off Idle	84	0	2	132	944 Turbo	0.61	Rich	1	14.7	-10.46	15.49	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:8	34.08	2156	1.17	13.42	98	195	Off Idle	83.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.46	15.46	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:01:8	34.08	2163	1.17	13.42	98	195	Off Idle	83.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.45	15.43	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:8	34.08	2162	1.17	13.42	98	195	Off Idle	83.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-10.46	15.39	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:8	34.08	2162	1.17	13.41	98	195	Off Idle	83.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.47	15.36	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:8	34.08	2162	1.17	13.41	98	195	Off Idle	84	0	2	132	944 Turbo	0.72	Rich	1	14.7	-10.47	15.34	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:8	34.08	2158	1.17	13.42	98	195	Off Idle	84	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.42	15.3	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:9	34.08	2155	1.17	13.43	98	195	Off Idle	83.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	-10.41	15.27	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:9	34.08	2155	1.17	13.43	98	195	Off Idle	84.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.44	15.2	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:9	34.08	2154	1.17	13.43	98	195	Off Idle	84.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.46	15.19	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:9	34.08	2151	1.17	13.42	98	195	Off Idle	84.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.5	15.17	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:9	34.08	2151	1.17	13.42	98	195	Off Idle	84.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.48	15.13	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:9	34.08	2147	1.17	13.42	98	195	Off Idle	84.6	0	2	132	944 Turbo	0.45	Rich	1	14.7	-10.47	15.11	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:01:9	34.08	2138	1.17	13.43	98	195	Off Idle	84.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-10.45	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:0	34.08	2134	1.17	13.44	98	195	Off Idle	84.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-10.43	15.05	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:0	34.08	2138	1.17	13.46	98	194	Off Idle	85	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.44	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:0	34.08	2142	1.17	13.45	98	194	Off Idle	85	0	2	132	944 Turbo	0.19	Lean	1	14.6	-10.46	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:0	34.08	2142	1.17	13.45	98	194	Off Idle	85.2	0	2	132	944 Turbo	0.15	Lean	1	14.7	-10.47	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:0	34.08	2140	1.17	13.45	98	194	Off Idle	85.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.45	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:0	34.08	2135	1.16	13.44	98	194	Off Idle	85.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.47	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:1	34.08	2131	1.16	13.42	98	194	Off Idle	85.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.48	15.01	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:1	34.08	2131	1.16	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.7	-10.46	15	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:1	34.08	2131	1.16	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.45	14.99	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:1	34.08	2134	1.16	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.7	-10.45	14.98	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:1	34.08	2134	1.16	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.45	14.96	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:1	34.08	2126	1.16	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.44	14.95	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:1	34.08	2137	1.16	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.41	14.93	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:2	34.08	2137	1.16	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-10.4	14.9	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:2	34.08	2136	1.16	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-10.42	14.89	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:2	34.08	2135	1.16	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-10.42	14.9	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:2	34.08	2135	1.16	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.33	Lean	1	14.7	-10.43	14.91	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:2	34.08	2133	1.16	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.43	Lean	1	14.7	-10.44	14.93	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:2	34.08	2131	1.16	13.44	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-10.46	14.97	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:3	34.08	2126	1.16	13.44	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-10.47	14.98	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:3	34.08	2124	1.16	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.62	Lean	1	14.7	-10.49	15	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:3	34.08	2118	1.16	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.47	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:3	34.08	2098	1.16	13.4	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.47	15.09	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:3	34.08	2106	1.16	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	-10.46	15.11	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:3	34.08	2118	1.16	13.4	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-10.44	15.12	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:4	34.08	2120	1.16	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.42	15.14	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:4	34.08	2119	1.16	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.7	-10.4	15.14	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:4	34.08	2119	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-10.39	15.14	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:4	34.08	2119	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.39	15.14	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:4	34.08	2119	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-10.41	15.13	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:4	34.08	2117	1.15	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.42	15.11	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:4	34.08	2111	1.15	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.42	15.09	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:5	34.08	2112	1.15	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.7	-10.41	15.08	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:5	34.08	2112	1.15	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-10.4	15.09	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:5	34.08	2110	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.39	15.08	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:5	34.08	2108	1.15	13.44	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-10.39	15.05	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:5	34.08	2109	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.4	15.02	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:5	34.08	2108	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.41	14.98	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:6	34.08	2107	1.15	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.42	14.96	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:6	34.08	2107	1.15	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-10.41	14.94	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:6	34.08	2106	1.15	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.46	Rich	1	14.7	-10.39	14.91	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:6	34.08	2104	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-10.39	14.88	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:6	34.08	2104	1.15	13.44	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.31	Lean	1	14.7	-10.39	14.8	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:6	34.08	2106	1.15	13.44	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-10.4	14.76	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:6	34.08	2108	1.15	13.44	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-10.41	14.74	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:7	34.08	2110	1.15	13.44	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.44	14.73	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:02:7	34.08	2110	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.44	14.71	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:7	34.08	2109	1.15	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-10.43	14.7	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:7	34.08	2103	1.15	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-10.39	14.7	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:7	34.08	2096	1.15	13.4	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.36	14.68	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:7	34.08	2094	1.15	13.41	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.34	14.7	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:8	34.08	2085	1.15	13.41	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.33	14.71	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:02:8	34.08	2082	1.15	13.42	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.32	14.72	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:02:8	34.08	2084	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.34	14.74	1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:02:8	34.08	2084	1.15	13.44	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.35	14.76	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:8	34.08	2082	1.15	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-10.33	14.76	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:8	34.08	2082	1.15	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.33	14.76	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:02:9	34.08	2078	1.15	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.7	-10.32	14.77	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:02:9	34.08	2080	1.15	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-10.33	14.79	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:9	34.08	2083	1.15	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-10.35	14.81	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:9	34.08	2088	1.15	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-10.39	14.83	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:9	34.08	2088	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.45	Rich	1	14.7	-10.43	14.86	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:9	34.08	2090	1.15	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-10.41	14.89	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:02:9	34.08	2092	1.15	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-10.39	14.91	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:0	34.08	2092	1.15	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.36	14.94	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:0	34.08	2089	1.15	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.33	14.97	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:0	34.08	2083	1.15	13.43	98	194	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.29	15.03	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:0	34.08	2083	1.15	13.45	98	194	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	-10.3	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:0	34.08	2081	1.15	13.46	98	194	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.32	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:0	34.08	2078	1.15	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.7	-10.33	15.08	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:1	34.08	2076	1.15	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.34	15.08	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:1	34.08	2076	1.15	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.34	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:1	34.08	2074	1.15	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.36	15.08	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:1	34.08	2074	1.15	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.33	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:1	34.08	2074	1.15	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.32	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:1	34.08	2074	1.15	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-10.32	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:1	34.08	2073	1.15	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.3	15.08	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:2	34.08	2071	1.15	13.46	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.29	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:2	34.08	2070	1.15	13.47	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.31	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:2	34.08	2064	1.15	13.47	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.32	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:2	34.08	2059	1.15	13.45	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-10.35	15.01	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:2	34.08	2059	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.38	14.98	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:2	34.08	2050	1.15	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.39	14.95	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:3	34.08	2059	1.15	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-10.39	14.93	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:3	34.08	2059	1.15	13.41	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-10.37	14.9	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:3	34.08	2061	1.15	13.42	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.34	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:3	34.08	2065	1.15	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.31	14.79	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:3	34.08	2081	1.15	13.44	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.34	14.77	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:3	34.08	2072	1.15	13.45	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.35	14.74	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:4	34.08	2059	1.15	13.45	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.37	14.74	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:4	34.08	2058	1.15	13.44	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.37	14.71	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:4	34.08	2051	1.15	13.44	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.7	-10.37	14.71	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:4	34.08	2045	1.14	13.44	98	194	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.7	-10.38	14.7	1	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:4	34.08	2041	1.14	13.44	98	194	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.7	-10.39	14.7	1	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:4	34.08	2041	1.14	13.44	98	194	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-10.41	14.7	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:4	34.08	2040	1.14	13.44	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.43	14.71	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:5	34.08	2042	1.13	13.43	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.68	Rich	1	14.7	-10.46	14.71	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:5	34.08	2043	1.13	13.42	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.49	14.72	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:5	34.08	2044	1.13	13.42	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-10.51	14.74	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:5	32.72	2021	1.13	13.4	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-10.52	14.74	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:5	32.72	2026	1.12	13.4	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.5	Rich	1	14.7	-10.53	14.76	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:5	32.72	2034	1.12	13.41	98	194	Off Idle	85.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-10.51	14.77	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:6	32.72	2037	1.12	13.42	98	194	Off Idle	85.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-10.52	14.78	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:6	32.72	2037	1.11	13.43	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.29	Lean	1	14.7	-10.51	14.79	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:03:6	32.72	2043	1.11	13.44	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-10.52	14.8	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:6	32.72	2043	1.11	13.46	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-10.5	14.8	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:6	32.72	2040	1.1	13.46	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.49	14.81	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:6	32.72	2056	1.1	13.46	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-10.48	14.82	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:6	32.72	2056	1.1	13.45	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.48	14.82	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:7	32.72	2041	1.09	13.45	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.51	14.82	1.01	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:7	32.72	2035	1.09	13.45	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.52	14.82	1.01	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:7	32.72	2017	1.08	13.46	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.58	14.83	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:7	32.72	2024	1.08	13.47	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.6	14.85	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:7	32.72	2026	1.07	13.47	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.09	Lean	1	14.7	-10.62	14.85	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:7	32.72	2018	1.07	13.47	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.09	Lean	1	14.7	-10.67	14.85	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:8	32.72	2018	1.07	13.46	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.69	14.85	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:8	32.72	2017	1.06	13.44	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.71	14.85	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:8	32.72	2006	1.06	13.44	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.72	14.85	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:8	32.72	2006	1.05	13.43	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.71	14.86	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:8	32.72	1995	1.05	13.44	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.71	14.86	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:8	32.72	2000	1.04	13.44	98	195	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.71	14.88	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:9	32.72	1998	1.04	13.43	98	195	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.7	-10.68	14.89	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:9	32.72	1998	1.03	13.42	98	195	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.67	14.88	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:9	32.72	2003	1.03	13.42	98	195	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.67	14.92	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:9	32.72	2006	1.02	13.41	98	195	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.7	-10.68	14.95	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:9	32.72	2006	1.02	13.41	98	195	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-10.66	14.97	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:03:9	32.72	2009	1.02	13.42	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.67	14.99	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:03:9	32.72	2007	1.01	13.43	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.71	15.03	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:0	32.72	2006	1.01	13.43	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.75	15.05	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:0	32.72	2000	1.01	13.43	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.79	15.08	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:0	32.72	1998	1	13.43	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.84	15.1	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:0	32.72	1998	1	13.44	98	194	Off Idle	85.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.85	15.13	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:0	32.72	1998	1	13.45	98	195	Full Load	85.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.85	15.17	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:0	32.72	1993	0.99	13.46	98	195	Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.87	15.18	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:1	32.72	1991	0.99	13.46	98	195	Idle	85.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.86	15.2	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:1	32.72	1991	0.98	13.46	98	194	Idle	84.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.87	15.21	1.04	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:1	32.72	1973	0.98	13.45	98	194	Idle	83.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.86	15.21	1.04	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:1	29.99	1953	0.98	13.45	98	194	Idle	82.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.85	15.21	1.04	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:1	29.99	1953	0.98	13.44	98	194	Idle	80.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.83	15.21	1.04	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:04:1	24.54	1948	0.99	13.45	98	194	Idle	79.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.81	15.2	1.04	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:1	24.54	1940	1	13.45	98	194	Idle	77.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.75	15.2	1.04	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:2	19.09	1940	1.02	13.46	98	194	Idle	73	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.69	15.2	1.04	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:2	17.72	1953	1.03	13.46	98	195	Idle	71.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.59	15.17	1.03	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:2	17.72	1941	1.05	13.45	98	195	Idle	70.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.43	15.16	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:2	17.72	1956	1.07	13.45	98	195	Idle	68.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.3	15.17	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:2	17.72	1954	1.08	13.44	98	194	Idle	67.9	0	2	132	944 Turbo	0.06	Lean	1	14.7	-10.25	15.18	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:2	17.72	1954	1.11	13.42	98	194	Idle	67.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.08	15.21	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:3	17.72	1954	1.12	13.41	98	194	Idle	66.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10	15.23	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:3	17.72	1956	1.14	13.4	98	195	Idle	65.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.95	15.26	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:3	17.72	1961	1.15	13.39	98	195	Idle	66	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.9	15.3	1.04	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:3	17.72	1962	1.17	13.4	98	195	Idle	66.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.88	15.35	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:3	17.72	1963	1.18	13.41	98	195	Idle	67.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.9	15.4	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:3	17.72	1964	1.19	13.42	98	195	Idle	68.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.94	15.46	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:4	17.72	1964	1.2	13.43	98	195	Idle	70.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.98	15.5	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:4	17.72	1962	1.21	13.44	98	194	Idle	72.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.02	15.55	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:4	17.72	1961	1.22	13.45	98	194	Idle	76.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.04	15.6	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:4	17.72	1956	1.22	13.46	98	194	Idle	78	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.07	15.63	1.06	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:4	17.72	1951	1.22	13.45	98	195	Idle	79.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.1	15.67	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:4	17.72	1940	1.22	13.45	98	195	Idle	80.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.13	15.69	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:4	17.72	1940	1.2	13.43	98	195	Idle	81.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.17	15.72	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:5	17.72	1936	1.19	13.43	98	195	Idle	82.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.19	15.73	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:5	17.72	1928	1.17	13.41	98	195	Idle	82.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.22	15.74	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:04:8	17.72	1928	1.15	13.41	98	195	Idle	83.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.26	15.75	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1924	1.13	13.4	98	195	Idle	83.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.26	15.75	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1921	1.1	13.4	98	195	Idle	84	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.27	15.77	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1921	1.08	13.41	98	195	Idle	84.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.3	15.76	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1919	1.07	13.42	98	195	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	15.77	1.07	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1918	1.06	13.45	98	195	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	15.79	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1917	1.05	13.44	98	195	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	15.82	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1917	1.04	13.46	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	15.88	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1916	1.03	13.46	98	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	15.98	1.09	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1915	1.02	13.47	98	195	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	16.12	1.1	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1915	1.01	13.46	98	195	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	16.32	1.11	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:7	17.72	1915	1	13.46	98	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	16.45	1.12	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:7	17.72	1910	1	13.46	98	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	16.92	1.15	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:7	17.72	1910	1	13.44	98	194	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	17.34	1.18	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:7	17.72	1906	0.99	13.41	98	194	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	17.77	1.21	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:7	17.72	1901	0.99	13.4	98	194	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	18.2	1.24	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:7	17.72	1897	0.99	13.4	98	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	18.81	1.28	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1897	0.99	13.41	98	194	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	19.18	1.31	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1892	0.99	13.42	98	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	19.52	1.33	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1888	0.99	13.43	98	194	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	19.78	1.35	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1888	0.99	13.43	98	195	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20	1.36	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1884	0.99	13.43	98	195	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.18	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:8	17.72	1881	0.99	13.42	98	195	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.2	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:9	17.72	1879	0.99	13.43	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:9	17.72	1879	0.99	13.43	98	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:9	17.72	1876	0.99	13.42	98	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.21	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:9	17.72	1873	0.98	13.42	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:9	17.72	1873	0.98	13.42	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:9	17.72	1871	0.98	13.42	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:04:9	17.72	1868	0.98	13.43	98	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:0	17.72	1865	0.98	13.41	98	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:0	17.72	1865	0.98	13.41	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:0	17.72	1856	0.98	13.41	98	195	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:0	17.72	1858	0.98	13.42	98	195	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:0	17.72	1855	0.98	13.43	98	195	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:0	17.72	1855	0.98	13.44	98	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:1	17.72	1858	0.98	13.45	98	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:1	17.72	1847	0.98	13.44	98	194	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:1	17.72	1847	0.98	13.43	98	195	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:1	17.72	1836	0.98	13.42	98	195	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:1	17.72	1839	0.98	13.41	98	195	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:1	17.72	1839	0.98	13.41	98	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:1	17.72	1837	0.98	13.42	98	194	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:2	17.72	1837	0.98	13.43	98	194	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:2	17.72	1834	0.98	13.45	98	195	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:2	17.72	1831	0.98	13.43	98	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:2	17.72	1828	0.97	13.4	98	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:2	17.72	1827	0.97	13.38	98	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:2	17.72	1826	0.97	13.36	98	195	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:3	17.72	1823	0.97	13.35	98	195	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:3	17.72	1819	0.97	13.37	98	195	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:3	17.72	1818	0.97	13.38	98	195	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:3	17.72	1816	0.97	13.38	98	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:3	17.72	1813	0.97	13.38	98	195	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:3	17.72	1810	0.97	13.38	98	195	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:4	17.72	1810	0.97	13.38	98	195	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:4	17.72	1808	0.97	13.39	98	195	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:4	17.72	1806	0.97	13.37	98	195	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:05:4	17.72	1804	0.97	13.37	98	195	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:4	17.72	1804	0.97	13.37	98	195	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:4	17.72	1801	0.97	13.39	98	195	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:4	17.72	1797	0.97	13.38	98	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:5	17.72	1797	0.97	13.39	98	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:5	17.72	1792	0.97	13.38	98	195	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:5	17.72	1787	0.97	13.39	98	195	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:5	17.72	1787	0.97	13.39	98	195	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:5	17.72	1782	0.97	13.39	98	195	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:5	17.72	1776	0.97	13.4	98	194	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:6	17.72	1769	0.97	13.39	98	194	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:6	17.72	1769	0.97	13.38	98	194	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:6	17.72	1766	0.97	13.37	98	195	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:6	17.72	1762	0.97	13.37	98	195	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:6	17.72	1760	0.97	13.36	98	195	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:6	17.72	1754	0.97	13.37	98	195	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:6	17.72	1751	0.97	13.39	98	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:7	17.72	1751	0.97	13.37	98	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:7	17.72	1745	0.97	13.37	98	195	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:7	17.72	1740	0.97	13.37	98	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.2	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:7	17.72	1740	0.97	13.38	98	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.2	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:7	17.72	1737	0.97	13.36	98	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:7	17.72	1734	0.97	13.36	98	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:8	17.72	1729	0.98	13.37	98	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:8	17.72	1729	0.98	13.37	98	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:8	17.72	1723	0.98	13.38	98	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.2	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:8	17.72	1718	0.98	13.38	98	194	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.2	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:8	17.72	1712	0.98	13.37	98	195	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:8	17.72	1712	0.98	13.39	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:9	17.72	1705	0.98	13.37	98	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:9	17.72	1696	0.98	13.38	98	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:9	17.72	1696	0.98	13.39	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:9	17.72	1696	0.98	13.39	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:9	17.72	1687	0.98	13.38	98	195	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.23	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:9	17.72	1687	0.98	13.38	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	20.24	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:05:9	17.72	1676	0.98	13.36	98	195	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.24	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:0	17.72	1676	0.98	13.35	98	195	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:0	17.72	1672	0.98	13.36	98	195	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.23	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:0	17.72	1672	0.98	13.35	98	195	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.18	20.23	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:0	17.72	1667	0.98	13.36	98	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:0	17.72	1665	0.98	13.38	98	195	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:0	17.72	1647	0.98	13.38	98	195	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:1	17.72	1647	0.98	13.37	98	195	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:1	17.72	1629	0.98	13.37	98	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:1	17.72	1611	0.98	13.35	98	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:1	17.72	1600	0.99	13.36	98	195	Idle	82.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.21	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:1	17.72	1578	0.99	13.37	98	195	Idle	82.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:1	17.72	1568	0.99	13.37	98	195	Idle	82.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:1	17.72	1556	0.99	13.37	98	195	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.22	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:2	17.72	1511	0.99	13.38	98	195	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.22	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:2	17.72	1499	0.99	13.37	98	195	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:2	17.72	1474	0.99	13.39	98	195	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:2	17.72	1474	1	13.38	98	195	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.22	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:2	17.72	1449	1	13.38	98	195	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:2	17.72	1423	1	13.37	98	195	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.23	1.38	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:3	17.72	1423	1.01	13.36	98	195	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.67	20.22	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:06:3	17.72	1386	1.01	13.38	98	195	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.22	1.38	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:06:3	17.72	1369	1.02	13.36	98	195	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	20.22	1.38	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:06:3	17.72	1369	1.03	13.36	98	195	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	20.22	1.38	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:06:3	17.72	1331	1.04	13.37	98	195	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.27	20.22	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:06:3	17.72	1313	1.05	13.37	98	195	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.22	1.38	4.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:06:4	17.72	1284	1.05	13.36	98	194	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.22	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:4	17.72	1248	1.06	13.38	98	194	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	20.22	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:4	16.36	1248	1.07	13.38	98	194	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.86	20.22	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:4	16.36	1239	1.08	13.38	98	195	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	20.21	1.38	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:4	16.36	1239	1.09	13.39	98	195	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.66	20.21	1.38	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:4	16.36	1225	1.1	13.38	98	195	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.58	20.21	1.38	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:4	16.36	1210	1.11	13.37	98	195	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.49	20.21	1.38	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:06:5	16.36	1208	1.11	13.37	98	195	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.42	20.21	1.38	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:06:5	16.36	1189	1.12	13.37	98	195	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.37	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:06:5	16.36	1189	1.13	13.36	98	195	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.31	20.21	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:06:5	16.36	1207	1.13	13.36	98	195	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.28	20.21	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:06:5	16.36	1215	1.14	13.37	98	195	Idle	74.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.25	20.21	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:06:5	16.36	1215	1.14	13.37	98	195	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.23	20.21	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:06:6	16.36	1225	1.14	13.38	98	195	Idle	75.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.21	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:6	14.99	1226	1.14	13.38	98	195	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.22	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:6	14.99	1238	1.14	13.38	98	195	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.22	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:6	14.99	1238	1.13	13.38	98	195	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.22	20.23	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:06:6	14.99	1241	1.13	13.36	98	195	Idle	79.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.23	20.23	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:06:6	14.99	1244	1.12	13.37	98	195	Idle	80.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.26	20.23	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:06:6	14.99	1244	1.11	13.35	98	195	Idle	81.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.27	20.23	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:7	13.63	1246	1.11	13.35	98	195	Idle	82.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.31	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:7	13.63	1247	1.09	13.37	98	195	Idle	83.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.4	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:7	13.63	1239	1.08	13.37	98	195	Idle	84.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.42	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:06:7	13.63	1231	1.07	13.35	98	195	Idle	85	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.45	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:06:7	13.63	1224	1.06	13.37	98	195	Idle	85.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.45	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:06:7	13.63	1224	1.05	13.36	98	195	Idle	85.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.48	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:06:8	14.99	1224	1.04	13.36	98	195	Idle	86.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.49	20.21	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:06:8	14.99	1198	1.03	13.37	98	195	Idle	86.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.5	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:06:8	14.99	1200	1.01	13.36	98	195	Idle	87.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	20.21	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:06:8	14.99	1200	1	13.38	98	195	Idle	87.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.56	20.21	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:06:8	14.99	1174	0.99	13.37	98	195	Idle	87.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.58	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:06:8	14.99	1174	0.99	13.37	98	195	Idle	87.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.6	20.22	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:9	14.99	1169	0.98	13.38	98	195	Idle	87.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.56	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:9	14.99	1149	0.97	13.38	98	195	Idle	87.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.57	20.22	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:9	14.99	1140	0.97	13.39	98	195	Idle	88.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.59	20.21	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:9	14.99	1140	0.96	13.39	98	195	Idle	88.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.57	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:9	14.99	1127	0.96	13.39	98	195	Idle	88.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.62	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:9	14.99	1127	0.95	13.39	98	195	Idle	88.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.6	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:06:9	14.99	1121	0.95	13.38	98	195	Idle	88.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.58	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:0	14.99	1110	0.95	13.38	98	195	Idle	88.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.57	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:0	13.63	1104	0.95	13.37	98	195	Idle	88.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.6	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:0	13.63	1107	0.94	13.37	98	195	Idle	89	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.62	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:0	13.63	1107	0.94	13.38	98	195	Idle	89.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.59	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:0	13.63	1095	0.94	13.37	98	195	Idle	89.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.6	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:0	13.63	1095	0.93	13.38	98	195	Idle	90.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.59	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:1	13.63	1091	0.93	13.37	98	195	Idle	90.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	20.21	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:1	13.63	1091	0.93	13.39	98	195	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	20.22	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:1	13.63	1089	0.92	13.38	98	195	Idle	91.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	20.22	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:1	13.63	1077	0.92	13.37	98	195	Idle	91.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.53	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:1	13.63	1077	0.91	13.37	98	195	Idle	91.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	20.2	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:1	13.63	1074	0.91	13.37	98	195	Idle	92.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.54	20.12	1.37	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:1	13.63	1074	0.91	13.38	98	195	Idle	92.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.5	19.97	1.36	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:2	13.63	1074	0.9	13.37	98	195	Idle	92.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	19.79	1.35	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:2	12.27	1062	0.9	13.39	98	195	Idle	92.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	19.56	1.33	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:2	12.27	1050	0.89	13.38	98	195	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.48	19.17	1.31	4.9	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:07:2	12.27	1040	0.89	13.39	98	195	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.53	18.87	1.29	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:2	12.27	1040	0.89	13.39	98	195	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.5	18.55	1.26	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:2	12.27	1030	0.88	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	18.19	1.24	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:3	12.27	1030	0.88	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.47	17.82	1.21	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:3	12.27	1028	0.88	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	17.5	1.19	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:3	12.27	1025	0.87	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.44	17.22	1.17	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:3	12.27	1031	0.87	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.45	17	1.16	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:3	12.27	1031	0.87	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.43	16.72	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:3	12.27	1013	0.87	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.38	16.64	1.13	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:4	12.27	1023	0.86	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.41	16.49	1.12	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:4	10.9	1023	0.86	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.35	16.39	1.12	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:4	10.9	1024	0.86	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.4	16.29	1.11	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:4	10.9	1026	0.86	13.4	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.35	16.24	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:4	10.9	1006	0.86	13.38	98	194	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.36	16.18	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:4	10.9	1006	0.86	13.39	98	194	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.34	16.15	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:4	10.9	1007	0.86	13.39	98	194	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.34	16.12	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:5	10.9	1007	0.86	13.4	98	194	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.32	16.1	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:5	10.9	1003	0.86	13.41	98	194	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.36	16.09	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:5	10.9	999	0.86	13.41	98	194	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.3	16.09	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:5	10.9	989	0.86	13.41	98	194	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.31	16.08	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:5	10.9	989	0.86	13.43	98	194	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.3	16.08	1.1	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:5	10.9	992	0.86	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.27	16.05	1.09	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:6	10.9	994	0.86	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.31	16.02	1.09	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:6	10.9	991	0.85	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.23	15.99	1.09	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:6	10.9	982	0.85	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.29	15.96	1.09	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:6	10.9	982	0.85	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.25	15.94	1.09	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:6	10.9	978	0.85	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.26	15.9	1.08	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:6	10.9	973	0.85	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.21	15.85	1.08	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:6	10.9	973	0.85	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.23	15.81	1.08	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:7	9.54	969	0.85	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.18	15.76	1.07	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:7	9.54	974	0.85	13.41	98	194	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.21	15.69	1.07	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:7	9.54	974	0.85	13.41	98	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.17	15.66	1.07	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:7	9.54	974	0.85	13.43	98	194	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.21	15.61	1.06	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:7	8.18	952	0.85	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.15	15.56	1.06	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:7	8.18	952	0.85	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.18	15.55	1.06	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:07:8	8.18	952	0.85	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.17	15.49	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:8	9.54	952	0.85	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.16	15.45	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:8	9.54	951	0.85	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.1	15.44	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:8	9.54	936	0.85	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.14	15.42	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:8	9.54	936	0.85	13.42	98	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.03	15.41	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:8	9.54	933	0.84	13.42	98	194	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.04	15.41	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:9	9.54	930	0.84	13.42	98	194	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.02	15.4	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:9	9.54	930	0.84	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.06	15.41	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:9	9.54	930	0.84	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.98	15.41	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:9	9.54	928	0.84	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.03	15.4	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:9	9.54	925	0.84	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.99	15.4	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:9	9.54	935	0.84	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8	15.39	1.05	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:07:9	9.54	935	0.84	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.96	15.4	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:0	9.54	933	0.84	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.01	15.39	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:0	8.18	931	0.84	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.95	15.39	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:0	8.18	931	0.84	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.98	15.38	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:0	8.18	934	0.84	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.92	15.38	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:0	8.18	924	0.84	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.96	15.38	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:0	8.18	924	0.84	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.91	15.36	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:1	8.18	924	0.84	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.96	15.36	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:1	8.18	936	0.84	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.7	-7.95	15.34	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:1	8.18	936	0.84	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.97	15.32	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:1	9.54	942	0.84	13.4	98	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.91	15.3	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:08:1	9.54	929	0.84	13.41	98	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.92	15.29	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:1	9.54	929	0.84	13.41	98	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.89	15.27	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:1	9.54	929	0.83	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.91	15.24	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:2	8.18	935	0.83	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.89	15.23	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:2	8.18	935	0.83	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-7.94	15.23	1.04	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:2	8.18	929	0.83	13.44	98	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.89	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:2	8.18	929	0.83	13.44	98	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.91	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:2	9.54	927	0.83	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.89	15.19	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:2	9.54	927	0.83	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.91	15.17	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:3	9.54	919	0.83	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.89	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:3	9.54	911	0.83	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.93	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:3	8.18	937	0.83	13.4	98	195	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.87	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:3	8.18	937	0.83	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.88	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:3	8.18	927	0.83	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.85	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:3	8.18	927	0.83	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.83	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:4	8.18	923	0.83	13.4	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.82	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:4	8.18	923	0.83	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.06	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:4	8.18	928	0.83	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.84	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:4	8.18	928	0.83	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.84	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:4	9.54	932	0.83	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.85	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:4	9.54	932	0.83	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.86	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:4	9.54	936	0.83	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.89	14.99	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:5	9.54	939	0.83	13.44	98	195	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.9	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:5	8.18	936	0.83	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.87	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:5	8.18	936	0.83	13.44	98	195	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.9	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:5	8.18	925	0.83	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.88	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:5	8.18	925	0.83	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.85	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:5	8.18	922	0.83	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.84	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:6	8.18	920	0.83	13.43	98	194	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.88	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:6	8.18	909	0.83	13.41	98	194	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.85	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:6	8.18	909	0.83	13.43	98	194	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.89	14.94	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:6	9.54	916	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.89	14.92	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:6	9.54	922	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.88	14.92	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:6	9.54	901	0.82	13.41	98	194	Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.85	14.89	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:08:6	9.54	901	0.82	13.43	98	194	Idle	93.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.86	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:7	8.18	911	0.82	13.42	98	194	Idle	93.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.84	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:7	8.18	921	0.82	13.42	98	194	Idle	93.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.82	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:7	8.18	915	0.82	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.85	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:7	8.18	915	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.81	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:7	8.18	912	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.84	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:7	8.18	909	0.82	13.44	98	195	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.78	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:8	8.18	909	0.82	13.44	98	195	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.8	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:8	8.18	903	0.82	13.45	98	194	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.78	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:8	8.18	912	0.82	13.45	98	194	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.8	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:8	8.18	922	0.82	13.43	98	194	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:8	8.18	922	0.82	13.45	98	195	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.82	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:8	8.18	914	0.82	13.44	98	195	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:9	8.18	914	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.8	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:9	8.18	912	0.82	13.41	99	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:9	8.18	912	0.82	13.43	99	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.8	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:9	8.18	913	0.82	13.41	99	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:9	8.18	913	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:9	8.18	914	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:08:9	8.18	916	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.8	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:0	8.18	918	0.82	13.4	98	195	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:0	8.18	918	0.82	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.81	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:0	6.81	901	0.82	13.4	98	195	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.8	14.8	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:0	6.81	901	0.82	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.82	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:09:0	6.81	921	0.82	13.4	98	195	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	14.79	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:0	6.81	921	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.8	14.79	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:1	8.18	918	0.82	13.4	98	195	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.79	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:1	8.18	918	0.82	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.77	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:1	8.18	914	0.82	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.8	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:1	8.18	911	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.77	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:1	8.18	921	0.82	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.84	14.9	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:1	8.18	921	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.79	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:1	8.18	923	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.83	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:2	8.18	925	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.79	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:2	8.18	925	0.82	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.8	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:2	8.18	923	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:2	8.18	934	0.82	13.41	98	194	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.81	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:2	8.18	934	0.82	13.43	98	194	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.78	15.05	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:2	8.18	935	0.82	13.41	98	194	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.81	15.07	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:3	8.18	936	0.82	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:3	8.18	924	0.82	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.83	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:3	8.18	924	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.8	15.08	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:3	9.54	932	0.82	13.41	98	194	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.83	15.08	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:3	9.54	941	0.82	13.43	98	194	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	15.09	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:3	9.54	936	0.82	13.42	98	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.08	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:4	9.54	936	0.82	13.43	98	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	15.08	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:4	8.18	932	0.82	13.41	98	194	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:4	8.18	929	0.82	13.42	98	194	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.83	15.08	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:4	8.18	929	0.82	13.43	98	194	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.89	15.06	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:4	8.18	935	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.84	15.06	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:4	8.18	926	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.85	15.04	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:4	8.18	918	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.86	15.03	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:5	8.18	918	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.89	15.01	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:5	8.18	930	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.84	15.01	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:5	8.18	925	0.82	13.44	98	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.89	14.99	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:5	8.18	925	0.82	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.87	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:5	8.18	925	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.88	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:09:5	8.18	924	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.86	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:6	8.18	910	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.89	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:6	8.18	910	0.82	13.41	98	195	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.82	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:6	8.18	910	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.83	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:6	8.18	917	0.82	13.42	98	195	Idle	93.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.8	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:6	8.18	917	0.82	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.82	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:6	9.54	912	0.82	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.83	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:6	9.54	912	0.82	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.84	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:7	9.54	916	0.82	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.81	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:7	9.54	916	0.82	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.86	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:7	8.18	922	0.82	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.84	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:7	8.18	922	0.82	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.85	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:7	8.18	920	0.82	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.81	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:7	8.18	917	0.82	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.83	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:8	8.18	922	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.81	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:8	8.18	922	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.8	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:8	8.18	928	0.82	13.35	98	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.8	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:8	8.18	933	0.82	13.34	98	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.82	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:8	8.18	925	0.82	13.33	98	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.82	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:8	8.18	925	0.82	13.35	98	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.85	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:9	8.18	928	0.82	13.33	98	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.86	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:9	8.18	932	0.82	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.88	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:9	6.81	925	0.82	13.35	98	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.86	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:9	6.81	925	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.86	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:9	6.81	920	0.82	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.83	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:09:9	6.81	914	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.81	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:09:9	6.81	921	0.82	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.85	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:0	6.81	921	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.82	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:0	6.81	923	0.82	13.35	98	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.85	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:0	6.81	925	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.84	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:0	9.54	925	0.82	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.83	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:0	9.54	926	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.8	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:0	9.54	907	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.81	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:1	9.54	907	0.82	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.78	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:1	9.54	907	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.81	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:1	9.54	916	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.78	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:1	9.54	924	0.82	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.83	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:1	9.54	924	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.79	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:1	9.54	924	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.82	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:1	9.54	912	0.82	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.79	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:2	9.54	912	0.82	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.81	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:2	9.54	935	0.82	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.79	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:2	9.54	935	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.82	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:2	9.54	933	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.81	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:2	9.54	924	0.82	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.85	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:2	9.54	924	0.82	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.79	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:3	9.54	927	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.84	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:3	9.54	930	0.82	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.8	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:3	9.54	930	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.81	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:3	9.54	916	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.79	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:3	9.54	916	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.83	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:3	9.54	933	0.82	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.78	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:4	9.54	933	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.83	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:4	9.54	914	0.82	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:4	9.54	914	0.82	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.82	15.08	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:4	8.18	920	0.82	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.8	15.08	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:4	8.18	927	0.82	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.85	15.08	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:4	8.18	933	0.82	13.36	98	194	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.84	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:4	8.18	933	0.82	13.38	98	194	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.87	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:5	6.81	919	0.81	13.37	98	194	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.83	15.05	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:5	6.81	919	0.81	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.86	15.05	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:5	6.81	925	0.81	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.85	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:5	6.81	925	0.81	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.88	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:5	6.81	912	0.81	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.86	14.98	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:5	6.81	912	0.81	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-7.85	14.98	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:10:6	6.81	923	0.81	13.38	99	195	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.86	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:6	6.81	934	0.81	13.38	99	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:6	8.18	934	0.81	13.36	99	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:6	8.18	915	0.81	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:6	8.18	910	0.81	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:6	8.18	910	0.81	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:6	8.18	910	0.81	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:7	8.18	910	0.81	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:7	8.18	901	0.81	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:7	8.18	901	0.81	13.4	98	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:7	8.18	903	0.81	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:7	8.18	905	0.81	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:7	8.18	905	0.81	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:8	8.18	904	0.81	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:8	8.18	904	0.81	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:8	6.81	900	0.81	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:8	6.81	897	0.81	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.83	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:8	6.81	897	0.81	13.36	98	195	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.77	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:10:8	6.81	897	0.81	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.79	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:9	8.18	896	0.81	13.36	98	195	Idle	93.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.77	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:9	8.18	896	0.81	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.77	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:9	8.18	890	0.81	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.74	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:9	8.18	890	0.81	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.77	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:9	9.54	890	0.81	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.76	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:9	9.54	889	0.81	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.76	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:10:9	9.54	862	0.81	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.76	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:0	9.54	862	0.81	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.71	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:0	9.54	862	0.81	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.71	14.89	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:0	9.54	899	0.81	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.68	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:0	9.54	906	0.81	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.68	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:0	9.54	906	0.81	13.36	98	195	Idle	93.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.68	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:0	9.54	906	0.81	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.71	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:1	9.54	905	0.81	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.69	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:1	9.54	910	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.73	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:1	9.54	910	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.7	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:1	9.54	910	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.74	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:1	9.54	917	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.72	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:1	9.54	922	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.78	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:1	9.54	922	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.73	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:2	9.54	924	0.8	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.41	Lean	1	14.7	-7.78	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:2	8.18	925	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.76	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:2	8.18	925	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.78	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:2	8.18	927	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.76	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:2	8.18	927	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.78	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:2	8.18	926	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.76	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:3	8.18	926	0.8	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.76	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:3	8.18	926	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.79	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:3	8.18	926	0.8	13.4	98	195	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.81	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:3	9.54	916	0.8	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:3	9.54	916	0.8	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.81	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:3	9.54	905	0.8	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.8	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:4	9.54	905	0.8	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:4	8.18	914	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:4	8.18	914	0.8	13.4	98	195	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:4	8.18	917	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:4	8.18	920	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.77	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:4	8.18	902	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:4	8.18	902	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:5	8.18	912	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:11:5	8.18	922	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:11:5	9.54	909	0.8	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.73	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:11:5	9.54	909	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.03	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:11:5	9.54	905	0.8	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:11:5	9.54	901	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:11:6	8.18	901	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:11:6	8.18	899	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:11:6	8.18	899	0.8	13.4	98	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:11:6	8.18	899	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:6	8.18	913	0.8	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:6	8.18	896	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.66	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:6	8.18	896	0.8	13.36	99	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:7	8.18	892	0.8	13.37	99	195	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:7	8.18	892	0.8	13.39	99	195	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.71	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:7	9.54	881	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:7	9.54	881	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.71	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:7	9.54	883	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.69	15	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:11:7	9.54	883	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.69	14.98	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:8	10.9	879	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.65	14.97	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:8	10.9	875	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.64	14.93	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:8	10.9	875	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.64	14.9	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:8	10.9	875	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.6	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:8	10.9	880	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.62	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:8	10.9	885	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.59	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:9	10.9	885	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.61	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:9	10.9	878	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.58	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:9	10.9	878	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.59	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:9	10.9	901	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.55	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:9	10.9	901	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.61	14.83	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:11:9	10.9	892	0.8	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:11:9	10.9	892	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:0	9.54	898	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.61	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:0	9.54	904	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:0	9.54	900	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:0	9.54	900	0.8	13.4	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.61	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:0	8.18	901	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:0	8.18	902	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.6	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:1	8.18	903	0.8	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:1	8.18	903	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:1	6.81	902	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:1	6.81	901	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:1	6.81	906	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:1	6.81	906	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:1	6.81	904	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:2	8.18	902	0.8	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.61	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:2	8.18	902	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:2	8.18	902	0.8	13.38	99	195	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.65	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:2	8.18	902	0.8	13.37	99	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.68	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:2	8.18	903	0.8	13.38	99	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.63	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:2	8.18	903	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.65	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:3	8.18	893	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.62	15.03	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:12:3	8.18	893	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.64	15.05	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:12:3	8.18	906	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.62	15.05	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:12:3	8.18	906	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.67	15.09	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:12:3	8.18	906	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.63	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:3	8.18	907	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.65	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:4	8.18	908	0.8	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.65	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:4	8.18	908	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.63	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:4	8.18	901	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.68	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:4	8.18	894	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.61	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:4	8.18	902	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.65	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:4	8.18	902	0.8	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.68	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:4	8.18	904	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:5	8.18	906	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:5	8.18	891	0.8	13.37	98	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.15	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:5	8.18	891	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	15.14	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:5	8.18	888	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.15	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:5	8.18	886	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	15.14	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:5	8.18	886	0.8	13.38	98	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:6	8.18	893	0.8	13.36	98	195	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.62	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:6	8.18	893	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:6	8.18	892	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.63	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:6	8.18	890	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.65	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:6	8.18	897	0.8	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:6	8.18	897	0.8	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	15.07	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:12:6	8.18	889	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:7	8.18	889	0.8	13.39	98	195	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	15.05	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:7	8.18	901	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:7	8.18	901	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:7	8.18	899	0.8	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:7	8.18	899	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:7	8.18	899	0.8	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:8	8.18	892	0.8	13.38	98	195	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:8	8.18	897	0.8	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:8	8.18	897	0.8	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.68	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:8	8.18	897	0.8	13.36	98	195	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.68	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:8	9.54	908	0.8	13.37	98	195	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.65	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:8	9.54	903	0.8	13.36	98	195	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.67	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:9	9.54	903	0.8	13.36	98	195	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.64	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:9	9.54	892	0.8	13.38	99	195	Idle	93.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:9	9.54	881	0.8	13.37	99	195	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.68	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:9	9.54	881	0.8	13.4	99	195	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.68	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:9	9.54	898	0.8	13.4	99	195	Idle	93.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.65	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:9	9.54	898	0.8	13.41	99	195	Idle	93.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.67	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:12:9	9.54	902	0.8	13.39	99	195	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.63	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:0	9.54	905	0.8	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.67	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:0	9.54	901	0.81	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:0	9.54	901	0.81	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.67	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:0	9.54	890	0.81	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:0	9.54	890	0.81	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:0	9.54	890	0.81	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:1	9.54	898	0.81	13.43	98	195	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:1	8.18	907	0.81	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.66	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:1	8.18	907	0.81	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.63	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:1	8.18	904	0.81	13.42	98	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:1	8.18	902	0.81	13.43	98	195	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.64	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:1	8.18	904	0.81	13.43	99	195	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:1	8.18	904	0.81	13.43	99	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.65	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:2	8.18	906	0.81	13.43	99	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:2	8.18	909	0.81	13.41	99	195	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.66	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:2	8.18	909	0.81	13.41	98	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:2	8.18	913	0.81	13.39	98	195	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:2	8.18	913	0.81	13.4	98	195	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.71	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:2	8.18	916	0.81	13.41	98	195	Full Load	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:3	8.18	918	0.81	13.44	98	195	Full Load	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.7	-7.7	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:3	8.18	909	0.82	13.42	98	195	Off Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.6	14.9	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:3	8.18	909	0.82	13.43	98	195	Off Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.7	-7.6	14.9	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:13:3	8.18	914	0.85	13.42	98	195	Off Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.49	14.93	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:13:3	8.18	914	0.87	13.42	98	195	Off Idle	92.7	0	2	132	944 Turbo	0.19	Lean	1	14.7	-7.42	14.98	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:13:3	6.81	932	0.89	13.42	98	195	Off Idle	92.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.28	15	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:13:4	6.81	932	0.93	13.43	98	195	Off Idle	91.1	0	2	132	944 Turbo	0.25	Lean	1	14.7	-7.13	15.04	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:13:4	6.81	927	0.96	13.42	98	195	Off Idle	90.5	0	2	132	944 Turbo	0.3	Rich	1	14.7	-6.85	15.04	1.02	4.9	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:13:4	6.81	927	0.98	13.44	98	195	Off Idle	90	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.79	15.06	1.03	5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:13:4	8.18	927	1.01	13.42	98	195	Off Idle	89.4	0	2	132	944 Turbo	0.36	Rich	1	14.7	-6.58	15.05	1.03	5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:13:4	8.18	921	1.04	13.42	99	195	Off Idle	88.9	0	2	132	944 Turbo	0.41	Rich	1	14.7	-6.4	15.06	1.03	5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:13:4	8.18	901	1.09	13.41	99	195	Off Idle	88.3	0	2	132	944 Turbo	0.5	Rich	1	14.7	-6.07	15.07	1.03	5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:13:4	8.18	901	1.13	13.42	98	195	Off Idle	87.8	0	2	132	944 Turbo	0.55	Rich	1	14.7	-5.9	15.08	1.03	5.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:5	8.18	878	1.17	13.4	98	195	Off Idle	87.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.64	15.06	1.03	5.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:5	8.18	878	1.21	13.42	98	195	Off Idle	86.6	0	2	132	944 Turbo	0.65	Rich	1	14.7	-5.43	15.07	1.03	4.9	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:5	8.18	884	1.25	13.42	99	195	Off Idle	86	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.17	15.08	1.03	4.9	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:5	8.18	884	1.3	13.42	99	195	Off Idle	85.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-4.83	15.07	1.03	4.9	4.5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:5	8.18	884	1.35	13.41	99	195	Off Idle	84.8	0	2	132	944 Turbo	0.67	Rich	1	14.7	-4.54	15.07	1.03	4.9	4.5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:5	8.18	867	1.41	13.43	99	195	Off Idle	84.8	0	2	132	944 Turbo	0.68	Rich	1	14.7	-4.15	15.08	1.03	4.9	4.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:13:6	8.18	936	1.46	13.43	99	195	Off Idle	84.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	-3.87	15.08	1.03	4.9	4.5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:6	8.18	936	1.51	13.42	99	195	Off Idle	84.7	0	2	132	944 Turbo	0.64	Rich	1	14.7	-3.48	15.07	1.03	4.9	5.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:6	8.18	925	1.55	13.41	98	195	Off Idle	84.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-3.21	15.07	1.03	4.9	5.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:6	20.45	914	1.6	13.41	98	195	Off Idle	84.7	0	2	132	944 Turbo	0.59	Rich	1	14.7	-2.9	15.06	1.03	4.7	5.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:6	20.45	936	1.63	13.42	98	195	Off Idle	84.7	0	2	132	944 Turbo	0.56	Rich	1	14.7	-2.58	15.05	1.03	4.6	5.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:6	20.45	936	1.66	13.42	98	195	Off Idle	84.7	0	2	132	944 Turbo	0.55	Rich	1	14.7	-2.28	15.04	1.02	4.6	5.8	ON	28 Pin	OFF	Removed	Disabled
03:28:13:6	20.45	936	1.69	13.44	98	195	Off Idle	84.7	0	2	132	944 Turbo	0.56	Rich	1	14.7	-2.06	15.03	1.02	4.5	5.8	ON	28 Pin	OFF	Removed	Disabled
03:28:13:7	20.45	952	1.7	13.45	98	195	Off Idle	84.8	0	2	132	944 Turbo	0.57	Rich	1	14.7	-1.93	15.03	1.02	4.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:28:13:7	20.45	984	1.72	13.45	99	195	Off Idle	84.8	0	2	132	944 Turbo	0.59	Rich	1	14.7	-1.81	15.02	1.02	4.4	5.8	ON	28 Pin	OFF	Removed	Disabled
03:28:13:7	20.45	1002	1.76	13.46	99	195	Off Idle	84.9	0	2	132	944 Turbo	0.63	Rich	1	14.7	-1.54	15.01	1.02	4.2	5.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:7	19.09	1053	1.79	13.45	99	195	Off Idle	85	0	2	132	944 Turbo	0.66	Rich	1	14.7	-1.47	15.02	1.02	4.2	5.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:7	19.09	1053	1.81	13.44	99	195	Off Idle	85	0	2	132	944 Turbo	0.7	Rich	1	14.7	-1.31	15.02	1.02	4.2	5.7	ON	28 Pin	OFF	Removed	Disabled
03:28:13:7	19.09	1072	1.82	13.44	99	195	Off Idle	85.1	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.27	15.02	1.02	4.2	5.5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:8	19.09	1072	1.84	13.43	99	195	Off Idle	85.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.19	15	1.02	4.2	5.5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:8	19.09	1084	1.85	13.44	99	195	Off Idle	85.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.14	14.98	1.02	4.2	5.5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:8	19.09	1106	1.86	13.44	99	195	Off Idle	85.4	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.19	14.98	1.02	4.3	5.5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:8	19.09	1115	1.86	13.43	98	195	Off Idle	85.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.13	15.01	1.02	4.3	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:13:8	20.45	1124	1.86	13.43	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.17	15.01	1.02	4.3	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:13:8	20.45	1124	1.86	13.42	98	195	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.14	14.99	1.02	4.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:13:9	20.45	1119	1.86	13.41	99	195	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.16	14.94	1.02	4.4	5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:9	20.45	1117	1.86	13.4	99	195	Off Idle	85.7	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.14	14.86	1.01	4.4	5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:9	20.45	1117	1.87	13.41	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.12	14.78	1.01	4.5	5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:9	20.45	1108	1.87	13.4	98	195	Off Idle	85.8	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.14	14.62	1	4.7	5	ON	28 Pin	OFF	Removed	Disabled
03:28:13:9	20.45	1098	1.87	13.4	98	195	Off Idle	85.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.06	14.5	0.99	4.7	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:13:9	20.45	1086	1.87	13.41	98	195	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.08	14.34	0.98	4.7	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:13:9	20.45	1075	1.87	13.42	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.02	14.15	0.96	4.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:14:0	20.45	1061	1.86	13.38	99	195	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.03	13.89	0.95	4.7	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:14:0	20.45	1020	1.86	13.42	99	195	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.03	13.64	0.93	4.8	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:14:0	20.45	1020	1.85	13.38	99	195	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.01	13.4	0.91	4.7	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:14:0	20.45	1014	1.85	13.38	99	195	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.02	13.16	0.9	4.7	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:14:0	20.45	1008	1.84	13.38	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.96	12.91	0.88	4.8	5.2	ON	28 Pin	OFF	Removed	Disabled
03:28:14:0	21.81	1008	1.84	13.4	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.98	12.67	0.86	4.8	5.2	ON	28 Pin	OFF	Removed	Disabled
03:28:14:1	21.81	969	1.83	13.39	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.93	12.44	0.85	4.9	5.2	ON	28 Pin	OFF	Removed	Disabled
03:28:14:1	21.81	922	1.82	13.37	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.96	12.12	0.83	5	5.2	ON	28 Pin	OFF	Removed	Disabled
03:28:14:1	21.81	922	1.82	13.36	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.88	11.89	0.81	5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:28:14:1	21.81	922	1.81	13.37	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.91	11.75	0.8	5.1	5.4	ON	28 Pin	OFF	Removed	Disabled
03:28:14:1	21.81	888	1.8	13.35	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.84	11.62	0.79	5.1	5.4	ON	28 Pin	OFF	Removed	Disabled
03:28:14:1	21.81	888	1.79	13.38	98	195	Off Idle	85.4	0	2	132	944 Turbo	0.87	Rich	1	14.7	-0.84	11.51	0.78	5.2	5.4	ON	28 Pin	OFF	Removed	Disabled
03:28:14:1	21.81	869	1.77	13.39	98	195	Off Idle	85.2	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.81	11.43	0.78	5.3	5.3	ON	28 Pin	OFF	Removed	Disabled
03:28:14:2	21.81	850	1.76	13.39	99	195	Off Idle	85.2	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.8	11.35	0.77	5.4	5.3	ON	28 Pin	OFF	Removed	Disabled
03:28:14:2	20.45	818	1.74	13.38	99	195	Off Idle	85.1	0	2	132	944 Turbo	0.87	Rich	1	14.7	-0.76	11.33	0.77	5.5	5.3	ON	28 Pin	OFF	Removed	Disabled
03:28:14:2	20.45	818	1.72	13.38	99	195	Off Idle	84.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-0.71	11.31	0.77	5.6	5.3	ON	28 Pin	OFF	Removed	Disabled
03:28:14:2	20.45	792	1.71	13.37	99	195	Off Idle	84.5	0	2	132	944 Turbo	0.87	Rich	1	14.7	-0.68	11.32	0.77	5.7	5.3	ON	28 Pin	OFF	Removed	Disabled
03:28:14:2	20.45	765	1.69	13.38	99	195	Off Idle	84.3	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.63	11.34	0.77	5.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:28:14:2	20.45	765	1.67	13.4	99	195	Off Idle	84.1	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.6	11.36	0.77	5.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:28:14:3	20.45	756	1.65	13.34	99	195	Off Idle	84	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.65	11.39	0.78	5.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:28:14:3	20.45	747	1.64	13.37	99	195	Off Idle	83.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.57	11.4	0.78	5.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:28:14:3	20.45	747	1.63	13.4	98	195	Off Idle	83.6	0	2	132	944 Turbo	0.87	Rich	1	14.7	-0.58	11.45	0.78	5.5	5.4	ON	28 Pin	OFF	Removed	Disabled
03:28:14:3	20.45	762	1.61	13.39	98	195	Off Idle	83.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.62	11.46	0.78	5.4	5.2	ON	28 Pin	OFF	Removed	Disabled
03:28:14:3	20.45	762	1.59	13.39	98	195	Off Idle	83.3	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.6	11.49	0.78	5.2	5.2	ON	28 Pin	OFF	Removed	Disabled
03:28:14:3	19.09	776	1.59	13.43	99	195	Off Idle	83.2	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.6	11.54	0.79	5.1	5.2	ON	28 Pin	OFF	Removed	Disabled
03:28:14:4	19.09	790	1.58	13.43	99	195	Off Idle	83.1	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.6	11.57	0.79	4.7	5.2	ON	28 Pin	OFF	Removed	Disabled
03:28:14:4	19.09	861	1.58	13.42	99	195	Off Idle	83.1	0	2	132	944 Turbo	0.88	Rich	1	14.7	-0.61	11.6	0.79	4.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:14:4	19.09	861	1.58	13.45	99	195	Off Idle	83	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.59	11.64	0.79	4.6	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:14:4	20.45	861	1.58	13.45	99	195	Off Idle	82.9	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.66	11.68	0.8	4.5	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:14:4	20.45	916	1.58	13.49	99	195	Off Idle	83.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.6	11.71	0.8	4.4	5.1	ON	28 Pin	OFF	Removed	Disabled
03:28:14:4	20.45	955	1.59	13.47	99	195	Off Idle	83.3	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.72	11.73	0.8	4.2	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:4	20.45	955	1.59	13.49	99	195	Off Idle	83.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.75	11.75	0.8	4.1	5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:14:5	17.72	982	1.6	13.47	99	195	Off Idle	83.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.78	11.75	0.8	4	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:5	17.72	1009	1.62	13.47	98	195	Off Idle	83.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.82	11.73	0.8	4	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:5	17.72	1057	1.63	13.42	98	195	Off Idle	83.8	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.83	11.73	0.8	4.2	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:14:5	17.72	1057	1.64	13.44	98	195	Off Idle	84	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.85	11.7	0.8	4.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:14:5	19.09	1036	1.66	13.41	99	195	Off Idle	84.2	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.86	11.65	0.79	4.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:14:5	19.09	1034	1.67	13.42	99	195	Off Idle	84.3	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.87	11.6	0.79	4.6	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:14:6	19.09	1034	1.69	13.41	99	195	Off Idle	84.5	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.81	11.5	0.78	4.6	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:6	19.09	1030	1.71	13.42	99	195	Off Idle	84.7	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.85	11.43	0.78	4.6	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:6	19.09	1027	1.73	13.41	99	195	Off Idle	84.9	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.77	11.35	0.77	4.6	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:6	19.09	1024	1.74	13.41	99	195	Off Idle	85.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.8	11.28	0.77	4.6	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:6	19.09	1024	1.76	13.42	99	195	Off Idle	85.3	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.74	11.19	0.76	4.6	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:6	20.45	1038	1.77	13.41	99	195	Off Idle	85.5	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.77	11.14	0.76	4.6	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:6	20.45	1056	1.78	13.42	99	195	Off Idle	85.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.75	11.07	0.75	4.6	5	ON	28 Pin	OFF	Removed	Disabled
03:28:14:7	20.45	1056	1.79	13.4	99	195	Off Idle	85.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.75	10.99	0.75	4.5	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:14:7	20.45	1056	1.8	13.44	99	195	Off Idle	85.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.85	10.93	0.74	4.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:14:7	20.45	1087	1.81	13.42	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.81	10.88	0.74	4.3	4.9	ON	28 Pin	OFF	Removed	Disabled
03:28:14:7	20.45	1128	1.81	13.43	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.91	10.84	0.74	4.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:28:14:7	20.45	1128	1.82	13.42	98	195	Off Idle	85.7	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.85	10.8	0.74	4.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:28:14:7	20.45	1132	1.83	13.42	99	195	Off Idle	85.7	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.9	10.77	0.73	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:28:14:8	20.45	1160	1.84	13.43	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.91	10.74	0.73	4.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:28:14:8	20.45	1160	1.84	13.43	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.88	10.71	0.73	4.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:28:14:8	20.45	1182	1.85	13.44	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.89	10.7	0.73	4.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:28:14:8	20.45	1182	1.85	13.44	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.91	10.68	0.73	4.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:28:14:8	20.45	1193	1.86	13.44	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.9	Rich	1	14.7	-0.94	10.68	0.73	4.3	4.7	ON	28 Pin	OFF	Removed	Disabled
03:28:14:8	20.45	1219	1.87	13.43	99	195	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.92	10.69	0.73	4.2	4.7	ON	28 Pin	OFF	Removed	Disabled
03:28:14:9	20.45	1256	1.87	13.43	99	195	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.94	10.71	0.73	4.2	4.7	ON	28 Pin	OFF	Removed	Disabled
03:28:14:9	20.45	1256	1.89	13.43	99	195	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.97	10.72	0.73	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:28:14:9	21.81	1260	1.9	13.41	99	195	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.7	-0.99	10.72	0.73	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:28:14:9	21.81	1264	1.91	13.42	99	195	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1	10.75	0.73	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:28:14:9	21.81	1269	1.91	13.42	99	195	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.03	10.77	0.73	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:28:14:9	21.81	1272	1.92	13.44	99	195	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.06	10.78	0.73	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:28:14:9	21.81	1282	1.93	13.44	99	195	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.07	10.79	0.73	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:28:15:0	21.81	1290	1.94	13.43	99	195	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.03	10.8	0.74	4.4	4.7	ON	28 Pin	OFF	Removed	Disabled
03:28:15:0	21.81	1298	1.95	13.43	99	195	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.02	10.82	0.74	4.3	4.7	ON	28 Pin	OFF	Removed	Disabled
03:28:15:0	21.81	1312	1.96	13.43	99	195	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.07	10.83	0.74	4.3	4.7	ON	28 Pin	OFF	Removed	Disabled
03:28:15:0	21.81	1317	1.97	13.41	99	195	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.02	10.84	0.74	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:28:15:0	21.81	1321	1.98	13.42	99	195	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.04	10.86	0.74	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:28:15:0	21.81	1338	1.99	13.4	99	195	Off Idle	86.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.02	10.89	0.74	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:28:15:1	21.81	1354	2	13.41	99	195	Off Idle	86.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.08	10.92	0.74	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:28:15:1	21.81	1354	2	13.42	99	195	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.05	10.93	0.74	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:28:15:1	21.81	1364	2.01	13.42	99	195	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.12	10.96	0.75	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:28:15:1	21.81	1402	2.02	13.42	99	195	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.16	11.03	0.75	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:1	23.18	1402	2.02	13.41	99	195	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.12	11.05	0.75	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:1	23.18	1410	2.03	13.43	99	195	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.17	11.14	0.76	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:28:15:1	23.18	1428	2.04	13.43	99	195	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.23	11.21	0.76	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:28:15:2	23.18	1457	2.04	13.43	99	195	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.23	11.28	0.77	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:28:15:2	23.18	1476	2.05	13.42	99	195	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.25	11.39	0.78	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:2	24.54	1476	2.06	13.42	99	195	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.27	11.47	0.78	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:2	24.54	1482	2.07	13.42	99	195	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.28	11.61	0.79	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:2	24.54	1512	2.08	13.41	99	195	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.29	11.7	0.8	4.1	4.4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:2	24.54	1512	2.09	13.43	99	195	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.3	11.75	0.8	4.2	4.4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:3	24.54	1523	2.09	13.44	99	195	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.28	11.89	0.81	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:15:3	24.54	1529	2.1	13.43	99	195	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.27	11.97	0.82	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:15:3	24.54	1542	2.11	13.41	99	195	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.3	12.07	0.82	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:15:3	25.9	1555	2.12	13.42	99	195	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.29	12.17	0.83	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:15:3	25.9	1560	2.13	13.41	99	195	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.31	12.28	0.84	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:15:3	25.9	1560	2.13	13.42	99	195	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.32	12.38	0.84	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:15:4	25.9	1573	2.14	13.41	99	195	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.32	12.5	0.85	4	4.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:15:4	25.9	1586	2.14	13.42	99	195	Off Idle	86.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.32	12.67	0.86	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:15:4	25.9	1593	2.15	13.41	99	195	Off Idle	86.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.29	12.77	0.87	4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:15:4	25.9	1599	2.16	13.41	99	195	Off Idle	86.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.32	12.88	0.88	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:4	25.9	1628	2.16	13.42	99	195	Off Idle	86.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.35	12.98	0.88	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:4	25.9	1633	2.17	13.42	98	195	Off Idle	86.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.35	13.08	0.89	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:4	25.9	1633	2.18	13.41	98	195	Off Idle	86.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.35	13.18	0.9	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:5	25.9	1654	2.18	13.4	98	195	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.37	13.25	0.9	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:5	25.9	1662	2.19	13.42	99	195	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.43	13.36	0.91	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:5	25.9	1668	2.2	13.41	99	195	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.4	13.42	0.91	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:5	25.9	1689	2.21	13.4	99	195	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.42	13.48	0.92	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:5	25.9	1701	2.21	13.42	99	195	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.44	13.53	0.92	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:5	25.9	1707	2.22	13.42	99	195	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.44	13.58	0.93	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:6	27.27	1727	2.23	13.41	99	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.47	13.66	0.93	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:6	27.27	1741	2.23	13.43	99	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.49	13.69	0.93	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:6	27.27	1756	2.24	13.41	99	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.44	13.74	0.94	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:6	27.27	1756	2.25	13.41	99	195	Off Idle	86.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.46	13.8	0.94	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:6	27.27	1786	2.26	13.39	99	195	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.45	13.84	0.94	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:6	27.27	1800	2.27	13.4	99	195	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.42	13.89	0.95	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:6	27.27	1800	2.28	13.4	99	195	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.4	13.91	0.95	3.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:7	27.27	1822	2.29	13.4	99	195	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.42	13.95	0.95	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:7	27.27	1829	2.3	13.41	99	195	Off Idle	86.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.43	13.97	0.95	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:7	27.27	1855	2.3	13.42	99	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.43	13.98	0.95	3.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:7	27.27	1855	2.31	13.43	99	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.45	13.97	0.95	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:7	27.27	1870	2.32	13.43	99	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.43	13.98	0.95	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:15:7	27.27	1899	2.33	13.41	99	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.39	13.96	0.95	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:8	27.27	1899	2.34	13.41	99	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.39	13.94	0.95	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:8	27.27	1907	2.35	13.4	99	195	Off Idle	86.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.39	13.92	0.95	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:8	28.63	1914	2.35	13.39	99	195	Off Idle	86.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.43	13.9	0.95	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:8	28.63	1914	2.36	13.4	99	195	Off Idle	86.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.46	13.89	0.95	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:8	28.63	1930	2.37	13.4	99	195	Off Idle	86.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.49	13.87	0.94	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:8	28.63	1942	2.38	13.41	99	195	Off Idle	86.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.52	13.84	0.94	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:9	28.63	1960	2.38	13.42	99	195	Off Idle	86	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.52	13.82	0.94	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:9	28.63	1960	2.39	13.43	99	195	Off Idle	86	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.53	13.82	0.94	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:9	28.63	1976	2.4	13.44	99	195	Off Idle	86	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.52	13.81	0.94	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:9	28.63	1995	2.4	13.45	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.51	13.79	0.94	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:9	28.63	1995	2.41	13.45	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.51	13.77	0.94	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:15:9	28.63	2012	2.41	13.44	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.54	13.76	0.94	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:15:9	28.63	2027	2.42	13.45	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.54	13.71	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:0	28.63	2040	2.42	13.45	99	195	Off Idle	85.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.59	13.68	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:0	28.63	2049	2.43	13.44	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.63	13.68	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:0	28.63	2068	2.43	13.42	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.64	13.67	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:0	28.63	2088	2.44	13.42	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.64	13.63	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:0	28.63	2088	2.44	13.4	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.64	13.63	0.93	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:0	29.99	2123	2.45	13.38	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.64	13.64	0.93	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:1	29.99	2127	2.46	13.37	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.57	13.65	0.93	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:1	29.99	2139	2.46	13.37	99	195	Off Idle	85.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.54	13.66	0.93	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:1	29.99	2146	2.47	13.37	99	195	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.52	13.71	0.93	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:1	29.99	2178	2.47	13.37	99	195	Off Idle	85.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.46	13.74	0.94	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:1	29.99	2174	2.47	13.38	99	195	Off Idle	85.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.48	13.76	0.94	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:1	29.99	2179	2.48	13.4	99	195	Off Idle	85.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.52	13.77	0.94	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:1	29.99	2197	2.48	13.4	99	195	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.54	13.8	0.94	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:2	29.99	2209	2.49	13.39	99	195	Off Idle	85.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.58	13.84	0.94	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:2	29.99	2214	2.5	13.39	99	195	Off Idle	85.1	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.6	13.86	0.94	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:2	29.99	2226	2.5	13.4	99	195	Off Idle	84.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.59	13.88	0.95	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:2	29.99	2250	2.51	13.39	99	195	Off Idle	84.9	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.59	13.91	0.95	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:2	29.99	2262	2.52	13.39	99	195	Off Idle	84.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.57	13.92	0.95	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:2	29.99	2262	2.52	13.4	99	195	Off Idle	84.3	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.61	13.94	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:3	29.99	2283	2.53	13.4	99	195	Off Idle	83.6	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.63	13.97	0.95	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:16:3	29.99	2292	2.54	13.41	99	195	Off Idle	83.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.64	14	0.95	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:3	29.99	2298	2.55	13.43	99	195	Off Idle	82.7	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.69	14.05	0.96	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:3	31.36	2340	2.55	13.43	99	195	Off Idle	82.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.69	14.09	0.96	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:3	31.36	2340	2.56	13.43	99	195	Off Idle	82.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.68	14.1	0.96	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:3	31.36	2340	2.57	13.43	99	195	Off Idle	80.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.67	14.14	0.96	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:4	31.36	2360	2.57	13.43	99	195	Off Idle	80	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.71	14.16	0.96	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:4	31.36	2376	2.58	13.41	99	195	Off Idle	79.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.67	14.18	0.97	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:4	31.36	2374	2.59	13.41	99	195	Off Idle	78.7	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.68	14.21	0.97	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:4	31.36	2377	2.59	13.41	99	195	Off Idle	78.1	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.7	14.24	0.97	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:4	31.36	2383	2.6	13.41	99	195	Off Idle	77.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.65	14.26	0.97	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:4	31.36	2385	2.61	13.41	99	195	Off Idle	76.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.66	14.28	0.97	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:4	31.36	2385	2.61	13.43	99	195	Off Idle	76.1	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.65	14.31	0.97	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:5	31.36	2386	2.62	13.43	99	195	Off Idle	75.5	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.65	14.37	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:5	31.36	2386	2.62	13.42	99	195	Off Idle	74.9	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.62	14.39	0.98	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:5	31.36	2388	2.63	13.42	99	195	Off Idle	74.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.64	14.47	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:5	31.36	2388	2.64	13.42	99	195	Off Idle	74	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.66	14.5	0.99	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:5	31.36	2394	2.64	13.43	99	195	Off Idle	73.6	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.64	14.56	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:5	31.36	2394	2.64	13.43	99	195	Off Idle	73.3	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.62	14.58	0.99	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:16:6	31.36	2411	2.65	13.41	99	195	Off Idle	73	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.61	14.61	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:6	31.36	2421	2.65	13.43	99	195	Off Idle	72.9	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.57	14.66	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:6	31.36	2455	2.66	13.42	99	195	Off Idle	72.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.58	14.69	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:6	31.36	2467	2.66	13.42	99	195	Off Idle	72.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.62	14.7	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:6	31.36	2476	2.66	13.42	99	195	Off Idle	72.2	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.62	14.7	1	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:6	31.36	2506	2.67	13.42	99	195	Off Idle	71.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.68	14.72	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:6	31.36	2532	2.67	13.41	99	195	Off Idle	71.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.71	14.72	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:7	31.36	2532	2.68	13.43	99	195	Off Idle	70.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.7	14.73	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:7	31.36	2557	2.68	13.42	99	195	Off Idle	70.1	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.7	14.74	1	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:7	31.36	2577	2.68	13.43	99	195	Off Idle	69.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.69	14.78	1.01	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:7	31.36	2593	2.69	13.43	99	195	Off Idle	69.1	0	2	132	944 Turbo	0.69	Rich	1	14.7	-1.75	14.75	1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:16:7	31.36	2675	2.69	13.41	99	195	Off Idle	68.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-1.77	14.75	1	3.4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:16:7	32.72	2649	2.7	13.41	99	195	Off Idle	67.6	0	2	132	944 Turbo	0.66	Rich	1	14.7	-1.81	14.76	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:8	32.72	2633	2.7	13.41	99	195	Off Idle	66.9	0	2	132	944 Turbo	0.65	Rich	1	14.7	-1.79	14.77	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:16:8	32.72	2633	2.71	13.41	99	195	Off Idle	66	0	2	132	944 Turbo	0.62	Rich	1	14.7	-1.82	14.78	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:16:8	32.72	2645	2.71	13.41	99	195	Off Idle	65.1	0	2	132	944 Turbo	0.6	Rich	1	14.7	-1.79	14.79	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:16:8	32.72	2657	2.72	13.43	99	195	Off Idle	64.2	0	2	132	944 Turbo	0.56	Rich	1	14.7	-1.79	14.79	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:8	32.72	2657	2.73	13.43	99	195	Off Idle	62.7	0	2	132	944 Turbo	0.51	Rich	1	14.7	-1.79	14.81	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:16:8	32.72	2663	2.74	13.43	99	195	Off Idle	62	0	2	132	944 Turbo	0.46	Rich	1	14.7	-1.8	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:9	32.72	2670	2.74	13.41	99	195	Off Idle	61.2	0	2	132	944 Turbo	0.39	Rich	1	14.7	-1.83	14.83	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:9	32.72	2670	2.75	13.42	99	195	Off Idle	60.6	0	2	132	944 Turbo	0.34	Rich	1	14.7	-1.82	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:9	31.36	2692	2.76	13.42	99	195	Off Idle	60	0	2	132	944 Turbo	0.28	Rich	1	14.7	-1.76	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:9	31.36	2707	2.76	13.41	99	195	Off Idle	59.5	0	2	132	944 Turbo	0.23	Rich	1	14.7	-1.72	15.03	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:9	31.36	2718	2.77	13.42	99	195	Off Idle	58.9	0	2	132	944 Turbo	0.19	Rich	1	14.7	-1.74	15.08	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:9	31.36	2718	2.77	13.43	99	195	Off Idle	58.2	0	2	132	944 Turbo	0.15	Lean	1	14.7	-1.73	15.14	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:16:9	32.72	2750	2.78	13.41	99	195	Off Idle	57.6	0	2	132	944 Turbo	0.13	Lean	1	14.7	-1.65	15.21	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:0	32.72	2733	2.79	13.41	99	195	Off Idle	57.1	0	2	132	944 Turbo	0.13	Lean	1	14.7	-1.7	15.28	1.04	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:0	32.72	2736	2.79	13.42	99	195	Off Idle	56.7	0	2	132	944 Turbo	0.14	Lean	1	14.7	-1.7	15.31	1.04	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:0	32.72	2748	2.79	13.42	99	195	Off Idle	55.9	0	2	132	944 Turbo	0.17	Lean	1	14.7	-1.67	15.33	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:0	32.72	2757	2.8	13.42	99	195	Off Idle	55.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-1.68	15.34	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:17:0	32.72	2760	2.8	13.43	99	195	Off Idle	55.4	0	2	132	944 Turbo	0.24	Lean	1	14.7	-1.67	15.33	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:0	32.72	2770	2.81	13.44	99	195	Off Idle	54.6	0	2	132	944 Turbo	0.32	Lean	1	14.7	-1.64	15.33	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:17:1	32.72	2784	2.81	13.42	99	195	Off Idle	54.3	0	2	132	944 Turbo	0.38	Lean	1	14.7	-1.66	15.34	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:17:1	32.72	2794	2.81	13.41	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.44	Lean	1	14.7	-1.63	15.32	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:17:1	32.72	2810	2.82	13.43	99	195	Off Idle	53.4	0	2	132	944 Turbo	0.47	Lean	1	14.7	-1.63	15.28	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:17:1	32.72	2813	2.82	13.42	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.48	Lean	1	14.7	-1.64	15.22	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:1	32.72	2836	2.82	13.41	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.47	Lean	1	14.7	-1.68	15.14	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:1	32.72	2836	2.83	13.41	99	195	Off Idle	51.6	0	2	132	944 Turbo	0.44	Lean	1	14.7	-1.71	15.09	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:1	32.72	2873	2.83	13.4	99	195	Off Idle	51.3	0	2	132	944 Turbo	0.41	Lean	1	14.7	-1.68	15.02	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:2	32.72	2884	2.83	13.41	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.36	Lean	1	14.7	-1.72	14.98	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:17:2	32.72	2893	2.84	13.41	99	195	Off Idle	50.3	0	2	132	944 Turbo	0.31	Lean	1	14.7	-1.72	14.96	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:2	32.72	2896	2.84	13.44	99	195	Off Idle	49.1	0	2	132	944 Turbo	0.22	Lean	1	14.7	-1.72	14.95	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:2	32.72	2916	2.84	13.44	99	195	Off Idle	49.1	0	2	132	944 Turbo	0.19	Lean	1	14.7	-1.72	14.96	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:17:2	32.72	2951	2.85	13.42	99	195	Off Idle	47.9	0	2	132	944 Turbo	0.12	Lean	1	14.7	-1.73	14.99	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:17:2	32.72	2957	2.85	13.43	99	195	Off Idle	47.4	0	2	132	944 Turbo	0.1	Lean	1	14.7	-1.77	15.03	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:17:3	32.72	2964	2.86	13.43	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.11	Lean	1	14.7	-1.75	15.08	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:3	32.72	2982	2.86	13.41	99	195	Off Idle	46	0	2	132	944 Turbo	0.17	Lean	1	14.7	-1.79	15.13	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:3	34.08	3051	2.86	13.41	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.22	Lean	1	14.7	-1.76	15.18	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:3	34.08	3015	2.87	13.43	99	195	Off Idle	44.9	0	2	132	944 Turbo	0.28	Lean	1	14.7	-1.84	15.21	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:3	34.08	3020	2.87	13.41	99	195	Off Idle	44.4	0	2	132	944 Turbo	0.34	Lean	1	14.7	-1.86	15.26	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:3	34.08	3032	2.88	13.4	99	195	Off Idle	44	0	2	132	944 Turbo	0.41	Lean	1	14.7	-1.89	15.26	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:4	34.08	3036	2.88	13.42	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.44	Lean	1	14.7	-1.87	15.23	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:4	34.08	3041	2.89	13.43	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.5	Lean	1	14.7	-1.96	15.17	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:4	34.08	3040	2.89	13.42	99	195	Off Idle	42.7	0	2	132	944 Turbo	0.54	Rich	1	14.7	-1.93	15.13	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:4	34.08	3046	2.9	13.43	99	195	Off Idle	42.5	0	2	132	944 Turbo	0.56	Rich	1	14.7	-1.92	15.08	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:4	34.08	3046	2.9	13.42	99	195	Off Idle	42.2	0	2	132	944 Turbo	0.56	Rich	1	14.7	-1.92	15.03	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:4	34.08	3046	2.91	13.42	99	196	Off Idle	42	0	2	132	944 Turbo	0.52	Rich	1	14.7	-1.94	15.01	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:4	34.08	3050	2.91	13.43	99	196	Off Idle	41.8	0	2	132	944 Turbo	0.47	Rich	1	14.7	-1.93	14.97	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:5	34.08	3057	2.91	13.43	99	196	Off Idle	41.7	0	2	132	944 Turbo	0.38	Rich	1	14.7	-1.92	14.89	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:17:5	34.08	3058	2.92	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.7	-1.9	14.87	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:17:5	34.08	3071	2.92	13.42	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.7	-1.9	14.9	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:17:5	34.08	3084	2.92	13.42	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.2	Rich	1	14.7	-1.92	14.95	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:17:5	34.08	3097	2.92	13.41	99	196	Off Idle	41.3	0	2	132	944 Turbo	0.16	Rich	1	14.7	-1.96	14.99	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:17:5	34.08	3102	2.92	13.42	99	196	Off Idle	41.3	0	2	132	944 Turbo	0.15	Lean	1	14.7	-2	15.04	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:6	34.08	3146	2.92	13.41	99	196	Off Idle	41.3	0	2	132	944 Turbo	0.17	Lean	1	14.7	-2.02	15.08	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:6	34.08	3148	2.93	13.42	99	196	Off Idle	41.3	0	2	132	944 Turbo	0.22	Lean	1	14.7	-2.11	15.1	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:17:6	34.08	3152	2.93	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.28	Lean	1	14.7	-2.12	15.14	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:6	34.08	3174	2.93	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.17	15.21	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:6	34.08	3181	2.93	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.4	Lean	1	14.7	-2.23	15.25	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:17:6	34.08	3197	2.93	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.28	15.25	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:17:6	34.08	3192	2.93	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.53	Lean	1	14.7	-2.29	15.19	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:17:7	34.08	3205	2.93	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.6	Lean	1	14.7	-2.34	15.13	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:17:7	34.08	3207	2.93	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Lean	1	14.7	-2.32	15.05	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:17:7	34.08	3210	2.93	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.7	-2.41	15	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:17:7	34.08	3210	2.93	13.42	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.58	Lean	1	14.7	-2.35	14.96	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:17:7	34.08	3216	2.93	13.42	99	196	Off Idle	41.3	0	2	132	944 Turbo	0.53	Lean	1	14.7	-2.45	14.92	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:7	34.08	3218	2.93	13.42	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.42	14.85	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:8	34.08	3216	2.93	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.7	-2.43	14.8	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:8	34.08	3220	2.93	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.41	14.77	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:8	34.08	3232	2.93	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-2.41	14.79	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:8	34.08	3239	2.93	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-2.36	14.83	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:8	34.08	3268	2.93	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-2.36	14.91	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:8	34.08	3294	2.93	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-2.38	14.98	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:17:9	34.08	3319	2.93	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.7	-2.4	15.08	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:9	34.08	3324	2.93	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.7	-2.48	15.11	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:9	34.08	3381	2.93	13.44	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-2.48	15.2	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:9	34.08	3365	2.93	13.43	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-2.52	15.28	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:9	34.08	3366	2.93	13.43	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-2.64	15.3	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:17:9	34.08	3386	2.93	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-2.58	15.33	1.04	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:17:9	34.08	3392	2.94	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	-2.54	15.34	1.05	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:18:0	34.08	3392	2.94	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-2.65	15.33	1.04	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:18:0	34.08	3400	2.94	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	-2.69	15.11	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:18:0	34.08	3401	2.94	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	-2.66	15.06	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:18:0	34.08	3401	2.94	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-2.72	15	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:18:0	34.08	3396	2.94	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-2.83	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:18:0	34.08	3392	2.94	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-2.77	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:18:1	34.08	3394	2.94	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.7	-2.79	14.82	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:18:1	34.08	3396	2.94	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.7	-2.9	14.77	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:18:1	34.08	3404	2.93	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.7	-2.93	14.71	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:18:1	34.08	3413	2.93	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.7	-2.9	14.68	1	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:18:1	34.08	3417	2.93	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.7	-3.03	14.86	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:18:1	35.45	3444	2.93	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Rich	1	14.7	-3.1	14.89	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:18:1	35.45	3445	2.93	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Rich	1	14.7	-3.05	14.92	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:18:2	35.45	3450	2.93	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-3.1	14.98	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:18:2	35.45	3456	2.92	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.28	15.08	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:18:2	35.45	3472	2.92	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.3	15.14	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:18:2	34.08	3480	2.91	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.43	15.18	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:18:2	34.08	3480	2.9	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.69	15.24	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:18:2	34.08	3492	2.89	13.44	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.87	15.28	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:18:3	35.45	3500	2.87	13.44	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.1	15.28	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:28:18:3	35.45	3500	2.84	13.42	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-4.48	15.27	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:18:3	35.45	3496	2.78	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.02	15.24	1.04	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:28:18:3	35.45	3484	2.73	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-5.58	15.21	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:18:3	36.81	3508	2.68	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.27	15.17	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:18:3	36.81	3468	2.62	13.41	99	195	Full Load	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.99	15.15	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:28:18:4	36.81	3440	2.56	13.44	99	195	Idle	41.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.58	15.15	1.03	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:4	36.81	3433	2.49	13.42	99	195	Idle	41.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.04	15.15	1.03	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:4	36.81	3382	2.4	13.44	99	195	Idle	41.3	0	2	132	944 Turbo	0.63	Rich	1	14.7	-8.58	15.09	1.03	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:28:18:4	34.08	3308	2.35	13.43	99	195	Idle	41.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.76	15.05	1.03	3.7	1.3	ON	28 Pin	OFF	Removed	Disabled
03:28:18:4	28.63	3276	2.32	13.42	99	195	Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.96	15	1.02	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:4	23.18	3244	2.26	13.42	99	196	Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.08	14.92	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:4	20.45	3281	2.19	13.43	99	196	Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.13	14.83	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:5	20.45	3260	2.1	13.43	99	195	Idle	41.4	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.18	14.68	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:5	20.45	3222	2.04	13.43	99	195	Idle	41.4	0	2	132	944 Turbo	0.75	Lean	1	14.6	-9.23	14.56	0.99	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:5	20.45	3202	1.95	13.44	99	195	Idle	41	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.2	14.42	0.98	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:5	20.45	3166	1.9	13.43	99	195	Idle	40.7	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.23	14.22	0.97	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:5	20.45	3143	1.85	13.44	99	195	Idle	40.1	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.25	14.11	0.96	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:5	20.45	3110	1.81	13.43	99	195	Idle	39.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.24	14.04	0.96	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:6	20.45	3106	1.78	13.43	99	195	Idle	38.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.28	14.04	0.96	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:6	20.45	3065	1.76	13.42	99	195	Idle	37.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.28	14.07	0.96	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:6	20.45	3065	1.73	13.43	99	195	Idle	36.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.25	14.12	0.96	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:6	20.45	3024	1.72	13.43	99	195	Idle	35.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.26	14.23	0.97	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:6	20.45	2984	1.72	13.44	99	195	Idle	34.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.19	14.41	0.98	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:6	20.45	2984	1.72	13.44	99	195	Idle	33.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.16	14.63	1	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:6	19.09	2932	1.73	13.45	99	195	Idle	32.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.06	14.87	1.01	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:7	19.09	2898	1.74	13.45	99	195	Idle	32.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.04	15.15	1.03	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:7	19.09	2901	1.75	13.44	99	195	Idle	30.5	0	2	132	944 Turbo	0.04	Lean	1	14.7	-8.99	15.72	1.07	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:7	19.09	2871	1.75	13.45	99	195	Idle	29.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.91	15.97	1.09	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:7	19.09	2820	1.76	13.44	99	195	Idle	28.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.92	16.24	1.11	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:7	19.09	2822	1.76	13.45	99	195	Idle	28.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.88	16.38	1.12	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:7	19.09	2798	1.78	13.44	99	195	Idle	27.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.83	16.76	1.14	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:8	19.09	2776	1.79	13.43	99	195	Idle	27	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.8	17	1.16	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:8	19.09	2767	1.8	13.43	99	195	Idle	26.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.77	17.31	1.18	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:8	19.09	2714	1.81	13.42	99	195	Idle	26.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.72	17.85	1.22	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:8	19.09	2701	1.81	13.44	99	195	Idle	26.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.71	18.2	1.24	3.7	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:8	19.09	2675	1.81	13.42	99	195	Idle	26.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.68	18.56	1.26	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:8	19.09	2656	1.81	13.41	99	195	Idle	27.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.63	18.89	1.29	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:9	19.09	2641	1.81	13.42	99	195	Idle	27.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	19.05	1.3	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:9	19.09	2609	1.81	13.42	99	195	Idle	28.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	19.49	1.33	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:9	19.09	2591	1.82	13.42	99	195	Idle	28.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.63	19.76	1.35	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:9	19.09	2575	1.82	13.42	99	195	Idle	30.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.62	20.07	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:9	19.09	2542	1.82	13.42	99	195	Idle	31.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.62	20.18	1.37	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:9	19.09	2508	1.82	13.44	99	195	Idle	32.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:18:9	19.09	2508	1.82	13.44	99	195	Idle	33.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.62	20.21	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:0	19.09	2457	1.81	13.43	99	195	Idle	34.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.61	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:0	19.09	2458	1.81	13.43	99	195	Idle	35.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.6	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:19:0	19.09	2450	1.81	13.44	99	195	Idle	36.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.61	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:0	19.09	2404	1.8	13.44	99	195	Idle	36.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.61	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:0	19.09	2387	1.8	13.42	99	195	Idle	38.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.6	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:0	19.09	2379	1.78	13.42	99	195	Full Load	40.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.64	20.19	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:1	19.09	2352	1.77	13.41	99	195	Off Idle	42.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.64	20.2	1.38	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:1	19.09	2317	1.76	13.41	99	195	Off Idle	43.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.65	20.21	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:28:19:1	9.54	2183	1.76	13.42	99	195	Off Idle	44.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.64	20.22	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:28:19:1	9.54	2222	1.75	13.41	99	195	Off Idle	46.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.56	20.23	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:1	12.27	2279	1.75	13.42	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.5	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:1	12.27	2235	1.75	13.43	99	195	Off Idle	51.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.41	20.23	1.38	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:19:1	14.99	2235	1.76	13.41	99	195	Off Idle	54.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.29	20.23	1.38	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:19:2	17.72	2182	1.77	13.41	99	195	Off Idle	56.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.06	20.24	1.38	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:19:2	17.72	2148	1.78	13.41	99	195	Off Idle	59.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.83	20.24	1.38	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:19:2	20.45	2148	1.81	13.42	99	195	Off Idle	62.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.39	20.23	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:28:19:2	20.45	2090	1.83	13.42	99	195	Off Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.06	20.24	1.38	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:2	23.18	2022	1.85	13.44	99	195	Off Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.75	20.23	1.38	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:2	23.18	2006	1.87	13.46	99	195	Off Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.7	-6.45	20.24	1.38	3.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:3	25.9	2005	1.89	13.45	99	195	Off Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-6.18	20.25	1.38	3.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:3	25.9	2007	1.9	13.44	99	195	Off Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-5.89	20.25	1.38	3.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:3	28.63	2027	1.92	13.42	99	195	Off Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-5.72	20.25	1.38	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:3	29.99	2027	1.94	13.4	99	195	Off Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.7	-5.47	20.25	1.38	3.7	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:3	29.99	2030	1.99	13.38	99	195	Off Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-5.23	20.25	1.38	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:3	29.99	2071	2	13.39	99	196	Off Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.7	-4.94	20.25	1.38	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:19:4	29.99	2071	2.04	13.4	99	196	Off Idle	84.5	0	2	132	944 Turbo	0.03	Lean	1	14.7	-4.54	20.25	1.38	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:19:4	29.99	2094	2.11	13.4	99	196	Off Idle	84.9	0	2	132	944 Turbo	0.04	Lean	1	14.7	-4.09	20.25	1.38	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:4	29.99	2110	2.15	13.41	99	195	Off Idle	85.4	0	2	132	944 Turbo	0.04	Lean	1	14.7	-3.78	20.25	1.38	3.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:4	31.36	2148	2.19	13.43	99	195	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.7	-3.55	20.25	1.38	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:4	31.36	2136	2.23	13.44	99	195	Off Idle	85.7	0	2	132	944 Turbo	0.05	Lean	1	14.7	-3.36	20.25	1.38	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:4	31.36	2118	2.26	13.44	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.06	Lean	1	14.7	-3.2	20.25	1.38	3.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:4	31.36	2108	2.3	13.43	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.06	Lean	1	14.7	-3.01	20.26	1.38	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:5	31.36	2108	2.3	13.43	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.06	Lean	1	14.7	-2.97	20.18	1.37	3.5	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:5	31.36	2084	2.34	13.42	99	195	Off Idle	85.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-2.82	19.84	1.35	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:19:5	29.99	2086	2.36	13.41	99	195	Off Idle	85.6	0	2	132	944 Turbo	0.15	Lean	1	14.7	-2.74	19.51	1.33	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:19:5	29.99	2077	2.37	13.41	99	195	Off Idle	85.6	0	2	132	944 Turbo	0.21	Lean	1	14.7	-2.68	19.14	1.3	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:19:5	29.99	2076	2.37	13.4	99	195	Off Idle	85.6	0	2	132	944 Turbo	0.27	Lean	1	14.7	-2.65	18.74	1.28	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:19:5	29.99	2073	2.38	13.4	99	195	Off Idle	85.5	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.58	18.29	1.25	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:19:6	29.99	2073	2.39	13.39	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.42	Rich	1	14.7	-2.55	17.85	1.22	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:19:6	29.99	2076	2.41	13.38	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.52	Rich	1	14.7	-2.46	17.13	1.17	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:19:6	29.99	2092	2.42	13.37	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-2.41	16.67	1.14	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:19:6	29.99	2108	2.43	13.37	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-2.37	16.23	1.11	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:19:6	29.99	2108	2.44	13.37	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.7	-2.35	15.9	1.08	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:6	29.99	2124	2.44	13.38	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.37	15.48	1.05	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:6	29.99	2141	2.44	13.39	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.38	15.22	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:7	29.99	2143	2.43	13.41	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.41	14.98	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:7	29.99	2142	2.43	13.42	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.46	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:7	29.99	2144	2.42	13.41	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.49	14.58	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:7	29.99	2140	2.42	13.41	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.49	14.41	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:7	29.99	2140	2.42	13.39	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.51	14.24	0.97	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:7	29.99	2144	2.42	13.37	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.43	14.09	0.96	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:8	29.99	2137	2.42	13.37	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.46	14	0.95	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:8	29.99	2137	2.42	13.4	99	195	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.37	13.91	0.95	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:8	29.99	2140	2.42	13.41	99	195	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.38	13.9	0.95	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:8	29.99	2130	2.42	13.42	99	195	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.41	13.91	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:8	29.99	2140	2.42	13.44	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.41	13.92	0.95	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:19:8	29.99	2156	2.42	13.44	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.42	13.93	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:9	29.99	2174	2.42	13.44	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.44	13.94	0.95	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:9	29.99	2194	2.42	13.45	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.47	13.95	0.95	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:9	29.99	2185	2.42	13.45	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.45	13.94	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:19:9	29.99	2190	2.42	13.45	99	196	Off Idle	85.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.48	13.95	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:9	29.99	2200	2.43	13.44	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.5	13.96	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:9	29.99	2217	2.43	13.43	99	196	Off Idle	85	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.49	13.96	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:19:9	31.36	2217	2.43	13.41	99	196	Off Idle	84.9	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.47	13.96	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:0	31.36	2201	2.43	13.41	99	196	Off Idle	84.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.45	13.97	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:0	31.36	2201	2.44	13.42	99	196	Off Idle	84.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.47	13.97	0.95	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:20:0	31.36	2202	2.44	13.41	99	196	Off Idle	84.4	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.46	13.99	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:0	31.36	2224	2.44	13.42	99	195	Off Idle	84.3	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.46	14	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:0	31.36	2214	2.44	13.42	98	195	Off Idle	84.1	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.46	14.02	0.95	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:0	31.36	2218	2.44	13.41	98	195	Off Idle	84	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.47	14.01	0.95	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:1	31.36	2220	2.45	13.39	98	196	Off Idle	83.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.48	14	0.95	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:1	31.36	2227	2.45	13.39	99	196	Off Idle	83.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.46	14	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:1	31.36	2229	2.45	13.4	99	196	Off Idle	83	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.44	14	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:1	31.36	2237	2.45	13.39	99	196	Off Idle	82.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.48	13.99	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:1	31.36	2245	2.46	13.41	99	196	Off Idle	82.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.44	14.01	0.95	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:1	31.36	2246	2.46	13.41	99	196	Off Idle	82.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.45	14.03	0.96	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:20:1	31.36	2266	2.46	13.42	99	196	Off Idle	82.2	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.46	14.04	0.96	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:20:2	31.36	2248	2.47	13.44	99	196	Off Idle	81.9	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.48	14.05	0.96	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:20:2	31.36	2248	2.47	13.43	99	196	Off Idle	81.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.48	14.07	0.96	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:20:2	31.36	2248	2.48	13.41	99	195	Off Idle	81.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.45	14.09	0.96	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:20:2	31.36	2227	2.48	13.42	99	195	Off Idle	81.3	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.36	14.12	0.96	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:2	31.36	2227	2.49	13.42	99	195	Off Idle	81	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.21	14.14	0.96	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:20:2	31.36	2244	2.5	13.43	99	196	Off Idle	80.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.14	14.15	0.96	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:3	31.36	2250	2.5	13.41	99	196	Off Idle	80.4	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.08	14.14	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:3	31.36	2266	2.51	13.41	99	196	Off Idle	80.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.96	14.16	0.96	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:3	31.36	2266	2.51	13.41	99	195	Off Idle	79.8	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.9	14.16	0.96	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:20:3	29.99	2280	2.52	13.41	99	195	Off Idle	79.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.88	14.18	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:3	29.99	2284	2.53	13.41	99	195	Off Idle	79.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.82	14.18	0.97	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:3	29.99	2288	2.53	13.42	99	195	Off Idle	78.9	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.78	14.21	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:4	29.99	2299	2.54	13.41	99	195	Off Idle	78.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.82	14.24	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:4	31.36	2325	2.55	13.4	99	195	Off Idle	78.3	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.79	14.3	0.97	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:4	31.36	2312	2.55	13.41	99	195	Off Idle	78.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.75	14.37	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:4	31.36	2314	2.56	13.42	99	195	Off Idle	78.1	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.75	14.42	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:4	31.36	2319	2.57	13.41	99	196	Off Idle	78	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.76	14.48	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:4	31.36	2322	2.58	13.43	99	196	Off Idle	77.8	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.75	14.51	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:4	31.36	2323	2.59	13.43	99	196	Off Idle	77.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.75	14.53	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:5	31.36	2324	2.59	13.42	99	196	Off Idle	77.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.76	14.56	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:5	31.36	2327	2.6	13.43	99	195	Off Idle	77.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.78	14.56	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:5	31.36	2327	2.6	13.42	99	195	Off Idle	76.8	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.8	14.56	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:5	31.36	2327	2.6	13.41	99	195	Off Idle	76.7	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.78	14.5	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:5	31.36	2329	2.6	13.42	99	195	Off Idle	76.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.75	14.51	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:5	31.36	2339	2.6	13.41	99	195	Off Idle	76.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.74	14.48	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:6	31.36	2339	2.6	13.41	99	195	Off Idle	76.4	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.71	14.46	0.99	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:6	31.36	2360	2.6	13.42	99	195	Off Idle	76.2	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.69	14.44	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:6	31.36	2360	2.61	13.43	99	195	Off Idle	76.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.72	14.43	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:6	31.36	2365	2.61	13.42	99	195	Off Idle	75.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.73	14.43	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:6	31.36	2365	2.61	13.43	99	195	Off Idle	75.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.76	14.42	0.98	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:20:6	31.36	2374	2.61	13.42	99	195	Off Idle	75.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.78	14.42	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:6	31.36	2375	2.61	13.41	99	195	Off Idle	75	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.74	14.43	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:7	31.36	2378	2.62	13.41	99	195	Off Idle	74.7	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.75	14.44	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:7	31.36	2386	2.62	13.41	99	196	Off Idle	74.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.75	14.43	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:7	31.36	2390	2.62	13.41	99	196	Off Idle	74	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.75	14.44	0.98	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:7	31.36	2390	2.62	13.41	99	195	Off Idle	73.9	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.72	14.47	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:7	31.36	2394	2.63	13.41	99	195	Off Idle	73.6	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.77	14.48	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:7	31.36	2400	2.63	13.41	99	195	Off Idle	73.3	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.75	14.49	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:8	31.36	2410	2.63	13.41	99	195	Off Idle	73	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.7	14.5	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:8	31.36	2410	2.63	13.41	99	195	Off Idle	72.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.67	14.52	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:8	31.36	2419	2.63	13.41	99	195	Off Idle	72.6	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.71	14.52	0.99	3.5	4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:20:8	31.36	2425	2.64	13.43	99	196	Off Idle	72	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.64	14.55	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:8	31.36	2427	2.64	13.43	99	196	Off Idle	71.7	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.64	14.56	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:8	31.36	2437	2.64	13.42	99	196	Off Idle	71.6	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.64	14.59	0.99	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:9	31.36	2438	2.65	13.41	99	195	Off Idle	71.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.65	14.61	1	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:9	31.36	2456	2.65	13.42	99	195	Off Idle	71.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.67	14.65	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:9	31.36	2450	2.65	13.4	99	195	Off Idle	71.1	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.7	14.68	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:9	31.36	2449	2.66	13.4	99	195	Off Idle	70.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.68	14.7	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:9	31.36	2448	2.66	13.42	99	195	Off Idle	70.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-1.69	14.73	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:9	31.36	2468	2.66	13.42	99	195	Off Idle	70.3	0	2	132	944 Turbo	0.68	Rich	1	14.7	-1.68	14.76	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:20:9	32.72	2447	2.66	13.4	99	195	Off Idle	70	0	2	132	944 Turbo	0.65	Rich	1	14.7	-1.68	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:0	32.72	2447	2.67	13.42	99	195	Off Idle	70	0	2	132	944 Turbo	0.62	Lean	1	14.7	-1.68	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:0	32.72	2453	2.67	13.41	99	195	Off Idle	69.6	0	2	132	944 Turbo	0.55	Lean	1	14.7	-1.67	14.83	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:0	32.72	2449	2.67	13.41	99	195	Off Idle	69.6	0	2	132	944 Turbo	0.5	Lean	1	14.7	-1.67	14.84	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:0	32.72	2462	2.68	13.41	99	195	Off Idle	69.6	0	2	132	944 Turbo	0.45	Lean	1	14.7	-1.65	14.83	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:0	31.36	2465	2.68	13.41	99	195	Off Idle	69.6	0	2	132	944 Turbo	0.4	Lean	1	14.7	-1.66	14.83	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:0	31.36	2471	2.68	13.41	99	195	Off Idle	69.6	0	2	132	944 Turbo	0.36	Lean	1	14.7	-1.61	14.84	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:1	31.36	2501	2.68	13.41	99	195	Off Idle	69.3	0	2	132	944 Turbo	0.35	Lean	1	14.7	-1.62	14.86	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:1	31.36	2501	2.68	13.42	99	195	Off Idle	69	0	2	132	944 Turbo	0.35	Lean	1	14.7	-1.62	14.88	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:1	31.36	2498	2.69	13.41	99	195	Off Idle	68.9	0	2	132	944 Turbo	0.39	Lean	1	14.7	-1.61	14.9	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:1	31.36	2512	2.69	13.42	99	195	Off Idle	68.7	0	2	132	944 Turbo	0.43	Lean	1	14.7	-1.61	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:1	31.36	2512	2.69	13.42	99	195	Off Idle	68.5	0	2	132	944 Turbo	0.48	Rich	1	14.7	-1.6	14.95	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:1	31.36	2512	2.7	13.43	99	195	Off Idle	68.2	0	2	132	944 Turbo	0.53	Rich	1	14.7	-1.64	14.98	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:1	31.36	2512	2.7	13.41	99	195	Off Idle	67.9	0	2	132	944 Turbo	0.59	Rich	1	14.7	-1.64	15.04	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:2	31.36	2514	2.7	13.41	99	195	Off Idle	67.7	0	2	132	944 Turbo	0.64	Rich	1	14.7	-1.64	15.07	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:2	31.36	2516	2.7	13.42	99	195	Off Idle	67.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-1.61	15.06	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:2	31.36	2525	2.7	13.41	99	195	Off Idle	67.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.64	15.05	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:2	31.36	2520	2.71	13.42	99	195	Off Idle	66.8	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.58	15.01	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:2	31.36	2522	2.71	13.41	99	195	Off Idle	66.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-1.55	14.98	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:2	31.36	2532	2.71	13.42	99	195	Off Idle	66.1	0	2	132	944 Turbo	0.65	Rich	1	14.7	-1.55	14.94	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:3	31.36	2546	2.71	13.43	99	195	Off Idle	65.6	0	2	132	944 Turbo	0.59	Rich	1	14.7	-1.54	14.89	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:3	31.36	2551	2.71	13.43	99	195	Off Idle	65.5	0	2	132	944 Turbo	0.54	Lean	1	14.7	-1.62	14.83	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:3	31.36	2554	2.72	13.42	99	195	Off Idle	65.3	0	2	132	944 Turbo	0.48	Lean	1	14.7	-1.57	14.79	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:3	31.36	2562	2.72	13.42	99	195	Off Idle	65	0	2	132	944 Turbo	0.42	Lean	1	14.7	-1.57	14.78	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:3	31.36	2565	2.72	13.44	99	195	Off Idle	64.6	0	2	132	944 Turbo	0.36	Lean	1	14.7	-1.59	14.75	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:3	31.36	2565	2.72	13.42	99	195	Off Idle	64.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-1.64	14.75	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:4	31.36	2570	2.72	13.42	99	195	Off Idle	64.3	0	2	132	944 Turbo	0.25	Lean	1	14.7	-1.58	14.75	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:21:4	31.36	2577	2.73	13.41	99	195	Off Idle	64.2	0	2	132	944 Turbo	0.25	Lean	1	14.7	-1.58	14.64	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:21:4	31.36	2580	2.73	13.42	99	195	Off Idle	63.9	0	2	132	944 Turbo	0.28	Lean	1	14.7	-1.59	14.67	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:21:4	31.36	2581	2.73	13.43	99	195	Off Idle	63.6	0	2	132	944 Turbo	0.29	Lean	1	14.7	-1.62	14.69	1	3.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:28:21:4	31.36	2584	2.73	13.42	99	195	Off Idle	63.3	0	2	132	944 Turbo	0.37	Lean	1	14.7	-1.56	14.73	1	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:4	31.36	2584	2.74	13.42	99	195	Off Idle	63	0	2	132	944 Turbo	0.42	Rich	1	14.7	-1.54	14.79	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:4	31.36	2585	2.74	13.43	99	195	Off Idle	62.7	0	2	132	944 Turbo	0.49	Rich	1	14.7	-1.62	14.83	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:5	31.36	2586	2.74	13.43	99	195	Off Idle	62.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-1.62	14.84	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:5	31.36	2589	2.74	13.44	99	195	Off Idle	62.1	0	2	132	944 Turbo	0.61	Rich	1	14.7	-1.61	14.85	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:5	31.36	2593	2.74	13.42	99	195	Off Idle	62	0	2	132	944 Turbo	0.7	Rich	1	14.7	-1.61	14.84	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:5	31.36	2604	2.74	13.42	99	195	Off Idle	61.9	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.66	14.82	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:5	31.36	2615	2.74	13.42	99	195	Off Idle	61.6	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.64	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:5	32.72	2644	2.75	13.41	99	195	Off Idle	61.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.65	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:6	32.72	2635	2.75	13.4	99	195	Off Idle	61	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.63	14.9	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:6	32.72	2628	2.75	13.4	99	195	Off Idle	60.8	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.64	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:6	32.72	2632	2.75	13.41	99	195	Off Idle	60.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.63	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:6	32.72	2633	2.76	13.41	99	195	Off Idle	60.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.62	14.74	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:6	32.72	2639	2.76	13.41	99	195	Off Idle	60.1	0	2	132	944 Turbo	0.68	Rich	1	14.7	-1.65	14.74	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:6	32.72	2640	2.76	13.42	99	195	Off Idle	60	0	2	132	944 Turbo	0.64	Rich	1	14.7	-1.63	14.74	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:6	32.72	2642	2.76	13.42	99	195	Off Idle	59.7	0	2	132	944 Turbo	0.59	Rich	1	14.7	-1.66	14.75	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:7	32.72	2652	2.76	13.42	99	195	Off Idle	59.1	0	2	132	944 Turbo	0.51	Rich	1	14.7	-1.7	14.75	1	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:7	32.72	2652	2.76	13.42	99	195	Off Idle	59.1	0	2	132	944 Turbo	0.51	Rich	1	14.7	-1.7	14.76	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:7	32.72	2664	2.76	13.42	99	195	Off Idle	58.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-1.78	14.77	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:21:7	32.72	2668	2.77	13.42	99	195	Off Idle	58.2	0	2	132	944 Turbo	0.34	Rich	1	14.7	-1.75	14.77	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:7	32.72	2672	2.77	13.44	99	195	Off Idle	58	0	2	132	944 Turbo	0.31	Rich	1	14.7	-1.81	14.81	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:7	32.72	2675	2.77	13.44	99	195	Off Idle	57.8	0	2	132	944 Turbo	0.3	Rich	1	14.7	-1.81	14.83	1.01	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:21:8	32.72	2672	2.77	13.43	99	195	Off Idle	57.7	0	2	132	944 Turbo	0.32	Rich	1	14.7	-1.78	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:8	32.72	2686	2.77	13.43	99	195	Off Idle	57.4	0	2	132	944 Turbo	0.35	Rich	1	14.7	-1.84	14.88	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:8	32.72	2683	2.77	13.44	99	195	Off Idle	57.1	0	2	132	944 Turbo	0.4	Rich	1	14.7	-1.83	14.91	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:8	32.72	2679	2.77	13.43	99	195	Off Idle	57	0	2	132	944 Turbo	0.45	Rich	1	14.7	-1.83	14.99	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:8	32.72	2680	2.77	13.44	99	195	Off Idle	56.8	0	2	132	944 Turbo	0.51	Rich	1	14.7	-1.79	14.99	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:8	32.72	2684	2.77	13.43	99	195	Off Idle	56.7	0	2	132	944 Turbo	0.57	Rich	1	14.7	-1.81	15.01	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:21:9	32.72	2691	2.77	13.42	99	195	Off Idle	56.6	0	2	132	944 Turbo	0.67	Rich	1	14.7	-1.79	14.99	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:9	32.72	2693	2.77	13.43	99	195	Off Idle	56.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-1.75	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:21:9	32.72	2706	2.77	13.41	99	195	Off Idle	56.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.8	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:21:9	32.72	2708	2.77	13.41	99	195	Off Idle	56.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.81	14.85	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:21:9	32.72	2712	2.77	13.42	99	195	Off Idle	56.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	-1.87	14.83	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:21:9	32.72	2729	2.77	13.43	99	195	Off Idle	55.9	0	2	132	944 Turbo	0.64	Rich	1	14.7	-1.88	14.78	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:21:9	32.72	2729	2.77	13.41	99	195	Off Idle	55.7	0	2	132	944 Turbo	0.58	Rich	1	14.7	-1.89	14.74	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:22:0	32.72	2729	2.77	13.43	99	195	Off Idle	55.4	0	2	132	944 Turbo	0.48	Rich	1	14.7	-1.89	14.74	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:22:0	32.72	2732	2.78	13.43	99	195	Off Idle	55.2	0	2	132	944 Turbo	0.42	Rich	1	14.7	-1.89	14.74	1	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:22:0	32.72	2742	2.78	13.42	99	195	Off Idle	55.2	0	2	132	944 Turbo	0.35	Rich	1	14.7	-1.86	14.74	1	3.6	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:22:0	32.72	2747	2.78	13.42	99	195	Off Idle	55.1	0	2	132	944 Turbo	0.29	Rich	1	14.7	-1.85	14.77	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:22:0	32.72	2747	2.78	13.41	99	195	Off Idle	54.8	0	2	132	944 Turbo	0.23	Rich	1	14.7	-1.85	14.8	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:22:0	32.72	2750	2.78	13.43	99	195	Off Idle	54.3	0	2	132	944 Turbo	0.19	Rich	1	14.7	-1.85	14.84	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:22:1	32.72	2754	2.78	13.42	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.18	Lean	1	14.7	-1.89	14.88	1.01	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:22:1	32.72	2753	2.78	13.41	99	195	Off Idle	53.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-1.88	14.93	1.02	3.5	4.2	ON	28 Pin	OFF	Removed	Disabled
03:28:22:1	32.72	2754	2.78	13.42	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.26	Lean	1	14.7	-1.85	14.94	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:1	32.72	2781	2.78	13.43	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.32	Lean	1	14.7	-1.9	14.96	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:1	32.72	2772	2.78	13.42	99	195	Off Idle	52.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-1.88	15.02	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:1	32.72	2766	2.78	13.43	99	195	Off Idle	52.1	0	2	132	944 Turbo	0.47	Lean	1	14.7	-1.93	15.08	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:1	32.72	2774	2.78	13.43	99	195	Off Idle	51.8	0	2	132	944 Turbo	0.51	Lean	1	14.7	-1.94	15.09	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:2	32.72	2779	2.78	13.42	99	195	Off Idle	51.7	0	2	132	944 Turbo	0.57	Lean	1	14.7	-1.96	15.08	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:2	32.72	2777	2.79	13.42	99	195	Off Idle	51.7	0	2	132	944 Turbo	0.63	Lean	1	14.7	-1.98	15.06	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:2	32.72	2785	2.79	13.42	99	195	Off Idle	51.5	0	2	132	944 Turbo	0.68	Lean	1	14.7	-2.02	15.03	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:2	32.72	2787	2.79	13.41	99	195	Off Idle	51.4	0	2	132	944 Turbo	0.71	Lean	1	14.7	-2.02	14.98	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:22:2	32.72	2787	2.79	13.42	99	195	Off Idle	50.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-2.06	14.94	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:22:2	32.72	2795	2.79	13.42	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-2.12	14.9	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:22:3	32.72	2795	2.79	13.42	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-2.09	14.83	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:22:3	32.72	2804	2.79	13.43	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.67	Rich	1	14.7	-2.09	14.79	1.01	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:22:3	32.72	2810	2.79	13.42	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.63	Rich	1	14.7	-2.1	14.76	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:3	32.72	2809	2.79	13.43	99	195	Off Idle	50.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-2.07	14.76	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:3	32.72	2808	2.79	13.42	99	195	Off Idle	50.4	0	2	132	944 Turbo	0.51	Rich	1	14.7	-2.13	14.75	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:3	32.72	2814	2.79	13.44	99	195	Off Idle	50.4	0	2	132	944 Turbo	0.45	Rich	1	14.7	-2.16	14.74	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:4	32.72	2825	2.79	13.43	99	195	Off Idle	50.3	0	2	132	944 Turbo	0.39	Rich	1	14.7	-2.22	14.74	1	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:4	32.72	2825	2.78	13.43	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.32	Rich	1	14.7	-2.24	14.77	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:4	32.72	2834	2.78	13.43	99	195	Off Idle	49.9	0	2	132	944 Turbo	0.27	Lean	1	14.7	-2.25	14.81	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:4	32.72	2846	2.79	13.44	99	195	Off Idle	49.6	0	2	132	944 Turbo	0.22	Lean	1	14.7	-2.24	14.84	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:4	32.72	2849	2.79	13.43	99	195	Off Idle	49.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-2.27	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:4	32.72	2850	2.79	13.44	99	195	Off Idle	49.2	0	2	132	944 Turbo	0.13	Lean	1	14.7	-2.25	14.9	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:4	32.72	2864	2.79	13.44	99	195	Off Idle	48.9	0	2	132	944 Turbo	0.1	Lean	1	14.7	-2.25	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:5	32.72	2850	2.79	13.44	99	195	Off Idle	48.6	0	2	132	944 Turbo	0.11	Lean	1	14.7	-2.26	15.01	1.02	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:5	32.72	2852	2.79	13.43	99	195	Off Idle	48.3	0	2	132	944 Turbo	0.13	Lean	1	14.7	-2.27	15.09	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:5	32.72	2853	2.79	13.44	99	195	Off Idle	48	0	2	132	944 Turbo	0.16	Lean	1	14.7	-2.28	15.12	1.03	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:5	32.72	2858	2.79	13.43	99	195	Off Idle	47.7	0	2	132	944 Turbo	0.21	Lean	1	14.7	-2.29	15.15	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:5	32.72	2858	2.79	13.42	99	195	Off Idle	47.4	0	2	132	944 Turbo	0.26	Rich	1	14.7	-2.27	15.17	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:5	32.72	2866	2.79	13.4	99	195	Off Idle	47.1	0	2	132	944 Turbo	0.34	Rich	1	14.7	-2.27	15.19	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:22:6	32.72	2868	2.79	13.42	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.39	Rich	1	14.7	-2.23	15.21	1.04	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:22:6	32.72	2872	2.79	13.42	99	195	Off Idle	46.7	0	2	132	944 Turbo	0.44	Rich	1	14.7	-2.24	15.19	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:22:6	32.72	2878	2.79	13.41	99	195	Off Idle	46.5	0	2	132	944 Turbo	0.47	Rich	1	14.7	-2.24	15.16	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:6	32.72	2878	2.79	13.42	99	195	Off Idle	46.4	0	2	132	944 Turbo	0.48	Rich	1	14.7	-2.29	15.15	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:22:6	32.72	2891	2.79	13.44	99	195	Off Idle	46.1	0	2	132	944 Turbo	0.47	Rich	1	14.7	-2.31	15.12	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:28:22:6	32.72	2894	2.79	13.44	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.43	Rich	1	14.7	-2.31	15.04	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:6	32.72	2904	2.8	13.43	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.38	Rich	1	14.7	-2.33	14.98	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:7	32.72	2904	2.8	13.43	99	195	Off Idle	45.3	0	2	132	944 Turbo	0.33	Rich	1	14.7	-2.31	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:7	32.72	2907	2.8	13.43	99	195	Off Idle	45.2	0	2	132	944 Turbo	0.27	Lean	1	14.7	-2.34	14.94	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:7	32.72	2914	2.8	13.41	99	195	Off Idle	45.1	0	2	132	944 Turbo	0.2	Lean	1	14.7	-2.29	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:7	32.72	2914	2.8	13.41	99	195	Off Idle	45	0	2	132	944 Turbo	0.16	Lean	1	14.7	-2.37	14.91	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:7	32.72	2924	2.8	13.41	99	195	Off Idle	44.7	0	2	132	944 Turbo	0.15	Lean	1	14.7	-2.38	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:7	32.72	2914	2.8	13.41	99	195	Off Idle	44.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-2.36	14.96	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:8	32.72	2910	2.8	13.42	99	195	Off Idle	44.1	0	2	132	944 Turbo	0.22	Lean	1	14.7	-2.41	14.99	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:8	32.72	2910	2.8	13.42	99	195	Off Idle	43.8	0	2	132	944 Turbo	0.25	Lean	1	14.7	-2.34	15	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:28:22:8	32.72	2892	2.8	13.43	99	195	Off Idle	43.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-2.42	15.05	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:8	32.72	2900	2.8	13.42	99	195	Off Idle	43.2	0	2	132	944 Turbo	0.35	Lean	1	14.7	-2.37	15.13	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:8	32.72	2902	2.8	13.41	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.4	Lean	1	14.7	-2.37	15.15	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:8	32.72	2905	2.8	13.42	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.44	Lean	1	14.7	-2.41	15.14	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:22:9	32.72	2912	2.81	13.41	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-2.39	15.12	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:9	32.72	2927	2.8	13.41	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.43	Lean	1	14.7	-2.42	15.1	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:9	32.72	2932	2.8	13.42	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.42	Lean	1	14.7	-2.43	15.06	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:9	32.72	2949	2.8	13.43	99	195	Off Idle	42.6	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.45	15.01	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:9	32.72	2953	2.8	13.45	99	195	Off Idle	42.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-2.53	14.98	1.02	3.4	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:9	32.72	2992	2.8	13.45	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.24	Lean	1	14.7	-2.55	14.94	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:22:9	32.72	2975	2.8	13.44	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.19	Lean	1	14.7	-2.6	14.92	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:0	32.72	2980	2.8	13.45	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.17	Lean	1	14.7	-2.63	14.93	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:0	32.72	2982	2.8	13.44	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.18	Lean	1	14.7	-2.65	14.97	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:0	34.08	3008	2.8	13.42	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.25	Rich	1	14.7	-2.62	14.99	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:0	34.08	2987	2.8	13.44	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.3	Rich	1	14.7	-2.68	15.02	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:0	34.08	2982	2.8	13.42	99	195	Off Idle	42.1	0	2	132	944 Turbo	0.36	Rich	1	14.7	-2.65	15.06	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:0	34.08	2982	2.8	13.43	99	195	Off Idle	42	0	2	132	944 Turbo	0.43	Rich	1	14.7	-2.76	15.12	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:1	34.08	2975	2.8	13.42	99	195	Off Idle	41.8	0	2	132	944 Turbo	0.49	Rich	1	14.7	-2.73	15.14	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:23:1	34.08	2966	2.8	13.42	99	195	Off Idle	41.7	0	2	132	944 Turbo	0.58	Rich	1	14.7	-2.82	15.14	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:23:1	34.08	2966	2.8	13.42	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-2.89	15.11	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:23:1	34.08	2975	2.79	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-2.92	15.06	1.03	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:23:1	34.08	2974	2.79	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-2.93	15.02	1.02	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:23:1	34.08	2982	2.79	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-2.93	14.99	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:1	34.08	2986	2.79	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-2.95	14.97	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:2	34.08	2992	2.79	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.96	14.93	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:2	34.08	3006	2.79	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.7	-2.97	14.88	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:2	34.08	3017	2.79	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.7	-3.02	14.83	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:2	34.08	3016	2.78	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-3.01	14.84	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:2	34.08	3016	2.78	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-3.08	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:2	34.08	3012	2.78	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-3.12	14.89	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:3	34.08	3014	2.78	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-3.13	14.92	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:3	34.08	3012	2.77	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-3.23	14.98	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:3	34.08	3017	2.77	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-3.23	15	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:28:23:3	34.08	3019	2.76	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-3.34	15.05	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:28:23:3	34.08	3021	2.76	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.22	Lean	1	14.7	-3.35	15.08	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:3	34.08	3031	2.76	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.25	Lean	1	14.7	-3.49	15.11	1.03	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:4	34.08	3060	2.76	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.31	Lean	1	14.7	-3.52	15.12	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:4	34.08	3060	2.75	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-3.61	15.14	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:4	34.08	3032	2.75	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	-3.6	15.15	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:4	34.08	3032	2.75	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.7	-3.65	15.13	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:4	34.08	3032	2.74	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Lean	1	14.7	-3.62	15.11	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:4	34.08	3037	2.74	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.7	-3.65	15.04	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:4	34.08	3040	2.74	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Lean	1	14.7	-3.64	15.02	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:5	34.08	3037	2.74	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.7	-3.69	14.97	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:5	34.08	3042	2.73	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.7	-3.65	14.94	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:5	34.08	3024	2.73	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	-3.75	14.91	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:5	34.08	3040	2.73	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-3.78	14.88	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:23:5	34.08	3062	2.72	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.29	Lean	1	14.7	-3.85	14.8	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:5	34.08	3070	2.72	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.26	Lean	1	14.7	-3.83	14.81	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:6	34.08	3070	2.72	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.17	Lean	1	14.7	-3.86	14.85	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:6	34.08	3104	2.71	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.12	Lean	1	14.7	-3.83	14.91	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:6	34.08	3084	2.71	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.82	14.97	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:6	34.08	3086	2.71	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.83	15.04	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:6	34.08	3086	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.88	15.11	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:6	34.08	3088	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.87	15.17	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:6	34.08	3088	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.92	15.26	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:7	34.08	3088	2.71	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.98	15.3	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:7	34.08	3088	2.71	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.93	15.3	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:7	34.08	3092	2.71	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.11	Lean	1	14.7	-3.91	15.29	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:7	34.08	3094	2.71	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.12	Lean	1	14.7	-3.95	15.28	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:7	34.08	3090	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.16	Lean	1	14.7	-3.97	15.24	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:7	34.08	3086	2.72	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.21	Lean	1	14.7	-3.99	15.21	1.04	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:8	34.08	3086	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.29	Lean	1	14.7	-4.03	15.16	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:8	34.08	3087	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.34	Lean	1	14.7	-4.03	15.12	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:8	34.08	3088	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.4	Rich	1	14.7	-4.02	15.13	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:8	34.08	3088	2.71	13.44	99	195	Off Idle	41.2	0	2	132	944 Turbo	0.49	Rich	1	14.7	-4.04	15.13	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:8	34.08	3099	2.71	13.44	99	195	Off Idle	41.2	0	2	132	944 Turbo	0.53	Rich	1	14.7	-3.99	15.11	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:8	34.08	3108	2.71	13.44	99	195	Off Idle	41.2	0	2	132	944 Turbo	0.54	Rich	1	14.7	-4.04	14.96	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:28:23:9	34.08	3108	2.71	13.44	99	195	Off Idle	41.2	0	2	132	944 Turbo	0.54	Rich	1	14.7	-4	14.94	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:9	34.08	3119	2.71	13.44	99	195	Off Idle	41.2	0	2	132	944 Turbo	0.51	Rich	1	14.7	-4.04	14.9	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:9	34.08	3145	2.71	13.44	99	195	Off Idle	41.2	0	2	132	944 Turbo	0.46	Rich	1	14.7	-4.02	14.89	1.01	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:28:23:9	34.08	3134	2.71	13.43	99	195	Off Idle	41.2	0	2	132	944 Turbo	0.43	Rich	1	14.7	-4.05	14.84	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:9	34.08	3130	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.35	Rich	1	14.7	-4.04	14.8	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:9	34.08	3136	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.32	Rich	1	14.7	-4.07	14.79	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:23:9	34.08	3130	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.24	Lean	1	14.7	-4.09	14.76	1.01	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:24:0	34.08	3144	2.71	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.2	Lean	1	14.7	-4.1	14.78	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:24:0	34.08	3146	2.71	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.17	Lean	1	14.7	-4.14	14.8	1.01	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:24:0	34.08	3138	2.71	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.17	Lean	1	14.7	-4.14	14.96	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:24:0	34.08	3149	2.71	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.21	14.99	1.02	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:28:24:0	34.08	3147	2.7	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-4.3	15.04	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:0	34.08	3144	2.7	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.32	Lean	1	14.7	-4.32	15.06	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:1	34.08	3142	2.7	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.7	-4.39	15.14	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:1	34.08	3143	2.7	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.47	15.17	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:1	35.45	3144	2.69	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.7	-4.56	15.18	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:28:24:1	35.45	3140	2.69	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-4.58	15.16	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:28:24:1	35.45	3142	2.68	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-4.64	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:1	35.45	3155	2.68	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-4.74	15.09	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:1	35.45	3144	2.67	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.68	Rich	1	14.7	-4.77	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:2	35.45	3146	2.66	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.64	Rich	1	14.7	-4.87	15.02	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:2	35.45	3145	2.65	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.59	Rich	1	14.7	-4.92	14.99	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:2	35.45	3145	2.65	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.54	Rich	1	14.7	-4.94	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:2	35.45	3148	2.64	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.48	Rich	1	14.7	-4.96	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:2	35.45	3149	2.63	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.7	-5.03	14.86	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:2	35.45	3153	2.63	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Rich	1	14.7	-5.02	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:3	35.45	3142	2.62	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-5.08	14.84	1.01	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:3	35.45	3167	2.61	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-5.08	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:3	35.45	3169	2.61	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-5.13	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:3	35.45	3171	2.6	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-5.14	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:3	35.45	3182	2.6	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-5.17	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:3	35.45	3187	2.59	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-5.11	15.07	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:4	35.45	3190	2.59	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.7	-5.18	15.11	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:4	35.45	3194	2.58	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.15	15.21	1.04	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:4	35.45	3197	2.58	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.23	15.28	1.04	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:4	35.45	3196	2.58	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.17	15.36	1.05	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:4	35.45	3191	2.58	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.25	15.44	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:24:4	35.45	3187	2.58	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.23	15.47	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:4	35.45	3187	2.58	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.29	15.49	1.06	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:5	35.45	3182	2.58	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.7	-5.32	15.49	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:5	35.45	3178	2.57	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.33	15.49	1.06	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:5	35.45	3178	2.57	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.34	15.46	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:5	35.45	3180	2.57	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.37	15.43	1.05	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:28:24:5	35.45	3180	2.57	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.32	15.39	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:5	35.45	3184	2.56	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.34	15.37	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:6	35.45	3184	2.56	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-5.32	15.34	1.05	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:6	35.45	3192	2.56	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.43	15.3	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:6	35.45	3202	2.55	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-5.42	15.26	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:6	35.45	3202	2.55	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-5.49	15.22	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:6	35.45	3209	2.55	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-5.53	15.19	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:6	35.45	3210	2.54	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-5.64	15.13	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:6	35.45	3219	2.54	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-5.62	15.12	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:28:24:7	35.45	3217	2.54	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-5.67	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:7	35.45	3218	2.53	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	-5.71	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:28:24:7	35.45	3215	2.53	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.7	-5.71	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:28:24:7	35.45	3213	2.53	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	-5.78	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:28:24:7	35.45	3213	2.52	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.7	-5.79	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:28:24:7	35.45	3208	2.52	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.7	-5.8	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:28:24:8	35.45	3204	2.52	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-5.81	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:28:24:8	35.45	3204	2.51	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-5.83	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:28:24:8	35.45	3203	2.51	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.7	-5.84	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:8	35.45	3204	2.51	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.7	-5.84	15	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:8	35.45	3211	2.5	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.7	-5.88	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:8	35.45	3213	2.5	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.7	-5.84	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:9	35.45	3224	2.5	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.9	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:9	35.45	3232	2.5	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-5.91	14.9	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:9	35.45	3234	2.49	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.91	14.9	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:9	35.45	3236	2.49	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-5.94	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:9	35.45	3241	2.49	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.98	14.95	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:9	35.45	3254	2.48	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.11	Lean	1	14.7	-5.97	14.99	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:24:9	36.81	3254	2.48	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.05	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:25:0	36.81	3236	2.48	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.13	Lean	1	14.7	-6.07	15.06	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:25:0	36.81	3237	2.48	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.18	Lean	1	14.7	-6.08	15.11	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:28:25:0	36.81	3226	2.47	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.23	Lean	1	14.7	-6.12	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:28:25:0	36.81	3236	2.47	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-6.23	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:28:25:0	36.81	3236	2.46	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.38	Rich	1	14.7	-6.25	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:28:25:0	36.81	3239	2.46	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.45	Rich	1	14.7	-6.35	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:28:25:1	36.81	3238	2.45	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.51	Rich	1	14.7	-6.38	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:1	36.81	3236	2.45	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.58	Rich	1	14.7	-6.44	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:1	36.81	3238	2.44	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-6.45	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:1	36.81	3238	2.44	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-6.46	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:1	36.81	3234	2.43	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-6.5	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:1	36.81	3234	2.42	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-6.53	15.03	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:28:25:1	36.81	3237	2.42	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.56	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:28:25:2	36.81	3238	2.42	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-6.61	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:28:25:2	36.81	3252	2.41	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Lean	1	14.7	-6.65	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:2	36.81	3246	2.4	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	-6.65	14.9	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:2	36.81	3248	2.4	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-6.73	14.86	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:2	36.81	3256	2.39	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.78	14.82	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:2	36.81	3267	2.39	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-6.78	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:3	36.81	3269	2.38	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-6.83	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:3	36.81	3268	2.38	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.82	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:3	36.81	3268	2.37	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.85	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:3	36.81	3274	2.36	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-6.91	14.92	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:25:3	36.81	3252	2.36	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Rich	1	14.6	-6.96	14.98	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:25:3	36.81	3250	2.35	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Rich	1	14.7	-7.04	15.03	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:25:4	36.81	3241	2.35	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Rich	1	14.7	-7.06	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:25:4	36.81	3224	2.34	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.13	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:4	36.81	3224	2.34	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Rich	1	14.7	-7.17	15.14	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:4	36.81	3225	2.32	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.17	15.18	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:4	36.81	3202	2.32	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-7.2	15.18	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:4	36.81	3226	2.31	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-7.28	15.19	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:4	36.81	3228	2.3	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-7.27	15.18	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:5	36.81	3227	2.3	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.35	15.13	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:5	36.81	3237	2.29	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-7.38	15.1	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:5	36.81	3237	2.28	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-7.41	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:5	36.81	3240	2.27	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.45	15.04	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:5	36.81	3246	2.27	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.48	14.98	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:5	36.81	3246	2.26	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.49	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:6	36.81	3270	2.26	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.7	-7.49	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:6	36.81	3263	2.25	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.49	14.9	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:6	36.81	3264	2.24	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.31	Rich	1	14.7	-7.55	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:6	36.81	3262	2.24	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.54	14.82	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:6	36.81	3267	2.24	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.2	Rich	1	14.7	-7.56	14.78	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:6	36.81	3267	2.23	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.59	14.79	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:6	36.81	3264	2.23	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.6	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:7	36.81	3292	2.23	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.11	Lean	1	14.7	-7.6	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:7	36.81	3279	2.23	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.87	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:7	36.81	3261	2.23	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.65	14.92	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:7	36.81	3235	2.23	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.11	Lean	1	14.7	-7.65	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:7	36.81	3245	2.22	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:7	36.81	3247	2.22	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	15.07	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:8	36.81	3249	2.22	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.2	Lean	1	14.7	-7.65	15.14	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:8	36.81	3254	2.22	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.28	Lean	1	14.7	-7.7	15.17	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:8	36.81	3264	2.22	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.33	Rich	1	14.7	-7.65	15.19	1.04	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:8	36.81	3264	2.22	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.39	Rich	1	14.7	-7.67	15.18	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:8	36.81	3258	2.22	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.65	15.17	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:25:8	36.81	3262	2.22	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.67	15.14	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:25:9	36.81	3264	2.21	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.68	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:25:9	36.81	3261	2.21	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.71	15.12	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:25:9	36.81	3256	2.21	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.65	Rich	1	14.7	-7.68	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:25:9	36.81	3256	2.21	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.63	Rich	1	14.7	-7.69	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:25:9	36.81	3253	2.21	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.58	Rich	1	14.7	-7.68	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:9	36.81	3251	2.21	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.69	15.05	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:25:9	36.81	3230	2.2	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.71	15.03	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:0	36.81	3243	2.2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.7	-7.75	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:0	36.81	3243	2.2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.78	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:0	36.81	3247	2.2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.79	14.96	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:0	36.81	3248	2.2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.83	14.94	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:0	36.81	3261	2.2	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.18	Lean	1	14.7	-7.83	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:0	36.81	3251	2.2	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.83	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:1	36.81	3254	2.19	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-7.86	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:1	36.81	3257	2.19	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.83	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:1	36.81	3256	2.19	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Rich	1	14.7	-7.88	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:1	36.81	3257	2.19	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Rich	1	14.7	-7.87	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:1	36.81	3257	2.19	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.7	-7.88	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:1	36.81	3256	2.18	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.7	-7.91	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:1	36.81	3259	2.18	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.91	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:2	36.81	3250	2.18	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.7	-7.92	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:2	36.81	3256	2.18	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-7.92	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:2	36.81	3250	2.18	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-7.94	15.06	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:2	36.81	3250	2.18	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.99	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:2	36.81	3247	2.18	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.95	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:26:2	36.81	3243	2.18	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.92	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:3	36.81	3233	2.17	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.94	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:3	36.81	3232	2.17	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.89	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:3	36.81	3234	2.17	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.89	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:3	36.81	3233	2.17	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-7.89	14.96	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:3	36.81	3233	2.17	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.88	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:3	36.81	3240	2.17	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.7	-7.89	14.9	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:4	36.81	3250	2.17	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.88	14.88	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:4	36.81	3258	2.17	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Rich	1	14.7	-7.91	14.85	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:4	36.81	3258	2.17	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.94	14.84	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:4	36.81	3261	2.17	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.9	14.81	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:4	36.81	3287	2.17	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-7.97	14.8	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:4	36.81	3274	2.17	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.99	14.79	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:26:4	36.81	3257	2.17	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-7.93	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:5	36.81	3255	2.17	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	-7.94	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:5	36.81	3254	2.17	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.7	-7.97	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:5	36.81	3247	2.16	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.94	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:5	36.81	3247	2.16	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.96	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:5	36.81	3247	2.16	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Lean	1	14.7	-7.98	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:5	36.81	3243	2.16	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.99	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:6	36.81	3244	2.16	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.01	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:6	36.81	3243	2.16	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-7.98	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:6	36.81	3239	2.16	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.99	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:6	36.81	3235	2.16	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:6	36.81	3224	2.16	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.97	15.05	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:6	36.81	3234	2.16	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.97	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:6	36.81	3236	2.16	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.95	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:7	36.81	3245	2.16	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.95	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:7	36.81	3245	2.16	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.96	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:7	36.81	3251	2.16	13.46	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.43	Rich	1	14.7	-7.96	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:7	36.81	3256	2.15	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.97	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:7	36.81	3256	2.15	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:7	36.81	3261	2.15	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.97	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:8	36.81	3260	2.15	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:8	36.81	3256	2.15	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.02	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:8	36.81	3258	2.15	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.04	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:26:8	36.81	3249	2.15	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.09	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:8	36.81	3250	2.14	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.13	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:8	36.81	3248	2.14	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.09	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:9	36.81	3250	2.14	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.13	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:9	36.81	3252	2.14	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	-8.11	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:9	36.81	3245	2.14	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.08	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:9	36.81	3249	2.14	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.1	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:9	36.81	3248	2.13	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.08	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:9	36.81	3245	2.13	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.08	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:26:9	36.81	3250	2.13	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.11	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:0	36.81	3249	2.13	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.1	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:0	36.81	3250	2.13	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.1	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:0	36.81	3245	2.13	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.1	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:0	36.81	3249	2.13	13.47	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.14	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:0	36.81	3246	2.13	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.13	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:0	36.81	3246	2.13	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.5	Lean	1	14.7	-8.15	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:1	36.81	3228	2.13	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.41	Lean	1	14.7	-8.13	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:1	36.81	3242	2.12	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.12	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:1	36.81	3242	2.12	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.15	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:1	36.81	3242	2.12	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.14	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:1	36.81	3244	2.12	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.12	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:1	36.81	3258	2.12	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.18	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:27:1	36.81	3245	2.12	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.18	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:2	36.81	3242	2.12	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.14	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:2	36.81	3242	2.12	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.22	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:2	36.81	3237	2.11	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.22	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:2	36.81	3230	2.11	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.24	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:2	36.81	3221	2.11	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.24	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:2	36.81	3221	2.11	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.23	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:3	36.81	3226	2.11	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.24	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:3	36.81	3227	2.11	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.21	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:3	36.81	3227	2.11	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.23	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:3	36.81	3228	2.1	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.27	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:3	36.81	3230	2.1	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.3	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:3	36.81	3236	2.1	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.31	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:4	36.81	3236	2.1	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.59	Lean	1	14.7	-8.31	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:4	36.81	3239	2.1	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.31	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:4	36.81	3240	2.09	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.7	-8.28	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:4	36.81	3220	2.09	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.27	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:4	36.81	3244	2.09	13.46	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.28	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:4	36.81	3244	2.09	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.3	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:4	36.81	3248	2.09	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.28	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:5	36.81	3273	2.09	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.34	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:5	36.81	3254	2.09	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.36	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:5	36.81	3255	2.08	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.32	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:5	36.81	3259	2.08	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.33	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:5	36.81	3257	2.08	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.32	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:5	36.81	3255	2.08	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.32	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:6	36.81	3252	2.08	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.35	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:6	38.18	3251	2.08	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.35	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:6	38.18	3250	2.08	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.37	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:6	38.18	3245	2.08	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.36	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:6	38.18	3234	2.08	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.34	15.16	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:6	36.81	3204	2.08	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.36	Rich	1	14.7	-8.38	15.19	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:6	36.81	3212	2.08	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.7	-8.34	15.19	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:7	36.81	3200	2.08	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.35	15.18	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:7	36.81	3204	2.08	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.35	15.19	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:7	36.81	3200	2.08	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.37	15.17	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:7	36.81	3198	2.08	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.32	15.16	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:7	36.81	3195	2.07	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.37	15.15	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:7	36.81	3197	2.07	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.33	15.16	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:8	36.81	3198	2.07	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.4	15.15	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:8	36.81	3200	2.07	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.38	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:27:8	36.81	3205	2.07	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.41	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:8	36.81	3205	2.07	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.41	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:8	36.81	3218	2.07	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.41	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:8	36.81	3222	2.06	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	-8.42	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:9	36.81	3226	2.06	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.48	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:9	36.81	3226	2.06	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.46	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:9	36.81	3226	2.06	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.41	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:9	36.81	3230	2.06	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.42	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:9	36.81	3236	2.06	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.47	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:9	36.81	3246	2.06	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.43	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:27:9	36.81	3231	2.06	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Rich	1	14.7	-8.45	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:0	36.81	3235	2.06	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.46	14.9	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:0	36.81	3235	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.7	-8.46	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:0	36.81	3236	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.47	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:0	38.18	3234	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.7	-8.46	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:0	38.18	3234	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.48	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:0	38.18	3230	2.05	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.47	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:28:1	38.18	3230	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-8.43	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:1	36.81	3192	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.41	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:1	36.81	3211	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.38	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:1	36.81	3211	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.37	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:1	36.81	3208	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.42	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:1	36.81	3206	2.05	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.51	Lean	1	14.7	-8.42	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:1	36.81	3204	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.43	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:2	36.81	3204	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.41	Lean	1	14.7	-8.48	15.05	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:2	36.81	3211	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.47	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:2	36.81	3211	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.44	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:2	36.81	3216	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.41	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:2	36.81	3218	2.05	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.38	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:2	36.81	3226	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.22	Rich	1	14.7	-8.37	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:3	36.81	3223	2.05	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.26	Rich	1	14.7	-8.39	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:3	36.81	3221	2.05	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.29	Rich	1	14.7	-8.38	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:3	36.81	3222	2.05	13.41	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.37	Rich	1	14.7	-8.36	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:3	38.18	3236	2.05	13.41	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.38	14.9	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:3	38.18	3229	2.05	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.41	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:3	38.18	3225	2.05	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.43	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:4	38.18	3226	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.43	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:4	36.81	3214	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.44	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:4	36.81	3213	2.05	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.48	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:4	36.81	3211	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.45	15.05	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:4	36.81	3206	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.44	15.05	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:4	36.81	3197	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.45	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:4	38.18	3197	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.41	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:5	38.18	3192	2.05	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.41	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:5	38.18	3190	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.7	-8.4	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:5	38.18	3189	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.39	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:5	38.18	3189	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.39	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:5	38.18	3190	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.39	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:5	38.18	3190	2.05	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.33	Rich	1	14.7	-8.39	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:6	38.18	3192	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.4	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:6	38.18	3190	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.4	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:6	38.18	3171	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.4	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:6	36.81	3184	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.4	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:6	36.81	3222	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.4	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:6	36.81	3197	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.41	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:6	36.81	3210	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.4	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:7	36.81	3214	2.05	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.35	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:7	36.81	3214	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.41	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:7	36.81	3218	2.05	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.37	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:7	36.81	3216	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.41	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:7	36.81	3218	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.43	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:7	36.81	3220	2.05	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.47	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:8	36.81	3221	2.05	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.47	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:8	36.81	3220	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.47	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:8	36.81	3218	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.49	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:8	36.81	3239	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.47	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:8	38.18	3239	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.48	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:8	38.18	3207	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.46	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:28:9	38.18	3193	2.05	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.43	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:9	38.18	3192	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	-8.44	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:9	38.18	3189	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.44	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:9	38.18	3187	2.05	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.43	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:9	38.18	3188	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.45	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:9	38.18	3189	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.46	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:28:9	38.18	3188	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.44	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:29:0	36.81	3167	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.46	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:0	36.81	3192	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.44	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:0	36.81	3190	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.44	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:0	36.81	3184	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.44	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:0	36.81	3179	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Rich	1	14.7	-8.45	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:0	36.81	3180	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.42	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:1	36.81	3178	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.43	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:1	36.81	3174	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.42	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:1	36.81	3176	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.39	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:1	36.81	3181	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.41	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:1	38.18	3188	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.36	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:1	38.18	3190	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.41	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:1	38.18	3186	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.4	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:2	38.18	3184	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.41	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:2	38.18	3188	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.41	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:2	38.18	3186	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.42	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:2	38.18	3191	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.43	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:2	38.18	3187	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.45	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:2	38.18	3188	2.05	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.42	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:3	38.18	3192	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.46	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:3	38.18	3198	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.43	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:3	38.18	3196	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.41	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:3	38.18	3195	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.41	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:3	38.18	3199	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.42	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:3	36.81	3198	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.42	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:4	36.81	3198	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.45	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:4	36.81	3198	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.45	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:4	36.81	3198	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.46	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:4	38.18	3198	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.7	-8.46	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:4	38.18	3203	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.47	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:4	38.18	3189	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	-8.45	15.13	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:4	38.18	3184	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.7	-8.47	15.17	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:5	38.18	3184	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.48	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:5	38.18	3184	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Lean	1	14.7	-8.46	15.16	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:5	38.18	3178	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.44	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:5	38.18	3178	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.46	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:5	38.18	3176	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.41	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:5	38.18	3174	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.42	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:6	36.81	3174	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.41	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:6	36.81	3174	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.41	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:6	36.81	3172	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.39	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:6	36.81	3170	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.4	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:6	36.81	3170	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.37	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:6	38.18	3180	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.7	-8.4	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:6	38.18	3172	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.43	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:7	38.18	3172	2.05	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.43	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:7	38.18	3171	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.45	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:7	38.18	3174	2.05	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.46	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:7	38.18	3174	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.46	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:7	38.18	3180	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.42	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:7	38.18	3186	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.42	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:8	38.18	3189	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.38	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:8	38.18	3190	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.41	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:8	38.18	3187	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.37	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:8	38.18	3187	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.38	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:8	38.18	3187	2.04	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.4	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:8	38.18	3186	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.4	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:9	36.81	3169	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.41	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:29:9	36.81	3173	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.43	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:9	36.81	3166	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.42	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:9	36.81	3164	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.46	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:9	36.81	3158	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.44	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:29:9	36.81	3151	2.04	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.46	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:29:9	36.81	3152	2.04	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.43	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:0	36.81	3148	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	-8.43	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:0	36.81	3142	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.41	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:0	36.81	3144	2.05	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.38	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:0	36.81	3150	2.05	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.41	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:0	36.81	3160	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.36	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:0	36.81	3160	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.38	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:1	36.81	3164	2.05	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.41	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:1	36.81	3166	2.05	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.41	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:1	36.81	3166	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.43	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:1	36.81	3168	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.44	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:1	36.81	3168	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.4	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:1	36.81	3170	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.41	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:1	38.18	3169	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.33	Lean	1	14.7	-8.41	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:30:2	38.18	3164	2.04	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.4	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:2	38.18	3160	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.39	14.96	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:2	38.18	3157	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.55	Lean	1	14.7	-8.39	15	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:2	38.18	3157	2.05	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.6	Lean	1	14.7	-8.39	15.02	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:2	36.81	3168	2.05	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.38	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:2	36.81	3168	2.04	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.68	Lean	1	14.7	-8.36	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:3	36.81	3152	2.04	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.39	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:30:3	36.81	3152	2.04	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.42	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:30:3	36.81	3139	2.04	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.41	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:30:3	36.81	3146	2.04	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.45	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:30:3	36.81	3146	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.43	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:3	36.81	3147	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.7	-8.4	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:4	36.81	3164	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.7	-8.39	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:4	36.81	3157	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.37	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:4	36.81	3158	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Rich	1	14.7	-8.41	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:4	36.81	3162	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Rich	1	14.7	-8.4	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:4	36.81	3165	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.43	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:4	36.81	3165	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.41	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:4	36.81	3172	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.45	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:5	36.81	3168	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.39	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:5	36.81	3167	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.41	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:5	36.81	3168	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.41	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:5	36.81	3162	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.7	-8.4	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:5	38.18	3181	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.7	-8.37	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:5	38.18	3147	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.39	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:6	38.18	3146	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.39	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:30:6	38.18	3140	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.37	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:6	38.18	3139	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.4	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:6	36.81	3126	2.04	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.37	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:6	36.81	3124	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.43	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:6	36.81	3137	2.04	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.41	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:30:6	36.81	3136	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-8.42	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:7	36.81	3139	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.42	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:7	38.18	3141	2.04	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.7	-8.42	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:7	38.18	3147	2.04	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.7	-8.42	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:7	38.18	3146	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.7	-8.42	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:7	38.18	3148	2.04	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.41	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:7	38.18	3132	2.04	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.42	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:8	36.81	3144	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.39	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:30:8	36.81	3155	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.4	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:30:8	36.81	3150	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.39	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:8	36.81	3150	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.4	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:8	36.81	3164	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.41	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:8	36.81	3146	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.43	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:9	36.81	3146	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.42	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:9	36.81	3145	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.42	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:9	36.81	3142	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.43	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:9	36.81	3126	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.4	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:9	36.81	3126	2.04	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.39	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:9	36.81	3123	2.04	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.39	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:30:9	36.81	3096	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.43	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:0	36.81	3108	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.42	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:0	36.81	3124	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.46	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:0	36.81	3125	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.43	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:0	36.81	3127	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.48	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:0	36.81	3125	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.41	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:0	36.81	3131	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Lean	1	14.7	-8.4	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:1	36.81	3129	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.41	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:1	36.81	3132	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.4	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:1	36.81	3134	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.7	-8.38	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:1	36.81	3148	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.41	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:1	36.81	3148	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.44	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:1	36.81	3150	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.4	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:1	36.81	3155	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.44	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:2	36.81	3155	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.4	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:2	36.81	3152	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.39	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:2	36.81	3171	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.43	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:2	38.18	3161	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.41	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:2	38.18	3161	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.4	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:2	38.18	3158	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.4	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:3	38.18	3150	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.42	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:3	36.81	3148	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.41	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:3	36.81	3138	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.43	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:3	36.81	3124	2.04	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.42	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:3	36.81	3114	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.43	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:3	36.81	3112	2.04	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.7	-8.41	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:4	36.81	3108	2.04	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Lean	1	14.7	-8.4	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:4	36.81	3110	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.4	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:4	36.81	3112	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.4	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:4	36.81	3115	2.04	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.44	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:4	36.81	3116	2.04	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.48	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:4	36.81	3121	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.52	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:4	36.81	3122	2.03	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.46	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:5	36.81	3128	2.03	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.49	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:5	36.81	3126	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.46	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:5	36.81	3124	2.03	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.46	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:5	36.81	3123	2.03	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.45	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:5	36.81	3125	2.03	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.48	Lean	1	14.7	-8.45	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:5	36.81	3125	2.03	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.45	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:6	36.81	3132	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.45	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:6	36.81	3137	2.03	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.47	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:6	36.81	3136	2.03	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.43	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:6	36.81	3140	2.03	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.47	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:6	36.81	3140	2.03	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.47	14.75	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:6	36.81	3147	2.03	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.44	14.75	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:6	36.81	3146	2.03	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.44	14.77	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:7	36.81	3146	2.03	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.45	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:31:7	36.81	3140	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.49	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:7	36.81	3138	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.46	14.79	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:7	36.81	3131	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.47	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:7	38.18	3146	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.48	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:7	38.18	3120	2.03	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.47	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:8	38.18	3121	2.03	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.46	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:8	38.18	3121	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.46	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:8	38.18	3122	2.03	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.45	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:8	36.81	3108	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.44	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:8	36.81	3120	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.46	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:8	36.81	3119	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.44	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:9	36.81	3119	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.49	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:9	36.81	3124	2.03	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.51	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:9	36.81	3126	2.03	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.51	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:31:9	36.81	3126	2.03	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.51	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:9	36.81	3126	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.5	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:9	36.81	3124	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.5	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:31:9	36.81	3127	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.47	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:0	36.81	3126	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.52	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:0	36.81	3120	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.47	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:0	36.81	3117	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.52	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:0	36.81	3117	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Lean	1	14.7	-8.48	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:0	36.81	3115	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.48	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:0	36.81	3115	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.48	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:1	36.81	3114	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.49	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:1	36.81	3119	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.5	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:1	36.81	3120	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.52	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:1	36.81	3118	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.5	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:1	36.81	3117	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.48	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:1	36.81	3115	2.02	13.43	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.5	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:1	36.81	3115	2.02	13.44	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.46	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:2	36.81	3115	2.02	13.45	98	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.47	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:2	36.81	3108	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.44	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:2	36.81	3100	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.47	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:2	36.81	3102	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.44	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:2	36.81	3101	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.52	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:2	36.81	3106	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.49	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:3	36.81	3106	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.53	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:3	36.81	3107	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.52	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:3	36.81	3114	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.52	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:3	36.81	3110	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.49	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:3	36.81	3117	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.52	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:3	36.81	3116	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.49	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:4	36.81	3120	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.52	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:4	36.81	3120	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.51	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:4	36.81	3123	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.49	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:4	36.81	3123	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.47	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:4	36.81	3125	2.02	13.42	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.44	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:4	36.81	3126	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.46	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:4	36.81	3122	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.47	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:5	36.81	3122	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.49	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:5	36.81	3117	2.02	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.51	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:5	36.81	3113	2.02	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.53	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:5	36.81	3110	2.02	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.52	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:5	36.81	3101	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.52	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:5	36.81	3103	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.51	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:6	36.81	3104	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.52	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:6	36.81	3096	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.49	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:32:6	36.81	3094	2.02	13.42	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.49	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:6	36.81	3092	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.7	-8.46	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:6	36.81	3092	2.02	13.42	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.7	-8.47	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:6	36.81	3086	2.02	13.42	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	-8.43	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:6	36.81	3085	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.45	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:7	36.81	3080	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.45	15.05	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:7	36.81	3080	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.49	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:7	36.81	3090	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.47	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:7	36.81	3085	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.48	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:7	36.81	3086	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.45	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:7	36.81	3089	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.46	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:8	36.81	3096	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.42	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:8	36.81	3098	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.46	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:8	36.81	3099	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.44	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:8	36.81	3104	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.47	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:8	36.81	3107	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.7	-8.41	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:8	36.81	3107	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.49	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:9	36.81	3115	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.47	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:9	36.81	3117	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.5	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:9	36.81	3116	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.52	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:32:9	36.81	3121	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.52	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:9	36.81	3119	2.02	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.5	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:9	36.81	3121	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.52	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:32:9	36.81	3116	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.7	-8.47	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:0	36.81	3108	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.7	-8.47	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:0	36.81	3107	2.02	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.48	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:0	36.81	3104	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.7	-8.45	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:0	36.81	3093	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.41	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:0	36.81	3093	2.02	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.47	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:0	36.81	3086	2.02	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.43	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:1	36.81	3083	2.02	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.48	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:1	36.81	3074	2.02	13.48	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.47	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:1	36.81	3074	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.48	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:1	36.81	3076	2.02	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.47	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:1	36.81	3079	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.45	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:1	36.81	3079	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.46	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:1	36.81	3082	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.44	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:2	36.81	3088	2.02	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.43	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:2	36.81	3093	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.42	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:2	36.81	3093	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.44	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:2	36.81	3098	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.42	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:2	36.81	3098	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-8.44	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:2	36.81	3101	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.41	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:33:3	36.81	3121	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.43	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:3	36.81	3089	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.43	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:3	36.81	3090	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.46	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:3	36.81	3090	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.46	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:3	36.81	3088	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.48	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:3	36.81	3088	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.49	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:33:4	36.81	3080	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.5	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:33:4	36.81	3076	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.7	-8.49	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:33:4	36.81	3072	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.7	-8.45	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:4	36.81	3072	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Lean	1	14.7	-8.49	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:4	36.81	3070	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.41	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:4	36.81	3080	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.44	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:4	36.81	3078	2.02	13.41	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.4	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:5	36.81	3070	2.02	13.42	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.44	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:5	36.81	3075	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.42	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:33:5	36.81	3075	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.45	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:5	36.81	3076	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.44	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:5	36.81	3078	2.02	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.48	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:5	36.81	3082	2.02	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.51	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:6	36.81	3082	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.52	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:6	36.81	3090	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.52	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:6	36.81	3116	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.49	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:6	36.81	3116	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.49	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:6	36.81	3100	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.45	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:6	36.81	3099	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.45	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:6	36.81	3100	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.47	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:7	36.81	3100	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.5	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:33:7	36.81	3092	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.47	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:7	36.81	3092	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.7	-8.47	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:7	36.81	3084	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.51	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:7	36.81	3065	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.7	-8.44	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:7	36.81	3059	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.43	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:33:8	36.81	3058	2.02	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.43	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:8	36.81	3060	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.42	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:8	36.81	3050	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.47	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:8	36.81	3065	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.4	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:8	36.81	3065	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.44	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:8	36.81	3062	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.45	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:9	36.81	3066	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.42	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:9	36.81	3069	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.41	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:9	36.81	3071	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.7	-8.42	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:9	36.81	3077	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.46	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:9	36.81	3075	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.42	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:33:9	36.81	3075	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.47	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:33:9	36.81	3077	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.45	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:0	36.81	3072	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.45	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:0	36.81	3067	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.43	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:0	36.81	3066	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.41	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:0	36.81	3066	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.44	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:0	36.81	3074	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.43	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:0	36.81	3075	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.44	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:1	36.81	3054	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.46	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:1	36.81	3064	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.42	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:1	36.81	3074	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.46	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:1	36.81	3066	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.48	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:1	36.81	3066	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.47	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:1	36.81	3064	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.51	15.14	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:1	36.81	3062	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.47	15.13	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:2	36.81	3062	2.02	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.47	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:2	36.81	3058	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.47	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:2	36.81	3056	2.02	13.46	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.46	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:2	36.81	3056	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.44	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:2	36.81	3056	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.5	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:2	36.81	3060	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-8.48	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:3	36.81	3060	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.48	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:3	36.81	3061	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.48	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:3	36.81	3061	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.7	-8.49	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:3	36.81	3060	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.41	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:3	36.81	3072	2.02	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.7	-8.42	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:3	36.81	3054	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.41	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:4	36.81	3056	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.44	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:4	36.81	3061	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.48	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:4	36.81	3052	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.43	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:34:4	36.81	3064	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.1	Lean	1	14.7	-8.52	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:4	36.81	3068	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.7	-8.49	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:4	36.81	3068	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.5	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:4	36.81	3087	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.45	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:5	36.81	3074	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.46	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:5	36.81	3074	2.02	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.41	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:5	36.81	3070	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.46	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:5	36.81	3049	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.41	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:5	36.81	3049	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.47	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:6	36.81	3050	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.7	-8.48	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:6	36.81	3039	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.46	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:6	36.81	3036	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.7	-8.44	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:6	36.81	3036	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.45	15.16	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:6	36.81	3034	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.44	15.16	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:6	36.81	3036	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.41	15.17	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:6	36.81	3026	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.41	15.17	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:6	36.81	3040	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.44	15.16	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:7	36.81	3049	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.41	15.14	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:7	36.81	3046	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.7	-8.41	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:7	36.81	3071	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.7	-8.41	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:7	36.81	3052	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	-8.4	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:7	36.81	3056	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.42	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:7	36.81	3058	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.41	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:8	36.81	3058	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.44	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:8	36.81	3060	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.41	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:8	36.81	3060	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.47	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:8	36.81	3056	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.44	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:8	36.81	3058	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.46	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:8	36.81	3056	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.47	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:9	36.81	3056	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.47	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:9	36.81	3055	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.45	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:9	36.81	3052	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.46	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:34:9	36.81	3052	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.45	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:9	36.81	3052	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.43	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:9	36.81	3048	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.47	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:34:9	36.81	3042	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.44	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:0	36.81	3042	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.7	-8.46	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:0	36.81	3037	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.47	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:0	36.81	3029	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.48	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:0	36.81	3027	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.46	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:0	36.81	3028	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.45	15.13	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:0	36.81	3028	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.46	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:1	36.81	3030	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.42	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:1	36.81	3030	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.42	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:1	36.81	3060	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.42	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:1	36.81	3050	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.41	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:1	36.81	3043	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.7	-8.39	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:1	36.81	3044	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.46	Rich	1	14.7	-8.41	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:1	36.81	3044	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.39	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:2	36.81	3050	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.39	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:2	36.81	3047	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.38	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:2	36.81	3047	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.41	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:2	36.81	3044	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.38	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:2	36.81	3039	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.42	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:2	36.81	3040	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.43	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:3	36.81	3040	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.34	Lean	1	14.7	-8.42	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:3	36.81	3040	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.46	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:3	36.81	3028	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.46	Lean	1	14.7	-8.42	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:35:3	36.81	3025	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.52	Lean	1	14.7	-8.42	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:3	36.81	3025	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.42	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:3	36.81	3022	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.41	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:4	36.81	3022	2.02	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.41	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:4	36.81	3035	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.41	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:4	36.81	3041	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.41	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:4	36.81	3041	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:4	36.81	3043	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.43	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:4	36.81	3054	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.4	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:4	36.81	3056	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.41	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:5	36.81	3056	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.39	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:5	36.81	3056	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.41	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:5	36.81	3054	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.4	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:5	36.81	3048	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.39	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:5	36.81	3041	2.02	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.42	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:5	36.81	3040	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.41	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:6	36.81	3037	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.44	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:6	36.81	3033	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.41	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:6	36.81	3028	2.02	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.42	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:6	36.81	3028	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.39	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:35:6	36.81	3030	2.02	13.46	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.28	Rich	1	14.7	-8.41	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:6	36.81	3032	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.34	Rich	1	14.7	-8.41	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:6	36.81	3032	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.46	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:7	36.81	3032	2.02	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.48	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:7	36.81	3030	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.45	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:7	36.81	3031	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.49	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:7	36.81	3031	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.43	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:7	36.81	3025	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.41	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:7	36.81	3026	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.4	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:8	36.81	3025	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.38	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:8	36.81	3026	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.42	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:8	36.81	3023	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.41	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:8	36.81	3020	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.43	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:8	36.81	3019	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.44	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:8	36.81	3019	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.41	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:9	36.81	3025	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.4	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:9	36.81	3026	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.7	-8.41	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:9	36.81	3034	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.41	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:9	36.81	3034	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.43	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:9	36.81	3026	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.38	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:9	36.81	3024	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.42	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:35:9	36.81	3025	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.41	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:0	36.81	3024	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.43	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:0	36.81	3022	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.41	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:0	36.81	3021	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.46	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:0	36.81	3019	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.41	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:0	36.81	3020	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.42	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:0	36.81	3021	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.43	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:1	36.81	3021	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.43	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:1	36.81	3022	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.45	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:1	36.81	3020	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.7	-8.41	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:1	36.81	3016	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.7	-8.45	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:1	36.81	3011	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.7	-8.44	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:1	36.81	3010	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.43	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:1	36.81	3010	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.45	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:2	36.81	3004	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.44	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:2	36.81	3009	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.42	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:2	36.81	3006	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.41	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:36:2	36.81	3008	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.41	15.09	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:2	36.81	3038	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.39	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:2	36.81	3026	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.41	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:3	36.81	3016	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.4	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:3	36.81	3018	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.44	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:3	36.81	3018	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.42	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:3	36.81	3000	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.45	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:3	36.81	3025	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.39	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:3	36.81	3024	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.43	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:4	36.81	3022	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.41	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:4	36.81	3018	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.43	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:4	36.81	3013	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.41	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:4	36.81	3004	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Rich	1	14.7	-8.44	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:4	36.81	3004	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.4	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:4	36.81	2998	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.7	-8.44	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:4	36.81	2998	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.41	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:5	36.81	3000	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.47	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:5	36.81	3001	2.01	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.45	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:5	36.81	3007	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.45	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:5	36.81	3007	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.48	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:5	36.81	3015	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.46	15.08	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:5	36.81	3012	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.46	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:6	36.81	3014	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	-8.44	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:6	36.81	3021	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	-8.46	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:6	36.81	3013	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.43	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:6	36.81	3013	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.44	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:6	36.81	3030	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.46	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:6	36.81	3026	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.45	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:6	36.81	3024	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.43	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:7	36.81	3022	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.47	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:7	36.81	3012	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.42	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:7	36.81	3008	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.44	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:7	36.81	3006	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.41	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:7	36.81	3000	2.01	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.41	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:7	36.81	2994	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.7	-8.41	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:8	36.81	2992	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.41	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:8	36.81	2990	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.7	-8.42	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:8	36.81	2982	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.39	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:8	36.81	2987	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.41	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:8	36.81	2988	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.37	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:8	36.81	2992	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.39	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:9	36.81	2994	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.39	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:9	36.81	2994	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.4	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:9	36.81	3002	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.55	Lean	1	14.7	-8.39	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:9	36.81	3007	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.39	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:9	36.81	3011	2.01	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.39	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:9	36.81	3012	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.4	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:9	36.81	3015	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.39	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:0	36.81	3019	2.01	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.41	14.89	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:0	36.81	3016	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.41	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:0	36.81	3017	2.01	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.41	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:0	36.81	3015	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.43	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:0	36.81	3017	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.41	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:0	36.81	3017	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.34	Rich	1	14.7	-8.42	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:1	36.81	3008	2.01	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.4	Rich	1	14.7	-8.42	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:1	36.81	3022	2.01	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.46	Rich	1	14.7	-8.41	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:1	36.81	3008	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.52	Rich	1	14.7	-8.41	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:1	36.81	2988	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.42	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:37:1	36.81	2989	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.41	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:1	36.81	2976	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.41	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:1	36.81	2988	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.41	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:2	36.81	2996	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.41	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:2	36.81	2996	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.57	Lean	1	14.7	-8.41	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:2	36.81	3000	2.01	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.51	Lean	1	14.7	-8.4	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:2	36.81	2998	2.01	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.48	Lean	1	14.7	-8.41	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:2	36.81	3001	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.4	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:2	36.81	3002	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.41	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:3	36.81	3001	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.4	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:3	36.81	3006	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.41	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:3	36.81	3006	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.41	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:3	36.81	3004	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.41	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:3	36.81	3002	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.41	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:3	36.81	2997	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-8.39	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:4	36.81	2997	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Rich	1	14.7	-8.39	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:4	36.81	2997	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.38	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:4	36.81	2998	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.43	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:4	36.81	2996	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.38	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:4	36.81	2995	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.43	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:4	36.81	2997	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-8.43	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:4	36.81	2995	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.44	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:5	36.81	2993	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.42	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:5	36.81	2989	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.44	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:5	36.81	2990	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.42	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:5	36.81	2992	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.36	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:5	36.81	2993	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.41	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:5	36.81	2989	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.38	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:6	36.81	2991	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.4	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:6	36.81	2992	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.39	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:6	36.81	2997	2.02	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.41	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:6	36.81	2997	2.02	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.38	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:6	36.81	2999	2.02	13.46	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.41	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:6	36.81	3002	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.39	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:6	36.81	2996	2.02	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.38	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:7	36.81	2996	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.34	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:7	36.81	2996	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.37	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:7	36.81	2995	2.02	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.36	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:7	36.81	2995	2.02	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.4	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:7	36.81	2996	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.44	14.78	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:37:7	36.81	2992	2.02	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.41	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:8	36.81	2990	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.7	-8.43	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:8	36.81	2988	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-8.42	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:8	36.81	2987	2.02	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	-8.41	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:8	36.81	2983	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.7	-8.38	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:8	36.81	2986	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.38	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:8	36.81	2986	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.38	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:9	36.81	2987	2.01	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.37	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:9	36.81	2988	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.39	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:9	36.81	2983	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.41	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:9	36.81	2986	2.01	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.34	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:9	36.81	2990	2.01	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.4	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:9	36.81	2992	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.36	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:37:9	36.81	2995	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.39	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:0	36.81	2992	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.35	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:0	36.81	2988	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.41	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:0	36.81	2984	2.01	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.35	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:0	36.81	2985	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.4	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:38:0	36.81	2988	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.41	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:0	36.81	2990	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.39	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:1	36.81	2987	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.37	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:1	36.81	2983	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.38	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:1	36.81	2983	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.39	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:1	36.81	2986	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.37	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:1	36.81	2988	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.36	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:1	36.81	2988	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Rich	1	14.7	-8.4	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:1	36.81	2990	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Rich	1	14.7	-8.4	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:2	36.81	2980	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.38	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:2	36.81	2988	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.4	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:2	36.81	2988	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.41	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:2	36.81	2978	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.38	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:2	36.81	2976	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.41	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:2	36.81	2980	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.4	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:3	36.81	2980	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.41	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:3	36.81	2980	2.02	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.43	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:3	36.81	2974	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.42	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:3	36.81	2974	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.44	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:3	36.81	2978	2.01	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.43	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:3	36.81	2983	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.41	15.1	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:4	36.81	2984	2.01	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.4	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:4	36.81	2984	2.01	13.46	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.4	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:4	36.81	2985	2.01	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.39	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:4	36.81	2985	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.26	Rich	1	14.7	-8.37	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:4	36.81	2984	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.41	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:4	36.81	2988	2.01	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.41	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:4	36.81	2988	2.01	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.41	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:5	36.81	2990	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.41	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:5	36.81	2984	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.41	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:5	36.81	2984	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.38	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:5	36.81	2986	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.37	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:5	36.81	2984	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.7	-8.4	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:5	36.81	2984	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	-8.37	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:6	36.81	2983	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.41	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:6	36.81	2979	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Lean	1	14.7	-8.41	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:6	36.81	2980	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.37	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:6	36.81	2976	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.37	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:6	36.81	2978	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.37	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:6	36.81	2975	2.02	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.32	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:6	36.81	2975	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.34	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:7	36.81	2978	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.33	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:7	36.81	2976	2.02	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.36	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:7	36.81	2976	2.02	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.31	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:7	36.81	2980	2.01	13.46	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.35	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:7	36.81	2980	2.01	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.36	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:7	36.81	2975	2.01	13.45	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.7	-8.37	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:8	36.81	2975	2.01	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.41	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:8	36.81	2978	2.01	13.44	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.7	-8.39	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:8	36.81	2978	2.01	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.43	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:8	36.81	2979	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.39	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:8	36.81	2980	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.41	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:8	36.81	2979	2.01	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.37	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:9	36.81	2979	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.38	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:9	36.81	2984	2.01	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.37	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:9	36.81	2988	2.01	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.4	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:38:9	36.81	2988	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-8.41	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:9	36.81	2988	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Rich	1	14.7	-8.39	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:38:9	36.81	2986	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Rich	1	14.7	-8.43	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:38:9	36.81	2977	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.7	-8.39	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:0	36.81	2967	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.48	Rich	1	14.7	-8.37	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:0	36.81	2967	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.36	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:0	36.81	2962	2.01	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.37	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:0	36.81	2960	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.37	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:0	36.81	2960	2.01	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.39	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:0	36.81	2956	2.01	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.41	15.14	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:1	36.81	2957	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.44	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:1	36.81	2954	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.44	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:1	36.81	2955	2.01	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.44	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:1	36.81	2956	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.46	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:1	36.81	2959	2.01	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.46	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:1	36.81	2965	2	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.43	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:1	36.81	2968	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.46	Rich	1	14.7	-8.4	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:2	36.81	2968	2	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.7	-8.41	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:2	36.81	2992	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.41	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:2	36.81	2992	2	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.7	-8.41	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:2	36.81	2976	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.42	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:2	36.81	2977	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.43	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:2	36.81	2976	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.42	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:3	36.81	2979	2	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.44	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:3	36.81	2983	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.7	-8.45	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:3	36.81	2987	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.7	-8.5	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:3	36.81	2985	2	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.49	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:3	36.81	2980	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.63	Lean	1	14.6	-8.49	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:3	36.81	2983	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.68	Lean	1	14.7	-8.47	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:4	36.81	2982	2	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.52	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:4	36.81	2974	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.48	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:4	36.81	2972	2	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.47	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:4	36.81	2972	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.49	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:4	36.81	2963	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.47	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:4	36.81	2958	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.45	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:4	36.81	2937	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.43	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:5	36.81	2948	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.42	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:5	36.81	2956	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.46	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:5	36.81	2953	2	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.44	14.92	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:5	36.81	2953	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.47	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:5	36.81	2956	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.49	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:5	36.81	2959	2	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.49	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:6	36.81	2959	2	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.5	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:6	36.81	2964	2	13.42	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.48	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:6	36.81	2965	2	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.48	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:6	36.81	2973	2	13.42	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.48	14.82	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:6	36.81	2972	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.46	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:6	36.81	2973	2	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.46	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:6	36.81	2969	2	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.46	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:39:7	36.81	2969	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Rich	1	14.6	-8.47	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:7	36.81	2968	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.48	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:7	36.81	2959	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.7	-8.45	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:7	36.81	2959	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.46	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:7	36.81	2948	2	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.43	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:7	36.81	2942	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.43	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:8	36.81	2942	2	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.44	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:8	36.81	2944	2	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.5	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:8	36.81	2946	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.5	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:8	36.81	2946	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.51	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:8	36.81	2933	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.52	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:39:8	36.81	2956	2	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.5	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:9	36.81	2962	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.5	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:9	36.81	2960	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.48	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:9	36.81	2968	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.46	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:9	36.81	2959	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.47	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:9	36.81	2951	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.45	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:9	36.81	2952	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.47	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:39:9	36.81	2953	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.44	14.9	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:0	36.81	2953	2	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Rich	1	14.7	-8.47	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:0	36.81	2960	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.46	14.85	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:0	36.81	2939	2	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.45	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:0	36.81	2964	2	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.47	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:0	36.81	2962	1.99	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.47	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:0	36.81	2965	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.47	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:1	36.81	2968	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.47	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:1	36.81	2965	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.47	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:1	36.81	2963	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.46	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:1	36.81	2959	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.7	-8.45	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:1	36.81	2955	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.7	-8.47	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:1	36.81	2955	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.7	-8.49	14.9	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:1	36.81	2947	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.46	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:2	36.81	2947	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.47	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:2	36.81	2948	1.99	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.44	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:2	36.81	2936	1.99	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.48	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:2	36.81	2951	1.99	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.42	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:2	36.81	2955	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.46	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:2	36.81	2955	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.44	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:3	36.81	2948	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.44	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:3	36.81	2945	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.46	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:3	36.81	2946	1.99	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.43	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:3	36.81	2934	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.66	Lean	1	14.6	-8.44	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:3	36.81	2944	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.61	Lean	1	14.7	-8.44	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:3	36.81	2946	1.99	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.7	-8.44	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:4	36.81	2946	1.99	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.42	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:4	36.81	2954	1.99	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.45	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:4	36.81	2956	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.43	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:4	36.81	2960	1.99	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.5	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:4	36.81	2961	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.47	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:4	36.81	2962	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.45	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:4	36.81	2966	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.47	14.81	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:5	36.81	2964	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.45	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:5	36.81	2964	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-8.47	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:5	36.81	2984	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.46	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:5	36.81	2958	1.99	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.44	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:5	36.81	2958	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.45	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:5	36.81	2948	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.43	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:6	36.81	2925	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.45	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:6	36.81	2936	1.99	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	-8.43	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:6	36.81	2945	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.56	Lean	1	14.7	-8.42	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:6	36.81	2946	1.99	13.42	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.41	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:6	36.81	2947	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.4	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:6	36.81	2948	1.99	13.43	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.42	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:6	36.81	2948	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.39	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:7	36.81	2948	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.43	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:7	36.81	2958	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.41	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:7	36.81	2958	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.42	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:7	36.81	2936	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.41	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:7	36.81	2942	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.44	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:40:7	36.81	2922	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.45	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:8	36.81	2935	1.99	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.58	Lean	1	14.7	-8.46	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:8	36.81	2950	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.51	Lean	1	14.7	-8.45	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:8	36.81	2954	1.99	13.44	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.45	Lean	1	14.7	-8.44	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:8	36.81	2956	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.41	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:8	36.81	2969	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	-8.44	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:8	36.81	2959	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.45	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:9	36.81	2958	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.46	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:9	36.81	2957	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.48	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:9	36.81	2957	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.44	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:9	36.81	2959	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.45	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:40:9	36.81	2959	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.46	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:9	36.81	2956	1.99	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.47	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:40:9	36.81	2944	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.47	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:0	36.81	2946	1.99	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.46	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:0	36.81	2948	1.99	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	-8.44	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:0	36.81	2948	1.99	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.46	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:0	36.81	2933	1.99	13.41	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.56	Lean	1	14.7	-8.45	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:0	36.81	2931	1.99	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.49	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:0	36.81	2933	1.99	13.42	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.69	Lean	1	14.6	-8.51	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:1	36.81	2934	1.99	13.43	99	195	Off Idle	41.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.53	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:1	36.81	2930	1.99	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.5	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:1	36.81	2927	1.99	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.5	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:1	36.81	2928	1.99	13.43	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.47	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:1	36.81	2929	1.99	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.49	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:1	36.81	2936	1.99	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.47	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:1	36.81	2939	1.99	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.49	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:2	36.81	2941	1.99	13.43	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.47	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:2	36.81	2950	1.99	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.44	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:2	36.81	2948	1.99	13.43	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.45	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:2	36.81	2946	1.99	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.42	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:2	36.81	2946	1.98	13.43	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.45	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:2	36.81	2947	1.98	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.47	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:41:3	36.81	2960	1.98	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.48	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:41:3	36.81	2948	1.98	13.44	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.51	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:3	36.81	2948	1.98	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.5	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:3	36.81	2946	1.98	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.52	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:41:3	36.81	2946	1.98	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.5	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:41:3	36.81	2946	1.98	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.53	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:41:4	36.81	2936	1.98	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.49	14.87	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:41:4	36.81	2936	1.98	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.52	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:4	36.81	2936	1.98	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.41	Rich	1	14.7	-8.5	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:4	36.81	2930	1.98	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.49	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:4	36.81	2931	1.98	13.42	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.47	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:4	36.81	2929	1.98	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.45	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:4	36.81	2929	1.99	13.41	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.47	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:5	36.81	2929	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.45	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:5	36.81	2922	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.45	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:5	36.81	2921	1.99	13.43	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.45	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:5	36.81	2921	1.99	13.46	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.43	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:5	36.81	2924	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.42	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:5	36.81	2924	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.43	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:6	36.81	2924	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.46	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:6	36.81	2931	1.99	13.44	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.44	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:6	36.81	2931	1.99	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.49	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:41:6	36.81	2932	1.99	13.43	99	195	Off Idle	41.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.46	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:6	36.81	2937	1.99	13.44	99	195	Off Idle	41.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.48	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:6	36.81	2936	1.99	13.42	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.49	14.81	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:41:8	36.81	2933	1.98	13.43	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.45	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:7	36.81	2933	1.98	13.42	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.52	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:7	36.81	2930	1.98	13.42	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.48	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:7	36.81	2932	1.98	13.42	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.5	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:7	36.81	2932	1.98	13.43	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.47	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:7	36.81	2934	1.98	13.42	99	195	Off Idle	41.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.51	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:7	36.81	2933	1.98	13.43	99	195	Off Idle	41.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.49	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:8	36.81	2932	1.98	13.43	99	195	Off Idle	42	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.49	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:8	36.81	2932	1.98	13.42	99	195	Off Idle	42.2	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.49	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:41:8	36.81	2934	1.98	13.41	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.48	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:8	36.81	2932	1.98	13.43	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.49	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:8	36.81	2931	1.98	13.41	99	195	Off Idle	42.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.48	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:8	36.81	2930	1.98	13.43	99	195	Off Idle	42	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.49	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:9	36.81	2930	1.98	13.43	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.54	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:9	36.81	2923	1.98	13.43	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.5	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:9	36.81	2916	1.98	13.43	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.49	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:9	36.81	2916	1.98	13.44	99	195	Off Idle	41.9	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.49	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:9	36.81	2916	1.98	13.45	99	195	Off Idle	42	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.46	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:9	36.81	2916	1.98	13.44	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.45	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:41:9	36.81	2916	1.98	13.43	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.46	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:0	36.81	2933	1.98	13.44	99	195	Off Idle	42.7	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.46	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:0	36.81	2923	1.98	13.42	99	195	Off Idle	42.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.41	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:0	36.81	2926	1.98	13.44	99	195	Off Idle	42.7	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.48	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:0	36.81	2927	1.98	13.43	99	195	Off Idle	42.7	0	2	132	944 Turbo	0.47	Lean	1	14.7	-8.48	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:0	36.81	2933	1.98	13.44	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.41	Lean	1	14.7	-8.48	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:0	36.81	2932	1.98	13.42	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.55	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:1	36.81	2931	1.98	13.44	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.55	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:1	36.81	2928	1.98	13.42	99	195	Off Idle	42.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.55	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:1	36.81	2928	1.98	13.44	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.52	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:1	36.81	2928	1.97	13.44	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.54	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:1	36.81	2930	1.97	13.43	99	195	Off Idle	43.3	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.52	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:1	36.81	2929	1.97	13.44	99	195	Off Idle	43.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.52	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:1	36.81	2928	1.97	13.43	99	195	Off Idle	43.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.52	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:2	35.45	2922	1.97	13.44	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.57	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:2	35.45	2922	1.97	13.43	99	195	Off Idle	42.9	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.53	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:2	35.45	2919	1.97	13.44	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.43	Rich	1	14.7	-8.53	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:2	35.45	2916	1.97	13.44	99	195	Off Idle	42.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.54	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:2	35.45	2914	1.97	13.43	99	195	Off Idle	42.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.6	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:2	36.81	2909	1.97	13.44	99	195	Off Idle	42.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.55	15.05	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:3	36.81	2909	1.97	13.43	99	195	Off Idle	42.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.57	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:3	36.81	2898	1.97	13.44	99	195	Off Idle	42.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.53	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:3	36.81	2902	1.96	13.42	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.56	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:3	36.81	2906	1.96	13.43	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.53	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:3	36.81	2904	1.96	13.44	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.66	Lean	1	14.6	-8.61	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:3	36.81	2906	1.96	13.43	99	195	Off Idle	43	0	2	132	944 Turbo	0.61	Lean	1	14.7	-8.59	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:4	36.81	2906	1.96	13.45	99	195	Off Idle	43	0	2	132	944 Turbo	0.55	Lean	1	14.7	-8.62	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:4	36.81	2908	1.96	13.44	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.61	15.05	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:4	36.81	2919	1.96	13.44	99	195	Off Idle	43	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.62	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:4	36.81	2922	1.96	13.44	99	195	Off Idle	43	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.62	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:4	36.81	2936	1.96	13.43	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.59	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:4	36.81	2936	1.95	13.44	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.61	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:4	36.81	2933	1.95	13.43	99	195	Off Idle	43.3	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.58	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:5	36.81	2957	1.95	13.44	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.59	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:5	36.81	2946	1.95	13.43	99	195	Off Idle	43.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.6	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:5	36.81	2933	1.95	13.45	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.61	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:5	36.81	2926	1.95	13.45	99	195	Off Idle	43	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.64	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:5	36.81	2899	1.95	13.44	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.65	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:5	36.81	2910	1.95	13.45	99	195	Off Idle	42.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.64	14.9	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:42:6	36.81	2918	1.95	13.44	99	195	Off Idle	42.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.71	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:6	36.81	2906	1.95	13.43	99	195	Off Idle	42.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.66	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:6	36.81	2906	1.95	13.43	99	195	Off Idle	42.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.68	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:6	36.81	2912	1.95	13.43	99	195	Off Idle	42.4	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.68	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:6	36.81	2892	1.95	13.42	99	195	Off Idle	42.4	0	2	132	944 Turbo	0.69	Lean	1	14.6	-8.69	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:6	36.81	2899	1.95	13.42	99	195	Off Idle	42.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.63	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:6	36.81	2899	1.95	13.44	99	195	Off Idle	42.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.71	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:7	36.81	2890	1.95	13.43	99	195	Off Idle	42.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.69	15.14	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:7	36.81	2897	1.95	13.44	99	195	Off Idle	42.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.68	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:7	36.81	2896	1.95	13.45	99	195	Off Idle	42.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.68	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:7	36.81	2890	1.94	13.45	99	195	Off Idle	42.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.68	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:7	36.81	2890	1.94	13.45	99	195	Off Idle	43	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.7	15.05	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:7	36.81	2891	1.94	13.45	99	195	Off Idle	43.1	0	2	132	944 Turbo	0.37	Rich	1	14.7	-8.7	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:8	36.81	2892	1.94	13.43	99	195	Off Idle	43.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.73	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:8	36.81	2898	1.94	13.44	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.74	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:8	36.81	2898	1.94	13.43	99	195	Off Idle	43.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.77	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:8	36.81	2912	1.94	13.44	99	195	Off Idle	43.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.73	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:8	36.81	2901	1.94	13.43	99	195	Off Idle	43.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.76	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:8	36.81	2901	1.93	13.45	99	195	Off Idle	43.7	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.7	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:9	36.81	2901	1.93	13.44	99	195	Off Idle	43.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.73	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:9	36.81	2901	1.93	13.44	99	195	Off Idle	43.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.72	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:42:9	36.81	2902	1.93	13.43	99	195	Off Idle	43.7	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.72	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:9	36.81	2908	1.93	13.44	99	195	Off Idle	43.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.74	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:9	36.81	2909	1.93	13.43	99	195	Off Idle	43.7	0	2	132	944 Turbo	0.38	Lean	1	14.7	-8.76	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:9	36.81	2905	1.93	13.43	99	195	Off Idle	43.7	0	2	132	944 Turbo	0.44	Lean	1	14.7	-8.76	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:42:9	36.81	2908	1.93	13.44	99	195	Off Idle	43.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.73	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:0	36.81	2907	1.93	13.45	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.73	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:0	36.81	2900	1.93	13.45	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.73	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:0	36.81	2899	1.93	13.45	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.75	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:0	36.81	2896	1.93	13.45	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.78	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:0	36.81	2893	1.93	13.45	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.77	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:0	36.81	2891	1.93	13.44	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.77	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:1	36.81	2891	1.93	13.44	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.74	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:1	36.81	2892	1.93	13.43	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.74	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:1	36.81	2891	1.93	13.43	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.75	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:1	36.81	2878	1.93	13.41	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.53	Lean	1	14.7	-8.78	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:1	36.81	2882	1.93	13.42	99	195	Off Idle	43.4	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.75	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:1	36.81	2882	1.93	13.42	99	195	Off Idle	43.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.81	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:1	36.81	2888	1.93	13.42	99	195	Off Idle	43.6	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.74	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:2	36.81	2895	1.93	13.43	99	195	Off Idle	43.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.78	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:2	36.81	2896	1.93	13.43	99	195	Off Idle	44.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.75	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:2	36.81	2903	1.93	13.43	99	195	Off Idle	44.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.76	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:2	36.81	2903	1.93	13.43	99	195	Off Idle	44.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.78	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:2	36.81	2904	1.92	13.44	99	195	Off Idle	44.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.81	14.79	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:2	36.81	2903	1.92	13.45	99	195	Off Idle	44.2	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.8	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:3	36.81	2895	1.92	13.44	99	195	Off Idle	44.1	0	2	132	944 Turbo	0.22	Rich	1	14.6	-8.83	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:3	36.81	2894	1.92	13.46	99	195	Off Idle	43.9	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.83	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:3	36.81	2892	1.92	13.44	99	195	Off Idle	43.9	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.82	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:3	36.81	2887	1.92	13.45	99	195	Off Idle	43.9	0	2	132	944 Turbo	0.4	Rich	1	14.7	-8.77	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:3	36.81	2887	1.92	13.44	99	195	Off Idle	44.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.78	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:3	36.81	2878	1.92	13.43	99	195	Off Idle	44.2	0	2	132	944 Turbo	0.54	Rich	1	14.7	-8.75	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:4	36.81	2877	1.92	13.43	99	195	Off Idle	44	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.75	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:4	36.81	2875	1.92	13.42	99	195	Off Idle	44	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.8	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:4	36.81	2875	1.92	13.42	99	195	Off Idle	44	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.77	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:4	36.81	2878	1.92	13.43	99	195	Off Idle	44	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.82	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:4	36.81	2878	1.92	13.43	99	195	Off Idle	44.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.79	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:4	36.81	2878	1.92	13.44	99	195	Off Idle	44.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.83	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:4	36.81	2877	1.92	13.45	99	195	Off Idle	44.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.83	15.1	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:43:5	35.45	2876	1.92	13.44	99	195	Off Idle	44.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.84	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:5	35.45	2876	1.92	13.44	99	195	Off Idle	44.7	0	2	132	944 Turbo	0.54	Rich	1	14.7	-8.85	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:5	35.45	2877	1.92	13.46	99	195	Off Idle	45	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.84	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:5	35.45	2881	1.92	13.44	99	195	Off Idle	45.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.82	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:5	35.45	2885	1.92	13.43	99	195	Off Idle	45.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.78	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:5	35.45	2885	1.92	13.45	99	195	Off Idle	45.1	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.82	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:6	35.45	2886	1.92	13.44	99	195	Off Idle	45.2	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.83	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:6	35.45	2887	1.92	13.44	99	195	Off Idle	45.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.85	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:6	35.45	2896	1.91	13.44	99	195	Off Idle	45.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.83	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:6	35.45	2892	1.91	13.45	99	195	Off Idle	45.2	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.83	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:6	36.81	2904	1.91	13.43	99	195	Off Idle	44.9	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.83	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:6	36.81	2896	1.91	13.43	99	195	Off Idle	45	0	2	132	944 Turbo	0.28	Lean	1	14.7	-8.78	14.8	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:6	36.81	2889	1.91	13.43	99	195	Off Idle	45.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.82	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:7	36.81	2888	1.91	13.44	99	195	Off Idle	45.1	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.85	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:7	36.81	2888	1.91	13.45	99	195	Off Idle	44.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.84	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:7	36.81	2889	1.91	13.45	99	195	Off Idle	44.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.87	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:7	36.81	2876	1.91	13.44	99	195	Off Idle	44.6	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.86	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:7	36.81	2876	1.91	13.45	99	195	Off Idle	44.6	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.87	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:7	36.81	2874	1.91	13.44	99	195	Off Idle	44.7	0	2	132	944 Turbo	0.68	Rich	1	14.7	-8.84	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:8	36.81	2864	1.91	13.44	99	195	Off Idle	44.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.86	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:8	36.81	2838	1.91	13.44	99	195	Off Idle	44.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.87	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:8	35.45	2838	1.91	13.45	99	195	Off Idle	44.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.86	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:8	35.45	2854	1.91	13.45	99	195	Off Idle	44.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.85	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:8	35.45	2851	1.91	13.46	99	195	Off Idle	45	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.85	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:8	35.45	2852	1.91	13.45	99	195	Off Idle	45.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.86	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:9	35.45	2854	1.91	13.45	99	195	Off Idle	45.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.88	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:9	35.45	2850	1.91	13.45	99	195	Off Idle	45.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.84	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:43:9	35.45	2851	1.91	13.45	99	195	Off Idle	45.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.85	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:9	35.45	2845	1.9	13.46	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.88	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:9	35.45	2854	1.9	13.45	99	195	Off Idle	45.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.85	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:9	35.45	2855	1.9	13.46	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.86	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:43:9	35.45	2855	1.9	13.44	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.92	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:0	35.45	2861	1.9	13.45	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.89	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:0	35.45	2862	1.9	13.45	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.92	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:0	35.45	2862	1.9	13.44	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.9	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:0	35.45	2864	1.9	13.44	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.9	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:0	35.45	2870	1.9	13.44	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.9	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:0	35.45	2872	1.9	13.44	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.88	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:1	35.45	2872	1.9	13.44	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.89	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:1	35.45	2874	1.89	13.44	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.93	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:1	35.45	2877	1.89	13.45	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.93	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:1	35.45	2877	1.89	13.45	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.95	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:1	35.45	2872	1.89	13.45	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.94	14.9	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:1	35.45	2865	1.89	13.46	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-8.95	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:1	35.45	2865	1.89	13.44	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.94	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:2	35.45	2848	1.89	13.45	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.94	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:2	35.45	2856	1.89	13.44	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.96	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:2	35.45	2856	1.89	13.46	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.96	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:2	35.45	2846	1.89	13.44	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.93	15.05	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:2	35.45	2874	1.89	13.43	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.92	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:2	35.45	2847	1.89	13.44	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.92	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:3	35.45	2847	1.89	13.43	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.92	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:3	35.45	2850	1.89	13.43	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.93	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:3	35.45	2829	1.89	13.44	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.95	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:3	35.45	2855	1.89	13.45	99	195	Off Idle	45.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-8.94	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:3	35.45	2856	1.89	13.45	99	195	Off Idle	45.6	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.95	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:3	35.45	2861	1.89	13.45	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.96	14.94	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:4	35.45	2858	1.89	13.43	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.95	14.92	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:44:4	35.45	2879	1.89	13.44	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.95	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:4	35.45	2860	1.89	13.43	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.92	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:4	35.45	2860	1.89	13.42	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.94	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:4	35.45	2858	1.89	13.43	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.9	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:4	35.45	2858	1.89	13.43	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.92	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:4	35.45	2858	1.89	13.43	99	195	Off Idle	45.8	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.91	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:5	35.45	2855	1.89	13.45	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.94	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:5	35.45	2851	1.89	13.45	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.52	Lean	1	14.7	-8.91	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:5	35.45	2848	1.89	13.44	99	195	Off Idle	45.7	0	2	132	944 Turbo	0.62	Lean	1	14.6	-8.94	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:5	35.45	2831	1.89	13.44	99	195	Off Idle	45.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.96	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:5	35.45	2842	1.89	13.44	99	195	Off Idle	46	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.96	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:5	35.45	2842	1.89	13.44	99	195	Off Idle	46	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.95	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:6	35.45	2838	1.89	13.44	99	195	Off Idle	46	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.97	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:6	35.45	2859	1.89	13.45	99	195	Off Idle	46	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.97	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:6	35.45	2833	1.89	13.45	99	195	Off Idle	46.1	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.98	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:6	35.45	2835	1.89	13.45	99	195	Off Idle	46.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.96	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:6	35.45	2832	1.89	13.46	99	195	Off Idle	46.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.98	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:6	35.45	2836	1.89	13.44	99	195	Off Idle	46.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.97	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:6	35.45	2834	1.89	13.44	99	195	Off Idle	46.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.94	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:7	35.45	2834	1.88	13.44	99	195	Off Idle	46.7	0	2	132	944 Turbo	0.57	Lean	1	14.7	-8.94	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:7	35.45	2826	1.88	13.44	99	195	Off Idle	46.7	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.99	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:7	35.45	2834	1.88	13.45	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.97	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:7	35.45	2834	1.88	13.46	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.98	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:7	35.45	2836	1.88	13.45	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.34	Lean	1	14.7	-9.01	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:7	35.45	2843	1.88	13.45	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.95	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:8	35.45	2843	1.88	13.45	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.96	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:8	35.45	2844	1.88	13.44	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.94	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:8	35.45	2844	1.88	13.46	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.98	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:8	35.45	2844	1.88	13.44	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.95	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:8	35.45	2843	1.88	13.46	99	195	Off Idle	46.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.99	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:8	35.45	2844	1.88	13.45	99	195	Off Idle	46.9	0	2	132	944 Turbo	0.11	Lean	1	14.7	-8.97	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:9	35.45	2844	1.88	13.46	99	195	Off Idle	46.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.97	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:9	35.45	2844	1.88	13.46	99	195	Off Idle	46.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.99	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:9	35.45	2843	1.88	13.46	99	195	Off Idle	46.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.98	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:9	35.45	2855	1.88	13.44	99	195	Off Idle	46.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.94	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:44:9	35.45	2842	1.88	13.44	99	195	Off Idle	46.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.95	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:9	35.45	2843	1.88	13.44	99	195	Off Idle	46.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.94	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:44:9	35.45	2843	1.88	13.44	99	195	Off Idle	46.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.95	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:45:0	35.45	2843	1.88	13.44	99	195	Off Idle	46.6	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.93	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:0	35.45	2840	1.88	13.46	99	195	Off Idle	46.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.98	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:0	35.45	2840	1.88	13.46	99	195	Off Idle	46.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.99	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:0	35.45	2831	1.88	13.47	99	195	Off Idle	46.8	0	2	132	944 Turbo	0.57	Rich	1	14.7	-9.04	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:0	35.45	2824	1.88	13.46	99	195	Off Idle	46.7	0	2	132	944 Turbo	0.6	Rich	1	14.7	-9.01	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:0	35.45	2809	1.88	13.46	99	195	Off Idle	46.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	-9.02	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:1	35.45	2809	1.88	13.46	99	195	Off Idle	47	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.02	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:1	35.45	2802	1.88	13.46	99	195	Off Idle	47.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.98	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:1	35.45	2804	1.88	13.46	99	195	Off Idle	47.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.98	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:1	35.45	2804	1.88	13.44	99	195	Off Idle	47.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.99	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:1	35.45	2798	1.88	13.45	99	195	Off Idle	47.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:1	35.45	2806	1.88	13.44	99	195	Off Idle	47.9	0	2	132	944 Turbo	0.7	Lean	1	14.6	-8.97	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:1	35.45	2807	1.88	13.46	99	195	Off Idle	47.9	0	2	132	944 Turbo	0.65	Lean	1	14.7	-8.98	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:2	35.45	2802	1.88	13.45	99	195	Off Idle	48	0	2	132	944 Turbo	0.56	Lean	1	14.7	-8.98	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:45:2	35.45	2818	1.88	13.44	99	195	Off Idle	48	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.99	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:45:2	35.45	2822	1.88	13.44	99	195	Off Idle	48.3	0	2	132	944 Turbo	0.43	Lean	1	14.7	-9	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:2	35.45	2822	1.88	13.43	99	195	Off Idle	48.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:2	35.45	2844	1.87	13.43	99	195	Off Idle	48.2	0	2	132	944 Turbo	0.3	Lean	1	14.7	-9.01	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:2	35.45	2824	1.87	13.43	99	195	Off Idle	48.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.02	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:3	35.45	2821	1.87	13.44	99	195	Off Idle	48.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.97	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:45:3	35.45	2834	1.87	13.45	99	195	Off Idle	48.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.01	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:3	35.45	2810	1.87	13.44	99	195	Off Idle	48.2	0	2	132	944 Turbo	0.21	Rich	1	14.7	-8.99	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:3	35.45	2833	1.87	13.45	99	195	Off Idle	48.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-9.03	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:3	35.45	2832	1.87	13.45	99	195	Off Idle	48.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.04	14.82	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:3	35.45	2828	1.87	13.44	99	195	Off Idle	48.3	0	2	132	944 Turbo	0.4	Rich	1	14.7	-9.04	14.84	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:4	35.45	2829	1.87	13.44	99	195	Off Idle	48.1	0	2	132	944 Turbo	0.46	Rich	1	14.7	-9.05	14.85	1.01	3.4	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:4	35.45	2837	1.87	13.43	99	195	Off Idle	48	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.02	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:4	35.45	2820	1.87	13.44	99	195	Off Idle	48	0	2	132	944 Turbo	0.55	Rich	1	14.7	-9.02	14.9	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:4	35.45	2819	1.87	13.42	99	195	Off Idle	48	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.03	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:4	35.45	2816	1.87	13.44	99	195	Off Idle	47.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.03	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:4	35.45	2816	1.87	13.45	99	195	Off Idle	48	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.02	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:4	35.45	2810	1.87	13.44	99	195	Off Idle	48.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.03	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:5	35.45	2807	1.87	13.45	99	195	Off Idle	48.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.04	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:5	35.45	2807	1.87	13.45	99	195	Off Idle	48.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.04	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:5	35.45	2806	1.87	13.45	99	195	Off Idle	48.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9.04	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:5	35.45	2810	1.87	13.44	99	195	Off Idle	48.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.03	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:5	35.45	2808	1.87	13.43	99	195	Off Idle	48.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.03	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:5	35.45	2806	1.87	13.43	99	195	Off Idle	48.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:6	35.45	2804	1.87	13.43	99	195	Off Idle	48.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.98	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:6	35.45	2799	1.87	13.45	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.98	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:6	35.45	2796	1.87	13.45	99	195	Off Idle	48.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.98	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:6	35.45	2797	1.87	13.45	99	195	Off Idle	48.8	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.01	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:6	35.45	2798	1.87	13.46	99	195	Off Idle	48.8	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.01	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:6	35.45	2800	1.87	13.44	99	195	Off Idle	48.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.03	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:6	35.45	2801	1.87	13.43	99	195	Off Idle	48.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.03	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:7	35.45	2801	1.87	13.44	99	195	Off Idle	48.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.02	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:45:7	35.45	2803	1.87	13.45	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.97	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:45:7	35.45	2802	1.87	13.46	99	195	Off Idle	48.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.99	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:45:7	35.45	2803	1.87	13.47	99	195	Off Idle	48.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.98	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:45:7	35.45	2809	1.87	13.45	99	195	Off Idle	48.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.97	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:7	35.45	2806	1.87	13.45	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.96	14.81	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:8	35.45	2808	1.87	13.45	99	195	Off Idle	48.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.95	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:8	35.45	2808	1.87	13.46	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.99	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:8	35.45	2806	1.87	13.45	99	195	Off Idle	48.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.98	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:8	35.45	2809	1.87	13.46	99	195	Off Idle	48.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.93	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:8	35.45	2812	1.87	13.45	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.94	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:8	35.45	2807	1.87	13.45	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.94	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:9	35.45	2808	1.87	13.44	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.94	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:9	35.45	2802	1.87	13.44	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.94	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:9	35.45	2798	1.87	13.44	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.94	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:9	35.45	2792	1.88	13.44	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.93	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:9	35.45	2792	1.88	13.44	99	195	Off Idle	48.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.94	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:9	35.45	2791	1.88	13.45	99	195	Off Idle	48.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.89	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:45:9	35.45	2785	1.88	13.46	99	195	Off Idle	48.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.94	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:0	35.45	2783	1.88	13.44	99	195	Off Idle	48.9	0	2	132	944 Turbo	0.63	Rich	1	14.7	-8.87	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:0	35.45	2784	1.88	13.46	99	195	Off Idle	48.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.9	14.93	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:0	35.45	2784	1.88	13.44	99	195	Off Idle	49.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.86	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:0	35.45	2782	1.88	13.44	99	195	Off Idle	49.2	0	2	132	944 Turbo	0.45	Rich	1	14.7	-8.87	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:0	35.45	2788	1.88	13.45	99	195	Off Idle	49.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.86	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:0	35.45	2788	1.88	13.45	99	195	Off Idle	49.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-8.9	14.76	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:1	35.45	2788	1.88	13.44	99	195	Off Idle	49.4	0	2	132	944 Turbo	0.23	Rich	1	14.7	-8.86	14.76	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:1	35.45	2788	1.88	13.45	99	195	Off Idle	49.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.84	14.76	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:1	35.45	2785	1.88	13.44	99	195	Off Idle	49.5	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.85	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:1	35.45	2786	1.89	13.45	99	195	Off Idle	49.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.88	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:1	35.45	2789	1.89	13.45	99	195	Off Idle	49.6	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.84	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:1	35.45	2786	1.89	13.46	99	195	Off Idle	49.7	0	2	132	944 Turbo	0.25	Lean	1	14.7	-8.85	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:1	35.45	2788	1.89	13.46	99	195	Off Idle	49.6	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.84	14.79	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:2	35.45	2768	1.89	13.47	99	195	Off Idle	49.6	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.83	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:46:2	35.45	2778	1.89	13.46	99	195	Off Idle	49.6	0	2	132	944 Turbo	0.44	Lean	1	14.7	-8.81	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:2	35.45	2791	1.89	13.46	99	195	Off Idle	49.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.77	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:2	35.45	2790	1.89	13.46	99	195	Off Idle	49.4	0	2	132	944 Turbo	0.55	Lean	1	14.7	-8.77	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:2	35.45	2790	1.89	13.45	99	195	Off Idle	49.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.78	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:2	35.45	2803	1.89	13.44	99	195	Off Idle	49.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.76	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:3	35.45	2795	1.89	13.43	99	195	Off Idle	49.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.74	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:3	35.45	2796	1.89	13.42	99	195	Off Idle	49.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.77	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:3	35.45	2798	1.89	13.41	99	195	Off Idle	49	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.78	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:3	35.45	2796	1.89	13.42	99	195	Off Idle	49	0	2	132	944 Turbo	0.62	Rich	1	14.7	-8.76	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:3	35.45	2796	1.89	13.43	99	195	Off Idle	48.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.76	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:3	35.45	2788	1.9	13.43	99	195	Off Idle	48.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.75	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:4	35.45	2778	1.9	13.44	99	195	Off Idle	48.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.72	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:4	35.45	2776	1.9	13.46	99	195	Off Idle	48.9	0	2	132	944 Turbo	0.41	Rich	1	14.6	-8.71	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:4	35.45	2765	1.9	13.44	99	195	Off Idle	48.9	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.72	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:4	35.45	2766	1.9	13.43	99	195	Off Idle	48.9	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.73	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:4	35.45	2764	1.9	13.43	99	195	Off Idle	49	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.71	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:4	35.45	2768	1.9	13.44	99	195	Off Idle	49.2	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.72	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:4	35.45	2775	1.9	13.43	99	195	Off Idle	49.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.74	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:5	35.45	2776	1.9	13.43	99	195	Off Idle	49.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.68	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:5	35.45	2779	1.9	13.43	99	195	Off Idle	49.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.69	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:5	35.45	2781	1.9	13.43	99	195	Off Idle	49.6	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.7	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:5	35.45	2781	1.9	13.41	99	195	Off Idle	49.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.72	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:5	35.45	2779	1.9	13.41	99	195	Off Idle	50	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.71	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:5	35.45	2781	1.9	13.43	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.73	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:6	35.45	2778	1.9	13.43	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.31	Rich	1	14.7	-8.73	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:6	35.45	2779	1.9	13.43	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-8.73	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:6	35.45	2779	1.9	13.45	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.5	Rich	1	14.7	-8.74	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:6	35.45	2776	1.9	13.47	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.57	Rich	1	14.7	-8.73	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:6	35.45	2776	1.9	13.46	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.73	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:6	35.45	2776	1.9	13.46	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.74	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:6	35.45	2779	1.9	13.46	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.72	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:7	35.45	2774	1.9	13.46	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.7	15.13	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:7	35.45	2774	1.9	13.46	99	195	Off Idle	50.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.69	15.14	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:7	35.45	2770	1.9	13.47	99	195	Off Idle	50.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.68	15.15	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:7	35.45	2768	1.9	13.46	99	195	Off Idle	50.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.71	15.13	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:7	35.45	2768	1.9	13.46	99	195	Off Idle	50.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.7	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:7	35.45	2770	1.9	13.45	99	195	Off Idle	50.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.69	15.07	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:8	35.45	2769	1.9	13.45	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.68	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:8	35.45	2770	1.9	13.45	99	195	Off Idle	51	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.68	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:8	35.45	2771	1.9	13.44	99	195	Off Idle	51	0	2	132	944 Turbo	0.36	Rich	1	14.7	-8.63	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:8	35.45	2769	1.9	13.45	99	195	Off Idle	51	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.66	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:8	35.45	2772	1.9	13.45	99	195	Off Idle	51	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.66	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:8	35.45	2762	1.9	13.45	99	195	Off Idle	51	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.65	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:9	35.45	2766	1.9	13.45	99	195	Off Idle	51	0	2	132	944 Turbo	0.15	Lean	1	14.7	-8.66	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:9	35.45	2766	1.9	13.45	99	195	Off Idle	51	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.65	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:9	35.45	2766	1.9	13.47	99	195	Off Idle	51	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.66	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:9	35.45	2764	1.9	13.45	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.2	Lean	1	14.7	-8.65	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:9	35.45	2767	1.91	13.45	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.64	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:46:9	35.45	2766	1.91	13.44	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.65	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:46:9	35.45	2767	1.91	13.44	99	195	Off Idle	51	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.61	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:0	35.45	2745	1.91	13.44	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.46	Lean	1	14.7	-8.64	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:0	35.45	2745	1.91	13.44	99	195	Off Idle	50.7	0	2	132	944 Turbo	0.53	Lean	1	14.7	-8.63	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:0	35.45	2765	1.91	13.44	99	195	Off Idle	50.5	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.63	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:0	35.45	2765	1.91	13.44	99	195	Off Idle	50.5	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.66	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:0	35.45	2765	1.91	13.42	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.66	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:0	35.45	2768	1.91	13.44	99	195	Off Idle	50.5	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.67	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:1	35.45	2768	1.91	13.44	99	195	Off Idle	50.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.65	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:1	35.45	2768	1.91	13.43	99	195	Off Idle	50.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.63	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:47:1	35.45	2771	1.91	13.45	99	195	Off Idle	50.7	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.57	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:1	35.45	2776	1.91	13.45	99	195	Off Idle	50.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.61	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:1	35.45	2776	1.92	13.45	99	195	Off Idle	51	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.56	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:1	35.45	2765	1.92	13.44	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.56	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:1	35.45	2764	1.92	13.44	99	195	Off Idle	50.7	0	2	132	944 Turbo	0.54	Lean	1	14.7	-8.57	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:2	35.45	2745	1.92	13.44	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.59	15.03	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:2	35.45	2745	1.92	13.43	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.58	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:2	35.45	2763	1.92	13.42	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.58	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:2	35.45	2763	1.92	13.43	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.6	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:2	35.45	2765	1.92	13.43	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.58	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:2	35.45	2763	1.92	13.45	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.56	14.91	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:3	35.45	2762	1.92	13.44	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.56	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:3	35.45	2762	1.92	13.45	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.57	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:3	35.45	2759	1.92	13.44	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.53	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:3	35.45	2758	1.92	13.45	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.51	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:3	35.45	2769	1.92	13.44	99	195	Off Idle	50.3	0	2	132	944 Turbo	0.19	Lean	1	14.7	-8.52	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:3	35.45	2769	1.92	13.45	99	195	Off Idle	50.1	0	2	132	944 Turbo	0.27	Lean	1	14.7	-8.54	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:4	35.45	2754	1.92	13.44	99	195	Off Idle	50.3	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.52	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:4	35.45	2754	1.93	13.45	99	195	Off Idle	50.3	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.52	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:4	35.45	2755	1.93	13.44	99	195	Off Idle	50.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.53	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:4	35.45	2755	1.93	13.44	99	195	Off Idle	50.4	0	2	132	944 Turbo	0.49	Lean	1	14.7	-8.52	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:4	35.45	2750	1.93	13.43	99	195	Off Idle	50.6	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.52	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:4	35.45	2752	1.93	13.41	99	195	Off Idle	50.7	0	2	132	944 Turbo	0.65	Lean	1	14.7	-8.52	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:4	35.45	2793	1.93	13.43	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.69	Lean	1	14.6	-8.49	15.13	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:5	35.45	2793	1.93	13.44	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.48	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:5	35.45	2758	1.93	13.43	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.5	15.13	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:5	35.45	2758	1.93	13.44	99	195	Off Idle	50.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.46	15.15	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:5	35.45	2760	1.93	13.45	99	195	Off Idle	51.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.47	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:5	35.45	2760	1.93	13.44	99	195	Off Idle	51.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.49	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:5	35.45	2760	1.93	13.45	99	195	Off Idle	51.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.49	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:6	35.45	2758	1.93	13.45	99	195	Off Idle	51.6	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.5	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:6	35.45	2753	1.93	13.46	99	196	Off Idle	51.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.52	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:6	35.45	2758	1.93	13.45	99	196	Off Idle	51.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.52	15.01	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:6	35.45	2750	1.93	13.46	99	196	Off Idle	51.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-8.49	14.98	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:6	35.45	2750	1.93	13.45	99	195	Off Idle	51.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.51	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:6	35.45	2733	1.93	13.45	99	195	Off Idle	51.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.48	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:6	35.45	2755	1.93	13.46	99	195	Off Idle	51.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.5	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:7	35.45	2755	1.93	13.46	99	196	Off Idle	51.7	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.54	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:7	35.45	2756	1.93	13.44	99	196	Off Idle	51.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.52	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:7	35.45	2755	1.93	13.46	99	196	Off Idle	52	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.53	14.85	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:7	35.45	2756	1.93	13.44	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.18	Lean	1	14.7	-8.52	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:7	35.45	2757	1.93	13.43	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.52	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:7	35.45	2756	1.93	13.44	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.23	Lean	1	14.7	-8.51	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:47:8	35.45	2756	1.93	13.44	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-8.5	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:8	35.45	2755	1.93	13.43	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.34	Rich	1	14.7	-8.49	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:8	35.45	2752	1.93	13.44	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.41	Rich	1	14.7	-8.5	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:8	35.45	2750	1.93	13.45	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.48	Rich	1	14.7	-8.5	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:8	35.45	2750	1.93	13.45	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.52	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:8	35.45	2743	1.93	13.46	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.51	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:9	35.45	2736	1.93	13.46	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.52	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:9	35.45	2736	1.93	13.46	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.53	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:9	35.45	2738	1.93	13.46	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.51	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:9	35.45	2742	1.93	13.45	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.51	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:9	35.45	2742	1.93	13.44	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.52	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:9	35.45	2742	1.93	13.43	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.51	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:47:9	35.45	2745	1.93	13.44	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.48	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:0	35.45	2748	1.93	13.43	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.53	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:0	35.45	2752	1.93	13.43	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.49	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:48:0	35.45	2752	1.93	13.44	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.5	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:0	35.45	2752	1.93	13.42	99	195	Off Idle	52.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.51	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:0	35.45	2749	1.93	13.43	99	195	Off Idle	52.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.53	14.9	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:0	35.45	2749	1.92	13.43	99	195	Off Idle	52.5	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.51	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:1	35.45	2749	1.92	13.43	99	195	Off Idle	52.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.52	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:1	35.45	2751	1.92	13.44	99	196	Off Idle	52.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.53	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:1	35.45	2748	1.92	13.45	99	196	Off Idle	52.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.54	14.77	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:1	35.45	2752	1.92	13.46	99	196	Off Idle	52.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.53	14.77	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:1	35.45	2739	1.92	13.46	99	196	Off Idle	52.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.52	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:1	35.45	2738	1.92	13.45	99	195	Off Idle	52.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.56	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:1	35.45	2738	1.92	13.45	99	195	Off Idle	52.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.55	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:2	35.45	2726	1.92	13.46	99	195	Off Idle	52.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-8.52	14.77	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:2	35.45	2736	1.92	13.45	99	195	Off Idle	52.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.56	14.78	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:2	35.45	2737	1.92	13.46	99	195	Off Idle	52.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.53	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:2	35.45	2740	1.92	13.44	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.53	14.73	1	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:2	35.45	2742	1.92	13.45	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.53	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:2	35.45	2742	1.92	13.45	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.37	Rich	1	14.7	-8.54	14.79	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:3	35.45	2744	1.92	13.44	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.52	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:3	35.45	2742	1.92	13.44	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.5	Rich	1	14.7	-8.51	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:3	35.45	2742	1.92	13.45	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.52	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:3	35.45	2738	1.92	13.45	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.48	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:3	35.45	2734	1.92	13.44	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.48	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:3	35.45	2733	1.92	13.44	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.52	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:4	35.45	2733	1.92	13.44	99	196	Off Idle	52.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.51	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:4	35.45	2728	1.92	13.42	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.51	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:4	35.45	2724	1.92	13.43	99	196	Off Idle	52.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.52	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:4	35.45	2720	1.92	13.42	99	195	Off Idle	52.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.5	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:4	35.45	2727	1.92	13.43	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.53	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:4	35.45	2726	1.92	13.43	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.52	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:4	35.45	2723	1.92	13.45	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.52	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:5	35.45	2725	1.92	13.45	99	195	Off Idle	52.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.54	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:5	35.45	2724	1.92	13.46	99	195	Off Idle	52.9	0	2	132	944 Turbo	0.48	Rich	1	14.7	-8.57	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:5	35.45	2709	1.92	13.46	99	195	Off Idle	52.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.57	14.98	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:5	35.45	2737	1.92	13.45	99	195	Off Idle	53	0	2	132	944 Turbo	0.36	Rich	1	14.7	-8.55	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:5	35.45	2737	1.92	13.44	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.28	Rich	1	14.7	-8.57	14.91	1.02	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:5	35.45	2746	1.92	13.44	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.26	Rich	1	14.6	-8.58	14.88	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:6	35.45	2767	1.92	13.43	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.58	14.85	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:6	35.45	2745	1.92	13.44	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.56	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:6	35.45	2745	1.92	13.43	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.58	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:6	35.45	2745	1.92	13.44	99	195	Off Idle	53.2	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.58	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:6	35.45	2745	1.92	13.44	99	195	Off Idle	53.2	0	2	132	944 Turbo	0.31	Lean	1	14.7	-8.56	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:6	35.45	2745	1.92	13.45	99	195	Off Idle	53.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.54	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:6	35.45	2742	1.92	13.44	99	195	Off Idle	53	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.56	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:7	35.45	2742	1.92	13.44	99	195	Off Idle	52.9	0	2	132	944 Turbo	0.53	Lean	1	14.7	-8.56	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:7	35.45	2740	1.92	13.45	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.54	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:7	35.45	2732	1.92	13.44	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.59	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:7	35.45	2731	1.92	13.44	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.56	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:7	35.45	2732	1.92	13.45	99	195	Off Idle	52.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.57	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:7	35.45	2729	1.92	13.44	99	195	Off Idle	52.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.55	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:8	35.45	2712	1.92	13.44	99	196	Off Idle	52.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-8.53	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:8	35.45	2736	1.92	13.44	99	196	Off Idle	52.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.5	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:8	35.45	2736	1.92	13.43	99	196	Off Idle	52.7	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.52	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:8	35.45	2745	1.92	13.41	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.54	15.05	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:8	35.45	2760	1.92	13.43	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.52	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:8	35.45	2760	1.92	13.41	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.52	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:9	35.45	2739	1.92	13.41	99	196	Off Idle	52.7	0	2	132	944 Turbo	0.41	Rich	1	14.7	-8.52	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:9	35.45	2738	1.92	13.42	99	196	Off Idle	52.7	0	2	132	944 Turbo	0.32	Lean	1	14.7	-8.51	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:48:9	35.45	2738	1.92	13.44	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.26	Lean	1	14.7	-8.51	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:48:9	35.45	2735	1.92	13.43	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.53	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:9	35.45	2728	1.92	13.45	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.52	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:9	35.45	2722	1.92	13.45	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.54	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:48:9	35.45	2724	1.92	13.45	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.54	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:0	35.45	2718	1.92	13.46	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.52	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:0	35.45	2731	1.92	13.46	99	195	Off Idle	52.8	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.54	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:0	35.45	2734	1.92	13.46	99	195	Off Idle	52.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.54	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:0	35.45	2734	1.92	13.45	99	195	Off Idle	52.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-8.54	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:0	35.45	2735	1.92	13.46	99	195	Off Idle	52.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.56	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:0	35.45	2746	1.92	13.44	99	195	Off Idle	52.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.54	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:1	35.45	2734	1.92	13.44	99	195	Off Idle	52.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.55	14.95	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:1	35.45	2730	1.92	13.44	99	196	Off Idle	52.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.54	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:1	35.45	2723	1.92	13.43	99	196	Off Idle	52.6	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.52	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:1	35.45	2712	1.92	13.44	99	196	Off Idle	52.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.5	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:1	35.45	2722	1.92	13.44	99	195	Off Idle	52.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.52	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:1	35.45	2720	1.92	13.44	99	195	Off Idle	52.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.5	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:1	35.45	2720	1.92	13.44	99	195	Off Idle	52.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.52	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:2	35.45	2725	1.92	13.44	99	195	Off Idle	52.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.51	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:2	35.45	2728	1.92	13.44	99	195	Off Idle	52.7	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.52	15.07	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:2	35.45	2729	1.92	13.42	99	195	Off Idle	52.9	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.52	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:2	35.45	2730	1.92	13.43	99	195	Off Idle	52.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.52	15.02	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:2	35.45	2730	1.92	13.43	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.52	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:2	35.45	2742	1.92	13.43	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.54	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:3	35.45	2728	1.92	13.43	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.55	14.95	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:3	35.45	2721	1.91	13.45	99	195	Off Idle	53.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.56	14.91	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:3	35.45	2720	1.91	13.45	99	195	Off Idle	53.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.59	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:3	35.45	2696	1.91	13.45	99	195	Off Idle	53.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.6	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:3	35.45	2718	1.91	13.45	99	195	Off Idle	53.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.58	14.82	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:3	35.45	2718	1.91	13.44	99	195	Off Idle	53.6	0	2	132	944 Turbo	0.22	Rich	1	14.7	-8.57	14.79	1.01	3.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:4	35.45	2718	1.91	13.45	99	195	Off Idle	53.7	0	2	132	944 Turbo	0.24	Rich	1	14.6	-8.57	14.79	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:4	35.45	2762	1.91	13.45	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.57	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:4	35.45	2720	1.91	13.45	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.57	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:4	35.45	2720	1.91	13.44	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.57	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:4	35.45	2726	1.91	13.44	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.6	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:4	35.45	2730	1.91	13.44	99	195	Off Idle	54	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.6	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:4	35.45	2730	1.91	13.44	99	195	Off Idle	54	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.6	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:5	35.45	2734	1.91	13.45	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.6	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:5	35.45	2730	1.91	13.45	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.76	Rich	1	14.7	-8.58	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:5	35.45	2729	1.91	13.45	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.58	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:5	35.45	2722	1.91	13.45	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.58	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:5	35.45	2719	1.91	13.45	99	195	Off Idle	53.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.57	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:5	35.45	2720	1.91	13.45	99	195	Off Idle	53.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.57	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:6	35.45	2719	1.91	13.44	99	195	Off Idle	53.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.58	15.01	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:6	35.45	2741	1.91	13.44	99	195	Off Idle	53.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.56	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:6	35.45	2732	1.91	13.44	99	196	Off Idle	53.7	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.57	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:6	35.45	2723	1.91	13.44	99	196	Off Idle	53.7	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.56	14.9	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:6	35.45	2722	1.91	13.43	99	196	Off Idle	53.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.58	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:6	35.45	2712	1.91	13.43	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.58	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:6	35.45	2720	1.91	13.43	99	195	Off Idle	53.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.55	14.77	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:7	35.45	2717	1.91	13.45	99	195	Off Idle	53.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.55	14.75	1	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:7	35.45	2710	1.91	13.43	99	195	Off Idle	53.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.57	14.74	1	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:7	35.45	2710	1.91	13.44	99	195	Off Idle	53.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.54	14.76	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:7	35.45	2713	1.91	13.45	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.57	14.77	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:7	35.45	2712	1.91	13.45	99	195	Off Idle	54	0	2	132	944 Turbo	0.22	Lean	1	14.7	-8.59	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:7	35.45	2710	1.91	13.45	99	195	Off Idle	54	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.59	14.77	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:8	35.45	2708	1.91	13.46	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.58	14.78	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:8	35.45	2706	1.91	13.46	99	196	Off Idle	53.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.59	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:8	35.45	2707	1.91	13.45	99	196	Off Idle	53.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.56	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:49:8	35.45	2709	1.91	13.45	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.58	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:8	35.45	2709	1.91	13.44	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.58	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:8	35.45	2709	1.91	13.44	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.59	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:9	35.45	2710	1.91	13.45	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.61	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:9	35.45	2709	1.9	13.45	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	-8.61	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:9	35.45	2713	1.9	13.45	99	195	Off Idle	53.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.59	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:9	35.45	2713	1.9	13.45	99	196	Off Idle	54	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.62	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:9	35.45	2705	1.9	13.44	99	196	Off Idle	54.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.6	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:49:9	35.45	2704	1.9	13.44	99	196	Off Idle	54.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.58	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:49:9	35.45	2704	1.9	13.45	99	196	Off Idle	54.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.6	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:0	35.45	2705	1.9	13.45	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.59	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:0	35.45	2704	1.9	13.44	99	196	Off Idle	54.5	0	2	132	944 Turbo	0.53	Lean	1	14.6	-8.6	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:0	35.45	2698	1.9	13.45	99	196	Off Idle	54.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.59	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:0	35.45	2698	1.9	13.45	99	196	Off Idle	54.5	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.59	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:0	35.45	2702	1.9	13.45	99	196	Off Idle	54.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.58	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:0	35.45	2708	1.9	13.45	99	195	Off Idle	54.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.57	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:1	35.45	2708	1.9	13.46	99	195	Off Idle	54.6	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.56	14.86	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:1	35.45	2712	1.9	13.45	99	195	Off Idle	54.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.56	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:1	35.45	2710	1.9	13.45	99	195	Off Idle	54.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.58	14.85	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:1	35.45	2714	1.9	13.45	99	195	Off Idle	54.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.59	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:1	35.45	2714	1.9	13.46	99	195	Off Idle	54.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.62	14.81	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:1	35.45	2713	1.9	13.45	99	195	Off Idle	54.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.61	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:1	35.45	2712	1.9	13.45	99	195	Off Idle	54.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.62	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:2	35.45	2712	1.9	13.44	99	195	Off Idle	54.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.62	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:2	35.45	2710	1.9	13.44	99	195	Off Idle	54.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.59	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:2	35.45	2709	1.9	13.45	99	195	Off Idle	54.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.61	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:2	35.45	2708	1.9	13.45	99	196	Off Idle	54.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.6	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:2	35.45	2712	1.9	13.44	99	196	Off Idle	54.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.6	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:2	35.45	2700	1.9	13.45	99	196	Off Idle	54.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-8.6	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:3	35.45	2698	1.9	13.44	99	195	Off Idle	54.2	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.58	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:3	35.45	2698	1.9	13.44	99	195	Off Idle	54.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.57	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:3	35.45	2688	1.9	13.45	99	195	Off Idle	54.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.6	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:3	35.45	2696	1.9	13.45	99	195	Off Idle	54.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.59	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:3	35.45	2696	1.9	13.44	99	195	Off Idle	54.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.56	15.12	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:3	35.45	2701	1.9	13.45	99	195	Off Idle	54.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.62	15.11	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:4	35.45	2704	1.9	13.44	99	195	Off Idle	54.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.6	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:4	35.45	2695	1.9	13.44	99	196	Off Idle	54.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.58	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:4	35.45	2710	1.9	13.44	99	196	Off Idle	54.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.57	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:4	35.45	2710	1.9	13.44	99	196	Off Idle	54.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.56	15.01	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:4	35.45	2709	1.9	13.43	99	196	Off Idle	54.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.57	14.98	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:4	35.45	2707	1.9	13.45	99	196	Off Idle	54.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.55	14.95	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:4	35.45	2703	1.9	13.44	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.54	14.92	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:5	35.45	2702	1.9	13.43	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.56	14.86	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:5	35.45	2700	1.9	13.45	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.59	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:5	35.45	2706	1.9	13.45	99	195	Off Idle	54.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.58	14.79	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:5	35.45	2696	1.9	13.43	99	195	Off Idle	54.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.57	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:5	35.45	2696	1.9	13.43	99	195	Off Idle	54.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.58	14.8	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:5	35.45	2695	1.9	13.44	99	195	Off Idle	54.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.6	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:6	35.45	2694	1.9	13.43	99	195	Off Idle	54.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.6	14.79	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:6	35.45	2694	1.9	13.43	99	195	Off Idle	54.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.6	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:6	35.45	2695	1.9	13.43	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.3	Rich	1	14.7	-8.62	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:6	35.45	2690	1.9	13.44	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.36	Rich	1	14.7	-8.61	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:6	35.45	2687	1.9	13.43	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.42	Rich	1	14.7	-8.62	14.92	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:6	35.45	2687	1.9	13.42	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.49	Rich	1	14.7	-8.62	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:6	35.45	2687	1.9	13.43	99	196	Off Idle	54.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.61	14.98	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:7	35.45	2687	1.9	13.43	99	196	Off Idle	54.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.61	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:7	35.45	2688	1.9	13.44	99	196	Off Idle	55.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.61	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:7	35.45	2682	1.9	13.43	99	195	Off Idle	55.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.57	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:50:7	35.45	2683	1.9	13.43	99	195	Off Idle	55.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.57	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:7	35.45	2683	1.9	13.44	99	195	Off Idle	55.7	0	2	132	944 Turbo	0.75	Rich	1	14.7	-8.57	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:7	35.45	2684	1.9	13.46	99	195	Off Idle	55.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.61	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:8	35.45	2687	1.9	13.45	99	195	Off Idle	56	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.62	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:8	35.45	2692	1.9	13.44	99	196	Off Idle	56	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.62	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:8	35.45	2693	1.89	13.46	99	196	Off Idle	56	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.62	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:8	35.45	2694	1.89	13.46	99	196	Off Idle	56.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.65	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:8	35.45	2693	1.89	13.44	99	196	Off Idle	56.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.65	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:8	35.45	2693	1.89	13.44	99	196	Off Idle	56.1	0	2	132	944 Turbo	0.69	Rich	1	14.7	-8.67	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:9	35.45	2695	1.89	13.44	99	196	Off Idle	56	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.68	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:9	35.45	2692	1.89	13.44	99	195	Off Idle	55.8	0	2	132	944 Turbo	0.67	Rich	1	14.7	-8.68	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:9	35.45	2691	1.89	13.43	99	195	Off Idle	55.6	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.69	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:9	35.45	2690	1.89	13.45	99	195	Off Idle	55.5	0	2	132	944 Turbo	0.66	Rich	1	14.7	-8.66	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:9	35.45	2687	1.89	13.45	99	196	Off Idle	55.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.66	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:50:9	35.45	2688	1.89	13.45	99	196	Off Idle	55.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.63	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:50:9	35.45	2688	1.89	13.45	99	196	Off Idle	55	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.62	14.79	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:0	35.45	2683	1.89	13.45	99	195	Off Idle	55	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.63	14.78	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:0	35.45	2679	1.89	13.45	99	195	Off Idle	55	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.62	14.8	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:0	35.45	2674	1.89	13.44	99	196	Off Idle	54.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.63	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:0	35.45	2674	1.89	13.43	99	196	Off Idle	54.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.61	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:0	35.45	2678	1.89	13.45	99	196	Off Idle	55	0	2	132	944 Turbo	0.55	Rich	1	14.6	-8.62	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:0	35.45	2679	1.89	13.44	99	196	Off Idle	55.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.62	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:1	35.45	2677	1.89	13.43	99	196	Off Idle	55.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.6	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:1	35.45	2680	1.89	13.44	99	196	Off Idle	55.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-8.61	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:1	35.45	2680	1.89	13.45	99	196	Off Idle	55.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.62	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:1	35.45	2680	1.89	13.45	99	196	Off Idle	55.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.63	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:1	35.45	2680	1.89	13.44	99	196	Off Idle	55.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.63	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:1	35.45	2678	1.89	13.44	99	196	Off Idle	55.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.65	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:1	35.45	2664	1.89	13.45	99	196	Off Idle	56	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.67	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:2	35.45	2674	1.89	13.45	99	196	Off Idle	56.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.64	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:2	35.45	2686	1.89	13.46	99	196	Off Idle	56.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.65	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:2	35.45	2688	1.89	13.45	99	195	Off Idle	55.9	0	2	132	944 Turbo	0.13	Lean	1	14.7	-8.65	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:2	35.45	2688	1.89	13.45	99	195	Off Idle	55.9	0	2	132	944 Turbo	0.17	Rich	1	14.6	-8.62	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:2	35.45	2687	1.89	13.44	99	195	Off Idle	56.1	0	2	132	944 Turbo	0.23	Rich	1	14.6	-8.62	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:2	35.45	2689	1.89	13.45	99	195	Off Idle	56.1	0	2	132	944 Turbo	0.27	Rich	1	14.7	-8.66	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:3	35.45	2686	1.89	13.43	99	195	Off Idle	56.1	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.65	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:3	35.45	2679	1.89	13.45	99	196	Off Idle	55.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.65	15.03	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:3	35.45	2698	1.89	13.45	99	196	Off Idle	55.6	0	2	132	944 Turbo	0.4	Rich	1	14.7	-8.66	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:3	35.45	2688	1.89	13.44	99	196	Off Idle	55.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.65	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:3	35.45	2678	1.89	13.44	99	195	Off Idle	55.6	0	2	132	944 Turbo	0.45	Rich	1	14.7	-8.64	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:3	35.45	2680	1.89	13.45	99	195	Off Idle	55.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-8.66	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:4	35.45	2678	1.89	13.45	99	195	Off Idle	55.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.62	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:4	35.45	2668	1.89	13.44	99	196	Off Idle	55.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.63	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:4	35.45	2664	1.89	13.45	99	196	Off Idle	55.4	0	2	132	944 Turbo	0.37	Lean	1	14.7	-8.64	15.11	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:4	35.45	2667	1.89	13.46	99	196	Off Idle	55.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.62	15.09	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:4	35.45	2670	1.89	13.44	99	195	Off Idle	55.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.59	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:4	35.45	2674	1.89	13.45	99	195	Off Idle	55.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.62	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:4	35.45	2673	1.89	13.45	99	195	Off Idle	55.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.65	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:5	35.45	2676	1.89	13.44	99	195	Off Idle	55.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.62	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:5	35.45	2690	1.89	13.42	99	195	Off Idle	55.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.64	14.99	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:5	35.45	2680	1.89	13.44	99	196	Off Idle	55.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.64	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:5	35.45	2680	1.89	13.44	99	196	Off Idle	56	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.65	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:5	35.45	2674	1.89	13.43	99	196	Off Idle	56.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.64	14.99	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:5	35.45	2652	1.89	13.44	99	196	Off Idle	56.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.62	15.01	1.02	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:6	35.45	2652	1.89	13.44	99	196	Off Idle	56.6	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.68	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:6	35.45	2676	1.89	13.45	99	196	Off Idle	56.7	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.69	15.05	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:6	35.45	2670	1.89	13.45	99	196	Off Idle	56.6	0	2	132	944 Turbo	0.36	Lean	1	14.7	-8.66	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:6	35.45	2668	1.88	13.44	99	196	Off Idle	56.6	0	2	132	944 Turbo	0.43	Lean	1	14.7	-8.66	15.12	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:51:6	35.45	2668	1.88	13.44	99	196	Off Idle	56.6	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.67	15.16	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:6	35.45	2665	1.88	13.43	99	196	Off Idle	56.4	0	2	132	944 Turbo	0.56	Lean	1	14.6	-8.66	15.18	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:6	35.45	2663	1.88	13.43	99	196	Off Idle	56.3	0	2	132	944 Turbo	0.63	Lean	1	14.7	-8.65	15.2	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:7	35.45	2661	1.88	13.41	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.68	Lean	1	14.7	-8.63	15.21	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:7	35.45	2656	1.88	13.43	99	196	Off Idle	56.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.65	15.23	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:7	35.45	2662	1.88	13.43	99	196	Off Idle	56.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.65	15.21	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:7	35.45	2665	1.88	13.41	99	196	Off Idle	56.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.63	15.23	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:7	35.45	2668	1.88	13.43	99	196	Off Idle	56.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.64	15.22	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:7	35.45	2661	1.88	13.44	99	196	Off Idle	56.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.73	15.17	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:8	35.45	2670	1.88	13.45	99	196	Off Idle	56.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.72	15.13	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:8	35.45	2672	1.88	13.45	99	196	Off Idle	56.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.75	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:8	35.45	2670	1.88	13.45	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.74	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:51:8	35.45	2683	1.88	13.46	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.73	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:8	35.45	2673	1.87	13.45	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.76	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:8	35.45	2672	1.87	13.44	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-8.74	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:9	35.45	2668	1.87	13.46	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.74	14.9	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:9	35.45	2667	1.87	13.46	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.39	Lean	1	14.7	-8.75	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:9	35.45	2661	1.87	13.44	99	196	Off Idle	56.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.74	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:9	35.45	2670	1.87	13.44	99	196	Off Idle	56.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.73	14.86	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:9	35.45	2662	1.87	13.46	99	195	Off Idle	56.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.75	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:9	35.45	2657	1.87	13.44	99	195	Off Idle	56.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.77	14.85	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:51:9	35.45	2658	1.87	13.44	99	195	Off Idle	56.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.75	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:52:0	35.45	2652	1.87	13.46	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.74	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:52:0	35.45	2650	1.86	13.46	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.81	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:52:0	35.45	2651	1.86	13.46	99	196	Off Idle	56.2	0	2	132	944 Turbo	0.22	Rich	1	14.6	-8.79	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:52:0	35.45	2651	1.86	13.45	99	196	Off Idle	56.5	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.79	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:0	35.45	2649	1.86	13.44	99	196	Off Idle	56.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.78	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:0	35.45	2648	1.86	13.44	99	196	Off Idle	56.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.83	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:1	35.45	2648	1.86	13.44	99	196	Off Idle	56.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.79	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:1	35.45	2645	1.86	13.42	99	196	Off Idle	57	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.8	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:1	35.45	2645	1.86	13.44	99	196	Off Idle	57.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.81	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:1	35.45	2645	1.85	13.44	99	196	Off Idle	57.3	0	2	132	944 Turbo	0.65	Rich	1	14.7	-8.85	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:1	35.45	2642	1.85	13.44	99	196	Off Idle	57.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.83	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:1	35.45	2644	1.85	13.42	99	196	Off Idle	57.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.82	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:1	35.45	2641	1.85	13.44	99	196	Off Idle	57.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.8	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:2	35.45	2641	1.85	13.44	99	196	Off Idle	57.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.83	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:2	35.45	2647	1.85	13.42	99	195	Off Idle	57.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.84	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:2	35.45	2652	1.84	13.43	99	195	Off Idle	57.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.83	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:2	35.45	2652	1.84	13.45	99	195	Off Idle	57.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.84	15.04	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:2	35.45	2648	1.84	13.45	99	196	Off Idle	57.5	0	2	132	944 Turbo	0.6	Rich	1	14.7	-8.88	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:2	35.45	2650	1.84	13.44	99	196	Off Idle	57.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.9	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:3	35.45	2652	1.84	13.45	99	196	Off Idle	57.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.9	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:3	35.45	2654	1.83	13.46	99	196	Off Idle	57.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.94	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:3	35.45	2656	1.83	13.45	99	196	Off Idle	57.4	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.98	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:3	35.45	2656	1.83	13.46	99	196	Off Idle	57.4	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.97	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:3	35.45	2643	1.83	13.45	99	196	Off Idle	57.4	0	2	132	944 Turbo	0.29	Lean	1	14.7	-8.97	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:3	35.45	2654	1.83	13.44	99	196	Off Idle	57.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.97	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:4	35.45	2652	1.83	13.42	99	196	Off Idle	57.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.95	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:4	35.45	2648	1.83	13.43	99	196	Off Idle	57.7	0	2	132	944 Turbo	0.24	Lean	1	14.7	-8.96	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:4	35.45	2647	1.83	13.44	99	196	Off Idle	57.7	0	2	132	944 Turbo	0.28	Lean	1	14.7	-9	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:4	35.45	2658	1.83	13.44	99	196	Off Idle	57.7	0	2	132	944 Turbo	0.34	Lean	1	14.7	-9.01	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:4	35.45	2645	1.83	13.44	99	196	Off Idle	57.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.98	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:4	35.45	2645	1.82	13.44	99	196	Off Idle	57.6	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.99	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:4	35.45	2637	1.82	13.43	99	196	Off Idle	57.4	0	2	132	944 Turbo	0.51	Lean	1	14.7	-9.01	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:5	35.45	2638	1.82	13.43	99	196	Off Idle	57.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.96	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:5	35.45	2638	1.82	13.43	99	196	Off Idle	57.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.98	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:5	35.45	2638	1.82	13.45	99	196	Off Idle	57.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.01	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:5	35.45	2634	1.82	13.45	99	196	Off Idle	57.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.04	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:52:5	35.45	2638	1.82	13.44	99	196	Off Idle	57.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.01	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:5	35.45	2640	1.82	13.46	99	196	Off Idle	57.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.02	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:6	35.45	2638	1.82	13.45	99	196	Off Idle	58	0	2	132	944 Turbo	0.65	Rich	1	14.7	-9.04	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:6	35.45	2639	1.82	13.45	99	196	Off Idle	58	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.01	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:6	35.45	2640	1.82	13.44	99	196	Off Idle	57.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.99	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:6	35.45	2652	1.82	13.44	99	196	Off Idle	57.9	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:6	35.45	2646	1.82	13.44	99	196	Off Idle	57.9	0	2	132	944 Turbo	0.38	Lean	1	14.7	-9.04	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:6	35.45	2648	1.82	13.44	99	196	Off Idle	58	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.03	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:6	35.45	2638	1.82	13.45	99	196	Off Idle	58.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:7	35.45	2642	1.82	13.45	99	196	Off Idle	58.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.02	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:7	35.45	2640	1.82	13.46	99	196	Off Idle	58.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.01	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:7	35.45	2640	1.82	13.46	99	196	Off Idle	58.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.98	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:7	35.45	2635	1.82	13.46	99	196	Off Idle	58.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.02	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:7	35.45	2631	1.82	13.47	99	196	Off Idle	58.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.02	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:7	35.45	2632	1.82	13.45	99	196	Off Idle	58.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	-9.05	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:8	35.45	2632	1.81	13.44	99	196	Off Idle	58.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-9.05	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:8	35.45	2617	1.81	13.45	99	196	Off Idle	58.5	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.04	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:8	35.45	2622	1.81	13.44	99	196	Off Idle	58.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.07	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:8	35.45	2622	1.81	13.42	99	196	Off Idle	58.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.06	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:8	35.45	2619	1.81	13.44	99	196	Off Idle	58.6	0	2	132	944 Turbo	0.55	Rich	1	14.7	-9.04	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:8	35.45	2641	1.81	13.44	99	196	Off Idle	58.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.04	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:9	35.45	2633	1.81	13.42	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.06	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:9	35.45	2626	1.81	13.43	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.03	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:9	35.45	2628	1.81	13.44	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.04	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:9	35.45	2630	1.81	13.42	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.04	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:9	35.45	2625	1.81	13.42	99	196	Off Idle	59	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.03	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:9	35.45	2624	1.81	13.43	99	196	Off Idle	59	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.03	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:52:9	35.45	2618	1.8	13.44	99	196	Off Idle	59	0	2	132	944 Turbo	0.75	Rich	1	14.7	-9.08	15.1	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:0	35.45	2618	1.8	13.43	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.08	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:0	35.45	2617	1.8	13.44	99	196	Off Idle	59	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.06	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:0	35.45	2617	1.8	13.44	99	195	Off Idle	59	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.08	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:0	35.45	2618	1.8	13.46	99	195	Off Idle	59	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.08	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:0	35.45	2619	1.8	13.46	99	195	Off Idle	58.9	0	2	132	944 Turbo	0.66	Rich	1	14.7	-9.07	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:0	35.45	2624	1.8	13.45	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.07	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:1	35.45	2623	1.8	13.44	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.06	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:1	35.45	2624	1.8	13.44	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.05	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:1	35.45	2624	1.8	13.44	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.04	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:1	35.45	2622	1.8	13.45	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.06	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:1	35.45	2625	1.8	13.43	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.07	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:1	35.45	2626	1.8	13.45	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.06	14.81	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:1	35.45	2626	1.8	13.45	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.08	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:2	35.45	2624	1.8	13.43	99	195	Off Idle	58.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.1	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:2	35.45	2624	1.8	13.44	99	195	Off Idle	58.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.09	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:2	35.45	2625	1.8	13.44	99	195	Off Idle	58.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.13	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:2	35.45	2624	1.8	13.45	99	195	Off Idle	58.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.13	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:2	35.45	2620	1.8	13.45	99	195	Off Idle	58.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.14	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:2	35.45	2620	1.8	13.45	99	195	Off Idle	58.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.15	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:3	35.45	2617	1.8	13.44	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.17	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:3	35.45	2615	1.8	13.43	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.17	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:3	35.45	2613	1.79	13.43	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.18	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:3	35.45	2614	1.79	13.43	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.16	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:3	35.45	2604	1.79	13.43	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.17	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:3	35.45	2603	1.79	13.45	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.44	Lean	1	14.7	-9.17	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:53:4	35.45	2603	1.79	13.44	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.5	Lean	1	14.7	-9.15	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:4	35.45	2604	1.79	13.44	99	196	Off Idle	59.1	0	2	132	944 Turbo	0.59	Lean	1	14.7	-9.17	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:4	35.45	2605	1.79	13.44	99	196	Off Idle	59.2	0	2	132	944 Turbo	0.65	Lean	1	14.7	-9.2	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:4	35.45	2604	1.78	13.45	99	196	Off Idle	59.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.21	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:4	35.45	2604	1.78	13.44	99	196	Off Idle	59.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.22	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:53:4	35.45	2609	1.78	13.45	99	196	Off Idle	59.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.22	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:4	35.45	2610	1.78	13.45	99	196	Off Idle	59.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.23	15.05	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:5	35.45	2610	1.77	13.45	99	195	Off Idle	59.7	0	2	132	944 Turbo	0.74	Rich	1	14.7	-9.22	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:5	35.45	2612	1.77	13.43	99	195	Off Idle	59.7	0	2	132	944 Turbo	0.71	Rich	1	14.7	-9.24	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:5	35.45	2609	1.77	13.43	99	195	Off Idle	59.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.28	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:5	35.45	2610	1.76	13.43	99	196	Off Idle	59.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.28	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:5	35.45	2610	1.76	13.43	99	196	Off Idle	59.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.26	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:5	35.45	2607	1.76	13.43	99	196	Off Idle	59.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.31	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:6	35.45	2609	1.76	13.45	99	196	Off Idle	59.7	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.31	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:6	35.45	2609	1.75	13.44	99	196	Off Idle	59.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.35	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:6	35.45	2606	1.75	13.43	99	196	Off Idle	59.6	0	2	132	944 Turbo	0.23	Lean	1	14.7	-9.39	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:6	35.45	2607	1.74	13.45	99	196	Off Idle	59.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.41	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:6	35.45	2606	1.74	13.44	99	196	Off Idle	59.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.44	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:6	35.45	2606	1.73	13.44	99	196	Off Idle	59.1	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.49	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:53:6	35.45	2604	1.72	13.44	99	196	Off Idle	59	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.56	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:28:53:7	35.45	2600	1.72	13.44	99	196	Off Idle	59	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.57	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:28:53:7	35.45	2597	1.71	13.45	99	196	Off Idle	59	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.63	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:28:53:7	35.45	2592	1.7	13.45	99	196	Off Idle	59.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-9.71	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:28:53:7	35.45	2590	1.68	13.44	99	196	Off Idle	59.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.77	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:28:53:7	35.45	2589	1.67	13.45	99	196	Off Idle	59.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.81	14.85	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:28:53:7	35.45	2585	1.65	13.45	99	196	Full Load	59.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.91	14.87	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:28:53:8	35.45	2580	1.62	13.44	99	196	Idle	59.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.04	14.9	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:53:8	35.45	2580	1.61	13.43	99	196	Idle	59.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-10.05	14.88	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:53:8	35.45	2566	1.59	13.43	99	196	Idle	60.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-10.16	14.91	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:53:8	35.45	2563	1.57	13.44	99	196	Idle	60.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.25	14.94	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:53:8	32.72	2507	1.55	13.43	99	196	Idle	60.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.29	14.96	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:28:53:8	27.27	2507	1.53	13.45	99	196	Idle	60.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.36	14.99	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:53:9	27.27	2486	1.51	13.44	99	196	Idle	61.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.39	15.01	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:53:9	21.81	2460	1.49	13.44	99	196	Idle	61.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-10.39	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:53:9	19.09	2489	1.47	13.43	99	196	Idle	62.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-10.41	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:53:9	19.09	2487	1.45	13.43	99	196	Idle	62.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.43	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:53:9	19.09	2479	1.44	13.43	99	196	Idle	62.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.45	15.02	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:53:9	19.09	2482	1.43	13.44	99	196	Idle	62.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.44	15.01	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:53:9	19.09	2486	1.41	13.44	99	196	Idle	63	0	2	132	944 Turbo	0.54	Rich	1	14.6	-10.46	14.98	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:0	19.09	2508	1.4	13.44	99	196	Idle	63.1	0	2	132	944 Turbo	0.48	Rich	1	14.6	-10.49	14.94	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:0	19.09	2529	1.38	13.45	99	196	Idle	63.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.51	14.91	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:0	19.09	2534	1.37	13.44	99	196	Idle	63.2	0	2	132	944 Turbo	0.3	Rich	1	14.6	-10.54	14.87	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:0	19.09	2552	1.37	13.44	99	196	Idle	63.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-10.51	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:0	19.09	2571	1.36	13.44	99	196	Idle	63.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-10.51	14.78	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:0	19.09	2571	1.36	13.44	99	196	Idle	63.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.51	14.76	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:1	19.09	2579	1.36	13.43	99	196	Idle	63.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.5	14.72	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:1	19.09	2576	1.36	13.44	99	196	Idle	63.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	14.7	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:1	19.09	2576	1.36	13.44	99	196	Idle	63.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.48	14.69	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:1	19.09	2553	1.36	13.44	99	196	Idle	62.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.45	14.71	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:1	19.09	2548	1.36	13.44	99	196	Idle	62.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.45	14.71	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:1	19.09	2518	1.35	13.44	99	196	Idle	62.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.41	14.7	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:1	19.09	2518	1.35	13.43	99	196	Idle	62.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.39	14.71	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:2	19.09	2507	1.35	13.44	99	196	Idle	62.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.35	14.72	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:2	19.09	2482	1.35	13.45	99	196	Idle	62.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.36	14.73	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:2	19.09	2482	1.35	13.44	99	196	Idle	62.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.34	14.74	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:2	19.09	2482	1.35	13.45	99	196	Idle	62.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.31	14.73	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:2	19.09	2479	1.35	13.44	99	196	Idle	62	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.29	14.74	1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:2	19.09	2503	1.36	13.45	99	196	Idle	61.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.28	14.79	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:3	19.09	2503	1.36	13.45	99	196	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	14.84	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:3	19.09	2486	1.36	13.45	99	196	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	14.91	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:3	19.09	2494	1.37	13.44	99	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	15	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:3	19.09	2498	1.37	13.45	99	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	15.11	1.03	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:3	19.09	2499	1.37	13.45	99	196	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	15.26	1.04	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:54:3	19.09	2501	1.37	13.45	99	196	Idle	61.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	15.48	1.05	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:4	19.09	2500	1.37	13.45	99	196	Idle	61.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	15.78	1.08	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:4	19.09	2498	1.37	13.45	99	196	Idle	61.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	16.2	1.1	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:4	19.09	2492	1.37	13.44	99	196	Idle	61.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	16.66	1.13	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:4	19.09	2487	1.37	13.46	99	196	Idle	61.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.2	17.4	1.19	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:4	19.09	2487	1.37	13.46	99	196	Idle	62.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.21	17.65	1.2	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:4	19.09	2476	1.37	13.47	99	196	Idle	62.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	17.89	1.22	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:4	19.09	2464	1.37	13.46	99	196	Idle	62.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	18.59	1.27	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:5	19.09	2462	1.37	13.45	99	196	Idle	63.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	19.03	1.3	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:5	19.09	2454	1.36	13.45	99	196	Idle	63.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	19.22	1.31	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:5	19.09	2446	1.36	13.44	99	196	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	19.73	1.34	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:5	19.09	2446	1.36	13.44	99	196	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	19.98	1.36	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:5	19.09	2442	1.35	13.44	99	196	Idle	65	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.16	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:5	19.09	2431	1.35	13.45	99	196	Idle	65.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.19	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:6	19.09	2441	1.34	13.44	99	196	Idle	65.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:6	19.09	2442	1.34	13.44	99	196	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:6	17.72	2436	1.34	13.44	99	196	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:6	17.72	2445	1.33	13.45	99	196	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:6	17.72	2445	1.32	13.44	99	196	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:6	17.72	2446	1.32	13.43	99	195	Idle	66.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:6	17.72	2436	1.31	13.43	99	195	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:7	17.72	2443	1.31	13.43	99	195	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:7	17.72	2442	1.3	13.43	99	196	Idle	67.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:7	17.72	2446	1.3	13.44	99	196	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:7	17.72	2433	1.29	13.44	99	196	Idle	67.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:7	17.72	2433	1.29	13.44	99	196	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:7	17.72	2425	1.29	13.43	99	196	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:8	17.72	2421	1.28	13.44	99	196	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:8	17.72	2416	1.28	13.43	99	196	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:8	17.72	2414	1.28	13.44	99	196	Idle	67.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:8	17.72	2406	1.28	13.44	99	196	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:8	17.72	2402	1.27	13.44	99	196	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:8	17.72	2410	1.27	13.43	99	196	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:9	17.72	2397	1.27	13.44	99	196	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:9	17.72	2376	1.27	13.43	99	196	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:9	17.72	2376	1.26	13.43	99	196	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:9	17.72	2392	1.26	13.44	99	196	Idle	68.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:9	17.72	2386	1.26	13.44	99	196	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:9	17.72	2393	1.26	13.43	99	196	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:54:9	17.72	2389	1.25	13.44	99	196	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:0	17.72	2383	1.25	13.43	99	196	Idle	68.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:0	17.72	2380	1.25	13.43	99	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:0	17.72	2379	1.25	13.43	99	196	Idle	69.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:0	17.72	2374	1.24	13.44	99	196	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:0	17.72	2369	1.24	13.45	99	196	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:0	17.72	2368	1.23	13.45	99	196	Idle	69.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:1	17.72	2363	1.23	13.42	99	196	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:1	17.72	2357	1.23	13.4	99	196	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:1	17.72	2356	1.23	13.38	99	196	Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:1	17.72	2372	1.22	13.36	99	196	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:1	17.72	2342	1.22	13.36	99	196	Idle	71	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:1	17.72	2348	1.21	13.37	99	196	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:1	17.72	2348	1.21	13.37	99	196	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:2	17.72	2347	1.2	13.39	99	196	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:2	17.72	2344	1.2	13.4	99	196	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:2	17.72	2344	1.2	13.4	99	196	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:2	17.72	2340	1.19	13.4	99	196	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:2	17.72	2338	1.19	13.4	99	196	Idle	72.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:55:2	17.72	2344	1.18	13.4	99	196	Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.25	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:3	17.72	2337	1.18	13.39	99	196	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:3	17.72	2331	1.17	13.39	99	196	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:3	17.72	2330	1.17	13.4	99	196	Idle	73	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:3	17.72	2326	1.17	13.38	99	196	Idle	73.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:3	17.72	2308	1.17	13.39	99	196	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:3	17.72	2317	1.16	13.39	99	196	Idle	73.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:4	17.72	2316	1.16	13.38	99	196	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:4	17.72	2309	1.16	13.39	99	196	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:4	17.72	2304	1.15	13.4	99	196	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:4	17.72	2304	1.15	13.39	99	196	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:4	17.72	2300	1.15	13.4	99	196	Idle	73.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:4	17.72	2297	1.15	13.41	99	196	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:4	17.72	2291	1.14	13.4	99	196	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:5	17.72	2291	1.14	13.4	99	196	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:5	17.72	2288	1.14	13.4	99	196	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:5	17.72	2283	1.14	13.41	99	196	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:5	17.72	2282	1.13	13.41	99	196	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:5	17.72	2279	1.13	13.4	99	196	Idle	74.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:5	17.72	2277	1.13	13.4	99	196	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:6	17.72	2276	1.13	13.4	99	196	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:6	17.72	2270	1.13	13.39	99	196	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:6	17.72	2264	1.12	13.4	99	196	Idle	75.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:6	17.72	2259	1.12	13.41	99	196	Idle	75.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:6	17.72	2259	1.12	13.4	99	196	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:6	17.72	2244	1.11	13.41	99	196	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:6	17.72	2246	1.11	13.4	99	196	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:7	17.72	2253	1.11	13.39	99	196	Idle	76.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:7	17.72	2237	1.11	13.39	99	196	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:7	17.72	2231	1.11	13.38	99	196	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:7	17.72	2228	1.1	13.37	99	196	Idle	76.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.21	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:7	17.72	2218	1.1	13.38	99	196	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:7	17.72	2220	1.1	13.39	99	196	Idle	76.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:8	17.72	2214	1.1	13.39	99	196	Idle	76.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:8	17.72	2214	1.09	13.4	99	196	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:8	17.72	2210	1.09	13.39	99	196	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:8	17.72	2207	1.09	13.38	99	196	Idle	77.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:8	17.72	2207	1.08	13.39	99	196	Idle	77.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:8	17.72	2194	1.08	13.39	99	196	Idle	78.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:9	17.72	2198	1.07	13.39	99	196	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:9	17.72	2195	1.07	13.4	99	196	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:9	17.72	2195	1.07	13.39	99	196	Idle	78.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:9	17.72	2190	1.06	13.36	99	196	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:9	17.72	2186	1.06	13.35	99	196	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:9	17.72	2178	1.06	13.36	99	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:55:9	17.72	2189	1.05	13.35	99	196	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:0	17.72	2164	1.05	13.36	99	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:0	17.72	2166	1.05	13.37	99	196	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:0	17.72	2166	1.04	13.36	99	196	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:0	17.72	2164	1.04	13.36	99	196	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:0	17.72	2156	1.03	13.36	99	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:0	17.72	2149	1.03	13.36	99	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:1	17.72	2149	1.03	13.37	99	196	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:1	17.72	2145	1.02	13.38	99	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:1	17.72	2137	1.02	13.39	99	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:1	17.72	2137	1.01	13.37	99	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:1	17.72	2130	1.01	13.36	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:1	17.72	2121	1.01	13.35	99	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:56:1	17.72	2121	1.01	13.35	99	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:2	17.72	2099	1.01	13.37	99	195	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:2	17.72	2099	1.01	13.38	99	195	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.63	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:2	17.72	2099	1	13.39	99	195	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:2	17.72	2085	1	13.39	99	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:2	17.72	2085	1	13.38	99	196	Idle	82.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.66	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:2	17.72	2080	1	13.37	99	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:3	17.72	2074	1	13.37	99	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:3	17.72	2074	0.99	13.36	99	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:3	17.72	2068	0.99	13.37	99	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:3	17.72	2062	0.99	13.38	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:3	17.72	2057	0.99	13.39	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:3	17.72	2046	0.99	13.39	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.61	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:4	17.72	2045	0.99	13.39	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:4	17.72	2040	0.99	13.4	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.64	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:4	17.72	2038	0.99	13.41	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.62	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:4	17.72	2032	0.99	13.41	99	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:4	17.72	2029	0.99	13.42	99	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:4	17.72	2024	0.99	13.41	99	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:4	17.72	2024	0.99	13.41	99	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:5	17.72	2020	0.99	13.39	99	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:5	17.72	2016	0.99	13.38	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:5	17.72	2015	0.99	13.37	99	196	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:5	17.72	2010	0.99	13.36	99	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:5	17.72	2005	0.99	13.36	99	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:5	17.72	2002	0.99	13.36	99	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:6	17.72	1992	0.99	13.36	99	196	Idle	82.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:6	17.72	1986	0.99	13.35	99	196	Idle	82.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-10.54	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:6	17.72	1971	0.99	13.36	99	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:6	17.72	1971	0.99	13.37	99	196	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:6	17.72	1959	0.98	13.38	99	196	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:6	17.72	1948	0.98	13.39	99	196	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.59	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:6	17.72	1948	0.98	13.39	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.57	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:7	17.72	1931	0.98	13.39	99	196	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:7	17.72	1929	0.98	13.38	99	196	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:7	17.72	1929	0.98	13.37	99	196	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:7	17.72	1920	0.98	13.36	99	196	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:7	17.72	1912	0.98	13.35	99	196	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:7	17.72	1912	0.99	13.34	99	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:8	17.72	1902	0.99	13.35	99	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:8	17.72	1898	0.99	13.35	99	196	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:8	17.72	1887	0.99	13.35	99	196	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:8	17.72	1887	0.99	13.34	99	196	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:8	17.72	1879	0.99	13.35	99	196	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:8	17.72	1869	0.99	13.36	99	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:9	17.72	1864	0.99	13.37	99	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:9	17.72	1852	0.99	13.37	99	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:9	17.72	1840	0.99	13.37	99	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:9	17.72	1828	1	13.36	99	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:9	17.72	1828	1	13.36	99	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:9	17.72	1818	1	13.35	99	196	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:56:9	17.72	1797	1	13.36	99	196	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:0	17.72	1800	1	13.36	99	196	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:0	17.72	1796	1	13.36	99	196	Idle	80	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:0	17.72	1786	1	13.35	99	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:0	17.72	1777	1	13.35	99	196	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:0	17.72	1769	1.01	13.35	99	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:0	17.72	1764	1.01	13.33	99	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.24	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:57:1	17.72	1753	1.01	13.34	99	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.23	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:1	17.72	1744	1.01	13.35	99	196	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.26	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:1	17.72	1744	1.01	13.33	99	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.22	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:1	17.72	1730	1.01	13.35	99	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:1	17.72	1720	1.01	13.35	99	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:1	17.72	1720	1.01	13.34	99	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:1	17.72	1706	1.01	13.33	99	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:2	17.72	1695	1.01	13.36	99	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:2	17.72	1695	1.01	13.36	99	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:2	17.72	1682	1.01	13.38	99	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	20.22	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:2	17.72	1667	1.01	13.38	99	196	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.21	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:2	17.72	1656	1.01	13.37	99	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.21	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:2	17.72	1649	1.01	13.38	99	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:3	17.72	1637	1.01	13.39	99	196	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:3	17.72	1637	1.01	13.38	99	196	Idle	79.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:3	17.72	1628	1.02	13.37	99	196	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:3	17.72	1616	1.02	13.38	99	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.21	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:3	17.72	1608	1.02	13.37	99	196	Idle	78.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:3	17.72	1592	1.02	13.38	99	196	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:4	17.72	1557	1.02	13.38	99	196	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:4	17.72	1557	1.02	13.38	99	196	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:4	17.72	1533	1.02	13.37	99	196	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.85	20.21	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:4	17.72	1496	1.02	13.37	99	196	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:4	17.72	1481	1.02	13.37	99	196	Idle	77.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.22	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:4	17.72	1481	1.02	13.38	99	196	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.74	20.22	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:4	17.72	1455	1.03	13.38	99	196	Idle	77.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.22	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:5	17.72	1428	1.03	13.38	99	196	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.58	20.22	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:5	17.72	1428	1.03	13.38	99	196	Idle	76.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.22	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:5	17.72	1390	1.03	13.37	99	196	Idle	76	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	20.22	1.38	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:5	17.72	1385	1.04	13.37	99	196	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.38	20.22	1.38	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:5	19.09	1385	1.04	13.37	99	196	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.34	20.22	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:6	19.09	1322	1.05	13.38	99	196	Idle	74.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.28	20.22	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:28:57:6	19.09	1298	1.05	13.37	99	196	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	20.22	1.38	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:57:6	17.72	1289	1.06	13.36	99	196	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.15	20.23	1.38	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:57:6	17.72	1289	1.07	13.37	99	196	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	20.23	1.38	4.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:28:57:6	17.72	1249	1.07	13.36	99	196	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.92	20.22	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:28:57:6	16.36	1220	1.08	13.34	99	196	Idle	72.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.83	20.22	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:28:57:6	16.36	1220	1.08	13.35	99	196	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.69	20.23	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:28:57:6	16.36	1198	1.09	13.36	99	196	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.58	20.22	1.38	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:57:7	16.36	1169	1.1	13.36	99	196	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.49	20.22	1.38	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:57:7	16.36	1169	1.1	13.36	99	196	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.4	20.22	1.38	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:28:57:7	16.36	1174	1.11	13.35	99	196	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.26	20.23	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:57:7	16.36	1171	1.11	13.35	99	196	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.17	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:57:7	16.36	1168	1.12	13.34	99	196	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.1	20.21	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:57:7	16.36	1170	1.12	13.35	99	196	Idle	72.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.04	20.22	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:57:8	16.36	1172	1.13	13.35	99	196	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.05	20.23	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:57:8	16.36	1171	1.13	13.35	99	196	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.99	20.23	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:57:8	16.36	1171	1.13	13.35	99	196	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8	20.22	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:57:8	16.36	1189	1.13	13.35	99	196	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.99	20.22	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:57:8	14.99	1189	1.13	13.34	99	196	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.97	20.22	1.38	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:57:8	14.99	1219	1.12	13.33	99	196	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.99	20.23	1.38	4.3	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:57:9	14.99	1219	1.12	13.34	99	196	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.01	20.23	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:57:9	14.99	1214	1.11	13.35	99	196	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.04	20.23	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:57:9	14.99	1226	1.09	13.34	99	196	Idle	80.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.09	20.23	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:57:9	14.99	1226	1.08	13.36	99	196	Idle	81.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.14	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:57:9	14.99	1224	1.08	13.35	99	196	Idle	82.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.17	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:57:9	14.99	1213	1.07	13.35	99	196	Idle	83.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.21	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:57:9	14.99	1205	1.06	13.35	99	196	Idle	84.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.25	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:58:0	13.63	1218	1.04	13.34	99	196	Idle	85	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.28	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:58:0	13.63	1231	1.03	13.34	99	196	Idle	85.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.3	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:58:0	13.63	1198	1.02	13.35	99	196	Idle	86.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.34	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:58:0	13.63	1185	1.01	13.35	99	196	Idle	87	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.37	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:58:0	13.63	1185	1	13.36	99	196	Idle	87.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.41	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:58:0	13.63	1176	0.99	13.36	99	196	Idle	87.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.44	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:58:1	13.63	1157	0.98	13.38	99	196	Idle	87.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.44	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:58:1	14.99	1157	0.97	13.37	99	196	Idle	87.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.45	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:58:1	14.99	1149	0.96	13.38	99	196	Idle	87.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.47	20.23	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:28:58:1	14.99	1149	0.95	13.38	99	196	Idle	88.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.5	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:1	14.99	1145	0.94	13.37	99	196	Idle	88.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.49	20.23	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:1	14.99	1141	0.94	13.38	99	196	Idle	88.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:1	14.99	1137	0.93	13.37	99	196	Idle	89.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:2	14.99	1124	0.93	13.37	99	196	Idle	89.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:2	14.99	1109	0.92	13.37	99	196	Idle	89.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.52	20.23	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:2	14.99	1109	0.92	13.37	99	196	Idle	89.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.54	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:2	14.99	1099	0.91	13.38	99	196	Idle	90.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.54	20.23	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:2	13.63	1099	0.91	13.38	99	196	Idle	90.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.54	20.24	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:2	13.63	1090	0.9	13.38	99	196	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.54	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:3	13.63	1091	0.9	13.37	99	196	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.51	20.22	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:3	13.63	1084	0.89	13.37	99	196	Idle	91.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:3	13.63	1084	0.89	13.38	99	196	Idle	91.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.51	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:3	13.63	1075	0.89	13.36	99	196	Idle	91.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.51	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:3	13.63	1055	0.88	13.39	99	196	Idle	92.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	20.23	1.38	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:3	13.63	1055	0.88	13.38	99	196	Idle	92.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	20.22	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:4	13.63	1050	0.88	13.38	99	196	Idle	92.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.52	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:4	13.63	1045	0.87	13.37	99	196	Idle	92.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.47	20.16	1.37	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:4	13.63	1045	0.87	13.36	99	196	Idle	92.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.49	20.04	1.37	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:4	13.63	1046	0.87	13.36	99	196	Idle	92.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.46	19.79	1.35	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:4	13.63	1038	0.86	13.34	99	196	Idle	92.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.47	19.57	1.33	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:4	13.63	1038	0.86	13.35	99	196	Idle	92.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.46	19.44	1.32	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:4	12.27	1028	0.86	13.35	99	196	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.48	19.15	1.3	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:5	12.27	1018	0.86	13.36	99	196	Idle	93.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.47	18.66	1.27	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:5	12.27	1018	0.85	13.36	99	196	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.41	18.32	1.25	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:5	12.27	1014	0.85	13.36	99	196	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.44	17.96	1.22	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:5	12.27	1014	0.85	13.35	99	196	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.38	17.62	1.2	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:5	12.27	1011	0.85	13.36	99	196	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.42	17.32	1.18	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:5	12.27	1008	0.84	13.35	99	196	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.37	17.08	1.16	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:6	12.27	1008	0.84	13.36	99	196	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	16.89	1.15	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:6	12.27	994	0.84	13.35	99	196	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.36	16.72	1.14	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:6	12.27	979	0.84	13.35	99	196	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.41	16.59	1.13	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:6	12.27	979	0.84	13.37	99	196	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.35	16.51	1.12	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:6	12.27	980	0.83	13.35	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.39	16.43	1.12	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:6	12.27	980	0.83	13.36	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.34	16.36	1.11	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:6	12.27	980	0.83	13.37	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.36	16.34	1.11	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:28:58:7	12.27	972	0.83	13.35	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.25	16.31	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:7	10.9	957	0.83	13.35	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.23	16.28	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:7	10.9	957	0.83	13.36	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	16.26	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:7	10.9	960	0.83	13.34	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	16.25	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:7	10.9	963	0.83	13.36	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.21	16.24	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:7	10.9	959	0.83	13.34	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.19	16.24	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:8	10.9	959	0.83	13.36	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.19	16.23	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:8	10.9	953	0.82	13.33	99	196	Idle	93	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.18	16.23	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:8	10.9	947	0.82	13.34	99	196	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.15	16.22	1.11	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:8	10.9	954	0.82	13.33	99	196	Idle	93.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.15	16.22	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:8	10.9	954	0.82	13.36	99	196	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.13	16.21	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:8	10.9	953	0.82	13.34	99	196	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.12	16.18	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:9	10.9	952	0.82	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.08	16.17	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:58:9	9.54	948	0.82	13.35	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.08	16.14	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:9	9.54	948	0.82	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.05	16.12	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:9	9.54	955	0.82	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.08	16.08	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:9	9.54	955	0.82	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.05	16.05	1.09	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:9	9.54	940	0.82	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.08	16.01	1.09	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:58:9	9.54	924	0.82	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.08	15.97	1.09	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:59:0	9.54	928	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.08	15.94	1.09	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:59:0	9.54	928	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.05	15.88	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:0	8.18	926	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.02	15.85	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:0	8.18	923	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.99	15.81	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:0	8.18	936	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8	15.77	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:0	8.18	936	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.95	15.75	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:1	8.18	926	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.96	15.73	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:1	8.18	915	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.92	15.71	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:1	8.18	921	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.95	15.7	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:1	8.18	921	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.89	15.68	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:1	9.54	920	0.81	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.92	15.67	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:1	9.54	920	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.89	15.66	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:1	9.54	915	0.81	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.91	15.66	1.07	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:59:2	9.54	915	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.86	15.65	1.07	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:59:2	8.18	908	0.81	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.89	15.65	1.07	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:59:2	8.18	901	0.81	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.84	15.64	1.07	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:59:2	8.18	901	0.81	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.87	15.63	1.06	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:59:2	8.18	910	0.81	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.82	15.63	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:2	8.18	910	0.81	13.33	99	196	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.86	15.64	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:3	9.54	914	0.81	13.32	99	196	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.83	15.63	1.07	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:3	9.54	917	0.81	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.88	15.62	1.06	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:3	9.54	900	0.81	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.82	15.62	1.06	5.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:3	9.54	867	0.81	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.85	15.6	1.06	5.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:3	8.18	867	0.81	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.84	15.59	1.06	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:3	8.18	867	0.81	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.83	15.57	1.06	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:4	8.18	895	0.81	13.35	99	196	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.8	15.56	1.06	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:4	8.18	895	0.8	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.8	15.52	1.06	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:4	9.54	884	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.76	15.49	1.06	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:4	9.54	873	0.8	13.35	99	196	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.77	15.47	1.05	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:4	9.54	886	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.76	15.45	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:4	9.54	886	0.8	13.35	99	196	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.76	15.42	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:4	9.54	884	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.76	15.39	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:5	9.54	883	0.8	13.35	99	196	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.72	15.38	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:5	9.54	883	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.73	15.36	1.05	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:5	9.54	904	0.8	13.35	99	196	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.7	15.34	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:5	9.54	904	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.72	15.31	1.04	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:5	9.54	886	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.72	15.27	1.04	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:5	9.54	886	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.76	15.25	1.04	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:28:59:6	9.54	898	0.8	13.32	99	196	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	15.22	1.04	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:6	9.54	898	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.73	15.2	1.04	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:6	8.18	903	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.7	15.18	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:6	8.18	908	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.72	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:6	8.18	900	0.8	13.33	99	196	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.68	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:6	8.18	900	0.8	13.35	99	196	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.7	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:6	8.18	902	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.7	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:7	8.18	905	0.8	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.69	15.09	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:7	8.18	904	0.8	13.34	99	196	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:7	8.18	904	0.8	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.69	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:7	8.18	903	0.8	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.72	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:7	8.18	903	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.73	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:7	8.18	888	0.8	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.73	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:8	8.18	888	0.8	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.75	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:28:59:8	8.18	890	0.8	13.36	99	196	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.74	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:8	8.18	892	0.8	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:8	8.18	892	0.8	13.37	99	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:8	8.18	881	0.8	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:8	8.18	878	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:9	9.54	876	0.8	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.64	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:9	9.54	876	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:9	9.54	869	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:9	9.54	869	0.81	13.42	99	196	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.65	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:9	8.18	874	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.61	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:9	8.18	879	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:59:9	8.18	871	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:0	8.18	871	0.81	13.42	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.63	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:0	8.18	874	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.62	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:0	8.18	877	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.6	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:0	8.18	865	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.6	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:0	8.18	865	0.81	13.41	99	196	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.56	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:0	8.18	871	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.59	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:1	8.18	877	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.58	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:1	8.18	877	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.6	14.99	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:1	8.18	866	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:1	8.18	866	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.61	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:1	8.18	858	0.81	13.38	99	196	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.58	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:1	8.18	858	0.81	13.4	99	196	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.55	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:1	8.18	857	0.81	13.39	99	196	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.59	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:2	8.18	856	0.81	13.39	99	196	Full Load	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.53	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:2	8.18	856	0.81	13.38	99	196	Off Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.55	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:2	8.18	846	0.82	13.38	99	196	Off Idle	93.2	0	2	132	944 Turbo	0.49	Rich	1	14.7	-7.46	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:2	8.18	850	0.83	13.37	99	196	Off Idle	92.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.43	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:2	8.18	854	0.84	13.38	99	196	Off Idle	92.1	0	2	132	944 Turbo	0.39	Rich	1	14.7	-7.32	14.96	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:2	8.18	854	0.86	13.37	99	196	Off Idle	91.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.27	14.96	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:3	9.54	855	0.88	13.39	99	196	Off Idle	90.9	0	2	132	944 Turbo	0.31	Lean	1	14.7	-7.15	14.96	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:3	9.54	855	0.9	13.39	99	196	Off Idle	90.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.03	14.95	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:3	9.54	850	0.94	13.38	99	196	Off Idle	88.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.89	14.93	1.02	4.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:3	9.54	844	0.95	13.39	99	196	Off Idle	88.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.75	14.93	1.02	4.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:3	9.54	849	0.97	13.4	99	196	Off Idle	87.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.59	14.93	1.02	4.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:3	10.9	854	1	13.38	99	196	Off Idle	87.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.4	14.91	1.02	4.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:4	10.9	854	1.04	13.38	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.15	Lean	1	14.7	-6.19	14.88	1.01	4.8	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:4	10.9	848	1.06	13.37	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.7	-6.01	14.86	1.01	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:00:4	10.9	860	1.09	13.39	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.13	Lean	1	14.7	-5.88	14.85	1.01	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:00:4	9.54	860	1.11	13.37	99	196	Off Idle	84.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.77	14.85	1.01	4.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:00:4	9.54	871	1.15	13.39	99	196	Off Idle	84	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.6	14.85	1.01	4.9	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:00:4	9.54	889	1.18	13.37	99	196	Off Idle	84	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.4	14.85	1.01	4.8	4	ON	28 Pin	OFF	Removed	Disabled
03:29:00:4	9.54	889	1.22	13.39	99	196	Off Idle	84	0	2	132	944 Turbo	0.11	Lean	1	14.7	-5.29	14.84	1.01	4.8	4	ON	28 Pin	OFF	Removed	Disabled
03:29:00:5	9.54	902	1.25	13.37	99	196	Off Idle	84	0	2	132	944 Turbo	0.11	Lean	1	14.7	-5.13	14.83	1.01	4.7	4	ON	28 Pin	OFF	Removed	Disabled
03:29:00:5	9.54	915	1.31	13.41	99	196	Off Idle	84.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.01	14.83	1.01	4.7	4	ON	28 Pin	OFF	Removed	Disabled
03:29:00:5	9.54	929	1.32	13.39	99	196	Off Idle	84.3	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.83	14.83	1.01	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:5	9.54	929	1.37	13.42	99	196	Off Idle	84.4	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.63	14.85	1.01	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:5	9.54	968	1.39	13.41	99	196	Off Idle	84.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.44	14.88	1.01	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:5	9.54	968	1.4	13.41	99	196	Off Idle	84.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.35	14.88	1.01	4.6	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:00:6	9.54	1038	1.44	13.42	99	196	Off Idle	84.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.11	14.87	1.01	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:6	20.45	1038	1.48	13.46	99	196	Off Idle	84.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.98	14.88	1.01	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:6	20.45	1009	1.49	13.44	99	196	Off Idle	84.8	0	2	132	944 Turbo	0.25	Lean	1	14.7	-3.74	14.91	1.02	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:6	20.45	1026	1.55	13.43	99	196	Off Idle	85.1	0	2	132	944 Turbo	0.35	Lean	1	14.6	-3.48	14.96	1.02	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:6	20.45	1043	1.57	13.43	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.39	Lean	1	14.7	-3.2	14.97	1.02	4.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:00:6	20.45	1043	1.61	13.43	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.5	Lean	1	14.7	-2.91	15	1.02	4.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:00:6	20.45	1079	1.64	13.42	99	196	Off Idle	85.3	0	2	132	944 Turbo	0.57	Lean	1	14.7	-2.76	15.02	1.02	4.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:00:7	20.45	1105	1.67	13.42	99	196	Off Idle	85.4	0	2	132	944 Turbo	0.65	Lean	1	14.6	-2.57	15.04	1.02	4.3	5.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:00:7	20.45	1133	1.69	13.44	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.72	Lean	1	14.6	-2.4	15.06	1.03	4.2	5.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:7	20.45	1133	1.71	13.41	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.23	15.11	1.03	4.2	5.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:7	20.45	1173	1.74	13.41	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.12	15.14	1.03	4.2	5.2	ON	28 Pin	OFF	Removed	Disabled
03:29:00:7	20.45	1173	1.77	13.43	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.01	15.15	1.03	4.4	5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:7	20.45	1173	1.78	13.41	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.99	15.17	1.03	4.4	5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:8	20.45	1191	1.8	13.41	99	196	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.97	15.21	1.04	4.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:00:8	20.45	1191	1.82	13.41	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.96	15.18	1.03	4.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:00:8	21.81	1215	1.83	13.42	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.96	15.12	1.03	4.3	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:00:8	21.81	1223	1.85	13.41	99	196	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.01	14.97	1.02	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:8	21.81	1218	1.86	13.41	99	196	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.96	14.84	1.01	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:8	21.81	1218	1.87	13.41	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.99	14.69	1	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:9	21.81	1220	1.88	13.41	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.97	14.54	0.99	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:9	21.81	1221	1.88	13.39	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.96	14.36	0.98	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:9	21.81	1220	1.88	13.39	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.95	14.17	0.97	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:9	21.81	1213	1.88	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.96	13.94	0.95	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:9	21.81	1208	1.88	13.37	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.95	13.74	0.94	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:9	21.81	1202	1.88	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.94	13.56	0.92	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:00:9	21.81	1192	1.88	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.93	13.32	0.91	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:01:0	21.81	1188	1.87	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.89	13.19	0.9	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:0	21.81	1186	1.87	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.9	13.13	0.89	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:0	21.81	1184	1.87	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.86	12.93	0.88	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:0	21.81	1168	1.87	13.37	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.86	12.82	0.87	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:01:0	21.81	1168	1.87	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.82	12.66	0.86	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:01:0	21.81	1166	1.87	13.36	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.77	12.56	0.86	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:01:1	21.81	1170	1.87	13.37	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.78	12.49	0.85	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:1	21.81	1170	1.87	13.36	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.71	12.45	0.85	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:1	24.54	1171	1.87	13.37	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.7	12.37	0.84	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:1	24.54	1152	1.87	13.37	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.7	12.33	0.84	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:1	24.54	1131	1.87	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.7	12.27	0.84	4.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:1	23.18	1131	1.87	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.68	12.23	0.83	4.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:1	23.18	1146	1.86	13.39	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.64	12.19	0.83	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:2	23.18	1120	1.86	13.39	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.64	12.18	0.83	4.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:2	23.18	1118	1.86	13.39	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.61	12.17	0.83	4.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:2	23.18	1118	1.86	13.37	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.56	12.19	0.83	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:2	23.18	1091	1.86	13.38	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.6	12.23	0.83	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:2	23.18	1091	1.85	13.4	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.55	12.24	0.83	4.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:01:2	23.18	1082	1.85	13.38	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.57	12.3	0.84	4.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:01:3	23.18	1074	1.84	13.41	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.57	12.35	0.84	4.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:01:3	23.18	1059	1.84	13.38	99	196	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.51	12.39	0.84	4.7	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:01:3	23.18	1042	1.84	13.38	99	196	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.51	12.44	0.85	4.7	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:01:3	23.18	1042	1.83	13.38	99	196	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.43	12.48	0.85	4.8	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:01:3	23.18	1033	1.83	13.39	99	196	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.44	12.53	0.85	4.8	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:01:3	23.18	1024	1.82	13.38	99	196	Off Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.35	12.57	0.86	4.9	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:4	23.18	1024	1.82	13.39	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.42	12.61	0.86	4.9	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:4	23.18	1003	1.81	13.4	99	196	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.31	12.63	0.86	5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:4	23.18	978	1.8	13.41	99	196	Off Idle	85.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.36	12.66	0.86	4.9	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:4	23.18	978	1.8	13.39	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.25	12.69	0.86	4.7	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:4	21.81	978	1.79	13.41	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.26	12.73	0.87	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:4	21.81	978	1.78	13.43	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.22	12.74	0.87	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:4	21.81	979	1.77	13.39	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.25	12.75	0.87	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:5	21.81	979	1.77	13.42	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.2	12.75	0.87	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:5	21.81	975	1.76	13.39	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.25	12.76	0.87	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:5	21.81	975	1.76	13.42	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.22	12.77	0.87	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:5	21.81	982	1.75	13.4	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.27	12.77	0.87	4.6	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:5	21.81	990	1.74	13.44	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.28	12.76	0.87	4.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:5	21.81	1016	1.74	13.42	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.27	12.76	0.87	4.5	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:6	21.81	1040	1.74	13.45	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.27	12.74	0.87	4.4	4.8	ON	28 Pin	OFF	Removed	Disabled
03:29:01:6	21.81	1040	1.74	13.41	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.23	12.73	0.87	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:01:6	19.09	1048	1.74	13.42	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.27	12.72	0.87	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:6	19.09	1057	1.74	13.43	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.21	12.7	0.87	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:6	19.09	1105	1.74	13.41	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.26	12.69	0.86	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:6	19.09	1105	1.74	13.43	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.24	12.66	0.86	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:6	19.09	1125	1.75	13.42	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.28	12.64	0.86	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:7	19.09	1150	1.75	13.42	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.28	12.63	0.86	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:01:7	19.09	1150	1.76	13.39	99	196	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.31	12.62	0.86	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:7	20.45	1163	1.76	13.39	99	196	Off Idle	85.8	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.32	12.6	0.86	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:7	20.45	1168	1.77	13.38	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.36	12.59	0.86	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:7	20.45	1172	1.78	13.37	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.34	12.58	0.86	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:7	20.45	1172	1.79	13.36	99	196	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.37	12.56	0.86	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:8	20.45	1187	1.8	13.39	99	196	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.4	12.55	0.86	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:8	20.45	1200	1.81	13.37	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.42	12.53	0.85	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:8	20.45	1213	1.82	13.38	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.44	12.5	0.85	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:8	20.45	1213	1.83	13.4	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.45	12.48	0.85	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:8	20.45	1214	1.83	13.4	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.46	12.46	0.85	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:8	20.45	1227	1.85	13.4	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.44	12.43	0.85	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:9	20.45	1227	1.86	13.4	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.45	12.42	0.85	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:01:9	20.45	1252	1.86	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.43	12.4	0.84	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:01:9	21.81	1241	1.88	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.41	12.37	0.84	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:01:9	21.81	1241	1.89	13.4	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.36	12.35	0.84	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:01:9	21.81	1253	1.89	13.4	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.34	12.33	0.84	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:01:9	21.81	1261	1.9	13.42	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.3	12.33	0.84	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:01:9	21.81	1269	1.91	13.42	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.3	12.34	0.84	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:02:0	21.81	1274	1.92	13.4	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.25	12.36	0.84	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:02:0	21.81	1286	1.93	13.39	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.24	12.38	0.84	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:02:0	21.81	1294	1.94	13.39	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.2	12.4	0.84	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:02:0	21.81	1312	1.95	13.37	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.17	12.45	0.85	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:02:0	21.81	1322	1.96	13.38	99	196	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.17	12.5	0.85	4.3	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:02:0	21.81	1322	1.96	13.39	99	196	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.2	12.56	0.86	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:02:1	21.81	1358	1.97	13.38	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.18	12.61	0.86	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:1	21.81	1362	1.98	13.39	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.2	12.69	0.86	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:1	21.81	1375	1.99	13.41	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.26	12.75	0.87	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:1	21.81	1400	2	13.4	99	196	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.26	12.8	0.87	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:1	21.81	1400	2	13.41	99	196	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.25	12.86	0.88	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:1	21.81	1401	2.01	13.42	99	196	Off Idle	86.7	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.31	12.89	0.88	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:1	21.81	1412	2.01	13.42	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.26	12.93	0.88	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:2	21.81	1412	2.02	13.42	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-1.26	12.98	0.88	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:2	21.81	1435	2.03	13.43	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.26	13	0.89	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:2	24.54	1447	2.04	13.42	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.28	13.03	0.89	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:2	24.54	1447	2.04	13.42	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.23	13.06	0.89	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:2	24.54	1455	2.05	13.42	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.23	13.09	0.89	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:2	24.54	1446	2.06	13.41	99	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.23	13.11	0.89	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:3	24.54	1468	2.07	13.42	99	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.25	13.13	0.89	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:3	24.54	1472	2.07	13.41	99	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.3	13.14	0.9	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:3	24.54	1486	2.08	13.43	99	196	Off Idle	86.9	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.27	13.17	0.9	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:3	24.54	1492	2.08	13.41	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.83	Rich	1	14.7	-1.26	13.19	0.9	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:3	24.54	1492	2.09	13.42	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.28	13.22	0.9	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:02:3	24.54	1502	2.1	13.42	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.3	13.23	0.9	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:4	24.54	1502	2.1	13.41	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.28	13.24	0.9	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:4	24.54	1520	2.11	13.43	99	196	Off Idle	86.8	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.31	13.27	0.9	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:4	24.54	1524	2.12	13.43	99	196	Off Idle	86.7	0	2	132	944 Turbo	0.82	Rich	1	14.7	-1.31	13.3	0.91	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:4	24.54	1532	2.12	13.43	99	196	Off Idle	86.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.29	13.35	0.91	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:4	24.54	1545	2.12	13.44	99	196	Off Idle	86.7	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.31	13.37	0.91	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:4	24.54	1560	2.13	13.43	99	196	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.33	13.43	0.92	4.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:4	24.54	1573	2.14	13.43	99	196	Off Idle	86.6	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.3	13.48	0.92	4.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:5	24.54	1573	2.14	13.43	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.26	13.52	0.92	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:5	24.54	1584	2.15	13.41	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-1.29	13.57	0.92	4.1	4.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:02:5	24.54	1596	2.15	13.38	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.3	13.61	0.93	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:5	25.9	1602	2.16	13.38	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.32	13.68	0.93	4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:5	25.9	1614	2.17	13.36	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.33	13.72	0.93	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:5	25.9	1632	2.17	13.35	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.33	13.75	0.94	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:6	25.9	1662	2.18	13.37	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.34	13.79	0.94	3.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:02:6	25.9	1662	2.18	13.38	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.35	13.81	0.94	3.9	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:6	25.9	1667	2.19	13.38	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-1.38	13.83	0.94	3.9	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:6	25.9	1674	2.19	13.38	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.39	13.85	0.94	3.9	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:6	25.9	1680	2.2	13.39	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.4	13.87	0.95	3.9	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:6	25.9	1696	2.21	13.38	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.44	13.91	0.95	3.9	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:6	25.9	1706	2.21	13.38	99	196	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-1.48	13.95	0.95	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:7	25.9	1712	2.22	13.39	99	196	Off Idle	86.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-1.51	13.97	0.95	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:7	25.9	1724	2.22	13.39	99	196	Off Idle	86.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.54	14	0.95	3.8	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:7	25.9	1751	2.23	13.35	99	196	Off Idle	86.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.46	14.05	0.96	3.8	4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:7	25.9	1745	2.24	13.37	99	196	Off Idle	86.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.48	14.08	0.96	3.8	4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:7	27.27	1745	2.25	13.38	99	196	Off Idle	86.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.51	14.11	0.96	3.7	4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:7	27.27	1754	2.25	13.37	99	196	Off Idle	86.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.52	14.14	0.96	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:8	27.27	1769	2.26	13.37	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.53	14.17	0.97	3.7	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:02:8	27.27	1761	2.27	13.38	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.54	14.22	0.97	3.8	4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:8	27.27	1761	2.27	13.37	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.51	14.24	0.97	3.8	4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:8	27.27	1767	2.28	13.38	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.77	Rich	1	14.7	-1.5	14.28	0.97	3.8	4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:8	27.27	1776	2.29	13.38	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.46	14.29	0.97	3.8	4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:8	27.27	1784	2.29	13.37	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.7	-1.43	14.33	0.98	3.8	4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:9	27.27	1805	2.3	13.37	99	196	Off Idle	86.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-1.46	14.37	0.98	3.7	4	ON	28 Pin	OFF	Removed	Disabled
03:29:02:9	27.27	1817	2.3	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-1.45	14.41	0.98	3.7	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:02:9	27.27	1825	2.31	13.36	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.7	-1.46	14.44	0.98	3.7	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:02:9	27.27	1845	2.31	13.36	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.49	14.47	0.99	3.7	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:02:9	27.27	1859	2.31	13.37	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.71	Rich	1	14.7	-1.53	14.49	0.99	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:02:9	27.27	1866	2.32	13.36	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.7	Rich	1	14.7	-1.54	14.53	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:02:9	27.27	1880	2.33	13.38	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.69	Rich	1	14.7	-1.56	14.59	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:0	27.27	1887	2.33	13.39	99	196	Off Idle	86.2	0	2	132	944 Turbo	0.67	Rich	1	14.7	-1.61	14.6	0.99	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:0	27.27	1890	2.33	13.42	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.64	Rich	1	14.7	-1.65	14.66	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:0	27.27	1896	2.34	13.43	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.6	Rich	1	14.7	-1.69	14.7	1	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:0	28.63	1935	2.34	13.45	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.58	Rich	1	14.7	-1.7	14.72	1	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:0	28.63	1918	2.35	13.45	99	196	Off Idle	86.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-1.71	14.76	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:0	28.63	1924	2.35	13.45	99	196	Off Idle	86	0	2	132	944 Turbo	0.44	Lean	1	14.7	-1.73	14.77	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:1	28.63	1942	2.35	13.45	99	196	Off Idle	86	0	2	132	944 Turbo	0.38	Lean	1	14.6	-1.73	14.8	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:1	28.63	1950	2.36	13.45	99	196	Off Idle	86	0	2	132	944 Turbo	0.33	Lean	1	14.7	-1.7	14.84	1.01	3.6	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:1	28.63	1953	2.36	13.45	99	196	Off Idle	86	0	2	132	944 Turbo	0.27	Lean	1	14.6	-1.71	14.88	1.01	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:1	28.63	1964	2.37	13.45	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-1.71	14.91	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:1	28.63	1976	2.37	13.44	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.17	Lean	1	14.7	-1.72	14.96	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:1	28.63	1982	2.37	13.44	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.13	Lean	1	14.7	-1.74	15.02	1.02	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:1	28.63	1995	2.38	13.44	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.7	-1.76	15.06	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:2	28.63	2008	2.39	13.44	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.7	-1.78	15.13	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:2	28.63	2015	2.39	13.45	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.7	-1.8	15.19	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:2	28.63	2030	2.39	13.45	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.7	-1.8	15.25	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:2	28.63	2038	2.4	13.45	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.7	-1.82	15.27	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:2	28.63	2048	2.4	13.43	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.11	Lean	1	14.7	-1.84	15.31	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:2	29.99	2060	2.41	13.43	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.13	Lean	1	14.7	-1.85	15.32	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:3	29.99	2067	2.41	13.42	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.16	Lean	1	14.7	-1.85	15.34	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:3	29.99	2071	2.41	13.41	99	196	Off Idle	85.9	0	2	132	944 Turbo	0.2	Lean	1	14.7	-1.88	15.35	1.05	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:3	29.99	2084	2.42	13.39	99	196	Off Idle	85.8	0	2	132	944 Turbo	0.22	Lean	1	14.7	-1.92	15.3	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:3	29.99	2090	2.42	13.39	99	196	Off Idle	85.8	0	2	132	944 Turbo	0.24	Lean	1	14.7	-1.92	15.28	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:3	29.99	2111	2.43	13.37	99	196	Off Idle	85.8	0	2	132	944 Turbo	0.27	Lean	1	14.7	-1.96	15.25	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:3	29.99	2119	2.43	13.35	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.31	Lean	1	14.7	-1.94	15.23	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:4	29.99	2119	2.44	13.36	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.35	Lean	1	14.7	-1.9	15.23	1.04	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:4	29.99	2126	2.44	13.37	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.4	Rich	1	14.7	-1.91	15.17	1.03	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:03:4	29.99	2132	2.44	13.4	99	196	Off Idle	85.7	0	2	132	944 Turbo	0.42	Rich	1	14.7	-1.9	15.14	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:03:4	29.99	2136	2.45	13.39	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-1.94	15.09	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:4	29.99	2148	2.45	13.39	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.5	Rich	1	14.7	-1.92	15.07	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:4	29.99	2157	2.45	13.38	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.56	Rich	1	14.7	-1.96	15.05	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:4	29.99	2169	2.46	13.38	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.59	Rich	1	14.7	-1.98	15.05	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:5	29.99	2178	2.46	13.37	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.63	Rich	1	14.7	-2	15.02	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:5	29.99	2190	2.46	13.37	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-2	15	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:5	29.99	2196	2.47	13.37	99	196	Off Idle	85.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-1.99	14.95	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:5	29.99	2200	2.47	13.38	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-2.04	14.93	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:5	29.99	2213	2.47	13.37	99	196	Off Idle	85	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.99	14.91	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:5	29.99	2222	2.48	13.37	99	196	Off Idle	84.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-1.97	14.91	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:6	29.99	2232	2.48	13.37	99	196	Off Idle	84.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-1.97	14.93	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:6	31.36	2232	2.48	13.38	99	196	Off Idle	84	0	2	132	944 Turbo	0.66	Rich	1	14.7	-1.95	14.9	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:6	31.36	2260	2.49	13.39	99	196	Off Idle	83.7	0	2	132	944 Turbo	0.61	Rich	1	14.6	-1.97	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:6	31.36	2253	2.49	13.4	99	196	Off Idle	83.3	0	2	132	944 Turbo	0.55	Rich	1	14.7	-2.06	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:6	31.36	2267	2.49	13.4	99	196	Off Idle	83	0	2	132	944 Turbo	0.49	Rich	1	14.7	-2.06	14.84	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:6	31.36	2273	2.49	13.4	99	196	Off Idle	83	0	2	132	944 Turbo	0.46	Rich	1	14.7	-2.02	14.84	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:6	29.99	2288	2.5	13.4	99	196	Off Idle	82.2	0	2	132	944 Turbo	0.37	Rich	1	14.7	-2.1	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:7	29.99	2300	2.5	13.39	99	196	Off Idle	81.8	0	2	132	944 Turbo	0.31	Lean	1	14.7	-2.08	14.82	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:7	29.99	2303	2.5	13.41	99	196	Off Idle	81.3	0	2	132	944 Turbo	0.25	Lean	1	14.7	-2.06	14.83	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:7	29.99	2320	2.51	13.4	99	196	Off Idle	80.9	0	2	132	944 Turbo	0.17	Lean	1	14.7	-2.11	14.85	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:7	29.99	2350	2.51	13.39	99	196	Off Idle	80.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-2.14	14.9	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:7	31.36	2346	2.52	13.4	99	196	Off Idle	80	0	2	132	944 Turbo	0.11	Lean	1	14.7	-2.1	14.95	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:7	31.36	2346	2.52	13.41	99	196	Off Idle	79.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-2.12	14.99	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:8	31.36	2360	2.53	13.41	99	196	Off Idle	78.7	0	2	132	944 Turbo	0.1	Lean	1	14.7	-2.14	15.03	1.02	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:8	31.36	2391	2.53	13.41	99	196	Off Idle	78.3	0	2	132	944 Turbo	0.11	Lean	1	14.7	-2.13	15.05	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:8	31.36	2391	2.54	13.42	99	196	Off Idle	77.8	0	2	132	944 Turbo	0.12	Lean	1	14.7	-2.16	15.12	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:8	31.36	2389	2.54	13.42	99	196	Off Idle	77.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-2.19	15.17	1.03	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:8	31.36	2403	2.55	13.42	99	196	Off Idle	77	0	2	132	944 Turbo	0.2	Rich	1	14.7	-2.21	15.2	1.04	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:03:8	31.36	2411	2.55	13.41	99	196	Off Idle	76.4	0	2	132	944 Turbo	0.26	Rich	1	14.7	-2.22	15.2	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:9	31.36	2424	2.56	13.42	99	196	Off Idle	75.8	0	2	132	944 Turbo	0.32	Rich	1	14.7	-2.26	15.2	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:9	31.36	2428	2.56	13.43	99	196	Off Idle	75.4	0	2	132	944 Turbo	0.38	Rich	1	14.7	-2.29	15.21	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:9	31.36	2437	2.57	13.42	99	196	Off Idle	74.8	0	2	132	944 Turbo	0.44	Rich	1	14.7	-2.3	15.21	1.04	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:03:9	31.36	2440	2.57	13.42	99	196	Off Idle	74.2	0	2	132	944 Turbo	0.51	Rich	1	14.7	-2.3	15.2	1.04	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:9	31.36	2451	2.58	13.43	99	196	Off Idle	73.6	0	2	132	944 Turbo	0.57	Rich	1	14.7	-2.28	15.17	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:9	31.36	2460	2.58	13.42	99	196	Off Idle	73.2	0	2	132	944 Turbo	0.63	Rich	1	14.7	-2.34	15.14	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:03:9	31.36	2460	2.59	13.43	99	196	Off Idle	72.7	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.3	15.09	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:0	31.36	2473	2.59	13.42	99	196	Off Idle	72.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-2.32	15.05	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:0	31.36	2478	2.6	13.42	99	196	Off Idle	71.7	0	2	132	944 Turbo	0.72	Rich	1	14.7	-2.31	15.01	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:0	32.72	2478	2.6	13.41	99	196	Off Idle	71.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-2.35	14.99	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:0	32.72	2494	2.6	13.42	99	196	Off Idle	70.8	0	2	132	944 Turbo	0.68	Rich	1	14.7	-2.32	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:0	32.72	2499	2.61	13.42	99	196	Off Idle	70.4	0	2	132	944 Turbo	0.61	Rich	1	14.7	-2.34	14.88	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:0	32.72	2508	2.61	13.43	99	196	Off Idle	69.4	0	2	132	944 Turbo	0.55	Rich	1	14.7	-2.34	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:1	32.72	2514	2.62	13.42	99	196	Off Idle	68.9	0	2	132	944 Turbo	0.48	Rich	1	14.7	-2.36	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:1	32.72	2532	2.62	13.42	99	196	Off Idle	68.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-2.37	14.81	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:1	32.72	2554	2.63	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.3	Rich	1	14.7	-2.35	14.8	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:1	32.72	2577	2.63	13.43	99	196	Off Idle	67.7	0	2	132	944 Turbo	0.27	Rich	1	14.7	-2.4	14.82	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:1	32.72	2577	2.63	13.41	99	196	Off Idle	67.5	0	2	132	944 Turbo	0.23	Rich	1	14.7	-2.36	14.85	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:1	32.72	2622	2.64	13.4	99	196	Off Idle	67	0	2	132	944 Turbo	0.21	Rich	1	14.7	-2.35	14.89	1.01	3.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:1	32.72	2631	2.64	13.41	99	196	Off Idle	66.6	0	2	132	944 Turbo	0.24	Rich	1	14.7	-2.39	14.94	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:2	32.72	2631	2.65	13.39	99	196	Off Idle	65.9	0	2	132	944 Turbo	0.28	Rich	1	14.7	-2.41	14.97	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:2	32.72	2648	2.65	13.39	99	196	Off Idle	65.1	0	2	132	944 Turbo	0.34	Rich	1	14.7	-2.39	14.99	1.02	3.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:2	32.72	2666	2.66	13.38	99	196	Off Idle	64.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-2.46	15.03	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:2	32.72	2666	2.66	13.38	99	196	Off Idle	63.8	0	2	132	944 Turbo	0.5	Rich	1	14.7	-2.47	15.1	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:2	32.72	2672	2.67	13.39	99	196	Off Idle	63	0	2	132	944 Turbo	0.56	Rich	1	14.7	-2.49	15.13	1.03	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:2	32.72	2678	2.67	13.39	99	196	Off Idle	62.3	0	2	132	944 Turbo	0.62	Rich	1	14.7	-2.48	15.15	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:3	32.72	2708	2.67	13.39	99	196	Off Idle	61.7	0	2	132	944 Turbo	0.67	Rich	1	14.7	-2.48	15.11	1.03	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:3	32.72	2708	2.68	13.39	99	196	Off Idle	61	0	2	132	944 Turbo	0.68	Rich	1	14.7	-2.52	15.07	1.03	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:3	32.72	2695	2.68	13.39	99	196	Off Idle	60.2	0	2	132	944 Turbo	0.66	Lean	1	14.7	-2.52	15.03	1.02	3.6	3.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:04:3	32.72	2699	2.69	13.4	99	196	Off Idle	59.6	0	2	132	944 Turbo	0.62	Lean	1	14.7	-2.54	14.99	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:3	32.72	2702	2.69	13.4	99	196	Off Idle	58.3	0	2	132	944 Turbo	0.56	Lean	1	14.7	-2.56	14.95	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:3	32.72	2689	2.7	13.4	99	196	Off Idle	57.6	0	2	132	944 Turbo	0.47	Lean	1	14.7	-2.54	14.93	1.02	3.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:4	32.72	2728	2.7	13.39	99	196	Off Idle	57	0	2	132	944 Turbo	0.42	Lean	1	14.7	-2.48	14.84	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:4	32.72	2728	2.71	13.4	99	196	Off Idle	57	0	2	132	944 Turbo	0.39	Lean	1	14.7	-2.53	14.8	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:4	32.72	2747	2.71	13.39	99	196	Off Idle	56	0	2	132	944 Turbo	0.35	Lean	1	14.7	-2.53	14.79	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:4	32.72	2772	2.71	13.39	99	196	Off Idle	55.5	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.51	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:04:4	32.72	2770	2.72	13.39	99	196	Off Idle	55.1	0	2	132	944 Turbo	0.34	Lean	1	14.7	-2.56	14.81	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:4	32.72	2774	2.72	13.39	99	196	Off Idle	54.8	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.58	14.82	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:4	32.72	2795	2.73	13.38	99	196	Off Idle	54.5	0	2	132	944 Turbo	0.41	Rich	1	14.7	-2.55	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:5	32.72	2808	2.73	13.39	99	196	Off Idle	54	0	2	132	944 Turbo	0.46	Rich	1	14.7	-2.57	14.91	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:5	32.72	2806	2.73	13.39	99	196	Off Idle	53.6	0	2	132	944 Turbo	0.51	Rich	1	14.7	-2.56	14.93	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:5	32.72	2813	2.74	13.39	99	196	Off Idle	53.3	0	2	132	944 Turbo	0.56	Rich	1	14.7	-2.57	14.92	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:5	32.72	2823	2.74	13.4	99	196	Off Idle	53	0	2	132	944 Turbo	0.64	Rich	1	14.7	-2.58	14.95	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:5	32.72	2824	2.74	13.4	99	196	Off Idle	52.4	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.58	14.94	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:5	32.72	2834	2.74	13.39	99	196	Off Idle	51.8	0	2	132	944 Turbo	0.69	Rich	1	14.7	-2.6	14.93	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:6	32.72	2842	2.75	13.4	99	196	Off Idle	51	0	2	132	944 Turbo	0.65	Rich	1	14.7	-2.61	14.87	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:6	32.72	2847	2.75	13.41	99	196	Off Idle	50.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-2.58	14.86	1.01	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:6	32.72	2850	2.75	13.41	99	197	Off Idle	49.8	0	2	132	944 Turbo	0.55	Rich	1	14.7	-2.56	14.83	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:04:6	32.72	2870	2.75	13.42	99	197	Off Idle	49.4	0	2	132	944 Turbo	0.49	Lean	1	14.7	-2.6	14.8	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:04:6	32.72	2867	2.75	13.42	99	197	Off Idle	48.9	0	2	132	944 Turbo	0.42	Lean	1	14.7	-2.54	14.78	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:04:6	32.72	2870	2.76	13.43	99	196	Off Idle	48.5	0	2	132	944 Turbo	0.37	Lean	1	14.7	-2.58	14.76	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:04:6	32.72	2891	2.76	13.41	99	196	Off Idle	48	0	2	132	944 Turbo	0.31	Lean	1	14.7	-2.59	14.77	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:04:7	32.72	2909	2.76	13.42	99	196	Off Idle	47.6	0	2	132	944 Turbo	0.23	Lean	1	14.7	-2.63	14.81	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:04:7	32.72	2927	2.77	13.42	99	196	Off Idle	47.3	0	2	132	944 Turbo	0.2	Lean	1	14.7	-2.59	14.83	1.01	3.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:04:7	32.72	2934	2.77	13.42	99	196	Off Idle	46.9	0	2	132	944 Turbo	0.21	Lean	1	14.7	-2.64	14.86	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:7	32.72	2957	2.77	13.42	99	196	Off Idle	45.9	0	2	132	944 Turbo	0.24	Lean	1	14.7	-2.63	14.92	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:7	32.72	2957	2.78	13.43	99	196	Off Idle	45.4	0	2	132	944 Turbo	0.31	Lean	1	14.7	-2.63	14.94	1.02	3.4	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:7	34.08	3002	2.78	13.42	99	196	Off Idle	45	0	2	132	944 Turbo	0.36	Lean	1	14.7	-2.6	14.96	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:8	34.08	2991	2.79	13.43	99	196	Off Idle	44.5	0	2	132	944 Turbo	0.42	Rich	1	14.7	-2.68	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:8	34.08	2994	2.79	13.43	99	196	Off Idle	44.1	0	2	132	944 Turbo	0.48	Rich	1	14.7	-2.68	15.04	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:8	34.08	3012	2.79	13.44	99	196	Off Idle	43.8	0	2	132	944 Turbo	0.54	Rich	1	14.7	-2.78	15.08	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:8	34.08	3001	2.79	13.42	99	196	Off Idle	43.5	0	2	132	944 Turbo	0.59	Rich	1	14.7	-2.77	15.08	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:8	34.08	3000	2.8	13.44	99	196	Off Idle	43.3	0	2	132	944 Turbo	0.63	Rich	1	14.7	-2.88	15.06	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:8	34.08	3006	2.8	13.42	99	196	Off Idle	43	0	2	132	944 Turbo	0.62	Rich	1	14.7	-2.83	15.05	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:9	34.08	3003	2.8	13.43	99	196	Off Idle	42.7	0	2	132	944 Turbo	0.58	Rich	1	14.7	-2.89	15.03	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:04:9	34.08	3006	2.8	13.42	99	196	Off Idle	42.4	0	2	132	944 Turbo	0.53	Rich	1	14.7	-2.84	15	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:9	34.08	3009	2.8	13.43	99	196	Off Idle	42.1	0	2	132	944 Turbo	0.44	Rich	1	14.7	-2.86	14.95	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:9	34.08	3018	2.8	13.41	99	196	Off Idle	41.8	0	2	132	944 Turbo	0.41	Lean	1	14.7	-2.85	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:04:9	34.08	3037	2.81	13.42	99	196	Off Idle	41.6	0	2	132	944 Turbo	0.35	Lean	1	14.7	-2.82	14.87	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:04:9	34.08	3037	2.81	13.41	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-2.84	14.86	1.01	3.5	4	ON	28 Pin	OFF	Removed	Disabled
03:29:04:9	34.08	3058	2.81	13.41	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	-2.85	14.87	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:05:0	34.08	3071	2.81	13.42	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-2.91	14.89	1.01	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:05:0	34.08	3077	2.81	13.4	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-2.93	14.94	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:05:0	34.08	3088	2.81	13.41	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-2.98	14.97	1.02	3.5	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:05:0	34.08	3100	2.81	13.4	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	-3.01	15.01	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:05:0	34.08	3106	2.81	13.4	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-3.01	15.01	1.02	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:05:0	34.08	3108	2.81	13.39	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-3.01	15.07	1.03	3.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:05:1	34.08	3136	2.81	13.39	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.7	-3.14	15.13	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:05:1	34.08	3135	2.81	13.38	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.47	Rich	1	14.7	-3.18	15.15	1.03	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:05:1	34.08	3140	2.81	13.38	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.53	Rich	1	14.7	-3.25	15.14	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:1	34.08	3145	2.81	13.4	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.62	Rich	1	14.7	-3.31	15.12	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:1	34.08	3164	2.81	13.4	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.7	-3.35	15.05	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:1	34.08	3167	2.81	13.4	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.69	Rich	1	14.7	-3.35	15.01	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:1	34.08	3161	2.81	13.41	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-3.4	14.98	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:2	34.08	3165	2.81	13.41	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-3.41	14.96	1.02	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:05:2	34.08	3168	2.81	13.39	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-3.44	14.95	1.02	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:05:2	34.08	3174	2.81	13.41	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.7	-3.49	14.89	1.01	3.6	3.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:05:2	34.08	3187	2.8	13.39	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-3.5	14.85	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:05:2	34.08	3187	2.8	13.4	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.38	Lean	1	14.7	-3.59	14.84	1.01	3.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:05:2	34.08	3210	2.8	13.4	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-3.59	14.83	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:05:3	34.08	3228	2.8	13.38	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-3.61	14.86	1.01	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:05:3	34.08	3250	2.8	13.39	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.7	-3.57	14.89	1.01	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:3	34.08	3250	2.8	13.4	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-3.66	14.94	1.02	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:3	34.08	3282	2.8	13.4	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-3.63	15.03	1.02	3.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:05:3	35.45	3286	2.79	13.38	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.7	-3.73	15.08	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:3	35.45	3304	2.79	13.38	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.22	Lean	1	14.7	-3.79	15.11	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:4	35.45	3306	2.79	13.41	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-3.77	15.13	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:4	35.45	3310	2.79	13.39	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-3.79	15.18	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:4	35.45	3320	2.79	13.4	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.7	-3.89	15.22	1.04	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:4	35.45	3320	2.79	13.43	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.7	-3.83	15.24	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:05:4	35.45	3322	2.79	13.41	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-3.83	15.25	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:05:4	35.45	3317	2.79	13.44	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.39	Rich	1	14.7	-3.94	15.22	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:05:4	35.45	3316	2.79	13.44	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.7	-3.92	15.19	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:05:5	35.45	3318	2.79	13.41	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.7	-4.01	15.08	1.03	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:5	35.45	3314	2.79	13.41	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.29	Rich	1	14.7	-4.07	15.04	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:5	35.45	3323	2.79	13.43	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.24	Rich	1	14.7	-4	15.03	1.02	3.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:5	35.45	3323	2.79	13.41	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.19	Rich	1	14.7	-4.04	15.05	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:5	35.45	3336	2.79	13.42	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Rich	1	14.7	-4.11	15.06	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:5	35.45	3350	2.79	13.43	99	196	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-4.02	15.06	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:6	35.45	3352	2.79	13.4	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.04	15.08	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:6	35.45	3374	2.79	13.41	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-4.13	15.1	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:6	35.45	3373	2.79	13.43	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.19	Lean	1	14.7	-4.12	15.12	1.03	3.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:05:6	35.45	3375	2.79	13.42	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.7	-4.05	15.13	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:6	35.45	3382	2.79	13.41	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-4.17	15.17	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:6	35.45	3388	2.78	13.43	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.39	Lean	1	14.7	-4.2	15.19	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:6	35.45	3398	2.78	13.41	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.44	Lean	1	14.7	-4.19	15.21	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:7	35.45	3406	2.78	13.41	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.49	Lean	1	14.7	-4.29	15.2	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:7	35.45	3404	2.78	13.45	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.7	-4.26	15.16	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:7	35.45	3409	2.78	13.44	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.51	Lean	1	14.7	-4.25	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:7	35.45	3416	2.78	13.42	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.5	Lean	1	14.7	-4.32	15.06	1.03	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:7	35.45	3419	2.78	13.44	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.7	-4.39	15.03	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:7	35.45	3420	2.77	13.42	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.41	Lean	1	14.7	-4.44	14.97	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:8	35.45	3426	2.77	13.42	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.36	Lean	1	14.7	-4.53	14.95	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:8	35.45	3467	2.77	13.45	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.7	-4.51	14.95	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:05:8	35.45	3444	2.77	13.43	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.7	-4.54	14.96	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:8	35.45	3448	2.77	13.43	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.24	Lean	1	14.7	-4.61	14.97	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:8	35.45	3466	2.76	13.43	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.7	-4.55	15	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:8	35.45	3472	2.76	13.43	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.63	15.03	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:9	35.45	3474	2.76	13.44	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-4.68	15.07	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:9	35.45	3482	2.76	13.45	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.66	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:9	35.45	3479	2.76	13.44	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.73	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:9	35.45	3482	2.76	13.46	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.8	15.19	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:9	35.45	3495	2.75	13.45	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.73	15.21	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:9	35.45	3502	2.75	13.42	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.77	15.18	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:05:9	35.45	3513	2.75	13.43	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-4.84	15.16	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:06:0	35.45	3514	2.75	13.44	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.84	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:06:0	35.45	3526	2.75	13.43	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.13	Lean	1	14.7	-4.83	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:06:0	35.45	3535	2.75	13.43	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-4.88	15.09	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:06:0	35.45	3538	2.74	13.44	99	196	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.7	-4.98	15.07	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:06:0	35.45	3548	2.74	13.45	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.1	15.05	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:06:0	35.45	3558	2.73	13.45	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.15	Lean	1	14.7	-5.25	15.06	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:06:1	35.45	3559	2.71	13.45	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.7	-5.51	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:06:1	35.45	3563	2.68	13.44	99	197	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.7	-5.87	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:1	35.45	3561	2.65	13.44	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-6.29	15.05	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:06:1	35.45	3564	2.61	13.44	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Lean	1	14.7	-6.97	15.07	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:06:1	36.81	3545	2.56	13.43	99	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.48	15.1	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:06:1	36.81	3513	2.51	13.4	99	197	Full Load	41.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.99	15.09	1.03	3.5	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:1	36.81	3495	2.43	13.43	99	197	Idle	41.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	-8.52	15.07	1.03	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:2	36.81	3475	2.38	13.41	99	196	Idle	41.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.79	15.03	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:2	38.18	3488	2.36	13.41	99	196	Idle	41.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-8.92	15	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:06:2	38.18	3440	2.28	13.45	99	196	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.17	14.97	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:06:2	38.18	3420	2.26	13.45	99	196	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.34	14.89	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:06:2	38.18	3408	2.2	13.45	99	196	Idle	41.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-9.38	14.82	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:06:2	35.45	3356	2.13	13.45	99	197	Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.6	14.65	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:06:3	35.45	3299	2.08	13.45	99	197	Idle	41.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.68	14.52	0.99	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:3	29.99	3294	2	13.45	99	197	Idle	41.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.72	14.35	0.98	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:3	24.54	3274	1.95	13.44	99	197	Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.73	14.14	0.96	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:3	20.45	3289	1.9	13.46	99	197	Idle	41.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.75	14.04	0.96	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:3	20.45	3272	1.85	13.46	99	197	Idle	41.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.76	13.94	0.95	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:3	20.45	3267	1.81	13.44	99	196	Idle	41.4	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.77	13.88	0.95	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:4	20.45	3226	1.77	13.44	99	196	Idle	41	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.81	13.87	0.94	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:4	20.45	3207	1.74	13.44	99	196	Idle	40.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.85	13.88	0.95	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:4	20.45	3199	1.73	13.44	99	196	Idle	39.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.84	13.94	0.95	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:4	20.45	3144	1.72	13.44	99	196	Idle	39	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.82	14.02	0.96	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:4	20.45	3129	1.71	13.44	99	196	Idle	38.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.73	14.16	0.96	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:4	20.45	3099	1.72	13.44	99	197	Idle	37.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.63	14.23	0.97	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:4	20.45	3099	1.72	13.43	99	197	Idle	36.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.56	14.3	0.97	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:5	20.45	3059	1.72	13.44	99	197	Idle	36.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.49	14.44	0.98	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:5	20.45	3010	1.72	13.43	99	197	Idle	35.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.42	14.61	1	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:5	20.45	3015	1.73	13.43	99	197	Idle	34.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.38	14.81	1.01	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:5	19.09	2989	1.73	13.45	99	197	Idle	33.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.33	14.99	1.02	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:5	19.09	2957	1.74	13.43	99	197	Idle	32.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.26	15.14	1.03	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:5	19.09	2924	1.74	13.45	99	197	Idle	31.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.28	15.37	1.05	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:6	19.09	2924	1.75	13.44	99	197	Idle	30.6	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.22	15.52	1.06	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:6	19.09	2885	1.75	13.44	99	196	Idle	29.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.23	15.68	1.07	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:6	19.09	2860	1.76	13.43	99	196	Idle	29.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.16	15.81	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:6	19.09	2842	1.77	13.43	99	196	Idle	28.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.11	15.91	1.08	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:6	19.09	2829	1.77	13.43	99	196	Idle	28.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.09	15.95	1.09	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:6	19.09	2796	1.78	13.43	99	196	Idle	27.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.02	16.11	1.1	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:6	19.09	2764	1.79	13.44	99	196	Idle	27.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.95	16.37	1.12	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:7	19.09	2756	1.8	13.44	99	196	Idle	27.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	16.68	1.14	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:7	19.09	2712	1.8	13.44	99	196	Idle	27.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.89	17.06	1.16	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:7	19.09	2681	1.81	13.44	99	196	Idle	27.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.85	17.47	1.19	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:7	19.09	2681	1.82	13.44	99	196	Idle	27.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.82	17.88	1.22	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:7	19.09	2647	1.82	13.44	99	196	Idle	27.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.8	18.28	1.25	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:7	19.09	2632	1.82	13.44	99	196	Idle	28.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.76	18.69	1.27	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:8	19.09	2623	1.83	13.45	99	196	Idle	28.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.76	19.08	1.3	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:8	19.09	2580	1.83	13.44	99	196	Idle	29.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.73	19.46	1.33	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:8	19.09	2565	1.83	13.43	99	196	Idle	30.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.7	19.79	1.35	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:8	19.09	2531	1.83	13.41	99	196	Idle	31.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.72	20.05	1.37	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:8	19.09	2523	1.82	13.41	99	196	Idle	32.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.72	20.19	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:8	19.09	2471	1.82	13.43	99	196	Idle	33.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.72	20.21	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:9	19.09	2464	1.82	13.43	99	196	Idle	35.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.75	20.22	1.38	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:9	19.09	2464	1.81	13.45	99	196	Idle	37.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.76	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:9	19.09	2430	1.81	13.44	99	197	Idle	37.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.76	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:9	19.09	2395	1.8	13.44	99	197	Idle	40.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.77	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:9	19.09	2395	1.79	13.43	99	197	Idle	41.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.81	20.22	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:9	19.09	2370	1.78	13.44	99	196	Idle	42.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.83	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:06:9	19.09	2325	1.77	13.43	99	196	Full Load	44	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.82	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:0	19.09	2174	1.76	13.43	99	196	Off Idle	45.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.81	20.23	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:0	19.09	2174	1.75	13.42	99	197	Off Idle	47.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.8	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:0	9.54	2288	1.74	13.42	99	197	Off Idle	47.7	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.77	20.24	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:0	12.27	2271	1.73	13.41	99	197	Off Idle	52.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.77	20.24	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:07:0	12.27	2262	1.72	13.4	99	197	Off Idle	55.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.74	20.25	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:07:0	14.99	2234	1.71	13.41	99	197	Off Idle	57.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.77	20.25	1.38	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:07:1	17.72	2194	1.69	13.42	99	197	Off Idle	60.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.8	20.25	1.38	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:07:1	17.72	2175	1.66	13.41	99	197	Off Idle	62.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.85	20.25	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:07:1	20.45	2168	1.65	13.41	99	197	Off Idle	65.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.84	20.25	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:1	20.45	2119	1.64	13.42	99	197	Off Idle	67.6	0	2	132	944 Turbo	0.01	Lean	1	14.7	-8.77	20.25	1.38	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:1	23.18	2129	1.64	13.41	99	197	Off Idle	70	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.63	20.23	1.38	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:1	23.18	2121	1.65	13.41	99	197	Off Idle	72.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.46	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:07:1	25.9	2090	1.66	13.42	99	196	Off Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.7	-8.32	20.23	1.38	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:07:2	25.9	2068	1.67	13.43	99	196	Off Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.19	20.23	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:07:2	28.63	2052	1.67	13.44	99	196	Off Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.09	20.23	1.38	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:07:2	28.63	2041	1.68	13.45	99	197	Off Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.93	20.23	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:2	31.36	2042	1.69	13.45	99	197	Off Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.82	20.23	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:2	31.36	2036	1.7	13.44	99	197	Off Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.68	20.23	1.38	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:2	32.72	2036	1.71	13.42	99	197	Off Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.7	-7.54	20.24	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:3	32.72	2046	1.72	13.43	99	196	Off Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.48	20.24	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:3	31.36	2075	1.73	13.4	99	196	Off Idle	85.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.39	20.24	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:3	31.36	2080	1.75	13.39	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.34	20.24	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:3	31.36	2094	1.75	13.39	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.7	-7.27	20.24	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:3	31.36	2118	1.77	13.39	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-7.16	20.23	1.38	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:3	31.36	2115	1.78	13.39	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.03	Lean	1	14.7	-7.12	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:4	31.36	2116	1.8	13.41	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.7	-7.06	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:4	31.36	2133	1.82	13.42	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.04	Lean	1	14.7	-7.01	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:4	32.72	2124	1.83	13.44	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.7	-6.99	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:4	32.72	2104	1.85	13.42	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.7	-6.98	20.23	1.38	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:07:4	32.72	2087	1.87	13.41	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.95	20.24	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:4	32.72	2074	1.88	13.41	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.93	20.2	1.38	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:4	32.72	2070	1.88	13.41	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.89	20.05	1.37	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:5	32.72	2053	1.88	13.41	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.85	19.84	1.35	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:5	32.72	2046	1.88	13.43	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.08	Lean	1	14.7	-6.85	19.56	1.33	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:5	32.72	2045	1.88	13.46	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.84	19.23	1.31	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:5	32.72	2047	1.89	13.46	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.77	18.68	1.27	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:5	32.72	2049	1.89	13.45	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.75	18.27	1.24	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:5	32.72	2050	1.89	13.42	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.73	17.63	1.2	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:6	32.72	2073	1.9	13.41	99	197	Off Idle	85.7	0	2	132	944 Turbo	0.08	Lean	1	14.7	-6.71	17.19	1.17	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:6	32.72	2083	1.9	13.39	99	197	Off Idle	85.7	0	2	132	944 Turbo	0.08	Lean	1	14.7	-6.67	16.77	1.14	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:6	32.72	2082	1.9	13.39	99	197	Off Idle	85.7	0	2	132	944 Turbo	0.08	Lean	1	14.7	-6.65	16.46	1.12	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:6	31.36	2117	1.91	13.39	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.7	-6.61	16.22	1.1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:6	31.36	2102	1.91	13.38	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.54	15.96	1.09	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:6	31.36	2102	1.91	13.4	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.49	15.85	1.08	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:6	31.36	2102	1.92	13.41	99	196	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.46	15.77	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:7	31.36	2101	1.92	13.42	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.45	15.69	1.07	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:7	31.36	2098	1.92	13.43	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-6.43	15.64	1.07	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:7	31.36	2098	1.93	13.45	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.1	Lean	1	14.7	-6.44	15.59	1.06	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:7	31.36	2096	1.93	13.44	99	197	Off Idle	85.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.42	15.54	1.06	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:7	31.36	2093	1.93	13.43	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-6.42	15.51	1.06	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:7	31.36	2091	1.93	13.41	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-6.37	15.48	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:8	31.36	2094	1.94	13.4	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.41	15.44	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:8	31.36	2094	1.94	13.39	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.18	Lean	1	14.7	-6.42	15.42	1.05	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:07:8	31.36	2096	1.94	13.39	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.43	15.37	1.05	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:8	31.36	2098	1.94	13.37	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.45	15.36	1.05	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:8	31.36	2098	1.95	13.39	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.31	Lean	1	14.7	-6.47	15.35	1.05	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:8	31.36	2104	1.95	13.39	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.4	Lean	1	14.7	-6.4	15.32	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:9	31.36	2108	1.95	13.41	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.43	Rich	1	14.7	-6.4	15.29	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:9	31.36	2110	1.95	13.43	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.5	Rich	1	14.7	-6.36	15.27	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:9	31.36	2112	1.95	13.44	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.59	Rich	1	14.7	-6.36	15.24	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:9	31.36	2114	1.95	13.43	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.39	15.19	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:07:9	31.36	2116	1.95	13.42	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.7	-6.39	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:07:9	31.36	2119	1.95	13.41	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.4	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:07:9	31.36	2119	1.95	13.41	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.39	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:0	31.36	2120	1.95	13.42	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.36	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:0	31.36	2118	1.95	13.45	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.33	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:0	31.36	2118	1.95	13.45	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.32	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:0	31.36	2118	1.95	13.45	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.31	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:0	31.36	2118	1.95	13.45	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.31	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:0	31.36	2111	1.95	13.46	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-6.34	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:1	31.36	2112	1.95	13.45	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.38	14.88	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:1	31.36	2111	1.95	13.44	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.39	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:1	31.36	2111	1.96	13.42	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.58	Rich	1	14.7	-6.38	14.81	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:1	31.36	2112	1.96	13.42	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.33	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:1	31.36	2115	1.96	13.41	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.24	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:1	31.36	2121	1.96	13.42	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.19	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:1	31.36	2124	1.97	13.43	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.16	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:2	31.36	2128	1.97	13.44	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.3	Lean	1	14.7	-6.18	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:2	31.36	2148	1.97	13.44	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.16	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:2	31.36	2140	1.97	13.43	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-6.2	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:2	31.36	2135	1.97	13.43	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.21	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:2	31.36	2136	1.98	13.42	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.12	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:2	31.36	2120	1.98	13.42	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-6.12	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:3	31.36	2128	1.98	13.42	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.1	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:3	31.36	2131	1.98	13.44	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-6.08	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:3	31.36	2129	1.98	13.45	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.7	-6.13	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:3	31.36	2129	1.98	13.44	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.19	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:3	31.36	2133	1.98	13.43	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.17	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:3	31.36	2137	1.99	13.42	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.17	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:4	31.36	2137	1.99	13.43	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.16	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:4	31.36	2143	1.99	13.42	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.57	Rich	1	14.7	-6.08	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:4	31.36	2164	1.99	13.43	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.1	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:4	31.36	2164	1.99	13.45	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.12	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:4	31.36	2153	1.99	13.46	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.12	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:4	31.36	2160	1.99	13.43	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.17	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:4	31.36	2166	1.99	13.42	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-6.2	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:5	31.36	2168	1.99	13.42	99	197	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-6.13	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:5	31.36	2170	1.99	13.42	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-6.13	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:5	31.36	2174	1.99	13.42	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-6.15	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:5	31.36	2174	1.99	13.42	99	196	Off Idle	85.5	0	2	132	944 Turbo	0.77	Rich	1	14.7	-6.17	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:5	31.36	2172	1.99	13.44	99	197	Off Idle	85.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.22	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:5	31.36	2168	1.99	13.43	99	197	Off Idle	85.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.28	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:6	31.36	2166	1.99	13.43	99	197	Off Idle	85.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.3	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:6	31.36	2163	1.99	13.43	99	197	Off Idle	85.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.23	14.72	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:6	31.36	2162	1.99	13.42	99	197	Off Idle	85.2	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.18	14.7	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:6	31.36	2161	1.99	13.42	99	197	Off Idle	85.2	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.19	14.7	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:6	31.36	2158	1.99	13.44	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.17	14.7	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:6	31.36	2158	1.99	13.44	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-6.22	14.7	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:6	31.36	2160	1.99	13.42	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.26	14.72	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:7	31.36	2163	1.99	13.4	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.29	14.74	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:7	31.36	2165	1.99	13.4	99	196	Off Idle	85.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.31	14.75	1	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:7	31.36	2176	1.99	13.38	99	197	Off Idle	85.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.29	14.77	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:7	32.72	2178	1.99	13.39	99	197	Off Idle	85	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.24	14.78	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:08:7	32.72	2184	1.99	13.4	99	197	Off Idle	85	0	2	132	944 Turbo	0.6	Rich	1	14.7	-6.23	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:7	32.72	2188	1.99	13.4	99	196	Off Idle	85	0	2	132	944 Turbo	0.51	Rich	1	14.7	-6.23	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:8	32.72	2198	1.99	13.41	99	196	Off Idle	84.9	0	2	132	944 Turbo	0.48	Rich	1	14.7	-6.25	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:8	32.72	2205	1.99	13.43	99	196	Off Idle	84.7	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.3	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:8	32.72	2206	1.99	13.42	99	196	Off Idle	84.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.28	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:8	32.72	2206	1.99	13.42	99	196	Off Idle	84.4	0	2	132	944 Turbo	0.27	Lean	1	14.7	-6.29	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:8	32.72	2202	1.99	13.43	99	196	Off Idle	84.3	0	2	132	944 Turbo	0.22	Lean	1	14.7	-6.31	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:08:8	32.72	2195	2	13.43	99	196	Off Idle	83.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.34	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:9	32.72	2195	2	13.43	99	196	Off Idle	83.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.33	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:9	32.72	2192	2	13.43	99	196	Off Idle	83.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-6.34	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:9	32.72	2187	2	13.43	99	196	Off Idle	83.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-6.33	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:9	32.72	2185	2	13.43	99	196	Off Idle	83.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.31	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:08:9	32.72	2185	2	13.43	99	196	Off Idle	83	0	2	132	944 Turbo	0.23	Lean	1	14.7	-6.29	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:9	32.72	2190	2	13.43	99	196	Off Idle	83	0	2	132	944 Turbo	0.29	Lean	1	14.7	-6.29	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:08:9	32.72	2196	2	13.42	99	196	Off Idle	83	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.27	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:0	32.72	2196	2	13.42	99	196	Off Idle	83	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.26	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:0	32.72	2205	2	13.43	99	196	Off Idle	83	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.25	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:0	32.72	2208	2	13.42	99	196	Off Idle	83	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.25	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:0	32.72	2210	2	13.43	99	196	Off Idle	83	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.23	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:0	32.72	2210	2	13.42	99	196	Off Idle	82.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.25	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:0	32.72	2210	2	13.4	99	196	Off Idle	82.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.33	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:1	32.72	2208	2	13.41	99	197	Off Idle	82.7	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.28	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:1	32.72	2208	2	13.41	99	197	Off Idle	82.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.26	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:1	32.72	2209	2	13.41	99	197	Off Idle	82.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.29	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:1	32.72	2208	2	13.42	99	196	Off Idle	82.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.29	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:1	32.72	2208	2.01	13.42	99	196	Off Idle	82.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-6.27	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:1	32.72	2208	2.01	13.42	99	196	Off Idle	82.6	0	2	132	944 Turbo	0.69	Rich	1	14.7	-6.31	14.98	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:1	32.72	2212	2.01	13.43	99	196	Off Idle	82.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.32	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:2	32.72	2212	2.01	13.43	99	196	Off Idle	82.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.3	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:2	32.72	2213	2.01	13.41	99	196	Off Idle	82.3	0	2	132	944 Turbo	0.53	Rich	1	14.7	-6.31	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:2	32.72	2218	2.01	13.41	99	196	Off Idle	82.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.3	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:2	32.72	2239	2.01	13.42	99	196	Off Idle	82.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.28	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:2	32.72	2232	2.01	13.4	99	196	Off Idle	82.3	0	2	132	944 Turbo	0.35	Rich	1	14.7	-6.3	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:2	32.72	2229	2.01	13.4	99	197	Off Idle	82.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.3	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:3	32.72	2235	2.01	13.41	99	197	Off Idle	82.6	0	2	132	944 Turbo	0.23	Rich	1	14.6	-6.29	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:3	32.72	2238	2.01	13.42	99	197	Off Idle	82.6	0	2	132	944 Turbo	0.18	Lean	1	14.7	-6.3	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:3	32.72	2248	2.01	13.41	99	196	Off Idle	82.6	0	2	132	944 Turbo	0.15	Lean	1	14.7	-6.34	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:3	32.72	2253	2.01	13.41	99	196	Off Idle	82.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.35	14.81	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:3	32.72	2253	2.01	13.43	99	196	Off Idle	82.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.36	14.83	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:3	32.72	2254	2.01	13.43	99	196	Off Idle	81.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.35	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:4	32.72	2272	2.01	13.43	99	196	Off Idle	81.6	0	2	132	944 Turbo	0.2	Lean	1	14.7	-6.36	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:4	32.72	2252	2.01	13.44	99	196	Off Idle	81.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.36	14.93	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:4	32.72	2252	2.01	13.44	99	196	Off Idle	81.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.36	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:4	32.72	2245	2.01	13.44	99	196	Off Idle	81.1	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.39	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:4	32.72	2245	2.02	13.44	99	196	Off Idle	80.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.37	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:4	32.72	2234	2.02	13.43	99	196	Off Idle	80.6	0	2	132	944 Turbo	0.53	Rich	1	14.7	-6.36	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:4	32.72	2243	2.02	13.41	99	196	Off Idle	80.3	0	2	132	944 Turbo	0.59	Rich	1	14.7	-6.39	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:5	32.72	2247	2.02	13.41	99	196	Off Idle	80	0	2	132	944 Turbo	0.67	Rich	1	14.7	-6.44	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:5	32.72	2247	2.02	13.41	99	196	Off Idle	79.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.4	15.12	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:5	32.72	2258	2.02	13.42	99	196	Off Idle	79.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.39	15.13	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:5	32.72	2254	2.02	13.43	99	196	Off Idle	79.8	0	2	132	944 Turbo	0.71	Rich	1	14.7	-6.4	15.12	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:5	32.72	2257	2.02	13.42	99	196	Off Idle	79.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.39	15.09	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:5	32.72	2257	2.02	13.41	99	196	Off Idle	80	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.37	15.08	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:6	32.72	2259	2.02	13.43	99	197	Off Idle	80.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.4	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:6	32.72	2257	2.02	13.41	99	197	Off Idle	80.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.42	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:6	32.72	2256	2.03	13.41	99	197	Off Idle	80.3	0	2	132	944 Turbo	0.46	Lean	1	14.7	-6.37	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:6	32.72	2258	2.03	13.43	99	196	Off Idle	80.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.38	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:6	32.72	2277	2.03	13.42	99	196	Off Idle	80.8	0	2	132	944 Turbo	0.34	Lean	1	14.7	-6.43	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:6	32.72	2277	2.03	13.42	99	196	Off Idle	80.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.41	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:6	32.72	2263	2.03	13.42	99	196	Off Idle	80.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.39	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:7	32.72	2269	2.03	13.42	99	196	Off Idle	80.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.44	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:7	32.72	2270	2.03	13.41	99	196	Off Idle	80.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.41	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:7	32.72	2275	2.03	13.43	99	196	Off Idle	80.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.4	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:7	32.72	2282	2.03	13.43	99	196	Off Idle	80.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.44	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:7	32.72	2283	2.03	13.42	99	196	Off Idle	80	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.43	14.9	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:09:7	32.72	2284	2.03	13.43	99	196	Off Idle	79.8	0	2	132	944 Turbo	0.18	Lean	1	14.7	-6.38	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:8	32.72	2286	2.03	13.44	99	196	Off Idle	79.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.41	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:8	32.72	2287	2.03	13.44	99	196	Off Idle	79.6	0	2	132	944 Turbo	0.28	Lean	1	14.7	-6.44	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:09:8	32.72	2287	2.03	13.44	99	197	Off Idle	79.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.47	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:8	32.72	2290	2.03	13.42	99	197	Off Idle	79.2	0	2	132	944 Turbo	0.4	Lean	1	14.7	-6.48	15.09	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:8	32.72	2292	2.03	13.42	99	197	Off Idle	79.1	0	2	132	944 Turbo	0.42	Lean	1	14.7	-6.52	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:8	32.72	2290	2.03	13.41	99	196	Off Idle	78.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.5	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:9	32.72	2290	2.03	13.42	99	196	Off Idle	78.7	0	2	132	944 Turbo	0.56	Lean	1	14.7	-6.47	15.16	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:9	32.72	2290	2.03	13.42	99	196	Off Idle	78.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-6.46	15.15	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:9	32.72	2288	2.03	13.42	99	197	Off Idle	78.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.48	15.15	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:9	32.72	2288	2.03	13.42	99	197	Off Idle	78.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.45	15.14	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:9	32.72	2292	2.03	13.42	99	197	Off Idle	78.1	0	2	132	944 Turbo	0.66	Rich	1	14.7	-6.48	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:9	32.72	2291	2.03	13.42	99	196	Off Idle	78.1	0	2	132	944 Turbo	0.67	Rich	1	14.7	-6.5	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:09:9	32.72	2291	2.03	13.42	99	196	Off Idle	78.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.48	15.08	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:0	32.72	2292	2.03	13.42	99	196	Off Idle	78.1	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.48	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:0	32.72	2294	2.03	13.42	99	196	Off Idle	78	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.46	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:0	32.72	2297	2.03	13.42	99	196	Off Idle	77.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.46	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:0	32.72	2296	2.03	13.42	99	196	Off Idle	77.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.47	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:0	32.72	2299	2.03	13.41	99	197	Off Idle	77.6	0	2	132	944 Turbo	0.39	Rich	1	14.7	-6.49	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:0	32.72	2301	2.03	13.42	99	197	Off Idle	77.4	0	2	132	944 Turbo	0.3	Rich	1	14.7	-6.46	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:1	32.72	2301	2.03	13.43	99	197	Off Idle	77.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.44	14.94	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:1	32.72	2302	2.03	13.42	99	196	Off Idle	77.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.48	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:1	32.72	2307	2.03	13.42	99	196	Off Idle	77.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.47	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:1	32.72	2308	2.03	13.42	99	196	Off Idle	77.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.43	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:1	32.72	2312	2.04	13.44	99	196	Off Idle	77.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.48	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:1	32.72	2314	2.04	13.42	99	196	Off Idle	77.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.45	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:1	32.72	2314	2.04	13.42	99	196	Off Idle	77.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.47	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:2	32.72	2318	2.04	13.43	99	196	Off Idle	76.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.45	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:2	32.72	2324	2.04	13.44	99	196	Off Idle	76.8	0	2	132	944 Turbo	0.19	Lean	1	14.7	-6.5	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:2	32.72	2322	2.04	13.42	99	196	Off Idle	76.8	0	2	132	944 Turbo	0.24	Lean	1	14.7	-6.51	15.05	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:2	32.72	2320	2.04	13.42	99	196	Off Idle	76.8	0	2	132	944 Turbo	0.28	Rich	1	14.7	-6.49	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:2	32.72	2320	2.04	13.43	99	196	Off Idle	76.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.53	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:2	32.72	2317	2.04	13.42	99	197	Off Idle	76.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.54	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:3	32.72	2320	2.04	13.42	99	197	Off Idle	76.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.47	15.19	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:3	32.72	2322	2.04	13.42	99	197	Off Idle	76.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.48	15.16	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:3	32.72	2326	2.04	13.41	99	197	Off Idle	76.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.45	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:3	32.72	2327	2.05	13.41	99	196	Off Idle	76.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.38	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:3	32.72	2327	2.05	13.43	99	196	Off Idle	76.8	0	2	132	944 Turbo	0.68	Rich	1	14.7	-6.35	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:3	32.72	2341	2.05	13.43	99	196	Off Idle	76.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.38	15.15	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:4	32.72	2336	2.06	13.43	99	196	Off Idle	76.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.33	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:4	32.72	2338	2.06	13.43	99	196	Off Idle	76.8	0	2	132	944 Turbo	0.69	Lean	1	14.6	-6.29	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:4	32.72	2343	2.06	13.42	99	196	Off Idle	76.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.31	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:4	32.72	2348	2.07	13.43	99	196	Off Idle	76.3	0	2	132	944 Turbo	0.59	Lean	1	14.7	-6.25	15.05	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:10:4	32.72	2354	2.07	13.43	99	196	Off Idle	76.2	0	2	132	944 Turbo	0.49	Lean	1	14.7	-6.23	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:10:4	32.72	2356	2.08	13.43	99	196	Off Idle	76	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.23	15.03	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:10:4	32.72	2361	2.08	13.43	99	197	Off Idle	75.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.21	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:10:5	32.72	2362	2.08	13.43	99	197	Off Idle	75.5	0	2	132	944 Turbo	0.29	Lean	1	14.7	-6.21	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:10:5	32.72	2361	2.09	13.43	99	197	Off Idle	75.2	0	2	132	944 Turbo	0.23	Lean	1	14.7	-6.21	14.91	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:5	32.72	2359	2.09	13.43	99	196	Off Idle	75.1	0	2	132	944 Turbo	0.17	Lean	1	14.7	-6.16	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:5	32.72	2354	2.1	13.44	99	196	Off Idle	74.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.12	14.85	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:5	32.72	2354	2.1	13.44	99	196	Off Idle	74.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.11	14.87	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:5	32.72	2356	2.11	13.43	99	196	Off Idle	74.6	0	2	132	944 Turbo	0.09	Lean	1	14.7	-6.05	14.89	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:6	32.72	2358	2.11	13.45	99	196	Off Idle	74.5	0	2	132	944 Turbo	0.09	Lean	1	14.7	-6.06	14.87	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:6	32.72	2361	2.11	13.44	99	196	Off Idle	74.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.08	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:6	32.72	2361	2.12	13.43	99	196	Off Idle	74.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.11	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:6	32.72	2365	2.12	13.44	99	196	Off Idle	74	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.11	15.02	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:6	32.72	2365	2.12	13.43	99	196	Off Idle	73.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.14	15.06	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:10:6	32.72	2364	2.12	13.43	99	196	Off Idle	73.7	0	2	132	944 Turbo	0.25	Lean	1	14.7	-6.12	15.11	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:10:6	32.72	2367	2.12	13.42	99	196	Off Idle	73.7	0	2	132	944 Turbo	0.31	Lean	1	14.7	-6.16	15.18	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:10:7	32.72	2372	2.12	13.42	99	196	Off Idle	73.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.17	15.19	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:10:7	32.72	2373	2.12	13.41	99	196	Off Idle	73.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-6.19	15.19	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:10:7	32.72	2377	2.12	13.42	99	196	Off Idle	73.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.16	15.19	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:7	32.72	2380	2.12	13.42	99	196	Off Idle	73.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.17	15.24	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:7	32.72	2380	2.12	13.42	99	196	Off Idle	73.6	0	2	132	944 Turbo	0.66	Rich	1	14.7	-6.21	15.2	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:7	32.72	2384	2.11	13.42	99	196	Off Idle	73.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-6.27	15.2	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:8	32.72	2387	2.11	13.43	99	196	Off Idle	73.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.32	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:8	32.72	2388	2.11	13.42	99	196	Off Idle	73.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.35	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:8	32.72	2388	2.11	13.41	99	196	Off Idle	73	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.42	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:8	32.72	2386	2.11	13.42	99	196	Off Idle	72.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.42	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:8	32.72	2386	2.1	13.41	99	196	Off Idle	72.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.44	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:8	32.72	2386	2.1	13.41	99	196	Off Idle	72.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.45	14.97	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:9	32.72	2388	2.1	13.41	99	196	Off Idle	72.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.47	14.94	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:9	32.72	2390	2.09	13.42	99	196	Off Idle	72.4	0	2	132	944 Turbo	0.67	Rich	1	14.7	-6.46	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:9	32.72	2391	2.09	13.42	99	196	Off Idle	72.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.52	14.86	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:10:9	32.72	2391	2.09	13.43	99	196	Off Idle	72.4	0	2	132	944 Turbo	0.53	Rich	1	14.7	-6.55	14.82	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:9	32.72	2391	2.08	13.41	99	196	Off Idle	72.4	0	2	132	944 Turbo	0.47	Rich	1	14.7	-6.61	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:9	32.72	2393	2.08	13.43	99	196	Off Idle	72.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.63	14.79	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:10:9	32.72	2404	2.07	13.43	99	196	Off Idle	72	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.71	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:11:0	32.72	2398	2.06	13.43	99	196	Off Idle	72	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.79	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:11:0	32.72	2405	2.05	13.42	99	196	Off Idle	72	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.85	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:11:0	32.72	2406	2.05	13.43	99	196	Off Idle	71.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.92	14.79	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:11:0	32.72	2410	2.04	13.43	99	196	Off Idle	71.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.96	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:11:0	32.72	2416	2.04	13.43	99	196	Off Idle	71.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.98	14.82	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:11:0	32.72	2416	2.03	13.41	99	196	Off Idle	71.6	0	2	132	944 Turbo	0.14	Lean	1	14.7	-7.02	14.84	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:11:1	32.72	2426	2.03	13.42	99	196	Off Idle	71.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.06	14.87	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:11:1	32.72	2426	2.02	13.42	99	196	Off Idle	71.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.13	14.89	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:11:1	34.08	2418	2.01	13.41	99	196	Off Idle	71.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-7.21	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:11:1	34.08	2413	2	13.42	99	196	Off Idle	71.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.29	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:11:1	34.08	2417	2	13.43	99	196	Off Idle	71.1	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.37	15.02	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:1	34.08	2416	1.99	13.43	99	196	Off Idle	71	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.45	15.06	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:1	34.08	2412	1.98	13.43	99	196	Off Idle	71	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.5	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:2	34.08	2398	1.97	13.43	99	196	Off Idle	70.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.55	15.12	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:2	34.08	2398	1.97	13.43	99	196	Off Idle	70.6	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.56	15.12	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:2	34.08	2418	1.95	13.44	99	196	Off Idle	70.5	0	2	132	944 Turbo	0.71	Rich	1	14.7	-7.62	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:2	34.08	2422	1.95	13.44	99	196	Off Idle	70.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.63	15.17	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:2	34.08	2427	1.94	13.44	99	196	Off Idle	70.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.68	15.15	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:2	34.08	2427	1.93	13.44	99	196	Off Idle	70.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.13	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:3	34.08	2437	1.93	13.44	99	196	Off Idle	70.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.11	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:3	34.08	2432	1.92	13.43	99	196	Off Idle	70.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	15.1	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:3	34.08	2428	1.92	13.43	99	196	Off Idle	70.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.81	15.04	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:3	34.08	2428	1.91	13.44	99	196	Off Idle	70.2	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.84	15.01	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:3	34.08	2430	1.91	13.44	99	196	Off Idle	70.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.89	14.99	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:3	34.08	2428	1.9	13.42	99	196	Off Idle	70.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.92	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:4	34.08	2428	1.9	13.43	99	196	Off Idle	70.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.91	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:4	34.08	2431	1.9	13.42	99	196	Off Idle	70.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.93	14.88	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:4	34.08	2433	1.89	13.43	99	196	Off Idle	70	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.93	14.87	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:4	34.08	2433	1.89	13.43	99	196	Off Idle	70	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.95	14.86	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:4	34.08	2432	1.89	13.44	99	196	Off Idle	70	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.98	14.84	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:4	34.08	2427	1.89	13.44	99	196	Off Idle	70	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.98	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:4	34.08	2427	1.89	13.44	99	196	Off Idle	70	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8	14.83	1.01	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:5	34.08	2440	1.89	13.44	99	196	Off Idle	70	0	2	132	944 Turbo	0.21	Lean	1	14.7	-8.02	14.82	1.01	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:11:5	34.08	2434	1.88	13.43	99	196	Off Idle	70	0	2	132	944 Turbo	0.25	Rich	1	14.6	-8.06	14.83	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:5	34.08	2434	1.88	13.43	99	196	Off Idle	70	0	2	132	944 Turbo	0.3	Rich	1	14.7	-8.09	14.84	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:5	34.08	2417	1.88	13.43	99	196	Off Idle	70	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.13	14.88	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:5	34.08	2437	1.88	13.43	99	196	Off Idle	70	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.16	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:5	34.08	2437	1.87	13.43	99	196	Off Idle	69.8	0	2	132	944 Turbo	0.52	Rich	1	14.7	-8.2	14.94	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:11:6	34.08	2436	1.87	13.44	99	196	Off Idle	69.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.21	14.96	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:6	34.08	2435	1.87	13.42	99	196	Off Idle	69.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.23	15	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:6	34.08	2434	1.87	13.42	99	196	Off Idle	69.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.29	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:6	34.08	2435	1.86	13.41	99	196	Off Idle	69.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.29	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:6	34.08	2433	1.86	13.41	99	196	Off Idle	69.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.29	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:6	34.08	2433	1.86	13.41	99	196	Off Idle	69.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.29	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:6	34.08	2432	1.86	13.43	99	196	Off Idle	69.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.26	15.09	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:7	34.08	2435	1.85	13.43	99	196	Off Idle	69.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.26	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:7	34.08	2439	1.85	13.44	99	196	Off Idle	69.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.27	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:7	34.08	2440	1.85	13.44	99	196	Off Idle	69.1	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.28	15.05	1.03	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:7	34.08	2447	1.84	13.44	99	196	Off Idle	69.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.31	15	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:7	34.08	2449	1.84	13.44	99	196	Off Idle	69	0	2	132	944 Turbo	0.49	Rich	1	14.6	-8.31	14.99	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:7	34.08	2451	1.84	13.45	99	196	Off Idle	69	0	2	132	944 Turbo	0.43	Rich	1	14.6	-8.31	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:8	34.08	2451	1.84	13.44	99	196	Off Idle	69.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.31	14.96	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:8	34.08	2453	1.84	13.44	99	196	Off Idle	69.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-8.36	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:8	34.08	2449	1.84	13.43	99	196	Off Idle	69.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.35	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:8	34.08	2450	1.83	13.45	99	196	Off Idle	69.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.41	14.88	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:8	34.08	2450	1.83	13.43	99	196	Off Idle	69.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.45	14.84	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:8	34.08	2466	1.83	13.43	99	196	Off Idle	69.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.44	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:9	34.08	2447	1.83	13.43	99	196	Off Idle	69.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.41	14.8	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:11:9	34.08	2448	1.83	13.43	99	196	Off Idle	69.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.43	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:9	34.08	2450	1.83	13.42	99	196	Off Idle	69.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.44	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:9	34.08	2455	1.83	13.43	99	196	Off Idle	69.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-8.43	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:9	34.08	2455	1.83	13.42	99	196	Off Idle	69.2	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.46	14.86	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:9	34.08	2459	1.83	13.42	99	196	Off Idle	69	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.47	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:11:9	35.45	2452	1.82	13.42	99	196	Off Idle	68.9	0	2	132	944 Turbo	0.55	Rich	1	14.7	-8.47	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:0	35.45	2454	1.82	13.42	99	196	Off Idle	68.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.47	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:0	35.45	2467	1.82	13.42	99	196	Off Idle	68.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.5	14.95	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:0	35.45	2459	1.82	13.44	99	196	Off Idle	68.4	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.45	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:0	35.45	2459	1.82	13.43	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.44	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:0	35.45	2461	1.82	13.44	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.44	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:0	34.08	2445	1.82	13.42	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.46	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:1	34.08	2454	1.82	13.43	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.44	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:1	34.08	2454	1.82	13.43	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.45	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:1	34.08	2455	1.82	13.43	99	196	Off Idle	68.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.44	15.07	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:1	34.08	2475	1.82	13.42	99	196	Off Idle	68	0	2	132	944 Turbo	0.63	Lean	1	14.6	-8.47	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:1	34.08	2465	1.82	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.47	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:1	34.08	2454	1.82	13.42	99	196	Off Idle	68	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.52	15.01	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:1	34.08	2456	1.82	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.46	Lean	1	14.6	-8.52	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:2	34.08	2456	1.82	13.41	99	196	Off Idle	68	0	2	132	944 Turbo	0.37	Lean	1	14.7	-8.55	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:2	34.08	2452	1.82	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.52	14.93	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:2	34.08	2467	1.82	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.54	14.91	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:2	34.08	2465	1.82	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.54	14.89	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:2	35.45	2486	1.82	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.17	Lean	1	14.7	-8.52	14.87	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:2	35.45	2470	1.82	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.5	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:3	35.45	2470	1.81	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.52	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:3	35.45	2470	1.81	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.52	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:3	35.45	2472	1.81	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.55	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:3	35.45	2472	1.81	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.61	14.88	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:3	35.45	2472	1.81	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.65	14.91	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:3	35.45	2472	1.81	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.38	Lean	1	14.6	-8.69	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:4	35.45	2471	1.8	13.44	99	197	Off Idle	68	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.7	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:4	35.45	2470	1.8	13.43	99	197	Off Idle	68	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.71	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:4	35.45	2466	1.8	13.43	99	197	Off Idle	68	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.74	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:4	35.45	2468	1.8	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.64	Lean	1	14.6	-8.75	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:4	35.45	2464	1.79	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.76	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:4	35.45	2467	1.79	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.77	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:4	35.45	2466	1.79	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.78	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:12:5	35.45	2462	1.78	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.78	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:5	35.45	2462	1.78	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.83	15.13	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:5	35.45	2458	1.78	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.73	Rich	1	14.7	-8.85	15.12	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:5	35.45	2458	1.78	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.85	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:5	35.45	2462	1.77	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.65	Rich	1	14.6	-8.87	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:5	35.45	2462	1.77	13.44	99	196	Off Idle	68	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.9	15.03	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:6	35.45	2464	1.77	13.42	99	196	Off Idle	68	0	2	132	944 Turbo	0.53	Rich	1	14.7	-8.89	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:6	35.45	2466	1.77	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.83	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:6	35.45	2466	1.76	13.43	99	196	Off Idle	68.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.85	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:6	35.45	2469	1.76	13.42	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.87	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:6	35.45	2474	1.76	13.43	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.84	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:6	35.45	2479	1.76	13.44	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.89	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:6	35.45	2479	1.76	13.43	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.91	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:7	35.45	2483	1.76	13.42	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.9	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:7	35.45	2482	1.76	13.43	99	196	Off Idle	68.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.87	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:7	35.45	2482	1.76	13.43	100	196	Off Idle	68.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.91	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:7	35.45	2483	1.76	13.44	100	196	Off Idle	68.1	0	2	132	944 Turbo	0.16	Lean	1	14.7	-8.85	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:7	35.45	2480	1.77	13.43	99	196	Off Idle	68	0	2	132	944 Turbo	0.21	Rich	1	14.6	-8.83	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:7	35.45	2477	1.77	13.43	99	196	Off Idle	67.8	0	2	132	944 Turbo	0.27	Rich	1	14.6	-8.77	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:8	35.45	2476	1.78	13.42	99	196	Off Idle	67.7	0	2	132	944 Turbo	0.33	Rich	1	14.7	-8.73	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:8	35.45	2474	1.78	13.43	99	196	Off Idle	67.7	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.66	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:8	35.45	2472	1.79	13.44	99	196	Off Idle	67.5	0	2	132	944 Turbo	0.45	Rich	1	14.7	-8.63	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:8	35.45	2472	1.79	13.44	99	196	Off Idle	67.2	0	2	132	944 Turbo	0.51	Rich	1	14.7	-8.57	14.97	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:8	35.45	2474	1.8	13.44	99	196	Off Idle	66.9	0	2	132	944 Turbo	0.59	Rich	1	14.7	-8.49	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:8	35.45	2477	1.81	13.45	99	196	Off Idle	66.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.42	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:12:9	35.45	2481	1.82	13.44	99	196	Off Idle	66.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.31	15.08	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:9	35.45	2482	1.83	13.44	99	196	Off Idle	66.9	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.27	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:12:9	35.45	2486	1.85	13.43	99	196	Off Idle	66.9	0	2	132	944 Turbo	0.58	Lean	1	14.6	-8.17	15.1	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:12:9	35.45	2490	1.86	13.44	99	196	Off Idle	66.9	0	2	132	944 Turbo	0.52	Lean	1	14.6	-8.06	15.11	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:12:9	35.45	2492	1.87	13.43	99	196	Off Idle	66.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.98	15.12	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:12:9	35.45	2498	1.88	13.44	99	196	Off Idle	66.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.89	15.11	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:12:9	35.45	2502	1.9	13.42	99	196	Off Idle	66.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.82	15.09	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:0	35.45	2504	1.91	13.42	99	196	Off Idle	67	0	2	132	944 Turbo	0.28	Lean	1	14.7	-7.71	15.07	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:0	35.45	2505	1.92	13.43	99	196	Off Idle	67	0	2	132	944 Turbo	0.21	Lean	1	14.7	-7.66	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:0	34.08	2507	1.94	13.43	99	197	Off Idle	67	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.58	15	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:0	34.08	2507	1.95	13.44	99	197	Off Idle	66.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.57	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:0	34.08	2506	1.96	13.44	99	197	Off Idle	66.8	0	2	132	944 Turbo	0.1	Lean	1	14.7	-7.52	14.94	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:0	34.08	2508	1.97	13.44	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.49	14.93	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:1	34.08	2506	1.98	13.43	100	196	Off Idle	66.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.48	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:1	34.08	2504	1.99	13.42	100	196	Off Idle	66.7	0	2	132	944 Turbo	0.15	Lean	1	14.7	-7.46	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:1	34.08	2502	2	13.44	99	196	Off Idle	66.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.4	14.95	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:1	34.08	2501	2.01	13.44	99	196	Off Idle	66.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.38	14.99	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:1	34.08	2500	2.02	13.42	99	196	Off Idle	66.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.36	15.04	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:1	34.08	2494	2.02	13.42	100	196	Off Idle	66.1	0	2	132	944 Turbo	0.35	Lean	1	14.7	-7.32	15.08	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:13:1	34.08	2493	2.02	13.43	100	196	Off Idle	66	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.33	15.13	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:2	34.08	2492	2.03	13.42	100	196	Off Idle	66	0	2	132	944 Turbo	0.48	Lean	1	14.7	-7.32	15.16	1.03	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:2	34.08	2491	2.03	13.43	100	196	Off Idle	66.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.29	15.2	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:2	34.08	2499	2.03	13.44	100	196	Off Idle	66.1	0	2	132	944 Turbo	0.61	Rich	1	14.7	-7.26	15.2	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:2	34.08	2502	2.04	13.45	100	196	Off Idle	66.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.22	15.21	1.04	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:13:2	34.08	2509	2.04	13.44	99	196	Off Idle	66.1	0	2	132	944 Turbo	0.6	Rich	1	14.7	-7.15	15.21	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:13:2	34.08	2509	2.05	13.44	99	196	Off Idle	66.1	0	2	132	944 Turbo	0.56	Rich	1	14.7	-7.11	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:3	34.08	2502	2.05	13.42	99	196	Off Idle	66.1	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.06	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:3	34.08	2512	2.06	13.44	99	196	Off Idle	66.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.01	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:3	34.08	2512	2.07	13.44	99	196	Off Idle	66.1	0	2	132	944 Turbo	0.36	Rich	1	14.6	-6.96	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:3	34.08	2519	2.07	13.45	99	196	Off Idle	66.1	0	2	132	944 Turbo	0.3	Rich	1	14.7	-6.96	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:3	34.08	2526	2.07	13.43	99	196	Off Idle	66.1	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.92	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:3	34.08	2532	2.08	13.43	99	196	Off Idle	66.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.9	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:4	34.08	2535	2.08	13.44	99	196	Off Idle	66	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.88	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:13:4	34.08	2551	2.09	13.43	99	197	Off Idle	65.7	0	2	132	944 Turbo	0.13	Lean	1	14.7	-6.89	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:4	34.08	2543	2.09	13.42	99	197	Off Idle	65.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-6.87	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:4	34.08	2542	2.1	13.42	99	197	Off Idle	65.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.85	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:4	34.08	2540	2.1	13.43	99	196	Off Idle	65.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.85	14.91	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:13:4	34.08	2542	2.11	13.44	99	196	Off Idle	65	0	2	132	944 Turbo	0.28	Lean	1	14.7	-6.86	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:13:4	34.08	2541	2.11	13.43	99	196	Off Idle	64.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.86	14.99	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:13:5	34.08	2534	2.12	13.43	99	197	Off Idle	64.7	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.82	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:5	34.08	2528	2.12	13.44	99	197	Off Idle	64.6	0	2	132	944 Turbo	0.51	Lean	1	14.7	-6.81	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:5	34.08	2508	2.13	13.45	99	197	Off Idle	64.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.81	15.14	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:13:5	34.08	2508	2.13	13.44	99	196	Off Idle	64.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.77	15.17	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:13:5	34.08	2528	2.13	13.43	99	196	Off Idle	64.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.75	15.2	1.04	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:13:5	34.08	2530	2.13	13.44	99	196	Off Idle	64	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.74	15.18	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:13:6	34.08	2530	2.13	13.42	99	196	Off Idle	63.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.76	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:6	34.08	2544	2.13	13.43	100	196	Off Idle	63.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.74	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:6	34.08	2540	2.13	13.42	100	196	Off Idle	63.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.71	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:6	34.08	2542	2.14	13.44	100	196	Off Idle	63.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.69	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:6	34.08	2552	2.14	13.44	99	196	Off Idle	63.6	0	2	132	944 Turbo	0.5	Rich	1	14.7	-6.68	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:6	34.08	2553	2.14	13.45	99	196	Off Idle	63.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.72	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:6	34.08	2555	2.14	13.45	99	196	Off Idle	63.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.7	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:7	34.08	2556	2.14	13.43	99	196	Off Idle	63.6	0	2	132	944 Turbo	0.31	Lean	1	14.7	-6.73	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:7	34.08	2566	2.14	13.45	99	196	Off Idle	63.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.7	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:7	34.08	2558	2.15	13.42	100	196	Off Idle	63.5	0	2	132	944 Turbo	0.19	Lean	1	14.7	-6.72	14.77	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:7	34.08	2558	2.15	13.41	100	196	Off Idle	63.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.68	14.76	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:7	34.08	2557	2.15	13.41	100	196	Off Idle	63.2	0	2	132	944 Turbo	0.13	Lean	1	14.7	-6.66	14.78	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:7	34.08	2562	2.15	13.43	100	196	Off Idle	63.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.65	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:8	34.08	2556	2.15	13.43	100	196	Off Idle	63.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.66	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:8	34.08	2556	2.15	13.41	100	197	Off Idle	63.1	0	2	132	944 Turbo	0.19	Lean	1	14.7	-6.67	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:13:8	34.08	2573	2.15	13.44	100	197	Off Idle	62.5	0	2	132	944 Turbo	0.28	Rich	1	14.6	-6.66	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:8	34.08	2576	2.15	13.45	99	197	Off Idle	62.5	0	2	132	944 Turbo	0.33	Rich	1	14.7	-6.67	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:8	34.08	2579	2.15	13.44	99	197	Off Idle	62.5	0	2	132	944 Turbo	0.4	Rich	1	14.7	-6.69	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:8	34.08	2579	2.16	13.46	99	197	Off Idle	62.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.69	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:9	34.08	2583	2.16	13.44	99	196	Off Idle	62.3	0	2	132	944 Turbo	0.53	Rich	1	14.7	-6.67	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:9	34.08	2580	2.16	13.42	99	196	Off Idle	62.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.66	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:9	34.08	2579	2.16	13.43	99	196	Off Idle	62	0	2	132	944 Turbo	0.69	Rich	1	14.7	-6.67	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:9	34.08	2579	2.16	13.43	99	197	Off Idle	61.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-6.69	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:9	34.08	2576	2.16	13.41	99	197	Off Idle	61.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.64	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:9	34.08	2574	2.16	13.41	99	197	Off Idle	61.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.62	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:13:9	34.08	2574	2.16	13.41	99	196	Off Idle	61.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.66	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:0	34.08	2574	2.17	13.42	99	196	Off Idle	61.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.64	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:0	34.08	2568	2.17	13.43	99	196	Off Idle	62	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.64	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:0	34.08	2581	2.17	13.45	99	196	Off Idle	62.1	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.63	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:0	34.08	2582	2.17	13.43	99	196	Off Idle	62.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.64	14.87	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:14:0	34.08	2588	2.17	13.44	100	197	Off Idle	62	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.64	14.85	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:14:0	34.08	2611	2.17	13.45	100	197	Off Idle	61.8	0	2	132	944 Turbo	0.68	Rich	1	14.7	-6.69	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:1	34.08	2594	2.17	13.45	100	197	Off Idle	61.8	0	2	132	944 Turbo	0.66	Rich	1	14.7	-6.67	14.75	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:14:1	34.08	2594	2.17	13.44	99	197	Off Idle	61.6	0	2	132	944 Turbo	0.64	Rich	1	14.7	-6.67	14.75	1	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:14:1	34.08	2594	2.17	13.45	99	197	Off Idle	61.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.65	14.77	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:14:1	34.08	2592	2.17	13.43	99	197	Off Idle	61.5	0	2	132	944 Turbo	0.58	Rich	1	14.7	-6.63	14.78	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:14:1	34.08	2592	2.17	13.42	99	196	Off Idle	61.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.64	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:14:1	34.08	2591	2.17	13.43	99	196	Off Idle	61.5	0	2	132	944 Turbo	0.48	Lean	1	14.7	-6.59	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:1	34.08	2592	2.18	13.42	99	196	Off Idle	61.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.61	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:2	34.08	2598	2.18	13.4	99	196	Off Idle	61.4	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.59	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:2	34.08	2597	2.18	13.41	99	196	Off Idle	61.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.57	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:2	34.08	2602	2.18	13.42	99	196	Off Idle	61.1	0	2	132	944 Turbo	0.28	Lean	1	14.7	-6.56	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:2	34.08	2602	2.18	13.41	99	196	Off Idle	61	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.57	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:2	34.08	2614	2.18	13.41	99	196	Off Idle	61	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.59	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:2	34.08	2620	2.18	13.41	99	196	Off Idle	61	0	2	132	944 Turbo	0.16	Lean	1	14.7	-6.59	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:3	34.08	2625	2.18	13.43	99	197	Off Idle	60.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.61	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:14:3	34.08	2624	2.18	13.42	99	197	Off Idle	60.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.64	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:3	34.08	2624	2.18	13.43	99	197	Off Idle	60.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.64	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:3	34.08	2622	2.18	13.43	99	196	Off Idle	60.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.64	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:3	34.08	2618	2.19	13.44	99	196	Off Idle	60.6	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.64	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:3	34.08	2618	2.19	13.44	99	196	Off Idle	60.4	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.62	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:4	34.08	2616	2.19	13.43	99	196	Off Idle	60.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.6	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:4	34.08	2614	2.19	13.43	99	196	Off Idle	60.1	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.59	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:4	34.08	2615	2.19	13.43	99	196	Off Idle	60.1	0	2	132	944 Turbo	0.6	Lean	1	14.7	-6.61	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:4	34.08	2615	2.19	13.43	100	196	Off Idle	60.1	0	2	132	944 Turbo	0.66	Lean	1	14.7	-6.6	15.19	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:4	34.08	2613	2.19	13.41	100	196	Off Idle	59.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	-6.59	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:4	34.08	2614	2.19	13.42	100	196	Off Idle	59.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.57	15.23	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:4	34.08	2614	2.19	13.42	99	196	Off Idle	59.6	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.6	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:5	34.08	2618	2.19	13.4	99	196	Off Idle	59.5	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.57	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:5	34.08	2627	2.19	13.4	99	196	Off Idle	59.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.57	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:5	34.08	2627	2.19	13.41	99	196	Off Idle	59.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.6	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:5	34.08	2636	2.19	13.41	99	196	Off Idle	59.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.6	15.05	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:5	34.08	2644	2.19	13.4	99	197	Off Idle	59.2	0	2	132	944 Turbo	0.48	Rich	1	14.7	-6.61	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:5	34.08	2650	2.19	13.42	100	197	Off Idle	59.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.59	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:6	34.08	2650	2.19	13.42	100	197	Off Idle	58.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.61	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:6	34.08	2650	2.19	13.39	100	196	Off Idle	58.9	0	2	132	944 Turbo	0.29	Lean	1	14.7	-6.62	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:6	34.08	2671	2.19	13.41	99	196	Off Idle	58.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.61	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:6	34.08	2671	2.19	13.41	99	196	Off Idle	58.6	0	2	132	944 Turbo	0.19	Lean	1	14.7	-6.63	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:6	34.08	2650	2.19	13.39	99	196	Off Idle	58.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.63	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:6	34.08	2650	2.19	13.41	99	196	Off Idle	58.1	0	2	132	944 Turbo	0.15	Lean	1	14.7	-6.59	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:6	34.08	2646	2.19	13.41	99	196	Off Idle	58	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.55	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:7	34.08	2649	2.19	13.44	100	196	Off Idle	57.9	0	2	132	944 Turbo	0.19	Lean	1	14.7	-6.6	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:7	34.08	2648	2.19	13.42	100	196	Off Idle	57.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.58	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:7	34.08	2649	2.2	13.43	100	196	Off Idle	57.6	0	2	132	944 Turbo	0.26	Lean	1	14.7	-6.57	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:14:7	34.08	2649	2.2	13.42	99	196	Off Idle	57.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-6.61	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:7	34.08	2654	2.2	13.42	99	196	Off Idle	57.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.61	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:7	34.08	2654	2.2	13.42	99	197	Off Idle	57.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.57	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:8	34.08	2658	2.2	13.43	99	197	Off Idle	57.1	0	2	132	944 Turbo	0.49	Rich	1	14.7	-6.6	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:8	34.08	2657	2.2	13.42	99	197	Off Idle	57.1	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.58	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:8	34.08	2658	2.2	13.41	99	197	Off Idle	57.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.56	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:8	34.08	2660	2.2	13.43	99	197	Off Idle	57	0	2	132	944 Turbo	0.65	Rich	1	14.7	-6.58	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:8	34.08	2660	2.2	13.43	99	197	Off Idle	57	0	2	132	944 Turbo	0.67	Rich	1	14.7	-6.55	15.05	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:8	34.08	2673	2.2	13.41	99	196	Off Idle	56.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-6.56	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:9	34.08	2673	2.21	13.42	99	196	Off Idle	56.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.53	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:9	34.08	2674	2.21	13.43	99	196	Off Idle	56.9	0	2	132	944 Turbo	0.75	Rich	1	14.7	-6.56	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:9	34.08	2672	2.21	13.41	99	197	Off Idle	56.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.59	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:9	34.08	2668	2.21	13.43	99	197	Off Idle	56.7	0	2	132	944 Turbo	0.76	Rich	1	14.7	-6.57	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:9	34.08	2667	2.21	13.43	99	197	Off Idle	56.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.59	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:9	34.08	2671	2.21	13.44	99	197	Off Idle	56.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.62	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:14:9	34.08	2673	2.21	13.45	99	197	Off Idle	56.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.63	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:0	34.08	2674	2.21	13.46	99	197	Off Idle	56.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.61	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:0	34.08	2678	2.21	13.45	99	197	Off Idle	56.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.66	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:0	34.08	2678	2.21	13.44	99	197	Off Idle	56.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.63	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:0	34.08	2682	2.21	13.44	100	197	Off Idle	56.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.64	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:0	34.08	2688	2.21	13.43	100	197	Off Idle	56.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.64	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:0	34.08	2689	2.21	13.44	99	197	Off Idle	56.3	0	2	132	944 Turbo	0.36	Rich	1	14.7	-6.64	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:1	34.08	2694	2.21	13.43	99	197	Off Idle	56.3	0	2	132	944 Turbo	0.3	Lean	1	14.7	-6.65	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:1	34.08	2695	2.21	13.43	99	196	Off Idle	56.1	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.61	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:1	34.08	2698	2.21	13.44	99	196	Off Idle	56	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.63	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:1	34.08	2696	2.21	13.44	99	196	Off Idle	55.8	0	2	132	944 Turbo	0.19	Lean	1	14.7	-6.62	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:1	34.08	2694	2.21	13.44	99	197	Off Idle	55.8	0	2	132	944 Turbo	0.2	Lean	1	14.7	-6.64	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:15:1	34.08	2695	2.21	13.42	99	197	Off Idle	55.7	0	2	132	944 Turbo	0.24	Lean	1	14.7	-6.65	14.9	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:1	34.08	2695	2.21	13.44	99	197	Off Idle	55.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.68	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:2	34.08	2692	2.21	13.44	99	197	Off Idle	55.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.7	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:15:2	34.08	2691	2.21	13.44	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-6.69	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:2	34.08	2686	2.21	13.44	100	197	Off Idle	55	0	2	132	944 Turbo	0.44	Rich	1	14.7	-6.7	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:2	34.08	2686	2.21	13.43	100	196	Off Idle	54.9	0	2	132	944 Turbo	0.48	Rich	1	14.7	-6.69	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:2	34.08	2688	2.21	13.42	100	196	Off Idle	54.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.69	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:2	34.08	2692	2.21	13.42	100	196	Off Idle	55.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.75	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:3	34.08	2694	2.21	13.42	99	197	Off Idle	55.4	0	2	132	944 Turbo	0.64	Rich	1	14.7	-6.73	15.13	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:15:3	34.08	2699	2.21	13.41	99	197	Off Idle	55.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.7	15.1	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:15:3	34.08	2703	2.21	13.42	99	197	Off Idle	55.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.72	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:15:3	34.08	2710	2.21	13.43	99	197	Off Idle	55.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.75	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:3	34.08	2710	2.2	13.43	99	196	Off Idle	55.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.73	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:3	34.08	2713	2.2	13.44	99	196	Off Idle	55.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.77	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:4	34.08	2718	2.2	13.44	99	196	Off Idle	55.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.83	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:4	34.08	2720	2.2	13.44	99	197	Off Idle	55	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.85	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:4	34.08	2724	2.2	13.44	99	197	Off Idle	55.1	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.87	14.89	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:4	34.08	2728	2.19	13.44	99	197	Off Idle	55.1	0	2	132	944 Turbo	0.36	Lean	1	14.7	-6.89	14.84	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:15:4	34.08	2728	2.19	13.43	99	197	Off Idle	55.1	0	2	132	944 Turbo	0.37	Lean	1	14.7	-6.91	14.82	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:15:4	34.08	2734	2.19	13.44	99	197	Off Idle	54.9	0	2	132	944 Turbo	0.4	Lean	1	14.7	-6.97	14.8	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:15:4	35.45	2723	2.18	13.45	99	196	Off Idle	54.8	0	2	132	944 Turbo	0.46	Lean	1	14.7	-7.03	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:15:5	35.45	2720	2.18	13.45	99	196	Off Idle	54.6	0	2	132	944 Turbo	0.48	Lean	1	14.7	-7.02	14.82	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:15:5	35.45	2716	2.17	13.46	99	196	Off Idle	54.4	0	2	132	944 Turbo	0.53	Lean	1	14.7	-7.1	14.83	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:15:5	35.45	2712	2.17	13.45	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.12	14.86	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:15:5	35.45	2710	2.16	13.44	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.65	Rich	1	14.7	-7.16	14.87	1.01	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:15:5	35.45	2710	2.16	13.43	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.7	Rich	1	14.7	-7.21	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:5	35.45	2712	2.15	13.42	99	197	Off Idle	54.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-7.27	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:6	35.45	2713	2.15	13.42	99	197	Off Idle	54.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.27	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:6	35.45	2713	2.14	13.42	99	197	Off Idle	54.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.31	14.97	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:6	35.45	2716	2.14	13.42	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.35	15	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:15:6	35.45	2720	2.13	13.41	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.37	14.99	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:6	35.45	2727	2.13	13.42	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.41	14.96	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:6	35.45	2727	2.12	13.43	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.48	14.94	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:6	35.45	2728	2.11	13.41	100	197	Off Idle	54.6	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.49	14.93	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:7	35.45	2736	2.11	13.43	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.51	14.9	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:7	35.45	2737	2.1	13.43	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.53	14.86	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:7	35.45	2750	2.1	13.44	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.55	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:7	35.45	2740	2.09	13.44	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.58	14.82	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:7	35.45	2740	2.09	13.45	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.58	14.79	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:7	35.45	2740	2.09	13.45	100	197	Off Idle	54	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.58	14.77	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:8	35.45	2737	2.08	13.45	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.63	14.78	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:8	35.45	2728	2.08	13.44	100	197	Off Idle	53.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.62	14.8	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:8	35.45	2728	2.08	13.44	100	197	Off Idle	53.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.63	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:15:8	35.45	2733	2.08	13.42	99	197	Off Idle	53.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.6	14.86	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:15:8	35.45	2728	2.07	13.42	99	197	Off Idle	53.4	0	2	132	944 Turbo	0.25	Rich	1	14.7	-7.62	14.88	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:8	35.45	2728	2.07	13.44	99	197	Off Idle	53.4	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.62	14.89	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:15:9	35.45	2727	2.07	13.44	99	197	Off Idle	53.4	0	2	132	944 Turbo	0.35	Rich	1	14.7	-7.63	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:15:9	35.45	2709	2.07	13.43	99	197	Off Idle	53.4	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.67	14.97	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:15:9	35.45	2737	2.07	13.45	99	197	Off Idle	53.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.69	15.02	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:15:9	35.45	2740	2.06	13.45	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.53	Rich	1	14.7	-7.72	15.05	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:15:9	35.45	2742	2.06	13.46	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.75	15.06	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:15:9	35.45	2750	2.06	13.46	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.76	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:15:9	35.45	2764	2.06	13.45	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.66	Rich	1	14.7	-7.75	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:16:0	35.45	2755	2.06	13.45	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.75	15.07	1.03	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:16:0	35.45	2754	2.06	13.44	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.61	Rich	1	14.7	-7.75	15.06	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:0	35.45	2772	2.06	13.44	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.78	15.07	1.03	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:0	35.45	2772	2.06	13.44	100	197	Off Idle	53.1	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.77	15.05	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:0	35.45	2751	2.05	13.44	100	197	Off Idle	52.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.79	15.04	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:0	35.45	2753	2.05	13.44	99	197	Off Idle	52.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.78	15.02	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:1	35.45	2753	2.05	13.44	99	197	Off Idle	52.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.81	15.01	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:1	35.45	2747	2.05	13.45	99	197	Off Idle	52.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.8	14.99	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:16:1	35.45	2757	2.05	13.43	99	197	Off Idle	52.3	0	2	132	944 Turbo	0.2	Lean	1	14.7	-7.85	14.96	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:1	35.45	2756	2.04	13.42	99	197	Off Idle	51.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.88	14.93	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:16:1	35.45	2754	2.04	13.43	99	197	Off Idle	51.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.9	14.91	1.02	3.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:16:1	35.45	2753	2.04	13.42	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.91	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:1	35.45	2752	2.04	13.43	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.94	14.89	1.01	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:2	35.45	2745	2.04	13.43	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.25	Rich	1	14.7	-7.96	14.9	1.02	3.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:16:2	35.45	2742	2.03	13.44	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.99	14.93	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:16:2	35.45	2750	2.03	13.44	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.02	14.95	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:16:2	35.45	2738	2.03	13.44	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.01	14.97	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:2	35.45	2738	2.03	13.44	99	196	Off Idle	52	0	2	132	944 Turbo	0.53	Rich	1	14.7	-8.04	15	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:2	35.45	2738	2.02	13.44	99	196	Off Idle	52.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-8.07	15.04	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:3	35.45	2717	2.02	13.44	99	197	Off Idle	52.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.08	15.07	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:3	35.45	2734	2.02	13.46	99	197	Off Idle	52.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.06	15.12	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:3	35.45	2734	2.01	13.45	99	197	Off Idle	52.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.09	15.13	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:3	35.45	2742	2.01	13.45	99	197	Off Idle	52.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-8.1	15.15	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:3	35.45	2745	2.01	13.44	99	197	Off Idle	52.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-8.12	15.11	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:3	35.45	2748	2	13.45	99	197	Off Idle	52.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.13	15.06	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:4	35.45	2759	2	13.45	99	197	Off Idle	52.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.14	15.03	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:4	35.45	2772	2	13.44	99	197	Off Idle	52.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.16	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:4	35.45	2772	1.99	13.46	99	197	Off Idle	52.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.2	14.94	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:4	35.45	2790	1.99	13.44	100	197	Off Idle	52.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.22	14.9	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:4	35.45	2782	1.99	13.44	100	197	Off Idle	52.1	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.22	14.86	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:4	35.45	2783	1.99	13.44	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-8.22	14.79	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:4	35.45	2784	1.99	13.44	100	197	Off Idle	51.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.24	14.76	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:5	35.45	2784	1.98	13.45	100	197	Off Idle	51.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.24	14.73	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:5	35.45	2780	1.98	13.44	100	197	Off Idle	51.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.22	14.72	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:5	35.45	2781	1.98	13.44	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.25	14.75	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:5	35.45	2776	1.98	13.46	100	197	Off Idle	51.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.28	14.76	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:5	35.45	2754	1.98	13.45	99	197	Off Idle	51	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.32	14.75	1	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:5	35.45	2762	1.97	13.43	99	197	Off Idle	51	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.32	14.76	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:6	35.45	2765	1.97	13.44	99	197	Off Idle	51	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.35	14.78	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:6	35.45	2762	1.97	13.43	100	197	Off Idle	50.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.34	14.83	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:6	35.45	2762	1.97	13.43	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.39	14.87	1.01	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:6	35.45	2762	1.97	13.42	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.39	14.89	1.01	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:6	35.45	2755	1.96	13.43	99	197	Off Idle	50.4	0	2	132	944 Turbo	0.36	Rich	1	14.6	-8.39	14.91	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:6	35.45	2755	1.96	13.43	99	197	Off Idle	50.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.43	14.94	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:6	35.45	2759	1.96	13.44	99	197	Off Idle	50.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.44	14.98	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:7	35.45	2758	1.96	13.44	99	197	Off Idle	50.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-8.44	15.02	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:7	35.45	2763	1.96	13.44	99	197	Off Idle	50.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.44	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:7	35.45	2764	1.95	13.44	99	197	Off Idle	50.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.48	15.05	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:7	35.45	2767	1.95	13.44	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.49	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:7	35.45	2767	1.95	13.44	100	197	Off Idle	51.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.49	15.05	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:7	35.45	2770	1.95	13.43	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.52	15.08	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:8	35.45	2768	1.94	13.43	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.56	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:8	35.45	2765	1.94	13.43	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.54	15.06	1.03	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:8	35.45	2750	1.94	13.44	99	197	Off Idle	51.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.52	15.04	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:8	35.45	2750	1.93	13.45	99	197	Off Idle	51.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.55	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:8	35.45	2752	1.93	13.45	99	197	Off Idle	51.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.54	14.97	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:8	35.45	2756	1.93	13.44	99	197	Off Idle	51.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-8.52	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:16:9	35.45	2760	1.93	13.45	99	197	Off Idle	51.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.54	14.93	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:9	35.45	2760	1.92	13.45	99	197	Off Idle	51.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.57	14.9	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:9	35.45	2771	1.92	13.44	99	197	Off Idle	51.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-8.56	14.84	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:9	35.45	2773	1.92	13.44	99	197	Off Idle	51.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-8.55	14.83	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:9	35.45	2774	1.92	13.43	99	197	Off Idle	51.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-8.57	14.81	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:9	35.45	2798	1.92	13.42	99	197	Off Idle	51.1	0	2	132	944 Turbo	0.26	Lean	1	14.6	-8.56	14.8	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:16:9	35.45	2782	1.92	13.42	99	197	Off Idle	50.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.55	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:0	35.45	2784	1.92	13.44	100	197	Off Idle	50.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.58	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:0	35.45	2784	1.92	13.44	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.57	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:17:0	35.45	2788	1.92	13.45	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.57	14.8	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:0	35.45	2788	1.92	13.45	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.57	14.82	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:0	35.45	2781	1.92	13.46	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.58	14.83	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:0	35.45	2781	1.92	13.46	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.59	14.87	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:1	35.45	2780	1.92	13.44	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.59	14.89	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:1	35.45	2776	1.92	13.46	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.59	14.92	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:1	35.45	2772	1.92	13.44	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.45	Rich	1	14.7	-8.63	14.96	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:1	35.45	2760	1.92	13.43	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.66	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:1	35.45	2760	1.92	13.43	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.58	Rich	1	14.7	-8.65	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:1	35.45	2744	1.91	13.43	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.68	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:1	35.45	2753	1.91	13.42	100	197	Off Idle	50.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.7	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:2	35.45	2754	1.91	13.43	100	197	Off Idle	50.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.67	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:2	35.45	2756	1.91	13.44	100	197	Off Idle	50.9	0	2	132	944 Turbo	0.74	Rich	1	14.7	-8.67	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:2	35.45	2748	1.91	13.43	100	197	Off Idle	50.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.68	15.12	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:2	35.45	2750	1.91	13.43	100	197	Off Idle	50.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.71	15.11	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:2	35.45	2750	1.91	13.45	100	197	Off Idle	50.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.7	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:2	35.45	2757	1.9	13.44	99	197	Off Idle	51.1	0	2	132	944 Turbo	0.65	Lean	1	14.6	-8.71	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:3	35.45	2743	1.9	13.44	99	197	Off Idle	51.2	0	2	132	944 Turbo	0.61	Lean	1	14.6	-8.71	15.02	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:3	35.45	2743	1.9	13.43	99	197	Off Idle	51.2	0	2	132	944 Turbo	0.53	Lean	1	14.7	-8.73	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:3	35.45	2764	1.9	13.43	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.73	14.96	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:3	35.45	2764	1.9	13.44	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.77	14.93	1.02	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:3	35.45	2797	1.9	13.43	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.76	14.89	1.01	3.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:3	35.45	2797	1.9	13.43	99	197	Off Idle	51.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-8.78	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:4	35.45	2779	1.9	13.43	99	197	Off Idle	51.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.79	14.84	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:4	35.45	2785	1.89	13.43	100	197	Off Idle	51.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.75	14.83	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:4	35.45	2785	1.89	13.44	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.75	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:4	35.45	2794	1.89	13.44	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.76	14.82	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:4	35.45	2787	1.89	13.44	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.76	14.81	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:4	35.45	2780	1.89	13.44	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.8	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:4	35.45	2778	1.89	13.43	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.83	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:5	35.45	2777	1.89	13.44	100	197	Off Idle	50.9	0	2	132	944 Turbo	0.34	Lean	1	14.7	-8.83	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:5	35.45	2773	1.89	13.43	100	197	Off Idle	50.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-8.79	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:5	35.45	2767	1.89	13.45	100	197	Off Idle	50.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-8.78	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:5	35.45	2767	1.89	13.43	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.54	Lean	1	14.6	-8.79	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:5	35.45	2762	1.89	13.44	100	197	Off Idle	50.4	0	2	132	944 Turbo	0.6	Lean	1	14.6	-8.77	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:5	35.45	2758	1.89	13.43	100	197	Off Idle	50.1	0	2	132	944 Turbo	0.67	Lean	1	14.6	-8.78	14.98	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:6	35.45	2759	1.89	13.43	100	197	Off Idle	50.1	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.79	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:6	35.45	2756	1.89	13.41	100	197	Off Idle	50.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.77	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:6	35.45	2747	1.89	13.42	100	197	Off Idle	50.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.77	15.07	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:6	35.45	2747	1.89	13.41	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.7	Rich	1	14.7	-8.83	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:6	35.45	2746	1.89	13.41	100	197	Off Idle	50.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-8.8	15.1	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:6	35.45	2746	1.89	13.43	100	197	Off Idle	50.9	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.8	15.08	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:6	35.45	2750	1.89	13.43	99	197	Off Idle	51.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.83	15.05	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:7	35.45	2742	1.89	13.43	99	197	Off Idle	51.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-8.78	15.03	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:7	35.45	2768	1.88	13.43	99	197	Off Idle	51.4	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.79	15	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:7	35.45	2768	1.88	13.45	100	197	Off Idle	51.5	0	2	132	944 Turbo	0.33	Rich	1	14.6	-8.8	14.99	1.02	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:7	35.45	2770	1.88	13.45	100	197	Off Idle	51.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.83	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:7	35.45	2786	1.88	13.46	100	197	Off Idle	51.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.87	14.92	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:7	35.45	2786	1.88	13.46	100	197	Off Idle	51.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.86	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:8	35.45	2781	1.88	13.46	100	197	Off Idle	51.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.88	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:8	35.45	2776	1.88	13.46	100	197	Off Idle	51.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.9	14.78	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:17:8	35.45	2774	1.88	13.44	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-8.88	14.77	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:8	35.45	2773	1.87	13.43	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.9	14.76	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:8	35.45	2774	1.87	13.43	99	197	Off Idle	51.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.87	14.76	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:8	35.45	2775	1.87	13.42	99	197	Off Idle	51.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.84	14.77	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:9	35.45	2778	1.87	13.42	99	197	Off Idle	50.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.85	14.79	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:9	35.45	2769	1.87	13.44	99	197	Off Idle	50.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-8.85	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:9	35.45	2768	1.87	13.44	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.56	Rich	1	14.7	-8.86	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:17:9	35.45	2768	1.87	13.45	100	197	Off Idle	50.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-8.86	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:9	35.45	2763	1.87	13.45	100	197	Off Idle	50.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.89	14.95	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:9	35.45	2756	1.87	13.45	100	197	Off Idle	50.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.89	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:17:9	35.45	2756	1.87	13.45	100	197	Off Idle	50.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.86	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:0	35.45	2763	1.87	13.45	99	197	Off Idle	50.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.86	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:0	35.45	2761	1.87	13.44	99	197	Off Idle	50.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-8.87	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:0	35.45	2759	1.87	13.44	99	197	Off Idle	50.9	0	2	132	944 Turbo	0.59	Rich	1	14.6	-8.88	15.09	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:0	35.45	2759	1.87	13.44	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-8.87	15.09	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:0	35.45	2760	1.87	13.44	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.9	15.08	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:0	35.45	2757	1.87	13.42	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.91	15.05	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:1	35.45	2759	1.87	13.43	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.92	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:1	35.45	2759	1.87	13.44	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.3	Lean	1	14.7	-8.93	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:1	35.45	2756	1.87	13.41	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.93	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:1	35.45	2759	1.87	13.43	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.94	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:1	35.45	2760	1.87	13.44	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.94	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:1	35.45	2751	1.87	13.45	100	197	Off Idle	51.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.94	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:1	35.45	2759	1.87	13.45	100	197	Off Idle	51.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.94	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:2	35.45	2760	1.87	13.45	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.95	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:2	35.45	2760	1.87	13.44	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.42	Rich	1	14.6	-8.94	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:2	35.45	2765	1.87	13.44	100	197	Off Idle	51.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.92	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:2	35.45	2749	1.87	13.44	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.94	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:2	35.45	2748	1.87	13.44	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8.93	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:2	35.45	2744	1.87	13.44	99	197	Off Idle	51.1	0	2	132	944 Turbo	0.64	Rich	1	14.7	-8.9	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:3	35.45	2740	1.87	13.43	99	197	Off Idle	51.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.89	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:3	35.45	2740	1.86	13.43	100	197	Off Idle	51.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-8.92	14.9	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:3	35.45	2722	1.86	13.43	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.91	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:3	35.45	2722	1.86	13.43	100	197	Off Idle	51.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-8.9	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:3	35.45	2738	1.86	13.41	100	197	Off Idle	51.7	0	2	132	944 Turbo	0.67	Rich	1	14.6	-8.88	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:3	35.45	2742	1.86	13.44	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.62	Lean	1	14.7	-8.91	15.02	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:4	35.45	2746	1.86	13.43	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-8.93	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:4	35.45	2750	1.86	13.44	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-8.94	15.01	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:4	35.45	2750	1.86	13.46	100	197	Off Idle	52.1	0	2	132	944 Turbo	0.45	Lean	1	14.6	-8.99	15	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:4	35.45	2755	1.86	13.46	100	197	Off Idle	52.4	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.97	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:4	35.45	2755	1.86	13.45	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:4	35.45	2753	1.86	13.44	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.96	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:4	35.45	2752	1.86	13.44	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.96	14.94	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:5	35.45	2752	1.86	13.43	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.97	14.9	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:5	35.45	2749	1.86	13.42	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.98	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:5	35.45	2754	1.86	13.44	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.02	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:5	35.45	2754	1.86	13.43	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.02	14.82	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:5	35.45	2758	1.86	13.46	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.4	Rich	1	14.7	-9.03	14.84	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:5	35.45	2769	1.86	13.45	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.03	14.85	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:6	35.45	2760	1.85	13.46	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.04	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:6	35.45	2760	1.85	13.44	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.01	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:6	35.45	2756	1.85	13.45	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.04	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:6	35.45	2752	1.85	13.44	100	197	Off Idle	52.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.03	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:6	35.45	2750	1.85	13.44	100	197	Off Idle	51.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.04	14.9	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:6	35.45	2742	1.85	13.44	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.04	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:6	35.45	2738	1.85	13.45	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.04	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:7	35.45	2737	1.85	13.44	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.05	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:7	35.45	2691	1.84	13.45	100	197	Off Idle	51.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.09	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:7	35.45	2729	1.84	13.46	100	197	Off Idle	51.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.09	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:7	35.45	2728	1.84	13.45	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.11	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:7	35.45	2728	1.84	13.46	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.14	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:7	35.45	2730	1.83	13.47	100	197	Off Idle	52	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.16	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:8	35.45	2730	1.83	13.45	99	197	Off Idle	52.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.15	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:8	35.45	2734	1.83	13.45	99	197	Off Idle	52.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.19	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:8	35.45	2734	1.82	13.46	99	197	Off Idle	52.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-9.23	14.88	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:18:8	35.45	2755	1.82	13.45	99	197	Off Idle	52.6	0	2	132	944 Turbo	0.46	Lean	1	14.7	-9.24	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:8	35.45	2743	1.82	13.44	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.21	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:8	35.45	2734	1.81	13.44	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.23	14.77	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:9	35.45	2736	1.81	13.43	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.24	14.76	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:9	35.45	2717	1.81	13.45	100	197	Off Idle	53	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.23	14.76	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:9	36.81	2728	1.81	13.43	100	197	Off Idle	53	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.24	14.76	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:9	36.81	2738	1.81	13.43	100	197	Off Idle	53	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.24	14.77	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:9	36.81	2743	1.8	13.45	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.23	14.78	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:18:9	36.81	2744	1.8	13.45	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.22	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:18:9	36.81	2744	1.8	13.44	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.23	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:0	35.45	2748	1.8	13.45	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.26	14.78	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:0	35.45	2749	1.8	13.46	100	197	Off Idle	52.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.28	14.79	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:0	35.45	2748	1.8	13.46	99	197	Off Idle	52.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.28	14.83	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:0	35.45	2752	1.8	13.45	99	197	Off Idle	52.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.3	14.86	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:0	35.45	2766	1.8	13.45	99	197	Off Idle	52.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.3	14.89	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:0	36.81	2759	1.8	13.45	100	197	Off Idle	52.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.28	14.91	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:1	36.81	2758	1.8	13.45	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.27	14.93	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:1	36.81	2755	1.8	13.45	100	197	Off Idle	52.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.3	14.95	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:1	36.81	2756	1.8	13.44	100	197	Off Idle	52.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.28	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:1	36.81	2758	1.8	13.44	100	197	Off Idle	52	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.31	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:1	36.81	2755	1.8	13.43	100	197	Off Idle	52	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.31	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:1	36.81	2751	1.8	13.43	100	197	Off Idle	52	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.3	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:1	36.81	2751	1.8	13.42	100	197	Off Idle	52	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.28	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:2	36.81	2742	1.8	13.42	100	197	Off Idle	52	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.27	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:2	36.81	2734	1.8	13.41	100	197	Off Idle	52	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.25	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:2	36.81	2703	1.8	13.43	100	197	Off Idle	52	0	2	132	944 Turbo	0.69	Rich	1	14.7	-9.26	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:2	36.81	2703	1.8	13.43	100	197	Off Idle	52	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.25	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:2	36.81	2712	1.8	13.41	100	197	Off Idle	52	0	2	132	944 Turbo	0.68	Rich	1	14.7	-9.25	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:2	36.81	2712	1.8	13.44	100	197	Off Idle	52	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.25	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:3	36.81	2706	1.8	13.44	100	197	Off Idle	52.2	0	2	132	944 Turbo	0.59	Rich	1	14.7	-9.25	15.08	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:3	36.81	2705	1.8	13.44	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.27	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:3	36.81	2705	1.8	13.45	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.3	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:3	35.45	2711	1.8	13.46	100	197	Off Idle	53	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.31	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:3	35.45	2719	1.8	13.44	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.33	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:3	35.45	2719	1.8	13.45	100	197	Off Idle	53.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.31	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:4	35.45	2745	1.8	13.44	100	197	Off Idle	53.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.32	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:4	35.45	2725	1.8	13.44	100	197	Off Idle	53.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.33	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:4	35.45	2733	1.79	13.45	100	197	Off Idle	53.7	0	2	132	944 Turbo	0.16	Lean	1	14.7	-9.34	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:4	35.45	2735	1.79	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.35	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:4	35.45	2740	1.79	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.34	14.87	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:4	35.45	2744	1.79	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.35	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:4	35.45	2744	1.79	13.45	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.35	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:5	35.45	2760	1.79	13.45	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-9.35	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:5	36.81	2753	1.79	13.46	100	197	Off Idle	53.6	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.35	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:5	36.81	2754	1.79	13.45	100	197	Off Idle	53.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.35	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:5	36.81	2756	1.78	13.45	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.34	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:5	36.81	2758	1.78	13.43	100	197	Off Idle	53.1	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.35	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:5	36.81	2782	1.78	13.44	100	197	Off Idle	52.8	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.35	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:6	36.81	2770	1.78	13.44	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.68	Lean	1	14.6	-9.33	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:6	36.81	2756	1.78	13.44	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.71	Lean	1	14.6	-9.33	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:6	36.81	2748	1.78	13.45	100	197	Off Idle	52.2	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9.31	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:6	36.81	2721	1.78	13.44	100	197	Off Idle	52	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.3	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:6	36.81	2732	1.79	13.44	100	197	Off Idle	52	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.26	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:6	36.81	2744	1.79	13.44	100	197	Off Idle	52	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.29	15.09	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:6	36.81	2741	1.79	13.44	100	197	Off Idle	52	0	2	132	944 Turbo	0.69	Rich	1	14.7	-9.26	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:7	36.81	2715	1.79	13.43	100	197	Off Idle	52	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.29	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:7	36.81	2736	1.79	13.43	100	197	Off Idle	52	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.28	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:7	36.81	2736	1.79	13.45	100	197	Off Idle	52	0	2	132	944 Turbo	0.49	Rich	1	14.7	-9.33	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:19:7	36.81	2739	1.79	13.43	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.34	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:7	36.81	2756	1.79	13.45	100	197	Off Idle	51.9	0	2	132	944 Turbo	0.34	Rich	1	14.7	-9.35	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:7	36.81	2756	1.79	13.46	100	197	Off Idle	52	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.35	14.96	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:19:8	36.81	2739	1.79	13.45	100	197	Off Idle	52.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.35	14.93	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:8	36.81	2738	1.79	13.45	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.35	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:8	36.81	2738	1.79	13.45	100	197	Off Idle	52.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.35	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:8	36.81	2730	1.79	13.43	100	197	Off Idle	52.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.35	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:8	36.81	2744	1.79	13.43	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.34	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:8	36.81	2746	1.79	13.42	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.35	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:9	36.81	2746	1.79	13.42	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.34	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:9	36.81	2754	1.79	13.43	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.32	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:9	36.81	2743	1.79	13.43	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-9.32	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:9	36.81	2740	1.79	13.44	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.29	Rich	1	14.7	-9.31	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:9	36.81	2738	1.79	13.44	100	197	Off Idle	53	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.32	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:9	36.81	2739	1.79	13.45	100	197	Off Idle	53	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.35	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:19:9	36.81	2736	1.78	13.45	99	197	Off Idle	53	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.37	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:0	36.81	2738	1.78	13.45	99	197	Off Idle	52.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.38	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:0	36.81	2732	1.78	13.45	99	197	Off Idle	52.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.39	15.05	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:0	36.81	2707	1.78	13.45	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.39	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:0	36.81	2707	1.78	13.45	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.39	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:0	36.81	2721	1.78	13.44	100	197	Off Idle	52.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.38	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:0	36.81	2723	1.78	13.44	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.37	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:1	36.81	2723	1.78	13.44	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.37	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:1	36.81	2738	1.78	13.43	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:1	36.81	2719	1.78	13.43	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.34	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:1	36.81	2718	1.78	13.44	100	197	Off Idle	52.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.35	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:1	36.81	2719	1.78	13.45	100	197	Off Idle	52.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.35	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:1	36.81	2703	1.78	13.45	99	197	Off Idle	52.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.36	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:1	36.81	2720	1.78	13.45	99	197	Off Idle	52.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.38	15.01	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:2	36.81	2720	1.78	13.45	99	197	Off Idle	53.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.36	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:2	36.81	2721	1.78	13.45	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.37	14.99	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:20:2	36.81	2725	1.78	13.45	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.39	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:2	36.81	2726	1.78	13.43	100	197	Off Idle	53.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.38	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:2	36.81	2732	1.78	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.24	Lean	1	14.7	-9.37	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:2	36.81	2743	1.78	13.45	100	197	Off Idle	53.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.38	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:3	36.81	2743	1.78	13.46	100	197	Off Idle	53.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.39	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:3	36.81	2746	1.77	13.44	100	197	Off Idle	53.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.4	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:3	36.81	2753	1.77	13.46	100	197	Off Idle	53.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.4	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:3	36.81	2753	1.77	13.46	100	197	Off Idle	53.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.42	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:3	36.81	2759	1.77	13.45	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.44	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:3	36.81	2758	1.77	13.45	100	197	Off Idle	53.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.43	14.83	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:20:4	36.81	2758	1.77	13.44	100	197	Off Idle	53.6	0	2	132	944 Turbo	0.44	Lean	1	14.6	-9.44	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:4	36.81	2756	1.77	13.43	100	197	Off Idle	53.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.46	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:4	36.81	2754	1.77	13.43	100	197	Off Idle	53.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.43	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:4	36.81	2743	1.77	13.43	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.41	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:4	36.81	2742	1.77	13.42	100	197	Off Idle	53.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.4	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:4	36.81	2728	1.77	13.43	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.37	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:4	36.81	2716	1.77	13.45	100	197	Off Idle	52.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.37	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:5	36.81	2716	1.77	13.45	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.36	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:5	36.81	2711	1.77	13.45	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.37	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:5	36.81	2710	1.77	13.45	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.38	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:5	36.81	2710	1.77	13.45	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.64	Lean	1	14.6	-9.39	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:5	36.81	2712	1.77	13.45	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.58	Lean	1	14.6	-9.35	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:5	36.81	2706	1.77	13.44	100	197	Off Idle	52.8	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.39	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:6	36.81	2706	1.77	13.45	100	197	Off Idle	52.9	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.39	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:6	36.81	2707	1.77	13.44	100	197	Off Idle	53.1	0	2	132	944 Turbo	0.39	Lean	1	14.6	-9.4	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:6	36.81	2686	1.77	13.45	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.38	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:6	35.45	2708	1.77	13.45	100	197	Off Idle	53.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.4	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:20:6	35.45	2710	1.78	13.43	100	197	Off Idle	53.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.37	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:20:6	35.45	2713	1.78	13.44	100	197	Off Idle	53.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.37	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:6	35.45	2718	1.77	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.38	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:7	35.45	2716	1.77	13.45	100	197	Off Idle	53.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.42	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:7	36.81	2730	1.77	13.44	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.43	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:7	36.81	2719	1.77	13.43	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.41	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:7	36.81	2729	1.77	13.44	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.4	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:7	36.81	2720	1.77	13.42	100	197	Off Idle	54.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.41	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:7	36.81	2721	1.77	13.44	100	197	Off Idle	54.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.38	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:8	36.81	2720	1.77	13.45	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.36	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:8	35.45	2708	1.77	13.45	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.36	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:8	35.45	2700	1.77	13.43	100	197	Off Idle	54.2	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.39	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:8	35.45	2723	1.77	13.44	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-9.38	14.99	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:8	35.45	2723	1.77	13.42	100	197	Off Idle	54	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.39	15.01	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:8	35.45	2728	1.77	13.43	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.42	15.08	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:9	35.45	2734	1.77	13.43	100	197	Off Idle	53.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.42	15.11	1.03	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:9	35.45	2728	1.77	13.43	100	197	Off Idle	53.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.44	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:9	35.45	2728	1.77	13.44	100	197	Off Idle	53.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.4	15.13	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:9	35.45	2730	1.77	13.44	100	197	Off Idle	53.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.4	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:9	35.45	2744	1.77	13.44	100	197	Off Idle	53.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.39	15.11	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:9	35.45	2748	1.77	13.43	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.41	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:20:9	36.81	2738	1.77	13.43	100	197	Off Idle	53.1	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.38	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:0	36.81	2727	1.77	13.44	100	197	Off Idle	53	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.41	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:0	36.81	2727	1.77	13.43	100	197	Off Idle	53	0	2	132	944 Turbo	0.46	Lean	1	14.6	-9.4	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:0	36.81	2728	1.77	13.43	100	197	Off Idle	53	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.4	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:0	36.81	2734	1.77	13.43	100	197	Off Idle	53	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.41	15.02	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:0	36.81	2731	1.77	13.43	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.38	14.99	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:0	36.81	2732	1.77	13.43	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.39	14.97	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:1	36.81	2734	1.77	13.42	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.36	14.96	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:1	36.81	2736	1.77	13.43	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.35	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:1	36.81	2743	1.77	13.43	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.35	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:1	36.81	2743	1.77	13.45	100	197	Off Idle	53.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.37	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:1	36.81	2744	1.77	13.45	100	197	Off Idle	53.1	0	2	132	944 Turbo	0.22	Lean	1	14.7	-9.37	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:1	36.81	2748	1.77	13.45	100	197	Off Idle	53.1	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.38	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:1	36.81	2748	1.77	13.46	100	197	Off Idle	53.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.39	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:2	36.81	2743	1.77	13.45	100	197	Off Idle	53	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.4	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:2	36.81	2743	1.77	13.45	100	197	Off Idle	53	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.38	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:2	36.81	2744	1.77	13.45	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.39	14.87	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:2	36.81	2730	1.78	13.44	100	197	Off Idle	52.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.36	14.91	1.02	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:2	36.81	2720	1.78	13.44	100	197	Off Idle	52.6	0	2	132	944 Turbo	0.69	Rich	1	14.7	-9.35	14.94	1.02	3.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:2	36.81	2674	1.78	13.44	100	197	Off Idle	52.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.35	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:3	36.81	2694	1.78	13.43	100	197	Off Idle	52.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.33	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:3	36.81	2708	1.78	13.45	100	197	Off Idle	52.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.34	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:3	36.81	2704	1.78	13.46	100	197	Off Idle	52.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.35	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:3	36.81	2705	1.78	13.45	100	197	Off Idle	52.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.36	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:3	36.81	2707	1.78	13.45	100	197	Off Idle	52.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.38	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:3	36.81	2706	1.78	13.45	99	197	Off Idle	52.7	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.38	15.06	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:4	36.81	2704	1.78	13.44	99	197	Off Idle	52.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.37	15.05	1.03	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:4	36.81	2705	1.78	13.44	99	197	Off Idle	53	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.37	15.03	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:4	36.81	2705	1.78	13.44	100	197	Off Idle	53.1	0	2	132	944 Turbo	0.33	Rich	1	14.6	-9.37	15.01	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:4	36.81	2703	1.78	13.44	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-9.35	14.98	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:4	36.81	2700	1.78	13.44	100	197	Off Idle	53.3	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.35	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:4	36.81	2700	1.78	13.44	100	197	Off Idle	53.6	0	2	132	944 Turbo	0.15	Rich	1	14.6	-9.39	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:4	36.81	2696	1.78	13.44	100	197	Off Idle	53.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.38	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:5	36.81	2696	1.78	13.44	100	197	Off Idle	54	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.39	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:5	36.81	2691	1.78	13.45	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.39	14.87	1.01	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:5	36.81	2691	1.78	13.44	100	197	Off Idle	54.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.38	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:5	36.81	2694	1.78	13.44	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.39	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:21:8	36.81	2694	1.77	13.43	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.4	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	36.81	2689	1.77	13.44	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.43	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	35.45	2702	1.77	13.43	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.43	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	35.45	2702	1.77	13.44	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.41	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	35.45	2701	1.77	13.44	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.41	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	35.45	2704	1.77	13.44	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.44	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	35.45	2705	1.77	13.43	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.44	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	35.45	2714	1.77	13.45	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.43	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	36.81	2708	1.77	13.45	100	197	Off Idle	54.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.45	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:7	36.81	2707	1.76	13.43	100	197	Off Idle	54.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.44	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:7	36.81	2706	1.76	13.43	100	197	Off Idle	54.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.43	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:7	36.81	2710	1.76	13.44	100	197	Off Idle	54.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.46	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:7	36.81	2712	1.76	13.44	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.46	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:7	36.81	2705	1.76	13.44	100	197	Off Idle	54.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.46	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:7	36.81	2703	1.76	13.44	100	197	Off Idle	54.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.45	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	36.81	2700	1.76	13.44	100	197	Off Idle	53.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.46	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	36.81	2700	1.76	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.43	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	36.81	2700	1.76	13.43	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.4	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	36.81	2698	1.77	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.43	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	36.81	2698	1.77	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.4	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:8	36.81	2700	1.77	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.39	14.97	1.02	3.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:21:9	36.81	2707	1.77	13.45	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.4	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:9	36.81	2712	1.77	13.45	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.42	14.9	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:9	36.81	2715	1.77	13.44	100	197	Off Idle	53.8	0	2	132	944 Turbo	0.25	Rich	1	14.6	-9.37	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:9	36.81	2715	1.77	13.45	100	197	Off Idle	53.9	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.4	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:9	36.81	2715	1.77	13.43	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.41	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:9	36.81	2714	1.77	13.43	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.38	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:21:9	36.81	2714	1.77	13.44	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.37	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:0	36.81	2723	1.77	13.44	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.39	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:0	36.81	2712	1.77	13.44	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.4	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:0	36.81	2710	1.77	13.45	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.41	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:0	36.81	2704	1.77	13.44	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.44	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:0	36.81	2684	1.77	13.44	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.42	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:0	36.81	2690	1.77	13.45	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-9.43	14.92	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:1	36.81	2690	1.77	13.44	100	197	Off Idle	54.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.44	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:1	36.81	2682	1.77	13.43	100	197	Off Idle	54.4	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.4	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:1	36.81	2682	1.77	13.44	100	197	Off Idle	54.6	0	2	132	944 Turbo	0.69	Rich	1	14.7	-9.41	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:1	36.81	2682	1.76	13.44	100	197	Off Idle	54.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.42	15.03	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:1	36.81	2676	1.76	13.44	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9.42	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:1	36.81	2679	1.76	13.42	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.39	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:1	36.81	2677	1.76	13.42	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.43	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:2	36.81	2674	1.76	13.42	100	197	Off Idle	55.1	0	2	132	944 Turbo	0.65	Rich	1	14.7	-9.45	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:2	36.81	2674	1.76	13.44	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.47	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:2	36.81	2674	1.76	13.42	100	197	Off Idle	55.4	0	2	132	944 Turbo	0.56	Rich	1	14.7	-9.49	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:2	36.81	2672	1.76	13.44	100	197	Off Idle	56	0	2	132	944 Turbo	0.47	Lean	1	14.6	-9.46	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:2	36.81	2673	1.76	13.42	100	197	Off Idle	56.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.46	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:2	36.81	2674	1.76	13.43	100	197	Off Idle	56.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.45	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:3	35.45	2674	1.76	13.43	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-9.46	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:3	35.45	2674	1.75	13.45	100	197	Off Idle	56.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.46	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:3	35.45	2671	1.75	13.45	100	197	Off Idle	56.8	0	2	132	944 Turbo	0.17	Lean	1	14.7	-9.43	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:3	35.45	2670	1.75	13.44	100	197	Off Idle	56.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.45	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:3	35.45	2674	1.75	13.44	100	197	Off Idle	56.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.44	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:3	35.45	2698	1.75	13.43	100	197	Off Idle	56.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.46	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:4	36.81	2683	1.75	13.43	100	197	Off Idle	56.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.47	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:4	36.81	2684	1.75	13.45	100	197	Off Idle	56.4	0	2	132	944 Turbo	0.26	Rich	1	14.6	-9.47	14.81	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:4	36.81	2688	1.75	13.45	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.46	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:4	36.81	2690	1.74	13.43	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.46	14.86	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:4	36.81	2690	1.74	13.45	100	197	Off Idle	56.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.46	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:22:4	36.81	2688	1.74	13.45	100	197	Off Idle	56.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.46	14.9	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:4	36.81	2688	1.74	13.43	100	197	Off Idle	56	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.49	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:5	36.81	2693	1.74	13.44	100	197	Off Idle	55.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.44	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:5	36.81	2694	1.74	13.45	100	197	Off Idle	55.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.46	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:5	36.81	2694	1.75	13.45	100	197	Off Idle	55.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.46	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:5	36.81	2692	1.75	13.43	100	197	Off Idle	55.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9.42	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:5	36.81	2693	1.75	13.44	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.42	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:5	36.81	2693	1.75	13.44	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.45	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:6	36.81	2693	1.75	13.43	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.44	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:6	36.81	2694	1.75	13.43	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.44	15.08	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:6	36.81	2695	1.75	13.45	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.42	15.07	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:6	36.81	2691	1.75	13.45	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-9.42	15.06	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:6	36.81	2694	1.75	13.43	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.4	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:6	36.81	2684	1.75	13.42	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.39	15.02	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:6	36.81	2678	1.75	13.44	100	197	Off Idle	54.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-9.4	15	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:7	36.81	2676	1.75	13.42	100	197	Off Idle	54.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.43	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:7	36.81	2667	1.76	13.42	100	197	Off Idle	54.8	0	2	132	944 Turbo	0.28	Lean	1	14.7	-9.42	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:7	36.81	2668	1.76	13.44	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.42	14.93	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:7	36.81	2669	1.76	13.45	100	197	Off Idle	55	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.43	14.88	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:22:7	36.81	2670	1.76	13.44	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.41	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:22:7	36.81	2674	1.76	13.46	100	197	Off Idle	55.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.42	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:22:8	36.81	2678	1.76	13.46	100	197	Off Idle	55.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.44	14.86	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:22:8	36.81	2668	1.76	13.44	100	197	Off Idle	55.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.39	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:22:8	35.45	2683	1.76	13.43	100	197	Off Idle	55.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.4	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:8	35.45	2686	1.76	13.43	100	197	Off Idle	55.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.43	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:8	35.45	2686	1.76	13.44	100	197	Off Idle	55.8	0	2	132	944 Turbo	0.2	Rich	1	14.6	-9.42	14.84	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:8	35.45	2687	1.75	13.44	100	197	Off Idle	56	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.46	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:9	35.45	2686	1.75	13.43	100	197	Off Idle	56.1	0	2	132	944 Turbo	0.35	Rich	1	14.6	-9.52	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:9	36.81	2684	1.75	13.43	100	197	Off Idle	56.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.49	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:9	36.81	2682	1.75	13.44	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.48	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:9	36.81	2673	1.75	13.45	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.5	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:9	36.81	2671	1.75	13.43	100	197	Off Idle	56.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-9.47	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:9	36.81	2670	1.75	13.45	100	197	Off Idle	56.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.47	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:22:9	36.81	2642	1.75	13.45	100	197	Off Idle	56.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.47	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:0	35.45	2659	1.75	13.44	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.48	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:0	35.45	2659	1.75	13.44	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.48	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:0	35.45	2656	1.75	13.44	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.48	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:0	35.45	2655	1.75	13.44	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.48	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:0	35.45	2656	1.75	13.43	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.46	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:0	35.45	2657	1.75	13.44	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.46	15.13	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:1	35.45	2660	1.75	13.45	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.46	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:1	35.45	2639	1.74	13.45	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.47	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:1	35.45	2659	1.74	13.44	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.42	Rich	1	14.6	-9.48	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:1	35.45	2660	1.74	13.45	100	197	Off Idle	56.5	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.49	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:1	35.45	2657	1.74	13.45	100	197	Off Idle	56.6	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.46	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:1	35.45	2678	1.74	13.45	100	197	Off Idle	56.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.47	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:1	35.45	2669	1.74	13.43	100	197	Off Idle	56.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.46	14.91	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:2	35.45	2660	1.74	13.44	100	197	Off Idle	56.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.48	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:2	35.45	2658	1.74	13.44	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.49	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:2	35.45	2658	1.74	13.45	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.5	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:2	35.45	2658	1.74	13.43	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.48	14.79	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:2	35.45	2656	1.74	13.44	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.49	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:2	35.45	2656	1.74	13.43	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.47	14.78	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:3	35.45	2651	1.74	13.44	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.47	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:3	35.45	2652	1.74	13.45	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.5	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:3	35.45	2652	1.74	13.44	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.44	Lean	1	14.7	-9.49	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:3	35.45	2654	1.74	13.46	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.53	Rich	1	14.6	-9.48	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:3	35.45	2655	1.74	13.46	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.5	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:23:3	35.45	2648	1.74	13.46	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.5	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:4	35.45	2656	1.74	13.45	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.5	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:4	35.45	2657	1.74	13.44	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.5	15	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:4	35.45	2662	1.74	13.45	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9.48	15.03	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:4	35.45	2645	1.74	13.44	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.5	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:4	35.45	2644	1.74	13.43	100	197	Off Idle	56.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.49	15.04	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:4	35.45	2638	1.74	13.44	100	197	Off Idle	57	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.5	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:4	35.45	2636	1.74	13.44	100	197	Off Idle	57.2	0	2	132	944 Turbo	0.68	Lean	1	14.7	-9.5	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:5	35.45	2616	1.74	13.43	100	197	Off Idle	57.3	0	2	132	944 Turbo	0.65	Lean	1	14.6	-9.54	15.05	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:5	35.45	2636	1.74	13.43	100	197	Off Idle	57.4	0	2	132	944 Turbo	0.62	Lean	1	14.6	-9.54	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:5	35.45	2637	1.74	13.45	100	197	Off Idle	57.6	0	2	132	944 Turbo	0.57	Lean	1	14.6	-9.55	15.02	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:5	35.45	2638	1.73	13.44	100	197	Off Idle	57.7	0	2	132	944 Turbo	0.51	Lean	1	14.6	-9.54	15.01	1.02	3.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:5	35.45	2648	1.73	13.42	100	197	Off Idle	57.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.56	14.99	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:5	35.45	2634	1.73	13.44	100	197	Off Idle	57.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-9.54	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:6	35.45	2634	1.73	13.44	100	197	Off Idle	57.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.56	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:6	35.45	2637	1.73	13.42	100	197	Off Idle	57.9	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.58	14.97	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:6	35.45	2638	1.73	13.43	100	197	Off Idle	57.9	0	2	132	944 Turbo	0.21	Lean	1	14.6	-9.6	14.95	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:6	35.45	2640	1.73	13.43	100	197	Off Idle	58.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.6	14.89	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:6	35.45	2647	1.72	13.42	100	197	Off Idle	58.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.61	14.87	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:6	35.45	2642	1.72	13.44	100	197	Off Idle	58.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-9.61	14.85	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:6	35.45	2642	1.72	13.44	100	197	Off Idle	58.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.59	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:7	35.45	2664	1.72	13.43	100	197	Off Idle	58.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	14.82	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:7	35.45	2650	1.72	13.42	100	197	Off Idle	58.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.55	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:7	35.45	2655	1.72	13.43	100	197	Off Idle	58.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.54	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:7	35.45	2655	1.72	13.43	100	197	Off Idle	58	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.53	14.88	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:7	35.45	2637	1.72	13.42	100	197	Off Idle	57.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.55	14.9	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:7	35.45	2653	1.72	13.43	100	197	Off Idle	57.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.54	14.92	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:8	35.45	2653	1.72	13.44	100	197	Off Idle	57.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-9.53	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:23:8	35.45	2652	1.72	13.42	100	197	Off Idle	57.7	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.52	14.99	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:23:8	35.45	2667	1.72	13.42	100	197	Off Idle	57.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.5	15.03	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:23:8	35.45	2667	1.72	13.43	100	197	Off Idle	57.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.5	15.06	1.03	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:23:8	35.45	2644	1.72	13.44	100	197	Off Idle	57.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-9.51	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:8	35.45	2632	1.72	13.42	100	197	Off Idle	57.3	0	2	132	944 Turbo	0.72	Rich	1	14.7	-9.49	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:9	35.45	2628	1.72	13.44	100	197	Off Idle	57.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.49	15.1	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:9	35.45	2628	1.72	13.43	100	197	Off Idle	57.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.52	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:9	35.45	2622	1.72	13.41	100	197	Off Idle	57.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.51	15.1	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:9	35.45	2627	1.72	13.43	100	197	Off Idle	57.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-9.52	15.12	1.03	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:9	35.45	2627	1.72	13.43	100	197	Off Idle	57.7	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.56	15.12	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:9	35.45	2623	1.72	13.41	100	197	Off Idle	57.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.53	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:23:9	35.45	2622	1.72	13.43	100	197	Off Idle	57.7	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.54	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:0	35.45	2622	1.72	13.43	100	197	Off Idle	57.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.54	15.05	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:0	35.45	2612	1.72	13.45	100	197	Off Idle	57.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.52	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:0	35.45	2622	1.72	13.44	100	197	Off Idle	58	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.53	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:0	35.45	2626	1.72	13.45	100	197	Off Idle	58.1	0	2	132	944 Turbo	0.2	Lean	1	14.7	-9.55	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:0	35.45	2628	1.72	13.44	100	197	Off Idle	58.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.55	14.96	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:0	35.45	2632	1.72	13.43	100	197	Off Idle	58.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.53	14.94	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:1	35.45	2631	1.72	13.44	100	197	Off Idle	58.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.55	14.88	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:1	35.45	2630	1.72	13.44	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.56	14.83	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:1	35.45	2632	1.72	13.46	100	197	Off Idle	58.7	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.57	14.8	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:1	35.45	2633	1.72	13.44	100	197	Off Idle	58.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-9.59	14.79	1.01	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:1	35.45	2634	1.72	13.46	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.59	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:1	35.45	2634	1.72	13.46	100	197	Off Idle	58.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.62	14.83	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:1	35.45	2635	1.71	13.45	100	197	Off Idle	58.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.6	14.85	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:2	35.45	2636	1.71	13.43	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.42	Lean	1	14.6	-9.57	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:2	35.45	2635	1.71	13.45	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-9.59	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:2	35.45	2635	1.71	13.44	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.62	14.94	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:2	35.45	2632	1.71	13.44	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-9.59	14.98	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:2	35.45	2646	1.71	13.44	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.58	15.04	1.02	3.5	1.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:24:2	35.45	2622	1.71	13.45	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.58	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:3	35.45	2622	1.71	13.45	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.6	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:3	35.45	2617	1.71	13.45	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.58	15.09	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:3	35.45	2617	1.71	13.45	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.56	15.1	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:3	35.45	2607	1.71	13.46	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.58	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:3	35.45	2612	1.71	13.46	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.56	15.11	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:3	35.45	2606	1.71	13.45	100	197	Off Idle	58.7	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.53	15.09	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:4	35.45	2606	1.71	13.44	100	197	Off Idle	59	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.56	15.07	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:4	35.45	2606	1.71	13.44	100	197	Off Idle	59.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-9.56	15.05	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:4	35.45	2603	1.71	13.44	100	197	Off Idle	59.4	0	2	132	944 Turbo	0.41	Lean	1	14.6	-9.58	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:4	35.45	2604	1.71	13.44	100	197	Off Idle	59.7	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.59	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:4	35.45	2604	1.71	13.45	100	197	Off Idle	59.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.6	14.95	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:4	35.45	2599	1.71	13.44	100	197	Off Idle	60	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.62	14.91	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:4	35.45	2604	1.7	13.44	100	197	Off Idle	60.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.61	14.89	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:5	35.45	2611	1.7	13.45	100	197	Off Idle	60.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.61	14.84	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:5	35.45	2611	1.7	13.43	100	197	Off Idle	60.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.64	14.82	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:5	35.45	2614	1.7	13.44	100	197	Off Idle	60.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.62	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:5	35.45	2610	1.7	13.44	100	197	Off Idle	60.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.61	14.81	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:5	35.45	2610	1.7	13.44	100	197	Off Idle	60.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.61	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:5	35.45	2612	1.69	13.44	100	197	Off Idle	61.1	0	2	132	944 Turbo	0.18	Rich	1	14.6	-9.65	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:6	35.45	2612	1.69	13.44	100	197	Off Idle	61.1	0	2	132	944 Turbo	0.21	Rich	1	14.6	-9.63	14.8	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:6	35.45	2612	1.69	13.44	100	197	Off Idle	61	0	2	132	944 Turbo	0.3	Rich	1	14.6	-9.65	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:6	35.45	2612	1.69	13.45	100	197	Off Idle	60.8	0	2	132	944 Turbo	0.36	Rich	1	14.6	-9.68	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:6	35.45	2611	1.69	13.45	100	197	Off Idle	60.7	0	2	132	944 Turbo	0.43	Rich	1	14.7	-9.68	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:6	35.45	2610	1.69	13.43	100	197	Off Idle	60.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.65	14.9	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:6	35.45	2610	1.69	13.45	100	197	Off Idle	60.4	0	2	132	944 Turbo	0.56	Rich	1	14.6	-9.65	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:6	35.45	2609	1.69	13.44	100	197	Off Idle	60.4	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.66	14.94	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:7	35.45	2608	1.69	13.44	100	197	Off Idle	60.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.63	14.97	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:7	35.45	2606	1.69	13.43	100	197	Off Idle	60.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.63	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:7	35.45	2604	1.68	13.43	100	197	Off Idle	60.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.62	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:7	35.45	2605	1.68	13.43	100	197	Off Idle	60.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.65	15.08	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:7	35.45	2605	1.68	13.44	100	197	Off Idle	60.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.66	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:7	35.45	2601	1.68	13.43	100	197	Off Idle	60.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.63	15.12	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:8	35.45	2599	1.68	13.43	100	197	Off Idle	60.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.66	15.13	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:8	35.45	2599	1.68	13.43	100	197	Off Idle	60.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-9.68	15.11	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:8	35.45	2586	1.68	13.44	100	197	Off Idle	60.6	0	2	132	944 Turbo	0.57	Rich	1	14.6	-9.67	15.08	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:8	35.45	2584	1.68	13.42	100	197	Off Idle	60.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.67	15.06	1.03	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:8	35.45	2584	1.68	13.44	100	197	Off Idle	60.9	0	2	132	944 Turbo	0.45	Rich	1	14.7	-9.67	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:8	35.45	2582	1.68	13.44	100	197	Off Idle	61.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.66	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:9	35.45	2582	1.68	13.44	100	197	Off Idle	61.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-9.66	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:9	35.45	2583	1.68	13.45	100	197	Off Idle	61.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.66	14.9	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:9	35.45	2573	1.68	13.45	100	197	Off Idle	61.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.66	14.86	1.01	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:24:9	35.45	2583	1.68	13.45	100	197	Off Idle	61.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.68	14.84	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:9	35.45	2584	1.67	13.44	100	197	Off Idle	61.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.7	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:9	35.45	2590	1.67	13.44	100	197	Off Idle	61.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.7	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:24:9	35.45	2576	1.67	13.43	100	197	Off Idle	61.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.7	14.85	1.01	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:0	35.45	2574	1.67	13.43	100	197	Off Idle	61.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.7	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:0	35.45	2574	1.66	13.43	100	197	Off Idle	61.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.71	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:0	35.45	2576	1.66	13.43	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.25	Lean	1	14.7	-9.67	14.81	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:0	35.45	2568	1.66	13.42	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-9.68	14.82	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:0	35.45	2568	1.66	13.43	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.71	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:0	35.45	2578	1.66	13.43	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.73	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:1	35.45	2572	1.65	13.44	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-9.72	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:1	35.45	2585	1.65	13.42	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.56	Rich	1	14.7	-9.73	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:1	35.45	2582	1.65	13.43	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-9.75	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:1	35.45	2574	1.65	13.43	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.73	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:1	35.45	2575	1.65	13.44	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.72	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:1	35.45	2575	1.65	13.44	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.75	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:25:1	35.45	2574	1.65	13.44	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.74	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:2	35.45	2570	1.65	13.44	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.73	15.03	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:2	35.45	2570	1.65	13.44	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.73	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:2	35.45	2570	1.64	13.44	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.73	15.07	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:2	35.45	2572	1.64	13.45	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.73	15.05	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:2	35.45	2571	1.64	13.44	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.76	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:2	35.45	2572	1.64	13.42	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.76	15.01	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:3	35.45	2576	1.64	13.43	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.52	Rich	1	14.6	-9.78	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:3	35.45	2580	1.64	13.43	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.46	Rich	1	14.6	-9.79	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:3	35.45	2582	1.64	13.42	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-9.77	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:3	35.45	2583	1.64	13.42	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-9.74	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:3	35.45	2582	1.64	13.43	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.77	14.91	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:3	35.45	2582	1.64	13.44	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.77	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:4	35.45	2586	1.64	13.44	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.78	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:4	35.45	2581	1.64	13.44	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.76	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:4	35.45	2582	1.64	13.44	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.77	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:4	35.45	2582	1.64	13.45	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.76	14.85	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:4	35.45	2585	1.64	13.44	100	197	Off Idle	61.5	0	2	132	944 Turbo	0.18	Lean	1	14.7	-9.74	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:4	35.45	2585	1.64	13.45	100	197	Off Idle	61.4	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.73	14.83	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:4	35.45	2586	1.64	13.44	100	197	Off Idle	61.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-9.77	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:5	35.45	2587	1.64	13.45	100	197	Off Idle	61.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-9.75	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:5	35.45	2587	1.64	13.44	100	197	Off Idle	61.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.74	14.87	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:5	35.45	2587	1.64	13.45	100	197	Off Idle	61.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.78	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:5	35.45	2586	1.64	13.45	100	197	Off Idle	61.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.75	14.92	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:5	35.45	2581	1.64	13.45	100	197	Off Idle	61.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-9.75	14.95	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:5	35.45	2580	1.64	13.44	100	197	Off Idle	61.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-9.77	14.97	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:6	35.45	2577	1.64	13.44	100	197	Off Idle	61.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.75	14.99	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:6	35.45	2563	1.64	13.44	100	197	Off Idle	61.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.77	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:6	35.45	2571	1.65	13.42	100	197	Off Idle	61.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-9.78	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:6	35.45	2569	1.64	13.43	100	197	Off Idle	61.7	0	2	132	944 Turbo	0.73	Rich	1	14.7	-9.76	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:6	35.45	2563	1.64	13.43	100	197	Off Idle	61.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.75	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:6	35.45	2562	1.64	13.45	100	197	Off Idle	61.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-9.77	15.04	1.02	3.5	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:6	35.45	2572	1.64	13.44	100	197	Off Idle	62.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.77	15.05	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:7	35.45	2559	1.64	13.44	100	197	Off Idle	62.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.77	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:7	35.45	2556	1.64	13.43	100	197	Off Idle	62.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-9.79	15.06	1.03	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:7	35.45	2545	1.64	13.45	100	197	Off Idle	62.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.78	15.04	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:7	35.45	2545	1.64	13.43	100	197	Off Idle	62.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-9.79	15.02	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:7	35.45	2546	1.64	13.44	100	197	Off Idle	62.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-9.79	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:7	35.45	2543	1.63	13.44	100	197	Off Idle	62.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-9.77	15	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:8	35.45	2545	1.63	13.44	100	197	Off Idle	62.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-9.78	14.98	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:8	35.45	2545	1.63	13.46	100	197	Off Idle	62.6	0	2	132	944 Turbo	0.24	Rich	1	14.6	-9.79	14.96	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:8	35.45	2544	1.63	13.45	100	197	Off Idle	62.7	0	2	132	944 Turbo	0.19	Lean	1	14.6	-9.79	14.94	1.02	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:8	35.45	2543	1.63	13.45	100	197	Off Idle	62.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.78	14.89	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:8	35.45	2543	1.62	13.43	100	197	Off Idle	62.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.82	14.88	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:8	35.45	2544	1.62	13.45	100	197	Off Idle	62.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.81	14.86	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:9	35.45	2547	1.61	13.43	100	197	Off Idle	62.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.85	14.84	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:25:9	35.45	2547	1.61	13.44	100	197	Off Idle	62.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.87	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:25:9	35.45	2547	1.6	13.44	100	197	Off Idle	62.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.92	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:25:9	35.45	2551	1.59	13.45	100	197	Off Idle	62.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.94	14.83	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:25:9	35.45	2553	1.59	13.45	100	197	Off Idle	62.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.99	14.84	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:25:9	35.45	2553	1.58	13.46	100	197	Off Idle	62.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10.07	14.86	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:25:9	35.45	2552	1.56	13.46	100	197	Full Load	62.9	0	2	132	944 Turbo	0.17	Rich	1	14.6	-10.13	14.87	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:26:0	35.45	2553	1.54	13.44	100	197	Idle	63.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-10.23	14.9	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:26:0	35.45	2552	1.53	13.43	100	197	Idle	63.2	0	2	132	944 Turbo	0.3	Rich	1	14.6	-10.27	14.94	1.02	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:26:0	35.45	2551	1.51	13.42	100	197	Idle	63.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-10.32	14.98	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:29:26:0	35.45	2546	1.5	13.43	100	197	Idle	63.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-10.38	15.01	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:0	35.45	2546	1.49	13.42	100	197	Idle	63.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-10.39	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:0	29.99	2496	1.47	13.42	100	197	Idle	63.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-10.42	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:26:1	29.99	2470	1.46	13.44	100	197	Idle	63.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.48	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:1	24.54	2470	1.44	13.44	100	197	Idle	63.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-10.49	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:1	19.09	2455	1.43	13.44	100	197	Idle	63.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-10.5	15.08	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:1	19.09	2485	1.42	13.44	100	197	Idle	63.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.5	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:1	19.09	2482	1.4	13.42	100	197	Idle	63.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-10.5	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:1	19.09	2474	1.39	13.43	100	197	Idle	63.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-10.49	15.04	1.02	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:1	19.09	2474	1.38	13.43	100	197	Idle	64	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.51	15.05	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:2	19.09	2479	1.37	13.43	100	197	Idle	64	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.55	15.07	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:2	19.09	2479	1.36	13.44	100	197	Idle	64	0	2	132	944 Turbo	0.53	Rich	1	14.6	-10.54	15.06	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:2	19.09	2491	1.36	13.43	100	197	Idle	64	0	2	132	944 Turbo	0.46	Rich	1	14.6	-10.53	15.04	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:2	19.09	2508	1.35	13.44	100	197	Idle	64	0	2	132	944 Turbo	0.4	Rich	1	14.6	-10.54	15.02	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:2	19.09	2508	1.35	13.44	100	197	Idle	63.9	0	2	132	944 Turbo	0.29	Rich	1	14.6	-10.48	15.03	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:2	19.09	2520	1.35	13.44	100	197	Idle	63.9	0	2	132	944 Turbo	0.22	Rich	1	14.6	-10.47	15	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:3	19.09	2528	1.35	13.45	100	197	Idle	64	0	2	132	944 Turbo	0.15	Lean	1	14.6	-10.49	14.97	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:3	19.09	2531	1.35	13.45	100	197	Idle	64	0	2	132	944 Turbo	0.11	Lean	1	14.6	-10.48	14.96	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:3	19.09	2530	1.35	13.44	100	197	Idle	64	0	2	132	944 Turbo	0.09	Lean	1	14.6	-10.47	14.94	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:3	19.09	2523	1.35	13.44	100	197	Idle	63.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.43	14.85	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:3	19.09	2534	1.35	13.44	100	197	Idle	63.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.43	14.83	1.01	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:3	19.09	2534	1.35	13.45	100	197	Idle	63.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.39	14.8	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:4	19.09	2500	1.35	13.43	100	197	Idle	63.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.38	14.8	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:4	19.09	2487	1.35	13.44	100	197	Idle	63.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.36	14.78	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:4	19.09	2479	1.35	13.44	100	197	Idle	63.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.37	14.75	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:4	19.09	2476	1.34	13.44	100	197	Idle	64	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.38	14.74	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:4	19.09	2467	1.34	13.43	100	197	Idle	64.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.35	14.76	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:4	19.09	2464	1.34	13.44	100	197	Idle	64.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.34	14.74	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:4	19.09	2464	1.34	13.44	100	197	Idle	64.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.32	14.74	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:5	19.09	2464	1.34	13.43	100	197	Idle	64.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.33	14.73	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:5	19.09	2468	1.35	13.41	100	197	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	14.74	1	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:5	19.09	2470	1.35	13.39	100	197	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	14.84	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:5	19.09	2474	1.35	13.38	100	197	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	14.89	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:5	19.09	2479	1.35	13.35	100	197	Idle	64.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	15.14	1.03	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:5	19.09	2482	1.35	13.37	100	197	Idle	64.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	15.41	1.05	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:6	19.09	2482	1.35	13.38	100	197	Idle	64.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.3	15.78	1.08	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:6	19.09	2482	1.35	13.38	100	197	Idle	64.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	16.25	1.11	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:6	19.09	2482	1.34	13.39	100	197	Idle	64.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	16.78	1.14	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:6	19.09	2480	1.34	13.4	100	197	Idle	64.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.31	17.34	1.18	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:6	19.09	2474	1.34	13.4	100	197	Idle	65.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	17.89	1.22	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:6	19.09	2467	1.34	13.41	100	197	Idle	65.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	18.41	1.25	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:6	19.09	2464	1.34	13.4	100	197	Idle	65.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	18.88	1.29	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:7	19.09	2452	1.33	13.41	100	197	Idle	65.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	19.51	1.33	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:7	19.09	2445	1.33	13.39	100	197	Idle	66	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	19.83	1.35	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:7	19.09	2437	1.33	13.4	100	197	Idle	66.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.07	1.37	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:7	17.72	2437	1.33	13.4	100	197	Idle	66.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:7	17.72	2422	1.33	13.39	100	197	Idle	66.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:7	17.72	2428	1.32	13.39	100	197	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:8	17.72	2427	1.32	13.39	100	197	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:8	17.72	2424	1.32	13.38	100	197	Idle	67.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:8	17.72	2422	1.32	13.38	100	197	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:8	17.72	2420	1.31	13.39	100	197	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:8	17.72	2420	1.31	13.39	100	197	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:8	17.72	2410	1.31	13.4	100	197	Idle	67.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:9	17.72	2416	1.3	13.39	100	197	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.32	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:9	17.72	2415	1.3	13.4	100	197	Idle	67.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:9	17.72	2421	1.3	13.4	100	197	Idle	67.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:9	17.72	2409	1.3	13.4	100	197	Idle	67.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.33	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:9	17.72	2409	1.29	13.4	100	197	Idle	67.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:9	17.72	2402	1.29	13.4	100	197	Idle	68	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:26:9	17.72	2377	1.29	13.4	100	197	Idle	68.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:27:0	17.72	2392	1.28	13.38	100	197	Idle	68.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:0	17.72	2391	1.28	13.4	100	197	Idle	68.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:0	17.72	2386	1.28	13.39	100	197	Idle	68.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:0	17.72	2384	1.28	13.39	100	197	Idle	69.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:0	17.72	2384	1.27	13.39	100	197	Idle	69.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:0	17.72	2379	1.27	13.39	100	197	Idle	69.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:1	17.72	2375	1.26	13.4	100	197	Idle	69.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:1	17.72	2373	1.26	13.39	100	197	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:1	17.72	2372	1.26	13.39	100	197	Idle	69.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:1	17.72	2368	1.25	13.4	100	197	Idle	70	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:1	17.72	2365	1.25	13.4	100	197	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:1	17.72	2365	1.25	13.39	100	197	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:1	17.72	2359	1.24	13.39	100	197	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.2	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:2	17.72	2354	1.24	13.4	100	197	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.19	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:2	17.72	2349	1.23	13.4	100	197	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:2	17.72	2348	1.23	13.4	100	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:2	17.72	2340	1.23	13.39	100	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:2	17.72	2331	1.22	13.39	100	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:2	17.72	2331	1.22	13.4	100	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:3	17.72	2330	1.22	13.39	100	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:3	17.72	2323	1.21	13.39	100	197	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:3	17.72	2318	1.21	13.4	100	197	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:3	17.72	2318	1.21	13.39	100	197	Idle	71.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:3	17.72	2305	1.21	13.39	100	197	Idle	71.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:3	17.72	2310	1.21	13.39	100	197	Idle	71.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:4	17.72	2310	1.2	13.4	100	197	Idle	71.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.23	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:4	17.72	2304	1.2	13.4	100	197	Idle	72	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:4	17.72	2302	1.2	13.4	100	197	Idle	72.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.41	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:4	17.72	2296	1.19	13.4	100	197	Idle	72.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:4	17.72	2296	1.19	13.4	100	197	Idle	72.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:4	17.72	2288	1.19	13.4	100	197	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:4	17.72	2282	1.18	13.39	100	197	Idle	73.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:5	17.72	2282	1.18	13.39	100	197	Idle	73.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:5	17.72	2275	1.18	13.39	100	197	Idle	73.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:5	17.72	2269	1.18	13.39	100	197	Idle	73.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.2	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:5	17.72	2269	1.17	13.38	100	197	Idle	74	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:5	17.72	2263	1.17	13.39	100	197	Idle	74.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:5	17.72	2255	1.17	13.39	100	197	Idle	74.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:6	17.72	2250	1.16	13.38	100	197	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:6	17.72	2250	1.16	13.39	100	197	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:6	17.72	2242	1.16	13.4	100	197	Idle	74.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:6	17.72	2238	1.15	13.4	100	197	Idle	74.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:6	17.72	2236	1.15	13.39	100	197	Idle	75	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:6	17.72	2220	1.15	13.41	100	197	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:6	17.72	2223	1.14	13.4	100	197	Idle	75.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:7	17.72	2223	1.14	13.4	100	197	Idle	75.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:7	17.72	2218	1.14	13.4	100	197	Idle	75.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:7	17.72	2210	1.14	13.4	100	197	Idle	75.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:7	17.72	2205	1.13	13.39	100	197	Idle	76.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:7	17.72	2205	1.13	13.39	100	197	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:7	17.72	2197	1.13	13.39	100	197	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:8	17.72	2197	1.12	13.39	100	197	Idle	76.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:8	17.72	2185	1.12	13.38	100	197	Idle	77.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:8	17.72	2186	1.12	13.39	100	197	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:8	17.72	2182	1.11	13.39	100	197	Idle	77.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:8	17.72	2180	1.11	13.38	100	197	Idle	78.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:8	17.72	2171	1.1	13.38	100	197	Idle	78.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:9	17.72	2165	1.1	13.39	100	197	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.44	20.21	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:27:9	17.72	2165	1.09	13.39	100	197	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:9	17.72	2156	1.09	13.39	100	197	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:9	17.72	2149	1.09	13.39	100	197	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:9	17.72	2142	1.08	13.38	100	197	Idle	80.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:9	17.72	2142	1.08	13.37	100	197	Idle	80.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:27:9	17.72	2136	1.07	13.35	100	197	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:0	17.72	2129	1.06	13.35	100	197	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:0	17.72	2129	1.06	13.35	100	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:0	17.72	2122	1.05	13.37	100	197	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:0	17.72	2103	1.05	13.39	100	197	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:0	17.72	2102	1.05	13.4	100	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.21	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:0	17.72	2102	1.04	13.41	100	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:1	17.72	2098	1.04	13.41	100	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.22	1.38	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:1	17.72	2090	1.03	13.41	100	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:1	17.72	2085	1.03	13.4	100	197	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.6	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:1	17.72	2084	1.03	13.39	100	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:1	17.72	2079	1.03	13.37	100	197	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:1	17.72	2074	1.02	13.36	100	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:1	17.72	2072	1.02	13.36	100	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:2	17.72	2065	1.02	13.37	100	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.46	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:2	17.72	2060	1.02	13.38	100	197	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.47	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:2	17.72	2058	1.02	13.39	100	197	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:2	17.72	2045	1.02	13.41	100	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.56	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:2	17.72	2021	1.01	13.39	100	197	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:2	17.72	2021	1.01	13.38	100	197	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:3	17.72	2026	1.01	13.37	100	197	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.58	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:3	17.72	2017	1.01	13.35	100	197	Idle	81.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:3	17.72	2012	1.01	13.33	100	197	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:3	17.72	2009	1.01	13.35	100	197	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:3	17.72	2001	1.01	13.33	100	197	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:3	17.72	1995	1.01	13.34	100	197	Idle	81.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.49	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:4	17.72	1992	1.01	13.37	100	197	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.51	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:4	17.72	1983	1.01	13.39	100	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:4	17.72	1979	1	13.4	100	197	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.52	20.22	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:4	17.72	1976	1	13.41	100	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.22	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:4	17.72	1953	1	13.41	100	197	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.54	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:4	17.72	1965	1	13.41	100	197	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:4	17.72	1962	1	13.41	100	197	Idle	81	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.55	20.23	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:5	17.72	1957	1	13.41	100	197	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.53	20.24	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:5	17.72	1949	1	13.4	100	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.5	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:5	17.72	1946	1	13.4	100	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.48	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:5	17.72	1939	1	13.4	100	197	Idle	80.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.45	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:5	17.72	1934	1	13.39	100	197	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.43	20.25	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:5	17.72	1930	1	13.37	100	197	Idle	80.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.42	20.26	1.38	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:6	17.72	1920	1	13.36	100	197	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.4	20.25	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:6	17.72	1910	1	13.36	100	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.25	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:6	17.72	1899	1	13.35	100	197	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.26	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:6	17.72	1899	1	13.35	100	197	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.25	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:6	17.72	1889	1	13.35	100	197	Idle	81.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.35	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:6	17.72	1879	1	13.36	100	197	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.24	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:6	17.72	1879	1.01	13.36	100	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.37	20.23	1.38	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:7	17.72	1871	1.01	13.39	100	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.38	20.12	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:7	17.72	1865	1.01	13.38	100	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.13	1.37	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:7	17.72	1854	1.01	13.39	100	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.13	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:7	17.72	1851	1.01	13.38	100	197	Idle	81.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.39	20.13	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:7	17.72	1842	1.01	13.37	100	197	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.36	20.13	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:7	17.72	1837	1	13.35	100	197	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.34	20.13	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:8	17.72	1823	1	13.35	100	197	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.13	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:28:8	17.72	1810	1	13.35	100	197	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.29	20.14	1.37	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:8	17.72	1805	1	13.37	100	197	Idle	80.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.14	1.37	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:8	17.72	1800	1	13.37	100	197	Idle	80.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.28	20.25	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:8	17.72	1788	1.01	13.36	100	197	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:8	17.72	1788	1.01	13.38	100	197	Idle	80.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.27	20.24	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:9	17.72	1779	1.01	13.37	100	197	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.25	20.23	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:9	17.72	1768	1.01	13.36	100	197	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:9	17.72	1756	1.01	13.35	100	197	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.16	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:9	17.72	1747	1.01	13.37	100	197	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:9	17.72	1747	1.01	13.35	100	197	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.19	20.22	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:9	17.72	1734	1.01	13.35	100	197	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:28:9	17.72	1719	1.02	13.36	100	197	Idle	79.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:0	17.72	1719	1.02	13.38	100	197	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.17	20.2	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:0	17.72	1711	1.02	13.36	100	197	Idle	79.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	20.2	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:0	17.72	1686	1.02	13.36	100	197	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	20.2	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:0	17.72	1687	1.02	13.38	100	197	Idle	79.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	20.2	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:0	17.72	1682	1.02	13.37	100	197	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	20.21	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:0	17.72	1667	1.03	13.36	100	197	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.2	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:1	17.72	1656	1.03	13.37	100	197	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.2	1.38	3.9	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:1	17.72	1656	1.03	13.37	100	197	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.2	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:1	17.72	1641	1.03	13.36	100	197	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.19	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:1	17.72	1623	1.03	13.36	100	197	Idle	79.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.01	20.2	1.38	4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:1	17.72	1612	1.03	13.36	100	197	Idle	79.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.2	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:1	17.72	1588	1.03	13.37	100	197	Idle	79.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.21	1.38	4.1	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:1	17.72	1550	1.03	13.37	100	197	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:2	17.72	1550	1.03	13.37	100	197	Idle	79	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.81	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:2	17.72	1514	1.03	13.37	100	197	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:2	17.72	1500	1.03	13.38	100	197	Idle	78	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.75	20.21	1.38	4.2	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:2	17.72	1475	1.04	13.37	100	197	Idle	77.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.69	20.21	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:2	17.72	1475	1.04	13.39	100	197	Idle	77	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.22	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:2	17.72	1447	1.04	13.37	100	197	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	20.23	1.38	4.4	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:3	17.72	1421	1.05	13.37	100	197	Idle	75.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.5	20.23	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:3	19.09	1408	1.05	13.36	100	197	Idle	74.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	20.23	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:3	19.09	1380	1.06	13.38	100	197	Idle	73.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.23	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:3	19.09	1367	1.07	13.38	100	197	Idle	73.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.26	20.23	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:3	19.09	1353	1.07	13.38	100	197	Idle	72.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.16	20.22	1.38	4.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:3	19.09	1315	1.08	13.38	100	197	Idle	72.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	20.22	1.38	4.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:4	19.09	1291	1.09	13.39	100	197	Idle	71.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.97	20.23	1.38	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:29:4	16.36	1271	1.09	13.39	100	197	Idle	71.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.83	20.22	1.38	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:29:4	16.36	1271	1.1	13.39	100	197	Idle	70.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.74	20.22	1.38	4.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:29:4	16.36	1243	1.11	13.39	100	197	Idle	70.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.66	20.22	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:29:4	16.36	1222	1.11	13.39	100	197	Idle	70.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.5	20.21	1.38	4.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:29:4	16.36	1192	1.12	13.38	100	197	Idle	70.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.41	20.21	1.38	4.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:29:4	16.36	1192	1.13	13.38	100	197	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.31	20.21	1.38	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:5	16.36	1166	1.14	13.38	100	197	Idle	70.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.24	20.2	1.38	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:5	16.36	1166	1.14	13.37	100	197	Idle	70.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.13	20.2	1.38	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:29:5	16.36	1171	1.15	13.37	100	197	Idle	70.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.06	20.2	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:29:5	16.36	1179	1.16	13.38	100	197	Idle	70.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.95	20.2	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:29:5	16.36	1182	1.16	13.37	100	197	Idle	71.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.88	20.2	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:29:5	16.36	1186	1.16	13.38	100	197	Idle	71.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.82	20.2	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:29:6	16.36	1190	1.16	13.38	100	197	Idle	72.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.82	20.2	1.38	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:29:6	14.99	1189	1.16	13.38	100	197	Idle	74.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.8	20.22	1.38	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:29:6	14.99	1209	1.16	13.37	100	197	Idle	75.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.79	20.21	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:29:6	14.99	1209	1.16	13.37	100	197	Idle	76.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.83	20.21	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:29:6	14.99	1213	1.15	13.37	100	197	Idle	77.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.85	20.21	1.38	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:29:6	14.99	1217	1.14	13.37	100	197	Idle	78.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.88	20.22	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:29:6	14.99	1217	1.13	13.37	100	197	Idle	79.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.92	20.22	1.38	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:29:7	14.99	1222	1.12	13.38	100	197	Idle	80.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.92	20.22	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:29:7	14.99	1227	1.11	13.37	100	197	Idle	81.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.02	20.22	1.38	4.4	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:29:7	14.99	1227	1.1	13.38	100	197	Idle	83	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.07	20.22	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:29:29:7	14.99	1230	1.09	13.37	100	197	Idle	83.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.11	20.21	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:29:29:7	14.99	1222	1.08	13.36	100	197	Idle	84.9	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.2	20.21	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:7	14.99	1222	1.06	13.38	100	197	Idle	85.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.25	20.22	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:8	13.63	1225	1.05	13.37	100	197	Idle	86.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.27	20.23	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:8	13.63	1228	1.04	13.37	100	197	Idle	87.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.33	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:8	13.63	1227	1.03	13.38	100	197	Idle	87.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-8.37	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:8	13.63	1214	1.02	13.37	100	197	Idle	88	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.39	20.23	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:8	13.63	1200	1	13.37	100	197	Idle	88.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.41	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:8	13.63	1187	0.99	13.37	100	197	Idle	88.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.44	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:9	14.99	1178	0.98	13.37	100	197	Idle	88.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.47	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:9	14.99	1178	0.97	13.37	100	197	Idle	88.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.47	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:9	14.99	1165	0.96	13.37	100	197	Idle	89.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.53	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:9	14.99	1164	0.95	13.38	100	197	Idle	89.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.55	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:9	14.99	1164	0.95	13.37	100	197	Idle	89.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.56	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:9	14.99	1160	0.94	13.37	100	197	Idle	90.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.57	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:29:9	14.99	1160	0.94	13.36	100	197	Idle	90.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.57	20.21	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:0	13.63	1150	0.93	13.36	100	197	Idle	90.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.57	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:0	13.63	1138	0.93	13.37	100	197	Idle	91.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.58	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:0	13.63	1135	0.92	13.37	100	197	Idle	91.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.59	20.21	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:0	13.63	1115	0.92	13.38	100	197	Idle	91.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.58	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:0	13.63	1115	0.91	13.38	100	197	Idle	92	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.58	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:0	13.63	1102	0.91	13.38	100	197	Idle	92.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.57	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:1	13.63	1090	0.9	13.38	100	197	Idle	92.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.57	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:1	13.63	1090	0.9	13.38	100	197	Idle	92.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	20.23	1.38	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:1	13.63	1080	0.89	13.39	100	197	Idle	93	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.57	20.23	1.38	4.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:30:1	13.63	1069	0.89	13.38	100	197	Idle	93	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.57	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:1	13.63	1069	0.88	13.37	100	197	Idle	93.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.6	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:1	13.63	1055	0.88	13.39	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	20.19	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:1	13.63	1055	0.87	13.37	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.61	20.12	1.37	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:2	13.63	1041	0.87	13.39	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.6	20	1.36	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:2	12.27	1041	0.87	13.37	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.55	19.84	1.35	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:2	12.27	1040	0.87	13.39	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.54	19.62	1.34	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:2	12.27	1040	0.86	13.38	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.49	19.37	1.32	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:2	12.27	1040	0.86	13.37	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.5	19.08	1.3	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:2	12.27	1024	0.86	13.4	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.45	18.77	1.28	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:3	12.27	1006	0.86	13.38	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.46	18.27	1.24	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:3	12.27	1006	0.85	13.39	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.44	17.93	1.22	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:3	12.27	1002	0.85	13.37	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.43	17.61	1.2	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:3	12.27	997	0.85	13.39	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.41	17.33	1.18	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:3	12.27	994	0.85	13.37	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.4	17.21	1.17	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:3	12.27	994	0.85	13.39	100	197	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.38	16.99	1.16	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:4	12.27	985	0.85	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.38	16.83	1.15	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:4	12.27	985	0.85	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.32	16.69	1.14	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:4	12.27	980	0.85	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.31	16.59	1.13	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:4	12.27	976	0.84	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.29	16.51	1.12	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:4	10.9	962	0.84	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.27	16.46	1.12	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:4	10.9	962	0.84	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.23	16.42	1.12	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:4	10.9	977	0.84	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.21	16.4	1.12	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:5	10.9	975	0.84	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.25	16.39	1.12	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:5	10.9	973	0.84	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.24	16.38	1.12	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:5	10.9	972	0.84	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.27	16.38	1.12	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:5	10.9	972	0.84	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.19	16.38	1.12	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:5	10.9	972	0.83	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.21	16.37	1.12	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:5	10.9	972	0.83	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.17	16.36	1.11	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:6	10.9	972	0.83	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.15	16.36	1.11	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:6	10.9	961	0.83	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.13	16.34	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:30:6	10.9	961	0.83	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.16	16.32	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:6	10.9	961	0.83	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.1	16.3	1.11	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:6	10.9	961	0.83	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.1	16.29	1.11	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:6	10.9	947	0.83	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.05	16.25	1.11	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:6	10.9	947	0.83	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.06	16.21	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:7	9.54	944	0.83	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.01	16.18	1.1	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:7	9.54	944	0.83	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.05	16.17	1.1	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:30:7	9.54	942	0.83	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.05	16.14	1.1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:7	9.54	939	0.83	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.07	16.1	1.1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:7	9.54	941	0.82	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.04	16.07	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:7	9.54	934	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.06	16.04	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:8	9.54	934	0.82	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.06	16.02	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:8	9.54	932	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8	15.97	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:8	9.54	929	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.96	15.95	1.09	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:8	9.54	927	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8	15.92	1.08	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:8	9.54	927	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.94	15.91	1.08	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:8	9.54	930	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.98	15.88	1.08	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:9	8.18	934	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.95	15.86	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:9	8.18	934	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.97	15.85	1.08	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:9	8.18	923	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.92	15.84	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:9	8.18	922	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.95	15.84	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:9	8.18	922	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.9	15.84	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:9	8.18	922	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.9	15.82	1.08	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:30:9	8.18	933	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.89	15.82	1.08	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:0	8.18	933	0.82	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.9	15.8	1.08	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:0	9.54	925	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.85	15.8	1.08	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:0	9.54	925	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.88	15.79	1.08	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:0	9.54	924	0.82	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.84	15.77	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:0	9.54	924	0.82	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.85	15.75	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:0	9.54	926	0.82	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.82	15.73	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:1	9.54	929	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.8	15.69	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:1	9.54	930	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.84	15.65	1.07	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:1	9.54	930	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.83	15.61	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:1	8.18	917	0.81	13.33	100	197	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.85	15.58	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:1	8.18	917	0.81	13.34	100	197	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.84	15.54	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:1	8.18	923	0.81	13.31	100	197	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.5	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:1	8.18	923	0.81	13.32	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.86	15.47	1.05	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:2	8.18	903	0.81	13.34	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.86	15.43	1.05	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:2	8.18	903	0.81	13.33	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.39	1.05	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:2	8.18	903	0.81	13.33	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.36	1.05	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:2	8.18	913	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.33	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:2	9.54	889	0.81	13.34	100	197	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.29	1.04	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:2	9.54	889	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.27	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:3	9.54	897	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:3	9.54	905	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.77	15.2	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:3	9.54	903	0.81	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:3	6.81	903	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:3	6.81	903	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.16	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:3	6.81	915	0.81	13.34	100	197	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.75	15.13	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:4	6.81	910	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.77	15.12	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:4	8.18	910	0.81	13.33	100	197	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.71	15.11	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:4	8.18	906	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.73	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:31:4	8.18	903	0.81	13.34	100	197	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.69	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:4	8.18	903	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.72	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:4	8.18	910	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.7	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:4	8.18	910	0.81	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.76	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:5	8.18	894	0.81	13.33	100	197	Idle	93.3	0	2	132	944 Turbo	0.22	Rich	1	14.6	-7.71	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:5	8.18	894	0.8	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.73	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:31:5	8.18	897	0.8	13.33	100	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.72	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:5	8.18	897	0.8	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:5	8.18	896	0.8	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:5	8.18	896	0.8	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:6	9.54	899	0.8	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:6	9.54	899	0.8	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:6	9.54	894	0.8	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.76	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:6	9.54	890	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:6	9.54	890	0.8	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:6	6.81	896	0.8	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:6	6.81	921	0.8	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:7	6.81	921	0.8	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:7	6.81	921	0.8	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:7	8.18	913	0.8	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:7	8.18	905	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:7	8.18	905	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:7	8.18	905	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:8	8.18	912	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:8	8.18	912	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:8	8.18	906	0.8	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:8	8.18	906	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:8	6.81	902	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:8	6.81	902	0.8	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:9	6.81	921	0.8	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:9	6.81	921	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:9	6.81	890	0.8	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:9	6.81	890	0.8	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:9	6.81	900	0.8	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:9	6.81	909	0.8	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.75	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:31:9	8.18	907	0.8	13.33	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.79	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:0	8.18	907	0.8	13.34	100	197	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:0	8.18	908	0.8	13.34	100	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:0	8.18	909	0.8	13.35	100	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:0	8.18	909	0.8	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:0	8.18	914	0.8	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:0	8.18	901	0.8	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.72	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:1	8.18	901	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.65	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:1	8.18	906	0.8	13.36	100	197	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:1	8.18	912	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	15.17	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:1	8.18	912	0.8	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.73	15.19	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:1	8.18	909	0.81	13.37	100	197	Idle	93.3	0	2	132	944 Turbo	0.2	Rich	1	14.6	-7.71	15.22	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:1	8.18	900	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.25	Rich	1	14.6	-7.77	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:1	6.81	900	0.81	13.38	100	197	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.72	15.23	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:2	6.81	900	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.74	15.24	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:2	6.81	903	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.72	15.24	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:2	6.81	903	0.81	13.41	100	197	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.72	15.24	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:2	8.18	910	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.68	15.24	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:2	8.18	910	0.81	13.4	100	197	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.74	15.22	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:2	8.18	918	0.81	13.39	100	197	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.7	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:3	8.18	918	0.81	13.39	100	197	Full Load	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.73	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:3	8.18	902	0.81	13.37	100	197	Off Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	15.19	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:3	8.18	902	0.82	13.39	100	197	Off Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.68	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:3	8.18	912	0.83	13.37	100	197	Off Idle	92.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.61	15.15	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:3	8.18	912	0.84	13.38	100	197	Off Idle	92.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.53	15.14	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:3	6.81	907	0.86	13.39	100	197	Off Idle	91.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.44	15.13	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:4	6.81	907	0.89	13.38	100	197	Off Idle	91	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.33	15.13	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:4	6.81	907	0.91	13.38	100	197	Off Idle	90.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.2	15.11	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:4	6.81	913	0.95	13.42	100	197	Off Idle	89.9	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.99	15.11	1.03	4.7	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:32:4	6.81	911	1	13.41	100	197	Off Idle	89.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.68	15.09	1.03	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:4	6.81	911	1.04	13.42	100	197	Off Idle	88.8	0	2	132	944 Turbo	0.73	Rich	1	14.7	-6.45	15.09	1.03	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:4	6.81	914	1.08	13.42	100	197	Off Idle	88.2	0	2	132	944 Turbo	0.74	Rich	1	14.7	-6.2	15.08	1.03	4.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:4	6.81	916	1.12	13.44	100	197	Off Idle	87.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.92	15.08	1.03	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:32:5	6.81	923	1.15	13.44	100	197	Off Idle	87.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.71	15.06	1.03	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:32:5	9.54	923	1.17	13.42	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.56	15.06	1.03	4.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:32:5	9.54	923	1.21	13.44	100	197	Off Idle	86	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.39	15.05	1.03	4.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:32:5	9.54	919	1.28	13.42	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	-4.98	15.03	1.02	4.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:5	9.54	992	1.32	13.41	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.81	15.01	1.02	4.9	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:5	20.45	992	1.36	13.42	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-4.64	15.01	1.02	4.8	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:6	20.45	984	1.4	13.43	100	197	Off Idle	85	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.53	15	1.02	4.7	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:6	20.45	984	1.44	13.46	100	197	Off Idle	85	0	2	132	944 Turbo	0.48	Rich	1	14.6	-4.35	14.99	1.02	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:6	20.45	984	1.5	13.42	100	197	Off Idle	85	0	2	132	944 Turbo	0.38	Lean	1	14.6	-4.18	15	1.02	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:6	20.45	1014	1.53	13.45	100	197	Off Idle	85.1	0	2	132	944 Turbo	0.32	Lean	1	14.6	-4.05	15.02	1.02	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:6	20.45	1074	1.56	13.42	100	197	Off Idle	85.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-3.92	15.01	1.02	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:6	20.45	1103	1.59	13.44	100	197	Off Idle	85.1	0	2	132	944 Turbo	0.21	Lean	1	14.7	-3.79	15.02	1.02	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:6	20.45	1103	1.61	13.42	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-3.63	15.02	1.02	4.3	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:7	20.45	1140	1.62	13.44	100	197	Off Idle	85.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.54	15.01	1.02	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:7	20.45	1140	1.64	13.42	100	197	Off Idle	85.4	0	2	132	944 Turbo	0.33	Lean	1	14.7	-3.42	14.99	1.02	4.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:7	20.45	1166	1.65	13.4	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.4	Lean	1	14.7	-3.3	14.97	1.02	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:7	20.45	1200	1.66	13.4	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.47	Lean	1	14.7	-3.23	14.96	1.02	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:7	20.45	1200	1.68	13.39	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.55	Lean	1	14.7	-3.13	14.92	1.02	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:7	20.45	1218	1.7	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.62	Rich	1	14.7	-3	14.87	1.01	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:8	20.45	1271	1.72	13.4	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-2.88	14.86	1.01	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:8	20.45	1271	1.76	13.42	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-2.66	14.87	1.01	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:8	21.81	1285	1.78	13.41	100	197	Off Idle	86	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.57	14.87	1.01	4.2	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:8	21.81	1319	1.81	13.4	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.48	14.93	1.02	4.1	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:32:8	21.81	1346	1.83	13.39	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.39	14.96	1.02	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:32:8	21.81	1352	1.85	13.37	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.36	14.95	1.02	4.2	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:32:9	21.81	1382	1.87	13.35	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.36	14.9	1.02	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:9	23.18	1382	1.89	13.37	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.33	14.77	1.01	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:9	23.18	1393	1.9	13.39	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.36	14.67	1	4.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:32:9	23.18	1388	1.91	13.39	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.27	14.54	0.99	4.2	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:9	23.18	1398	1.93	13.38	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.32	14.28	0.97	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:9	23.18	1383	1.94	13.38	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.33	14.07	0.96	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:32:9	23.18	1383	1.96	13.37	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.35	13.84	0.94	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:33:0	23.18	1373	1.97	13.36	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.35	13.69	0.93	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:33:0	23.18	1355	1.98	13.36	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.34	13.35	0.91	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:33:0	23.18	1350	1.98	13.35	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.32	13.18	0.9	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:33:0	23.18	1350	1.98	13.36	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.23	13.05	0.89	4.3	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:33:0	23.18	1339	1.98	13.35	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.21	12.96	0.88	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:33:0	23.18	1339	1.98	13.36	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.2	12.92	0.88	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:33:1	23.18	1327	1.98	13.37	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.17	12.85	0.88	4.4	4.3	ON	28 Pin	OFF	Removed	Disabled
03:29:33:1	23.18	1312	1.98	13.35	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.13	12.81	0.87	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:1	24.54	1303	1.97	13.38	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.15	12.8	0.87	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:1	24.54	1270	1.97	13.4	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.1	12.82	0.87	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:1	24.54	1270	1.97	13.38	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.06	12.84	0.87	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:1	24.54	1265	1.97	13.41	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.05	12.86	0.88	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:1	24.54	1265	1.97	13.42	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.06	12.89	0.88	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:2	24.54	1260	1.97	13.41	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.99	12.91	0.88	4.5	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:2	24.54	1234	1.96	13.41	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.01	12.92	0.88	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:2	24.54	1215	1.96	13.41	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.96	12.94	0.88	4.6	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:2	24.54	1209	1.96	13.39	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.93	12.96	0.88	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:33:2	24.54	1190	1.95	13.39	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.88	13	0.89	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:33:2	24.54	1177	1.94	13.39	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.81	13.03	0.89	4.8	4.5	ON	28 Pin	OFF	Removed	Disabled
03:29:33:3	24.54	1130	1.94	13.37	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.8	13.08	0.89	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:3	24.54	1130	1.93	13.38	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.71	13.11	0.89	4.8	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:3	23.18	1112	1.93	13.38	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.84	Rich	1	14.7	-1.73	13.15	0.9	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:33:3	23.18	1112	1.92	13.39	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-1.65	13.22	0.9	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:3	23.18	1074	1.91	13.38	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.58	13.26	0.9	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:3	23.18	1074	1.9	13.41	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.85	Rich	1	14.7	-1.55	13.27	0.9	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:4	23.18	1056	1.89	13.39	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.5	13.31	0.91	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:4	23.18	1042	1.88	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-1.52	13.32	0.91	4.9	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:4	23.18	1029	1.87	13.39	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.43	13.31	0.91	4.9	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:33:4	23.18	1031	1.87	13.42	100	197	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.43	13.32	0.91	4.8	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:33:4	23.18	1031	1.85	13.42	100	197	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.7	-1.39	13.3	0.91	4.8	4.7	ON	28 Pin	OFF	Removed	Disabled
03:29:33:4	23.18	1047	1.84	13.41	100	197	Off Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-1.42	13.27	0.9	4.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:4	23.18	1073	1.84	13.44	100	197	Off Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.6	-1.37	13.24	0.9	4.7	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:5	21.81	1073	1.83	13.42	100	197	Off Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.41	13.2	0.9	4.6	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:5	21.81	1093	1.82	13.44	100	197	Off Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.7	-1.45	13.17	0.9	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:29:33:5	21.81	1113	1.82	13.41	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.44	13.13	0.89	4.4	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:5	21.81	1132	1.81	13.4	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.5	13.09	0.89	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:5	21.81	1152	1.81	13.4	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.54	13.03	0.89	4.3	4.4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:5	21.81	1205	1.8	13.39	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.88	Rich	1	14.7	-1.57	12.98	0.88	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:33:6	20.45	1205	1.8	13.38	100	197	Off Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.62	12.94	0.88	4.4	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:33:6	20.45	1237	1.8	13.39	100	197	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.71	12.9	0.88	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:33:6	20.45	1267	1.81	13.39	100	197	Off Idle	86	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.72	12.85	0.88	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:6	21.81	1310	1.81	13.39	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.75	12.79	0.87	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:6	21.81	1310	1.81	13.41	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.79	12.74	0.87	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:6	21.81	1304	1.82	13.39	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.77	12.68	0.86	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:6	21.81	1311	1.83	13.39	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.8	12.63	0.86	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:7	21.81	1311	1.83	13.38	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.88	12.57	0.86	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:7	21.81	1327	1.84	13.38	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.85	12.5	0.85	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:7	23.18	1317	1.85	13.38	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.89	12.39	0.85	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:7	23.18	1318	1.86	13.36	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.96	12.33	0.84	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:33:7	23.18	1318	1.87	13.38	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.89	Rich	1	14.6	-1.96	12.26	0.84	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:33:7	23.18	1330	1.88	13.36	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.97	12.23	0.83	4.3	4.2	ON	28 Pin	OFF	Removed	Disabled
03:29:33:8	23.18	1325	1.89	13.37	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.89	Rich	1	14.7	-1.97	12.16	0.83	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:8	23.18	1333	1.9	13.38	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2	12.09	0.82	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:8	23.18	1333	1.91	13.4	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.6	-1.97	12.08	0.82	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:8	23.18	1344	1.92	13.4	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2	12.02	0.82	4.4	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:8	23.18	1360	1.93	13.39	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.01	12.01	0.82	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:8	23.18	1360	1.93	13.41	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.88	Rich	1	14.7	-2.02	12.01	0.82	4.3	4.1	ON	28 Pin	OFF	Removed	Disabled
03:29:33:9	23.18	1378	1.94	13.39	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.03	12.03	0.82	4.3	4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:9	23.18	1378	1.94	13.4	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.03	12.05	0.82	4.2	4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:9	23.18	1398	1.95	13.4	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.01	12.08	0.82	4.2	4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:9	23.18	1422	1.95	13.4	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.6	-2.08	12.18	0.83	4.1	4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:9	23.18	1456	1.96	13.39	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.87	Rich	1	14.7	-2.09	12.2	0.83	4.1	4	ON	28 Pin	OFF	Removed	Disabled
03:29:33:9	23.18	1480	1.96	13.39	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.15	12.33	0.84	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:33:9	24.54	1480	1.97	13.38	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.2	12.4	0.84	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:34:0	24.54	1504	1.97	13.39	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.6	-2.25	12.55	0.85	4.1	3.9	ON	28 Pin	OFF	Removed	Disabled
03:29:34:0	24.54	1521	1.97	13.39	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.23	12.6	0.86	4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:34:0	25.9	1529	1.98	13.4	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.26	12.71	0.87	4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:34:0	25.9	1542	1.98	13.41	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.31	12.78	0.87	4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:34:0	25.9	1553	1.99	13.41	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.37	12.85	0.88	4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:34:0	25.9	1560	1.99	13.41	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.38	12.92	0.88	4.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:29:34:1	25.9	1560	2	13.41	100	197	Off Idle	86.8	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.41	12.98	0.88	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:34:1	25.9	1568	2.01	13.41	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.45	13.03	0.89	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:34:1	25.9	1572	2.01	13.41	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.85	Rich	1	14.7	-2.45	13.06	0.89	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:34:1	25.9	1576	2.02	13.41	100	197	Off Idle	86.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.49	13.13	0.89	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:34:1	25.9	1577	2.02	13.41	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.53	13.16	0.9	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:34:1	25.9	1582	2.03	13.42	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.7	-2.53	13.21	0.9	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:34:1	25.9	1601	2.03	13.42	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.54	13.26	0.9	4	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:34:2	25.9	1601	2.04	13.42	100	197	Off Idle	86.6	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.54	13.3	0.91	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:34:2	25.9	1593	2.04	13.42	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.54	13.34	0.91	4.1	3.7	ON	28 Pin	OFF	Removed	Disabled
03:29:34:2	25.9	1601	2.05	13.42	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.83	Rich	1	14.7	-2.54	13.39	0.91	4.1	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:34:2	27.27	1608	2.05	13.41	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.57	13.44	0.92	4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:34:2	27.27	1622	2.06	13.42	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.82	Rich	1	14.7	-2.6	13.49	0.92	4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:34:2	27.27	1649	2.06	13.41	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.6	-2.66	13.54	0.92	3.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:34:3	27.27	1666	2.06	13.41	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.68	13.63	0.93	3.8	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:34:3	27.27	1682	2.07	13.42	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.81	Rich	1	14.7	-2.71	13.69	0.93	3.8	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:34:3	27.27	1704	2.07	13.41	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-2.73	13.74	0.94	3.8	3.6	ON	28 Pin	OFF	Removed	Disabled
03:29:34:3	27.27	1704	2.08	13.4	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.8	Rich	1	14.7	-2.79	13.8	0.94	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:3	27.27	1718	2.08	13.39	100	197	Off Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.82	13.89	0.95	3.8	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:3	27.27	1743	2.08	13.38	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.79	Rich	1	14.7	-2.86	13.96	0.95	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:4	27.27	1743	2.09	13.38	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-2.88	13.99	0.95	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:4	27.27	1748	2.09	13.37	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-2.97	14.05	0.96	3.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:4	27.27	1754	2.1	13.37	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.78	Rich	1	14.7	-3	14.14	0.96	3.9	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:4	27.27	1775	2.1	13.36	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-3.02	14.2	0.97	3.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:4	28.63	1766	2.11	13.36	100	197	Off Idle	86.4	0	2	132	944 Turbo	0.77	Rich	1	14.7	-3.05	14.24	0.97	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:4	28.63	1766	2.11	13.38	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-3.07	14.29	0.97	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:4	28.63	1774	2.11	13.37	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-3.1	14.35	0.98	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:5	28.63	1779	2.12	13.36	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.75	Rich	1	14.7	-3.08	14.4	0.98	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:5	28.63	1779	2.12	13.38	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.73	Rich	1	14.7	-3.15	14.45	0.98	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:5	28.63	1784	2.13	13.38	100	197	Off Idle	86.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-3.13	14.47	0.99	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:5	28.63	1800	2.13	13.39	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.68	Rich	1	14.7	-3.19	14.53	0.99	3.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:5	28.63	1807	2.14	13.39	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-3.2	14.56	0.99	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:5	28.63	1807	2.14	13.4	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-3.2	14.59	0.99	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:6	28.63	1820	2.14	13.38	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.52	Rich	1	14.7	-3.18	14.62	1	3.7	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:6	28.63	1839	2.15	13.36	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-3.2	14.66	1	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:6	28.63	1839	2.15	13.36	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.39	Rich	1	14.6	-3.23	14.71	1	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:6	28.63	1851	2.15	13.37	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.33	Lean	1	14.7	-3.29	14.72	1	3.7	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:6	28.63	1861	2.16	13.4	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.27	Lean	1	14.7	-3.36	14.75	1	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:6	28.63	1870	2.16	13.38	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-3.4	14.78	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:6	28.63	1904	2.16	13.39	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.14	Lean	1	14.7	-3.4	14.83	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:7	28.63	1918	2.16	13.38	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-3.4	14.89	1.01	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:7	28.63	1918	2.17	13.37	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.1	Lean	1	14.7	-3.43	14.95	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:7	28.63	1928	2.17	13.37	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.49	15.03	1.02	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:7	28.63	1937	2.17	13.37	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.51	15.08	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:7	28.63	1937	2.17	13.36	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.49	15.12	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:7	28.63	1946	2.17	13.36	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.51	15.16	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:8	28.63	1949	2.18	13.36	100	197	Off Idle	86	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.58	15.19	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:8	28.63	1950	2.18	13.38	100	197	Off Idle	86	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.56	15.23	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:8	28.63	1953	2.18	13.4	100	197	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.66	15.24	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:8	29.99	1963	2.18	13.42	100	197	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.71	15.23	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:8	29.99	1963	2.19	13.43	100	197	Off Idle	86	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.72	15.23	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:8	29.99	1967	2.19	13.44	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.7	15.21	1.04	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:9	29.99	1973	2.19	13.44	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.68	15.2	1.04	3.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:9	29.99	1973	2.19	13.43	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.7	15.18	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:9	29.99	1989	2.2	13.42	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.7	15.16	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:34:9	29.99	1987	2.2	13.43	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.73	15.15	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:9	29.99	1987	2.2	13.43	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.73	15.15	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:9	29.99	1998	2.2	13.43	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.76	15.14	1.03	3.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:29:34:9	29.99	2011	2.2	13.44	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.81	15.12	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:35:0	29.99	2011	2.2	13.44	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-3.85	15.1	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:35:0	29.99	2031	2.2	13.44	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.83	15.11	1.03	3.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:35:0	29.99	2050	2.21	13.44	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.08	Lean	1	14.7	-3.87	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:0	29.99	2065	2.21	13.43	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.89	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:0	29.99	2065	2.21	13.4	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.88	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:0	29.99	2082	2.21	13.39	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.91	15.12	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:1	29.99	2111	2.21	13.38	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.7	-3.91	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:1	29.99	2111	2.21	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.89	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:1	29.99	2105	2.21	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-3.91	15.12	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:1	29.99	2112	2.22	13.41	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.95	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:35:1	31.36	2122	2.22	13.41	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.98	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:1	31.36	2119	2.22	13.38	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.04	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:1	31.36	2125	2.22	13.37	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.04	15.12	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:2	31.36	2128	2.22	13.36	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.08	Lean	1	14.7	-4	15.11	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:2	31.36	2134	2.22	13.38	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.99	15.08	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:2	31.36	2142	2.23	13.38	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.7	-4	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:2	31.36	2151	2.23	13.39	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.01	15.09	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:2	31.36	2152	2.23	13.4	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.04	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:2	31.36	2162	2.23	13.37	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.06	15.14	1.03	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:3	31.36	2184	2.23	13.36	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-4.07	15.15	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:3	31.36	2184	2.23	13.34	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.7	-4.08	15.17	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:3	31.36	2183	2.24	13.34	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.13	15.19	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:3	31.36	2188	2.24	13.35	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-4.15	15.24	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:3	31.36	2192	2.24	13.35	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.7	-4.14	15.26	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:3	31.36	2203	2.24	13.37	100	197	Off Idle	85.4	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.1	15.27	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:4	31.36	2214	2.24	13.37	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.18	Lean	1	14.7	-4.07	15.27	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:4	31.36	2214	2.24	13.37	100	197	Off Idle	85.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.14	15.27	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:4	31.36	2234	2.24	13.35	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.18	15.23	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:4	31.36	2231	2.25	13.37	100	197	Off Idle	84.7	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.19	15.2	1.04	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:4	31.36	2233	2.25	13.38	100	197	Off Idle	84.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-4.24	15.18	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:4	31.36	2242	2.25	13.37	100	197	Off Idle	84.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.25	15.15	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:4	31.36	2251	2.25	13.36	100	197	Off Idle	83.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.25	15.15	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:5	31.36	2285	2.25	13.35	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.41	Lean	1	14.7	-4.32	15.1	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:5	31.36	2285	2.25	13.36	100	197	Off Idle	82.7	0	2	132	944 Turbo	0.41	Lean	1	14.7	-4.28	15.07	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:5	31.36	2276	2.26	13.37	100	197	Off Idle	82.2	0	2	132	944 Turbo	0.42	Lean	1	14.7	-4.28	15.04	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:5	31.36	2290	2.26	13.38	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.42	Lean	1	14.7	-4.33	15	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:5	31.36	2290	2.26	13.36	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.31	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:5	31.36	2316	2.26	13.39	100	197	Off Idle	80.6	0	2	132	944 Turbo	0.37	Lean	1	14.7	-4.34	14.98	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:6	32.72	2316	2.26	13.4	100	197	Off Idle	80.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-4.34	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:6	32.72	2320	2.27	13.41	100	197	Off Idle	79.7	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.34	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:6	32.72	2327	2.27	13.41	100	197	Off Idle	79.3	0	2	132	944 Turbo	0.29	Lean	1	14.7	-4.35	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:6	32.72	2337	2.27	13.42	100	197	Off Idle	78.9	0	2	132	944 Turbo	0.28	Lean	1	14.7	-4.35	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:6	32.72	2340	2.27	13.42	100	197	Off Idle	78.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.36	14.9	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:6	32.72	2340	2.28	13.43	100	197	Off Idle	78.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.33	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:6	32.72	2338	2.28	13.44	100	197	Off Idle	77.7	0	2	132	944 Turbo	0.24	Lean	1	14.7	-4.34	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:7	32.72	2343	2.28	13.41	100	197	Off Idle	76.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-4.37	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:7	32.72	2343	2.29	13.42	100	197	Off Idle	76.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-4.39	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:7	32.72	2350	2.29	13.42	100	197	Off Idle	76.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.38	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:7	32.72	2357	2.29	13.41	100	197	Off Idle	76	0	2	132	944 Turbo	0.33	Lean	1	14.7	-4.43	14.97	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:7	32.72	2371	2.3	13.42	100	197	Off Idle	75.7	0	2	132	944 Turbo	0.37	Lean	1	14.6	-4.45	14.99	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:7	32.72	2384	2.3	13.42	100	197	Off Idle	75.4	0	2	132	944 Turbo	0.39	Lean	1	14.7	-4.49	15	1.02	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:8	32.72	2385	2.3	13.42	100	197	Off Idle	75.1	0	2	132	944 Turbo	0.42	Lean	1	14.6	-4.49	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:8	32.72	2400	2.3	13.42	100	197	Off Idle	74.8	0	2	132	944 Turbo	0.45	Lean	1	14.7	-4.48	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:8	32.72	2400	2.31	13.43	100	197	Off Idle	74.5	0	2	132	944 Turbo	0.49	Lean	1	14.7	-4.52	14.99	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:8	32.72	2406	2.31	13.43	100	197	Off Idle	74.2	0	2	132	944 Turbo	0.51	Lean	1	14.7	-4.51	15.01	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:35:8	32.72	2420	2.31	13.44	100	197	Off Idle	73.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-4.54	15.01	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:35:8	32.72	2430	2.32	13.43	100	197	Off Idle	73.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-4.56	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:9	32.72	2432	2.32	13.41	100	197	Off Idle	72.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-4.56	15	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:9	32.72	2446	2.32	13.42	100	197	Off Idle	72.6	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.56	14.99	1.02	3.4	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:9	32.72	2445	2.32	13.42	100	197	Off Idle	72.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-4.6	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:9	32.72	2445	2.33	13.41	100	197	Off Idle	72	0	2	132	944 Turbo	0.31	Lean	1	14.6	-4.6	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:9	32.72	2459	2.33	13.41	100	197	Off Idle	71.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-4.57	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:9	32.72	2469	2.33	13.4	100	197	Off Idle	71.1	0	2	132	944 Turbo	0.21	Lean	1	14.6	-4.56	14.95	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:35:9	32.72	2472	2.34	13.39	100	197	Off Idle	70.7	0	2	132	944 Turbo	0.14	Lean	1	14.7	-4.57	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:0	32.72	2496	2.34	13.39	100	197	Off Idle	70.7	0	2	132	944 Turbo	0.12	Lean	1	14.7	-4.56	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:0	32.72	2496	2.34	13.38	100	197	Off Idle	70.4	0	2	132	944 Turbo	0.09	Lean	1	14.7	-4.58	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:0	32.72	2506	2.34	13.38	100	197	Off Idle	70.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.65	14.99	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:0	32.72	2514	2.34	13.38	100	197	Off Idle	69.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-4.67	15.01	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:36:0	32.72	2514	2.35	13.38	100	197	Off Idle	69.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.71	15.07	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:0	32.72	2526	2.35	13.38	100	197	Off Idle	68.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-4.7	15.13	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:1	32.72	2529	2.36	13.37	100	197	Off Idle	68.4	0	2	132	944 Turbo	0.18	Lean	1	14.7	-4.69	15.17	1.03	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:1	32.72	2537	2.36	13.38	100	197	Off Idle	68.2	0	2	132	944 Turbo	0.23	Lean	1	14.7	-4.72	15.19	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:1	32.72	2537	2.36	13.38	100	197	Off Idle	67.9	0	2	132	944 Turbo	0.29	Lean	1	14.7	-4.67	15.21	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:1	32.72	2546	2.36	13.38	100	197	Off Idle	67.6	0	2	132	944 Turbo	0.35	Lean	1	14.7	-4.65	15.22	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:1	32.72	2555	2.37	13.39	100	197	Off Idle	67.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-4.67	15.22	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:1	32.72	2555	2.37	13.38	100	197	Off Idle	66.3	0	2	132	944 Turbo	0.44	Lean	1	14.7	-4.71	15.2	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:1	32.72	2562	2.37	13.39	100	197	Off Idle	65.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-4.74	15.2	1.04	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:2	32.72	2562	2.38	13.38	100	197	Off Idle	65.3	0	2	132	944 Turbo	0.58	Rich	1	14.7	-4.75	15.18	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:2	32.72	2573	2.38	13.39	100	197	Off Idle	65	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.74	15.15	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:2	32.72	2584	2.38	13.39	100	197	Off Idle	64.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.75	15.1	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:2	32.72	2589	2.39	13.39	100	197	Off Idle	64.2	0	2	132	944 Turbo	0.67	Rich	1	14.7	-4.77	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:2	32.72	2602	2.39	13.39	100	197	Off Idle	64.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.74	15.04	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:2	32.72	2600	2.39	13.4	100	197	Off Idle	63.6	0	2	132	944 Turbo	0.64	Rich	1	14.7	-4.75	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:3	32.72	2607	2.39	13.38	100	197	Off Idle	63.2	0	2	132	944 Turbo	0.59	Rich	1	14.7	-4.77	15	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:3	32.72	2608	2.4	13.4	100	197	Off Idle	62.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.75	14.99	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:3	32.72	2612	2.4	13.39	100	197	Off Idle	62.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-4.79	14.96	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:3	34.08	2638	2.4	13.39	100	197	Off Idle	61.9	0	2	132	944 Turbo	0.4	Lean	1	14.7	-4.78	14.96	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:36:3	34.08	2638	2.41	13.4	100	197	Off Idle	61.4	0	2	132	944 Turbo	0.34	Lean	1	14.7	-4.8	14.93	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:36:3	34.08	2632	2.41	13.4	100	197	Off Idle	61.1	0	2	132	944 Turbo	0.29	Lean	1	14.7	-4.84	14.92	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:36:4	34.08	2647	2.41	13.4	100	197	Off Idle	60.8	0	2	132	944 Turbo	0.26	Lean	1	14.7	-4.79	14.92	1.02	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:29:36:4	34.08	2654	2.41	13.41	100	197	Off Idle	60.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-4.79	14.93	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:4	34.08	2654	2.42	13.42	100	197	Off Idle	60	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.78	14.94	1.02	3.6	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:4	34.08	2666	2.42	13.43	100	197	Off Idle	59.7	0	2	132	944 Turbo	0.32	Lean	1	14.7	-4.77	14.96	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:4	34.08	2670	2.42	13.41	100	197	Off Idle	59.4	0	2	132	944 Turbo	0.37	Lean	1	14.7	-4.77	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:4	34.08	2670	2.43	13.43	100	197	Off Idle	59	0	2	132	944 Turbo	0.47	Lean	1	14.6	-4.8	14.99	1.02	3.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:4	34.08	2677	2.43	13.43	100	197	Off Idle	58.6	0	2	132	944 Turbo	0.53	Rich	1	14.7	-4.86	14.98	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:5	34.08	2681	2.43	13.42	100	197	Off Idle	58.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-4.85	15.04	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:5	34.08	2690	2.43	13.43	100	197	Off Idle	58.1	0	2	132	944 Turbo	0.65	Rich	1	14.7	-4.84	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:5	34.08	2690	2.43	13.43	100	197	Off Idle	58	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.88	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:5	34.08	2703	2.44	13.43	100	197	Off Idle	57.9	0	2	132	944 Turbo	0.72	Rich	1	14.7	-4.84	15.07	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:5	34.08	2709	2.44	13.44	100	197	Off Idle	57.6	0	2	132	944 Turbo	0.72	Rich	1	14.7	-4.85	15.05	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:5	34.08	2712	2.44	13.42	100	197	Off Idle	57.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.84	15.02	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:6	34.08	2724	2.44	13.4	100	197	Off Idle	57	0	2	132	944 Turbo	0.7	Rich	1	14.7	-4.86	14.99	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:6	34.08	2732	2.44	13.41	100	197	Off Idle	56.7	0	2	132	944 Turbo	0.68	Rich	1	14.7	-4.86	14.96	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:6	34.08	2734	2.45	13.41	100	197	Off Idle	56.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-4.87	14.94	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:6	34.08	2741	2.45	13.4	100	197	Off Idle	56	0	2	132	944 Turbo	0.63	Lean	1	14.7	-4.9	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:6	34.08	2748	2.45	13.41	100	197	Off Idle	55.6	0	2	132	944 Turbo	0.61	Lean	1	14.6	-4.92	14.87	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:6	34.08	2761	2.45	13.42	100	197	Off Idle	55.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-4.89	14.85	1.01	3.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:6	34.08	2775	2.45	13.41	100	197	Off Idle	54.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-4.92	14.84	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:7	34.08	2772	2.45	13.41	100	197	Off Idle	54.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-4.96	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:7	34.08	2777	2.46	13.42	100	197	Off Idle	54.1	0	2	132	944 Turbo	0.37	Lean	1	14.7	-4.93	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:7	34.08	2782	2.46	13.42	100	197	Off Idle	53.4	0	2	132	944 Turbo	0.32	Lean	1	14.7	-4.97	14.85	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:7	34.08	2797	2.46	13.42	100	197	Off Idle	53.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-4.97	14.86	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:7	34.08	2815	2.46	13.41	100	197	Off Idle	52.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.96	14.88	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:7	34.08	2817	2.46	13.4	100	197	Off Idle	52.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.95	14.89	1.01	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:8	34.08	2817	2.47	13.39	100	197	Off Idle	52	0	2	132	944 Turbo	0.14	Lean	1	14.6	-4.96	14.91	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:8	34.08	2819	2.47	13.38	100	197	Off Idle	51.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-4.97	14.94	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:8	34.08	2821	2.47	13.37	100	197	Off Idle	51.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-4.99	14.97	1.02	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:29:36:8	34.08	2822	2.47	13.39	100	197	Off Idle	50.7	0	2	132	944 Turbo	0.25	Lean	1	14.7	-4.98	15	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:8	34.08	2829	2.47	13.38	100	197	Off Idle	50.3	0	2	132	944 Turbo	0.31	Lean	1	14.7	-4.99	15.02	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:8	34.08	2834	2.48	13.39	100	197	Off Idle	50	0	2	132	944 Turbo	0.37	Lean	1	14.7	-4.99	15.06	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:9	34.08	2836	2.48	13.39	100	197	Off Idle	49.7	0	2	132	944 Turbo	0.47	Lean	1	14.7	-5.02	15.09	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:9	34.08	2844	2.48	13.38	100	197	Off Idle	49.7	0	2	132	944 Turbo	0.54	Lean	1	14.6	-4.99	15.16	1.03	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:36:9	34.08	2843	2.48	13.38	100	197	Off Idle	49.5	0	2	132	944 Turbo	0.6	Lean	1	14.6	-5	15.19	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:9	34.08	2841	2.48	13.38	100	197	Off Idle	48.7	0	2	132	944 Turbo	0.66	Lean	1	14.6	-5.06	15.17	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:9	34.08	2842	2.48	13.37	100	198	Off Idle	48.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-5.06	15.13	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:36:9	34.08	2860	2.49	13.39	100	198	Off Idle	48.1	0	2	132	944 Turbo	0.74	Rich	1	14.7	-5.06	15.1	1.03	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:36:9	34.08	2852	2.49	13.4	100	197	Off Idle	47.8	0	2	132	944 Turbo	0.74	Rich	1	14.7	-5.1	15.06	1.03	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:0	34.08	2855	2.49	13.41	100	197	Off Idle	47.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.12	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:0	34.08	2864	2.49	13.42	100	197	Off Idle	47.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.08	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:0	34.08	2864	2.49	13.43	100	197	Off Idle	46.9	0	2	132	944 Turbo	0.71	Rich	1	14.7	-5.08	14.94	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:0	34.08	2874	2.49	13.43	100	197	Off Idle	46.8	0	2	132	944 Turbo	0.68	Rich	1	14.7	-5.09	14.89	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:0	34.08	2884	2.49	13.43	100	197	Off Idle	46.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.06	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:0	34.08	2896	2.49	13.42	100	197	Off Idle	46.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.02	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:1	34.08	2898	2.49	13.43	100	197	Off Idle	46	0	2	132	944 Turbo	0.51	Rich	1	14.7	-5.06	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:1	34.08	2912	2.49	13.42	100	197	Off Idle	45.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.08	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:1	34.08	2912	2.49	13.41	100	197	Off Idle	45.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.08	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:1	34.08	2930	2.5	13.41	100	197	Off Idle	45.2	0	2	132	944 Turbo	0.34	Lean	1	14.7	-5.08	14.82	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:1	34.08	2942	2.5	13.42	100	197	Off Idle	45.1	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.14	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:1	34.08	2942	2.5	13.42	100	197	Off Idle	44.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-5.11	14.85	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:1	34.08	2954	2.5	13.42	100	197	Off Idle	44.2	0	2	132	944 Turbo	0.28	Lean	1	14.7	-5.13	14.87	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:2	34.08	2960	2.5	13.44	100	197	Off Idle	43.9	0	2	132	944 Turbo	0.34	Lean	1	14.7	-5.16	14.88	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:2	34.08	2959	2.5	13.42	100	197	Off Idle	43.6	0	2	132	944 Turbo	0.36	Lean	1	14.7	-5.14	14.9	1.01	3.4	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:2	34.08	2980	2.5	13.44	100	197	Off Idle	43.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.18	14.93	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:2	34.08	2957	2.51	13.42	100	197	Off Idle	43	0	2	132	944 Turbo	0.48	Lean	1	14.7	-5.17	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:2	34.08	2958	2.51	13.41	100	197	Off Idle	42.7	0	2	132	944 Turbo	0.54	Rich	1	14.7	-5.2	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:2	34.08	2959	2.51	13.42	100	197	Off Idle	42.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.22	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:3	34.08	2956	2.51	13.43	100	197	Off Idle	42.3	0	2	132	944 Turbo	0.64	Rich	1	14.7	-5.19	15.03	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:3	34.08	2957	2.51	13.43	100	197	Off Idle	42.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.24	15.02	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:3	34.08	2956	2.51	13.44	100	197	Off Idle	42	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.2	15.01	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:37:3	34.08	2960	2.51	13.44	100	197	Off Idle	41.8	0	2	132	944 Turbo	0.58	Rich	1	14.7	-5.22	14.99	1.02	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:37:3	35.45	2960	2.51	13.45	100	197	Off Idle	41.7	0	2	132	944 Turbo	0.55	Rich	1	14.7	-5.18	14.98	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:3	35.45	2966	2.51	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.26	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:4	35.45	2983	2.51	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Rich	1	14.7	-5.26	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:4	35.45	2993	2.51	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.29	14.83	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:4	35.45	3008	2.51	13.41	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-5.31	14.8	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:4	35.45	3009	2.51	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.7	-5.38	14.81	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:4	35.45	3019	2.51	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.18	Lean	1	14.7	-5.36	14.83	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:4	35.45	3022	2.51	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.42	14.85	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:4	35.45	3034	2.51	13.41	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-5.4	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:5	35.45	3041	2.5	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.43	14.91	1.02	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:37:5	35.45	3042	2.5	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.7	-5.44	14.95	1.02	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:37:5	35.45	3071	2.5	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.33	Lean	1	14.7	-5.5	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:37:5	35.45	3054	2.5	13.42	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.7	-5.57	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:37:5	35.45	3056	2.49	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.46	Lean	1	14.7	-5.66	15.06	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:37:5	35.45	3052	2.49	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.7	-5.67	15.1	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:37:6	35.45	3045	2.48	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.81	15.1	1.03	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:37:6	35.45	3045	2.47	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.86	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:6	35.45	3050	2.47	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-5.86	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:6	35.45	3050	2.46	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-5.91	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:6	35.45	3052	2.46	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.7	-5.95	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:37:6	35.45	3056	2.45	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:37:6	35.45	3058	2.45	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.7	-6	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:37:7	35.45	3058	2.44	13.42	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.7	-6.11	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:37:7	35.45	3064	2.44	13.41	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-6.1	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:7	35.45	3066	2.43	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.19	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:7	35.45	3082	2.43	13.42	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.47	Lean	1	14.7	-6.16	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:7	35.45	3082	2.42	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.41	Lean	1	14.7	-6.19	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:7	35.45	3102	2.42	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.14	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:8	35.45	3089	2.41	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.7	-6.21	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:8	35.45	3089	2.41	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.2	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:8	35.45	3092	2.41	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.23	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:8	35.45	3098	2.4	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.13	Lean	1	14.7	-6.2	14.9	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:8	35.45	3102	2.4	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.12	Lean	1	14.7	-6.25	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:37:8	35.45	3104	2.4	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.2	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:9	35.45	3110	2.4	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.27	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:37:9	35.45	3111	2.4	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.23	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:37:9	35.45	3111	2.4	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.29	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:37:9	35.45	3116	2.4	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.26	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:37:9	35.45	3119	2.4	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.38	Rich	1	14.7	-6.3	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:37:9	35.45	3120	2.4	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.32	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:37:9	35.45	3118	2.4	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.33	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:0	35.45	3121	2.4	13.46	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.27	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:0	35.45	3118	2.4	13.45	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.56	Rich	1	14.7	-6.37	15.15	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:0	35.45	3118	2.4	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.33	15.12	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:0	35.45	3111	2.4	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.36	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:0	35.45	3109	2.4	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.33	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:0	35.45	3110	2.4	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.38	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:1	35.45	3118	2.4	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.34	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:1	35.45	3126	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.4	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:1	36.81	3130	2.39	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.34	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:1	36.81	3130	2.39	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.2	Lean	1	14.7	-6.37	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:1	36.81	3140	2.39	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.37	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:1	36.81	3144	2.39	13.45	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.43	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:1	36.81	3179	2.39	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.38	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:2	36.81	3179	2.39	13.45	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.44	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:2	36.81	3160	2.39	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.44	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:2	36.81	3163	2.39	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.41	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:2	36.81	3162	2.39	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.59	Rich	1	14.7	-6.37	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:2	36.81	3150	2.39	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.65	Rich	1	14.7	-6.43	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:2	35.45	3163	2.39	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.36	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:3	35.45	3163	2.39	13.44	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.42	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:3	35.45	3163	2.39	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.4	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:3	35.45	3163	2.39	13.43	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.7	-6.44	15.03	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:3	35.45	3161	2.39	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.45	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:3	35.45	3162	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-6.51	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:3	35.45	3161	2.39	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.47	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:4	35.45	3156	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.51	Lean	1	14.7	-6.51	14.9	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:4	35.45	3156	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.52	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:4	36.81	3182	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.35	Lean	1	14.7	-6.51	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:4	36.81	3161	2.39	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.32	Lean	1	14.7	-6.51	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:4	36.81	3164	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.26	Lean	1	14.7	-6.55	14.78	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:4	36.81	3168	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.58	14.78	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:4	36.81	3175	2.39	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.7	-6.53	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:5	36.81	3184	2.39	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.56	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:5	36.81	3185	2.39	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.53	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:5	36.81	3192	2.39	13.41	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.18	Rich	1	14.6	-6.54	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:5	36.81	3193	2.39	13.42	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.23	Rich	1	14.6	-6.54	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:5	36.81	3194	2.39	13.42	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.54	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:5	36.81	3199	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.56	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:6	36.81	3205	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.58	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:6	36.81	3203	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.58	15.05	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:6	36.81	3205	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.55	Rich	1	14.7	-6.59	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:6	36.81	3206	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.59	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:6	36.81	3202	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.59	15.09	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:6	36.81	3203	2.39	13.41	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.64	Rich	1	14.7	-6.58	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:6	36.81	3202	2.39	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.6	Lean	1	14.7	-6.57	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:7	36.81	3199	2.39	13.42	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.62	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:7	36.81	3196	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.5	Lean	1	14.6	-6.55	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:7	36.81	3196	2.39	13.42	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.59	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:7	36.81	3198	2.39	13.43	100	198	Off Idle	41.4	0	2	132	944 Turbo	0.38	Lean	1	14.7	-6.59	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:7	36.81	3200	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.6	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:38:7	36.81	3200	2.39	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.59	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:8	36.81	3206	2.39	13.43	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.25	Lean	1	14.7	-6.64	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:8	36.81	3210	2.39	13.45	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.65	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:38:8	36.81	3212	2.39	13.43	100	198	Off Idle	41.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.67	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:38:8	36.81	3212	2.39	13.45	100	198	Off Idle	41.4	0	2	132	944 Turbo	0.35	Rich	1	14.6	-6.68	14.9	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:8	36.81	3214	2.39	13.43	100	198	Off Idle	41.4	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.64	14.92	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:8	36.81	3214	2.39	13.45	100	198	Off Idle	41.4	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.66	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:9	36.81	3216	2.39	13.45	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.61	15.01	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:9	36.81	3210	2.39	13.44	100	198	Off Idle	41.4	0	2	132	944 Turbo	0.6	Rich	1	14.7	-6.67	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:9	36.81	3210	2.39	13.44	100	198	Off Idle	41.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.71	15.08	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:9	36.81	3209	2.39	13.45	100	197	Off Idle	41.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.71	15.07	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:9	36.81	3207	2.38	13.45	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.78	15.04	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:38:9	36.81	3204	2.37	13.44	100	197	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.88	15.02	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:38:9	36.81	3204	2.35	13.45	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.08	15.01	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:39:0	36.81	3202	2.3	13.45	100	198	Off Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.48	14.95	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:39:0	36.81	3197	2.27	13.45	100	197	Full Load	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.86	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:39:0	36.81	3184	2.23	13.44	100	197	Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.15	14.9	1.01	3.6	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:39:0	36.81	3178	2.2	13.43	100	197	Idle	41.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.49	14.85	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:39:0	36.81	3176	2.15	13.42	100	197	Idle	41.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-8.8	14.82	1.01	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:39:0	36.81	3161	2.12	13.43	100	197	Idle	41.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9	14.82	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:39:1	34.08	3083	2.08	13.41	100	197	Idle	41.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.14	14.82	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:39:1	28.63	3063	2.05	13.44	100	198	Idle	41.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-9.27	14.82	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:39:1	23.18	3046	2.02	13.43	100	198	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.34	14.82	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:39:1	23.18	3068	1.98	13.43	100	198	Idle	41.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-9.43	14.84	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:39:1	20.45	3064	1.97	13.43	100	197	Idle	41.5	0	2	132	944 Turbo	0.78	Lean	1	14.6	-9.49	14.84	1.01	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:39:1	20.45	3024	1.93	13.44	100	197	Idle	41.5	0	2	132	944 Turbo	0.73	Lean	1	14.6	-9.59	14.82	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:1	19.09	3012	1.9	13.44	100	197	Idle	41.3	0	2	132	944 Turbo	0.63	Lean	1	14.6	-9.64	14.79	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:2	19.09	3006	1.87	13.44	100	197	Idle	41.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-9.7	14.76	1.01	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:2	19.09	2983	1.83	13.44	100	197	Idle	40.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	-9.77	14.69	1	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:2	19.09	2969	1.8	13.44	100	197	Idle	39.6	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.77	14.62	1	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:2	19.09	2954	1.79	13.44	100	198	Idle	38.9	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.76	14.53	0.99	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:2	19.09	2936	1.75	13.43	100	198	Idle	38.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-9.73	14.45	0.98	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:2	19.09	2906	1.74	13.44	100	198	Idle	37.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.76	14.37	0.98	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:3	19.09	2876	1.73	13.43	100	197	Idle	37.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.7	14.32	0.98	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:3	19.09	2857	1.73	13.43	100	197	Idle	36.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.66	14.28	0.97	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:3	19.09	2824	1.73	13.43	100	197	Idle	35.8	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.65	14.28	0.97	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:3	19.09	2817	1.74	13.43	100	197	Idle	35.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.58	14.3	0.97	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:3	19.09	2785	1.74	13.43	100	197	Idle	34.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.5	14.33	0.98	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:3	19.09	2738	1.75	13.43	100	197	Idle	34.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.39	14.4	0.98	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:4	19.09	2728	1.75	13.45	100	197	Idle	33.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-9.35	14.51	0.99	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:4	19.09	2728	1.75	13.44	100	197	Idle	33.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.29	14.63	1	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:4	19.09	2676	1.75	13.43	100	197	Idle	32.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.21	14.76	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:4	19.09	2661	1.76	13.44	100	198	Idle	32.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.2	14.89	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:4	19.09	2642	1.76	13.44	100	198	Idle	33	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.17	14.99	1.02	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:4	19.09	2620	1.77	13.43	100	198	Idle	33.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.13	15.09	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:4	19.09	2596	1.77	13.43	100	197	Idle	34.4	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.14	15.18	1.03	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:5	19.09	2596	1.77	13.45	100	197	Idle	35	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.12	15.27	1.04	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:5	19.09	2554	1.77	13.43	100	197	Idle	35.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.1	15.39	1.05	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:5	19.09	2508	1.77	13.44	100	197	Idle	35.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	15.49	1.06	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:5	19.09	2511	1.77	13.42	100	197	Idle	36.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	15.67	1.07	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:5	19.09	2502	1.77	13.42	100	197	Idle	37.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.03	15.85	1.08	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:5	19.09	2460	1.77	13.41	100	197	Idle	37.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	16.13	1.1	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:6	19.09	2444	1.77	13.42	100	197	Idle	38.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.01	16.54	1.13	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:6	19.09	2434	1.77	13.43	100	197	Idle	39.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.97	17.23	1.17	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:6	19.09	2409	1.76	13.42	100	198	Idle	40.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.94	17.7	1.21	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:6	19.09	2374	1.76	13.43	100	198	Idle	41.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.94	18.16	1.24	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:6	19.09	2356	1.75	13.44	100	198	Idle	42.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.93	18.6	1.27	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:6	19.09	2339	1.74	13.44	100	197	Idle	44	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.93	19.04	1.3	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:39:6	19.09	2304	1.73	13.45	100	197	Idle	45.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.94	19.44	1.32	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:7	17.72	2269	1.72	13.45	100	197	Idle	46.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.95	19.8	1.35	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:7	17.72	2269	1.71	13.44	100	197	Idle	47.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.96	20.07	1.37	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:7	17.72	2259	1.69	13.44	100	197	Idle	48.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.99	20.2	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:7	17.72	2232	1.68	13.43	100	197	Idle	49.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.04	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:7	17.72	2224	1.66	13.43	100	198	Idle	50.8	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.04	20.22	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:7	17.72	2178	1.64	13.42	100	198	Idle	52.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.06	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:8	17.72	2161	1.63	13.4	100	198	Idle	54.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.07	20.22	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:8	17.72	2161	1.61	13.41	100	197	Idle	55.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.04	20.23	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:8	17.72	2124	1.59	13.42	100	197	Full Load	57.1	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.04	20.25	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:8	17.72	2087	1.57	13.43	100	197	Off Idle	58.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.09	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:8	17.72	2085	1.56	13.44	100	198	Off Idle	59.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.11	20.24	1.38	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:8	17.72	2023	1.55	13.46	100	198	Off Idle	60.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.11	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:39:9	9.54	2061	1.55	13.46	100	198	Off Idle	62.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-9.08	20.25	1.38	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:39:9	9.54	2042	1.54	13.45	100	198	Off Idle	64.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.96	20.25	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:9	12.27	2003	1.54	13.43	100	198	Off Idle	66.4	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.84	20.26	1.38	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:39:9	12.27	2003	1.54	13.43	100	197	Off Idle	68.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.73	20.25	1.38	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:29:39:9	14.99	1953	1.54	13.41	100	197	Off Idle	70.5	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.61	20.24	1.38	3.8	2	ON	28 Pin	OFF	Removed	Disabled
03:29:39:9	14.99	1930	1.55	13.41	100	197	Off Idle	72.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.43	20.24	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:39:9	17.72	1930	1.56	13.39	100	198	Off Idle	73.9	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.25	20.24	1.38	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:0	20.45	1900	1.58	13.39	100	198	Off Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-8.06	20.24	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:0	20.45	1866	1.59	13.39	100	198	Off Idle	77.2	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.89	20.24	1.38	3.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:0	20.45	1834	1.62	13.41	100	198	Off Idle	80.3	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.67	20.24	1.38	3.8	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:40:0	23.18	1834	1.64	13.42	100	198	Off Idle	81.6	0	2	132	944 Turbo	0.01	Lean	1	14.6	-7.49	20.24	1.38	3.9	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:40:0	25.9	1808	1.66	13.42	100	198	Off Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.32	20.24	1.38	3.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:40:0	25.9	1800	1.67	13.42	100	197	Off Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.19	20.24	1.38	3.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:40:1	25.9	1793	1.69	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-7.08	20.24	1.38	3.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:40:1	28.63	1760	1.73	13.42	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.95	20.24	1.38	3.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:40:1	28.63	1775	1.75	13.42	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.02	Lean	1	14.7	-6.87	20.23	1.38	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:40:1	29.99	1768	1.77	13.43	100	198	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.81	20.24	1.38	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:40:1	29.99	1772	1.79	13.43	100	198	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.68	20.24	1.38	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:1	29.99	1785	1.81	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.57	20.24	1.38	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:1	29.99	1800	1.84	13.41	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-6.4	20.23	1.38	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:2	29.99	1813	1.86	13.4	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.27	20.24	1.38	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:2	29.99	1818	1.87	13.39	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-6.13	20.23	1.38	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:40:2	29.99	1830	1.89	13.4	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-6.05	20.23	1.38	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:40:2	29.99	1832	1.9	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-5.98	20.24	1.38	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:40:2	29.99	1832	1.91	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.14	Rich	1	14.6	-5.89	20.24	1.38	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:40:2	29.99	1830	1.91	13.42	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.83	20.24	1.38	3.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:40:3	29.99	1819	1.92	13.42	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.72	20.23	1.38	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:3	29.99	1819	1.92	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.63	20.24	1.38	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:3	29.99	1811	1.92	13.4	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.55	20.24	1.38	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:3	29.99	1801	1.93	13.4	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.5	20.21	1.38	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:3	29.99	1801	1.93	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.48	20.08	1.37	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:3	29.99	1794	1.94	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.39	19.85	1.35	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:4	29.99	1798	1.95	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.69	Rich	1	14.7	-5.35	19.54	1.33	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:4	29.99	1798	1.95	13.4	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.33	19.17	1.31	3.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:4	29.99	1802	1.96	13.4	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.31	18.76	1.28	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:4	29.99	1803	1.96	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.28	18.31	1.25	3.8	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:4	29.99	1806	1.97	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.29	17.85	1.22	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:4	28.63	1807	1.97	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.28	17.38	1.18	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:4	28.63	1827	1.98	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.75	Rich	1	14.7	-5.27	16.89	1.15	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:5	28.63	1830	1.98	13.4	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.2	16.22	1.11	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:5	28.63	1831	1.97	13.4	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.22	15.89	1.08	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:5	28.63	1832	1.97	13.4	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.69	Rich	1	14.7	-5.24	15.66	1.07	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:5	28.63	1827	1.97	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.25	15.43	1.05	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:5	28.63	1827	1.97	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.24	15.33	1.04	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:5	28.63	1818	1.97	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.27	15.29	1.04	3.7	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:40:6	28.63	1813	1.97	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.28	15.17	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:6	28.63	1812	1.97	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.31	15.11	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:6	28.63	1812	1.97	13.44	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.3	15.07	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:6	28.63	1815	1.96	13.44	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.33	15.05	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:6	28.63	1821	1.96	13.44	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.29	15.05	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:6	28.63	1821	1.96	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.29	15.05	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:6	28.63	1826	1.96	13.42	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.25	15.06	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:7	28.63	1832	1.96	13.42	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.29	15.05	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:7	28.63	1832	1.96	13.42	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.29	15.05	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:7	28.63	1836	1.96	13.43	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.31	15.09	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:7	28.63	1838	1.96	13.44	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.31	15.12	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:7	28.63	1838	1.96	13.44	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.26	Lean	1	14.7	-5.34	15.15	1.03	3.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:40:7	28.63	1842	1.96	13.44	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.33	15.17	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:8	28.63	1843	1.96	13.44	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.37	Lean	1	14.7	-5.33	15.17	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:8	28.63	1843	1.96	13.42	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.32	15.17	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:8	28.63	1840	1.96	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.3	15.17	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:8	28.63	1847	1.96	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-5.26	15.17	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:8	28.63	1847	1.96	13.4	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.24	15.17	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:8	28.63	1838	1.96	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.69	Lean	1	14.7	-5.23	15.17	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:9	28.63	1836	1.96	13.42	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.3	15.16	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:9	28.63	1838	1.96	13.43	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-5.28	15.17	1.03	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:40:9	28.63	1847	1.96	13.41	100	197	Off Idle	86.2	0	2	132	944 Turbo	0.78	Rich	1	14.7	-5.29	15.18	1.03	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:40:9	28.63	1862	1.96	13.42	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.29	15.14	1.03	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:40:9	28.63	1861	1.96	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.29	15.11	1.03	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:40:9	28.63	1861	1.96	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.31	15.09	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:40:9	28.63	1867	1.96	13.41	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.32	15.05	1.03	3.7	3	ON	28 Pin	OFF	Removed	Disabled
03:29:41:0	28.63	1867	1.96	13.42	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.37	14.99	1.02	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:0	28.63	1866	1.96	13.43	100	198	Off Idle	86.2	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.36	14.93	1.02	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:0	28.63	1864	1.96	13.43	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.33	14.88	1.01	3.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:0	28.63	1864	1.96	13.42	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.27	14.82	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:0	28.63	1864	1.96	13.4	100	197	Off Idle	86.1	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.29	14.7	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:0	28.63	1863	1.96	13.4	100	198	Off Idle	86.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.31	14.64	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:1	28.63	1864	1.97	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.36	14.57	0.99	3.8	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:1	29.99	1879	1.97	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.8	Rich	1	14.7	-5.39	14.51	0.99	3.8	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:1	29.99	1868	1.97	13.42	100	197	Off Idle	86	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.38	14.47	0.99	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:1	29.99	1868	1.97	13.41	100	197	Off Idle	86	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.36	14.46	0.98	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:1	29.99	1868	1.97	13.4	100	197	Off Idle	86	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.34	14.43	0.98	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:1	29.99	1868	1.97	13.42	100	198	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.35	14.42	0.98	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:1	29.99	1870	1.97	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.31	14.41	0.98	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:2	29.99	1868	1.97	13.41	100	198	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.31	14.41	0.98	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:2	29.99	1872	1.97	13.41	100	197	Off Idle	86	0	2	132	944 Turbo	0.79	Rich	1	14.7	-5.34	14.4	0.98	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:2	29.99	1870	1.97	13.4	100	197	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.7	-5.33	14.41	0.98	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:2	29.99	1870	1.97	13.4	100	197	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.7	-5.34	14.43	0.98	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:2	29.99	1870	1.97	13.4	100	198	Off Idle	86	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.37	14.43	0.98	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:2	29.99	1874	1.97	13.4	100	198	Off Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.7	-5.38	14.43	0.98	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:3	29.99	1877	1.97	13.42	100	197	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.37	14.45	0.98	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:3	29.99	1881	1.97	13.42	100	197	Off Idle	86	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.39	14.46	0.99	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:3	29.99	1882	1.97	13.42	100	197	Off Idle	86	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.4	14.47	0.99	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:3	29.99	1885	1.97	13.43	100	197	Off Idle	86	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.42	14.48	0.99	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:3	29.99	1886	1.97	13.43	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.43	14.51	0.99	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:3	29.99	1892	1.97	13.43	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.44	14.54	0.99	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:4	29.99	1892	1.97	13.42	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.39	14.56	0.99	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:4	29.99	1892	1.97	13.41	100	198	Off Idle	85.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.38	14.58	0.99	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:4	29.99	1891	1.97	13.4	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.34	14.62	1	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:4	29.99	1892	1.97	13.38	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.36	14.66	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:4	29.99	1892	1.97	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.38	14.69	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:4	29.99	1891	1.97	13.38	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.41	14.72	1	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:4	29.99	1889	1.97	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.44	14.77	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:41:5	29.99	1892	1.97	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.49	14.79	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:5	29.99	1896	1.97	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.48	14.8	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:5	29.99	1902	1.97	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.46	14.81	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:5	29.99	1909	1.97	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.45	14.82	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:5	29.99	1909	1.97	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.47	14.8	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:5	29.99	1912	1.97	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.47	14.8	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:6	29.99	1911	1.97	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.51	14.8	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:6	29.99	1908	1.97	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.56	14.82	1.01	3.7	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:41:6	29.99	1908	1.97	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.57	14.84	1.01	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:6	29.99	1907	1.97	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.56	14.85	1.01	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:6	29.99	1909	1.96	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.53	14.89	1.01	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:6	29.99	1909	1.96	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.51	14.94	1.02	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:6	29.99	1907	1.96	13.38	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.51	14.96	1.02	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:7	29.99	1902	1.96	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.56	14.98	1.02	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:7	29.99	1908	1.96	13.38	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.6	15.03	1.02	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:7	29.99	1908	1.96	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.67	Rich	1	14.7	-5.64	15.07	1.03	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:7	29.99	1911	1.96	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.7	15.1	1.03	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:7	29.99	1912	1.96	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.71	15.11	1.03	3.7	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:7	29.99	1913	1.96	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.71	15.09	1.03	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:41:8	29.99	1916	1.96	13.46	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.73	15.07	1.03	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:41:8	29.99	1918	1.96	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.68	Lean	1	14.6	-5.72	15.03	1.02	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:41:8	29.99	1918	1.95	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.71	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:41:8	29.99	1923	1.95	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.72	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:8	29.99	1926	1.95	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.74	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:8	29.99	1928	1.95	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-5.72	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:9	29.99	1928	1.95	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.71	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:9	29.99	1934	1.95	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.68	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:9	29.99	1934	1.95	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.67	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:9	29.99	1936	1.95	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.63	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:9	29.99	1940	1.95	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.64	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:9	31.36	1940	1.95	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.66	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:41:9	31.36	1949	1.95	13.38	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.68	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:0	31.36	1942	1.95	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.69	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:0	31.36	1941	1.95	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.78	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:0	31.36	1941	1.95	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.81	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:0	31.36	1936	1.95	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.79	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:0	31.36	1936	1.95	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.77	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:0	31.36	1936	1.95	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.71	15.05	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:1	29.99	1925	1.95	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.7	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:1	29.99	1936	1.95	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.31	Lean	1	14.7	-5.69	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:1	29.99	1936	1.95	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.69	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:1	29.99	1936	1.95	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.7	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:1	29.99	1940	1.95	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.71	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:1	29.99	1943	1.95	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.72	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:1	29.99	1944	1.96	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.58	Rich	1	14.7	-5.74	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:2	29.99	1946	1.96	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.75	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:2	29.99	1951	1.96	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.74	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:2	29.99	1955	1.96	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.75	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:2	29.99	1956	1.96	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.73	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:2	29.99	1959	1.96	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.73	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:2	29.99	1961	1.96	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.71	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:3	29.99	1957	1.96	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.7	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:3	29.99	1957	1.96	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.74	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:3	29.99	1955	1.96	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.78	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:3	31.36	1966	1.96	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.78	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:3	31.36	1958	1.96	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.79	14.9	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:3	31.36	1948	1.96	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.8	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:4	31.36	1948	1.96	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.8	14.88	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:42:4	31.36	1950	1.96	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.8	14.9	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:42:4	31.36	1957	1.96	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.8	14.92	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:42:4	31.36	1960	1.96	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.78	14.93	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:42:4	31.36	1962	1.96	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.7	-5.79	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:4	29.99	1956	1.96	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.78	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:4	29.99	1975	1.96	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.78	15.07	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:42:5	29.99	1980	1.96	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.77	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:5	29.99	1980	1.96	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.79	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:5	29.99	1982	1.96	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.79	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:5	29.99	1976	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-5.81	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:5	29.99	1976	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.79	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:5	31.36	1982	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.46	Lean	1	14.7	-5.81	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:6	31.36	1969	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.8	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:6	31.36	1969	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.81	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:6	31.36	1983	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.82	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:6	31.36	1975	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.81	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:6	31.36	1976	1.97	13.45	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.82	15.08	1.03	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:6	31.36	1976	1.97	13.44	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.82	15.07	1.03	3.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:6	31.36	1966	1.97	13.45	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.84	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:7	31.36	1985	1.97	13.45	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.82	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:7	31.36	1986	1.97	13.45	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.86	15	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:7	31.36	1985	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.87	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:7	31.36	1987	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.88	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:7	31.36	1988	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.85	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:7	31.36	1992	1.97	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-5.88	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:8	31.36	1991	1.97	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.29	Lean	1	14.7	-5.87	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:8	31.36	1993	1.97	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.85	14.83	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:42:8	31.36	2003	1.97	13.43	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.85	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:8	31.36	2006	1.97	13.43	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.86	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:8	31.36	2002	1.97	13.44	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.81	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:8	31.36	2002	1.97	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.8	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:9	31.36	1997	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.81	14.9	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:9	31.36	1996	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.82	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:42:9	31.36	2000	1.97	13.46	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.19	Rich	1	14.6	-5.85	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:9	31.36	2000	1.97	13.46	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.24	Rich	1	14.6	-5.88	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:9	31.36	2001	1.97	13.46	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.92	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:9	31.36	2001	1.97	13.46	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.92	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:42:9	31.36	2001	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.91	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:0	31.36	2005	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.91	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:0	31.36	2008	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.91	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:0	31.36	2009	1.97	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.86	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:0	31.36	2010	1.97	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.87	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:0	31.36	2008	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.88	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:0	31.36	2007	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.89	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:1	31.36	2007	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.89	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:1	31.36	2009	1.97	13.45	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.89	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:1	31.36	2012	1.97	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.68	Rich	1	14.7	-5.88	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:1	31.36	2012	1.97	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.89	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:1	31.36	2017	1.97	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.9	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:1	31.36	2021	1.97	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.93	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:1	31.36	2022	1.97	13.38	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.93	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:2	31.36	2020	1.97	13.38	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.37	Rich	1	14.7	-5.94	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:2	31.36	2024	1.97	13.37	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.91	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:2	31.36	2027	1.97	13.38	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.89	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:2	31.36	2027	1.97	13.37	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.87	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:2	31.36	2028	1.97	13.38	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.88	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:2	31.36	2029	1.97	13.39	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.11	Lean	1	14.7	-5.91	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:3	31.36	2029	1.97	13.39	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.91	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:43:3	31.36	2025	1.97	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.91	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:3	31.36	2022	1.97	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.86	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:3	31.36	2022	1.97	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.84	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:3	31.36	2024	1.97	13.4	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.81	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:3	31.36	2022	1.97	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.82	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:4	31.36	2025	1.97	13.41	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.82	15.05	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:4	31.36	2026	1.97	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.83	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:4	31.36	2029	1.97	13.42	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.83	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:4	31.36	2028	1.97	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.33	Lean	1	14.7	-5.83	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:4	31.36	2031	1.97	13.43	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.39	Lean	1	14.7	-5.83	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:4	31.36	2038	1.97	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.48	Lean	1	14.7	-5.84	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:4	31.36	2044	1.98	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.85	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:43:5	31.36	2048	1.98	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.59	Lean	1	14.7	-5.83	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:5	31.36	2048	1.98	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.65	Lean	1	14.6	-5.82	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:5	31.36	2045	1.99	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.8	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:5	31.36	2041	1.99	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.77	15.15	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:5	31.36	2041	1.99	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.73	15.12	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:43:5	31.36	2039	2	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.68	15.09	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:43:6	31.36	2038	2	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.67	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:6	31.36	2039	2.01	13.44	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.62	Rich	1	14.7	-5.63	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:43:6	31.36	2039	2.01	13.42	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.57	15.02	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:6	31.36	2044	2.02	13.41	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.5	15	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:6	31.36	2046	2.03	13.4	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.42	Rich	1	14.6	-5.41	14.96	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:6	31.36	2046	2.03	13.39	100	197	Off Idle	85.9	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.31	14.92	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:6	31.36	2056	2.04	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.22	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:43:7	31.36	2063	2.05	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.16	14.88	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:43:7	31.36	2065	2.06	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.17	14.84	1.01	3.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:29:43:7	31.36	2068	2.06	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.17	14.84	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:43:7	29.99	2054	2.07	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.15	14.86	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:43:7	29.99	2054	2.08	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-5.15	14.9	1.01	3.5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:43:7	29.99	2069	2.08	13.39	100	197	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.1	14.91	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:43:8	29.99	2066	2.08	13.39	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.08	14.96	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:43:8	29.99	2062	2.09	13.41	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.18	Lean	1	14.7	-5.06	15.01	1.02	3.6	3.1	ON	28 Pin	OFF	Removed	Disabled
03:29:43:8	29.99	2058	2.09	13.42	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.08	15.06	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:8	29.99	2054	2.09	13.43	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.06	15.1	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:8	29.99	2066	2.1	13.45	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.07	15.15	1.03	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:8	31.36	2066	2.1	13.45	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.07	15.19	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:9	31.36	2055	2.1	13.45	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.07	15.22	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:9	31.36	2046	2.1	13.45	100	197	Off Idle	85.7	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.06	15.2	1.04	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:9	31.36	2046	2.1	13.45	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.07	15.21	1.04	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:9	31.36	2070	2.1	13.44	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.05	15.18	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:9	31.36	2073	2.1	13.44	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.1	15.14	1.03	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:43:9	31.36	2076	2.1	13.44	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.13	15.1	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:43:9	31.36	2089	2.1	13.43	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.7	-5.12	15.05	1.03	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:44:0	31.36	2083	2.1	13.43	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.16	15.01	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:44:0	31.36	2078	2.1	13.43	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.15	14.94	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:44:0	31.36	2078	2.1	13.43	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.12	14.91	1.02	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:44:0	31.36	2074	2.1	13.43	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.13	14.87	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:44:0	31.36	2069	2.1	13.42	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.09	14.81	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:44:0	31.36	2071	2.1	13.41	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-5.07	14.78	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:1	31.36	2072	2.09	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.11	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:1	31.36	2077	2.09	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.13	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:1	31.36	2081	2.09	13.4	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.09	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:1	31.36	2084	2.09	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.15	14.77	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:1	31.36	2092	2.09	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.17	14.76	1.01	3.6	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:1	31.36	2099	2.09	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.19	14.78	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:1	31.36	2106	2.09	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.19	14.81	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:2	31.36	2108	2.09	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.25	14.85	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:44:2	31.36	2110	2.09	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.28	14.86	1.01	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:2	31.36	2109	2.09	13.4	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.3	14.93	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:2	31.36	2107	2.09	13.39	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.34	14.98	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:2	31.36	2104	2.08	13.38	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.34	15.03	1.02	3.5	3	ON	28 Pin	OFF	Removed	Disabled
03:29:44:2	31.36	2100	2.08	13.37	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.37	15.08	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:3	31.36	2102	2.08	13.39	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.28	Rich	1	14.6	-5.37	15.13	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:3	31.36	2102	2.07	13.4	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-5.38	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:3	31.36	2102	2.07	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.43	Rich	1	14.7	-5.38	15.21	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:3	31.36	2101	2.06	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.41	15.21	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:3	31.36	2098	2.06	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.41	15.2	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:3	31.36	2098	2.06	13.4	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.44	15.2	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:4	31.36	2100	2.05	13.39	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.45	15.21	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:4	31.36	2099	2.05	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.48	15.21	1.04	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:4	31.36	2100	2.05	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.5	15.17	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:4	31.36	2104	2.04	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.52	15.13	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:4	31.36	2110	2.04	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.7	-5.57	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:44:4	31.36	2110	2.04	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-5.59	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:44:4	31.36	2115	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.61	15.03	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:44:5	31.36	2119	2.03	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.62	14.98	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:44:5	31.36	2125	2.03	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.44	Rich	1	14.7	-5.64	14.96	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:44:5	31.36	2125	2.03	13.44	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.39	Rich	1	14.6	-5.68	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:5	31.36	2130	2.03	13.44	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.72	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:5	31.36	2147	2.03	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-5.75	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:5	31.36	2147	2.03	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5.74	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:6	31.36	2132	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.17	Rich	1	14.6	-5.74	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:6	31.36	2129	2.03	13.41	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.74	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:6	31.36	2127	2.03	13.42	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.71	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:6	31.36	2128	2.03	13.43	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.71	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:6	31.36	2130	2.03	13.45	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.73	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:6	31.36	2133	2.03	13.46	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.16	Lean	1	14.7	-5.71	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:6	31.36	2133	2.03	13.46	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.72	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:7	31.36	2138	2.03	13.43	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.75	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:7	31.36	2123	2.03	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.76	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:7	31.36	2138	2.03	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.78	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:7	31.36	2136	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.81	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:7	31.36	2135	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.8	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:7	31.36	2135	2.03	13.4	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.78	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:8	31.36	2144	2.03	13.4	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.77	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:8	31.36	2136	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.75	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:44:8	31.36	2135	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.75	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:44:8	31.36	2135	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.76	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:44:8	31.36	2136	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.76	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:44:8	31.36	2140	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.76	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:44:9	31.36	2144	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.75	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:44:9	31.36	2146	2.03	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.74	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:44:9	31.36	2144	2.03	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.76	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:9	31.36	2156	2.03	13.41	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.79	14.99	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:9	31.36	2154	2.03	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.83	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:9	31.36	2154	2.03	13.41	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.82	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:44:9	31.36	2155	2.03	13.4	101	197	Off Idle	85.6	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.81	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:0	31.36	2174	2.03	13.41	101	197	Off Idle	85.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.8	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:0	31.36	2165	2.03	13.43	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.8	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:0	31.36	2158	2.03	13.42	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.8	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:0	31.36	2158	2.03	13.43	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.86	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:0	31.36	2157	2.03	13.43	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.87	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:0	31.36	2155	2.03	13.41	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.7	-5.86	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:1	31.36	2154	2.03	13.41	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.85	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:1	31.36	2156	2.03	13.41	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.82	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:45:1	31.36	2160	2.03	13.41	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.81	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:1	31.36	2162	2.03	13.4	101	197	Off Idle	85.6	0	2	132	944 Turbo	0.25	Lean	1	14.7	-5.83	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:1	31.36	2162	2.03	13.4	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.86	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:1	31.36	2159	2.03	13.39	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.86	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:1	31.36	2158	2.03	13.39	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.85	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:2	31.36	2158	2.03	13.4	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.85	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:2	31.36	2160	2.03	13.41	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.82	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:2	31.36	2157	2.03	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.63	Rich	1	14.7	-5.82	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:2	31.36	2157	2.03	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.86	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:2	31.36	2159	2.03	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.91	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:2	31.36	2160	2.03	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.89	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:3	31.36	2162	2.03	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.83	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:3	31.36	2162	2.03	13.42	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.83	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:3	31.36	2163	2.03	13.43	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.81	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:3	31.36	2167	2.03	13.44	100	197	Off Idle	85.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.78	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:3	31.36	2167	2.03	13.44	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.81	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:3	31.36	2167	2.03	13.42	101	197	Off Idle	85.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.88	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:4	31.36	2178	2.04	13.42	101	197	Off Idle	85.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.9	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:4	31.36	2172	2.04	13.41	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.84	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:4	32.72	2180	2.04	13.42	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.85	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:4	32.72	2170	2.04	13.43	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.86	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:4	32.72	2173	2.04	13.43	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.87	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:4	32.72	2173	2.04	13.43	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.89	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:4	32.72	2176	2.04	13.43	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.91	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:5	32.72	2178	2.04	13.43	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.91	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:5	32.72	2178	2.04	13.42	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-5.89	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:5	31.36	2166	2.04	13.42	100	197	Off Idle	85.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.91	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:5	31.36	2181	2.04	13.4	100	197	Off Idle	85.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.9	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:5	31.36	2175	2.04	13.4	100	197	Off Idle	85.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.89	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:5	31.36	2175	2.04	13.4	100	197	Off Idle	85.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.88	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:6	31.36	2168	2.04	13.41	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.86	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:6	31.36	2163	2.04	13.42	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.87	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:6	31.36	2164	2.04	13.42	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.88	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:6	31.36	2164	2.04	13.44	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.89	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:6	31.36	2164	2.04	13.44	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.51	Lean	1	14.6	-5.89	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:6	31.36	2164	2.04	13.43	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.9	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:6	31.36	2174	2.04	13.42	100	197	Off Idle	84.9	0	2	132	944 Turbo	0.63	Lean	1	14.6	-5.89	15.19	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:7	31.36	2180	2.04	13.43	100	197	Off Idle	84.7	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.82	15.18	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:7	31.36	2180	2.04	13.42	100	197	Off Idle	84.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.81	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:7	31.36	2182	2.04	13.42	100	197	Off Idle	84.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.83	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:7	31.36	2189	2.04	13.44	100	197	Off Idle	84.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.79	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:7	31.36	2189	2.04	13.45	100	197	Off Idle	84.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.84	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:7	31.36	2188	2.04	13.42	100	197	Off Idle	84.6	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.89	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:45:8	31.36	2182	2.04	13.42	100	197	Off Idle	84.6	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.91	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:8	31.36	2182	2.04	13.42	100	197	Off Idle	84.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.9	15.02	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:8	31.36	2180	2.04	13.42	100	197	Off Idle	84.6	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.91	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:8	32.72	2189	2.04	13.43	100	197	Off Idle	84.4	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.9	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:8	32.72	2185	2.04	13.44	100	197	Off Idle	84.4	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.9	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:8	32.72	2185	2.04	13.44	100	197	Off Idle	84.2	0	2	132	944 Turbo	0.26	Lean	1	14.7	-5.91	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:9	32.72	2188	2.04	13.43	100	197	Off Idle	84.1	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.9	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:9	32.72	2188	2.04	13.43	100	197	Off Idle	83.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.89	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:9	32.72	2188	2.04	13.43	100	197	Off Idle	83.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.87	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:9	32.72	2188	2.04	13.41	100	197	Off Idle	83.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.87	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:9	32.72	2187	2.04	13.42	100	197	Off Idle	83.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.88	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:9	32.72	2190	2.04	13.42	100	197	Off Idle	83.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.89	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:45:9	32.72	2194	2.04	13.41	100	197	Off Idle	83.6	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.91	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:0	32.72	2196	2.04	13.41	100	197	Off Idle	83.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.9	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:0	32.72	2198	2.04	13.42	100	197	Off Idle	83.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.87	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:46:0	32.72	2198	2.04	13.43	100	197	Off Idle	83.5	0	2	132	944 Turbo	0.48	Rich	1	14.6	-5.89	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:0	32.72	2191	2.04	13.43	100	197	Off Idle	83.4	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.89	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:0	32.72	2186	2.04	13.43	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.89	15.19	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:0	32.72	2186	2.04	13.43	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.89	15.2	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:1	32.72	2183	2.04	13.42	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.89	15.22	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:1	32.72	2181	2.04	13.42	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.88	15.21	1.04	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:1	32.72	2182	2.04	13.43	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.89	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:1	32.72	2184	2.04	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.88	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:1	32.72	2186	2.04	13.42	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.85	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:1	32.72	2172	2.04	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.7	Lean	1	14.6	-5.85	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:1	31.36	2172	2.04	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-5.87	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:2	31.36	2194	2.04	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-5.86	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:2	31.36	2194	2.04	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-5.86	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:2	31.36	2200	2.04	13.42	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.92	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:2	31.36	2199	2.05	13.42	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.39	Lean	1	14.7	-5.94	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:2	31.36	2201	2.05	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.95	14.77	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:2	31.36	2201	2.05	13.4	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.94	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:3	32.72	2204	2.05	13.39	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.94	14.73	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:3	32.72	2207	2.05	13.38	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.93	14.73	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:3	32.72	2207	2.05	13.39	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.9	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:3	32.72	2208	2.05	13.41	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.9	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:3	32.72	2207	2.05	13.41	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.91	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:3	32.72	2207	2.05	13.41	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.92	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:4	32.72	2203	2.05	13.41	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.89	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:4	32.72	2203	2.05	13.41	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.89	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:4	32.72	2201	2.05	13.4	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.86	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:4	32.72	2200	2.05	13.41	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.82	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:4	32.72	2197	2.05	13.41	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.85	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:4	32.72	2193	2.05	13.42	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.89	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:4	32.72	2193	2.05	13.43	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.87	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:5	32.72	2196	2.05	13.43	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.89	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:5	32.72	2199	2.05	13.44	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.91	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:5	32.72	2222	2.05	13.44	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.88	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:5	32.72	2222	2.05	13.42	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.89	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:5	32.72	2211	2.05	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.92	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:5	32.72	2213	2.05	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.89	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:6	32.72	2213	2.05	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.89	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:6	32.72	2206	2.05	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.91	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:6	32.72	2215	2.05	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.91	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:6	32.72	2208	2.05	13.41	100	197	Off Idle	83	0	2	132	944 Turbo	0.54	Lean	1	14.6	-5.91	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:6	32.72	2203	2.05	13.4	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.93	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:6	32.72	2203	2.05	13.41	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.94	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:6	32.72	2198	2.05	13.43	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.88	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:7	32.72	2195	2.05	13.44	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.88	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:7	32.72	2200	2.05	13.45	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.91	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:7	32.72	2200	2.05	13.44	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.91	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:7	32.72	2204	2.05	13.43	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.91	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:7	32.72	2207	2.05	13.42	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.88	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:46:7	32.72	2212	2.05	13.41	101	197	Off Idle	82.8	0	2	132	944 Turbo	0.22	Rich	1	14.6	-5.86	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:8	32.72	2214	2.05	13.43	101	197	Off Idle	82.8	0	2	132	944 Turbo	0.27	Rich	1	14.6	-5.87	14.86	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:8	32.72	2214	2.05	13.43	101	197	Off Idle	82.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.9	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:8	32.72	2222	2.05	13.42	100	197	Off Idle	82.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-5.92	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:8	32.72	2211	2.05	13.42	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.44	Rich	1	14.6	-5.94	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:8	32.72	2211	2.05	13.42	100	197	Off Idle	82.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.93	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:8	32.72	2208	2.05	13.42	100	197	Off Idle	82.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.95	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:9	32.72	2207	2.05	13.42	100	197	Off Idle	82.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.93	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:9	32.72	2199	2.05	13.42	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.93	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:9	32.72	2208	2.05	13.42	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.95	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:46:9	32.72	2209	2.05	13.42	100	197	Off Idle	82.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.96	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:9	32.72	2202	2.05	13.42	100	197	Off Idle	82.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.95	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:9	32.72	2209	2.05	13.42	101	197	Off Idle	82.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.94	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:46:9	32.72	2207	2.05	13.43	101	197	Off Idle	81.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.95	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:0	32.72	2209	2.05	13.43	101	197	Off Idle	81.9	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.96	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:0	32.72	2209	2.05	13.42	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.96	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:0	32.72	2212	2.05	13.41	100	197	Off Idle	81.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.95	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:0	32.72	2231	2.05	13.43	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.92	14.9	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:0	32.72	2231	2.05	13.43	100	197	Off Idle	81.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.91	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:0	32.72	2211	2.05	13.41	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.35	Rich	1	14.6	-5.91	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:1	32.72	2216	2.05	13.41	101	197	Off Idle	81.6	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.9	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:1	32.72	2218	2.05	13.41	101	197	Off Idle	81.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.91	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:1	32.72	2219	2.05	13.41	101	197	Off Idle	81.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.91	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:1	32.72	2222	2.05	13.41	100	197	Off Idle	81.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.92	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:1	32.72	2221	2.05	13.41	100	197	Off Idle	81.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.89	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:1	32.72	2220	2.05	13.41	100	197	Off Idle	81.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.87	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:1	32.72	2214	2.05	13.42	100	197	Off Idle	81.4	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.87	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:2	32.72	2208	2.05	13.41	100	197	Off Idle	81.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.89	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:2	32.72	2208	2.05	13.41	100	197	Off Idle	81.4	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.87	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:2	32.72	2204	2.05	13.41	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.39	Lean	1	14.6	-5.86	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:2	32.72	2206	2.05	13.41	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.45	Rich	1	14.6	-5.89	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:2	32.72	2205	2.05	13.41	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.91	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:2	32.72	2205	2.05	13.41	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-5.89	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:3	32.72	2214	2.05	13.41	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-5.91	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:3	32.72	2213	2.05	13.41	101	197	Off Idle	82	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.94	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:3	32.72	2222	2.05	13.41	101	197	Off Idle	82.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.92	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:3	32.72	2218	2.05	13.41	101	197	Off Idle	82.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.93	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:3	32.72	2221	2.05	13.42	100	197	Off Idle	82.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.95	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:3	32.72	2222	2.05	13.43	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.99	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:4	32.72	2224	2.05	13.42	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.02	15.05	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:4	32.72	2220	2.05	13.41	100	197	Off Idle	82.7	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:4	32.72	2222	2.05	13.41	100	197	Off Idle	82.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-5.99	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:4	32.72	2222	2.05	13.41	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.95	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:4	32.72	2224	2.05	13.41	101	197	Off Idle	82.9	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.95	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:4	32.72	2207	2.05	13.42	101	197	Off Idle	82.9	0	2	132	944 Turbo	0.31	Lean	1	14.6	-5.91	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:4	32.72	2207	2.05	13.43	101	197	Off Idle	82.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.91	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:5	32.72	2226	2.05	13.44	100	197	Off Idle	82.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.92	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:5	32.72	2226	2.05	13.43	100	197	Off Idle	82.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.96	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:5	32.72	2240	2.05	13.43	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:5	32.72	2240	2.05	13.42	100	197	Off Idle	82.4	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.02	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:5	32.72	2221	2.05	13.43	100	197	Off Idle	82.2	0	2	132	944 Turbo	0.16	Rich	1	14.6	-6.02	14.89	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:5	32.72	2219	2.05	13.41	100	197	Off Idle	82.1	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.04	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:6	32.72	2216	2.05	13.4	100	197	Off Idle	82	0	2	132	944 Turbo	0.27	Rich	1	14.6	-6.02	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:6	32.72	2213	2.05	13.42	100	197	Off Idle	82	0	2	132	944 Turbo	0.33	Rich	1	14.6	-5.96	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:6	32.72	2211	2.05	13.43	100	197	Off Idle	82.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.96	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:6	32.72	2211	2.05	13.41	100	197	Off Idle	82.1	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.99	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:6	32.72	2209	2.05	13.41	100	197	Off Idle	82	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.96	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:6	32.72	2211	2.05	13.41	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-5.95	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:6	32.72	2204	2.05	13.41	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.98	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:7	32.72	2212	2.05	13.42	100	197	Off Idle	81.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.97	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:7	32.72	2214	2.05	13.42	100	197	Off Idle	81.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.93	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:7	32.72	2218	2.05	13.42	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.94	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:7	32.72	2217	2.05	13.41	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.97	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:7	32.72	2217	2.05	13.41	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.96	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:7	32.72	2215	2.05	13.4	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.92	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:8	32.72	2216	2.05	13.41	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.94	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:8	32.72	2220	2.05	13.42	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.98	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:47:8	32.72	2226	2.05	13.41	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.96	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:47:8	32.72	2226	2.05	13.42	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.99	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:8	32.72	2222	2.05	13.44	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.03	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:8	32.72	2223	2.05	13.43	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:9	32.72	2223	2.05	13.44	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.01	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:9	32.72	2232	2.05	13.43	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.03	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:9	32.72	2225	2.05	13.41	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:9	32.72	2225	2.05	13.42	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.02	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:9	32.72	2226	2.05	13.41	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.01	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:9	32.72	2225	2.05	13.4	101	197	Off Idle	81.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.95	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:47:9	32.72	2224	2.05	13.42	101	197	Off Idle	81.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.92	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:0	32.72	2222	2.05	13.42	100	197	Off Idle	81.4	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.94	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:0	32.72	2219	2.05	13.41	100	197	Off Idle	81.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.96	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:0	32.72	2219	2.05	13.41	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.95	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:0	32.72	2207	2.05	13.42	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-5.99	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:0	32.72	2214	2.05	13.41	100	197	Off Idle	82	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.02	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:0	32.72	2214	2.05	13.4	100	197	Off Idle	82	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.04	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:1	32.72	2212	2.05	13.42	100	197	Off Idle	82.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.02	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:1	32.72	2213	2.05	13.42	100	197	Off Idle	82.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.03	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:1	32.72	2212	2.05	13.43	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.07	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:1	32.72	2213	2.05	13.44	101	197	Off Idle	82.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.03	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:1	32.72	2214	2.04	13.43	101	197	Off Idle	82.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.05	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:1	32.72	2235	2.04	13.43	101	197	Off Idle	82.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.04	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:1	32.72	2215	2.04	13.43	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.06	15.03	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:48:2	32.72	2216	2.04	13.42	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.08	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:48:2	32.72	2216	2.04	13.41	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.08	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:2	32.72	2211	2.04	13.41	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.03	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:2	32.72	2202	2.04	13.41	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.02	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:2	32.72	2208	2.04	13.41	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.56	Rich	1	14.7	-6.03	14.87	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:2	32.72	2205	2.04	13.4	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.04	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:3	32.72	2206	2.04	13.41	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.03	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:3	32.72	2212	2.04	13.43	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.34	Rich	1	14.6	-6.06	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:3	32.72	2214	2.04	13.43	100	198	Off Idle	82.5	0	2	132	944 Turbo	0.29	Rich	1	14.6	-6.07	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:3	32.72	2221	2.04	13.42	100	198	Off Idle	82.4	0	2	132	944 Turbo	0.23	Rich	1	14.6	-6.08	14.81	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:3	32.72	2226	2.04	13.41	100	198	Off Idle	82.5	0	2	132	944 Turbo	0.18	Rich	1	14.6	-6.07	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:3	32.72	2232	2.04	13.41	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.1	14.82	1.01	3.4	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:4	32.72	2241	2.04	13.41	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.12	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:4	32.72	2231	2.04	13.4	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.12	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:4	32.72	2227	2.04	13.4	101	197	Off Idle	82.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.1	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:4	32.72	2224	2.04	13.42	101	197	Off Idle	82.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.12	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:4	32.72	2204	2.04	13.43	100	197	Off Idle	82.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.14	15	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:4	32.72	2206	2.04	13.42	100	197	Off Idle	82.1	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.12	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:4	32.72	2206	2.04	13.42	100	197	Off Idle	82	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.11	15.08	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:5	32.72	2205	2.04	13.41	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.07	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:5	32.72	2204	2.04	13.41	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.41	Lean	1	14.6	-6.03	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:5	32.72	2204	2.04	13.41	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.02	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:5	32.72	2208	2.04	13.4	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.02	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:5	32.72	2211	2.04	13.4	100	197	Off Idle	81.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.03	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:5	32.72	2215	2.04	13.41	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.04	15.17	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:6	32.72	2216	2.04	13.42	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.06	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:6	32.72	2240	2.04	13.42	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.11	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:6	32.72	2234	2.04	13.42	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.09	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:6	32.72	2228	2.04	13.43	100	198	Off Idle	81.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.12	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:6	32.72	2228	2.04	13.42	100	198	Off Idle	81.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.11	15.05	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:6	32.72	2226	2.04	13.4	100	198	Off Idle	81.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.12	15.01	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:6	32.72	2221	2.04	13.41	100	198	Off Idle	81.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.1	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:7	32.72	2212	2.04	13.42	100	198	Off Idle	81.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.12	14.98	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:7	32.72	2209	2.04	13.41	101	197	Off Idle	81.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.12	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:7	32.72	2203	2.04	13.4	101	197	Off Idle	81.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.13	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:48:7	32.72	2184	2.04	13.42	101	197	Off Idle	81.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.12	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:7	32.72	2192	2.04	13.43	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.09	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:7	32.72	2200	2.04	13.41	100	197	Off Idle	81.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.08	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:8	32.72	2201	2.04	13.42	100	197	Off Idle	81.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.04	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:48:8	32.72	2203	2.04	13.43	101	197	Off Idle	81.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.02	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:8	32.72	2208	2.04	13.41	101	197	Off Idle	81.9	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.1	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:8	32.72	2211	2.04	13.4	101	197	Off Idle	82.1	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.09	14.96	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:8	32.72	2210	2.04	13.4	101	197	Off Idle	82.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.04	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:8	32.72	2210	2.04	13.41	101	197	Off Idle	82.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-6.05	15.01	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:9	32.72	2212	2.04	13.41	101	197	Off Idle	82.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.04	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:9	32.72	2200	2.04	13.43	101	198	Off Idle	82.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.03	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:9	32.72	2200	2.03	13.43	100	198	Off Idle	82.7	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.07	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:9	32.72	2198	2.03	13.42	100	198	Off Idle	82.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.08	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:9	32.72	2195	2.03	13.42	100	198	Off Idle	83	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.09	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:9	32.72	2201	2.03	13.41	100	198	Off Idle	83.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.09	15.05	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:48:9	32.72	2201	2.03	13.41	100	198	Off Idle	83.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.08	15.02	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:0	32.72	2202	2.03	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.67	Lean	1	14.6	-6.09	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:0	32.72	2202	2.03	13.4	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.63	Lean	1	14.6	-6.08	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:0	32.72	2202	2.03	13.4	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.57	Lean	1	14.6	-6.07	14.95	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:0	32.72	2205	2.03	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.06	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:0	32.72	2206	2.03	13.41	100	197	Off Idle	83.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.06	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:0	32.72	2208	2.03	13.42	100	197	Off Idle	83	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.05	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:1	32.72	2210	2.03	13.42	101	198	Off Idle	82.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.07	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:1	32.72	2222	2.03	13.42	101	198	Off Idle	82.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.12	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:1	32.72	2217	2.03	13.42	101	198	Off Idle	82.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.09	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:1	32.72	2219	2.03	13.42	101	198	Off Idle	82.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.1	14.78	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:1	32.72	2222	2.03	13.42	101	198	Off Idle	82.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.08	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:1	32.72	2220	2.03	13.42	101	198	Off Idle	82.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.13	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:1	32.72	2216	2.03	13.42	101	198	Off Idle	82.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.12	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:2	32.72	2216	2.03	13.41	101	198	Off Idle	82.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.13	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:2	32.72	2214	2.03	13.43	100	198	Off Idle	82.5	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.12	14.9	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:2	32.72	2210	2.03	13.42	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.12	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:2	32.72	2204	2.03	13.43	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.11	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:2	32.72	2204	2.03	13.42	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.12	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:2	32.72	2200	2.03	13.42	100	197	Off Idle	82.5	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.12	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:3	32.72	2195	2.03	13.42	100	197	Off Idle	82.6	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.15	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:3	32.72	2194	2.03	13.41	101	197	Off Idle	82.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.14	15.11	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:3	32.72	2196	2.03	13.39	101	198	Off Idle	82.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.12	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:3	32.72	2194	2.03	13.41	101	198	Off Idle	83	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.05	15.15	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:3	32.72	2193	2.03	13.42	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.05	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:3	32.72	2190	2.03	13.42	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.02	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:4	32.72	2196	2.03	13.42	100	197	Off Idle	83.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.02	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:4	32.72	2195	2.03	13.42	100	198	Off Idle	83.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.05	14.98	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:4	32.72	2194	2.03	13.42	100	198	Off Idle	83.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.04	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:4	32.72	2192	2.03	13.43	101	198	Off Idle	83.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.07	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:4	32.72	2195	2.03	13.41	101	197	Off Idle	83.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.1	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:4	32.72	2195	2.03	13.4	101	197	Off Idle	83.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-6.09	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:4	32.72	2197	2.03	13.4	101	197	Off Idle	83.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.09	14.73	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:5	32.72	2201	2.03	13.4	101	198	Off Idle	83.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.12	14.71	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:5	32.72	2202	2.03	13.38	101	198	Off Idle	83.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.05	14.69	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:5	32.72	2202	2.03	13.41	101	198	Off Idle	83.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.03	14.68	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:5	32.72	2204	2.03	13.41	100	198	Off Idle	83.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.02	14.69	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:5	32.72	2200	2.03	13.43	100	198	Off Idle	83.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6	14.71	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:5	32.72	2200	2.03	13.43	100	198	Off Idle	83.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.03	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:6	32.72	2196	2.03	13.43	100	197	Off Idle	83	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.08	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:6	32.72	2192	2.03	13.43	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.09	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:6	32.72	2192	2.03	13.44	100	197	Off Idle	82.9	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.05	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:6	32.72	2186	2.03	13.42	100	198	Off Idle	82.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.06	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:49:6	32.72	2183	2.03	13.42	100	198	Off Idle	83.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.05	14.97	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:6	32.72	2182	2.03	13.42	100	198	Off Idle	83.1	0	2	132	944 Turbo	0.4	Rich	1	14.6	-6.07	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:6	32.72	2182	2.03	13.42	100	198	Off Idle	83.1	0	2	132	944 Turbo	0.47	Rich	1	14.6	-6.05	15.04	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:7	32.72	2183	2.03	13.41	100	198	Off Idle	83.1	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.02	15.07	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:7	32.72	2187	2.03	13.43	101	198	Off Idle	83.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:7	32.72	2188	2.03	13.43	101	198	Off Idle	83.4	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.02	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:7	32.72	2190	2.03	13.43	101	198	Off Idle	83.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.03	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:7	32.72	2192	2.03	13.42	101	198	Off Idle	83.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.06	15.13	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:7	32.72	2193	2.03	13.42	101	197	Off Idle	83.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.05	15.09	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:8	32.72	2194	2.03	13.41	101	197	Off Idle	83.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.03	15.05	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:8	31.36	2178	2.03	13.41	100	197	Off Idle	83.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.99	15.03	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:8	31.36	2193	2.03	13.42	100	198	Off Idle	83.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.98	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:8	31.36	2190	2.03	13.42	100	198	Off Idle	83.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.93	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:8	31.36	2180	2.03	13.42	100	197	Off Idle	83.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.92	14.91	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:8	31.36	2179	2.03	13.41	100	197	Off Idle	83.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.99	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:9	31.36	2177	2.03	13.41	101	197	Off Idle	83.7	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.97	14.78	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:9	31.36	2176	2.03	13.42	101	198	Off Idle	83.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.94	14.75	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:49:9	32.72	2195	2.03	13.42	101	198	Off Idle	84	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.96	14.73	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:9	32.72	2179	2.03	13.42	101	198	Off Idle	84	0	2	132	944 Turbo	0.5	Lean	1	14.6	-5.97	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:9	32.72	2179	2.03	13.42	101	197	Off Idle	83.8	0	2	132	944 Turbo	0.44	Lean	1	14.6	-5.97	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:9	32.72	2184	2.03	13.42	101	197	Off Idle	83.7	0	2	132	944 Turbo	0.38	Lean	1	14.6	-5.97	14.74	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:49:9	32.72	2188	2.03	13.41	100	197	Off Idle	83.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.97	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:0	32.72	2188	2.03	13.41	100	198	Off Idle	83.5	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.96	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:0	32.72	2190	2.03	13.41	100	198	Off Idle	83.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.93	14.77	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:0	31.36	2180	2.03	13.43	101	198	Off Idle	83.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.89	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:0	31.36	2187	2.03	13.42	101	198	Off Idle	83.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.93	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:50:0	31.36	2187	2.03	13.42	101	198	Off Idle	83.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.95	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:50:0	31.36	2181	2.03	13.41	101	198	Off Idle	83.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.96	14.86	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:1	31.36	2179	2.03	13.41	101	197	Off Idle	83.8	0	2	132	944 Turbo	0.21	Rich	1	14.6	-5.97	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:1	31.36	2174	2.03	13.43	101	197	Off Idle	84	0	2	132	944 Turbo	0.3	Rich	1	14.6	-5.97	14.92	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:1	31.36	2174	2.03	13.41	101	197	Off Idle	84	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6	14.94	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:1	32.72	2192	2.03	13.41	101	197	Off Idle	83.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:1	32.72	2181	2.03	13.41	101	197	Off Idle	83.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.99	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:1	32.72	2181	2.03	13.41	101	198	Off Idle	83.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.98	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:1	32.72	2178	2.03	13.41	101	198	Off Idle	83.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.98	15.09	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:2	32.72	2176	2.03	13.41	101	198	Off Idle	83.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.96	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:2	32.72	2176	2.03	13.41	100	197	Off Idle	83.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.94	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:2	32.72	2175	2.03	13.42	100	197	Off Idle	84.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.95	15.12	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:2	32.72	2180	2.03	13.41	100	197	Off Idle	84.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.95	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:2	32.72	2180	2.03	13.4	100	198	Off Idle	84.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.99	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:2	32.72	2176	2.03	13.41	100	198	Off Idle	84.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.97	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:3	32.72	2170	2.03	13.41	101	198	Off Idle	84.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.97	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:3	32.72	2170	2.03	13.41	101	198	Off Idle	84.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.93	14.87	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:3	32.72	2170	2.03	13.42	101	198	Off Idle	84.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.92	14.85	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:3	32.72	2160	2.03	13.43	101	198	Off Idle	84.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.92	14.8	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:3	31.36	2164	2.03	13.44	101	198	Off Idle	84.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.92	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:3	31.36	2164	2.03	13.44	101	198	Off Idle	84.9	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6	14.74	1	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:4	31.36	2160	2.03	13.42	101	198	Off Idle	85.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.02	14.73	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:4	31.36	2156	2.03	13.41	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.62	Lean	1	14.6	-6.02	14.82	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:4	31.36	2156	2.03	13.41	101	198	Off Idle	85.4	0	2	132	944 Turbo	0.57	Lean	1	14.6	-5.98	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:4	31.36	2158	2.03	13.42	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:50:4	31.36	2155	2.03	13.41	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.95	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:50:4	32.72	2162	2.03	13.41	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.43	Lean	1	14.6	-5.93	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:50:4	32.72	2157	2.02	13.41	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.92	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:5	32.72	2160	2.02	13.39	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.91	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:5	32.72	2177	2.02	13.41	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-5.89	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:5	32.72	2177	2.02	13.42	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.91	14.83	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:5	32.72	2174	2.02	13.44	100	197	Off Idle	85.6	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.96	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:50:5	32.72	2164	2.02	13.44	101	197	Off Idle	85.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:5	31.36	2171	2.02	13.42	101	197	Off Idle	85.6	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.02	14.88	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:6	31.36	2171	2.02	13.41	101	197	Off Idle	85.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.02	14.88	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:6	31.36	2166	2.02	13.41	101	197	Off Idle	85.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.01	14.9	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:6	31.36	2159	2.02	13.41	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-5.99	14.92	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:6	31.36	2156	2.02	13.41	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.97	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:6	31.36	2146	2.02	13.42	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-5.97	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:6	31.36	2142	2.02	13.42	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-5.94	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:6	31.36	2141	2.02	13.41	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.97	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:7	31.36	2141	2.02	13.4	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.95	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:7	31.36	2142	2.02	13.4	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.93	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:7	31.36	2146	2.02	13.4	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.91	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:7	31.36	2146	2.02	13.41	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.9	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:7	31.36	2148	2.02	13.43	101	198	Off Idle	85.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.91	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:50:7	31.36	2150	2.02	13.44	100	198	Off Idle	85.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.91	15.06	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:8	31.36	2151	2.02	13.44	100	198	Off Idle	85.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-5.95	15.03	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:8	31.36	2151	2.02	13.43	100	198	Off Idle	85.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.98	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:8	31.36	2150	2.02	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.99	14.97	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:8	31.36	2153	2.02	13.41	101	198	Off Idle	85.4	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.96	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:8	31.36	2153	2.02	13.42	101	198	Off Idle	85.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.95	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:8	31.36	2154	2.02	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-5.95	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:9	31.36	2153	2.02	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.95	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:9	32.72	2160	2.02	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.95	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:9	32.72	2151	2.02	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.95	14.81	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:50:9	32.72	2148	2.02	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.95	14.84	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:50:9	32.72	2147	2.02	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-5.93	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:9	32.72	2146	2.02	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.7	-5.94	14.9	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:50:9	32.72	2138	2.02	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-5.93	14.93	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:0	32.72	2137	2.02	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.91	14.96	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:0	31.36	2130	2.02	13.4	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.9	14.99	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:0	31.36	2139	2.02	13.4	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.41	Rich	1	14.6	-5.87	15.02	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:0	31.36	2136	2.02	13.42	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.47	Rich	1	14.6	-5.85	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:0	31.36	2136	2.02	13.43	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.89	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:0	31.36	2136	2.02	13.45	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.91	15.1	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:1	31.36	2129	2.01	13.42	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.61	Rich	1	14.6	-5.94	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:1	31.36	2132	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.91	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:1	31.36	2130	2.01	13.41	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.92	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:1	31.36	2114	2.01	13.41	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.91	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:1	31.36	2134	2.01	13.43	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.88	15.06	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:1	31.36	2135	2.01	13.45	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.9	15	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:1	31.36	2134	2.01	13.44	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.9	14.99	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:2	31.36	2133	2.01	13.44	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.92	14.93	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:2	31.36	2136	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.92	14.9	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:2	31.36	2136	2.01	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.66	Rich	1	14.6	-5.91	14.85	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:2	31.36	2134	2.01	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.6	Rich	1	14.6	-5.91	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:2	31.36	2134	2.01	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-5.91	14.75	1	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:2	31.36	2130	2.01	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-5.91	14.75	1	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:3	31.36	2128	2.01	13.43	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5.91	14.76	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:3	31.36	2128	2.01	13.43	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.89	14.77	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:3	31.36	2126	2.01	13.44	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.29	Lean	1	14.6	-5.95	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:3	31.36	2126	2.01	13.43	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.97	14.78	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:3	31.36	2146	2.01	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6	14.79	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:3	31.36	2138	2.01	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.92	14.79	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:4	31.36	2130	2.01	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-5.91	14.8	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:4	31.36	2130	2.01	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.23	Lean	1	14.6	-5.9	14.82	1.01	3.6	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:4	31.36	2130	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-5.91	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:4	31.36	2118	2.01	13.44	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-5.91	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:4	31.36	2123	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.39	Lean	1	14.7	-5.92	14.91	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:51:4	31.36	2119	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-5.91	14.93	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:4	31.36	2118	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.89	14.96	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:5	31.36	2115	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.86	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:5	31.36	2108	2.01	13.43	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-5.84	15.06	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:5	31.36	2108	2.01	13.45	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.88	15.11	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:5	31.36	2106	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.91	15.12	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:5	31.36	2113	2.01	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.93	15.1	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:5	31.36	2115	2.01	13.39	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.95	15.07	1.03	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:6	31.36	2116	2.01	13.38	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-5.95	15.04	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:6	31.36	2120	2.01	13.38	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.91	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:6	31.36	2124	2.01	13.39	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.9	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:6	31.36	2134	2.01	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.91	14.95	1.02	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:6	31.36	2125	2.01	13.43	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.9	14.89	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:6	31.36	2125	2.01	13.43	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.92	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:6	31.36	2120	2.01	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.99	14.76	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:7	31.36	2112	2.01	13.42	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6	14.76	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:51:7	31.36	2093	2.01	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.99	14.76	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:7	31.36	2101	2.01	13.4	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.95	14.76	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:7	31.36	2107	2.01	13.4	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.92	14.77	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:7	31.36	2108	2.01	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.51	Rich	1	14.6	-5.91	14.78	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:7	31.36	2107	2.01	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.86	14.81	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:8	31.36	2104	2.01	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.37	Lean	1	14.6	-5.83	14.82	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:8	31.36	2104	2.01	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-5.83	14.84	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:8	31.36	2108	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.82	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:8	31.36	2108	2.01	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.81	14.85	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:8	31.36	2113	2.01	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.81	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:8	31.36	2109	2.01	13.42	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.81	14.86	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:9	31.36	2110	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.83	14.89	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:9	31.36	2110	2.01	13.43	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.84	14.9	1.01	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:9	31.36	2107	2.01	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.87	14.92	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:9	31.36	2107	2.01	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.88	14.94	1.02	3.5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:29:51:9	31.36	2104	2.01	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.89	14.97	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:9	31.36	2100	2.01	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.89	14.98	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:51:9	31.36	2100	2.01	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.88	15.01	1.02	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:0	31.36	2095	2.01	13.44	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.53	Rich	1	14.6	-5.82	15.05	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:0	31.36	2088	2.01	13.45	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-5.83	15.07	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:0	31.36	2088	2.01	13.45	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.62	Rich	1	14.6	-5.82	15.08	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:0	31.36	2087	2.01	13.45	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.82	15.12	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:0	31.36	2087	2.01	13.45	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-5.81	15.11	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:0	31.36	2087	2.01	13.44	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.84	15.09	1.03	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:1	31.36	2090	2.01	13.45	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.86	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:1	31.36	2092	2.01	13.44	100	197	Off Idle	85.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-5.86	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:1	31.36	2092	2.01	13.44	101	197	Off Idle	85.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-5.89	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:1	31.36	2093	2	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-5.92	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:1	31.36	2094	2	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-5.91	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:1	31.36	2094	2	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-5.92	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:1	31.36	2094	2	13.39	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.58	Rich	1	14.6	-5.91	14.85	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:2	31.36	2095	2	13.39	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.52	Rich	1	14.6	-5.91	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:2	31.36	2093	2	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.46	Rich	1	14.6	-5.89	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:2	31.36	2088	2	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.43	Rich	1	14.6	-5.89	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:2	31.36	2088	2	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.37	Rich	1	14.6	-5.9	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:2	31.36	2087	1.99	13.42	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.91	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:2	31.36	2087	1.99	13.42	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-5.93	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:3	31.36	2087	1.99	13.43	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.01	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:3	31.36	2089	1.99	13.44	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.08	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:3	31.36	2087	1.99	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.09	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:3	31.36	2086	1.98	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.13	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:3	31.36	2081	1.98	13.4	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.14	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:52:3	31.36	2080	1.98	13.4	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.13	14.88	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:4	31.36	2080	1.97	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.12	14.9	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:52:4	31.36	2076	1.97	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.17	14.95	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:4	31.36	2074	1.97	13.42	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.19	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:4	31.36	2074	1.96	13.44	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-6.24	15.02	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:4	31.36	2072	1.96	13.44	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.3	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:4	31.36	2069	1.96	13.43	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.35	15.06	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:4	31.36	2071	1.95	13.42	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.33	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:5	31.36	2071	1.95	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.37	15.11	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:5	31.36	2069	1.94	13.39	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.36	15.12	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:5	31.36	2068	1.94	13.38	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.36	15.1	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:5	31.36	2069	1.94	13.38	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.35	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:5	31.36	2069	1.94	13.38	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.36	15.05	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:5	31.36	2072	1.93	13.39	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.37	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:6	31.36	2074	1.93	13.41	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.37	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:52:6	31.36	2074	1.93	13.41	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.51	Lean	1	14.6	-6.36	14.93	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:6	31.36	2070	1.93	13.42	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.48	Lean	1	14.6	-6.39	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:6	31.36	2069	1.93	13.42	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.41	14.83	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:6	31.36	2069	1.92	13.43	101	197	Off Idle	85.6	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.42	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:6	31.36	2068	1.92	13.43	101	197	Off Idle	85.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.42	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:6	31.36	2071	1.92	13.43	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.45	14.77	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:7	31.36	2073	1.92	13.44	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.47	14.74	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:7	31.36	2073	1.92	13.45	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.47	14.76	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:7	31.36	2074	1.92	13.45	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.46	14.78	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:7	31.36	2069	1.92	13.45	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.48	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:7	31.36	2068	1.92	13.44	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.47	14.86	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:7	31.36	2064	1.92	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.46	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:8	31.36	2060	1.92	13.41	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.47	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:8	31.36	2058	1.92	13.4	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.45	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:8	31.36	2054	1.92	13.39	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.44	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:8	31.36	2052	1.92	13.4	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.36	Lean	1	14.6	-6.4	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:8	31.36	2052	1.92	13.41	101	198	Off Idle	85.5	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.38	15.14	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:8	31.36	2052	1.92	13.42	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.45	Lean	1	14.6	-6.36	15.15	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:9	31.36	2049	1.92	13.43	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.55	Lean	1	14.6	-6.4	15.17	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:9	31.36	2051	1.92	13.44	100	198	Off Idle	85.5	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.39	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:9	31.36	2051	1.92	13.44	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.42	15.16	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:9	31.36	2043	1.92	13.44	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.37	15.18	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:9	31.36	2047	1.92	13.44	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.33	15.16	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:9	31.36	2050	1.92	13.44	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.32	15.14	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:52:9	31.36	2050	1.92	13.44	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.34	15.1	1.03	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:0	31.36	2051	1.92	13.44	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.34	15.06	1.03	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:0	31.36	2050	1.92	13.44	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.35	15.03	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:0	31.36	2051	1.92	13.44	100	198	Off Idle	85.6	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.4	14.99	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:0	31.36	2051	1.92	13.45	101	198	Off Idle	85.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.41	14.95	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:0	31.36	2040	1.92	13.45	101	198	Off Idle	85.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.43	14.91	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:0	31.36	2037	1.92	13.45	101	198	Off Idle	85.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.47	14.83	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:1	31.36	2038	1.92	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.48	14.79	1.01	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:1	31.36	2036	1.92	13.43	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.47	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:1	31.36	2033	1.92	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.47	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:1	31.36	2034	1.92	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.46	14.75	1	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:1	31.36	2036	1.92	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.42	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:1	31.36	2039	1.92	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-6.4	14.76	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:1	31.36	2040	1.92	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.36	14.77	1.01	3.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:2	31.36	2044	1.92	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.3	Rich	1	14.6	-6.34	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:2	31.36	2045	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-6.32	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:2	31.36	2047	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.29	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:2	31.36	2047	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.27	14.79	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:2	31.36	2044	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.28	14.8	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:53:2	31.36	2038	1.92	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.31	14.82	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:3	31.36	2038	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.32	14.84	1.01	3.5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:3	31.36	2032	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.32	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:3	31.36	2028	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.33	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:3	31.36	2026	1.93	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.29	14.9	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:3	31.36	2025	1.93	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.26	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:3	31.36	2022	1.93	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.25	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:4	31.36	2022	1.93	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-6.24	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:4	31.36	2016	1.93	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.6	Rich	1	14.6	-6.21	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:4	31.36	2016	1.93	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.23	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:4	31.36	2022	1.93	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.27	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:4	31.36	2022	1.93	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.29	15.13	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:4	31.36	2022	1.93	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.32	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:4	31.36	2023	1.93	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.33	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:5	31.36	2023	1.93	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.31	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:5	31.36	2023	1.93	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.28	15.01	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:5	31.36	2024	1.93	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.25	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:5	31.36	2026	1.93	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.23	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:5	31.36	2026	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.23	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:5	31.36	2029	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.27	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:6	31.36	2028	1.93	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.26	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:6	31.36	2026	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.26	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:6	31.36	2026	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.29	14.79	1.01	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:53:6	31.36	2028	1.93	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.27	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:6	31.36	2028	1.93	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.25	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:6	31.36	2027	1.93	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.3	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:6	31.36	2024	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-6.31	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:7	31.36	2022	1.93	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.33	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:7	31.36	2021	1.93	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-6.35	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:7	31.36	2021	1.93	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-6.36	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:7	31.36	2021	1.93	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.35	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:7	31.36	2021	1.93	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.36	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:7	31.36	2022	1.93	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.33	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:8	31.36	2020	1.93	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.31	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:8	31.36	2018	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.33	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:8	31.36	2017	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.3	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:53:8	31.36	2016	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.2	Rich	1	14.6	-6.3	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:8	31.36	2012	1.93	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.25	Rich	1	14.6	-6.32	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:8	31.36	2005	1.93	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.34	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:9	31.36	2005	1.93	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.35	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:9	31.36	1997	1.93	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.37	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:9	31.36	1997	1.93	13.37	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.37	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:9	31.36	1997	1.93	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.57	Rich	1	14.6	-6.37	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:9	31.36	1996	1.93	13.37	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.66	Rich	1	14.6	-6.34	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:9	31.36	1993	1.93	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.33	15.11	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:53:9	31.36	1988	1.93	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.32	15.12	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:0	31.36	1996	1.93	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.33	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:0	31.36	2003	1.93	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.33	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:0	31.36	2006	1.92	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.33	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:0	31.36	2008	1.92	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.34	15.01	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:0	31.36	2011	1.92	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.34	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:0	31.36	2012	1.92	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.34	14.94	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:1	31.36	2010	1.92	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.33	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:1	31.36	2010	1.92	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.33	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:1	31.36	2006	1.92	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.35	14.84	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:1	31.36	2002	1.92	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.35	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:1	31.36	2002	1.92	13.42	101	197	Off Idle	85.8	0	2	132	944 Turbo	0.31	Lean	1	14.6	-6.33	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:1	31.36	2001	1.92	13.43	101	197	Off Idle	85.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-6.34	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:54:1	31.36	1999	1.92	13.43	101	197	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.31	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:2	31.36	1999	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.28	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:2	31.36	2002	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.27	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:2	31.36	2001	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.27	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:2	31.36	2001	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.24	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:2	31.36	2002	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.24	14.91	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:2	31.36	2006	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.23	14.92	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:3	31.36	2008	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.21	Rich	1	14.6	-6.2	14.95	1.02	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:3	31.36	2009	1.92	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.21	14.96	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:3	31.36	2011	1.92	13.43	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.24	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:3	31.36	2014	1.92	13.43	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.25	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:3	31.36	2014	1.92	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.26	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:3	31.36	2012	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.32	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:4	31.36	2003	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.31	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:4	31.36	2003	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-6.29	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:4	31.36	1996	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.28	15.08	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:4	31.36	1996	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.31	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:4	31.36	1996	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.31	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:4	31.36	1996	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.32	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:4	31.36	1991	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.29	15.05	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:5	31.36	1989	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.3	15.02	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:5	31.36	1989	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.29	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:5	31.36	1990	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.24	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:5	31.36	1991	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.24	14.94	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:5	31.36	1994	1.92	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-6.22	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:5	31.36	1995	1.92	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.19	14.87	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:6	31.36	1996	1.92	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.59	Rich	1	14.6	-6.17	14.85	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:6	31.36	1999	1.92	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.53	Rich	1	14.6	-6.21	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:6	31.36	2000	1.92	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.23	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:6	31.36	2002	1.92	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.24	14.81	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:6	31.36	2001	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.23	14.8	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:6	31.36	2002	1.92	13.43	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.23	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:6	31.36	1998	1.92	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.23	14.78	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:7	31.36	1997	1.92	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.19	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:7	31.36	1997	1.92	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.18	14.82	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:7	31.36	2000	1.92	13.39	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.17	14.83	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:7	31.36	1999	1.92	13.39	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.19	14.86	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:7	31.36	1996	1.92	13.39	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-6.22	14.89	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:54:7	31.36	1997	1.92	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.24	Rich	1	14.6	-6.26	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:8	31.36	1998	1.92	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.33	Rich	1	14.6	-6.3	14.97	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:8	31.36	1999	1.92	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.39	Rich	1	14.6	-6.31	15	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:8	31.36	1999	1.92	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.46	Rich	1	14.6	-6.33	15.03	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:8	31.36	1998	1.92	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-6.31	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:8	31.36	1997	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.3	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:8	31.36	1996	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-6.3	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:9	31.36	1994	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.3	15.09	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:9	31.36	1992	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.31	15.1	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:9	31.36	1989	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.32	15.07	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:9	31.36	1988	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.31	15.06	1.03	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:9	31.36	1985	1.92	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.29	15.04	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:9	31.36	1992	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.29	14.99	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:54:9	31.36	1992	1.92	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.27	14.98	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:0	31.36	1996	1.92	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-6.24	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:0	31.36	1998	1.92	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.23	14.92	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:0	31.36	1998	1.92	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.23	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:0	31.36	2002	1.92	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.23	14.79	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:55:0	31.36	2001	1.92	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.22	14.77	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:55:0	31.36	2001	1.91	13.37	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.28	14.76	1.01	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:55:1	31.36	1999	1.91	13.37	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.42	Lean	1	14.6	-6.31	14.75	1	3.6	2.8	ON	28 Pin	OFF	Removed	Disabled
03:29:55:1	31.36	1996	1.91	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.37	Lean	1	14.6	-6.36	14.76	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:1	31.36	1993	1.91	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-6.39	14.77	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:1	31.36	1994	1.91	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.43	14.76	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:1	31.36	1997	1.91	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.45	14.79	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:1	31.36	2003	1.9	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.49	14.8	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:1	31.36	2002	1.9	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.53	14.81	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:2	31.36	2002	1.9	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.55	14.84	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:2	31.36	2004	1.9	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.59	14.87	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:2	31.36	2001	1.89	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.62	14.88	1.01	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:2	31.36	2001	1.89	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-6.63	14.91	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:2	31.36	2001	1.89	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-6.64	14.95	1.02	3.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:29:55:2	31.36	1996	1.89	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-6.66	14.96	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:55:3	31.36	1989	1.89	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.67	14.97	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:55:3	31.36	1987	1.88	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.67	15	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:55:3	31.36	1986	1.88	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-6.68	15.03	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:55:3	31.36	1988	1.88	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.52	Lean	1	14.6	-6.68	15.05	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:55:3	31.36	1988	1.88	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.58	Lean	1	14.6	-6.7	15.07	1.03	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:55:3	31.36	1991	1.87	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.64	Lean	1	14.6	-6.71	15.06	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:4	31.36	1994	1.87	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.68	Lean	1	14.6	-6.71	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:4	31.36	1996	1.87	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.73	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:4	31.36	1992	1.87	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.73	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:4	31.36	1992	1.87	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.73	15.09	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:4	31.36	1992	1.87	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.75	15.07	1.03	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:4	31.36	1982	1.86	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.81	15.04	1.02	3.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:55:4	31.36	1991	1.86	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.82	15	1.02	3.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:29:55:5	31.36	1991	1.86	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.85	14.97	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:5	31.36	2002	1.85	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.87	14.92	1.02	3.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:5	31.36	2004	1.85	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-6.93	14.87	1.01	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:55:5	31.36	1997	1.85	13.44	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.59	Lean	1	14.6	-6.91	14.81	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:5	31.36	1997	1.84	13.45	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.53	Lean	1	14.6	-6.92	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:5	31.36	1994	1.84	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-6.95	14.75	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:6	31.36	1990	1.84	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.4	Lean	1	14.6	-6.97	14.74	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:6	31.36	1990	1.83	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-6.98	14.72	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:6	31.36	1991	1.83	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.03	14.74	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:6	31.36	1989	1.83	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.04	14.74	1	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:6	31.36	1986	1.83	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.04	14.76	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:6	31.36	1982	1.82	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.05	14.76	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:6	31.36	1984	1.82	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.08	14.78	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:7	31.36	1986	1.81	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.12	14.8	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:7	31.36	1986	1.81	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.13	14.83	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:7	31.36	1988	1.8	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.18	14.85	1.01	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:7	31.36	1992	1.8	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.22	14.9	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:29:55:7	31.36	1992	1.79	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.27	14.93	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:55:7	31.36	1993	1.79	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.29	14.95	1.02	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:55:8	31.36	1998	1.79	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.31	14.97	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:55:8	31.36	1998	1.78	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.29	15	1.02	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:55:8	31.36	2000	1.78	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.3	15.05	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:55:8	31.36	1996	1.78	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.28	15.06	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:55:8	31.36	1993	1.77	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.28	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:55:8	31.36	1992	1.77	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.34	15.09	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:55:9	31.36	1989	1.76	13.38	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.36	15.08	1.03	3.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:29:55:9	31.36	1990	1.76	13.39	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.4	15.08	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:55:9	31.36	1990	1.75	13.39	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.44	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:55:9	31.36	1994	1.74	13.4	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.51	15.11	1.03	3.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:55:9	31.36	1995	1.73	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.6	15.09	1.03	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:55:9	31.36	1996	1.71	13.41	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.06	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:55:9	31.36	2000	1.7	13.42	100	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.04	1.02	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:56:0	31.36	2001	1.69	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.89	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:0	31.36	2000	1.68	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.95	14.96	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:0	31.36	1996	1.68	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.99	14.93	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:0	31.36	1992	1.66	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.05	14.9	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:0	31.36	1977	1.65	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.08	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:0	31.36	1977	1.65	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.09	14.78	1.01	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:1	32.72	1970	1.64	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-8.11	14.76	1.01	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:1	32.72	1947	1.63	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8.12	14.76	1.01	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:1	32.72	1947	1.62	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.11	14.75	1	3.7	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:1	32.72	1934	1.61	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.14	14.76	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:1	32.72	1927	1.6	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-8.19	14.77	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:1	32.72	1929	1.59	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.49	Lean	1	14.6	-8.21	14.78	1.01	3.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:56:1	32.72	1929	1.58	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-8.24	14.79	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:56:2	32.72	1930	1.57	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.27	14.82	1.01	3.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:56:2	32.72	1945	1.57	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.29	14.84	1.01	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:56:2	32.72	1951	1.56	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.31	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:2	32.72	1954	1.56	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.34	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:2	32.72	1961	1.56	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.38	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:2	32.72	1964	1.55	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.4	14.84	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:3	32.72	1966	1.55	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.45	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:3	32.72	1967	1.55	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.47	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:3	32.72	1966	1.54	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.51	14.82	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:3	32.72	1963	1.54	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.53	14.83	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:3	32.72	1962	1.53	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.58	14.85	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:3	32.72	1962	1.53	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.6	14.89	1.01	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:4	32.72	1962	1.53	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.61	14.92	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:4	32.72	1960	1.53	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.61	14.94	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:4	32.72	1958	1.52	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.6	15	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:4	32.72	1956	1.52	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-8.58	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:4	32.72	1951	1.51	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.57	15.11	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:4	32.72	1951	1.51	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.58	15.16	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:4	32.72	1947	1.51	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.56	15.21	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:5	32.72	1944	1.51	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.33	Lean	1	14.6	-8.54	15.22	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:5	32.72	1943	1.51	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-8.54	15.23	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:5	32.72	1943	1.51	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.3	Lean	1	14.6	-8.55	15.22	1.04	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:5	32.72	1945	1.51	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.55	15.21	1.04	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:56:5	32.72	1949	1.51	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.6	15.19	1.03	3.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:29:56:5	32.72	1950	1.51	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.68	15.16	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:6	32.72	1951	1.51	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.71	15.13	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:6	32.72	1951	1.5	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.73	15.1	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:6	32.72	1951	1.5	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.77	15.06	1.03	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:6	32.72	1949	1.5	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.79	15.04	1.02	3.6	2	ON	28 Pin	OFF	Removed	Disabled
03:29:56:6	32.72	1946	1.49	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.83	15.02	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:56:6	32.72	1937	1.49	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.85	15.01	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:56:6	32.72	1937	1.48	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.87	14.99	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:56:7	32.72	1930	1.47	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.91	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:56:7	32.72	1925	1.46	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.95	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:56:7	32.72	1921	1.45	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.99	14.98	1.02	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:56:7	32.72	1920	1.43	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.04	14.98	1.02	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:56:7	32.72	1918	1.42	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.11	14.99	1.02	3.7	1.8	ON	28 Pin	OFF	Removed	Disabled
03:29:56:7	32.72	1917	1.41	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.17	15.01	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:56:8	32.72	1914	1.4	13.38	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.25	15	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:56:8	32.72	1911	1.38	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.51	Rich	1	14.6	-9.35	15.01	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:56:8	31.36	1893	1.37	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.43	15.01	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:56:8	31.36	1899	1.36	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.64	Rich	1	14.6	-9.47	15.03	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:56:8	31.36	1903	1.34	13.44	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.7	Rich	1	14.6	-9.52	15.03	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:56:8	31.36	1898	1.32	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.57	15.04	1.02	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:56:9	31.36	1897	1.31	13.45	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.58	15.04	1.02	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:56:9	31.36	1898	1.31	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.58	15.04	1.02	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:56:9	31.36	1900	1.3	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.57	15.04	1.02	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:56:9	31.36	1899	1.28	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-9.57	15.03	1.02	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:56:9	32.72	1906	1.27	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-9.56	15.06	1.03	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:56:9	32.72	1896	1.27	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-9.57	15.07	1.03	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:56:9	32.72	1894	1.26	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-9.61	15.07	1.03	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:0	32.72	1894	1.25	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.72	Rich	1	14.6	-9.65	15.05	1.03	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:0	32.72	1894	1.25	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.67	Rich	1	14.6	-9.68	15.03	1.02	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:0	32.72	1893	1.24	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.58	Rich	1	14.6	-9.72	14.99	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:0	32.72	1893	1.24	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.55	Rich	1	14.6	-9.75	14.98	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:0	32.72	1894	1.23	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.45	Rich	1	14.6	-9.73	14.95	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:0	32.72	1895	1.23	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-9.73	14.93	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:1	32.72	1896	1.23	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-9.71	14.89	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:1	32.72	1896	1.23	13.43	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.26	Lean	1	14.6	-9.71	14.85	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:1	32.72	1897	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.72	14.81	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:1	32.72	1897	1.23	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.72	14.8	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:1	32.72	1898	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.74	14.79	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:1	32.72	1900	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.76	14.78	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:1	32.72	1899	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.77	14.77	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:2	32.72	1898	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.74	14.77	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:2	32.72	1898	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.74	14.78	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:2	32.72	1895	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.74	14.79	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:2	32.72	1895	1.23	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.72	14.8	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:2	32.72	1895	1.23	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.74	14.78	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:2	32.72	1894	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.75	14.78	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:3	32.72	1891	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.76	14.8	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:3	32.72	1890	1.23	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.73	14.83	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:3	32.72	1888	1.23	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.71	14.87	1.01	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:3	32.72	1885	1.23	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.7	14.9	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:3	32.72	1884	1.23	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.7	14.94	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:3	32.72	1884	1.23	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.72	14.97	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:4	32.72	1882	1.23	13.39	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.76	15.02	1.02	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:4	32.72	1881	1.23	13.4	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.77	15.11	1.03	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:4	32.72	1879	1.23	13.41	101	198	Off Idle	85.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.77	15.17	1.03	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:4	32.72	1875	1.23	13.41	101	198	Off Idle	85.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.75	15.19	1.03	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:4	32.72	1874	1.23	13.41	101	198	Off Idle	85.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.77	15.22	1.04	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:4	32.72	1874	1.23	13.41	101	198	Off Idle	85.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.77	15.23	1.04	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:4	32.72	1876	1.23	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.78	15.25	1.04	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:5	32.72	1876	1.22	13.41	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.13	Lean	1	14.6	-9.82	15.25	1.04	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:5	32.72	1874	1.22	13.42	101	198	Off Idle	85.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.87	15.26	1.04	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:5	32.72	1857	1.22	13.43	101	198	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.86	15.26	1.04	3.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:5	32.72	1871	1.21	13.44	101	198	Off Idle	85.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.85	15.25	1.04	3.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:29:57:5	32.72	1871	1.21	13.43	101	198	Off Idle	85.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.83	15.24	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:5	32.72	1870	1.21	13.42	101	198	Off Idle	85.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.82	15.23	1.04	3.6	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:6	32.72	1882	1.2	13.41	101	198	Off Idle	86	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.83	15.22	1.04	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:6	32.72	1874	1.2	13.41	101	198	Off Idle	86	0	2	132	944 Turbo	0.16	Lean	1	14.6	-9.85	15.2	1.04	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:6	32.72	1863	1.19	13.41	101	198	Off Idle	85.9	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.87	15.2	1.04	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:6	32.72	1858	1.19	13.42	101	198	Off Idle	86	0	2	132	944 Turbo	0.2	Lean	1	14.6	-9.92	15.17	1.03	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:6	32.72	1855	1.19	13.42	101	198	Off Idle	86	0	2	132	944 Turbo	0.23	Lean	1	14.6	-9.91	15.15	1.03	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:6	32.72	1854	1.18	13.42	101	198	Off Idle	86	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.89	15.14	1.03	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:6	32.72	1850	1.18	13.41	101	198	Off Idle	86	0	2	132	944 Turbo	0.33	Lean	1	14.6	-9.87	15.13	1.03	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:7	32.72	1846	1.18	13.4	101	198	Off Idle	86	0	2	132	944 Turbo	0.38	Lean	1	14.6	-9.87	15.11	1.03	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:7	32.72	1845	1.17	13.39	101	198	Off Idle	86.1	0	2	132	944 Turbo	0.43	Lean	1	14.6	-9.88	15.1	1.03	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:7	32.72	1829	1.17	13.4	101	198	Off Idle	86.1	0	2	132	944 Turbo	0.49	Rich	1	14.6	-9.93	15.09	1.03	3.8	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:7	32.72	1843	1.16	13.41	101	198	Off Idle	86.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-9.98	15.08	1.03	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:7	32.72	1843	1.15	13.41	101	198	Off Idle	86.1	0	2	132	944 Turbo	0.59	Rich	1	14.6	-10.03	15.06	1.03	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:7	32.72	1839	1.14	13.42	101	198	Off Idle	86.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-10.08	15.06	1.03	3.7	1.6	ON	28 Pin	OFF	Removed	Disabled
03:29:57:8	32.72	1834	1.13	13.41	101	198	Full Load	86.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-10.11	15.06	1.03	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:57:8	32.72	1823	1.12	13.42	101	198	Idle	86.1	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.17	15.06	1.03	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:57:8	32.72	1823	1.11	13.43	101	198	Idle	84.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-10.2	15.04	1.02	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:57:8	31.36	1814	1.1	13.42	101	198	Idle	82.5	0	2	132	944 Turbo	0.65	Rich	1	14.6	-10.22	15.03	1.02	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:57:8	31.36	1814	1.09	13.41	101	198	Idle	80.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-10.23	15.03	1.02	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:57:8	31.36	1814	1.09	13.4	101	198	Idle	78	0	2	132	944 Turbo	0.61	Rich	1	14.6	-10.21	15.01	1.02	3.7	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:57:9	31.36	1806	1.09	13.4	101	198	Idle	75.6	0	2	132	944 Turbo	0.58	Lean	1	14.6	-10.18	14.97	1.02	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:57:9	31.36	1804	1.1	13.4	101	198	Idle	73.1	0	2	132	944 Turbo	0.54	Lean	1	14.6	-10.09	14.97	1.02	3.8	1.5	ON	28 Pin	OFF	Removed	Disabled
03:29:57:9	31.36	1792	1.12	13.4	101	198	Idle	70.6	0	2	132	944 Turbo	0.49	Lean	1	14.6	-10	14.96	1.02	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:57:9	31.36	1774	1.13	13.4	101	198	Idle	68	0	2	132	944 Turbo	0.45	Lean	1	14.6	-9.9	14.95	1.02	3.8	1.9	ON	28 Pin	OFF	Removed	Disabled
03:29:57:9	31.36	1768	1.15	13.41	101	198	Idle	66	0	2	132	944 Turbo	0.4	Lean	1	14.6	-9.79	14.94	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:57:9	28.63	1756	1.17	13.41	101	198	Idle	62.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-9.67	14.93	1.02	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:57:9	28.63	1758	1.18	13.41	101	198	Idle	60.5	0	2	132	944 Turbo	0.32	Lean	1	14.6	-9.56	14.93	1.02	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:58:0	23.18	1775	1.2	13.41	101	198	Idle	59.1	0	2	132	944 Turbo	0.28	Lean	1	14.6	-9.45	14.94	1.02	3.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:29:58:0	23.18	1795	1.22	13.42	101	198	Idle	57.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-9.28	14.95	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:0	17.72	1804	1.23	13.42	101	198	Idle	57.8	0	2	132	944 Turbo	0.18	Lean	1	14.6	-9.23	14.99	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:0	17.72	1832	1.25	13.42	101	198	Idle	59.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.2	14.98	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:0	17.72	1862	1.27	13.43	101	198	Idle	61.5	0	2	132	944 Turbo	0.12	Lean	1	14.6	-9.26	14.96	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:0	17.72	1862	1.27	13.44	101	198	Idle	63.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-9.31	14.94	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:1	17.72	1866	1.28	13.42	101	198	Idle	66	0	2	132	944 Turbo	0.09	Lean	1	14.6	-9.43	14.92	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:1	17.72	1861	1.28	13.42	101	198	Idle	68.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-9.5	14.91	1.02	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:1	17.72	1861	1.28	13.41	101	198	Idle	70.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.55	14.9	1.01	3.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:1	17.72	1812	1.29	13.4	101	198	Idle	73.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.67	14.88	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:1	17.72	1792	1.29	13.41	101	198	Idle	75.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.74	14.87	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:1	17.72	1769	1.29	13.42	101	198	Idle	78	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.77	14.86	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:1	17.72	1769	1.29	13.42	101	198	Idle	81.4	0	2	132	944 Turbo	0.06	Lean	1	14.6	-9.83	14.85	1.01	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:2	17.72	1742	1.27	13.43	101	198	Idle	81.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-9.85	14.87	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:2	17.72	1728	1.24	13.43	100	198	Idle	83.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-9.91	14.9	1.01	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:2	17.72	1718	1.22	13.42	100	198	Idle	84.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.94	14.93	1.02	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:2	17.72	1718	1.19	13.41	101	198	Idle	84.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.93	14.96	1.02	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:2	17.72	1721	1.17	13.4	101	198	Idle	83.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-9.96	15	1.02	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:2	17.72	1731	1.14	13.41	101	198	Idle	82.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.98	15.02	1.02	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:3	17.72	1747	1.12	13.41	101	198	Idle	82.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-9.99	15.04	1.02	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:3	17.72	1756	1.11	13.42	101	198	Idle	81.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10	15.06	1.03	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:3	17.72	1783	1.09	13.42	101	198	Idle	81	0	2	132	944 Turbo	0.14	Lean	1	14.6	-10	15.1	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:3	17.72	1797	1.07	13.42	101	198	Idle	81	0	2	132	944 Turbo	0.12	Lean	1	14.6	-10.04	15.14	1.03	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:3	17.72	1801	1.05	13.41	101	198	Idle	81	0	2	132	944 Turbo	0.08	Lean	1	14.6	-10.02	15.2	1.04	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:3	17.72	1808	1.04	13.41	101	198	Idle	81	0	2	132	944 Turbo	0.05	Lean	1	14.6	-10.03	15.26	1.04	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:4	17.72	1805	1.04	13.4	101	198	Idle	81	0	2	132	944 Turbo	0.04	Lean	1	14.6	-10.03	15.31	1.04	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:4	17.72	1797	1.03	13.4	101	198	Idle	81	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.02	15.42	1.05	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:4	17.72	1797	1.03	13.41	101	198	Idle	81.3	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.02	15.5	1.06	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:4	17.72	1778	1.03	13.42	101	198	Idle	81.6	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.05	15.58	1.06	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:4	17.72	1756	1.03	13.41	101	198	Idle	82.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-10.06	15.65	1.07	3.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:4	17.72	1756	1.03	13.42	101	198	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	15.69	1.07	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:4	17.72	1741	1.03	13.43	101	198	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	15.73	1.07	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:5	17.72	1727	1.03	13.41	101	198	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.13	15.76	1.07	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:5	17.72	1715	1.03	13.41	101	198	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.12	15.77	1.07	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:5	17.72	1710	1.03	13.41	101	198	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	15.78	1.07	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:5	17.72	1701	1.03	13.4	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	15.77	1.07	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:5	17.72	1700	1.03	13.39	101	198	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	15.8	1.08	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:5	17.72	1700	1.03	13.41	101	198	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.14	15.83	1.08	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:6	17.72	1704	1.02	13.41	101	198	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.15	16	1.09	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:6	17.72	1704	1.02	13.41	101	198	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.11	16.21	1.1	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:6	17.72	1716	1.02	13.41	101	198	Idle	82.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.1	16.5	1.12	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:6	17.72	1719	1.02	13.41	101	198	Idle	82	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	16.7	1.14	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:6	17.72	1721	1.02	13.41	101	198	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	17.14	1.17	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:6	17.72	1726	1.02	13.42	101	198	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	17.59	1.2	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:6	17.72	1726	1.02	13.41	101	198	Idle	81.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	18.05	1.23	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:7	17.72	1726	1.02	13.4	101	198	Idle	81.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	18.71	1.27	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:58:7	17.72	1723	1.02	13.4	101	198	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	19.12	1.3	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:7	17.72	1713	1.02	13.4	101	198	Idle	81.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	19.3	1.31	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:7	17.72	1705	1.02	13.4	101	198	Idle	82.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	19.79	1.35	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:7	17.72	1705	1.02	13.41	101	198	Idle	82.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.06	20.02	1.36	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:7	17.72	1684	1.02	13.39	101	198	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.18	1.37	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:8	17.72	1676	1.02	13.39	101	198	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.07	20.21	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:8	17.72	1676	1.02	13.41	101	198	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:8	17.72	1670	1.02	13.41	101	198	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.23	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:8	17.72	1665	1.02	13.41	101	198	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.23	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:8	17.72	1663	1.02	13.43	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.09	20.22	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:8	17.72	1660	1.02	13.41	101	198	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:9	17.72	1660	1.02	13.4	101	198	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.22	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:9	17.72	1663	1.02	13.41	101	198	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:9	17.72	1663	1.01	13.42	101	198	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.08	20.21	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:9	17.72	1665	1.01	13.4	101	198	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.21	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:9	17.72	1669	1.01	13.41	101	198	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.21	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:9	17.72	1669	1.01	13.41	101	198	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.2	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:58:9	17.72	1670	1.01	13.41	101	198	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.21	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:0	17.72	1669	1.01	13.42	101	198	Idle	83	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.05	20.2	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:0	17.72	1666	1	13.41	100	198	Idle	83.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.21	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:0	17.72	1660	1	13.41	100	198	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.2	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:0	17.72	1660	1	13.42	100	198	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.04	20.21	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:0	17.72	1654	1	13.42	100	198	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.21	1.38	3.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:0	17.72	1651	1	13.42	100	198	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.03	20.2	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:1	17.72	1648	1	13.42	100	198	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10.02	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:1	17.72	1641	1	13.41	101	198	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.2	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:1	17.72	1637	1	13.42	101	198	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.2	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:1	17.72	1637	1	13.41	101	198	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.2	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:1	17.72	1632	1	13.41	101	198	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-10	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:1	17.72	1628	1	13.41	101	198	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:1	17.72	1628	1	13.4	101	198	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.2	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:2	17.72	1626	1	13.39	101	198	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:2	17.72	1624	1	13.4	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.2	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:2	17.72	1623	1	13.41	101	198	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.99	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:2	17.72	1622	1	13.43	101	198	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.98	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:2	17.72	1619	1	13.43	101	198	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.97	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:2	17.72	1619	1	13.42	101	198	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.95	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:3	17.72	1616	1	13.43	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.94	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:3	17.72	1613	1	13.42	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.92	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:3	17.72	1613	1	13.42	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.93	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:3	17.72	1608	1	13.42	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:3	17.72	1604	1	13.41	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:3	17.72	1598	1	13.41	101	198	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:4	17.72	1598	1	13.41	101	198	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.91	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:4	17.72	1595	1	13.41	101	198	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.89	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:4	17.72	1590	1	13.41	101	198	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:4	17.72	1589	1	13.41	101	198	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:4	17.72	1588	1	13.41	101	198	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.88	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:4	17.72	1585	1	13.42	101	198	Idle	85.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:4	17.72	1570	1	13.4	101	198	Idle	85.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:5	17.72	1570	1	13.37	101	198	Idle	85.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.87	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:5	17.72	1578	1	13.35	101	198	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:5	17.72	1578	1	13.34	101	198	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.84	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:5	17.72	1580	1	13.32	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.83	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:5	17.72	1564	0.99	13.35	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.2	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:5	17.72	1565	0.99	13.35	101	198	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.82	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:6	17.72	1565	0.99	13.36	101	198	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.8	20.2	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:6	17.72	1561	0.99	13.36	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	4	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:29:59:6	17.72	1560	0.99	13.37	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.79	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:6	17.72	1556	0.99	13.36	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.78	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:6	17.72	1556	1	13.37	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.77	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:6	17.72	1553	1	13.38	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.76	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:6	17.72	1548	1	13.37	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:7	17.72	1548	1	13.38	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:7	17.72	1546	1	13.38	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.23	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:7	17.72	1544	1	13.39	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:7	17.72	1544	1	13.37	101	198	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.23	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:7	17.72	1540	1	13.38	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:7	17.72	1537	1	13.37	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.7	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:8	17.72	1536	1	13.37	101	198	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.23	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:8	17.72	1532	1	13.37	101	198	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.72	20.22	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:8	17.72	1526	1	13.38	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:8	17.72	1526	1	13.38	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.73	20.21	1.38	4.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:8	17.72	1522	1	13.37	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.71	20.21	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:8	17.72	1518	1	13.37	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.68	20.21	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:9	17.72	1518	0.99	13.38	101	198	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.66	20.21	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:9	17.72	1514	0.99	13.38	101	198	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.64	20.21	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:9	17.72	1508	0.99	13.38	101	198	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:9	17.72	1505	0.99	13.38	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:9	17.72	1504	0.99	13.37	101	198	Idle	84.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.63	20.22	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:9	17.72	1498	0.99	13.38	101	198	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.22	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:59:9	17.72	1498	0.99	13.38	101	198	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.62	20.23	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:0	17.72	1494	0.99	13.39	101	198	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.59	20.23	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:0	17.72	1490	0.99	13.37	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:0	17.72	1485	0.99	13.37	101	198	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.55	20.23	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:0	17.72	1482	0.99	13.37	101	198	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.56	20.23	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:0	17.72	1479	0.99	13.37	101	198	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.53	20.23	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:0	17.72	1476	0.99	13.39	101	198	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.54	20.22	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:1	17.72	1469	0.99	13.38	101	198	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.52	20.22	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:1	17.72	1463	0.99	13.37	101	198	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.51	20.22	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:1	17.72	1457	0.99	13.38	101	198	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.49	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:1	17.72	1457	0.99	13.36	101	198	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.48	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:1	17.72	1440	0.99	13.35	101	198	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.45	20.22	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:1	17.72	1445	0.99	13.36	101	198	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.21	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:1	17.72	1445	0.99	13.37	101	198	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.44	20.21	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:2	17.72	1434	0.99	13.38	101	198	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.44	20.21	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:2	17.72	1434	1	13.39	101	198	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.43	20.22	1.38	4.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:2	19.09	1441	1	13.38	101	198	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.46	20.22	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:2	19.09	1424	1	13.38	101	198	Idle	83.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.45	20.21	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:2	19.09	1409	1	13.4	101	198	Idle	83.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.41	20.21	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:2	17.72	1409	1	13.38	101	198	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.37	20.21	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:3	17.72	1415	1	13.37	101	198	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.36	20.21	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:3	19.09	1421	1	13.38	101	198	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.35	20.21	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:3	19.09	1421	1	13.38	101	198	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.32	20.22	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:3	19.09	1405	1	13.36	101	198	Idle	83.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.32	20.22	1.38	4.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:3	19.09	1398	1	13.36	101	198	Idle	83.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.33	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:3	19.09	1398	1	13.38	101	198	Idle	83.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.33	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:4	19.09	1392	1	13.36	101	198	Idle	83.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.3	20.23	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:4	17.72	1375	1	13.37	101	198	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.3	20.22	1.38	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:4	17.72	1367	1	13.36	101	198	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:00:4	17.72	1367	1	13.37	101	198	Idle	83.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.25	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:00:4	17.72	1370	1	13.37	101	198	Idle	83.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	20.23	1.38	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:00:4	17.72	1363	1	13.37	101	198	Idle	84	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.19	20.23	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:30:00:4	17.72	1360	1	13.37	101	198	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.13	20.23	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:30:00:5	17.72	1356	1	13.37	101	198	Idle	84.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.23	1.38	4.3	1.5	ON	28 Pin	OFF	Removed	Disabled
03:30:00:5	17.72	1352	1	13.37	101	198	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.12	20.22	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:00:5	17.72	1346	1	13.36	101	198	Idle	84.2	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.11	20.22	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:5	17.72	1334	1	13.36	101	198	Idle	84.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.13	20.22	1.38	4.4	2	ON	28 Pin	OFF	Removed	Disabled
03:30:00:5	17.72	1326	1	13.36	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	20.23	1.38	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:30:00:5	16.36	1330	1	13.34	101	198	Idle	84.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.06	20.23	1.38	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:30:00:6	16.36	1332	1	13.33	101	198	Idle	84.5	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.07	20.22	1.38	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:30:00:6	16.36	1328	1	13.35	101	198	Idle	84.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.06	20.21	1.38	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:30:00:6	16.36	1326	1	13.35	101	198	Idle	84.8	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.08	20.21	1.38	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:30:00:6	16.36	1323	1	13.35	101	198	Idle	84.9	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.09	20.21	1.38	4.4	1.8	ON	28 Pin	OFF	Removed	Disabled
03:30:00:6	16.36	1316	1	13.37	101	198	Idle	85	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.21	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:6	16.36	1316	1	13.35	101	198	Idle	85.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.21	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:6	16.36	1301	0.99	13.36	101	198	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:7	16.36	1301	0.99	13.36	101	198	Idle	85.6	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.14	20.21	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:7	16.36	1281	0.99	13.36	101	198	Idle	86.1	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.19	20.21	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:7	16.36	1282	0.99	13.35	101	198	Idle	86.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.18	20.21	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:7	16.36	1278	0.99	13.37	101	198	Idle	86.7	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.2	20.21	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:7	16.36	1273	0.99	13.36	101	198	Idle	87	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.17	20.21	1.38	4.4	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:7	16.36	1268	0.99	13.36	101	198	Idle	87.3	0	2	132	944 Turbo	0.02	Lean	1	14.6	-9.15	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:8	16.36	1256	0.99	13.36	101	198	Idle	87.5	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.14	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:8	16.36	1250	0.98	13.37	101	198	Idle	87.7	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.12	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:8	16.36	1235	0.98	13.37	101	198	Idle	87.8	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.1	20.21	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:8	16.36	1235	0.98	13.37	101	198	Idle	88	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.12	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:8	16.36	1215	0.98	13.38	101	198	Idle	88.1	0	2	132	944 Turbo	0.03	Lean	1	14.6	-9.1	20.22	1.38	4.7	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:8	16.36	1215	0.98	13.36	101	198	Idle	88.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.09	20.23	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:9	16.36	1193	0.97	13.37	101	198	Idle	88.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.11	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:9	16.36	1192	0.97	13.37	101	198	Idle	88.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.05	20.22	1.38	4.5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:9	16.36	1176	0.97	13.37	101	198	Idle	88.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.04	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:9	16.36	1176	0.97	13.37	101	198	Idle	88.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-9.02	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:9	14.99	1174	0.96	13.36	101	198	Idle	88.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.99	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:9	14.99	1167	0.96	13.37	101	198	Idle	88.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.97	20.22	1.38	4.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:00:9	14.99	1160	0.96	13.35	101	198	Idle	88.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.94	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:0	14.99	1160	0.96	13.34	101	198	Idle	88.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.89	20.21	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:0	14.99	1163	0.95	13.35	101	198	Idle	88.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.84	20.21	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:0	14.99	1165	0.95	13.35	101	198	Idle	89.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.83	20.2	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:0	14.99	1148	0.95	13.36	101	198	Idle	89.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-8.81	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:0	14.99	1148	0.95	13.36	101	198	Idle	89.6	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.81	20.21	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:0	14.99	1136	0.95	13.36	101	198	Idle	89.9	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.8	20.2	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:1	14.99	1146	0.94	13.37	101	198	Idle	90.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.77	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:1	14.99	1146	0.94	13.37	101	198	Idle	90.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.77	20.21	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:1	14.99	1144	0.94	13.37	101	198	Idle	90.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.76	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:1	14.99	1141	0.93	13.38	101	198	Idle	91.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.68	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:1	13.63	1141	0.93	13.36	101	198	Idle	91.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.7	20.22	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:1	13.63	1131	0.93	13.36	101	198	Idle	91.9	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.67	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:1	13.63	1124	0.92	13.36	101	198	Idle	92.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.68	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:2	13.63	1117	0.92	13.38	101	198	Idle	92.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.68	20.22	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:2	13.63	1117	0.92	13.36	101	198	Idle	92.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-8.66	20.23	1.38	4.9	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:2	13.63	1102	0.91	13.38	101	198	Idle	92.9	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.68	20.23	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:2	13.63	1102	0.91	13.36	101	198	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.65	20.22	1.38	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:2	13.63	1104	0.91	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.64	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:2	13.63	1106	0.9	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.63	20.22	1.38	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:3	13.63	1092	0.9	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-8.61	20.22	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:3	13.63	1092	0.9	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.6	20.21	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:3	13.63	1093	0.89	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.6	20.21	1.38	4.5	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:3	13.63	1077	0.89	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-8.62	20.19	1.38	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:3	13.63	1077	0.89	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.6	20.14	1.37	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:3	12.27	1070	0.88	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.62	19.97	1.36	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:4	12.27	1070	0.88	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-8.62	19.82	1.35	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:4	12.27	1054	0.88	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.62	19.73	1.34	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:4	12.27	1064	0.88	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.61	19.42	1.32	4.5	2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:01:4	12.27	1064	0.87	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.57	19.19	1.31	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:4	12.27	1054	0.87	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.57	18.79	1.28	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:4	12.27	1045	0.87	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-8.51	18.51	1.26	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:4	12.27	1035	0.87	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.52	18.21	1.24	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:5	12.27	1035	0.87	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-8.48	17.94	1.22	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:5	12.27	1029	0.87	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.42	17.69	1.2	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:5	12.27	1022	0.86	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.44	17.34	1.18	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:5	12.27	1015	0.86	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-8.41	17.14	1.17	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:5	12.27	1015	0.86	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-8.43	16.95	1.15	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:5	12.27	1013	0.86	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-8.4	16.78	1.14	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:6	12.27	1014	0.86	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-8.43	16.62	1.13	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:6	10.9	1015	0.86	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.41	16.54	1.13	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:6	10.9	1015	0.86	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.42	16.37	1.12	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:6	10.9	1010	0.86	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.38	16.23	1.11	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:6	10.9	1006	0.86	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-8.41	16.1	1.1	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:6	10.9	1006	0.85	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-8.38	15.99	1.09	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:01:6	10.9	1005	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.39	15.85	1.08	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:7	10.9	1004	0.85	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.36	15.75	1.07	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:7	10.9	996	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-8.35	15.66	1.07	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:7	10.9	996	0.85	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.35	Rich	1	14.6	-8.33	15.57	1.06	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:7	10.9	995	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-8.32	15.49	1.06	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:7	10.9	985	0.85	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-8.3	15.43	1.05	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:7	10.9	985	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-8.3	15.39	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:8	10.9	985	0.85	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-8.29	15.35	1.05	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:8	10.9	978	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.27	15.32	1.04	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:8	10.9	999	0.85	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.26	15.26	1.04	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:8	9.54	999	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-8.21	15.23	1.04	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:8	9.54	994	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-8.24	15.2	1.04	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:8	9.54	990	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.2	15.19	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:9	9.54	990	0.85	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.19	15.18	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:9	9.54	1001	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-8.15	15.15	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:9	9.54	983	0.85	13.35	100	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-8.17	15.14	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:9	9.54	983	0.85	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-8.11	15.11	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:9	9.54	980	0.85	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-8.16	15.11	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:9	9.54	978	0.85	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-8.12	15.09	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:01:9	9.54	979	0.85	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-8.15	15.08	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:0	9.54	979	0.85	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-8.14	15.07	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:0	8.18	975	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-8.12	15.07	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:0	8.18	971	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-8.12	15.07	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:0	8.18	973	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-8.12	15.08	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:0	8.18	973	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-8.09	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:0	6.81	956	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-8.09	15.07	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:1	6.81	956	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-8.03	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:1	6.81	956	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-8.02	15.1	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:1	6.81	955	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-8	15.11	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:1	8.18	955	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-8.01	15.11	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:1	8.18	960	0.84	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-8.01	15.12	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:1	8.18	948	0.84	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-8	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:1	8.18	948	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-8.01	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:2	8.18	946	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-8.04	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:2	8.18	944	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.99	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:2	8.18	945	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.98	15.13	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:2	8.18	945	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.92	15.14	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:2	8.18	944	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.89	15.14	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:2	8.18	944	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.92	15.14	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:3	8.18	945	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.91	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:3	8.18	945	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.89	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:3	6.81	939	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.91	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:02:3	6.81	933	0.84	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.89	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:3	6.81	938	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:3	6.81	938	0.84	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.85	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:4	6.81	936	0.84	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:4	6.81	936	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.86	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:4	6.81	928	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:4	6.81	928	0.84	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.86	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:4	6.81	924	0.84	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.86	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:4	6.81	924	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.88	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:4	6.81	928	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:5	6.81	932	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:5	8.18	925	0.84	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.85	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:5	8.18	925	0.84	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:5	8.18	925	0.84	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:5	8.18	925	0.84	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:5	9.54	923	0.84	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	14.98	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:6	9.54	923	0.84	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:6	9.54	927	0.84	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:6	9.54	927	0.84	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:6	9.54	936	0.84	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:6	9.54	944	0.84	13.37	100	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:6	9.54	944	0.84	13.36	100	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.9	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:6	9.54	935	0.83	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.89	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:7	8.18	942	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:7	8.18	942	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:7	8.18	942	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:7	8.18	942	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:7	8.18	937	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:7	8.18	937	0.83	13.38	101	198	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:8	8.18	930	0.83	13.38	100	198	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.82	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:8	8.18	924	0.83	13.38	100	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.78	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:8	8.18	931	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.8	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:8	8.18	931	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.75	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:8	8.18	922	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.77	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:02:8	8.18	914	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.72	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:9	8.18	914	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.76	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:9	6.81	916	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.71	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:9	6.81	929	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.77	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:9	6.81	929	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.73	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:9	8.18	924	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.78	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:9	8.18	919	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.75	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:02:9	8.18	919	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.77	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:0	8.18	903	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:0	8.18	908	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.75	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:0	8.18	914	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:0	8.18	914	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:0	8.18	906	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:0	8.18	906	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:1	8.18	914	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:1	8.18	922	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:1	8.18	917	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:1	8.18	917	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:1	8.18	916	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:1	6.81	915	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:1	6.81	918	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:2	6.81	918	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:2	8.18	911	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	14.8	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:2	8.18	911	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:03:2	8.18	911	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.8	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:2	8.18	913	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:2	8.18	920	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:3	8.18	920	0.83	13.38	101	198	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:3	8.18	924	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:3	8.18	924	0.83	13.38	101	198	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:3	8.18	924	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:3	8.18	906	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.62	14.99	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:3	8.18	904	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:4	8.18	904	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.64	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:4	8.18	904	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.67	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:4	8.18	929	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.65	15.13	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:4	8.18	902	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	15.16	1.03	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:4	8.18	902	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	15.18	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:4	8.18	911	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	15.18	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:4	8.18	920	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.69	15.2	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:5	8.18	920	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.69	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:5	8.18	910	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.66	15.23	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:5	8.18	910	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.69	15.22	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:5	6.81	907	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.67	15.22	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:5	6.81	904	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.67	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:5	6.81	920	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.64	15.22	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:6	6.81	920	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.66	15.22	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:6	9.54	920	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.66	15.22	1.04	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:6	9.54	920	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.69	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:6	9.54	918	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.69	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:6	9.54	917	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.68	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:6	9.54	919	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.69	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:6	9.54	919	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.67	15.22	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:7	9.54	910	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.69	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:7	9.54	910	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.64	15.2	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:7	9.54	910	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.68	15.19	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:7	8.18	935	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.69	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:7	8.18	924	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.69	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:7	8.18	924	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.71	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:8	8.18	924	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:8	8.18	923	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:8	8.18	925	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:8	8.18	925	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:8	8.18	919	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:8	8.18	919	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.72	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:9	8.18	919	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.75	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:9	8.18	922	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.69	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:9	9.54	914	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.72	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:9	9.54	914	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.68	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:9	9.54	914	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:9	9.54	908	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.67	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:03:9	9.54	917	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.7	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:0	8.18	917	0.83	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.63	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:0	8.18	920	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:0	8.18	924	0.83	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.64	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:0	8.18	924	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.68	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:0	6.81	923	0.83	13.35	101	198	Idle	93.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.64	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:0	6.81	928	0.83	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.71	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:1	6.81	932	0.83	13.34	101	198	Idle	93.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:1	6.81	932	0.83	13.35	101	198	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:1	6.81	930	0.83	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.71	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:1	6.81	930	0.83	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:04:1	6.81	938	0.83	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.7	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:1	6.81	938	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:1	6.81	925	0.83	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:2	6.81	925	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:2	6.81	923	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.73	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:2	6.81	923	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:2	8.18	926	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.72	14.95	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:2	8.18	930	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:2	8.18	918	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.72	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:3	8.18	933	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:3	9.54	933	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.72	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:3	9.54	933	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.75	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:3	9.54	914	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.72	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:3	9.54	914	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:3	8.18	923	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.74	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:4	8.18	923	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.73	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:4	8.18	931	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:4	8.18	931	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.72	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:4	9.54	921	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:4	9.54	921	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.72	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:4	9.54	914	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.74	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:4	9.54	908	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.69	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:5	8.18	928	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.72	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:5	8.18	928	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.73	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:5	8.18	928	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.73	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:5	8.18	927	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.75	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:5	9.54	934	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:5	9.54	934	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.73	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:6	9.54	934	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.76	15.06	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:6	9.54	934	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:6	9.54	930	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:6	9.54	930	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	15.05	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:6	9.54	927	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.04	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:6	9.54	924	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:6	8.18	924	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:7	8.18	940	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:7	8.18	935	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:7	8.18	935	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:7	8.18	924	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:7	8.18	914	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:7	8.18	923	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:8	8.18	923	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:8	8.18	923	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:8	6.81	920	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:8	6.81	920	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:8	6.81	922	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.72	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:8	6.81	912	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:9	6.81	902	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:9	6.81	902	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:9	6.81	914	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:9	6.81	914	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:9	8.18	910	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.69	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:9	8.18	907	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:04:9	8.18	908	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:0	8.18	903	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.72	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:0	8.18	903	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:0	8.18	903	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.72	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:0	8.18	900	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.71	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:05:0	8.18	900	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.7	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:0	8.18	900	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.68	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:1	8.18	900	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.67	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:1	8.18	893	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.68	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:1	8.18	893	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.62	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:1	8.18	889	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.68	14.87	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:1	8.18	885	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.6	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:1	8.18	878	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.62	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:1	8.18	878	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.59	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:2	8.18	888	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.61	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:2	8.18	899	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.58	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:2	8.18	899	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.6	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:2	8.18	898	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.58	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:2	8.18	898	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.6	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:2	8.18	900	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.56	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:3	8.18	902	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:3	8.18	909	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.56	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:3	8.18	923	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.59	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:3	8.18	923	0.83	13.34	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:3	8.18	923	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.62	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:3	8.18	918	0.83	13.34	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.6	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:4	8.18	918	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.61	14.82	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:4	6.81	918	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.6	14.8	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:4	6.81	914	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.63	14.8	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:4	6.81	931	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.62	14.8	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:05:4	6.81	931	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.65	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:4	6.81	926	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.64	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:4	6.81	921	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.62	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:5	6.81	928	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-7.65	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:5	6.81	935	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.62	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:5	6.81	918	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.62	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:5	6.81	918	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.67	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:5	6.81	925	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.66	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:5	6.81	932	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.65	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:6	6.81	916	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:6	8.18	916	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.67	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:6	8.18	922	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:6	8.18	928	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:6	9.54	918	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:6	9.54	918	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:6	9.54	918	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:7	9.54	917	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:7	9.54	917	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:7	9.54	941	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:7	9.54	923	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:7	9.54	923	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:7	9.54	920	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:8	8.18	916	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:8	8.18	916	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:8	8.18	929	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.64	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:8	8.18	929	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:8	9.54	922	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:8	9.54	916	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:9	9.54	915	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.67	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:9	9.54	900	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.69	15.05	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:9	8.18	900	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.67	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:9	8.18	900	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.68	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:9	8.18	926	0.83	13.34	101	198	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.67	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:05:9	8.18	926	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.67	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:05:9	8.18	918	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.63	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:0	8.18	918	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:0	8.18	924	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.66	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:0	8.18	924	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:0	8.18	927	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.68	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:0	8.18	927	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.7	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:0	8.18	921	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:1	8.18	915	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:1	8.18	934	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:1	8.18	934	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:1	8.18	927	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:1	8.18	920	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:1	6.81	926	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:1	6.81	926	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:2	6.81	926	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.73	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:2	6.81	926	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:2	6.81	923	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:2	6.81	923	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:2	6.81	926	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.76	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:2	6.81	929	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:3	6.81	919	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.77	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:3	8.18	919	0.83	13.34	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:3	8.18	922	0.83	13.34	101	198	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:3	8.18	924	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:3	8.18	924	0.83	13.35	101	198	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:3	8.18	924	0.83	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.89	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:4	8.18	954	0.83	13.35	101	199	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.71	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:4	8.18	954	0.83	13.37	101	199	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.7	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:4	8.18	954	0.83	13.35	101	198	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.73	14.94	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:4	8.18	916	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.69	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:4	8.18	928	0.83	13.37	101	198	Idle	93.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:4	8.18	928	0.83	13.35	101	198	Idle	93.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.69	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:4	8.18	928	0.83	13.36	101	198	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.72	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:5	9.54	936	0.83	13.34	101	198	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.67	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:5	9.54	925	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.75	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:5	9.54	925	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.71	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:5	9.54	925	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.74	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:5	8.18	935	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.7	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:5	8.18	936	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.75	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:6	8.18	936	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.73	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:6	8.18	938	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.78	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:6	9.54	949	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:6	9.54	927	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.84	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:6	9.54	927	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:6	9.54	934	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:6	8.18	942	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.78	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:7	8.18	942	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:7	8.18	934	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:7	8.18	934	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:7	8.18	932	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.69	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:7	8.18	930	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:7	8.18	923	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:8	8.18	922	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:8	8.18	922	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.74	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:8	8.18	922	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:8	8.18	924	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:8	8.18	924	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:06:8	9.54	925	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:9	9.54	926	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:9	9.54	920	0.83	13.34	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:9	9.54	920	0.83	13.36	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.73	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:9	8.18	906	0.83	13.35	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.74	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:9	8.18	906	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:9	8.18	916	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:06:9	8.18	916	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:0	6.81	919	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:0	6.81	919	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:0	6.81	911	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.73	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:0	6.81	911	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.7	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:0	8.18	924	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:0	8.18	924	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:1	8.18	918	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.71	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:1	8.18	918	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:1	6.81	920	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.7	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:1	6.81	921	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:1	6.81	920	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.71	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:1	6.81	920	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.69	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:1	6.81	915	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:2	6.81	915	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.71	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:2	6.81	915	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.75	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:2	6.81	922	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:2	6.81	912	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:2	6.81	902	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:2	6.81	902	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:3	6.81	918	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:3	6.81	912	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:3	8.18	906	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:3	8.18	906	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:3	8.18	896	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:3	8.18	896	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:4	8.18	906	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:4	8.18	916	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:4	8.18	913	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.64	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:4	8.18	914	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.69	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:4	8.18	914	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.67	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:4	8.18	914	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.66	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:4	8.18	917	0.83	13.38	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:5	8.18	917	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:5	8.18	917	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:5	8.18	917	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.69	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:5	8.18	922	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:5	8.18	928	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:5	8.18	911	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.69	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:6	8.18	911	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.7	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:6	8.18	912	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.72	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:6	8.18	914	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.67	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:6	8.18	911	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.69	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:6	8.18	911	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.69	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:6	8.18	920	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.69	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:6	8.18	929	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.69	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:7	8.18	919	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.69	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:7	8.18	919	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.65	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:7	8.18	919	0.83	13.37	101	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:7	8.18	918	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.68	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:7	8.18	918	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.7	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:07:7	9.54	918	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.69	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:8	9.54	922	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.71	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:8	9.54	927	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.65	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:8	9.54	927	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.69	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:8	9.54	935	0.83	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:8	9.54	942	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.72	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:8	9.54	942	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:9	9.54	944	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.74	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:9	8.18	946	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:9	8.18	946	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:9	8.18	943	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:9	8.18	934	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:9	8.18	934	0.83	13.42	101	198	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:07:9	8.18	937	0.83	13.42	101	198	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:0	8.18	940	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:0	8.18	940	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:0	8.18	933	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:0	8.18	938	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.77	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:0	8.18	938	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.74	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:0	8.18	943	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.79	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:1	8.18	941	0.83	13.43	101	198	Idle	93.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.72	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:1	8.18	941	0.83	13.42	101	198	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.76	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:1	8.18	940	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.73	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:1	8.18	940	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.76	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:1	8.18	943	0.83	13.39	101	198	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:1	8.18	938	0.83	13.39	101	198	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.76	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:1	8.18	934	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.76	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:2	8.18	934	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.79	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:2	8.18	942	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.77	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:2	8.18	940	0.83	13.43	101	198	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.82	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:2	8.18	938	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:2	8.18	938	0.83	13.42	101	198	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.83	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:2	9.54	942	0.83	13.39	101	198	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.77	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:3	9.54	936	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.81	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:3	9.54	936	0.83	13.39	101	198	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.76	15.07	1.03	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:3	8.18	944	0.83	13.4	101	198	Idle	93.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.79	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:3	8.18	951	0.83	13.4	101	198	Idle	93.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.76	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:3	8.18	951	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.79	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:3	8.18	949	0.83	13.4	101	198	Idle	93.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.75	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:4	8.18	951	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.81	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:4	8.18	951	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.81	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:4	8.18	953	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.83	15.07	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:4	8.18	949	0.83	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.79	15.07	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:4	8.18	956	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.85	15.07	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:4	8.18	956	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.79	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:4	8.18	948	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.82	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:5	8.18	939	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.78	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:5	8.18	939	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.82	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:5	8.18	954	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.78	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:5	8.18	948	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:5	8.18	941	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:5	8.18	941	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.85	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:6	8.18	948	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:6	8.18	936	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.87	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:6	8.18	936	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.04	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:6	8.18	936	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.83	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:6	8.18	936	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:6	8.18	936	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:08:6	8.18	933	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:7	8.18	928	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:7	8.18	928	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:7	8.18	922	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:08:7	8.18	909	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:7	8.18	923	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:7	9.54	923	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:8	9.54	923	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:8	9.54	918	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.77	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:8	9.54	918	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:8	8.18	919	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.75	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:8	8.18	919	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.75	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:8	8.18	917	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.75	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:9	8.18	917	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.73	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:9	8.18	929	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.73	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:9	8.18	929	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.76	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:9	8.18	928	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.78	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:9	8.18	927	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.77	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:9	8.18	930	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.79	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:08:9	8.18	930	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.79	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:0	8.18	924	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.8	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:0	8.18	919	0.83	13.43	101	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.78	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:0	6.81	922	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.76	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:0	6.81	922	0.83	13.43	101	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.75	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:0	6.81	923	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:0	6.81	923	0.83	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.73	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:1	8.18	923	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:1	8.18	905	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:1	8.18	908	0.82	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:1	8.18	908	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:1	8.18	912	0.82	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:1	8.18	917	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.7	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:1	8.18	917	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.73	14.82	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:2	8.18	906	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:2	8.18	904	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.72	14.81	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:2	6.81	902	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.67	14.8	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:2	6.81	902	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	14.81	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:2	6.81	918	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.68	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:2	6.81	918	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.7	14.82	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:3	9.54	916	0.82	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.68	14.84	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:3	9.54	913	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.72	14.85	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:3	9.54	907	0.82	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.66	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:3	9.54	907	0.82	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.68	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:3	9.54	913	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.64	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:3	9.54	919	0.82	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.65	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:4	9.54	922	0.82	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.64	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:4	9.54	922	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.64	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:4	9.54	922	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.65	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:4	9.54	923	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:4	9.54	926	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:4	9.54	926	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.7	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:4	9.54	928	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:5	9.54	930	0.82	13.43	101	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.68	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:5	9.54	912	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.66	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:5	9.54	912	0.82	13.43	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:5	8.18	919	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.66	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:5	8.18	926	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:5	8.18	926	0.82	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:09:6	8.18	931	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.69	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:6	9.54	923	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:6	9.54	923	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:6	9.54	900	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:6	9.54	900	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:6	6.81	914	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:6	6.81	914	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:7	6.81	914	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:7	6.81	905	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:7	6.81	890	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:7	8.18	890	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.67	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:7	8.18	887	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:7	8.18	884	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:8	8.18	884	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:8	8.18	882	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.61	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:8	8.18	882	0.82	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.61	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:09:8	8.18	880	0.82	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:8	8.18	878	0.82	13.4	101	198	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.58	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:8	9.54	873	0.82	13.38	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:9	9.54	873	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.57	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:9	9.54	878	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.58	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:9	9.54	883	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.55	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:9	9.54	883	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.54	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:9	9.54	883	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.54	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:9	9.54	876	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.55	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:09:9	9.54	868	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.54	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:0	9.54	874	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.55	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:0	8.18	874	0.82	13.4	101	198	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.54	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:0	8.18	876	0.82	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.57	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:0	8.18	877	0.82	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.53	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:0	8.18	877	0.82	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.55	14.83	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:0	8.18	883	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.5	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:1	8.18	883	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.51	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:1	8.18	893	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.49	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:1	8.18	903	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.5	14.84	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:1	9.54	876	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.51	14.83	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:1	9.54	876	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.5	14.83	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:1	9.54	876	0.82	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.51	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:1	9.54	885	0.82	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.48	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:2	6.81	889	0.82	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.51	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:2	6.81	889	0.82	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.47	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:2	6.81	889	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.51	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:2	6.81	909	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.48	14.84	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:2	6.81	886	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.52	14.83	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:2	8.18	886	0.82	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.49	14.83	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:3	8.18	886	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.54	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:3	8.18	894	0.82	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.52	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:3	8.18	894	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.54	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:3	8.18	902	0.82	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.52	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:3	8.18	902	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.56	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:3	8.18	898	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.53	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:4	8.18	894	0.82	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.56	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:4	9.54	904	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.57	14.81	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:4	9.54	904	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.56	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:4	9.54	904	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.54	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:4	9.54	911	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.58	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:4	9.54	917	0.82	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.55	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:4	9.54	917	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:10:5	9.54	909	0.82	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.59	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:5	9.54	901	0.82	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.9	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:5	9.54	913	0.82	13.39	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:5	8.18	913	0.82	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.59	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:5	8.18	917	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.63	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:5	8.18	921	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:6	8.18	921	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.62	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:6	6.81	903	0.82	13.42	101	198	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.59	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:6	6.81	910	0.82	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:6	6.81	918	0.82	13.42	101	198	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.63	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:10:6	6.81	918	0.82	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.65	14.96	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:10:6	8.18	902	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.6	14.96	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:10:6	8.18	892	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.65	14.95	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:10:7	8.18	881	0.82	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.58	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:7	8.18	881	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.6	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:7	8.18	887	0.82	13.38	101	199	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.6	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:7	8.18	887	0.82	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.6	14.98	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:10:7	8.18	884	0.82	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.58	14.98	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:7	8.18	882	0.82	13.4	101	198	Idle	93.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.58	14.99	1.02	5.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:8	10.9	866	0.82	13.39	101	198	Idle	93.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.57	14.98	1.02	5.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:8	10.9	866	0.82	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.55	14.98	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:8	10.9	866	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.54	14.97	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:8	10.9	857	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.51	14.97	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:8	10.9	863	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.49	14.95	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:8	10.9	863	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.48	14.92	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:9	10.9	863	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.52	14.9	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:9	10.9	861	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.48	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:9	10.9	861	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.52	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:9	10.9	860	0.82	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.49	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:9	10.9	858	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.5	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:9	10.9	867	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.49	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:10:9	10.9	867	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.49	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:0	10.9	876	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.51	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:0	10.9	885	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.48	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:0	10.9	885	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.51	14.85	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:0	10.9	873	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.49	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:0	10.9	880	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.49	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:0	8.18	888	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.44	14.85	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:1	8.18	888	0.82	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.49	14.85	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:1	8.18	916	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.45	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:1	8.18	899	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.51	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:1	8.18	899	0.82	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.51	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:1	8.18	899	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.56	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:1	8.18	902	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.54	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:1	8.18	902	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.58	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:2	8.18	893	0.82	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.53	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:2	8.18	893	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.55	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:2	8.18	893	0.82	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.55	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:2	8.18	893	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.56	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:2	9.54	921	0.82	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.54	14.94	1.02	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:2	9.54	921	0.82	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.52	15	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:3	9.54	912	0.82	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	15.03	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:3	9.54	903	0.82	13.42	101	198	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.57	15.06	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:3	8.18	915	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	15.08	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:3	8.18	915	0.82	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.57	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:3	8.18	914	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.61	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:3	8.18	914	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.58	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:4	8.18	914	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.6	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:11:4	8.18	918	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.58	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:4	8.18	910	0.82	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.6	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:4	8.18	901	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.57	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:4	8.18	901	0.82	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.6	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:4	8.18	920	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.56	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:4	8.18	920	0.82	13.43	101	199	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.58	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:5	8.18	902	0.82	13.42	101	198	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.55	15.15	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:5	8.18	902	0.82	13.43	101	198	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.58	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:5	8.18	912	0.82	13.41	101	198	Idle	93.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.54	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:5	8.18	912	0.82	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.57	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:5	8.18	922	0.82	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.57	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:5	8.18	922	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.6	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:6	8.18	907	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.58	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:6	8.18	907	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.6	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:6	8.18	912	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.56	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:6	8.18	912	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.61	15.13	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:6	8.18	912	0.83	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.58	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:6	8.18	912	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.59	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:6	8.18	917	0.83	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.59	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:7	8.18	917	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.59	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:7	8.18	898	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.57	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:7	8.18	898	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.6	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:7	8.18	909	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.58	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:7	8.18	909	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.57	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:7	8.18	915	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.63	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:8	8.18	921	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.6	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:8	8.18	907	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.62	15.03	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:8	8.18	907	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.6	15.02	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:8	6.81	907	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.63	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:8	6.81	902	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.58	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:8	6.81	902	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.64	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:11:9	6.81	914	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.61	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:9	6.81	915	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.61	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:9	9.54	915	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.59	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:9	9.54	915	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.63	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:9	9.54	905	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.6	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:9	9.54	917	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.65	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:11:9	8.18	917	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.62	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:12:0	8.18	917	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.66	14.93	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:12:0	8.18	930	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.92	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:0	8.18	929	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.92	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:0	8.18	929	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:0	8.18	929	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:0	8.18	931	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:1	8.18	938	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.71	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:1	9.54	938	0.83	13.4	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:1	9.54	938	0.83	13.41	101	198	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.72	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:1	9.54	938	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:1	9.54	931	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:1	8.18	947	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.68	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:1	8.18	946	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:2	8.18	946	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:2	8.18	946	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.71	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:2	8.18	938	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.7	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:2	8.18	940	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.77	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:2	8.18	940	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.75	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:2	8.18	944	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.79	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:3	8.18	948	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.74	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:12:3	8.18	948	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.77	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:3	8.18	951	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.73	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:3	8.18	951	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.76	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:3	8.18	951	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.74	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:3	8.18	951	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:4	8.18	953	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	15.1	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:4	8.18	953	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.79	15.11	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:4	6.81	948	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	15.11	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:4	6.81	954	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	15.09	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:4	6.81	959	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15.1	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:4	6.81	959	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	15.11	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:4	8.18	963	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	15.11	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:5	8.18	963	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	15.11	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:5	8.18	960	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.11	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:5	8.18	956	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	15.1	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:5	8.18	960	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.09	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:5	8.18	948	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.86	15.08	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:5	8.18	948	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	15.06	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:6	8.18	952	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.85	15.05	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:6	8.18	955	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.83	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:6	8.18	931	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.86	15.01	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:12:6	8.18	931	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:6	8.18	933	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.88	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:6	8.18	935	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:6	8.18	935	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.86	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:7	8.18	932	0.83	13.38	101	199	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:7	8.18	932	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.84	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:7	8.18	929	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.82	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:7	8.18	926	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.85	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:7	8.18	922	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.8	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:7	8.18	917	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.84	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:8	8.18	917	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:8	8.18	920	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:8	8.18	924	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.78	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:8	8.18	909	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.8	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:8	9.54	909	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.78	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:8	9.54	909	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.79	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:9	9.54	909	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.78	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:9	9.54	920	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.79	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:9	8.18	917	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.76	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:9	8.18	917	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.75	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:9	8.18	940	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.77	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:9	8.18	940	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.73	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:12:9	9.54	934	0.83	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.78	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:0	9.54	927	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.75	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:0	9.54	931	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.75	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:0	9.54	931	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.77	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:0	8.18	938	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.76	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:0	8.18	946	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.73	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:0	8.18	946	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.79	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:1	8.18	946	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.75	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:1	8.18	941	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.79	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:1	8.18	941	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.79	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:1	8.18	940	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.79	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:1	8.18	940	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.82	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:1	8.18	942	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.81	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:1	8.18	942	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.81	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:2	8.18	945	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.79	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:13:2	8.18	945	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.79	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:2	8.18	945	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.8	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:2	8.18	945	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.79	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:2	8.18	952	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.8	14.86	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:2	8.18	952	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.88	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:3	6.81	954	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.8	14.91	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:3	6.81	954	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.82	14.92	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:3	6.81	959	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.85	14.92	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:3	6.81	959	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.84	14.94	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:3	6.81	946	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.88	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:3	6.81	946	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.85	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:4	6.81	937	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.85	14.91	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:4	6.81	937	0.83	13.43	101	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	14.91	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:4	6.81	929	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	14.91	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:4	6.81	929	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	14.92	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:13:4	6.81	927	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:4	6.81	925	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:4	6.81	919	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:5	6.81	919	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.82	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:5	6.81	916	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:5	6.81	914	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:5	8.18	939	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:5	8.18	939	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:5	8.18	930	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:6	8.18	921	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:6	8.18	912	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:6	8.18	912	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:6	8.18	924	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:6	8.18	936	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:6	9.54	928	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:6	9.54	920	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:7	9.54	924	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:7	9.54	924	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:7	9.54	933	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:7	6.81	933	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:7	6.81	928	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:7	6.81	922	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.75	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:8	6.81	922	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.8	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:8	6.81	922	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:8	6.81	920	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:8	6.81	920	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:8	6.81	920	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:8	8.18	931	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.77	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:9	8.18	915	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.79	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:9	8.18	915	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.73	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:9	8.18	924	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.77	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:9	8.18	934	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.74	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:9	8.18	934	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.73	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:9	8.18	927	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.73	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:13:9	8.18	927	0.83	13.43	101	199	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.76	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:0	8.18	928	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.73	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:0	8.18	929	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.8	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:0	8.18	935	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.75	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:0	8.18	935	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.79	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:0	9.54	948	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.76	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:0	9.54	942	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.78	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:1	9.54	936	0.83	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.74	14.89	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:1	9.54	936	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.77	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:14:1	8.18	937	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.76	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:1	8.18	937	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.83	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:1	8.18	935	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.78	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:1	8.18	933	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.82	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:1	9.54	940	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.78	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:2	9.54	923	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.8	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:2	9.54	923	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.75	14.83	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:2	9.54	923	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.78	14.82	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:2	9.54	931	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.75	14.82	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:2	9.54	931	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.77	14.82	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:14:2	9.54	926	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:3	9.54	925	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:3	9.54	924	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:3	9.54	924	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:3	9.54	923	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:3	9.54	923	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:3	8.18	926	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.75	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:4	8.18	928	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:4	8.18	921	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:4	8.18	921	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.77	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:4	8.18	913	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.79	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:4	8.18	913	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.76	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:4	8.18	916	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.77	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:4	8.18	919	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.76	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:5	8.18	919	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.76	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:5	9.54	901	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.74	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:5	9.54	902	0.83	13.42	101	199	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.75	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:5	9.54	902	0.83	13.43	101	199	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.73	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:5	9.54	900	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.73	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:5	8.18	899	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:6	8.18	899	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.69	14.91	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:14:6	8.18	904	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.67	14.91	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:6	8.18	880	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.9	1.02	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:6	8.18	880	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.66	14.91	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:6	8.18	880	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.68	14.91	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:6	8.18	885	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.63	14.91	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:6	8.18	885	0.83	13.43	101	199	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.63	14.92	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:7	9.54	884	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.91	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:7	9.54	884	0.83	13.42	101	199	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.6	14.9	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:7	9.54	884	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.58	14.9	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:7	9.54	880	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.58	14.89	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:7	8.18	864	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:7	8.18	864	0.83	13.41	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.56	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:8	8.18	864	0.83	13.4	101	199	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.59	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:8	8.18	872	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.54	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:8	8.18	881	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.56	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:8	8.18	881	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.52	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:8	8.18	881	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.53	14.88	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:8	8.18	862	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.5	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:9	8.18	862	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.5	14.9	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:9	9.54	864	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.48	14.92	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:9	9.54	867	0.83	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.47	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:9	9.54	857	0.83	13.39	101	199	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.48	14.95	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:9	9.54	857	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.44	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:9	8.18	857	0.83	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.48	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:14:9	8.18	866	0.83	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.48	14.97	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:0	8.18	874	0.83	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.48	14.86	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:0	8.18	874	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.48	14.87	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:15:0	8.18	874	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.48	14.88	1.01	5.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:0	8.18	841	0.83	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.47	14.89	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:0	8.18	841	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.46	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:0	8.18	855	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.46	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:1	8.18	855	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.46	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:1	8.18	854	0.82	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.44	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:1	8.18	854	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.41	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:1	8.18	864	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.4	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:1	8.18	864	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.38	15.1	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:1	8.18	848	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.37	15.11	1.03	5.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:1	10.9	831	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.38	15.12	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:2	10.9	831	0.82	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.39	15.13	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:2	10.9	833	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.35	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:2	10.9	833	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.37	15.13	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:2	9.54	841	0.82	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.33	15.14	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:2	9.54	841	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.32	15.15	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:2	9.54	845	0.82	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.32	15.14	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:3	9.54	849	0.82	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.32	15.14	1.03	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:3	9.54	849	0.82	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.32	15.12	1.03	5.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:3	9.54	812	0.82	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.31	15.11	1.03	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:3	9.54	812	0.81	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.32	15.09	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:3	9.54	826	0.81	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.29	15.06	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:3	9.54	826	0.81	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.29	15.05	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:4	9.54	820	0.81	13.41	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.3	15.07	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:4	10.9	820	0.81	13.4	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.26	15.06	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:4	10.9	820	0.81	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.25	15.05	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:15:4	10.9	807	0.81	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.25	15.03	1.02	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:15:4	10.9	807	0.81	13.38	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.2	15.01	1.02	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:15:4	10.9	779	0.81	13.37	101	199	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.2	14.99	1.02	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:15:4	10.9	779	0.81	13.36	101	199	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.15	14.98	1.02	5.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:15:5	10.9	764	0.81	13.39	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.09	14.96	1.02	5.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:15:5	10.9	748	0.81	13.36	101	199	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.05	14.94	1.02	5.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:5	10.9	748	0.81	13.37	101	199	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7	14.9	1.02	5.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:5	12.27	735	0.82	13.38	101	199	Idle	93.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7	14.87	1.01	5.4	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:5	12.27	722	0.82	13.35	101	199	Idle	92.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-6.95	14.86	1.01	5.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:5	12.27	722	0.82	13.36	101	199	Idle	92.7	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.9	14.86	1.01	5.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:6	12.27	709	0.82	13.36	101	199	Idle	91.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.9	14.84	1.01	5.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:15:6	12.27	696	0.82	13.34	101	199	Idle	90	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.8	14.83	1.01	5.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:15:6	12.27	663	0.82	13.36	101	199	Idle	90	0	2	132	944 Turbo	0.71	Rich	1	14.6	-6.75	14.83	1.01	5.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:15:6	23.18	663	0.82	13.34	101	199	Idle	87.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.72	14.82	1.01	5.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:15:6	23.18	663	0.83	13.34	101	199	Idle	86.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6.56	14.82	1.01	5.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:15:6	23.18	663	0.84	13.37	101	199	Idle	86.1	0	2	132	944 Turbo	0.58	Rich	1	14.6	-6.47	14.82	1.01	5.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:15:6	23.18	650	0.86	13.31	101	199	Idle	83.6	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.33	14.81	1.01	5.7	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:15:7	23.18	636	0.86	13.31	101	199	Idle	82.4	0	2	132	944 Turbo	0.44	Rich	1	14.6	-6.16	14.8	1.01	5.8	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:15:7	23.18	632	0.87	13.35	101	199	Idle	81.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-6.11	14.79	1.01	5.8	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:15:7	23.18	628	0.88	13.29	101	199	Idle	80.4	0	2	132	944 Turbo	0.32	Rich	1	14.6	-5.99	14.78	1.01	5.6	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:15:7	23.18	628	0.89	13.28	101	199	Idle	79.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-5.8	14.78	1.01	5.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:15:7	23.18	626	0.9	13.33	101	199	Idle	78.6	0	2	132	944 Turbo	0.22	Lean	1	14.6	-5.74	14.78	1.01	5.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:15:7	23.18	625	0.91	13.31	101	199	Idle	77.9	0	2	132	944 Turbo	0.2	Lean	1	14.6	-5.69	14.77	1.01	5.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:15:8	23.18	625	0.92	13.29	101	199	Idle	77.1	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.53	14.76	1.01	5.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:15:8	23.18	625	0.93	13.34	101	199	Idle	76.4	0	2	132	944 Turbo	0.16	Lean	1	14.6	-5.48	14.75	1.01	5.6	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:15:8	23.18	622	0.94	13.29	101	199	Idle	76.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-5.47	14.76	1.01	5.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:15:8	23.18	622	0.94	13.32	101	199	Idle	76.8	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.27	14.75	1	5.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:15:8	23.18	622	0.95	13.37	101	199	Idle	77.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.28	14.75	1	5.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:15:8	23.18	638	0.96	13.34	101	199	Idle	77.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-5.25	14.75	1	5.5	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:9	23.18	638	0.97	13.34	101	199	Idle	77.5	0	2	132	944 Turbo	0.14	Lean	1	14.6	-5.13	14.75	1	5.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:9	23.18	638	0.98	13.39	101	199	Idle	77.9	0	2	132	944 Turbo	0.18	Rich	1	14.6	-5.17	14.75	1	5.6	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:9	23.18	654	0.98	13.34	101	199	Idle	78	0	2	132	944 Turbo	0.2	Rich	1	14.6	-5.14	14.77	1.01	5.4	3.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:15:9	23.18	654	0.98	13.35	101	199	Idle	78.1	0	2	132	944 Turbo	0.25	Rich	1	14.6	-5.05	14.78	1.01	5.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:9	23.18	654	0.98	13.36	101	199	Idle	77.9	0	2	132	944 Turbo	0.31	Rich	1	14.6	-5.07	14.79	1.01	5.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:15:9	23.18	666	0.98	13.32	101	199	Idle	77.7	0	2	132	944 Turbo	0.4	Rich	1	14.6	-5	14.8	1.01	5.3	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:15:9	23.18	666	0.98	13.35	101	199	Idle	77.6	0	2	132	944 Turbo	0.47	Rich	1	14.6	-4.96	14.81	1.01	5.5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:16:0	20.45	663	0.97	13.38	101	199	Idle	77.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-4.99	14.82	1.01	5.4	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:16:0	20.45	663	0.97	13.34	101	199	Idle	77.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-4.93	14.83	1.01	5.2	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:16:0	20.45	663	0.97	13.36	101	199	Idle	77.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-4.89	14.84	1.01	5	3.2	ON	28 Pin	OFF	Removed	Disabled
03:30:16:0	20.45	699	0.97	13.38	101	199	Idle	77	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.98	14.84	1.01	5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:30:16:0	20.45	699	0.97	13.36	101	199	Idle	77	0	2	132	944 Turbo	0.76	Rich	1	14.6	-4.93	14.84	1.01	5.1	3.1	ON	28 Pin	OFF	Removed	Disabled
03:30:16:0	20.45	706	0.97	13.38	101	199	Idle	76.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.93	14.84	1.01	5.2	3.1	ON	28 Pin	OFF	Removed	Disabled
03:30:16:1	20.45	713	0.96	13.36	101	199	Idle	76.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-4.95	14.84	1.01	5.1	3.1	ON	28 Pin	OFF	Removed	Disabled
03:30:16:1	20.45	713	0.96	13.38	101	199	Idle	76.6	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.9	14.82	1.01	5	3.1	ON	28 Pin	OFF	Removed	Disabled
03:30:16:1	20.45	720	0.96	13.39	101	199	Idle	76.7	0	2	132	944 Turbo	0.81	Rich	1	14.6	-4.95	14.81	1.01	5.1	3	ON	28 Pin	OFF	Removed	Disabled
03:30:16:1	20.45	727	0.96	13.36	101	199	Idle	76.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.91	14.8	1.01	5.2	3	ON	28 Pin	OFF	Removed	Disabled
03:30:16:1	20.45	731	0.97	13.38	101	199	Idle	76.7	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.9	14.81	1.01	5.4	3	ON	28 Pin	OFF	Removed	Disabled
03:30:16:1	20.45	731	0.97	13.38	101	199	Idle	76.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.97	14.81	1.01	5.3	3	ON	28 Pin	OFF	Removed	Disabled
03:30:16:1	20.45	731	0.97	13.38	101	199	Idle	76.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.94	14.83	1.01	5.2	3	ON	28 Pin	OFF	Removed	Disabled
03:30:16:2	20.45	747	0.97	13.4	101	199	Idle	76.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.99	14.84	1.01	5.2	3	ON	28 Pin	OFF	Removed	Disabled
03:30:16:2	20.45	747	0.97	13.38	101	199	Idle	76.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.99	14.84	1.01	5.2	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:2	20.45	747	0.97	13.39	101	199	Idle	76.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.98	14.85	1.01	5.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:2	20.45	766	0.97	13.4	101	199	Idle	76.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.05	14.88	1.01	5.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:2	20.45	766	0.97	13.39	101	199	Idle	76.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.04	14.94	1.02	5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:2	20.45	764	0.97	13.39	101	199	Idle	76.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.07	14.97	1.02	4.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:3	20.45	762	0.97	13.38	101	199	Idle	76.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.09	14.99	1.02	4.8	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:3	20.45	759	0.97	13.37	101	199	Idle	76.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.09	14.98	1.02	4.8	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:3	16.36	756	0.97	13.37	101	199	Idle	76.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.16	14.98	1.02	4.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:3	16.36	756	0.97	13.37	101	199	Idle	76.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.15	14.94	1.02	5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:3	16.36	771	0.98	13.37	101	199	Idle	76.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.23	14.9	1.02	5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:3	16.36	786	0.98	13.37	101	199	Idle	76.6	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.22	14.85	1.01	5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:4	16.36	775	0.98	13.38	101	199	Idle	76.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.22	14.8	1.01	5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:4	20.45	775	0.98	13.38	101	199	Idle	76.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.2	14.7	1	5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:4	20.45	775	0.98	13.37	101	199	Idle	76.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.24	14.6	0.99	4.9	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:4	20.45	754	0.98	13.38	101	199	Idle	76.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.21	14.52	0.99	5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:4	20.45	754	0.98	13.38	101	199	Idle	76.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.21	14.43	0.98	5	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:4	16.36	759	0.98	13.39	101	199	Idle	76.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.24	14.34	0.98	5.1	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:4	16.36	764	0.98	13.38	101	199	Idle	76.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.24	14.25	0.97	5.1	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:5	16.36	764	0.99	13.39	101	199	Idle	76.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.22	14.15	0.96	5.1	2.8	ON	28 Pin	OFF	Removed	Disabled
03:30:16:5	16.36	764	0.99	13.38	101	199	Off Idle	76.4	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.24	14.03	0.96	5.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:5	16.36	764	0.99	13.37	101	199	Off Idle	76.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.19	13.95	0.95	5.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:5	20.45	764	1	13.39	101	199	Off Idle	76.3	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.17	13.89	0.95	5.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:5	20.45	769	1	13.39	101	199	Off Idle	76.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.15	13.86	0.94	5.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:5	20.45	769	1.02	13.39	101	199	Off Idle	76.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.06	13.76	0.94	5.1	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:16:6	20.45	764	1.03	13.4	101	199	Off Idle	76.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.04	13.74	0.94	5.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:16:6	20.45	760	1.04	13.39	101	199	Off Idle	77	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.93	13.7	0.93	5.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:16:6	20.45	741	1.04	13.39	101	199	Off Idle	77.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.88	13.68	0.93	5.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:16:6	20.45	741	1.05	13.36	101	199	Off Idle	78.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.86	13.66	0.93	5.2	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:16:6	20.45	741	1.06	13.38	101	199	Off Idle	78.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-4.74	13.64	0.93	5.1	3.5	ON	28 Pin	OFF	Removed	Disabled
03:30:16:6	20.45	749	1.07	13.36	101	199	Off Idle	79.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.75	13.65	0.93	5.1	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:6	20.45	749	1.07	13.37	101	199	Off Idle	79.6	0	2	132	944 Turbo	0.71	Rich	1	14.6	-4.68	13.65	0.93	5.1	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:7	19.09	749	1.08	13.41	101	199	Off Idle	80	0	2	132	944 Turbo	0.68	Rich	1	14.6	-4.67	13.64	0.93	5.1	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:7	19.09	756	1.08	13.37	101	199	Off Idle	80.5	0	2	132	944 Turbo	0.64	Rich	1	14.6	-4.66	13.66	0.93	5.1	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:7	19.09	759	1.09	13.37	101	199	Off Idle	80.9	0	2	132	944 Turbo	0.58	Rich	1	14.6	-4.65	13.67	0.93	5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:7	19.09	759	1.09	13.38	101	199	Off Idle	81.4	0	2	132	944 Turbo	0.55	Rich	1	14.6	-4.64	13.68	0.93	5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:7	19.09	762	1.1	13.37	101	199	Off Idle	81.4	0	2	132	944 Turbo	0.46	Rich	1	14.6	-4.64	13.71	0.93	5.1	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:7	19.09	766	1.1	13.38	101	199	Off Idle	81.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-4.65	13.73	0.94	5.1	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:8	20.45	771	1.1	13.38	101	199	Off Idle	82.3	0	2	132	944 Turbo	0.33	Rich	1	14.6	-4.64	13.76	0.94	5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:8	20.45	772	1.11	13.4	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.24	Rich	1	14.6	-4.62	13.84	0.94	5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:8	20.45	772	1.11	13.39	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-4.62	13.9	0.95	5	3.6	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:16:8	20.45	772	1.12	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.15	Lean	1	14.6	-4.6	13.97	0.95	5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:8	20.45	789	1.12	13.39	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.12	Lean	1	14.6	-4.59	14.04	0.96	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:8	20.45	789	1.11	13.37	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.59	14.08	0.96	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:9	20.45	786	1.11	13.37	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-4.6	14.16	0.96	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:9	20.45	782	1.11	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-4.59	14.25	0.97	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:9	20.45	782	1.11	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-4.55	14.38	0.98	5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:9	20.45	780	1.11	13.39	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.22	Lean	1	14.6	-4.54	14.42	0.98	5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:9	20.45	777	1.12	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.28	Lean	1	14.6	-4.49	14.53	0.99	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:9	20.45	775	1.12	13.39	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.35	Lean	1	14.6	-4.47	14.58	0.99	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:16:9	20.45	775	1.12	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.42	Rich	1	14.6	-4.44	14.64	1	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:17:0	20.45	775	1.13	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.49	Rich	1	14.6	-4.41	14.68	1	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:17:0	20.45	792	1.13	13.39	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.56	Rich	1	14.6	-4.38	14.73	1	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:17:0	20.45	792	1.14	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-4.33	14.74	1	4.9	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:17:0	20.45	789	1.15	13.41	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-4.29	14.76	1.01	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:0	20.45	786	1.16	13.39	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-4.25	14.79	1.01	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:0	20.45	780	1.16	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-4.2	14.83	1.01	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:1	19.09	780	1.17	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.82	Rich	1	14.6	-4.16	14.9	1.01	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:1	19.09	780	1.18	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.12	14.94	1.02	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:1	19.09	794	1.19	13.36	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.09	14.96	1.02	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:1	19.09	794	1.2	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.05	15	1.02	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:1	20.45	794	1.2	13.4	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.04	15.03	1.02	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:1	20.45	799	1.21	13.4	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.05	15.06	1.03	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:1	20.45	800	1.21	13.41	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.03	15.13	1.03	4.8	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:2	20.45	801	1.22	13.4	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.01	15.17	1.03	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:2	20.45	801	1.22	13.4	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.01	15.19	1.03	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:2	19.09	802	1.22	13.41	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4	15.16	1.03	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:2	19.09	802	1.23	13.39	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.97	15.12	1.03	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:2	19.09	802	1.23	13.4	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.97	15.04	1.02	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:2	19.09	797	1.23	13.4	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.96	14.97	1.02	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:3	19.09	802	1.23	13.39	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.96	14.89	1.01	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:3	17.72	806	1.23	13.38	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.94	14.78	1.01	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:3	17.72	806	1.23	13.4	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.94	14.64	1	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:3	17.72	800	1.23	13.36	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.94	14.51	0.99	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:3	17.72	800	1.23	13.38	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.92	14.27	0.97	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:3	17.72	780	1.23	13.36	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.92	14.14	0.96	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:4	20.45	780	1.23	13.37	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.93	14.02	0.96	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:4	20.45	780	1.23	13.37	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.85	13.91	0.95	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:4	20.45	759	1.23	13.39	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.85	13.85	0.94	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:4	20.45	759	1.23	13.36	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.78	13.75	0.94	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:4	20.45	759	1.23	13.38	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.76	13.61	0.93	5.2	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:4	20.45	747	1.23	13.33	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.76	13.58	0.93	5.3	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:4	20.45	747	1.23	13.32	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.68	13.53	0.92	5.4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:5	20.45	747	1.23	13.33	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.69	13.48	0.92	5.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:5	20.45	697	1.22	13.26	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.52	13.43	0.91	5.8	4	ON	28 Pin	OFF	Removed	Disabled
03:30:17:5	20.45	697	1.22	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.52	13.41	0.91	5.8	4	ON	28 Pin	OFF	Removed	Disabled
03:30:17:5	20.45	659	1.22	13.29	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.54	13.37	0.91	5.8	4	ON	28 Pin	OFF	Removed	Disabled
03:30:17:5	20.45	659	1.21	13.25	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.39	13.36	0.91	6	4	ON	28 Pin	OFF	Removed	Disabled
03:30:17:5	20.45	659	1.21	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.33	13.35	0.91	6.1	4	ON	28 Pin	OFF	Removed	Disabled
03:30:17:6	20.45	632	1.21	13.31	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.38	13.33	0.91	6.1	4.3	ON	28 Pin	OFF	Removed	Disabled
03:30:17:6	20.45	632	1.2	13.27	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.24	13.33	0.91	6.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:30:17:6	20.45	632	1.2	13.28	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.13	13.33	0.91	6.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:30:17:6	20.45	628	1.19	13.34	101	199	Off Idle	82.7	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.17	13.32	0.91	6.2	4.3	ON	28 Pin	OFF	Removed	Disabled
03:30:17:6	20.45	628	1.19	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3	13.33	0.91	5.8	4.3	ON	28 Pin	OFF	Removed	Disabled
03:30:17:6	20.45	628	1.18	13.34	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3	13.33	0.91	5.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:30:17:6	20.45	639	1.18	13.36	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.01	13.33	0.91	5.6	4.1	ON	28 Pin	OFF	Removed	Disabled
03:30:17:7	20.45	650	1.17	13.33	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.93	13.32	0.91	5.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:30:17:7	20.45	650	1.17	13.4	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3	13.32	0.91	5.5	4.1	ON	28 Pin	OFF	Removed	Disabled
03:30:17:7	20.45	670	1.16	13.35	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.09	13.32	0.91	5.3	4.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:17:7	20.45	690	1.15	13.37	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.03	13.31	0.91	5.2	4.1	ON	28 Pin	OFF	Removed	Disabled
03:30:17:7	20.45	722	1.15	13.4	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.07	13.3	0.91	5.1	4.1	ON	28 Pin	OFF	Removed	Disabled
03:30:17:7	20.45	722	1.14	13.37	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.86	Rich	1	14.6	-3.1	13.28	0.9	5.2	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:8	20.45	722	1.14	13.37	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.1	13.27	0.9	5.3	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:8	17.72	728	1.14	13.35	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.21	13.24	0.9	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:8	17.72	728	1.13	13.33	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.16	13.23	0.9	4.9	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:8	17.72	728	1.13	13.37	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.23	13.22	0.9	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:17:8	17.72	733	1.13	13.31	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.26	13.21	0.9	5.3	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:17:8	17.72	733	1.13	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.21	13.2	0.9	5.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:17:9	17.72	733	1.13	13.35	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.28	13.19	0.9	5.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:17:9	17.72	706	1.13	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.26	13.17	0.9	5.8	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:17:9	17.72	706	1.13	13.35	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.22	13.19	0.9	6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:17:9	17.72	692	1.13	13.33	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.28	13.17	0.9	6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:17:9	17.72	677	1.13	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.24	13.17	0.9	5.9	3.9	ON	28 Pin	OFF	Removed	Disabled
03:30:17:9	17.72	677	1.13	13.35	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.19	13.18	0.9	5.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:30:17:9	19.09	672	1.14	13.33	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.21	13.18	0.9	5.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:30:18:0	19.09	667	1.14	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.11	13.17	0.9	5.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:30:18:0	19.09	664	1.14	13.36	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.12	13.19	0.9	5.8	3.9	ON	28 Pin	OFF	Removed	Disabled
03:30:18:0	19.09	662	1.14	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.16	13.18	0.9	5.7	4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:0	19.09	662	1.14	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.08	13.18	0.9	5.6	4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:0	19.09	662	1.14	13.33	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.08	13.19	0.9	5.5	4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:0	19.09	683	1.13	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.12	13.17	0.9	5.3	4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:1	19.09	683	1.13	13.34	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.09	13.19	0.9	5.2	4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:1	19.09	690	1.13	13.38	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.2	13.17	0.9	5.2	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:1	19.09	698	1.13	13.35	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.15	13.16	0.9	5.2	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:1	19.09	698	1.13	13.4	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.15	13.17	0.9	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:1	17.72	709	1.13	13.36	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.21	13.17	0.9	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:1	17.72	720	1.13	13.35	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.18	13.17	0.9	5.1	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:1	17.72	728	1.13	13.36	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.19	13.18	0.9	5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:2	17.72	728	1.13	13.35	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.23	13.16	0.9	5.3	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:2	17.72	728	1.13	13.35	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.21	13.17	0.9	5.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:2	17.72	714	1.13	13.34	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.3	13.15	0.9	5.4	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:2	17.72	714	1.13	13.34	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.21	13.13	0.89	5.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:2	17.72	714	1.13	13.36	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.21	13.14	0.9	5.5	3.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:2	17.72	705	1.13	13.31	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.25	13.11	0.89	5.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:3	17.72	705	1.13	13.33	102	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.21	13.1	0.89	5.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:3	17.72	701	1.13	13.37	102	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.28	13.07	0.89	5.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:3	17.72	701	1.13	13.33	102	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.28	13.05	0.89	5.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:3	17.72	701	1.13	13.34	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.26	13.04	0.89	5.5	3.8	ON	28 Pin	OFF	Removed	Disabled
03:30:18:3	17.72	700	1.13	13.36	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.34	13.02	0.89	5.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:18:3	17.72	700	1.13	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.3	13.01	0.89	5.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:18:4	17.72	702	1.13	13.36	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.3	13.02	0.89	5.6	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:18:4	19.09	705	1.13	13.32	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.37	13	0.89	5.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:18:4	19.09	705	1.12	13.33	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.38	13.01	0.89	5.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:18:4	19.09	705	1.12	13.33	101	199	Off Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.38	13.01	0.89	5.5	3.7	ON	28 Pin	OFF	Removed	Disabled
03:30:18:4	19.09	706	1.06	13.33	101	199	Full Load	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.63	13.02	0.89	5.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:4	19.09	706	1.03	13.34	101	199	Idle	82.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.77	13.04	0.89	5.1	3.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:4	17.72	716	1.01	13.34	101	199	Idle	82.6	0	2	132	944 Turbo	0.84	Rich	1	14.6	-3.88	13.06	0.89	5.1	3.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:5	17.72	726	0.99	13.34	101	199	Idle	82.4	0	2	132	944 Turbo	0.85	Rich	1	14.6	-3.96	13.1	0.89	5.2	3.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:5	17.72	727	0.98	13.34	101	199	Idle	82.1	0	2	132	944 Turbo	0.85	Rich	1	14.6	-4.04	13.14	0.89	5.3	3.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:5	17.72	728	0.97	13.34	101	199	Idle	82.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.25	13.17	0.9	5.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:5	17.72	728	0.95	13.34	101	199	Idle	82	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.33	13.22	0.9	5.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:5	20.45	726	0.94	13.35	101	199	Idle	81.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.46	13.24	0.9	5.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:5	20.45	725	0.91	13.32	101	199	Idle	81.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.51	13.31	0.91	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:6	20.45	725	0.9	13.36	101	199	Idle	81.5	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.55	13.32	0.91	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:6	20.45	719	0.88	13.31	101	199	Idle	81.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.65	13.34	0.91	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:6	20.45	719	0.87	13.32	101	199	Idle	81.3	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.66	13.36	0.91	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:6	20.45	714	0.86	13.37	101	199	Idle	81.2	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.7	13.37	0.91	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:18:6	20.45	714	0.85	13.34	101	199	Idle	81.1	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.74	13.38	0.91	5.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:6	20.45	714	0.84	13.34	101	199	Idle	80.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.74	13.41	0.91	5.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:18:6	20.45	717	0.82	13.37	101	199	Idle	80.9	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.81	13.41	0.91	5.4	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:7	20.45	717	0.81	13.34	101	199	Idle	80.7	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.84	13.42	0.91	5.3	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:7	20.45	724	0.82	13.38	101	199	Idle	80.8	0	2	132	944 Turbo	0.83	Rich	1	14.6	-4.87	13.41	0.91	5.3	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:7	21.81	732	0.83	13.36	101	199	Idle	80.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.93	13.41	0.91	5.1	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:7	21.81	732	0.85	13.37	101	199	Idle	80.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-4.98	13.43	0.91	4.9	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:7	21.81	750	0.86	13.4	101	199	Idle	80.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.01	13.43	0.91	4.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:18:7	21.81	768	0.87	13.41	101	199	Idle	80.9	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.09	13.43	0.91	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:18:8	21.81	816	0.87	13.41	101	199	Idle	81	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.16	13.45	0.92	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:18:8	20.45	816	0.87	13.43	101	199	Idle	81.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.23	13.46	0.92	4.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:18:8	20.45	836	0.87	13.42	101	199	Idle	81.1	0	2	132	944 Turbo	0.84	Rich	1	14.6	-5.29	13.47	0.92	4.5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:18:8	20.45	857	0.86	13.42	101	199	Idle	81	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.39	13.51	0.92	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:18:8	20.45	857	0.87	13.41	101	199	Idle	81	0	2	132	944 Turbo	0.82	Rich	1	14.6	-5.48	13.53	0.92	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:18:8	12.27	853	0.88	13.41	101	199	Idle	81.1	0	2	132	944 Turbo	0.81	Rich	1	14.6	-5.55	13.56	0.92	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:18:9	12.27	849	0.88	13.4	101	199	Idle	81.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-5.64	13.58	0.92	4.3	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:18:9	12.27	926	0.89	13.41	101	199	Idle	81.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-5.7	13.6	0.93	4.4	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:18:9	12.27	926	0.88	13.41	101	199	Idle	81.8	0	2	132	944 Turbo	0.75	Rich	1	14.6	-5.81	13.62	0.93	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:18:9	12.27	931	0.88	13.39	101	199	Idle	81.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-5.88	13.63	0.93	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:18:9	12.27	931	0.88	13.41	101	199	Idle	82.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-6	13.65	0.93	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:18:9	12.27	928	0.89	13.38	101	199	Idle	82.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.04	13.65	0.93	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:18:9	12.27	928	0.89	13.41	101	199	Idle	82.5	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.14	13.64	0.93	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:0	12.27	910	0.89	13.38	101	199	Idle	82.6	0	2	132	944 Turbo	0.42	Rich	1	14.6	-6.2	13.62	0.93	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:0	12.27	910	0.89	13.4	101	199	Idle	82.8	0	2	132	944 Turbo	0.32	Rich	1	14.6	-6.23	13.61	0.93	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:0	12.27	910	0.9	13.39	101	199	Idle	83	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.27	13.6	0.93	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:0	12.27	899	0.9	13.41	101	199	Idle	83	0	2	132	944 Turbo	0.23	Lean	1	14.6	-6.33	13.59	0.93	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:0	12.27	893	0.9	13.41	101	199	Idle	83.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.37	13.59	0.93	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:0	12.27	893	0.9	13.42	101	199	Idle	83.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.44	13.59	0.93	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:1	12.27	906	0.9	13.4	101	199	Idle	83.6	0	2	132	944 Turbo	0.08	Lean	1	14.6	-6.47	13.6	0.93	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:1	12.27	906	0.91	13.41	101	199	Idle	83.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.5	13.62	0.93	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:19:1	12.27	906	0.91	13.39	101	199	Idle	83.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.53	13.64	0.93	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:19:1	12.27	912	0.91	13.39	101	199	Idle	83.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.56	13.7	0.93	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:19:1	12.27	912	0.91	13.39	101	199	Idle	83.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-6.63	13.76	0.94	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:19:1	12.27	927	0.91	13.4	101	199	Idle	83.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.62	13.82	0.94	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:19:1	12.27	954	0.91	13.4	101	199	Idle	83.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.71	13.89	0.95	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:19:2	10.9	954	0.91	13.41	101	199	Idle	83.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.68	13.98	0.95	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:19:2	10.9	942	0.91	13.39	101	199	Idle	84	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.75	14.09	0.96	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:19:2	10.9	942	0.91	13.4	101	199	Idle	84.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.73	14.09	0.96	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:2	10.9	942	0.92	13.4	101	199	Idle	84.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.78	14.2	0.97	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:2	10.9	926	0.92	13.41	101	199	Idle	84.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.79	14.29	0.97	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:2	10.9	934	0.92	13.4	101	199	Idle	84.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.87	14.36	0.98	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:3	10.9	934	0.92	13.4	101	199	Idle	84.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.85	14.45	0.98	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:3	12.27	941	0.92	13.38	101	199	Idle	84.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.91	14.54	0.99	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:3	12.27	948	0.92	13.4	101	199	Idle	84.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.9	14.66	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:3	12.27	945	0.92	13.39	101	199	Idle	84.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.96	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:3	12.27	945	0.92	13.41	101	199	Idle	84.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.95	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:3	12.27	955	0.92	13.4	101	199	Idle	84.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.99	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:4	12.27	965	0.92	13.38	101	199	Idle	84.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7	15.35	1.05	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:4	12.27	965	0.92	13.4	101	199	Idle	84.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.07	15.51	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:4	12.27	956	0.92	13.4	101	199	Idle	84.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.04	15.69	1.07	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:4	12.27	975	0.92	13.41	101	199	Idle	84.9	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.1	15.87	1.08	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:4	9.54	975	0.92	13.41	101	199	Idle	85	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.09	16.04	1.09	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:4	9.54	976	0.92	13.4	101	199	Idle	85.1	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.13	16.19	1.1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:4	9.54	978	0.92	13.41	101	199	Idle	85.2	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.15	16.41	1.12	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:5	9.54	961	0.92	13.4	101	199	Idle	85.3	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.21	16.54	1.13	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:5	9.54	961	0.92	13.41	101	199	Idle	85.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.16	16.68	1.14	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:5	9.54	980	0.92	13.39	101	199	Idle	85.5	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.21	16.79	1.14	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:5	9.54	980	0.92	13.4	101	199	Idle	85.7	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.19	16.89	1.15	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:19:5	9.54	976	0.92	13.39	101	199	Full Load	85.8	0	2	132	944 Turbo	0.04	Lean	1	14.6	-7.23	16.97	1.16	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:5	9.54	972	0.92	13.39	101	199	Off Idle	86	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.19	17.05	1.16	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:6	9.54	981	0.93	13.36	101	199	Off Idle	86.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.19	17.11	1.17	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:6	9.54	981	0.93	13.4	101	199	Off Idle	86.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.23	17.2	1.17	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:6	10.9	986	0.94	13.39	101	199	Off Idle	86.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.22	17.22	1.17	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:6	10.9	986	0.95	13.41	101	199	Off Idle	86.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.12	17.26	1.18	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:19:6	10.9	985	0.97	13.38	101	199	Off Idle	86.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-7.01	17.28	1.18	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:19:6	10.9	985	0.98	13.41	101	199	Off Idle	86.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.97	17.29	1.18	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:19:6	9.54	989	1	13.39	101	199	Off Idle	86.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.86	17.29	1.18	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:19:7	9.54	982	1.03	13.38	101	199	Off Idle	86.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.78	17.28	1.18	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:19:7	9.54	982	1.05	13.4	101	199	Off Idle	86.1	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.64	17.25	1.17	4.8	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:19:7	9.54	982	1.07	13.41	101	199	Off Idle	86	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.55	17.23	1.17	4.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:19:7	9.54	960	1.1	13.4	101	199	Off Idle	86	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.35	17.19	1.17	4.9	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:19:7	9.54	952	1.13	13.41	101	199	Off Idle	85.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.24	17.15	1.17	5	2.9	ON	28 Pin	OFF	Removed	Disabled
03:30:19:7	9.54	952	1.16	13.4	101	199	Off Idle	85.8	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6	17.13	1.17	5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:30:19:8	9.54	957	1.19	13.41	101	199	Off Idle	85.7	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.85	17.09	1.16	4.9	3.4	ON	28 Pin	OFF	Removed	Disabled
03:30:19:8	10.9	962	1.22	13.4	101	199	Off Idle	85.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.6	17.04	1.16	4.8	3.4	ON	28 Pin	OFF	Removed	Disabled
03:30:19:8	10.9	962	1.26	13.41	101	199	Off Idle	85.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.46	17	1.16	4.6	3.4	ON	28 Pin	OFF	Removed	Disabled
03:30:19:8	10.9	971	1.31	13.4	101	199	Off Idle	85.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-5.06	16.96	1.15	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:30:19:8	9.54	986	1.37	13.39	101	199	Off Idle	85.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.88	16.88	1.15	4.6	3.9	ON	28 Pin	OFF	Removed	Disabled
03:30:19:8	9.54	1000	1.41	13.39	101	199	Off Idle	85.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.62	16.84	1.15	4.7	3.9	ON	28 Pin	OFF	Removed	Disabled
03:30:19:9	9.54	1026	1.45	13.39	101	199	Off Idle	85.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.43	16.79	1.14	4.7	4.5	ON	28 Pin	OFF	Removed	Disabled
03:30:19:9	9.54	1026	1.48	13.39	101	199	Off Idle	85.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-4.19	16.75	1.14	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:30:19:9	10.9	1041	1.52	13.41	101	199	Off Idle	85.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-4.04	16.69	1.14	4.6	4.5	ON	28 Pin	OFF	Removed	Disabled
03:30:19:9	10.9	1118	1.55	13.4	102	199	Off Idle	85.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-3.85	16.63	1.13	4.5	4.5	ON	28 Pin	OFF	Removed	Disabled
03:30:19:9	10.9	1118	1.57	13.38	102	199	Off Idle	85.4	0	2	132	944 Turbo	0.04	Lean	1	14.6	-3.72	16.57	1.13	4.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:30:19:9	10.9	1100	1.6	13.41	102	199	Off Idle	85.4	0	2	132	944 Turbo	0.05	Lean	1	14.6	-3.58	16.52	1.13	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:30:19:9	20.45	1081	1.63	13.4	101	199	Off Idle	85.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-3.35	16.42	1.12	4.4	4.6	ON	28 Pin	OFF	Removed	Disabled
03:30:20:0	20.45	1114	1.65	13.4	101	199	Off Idle	85.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-3.3	16.37	1.11	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:30:20:0	20.45	1114	1.67	13.42	101	199	Off Idle	85.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-3.18	16.34	1.11	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:30:20:0	20.45	1124	1.69	13.4	101	199	Off Idle	85.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-3.13	16.27	1.11	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:30:20:0	20.45	1132	1.7	13.42	101	199	Off Idle	85.7	0	2	132	944 Turbo	0.24	Lean	1	14.6	-3.26	16.21	1.1	4.4	4.5	ON	28 Pin	OFF	Removed	Disabled
03:30:20:0	20.45	1132	1.7	13.4	101	199	Off Idle	85.7	0	2	132	944 Turbo	0.32	Lean	1	14.6	-3.32	16.18	1.1	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:30:20:0	20.45	1133	1.66	13.39	101	199	Off Idle	85.8	0	2	132	944 Turbo	0.43	Lean	1	14.6	-3.56	16.14	1.1	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:30:20:1	20.45	1138	1.63	13.39	101	199	Full Load	85.8	0	2	132	944 Turbo	0.47	Lean	1	14.6	-3.74	16.13	1.1	4.4	4	ON	28 Pin	OFF	Removed	Disabled
03:30:20:1	20.45	1143	1.57	13.38	101	199	Idle	85.9	0	2	132	944 Turbo	0.55	Lean	1	14.6	-4.09	16.1	1.1	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:1	20.45	1143	1.51	13.38	101	199	Idle	85.9	0	2	132	944 Turbo	0.63	Lean	1	14.6	-4.39	16.08	1.1	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:1	20.45	1124	1.42	13.37	101	199	Idle	86	0	2	132	944 Turbo	0.7	Rich	1	14.6	-4.7	16.05	1.09	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:1	20.45	1116	1.39	13.38	101	199	Idle	86	0	2	132	944 Turbo	0.77	Rich	1	14.6	-4.99	16.02	1.09	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:1	20.45	1116	1.37	13.38	101	199	Idle	86	0	2	132	944 Turbo	0.8	Rich	1	14.6	-5.23	15.97	1.09	4.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:1	23.18	1086	1.32	13.38	101	199	Idle	86	0	2	132	944 Turbo	0.83	Rich	1	14.6	-5.58	15.86	1.08	4.7	1.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:2	23.18	1082	1.28	13.4	101	199	Idle	86	0	2	132	944 Turbo	0.85	Rich	1	14.6	-5.75	15.77	1.07	4.6	1.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:2	23.18	1078	1.23	13.38	101	199	Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-5.93	15.71	1.07	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:2	24.54	1078	1.17	13.4	101	199	Idle	86	0	2	132	944 Turbo	0.86	Rich	1	14.6	-6.09	15.62	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:2	24.54	1060	1.12	13.38	101	199	Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.6	-6.23	15.5	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:2	24.54	1033	1.08	13.38	101	199	Idle	86	0	2	132	944 Turbo	0.87	Rich	1	14.6	-6.44	15.38	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:2	24.54	1033	1.05	13.4	101	199	Idle	86	0	2	132	944 Turbo	0.88	Rich	1	14.6	-6.46	15.14	1.03	5.1	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:20:3	24.54	1008	1.01	13.39	101	199	Idle	85.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-6.6	15.05	1.02	5.1	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:20:3	24.54	983	0.95	13.41	101	199	Idle	85.2	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.69	14.85	1.01	5	1.9	ON	28 Pin	OFF	Removed	Disabled
03:30:20:3	24.54	966	0.91	13.39	101	199	Idle	84.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.72	14.56	0.99	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:3	24.54	966	0.87	13.41	101	199	Idle	84.3	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.75	14.37	0.98	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:3	24.54	944	0.84	13.39	101	199	Idle	83.7	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.77	14.27	0.97	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:3	24.54	922	0.84	13.4	101	199	Idle	83.1	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.75	13.94	0.95	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:4	24.54	873	0.85	13.39	101	199	Idle	82.6	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.75	13.74	0.94	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:20:4	24.54	873	0.88	13.39	101	199	Idle	81.8	0	2	132	944 Turbo	0.89	Rich	1	14.6	-6.7	13.56	0.92	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:20:4	24.54	852	0.91	13.39	101	199	Idle	80.9	0	2	132	944 Turbo	0.88	Rich	1	14.6	-6.7	13.38	0.91	5.3	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:20:4	23.18	830	0.94	13.38	101	199	Idle	80	0	2	132	944 Turbo	0.88	Rich	1	14.6	-6.64	13.24	0.9	5.4	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:20:4	23.18	830	0.94	13.38	101	199	Idle	78.8	0	2	132	944 Turbo	0.88	Rich	1	14.6	-6.6	13.14	0.89	5.5	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:20:4	23.18	786	0.94	13.37	101	199	Idle	77.6	0	2	132	944 Turbo	0.87	Rich	1	14.6	-6.54	13.04	0.89	5.6	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:20:4	23.18	786	0.94	13.37	101	199	Idle	76.4	0	2	132	944 Turbo	0.86	Rich	1	14.6	-6.42	12.94	0.88	5.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:20:5	23.18	770	0.95	13.39	101	199	Idle	75.1	0	2	132	944 Turbo	0.86	Rich	1	14.6	-6.33	12.87	0.88	5.5	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:20:5	23.18	770	0.98	13.38	102	199	Idle	73.5	0	2	132	944 Turbo	0.85	Rich	1	14.6	-6.24	12.8	0.87	5.3	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:20:5	23.18	770	0.99	13.39	102	199	Idle	72.8	0	2	132	944 Turbo	0.84	Rich	1	14.6	-6.12	12.74	0.87	5.2	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:20:5	23.18	784	1.01	13.38	102	199	Idle	72.5	0	2	132	944 Turbo	0.82	Rich	1	14.6	-6.04	12.68	0.86	5.2	3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:5	23.18	784	1.02	13.38	101	199	Idle	72.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6	12.64	0.86	5.2	3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:5	19.09	779	1.02	13.38	101	199	Idle	72.6	0	2	132	944 Turbo	0.7	Rich	1	14.6	-5.89	12.54	0.85	5.2	3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:6	19.09	774	1.03	13.38	101	199	Idle	72.6	0	2	132	944 Turbo	0.67	Rich	1	14.6	-5.84	12.51	0.85	5	3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:6	19.09	774	1.03	13.38	101	199	Idle	72.9	0	2	132	944 Turbo	0.59	Lean	1	14.6	-5.8	12.45	0.85	4.8	3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:6	19.09	826	1.05	13.39	101	199	Idle	73.8	0	2	132	944 Turbo	0.48	Lean	1	14.6	-5.7	12.34	0.84	4.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:30:20:6	19.09	837	1.05	13.4	101	199	Idle	74.4	0	2	132	944 Turbo	0.4	Lean	1	14.6	-5.72	12.28	0.84	4.9	3.1	ON	28 Pin	OFF	Removed	Disabled
03:30:20:6	19.09	848	1.06	13.4	101	199	Idle	75.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-5.71	12.24	0.83	4.8	3.1	ON	28 Pin	OFF	Removed	Disabled
03:30:20:6	19.09	848	1.05	13.41	101	199	Idle	76.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-5.78	12.19	0.83	4.7	3.1	ON	28 Pin	OFF	Removed	Disabled
03:30:20:6	19.09	867	1.05	13.41	101	199	Idle	77.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-5.82	12.16	0.83	4.7	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:7	19.09	867	1.05	13.41	101	199	Idle	78.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-5.88	12.11	0.82	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:7	16.36	878	1.04	13.39	101	199	Idle	79.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-5.95	12.1	0.82	4.6	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:7	16.36	890	1.04	13.42	101	199	Idle	80.5	0	2	132	944 Turbo	0.06	Lean	1	14.6	-5.97	12.1	0.82	4.5	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:7	16.36	927	1.04	13.4	101	199	Idle	81.6	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.08	12.12	0.83	4.4	2.7	ON	28 Pin	OFF	Removed	Disabled
03:30:20:7	16.36	927	1.03	13.43	101	199	Idle	82.5	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.16	12.15	0.83	4.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:20:7	14.99	935	1.02	13.4	101	199	Idle	83.2	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.22	12.2	0.83	4.3	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:20:8	14.99	943	1.01	13.42	101	199	Idle	83.9	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.28	12.26	0.84	4.2	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:20:8	14.99	979	1	13.4	101	199	Idle	84	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.36	12.35	0.84	4.4	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:8	14.99	979	0.99	13.41	101	199	Idle	84.3	0	2	132	944 Turbo	0.05	Lean	1	14.6	-6.39	12.46	0.85	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:8	14.99	974	0.98	13.39	101	199	Idle	84.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-6.48	12.6	0.86	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:8	14.99	974	0.97	13.41	102	199	Idle	84.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.51	12.77	0.87	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:8	14.99	978	0.97	13.39	102	199	Idle	85.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.6	12.95	0.88	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:9	14.99	983	0.95	13.41	102	199	Idle	85.4	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.69	13.27	0.9	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:9	14.99	996	0.95	13.39	101	199	Idle	85.5	0	2	132	944 Turbo	0.33	Lean	1	14.6	-6.72	13.51	0.92	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:9	14.99	996	0.94	13.41	101	199	Idle	85.6	0	2	132	944 Turbo	0.41	Rich	1	14.6	-6.8	13.71	0.93	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:20:9	14.99	996	0.94	13.38	101	199	Idle	85.7	0	2	132	944 Turbo	0.48	Rich	1	14.6	-6.84	13.92	0.95	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:9	14.99	987	0.94	13.41	102	199	Idle	85.9	0	2	132	944 Turbo	0.55	Rich	1	14.6	-6.91	14.17	0.97	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:9	13.63	978	0.94	13.39	102	199	Idle	86	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.92	14.41	0.98	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:20:9	13.63	978	0.93	13.38	102	199	Idle	86.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.97	14.66	1	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:0	13.63	989	0.93	13.39	101	199	Idle	86.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:0	13.63	989	0.93	13.4	101	199	Idle	86.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.09	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:0	13.63	989	0.93	13.38	101	199	Idle	86.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.06	15.25	1.04	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:0	13.63	989	0.93	13.38	101	199	Idle	86.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.12	15.38	1.05	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:0	13.63	974	0.93	13.39	101	199	Idle	86.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.12	15.55	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:0	14.99	963	0.92	13.39	101	199	Idle	86.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.17	15.66	1.07	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:1	14.99	963	0.92	13.39	101	199	Idle	86.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.16	15.7	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:1	14.99	953	0.92	13.39	101	199	Idle	86.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.22	15.69	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:1	14.99	943	0.92	13.39	101	199	Idle	86.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.19	15.67	1.07	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:1	16.36	936	0.92	13.37	101	199	Idle	87	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.23	15.54	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:1	16.36	936	0.92	13.38	101	199	Idle	87	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.19	15.5	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:1	16.36	932	0.92	13.39	101	199	Idle	86.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.24	15.39	1.05	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:1	16.36	929	0.92	13.38	101	199	Idle	87	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.22	15.34	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:2	16.36	912	0.92	13.39	101	199	Idle	87.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.24	15.28	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:2	14.99	912	0.91	13.38	101	199	Idle	87.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.2	15.24	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:2	14.99	912	0.91	13.4	101	199	Idle	87.1	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.27	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:21:2	14.99	912	0.91	13.4	101	199	Idle	87.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.2	15.1	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:21:2	14.99	912	0.91	13.39	101	199	Idle	87.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.23	15.05	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:21:2	13.63	896	0.91	13.39	101	199	Idle	87.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.22	15	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:21:3	13.63	899	0.91	13.38	101	199	Idle	87.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.25	14.95	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:21:3	13.63	902	0.91	13.38	101	199	Idle	87.3	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.21	14.91	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:21:3	13.63	902	0.91	13.4	101	199	Idle	87.3	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.23	14.88	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:21:3	14.99	882	0.91	13.38	101	199	Idle	87.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.19	14.81	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:21:3	14.99	882	0.91	13.4	101	199	Idle	87.1	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.2	14.75	1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:21:3	14.99	884	0.91	13.39	101	199	Idle	87.1	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.16	14.7	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:4	14.99	887	0.91	13.4	101	199	Idle	87.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.18	14.67	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:4	14.99	886	0.91	13.37	101	199	Idle	87.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.16	14.64	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:4	14.99	886	0.91	13.39	101	199	Idle	87.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.17	14.63	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:4	14.99	881	0.91	13.39	101	199	Idle	87.1	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.18	14.62	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:4	14.99	876	0.91	13.38	101	199	Idle	87.1	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.15	14.63	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:4	14.99	876	0.91	13.4	101	199	Idle	87.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.18	14.63	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:4	13.63	876	0.91	13.38	101	199	Idle	87.1	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.14	14.62	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:5	13.63	872	0.9	13.39	101	199	Idle	86.8	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.17	14.63	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:5	13.63	868	0.9	13.41	101	199	Idle	86.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.14	14.65	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:5	13.63	868	0.9	13.4	101	199	Idle	86.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.16	14.67	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:5	13.63	875	0.9	13.4	101	199	Idle	86.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.1	14.68	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:5	13.63	875	0.9	13.4	101	199	Idle	86.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.13	14.69	1	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:5	13.63	866	0.9	13.38	101	199	Idle	87	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.09	14.72	1	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:6	13.63	866	0.9	13.4	101	199	Idle	86.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.09	14.73	1	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:6	13.63	857	0.9	13.39	101	199	Idle	86.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.07	14.75	1	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:6	13.63	857	0.9	13.4	101	199	Idle	86.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.06	14.77	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:6	13.63	857	0.9	13.38	101	199	Idle	86.8	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.01	14.78	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:21:6	13.63	855	0.9	13.39	101	199	Idle	86.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.99	14.8	1.01	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:6	13.63	854	0.9	13.39	102	199	Idle	86.4	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.99	14.8	1.01	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:6	13.63	854	0.9	13.39	102	199	Idle	86.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-6.96	14.8	1.01	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:7	13.63	853	0.9	13.39	102	199	Idle	86.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-6.96	14.81	1.01	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:7	13.63	840	0.9	13.39	101	199	Idle	86.1	0	2	132	944 Turbo	0.26	Rich	1	14.6	-6.95	14.81	1.01	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:7	13.63	840	0.9	13.42	101	199	Idle	86.1	0	2	132	944 Turbo	0.31	Rich	1	14.6	-6.94	14.83	1.01	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:7	10.9	828	0.9	13.41	101	199	Idle	86.1	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.91	14.84	1.01	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:7	10.9	816	0.9	13.41	102	199	Idle	86	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.91	14.86	1.01	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:7	10.9	834	0.91	13.39	102	199	Idle	85.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-6.91	14.89	1.01	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:8	10.9	834	0.91	13.39	101	199	Idle	85.5	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.83	14.91	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:8	10.9	834	0.91	13.38	101	199	Idle	85.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.84	14.93	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:8	10.9	834	0.91	13.36	101	199	Idle	84.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-6.81	14.99	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:8	10.9	833	0.91	13.38	101	199	Idle	84.7	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.79	15.02	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:8	10.9	833	0.91	13.38	101	199	Idle	84.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-6.79	15.04	1.02	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:8	10.9	833	0.92	13.39	101	199	Idle	84.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-6.77	15.06	1.03	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:9	12.27	822	0.92	13.39	101	199	Idle	84.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.75	15.06	1.03	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:9	12.27	822	0.92	13.39	101	199	Idle	84.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.73	15.06	1.03	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:9	12.27	822	0.92	13.39	101	199	Idle	84.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.73	15.06	1.03	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:21:9	12.27	832	0.92	13.39	102	199	Idle	84.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.66	15.07	1.03	4.9	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:21:9	12.27	832	0.93	13.39	102	199	Idle	84.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.68	15.07	1.03	4.9	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:21:9	10.9	834	0.93	13.37	102	199	Idle	84.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.65	15.07	1.03	4.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:21:9	10.9	836	0.93	13.39	101	199	Idle	84.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.69	15.07	1.03	4.8	2.6	ON	28 Pin	OFF	Removed	Disabled
03:30:22:0	10.9	841	0.93	13.38	101	199	Idle	84.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.68	15.06	1.03	4.9	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:22:0	10.9	841	0.93	13.39	101	199	Idle	85	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.68	15.06	1.03	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:22:0	12.27	842	0.93	13.38	101	199	Idle	85.1	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.68	15.07	1.03	5.1	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:22:0	12.27	842	0.93	13.39	101	199	Idle	85.3	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.66	15.08	1.03	5	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:22:0	12.27	844	0.93	13.4	101	199	Idle	85.5	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.65	15.07	1.03	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:22:0	12.27	844	0.93	13.41	101	199	Idle	85.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.63	15.05	1.03	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:22:1	12.27	844	0.93	13.4	101	199	Idle	85.8	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.66	15.04	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:22:1	10.9	850	0.93	13.4	101	199	Idle	86	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.67	15.07	1.03	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:22:1	10.9	850	0.93	13.4	101	199	Idle	86	0	2	132	944 Turbo	0.8	Rich	1	14.6	-6.69	15.07	1.03	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:22:1	10.9	860	0.93	13.4	102	199	Idle	86.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.72	15.07	1.03	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:1	10.9	860	0.92	13.4	102	199	Idle	86.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.74	15.06	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:1	10.9	863	0.92	13.39	101	199	Idle	86.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.75	15.03	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:1	10.9	863	0.92	13.4	101	199	Idle	86.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.7	15.01	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:2	10.9	868	0.92	13.39	101	199	Idle	86.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.75	14.98	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:2	10.9	874	0.92	13.39	102	200	Idle	86.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.72	14.97	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:2	12.27	889	0.92	13.38	102	200	Idle	86.9	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.75	14.95	1.02	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:2	12.27	889	0.91	13.4	102	200	Idle	87	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.75	14.91	1.02	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:2	12.27	890	0.91	13.39	102	199	Idle	87.1	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.8	14.87	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:22:2	12.27	890	0.91	13.39	102	199	Idle	87.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.8	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:3	12.27	890	0.91	13.41	102	199	Idle	87.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.84	14.81	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:3	9.54	884	0.91	13.4	102	199	Idle	87.7	0	2	132	944 Turbo	0.79	Rich	1	14.6	-6.85	14.8	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:3	9.54	914	0.91	13.42	102	199	Idle	87.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.94	14.78	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:3	9.54	914	0.9	13.4	102	199	Idle	87.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.91	14.76	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:3	9.54	914	0.9	13.4	101	199	Idle	87.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.98	14.74	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:3	9.54	913	0.9	13.39	101	199	Idle	87.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.95	14.73	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:4	9.54	913	0.9	13.41	101	199	Idle	87.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.97	14.72	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:4	9.54	914	0.9	13.39	101	199	Idle	87.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.96	14.7	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:4	9.54	914	0.9	13.43	101	199	Idle	87.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7	14.7	1	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:4	10.9	904	0.9	13.41	101	200	Idle	87.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.98	14.69	1	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:4	10.9	894	0.9	13.41	102	200	Idle	87.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.99	14.69	1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:4	10.9	896	0.9	13.4	102	200	Idle	87.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.01	14.69	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:4	10.9	896	0.9	13.41	102	199	Idle	87.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.05	14.68	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:5	10.9	899	0.9	13.38	101	199	Idle	87.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.05	14.68	1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:5	10.9	902	0.9	13.39	101	199	Idle	88	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.07	14.67	1	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:5	10.9	902	0.9	13.4	101	199	Idle	88	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.09	14.67	1	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:5	10.9	895	0.9	13.4	102	199	Idle	88	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.09	14.66	1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:5	9.54	899	0.9	13.4	102	199	Idle	88.1	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.09	14.65	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:5	9.54	899	0.9	13.4	102	199	Idle	88.1	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.09	14.65	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:6	9.54	905	0.9	13.41	102	200	Idle	88.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.12	14.65	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:6	9.54	911	0.9	13.4	102	200	Idle	88.2	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.08	14.62	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:6	9.54	916	0.9	13.39	102	200	Idle	88.2	0	2	132	944 Turbo	0.35	Rich	1	14.6	-7.13	14.63	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:6	9.54	916	0.9	13.4	102	199	Idle	88.2	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.12	14.63	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:6	9.54	914	0.9	13.39	102	199	Idle	88.4	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.18	14.64	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:6	9.54	912	0.9	13.41	102	199	Idle	88.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.14	14.65	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:6	9.54	912	0.9	13.4	102	199	Idle	88.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.2	14.66	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:7	9.54	902	0.9	13.39	102	199	Idle	88.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.17	14.67	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:7	9.54	902	0.9	13.4	101	199	Idle	88.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.21	14.68	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:7	9.54	905	0.89	13.4	101	199	Idle	88.7	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.19	14.68	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:7	9.54	905	0.89	13.4	101	199	Idle	88.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.22	14.7	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:7	9.54	903	0.89	13.38	101	199	Idle	88.7	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.16	14.7	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:7	9.54	903	0.89	13.39	101	199	Idle	88.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.21	14.72	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:8	9.54	902	0.89	13.37	101	199	Idle	88.8	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.19	14.73	1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:8	9.54	900	0.89	13.4	102	199	Idle	88.8	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.21	14.73	1	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:8	8.18	868	0.89	13.4	102	199	Idle	88.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.2	14.75	1	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:8	8.18	868	0.89	13.4	101	199	Idle	88.7	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.22	14.76	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:8	8.18	878	0.89	13.4	101	199	Idle	88.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.24	14.77	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:22:8	8.18	889	0.89	13.39	101	199	Idle	88.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.17	14.79	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:9	8.18	873	0.89	13.38	101	199	Idle	88.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.2	14.8	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:9	8.18	873	0.89	13.4	101	199	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.18	14.8	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:9	8.18	880	0.89	13.39	101	199	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.18	14.79	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:9	8.18	887	0.89	13.4	102	199	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.16	14.8	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:9	8.18	887	0.89	13.39	102	200	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.18	14.81	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:9	8.18	887	0.89	13.39	102	200	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.14	14.82	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:22:9	8.18	878	0.89	13.39	101	200	Idle	88.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.16	14.85	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:0	8.18	868	0.89	13.38	101	199	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.11	14.87	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:0	8.18	868	0.89	13.4	101	199	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.15	14.9	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:0	8.18	874	0.89	13.4	102	199	Idle	88.1	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.12	14.93	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:0	8.18	874	0.89	13.4	102	199	Idle	88.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.12	14.98	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:0	8.18	881	0.89	13.39	102	199	Idle	88	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.1	15.04	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:0	8.18	881	0.89	13.4	101	199	Idle	88	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.13	15.09	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:1	10.9	886	0.89	13.39	101	199	Idle	88	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.12	15.13	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:1	10.9	886	0.89	13.39	101	199	Idle	88.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.1	15.16	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:1	10.9	886	0.9	13.39	101	199	Idle	88.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.12	15.17	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:1	10.9	863	0.9	13.4	102	199	Idle	88.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.07	15.21	1.04	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:1	10.9	872	0.9	13.4	102	199	Idle	88.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.08	15.21	1.04	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:1	9.54	882	0.9	13.39	102	199	Idle	88.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.06	15.21	1.04	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:23:1	9.54	882	0.9	13.4	102	199	Idle	88.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.09	15.22	1.04	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:2	9.54	884	0.9	13.4	102	199	Idle	88.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.07	15.21	1.04	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:2	9.54	884	0.9	13.41	102	199	Idle	88.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.12	15.22	1.04	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:2	9.54	877	0.9	13.39	102	199	Idle	88.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.08	15.1	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:2	9.54	870	0.9	13.41	102	199	Idle	88.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.12	15.1	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:2	9.54	875	0.89	13.39	102	200	Idle	88.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.09	15.1	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:2	9.54	875	0.89	13.41	102	200	Idle	88.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.13	15.09	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:3	9.54	874	0.89	13.39	102	200	Idle	88.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.11	15.1	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:3	9.54	874	0.89	13.41	102	200	Idle	88.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.12	15.1	1.03	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:3	9.54	879	0.89	13.38	102	200	Idle	88.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.12	15.11	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:3	9.54	879	0.89	13.4	102	199	Idle	88.8	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.11	15.12	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:3	9.54	880	0.89	13.39	102	199	Idle	88.7	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.12	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:3	9.54	880	0.89	13.39	102	199	Idle	88.7	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.12	15.23	1.04	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:4	9.54	866	0.89	13.39	102	200	Idle	88.7	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.13	15.23	1.04	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:4	9.54	866	0.89	13.39	102	200	Idle	88.6	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.08	15.23	1.04	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:4	9.54	866	0.89	13.39	101	200	Idle	88.5	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.1	15.23	1.04	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:4	9.54	877	0.89	13.4	101	200	Idle	88.4	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.07	15.24	1.04	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:4	9.54	877	0.89	13.39	101	200	Idle	88.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.09	15.23	1.04	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:4	9.54	881	0.89	13.38	101	200	Idle	88.4	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.06	15.23	1.04	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:4	9.54	886	0.89	13.39	102	199	Idle	88.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.12	15.22	1.04	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:5	9.54	891	0.89	13.37	102	199	Idle	88.5	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.1	15.22	1.04	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:5	9.54	891	0.89	13.4	102	199	Idle	88.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.13	15.22	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:5	9.54	890	0.89	13.38	102	200	Idle	88.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.12	15.21	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:5	9.54	890	0.89	13.4	102	200	Idle	88.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.13	15.2	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:5	8.18	896	0.89	13.38	102	200	Idle	88.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.14	15.19	1.04	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:5	8.18	901	0.89	13.39	102	200	Idle	88.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.11	15.19	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:6	8.18	907	0.89	13.37	102	200	Idle	89	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.14	15.17	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:6	8.18	907	0.89	13.4	102	199	Idle	89	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.14	15.17	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:6	9.54	889	0.89	13.39	102	199	Idle	89.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.16	15.15	1.03	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:6	9.54	871	0.89	13.38	102	199	Idle	89.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.15	15.13	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:6	9.54	871	0.89	13.4	102	200	Idle	89.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.16	15.12	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:6	9.54	883	0.89	13.38	102	200	Idle	89.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.13	15.11	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:6	9.54	883	0.88	13.39	102	200	Idle	89.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.16	15.1	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:7	9.54	888	0.88	13.37	102	199	Idle	89.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.15	15.08	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:7	9.54	892	0.88	13.39	102	199	Idle	89.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.18	15.06	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:7	9.54	873	0.88	13.39	102	199	Idle	89.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.14	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:7	9.54	873	0.88	13.39	102	200	Idle	89.4	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.19	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:7	8.18	872	0.88	13.37	102	200	Idle	89.4	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.16	15	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:7	8.18	870	0.88	13.38	102	200	Idle	89.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.18	15	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:8	8.18	860	0.88	13.36	102	200	Idle	89.1	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.18	14.99	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:8	8.18	860	0.88	13.37	102	200	Idle	89	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.18	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:8	8.18	867	0.88	13.37	102	200	Idle	88.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.23	14.96	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:8	9.54	867	0.88	13.38	102	199	Idle	88.8	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.15	14.94	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:8	9.54	867	0.88	13.39	102	199	Idle	88.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.17	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:23:8	9.54	854	0.88	13.38	102	200	Idle	88.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.09	14.96	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:9	9.54	854	0.88	13.38	102	200	Idle	88.1	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.07	14.93	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:9	10.9	855	0.88	13.36	102	200	Idle	88.1	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.05	14.9	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:9	10.9	855	0.88	13.38	102	200	Idle	88	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.04	14.86	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:9	10.9	843	0.88	13.36	102	200	Idle	87.8	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7	14.72	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:9	10.9	843	0.88	13.38	102	200	Idle	87.5	0	2	132	944 Turbo	0.35	Lean	1	14.6	-6.99	14.7	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:9	10.9	862	0.88	13.38	102	200	Idle	87.4	0	2	132	944 Turbo	0.3	Lean	1	14.6	-6.99	14.68	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:23:9	10.9	862	0.88	13.39	102	200	Idle	87.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-6.97	14.67	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:0	10.9	862	0.89	13.37	102	200	Idle	87.4	0	2	132	944 Turbo	0.2	Lean	1	14.6	-6.96	14.65	1	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:0	10.9	849	0.89	13.38	102	200	Idle	87.5	0	2	132	944 Turbo	0.18	Lean	1	14.6	-6.96	14.64	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:0	10.9	848	0.89	13.39	102	200	Idle	87.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-6.98	14.62	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:0	9.54	846	0.89	13.39	102	200	Idle	87.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.96	14.61	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:0	9.54	846	0.89	13.39	102	199	Idle	87.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.98	14.61	0.99	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:0	9.54	855	0.89	13.38	102	199	Idle	87.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-6.97	14.6	0.99	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:24:1	9.54	855	0.89	13.39	102	199	Idle	88	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.96	14.73	1	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:24:1	9.54	854	0.89	13.38	102	199	Idle	88	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.94	14.76	1.01	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:24:1	9.54	852	0.89	13.39	102	199	Idle	88.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.94	14.76	1.01	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:24:1	9.54	867	0.89	13.38	102	199	Idle	88.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-6.95	14.78	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:1	9.54	867	0.89	13.4	102	200	Idle	88.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.91	14.79	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:1	9.54	860	0.89	13.37	102	200	Idle	88.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-6.96	14.8	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:1	9.54	852	0.89	13.4	102	200	Idle	89	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.93	14.71	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:2	9.54	852	0.89	13.39	102	200	Idle	89.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.98	14.72	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:2	9.54	865	0.89	13.41	102	200	Idle	89.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.96	14.74	1	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:2	9.54	872	0.89	13.4	102	200	Idle	89.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.96	14.73	1	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:2	9.54	880	0.89	13.4	102	200	Idle	89.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-6.95	14.71	1	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:2	9.54	880	0.89	13.4	102	200	Idle	89.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.97	14.71	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:2	9.54	876	0.89	13.38	102	199	Idle	89.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.96	14.72	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:3	9.54	876	0.89	13.39	102	199	Idle	89.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-6.96	14.72	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:3	9.54	876	0.89	13.38	102	199	Idle	89.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7	14.73	1	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:3	9.54	876	0.89	13.39	102	200	Idle	89.6	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7	14.84	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:3	9.54	877	0.89	13.38	102	200	Idle	89.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.01	14.87	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:3	9.54	877	0.88	13.4	102	200	Idle	89.6	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.02	14.9	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:3	8.18	886	0.88	13.39	102	200	Idle	89.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.04	14.92	1.02	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:4	8.18	894	0.88	13.4	102	200	Idle	89.6	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.05	14.96	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:4	8.18	890	0.88	13.39	102	200	Idle	89.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.08	14.98	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:4	8.18	890	0.88	13.4	102	199	Idle	89.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.06	15.01	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:4	8.18	877	0.88	13.4	102	199	Idle	89.6	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.12	15.02	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:4	6.81	864	0.88	13.37	102	199	Idle	89.5	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.09	15.03	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:4	6.81	864	0.88	13.39	102	200	Idle	89.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.11	15.05	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:4	6.81	887	0.88	13.39	102	200	Idle	89.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.08	15.04	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:5	6.81	886	0.88	13.39	102	200	Idle	88.9	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.11	15.04	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:5	6.81	884	0.88	13.37	102	200	Idle	88.6	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.07	15.04	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:5	6.81	884	0.88	13.39	102	200	Idle	88.4	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.11	15.05	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:5	6.81	875	0.88	13.4	102	199	Idle	88.4	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.09	15.05	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:5	6.81	875	0.88	13.4	102	199	Idle	88.4	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.09	15.07	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:5	8.18	871	0.88	13.39	102	199	Idle	88.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.08	15.07	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:6	8.18	867	0.88	13.41	102	199	Idle	88.4	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.06	15.07	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:6	8.18	851	0.88	13.39	102	199	Idle	88.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.08	15.06	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:24:6	8.18	851	0.88	13.4	102	199	Idle	88.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.04	15.07	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:6	8.18	851	0.88	13.39	102	200	Idle	88.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.06	15.07	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:6	8.18	860	0.88	13.39	102	200	Idle	88	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.01	15.09	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:6	8.18	860	0.88	13.39	102	200	Idle	88	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.05	15.09	1.03	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:6	8.18	856	0.89	13.38	102	200	Idle	87.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.01	15.09	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:7	8.18	851	0.89	13.39	102	200	Idle	87.9	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.02	15.08	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:7	9.54	847	0.89	13.39	102	200	Idle	87.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.01	15.08	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:7	9.54	847	0.89	13.39	102	200	Idle	87.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.99	15.09	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:7	9.54	848	0.89	13.37	102	200	Idle	88.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-6.97	15.08	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:7	9.54	848	0.89	13.39	102	200	Idle	88.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.95	15.08	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:7	9.54	853	0.89	13.38	102	199	Idle	88	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.96	15.07	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:8	9.54	853	0.89	13.37	102	199	Idle	88	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.93	15.05	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:8	9.54	856	0.89	13.38	102	199	Idle	88.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-6.96	15.05	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:8	9.54	859	0.9	13.4	102	200	Idle	88.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-6.95	15.05	1.03	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:8	9.54	859	0.89	13.4	102	200	Idle	88.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-6.98	15.07	1.03	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:8	9.54	862	0.89	13.39	102	200	Idle	88.5	0	2	132	944 Turbo	0.67	Rich	1	14.6	-6.94	15.07	1.03	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:8	9.54	862	0.89	13.4	102	200	Idle	88.6	0	2	132	944 Turbo	0.62	Rich	1	14.6	-6.97	15.05	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:9	9.54	869	0.89	13.39	102	200	Idle	88.7	0	2	132	944 Turbo	0.56	Rich	1	14.6	-6.96	15.01	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:9	9.54	869	0.89	13.4	102	200	Idle	88.9	0	2	132	944 Turbo	0.49	Rich	1	14.6	-6.95	14.99	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:9	9.54	880	0.89	13.38	102	200	Idle	89.3	0	2	132	944 Turbo	0.43	Rich	1	14.6	-6.99	14.97	1.02	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:9	9.54	880	0.89	13.4	102	200	Idle	89.3	0	2	132	944 Turbo	0.37	Rich	1	14.6	-6.96	14.96	1.02	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:9	9.54	880	0.89	13.37	102	200	Idle	89.9	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.01	14.95	1.02	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:9	9.54	884	0.89	13.4	102	200	Idle	89.9	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.04	14.92	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:24:9	9.54	884	0.89	13.39	102	200	Idle	89.9	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.06	14.85	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:25:0	9.54	884	0.88	13.39	102	200	Idle	90	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.05	14.83	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:0	9.54	884	0.88	13.38	102	200	Idle	90	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.12	14.82	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:0	9.54	882	0.88	13.39	102	200	Idle	90	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.06	14.8	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:0	9.54	882	0.88	13.39	102	200	Idle	90.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.13	14.79	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:0	8.18	894	0.88	13.4	102	200	Idle	90.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.1	14.79	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:0	8.18	900	0.88	13.39	102	200	Idle	90	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.14	14.78	1.01	4.5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:1	8.18	905	0.88	13.39	102	200	Idle	90.1	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.13	14.77	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:1	8.18	905	0.88	13.4	102	199	Idle	90.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.16	14.77	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:1	9.54	886	0.88	13.39	102	199	Idle	90.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.13	14.77	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:1	9.54	886	0.88	13.4	102	199	Idle	90.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.1	14.77	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:1	9.54	890	0.88	13.38	102	200	Idle	90.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.12	14.78	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:1	9.54	890	0.87	13.39	102	200	Idle	90.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.12	14.79	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:1	9.54	890	0.87	13.38	102	200	Idle	90.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.16	14.8	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:2	9.54	890	0.87	13.4	102	199	Idle	90.4	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.2	14.81	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:2	9.54	893	0.87	13.38	102	199	Idle	90.4	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.22	14.81	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:2	9.54	896	0.87	13.4	102	199	Idle	90.4	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.18	14.82	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:2	8.18	894	0.87	13.39	102	200	Idle	90.4	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.25	14.81	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:2	8.18	894	0.87	13.39	102	200	Idle	90.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.23	14.8	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:2	8.18	895	0.87	13.39	102	200	Idle	90.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.23	14.8	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:3	8.18	896	0.87	13.4	102	200	Idle	90.3	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.22	14.82	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:3	8.18	888	0.87	13.39	102	200	Idle	90.4	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.23	14.83	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:3	8.18	888	0.87	13.4	102	200	Idle	90.4	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.21	14.84	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:3	8.18	891	0.87	13.39	102	200	Idle	90.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.26	14.86	1.01	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:3	8.18	894	0.87	13.37	102	200	Idle	90.5	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.23	14.89	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:3	8.18	894	0.87	13.38	102	200	Idle	90.5	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.24	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:4	9.54	881	0.87	13.38	102	199	Idle	90.5	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.24	14.95	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:4	9.54	881	0.87	13.39	102	199	Idle	90.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.22	14.98	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:4	9.54	876	0.87	13.38	102	199	Idle	90.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.23	15	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:4	9.54	871	0.87	13.4	102	199	Idle	90.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.21	15.03	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:4	9.54	868	0.87	13.38	102	200	Idle	90.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.22	15.04	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:4	9.54	868	0.87	13.39	102	200	Idle	90.4	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.23	15.04	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:4	9.54	868	0.87	13.38	102	199	Idle	90.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.23	15.05	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:5	9.54	856	0.87	13.38	102	199	Idle	90.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.19	15.05	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:5	10.9	856	0.87	13.38	102	199	Idle	90.4	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.2	15.04	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:5	10.9	856	0.87	13.4	102	200	Idle	90.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.17	15.04	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:5	10.9	856	0.87	13.4	102	200	Idle	90.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.16	15.03	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:25:5	10.9	851	0.87	13.39	102	200	Idle	89.9	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.1	15.02	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:5	10.9	851	0.87	13.4	102	200	Idle	89.5	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.12	15.01	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:6	9.54	854	0.87	13.39	102	200	Idle	89.4	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.09	15.01	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:6	9.54	858	0.87	13.4	102	200	Idle	89.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.1	15	1.02	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:6	9.54	848	0.87	13.39	102	200	Idle	89	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.11	15	1.02	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:6	9.54	848	0.87	13.4	102	200	Idle	88.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.11	15	1.02	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:6	10.9	852	0.87	13.38	102	200	Idle	88.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.12	15.01	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:6	10.9	855	0.88	13.39	102	200	Idle	88.7	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.05	15.02	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:6	10.9	855	0.88	13.39	102	200	Idle	88.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.05	15.01	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:7	10.9	856	0.88	13.39	102	200	Idle	88.7	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.01	15.01	1.02	4.8	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:25:7	10.9	859	0.88	13.4	102	200	Idle	88.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.04	15	1.02	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:25:7	9.54	862	0.88	13.4	102	200	Idle	88.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.04	14.99	1.02	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:25:7	9.54	862	0.88	13.4	102	200	Idle	88.9	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.08	14.98	1.02	4.7	2.5	ON	28 Pin	OFF	Removed	Disabled
03:30:25:7	9.54	869	0.88	13.39	102	200	Idle	89	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.08	14.97	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:7	9.54	869	0.88	13.41	102	200	Idle	89.1	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.07	14.93	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:8	9.54	860	0.88	13.38	102	200	Idle	89.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.05	14.9	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:8	9.54	860	0.88	13.39	102	200	Idle	89.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.04	14.89	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:8	9.54	862	0.88	13.39	102	200	Idle	89.9	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.04	14.88	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:8	9.54	865	0.88	13.39	102	200	Idle	90	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.02	14.88	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:8	9.54	865	0.88	13.39	102	200	Idle	90.1	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.06	14.87	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:8	9.54	856	0.88	13.38	102	200	Idle	90.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.03	14.86	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:9	9.54	856	0.88	13.39	102	200	Idle	90.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.08	14.84	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:25:9	9.54	858	0.88	13.4	102	200	Idle	90.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.06	14.82	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:9	9.54	859	0.88	13.4	102	200	Idle	90.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.06	14.81	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:9	9.54	861	0.88	13.38	102	200	Idle	90.4	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.06	14.82	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:9	9.54	861	0.88	13.39	102	200	Idle	90.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.08	14.82	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:9	9.54	862	0.88	13.38	102	200	Idle	90.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.05	14.83	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:25:9	9.54	862	0.88	13.39	102	200	Idle	90.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.06	14.84	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:0	9.54	864	0.88	13.39	102	200	Idle	90.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.07	14.85	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:0	9.54	864	0.87	13.4	102	200	Idle	90.1	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.06	14.88	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:0	9.54	867	0.87	13.38	102	199	Idle	90.1	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.08	14.91	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:0	9.54	870	0.87	13.39	102	199	Idle	90.1	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.06	14.94	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:0	9.54	870	0.87	13.38	102	199	Idle	90.1	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.1	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:0	9.54	867	0.87	13.39	102	200	Idle	90.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.08	15.01	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:1	9.54	864	0.87	13.39	102	200	Idle	90.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.1	15.02	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:1	9.54	861	0.87	13.38	102	200	Idle	90.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.09	15.04	1.02	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:1	9.54	861	0.87	13.39	102	200	Idle	90.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.11	15.05	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:1	9.54	868	0.87	13.4	102	200	Idle	90.4	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.08	15.06	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:1	9.54	868	0.87	13.4	102	200	Idle	90.4	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.09	15.08	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:1	9.54	858	0.87	13.37	102	199	Idle	90.5	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.06	15.09	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:1	9.54	858	0.87	13.38	102	199	Idle	90.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.07	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:2	9.54	855	0.87	13.39	102	199	Idle	90.6	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.08	15.11	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:2	9.54	852	0.87	13.36	102	199	Idle	90.7	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.06	15.11	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:2	9.54	852	0.87	13.37	102	199	Idle	90.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.07	15.12	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:2	9.54	860	0.87	13.37	102	199	Idle	90.7	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.08	15.13	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:2	9.54	851	0.87	13.39	102	200	Idle	90.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.09	15.13	1.03	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:2	10.9	851	0.87	13.38	102	200	Idle	90.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.07	15.13	1.03	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:3	10.9	842	0.87	13.4	102	200	Idle	90.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.1	15.11	1.03	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:3	10.9	846	0.87	13.39	102	200	Idle	90.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.06	15.11	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:3	10.9	846	0.87	13.4	102	200	Idle	90.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.06	15.09	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:3	10.9	846	0.87	13.4	102	200	Idle	90.4	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.06	15.08	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:3	10.9	842	0.87	13.41	102	200	Idle	90.3	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.06	15.07	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:3	10.9	839	0.87	13.39	102	200	Idle	90.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.08	15.05	1.03	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:4	10.9	839	0.87	13.39	102	200	Idle	90.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.06	15.03	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:4	10.9	839	0.87	13.38	102	200	Idle	90.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.08	15.01	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:4	10.9	857	0.87	13.38	102	200	Idle	90.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.03	15.01	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:4	10.9	857	0.87	13.39	102	200	Idle	90.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.05	15.02	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:4	10.9	852	0.86	13.37	102	200	Idle	90.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.02	15.04	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:4	10.9	847	0.86	13.39	102	200	Idle	90.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.05	15.03	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:4	10.9	863	0.86	13.36	102	200	Idle	90.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.05	15.02	1.02	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:5	10.9	863	0.86	13.39	102	200	Idle	90.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.06	15.02	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:5	10.9	862	0.86	13.37	102	200	Idle	90.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.08	15	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:5	10.9	860	0.86	13.38	102	200	Idle	90.4	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.07	14.98	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:5	9.54	860	0.86	13.39	102	200	Idle	90.5	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.09	14.96	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:5	9.54	873	0.86	13.38	102	200	Idle	90.5	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.06	14.95	1.02	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:5	9.54	878	0.86	13.39	102	200	Idle	90.5	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.1	14.92	1.02	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:6	9.54	883	0.86	13.38	102	200	Idle	90.7	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.11	14.87	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:6	9.54	883	0.86	13.38	102	200	Idle	90.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.12	14.85	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:6	9.54	869	0.86	13.38	102	200	Idle	90.8	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.13	14.84	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:6	9.54	869	0.86	13.38	102	200	Idle	90.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.13	14.83	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:6	9.54	877	0.86	13.37	102	200	Idle	90.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.12	14.82	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:6	9.54	877	0.86	13.39	102	200	Idle	90.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.12	14.81	1.01	4.6	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:6	9.54	885	0.86	13.37	102	200	Idle	90.9	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.11	14.81	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:7	9.54	885	0.86	13.4	102	200	Idle	90.9	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.1	14.81	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:7	9.54	885	0.86	13.39	102	200	Idle	90.9	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.15	14.81	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:7	9.54	859	0.86	13.4	102	200	Idle	90.9	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.12	14.81	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:7	9.54	873	0.86	13.38	102	200	Idle	90.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.16	14.81	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:7	9.54	873	0.86	13.39	102	200	Idle	90.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.14	14.81	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:7	9.54	873	0.86	13.38	102	200	Idle	90.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.14	14.81	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:8	9.54	874	0.86	13.39	102	200	Idle	90.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.1	14.81	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:26:8	9.54	863	0.86	13.39	102	200	Idle	90.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.14	14.82	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:8	9.54	863	0.86	13.38	102	200	Idle	90.7	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.12	14.82	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:8	9.54	863	0.86	13.4	102	200	Idle	90.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.16	14.82	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:8	9.54	863	0.86	13.38	102	200	Idle	90.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.15	14.81	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:8	9.54	863	0.86	13.4	102	200	Idle	90.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.17	14.81	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:9	9.54	872	0.86	13.37	102	200	Idle	90.7	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.15	14.81	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:9	9.54	880	0.86	13.37	102	200	Idle	90.6	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.16	14.82	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:26:9	9.54	864	0.86	13.36	102	200	Idle	90.6	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.15	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:9	9.54	864	0.86	13.37	102	200	Idle	90.6	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.11	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:9	9.54	870	0.86	13.38	102	200	Idle	90.7	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.16	14.88	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:9	8.18	876	0.86	13.39	102	200	Idle	90.8	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.14	14.89	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:26:9	8.18	889	0.86	13.38	102	200	Idle	91	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.18	14.92	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:0	8.18	889	0.86	13.38	102	200	Idle	91	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.19	14.95	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:0	9.54	894	0.86	13.38	102	200	Idle	91	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.22	14.98	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:0	9.54	899	0.86	13.37	102	200	Idle	91	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.23	15.01	1.02	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:0	9.54	899	0.86	13.39	102	200	Idle	91.1	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.24	15.03	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:0	9.54	903	0.86	13.39	102	200	Idle	91.1	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.22	15.04	1.02	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:0	9.54	912	0.86	13.4	102	200	Idle	91.1	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.26	15.05	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:1	9.54	921	0.86	13.38	102	200	Idle	91.1	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.22	15.05	1.03	4.5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:1	9.54	921	0.86	13.39	102	200	Idle	91.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.27	15.05	1.03	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:1	9.54	910	0.86	13.38	102	200	Idle	91.4	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.27	15.05	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:1	9.54	910	0.86	13.4	102	200	Idle	91.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.27	15.06	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:1	6.81	910	0.86	13.39	102	200	Idle	91.5	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.27	15.04	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:1	6.81	909	0.86	13.4	102	200	Idle	91.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.3	15.04	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:1	6.81	927	0.86	13.39	102	200	Idle	91.6	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.28	15.03	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:2	6.81	927	0.86	13.4	102	200	Idle	91.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.33	15.02	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:2	6.81	932	0.86	13.39	102	200	Idle	91.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.3	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:2	6.81	936	0.86	13.39	102	200	Idle	91.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.31	15.01	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:2	6.81	944	0.86	13.37	102	200	Idle	92	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.39	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:2	6.81	944	0.86	13.39	102	200	Idle	92	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.44	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:2	8.18	934	0.86	13.39	102	200	Idle	92.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.46	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:3	8.18	923	0.86	13.39	102	200	Idle	92.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.45	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:3	8.18	908	0.86	13.38	102	200	Idle	92.3	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.45	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:3	8.18	908	0.86	13.4	102	200	Idle	92.4	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.47	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:3	8.18	918	0.86	13.38	102	200	Idle	92.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.45	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:3	8.18	927	0.86	13.4	102	200	Idle	92.5	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.45	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:3	8.18	905	0.86	13.39	102	200	Idle	92.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.49	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:4	8.18	905	0.86	13.4	102	200	Idle	92.6	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.46	14.97	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:4	8.18	910	0.86	13.37	102	200	Idle	92.7	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.45	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:4	8.18	914	0.86	13.39	102	200	Idle	92.8	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.46	14.94	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:4	8.18	908	0.86	13.39	102	200	Idle	92.8	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.48	14.78	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:4	8.18	908	0.86	13.38	102	200	Idle	92.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.46	14.75	1	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:4	8.18	903	0.86	13.39	102	200	Idle	92.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.49	14.72	1	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:4	8.18	903	0.86	13.37	102	200	Idle	92.9	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.48	14.72	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:5	8.18	903	0.86	13.38	102	200	Idle	92.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.52	14.71	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:5	8.18	906	0.86	13.37	102	200	Idle	92.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.48	14.69	1	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:5	8.18	906	0.86	13.38	102	200	Idle	93	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.51	14.69	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:5	9.54	905	0.86	13.37	102	200	Idle	93	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.47	14.69	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:5	9.54	905	0.86	13.39	102	200	Idle	93	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.53	14.7	1	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:27:5	9.54	895	0.86	13.37	102	200	Idle	93	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.49	14.7	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:6	9.54	895	0.85	13.4	102	200	Idle	93.1	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.51	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:6	9.54	896	0.85	13.38	102	200	Idle	92.9	0	2	132	944 Turbo	0.39	Rich	1	14.6	-7.51	14.8	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:6	9.54	896	0.85	13.39	102	200	Idle	92.8	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.48	14.79	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:6	9.54	884	0.85	13.38	102	200	Idle	92.8	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.48	14.78	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:6	9.54	884	0.85	13.41	102	200	Idle	92.8	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.47	14.78	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:6	9.54	882	0.85	13.39	102	200	Idle	92.8	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.46	14.77	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:6	9.54	880	0.85	13.41	102	200	Idle	92.7	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.47	14.76	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:7	9.54	883	0.85	13.41	102	200	Idle	92.7	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.48	14.74	1	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:27:7	9.54	883	0.85	13.4	102	200	Idle	92.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.45	14.73	1	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:7	8.18	883	0.85	13.39	102	200	Idle	92.6	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.47	14.73	1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:7	8.18	883	0.85	13.4	102	200	Idle	92.5	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.45	14.74	1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:7	8.18	879	0.85	13.39	102	200	Idle	92.4	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.45	14.74	1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:7	8.18	879	0.85	13.4	102	200	Idle	92.4	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.42	14.75	1	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:8	8.18	876	0.85	13.4	102	200	Idle	92.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.45	14.76	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:8	8.18	874	0.85	13.4	102	200	Idle	92.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.46	14.77	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:8	8.18	874	0.85	13.4	102	200	Idle	92.4	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.47	14.78	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:8	8.18	889	0.85	13.39	102	200	Idle	92.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.44	14.8	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:8	8.18	889	0.85	13.39	102	200	Idle	92.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.47	14.81	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:8	8.18	886	0.85	13.37	102	200	Idle	92.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.45	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:9	8.18	883	0.85	13.4	102	200	Idle	92.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.45	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:9	8.18	890	0.85	13.37	102	200	Idle	92.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.42	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:9	8.18	890	0.85	13.4	102	200	Idle	92.5	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.44	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:9	8.18	879	0.85	13.38	102	200	Idle	92.6	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.45	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:9	8.18	879	0.85	13.41	102	200	Idle	92.5	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.41	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:9	8.18	889	0.85	13.39	102	200	Idle	92.6	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.43	14.84	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:27:9	8.18	889	0.85	13.38	102	200	Idle	92.7	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.43	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:0	9.54	896	0.85	13.36	102	200	Idle	92.7	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.42	14.87	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:0	9.54	903	0.85	13.38	102	200	Idle	92.7	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.39	14.88	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:0	9.54	903	0.85	13.37	102	200	Idle	92.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.41	14.91	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:0	9.54	886	0.85	13.38	102	200	Idle	92.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.42	14.94	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:0	9.54	886	0.85	13.4	102	200	Idle	92.7	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.45	14.98	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:0	8.18	880	0.85	13.4	102	200	Idle	92.8	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.4	15.01	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:1	8.18	880	0.85	13.4	102	200	Idle	92.8	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.44	15.02	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:1	8.18	885	0.85	13.38	102	200	Idle	92.7	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.4	15.03	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:1	8.18	885	0.85	13.4	102	200	Idle	92.7	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.41	15.04	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:1	8.18	892	0.85	13.38	102	200	Idle	92.7	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.39	15.06	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:1	8.18	892	0.85	13.39	102	200	Idle	92.8	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.42	15.07	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:1	8.18	892	0.84	13.38	102	200	Idle	92.9	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.41	15.08	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:1	8.18	860	0.84	13.4	102	200	Idle	92.9	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.43	15.09	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:2	9.54	883	0.84	13.38	102	200	Idle	92.9	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.41	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:2	9.54	883	0.84	13.4	102	200	Idle	92.9	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.39	15.1	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:2	9.54	883	0.84	13.39	102	200	Idle	92.9	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.39	15.1	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:2	9.54	883	0.84	13.39	102	200	Idle	92.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.36	15.11	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:2	9.54	867	0.84	13.39	102	200	Idle	92.9	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.38	15.12	1.03	5.2	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:2	9.54	867	0.84	13.39	102	200	Idle	92.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.36	15.12	1.03	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:3	9.54	867	0.84	13.38	102	200	Idle	92.9	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.4	15.11	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:3	9.54	868	0.84	13.38	102	200	Idle	93	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.36	15.12	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:3	9.54	868	0.84	13.38	102	200	Idle	93	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.37	15.11	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:3	9.54	863	0.84	13.38	102	200	Idle	93.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.36	15.11	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:3	9.54	858	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.37	15.09	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:3	9.54	869	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.37	15.08	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:4	9.54	869	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.4	15.08	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:4	9.54	870	0.84	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.37	15.06	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:4	9.54	871	0.84	13.39	102	200	Idle	93.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.38	15.04	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:4	9.54	871	0.84	13.38	102	200	Idle	93.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.39	15.03	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:4	9.54	871	0.84	13.39	102	200	Idle	93.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.34	15.01	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:4	9.54	858	0.84	13.39	102	200	Idle	93.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.37	15	1.02	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:4	8.18	844	0.84	13.39	102	200	Idle	93.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.33	15	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:5	8.18	844	0.84	13.4	102	200	Idle	93	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.35	15.01	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:5	8.18	862	0.84	13.39	102	200	Idle	92.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.32	15.01	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:5	8.18	862	0.84	13.39	102	200	Idle	92.8	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.33	15.01	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:5	8.18	863	0.84	13.37	102	200	Idle	92.7	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.31	15	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:5	8.18	864	0.84	13.39	102	200	Idle	92.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.35	15	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:5	8.18	858	0.84	13.37	102	200	Idle	92.6	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.31	14.98	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:6	8.18	858	0.84	13.38	102	200	Idle	92.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.3	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:6	8.18	854	0.84	13.38	102	200	Idle	92.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.34	14.97	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:28:6	8.18	854	0.84	13.38	102	200	Idle	92.5	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.34	14.96	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:6	8.18	844	0.84	13.38	102	200	Idle	92.1	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.3	14.9	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:6	8.18	844	0.84	13.37	102	200	Idle	92	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.21	14.88	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:6	8.18	844	0.84	13.39	102	200	Idle	91.9	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.25	14.86	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:6	8.18	844	0.84	13.36	102	200	Idle	91.8	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.22	14.85	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:7	8.18	844	0.84	13.39	102	200	Idle	91.5	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.24	14.84	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:28:7	8.18	834	0.84	13.39	102	200	Idle	91.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.24	14.84	1.01	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:7	8.18	834	0.84	13.4	102	200	Idle	91.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.25	14.84	1.01	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:7	8.18	813	0.84	13.39	102	200	Idle	91.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.23	14.83	1.01	5.2	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:7	10.9	813	0.84	13.39	102	200	Idle	91.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.18	14.84	1.01	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:7	10.9	814	0.84	13.39	102	200	Idle	91	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.16	14.82	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:8	10.9	816	0.84	13.39	102	200	Idle	90.9	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.15	14.82	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:8	10.9	816	0.84	13.39	102	200	Idle	90.7	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.14	14.82	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:8	10.9	829	0.85	13.38	102	200	Idle	90.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.11	14.82	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:8	10.9	829	0.85	13.39	102	200	Idle	90.5	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.1	14.81	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:8	10.9	829	0.85	13.37	102	200	Idle	90.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.08	14.81	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:8	10.9	830	0.85	13.38	102	200	Idle	90.6	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.07	14.79	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:9	10.9	832	0.85	13.37	102	200	Idle	90.5	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.06	14.8	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:9	9.54	835	0.85	13.37	102	200	Idle	90.5	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.04	14.78	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:9	9.54	835	0.85	13.37	102	200	Idle	90.7	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.06	14.78	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:9	9.54	836	0.85	13.37	102	200	Idle	91.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.04	14.78	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:9	9.54	836	0.85	13.37	102	200	Idle	91.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.05	14.77	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:9	10.9	842	0.86	13.38	102	200	Idle	91.4	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.07	14.77	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:28:9	10.9	848	0.86	13.39	102	200	Idle	91.5	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.05	14.77	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:0	10.9	845	0.86	13.37	102	200	Idle	91.7	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.06	14.77	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:0	10.9	845	0.86	13.39	102	200	Idle	91.9	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.05	14.77	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:0	12.27	849	0.86	13.39	102	200	Idle	91.9	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.06	14.78	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:0	12.27	853	0.86	13.37	102	200	Idle	92	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.04	14.79	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:0	12.27	853	0.86	13.38	102	200	Idle	92.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.06	14.79	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:0	12.27	844	0.86	13.37	102	200	Idle	92.4	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.05	14.81	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:1	12.27	844	0.86	13.4	102	200	Idle	92.5	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.06	14.81	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:1	10.9	868	0.86	13.39	102	200	Idle	92.7	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.06	14.82	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:1	10.9	868	0.86	13.4	102	200	Idle	92.7	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.1	14.83	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:29:1	10.9	859	0.85	13.39	102	200	Idle	92.5	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.09	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:1	10.9	859	0.85	13.39	102	200	Idle	92.5	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.12	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:1	9.54	859	0.85	13.38	102	200	Idle	92.5	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.15	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:1	9.54	865	0.85	13.39	102	200	Idle	92.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.09	14.83	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:2	9.54	865	0.85	13.4	102	200	Idle	92.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.11	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:2	9.54	874	0.85	13.39	102	200	Idle	92.6	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.11	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:2	10.9	874	0.85	13.39	102	200	Idle	92.6	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.13	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:2	10.9	887	0.85	13.4	102	200	Idle	92.8	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.12	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:2	10.9	887	0.85	13.39	102	200	Idle	92.9	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.18	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:2	10.9	884	0.85	13.39	102	200	Idle	92.9	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.16	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:3	10.9	882	0.85	13.39	102	200	Idle	92.9	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.23	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:3	8.18	875	0.85	13.38	102	200	Idle	93	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.22	14.87	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:3	8.18	875	0.85	13.39	102	200	Idle	93	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.27	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:3	8.18	880	0.84	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.27	14.84	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:3	8.18	884	0.84	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.28	14.82	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:3	8.18	886	0.84	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.28	14.81	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:4	9.54	886	0.84	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.27	14.82	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:4	9.54	890	0.84	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.28	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:4	9.54	894	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.3	14.86	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:4	9.54	883	0.84	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.34	14.87	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:4	8.18	883	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.33	14.89	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:4	8.18	894	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.37	14.9	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:4	8.18	906	0.84	13.39	102	200	Idle	93.1	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.34	14.92	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:5	8.18	906	0.84	13.4	102	200	Idle	93.1	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.38	14.95	1.02	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:5	8.18	903	0.84	13.4	102	200	Idle	93.1	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.33	14.98	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:29:5	8.18	903	0.84	13.39	102	200	Idle	93.1	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.36	14.99	1.02	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:29:5	8.18	912	0.84	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.36	15.01	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:5	8.18	921	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.42	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:5	8.18	906	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.4	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:6	8.18	912	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.47	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:6	8.18	912	0.84	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.42	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:6	8.18	925	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.48	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:6	8.18	938	0.84	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.47	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:6	8.18	938	0.84	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.52	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:6	8.18	917	0.84	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.5	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:6	8.18	917	0.84	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.55	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:7	8.18	922	0.84	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.52	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:7	8.18	926	0.84	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.54	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:7	8.18	911	0.84	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.56	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:7	8.18	911	0.84	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.57	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:7	8.18	924	0.83	13.32	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.55	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:7	8.18	924	0.83	13.32	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.58	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:8	8.18	904	0.83	13.32	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.57	14.95	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:8	8.18	904	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.58	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:8	8.18	907	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.61	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:8	8.18	907	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.59	14.95	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:8	8.18	907	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.57	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:8	8.18	902	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.58	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:9	8.18	920	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.6	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:9	8.18	920	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.58	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:9	8.18	920	0.83	13.33	102	200	Idle	93.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.62	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:9	8.18	906	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.61	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:9	8.18	908	0.83	13.35	102	200	Idle	93.3	0	2	132	944 Turbo	0.28	Rich	1	14.6	-7.64	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:9	8.18	911	0.83	13.36	102	200	Idle	93.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.63	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:29:9	8.18	911	0.83	13.35	102	200	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.65	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:0	8.18	917	0.83	13.36	102	200	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.62	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:0	8.18	919	0.83	13.35	102	200	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.65	14.94	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:0	9.54	919	0.83	13.34	102	200	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.58	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:0	9.54	918	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.63	14.91	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:0	9.54	918	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.6	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:0	9.54	936	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.88	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:1	8.18	936	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.64	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:1	8.18	932	0.83	13.34	102	200	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.68	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:1	8.18	928	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.87	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:1	8.18	928	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.87	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:1	8.18	905	0.83	13.33	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.6	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:1	8.18	923	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.65	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:1	8.18	923	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.63	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:2	8.18	923	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.68	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:2	9.54	914	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.66	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:2	9.54	914	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:2	9.54	914	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:2	9.54	913	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.7	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:2	8.18	928	0.83	13.33	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:3	8.18	928	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.72	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:3	8.18	930	0.83	13.33	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:3	8.18	932	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:3	6.81	922	0.83	13.32	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:3	6.81	922	0.83	13.33	102	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:3	6.81	924	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:4	6.81	925	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.67	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:4	6.81	918	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:4	6.81	918	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.69	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:30:4	6.81	918	0.83	13.34	102	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:4	6.81	918	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:4	6.81	918	0.83	13.33	102	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:4	6.81	898	0.83	13.35	102	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	15.14	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:5	6.81	914	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	15.14	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:30:5	6.81	914	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.69	15.18	1.03	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:30:5	8.18	914	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.7	15.18	1.03	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:30:5	8.18	905	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.71	15.19	1.03	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:30:5	8.18	909	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.7	15.19	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:30:5	8.18	909	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.7	15.19	1.04	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:30:6	8.18	909	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.72	15.19	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:30:6	8.18	925	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.67	15.2	1.04	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:30:6	8.18	919	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.69	15.18	1.03	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:30:6	8.18	919	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.66	15.19	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:6	8.18	919	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.68	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:6	8.18	929	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.64	15.15	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:6	8.18	911	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.71	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:7	8.18	911	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.66	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:7	8.18	911	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.69	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:7	8.18	913	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.65	15.13	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:7	8.18	924	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.68	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:7	8.18	924	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.65	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:7	8.18	924	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.68	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:8	9.54	922	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:8	9.54	922	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:8	9.54	925	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:8	9.54	925	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	15.07	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:8	8.18	932	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.7	15.09	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:8	8.18	938	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	15.08	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:9	8.18	941	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.7	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:9	8.18	941	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.05	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:9	8.18	946	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.72	15.05	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:9	8.18	950	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:30:9	8.18	940	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:30:9	8.18	940	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:30:9	8.18	953	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.78	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:0	8.18	953	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.83	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:0	8.18	948	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:0	8.18	948	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:0	8.18	954	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.02	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:0	8.18	954	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.84	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:0	8.18	953	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.01	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:1	8.18	953	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.83	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:1	8.18	957	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:1	8.18	950	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.81	14.97	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:1	8.18	943	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.96	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:1	8.18	943	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.82	14.93	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:1	8.18	948	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.9	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:1	8.18	948	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:2	8.18	942	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.83	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:2	8.18	936	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.88	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:2	8.18	942	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.83	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:2	8.18	942	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.89	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:2	8.18	929	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:2	8.18	929	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:3	8.18	929	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.84	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:3	8.18	929	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	14.87	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:3	8.18	931	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:31:3	8.18	931	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.82	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:3	9.54	927	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:3	9.54	927	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:4	9.54	887	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.82	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:4	9.54	887	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:4	9.54	912	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:4	9.54	912	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.75	14.81	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:4	9.54	891	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	14.8	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:4	9.54	891	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	14.8	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:4	9.54	900	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:5	9.54	900	0.83	13.41	102	200	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:5	9.54	908	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	14.8	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:5	9.54	917	0.83	13.41	102	200	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.73	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:5	9.54	912	0.83	13.41	102	200	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.76	14.81	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:5	9.54	912	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.72	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:5	9.54	914	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.76	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:6	9.54	914	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.7	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:6	8.18	914	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.74	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:6	8.18	920	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.67	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:6	8.18	920	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.68	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:6	8.18	907	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.66	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:6	8.18	907	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:6	8.18	918	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.65	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:7	8.18	910	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:7	8.18	910	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.83	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:7	8.18	910	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.71	14.82	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:7	6.81	912	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.7	14.82	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:7	6.81	912	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.73	14.83	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:7	6.81	920	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:8	6.81	920	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.75	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:8	6.81	912	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:8	6.81	912	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.86	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:8	6.81	924	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	14.87	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:8	6.81	924	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.7	14.86	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:8	6.81	896	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:9	6.81	896	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.68	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:31:9	6.81	908	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:9	6.81	908	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:9	8.18	898	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.68	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:9	8.18	898	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.62	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:9	8.18	898	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:31:9	8.18	900	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:0	8.18	904	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.67	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:0	8.18	907	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.63	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:0	8.18	898	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.63	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:0	8.18	898	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.65	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:0	8.18	906	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.68	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:0	8.18	915	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.64	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:1	8.18	915	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.69	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:1	8.18	920	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.65	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:1	8.18	908	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.68	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:1	8.18	896	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.63	14.9	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:1	8.18	896	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.65	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:1	8.18	906	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.64	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:1	8.18	906	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.66	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:2	8.18	908	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.66	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:2	8.18	909	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:2	8.18	916	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.67	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:32:2	8.18	916	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:2	6.81	908	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:2	6.81	900	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:3	6.81	900	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:3	6.81	920	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.65	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:3	8.18	920	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.63	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:3	8.18	920	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.67	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:3	8.18	922	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:3	8.18	924	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:4	8.18	927	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:4	8.18	927	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:4	8.18	930	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:4	8.18	933	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.66	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:4	9.54	942	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:4	9.54	942	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:4	9.54	929	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:5	9.54	929	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:5	9.54	933	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:5	8.18	937	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:5	8.18	941	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.75	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:5	8.18	941	0.83	13.41	102	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.76	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:5	8.18	941	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.76	15.05	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:6	8.18	941	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.77	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:6	8.18	938	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.79	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:6	8.18	938	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.79	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:6	8.18	935	0.83	13.36	102	200	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.79	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:6	8.18	932	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.82	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:6	8.18	935	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.85	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:6	8.18	935	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.84	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:7	8.18	937	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.82	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:7	8.18	939	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.8	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:7	8.18	936	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.83	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:7	8.18	936	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.79	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:7	8.18	933	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.8	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:7	8.18	930	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.79	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:8	8.18	930	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.82	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:32:8	8.18	926	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.79	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:8	8.18	926	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.8	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:8	8.18	926	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.79	15.09	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:8	8.18	926	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.79	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:8	8.18	921	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.78	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:9	8.18	936	0.83	13.41	102	200	Idle	93.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.82	15.07	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:9	8.18	936	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.77	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:9	8.18	938	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.81	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:9	8.18	941	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.77	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:9	8.18	941	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:9	8.18	933	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:32:9	8.18	939	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.8	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:0	8.18	945	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:0	8.18	945	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:0	8.18	944	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.81	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:0	8.18	946	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.83	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:0	8.18	949	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:0	8.18	949	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.84	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:1	8.18	954	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:1	8.18	955	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.85	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:1	8.18	955	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.84	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:1	8.18	955	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.85	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:33:1	6.81	947	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.87	14.96	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:1	6.81	965	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.89	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:1	6.81	965	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.87	14.95	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:2	5.45	954	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.88	14.96	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:2	5.45	954	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.87	14.96	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:2	5.45	954	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:2	5.45	958	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.87	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:2	6.81	952	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.89	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:2	6.81	952	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.87	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:3	6.81	952	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.91	15	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:3	6.81	940	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.86	15	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:3	6.81	931	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.92	14.99	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:3	6.81	931	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.88	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:3	6.81	928	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.9	14.96	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:3	6.81	926	0.83	13.41	102	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.84	14.93	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:4	8.18	908	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.88	14.9	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:4	8.18	908	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.85	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:4	8.18	911	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.86	14.87	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:33:4	8.18	914	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.84	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:4	9.54	914	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.87	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:4	9.54	913	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.8	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:4	9.54	913	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.81	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:5	9.54	903	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.79	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:5	9.54	893	0.83	13.41	102	200	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.81	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:5	9.54	913	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.76	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:5	9.54	901	0.83	13.41	102	200	Idle	93.3	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.8	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:5	9.54	901	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.76	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:5	9.54	901	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.75	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:6	9.54	924	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:6	9.54	924	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:6	9.54	904	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:6	9.54	904	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.77	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:6	6.81	904	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:6	6.81	904	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:6	6.81	924	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.79	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:7	6.81	924	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:7	8.18	921	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:7	8.18	918	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.76	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:7	8.18	920	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.16	Rich	1	14.6	-7.72	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:7	8.18	920	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.19	Rich	1	14.6	-7.75	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:7	8.18	925	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.21	Rich	1	14.6	-7.77	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:8	6.81	930	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.23	Rich	1	14.6	-7.76	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:8	6.81	919	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.24	Rich	1	14.6	-7.76	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:8	6.81	919	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.79	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:8	6.81	926	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.29	Rich	1	14.6	-7.79	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:8	6.81	933	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.77	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:8	6.81	938	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.79	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:9	6.81	938	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.76	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:9	6.81	930	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.79	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:9	6.81	922	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.75	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:9	6.81	922	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.78	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:9	6.81	922	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.78	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:9	9.54	940	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:33:9	9.54	940	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.75	15.04	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:0	9.54	930	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:0	9.54	920	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:0	9.54	920	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.76	15.09	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:0	8.18	930	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.72	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:34:0	8.18	934	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:0	8.18	939	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:1	9.54	939	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:1	9.54	953	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.74	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:1	9.54	953	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:1	9.54	947	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:1	9.54	936	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	15.06	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:1	5.45	930	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:1	5.45	930	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	15.05	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:2	5.45	949	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:2	5.45	946	0.83	13.4	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:2	6.81	943	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:2	6.81	943	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.81	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:2	6.81	939	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.75	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:2	6.81	930	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:3	8.18	930	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:3	8.18	930	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:3	8.18	914	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:3	8.18	923	0.83	13.39	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.83	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:3	8.18	923	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:3	8.18	923	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.83	14.97	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:4	8.18	917	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.76	14.95	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:4	8.18	917	0.83	13.37	102	200	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.93	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:4	8.18	933	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.77	14.92	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:4	8.18	933	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.79	14.89	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:4	8.18	916	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.74	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:4	8.18	916	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.79	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:4	8.18	920	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.75	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:5	8.18	920	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.77	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:5	8.18	924	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.74	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:5	8.18	928	0.83	13.41	102	200	Idle	93.3	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.77	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:5	9.54	919	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.74	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:5	9.54	919	0.83	13.41	103	200	Idle	93.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.75	14.85	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:5	9.54	917	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:6	9.54	917	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.73	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:6	8.18	924	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.72	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:6	8.18	924	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.77	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:6	8.18	913	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.73	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:6	8.18	913	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.74	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:6	8.18	917	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.75	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:6	8.18	921	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.73	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:7	8.18	915	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.72	14.83	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:34:7	8.18	915	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.36	Lean	1	14.6	-7.71	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:7	8.18	914	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.72	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:7	8.18	914	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.7	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:7	8.18	915	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.76	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:7	8.18	915	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.72	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:8	6.81	918	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.76	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:8	6.81	922	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.71	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:8	6.81	917	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.71	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:8	6.81	917	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:8	6.81	910	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:8	8.18	903	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.69	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:9	8.18	903	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:9	8.18	908	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:9	8.18	908	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:9	8.18	903	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.75	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:9	8.18	898	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.74	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:34:9	8.18	898	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:9	8.18	911	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.75	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:0	8.18	911	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.7	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:0	8.18	911	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:0	8.18	911	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.69	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:0	8.18	899	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:0	8.18	902	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:0	8.18	902	0.83	13.4	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.68	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:1	8.18	904	0.83	13.37	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:1	8.18	907	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.66	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:1	8.18	915	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:1	8.18	915	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:1	8.18	917	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:1	8.18	919	0.83	13.39	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.7	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:1	6.81	906	0.83	13.38	102	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	15.03	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:2	6.81	906	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.69	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:2	6.81	914	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:2	6.81	923	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	15.08	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:2	8.18	923	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.66	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:2	8.18	906	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.68	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:2	8.18	913	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.7	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:3	8.18	920	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.27	Rich	1	14.6	-7.71	15.14	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:3	8.18	920	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.32	Rich	1	14.6	-7.72	15.15	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:3	8.18	929	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.36	Rich	1	14.6	-7.69	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:3	8.18	927	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.45	Rich	1	14.6	-7.73	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:3	8.18	927	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.69	15.18	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:3	9.54	927	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.72	15.2	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:4	9.54	942	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.75	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:4	9.54	928	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:4	9.54	928	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:4	8.18	930	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.75	15.21	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:4	8.18	933	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:4	8.18	933	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.76	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:4	8.18	927	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.18	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:5	8.18	932	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	15.17	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:5	8.18	938	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	15.15	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:5	8.18	938	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.13	1.03	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:5	8.18	947	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.12	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:5	8.18	936	0.83	13.41	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:5	8.18	936	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.1	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:6	8.18	937	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:6	8.18	938	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.77	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:6	8.18	938	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:6	8.18	943	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:6	8.18	943	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.83	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:6	8.18	943	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:6	8.18	943	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.83	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:7	8.18	931	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:7	8.18	928	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.84	15.04	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:7	8.18	924	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:7	8.18	924	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.83	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:7	8.18	926	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	14.99	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:7	8.18	926	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	14.98	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:8	8.18	924	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	14.96	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:8	8.18	922	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.84	14.95	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:8	8.18	909	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.81	14.91	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:8	8.18	909	0.83	13.41	103	200	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.83	14.87	1.01	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:8	8.18	905	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:35:8	8.18	905	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.79	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:9	9.54	924	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.76	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:9	9.54	924	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.75	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:35:9	9.54	913	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.79	14.86	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:9	9.54	913	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.76	14.86	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:9	9.54	932	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.71	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:9	9.54	932	0.83	13.41	103	200	Idle	93.3	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.71	14.86	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:35:9	9.54	919	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.41	Rich	1	14.6	-7.69	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:0	9.54	919	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.38	Rich	1	14.6	-7.71	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:0	8.18	912	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.34	Rich	1	14.6	-7.73	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:0	8.18	912	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.31	Rich	1	14.6	-7.76	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:0	8.18	912	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.3	Rich	1	14.6	-7.79	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:0	8.18	920	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.73	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:0	6.81	909	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.76	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:1	6.81	909	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:1	6.81	910	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:1	6.81	912	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.78	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:1	8.18	910	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:1	8.18	910	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.74	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:1	8.18	910	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:1	8.18	919	0.83	13.32	103	200	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:2	8.18	908	0.83	13.3	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.73	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:2	8.18	908	0.83	13.3	102	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.71	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:2	8.18	912	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.74	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:2	8.18	915	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.76	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:3	6.81	917	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.72	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:3	6.81	924	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:3	6.81	924	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.71	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:3	6.81	911	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.73	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:3	6.81	918	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:3	6.81	918	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.69	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:4	6.81	918	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.68	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:4	6.81	900	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.72	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:4	6.81	900	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:4	6.81	914	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.77	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:4	6.81	914	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:4	6.81	912	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.76	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:4	6.81	911	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.72	15.02	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:5	6.81	916	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.79	15.04	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:5	6.81	916	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.73	15.06	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:5	9.54	916	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.27	Lean	1	14.6	-7.73	15.08	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:5	9.54	916	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.69	15.1	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:5	9.54	918	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.71	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:5	9.54	919	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.7	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:6	9.54	916	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.74	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:6	9.54	916	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.76	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:6	9.54	912	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.76	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:6	9.54	912	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.74	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:6	9.54	908	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.71	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:6	9.54	919	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.69	15.11	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:6	9.54	928	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.74	15.1	1.03	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:7	9.54	927	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.71	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:7	8.18	928	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.43	Rich	1	14.6	-7.75	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:7	8.18	930	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.72	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:7	8.18	939	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.75	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:7	8.18	939	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.75	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:7	8.18	939	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.77	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:8	8.18	948	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.73	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:36:8	8.18	948	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.79	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:36:8	8.18	944	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:8	8.18	940	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:8	8.18	937	0.83	13.36	102	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.72	15.05	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:8	8.18	938	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.73	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:9	8.18	938	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.76	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:9	8.18	941	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.79	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:9	8.18	941	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.82	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:9	8.18	940	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.84	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:9	8.18	940	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:9	8.18	940	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:36:9	8.18	940	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.77	15	1.02	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:37:0	8.18	934	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	15	1.02	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:37:0	8.18	929	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.78	15	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:0	8.18	921	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.8	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:0	8.18	921	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.85	14.98	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:0	8.18	926	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.85	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:0	8.18	926	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.8	14.96	1.02	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:1	8.18	909	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.82	14.97	1.02	5.3	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:1	8.18	892	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.01	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:1	8.18	892	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:1	8.18	897	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.74	15.03	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:1	8.18	902	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	15.04	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:1	8.18	878	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15.01	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:1	8.18	878	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.7	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:2	8.18	880	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:2	8.18	880	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.71	14.9	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:2	8.18	881	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.71	14.88	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:2	8.18	881	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:2	8.18	881	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.71	14.85	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:2	8.18	876	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.64	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:3	8.18	876	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.67	14.84	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:3	8.18	876	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:3	8.18	876	0.83	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.61	14.84	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:3	8.18	856	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.59	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:3	8.18	856	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.57	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:3	9.54	844	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	14.83	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:4	9.54	844	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.49	14.82	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:4	9.54	849	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.54	14.81	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:4	9.54	849	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.5	14.8	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:4	8.18	848	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.54	14.78	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:4	8.18	848	0.83	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.47	14.78	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:4	8.18	848	0.83	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.51	14.78	1.01	5.1	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:4	8.18	836	0.83	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.48	14.78	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:5	8.18	836	0.83	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.46	14.78	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:5	9.54	825	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.44	14.79	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:5	9.54	825	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.41	14.8	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:5	9.54	828	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.46	14.81	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:5	9.54	830	0.83	13.37	103	200	Idle	93.1	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.38	14.82	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:5	10.9	823	0.83	13.35	103	200	Idle	93.1	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.44	14.82	1.01	5	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:6	10.9	823	0.83	13.34	103	200	Idle	93	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.39	14.83	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:6	10.9	823	0.83	13.34	103	200	Idle	93	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.37	14.84	1.01	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:6	10.9	817	0.82	13.33	103	200	Idle	93	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.35	14.84	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:6	10.9	817	0.82	13.33	103	200	Idle	93	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.31	14.84	1.01	5	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:6	10.9	805	0.82	13.33	103	200	Idle	93	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.3	14.83	1.01	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:6	10.9	805	0.82	13.32	103	200	Idle	93	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.26	14.83	1.01	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:6	10.9	801	0.82	13.37	103	200	Idle	93	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.27	14.83	1.01	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:7	10.9	801	0.82	13.34	103	200	Idle	93.1	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.21	14.85	1.01	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:37:7	10.9	801	0.82	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.26	14.84	1.01	5.1	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:7	10.9	815	0.82	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.26	14.84	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:7	10.9	815	0.82	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.22	14.85	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:7	10.9	830	0.82	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.27	14.84	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:7	10.9	830	0.82	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.2	14.84	1.01	4.7	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:8	14.99	832	0.82	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.19	14.84	1.01	4.8	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:8	14.99	832	0.82	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.13	14.83	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:8	14.99	843	0.82	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.2	14.85	1.01	4.9	2.4	ON	28 Pin	OFF	Removed	Disabled
03:30:37:8	14.99	843	0.82	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.16	14.85	1.01	4.8	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:8	14.99	843	0.82	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.19	14.85	1.01	4.7	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:8	13.63	866	0.82	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.23	14.86	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:9	13.63	896	0.82	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.23	14.85	1.01	4.6	2.3	ON	28 Pin	OFF	Removed	Disabled
03:30:37:9	13.63	896	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.27	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:9	13.63	896	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.24	14.85	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:9	13.63	921	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.27	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:9	13.63	921	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.3	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:9	13.63	926	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.3	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:37:9	13.63	932	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.33	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:0	13.63	957	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.38	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:0	13.63	957	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.41	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:0	13.63	961	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.51	14.85	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:0	13.63	961	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.51	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:0	12.27	961	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.52	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:0	12.27	979	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.55	14.84	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:1	12.27	979	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.6	14.84	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:1	12.27	984	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.66	14.84	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:1	12.27	990	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.68	14.83	1.01	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:1	12.27	990	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.71	14.83	1.01	4.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:1	12.27	991	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.73	14.83	1.01	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:1	12.27	991	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.71	14.83	1.01	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:1	12.27	987	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.72	14.84	1.01	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:2	12.27	975	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.77	14.84	1.01	4.8	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:2	12.27	975	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	14.84	1.01	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:2	12.27	980	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.79	14.84	1.01	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:2	12.27	985	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.77	14.84	1.01	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:2	12.27	986	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.83	14.84	1.01	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:2	12.27	986	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.8	14.84	1.01	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:3	12.27	981	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.87	14.84	1.01	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:3	12.27	976	0.83	13.41	103	200	Idle	93.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.87	14.84	1.01	4.6	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:3	12.27	976	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.89	14.84	1.01	4.7	2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:3	12.27	963	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.89	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:3	12.27	962	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.89	14.83	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:3	12.27	962	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.9	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:4	12.27	962	0.83	13.3	103	200	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.9	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:4	12.27	967	0.84	13.28	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.88	14.87	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:4	13.63	974	0.84	13.27	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.89	14.87	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:4	13.63	982	0.84	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.89	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:4	13.63	964	0.84	13.3	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.89	14.9	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:4	13.63	964	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.89	14.92	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:4	12.27	966	0.84	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.89	14.96	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:5	12.27	969	0.84	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.89	14.99	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:5	12.27	976	0.84	13.32	103	200	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.86	15	1.02	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:5	12.27	976	0.84	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.85	14.99	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:5	10.9	955	0.84	13.3	103	200	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.83	14.97	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:5	10.9	955	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.83	14.94	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:5	10.9	960	0.84	13.3	103	200	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.85	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:6	10.9	967	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.83	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:6	12.27	974	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.83	14.87	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:38:6	12.27	974	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.85	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:6	12.27	967	0.84	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.84	14.88	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:6	12.27	960	0.84	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.86	14.93	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:6	10.9	969	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.84	14.96	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:6	10.9	969	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.82	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:7	10.9	961	0.84	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-7.85	15.06	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:7	10.9	961	0.84	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.85	15.11	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:7	12.27	962	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.84	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:7	12.27	960	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.88	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:7	12.27	958	0.84	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.83	15.23	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:7	12.27	958	0.84	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.86	15.28	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:8	9.54	958	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.82	15.32	1.04	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:8	9.54	966	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.87	15.36	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:8	9.54	966	0.84	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.82	15.4	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:8	10.9	973	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.88	15.43	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:8	10.9	973	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.82	15.46	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:8	10.9	966	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.87	15.48	1.05	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:9	10.9	959	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.81	15.53	1.06	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:9	9.54	962	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.87	15.56	1.06	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:9	9.54	962	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.83	15.58	1.06	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:38:9	9.54	943	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.86	15.59	1.06	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:9	9.54	943	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.85	15.59	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:9	9.54	948	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.89	15.59	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:38:9	9.54	948	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.83	15.58	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:0	9.54	956	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.87	15.57	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:0	9.54	956	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.81	15.57	1.06	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:0	9.54	956	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.83	15.57	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:0	8.18	943	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.8	15.56	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:0	8.18	944	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.83	15.53	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:0	8.18	945	0.84	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.81	15.49	1.06	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:1	8.18	948	0.84	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.79	15.46	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:1	8.18	948	0.84	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.76	15.45	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:1	8.18	926	0.84	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.77	15.42	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:1	8.18	926	0.84	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.74	15.4	1.05	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:1	8.18	926	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.76	15.37	1.05	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:1	8.18	926	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.77	15.34	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:1	8.18	923	0.84	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.75	15.31	1.04	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:2	8.18	920	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.74	15.29	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:2	9.54	920	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.77	15.27	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:2	9.54	947	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.71	15.24	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:2	9.54	933	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.73	15.23	1.04	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:2	9.54	919	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.68	15.2	1.04	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:2	9.54	926	0.84	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.72	15.18	1.03	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:3	9.54	926	0.84	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.69	15.18	1.03	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:3	9.54	922	0.83	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.74	15.17	1.03	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:3	9.54	918	0.84	13.32	103	200	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.67	15.16	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:3	8.18	918	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.68	15.14	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:3	8.18	929	0.83	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.66	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:3	8.18	929	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.69	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:4	8.18	938	0.83	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.69	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:4	8.18	941	0.83	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.74	15.14	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:4	9.54	944	0.83	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.48	Lean	1	14.6	-7.68	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:4	9.54	934	0.83	13.33	103	200	Idle	93.3	0	2	132	944 Turbo	0.49	Lean	1	14.6	-7.75	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:4	9.54	934	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.68	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:4	8.18	943	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.68	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:4	8.18	943	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.67	15.1	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:5	8.18	941	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.59	Rich	1	14.6	-7.67	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:5	8.18	939	0.83	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.61	Rich	1	14.6	-7.66	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:39:5	8.18	929	0.83	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.68	15.05	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:39:5	8.18	929	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.69	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:39:5	8.18	929	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.71	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:39:5	8.18	937	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.69	15.02	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:6	8.18	931	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:6	8.18	925	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.7	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:6	8.18	925	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.74	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:6	8.18	933	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.76	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:6	8.18	929	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.75	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:6	8.18	929	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.78	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:6	8.18	927	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.73	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:7	9.54	927	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.71	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:7	9.54	942	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.72	14.96	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:7	9.54	916	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.76	14.96	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:7	9.54	916	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.78	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:7	9.54	918	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.76	14.97	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:8	8.18	918	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.71	14.96	1.02	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:8	8.18	918	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.72	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:8	8.18	933	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.69	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:8	8.18	934	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.78	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:8	8.18	934	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.75	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:9	8.18	939	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.78	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:9	8.18	939	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:9	8.18	941	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.8	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:9	8.18	941	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:9	8.18	940	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:9	8.18	940	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:39:9	8.18	940	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:0	8.18	940	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:0	8.18	946	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.84	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:0	8.18	946	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.83	14.89	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:0	8.18	926	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.85	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:0	8.18	933	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.83	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:0	8.18	933	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.83	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:1	8.18	935	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.83	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:1	8.18	935	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.77	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:1	8.18	935	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.79	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:1	8.18	945	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.77	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:1	8.18	945	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.79	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:1	8.18	930	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.79	15	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:1	8.18	930	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.71	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:2	8.18	942	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.76	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:2	8.18	942	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.58	Rich	1	14.6	-7.74	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:2	8.18	953	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.76	15.07	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:2	8.18	953	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.74	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:2	8.18	935	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.78	15.09	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:2	8.18	935	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	15.11	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:3	8.18	939	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.78	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:3	8.18	939	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.81	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:3	8.18	949	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.81	15.12	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:3	8.18	949	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.84	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:3	8.18	938	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.83	15.12	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:3	8.18	938	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:4	8.18	941	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	15.11	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:40:4	8.18	941	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.78	15.11	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:40:4	8.18	941	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.1	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:40:4	8.18	910	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.76	15.09	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:40:4	8.18	904	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:40:4	8.18	904	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.07	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:4	9.54	902	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.79	15.06	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:5	9.54	902	0.83	13.3	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	15.04	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:5	9.54	895	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.03	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:5	9.54	888	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.71	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:5	8.18	900	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.77	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:5	8.18	900	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	14.99	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:5	8.18	900	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.69	14.98	1.02	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:6	8.18	885	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:6	8.18	885	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.66	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:6	8.18	896	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:6	8.18	891	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.67	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:6	8.18	891	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.68	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:6	8.18	892	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.67	15.01	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:6	9.54	892	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.69	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:7	9.54	892	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.66	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:7	9.54	894	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:7	9.54	894	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.66	14.9	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:7	8.18	887	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.67	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:7	8.18	887	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.62	14.87	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:7	8.18	909	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.68	14.86	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:8	8.18	909	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:8	8.18	902	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.63	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:8	8.18	902	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.65	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:8	8.18	910	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.64	14.85	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:8	8.18	910	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.65	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:8	6.81	910	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.63	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:9	6.81	910	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.63	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:9	6.81	929	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.66	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:9	6.81	929	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.67	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:9	6.81	917	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:9	6.81	917	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:40:9	6.81	920	0.83	13.3	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	14.87	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:0	6.81	920	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.66	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:0	6.81	914	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.67	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:0	6.81	908	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.65	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:0	6.81	944	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.66	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:0	6.81	944	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.66	14.88	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:0	8.18	944	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	14.87	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:0	8.18	911	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.79	Rich	1	14.6	-7.69	14.88	1.01	5.2	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:1	8.18	901	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.68	14.87	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:1	8.18	901	0.83	13.32	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.64	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:1	8.18	901	0.83	13.31	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.61	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:1	8.18	930	0.83	13.33	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.58	14.86	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:1	8.18	899	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.61	14.85	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:1	8.18	899	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.58	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:2	8.18	906	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.58	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:2	8.18	906	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.57	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:2	8.18	906	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.57	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:2	8.18	909	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.56	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:2	8.18	904	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.56	14.82	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:2	8.18	899	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.53	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:3	8.18	899	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.53	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:3	8.18	908	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.48	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:3	8.18	908	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.5	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:3	8.18	909	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.22	Lean	1	14.6	-7.48	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:3	8.18	909	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.49	14.81	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:3	8.18	913	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.47	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:41:3	8.18	913	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.5	14.8	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:4	8.18	914	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.5	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:4	8.18	914	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.5	14.78	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:4	8.18	910	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.52	14.78	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:4	8.18	905	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.51	14.78	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:4	6.81	910	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.5	14.78	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:4	6.81	910	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.48	14.78	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:5	6.81	920	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.54	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:5	6.81	920	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.47	14.79	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:5	9.54	924	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.56	14.8	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:5	9.54	927	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.52	14.8	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:5	9.54	919	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.57	14.83	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:5	9.54	919	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.54	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:5	9.54	932	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.6	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:6	9.54	945	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.55	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:6	9.54	925	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.83	1.01	5.1	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:6	9.54	925	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.6	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:6	9.54	944	0.83	13.38	103	200	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.64	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:6	9.54	944	0.83	13.37	103	200	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.59	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:6	9.54	944	0.83	13.37	103	200	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.65	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:7	9.54	945	0.83	13.37	103	200	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.65	14.89	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:7	8.18	929	0.83	13.39	103	200	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.71	14.93	1.02	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:7	8.18	929	0.83	13.38	103	200	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.72	15	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:7	8.18	940	0.83	13.38	103	200	Idle	93.1	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.73	15.05	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:7	8.18	940	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.67	15.08	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:7	8.18	940	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:8	8.18	947	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.67	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:8	8.18	946	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	15.18	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:8	8.18	946	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.69	15.2	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:8	6.81	950	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	15.21	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:8	6.81	954	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.7	15.22	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:8	6.81	954	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.75	15.23	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:8	6.81	955	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.73	15.24	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:9	6.81	959	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.74	15.26	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:9	6.81	959	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.7	15.25	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:9	6.81	964	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.75	15.25	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:9	6.81	964	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.74	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:9	6.81	953	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.79	15.25	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:41:9	6.81	942	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.75	15.24	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:0	6.81	956	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.82	15.24	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:0	6.81	956	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.79	15.23	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:0	8.18	952	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.8	15.22	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:0	8.18	952	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.79	15.22	1.04	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:0	8.18	951	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.77	15.22	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:0	8.18	951	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.25	Lean	1	14.6	-7.76	15.21	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:0	8.18	943	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.76	15.2	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:1	8.18	943	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.74	15.19	1.04	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:1	8.18	941	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.78	15.18	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:1	8.18	939	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.49	Rich	1	14.6	-7.79	15.17	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:1	9.54	944	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.86	15.16	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:1	9.54	950	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.85	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:1	9.54	935	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.55	Rich	1	14.6	-7.84	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:2	9.54	935	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.79	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:2	8.18	937	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.83	15.13	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:2	8.18	937	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.54	Rich	1	14.6	-7.81	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:2	8.18	938	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.84	15.12	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:2	8.18	939	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.79	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:2	8.18	943	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.81	15.1	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:42:3	8.18	947	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.78	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:3	8.18	931	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.77	15.08	1.03	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:3	8.18	931	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.77	15.05	1.03	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:3	8.18	935	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.78	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:3	8.18	935	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.43	Lean	1	14.6	-7.77	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:3	8.18	937	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.81	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:3	8.18	937	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.47	Rich	1	14.6	-7.79	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:4	8.18	941	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.52	Rich	1	14.6	-7.81	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:4	8.18	941	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.57	Rich	1	14.6	-7.82	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:4	8.18	944	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.81	15.02	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:4	8.18	944	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.75	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:4	8.18	944	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:4	8.18	945	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.72	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:5	8.18	948	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.74	14.98	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:5	8.18	948	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:5	8.18	946	0.83	13.34	103	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.79	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:5	8.18	946	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.74	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:5	8.18	946	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.8	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:5	8.18	946	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.79	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:5	8.18	943	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	14.94	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:6	8.18	943	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	14.94	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:6	8.18	944	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.94	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:6	8.18	944	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.8	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:6	8.18	946	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:6	8.18	948	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.82	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:6	8.18	949	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.84	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:7	8.18	949	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.81	14.96	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:7	8.18	948	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.86	14.96	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:7	8.18	946	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	14.95	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:7	8.18	946	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.84	14.96	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:7	8.18	946	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.83	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:7	8.18	948	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.79	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:8	8.18	949	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.83	15	1.02	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:8	8.18	941	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.83	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:8	8.18	941	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.86	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:8	6.81	942	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.86	14.99	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:8	6.81	942	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.78	Rich	1	14.6	-7.88	14.98	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:8	6.81	946	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.88	14.97	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:8	6.81	946	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.87	14.96	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:9	8.18	934	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.83	14.94	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:9	8.18	934	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.87	14.9	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:42:9	8.18	934	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.85	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:9	8.18	940	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.83	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:9	8.18	922	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:42:9	8.18	922	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:0	8.18	930	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:0	8.18	930	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:0	8.18	930	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.84	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:0	8.18	930	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.81	14.81	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:0	8.18	951	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	14.82	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:0	8.18	951	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.82	14.81	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:0	8.18	948	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.85	14.81	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:1	8.18	944	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.84	14.82	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:1	8.18	942	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.84	14.82	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:1	8.18	942	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.87	14.83	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:1	8.18	942	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.89	14.82	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:1	8.18	943	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.87	14.83	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:1	8.18	938	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.86	14.83	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:43:2	8.18	938	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.87	14.82	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:2	8.18	932	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.88	14.82	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:2	8.18	925	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.88	14.82	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:2	8.18	916	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	14.82	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:2	8.18	916	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.87	14.82	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:2	8.18	922	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.86	14.82	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:3	8.18	929	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	14.83	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:3	8.18	929	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.83	14.82	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:3	8.18	929	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	14.82	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:3	8.18	920	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.81	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:3	9.54	920	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.8	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:3	9.54	920	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:3	9.54	917	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:4	9.54	926	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.79	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:4	8.18	926	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.75	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:4	8.18	925	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:4	8.18	924	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.77	Rich	1	14.6	-7.76	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:4	8.18	910	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.78	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:4	8.18	910	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.73	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:5	8.18	910	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.75	14.86	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:5	8.18	932	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:5	8.18	914	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.77	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:5	8.18	914	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.73	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:5	8.18	916	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.87	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:5	8.18	918	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:5	8.18	918	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.74	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:6	9.54	921	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.73	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:6	9.54	921	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.67	Lean	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:6	9.54	920	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.64	Lean	1	14.6	-7.76	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:6	9.54	920	0.83	13.41	103	200	Idle	93.2	0	2	132	944 Turbo	0.61	Lean	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:6	8.18	913	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.75	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:6	8.18	913	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.75	14.84	1.01	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:7	8.18	934	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.76	14.84	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:7	8.18	934	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.77	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:7	8.18	917	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.75	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:7	8.18	917	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.73	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:7	8.18	915	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.62	Lean	1	14.6	-7.73	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:7	8.18	915	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.76	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:8	9.54	920	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.73	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:8	9.54	920	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:8	9.54	916	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.76	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:8	9.54	912	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.73	14.84	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:8	9.54	914	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.77	14.83	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:8	9.54	914	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:8	9.54	907	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:9	9.54	900	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.77	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:9	9.54	930	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:9	6.81	930	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.74	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:9	6.81	926	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.76	14.86	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:43:9	6.81	921	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.73	14.87	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:43:9	8.18	921	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.65	Rich	1	14.6	-7.75	14.87	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:0	8.18	913	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.68	14.86	1.01	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:0	8.18	918	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.56	Rich	1	14.6	-7.72	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:0	8.18	918	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.53	Rich	1	14.6	-7.69	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:0	8.18	918	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.73	14.85	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:0	8.18	906	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.72	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:0	8.18	911	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.51	Rich	1	14.6	-7.76	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:0	8.18	911	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.5	Rich	1	14.6	-7.7	14.84	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:44:1	8.18	911	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.48	Rich	1	14.6	-7.71	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:1	8.18	902	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.46	Rich	1	14.6	-7.71	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:1	8.18	904	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.7	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:1	8.18	907	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.44	Rich	1	14.6	-7.68	14.88	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:1	8.18	907	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.42	Rich	1	14.6	-7.7	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:1	8.18	918	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.4	Rich	1	14.6	-7.69	14.9	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:2	8.18	918	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.33	Rich	1	14.6	-7.68	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:2	8.18	908	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.26	Rich	1	14.6	-7.66	14.92	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:2	8.18	908	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.71	14.93	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:2	6.81	910	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.67	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:2	6.81	911	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.69	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:2	6.81	918	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.66	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:3	6.81	926	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.66	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:3	6.81	911	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.65	14.91	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:3	6.81	911	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.69	14.9	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:3	6.81	911	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.26	Lean	1	14.6	-7.69	14.89	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:3	6.81	911	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.69	14.92	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:3	8.18	910	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.73	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:3	8.18	910	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.69	14.93	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:4	8.18	911	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.7	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:4	8.18	911	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.46	Lean	1	14.6	-7.67	14.93	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:4	8.18	912	0.84	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.68	14.95	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:4	9.54	914	0.84	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.66	14.96	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:4	9.54	914	0.84	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.67	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:4	9.54	919	0.84	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.67	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:5	9.54	919	0.84	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.58	Lean	1	14.6	-7.69	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:5	9.54	930	0.84	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.6	Lean	1	14.6	-7.68	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:5	9.54	930	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.75	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:5	9.54	921	0.84	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.69	14.97	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:5	8.18	935	0.84	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.72	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:5	8.18	935	0.84	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.71	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:5	8.18	935	0.84	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.72	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:6	8.18	936	0.84	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.71	15	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:6	8.18	936	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.77	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:6	8.18	933	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.76	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:6	8.18	933	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.68	Rich	1	14.6	-7.79	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:6	8.18	937	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.66	Rich	1	14.6	-7.76	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:6	8.18	936	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.63	Lean	1	14.6	-7.79	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:7	8.18	936	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.74	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:7	8.18	936	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.78	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:44:7	8.18	935	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.52	Lean	1	14.6	-7.72	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:7	8.18	935	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.74	15	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:7	9.54	935	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.39	Lean	1	14.6	-7.71	14.99	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:7	9.54	922	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.34	Lean	1	14.6	-7.77	14.98	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:8	9.54	908	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.76	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:8	9.54	908	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.24	Lean	1	14.6	-7.79	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:8	8.18	922	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.77	14.97	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:8	8.18	922	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.21	Lean	1	14.6	-7.79	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:8	8.18	929	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.19	Lean	1	14.6	-7.77	15	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:8	8.18	929	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.15	Lean	1	14.6	-7.79	14.99	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:8	8.18	916	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.73	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:9	8.18	916	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.12	Lean	1	14.6	-7.76	14.98	1.02	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:9	8.18	934	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.73	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:9	8.18	934	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.76	14.96	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:9	6.81	929	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.79	14.94	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:9	6.81	929	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.78	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:44:9	6.81	929	0.83	13.34	103	200	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.78	14.89	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:0	6.81	935	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.79	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:45:0	6.81	930	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.75	14.88	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:0	6.81	930	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:0	6.81	932	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.74	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:0	6.81	934	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.76	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:0	6.81	937	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.08	Lean	1	14.6	-7.79	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:0	6.81	937	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.81	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:1	6.81	937	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.8	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:1	6.81	937	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.8	14.85	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:1	8.18	943	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.09	Lean	1	14.6	-7.8	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:1	8.18	943	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.76	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:1	8.18	938	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.76	14.92	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:1	8.18	938	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.77	14.95	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:2	8.18	944	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.1	Lean	1	14.6	-7.74	14.97	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:2	8.18	944	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.11	Lean	1	14.6	-7.77	14.99	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:2	8.18	946	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.14	Lean	1	14.6	-7.78	15.01	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:2	8.18	946	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.81	15.03	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:2	8.18	943	0.83	13.37	104	200	Idle	93.3	0	2	132	944 Turbo	0.17	Lean	1	14.6	-7.8	15.04	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:2	8.18	943	0.83	13.39	104	200	Idle	93.3	0	2	132	944 Turbo	0.18	Lean	1	14.6	-7.85	15.06	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:3	8.18	947	0.83	13.38	104	200	Idle	93.3	0	2	132	944 Turbo	0.2	Lean	1	14.6	-7.84	15.07	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:3	8.18	947	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.23	Lean	1	14.6	-7.83	15.09	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:3	8.18	952	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.82	15.11	1.03	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:3	8.18	952	0.83	13.37	103	200	Idle	93.3	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.83	15.12	1.03	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:3	8.18	954	0.83	13.35	103	200	Idle	93.3	0	2	132	944 Turbo	0.4	Lean	1	14.6	-7.84	15.14	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:3	8.18	954	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.44	Lean	1	14.6	-7.83	15.15	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:3	8.18	951	0.83	13.36	103	200	Idle	93.3	0	2	132	944 Turbo	0.5	Lean	1	14.6	-7.84	15.17	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:4	8.18	951	0.83	13.37	104	200	Idle	93.3	0	2	132	944 Turbo	0.55	Lean	1	14.6	-7.88	15.18	1.03	4.7	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:4	8.18	959	0.83	13.37	104	200	Idle	93.3	0	2	132	944 Turbo	0.6	Rich	1	14.6	-7.86	15.19	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:4	8.18	959	0.83	13.39	104	200	Idle	93.2	0	2	132	944 Turbo	0.67	Rich	1	14.6	-7.87	15.19	1.03	5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:4	8.18	943	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.7	Rich	1	14.6	-7.86	15.18	1.03	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:4	8.18	943	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.89	15.18	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:4	8.18	945	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.84	15.17	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:5	8.18	947	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.86	15.16	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:5	8.18	943	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.86	15.15	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:5	8.18	939	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.85	15.14	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:5	8.18	943	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.86	15.12	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:5	8.18	947	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.88	15.11	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:5	8.18	947	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.84	15.11	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:5	8.18	947	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.85	15.09	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:6	8.18	944	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.85	15.08	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:6	8.18	944	0.83	13.37	104	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.86	15.07	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:6	8.18	938	0.83	13.34	104	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.85	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:6	8.18	940	0.83	13.36	104	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.85	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:6	8.18	940	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.83	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:6	8.18	940	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	15.01	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:7	8.18	940	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	15.02	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:7	8.18	940	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	15.03	1.02	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:7	8.18	932	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.84	15.03	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:7	8.18	932	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.82	15.02	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:7	8.18	928	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.86	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:7	8.18	923	0.83	13.4	103	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.85	15.01	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:8	8.18	923	0.83	13.36	104	200	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.86	15	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:8	8.18	923	0.83	13.36	104	199	Idle	93.2	0	2	132	944 Turbo	0.75	Rich	1	14.6	-7.8	14.97	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:8	8.18	936	0.83	13.36	103	199	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.84	14.95	1.02	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:8	8.18	936	0.83	13.38	103	200	Idle	93.2	0	2	132	944 Turbo	0.74	Rich	1	14.6	-7.78	14.9	1.01	5.1	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:8	8.18	930	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.83	14.88	1.01	5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:8	8.18	924	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.73	Rich	1	14.6	-7.79	14.85	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:8	8.18	929	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.72	Rich	1	14.6	-7.8	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:45:9	8.18	929	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.71	Rich	1	14.6	-7.79	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInput
03:30:45:9	8.18	928	0.83	13.36	104	200	Idle	93.2	0	2	132	944 Turbo	0.69	Rich	1	14.6	-7.82	14.83	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:9	8.18	928	0.83	13.36	104	200	Idle	93.2	0	2	132	944 Turbo	0.63	Rich	1	14.6	-7.79	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:9	8.18	925	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.59	Lean	1	14.6	-7.83	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:9	8.18	925	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.57	Lean	1	14.6	-7.82	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:45:9	8.18	926	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.56	Lean	1	14.6	-7.84	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:0	8.18	926	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.54	Lean	1	14.6	-7.84	14.84	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:0	8.18	927	0.83	13.38	104	200	Idle	93.2	0	2	132	944 Turbo	0.51	Lean	1	14.6	-7.83	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:0	8.18	927	0.83	13.38	104	200	Idle	93.2	0	2	132	944 Turbo	0.47	Lean	1	14.6	-7.79	14.83	1.01	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:0	8.18	930	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.45	Lean	1	14.6	-7.84	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:0	8.18	932	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.77	14.82	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:0	8.18	939	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.79	14.83	1.01	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:0	8.18	939	0.83	13.36	103	200	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.77	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:1	8.18	939	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.78	14.83	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:1	8.18	939	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.37	Lean	1	14.6	-7.79	14.84	1.01	4.9	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:1	8.18	934	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.81	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:1	8.18	934	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.79	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:1	8.18	934	0.83	13.35	103	200	Idle	93.2	0	2	132	944 Turbo	0.42	Lean	1	14.6	-7.81	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:1	8.18	935	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.41	Lean	1	14.6	-7.76	14.84	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:2	8.18	938	0.83	13.37	103	200	Idle	93.2	0	2	132	944 Turbo	0.38	Lean	1	14.6	-7.81	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:2	8.18	941	0.83	13.38	104	200	Idle	93.2	0	2	132	944 Turbo	0.35	Lean	1	14.6	-7.76	14.87	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:2	8.18	943	0.83	13.35	104	200	Idle	93.2	0	2	132	944 Turbo	0.33	Lean	1	14.6	-7.83	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:2	8.18	943	0.83	13.36	104	200	Idle	93.2	0	2	132	944 Turbo	0.32	Lean	1	14.6	-7.81	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:2	8.18	942	0.83	13.35	104	200	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.84	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:2	8.18	941	0.83	13.36	104	200	Idle	93.2	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.83	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:3	8.18	941	0.83	13.39	103	200	Idle	93.2	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.83	14.86	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:3	8.18	941	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.82	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:3	8.18	944	0.83	13.38	104	200	Idle	93.3	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.84	14.82	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:3	8.18	946	0.83	13.39	104	200	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.84	14.81	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:3	8.18	945	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.87	14.8	1.01	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:3	8.18	945	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.82	14.82	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:3	6.81	931	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.87	14.84	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:4	6.81	931	0.83	13.39	103	200	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.83	14.86	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:4	6.81	933	0.83	13.4	103	200	Idle	93.3	0	2	132	944 Turbo	0.31	Lean	1	14.6	-7.87	14.88	1.01	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:30:46:4	6.81	935	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.3	Lean	1	14.6	-7.79	14.91	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:4	6.81	942	0.83	13.38	103	200	Idle	93.3	0	2	132	944 Turbo	0.29	Lean	1	14.6	-7.81	14.94	1.02	4.9	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:46:4	6.81	1968	0.81	10.94	103	200	Idle	93	0	0	0	Unknown	0.28	Lean	1	4.5	-8.47	14.94	1.02	5	0	ON	28 Pin	ON	Removed	Disabled
03:30:46:4	6.81	1968	0.76	5.62	132	200	Idle	92.5	0	0	0	Unknown	0.26	Lean	1	4.4	-10.07	14.94	1.02	5.1	0	ON	28 Pin	ON	Removed	Disabled
03:30:46:5	----	----	----	----	----	----	----	----	----	----	----	----	----	Lean	1	----	----	14.94	1.02	----	----	ON	28 Pin	----	Removed	Disabled
03:30:46:5	----	----	----	----	----	----	----	----	----	----	----	----	----	Lean	----	----	----	14.94	1.02	----	----	ON	28 Pin	----	Removed	Disabled
03:30:46:5	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	14.94	1.02	----	----	ON	28 Pin	----	Removed	Disabled
03:30:46:5	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	14.94	1.02	----	----	ON	28 Pin	----	Removed	Disabled
03:30:46:5	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	14.94	1.02	----	----	ON	28 Pin	----	Removed	Disabled
03:30:46:5	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	14.94	1.02	----	----	----	28 Pin	----	Removed	Disabled
03:30:46:5	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	14.94	1.02	----	----	----	28 Pin	----	Removed	Disabled
03:30:46:6	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	14.94	1.02	----	----	----	28 Pin	----	Removed	Disabled
03:30:46:6	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	14.94	1.02	----	----	----	28 Pin	----	Removed	Disabled
03:30:46:6	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	14.94	1.02	----	----	----	28 Pin	----	Removed	Disabled